

#### issues

# NOTIFICATION BULLETIN No. RTC-044b R1

# TECHNICAL CONTENT OF THIS DOCUMENT IS APPROVED ON THE BASIS OF AUTHORIZATION DOA NO. EASA.21J.057.

1. CONCERNING TO: Airplane SPORTSTAR RTC S/N 20151729, Reg. N. OE-ASA

and S/N 20192112, Reg. N. S5-DNK

**2. REASON:** Installation of the modified exhaust system Dwg. No. S6 18-15

01 SL1729 on the above mentioned airplanes for the purpose of

operation data collection.

3. **REQUIRED ACTIONS:** 1. Replace the standard exhaust system with the modified

exhaust system Dwg. No. S6 18-15 01 SL1729.

2. Record the bulletin implementation in the Logbook.

3. Regularly check the condition of the exhaust system and

inform the manufacturer of the airplane

4. LATEST DAY OF THE ACTION: After receiving this bulletin.

**5. CARRIED OUT BY:** Airplane manufacturer.

**6. COSTS COVERED BY:** Airplane manufacturer.

**7. NECESSARY MATERIAL:** In accordance with the text of the bulletin.

**8. WORK PROCEDURE:** In accordance with the text of the bulletin.

**9. APPENDICES:** None.

Valid from: 19. 09. 2019



# 1. Description of exhaust system

The exhaust system Dwg. No. S6 18-15 01 SL1729 differs from the standard exhaust system Dwg. No. E6 18-15 01 by replacing the flexible parts of individual exhaust pipeline with the new hydroformed pipeline with ball joints.

The geometry of the whole exhaust system, the cross-section of the pipeline, the length of the flue gas routes and the way of installation in the airplane do not change. A major benefit, leading to increased life and safety of the exhaust system is to increase the wall thickness at the location of the ball joint where the original version has a wall thickness of approximately 0.4 mm and the modified version has a 1 mm.

## 2. Work procedure

### 2.1 Necessary tools

See Airplane Maintenance Manual for SportStar RTC (doc. No. ERTC022-10-AS), Section 78-20.

## 2.2 Necessary material

| Name   | Marking | Nomencl.           | Quantity |
|--|---------|--------------------|----------|
| Exhaust system   |         | S6 18-15 01 SL1729 | 1 pc     |
| Material shall be supplied by the airplane manufacturer. |         |                    |          |

# 2.3 Work procedure

## 2.3.1 E6 18-15 01 Exhaust system removal

Remove the E6 18-15 01 Exhaust system according the procedure mentioned in the Airplane Maintenance Manual for SportStar RTC (doc. No. ERTC022-10-AS), Section 78-20, par. 2 A. (1).

### 2.3.2 S6 18-15 01 SL1729 Exhaust system installation

Install the S6 18-15 01 SL1729 Exhaust system according the procedure mentioned in the Airplane Maintenance Manual for SportStar RTC (doc. No. ERTC022-10-AS), Section 78-20, par. 2 A. (2).

### 3. Influence on airplane documentation

## 3.1 Accompanying technical documentation

3.1.1 Pilot's Operating Handbook for SportStar RTC (doc. No. ERTC020-10-AS)

Pre-flight Check (Par. 4.4, point 15. Engine) do according to the following procedure: Checks before the first flight of day:

- remove engine cowlings
- check condition of engine mount
- check condition of engine attachment
- check exhaust pipes, muffler and heat exchanger for condition, cracks, deformations or damage; check exhaust system fasteners for security. In case of damage finding, immediately inform the airplane manufacturer.
- check condition of engine cowlings
- visual check on fuel and electrical system condition
- check on cooling liquid volume in the expansion tank on the engine body (replenish as required up to max. 2/3 of the expansion tank volume)
- check on cooling liquid level in the overflow bottle (volume should be approx. 0.42 pints (0.2 liter))
- install the engine cowlings

tel: +420 632 537 428 fax: +420 632 537 901 e-mail: evektor@evektor.cz https://www.evektor.cz

page: 2/3



Checks before every flight:

- check cleanness of air intakes
- check on oil level (between marks flattening on the dip stick; difference between min. max. marks is 0.5 l)
- check proper closing of the upper engine cowling

# 3.2 Operation technical documentation

The authorized person will carry out this record in the Aircraft Logbook after bulletin implementation: "The removal of the existing E6 18-15 01 Exhaust system and the installation of the new S6 18-15 01 SL1729 Exhaust system were carried out according to the Information Bulletin No. RTC-044b R1" and he will add the date and his signature.

# 4. Influence on weight and balancing

Not affected.

tel: +420 632 537 428 fax: +420 632 537 901 e-mail: evektor@evektor.cz https://www.evektor.cz

page: 3/3