

*issues*

**MANDATORY BULLETIN No. EV97-045a SR**

- 1. CONCERNING TO:** *All EV97 Eurostar SL; SLW; SL+; EV97 Eurostar mod. 97; 99; 2000; 2000R aircraft, manufactured up to 2017 (inclusive), i.e. S/N 2017 XXXX.*
  
- 2. REASON:** *Loosening of the bearing in the adjustable rod eye ONL 3797.1 (nom. 079575).*
  
- 3. REQUIRED ACTIONS:** *Inspection of the bearing swaging of the adjustable rod eyes ONL 3779.1.*
  
- 4. LATEST DAY OF THE ACTION:** *Immediately after bulletin delivery.*
  
- 5. CARRIED OUT BY:** *Operator.*
  
- 6. COSTS COVERED BY:** *Operator.*
  
- 7. NECESSARY MATERIAL:** *Manufacturer build to order.*
  
- 8. WORK PROCEDURE:** *According to the bulletin text.*
  
- 9. APPENDICES:** *None.*

Valid from: 29. 04. 2026

**1. Necessary tools**

Name	Designation	Number of pieces
Combinated pliers	-	1
Cutting pliers	-	1
Wrench	No. 9	1
Wrench	No. 10	1
Wrench	No. 13	1
Offset box-end wrench	No. 13	1
Adjustable wrench	E.g. KNIPEX	1
Philips screwdriver	No. 2	1

**2. Necessary material**

Materials required for the removal of the lateral control rod joints

Name	Nomenclature	Number of pieces
Cotter pin 1,6x12 ISO 1234	040002	2 pcs

Materials required for rod eye replacement

Name	Nomenclature	Number of pieces
Washer 8,4 ISO 7089	038208	As required
Adjustable rod eye with bearing AEN 3779.1	079563	As required

Materials required for rudder removal

Name	Nomenclature	Number of pieces
Cotter pin 1x12 ISO 1234	038862	2 pcs

Materials required for rudder upper hinge rod eye removal

Name	Nomenclature	Number of pieces
Cotter pin 8,4 DIN 463	038241	As required
Nut M8 DIN 980 V	033870	1 pc
Adjustable rod eye with bearing AEN 3779.1	079563	As required

**3. Work procedure**Reason for inspection

Due to a reported case of bearing loosening in the adjustable rod eye ONL 3779.1 (Fig. 1) in service, perform an inspection of all aircraft that may be equipped with eyes with insufficiently staked (swaged) bearings. The cause is that during manufacturing, the bearing in the rod eye was not secured by rolling over groove material onto the chamfered edge of the bearing outer ring (Fig. 3 bottom).


**ADJUSTABLE ROD EYE WITH BEARING ONL 3779.1**


Fig. 1 Adjustable rod eye ONL 3779.1




Fig. 2 shows the proper bearing swaging in accordance with standard ONL 1331.2, where the bearing is secured by rolling over groove material onto the edge of the outer ring.

## BEARING SECURING ACCORDING TO STANDARD ONL 1331.2

### HOUSING FOR BEARING FOR DOUBLE - SIDED ROLING




### BEARING ROLLED ON BOTH SIDES



### DETAIL

### EYE MATERIAL ROLLED ONTO THE EDGE OF THE OUTER RING OF THE BEARING




### GROOVE EDGE PRESSED BY ROLLING BALL

Fig. 2 Groove profile before swaging and properly swaged bearing



## NON - ROLLED BEARING



## INCORRECTLY SWAGED BEARING




Fig 3. Incorrectly swaged bearing

Fig. 3 shows incorrect bearing swaging, where the bearing is not secured against falling out of the rod eye. Such condition can be critical, especially in the lateral control rod joints (Fig. 4, detail A; B), where a disconnection of the lateral control rods may occur.

Check the condition of the bearing swaging in the E4 01-04 01 adjustable rod eye and in the E4 01-13-01 aileron control rods.

**Inspection of clearance in the E4 01- 13 01 and E4 01-04 01 control rod joints**

Before starting the inspection, remove the fuselage-to-wing fairing.

To perform the bearing swaging inspection, remove the 1,6x12 cotter pins (Fig. 4, detail A; B) and remove the M6 nuts.

Remove the 5x0,5 washers, slide out the 6x25 bolts and remove the E4 01-18 21 washers.

Check the bearing swaging in the rod eye for clearance by hand.

If clearance is detected, unlock the washer and remove the rod eye.

Visually inspect (preferably using a magnifying glass) the condition of the swaging grooves and the bearing securing in the eye. If you find conditions similar or the same as in Fig. 3, replace the adjustable eye with a new one, 8x14x6 AEN 3779.1, nomenclature 079563, supplied by the aircraft manufacturer (a rod eye with a shortened threaded part is used for the E4 01-13 01 rods).

In case of replacement, install the new rod eye including a washer.

Check aileron deflections and adjust as necessary. After checking and adjusting the deflections, secure the washer.

Insert the 6x25 bolts into the bearing of the E4 01-13 01 rods (Fig. 4, detail A; B) and slide on the E4 01- 18 21 washers.

Further insert the bolts into the holes in the control levers and into the bearing in the E4 01-04 01 control rod.

Slide on the 6x0,5 washers and install the M6 nuts.

Secure the nuts with 1,6x12 cotter pins.

If, during the pre-flight inspection, no excessive clearance in the manual control system or rudder mounting is found, stiffness in the control system, or any other abnormal condition is detected, perform a visual inspection of the rod eye E4 01-10 01 in the elevator control system (Fig. 5, Detail A) and the rod eye of the upper rudder hinge (Fig. 5, Detail B) at the next annual or 100-hour inspection.

If abnormal clearance or stiffness is observed in the joint, perform the inspection immediately.

In these joints, the rod eye may slip over the bolt head, leading to a disconnection of the control circuit.

The same removal / installation procedure for the control rod joints applies as in the previous case.

**Inspection / replacement of the elevator control rod eye**

Disconnect the connection between the rod and the lever on the elevator.

Remove the 1,6x12 cotter pin (Fig. 5) and the M6 nut.

Remove the 6x1 washer and the 6x23,5 bolt.

Check the bearing swaging in the rod eye for clearance by hand.

If clearance is detected, unlock the washer and remove the rod eye.

Visually inspect (preferably using a magnifying glass) the condition of the swaging grooves and the bearing securing in the eye. If you find conditions similar or the same as in Fig. 3, replace the adjustable eye with a new one, 8x14x6 AEN 3779.1, nomenclature 079563, supplied by the aircraft manufacturer.

In case of replacement, install the new rod eye including a new washer.

Connect the control rod to the elevator lever using a 6x23,5 bolt, 6x1 washer and M6 nut (Fig. 5).

Check the elevator deflection and adjust as necessary. After checking and adjusting the deflections, secure the washer.

Secure the M6 nut with a 1,6x12 cotter pin.

**Inspection of the rudder upper hinge rod eye**

Disconnect the control cables from the rudder hinges (Fig. 6, Detail C).

Remove the 6x23 bolts and the 6,4 ISO 7089 washers.

Remove the 6x23 bolts from the ends of the rudder cables and remove the 6,4 DIN 463 washers.

Secure the free ends of the cables to prevent them from being pulled into a fuselage (e.g. using safety wire).

Remove the rudder according to Fig. 6, Detail D.

Remove the 1x12 cotter pin and the M5 nut from the rudder lower hinge.

Remove the rudder.

Visually inspect (preferably using a magnifying glass) the condition of the swaging grooves and the bearing securing in the rod eye of the rudder upper hinge.

If you find conditions similar or the same as in Fig. 3, replace the adjustable eye with a new one, 8x14x6 AEN 3779.1, nomenclature 079563, supplied by the aircraft manufacturer.

**Removal / installation of the rudder upper hinge rod eye**

According to Fig. 7, unlock the washer.



Hold the M8 self-locking nut inside fin using an offset wrench (No. 13) and loosen the M8 nut on the rod eye thread. Unscrew the rod eye using an adjustable wrench. Screw the eye by the flat part avoiding the bearing inner ring.

If necessary, the inner bearing ring can be removed.

Remove the M8 self-locking nut.

Install a new M8 nut onto the threaded section of the new rod eye and slide on a new washer. Position the M8 self-locking nut on the fin rear spar, against the rod eye hole. Position the nut with one of its flats horizontally and hold it in place with an offset wrench (No. 13). In this position, screw the rod eye into the nut thread by hand. Once increased resistance is felt, use the adjustable wrench to complete the installation.

Adjust the rod eye depth to maintain a distance of 31 mm according to Fig. 7, bottom.

Tighten the M8 nut and bend the tabs of the washer.

After inspecting the upper hinge, install the rudder and connect the control cables (Fig. 6).

#### **4. Influence on airplane documentation**

Accompanying technical documentation - without influence.

Operational technical documentation - after compliance with this bulletin, record the following note in the aircraft logbook: „Inspection of bearing swaging in control rods performed in accordance with MB No. EV97 -045a SR”, and add date and signature.

#### **5. Influence on weight and balancing**

Without influence.




Fig. 4 Inspected manual control rod joints




Fig. 5 Elevator control rod removal




Fig. 6 Rudder removal



**RUDDER UPPER HINGE**




Fig. 7 Rudder upper hinge rod eye removal