



# Facade Solutions

## Facades - Building - Thermal Inspection

Page 8

North Façade, Windows, and Thermal



Report Date: 00/00/0000

Survey Date: 00/00/0000


Job Number: 00-0000

Page 9

Location: North Façade, Quadrants 1–4

Date: 00/00/0000

Comments: This image index shows the locations of the visually observed failures on the north facade.



Report Date: 00/00/0000

Survey Date: 00/00/0000


Job Number: 00-0000

# Facade Solutions

## Facades - Building - Thermal Inspection

Page 10

**Image #:** 1 **Date:** 00/00/0000  
**Location:** North Facade  
**Folder:** Quadrant 1 Zoom  
**File:** DJI\_20230717163022\_0023\_SUPR, DJI\_20230717163016\_0019\_SUPR, DJI\_20230717163015\_0018\_SUPR, DJI\_20230717163015\_0017\_SUPR, DJI\_20230717163014\_0016\_SUPR, DJI\_20230717163013\_0015\_SUPR  
**Comments:** Suspected separation of sealant. There is so much sealant present that some of it could be overlap in sealant, but is highlighted for further review.



Report Date: 00/00/0000

Survey Date: 00/00/0000

Job Number: 00-0000

Page 11

**Image #:** 2 **Date:** 00/00/0000  
**Location:** North Facade  
**Folder:** Quadrant 1 Zoom  
**File:** DJI\_20230717163150\_0116\_SUPR  
**Comments:** Missing sealant at vent corner



Report Date: 00/00/0000


Survey Date: 00/00/0000

Job Number: 00-0000

# Facade Solutions


# Facades - Building - Thermal Inspection

**Location:** North Façade, Gray Section Anomalies      **Date:** 00/00/0000  
**Comments:** Cracking observed throughout this section.



Page 19

**Image #:** 14 **Date:** 00/00/0000  
**Location:** North Facade  
**Folder:** Gray Section Zoomed  
**File:** DJI\_20230717162313\_0093\_SUPR, DJI\_20230717162313\_0092\_SUPR,  
DJI\_20230717162322\_0101\_SUPR  
**Comments:** Cracks, Organic Matter




Page 35

# Facade Solutions

## Facades - Building - Thermal Inspection

Page 46

**Location:** North Façade, Window Overview      **Date:** 00/00/0000  
**Comments:** This image index shows the locations of visually observed defects correlated with the windows.




Report Date: 00/00/0000

Survey Date: 00/00/0000

Job Number: 00-0000

Page 92

**Location:** South Façade, Window Overview      **Date:** 00/00/0000  
**Comments:** This image index shows the locations of visually observed defects correlated with the windows.



Report Date: 00/00/0000

Survey Date: 00/00/0000

Job Number: 00-0000

# Facade Solutions

## Facades - Building - Thermal Inspection

Page 59

**Image #:** 3      **Job #:** 23-0717      **Date:** 00/00/0000      **Time:** 7:00pm – 7:45pm

**Wind Speed:** Calm      **Sky:** Cloudy


**Humidity:** 78%      **Ambient Temperature:** 83° F

**Subject Priority:** 2      **Location:** Grey Section, 1<sup>st</sup> Floor

**Equipment:** DJI Matrice 30T      **Image Type:** Infrared/Visible

**Image:** DJI\_20230717191047\_0020\_T, DJI\_20230717191047\_0020\_W

**Comments:** Suspected moisture.



Report Date: 00/00/0000

Survey Date: 00/00/0000

Job Number: 00-0000