


I'm not robot  reCAPTCHA

I am not robot!

Cyclone box installer 1.22.exe. Setup cyclone box download. Cyclone box installer v1.22 download.



The tool supports various Nokia phone brands and features include: * Easy backup and restore of IMEI data * Repair of BB5, DCT4, DCT4+, and DCTL devices * Fast flashing and software upgrade capabilities * Support for UFS and ATF pinouts * Ability to read telephone software files Cyclone Box has released a new update, Installer v1.22, which adds support for XGold223 (Asha 308, Asha309) and various features like Write Flash, Read/Write Certificates, Read RPL, and more.

The update also includes firmware v02.11, Lumia SmartTP(R), and improved flashing speed. Some of the notable additions include: * New CPU support * Improved flashing speed and NPC certs reading time * Fixed BSI spurious glitch problem with ~2.x firmware * Fixed DCT4 booting problems * Improved FBUS Local Mode entry * XGold213xx certificates Backup Added (NPC, HWC, CCC,...) * XGold213xx Full Flash chip dump to BIN added * XGold213xx Low-level PMM dump added (can dump PM from dead mobile) * XGold213xx Low-Level FILESYSTEM dump from dead mobiles added Additionally, the update notes that: * Switching to RAW mode is not supported for XGold223 flashing * Battery reset needed after flashing, but software may not always prompt you * Read RPL is not a full backup and missing crypted PM308 data The Cyclone Team reminds users to stay tuned and not to erase their phones until the loaders with asymmetric key hack are ready. Mandatory Update for Cyclone Box Users! New firmware version 02.11 is now available, and it's a must-have upgrade! This update brings several exciting features and improvements to the Cyclone Box, including: * Support for XGold223 CPUs (Asha 308 and Asha309) * New operations like Write Flash, Read/Write Certificates, and more * Introduction of Lumia SmartTP(R) for testers only * Improved flashing speed and NPC certs reading time * Fixed BSI spurious glitch problem with ~2.x firmware * Enhanced CBUS protocol handling to prevent synchronization issues Additionally, this update includes: * New BB5 Loaders added * Improved Lumia USB Flashing capabilities * Latest Blackberry MEPs included * Minor bugfixes and changes Important Notes for XGold 223 Users: * RAW mode flashing is not supported * Battery reset may be required after flashing * RPL readbacks are incomplete (missing crypted PM308 data) * Autoupdate module should work, but if not, you can use the alternative link provided. Get your Cyclone Box updated today and take advantage of these exciting new features!