

***30691-4 OY3 #3 December 2023 / Building 2 / 1st Floor / 1st Floor Bldg 2.**




Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	1713	885619		cja1080	Repairs	TP-Wall	Metallic Pipe	1 Hour Smoke Zone Barrier	Concrete	Repair			12/14/23		MS	
Repair 12/14/23 12/23/23 NFPA 101 Section 8.5 Room Number 110103 12/14/23 12/23/23 Wall Direction 12/14/23 12/23/23 East Lineal Feet 12/14/23 12/23/23 Repair 12/14/23 12/23/23 NFPA 101 Section 8.5																
																
	1724	885968			Area	Area Survey	Construction Area			Note			2/13/24		MS	
Note 2/13/24 2/13/24 Wall Direction 2/13/24 Room Number 2/13/24																
																
	2333	887412		hwd0236	Repairs	TP-Wall	Blank Opening	1 Hour Smoke Zone Barrier	Gypsum	Repair			2/19/24		MS	
Repair 2/19/24 2/19/24 NFPA 101 Section 8.5 Room Number 134243 2/19/24 2/19/24 Wall Direction 2/19/24 2/19/24 south Lineal Feet 2/19/24 2/19/24 Repair 2/19/24 2/19/24 NFPA 101 Section 8.5																
																

***30691-4 OY3 #3 December 2023 / Building 2 / 2nd Floor / 2nd Floor Bldg 2. (2nd Floor Bldg 2)**




Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	2039	885755			Repairs	TP-Wall	Metallic Pipe	1 Hour Smoke Zone Barrier	Gypsum	Repair			12/17/23		MS	
Repair 12/17/23 12/23/23 NFPA 101 Section 8.5 Room Number 210321a 12/17/23 12/18/23 Wall Direction 12/17/23 12/23/23 West Lineal Feet 12/17/23 12/23/23 Repair 12/17/23 12/23/23 NFPA 101 Section 8.5																
																
	2040	885756		caj1080	Repairs	TP-Wall	Metallic Pipe	1 Hour Smoke Zone Barrier	Gypsum	Repair			12/17/23		MS	
Repair 12/17/23 12/23/23 NFPA 101 Section 8.5 Room Number 210321 12/17/23 12/18/23 Wall Direction 12/17/23 12/23/23 East Lineal Feet 12/17/23 12/23/23 Repair 12/17/23 12/23/23 NFPA 101 Section 8.5																
																


*30691-4 OY3 #3 December 2023 / Building 2 / 3rd Floor / 3rd Floor Bldg 2





Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	735	885627		caj1080	Repairs	TP-Wall	Metallic Pipe	1 Hour Smoke Zone Barrier	Concrete	Repair			12/14/23		MS	
	Repair 12/14/23 12/23/23 NFPA 101 Section 8.5 Room Number st43n 12/14/23 12/23/23 Wall Direction 12/14/23 12/23/23 West Lineal Feet 12/14/23 12/23/23 Repair 12/14/23 12/23/23 NFPA 101 Section 8.5															
	 															
	738	885630		wl0034	Repairs	TP-Wall	Blank Opening	2 Hour	Concrete	Repair			12/14/23		MS	
	Repair 12/14/23 12/20/23 NFPA 101 Section 8.5 Room Number 323402 12/14/23 12/20/23 Wall Direction 12/14/23 12/20/23 North Lineal Feet 12/14/23 12/20/23 Repair 12/14/23 12/20/23 NFPA 101 Section 8.5															

Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	832	886205		w1049	Repairs	TP-Wall	Metallic Pipe	1 Hour Smoke Zone Barrier	Gypsum	Repair			2/14/24		MS	
			Repair	2/14/24	2/14/24	NFPA 101 Section 8.5										
			Room Number	320412	2/14/24	2/14/24										
			Wall Direction	2/14/24	2/14/24	south										
			Lineal Feet	2/14/24	2/14/24											
			Repair	2/14/24	2/14/24	NFPA 101 Section 8.5										
	848	886251			Area	Area Survey	Construction Area			Note			2/14/24		MS	
			Note	2/14/24	2/14/24											
			Wall Direction	2/14/24												
			Room Number	2/14/24												
	849	886252			Area	Area Survey	Construction Area			Note			2/14/24		MS	
			Note	2/14/24	2/14/24											
			Wall Direction	2/14/24												
			Room Number	2/14/24												
	350	886253			Area	Area Survey	Construction Area			Note			2/14/24		MS	


Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	Note		2/14/24	2/14/24												
	Wall Direction		2/14/24													
	Room Number		2/14/24													
	 															






Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
		885634			Repairs	TP-Wall	Cable Tray		Gypsum	Repair			12/14/23		MS	
Repair12/14/23NFPA 101 Section 8.5 Room Number12/14/23 Wall Direction12/14/23 Lineal Feet12/14/23 Repair12/14/23NFPA 101 Section 8.5																
																

*30691-4 OY3 #3 December 2023 / Building 2 / 4th Floor Bldg 2 RFS (4th Floor Bldg 2 RFS layers)




Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	1293	885966			Large Opening	Large Opening	Sections of walls missing		Gypsum	Repair			2/13/24		MS	
	Repair	2/13/24			NFPA 101 Section 8.5											
	Room Number	st14	2/13/24													
	Wall Direction	2/13/24			East											
	Lineal Feet	2/13/24														
	Repair	2/13/24			NFPA 101 Section 8.5											
																
	1302	885983		w1049	Repairs	TP-Wall	Metallic Pipe	1 Hour Smoke Zone Barrier	Gypsum	Complete			2/13/24		MS	
	Repair	2/13/24			2/13/24	NFPA 101 Section 8.5										
	Room Number	420604	2/13/24		2/13/24											
	Room Number	2/13/24														
	Wall Direction	2/13/24			2/13/24	west										
	Lineal Feet	2/13/24			2/13/24											
	Repair	2/13/24			2/13/24	NFPA 101 Section 8.5										


[illegible]

Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority	
																	


*30691-4 OY3 #3 December 2023 / Building 2 / 5th Floor Bldg 2.




Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	10	887507			Area	Area Survey	Access Issue-Hard Lid Ceiling			Note			2/20/24		JA	
	Note 2/20/24 2/20/24 Wall Direction 2/20/24 Room Number 531902 2/20/24															
	13	887510			Area	Area Survey	Access Issue-Hard Lid Ceiling			Note			2/20/24		JA	
	Note 2/20/24 2/20/24 Wall Direction 2/20/24 Room Number 531601 2/20/24															
	14	887512			Area	Area Survey	Access Issue-Hard Lid Ceiling			Note			2/20/24		JA	
	Note 2/20/24 2/20/24 Wall Direction 2/20/24 Room Number 531601 2/20/24															





Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	168	887534			Area	Area Survey	Construction Area			Note			2/21/24		MS	
	Note 2/21/24 2/21/24 Wall Direction 2/21/24 Room Number 2/21/24															




Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	1	887536			Area	Area Survey	Construction Area			Note			2/21/24		MS	
	Note 2/21/24 2/21/24 Wall Direction 2/21/24 Room Number 2/21/24															





Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	1	887535			Area	Area Survey	Construction Area			Note			2/21/24		MS	
Note 2/21/24 2/21/24																
Wall Direction 2/21/24																
Room Number 2/21/24																
																




Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	74	887537			Area	Area Survey	Construction Area			Note			2/21/24		MS	
	Note 2/21/24 2/21/24 Wall Direction 2/21/24 Room Number 2/21/24															




Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	57	887538			Area	Area Survey	Construction Area			Note			2/21/24		MS	
	Note 2/21/24 2/21/24 Wall Direction 2/21/24 Room Number 2/21/24															
																




Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	1	887539			Area	Area Survey	Construction Area			Note			2/21/24		MS	
Note 2/21/24 2/21/24																
Wall Direction 2/21/24																
Room Number 2/21/24																




Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	1	887540			Area	Area Survey	Construction Area			Note			2/21/24		MS	
	Note 2/21/24 2/21/24 Wall Direction 2/21/24 Room Number 2/21/24															





Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	1	887541			Area	Area Survey	Construction Area			Note			2/21/24		MS	
	Note 2/21/24 2/21/24 Wall Direction 2/21/24 Room Number 2/21/24															




Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	56	887542			Area	Area Survey	Construction Area			Note			2/21/24		MS	
Note 2/21/24 2/21/24 Wall Direction 2/21/24 Room Number 2/21/24																
																


*30691-4 OY3 #3 December 2023 / Building 3 / Floor 10




Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	1	887543			Area	Area Survey	Construction Area		Gypsum	Note			2/21/24		MS	
	Note 2/21/24 2/21/24 Wall Direction 2/21/24 Room Number 2/21/24															
																





Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	1	887544			Area	Area Survey	Construction Area			Note			2/21/24		MS	
	Note 2/21/24 2/21/24 Wall Direction 2/21/24 Room Number 2/21/24															



Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	1	887495			Area	Area Survey	Construction Area			Note			2/20/24		MS	
	Note 2/20/24 2/20/24 Wall Direction 2/20/24 Room Number 2/20/24															



Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	27	887488			Area	Area Survey	Construction Area			Note			2/20/24		MS	
	Note 2/20/24 2/20/24 Wall Direction 2/20/24 Room Number 2/20/24															
																



Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	1	887472			Area	Area Survey	Construction Area		Gypsum	Note			2/20/24		MS	
	Note 2/20/24 2/20/24 Wall Direction 2/20/24 Room Number 2/20/24															

15TH FLOOR PLAN



Icon	Punch #	ID	Room Number	System	Inspection Type	Item	Type	Fire Rating	Wall Material	Action	Resource	Comments	Due	Type Comment	Created By	Priority
	1	887476			Area	Area Survey	Construction Area			Note			2/20/24		MS	
	Note2/20/242/20/24 Wall Direction2/20/24 Room Number2/20/24															
	