

I'm not robot



Cen-tech 61593 manual

Cen tech timing light instructions. Cen tech digital multimeter instructions. Cen-tech 57015 manual. Cen-tech code reader manual. Cen-tech manual. Cen tech multimeter instructions. Cen tech p30756 instructions.

1. Save the manual and receipt in a safe place for future reference. 2. Check that all parts are included when unpacking. 3. Contact Harbor Freight Tools at 1-888-866-5797 if any parts are missing or broken. 4. Read and follow safety warnings and precautions before using the product. 5. Ensure proper assembly and use of tools, as some may not be included. 6. Use caution when working with voltages above 30 VAC rms, 42 VAC peak, or 60 VDC. 7. Disconnect power to circuit before connecting the meter in series. 8. Handle probes with fingers behind guards and avoid electrical shock. 9. Keep work area clean and well lit, avoid damp or wet locations. 10. Keep children away from work areas and stay alert while operating the meter. - Testing voltage above 750 AC or 1000 DC should only be carried out by a licensed electrician. - Do not measure current on circuits with a flow rate below 20 mA. - Store idle equipment in dry locations, storing meters safely and keeping them inaccessible to children when not in use. - Wear protective attire suitable for electrical work, including non-slip footwear. - Use safety goggles approved by the American National Standards Institute (ANSI) while using the meter. - Only utilize accessories specifically designed for use with this device.