

2 and Solid 4 is set to Flashing 2.

For Software Version 1.1 or higher verify that Solid 2 is set to Flashing 5. This achieves door opening voltage on pins 11&12.

OC-904C T's connect in parallel. Be sure to

observe polarity (+ to +, - to -).

DO NOT connect purple wires

to Door Control.

- 1. Set door speeds and verify proper door operation prior to final connection of sensor system.
- 2. Technician MUST WALK TEST to verify function and detection patterns comply with ANSI/BHMA A156.10 requirments.

Title: 16300980 Tormax TTX II Single with Elite		Drawing # 16300980	
Drawing By: RNG	Date: 09/16/17	Sheet:	1 of 1

OPTEX Technologies Inc. 18730 S. Wilmington Ave. Unit 100 Rancho Dominguez, CA. 90220 800-877-6656 FAX 310-898-1098