

Company

Owner: ABS Jets, a.s.
Operator:

Major Assemblies

Airframe	560XL (Citation XLS 560-6198 +)	07-Nov-2024	3316:07 Hrs	2,576 Ldg	1623:42 Hrs(APU)	3,484 Start(APU)
Eng 1	PW545C	PCE-DF0403	07-Nov-2024	3316:07 Hrs	2,576 Enc	
Eng 2	PW545C	PCE-DF0402	07-Nov-2024	3316:07 Hrs	2,576 Enc	
APU 1	RE100[XL]	P-997	31-Oct-2024	1623:42 Hrs	3,484 APUS	

Additional Information

Program Type: MSG-3, General Categories: FAR 91

Cost: 85+
Man Hrs: 1,180.51+

Analyst: Laurence Kirk lkirk@jetsupport.com

Task No	Description								Categories	Time								
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining								
▼ 0 - GENERAL																		
 0 A/F									RE (-)									
										Mos								
										Hrs								
										Ldg								
AMP ABS-MT-057																		
 0 A/F									RE (-)									
										Mos								
									24-Aug-2023	Hrs								
										Ldg								
Note: Issue 1 Rev. 1																		
Engine data download																		
 0 A/F									RE									
										Mos								
									31-Oct-2024	1								
									30-Nov-2024	16 Days								
										Hrs								
										Ldg								
										2,570								
Interior Care - Seats																		
 0 A/F									RE (-)									
										Mos								
									09-Oct-2023	Hrs								
										3048:30								
										Ldg								
										2,362								
Interior Care - Sidepanels																		
 0 A/F									RE (-)									
										Mos								
									09-Oct-2023	Hrs								
										3048:30								
										Ldg								
										2,362								
▼ 2 - *Reserved for Airline Use																		
SL560XL-02-01																		
Year 2000 Readiness Disclosure																		
 2 A/F Eff: 03-Dec-1998									T (A/R)	Informational								
										Mos								
										Hrs								
										Ldg								
SL560XL-02-02																		
Airport Noise Abatement Information																		
 2 A/F Complied With									RE (-)	Recommended								
										Mos								
									13-Sep-2021	Hrs								
										Ldg								
SL560XL-02-02 Rev 01																		
Airport Noise Abatement Information																		
 2 A/F Eff: 10-Jan-2002									T (A/R)	Informational								
										Mos								
										Hrs								
										Ldg								

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-02-03	Miscellaneous - Cessna CD-ROM Technical Library						T (A/R)		Informational	
 2 A/F										
Eff: 11-Nov-1999										
▼ 3 - *Reserved for Airline Use										
CIL-03-01	Certification Requirements - Supplemental Type Certificate (STC)						T (A/R)		Informational	
 3 A/F										
Eff: 03-Jun-2013										
SL560XL-03-01	Supplemental Type Certificate (STC) - CANCELLED						RE (-)		Service Letter	
 3 A/F										
SL560XL-03-01 Rev 01	Supplemental Type Certificate (STC) - CANCELLED						T (A/R)		Service Letter	
 3 A/F										
Eff: 03-Jun-2013										
▼ 4 - AIRCRAFT STATS / LIMITATIONS										
4-12-MB	Airworthiness Limitations Inspection Document MB						RE (N/A)		Airworthiness Limitations Inspection Document	
 4 A/F										
(AVG MAN HRS: 7.2) (SOURCE: 560 XL MM Section 4-12-00)										
4-12-MD	Airworthiness Limitations Inspection Document MD						T		Airworthiness Limitations Inspection Document	
 4 A/F										
(AVG MAN HRS: 15.75) (SOURCE: 560 XL MM Section 4-12-00)										
4-12-ME	Airworthiness Limitations Inspection Document ME						RE		Airworthiness Limitations Inspection Document	≈11-Feb-2041
 4 A/F										
(AVG MAN HRS: 91.24) (SOURCE: 560 XL MM Section 4-12-00)										
4-12-MF	Airworthiness Limitations Inspection Document MF						T		Airworthiness Limitations Inspection Document	≈04-Sep-2030
 4 A/F										
(AVG MAN HRS: 30.38) (SOURCE: 560 XL MM Section 4-12-00)										
4-12-MG	Airworthiness Limitations Inspection Document MG						RE (N/A)		Airworthiness Limitations Inspection Document	
 4 A/F										
(AVG MAN HRS: 1.13) (SOURCE: 560 XL MM Section 4-12-00)										
4-12-MH	Airworthiness Limitations Inspection Document MH						RE (N/A)		Airworthiness Limitations Inspection Document	
 4 A/F										
(AVG MAN HRS: 1.13) (SOURCE: 560 XL MM Section 4-12-00)										
4-12-MI	Airworthiness Limitations Inspection Document MI						RE (N/A)		Airworthiness Limitations Inspection Document	
 4 A/F										
(AVG MAN HRS: 1.13) (SOURCE: 560 XL MM Section 4-12-00)										

Task No		Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
4-12-MJ		Airworthiness Limitations Inspection Document MJ							RE	Airworthiness Limitations Inspection Document		≈30-Apr-2038
	4 A/F					Mos	29-Oct-2015					
						Hrs	0	13,000		13000	9683:53 Hrs	
		(AVG MAN HRS: 13.5) (SOURCE: 560 XL MM Section 4-12-00)				Ldg	0					
4-12-MK		Airworthiness Limitations Inspection Document MK							RE (N/A)	Airworthiness Limitations Inspection Document		
	4 A/F					Mos						
						Hrs						
		(AVG MAN HRS: 1.13) (SOURCE: 560 XL MM Section 4-12-00)				Ldg						
4-12-ML		Airworthiness Limitations Inspection Document ML							T	Airworthiness Limitations Inspection Document		≈29-Mar-2036
	4 A/F					Mos	29-Oct-2015					
						Hrs	0	11,500		11500	8183:53 Hrs	
		(AVG MAN HRS: 2.25) (SOURCE: 560 XL MM Section 4-12-00)				Ldg	0					
4-12-MM		Airworthiness Limitations Inspection Document MM							T	Airworthiness Limitations Inspection Document		≈18-Jul-2035
	4 A/F					Mos	29-Oct-2015					
						Hrs	0	11,000		11000	7683:53 Hrs	
		(AVG MAN HRS: 1.13) (SOURCE: 560 XL MM Section 4-12-00)				Ldg	0					
4-12-MN		Airworthiness Limitations Inspection Document MN							T	Airworthiness Limitations Inspection Document		≈05-Oct-2032
	4 A/F					Mos	29-Oct-2015					
						Hrs	0	9,000		9000	5683:53 Hrs	
		(AVG MAN HRS: 1.13) (SOURCE: 560 XL MM Section 4-12-00)				Ldg	0					
4-12-MO		Airworthiness Limitations Inspection Document MO							T	Airworthiness Limitations Inspection Document		≈19-Aug-2037
	4 A/F					Mos	29-Oct-2015					
						Hrs	0	12,500		12500	9183:53 Hrs	
		(SOURCE: 560 XL MM Section 4-12-00)				Ldg	0					
4-12-MP		Airworthiness Limitations Inspection Document MP							RE (N/A)	Airworthiness Limitations Inspection Document		
	4 A/F					Mos						
						Hrs						
		(AVG MAN HRS: 0.23) (SOURCE: 560 XL MM Section 4-12-00)				Ldg						
4-12-MR		Airworthiness Limitations Inspection Document MR							RE (N/A)	Airworthiness Limitations Inspection Document		
	4 A/F					Mos						
						Hrs						
		(AVG MAN HRS: 1.13) (SOURCE: 560 XL MM Section 4-12-00)				Ldg						
4-12-MS		Airworthiness Limitations Inspection Document MS							RE (N/A)	Airworthiness Limitations Inspection Document		
	4 A/F					Mos						
						Hrs						
		(SOURCE: 560 XL MM Section 4-12-00)				Ldg						
4-12-MT		Airworthiness Limitations Inspection Document MT							RE (N/A)	Airworthiness Limitations Inspection Document		
	4 A/F					Mos						
						Hrs						
		(SOURCE: 560 XL MM Section 4-12-00)				Ldg						

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
4-12-MU	Airworthiness Limitations Inspection Document MU						RE (N/A)		Airworthiness Limitations Inspection Document	
 4 A/F						Mos				
	(SOURCE: 560 XL MM Section 4-12-00)					Hrs				
						Ldg				
4-12-MV	Airworthiness Limitations Inspection Document MV						RE		Airworthiness Limitations Inspection Document	
 4 A/F						Mos	24		[03-Jul-2026]	1.6 Years
	(SOURCE: 560 XL MM)					Hrs				
						Ldg				
▼ 5 - TIME LIMITS/MAINTENANCE CHECKS										
05-00-03	Airworthiness Review Certificate Renewal/Extension						RE			
 5 A/F						Mos	31-Oct-2024	12	09-Oct-2025	11 Months
	Expiration Date 09-Oct-2025					Hrs	3308:54			
						Ldg	2,570			
05-50-00(A)(1)	Hard/overweight landings - Check						RE (A/R)		Unscheduled Maintenance Check	
 5 A/F						Mos	30-Apr-2019			
						Hrs	1360:12			
						Ldg				
	Note: (1) A hard landing is a landing that is made by an airplane with a sink rate that is more than the permitted sink rate. (2) Related to a hard landing is an overweight landing, which is landing the airplane at any gross weight which is more than the placard landing weights.									
05-50-00(A)(10)	Airplane towed with a large fuel unbalance or high drag/side loads because of ground handling - Check						RE (A/R)		Unscheduled Maintenance Check	
 5 A/F						Mos				
						Hrs				
						Ldg				
05-50-00(A)(11)	Airplane Operation Through Deep Standing Water - Check						RE (A/R)		Unscheduled Maintenance Check	
 5 A/F						Mos				
						Hrs				
						Ldg				
05-50-00(A)(12)	Nose Landing Gear Tow Limits - Check						RE (A/R)		Unscheduled Maintenance Check	
 5 A/F						Mos				
						Hrs				
						Ldg				
05-50-00(A)(13)	Exposure to High Winds While the Aircraft is Parked Check						RE (A/R)		Unscheduled Maintenance Check	
 5 A/F						Mos				
						Hrs				
						Ldg				
05-50-00(A)(14)	Interior Cabin/Tailcone Fluid Spill						RE (A/R)		Unscheduled Maintenance Check	
 5 A/F						Mos				
						Hrs				
	Ref:Chapter 20, Interior Finish - Cleaning/Painting					Ldg				
05-50-00(A)(15)	Engine Fire Extinguisher Discharge Inspection						RE (A/R)		Unscheduled Maintenance Check	
 5 A/F						Mos				
						Hrs				
						Ldg				
05-50-00(A)(16)	Auxiliary Power Unit (APU) Fire Extinguisher Discharge Inspection						RE (A/R)		Unscheduled Maintenance Check	
 5 A/F						Mos				
						Hrs				
						Ldg				

Task No		Description								Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
05-50-00(A)(2)	 5 A/F	Overspeed (Above 8000 ft) - Check Note: Note: A condition in which the airplane is operated at airspeeds that are more than those permitted by the Approved Airplane Flight Manual at altitudes that are more than 8000 feet.						RE (A/R)	Unscheduled Maintenance Check			
05-50-00(A)(3)	 5 A/F	Overspeed (Below 8000 ft) - Check Note: Note: A condition in which the airplane is operated at airspeeds that are more than those permitted by the Approved Airplane Flight Manual at altitudes that are less than 8000 feet. Overspeed conditions at this altitude also increase the chance for birdstrike damage to the airplane.						RE (A/R)	Unscheduled Maintenance Check			
05-50-00(A)(4)	 5 A/F	Flap System Overspeed - Check Note: Note: A condition in which the flaps are extended at airspeeds that are more than those permitted by the Approved Airplane Flight Manual.						RE (A/R)	Unscheduled Maintenance Check			
05-50-00(A)(5)	 5 A/F	Landing Gear Assembly Overspeed - Check Note: Note: A condition in which the landing gear is extended at airspeeds that are more than those permitted by the Approved Airplane Flight Manual.						RE (A/R)	Unscheduled Maintenance Check			
05-50-00(A)(6)	 5 A/F	Dangerous air turbulence or dangerous maneuvers - Check Note: (1) Conditions that can dangerously shake an airplane. Dangerous maneuvers are any maneuvers that are more than those permitted by the Approved Airplane Flight Manual.						RE (A/R)	Unscheduled Maintenance Check			
05-50-00(A)(7)	 5 A/F	Accidental in-flight thrust reverser deployment - Check						RE (A/R)	Unscheduled Maintenance Check			
05-50-00(A)(8)	 5 A/F	Lightning Strike - Check						RE (A/R)	Unscheduled Maintenance Check			
05-50-00(A)(9)	 5 A/F	Foreign Object Damage - Check						RE (A/R)	Unscheduled Maintenance Check			
5-12-01	 5 A/F (SOURCE: 560 XL MM Section 5-12-00)	Inspection Document 1 (Every 12 Mos)						RE 5-91-01 MSG-3 INSPECTION TIME LIMITS				
5-12-02	 5 A/F (SOURCE: 560 XL MM Section 5-12-00)	Inspection Document 2 (Every 600 Hrs)						RE (N/A) 5-91-01 MSG-3 INSPECTION TIME LIMITS				

Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
5-12-03		Inspection Document 3 (Every 24 Mos)								RE 5-91-01 MSG-3 INSPECTION TIME LIMITS	
	5 A/F	(SOURCE: 560 XL MM Section 5-12-00)				Mos	09-Oct-2023	24	-/+1m	31-Oct-2025	11.7 Months (+30 Days)
						Hrs	3048:30				
						Ldg	2,362				
5-12-06		Inspection Document 6 (Every 48 Mos)								RE 5-91-01 MSG-3 INSPECTION TIME LIMITS	
	5 A/F	(Tol. Adjustment: 21d) (SOURCE: 560 XL MM Section 5-12-00)				Mos	09-Oct-2023	48	-/+1m	31-Oct-2027	3 Years (+30 Days)
						Hrs	3048:30				
						Ldg	2,362				
5-12-07		Inspection Document 7 (Every 1600 Hrs)								RE 5-91-01 MSG-3 INSPECTION TIME LIMITS	≈26-Jan-2027
	5 A/F	(SOURCE: 560 XL MM Section 5-12-00)				Mos	31-Oct-2024				
						Hrs	3308:54	1,600	-/+25	4908:54	1592:47 Hrs (+25)
						Ldg	2,570				
5-12-08		Inspection Document 8 (Every 2400 Hours))								RE 5-91-01 MSG-3 INSPECTION TIME LIMITS	≈09-Oct-2026
	5 A/F	(UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 25-11-01-2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES -5002 THRU -5555 INCORPORATINGSB560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019,CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560 XL MM Section 5-12-00)				Mos	17-Dec-2021				
						Hrs	2295:34	2,400	-/+25	4695:34	1379:27 Hrs (+25)
						Ldg	1,748				
5-12-11		Inspection Document 11 (Every 48 Months, then Every 24 Months thereafter)								RE 5-91-01 MSG-3 INSPECTION TIME LIMITS	
	5 A/F	(Tol. Adjustment: 21d) (SOURCE: 560 XL MM Section 5-12-00)				Mos	09-Oct-2023	24	-/+1m	31-Oct-2025	11.7 Months (+30 Days)
						Hrs	3048:30				
						Ldg	2,362				
5-12-12		Inspection Document 12 (Every 60 Months)								RE 5-91-01 MSG-3 INSPECTION TIME LIMITS	
	5 A/F	(Tol. Adjustment: 28d) (SOURCE: 560 XL MM Section 5-12-00)				Mos	09-Oct-2023	60	-/+1m	06-Nov-2028	4 Years (+30 Days)
						Hrs	3048:30				
						Ldg	2,362				

Task No	Description									Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
5-12-13		Inspection Document 13 (Every 72 Months)							RE 5-91-01 MSG-3 INSPECTION TIME LIMITS			
	5 A/F	(Tol. Adjustment: -48d) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 13 IAW AMM 560XL (REV 46) CHAPTER 5-12-13 (REV 46) PERFORMED TASK 23-70-00-7100 COCKPIT VOICE RECORDER SYSTEM AND MICROPHONE OPERATIONAL CHECK I.A.W. MODEL 560XL MM REV46 CHPATER23-70-00 REV46. CHECK FOUND SATISFACTORY. NO FAULTS FOUND.PERFORMED EXTERNAL POWER OVERVOLTAGE SYSTEM FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 24-41-02-7200- NO FAULTS FOUNDPERFORMED HYDRAULIC SYSTEM FILTERS DISCARD I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 29-11-04-9600- NO FAULTS FOUNDPERFORMED AUXILIARY POWER UNIT CONTAINMENT BOX ASSEMBLY GENERAL VISUAL INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019,CH: 49-00-00-2103- NO FAULTS FOUNDPERFORMED NOSE SECTION INTERNAL ZONAL GENERAL VISUAL INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER:53-10-00-2101- NO FAULTS FOUNDPERFORMED TASK 53-10-00-2102 NOSE AVIONICS COMPONENTS WIRING AND BULKHEAD CONNECTORS STANDALONE EZAP GENERAL VISUAL INSPECTION IAWC560XL AMM REV46. NO FAULT FOUND.TASK NOT APPLICABLE DUE TO AC S/N 560XL-6198.PERFORMED COCKPIT INTERNAL (BELOW FLOORLINE) ZONAL GENERAL VISUAL INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019,CHAPTER: 53-20-00-2100- NO FAULTS FOUNDPERFORMED TASK 53-20-00-2102 COCKPIT WIRE BUNDLES STANDALONE EZAP GENERAL VISUAL INSPECTION IAW C560XL AMM REV46. NO FAULT FOUND.PERFORMED TASK 55-10-00-2100 EMPENNAGE EXTERNAL ZONAL GENERAL VISUAL INSPECTION IAW AMM 560XL (REV 46); NO FAULT FOUND.PERFORMED TASK 55-10-00-2200 HORIZONTAL STABILIZER POSITION SWITCHES L/HIRF DETAILED INSPECTION IAW AMM 560XL (REV 46); NO FAULTPERFORMED TASK 55-10-00-2201 FLUX DETECTORS L/HIRF DETAILED INSPECTION IAW AMM 560XL (REV 46); NO FAULT FOUND.) (SOURCE: 560 XL MM Section 5-12-00)				Mos	17-Dec-2021	72	-/+1m	29-Oct-2027	3 Years (+31 Days)	
						Hrs	2295:34					
						Ldg	1,748					
5-12-16		Inspection Document 16 (Every 96 Months)							RE 5-91-01 MSG-3 INSPECTION TIME LIMITS			
	5 A/F	(Tol. Adjustment: 20d) (SOURCE: 560 XL MM Section 5-12-00)				Mos	09-Oct-2023	96	-/+1m	31-Oct-2031	7 Years (+30 Days)	
						Hrs	3048:30					
						Ldg	2,362					
5-12-17		Inspection Document 17 (6000 Flight Hours, Then Every 1600 Flight Hours Thereafter)							T 5-91-01 MSG-3 INSPECTION TIME LIMITS			≈02-Aug-2028
	5 A/F	(SOURCE: 560 XL MM Section 5-12-00)				Mos						
						Hrs	6,000	-/+25	6000	2683:53 Hrs (+25)		
						Ldg						
5-12-18		Inspection Document 18 (Every 150 Flight Hours)							RE (N/A) 5-91-01 MSG-3 INSPECTION TIME LIMITS			
	5 A/F	(SOURCE: 560 XL MM Section 5-12-00)				Mos						
						Hrs						
						Ldg						
5-12-19		Inspection Document 19 (Every 300 Flight Hours)							RE 5-91-01 MSG-3 INSPECTION TIME LIMITS			≈04-Apr-2025
	5 A/F	(SOURCE: 560 XL MM Section 5-12-00)				Mos	31-Oct-2024					
						Hrs	3308:54	300	-/+25	3608:54	292:47 Hrs (+25)	
						Ldg	2,570					
5-12-20		Inspection Document 20 (Every 100 Flight Hours or 12 Months)							RE (A/R) 5-91-01 MSG-3 INSPECTION TIME LIMITS			
	5 A/F	(SOURCE: 560 XL MM Section 5-12-00)				Mos						
						Hrs						
						Ldg						
5-12-21		Inspection Document 21 (Every 600 Flight Hours or 12 Months)							RE (N/A) 5-91-01 MSG-3 INSPECTION TIME LIMITS			
	5 A/F	(SOURCE: 560 XL MM Section 5-12-00)				Mos						
						Hrs						
						Ldg						

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
5-12-22	Inspection Document 22 (Every 6600 Flight Hours)								RE 5-91-01 MSG-3 INSPECTION TIME LIMITS	≈03-Jun-2029
 5 A/F										
	(SOURCE: 560 XL MM Section 5-12-00)									
5-12-25	Inspection Document 25 (Every 7200 Flight Hours)								RE 5-91-01 MSG-3 INSPECTION TIME LIMITS	≈04-Apr-2030
 5 A/F										
	(SOURCE: 560 XL MM Section 5-12-00)									
SL560XL-05-01	Time Limits/Maintenanance Checks - Transmittal of Pratt & Whitney Canada Maintenance Manual Temporary Revision No. 05-6, Scheduled Maintenance Checks								T (A/R)	Informational
 5 A/F										
	Eff: 06-Dec-2002									
SL560XL-05-02	Corrosive Environment Inspection								T (A/R)	Informational
 5 A/F										
	Eff: 23-Feb-2006									
SL560XL-05-05	Time Limit/Maintenance Checks - MSG-3 Scheduled Maintenance Program Change Bridging Document								T (-)	Service Letter
 5 A/F										
	Eff: 08-Aug-2018									
SL560XL-05-05 Rev 1	Time Limit/Maintenance Checks - MSG-3 Scheduled Maintenance Program Change Bridging Document								T (-)	Informational, Service Letter
 5 A/F										
	Eff: 28-Sep-2018									
SL560XL-05-05 Rev 2	Time Limit/Maintenance Checks - MSG-3 Scheduled Maintenance Program Change Bridging Document								T (A/R)	Informational, Service Letter
 5 A/F										
	Eff: 31-Jan-2019									
SL560XL-05-06	Time Limits/Maintenance Checks - New AE13083-5 Engine and Auxiliary Power Unit Fire Extinguisher Cartridge Squib Interval Grace Period Implementation								T (A/R)	Informational, Service Letter
 5 A/F										
	Eff: 31-Jan-2019									
▼ 8 - LEVELING AND WEIGHING.										
08-10-01-001	Aircraft Weighting								RE	
 8 A/F										
	Inspected Date 09-Oct-2023									
	(UPDATE NOTE: Performed by SC Dusseldorf.)									
▼ 11 - PLACARDS AND MARKINGS										
SL560XL-11-01	Model 560XL Illustrated Parts Catalog and Maintenance Manual Changes								T (A/R)	Informational
 11 A/F										
	Eff: 01-Oct-2003									
▼ 12 - SERVICING - ROUTINE MAINTENANCE										
12-20-27-6400	Flap Roller Lubrication								RE 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
 12 A/F	5-12-01									
	(ZONE: 512, 522, 612, 622) (SOURCE: 560 XL MM Section 5-10-02)									

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
12-20-32-6100		Shimmy Damper Servicing							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	12 A/F	5-12-01					Mos	31-Oct-2024	12	-/+1m (31-Oct-2025)	11.7 Months (+30 Days)
	5543001-12						Hrs	3308:54			
	25017372A						Ldg	2,570			
		(ZONE: 710) (SOURCE: 560 XL MM Section 5-10-02)									
12-20-32-6400		Landing Gear and Landing Gear Doors Lubrication							RE	05-10-01, 05-10-02, Category 5, Category 6	
	12 A/F	5-12-01					Mos	31-Oct-2024	12	-/+1m (31-Oct-2025)	11.7 Months (+30 Days)
		MRBR Task:32-10-00-601, MRBR Task:32-20-00-601, MRBR Task:32-20-00-602, MRBR Task:32-20-00-604, MRBR Task:52-80-00-601, MRBR Task:52-80-00-602, MRBR Task:32-50-00-601 (ZONE: 710, 720, 730) (SOURCE: 560XL MM)					Hrs	3308:54			
							Ldg	2,570			
12-20-52-6400		Cabin Door Hinge Lubrication							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	12 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)
		(ZONE: 810, 811) (SOURCE: 560 XL MM Section 5-10-02)					Hrs	3048:30			
		Note: NOTE: It is recommended you do this task at the same time as Task 52-10-00-2200					Ldg	2,362			
12-26-00-6001		15 Day High Exposure Area Wash							RE (N/A)	Discretionary Maintenance	
	12 A/F						Mos				
		Ref:Chapter 51, Corrosion - Description and Operation, Ref:Chapter 51, Corrosion Severity Maps - Description and Operation, Ref:Chapter 20, Exterior Cleaning/Washing/Rinse - Servicing (SOURCE: 560 XL MM Section 5-19-00)					Hrs				
							Ldg				
12-26-00-6002		45 Day Medium Exposure Area Wash							RE (N/A)	Discretionary Maintenance	
	12 A/F						Mos				
		Ref:Chapter 51, Corrosion - Description and Operation, Ref:Chapter 51, Corrosion Severity Maps - Description and Operation, Ref:Chapter 20, Exterior Cleaning/Washing/Rinse - Servicing (SOURCE: 560 XL MM Section 5-19-00)					Hrs				
							Ldg				
12-26-00-6003		90 Day Low Exposure Area Wash							RE	Discretionary Maintenance	
	12 A/F						Days	31-Oct-2024	90	29-Jan-2025	76 Days
		Ref:Chapter 51, Corrosion - Description and Operation, Ref:Chapter 51, Corrosion Severity Maps - Description and Operation, Ref:Chapter 20, Exterior Cleaning/Washing/Rinse - Servicing (SOURCE: 560 XL MM Section 5-19-00)					Hrs	3308:54			
							Ldg	2,570			
▼ 20 - STANDARD PRACTICES – AIRFRAME											
560XL-20-04		Standard Practices - Cessna Standard Practices Manual							T (A/R)	Service Letter	
	20 A/F						Mos				
		Eff: 05-Oct-2017					Hrs				
							Ldg				
CIL-20-01		Standard Practices - Cessna Certification Of Nondestructive Testing Facilities/Personnel							RE (-)	Informational	
	20 A/F						Mos				
		Eff: 09-Apr-2012					Hrs				
							Ldg				
CIL-20-01 R3		Standard Practices - Cessna Certification of Nondestructive Testing Facilities/Personnel (This SL has been Cancelled)							RE (-)	Service Letter	
	20 A/F						Mos				
		Eff: 30-May-2023					Hrs				
							Ldg				
CIL-20-01 Revision 1		Standard Practices - Cessna Certification Of Nondestructive Testing Facilities/Personnel							RE (-)	Informational	
	20 A/F						Mos				
							Hrs				
							Ldg				
SL560XL-20-01		Cessna Certification of Nondestructive Testing Facilities/Personnel							RE (-)	Optional	
	20 A/F						Mos				
							Hrs				
							Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-20-01 Rev 01  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
SL560XL-20-01 Rev 02  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
SL560XL-20-01 Rev 03  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
SL560XL-20-01 Rev 04  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
SL560XL-20-01 Rev 05  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
SL560XL-20-01 Rev 06  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
SL560XL-20-01 Rev 07  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
SL560XL-20-01 Rev 08  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
SL560XL-20-01 Rev 09  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
SL560XL-20-01 Rev 10  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
SL560XL-20-01 Rev 11  20 A/F Eff: 21-Sep-2012	Cessna Certification of Nondestructive Testing Facilities/Personnel						T (A/R)		Informational	
▼ 21 - AIR CONDITIONING AND PRESSURIZATION										
	A/C Compressor						RE (O/C)			
 21 A/F										
Unknown										
Unknown										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		A/C Condenser Coil Assembly					RE (O/C)				
	21 A/F	Unknown Unknown					Mos				
							Hrs				
							Ldg				
		Acm Cooling Turbine					RE (O/C)				
	21 A/F	2206610-1 1435 New	0				Mos 29-Oct-2015				
			0				Hrs 0				
			0				Ldg 0				
		Bi-Level Valve					RE (O/C)				
	21 A/F	1988-00-3 3366 Left New	0				Mos 29-Oct-2015				
			0				Hrs 0				
			0				Ldg 0				
		Bi-Level Valve					RE (O/C)				
	21 A/F	1988-00-3 3367 Right New	0				Mos 29-Oct-2015				
			0				Hrs 0				
			0				Ldg 0				
		Binary Pressure Switch					RE (O/C)				
	21 A/F	Unknown Unknown					Mos				
							Hrs				
							Ldg				
		Cabin Altitude (U1005) Controller					RE (O/C)				
	21 A/F	52770-116 05041 New	0				Mos 29-Oct-2015				
			0				Hrs 0				
			0				Ldg 0				
		Cabin Altitude Pressure Switch					RE (O/C)				
	21 A/F	GB300NA161 1514241 New	0				Mos 29-Oct-2015				
			0				Hrs 0				
			0				Ldg 0				
		Cabin Duct Overheat (SC013) Switch					RE (O/C)				
	21 A/F	1173T42 4140 New	0				Mos 29-Oct-2015				
			0				Hrs 0				
			0				Ldg 0				
		Cabin Duct Temperature (UC014) Sensor					RE (O/C)				
	21 A/F	Unknown Unknown Left					Mos 29-Oct-2015				
							Hrs 0				
							Ldg 0				
		Cabin Temp Sensor					RE (O/C)				
	21 A/F	1E47-1 2BK11 No.1 New	0				Mos 29-Oct-2015				
			0				Hrs 0				
			0				Ldg 0				
		Cabin Temp Sensor					RE (O/C)				
	21 A/F	1E47-1 4BK15 No.2 New	0				Mos 29-Oct-2015				
			0				Hrs 0				
			0				Ldg 0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Cabin Temperature Control (VT029) Valve								RE (O/C)	
	21 A/F	New	0			Mos	29-Oct-2015				
	27241287-14		0			Hrs	0				
	7BM86F		0			Ldg	0				
		Cockpit Duct Overheat (SF034) Switch								RE (O/C)	
	21 A/F	New	0			Mos	29-Oct-2015				
	1173T42		0			Hrs	0				
	4143		0			Ldg	0				
		Cockpit Temperature Control (VT030) Valve								RE (O/C)	
	21 A/F	New	0			Mos	29-Oct-2015				
	27241287-14		0			Hrs	0				
	9BM134F					Ldg	0				
		Condenser Hour Meter								RE (O/C)	
	21 A/F	Unknown Unknown				Mos					
						Hrs					
						Ldg					
		Condenser/Compressor Switch								RE (O/C)	
	21 A/F	Unknown Unknown				Mos					
						Hrs					
						Ldg					
		ECU Overheat Switch								RE (O/C)	
	21 A/F	New	0			Mos	23-Dec-2016				
	927223-2-3		0			Hrs	360:50				
	0501					Ldg	351				
						Hrs (APU)	201				
						Start (APU)	245				
		ECU Temp Control Valve								RE (O/C)	
	21 A/F	New	0			Mos	29-Oct-2015				
	27241287-14		0			Hrs	0				
	9BK95F		0			Ldg	0				
		Emergency Pressurization Flow (Uy005) Valve								RE (O/C)	
	21 A/F	New	0			Mos	29-Oct-2015				
	4713-19		0			Hrs	0				
	1371		0			Ldg	0				
		Environmental Control Unit								RE (O/C)	
	21 A/F	New	0			Mos	29-Oct-2015				
	2215460-4		0			Hrs	0				
	1462		0			Ldg	0				
		Environmental Temp Controller								RE (O/C)	
	21 A/F	New	0			Mos	29-Oct-2015				
	1E64-2		0			Hrs	0				
	3BM7					Ldg	0				

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
	21 A/F Unknown Unknown	Evaporator Assembly						RE (O/C)				
		Aft						Mos				
								Hrs				
								Ldg				
	21 A/F Unknown Unknown	Evaporator Assembly						RE (O/C)				
		Fwd						Mos				
								Hrs				
								Ldg				
	21 A/F 4001-20 6973A	Lower Warm Air Check Valve						RE (O/C)				
		Left	0				Mos	29-Oct-2015				
		New	0				Hrs	0				
			0				Ldg	0				
	21 A/F 4001-20 6985A	Lower Warm Air Check Valve						RE (O/C)				
		Right	0				Mos	29-Oct-2015				
		New	0				Hrs	0				
			0				Ldg	0				
	21 A/F Unknown Unknown	Manual Control Outflow Valve						RE (O/C)				
								Mos	29-Oct-2015			
								Hrs	0			
								Ldg	0			
	21 A/F 52773-114 1599	Manual Toggle Valve						RE (O/C)				
			0				Mos	29-Oct-2015				
		New	0				Hrs	0				
			0				Ldg	0				
	21 A/F 7003-400 1085	Motor And Blower Assembly						RE (O/C)				
			0				Mos	29-Oct-2015				
		New	0				Hrs	0				
			0				Ldg	0				
	21 A/F 31A437-1 1908	Ozone Converter						RE (O/C)				
		Left	0				Mos	29-Oct-2015				
		New	0				Hrs	0				
			0				Ldg	0				
	21 A/F 31A437-1 1911	Ozone Converter						RE (O/C)				
		Right	0				Mos	29-Oct-2015				
		New	0				Hrs	0				
			0				Ldg	0				
	21 A/F 52771-314 05040	Primary Outflow Valve						RE (O/C)				
			0				Mos	29-Oct-2015				
		New	0				Hrs	0				
			0				Ldg	0				
	21 A/F 52772-114 05035	Secondary Outflow Valve						RE (O/C)				
			0				Mos	29-Oct-2015				
		New	0				Hrs	0				
			0				Ldg	0				

Task No	Description		TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition								DUE	Remaining
	21 A/F 4001-20 6975A	Upper Cool Air Check Valve								RE (O/C)	
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	21 A/F 4001-20 6976A	Upper Cool Air Check Valve								RE (O/C)	
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	21 A/F 2341316-3 1492	Water Separator								RE (O/C)	
			74			Mos	17-Dec-2021				
			2295:34			Hrs	2295:34				
		(UPDATE NOTE: REPLACED CORRODED WATER SEPERATOR SHELL ASSY PN: 2311364-1 AND REINSTALLED WATER SEPERATOR IAW C560XL AMM REV 46 CHAPTER 21-51-00 PERFORMED LEAK CHECK; SAT.)	1,748			Ldg	1,748				
	21 A/F 1E62-1 7BM76	Water Separator Temp 1 Sensor								RE (O/C)	
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
	21 A/F 2215605-1 NSN	Water Spray ECU Aspirator								RE (O/C)	
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
	21 A/F 1E46-1 5BM45	Zone Temperature (UC021) Sensor								RE (O/C)	
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
	21 A/F 1E46-1 5BM44	Zone Temperature (UF029) Sensor								RE (O/C)	
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
12-20-21-1600		Water Separator (Cleaning) Restoration						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈26-Jan-2027
	21 A/F 2341316-3 1492	5-12-07				Mos	31-Oct-2024				
						Hrs	3308:54	1,600	-/+25	(4908:54)	1592:47 Hrs (+25)
		(ZONE: 312) (Tol. Adjustment: -108.9 Hrs) (SOURCE: 560 XL MM Section 5-10-02)				Ldg	2,570				
12-20-21-1601		Ozone Converters (Cleaning) Restoration						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈03-Jun-2029
	21 A/F 31A437-1 1908	Left5-12-22				Mos					
						Hrs		6,600	-/+25	(6600)	3283:53 Hrs (+25)
		(ZONE: 321) (SOURCE: 560 XL MM Section 5-10-02)				Ldg					
12-20-21-1601		Ozone Converters (Cleaning) Restoration						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈03-Jun-2029
	21 A/F 31A437-1 1911	Right5-12-22				Mos					
						Hrs		6,600	-/+25	(6600)	3283:53 Hrs (+25)
		(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02)				Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2013-09-11	Air Conditioning						RE (-)		Mandatory	
 21 A/F	BY SERIAL NUMBER					Mos	05-Jul-2021			
Eff: 05-Jul-2013 Not Applicable						Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				
2013-09-11 Par. (m)	Air Conditioning - Replacement Of The Brushes On A/C Compressor Motors, Part Nos. 1134104-1/1134104-5, Or Deactivation Of The A/C System Parts Return And Reporting Requirements						RE (-)		Mandatory	
 21 A/F						Mos	05-Jul-2021			
Not Applicable	by S/N					Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				
21-22-00-2900	Cabin Air Distribution Check Valves (Borescope) Special Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 21 A/F	5-12-16					Mos	09-Oct-2023	96	-/+1m (31-Oct-2031)	7 Years (+30 Days)
(ZONE: 161, 162) (Tol. Adjustment: 20d) (SOURCE: 560 XL MM Section 5-10-02)						Hrs	3048:30			
						Ldg	2,362			
21-22-00-9600	Cockpit Side Window Defog Filter Discard						RE (A/R)		Discretionary Maintenance	
 21 A/F						Mos				
Ref:Chapter 21, Warm Air Distribution - Inspection/Check (SOURCE: 560 XL MM Section 5-19-00)						Hrs				
Note: As Necessary						Ldg				
21-30-00-7200	Pressurization System Operational and Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 21 A/F	5-12-03					Mos	09-Oct-2023	24	-/+1m (31-Oct-2025)	11.7 Months (+30 Days)
(ZONE: 241, 261, 262) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-03)						Hrs	3048:30			
						Ldg	2,362			
21-31-05-7200	Cabin Altitude Pressure Switch Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 21 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)
GB300NA161 1514241						Hrs	3048:30			
(ZONE: 241) (SOURCE: 560 XL MM Section 5-10-02)						Ldg	2,362			
21-52-00-2100	Vapor Cycle Cooling System Hour Meter Visual Check (Airplanes Incorporating Vapor Cycle Cooling with 1134104-1 and -5 Compressor Motors)						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS, Airworthiness Limitations Inspection Time Limits		
 21 A/F						Mos				
MRBR Task:21-52-00-205 (ZONE: 322) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02, 5-10-01, 5-10-02)						Hrs				
						Ldg				
21-52-00-2101	Vapor Cycle Cooling System 500 Compressor Hour Maintenance (Airplanes Incorporating Vapor Cycle Cooling System with 1134104-1 and -5 Compressor Motors)						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 21 A/F						Mos				
MRBR Task:21-52-00-201, MRBR Task:21-52-00-202, MRBR Task:21-52-00-203 (ZONE: 322) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02)						Hrs				
						Ldg				
21-52-00-2200	Vapor Cycle Cooling System 12 Month Maintenance (Airplanes Incorporating Vapor Cycle Cooling System)						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 21 A/F						Mos				
MRBR Task:21-52-00-204 (ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02)						Hrs				
						Ldg				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
21-52-00-9600		Vapor Cycle Cooling System 500 Compressor Hour Drive Motor Brush Discard (Airplanes Incorporating Vapor Cycle Cooling System with 1134104-1 and -5 Compressor Motors)						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS, Airworthiness Limitations Inspection Time Limits		
	21 A/F						Mos				
		MRBR Task:21-52-00-901 (ZONE: 311) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02, 5-10-02, 5-18-00)					Hrs				
							Ldg				
CIL-21-03		Air Conditioning - Transmittal of Honeywell Service Bulletin 2341316-21-2828, Inspection and Repair of the Interior Surfaces of the Water Separator, PN 2341316-2 and -3, for Corrosion						T (-)		Informational	
	21 A/F						Mos				
	Eff: 22-Oct-2015						Hrs				
		Note: This service letter is for informational purposes only.					Ldg				
CIL-21-03 R1		Air Conditioning - Transmittal of Honeywell Service Bulletin 2341316-21-2828, Inspection and Repair of the Interior Surfaces of the Water Separator, PN 2341316-2 and -3, for Corrosion						T (A/R)		Informational	
	21 A/F						Mos				
	Eff: 25-May-2022						Hrs				
							Ldg				
SL560XL-21-07		Transmittal of Honeywell Service Bulletin 2215460-21-2762, Environmental Control Unit (ECU) - Inspect and Replace the Over Temperature Switch						RE (-)		Optional	
	21 A/F						Mos				
							Hrs				
							Ldg				
SL560XL-21-07 Rev 01		Transmittal of Honeywell Service Bulletin 2215460-21-2762, Environmental Control Unit (ECU) - Inspect and Replace the Over Temperature Switch						RE (-)		Recommended	
	21 A/F						Mos	13-Sep-2021			
	Eff: 10-Feb-2004 Not Applicable	different SN of Aircraft					Hrs				
							Ldg				
SL560XL-21-12		Transmittal of Honeywells Service Bulletin 2215460-21-2814, Air Conditioning - Environmental Control Unit - Modification of Environmental Control Unit (ECU), PN 2215460-3 Series 1, By Replacement of Compressor Outlet Over Temperature Switch, PN 927223-2-2						RE (-)		Informational	
	21 A/F						Mos				
	Eff: 03-Jun-2010						Hrs				
							Ldg				
▼ 22 - AUTOFLIGHT											
		Aileron Drive Servo						RE (O/C)			
	22 A/F						0	Mos	29-Oct-2015		
	822-1168-022	New					0	Hrs	0		
	46YPND						0	Ldg	0		
		Autopilot (PC400) Controller						RE (O/C)			
	22 A/F						Mos	29-Oct-2015			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
		Autopilot Elevator Trim Servo						RE (O/C)			
	22 A/F						6	Mos	09-Aug-2016		
	822-1168-023						Hrs	224:43			
	2HJ1V						Ldg	223			
							Hrs	125			
							Start	148			
							(APU)				

Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	22 A/F 822-1168-022 3CCKP	Elevator Drive Servo							RE (O/C)		
							Mos	09-Nov-2020			
							Hrs	2029:01			
							Ldg	1,561			
	22 A/F Unknown Unknown	Pitch Servo Mount							RE (O/C)		
							Mos	29-Oct-2015			
							Hrs	0			
							Ldg	0			
	22 A/F Unknown Unknown	Pitch Trim Servo Mount							RE (O/C)		
							Mos	29-Oct-2015			
							Hrs	0			
							Ldg	0			
	22 A/F Unknown Unknown	Roll Servo Mount							RE (O/C)		
							Mos	29-Oct-2015			
							Hrs	0			
							Ldg	0			
	22 A/F 822-1168-022 46YPPN	Rudder Drive Servo							RE (O/C)		
							Mos	09-Nov-2020			
							Hrs	2029:01			
							Ldg	1,561			
	22 A/F Unknown Unknown	Yaw Servo Mount							RE (O/C)		
							Mos	29-Oct-2015			
							Hrs	0			
							Ldg	0			
▼ 23 - COMMUNICATIONS											
	23 A/F Unknown Unknown	AFIS Antenna							RE (O/C)		
							Mos	29-Oct-2015			
							Hrs	0			
							Ldg	0			
	23 A/F Unknown Unknown	Airborne Duplexer							RE (O/C)		
							Mos	29-Oct-2015			
							Hrs	0			
							Ldg	0			
	23 A/F Unknown Unknown	Aircell (ATG) Antenna Aft							RE (O/C)		
							Mos	29-Oct-2015			
							Hrs	0			
							Ldg	0			
	23 A/F Unknown Unknown	Aircell (ATG) Antenna Fwd							RE (O/C)		
							Mos	29-Oct-2015			
							Hrs	0			
							Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	23 A/F P12023 1202314183	Aircell Axxess Satellite Transceiver New						RE (O/C)			
			0			Mos	29-Oct-2015				
			0			Hrs	0				
						Ldg	0				
	23 A/F 405040A-001 80828836	Aircell Configuration Module New						RE (O/C)			
			0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
	23 A/F Unknown Unknown	Aircell High Speed Internet (ATG 5000) Unit						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	23 A/F P12083-001 1208373319	Aircell Router New						RE (O/C)			
			0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
	23 A/F Unknown Unknown	Airshow Unit						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	23 A/F Unknown Unknown	ATG4000 Broadband RLU Aircell						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	23 A/F Unknown Unknown	Audio Amplifer						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	23 A/F 822-2381-230 4P7HV	Audio Control Panel Amplifier No.1 New						RE (O/C)			
			0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
	23 A/F 822-2381-230 4P7HX	Audio Control Panel Amplifier No.2 New						RE (O/C)			
			0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
	23 A/F Unknown Unknown	Axxess Call Alerter II (ACA II)						RE (O/C)			
						Mos					
						Hrs					
						Ldg					
	23 A/F Unknown Unknown	Call Alerter Switch						RE (O/C)			
						Mos					
						Hrs					
						Ldg					

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
	23 A/F Unknown Unknown	Cockpit Airshow Controller						RE (O/C)				
							Mos	29-Oct-2015				
							Hrs	0				
							Ldg	0				
	23 A/F 2100-1025-22 000954659	Cockpit Voice Recorder (CVR)						RE (O/C)				
		Repaired						Mos	17-Mar-2023			
								Hrs	2961:08			
								Ldg	2,283			
	23 A/F Unknown Unknown	Cockpit Voice Recorder (CVR) Gravity Switch						RE (O/C)				
							Mos	29-Oct-2015				
							Hrs	0				
							Ldg	0				
	23 A/F 266-E5542-00 ULB047001	Cockpit Voice Recorder (CVR) Underwater Locating Device (ULD)						RE (O/C)				
							Mos	17-Mar-2023				
							Hrs	2961:08				
							Ldg	2,283				
	23 A/F 266-E5542-00 ULB047001 Ref:23-70-00-9600 Note: Expires DEC/2029	Cockpit Voice Recorder (CVR) Underwater Locating Device (ULD) Battery						RE (H/T) 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS				
							Mos	17-Mar-2023				
							Hrs	2961:08				
							Ldg	2,283				
	23 A/F S65-8280-45 326-0865	Comm Antenna						RE (O/C)				
		No.1	0				Mos	29-Oct-2015				
			0				Hrs	0				
			0				Ldg	0				
	23 A/F 21-38-1RF/36 51068	Comm Antenna						RE (O/C)				
		No.2	0				Mos	29-Jul-2021				
			0				Hrs	2169:34				
			0				Ldg	1,654				
	23 A/F 21-38-1RF/36 51067	Comm Antenna						RE (O/C)				
		No.3	0				Mos	29-Jul-2021				
			0				Hrs	2169:34				
			0				Ldg	1,654				
	23 A/F 822-1468-310 4PKRR	Comm Transceiver						RE (O/C)				
		No.1						Mos	24-Nov-2019			
								Hrs	1700:03			
								Ldg	1,331			
	23 A/F 822-1468-110 4R0D9	Comm Transceiver						RE (O/C)				
		No.2						Mos	24-Nov-2019			
								Hrs	1700:03			
								Ldg	1,331			

Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	23 A/F S251-1120-00 001046447	CVR Control Unit New						RE (O/C)			
			0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
	23 A/F Unknown Unknown	Diversity Antenna Remote No.1						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	23 A/F Unknown Unknown	Diversity Antenna Remote No.2						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	23 A/F Unknown Unknown	Flitephone 800 Radiotelephone Antenna						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	23 A/F Unknown Unknown	Flitephone 800 Radiotelephone Tranceiver						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	23 A/F S67-1575-165 449-7707	Flitephone Vi Assembly Antenna New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
				23 A/F Unknown Unknown	GSM/WLAN Antenna						RE (O/C)
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	23 A/F Unknown Unknown	H.F. Antenna/Cable Assembly						RE (O/C)			
						Mos					
						Hrs					
						Ldg					
	23 A/F Unknown Unknown	Handset Phone Cabin						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	23 A/F Unknown Unknown	Handset Phone Cockpit						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	23 A/F Unknown Unknown	High Frequency (HF) Antenna						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
23 A/F Unknown Unknown		High Frequency (HF) Power Amp						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
23 A/F Unknown Unknown		High Frequency (HF) Receiver/Exciter						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
23 A/F Unknown Unknown		KHF950 High Frequency (HF) Adapter						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
23 A/F Unknown Unknown		KHF950 High Frequency (HF) Controller						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
23 A/F Unknown Unknown		Magnastar-CDR						RE (O/C)			
							Mos				
							Hrs				
23 A/F QAR200-30-04 001058013		Mini Quick Access Recorder						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
23 A/F 822-2177-001 4P67C		Nav/Comm Control						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
23 A/F 822-1863-072 4P6PF		Radio Interface Unit						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
23 A/F 822-1864-022 4PP3G		Radio Interface Unit						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
23 A/F 0300-412 15060093		Rosen Cockpit Controller						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
23 A/F Unknown Unknown		Standby Nav/Com Control Unit						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
Stereo Amplifier										
	23 A/F					Mos	29-Oct-2015		RE (O/C)	
	Unknown					Hrs	0			
	Unknown					Ldg	0			
23-00-CUS-001 VHF navigation check (IFR check)										
	23 A/F					Mos	31-Oct-2024	12	31-Oct-2025	11.7 Months
						Hrs	3308:54			
						Ldg	2,570			
Note: CAA Requirement										
23-10-00-7100 Crew Oxygen Mask Microphone and Switch Operational Check										
	23 A/F	Copilot5-12-01				Mos	31-Oct-2024	12	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	11.7 Months (+30 Days)
	MC10-16-150					Hrs	3308:54			
	S103557DMF					Ldg	2,570			
(ZONE: 242) (SOURCE: 560 XL MM Section 5-10-02)										
23-10-00-7100 Crew Oxygen Mask Microphone and Switch Operational Check										
	23 A/F	Pilot5-12-01				Mos	31-Oct-2024	12	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	11.7 Months (+30 Days)
	MC10-16-150					Hrs	3308:54			
	SE23200					Ldg	2,570			
(ZONE: 241) (SOURCE: 560 XL MM Section 5-10-02)										
231051 Aircell Swift Broadband Unit (Sbu) Modem Unit										
	23 A/F					Mos	29-Oct-2015		RE (O/C)	
	405040A	New				Hrs	0			
	14438609					Ldg	0			
231501 Satcom Antenna										
	23 A/F	No.2				Mos	29-Oct-2015		RE (O/C)	
	Unknown					Hrs	0			
	Unknown					Ldg	0			
232010 Comm Transceiver										
	23 A/F	No.3				Mos	29-Oct-2015		RE (O/C)	
	822-1468-310	New				Hrs	0			
	4PKRR					Ldg	0			
23-50-00-7100 Audio Amplifier Emergency Switch Operational Check (Airplanes -5001 thru - 6000)										
	23 A/F					Mos			RE (N/A) 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
						Hrs				
						Ldg				
(ZONE: 241, 242) (SOURCE: 560 XL MM Section 5-10-02)										
23-60-00-7200 Static Discharging System Functional Check										
	23 A/F	5-12-11				Mos	09-Oct-2023	24	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	11.7 Months (+30 Days)
						Hrs	3048:30			
						Ldg	2,362			
(ZONE: 532, 540, 632, 641, 341, 353, 354, 323) (UPDATE NOTE: Found Five Static Wicks Out of Tolerance refer to Order 101049360 for Replacement. Found Rudder Horn Base Out of Tolerance refer to Order 101049363.) (SOURCE: 560 XL MM Section 5-10-02)										

Task No	Description						Categories		Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
23-70-00-9600		DK120 or DK120/90 Cockpit Voice Recorder Underwater Locator Beacon Battery Discard						RE	05-10-01, 05-10-02, 05-12-00, Category 9		
	23 A/F					Mos	17-Mar-2023	72	31-Dec-2029		
	266-E5542-00					Hrs	2961:08		5.1 Years		
	ULB047001					Ldg	2,283				
	Expiration Date 31-Dec-2029 MRBR Task:23-70-00-901, MRBR Task:23-70-00-902 (ZONE: 312) (SOURCE: 560XL MM) Note: 72 Months (DK120) Tracked by Component Expiration Date. NOTE: Per Supplier Recommendation Dukane Seacom 03-TM-0037 (DK120) or 03-TM-0063 (DK120/90) Technical Manual Underwater Acoustic Beacon.										
23-90-20-7200		Transponder Functional Check (Airplanes -5001 thru -6000)						RE (N/A)	Regulatory Inspections/Time Limits		
	23 A/F	No.1				Mos					
	622-9210-501					Hrs					
	2GCVB					Ldg					
	(SOURCE: 560 XL MM Section 5-13-00)										
23-90-20-7200		Transponder Functional Check (Airplanes -5001 thru -6000)						RE (N/A)	Regulatory Inspections/Time Limits		
	23 A/F	No.2				Mos					
	622-9210-501					Hrs					
	4KXVX					Ldg					
	(SOURCE: 560 XL MM Section 5-13-00)										
SB560XL-23-10		Communications - Aviator 300 SATCOM Intermediate Gain Antenna (IGA) Replacement						T (A/R)	Optional		
	23 A/F					Mos					
	Eff: 16-Jun-2021					Hrs					
						Ldg					
SB560XL-23-11		Communications - ATN-B1 Controller Pilot Data Link Communications (CPDLC) Installation						T (A/R)	Optional		
	23 A/F					Mos					
	Eff: 07-Apr-2022					Hrs					
						Ldg					
SL560XL-23-01		Communication - Transmittal Of Airshow Service Bulletin 920720-1 Airshow 400 Digital Interface Unit						T (A/R)	Optional		
	23 A/F					Mos					
	Eff: 04-Nov-1999					Hrs					
						Ldg					
SL560XL-23-02		Communication - Transmittal Of Airshow Service Bulletin 20721-1 Genesys Data Communication Unit						T (A/R)	Optional		
	23 A/F					Mos					
	Eff: 04-Nov-1999					Hrs					
						Ldg					
SL560XL-23-09		Communications - SITA Datalink Frequency Change for North America						T (A/R)	Service Letter		
	23 A/F					Mos					
	Eff: 12-May-2017					Hrs					
						Ldg					
	Note: COMPLIANCE: This service document is for informational purposes only.										
SL560XL-23-10		Communications - ATG 4000 Software Update						T (A/R)	Service Letter		
	23 A/F					Mos					
	Eff: 12-Sep-2017					Hrs					
						Ldg					
	Note: EFFECTIVITY: Aircraft that have the Aircell Broadband System installed by Textron Aviation.										
SL560XL-23-11		Communications - ATG 4000 Software Update To Version 2.8						T (A/R)	Service Letter		
	23 A/F					Mos					
	Eff: 25-Jan-2018					Hrs					
						Ldg					

OK-ECR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-ECR,SN 560-6198

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-23-12	Communications - Installation of the Satcom Antenna Doublers						RE (-)		Optional	
 23 A/F						Mos				
Eff: 12-Jul-2019						Hrs				
						Ldg				
SL560XL-23-13	Communications - Cockpit Voice Recorder (CVR) Control Panel Replacement						RE (-)		Recommended	
 23 A/F						Mos	13-Sep-2021			
Eff: 18-Aug-2021 Not	different SN of Aircraft					Hrs				
Applicable						Ldg				
(AVG MAN HRS: 3)										
SL560XL-23-14	Communications - Transmittal of Collins Operators Bulletin - OPSB 0244-23 RIU-4010 CPDLC ATN-B1 Dropouts						T (A/R)		Informational	
 23 A/F						Mos				
Eff: 27-Nov-2023						Hrs				
						Ldg				
Note: NOTE: This service letter is applicable to the aircraft serial numbers listed above that have complied with Optional Service Bulletin SB560XL-23-11 - Communication - ATN-B1 Controller Pilot Data Link Communications (CPDLC) Installation, original issue or latest.										
▼ 24 - ELECTRICAL POWER										
	30Va Static Inverter						RE (O/C)			
 24 A/F						Mos	29-Oct-2015			
Unknown						Hrs	0			
Unknown						Ldg	0			
	Ac (UD017) Generator						RE (O/C)			
 24 A/F		0				Mos	29-Oct-2015			
91372-3	New	0				Hrs	0			
1918B		0				Ldg	0			
	Ac (UE018) Generator						RE (O/C)			
 24 A/F		0				Mos	29-Oct-2015			
91372-3	New	0				Hrs	0			
1908B		0				Ldg	0			
	Anti Ice NZ019 PCB						RE (O/C)			
 24 A/F		0				Mos	29-Oct-2015			
6618826-1	New	0				Hrs	0			
0503		0				Ldg	0			
	Anti-Ice NZ018 PCB						RE (O/C)			
 24 A/F		0				Mos	29-Oct-2015			
6618826-1	New	0				Hrs	0			
0507		0				Ldg	0			
	APU Generator (UT032) Control Unit						RE (O/C)			
 24 A/F		0				Mos	29-Oct-2015			
51525-001F	New	0				Hrs	0			
P7058		0				Ldg	0			
	APU NZ025 PCB						RE (O/C)			
 24 A/F		0				Mos	29-Oct-2015			
6618808-43	New	0				Hrs	0			
0306		0				Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
APU NZ026 PCB										
24 A/F	6618809-6	New	0			Mos	29-Oct-2015		RE (O/C)	
0307			0			Hrs	0			
			0			Ldg	0			
Battery Disconnect (KY001) Relay										
24 A/F	A876K	New	0			Mos	29-Oct-2015		RE (O/C)	
CT-41787			0			Hrs	0			
			0			Ldg	0			
Battery Temp Indicator										
24 A/F	1229-1	New	0			Mos	29-Oct-2015		RE (O/C)	
3851			0			Hrs	0			
			0			Ldg	0			
Battery Temp Sensor										
24 A/F	19504	New	0			Mos	29-Oct-2015		RE (O/C)	
NSN			0			Hrs	0			
			0			Ldg	0			
Cabin Door NZ007 PCB										
24 A/F	6618823-16	New	0			Mos	09-Aug-2016		RE (O/C)	
0299			0			Hrs	224:43			
						Ldg	223			
						Hrs (APU)	125			
						Start (APU)	148			
Dc (EI009) Voltmeter										
24 A/F	C662502-0101	New	0			Mos	29-Oct-2015		RE (O/C)	
C15-10473			0			Hrs	0			
			0			Ldg	0			
Dc (EI010) Ammeter										
24 A/F	MD144-1	New	0			Mos	29-Oct-2015		RE (O/C)	
B15-10296			0			Hrs	0			
			0			Ldg	0			
Dc (EI011) Ammeter										
24 A/F	MD144-1	New	0			Mos	29-Oct-2015		RE (O/C)	
B15-10295			0			Hrs	0			
			0			Ldg	0			
Dimming NZ023 PCB										
24 A/F	6518366-3	New	0			Mos	29-Oct-2015		RE (O/C)	
0797			0			Hrs	0			
			0			Ldg	0			
EEC Interface (NZ021) PCB										
24 A/F	6618831-11	Left	0			Mos	29-Oct-2015		RE (O/C)	
0306		New	0			Hrs	0			
			0			Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	24 A/F Unknown Unknown	EEC Interface NZ020 PCB Right						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
	24 A/F 6618825-6 0520	Fuel NZ014 PCB Serviceable						RE (O/C)			
							Mos	24-Jan-2022			
							Hrs	2346:30			
	24 A/F 6618825-6 0521	Fuel NZ015 PCB Serviceable						RE (O/C)			
							Mos	24-Jan-2022			
							Hrs	2346:30			
	24 A/F 51525-001F P7022	Generator (UT007) Control Unit New						RE (O/C)			
			0				Mos	29-Oct-2015			
			0				Hrs	0			
	24 A/F 51525-001F P7069	Generator (UT008) Control Unit New						RE (O/C)			
			0				Mos	29-Oct-2015			
			0				Hrs	0			
	24 A/F Unknown Unknown	Ground Fault Current (UT017) Transformer Left						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
	24 A/F Unknown Unknown	Ground Fault Current (UT018) Transformer Right						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
	24 A/F Unknown Unknown	Ground Fault Interrupter						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
	24 A/F 6618820-1 0312	Hydraulic NZ016 PCB New						RE (O/C)			
			0				Mos	29-Oct-2015			
			0				Hrs	0			
	24 A/F 6618822-6 0298	Landing Gear Control NZ009 PCB New						RE (O/C)			
			0				Mos	29-Oct-2015			
			0				Hrs	0			
	24 A/F 6618821-14 0305	Landing Gear NZ004 PCB New						RE (O/C)			
			0				Mos	29-Oct-2015			
			0				Hrs	0			
											
							Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	24 A/F 9914058-6 11501066	Main Battery (UY006)							RE (O/C)		
									Mos	29-Jul-2021	
									Hrs	2169:34	
									Ldg	1,654	
	24 A/F 6618832-17 0300	Miscellaneous NZ035 PCB New							RE (O/C)		
			0						Mos	29-Oct-2015	
			0						Hrs	0	
			0						Ldg	0	
	24 A/F 6618824-6 0306	No Take-Off NZ008 PCB New							RE (O/C)		
			0						Mos	29-Oct-2015	
			0						Hrs	0	
			0						Ldg	0	
	24 A/F 6618828-7 0309	NZ022 Diagnostics PCB New							RE (O/C)		
			0						Mos	29-Oct-2015	
			0						Hrs	0	
			0						Ldg	0	
	24 A/F 1645-1-3 4987	Overvoltage (UZ003) Monitor New							RE (O/C)		
			0						Mos	29-Oct-2015	
			0						Hrs	0	
			0						Ldg	0	
	24 A/F 6618833-5 0300	PCB-APU Current Limiter New							RE (O/C)		
			0						Mos	29-Oct-2015	
			0						Hrs	0	
			0						Ldg	0	
	24 A/F 9914216-6 2530	Power Control (UD015) Unit Overhauled							RE (O/C)		
									Mos	22-Jun-2022	
			0						Hrs	2640:29	
			0						Ldg	2,019	
	24 A/F 91479-1 2952	Power Control (UE016) Unit New							RE (O/C)		
			0						Mos	29-Oct-2015	
			0						Hrs	0	
			0						Ldg	0	
	24 A/F 6518352-5 NSN	Press NZ002 PCB New							RE (O/C)		
			0						Mos	29-Oct-2015	
			0						Hrs	0	
			0						Ldg	0	
	24 A/F 6618830-7 0455	Rudder Bias NZ029 PCB New							RE (O/C)		
			0						Mos	18-Jun-2020	
			0						Hrs	1815:52	
			0						Ldg	1,420	
	24 A/F 6618706-1 1051	Squat Switch NZ006 PCB New							RE (O/C)		
			0						Mos	29-Oct-2015	
			0						Hrs	0	
			0						Ldg	0	

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
Start Control NZ012 PCB										
24 A/F	6318324-5	New	0			Mos	29-Oct-2015		RE (O/C)	
	NSN		0			Hrs	0			
			0			Ldg	0			
Start Control NZ013 PCB										
24 A/F	6318324-5	New	0			Mos	29-Oct-2015		RE (O/C)	
	NSN		0			Hrs	0			
			0			Ldg	0			
Start NZ013 PCB										
24 A/F	6618829-14	Left	0			Mos	29-Oct-2015		RE (O/C)	
	0501	New	0			Hrs	0			
			0			Ldg	0			
Start NZ013 PCB										
24 A/F	6618829-14	Right	0			Mos	29-Oct-2015		RE (O/C)	
	0515	New	0			Hrs	0			
			0			Ldg	0			
Tail Deice (NZ005) PCB										
24 A/F	Unknown					Mos	29-Oct-2015		RE (O/C)	
	Unknown					Hrs	0			
						Ldg	0			
Tail Deice Cont NZ031 PCB										
24 A/F	6618730-1	New	0			Mos	29-Oct-2015		RE (O/C)	
	0649		0			Hrs	0			
			0			Ldg	0			
Tail Deice Mon NZ033 PCB										
24 A/F	6618731-1	New	0			Mos	29-Oct-2015		RE (O/C)	
	0659		0			Hrs	0			
			0			Ldg	0			
Trim (NZ001) PCB										
24 A/F	Unknown					Mos	29-Oct-2015		RE (O/C)	
	Unknown					Hrs	0			
						Ldg	0			
Two Position Tail NZ017 PCB										
24 A/F	6618827-1	New	0			Mos	29-Oct-2015		RE (O/C)	
	0319		0			Hrs	0			
			0			Ldg	0			
2017-04-14 Electrical Power - Inspections of the Fuel Tube and Right Alternating Current (AC) Generator Wires										
24 A/F							RE (-)		Mandatory	
	Eff: 09-Mar-2017 Complied With					Mos	30-Jan-2017			
	(AVG MAN HRS: 17) (ISSUING AUTHORITY: FAA)					Hrs	388:12			
						Ldg	381			
2017-04-14 Par. 2(g) Electrical Power - Inspections of the Fuel Tube and Right Alternating Current (AC) Generator Wires - Inspections, Adjustments, and Corrective Actions										
24 A/F							RE (-)		Mandatory	
	Eff: 09-Mar-2017 Complied	SL560XL-24-07 ON THE 30/01/17				Mos	30-Jan-2017			
	With					Hrs	388:12			
	(AVG MAN HRS: 16) (ISSUING AUTHORITY: FAA)					Ldg	381			

Task No		Description								Categories		Time				
SEQ	PN/SN	MOC Note or Component Condition					TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
2017-04-14 Par. 2(h)		Electrical Power - Inspections of the Fuel Tube and Right Alternating Current (AC) Generator Wires - Reporting										RE (-)	Mandatory			
	24 A/F										Mos	30-Jan-2017				
	Eff: 09-Mar-2017 Complied With										Hrs	388:12				
	(AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA)										Ldg	381				
	Note: COMPLIANCE: If the inspection was done before the effective date of this AD: Submit the report within 10 days after the effective date of this AD.															
24-32-00-7200		44 Amp-Hour Marathon Ni-Cad Main Battery (Capacity Check) Functional Check										RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈25-May-2025		
	24 A/F	5-12-20									Mos	31-Oct-2024	12	-/+1m	31-Oct-2025	11.7 Months (+30 Days)
	9914058-6										Hrs	3308:54	400	-/+25	3708:54	392:47 Hrs (+25)
	11501066										Ldg	2,570				
	(ZONE: 311) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00)															
Note: The inspection interval can be adjusted after the water loss per cell is established. Refer to the Battery Service Table in the task.																
24-32-00-7201		43 Amp-Hour Saft Ni-Cad Main Battery (Capacity Check) Functional Check										RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	24 A/F										Mos					
	9914058-6										Hrs					
	11501066										Ldg					
	(ZONE: 311) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00)															
24-32-00-7202		42 Amp-Hour Concorde Lead Acid Main Battery (Capacity Check) Functional Check										RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	24 A/F										Mos					
	9914058-6										Hrs					
	11501066										Ldg					
	(ZONE: 311) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00)															
24-32-00-7203		L3 Com PS-835D Standby Battery Pack (Capacity Check) Functional Check										RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	24 A/F	Left									Mos					
	100-2410-04										Hrs					
	1075										Ldg					
	(ZONE: 211) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00)															
24-32-00-7203		L3 Com PS-835D Standby Battery Pack (Capacity Check) Functional Check										RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	24 A/F	Right									Mos					
	Unknown										Hrs					
	Unknown										Ldg					
	(ZONE: 212) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00)															

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
24-32-00-7204		L3 Com PS-855B Standby Battery Pack (Capacity Check) Functional Check							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	24 A/F	Left					Mos	17-Dec-2021				
	100-2410-04						Hrs	2295:34				
	1075						Ldg	1,748				
	(ZONE: 211) (Tol. Adjustment: -28d) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 01 IAW AMM 560XL (REV 46) CHAPTER 5-12-01 (REV 46)PERFORMED TASK 12-20-27-6400 Flap Roller Lubrication IAW MODEL 560XL MAINTENANCE MANUAL REV.46 CH-12-20-27.PERFORMED TASK 12-20-27-6401 TRIM ACTUATORS LUBRICATION SAT., IAW C560XL AMM REV.46 CH12-20-27-6401 REV.46.PERFORMED TASK 12-20-32-6100 Shimmy Damper Servicing IAW MODEL 560XL MAINTENANCE MANUAL REV.46 CH-12-20-32. FOUND SHIMMY DAMPERSERVICE CHECK VALVE U/S REFER TO ORDER 100335873.PERFORMED TASK 12-20-32-6400 LANDING GEAR AND LANDING GEAR DOORS LUBRICATION IAW C560XL AMM REV 46PERFORMED TASK 12-20-52-6401 Door Keyed Cam Lock Lubrication IAW MODEL 560XL MAINTENANCE MANUAL REV.46 CH-12-20-52. NO FAULT FOUND.TASK NOT APPLICABLE DUE TO AC S/N 560XL-6198.PERFORMED 23-10-00-7100 CREW OXYGEN MASK MICROPHONE AND SWITCH OPERATIONAL CHECK IAW AMM 560XL (REV 46); NO FAULT FOUND.TASK NOT APPLICABLE DUE TO AC S/N 560XL-6198.TASK NOT APPLICABLE; EQUIPMENT NOT INSTALLED.TASK NOT APPLICABLE; EQUIPMENT NOT INSTALLED.PERFORMED TASK 25-60-00-2200 FIRST AID KIT DETAILED INSPECTION IAW AMM 560XL (REV 46); FOUND FAK DUE TO EXPIRE ON 18/NOV/2021; REFERTO ORDER #100335879.PERFORMED TASK 25-60-00-2201 SMOKE GOGGLES DETAILED INSPECTION IAW AMM 560XL (REV 46); NO FAULT FOUND.PERFORMED TASK 25-60-00-9602 CREW FLASHLIGHT D-CELL BATTERY DISCARD IAW AMM 560XL (REV 46) PERFORMED TASK 27-10-00-2202 AILERON TRIM ACTUATOR DETAILED INSPECTIONIAW MODEL C560XL MM (REV.46) CHAPTER 27-10-00 (REV.46)NO FAULTS FOUNDFOUND SATPERFORMED TASK 27-20-00-2201 RUDDER TRIM ACTUATOR DETAILED INSPECTIONIAW MODEL C560XL MM (REV.46) CHAPTER 27-20-00 (REV.46)FOUND BOTH SCREW ASSYS DAMAGED, FOR FURTHER INFORMATION REFER TO ITEM #100347440PERFORMED TASK 28-11-04-2200 Fuel Filler Cap Detailed Inspection IAW MODEL 560XL MAINTENANCE MANUAL REV.46 CH-28-11-04. NO FAULTFOUND.) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00)											
24-32-00-7204		L3 Com PS-855B Standby Battery Pack (Capacity Check) Functional Check							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	24 A/F	Right					Mos	17-Dec-2021				
	Unknown						Hrs	2295:34				
	Unknown						Ldg	1,748				
	(ZONE: 212) (Tol. Adjustment: -28d) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 01 IAW AMM 560XL (REV 46) CHAPTER 5-12-01 (REV 46)PERFORMED TASK 12-20-27-6400 Flap Roller Lubrication IAW MODEL 560XL MAINTENANCE MANUAL REV.46 CH-12-20-27.PERFORMED TASK 12-20-27-6401 TRIM ACTUATORS LUBRICATION SAT., IAW C560XL AMM REV.46 CH12-20-27-6401 REV.46.PERFORMED TASK 12-20-32-6100 Shimmy Damper Servicing IAW MODEL 560XL MAINTENANCE MANUAL REV.46 CH-12-20-32. FOUND SHIMMY DAMPERSERVICE CHECK VALVE U/S REFER TO ORDER 100335873.PERFORMED TASK 12-20-32-6400 LANDING GEAR AND LANDING GEAR DOORS LUBRICATION IAW C560XL AMM REV 46PERFORMED TASK 12-20-52-6401 Door Keyed Cam Lock Lubrication IAW MODEL 560XL MAINTENANCE MANUAL REV.46 CH-12-20-52. NO FAULT FOUND.TASK NOT APPLICABLE DUE TO AC S/N 560XL-6198.PERFORMED 23-10-00-7100 CREW OXYGEN MASK MICROPHONE AND SWITCH OPERATIONAL CHECK IAW AMM 560XL (REV 46); NO FAULT FOUND.TASK NOT APPLICABLE DUE TO AC S/N 560XL-6198.TASK NOT APPLICABLE; EQUIPMENT NOT INSTALLED.TASK NOT APPLICABLE; EQUIPMENT NOT INSTALLED.PERFORMED TASK 25-60-00-2200 FIRST AID KIT DETAILED INSPECTION IAW AMM 560XL (REV 46); FOUND FAK DUE TO EXPIRE ON 18/NOV/2021; REFERTO ORDER #100335879.PERFORMED TASK 25-60-00-2201 SMOKE GOGGLES DETAILED INSPECTION IAW AMM 560XL (REV 46); NO FAULT FOUND.PERFORMED TASK 25-60-00-9602 CREW FLASHLIGHT D-CELL BATTERY DISCARD IAW AMM 560XL (REV 46) PERFORMED TASK 27-10-00-2202 AILERON TRIM ACTUATOR DETAILED INSPECTIONIAW MODEL C560XL MM (REV.46) CHAPTER 27-10-00 (REV.46)NO FAULTS FOUNDFOUND SATPERFORMED TASK 27-20-00-2201 RUDDER TRIM ACTUATOR DETAILED INSPECTIONIAW MODEL C560XL MM (REV.46) CHAPTER 27-20-00 (REV.46)FOUND BOTH SCREW ASSYS DAMAGED, FOR FURTHER INFORMATION REFER TO ITEM #100347440PERFORMED TASK 28-11-04-2200 Fuel Filler Cap Detailed Inspection IAW MODEL 560XL MAINTENANCE MANUAL REV.46 CH-28-11-04. NO FAULTFOUND.) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00)											
24-32-00-7205		Securaplane Standby Battery (Energy Level Test) Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	24 A/F	Left5-12-03					Mos	09-Oct-2023	24	-/+ 1m	(31-Oct-2025)	11.7 Months (+30 Days)
	100-2410-04						Hrs	3048:30				
	1075						Ldg	2,362				
	(ZONE: 211) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00) Note: NOTE:Per Supplier Recommendation. Reference Securaplane Technologies Inc. 24-32-24 Component Maintenance Manual.											

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
24-32-00-9600	Securaplane Battery Discard						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 24 A/F	Left					Mos	31-Oct-2024	48	30-Jun-2028	3.6 Years
100-2410-04						Hrs	3308:54			
1075						Ldg	2,570			
Expiration Date 24-Jun-2028 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) Note: 48 Months Tracked by Component Expiration Date. NOTE: Per Supplier Recommendation. Reference Securaplane Technologies Inc. 24-32-24 Component Maintenance Manual										
24-41-02-7200	External Power Overvoltage System Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 24 A/F	5-12-13					Mos	17-Dec-2021	72	-/+1m (29-Oct-2027)	3 Years (+31 Days)
						Hrs	2295:34			
	(ZONE: 321) (Tol. Adjustment: -48d) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 13 IAW AMM 560XL (REV 46) CHAPTER 5-12-13 (REV 46)) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	1,748			
560XL-24-01	Electrical Power - Saft Battery Installation						T (A/R)		Optional	
 24 A/F						Mos				
Eff: 13-May-1999						Hrs				
						Ldg				
560XL-24-02	Electrical Power - Concorde Battery Installation						RE (-)		Recommended	
 24 A/F						Mos				
						Hrs				
						Ldg				
560XL-24-02 Rev 01	Electrical Power - Concorde Battery Installation						T (A/R)		Optional	
 24 A/F						Mos				
Eff: 20-Feb-2001						Hrs				
						Ldg				
560XL-24-16	APU Starter/Generator Wiring Improvement						RE (-)		Recommended	
 24 A/F						Mos	13-Sep-2021			
Eff: 15-Nov-2010 Not Applicable	different SN of Aircraft					Hrs				
						Ldg				
560XL-24-17	Tailcone Inverter Relocation						RE (-)		Discretionary	
 24 A/F						Mos				
Eff: 28-Jul-2010						Hrs				
						Ldg				
560XL-24-18	Standby Power Wiring Modification						RE (-)		Recommended	
 24 A/F						Mos	13-Sep-2021			
Eff: 03-Nov-2011 Not Applicable	Different SN of Aircraft					Hrs				
						Ldg				
560XL-24-19	Electrical Power - Right Hand Engine Wire Bundle Routing Improvement						RE (-)		Recommended	
 24 A/F						Mos	06-Jun-2018			
Eff: 08-Mar-2017 Complied With	NO WIRING BUNDLE DAMAGED NOTED. INSTALLED CLAMPS TO ACHIEVE 0.5 GAP BETWEEN BUNDLE AND FADEC MOUNTING BRACKET.					Hrs	1000:36			
(AVG MAN HRS: 1)						Ldg	848			
560XL-24-20	Electrical Power - AC J-Box Wire Bundle Anchor Installation						RE (-)		Mandatory	
 24 A/F						Mos	23-May-2019			
Eff: 03-Oct-2017 Complied With						Hrs	1397:27			
(AVG MAN HRS: 3)						Ldg	1,136			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SB560XL-24-21	Electrical Power - Install New Right Alternator Power Control Unit (PCU) (UE016) Mounting Bracket								T (-)	Recommended, Service Bulletin
 24 A/F						Mos				
	(AVG MAN HRS: 3)					Hrs				
	Note: COMPLIANCE: This service document should be accomplished at a scheduled maintenance period or inspection.					Ldg				
	NOTE: This service document provides parts and instructions to replace the existing 6658018-5 Bracket Assembly with a newly designed 6658018-9 Bracket Assembly.									
SB560XL-24-21 R1	Electrical Power - Install New Right Alternator Power Control Unit (PCU) (UE016) Mounting Bracket								RE (-)	Recommended
 24 A/F						Mos	17-Dec-2021			
	Eff: 13-Mar-2020 Complied With					Hrs	2295:34			
	(AVG MAN HRS: 3) (UPDATE NOTE: PERFORMED SB560XL-24-21 R1 ELECTRICAL POWER - INSTALL NEW RIGHT ALTERNATOR POWER CONTROL UNIT (PCU) (UE016) MOUNTING BRACKET IAW SB INSTRUCTIONS PERFORMED OPERATIONAL CHECK; SAT.)					Ldg	1,748			
SL560XL-24-07	Electrical Power - Right Ac Generator Wire Routing Verification								RE (-)	Mandatory
 24 A/F						Mos	02-Feb-2017			
	Eff: 13-Jan-2017 Complied With					Hrs	388:12			
	(AVG MAN HRS: 16)					Ldg	381			
SL560XL-24-08	Starting - Engine Starter Generator and Auxiliary Power Unit (APU) Starter Generator Ground Repair								RE (-)	Service Letter
 24 A/F						Mos	07-Nov-2018			
	Eff: 02-Jan-2018 Complied With					Hrs	1230:36			
	(AVG MAN HRS: 13)					Ldg	1,009			
SL560XL-24-09	Electrical Power - Battery Temperature Indicator Gage Blanking Plate Installation								T (A/R)	Service Letter
 24 A/F						Mos				
	Eff: 30-Mar-2018					Hrs				
						Ldg				
▼ 25 - EQUIPMENT/FURNISHINGS										
	Crew Flashlight								RE (O/C)	
 25 A/F						Mos	29-Oct-2015			
	Unknown					Hrs	0			
	Unknown					Ldg	0			
	Crew Flashlight Battery								RE (H/T)	
 25 A/F						Mos	29-Oct-2015			
	Unknown					Hrs	0			
	Unknown					Ldg	0			
	Crew Seat Assy								RE (O/C)	
 25 A/F	Copilot					Mos	29-Oct-2015			
	Unknown					Hrs	0			
	Unknown					Ldg	0			
	Crew Seat Assy								RE (O/C)	
 25 A/F	Pilot					Mos	29-Oct-2015			
	Unknown					Hrs	0			
	Unknown					Ldg	0			
	Digital Interface Unit (DIU)								RE (O/C)	
 25 A/F						Mos	29-Oct-2015			
	Unknown					Hrs	0			
	Unknown					Ldg	0			

Task No	Description										Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	DUE	Remaining
DVD Player									RE (O/C)			
	25 A/F Unknown Unknown							Mos	29-Oct-2015			
								Hrs	0			
								Ldg	0			
ELT Antenna									RE (O/C)			
	25 A/F 110-340 471739	New	0					Mos	29-Oct-2015			
			0					Hrs	0			
			0					Ldg	0			
Emergency Locator Transmitter									RE (O/C)			
	25 A/F 453-5060 16359 Brand C:256019	New	0					Mos	29-Oct-2015			
			0					Hrs	0			
			0					Ldg	0			
Emergency Locator Transmitter Battery									RE (H/T) 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	25 A/F 453-0133 385185-035 Brand C:256025, Ref.:25-60-10-9600 (Manual Adjustment: 11d)	New	0					Mos	20-Sep-2020			
			0					Hrs	1997:10			
			0					Ldg	1,542			
Externally Servicable Toilet									RE (O/C)			
	25 A/F 9919009-5 0360	New	0					Mos	29-Oct-2015			
			0					Hrs	0			
			0					Ldg	0			
First Aid Kit									RE (O/C)			
	25 A/F FAK10 7193A0 Expiration Date 01-Apr-2025	Serviceable						Mos	19-Dec-2023 01-Apr-2025 4.6 Months			
			0					Hrs	3111:35			
			0					Ldg	2,411			
Heated Water Tank (Prepco)									RE (O/C)			
	25 A/F Unknown Unknown							Mos	29-Oct-2015			
								Hrs	0			
								Ldg	0			
Life Raft									RE (O/C)			
	25 A/F Unknown Unknown (ZONE: 261, 262)							Mos	29-Oct-2015			
								Hrs	0			
								Ldg	0			
Life Vest									RE (O/C)			
	25 A/F P01074-207 15080810064	Copilot	1					Mos	29-Oct-2015			
								Hrs	0			
								Ldg	0			
Life Vest									RE (O/C)			
	25 A/F Unknown Unknown	Lavatory						Mos	29-Oct-2015			
								Hrs	0			
								Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
25 A/F P01074-207 15080810055		Life Vest Left No.1	1			Mos	29-Oct-2015	RE (O/C)			
							Hrs	0			
							Ldg	0			
25 A/F P0074-207 15072300135		Life Vest Left No.2				Mos	07-Nov-2018	RE (O/C)			
							Hrs	1230:36			
							Ldg	1,009			
25 A/F P01074-207 15072300107		Life Vest Left No.3				Mos	05-Nov-2017	RE (O/C)			
							Hrs	811			
							Ldg	699			
25 A/F Unknown Unknown		Life Vest Left No.4				Mos	29-Oct-2015	RE (O/C)			
							Hrs	0			
							Ldg	0			
25 A/F P01074-207 15072300023		Life Vest No.10	2			Mos	29-Oct-2015	RE (O/C)			
							Hrs	0			
							Ldg	0			
25 A/F P01074-207 15072300044		Life Vest No.11				Mos	05-Nov-2017	RE (O/C)			
							Hrs	811			
							Ldg	699			
25 A/F P01074-207 15080810080		Life Vest No.9				Mos	05-Nov-2017	RE (O/C)			
							Hrs	811			
							Ldg	699			
25 A/F P01074-207 15080810020		Life Vest Pilot				Mos	05-Nov-2017	RE (O/C)			
							Hrs	811			
							Ldg	699			
25 A/F P0074-207 15072300086		Life Vest Right No.1				Mos	07-Nov-2018	RE (O/C)			
							Hrs	1230:36			
							Ldg	1,009			
25 A/F P01074-207 15072300050		Life Vest Right No.2				Mos	05-Nov-2017	RE (O/C)			
							Hrs	811			
							Ldg	699			
25 A/F P01074-207 15072300088		Life Vest Right No.3				Mos	05-Nov-2017	RE (O/C)			
							Hrs	811			
							Ldg	699			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	25 A/F Unknown Unknown	Life Vest Right No.4					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F Unknown Unknown	Passenger Seat Left No.1					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F Unknown Unknown	Passenger Seat Left No.2					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F Unknown Unknown	Passenger Seat Left No.3					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F Unknown Unknown	Passenger Seat Left No.4					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F Unknown Unknown	Passenger Seat Right No.1					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F Unknown Unknown	Passenger Seat Right No.2					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F Unknown Unknown	Passenger Seat Right No.3					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F Unknown Unknown	Passenger Seat Right No.4					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F Unknown Unknown	Smoke Goggle Assembly Left					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F Unknown Unknown	Smoke Goggle Assembly Right					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
Temperature Probe										
25 A/F	Unknown					Mos	29-Oct-2015		RE (O/C)	
Unknown	Unknown					Hrs	0			
						Ldg	0			
Vanity Sink Drain Valve										
25 A/F	Unknown					Mos	29-Oct-2015		RE (O/C)	
Unknown	Unknown					Hrs	0			
						Ldg	0			
2016-0164 Cabin Attendant Seat - Inspection (Superseded by AD 2017-0001)										
25 A/F	Eff: 24-Aug-2016 Superseded (ISSUING AUTHORITY: EASA)					Mos	09-Sep-2017		RE (-)	Mandatory (Appliance AD)
						Hrs				
						Ldg				
2017-16-01 PARA (G) Perform General Visual Inspections Of The Elt For Discrepancies; Checks , Tests And Verifications As Applicable, To Ensure The Elt Is Functioning, And All Applicable Corrective Actions										
25 A/F	Not Applicable (ISSUING AUTHORITY: FAA)					Mos			RE (-)	
	BY EQUIPMENT INSTALLED					Hrs				
						Ldg				
2019-0235 Par. (1)(2) ACR ELECTRONICS, Inc. - Emergency Locator Transmitter - Inspection / Testing										
25 A/F	Not Applicable (ISSUING AUTHORITY: EASA)					Mos			RE (-)	Mandatory (Appliance AD)
	UNIT NEW WHEN INSTALLED					Hrs				
						Ldg				
2019-0235 Par. (3)(4) ACR ELECTRONICS, Inc. - Emergency Locator Transmitter - Repetitive Test Interval Reduction										
25 A/F	Not Applicable (ISSUING AUTHORITY: EASA)					Mos			RE (-)	Mandatory (Appliance AD)
	UNIT NEW WHEN INSTALLED					Hrs				
	Note: COMPLIANCE: Upon exceeding 5 years TIS by an affected part, reduce the interval of the G-switch testing, as required by paragraph (1.1) of this AD, to the applicable value as specified in section 8 of the SB.					Ldg				
2019-0235 Par. (5)(6) ACR ELECTRONICS, Inc. - Emergency Locator Transmitter - Modification / Replacement (Terminating Action)										
25 A/F	Eff: 04-Oct-2019 Not Applicable (ISSUING AUTHORITY: EASA)					Mos	29-Sep-2020		RE (-)	Mandatory (Appliance AD)
	BY ELT CURRENTLY FITTED TO RSXP WAS NEW AT BUILD THIS ELT, P/N 453-5060 S/N 16359 IS NOT CLASSED AS AN AFFECTED PART					Hrs				
						Ldg				
2021-07-13 Par. (e)(1) Pacific Scientific Company Rotary Buckle Assembly, P/Ns 1111430 and 1111475 - Inspect the Buckle Handle for a Crack										
25 A/F	Eff: 11-May-2021 Not Applicable (UPDATE NOTE: NOT APPLICABLE TO 560XL-6198; AM SAFE SEATBELTS INSTALLED.) (ISSUING AUTHORITY: FAA)					Mos	17-Dec-2021		RE (-)	Mandatory (Appliance AD)
	Note: COMPLIANCE: Within 6 months, inspect the buckle handle for a crack. If the buckle handle is cracked, before further flight, remove the buckle as depicted in Figure 5 and by following the Procedures, paragraph 9, of SB 25-1111432, and replace it with an airworthy buckle, except you are not required to return the removed buckle to Pacific Scientific.					Hrs	2295:34			
						Ldg	1,748			
2021-07-13 Par. (e)(2) Pacific Scientific Company Rotary Buckle Assembly, P/Ns 1111430 and 1111475 - Measure the Thickness of the Buckle Handle Vane										
25 A/F	Eff: 11-May-2021 Not Applicable (UPDATE NOTE: NOT APPLICABLE TO 560XL-6198; AM SAFE SEATBELTS INSTALLED.) (ISSUING AUTHORITY: FAA)					Mos	17-Dec-2021		RE (-)	Mandatory (Appliance AD)
	Note: COMPLIANCE: Within 12 months, measure the thickness of the buckle handle vane as depicted in Figure 3 of SB 25-1111432. If the handle vane thickness is 0.125 inch or greater, before further flight, remove the buckle from service and replace it with an airworthy buckle.					Hrs	2295:34			
						Ldg	1,748			
2023-12-25 Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets										
25 A/F	Not Applicable (ISSUING AUTHORITY: FAA)					Mos			RE (N/A)	Mandatory
	Afected PN not installed.					Hrs				
						Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2023-12-25 Par. (g)	Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets - Inspection						T (N/A)		Mandatory	
25 A/F										
Not Applicable	Afected PN not installed.									
(ISSUING AUTHORITY: FAA)										
2023-12-25 Par. (h)	Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets - Follow-On and Corrective Action						T (N/A)		Mandatory	
25 A/F										
Not Applicable	Afected PN not installed.									
(ISSUING AUTHORITY: FAA)										
2023-14-10	Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats (Supersedes FAA AD 2019-21-06)						RE (N/A)		Mandatory (Appliance AD)	
25 A/F										
Not Applicable	Afected PN not installed.									
(ISSUING AUTHORITY: FAA)										
2023-14-10 Par. (g)(1)	Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Modify and Re-Identify each Affected Pilot and Co-Pilot Seat						RE (N/A)		Mandatory (Appliance AD)	
25 A/F										
Not Applicable	Afected PN not installed.									
(ISSUING AUTHORITY: FAA)										
2023-14-10 Par. (g)(2)(i)	Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Inspect the Track Lock Spring of Each Seat						RE (N/A)		Mandatory (Appliance AD)	
25 A/F										
Not Applicable	Afected PN not installed.									
(ISSUING AUTHORITY: FAA)										
2023-14-10 Par. (g)(2)(ii)	Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Replace both Track Lock Springs of the Affected Seat						RE (N/A)		Mandatory (Appliance AD)	
25 A/F										
Not Applicable	Afected PN not installed.									
(ISSUING AUTHORITY: FAA)										
2023-14-10 Par. (h)	Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - New Mandatory Terminating Action						RE (N/A)		Mandatory (Appliance AD)	
25 A/F										
Not Applicable	Afected PN not installed.									
(ISSUING AUTHORITY: FAA)										
250002	Av Visor Plus Processor						RE (O/C)			
25 A/F										
90007-003	New	0				29-Oct-2015				
NSN		0				0				
		0				0				
25-00-CUS-001	ELT Operation Check						RE			
25 A/F						31-Oct-2024	12		31-Oct-2025	11.7 Months
						3308:54				
						2,570				
Note: CAA Requirement										

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
25-11-01-2200		Crew Seat Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈09-Oct-2026
	25 A/F	Copilot5-12-08				Mos	17-Dec-2021				
	Unknown					Hrs	2295:34	2,400	-/+25	(4695:34)	1379:27 Hrs (+25)
	Unknown					Ldg	1,748				
	(ZONE: 244) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 25-11-01-2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES -5002 THRU -5555 INCORPORATINGSB560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019,CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560 XL MM Section 5-10-02)										
25-11-01-2200		Crew Seat Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈09-Oct-2026
	25 A/F	Pilot5-12-08				Mos	17-Dec-2021				
	Unknown					Hrs	2295:34	2,400	-/+25	(4695:34)	1379:27 Hrs (+25)
	Unknown					Ldg	1,748				
	(ZONE: 243) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 25-11-01-2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES -5002 THRU -5555 INCORPORATINGSB560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019,CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560 XL MM Section 5-10-02)										
25-21-01-2200		Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.15-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
	Unknown					Hrs	3048:30				
	Unknown					Ldg	2,362				
	(ZONE: 252, 261, 262, 171)										
25-21-01-2200		Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.25-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
	Unknown					Hrs	3048:30				
	Unknown					Ldg	2,362				
	(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)										
25-21-01-2200		Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.35-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
	Unknown					Hrs	3048:30				
	Unknown					Ldg	2,362				
	(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
25-21-01-2200	Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 25 A/F	Left No.45-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
Unknown					Hrs	3048:30				
Unknown					Ldg	2,362				
(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)										
25-21-01-2200	Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 25 A/F	Right No.15-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
Unknown					Hrs	3048:30				
Unknown					Ldg	2,362				
(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)										
25-21-01-2200	Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 25 A/F	Right No.25-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
Unknown					Hrs	3048:30				
Unknown					Ldg	2,362				
(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)										
25-21-01-2200	Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 25 A/F	Right No.35-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
Unknown					Hrs	3048:30				
Unknown					Ldg	2,362				
(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)										
25-21-01-2200	Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 25 A/F	Right No.45-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
Unknown					Hrs	3048:30				
Unknown					Ldg	2,362				
(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)										
25-60-00-2200	First Aid Kit Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 25 A/F	5-12-01				Mos	31-Oct-2024	12	-/+1m	(31-Oct-2025)	11.7 Months (+30 Days)
FAK10					Hrs	3308:54				
7193A0					Ldg	2,570				
(ZONE: 241, 242) (SOURCE: 560 XL MM Section 5-10-02)										
25-60-00-2201	Smoke Goggle Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 25 A/F	Left5-12-01				Mos	31-Oct-2024	12	-/+1m	(31-Oct-2025)	11.7 Months (+30 Days)
Unknown					Hrs	3308:54				
Unknown					Ldg	2,570				
(ZONE: 241) (SOURCE: 560 XL MM Section 5-10-02)										
25-60-00-2201	Smoke Goggle Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 25 A/F	Right5-12-01				Mos	31-Oct-2024	12	-/+1m	(31-Oct-2025)	11.7 Months (+30 Days)
Unknown					Hrs	3308:54				
Unknown					Ldg	2,570				
(ZONE: 242) (SOURCE: 560 XL MM Section 5-10-02)										
25-60-00-2202	P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 25 A/F	Copilot5-12-12				Mos	09-Oct-2023	60	-/+1m	(06-Nov-2028)	4 Years (+30 Days)
P01074-207					Hrs	3048:30				
15080810064					Ldg	2,362				
(ZONE: 251, 252, 261, 262) (Tol. Adjustment: -1060d) (SOURCE: 560 XL MM Section 5-10-02)										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Lavatory									
	Unknown										
	Unknown										
(ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)											
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.15-12-12									
	P01074-207										
	15080810055										
(ZONE: 251, 252, 261, 262) (Tol. Adjustment: -1060d) (SOURCE: 560 XL MM Section 5-10-02)											
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.25-12-12									
	P0074-207										
	15072300135										
(ZONE: 251, 252, 261, 262) (Tol. Adjustment: -1060d) (SOURCE: 560 XL MM Section 5-10-02)											
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.35-12-12									
	P01074-207										
	15072300107										
(ZONE: 251, 252, 261, 262) (Tol. Adjustment: -1060d) (SOURCE: 560 XL MM Section 5-10-02)											
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.4									
	Unknown										
	Unknown										
(ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)											
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	No.105-12-12									
	P01074-207										
	15072300023										
(ZONE: 251, 252, 261, 262) (Tol. Adjustment: -1060d) (SOURCE: 560 XL MM Section 5-10-02)											
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	No.115-12-12									
	P01074-207										
	15072300044										
(ZONE: 251, 252, 261, 262) (Tol. Adjustment: -1060d) (SOURCE: 560 XL MM Section 5-10-02)											
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	No.95-12-12									
	P01074-207										
	15080810080										
(ZONE: 251, 252, 261, 262) (Tol. Adjustment: -1060d) (SOURCE: 560 XL MM Section 5-10-02)											
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Pilot5-12-12									
	P01074-207										
	15080810020										
(ZONE: 251, 252, 261, 262) (Tol. Adjustment: -1060d) (SOURCE: 560 XL MM Section 5-10-02)											

Task No		Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Right No.15-12-12				Mos	09-Oct-2023	60	-/+1m	(06-Nov-2028)	4 Years (+30 Days)	
	P0074-207					Hrs	3048:30					
	15072300086					Ldg	2,362					
		(ZONE: 251, 252, 261, 262) (Tol. Adjustment: -1060d) (SOURCE: 560 XL MM Section 5-10-02)										
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Right No.25-12-12				Mos	09-Oct-2023	60	-/+1m	(06-Nov-2028)	4 Years (+30 Days)	
	P01074-207					Hrs	3048:30					
	15072300050					Ldg	2,362					
		(ZONE: 251, 252, 261, 262) (Tol. Adjustment: -1060d) (SOURCE: 560 XL MM Section 5-10-02)										
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Right No.35-12-12				Mos	09-Oct-2023	60	-/+1m	(06-Nov-2028)	4 Years (+30 Days)	
	P01074-207					Hrs	3048:30					
	15072300088					Ldg	2,362					
		(ZONE: 251, 252, 261, 262) (Tol. Adjustment: -1060d) (SOURCE: 560 XL MM Section 5-10-02)										
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Right No.4				Mos						
	Unknown					Hrs						
	Unknown					Ldg						
		(ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)										
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Copilot				1	Mos	29-Oct-2015	120	[11-Aug-2025]	9 Months	
	P01074-207						Hrs	0				
	15080810064						Ldg	0				
		Manufactured Date 11-Aug-2015 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Lavatory					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
		(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.1				1	Mos	29-Oct-2015	120	[11-Aug-2025]	9 Months	
	P01074-207						Hrs	0				
	15080810055						Ldg	0				
		Manufactured Date 11-Aug-2015 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.2					Mos	07-Nov-2018	120	[30-Jul-2025]	8.6 Months	
	P0074-207						Hrs	1230:36				
	15072300135						Ldg	1,009				
		Manufactured Date 30-Jul-2015 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										

Task No	Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Left No.3				Mos	05-Nov-2017	120		[30-Jul-2025]	8.6 Months
	P01074-207					Hrs	811				
	15072300107					Ldg	699				
	Manufactured Date 30-Jul-2015 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Left No.4				Mos					
	Unknown					Hrs					
	Unknown					Ldg					
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	No.10			2	Mos	29-Oct-2015	120		31-Aug-2025	9.7 Months
	P01074-207				0	Hrs	0				
	15072300023				0	Ldg	0				
	Manufactured Date 29-Oct-2015 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	No.11				Mos	05-Nov-2017	120		[01-Jul-2025]	7.6 Months
	P01074-207					Hrs	811				
	15072300044					Ldg	699				
	Manufactured Date 01-Jul-2015 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	No.9				Mos	05-Nov-2017	120		[01-Aug-2025]	8.7 Months
	P01074-207					Hrs	811				
	15080810080					Ldg	699				
	Manufactured Date 01-Aug-2015 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Pilot				Mos	05-Nov-2017	120		[11-Aug-2025]	9 Months
	P01074-207					Hrs	811				
	15080810020					Ldg	699				
	Manufactured Date 11-Aug-2015 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Right No.1				Mos	07-Nov-2018	120		[30-Jul-2025]	8.6 Months
	P0074-207					Hrs	1230:36				
	15072300086					Ldg	1,009				
	Manufactured Date 30-Jul-2015 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Right No.2				Mos	05-Nov-2017	120		[30-Jul-2025]	8.6 Months
	P01074-207					Hrs	811				
	15072300050					Ldg	699				
	Manufactured Date 30-Jul-2015 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										

Task No		Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Right No.3				Mos	05-Nov-2017	120		[30-Jul-2025]	8.6 Months	
	P01074-207					Hrs	811					
	15072300088					Ldg	699					
	Manufactured Date 30-Jul-2015											
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Right No.4				Mos						
	Unknown					Hrs						
	Unknown					Ldg						
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Copilot				Mos						
	P01074-207					Hrs						
	15080810064					Ldg						
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Lavatory				Mos						
	Unknown					Hrs						
	Unknown					Ldg						
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.1				Mos						
	P01074-207					Hrs						
	15080810055					Ldg						
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.2				Mos						
	P0074-207					Hrs						
	15072300135					Ldg						
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.3				Mos						
	P01074-207					Hrs						
	15072300107					Ldg						
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.4				Mos						
	Unknown					Hrs						
	Unknown					Ldg						
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	No.10				Mos						
	P01074-207					Hrs						
	15072300023					Ldg						
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	No.11									
	P01074-207										
	15072300044										
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	No.9									
	P01074-207										
	15080810080										
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Pilot									
	P01074-207										
	15080810020										
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Right No.1									
	P0074-207										
	15072300086										
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Right No.2									
	P01074-207										
	15072300050										
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Right No.3									
	P01074-207										
	15072300088										
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Right No.4									
	Unknown										
	Unknown										
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9602		Crew Flashlight D-Cell Battery Discard							RE	05-10-01, 05-10-02, Category 8	
	25 A/F	5-12-01									
	Unknown										
	Unknown										
	MRBR Task:33-50-00-901 (ZONE: 241, 242) (SOURCE: 560XL MM)										
25-60-10-7200		Artex 110-4 Emergency Locator Transmitter System Detailed Inspection and Functional Check (Airplanes -5001 thru -5500 Not Incorporating SB560XL-25-11)							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F										
	453-5060										
	16359										
	(SOURCE: 560 XL MM Section 5-10-02, 5-13-00)										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
25-60-10-7201		Artex 110-406 Emergency Locator Transmitter System Detailed Inspection and Functional Check (Airplanes -5501 thru -5564 and Airplanes -5002 thru -5372 Not Incorporating SB560XL-25-11)						RE (N/A)	05-10-01, 05-10-02, Category 8		
	25 A/F						Mos				
	453-5060						Hrs				
	16359						Ldg				
	MRBR Task:25-60-00-204, MRBR Task:25-60-00-205, MRBR Task:25-60-00-701, MRBR Task:25-60-00-703, MRBR Task:25-60-00-704 (SOURCE: 560XL MM)										
25-60-10-7202		Artex C406-2 Emergency Locator Transmitter System Detailed Inspection and Functional Test (Airplanes -5501 thru -5564 and Airplanes -5002 thru -5372 Incorporating SB560XL-25-11)						RE (N/A)	05-10-01, 05-10-02, Category 8		
	25 A/F						Mos				
	453-5060						Hrs				
	16359						Ldg				
	MRBR Task:25-60-00-204, MRBR Task:25-60-00-205, MRBR Task:25-60-00-206, MRBR Task:25-60-00-209, MRBR Task:25-60-00-701, MRBR Task:25-60-00-703, MRBR Task:25-60-00-704, MRBR Task:25-60-00-706 (SOURCE: 560XL MM)										
25-60-10-7203		Artex C406-N Emergency Locator Transmitter System Detailed Inspection and Functional Check (Airplanes -5565 and On)						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F						Mos	31-Oct-2024	12	31-Oct-2025	11.7 Months
	453-5060						Hrs	3308:54			
	16359						Ldg	2,570			
	(SOURCE: 560 XL MM Section 5-10-02, 5-13-00) Note: NOTE: National Requirements may exist with a different interval										
25-60-10-9600		Emergency Locator Transmitter Battery Discard						RE	05-10-01, 05-10-02, 05-12-00, Category 8		
	25 A/F				0	Mos	20-Sep-2020	60		31-Oct-2025	11.7 Months
	453-0133				0	Hrs	1997:10				
	385185-035				0	Ldg	1,542				
	Expiration Date 01-Oct-2025 MRBR Task:25-60-00-902 (Manual Adjustment: 11d) (SOURCE: 560XL MM) Note: NOTE: Typical battery life for Artex ELT 110-406, C406-2 and C406-N is 60 Months										
256061		Rosenview Monitor						RE (O/C)			
	25 A/F				0	Mos	09-Aug-2016				
	1043-005	New			0	Hrs	224:43				
	16030081					Ldg	223				
						Hrs (APU)	125				
						Start (APU)	148				
560XL-25-12		Glareshield Leather Strip Installation						RE (-)	Optional		
	25 A/F					Mos					
						Hrs					
						Ldg					
560XL-25-12 Rev 01		Glareshield Leather Strip Installation						T (A/R)	Optional		
	25 A/F					Mos					
	Eff: 24-Aug-2004					Hrs					
						Ldg					
560XL-25-18		Equipment/Furnishings - Passenger Seat Web Guide Improvement						RE (-)	Optional		
	25 A/F					Mos					
	Eff: 20-Aug-2015					Hrs					
						Ldg					
74-08-09 R2		Equipment/furnishings - Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles						RE (-)	Mandatory		
	25 A/F					Mos	27-Apr-2020				
	Eff: 06-Aug-1974 Superseded R3 is c/w (ISSUING AUTHORITY: FAA)					Hrs	1791:04				
						Ldg	1,398				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
74-08-09 R2 Paragraph (g)		Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - (1) Install a placard on each side of each lavatory door over the door knob, or on each side of each lavatory door, or adjacent to each side of each lavatory door. (2) Install a placard on or near each lavatory paper or linen waste disposal receptacle door, containing the legible words or symbology indicating "No Cigarette Disposal."						RE (-)		Mandatory	
	25 A/F					Mos	27-Apr-2020				
	Eff: 06-Aug-1974 Superseded R3 is c/w					Hrs	1791:04				
	(ISSUING AUTHORITY: FAA)					Ldg	1,398				
74-08-09 R2 Paragraph (h)		Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - establish a procedure that requires that, no later than a time immediately after the "No Smoking" sign is extinguished following takeoff, an announcement be made by a crewmember to inform all aircraft occupants that smoking is prohibited in the aircraft lavatories; except that, if the aircraft is not equipped with a "No Smoking" sign, the required procedure must provide that the announcement be made prior to each takeoff.						RE (-)		Mandatory	
	25 A/F					Mos	27-Apr-2020				
	Eff: 06-Aug-1974 Superseded R3 is c/w					Hrs	1791:04				
	(ISSUING AUTHORITY: FAA)					Ldg	1,398				
74-08-09 R2 Paragraph (i)		Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Install a self-contained, removable ashtray on or near the entry side of each lavatory door. One ashtray may serve more than one lavatory door if the ashtray can be seen readily from the cabin side of each lavatory door served.						RE (-)		Mandatory	
	25 A/F					Mos	27-Apr-2020				
	Eff: 06-Aug-1974 Superseded R3 is c/w					Hrs	1791:04				
	(ISSUING AUTHORITY: FAA)					Ldg	1,398				
74-08-09 R2 Paragraph (j)		Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - An airplane with multiple lavatory doors may be operated with up to 50 percent of the lavatory door ashtrays missing or inoperative, provided 50 percent of the missing or inoperative ashtrays are replaced within 3 days and all remaining missing or inoperative ashtrays are replaced within 10 days. An airplane with only 1 lavatory door may be operated for a period of 10 days with the lavatory door ashtray missing or inoperative						RE (-)		Mandatory	
	25 A/F					Mos	27-Apr-2020				
	Eff: 06-Aug-1974 Superseded R3 is c/w					Hrs	1791:04				
	(ISSUING AUTHORITY: FAA)					Ldg	1,398				
74-08-09 R2 Paragraph (k)		Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Inspect all lavatory paper and linen waste receptacle enclosure access doors and disposal doors for proper operation, fit, sealing, and latching for the containment of possible trash fires.						RE (-)		Mandatory	
	25 A/F					Mos	27-Apr-2020				
	Eff: 06-Aug-1974 Superseded R3 is c/w					Hrs	1791:04				
	(ISSUING AUTHORITY: FAA)					Ldg	1,398				
74-08-09 R3		Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles						RE (-)		Mandatory	
	25 A/F					Mos	31-Oct-2024				
	Eff: 28-Mar-2012 Complied With					Hrs	3308:54				
	(ISSUING AUTHORITY: FAA)					Ldg	2,570				
74-08-09 R3 Paragraph (g)		Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - (1) Install a placard on each side of each lavatory door over the door knob, or on each side of each lavatory door, or adjacent to each side of each lavatory door. (2) Install a placard on or near each lavatory paper or linen waste disposal receptacle door, containing the legible words or symbology indicating "No Cigarette Disposal."						RE (-)		Mandatory	
	25 A/F					Mos	31-Oct-2024				
	Eff: 06-Aug-1974 Complied With					Hrs	3308:54				
	(ISSUING AUTHORITY: FAA)					Ldg	2,570				
74-08-09 R3 Paragraph (h)		Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - establish a procedure that requires that, no later than a time immediately after the "No Smoking" sign is extinguished following takeoff, an announcement be made by a crewmember to inform all aircraft occupants that smoking is prohibited in the aircraft lavatories; except that, if the aircraft is not equipped with a "No Smoking" sign, the required procedure must provide that the announcement be made prior to each takeoff.						RE (-)		Mandatory	
	25 A/F					Mos	31-Oct-2024				
	Eff: 06-Aug-1974 Complied With					Hrs	3308:54				
	(ISSUING AUTHORITY: FAA)					Ldg	2,570				
74-08-09 R3 Paragraph (i)		Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Install a self-contained, removable ashtray on or near the entry side of each lavatory door. One ashtray may serve more than one lavatory door if the ashtray can be seen readily from the cabin side of each lavatory door served.						RE (-)		Mandatory	
	25 A/F					Mos	31-Oct-2024				
	Eff: 06-Aug-1974 Complied With					Hrs	3308:54				
	(ISSUING AUTHORITY: FAA)					Ldg	2,570				

OK-ECR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-ECR,SN 560-6198

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
74-08-09 R3 Paragraph (j)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - An airplane with multiple lavatory doors may be operated with up to 50 percent of the lavatory door ashtrays missing or inoperative, provided 50 percent of the missing or inoperative ashtrays are replaced within 3 days and all remaining missing or inoperative ashtrays are replaced within 10 days. An airplane with only 1 lavatory door may be operated for a period of 10 days with the lavatory door ashtray missing or inoperative						RE (-)		Mandatory	
 25 A/F					Mos	31-Oct-2024				
Eff: 28-Mar-2012 Complied With					Hrs	3308:54				
(ISSUING AUTHORITY: FAA)					Ldg	2,570				
Note: Note 1 to paragraph (j) of this AD: This AD permits a lavatory door ashtray to be missing, although the FAA-approved Master Minimum Equipment List (MMEL) may not allow such provision. In any case, the provisions of this AD prevail.										
74-08-09 R3 Paragraph (k)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Inspect all lavatory paper and linen waste receptacle enclosure access doors and disposal doors for proper operation, fit, sealing, and latching for the containment of possible trash fires.						RE		Mandatory	≈26-Mar-2026
 25 A/F					Mos	31-Oct-2024				
Eff: 06-Aug-1974 Complied With					Hrs	3308:54	1,000		4308:54	992:47 Hrs
(ISSUING AUTHORITY: FAA)					Ldg	2,570				
CIL-25-02	Equipment/Furnishings - Medaire Aircraft First Aid Kits with Medication Subject to Recall Notice						RE (-)		Informational, Service Bulletin	
 25 A/F					Mos					
Eff: 05-Nov-2019					Hrs					
					Ldg					
CIL-25-03	Equipment/Furnishings - Seat Pan Tilt Blocking Tab Installation						RE (-)		Informational, Service Letter	
 25 A/F					Mos					
Eff: 12-Aug-2020					Hrs					
(AVG MAN HRS: 0.25)					Ldg					
CIL-25-03 R1	Equipment/Furnishings - Seat Pan Tilt Blocking Tab Installation						RE (-)		Informational, Service Letter	
 25 A/F					Mos					
Eff: 08-Oct-2020					Hrs					
(AVG MAN HRS: 0.25)					Ldg					
PAD-PAK-04	PEDIATRIC PAD WITH BATTERY						RE (-)			
 25 A/F					Mos	25-Jan-2024			[31-Aug-2027]	2.8 Years
PAD-PAK-04	New				Hrs					
Unknown					Ldg					
Note: Expiration: 31.08.2027										
PAD-PAK-07	ADULT PAD-PAK WITH BATTERY						RE (-)			
 25 A/F					Mos	25-Jan-2024			[01-Nov-2027]	3 Years
PAD-PAK-07	New				Hrs					
Unknown					Ldg					
(UPDATE NOTE: Expiration: 01.11.2027)										
Note: Expiration: 01.11.2027										
PADSAM350P	DEFIBRILATOR HEARTSINE SAMARITAN						RE (NONE)			
 25 A/F					Mos					
PADSAM350P	New				Hrs					
22D91177276I22					Ldg					
SB560XL-25-19	Equipment/Furnishings - Replacement of the 4569508-1 Water Barrier Assembly						RE (-)		Recommended	
 25 A/F					Mos					
Eff: 15-Jul-2024					Hrs					
(AVG MAN HRS: 0.5)					Ldg					
SL560XL-25-13	Transmittal of Rockwell Collins Aishow 4000 Service Bulletin 30, Correction of Hard Drive Mounting Screws - Mod U						RE (-)		Recommended	
 25 A/F					Mos	13-Sep-2021				
Eff: 22-Mar-2010 Not Applicable	Different SN of Aircraft				Hrs					
					Ldg					

OK-ECR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-ECR,SN 560-6198

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-25-15	Transmittal of Aircraft Belts Inc. SB-BUC062-A001 Inspection of Buckles for Proper Operation						RE (-)		Optional	
 25 A/F					Mos	09-Sep-2021				
Not Applicable	as per S/N				Hrs	2218:31				
					Ldg	1,685				
SL560XL-25-15 Rev 01	Transmittal of Aircraft Belts Inc. SB-BUC062-A001 Inspection of Buckles for Proper Operation						RE (-)		Mandatory	
 25 A/F					Mos	09-Sep-2021				
Eff: 16-Aug-2010 Not Applicable	as per S/N				Hrs	2218:31				
					Ldg	1,685				
SL560XL-25-16	Transmittal of IPECO Service Bulletins 428-25-01, and 429-25-01, Addition of Cable Clip						RE (-)		Recommended	
 25 A/F					Mos	13-Sep-2021				
Eff: 13-Dec-2010 Not Applicable	Different SN of Aircraft				Hrs					
					Ldg					
SL560XL-25-17	Transmittal of Goodrich Service Bulletin 1423-25-003 Revision C Lumbar Assembly Cable Wear						RE (-)		Recommended	
 25 A/F					Mos	13-Sep-2021				
Eff: 03-Aug-2012 Not Applicable	Different SN of Aircraft				Hrs					
					Ldg					
SL560XL-25-18	Equipment/Furnishings - Replacement of the Cabinet Spring Assembly Pins						RE (-)		Recommended	
 25 A/F					Mos	13-Sep-2021				
Eff: 18-Jul-2019 Not Applicable	Different SN of Aircraft				Hrs					
(AVG MAN HRS: 3)					Ldg					
SL560XL-25-19	Equipment/Furnishings - Inspection of the Millennium Crew Seat Assemblies for Incorrectly Installed Seat Pan Tilt Mechanism Snap Rings (Millennium Service Bulletin SB2050-25-20-02)						RE (-)		Recommended, Service Letter	
 25 A/F					Mos	13-Sep-2021				
Eff: 11-Sep-2019 Not Applicable	Different SN of Aircraft				Hrs					
(AVG MAN HRS: 1.8)					Ldg					
SL560XL-25-19 R1	Equipment/Furnishings - Replacement of the Seat Pan Tilt Snap Rings (Millennium Service Bulletin SB2050-25-20-02B)						RE (-)		Recommended, Service Letter	
 25 A/F					Mos	13-Sep-2021				
Eff: 21-Nov-2019 Not Applicable	Different SN of Aircraft				Hrs					
(AVG MAN HRS: 1.5)					Ldg					
SL560XL-25-21	Equipment/Furnishings - Transmittal of Millennium Service Bulletin SB2050-25-20-09 Model 2050 Seating System Cross Tube Cover Installation						RE (-)		Optional	
 25 A/F					Mos	02-Jan-2023				
Eff: 19-Dec-2022 Not Applicable	per aircraft S/N				Hrs	2864:17				
(AVG MAN HRS: 0.25)					Ldg	2,197				
SL560XL-25-22	Equipment/Furnishings - Inspection of the SWI610-31 Entry Door Switch Indicator Light Emitting Diode (Led) Lights for Proper Indication						RE (-)		Recommended	
 25 A/F					Mos	12-Jan-2023				
Eff: 09-Jan-2023 Not Applicable	as per aircraft s/n				Hrs	2879:14				
(AVG MAN HRS: 3)					Ldg	2,210				
SL560XL-25-23	Equipment/Furnishings - Passenger Seat Swivel Plate Swing Arm Assembly Fastener Inspection for Proper Adhesive Application						RE (-)		Recommended	
 25 A/F					Mos					
Eff: 05-Apr-2023					Hrs					
(AVG MAN HRS: 8)					Ldg					

OK-ECR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-ECR,SN 560-6198

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
▼ 26 - FIRE PROTECTION											
		Aft Vanity Fire Extinguisher						RE (O/C)			
	26 A/F	Unknown Unknown					Mos	29-Oct-2015			
							Hrs	0			
							Ldg	0			
		APU Fire Bottle Cartridge						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	26 A/F	13083-5 LOTESD20A755-001 Manufactured Date 01-Jan-2020 Task:26-21-01-9601, Task:26-21-01-9603 (ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00) Note: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual.					Mos	19-Jul-2020	108	31-Jan-2029	4.2 Years
							Hrs	1887:21			
							Ldg	1,465			
		Engine Fire Bottle						RE (O/C)			
	26 A/F	Aft 30400037-1 40026B1					Mos	27-Apr-2020			
							Hrs	1791:04			
							Ldg	1,398			
		Engine Fire Bottle						RE (O/C)			
	26 A/F	Fwd 30400037-1 43849B1					Mos	27-Apr-2020			
							Hrs	1791:04			
							Ldg	1,398			
		Engine Fire Bottle Cartridge						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	26 A/F	Aft - No.1	0				Mos	27-Apr-2020	108	31-Jan-2029	4.2 Years
		New					Hrs	1791:04			
							Ldg				
		Manufactured Date 01-Jan-2020 Task:26-21-01-9600, Task:26-21-01-9602 (ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00) Note: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual.									
		Engine Fire Bottle Cartridge						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	26 A/F	Aft - No.2	0				Mos	27-Apr-2020	108	31-Jan-2029	4.2 Years
		New					Hrs	1791:04			
							Ldg				
		Manufactured Date 01-Jan-2020 Task:26-21-01-9600, Task:26-21-01-9602 (ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00) Note: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual.									
		Engine Fire Bottle Cartridge						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	26 A/F	Fwd - No.1	0				Mos	27-Apr-2020	108	31-Jan-2029	4.2 Years
		New					Hrs	1791:04			
							Ldg	1,398			
		Manufactured Date 01-Jan-2020 Task:26-21-01-9600, Task:26-21-01-9602 (ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00) Note: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual.									

Task No	Description					Categories		Time			
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
Engine Fire Bottle Cartridge									RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	26 A/F	Fwd - No.2	0			Mos	27-Apr-2020	108		31-Jan-2029	4.2 Years
	13083-5	New				Hrs	1791:04				
	LOT:ESD20A785-001					Ldg	1,398				
	Manufactured Date 01-Jan-2020										
Task:26-21-01-9600, Task:26-21-01-9602 (ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00)											
Note: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual.											
Engine Fire Detect (UE001) Cable									RE (O/C)		
	26 A/F	Left				Mos	29-Oct-2015				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
Engine Fire Detect (UE001) Cable									RE (O/C)		
	26 A/F	Right				Mos	29-Oct-2015				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
Engine Fire Detect (UT020) Control Unit									RE (O/C)		
	26 A/F	New	0			Mos	29-Oct-2015				
	377-02838		0			Hrs	0				
	1525-485		0			Ldg	0				
Engine Fire Detect (UT021) Control Unit									RE (O/C)		
	26 A/F	New	0			Mos	29-Oct-2015				
	377-02838		0			Hrs	0				
	1515-477		0			Ldg	0				
Fire Bottle APU									RE (O/C)		
	26 A/F	Overhauled		0		Mos	19-Jul-2020				
	30100033-7					Hrs	1887:21				
	55509A1					Ldg	1,465				
Portable Fire Extinguisher									RE (O/C)		
	26 A/F	Cabin				Mos	17-Dec-2021				
	C352TS	New	0	0		Hrs	2295:34				
	G-40531541		0	0		Ldg	1,748				
Portable Fire Extinguisher									RE (O/C)		
	26 A/F	Cockpit				Mos	17-Dec-2021				
	C352CS	New	0			Hrs	2295:34				
	F-95368046		0			Ldg	1,748				
2006-04-10	This AD Requires Installing Identification Sleeves On The Wires For The Positive And Negative Studs Of The Engine And/ Or (APU) Fire Extinguishing Bottles, As Applicable, And Reconnecting The Wires To The Correct Terminal Studs. (Superseded by AD 2007-11-17							RE (-)	Mandatory		
	26 A/F						Mos	28-Oct-2015			
	Eff: 24-Mar-2006 Superseded						Hrs	5			
	(ISSUING AUTHORITY: FAA)						Ldg	3			
2007-11-17	Wires for the positive and negative terminal studs of the engine and/or auxiliary power unit (APU) fire extinguishing bottles.							RE (-)	Mandatory		
	26 A/F						Mos	28-Oct-2015			
	Eff: 06-Jul-2007 Complied	AD2007-11-17: SUPERCEDES AD2006-04-10. THE EQUIVALENT OF SB560XL-26-02, REV1 HAS BEEN						Hrs	5		
	With	COMPLIED WITH BY INCORPORATION OF EC055284 AND FOUND TO BE A SATISFACTORY MEANS OF COMPLIANCE.						Ldg	3		
(AVG MAN HRS: 4) (ISSUING AUTHORITY: FAA)											

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2016-0024	Fire Protection - Optical and Ambient Smoke Detectors - Identification / Replacement						RE (-)		Mandatory (Appliance AD)	
26 A/F						Mos	03-Mar-2016			
Eff: 01-Feb-2016 Not Applicable	BY EQUIPMENT FITTED					Hrs				
(ISSUING AUTHORITY: EASA)						Ldg				
2016-0044	Fire Protection - Engine and Auxiliary Power Unit Automatic Fire Extinguishers - Inspection/Overhaul						RE (-)		Mandatory (Appliance AD)	
26 A/F						Mos	05-Apr-2016			
Eff: 22-Mar-2016 Not Applicable	BY P/N FITTED					Hrs				
(ISSUING AUTHORITY: EASA)						Ldg				
2020-21-02	Fire protection - Kidde Aerospace & Defense - Cargo Fire Extinguisher Halon Bottles						RE (-)		Mandatory (Appliance AD)	
26 A/F						Mos	22-Oct-2020			
Eff: 19-Nov-2020 Not Applicable	BY EQUIPMENT TYPE NOT INSTALLED					Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				
2020-21-02 PARA (H) & (I)	Do an Inspection to Determine the Part Number and Serial Number of the Cargo Fire Extinguisher Halon Bottles Installed in the Cargo Compartment and Replace With a Serviceable Part as Required						RE (-)		Mandatory	
26 A/F						Mos	22-Oct-2020			
Not Applicable	BY EQUIPMENT TYPE NOT INSTALLED					Hrs				
						Ldg				
2020-21-02 PARA (J)	No Person May Install on Any Airplane an Affected Part as Identified in Paragraph (G)(3) of this AD Unless that Part has a Circled Letter "G" Stamped at a Distance 8 of Approximately One Inch From the Left Edge of the Placard, Indicating that the Cargo Fire Extinguisher Halon Bottle Has Been Tested and Refilled						RE (-)		Mandatory	
26 A/F						Mos	22-Oct-2020			
Not Applicable	BY EQUIPMENT TYPE NOT INSTALLED					Hrs				
						Ldg				
2021-0185R2	Fire Protection - Hand-operated Fire Extinguishers - Inspection/Replacement						RE (-)		Mandatory (Appliance AD)	
26 A/F						Days	27-Jul-2022			
Eff: 14-Sep-2022 Not Applicable	affected P/N not installed					Hrs	2706:14			
(ISSUING AUTHORITY: EASA)						Ldg	2,068			
2021-22-07	Fire Protection - Impaired Fire Extinguisher						RE (-)		Mandatory (Appliance AD)	
26 A/F						Days	10-Nov-2021			
Eff: 17-Nov-2021 Not Applicable	different extinguisher PN installed					Hrs	2295:34			
(ISSUING AUTHORITY: FAA)						Ldg	1,748			
2022-01-03	Fire Bottle, Portable - HAFEX (Halon-free) Hand-Held P3HAFEX Fire Extinguisher						RE (-)		Mandatory (Appliance AD)	
26 A/F						Mos	02-Feb-2022			
Eff: 07-Mar-2022 Not Applicable	mentioned P/N not installed					Hrs	2372:06			
(ISSUING AUTHORITY: FAA)						Ldg	1,802			
Note: Required Actions: (1) Within 12 months after the effective date of this AD, remove each fire extinguisher identified in the introductory text of paragraph (c) from service.										
26-11-00-7200	Optional Baggage Compartment and Lavatory Smoke Detection System Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
26 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)
(ZONE: 235, 311) (SOURCE: 560 XL MM Section 5-10-02)						Hrs	3048:30			
						Ldg	2,362			
26-20-00-2200	Left Engine Fire Deployment Check Tee Special Detailed Inspection						RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
26 A/F						Mos				
(ZONE: 321) (SOURCE: 560 XL MM Section 5-10-02)						Hrs				
Note: NOTE: Anytime bottle 1 or 2 of the associated Engine Fire Extinguishing System is fired						Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
26-20-00-2200	Right Engine Fire Deployment Check Tee Special Detailed Inspection						RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 26 A/F										
	(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02)									
	Note: NOTE: Anytime bottle 1 or 2 of the associated Engine Fire Extinguishing System is fired									
26-21-00-2200	Engine Fire Extinguisher Wiring Detailed Inspection						RE		04-10-01	
 26 A/F	4-12-MV						24	(03-Jul-2026)		1.6 Years
	(ZONE: 311, 312) (SOURCE: 560 XL MM)									
26-21-00-7100	Left Engine Fire Extinguishing System Functional Check						RE	05-10-01, 05-10-02, Category 8, Category 9		
 26 A/F	5-12-06						48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
	MRBR Task:26-20-00-701, MRBR Task:26-20-00-702, MRBR Task:26-20-00-703, MRBR Task:26-20-00-704, MRBR Task:26-20-00-706, MRBR Task:26-20-00-709 (ZONE: 313, 235, 321) (SOURCE: 560XL MM)						3048:30			
							2,362			
26-21-00-7100	Right Engine Fire Extinguishing System Functional Check						RE	05-10-01, 05-10-02, Category 8, Category 9		
 26 A/F	5-12-06						48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
	MRBR Task:26-20-00-701, MRBR Task:26-20-00-702, MRBR Task:26-20-00-703, MRBR Task:26-20-00-704, MRBR Task:26-20-00-706, MRBR Task:26-20-00-709 (ZONE: 314, 235, 322) (SOURCE: 560XL MM)						3048:30			
							2,362			
26-21-01-7100	Engine Fire Extinguisher Aft Bottle Low Pressure Switch Operational Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 26 A/F							60		19-Feb-2025	3.2 Months
	Hydrostatic Tested Date 19-Feb-2020									
	MRBR Task:26-20-00-711 (ZONE: 312) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00)									
	Note: NOTE: This task is accomplished during the Hydrostatic check. Per Supplier Recommendation. Reference Pacific Scientific 26-20-202 Component Maintenance Manual.									
 ECR-WP-010 / OKECR/013 START 24-JUN-2024										
26-21-01-7100	Engine Fire Extinguisher Fwd Bottle Low Pressure Switch Operational Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 26 A/F							60		13-Feb-2025	3 Months
	Hydrostatic Tested Date 13-Feb-2020									
	MRBR Task:26-20-00-711 (ZONE: 235) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00)									
	Note: NOTE: This task is accomplished during the Hydrostatic check. Per Supplier Recommendation. Reference Pacific Scientific 26-20-202 Component Maintenance Manual.									
 ECR-WP-010 / OKECR/013 START 24-JUN-2024										
26-21-01-7200	Optional Aft Vanity Fire Extinguisher Bottle (Weight Check) Functional Check (Airplanes - 6224 and On)						RE (N/A)	Regulatory Inspections/Time Limits		
 26 A/F										
	Unknown									
	Unknown									
	(SOURCE: 560 XL MM Section 5-13-00, 5-18-00)									
26-21-01-7800	Engine Fire Extinguisher Bottle (Hydrostatic Test) Restoration						RE	Regulatory Inspections/Time Limits		
 26 A/F	Aft						60		28-Feb-2025	3.5 Months
	30400037-1									
	40026B1									
	Hydrostatic Tested Date 19-Feb-2020									
	(SOURCE: 560 XL MM Section 5-13-00)									
	Note: Regulation : US DOT CFR 49 Part 180.209 Requirements for Re-qualification of Specification Cylinders. NOTE: The fire extinguisher bottle is manufactured under U.S. DOT-SP-7945									
 ECR-WP-010 / OKECR/013 START 24-JUN-2024										

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
26-21-01-7800		Engine Fire Extinguisher Bottle (Hydrostatic Test) Restoration							RE	Regulatory Inspections/Time Limits	
	26 A/F	Fwd					Mos	13-Feb-2020	60	28-Feb-2025	3.5 Months
	30400037-1						Hrs				
	43849B1						Ldg				
		Hydrostatic Tested Date 13-Feb-2020 (SOURCE: 560 XL MM Section 5-13-00) Note: Regulation : US DOT CFR 49 Part 180.209 Requirements for Re-qualification of Specification Cylinders. NOTE: The fire extinguisher bottle is manufactured under U.S. DOT-SP-7945									
		ECR-WP-010 / OKECR/013 START 24-JUN-2024									
26-21-01-9600		13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	26 A/F	Aft - No.1					Mos	27-Apr-2020	72	27-Apr-2026	1.4 Years
	13083-5						Hrs	1791:04			
	LOT:ESD20A785-001						Ldg				
		(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) Note: NOTE: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months Tracked by Component Installation Date. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual									
26-21-01-9600		13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	26 A/F	Aft - No.2					Mos	27-Apr-2020	72	27-Apr-2026	1.4 Years
	13083-5						Hrs	1791:04			
	LOT:ESD20A785-001						Ldg				
		(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) Note: NOTE: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months Tracked by Component Installation Date. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual									
26-21-01-9600		13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	26 A/F	Fwd - No.1					Mos	27-Apr-2020	72	27-Apr-2026	1.4 Years
	13083-5						Hrs	1791:04			
	LOT:ESD20A785-001						Ldg	1,398			
		(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) Note: NOTE: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months Tracked by Component Installation Date. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual									
26-21-01-9600		13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	26 A/F	Fwd - No.2					Mos	27-Apr-2020	72	27-Apr-2026	1.4 Years
	13083-5						Hrs	1791:04			
	LOT:ESD20A785-001						Ldg	1,398			
		(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) Note: NOTE: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months Tracked by Component Installation Date. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual									
26-21-01-9601		13083-5 Auxiliary Power Unit Fire Extinguisher Cartridge Squib Discard (In Service Limitation)							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	26 A/F						Mos	18-Jun-2020	72	18-Jun-2026	1.6 Years
	13083-5						Hrs				
	LOTESD20A755-001						Ldg				
		(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) Note: NOTE: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months Tracked by Component Installation Date. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual									

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
26-21-01-9602	AE 13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)						RE (N/A)	05-10-01, 05-10-02, Category 8		
	26 A/F	Aft - No.1				Mos				
	13083-5					Hrs				
	LOT:ESD20A785-001					Ldg				
	MRBR Task:25-20-00-903 (ZONE: 322) (SOURCE: 560XL MM)									
26-21-01-9602	AE 13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)						RE (N/A)	05-10-01, 05-10-02, Category 8		
	26 A/F	Aft - No.2				Mos				
	13083-5					Hrs				
	LOT:ESD20A785-001					Ldg				
	MRBR Task:25-20-00-903 (ZONE: 322) (SOURCE: 560XL MM)									
26-21-01-9602	AE 13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)						RE (N/A)	05-10-01, 05-10-02, Category 8		
	26 A/F	Fwd - No.1				Mos				
	13083-5					Hrs				
	LOT:ESD20A785-001					Ldg				
	MRBR Task:25-20-00-903 (ZONE: 322) (SOURCE: 560XL MM)									
26-21-01-9602	AE 13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)						RE (N/A)	05-10-01, 05-10-02, Category 8		
	26 A/F	Fwd - No.2				Mos				
	13083-5					Hrs				
	LOT:ESD20A785-001					Ldg				
	MRBR Task:25-20-00-903 (ZONE: 322) (SOURCE: 560XL MM)									
26-21-01-9603	AE 13083-5 Auxiliary Power Unit Fire Extinguisher Cartridge Squib Discard (In Service Limitation)						RE (N/A)	05-10-01, 05-10-02, Category 8		
	26 A/F					Mos				
	13083-5					Hrs				
	LOTESD20A755-001					Ldg				
	MRBR Task:25-20-00-904 (ZONE: 322) (SOURCE: 560XL MM)									
26-22-00-2200	Portable Fire Extinguisher Detailed and (Weight) Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	26 A/F	Cabin5-12-01				Mos	31-Oct-2024	12	(31-Oct-2025)	11.7 Months (+30 Days)
	C352TS					Hrs	3308:54			
	G-40531541					Ldg	2,570			
	(ZONE: 242) (Tol. Adjustment: -50d) (SOURCE: 560 XL MM Section 5-10-02, 5-13-00)									
	Note: NOTE: Per Supplier Recommendation and/or Local Regulatory Requirement. Reference NFPA 10									
26-22-00-2200	Portable Fire Extinguisher Detailed and (Weight) Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	26 A/F	Cockpit5-12-01				Mos	31-Oct-2024	12	(31-Oct-2025)	11.7 Months (+30 Days)
	C352CS					Hrs	3308:54			
	F-95368046					Ldg	2,570			
	(ZONE: 262) (Tol. Adjustment: -50d) (SOURCE: 560 XL MM Section 5-10-02, 5-13-00)									
	Note: NOTE: Per Supplier Recommendation and/or Local Regulatory Requirement. Reference NFPA 10									
26-22-00-2201	Portable Fire Extinguisher Restoration (Internal Inspection)						RE	Regulatory Inspections/Time Limits		
	26 A/F	Cabin				Mos	17-Dec-2021	72	31-Dec-2027	3.1 Years
	C352TS					Hrs	2295:34			
	G-40531541					Ldg	1,748			
	(UPDATE NOTE: PERFORMED TASK 26-22-00-2201 PORTABLE FIRE EXTINGUISHER RESTORATION (INTERNAL INSPECTION) COCKPIT IAW AMM 560XL (REV 46); REMOVED COCKPIT FIRE EXT. AND SENT TO OUTSIDE VENDOR FOR RESTORATION; INSTALLED EXCHANGE FIRE EXT. IN NEW CONDITION.P/N ON: C352S/N ON: F-95368046WEIGHT: 2,148 KGEXP: 2032NEXT CHECK: 09.11.2022PERFORMED TASK 26-22-00-2201 PORTABLE FIRE EXTINGUISHER RESTORATION (INTERNAL INSPECTION) CABIN IAW AMM 560XL (REV 46); REMOVEDCABIN FIRE EXT. AND SENT TO OUTSIDE VENDOR FOR RESTORATION; INSTALLED EXCHANGE FIRE EXT. IN NEW CONDITION.P/N ON: C352S/N ON: G-40531541WEIGHT: 2,16 KGEXP: 2033NEXT CHECK: 09.11.2022) (SOURCE: 560 XL MM Section 5-13-00)									
	Note: National Fire Protection Agency									
	NFPA 10: Standard for Portable									
	Fire Extinguishers									

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
26-22-00-2201		Portable Fire Extinguisher Restoration (Internal Inspection)							RE	Regulatory Inspections/Time Limits		
	26 A/F	Cockpit					Mos	17-Dec-2021	72	31-Dec-2027	3.1 Years	
	C352CS						Hrs	2295:34				
	F-95368046						Ldg	1,748				
	(UPDATE NOTE: PERFORMED TASK 26-22-00-2201 PORTABLE FIRE EXTINGUISHER RESTORATION (INTERNAL INSPECTION) COCKPIT IAW AMM 560XL (REV 46); REMOVED COCKPIT FIRE EXT. AND SENT TO OUTSIDE VENDOR FOR RESTORATION; INSTALLED EXCHANGE FIRE EXT. IN NEW CONDITION.P/N ON: C352S/N ON: F-95368046WEIGHT: 2,148 KGEXP: 2032NEXT CHECK: 09.11.2022PERFORMED TASK 26-22-00-2201 PORTABLE FIRE EXTINGUISHER RESTORATION (INTERNAL INSPECTION) CABIN IAW AMM 560XL (REV 46); REMOVEDCABIN FIRE EXT. AND SENT TO OUTSIDE VENDOR FOR RESTORATION; INSTALLED EXCHANGE FIRE EXT. IN NEW CONDITION.P/N ON: C352S/N ON: G-40531541WEIGHT: 2,16 KGEXP: 2033NEXT CHECK: 09.11.2022) (SOURCE: 560 XL MM Section 5-13-00) Note: National Fire Protection Agency NFPA 10: Standard for Portable Fire Extinguishers											
26-22-00-7800		Portable Fire Extinguisher (Hydrostatic Test) Functional Check							RE	Regulatory Inspections/Time Limits		
	26 A/F	Cabin					Mos	17-Dec-2021	144	31-Dec-2033	9.1 Years	
	C352TS						Hrs	2295:34				
	G-40531541						Ldg	1,748				
	Hydrostatic Tested Date 17-Dec-2021 (SOURCE: 560 XL MM Section 5-13-00) Note: Regulation: National Fire Protection Agency NFPA 10: Standard for Portable Fire Extinguishers											
26-22-00-7800		Portable Fire Extinguisher (Hydrostatic Test) Functional Check							RE	Regulatory Inspections/Time Limits		
	26 A/F	Cockpit					Mos	17-Dec-2021	144	31-Dec-2033	9.1 Years	
	C352CS						Hrs	2295:34				
	F-95368046						Ldg	1,748				
	Hydrostatic Tested Date 17-Dec-2021 (SOURCE: 560 XL MM Section 5-13-00) Note: Regulation: National Fire Protection Agency NFPA 10: Standard for Portable Fire Extinguishers											
26-23-00-2200		Auxiliary Power Unit Fire Extinguisher Wiring Detailed Inspection (If APU installed)							RE	04-10-01		
	26 A/F	4-12-MV					Mos		24	(03-Jul-2026)	1.6 Years	
							Hrs					
	(ZONE: 312) (SOURCE: 560 XL MM)						Ldg					
26-23-00-7100		Auxiliary Power Unit Fire Extinguishing System Operational and Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	26 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)	
							Hrs	3048:30				
	(ZONE: 235, 313) (SOURCE: 560 XL MM Section 5-10-02)						Ldg	2,362				
26-23-00-7101		Auxiliary Power Unit Fire Extinguisher Bottle Low Pressure Switch Operational Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	26 A/F						Mos	10-Feb-2020	60	10-Feb-2025	88 Days	
	Hydrostatic Tested Date 10-Feb-2020						Hrs					
	(ZONE: 312) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)						Ldg					
Note: NOTE: This task is accomplished during the Hydrostatic check. Per Supplier Recommendation. Reference Pacific Scientific 26-22-202 Component Maintenance Manual.												
	ECR-WP-010 / OKECR/013 START 24-JUN-2024											

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
26-23-00-7800	APU Fire Extinguisher Bottle (Hydrostatic Test) Restoration						RE		Regulatory Inspections/Time Limits	
 26 A/F 30100033-7 55509A1 Hydrostatic Tested Date 10-Feb-2020 (SOURCE: 560 XL MM Section 5-13-00) Note: Regulation : US DOT CFR 49 Part 180.209 Requirements for Re-qualification of Specification Cylinders. NOTE: The fire extinguisher bottle is manufactured under U.S. DOT-SP-7945  ECR-WP-010 / OKECR/013 START 24-JUN-2024						Mos Hrs Ldg	10-Feb-2020 60		28-Feb-2025	3.5 Months
560XL-26-03	Engine Fire Bottle Arm Annunciation Modification						RE (-)		Mandatory	
 26 A/F Eff: 28-May-2009 Not Applicable	560XL-26-03					Mos Hrs Ldg	09-Sep-2021 2218:31 1,685			
CIL-26-01	Fire Protection - Fire Extinguisher Bottle Cartridge Ground Stud Torquing						RE (-)		Mandatory	
 26 A/F Eff: 10-May-2016 Not Applicable (AVG MAN HRS: 0.5)	R1 is c/w					Mos Hrs Ldg	09-Sep-2021 2218:31 1,685			
CIL-26-01 R1	Fire Protection - Fire Extinguisher Bottle Cartridge Ground Stud Torquing						RE (-)		Mandatory	
 26 A/F Eff: 10-May-2016 Complied With (AVG MAN HRS: 0.5)						Mos Hrs Ldg	07-Nov-2018 1230:36 1,009			
SB560XL-26-04	Fire Protection - Replacement of the Halon Type 1211 Portable Fire Extinguishers						T (A/R)		Optional	
 26 A/F Eff: 26-May-2022						Mos Hrs Ldg				
SL560XL-26-02	Fire Protection - Fire Bottle Wire Verification and Test						RE (-)		Mandatory	
 26 A/F Eff: 08-Jul-2021 Complied With (AVG MAN HRS: 3) Note: COMPLIANCE: MANDATORY. This service document must be accomplished within 100 flight hours or 60 days from the date of receipt, whichever occurs first.						Mos Hrs Ldg	13-Aug-2021 2173:12 1,656			
SL560XL-26-02 R1	Fire Protection - Fire Bottle Wire Verification and Test						RE (-)		Mandatory	
 26 A/F Eff: 31-Jul-2024 Complied With (AVG MAN HRS: 3) Note: EFFECTIVITY: Airplanes that have previously complied with this document must inspect the fire bottle wiring per Step 6. COMPLIANCE: MANDATORY. This service document must be accomplished within 100 flight hours or 60 days from the date of receipt, whichever occurs first.						Days Hrs Ldg	31-Oct-2024 3308:54 2,570			
UK G-2015-0001 R01	Fire Protection - Engine And Apu Automatic Fire Extinguishers - Inspection / Overhaul						RE (-)			
 26 A/F Not Applicable	BY P/N FITTED					Mos Hrs Ldg	06-Jun-2016			
▼ 27 - FLIGHT CONTROLS										
	Actuator Aileron Trim Tab						RE (O/C)			
 27 A/F Unknown Unknown						Mos Hrs Ldg	29-Oct-2015 0 0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	27 A/F 6660003-1 NSN	Aft Elevator Trim Cable Assembly New						RE (O/C)			
			0				Mos	29-Oct-2015			
			0				Hrs	0			
			0				Ldg	0			
	27 A/F Unknown Unknown	Aileron Assembly Left						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
							Ldg	0			
	27 A/F Unknown Unknown (ZONE: r)	Aileron Assembly Right						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
							Ldg	0			
	27 A/F Unknown Unknown	Airspeed Switch						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
							Ldg	0			
	27 A/F Unknown Unknown	Elev Trim Switch						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
							Ldg	0			
	27 A/F Unknown Unknown	Elevator Assembly Left						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
							Ldg	0			
	27 A/F Unknown Unknown	Elevator Assembly Right						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
							Ldg	0			
	27 A/F Unknown Unknown	Elevator Electric Trim Actuator						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
							Ldg	0			
	27 A/F Unknown Unknown	Elevator Trim Actuator Left						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
							Ldg	0			
	27 A/F Unknown Unknown	Elevator Trim Actuator Right						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
							Ldg	0			
	27 A/F 1535000-3 3586	Flap Actuator Left New						RE (O/C)			
			0				Mos	29-Oct-2015			
			0				Hrs	0			
			0				Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	27 A/F 1535000-3 3588	Flap Actuator						RE (O/C)			
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	27 A/F 4216-3 0549	Flap Control (Uy024) Valve						RE (O/C)			
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
	27 A/F 4218-1 0545	Horizontal Stab Valve Assy						RE (O/C)			
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
	27 A/F 41011680-108 1220	Horizontal Stabilizer Actuator						RE (O/C)			
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
	27 A/F 4220-1 0550	Horizontal Stabilizer Isolation (Uy015) Valve						RE (O/C)			
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
	27 A/F 8244-2 0536	Hydraulic Manifold Assembly						RE (O/C)			
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
	27 A/F 6633000-31 25208933	Rudder Assembly						RE (O/C)			
						Mos	29-Jul-2021				
						Hrs	2169:34				
						Ldg	1,654				
	27 A/F 6660613-12 5977	Rudder Bias Actuator						RE (O/C)			
				6		Mos	03-Jun-2016				
						Hrs	149:20				
						Ldg	153				
	27 A/F 5307-1 1905C	Rudder Bias Shutoff Valve						RE (O/C)			
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
	27 A/F Unknown Unknown	Rudder Trim Tab Actuator						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	27 A/F Unknown Unknown	Servo Actuator						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
Speed Brake Actuator										
27 A/F	Left						RE (O/C)			
1535500-1	New	0			Mos	29-Oct-2015				
4015		0			Hrs	0				
		0			Ldg	0				
Speed Brake Actuator										
27 A/F	Right						RE (O/C)			
1535500-1	New	0			Mos	29-Oct-2015				
4017		0			Hrs	0				
		0			Ldg	0				
Speed Brake Control Valve										
27 A/F							RE (O/C)			
4216-2	New	0			Mos	29-Oct-2015				
0551		0			Hrs	0				
		0			Ldg	0				
Speed Brake Safety Valve										
27 A/F							RE (O/C)			
4217-1	New	0			Mos	29-Oct-2015				
0557		0			Hrs	0				
		0			Ldg	0				
Stick Shaker (MC001) Unit										
27 A/F							RE (O/C)			
201	New	0			Mos	29-Oct-2015				
159536-10		0			Hrs	0				
		0			Ldg	0				
Stick Shaker (MF004) Unit										
27 A/F							RE (O/C)			
201	New	0			Mos	29-Oct-2015				
159915A-05		0			Hrs	0				
		0			Ldg	0				
Throttle Quadrant Assembly										
27 A/F							RE (O/C)			
6665260-4				11	Mos	12-Dec-2017				
HAC-0110-4					Hrs	835:36				
					Ldg	718				
Trim Actuators Lubrication										
12-20-27-6401	5-12-01						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
27 A/F					Mos	31-Oct-2024	12	-/+1m (31-Oct-2025)	11.7 Months (+30 Days)	
	(ZONE: 340, 351, 352, 532) (SOURCE: 560 XL MM Section 5-10-02)				Hrs	3308:54				
	Note: NOTE: It is recommended to do this task at the same time as Tasks 27-10-00-2202 and 27-20-00-2201.				Ldg	2,570				
Horizontal Stabilizer Scissor Fitting Bolts and Aft Pivot Bolts Lubrication										
12-20-27-6403	5-12-03						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
27 A/F					Mos	09-Oct-2023	24	-/+1m (31-Oct-2025)	11.7 Months (+30 Days)	
	(ZONE: 340) (SOURCE: 560 XL MM Section 5-10-02)				Hrs	3048:30				
					Ldg	2,362				
Aileron Cable Fairlead Tube and Aileron Cable Sector										
2000-15-51							RE (-)		Mandatory	
27 A/F										
Eff: 14-Aug-2000 Complied With	AD2000-15-51: THE EQUIVALENT OF SB560XL-27-12 HAS BEEN INSTALLED WITH BY INCORPORATION OF EC46190 AND FOUND TO BE AN ALTERNATE MEANS OF COMPLIANCE (REFERENCE AMOC2000-15-51).				Mos	28-Oct-2015				
(ISSUING AUTHORITY: FAA)					Hrs	5				
					Ldg	3				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2000-15-51 Paragraph (a)	Aileron Cable Fairlead Tube - Pre-modification Inspection						RE (-)		Mandatory	
27 A/F						Mos	28-Oct-2015			
Eff: 14-Aug-2000 Complied With	AD2000-15-51: THE EQUIVALENT OF SB560XL-27-12 HAS BEEN INSTALLED WITH BY INCORPORATION OF EC46190 AND FOUND TO BE AN ALTERNATE MEANS OF COMPLIANCE (REFERENCE AMOC2000-15-51).					Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				
2000-15-51 Paragraph (b)	Aileron Cable Fairlead Tube - Modification						RE (-)		Mandatory	
27 A/F						Mos	28-Oct-2015			
Eff: 14-Aug-2000 Complied With	AD2000-15-51: THE EQUIVALENT OF SB560XL-27-12 HAS BEEN INSTALLED WITH BY INCORPORATION OF EC46190 AND FOUND TO BE AN ALTERNATE MEANS OF COMPLIANCE (REFERENCE AMOC2000-15-51).					Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				
2000-15-51 Paragraph (c)	Aileron Cable Fairlead Tube - Post-modification Inspection						RE (-)		Mandatory	
27 A/F						Mos	28-Oct-2015			
Eff: 14-Aug-2000 Complied With	AD2000-15-51: THE EQUIVALENT OF SB560XL-27-12 HAS BEEN INSTALLED WITH BY INCORPORATION OF EC46190 AND FOUND TO BE AN ALTERNATE MEANS OF COMPLIANCE (REFERENCE AMOC2000-15-51).					Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				
27-10-00-2201	Aileron Left Wing Cable Detailed Inspection (Airplanes -5556 and On, and Airplanes -5002 thru - 5555 Incorporating SB560XL-27-22)						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈09-Oct-2026	
27 A/F	5-12-08					Mos	17-Dec-2021			
						Hrs	2295:34	2,400	-/+25	(4695:34) 1379:27 Hrs (+25)
	(ZONE: 313, 314, 512, 522, 532) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 25-11-01 -2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES -5002 THRU -5555 INCORPORATINGSB560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560 XL MM Section 5-10-02) Note: NOTE: It is recommended you do this task at the same time as Task 27-10-00-2203				Ldg	1,748				
27-10-00-2201	Aileron Right Wing Cable Detailed Inspection (Airplanes -5556 and On, and Airplanes -5002 thru - 5555 Incorporating SB560XL-27-22)						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈09-Oct-2026	
27 A/F	5-12-08					Mos	17-Dec-2021			
						Hrs	2295:34	2,400	-/+25	(4695:34) 1379:27 Hrs (+25)
	(ZONE: 612, 622, 632) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 25-11-01-2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES -5002 THRU -5555 INCORPORATINGSB560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560 XL MM Section 5-10-02) Note: NOTE: It is recommended you do this task at the same time as Task 27-10-00-2203				Ldg	1,748				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
27-10-00-2202	Aileron Trim Actuator Detailed Inspection						RE	05-10-01, 05-10-02, Category 6		
 27 A/F	5-12-01					Mos	31-Oct-2024	12	-(+1m (31-Oct-2025)	11.7 Months (+30 Days)
Unknown						Hrs	3308:54			
Unknown						Ldg	2,570			
MRBR Task:27-10-00-208 (ZONE: 532) (SOURCE: 560XL MM) Note: NOTE: It is recommended to do this task at the same time as Tasks 12-20-27-6401 and 27-20-00-2201.										
27-10-00-2203	Aileron and Aileron Trim Detailed Inspection and Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈09-Oct-2026
 27 A/F	5-12-08					Mos	17-Dec-2021			
						Hrs	2295:34	2,400	-/+25 (4695:34)	1379:27 Hrs (+25)
						Ldg	1,748			
(ZONE: 141,153,163,165,236,241,242,313,512,522,532,534) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 25-11-01-2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES -5002 THRU -5555 INCORPORATINGSB560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019,CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560 XL MM Section 5-10-02) Note: NOTE: It is recommended you do this task at the same time as Task 27-10-00-2201										
27-10-00-7201	Aileron Trim Tab and Pushrod (Free Play) Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈26-Jan-2027
 27 A/F	5-12-07					Mos	31-Oct-2024			
						Hrs	3308:54	1,600	-/+25 (4908:54)	1592:47 Hrs (+25)
						Ldg	2,570			
(ZONE: 532) (Tol. Adjustment: -108.9 Hrs) (SOURCE: 560 XL MM Section 5-10-02)										
27-20-00-2200	Rudder Bias Cable Assembly Detailed Inspection (Airplanes - 5001, -5044, -5052, -5085, -5088 and On. And Airplanes -5002 thru -5043, -5045 thru -5051, -5053 thru -5084 and -5086 thru - 5087 Incorporating SB560XL-27-06)						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈09-Oct-2026
 27 A/F	5-12-08					Mos	17-Dec-2021			
						Hrs	2295:34	2,400	-/+25 (4695:34)	1379:27 Hrs (+25)
						Ldg	1,748			
(ZONE: 340) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 25-11-01-2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES -5002 THRU -5555 INCORPORATINGSB560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019,CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560 XL MM Section 5-10-02)										
27-20-00-2201	Rudder Trim Actuator Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 27 A/F	5-12-01					Mos	31-Oct-2024	12	-(+1m (31-Oct-2025)	11.7 Months (+30 Days)
Unknown						Hrs	3308:54			
Unknown						Ldg	2,570			
(ZONE: 340) (SOURCE: 560 XL MM Section 5-10-02) Note: NOTE: It is recommended to do this task at the same time as Tasks 12-20-27-6401 and 27-10-00-2202										

Task No		Description									Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining		
27-20-00-2202		Rudder and Rudder Trim Detailed Inspection and Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈09-Oct-2026	
	27 A/F	5-12-08					Mos	17-Dec-2021					
							Hrs	2295:34		2,400	-/+25	(4695:34)	1379:27 Hrs (+25)
							Ldg	1,748					
			(ZONE: 241, 242, 251, 252, 263, 264, 321, 322, 340, 341) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 25-11-01-2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES -5002 THRU -5555 INCORPORATINGSB560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019,CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560 XL MM Section 5-10-02)										
27-20-00-7201		Rudder Trim Actuator and Pushrod (Free Play) Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈26-Jan-2027	
	27 A/F	5-12-07					Mos	31-Oct-2024					
							Hrs	3308:54		1,600	-/+25	(4908:54)	1592:47 Hrs (+25)
							Ldg	2,570					
27-31-00-2200		Elevator and Trim Tab System Detailed Inspection							RE	05-10-01, 05-10-02, Category 5, Category 6			
	27 A/F	5-12-06					Mos	09-Oct-2023		48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
							Hrs	3048:30					
							Ldg	2,362					
27-31-00-2201		Elevator and Elevator Trim Detailed Inspection and Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈09-Oct-2026	
	27 A/F	5-12-08					Mos	17-Dec-2021					
							Hrs	2295:34		2,400	-/+25	(4695:34)	1379:27 Hrs (+25)
							Ldg	1,748					
27-31-00-2201		Elevator and Elevator Trim Detailed Inspection and Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈09-Oct-2026	
	27 A/F	5-12-07					Mos	31-Oct-2024					
							Hrs	3308:54		1,600	-/+25	(4908:54)	1592:47 Hrs (+25)
							Ldg	2,570					
27-31-00-7201		Elevator Trim Tab and Pushrod (Free Play) Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈26-Jan-2027	
	27 A/F	5-12-07					Mos	31-Oct-2024					
							Hrs	3308:54		1,600	-/+25	(4908:54)	1592:47 Hrs (+25)
							Ldg	2,570					
		(ZONE: 353, 354) (Tol. Adjustment: -108.9 Hrs) (SOURCE: 560 XL MM Section 5-10-02)											

Task No		Description							Categories		Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining		
27-40-00-7200		Two-Position Horizontal Stabilizer Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈09-Oct-2026	
	27 A/F	5-12-08					Mos	17-Dec-2021					
							Hrs	2295:34		2,400	-/+25	(4695:34)	1379:27 Hrs (+25)
							Ldg	1,748					
			(ZONE: 252, 340) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 25-11-01-2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES -5002 THRU -5555 INCORPORATINGSB560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560 XL MM Section 5-10-02)										
27-51-00-2200		Flap Cables Detailed Inspection and Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈09-Oct-2026	
	27 A/F	5-12-08					Mos	17-Dec-2021					
							Hrs	2295:34		2,400	-/+25	(4695:34)	1379:27 Hrs (+25)
							Ldg	1,748					
			(ZONE: 514, 614, 241) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 25-11-01-2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES -5002 THRU -5555 INCORPORATINGSB560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560 XL MM Section 5-10-02)										
27-71-00-7100		Control (Gust) Lock System Operational Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	27 A/F	5-12-01					Mos	31-Oct-2024		12	-/+1m	(31-Oct-2025)	11.7 Months (+30 Days)
							Hrs	3308:54					
							Ldg	2,570					
			(ZONE: 141, 235) (SOURCE: 560 XL MM Section 5-10-02)										
560XL-27-32		Rudder Pedal Position Modification							RE (-)		Optional		
	27 A/F					Mos							
						Hrs							
						Ldg							
560XL-27-32 Rev 01		Rudder Pedal Position Modification							RE (-)		Optional		
	27 A/F					Mos							
						Hrs							
						Ldg							
560XL-27-32 Rev 02		Rudder Pedal Position Modification							RE (-)		Recommended		
	27 A/F	Eff: 10-May-2011 Not Applicable	Different SN of Aircraft					Mos	13-Sep-2021				
								Hrs					
								Ldg					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
560XL-27-35		Flight Controls - Stainless Steel Hydraulic Tube Replacement								RE (-)	Optional
	27 A/F	Not Applicable as per S/N					Mos	09-Sep-2021			
							Hrs	2218:31			
							Ldg	1,685			
560XL-27-35 Rev 01		Flight Controls - Stainless Steel Hydraulic Tube Replacement								RE (-)	Optional
	27 A/F	Eff: 11-Nov-2014 Not Applicable as per S/N					Mos	09-Sep-2021			
							Hrs	2218:31			
							Ldg	1,685			
57-50-00-2200		Left Speed Brake Panels and Attachment Fittings Detailed Inspection								REMSG-3 Structures Inspection Tasks	
	27 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027) 3 Years (+30 Days)
		(ZONE: 522) (SOURCE: 560 XL MM Section 5-10-03)					Hrs	3048:30			
							Ldg	2,362			
57-50-00-2200		Right Speed Brake Panels and Attachment Fittings Detailed Inspection								REMSG-3 Structures Inspection Tasks	
	27 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027) 3 Years (+30 Days)
		(ZONE: 622) (UPDATE NOTE: RH Upper Speed Brake Pushrod Bonding Jumper Torn Apart Refer to Order: 101046709) (SOURCE: 560 XL MM Section 5-10-03)					Hrs	3048:30			
							Ldg	2,362			
SL560XL-27-05		Cable Fairlead Replacement								RE (-)	Recommended
	27 A/F	Not Applicable as per S/N					Mos	09-Sep-2021			
							Hrs	2218:31			
							Ldg	1,685			
SL560XL-27-05 Rev 01		Cable Fairlead Replacement								RE (-)	Recommended
	27 A/F	Not Applicable as per S/N					Mos	09-Sep-2021			
							Hrs	2218:31			
							Ldg	1,685			
SL560XL-27-05 Rev 02		Cable Fairlead Replacement								RE (-)	Mandatory
	27 A/F	Eff: 05-Feb-2014 Not Applicable as per S/N					Mos	09-Sep-2021			
							Hrs	2218:31			
							Ldg	1,685			
SL560XL-27-14		Horizontal and Vertical Stabilizer Erosion Boot Installation								T (A/R)	Optional
	27 A/F	Eff: 30-Mar-2006					Mos				
							Hrs				
							Ldg				
SL560XL-27-18		Elevator Trim Cable Replacement Intervals								T (A/R)	Informational
	27 A/F	Eff: 21-Feb-2012					Mos				
							Hrs				
							Ldg				
SL560XL-27-20		Rudder Torque Tube/Sector Assembly Gap Inspection								RE (-)	Recommended
	27 A/F	Not Applicable as per S/N					Mos	09-Sep-2021			
							Hrs	2218:31			
							Ldg	1,685			
SL560XL-27-20 Rev 01		Rudder Torque Tube/Sector Assembly Gap Inspection								RE (-)	Recommended
	27 A/F	Not Applicable as per S/N					Mos	09-Sep-2021			
							Hrs	2218:31			
							Ldg	1,685			
SL560XL-27-20 Rev 02		Rudder Torque Tube/Sector Assembly Gap Inspection								RE (-)	Mandatory
	27 A/F	Eff: 18-Jan-2014 Not Applicable as per S/N					Mos	09-Sep-2021			
							Hrs	2218:31			
							Ldg	1,685			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SL560XL-27-21		Rudder Torque Tube/Sector Assembly Inspection						RE (-)		Mandatory	
	27 A/F						Mos	09-Sep-2021			
	Eff: 18-Jan-2014 Not Applicable	as per S/N					Hrs	2218:31			
							Ldg	1,685			
SL560XL-27-33		Flight Controls - Elevator Cable Inspection at the Aft Canted Bulkhead						RE (-)		Mandatory	
	27 A/F						Mos	09-Sep-2021			
	Eff: 05-Nov-2014 Not Applicable	as per S/N					Hrs	2218:31			
							Ldg	1,685			
SL560XL-27-34		Flight Controls - Right Outboard Aileron Wing Up Cable Assembly Inspection						RE (-)		Recommended	
	27 A/F						Mos	09-Sep-2021			
	Not Applicable	as per S/N					Hrs	2218:31			
							Ldg	1,685			
SL560XL-27-34 Rev 01		Flight Controls - Right Outboard Aileron Wing Up Cable Assembly Inspection						RE (-)		Mandatory	
	27 A/F						Mos	09-Sep-2021			
	Eff: 22-Jan-2015 Not Applicable	as per S/N					Hrs	2218:31			
							Ldg	1,685			
SL560XL-27-34 Rev 02		Flight Controls - Right Outboard Aileron Wing Up Cable Assembly Inspection						RE (-)		Mandatory	
	27 A/F						Mos	09-Sep-2021			
	Eff: 12-Jun-2019 Not Applicable	as per S/N					Hrs	2218:31			
	(AVG MAN HRS: 3.2)						Ldg	1,685			
SL560XL-27-35		Flight Controls - AFT Aileron Sector Assembly Inspection						RE (-)		Mandatory	
	27 A/F						Mos	09-Sep-2021			
	Eff: 16-Nov-2015 Not Applicable	as per S/N					Hrs	2218:31			
	(AVG MAN HRS: 1)						Ldg	1,685			
SL560XL-27-36		Flight Controls - Horizontal Stabilizer Actuator Bolt Inspection						RE (-)		Mandatory	
	27 A/F						Mos	09-Sep-2021			
	Eff: 26-Aug-2015 Not Applicable	as per S/N					Hrs	2218:31			
							Ldg	1,685			
SL560XL-27-37		Flight Controls - Rudder Position Sensor Wire Routing Improvement						RE (-)		Mandatory	
	27 A/F						Mos	09-Sep-2021			
	Eff: 13-Jan-2016 Not Applicable	as per S/N					Hrs	2218:31			
	(AVG MAN HRS: 1.5)						Ldg	1,685			
SL560XL-27-37 Rev 01		Flight Controls - Rudder Position Sensor Wire Routing Improvement						RE (-)		Mandatory	
	27 A/F						Mos	09-Sep-2021			
	Eff: 25-Mar-2016 Not Applicable	as per S/N					Hrs	2218:31			
	(AVG MAN HRS: 1.5)						Ldg	1,685			
SL560XL-27-37 Rev 02		Flight Controls - Rudder Position Sensor Wire Routing Improvement						RE (-)		Mandatory	
	27 A/F						Mos	09-Sep-2021			
	Eff: 21-Jul-2016 Not Applicable	as per S/N					Hrs	2218:31			
	(AVG MAN HRS: 1.5)						Ldg	1,685			
SL560XL-27-38		Flight Controls - Inspection of the Horizontal Stabilizer Upper Scissor Link Fitting						RE (-)		Recommended	
	27 A/F						Mos	26-Oct-2022			
	Eff: 05-Oct-2022 Not Applicable	by S/N of aircraft					Hrs	2753:43			
							Ldg	2,108			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-27-39	Flight Controls - Control Lock Cable Assembly Swivel Seal Inspection						RE (-)		Recommended	
 27 A/F						Mos				
Eff: 03-Sep-2024						Hrs				
(AVG MAN HRS: 7.5)						Ldg				
▼ 28 - FUEL										
	Boost Fuel Electric Pump						RE (O/C)			
28 A/F	Left	0				Mos	29-Oct-2015			
LR55540B	New	0				Hrs	0			
B1916		0				Ldg	0			
	Boost Fuel Electric Pump						RE (O/C)			
28 A/F	Right	0				Mos	29-Oct-2015			
LR55540B	New	0				Hrs	0			
B1929		0				Ldg	0			
	Fuel Boost Cartridge						RE (O/C)			
28 A/F	Left	0				Mos	29-Oct-2015			
LR55505-2	New	0				Hrs	0			
E-037		0				Ldg	0			
	Fuel Boost Cartridge						RE (O/C)			
28 A/F	Right	0				Mos	29-Oct-2015			
LR55505-2	New	0				Hrs	0			
E-042		0				Ldg	0			
	Fuel Crossfeed Actuator						RE (O/C)			
28 A/F		0				Mos	29-Oct-2015			
MA20A1029-1	New	0				Hrs	0			
AA514507		0				Ldg	0			
	Fuel Crossfeed Valve						RE (O/C)			
28 A/F		0				Mos	29-Oct-2015			
125838AW	New	0				Hrs	0			
AA527338		0				Ldg	0			
	Fuel Qty W0 Probe						RE (O/C)			
28 A/F	Left	0				Mos	29-Oct-2015			
10634T07Y00	New	0				Hrs	0			
MN36651		0				Ldg	0			
	Fuel Qty W0 Probe						RE (O/C)			
28 A/F	Right	0				Mos	29-Oct-2015			
10634T07Y00	New	0				Hrs	0			
MN36647		0				Ldg	0			
	Fuel Qty W1 Probe						RE (O/C)			
28 A/F	Left	0				Mos	29-Oct-2015			
10634T02Y00	New	0				Hrs	0			
MN35929		0				Ldg	0			
	Fuel Qty W1 Probe						RE (O/C)			
28 A/F	Right	0				Mos	29-Oct-2015			
10634T02Y00	New	0				Hrs	0			
MN36531		0				Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	28 A/F 10634T03Y00 MN35649	Fuel Qty W2 Probe						RE (O/C)			
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	28 A/F 10634T03Y00 MN36236	Fuel Qty W2 Probe						RE (O/C)			
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	28 A/F 10634T04Y00 MN35941	Fuel Qty W3 Probe						RE (O/C)			
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	28 A/F 10634T04Y00 MN35945	Fuel Qty W3 Probe						RE (O/C)			
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	28 A/F 10634T05Y00 MN35950	Fuel Qty W4 Probe						RE (O/C)			
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	28 A/F 10634T05Y00 MN36447	Fuel Qty W4 Probe						RE (O/C)			
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	28 A/F 10634T01Y00 MN35927	Fuel Qty W5 Probe						RE (O/C)			
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	28 A/F 10634T01Y00 MN36427	Fuel Qty W5 Probe						RE (O/C)			
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	28 A/F 10634T06Y00 MN36097	Fuel Qty W6 Probe						RE (O/C)			
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	28 A/F 10634T06Y00 MN36098	Fuel Qty W6 Probe						RE (O/C)			
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	28 A/F 10635B03Y04 15071707	Fuel Quantity Signal Conditioner						RE (O/C)			
			0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	28 A/F 840203-105 7684XP	Fuel Relief Valve Assy								RE (O/C)	
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	28 A/F 840203-105 7612XP	Fuel Relief Valve Assy								RE (O/C)	
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	28 A/F 71498 2244A	Fuel Shut-Off Valve								RE (O/C)	
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	28 A/F 71498 2238A	Fuel Shut-Off Valve								RE (O/C)	
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	28 A/F Unknown Unknown	Fuel Temperature (EI014) Indicator								RE (O/C)	
						Mos	29-Oct-2015				
						Hrs	0				
	28 A/F 750800-2 3422	Fuel Valve Assy								RE (O/C)	
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	28 A/F 750800-2 3439	Fuel Valve Assy								RE (O/C)	
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	28 A/F 60221-4 2968	Fuel Vent Float Valve								RE (O/C)	
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	28 A/F 60221-4 2977	Fuel Vent Float Valve								RE (O/C)	
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	28 A/F 61087 6571	High Level Fuel Valve								RE (O/C)	
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	28 A/F 61087 6633	High Level Fuel Valve								RE (O/C)	
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	28 A/F L16H-15 964	Low Fuel Level Sensor								RE (O/C)	
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	28 A/F L16H-15 950	Low Fuel Level Sensor								RE (O/C)	
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	28 A/F 726400-1 2926	Low Level Valve Assy								RE (O/C)	
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	28 A/F 726400-1 2925	Low Level Valve Assy								RE (O/C)	
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	28 A/F 4151 1884	Motive Flow Shutoff (UY008) Valve								RE (O/C)	
		Serviceable					Mos	22-Feb-2022			
							Hrs	2400:50			
	28 A/F 4151 1863	Motive Flow Shutoff (UY009) Valve								RE (O/C)	
		Serviceable					Mos	22-Feb-2022			
							Hrs	2400:50			
	28 A/F 2950023-101 1889	Primary Motive Flow Ejector Pump								RE (O/C)	
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	28 A/F 2950023-101 1896	Primary Motive Flow Ejector Pump								RE (O/C)	
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	28 A/F 2950024-101 5556	Scavenge Fuel Ejector Pump								RE (O/C)	
		Aft - Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	28 A/F 2950024-101 5554	Scavenge Fuel Ejector Pump								RE (O/C)	
		Aft - Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	28 A/F 2950024-101 5559	Scavenge Fuel Ejector Pump								RE (O/C)	
		Fwd - Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
	28 A/F 2950024-101 5555	Scavenge Fuel Ejector Pump					RE (O/C)			
		Fwd - Right	0		Mos	29-Oct-2015				
		New	0		Hrs	0				
			0		Ldg	0				
	28 A/F 2950024-101 5558	Scavenge Fuel Ejector Pump					RE (O/C)			
		Mid - Left	0		Mos	29-Oct-2015				
		New	0		Hrs	0				
			0		Ldg	0				
	28 A/F 2950024-101 5379	Scavenge Fuel Ejector Pump					RE (O/C)			
		Mid - Right	0		Mos	29-Oct-2015				
		New	0		Hrs	0				
			0		Ldg	0				
	28 A/F 80002-101 2594	Single Point Refuel/Defuel Shutoff Valve					RE (O/C)			
		Left	0		Mos	29-Oct-2015				
		New	0		Hrs	0				
			0		Ldg	0				
	28 A/F 80002-101 2596	Single Point Refuel/Defuel Shutoff Valve					RE (O/C)			
		Right	0		Mos	29-Oct-2015				
		New	0		Hrs	0				
			0		Ldg	0				
	28 A/F 9036-351-2 2192	Valve-Refuel/Defuel					RE (O/C)			
			0		Mos	29-Oct-2015				
			0		Hrs	0				
			0		Ldg	0				
	28 A/F Unknown Unknown	Wing Fuel Low Level Float Switch					RE (O/C)			
		Left			Mos	29-Oct-2015				
					Hrs	0				
					Ldg	0				
28-00-02-2200	Microbiological Contamination Inspection (Airplanes Not Using the Biocidal Preventative Treatment)						RE	Discretionary Maintenance		
	28 A/F	Ref:Chapter 28, Fuel Contamination - Inspection/Check (SOURCE: 560 XL MM Section 5-19-00)			Mos	31-Oct-2024	3	31-Jan-2025	78 Days	
					Hrs	3308:54				
					Ldg	2,570				
28-00-02-2201	Microbiological Contamination Inspection (Airplanes Using the Biocidal Preventative Treatment)						RE (N/A)	Discretionary Maintenance		
	28 A/F	Ref:Chapter 28, Fuel Contamination - Inspection/Check (SOURCE: 560 XL MM Section 5-19-00)			Mos					
					Hrs					
					Ldg					
28-11-04-2200	Fuel Filler Cap Detailed Inspection and Lubrication						RE	05-10-01, 05-10-02, Category 9		
	28 A/F	5-12-01			Mos	31-Oct-2024	12	-/+ 1m	(31-Oct-2025)	11.7 Months (+30 Days)
					Hrs	3308:54				
					Ldg	2,570				
28-11-04-2200	Fuel Filler Cap Detailed Inspection and Lubrication						RE	05-10-01, 05-10-02, Category 9		
	28 A/F	5-12-01			Mos	31-Oct-2024	12	-/+ 1m	(31-Oct-2025)	11.7 Months (+30 Days)
					Hrs	3308:54				
					Ldg	2,570				
		MRBR Task:28-10-00-201, MRBR Task:28-10-00-601 (ZONE: 631) (SOURCE: 560XL MM)								

Task No		Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
28-42-00-7100		Fuel Low Level Float Switch Operational Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	28 A/F	5-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)	
		(ZONE: 235) (SOURCE: 560 XL MM Section 5-10-02)				Hrs	3048:30					
		Note: NOTE: It is recommended you do this task at the same time as Tasks 57-00-00-2101 and 57-00-00-2102				Ldg	2,362					
CIL-28-01		Fuel - Microbiological Contamination in Aircraft Fuel Tanks and Fuel Systems						T (A/R)		Informational		
	28 A/F					Mos						
	Eff: 24-Feb-2023					Hrs						
						Ldg						
SIL-GEN-108		Jet Fuel Containing Fatty Acid Methyl Esters (FAME)						RE (-)		Service Information Letter		
	28 ENG1					Mos						
						Hrs						
						Enc						
SIL-GEN-108		Jet Fuel Containing Fatty Acid Methyl Esters (FAME)						RE (-)		Service Information Letter		
	28 ENG2					Mos						
						Hrs						
						Enc						
SIL-GEN-108 Rev 1		Jet Fuel Containing Fatty Acid Methyl Esters (FAME)						RE (-)		Service Information Letter		
	28 ENG1					Mos						
						Hrs						
						Enc						
SIL-GEN-108 Rev 1		Jet Fuel Containing Fatty Acid Methyl Esters (FAME)						RE (-)		Service Information Letter		
	28 ENG2					Mos						
						Hrs						
						Enc						
SIL-GEN-108 Rev 2		Jet Fuel Containing Fatty Acid Methyl Esters (FAME)						T (A/R)		Service Information Letter		
	28 ENG1					Mos						
	Eff: 01-Nov-2017					Hrs						
						Enc						
SIL-GEN-108 Rev 2		Jet Fuel Containing Fatty Acid Methyl Esters (FAME)						T (A/R)		Service Information Letter		
	28 ENG2					Mos						
	Eff: 01-Nov-2017					Hrs						
						Enc						
SL560XL-28-03		Motive Flow Shutoff Valve O-Ring Replacement						RE (-)		Recommended		
	28 A/F					Mos	13-Sep-2021					
	Eff: 15-Nov-2010 Not Applicable	Different SN of Aircraft				Hrs						
						Ldg						
SL560XL-28-06		Fuel - Fuel Hopper Panel Protection						RE (-)		Service Letter		
	28 A/F					Mos						
	Eff: 26-Feb-2018					Hrs						
	(AVG MAN HRS: 6)					Ldg						
SL560XL-28-07		Fuel - 6621102-1 Left Web Corrosion Protection						RE (-)		Recommended		
	28 A/F					Mos	24-May-2022					
	Eff: 16-May-2022 Not Applicable	as per S/N of A/C				Hrs	2577:13					
	(AVG MAN HRS: 8)					Ldg	1,968					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
▼ 29 - HYDRAULIC POWER											
	29 A/F AV24B1325C5 AA529053	Firewall Hyd Shutoff Valve								RE (O/C)	
		Left									
		New									
			0			Mos	29-Oct-2015				
	29 A/F AV24B1325C5 AA529054	Firewall Hyd Shutoff Valve								RE (O/C)	
		Right									
		New									
			0			Mos	29-Oct-2015				
	29 A/F Unknown Unknown	Hydraulic Bypass Valve								RE (O/C)	
						Mos	29-Oct-2015				
	29 A/F 3520020100-4 07862	Hydraulic Flow Switch								RE (O/C)	
		Left									
		New									
			0			Mos	29-Oct-2015				
	29 A/F 3520020100-4 07871	Hydraulic Flow Switch								RE (O/C)	
		Right									
		New									
			0			Mos	29-Oct-2015				
	29 A/F 80637 1745	Hydraulic Pressure Switch								RE (O/C)	
		New									
			0			Mos	29-Oct-2015				
			0			Hrs		0			
	29 A/F 24195-LAA 5983	Hydraulic Pump								RE (O/C)	
		Left									
		New									
			0			Mos	29-Oct-2015				
	29 A/F 24195-LAA 5965	Hydraulic Pump								RE (O/C)	
		Right									
		New									
			0			Mos	29-Oct-2015				
	29 A/F Unknown Unknown	Hydraulic Relief Valve								RE (O/C)	
						Mos	29-Oct-2015				
	29 A/F 7470-1 1108	Hydraulic Reservoir								RE (O/C)	
		New									
			0			Mos	29-Oct-2015				
			0			Hrs		0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
Hydraulic Thermal Relief Valve										
29 A/F	Unknown					Mos	29-Oct-2015		RE (O/C)	
	Unknown					Hrs	0			
						Ldg	0			
Speed Brake Thermal Relief Valve										
29 A/F	2664	New	0			Mos	29-Oct-2015		RE (O/C)	
	0542		0			Hrs	0			
			0			Ldg	0			
29-11-04-9600 Hydraulic System Filters Discard										
29 A/F	5-12-13					Mos	17-Dec-2021	72	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	(ZONE: 313) (Tol. Adjustment: -48d) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 13 IAW AMM 560XL (REV 46) CHAPTER 5-12-13 (REV 46)					Hrs	2295:34	-/+1m	(29-Oct-2027)	3 Years (+31 Days)
	) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	1,748			
SL560XL-29-03 R1 Hydraulic Power - Engine Hydraulic Hose Inspection										
29 A/F	Eff: 17-Jun-2020 Not Applicable	by aircraft S/N				Mos	13-Sep-2021		RE (-)	Recommended
	(AVG MAN HRS: 6)					Hrs	2222:03			
						Ldg	1,687			
SL560XL-29-04 Hydraulic Power - Hydraulic Manifold Control Valve Wire Bundle Inspection										
29 A/F	Eff: 15-Jan-2015 Not Applicable	Different SN of Aircraft				Mos	13-Sep-2021		RE (-)	Recommended
						Hrs				
						Ldg				
SL560XL-29-04 Rev 1 Hydraulic Power - Hydraulic Manifold Control Valve Wire Bundle Inspection										
29 A/F	Eff: 12-Jun-2019 Not Applicable	Different SN of Aircraft				Mos	13-Sep-2021		RE (-)	Recommended
	(AVG MAN HRS: 1.5)					Hrs				
						Ldg				
SL560XL-29-05 Engine Driven Pump Hydraulic Verification										
29 A/F	Eff: 14-Jun-2017 Complied With	PARTS INSTALLED ARE UNAFFECTED. NO ACTION REQUIRED. LH ENG EDP S/N: 5983 RH ENG EDP S/N: 5965				Mos	06-Jun-2018		RE (-)	Recommended, Service Letter
						Hrs	1000:36			
						Ldg	848			
Note: COMPLIANCE: This service letter should be accomplished at a scheduled maintenance period or inspection.										
▼ 30 - ICE AND RAIN PROTECTION										
Anti-Ice Bleed Air Under Temp SI013 Switch										
30 A/F	1173T42-4	Left	0			Mos	29-Oct-2015		RE (O/C)	
	5054	New	0			Hrs	0			
			0			Ldg	0			
Anti-Ice Bleed Air Under Temp Sr016 Switch										
30 A/F	1173T42-4	Right	0			Mos	29-Oct-2015		RE (O/C)	
	5053	New	0			Hrs	0			
			0			Ldg	0			
Deice Tail Valve										
30 A/F	3D2353-06	Left	0			Mos	29-Oct-2015		RE (O/C)	
	N151424	New	0			Hrs	0			
			0			Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	30 A/F 3D2353-06 N151242	Deice Tail Valve								RE (O/C)	
		Right	0				Mos	29-Oct-2015			
		New	0				Hrs	0			
	30 A/F P29S4D5280-11 NFA3670	Horiz Stab Deice Boot								RE (O/C)	
		Left	0				Mos	24-Oct-2019			
		New	0				Hrs	1689:25			
	30 A/F P29S4D5280-02 NER5920	Horiz Stab Deice Boot								RE (O/C)	
		Right					Mos	31-Dec-2020			
							Hrs	2086:50			
	30 A/F 1962-00-7 5692	Inlet Anti-Ice Pressure Reg Shutoff Vd001 Valve								RE (O/C)	
		Left	0				Mos	29-Oct-2015			
		New	0				Hrs	0			
	30 A/F 1962-00-7 5644	Inlet Anti-Ice Pressure Reg Shutoff Ve002 Valve								RE (O/C)	
		Right	0				Mos	29-Oct-2015			
		New	0				Hrs	0			
	30 A/F 2602-36 2544	Isolation Valve								RE (O/C)	
		New	0				Mos	29-Oct-2015			
			0				Hrs	0			
	30 A/F 1173T0759 7393	Nacelle Inlet Switch								RE (O/C)	
		Left	0				Mos	29-Oct-2015			
		New	0				Hrs	0			
	30 A/F 1173T0759 7412	Nacelle Inlet Switch								RE (O/C)	
		Right	0				Mos	29-Oct-2015			
		New	0				Hrs	0			
	30 A/F Unknown Unknown	Nose Compartment Overtemperature Switch								RE (O/C)	
							Mos	29-Oct-2015			
							Hrs	0			
	30 A/F PH1100-1-VCW AS08164061	Pitot Tube								RE (O/C)	
		Left	0				Mos	20-Jun-2017			
		New	0				Hrs	592:35			
	30 A/F PH1100-1-VCW AS08164065	Pitot Tube								RE (O/C)	
		Right	0				Mos	20-Jun-2017			
		New	0				Hrs	592:35			
											
							Ldg	544			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
30 A/F 1946-00-19 5158	Left New	Pressure Reg Valve					RE (O/C)			
			0		Mos	29-Oct-2015				
			0		Hrs	0				
30 A/F 1946-00-19 5160	Right New	Pressure Reg Valve					RE (O/C)			
			0		Mos	29-Oct-2015				
			0		Hrs	0				
30 A/F PH1100-1-RCDW AS11166736	New	Standby Pitot Tube					RE (O/C)			
			0		Mos	20-Jun-2017				
			0		Hrs	592:35				
30 A/F 1106P55-1 12168A	Right New	Tail Deice Pressure Sv004 Switch					RE (O/C)			
			0		Mos	14-Aug-2019				
			0		Hrs	1589:15				
30 A/F Unknown 12759A	Left	Tail Deice Pressure Sv005 Switch					RE (O/C)			
					Mos	08-Jan-2021				
					Hrs					
30 A/F 856-1-3 458XFT	Left New	Windshield Controller					RE (O/C)			
			0		Mos	29-Oct-2015				
			0		Hrs	0				
30 A/F 856-1-3 458XFX	Right New	Windshield Controller					RE (O/C)			
			0		Mos	29-Oct-2015				
			0		Hrs	0				
30 A/F 011598-501 C15240352	New	Windshield Rain Removal Mn001 Fan					RE (O/C)			
			0		Mos	29-Oct-2015				
			0		Hrs	0				
2012-06-01 30 A/F Eff: 25-Apr-2012 Not Applicable (ISSUING AUTHORITY: FAA)	BY SERIAL NUMBER	To Prevent Ice Accumulation on the Cables and Pulleys of the Stinger					RE (-)		Mandatory	
					Mos	05-Jul-2021				
					Hrs					
30 A/F 5-12-01 (ZONE: 162, 235) (SOURCE: 560 XL MM Section 5-10-02)		Bleed Air Anti-Ice Systems Operational Check					RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
					Mos	31-Oct-2024	12	-/+1m (31-Oct-2025)	11.7 Months (+30 Days)	
					Hrs	3308:54				
					Ldg	2,570				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30-12-00-7100	Horizontal Stabilizer Deice System Operational Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 30 A/F	5-12-01				Mos	31-Oct-2024	12	-/+1m (31-Oct-2025)		11.7 Months (+30 Days)
	(ZONE: 311, 312, 321, 322, 340) (SOURCE: 560 XL MM Section 5-10-02)				Hrs	3308:54				
					Ldg	2,570				
560XL-30-06	Horizontal Stabilizer Deice System Pressure Switch Installation Improvement						RE (-)		Discretionary	
 30 A/F					Mos					
	Eff. 15-Sep-2008				Hrs					
					Ldg					
98-04-38	AFM - Limitations Section - Icing						RE (-)		Mandatory	
 30 A/F					Mos	28-Oct-2015				
	Eff. 25-Mar-1998 Complied AFM checked				Hrs					
	With				Ldg					
	(ISSUING AUTHORITY: FAA)									
CIL-30-01	Ice and Rain Protection - Approved Deicing Program Updates						RE (-)		Informational	
 30 A/F					Mos					
					Hrs					
					Ldg					
CIL-30-01 R1	Ice and Rain Protection - Approved Deicing Program Updates						T (A/R)		Informational	
 30 A/F					Mos					
	Eff. 13-Sep-2013				Hrs					
					Ldg					
SL560XL-30-01	Approved Deicing Program Updates						RE (-)		Optional	
 30 A/F					Mos					
					Hrs					
					Ldg					
SL560XL-30-01 Rev 01	Approved Deicing Program Updates						RE (-)		Optional	
 30 A/F					Mos					
					Hrs					
					Ldg					
SL560XL-30-01 Rev 02	Approved Deicing Program Updates						RE (-)		Optional	
 30 A/F					Mos					
					Hrs					
					Ldg					
SL560XL-30-01 Rev 03	Approved Deicing Program Updates						RE (-)		Optional	
 30 A/F					Mos					
					Hrs					
					Ldg					
SL560XL-30-01 Rev 04	Approved Deicing Program Updates						RE (-)		Optional	
 30 A/F					Mos					
					Hrs					
					Ldg					
SL560XL-30-01 Rev 05	Approved Deicing Program Updates						RE (-)		Optional	
 30 A/F					Mos					
					Hrs					
					Ldg					
SL560XL-30-01 Rev 06	Approved Deicing Program Updates						RE (-)		Optional	
 30 A/F					Mos					
					Hrs					
					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-30-01 Rev 07  30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-30-01 Rev 08  30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-30-01 Rev 09  30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-30-01 Rev 10  30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-30-01 Rev 11  30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-30-01 Rev 12  30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-30-01 Rev 13  30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-30-01 Rev 14  30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-30-01 Rev 15  30 A/F Eff: 08-Oct-2012	Approved Deicing Program Updates						T (A/R)		Informational	
					Mos					
					Hrs					
					Ldg					
▼ 31 - INDICATING / RECORDING SYSTEM										
 31 A/F M877A5V 22482		Digital Clock					RE (O/C)			
	Left					0	Mos	29-Oct-2015		
	New					0	Hrs	0		
						0	Ldg	0		
 31 A/F Unknown Unknown		Digital Clock					RE (O/C)			
	Right						Mos	29-Oct-2015		
							Hrs	0		
							Ldg	0		
 31 A/F 6222SM15 22627		Engine Accelerometer					RE (O/C)			
	Left					0	Mos	29-Oct-2015		
	New					0	Hrs	0		
						0	Ldg	0		

OK-ECR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-ECR,SN 560-6198

Task No	Description		TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition								DUE	Remaining
	31 A/F 6222SM15 22620	Engine Accelerometer						RE (O/C)			
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	31 A/F 2100-2045-00 002055610	Flight Data Recorder (FDR)						RE (O/C)			
						Mos	09-Oct-2022				
		Overhauled		0		Hrs	2719:35				
				0		Ldg	2,082				
	31 A/F 3001-01-111-3 0715-DTY8385	Flight Data Recorder (FDR) Accelerometer						RE (O/C)			
			0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	31 A/F Unknown Unknown	Flight Data Recorder (FDR) Fail Annunciator						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	31 A/F Unknown Unknown	Flight Data Recorder (FDR) Impact Switch						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	31 A/F 266-E5542-00 ULB039730	Flight Data Recorder (FDR) Underwater Locating Device (ULD)						RE (O/C)			
						Mos	09-Oct-2022				
		New				Hrs	2719:35				
						Ldg	2,082				
	31 A/F 266-E5542-00 ULB013369 Ref:31-30-04-9600	Flight Data Recorder (FDR) Underwater Locating Device (ULD) Battery						RE (H/T)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
						Mos	09-Oct-2022				
						Hrs	2719:35				
						Ldg	2,082				
	31 A/F NS-5DMG2-RXA 1332039	Inclinometer						RE (O/C)			
			0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	31 A/F Unknown Unknown	Master Warning Annunicator						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	31 A/F Unknown Unknown	MFDAU Flight Data Recorder (FDR) Unit						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				

Task No	Description										Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL		DUE	Remaining
Tilt Indicator								RE (O/C)				
	31 A/F	New	0			Mos	29-Oct-2015					
	3001J72		0			Hrs	0					
	25632		0			Ldg	0					
Warning Gen/Mixer Unit								RE (O/C)				
	31 A/F	Left				Mos	29-Oct-2015					
	Unknown					Hrs	0					
	Unknown					Ldg	0					
Warning Gen/Mixer Unit								RE (O/C)				
	31 A/F	Right				Mos	29-Oct-2015					
	Unknown					Hrs	0					
	Unknown					Ldg	0					
31-20-01-9600		Left Digital Clock AA Long Life Battery Discard						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	31 A/F	Left5-12-01				Mos	31-Oct-2024	12	-/+1m	(31-Oct-2025)	11.7 Months (+30 Days)	
	M877A5V					Hrs	3308:54					
	22482					Ldg	2,570					
(ZONE: 235) (SOURCE: 560 XL MM Section 5-10-02)												
31-20-01-9600		Right Digital Clock AA Long Life Battery Discard						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	31 A/F	Right5-12-01				Mos	31-Oct-2024	12	-/+1m	(31-Oct-2025)	11.7 Months (+30 Days)	
	Unknown					Hrs	3308:54					
	Unknown					Ldg	2,570					
(ZONE: 235) (SOURCE: 560 XL MM Section 5-10-02)												
31-30-04-9600		DK120 or DK120/90 Flight Data Recorder Underwater Locator Beacon Battery Discard						RE	05-10-01, 05-10-02, 05-12-00, Category 9			
	31 A/F	266-E5542-00 ULB013369				Mos	09-Oct-2022	72			31-Mar-2025	4.6 Months
						Hrs	2719:35					
						Ldg	2,082					
Expiration Date 01-Mar-2025												
MRBR Task:31-30-00-901, MRBR Task:31-30-00-902, MRBR Task:31-31-00-902, MRBR Task:31-31-00-901 (SOURCE: 560XL MM)												
Note: 72 Months (DK120) Tracked by Component Expiration Date. NOTE: Per Supplier Recommendation. Reference L3 Communications FA2100FDR Component Maintenance Manual or the Dukane Seacom 03-TM-0037 (DK120) Technical Manual												
	ECR-WP-010 / OKECR/013 START 24-JUN-2024											
313010		Flight Data Aquisition (Fdau) Unit						RE (O/C)				
	31 A/F	3001-7440-03 002018716				Mos	03-Oct-2022					
						Hrs	2706:58					
						Ldg	2,069					
313011		Inboard Flight Data Recorder (PCB) Printed Circuit Board						RE (O/C)				
	31 A/F	New	0			Mos	29-Oct-2015					
	8718-973-1		0			Hrs	0					
	0242		0			Ldg	0					
313011		Outboard Flight Data Recorder (PCB) Printed Circuit Board						RE (O/C)				
	31 A/F	New	0			Mos	29-Oct-2015					
	8718973-1		0			Hrs	0					
	0246		0			Ldg	0					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
316016		Rosenview Lx Processor								RE (O/C)	Custom Task
	31 A/F						Mos	08-Oct-2015			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
560XL-31-05		Data Concentrator Unit Software Upgrade								RE (-)	Mandatory
	31 A/F						Mos	09-Sep-2021			
	Eff: 03-Jun-2009 Not Applicable	as per S/N					Hrs	2218:31			
							Ldg	1,685			
CIL-31-01		Indicating/Recording Systems - CVR, FDR, and CVDR 90-Day Battery Underwater Locator Beacon (ULB) Installation								RE (-)	Informational, Service Letter
	31 A/F						Mos	20-Aug-2018			
	Eff: 02-Feb-2018 Complied With						Hrs	1138:38			
							Ldg	941			
Note: EFFECTIVITY: All Citation airplanes that are equipped with a Textron Aviation engineered CVR, FDR, or CVDR installation.											
SB560XL-31-06		Indicating/Recording Systems - Option to Replace the Avionics Secondary Quick Access Recorder (QAR) with an L-3 Secondary Quick Access Recorder								T (A/R)	Optional, Service Bulletin
	31 A/F						Mos				
							Hrs				
							Ldg				
SL560XL-31-05		Transmittal of L-3 Communications Alert Bulletin No. Cessna SB 001								RE (-)	Mandatory
	31 A/F						Mos	09-Sep-2021			
	Eff: 04-Aug-2011 Not Applicable	as per S/N					Hrs	2218:31			
							Ldg	1,685			
SL560XL-31-06		Inspection of the Position-Sensor Potentiometer for the Elevator Trim Tab								RE (-)	Recommended
	31 A/F						Mos	13-Sep-2021			
	Eff: 22-Oct-2012 Not Applicable	Different SN of Aircraft					Hrs				
							Ldg				
SL560XL-31-07		Indicating/ Recording Systems - Rudder Surface Input Sensor Pushrod Lockwire Installation								RE (-)	Recommended, Service Letter
	31 A/F						Mos	13-Sep-2021			
	Eff: 23-Jun-2017 Not Applicable	Different SN of Aircraft					Hrs				
	(AVG MAN HRS: 1.4)						Ldg				
SL560XL-31-08		Indicating/Recording Systems - Collins Environmental Controller (IEC) and Power Supply (PWR) IAPS Modules Inspection/Replacement								RE (-)	Recommended
	31 A/F						Mos				
	Eff: 14-Jun-2023						Hrs				
	(AVG MAN HRS: 4.5)						Ldg				
▼ 32 - LANDING GEAR											
		Antiskid Control (UY009) Valve								RE (O/C)	
	32 A/F						Mos	29-Oct-2015			
	39-837	New					Hrs	0			
	1260						Ldg	0			
		Antiskid Digital Control								RE (O/C)	
	32 A/F						Mos	29-Oct-2015			
	42-985-2	New					Hrs	0			
	1004B						Ldg	0			
		Antiskid Fault Display								RE (O/C)	
	32 A/F						Mos	29-Oct-2015			
	42-92750	New					Hrs	0			
	2764A						Ldg	0			

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
	32 A/F 1785-2 1302	Antiskid Hyd Relief Valve						RE (O/C)				
		New	0			Mos	29-Oct-2015					
			0			Hrs	0					
			0			Ldg	0					
	32 A/F 19940929-1 056311	Antiskid Pressure Gauge						RE (O/C)				
		New	0			Mos	29-Oct-2015					
			0			Hrs	0					
			0			Ldg	0					
	32 A/F 640931 7268	Brake Press Pump Assembly						RE (O/C)				
		New	0			Mos	29-Oct-2015					
			0			Hrs	0					
			0			Ldg	0					
	32 A/F 211-114 2263	Brake Shuttle Valve						RE (O/C)				
		Left	New	0			Mos	29-Oct-2015				
		0				Hrs	0					
		0				Ldg	0					
	32 A/F 211-114 2254	Brake Shuttle Valve						RE (O/C)				
		Right	New	0			Mos	29-Oct-2015				
		0				Hrs	0					
		0				Ldg	0					
	32 A/F 65830-4 1295	Emergency Air Brake Control Valve						RE (O/C)				
		New	0			Mos	29-Oct-2015					
			0			Hrs	0					
			0			Ldg	0					
	32 A/F 9615 0551	Emergency Dump Valve						RE (O/C)				
		New	0			Mos	29-Oct-2015					
			0			Hrs	0					
			0			Ldg	0					
	32 A/F 40005347-3 7432 Manufactured Date 31-Jan-2023 Ref:32-30-09-9600 (SOURCE: 560 XL MM Section 5-13-00) Note: Regulation: US DOT CFR 49 Part 180.209 Requirements for Re-qualification of Specification Cylinders. NOTE: The pneumatic storage bottle is manufactured under U.S. DOT 3HT	Emergency Gear Extension/Brake Pneumatic Storage Bottle						RE	Regulatory Inspections/Time Limits			
		Overhauled				Mos	09-Oct-2023	288		[31-Jan-2035]	10.2 Years	
			0			Hrs	3048:30					
			0			Ldg	2,362					
	32 A/F 98120 5298A	Extend/Retract Valve						RE (O/C)				
		Left	New	0			Mos	29-Oct-2015				
		0				Hrs	0					
		0				Ldg	0					
	32 A/F 98120 5223A	Extend/Retract Valve						RE (O/C)				
		Right	New	0			Mos	29-Oct-2015				
		0				Hrs	0					
		0				Ldg	0					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Landing Gear Control								RE (O/C)	
	32 A/F	Overhauled					Mos	25-Oct-2022			
	9912550-1						Hrs	0			
	0124						Ldg	0			
		Landing Gear Control (VY047) Valve								RE (O/C)	
	32 A/F	New					Mos	29-Oct-2015			
	4219-1						Hrs	0			
	0546						Ldg	0			
		Loading Valve								RE (O/C)	
	32 A/F	New					Mos	29-Oct-2015			
	4215-2						Hrs	0			
	0419						Ldg	0			
		Main Brake Assembly								RE (O/C)	
	32 A/F	Left					Mos	22-Feb-2022			
	2-1601-1	Overhauled					Hrs	0			
	D0062						Ldg	1,827			
		Main Brake Assembly								RE (O/C)	
	32 A/F	Right					Mos	29-Jul-2021			
	2-1601-1	2308P					Hrs	2169:34			
							Ldg	1,654			
		Main Gear Down and Lock (SN011) Switch								RE (O/C)	
	32 A/F	Left					Mos	29-Oct-2015			
	Unknown	Unknown					Hrs	0			
	Unknown						Ldg	0			
		Main Gear Down and Lock (SR008) Switch								RE (O/C)	
	32 A/F	Right					Mos	29-Oct-2015			
	Unknown	Unknown					Hrs	0			
	Unknown						Ldg	0			
		Main Gear Up & Locked (S3) Switch								RE (O/C)	
	32 A/F	Left					Mos	29-Oct-2015			
	65-430087	New					Hrs	0			
	NSN						Ldg	0			
		Main Gear Up & Locked (S3) Switch								RE (O/C)	
	32 A/F	Right					Mos	29-Oct-2015			
	65-430087	New					Hrs	0			
	NSN						Ldg	0			
		Main Landing Gear Assy								RE (O/C)	
	32 A/F	Left					Mos	29-Oct-2015			
	Unknown	Unknown					Hrs	0			
	Unknown						Ldg	0			
		Main Landing Gear Assy								RE (O/C)	
	32 A/F	Right					Mos	29-Oct-2015			
	Unknown	Unknown					Hrs	0			
	Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	32 A/F QSB-5-SS NSN	Main Landing Gear Breather Vent	RE (H/T)								
		Left	0			Mos	07-Nov-2018				
		New	0			Hrs	1230:36				
	32 A/F QSB-5-SS NSN	Main Landing Gear Breather Vent	RE (H/T)								
		Right	0			Mos	07-Nov-2018				
		New	0			Hrs	1230:36				
	32 A/F M13702 2315T240	Main Tire	RE (O/C)								
		Left				Mos	10-Jan-2024				
		New	0			Hrs	3127:37				
	32 A/F M13702 1340T158	Main Tire	RE (O/C)								
		Right				Mos	11-May-2023				
		New	0			Hrs	3006:19				
	32 A/F 3-1571-6 4933	Main Wheel Assembly	RE (O/C)								
		Left				Mos	10-Jan-2024				
		Overhauled		0		Hrs	3127:37				
	32 A/F 3-1571-6 4878	Main Wheel Assembly	RE (O/C)								
		Right				Mos	11-May-2023				
		Tested/Inspected				Hrs	3006:19				
	32 A/F Unknown Unknown	Master Brake Cylinder	RE (O/C)								
		Left Inboard				Mos	29-Oct-2015				
						Hrs	0				
	32 A/F Unknown Unknown	Master Brake Cylinder	RE (O/C)								
		Left Outboard				Mos	29-Oct-2015				
						Hrs	0				
	32 A/F Unknown Unknown	Master Brake Cylinder	RE (O/C)								
		Right Inboard				Mos	29-Oct-2015				
						Hrs	0				
	32 A/F Unknown Unknown	Master Brake Cylinder	RE (O/C)								
		Right Outboard				Mos	29-Oct-2015				
						Hrs	0				
	32 A/F Unknown Unknown	Nose Gear Down and Lock (SN002) Switch	RE (O/C)								
						Mos	29-Oct-2015				
						Hrs	0				
	32 A/F Unknown Unknown					Ldg	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Nose Gear Up & Locked (SN001) Switch								RE (O/C)	
	32 A/F	New	0			Mos	29-Oct-2015				
	65-430087		0			Hrs	0				
	NSN		0			Ldg	0				
		Nose Landing Gear Extend/Retract Valve								RE (O/C)	
	32 A/F	New	0			Mos	29-Oct-2015				
	98120		0			Hrs	0				
	5305A		0			Ldg	0				
		Nose Landing Gear Shimmy Damper								RE (O/C)	
	32 A/F	New	0			Mos	29-Oct-2015				
	5543001-12		0			Hrs	0				
	25017372A		0			Ldg	0				
		Nose Landing Gear Trunnion								RE (O/C)	
	32 A/F	New	0			Mos	29-Oct-2015				
	6642611-9		0			Hrs	0				
	NSN		0			Ldg	0				
		Nose Landing Gear Uplock Actuator								RE (O/C)	
	32 A/F	New	0			Mos	29-Oct-2015				
	5527504-3		0			Hrs	0				
	4875		0			Ldg	0				
		Nose Landing Gear Wheel Assembly								RE (O/C)	
	32 A/F					Mos	27-Jun-2023				
	9914069-2					Hrs	3038:01				
	9590					Ldg	2,352				
		Nose Tire								RE (O/C)	
	32 A/F					Mos	27-Jun-2023				
	031-613-8					Hrs	3038:01				
	UKN					Ldg	2,352				
		Parking Brake Valve								RE (O/C)	
	32 A/F	New	0			Mos	29-Oct-2015				
	98433-2		0			Hrs	0				
	0542		0			Ldg	0				
		Power Brake Accumulator								RE (O/C)	
	32 A/F	New	0			Mos	29-Oct-2015				
	7551-1		0			Hrs	0				
	0440		0			Ldg	0				
		Power Brake Assembly Motor								RE (O/C)	
	32 A/F	Unknown Unknown				Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
		Power Brake Valve								RE (O/C)	
	32 A/F	New	0			Mos	29-Oct-2015				
	32-105-3		0			Hrs	0				
	659		0			Ldg	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Power Pack Motor								RE (O/C)	
	32 A/F	New	0			Mos	29-Oct-2015				
	MP50B1		0			Hrs	0				
	4984		0			Ldg	0				
		Press Antiskid Brk Switch								RE (O/C)	
	32 A/F	New	0			Mos	29-Oct-2015				
	GPP1250-73		0			Hrs	0				
	1512988		0			Ldg	0				
		Pressure (SN011) Switch								RE (O/C)	
	32 A/F	New	0			Mos	29-Oct-2015				
	GPP1250-52		0			Hrs	0				
	1529332		0			Ldg	0				
		Pressure Emer Gear Gauge								RE (O/C)	
	32 A/F	New	0			Mos	29-Oct-2015				
	19940929-1		0			Hrs	0				
	057066		0			Ldg	0				
		Uplock Actuator								RE (O/C)	
	32 A/F	Left	0			Mos	29-Oct-2015				
	5527504-3	New	0			Hrs	0				
	4864		0			Ldg	0				
		Uplock Actuator								RE (O/C)	
	32 A/F	Right	0			Mos	29-Oct-2015				
	5527504-3	New	0			Hrs	0				
	4873		0			Ldg	0				
		Wheel Transducer								RE (O/C)	
	32 A/F	Left				Mos	29-Jul-2021				
	40-955					Hrs	2169:34				
	10479					Ldg	1,654				
		Wheel Transducer								RE (O/C)	
	32 A/F	Right	0			Mos	29-Oct-2015				
	40-955	New	0			Hrs	0				
	NSN		0			Ldg	0				
2012-09-01		To Prevent Brake Failure, Which Could Result in an Airplane Not Being Able to Stop on the Runway							RE (-)		Mandatory
	32 A/F	BY SERIAL NUMBER				Mos	05-Jul-2021				
	Eff: 07-Jun-2012 Not					Hrs					
	Applicable					Ldg					
		(ISSUING AUTHORITY: FAA)									
32-00-00-2101		Left Main Landing Gear Door General Visual Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	32 A/F	5-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
						Hrs	3048:30				
						Ldg	2,362				
		(ZONE: 720) (UPDATE NOTE: Found MLG Dorr With Freeplay refer to Order 101048103) (SOURCE: 560 XL MM Section 5-10-02) Note: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-7100, 53-10-00-2100, and 57-10-00-2100									

Task No	Description								Categories	Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
32-00-00-2101		Nose Landing Gear Door General Visual Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)	
							Hrs	3048:30				
							Ldg	2,362				
(ZONE: 710) (UPDATE NOTE: Refer to Order 101048018 and 101048101) (SOURCE: 560 XL MM Section 5-10-02)												
Note: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-7100, 53-10-00-2100, and 57-10-00-2100												
32-00-00-2101		Right Main Landing Gear Door General Visual Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)	
							Hrs	3048:30				
							Ldg	2,362				
(ZONE: 730) (UPDATE NOTE: Found MLG Dorr With Freeplay refer to Order 101048103) (SOURCE: 560 XL MM Section 5-10-02)												
Note: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-7100, 53-10-00-2100, and 57-10-00-2100												
32-00-00-7100		Landing Gear System General Visual Inspection, Operational Check and Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)	
							Hrs	3048:30				
							Ldg	2,362				
(ZONE: 211, 235,313, 710, 720, 730) (UPDATE NOTE: NLG Cable damaged WO: 101051791) (SOURCE: 560 XL MM Section 5-10-02)												
Note: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-2101, 53-10-00-2100, and 57-10-00-2100												
32-10-00-2200		Left Main Landing Gear Detailed Inspection							RE	05-10-01, 05-10-02, Category 5, Category 6		≈09-Oct-2026
	32 A/F	5-12-08					Mos	17-Dec-2021		-/+25 (4695:34)	1379:27 Hrs (+25)	
							Hrs	2295:34				
							Ldg	1,748				
MRBR Task:32-10-00-201, MRBR Task:32-10-00-202, MRBR Task:32-10-00-203, MRBR Task:32-10-00-204, MRBR Task:32-10-00-205 (ZONE: 720) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 25-11-01-2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES -5002 THRU -5555 INCORPORATINGSB560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019,CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560XL MM)												
32-10-00-2200		Right Main Landing Gear Detailed Inspection							RE	05-10-01, 05-10-02, Category 5, Category 6		≈09-Oct-2026
	32 A/F	5-12-08					Mos	17-Dec-2021		-/+25 (4695:34)	1379:27 Hrs (+25)	
							Hrs	2295:34				
							Ldg	1,748				
MRBR Task:32-10-00-201, MRBR Task:32-10-00-202, MRBR Task:32-10-00-203, MRBR Task:32-10-00-204, MRBR Task:32-10-00-205 (ZONE: 730) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 25-11-01-2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES -5002 THRU -5555 INCORPORATINGSB560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019,CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560XL MM)												

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
32-10-00-9600	Main Landing Gear Oleo Breather Vent Discard (If Installed)						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 32 A/F QSB-5-SS NSN (ZONE: 720) (SOURCE: 560 XL MM Section 5-10-02)	Left5-12-01					Mos Hrs Ldg	31-Oct-2024 3308:54 2,570	12 -/+1m (31-Oct-2025)		11.7 Months (+30 Days)
32-10-00-9600	Main Landing Gear Oleo Breather Vent Discard (If Installed)						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 32 A/F QSB-5-SS NSN (ZONE: 730) (SOURCE: 560 XL MM Section 5-10-02)	Right5-12-01					Mos Hrs Ldg	31-Oct-2024 3308:54 2,570	12 -/+1m (31-Oct-2025)		11.7 Months (+30 Days)
32-10-00-9601	Main Landing Gear Trunnion Subassembly						RE	Airworthiness Limitations Inspection Time Limits		≈30-Dec-2088
 32 A/F 6641630-41 24993038 (ZONE: 730) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)	Left New	0 0 0				Mos Hrs Ldg	29-Oct-2015 0 0			30,724 Ldg
32-10-00-9601	Main Landing Gear Trunnion Subassembly						RE	Airworthiness Limitations Inspection Time Limits		≈30-Dec-2088
 32 A/F 6641630-42 24993395 (ZONE: 720) (UPDATE NOTE: Trunnion Assembly True vendor PN: 6641501-20) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02) Note: Trunnion Assembly True vendor PN: 6641501-20	Right	2169:34 1,654				Mos Hrs Ldg	29-Jul-2021 2169:34 1,654	33,300	33,300	30,724 Ldg
32-10-00-9602	Main Landing Gear Trailing Link Assembly						RE	Airworthiness Limitations Inspection Time Limits		≈13-Jun-2092
 32 A/F 6641530-3 30314848 (ZONE: 730) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)	Left New	0 0 0				Mos Hrs Ldg	29-Jul-2021 2169:34 1,654	33,300	34,954	32,378 Ldg
32-10-00-9602	Main Landing Gear Trailing Link Assembly						RE	Airworthiness Limitations Inspection Time Limits		≈13-Jun-2092
 32 A/F 6641530-4 30336866 (ZONE: 720) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)	Right New	0 0 0				Mos Hrs Ldg	29-Jul-2021 2169:34 1,654	33,300	34,954	32,378 Ldg
32-10-00-9603	Main Landing Gear Trailing Link Spacer						RE	Airworthiness Limitations Inspection Time Limits		≈30-Dec-2088
 32 A/F 6641533-2 24993038 (ZONE: 730) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)	Left New	0 0 0				Mos Hrs Ldg	29-Oct-2015 0 0	33,300	33,300	30,724 Ldg
32-10-00-9603	Main Landing Gear Trailing Link Spacer						RE	Airworthiness Limitations Inspection Time Limits		≈30-Dec-2088
 32 A/F 6641533-2 24993395 (ZONE: 720) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)	Right New	0 0 0				Mos Hrs Ldg	29-Oct-2015 0 0	33,300	33,300	30,724 Ldg

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
32-10-00-9604	Main Landing Gear Oleo Assembly (Except Upper Cap)						RE		Airworthiness Limitations Inspection Time Limits	≈06-Oct-2099
32 A/F	Left				Mos	07-Dec-2022				
6641615-7	Repaired			0	Hrs	2834:32				
24989055		1,707		0	Ldg	2,163	38,000		38,456	35,880 Ldg
(ZONE: 730) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
32-10-00-9604	Main Landing Gear Oleo Assembly (Except Upper Cap)						RE		Airworthiness Limitations Inspection Time Limits	≈23-Oct-2098
32 A/F	Right	0			Mos	29-Oct-2015				
6641615-7	New	0			Hrs	0				
24993098		0			Ldg	0	38,000		38,000	35,424 Ldg
(ZONE: 720) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
32-10-00-9604	Main Landing Gear Oleo Upper Cap						RE		Airworthiness Limitations Inspection Time Limits	≈31-Jul-2050
32 A/F	Left	0			Mos	29-Oct-2015				
6641616-5	New	0			Hrs	0				
24989055		0			Ldg	0	14,900		14,900	12,324 Ldg
(ZONE: 730) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
32-10-00-9604	Main Landing Gear Oleo Upper Cap						RE		Airworthiness Limitations Inspection Time Limits	≈31-Jul-2050
32 A/F	Right	69			Mos	29-Jul-2021				
6641616-5		2169:34			Hrs	2169:34				
24993098		1,654			Ldg	1,654	14,900		14,900	12,324 Ldg
(ZONE: 720) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
32-10-00-9605	Main Landing Gear Actuator Assembly						RE		Airworthiness Limitations Inspection Time Limits	≈16-Jan-2166
32 A/F	Left	0			Mos	29-Oct-2015				
9912537-5	New	0			Hrs	0				
1935		0			Ldg	0	70,200		70,200	67,624 Ldg
(ZONE: 730) (UPDATE NOTE: True vendor PN: 1550000-7) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02) Note: True vendor PN: 1550000-7										
32-10-00-9605	Main Landing Gear Actuator Assembly						RE		Airworthiness Limitations Inspection Time Limits	≈16-Jan-2166
32 A/F	Right	0			Mos	29-Oct-2015				
9912537-6	New	0			Hrs	0				
1936		0			Ldg	0	70,200		70,200	67,624 Ldg
(ZONE: 720) (UPDATE NOTE: True vendor PN: 1550000-8) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02) Note: True vendor PN: 1550000-8										
32-20-00-2200	Nose Landing Gear Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈09-Oct-2026
32 A/F	5-12-08				Mos	17-Dec-2021				
					Hrs	2295:34	2,400	-/+25	(4695:34)	1379:27 Hrs (+25)
					Ldg	1,748				
(ZONE: 710) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 25-11-01-2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES -5002 THRU -5555 INCORPORATING560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019,CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560 XL MM Section 5-10-02)										

OK-ECR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-ECR,SN 560-6198

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
32-20-00-9600	Nose Landing Gear Assembly						RE		Airworthiness Limitations Inspection Time Limits	≈30-Dec-2088
 32 A/F		0			Mos	29-Oct-2015				
6642635-1	New	0			Hrs	0				
24994145		0			Ldg	0	33,300		33,300	30,724 Ldg
(ZONE: 710) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
32-20-00-9601	Nose Landing Gear Actuator						RE		Airworthiness Limitations Inspection Time Limits	≈30-Dec-2088
 32 A/F		0			Mos	29-Oct-2015				
9912491-6	New	0			Hrs	0				
1092		0			Ldg	0	33,300		33,300	30,724 Ldg
(ZONE: 710) (UPDATE NOTE: True vendor PN: 1549300-11) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02) Note: True vendor PN: 1549300-11										
32-30-09-7800	Emergency Gear Extension/Brake Pneumatic Storage Bottle (Hydrostatic Test) Restoration						RE		Regulatory Inspections/Time Limits	
 32 A/F					Mos	06-Apr-2023	36		[31-Mar-2026]	1.4 Years
40005347-3					Hrs					
7432					Ldg					
Hydrostatic Tested Date 06-Apr-2023 (SOURCE: 560 XL MM Section 5-13-00) Note: Regulation: US DOT CFR 49 Part 180.209 Requirements for Re-qualification of Specification Cylinders. NOTE: The pneumatic storage bottle is manufactured under U.S. DOT 3HT										
32-40-00-2200	Main Landing Gear Brakes Detailed Inspection, Landing Gear Axle General Visual Inspection, and Functional (Wear Pin) Check						RE (A/R)		05-10-01, 05-10-02, Category 6	
 32 A/F	Left				Mos	22-Feb-2022				
2-1601-1					Hrs	2400:50				
D0062					Ldg	1,827				
MRBR Task:32-40-00-203, MRBR Task:32-41-00-201, MRBR Task:32-42-00-201, MRBR Task:32-41-00-701, MRBR Task:32-42-00-701, MRBR Task:32-40-00-202, MRBR Task:32-40-00-206 (ZONE: 720) (SOURCE: 560XL MM) Note: Every Wheel Removal										
32-40-00-2200	Main Landing Gear Brakes Detailed Inspection, Landing Gear Axle General Visual Inspection, and Functional (Wear Pin) Check						RE (A/R)		05-10-01, 05-10-02, Category 6	
 32 A/F	Right				Mos	07-Nov-2018				
2-1601-1					Hrs	1230:36				
2308P					Ldg	1,009				
MRBR Task:32-40-00-203, MRBR Task:32-41-00-201, MRBR Task:32-42-00-201, MRBR Task:32-41-00-701, MRBR Task:32-42-00-701, MRBR Task:32-40-00-202, MRBR Task:32-40-00-206 (ZONE: 730) (SOURCE: 560XL MM) Note: Every Wheel Removal										
32-40-00-2201	Main Landing Gear Brake Master Cylinder Detailed Inspection (Airplanes -5001 thru -5500)						RE (N/A)		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
 32 A/F	Left Inboard				Mos					
Unknown					Hrs					
Unknown					Ldg					
(ZONE: 235) (SOURCE: 560 XL MM Section 5-10-02)										
32-40-00-2201	Main Landing Gear Brake Master Cylinder Detailed Inspection (Airplanes -5001 thru -5500)						RE (N/A)		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
 32 A/F	Left Outboard				Mos					
Unknown					Hrs					
Unknown					Ldg					
(ZONE: 235) (SOURCE: 560 XL MM Section 5-10-02)										
32-40-00-2201	Main Landing Gear Brake Master Cylinder Detailed Inspection (Airplanes -5001 thru -5500)						RE (N/A)		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
 32 A/F	Right Inboard				Mos					
Unknown					Hrs					
Unknown					Ldg					
(ZONE: 235) (SOURCE: 560 XL MM Section 5-10-02)										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
32-40-00-2201	Main Landing Gear Brake Master Cylinder Detailed Inspection (Airplanes -5001 thru -5500)						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 32 A/F	Right Outboard									Mos
Unknown										Hrs
Unknown										Ldg
(ZONE: 235) (SOURCE: 560 XL MM Section 5-10-02)										
32-40-00-2202	Emergency Brake System Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈09-Oct-2026
 32 A/F	5-12-08									Mos
						17-Dec-2021				Hrs
						2295:34	2,400	-/+25	(4695:34)	1379:27 Hrs (+25)
						1,748				Ldg
(ZONE: 211, 235, 720, 730) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 25-11-01-2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES - 5002 THRU -5555 INCORPORATINGSB560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019,CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560 XL MM Section 5-10-02)										
32-40-00-2203	Nose Landing Gear Axle General Visual Inspection						RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 32 A/F										Mos
										Hrs
	MRBR Task:32-40-00-202, MRBR Task:32-40-00-206 (ZONE: 710) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00) Note: Every Wheel Removal									Ldg
32-40-00-7100	Emergency Brake System Operational Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈09-Oct-2026
 32 A/F	5-12-08									Mos
						17-Dec-2021				Hrs
						2295:34	2,400	-/+25	(4695:34)	1379:27 Hrs (+25)
						1,748				Ldg
(ZONE: 211, 235) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 25-11-01-2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES -5002 THRU - 5555 INCORPORATINGSB560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019,CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560 XL MM Section 5-10-02)										
32-40-00-9600	Brake System Filters Discard (Airplanes -5001 thru -5500)						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 32 A/F										Mos
										Hrs
	(ZONE: 211) (SOURCE: 560 XL MM Section 5-10-02)									Ldg

Task No		Description								Categories	Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining		
32-40-00-9601		Power Brake and Antiskid Filter Element Discard (Airplanes -5501 and On)							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈09-Oct-2026	
	32 A/F	5-12-08					Mos	17-Dec-2021					
							Hrs	2295:34		2,400	-/+25	(4695:34)	1379:27 Hrs (+25)
							Ldg	1,748					
			(ZONE: 165) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 25-11-01-2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES -5002 THRU -5555 INCORPORATINGSB560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019,CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560 XL MM Section 5-10-02)										
32-41-00-2101		Optional Nose Wheel Spin Up General Visual Inspection							RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	32 A/F	(ZONE: 710) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00) Note: Every Wheel Removal					Mos	20-Jun-2019					
							Hrs						
							Ldg						
32-41-00-2200		Left Main Landing Gear Wheel and Tire Detailed Inspection							REMSG-3 Structures Inspection Tasks				
	32 A/F	(ZONE: 720) (UPDATE NOTE: TC Acomplished by L/H MLG Wheel Assy Reaplacement i.a.w. Main Landing Gear Wheel Removal/Installation (REF: 32-41-02 / 3. / A. / (10) and (11))) (SOURCE: 560 XL MM Section 5-10-01, 5-10-03, 5-12-00) Note: Every Wheel Removal not to Exceed 24 Months					Mos	10-Jan-2024		24	-/+1m	31-Jan-2026	1.2 Years (+28 Days)
							Hrs	3127:37					
							Ldg	2,420					
32-41-00-2200		Right Main Landing Gear Wheel and Tire Detailed Inspection							REMSG-3 Structures Inspection Tasks				
	32 A/F	(ZONE: 730) (UPDATE NOTE: TC Acomplished by R/H MLG Wheel Assy Reaplacement i.a.w. Main Landing Gear Wheel Removal/Installation (REF: 32-41-02 / 3. / A. / (10) and (11))) (SOURCE: 560 XL MM Section 5-10-01, 5-10-03, 5-12-00) Note: Every Wheel Removal not to Exceed 24 Months					Mos	11-May-2023		24	-/+1m	31-May-2025	6.6 Months (+30 Days)
							Hrs	3006:19					
							Ldg	2,328					
32-41-00-2800		Nose Landing Gear Wheel (Eddy Current) Special Detailed Inspection							RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	32 A/F 9914069-2 9590	(ZONE: 710) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) Note: Tracked by Tire Changes NOTE:Per Supplier Recommendation. Reference BF Goodrich 32-47-42 Component Maintenance Manual					Mos	27-Jun-2023					
							Hrs	3038:01					
							Ldg	2,352					
32-41-00-2801		Main Landing Gear Wheel (Eddy Current) Special Detailed Inspection							RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	32 A/F 3-1571-6 4933	Left (ZONE: 720) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) Note: Tracked by Tire Changes NOTE:Per Supplier Recommendation. Reference BF Goodrich 32-45-48 Component Maintenance Manual					Mos	10-Jan-2024					
							Hrs	3127:37					
							Ldg	2,420					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
32-41-00-2801	Main Landing Gear Wheel (Eddy Current) Special Detailed Inspection						RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 32 A/F	Right				Mos	11-May-2023				
3-1571-6					Hrs	3006:19				
4878					Ldg	2,328				
(ZONE: 730) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
Note: Tracked by Tire Changes NOTE:Per Supplier Recommendation, Reference BF Goodrich 32-45-48 Component Maintenance Manual										
32-41-00-7200	Optional Nose Wheel Spin up Functional Check						RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 32 A/F					Mos	20-Jun-2019				
					Hrs					
					Ldg					
(SOURCE: 560 XL MM Section 5-10-02, 5-12-00)										
Note: Every Wheel Removal										
32-50-00-2200	Steering System Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 32 A/F	5-12-06				Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)	
					Hrs	3048:30				
					Ldg	2,362				
(ZONE: 710) (UPDATE NOTE: Steering Bellcrank Worn for Replacement refer to Order WO: 101046395) (SOURCE: 560 XL MM Section 5-10-02)										
Note: NOTE: It is recommended you do this task at the same time as Task 32-50-00-7200										
32-50-00-7200	Steering Cable System Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 32 A/F	5-12-06				Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)	
					Hrs	3048:30				
					Ldg	2,362				
(ZONE: 710, 241, 242) (SOURCE: 560 XL MM Section 5-10-02)										
Note: NOTE: It is recommended you do this task at the same time as Task 32-50-00-2200										
560XL-32-38	Landing Gear - Remove the Quick Disconnect from the Nose Landing Gear Torque Link						RE (-)	Recommended		
 32 A/F					Mos	13-Sep-2021				
Superseded					Hrs					
					Ldg					
560XL-32-38 Rev 01	Landing Gear - Remove the Quick Disconnect from the Nose Landing Gear Torque Link						T (-)	Optional		
 32 A/F					Mos					
Eff: 07-Dec-2010					Hrs					
					Ldg					
560XL-32-38 Rev 02	Landing Gear - Remove the Quick Disconnect from the Nose Landing Gear Torque Link						T (A/R)	Optional		
 32 A/F					Mos					
Eff: 15-Feb-2019					Hrs					
					Ldg					
560XL-32-41	Transmittal of Goodrich Service Bulletin 3-1571-32-7						RE (-)	Recommended		
 32 A/F					Mos	09-Sep-2021				
Not Applicable	as per S/N				Hrs	2218:31				
					Ldg	1,685				
560XL-32-41 Rev 01	Transmittal of Goodrich Service Bulletin 3-1571-32-7						RE (-)	Mandatory		
 32 A/F					Mos	09-Sep-2021				
Eff: 05-May-2011 Not Applicable	as per S/N				Hrs	2218:31				
					Ldg	1,685				
Note: This service bulletin must be accomplished at the next tire change or one year from the date of receipt, whichever occurs first.										
560XL-32-42	Landing Gear - Stainless Steel Hydraulic Tube Replacement						RE (-)	Recommended		
 32 A/F					Mos	13-Sep-2021				
Superseded	rev 2				Hrs					
					Ldg					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
560XL-32-42 Rev 01	 32 A/F Superseded	Landing Gear - Stainless Steel Hydraulic Tube Replacement						RE (-)		Recommended	
						Mos	13-Sep-2021				
						Hrs					
		rev 2				Ldg					
560XL-32-42 Rev 02	 32 A/F Eff: 11-Nov-2014	Landing Gear - Stainless Steel Hydraulic Tube Replacement						RE (-)		Optional	
						Mos					
						Hrs					
						Ldg					
CIL-32-01	 32 A/F Eff: 07-Feb-2013	Improved Nose Wheel Grease Seal						RE (-)		Informational	
						Mos					
						Hrs					
		Note: With 3-1418OPT2 (9914069-2), 3-1418OPT3 (9914069-3), or 3-1418OPT4 (9914069-4) Nose Wheels installed.				Ldg					
CIL-32-04	 32 A/F Eff: 25-Sep-2014	Landing Gear - Wireless Tire Pressure Monitoring System Installation						T (A/R)		Informational	
						Mos					
						Hrs					
						Ldg					
CIL-32-06	 32 A/F Eff: 09-Mar-2020	Landing Gear - Wireless Tire Pressure Sensor Fill Valve Torque Verification						T (A/R)		Informational	
						Mos					
						Hrs					
						Ldg					
G-004-09-83	 32 A/F Eff: 12-Dec-1983 Superseded (ISSUING AUTHORITY: EASA)	SUPERSEDED BY CAA UK AD 017-11-83						RE (-)		Mandatory	
						Mos	09-Sep-2021				
						Hrs	2218:31				
						Ldg	1,685				
G-005-09-83	 32 A/F Eff: 12-Dec-1983 Superseded (ISSUING AUTHORITY: EASA)	SUPERSEDED BY CAA UK AD 016-11-83						RE (-)		Mandatory	
						Mos	09-Sep-2021				
						Hrs	2218:31				
						Ldg	1,685				
G-013-08-90	 32 A/F Eff: 20-Jan-1993 Superseded (ISSUING AUTHORITY: EASA)	SUPERSEDED BY CAA UK AD 009-02-93						RE (-)		Mandatory	
						Mos	09-Sep-2021				
						Hrs	2218:31				
						Ldg	1,685				
SB560XL-32-44	 32 A/F Eff: 07-Jun-2017	Landing Gear - Nose Landing Gear Bearing Grease Fitting Installation						T (-)		Optional	
						Mos					
						Hrs					
						Ldg					
SB560XL-32-44 R1	 32 A/F Eff: 13-Nov-2018	Landing Gear - Nose Landing Gear Bearing Grease Fitting Installation						T (-)		Optional	
						Mos					
						Hrs					
						Ldg					
SB560XL-32-44 R2	 32 A/F Eff: 25-Nov-2019	Landing Gear - Nose Landing Gear Bearing Grease Fitting Installation						T (A/R)		Optional, Service Bulletin	
						Mos					
						Hrs					
		Note: EFFECTIVITY: The equivalent of this service bulletin has been incorporated on production airplanes -6262 and On				Ldg					
SB560XL-32-47	 32 A/F Eff: 11-Sep-2023	Landing Gear - Main Landing Gear Brake Hydraulic Line Fitting Replacement						T (A/R)		Optional	
						Mos					
						Hrs					
						Ldq					

OK-ECR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-ECR,SN 560-6198

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-32-06	Landing Gear - Power Brake System Operation						T (A/R)		Informational	
 32 A/F Eff: 08-Aug-2000						Mos				
						Hrs				
						Ldg				
SL560XL-32-08	Landing Gear - Transmittal Of BFGoodrich Service Letter SL1866 Landing Gear Main And Nose Wheels Approved Cleaners For Aluminum Wheel Assembly						T (A/R)		Informational	
 32 A/F Eff: 30-Oct-2000						Mos				
						Hrs				
						Ldg				
SL560XL-32-09	Landing Gear - Transmittal Of BFGoodrich Service Letter SL1878, Effect Of Disinfectant On Wheel And Brake Assemblies						T (A/R)		Informational	
 32 A/F Eff: 08-May-2001						Mos				
						Hrs				
						Ldg				
SL560XL-32-22	Landing Gear Component Placard Installation						RE (-)		Optional	
 32 A/F Eff: 10-Aug-2009						Mos				
						Hrs				
						Ldg				
SL560XL-32-22 Rev 1	Landing Gear Component Placard Installation						RE (-)		Optional	
 32 A/F Eff: 03-May-2019						Mos				
						Hrs				
						Ldg				
SL560XL-32-24	Revision 1 Cancels Transmittal of Curtiss Wright SB 049801-32-01, Landing Gear Control - Alternate LED Lighting Bulb						RE (-)		Optional	
 32 A/F						Mos				
						Hrs				
						Ldg				
SL560XL-32-24 Rev 01	Revision 1 Cancels Transmittal of Curtiss Wright SB 049801-32-01, Landing Gear Control - Alternate LED Lighting Bulb						RE (-)		Informational	
 32 A/F Eff: 01-May-2012						Mos				
						Hrs				
						Ldg				
SL560XL-32-25	Main Wheel Assembly, P/N 3-1571 Series - Model 560XL/XLS Series Aircraft - Improved Inspection Procedure						T (A/R)		Informational	
 32 A/F Eff: 29-Jun-2010						Mos				
						Hrs				
						Ldg				
SL560XL-32-27	Landing Gear - Hydraulic Loading Valve Wire Bundle Inspection						RE (-)		Optional	
 32 A/F Not Applicable	as per S/N					Mos	09-Sep-2021			
						Hrs	2218:31			
						Ldg	1,685			
SL560XL-32-27 Rev 01	Landing Gear - Hydraulic Loading Valve Wire Bundle Inspection						RE (-)		Mandatory	
 32 A/F Eff: 15-Jan-2015 Not Applicable	as per S/N					Mos	09-Sep-2021			
						Hrs	2218:31			
						Ldg	1,685			
SL560XL-32-27 Rev 02	Landing Gear - Hydraulic Loading Valve Wire Bundle Inspection						RE (-)		Mandatory	
 32 A/F Eff: 12-Jun-2019 Not Applicable (AVG MAN HRS: 1.5)	as per S/N					Mos	09-Sep-2021			
						Hrs	2218:31			
						Ldg	1,685			
SL560XL-32-29	Main Landing Gear Actuator Lock Tab Verification						RE (-)		Recommended	
 32 A/F Eff: 22-Dec-2016 Complied With (AVG MAN HRS: 5)						Mos	07-Nov-2018			
						Hrs	1230:36			
						Ldg	1,009			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SL560XL-32-30		Landing Gear - Brake Hydraulic Reservoir Sight Glass Fastener Torque Inspection								RE (-)	Recommended
	32 A/F										
	Eff: 11-Sep-2023										
	(AVG MAN HRS: 0.5)										
SL560XL-32-32		Landing Gear - Main Landing Gear Components Repair								T (A/R)	Informational
	32 A/F										
	Eff: 20-May-2024										
▼ 33 - LIGHTS											
		5 Vdc UN002 Dimmer Power Supply								RE (O/C)	
	33 A/F	Left									
	273-1	New									
	445FGD										
		5 Vdc UN004 Dimmer Power Supply								RE (O/C)	
	33 A/F	Center									
	273-1	New									
	44RFLO										
		5 Vdc UN006 Dimmer Power Supply								RE (O/C)	
	33 A/F	Right									
	Unknown										
	Unknown										
		Cabin & Entry Light Panel Switch								RE (O/C)	
	33 A/F										
	Unknown										
	Unknown										
		Electroluminescent Panel Inverter								RE (O/C)	
	33 A/F										
	EM2044-1	New									
	6408A										
		Emergency Lighting Battery Pack (UC019)								RE (O/C)	
	33 A/F	Fwd									
	9913-1	Overhauled									
	1993										
		Emergency Lighting Battery Pack (UC020)								RE (O/C)	
	33 A/F	Aft									
	9913-1										
	2925										
		Empennage Light Assy								RE (O/C)	
	33 A/F										
	01-0790044-37	New									
	NSN										
		Entertainment Switch Panel								RE (O/C)	
	33 A/F	No.6									
	Unknown										
	Unknown										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	33 A/F Unknown Unknown	Glareshield Inverter						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
	33 A/F Unknown Unknown	Light Power Supply Left No.1						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
	33 A/F Unknown Unknown	Light Power Supply Left No.2						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
	33 A/F Unknown Unknown	Light Power Supply Left No.3						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
	33 A/F Unknown Unknown	Light Power Supply Left No.4						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
	33 A/F Unknown Unknown	Light Power Supply Left No.5						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
	33 A/F Unknown Unknown	Light Power Supply Left No.6						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
	33 A/F Unknown Unknown	Light Power Supply Left No.7						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
	33 A/F Unknown Unknown	Light Power Supply Left No.8						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
	33 A/F Unknown Unknown	Light Power Supply Left No.9						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			
	33 A/F Unknown Unknown	Light Power Supply Right No.1						RE (O/C)			
							Mos	29-Oct-2015			
							Hrs	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	33 A/F Unknown Unknown	Light Power Supply Right No.10					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Right No.2					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Right No.3					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Right No.4					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Right No.5					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Right No.6					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Right No.7					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Right No.8					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Right No.9					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F 01-0770966-00 05355A	Navigation Light Tail New	0				Mos	29-Oct-2015		RE (O/C)	
			0				Hrs	0			
			0				Ldg	0			
	33 A/F Unknown Unknown	Overwing Emergency Light Aft					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
Pulse Lite Control										
33 A/F	2401C	New	0			Mos	29-Oct-2015		RE (O/C)	
	TR02347		0			Hrs	0			
			0			Ldg	0			
Strobe Power Supply										
33 A/F	01-0771120-00	Left	0			Mos	29-Oct-2015		RE (O/C)	
	01000	New	0			Hrs	0			
			0			Ldg	0			
Strobe Power Supply										
33 A/F	01-0771120-00	Right	0			Mos	29-Oct-2015		RE (O/C)	
	01001	New	0			Hrs	0			
			0			Ldg	0			
Tail Light Assy										
33 A/F	Unknown					Mos	29-Oct-2015		RE (O/C)	
	Unknown					Hrs	0			
						Ldg	0			
Wing Tip Navigation FL001 Light										
33 A/F	Unknown	Left				Mos	29-Oct-2015		RE (O/C)	
	Unknown					Hrs	0			
						Ldg	0			
Wing Tip Navigation FR001 Light										
33 A/F	Unknown	Right				Mos	29-Oct-2015		RE (O/C)	
	Unknown					Hrs	0			
						Ldg	0			
2001-14-09 Wiring of the Landing Light Switch and theJ-Box Fairing Light Relays										
33 A/F	Eff: 26-Jul-2001 Not Applicable	AD2001-14-09: INSPECTION FOR CHAFING, DISCOLORATION, OR DAMAGED WIRING DOES NOT APPLY DUE TO AIRCRAFT SERIAL NUMBER APPLICABILITY RANGE.				Mos	28-Oct-2015		RE (-)	Mandatory (Appliance AD)
	(ISSUING AUTHORITY: FAA)					Hrs	5			
						Ldg	3			
33-40-00-7200 Tail Light Assembly (NAV-LED 72 segment) Functional Check										
33 A/F	5-12-03					Mos	09-Oct-2023	24	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	11.7 Months (+30 Days)
	(ZONE: 340) (SOURCE: 560 XL MM Section 5-10-02)					Hrs	3048:30			
	Note: -5001 and On Incorporating NAV-LED 72 Segment Tail Light Assembly					Ldg	2,362			
33-50-00-7100 Emergency Lighting System Operational Check										
33 A/F	5-12-03					Mos	09-Oct-2023	24	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	11.7 Months (+30 Days)
	(ZONE: 166, 241, 251, 261, 262) (UPDATE NOTE: Found RH AFT Overwing Emergency LED Light Assy INOP, REF ORDER: 101061628)					Hrs	3048:30			
	(SOURCE: 560 XL MM Section 5-10-02)					Ldg	2,362			
33-50-00-7200 Emergency Battery Pack (Capacity Check) Functional Check										
33 A/F	Aft5-12-01					Mos	31-Oct-2024	12	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	11.7 Months (+30 Days)
	9913-1					Hrs	3308:54			
	2925					Ldg	2,570			
	MRBR Task:33-50-00-701 (ZONE: 261, 262) (SOURCE: 560XL MM Section 5-10-01, 5-10-02, 5-12-01)									

Task No	Description								Categories	Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
33-50-00-7200		Emergency Battery Pack (Capacity Check) Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	33 A/F	Fwd5-12-01					Mos	31-Oct-2024	12	-/+1m	(31-Oct-2025) 11.7 Months (+30 Days)	
	9913-1						Hrs	3308:54				
	1993						Ldg	2,570				
	MRBR Task:33-50-00-701 (ZONE: 251, 252) (SOURCE: 560XL MM Section 5-10-01, 5-10-02, 5-12-01)											
33-50-00-9600		Emergency Lighting Battery Pack Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS, MSG-3 Inspection Documents		
	33 A/F	Aft					Mos	17-Dec-2021	48	-/+1m	31-Dec-2025 1.1 Years (+31 Days)	
	9913-1						Hrs	2295:34				
	2925						Ldg	1,748				
	Restored Date 17-Dec-2021											
MRBR Task:33-50-00-902 (SOURCE: 560 XL MM Section 5-10-01, 5-12-00)												
Note: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored emergency lighting battery pack and/or refer to Avtech Emergency Battery Pack Component Maintenance Manual, 33-50-01.												
33-50-00-9600		Emergency Lighting Battery Pack Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS, MSG-3 Inspection Documents		
	33 A/F	Fwd					Mos	10-Jan-2024	48	-/+1m	30-Sep-2027 2.9 Years (+30 Days)	
	9913-1						Hrs	3127:37				
	1993						Ldg	2,420				
	Restored Date 15-Sep-2023											
MRBR Task:33-50-00-902 (SOURCE: 560 XL MM Section 5-10-01, 5-12-00)												
Note: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored emergency lighting battery pack and/or refer to Avtech Emergency Battery Pack Component Maintenance Manual, 33-50-01.												
SL560XL-33-01		Lights - DeVore Logo Light Installation							T (A/R)	Informational		
	33 A/F						Mos					
	Eff: 15-Sep-1999						Hrs					
								Ldg				
▼ 34 - NAVIGATION												
		Standby Air Data Computer							RE (-)			
	34 A/F	Fwd					Mos					
	9200-30000-080	New					Hrs					
	Unknown						Ldg					
		ADF Antenna							RE (O/C)			
	34 A/F	No.2		0			Mos	29-Oct-2015				
	622-7383-001	New		0			Hrs	0				
	44PMMM			0			Ldg	0				
		AFIS Configuration Module							RE (O/C)			
	34 A/F						Mos	29-Oct-2015				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		AFIS Data Management Unit							RE (O/C)			
	34 A/F						Mos	29-Oct-2015				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No	Description	Categories	Time							
SEQ	PN/SN	MOC Note or Component Condition	TSNI TSOI TSRI TSI CW REQ TOL DUE Remaining							
	34 A/F Unknown Unknown	AHRS 1 Battery Pack No.1							RE (O/C)	
				Mos	29-Oct-2015					
				Hrs	0					
				Ldg	0					
	34 A/F 822-1110-002 2B4KK	AHRS Computer Left		1	Mos	09-Aug-2016				
				Hrs	224:43					
				Ldg	223					
				Hrs (APU)	125					
				Start (APU)	148					
	34 A/F 822-1110-002 44XXMM	AHRS Computer Right		7	Mos	22-May-2016				
				141	Hrs	141:42				
				Ldg	145					
	34 A/F 822-1109-126 41HF6T	Air Data Computer No.1 New		0	Mos	29-Oct-2015				
				0	Hrs	0				
				0	Ldg	0				
	34 A/F 822-1109-126 46XY60	Air Data Computer No.2 Overhauled		6	Mos	06-May-2022				
				0	Hrs	2543:33				
				0	Ldg	1,937				
	34 A/F 622-9210-501 2GCYB	ATC Transponder No.1			Mos	24-Nov-2019				
					Hrs	1700:03				
					Ldg	1,331				
	34 A/F 622-9210-501 4KXVX	ATC Transponder No.2			Mos	24-Nov-2019				
					Hrs	1700:03				
					Ldg	1,331				
	34 A/F Unknown Unknown	Comm Unit Rack No.1			Mos	29-Oct-2015				
					Hrs	0				
					Ldg	0				
	34 A/F Unknown Unknown	Comm Unit Rack No.2			Mos	29-Oct-2015				
					Hrs	0				
					Ldg	0				
	34 A/F 822-1363-002 45CM5C	Configuration Strapping Unit Switch No.1 New		0	Mos	29-Oct-2015				
				0	Hrs	0				
				0	Ldg	0				

Task No	Description										Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
	34 A/F 822-1363-002 45CM59	Configuration Strapping Unit Switch						RE (O/C)				
		No.2	0			Mos	29-Oct-2015					
		New	0			Hrs	0					
			0			Ldg	0					
	34 A/F 822-2388-001 44R438	Control Display Panel						RE (O/C)				
		No.1	0			Mos	29-Oct-2015					
		New	0			Hrs	0					
			0			Ldg	0					
	34 A/F 822-2388-001 44R440	Control Display Panel						RE (O/C)				
		No.2	0			Mos	29-Oct-2015					
		New	0			Hrs	0					
			0			Ldg	0					
	34 A/F Unknown Unknown	Cooling Fan						RE (O/C)				
						Mos	29-Oct-2015					
						Hrs	0					
						Ldg	0					
	34 A/F 822-2389-001 44R3T1	Cursor Control Panel						RE (O/C)				
		No.1	0			Mos	29-Oct-2015					
		New	0			Hrs	0					
			0			Ldg	0					
	34 A/F 822-2389-001 44R42H	Cursor Control Panel						RE (O/C)				
		No.2	0			Mos	29-Oct-2015					
		New	0			Hrs	0					
			0			Ldg	0					
	34 A/F 822-1538-104 41GMD8	Data Concentrator Unit						RE (O/C)				
			0			Mos	29-Oct-2015					
			0			Hrs	0					
			0			Ldg	0					
	34 A/F Unknown Unknown	Data Link Radio Antenna						RE (O/C)				
						Mos	29-Oct-2015					
						Hrs	0					
						Ldg	0					
	34 A/F 501-1803-222 6725	Detach Configuration Module						RE (O/C)				
			0			Mos	29-Oct-2015					
			0			Hrs	0					
			0			Ldg	0					
	34 A/F Unknown Unknown	Differential Pressure Switch						RE (O/C)				
						Mos	29-Oct-2015					
						Hrs	0					
						Ldg	0					
	34 A/F L10-611-14 7592	Distance Measuring Equipment (DME) Antenna						RE (O/C)				
		No.1	0			Mos	29-Oct-2015					
		New	0			Hrs	0					
			0			Ldg	0					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
✖	34 A/F L10-611-14 7590	Distance Measuring Equipment (DME) Antenna No.2 New	0			Mos	29-Oct-2015	RE (O/C)			
			0			Hrs	0				
			0			Ldg	0				
✖	34 A/F 822-1466-001 44V4V0	DME Transceiver No.1				Mos	24-Nov-2019	RE (O/C)			
						Hrs	1700:03				
						Ldg	1,331				
✖	34 A/F 822-1466-001 44V4TC	DME Transceiver No.2	49			Mos	24-Nov-2019	RE (O/C)			
			1700:03			Hrs	1700:03				
			1,331			Ldg	1,331				
✖	34 A/F 965-0976-040-228-228 EMK5-37436	Egpws Computer New	0			Mos	29-Oct-2015	RE (O/C)			
			0			Hrs	0				
			0			Ldg	0				
✖	34 A/F 501-1879-0102 1618B	Elec Horiz Sit Indicator New	0			Mos	29-Oct-2015	RE (O/C)			
			0			Hrs	0				
			0			Ldg	0				
✖	34 A/F 822-1543-201 4FKDHP	External Compensation FSU Unit New	0			Mos	29-Oct-2015	RE (O/C)			
			0			Hrs	0				
			0			Ldg	0				
✖	34 A/F 822-1200-998 44YOHD	External Compensation Unit No.1 New	0			Mos	29-Oct-2015	RE (O/C)			
			0			Hrs	0				
			0			Ldg	0				
✖	34 A/F 822-1200-003 44XXPF	External Compensation Unit No.2 New	0			Mos	29-Oct-2015	RE (O/C)			
			0			Hrs	0				
			0			Ldg	0				
✖	34 A/F Unknown Unknown	File Server Unit				Mos	09-Nov-2020	RE (O/C)			
						Hrs	2029:01				
						Ldg	1,561				
✖	34 A/F 822-1108-143 45CLPH	Flight Guidance Computer No.1	40			Mos	27-Feb-2019	RE (O/C)			
			1322:53			Hrs	1322:53				
			1,083			Ldg	1,083				
✖	34 A/F 822-1108-143 472TN5	Flight Guidance Computer No.2	40			Mos	28-Feb-2019	RE (O/C)			
			1322:53			Hrs	1322:53				
			1,083			Ldg	1,083				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
Flight Guidance Panel										
34 A/F	822-1107-116					Mos	28-Feb-2019		RE (O/C)	
44R53C						Hrs	1322:53			
						Ldg	1,083			
Flux Detector										
34 A/F	822-1193-001	Left	0			Mos	29-Oct-2015		RE (O/C)	
303851	New		0			Hrs	0			
			0			Ldg	0			
Flux Detector										
34 A/F	822-1193-001	Right	0			Mos	29-Oct-2015		RE (O/C)	
303852	New		0			Hrs	0			
			0			Ldg	0			
FMS Data Base Unit										
34 A/F	822-2215-602	New	0			Mos	29-Oct-2015		RE (O/C)	
45CKRK			0			Hrs	0			
			0			Ldg	0			
FMS-Control Display Unit										
34 A/F	822-0884-604	No.1	0			Mos	29-Oct-2015		RE (O/C)	
429RT0	New		0			Hrs	0			
			0			Ldg	0			
FMS-Control Display Unit										
34 A/F	822-0884-604	No.2	0			Mos	29-Oct-2015		RE (O/C)	
429P90	New		0			Hrs	0			
			0			Ldg	0			
Glideslope Antenna										
34 A/F	RGS10-48	New	0			Mos	29-Oct-2015		RE (O/C)	
18442			0			Hrs	0			
			0			Ldg	0			
Glideslope Antenna Coupler										
34 A/F	DGSC20-02	New	0			Mos	29-Oct-2015		RE (O/C)	
7664			0			Hrs	0			
			0			Ldg	0			
GPS Antenna										
34 A/F	CI401-460	No.1	0			Mos	29-Oct-2015		RE (O/C)	
496144	New		0			Hrs	0			
			0			Ldg	0			
GPS Antenna										
34 A/F	S67-1575-132	No.2	0			Mos	29-Oct-2015		RE (O/C)	
435-6002	New		0			Hrs	0			
			0			Ldg	0			
GPS Flight Management Computer										
34 A/F	822-0883-038	No.1				Mos	31-Aug-2021		RE (O/C)	
45CL2Y	Tested/Inspected					Hrs	2195:42			
						Ldg	1,673			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		GPS Flight Management Computer								RE (O/C)	
	34 A/F	No.2					Mos	31-Aug-2021			
	822-0883-038	Tested/Inspected					Hrs	2195:42			
	45CLL7						Ldg	1,673			
		GPS W/SBAS Receiver								RE (O/C)	
	34 A/F	No.1					Mos	29-Oct-2015			
	822-2189-010	New	0				Hrs	0			
	4PVNC		0				Ldg	0			
		GPS W/SBAS Receiver								RE (O/C)	
	34 A/F	No.2					Mos	29-Oct-2015			
	822-2189-010	New	0				Hrs	0			
	4PVN6		0				Ldg	0			
		IAPS Card Cage								RE (O/C)	
	34 A/F		0				Mos	29-Oct-2015			
	822-2191-001	New	0				Hrs	0			
	45CKYR		0				Ldg	0			
		IAPS Environmental Controller								RE (O/C)	
	34 A/F		0				Mos	29-Oct-2015			
	822-1167-001	New	0				Hrs	0			
	45CL00		0				Ldg	0			
		IAPS Power Supply								RE (O/C)	
	34 A/F	No.1	0				Mos	29-Oct-2015			
	822-1137-001	New	0				Hrs	0			
	45CMNN		0				Ldg	0			
		IAPS Power Supply								RE (O/C)	
	34 A/F	No.2					Mos	14-Oct-2021			
	822-1137-001	Overhauled	0				Hrs	2276:10			
	2D6KB		0				Ldg	1,740			
		Indicator - Standby HSI								RE (O/C)	
	34 A/F						Mos	29-Oct-2015			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
		Input/Output loc Concentrator								RE (O/C)	
	34 A/F	Aft	0				Mos	29-Oct-2015			
	822-2065-001	New	0				Hrs	0			
	45N4RL		0				Ldg	0			
		Input/Output loc Concentrator								RE (O/C)	
	34 A/F	Fwd	0				Mos	29-Oct-2015			
	822-2065-001	New	0				Hrs	0			
	45N54R		0				Ldg	0			
		Litef LCR-93 AHRS Tray								RE (O/C)	
	34 A/F	Left					Mos	29-Oct-2015			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	34 A/F Unknown Unknown	Litef LCR-93 AHRS Tray Right						RE (O/C)			
								Mos	29-Oct-2015		
								Hrs	0		
								Ldg	0		
	34 A/F 501-1826-03 3008	Magnetometer						RE (O/C)			
								Mos	31-Dec-2020		
								Hrs	2086:50		
								Ldg	1,594		
	34 A/F 822-1987-007 45CLF3	Maintenance Diagnostic Computer New	0					Mos	29-Oct-2015		
			0					Hrs	0		
			0					Ldg	0		
	34 A/F MB10-754 2038	Marker Beacon Antenna New	0					Mos	29-Oct-2015		
			0					Hrs	0		
			0					Ldg	0		
	34 A/F CI509 495587	Marker Beacon Antenna Coupler New	0					Mos	29-Oct-2015		
			0					Hrs	0		
			0					Ldg	0		
	34 A/F Unknown Unknown	MD302 Standby Attitude Module						RE (O/C)			
								Mos	29-Oct-2015		
								Hrs	0		
								Ldg	0		
	34 A/F 501-1741-2105 2300A	Meggitt Secondary Flight (EI016) Display						RE (O/C)			
			3					Mos	09-Aug-2016		
								Hrs	224:43		
								Ldg	223		
								Hrs (APU)	125		
								Start (APU)	148		
	34 A/F Unknown Unknown	Meggitt Static Converter						RE (O/C)			
								Mos	29-Oct-2015		
								Hrs	0		
								Ldg	0		
	34 A/F Unknown Unknown	MSU Calibration Prom Unit Left						RE (O/C)			
								Mos	29-Oct-2015		
								Hrs	0		
								Ldg	0		
	34 A/F Unknown Unknown	MSU Calibration Prom Unit Right						RE (O/C)			
								Mos	29-Oct-2015		
								Hrs	0		
								Ldg	0		

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Multi Function (MFD) Display								RE (O/C)	
	34 A/F	No.1	0			Mos	29-Oct-2015				
	822-2349-100	New	0			Hrs	0				
	46T6HH		0			Ldg	0				
		Multi Function (MFD) Display								RE (O/C)	
	34 A/F	No.2	0			Mos	29-Oct-2015				
	822-2349-100	New	0			Hrs	0				
	46T6H7		0			Ldg	0				
		Nav (VOR/ILS) Receiver								RE (O/C)	
	34 A/F	No.2	0			Mos	29-Oct-2015				
	822-1579-001	New	0			Hrs	0				
	4P98T		0			Ldg	0				
		Nav Antenna								RE (O/C)	
	34 A/F	Left	0			Mos	29-Oct-2015				
	DMN4-17-1N	New	0			Hrs	0				
	489469		0			Ldg	0				
		Nav Antenna								RE (O/C)	
	34 A/F	Right	0			Mos	29-Oct-2015				
	DMN4-17-1N	New	0			Hrs	0				
	489468		0			Ldg	0				
		Nav VOR/ILS/ADF Receiver								RE (O/C)	
	34 A/F	No.1		0		Mos	21-Jun-2019				
	822-1465-001	Overhauled		0		Hrs	1473:57				
	4KM1P			0		Ldg	1,181				
		Navigation Antenna Coupler								RE (O/C)	
	34 A/F		0			Mos	29-Oct-2015				
	CI-120-5	New	0			Hrs	0				
	489668		0			Ldg	0				
		Primary Flight (PFD) Display								RE (O/C)	
	34 A/F	No.1	0			Mos	29-Oct-2015				
	822-1993-100	New	0			Hrs	0				
	46T6FC		0			Ldg	0				
		Primary Flight (PFD) Display								RE (O/C)	
	34 A/F	No.2	0			Mos	29-Oct-2015				
	822-1993-100	New	0			Hrs	0				
	46T6F9		0			Ldg	0				
		Radar Controller								RE (O/C)	
	34 A/F					Mos	29-Oct-2015				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
		Radio Alt Receiver Antenna								RE (O/C)	
	34 A/F	Aft	0			Mos	29-Oct-2015				
	S67-2002	New	0			Hrs	0				
	543-78636		0			Ldg	0				

Task No	Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	34 A/F S67-2002 543-78637	Radio Alt Transmitter Antenna						RE (O/C)			
		Fwd	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	34 A/F 822-0615-206 4PT0K	Radio Altimeter ALT-55B Transceiver						RE (O/C)			
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
	34 A/F Unknown Unknown	Ram Air Temp Display						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	34 A/F 622-8439-004 4KCKK	Receiver/Ant/ Weather Radar Transceiver						RE (O/C)			
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
	34 A/F Unknown Unknown	Safe Flight AOA EI001 Indicator						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	34 A/F C12763-1 155520-09	Safe Flight AOA FI003 Indexer						RE (O/C)			
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
	34 A/F C13006-3EX 164735-04	Safe Flight Aoa UC009 Computer						RE (O/C)			
		New	0			Mos	17-Feb-2016				
			0			Hrs	76:09				
						Ldg	71				
						Hrs (APU)	41				
						Start (APU)	48				
	34 A/F C-12717-1 160994-07	Safe Flight Aoa UF004 Sensor						RE (O/C)			
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
	34 A/F 9200-30000-080 6791	Secondary ADU						RE (O/C)			
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Ldg	0				
	34 A/F Unknown Unknown	Speaker Amplifier						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
Standby Battery (AHRS)										
34 A/F	Unknown	Right				Mos	29-Oct-2015			
	Unknown					Hrs	0			
	Unknown					Ldg	0			
Standby Battery (Secondary Flight Display)										
34 A/F	100-2410-04	Left	3		0	Mos	31-Dec-2020			
	1075	Repaired			0	Hrs	2086:50			
					0	Ldg	1,594			
Standby Comm-Nav Control Head										
34 A/F	822-2177-001					Mos	20-Aug-2017			
	2LJON					Hrs	714:59			
						Ldg	630			
Standby Magnetic Compass										
34 A/F	Unknown					Mos	29-Oct-2015			
	Unknown					Hrs	0			
	Unknown					Ldg	0			
Taws,Waas Options Control Module										
34 A/F	822-1484-228	No.1	0			Mos	29-Oct-2015			
	45CM4C	New	0			Hrs	0			
			0			Ldg	0			
Taws,Waas Options Control Module										
34 A/F	822-1484-228	No.2	0			Mos	29-Oct-2015			
	45CM49	New	0			Hrs	0			
			0			Ldg	0			
TCAS Antenna										
34 A/F	622-8973-001	Bottom	0			Mos	17-Feb-2016			
	4589KM	New	0			Hrs	76:09			
						Ldg	71			
						Hrs (APU)	41			
						Start (APU)	48			
TCAS Processor										
34 A/F	822-1294-032					Mos	24-Nov-2019			
	4PV792					Hrs	1700:03			
						Ldg	1,331			
Top Transponder Diversity Antenna										
34 A/F	L10-611-14	No.1	0			Mos	29-Oct-2015			
	7437	New	0			Hrs	0			
			0			Ldg	0			
Top Transponder Diversity Antenna										
34 A/F	L10-611-14	No.2				Mos	24-Nov-2019			
	12833					Hrs	1700:03			
						Ldg	1,331			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
Transponder Bottom Antenna										
34 A/F	No.1		0			Mos	29-Oct-2015		RE (O/C)	
L10-611-14	New		0			Hrs	0			
7936						Ldg	0			
Transponder Bottom Antenna										
34 A/F	No.2		0			Mos	29-Oct-2015		RE (O/C)	
L10-611-14	New		0			Hrs	0			
7412			0			Ldg	0			
Upper TCAS Antenna										
34 A/F			0			Mos	29-Oct-2015		RE (O/C)	
622-8973-001	New		0			Hrs	0			
448C08			0			Ldg	0			
XM Weather Receiver Unit										
34 A/F			0			Mos	29-Oct-2015		RE (O/C)	
822-2031-002	New		0			Hrs	0			
4PV0R			0			Ldg	0			
2000-03-09 Residual Ice										
34 A/F						Mos	05-Jul-2021		RE (-)	Mandatory
Eff: 03-Apr-2000 Not	BY SERIAL NUMBER					Hrs				
Applicable						Ldg				
(ISSUING AUTHORITY: FAA)										
2006-22-05 Honeywell Primus II RNZ-850/-851 Integrated Navigation Unit (INU) - CANCELLED(SUPERCEDED BY AD 2010-07-02)										
34 A/F						Mos	28-Oct-2015		RE (-)	Mandatory (Appliance AD)
Eff: 01-Dec-2006 Not	AD2006-22-05: HONEYWELL PRIMUS LL RNZ-850/851 DOES NOT APPLY, AS PARTS LISTED IN TABLE 1 OF					Hrs	5			
Applicable	THIS AD, ARE NOT INSTALLED ON AIRCRAFT.					Ldg	3			
(ISSUING AUTHORITY: FAA)										
2007-23-13 Inspect - Adjustment Of Stall Warning System (Superseded by AD2008-26-04)										
34 A/F						Mos	28-Oct-2015		RE (-)	Mandatory
Eff: 30-Nov-2007 Superseded						Hrs	2218:31			
(ISSUING AUTHORITY: FAA)						Ldg	1,685			
2010-07-02 Integrated Navigation Units (INUs) - Honeywell Primus II RNZ-850()/-851() (This AD supersedes AD 2006-22-05)										
34 A/F						Mos	05-Jul-2021		RE (-)	Mandatory (Appliance AD)
Eff: 03-May-2010 Not	HONEYWELL PRIMUS RMZ-850()/-851() NOT INSTALLED, THIS AD SUPERSEDES FAA AD 2006-22-05.					Hrs				
Applicable						Ldg				
(ISSUING AUTHORITY: FAA)										
2012-26-15 Honeywell International Inc. - Air Data Pressure Transducers										
34 A/F						Mos	28-Oct-2015		RE (-)	Mandatory (Appliance AD)
Eff: 24-Jan-2013 Not	AD2012-26-15 HONEYWELL INTERNATIONAL INC.: AD APPLICABILITY OF THE HONEYWELL AIR DATA					Hrs	5			
Applicable	MODULES DOES NOT APPLY, AS PARTS ARE NOT INSTALLED ON AIRCRAFT					Ldg	3			
Brand A:9990-2012-26-15 (ISSUING AUTHORITY: FAA)										
2012-26-15 (G) (1) Remove Identify Out Of Spec Adc, Adm, Adahrs, And Dadc. (Rescinded By Faa 2012-26-15 R1) Affected Adc, Adm, Adahrs, Or Dadc										
34 A/F						Mos	28-Oct-2015		RE (-)	Mandatory
Not Applicable	AD2012-26-15 HONEYWELL INTERNATIONAL INC.: AD APPLICABILITY OF THE HONEYWELL AIR DATA					Hrs	5			
(ISSUING AUTHORITY: FAA)	MODULES DOES NOT APPLY, AS PARTS ARE NOT INSTALLED ON AIRCRAFT					Ldg	3			
2012-26-15 (G) (2) Perform Identify Out Of Spec Adc, Adm, Adahrs, And Dadc. (Rescinded By Faa 2012-26-15 R1) Pitot-Static Certification Test										
34 A/F						Mos	28-Oct-2015		RE (-)	
Not Applicable	AD2012-26-15 HONEYWELL INTERNATIONAL INC.: AD APPLICABILITY OF THE HONEYWELL AIR DATA					Hrs	5			
(ISSUING AUTHORITY: FAA)	MODULES DOES NOT APPLY, AS PARTS ARE NOT INSTALLED ON AIRCRAFT					Ldg	3			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2014-18-01	Rockwell Collins, Inc. - Navigation - inspect the airplane type code category strapping setting for a value of zero (0) or one (1) following Rockwell Collins, Inc. Service Information Letter 07-2, 523-0810069-101000, TDR-94() SIL 07-02.						RE (-)		Mandatory (Appliance AD)	
34 A/F					Mos	28-Oct-2015				
Eff: 14-Oct-2014 Not Applicable	AD 2014-18-01 IS NOT APPLICABLE DUE TO PAGES 6&7 SECTION (C) (3) (V) AND ECR 58032.				Hrs	5				
Brand A:9990-2014-18-01 (AVG MAN HRS: 4) (APX COST: 85) (ISSUING AUTHORITY: FAA)					Ldg	3				
2019-07-10	Attitude and Directional Data System						RE (-)		Mandatory (Appliance AD)	
34 A/F					Mos	13-Sep-2021				
Eff: 29-May-2019 Not Applicable	LCR-93 installed				Hrs	2222:03				
(ISSUING AUTHORITY: FAA)					Ldg	1,687				
2019-07-10 Paragraph (f)(1)	Attitude and Directional Data System - Remove the AHRS unit from service						RE (-)		Mandatory (Appliance AD)	
34 A/F					Mos	13-Sep-2021				
Eff: 29-May-2019 Not Applicable	LCR-93 installed				Hrs	2222:03				
(ISSUING AUTHORITY: FAA)					Ldg	1,687				
2019-07-10 Paragraph (f)(2)	Attitude and Directional Data System - Removal from service of P/N 145130-7100 terminates the requirements of AD 2010-26-09(75 FR 81424, December 28, 2010).						RE (-)		Mandatory (Appliance AD)	
34 A/F					Mos	13-Sep-2021				
Not Applicable	LCR-93 installed				Hrs	2222:03				
(ISSUING AUTHORITY: FAA)					Ldg	1,687				
2019-07-10 Paragraph (f)(3)	Attitude and Directional Data System - Do not install an AHRS unit P/N 145130-2000, 145130-2001, 145130-7000, 145130-7001, or 145130-7100 on any aircraft.						RE (-)		Mandatory (Appliance AD)	
34 A/F					Mos	13-Sep-2021				
Not Applicable	LCR-93 installed				Hrs	2222:03				
(ISSUING AUTHORITY: FAA)					Ldg	1,687				
2020-10-05	Flight Management Computing Hardware System - Rockwell Collins Pro Line 4 and Pro Line 21 Flight Management Systems						RE (-)		Mandatory (Appliance AD)	
34 A/F					Mos	29-Jul-2021				
Eff: 24-Jun-2020 Complied With					Hrs	2169:34				
(ISSUING AUTHORITY: FAA)					Ldg	1,654				
2021-23-12	Indicating/Recording System, Navigation - Radio Altimeter (Transport and Commuter Category Airplanes)						RE (-)		Mandatory (Appliance AD)	
34 A/F					Mos	04-Jan-2022				
Eff: 03-Jan-2022 Complied With	AFM updated				Hrs	2314:12				
(ISSUING AUTHORITY: FAA)					Ldg	1,762				
Note: COMPLIANCE: On or before January 4, 2022: Revise the Limitations Section of the existing AFM by incorporating the limitations specified in figure 1 to paragraph (g) of this AD. This may be done by inserting a copy of this AD into the existing AFM.										
2022-0024	Navigation - Flight Management Computer 2 / Navigation Modules - Operational Limitations / Amendment						RE (-)		Mandatory (Appliance AD)	
34 A/F					Mos	05-Feb-2022				
Eff: 18-Feb-2022 Not Applicable	affected P/N not installed				Hrs	2376:49				
(ISSUING AUTHORITY: EASA)					Ldg	1,808				
Note: APPLICABILITY: Thales Flight Management Computer (FMC) 2 Navigation Modules (NAVM), identified by Part Number C13084CA03. These FMC2 NAVM are known to be installed on, but not limited to, Dassault (formerly Bréguet) Br.1150 Atlantique 2 (ATL2) maritime patrol aeroplanes.										
2022-0024 Par. (1)	Navigation - Flight Management Computer 2 / Navigation Modules - Operational Limitations / Amendment: Operational Limitation(s)						RE (-)		Mandatory (Appliance AD)	
34 A/F					Days	05-Feb-2022				
Eff: 18-Feb-2022 Not Applicable	affected P/N not installed				Hrs	2376:49				
(ISSUING AUTHORITY: EASA)					Ldg	1,808				
Note: COMPLIANCE: Within 30 days after the effective date of this AD, amend the applicable AFM to refer to Thales FMS User Manual J68952AA-01, containing the limitations specified in Table 1 of this AD, inform all flight crew and, thereafter, operate the Flight Management System (FMS) in accordance with Table 2 of this AD.										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time Remaining
SEQ PN/SN	MOC Note or Component Condition								DUE	
2022-0024 Par. (2)	Navigation - Flight Management Computer 2 / Navigation Modules - Operational Limitations / Amendment: Use of Navigation Database						RE (-)		Mandatory (Appliance AD)	
34 A/F						Days	05-Feb-2022			
Eff: 18-Feb-2022 Not Applicable	affected P/N not installed					Hrs	2376:49			
(ISSUING AUTHORITY: EASA)						Ldg	1,808			
Note: COMPLIANCE: Within 30 days after the effective date of this AD, update the navigation database delivered to installers and operators to remove some navigation procedures as defined in the SIL, and, thereafter, use only a regularly updated navigation database where the above-mentioned procedures have been removed.										
2023-21-05	Navigation - Thales AVS France SAS Flight Management Computer Navigation Modules (FMC2 NAVM)						RE (N/A)		Mandatory (Appliance AD)	
34 A/F						Mos				
Not Applicable	Afected PN not installed.					Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				
2023-21-05 Par. (g)(1)	Navigation - Thales AVS France SAS Flight Management Computer Navigation Modules (FMC2 NAVM) - Revise the Limitations Section of the Existing Airplane Flight Manual						T (N/A)		Mandatory (Appliance AD)	
34 A/F						Mos				
Not Applicable	Afected PN not installed.					Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				
2023-21-05 Par. (g)(2)	Navigation - Thales AVS France SAS Flight Management Computer Navigation Modules (FMC2 NAVM) - Update the Database for Thales FMC2 NAVM - P/N C13084CA03						T (N/A)		Mandatory (Appliance AD)	
34 A/F						Mos				
Not Applicable	Afected PN not installed.					Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				
2024-0024	Navigation - Digital Air Data Computer - Replacement						T (N/A)		Mandatory (Appliance AD)	
34 A/F						Mos				
Not Applicable	Afected PN not installed. Installed ADC-3000 manufactured by Rockwell Collins					Hrs				
(ISSUING AUTHORITY: EASA)						Ldg				
34-00-CUS-001	Compass Swing						RE			
34 A/F						Mos	31-Oct-2024	12	31-Oct-2025	11.7 Months
						Hrs	3308:54			
						Ldg	2,570			
Note: CAA Requirement										
342507-0101	FMS Display Controller						RE (O/C)			
34 A/F	Left					Mos	29-Oct-2015			
Unknown						Hrs	0			
Unknown						Ldg	0			
342507-0102	FMS Display Controller						RE (O/C)			
34 A/F	Right					Mos	29-Oct-2015			
Unknown						Hrs	0			
Unknown						Ldg	0			
34-53-07-7200	Transponder System Functional Check (Airplanes -6001 and On)						RE		Regulatory Inspections/Time Limits	
34 A/F	No.1					Mos	09-Oct-2023	24	31-Oct-2025	11.7 Months
622-9210-501						Hrs	3048:30			
2GCYB						Ldg	2,362			
(SOURCE: 560 XL MM Section 5-13-00)										
Note: Regulation: 14 CFR Part 91.413. NOTE : This task also includes inspections necessary for RVSM Certified Airplanes										
34-53-07-7200	Transponder System Functional Check (Airplanes -6001 and On)						RE		Regulatory Inspections/Time Limits	
34 A/F	No.2					Mos	09-Oct-2023	24	31-Oct-2025	11.7 Months
622-9210-501						Hrs	3048:30			
4KXVX						Ldg	2,362			
(SOURCE: 560 XL MM Section 5-13-00)										
Note: Regulation: 14 CFR Part 91.413. NOTE : This task also includes inspections necessary for RVSM Certified Airplanes										

Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
34-90-10-7200		Pitot-Static System Functional Check (Airplanes -5001 thru -6000)							RE (N/A)	Regulatory Inspections/Time Limits	
	34 A/F	(SOURCE: 560 XL MM Section 5-13-00)					Mos				
							Hrs				
							Ldg				
34-90-12-7200		Functional Check Secondary (Standby) Adu Pitot-Static System Functional Check (Airplanes -6001 And On) (14 Cfr 91.411, 91.413 And Rvsm Certification)							RE		
	34 A/F	(UPDATE NOTE: Systems Found Operating Within Specified Tolerancies) Note: CAA Requirement					Mos	09-Oct-2023	24	31-Oct-2025	11.7 Months
							Hrs	3048:30			
							Ldg	2,362			
34-90-12-7200		Pitot-Static System Functional Check (Airplanes -6001 and On)							RE	Regulatory Inspections/Time Limits	
	34 A/F	(UPDATE NOTE: Systems Found Operating Within Specified Tolerancies) (SOURCE: 560 XL MM Section 5-13-00) Note: Regulation: 14 CFR 91.411, 91.413 and RVSM certification. NOTE : This task also includes inspections necessary for RVSM Certified Airplanes					Mos	09-Oct-2023	24	31-Oct-2025	11.7 Months
							Hrs	3048:30			
							Ldg	2,362			
34-90-12-7200		Rvsm Skin Waviness Inspection Pitot-Static System Functional Check (Airplanes -6001 And On) (14 Cfr 91.411, 91.413 And Rvsm Certification)							RE		
	34 A/F	(UPDATE NOTE: Systems Found Operating Within Specified Tolerancies) Note: CAA Requirement					Mos	09-Oct-2023	24	31-Oct-2025	11.7 Months
							Hrs	3048:30			
							Ldg	2,362			
560XL-34-27		Navigation - Universal Avionics Performance Database							RE (-)	Optional	
	34 A/F Eff: 01-May-2003 Not Applicable	as per P/N of GPS					Mos	13-Sep-2021			
							Hrs	2222:03			
							Ldg	1,687			
560XL-34-37		Enhanced Ground Proximity Warning System (EGPWS) Steep Approach Switch Installation							T (A/R)	Optional	
	34 A/F Eff: 29-Mar-2004						Mos				
							Hrs				
							Ldg				
560XL-34-40		Enhanced Ground Proximity Warning System (EGPWS) Runway Awareness Advisory System (RAAS) Upgrade							RE (-)	Recommended	
	34 A/F Superseded	rev 1					Mos	13-Sep-2021			
							Hrs				
							Ldg				
560XL-34-40 Rev 01		Enhanced Ground Proximity Warning System (EGPWS) Runway Awareness Advisory System (RAAS) Upgrade							T (A/R)	Optional	
	34 A/F Eff: 05-Mar-2008						Mos				
							Hrs				
							Ldg				
560XL-34-41		Honeywell Transponder Upgrade for Elementary Surveillance							RE (-)	Recommended	
	34 A/F Superseded	REV 2					Mos	13-Sep-2021			
							Hrs				
							Ldg				
560XL-34-41 Rev 01		Honeywell Transponder Upgrade for Elementary Surveillance							RE (-)	Recommended	
	34 A/F Superseded	REV 2					Mos	13-Sep-2021			
							Hrs				
							Ldg				
560XL-34-41 Rev 02		Honeywell Transponder Upgrade for Elementary Surveillance							T (A/R)	Optional	
	34 A/F Eff: 15-Jun-2006						Mos				
							Hrs				
							Ldg				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
560XL-34-43		Universal Avionics Performance Database Upgrade						RE (-)		Recommended	
	34 A/F					Mos	13-Sep-2021				
	Superseded	REV 1				Hrs					
						Ldg					
560XL-34-43 Rev 01		Universal Avionics Performance Database Upgrade						T (A/R)		Optional	
	34 A/F					Mos					
	Eff: 27-Jan-2006					Hrs					
						Ldg					
560XL-34-49		Runway Awareness Advisory System (RAAS) Audio Inhibit Switch Installation						RE (-)		Mandatory	
	34 A/F					Mos	09-Sep-2021				
	Not Applicable	as per S/N				Hrs	2218:31				
						Ldg	1,685				
560XL-34-49 Rev 01		Runway Awareness Advisory System (RAAS) Audio Inhibit Switch Installation						RE (-)		Optional	
	34 A/F					Mos	09-Sep-2021				
	Eff: 29-Nov-2007 Not Applicable	as per S/N				Hrs	2218:31				
						Ldg	1,685				
560XL-34-63		XLS+ FMS 4.0 (WAAS) Upgrade and V-Speeds Database Installation						RE (-)		Recommended	
	34 A/F					Mos	13-Sep-2021				
	Superseded	REV1				Hrs					
						Ldg					
560XL-34-63 Rev 01		XLS+ FMS 4.0 (WAAS) Upgrade and V-Speeds Database Installation						RE (-)		Recommended	
	34 A/F					Mos	13-Sep-2021				
	Eff: 30-Mar-2010 Complied With	new FMS 29-Oct-2015				Hrs					
						Ldg					
560XL-34-64		CAT II Landing Operation Option						RE (-)		Optional	
	34 A/F					Mos	17-Dec-2021				
	Eff: 02-Dec-2009 Complied With					Hrs	2295:34				
	(UPDATE NOTE: SB560XL-34-64 CAT II IMPLEMENTATION IAW SB INSTRUCTIONS ISSUE DEC 02/2009 PERFORMED. FOUND OK. AFM SUPPLEMENT DATA UPDATED.)					Ldg	1,748				
560XL-34-65		XLS+ Adaptive Flight Displays (AFD) Software and Hardware						RE (-)		Recommended	
	34 A/F					Mos	13-Sep-2021				
	Eff: 02-Dec-2009 Not Applicable	Different SN of aircraft				Hrs					
						Ldg					
560XL-34-68		AFD AOA Configuration Wiring Installation						RE (-)		Recommended	
	34 A/F					Mos	13-Sep-2021				
	Not Applicable	Different SN of aircraft				Hrs					
						Ldg					
560XL-34-68 Rev 01		AFD AOA Configuration Wiring Installation						RE (-)		Recommended	
	34 A/F					Mos	13-Sep-2021				
	Eff: 15-Jun-2011 Not Applicable	Different SN of aircraft				Hrs					
						Ldg					
560XL-34-73		Traffic Surveillance System (TTR-4000) TCAS II Software 7.1 Upgrade						RE (-)		Optional	
	34 A/F					Mos					
	Eff: 01-Aug-2012					Hrs					
						Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
560XL-34-74	Navigation - GPS-4000S Software Update						RE (-)		Recommended	
 34 A/F						Mos	13-Sep-2021			
Eff: 28-Apr-2014 Not Applicable	Different SN of aircraft					Hrs				
						Ldg				
560XL-34-76	Navigation - Automatic Dependent Surveillance Broadcast (ADS-B) Out Transponder Installation						RE (-)		Optional	
 34 A/F						Mos	24-Nov-2019			
Eff: 03-Mar-2016 Complied With						Hrs	1700:03			
						Ldg	1,331			
Note: NOTE: Airplanes -6002, -6004 thru -6013, -6015 thru -6023, -6025 thru -6028, -6030, -6032 thru -6035 and -6037 thru -6044 must incorporate SB560XL-34-63, XLS+ FMS 4.0 (WAAS) Upgrade and V-Speeds Database Installation prior to or in conjunction with this service bulletin.										
560XL-34-79 Rev 01	Navigation - LCR-100 with Synchro AHRS Upgrade						RE (-)		Mandatory	
 34 A/F						Days	13-Sep-2021			
Eff: 21-Mar-2017 Not Applicable	LCR-93 installed					Hrs	2222:03			
(AVG MAN HRS: 1.5)						Ldg	1,687			
Note: NOTE: This Service Bulletin is related to and when completed complies with European Aviation Safety Agency EASA AD 2015-0093.										
94-01-04	Honeywell - Traffic Alert And Collision Avoidance System (TCAS) II						RE (-)		Mandatory (Appliance AD)	
 34 A/F						Mos	05-Jul-2021			
Eff: 04-Feb-1994 Not Applicable	COLLINS TCAS INSTALLED.					Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				
96-24-06	Icing Condition or Ice on the Wing Addition to AFM (Superseded by AD 2000-03-09)						RE (-)		Mandatory	
 34 A/F						Mos	28-Oct-2015			
Eff: 05-Dec-1996 Superseded						Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				
98-25-02	BF Goodrich Avionics Systems, Inc. SKYWATCH SKY497 Installations with a Top-Mounted Antenna						RE (-)		Mandatory (Appliance AD)	
 34 A/F						Mos	05-Jul-2021			
Eff: 22-Dec-1998 Not Applicable	NOT INSTALLED					Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				
CIL-34-04	Navigation - TDR-94/94D Transponder Alt - Call						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 25-Sep-2014						Hrs				
						Ldg				
CIL-34-08	Navigation - Transmittal of Collins Aerospace Service Bulletin ATL-4000-34-D, Navigation - ALT-4000 - Evaluation of Surface Mount Ferrite Bead Used on the Power Supply						RE (-)		Recommended	
 34 A/F						Mos	13-Sep-2021			
Eff: 18-May-2021 Not Applicable						Hrs				
(AVG MAN HRS: 2.5)						Ldg				
CIL-34-11	Navigation - Transmittal of Collins Aerospace Service Bulletin ALT-4000-34-14, Navigation - ALT 4000 Power Supply Robustness Improvement						T (A/R)		Optional, Service Letter	
 34 A/F						Mos				
Eff: 17-Oct-2022						Hrs				
(AVG MAN HRS: 2.5)						Ldg				
FAR 91.171	VOR - Test and Inspection per FAR 91.171						RE (A/R)		FAR91, FAR 91	
 34 A/F						Mos				
						Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				

OK-ECR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-ECR,SN 560-6198

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
FAR 91.411	Air Data Computer tests and inspections per FAR 91.411 Appendix E of Part 43						RE		FAR91, FAR 91	
 34 A/F	No.2				Mos	09-Oct-2023	24		09-Oct-2025	11 Months
822-1109-126					Hrs	3048:30				
46XY60					Ldg	2,362				
Inspected Date 09-Oct-2023										
(UPDATE NOTE: Systems Found Operating Within Specified Tolerances) (ISSUING AUTHORITY: FAA)										
Note: CAA Requirement										
FAR 91.411	Standby Air Data Computer tests and inspections per FAR 91.411 Appendix E of Part 43						RE		FAR91, FAR 91	
 34 A/F					Mos	09-Oct-2023	24		09-Oct-2025	11 Months
Inspected Date 09-Oct-2023					Hrs	3048:30				
(UPDATE NOTE: Systems Found Operating Within Specified Tolerances)										
Note: CAA Requirement										
ICA-560XL-34-00010	Honeywell ADS-B Out (ICA Supplement)						RE (-)		Mandatory	
 34 A/F					Mos	09-Sep-2021				
Eff: 26-Apr-2016 Not	as per S/N				Hrs	2218:31				
Applicable					Ldg	1,685				
ICA-560XL-34-00011	GH-3000/3900 Electronic Standby Instrument - System Update						RE (-)		ICA Supplement	
 34 A/F					Mos					
Eff: 22-Mar-2018					Hrs					
					Ldg					
SB560XL-34-81	Navigation - FMS-3000 Flight Management System (FMS) Search and Rescue Upgrade						T (A/R)		Optional	
 34 A/F					Mos					
Eff: 17-Dec-2018					Hrs					
					Ldg					
Note: NOTE: Airplanes -6002, -6004 thru -6013, -6015 thru -6023, -6025 thru -6028, -6030, -6032 thru -6035 and -6037 thru -6044 must incorporate SB560XL-34-63 Navigation - XLS+ FMS 4.0 (WAAS) Upgrade and V-Speeds Database Installation prior to or in conjunction with this service bulletin.										
SB560XL-34-82	Navigation - Standby Flight Display (SFD) Weight on Wheels (WOW) Electrical Wiring Improvement						RE (-)		Recommended	
 34 A/F					Mos					
Eff: 22-May-2023					Hrs					
(AVG MAN HRS: 3.5)					Ldg					
SL560XL-34-01	Navigation - B-RNAV Operation Navigation System Approval						T (A/R)		Informational	
 34 A/F					Mos					
Eff: 27-Jul-1998					Hrs					
					Ldg					
SL560XL-34-02	Reduced Vertical Separation Minimum (RVSM)						RE (-)		Optional	
 34 A/F					Mos					
					Hrs					
					Ldg					
SL560XL-34-02 Rev 01	Reduced Vertical Separation Minimum (RVSM)						T (A/R)		Informational	
 34 A/F					Mos					
Eff: 01-Dec-2004					Hrs					
					Ldg					
SL560XL-34-04	Navigation - IC-600/IC-615 Integrated Avionics Computer Operational Check						T (A/R)		Informational	
 34 A/F					Mos					
Eff: 17-Sep-2001					Hrs					
					Ldg					
SL560XL-34-05	Navigation - Transmittal of Meggitt Avionics Service Information Letter No. 17, Secondary Flight Displays Mark 2						RE (-)		Optional	
 34 A/F					Mos					
					Hrs					
					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
SL560XL-34-05 Rev 01  34 A/F Eff: 21-Dec-2001	Navigation - Transmittal of Meggitt Avionics Service Information Letter No. 17, Secondary Flight Displays Mark 2						T (A/R)		Informational	
	Mos									
	Hrs									
SL560XL-34-06  34 A/F Eff: 17-Jul-2002	Navigation - TCAS Compatibility with RVSM Operations						T (A/R)		Informational	
	Mos									
	Hrs									
SL560XL-34-08A  34 A/F Eff: 17-Feb-2003 Not Applicable	Navigation - Transmittal of Honeywell Technical Newsletter A23-3850-001						RE (-)		Mandatory	
	ASL560XL-34-08: NAVIGATION-TRANSMITTAL OF HONEYWELL TECHNICAL NEWSLETTER A23-3850-001 DOES NOT APPLY, AS PARTS ARE NOT INSTALLED ON AIRCRAFT.						28-Oct-2015			
	Ldg						5			
SL560XL-34-10  34 A/F Eff: 21-Apr-2003	Navigation - Pitot/Static Leak Check Update						T (A/R)		Informational	
	Mos									
	Hrs									
SL560XL-34-14  34 A/F Eff: 01-Apr-2004	Flux Valve Inspection Criteria						T (A/R)		Informational	
	Mos									
	Hrs									
SL560XL-34-15  34 A/F Eff: 01-Apr-2004	560XL Compass System Troubleshooting Procedures						T (A/R)		Informational	
	Mos									
	Hrs									
SL560XL-34-21  34 A/F Eff: 25-Feb-2009	Operational Compliance Summary for EASA Temporary Guidance Leaflet (TGL) -36 Approval of Electronic Flight Bags (EFB) for the Rockwell Collins Integrated Flight Information System (IFIS)						T (A/R)		Informational	
	Mos									
	Hrs									
SL560XL-34-25  34 A/F Eff: 22-Jun-2016 Note: EFFECTIVITY: Aircraft with XM weather receiver.	Navigation - Transmittal of Rockwell Collins Service Information Letter 16-1 - Function of Reset Override Mode Switch on XM Weather Receiver for Proline 21/Proline Fusion						T (A/R)		Informational	
	Mos									
	Hrs									
SL560XL-34-26  34 A/F Eff: 13-Mar-2019 Not Applicable (AVG MAN HRS: 2)	Navigation - 822-2189-100 GPS-4000S SB15 Update						RE (-)	Recommended, Service Letter		
	PN not end in - 100 this service letter does not apply on aircraft						14-Sep-2021			
	Ldg									
SL560XL-34-27  34 A/F Eff: 19-Aug-2020 Not Applicable	Navigation - GPS-4000S Global Positioning System Software Update						RE (-)	Recommended		
	as per P/N of GPS						13-Sep-2021			
	Ldg						2222:03			
SL560XL-34-27 R1  34 A/F Eff: 15-Mar-2021 Not Applicable Note: EFFECTIVITY: 560 (Citation Excel) equipped with 822-2189-100 GPS-4000S Global Positioning System (GPS) Units.	Navigation - GPS-4000s Global Positioning System Software Update						RE (-)	Recommended, Service Letter		
	Different GPS PN						11-Oct-2021			
	Ldg									

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-34-27 R2	Navigation - GPS-4000s Global Positioning System Software Update						RE (-)		Mandatory	
 34 A/F						Mos	11-Oct-2021			
Eff: 11-May-2023 Not Applicable	Different PN of GPS					Hrs				
						Ldg				
Note: EFFECTIVITY: 560XL-6001 to 560XL-6289 equipped with equipped with 822-2189-100 GPS-4000S Global Positioning System (GPS) Units. COMPLIANCE: MANDATORY: This service letter must be accomplished by May 12, 2023.										
SL560XL-34-29	Navigation - Implement Airplane Flight Manual (AFM) Changes						RE (-)		Mandatory, Service Letter	
 34 A/F						Mos	29-Jul-2021			
Eff: 23-Jun-2021 Complied With						Hrs	2169:34			
(AVG MAN HRS: 0.5)						Ldg	1,654			
Note: COMPLIANCE: This service document must be accomplished prior to June 24, 2021.										
SL560XL-34-30	Navigation - Transmittal of Collins Aerospace Service Bulletin FGC-3XXX-22-AA - Pitch Trim Failure and/or Chatter at Start-Up						T (A/R)		Optional	
 34 A/F						Mos				
Eff: 26-Sep-2022						Hrs				
						Ldg				
Note: EFFECTIVITIY: 560XL (XLS+) 560-6001 thru 560-6044, that have incorporated SB 560XL-34-63.										
SL560XL-53-20	Fuselage - Instrument Panel Support Fastener Verification						RE (-)		Recommended	
 34 A/F						Mos	13-Sep-2021			
Eff: 03-Dec-2018 Not Applicable	Different SN of aircraft					Hrs				
(AVG MAN HRS: 14)						Ldg				
▼ 35 - OXYGEN										
	Crew Mask and Stowage Boxe						RE (O/C)			
 35 A/F	Copilot					Mos	29-Oct-2015			
Unknown						Hrs	0			
Unknown						Ldg	0			
	Crew Mask and Stowage Boxe						RE (O/C)			
 35 A/F	Pilot					Mos	29-Oct-2015			
Unknown						Hrs	0			
Unknown						Ldg	0			
	Oxygen Bottle Assembly						RE	Regulatory Inspections/Time Limits		
 35 A/F	New	0				Mos	27-Apr-2020	180	30-Nov-2034	10 Years
804882-14						Hrs	1791:04			
C07020020						Ldg	1,398			
Manufactured Date 01-Nov-2019 Ref:35-90-00-9600 (SOURCE: 560 XL MM Section 5-13-00) Note: NOTE: The Oxygen Bottle Assembly is manufactured Under U.S. DOT-SP 8162.										
	Oxygen Charging Valve						RE (O/C)			
 35 A/F						Mos	29-Oct-2015			
Unknown						Hrs	0			
Unknown						Ldg	0			
	Oxygen Dropout Box						RE (O/C)			
 35 A/F	No.1					Mos	29-Oct-2015			
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
✖	35 A/F Unknown Unknown	Oxygen Dropout Box No.2					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	35 A/F Unknown Unknown	Oxygen Dropout Box No.3					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	35 A/F Unknown Unknown	Oxygen Dropout Box No.4					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	35 A/F Unknown Unknown	Oxygen Dropout Box No.5					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	35 A/F Unknown Unknown	Oxygen Dropout Box No.6					Mos	29-Oct-2015		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	35 A/F MC10-16-150 S103557DMF (UPDATE NOTE: PERFORMED TASK 35-10-00-9600 COPILOT MC10-16-150, MC10-160-100 OR MLD20- 505 CREW MASK RESTORATION IAW AMM 560XL (REV 46); REMOVED COPILOT CREW MASK AND SENT TO OUTSIDE VENDOR FOR RESTORATION; INSTALLED EXCHANGE CREW MASK IN OVERHAULED CONDITION; PERFORMEDFUNCTIONAL CHECK; SAT.P/N ON: MC10-16-150S/N ON: SE23200DMF: 12/2008LAST OHL: 04/2021NEXT OHL: 04/2027PERFORMED TASK 35-10-00-9600 PILOT MC10-16-150, MC10-160-100 OR MLD20- 505 CREW MASK RESTORATION IAW AMM 560XL (REV 46); REMOVEDCOPILOT CREW MASK AND SENT TO OUTSIDE VENDOR FOR RESTORATION; INSTALLED EXCHANGE CREW MASK IN OVERHAULED CONDITION; PERFORMEDFUNCTIONAL CHECK; SAT.P/N ON: MC10-16-150S/N ON: S103557DMF: 09/2015LAST OHL: 09/2021NEXT OHL: 09/2027)	Oxygen Mask Copilot					Mos	17-Dec-2021		RE (O/C)	
							Hrs	2295:34			
							Ldg	1,748			
✖	35 A/F MC10-16-150 SE23200	Oxygen Mask Pilot					Mos	17-Dec-2021		RE (O/C)	
							Hrs	2295:34			
							Ldg	1,748			
✖	35 A/F C668512-0101 B15-11324	Oxygen Pressure (EI002) Gage New	0				Mos	29-Oct-2015		RE (O/C)	
			0				Hrs	0			
			0				Ldg	0			
✖	35 A/F C668512-0101 C15-11692	Oxygen Pressure Gauge New	0				Mos	29-Oct-2015		RE (O/C)	
			0				Hrs	0			
			0				Ldg	0			
✖	35 A/F 804881-01 C15050599	Oxygen Regulator New	0				Mos	29-Oct-2015		RE (O/C)	
			0				Hrs	0			
			0				Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
Passenger Oxygen Altitude Pressure Switch										
35 A/F	P24032	New	0			Mos	29-Oct-2015		RE (O/C)	
	1709		0			Hrs	0			
			0			Ldg	0			
Passenger Oxygen Control Valve										
35 A/F	P21006	New	0			Mos	29-Oct-2015		RE (O/C)	
	3573		0			Hrs	0			
			0			Ldg	0			
Portable Oxygen Bottle										
35 A/F	Unknown					Mos			RE (O/C)	Regulatory Inspections/Time Limits
	Unknown					Hrs				
	Ref:35-90-00-9601 (SOURCE: 560 XL MM Section 5-13-00)					Ldg				
Protective Breathing Equipment										
35 A/F	MR10051N	New				Mos	09-Oct-2023	120	RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS
	E2301030		0			Hrs	3048:30		[30-Sep-2033]	8.9 Years
	Manufactured Date 16-Jun-2023		0			Ldg	2,362			
	Ref:35-30-00-9600 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									
	Note: NOTE:Per Supplier Recommendation. Reference EROS (Air Liquid) 35-32- 17 Component Maintenance Manual With IPC or AVOX Component Maintenance Manual With IPC									
2015-08-07 Zodiac Aerotechnics (formerly Intertechnique Aircraft Systems) - Oxygen - Flightcrew Oxygen Mask Regulators										
35 A/F	Eff: 16-Jun-2015 Not Applicable	as per PN of GPS				Mos	13-Sep-2021		RE (-)	Mandatory (Appliance AD)
	(ISSUING AUTHORITY: FAA)					Hrs	2222:03			
						Ldg	1,687			
2015-08-07 Paragraph (g) Zodiac Aerotechnics (formerly Intertechnique Aircraft Systems) - Oxygen - Flightcrew Oxygen Mask Regulators - Inspection										
35 A/F	Not Applicable	as per PN of GPS				Mos	13-Sep-2021		RE (-)	Mandatory (Appliance AD)
	(ISSUING AUTHORITY: FAA)					Hrs	2222:03			
	Note: [24 MOS Initial Req.]					Ldg	1,687			
2015-08-07 Paragraph (h) Zodiac Aerotechnics (formerly Intertechnique Aircraft Systems) - Oxygen - Flightcrew Oxygen Mask Regulators - Replacement										
35 A/F	Not Applicable	as per PN of GPS				Mos	13-Sep-2021		RE (-)	Mandatory (Appliance AD)
	(ISSUING AUTHORITY: FAA)					Hrs	2222:03			
	Note: [24 MOS Initial Req.]					Ldg	1,687			
2016-11-20 Paragraph (g) Oxygen - Aerospace Protective Breathing Equipment (PBE), part number (P/N) 119003-11 - Inspection										
35 A/F	Eff: 15-Jul-2016 Not Applicable	DUE TO PART NUMBER FITTED				Mos			RE (-)	Mandatory (Appliance AD)
	Brand A:9990-2016-11-20(g) (ISSUING AUTHORITY: FAA)					Hrs				
						Ldg				
2017-18-12 Par. (i) Oxygen - B/E Aerospace Protective Breathing Equipment (PBE) Units - New Inspection for Airplanes With PBE, P/N 119003-21, Installed										
35 A/F	Eff: 16-Oct-2017 Not Applicable	BY P/N				Mos			RE (-)	Mandatory (Appliance AD)
	(AVG MAN HRS: 0.5) (ISSUING AUTHORITY: FAA)					Hrs				
	Note: NOTE: Refer to B/E Aerospace SB No. 119003-35-013, Rev. 002, dated July 19, 2017.					Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2017-18-12 Par. (j)	Oxygen - B/E Aerospace Protective Breathing Equipment (PBE) Units - New Replacement for Airplanes With PBE, P/N 119003-21, Installed						RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos				
Eff: 16-Oct-2017 Not Applicable	BY P/N					Hrs				
(AVG MAN HRS: 0.5) (ISSUING AUTHORITY: FAA)						Ldg				
Note: NOTE: Refer to B/E Aerospace SB No. 119003-35-013, Rev. 002, dated July 19, 2017.										
2022-04-09	Valve Assembly Vent - AVOX Systems Inc. Oxygen Cylinder and Valve Assemblies (Superseded by FAA AD 2023-13-11)						RE (-)		Mandatory (Appliance AD)	
35 A/F						Days	06-Mar-2022			
Eff: 04-Apr-2022 Not Applicable	affected PN not installed					Hrs	2431:33			
(ISSUING AUTHORITY: FAA)						Ldg	1,850			
Note: COMPLIANCE: Within 60 days after the effective date of this AD, inspect the oxygen valve assemblies, and oxygen cylinder and valve assemblies, to determine if the serial numbers of the valve, cylinder, and entire assembly, are listed in Appendix 1, "Affected Shipments," of the applicable service information identified in paragraphs (h)(1) through (3) of this AD. A review of airplane maintenance records is acceptable in lieu of this inspection if the serial numbers can be conclusively determined from that review. (1) AVOX Systems Inc. Alert Service Bulletin 10015804-35-01, Revision 02, dated October 16, 2019. (2) AVOX Systems Inc. Alert Service Bulletin 10015804-35-02, Revision 2, dated October 31, 2019. (3) AVOX Systems Inc. Alert Service Bulletin 10015804-35-03, Revision 02, dated October 15, 2019.										
2023-13-11	Oxygen - AVOX Systems Inc. (Formerly Scott Aviation) Oxygen Cylinder and Valve Assemblies (Supersedes FAA AD 2022-04-09)						RE (N/A)		Mandatory (Appliance AD)	
35 A/F						Mos				
Not Applicable	Afected PN not installed.					Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				
35-10-00-2200	Crew Mask and Stowage Boxe Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
35 A/F	Copilot5-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)
Unknown						Hrs	3048:30			
Unknown						Ldg	2,362			
(ZONE: 245) (SOURCE: 560 XL MM Section 5-10-02)										
35-10-00-2200	Crew Mask and Stowage Boxe Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
35 A/F	Pilot5-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)
Unknown						Hrs	3048:30			
Unknown						Ldg	2,362			
(ZONE: 246) (SOURCE: 560 XL MM Section 5-10-02)										
35-10-00-9600	MC10-16-150, MC10-16-100 or MLD20- 505 Crew Mask (Accomplish Supplier Testing and Fault Isolation Task) Restoration						RE	05-10-01, 05-10-02, Category 8		
35 A/F	Copilot					Mos	17-Dec-2021	72	31-Dec-2027	3.1 Years
MC10-16-150						Hrs	2295:34			
S103557DMF						Ldg	1,748			
Restored Date 17-Dec-2021										
MRBR Task:35-10-00-901, MRBR Task:35-10-00-902 (ZONE: 245) (UPDATE NOTE: PERFORMED TASK 35-10-00-9600 COPILOT MC10-16-150, MC10-160-100 OR MLD20- 505 CREW MASK RESTORATION IAW AMM 560XL (REV 46); REMOVED COPILOT CREW MASK AND SENT TO OUTSIDE VENDOR FOR RESTORATION; INSTALLED EXCHANGE CREW MASK IN OVERHAULED CONDITION; PERFORMEDFUNCTIONAL CHECK; SAT.P/N ON: MC10-16-150S/N ON: SE23200DMF: 12/2008LAST OHL: 04/2021NEXT OHL: 04/2027PERFORMED TASK 35-10-00-9600 PILOT MC10-16-150, MC10-160-100 OR MLD20- 505 CREW MASK RESTORATION IAW AMM 560XL (REV 46); REMOVEDCOPILOT CREW MASK AND SENT TO OUTSIDE VENDOR FOR RESTORATION; INSTALLED EXCHANGE CREW MASK IN OVERHAULED CONDITION; PERFORMEDFUNCTIONAL CHECK; SAT.P/N ON: MC10-16-150S/N ON: S103557DMF: 09/2015LAST OHL: 09/2021NEXT OHL: 09/2027) (SOURCE: 560XL MM)										
Note: Tracked by Component Time Limits.										
NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored MC10-16-150, MC10-16-100, or MLD20-505 Crew Mask and/or reference EROS (Intertechnique) 35-13-63 (MC10- 16-150 and MC10-16-100) and 35-13-64 (MLD20-505) Component Maintenance Manual and IPL.										

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
35-10-00-9600		MC10-16-150, MC10-16-100 or MLD20- 505 Crew Mask (Accomplish Supplier Testing and Fault Isolation Task) Restoration							RE	05-10-01, 05-10-02, Category 8		
	35 A/F	Pilot					Mos	17-Dec-2021	72	31-Dec-2027	3.1 Years	
	MC10-16-150						Hrs	2295:34				
	SE23200						Ldg	1,748				
	Restored Date 17-Dec-2021											
	MRBR Task:35-10-00-901, MRBR Task:35-10-00-902 (ZONE: 246) (SOURCE: 560XL MM)											
	Note: Tracked by Component Time Limits.											
	NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored											
	MC10-16-150, MC10-16-100, or MLD20-505 Crew Mask and/or reference EROS (Intertechnique) 35-13-63 (MC10- 16-150 and MC10-16-100) and 35-13-64 (MLD20-505) Component Maintenance Manual and IPL.											
35-20-00-2200		Passenger Drop Box and Mask Assembly Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	35 A/F	No.15-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)	
	Unknown						Hrs	3048:30				
	Unknown						Ldg	2,362				
	(ZONE: 171) (SOURCE: 560 XL MM Section 5-10-02)											
	Note: NOTE: It is recommended you do this task at the same time as Task 35-20-00-7200											
35-20-00-2200		Passenger Drop Box and Mask Assembly Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	35 A/F	No.25-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)	
	Unknown						Hrs	3048:30				
	Unknown						Ldg	2,362				
	(ZONE: 172) (SOURCE: 560 XL MM Section 5-10-02)											
	Note: NOTE: It is recommended you do this task at the same time as Task 35-20-00-7200											
35-20-00-2200		Passenger Drop Box and Mask Assembly Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	35 A/F	No.35-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)	
	Unknown						Hrs	3048:30				
	Unknown						Ldg	2,362				
	(ZONE: 251) (SOURCE: 560 XL MM Section 5-10-02)											
	Note: NOTE: It is recommended you do this task at the same time as Task 35-20-00-7200											
35-20-00-2200		Passenger Drop Box and Mask Assembly Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	35 A/F	No.45-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)	
	Unknown						Hrs	3048:30				
	Unknown						Ldg	2,362				
	(ZONE: 252) (SOURCE: 560 XL MM Section 5-10-02)											
	Note: NOTE: It is recommended you do this task at the same time as Task 35-20-00-7200											
35-20-00-2200		Passenger Drop Box and Mask Assembly Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	35 A/F	No.55-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)	
	Unknown						Hrs	3048:30				
	Unknown						Ldg	2,362				
	(ZONE: 261) (SOURCE: 560 XL MM Section 5-10-02)											
	Note: NOTE: It is recommended you do this task at the same time as Task 35-20-00-7200											
35-20-00-2200		Passenger Drop Box and Mask Assembly Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	35 A/F	No.65-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)	
	Unknown						Hrs	3048:30				
	Unknown						Ldg	2,362				
	(ZONE: 262) (SOURCE: 560 XL MM Section 5-10-02)											
	Note: NOTE: It is recommended you do this task at the same time as Task 35-20-00-7200											

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
35-20-00-7100	Passenger Oxygen System Operational Check								RE 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
 35 A/F	5-12-03					Mos 09-Oct-2023	24	-/+1m (31-Oct-2025)		11.7 Months (+30 Days)
	(ZONE: 171, 172, 235, 251, 252, 261, 262, 235) (SOURCE: 560 XL MM Section 5-10-02)					Hrs 3048:30				
						Ldg 2,362				
35-20-00-7200	Passenger Oxygen System Functional Check								RE 05-10-01, 05-10-02, Category 8, Category 9	
 35 A/F	5-12-06					Mos 09-Oct-2023	48	-/+1m (31-Oct-2027)		3 Years (+30 Days)
	MRBR Task:21-30-00-702, MRBR Task:35-10-00-704, MRBR Task:35-10-00-705, MRBR Task:35-10-00-706, MRBR Task:35-10-00-707 (ZONE: 171, 172, 235, 251, 252, 261, 262) (SOURCE: 560XL MM)					Hrs 3048:30				
	Note: NOTE: It is recommended you do this task at the same time as Task 35-20-00-2200					Ldg 2,362				
35-30-00-2200	Optional Protective Breathing Equipment Detailed Inspection								RE 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
 35 A/F	5-12-01					Mos 31-Oct-2024	12	-/+1m (31-Oct-2025)		11.7 Months (+30 Days)
	MR10051N E2301030					Hrs 3308:54				
	(ZONE: 245) (Tol. Adjustment: -22d) (SOURCE: 560 XL MM Section 5-10-02)					Ldg 2,570				
35-90-00-7800	Oxygen Bottle Assembly (Hydrostatic Test) Restoration								RE Regulatory Inspections/Time Limits	
 35 A/F						Mos 01-Feb-2020	60	28-Feb-2025		3.5 Months
	804882-14 C07020020					Hrs				
	Hydrostatic Tested Date 01-Feb-2020 (SOURCE: 560 XL MM Section 5-13-00)					Ldg				
	Note: NOTE: The Oxygen Bottle Assembly is manufactured Under U.S. DOT-SP 8162.									
 ECR-WP-010 / OKECR/013 START 24-JUN-2024										
35-90-00-7801	Portable Oxygen Bottle Assembly (Hydrostatic Test) Restoration								RE (N/A) Regulatory Inspections/Time Limits	
 35 A/F						Mos 01-Feb-2020				
	Unknown					Hrs 1791:04				
	Unknown					Ldg 1,398				
	(SOURCE: 560 XL MM Section 5-13-00)									
CIL-35-02	Oxygen-Transmittal of Zodiac Aerotechnics Service Bulletin MC10-35-274								RE (-) Mandatory	
 35 A/F						Mos 09-Sep-2021				
	Eff: 12-Jun-2015 Not Applicable					Hrs 2218:31				
	as per S/N					Ldg 1,685				
CIL-35-05	Oxygen - Transmittal of Zodiac Aerospace Service Bulletin MCF-35-001								RE (-) Mandatory	
 35 A/F						Mos 03-Mar-2016				
	Eff: 08-Jan-2016 Not Applicable					Hrs				
	BY P/N FITTED					Ldg				
	(AVG MAN HRS: 3)									
	Note: All Citation Models with flight crew oxygen mask regulators, having P/N MC10, MF10, MF20 series with S7N as listed in Zodiac Aerospace SB MCF-SBU-35-001									
SB560XL-35-04	Oxygen - Oxygen System Pressure Switch Replacement for Chinese Registered Airplanes								RE (-) Optional	
 35 A/F						Mos 09-Sep-2021				
	Eff: 13-Aug-2018 Not Applicable					Hrs 2218:31				
	as per S/N					Ldg 1,685				
SL560XL-35-03	Transmittal of AVOX Systems Service Bulletin 36758-35-01								RE (-) Recommended	
 35 A/F						Mos 13-Sep-2021				
	Eff: 23-Jul-2009 Not Applicable					Hrs				
	Different SN of aircraft					Ldg				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SL560XL-35-04		Transmittal of Intertechnique Service Bulletin MXH-35-240 Revision 2								RE (-)	Optional
	35 A/F						Mos	09-Sep-2021			
	Not Applicable	as per S/N					Hrs	2218:31			
							Ldg	1,685			
SL560XL-35-04 Rev 01		Transmittal of Intertechnique Service Bulletin MXH-35-240 Revision 2								RE (-)	Optional
	35 A/F						Mos	09-Sep-2021			
	Not Applicable	as per S/N					Hrs	2218:31			
							Ldg	1,685			
SL560XL-35-04 Rev 02		Transmittal of Intertechnique Service Bulletin MXH-35-240 Revision 2								RE (-)	Mandatory
	35 A/F						Mos	09-Sep-2021			
	Eff: 25-Oct-2012 Not Applicable	as per S/N					Hrs	2218:31			
							Ldg	1,685			
▼ 36 - PNEUMATIC											
		APU Bleed Air Shutoff (VT004) Valve								RE (O/C)	
	36 A/F						Mos	29-Oct-2015			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
		APU Check Valve								RE (O/C)	
	36 A/F		0			Mos	29-Oct-2015				
	8C1045	New	0			Hrs	0				
	1061		0			Ldg	0				
		Bleed Air Manifold Temperature (TT001) Sensor								RE (O/C)	
	36 A/F		0			Mos	29-Oct-2015				
	1E51-1	New	0			Hrs	0				
	6BM242		0			Ldg	0				
		Bleed Air Manifold Temperature (TT002) Sensor								RE (O/C)	
	36 A/F		0			Mos	29-Oct-2015				
	1E51-1	New	0			Hrs	0				
	6BM243		0			Ldg	0				
		Bleed Air Overtemp (ST014) Switch								RE (O/C)	
	36 A/F		0			Mos	29-Oct-2015				
	1173T181-2	New	0			Hrs	0				
	7783		0			Ldg	0				
		Bleed Air Overtemp (ST017) Switch								RE (O/C)	
	36 A/F		0			Mos	29-Oct-2015				
	1173T181-2	New	0			Hrs	0				
	7875		0			Ldg	0				
		Bleed Air Temperature (ST020) Switch								RE (O/C)	
	36 A/F	Right					Mos	29-Oct-2015			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
		Bleed Air Temperature (ST021) Switch								RE (O/C)	
	36 A/F	Left					Mos	29-Oct-2015			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	36 A/F 8C1045 1116	Bleed Air to Presurization Check Valve						RE (O/C)			
		No.1	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	36 A/F 8C1045 1123	Bleed Air to Presurization Check Valve						RE (O/C)			
		No.2	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	36 A/F 6711335-1 NSN	Door Solenoid Valve						RE (O/C)			
						Mos	07-Dec-2022				
						Hrs	2834:32				
						Ldg	2,163				
	36 A/F 9912486-2 S4883T3861	Heat B/A Exchanger						RE (O/C)			
		Left				Mos	30-Sep-2021				
		New	0			Hrs	2245:07				
			0			Ldg	1,714				
	36 A/F 8230-2 S4883T2845	Heat B/A Exchanger						RE (O/C)			
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	36 A/F 2340594-6 1583	Heat Exchanger						RE (O/C)			
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	36 A/F Unknown Unknown	Heat Exchanger						RE (O/C)			
		Right				Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	36 A/F 1E50-2 5BK31	Heat Exchanger Actuator						RE (O/C)			
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	36 A/F 1E50-2 5BK25	Heat Exchanger Actuator						RE (O/C)			
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	36 A/F 1406-7 1009	Precooler VD003 Valve						RE (O/C)			
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				
	36 A/F 1406-8 1363	Precooler VD003 Valve						RE (O/C)			
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
Rudder Bias Check Valve										
	36 A/F					Mos	29-Oct-2015		RE (O/C)	
	Unknown					Hrs	0			
	Unknown					Ldg	0			
(ZONE: .)										
Service Air Regulator										
	36 A/F					Mos	29-Oct-2015		RE (O/C)	
	1H75-18	New				Hrs	0			
	6BM53					Ldg	0			
36-11-03-2100 Precooler Heat Exchanger General Visual Inspection										
	36 A/F	Left5-12-01				Mos	31-Oct-2024	12	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	11.7 Months (+30 Days)
	2340594-6					Hrs	3308:54			
	1583					Ldg	2,570			
(ZONE: 411) (SOURCE: 560 XL MM Section 5-10-02)										
36-11-03-2100 Precooler Heat Exchanger General Visual Inspection										
	36 A/F	Right5-12-01				Mos	31-Oct-2024	12	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	11.7 Months (+30 Days)
	Unknown					Hrs	3308:54			
	Unknown					Ldg	2,570			
(ZONE: 412) (SOURCE: 560 XL MM Section 5-10-02)										
36-12-00-2200 Auxiliary Power Unit Bleed Air Check Valve Detailed Inspection										
	36 A/F	5-12-06				Mos	09-Oct-2023	48	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	3 Years (+30 Days)
						Hrs	3048:30			
						Ldg	2,362			
(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02)										
361208 Rudder Bias Check Valve										
	36 A/F					Mos	29-Oct-2015		RE (O/C)	
	8C1045	New				Hrs	0			
	1185					Ldg	0			
36-15-00-1700 Particulate Trap (Cleaning) Restoration										
	36 A/F	5-12-06				Mos	09-Oct-2023	48	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	3 Years (+30 Days)
						Hrs	3048:30			
						Ldg	2,362			
(ZONE: 171, 261) (UPDATE NOTE: Particulate Trap Corroded Refer to Order 101048066 for replacement.) (SOURCE: 560 XL MM Section 5-10-02)										
▼ 38 - WATER/WASTE										
38-30-02-2200 Externally Serviceable Toilet System Detailed Inspection										
	38 A/F	5-12-03				Mos	09-Oct-2023	24	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	11.7 Months (+30 Days)
	9919009-5					Hrs	3048:30			
	0360					Ldg	2,362			
(ZONE: 172, 170, 315) (SOURCE: 560 XL MM Section 5-10-02)										
Note: NOTE: It is recommended you do this task at the same time as Task 53-10-11-2200										
560XL-38-03 Toilet Override Relay Installation										
	38 A/F					Mos			RE (-)	Optional
	Eff: 03-Mar-2014					Hrs				
						Ldg				
SL560XL-38-01 Transmittal of Monogram Systems Service Information Letter SIL 15900-023										
	38 A/F					Mos	13-Sep-2021		RE (-)	Recommended
	Eff: 06-Jan-2011 Not Applicable	Different SN of aircraft				Hrs				
						Ldg				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
▼ 49 - AIRBORNE AUXILIARY POWER											
APU Electronic Control			RE (O/C)								
	49 APU1	New	0				Mos	29-Oct-2015			
	2119552-4		0				Hrs	0			
	25-N0293		0				APUS	0			
APU Igniter Plug			RE (O/C)								
	49 APU1						Mos	03-Mar-2019			
	304634-2						Hrs				
	NSN						APUS				
Bleed Air Shutoff Valve			RE (O/C)								
	49 APU1	New	0				Mos	29-Oct-2015			
	1413-19		0				Hrs	0			
	1274		0				APUS	0			
Compressor Rotor, Centrifugal			RE (O/C)								
	49 APU1	Unknown Unknown					Mos	29-Oct-2015			
	Unknown						Hrs	0			
	Unknown						APUS	0			
DC Ammeter			RE (O/C)								
	49 A/F	New	0				Mos	29-Oct-2015			
	MD144-3		0				Hrs	0			
	G13-10616						Ldg				
Electrical Igniter Lead			RE (O/C)								
	49 APU1	New	0				Mos	29-Oct-2015			
	3888302-20		0				Hrs	0			
	NSN		0				APUS	0			
Fuel Control Assembly			RE (O/C)								
	49 APU1	New	0				Mos	29-Oct-2015			
	3883900-1		0				Hrs	0			
	1501969		0				APUS	0			
Fuel Filter			RE (O/C)								
	49 APU1						Mos	24-Nov-2019			
	3800722-1						Hrs	656:06			
	P-997						APUS				
Fuel Nozzle Assembly			RE (O/C)								
	49 APU1	Unknown Unknown Brand CE:054906					Mos	29-Oct-2015			
	Unknown						Hrs	0			
	Unknown						APUS	0			
Fuel Shut-Off Valve			RE (O/C)								
	49 APU1						Mos	26-Feb-2019			
	692545-17						Hrs				
	7713						APUS				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	49 A/F C664503-0104 NSN	Hourmeter New						RE (O/C)			
			0			Mos	29-Oct-2015				
			0			Hrs	0				
						Ldg					
	49 APU1 3888000-7 J14490385	Ignition Unit New						RE (O/C)			
			0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			APUS	0				
	49 APU1 3876351-1 14-150241-02194	Low Oil Pressure Switch New						RE (O/C)			
			0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			APUS	0				
	49 APU1 3881825-1 P-2031	Lube Pump Assembly New						RE (O/C)			
			0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			APUS	0				
	49 APU1 3876318-3 15162221015336	Oil Level Switch New						RE (O/C)			
			0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			APUS	0				
	49 A/F 3001-212-1004/455-9 214276	Overheat Detector New						RE (O/C)			
			0			Mos	29-Oct-2015				
			0			Hrs	0				
						Ldg					
	49 APU1 Unknown Unknown	Power Section Assembly 						RE (O/C)			
						Mos	29-Oct-2015				
						Hrs	0				
						APUS	0				
	49 A/F MD680-4 D15-10065	RPM/Max Indicator New						RE (O/C)			
			0			Mos	29-Oct-2015				
			0			Hrs	0				
						Ldg					
	49 APU1 66503-101165-001 14-751	Tee-Flow Divider Valve New						RE (O/C)			
			0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			APUS	0				
3615880-49-8149		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUs							RE (-)		Recommended
	49 APU1 Eff: 12-Jun-2015 Not Applicable	Different SN					Mos	13-Sep-2021			
							Hrs				
							APUS				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
3615880-49-8149 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUS						RE (-)		Recommended	
	49 APU1	Different SN				Mos	13-Sep-2021				
	Not Applicable					Hrs					
						APUS					
3615880-49-8149 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUS						RE (-)		Recommended	
	49 APU1	Different SN				Mos	13-Sep-2021				
	Not Applicable					Hrs					
						APUS					
3615880-49-8149 Rev 3		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUS						RE (-)		Recommended	
	49 APU1	Different SN				Mos	13-Sep-2021				
	Eff: 15-Dec-2017 Not Applicable					Hrs					
	(AVG MAN HRS: 1.5)					APUS					
3822101-49-8148 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, P/N 3822101-1, on Multiple APU's						RE (-)		Recommended	
	49 APU1	Different SN				Mos	13-Sep-2021				
	Eff: 20-Oct-2015 Not Applicable					Hrs					
						APUS					
3881800-49-7523		Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS						RE (-)		Recommended	
	49 APU1	Lube pump assembly with new PN				Mos	13-Sep-2021				
	Eff: 01-Feb-2000 Not Applicable					Hrs					
	(AVG MAN HRS: 2)					APUS					
3881800-49-7523 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS						RE (-)		Recommended	
	49 APU1	Lube pump assembly with new PN				Mos	13-Sep-2021				
	Eff: 05-May-2000 Not Applicable					Hrs					
	(AVG MAN HRS: 2)					APUS					
3881800-49-7523 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS						RE (-)		Recommended	
	49 APU1	Lube pump assembly with new PN				Mos	13-Sep-2021				
	Eff: 26-Oct-2001 Not Applicable					Hrs					
	(AVG MAN HRS: 2)					APUS					
3881800-49-7523 Rev 3		Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS						RE (-)		Recommended	
	49 APU1	Lube pump assembly with new PN				Mos	13-Sep-2021				
	Eff: 22-Feb-2002 Not Applicable					Hrs					
	(AVG MAN HRS: 2)					APUS					
3881800-49-7523 Rev 4		Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS						RE (-)		Recommended	
	49 APU1	Lube pump assembly with new PN				Mos	13-Sep-2021				
	Eff: 30-Oct-2014 Not Applicable					Hrs					
	(AVG MAN HRS: 2)					APUS					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
3883900-49-7976		Airborne Auxiliary Power - Main Fuel Control Unit (FCU) - Check Nameplate for Latest Change Number. Install Fuel Flow Deflector, PN 70720001-1, on the Fuel Control Differential Pressure (Delta P) Sleeve as Required at Next Auxiliary Power Unit (APU) Shop Visit							RE (-)	Recommended	
	49 APU1					Mos					
	Eff: 25-Feb-2009					Hrs					
	(AVG MAN HRS: 1)					APUS					
3883900-49-7976 Rev 1		Airborne Auxiliary Power - Main Fuel Control Unit (FCU) - Check Nameplate for Latest Change Number. Install Fuel Flow Deflector, PN 70720001-1, on the Fuel Control Differential Pressure (Delta P) Sleeve as Required at Next Auxiliary Power Unit (APU) Shop Visit							RE (-)	Recommended	
	49 APU1					Mos					
	Eff: 10-Apr-2009					Hrs					
	(AVG MAN HRS: 1)					APUS					
3883900-49-7976 Rev 2		Airborne Auxiliary Power - Main Fuel Control Unit (FCU) - Check Nameplate for Latest Change Number. Install Fuel Flow Deflector, PN 70720001-1, on the Fuel Control Differential Pressure (Delta P) Sleeve as Required at Next Auxiliary Power Unit (APU) Shop Visit							RE (-)	Recommended	
	49 APU1					Mos					
	Eff: 11-May-2019					Hrs					
	(AVG MAN HRS: 1)					APUS					
3883900-49-8297		Airborne Auxiliary Power - Gas Turbine Engine - Replace Oil Seal, PN 3883905-1, with PN 70722907-1 on the Fuel Control Unit (FCU), PN 3883900-1 for the RE100 APU							RE (-)	Recommended	
	49 APU1					Mos	16-Sep-2021				
	Eff: 24-Feb-2020 Complied With					Hrs					
						APUS					
	Note: COMPLIANCE: This service bulletin, recommended by Honeywell, is done on an attritional basis, oil seal to be replaced if a high leakage rate is present.										
49-00-00-2100		Auxiliary Power Unit General Visual Inspection and Operational Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	49 A/F	5-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
						Hrs	3048:30				
	(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	2,362				
	Note: NOTE: It is recommended you do this task at the same time as Tasks 53-10-12-2100, 53-10-12-2102, 53-10-12-2103, 53-10-12-2104, and 53-10-12-2200										
49-00-00-2103		Auxiliary Power Unit Containment Box Assembly General Visual Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	49 A/F	5-12-13				Mos	17-Dec-2021	72	-/+1m	(29-Oct-2027)	3 Years (+31 Days)
						Hrs	2295:34				
	(ZONE: 312) (Tol. Adjustment: -48d) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 13 IAW AMM 560XL (REV 46) CHAPTER 5-12-13 (REV 46)) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	1,748				
49-00-00-9600		Compressor Rotor Disk Discard							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈25-Mar-2050
	49 APU1		0			Mos	29-Oct-2015				
	3822523-003	New	0			Hrs	0				
	14-162053-07521		0			APUS	0	12,000		12,000	8,516 APUS
	MRBR Task:49-01-00-902 (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00, 5-18-00)										
	Note: NOTE: Per Supplier Recommendation. Reference Honeywell 49-25-85 RE100 (XL) Maintenance Manual.										
49-00-00-9601		Turbine Rotor Disk Discard							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈15-May-2026
	49 APU1		0			Mos	29-Oct-2015				
	3842340-2	New	0			Hrs	0				
	14-156101-13972		0			APUS	0	4,000		4,000	516 APUS
	MRBR Task: 49-01-00-903 (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00, 5-18-00)										
	Note: NOTE: Per Supplier Recommendation. Reference Honeywell 49-25-85 RE100 (XL) Maintenance Manual.										
491001		Replace Turbine Housing Assembly, Combustion Chamber, Retainer, Turbine Nozzle Assembly, Shim, Deswirl Deflector, Turbine Rotor, Interstage Seal							RE		≈15-May-2026
	49 APU1					Mos	29-Oct-2015				
						Hrs	0				
						APUS	0	4,000		4,000	516 APUS

Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
492040-0101		Bearing Ball Anlr						RE (O/C)			
	49 APU1					Mos	29-Oct-2015				
	Unknown					Hrs	0				
	Unknown					APUS	0				
49-30-00-9600		Auxiliary Power Unit Fuel Filter Element Discard						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	49 APU1					Mos	09-Oct-2023	24		31-Oct-2025	11.7 Months
						Hrs	1449:48	900		2349:48	726:06 Hrs
	MRBR Task:49-01-00-901 (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00, 5-18-00)					APUS	3,162				
49-40-00-2200		Auxiliary Power Unit Igniter Plug Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	49 APU1					Mos	09-Oct-2023	24		31-Oct-2025	11.7 Months
	304634-2					Hrs	1449:48	900		2349:48	726:06 Hrs
	NSN					APUS	3,162				
MRBR Task:49-01-00-201 (UPDATE NOTE: Found APU Ignitor Cable and Igniter With Burning Marks Refer to WO: 101047634) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00, 5-18-00) Note: NOTE: Per Supplier Recommendation. Reference Honeywell 49-25-85 RE100 (XL) Maintenance Manual.											
49-70-01-2200		Auxiliary Power Unit Magnetic Chip Collector Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	49 APU1					Mos	31-Oct-2024	12		31-Oct-2025	11.7 Months
						Hrs	1623:42	450		2073:42	450 Hrs
	MRBR Task:49-01-00-202 (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00, 5-18-00)					APUS	3,484				
49-7933		Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						RE (-)			
	49 APU1					Mos					
	Eff: 24-Apr-2007					Hrs					
						APUS					
49-7933 Rev 1		Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						RE (-)		Service Bulletin	
	49 APU1					Mos					
	Eff: 04-Jun-2007					Hrs					
						APUS					
49-7933 Rev 10		Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						T (A/R)		Service Bulletin	
	49 APU1					Mos					
	Eff: 18-Jan-2022					Hrs					
						APUS					
49-7933 Rev 2		Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						RE (-)		Service Bulletin	
	49 APU1					Mos					
	Eff: 09-Apr-2010					Hrs					
						APUS					
49-7933 Rev 3		Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						RE (-)		Service Bulletin	
	49 APU1					Mos					
	Eff: 31-Oct-2011					Hrs					
						APUS					
49-7933 Rev 4		Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						RE (-)		Service Bulletin	
	49 APU1					Mos					
	Eff: 12-Aug-2014					Hrs					
						APUS					
49-7933 Rev 5		Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						T (-)		Service Bulletin	
	49 APU1					Mos					
	Eff: 23-Oct-2014					Hrs					
						APUS					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
49-7933 Rev 6  49 APU1	Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						RE (-)		Service Bulletin	
						Mos				
						Hrs				
						APUS				
49-7933 Rev 7  49 APU1 Eff: 09-Feb-2017	Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						T (-)		Service Bulletin	
						Mos				
						Hrs				
						APUS				
49-7933 Rev 8  49 APU1 Eff: 27-Jul-2017 Complied With	Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						RE (-)		Service Bulletin	
						Mos	14-Sep-2021			
						Hrs				
						APUS				
49-7933 Rev 9  49 APU1 Eff: 03-Apr-2020 Complied With	Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						RE (-)		Service Bulletin	
						Mos	13-Sep-2021			
						Hrs				
						APUS				
49-7992  49 APU1	Remove and Replace Electronic Control Unit, PN 2119552-2 or PN 2119552-3, with Electronic Control Unit, PN 2119552-4						RE (-)		Optional	
						Mos				
						Hrs				
						APUS				
49-7992 Rev 1  49 APU1	Remove and Replace Electronic Control Unit, PN 2119552-2 or PN 2119552-3, with Electronic Control Unit, PN 2119552-4						RE (-)		Optional	
						Mos				
						Hrs				
						APUS				
49-7997  49 APU1 Eff: 16-Sep-2009 (ZONE: .)	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines.						RE (-)		Service Bulletin	
						Mos				
						Hrs				
						APUS				
49-7997 Rev 1  49 APU1 Eff: 11-Feb-2010	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines						RE (-)		Service Bulletin	
						Mos				
						Hrs				
						APUS				
49-7997 Rev 2  49 APU1 Eff: 22-Dec-2010	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines						RE (-)		Service Bulletin	
						Mos				
						Hrs				
						APUS				
49-7997 Rev 3  49 APU1 Eff: 16-Jan-2014	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines						RE (-)		Service Bulletin	
						Mos				
						Hrs				
						APUS				
49-7997 Rev 4  49 APU1 Eff: 12-Jan-2015	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines						T (-)		Service Bulletin	
						Mos				
						Hrs				
						APUS				
49-7997 Rev 5  49 APU1 Eff: 03-Feb-2017	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines						T (-)		Service Bulletin	
						Mos				
						Hrs				
						APUS				
49-7997 Rev 6  49 APU1 Eff: 05-Nov-2020 Complied With	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines						RE (-)		Service Bulletin	
						Mos	14-Sep-2021			
						Hrs				
						APUS				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
49-8252	Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs								RE (-)	
 49 APU1						Mos	14-Sep-2021			
Eff: 31-Aug-2018 Complied With						Hrs				
						APUS				
49-8252 Rev 1	Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs								RE (-)	
 49 APU1						Mos	14-Sep-2021			
Eff: 07-Mar-2019 Complied With						Hrs				
						APUS				
49-8252 Rev 2	Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs								RE (-)	Service Bulletin
 49 APU1						Mos	14-Sep-2021			
Eff: 13-Oct-2020 Complied With						Hrs				
						APUS				
49-90-00-9600	Auxiliary Power Unit Oil and Oil Filter Discard								RE	05-10-01, 05-10-02, Category 9
 49 APU1						Mos	09-Oct-2023	24	31-Oct-2025	11.7 Months
						Hrs	1449:48	900	2349:48	726:06 Hrs
MRBR Task:49-01-00-904 (SOURCE: 560XL MM)						APUS	3,162			
49-90-00-9601	SOAP								RE	
 49 APU1						Mos	09-Oct-2023	24	31-Oct-2025	11.7 Months
						Hrs	1449:48	900	2349:48	726:06 Hrs
Note: Spectrometric Oil Analysis Program						APUS	3,162			
49-CUS-001	APU SOAP Sample								RE	≈04-Apr-2025
 49 A/F						Mos	31-Oct-2024			
						Hrs	3308:54	300	3608:54	292:47 Hrs
						Ldg	2,570			
						Hrs (APU)	1623:42	500	2123:42	500 Hrs(APU)
560XL-49-17	Auxiliary Power - Auxiliary Power Unit Mount Bolt Change								RE (-)	Optional
 49 A/F						Mos				
Eff: 05-Oct-2015						Hrs				
						Ldg				
70721597-49-8166	Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs								RE (-)	Recommended
 49 APU1						Mos	13-Sep-2021			
Eff: 02-Jul-2015 Not Applicable	Different SN					Hrs				
						APUS				
70721597-49-8166 Rev 1	Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs								RE (-)	Recommended
 49 APU1						Mos	13-Sep-2021			
Eff: 31-Aug-2015 Not Applicable	Different SN					Hrs				
						APUS				
70721597-49-8166 Rev 2	Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs								RE (-)	Recommended
 49 APU1						Mos	13-Sep-2021			
Eff: 25-Oct-2016 Not Applicable	Different SN					Hrs				
						APUS				
70721597-49-8166 Rev 3	Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs								RE (-)	Recommended
 49 APU1						Mos	13-Sep-2021			
Eff: 13-Oct-2017 Not Applicable	Different SN					Hrs				
(AVG MAN HRS: 1)						APUS				
Note: COMPLIANCE: Honeywell recommends this service bulletin be done for the balance repair of the compressor rotor, PN 70721597-1.										

OK-ECR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-ECR,SN 560-6198

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
70721598-49-8168		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs						RE (-)		Recommended	
	49 APU1	Different SN					Mos	13-Sep-2021			
	Eff: 02-Jul-2015 Not Applicable						Hrs				
							APUS				
70721598-49-8168 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs						RE (-)		Recommended	
	49 APU1	Different SN					Mos	13-Sep-2021			
	Eff: 20-Oct-2015 Not Applicable						Hrs				
							APUS				
70721598-49-8168 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs						RE (-)		Recommended	
	49 APU1	Different SN					Mos	13-Sep-2021			
	Eff: 10-Jan-2017 Not Applicable						Hrs				
							APUS				
70721598-49-8168 Rev 3		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs						RE (-)		Recommended	
	49 APU1	Different SN					Mos	13-Sep-2021			
	Eff: 14-Dec-2017 Not Applicable						Hrs				
	(AVG MAN HRS: 1)						APUS				
70721725-49-8152		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs						RE (-)		Recommended	
	49 APU1	Different SN					Mos	13-Sep-2021			
	Eff: 27-May-2015 Not Applicable						Hrs				
							APUS				
70721725-49-8152 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs						RE (-)		Recommended	
	49 APU1	Different SN					Mos	13-Sep-2021			
	Eff: 27-May-2015 Not Applicable						Hrs				
							APUS				
70721725-49-8152 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs						RE (-)		Recommended	
	49 APU1	Different SN					Mos	13-Sep-2021			
	Not Applicable						Hrs				
							APUS				
70721725-49-8152 Rev 3		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs						RE (-)		Recommended	
	49 APU1	Different SN					Mos	13-Sep-2021			
	Eff: 27-Nov-2017 Not Applicable						Hrs				
							APUS				
70721725-49-8152 Rev 4		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs						RE (-)		Recommended	
	49 APU1	Different SN					Mos	13-Sep-2021			
	Eff: 19-Dec-2017 Not Applicable						Hrs				
							APUS				
APU 1		Honeywell - RE100[XL]						RE (-)			
	49 A/F	Time at install:					Mos	18-Aug-2015			
	3800722-1						Hrs				
	P-997						Ldg				
D201107000024 Rev 1		Approved Use of Biofuel Blends for All Honeywell Commercial and Military Auxiliary Power Units (APU)						T (A/R)		Service Information Letter	
	49 APU1						Mos				
	Eff: 03-Jun-2020						Hrs				
							APUS				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
D201112000050	Acceptance Criteria for On-Wing Borescope Inspections						RE (-)		Service Information Letter	
 49 APU1 Eff: 13-Jan-2012					Mos					
					Hrs					
					APUS					
D201112000050 Rev 1	Acceptance Criteria for On-Wing Borescope Inspections						T (A/R)		Service Information Letter	
 49 APU1 Eff: 14-Aug-2012					Mos					
					Hrs					
					APUS					
D201308000026	Uncommanded High Oil Temperature (HOT) Shutdown of the RE100[CS] and RE100[XL] AuxiliaryPower Units (APU)s						RE (-)		Service Information Letter	
 49 APU1 Eff: 10-Jan-2014					Mos					
					Hrs					
					APUS					
D201308000026 Rev 1	Uncommanded High Oil Temperature (HOT) Shutdown of the RE100[CS] and RE100[XL] AuxiliaryPower Units (APU)s						T (A/R)		Service Information Letter	
 49 APU1 Eff: 30-Mar-2016					Mos					
					Hrs					
					APUS					
D202207002674	Procedure to Determine if Hydro Pad Compressor Seal is Damaged and Evaluate if it was the Cause for Oil Leaks on the RE100 Series and 36-150 Series APU's						T (A/R)		Service Information Letter	
 49 APU1 Eff: 16-Aug-2022					Mos					
					Hrs					
					APUS					
	Note: EFFECTIVITY: Please see Par. B for more details.									
RE100-49-7400	Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, PN 3881739-2 with PN 3881800-1, Gearbox Housing, PN 3863409-4 with PN 3863409-2, and O-Ring, PN M83248/1-115 with PN M83248/1-116						RE (-)		Optional	
 49 APU1 Eff: 01-Feb-2000					Mos					
					Hrs					
					APUS					
RE100-49-7400 Rev 1	Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, Part No. 3881739-2 with Part No. 3881800-1, Gearbox Housing, Part No. 3863409-1/-2 with Part No. 3863409-3/-4 (Respectively), and O-ring, Part No. M83248/1-116 with Part No. M83248/1-115						T (A/R)		Optional	
 49 APU1 Eff: 14-Jun-2000					Mos					
					Hrs					
					APUS					
RE100-49-7465	Replace Thermocouple, Part No. 3876315-1						RE (-)		Recommended	
 49 APU1 Not Applicable	Different SN of APU				Mos	14-Sep-2021				
					Hrs					
					APUS					
RE100-49-7489	Airborne Auxiliary Power - Gas Turbine Engine - Replace Oil Filler Neck And Cap, PN 2A1126 (527-510-9001) With Oil Filler Neck and Dipstick Cap, PN 2A7732 (361-530-9354)						RE (-)		Optional	
 49 APU1 Eff: 02-Feb-2000					Mos					
					Hrs					
					APUS					
RE100-49-7530	Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, PN 3881800-1 with PN 3881825-1						RE (-)		Recommended	
 49 APU1 Eff: 01-Feb-2000 Not Applicable	Replaced with new PN				Mos	13-Sep-2021				
					Hrs					
					APUS					
RE100-49-7530 Rev 1	Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, PN 3881800-1 with PN 3881825-1						RE (-)		Recommended	
 49 APU1 Not Applicable	Replaced with new PN				Mos	13-Sep-2021				
					Hrs					
					APUS					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
RE100-49-7530 Rev 2	Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, PN 3881800-1 with PN 3881825-1						RE (-)		Recommended	
 49 APU1						Mos	13-Sep-2021			
Eff: 22-Feb-2002 Not Applicable	Replaced with new PN					Hrs				
						APUS				
RE100-49-7535	Airborne Auxiliary Power - Gas Turbine Engine - Replace Flow Divider Tee, PN 3883921-1 with PN 3883921-2						RE (-)		Recommended	
 49 APU1						Mos	13-Sep-2021			
Eff: 01-Oct-1999 Not Applicable	Replaced with new PN					Hrs				
						APUS				
RE100-49-7563	Airborne Auxiliary Power - Gas Turbine Engine - Replace Generator Seal, PN 3863387-1 with PN 3863504-1						RE (-)		Recommended	
 49 APU1						Mos	14-Sep-2021			
Eff: 11-May-2000 Not Applicable	Different SN of APU					Hrs				
						APUS				
RE100-49-7563 Rev 1	Airborne Auxiliary Power - Gas Turbine Engine - Replace Generator Seal, PN 3863387-1 with PN 3863504-1						RE (-)		Recommended	
 49 APU1						Mos	13-Sep-2021			
Eff: 22-May-2002 Not Applicable	Replaced with new PN					Hrs				
						APUS				
RE100-49-7773	Replace Electronic Control Unit (ECU), Part No. 2119552-2 with Part No. 2119552-3						RE (-)			
 49 APU1						Mos	14-Sep-2021			
Not Applicable	Different SN of APU					Hrs				
						APUS				
RE100-49-7787	Replace Low Oil Level Switch, Part No. 3876318-1 with Part No. 3876318-2						RE (-)		Optional	
 49 APU1						Mos				
Eff: 21-Jun-2004						Hrs				
						APUS				
RE100-49-7855	Replace Low Oil Level Switch, Part No. 3876318-1 or Part No. 3876318-2 with Part No. 3876318-3						RE (-)		Optional	
 49 APU1						Mos				
Eff: 09-Aug-2005						Hrs				
						APUS				
RE100-49-7896	Replace Oil Filler Neck and Cap						RE (-)		Optional	
 49 APU1						Mos				
						Hrs				
						APUS				
RE100-49-7896 Rev 1	Airborne Auxiliary Power - Gas Turbine Engine - Replace Oil Filler Neck and (Dipstic) Cap, P/N 361-530-9354						T (A/R)		Optional	
 49 APU1						Mos				
						Hrs				
						APUS				
RE100-49-8139	Airborne Auxiliary Power - Gas Turbine Engine - Increase the Installation Torque and add the Use of Locking Compound During Carbon Seal Assembly on the RE100 APU						RE (-)		Recommended	
 49 APU1						Mos	14-Sep-2021			
Eff: 15-Aug-2014 Not Applicable	Different SN of APU					Hrs				
						APUS				
RE100-49-8250	Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Module, PN 3881825-1 with PN 3881825-2, for the RE100[CS] and RE100[XL] Auxiliary Power Unit (APU)						T (-)			
 49 APU1						Mos				
Eff: 11-Sep-2017						Hrs				
						APUS				
Note: NOTE: Replacing lube module, PN 3881825-1 with PN 3881825-2, as described in this service bulletin, requires confirmation of high oil temperature shutdown. If HOT shutdown cannot be confirmed, this service bulletin is optional to the operator.										

OK-ECR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-ECR,SN 560-6198

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
RE100-49-8250 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Module, PN 3881825-1 with PN 3881825-2 for the RE100[CS] and RE100[XL] Auxiliary Power Unit (APU)						T (-)			
 49 APU1 Eff: 15-Jun-2018											
		Note: COMPLIANCE: This service bulletin is done by attrition by Honeywell if HOT shutdown is confirmed. If HOT shutdown cannot be confirmed, this service bulletin is optional to the operator.									
RE100-49-8250 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Module, PN 3881825-1 with PN 3881825-2, for the RE100[CS] and RE100[XL] Auxiliary Power Unit (APU)						T (A/R)		Service Bulletin	
 49 APU1 Eff: 30-Oct-2020											
		Note: COMPLIANCE: This service bulletin is done by attrition by Honeywell if HOT shutdown is confirmed. If HOT shutdown cannot be confirmed, this service bulletin is optional to the operator.									
RE100-49-8303		Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)						T (-)		Optional	
 49 APU1 Eff: 24-Feb-2020											
		Note: EFFECTIVITY: Applicable component PN 3800722-1, -2									
RE100-49-8303 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)						RE (-)		Optional	
 49 APU1 Eff: 01-Jul-2020											
RE100-49-8303 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)						RE (-)		Optional	
 49 APU1 Eff: 28-Aug-2020											
RE100-49-8303 Rev 3		Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)						T (-)		Optional	
 49 APU1 Eff: 01-Sep-2020											
RE100-49-8303 Rev 4		Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)						T (A/R)		Optional	
 49 APU1 Eff: 18-May-2022											
RE100-49-8360 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet PN M24243/6A401H with PN 627-504-9209 on Engines RE100[CS], RE100[LJ], and RE100[XL]						T (At Next Access)		Cat. 2 - Recommended	
 49 APU1 (AVG MAN HRS: 1)											
RE100-49-8360 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet PN M24243/6A401H with PN 627-504-9209 on RE100 Engine Models						RE (-)		Cat. 2 - Recommended	
 49 APU1 Eff: 29-Mar-2022 (AVG MAN HRS: 1)											
RE100-49-8363		Airborne Auxiliary Power - Gas Turbine Engine - Replace Inlet Housing PN 3810880-1/-2 with PN 70724596-1 or PN 70724596-2, Gearbox Housing PN 3863409-6 with PN 70724597-1, Gearbox Housing PN 3863409-5 with PN 70724597-2 and Gearbox Housing PN 3863409-4 with PN 70724597-3 on the RE100 Auxiliary Power Unit (APU)						RE (-)		Optional	
 49 APU1 Eff: 10-May-2022											

OK-ECR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-ECR,SN 560-6198

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
RE100-49-8363 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Replace Inlet Housing PN 3810880-1/-2 with PN 70724596-1 or PN 70724596-2, Gearbox Housing PN 3863409-6 with PN 70724597-1, Gearbox Housing PN 3863409-5 with PN 70724597-2 and Gearbox Housing PN 3863409-4 with PN 70724597-3 on the RE100 Auxiliary Power Unit (APU)						T (A/R)		Optional	
	49 APU1										
	Eff: 04-Aug-2022										
	Note: EFFECTIVITY: Refer to Par. 1.A. of this SB for more information.										
SIL APU-152		Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel						RE (-)		Service Information Letter	
	49 APU1										
	Eff: 18-Jul-2008										
SIL APU-152 Rev 1		Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel						RE (-)		Service Information Letter	
	49 APU1										
	Eff: 24-Jul-2009										
SIL APU-152 Rev 2		Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel						RE (-)		Service Information Letter	
	49 APU1										
	Eff: 30-Nov-2010										
SIL APU-152 Rev 3		Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel						RE (-)		Service Information Letter	
	49 APU1										
	Eff: 19-Feb-2015										
SIL APU-152 Rev 4		Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel						T (A/R)		Service Information Letter	
	49 APU1										
	Eff: 08-Feb-2018										
SIL APU-7		Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)						RE (-)		Service Information Letter	
	49 APU1										
SIL APU-7 Rev 1		Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)						RE (-)		Service Information Letter	
	49 APU1										
	Eff: 03-Mar-1988										
SIL APU-7 Rev 2		Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)						T (A/R)		Service Information Letter	
	49 APU1										
	Eff: 02-Mar-2015										
SIL APU-95 Rev 1		Uncommanded Protective Shutdown of the Auxiliary Power Unit (APU) with High Oil Temperature (HOT) Identified						RE (-)		Cancelled	
	49 APU1										
	Eff: 13-Jul-2020										
SIL D201701000026		Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine Worksheet for 36-100, 36-150, RE100, and RE220 APUs						RE (-)		Service Information Letter	
	49 APU1										
	Eff: 30-Jan-2017										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
 SIL D201701000026 Rev 1 49 APU1 Eff: 23-Jan-2018	Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine Worksheet for 36-100, 36-150, RE100, and RE220 APUs						T (-)		Service Information Letter	
					Mos					
					Hrs					
					APUS					
 SIL D201701000026 Rev 2 49 APU1 Eff: 21-Mar-2018	Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine worksheet for 36-100, 36-150, RE100, and RE220 APUs						T (A/R)		Service Information Letter	
					Mos					
					Hrs					
					APUS					
 SIL No. APU-49 Rev 10 49 APU1	Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)						RE (-)		Service Information Letter	
					Mos					
					Hrs					
					APUS					
	Note: COMPLIANCE: Every Aircraft 'A' check or every 500 APU hours or per AMM or MM criteria (customer option).									
 SIL No. APU-49 Rev 11 49 APU1	Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)						RE (-)		Service Information Letter	
					Mos					
					Hrs					
					APUS					
	Note: Analyst/operator will need to manually set the calendar start. COMPLIANCE: Every Aircraft 'A' check or every 500 APU hours or per AMM or MM criteria (customer option).									
 SIL No. APU-49 Rev 12 49 APU1	Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)						RE (-)		Service Information Letter	
					Mos					
					Hrs					
					APUS					
	Note: COMPLIANCE: First and subsequent oil and filter sample. Every Aircraft 'A' check or every 500 APU hours or per AMM or MM criteria (customer option).									
 SIL No. APU-49 Rev 13 49 APU1 Eff: 23-Nov-2023	Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APU)						T (A/R)		Service Information Letter	
					Mos					
					Hrs					
					APUS					
 SIL No. APU-49 Rev 9 49 APU1	Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)						RE (-)		Service Information Letter	
					Mos					
					Hrs					
					APUS					
	Note: The SOAP and filter analysis program was initially limited to the operators of the GTCP36-100/-150 Series Auxiliary Power Units enrolled in the Honeywell Engines, Systems & Services APU Maintenance Service Plan (MSP). The program is now offered to all operators of the Honeywell GTCP36-100/-150, RE100 and RE220 Series APUs.									
 SL560XL-49-09 49 A/F Eff: 08-Apr-2011	Transmittal of Honeywell Service Bulletin RE100-49-7992 Airborne Auxiliary Power - Gas Turbine Engine - Remove and Replace Electronic Control Unit, PN 2119552-2 or PN 2119552-3, with Electronic Control Unit, PN 2119552-4						RE (-)		Informational	
					Mos					
					Hrs					
					Ldg					
 SL560XL-49-13 49 A/F Eff: 08-May-2018	Auxiliary Power - Transmittal of Honeywell Service Bulletin RE100-49-8250 Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Module, PN 3881825-1 with PN 3881825-2, for the RE100[CS] and RE100[XL] Auxiliary Power Unit (APU)						T (A/R)		Informational, Service Letter	
					Mos					
					Hrs					
					Ldg					
 SL560XL-49-14 49 A/F Eff: 13-Mar-2023	Auxiliary Power - Transmittal of Honeywell Service Bulletin RE100-49-8364 Auxiliary Airborne - Gas Turbine Engine - Replace Wiring Harness PN 3888395-2 with PN 3888395-3 on the RE100[XL] Auxiliary Power Unit (APU)						T (A/R)		Optional	
					Mos					
					Hrs					
					Ldg					

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
▼ 52 - DOORS												
	52 A/F 9522-13 NSN	Acoustic Lower Aft Seal						RE (O/C)				
		New	0			Mos	29-Oct-2015					
			0			Hrs	0					
			0			Ldg	0					
	52 A/F 9522-15 NSN	Acoustic Lower Fwd Seal						RE (O/C)				
		New	0			Mos	29-Oct-2015					
			0			Hrs	0					
			0			Ldg	0					
	52 A/F 9522-11 NSN	Acoustic Upper Seal						RE (O/C)				
		New	0			Mos	29-Oct-2015					
			0			Hrs	0					
			0			Ldg	0					
	52 A/F Unknown Unknown	Cabin Door Primary Inflatable Pressure Seal						RE (O/C)				
						Mos	29-Oct-2015					
						Hrs	0					
						Ldg	0					
	52 A/F Unknown Unknown	Cabin Entrance Door Warning (SC046) Switch						RE (O/C)				
						Mos	29-Oct-2015					
						Hrs	0					
						Ldg	0					
	52 A/F 8-405-04 B71632	Emergency Exit Switch						RE (O/C)				
		New	0			Mos	29-Oct-2015					
			0			Hrs	0					
			0			Ldg	0					
12-20-52-6401		Door Keyed Cam Lock Lubrication						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	52 A/F (ZONE: 211, 212, 323, 331, 810, 811, 831) (SOURCE: 560 XL MM Section 5-10-02)	5-12-01					Mos	31-Oct-2024	12	-/+1m	(31-Oct-2025)	11.7 Months (+30 Days)
							Hrs	3308:54				
							Ldg	2,570				
52-10-00-2100		Cabin Door Seals General Visual Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	52 A/F (ZONE: 810) (SOURCE: 560 XL MM Section 5-10-02)	5-12-01					Mos	31-Oct-2024	12	-/+1m	(31-Oct-2025)	11.7 Months (+30 Days)
							Hrs	3308:54				
							Ldg	2,570				
52-10-00-2200		Cabin Door Assembly Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS, MSG-3 Structures Inspection Tasks			
	52 A/F (ZONE: 810, 811) (SOURCE: 560 XL MM Section 5-10-02, 5-10-03) Note: NOTE: It is recommended you do this task at the same time as Task 12-20-52-6400	5-12-06					Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
							Hrs	3048:30				
							Ldg	2,362				
52-10-00-2200		Cabin Door Assembly Detailed Inspection.						RE	Airworthiness Limitations Inspection Time Limits			
	52 A/F (ZONE: 810, 811) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)	4-12-ME					Mos					
							Hrs	15,000		(15000)	11683:53 Hrs	
							Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
52-20-00-2200	Emergency Exit Door Assembly Detailed Inspection and Operational Check						RE	05-10-01, 05-10-02, Category 6, Category 8, Category 9		
 52 A/F	5-12-03				Mos	09-Oct-2023	24	-/+1m (31-Oct-2025)		11.7 Months (+30 Days)
	MRBR Task:52-20-00-201, MRBR Task:52-20-00-202, MRBR Task:52-20-00-203, MRBR Task:52-20-00-701, MRBR Task:52-20-00-702 (ZONE: 820, 821) (SOURCE: 560XL MM)				Hrs	3048:30				
					Ldg	2,362				
52-20-00-2200	Emergency Exit Door Assembly Detailed Inspection and Operational Check						RE	04-10-01, 04-10-02, Airworthiness Limitations Inspection Time Limits, Category 6, Category 8, Category 9		≈11-Feb-2041
 52 A/F	4-12-ME				Mos					
	MRBR Task:52-20-00-201, MRBR Task:52-20-00-202, MRBR Task:52-20-00-203, MRBR Task:52-20-00-701, MRBR Task:52-20-00-702 (ZONE: 820, 821) (SOURCE: 560XL MM)				Hrs	15,000		(15000)		11683:53 Hrs
					Ldg					
52-20-00-2201	Emergency Exit Door Internal Detailed Inspection						REMSG-3 Structures Inspection Tasks			
 52 A/F	5-12-16				Mos	09-Oct-2023	96	-/+1m (31-Oct-2031)		7 Years (+30 Days)
	(ZONE: 820) (Tol. Adjustment: 20d) (SOURCE: 560 XL MM Section 5-10-03)				Hrs	3048:30				
					Ldg	2,362				
52-30-00-2200	Baggage Door Assembly Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 52 A/F	5-12-06				Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)		3 Years (+30 Days)
	(ZONE: 830, 831) (UPDATE NOTE: Found Three Baggage door latch Spings U/S for Replacement details Refer order: 101047822. Found Both Baggage Door Cable Boots Torn Apart for Replacement Details Refer Order: 101047824) (SOURCE: 560 XL MM Section 5-10-02)				Hrs	3048:30				
					Ldg	2,362				
560XL-52-08	Doors - Cabin Vent Door Solenoid Valve Replacement and Operation Improvement						RE (-)	Recommended		
 52 A/F	Eff: 22-Aug-2000 Not Applicable				Mos	13-Sep-2021				
					Hrs					
					Ldg					
SL560XL-52-07	Exterior Door Switch Improvement						RE (-)	Informational		
 52 A/F	Eff: 03-Mar-2011				Mos					
					Hrs					
					Ldg					
SL560XL-52-08	Doors - Cabin Door Lintel Fastener Verification						RE (-)	Recommended		
 52 A/F	Eff: 14-May-2020 Complied With				Mos	29-Jul-2021				
	(AVG MAN HRS: 1)				Hrs	2169:34				
	Note: COMPLIANCE: RECOMMENDED. This service document should be accomplished within 6 months of receipt of this service letter.				Ldg	1,654				
SL560XL-52-09	Doors - Cabin Entry Door Fastener Verification						RE (-)	Service Letter		
 52 A/F	Eff: 08-Dec-2017 Complied With				Mos	07-Nov-2018				
	(AVG MAN HRS: 2)				Hrs	1230:36				
					Ldg	1,009				
SL560XL-52-11	Doors - Installation of Protective Sleeve on the Cabin Entry Door Step Light Wire Harness Assembly						RE (-)	Recommended		
 52 A/F	Eff: 17-Jul-2023				Mos					
	(AVG MAN HRS: 2)				Hrs					
					Ldg					
▼ 53 - FUSELAGE										
	Nose Landing Gear Actuator Fitting Assy						RE (O/C)			
 53 A/F	Unknown				Mos	29-Oct-2015				
	Unknown				Hrs	0				
					Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time Remaining	
SEQ	PN/SN	MOC Note or Component Condition							DUE		
Radome Assembly											
	53 A/F Unknown Unknown					Mos	29-Oct-2015	RE (O/C)			
						Hrs	0				
						Ldg	0				
53-00-00-2100	Left Fuselage Fairing Internal Zonal General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks			
	53 A/F	5-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
						Hrs	3048:30				
		MRBR Task:53-100-03 (ZONE: 153, 163, 165, 313) (SOURCE: 560 XL MM Section 5-10-04)				Ldg	2,362				
53-00-00-2100	Right Fuselage Fairing Internal Zonal General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks			
	53 A/F	5-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
						Hrs	3048:30				
		MRBR Task:53-100-03 (ZONE: 154, 164, 166, 314) (SOURCE: 560 XL MM Section 5-10-04)				Ldg	2,362				
53-00-00-2101	Fuselage and Fairing External Zonal General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks			
	53 A/F	5-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
						Hrs	3048:30				
		MRBR Task:53-200-03, MRBR Task:53-100-05 (ZONE: 155, 167, 169, 315, 156, 168, 170, 316) (SOURCE: 560XL MM) Note: Zones Cont: 111, 143, 144, 213, 214, 223, 224, 253, 254, 263, 264, 153, 154, 163, 164, 165, 166, 263, 264. NOTE: It is recommended you do this task at the same time as Task 53-00-00-2201				Ldg	2,362				
53-00-00-2102	Communication and Navigation Antenna Mounting Corrosion General Visual Inspection						RE	05-10-01, 05-10-03			
	53 A/F	5-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
						Hrs	3048:30				
		MRBR Task:53-20-01-002 (ZONE: 263, 264) (Tol. Adjustment: -1420d) (SOURCE: 560XL MM) Note: This is a CPCP Task				Ldg	2,362				
53-00-00-2201	Forward and Aft Lower Fairing External L/HIRF Detailed Inspection						RE	MSG-3 L/HIRF Inspection Tasks			
	53 A/F	5-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
		(ZONE: 155, 156, 315, 316) (UPDATE NOTE: Several Corrosion Spots on Fuselage, Right and Left Lower Forward Fairings refer to WO: 101051618) (SOURCE: 560 XL MM Section 5-10-06)				Hrs	3048:30				
		Note: NOTE: It is recommended you do this task at the same time as Task 53-00-00-2101				Ldg	2,362				
53-00-00-9600	Nose Landing Gear Trunnion Support Assembly						RE	Airworthiness Limitations Inspection Time Limits			≈17-Sep-2072
	53 A/F 6613020-63 0059 (ZONE: 710) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)	Left				0	Mos	29-Oct-2015			
		New				0	Hrs	0			
						0	Ldg	0	25,500	25,500	22,924 Ldg
53-00-00-9600	Nose Landing Gear Trunnion Support Assembly						RE	Airworthiness Limitations Inspection Time Limits			≈17-Sep-2072
	53 A/F 6613020-64 121923-013 (ZONE: 710) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)	Right				0	Mos	29-Oct-2015			
		New				0	Hrs	0			
						0	Ldg	0	25,500	25,500	22,924 Ldg
53-00-00-9601	Nose Landing Gear Actuator Fitting Assembly						RE	Airworthiness Limitations Inspection Time Limits			≈17-Sep-2072
	53 A/F 6211191-3 6198 (ZONE: 710) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)	New				0	Mos	29-Oct-2015			
						0	Hrs	0			
						0	Ldg	0	25,500	25,500	22,924 Ldg
53-10-00-2100	Nose Landing Gear Wheel Well and Door Internal Zonal General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks			
	53 A/F	5-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
						Hrs	3048:30				
		MRBR Task:32-700-01 (ZONE: 710) (UPDATE NOTE: Found Carbon Missing On Several Sports. Refer to Order: 101047883) (SOURCE: 560 XL MM Section 5-10-04) Note: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-2101, 32-00-00-7100, and 57-10-00-2100				Ldg	2,362				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
53-10-00-2101		Nose Section Internal Zonal General Visual Inspection and Restoration						RE	05-10-01, 05-10-04, 05-10-05		
	53 A/F	5-12-13					Mos	17-Dec-2021	72	-/+1m (29-Oct-2027)	3 Years (+31 Days)
		MRBR Task:211-102E, MRBR Task:212-102E, MRBR Task:221-102E, MRBR Task:222-102E, MRBR Task:53-200-01, MRBR Task:112-001, MRBR Task:211-001, MRBR Task:212-001, MRBR Task:221-001, MRBR Task:222-001 (ZONE: 110, 211, 212, 221, 222) (Tol. Adjustment: -48d) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 13 IAW AMM 560XL (REV 46) CHAPTER 5-12-13 (REV 46)) (SOURCE: 560XL MM)					Hrs	2295:34			
		Note: NOTE: It is recommended you do this task at the same time as Tasks 53-10-00-2102 and 53-10-00-2103					Ldg	1,748			
53-10-00-2102		Nose Avionics Components Wiring and Bulkhead Connectors Standalone EZAP General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks		
	53 A/F	5-12-13					Mos	17-Dec-2021	72	-/+1m (29-Oct-2027)	3 Years (+31 Days)
		(ZONE: 211, 212, 221, 222) (Tol. Adjustment: -48d) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 13 IAW AMM 560XL (REV 46) CHAPTER 5-12-13 (REV 46)) (SOURCE: 560 XL MM Section 5-10-05)					Hrs	2295:34			
		Note: NOTE: It is recommended you do this task at the same time as Tasks 53-10-00-2101 and 53-10-00-2103					Ldg	1,748			
53-10-00-2103		Nose Avionics L/HIRF Standalone General Visual Inspection (Airplanes -5001 thru -6000)						RE (N/A)	MSG-3 L/HIRF Inspection Tasks		
	53 A/F						Mos				
		(ZONE: 211, 212) (SOURCE: 560 XL MM Section 5-10-06)					Hrs				
							Ldg				
53-10-00-2200		Nose Landing Gear and Wheel Well Structure and Corrosion General Visual and Detailed Inspection						REMSG-3 Structures Inspection Tasks			
	53 A/F	5-12-01					Mos	31-Oct-2024	12	-/+1m (31-Oct-2025)	11.7 Months (+30 Days)
		(ZONE: 710, 711) (SOURCE: 560 XL MM Section 5-10-03)					Hrs	3308:54			
		Note: NOTE: This is a CPCP Task					Ldg	2,570			
53-10-00-2201		Nose Structure Internal Detailed Inspection						REMSG-3 Structures Inspection Tasks			
	53 A/F	5-12-16					Mos	09-Oct-2023	96	-/+1m (31-Oct-2031)	7 Years (+30 Days)
		(ZONE: 110, 211, 212, 221, 222) (Tol. Adjustment: 20d) (SOURCE: 560 XL MM Section 5-10-03)					Hrs	3048:30			
							Ldg	2,362			
53-10-00-2202		Nose Non-Metallic Structure (Radome, Door Drip Caps) Internal Detailed Inspection						REMSG-3 Structures Inspection Tasks			
	53 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)
		(ZONE: 110,211, 212, 221, 222) (SOURCE: 560 XL MM Section 5-10-03)					Hrs	3048:30			
		Note: NOTE: It is recommended you do this task at the same time as Task 53-10-00-2203					Ldg	2,362			
53-10-00-2203		Radome Diverter Strips L/HIRF Detailed Inspection						RE	MSG-3 L/HIRF Inspection Tasks		
	53 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)
		(ZONE: 111) (SOURCE: 560 XL MM Section 5-10-06)					Hrs	3048:30			
		Note: NOTE: It is recommended you do this task at the same time as Task 53-10-00-2202					Ldg	2,362			
53-10-11-2200		Lower Aft Cabin Internal (Below Externally Serviced Toilet) Structural and Corrosion (Borescope) Special Detailed Inspection						REMSG-3 Structures Inspection Tasks			
	53 A/F	5-12-03					Mos	09-Oct-2023	24	-/+1m (31-Oct-2025)	11.7 Months (+30 Days)
		(ZONE: 172) (SOURCE: 560 XL MM Section 5-10-03)					Hrs	3048:30			
		Note: NOTE: This is a CPCP Task. NOTE: It is recommended you do this task at the same time as Task 38-30-02-2200.					Ldg	2,362			
53-10-11-2201		Aft Cabin Lower Skin (Below Drop Aisle) Internal Structural and Corrosion Detailed Inspection						REMSG-3 Structures Inspection Tasks			
	53 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)
		(ZONE: 151, 152, 161, 162, 171, 172) (SOURCE: 560 XL MM Section 5-10-03)					Hrs	3048:30			
		Note: NOTE: This is a CPCP Task					Ldg	2,362			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
53-10-11-2202	Lower Aft Cabin Internal (Below Carry-Out Toilet) Structural and Corrosion Detailed Inspection								REMSG-3 Structures Inspection Tasks	
 53 A/F	5-12-03					Mos	17-Dec-2021	24	-/+1m (31-Oct-2025)	11.7 Months (+30 Days)
	(ZONE: 171) (Tol. Adjustment: -23d) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 03 IAW AMM 560XL (REV 46) CHAPTER 5-12-03 (REV 46) PERFORMED TASK 12-20-27-6403 Horizontal Stabilizer Scissor Fitting Bolts and Aft Pivot Bolts Lubrication IAW MODEL 560XL MAINTENANCEMANUAL REV.46 CH-12-20-27.PERFORMED PRESSURIZATION SYSTEM OPERATIONAL AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV. 46, MAY. 2019, CHAPTER:21-30-00-7200- NO FAULTS FOUNDTASK 23-70-00-7200 "COCKPIT VOICE RECORDER UNDERWATER LOCATING DEVICE FUNCTIONAL CHECK" WAS PERFORMED I.A.W. C560XL MM REV46.NO FAULTS FOUND. TEST WAS SATISFACTORY.ULBP/N: 266-E5542-00S/N: ULB022434EXP. DATE: MAY 2025VOLT: 3.37 VDC; FOUND OKTASK 24-32-00 -7205 "Securaplane Standby Battery (Energy Level Test)-Functional Check" WAS PERFORMED I.A.W. C560XL MM REV46 CHAPTER24-32-00 REV46. TEST WAS SATISFACTORY.BATTERY P/N: 100-2410-04S/N: 1075PERFORMED TASK 31-30-04-7200 FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON FUNCTIONAL CHECK I.A.W. MODEL 560XL MM REV46 CHAPTER31-30-04 REV 46. FUNCTIONAL CHECK FOUND SATISFACTORY.PING TEST RESULTS: 3,36VULB P/N: 266E5542-00 S/N: ULB039730PERFORMED TASK 33-40-00-7200 TAIL LIGHT NAVIGATION ASSEMBLY FUNCTIONAL CHECK IAW AMM 560XL (REV 46); NO FAULT FOUND.PERFORMED TASK 33-50-00-7200 EMERGENCY BATTERY PACK(S) (CAPACITY CHECK) FUNCTIONAL CHECK IAW CESSNA C560XLS+ AMM (REV.46 - MAY01/19).) (SOURCE: 560 XL MM Section 5-10-03)				Hrs	2295:34				
	Note: NOTE: This is a CPCP Task.					Ldg	1,748			
53-10-11-2501	Forward Pressure Bulkhead (Eddy Current) Special Detailed Inspection								T	Airworthiness Limitations Inspection Time Limits
 53 A/F	4-12-MD					Mos	29-Oct-2015	120	(31-Oct-2025)	11.7 Months
	(ZONE: 141, 142, 241, 242) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs	0	6,000	(6000)	2683:53 Hrs
						Ldg	0			
53-10-11-2502	Aft Pressure Bulkhead General Visual Inspection								RE	Airworthiness Limitations Inspection Time Limits
 53 A/F	4-12-ME					Mos				≈11-Feb-2041
	(ZONE: 171, 172, 261, 262) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs	15,000		(15000)	11683:53 Hrs
						Ldg				
53-10-12-2100	Baggage Door and Forward Tailcone Internal Zonal General Visual Inspection								RE	MSG-3 Zonal Inspection Tasks
 53 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)
	MRBR Task:53-300-01 (ZONE: 311, 312) (SOURCE: 560 XL MM Section 5-10-04)					Hrs	3048:30			
	Note: NOTE: It is recommended you do this task at the same time as Tasks 49-00-00-2100, 53-10-12-2102, 53-10-12-2103, 53-10-12-2104, and 53-10-12-2200					Ldg	2,362			
53-10-12-2101	Tailcone External Zonal General Visual Inspection								RE	MSG-3 Zonal Inspection Tasks
 53 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)
	MRBR Task:53-300-02 (ZONE: 317, 318, 323, 324) (UPDATE NOTE: Several Nutplates On Tailcones Stinger Corroded refer to WO: 101051612. Several corrosion spots on RH Ventral Strak Refer to WO: 101051614) (SOURCE: 560 XL MM Section 5-10-04)					Hrs	3048:30			
						Ldg	2,362			
53-10-12-2102	Auxiliary Power Unit Enclosure and Stinger Internal Zonal General Visual Inspection and Restoration								RE	05-10-01, 05-10-04, 05-10-05
 53 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)
	MRBR Task:53-300-03 (ZONE: 321, 322) (UPDATE NOTE: Lower Stinger Doubler Was found Sheared Off. Refer to WO: 101047739) (SOURCE: 560XL MM)					Hrs	3048:30			
	Note: NOTE: It is recommended you do this task at the same time as Tasks 49-00-00-2100, 53-10-12-2100, 53-10-12-2103, 53-10-12-2104, and 53-10-12-2200					Ldg	2,362			
53-10-12-2103	Forward Tailcone Avionics Components, Wire Bundles and Connectors Standalone EZAP General Visual Inspection								RE	MSG-3 EZAP Inspection Tasks
 53 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)
	(ZONE: 311, 312) (SOURCE: 560 XL MM Section 5-10-05)					Hrs	3048:30			
	Note: NOTE: It is recommended you do this task at the same time as Tasks 49-00-00-2100, 53-10-12-2100, 53-10-12-2102, 53-10-12-2104, and 53-10-12-2200					Ldg	2,362			
53-10-12-2104	Auxiliary Power Unit Generator Power Feeder Cables Standalone EZAP General Visual Inspection								RE	MSG-3 EZAP Inspection Tasks
 53 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)
	(ZONE: 321, 322) (SOURCE: 560 XL MM Section 5-10-05)					Hrs	3048:30			
	Note: NOTE: It is recommended you do this task at the same time as Tasks 49-00-00-2100, 53-10-12-2100, 53-10-12-2102, 53-10-12-2103, and 53-10-12-2200					Ldg	2,362			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
53-10-12-2200	Auxiliary Power Unit Generator, Auxiliary Power Unit Generator Control Unit and Left / Right Engine Generator Control Unit L/HIRF Detailed Inspection						RE	MSG-3 L/HIRF Inspection Tasks		
 53 A/F	5-12-06					Mos 09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)	
	(ZONE: 321, 322) (SOURCE: 560 XL MM Section 5-10-06)					Hrs 3048:30				
	Note: NOTE: It is recommended you do this task at the same time as Tasks 49-00-00-2100, 53-10-12-2100, 53-10-12-2102, 53-10-12-2103, and 53-10-12-2104					Ldg 2,362				
53-20-00-2100	Cockpit Internal (Below Floorline) Zonal General Visual Inspection and Restoration						RE	05-10-01, 05-10-04, 05-10-05		
 53 A/F	5-12-13					Mos 17-Dec-2021	72	-/+1m (29-Oct-2027)	3 Years (+31 Days)	
	MRBR Task:53-100-01, MRBR Task:141-001, MRBR Task:142-001, MRBR Task:142-102E, MRBR Task:141-102E (ZONE: 141, 142) (Tol. Adjustment: -48d) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 13 IAW AMM 560XL (REV 46) CHAPTER 5-12-13 (REV 46)) (SOURCE: 560XL MM)					Hrs 2295:34				
	Note: NOTE: It is recommended you do this task at the same time as Task 53-20-00-2102					Ldg 1,748				
53-20-00-2101	Cockpit Internal (Above Floorline) Zonal General Visual Inspection and Restoration						RE	05-10-01, 05-10-04, 05-10-05		
 53 A/F	5-12-16					Mos 09-Oct-2023	96	-/+1m (31-Oct-2031)	7 Years (+30 Days)	
	MRBR Task:53-200-02, MRBR Task:235-001, MRBR Task:236-001, MRBR Task:241-001, MRBR Task:242-001, MRBR Task:245-001, MRBR Task:246-001, MRBR Task:235-102E, MRBR Task:236-102E, MRBR Task:245-102E, MRBR Task:246-102E (ZONE: 235, 236, 241, 242, 245, 246) (Tol. Adjustment: 20d) (SOURCE: 560XL MM)					Hrs 3048:30				
	Note: NOTE: It is recommended you do this task at the same time as Tasks 53-20-00-2103, 53-20-00-2104, 53-30-00-2101, and 56-11-00-2204					Ldg 2,362				
53-20-00-2102	Cockpit Wire Bundles Standalone EZAP General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks		
 53 A/F	5-12-13					Mos 17-Dec-2021	72	-/+1m (29-Oct-2027)	3 Years (+31 Days)	
	(ZONE: 141, 142) (Tol. Adjustment: -48d) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 13 IAW AMM 560XL (REV 46) CHAPTER 5-12-13 (REV 46)) (SOURCE: 560 XL MM Section 5-10-05)					Hrs 2295:34				
	Note: NOTE: It is recommended you do this task at the same time as Task 53-20-00-2100					Ldg 1,748				
53-20-00-2103	Cockpit Avionics Components and Wire Bundles Standalone EZAP General Visual Inspection						RE	MSG-3 EZAP Inspection Tasks		
 53 A/F	5-12-16					Mos 09-Oct-2023	96	-/+1m (31-Oct-2031)	7 Years (+30 Days)	
	(ZONE: 235, 236, 245, 246) (Tol. Adjustment: 20d) (SOURCE: 560 XL MM Section 5-10-05)					Hrs 3048:30				
	Note: NOTE: It is recommended you do this task at the same time as Tasks 53-20-00-2101, 53-20-00-2104, 53-30-00-2101, and 56-11-00-2204					Ldg 2,362				
53-20-00-2104	Cockpit Avionics Control Head L/HIRF Standalone General Visual Inspection						RE	MSG-3 L/HIRF Inspection Tasks		
 53 A/F	5-12-16					Mos 09-Oct-2023	96	-/+1m (31-Oct-2031)	7 Years (+30 Days)	
	(ZONE: 235, 236) (Tol. Adjustment: 20d) (SOURCE: 560 XL MM Section 5-10-06)					Hrs 3048:30				
	Note: NOTE: It is recommended you do this task at the same time as Tasks 53-20-00-2101, 53-20-00-2103, 53-30-00-2101, and 56-11-00-2204					Ldg 2,362				
53-30-00-2100	Cabin Internal Zonal General Visual Inspection and Restoration						RE	05-10-01, 05-10-04, 05-10-05		
 53 A/F	5-12-16					Mos 09-Oct-2023	96	-/+1m (31-Oct-2031)	7 Years (+30 Days)	
	MRBR Task:812-001 , MRBR Task:53-100-02, MRBR Task:161-001, MRBR Task:162-001, MRBR Task:171-001, MRBR Task:251-001, MRBR Task:252-001, MRBR Task:261-001, MRBR Task:262-001, MRBR Task:822-001, MRBR Task:161-101E, MRBR Task:162-101E, MRBR Task:171-101E, MRBR Task:172-101E, MRBR Task:812-101E, MRBR Task:822-101E, MRBR Task:172-001 (ZONE: 161, 162, 171, 172, 251, 252, 261, 262, 810, 820) (Tol. Adjustment: 20d) (UPDATE NOTE: Found Gouge In AFT Pressure Bulkhead. Refer to Order 101049105) (SOURCE: 560XL MM)					Hrs 3048:30				
						Ldg 2,362				
53-30-00-2101	Forward Cabin (Below Floorline) Internal General Visual Inspection and Restoration						RE	05-10-01, 05-10-04, 05-10-05		
 53 A/F	5-12-16					Mos 09-Oct-2023	96	-/+1m (31-Oct-2031)	7 Years (+30 Days)	
	MRBR Task:235-102E, MRBR Task:236-102E, MRBR Task:245-102E, MRBR Task:246-102E, MRBR Task:53-100-06, MRBR Task:151-001, MRBR Task:152-001 (ZONE: 151, 152) (Tol. Adjustment: 20d) (SOURCE: 560XL MM)					Hrs 3048:30				
	Note: NOTE: It is recommended you do this task at the same time as Tasks 53-20-00-2101, 53-20-00-2103, 53-20-00-2104, and 56-11-00-2204					Ldg 2,362				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
53-30-00-2200	Elevator and Elevator Trim Control System Support Structural Detailed Inspection								REMSG-3 Structures Inspection Tasks	
 53 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)
	(ZONE: 141, 142, 241, 242, 311, 312, 321, 322, 351, 352, 340, 151, 152, 161, 162, 171, 172) (SOURCE: 560 XL MM Section 5-10-03)					Hrs	3048:30			
	Note: NOTE: It is recommended you do this task at the same time as Tasks 27-31-00-2200 and 55-20-00-2200					Ldg	2,362			
53-30-01-2100	Upper Fuselage Skin from Right Stringer 13 to Left Stringer 13 General Visual Inspection								RE Airworthiness Limitations Inspection Time Limits	≈30-Apr-2038
 53 A/F	4-12-MJ					Mos				
	(ZONE: 213, 243, 253, 263, 323, 214, 244, 254, 264, 324) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs	13,000		(13000)	9683:53 Hrs
						Ldg				
53-30-01-2101	Lower Fuselage Skin from Right Stringer 13 to Left Stringer 13 General Visual Inspection								RE Airworthiness Limitations Inspection Time Limits	≈11-Feb-2041
 53 A/F	4-12-ME					Mos				
	(ZONE: 143, 151, 161, 171, 213, 144, 152, 162, 172, 214) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs	15,000		(15000)	11683:53 Hrs
						Ldg				
53-30-01-2500	Fuselage External Surface (Eddy Current) Special Detailed Inspection								REMSG-3 Structures Inspection Tasks	≈04-Apr-2030
 53 A/F	5-12-25					Mos				
	(ZONE: 143, 144, 223, 224, 243, 244, 253, 254, 263, 264) (SOURCE: 560 XL MM Section 5-10-03)					Hrs	7,200		-/+25 (7200)	3883:53 Hrs (+25)
	Note: Zone cont.: 317, 318, 323, 324					Ldg				
53-30-01-2501	Upper Fuselage Skin Splice at BL 0.00 (Eddy Current) Special Detailed Inspection								RE Airworthiness Limitations Inspection Time Limits	≈11-Feb-2041
 53 A/F	4-12-ME					Mos				
	(ZONE: 241, 242, 251, 252, 261, 262) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs	15,000		(15000)	11683:53 Hrs
						Ldg				
53-30-01-2502	Lower Fuselage Skin Splices at Stringers 13R and 13L (Eddy Current) Special Detailed Inspection								RE Airworthiness Limitations Inspection Time Limits	≈11-Feb-2041
 53 A/F	4-12-ME					Mos				
	(ZONE: 151, 161, 171, 152, 162, 172) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs	15,000		(15000)	11683:53 Hrs
						Ldg				
53-31-00-2200	Composite Ventral Strake (Coin Tap) Special Detailed Inspection								REMSG-3 Structures Inspection Tasks	
 53 A/F	5-12-16					Mos	09-Oct-2023	96	-/+1m (31-Oct-2031)	7 Years (+30 Days)
	(ZONE: 323, 324) (Tol. Adjustment: 20d) (SOURCE: 560 XL MM Section 5-10-03)					Hrs	3048:30			
						Ldg	2,362			
560XL-53-13	Nose Drip Cap Bond Inspection								RE (-) Recommended	
 53 A/F						Mos	09-Sep-2021			
Not Applicable	as per S/N					Hrs	2218:31			
						Ldg	1,685			
560XL-53-13 Rev 01	Nose Drip Cap Bond Inspection								RE (-) Mandatory	
 53 A/F						Mos	09-Sep-2021			
Eff: 05-Oct-2011 Not Applicable	as per S/N					Hrs	2218:31			
						Ldg	1,685			
560XL-53-14	Carbon Fiber Strake Modification								RE (-) Optional	
 53 A/F						Mos				
Eff: 09-Apr-2012						Hrs				
						Ldg				
560XL-53-15	Fastener Installation F.S. 115.20								RE (-) Mandatory	
 53 A/F						Mos	09-Sep-2021			
Eff: 19-Jan-2011 Not Applicable	as per S/N					Hrs	2218:31			
						Ldg	1,685			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
560XL-53-16	Stinger Drain Installation						RE (-)		Mandatory	
 53 A/F	as per S/N					Mos	09-Sep-2021			
Eff: 04-Oct-2011 Not Applicable						Hrs	2218:31			
						Ldg	1,685			
ASL560XL-53-08A	Aft Canted Bulkhead Drain Installation						RE (-)		Recommended	
 53 A/F	as per S/N					Mos	09-Sep-2021			
Not Applicable						Hrs	2218:31			
						Ldg	1,685			
ASL560XL-53-08A Rev 01	Aft Canted Bulkhead Drain Installation						RE (-)		Mandatory	
 53 A/F	as per S/N					Mos	09-Sep-2021			
Eff: 27-Jan-2011 Not Applicable						Hrs	2218:31			
						Ldg	1,685			
CIL-53-01	Fuselage - Nose Radome Guide Pin Replacement						RE (-)	Recommended, Service Letter		
 53 A/F	Different SN of Aircraft					Mos	14-Sep-2021			
Eff: 17-Dec-2020 Not Applicable						Hrs				
(AVG MAN HRS: 1.5)						Ldg				
CIL-53-01 R1	Fuselage - Nose Radome Guide Pin Replacement						RE (-)	Recommended		
 53 A/F	Different SN of Aircraft					Mos	14-Sep-2021			
Eff: 17-Mar-2021 Not Applicable						Hrs				
(AVG MAN HRS: 1.5)						Ldg				
SL560XL-53-03	Fuselage - Lightning Diverter Strip Installation/Repair Procedure Change (Radome)						T (A/R)		Informational	
 53 A/F						Mos				
Eff: 14-Aug-2001						Hrs				
						Ldg				
SL560XL-53-07	Lower Skin Assembly Fastener Inspection						RE (-)		Mandatory	
 53 A/F	as per S/N					Mos	09-Sep-2021			
Eff: 14-Apr-2009 Not Applicable						Hrs	2218:31			
						Ldg	1,685			
SL560XL-53-16	Fastener Inspection/Installation						RE (-)		Mandatory	
 53 A/F	as per S/N					Mos	09-Sep-2021			
Eff: 16-Aug-2011 Not Applicable						Hrs	2218:31			
						Ldg	1,685			
SL560XL-53-17	Dorsal Duct Inspection						RE (-)		Recommended	
 53 A/F	Different SN of Aircraft					Mos	14-Sep-2021			
Eff: 20-Nov-2012 Not Applicable						Hrs				
						Ldg				
SL560XL-53-18	Fuselage - Tailcone Missing Fastener Inspection and Installation						RE (-)		Mandatory	
 53 A/F	as per S/N					Mos	09-Sep-2021			
Eff: 13-Jan-2016 Not Applicable						Hrs	2218:31			
(AVG MAN HRS: 2.2)						Ldg	1,685			
SL560XL-53-18 Rev 01	Fuselage - Tailcone Missing Fastener Inspection and Installation						RE (-)		Mandatory	
 53 A/F	as per S/N					Mos	09-Sep-2021			
Eff: 22-Jun-2016 Not Applicable						Hrs	2218:31			
(AVG MAN HRS: 2.2)						Ldg	1,685			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-53-19	Fuselage - Empennage Fastener Verification								T (-)	Recommended
 53 A/F						Mos				
Eff: 14-May-2020						Hrs				
(AVG MAN HRS: 1)						Ldg				
Note: COMPLIANCE: RECOMMENDED. This service document should be accomplished at an Inspection Document 6.										
SL560XL-53-19 R1	Fuselage - Empennage Fastener Verification								RE (-)	Recommended
 53 A/F						Mos	17-Dec-2021			
Eff: 19-Jun-2020 Complied With						Hrs	2295:34			
(AVG MAN HRS: 1) (UPDATE Note: PERFORMED SL5650XL-53-19 INSTALED MISSING RIVETS PN: CR3223-5-05)						Ldg	1,748			
SL560XL-53-21	Fuselage - Inspection of the Tailcone Stinger Attach Nutplates for Damage								RE (-)	Recommended, Service Letter
 53 A/F						Mos				
Eff: 24-Jun-2024						Hrs				
(AVG MAN HRS: 4)						Ldg				
▼ 54 - NACELLES/PYLONS										
54-50-01-2100	Left Side Engine Cowlings and Pylons Internal and External Zonal General Visual Inspection and Restoration								RE	05-10-01, 05-10-04, 05-10-05
 54 A/F	5-12-03					Mos	09-Oct-2023	24	-/+1m (31-Oct-2025)	11.7 Months (+30 Days)
MRBR Task:71-400-01, MRBR Task:411-001, MRBR Task:412-001, MRBR Task:415-001, MRBR Task:421-001, MRBR Task:71-400-02, MRBR Task:413-001, MRBR Task:414-001, MRBR Task:431-001, MRBR Task:441-001, MRBR Task:411-101E, MRBR Task:412-101E, MRBR Task:415-101E, MRBR Task:421-101E (ZONE: 411, 413, 410, 430) (SOURCE: 560XL MM)						Hrs	3048:30			
Note: NOTE: It is recommended you do this task at the same time as Tasks 71-00-00-2100 and 71-00-00-2200						Ldg	2,362			
54-50-01-2100	Right Side Engine Cowlings and Pylons Internal and External Zonal General Visual Inspection and Restoration								RE	05-10-01, 05-10-04, 05-10-05
 54 A/F	5-12-03					Mos	09-Oct-2023	24	-/+1m (31-Oct-2025)	11.7 Months (+30 Days)
MRBR Task:71-400-01, MRBR Task:411-001, MRBR Task:412-001, MRBR Task:415-001, MRBR Task:421-001, MRBR Task:71-400-02, MRBR Task:413-001, MRBR Task:414-001, MRBR Task:431-001, MRBR Task:441-001, MRBR Task:411-101E, MRBR Task:412-101E, MRBR Task:415-101E, MRBR Task:421-101E (ZONE: 412, 414, 420, 440) (SOURCE: 560XL MM)						Hrs	3048:30			
Note: NOTE: It is recommended you do this task at the same time as Tasks 71-00-00-2100 and 71-00-00-2200						Ldg	2,362			
54-50-10-2100	Left Aft Engine Beam General Visual Inspection								RE (N/A)	Airworthiness Limitations Inspection Time Limits
 54 A/F						Mos				
(ZONE: 311, 411) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)						Hrs				
						Ldg				
54-50-10-2100	Right Aft Engine Beam General Visual Inspection								RE (N/A)	Airworthiness Limitations Inspection Time Limits
 54 A/F						Mos				
(ZONE: 312, 412) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)						Hrs				
						Ldg				
54-50-10-2500	Left Forward Engine Beam Upper Angles, Horizontal Cap Flange at BL 30.5 thru BL 42.0 (Eddy Current) Special Detailed Inspection								RE (N/A)	Airworthiness Limitations Inspection Time Limits
 54 A/F						Mos				
(ZONE: 311, 411) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)						Hrs				
						Ldg				
54-50-10-2500	Right Forward Engine Beam Upper Angles, Horizontal Cap Flange at BL 30.5 thru BL 42.0 (Eddy Current) Special Detailed Inspection								RE (N/A)	Airworthiness Limitations Inspection Time Limits
 54 A/F						Mos				
(ZONE: 312, 412) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)						Hrs				
						Ldg				
▼ 55 - STABILIZERS										
55-00-00-2200	Empennage Cove Structure and Corrosion Detailed Inspection								REMSG-3 Structures Inspection Tasks	
 55 A/F	5-12-01					Mos	31-Oct-2024	12	-/+1m (31-Oct-2025)	11.7 Months (+30 Days)
(ZONE: 321, 322, 341 353, 354) (SOURCE: 560 XL MM Section 5-10-03)						Hrs	3308:54			
Note: NOTE: This is a CPCP Task.						Ldg	2,570			

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
55-10-00-2100	Empennage External Zonal General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks		
 55 A/F	5-12-13				Mos	17-Dec-2021	72	-/+1m	(29-Oct-2027)	3 Years (+31 Days)
	MRBR Task:55-300-01 (ZONE: 341, 353, 354) (Tol. Adjustment: -48d) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 13 IAW AMM 560XL (REV 46) CHAPTER 5-12-13 (REV 46)) (SOURCE: 560XL MM)				Hrs	2295:34				
	Note: NOTE: It is recommended you do this task at the same time as Tasks 55-10-00-2200 and 55-10-00-2201				Ldg	1,748				
55-10-00-2101	Horizontal Stabilizer Surfaces Internal Zonal General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks		
 55 A/F	5-12-16				Mos	09-Oct-2023	96	-/+1m	(31-Oct-2031)	7 Years (+30 Days)
	MRBR Task:55-300-03 (ZONE: 351, 352) (Tol. Adjustment: 20d) (UPDATE NOTE: Inbound Spot corroded - Flux Valve panel corroded.) (SOURCE: 560XL MM)				Hrs	3048:30				
	Note: NOTE: It is recommended you do this task at the same time as Task 55-10-00-2900				Ldg	2,362				
55-10-00-2200	Horizontal Stabilizer Position Switches L/HIRF Detailed Inspection						RE	MSG-3 L/HIRF Inspection Tasks		
 55 A/F	5-12-13				Mos	17-Dec-2021	72	-/+1m	(29-Oct-2027)	3 Years (+31 Days)
	(ZONE: 342) (Tol. Adjustment: -48d) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 13 IAW AMM 560XL (REV 46) CHAPTER 5-12-13 (REV 46)) (SOURCE: 560 XL MM Section 5-10-06)				Hrs	2295:34				
	Note: NOTE: It is recommended you do this task at the same time as Tasks 55-10-00-2100 and 55-10-00-2201				Ldg	1,748				
55-10-00-2201	Flux Detectors L/HIRF Detailed Inspection						RE	MSG-3 L/HIRF Inspection Tasks		
 55 A/F	5-12-13				Mos	17-Dec-2021	72	-/+1m	(29-Oct-2027)	3 Years (+31 Days)
	(ZONE: 351, 352) (Tol. Adjustment: -48d) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 13 IAW AMM 560XL (REV 46) CHAPTER 5-12-13 (REV 46)) (SOURCE: 560 XL MM Section 5-10-06)				Hrs	2295:34				
	Note: NOTE: It is recommended you do this task at the same time as Tasks 55-10-00-2100 and 55-10-00-2200				Ldg	1,748				
55-10-00-2900	Internal Horizontal Stabilizer (Borescope) Special Detailed Inspection						REMSG-3 Structures Inspection Tasks			
 55 A/F	5-12-16				Mos	09-Oct-2023	96	-/+1m	(31-Oct-2031)	7 Years (+30 Days)
	(ZONE: 351, 352) (Tol. Adjustment: 20d) (SOURCE: 560 XL MM Section 5-10-03)				Hrs	3048:30				
	Note: NOTE: It is recommended you do this task at the same time as Task 55-10-00-2101				Ldg	2,362				
55-20-00-2200	Elevator Assembly Detailed Inspection						RE	05-10-01, 05-10-02, 05-10-03, Category 5		
 55 A/F	Left5-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
Unknown					Hrs	3048:30				
Unknown					Ldg	2,362				
	MRBR Task:55-20-01-001, MRBR Task:55-20-01-002 (ZONE: 354) (SOURCE: 560XL MM)									
	Note: NOTE: It is recommended you do this task at the same time as Tasks 27-31-00-2200 and 53-30-00-2200									
55-20-00-2200	Elevator Assembly Detailed Inspection						RE	05-10-01, 05-10-02, 05-10-03, Category 5		
 55 A/F	Right5-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
Unknown					Hrs	3048:30				
Unknown					Ldg	2,362				
	MRBR Task:55-20-01-001, MRBR Task:55-20-01-002 (ZONE: 353) (SOURCE: 560XL MM)									
	Note: NOTE: It is recommended you do this task at the same time as Tasks 27-31-00-2200 and 53-30-00-2200									
55-30-00-2102	Vertical Stabilizer Internal Zonal General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks		
 55 A/F	5-12-16				Mos	09-Oct-2023	96	-/+1m	(31-Oct-2031)	7 Years (+30 Days)
	MRBR Task:55-300-02 (ZONE: 340) (Tol. Adjustment: 20d) (UPDATE NOTE: Several Corrosion Spots Around H-STAB Acces Panels) (SOURCE: 560XL MM)				Hrs	3048:30				
	Note: NOTE: It is recommended you do this task at the same time as Task 55-30-00-2900				Ldg	2,362				
55-30-00-2200	Rudder and Rudder Trim Control System Structural Support Detailed Inspection						REMSG-3 Structures Inspection Tasks			
 55 A/F	5-12-06				Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
	(ZONE: 141,142,161,162,241,242,311,312,313,323,324,341) (UPDATE NOTE: Found FWD RH Upper Ruder Cable Chafed WO: 101050504) (SOURCE: 560 XL MM Section 5-10-03)				Hrs	3048:30				
	Note: NOTE: It is recommended you do this task at the same time as Task 55-40-00-2200				Ldg	2,362				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
55-30-00-2201		Vertical Stabilizer Pivot Fitting Detailed Inspection							TMSG-3 Structures Inspection Tasks	≈02-Aug-2028
	55 A/F	5-12-17								
	(ZONE: 340) (SOURCE: 560 XL MM Section 5-10-03)									
55-30-00-2500		Vertical Stabilizer Rear Spar Cap at WL 146 (Eddy Current) Special Detailed Inspection								
	55 A/F									
	(ZONE: 321, 322, 340) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)									
55-30-00-2501		Vertical Stabilizer Rear Spar Nested Angle at WL 146 (Eddy Current) Special Detailed Inspection								
	55 A/F									
	(ZONE: 321, 322, 340) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)									
55-30-00-2502		Vertical Stabilizer Rear Spar Strap at WL 146.00 (Eddy Current) Special Detailed Inspection								
	55 A/F									
	(ZONE: 321, 322, 340) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)									
55-30-00-2503		Vertical Stabilizer Forward Spar Strap at WL 150 (Eddy Current) Special Detailed Inspection								
	55 A/F									
	(ZONE: 321, 322, 340) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)									
55-30-00-2504		Vertical Stabilizer Forward Spar Strap at WL 188.00 (Eddy Current) Special Detailed Inspection								
	55 A/F									
	(ZONE: 340) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)									
55-30-00-2900		Vertical Stabilizer (Areas With Limited Access) (Borescope) Internal Special Detailed Inspection							REMSG-3 Structures Inspection Tasks	
	55 A/F	5-12-16								
	(ZONE: 340) (Tol. Adjustment: 20d) (SOURCE: 560 XL MM Section 5-10-03)									
	Note: NOTE: It is recommended you do this task at the same time as Task 55-30-00-2102									
55-40-00-2200		Rudder and Rudder Trim Tab Detailed Inspection								
	55 A/F	5-12-06								
	MRBR Task:55-40-01-001 (ZONE: 341) (UPDATE NOTE: Found Excessive Wear Freeplay in Rudder Trim Bolts) (SOURCE: 560XL MM)									
	Note: NOTE: It is recommended you do this task at the same time as Task 55-30-00-2200									
554040		Rudder Trim Tab Assembly								
	55 A/F									
	5533200-46									
	N/A									
SL560XL-55-01		Stabilizers - Pivot Fitting Inspection								
	55 A/F									
	Cancelled									
SL560XL-55-01 Rev 01		Stabilizers - Pivot Fitting Inspection								
	55 A/F									
	Cancelled									

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SL560XL-55-01 Rev 02		Stabilizers - Pivot Fitting Inspection								RE (-)	Mandatory
	55 A/F	Eff: 12-Jun-2015 Cancelled					Mos	09-Sep-2021			
							Hrs	2218:31			
							Ldg	1,685			
	Note: This service letter must be accomplished on airplanes that have attained 6,000 flight hours or more within 600 flight hours or one year from the date of receipt of the original issue of service letter. Aircraft that are under 6,000 flight hours on the date of receipt of the original issue of this service letter will need to comply with this service letter upon attaining 6,000 flight hours but not exceeding 6,600 flight hours.										
SL560XL-55-01 Rev 03		Stabilizers - Pivot Fitting Inspection (Cancelled)								RE (-)	Mandatory
	55 A/F	Eff: 09-Jun-2016 Cancelled					Mos	09-Sep-2021			
							Hrs	2218:31			
							Ldg	1,685			
	Note: NOTE: The inspection requirement previously contained in this service letter can now be found in the Phase 71 and the Inspection Document 52 inspections in the Cessna Model 560XL Maintenance Manual Revision 40. NOTE: This revision replaces the original issue of SL560XL-55-01 and previous revisions in their entirety.										
SL560XL-55-02		Stabilizers - Replacement of the Rudder Stop Block								RE (-)	Recommended, Service Letter
	55 A/F	Eff: 04-Nov-2019 Not Applicable Different SN of Aircraft					Mos	14-Sep-2021			
							Hrs				
							Ldg				
SL560XL-55-03		Stabilizers - Inspection of the Horizontal Stabilizer Upper and Lower Splice Plate Huck Bolt Fasteners								RE (-)	Recommended
	55 A/F	Eff: 16-May-2022 Not Applicable (AVG MAN HRS: 194) as per S/N of A/C					Mos	24-May-2022			
							Hrs	2577:13			
							Ldg	1,968			
SL560XL-55-03 R1		Stabilizers - Inspection of the Horizontal Stabilizer Upper and Lower Splice Plate Huck Bolt Fasteners								RE (-)	Recommended
	55 A/F	Eff: 26-Sep-2022 Not Applicable (AVG MAN HRS: 194) as per a/c S/N					Mos	05-Oct-2022			
							Hrs	2710:20			
							Ldg	2,074			
▼ 56 - WINDOWS											
		Cabin Window								RE (O/C)	
	56 A/F	Left No.2					Mos	29-Oct-2015			
	167400-03	New					Hrs	0			
	8561						Ldg	0			
		Cabin Window								RE (O/C)	
	56 A/F	Left No.3					Mos	29-Oct-2015			
	167400-03	New					Hrs	0			
	8574						Ldg	0			
		Cabin Window								RE (O/C)	
	56 A/F	Left No.4					Mos	29-Oct-2015			
	167400-03	New					Hrs	0			
	8615						Ldg	0			
		Cabin Window								RE (O/C)	
	56 A/F	Left No.5					Mos	29-Oct-2015			
	167400-03	New					Hrs	0			
	8735						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	56 A/F 167400-03 8565	Cabin Window Left No.6 New	0			Mos	29-Oct-2015	RE (O/C)			
			0			Hrs	0				
			0			Ldg	0				
	56 A/F Unknown Unknown	Cabin Window Left No.7				Mos	29-Oct-2015	RE (O/C)			
						Hrs	0				
						Ldg	0				
	56 A/F 167400-03 8543	Cabin Window Right No.2 New	0			Mos	29-Oct-2015	RE (O/C)			
			0			Hrs	0				
			0			Ldg	0				
	56 A/F 167400-03 8559	Cabin Window Right No.3 New	0			Mos	29-Oct-2015	RE (O/C)			
			0			Hrs	0				
			0			Ldg	0				
	56 A/F 167400-03 8601	Cabin Window Right No.4 New	0			Mos	29-Oct-2015	RE (O/C)			
			0			Hrs	0				
			0			Ldg	0				
	56 A/F 167400-03 8550	Cabin Window Right No.5 New	0			Mos	29-Oct-2015	RE (O/C)			
			0			Hrs	0				
			0			Ldg	0				
	56 A/F 167400-03 8535	Cabin Window Right No.6 New	0			Mos	29-Oct-2015	RE (O/C)			
			0			Hrs	0				
			0			Ldg	0				
	56 A/F Unknown Unknown	Cabin Window Right No.7				Mos	29-Oct-2015	RE (O/C)			
						Hrs	0				
						Ldg	0				
	56 A/F NP139722-7 15120H1169	Electrically Heated Cockpit Forward Side Window Left New	0			Mos	29-Oct-2015	RE (O/C)			
			0			Hrs	0				
			0			Ldg	0				
	56 A/F NP139722-8 15108H9684	Electrically Heated Cockpit Forward Side Window Right New	0			Mos	29-Oct-2015	RE (O/C)			
			0			Hrs	0				
			0			Ldg	0				
	56 A/F 167400-03 8710	Emergency Door Window Right No.1 New	0			Mos	29-Oct-2015	RE (O/C)			
			0			Hrs	0				
			0			Ldg	0				

Task No	Description								Categories	Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
	56 A/F NP139731-1 15113H0315	Main Windshield										
		Left									RE (O/C)	
	56 A/F NP139731-2 15105H9281	Main Windshield										
		Right									RE (O/C)	
	56 A/F NP139703-3 3523	Openable Cockpit Aft Side Window										
		Left									RE (O/C)	
	56 A/F NP139703-4 3424	Openable Cockpit Aft Side Window										
		Right									RE (O/C)	
56-11-00-2200		Heated Windshield Assembly Hump Seal Detailed Inspection										
	56 A/F NP139731-1 15113H0315 (ZONE: 243) (SOURCE: 560 XL MM Section 5-10-02)	Left5-12-01										
56-11-00-2200		Heated Windshield Assembly Hump Seal Detailed Inspection										
	56 A/F NP139731-2 15105H9281 (ZONE: 244) (SOURCE: 560 XL MM Section 5-10-02)	Right5-12-01										
56-11-00-2201		Cockpit Openable Aft Side Window Hinge and Latch Detailed Inspection										
	56 A/F NP139703-3 3523 (ZONE: 241) (Tol. Adjustment: -108.9 Hrs) (SOURCE: 560 XL MM Section 5-10-02)	Left5-12-07										
56-11-00-2201		Cockpit Openable Aft Side Window Hinge and Latch Detailed Inspection										
	56 A/F NP139703-4 3424 (ZONE: 242) (Tol. Adjustment: -108.9 Hrs) (SOURCE: 560 XL MM Section 5-10-02)	Right5-12-07										
56-11-00-2202		Windshield Detailed Inspection										
	56 A/F (ZONE: 241, 242, 243, 244) (SOURCE: 560 XL MM Section 5-10-03)	5-12-03										
56-11-00-2203		Windshield Retainer Detailed Inspection										
	56 A/F (ZONE: 243, 244) (Tol. Adjustment: 20d) (SOURCE: 560 XL MM Section 5-10-03)	5-12-16										

Task No		Description								Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
56-11-00-2204		Cockpit and Openable Side Window Internal Structure Detailed Inspection							REMSG-3 Structures Inspection Tasks			
	56 A/F	5-12-16					Mos	09-Oct-2023	96	-/+1m	(31-Oct-2031) 7 Years (+30 Days)	
							Hrs	3048:30				
							Ldg	2,362				
(ZONE: 241, 242, 243, 244) (Tol. Adjustment: 20d) (SOURCE: 560 XL MM Section 5-10-03) Note: NOTE: It is recommended you do this task at the same time as Tasks 53-20-00-2101, 53-20-00-2103, 53-20-00-2104, and 53-30-00-2101												
56-11-00-2207		Openable Side Cockpit Window (Transparency) Detailed Inspection							REMSG-3 Structures Inspection Tasks			
	56 A/F	Left5-12-06					Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027) 3 Years (+30 Days)	
NP139703-3							Hrs	3048:30				
3523							Ldg	2,362				
(ZONE: 241, 243) (SOURCE: 560 XL MM Section 5-10-03)												
56-11-00-2207		Openable Side Cockpit Window (Transparency) Detailed Inspection							REMSG-3 Structures Inspection Tasks			
	56 A/F	Right5-12-06					Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027) 3 Years (+30 Days)	
NP139703-4							Hrs	3048:30				
3424							Ldg	2,362				
(ZONE: 242,244) (SOURCE: 560 XL MM Section 5-10-03)												
56-11-00-7200		Heated Windshield Assembly Fastener Torque Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈09-Oct-2026
	56 A/F	Left5-12-08					Mos	17-Dec-2021				
NP139731-1							Hrs	2295:34	2,400	-/+25	(4695:34) 1379:27 Hrs (+25)	
15113H0315							Ldg	1,748				
(ZONE: 243) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 25-11-01-2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES -5002 THRU - 5555 INCORPORATINGSB560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019,CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560 XL MM Section 5-10-02)												
56-11-00-7200		Heated Windshield Assembly Fastener Torque Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈09-Oct-2026
	56 A/F	Right5-12-08					Mos	17-Dec-2021				
NP139731-2							Hrs	2295:34	2,400	-/+25	(4695:34) 1379:27 Hrs (+25)	
15105H9281							Ldg	1,748				
(ZONE: 244) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 25-11-01-2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES -5002 THRU - 5555 INCORPORATINGSB560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019,CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560 XL MM Section 5-10-02)												

Task No		Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE		Remaining
56-11-00-7201		Left Windshield Surface Seal (Mist Spray) Functional Check										
	56 A/F	Left5-12-01					Mos	31-Oct-2024	12	-/+1m	(31-Oct-2025)	11.7 Months (+30 Days)
	NP139731-1						Hrs	3308:54				
	15113H0315						Ldg	2,570				
	(ZONE: 243) (SOURCE: 560 XL MM Section 5-10-02) Note: NOTE: Operational Environment May Require Reduced Interval											
56-11-00-7201		Right Windshield Surface Seal (Mist Spray) Functional Check										
	56 A/F	Right5-12-01					Mos	31-Oct-2024	12	-/+1m	(31-Oct-2025)	11.7 Months (+30 Days)
	NP139731-2						Hrs	3308:54				
	15105H9281						Ldg	2,570				
	(ZONE: 244) (SOURCE: 560 XL MM Section 5-10-02) Note: NOTE: Operational Environment May Require Reduced Interval											
SL560XL-56-02		Windshield Delamination										
	56 A/F								T (A/R)		Informational	
	Eff: 31-Mar-2009						Mos					
							Hrs					
SL560XL-56-03		Openable Cockpit Window Hinge and Latch Inspection										
	56 A/F								RE (-)		Mandatory	
	Eff: 07-Dec-2010 Not	as per S/N					Mos	09-Sep-2021				
	Applicable						Hrs	2218:31				
▼ 57 - WINGS												
57 A/F		Flap Assy										
	Left Inboard								RE (O/C)			
	Unknown						Mos	29-Oct-2015				
	Unknown						Hrs	0				
57 A/F		Flap Assy										
	Left Outboard				0		Mos	20-Feb-2020				
	Repaired				0		Hrs	1750:25				
					0		Ldg	1,373				
57 A/F		Flap Assy										
	Right Inboard						Mos	29-Oct-2015				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
57 A/F		Flap Assy										
	Right Outboard						Mos	29-Oct-2015				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
57-00-00-2100		Left Wing External Zonal General Visual Inspection										
	57 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
							Hrs	3048:30				
							Ldg	2,362				
MRBR Task:57-500-01, MRBR Task:510-001, MRBR Task:511-001, MRBR Task:512-001, MRBR Task:521-001, MRBR Task:522-001, MRBR Task:531-001, MRBR Task:532-001, MRBR Task:542-001, MRBR Task:610-001, MRBR Task:611-001, MRBR Task:612-001, MRBR Task:621-001, MRBR Task:622-001, MRBR Task:631-001, MRBR Task:632-001, MRBR Task:641-001, MRBR Task:57-20-03-001, MRBR Task:57-50-02-001, MRBR Task:57-20-04-001 (ZONE: 511, 512, 515, 521, 522, 531, 532, 540) (UPDATE NOTE: Boost Pump Drain Placard Missing Refer to Order 101046700 for installation.) (SOURCE: 560 XL MM Section 5-10-01, 5-10-04, 5-12-06) Note: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-2101, 32-00-00-7100, and 53-10-00-2100												

Task No		Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
57-00-00-2100		Right Wing External Zonal General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks			
	57 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
							Hrs	3048:30				
							Ldg	2,362				
		MRBR Task:57-500-01, MRBR Task:510-001, MRBR Task:511-001, MRBR Task:512-001, MRBR Task:521-001, MRBR Task:522-001, MRBR Task:531-001, MRBR Task:532-001, MRBR Task:542-001, MRBR Task:610-001, MRBR Task:611-001, MRBR Task:612-001, MRBR Task:621-001, MRBR Task:622-001, MRBR Task:631-001, MRBR Task:632-001, MRBR Task:641-001, MRBR Task:57-20-03-001, MRBR Task:57-50-02-001, MRBR Task:57-20-04-001 (ZONE: 611, 612, 615, 621, 622, 631, 632, 641) (UPDATE NOTE: Boost Pump Drain Placard Missing Refer to Order 101046700 for installation.) (SOURCE: 560 XL MM Section 5-10-01, 5-10-04, 5-12-06)										
		Note: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-2101, 32-00-00-7100, and 53-10-00-2100										
57-00-00-2101		Left Wing Internal Zonal General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks			
	57 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
							Hrs	3048:30				
							Ldg	2,362				
		(ZONE: 513, 514, 515, 523, 524, 533, 534) (UPDATE NOTE: Domenuts Corroded Refer to WO: 101046520) (SOURCE: 560 XL MM Section 5-10-04)										
		Note: NOTE: It is recommended you do Task 28-42-00-7100 before you do this task.NOTE: It is recommended you do this task at the same time as Task 57-00-00-2102										
57-00-00-2101		Right Wing Internal Zonal General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks			
	57 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
							Hrs	3048:30				
							Ldg	2,362				
		(ZONE: 613, 614, 615, 623, 624, 633, 634) (UPDATE NOTE: Domenuts Corroded Refer to WO: 101046520) (SOURCE: 560 XL MM Section 5-10-04)										
		Note: NOTE: It is recommended you do Task 28-42-00-7100 before you do this task.NOTE: It is recommended you do this task at the same time as Task 57-00-00-2102										
57-00-00-2102		Left Wing Fuel Probe Wiring Harness Standalone EZAP General Visual Inspection						RE	MSG-3 EZAP Inspection Tasks			
	57 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
							Hrs	3048:30				
							Ldg	2,362				
		(ZONE: 513, 514, 515, 523, 524, 533, 534) (SOURCE: 560 XL MM Section 5-10-05)										
		Note: NOTE: It is recommended you do Task 28-42-00-7100 before you do this task. NOTE: It is recommended you do this task at the same time as Task 57-00-00-2101										
57-00-00-2102		Right Wing Fuel Probe Wiring Harness Standalone EZAP General Visual Inspection						RE	MSG-3 EZAP Inspection Tasks			
	57 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
							Hrs	3048:30				
							Ldg	2,362				
		(ZONE: 613, 614, 615, 623, 624, 633, 634) (SOURCE: 560 XL MM Section 5-10-05)										
		Note: NOTE: It is recommended you do Task 28-42-00-7100 before you do this task. NOTE: It is recommended you do this task at the same time as Task 57-00-00-2101										
57-00-00-2200		Left Wing Cove and Rear Spar Structure and Corrosion Detailed Inspection						REMSG-3 Structures Inspection Tasks				
	57 A/F	5-12-01					Mos	31-Oct-2024	12	-/+1m	(31-Oct-2025)	11.7 Months (+30 Days)
							Hrs	3308:54				
							Ldg	2,570				
		(ZONE: 512, 516, 522, 532) (SOURCE: 560 XL MM Section 5-10-03)										
		Note: NOTE: This is a CPCP Task										
57-00-00-2200		Right Wing Cove and Rear Spar Structure and Corrosion Detailed Inspection						REMSG-3 Structures Inspection Tasks				
	57 A/F	5-12-01					Mos	31-Oct-2024	12	-/+1m	(31-Oct-2025)	11.7 Months (+30 Days)
							Hrs	3308:54				
							Ldg	2,570				
		(ZONE: 614, 615, 624, 634) (SOURCE: 560 XL MM Section 5-10-03)										
		Note: NOTE: This is a CPCP Task										
57-10-00-2100		Left Main Landing Gear Wheel Well and Door Internal Zonal General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks			
	57 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
							Hrs	3048:30				
							Ldg	2,362				
		MRBR Task:32-700-02, MRBR Task:721- 001, MRBR Task:731-001 (ZONE: 730) (SOURCE: 560 XL MM Section 5-10-01, 5-10-04, 5-12-06)										
		Note: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-2101, 32-00-00-7100, and 53-10-00-2100										
57-10-00-2100		Right Main Landing Gear Wheel Well and Door Internal Zonal General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks			
	57 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
							Hrs	3048:30				
							Ldg	2,362				
		MRBR Task:32-700-02, MRBR Task:721- 001, MRBR Task:731-001 (ZONE: 720) (SOURCE: 560 XL MM Section 5-10-01, 5-10-04, 5-12-06)										
		Note: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-2101, 32-00-00-7100, and 53-10-00-2100										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
57-10-00-2101		Left and Right Wing Forward Spar (Forward Side) and Wing Tip Internal Standalone General Visual Inspection								REMSG-3 Structures Inspection Tasks	
	57 A/F	5-12-16					Mos	09-Oct-2023	96	-/+1m (31-Oct-2031)	7 Years (+30 Days)
		(ZONE: 513, 523, 533, 541, 613, 623, 633, 642) (Tol. Adjustment: 20d) (UPDATE NOTE: Found LH Inboard Leading Edge Diffusor Cracked Refer to W/O: 101046585. Found L/H All Leading Edge Heat Shields Cracked refer to W/O: 101046587. Found Corrosion Under Nutplates on FWD Wing Spar Frame refer to WO: 101047756.) (SOURCE: 560 XL MM Section 5-10-03)					Hrs	3048:30			
		Note: NOTE: It is recommended you do this task at the same time as Task 57-30-01-2100					Ldg	2,362			
57-10-00-2200		Left Main Landing Gear and Wheel Well Structure and Corrosion General Visual Inspection								REMSG-3 Structures Inspection Tasks	
	57 A/F	5-12-01					Mos	31-Oct-2024	12	-/+1m (31-Oct-2025)	11.7 Months (+30 Days)
		(ZONE: 720) (SOURCE: 560 XL MM Section 5-10-03)					Hrs	3308:54			
		Note: NOTE: This is a CPCP Task					Ldg	2,570			
57-10-00-2200		Right Main Landing Gear and Wheel Well Structure and Corrosion General Visual Inspection								REMSG-3 Structures Inspection Tasks	
	57 A/F	5-12-01					Mos	31-Oct-2024	12	-/+1m (31-Oct-2025)	11.7 Months (+30 Days)
		(ZONE: 730) (SOURCE: 560 XL MM Section 5-10-03)					Hrs	3308:54			
		Note: NOTE: This is a CPCP Task					Ldg	2,570			
57-10-00-2500		Left Lower Wing Main Spar Lower Skin Splice at WS 22.50 (Eddy Current and Ultrasonic) Special Detailed Inspection								T	Airworthiness Limitations Inspection Time Limits
	57 A/F	4-12-MF					Mos				≈04-Sep-2030
		(ZONE: 515) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs	7,500			
							Ldg				
57-10-00-2500		Right Lower Wing Main Spar Lower Skin Splice at WS 22.50 (Eddy Current and Ultrasonic) Special Detailed Inspection								T	Airworthiness Limitations Inspection Time Limits
	57 A/F	4-12-MF					Mos				≈04-Sep-2030
		(ZONE: 516) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs	7,500			
							Ldg				
57-10-00-2501		Left Lower Wing Main Spar Skin Splice Flange at WS 11.50 (Eddy Current and Ultrasonic) Special Detailed Inspection								T	Airworthiness Limitations Inspection Time Limits
	57 A/F	4-12-ML					Mos				≈29-Mar-2036
		(ZONE: 515) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs	11,500			
							Ldg				
57-10-00-2501		Right Lower Wing Main Spar Skin Splice Flange at WS 11.50 (Eddy Current and Ultrasonic) Special Detailed Inspection								T	Airworthiness Limitations Inspection Time Limits
	57 A/F	4-12-ML					Mos				≈29-Mar-2036
		(ZONE: 615) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs	11,500			
							Ldg				
57-10-00-2502		Left Lower Wing Main Spar at WS 114.57 (Eddy Current) Special Detailed Inspection								T	Airworthiness Limitations Inspection Time Limits
	57 A/F	4-12-MM					Mos				≈18-Jul-2035
		(ZONE: 523, 524) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs	11,000			
							Ldg				
57-10-00-2502		Right Lower Wing Main Spar at WS 114.57 (Eddy Current) Special Detailed Inspection								T	Airworthiness Limitations Inspection Time Limits
	57 A/F	4-12-MM					Mos				≈18-Jul-2035
		(ZONE: 623, 624) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs	11,000			
							Ldg				
57-10-00-2503		Left Lower Wing Main Spar at WS 131.07 (Eddy Current) Special Detailed Inspection								T	Airworthiness Limitations Inspection Time Limits
	57 A/F	4-12-MN					Mos				≈05-Oct-2032
		(ZONE: 523, 524) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs	9,000			
							Ldg				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
57-10-00-2503		Right Lower Wing Main Spar at WS 131.07 (Eddy Current) Special Detailed Inspection						T		Airworthiness Limitations Inspection Time Limits	≈ 05-Oct-2032
	57 A/F	4-12-MN				Mos					
		(ZONE: 623, 624) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Hrs		9,000		(9000)	5683:53 Hrs
						Ldg					
57-10-00-2504		Left Lower Wing Main Spar at WS 149.57 (Eddy Current) Special Detailed Inspection						T		Airworthiness Limitations Inspection Time Limits	≈ 19-Aug-2037
	57 A/F	4-12-MO				Mos					
		(ZONE: 523, 524) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Hrs		12,500		(12500)	9183:53 Hrs
						Ldg					
57-10-00-2504		Right Lower Wing Main Spar at WS 149.57 (Eddy Current) Special Detailed Inspection						T		Airworthiness Limitations Inspection Time Limits	≈ 19-Aug-2037
	57 A/F	4-12-MO				Mos					
		(ZONE: 623, 624) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Hrs		12,500		(12500)	9183:53 Hrs
						Ldg					
57-10-00-9600		Main Landing Gear Forward Trunnion Fitting						RE		Airworthiness Limitations Inspection Time Limits	≈ 28-Feb-2069
	57 A/F	Left	0			Mos	29-Oct-2015				
	6622123-5	New	0			Hrs	0				
	205057-3		0			Ldg	0	23,800		23,800	21,224 Ldg
		(ZONE: 730) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)									
57-10-00-9600		Main Landing Gear Forward Trunnion Fitting						RE		Airworthiness Limitations Inspection Time Limits	≈ 28-Feb-2069
	57 A/F	Right	0			Mos	29-Oct-2015				
	6622123-6	New	0			Hrs	0				
	203984-4		0			Ldg	0	23,800		23,800	21,224 Ldg
		(ZONE: 720) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)									
57-10-00-9601		Main Landing Gear Aft Trunnion Fitting						RE		Airworthiness Limitations Inspection Time Limits	≈ 28-Feb-2069
	57 A/F	Left	0			Mos	29-Oct-2015				
	6622124-5	New	0			Hrs	0				
	203989-8		0			Ldg	0	23,800		23,800	21,224 Ldg
		(ZONE: 730) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)									
57-10-00-9601		Main Landing Gear Aft Trunnion Fitting						RE		Airworthiness Limitations Inspection Time Limits	≈ 28-Feb-2069
	57 A/F	Right	0			Mos	29-Oct-2015				
	6622124-6	New	0			Hrs	0				
	211923-6		0			Ldg	0	23,800		23,800	21,224 Ldg
		(ZONE: 720) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)									
57-10-00-9602		Main Landing Gear Actuator Fitting						RE		Airworthiness Limitations Inspection Time Limits	≈ 28-Feb-2069
	57 A/F	Left	0			Mos	29-Oct-2015				
	6621125-9	New	0			Hrs	0				
	226304-1		0			Ldg	0	23,800		23,800	21,224 Ldg
		(ZONE: 730) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)									
57-10-00-9602		Main Landing Gear Actuator Fitting						RE		Airworthiness Limitations Inspection Time Limits	≈ 28-Feb-2069
	57 A/F	Right	0			Mos	29-Oct-2015				
	6621125-10	New	0			Hrs	0				
	223996-1		0			Ldg	0	23,800		23,800	21,224 Ldg
		(ZONE: 720) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)									

Task No		Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
57-30-01-2100	 57 A/F	Wing Tip Internal Zonal General Visual Inspection and Restoration 5-12-16 MRBR Task:541-101E, MRBR Task:642-101E, MRBR Task:57-500-03, MRBR Task:541-001, MRBR Task:642-001 (ZONE: 541, 642) (Tol. Adjustment: 20d) (SOURCE: 560XL MM) Note: NOTE: It is recommended you do this task at the same time as Task 57-10-00-2101						RE	05-10-01, 05-10-04, 05-10-05			
						Mos	09-Oct-2023	96	-/+1m	(31-Oct-2031)	7 Years (+30 Days)	
						Hrs	3048:30					
						Ldg	2,362					
57-50-03-2200	 57 A/F	Aileron, Aileron Trim Tab and Hinge Brackets Detailed Inspection 5-12-06 (ZONE: 532, 534, 632, 634) (SOURCE: 560 XL MM Section 5-10-03) Note: NOTE: It is recommended you do this task at the same time as Task 57-60-00-2200						REMSG-3 Structures Inspection Tasks				
						Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)	
						Hrs	3048:30					
						Ldg	2,362					
57-50-04-2900	 57 A/F	Flap (Coin Tap) Special Detailed Inspection Left Inboard5-12-06 Unknown Unknown (ZONE: 512) (SOURCE: 560 XL MM Section 5-10-03)						REMSG-3 Structures Inspection Tasks				
						Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)	
						Hrs	3048:30					
						Ldg	2,362					
57-50-04-2900	 57 A/F	Flap (Coin Tap) Special Detailed Inspection Left Outboard5-12-06 6525135-35 24944135 (ZONE: 612) (SOURCE: 560 XL MM Section 5-10-03)						REMSG-3 Structures Inspection Tasks				
						Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)	
						Hrs	3048:30					
						Ldg	2,362					
57-50-04-2900	 57 A/F	Flap (Coin Tap) Special Detailed Inspection Right Inboard5-12-06 Unknown Unknown (ZONE: 522) (SOURCE: 560 XL MM Section 5-10-03)						REMSG-3 Structures Inspection Tasks				
						Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)	
						Hrs	3048:30					
						Ldg	2,362					
57-50-04-2900	 57 A/F	Flap (Coin Tap) Special Detailed Inspection Right Outboard5-12-06 Unknown Unknown (ZONE: 612) (SOURCE: 560 XL MM Section 5-10-03)						REMSG-3 Structures Inspection Tasks				
						Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)	
						Hrs	3048:30					
						Ldg	2,362					
57-50-04-9600	 57 A/F	Left Wing Aft Flap Roller Left Inboard S3049-5F8 New NSN (ZONE: 500) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)	0			Mos	29-Oct-2015		RE	Airworthiness Limitations Inspection Time Limits	≈29-Nov-2029	
			0			Hrs	0					
			0			Ldg	0	5,000	5,000	2,424 Ldg		
57-50-04-9600	 57 A/F	Left Wing Aft Flap Roller Left Outboard S3049-5F8 New NSN (ZONE: 500) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)	0			Mos	29-Oct-2015		RE	Airworthiness Limitations Inspection Time Limits	≈29-Nov-2029	
			0			Hrs	0					
			0			Ldg	0	5,000	5,000	2,424 Ldg		
57-50-04-9600	 57 A/F	Left Wing Aft Flap Roller Right Inboard S3049-5F8 New NSN (ZONE: 500) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)	0			Mos	29-Oct-2015		RE	Airworthiness Limitations Inspection Time Limits	≈29-Nov-2029	
			0			Hrs	0					
			0			Ldg	0	5,000	5,000	2,424 Ldg		
57-50-04-9600	 57 A/F	Left Wing Aft Flap Roller Right Outboard S3049-5F8 New NSN (ZONE: 500) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)	0			Mos	29-Oct-2015		RE	Airworthiness Limitations Inspection Time Limits	≈29-Nov-2029	
			0			Hrs	0					
			0			Ldg	0	5,000	5,000	2,424 Ldg		

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
57-50-04-9600		Left Wing Fwd Flap Roller								RE	Airworthiness Limitations Inspection Time Limits	≈29-Nov-2029
	57 A/F	Left Inboard					Mos	29-Oct-2015				
	S3049-5F8	New					Hrs	0				
	NSN						Ldg	0	5,000	5,000	2,424 Ldg	
(ZONE: 500) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)												
57-50-04-9600		Left Wing Fwd Flap Roller								RE	Airworthiness Limitations Inspection Time Limits	≈29-Nov-2029
	57 A/F	Left Outboard					Mos	29-Oct-2015				
	S3049-5F8	New					Hrs	0				
	NSN						Ldg	0	5,000	5,000	2,424 Ldg	
(ZONE: 500) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)												
57-50-04-9600		Left Wing Fwd Flap Roller								RE	Airworthiness Limitations Inspection Time Limits	≈29-Nov-2029
	57 A/F	Right Inboard					Mos	29-Oct-2015				
	S3049-5F8	New					Hrs	0				
	NSN						Ldg	0	5,000	5,000	2,424 Ldg	
(ZONE: 500) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)												
57-50-04-9600		Left Wing Fwd Flap Roller								RE	Airworthiness Limitations Inspection Time Limits	≈29-Nov-2029
	57 A/F	Right Outboard					Mos	29-Oct-2015				
	S3049-5F8	New					Hrs	0				
	NSN						Ldg	0	5,000	5,000	2,424 Ldg	
(ZONE: 500) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)												
57-50-04-9600		Right Wing Aft Flap Roller								RE	Airworthiness Limitations Inspection Time Limits	≈29-Nov-2029
	57 A/F	Left Inboard					Mos	29-Oct-2015				
	S3049-5F8	New					Hrs	0				
	NSN						Ldg	0	5,000	5,000	2,424 Ldg	
(ZONE: 600) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)												
57-50-04-9600		Right Wing Aft Flap Roller								RE	Airworthiness Limitations Inspection Time Limits	≈29-Nov-2029
	57 A/F	Left Outboard					Mos	29-Oct-2015				
	S3049-5F8	New					Hrs	0				
	NSN						Ldg	0	5,000	5,000	2,424 Ldg	
(ZONE: 600) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)												
57-50-04-9600		Right Wing Aft Flap Roller								RE	Airworthiness Limitations Inspection Time Limits	≈29-Nov-2029
	57 A/F	Right Inboard					Mos	29-Oct-2015				
	S3049-5F8	New					Hrs	0				
	NSN						Ldg	0	5,000	5,000	2,424 Ldg	
(ZONE: 600) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)												
57-50-04-9600		Right Wing Aft Flap Roller								RE	Airworthiness Limitations Inspection Time Limits	≈29-Nov-2029
	57 A/F	Right Outboard					Mos	29-Oct-2015				
	S3049-5F8	New					Hrs	0				
	NSN						Ldg	0	5,000	5,000	2,424 Ldg	
(ZONE: 600) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)												
57-50-04-9600		Right Wing Fwd Flap Roller								RE	Airworthiness Limitations Inspection Time Limits	≈29-Nov-2029
	57 A/F	Left Inboard					Mos	29-Oct-2015				
	S3049-5F8	New					Hrs	0				
	NSN						Ldg	0	5,000	5,000	2,424 Ldg	
(ZONE: 600) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)												

Task No	Description								Categories	Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
57-50-04-9600		Right Wing Fwd Flap Roller								RE	Airworthiness Limitations Inspection Time Limits	≈29-Nov-2029
	57 A/F	Left Outboard					Mos	29-Oct-2015				
	S3049-5F8	New					Hrs	0				
	NSN						Ldg	0	5,000	5,000	2,424 Ldg	
(ZONE: 600) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)												
57-50-04-9600		Right Wing Fwd Flap Roller								RE	Airworthiness Limitations Inspection Time Limits	≈29-Nov-2029
	57 A/F	Right Inboard					Mos	29-Oct-2015				
	S3049-5F8	New					Hrs	0				
	NSN						Ldg	0	5,000	5,000	2,424 Ldg	
(ZONE: 600) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)												
57-50-04-9600		Right Wing Fwd Flap Roller								RE	Airworthiness Limitations Inspection Time Limits	≈29-Nov-2029
	57 A/F	Right Outboard					Mos	29-Oct-2015				
	S3049-5F8	New					Hrs	0				
	NSN						Ldg	0	5,000	5,000	2,424 Ldg	
(ZONE: 600) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)												
▼ 58 - *Unassigned												
57-60-00-2200		Aileron, Aileron Wing Sectors and Aileron Trim Components Structure Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS, MSG-3 Structures Inspection Tasks		
	58 A/F	5-12-06					Mos	09-Oct-2023	48	-/+1m	(31-Oct-2027)	3 Years (+30 Days)
	MRBR Task:27-10-01-002, MRBR Task:27-10-01-001, MRBR Task:27-10-00-213 (ZONE: 141, 142, 153, 154, 236, 241, 242, 248, 512, 522, 523, 532, 534, 612, 622, 632, 634) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-10-03) Note: NOTE: It is recommended you do this task at the same time as Task 57-50-03-2200					Hrs	3048:30					
						Ldg	2,362					
▼ 71 - POWER PLANT												
		Engine Aft Isolator								RE (O/C)		
	71 A/F	Left					Mos	29-Oct-2015				
	LM451-SA2	New					Hrs	0				
	LK1852						Ldg	0				
		Engine Aft Isolator								RE (O/C)		
	71 A/F	Right					Mos	29-Oct-2015				
	LM451-SA2	New					Hrs	0				
	LK1881						Ldg	0				
		Engine Vibration Monitor								RE (O/C)		
	71 A/F	New					Mos	13-Jan-2016				
	9912519-2						Hrs	67:17				
	021482						Ldg	59				
					Hrs (APU)	31						
					Start (APU)	39						
		Forward Engine Isolator								RE (O/C)		
	71 A/F	Lower - Left					Mos	29-Oct-2015				
	LM451-SA4	New					Hrs	0				
	LK4219						Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
	71 A/F LM451-SA4 LK4250	Forward Engine Isolator	RE (O/C)							
		Lower - Right	0			Mos	29-Oct-2015			
		New	0			Hrs	0			
	71 A/F LM451-SA4 LK4221	Forward Engine Isolator	RE (O/C)							
		Upper - Left	0			Mos	29-Oct-2015			
		New	0			Hrs	0			
	71 A/F LM451-SA4 LK4261	Forward Engine Isolator	RE (O/C)							
		Upper - Right	0			Mos	29-Oct-2015			
		New	0			Hrs	0			
54-50-01-2101	Left Engine Cowling, Engine Pylon Firewall General Visual Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	71 A/F	5-12-06				Mos	09-Oct-2023	48	-/+ 1m (31-Oct-2027)	3 Years (+30 Days)
		(ZONE: 410) (SOURCE: 560 XL MM Section 5-10-02)				Hrs	3048:30			
		Note: NOTE: It is recommended you do this task at the same time as Task 71-00-00-2201				Ldg	2,362			
54-50-01-2101	Right Engine Cowling, Engine Pylon Firewall General Visual Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	71 A/F	5-12-06				Mos	09-Oct-2023	48	-/+ 1m (31-Oct-2027)	3 Years (+30 Days)
		(ZONE: 420) (SOURCE: 560 XL MM Section 5-10-02)				Hrs	3048:30			
		Note: NOTE: It is recommended you do this task at the same time as Task 71-00-00-2201				Ldg	2,362			
560XL-71-11	Engine Fuel Manifold Drain Line Installation Revision 1						RE (-)	Optional		
	71 A/F Superseded	R1 is c/w				Mos	13-Sep-2021			
						Hrs	2222:03			
						Ldg	1,687			
560XL-71-11 Rev 01	Engine Fuel Manifold Drain Line Installation Revision 1						RE (-)	Optional		
	71 A/F Eff: 02-Aug-2012 Superseded	R1 is c/w				Mos	13-Sep-2021			
						Hrs	2222:03			
						Ldg	1,687			
560XL-71-12	Engine Fuel Manifold Drain Line Removal						T (A/R)	Optional		
	71 A/F Eff: 01-Oct-2012					Mos				
						Hrs				
						Ldg				
71-00-00	Engine Internal Wash						RE (A/R)			
	71 ENG1					Mos	23-May-2019			
						Hrs	1397:27			
						Enc	1,136			
71-00-00	Engine Internal Wash						RE (A/R)			
	71 ENG2					Mos	23-May-2019			
						Hrs	1397:27			
						Enc	1,136			
71-00-00-2100	Left Engine Fire Detection Element Standalone EZAP General Visual Inspection						RE	MSG-3 EZAP Inspection Tasks		
	71 A/F	5-12-03				Mos	09-Oct-2023	24	-/+ 1m (31-Oct-2025)	11.7 Months (+30 Days)
		(ZONE: 410) (SOURCE: 560 XL MM Section 5-10-05)				Hrs	3048:30			
		Note: NOTE: It is recommended you do this task at the same time as Tasks 54-50-01-2100 and 71-00-00-2200				Ldg	2,362			

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
71-00-00-2100	71 A/F	Right Engine Fire Detection Element Standalone EZAP General Visual Inspection 5-12-03 (ZONE: 420) (SOURCE: 560 XL MM Section 5-10-05) Note: NOTE: It is recommended you do this task at the same time as Tasks 54-50-01-2100 and 71-00-00-2200						RE	MSG-3 EZAP Inspection Tasks		
							Mos	09-Oct-2023	24	-/+1m (31-Oct-2025)	11.7 Months (+30 Days)
							Hrs	3048:30			
							Ldg	2,362			
71-00-00-2200	71 A/F	Left Engine Starter Generator, Alternator, Alternator PCU, Full Authority Digital Electronic Control L/HIRF Detailed Inspection 5-12-03 (ZONE: 410) (SOURCE: 560 XL MM Section 5-10-06) Note: NOTE: It is recommended you do this task at the same time as Tasks 54-50-01-2100 and 71-00-00-2100						RE	MSG-3 L/HIRF Inspection Tasks		
							Mos	09-Oct-2023	24	-/+1m (31-Oct-2025)	11.7 Months (+30 Days)
							Hrs	3048:30			
							Ldg	2,362			
71-00-00-2200	71 A/F	Right Engine Starter Generator, Alternator, Alternator PCU, Full Authority Digital Electronic Control L/HIRF Detailed Inspection 5-12-03 (ZONE: 420) (SOURCE: 560 XL MM Section 5-10-06) Note: NOTE: It is recommended you do this task at the same time as Tasks 54-50-01-2100 and 71-00-00-2100						RE	MSG-3 L/HIRF Inspection Tasks		
							Mos	09-Oct-2023	24	-/+1m (31-Oct-2025)	11.7 Months (+30 Days)
							Hrs	3048:30			
							Ldg	2,362			
71-00-00-2201	71 A/F	Left Engine Cowling L/HIRF Detailed Inspection 5-12-06 (ZONE: 430, 440) (SOURCE: 560 XL MM Section 5-10-06) Note: NOTE: It is recommended you do this task at the same time as Task 54-50-01-2101						RE	MSG-3 L/HIRF Inspection Tasks		
							Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)
							Hrs	3048:30			
							Ldg	2,362			
71-00-00-2201	71 A/F	Right Engine Cowling L/HIRF Detailed Inspection 5-12-06 (ZONE: 430, 440) (SOURCE: 560 XL MM Section 5-10-06) Note: NOTE: It is recommended you do this task at the same time as Task 54-50-01-2101						RE	MSG-3 L/HIRF Inspection Tasks		
							Mos	09-Oct-2023	48	-/+1m (31-Oct-2027)	3 Years (+30 Days)
							Hrs	3048:30			
							Ldg	2,362			
71-00-PW-009	71 ENG1	Engine Externals and Compressor Wash (Desalination) Ref:71-00-00-cl Note: As general observations warrant. As necessary by ECTM or at every approx. 20 °C ITT increase. Also by visual inspection of compressor gas path when you operate the engine in an adverse environment						RE (A/R)	EMM - Requirement		
							Mos				
							Hrs				
							Enc				
71-00-PW-009	71 ENG2	Engine Externals and Compressor Wash (Desalination) Ref:71-00-00-cl Note: As general observations warrant. As necessary by ECTM or at every approx. 20 °C ITT increase. Also by visual inspection of compressor gas path when you operate the engine in an adverse environment						RE (A/R)	EMM - Requirement		
							Mos				
							Hrs				
							Enc				
71-22-00-9600	71 A/F LM451-SA2 LK1852	Engine Aft Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration Left (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) Note: Every Second Engine Overhaul, Not To Exceed 11,000 Flight Hours NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored Forward Engine Isolator Mount and/or reference LORD Corporation 71-20-55 Component Maintenance Manual.						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Feb-2034
							Mos				
							Hrs	10,000	+100	10000	6683:53 Hrs (+100)
							Ldg				
71-22-00-9600	71 A/F LM451-SA2 LK1881	Engine Aft Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration Right (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) Note: Every Second Engine Overhaul, Not To Exceed 11,000 Flight Hours NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored Forward Engine Isolator Mount and/or reference LORD Corporation 71-20-55 Component Maintenance Manual.						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Feb-2034
							Mos				
							Hrs	10,000	+100	10000	6683:53 Hrs (+100)
							Ldg				

Task No	Description					Categories					Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
71-22-00-9600			Engine Forward Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration					RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Feb-2034
	71 A/F	Lower - Left				Mos					
	LM451-SA4					Hrs		10,000	+100	10000	6683:53 Hrs (+100)
	LK4219					Ldg					
(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) Note: Every Second Engine Overhaul, Not To Exceed 11,000 Flight Hours NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored Forward Engine Isolator Mount and/or reference LORD Corporation 71-20-55 Component Maintenance Manual.											
71-22-00-9600			Engine Forward Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration					RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Feb-2034
	71 A/F	Lower - Right				Mos					
	LM451-SA4					Hrs		10,000	+100	10000	6683:53 Hrs (+100)
	LK4250					Ldg					
(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) Note: Every Second Engine Overhaul, Not To Exceed 11,000 Flight Hours NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored Forward Engine Isolator Mount and/or reference LORD Corporation 71-20-55 Component Maintenance Manual.											
71-22-00-9600			Engine Forward Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration					RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Feb-2034
	71 A/F	Upper - Left				Mos					
	LM451-SA4					Hrs		10,000	+100	10000	6683:53 Hrs (+100)
	LK4221					Ldg					
(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) Note: Every Second Engine Overhaul, Not To Exceed 11,000 Flight Hours NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored Forward Engine Isolator Mount and/or reference LORD Corporation 71-20-55 Component Maintenance Manual.											
71-22-00-9600			Engine Forward Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration					RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Feb-2034
	71 A/F	Upper - Right				Mos					
	LM451-SA4					Hrs		10,000	+100	10000	6683:53 Hrs (+100)
	LK4261					Ldg					
(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) Note: Every Second Engine Overhaul, Not To Exceed 11,000 Flight Hours NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored Forward Engine Isolator Mount and/or reference LORD Corporation 71-20-55 Component Maintenance Manual.											
71-71-00-2100			Left Engine Drains General Visual Inspection					RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈09-Oct-2026
	71 A/F	5-12-08				Mos	17-Dec-2021				
						Hrs	2295:34	2,400	-/+25	(4695:34)	1379:27 Hrs (+25)
						Ldg	1,748				
(ZONE: 410) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 25-11-01-2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES -5002 THRU -5555 INCORPORATINGSB560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019,CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560 XL MM Section 5-10-02)											

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
71-71-00-2100	Right Engine Drains General Visual Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈09-Oct-2026
 71 A/F	5-12-08					Mos 17-Dec-2021				
						Hrs 2295:34	2,400	-/+25	(4695:34)	1379:27 Hrs (+25)
	(ZONE: 420) (UPDATE NOTE: ACCOMPLISHED INSPECTION DOCUMENT 08 IAW AMM 560XL (REV 46) CHAPTER 5-12-08 (REV 46) PERFORMED CREW SEATS DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 25-11-01-2200- NO FAULTS FOUNDPERFORMED AILERON WING CABLE DETAILED INSPECTION (AIRPLANES -5556 AND ON, AND AIRPLANES -5002 THRU -5555 INCORPORATINGSB560XL-27-22) I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-10-00-2201USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021*** FOUND LH WING UPPER AILERON CONTROL CABLE CHAFEDPERFORMED AILERON AND AILERON TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019,CHAPTER: 27-10-00-2203USED TENSIO METER JAD7472, NEXT CALIBRATION DATE DEC. 2021FINDINGS:*** BOTH AILERON FUSELAGE CONTROL CABLES CHAFED*** AILERON TRIM WING CONTROL CABLES CHAFED*** LH WING AILERON UPPER CONTROL CABLE CHAFED*** AILERON AUTOPILOT SERVO CABLE TENSION LOWPERFORMED RUDDER BIAS CABLE ASSEMBLY DETAILED INSPECTION I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY. 2019, CHAPTER: 27-20-00-2200- NO FAULTS FOUNDUSED TENSIO METER JAD6849, NEXT CALIBRATION DATE: JULY 2022PERFORMED 27-20-00-2202 RUDDER AND RUDDER TRIM DETAILED INSPECTION AND FUNCTIONAL CHECK I.A.W CESSNA MODEL 560XL AMM. REV.46, MAY.2019, CHAPTER: 27-20-00-2202TAILCONE SECTION) CHAFED.) (SOURCE: 560 XL MM Section 5-10-02)					Ldg 1,748				
CIL-71-01	Transmittal of Pratt & Whitney Canada Service Bulletin 30463						RE (-)		Optional	
 71 A/F						Mos				
Eff: 29-Jan-2013						Hrs				
						Ldg				
SIL-PW500-068	PW500 Engine Calibration Check						T (A/R)		Service Information Letter	
 71 ENG1						Mos				
Eff: 31-May-2017						Hrs				
						Enc				
SIL-PW500-068	PW500 Engine Calibration Check						T (A/R)		Service Information Letter	
 71 ENG2						Mos				
Eff: 31-May-2017						Hrs				
						Enc				
SL560XL-71-01	Power Plant - Transmittal Of Aeroquip Aerospace Service Bulletin ASB125 How To Repair Silicone Covered Hose Abrasions Using AE272 Flexwrap Firesleeve						T (A/R)		Informational	
 71 A/F						Mos				
Eff: 21-Jan-2001						Hrs				
						Ldg				
SL560XL-71-09	Transmittal of Pratt & Whitney Canada (P&WC) Service Bulletin Number 30294R2, Turbofan Engine Oil Tank Filler Cap Inspection Of						T (A/R)		Informational	
 71 A/F						Mos				
Eff: 15-Jun-2006						Hrs				
						Ldg				
SL560XL-71-11	Power Plant - Inspect the Left and Right Engine Forward Upper and Lower Isolator Assembly Mount Bolt Heads for Safety Wire Holes						RE (-)		Recommended, Service Letter	
 71 A/F						Mos 13-Sep-2021				
Eff: 15-Aug-2019 Superseded R1 is c/w						Hrs 2222:03				
(AVG MAN HRS: 4)						Ldg 1,687				
SL560XL-71-11 R1	Power Plant - Inspect the Left and Right Engine Forward Upper and Lower Isolator Assembly Mount Bolt Heads for Safety Wire Holes						RE (-)		Recommended, Service Letter	
 71 A/F						Mos 24-Nov-2019				
Eff: 29-Aug-2019 Complied With						Hrs 1700:03				
(AVG MAN HRS: 4)						Ldg 1,331				
SL560XL-71-11 R2	Power Plant - Inspect the Left and Right Engine Forward Upper and Lower Isolator Assembly Mount Bolt Heads for Safety Wire Holes						RE (-)		Recommended, Service Letter	
 71 A/F						Mos 13-Sep-2021				
Eff: 23-Oct-2019 Not Applicable	R1 is c/w					Hrs 2222:03				
(AVG MAN HRS: 4)						Ldg 1,687				
Note: NOTE: Only airplanes that were in for maintenance that required the engine removal or forward engine isolator to be removed between June 1, 2018 through April 30, 2019, will need to comply with this service letter.										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
▼ 72 - ENGINE											
	72 ENG1	1st Stage HP Compressor Rotor					RE			EMM - Life Limit	≈29-Aug-2047
	30J2821-01	New	0		Mos		29-Oct-2015				
	A003LXRA		0		Hrs		0				
			0		Enc		0	13,500	13,500	10,924	Enc
	72 ENG2	1st Stage HP Compressor Rotor					RE			EMM - Life Limit	≈29-Aug-2047
	30J2821-01	New	0		Mos		29-Oct-2015				
	A003LYPR		0		Hrs		0				
			0		Enc		0	13,500	13,500	10,924	Enc
	72 ENG1	1st-Stage Turbine Disk					RE			EMM - Life Limit	≈29-Aug-2047
	30J3461-01	New	0		Mos		29-Oct-2015				
	A003M4AT		0		Hrs		0				
			0		Enc		0	13,500	13,500	10,924	Enc
	72 ENG2	1st-Stage Turbine Disk					RE			EMM - Life Limit	≈29-Aug-2047
	30J3461-01	New	0		Mos		29-Oct-2015				
	A003M4AW		0		Hrs		0				
			0		Enc		0	13,500	13,500	10,924	Enc
	72 ENG1	2nd Stage HP Compressor Rotor					RE			EMM - Life Limit	≈29-Aug-2047
	30J2429-01	New	0		Mos		29-Oct-2015				
	EAAD000R934		0		Hrs		0				
			0		Enc		0	13,500	13,500	10,924	Enc
	72 ENG2	2nd Stage HP Compressor Rotor					RE			EMM - Life Limit	≈29-Aug-2047
	30J2429-01	New	0		Mos		29-Oct-2015				
	EAAD000R936		0		Hrs		0				
			0		Enc		0	13,500	13,500	10,924	Enc
	72 ENG1	2nd-Stage Turbine Disk					RE			EMM - Life Limit	≈29-Aug-2047
	30H3172	New	0		Mos		29-Oct-2015				
	ABT02831		0		Hrs		0				
			0		Enc		0	13,500	13,500	10,924	Enc
	72 ENG2	2nd-Stage Turbine Disk					RE			EMM - Life Limit	≈29-Aug-2047
	30H3172	New	0		Mos		29-Oct-2015				
	ABT02827		0		Hrs		0				
			0		Enc		0	13,500	13,500	10,924	Enc
	72 ENG1	3rd-Stage Turbine Disk					RE			EMM - Life Limit	≈29-Aug-2047
	30H3173	New	0		Mos		29-Oct-2015				
	ABT03048		0		Hrs		0				
			0		Enc		0	13,500	13,500	10,924	Enc
	72 ENG2	3rd-Stage Turbine Disk					RE			EMM - Life Limit	≈29-Aug-2047
	30H3173	New	0		Mos		29-Oct-2015				
	ABT03027		0		Hrs		0				
			0		Enc		0	13,500	13,500	10,924	Enc

Task No	Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG1 30H3174 ABT03099	4th-Stage Turbine Disk							RE	EMM - Life Limit	≈29-Aug-2047
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Enc	0	13,500		13,500	10,924 Enc
	72 ENG2 30H3174 ABT03104	4th-Stage Turbine Disk							RE	EMM - Life Limit	≈29-Aug-2047
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Enc	0	13,500		13,500	10,924 Enc
	72 ENG1 30J2973-01 RWA70E979	AC, Alternator Drive Spur Gearshaft Assembly							RE (O/C)		
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Enc	0				
	72 ENG2 30J2973-01 RWA70E977	AC, Alternator Drive Spur Gearshaft Assembly							RE (O/C)		
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Enc	0				
	72 ENG1 30J3620-01 PKAAA602857	Accessory Drive Gearshaft Assembly							RE (O/C)		
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Enc	0				
	72 ENG2 30J3620-01 PKAAA802855	Accessory Drive Gearshaft Assembly							RE (O/C)		
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Enc	0				
	72 ENG1 30J2937-01 RWA74E988	Accessory Gearbox Shaft							RE (O/C)		
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Enc	0				
	72 ENG2 30J2937-01 RWA62E509	Accessory Gearbox Shaft							RE (O/C)		
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Enc	0				
	72 ENG1 31J2196-01 FAA1506200	Annular Ball Bearing							RE (O/C)		
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Enc	0				
	72 ENG2 31J2196-01 FAA1500806	Annular Ball Bearing							RE (O/C)		
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Enc	0				
	72 ENG1 31J2879-05 5124	Anti-Icing Valve							RE (O/C)		
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Enc	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Anti-Icing Valve	RE (O/C)								
	72 ENG2	New	0			Mos	29-Oct-2015				
	31J2879-05		0			Hrs	0				
	5128		0			Enc	0				
		Bearing Seal Runner	RE (O/C)								
	72 ENG1	No.3	0			Mos	29-Oct-2015				
	31J2757-01	New	0			Hrs	0				
	AFD00R175		0			Enc	0				
		Bearing Seal Runner	RE (O/C)								
	72 ENG2	No.3	0			Mos	29-Oct-2015				
	31J2757-01	New	0			Hrs	0				
	AFD00R181		0			Enc	0				
		Centrifugal Impeller	RE EMM - Life Limit ≈29-Aug-2047								
	72 ENG1	New	0			Mos	29-Oct-2015				
	30J1450-01		0			Hrs	0				
	A003M5H6		0			Enc	0	13,500		13,500	10,924 Enc
		Centrifugal Impeller	RE EMM - Life Limit ≈29-Aug-2047								
	72 ENG2	New	0			Mos	29-Oct-2015				
	30J1450-01		0			Hrs	0				
	A003M5H8		0			Enc	0	13,500		13,500	10,924 Enc
		Cyl Roller Bearing	RE (O/C)								
	72 ENG1	New	0			Mos	29-Oct-2015				
	31J1292-01		0			Hrs	0				
	FCN420943		0			Enc	0				
		Cyl Roller Bearing	RE (O/C)								
	72 ENG2	New	0			Mos	29-Oct-2015				
	31J1292-01		0			Hrs	0				
	FCN426527		0			Enc	0				
		Cylindrical Roller Bearing	RE (O/C)								
	72 ENG1	New	0			Mos	29-Oct-2015				
	31J2552-01		0			Hrs	0				
	FCN427928		0			Enc	0				
		Cylindrical Roller Bearing	RE (O/C)								
	72 ENG2	New	0			Mos	29-Oct-2015				
	30J3422-01		0			Hrs	0				
	FAA1603026		0			Enc	0				
		Fan Case Assembly	RE (O/C)								
	72 ENG1	New	0			Mos	29-Oct-2015				
	30J3460-01		0			Hrs	0				
	BDA24272542		0			Enc	0				
		Fan Case Assembly	RE (O/C)								
	72 ENG2	New	0			Mos	29-Oct-2015				
	30J3460-01		0			Hrs	0				
	BDA24272535		0			Enc	0				

Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
 72 ENG1 Unknown Unknown		Flanged Ball Bearing								RE (O/C)	
							Mos	29-Oct-2015			
							Hrs	0			
							Enc	0			
 72 ENG1 31J2637-01 FAA1505485	New	Flanged Ball Bearing								RE (O/C)	
							Mos	29-Oct-2015			
							Hrs	0			
							Enc	0			
 72 ENG1 30J2936-01 FAA1419657	New	Flanged Ball Bearing								RE (O/C)	
							Mos	29-Oct-2015			
							Hrs	0			
							Enc	0			
 72 ENG2 31J2637-01 FAA1505488	New	Flanged Ball Bearing								RE (O/C)	
							Mos	29-Oct-2015			
							Hrs	0			
							Enc	0			
 72 ENG2 30J2936-01 FM1419658	New	Flanged Ball Bearing								RE (O/C)	
							Mos	29-Oct-2015			
							Hrs	0			
							Enc	0			
 72 ENG2 Unknown Unknown		Flanged Ball Bearing								RE (O/C)	
							Mos	29-Oct-2015			
							Hrs	0			
							Enc	0			
 72 ENG1 30J3209-01 Unknown	New	Flanged Roller Bearing								RE (O/C)	
							Mos	29-Oct-2015			
							Hrs	0			
							Enc	0			
 72 ENG2 30J3209-01 Unknown	New	Flanged Roller Bearing								RE (O/C)	
							Mos	29-Oct-2015			
							Hrs	0			
							Enc	0			
 72 ENG1 30J2998-01 UAAF244	New	Front Bearing Seal Runner	No.4							RE (O/C)	
			New				Mos	29-Oct-2015			
							Hrs	0			
							Enc	0			
 72 ENG2 30J2998-01 UAAF241	New	Front Bearing Seal Runner	No.4							RE (O/C)	
			New				Mos	29-Oct-2015			
							Hrs	0			
							Enc	0			
 72 ENG1 30J3357-01 KYAA015A611	New	Front Outer Bypass Duct Assy								RE (O/C)	
							Mos	29-Oct-2015			
							Hrs	0			
							Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Front Outer Bypass Duct Assy								RE (O/C)	
	72 ENG2	New	0			Mos	29-Oct-2015				
	30J3357-01		0			Hrs	0				
	KYAA015A812		0			Enc	0				
		Gas Generator Case Assembly								RE (O/C)	
	72 ENG1	New	0			Mos	29-Oct-2015				
	30J3519-01		0			Hrs	0				
	RWA79E319		0			Enc	0				
		Gas Generator Case Assembly								RE (O/C)	
	72 ENG2	New	0			Mos	29-Oct-2015				
	30J3519-01		0			Hrs	0				
	RWA79E003		0			Enc	0				
		Gas Generator Diffuser Set								RE (O/C)	
	72 ENG1	New	0			Mos	29-Oct-2015				
	30J2801-01		0			Hrs	0				
	A003MNSWA		0			Enc	0				
		Gas Generator Diffuser Set								RE (O/C)	
	72 ENG2	New	0			Mos	29-Oct-2015				
	30J2801-01		0			Hrs	0				
	A003MNSWB		0			Enc	0				
		Gearbox Drive Spiral Bevel Gearshaft								RE (O/C)	
	72 ENG1	New	0			Mos	29-Oct-2015				
	31J1654-01		0			Hrs	0				
	PKAAA615580		0			Enc	0				
		Gearbox Drive Spiral Bevel Gearshaft								RE (O/C)	
	72 ENG2	New	0			Mos	29-Oct-2015				
	31J1654-01		0			Hrs	0				
	PKAAA616572		0			Enc	0				
		High Pressure Compressor Shaft								RE (O/C)	
	72 ENG1	New	0			Mos	29-Oct-2015				
	30J2997-01		0			Hrs	0				
	EAAD000T078		0			Enc	0				
		High Pressure Compressor Shaft								RE (O/C)	
	72 ENG2	New	0			Mos	29-Oct-2015				
	30J2997-01		0			Hrs	0				
	EAAD000T078		0			Enc	0				
		High Pressure Turbine Blade								RE (O/C)	
	72 ENG1	No.1	0			Mos	29-Oct-2015				
	30J1581-01	New	0			Hrs	0				
	HWNR7214		0			Enc	0				
		High Pressure Turbine Blade								RE (O/C)	
	72 ENG2	No.1	0			Mos	29-Oct-2015				
	30J1581-01	New	0			Hrs	0				
	HWNR7219		0			Enc	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG1	High Pressure Turbine Blade No.10	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWNT3392		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.10	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2588		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.11	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWNT3395		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.11	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2594		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.12	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWNT3400		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.12	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2609		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.13	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2486		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.13	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2862		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.14	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2504		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.14	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2872		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.15	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2506		0				Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG2	High Pressure Turbine Blade No.15	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2880		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.16	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2572		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.16	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2881		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.17	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2582		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.17	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2895		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.18	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2604		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.18	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2898		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.19	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2851		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.19	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2911		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.2	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWNR7221		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.2	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWNT3319		0				Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG1	High Pressure Turbine Blade No.20	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2865		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.20	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2918		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.21	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2885		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.21	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2933		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.22	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2891		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.22	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2934		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.23	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2912		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.23	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP2940		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.24	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP3189		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.24	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP6976		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.25	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP3218		0				Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG2	High Pressure Turbine Blade No.25	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP6983		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.26	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP6966		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.26	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP6993		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.27	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP6982		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.27	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP7760		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.28	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP6996		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.28	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP7771		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.29	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP7000		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.29	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP7792		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.3	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWNT3324		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.3	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWNT3331		0				Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG1	High Pressure Turbine Blade No.30	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP7769		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.30	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP7795		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.31	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP7797		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.31	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP7798		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.32	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP9485		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.32	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP8236		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.33	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP9488		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.33	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP8238		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.34	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP9513		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.34	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPDP8245		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.35	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWPE0186		0				Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.35	0				Mos	29-Oct-2015			
	HWPE0191	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.36	0				Mos	29-Oct-2015			
	HWPE0187	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.36	0				Mos	29-Oct-2015			
	HWPE0232	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.37	0				Mos	29-Oct-2015			
	HWPE0196	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.37	0				Mos	29-Oct-2015			
	HWPE0235	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.38	0				Mos	29-Oct-2015			
	HWPE0197	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.38	0				Mos	29-Oct-2015			
	HWPE0237	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.39	0				Mos	29-Oct-2015			
	HWPE0206	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.39	0				Mos	29-Oct-2015			
	HWPE0239	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.4	0				Mos	29-Oct-2015			
	HWNT3326	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.4	0				Mos	29-Oct-2015			
	HWNT3382	New	0				Hrs	0			
			0				Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.40	0				Mos	29-Oct-2015			
	HWPE0211	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.40	0				Mos	29-Oct-2015			
	HWPE0248	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.41	0				Mos	29-Oct-2015			
	HWPE0214	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.41	0				Mos	29-Oct-2015			
	HWP3941	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.42	0				Mos	29-Oct-2015			
	HWPE0233	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.42	0				Mos	29-Oct-2015			
	HWP3944	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.43	0				Mos	29-Oct-2015			
	HWP4173	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.43	0				Mos	29-Oct-2015			
	HWP3947	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.44	0				Mos	29-Oct-2015			
	HWP4196	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.44	0				Mos	29-Oct-2015			
	HWP3958	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.45	0				Mos	29-Oct-2015			
	HWP4230	New	0				Hrs	0			
			0				Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG2	High Pressure Turbine Blade No.45	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP4158		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.46	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP4234		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.46	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP4162		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.47	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP4588		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.47	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP4182		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.48	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP4598		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.48	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP4227		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.49	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP4635		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.49	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP4243		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.5	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWNT3355		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.5	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWNT3376		0				Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG1	High Pressure Turbine Blade No.50	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP4645		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.50	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP4838		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.51	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP4667		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.51	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP4864		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.52	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP4674		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.52	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP4890		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.53	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP4678		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.53	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP5113		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.54	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP4679		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.54	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP5117		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.55	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP4686		0				Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG2	High Pressure Turbine Blade No.55	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP5119		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.56	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP54688		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.56	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP5160		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.57	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP5150		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.57	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP5181		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.58	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP5174		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.58	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP5185		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.59	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP5186		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.59	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWP5218		0				Enc	0			
	72 ENG1	High Pressure Turbine Blade No.6	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWNT3356		0				Enc	0			
	72 ENG2	High Pressure Turbine Blade No.6	0				Mos	29-Oct-2015		RE (O/C)	
	30J1581-01	New	0				Hrs	0			
	HWNT3377		0				Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.60	0				Mos	29-Oct-2015			
	HWP5189	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.60	0				Mos	29-Oct-2015			
	HWP5224	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.61	0				Mos	29-Oct-2015			
	HWP5204	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.61	0				Mos	29-Oct-2015			
	HWP5232	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.62	0				Mos	29-Oct-2015			
	HWP5219	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.62	0				Mos	29-Oct-2015			
	HWP8283	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.63	0				Mos	29-Oct-2015			
	HWP5221	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.63	0				Mos	29-Oct-2015			
	HWP8290	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.64	0				Mos	29-Oct-2015			
	HWP5223	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.64	0				Mos	29-Oct-2015			
	HWP9513	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.65	0				Mos	29-Oct-2015			
	HWP5234	New	0				Hrs	0			
			0				Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.65	0				Mos	29-Oct-2015			
	HWPK9523	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.66	0				Mos	29-Oct-2015			
	HWP5237	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.66	0				Mos	29-Oct-2015			
	HWPK9532	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.67	0				Mos	29-Oct-2015			
	HWP5240	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.67	0				Mos	29-Oct-2015			
	HWPK9543	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.68	0				Mos	29-Oct-2015			
	HWPK8298	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.68	0				Mos	29-Oct-2015			
	HWPK9546	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.69	0				Mos	29-Oct-2015			
	HWPK9521	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.69	0				Mos	29-Oct-2015			
	HWPL1114	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.7	0				Mos	29-Oct-2015			
	HWNT3357	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.7	0				Mos	29-Oct-2015			
	HWP2507	New	0				Hrs	0			
			0				Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.70	0				Mos	29-Oct-2015			
	HWPL1164	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.70	0				Mos	29-Oct-2015			
	HWPL1141	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.8	0				Mos	29-Oct-2015			
	HWNT3366	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.8	0				Mos	29-Oct-2015			
	HWPDP2555	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.9	0				Mos	29-Oct-2015			
	HWNT3375	New	0				Hrs	0			
			0				Enc	0			
	72 ENG2	High Pressure Turbine Blade								RE (O/C)	
	30J1581-01	No.9	0				Mos	29-Oct-2015			
	HWPDP2580	New	0				Hrs	0			
			0				Enc	0			
	72 ENG1	High Pressure Turbine Rotor Seal								RE (O/C)	
	Unknown						Mos	29-Oct-2015			
	Unknown						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Rotor Seal								RE (O/C)	
	Unknown						Mos	29-Oct-2015			
	Unknown						Hrs	0			
							Enc	0			
	72 ENG1	HPT Vane Ring								RE (O/C)	
	30J1291CL02	New	0				Mos	29-Oct-2015			
	PDAK42TA01		0				Hrs	0			
			0				Enc	0			
	72 ENG2	HPT Vane Ring								RE (O/C)	
	30J1291CL02	New	0				Mos	29-Oct-2015			
	PDAK42RY01		0				Hrs	0			
			0				Enc	0			
	72 ENG1	Inner Combustion Chamber Liner								RE (O/C)	
	30J3396-01	New	0				Mos	29-Oct-2015			
	A003MB3R		0				Hrs	0			
			0				Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Inner Combustion Chamber Liner								RE (O/C)	
	72 ENG2	New	0			Mos	29-Oct-2015				
	30J3396-01		0			Hrs	0				
	A003MB3P		0			Enc	0				
		Intermediate Case Assembly								RE (O/C)	
	72 ENG1	New	0			Mos	29-Oct-2015				
	30J3740-01		0			Hrs	0				
	A003MNPR		0			Enc	0				
		Intermediate Case Assembly								RE (O/C)	
	72 ENG2	New	0			Mos	29-Oct-2015				
	30J3740-01		0			Hrs	0				
	A003MK21		0			Enc	0				
		Lower Spiral Bevel Gearbox Drive Gearshaft								RE (O/C)	
	72 ENG1	New	0			Mos	29-Oct-2015				
	30J2939-01		0			Hrs	0				
	PKAAA605657		0			Enc	0				
		Lower Spiral Bevel Gearbox Drive Gearshaft								RE (O/C)	
	72 ENG2	New	0			Mos	29-Oct-2015				
	30J2939-01		0			Hrs	0				
	PKAAA805668		0			Enc	0				
		LP Compressor Boost Rotor								RE	EMM - Life Limit ≈29-Aug-2047
	72 ENG1	New	0			Mos	29-Oct-2015				
	30J2210-01		0			Hrs	0				
	A003MDER		0			Enc	0	13,500		13,500	10,924 Enc
		LP Compressor Boost Rotor								RE	EMM - Life Limit ≈29-Aug-2047
	72 ENG2	New	0			Mos	29-Oct-2015				
	30J2210-01		0			Hrs	0				
	A003MDEP		0			Enc	0	13,500		13,500	10,924 Enc
		LP Compressor Fan Rotor								RE	EMM - Life Limit ≈07-May-2040
	72 ENG1	New	0			Mos	29-Oct-2015				
	30J2921-01		0			Hrs	0				
	A003LKXW		0			Enc	0	10,000		10,000	7,424 Enc
		LP Compressor Fan Rotor								RE	EMM - Life Limit ≈07-May-2040
	72 ENG2	New	0			Mos	29-Oct-2015				
	30J2921-01		0			Hrs	0				
	A003LNPP		0			Enc	0	10,000		10,000	7,424 Enc
		LPT Rotor Balancing Assembly								RE (O/C)	
	72 ENG1	New	0			Mos	29-Oct-2015				
	31H3160-01		0			Hrs	0				
	BU5451864		0			Enc	0				
		LPT Rotor Balancing Assembly								RE (O/C)	
	72 ENG2	New	0			Mos	29-Oct-2015				
	31H3160-01		0			Hrs	0				
	BU5451883		0			Enc	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		No. 1 Annular Ball Bearing								RE (O/C)	
	72 ENG1	New	0			Mos	29-Oct-2015				
	31J2816-01		0			Hrs	0				
	FCN425784		0			Enc	0				
		No. 1 Annular Ball Bearing								RE (O/C)	
	72 ENG2	New	0			Mos	29-Oct-2015				
	31J2816-01		0			Hrs	0				
	FCN426787		0			Enc	0				
		No.3 Annular Ball Bearing								RE (O/C)	
	72 ENG1	New	0			Mos	29-Oct-2015				
	31J1272-01		0			Hrs	0				
	FCN424538		0			Enc	0				
		No.3 Annular Ball Bearing								RE (O/C)	
	72 ENG2	New	0			Mos	29-Oct-2015				
	31J1272-01		0			Hrs	0				
	FCN424540		0			Enc	0				
		No.5 Cylindrical Roller Bearing								RE (O/C)	
	72 ENG1	New	0			Mos	29-Oct-2015				
	30J3421-01		0			Hrs	0				
	FCN429000		0			Enc	0				
		No.5 Cylindrical Roller Bearing								RE (O/C)	
	72 ENG2	Unknown				Mos	29-Oct-2015				
	Unknown					Hrs	0				
	Unknown					Enc	0				
		Oil Pump Assembly								RE (O/C)	
	72 ENG1	New	0			Mos	29-Oct-2015				
	30J3365-03		0			Hrs	0				
	EC01A004A935		0			Enc	0				
		Oil Pump Assembly								RE (O/C)	
	72 ENG2	New	0			Mos	29-Oct-2015				
	30J3365-03		0			Hrs	0				
	EC01A004A931		0			Enc	0				
		Outer Combustion Chamber Liner								RE (O/C)	
	72 ENG1	New	0			Mos	29-Oct-2015				
	30J3395-01		0			Hrs	0				
	A003M2HH		0			Enc	0				
		Outer Combustion Chamber Liner								RE (O/C)	
	72 ENG2	New	0			Mos	29-Oct-2015				
	30J3395-01		0			Hrs	0				
	A003MB4A		0			Enc	0				
		Rear Bearing Seal Runner								RE (O/C)	
	72 ENG1	No.4	0			Mos	29-Oct-2015				
	30J3001-01		0			Hrs	0				
	MDAA006A054		0			Enc	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG2 30J3001-01 MDAA006A059	Rear Bearing Seal Runner	RE (O/C)								
		No.4	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	72 ENG1 30J3358-01 KYAA015A291	Rear Bypass Duct Assy	RE (O/C)								
			0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	72 ENG2 30J3358-01 KYAA015A295	Rear Bypass Duct Assy	RE (O/C)								
			0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	72 ENG1 31H3132-06 MAM39529	Stage 2 Turbine Multiple	RE (O/C)								
			0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	72 ENG2 31H3132-06 MAM39527	Stage 2 Turbine Multiple	RE (O/C)								
			0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	72 ENG1 31H3133-01 MAM19920	Stage 3 Turbine Multiple	RE (O/C)								
			0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	72 ENG2 31H3133-01 MAM19919	Stage 3 Turbine Multiple	RE (O/C)								
			0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	72 ENG1 31H3134-01 MAM37505	Stage 4 Turbine Multiple	RE (O/C)								
			0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	72 ENG2 31H3134-01 MAM37504	Stage 4 Turbine Multiple	RE (O/C)								
			0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	72 ENG1 31H3148-01 MAM20942	Turbine	RE (O/C)								
			0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	72 ENG2 31H3148-01 MAM20946	Turbine	RE (O/C)								
			0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Turbine Exhaust								RE (O/C)	
	72 ENG1	New	0			Mos	29-Oct-2015				
	31H3038-06		0			Hrs	0				
	MAM40521		0			Enc	0				
		Turbine Exhaust								RE (O/C)	
	72 ENG2	New	0			Mos	29-Oct-2015				
	31H3038-06		0			Hrs	0				
	MAM40520		0			Enc	0				
		Upper Spiral Bevel Gearbox Drive Gearshaft								RE (O/C)	
	72 ENG1	New	0			Mos	29-Oct-2015				
	30J2938-01		0			Hrs	0				
	PKAAA614331		0			Enc	0				
		Upper Spiral Bevel Gearbox Drive Gearshaft								RE (O/C)	
	72 ENG2	New	0			Mos	29-Oct-2015				
	30J2938-01		0			Hrs	0				
	PKAAA598688		0			Enc	0				
05-50-00-01		FOD								RE (A/R)	EMM - Unscheduled
	72 ENG1					Mos					
						Hrs					
						Enc					
05-50-00-01		FOD								RE (A/R)	EMM - Unscheduled
	72 ENG2					Mos					
						Hrs					
						Enc					
05-50-00-02		Bird Strike								RE (A/R)	EMM - Unscheduled
	72 ENG1					Mos					
						Hrs					
						Enc					
05-50-00-02		Bird Strike								RE (A/R)	EMM - Unscheduled
	72 ENG2					Mos					
						Hrs					
						Enc					
05-50-00-03		Engine Windmilling In Flight								RE (A/R)	EMM - Unscheduled
	72 ENG1					Mos					
						Hrs					
						Enc					
05-50-00-03		Engine Windmilling In Flight								RE (A/R)	EMM - Unscheduled
	72 ENG2					Mos					
						Hrs					
						Enc					
05-50-00-04		Lightning Strike								RE (A/R)	EMM - Unscheduled
	72 ENG1					Mos					
						Hrs					
						Enc					
05-50-00-04		Lightning Strike								RE (A/R)	EMM - Unscheduled
	72 ENG2					Mos					
						Hrs					
						Enc					

OK-ECR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-ECR,SN 560-6198

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
05-50-00-05		Fuel Filter Impending/Actual Bypass						RE (A/R)		EMM - Unscheduled	
	 72 ENG1										
05-50-00-05		Fuel Filter Impending/Actual Bypass						RE (A/R)		EMM - Unscheduled	
	 72 ENG2										
05-50-00-06		Engine Exposed To Fire Extinguishing Agent						RE (A/R)		EMM - Unscheduled	
	 72 ENG1										
	Brand A:726009										
05-50-00-06		Engine Exposed To Fire Extinguishing Agent						RE (A/R)		EMM - Unscheduled	
	 72 ENG2										
	Brand A:726009										
05-50-00-07		Incorrect Engine Shutdown On The Ground						RE (A/R)		EMM - Unscheduled	
	 72 ENG1										
	Brand A:726011										
05-50-00-07		Incorrect Engine Shutdown On The Ground						RE (A/R)		EMM - Unscheduled	
	 72 ENG2										
	Brand A:726011										
05-50-00-08		Heavy Landing						RE (A/R)		EMM - Unscheduled	
	 72 ENG1										
	Brand A:726013										
05-50-00-08		Heavy Landing						RE (A/R)		EMM - Unscheduled	
	 72 ENG2										
	Brand A:726013										
05-50-00-09		Sustained Running At An Oil Temperature Outside Of Limits						RE (A/R)		EMM - Unscheduled	
	 72 ENG1										
	Brand A:726015										
05-50-00-09		Sustained Running At An Oil Temperature Outside Of Limits						RE (A/R)		EMM - Unscheduled	
	 72 ENG2										
	Brand A:726015										
05-50-00-10		Higher-Than-Normal ITT Transient Excursion On Engine Start Due To A Frozen Fan						RE (A/R)		EMM - Unscheduled	
	 72 ENG1										
	Brand A:726017										
05-50-00-10		Higher-Than-Normal ITT Transient Excursion On Engine Start Due To A Frozen Fan						RE (A/R)		EMM - Unscheduled	
	 72 ENG2										
	Brand A:726017										
05-50-00-11		Leakage Of P3 Air In The Nacelle (From Engine P3 Air Tubes, Cabin Air Bleed Ports Or Airframe Tubes)						RE (A/R)		EMM - Unscheduled	
	 72 ENG1										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
05-50-00-11	 72 ENG2	Leakage Of P3 Air In The Nacelle (From Engine P3 Air Tubes, Cabin Air Bleed Ports Or Airframe Tubes)						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
05-50-00-12	 72 ENG1	Aircraft Flown Through A Cloud Of Volcanic Ash						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
		Brand A:726023 (SOURCE: PW545C MM 05-50-00)									
05-50-00-12	 72 ENG2	Aircraft Flown Through A Cloud Of Volcanic Ash						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
		Brand A:726023 (SOURCE: PW545C MM 05-50-00)									
05-50-00-13	 72 ENG1	Starter Generator Fail Indication						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
		(SOURCE: PW545C MM 05-50-00)									
05-50-00-13	 72 ENG2	Starter Generator Fail Indication						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
		(SOURCE: PW545C MM 05-50-00)									
05-50-00-14	 72 ENG1	Hydraulic Pump Unscheduled Removal						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
		(SOURCE: PW545C MM 05-50-00)									
05-50-00-14	 72 ENG2	Hydraulic Pump Unscheduled Removal						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
		(SOURCE: PW545C MM 05-50-00)									
05-50-00-15	 72 ENG1	Fuel Contamination (Fuel contamination with Diesel Exhaust Fluid (DEF) additive, improper concentration of biocide or hydraulic fluid or as recommended by P&WC.)						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
		(SOURCE: PW545C MM 05-50-00)									
05-50-00-15	 72 ENG2	Fuel Contamination (Fuel contamination with Diesel Exhaust Fluid (DEF) additive, improper concentration of biocide or hydraulic fluid or as recommended by P&WC.)						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
		(SOURCE: PW545C MM 05-50-00)									
30325	 72 ENG1	Oil-Pump Plain Seal - Replacement						RE (-)		Category 6	
						Mos					
						Hrs					
30325	 72 ENG2	Oil-Pump Plain Seal - Replacement						RE (-)		Category 6	
						Mos					
						Hrs					
30325 Rev 1	 72 ENG1	Oil-Pump Plain Seal - Replacement						RE (-)		Category 6	
						Mos	29-Oct-2015				
						Hrs	0				
		Eff: 12-Jun-2009 Complied With AT MANUFACTURE						0			
								0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30325 Rev 1	Oil-Pump Plain Seal - Replacement						RE (-)		Category 6	
 72 ENG2						Mos	29-Oct-2015			
Eff: 12-Jun-2009 Complied With	AT MANUFACTURE					Hrs	0			
						Enc	0			
30325 Rev 3	Oil-Pump Plain Seal - Replacement						RE (-)		Category 6	
 72 ENG1						Mos				
Eff: 30-Aug-2017						Hrs				
(AVG MAN HRS: 2)						Enc				
30325 Rev 3	Oil-Pump Plain Seal - Replacement						RE (-)		Category 6	
 72 ENG2						Mos				
Eff: 30-Aug-2017						Hrs				
(AVG MAN HRS: 2)						Enc				
30333	Fan Rotor Balancing Assembly - Replacement / Modification						RE (-)		Category 7	
 72 ENG1						Mos	29-Oct-2015			
Eff: 26-Jan-2010 Complied With	AT MANUFACTURE					Hrs	0			
						Enc	0			
30333	Fan Rotor Balancing Assembly - Replacement / Modification						RE (-)		Category 7	
 72 ENG2						Mos	29-Oct-2015			
Eff: 26-Jan-2010 Complied With	AT MANUFACTURE					Hrs	0			
						Enc	0			
30354	Accessory-Gearbox Plain-Seal - Replacement						RE (-)		Category 7	
 72 ENG1						Mos				
						Hrs				
						Enc				
30354	Accessory-Gearbox Plain-Seal - Replacement						RE (-)		Category 7	
 72 ENG2						Mos				
						Hrs				
						Enc				
30354 Rev 1	Accessory-Gearbox Plain-Seal - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	29-Oct-2015			
Eff: 28-Apr-2008 Complied With	AT MANUFACTURE					Hrs	0			
						Enc	0			
30354 Rev 1	Accessory-Gearbox Plain-Seal - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	29-Oct-2015			
Eff: 28-Apr-2008 Complied With	AT MANUFACTURE					Hrs	0			
						Enc	0			
30361	Outer Front Bypass Duct With New Studs - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	29-Oct-2015			
Eff: 05-May-2008 Complied With	AT MANUFACTURE					Hrs	0			
						Enc	0			
30361	Outer Front Bypass Duct With New Studs - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	29-Oct-2015			
Eff: 05-May-2008 Complied With	AT MANUFACTURE					Hrs	0			
						Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30362		HP Turbine Disk Balancing Assembly with Thicker Feather Seals - Replacement						RE (-)		Category 6	
	72 ENG1						Mos	29-Oct-2015			
	Eff: 05-Jun-2008 Complied With	AT MANUFACTURE					Hrs	0			
							Enc	0			
30362		HP Turbine Disk Balancing Assembly with Thicker Feather Seals - Replacement						RE (-)		Category 6	
	72 ENG2						Mos	29-Oct-2015			
	Eff: 05-Jun-2008 Complied With	AT MANUFACTURE					Hrs	0			
							Enc	0			
30365		Inlet Pressure Oil Tube Assy - Replacement						RE (-)		Category 7	
	72 ENG1						Mos	29-Oct-2015			
	Eff: 09-May-2008 Complied With	AT MANUFACTURE					Hrs	0			
							Enc	0			
30365		Inlet Pressure Oil Tube Assy - Replacement						RE (-)		Category 7	
	72 ENG2						Mos	29-Oct-2015			
	Eff: 09-May-2008 Complied With	AT MANUFACTURE					Hrs	0			
							Enc	0			
30366		Air/Oil Separator - Replacement						RE (-)		Category 7	
	72 ENG1						Mos	29-Oct-2015			
	Eff: 01-May-2008 Complied With	AT MANUFACTURE					Hrs	0			
							Enc	0			
30366		Air/Oil Separator - Replacement						RE (-)		Category 7	
	72 ENG2						Mos	29-Oct-2015			
	Eff: 01-May-2008 Complied With	AT MANUFACTURE					Hrs	0			
							Enc	0			
30369		Oil Pump Assembly With A New Rear Oil Pump Housing - Replacement/Modification						RE (-)		Category 6	
	72 ENG1						Mos				
							Hrs				
							Enc				
30369		Oil Pump Assembly With A New Rear Oil Pump Housing - Replacement/Modification						RE (-)		Category 6	
	72 ENG2						Mos				
							Hrs				
							Enc				
30369 Rev 1		Oil Pump Assembly With A New Rear Oil Pump Housing - Replacement/Modification						RE (-)		Category 6	
	72 ENG1						Mos	29-Oct-2015			
	Eff: 02-Sep-2011 Complied With	AT MANUFACTURE					Hrs	0			
							Enc	0			
30369 Rev 1		Oil Pump Assembly With A New Rear Oil Pump Housing - Replacement/Modification						RE (-)		Category 6	
	72 ENG2						Mos	29-Oct-2015			
	Eff: 02-Sep-2011 Complied With	AT MANUFACTURE					Hrs	0			
							Enc	0			
30370		Fuel Metering Unit - Replacement						RE (-)		Category 7	
	72 ENG1						Mos				
							Hrs				
							Enc				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30370		Fuel Metering Unit - Replacement						RE (-)		Category 7	
	72 ENG2					Mos					
						Hrs					
						Enc					
30370 Rev 1		Fuel Metering Unit - Replacement						RE (-)		Category 7	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 16-Feb-2009 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30370 Rev 1		Fuel Metering Unit - Replacement						RE (-)		Category 7	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 16-Feb-2009 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30371		Accessory Gearbox FCU - Starter Gearshaft Oil Baffle - Introduction						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
30371		Accessory Gearbox FCU - Starter Gearshaft Oil Baffle - Introduction						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
30371 Rev 1		Accessory Gearbox FCU - Starter Gearshaft Oil Baffle - Introduction						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
30371 Rev 1		Accessory Gearbox FCU - Starter Gearshaft Oil Baffle - Introduction						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
30371 Rev 2		Accessory Gearbox FCU - Starter Gearshaft Oil Baffle - Introduction						RE (-)		Category 10	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 11-Mar-2014 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30371 Rev 2		Accessory Gearbox FCU - Starter Gearshaft Oil Baffle - Introduction						RE (-)		Category 10	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 11-Mar-2014 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30373		Secondary Fuel Pressure Tube and Support Bracket - Replacement						RE (-)		Category 3	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 15-Aug-2008 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30373		Secondary Fuel Pressure Tube and Support Bracket - Replacement						RE (-)		Category 3	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 15-Aug-2008 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30376		Oil Pump Assembly and Oil-Pump-Drive Spur Gear - Replacement/Modification						RE (-)		Category 7	
	72 ENG1					Mos					
						Hrs					
						Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30376		Oil Pump Assembly and Oil-Pump-Drive Spur Gear - Replacement/Modification						RE (-)		Category 7	
	72 ENG2					Mos					
						Hrs					
						Enc					
30376 Rev 1		Oil Pump Assembly and Oil-Pump-Drive Spur Gear - Replacement/Modification						RE (-)		Category 7	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 19-Dec-2011 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30376 Rev 1		Oil Pump Assembly and Oil-Pump-Drive Spur Gear - Replacement/Modification						RE (-)		Category 7	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 19-Dec-2011 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30376 Rev 2		Oil Pump Assembly and Oil-Pump-Drive Spur Gear - Replacement/Modification						RE (-)		Category 7	
	72 ENG1					Mos					
	Eff: 16-Jun-2016					Hrs					
						Enc					
30376 Rev 2		Oil Pump Assembly and Oil-Pump-Drive Spur Gear - Replacement/Modification						RE (-)		Category 7	
	72 ENG2					Mos					
	Eff: 16-Jun-2016					Hrs					
						Enc					
30379		By-Pass Ducts - Replacement/Modification						RE (-)		Category 7	
	72 ENG1					Mos	29-Oct-2015				
	Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30379		By-Pass Ducts - Replacement/Modification						RE (-)		Category 7	
	72 ENG2					Mos	29-Oct-2015				
	Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30379 Rev 1		By-Pass Ducts - Replacement/Modification						T (A/R)		Category 7	
	72 ENG1					Mos					
	Eff: 11-Sep-2015					Hrs					
						Enc					
30379 Rev 1		By-Pass Ducts - Replacement/Modification						T (A/R)		Category 7	
	72 ENG2					Mos					
	Eff: 11-Sep-2015					Hrs					
						Enc					
30380		Gearbox-Drive-Shaft-Accessory Gearbox Drive Gearshaft-Assembly Gearbox Drive Spline Bevel- Gearshaft / Replacement						RE (-)		Category 7	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 09-Dec-2008 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30380		Gearbox-Drive-Shaft-Accessory Gearbox Drive Gearshaft-Assembly Gearbox Drive Spline Bevel- Gearshaft / Replacement						RE (-)		Category 7	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 09-Dec-2008 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30384		Air/Oil Separator - Replacement						RE (-)		Category 6	
	72 ENG1					Mos					
						Hrs					
						Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30384		Air/Oil Separator - Replacement						RE (-)		Category 6	
	72 ENG2						Mos				
							Hrs				
							Enc				
30384 Rev 1		Air/Oil Separator - Replacement						RE (-)		Category 6	
	72 ENG1						Mos	29-Oct-2015			
	Eff: 02-Sep-2011 Complied With	AT MANUFACTURE					Hrs	0			
							Enc	0			
30384 Rev 1		Air/Oil Separator - Replacement						RE (-)		Category 6	
	72 ENG2						Mos	29-Oct-2015			
	Eff: 02-Sep-2011 Complied With	AT MANUFACTURE					Hrs	0			
							Enc	0			
30385		Data Collection Unit - Replacement						RE (-)		Category 6	
	72 ENG1						Mos	29-Oct-2015			
	Eff: 27-Jan-2009 Complied With	AT MANUFACTURE					Hrs	0			
							Enc	0			
30385		Data Collection Unit - Replacement						RE (-)		Category 6	
	72 ENG2						Mos	29-Oct-2015			
	Eff: 27-Jan-2009 Complied With	AT MANUFACTURE					Hrs	0			
							Enc	0			
30389		Carbon Seal No. 4 Bearing - Replacement						RE (-)		Category 7	
	72 ENG1						Mos	29-Oct-2015			
	Eff: 05-Mar-2009 Complied With	AT MANUFACTURE					Hrs	0			
							Enc	0			
30389		Carbon Seal No. 4 Bearing - Replacement						RE (-)		Category 7	
	72 ENG2						Mos	29-Oct-2015			
	Eff: 05-Mar-2009 Complied With	AT MANUFACTURE					Hrs	0			
							Enc	0			
30391		Inlet Pressure Oil Tube Assy - Replacement						RE (-)		Category 7	
	72 ENG1						Mos	29-Oct-2015			
	Eff: 11-Jun-2009 Complied With	AT MANUFACTURE					Hrs	0			
							Enc	0			
30391		Inlet Pressure Oil Tube Assy - Replacement						RE (-)		Category 7	
	72 ENG2						Mos	29-Oct-2015			
	Eff: 11-Jun-2009 Complied With	AT MANUFACTURE					Hrs	0			
							Enc	0			
30392		Bolts - Replacement						RE (-)		Category 7	
	72 ENG1						Mos	29-Oct-2015			
	Eff: 25-Jun-2009 Complied With	AT MANUFACTURE					Hrs	0			
							Enc	0			
30392		Bolts - Replacement						RE (-)		Category 7	
	72 ENG2						Mos	29-Oct-2015			
	Eff: 25-Jun-2009 Complied With	AT MANUFACTURE					Hrs	0			
							Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30393		EEC Support Brackets - Replacement						RE (-)		Category 3	
	72 ENG1					Mos	09-Sep-2021				
	Not Applicable	R1 is c/w				Hrs	2218:31				
						Enc	1,685				
30393		EEC Support Brackets - Replacement						RE (-)		Category 3	
	72 ENG2					Mos	09-Sep-2021				
	Not Applicable	R1 is c/w				Hrs	2218:31				
						Enc	1,685				
30393 Rev 1		EEC Support Brackets - Replacement						RE (-)		Category 3	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 02-Jun-2010 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30393 Rev 1		EEC Support Brackets - Replacement						RE (-)		Category 3	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 02-Jun-2010 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30400		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7	
	72 ENG1					Mos					
						Hrs					
						Enc					
30400		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7	
	72 ENG2					Mos					
						Hrs					
						Enc					
30400 Rev 1		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7	
	72 ENG1					Mos					
						Hrs					
						Enc					
30400 Rev 1		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7	
	72 ENG2					Mos					
						Hrs					
						Enc					
30400 Rev 2		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7	
	72 ENG1					Mos					
						Hrs					
						Enc					
30400 Rev 2		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7	
	72 ENG2					Mos					
						Hrs					
						Enc					
30400 Rev 3		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 31-Oct-2012 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30400 Rev 3		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 31-Oct-2012 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30400 Rev 4		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7	
	72 ENG1										
	Eff: 23-Nov-2016										
30400 Rev 4		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7	
	72 ENG2										
	Eff: 23-Nov-2016										
30400 Rev 4 Part A		Intermediate Case Assembly - Replacement						RE (-)		Category 6	
	72 ENG1										
	Eff: 23-Nov-2016										
30400 Rev 4 Part A		Intermediate Case Assembly - Replacement						RE (-)		Category 6	
	72 ENG2										
	Eff: 23-Nov-2016										
30400 Rev 4 Part B		Intershaft Seal Carrier - Replacement						RE (-)		Category 7	
	72 ENG1										
	Eff: 23-Nov-2016										
30400 Rev 4 Part B		Intershaft Seal Carrier - Replacement						RE (-)		Category 7	
	72 ENG2										
	Eff: 23-Nov-2016										
30401		Electronic Engine Control Re-Programming / Replacement-Modification						RE (-)		Category 10	
	72 ENG1										
30401		Electronic Engine Control Re-Programming / Replacement-Modification						RE (-)		Category 10	
	72 ENG2										
30401 Rev 1		Electronic Engine Control Re-Programming / Replacement-Modification						RE (-)		Category 10	
	72 ENG1										
30401 Rev 1		Electronic Engine Control Re-Programming / Replacement-Modification						RE (-)		Category 10	
	72 ENG2										
30401 Rev 2		Electronic Engine Control Re-Programming / Replacement-Modification						T (A/R)		Category 10	
	72 ENG1										
	Eff: 20-Aug-2015										
30401 Rev 2		Electronic Engine Control Re-Programming / Replacement-Modification						T (A/R)		Category 10	
	72 ENG2										
	Eff: 20-Aug-2015										
30403		Replacement of Tee Head Bolt/1st - 2nd. Stage HP Compressor Assemblies						RE (-)		Category 6	
	72 ENG1										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30403		Replacement of Tee Head Bolt/1st - 2nd. Stage HP Compressor Assemblies						RE (-)		Category 6	
	72 ENG2					Mos					
						Hrs					
						Enc					
30403 Rev 1		Replacement of Tee Head Bolt/1st - 2nd. Stage HP Compressor Assemblies						RE (-)		Category 6	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 02-Oct-2009 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30403 Rev 1		Replacement of Tee Head Bolt/1st - 2nd. Stage HP Compressor Assemblies						RE (-)		Category 6	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 02-Oct-2009 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30403 Rev 2		Replacement of Tee Head Bolt/1st - 2nd Stage HP Compressor Assemblies						RE (-)		Category 6	
	72 ENG1					Mos					
	Eff: 20-Apr-2017					Hrs					
						Enc					
30403 Rev 2		Replacement of Tee Head Bolt/1st - 2nd Stage HP Compressor Assemblies						RE (-)		Category 6	
	72 ENG2					Mos					
	Eff: 20-Apr-2017					Hrs					
						Enc					
30403 Rev 3		Replacement of Tee Head Bolt/1st - 2nd Stage HP Compressor Assemblies						RE (-)		Category 6	
	72 ENG1					Mos					
	Eff: 05-Mar-2018					Hrs					
						Enc					
30403 Rev 3		Replacement of Tee Head Bolt/1st - 2nd Stage HP Compressor Assemblies						RE (-)		Category 6	
	72 ENG2					Mos					
	Eff: 05-Mar-2018					Hrs					
						Enc					
30403 Rev 4		Replacement of Tee Head Bolt/1st - 2nd Stage HP Compressor Assemblies						RE (-)		Category 6	
	72 ENG1					Mos					
	Eff: 12-Feb-2019					Hrs					
						Enc					
30403 Rev 4		Replacement of Tee Head Bolt/1st - 2nd Stage HP Compressor Assemblies						RE (-)		Category 6	
	72 ENG2					Mos					
	Eff: 12-Feb-2019					Hrs					
						Enc					
30404		Servo Valve For The Intercompressor Bleed-Valve - Replacement						RE (-)		Category 7	
	72 ENG1					Mos					
						Hrs					
						Enc					
30404		Servo Valve For The Intercompressor Bleed-Valve - Replacement						RE (-)		Category 7	
	72 ENG2					Mos					
						Hrs					
						Enc					
30404 Rev 1		Servo Valve For The Intercompressor Bleed-Valve - Replacement						RE (-)		Category 7	
	72 ENG1					Mos					
						Hrs					
						Enc					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30404 Rev 1  72 ENG2	Servo Valve For The Intercompressor Bleed-Valve - Replacement						RE (-)		Category 7	
					Mos					
					Hrs					
					Enc					
30404 Rev 2  72 ENG1	Servo Valve For The Intercompressor Bleed-Valve - Replacement						RE (-)		Category 7	
					Mos					
					Hrs					
					Enc					
30404 Rev 2  72 ENG2	Servo Valve For The Intercompressor Bleed-Valve - Replacement						RE (-)		Category 7	
					Mos					
					Hrs					
					Enc					
30404 Rev 3  72 ENG1 Eff: 03-May-2010 Complied AT MANUFACTURE With	Servo Valve For The Intercompressor Bleed-Valve - Replacement						RE (-)		Category 7	
					Mos	29-Oct-2015				
					Hrs	0				
					Enc	0				
30404 Rev 3  72 ENG2 Eff: 03-May-2010 Complied AT MANUFACTURE With	Servo Valve For The Intercompressor Bleed-Valve - Replacement						RE (-)		Category 7	
					Mos	29-Oct-2015				
					Hrs	0				
					Enc	0				
30407  72 ENG1 Eff: 12-Nov-2009 Complied AT MANUFACTURE With	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 7	
					Mos	29-Oct-2015				
					Hrs	0				
					Enc	0				
30407  72 ENG2 Eff: 12-Nov-2009 Complied AT MANUFACTURE With	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 7	
					Mos	29-Oct-2015				
					Hrs	0				
					Enc	0				
30407 Rev 1  72 ENG1 Eff: 30-Aug-2017 (AVG MAN HRS: 2)	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 7	
					Mos					
					Hrs					
					Enc					
30407 Rev 1  72 ENG2 Eff: 30-Aug-2017 (AVG MAN HRS: 2)	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 7	
					Mos					
					Hrs					
					Enc					
30411  72 ENG1	Gaskets - Replacement						RE (-)		Category 6	
					Mos					
					Hrs					
					Enc					
30411  72 ENG2	Gaskets - Replacement						RE (-)		Category 6	
					Mos					
					Hrs					
					Enc					
30411 Rev 1  72 ENG1 Eff: 22-Mar-2010 Complied AT MANUFACTURE With	Gaskets - Replacement						RE (-)		Category 6	
					Mos	29-Oct-2015				
					Hrs	0				
					Enc	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30411 Rev 1		Gaskets - Replacement						RE (-)		Category 6	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 22-Mar-2010 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30413		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG1					Mos					
						Hrs					
						Enc					
30413		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG2					Mos					
						Hrs					
						Enc					
30413 Rev 1		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG1					Mos					
						Hrs					
						Enc					
30413 Rev 1		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG2					Mos					
						Hrs					
						Enc					
30413 Rev 10		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG1					Mos					
	Eff: 29-Aug-2017					Hrs					
						Enc					
30413 Rev 10		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG2					Mos					
	Eff: 29-Aug-2017					Hrs					
						Enc					
30413 Rev 11		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG1					Mos					
	Eff: 30-Nov-2018					Hrs					
						Enc					
30413 Rev 11		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG2					Mos					
	Eff: 30-Nov-2018					Hrs					
						Enc					
30413 Rev 12		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG1					Mos					
	Eff: 21-Dec-2021					Hrs					
						Enc					
30413 Rev 12		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG2					Mos					
	Eff: 21-Dec-2021					Hrs					
						Enc					
30413 Rev 2		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG1					Mos					
						Hrs					
						Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30413 Rev 2		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG2					Mos					
						Hrs					
						Enc					
30413 Rev 3		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG1					Mos					
						Hrs					
						Enc					
30413 Rev 3		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG2					Mos					
						Hrs					
						Enc					
30413 Rev 4		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG1					Mos					
						Hrs					
						Enc					
30413 Rev 4		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG2					Mos					
						Hrs					
						Enc					
30413 Rev 5		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG1					Mos					
						Hrs					
						Enc					
30413 Rev 5		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG2					Mos					
						Hrs					
						Enc					
30413 Rev 6		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG1					Mos					
						Hrs					
						Enc					
30413 Rev 6		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG2					Mos					
						Hrs					
						Enc					
30413 Rev 7		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 08-Oct-2013 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30413 Rev 7		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 08-Oct-2013 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30413 Rev 8		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG1					Mos					
	Eff: 08-Jan-2016					Hrs					
						Enc					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30413 Rev 8	Introduction of Deeper Sump						RE (-)		Category 6	
 72 ENG2						Mos				
Eff: 08-Jan-2016						Hrs				
						Enc				
30413 Rev 9	Introduction of Deeper Sump						RE (-)		Category 6	
 72 ENG1						Mos				
Eff: 10-Aug-2016						Hrs				
						Enc				
30413 Rev 9	Introduction of Deeper Sump						RE (-)		Category 6	
 72 ENG2						Mos				
Eff: 10-Aug-2016						Hrs				
						Enc				
30415	No. 4 Roller Bearing - Replacement						RE (-)		Category 6	
 72 ENG1						Mos				
						Hrs				
						Enc				
30415	No. 4 Roller Bearing - Replacement						RE (-)		Category 6	
 72 ENG2						Mos				
						Hrs				
						Enc				
30415 Rev 1	No. 4 Roller Bearing - Replacement						RE (-)		Category 6	
 72 ENG1						Mos	29-Oct-2015			
Eff: 13-May-2013 Complied	AT MANUFACTURE					Hrs	0			
With						Enc	0			
30415 Rev 1	No. 4 Roller Bearing - Replacement						RE (-)		Category 6	
 72 ENG2						Mos	29-Oct-2015			
Eff: 13-May-2013 Complied	AT MANUFACTURE					Hrs	0			
With						Enc	0			
30415 Rev 2	No. 4 Roller Bearing - Replacement						RE (-)		Category 6	
 72 ENG1						Mos				
Eff: 06-Jan-2016						Hrs				
						Enc				
30415 Rev 2	No. 4 Roller Bearing - Replacement						RE (-)		Category 6	
 72 ENG2						Mos				
Eff: 06-Jan-2016						Hrs				
						Enc				
30415 Rev 3	Replacement of No. 4 Roller Bearing						RE (-)		Category 6	
 72 ENG1						Mos				
Eff: 13-Oct-2016						Hrs				
						Enc				
30415 Rev 3	Replacement of No. 4 Roller Bearing						RE (-)		Category 6	
 72 ENG2						Mos				
Eff: 13-Oct-2016						Hrs				
						Enc				
30415 Rev 4	Replacement of No. 4 Roller Bearing						RE (-)		Category 6	
 72 ENG1						Mos				
Eff: 06-Aug-2020						Hrs				
						Enc				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30415 Rev 4		Replacement of No. 4 Roller Bearing						RE (-)		Category 6	
	72 ENG2					Mos					
	Eff: 06-Aug-2020					Hrs					
						Enc					
30416		No.4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
30416		No.4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
30416 Rev 1		No.4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 23-Oct-2013 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30416 Rev 1		No.4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 23-Oct-2013 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30417		Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
30417		Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
30417 Rev 1		Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
30417 Rev 1		Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
30417 Rev 2		Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
30417 Rev 2		Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
30417 Rev 3		Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30417 Rev 3  72 ENG2	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
						Mos				
						Hrs				
						Enc				
30417 Rev 4  72 ENG1	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
						Mos				
						Hrs				
						Enc				
30417 Rev 4  72 ENG2	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
						Mos				
						Hrs				
						Enc				
30417 Rev 5  72 ENG1	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
						Mos				
						Hrs				
						Enc				
30417 Rev 5  72 ENG2	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
						Mos				
						Hrs				
						Enc				
30417 Rev 6  72 ENG1	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
						Mos				
						Hrs				
						Enc				
30417 Rev 6  72 ENG2	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
						Mos				
						Hrs				
						Enc				
30417 Rev 7  72 ENG1	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
						Mos				
						Hrs				
						Enc				
30417 Rev 7  72 ENG2	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
						Mos				
						Hrs				
						Enc				
30417 Rev 8  72 ENG1 Eff: 23-Nov-2012 Complied AT MANUFACTURE With	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
						Mos	29-Oct-2015			
						Hrs	0			
						Enc	0			
30417 Rev 8  72 ENG2 Eff: 23-Nov-2012 Complied AT MANUFACTURE With	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
						Mos	29-Oct-2015			
						Hrs	0			
						Enc	0			
30418  72 ENG1	Electrical Wiring Harness (TT0 Sensor) - Replacement						RE (-)		Category 6	
						Mos				
						Hrs				
						Enc				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30418		Electrical Wiring Harness (TT0 Sensor) - Replacement						RE (-)		Category 6	
	72 ENG2					Mos					
						Hrs					
						Enc					
30418 Rev 1		Electrical Wiring Harness (TT0 Sensor) - Replacement						RE (-)		Category 6	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 12-Apr-2011 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30418 Rev 1		Electrical Wiring Harness (TT0 Sensor) - Replacement						RE (-)		Category 6	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 12-Apr-2011 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30419		Combustion Chamber Liner - Replacement						RE (-)		Category 7	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 28-Sep-2010 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30419		Combustion Chamber Liner - Replacement						RE (-)		Category 7	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 28-Sep-2010 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30419 Rev 1		Combustion Chamber Liner - Replacement						RE (-)		Category 7	
	72 ENG1					Mos					
	Eff: 26-Feb-2016					Hrs					
						Enc					
30419 Rev 1		Combustion Chamber Liner - Replacement						RE (-)		Category 7	
	72 ENG2					Mos					
	Eff: 26-Feb-2016					Hrs					
						Enc					
30420		Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6	
	72 ENG1					Mos	09-Sep-2021				
	Not Applicable	R4 is c/w				Hrs	2218:31				
						Enc	1,685				
30420		Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6	
	72 ENG2					Mos	09-Sep-2021				
	Not Applicable	R4 is c/w				Hrs	2218:31				
						Enc	1,685				
30420 Rev 1		Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6	
	72 ENG1					Mos	09-Sep-2021				
	Not Applicable	R4 is c/w				Hrs	2218:31				
						Enc	1,685				
30420 Rev 1		Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6	
	72 ENG2					Mos	09-Sep-2021				
	Not Applicable	R4 is c/w				Hrs	2218:31				
						Enc	1,685				
30420 Rev 2		Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6	
	72 ENG1					Mos	09-Sep-2021				
	Not Applicable	R4 is c/w				Hrs	2218:31				
						Enc	1,685				

Task No	Description										Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
30420 Rev 2		Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6		
	72 ENG2					Mos	09-Sep-2021					
	Not Applicable	R4 is c/w				Hrs	2218:31					
						Enc	1,685					
30420 Rev 3		Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6		
	72 ENG1					Mos	09-Sep-2021					
	Not Applicable	R4 is c/w				Hrs	2218:31					
						Enc	1,685					
30420 Rev 3		Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6		
	72 ENG2					Mos	09-Sep-2021					
	Not Applicable	R4 is c/w				Hrs	2218:31					
						Enc	1,685					
30420 Rev 4		Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6		
	72 ENG1					Mos	29-Oct-2015					
	Eff: 18-Jun-2014 Complied With	AT MANUFACTURE				Hrs	0					
						Enc	0					
30420 Rev 4		Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6		
	72 ENG2					Mos	29-Oct-2015					
	Eff: 18-Jun-2014 Complied With	AT MANUFACTURE				Hrs	0					
						Enc	0					
30420 Rev 5		Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6		
	72 ENG1					Mos	09-Sep-2021					
	Eff: 20-Apr-2018 Not Applicable	R4 is c/w				Hrs	2218:31					
	(AVG MAN HRS: 4)					Enc	1,685					
30420 Rev 5		Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6		
	72 ENG2					Mos	09-Sep-2021					
	Eff: 20-Apr-2018 Not Applicable	as per S/N				Hrs	2218:31					
	(AVG MAN HRS: 4)					Enc	1,685					
30420 Rev 6		Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6		
	72 ENG1					Mos	09-Sep-2021					
	Eff: 16-Jul-2020 Not Applicable	as per S/N				Hrs	2218:31					
	(AVG MAN HRS: 4)					Enc	1,685					
30420 Rev 6		Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6		
	72 ENG2					Mos	09-Sep-2021					
	Eff: 16-Jul-2020 Not Applicable	as per S/N				Hrs	2218:31					
	(AVG MAN HRS: 4)					Enc	1,685					
30423		Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6		
	72 ENG1					Mos						
						Hrs						
						Enc						
30423		Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6		
	72 ENG2					Mos						
						Hrs						
						Enc						

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30423 Rev 1		Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 17-Sep-2012 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30423 Rev 1		Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 17-Sep-2012 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30425		No. 4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
30425		No. 4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
30425 Rev 1		No. 4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
30425 Rev 1		No. 4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
30425 Rev 2		No. 4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
30425 Rev 2		No. 4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
30425 Rev 3		No. 4 Bearing Carbon Seal - Replacement						T (A/R)		Category 10	
	72 ENG1					Mos					
	Eff: 23-Oct-2013					Hrs					
						Enc					
30425 Rev 3		No. 4 Bearing Carbon Seal - Replacement						T (A/R)		Category 10	
	72 ENG2					Mos					
	Eff: 23-Oct-2013					Hrs					
						Enc					
30426		Fan Case Assembly - Replacement						RE (-)		Category 7	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 08-Jul-2011 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30426		Fan Case Assembly - Replacement						RE (-)		Category 7	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 08-Jul-2011 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30427	72 ENG1	Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30427	72 ENG2	Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30427 Rev 1	72 ENG1	Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30427 Rev 1	72 ENG2	Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30427 Rev 2	72 ENG1	Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30427 Rev 2	72 ENG2	Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30427 Rev 3	72 ENG1 Eff: 13-Mar-2013 Complied With	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 7	
						Mos	29-Oct-2015				
						Hrs	0				
						Enc	0				
30427 Rev 3	72 ENG2 Eff: 13-Mar-2013 Complied With	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 7	
						Mos	29-Oct-2015				
						Hrs	0				
						Enc	0				
30427 Rev 4	72 ENG1 Eff: 06-Nov-2018 (AVG MAN HRS: 3)	Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30427 Rev 4	72 ENG2 Eff: 06-Nov-2018 (AVG MAN HRS: 3)	Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30428	72 ENG1	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
						Mos					
						Hrs					
						Enc					
30428	72 ENG2	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
						Mos					
						Hrs					
						Enc					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30428 Rev 1  72 ENG1	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
					Mos					
					Hrs					
					Enc					
30428 Rev 1  72 ENG2	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
					Mos					
					Hrs					
					Enc					
30428 Rev 2  72 ENG1	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
					Mos					
					Hrs					
					Enc					
30428 Rev 2  72 ENG2	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
					Mos					
					Hrs					
					Enc					
30428 Rev 3  72 ENG1	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
					Mos					
					Hrs					
					Enc					
30428 Rev 3  72 ENG2	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
					Mos					
					Hrs					
					Enc					
30428 Rev 4  72 ENG1 Eff: 03-May-2013 Complied AT MANUFACTURE With	Replacement Fuel Manifold System Interface					29-Oct-2015	RE (-)		Category 6	
					Mos					
					Hrs	0				
					Enc	0				
30428 Rev 4  72 ENG2 Eff: 03-May-2013 Complied AT MANUFACTURE With	Replacement Fuel Manifold System Interface					29-Oct-2015	RE (-)		Category 6	
					Mos					
					Hrs	0				
					Enc	0				
30428 Rev 5  72 ENG1 Eff: 19-Apr-2017 (AVG MAN HRS: 16)	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
					Mos					
					Hrs					
					Enc					
30428 Rev 5  72 ENG2 Eff: 19-Apr-2017 (AVG MAN HRS: 16)	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
					Mos					
					Hrs					
					Enc					
30428 Rev 6  72 ENG1 Eff: 08-Feb-2019 (AVG MAN HRS: 16)	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
					Mos					
					Hrs					
					Enc					
30428 Rev 6  72 ENG2 Eff: 08-Feb-2019 (AVG MAN HRS: 16)	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
					Mos					
					Hrs					
					Enc					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30429	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG1						Mos				
						Hrs				
						Enc				
30429	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG2						Mos				
						Hrs				
						Enc				
30429 Rev 1	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG1						Mos				
						Hrs				
						Enc				
30429 Rev 1	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG2						Mos				
						Hrs				
						Enc				
30429 Rev 2	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG1						Mos				
						Hrs				
						Enc				
30429 Rev 2	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG2						Mos				
						Hrs				
						Enc				
30429 Rev 3	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG1						Mos	29-Oct-2015			
Eff: 22-Jun-2015 Complied	AT MANUFACTURE					Hrs	0			
With						Enc	0			
30429 Rev 3	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG2						Mos	29-Oct-2015			
Eff: 22-Jun-2015 Complied	AT MANUFACTURE					Hrs	0			
With						Enc	0			
30429 Rev 4	Intermediate Case Assembly - Replacement/Modification						T (-)		Category 6	
 72 ENG1						Mos				
Eff: 14-Mar-2016						Hrs				
						Enc				
30429 Rev 4	Intermediate Case Assembly - Replacement/Modification						T (-)		Category 6	
 72 ENG2						Mos				
Eff: 14-Mar-2016						Hrs				
						Enc				
30429 Rev 5	Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 6	
 72 ENG1						Mos				
Eff: 10-Aug-2016						Hrs				
						Enc				
30429 Rev 5	Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 6	
 72 ENG2						Mos				
Eff: 10-Aug-2016						Hrs				
						Enc				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30429 Rev 6		Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 6	
	72 ENG1										
	Eff: 02-Aug-2017										
30429 Rev 6		Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 6	
	72 ENG2										
	Eff: 02-Aug-2017										
30432		Plain Seal Accessory Gearbox - Replacement						RE (-)		Category 7	
	72 ENG1										
30432		Plain Seal Accessory Gearbox - Replacement						RE (-)		Category 7	
	72 ENG2										
30432 Rev 1		Plain Seal Accessory Gearbox - Replacement						RE (-)		Category 7	
	72 ENG1										
	Eff: 12-May-2011 Complied	AT MANUFACTURE					29-Oct-2015				
	With						0				
							0				
30432 Rev 1		Plain Seal Accessory Gearbox - Replacement						RE (-)		Category 7	
	72 ENG2										
	Eff: 12-May-2011 Complied	AT MANUFACTURE					29-Oct-2015				
	With						0				
							0				
30434		Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
	72 ENG1										
30434		Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
	72 ENG2										
30434 Rev 1		Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
	72 ENG1										
30434 Rev 1		Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
	72 ENG2										
30434 Rev 2		Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
	72 ENG1										
30434 Rev 2		Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
	72 ENG2										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30434 Rev 3  72 ENG1	Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
					Mos					
					Hrs					
					Enc					
30434 Rev 3  72 ENG2	Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
					Mos					
					Hrs					
					Enc					
30434 Rev 4  72 ENG1 Complied With	Electronic Engine Control / Replacement-Modification AT MANUFACTURE						RE (-)		Category 10	
					Mos	29-Oct-2015				
					Hrs	0				
					Enc	0				
30434 Rev 4  72 ENG2 Complied With	Electronic Engine Control / Replacement-Modification AT MANUFACTURE						RE (-)		Category 10	
					Mos	29-Oct-2015				
					Hrs	0				
					Enc	0				
30434 Rev 5  72 ENG1 Eff: 15-Jul-2015	Electronic Engine Control / Replacement-Modification						T (A/R)		Category 10	
					Mos					
					Hrs					
					Enc					
30434 Rev 5  72 ENG2 Eff: 15-Jul-2015	Electronic Engine Control / Replacement-Modification						T (A/R)		Category 10	
					Mos					
					Hrs					
					Enc					
30436  72 ENG1 Complied With	LPT 2nd Stage Vane Assembly - Replacement/Modification AT MANUFACTURE						RE (-)		Category 7	
					Mos	29-Oct-2015				
					Hrs	0				
					Enc	0				
30436  72 ENG2 Complied With	LPT 2nd Stage Vane Assembly - Replacement/Modification AT MANUFACTURE						RE (-)		Category 7	
					Mos	29-Oct-2015				
					Hrs	0				
					Enc	0				
30436 Rev 1  72 ENG1	LPT 2nd Stage Vane Assembly - Replacement/Modification						RE (-)		Category 7	
					Mos					
					Hrs					
					Enc					
30436 Rev 1  72 ENG2	LPT 2nd Stage Vane Assembly - Replacement/Modification						RE (-)		Category 7	
					Mos					
					Hrs					
					Enc					
30436 Rev 2  72 ENG1	LPT 2nd Stage Vane Assembly - Replacement/Modification						RE (-)		Category 7	
					Mos					
					Hrs					
					Enc					
30436 Rev 2  72 ENG2	LPT 2nd Stage Vane Assembly - Replacement/Modification						RE (-)		Category 7	
					Mos					
					Hrs					
					Enc					
30436 Rev 3  72 ENG1 Eff: 28-Jul-2015	LPT 2nd Stage Vane Assembly - Replacement/Modification						T (-)		Category 7	
					Mos					
					Hrs					
					Enc					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30436 Rev 3  72 ENG2 Eff: 28-Jul-2015	LPT 2nd Stage Vane Assembly - Replacement/Modification						T (-)		Category 7	
						Mos				
						Hrs				
						Enc				
30436 Rev 4  72 ENG1 Eff: 18-Apr-2018	Replacement/Modification of LPT 2nd Stage Vane Assembly						RE (-)		Category 7	
						Mos				
						Hrs				
						Enc				
30436 Rev 4  72 ENG2 Eff: 18-Apr-2018	Replacement/Modification of LPT 2nd Stage Vane Assembly						RE (-)		Category 7	
						Mos				
						Hrs				
						Enc				
30438  72 ENG1	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
						Mos				
						Hrs				
						Enc				
30438  72 ENG2	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
						Mos				
						Hrs				
						Enc				
30438 Rev 1  72 ENG1	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
						Mos				
						Hrs				
						Enc				
30438 Rev 1  72 ENG2	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
						Mos				
						Hrs				
						Enc				
30438 Rev 2  72 ENG1	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
						Mos				
						Hrs				
						Enc				
30438 Rev 2  72 ENG2	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
						Mos				
						Hrs				
						Enc				
30438 Rev 3  72 ENG1	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
						Mos				
						Hrs				
						Enc				
30438 Rev 3  72 ENG2	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
						Mos				
						Hrs				
						Enc				
30438 Rev 4  72 ENG1 Complied With	Electronic Engine Control (EEC) - Replacement/Modification AT MANUFACTURE						RE (-)		Category 10	
						Mos	29-Oct-2015			
						Hrs	0			
						Enc	0			
30438 Rev 4  72 ENG2 Complied With	Electronic Engine Control (EEC) - Replacement/Modification AT MANUFACTURE						RE (-)		Category 10	
						Mos	29-Oct-2015			
						Hrs	0			
						Enc	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30438 Rev 5  72 ENG1 Eff: 15-Jul-2015	Electronic Engine Control (EEC) - Replacement/Modification						T (A/R)		Category 10	
						Mos				
						Hrs				
						Enc				
30438 Rev 5  72 ENG2 Eff: 15-Jul-2015	Electronic Engine Control (EEC) - Replacement/Modification						T (A/R)		Category 10	
						Mos				
						Hrs				
						Enc				
30440  72 ENG1	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
						Mos				
						Hrs				
						Enc				
30440  72 ENG2	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
						Mos				
						Hrs				
						Enc				
30440 Rev 1  72 ENG1	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
						Mos				
						Hrs				
						Enc				
30440 Rev 1  72 ENG2	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
						Mos				
						Hrs				
						Enc				
30440 Rev 2  72 ENG1	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
						Mos				
						Hrs				
						Enc				
30440 Rev 2  72 ENG2	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
						Mos				
						Hrs				
						Enc				
30440 Rev 3  72 ENG1	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
						Mos				
						Hrs				
						Enc				
30440 Rev 3  72 ENG2	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
						Mos				
						Hrs				
						Enc				
30440 Rev 4  72 ENG1 Eff: 07-Oct-2013 Complied With	Replacement of New or Modified Oil Tank Vent Tube Assembly AT MANUFACTURE						RE (-)		Category 6	
						Mos	29-Oct-2015			
						Hrs	0			
						Enc	0			
30440 Rev 4  72 ENG2 Eff: 07-Oct-2013 Complied With	Replacement of New or Modified Oil Tank Vent Tube Assembly AT MANUFACTURE						RE (-)		Category 6	
						Mos	29-Oct-2015			
						Hrs	0			
						Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30440 Rev 5		Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
	72 ENG1					Mos					
	Eff: 07-Jan-2016					Hrs					
						Enc					
30440 Rev 5		Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
	72 ENG2					Mos					
	Eff: 07-Jan-2016					Hrs					
						Enc					
30440 Rev 6		Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
	72 ENG1					Mos					
	Eff: 24-May-2019					Hrs					
						Enc					
30440 Rev 6		Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
	72 ENG2					Mos					
	Eff: 24-May-2019					Hrs					
						Enc					
30445		Electrical Wiring Harness - Replacement						RE (-)		Category 7	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 16-Sep-2011 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30445		Electrical Wiring Harness - Replacement						RE (-)		Category 7	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 16-Sep-2011 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30446		Low Pressure Compressor Shaft Balancing Assembly - Replacement						RE (-)		Category 7	
	72 ENG1					Mos					
						Hrs					
						Enc					
30446		Low Pressure Compressor Shaft Balancing Assembly - Replacement						RE (-)		Category 7	
	72 ENG2					Mos					
						Hrs					
						Enc					
30446 Rev 1		Low Pressure Compressor Shaft Balancing Assembly - Replacement						RE (-)		Category 7	
	72 ENG1					Mos					
						Hrs					
						Enc					
30446 Rev 1		Low Pressure Compressor Shaft Balancing Assembly - Replacement						RE (-)		Category 7	
	72 ENG2					Mos					
						Hrs					
						Enc					
30446 Rev 2		Low Pressure Compressor Shaft Balancing Assembly - Replacement						RE (-)		Category 7	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 11-Mar-2014 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30446 Rev 2		Low Pressure Compressor Shaft Balancing Assembly - Replacement						RE (-)		Category 7	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 11-Mar-2014 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30447	72 ENG1	Gas Generator Case - New Coating Modification						RE (-)		Category 6	
						Mos					
						Hrs					
						Enc					
30447	72 ENG2	Gas Generator Case - New Coating Modification						RE (-)		Category 6	
						Mos					
						Hrs					
						Enc					
30447 Rev 1	72 ENG1 Eff: 09-May-2012 Complied With	Gas Generator Case - New Coating Modification AT MANUFACTURE						RE (-)		Category 6	
						Mos	29-Oct-2015				
						Hrs	0				
						Enc	0				
30447 Rev 1	72 ENG2 Eff: 09-May-2012 Complied With	Gas Generator Case - New Coating Modification AT MANUFACTURE						RE (-)		Category 6	
						Mos	29-Oct-2015				
						Hrs	0				
						Enc	0				
30449	72 ENG1	HP Turbine Disk Assembly - Replacement						RE (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30449	72 ENG2	HP Turbine Disk Assembly - Replacement						RE (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30449 Rev 1	72 ENG1 Complied With	HP Turbine Disk Assembly - Replacement AT MANUFACTURE						RE (-)		Category 7	
						Mos	29-Oct-2015				
						Hrs	0				
						Enc	0				
30449 Rev 1	72 ENG2 Complied With	HP Turbine Disk Assembly - Replacement AT MANUFACTURE						RE (-)		Category 7	
						Mos	29-Oct-2015				
						Hrs	0				
						Enc	0				
30449 Rev 2	72 ENG1 Eff: 11-Sep-2015	HP Turbine Disk Assembly - Replacement						T (A/R)		Category 7	
						Mos					
						Hrs					
						Enc					
30449 Rev 2	72 ENG2 Eff: 11-Sep-2015	HP Turbine Disk Assembly - Replacement						T (A/R)		Category 7	
						Mos					
						Hrs					
						Enc					
30453	72 ENG1	No. 4 Carbon Seal - Replacement						RE (-)		Category 6, Category 7	
						Mos					
						Hrs					
						Enc					
30453	72 ENG2	No. 4 Carbon Seal - Replacement						RE (-)		Category 6, Category 7	
						Mos					
						Hrs					
						Enc					

Task No	Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30453	Rev 1	No. 4 Carbon Seal - Replacement						RE (-)		Category 6, Category 7	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 31-Jan-2014 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30453	Rev 1	No. 4 Carbon Seal - Replacement						RE (-)		Category 6, Category 7	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 31-Jan-2014 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30453	Rev 2	No. 4 Carbon Seal - Replacement						RE (-)		Category 6, Category 7	
	72 ENG1					Mos					
	Eff: 23-Dec-2015					Hrs					
						Enc					
30453	Rev 2	No. 4 Carbon Seal - Replacement						RE (-)		Category 6, Category 7	
	72 ENG2					Mos					
	Eff: 23-Dec-2015					Hrs					
						Enc					
30453	Rev 3	No. 4 Carbon Seal - Replacement						RE (-)		Category 6, Category 7	
	72 ENG1					Mos					
	Eff: 11-Aug-2017					Hrs					
						Enc					
30453	Rev 3	No. 4 Carbon Seal - Replacement						RE (-)		Category 6, Category 7	
	72 ENG2					Mos					
	Eff: 11-Aug-2017					Hrs					
						Enc					
30463		Accessory Drive Lip Seal - Replacement						RE (-)		Category 7	
	72 ENG1					Mos					
						Hrs					
						Enc					
30463		Accessory Drive Lip Seal - Replacement						RE (-)		Category 7	
	72 ENG2					Mos					
						Hrs					
						Enc					
30463	Rev 1	Accessory Drive Lip Seal - Replacement						RE (-)		Category 7	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 20-Nov-2012 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30463	Rev 1	Accessory Drive Lip Seal - Replacement						RE (-)		Category 7	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 20-Nov-2012 Complied	AT MANUFACTURE				Hrs	0				
	With					Enc	0				
30463	Rev 2	Replacement of Accessory Drive Lip Seal						RE (-)		Category 7	
	72 ENG1					Mos					
	Eff: 18-Aug-2016					Hrs					
	(AVG MAN HRS: 1)					Enc					
30463	Rev 2	Replacement of Accessory Drive Lip Seal						RE (-)		Category 7	
	72 ENG2					Mos					
	Eff: 18-Aug-2016					Hrs					
	(AVG MAN HRS: 1)					Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30465		Fuel Manifold Tubes - Replacement						RE (-)		Category 7	
	72 ENG1					Mos					
						Hrs					
						Enc					
30465		Fuel Manifold Tubes - Replacement						RE (-)		Category 7	
	72 ENG2					Mos					
						Hrs					
						Enc					
30465 Rev 1		Fuel Manifold Tubes - Replacement						RE (-)		Category 7	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 26-Aug-2014 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30465 Rev 1		Fuel Manifold Tubes - Replacement						RE (-)		Category 7	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 26-Aug-2014 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30466		Replacement/Modification of 2nd Stage Turbine Vane Assy						RE (-)		Category 7	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 19-Sep-2012 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30466		Replacement/Modification of 2nd Stage Turbine Vane Assy						RE (-)		Category 7	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 19-Sep-2012 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30466 Rev 1		Replacement/Modification of 2nd Stage Turbine Vane Assy						RE (-)		Category 7	
	72 ENG1					Mos					
	Eff: 02-Mar-2016					Hrs					
						Enc					
30466 Rev 1		Replacement/Modification of 2nd Stage Turbine Vane Assy						RE (-)		Category 7	
	72 ENG2					Mos					
	Eff: 02-Mar-2016					Hrs					
						Enc					
30466 Rev 2		Replacement/Modification of 2nd Stage Turbine Vane Assy						RE (-)		Category 7	
	72 ENG1					Mos					
	Eff: 12-Jul-2018					Hrs					
						Enc					
30466 Rev 2		Replacement/Modification of 2nd Stage Turbine Vane Assy						RE (-)		Category 7	
	72 ENG2					Mos					
	Eff: 12-Jul-2018					Hrs					
						Enc					
30470		Data Collection Unit - Replacement						RE (-)		Category 7	
	72 ENG1					Mos	29-Oct-2015				
	Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30470		Data Collection Unit - Replacement						RE (-)		Category 7	
	72 ENG2					Mos	29-Oct-2015				
	Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30470 Rev 1	Data Collection Unit - Replacement						T (A/R)		Category 7	
 72 ENG1						Mos				
Eff: 31-Aug-2015						Hrs				
						Enc				
30470 Rev 1	Data Collection Unit - Replacement						T (A/R)		Category 7	
 72 ENG2						Mos				
Eff: 31-Aug-2015						Hrs				
						Enc				
30474	Replacement of Electrical Wiring Harness						RE (-)		Category 7	
 72 ENG1						Mos	29-Oct-2015			
Eff: 30-Jul-2013 Complied	AT MANUFACTURE					Hrs	0			
With						Enc	0			
30474	Replacement of Electrical Wiring Harness						RE (-)		Category 7	
 72 ENG2						Mos	29-Oct-2015			
Eff: 30-Jul-2013 Complied	AT MANUFACTURE					Hrs	0			
With						Enc	0			
30474 Rev 1	Replacement of Electrical Wiring Harness						RE (-)		Category 7	
 72 ENG1						Mos				
Eff: 10-Nov-2015						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30474 Rev 1	Replacement of Electrical Wiring Harness						RE (-)		Category 7	
 72 ENG2						Mos				
Eff: 10-Nov-2015						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30475	Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly - Replacement						RE (-)		Category 7	
 72 ENG1						Mos				
						Hrs				
						Enc				
30475	Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly - Replacement						RE (-)		Category 7	
 72 ENG2						Mos				
						Hrs				
						Enc				
30475 Part A	Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Fuel Control Drive Gearshaft (Category 7)						RE (-)		Category 7	
 72 ENG1						Mos				
						Hrs				
						Enc				
30475 Part A	Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Fuel Control Drive Gearshaft (Category 7)						RE (-)		Category 7	
 72 ENG2						Mos				
						Hrs				
						Enc				
30475 Part B	Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Accessory Drive Gearshaft (Category 7)						RE (-)		Category 7	
 72 ENG1						Mos				
						Hrs				
						Enc				

OK-ECR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-ECR,SN 560-6198

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30475 Part B		Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Accessory Drive Gearshaft (Category 7)						RE (-)		Category 7	
	 72 ENG2					Mos					
						Hrs					
						Enc					
30475 Rev 1		Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly - Replacement						RE (-)		Category 7	
	 72 ENG1					Mos					
						Hrs					
						Enc					
30475 Rev 1		Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly - Replacement						RE (-)		Category 7	
	 72 ENG2					Mos					
						Hrs					
						Enc					
30475 Rev 1 Part A		Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Fuel Control Drive Gearshaft (Category 7)						RE (-)		Category 7	
	 72 ENG1					Mos					
						Hrs					
						Enc					
30475 Rev 1 Part A		Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Fuel Control Drive Gearshaft (Category 7)						RE (-)		Category 7	
	 72 ENG2					Mos					
						Hrs					
						Enc					
30475 Rev 1 Part B		Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Accessory Drive Gearshaft (Category 7)						RE (-)		Category 7	
	 72 ENG1					Mos					
						Hrs					
						Enc					
30475 Rev 1 Part B		Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Accessory Drive Gearshaft (Category 7)						RE (-)		Category 7	
	 72 ENG2					Mos					
						Hrs					
						Enc					
30475 Rev 2		Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly - Replacement						RE (-)		Category 7	
	 72 ENG1					Mos	29-Oct-2015				
	Eff: 18-Dec-2013 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30475 Rev 2		Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly - Replacement						RE (-)		Category 7	
	 72 ENG2					Mos	29-Oct-2015				
	Eff: 18-Dec-2013 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30475 Rev 2 Part A		Replacement of Fuel Control Drive Spur Gearshaft Assembly						RE (-)		Category 7	
	 72 ENG1					Mos					
						Hrs					
						Enc					
30475 Rev 2 Part A		Replacement of Fuel Control Drive Spur Gearshaft Assembly						RE (-)		Category 7	
	 72 ENG2					Mos					
						Hrs					
						Enc					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30475 Rev 2 Part B  72 ENG1	Replacement of Accessory Drive Gearshaft Assembly						RE (-)		Category 7	
30475 Rev 2 Part B  72 ENG2	Replacement of Accessory Drive Gearshaft Assembly						RE (-)		Category 7	
30475 Rev 3  72 ENG1 Eff: 18-Aug-2016	Replacement of Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly						RE (-)		Category 7	
30475 Rev 3  72 ENG2 Eff: 18-Aug-2016	Replacement of Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly						RE (-)		Category 7	
30475 Rev 3 Part A  72 ENG1 Eff: 18-Aug-2016	Replacement of Fuel Control Drive Spur Gearshaft Assembly						RE (-)		Category 7	
30475 Rev 3 Part A  72 ENG2 Eff: 18-Aug-2016	Replacement of Fuel Control Drive Spur Gearshaft Assembly						RE (-)		Category 7	
30475 Rev 3 Part B  72 ENG1 Eff: 18-Aug-2016	Replacement of Accessory Drive Gearshaft Assembly						RE (-)		Category 7	
30475 Rev 3 Part B  72 ENG2 Eff: 18-Aug-2016	Replacement of Accessory Drive Gearshaft Assembly						RE (-)		Category 7	
30478  72 ENG1 Not Applicable	Electronic Engine Control (EEC) - Replacement/Field Modification R2 is c/w						RE (-)		Category 3	
30478  72 ENG2 Not Applicable	Electronic Engine Control (EEC) - Replacement/Field Modification R2 is c/w						RE (-)		Category 3	
30478 Rev 1  72 ENG1 Not Applicable	Electronic Engine Control (EEC) - Replacement/Field Modification R2 is c/w						RE (-)		Category 3	
30478 Rev 1  72 ENG2 Not Applicable	Electronic Engine Control (EEC) - Replacement/Field Modification R2 is c/w						RE (-)		Category 3	
30478 Rev 2  72 ENG1 Complied With	Electronic Engine Control (EEC) - Replacement/Field Modification AT MANUFACTURE						RE (-)		Category 3	

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30478 Rev 2		Electronic Engine Control (EEC) - Replacement/Field Modification									
	72 ENG2	Complied With AT MANUFACTURE					Mos	29-Oct-2015		RE (-)	Category 3
							Hrs	0			
							Enc	0			
30478 Rev 3		Electronic Engine Control (EEC) - Replacement/Field Modification									
	72 ENG1	Eff: 15-Jul-2015 Not Applicable R2 is c/w					Mos	09-Sep-2021		RE (-)	Category 3
							Hrs	2218:31			
							Enc	1,685			
30478 Rev 3		Electronic Engine Control (EEC) - Replacement/Field Modification									
	72 ENG2	Eff: 15-Jul-2015 Not Applicable R2 is c/w					Mos	09-Sep-2021		RE (-)	Category 3
							Hrs	2218:31			
							Enc	1,685			
30479		No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement									
	72 ENG1	Not Applicable R3 is c/w					Mos	09-Sep-2021		RE (-)	Category 5
							Hrs	2218:31			
							Enc	1,685			
30479		No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement									
	72 ENG2	Not Applicable R3 is c/w					Mos	09-Sep-2021		RE (-)	Category 5
							Hrs	2218:31			
							Enc	1,685			
30479 Rev 1		No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement									
	72 ENG1	Not Applicable R3 is c/w					Mos	09-Sep-2021		RE (-)	Category 5
							Hrs	2218:31			
							Enc	1,685			
30479 Rev 1		No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement									
	72 ENG2	Not Applicable R3 is c/w					Mos	09-Sep-2021		RE (-)	Category 5
							Hrs	2218:31			
							Enc	1,685			
30479 Rev 2		No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement									
	72 ENG1	Not Applicable R3 is c/w					Mos	09-Sep-2021		RE (-)	Category 5
							Hrs	2218:31			
							Enc	1,685			
30479 Rev 2		No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement									
	72 ENG2	Not Applicable R3 is c/w					Mos	09-Sep-2021		RE (-)	Category 5
							Hrs	2218:31			
							Enc	1,685			
30479 Rev 3		No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement									
	72 ENG1	Eff: 22-Jun-2015 Complied With AT MANUFACTURE					Mos	29-Oct-2015		RE (-)	Category 5
							Hrs	0			
							Enc	0			
30479 Rev 3		No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement									
	72 ENG2	Eff: 22-Jun-2015 Complied With AT MANUFACTURE					Mos	29-Oct-2015		RE (-)	Category 5
							Hrs	0			
							Enc	0			
30479 Rev 4		No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement									
	72 ENG1	Eff: 04-Jan-2016 Not Applicable as per S/N					Mos	09-Sep-2021		RE (-)	Category 5
							Hrs	2218:31			
							Enc	1,685			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30479 Rev 4	No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement						RE (-)		Category 5	
 72 ENG2						Mos	09-Sep-2021			
Eff: 04-Jan-2016 Not Applicable	as per S/N					Hrs	2218:31			
						Enc	1,685			
30479 Rev 5	No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement						RE (-)		Category 5	
 72 ENG1						Mos	09-Sep-2021			
Eff: 21-Jan-2016 Not Applicable	as per S/N					Hrs	2218:31			
						Enc	1,685			
30479 Rev 5	No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement						RE (-)		Category 5	
 72 ENG2						Mos	09-Sep-2021			
Eff: 21-Jan-2016 Not Applicable	as per S/N					Hrs	2218:31			
						Enc	1,685			
30479 Rev 6	No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement						RE (-)		Category 3	
 72 ENG1						Mos	09-Sep-2021			
Eff: 20-May-2016 Not Applicable	as per S/N					Hrs	2218:31			
						Enc	1,685			
30479 Rev 6	No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement						RE (-)		Category 3	
 72 ENG2						Mos	09-Sep-2021			
Eff: 20-May-2016 Not Applicable	as per S/N					Hrs	2218:31			
						Enc	1,685			
30480	Rear Outer By-Pass Duct Silver Plated Nuts - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	29-Oct-2015			
Eff: 05-Dec-2013 Complied With	AT MANUFACTURE					Hrs	0			
						Enc	0			
30480	Rear Outer By-Pass Duct Silver Plated Nuts - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	29-Oct-2015			
Eff: 05-Dec-2013 Complied With	AT MANUFACTURE					Hrs	0			
						Enc	0			
30481	Fuel Shut-Off Cable - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	29-Oct-2015			
Eff: 06-Dec-2013 Complied With	AT MANUFACTURE					Hrs	0			
						Enc	0			
30481	Fuel Shut-Off Cable - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	29-Oct-2015			
Eff: 06-Dec-2013 Complied With	AT MANUFACTURE					Hrs	0			
						Enc	0			
30482	Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection						RE (-)		Category 10	
 72 ENG1						Mos				
						Hrs				
						Enc				
30482	Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection						RE (-)		Category 10	
 72 ENG2						Mos				
						Hrs				
						Enc				

OK-ECR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-ECR,SN 560-6198

Task No SEQ PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
30482 Rev 1  72 ENG1	Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection						RE (-)		Category 10	
										Mos
										Hrs
										Enc
30482 Rev 1  72 ENG2	Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection						RE (-)		Category 10	
										Mos
										Hrs
										Enc
30482 Rev 2  72 ENG1	Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection						RE (-)		Category 10	
										Mos
										Hrs
										Enc
30482 Rev 2  72 ENG2	Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection						RE (-)		Category 10	
										Mos
										Hrs
										Enc
30482 Rev 3  72 ENG1 Eff: 22-Oct-2014	Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection						T (A/R)		Category 10	
										Mos
										Hrs
										Enc
30482 Rev 3  72 ENG2 Eff: 22-Oct-2014	Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection						T (A/R)		Category 10	
										Mos
										Hrs
										Enc
30483  72 ENG1	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 10	
										Mos
										Hrs
										Enc
30483  72 ENG2	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 10	
										Mos
										Hrs
										Enc
30483 Rev 1  72 ENG1	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 10	
										Mos
										Hrs
										Enc
30483 Rev 1  72 ENG2	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 10	
										Mos
										Hrs
										Enc
30483 Rev 2  72 ENG1	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 10	
										Mos
										Hrs
										Enc
30483 Rev 2  72 ENG2	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 10	
										Mos
										Hrs
										Enc

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30483 Rev 3	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 10	
 72 ENG1						Mos	29-Oct-2015			
Eff: 22-Oct-2014 Complied With	AT MANUFACTURE					Hrs	0			
						Enc	0			
30483 Rev 3	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 10	
 72 ENG2						Mos	29-Oct-2015			
Eff: 22-Oct-2014 Complied With	AT MANUFACTURE					Hrs	0			
						Enc	0			
30485	Rear Outer By-Pass Duct Hardware - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	29-Oct-2015			
Eff: 19-Nov-2013 Complied With	AT MANUFACTURE					Hrs	0			
						Enc	0			
30485	Rear Outer By-Pass Duct Hardware - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	29-Oct-2015			
Eff: 19-Nov-2013 Complied With	AT MANUFACTURE					Hrs	0			
						Enc	0			
30485 Rev 1	Rear Outer By-Pass Duct Hardware - Replacement						RE (-)		Category 7	
 72 ENG1						Mos				
Eff: 31-May-2016						Hrs				
(AVG MAN HRS: 1)						Enc				
30485 Rev 1	Rear Outer By-Pass Duct Hardware - Replacement						RE (-)		Category 7	
 72 ENG2						Mos				
Eff: 31-May-2016						Hrs				
(AVG MAN HRS: 1)						Enc				
30485 Rev 2	Rear Outer By-Pass Duct Hardware - Replacement						RE (-)		Category 7	
 72 ENG1						Mos				
Eff: 14-Aug-2017						Hrs				
(AVG MAN HRS: 1)						Enc				
30485 Rev 2	Rear Outer By-Pass Duct Hardware - Replacement						RE (-)		Category 7	
 72 ENG2						Mos				
Eff: 14-Aug-2017						Hrs				
(AVG MAN HRS: 1)						Enc				
30487	Fuel Control Drive and Accessory Drive Lip Seal - Replacement						RE (-)		Category 10	
 72 ENG1						Mos				
						Hrs				
						Enc				
30487	Fuel Control Drive and Accessory Drive Lip Seal - Replacement						RE (-)		Category 10	
 72 ENG2						Mos				
						Hrs				
						Enc				
30487 Rev 1	Fuel Control Drive and Accessory Drive Lip Seal - Replacement						RE (-)		Category 10	
 72 ENG1						Mos				
						Hrs				
						Enc				
30487 Rev 1	Fuel Control Drive and Accessory Drive Lip Seal - Replacement						RE (-)		Category 10	
 72 ENG2						Mos				
						Hrs				
						Enc				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30487 Rev 2  72 ENG1	Fuel Control Drive and Accessory Drive Lip Seal - Replacement						RE (-)		Category 10	
30487 Rev 2  72 ENG2	Fuel Control Drive and Accessory Drive Lip Seal - Replacement						RE (-)		Category 10	
30487 Rev 3  72 ENG1 Eff: 09-Oct-2014	Fuel Control Drive and Accessory Drive Lip Seal - Replacement						T (A/R)		Category 10	
30487 Rev 3  72 ENG2 Eff: 09-Oct-2014	Fuel Control Drive and Accessory Drive Lip Seal - Replacement						T (A/R)		Category 10	
30491  72 ENG1	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 7	
30491  72 ENG2	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 7	
30491 Rev 1  72 ENG1 Complied With	Combustion Chamber Liner Assembly - Replacement/Modification AT MANUFACTURE						RE (-)		Category 7	
							29-Oct-2015			
							0			
							0			
30491 Rev 1  72 ENG2 Complied With	Combustion Chamber Liner Assembly - Replacement/Modification AT MANUFACTURE						RE (-)		Category 7	
							29-Oct-2015			
							0			
							0			
30491 Rev 2  72 ENG1 Eff: 27-Jul-2015	Combustion Chamber Liner Assembly - Replacement/Modification						T (A/R)		Category 7	
30491 Rev 2  72 ENG2 Eff: 27-Jul-2015	Combustion Chamber Liner Assembly - Replacement/Modification						T (A/R)		Category 7	
30492  72 ENG1	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
30492  72 ENG2	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
30492 Rev 1  72 ENG1	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30492 Rev 1		Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
	72 ENG2										
30492 Rev 2		Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
	72 ENG1										
30492 Rev 2		Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
	72 ENG2										
30492 Rev 3		Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
	72 ENG1										
	Eff: 27-Nov-2014 Complied	AT MANUFACTURE					29-Oct-2015				
	With							0			
								0			
30492 Rev 3		Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
	72 ENG2										
	Eff: 27-Nov-2014 Complied	AT MANUFACTURE					29-Oct-2015				
	With							0			
								0			
30492 Rev 4		Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
	72 ENG1										
	Eff: 10-Jan-2017										
	(AVG MAN HRS: 1.5)										
30492 Rev 4		Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
	72 ENG2										
	Eff: 10-Jan-2017										
	(AVG MAN HRS: 1.5)										
30495		Accessory Gearbox Cover Bolt Torquing Procedure - Modification						RE (-)		Category 10	
	72 ENG1										
	Eff: 15-Sep-2014 Complied	AT MANUFACTURE					29-Oct-2015				
	With							0			
								0			
30495		Accessory Gearbox Cover Bolt Torquing Procedure - Modification						RE (-)		Category 10	
	72 ENG2										
	Eff: 15-Sep-2014 Complied	AT MANUFACTURE					29-Oct-2015				
	With							0			
								0			
30495 Rev 1		Accessory Gearbox Cover Bolt Torquing Procedure - Modification						RE (-)		Category 10	
	72 ENG1										
	Eff: 13-Oct-2016										
	(AVG MAN HRS: 1.5)										
30495 Rev 1		Accessory Gearbox Cover Bolt Torquing Procedure - Modification						RE (-)		Category 10	
	72 ENG2										
	Eff: 13-Oct-2016										
	(AVG MAN HRS: 1.5)										
30496		Replacement/Modification of Second Stage Turbine Vane						RE (-)		Category 6	
	72 ENG1										
	Eff: 12-Aug-2014 Complied	AT MANUFACTURE					29-Oct-2015				
	With							0			
								0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30496		Replacement/Modification of Second Stage Turbine Vane						RE (-)		Category 6	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 12-Aug-2014 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30496 Rev 1		Replacement/Modification of Second Stage Turbine Vane						RE (-)		Category 6	
	72 ENG1					Mos					
	Eff: 01-Oct-2018					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30496 Rev 1		Replacement/Modification of Second Stage Turbine Vane						RE (-)		Category 6	
	72 ENG2					Mos					
	Eff: 01-Oct-2018					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30498		Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 7	
	72 ENG1					Mos	29-Oct-2015				
	Eff: 12-Sep-2014 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30498		Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 7	
	72 ENG2					Mos	29-Oct-2015				
	Eff: 12-Sep-2014 Complied With	AT MANUFACTURE				Hrs	0				
						Enc	0				
30498 Rev 1		Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 7	
	72 ENG1					Mos					
	Eff: 16-Nov-2016					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30498 Rev 1		Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 7	
	72 ENG2					Mos					
	Eff: 16-Nov-2016					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30498 Rev 2		Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
	72 ENG1					Mos					
	Eff: 10-Aug-2017					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30498 Rev 2		Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
	72 ENG2					Mos					
	Eff: 10-Aug-2017					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30498 Rev 3		Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
	72 ENG1					Mos					
	Eff: 20-Sep-2017					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30498 Rev 3		Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
	72 ENG2					Mos					
	Eff: 20-Sep-2017					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30502		Fuel Control Drive and Accessory Drive Plain Seal - Replacement						RE (-)		Category 7	
	72 ENG1					Mos					
						Hrs					
						Enc					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30502	Fuel Control Drive and Accessory Drive Plain Seal - Replacement						RE (-)		Category 7	
 72 ENG2										
30502 Rev 1	Fuel Control Drive and Accessory Drive Plain Seal - Replacement						RE (-)		Category 7	
 72 ENG1										
Complied With	AT MANUFACTURE									
30502 Rev 1	Fuel Control Drive and Accessory Drive Plain Seal - Replacement						RE (-)		Category 7	
 72 ENG2										
Complied With	AT MANUFACTURE									
30502 Rev 2	Fuel Control Drive and Accessory Drive Plain Seal - Replacement						T (-)		Category 7	
 72 ENG1										
Eff: 02-Oct-2015										
30502 Rev 2	Fuel Control Drive and Accessory Drive Plain Seal - Replacement						T (-)		Category 7	
 72 ENG2										
Eff: 02-Oct-2015										
30502 Rev 2 Part A	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Fuel Control Gearshaft Seal						RE (-)		Category 7	
 72 ENG1										
30502 Rev 2 Part A	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Fuel Control Gearshaft Seal						RE (-)		Category 7	
 72 ENG2										
30502 Rev 2 Part B	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Accessory Gearshaft Seal						RE (-)		Category 7	
 72 ENG1										
30502 Rev 2 Part B	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Accessory Gearshaft Seal						RE (-)		Category 7	
 72 ENG2										
30502 Rev 3	Fuel Control Drive and Accessory Drive Plain Seal - Replacement						RE (-)		Category 7	
 72 ENG1										
Eff: 04-Jan-2016										
(AVG MAN HRS: 1)										
30502 Rev 3	Fuel Control Drive and Accessory Drive Plain Seal - Replacement						RE (-)		Category 7	
 72 ENG2										
Eff: 04-Jan-2016										
(AVG MAN HRS: 1)										
30502 Rev 3 Part A	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Fuel Control Gearshaft Seal						RE (-)		Category 7	
 72 ENG1										
Eff: 04-Jan-2016										
30502 Rev 3 Part A	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Fuel Control Gearshaft Seal						RE (-)		Category 7	
 72 ENG2										
Eff: 04-Jan-2016										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30502 Rev 3 Part B	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Accessory Gearshaft Seal						RE (-)		Category 7	
 72 ENG1						Mos				
Eff: 04-Jan-2016						Hrs				
						Enc				
30502 Rev 3 Part B	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Accessory Gearshaft Seal						RE (-)		Category 7	
 72 ENG2						Mos				
Eff: 04-Jan-2016						Hrs				
						Enc				
30502 Rev 4	Fuel Control Drive and Accessory Drive Plain Seal - Replacement						RE (-)		Category 7	
 72 ENG1						Mos				
Eff: 20-Oct-2016						Hrs				
(AVG MAN HRS: 1)						Enc				
30502 Rev 4	Fuel Control Drive and Accessory Drive Plain Seal - Replacement						RE (-)		Category 7	
 72 ENG2						Mos				
Eff: 20-Oct-2016						Hrs				
(AVG MAN HRS: 1)						Enc				
30502 Rev 4 Part A	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Fuel Control Gearshaft Seal						RE (-)		Category 7	
 72 ENG1						Mos				
Eff: 20-Oct-2016						Hrs				
(AVG MAN HRS: 1)						Enc				
30502 Rev 4 Part A	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Fuel Control Gearshaft Seal						RE (-)		Category 7	
 72 ENG2						Mos				
Eff: 20-Oct-2016						Hrs				
(AVG MAN HRS: 1)						Enc				
30502 Rev 4 Part B	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Accessory Gearshaft Seal						RE (-)		Category 7	
 72 ENG1						Mos				
Eff: 20-Oct-2016						Hrs				
(AVG MAN HRS: 1)						Enc				
30502 Rev 4 Part B	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Accessory Gearshaft Seal						RE (-)		Category 7	
 72 ENG2						Mos				
Eff: 20-Oct-2016						Hrs				
(AVG MAN HRS: 1)						Enc				
30504	Replacement of Fuel/Oil Heat Exchanger						RE (-)		Category 7	
 72 ENG1						Mos	29-Oct-2015			
Complied With	AT MANUFACTURE					Hrs	0			
						Enc	0			
30504	Replacement of Fuel/Oil Heat Exchanger						RE (-)		Category 7	
 72 ENG2						Mos	29-Oct-2015			
Complied With	AT MANUFACTURE					Hrs	0			
						Enc	0			
30504 Rev 1	Replacement of Fuel/Oil Heat Exchanger						T (-)		Category 7	
 72 ENG1						Mos				
Eff: 25-Sep-2015						Hrs				
						Enc				
30504 Rev 1	Replacement of Fuel/Oil Heat Exchanger						T (-)		Category 7	
 72 ENG2						Mos				
Eff: 25-Sep-2015						Hrs				
						Enc				
30505	Replacement Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
 72 ENG1						Mos	29-Oct-2015			
Complied With	AT MANUFACTURER					Hrs	0			
						Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30505		Replacement Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
	72 ENG2	Complied With AT MANUFACTURER				Mos	29-Oct-2015				
						Hrs	0				
						Enc	0				
30505 Rev 1		Replacement Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
	72 ENG1	Not Applicable R2 is c/w				Mos	09-Sep-2021				
						Hrs	2218:31				
						Enc	1,685				
30505 Rev 1		Replacement Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
	72 ENG2	Not Applicable R2 is c/w				Mos	09-Sep-2021				
						Hrs	2218:31				
						Enc	1,685				
30505 Rev 2		Replacement Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
	72 ENG1	Eff: 21-May-2015 Complied With AT MANUFACTURE				Mos	29-Oct-2015				
						Hrs	0				
						Enc	0				
30505 Rev 2		Replacement Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
	72 ENG2	Eff: 21-May-2015 Complied With AT MANUFACTURE				Mos	29-Oct-2015				
						Hrs	0				
						Enc	0				
30505 Rev 3		Replacement of Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
	72 ENG1	Eff: 16-Jul-2020 Not Applicable (AVG MAN HRS: 1.5) as per S/N				Mos	09-Sep-2021				
						Hrs	2218:31				
						Enc	1,685				
30505 Rev 3		Replacement of Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
	72 ENG2	Eff: 16-Jul-2020 Not Applicable (AVG MAN HRS: 1.5) as per S/N				Mos	09-Sep-2021				
						Hrs	2218:31				
						Enc	1,685				
30505 Rev 4		Replacement of Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
	72 ENG1	Eff: 16-Nov-2022 Not Applicable (AVG MAN HRS: 1.5) as per engine S/N				Mos	04-Jan-2023				
						Hrs	2865:44				
						Enc	2,199				
30505 Rev 4		Replacement of Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
	72 ENG2	Eff: 16-Nov-2022 Not Applicable (AVG MAN HRS: 1.5) as per engine S/N				Mos	04-Jan-2023				
						Hrs	2865:44				
						Enc	2,199				
30506		Fuel Manifold Adapters - Replacement						RE (-)		Category 7	
	72 ENG1	Complied With AT MANUFACTURE				Mos	29-Oct-2015				
						Hrs	0				
						Enc	0				
30506		Fuel Manifold Adapters - Replacement						RE (-)		Category 7	
	72 ENG2	Complied With AT MANUFACTURE				Mos	29-Oct-2015				
						Hrs	0				
						Enc	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30506 Rev 1	72 ENG1	Fuel Manifold Adapters - Replacement						RE (-)		Category 7	
						Mos					
						Hrs					
30506 Rev 1	72 ENG2	Fuel Manifold Adapters - Replacement						RE (-)		Category 7	
						Mos					
						Hrs					
30506 Rev 2	72 ENG1 Eff: 11-Sep-2015	Fuel Manifold Adapters - Replacement						T (A/R)		Category 7	
						Mos					
						Hrs					
30506 Rev 2	72 ENG2 Eff: 11-Sep-2015	Fuel Manifold Adapters - Replacement						T (A/R)		Category 7	
						Mos					
						Hrs					
30508	72 ENG1	Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
						Mos					
						Hrs					
30508	72 ENG2	Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
						Mos					
						Hrs					
30508 Rev 1	72 ENG1	Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
						Mos					
						Hrs					
30508 Rev 1	72 ENG2	Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
						Mos					
						Hrs					
30508 Rev 2	72 ENG1 Eff: 14-May-2015 Complied With	Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
						Mos	29-Oct-2015				
						Hrs	0				
30508 Rev 2	72 ENG2 Eff: 14-May-2015 Complied With	Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
						Mos	29-Oct-2015				
						Hrs	0				
30508 Rev 3	72 ENG1 Eff: 06-Dec-2018 (AVG MAN HRS: 5)	Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
						Mos					
						Hrs					
30508 Rev 3	72 ENG2 Eff: 06-Dec-2018 (AVG MAN HRS: 5)	Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
						Mos					
						Hrs					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30508 Rev 4		Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
	72 ENG1										
	Eff: 13-Apr-2020										
	(AVG MAN HRS: 5)										
30508 Rev 4		Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
	72 ENG2										
	Eff: 13-Apr-2020										
	(AVG MAN HRS: 5)										
30510		Primary and Secondary Fuel Tube Support Bracket - Replacement						RE (-)		Category 7	
	72 ENG1										
	Eff: 29-Jan-2015 Complied	AT MANUFACTURE					29-Oct-2015				
	With							0			
								0			
30510		Primary and Secondary Fuel Tube Support Bracket - Replacement						RE (-)		Category 7	
	72 ENG2										
	Eff: 29-Jan-2015 Complied	AT MANUFACTURE					29-Oct-2015				
	With							0			
								0			
30511		AGB Cover Bolts or Nuts - Re-Torquing						T (-)		Category 6	
	72 ENG1										
	Eff: 31-Jul-2015										
30511		AGB Cover Bolts or Nuts - Re-Torquing						T (-)		Category 6	
	72 ENG2										
	Eff: 31-Jul-2015										
30511 Rev 1		Re-Torquing of AGB Cover Bolts or Nuts						RE (-)		Category 6	
	72 ENG1										
	Eff: 14-Jun-2016										
	(AVG MAN HRS: 1.5)										
30511 Rev 1		Re-Torquing of AGB Cover Bolts or Nuts						RE (-)		Category 6	
	72 ENG2										
	Eff: 14-Jun-2016										
	(AVG MAN HRS: 1.5)										
30511 Rev 2		Re-Torquing of AGB Cover Bolts or Nuts						T (A/R)		Category 6	
	72 ENG1										
	Eff: 02-Mar-2021										
	(AVG MAN HRS: 1.5)										
30511 Rev 2		Re-Torquing of AGB Cover Bolts or Nuts						T (A/R)		Category 6	
	72 ENG2										
	Eff: 02-Mar-2021										
	(AVG MAN HRS: 1.5)										
30516		HP Turbine Seal Rings - Replacement						RE (-)		Category 7	
	72 ENG1										
30516		HP Turbine Seal Rings - Replacement						RE (-)		Category 7	
	72 ENG2										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30516 Rev 1  72 ENG1	HP Turbine Seal Rings - Replacement						RE (-)		Category 7	
					Mos					
					Hrs					
					Enc					
30516 Rev 1  72 ENG2	HP Turbine Seal Rings - Replacement						RE (-)		Category 7	
					Mos					
					Hrs					
					Enc					
30516 Rev 2  72 ENG1 Eff: 22-Jun-2015 Complied AT MANUFACTURE With	HP Turbine Seal Rings - Replacement						RE (-)		Category 7	
					Mos	29-Oct-2015				
					Hrs	0				
					Enc	0				
30516 Rev 2  72 ENG2 Eff: 22-Jun-2015 Complied AT MANUFACTURE With	HP Turbine Seal Rings - Replacement						RE (-)		Category 7	
					Mos	29-Oct-2015				
					Hrs	0				
					Enc	0				
30517  72 ENG1 Eff: 09-Apr-2015 Complied AT MANUFACTURE With	Igniter Flange Gaskets - Deletion						RE (-)		Category 6	
					Mos	29-Oct-2015				
					Hrs	0				
					Enc	0				
30517  72 ENG2 Eff: 09-Apr-2015 Complied AT MANUFACTURE With	Igniter Flange Gaskets - Deletion						RE (-)		Category 6	
					Mos	29-Oct-2015				
					Hrs	0				
					Enc	0				
30517 Rev 1  72 ENG1 Eff: 05-Jan-2016 (AVG MAN HRS: 1.5)	Igniter Flange Gaskets - Deletion						RE (-)		Category 6	
					Mos					
					Hrs					
					Enc					
30517 Rev 1  72 ENG2 Eff: 05-Jan-2016 (AVG MAN HRS: 1.5)	Igniter Flange Gaskets - Deletion						RE (-)		Category 6	
					Mos					
					Hrs					
					Enc					
30518  72 ENG1 Eff: 13-Oct-2017	Turbine Exhaust Case End Cone - Saleability Change						T (A/R)		Category 9	
					Mos					
					Hrs					
					Enc					
30518  72 ENG2 Eff: 13-Oct-2017	Turbine Exhaust Case End Cone - Saleability Change						T (A/R)		Category 9	
					Mos					
					Hrs					
					Enc					
30521  72 ENG1 Eff: 20-Nov-2015 (AVG MAN HRS: 1.5)	Replacement of Combustion Chamber Liner						T (-)		Category 7	
					Mos					
					Hrs					
					Enc					
30521  72 ENG2 Eff: 20-Nov-2015 (AVG MAN HRS: 1.5)	Replacement of Combustion Chamber Liner						T (-)		Category 7	
					Mos					
					Hrs					
					Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30521 Rev 1		Replacement of Combustion Chamber Liner						T (A/R)		Category 7	
	72 ENG1										
	Eff: 18-Dec-2015										
	(AVG MAN HRS: 1.5)										
30521 Rev 1		Replacement of Combustion Chamber Liner						T (A/R)		Category 7	
	72 ENG2										
	Eff: 18-Dec-2015										
	(AVG MAN HRS: 1.5)										
30523		Accessory Gearbox Cover Gasket - Replacement						T (-)		Category 7	
	72 ENG1										
	Eff: 07-Aug-2015										
30523		Accessory Gearbox Cover Gasket - Replacement						T (-)		Category 7	
	72 ENG2										
	Eff: 07-Aug-2015										
30523 Rev 1		Accessory Gearbox Cover Gasket - Replacement						T (A/R)		Category 7	
	72 ENG1										
	Eff: 30-May-2016										
	(AVG MAN HRS: 1.5)										
30523 Rev 1		Accessory Gearbox Cover Gasket - Replacement						T (A/R)		Category 7	
	72 ENG2										
	Eff: 30-May-2016										
	(AVG MAN HRS: 1.5)										
30526		Modification of Intermediate Case Assembly						T (-)		Category 6	
	72 ENG1										
	Eff: 10-Aug-2016										
	Note: NOTE: This service bulletin supersedes P&WC SB30429 at overhaul or heavy maintenance where sufficient access to the intermediate case is available.										
30526		Modification of Intermediate Case Assembly						T (-)		Category 6	
	72 ENG2										
	Eff: 10-Aug-2016										
	Note: NOTE: This service bulletin supersedes P&WC SB30429 at overhaul or heavy maintenance where sufficient access to the intermediate case is available.										
30526 Rev 1		Modification of Intermediate Case Assembly						T (A/R)		Category 6	
	72 ENG1										
	Eff: 21-Dec-2021										
	(AVG MAN HRS: 1)										
	Note: CONCURRENT REQUIREMENTS: Operators must incorporate SB 30413 prior to, or in conjunction with this service bulletin.										
30526 Rev 1		Modification of Intermediate Case Assembly						T (A/R)		Category 6	
	72 ENG2										
	Eff: 21-Dec-2021										
	(AVG MAN HRS: 1)										
	Note: CONCURRENT REQUIREMENTS: Operators must incorporate SB 30413 prior to, or in conjunction with this service bulletin.										
30527		Replacement of No.4 Roller Bearing						RE (-)		Category 9	
	72 ENG1										
	Eff: 01-Dec-2015										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30527		Replacement of No.4 Roller Bearing						RE (-)		Category 9	
	72 ENG2										
	Eff: 01-Dec-2015										
30535		Replacement of Engine Shipping Container						T (-)		Category 7	
	72 ENG1										
	Eff: 24-Aug-2017										
	(AVG MAN HRS: 1.5)										
30535		Replacement of Engine Shipping Container						T (-)		Category 7	
	72 ENG2										
	Eff: 24-Aug-2017										
	(AVG MAN HRS: 1.5)										
30535 Rev 1		Replacement of Engine Shipping Container						T (-)		Category 7	
	72 ENG1										
	Eff: 29-Sep-2017										
	(AVG MAN HRS: 1.5)										
30535 Rev 1		Replacement of Engine Shipping Container						T (-)		Category 7	
	72 ENG2										
	Eff: 29-Sep-2017										
	(AVG MAN HRS: 1.5)										
30535 Rev 2		Replacement of Engine Shipping Container						T (A/R)		Category 7	
	72 ENG1										
	Eff: 15-Sep-2023										
	(AVG MAN HRS: 1.5)										
30535 Rev 2		Replacement of Engine Shipping Container						T (A/R)		Category 7	
	72 ENG2										
	Eff: 15-Sep-2023										
	(AVG MAN HRS: 1.5)										
30540		Replacement of High Pressure Turbine Air Seal (CONTROLLED SERVICE USE NO. 0004160)						RE (-)			
	72 ENG1										
	Eff: 26-Feb-2018 Not Applicable	Different SN of Engine						14-Sep-2021			
	(AVG MAN HRS: 1.5)										
30540		Replacement of High Pressure Turbine Air Seal (CONTROLLED SERVICE USE NO. 0004160)						RE (-)			
	72 ENG2										
	Eff: 26-Feb-2018 Not Applicable	Different SN of Engine						14-Sep-2021			
	(AVG MAN HRS: 1.5)										
30540 Rev 1		Replacement of High Pressure Turbine Air Seal						T (-)		Category 7	
	72 ENG1										
	Eff: 12-Nov-2020										
	(AVG MAN HRS: 1.5)										
30540 Rev 1		Replacement of High Pressure Turbine Air Seal						T (-)		Category 7	
	72 ENG2										
	Eff: 12-Nov-2020										
	(AVG MAN HRS: 1.5)										
30540 Rev 2		Replacement of High Pressure Turbine Air Seal						T (-)		Category 7	
	72 ENG1										
	Eff: 26-Oct-2021										
	(AVG MAN HRS: 1.5)										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30540 Rev 2	Replacement of High Pressure Turbine Air Seal						T (-)		Category 7	
 72 ENG2										
Eff: 26-Oct-2021										
(AVG MAN HRS: 1.5)										
30540 Rev 3	Replacement of High Pressure Turbine Air Seal						T (A/R)		Category 7	
 72 ENG1										
Eff: 25-Jul-2024										
(AVG MAN HRS: 1.5)										
30540 Rev 3	Replacement of High Pressure Turbine Air Seal						T (A/R)		Category 7	
 72 ENG2										
Eff: 25-Jul-2024										
(AVG MAN HRS: 1.5)										
30541	Replacement of Fuel Control Drive and Accessory Drive Plain Seal						RE (-)		Category 6, Category 7	
 72 ENG1										
Eff: 07-Mar-2018										
(AVG MAN HRS: 1.5)										
30541	Replacement of Fuel Control Drive and Accessory Drive Plain Seal						RE (-)		Category 6, Category 7	
 72 ENG2										
Eff: 07-Mar-2018										
(AVG MAN HRS: 1.5)										
30541 Part A	Replacement of Fuel Control Gearshaft Seal						T (-)		Category 6, Category 7	
 72 ENG1										
Eff: 07-Mar-2018										
30541 Part A	Replacement of Fuel Control Gearshaft Seal						T (-)		Category 6, Category 7	
 72 ENG2										
Eff: 07-Mar-2018										
30541 Part B	Replacement of Accessory Drive Plain Seal						T (-)		Category 6, Category 7	
 72 ENG1										
Eff: 07-Mar-2018										
30541 Part B	Replacement of Accessory Drive Plain Seal						T (-)		Category 6, Category 7	
 72 ENG2										
Eff: 07-Mar-2018										
30541 Rev 1	Replacement of Fuel Control Drive and Accessory Drive Plain Seal						RE (-)		Category 7	
 72 ENG1										
Eff: 12-Jun-2018										
(AVG MAN HRS: 1.5)										
30541 Rev 1	Replacement of Fuel Control Drive and Accessory Drive Plain Seal						RE (-)		Category 7	
 72 ENG2										
Eff: 12-Jun-2018										
(AVG MAN HRS: 1.5)										
30541 Rev 1 Part A	Replacement of Fuel Control Gearshaft Seal						T (A/R)		Category 7	
 72 ENG1										
Eff: 12-Jun-2018										
(AVG MAN HRS: 1.5)										
30541 Rev 1 Part A	Replacement of Fuel Control Gearshaft Seal						T (A/R)		Category 7	
 72 ENG2										
Eff: 12-Jun-2018										
(AVG MAN HRS: 1.5)										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30541 Rev 1 Part B	Replacement of Accessory Drive Plain Seal						T (A/R)		Category 7	
 72 ENG1										
Eff: 12-Jun-2018										
(AVG MAN HRS: 1.5)										
30541 Rev 1 Part B	Replacement of Accessory Drive Plain Seal						T (A/R)		Category 7	
 72 ENG2										
Eff: 12-Jun-2018										
(AVG MAN HRS: 1.5)										
30546	Replacement of HPT Air Seal						T (-)		Category 9	
 72 ENG1										
Eff: 05-Sep-2019										
(AVG MAN HRS: 1.5)										
30546	Replacement of HPT Air Seal						T (-)		Category 9	
 72 ENG2										
Eff: 05-Sep-2019										
(AVG MAN HRS: 1.5)										
30546 Rev 1	Replacement of HPT Air Seal						T (-)		Category 9	
 72 ENG1										
Eff: 06-Nov-2019										
(AVG MAN HRS: 1.5)										
30546 Rev 1	Replacement of HPT Air Seal						T (-)		Category 9	
 72 ENG2										
Eff: 06-Nov-2019										
(AVG MAN HRS: 1.5)										
30546 Rev 2	Replacement of HPT Air Seal						T (A/R)		Category 9	
 72 ENG1										
Eff: 12-Apr-2021										
(AVG MAN HRS: 1.5)										
30546 Rev 2	Replacement of HPT Air Seal						T (A/R)		Category 9	
 72 ENG2										
Eff: 12-Apr-2021										
(AVG MAN HRS: 1.5)										
30550	Replacement of No. 4 Bearing Seal Runners						RE (-)		Category 7	
 72 ENG1										
Eff: 09-May-2019										
(AVG MAN HRS: 1.5)										
30550	Replacement of No. 4 Bearing Seal Runners						RE (-)		Category 7	
 72 ENG2										
Eff: 09-May-2019										
(AVG MAN HRS: 1.5)										
30550 Part A	Replacement of No. 4 Bearing Seal Runners - Front No.4 Bearing Seal Runner						T (A/R)		Category 7	
 72 ENG1										
Eff: 09-May-2019										
(AVG MAN HRS: 1.5)										
30550 Part A	Replacement of No. 4 Bearing Seal Runners - Front No.4 Bearing Seal Runner						T (A/R)		Category 7	
 72 ENG2										
Eff: 09-May-2019										
(AVG MAN HRS: 1.5)										
30550 Part B	Replacement of No. 4 Bearing Seal Runners - Rear No.4 Bearing Seal Runner						T (A/R)		Category 7	
 72 ENG1										
Eff: 09-May-2019										
(AVG MAN HRS: 1.5)										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30550 Part B	Replacement of No. 4 Bearing Seal Runners - Rear No.4 Bearing Seal Runner						T (A/R)		Category 7	
 72 ENG2										
Eff: 09-May-2019										
(AVG MAN HRS: 1.5)										
30562	Replacement of Mixer Assembly						T (-)		Category 9	
 72 ENG1										
Eff: 18-May-2021										
(AVG MAN HRS: 1.5)										
30562	Replacement of Mixer Assembly						T (-)		Category 9	
 72 ENG2										
Eff: 18-May-2021										
(AVG MAN HRS: 1.5)										
30562 Rev 1	Replacement of Mixer Assembly						T (-)		Category 9	
 72 ENG1										
Eff: 27-May-2021										
(AVG MAN HRS: 1.5)										
30562 Rev 1	Replacement of Mixer Assembly						T (-)		Category 9	
 72 ENG2										
Eff: 27-May-2021										
(AVG MAN HRS: 1.5)										
30562 Rev 2	Replacement of Mixer Assembly						T (-)		Category 9	
 72 ENG1										
Eff: 26-Oct-2021										
(AVG MAN HRS: 1.5)										
30562 Rev 2	Replacement of Mixer Assembly						T (-)		Category 9	
 72 ENG2										
Eff: 26-Oct-2021										
(AVG MAN HRS: 1.5)										
30562 Rev 3	Replacement of Mixer Assembly						T (A/R)		Category 9	
 72 ENG1										
Eff: 04-Nov-2021										
(AVG MAN HRS: 1.5)										
30562 Rev 3	Replacement of Mixer Assembly						T (A/R)		Category 9	
 72 ENG2										
Eff: 04-Nov-2021										
(AVG MAN HRS: 1.5)										
30564	Replacement of Lockbolt Collar						T (-)		Category 9	
 72 ENG1										
Eff: 16-Sep-2022										
(AVG MAN HRS: 1.5)										
30564	Replacement of Lockbolt Collar						T (-)		Category 9	
 72 ENG2										
Eff: 16-Sep-2022										
(AVG MAN HRS: 1.5)										
30564 Rev 1	Replacement of Lockbolt Collar						T (-)		Category 9	
 72 ENG1										
Eff: 21-Dec-2022										
(AVG MAN HRS: 1.5)										
30564 Rev 1	Replacement of Lockbolt Collar						T (-)		Category 9	
 72 ENG2										
Eff: 21-Dec-2022										
(AVG MAN HRS: 1.5)										

OK-ECR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-ECR,SN 560-6198

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30564 Rev 2	Replacement/Modification of Second Stage Turbine Vane						T (-)		Category 7	
 72 ENG1						Mos				
Eff: 27-Jan-2023						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30564 Rev 2	Replacement/Modification of Second Stage Turbine Vane						T (-)		Category 7	
 72 ENG2						Mos				
Eff: 27-Jan-2023						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30564 Rev 3	Replacement/Modification of Second Stage Turbine Vane						T (A/R)		Category 7	
 72 ENG1						Mos				
Eff: 18-Sep-2023						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30564 Rev 3	Replacement/Modification of Second Stage Turbine Vane						T (A/R)		Category 7	
 72 ENG2						Mos				
Eff: 18-Sep-2023						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30568	Replacement of No. 4 Bearing Front and Rear Seal Runners						T (-)		Category 7	
 72 ENG1						Mos				
Eff: 17-Oct-2022						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30568	Replacement of No. 4 Bearing Front and Rear Seal Runners						T (-)		Category 7	
 72 ENG2						Mos				
Eff: 17-Oct-2022						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30568 Rev 1	Replacement of No. 4 Bearing Front and Rear Seal Runners						RE (-)		Category 7	
 72 ENG1						Mos				
Eff: 12-Jan-2023						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30568 Rev 1	Replacement of No. 4 Bearing Front and Rear Seal Runners						RE (-)		Category 7	
 72 ENG2						Mos				
Eff: 12-Jan-2023						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30568 Rev 1 Part A	Replacement of No. 4 Bearing Front and Rear Seal Runners - Replacement of the Front No. 4 Bearing Seal Runner						T (A/R)		Category 7	
 72 ENG1						Mos				
Eff: 12-Jan-2023						Hrs				
						Enc				
30568 Rev 1 Part A	Replacement of No. 4 Bearing Front and Rear Seal Runners - Replacement of the Front No. 4 Bearing Seal Runner						T (A/R)		Category 7	
 72 ENG2						Mos				
Eff: 12-Jan-2023						Hrs				
						Enc				
30568 Rev 1 Part B	Replacement of No. 4 Bearing Front and Rear Seal Runners - Replacement of the Rear No. 4 Bearing Seal Runner						T (A/R)		Category 7	
 72 ENG1						Mos				
Eff: 12-Jan-2023						Hrs				
						Enc				
30568 Rev 1 Part B	Replacement of No. 4 Bearing Front and Rear Seal Runners - Replacement of the Rear No. 4 Bearing Seal Runner						T (A/R)		Category 7	
 72 ENG2						Mos				
Eff: 12-Jan-2023						Hrs				
						Enc				
30569	Replacement of Intermediate Case						RE (-)		Category 7	
 72 ENG1						Mos				
						Hrs				
						Enc				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30569		Replacement of Intermediate Case						RE (-)		Category 7	
	72 ENG2										
30569 Rev 1		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG1										
	Eff: 24-Dec-2023										
30569 Rev 1		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG2										
	Eff: 24-Dec-2023										
30569 Rev 2		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG1										
	Eff: 18-Jan-2024										
30569 Rev 2		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG2										
	Eff: 18-Jan-2024										
30569 Rev 3		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG1										
	Eff: 31-Jan-2024										
30569 Rev 3		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG2										
	Eff: 31-Jan-2024										
30569 Rev 4		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG1										
	Eff: 22-Feb-2024										
30569 Rev 4		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG2										
	Eff: 22-Feb-2024										
30569 Rev 5		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG1										
	Eff: 15-Mar-2024										
30569 Rev 5		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG2										
	Eff: 15-Mar-2024										
30569 Rev 6		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG1										
	Eff: 10-Apr-2024										
30569 Rev 6		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG2										
	Eff: 10-Apr-2024										

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30569 Rev 7	Replacement of Intermediate Case						T (-)		Category 7	
 72 ENG1					Mos					
Eff: 26-Jul-2024					Hrs					
					Enc					
30569 Rev 7	Replacement of Intermediate Case						T (-)		Category 7	
 72 ENG2					Mos					
Eff: 26-Jul-2024					Hrs					
					Enc					
30569 Rev 8	Replacement of Intermediate Case						T (A/R)		Category 7	
 72 ENG1					Mos					
Eff: 20-Sep-2024					Hrs					
					Enc					
30569 Rev 8	Replacement of Intermediate Case						T (A/R)		Category 7	
 72 ENG2					Mos					
Eff: 20-Sep-2024					Hrs					
					Enc					
30572	Inspection of HP Turbine Disk						T (A/R)		Category 5	
 72 ENG1					Mos					
Eff: 31-Jul-2023					Hrs					
(AVG MAN HRS: 2)					Enc					
Note: EFFECTIVITY: Refer to Par. 1.A. of this SB for more information.										
30572	Inspection of HP Turbine Disk						T (A/R)		Category 5	
 72 ENG2					Mos					
Eff: 31-Jul-2023					Hrs					
(AVG MAN HRS: 2)					Enc					
Note: EFFECTIVITY: Refer to Par. 1.A. of this SB for more information.										
72-00-PW-057	Low Utilization Inspection						T		EMM - Requirement	
 72 ENG1					Yrs	29-Oct-2015	10		29-Oct-2025	11.6 Months
					Hrs	0				
					Enc	0				
Note: An additional 1 month or 10 flight-hours, whichever comes first, is available for scheduling purposes. Following the overhaul of a low utilization engine, the recommended initial on-wing Low Utilization Inspection (LUI) is at 10 years after engine overhaul.										
72-00-PW-057	Low Utilization Inspection						T		EMM - Requirement	
 72 ENG2					Yrs	29-Oct-2015	10		29-Oct-2025	11.6 Months
					Hrs	0				
					Enc	0				
Note: An additional 1 month or 10 flight-hours, whichever comes first, is available for scheduling purposes. Following the overhaul of a low utilization engine, the recommended initial on-wing Low Utilization Inspection (LUI) is at 10 years after engine overhaul.										
72-00-PW-059	Engine - Overhaul						RE	05-20-00, EMM - Requirement, Extended TBO		≈22-Nov-2027
 72 ENG1					Mos					
					Hrs	5,500	+50	5500	2183:53 Hrs (+50)	
					Enc					
(SOURCE: PW535B MM (P/N 3071822); PW545A MM (P/N 30J1272))										
Note: Applicable to PW545C engines which meet the following criteria:										
(a) The participation in an engine condition trend monitoring (ECTM) program, as defined in the P&WC Publication SIL GEN-055, is required from new engine delivery or from a scheduled maintenance event (HSL/Overhaul).										
(b) The rotor component life limitations, as outlined in the AIRWORTHINESS LIMITATIONS section of this manual, are not exceeded.										
Replace engine mount isolators at every second Engine Overhaul. The engine mount isolators do not have an hourly replacement requirement. They are replaced by the number of engine overhauls.										
Discard LP Compressor Shaft at scheduled overhaul if shaft has accumulated 10,000 hours or more.										

Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
72-00-PW-059		Engine - Overhaul						RE	05-20-00, EMM - Requirement, Extended TBO		≈22-Nov-2027
	72 ENG2						Mos				
							Hrs	5,500	+50	5500	2183:53 Hrs (+50)
							Enc				
	(SOURCE: PW535B MM (P/N 3071822); PW545A MM (P/N 30J1272)) Note: Applicable to PW545C engines which meet the following criteria: (a)The participation in an engine condition trend monitoring (ECTM) program, as defined in the P&WC Publication SIL GEN-055, is required from new engine delivery or from a scheduled maintenance event (HSI/Overhaul). (b) The rotor component life limitations, as outlined in the AIRWORTHINESS LIMITATIONS section of this manual, are not exceeded. Replace engine mount isolators at every second Engine Overhaul. The engine mount isolators do not have an hourly replacement requirement. They are replaced by the number of engine overhauls. Discard LP Compressor Shaft at scheduled overhaul if shaft has accumulated 10,000 hours or more.										
72-00-PW-061		Engine - Hot Section Inspection (HSI)						RE	EMM - Requirement, Extended HSI		≈31-Oct-2027
	72 ENG1						Mos	03-Oct-2022			
							Hrs	2706:58	2,750	-/+50	5456:58 2140:51 Hrs (+50)
							Enc	2,069			
	Ref:72-00-00-ic Note: Applicable to PW545C engines which meet the following criteria: (a)The participation in an engine condition trend monitoring (ECTM) program, as defined in the P&WC Publication SIL GEN-055, is required from new engine delivery or from a scheduled maintenance event (HSI/Overhaul). (b) The rotor component life limitations, as outlined in the AIRWORTHINESS LIMITATIONS section of this manual, are not exceeded.										
72-00-PW-061		Engine - Hot Section Inspection (HSI)						RE	EMM - Requirement, Extended HSI		≈31-Oct-2027
	72 ENG2						Mos	03-Oct-2022			
							Hrs	2706:58	2,750	-/+50	5456:58 2140:51 Hrs (+50)
							Enc	2,069			
	Ref:72-00-00-ic Note: Applicable to PW545C engines which meet the following criteria: (a)The participation in an engine condition trend monitoring (ECTM) program, as defined in the P&WC Publication SIL GEN-055, is required from new engine delivery or from a scheduled maintenance event (HSI/Overhaul). (b) The rotor component life limitations, as outlined in the AIRWORTHINESS LIMITATIONS section of this manual, are not exceeded.										
72-00-PW-063		Check Time Limited Dispatch Annunciations						RE	EMM - Requirement		≈18-Jan-2025
	72 ENG1						Mos	31-Oct-2024			
							Hrs	3308:54	150	-/+20	3458:54 142:47 Hrs (+20)
							Enc	2,570			
72-00-PW-063		Check Time Limited Dispatch Annunciations						RE	EMM - Requirement		≈18-Jan-2025
	72 ENG2						Mos	31-Oct-2024			
							Hrs	3308:54	150	-/+20	3458:54 142:47 Hrs (+20)
							Enc	2,570			
723004-0101		LP Compressor Shaft						RE	05-20-00, EMM - Life Limit		≈25-Feb-2034
	72 ENG1		0				Mos	29-Oct-2015			
	30J3206-01 New		0				Hrs	0 10,000		10000	6683:53 Hrs
	PKAAA606005		0				Enc	0 20,000		20,000	17,424 Enc
	(SOURCE: PW545C MM (P/N 30J2302)) Note: Discard at scheduled overhaul. If shaft has accumulated 10,000 hours or more.										
723004-0101		LP Compressor Shaft						RE	05-20-00, EMM - Life Limit		≈25-Feb-2034
	72 ENG2		0				Mos	29-Oct-2015			
	30J3206-01 New		0				Hrs	0 10,000		10000	6683:53 Hrs
	PKAAA606006		0				Enc	0 20,000		20,000	17,424 Enc
	(SOURCE: PW545C MM (P/N 30J2302)) Note: Discard at scheduled overhaul. If shaft has accumulated 10,000 hours or more.										
72-31-00-201		Engine Mount General Visual Inspection: Do a check for security and condition of the engine mount.						RE	EMM - Periodic Inspection		≈14-Dec-2025
	72 ENG1						Mos	31-Oct-2024			
							Hrs	3308:54	800	-/+25	(4108:54) 792:47 Hrs (+25)
							Enc	2,570			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
72-31-00-201	72 ENG2	Engine Mount General Visual Inspection: Do a check for security and condition of the engine mount. 72EH0800					Mos 31-Oct-2024 Hrs 3308:54 Enc 2,570	RE 800	EMM - Periodic Inspection -/ +25 (4108:54)	≈14-Dec-2025	792:47 Hrs (+25)
72-31-00-202	72 ENG1	External Engine General Visual Inspection: Do an inspection for fuel and oil leaks, corrosion, cracks and signs of damage. 72EH0000,...					Mos 31-Oct-2024 Hrs 3308:54 Enc 2,570	RE 800	EMM - Periodic Inspection -/ +25 #4108:54	≈14-Dec-2025	
72-31-00-202	72 ENG2	External Engine General Visual Inspection: Do an inspection for fuel and oil leaks, corrosion, cracks and signs of damage. 72EH0000,...					Mos 31-Oct-2024 Hrs 3308:54 Enc 2,570	RE 800	EMM - Periodic Inspection -/ +25 #4108:54	≈14-Dec-2025	
72-31-00-203	72 ENG1	Bleed Valve Seat On The Intermediate Case And Main Intermediate Case Flanges (Borescope Where Required) 72EH0800					Mos 31-Oct-2024 Hrs 3308:54 Enc 2,570	RE 800	EMM - Periodic Inspection -/ +25 (4108:54)	≈14-Dec-2025	792:47 Hrs (+25)
72-31-00-203	72 ENG2	Bleed Valve Seat On The Intermediate Case And Main Intermediate Case Flanges (Borescope Where Required) 72EH0800					Mos 31-Oct-2024 Hrs 3308:54 Enc 2,570	RE 800	EMM - Periodic Inspection -/ +25 (4108:54)	≈14-Dec-2025	792:47 Hrs (+25)
72-31-00-203	72 ENG1	Compressor Inlet General Visual Inspection: Do an inspection of the compressor inlet fan, fan exit stator vanes, abrasable fan seal for cleanliness, damage, corrosion, erosion and FOD. 72EH0800 (SOURCE: PW545C MM 30J2302) Note: For engine that operates more than 40% of the time in zones considered extreme in terms of environmental harshness per environment maps (Ref. 05-20-00, ENGINE EXTERNALS AND COMPRESSOR WASH, Fig. 1 thru 6), do a borescope/visual inspection of the bleed valve seat on the intermediate case, main intermediate case flanges. Do a magnesium corrosion treatment as necessary (Ref. 70-00-00, STANDARD PRACTICES - MAINTENANCE PROCEDURES).					Mos 31-Oct-2024 Hrs 3308:54 Enc 2,570	RE 800	EMM - Periodic Inspection -/ +25 (4108:54)	≈14-Dec-2025	792:47 Hrs (+25)
72-31-00-203	72 ENG2	Compressor Inlet General Visual Inspection: Do an inspection of the compressor inlet fan, fan exit stator vanes, abrasable fan seal for cleanliness, damage, corrosion, erosion and FOD. 72EH0800 (SOURCE: PW545C MM 30J2302) Note: For engine that operates more than 40% of the time in zones considered extreme in terms of environmental harshness per environment maps (Ref. 05-20-00, ENGINE EXTERNALS AND COMPRESSOR WASH, Fig. 1 thru 6), do a borescope/visual inspection of the bleed valve seat on the intermediate case, main intermediate case flanges. Do a magnesium corrosion treatment as necessary (Ref. 70-00-00, STANDARD PRACTICES - MAINTENANCE PROCEDURES).					Mos 31-Oct-2024 Hrs 3308:54 Enc 2,570	RE 800	EMM - Periodic Inspection -/ +25 (4108:54)	≈14-Dec-2025	792:47 Hrs (+25)
72-31-00-203	72 ENG1	Compressor Inlet General Visual Inspection: Do an inspection of the compressor inlet fan, fan exit stator vanes, abrasable fan seal for cleanliness, damage, corrosion, erosion and FOD. When outside air temperature is 5°C (41°F) or below: Examine the bottom center area of the fan case for ice. Make sure that the fan turns freely. 72EH0000					Mos Hrs Enc	RE (PreFlight)	EMM - Periodic Inspection		
72-31-00-203	72 ENG2	Compressor Inlet General Visual Inspection: Do an inspection of the compressor inlet fan, fan exit stator vanes, abrasable fan seal for cleanliness, damage, corrosion, erosion and FOD. When outside air temperature is 5°C (41°F) or below: Examine the bottom center area of the fan case for ice. Make sure that the fan turns freely. 72EH0000					Mos Hrs Enc	RE (PreFlight)	EMM - Periodic Inspection		
72-31-00-203	72 ENG1	Extreme Environment Inspection - Treat For Corrosion As Required (Magnesium Corrosion Treatment)					Mos Hrs Enc	RE (A/R)			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
72-31-00-203		Extreme Environment Inspection - Treat For Corrosion As Required (Magnesium Corrosion Treatment)						RE (A/R)			
	72 ENG2					Mos					
						Hrs					
						Enc					
72-31-00-901		Low Pressure Compressor Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE		EMM - Periodic Inspection, Extended TBO	≈22-Nov-2027
	72 ENG1					Mos					
						Hrs		5,500	+50	5500	2183:53 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)					Enc					
72-31-00-901		Low Pressure Compressor Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE		EMM - Periodic Inspection, Extended TBO	≈22-Nov-2027
	72 ENG2					Mos					
						Hrs		5,500	+50	5500	2183:53 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)					Enc					
72-32-00-201		Compressor Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE		EMM - Periodic Inspection, Extended HSI	≈31-Oct-2027
	72 ENG1					Mos	03-Oct-2022				
						Hrs	2706:58	2,750	+50	5456:58	2140:51 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)					Enc	2,069				
72-32-00-201		Compressor Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE		EMM - Periodic Inspection, Extended HSI	≈31-Oct-2027
	72 ENG2					Mos	03-Oct-2022				
						Hrs	2706:58	2,750	+50	5456:58	2140:51 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)					Enc	2,069				
72-32-00-901		High Pressure Compressor Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303. Second-stage HP Compressor Rotor: If the rotor has accumulated more than 4000 hours, replace the rotor at scheduled overhaul.						RE		EMM - Periodic Inspection, Extended TBO	≈22-Nov-2027
	72 ENG1					Mos					
						Hrs		5,500	+50	5500	2183:53 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)					Enc					
72-32-00-901		High Pressure Compressor Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303. Second-stage HP Compressor Rotor: If the rotor has accumulated more than 4000 hours, replace the rotor at scheduled overhaul.						RE		EMM - Periodic Inspection, Extended TBO	≈22-Nov-2027
	72 ENG2					Mos					
						Hrs		5,500	+50	5500	2183:53 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)					Enc					
72-40-00-201		Combustion Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE		EMM - Periodic Inspection, Extended HSI	≈31-Oct-2027
	72 ENG1					Mos	03-Oct-2022				
						Hrs	2706:58	2,750	+50	5456:58	2140:51 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)					Enc	2,069				
72-40-00-201		Combustion Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE		EMM - Periodic Inspection, Extended HSI	≈31-Oct-2027
	72 ENG2					Mos	03-Oct-2022				
						Hrs	2706:58	2,750	+50	5456:58	2140:51 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)					Enc	2,069				
72-40-00-901		Combustion Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE		EMM - Periodic Inspection, Extended TBO	≈22-Nov-2027
	72 ENG1					Mos					
						Hrs		5,500	+50	5500	2183:53 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)					Enc					

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
72-40-00-901		Combustion Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.							RE	EMM - Periodic Inspection, Extended TBO		≈22-Nov-2027
	72 ENG2					Mos						
						Hrs		5,500	+50	5500	2183:53 Hrs (+50)	
	(SOURCE: PW545C MM 30J2302)					Enc						
72-50-00-201		Turbine Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).							RE	EMM - Periodic Inspection, Extended HSI		≈31-Oct-2027
	72 ENG1					Mos	03-Oct-2022					
						Hrs	2706:58	2,750	+50	5456:58	2140:51 Hrs (+50)	
	(SOURCE: PW545C MM 30J2302)					Enc	2,069					
72-50-00-201		Turbine Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).							RE	EMM - Periodic Inspection, Extended HSI		≈31-Oct-2027
	72 ENG2					Mos	03-Oct-2022					
						Hrs	2706:58	2,750	+50	5456:58	2140:51 Hrs (+50)	
	(SOURCE: PW545C MM 30J2302)					Enc	2,069					
72-50-00-701		Performance Calibration (5-Point Run) Functional Check: Do a performance calibration check (Ref. 71-00-00, POWER PLANT - ADJUSTMENT/TEST) and compare with previous 5-point performance calibration. Alternatively, monitor the engine performance through Engine Condition Trend Monitoring (ECTM).							RE	EMM - Periodic Inspection		≈14-Dec-2025
	72 ENG1	72EH0800				Mos	31-Oct-2024					
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)	
						Enc	2,570					
72-50-00-701		Performance Calibration (5-Point Run) Functional Check: Do a performance calibration check (Ref. 71-00-00, POWER PLANT - ADJUSTMENT/TEST) and compare with previous 5-point performance calibration. Alternatively, monitor the engine performance through Engine Condition Trend Monitoring (ECTM).							RE	EMM - Periodic Inspection		≈14-Dec-2025
	72 ENG2	72EH0800				Mos	31-Oct-2024					
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)	
						Enc	2,570					
72-50-00-901		Turbine Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303. Discard the HPT nut and keywasher.							RE	EMM - Periodic Inspection, Extended TBO		≈22-Nov-2027
	72 ENG1					Mos						
						Hrs		5,500	+50	5500	2183:53 Hrs (+50)	
	(SOURCE: PW545C MM (P/N 30J2302))					Enc						
72-50-00-901		Turbine Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303. Discard the HPT nut and keywasher.							RE	EMM - Periodic Inspection, Extended TBO		≈22-Nov-2027
	72 ENG2					Mos						
						Hrs		5,500	+50	5500	2183:53 Hrs (+50)	
	(SOURCE: PW545C MM (P/N 30J2302))					Enc						
72-60-00-201		Engine Accessory General Visual Inspection: Do a check for security of installation and general condition of accessories and gearbox.							RE	EMM - Periodic Inspection		≈14-Dec-2025
	72 ENG1	72EH0800				Mos	31-Oct-2024					
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)	
						Enc	2,570					
72-60-00-201		Engine Accessory General Visual Inspection: Do a check for security of installation and general condition of accessories and gearbox.							RE	EMM - Periodic Inspection		≈14-Dec-2025
	72 ENG2	72EH0800				Mos	31-Oct-2024					
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)	
						Enc	2,570					
72-60-00-901		Accessory Gearbox (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.							RE	EMM - Periodic Inspection, Extended TBO		≈22-Nov-2027
	72 ENG1					Mos						
						Hrs		5,500	+50	5500	2183:53 Hrs (+50)	
	(SOURCE: PW545C MM 30J2302)					Enc						
72-60-00-901		Accessory Gearbox (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.							RE	EMM - Periodic Inspection, Extended TBO		≈22-Nov-2027
	72 ENG2					Mos						
						Hrs		5,500	+50	5500	2183:53 Hrs (+50)	
	(SOURCE: PW545C MM 30J2302)					Enc						

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
726060	Annular Ball Bearing						RE (O/C)			
 72 ENG1					Mos	29-Oct-2015				
Unknown					Hrs	0				
Unknown					Enc	0				
726060	Annular Ball Bearing						RE (O/C)			
 72 ENG2					Mos	29-Oct-2015				
Unknown					Hrs	0				
Unknown					Enc	0				
72-70-00-201	Bypass Ducts and Fairings General Visual Inspection: Do a check for cleanliness and FOD.Do an inspection for cracks in the outer bypass duct, rear bypass duct, struts and fairing.						RE	EMM - Periodic Inspection		≈14-Dec-2025
 72 ENG1	72EH0800				Mos	31-Oct-2024				
					Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
					Enc	2,570				
72-70-00-201	Bypass Ducts and Fairings General Visual Inspection: Do a check for cleanliness and FOD.Do an inspection for cracks in the outer bypass duct, rear bypass duct, struts and fairing.						RE	EMM - Periodic Inspection		≈14-Dec-2025
 72 ENG2	72EH0800				Mos	31-Oct-2024				
					Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
					Enc	2,570				
72-70-00-202	Bypass Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈31-Oct-2027
 72 ENG1					Mos	03-Oct-2022				
(SOURCE: PW545C MM 30J2302)					Hrs	2706:58	2,750	+50	5456:58	2140:51 Hrs (+50)
					Enc	2,069				
72-70-00-202	Bypass Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈31-Oct-2027
 72 ENG2					Mos	03-Oct-2022				
(SOURCE: PW545C MM 30J2302)					Hrs	2706:58	2,750	+50	5456:58	2140:51 Hrs (+50)
					Enc	2,069				
72-70-00-901	Bypass Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈22-Nov-2027
 72 ENG1					Mos					
(SOURCE: PW545C MM 30J2302)					Hrs		5,500	+50	5500	2183:53 Hrs (+50)
					Enc					
72-70-00-901	Bypass Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈22-Nov-2027
 72 ENG2					Mos					
(SOURCE: PW545C MM 30J2302)					Hrs		5,500	+50	5500	2183:53 Hrs (+50)
					Enc					
72EH0000	Pre-flight/Daily Engine Inspection						RE (PreFlight)			
 72 ENG1					Mos					
					Hrs					
					Enc					
72EH0000	Pre-flight/Daily Engine Inspection						RE (PreFlight)			
 72 ENG2					Mos					
					Hrs					
					Enc					
72EH0800	800 Engine Hours Periodic Inspection (For MSG-3 Scheduled Maintenance Program)						RE	EMM - Periodic Inspection		≈14-Dec-2025
 72 ENG1					Mos	31-Oct-2024				
					Hrs	3308:54	800	-/+25	4108:54	792:47 Hrs (+25)
					Enc	2,570				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
72EH0800		800 Engine Hours Periodic Inspection (For MSG-3 Scheduled Maintenance Program)						RE	EMM - Periodic Inspection		≈14-Dec-2025
	72 ENG2					Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	4108:54	792:47 Hrs (+25)
						Enc	2,570				
A30452		Oil System - Special Inspection of MOP						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
A30452		Oil System - Special Inspection of MOP						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
A30452 Rev 1		Oil System - Special Inspection of MOP						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
A30452 Rev 1		Oil System - Special Inspection of MOP						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
A30452 Rev 2		Oil System - Special Inspection of MOP						T (A/R)		Category 10	
	72 ENG1 Eff: 31-Jul-2015					Mos					
						Hrs					
						Enc					
A30452 Rev 2		Oil System - Special Inspection of MOP						T (A/R)		Category 10	
	72 ENG2 Eff: 31-Jul-2015					Mos					
						Hrs					
						Enc					
Engine 1		Pratt & Whitney of Canada - PW545C						RE (-)			
	72 A/F 30J2934-01 PCE-DF0403	Time at install:				Mos	25-Aug-2015				
						Hrs					
						Ldg					
Engine 2		Pratt & Whitney of Canada - PW545C						RE (-)			
	72 A/F 30J2934-01 PCE-DF0402	Time at install:				Mos	25-Aug-2015				
						Hrs					
						Ldg					
SIL No. GEN-143		P&WC Oil Analysis Technology Trial Program						T (-)	Service Information Letter		
	72 ENG1 Eff: 18-Aug-2016					Mos					
						Hrs					
						Enc					
		Note: NOTE: The purpose of this Service Information Letter is to introduce P&WC operators to the new Oil Analysis Technology Trial program currently in progress for the next 18 to 24 months at P&WC.									
SIL No. GEN-143		P&WC Oil Analysis Technology Trial Program						T (-)	Service Information Letter		
	72 ENG2 Eff: 18-Aug-2016					Mos					
						Hrs					
						Enc					
		Note: NOTE: The purpose of this Service Information Letter is to introduce P&WC operators to the new Oil Analysis Technology Trial program currently in progress for the next 18 to 24 months at P&WC.									

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL No. GEN-143 Rev 1		P&WC Oil Analysis Technology Trial Program						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 02-Feb-2017										
	Note: NOTE: It is recommended that this procedure be accomplished by the operator as soon as practicable upon first oil sampling kit reception and during scheduled maintenance.										
SIL No. GEN-143 Rev 1		P&WC Oil Analysis Technology Trial Program						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 02-Feb-2017										
	Note: NOTE: It is recommended that this procedure be accomplished by the operator as soon as practicable upon first oil sampling kit reception and during scheduled maintenance.										
SIL-GEN-015 R2		Shipment Discrepancies, New Non-Conforming Material and Material Returns						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 23-Nov-2020										
SIL-GEN-015 R2		Shipment Discrepancies, New Non-Conforming Material and Material Returns						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 23-Nov-2020										
SIL-GEN-016 Rev 1		Basic Unplanned Removals (BUR)						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 22-Jun-2023										
SIL-GEN-016 Rev 1		Basic Unplanned Removals (BUR)						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 22-Jun-2023										
SIL-GEN-020 Rev 5		Vane Rings Airflow Rig Correlation and Calibration with P&WC						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 15-Jul-2015										
SIL-GEN-020 Rev 5		Vane Rings Airflow Rig Correlation and Calibration with P&WC						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 15-Jul-2015										
SIL-GEN-020 Rev 6		Vane Rings Airflow Rig Correlation and Calibration with P&WC						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 27-Sep-2021										
SIL-GEN-020 Rev 6		Vane Rings Airflow Rig Correlation and Calibration with P&WC						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 27-Sep-2021										
SIL-GEN-020 Rev 7		Vane Rings Airflow Rig Correlation and Calibration with P&WC						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 09-Jan-2023										
SIL-GEN-020 Rev 7		Vane Rings Airflow Rig Correlation and Calibration with P&WC						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 09-Jan-2023										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-020 Rev 8		Vane Rings Airflow Rig Correlation and Calibration with P&WC						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 10-Jan-2023					Hrs					
						Enc					
SIL-GEN-020 Rev 8		Vane Rings Airflow Rig Correlation and Calibration with P&WC						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 10-Jan-2023					Hrs					
						Enc					
SIL-GEN-020 Rev 9		Vane Rings Airflow Rig Correlation and Calibration with P&WC						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 12-Jan-2024					Hrs					
						Enc					
SIL-GEN-020 Rev 9		Vane Rings Airflow Rig Correlation and Calibration with P&WC						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 12-Jan-2024					Hrs					
						Enc					
SIL-GEN-022 R10		P&WC Service Tool Procurement						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 27-Apr-2020					Hrs					
						Enc					
SIL-GEN-022 R10		P&WC Service Tool Procurement						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 27-Apr-2020					Hrs					
						Enc					
SIL-GEN-022 Rev 11		PWC Service Tool Procurement						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 27-Apr-2020					Hrs					
						Enc					
SIL-GEN-022 Rev 11		PWC Service Tool Procurement						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 27-Apr-2020					Hrs					
						Enc					
SIL-GEN-022 Rev 12		PWC Service Tool Procurement						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 29-May-2023					Hrs					
						Enc					
	Note: Applicability: ALL P&WC ENGINE.										
SIL-GEN-022 Rev 12		PWC Service Tool Procurement						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 29-May-2023					Hrs					
						Enc					
	Note: Applicability: ALL P&WC ENGINE.										
SIL-GEN-034 Rev 4		Engine Maintenance at other than Pratt and Whitney Canada Corp. ("PWC") Recommended Time Between Overhaul ("TBO")/Hot Section Inspection ("HSI") /Periodic Maintenance Intervals and the Effect on Warranty						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 13-Jun-2023					Hrs					
						Enc					
SIL-GEN-034 Rev 4		Engine Maintenance at other than Pratt and Whitney Canada Corp. ("PWC") Recommended Time Between Overhaul ("TBO")/Hot Section Inspection ("HSI") /Periodic Maintenance Intervals and the Effect on Warranty						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 13-Jun-2023					Hrs					
						Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-038 R4		Use of Non-Pratt and Whitney Canada (PWC) Supported Parts or Non-PWC Approved Repair Schemes						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 13-Jun-2023										
SIL-GEN-038 R4		Use of Non-Pratt and Whitney Canada (PWC) Supported Parts or Non-PWC Approved Repair Schemes						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 13-Jun-2023										
SIL-GEN-044		Return of Engine Parts to Pratt & Whitney Canada Inc. (P&WC) for Investigation - Evaluation						RE (-)		Service Information Letter	
	72 ENG1										
	Eff: 03-Jun-1998										
SIL-GEN-044		Return of Engine Parts to Pratt & Whitney Canada Inc. (P&WC) for Investigation - Evaluation						RE (-)		Service Information Letter	
	72 ENG2										
	Eff: 03-Jun-1998										
SIL-GEN-044 R1		Material Returned to PWC						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 16-Oct-2017										
SIL-GEN-044 R1		Material Returned to PWC						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 16-Oct-2017										
SIL-GEN-044 Rev 2		Material Returned to PWC						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 03-Aug-2023										
SIL-GEN-044 Rev 2		Material Returned to PWC						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 03-Aug-2023										
SIL-GEN-049		Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code						RE (-)		Service Information Letter	
	72 ENG1										
SIL-GEN-049		Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code						RE (-)		Service Information Letter	
	72 ENG2										
SIL-GEN-049 R1		Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 02-Nov-2012										
SIL-GEN-049 R1		Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 02-Nov-2012										
SIL-GEN-049 R2		Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 13-Sep-2019										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-049 R2		Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 13-Sep-2019										
SIL-GEN-055		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
	72 ENG1										
SIL-GEN-055		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
	72 ENG2										
SIL-GEN-055 R1		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
	72 ENG1										
SIL-GEN-055 R1		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
	72 ENG2										
SIL-GEN-055 R10		Guidelines and Standards for Subscribing and Utilizing the Internet-Based Engine Condition Trend Monitoring EHM Services						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 13-Nov-2018										
SIL-GEN-055 R10		Guidelines and Standards for Subscribing and Utilizing the Internet-Based Engine Condition Trend Monitoring EHM Services						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 13-Nov-2018										
SIL-GEN-055 R2		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
	72 ENG1										
SIL-GEN-055 R2		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
	72 ENG2										
SIL-GEN-055 R3		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
	72 ENG1										
SIL-GEN-055 R3		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
	72 ENG2										
SIL-GEN-055 R4		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
	72 ENG1										
SIL-GEN-055 R4		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
	72 ENG2										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-GEN-055 R5  72 ENG1	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
SIL-GEN-055 R5  72 ENG2	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
SIL-GEN-055 R6  72 ENG1	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
SIL-GEN-055 R6  72 ENG2	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
SIL-GEN-055 R8  72 ENG1 Eff: 06-Nov-2018	Guidelines and Standards for Subscribing and Utilizing the Internet-based Engine Condition Trend Monitoring EHM Services						T (-)		Service Information Letter	
SIL-GEN-055 R8  72 ENG2 Eff: 06-Nov-2018	Guidelines and Standards for Subscribing and Utilizing the Internet-based Engine Condition Trend Monitoring EHM Services						T (-)		Service Information Letter	
SIL-GEN-055 R9  72 ENG1 Eff: 08-Nov-2018	Guidelines and Standards for Subscribing and Utilizing the Internet-based Engine Condition Trend Monitoring EHM Services						T (-)		Service Information Letter	
SIL-GEN-055 R9  72 ENG2 Eff: 08-Nov-2018	Guidelines and Standards for Subscribing and Utilizing the Internet-based Engine Condition Trend Monitoring EHM Services						T (-)		Service Information Letter	
SIL-GEN-061  72 ENG1	Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061  72 ENG2	Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 1  72 ENG1	Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 1  72 ENG2	Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 10  72 ENG1 Eff: 25-Jan-2021	Engine Related Requests						T (-)		Service Information Letter	

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-061 Rev 10		Engine Related Requests								T (-)	Service Information Letter
	72 ENG2										
	Eff: 25-Jan-2021										
SIL-GEN-061 Rev 11		Engine Related Requests								T (A/R)	Service Information Letter
	72 ENG1										
	Eff: 19-Mar-2024										
SIL-GEN-061 Rev 11		Engine Related Requests								T (A/R)	Service Information Letter
	72 ENG2										
	Eff: 19-Mar-2024										
SIL-GEN-061 Rev 2		Engine Related Requests								RE (-)	Service Information Letter
	72 ENG1										
SIL-GEN-061 Rev 2		Engine Related Requests								RE (-)	Service Information Letter
	72 ENG2										
SIL-GEN-061 Rev 3		Engine Related Requests								RE (-)	Service Information Letter
	72 ENG1										
SIL-GEN-061 Rev 3		Engine Related Requests								RE (-)	Service Information Letter
	72 ENG2										
SIL-GEN-061 Rev 4		Engine Related Requests								RE (-)	Service Information Letter
	72 ENG1										
SIL-GEN-061 Rev 4		Engine Related Requests								RE (-)	Service Information Letter
	72 ENG2										
SIL-GEN-061 Rev 5		Engine Related Requests								RE (-)	Service Information Letter
	72 ENG1										
SIL-GEN-061 Rev 5		Engine Related Requests								RE (-)	Service Information Letter
	72 ENG2										
SIL-GEN-061 Rev 6		Engine Related Requests								RE (-)	Service Information Letter
	72 ENG1										
SIL-GEN-061 Rev 6		Engine Related Requests								RE (-)	Service Information Letter
	72 ENG2										

Task No SEQ PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
SIL-GEN-061 Rev 7  72 ENG1	Engine Related Requests						RE (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-061 Rev 7  72 ENG2	Engine Related Requests						RE (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-061 Rev 8  72 ENG1 Eff: 10-Apr-2018	Engine Related Requests						T (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-061 Rev 8  72 ENG2 Eff: 10-Apr-2018	Engine Related Requests						T (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-061 Rev 9  72 ENG1 Eff: 21-Mar-2019	Engine Related Requests						T (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-061 Rev 9  72 ENG2 Eff: 21-Mar-2019	Engine Related Requests						T (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-065 Rev 1  72 ENG1 Eff: 29-Jun-2023	Information Required to Process New Engine Accessory Warranty Claims						T (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-065 Rev 1  72 ENG2 Eff: 29-Jun-2023	Information Required to Process New Engine Accessory Warranty Claims						T (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-065 Rev 2  72 ENG1 Eff: 13-Mar-2024	Information Required to Process New Engine Accessory Warranty Claims						T (A/R)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-065 Rev 2  72 ENG2 Eff: 13-Mar-2024	Information Required to Process New Engine Accessory Warranty Claims						T (A/R)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-093  72 ENG1 Eff: 20-Mar-2009	Engine Preservation and Storage						RE (-)		Informational	
										Mos
										Hrs
										Enc
SIL-GEN-093  72 ENG2 Eff: 20-Mar-2009	Engine Preservation and Storage						RE (-)		Informational	
										Mos
										Hrs
										Enc
SIL-GEN-093 R1  72 ENG1 Eff: 14-Apr-2016	Engine Preservation and Storage						T (-)		Informational	
										Mos
										Hrs
										Enc

OK-ECR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-ECR,SN 560-6198

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-GEN-093 R1	Engine Preservation and Storage						T (-)		Informational	
 72 ENG2 Eff: 14-Apr-2016					Mos					
					Hrs					
					Enc					
SIL-GEN-093 R2	Engine Preservation and Storage						T (A/R)		Service Information Letter	
 72 ENG1 Eff: 22-Oct-2021					Mos					
					Hrs					
					Enc					
SIL-GEN-093 R2	Engine Preservation and Storage						T (A/R)		Service Information Letter	
 72 ENG2 Eff: 22-Oct-2021					Mos					
					Hrs					
					Enc					
SIL-GEN-110	Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						RE (-)		Service Information Letter	
 72 ENG1					Mos					
					Hrs					
					Enc					
SIL-GEN-110	Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						RE (-)		Service Information Letter	
 72 ENG2					Mos					
					Hrs					
					Enc					
SIL-GEN-110 Rev 1	Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						RE (-)		Service Information Letter	
 72 ENG1					Mos					
					Hrs					
					Enc					
SIL-GEN-110 Rev 1	Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						RE (-)		Service Information Letter	
 72 ENG2					Mos					
					Hrs					
					Enc					
SIL-GEN-110 Rev 3	Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						T (A/R)		Service Information Letter	
 72 ENG1 Eff: 19-Dec-2018					Mos					
					Hrs					
					Enc					
SIL-GEN-110 Rev 3	Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						T (A/R)		Service Information Letter	
 72 ENG2 Eff: 19-Dec-2018					Mos					
					Hrs					
					Enc					
SIL-GEN-117 Rev 1	Warranty Allowance for Consumable Materials and Miscellaneous Parts Used During Engine Line Maintenance Work in the Field						T (A/R)		Service Information Letter	
 72 ENG1 Eff: 14-Apr-2023					Mos					
					Hrs					
					Enc					
SIL-GEN-117 Rev 1	Warranty Allowance for Consumable Materials and Miscellaneous Parts Used During Engine Line Maintenance Work in the Field						T (A/R)		Service Information Letter	
 72 ENG2 Eff: 14-Apr-2023					Mos					
					Hrs					
					Enc					
SIL-GEN-121 Rev 1	Mobile Repair Team Travel Allowance Instructions for Warranty or ESP Program Coverage						T (A/R)		Service Information Letter	
 72 ENG1 Eff: 13-Apr-2023					Mos					
					Hrs					
					Enc					
SIL-GEN-121 Rev 1	Mobile Repair Team Travel Allowance Instructions for Warranty or ESP Program Coverage						T (A/R)		Service Information Letter	
 72 ENG2 Eff: 13-Apr-2023					Mos					
					Hrs					
					Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-122		Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
	72 ENG1					Mos					
						Hrs					
						Enc					
SIL-GEN-122		Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
	72 ENG2					Mos					
						Hrs					
						Enc					
SIL-GEN-122 R1		Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
	72 ENG1					Mos					
						Hrs					
						Enc					
SIL-GEN-122 R1		Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
	72 ENG2					Mos					
						Hrs					
						Enc					
SIL-GEN-122 R10		Recovery Fee for Maintenance Deviation Letters						RE (-)		Service Information Letter	
	72 ENG1					Mos					
						Hrs					
						Enc					
SIL-GEN-122 R10		Recovery Fee for Maintenance Deviation Letters						RE (-)		Service Information Letter	
	72 ENG2					Mos					
						Hrs					
						Enc					
SIL-GEN-122 R11		Recovery Fee for Maintenance Deviation Letters						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 29-Jun-2022					Hrs					
						Enc					
SIL-GEN-122 R11		Recovery Fee for Maintenance Deviation Letters						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 29-Jun-2022					Hrs					
						Enc					
SIL-GEN-122 R2		Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
	72 ENG1					Mos					
						Hrs					
						Enc					
SIL-GEN-122 R2		Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
	72 ENG2					Mos					
						Hrs					
						Enc					
SIL-GEN-122 R3		Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
	72 ENG1					Mos					
						Hrs					
						Enc					
SIL-GEN-122 R3		Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
	72 ENG2					Mos					
						Hrs					
						Enc					
SIL-GEN-122 R4		Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
	72 ENG1					Mos					
						Hrs					
						Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-122 R4	72 ENG2	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
SIL-GEN-122 R5	72 ENG1	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
SIL-GEN-122 R5	72 ENG2	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
SIL-GEN-122 R6	72 ENG1 Eff: 29-Dec-2017	Recovery Fee For Maintenance Deviation Letters						T (-)		Service Information Letter	
SIL-GEN-122 R6	72 ENG2 Eff: 29-Dec-2017	Recovery Fee For Maintenance Deviation Letters						T (-)		Service Information Letter	
SIL-GEN-122 R7	72 ENG1 Eff: 19-Dec-2018	Recovery Fee For Maintenance Deviation Letters						T (-)		Service Information Letter	
SIL-GEN-122 R7	72 ENG2 Eff: 19-Dec-2018	Recovery Fee For Maintenance Deviation Letters						T (-)		Service Information Letter	
SIL-GEN-122 R8	72 ENG1 Eff: 20-Dec-2019	Recovery Fee for Maintenance Deviation Letters						T (-)		Service Information Letter	
SIL-GEN-122 R8	72 ENG2 Eff: 20-Dec-2019	Recovery Fee for Maintenance Deviation Letters						T (-)		Service Information Letter	
SIL-GEN-122 R9	72 ENG1 Eff: 18-Dec-2020	Recovery Fee for Maintenance Deviation Letters						T (-)		Service Information Letter	
SIL-GEN-122 R9	72 ENG2 Eff: 18-Dec-2020	Recovery Fee for Maintenance Deviation Letters						T (-)		Service Information Letter	
SIL-GEN-123	72 ENG1 Eff: 21-Jan-2013	Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123	72 ENG2 Eff: 21-Jan-2013	Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-123 R1  72 ENG1		Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R1  72 ENG2		Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R2  72 ENG1		Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R2  72 ENG2		Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R3  72 ENG1		Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R3  72 ENG2		Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R4  72 ENG1		Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R4  72 ENG2		Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R5  72 ENG1		Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R5  72 ENG2		Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R6  72 ENG1		Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R6  72 ENG2		Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R7  72 ENG1 Eff: 10-Jul-2018		Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-GEN-123 R7	Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	
 72 ENG2										
Eff: 10-Jul-2018										
SIL-GEN-123 Rev 10	Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	
 72 ENG1										
Eff: 13-Mar-2023										
SIL-GEN-123 Rev 10	Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	
 72 ENG2										
Eff: 13-Mar-2023										
SIL-GEN-123 Rev 11	Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	
 72 ENG1										
Eff: 12-Sep-2023										
SIL-GEN-123 Rev 11	Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	
 72 ENG2										
Eff: 12-Sep-2023										
SIL-GEN-123 Rev 12	Qualified Engine Oil Analysis Laboratory List						T (A/R)		Service Information Letter	
 72 ENG1										
Eff: 04-Dec-2023										
SIL-GEN-123 Rev 12	Qualified Engine Oil Analysis Laboratory List						T (A/R)		Service Information Letter	
 72 ENG2										
Eff: 04-Dec-2023										
SIL-GEN-123 Rev 8	Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	
 72 ENG1										
Eff: 25-Jul-2018										
SIL-GEN-123 Rev 8	Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	
 72 ENG2										
Eff: 25-Jul-2018										
SIL-GEN-123 Rev 9	Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	
 72 ENG1										
Eff: 14-Jul-2022										
SIL-GEN-123 Rev 9	Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	
 72 ENG2										
Eff: 14-Jul-2022										
SIL-GEN-128 Rev 1	Limited Time Offer for P&WC Engine Diagnostic System for Applicable P&WC Turbofan Powered Aircraft						T (A/R)		Service Information Letter	
 72 ENG1										
Eff: 15-Jul-2013										
SIL-GEN-128 Rev 1	Limited Time Offer for P&WC Engine Diagnostic System for Applicable P&WC Turbofan Powered Aircraft						T (A/R)		Service Information Letter	
 72 ENG2										
Eff: 15-Jul-2013										

OK-ECR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
560XL (Citation XLS+) OK-ECR,SN 560-6198

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-135		Aviation Accidents / Incidents - Return to Service of Affected P&WC Products and the Effect on Engine Warranty and Service Policies Status (This Service Information Letter (SIL) supersedes SIL GEN-039)							T (-)	Service Information Letter	
	72 ENG1										
	Eff: 21-Feb-2017										
		Note: APPLICABILITY: All P&WC engines.									
SIL-GEN-135		Aviation Accidents / Incidents - Return to Service of Affected P&WC Products and the Effect on Engine Warranty and Service Policies Status (This Service Information Letter (SIL) supersedes SIL GEN-039)							T (-)	Service Information Letter	
	72 ENG2										
	Eff: 21-Feb-2017										
		Note: APPLICABILITY: All P&WC engines.									
SIL-GEN-135 Rev 1		Aviation Accidents / Incidents - Return to Service of Affected P&WC Products and the Effect on Engine Warranty and Service Policies Status							T (A/R)	Service Information Letter	
	72 ENG1										
	Eff: 03-Jun-2021										
SIL-GEN-135 Rev 1		Aviation Accidents / Incidents - Return to Service of Affected P&WC Products and the Effect on Engine Warranty and Service Policies Status							T (A/R)	Service Information Letter	
	72 ENG2										
	Eff: 03-Jun-2021										
SIL-GEN-143		P&WC'S Oil Analysis Technology Trial Program							RE (-)	Service Information Letter	
	72 ENG1										
	Eff: 18-Aug-2016										
SIL-GEN-143		P&WC'S Oil Analysis Technology Trial Program							RE (-)	Service Information Letter	
	72 ENG2										
	Eff: 18-Aug-2016										
SIL-GEN-143 R1		P&WC'S Oil Analysis Technology Trial Program							RE (-)	Service Information Letter	
	72 ENG1										
SIL-GEN-143 R1		P&WC'S Oil Analysis Technology Trial Program							RE (-)	Service Information Letter	
	72 ENG2										
SIL-GEN-143 R2		P&WC'S Oil Analysis Technology Trial Program							T (A/R)	Service Information Letter	
	72 ENG1										
	Eff: 09-Jul-2018										
SIL-GEN-143 R2		P&WC'S Oil Analysis Technology Trial Program							T (A/R)	Service Information Letter	
	72 ENG2										
	Eff: 09-Jul-2018										
SIL-GEN-153		P&WC's Oil Analysis Technology Program Logistics Information							T (-)	Service Information Letter	
	72 ENG1										
	Eff: 17-Jul-2018										
SIL-GEN-153		P&WC's Oil Analysis Technology Program Logistics Information							T (-)	Service Information Letter	
	72 ENG2										
	Eff: 17-Jul-2018										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-153 Rev 1		P&WC's Oil Analysis Technology Program Logistics Information						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 10-Mar-2019										
SIL-GEN-153 Rev 1		P&WC's Oil Analysis Technology Program Logistics Information						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 10-Mar-2019										
SIL-GEN-153 Rev 10		P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 31-Oct-2022										
SIL-GEN-153 Rev 10		P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 31-Oct-2022										
SIL-GEN-153 Rev 11		P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 22-Dec-2022										
SIL-GEN-153 Rev 11		P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 22-Dec-2022										
SIL-GEN-153 Rev 12		P&WC's Oil Analysis Technology Service Logistics Information						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 23-Jan-2024										
SIL-GEN-153 Rev 12		P&WC's Oil Analysis Technology Service Logistics Information						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 23-Jan-2024										
SIL-GEN-153 Rev 2		P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 20-Jun-2019										
SIL-GEN-153 Rev 2		P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 20-Jun-2019										
SIL-GEN-153 Rev 3		P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 26-Sep-2019										
SIL-GEN-153 Rev 3		P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 26-Sep-2019										
SIL-GEN-153 Rev 4		P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 05-May-2020										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-153 Rev 4	72 ENG2 Eff: 05-May-2020	P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-153 Rev 5	72 ENG1 Eff: 28-Sep-2020	P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-153 Rev 5	72 ENG2 Eff: 28-Sep-2020	P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-153 Rev 6	72 ENG1 Eff: 30-Oct-2020	P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-153 Rev 6	72 ENG2 Eff: 30-Oct-2020	P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-153 Rev 7	72 ENG1 Eff: 05-Jan-2021	P&WC's Oil Analysis Technology Service Logistics Information						T (A/R)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-153 Rev 7	72 ENG2 Eff: 05-Jan-2021	P&WC's Oil Analysis Technology Service Logistics Information						T (A/R)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-153 Rev 8	72 ENG1 Eff: 15-Sep-2021	P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-153 Rev 8	72 ENG2 Eff: 15-Sep-2021	P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-153 Rev 9	72 ENG1 Eff: 18-Jan-2022	P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-153 Rev 9	72 ENG2 Eff: 18-Jan-2022	P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-155	72 ENG1 Eff: 14-Jun-2019	Introduction of Hyperlinks in P&WC Service Bulletins						T (A/R)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-155	72 ENG2 Eff: 14-Jun-2019	Introduction of Hyperlinks in P&WC Service Bulletins						T (A/R)		Service Information Letter	
						Mos					
						Hrs					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-GEN-156 R1  72 ENG1 Eff: 02-Apr-2020	DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation								T (-)	Service Information Letter
SIL-GEN-156 R1  72 ENG2 Eff: 02-Apr-2020	DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation								T (-)	Service Information Letter
SIL-GEN-156 R2  72 ENG1 Eff: 07-Apr-2020	DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation								T (A/R)	Service Information Letter
SIL-GEN-156 R2  72 ENG2 Eff: 07-Apr-2020	DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation								T (A/R)	Service Information Letter
SIL-GEN-157  72 ENG1 Eff: 18-Mar-2020	Preservation - Engines Removed from Service on Temporary Basis								T (A/R)	Service Information Letter
SIL-GEN-157  72 ENG2 Eff: 18-Mar-2020	Preservation - Engines Removed from Service on Temporary Basis								T (A/R)	Service Information Letter
SIL-GEN-158  72 ENG1 Eff: 20-Jul-2020	Handling of Suspected Hexavalent Chromium Residue on Engine Parts During Maintenance, Repair and Overhaul								T (A/R)	Service Information Letter
SIL-GEN-158  72 ENG2 Eff: 20-Jul-2020	Handling of Suspected Hexavalent Chromium Residue on Engine Parts During Maintenance, Repair and Overhaul								T (A/R)	Service Information Letter
SIL-GEN-159  72 ENG1 Eff: 08-Jul-2020	Environmentally Assisted Cracking in Certain Aluminium Alloys								T (A/R)	Service Information Letter
SIL-GEN-159  72 ENG2 Eff: 08-Jul-2020	Environmentally Assisted Cracking in Certain Aluminium Alloys								T (A/R)	Service Information Letter
SIL-GEN-160  72 ENG1 Eff: 30-Jun-2020	Occasional Dust Plume Exposure								T (A/R)	Service Information Letter
SIL-GEN-160  72 ENG2 Eff: 30-Jun-2020	Occasional Dust Plume Exposure								T (A/R)	Service Information Letter
SIL-GEN-161  72 ENG1 Eff: 19-Oct-2020	Operations in Environments Affected by Wildfires, Bushfires and Forest Fires								T (A/R)	Service Information Letter

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-GEN-161	Operations in Environments Affected by Wildfires, Bushfires and Forest Fires						T (A/R)		Service Information Letter	
 72 ENG2										
Eff: 19-Oct-2020										
SIL-GEN-166	Critical Component Accumulated Cycle Counting						T (A/R)		Service Information Letter	
 72 ENG1										
Eff: 23-Jun-2021										
SIL-GEN-166	Critical Component Accumulated Cycle Counting						T (A/R)		Service Information Letter	
 72 ENG2										
Eff: 23-Jun-2021										
SIL-GEN-168	Reminder Regarding Scheduled Maintenance Tasks at Engine Shop Visits						T (A/R)		Service Information Letter	
 72 ENG1										
Eff: 23-Sep-2022										
SIL-GEN-168	Reminder Regarding Scheduled Maintenance Tasks at Engine Shop Visits						T (A/R)		Service Information Letter	
 72 ENG2										
Eff: 23-Sep-2022										
SIL-GEN-169	PWC Generation 3 Recorder End of New Production						T (A/R)		Service Information Letter	
 72 ENG1										
Eff: 27-Mar-2023										
SIL-GEN-169	PWC Generation 3 Recorder End of New Production						T (A/R)		Service Information Letter	
 72 ENG2										
Eff: 27-Mar-2023										
SIL-PW200-004	New Engine Serial Numbering Methodology						RE (-)		Service Information Letter	
 72 ENG1										
Eff: 20-Jun-1996										
SIL-PW200-004	New Engine Serial Numbering Methodology						RE (-)		Service Information Letter	
 72 ENG2										
Eff: 20-Jun-1996										
SIL-PW200-004 R1	New Engine Serial Numbering Methodology						RE (-)		Service Information Letter	
 72 ENG1										
Eff: 23-Sep-1998										
SIL-PW200-004 R1	New Engine Serial Numbering Methodology						RE (-)		Service Information Letter	
 72 ENG2										
Eff: 23-Sep-1998										
SIL-PW200-004 R2	New Engine Serial Numbering Methodology						T (A/R)		Service Information Letter	
 72 ENG1										
Eff: 12-Mar-2004										
SIL-PW200-004 R2	New Engine Serial Numbering Methodology						T (A/R)		Service Information Letter	
 72 ENG2										
Eff: 12-Mar-2004										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-PW300-007  72 ENG1 Eff: 20-Jun-1996	New Engine Serial Numbering Methodology						RE (-)		Service Information Letter	
SIL-PW300-007  72 ENG2 Eff: 20-Jun-1996	New Engine Serial Numbering Methodology						RE (-)		Service Information Letter	
SIL-PW300-007 Rev 1  72 ENG1 Eff: 23-Sep-1998	New Engine Serial Numbering Methodology						T (A/R)		Service Information Letter	
SIL-PW300-007 Rev 1  72 ENG2 Eff: 23-Sep-1998	New Engine Serial Numbering Methodology						T (A/R)		Service Information Letter	
SIL-PW500-022  72 ENG1 Eff: 01-Jan-2006	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)						RE (-)		Service Information Letter	
SIL-PW500-022  72 ENG2 Eff: 01-Jan-2006	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)						RE (-)		Service Information Letter	
SIL-PW500-022 Rev 1  72 ENG1	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)						RE (-)		Service Information Letter	
SIL-PW500-022 Rev 1  72 ENG2	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)						RE (-)		Service Information Letter	
SIL-PW500-022 Rev 2  72 ENG1	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)						RE (-)		Service Information Letter	
SIL-PW500-022 Rev 2  72 ENG2	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)						RE (-)		Service Information Letter	
SIL-PW500-022 Rev 3  72 ENG1 Eff: 13-Sep-2019	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)						T (A/R)		Service Information Letter	
SIL-PW500-022 Rev 3  72 ENG2 Eff: 13-Sep-2019	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)						T (A/R)		Service Information Letter	
SIL-PW500-067  72 ENG1 Eff: 28-Feb-2017	High Compressor Rotor 2nd Stage						T (A/R)		Service Information Letter	

OK-ECR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-ECR,SN 560-6198

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-PW500-067		High Compressor Rotor 2nd Stage						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 28-Feb-2017										
SIL-PW500-069		Electronic Engine Control (EEC) Service Bulletin 30478						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 20-Jun-2017										
		Note: Note: CSPN 1006723R08 will close on 31 December 2017, operators are advised that P&WC does not plan to extend the program beyond this date.									
SIL-PW500-069		Electronic Engine Control (EEC) Service Bulletin 30478						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 20-Jun-2017										
		Note: Note: CSPN 1006723R08 will close on 31 December 2017, operators are advised that P&WC does not plan to extend the program beyond this date.									
SIL-PW500-071		Electronic Data Analysis Service for Engine DCU Downloads						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 21-Nov-2017										
SIL-PW500-071		Electronic Data Analysis Service for Engine DCU Downloads						RE (-)		Service Information Letter	
	72 ENG2										
	Eff: 21-Nov-2017 Complied With										
SIL-PW500-072		ACES Viper II Analyzer Introduction						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 02-Oct-2018										
SIL-PW500-072		ACES Viper II Analyzer Introduction						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 02-Oct-2018										
SIL-PW500-073		Oil Analysis Technology Solution Now available						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 01-Aug-2019										
SIL-PW500-073		Oil Analysis Technology Solution Now available						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 01-Aug-2019										
SIL-PW500-073 Rev 1		Oil Analysis Technology Solution Now Available						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 04-Oct-2019										
SIL-PW500-073 Rev 1		Oil Analysis Technology Solution Now Available						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 04-Oct-2019										
SIL-PW500-073 Rev 2		P&WC's Oil Analysis Technology Solution Now Available						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 08-Jan-2020										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
 SIL-PW500-073 Rev 2 72 ENG2 Eff: 08-Jan-2020	P&WC's Oil Analysis Technology Solution Now Available								T (-)	Service Information Letter
 SIL-PW500-073 Rev 3 72 ENG1 Eff: 05-Jan-2021	P&WC's Oil Analysis Technology Solution Now Available								T (A/R)	Service Information Letter
 SIL-PW500-073 Rev 3 72 ENG2 Eff: 05-Jan-2021	P&WC's Oil Analysis Technology Solution Now Available								T (A/R)	Service Information Letter
 SIL-PW500-075 72 ENG1 Eff: 14-Dec-2021	BOV Servo Valve - New Revision to PW500 Maintenance Manuals, Section 05-20-00 Scheduled Maintenance Check - Engine Accessories at Engine Overhaul								T (A/R)	Service Information Letter
 SIL-PW500-075 72 ENG2 Eff: 14-Dec-2021	BOV Servo Valve - New Revision to PW500 Maintenance Manuals, Section 05-20-00 Scheduled Maintenance Check - Engine Accessories at Engine Overhaul								T (A/R)	Service Information Letter
 SIL-PW500-078 72 ENG1 Eff: 04-Dec-2023	Low Pressure Shaft Balancing Assembly - New revision to PW500 Maintenance Manuals, section 05-20-00 Scheduled Maintenance Check - Periodic Inspections								T (A/R)	Service Information Letter
 SIL-PW500-078 72 ENG2 Eff: 04-Dec-2023	Low Pressure Shaft Balancing Assembly - New revision to PW500 Maintenance Manuals, section 05-20-00 Scheduled Maintenance Check - Periodic Inspections								T (A/R)	Service Information Letter
 SL560XL-72-04 72 A/F Eff: 15-Mar-2001 Not Applicable	Engine - Transmittal Of Pratt & Whitney Canada Service Bulletin PW500-72-30110R1, Turbofan Engine - Oil Level Indicator - Replacement Of Different SN								RE (-)	Recommended
 SL560XL-72-05 72 A/F Eff: 15-Mar-2001 Not Applicable	Engine - Transmittal Of Pratt & Whitney Canada Service Bulletin PW500-72-30135R1, Turbofan Engine - Oil Filler Cap - Replacement Of Different SN								RE (-)	Recommended
 SL560XL-72-07 72 A/F Eff: 17-Dec-2001	Engine - Transmittal of Pratt & Whitney Canada (PW&C) Service Bulletins PW500-72-30193 and PW500-72-30193, Turbofan Engine Oil Leaks From No. 4 Bearing Pressure and Scavenge Transfer Tubes.								T (A/R)	Informational
 SL560XL-72-08 72 A/F Eff: 01-May-2002 Not Applicable	Engine - Transmittal of Pratt & Whitney Canada (P&WC) Service Bulletin PW500-72-30203, Replacement of Alternator Shaft Plain Seal as per engine S/N								RE (-)	Recommended

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-72-09	Engine - Transmittal of Pratt & Whitney Canada Service Bulletin PW500-72-30217, Turbofan Engine Fuel Tube - Inspection Of						RE (-)		Recommended	
 72 A/F						Mos	13-Sep-2021			
Eff: 03-Jun-2002 Not Applicable	as per engine S/N					Hrs	2222:03			
						Ldg	1,687			
SL560XL-72-10	Transmittal of Pratt & Whitney Canada (P&WC) Service Information Letter PW500-015, PW545A Fan Case Extension Cracking						T (A/R)		Informational	
 72 A/F						Mos				
Eff: 11-Aug-2003						Hrs				
						Ldg				
SL560XL-72-11	Transmittal of Pratt & Whitney Canada Service Bulletin PW500-72-30252 Number Four Bearing Oil Pressure and Oil Scavenge Tubes - Replacement Of						RE (-)		Optional	
 72 A/F						Mos	14-Sep-2021			
Cancelled	Cancelled - superseded by SL560XL-72-14)					Hrs				
						Ldg				
SL560XL-72-11 Rev 01	Transmittal of Pratt & Whitney Canada Service Bulletin PW500-72-30252 Number Four Bearing Oil Pressure and Oil Scavenge Tubes - Replacement Of						RE (-)		Recommended	
 72 A/F						Mos	14-Sep-2021			
Eff: 27-Nov-2007 Cancelled	Cancelled - superseded by SL560XL-72-14)					Hrs				
						Ldg				
Note: Cancelled - superseded by SL560XL-72-14										
▼ 73 - ENGINE - FUEL AND CONTROL										
 73 A/F	Fuel Flow Transmitter						RE (O/C)			
9-231-28	Left					Mos	17-Feb-2016			
L10265						Hrs	76:09			
						Ldg	71			
						Hrs (APU)	41			
						Start (APU)	48			
 73 A/F	Fuel Flow Transmitter						RE (O/C)			
9-231-28	Right					Mos	17-Feb-2016			
L7250						Hrs	76:09			
						Ldg	71			
						Hrs (APU)	41			
						Start (APU)	48			
 73 ENG1	Fuel Nozzle Assembly						RE (O/C)			
30J2313-02	No.1	0				Mos	29-Oct-2015			
DEAAA64700	New	0				Hrs	0			
		0				Enc	0			
 73 ENG2	Fuel Nozzle Assembly						RE (O/C)			
30J2313-02	No.1	0				Mos	29-Oct-2015			
DEAAA63874	New	0				Hrs	0			
		0				Enc	0			
 73 ENG1	Fuel Nozzle Assembly						RE (O/C)			
30J2313-02	No.10	0				Mos	29-Oct-2015			
DEAAA65376	New	0				Hrs	0			
		0				Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	73 ENG2 30J2313-02 DEAAA65374	Fuel Nozzle Assembly								RE (O/C)	
		No.10	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	73 ENG1 30J2313-02 DEAAA65378	Fuel Nozzle Assembly								RE (O/C)	
		No.11	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	73 ENG2 30J2313-02 DEAAA65377	Fuel Nozzle Assembly								RE (O/C)	
		No.11	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	73 ENG1 30J2313-02 DEAAA65358	Fuel Nozzle Assembly								RE (O/C)	
		No.2	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	73 ENG2 30J2313-02 DEAAA84287	Fuel Nozzle Assembly								RE (O/C)	
		No.2	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	73 ENG1 30J2313-02 DEAAA65359	Fuel Nozzle Assembly								RE (O/C)	
		No.3	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	73 ENG2 30J2313-02 DEAAA65362	Fuel Nozzle Assembly								RE (O/C)	
		No.3	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	73 ENG1 30J2313-02 DEAAA65360	Fuel Nozzle Assembly								RE (O/C)	
		No.4	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	73 ENG2 30J2313-02 DEAAA65384	Fuel Nozzle Assembly								RE (O/C)	
		No.4	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	73 ENG1 30J2313-02 DEAAA65361	Fuel Nozzle Assembly								RE (O/C)	
		No.5	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				
	73 ENG2 30J2313-02 DEAAA85366	Fuel Nozzle Assembly								RE (O/C)	
		No.5	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
			0			Enc	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	73 ENG1 30J2313-02 DEAAA65363	Fuel Nozzle Assembly						RE (O/C)			
		No.6	0					Mos	29-Oct-2015		
		New	0					Hrs	0		
			0					Enc	0		
	73 ENG2 30J2313-02 DEAAA65368	Fuel Nozzle Assembly						RE (O/C)			
		No.6	0					Mos	29-Oct-2015		
		New	0					Hrs	0		
			0					Enc	0		
	73 ENG1 30J2313-02 DEAAA65367	Fuel Nozzle Assembly						RE (O/C)			
		No.7	0					Mos	29-Oct-2015		
		New	0					Hrs	0		
			0					Enc	0		
	73 ENG2 30J2313-02 DEAAA65370	Fuel Nozzle Assembly						RE (O/C)			
		No.7	0					Mos	29-Oct-2015		
		New	0					Hrs	0		
			0					Enc	0		
	73 ENG1 30J2313-02 DEAAA65371	Fuel Nozzle Assembly						RE (O/C)			
		No.8	0					Mos	29-Oct-2015		
		New	0					Hrs	0		
			0					Enc	0		
	73 ENG2 30J2313-02 DEAAA65372	Fuel Nozzle Assembly						RE (O/C)			
		No.8	0					Mos	29-Oct-2015		
		New	0					Hrs	0		
			0					Enc	0		
	73 ENG1 30J2313-02 DEAAA65375	Fuel Nozzle Assembly						RE (O/C)			
		No.9	0					Mos	29-Oct-2015		
		New	0					Hrs	0		
			0					Enc	0		
	73 ENG2 30J2313-02 DEAAA65373	Fuel Nozzle Assembly						RE (O/C)			
		No.9	0					Mos	29-Oct-2015		
		New	0					Hrs	0		
			0					Enc	0		
	73 A/F 6057-3 3311	Fuel Pressure Switch						RE (O/C)			
		Left	0					Mos	29-Oct-2015		
		New	0					Hrs	0		
			0					Ldg	0		
	73 A/F 6057-3 3320	Fuel Pressure Switch						RE (O/C)			
		Right	0					Mos	29-Oct-2015		
		New	0					Hrs	0		
			0					Ldg	0		
	73 ENG1 30J3050-03 F82153	Hydromechanical Fuel Control						RE (O/C)			
			0					Mos	29-Oct-2015		
			0					Hrs	0		
			0					Enc	0		

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
Hydromechanical Fuel Control										
	73 ENG2	New	0			Mos	29-Oct-2015		RE (O/C)	
	30J3050-03		0			Hrs	0			
	F82112		0			Enc	0			
30405		Fuel Nozzle Manifold - Replacement							RE (-)	Category 6
	73 ENG1					Mos				
						Hrs				
						Enc				
30405		Fuel Nozzle Manifold - Replacement							RE (-)	Category 6
	73 ENG2					Mos				
						Hrs				
						Enc				
30405 Rev 1		Fuel Nozzle Manifold - Replacement							RE (-)	Category 6
	73 ENG1					Mos				
						Hrs				
						Enc				
30405 Rev 1		Fuel Nozzle Manifold - Replacement							RE (-)	Category 6
	73 ENG2					Mos				
						Hrs				
						Enc				
30405 Rev 2		Fuel Nozzle Manifold - Replacement							RE (-)	Category 6
	73 ENG1					Mos				
						Hrs				
						Enc				
30405 Rev 2		Fuel Nozzle Manifold - Replacement							RE (-)	Category 6
	73 ENG2					Mos				
						Hrs				
						Enc				
30405 Rev 3		Fuel Nozzle Manifold - Replacement							RE (-)	Category 6
	73 ENG1	Eff: 20-Jul-2012 Complied With AT MANUFACTURE				Mos	29-Oct-2015			
						Hrs	0			
						Enc	0			
30405 Rev 3		Fuel Nozzle Manifold - Replacement							RE (-)	Category 6
	73 ENG2	Eff: 20-Jul-2012 Complied With AT MANUFACTURE				Mos	29-Oct-2015			
						Hrs	0			
						Enc	0			
30405 Rev 4		Fuel Nozzle Manifold - Replacement							RE (-)	Category 6
	73 ENG1	Eff: 14-Mar-2018				Mos				
						Hrs				
						Enc				
30405 Rev 4		Fuel Nozzle Manifold - Replacement							RE (-)	Category 6
	73 ENG2	Eff: 14-Mar-2018				Mos				
						Hrs				
						Enc				
30418 Rev 2		Replacement/ Modification of Electrical Wiring Harness (TT0 Sensor)							RE (-)	Category 6
	73 ENG1	Eff: 12-May-2016 (AVG MAN HRS: 2.5)				Mos				
						Hrs				
						Enc				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30418 Rev 2		Replacement/ Modification of Electrical Wiring Harness (TT0 Sensor)						RE (-)		Category 6	
	73 ENG2					Mos					
	Eff: 12-May-2016					Hrs					
	(AVG MAN HRS: 2.5)					Enc					
30465 Rev 2		Replacement of Fuel Manifold Tubes						RE (-)		Category 7	
	73 ENG1					Mos					
	Eff: 08-Jul-2016					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30465 Rev 2		Replacement of Fuel Manifold Tubes						RE (-)		Category 7	
	73 ENG2					Mos					
	Eff: 08-Jul-2016					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30474 Rev 2		Replacement/ Modification of Electrical Wiring Harness						RE (-)		Category 7	
	73 ENG1					Mos					
	Eff: 12-May-2016					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30474 Rev 2		Replacement/ Modification of Electrical Wiring Harness						RE (-)		Category 7	
	73 ENG2					Mos					
	Eff: 12-May-2016					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30474 Rev 3		Replacement/ Modification of Electrical Wiring Harness						RE (-)		Category 7	
	73 ENG1					Mos					
	Eff: 16-Oct-2018					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30474 Rev 3		Replacement/ Modification of Electrical Wiring Harness						RE (-)		Category 7	
	73 ENG2					Mos					
	Eff: 16-Oct-2018					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30478 Rev 4		Electronic Engine Control (EEC) - Replacement/Field Modification						RE (-)		Category 3	
	73 ENG1					Mos	09-Sep-2021				
	Eff: 01-Dec-2015 Not Applicable	R2 is c/w				Hrs	2218:31				
	(AVG MAN HRS: 2.5)					Enc	1,685				
30478 Rev 4		Electronic Engine Control (EEC) - Replacement/Field Modification						RE (-)		Category 3	
	73 ENG2					Mos	09-Sep-2021				
	Eff: 01-Dec-2015 Not Applicable	R2 is c/w				Hrs	2218:31				
	(AVG MAN HRS: 2.5)					Enc	1,685				
30504 Rev 2		Replacement of Fuel/Oil Heat Exchanger						RE (-)		Category 7	
	73 ENG1					Mos					
	Eff: 04-Jan-2016					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30504 Rev 2		Replacement of Fuel/Oil Heat Exchanger						RE (-)		Category 7	
	73 ENG2					Mos					
	Eff: 04-Jan-2016					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30504 Rev 3		Replacement of Fuel/Oil Heat Exchanger						RE (-)		Category 7	
	73 ENG1					Mos					
	Eff: 15-Jan-2019					Hrs					
	(AVG MAN HRS: 1.5)					Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30504 Rev 3		Replacement of Fuel/Oil Heat Exchanger						RE (-)		Category 7	
	73 ENG2					Mos					
	Eff: 15-Jan-2019					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30539		Replacement of Fuel Supply Pad						T (-)		Category 7	
	73 ENG1					Mos					
	Eff: 26-Sep-2017					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30539		Replacement of Fuel Supply Pad						T (-)		Category 7	
	73 ENG2					Mos					
	Eff: 26-Sep-2017					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30539 Rev 1		Replacement of Fuel Supply Pad						T (A/R)		Category 7	
	73 ENG1					Mos					
	Eff: 01-Oct-2019					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30539 Rev 1		Replacement of Fuel Supply Pad						T (A/R)		Category 7	
	73 ENG2					Mos					
	Eff: 01-Oct-2019					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
73-00-PW-001		Fuel Metering Unit (FMU) - Overhaul (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO	≈22-Nov-2027	
	73 ENG1					Mos					
	30J3050-03					Hrs		5,500	+100	5500	2183:53 Hrs (+100)
	F82153					Enc					
	(SOURCE: PW545C MM (P/N 30J2302))										
	Note: NOTE: 1. The Fuel Control Unit (FCU) has the same TBO as the engine. If the FCU was replaced since last engine overhaul, at operator discretion, it can continue in service if: (1) The FCU was operating correctly at engine removal for overhaul, (2) The FCU remaining running time allows the engine to reach the next scheduled major maintenance event (preferably HSI)										
	NOTE: 2. Providing the accessory was operating correctly at engine removal, do a general visual inspection. If the accessory is reported as malfunctioning examine and test per CMM.										
	NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.										
73-00-PW-001		Fuel Metering Unit (FMU) - Overhaul (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO	≈22-Nov-2027	
	73 ENG2					Mos					
	30J3050-03					Hrs		5,500	+100	5500	2183:53 Hrs (+100)
	F82112					Enc					
	(SOURCE: PW545C MM (P/N 30J2302))										
	Note: NOTE: 1. The Fuel Control Unit (FCU) has the same TBO as the engine. If the FCU was replaced since last engine overhaul, at operator discretion, it can continue in service if: (1) The FCU was operating correctly at engine removal for overhaul, (2) The FCU remaining running time allows the engine to reach the next scheduled major maintenance event (preferably HSI)										
	NOTE: 2. Providing the accessory was operating correctly at engine removal, do a general visual inspection. If the accessory is reported as malfunctioning examine and test per CMM.										
	NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.										
73-00-PW-002		Fuel to Oil Heat Exchanger - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO	≈22-Nov-2027	
	73 ENG1					Mos					
	31J2955-03					Hrs		5,500	+100	5500	2183:53 Hrs (+100)
	09510997					Enc					
	Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)										

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
73-00-PW-002		Fuel to Oil Heat Exchanger - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
	73 ENG2					Mos					
	31J2955-03					Hrs		5,500	+100	5500	2183:53 Hrs (+100)
	09510998					Enc					
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-003		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
	73 ENG1	No.1				Mos					
	30J2313-02					Hrs		5,500	+100	5500	2183:53 Hrs (+100)
	DEAAA64700					Enc					
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-003		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
	73 ENG2	No.1				Mos					
	30J2313-02					Hrs		5,500	+100	5500	2183:53 Hrs (+100)
	DEAAA63874					Enc					
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-004		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
	73 ENG1	No.2				Mos					
	30J2313-02					Hrs		5,500	+100	5500	2183:53 Hrs (+100)
	DEAAA65358					Enc					
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-004		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
	73 ENG2	No.2				Mos					
	30J2313-02					Hrs		5,500	+100	5500	2183:53 Hrs (+100)
	DEAAA84287					Enc					
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-005		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
	73 ENG1	No.3				Mos					
	30J2313-02					Hrs		5,500	+100	5500	2183:53 Hrs (+100)
	DEAAA65359					Enc					
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-005		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
	73 ENG2	No.3				Mos					
	30J2313-02					Hrs		5,500	+100	5500	2183:53 Hrs (+100)
	DEAAA65362					Enc					
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-006		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
	73 ENG1	No.4				Mos					
	30J2313-02					Hrs		5,500	+100	5500	2183:53 Hrs (+100)
	DEAAA65360					Enc					
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-006		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
	73 ENG2	No.4				Mos					
	30J2313-02					Hrs		5,500	+100	5500	2183:53 Hrs (+100)
	DEAAA65384					Enc					
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									

Task No		Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
73-00-PW-007		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027	
	73 ENG1	No.5				Mos						
	30J2313-02					Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
	DEAAA65361					Enc						
	Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)											
73-00-PW-007		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027	
	73 ENG2	No.5				Mos						
	30J2313-02					Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
	DEAAA85366					Enc						
	Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)											
73-00-PW-008		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027	
	73 ENG1	No.6				Mos						
	30J2313-02					Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
	DEAAA65363					Enc						
	Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)											
73-00-PW-008		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027	
	73 ENG2	No.6				Mos						
	30J2313-02					Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
	DEAAA65368					Enc						
	Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)											
73-00-PW-009		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027	
	73 ENG1	No.7				Mos						
	30J2313-02					Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
	DEAAA65367					Enc						
	Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)											
73-00-PW-009		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027	
	73 ENG2	No.7				Mos						
	30J2313-02					Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
	DEAAA65370					Enc						
	Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)											
73-00-PW-010		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027	
	73 ENG1	No.8				Mos						
	30J2313-02					Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
	DEAAA65371					Enc						
	Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)											
73-00-PW-010		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027	
	73 ENG2	No.8				Mos						
	30J2313-02					Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
	DEAAA65372					Enc						
	Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)											
73-00-PW-011		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027	
	73 ENG1	No.9				Mos						
	30J2313-02					Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
	DEAAA65375					Enc						
	Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)											

Task No		Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE		Remaining
73-00-PW-011		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO			≈22-Nov-2027
	73 ENG2	No.9				Mos						
	30J2313-02					Hrs		5,500	+100	5500		2183:53 Hrs (+100)
	DEAAA65373					Enc						
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-012		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO			≈22-Nov-2027
	73 ENG1	No.10				Mos						
	30J2313-02					Hrs		5,500	+100	5500		2183:53 Hrs (+100)
	DEAAA65376					Enc						
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-012		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO			≈22-Nov-2027
	73 ENG2	No.10				Mos						
	30J2313-02					Hrs		5,500	+100	5500		2183:53 Hrs (+100)
	DEAAA65374					Enc						
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-013		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO			≈22-Nov-2027
	73 ENG1	No.11				Mos						
	30J2313-02					Hrs		5,500	+100	5500		2183:53 Hrs (+100)
	DEAAA65378					Enc						
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-013		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO			≈22-Nov-2027
	73 ENG2	No.11				Mos						
	30J2313-02					Hrs		5,500	+100	5500		2183:53 Hrs (+100)
	DEAAA65377					Enc						
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-015		Fuel Filter Differential Pressure Switch - Examine and functional test (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO			≈22-Nov-2027
	73 ENG1					Mos						
						Hrs		5,500	+100	5500		2183:53 Hrs (+100)
						Enc						
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-015		Fuel Filter Differential Pressure Switch - Examine and functional test (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO			≈22-Nov-2027
	73 ENG2					Mos						
						Hrs		5,500	+100	5500		2183:53 Hrs (+100)
						Enc						
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-016		Fuel Manifold - Inspect/Examine (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO			≈22-Nov-2027
	73 ENG1					Mos						
	Unknown					Hrs		5,500	+100	5500		2183:53 Hrs (+100)
	Unknown					Enc						
		(SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-016		Fuel Manifold - Inspect/Examine (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO			≈22-Nov-2027
	73 ENG2					Mos						
	Unknown					Hrs		5,500	+100	5500		2183:53 Hrs (+100)
	Unknown					Enc						
		(SOURCE: EMM 05-20-00 Par. 3 Table 1)										

Task No		Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE		Remaining
73-00-PW-017		Fuel Filter - Inspect and replace (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO			≈22-Nov-2027
	73 ENG1					Mos						
						Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
		Ref:73-10-05 (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Enc						
73-00-PW-017		Fuel Filter - Inspect and replace (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO			≈22-Nov-2027
	73 ENG2					Mos						
						Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
		Ref:73-10-05 (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Enc						
73-00-PW-018		Fuel Shut-off Cable - Examine per CIR						RE	EMM - Requirement, Extended TBO			≈22-Nov-2027
	73 ENG1 Unknown Unknown					Mos						
						Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
		Ref:CIR Manual P/N 30J2306 (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Enc						
73-00-PW-018		Fuel Shut-off Cable - Examine per CIR						RE	EMM - Requirement, Extended TBO			≈22-Nov-2027
	73 ENG2 Unknown Unknown					Mos						
						Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
		Ref:CIR Manual P/N 30J2306 (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Enc						
73-00-PW-020		Engine Wiring Harness - Examine and do a functional test (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO			≈22-Nov-2027
	73 ENG1 30J2970-06 ADXAX000916					Mos						
						Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Enc						
73-00-PW-020		Engine Wiring Harness - Examine and do a functional test (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO			≈22-Nov-2027
	73 ENG2 30J2970-06 ADXAX000915					Mos						
						Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Enc						
731004-001		Fuel Manifold						RE (O/C)				
	73 ENG1 Unknown Unknown					Mos						
						Hrs						
						Enc						
731004-001		Fuel Manifold						RE (O/C)				
	73 ENG2 Unknown Unknown					Mos						
						Hrs						
						Enc						
731007-001		Fuel Shut-off Cable						RE (O/C)				
	73 ENG1 Unknown Unknown					Mos	29-Oct-2015					
						Hrs	0					
						Enc	0					
731007-001		Fuel Shut-off Cable						RE (O/C)				
	73 ENG2 Unknown Unknown					Mos	29-Oct-2015					
						Hrs	0					
						Enc	0					

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
731007-002		Fuel Shut-off Valve								RE (O/C)		
	73 ENG1						Mos	29-Oct-2015				
	Unknown						Hrs	0				
	Unknown						Enc	0				
731007-002		Fuel Shut-off Valve								RE (O/C)		
	73 ENG2						Mos	29-Oct-2015				
	Unknown						Hrs	0				
	Unknown						Enc	0				
731013-0101		Fuel Manifold Pad								RE (O/C)		
	73 ENG1						Mos	29-Oct-2015				
	Unknown						Hrs	0				
	Unknown						Enc	0				
731013-0101		Fuel Manifold Pad								RE (O/C)		
	73 ENG2						Mos	29-Oct-2015				
	Unknown						Hrs	0				
	Unknown						Enc	0				
73-11-00-201		Fuel Oil Heat Exchanger General Visual Inspection: Do an inspection for security, leakage and general condition.								RE	EMM - Periodic Inspection	≈14-Dec-2025
	73 ENG1	72EH0800					Mos	31-Oct-2024				
							Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
							Enc	2,570				
73-11-00-201		Fuel Oil Heat Exchanger General Visual Inspection: Do an inspection for security, leakage and general condition.								RE	EMM - Periodic Inspection	≈14-Dec-2025
	73 ENG2	72EH0800					Mos	31-Oct-2024				
							Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
							Enc	2,570				
73-11-00-202		Fuel Metering and Control Components General Visual Inspection: Do a check for security, leakage and general condition.								RE	EMM - Periodic Inspection	≈14-Dec-2025
	73 ENG1	72EH0800					Mos	31-Oct-2024				
							Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
							Enc	2,570				
73-11-00-202		Fuel Metering and Control Components General Visual Inspection: Do a check for security, leakage and general condition.								RE	EMM - Periodic Inspection	≈14-Dec-2025
	73 ENG2	72EH0800					Mos	31-Oct-2024				
							Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
							Enc	2,570				
73-11-00-203		External Tubing General Visual Inspection: Examine for signs of wear, chafing, cracks, leaks and corrosion.								RE	EMM - Periodic Inspection	≈14-Dec-2025
	73 ENG1	72EH0800					Mos	31-Oct-2024				
							Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
							Enc	2,570				
73-11-00-203		External Tubing General Visual Inspection: Examine for signs of wear, chafing, cracks, leaks and corrosion.								RE	EMM - Periodic Inspection	≈14-Dec-2025
	73 ENG2	72EH0800					Mos	31-Oct-2024				
							Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
							Enc	2,570				
73-11-00-204		Fuel Distribution (Engine HSI) Special Detailed Inspection: If the engine is Pre-SB30539, replace fuel manifold pad when part has accumulated 7600 cycles.								RE	EMM - Periodic Inspection, Extended HSI	≈31-Oct-2027
	73 ENG1						Mos	03-Oct-2022				
	Unknown						Hrs	2706:58	2,750	+50	5456:58	2140:51 Hrs (+50)
	Unknown						Enc	2,069				
		(SOURCE: PW545C MM 30J2302)										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
73-11-00-204		Fuel Distribution (Engine HSI) Special Detailed Inspection: If the engine is Pre-SB30539, replace fuel manifold pad when part has accumulated 7600 cycles.						RE	EMM - Periodic Inspection, Extended HSI		≈31-Oct-2027
	73 ENG2					Mos	03-Oct-2022				
	Unknown					Hrs	2706:58	2,750	+50	5456:58	2140:51 Hrs (+50)
	Unknown					Enc	2,069				
	(SOURCE: PW545C MM 30J2302)										
73-11-00-204 (Replace)		Fuel Distribution (Engine HSI) Special Detailed Inspection: If the engine is Pre-SB30539, replace fuel manifold pad when part has accumulated 7600 cycles.						RE	EMM - Periodic Inspection		≈04-May-2035
	73 ENG1					Mos					
						Hrs					
						Enc		7,600		7,600	5,024 Enc
73-11-00-204 (Replace)		Fuel Distribution (Engine HSI) Special Detailed Inspection: If the engine is Pre-SB30539, replace fuel manifold pad when part has accumulated 7600 cycles.						RE	EMM - Periodic Inspection		≈04-May-2035
	73 ENG2					Mos					
						Hrs					
						Enc		7,600		7,600	5,024 Enc
73-11-00-205		Fuel Filter Element Detailed Inspection: Do an inspection for foreign material and damage.						RE	EMM - Periodic Inspection		≈14-Dec-2025
	73 ENG1	72EH0800				Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
		Ref:73-10-05-mp				Enc	2,570				
73-11-00-205		Fuel Filter Element Detailed Inspection: Do an inspection for foreign material and damage.						RE	EMM - Periodic Inspection		≈14-Dec-2025
	73 ENG2	72EH0800				Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
		Ref:73-10-05-mp				Enc	2,570				
73-11-00-206		Emergency Fuel Shutoff System Detailed Inspection: Do an inspection through hole in the exhaust cone and check for- Security of control lever- Signs of oil leaks or carbon at No.5 bearing area. Do an inspection of cable and linkages.						RE	EMM - Periodic Inspection		≈14-Dec-2025
	73 ENG1	72EH0800				Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
						Enc	2,570				
73-11-00-206		Emergency Fuel Shutoff System Detailed Inspection: Do an inspection through hole in the exhaust cone and check for- Security of control lever- Signs of oil leaks or carbon at No.5 bearing area. Do an inspection of cable and linkages.						RE	EMM - Periodic Inspection		≈14-Dec-2025
	73 ENG2	72EH0800				Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
						Enc	2,570				
73-11-00-701		Emergency Fuel Shutoff System Operational Check: Removal/Adjustment & Installation (Ref. 73-10-07, EMERGENCY FUEL SHUT-OFF - MAINTENANCE PRACTICES).						RE	EMM - Periodic Inspection, Extended HSI		≈22-Nov-2027
	73 ENG1					Mos	03-Oct-2022				
						Hrs	2706:58	2,750	+50	5500	2183:53 Hrs (+50)
		(Tol. Adjustment: 43 Hrs) (SOURCE: PW545C MM 30J2302)				Enc	2,069				
73-11-00-701		Emergency Fuel Shutoff System Operational Check: Removal/Adjustment & Installation (Ref. 73-10-07, EMERGENCY FUEL SHUT-OFF - MAINTENANCE PRACTICES).						RE	EMM - Periodic Inspection, Extended HSI		≈22-Nov-2027
	73 ENG2					Mos	03-Oct-2022				
						Hrs	2706:58	2,750	+50	5500	2183:53 Hrs (+50)
		(Tol. Adjustment: 43 Hrs) (SOURCE: PW545C MM 30J2302)				Enc	2,069				
73-11-00-901		Fuel Filter Element Discard: Install the new fuel filter element.						RE	EMM - Periodic Inspection		≈23-Feb-2026
	73 ENG1					Mos	09-Oct-2023				
						Hrs	3048:30	1,200	-/+25	4248:30	932:23 Hrs (+25)
		Ref:73-10-05-mp (UPDATE NOTE: WO: 101042304)				Enc	2,362				
73-11-00-901		Fuel Filter Element Discard: Install the new fuel filter element.						RE	EMM - Periodic Inspection		≈23-Feb-2026
	73 ENG2					Mos	09-Oct-2023				
						Hrs	3048:30	1,200	-/+25	4248:30	932:23 Hrs (+25)
		Ref:73-10-05-mp (UPDATE NOTE: WO: 101042303)				Enc	2,362				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
73-11-00-902	Fuel Distribution (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈22-Nov-2027
 73 ENG1					Mos					
					Hrs		5,500	+50	5500	2183:53 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)				Enc					
73-11-00-902	Fuel Distribution (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈22-Nov-2027
 73 ENG2					Mos					
					Hrs		5,500	+50	5500	2183:53 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)				Enc					
732002	Electrical Wiring Harness						RE (O/C)			
 73 ENG1		0			Mos	29-Oct-2015				
	30J2970-06	0			Hrs	0				
	ADXAX000916	0			Enc	0				
732002	Electrical Wiring Harness						RE (O/C)			
 73 ENG2		0			Mos	29-Oct-2015				
	30J2970-06	0			Hrs	0				
	ADXAX000915	0			Enc	0				
73-21-00-201	Engine Wiring Harness General Visual Inspection: Do a check for security of all clamps and brackets. Examine the cables for sign of wear, fraying, chafing and cracks. Do a check for security of all wiring harness connectors. Examine the outer surfaces for cracks and corrosion. For Pre-SB30393 Engine: Do a visual inspection of the EEC support beams, and the five support brackets for crack indications. (Ref. 73-20-03, EEC-MAINTENANCE PRACTICES, INSPECTION). For Post-SB30393 Engine: No action is necessary.						RE	EMM - Periodic Inspection		≈14-Dec-2025
 73 ENG1	72EH0800				Mos	31-Oct-2024				
					Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
	Ref:73-20-03-mp (SOURCE: PW545C MM (P/N 30J2302))				Enc	2,570				
73-21-00-201	Engine Wiring Harness General Visual Inspection: Do a check for security of all clamps and brackets. Examine the cables for sign of wear, fraying, chafing and cracks. Do a check for security of all wiring harness connectors. Examine the outer surfaces for cracks and corrosion. For Pre-SB30393 Engine: Do a visual inspection of the EEC support beams, and the five support brackets for crack indications. (Ref. 73-20-03, EEC-MAINTENANCE PRACTICES, INSPECTION). For Post-SB30393 Engine: No action is necessary.						RE	EMM - Periodic Inspection		≈14-Dec-2025
 73 ENG2	72EH0800				Mos	31-Oct-2024				
					Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
	Ref:73-20-03-mp (SOURCE: PW545C MM (P/N 30J2302))				Enc	2,570				
73-21-00-901	Engine Wiring Harness (Cleaning) Restoration: Disconnect each wiring harness connector, clean, inspect (Ref. 73-20-02, ELECTRICAL HARNESS - MAINTENANCE PRACTICES). Do the necessary engine checks after wiring harness replacement. For Pre-SB30434 Engine: Perform an EEC/DCU download (Ref: 72-00-01, ELECTRONIC ENGINE CONTROL - FAULT ISOLATION). Review download for fault codes 112 (T6 fault) and 252 (EEC overtemperature fault). If found recorded, proceed with fault isolation chart (Ref: 72-00-01, ELECTRONIC ENGINE CONTROL - FAULT ISOLATION). For Post-SB30434 Engine: No action is necessary.						RE	EMM - Periodic Inspection		≈14-Dec-2025
 73 ENG1	72EH0800				Mos	31-Oct-2024				
					Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
	Ref:73-20-02-mp (SOURCE: PW545C MM 30J2302)				Enc	2,570				
73-21-00-901	Engine Wiring Harness (Cleaning) Restoration: Disconnect each wiring harness connector, clean, inspect (Ref. 73-20-02, ELECTRICAL HARNESS - MAINTENANCE PRACTICES). Do the necessary engine checks after wiring harness replacement. For Pre-SB30434 Engine: Perform an EEC/DCU download (Ref: 72-00-01, ELECTRONIC ENGINE CONTROL - FAULT ISOLATION). Review download for fault codes 112 (T6 fault) and 252 (EEC overtemperature fault). If found recorded, proceed with fault isolation chart (Ref: 72-00-01, ELECTRONIC ENGINE CONTROL - FAULT ISOLATION). For Post-SB30434 Engine: No action is necessary.						RE	EMM - Periodic Inspection		≈14-Dec-2025
 73 ENG2	72EH0800				Mos	31-Oct-2024				
					Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
	Ref:73-20-02-mp (SOURCE: PW545C MM 30J2302)				Enc	2,570				
73-21-00-902	Fuel Controlling (Engine TBO) Restoration: Refer to Para. 3.						RE	EMM - Periodic Inspection, Extended TBO		≈22-Nov-2027
 73 ENG1					Mos					
					Hrs		5,500	+50	5500	2183:53 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)				Enc					

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
73-21-00-902	Fuel Controlling (Engine TBO) Restoration: Refer to Para. 3.						RE	EMM - Periodic Inspection, Extended TBO		≈22-Nov-2027
 73 ENG2					Mos					
					Hrs		5,500	+50	5500	2183:53 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)				Enc					
SL560XL-73-06	Transmittal of ELDEC Corporation Service Letter SL9-231-73-04, Shipping Instructions for the 9-231-28 Fuel Flow Transmitters						T (A/R)		Informational	
 73 A/F					Mos					
	Eff: 21-Jun-2005				Hrs					
					Ldg					
SL560XL-73-07	Transmittal of Pratt & Whitney Canada (P&WC) Service Bulletin 30197R4, Turbofan Engine New Fuel Manifold - Introduction Of						RE (-)		Optional	
 73 A/F					Mos					
					Hrs					
					Ldg					
SL560XL-73-07 Rev 01	Transmittal of Pratt & Whitney Canada (P&WC) Service Bulletin 30197R4, Turbofan Engine New Fuel Manifold - Introduction Of						RE (-)		Optional	
 73 A/F					Mos					
					Hrs					
					Ldg					
SL560XL-73-07 Rev 02	Transmittal of Pratt & Whitney Canada (P&WC) Service Bulletin 30197R4, Turbofan Engine New Fuel Manifold - Introduction Of						T (A/R)		Informational	
 73 A/F					Mos					
	Eff: 02-Jul-2007				Hrs					
					Ldg					
▼ 74 - IGNITION										
	Ignition Exciter						RE (O/C)			
 74 ENG1		0			Mos	29-Oct-2015				
	31J2807-07	0			Hrs	0				
	NNA15260117	0			Enc	0				
	New									
	Ignition Exciter						RE (O/C)			
 74 ENG2		0			Mos	29-Oct-2015				
	31J2807-07	0			Hrs	0				
	NNA15260002	0			Enc	0				
	New									
	Inboard Ignitor						RE (O/C)			
 74 ENG1		0			Mos	29-Oct-2015				
	502600-1	0			Hrs	0				
	NSN	0			Enc	0				
	New									
	Inboard Ignitor						RE (O/C)			
 74 ENG2		0			Mos	29-Oct-2015				
	502600-1	0			Hrs	0				
	NSN	0			Enc	0				
	New									
	Long Ignitor Lead						RE (O/C)			
 74 ENG1		0			Mos	29-Oct-2015				
	30J3125-02	0			Hrs	0				
	NNA15130217	0			Enc	0				
	New									
	Long Ignitor Lead						RE (O/C)			
 74 ENG2					Mos	24-Jan-2024				
	30J4167	0			Hrs	3130:01				
	NNAS22370004	0			Enc	2,424				
	New									

Task No	Description								Categories	Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
		Outboard Ignitor								RE (O/C)		
	74 ENG1	New	0			Mos	29-Oct-2015					
	502600-1		0			Hrs		0				
	NSN		0			Enc		0				
		Outboard Ignitor								RE (O/C)		
	74 ENG2	New	0			Mos	29-Oct-2015					
	502600-1		0			Hrs		0				
	NSN		0			Enc		0				
		Short Ignitor Lead								RE (O/C)		
	74 ENG1	New	0			Mos	29-Oct-2015					
	30J3125-01		0			Hrs		0				
	NNA15110123		0			Enc		0				
		Short Ignitor Lead								RE (O/C)		
	74 ENG2	New	0			Mos	29-Oct-2015					
	30J3125-01		0			Hrs		0				
	NNA15140253		0			Enc		0				
30542	Replacement of Igniter Cables									T (A/R)	Category 7	
	74 ENG1	Eff: 25-Apr-2018 (AVG MAN HRS: 1.5) Note: CONCURRENT REQUIRMENTS				Mos						
						Hrs						
						Enc						
30542	Replacement of Igniter Cables									T (A/R)	Category 7	
	74 ENG2	Eff: 25-Apr-2018 (AVG MAN HRS: 1.5) Note: CONCURRENT REQUIRMENTS				Mos						
						Hrs						
						Enc						
74-00-PW-001	Ignition Exciter Box - Clean and Examine (at Engine Overhaul)									RE	EMM - Requirement, Extended TBO	≈22-Nov-2027
	74 ENG1	31J2807-07 NNA15260117 Ref:74-10-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Mos						
						Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
						Enc						
74-00-PW-001	Ignition Exciter Box - Clean and Examine (at Engine Overhaul)									RE	EMM - Requirement, Extended TBO	≈22-Nov-2027
	74 ENG2	31J2807-07 NNA15260002 Ref:74-10-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Mos						
						Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
						Enc						
74-00-PW-002	Ignition Cable - Examine (at Engine Overhaul)									RE	EMM - Requirement, Extended TBO	≈22-Nov-2027
	74 ENG1	Inboard Unknown Unknown Ref:74-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Mos						
						Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
						Enc						
74-00-PW-002	Ignition Cable - Examine (at Engine Overhaul)									RE	EMM - Requirement, Extended TBO	≈22-Nov-2027
	74 ENG2	Inboard Unknown Unknown Ref:74-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Mos						
						Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
						Enc						

Task No		Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
74-00-PW-003		Ignition Cable - Examine (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
	74 ENG1	Outboard				Mos						
	Unknown					Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
	Unknown					Enc						
	Ref:74-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)											
74-00-PW-003		Ignition Cable - Examine (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
	74 ENG2	Outboard				Mos						
	Unknown					Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
	Unknown					Enc						
	Ref:74-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)											
74-00-PW-004		Inboard Ignition Plug - Examine (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
	74 ENG1					Mos						
	502600-1					Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
	NSN					Enc						
	Ref:74-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)											
74-00-PW-004		Inboard Ignition Plug - Examine (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
	74 ENG2					Mos						
	502600-1					Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
	NSN					Enc						
	Ref:74-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)											
74-00-PW-005		Outboard Ignition Plug - Examine (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
	74 ENG1					Mos						
	502600-1					Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
	NSN					Enc						
	Ref:74-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)											
74-00-PW-005		Outboard Ignition Plug - Examine (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
	74 ENG2					Mos						
	502600-1					Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
	NSN					Enc						
	Ref:74-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)											
741001-001		Cable Ignition Exciter to Igniter						RE (O/C)				
	74 ENG1	Inboard				Mos	29-Oct-2015					
	Unknown					Hrs		0				
	Unknown					Enc		0				
741001-001		Cable Ignition Exciter to Igniter						RE (O/C)				
	74 ENG2	Inboard				Mos	29-Oct-2015					
	Unknown					Hrs		0				
	Unknown					Enc		0				
741001-002		Cable Ignition Exciter to Igniter						RE (O/C)				
	74 ENG1	Outboard				Mos	29-Oct-2015					
	Unknown					Hrs		0				
	Unknown					Enc		0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
741001-002	74 ENG2 Unknown Unknown	Cable Ignition Exciter to Igniter Outboard								RE (O/C)	
							Mos	29-Oct-2015			
							Hrs	0			
							Enc	0			
74-20-00-201	74 ENG1	Ignition Exciter General Visual Inspection: Do a check for security and general condition. 72EH0800					Mos	31-Oct-2024	RE	EMM - Periodic Inspection	≈14-Dec-2025
							Hrs	3308:54	800	-/+25 (4108:54)	792:47 Hrs (+25)
							Enc	2,570			
74-20-00-201	74 ENG2	Ignition Exciter General Visual Inspection: Do a check for security and general condition. 72EH0800					Mos	31-Oct-2024	RE	EMM - Periodic Inspection	≈14-Dec-2025
							Hrs	3308:54	800	-/+25 (4108:54)	792:47 Hrs (+25)
							Enc	2,570			
74-20-00-204	74 ENG1 (SOURCE: PW545C MM 30J2302)	Igniters (Tip Measurement) Functional Check: Do a check for cleanliness and measure erosion. (Ref. 74-20-02, SPARK IGNITERS - MAINTENANCE PRACTICES). 72EH0800					Mos	31-Oct-2024	RE	EMM - Periodic Inspection	≈14-Dec-2025
							Hrs	3308:54	800	-/+25 (4108:54)	792:47 Hrs (+25)
							Enc	2,570			
74-20-00-204	74 ENG2 (SOURCE: PW545C MM 30J2302)	Igniters (Tip Measurement) Functional Check: Do a check for cleanliness and measure erosion. (Ref. 74-20-02, SPARK IGNITERS - MAINTENANCE PRACTICES). 72EH0800					Mos	31-Oct-2024	RE	EMM - Periodic Inspection	≈14-Dec-2025
							Hrs	3308:54	800	-/+25 (4108:54)	792:47 Hrs (+25)
							Enc	2,570			
74-20-00-205	74 ENG1	Ignition Cables General Visual Inspection: Do a check for chafing, wear and security. 72EH0800					Mos	31-Oct-2024	RE	EMM - Periodic Inspection	≈14-Dec-2025
							Hrs	3308:54	800	-/+25 (4108:54)	792:47 Hrs (+25)
							Enc	2,570			
74-20-00-205	74 ENG2	Ignition Cables General Visual Inspection: Do a check for chafing, wear and security. 72EH0800					Mos	31-Oct-2024	RE	EMM - Periodic Inspection	≈14-Dec-2025
							Hrs	3308:54	800	-/+25 (4108:54)	792:47 Hrs (+25)
							Enc	2,570			
74-20-00-206	74 ENG1 (SOURCE: PW545C MM 30J2302)	Ignition (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).					Mos	03-Oct-2022	RE	EMM - Periodic Inspection, Extended HSI	≈31-Oct-2027
							Hrs	2706:58	2,750	+50 5456:58	2140:51 Hrs (+50)
							Enc	2,069			
74-20-00-206	74 ENG2 (SOURCE: PW545C MM 30J2302)	Ignition (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).					Mos	03-Oct-2022	RE	EMM - Periodic Inspection, Extended HSI	≈31-Oct-2027
							Hrs	2706:58	2,750	+50 5456:58	2140:51 Hrs (+50)
							Enc	2,069			
74-20-00-701	74 ENG1	Igniters Operational Check: Do an operational test (Ref. 74-10-01, IGNITION SYSTEM - MAINTENANCE PRACTICES). 72EH0800					Mos	31-Oct-2024	RE	EMM - Periodic Inspection	≈14-Dec-2025
							Hrs	3308:54	800	-/+25 (4108:54)	792:47 Hrs (+25)
							Enc	2,570			
74-20-00-701	74 ENG2	Igniters Operational Check: Do an operational test (Ref. 74-10-01, IGNITION SYSTEM - MAINTENANCE PRACTICES). 72EH0800					Mos	31-Oct-2024	RE	EMM - Periodic Inspection	≈14-Dec-2025
							Hrs	3308:54	800	-/+25 (4108:54)	792:47 Hrs (+25)
							Enc	2,570			

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
74-20-00-901		Ignition (Engine TBO) Restoration: Do the engine restoration at an approved facility (Ref. Para. 3.).							RE	EMM - Periodic Inspection, Extended TBO		≈22-Nov-2027
	74 ENG1						Mos					
							Hrs	5,500	+50	5500	2183:53 Hrs (+50)	
	(SOURCE: PW545C MM 30J2302)						Enc					
74-20-00-901		Ignition (Engine TBO) Restoration: Do the engine restoration at an approved facility (Ref. Para. 3.).							RE	EMM - Periodic Inspection, Extended TBO		≈22-Nov-2027
	74 ENG2						Mos					
							Hrs	5,500	+50	5500	2183:53 Hrs (+50)	
	(SOURCE: PW545C MM 30J2302)						Enc					
▼ 75 - BLEED AIR												
		Bleed Servo Valve					RE (O/C)					
	75 ENG1		0				Mos	29-Jul-2021				
	30J4133-01	New	0				Hrs	2169:34				
	TRAXY000020		0				Enc	1,654				
		Bleed Servo Valve					RE (O/C)					
	75 ENG2						Mos	03-Oct-2022				
	30J4133-01						Hrs	2706:58				
	TRAXY000624						Enc	2,069				
		Compressor Bleed Valve Assy					RE (O/C)					
	75 ENG1		0				Mos	29-Oct-2015				
	30J2954-01	New	0				Hrs	0				
	AHX2100222		0				Enc	0				
		Compressor Bleed Valve Assy					RE (O/C)					
	75 ENG2		0				Mos	29-Oct-2015				
	30J2954-01	New	0				Hrs	0				
	AHX2100228		0				Enc	0				
		Linear Transducer					RE (O/C)					
	75 ENG1		0				Mos	29-Oct-2015				
	30J3053-01	New	0				Hrs	0				
	1481		0				Enc	0				
		Linear Transducer					RE (O/C)					
	75 ENG2		0				Mos	29-Oct-2015				
	30J3053-01	New	0				Hrs	0				
	1482		0				Enc	0				
30548		Replacement/Modification of Anti-Icing Valve					T (-)		Category 7			
	75 ENG1						Mos					
	Eff: 03-Jul-2018						Hrs					
	(AVG MAN HRS: 1)						Enc					
30548		Replacement/Modification of Anti-Icing Valve					T (-)		Category 7			
	75 ENG2						Mos					
	Eff: 03-Jul-2018						Hrs					
	(AVG MAN HRS: 1)						Enc					
30548 R1		Replacement/Modification of Anti-Icing Valve					T (-)		Category 7			
	75 ENG1						Mos					
	Eff: 05-Sep-2018						Hrs					
	(AVG MAN HRS: 1)						Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30548 R1		Replacement/Modification of Anti-Icing Valve						T (-)		Category 7	
	75 ENG2					Mos					
	Eff: 05-Sep-2018					Hrs					
	(AVG MAN HRS: 1)					Enc					
30548 R2		Replacement/Modification of Anti-Icing Valve						T (A/R)		Category 7	
	75 ENG1					Mos					
	Eff: 21-Sep-2018					Hrs					
	(AVG MAN HRS: 1)					Enc					
30548 R2		Replacement/Modification of Anti-Icing Valve						T (A/R)		Category 7	
	75 ENG2					Mos					
	Eff: 21-Sep-2018					Hrs					
	(AVG MAN HRS: 1)					Enc					
30554 Rev 1		Replacement of Intercompressor Bleed Valve/ Servo-Valve						T (-)		Category 7	
	75 ENG1					Mos					
	Eff: 03-Mar-2021					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
	Note: EFFECTIVITY: PW535E (BS1229, BS1348) Post-SB30558 engines converted to PW535E1.										
30554 Rev 1		Replacement of Intercompressor Bleed Valve/ Servo-Valve						T (-)		Category 7	
	75 ENG2					Mos					
	Eff: 03-Mar-2021					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
	Note: EFFECTIVITY: PW535E (BS1229, BS1348) Post-SB30558 engines converted to PW535E1.										
30554 Rev 2		Replacement of Intercompressor Bleed Valve/ Servo-Valve						T (A/R)		Category 7	
	75 ENG1					Mos					
	Eff: 26-Oct-2021					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30554 Rev 2		Replacement of Intercompressor Bleed Valve/ Servo-Valve						T (A/R)		Category 7	
	75 ENG2					Mos					
	Eff: 26-Oct-2021					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
75-00-PW-001		FADEC (EEC) - Inspection (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO	≈22-Nov-2027	
	75 ENG1					Mos					
						Hrs	5,500	+100	5500	2183:53 Hrs (+100)	
	(SOURCE: EMM 05-20-00 Par. 3 Table 1)					Enc					
75-00-PW-001		FADEC (EEC) - Inspection (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO	≈22-Nov-2027	
	75 ENG2					Mos					
						Hrs	5,500	+100	5500	2183:53 Hrs (+100)	
	(SOURCE: EMM 05-20-00 Par. 3 Table 1)					Enc					
75-00-PW-002		Anti-Icing Valve - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO	≈22-Nov-2027	
	75 ENG1					Mos					
	31J2879-05					Hrs	5,500	+50	5500	2183:53 Hrs (+50)	
	5124					Enc					
	(SOURCE: EMM 05-20-00 Par. 3 Table 1)										
75-00-PW-002		Anti-Icing Valve - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO	≈22-Nov-2027	
	75 ENG2					Mos					
	31J2879-05					Hrs	5,500	+50	5500	2183:53 Hrs (+50)	
	5128					Enc					
	(SOURCE: EMM 05-20-00 Par. 3 Table 1)										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
75-00-PW-003	P3 Air Inertial Separator - Inspect/Examine (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
 75 ENG1						Mos				
Unknown						Hrs	5,500	+100	5500	2183:53 Hrs (+100)
Unknown						Enc				
Ref:75-30-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
75-00-PW-003	P3 Air Inertial Separator - Inspect/Examine (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
 75 ENG2						Mos				
Unknown						Hrs	5,500	+100	5500	2183:53 Hrs (+100)
Unknown						Enc				
Ref:75-30-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
75-00-PW-005	BOV Torque Motor - Replace with new (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
 75 ENG1						Mos				
30J2954-01						Hrs	5,500	+100	5500	2183:53 Hrs (+100)
AHX2100222						Enc				
(SOURCE: EMM 05-20-00 Par. 3 Table 1)										
75-00-PW-005	BOV Torque Motor - Replace with new (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
 75 ENG2						Mos				
30J2954-01						Hrs	5,500	+100	5500	2183:53 Hrs (+100)
AHX2100228						Enc				
(SOURCE: EMM 05-20-00 Par. 3 Table 1)										
75-00-PW-005	Compressor Air Bleed Valve - Inspection (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
 75 ENG1						Mos				
30J2954-01						Hrs	5,500	+100	5500	2183:53 Hrs (+100)
AHX2100222						Enc				
Ref:CIR (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
75-00-PW-005	Compressor Air Bleed Valve - Inspection (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
 75 ENG2						Mos				
30J2954-01						Hrs	5,500	+100	5500	2183:53 Hrs (+100)
AHX2100228						Enc				
Ref:CIR (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
75-00-PW-006	Linear Variable Differential Transformer (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
 75 ENG1						Mos				
						Hrs	5,500	+100	5500	2183:53 Hrs (+100)
(SOURCE: EMM 05-20-00 Par. 3 Table 1)										
75-00-PW-006	Linear Variable Differential Transformer (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
 75 ENG2						Mos				
						Hrs	5,500	+100	5500	2183:53 Hrs (+100)
(SOURCE: EMM 05-20-00 Par. 3 Table 1)										
75-10-00-201	Anti-ice Valve and P3 Anti-ice Tube (Leak Check) General Visual Inspection: Do a check for leakage at P3 air supply to bleed valve, ant-ice valve, anti-ice air tube and FCU.						RE	EMM - Periodic Inspection		≈14-Dec-2025
 75 ENG1	72EH0800					Mos	31-Oct-2024			
						Hrs	3308:54	800	-/+25	(4108:54) 792:47 Hrs (+25)
						Enc	2,570			

OK-ECR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-ECR,SN 560-6198

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
75-10-00-201		Anti-ice Valve and P3 Anti-ice Tube (Leak Check) General Visual Inspection: Do a check for leakage at P3 air supply to bleed valve, ant-ice valve, anti-ice air tube and FCU.						RE	EMM - Periodic Inspection		≈14-Dec-2025
	75 ENG2	72EH0800				Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
						Enc	2,570				
75-10-00-202		P3 Bellows Seal and Bleed Air Transfer Tube General Visual Inspection: Do a visual inspection for air leak.						RE	EMM - Periodic Inspection		≈14-Dec-2025
	75 ENG1	72EH0800				Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
						Enc	2,570				
75-10-00-202		P3 Bellows Seal and Bleed Air Transfer Tube General Visual Inspection: Do a visual inspection for air leak.						RE	EMM - Periodic Inspection		≈14-Dec-2025
	75 ENG2	72EH0800				Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
						Enc	2,570				
75-10-00-203		Bleed Off Valve General Visual Inspection: Examine the torque motor electrical connection for security, fraying and corrosion. NOTE: If Pre-SB30420 intercompressor bleed valve servo valve, then replace it with Post-SB30420 configuration.						RE	EMM - Periodic Inspection		≈14-Dec-2025
	75 ENG1	72EH0800				Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
						Enc	2,570				
75-10-00-203		Bleed Off Valve General Visual Inspection: Examine the torque motor electrical connection for security, fraying and corrosion. NOTE: If Pre-SB30420 intercompressor bleed valve servo valve, then replace it with Post-SB30420 configuration.						RE	EMM - Periodic Inspection		≈14-Dec-2025
	75 ENG2	72EH0800				Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
						Enc	2,570				
75-10-00-204		Air System (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈31-Oct-2027
	75 ENG1					Mos	03-Oct-2022				
	(SOURCE: PW545C MM 30J2302)					Hrs	2706:58	2,750	+50	5456:58	2140:51 Hrs (+50)
						Enc	2,069				
75-10-00-204		Air System (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈31-Oct-2027
	75 ENG2					Mos	03-Oct-2022				
	(SOURCE: PW545C MM 30J2302)					Hrs	2706:58	2,750	+50	5456:58	2140:51 Hrs (+50)
						Enc	2,069				
75-10-00-901		Air System (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈22-Nov-2027
	75 ENG1					Mos					
	(SOURCE: PW545C MM 30J2302)					Hrs		5,500	+50	5500	2183:53 Hrs (+50)
						Enc					
75-10-00-901		Air System (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈22-Nov-2027
	75 ENG2					Mos					
	(SOURCE: PW545C MM 30J2302)					Hrs		5,500	+50	5500	2183:53 Hrs (+50)
						Enc					
753001-001		P3 Air Inertial Separator						RE (O/C)			
	75 ENG1					Mos	29-Oct-2015				
	Unknown					Hrs	0				
	Unknown					Enc	0				
753001-001		P3 Air Inertial Separator						RE (O/C)			
	75 ENG2					Mos	29-Oct-2015				
	Unknown					Hrs	0				
	Unknown					Enc	0				

Task No	Description		TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition								DUE	Remaining
▼ 76 - ENGINE CONTROLS											
	76 ENG1 30J3051-08 2015040014	Electronic Engine Control						RE (O/C)			
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Enc	0				
	76 ENG2 30J3051-08 2015040012	Electronic Engine Control						RE (O/C)			
		New	0			Mos	29-Oct-2015				
			0			Hrs	0				
			0			Enc	0				
	76 A/F Unknown Unknown	Throttle Bank Switch						RE (O/C)			
		Left				Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	76 A/F Unknown Unknown	Throttle Bank Switch						RE (O/C)			
		Right				Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	76 A/F Unknown Unknown	Throttle Detent Valve						RE (O/C)			
		Left				Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
	76 A/F Unknown Unknown	Throttle Detent Valve						RE (O/C)			
		Right				Mos	29-Oct-2015				
						Hrs	0				
						Ldg	0				
2020-26-05	Power Lever - Throttle Quadrant Inspection						RE (-)		Mandatory		
	76 A/F Eff: 17-Dec-2020 Complied With (ISSUING AUTHORITY: FAA) Note: "Within 50 hours time-in-service after the effective date of this AD, inspect the rivet in the left and right throttle quadrant assembly sensor link and sensor drive arm pivot for correct installation..."					Mos	31-Dec-2020				
						Hrs	2086				
					Ldg	1,594					
4-50-00-7100	Time Limited Dispatch Fault Visual Check						RE (N/A)		Airworthiness Limitations Inspection Time Limits		
	76 A/F (ZONE: 247) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Mos	03-Oct-2022				
						Hrs	2706:58				
					Ldg	2,069					
560XL-76-04	Transmittal of Pratt & Whitney Canada (P&WC) Service Bulletin 30434 Turbofan Engine - Electronic Engine Control/Replacement-Modification and P&WC Service Bulletin 30438 Turbofan Engine Electronic Engine Control (EEC) - Replacement/Modifications Of						RE (-)		Recommended		
	76 A/F Eff: 07-Sep-2011 Complied With					Mos	31-Dec-2020				
						Hrs					
					Ldg						
76-10-00-7200	Left Fuel Control Unit Throttle Lever Cutoff Functional Check (Airplanes -5001 thru -5196 Not Incorporating SB560XL-76-03)						RE (N/A)		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	76 A/F (ZONE: 410) (SOURCE: 560 XL MM Section 5-10-02)					Mos					
						Hrs					
					Ldg						

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
76-10-00-7200		Right Fuel Control Unit Throttle Lever Cutoff Functional Check (Airplanes -5001 thru -5196 Not Incorporating SB560XL-76-03)							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	76 A/F						Mos					
							Hrs					
	(ZONE: 420) (SOURCE: 560 XL MM Section 5-10-02)						Ldg					
76-10-00-7201		Left Fuel Control Unit Throttle Lever Cutoff Functional Check (Airplanes -5197 thru -6000, and Airplanes -5001 thru -5196 Incorporating SB560XL-76-03)							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	76 A/F						Mos					
							Hrs					
	(ZONE: 410) (SOURCE: 560 XL MM Section 5-10-02)						Ldg					
76-10-00-7201		Right Fuel Control Unit Throttle Lever Cutoff Functional Check (Airplanes -5197 thru -6000, and Airplanes -5001 thru -5196 Incorporating SB560XL-76-03)							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	76 A/F						Mos					
							Hrs					
	(ZONE: 420) (SOURCE: 560 XL MM Section 5-10-02)						Ldg					
SL560XL-76-03		Transmittal of Pratt & Whitney Canada Service Bulletin 30438 Turbofan Electronic Engine Control (EEC) - Replacement/Modifications of							RE (-)	Discretionary		
	76 A/F						Mos	14-Sep-2021				
	Not Applicable	different SN of aircraft					Hrs					
							Ldg					
SL560XL-76-03 Rev 02		Transmittal of Pratt & Whitney Canada Service Bulletin 30438 Turbofan Electronic Engine Control (EEC) - Replacement/Modifications of							RE (-)	Recommended		
	76 A/F						Mos	14-Sep-2021				
	Eff: 25-Sep-2015 Not Applicable	different SN of aircraft					Hrs					
	(AVG MAN HRS: 2.5)						Ldg					
SL560XL-76-03 Rev 1		Transmittal of Pratt & Whitney Canada Service Bulletin 30438 Turbofan Electronic Engine Control (EEC) - Replacement/Modifications of							RE (-)	Recommended		
	76 A/F						Mos	14-Sep-2021				
	Eff: 13-Sep-2011 Not Applicable	different SN of aircraft					Hrs					
							Ldg					
SL560XL-76-04		Engine Controls - Throttle Quadrant RVDT Linkage Inspection							RE (-)	Mandatory		
	76 A/F						Mos	09-Sep-2021				
	Eff: 12-Nov-2020 Superseded R1 is c/w						Hrs	2218:31				
	(AVG MAN HRS: 6)						Ldg	1,685				
Note: COMPLIANCE: This service document must be accomplished within the next Time Limited Dispatch Check not to exceed 170 airplane hours or 6 months from the date of receipt, whichever occurs first.												
SL560XL-76-04 R1		Engine Controls - Throttle Quadrant RVDT Linkage Inspection							RE (-)	Mandatory		
	76 A/F						Mos	31-Dec-2020				
	Eff: 24-Nov-2020 Complied With						Hrs	2086:50				
	(AVG MAN HRS: 6)						Ldg	1,594				
Note: COMPLIANCE: This service document must be accomplished within the next Time Limited Dispatch Check not to exceed 170 airplane hours or 6 months from the date of receipt, whichever occurs first.												
SL560XL-76-05		Engine Controls - Inspection of the Right Engine Throttle Quadrant Rotary Variable Differential Transformer (RVDT) Electrical Wiring							RE (-)	Mandatory		
	76 A/F						Days	27-Jun-2023				
	Eff: 06-Feb-2023 Complied With						Hrs	3038:01				
	(AVG MAN HRS: 45)						Ldg	2,352				
Note: COMPLIANCE: MANDATORY. This service document must be accomplished within 150.0 flight hours or 180 days from the date of receipt, whichever occurs first.												
▼ 77 - ENGINE INDICATING												
Data Collection Unit									RE (O/C)			
	77 ENG1						0	Mos	29-Oct-2015			
	30J3470-01	New					0	Hrs	0			
	15031281						0	Enc	0			

Task No	Description										Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL		DUE	Remaining
 77 ENG2 30J3470-01 15031430		New	0			Mos	29-Oct-2015					
			0			Hrs	0					
			0			Enc	0					
 77 A/F Unknown Unknown						Mos	29-Oct-2015					
						Hrs	0					
						Ldg	0					
 77 A/F 10677N02M01 0746A		New	0			Mos	29-Oct-2015					
			0			Hrs	0					
			0			Ldg	0					
30534	Replacement of Data Collection Unit							T (-)			Category 7	
 77 ENG1 Eff: 28-Mar-2017 (AVG MAN HRS: 1.5)						Mos						
						Hrs						
						Enc						
30534	Replacement of Data Collection Unit							T (-)			Category 7	
 77 ENG2 Eff: 28-Mar-2017 (AVG MAN HRS: 1.5)						Mos						
						Hrs						
						Enc						
30534 Rev 1	Replacement of Data Collection Unit							T (-)			Category 7	
 77 ENG1 Eff: 23-May-2017 (AVG MAN HRS: 1.5)						Mos						
						Hrs						
						Enc						
30534 Rev 1	Replacement of Data Collection Unit							T (-)			Category 7	
 77 ENG2 Eff: 23-May-2017 (AVG MAN HRS: 1.5)						Mos						
						Hrs						
						Enc						
30534 Rev 2	Replacement of Data Collection Unit							T (-)			Category 7	
 77 ENG1 Eff: 31-Oct-2017 (AVG MAN HRS: 1.5)						Mos						
						Hrs						
						Enc						
30534 Rev 2	Replacement of Data Collection Unit							T (-)			Category 7	
 77 ENG2 Eff: 31-Oct-2017 (AVG MAN HRS: 1.5)						Mos						
						Hrs						
						Enc						
30534 Rev 3	Replacement of Data Collection Unit							T (-)			Category 7	
 77 ENG1 Eff: 06-Feb-2018 (AVG MAN HRS: 1.5)						Mos						
						Hrs						
						Enc						
30534 Rev 3	Replacement of Data Collection Unit							T (-)			Category 7	
 77 ENG2 Eff: 06-Feb-2018 (AVG MAN HRS: 1.5)						Mos						
						Hrs						
						Enc						
30534 Rev 4	Replacement of Data Collection Unit							T (A/R)			Category 7	
 77 ENG1 Eff: 29-Jun-2018 (AVG MAN HRS: 1.5)						Mos						
						Hrs						
						Enc						

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30534 Rev 4	Replacement of Data Collection Unit						T (A/R)		Category 7	
 77 ENG2										
Eff: 29-Jun-2018										
(AVG MAN HRS: 1.5)										
77-00-PW-001	N1 Speed Sensor - Inspection (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
 77 ENG1										
Ref:77-10-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1)							5,500	+100	5500	2183:53 Hrs (+100)
77-00-PW-001	N1 Speed Sensor - Inspection (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
 77 ENG2										
Ref:77-10-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1)							5,500	+100	5500	2183:53 Hrs (+100)
77-00-PW-002	N2 Speed Sensor - Inspection (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
 77 ENG1										
Ref:77-10-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1)							5,500	+100	5500	2183:53 Hrs (+100)
77-00-PW-002	N2 Speed Sensor - Inspection (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
 77 ENG2										
Ref:77-10-01 (SOURCE: EMM 05-20-00 Par. 3 Table 1)							5,500	+100	5500	2183:53 Hrs (+100)
77-00-PW-003	T6 Harness and Thermocouples - Inspect and do a functional check (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
 77 ENG1										
Ref:77-20-02-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)							5,500	+100	5500	2183:53 Hrs (+100)
77-00-PW-003	T6 Harness and Thermocouples - Inspect and do a functional check (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
 77 ENG2										
Ref:77-20-02-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)							5,500	+100	5500	2183:53 Hrs (+100)
77-00-PW-005	Data Collection Unit - Download data (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
 77 ENG1										
30J3470-01										
15031281							5,500	+100	5500	2183:53 Hrs (+100)
(SOURCE: EMM 05-20-00 Par. 3 Table 1)										
77-00-PW-005	Data Collection Unit - Download data (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027
 77 ENG2										
30J3470-01										
15031430							5,500	+100	5500	2183:53 Hrs (+100)
(SOURCE: EMM 05-20-00 Par. 3 Table 1)										
77-10-00-201	Engine Wiring Harness General Visual Inspection: Do a check for security of all clamps and brackets, cables for signs of wear, fraying, chafing and cracks.Do a check for security of all wiring harness connectors.Examine the outer surfaces for cracks and corrosion.						RE	EMM - Periodic Inspection		≈14-Dec-2025
 77 ENG1	72EH0800									
							31-Oct-2024			
							3308:54	800	-/+25	(4108:54)
							2,570			792:47 Hrs (+25)

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
77-10-00-201		Engine Wiring Harness General Visual Inspection: Do a check for security of all clamps and brackets, cables for signs of wear, fraying, chafing and cracks.Do a check for security of all wiring harness connectors.Examine the outer surfaces for cracks and corrosion.						RE	EMM - Periodic Inspection		≈14-Dec-2025
	77 ENG2	72EH0800				Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
						Enc	2,570				
77-10-00-202		Engine Indicating Speed Sensor (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈31-Oct-2027
	77 ENG1					Mos	03-Oct-2022				
						Hrs	2706:58	2,750	+50	5456:58	2140:51 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)					Enc	2,069				
77-10-00-202		Engine Indicating Speed Sensor (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈31-Oct-2027
	77 ENG2					Mos	03-Oct-2022				
						Hrs	2706:58	2,750	+50	5456:58	2140:51 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)					Enc	2,069				
77-10-00-901		Engine Wiring Harness (Cleaning) Restoration: Disconnect each wiring harness connector, clean, inspect and connect again (Ref. 73-20-02, WIRING HARNESS - MAINTENANCE PRACTICES).Do the necessary engine checks after the replacement of wiring harness (Ref. 71-00-00, POWER PLANT - ADJUSTMENT/TEST).						RE	EMM - Periodic Inspection		≈14-Dec-2025
	77 ENG1	72EH0800				Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
						Enc	2,570				
77-10-00-901		Engine Wiring Harness (Cleaning) Restoration: Disconnect each wiring harness connector, clean, inspect and connect again (Ref. 73-20-02, WIRING HARNESS - MAINTENANCE PRACTICES).Do the necessary engine checks after the replacement of wiring harness (Ref. 71-00-00, POWER PLANT - ADJUSTMENT/TEST).						RE	EMM - Periodic Inspection		≈14-Dec-2025
	77 ENG2	72EH0800				Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
						Enc	2,570				
77-10-00-902		Engine Indicating Speed Sensor System (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈22-Nov-2027
	77 ENG1					Mos					
						Hrs		5,500	+50	5500	2183:53 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)					Enc					
77-10-00-902		Engine Indicating Speed Sensor System (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈22-Nov-2027
	77 ENG2					Mos					
						Hrs		5,500	+50	5500	2183:53 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)					Enc					
771002-0101		N1 Computer Display						RE (O/C)			
	77 A/F					Mos	29-Oct-2015				
	Unknown					Hrs		0			
	Unknown					Ldg		0			
771004-0101		N1/ITT Temp Indicator						RE (O/C)			
	77 A/F					Mos	29-Oct-2015				
	Unknown					Hrs		0			
	Unknown					Ldg		0			
771005-0101		N2/Oil Pressure/Oil Temperature Indicator						RE (O/C)			
	77 A/F					Mos	29-Oct-2015				
	Unknown					Hrs		0			
	Unknown					Ldg		0			
SL560XL-77-01		Transmittal of Pratt & Whitney Canada Service Information Letter PW500-016, PW545A ITT and N2 Splits in Climb						T (A/R)		Informational	
	77 A/F					Mos					
	Eff: 25-Jun-2003					Hrs					
						Ldg					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SL560XL-77-02		Transmittal of Pratt & Whitney Canada (P&WC) Service Information Letter PW500-018, PW500 High ITT						T (A/R)		Informational	
	 77 A/F						Mos				
	Eff: 11-Aug-2003						Hrs				
							Ldg				
▼ 78 - EXHAUST											
		ARM Pressure Switch						RE (O/C)			
	 78 A/F	Left					Mos	29-Oct-2015			
	80637-1	New	0				Hrs	0			
	1638		0				Ldg	0			
		ARM Pressure Switch						RE (O/C)			
	 78 A/F	Right					Mos	29-Oct-2015			
	80637-1	New	0				Hrs	0			
	1740		0				Ldg	0			
		Deploy Limit Switch						RE (O/C)			
	 78 A/F	Left					Mos	29-Oct-2015			
	53ND78304-5	New	0				Hrs	0			
	NSN		0				Ldg	0			
		Deploy Limit Switch						RE (O/C)			
	 78 A/F	Right					Mos	29-Oct-2015			
	53ND78304-5	New	0				Hrs	0			
	NSN		0				Ldg	0			
		Stow Limit Switch						RE (O/C)			
	 78 A/F	Left Inboard					Mos	29-Oct-2015			
	53ND78304-1	New	0				Hrs	0			
	NSN		0				Ldg	0			
		Stow Limit Switch						RE (O/C)			
	 78 A/F	Left Outboard					Mos	29-Oct-2015			
	53ND78304-1	New	0				Hrs	0			
	NSN		0				Ldg	0			
		Stow Limit Switch						RE (O/C)			
	 78 A/F	Right Inboard					Mos	29-Oct-2015			
	53ND78304-1	New	0				Hrs	0			
	NSN		0				Ldg	0			
		Stow Limit Switch						RE (O/C)			
	 78 A/F	Right Outboard					Mos	29-Oct-2015			
	53ND78304-1	New	0				Hrs	0			
	NSN		0				Ldg	0			
		Thrust Reverser Actuator						RE (O/C)			
	 78 A/F	Left Inboard					Mos	29-Oct-2015			
	64ND-78204-7	New	0				Hrs	0			
	3972		0				Ldg	0			
		Thrust Reverser Actuator						RE (O/C)			
	 78 A/F	Left Outboard					Mos	29-Oct-2015			
	64ND-78204-7	New	0				Hrs	0			
	3977		0				Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	78 A/F 64ND-78204-7 3978	Thrust Reverser Actuator								RE (O/C)	
		Right Inboard	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	78 A/F 64ND-78204-7 3979	Thrust Reverser Actuator								RE (O/C)	
		Right Outboard	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	78 A/F 64ND-78002-7 EX1751-4	Thrust Reverser Assembly								RE (O/C)	
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	78 A/F 64ND-78002-8 EX1752-2	Thrust Reverser Assembly								RE (O/C)	
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	78 A/F 4222 1065M	Thrust Reverser Isolation Valve								RE (O/C)	
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	78 A/F 4222 1036M	Thrust Reverser Isolation Valve								RE (O/C)	
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	78 A/F 8245 1030	Thrust Reverser Manifold Assembly								RE (O/C)	
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	78 A/F 8245 1062	Thrust Reverser Manifold Assembly								RE (O/C)	
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	78 A/F 4221 1040	Thrust Reverser Valve								RE (O/C)	
		Left	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	78 A/F 4221 1074	Thrust Reverser Valve								RE (O/C)	
		Right	0			Mos	29-Oct-2015				
		New	0			Hrs	0				
	78 A/F Unknown Unknown	Thurst Reverser Valve								RE (O/C)	
		Right				Mos	29-Oct-2015				
						Hrs	0				

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
12-20-78-6400		Left Thrust Reverser Guide Rod (D-5100NS Aerosol Spray Method) Lubrication							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈04-Apr-2025
	78 A/F	5-12-19					Mos	31-Oct-2024			
							Hrs	3308:54	300	-/+25	(3608:54) 292:47 Hrs (+25)
		(ZONE: 410) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	2,570			
12-20-78-6400		Right Thrust Reverser Guide Rod (D-5100NS Aerosol Spray Method) Lubrication							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈04-Apr-2025
	78 A/F	5-12-19					Mos	31-Oct-2024			
							Hrs	3308:54	300	-/+25	(3608:54) 292:47 Hrs (+25)
		(ZONE: 420) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	2,570			
12-20-78-6401		Thrust Reverser Pivot Point (WC-393 Method) Lubrication (Airplanes -5001 and On)							RE	05-10-01, 05-10-02, 05-12-00, Category 6	≈04-Apr-2025
	78 A/F	Left5-12-19					Mos	31-Oct-2024			
	64ND-78002-7 EX1751-4						Hrs	3308:54	300	-/+25	(3608:54) 292:47 Hrs (+25)
		MRBR Task:78-30-00-602 (ZONE: 410) (SOURCE: 560XL MM) Note: This task gives a Thrust Reverser Pivot Point Lubrication method that is an alternate to Task 12-20-78-6402 (C-5A Anti-Seize Method) Lubrication which is completed at a 600 Flight Hour interval. It is not required to complete this task if Task 12-20-78-6402 (C-5A Anti-Seize Method) Lubrication is currently being followed.					Ldg	2,570			
12-20-78-6401		Thrust Reverser Pivot Point (WC-393 Method) Lubrication (Airplanes -5001 and On)							RE	05-10-01, 05-10-02, 05-12-00, Category 6	≈04-Apr-2025
	78 A/F	Right5-12-19					Mos	31-Oct-2024			
	64ND-78002-8 EX1752-2						Hrs	3308:54	300	-/+25	(3608:54) 292:47 Hrs (+25)
		MRBR Task:78-30-00-602 (ZONE: 420) (SOURCE: 560XL MM) Note: This task gives a Thrust Reverser Pivot Point Lubrication method that is an alternate to Task 12-20-78-6402 (C-5A Anti-Seize Method) Lubrication which is completed at a 600 Flight Hour interval. It is not required to complete this task if Task 12-20-78-6402 (C-5A Anti-Seize Method) Lubrication is currently being followed.					Ldg	2,570			
12-20-78-6402		Thrust Reverser Pivot Point (C-5A Anti-Seize Method) Lubrication (Airplanes -5001 and On)							RE (N/A)	05-10-01, 05-10-02, Category 6	
	78 A/F	Left					Mos				
	64ND-78002-7 EX1751-4						Hrs				
		MRBR Task:78-30-00-603 (ZONE: 410) (SOURCE: 560XL MM) Note: NOTE: This task is not required if the Thrust Reverser Pivot Point (WC-393 Method) Lubrication is used					Ldg				
12-20-78-6402		Thrust Reverser Pivot Point (C-5A Anti-Seize Method) Lubrication (Airplanes -5001 and On)							RE (N/A)	05-10-01, 05-10-02, Category 6	
	78 A/F	Right					Mos				
	64ND-78002-8 EX1752-2						Hrs				
		MRBR Task:78-30-00-603 (ZONE: 420) (SOURCE: 560XL MM) Note: NOTE: This task is not required if the Thrust Reverser Pivot Point (WC-393 Method) Lubrication is used					Ldg				
78-10-00-201		Turbine Exhaust Case and Mixer (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).							RE	EMM - Periodic Inspection, Extended HSI	≈31-Oct-2027
	78 ENG1						Mos	03-Oct-2022			
		Ref:72-00-00-ic (SOURCE: PW545C MM 30J2302)					Hrs	2706:58	2,750	+50	5456:58 2140:51 Hrs (+50)
		Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.					Enc	2,069			
78-10-00-201		Turbine Exhaust Case and Mixer (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).							RE	EMM - Periodic Inspection, Extended HSI	≈31-Oct-2027
	78 ENG2						Mos	03-Oct-2022			
							Hrs	2706:58	2,750	+50	5456:58 2140:51 Hrs (+50)
		(SOURCE: PW545C MM 30J2302)					Enc	2,069			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
78-10-00-202		Emergency Fuel Shut Off Lever and Cable Detailed Inspection: Do an inspection through hole in theexhaust cone for - Security of control lever - Signs of oil leaks or carbon at No.5 bearing area - Examine the cable and linkages.						RE	EMM - Periodic Inspection		≈26-Jan-2027
	78 ENG1					Mos	31-Oct-2024				
						Hrs	3308:54	1,600	-/+25	4908:54	1592:47 Hrs (+25)
	Ref:73-10-07-mp					Enc	2,570				
78-10-00-202		Emergency Fuel Shut Off Lever and Cable Detailed Inspection: Do an inspection through hole in theexhaust cone for - Security of control lever - Signs of oil leaks or carbon at No.5 bearing area - Examine the cable and linkages.						RE	EMM - Periodic Inspection		≈26-Jan-2027
	78 ENG2					Mos	31-Oct-2024				
						Hrs	3308:54	1,600	-/+25	4908:54	1592:47 Hrs (+25)
	Ref:73-10-07-mp					Enc	2,570				
78-10-00-901		Turbine Exhaust Case and Mixer (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈22-Nov-2027
	78 ENG1					Mos					
						Hrs		5,500	+50	5500	2183:53 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)					Enc					
78-10-00-901		Turbine Exhaust Case and Mixer (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈22-Nov-2027
	78 ENG2					Mos					
						Hrs		5,500	+50	5500	2183:53 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)					Enc					
78-31-00-2200		Thrust Reverser Assembly Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈26-Jan-2027
	78 A/F	Left5-12-07				Mos	31-Oct-2024				
	64ND-78002-7					Hrs	3308:54	1,600	-/+25	(4908:54)	1592:47 Hrs (+25)
	EX1751-4					Ldg	2,570				
(ZONE: 410) (Tol. Adjustment: -108.9 Hrs) (SOURCE: 560 XL MM Section 5-10-02)											
78-31-00-2200		Thrust Reverser Assembly Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈26-Jan-2027
	78 A/F	Right5-12-07				Mos	31-Oct-2024				
	64ND-78002-8					Hrs	3308:54	1,600	-/+25	(4908:54)	1592:47 Hrs (+25)
	EX1752-2					Ldg	2,570				
(ZONE: 420) (Tol. Adjustment: -108.9 Hrs) (SOURCE: 560 XL MM Section 5-10-02)											
78-31-00-7200		Thrust Reverser Assembly Functional Check and Operational Check						RE	05-10-01, 05-10-02, Category 6, Category 9		≈26-Jan-2027
	78 A/F	Left5-12-07				Mos	31-Oct-2024				
	64ND-78002-7					Hrs	3308:54	1,600	-/+25	(4908:54)	1592:47 Hrs (+25)
	EX1751-4					Ldg	2,570				
MRBR Task:78-30-00-701, MRBR Task:78-30-00-702 (ZONE: 410, 235) (Tol. Adjustment: -108.9 Hrs) (SOURCE: 560XL MM)											
78-31-00-7200		Thrust Reverser Assembly Functional Check and Operational Check						RE	05-10-01, 05-10-02, Category 6, Category 9		≈26-Jan-2027
	78 A/F	Right5-12-07				Mos	31-Oct-2024				
	64ND-78002-8					Hrs	3308:54	1,600	-/+25	(4908:54)	1592:47 Hrs (+25)
	EX1752-2					Ldg	2,570				
MRBR Task:78-30-00-701, MRBR Task:78-30-00-702 (ZONE: 420, 235) (Tol. Adjustment: -108.9 Hrs) (SOURCE: 560XL MM)											
SL560XL-78-04		Thrust Reverser Stow Limit Switch Test						RE (-)		Discretionary	
	78 A/F					Mos					
						Hrs					
						Ldg					
SL560XL-78-04 Rev 01		Thrust Reverser Stow Limit Switch Test						RE (-)		Informational	
	78 A/F					Mos					
	Eff: 21-Mar-2007					Hrs					
						Ldq					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
▼ 79 - OIL											
		Engine Oil Transmitter								RE (O/C)	
79 A/F		Left	0			Mos	29-Oct-2015				
APTE-237E-1000-250D		New	0			Hrs	0				
8212-10-235			0			Ldg	0				
		Engine Oil Transmitter								RE (O/C)	
79 A/F		Right	0			Mos	29-Oct-2015				
APTE-237E-1000-250D		New	0			Hrs	0				
8225-11-467			0			Ldg	0				
		Fuel Oil Heat Exchanger								RE (O/C)	
79 ENG1		New	0			Mos	29-Oct-2015				
31J2955-03			0			Hrs	0				
09510997			0			Enc	0				
		Fuel Oil Heat Exchanger								RE (O/C)	
79 ENG2		New	0			Mos	29-Oct-2015				
31J2955-03			0			Hrs	0				
09510998			0			Enc	0				
		Magnetic Chip Collector								RE (O/C)	
79 ENG1		Unknown Unknown				Mos	29-Oct-2015				
Unknown						Hrs	0				
Unknown						Enc	0				
		Magnetic Chip Collector								RE (O/C)	
79 ENG2		Unknown Unknown				Mos	29-Oct-2015				
Unknown						Hrs	0				
Unknown						Enc	0				
		No.1 Oil Level Indicator								RE (O/C)	
79 ENG1		Unknown Unknown				Mos	29-Oct-2015				
Unknown						Hrs	0				
Unknown						Enc	0				
		No.1 Oil Level Indicator								RE (O/C)	
79 ENG2		Unknown Unknown				Mos	29-Oct-2015				
Unknown						Hrs	0				
Unknown						Enc	0				
		No.2 Oil Level Indicator								RE (O/C)	
79 ENG1		Unknown Unknown				Mos	29-Oct-2015				
Unknown						Hrs	0				
Unknown						Enc	0				
		No.2 Oil Level Indicator								RE (O/C)	
79 ENG2		Unknown Unknown				Mos	29-Oct-2015				
Unknown						Hrs	0				
Unknown						Enc	0				

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
	79 A/F 1153P0098-01 2607	Oil Pressure Switch								RE (O/C)		
		Left					Mos	29-Oct-2015				
		New					Hrs	0				
							Ldg	0				
	79 A/F 1153P0098-01 2611	Oil Pressure Switch								RE (O/C)		
		Right					Mos	29-Oct-2015				
		New					Hrs	0				
							Ldg	0				
	79 A/F 102-00083 194129	Oil Temp Transmitter Sensor								RE (O/C)		
		Left					Mos	29-Oct-2015				
		New					Hrs	0				
							Ldg	0				
	79 A/F 102-00083 194183	Oil Temp Transmitter Sensor								RE (O/C)		
		Right					Mos	29-Oct-2015				
		New					Hrs	0				
							Ldg	0				
30325 Rev 2		Oil-Pump Plain Seal - Replacement								RE (-)	Category 6	
	79 ENG1 Eff: 23-Dec-2015 (AVG MAN HRS: 2)						Mos					
							Hrs					
							Enc					
30325 Rev 2		Oil-Pump Plain Seal - Replacement								RE (-)	Category 6	
	79 ENG2 Eff: 23-Dec-2015 (AVG MAN HRS: 2)						Mos					
							Hrs					
							Enc					
79-00-PW-001		Oil Filter Differential Pressure Switch - Examine and do a functional test (at Engine Overhaul)								RE	EMM - Requirement, Extended TBO	≈22-Nov-2027
	79 ENG1 Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)						Mos					
							Hrs	5,500	+100	5500	2183:53 Hrs (+100)	
							Enc					
79-00-PW-001		Oil Filter Differential Pressure Switch - Examine and do a functional test (at Engine Overhaul)								RE	EMM - Requirement, Extended TBO	≈22-Nov-2027
	79 ENG2 Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)						Mos					
							Hrs	5,500	+100	5500	2183:53 Hrs (+100)	
							Enc					
79-00-PW-002		Chip Detector/Collector - Examine (at Engine Overhaul)								RE	EMM - Requirement, Extended TBO	≈22-Nov-2027
	79 ENG1 Unknown Unknown Ref:79-30-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)						Mos					
							Hrs	5,500	+100	5500	2183:53 Hrs (+100)	
							Enc					
79-00-PW-002		Chip Detector/Collector - Examine (at Engine Overhaul)								RE	EMM - Requirement, Extended TBO	≈22-Nov-2027
	79 ENG2 Unknown Unknown Ref:79-30-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)						Mos					
							Hrs	5,500	+100	5500	2183:53 Hrs (+100)	
							Enc					

Task No		Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
79-00-PW-003		Oil Tank Filler Cap - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027	
	79 ENG1					Mos						
						Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Enc						
79-00-PW-003		Oil Tank Filler Cap - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027	
	79 ENG2					Mos						
						Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Enc						
79-00-PW-004		Oil Level Indicator (sight glass) - Inspect (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027	
	79 ENG1					Mos						
						Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
		Ref:CIR (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Enc						
79-00-PW-004		Oil Level Indicator (sight glass) - Inspect (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027	
	79 ENG2					Mos						
						Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
		Ref:CIR (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Enc						
79-00-PW-005		Oil Filter - Examine and replace (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027	
	79 ENG1					Mos						
						Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
		Ref:79-20-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Enc						
79-00-PW-005		Oil Filter - Examine and replace (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈22-Nov-2027	
	79 ENG2					Mos						
						Hrs		5,500	+100	5500	2183:53 Hrs (+100)	
		Ref:79-20-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Enc						
79-10-00-201		External Oil Tube General Visual Inspection: Examine for signs of wear, chafing, cracks, leaks and corrosion.						RE	EMM - Periodic Inspection		≈14-Dec-2025	
	79 ENG1	72EH0800				Mos	31-Oct-2024					
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)	
						Enc	2,570					
79-10-00-201		External Oil Tube General Visual Inspection: Examine for signs of wear, chafing, cracks, leaks and corrosion.						RE	EMM - Periodic Inspection		≈14-Dec-2025	
	79 ENG2	72EH0800				Mos	31-Oct-2024					
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)	
						Enc	2,570					
79-10-00-202		Fuel Oil Heat Exchanger General Visual Inspection: Do an inspection for security, leakage and general condition. No leakage permitted.						RE	EMM - Periodic Inspection		≈14-Dec-2025	
	79 ENG1	72EH0800				Mos	31-Oct-2024					
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)	
						Enc	2,570					
79-10-00-202		Fuel Oil Heat Exchanger General Visual Inspection: Do an inspection for security, leakage and general condition. No leakage permitted.						RE	EMM - Periodic Inspection		≈14-Dec-2025	
	79 ENG2	72EH0800				Mos	31-Oct-2024					
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)	
						Enc	2,570					
79-10-00-203		Accessory Gear Box Pad Seal General Visual Inspection: Examine the pad seals for oil leaks.						RE	EMM - Periodic Inspection		≈14-Dec-2025	
	79 ENG1	72EH0800				Mos	31-Oct-2024					
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)	
						Enc	2,570					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
79-10-00-203	79 ENG2	Accessory Gear Box Pad Seal General Visual Inspection: Examine the pad seals for oil leaks. 72EH0800						RE	EMM - Periodic Inspection	≈14-Dec-2025	
						Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
79-10-00-204	79 ENG1	External Engine General Visual Inspection: Examine for fuel and oil leaks, corrosion, cracks and signs of damage. 72EH0800						RE	EMM - Periodic Inspection	≈14-Dec-2025	
						Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
79-10-00-204	79 ENG2	External Engine General Visual Inspection: Examine for fuel and oil leaks, corrosion, cracks and signs of damage. 72EH0800						RE	EMM - Periodic Inspection	≈14-Dec-2025	
						Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
79-10-00-205	79 ENG1	Oil Filter Detailed Inspection: Remove and do a check for foreign material and damage. 72EH0800						RE	EMM - Periodic Inspection	≈14-Dec-2025	
						Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
79-10-00-205	79 ENG2	Oil Filter Detailed Inspection: Remove and do a check for foreign material and damage. 72EH0800						RE	EMM - Periodic Inspection	≈14-Dec-2025	
						Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
79-10-00-206	79 ENG1	Oil Special Detailed Inspection: Do a check for oil level with the outboard sight glass. 72EH0000						RE (PreFlight)	EMM - Periodic Inspection		
						Mos					
						Hrs					
79-10-00-206	79 ENG2	Oil Special Detailed Inspection: Do a check for oil level with the outboard sight glass. 72EH0000						RE (PreFlight)	EMM - Periodic Inspection		
						Mos					
						Hrs					
79-10-00-206	79 ENG1	Oil Special Detailed Inspection: Do a check for oil level with the outboard sight glass. Monitor the oil quality on condition and do analysis periodically as observations warrant (Ref. 72-00-00, ENGINE, GENERAL - SERVICING). 72EH0800						RE	EMM - Periodic Inspection	≈14-Dec-2025	
						Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
79-10-00-206	79 ENG2	Oil Special Detailed Inspection: Do a check for oil level with the outboard sight glass. Monitor the oil quality on condition and do analysis periodically as observations warrant (Ref. 72-00-00, ENGINE, GENERAL - SERVICING). 72EH0800						RE	EMM - Periodic Inspection	≈14-Dec-2025	
						Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
79-10-00-207	79 ENG1	Oil Filter Bypass Valve Functional Check (Ref. 79-30-02, OIL PRESSURE SWITCH-MAINTENANCE PRACTICES - INSPECTION). Ref:79-30-02-mp (SOURCE: PW545C MM 30J2302) Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.						RE	EMM - Periodic Inspection, Extended HSI	≈16-Nov-2026	
						Mos	08-Oct-2020				
						Hrs	2021:50	2,750	+50	4771:50	1455:43 Hrs (+50)
79-10-00-207	79 ENG2	Oil Filter Bypass Valve Functional Check (Ref. 79-30-02, OIL PRESSURE SWITCH-MAINTENANCE PRACTICES - INSPECTION). Ref:79-30-02-mp (SOURCE: PW545C MM 30J2302) Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.						RE	EMM - Periodic Inspection, Extended HSI	≈16-Nov-2026	
						Mos	08-Oct-2020				
						Hrs	2021:50	2,750	+50	4771:50	1455:43 Hrs (+50)

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
79-10-00-208/209		Magnetic Chip Detector/Collector General Visual Inspection: (Ref. 79-30-01, CHIP DETECTION-MAINTENANCE PRACTICES - REMOVAL/INSTALLATION)							RE	EMM - Periodic Inspection	≈14-Dec-2025
	79 ENG1	72EH0800				Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
	Ref:79-30-01-mp (SOURCE: PW545C MM 30J2302)					Enc	2,570				
79-10-00-208/209		Magnetic Chip Detector/Collector General Visual Inspection: (Ref. 79-30-01, CHIP DETECTION-MAINTENANCE PRACTICES - REMOVAL/INSTALLATION)							RE	EMM - Periodic Inspection	≈14-Dec-2025
	79 ENG2	72EH0800				Mos	31-Oct-2024				
						Hrs	3308:54	800	-/+25	(4108:54)	792:47 Hrs (+25)
	Ref:79-30-01-mp (SOURCE: PW545C MM 30J2302)					Enc	2,570				
79-10-00-901		Oil Filter Discard: Install the new oil filter element.							RE	EMM - Periodic Inspection	≈23-Feb-2026
	79 ENG1					Mos	09-Oct-2023				
						Hrs	3048:30	1,200	-/+25	4248:30	932:23 Hrs (+25)
	(UPDATE NOTE: WO: 101042297) (SOURCE: PW545C MM (P/N 30J2302))					Enc	2,362				
		Note: requirement with new task number introduced EMM R28. Oil filter discard done at 2021:50 Hrs									
79-10-00-901		Oil Filter Discard: Install the new oil filter element.							RE	EMM - Periodic Inspection	≈23-Feb-2026
	79 ENG2					Mos	09-Oct-2023				
						Hrs	3048:30	1,200	-/+25	4248:30	932:23 Hrs (+25)
	(UPDATE NOTE: WO: 101042298) (SOURCE: PW545C MM (P/N 30J2302))					Enc	2,362				
		Note: requirement with new task number introduced EMM R28. Oil filter discard done at 2021:50 Hrs									
79-10-00-902		Engine Restoration (TBO): Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.							RE	EMM - Periodic Inspection, Extended TBO	≈22-Nov-2027
	79 ENG1					Mos					
						Hrs		5,500	+50	5500	2183:53 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)					Enc					
79-10-00-902		Engine Restoration (TBO): Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.							RE	EMM - Periodic Inspection, Extended TBO	≈22-Nov-2027
	79 ENG2					Mos					
						Hrs		5,500	+50	5500	2183:53 Hrs (+50)
	(SOURCE: PW545C MM 30J2302)					Enc					
▼ 80 - STARTING											
		Starter/Generator								RE (O/C)	
	80 A/F	Left				Mos	24-Apr-2023				
	300SGL138Q-4-3	Overhauled		0		Hrs	2988:36				
	4421XL			0		Ldg	2,304				
		Starter/Generator								RE (O/C)	
	80 A/F	Right				Mos	17-May-2022				
	991249-6EX	Overhauled		0		Hrs	2557:42				
	1949XL			0		Ldg	1,954				
		Starter/Generator APU								RE (O/C)	
	80 A/F					Mos	17-Dec-2021				
	9912499-31					Hrs	2295:34				
	5458XL					Ldg	1,748				
		(UPDATE NOTE: REPLACED APU STARTER GENERATOR PN: 9912499-31 IAW C560XL AMM REV46 CH24-31-02 REV44. REMOVED S/G:PN: 9912499-31SN: S001461INSTALLED S/G:PN: 9912499-31SN: 5458XLCONDITION: OVERHAULEDPERFORMED OPS CHECK; SAT)									
80-10-00-9600		Engine Starter - Generator (Bearings Discard and Armature Functional Check) Restoration							RE	05-10-01, 05-10-02, Category 6	≈19-Oct-2025
	80 A/F	Left			0	Mos	24-Apr-2023				
	300SGL138Q-4-3					Hrs	2988:36	1,000	-/+25	3997:10	681:03 Hrs (+25)
	4421XL					Ldg	2,304				
		MRBR Task:80-10-00-901 (Tol. Adjustment: 8.6 Hrs) (SOURCE: 560XL MM)									

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
80-10-00-9600	Engine Starter - Generator (Bearings Discard and Armature Functional Check) Restoration									
 80 A/F	Right				Mos	17-May-2022			RE 05-10-01, 05-10-02, Category 6	≈03-Mar-2025
991249-6EX					Hrs	2557:42	1,000	-/+25	3547:44	231:37 Hrs (+25)
1949XL					Ldg	1,954				
MRBR Task:80-10-00-901 (Tol. Adjustment: -10 Hrs) (SOURCE: 560XL MM)										
 ECR-WP-010 / OKECR/013 START 24-JUN-2024										
80-11-00-2200	Auxiliary Power Unit Starter - Generator Detailed Inspection									
 80 A/F					Mos	24-Apr-2023			RE 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈26-Nov-2025
9912499-31					Hrs	2988:36				
5458XL					Ldg	2,304				
(ZONE: 322) (Tol. Adjustment: 23.8 Hrs(APU)) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
Note: NOTE:Per Supplier Recommendation. Reference Skurka Aerospace Incorporated 300SGL Series Installation Maintenance Manual.										
80-11-00-9600	Auxiliary Power Unit Starter - Generator (Bearings Discard and Armature Functional Check) Restoration									
 80 A/F					Mos	17-Dec-2021			RE 05-10-01, 05-10-02, Category 9	≈24-Dec-2025
9912499-31					Hrs	2295:34				
5458XL					Ldg	1,748				
MRBR Task:80-10-00-902 (UPDATE NOTE: PERFORMED TASK 80-11-00-2200 AUXILIARY POWER UNIT STARTER-GENERATOR DETAILED INSPECTION IAW C560XL AMM REV46 CH80-11-00-2200 REV46. FOUND APU S/G COOLING FAN CORRODED. FOR DETAILS REFER TO ORDER 100347242) (SOURCE: 560XL MM)										
▼ 99 - --										
CIL-99-01	Use of Corrosion Inhibiting Compounds								RE (-)	Service Letter
 99 A/F					Mos					
					Hrs					
					Ldg					
CIL-99-01 R1	Use of Corrosion Inhibiting Compounds								T (-)	Service Letter
 99 A/F					Mos					
Eff: 15-Feb-2013					Hrs					
					Ldg					
CIL-99-01 R2	Use of Corrosion Inhibiting Compounds								RE (-)	Service Letter
 99 A/F					Mos	24-Nov-2019				
Eff: 02-Jul-2015 Complied With					Hrs	1700:03				
					Ldg	1,331				
CIL-99-01 R3	Use of Corrosion Inhibiting Compounds (Cancels this Service Letter)								RE (-)	Service Letter
 99 A/F					Mos					
Eff: 14-Aug-2019					Hrs					
					Ldg					
CIL-99-02	Avoid Operations on Runways Treated with Runway De-Ice (RDI) Fluids. Aircraft Washing Recommended after Exposure to RDI Fluids								T (-)	Service Letter
 99 A/F					Mos					
Eff: 23-May-2012					Hrs					
					Ldg					
Note: the airplane should be washed within 3 days of any exposure to RDI fluids										
CIL-99-02 R1	Avoid Operations on Runways Treated with Runway De-Ice (RDI) Fluids. Aircraft Washing Recommended after Exposure to RDI Fluids - (Cancels this Service Letter)								RE (-)	Service Letter
 99 A/F					Mos					
Eff: 14-Aug-2019					Hrs					
					Ldg					
CIL-99-03	Miscellaneous - Corrosion Prevention and Control Program (CPCP)								RE (-)	Recommended
 99 A/F					Mos	13-Sep-2021				
Eff: 04-Jan-2013 Cancelled					Hrs	2222:03				
					Ldg	1,687				
Note: his service letter should be accomplished at a scheduled maintenance period or phase inspection.										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CIL-99-03 R1	Miscellaneous - Corrosion Prevention and Control Program (CPCP)						RE (-)		Service Letter	
 99 A/F						Mos	13-Sep-2021			
Eff: 25-Mar-2013 Cancelled						Hrs	2222:03			
						Ldg	1,687			
Note: This service letter should be accomplished at a scheduled maintenance period or phase inspection.										
CIL-99-03 R2	Miscellaneous - Corrosion Prevention and Control Program (CPCP) (Cancels this Service Letter)						RE (-)		Service Letter	
 99 A/F						Mos	13-Sep-2021			
Eff: 14-Aug-2019 Cancelled						Hrs	2222:03			
						Ldg	1,687			
CIL-99-04	Miscellaneous - Incremental Library Updates For Cesview, Service Letter						RE (-)		Service Letter	
 99 A/F						Mos				
Eff: 23-May-2012						Hrs				
						Ldg				
CIL-99-04 R1	Miscellaneous - Incremental Library Updates For Cesview, Service Letter - (Cancels this Service Letter)						RE (-)		Service Letter	
 99 A/F						Mos				
Eff: 14-Aug-2019						Hrs				
						Ldg				
SL560XL-99-03	Transmittal of Cessna's Certification Requirements for Personal Electronic Device Usage						RE (-)		Discretionary	
 99 A/F						Mos				
						Hrs				
						Ldg				
SL560XL-99-03 Rev 01	Transmittal of Cessna's Certification Requirements for Personal Electronic Device Usage						T (A/R)		Informational	
 99 A/F						Mos				
Eff: 23-Aug-2013						Hrs				
						Ldg				
SL560XL-99-04	Cessna Part Number Suffixes For Remanufactured Parts						T (A/R)		Informational	
 99 A/F						Mos				
Eff: 15-Nov-2011						Hrs				
						Ldg				
SL560XL-99-05	Cessna Service Document Change Notification						T (A/R)		Informational	
 99 A/F						Mos				
Eff: 22-Nov-2011						Hrs				
						Ldg				
SL560XL-99-07	Miscellaneous - Transmittal of Rockwell Collins Operators Bulletin (OPSB) 0166-17 - The FMS May Turn In The Wrong Direction After Sequencing A "Climb To" Altitude That Was Manually Edited Or Temperature Compensated						T (A/R)		Informational, Service Letter	
 99 A/F						Mos				
Eff: 17-Aug-2017						Hrs				
						Ldg				
▼ 100 - GENERAL										
D202005000806	Biocide Treatment Process						T (A/R)		Service Information Letter	
 100 APU1						Mos				
Eff: 06-May-2020						Hrs				
						APUS				
SIL-GEN-156	DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation						T (-)		Service Information Letter	
 100 ENG1						Mos				
Eff: 06-Aug-2019						Hrs				
						Enc				
SIL-GEN-156	DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation						T (-)		Service Information Letter	
 100 ENG2						Mos				
Eff: 06-Aug-2019						Hrs				
						Enc				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-163		Removal of AWL Requirement to Mark Parts with Accumulated Cycles and/or Time						T (A/R)		Service Information Letter	
	100 ENG1										
	Eff: 03-Mar-2021										
SIL-GEN-163		Removal of AWL Requirement to Mark Parts with Accumulated Cycles and/or Time						T (A/R)		Service Information Letter	
	100 ENG2										
	Eff: 03-Mar-2021										
SIL-PW500-074		United States Parts Distribution						T (A/R)		Service Information Letter	
	100 ENG1										
	Eff: 02-Jun-2021										
SIL-PW500-074		United States Parts Distribution						T (A/R)		Service Information Letter	
	100 ENG2										
	Eff: 02-Jun-2021										