

OWNER: AEROPARTNER A.S.
ADDRESS: NA FIALCE 1637/54
 PRAHA 16300
PHONE: 420-724-772-253
FAX:

OPERATOR: AEROPARTNER A.S.
ADDRESS: NA FIALCE 1637/54
 PRAHA 16300
PHONE: 420-724-772-253
FAX:

ANALYST: COLIN DE MEYER
EMAIL: COLIN.DEMEYER@CAMPSYSTEMS.EU

+33-1.55.93.45.91 (DIRECT)
 +33 (0) 1.55.93.45.80 (OFFICE)
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Task Type In: ('AD','ADP','SB','SBP'); Group by Profile or Bulletin: Profile Type; Mode: With Compliance or Next Due; For: Airframe, Engine, APU Etc;

AIRCRAFT	SERIAL/REGNO: 560XL-5230/OK-HAR	MODEL: 560XL - CITATION XL (MSG)	MANUFACTURER: TEXTRON AVIATION INC.
-----------------	--	---	--

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE:	17-FEB-2002	7897:15 A/C HRS	as of 09-JUN-2023	_____ A/C HRS	as of ____/____/____
		6504 AFL	as of 09-JUN-2023	_____ AFL	as of ____/____/____
		3504:50 APH	as of 18-MAY-2023	_____ APH	as of ____/____/____
		6829 APS	as of 18-APR-2023	_____ APS	as of ____/____/____

APU	SERIAL/PART: P-268/3800722-1	MODEL: RE100 (XL)	MANUFACTURER: HONEYWELL
------------	-------------------------------------	--------------------------	--------------------------------

INSTALLED ON 07-AUG-2009		LAST ACTUALS		CURRENT ACTUAL	
0	APU HRS	3504:50 APU HRS	as of 18-MAY-2023	_____ APU HRS	as of ____/____/____
0	APUS	6829 APUS	as of 18-APR-2023	_____ APUS	as of ____/____/____

ENGINE NO. 1	SERIAL/PART: PCE-DB0473/31J1900-01	MODEL: PW545A	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
---------------------	---	----------------------	---

INSTALLED ON 17-FEB-2002		LAST ACTUALS		CURRENT ACTUAL	
17	ENG. HRS	17 A/C HRS	7843:53 ENG. HRS	as of 09-JUN-2023	_____ ENG. HRS as of ____/____/____
	ENC		6462 ENC	as of 09-JUN-2023	_____ ENC as of ____/____/____

ENGINE NO. 2	SERIAL/PART: PCE-DB0472/31J1900-01	MODEL: PW545A	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
---------------------	---	----------------------	---

INSTALLED ON 17-FEB-2002		LAST ACTUALS		CURRENT ACTUAL	
17	ENG. HRS	17 A/C HRS	7897:15 ENG. HRS	as of 09-JUN-2023	_____ ENG. HRS as of ____/____/____
	ENC		6504 ENC	as of 09-JUN-2023	_____ ENC as of ____/____/____

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - AD - 560XL-5230/OK-HAR							
EASA 2010-0003 R02 PARA (3)	EXEMPTIONS: ATR 42 AND ATR 72 AEROPLANES					MANDATORY	NOT APPLICABLE - BY PN TRANSPONDER
14-OCT-2014	MOS HRS/MSC - AFL			22-SEP-2014 4658:50 4378			
EASA 2014-0095 PARA (4)	DO NOT INSTALL A HR SMITH (TECHNICAL DEVELOPMENTS) CPI SYSTEM SERIES 15-503-134 OR 15-503-134-1 EQUIPPED WITH CONTROL PANEL P/N 503-22-(), BEACON RELEASE UNIT P/N 503-21 AND SYSTEM INTERFACE UNIT P/N 503-24-() (INCLUDING 503-24) OR P/N 503-42-() (INCLUDING 503-42) EXCLUDING SYSTEM INTERFACE UNIT P/N 503-24-A OR P/N 503-24-()A OR P/N 503-24-G OR P/N 503-24-()G OR P/N 503-42-A OR P/N 503-42-()A OR P/N 503-42-G OR P/N 503-42-()G ON AN AIRCRAFT UNLESS IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
07-MAY-2014	MOS HRS/MSC - AFL			20-MAY-2014 4573:18 4308			
EASA 2014-0142 R01	OXYGEN OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - CREW OXYGEN MASKS WITH PN MC10-16-100 ARE INSTALLED
18-JUN-2014	MOS HRS/MSC - AFL			30-JAN-2015 4675:30 4392			
EASA 2019-0235 PARA (1) THRU (4)	CONCURRENTLY ACCOMPLISH PARAS (1.1) AND (1.2) OF THIS AD AND ACCOMPLISH APPLICABLE CORRECTIVE ACTION(S) (IF, DISCREPANCIES ARE DETECTED, AS IDENTIFIED IN THE SIL); OPERATORS MAY CONTINUE TO USE ELTS WITH THE ORIGINAL G-SWITCHES BY REDUCING THE INTERVAL OF THE G-SWITCH TESTING, AS REQUIRED BY PARA (1.1)					MANDATORY	COMPLIED WITH - WORKS PERFORMED I.A.W. CESSNA 56XMM
04-OCT-2019	DAY HRS/MSC - AFL			13-DEC-2019 5416 4960			
FAA 1974-08-09 R02	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION					MANDATORY	COMPLIED WITH
	MOS HRS/MSC - AFL			17-JUN-2009 3835			
FAA 1974-08-09 R03	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION					MANDATORY	NOT APPLICABLE - ALL PLACARDS ARE INSTALLED.
	MOS HRS/MSC 1000 (s) AFL			14-SEP-2021 6755:02 5707			
FAA 2000-15-51	AILERON CABLE FAIRLEAD TUBE AND AILERON CABLE SECTOR					MANDATORY	COMPLIED WITH
14-AUG-2000	MOS HRS/MSC - AFL			17-FEB-2002 17 0			
FAA 2001-23-17	GARMIN INTERNATIONAL GNS 430					MANDATORY	COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED
	MOS HRS/MSC A/R AFL			17-FEB-2002 17 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2006-04-10	INSTALLING IDENTIFICATION SLEEVES ON THE WIRES FOR THE POSITIVE AND NEGATIVE STUDS OF THE ENGINE AND/ OR (APU) FIRE EXTINGUISHING BOTTLES, AS APPLICABLE, AND RECONNECTING THE WIRES TO THE CORRECT TERMINAL STUDS.					MANDATORY	COMPLIED WITH
24-MAR-2006		MOS HRS/MSC AFL	A/R	30-JAN-2006 2510			
FAA 2007-11-17	FIRE PROTECTION - INSTALLATION OF IDENTIFICATION SLEEVES ON THE WIRES FOR THE POSITIVE AND NEGATIVE TERMINAL STUDS OF THE APPLICABLE FIRE EXTINGUISHING BOTTLES				20-JUL-2007 3274	MANDATORY	COMPLIED WITH
FAA 2010-07-02	PERFORM A ONE-TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR THE HONEYWELL PRIMUS II NV-850 NAVIGATION RECEIVER MODULE (NRM)				28-APR-2010 3970 3818	MANDATORY	COMPLIED WITH
FAA 2012-06-01	MODIFY THE DRAIN INSTALLATION OF THE TAILCONE STINGER ON THE AFT CANTED BULKHEAD				05-MAY-2012 4272:33 4072	MANDATORY	COMPLIED WITH
07-JUN-2012		MOS HRS/MSC AFL	-	05-JUN-2012 4272:33 4072			
FAA 2013-09-11	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM					MANDATORY	NOT APPLICABLE - NO COMPRESSOR MOTOR PN 1134104-1/1134104-5 INSTALLED
05-JUL-2013		MOS HRS/MSC AFL	-	04-JUL-2013 4441:56 4208			
FAA 2013-09-11 PARA (G)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION FOR PART NUMBER (P/N)					MANDATORY	NOT APPLICABLE - NO COMPRESSOR MOTOR PN 1134104-1/1134104-5 INSTALLED
05-JUL-2013		DAYs HRS/MSC AFL	-	04-JUL-2013 4441:56 4208			
FAA 2013-09-11 PARA (H)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION A/C COMPRESSOR HOUR METER AND MAINTENANCE RECORDS					MANDATORY	NOT APPLICABLE - NO COMPRESSOR MOTOR PN 1134104-1/1134104-5 INSTALLED
05-JUL-2013		DAYs HRS/MSC AFL	-	04-JUL-2013 4441:56 4208			
FAA 2013-09-11 PARA (I) & (J)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REPLACEMENT OF A/C COMPRESSOR MOTOR BRUSHES AND RELATED MAINTENANCE MANUAL INFORMATION					MANDATORY	NOT APPLICABLE - NO COMPRESSOR MOTOR PN 1134104-1/1134104-5 INSTALLED
05-JUL-2013		MOS HRS/MSC AFL ACH	-	04-JUL-2013 4441:56 4208 2470:48			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2013-09-11 PARA (K)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM DEACTIVATION OF A/C SYSTEM					MANDATORY	NOT APPLICABLE - NO COMPRESSOR MOTOR PN 1134104-1/1134104-5 INSTALLED
05-JUL-2013		MOS		04-JUL-2013			
		HRS/MSC	A/R	4441:56			
		AFL		4208			
FAA 2013-09-11 PARA (L)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REACTIVATION OF A/C SYSTEM					MANDATORY	NOT APPLICABLE - NO COMPRESSOR MOTOR PN 1134104-1/1134104-5 INSTALLED
05-JUL-2013		MOS		04-JUL-2013			
		HRS/MSC	A/R	4441:56			
		AFL		4208			
FAA 2013-09-11 PARA (M)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM PARTS RETURN AND REPORTING REQUIREMENTS					MANDATORY	NOT APPLICABLE - NO COMPRESSOR MOTOR PN 1134104-1/1134104-5 INSTALLED
05-JUL-2013		DAY(S)		04-JUL-2013			
		HRS/MSC	- (s)	4441:56			
		AFL		4208			
FAA 2014-18-01	NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION					MANDATORY	NOT APPLICABLE - BY PN TRANSPONDER
14-OCT-2014		MOS		22-SEP-2014			
		HRS/MSC	-	4658:50			
		AFL		4378			
FAA 2017-04-14	ELECTRICAL POWER - INSPECTIONS OF THE FUEL TUBE AND RIGHT ALTERNATING CURRENT (AC) GENERATOR WIRES					MANDATORY	COMPLIED WITH - BY COMPLETION OF SL 24-07 AT 4977.1 ACTT ON 15 FEB 2017.
09-MAR-2017		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2017-04-14 PARA (G)	ACCOMPLISH GENERAL VISUAL INSPECTIONS OF THE FUEL TUBE AND RIGHT ALTERNATING CURRENT (AC) GENERATOR WIRES FOR EVIDENCE OF DAMAGE, ALL APPLICABLE ADJUSTMENTS, AND ALL APPLICABLE CORRECTIVE ACTIONS					MANDATORY	COMPLIED WITH - BY COMPLETION OF SL 24-07 AT 4977.1 ACTT ON 15 FEB 2017.
09-MAR-2017		DAY(S)		08-FEB-2019			
		HRS/MSC	-	5066:42			
		AFL		4739			
FAA 2017-04-14 PARA (H)	SUBMIT A REPORT OF THE FINDINGS (BOTH POSITIVE AND NEGATIVE) OF THE INSPECTIONS REQUIRED BY PARAGRAPH (G) OF THIS AD TO TEXTRON AVIATION					MANDATORY	COMPLIED WITH - BY COMPLETION OF SL 24-07 AT 4977.1 ACTT ON 15 FEB 2017.
09-MAR-2017		DAY(S)		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS						NOT APPLICABLE - COMPONENTS NOT INSTALLED
24-OCT-2017		MOS		08-FEB-2019			
		HRS/MSC	-	5066:42			
		AFL		4739			
FAA 2017-18-12	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES					MANDATORY	NOT APPLICABLE
16-OCT-2017		MOS		17-JUN-2019			
		HRS/MSC	- (s)	5110:47			
		AFL		4774			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED					MANDATORY	NOT APPLICABLE
16-OCT-2017	MOS HRS/MSC - (s) AFL			17-JUN-2019 5110:47 4774			
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED					MANDATORY	NOT APPLICABLE
16-OCT-2017	MOS HRS/MSC - (s) AFL			17-JUN-2019 5110:47 4774			
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.					MANDATORY	NOT APPLICABLE
16-OCT-2017	MOS HRS/MSC - AFL			17-JUN-2019 5110:47 4774			
FAA 2017-19-05	APPLIANCE AD - FIRE PROTECTION - OPTICAL AND AMBIENT SMOKE DETECTORS - IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
31-OCT-2017	MOS HRS/MSC - (s) AFL			08-FEB-2019 5066:42 4739			
FAA 2019-01-02	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) IN - AIRPLANE FLIGHT MANUAL SUPPLEMENT (AFMS) - DISABLE / REVISE					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
07-FEB-2019	MOS HRS/MSC - (s) AFL			08-FEB-2019 5066:42 4739			
FAA 2019-01-02 PARA (G)(1)	DISABLE THE AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) IN FUNCTION IN EACH UNIT					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
07-FEB-2019	MOS HRS/MSC - (s) AFL			08-FEB-2019 5066:42 4739			
FAA 2019-01-02 PARA (G)(2)	REVISE THE AIRPLANE FLIGHT MANUAL SUPPLEMENT IN ACCORDANCE WITH PARAGRAPH 5.2.C OF SB2018-01					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
07-FEB-2019	MOS HRS/MSC - (s) AFL			08-FEB-2019 5066:42 4739			
FAA 2019-07-10	NAVIGATION - LITEF ATTITUDE HEADING AND REFERENCE SYSTEM (AHRS) - REMOVAL					MANDATORY	NOT APPLICABLE - AIRCRAFT NOT EQUIPPED. AHRS P/N: 142185-1100 IS INSTALLED ON AIRCRAFT.
29-MAY-2019	MOS HRS/MSC - (s) AFL			17-JUN-2019 5110:47 4774			
FAA 2019-07-10 PARA (F)(1)	REMOVE THE AHRS UNIT FROM SERVICE					MANDATORY	NOT APPLICABLE - AIRCRAFT NOT EQUIPPED. AHRS P/N: 142185-1100 IS INSTALLED ON AIRCRAFT.
29-MAY-2019	MOS HRS/MSC - AFL			17-JUN-2019 5110:47 4774			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2019-07-10 PARA (F)(3)	DO NOT INSTALL AN AHRS UNIT P/N 145130-2000, 145130-2001, 145130-7000, 145130-7001, OR 145130-7100 ON ANY AIRCRAFT					MANDATORY	NOT APPLICABLE - COMPONENT NOT INSTALLED. AIRCRAFT EQUIPPED WITH AHRS COMPUTER P/N:142185-1100
29-MAY-2019		MOS HRS/MSC - (s) AFL		17-JUN-2019 5110:47 4774			
FAA 2020-26-05	ENGINE CONTROLS - LEFT AND RIGHT THROTTLE QUADRANT ASSEMBLY SENSOR LINK AND SENSOR DRIVE ARM PIVOT RIVETS - INSPECTION/CORRECTIVE ACTION					MANDATORY	NOT APPLICABLE - N/A BY AIRCRAFT S/N.
17-DEC-2020		MOS HRS/MSC - AFL		17-JUN-2022 7366:02 6120			
AD 26AD-01	OVERLAND AVIATION SERVICES						COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED
		MOS HRS/MSC - AFL		26-FEB-2002 33			
AD 34AD-10	ROCKWELL COLLINS MODE C XPDR						COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED
		MOS HRS/MSC - AFL		30-APR-2002 100			
AD 34AD-11	ROCKWELL COLLINS MODE S XPDR						COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED
		MOS HRS/MSC - AFL		30-APR-2002 100			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
APPLIANCE - 560XL-5230/OK-HAR							
EASA 2005-0021	APPLIANCE AD - HONEYWELL RCZ-83() AND RCZ-85() COMMUNICATION UNITS					SUPERSEDED	NOT APPLICABLE - NOT APPLICABLE
		MOS		26-AUG-2005			
		HRS/MSC	A/R	2353			
		AFL					
EASA 2010-0003 R02	APPLIANCE AD - NAVIGATION - MODE S TRANSPONDER AIRCRAFT TYPE MODE STRAPPING - CHECK / MODIFICATION				MANDATORY		NOT APPLICABLE - BY PN TRANSPONDER
14-OCT-2014		MOS		22-SEP-2014			
		HRS/MSC	-	4658:50			
		AFL		4378			
EASA 2010-0003 R02 PARA (1)	VERIFY AIRCRAFT TYPE MODE STRAPPING CODE S SET TO '0' (ZERO) OR '1', AS DEFINED IN ROCKWELL-COLLINS SERVICE LETTER TDR-94() SIL 07-2.					MANDATORY	NOT APPLICABLE - BY PN TRANSPONDER
14-OCT-2014		MOS		22-SEP-2014			
		HRS/MSC	-	4658:50			
		AFL		4378			
EASA 2010-0003 R02 PARA (2)	EXEMPTIONS: DASSAULT AEROPLANES					MANDATORY	NOT APPLICABLE - BY PN TRANSPONDER
14-OCT-2014		MOS		22-SEP-2014			
		HRS/MSC	-	4658:50			
		AFL		4378			
EASA 2010-0003 R02 PARA (4)	EXEMPTIONS: SAAB 2000 AEROPLANES					MANDATORY	NOT APPLICABLE - BY PN TRANSPONDER
14-OCT-2014		MOS		22-SEP-2014			
		HRS/MSC	-	4658:50			
		AFL		4378			
EASA 2010-0003 R02 PARA (5)	EXEMPTIONS: BOMBARDIER AEROSPACE (CANADAIR) AEROPLANES: CL-600-2B16 (604 VARIANT) AND CL-600-2B19 (RJ100 AND RJ200)					MANDATORY	NOT APPLICABLE - BY PN TRANSPONDER
14-OCT-2014		MOS		22-SEP-2014			
		HRS/MSC	-	4658:50			
		AFL		4378			
EASA 2010-0003 R02 PARA (6)	EXEMPTIONS: CESSNA AIRCRAFT COMPANY AEROPLANES: CESSNA MODEL 525, 525A, 525B; AND CESSNA MODEL 525, 525A, 525B, 560; 560XL					MANDATORY	NOT APPLICABLE - BY PN TRANSPONDER
14-OCT-2014		MOS		22-SEP-2014			
		HRS/MSC	-	4658:50			
		AFL		4378			
EASA 2010-0003 R02 PARA (7)	EXEMPTIONS: PIAGGIO AERO INDUSTRIES AEROPLANES: P.180 (AVANTI) AND P.180 (AVANTI II)					MANDATORY	NOT APPLICABLE - BY PN TRANSPONDER
14-OCT-2014		MOS		22-SEP-2014			
		HRS/MSC	-	4658:50			
		AFL		4378			
EASA 2011-0239	APPLIANCE AD - NAVIGATION - RADIO ALTIMETER INDICATOR - MODIFICATION - SMS (TRADING AS COBHAM AVIONICS), FORMERLY NEC AERO.					MANDATORY	NOT APPLICABLE - ITEM NOT INSTALLED
		MOS		16-JAN-2012			
		HRS/MSC	A/R	4210:59			
		AFL		4009			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2012-0037	APPLIANCE AD - FIRE PROTECTION - HAND OPERATED FIRE EXTINGUISHER - MODIFICATION - KIDDE GRAVINGER (A HAMILTON SUNDSTRAND COMPANY)						NOT APPLICABLE - NA BY P/N
		MOS		05-MAY-2012			
		HRS/MSC	-	4272:33			
		AFL		4072			
EASA 2012-0038	APPLIANCE AD - EQUIPMENT & FURNISHINGS - PASSENGER SEAT BACKREST LINK - INSPECTION / REPLACEMENT - SICMA AERO SEAT						NOT APPLICABLE - NA BY OTHER MANUFACTURER
		MOS		06-MAY-2012			
		HRS/MSC	A/R	4272:33			
		AFL		4072			
EASA 2012-0254	APPLIANCE AD - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR -IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT				MANDATORY		NOT APPLICABLE - SUPERSEDED BY R1
13-DEC-2012		MOS		08-JAN-2013			
		HRS/MSC	-	4390:08			
		AFL		4159			
EASA 2012-0254 PARA (1)	INSPECT/CHECK OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR -IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT OXYGEN MASK REGULATOR TO IDENTIFY THE P/N AND S/N				MANDATORY		NOT APPLICABLE - SUPERSEDED BY R1
13-DEC-2012		DAYS		08-JAN-2013			
		HRS/MSC	-	4390:08			
		AFL		4159			
EASA 2012-0254 PARA (2.1)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR -IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT AFFECTED OXYGEN MASK REGULATOR				MANDATORY		NOT APPLICABLE - SUPERSEDED BY R1
13-DEC-2012		MOS		08-JAN-2013			
		HRS/MSC	-	4390:08			
		AFL		4159			
EASA 2012-0254 PARA (2.2)	AMEND OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR -IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT AIRCRAFT FLIGHT MANUAL (AFM)				MANDATORY		NOT APPLICABLE - SUPERSEDED BY R1
13-DEC-2012		MOS		08-JAN-2013			
		HRS/MSC	-	4390:08			
		AFL		4159			
EASA 2012-0254 PARA (3)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR -IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR WITH A SERVICEABLE PART				MANDATORY		NOT APPLICABLE - SUPERSEDED BY R1
13-DEC-2012		MOS		08-JAN-2013			
		HRS/MSC	-	4390:08			
		AFL		4159			
EASA 2012-0254 R01	APPLIANCE AD - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT				MANDATORY		NOT APPLICABLE - BY PN AND SN CREW OXYGEN MASK REGULATOR
21-DEC-2012		MOS		08-JAN-2013			
		HRS/MSC	-	4390:08			
		AFL		4159			
EASA 2012-0254 R01 PARA (1)	INSPECT OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT EACH FLIGHT CREW OXYGEN MASK REGULATOR TO IDENTIFY THE P/N AND S/N				MANDATORY		NOT APPLICABLE - BY PN AND SN CREW OXYGEN MASK REGULATOR
21-DEC-2012		DAYS		08-JAN-2013			
		HRS/MSC	-	4390:08			
		AFL		4159			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2012-0254 R01 PARA (2.1)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR WITH A SERVICEABLE PART					MANDATORY	NOT APPLICABLE - BY PN AND SN CREW OXYGEN MASK REGULATOR
21-DEC-2012		DAYS		08-JAN-2013			
		HRS/MSC	-	4390:08			
		AFL		4159			
EASA 2012-0254 R01 PARA (2.2)	AMEND OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT THE AIRCRAFT FLIGHT MANUAL (AFM) AND INSTALL A PLACARD					MANDATORY	NOT APPLICABLE - BY PN AND SN CREW OXYGEN MASK REGULATOR
21-DEC-2012		DAYS		08-JAN-2013			
		HRS/MSC	-	4390:08			
		AFL		4159			
EASA 2012-0254 R01 PARA (3)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR					MANDATORY	NOT APPLICABLE - BY PN AND SN CREW OXYGEN MASK REGULATOR
21-DEC-2012		MOS		08-JAN-2013			
		HRS/MSC	-	4390:08			
		AFL		4159			
EASA 2013-0020	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - SUPERSEDED BY R1
14-FEB-2013		MOS		20-AUG-2013			
		HRS/MSC	-	4471:29			
		AFL		4230			
EASA 2013-0020 PARA (1)	INSPECT EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER					MANDATORY	NOT APPLICABLE - SUPERSEDED BY R1
14-FEB-2013		MOS		20-AUG-2013			
		HRS/MSC	-	4471:29			
		AFL		4230			
EASA 2013-0020 PARA (2)	VERIFY EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD					MANDATORY	NOT APPLICABLE - SUPERSEDED BY R1
14-FEB-2013		MOS		20-AUG-2013			
		HRS/MSC	-	4471:29			
		AFL		4230			
EASA 2013-0020 PARA (3)	REMOVE EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE					MANDATORY	NOT APPLICABLE - SUPERSEDED BY R1
14-FEB-2013		MOS		20-AUG-2013			
		HRS/MSC	-	4471:29			
		AFL		4230			
EASA 2013-0020 R01	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - SUPERSEDED BY R2
12-MAR-2013		MOS		20-AUG-2013			
		HRS/MSC	-	4471:29			
		AFL		4230			
EASA 2013-0020 R01 PARA (1)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER					MANDATORY	NOT APPLICABLE - SUPERSEDED BY R2
12-MAR-2013		MOS		20-AUG-2013			
		HRS/MSC	-	4471:29			
		AFL		4230			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2013-0020 R01 PARA (2)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD					MANDATORY	NOT APPLICABLE - SUPERSEDED BY R2
12-MAR-2013		MOS HRS/MSC - (s) AFL		20-AUG-2013 4471:29 4230			
EASA 2013-0020 R01 PARA (3)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE					MANDATORY	NOT APPLICABLE - SUPERSEDED BY R2
12-MAR-2013		MOS HRS/MSC - (s) AFL		20-AUG-2013 4471:29 4230			
EASA 2013-0020 R01 PARA (4)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD.					MANDATORY	NOT APPLICABLE - SUPERSEDED BY R2
12-MAR-2013		MOS HRS/MSC - AFL		20-AUG-2013 4471:29 4230			
EASA 2013-0020 R02	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT					MANDATORY	COMPLIED WITH - FOUND NO EVIDENCE OR REPAIR, MODIFICATION
11-JUL-2013		MOS HRS/MSC - AFL		20-AUG-2013 4471:29 4230			
EASA 2013-0020 R02 PARA (1)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER					MANDATORY	COMPLIED WITH - FOUND NO EVIDENCE OR REPAIR, MODIFICATION
11-JUL-2013		MOS HRS/MSC - AFL		20-AUG-2013 4471:29 4230			
EASA 2013-0020 R02 PARA (2)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD					MANDATORY	COMPLIED WITH - FOUND NO EVIDENCE OR REPAIR, MODIFICATION
11-JUL-2013		MOS HRS/MSC - (s) AFL		20-AUG-2013 4471:29 4230			
EASA 2013-0020 R02 PARA (3)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE					MANDATORY	COMPLIED WITH - FOUND NO EVIDENCE OR REPAIR, MODIFICATION
11-JUL-2013		MOS HRS/MSC - (s) AFL		20-AUG-2013 4471:29 4230			
EASA 2013-0020 R02 PARA (4)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD					MANDATORY	COMPLIED WITH - FOUND NO EVIDENCE OR REPAIR, MODIFICATION
11-JUL-2013		MOS HRS/MSC - AFL		20-AUG-2013 4471:29 4230			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2013-0020 R03	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - NOT MAINTAINED OR REPAIRED AFTER 28 SEP 2003
28-MAR-2014		MOS HRS/MSC - AFL		08-APR-2014 4566:55 4303			
EASA 2013-0020 R03 PARA (1)	INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER					MANDATORY	NOT APPLICABLE - NOT MAINTAINED OR REPAIRED AFTER 28 SEP 2003
28-MAR-2014		MOS HRS/MSC - AFL		08-APR-2014 4566:55 4303			
EASA 2013-0020 R03 PARA (2)	VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD					MANDATORY	NOT APPLICABLE - NOT MAINTAINED OR REPAIRED AFTER 28 SEP 2003
28-MAR-2014		MOS HRS/MSC - (s) AFL		08-APR-2014 4566:55 4303			
EASA 2013-0020 R03 PARA (3)	REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE					MANDATORY	NOT APPLICABLE - NOT MAINTAINED OR REPAIRED AFTER 28 SEP 2003
28-MAR-2014		MOS HRS/MSC - (s) AFL		08-APR-2014 4566:55 4303			
EASA 2013-0020 R03 PARA (4)	AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD					MANDATORY	NOT APPLICABLE - NOT MAINTAINED OR REPAIRED AFTER 28 SEP 2003
28-MAR-2014		MOS HRS/MSC - AFL		08-APR-2014 4566:55 4303			
EASA 2013-0020 R04	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - NOT MAINTAINED / REPAIRED AFTER SEP 2003
11-JUL-2014		MOS HRS/MSC - AFL		30-SEP-2014 4661:49 4380			
EASA 2013-0020 R04 PARA (1)	INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER					MANDATORY	NOT APPLICABLE - NOT MAINTAINED / REPAIRED AFTER SEP 2003
11-JUL-2014		MOS HRS/MSC - AFL		30-SEP-2014 4661:49 4380			
EASA 2013-0020 R04 PARA (2)	VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD					MANDATORY	NOT APPLICABLE - NOT MAINTAINED / REPAIRED AFTER SEP 2003
11-JUL-2014		MOS HRS/MSC - (s) AFL		30-SEP-2014 4661:49 4380			
EASA 2013-0020 R04 PARA (3)	REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE					MANDATORY	NOT APPLICABLE - NOT MAINTAINED / REPAIRED AFTER SEP 2003
11-JUL-2014		MOS HRS/MSC - (s) AFL		30-SEP-2014 4661:49 4380			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2013-0020 R04 PARA (4)	AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD					MANDATORY	NOT APPLICABLE - NOT MAINTAINED / REPAIRED AFTER SEP 2003
11-JUL-2014		MOS		30-SEP-2014			
		HRS/MSC	-	4661:49			
		AFL		4380			
EASA 2014-0019	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR - MODIFICATION AIRCRAFT FLIGHT MANUAL - AMENDMENT (SUPERSEDED BY EASA 2014-0095)					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
31-JAN-2014		MOS		07-FEB-2014			
		HRS/MSC	-	4561:51			
		AFL		4299			
EASA 2014-0019 PARA (1)	AMEND THE AFM OF THE AFFECTED AIRCRAFT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
31-JAN-2014		DAYS		07-FEB-2014			
		HRS/MSC	-	4561:51			
		AFL		4299			
EASA 2014-0019 PARA (2)	REPLACE THE SYSTEM INTERFACE UNIT P/N 503-24-() OR 503-42-()					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
31-JAN-2014		MOS		07-FEB-2014			
		HRS/MSC	-	4561:51			
		AFL		4299			
EASA 2014-0019 PARA (3)	DO NOT INSTALL A HR SMITH (TECHNICAL DEVELOPMENTS) CPI SYSTEM SERIES 15-503-134 OR 15-503-134-1 EQUIPPED WITH CONTROL PANEL P/N 503-22-(), BEACON RELEASE UNIT P/N 503-21 AND SYSTEM INTERFACE UNIT P/N 503-24-() OR P/N 503-42-(), EXCLUDING SYSTEM INTERFACE UNIT P/N 503-24-A, OR 503-24-()A, OR 503-24-G, OR 503-24-()G, OR 503-42-A OR 503-42-()A OR 503-42-G OR 503-42-()G, ON AN AIRCRAFT, UNLESS IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
31-JAN-2014		MOS		07-FEB-2014			
		HRS/MSC	-	4561:51			
		AFL		4299			
EASA 2014-0019 PARA (4)	REMOVE AFM AMENDMENT AND PLACARD AS REQUIRED BY PARAGRAPH (1) OF THIS AD					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
31-JAN-2014		MOS		07-FEB-2014			
		HRS/MSC	-	4561:51			
		AFL		4299			
EASA 2014-0088	APPLIANCE AD - COMMUNICATIONS - COCKPIT VOICE RECORDER - REPLACEMENT					MANDATORY	NOT APPLICABLE - BY PN CVR
29-APR-2014		MOS		20-MAY-2014			
		HRS/MSC	-	4573:18			
		AFL		4308			
EASA 2014-0088 PARA (1)	REMOVE THE TEAM CVR P/N AP71232101 OR P/N AP71231101, AS APPLICABLE, FROM THE AIRCRAFT AND, DEPENDING ON OPERATIONAL REGULATIONS, INSTALL A SERVICEABLE CVR IN ACCORDANCE WITH APPROVED AIRCRAFT MODIFICATION INSTRUCTIONS					MANDATORY	NOT APPLICABLE - BY PN CVR
29-APR-2014		MOS		20-MAY-2014			
		HRS/MSC	-	4573:18			
		AFL		4308			
EASA 2014-0088 PARA (2)	DO NOT INSTALL ON ANY AIRCRAFT A TEAM CVR P/N AP71232101 OR P/N AP71231101, AS REQUIRED BY PARAGRAPH (2.1) OR (2.2) OF THIS AD, AS APPLICABLE					MANDATORY	NOT APPLICABLE - BY PN CVR
29-APR-2014		MOS		20-MAY-2014			
		HRS/MSC	-	4573:18			
		AFL		4308			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2014-0095	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR - MODIFICATION AIRCRAFT FLIGHT MANUAL - AMENDMENT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
07-MAY-2014		MOS HRS/MSC - AFL		20-MAY-2014 4573:18 4308			
EASA 2014-0095 PARA (1)	INSTALL A PLACARD "DO NOT USE TRANSMIT OVER WATER" NEXT TO THE CPI CONTROL PANEL/AMEND THE AFM OF THE AIRCRAFT		DAYS HRS/MSC - AFL	20-MAY-2014 4573:18 4308		MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
07-MAY-2014							
EASA 2014-0095 PARA (2)	INCORPORATION OF APPENDIX A OF THIS AD INTO THE EMERGENCY PROCEDURES SECTION OF THE AFM OF THE AIRCRAFT IS AN ACCEPTABLE METHOD TO COMPLY WITH THE REQUIREMENT OF PARAGRAPH (1.2) OF THIS AD					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
07-MAY-2014		MOS HRS/MSC - AFL		20-MAY-2014 4573:18 4308			
EASA 2014-0095 PARA (3)	REPLACE THE SYSTEM INTERFACE UNIT P/N 503-24-() (INCLUDING 503-24) OR P/N 503-42-() (INCLUDING 503-42) WITH AN IMPROVED PART P/N 503-24-A, OR P/N 503-24-()A, OR P/N 503-24-G, OR P/N 503-24-()G, OR P/N 503-42-A OR P/N 503-42-()A OR P/N 503-42-G OR P/N 503-42-()G (THAT INCORPORATES AUTOMATIC CPI DEPLOYMENT AFTER MANUAL ACTIVATION) IN ACCORDANCE WITH AN APPROVED AIRCRAFT MAINTENANCE INSTRUCTION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
07-MAY-2014		MOS HRS/MSC - (s) AFL		20-MAY-2014 4573:18 4308			
EASA 2014-0095 PARA (5)	REMOVE THE AFM AMENDMENT AND PLACARD AS REQUIRED BY PARAGRAPH (1) OF THIS AD					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
07-MAY-2014		MOS HRS/MSC - AFL		20-MAY-2014 4573:18 4308			
EASA 2014-0095 R01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR - MODIFICATION AIRCRAFT FLIGHT MANUAL - AMENDMENT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
12-MAY-2014		MOS HRS/MSC - AFL		02-JUN-2014 4582:32 4317			
EASA 2014-0095 R01 PARA (1)	INSTALL A PLACARD "DO NOT USE TRANSMIT OVER WATER" NEXT TO THE CPI CONTROL PANEL/AMEND THE AFM OF THE AIRCRAFT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
12-MAY-2014		MOS HRS/MSC - AFL		02-JUN-2014 4582:32 4317			
EASA 2014-0095 R01 PARA (2)	INCORPORATION OF APPENDIX A OF THIS AD INTO THE EMERGENCY PROCEDURES SECTION OF THE AFM OF THE AIRCRAFT IS AN ACCEPTABLE METHOD TO COMPLY WITH THE REQUIREMENT OF PARAGRAPH (1.2) OF THIS AD					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
12-MAY-2014		MOS HRS/MSC - AFL		02-JUN-2014 4582:32 4317			
EASA 2014-0095 R01 PARA (3)	REPLACE THE SYSTEM INTERFACE UNIT P/N 503-24-() (INCLUDING 503-24) OR P/N 503-42-() (INCLUDING 503-42) WITH AN IMPROVED PART P/N 503-24-A, OR P/N 503-24-()A, OR P/N 503-24-G, OR P/N 503-24-()G, OR P/N 503-42-A OR P/N 503-42-()A OR P/N 503-42-G OR P/N 503-42-()G (THAT INCORPORATES AUTOMATIC CPI DEPLOYMENT AFTER MANUAL ACTIVATION) IN ACCORDANCE WITH AN APPROVED AIRCRAFT MAINTENANCE INSTRUCTION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
12-MAY-2014		MOS HRS/MSC - (s) AFL		02-JUN-2014 4582:32 4317			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2014-0095 R01 PARA (4)	DO NOT INSTALL A HR SMITH (TECHNICAL DEVELOPMENTS) CPI SYSTEM SERIES 15-503-134 OR 15-503-134-1 EQUIPPED WITH CONTROL PANEL P/N 503-22-(), BEACON RELEASE UNIT P/N 503-21 AND SYSTEM INTERFACE UNIT P/N 503-24-() (INCLUDING 503-24) OR P/N 503-42-() (INCLUDING 503-42) EXCLUDING SYSTEM INTERFACE UNIT P/N 503-24-A OR P/N 503-24-()-A OR P/N 503-24-G OR P/N 503-24-()-G OR P/N 503-42-A OR P/N 503-42-()-A OR P/N 503-42-G OR P/N 503-42-()-G ON AN AIRCRAFT UNLESS IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
12-MAY-2014	MOS HRS/MSC - AFL			02-JUN-2014 4582:32 4317			
EASA 2014-0095 R01 PARA (5)	REMOVE THE AFM AMENDMENT AND PLACARD AS REQUIRED BY PARAGRAPH (1) OF THIS AD					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
12-MAY-2014	MOS HRS/MSC - AFL			02-JUN-2014 4582:32 4317			
EASA 2014-0142	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE - IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - SUPERSEDED BY AD 2014-0142 R1
18-JUN-2014	MOS HRS/MSC - AFL			23-JUN-2014			
EASA 2014-0142 PARA (1)	ACCOMPLISH ACCOMPLISH THE ACTIONS AS SPECIFIED IN PARAGRAPHS (1.1) AND (1.2) OF THIS AD - DETERMINE THE DATE OF MANUFACTURING / REPLACE THE HARNESS INFLATION HOSE P/N 445952 WITH A SERVICEABLE PART, OR REMOVE THE INFLATABLE HARNESS FROM THE MASK REGULATOR AND REPLACE IT WITH A SERVICEABLE HARNESS					MANDATORY	NOT APPLICABLE - SUPERSEDED BY AD 2014-0142 R1
18-JUN-2014	MOS HRS/MSC - AFL			23-JUN-2014			
EASA 2014-0142 PARA (2)	ACCOMPLISH AN OXYGEN MASK REGULATOR EQUIPPED WITH A P/N MXH21-1 INFLATABLE HARNESS HAVING A DMF CODE OF NOVEMBER 2008 (0845-S OR 08/45-S) OR EARLIER, AND THOSE WITH A DMF OF JANUARY 2011 (1101-S OR 11/01-S) OR LATER, IS EXCLUDED FROM THE INSPECTION AND REPLACEMENT REQUIREMENTS OF PARAGRAPH (1) OF THIS AD					MANDATORY	NOT APPLICABLE - SUPERSEDED BY AD 2014-0142 R1
18-JUN-2014	MOS HRS/MSC - AFL			23-JUN-2014			
EASA 2014-0142 PARA (3)	ACCOMPLISH IT IS ALLOWED TO INSTALL ON AN AEROPLANE A FLIGHT CREW OXYGEN MASK REGULATOR, HAVING A P/N AS IDENTIFIED IN SECTION 1.A.(1) OF ZODIAC AEROTECHNIKS SB MC10-35-274, PROVIDED IT HAS BEEN DETERMINED THAT A P/N MXH21-31 INFLATABLE HARNESS IS INSTALLED, OR THAT THE P/N MXH21-1 INFLATABLE HARNESS INSTALLED ON THAT FLIGHT CREW OXYGEN MASK REGULATOR HAS BEEN CORRECTED, AS REQUIRED BY THIS AD.					MANDATORY	NOT APPLICABLE - SUPERSEDED BY AD 2014-0142 R1
18-JUN-2014	MOS HRS/MSC - AFL			23-JUN-2014			
EASA 2014-0142 R01 PARA (1)	ACCOMPLISH ACCOMPLISH THE ACTIONS AS SPECIFIED IN PARAGRAPHS (1.1) AND (1.2) OF THIS AD - DETERMINE THE DATE OF MANUFACTURING / REPLACE THE HARNESS INFLATION HOSE P/N 445186 OR P/N 445952, AS APPLICABLE, WITH A SERVICEABLE PART, OR REMOVE THE INFLATABLE HARNESS FROM THE MASK REGULATOR AND REPLACE IT WITH A SERVICEABLE HARNESS					MANDATORY	NOT APPLICABLE - CREW OXYGEN MASKS WITH P/N MC10-16-100 ARE INSTALLED
18-JUN-2014	MOS HRS/MSC - AFL			30-JAN-2015 4675:30 4392			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2014-0142 R01 PARA (2)	ACCOMPLISH AN OXYGEN MASK REGULATOR EQUIPPED WITH A P/N MXH20-1 OR P/N MXH21-1 INFLATABLE HARNESS HAVING A DMF CODE OF NOVEMBER 2008 (0845-S OR 08/45-S) OR EARLIER, AND THOSE WITH A DMF OF JANUARY 2011 (1101-S OR 11/01-S) OR LATER, IS EXCLUDED FROM THE INSPECTION AND REPLACEMENT REQUIREMENTS OF PARAGRAPH (1) OF THIS AD					MANDATORY	NOT APPLICABLE - CREW OXYGEN MASKS WITH PN MC10-16-100 ARE INSTALLED
18-JUN-2014		MOS		30-JAN-2015			
		HRS/MSC	-	4675:30			
		AFL		4392			
EASA 2014-0142 R01 PARA (3)	ACCOMPLISH IT IS ALLOWED TO INSTALL ON AN AEROPLANE A FLIGHT CREW OXYGEN MASK REGULATOR, HAVING A P/N AS IDENTIFIED IN SECTION 1.A.(1) OF ZODIAC AEROTECHNICS SB MC10-35-274, PROVIDED IT HAS BEEN DETERMINED THAT A P/N MXH21-31 INFLATABLE HARNESS IS INSTALLED, OR THAT THE P/N MXH20-1 OR P/N MXH21-1 INFLATABLE HARNESS INSTALLED ON THAT FLIGHT CREW OXYGEN MASK REGULATOR HAS BEEN CORRECTED, AS REQUIRED BY THIS AD					MANDATORY	NOT APPLICABLE - CREW OXYGEN MASKS WITH PN MC10-16-100 ARE INSTALLED
18-JUN-2014		MOS		30-JAN-2015			
		HRS/MSC	-	4675:30			
		AFL		4392			
EASA 2015-0093 PARA (1)	AMEND THE AFM OF THE AIRCRAFT BY INSERTING A TEMPORARY REVISION (TR) TO THE AFM (SUPPLEMENT)					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
10-JUN-2015		DAYS		30-JUN-2015			
		HRS/MSC	-	4794:57			
		AFL		4515			
EASA 2015-0093 PARA (2)	MODIFY THE AIRCRAFT BY REPLACING EACH AHRS UNIT HAVING A P/N SPECIFIED AS 'OLD' IN TABLE 2 OF THIS AD WITH A MODIFIED UNIT, HAVING A P/N SPECIFIED AS 'NEW' IN TABLE 2 OF THIS AD					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
10-JUN-2015		MOS		30-JUN-2015			
		HRS/MSC	-	4794:57			
		AFL		4515			
EASA 2016-0024	APPLIANCE AD - FIRE PROTECTION - OPTICAL AND AMBIENT SMOKE DETECTORS - IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
01-FEB-2016		MOS		08-FEB-2016			
		HRS/MSC	-	4915:07			
		AFL		4609			
EASA 2016-0024 PARA (1)	INSPECT EACH SIEMENS SMOKE DETECTOR TO DETERMINE WHETHER IT IS AN Affected PART					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
01-FEB-2016		MOS		08-FEB-2016			
		HRS/MSC	-	4915:07			
		AFL		4609			
EASA 2016-0024 PARA (2.1)	REPLACE CARGO COMPARTMENT SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 1 OR TABLE 2					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
01-FEB-2016		MOS		08-FEB-2016			
		HRS/MSC	-	4915:07			
		AFL		4609			
EASA 2016-0024 PARA (2.2)	REPLACE PASSENGER, CABIN OR ANY OTHER ON BOARD LOCATION SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 3					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
01-FEB-2016		MOS		08-FEB-2016			
		HRS/MSC	-	4915:07			
		AFL		4609			
EASA 2016-0024 PARA (2.3)	REPLACE REPAIRED SMOKE DETECTOR IDENTIFIED IN APPENDIX 1					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
01-FEB-2016		MOS		08-FEB-2016			
		HRS/MSC	-	4915:07			
		AFL		4609			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2016-0024 PARA (3)	FROM THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL ON ANY AEROPLANE AN AFFECTED P/N SMOKE DETECTOR UNLESS THE UNIT (GMC ONLY) IS MARKED 'SIL PMC-26-002'					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
01-FEB-2016		MOS		08-FEB-2016			
		HRS/MSC	-	4915:07			
		AFL		4609			
EASA 2016-0044	APPLIANCE AD - ATA 26 - FIRE PROTECTION - ENGINE AND AUXILIARY POWER UNIT AUTOMATIC FIRE EXTINGUISHERS - INSPECTION/OVERHAUL					MANDATORY	NOT APPLICABLE - BY PN FIRE EXTINGUISHER
22-MAR-2016		MOS		29-FEB-2016			
		HRS/MSC	-	4940:20			
		AFL		4631			
EASA 2016-0044 PARA (1)	INSPECT EACH FIRE EXTINGUISHER, EXCEPT THOSE HAVING P/N 57333 SERIES, INSTALLED ON BAE146 AND RJ AEROPLANES, AND THOSE HAVING P/N 57183 SERIES, INSTALLED ON ATP AEROPLANES, AND DEPENDING ON FINDINGS, ACCOMPLISH CORRECTIVE ACTIONS IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SB 26-080 REVISION 1					MANDATORY	NOT APPLICABLE - BY PN FIRE EXTINGUISHER
22-MAR-2016		MOS		29-FEB-2016			
		HRS/MSC	-	4940:20			
		AFL		4631			
EASA 2016-0044 PARA (2)	ACCOMPLISHMENT OF AN OVERHAUL (SEE NOTE 2 OF THIS AD) OF A FIRE EXTINGUISHER BY KIDDE GRAVINGER OR HUGEN, OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SIL 01-10 OR IN ACCORDANCE WITH KG CMM 26-21-40 REVISION 14 OR LATER OR KG CMM 26-21-52 REVISION 13 OR LATER (AS APPLICABLE TO FIRE EXTINGUISHER P/N) IS ACCEPTABLE TO COMPLY WITH THE REQUIREMENT OF PARAGRAPH (1).					MANDATORY	NOT APPLICABLE - BY PN FIRE EXTINGUISHER
22-MAR-2016		MOS		29-FEB-2016			
		HRS/MSC	-	4940:20			
		AFL		4631			
EASA 2016-0044 PARA (3)	FROM THE EFFECTIVE DATE OF THIS AD DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED FIRE EXTINGUISHER, UNLESS IT IS NEW, OR HAS PASSED AN INSPECTION IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SB 26-080 REVISION 1, OR IT HAS BEEN OVERHAULED (SEE NOTE 2) BY KG, OR BY HUGEN OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SIL 01-10 OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG CMM 26-21-40 REVISION 14, OR OF KG CMM 26-21-52 REVISION 13, AS APPLICABLE TO FIRE EXTINGUISHER P/N					MANDATORY	NOT APPLICABLE - BY PN FIRE EXTINGUISHER
22-MAR-2016		MOS		29-FEB-2016			
		HRS/MSC	-	4940:20			
		AFL		4631			
EASA 2019-0235	APPLIANCE AD - EQUIPMENT / FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER - INSPECTION / MODIFICATION / REPLACEMENT					MANDATORY	COMPLIED WITH - WORKS PERFORMED I.A.W. CESSNA 56X MM.
04-OCT-2019		MOS		13-DEC-2019			
		HRS/MSC	- (s)	5416			
		AFL		4960			
EASA 2019-0235 PARA (5)	REMOVE THE AFFECTED PART FROM SERVICE IAW THE INSTRUCTIONS OF SECTION 7 OF THE SB FOR THE PURPOSE OF IN-SHOP MODIFICATION					MANDATORY	NOT APPLICABLE
04-OCT-2019		MOS		13-DEC-2019			
		HRS/MSC	-	5416			
		AFL		4960			
EASA 2019-0235 PARA (6)	IN-SHOP CORRECTION OF AN AFFECTED PART OR MODIFICATION INTO A SERVICEABLE PART IAW THE INSTRUCTIONS OF THE SB CONSTITUTES TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS AND TESTING AS REQUIRED BY THIS AD FOR THAT PART					MANDATORY	NOT APPLICABLE
04-OCT-2019		MOS		13-DEC-2019			
		HRS/MSC	- (s)	5416			
		AFL		4960			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2019-0235 PARA (9)	DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED PART THAT HAS ACCUMULATED 10 YEAR TIS OR MORE					MANDATORY	NOT APPLICABLE
04-OCT-2019	MOS HRS/MSC - (s) AFL			13-DEC-2019 5416 4960			
FAA 1974-20-10	APPLIANCE AD - EQUIPMENT AND FURNISHINGS - TO PREVENT CHEMICAL CORROSION RESULTING IN EITHER FAILURE OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) TO OPERATE OR INADVERTENT ACTIVATION, JAMMING THE EMERGENCY FREQUENCIES OF 121.5 MHZ AND 243.0 MHZ					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
	DAYS HRS/MSC - (s) AFL			08-FEB-2019 5066:42 4739			
FAA 1995-22-01	APPLIANCE AD - AEROSPACE LIGHTING POWER UNIT					MANDATORY	COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED
	MOS HRS/MSC A/R AFL			17-FEB-2002 17 0			
FAA 1997-05-03 R01	APPLIANCE AD - GNX-XLS AND GNS-XL GPS					MANDATORY	COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED
	MOS HRS/MSC A/R AFL			17-FEB-2002 17 0			
FAA 1998-25-10	APPLIANCE AD - AIRCRAFT BELT INSPECTION					MANDATORY	COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED
	MOS HRS/MSC A/R AFL			17-FEB-2002 17 0			
FAA 2002-13-07	APPLIANCE AD - HONEYWELL, INC. PART NUMBER HG1075AB05 AND HG1075GB05 INERTIAL REFERENCE UNITS					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
39-12795 09-AUG-2002	MOS HRS/MSC - (s) AFL			08-FEB-2019 5066:42 4739			
FAA 2002-14-19	APPLIANCE AD - ROCKWELL COLLINS, INC. ADC-85, ADC-85A, ADC-850D, AND ADC-850F AIR DATA COMPUTERS					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
39-12819 23-AUG-2002	MOS HRS/MSC - (s) AFL			08-FEB-2019 5066:42 4739			
FAA 2002-20-09	APPLIANCE AD - ROCKWELL COLLINS, INC. AFD-3010 ADAPTIVE FLIGHT DISPLAY UNITS					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
39-12906 12-NOV-2002	MOS HRS/MSC - (s) AFL			08-FEB-2019 5066:42 4739			
FAA 2002-22-13	APPLIANCE AD - NAVIGATION - REPLACEMENT OF ROCKWELL COLLINS FMC-4200, FMC-5000 AND FMC-6000 COMPUTERS TO PREVENT THE FMC FROM RETAINING ORIGINAL INFORMATION WHEN AN EDIT IS MADE TO A PROCEDURE OR FLIGHT PLAN						NOT APPLICABLE - COMPONENTS NOT INSTALLED
	MOS HRS/MSC - (s) AFL			08-FEB-2019 5066:42 4739			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2003-04-06	APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM					SUPERSEDED	COMPLIED WITH
		MOS HRS/MSC AFL		09-MAY-2003 641			
FAA 2003-26-14	APPLIANCE AD - KIDDE AEROSPACE HAND HELD BOTTLE					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
		MOS HRS/MSC AFL		08-FEB-2019 5066:42 4739			
FAA 2005-11-05	APPLIANCE AD - VACUUM - REPLACE THE AIRPLANE FLIGHT MANUAL SUPPLEMENT (AFMS) IN THE AIRPLANE FLIGHT MANUAL WITH THE APPROPRIATE REVISION AND INSTALL PLACARDS AS DEFINED IN THE AFMS, UPGRADE THE MODEL SVS I OR SVS IA SVS TO THE MODEL VI SVS					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
18-JUL-2005		MOS HRS/MSC AFL		08-FEB-2019 5066:42 4739			
FAA 2005-11-05 PARA (1)	INCORPORATE THE AIRPLANE FLIGHT MANUAL SUPPLEMENT (AFMS) IN THE AIRPLANE FLIGHT MANUAL WITH THE APPROPRIATE REVISION IN THE FAA-APPROVED AIRPLANE FLIGHT MANUAL (AFM).					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
18-JUL-2005		MOS HRS/MSC AFL		08-FEB-2019 5066:42 4739			
FAA 2005-11-05 PARA (2)	INSTALL PLACARDS DESCRIBED IN THE AFMS					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
18-JUL-2005		MOS HRS/MSC AFL		08-FEB-2019 5066:42 4739			
FAA 2005-11-05 PARA (3)	UPGRADE THE MODEL SVS I OR SVS IA SVS TO THE MODEL VI SVS, INSTALL THE APPROPRIATE PLACARDS, AND ADD THE INSTALLATION REPORT INCLUDING THE INSTRUCTIONS FOR CONTINUED AIRWORTHINESS (ICA) TO THE MAINTENANCE SCHEDULE FOR THE AIRCRAFT.					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
18-JUL-2005		MOS HRS/MSC AFL		08-FEB-2019 5066:42 4739			
FAA 2006-04-04	APPLIANCE AD - IDENTIFY AND PROVIDE CORRECTIVE ACTION FOR A POTENTIALLY INOPERATIVE SMOKE DETECTOR AND TO ENSURE THAT THE FLIGHTCREW IS ALERTED IN THE EVENT OF A FIRE.					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
24-MAR-2006		MOS HRS/MSC AFL		08-FEB-2019 5066:42 4739			
FAA 2006-16-18	APPLIANCE AD - SANDEL AVI MOD ST3400 TAWS/RM					MANDATORY	NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED
17-OCT-2006		MOS HRS/MSC AFL		10-OCT-2006 2842			
FAA 2006-19-04	APPLIANCE AD - HONEYWELL RCZ COMM & XPDRS					MANDATORY	NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED
17-OCT-2006		MOS HRS/MSC AFL		10-OCT-2006 2842			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2006-22-05	APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM					MANDATORY	NOT APPLICABLE - NOT APPLICABLE
		MOS HRS/MSC AFL		12-JAN-2007 2959			
FAA 2007-19-12	APPLIANCE AD - SICMA AERO SEATS - 50XXX					AIRWORTHINESS	NOT APPLICABLE - COMPONENTS NOT INSTALLED
26-OCT-2007		MOS HRS/MSC AFL		08-FEB-2019 5066:42 4739			
FAA 2007-19-13	APPLIANCE AD - B/E AEROSPACE SKYLUXE SEATS					AIRWORTHINESS	NOT APPLICABLE - COMPONENTS NOT INSTALLED
03-OCT-2007		MOS HRS/MSC AFL		08-FEB-2019 5066:42 4739			
FAA 2007-26-11	APPLIANCE AD - HIGH-PRESSURE OXYGEN CYLINDER TEARING WITH SUDDEN EMPTYING					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
		MOS HRS/MSC AFL		08-FEB-2019 5066:42 4739			
FAA 2008-02-06	APPLIANCE AD - AUTO FLIGHT - INSPECT THE GSM 85 SERVO GEARBOX FOR FOREIGN OBJECT DEBRIS AND RETURN THE UNIT TO THE MANUFACTURER FOR REPLACEMENT IF YOU FIND DEBRIS					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
26-FEB-2008		MOS HRS/MSC AFL		08-FEB-2019 5066:42 4739			
FAA 2008-02-06 PARA (E)(1)	CHECK THE SERIAL TAG OF THE INSTALLED GSM 85 SERVO GEARBOX UNIT TO DETERMINE THE MOD LEVEL					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
26-FEB-2008		MOS HRS/MSC AFL		08-FEB-2019 5066:42 4739			
FAA 2008-02-06 PARA (E)(2)	INSPECT THE SERVO GEARBOX FOR FOREIGN OBJECT DEBRIS (IF THE SERIAL TAG ON THE GSM 85 SERVO GEARBOX FOR P/NS SPECIFIED IN PARA (E)(1) IS NOT MARKED AT MOD LEVEL 1 OR MOD LEVEL 3)					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
26-FEB-2008		MOS HRS/MSC AFL		08-FEB-2019 5066:42 4739			
FAA 2008-02-06 PARA (E)(3)	REMOVE AND RETURN THE GSM 85 SERVO GEARBOX TO THE MANUFACTURER FOR REPLACEMENT (IF FOREIGN OBJECT DEBRIS IS FOUND DURING THE INSPECTION REQUIRED IN PARA (E)(2))					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
26-FEB-2008		MOS HRS/MSC AFL		08-FEB-2019 5066:42 4739			
FAA 2009-05-05	APPLIANCE AD - INDICATING AND RECORDING - CHECK OF THE MAINTENANCE RECORDS AND INSPECTION OF THE PFD (IF NECESSARY) TO DETERMINE IF AN AFFECTED SERIAL NUMBER PFD IS INSTALLED AND INCORPORATE (IF NECESSARY) OPERATIONAL LIMITATIONS.					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
03-APR-2009		MOS HRS/MSC AFL		08-FEB-2019 5066:42 4739			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2009-05-05 PARA (F)(1)	INCORPORATE THE OPERATIONAL LIMITATIONS					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
03-APR-2009		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2009-05-05 PARA (F)(2)	INSPECT FOR A LABEL MARKED "DEVIATION 08-19A" ON THE EXTERIOR OF THE PFD NEAR THE TSO LABEL OR A "MOD 52" MARKING.					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
03-APR-2009		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2009-05-05 PARA (F)(3)	REMOVE REMOVE THE LIMITATIONS REQUIRED BY PARA (F)(1) AND AD 2008-06-28 R1 (IF PFD PASSES THE TEST REQUIRED IN PARAGRAPH (F)(2)(II))					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
03-APR-2009		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2009-05-05 PARA (F)(4)	REMOVE THE PFD, INSTALL A PFD THAT HAS PASSED THE AIR DATA SYSTEM PERFORMANCE VERIFICATION TEST AND REMOVE THE LIMITATIONS REQUIRED BY PARA (F)(1)					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
03-APR-2009		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2009-05-08	APPLIANCE AD - NAVIGATION - UPGRADE THE SYSTEM SOFTWARE OF ANY TRIMBLE OR FREEFLIGHT SYSTEMS 2101 I/O APPROACH PLUS GPS NAVIGATION SYSTEM, PART NUMBER (P/N) 81440-XX-241E, 81440-XX-241F, OR 81440-XX-241G					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2009-08-01	APPLIANCE AD - NAVIGATION - IDENTIFY Affected COMPUTERS BY PART NUMBER AND SOFTWARE MODIFICATION LEVEL AND REVISE THE LIMITATIONS SECTION OF APPLICABLE AIRPLANE FLIGHT MANUALS & UPGRADING NEW SOFTWARE					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
14-MAY-2009		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2009-08-01 PARA (F)	DETERMINE IF THE INSTALLED NZ-2000 NAVIGATION COMPUTERS AND IC-800 OR IC-800E INTEGRATED AVIONICS COMPUTERS SERVING FMSS HAVE COMPUTER PART NUMBERS AND SOFTWARE MODIFICATION LEVELS IDENTIFIED IN HONEYWELL TECHNICAL NEWSLETTER A23-6111-008 R1					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
14-MAY-2009		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2009-08-01 PARA (G)	REVISE THE LIMITATIONS SECTION OF THE APPLICABLE AFM					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
14-MAY-2009		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2009-08-01 PARA (H)	UPGRADE THE APPLICABLE SOFTWARE AS SPECIFIED IN TABLE 2 OF THIS AD					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
14-MAY-2009		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2009-21-10 R01	APPLIANCE AD - INSPECT TO DETERMINE THE SERIAL NUMBER OF THE OXYGEN CYLINDER ASSEMBLIES INSTALLED IN THE AIRPLANE				MANDATORY		NOT APPLICABLE - COMPONENTS NOT INSTALLED
		MOS		08-FEB-2019			
		HRS/MSC	-	5066:42			
		AFL		4739			
FAA 2010-01-03	APPLIANCE AD - IDENTIFY AND REMOVE FROM SERVICE ALL AFFECTED FIRE EXTINGUISHERS AND REPLACE WITH SERVICABLE UNITS				MANDATORY		NOT APPLICABLE - COMPONENTS NOT INSTALLED
20-JAN-2010		MOS		08-FEB-2019			
		HRS/MSC	A/R	5066:42			
		AFL		4739			
FAA 2010-02-06	APPLIANCE AD - EQUIPMENT/FURNISHINGS - INSPECTIONS / REPLACEMENT OF CENTRAL SPREADERS, ALL APPLICABLE CORRECTIVE ACTIONS				MANDATORY		NOT APPLICABLE - COMPONENTS NOT INSTALLED
24-FEB-2010		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2010-02-06 PARA (F)(1)	PERFORM A VISUAL INSPECTION OF CENTRAL SPREADERS, P/N 92-000100-200-1 AND P/N 92-000101-200-1, OF THE AFFECTED SEATS / REPEAT (IF NO CRACK IS FOUND)				MANDATORY		NOT APPLICABLE - COMPONENTS NOT INSTALLED
24-FEB-2010		MOS		08-FEB-2019			
		HRS/MSC	500 (s)	5066:42			
		AFL		4739			
FAA 2010-02-06 PARA (F)(I)	CHECK THE CRACK TO DETERMINE THAT IT DID NOT ENLARGE TO A TYPE 2 OR TYPE 3 CRACK (IF A TYPE 1 CRACK IS FOUND)				MANDATORY		NOT APPLICABLE - COMPONENTS NOT INSTALLED
24-FEB-2010		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2010-02-06 PARA (F)(II)	REPLACE THE AFFECTED CENTRAL SPREADER WITH A NEW ONE WITH THE SAME PART NUMBER, EQUIPPED WITH DOUBLERS, P/N 00-6536 (IF A TYPE 2 OR 3 CRACK IS FOUND)				MANDATORY		NOT APPLICABLE - COMPONENTS NOT INSTALLED
24-FEB-2010		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2010-02-06 PARA (F)(III)	ACCOMPLISH TEMPORARY REPAIR BY INSTALLING DOUBLERS, P/N 00-6536 (IF A NEW SPREADER IS UNAVAILABLE)				MANDATORY		NOT APPLICABLE - COMPONENTS NOT INSTALLED
24-FEB-2010		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2010-02-06 PARA (F)(2)	INSTALL DOUBLERS, P/N 00-6536, ON NEW CENTRAL SPREADERS OF AFFECTED SEATS (IF ALREADY NOT DONE)				MANDATORY		NOT APPLICABLE - COMPONENTS NOT INSTALLED
24-FEB-2010		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2010-04-16	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI				MANDATORY		NOT APPLICABLE - COMPONENTS NOT INSTALLED
08-MAR-2010		MOS		08-FEB-2019			
		HRS/MSC	A/R	5066:42			
		AFL		4739			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2010-04-16 PARA (G)	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI WITH SERVICABLE UNIT					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
08-MAR-2010		DAYS		08-FEB-2019			
		HRS/MSC	-	5066:42			
		AFL		4739			
FAA 2010-04-16 PARA (H)	RETURN TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI THE AFFECTED FIRE EXTINGUISHER TO MANUFACTURER					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
08-MAR-2010		DAYS		08-FEB-2019			
		HRS/MSC	-	5066:42			
		AFL		4739			
FAA 2010-09-04	APPLIANCE AD - NAVIGATION - REVISE THE LIMITATIONS SECTION OF THE APPLICABLE AFM					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
14-MAY-2010		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2010-11-05	APPLIANCE AD - INSPECT FOR AND REMOVE SUBSTANDARD OXYGEN CYLINDERS FROM AIRPLANE					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
06-JUL-2010		DAYS		08-FEB-2019			
		HRS/MSC	A/R	5066:42			
		AFL		4739			
FAA 2011-21-08	APPLIANCE AD - EQUIPMENT/FURNISHINGS - TO IDENTIFY AND CORRECT AN UNSAFE CONDITION FOR SICMA AERO SEAT 88XX, 89XX, 90XX, 91XX, 92XX, 93XX, 95XX, AND 96XX SERIES PASSENGER SEAT ASSEMBLIES					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
23-NOV-2011		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2011-21-08 PARA (F)(1)	GENERAL VISUAL INSPECTION OF THE BACKREST LINKS HAVING P/NS 90-000200-104-1 AND 90-000200-104-2					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
23-NOV-2011		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2011-21-08 PARA (F)(2)	REPLACE BOTH BACKREST LINKS OF THE AFFECTED SEAT WITH NEW, IMPROVED BACKREST LINKS HAVING P/NS 90-100200-104-1 AND 90-100200-104-2 (IF, DURING THE INSPECTION REQUIRED BY PARA (F)(1), CRACKING IS FOUND BETWEEN THE SIDE OF THE BACKREST LINK AND THE LOCK-OUT PIN HOLE BUT THE CRACKING DOES NOT PASS THIS LOCK-OUT PIN HOLE)					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
23-NOV-2011		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2011-21-08 PARA (F)(3)	REPLACE BOTH BACKREST LINKS OF THE AFFECTED SEAT WITH NEW, IMPROVED BACKREST LINKS HAVING P/NS 90-100200-104-1 AND 90-100200-104-2 (IF, DURING THE INSPECTION REQUIRED BY PARA (F)(1), CRACKING IS FOUND THAT PASSES BEYOND THE LOCK-OUT PIN HOLE)					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
23-NOV-2011		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2011-21-08 PARA (F)(5)	REPLACE THE LINKS, P/NS 90-000200-104-1 AND 90-000200-104-2, WITH NEW IMPROVED LINKS, P/NS 90-100200-104-1 AND 90-100200-104-2 (IF NO CRACKING IS FOUND DURING THE INSPECTION REQUIRED BY PARA (F)(1))					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
23-NOV-2011		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATIONS & SURVEILLANCE SYSTEMS (ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS						NOT APPLICABLE - N/A BY MANUF. (HONEYWELL TPU 67A IS INST.)
		MOS		16-MAR-2012			
		HRS/MSC	-	4257:01			
		AFL		4051			
FAA 2012-08-07	APPLIANCE AD - EQUIPMENT/FURNISHINGS - REPETITIVE DETAILED INSPECTIONS FOR CRACKING OF THE CENTRAL AND LATERAL SPREADERS OF THE AFFECTED SEATS, AND REPAIR OR REPLACEMENT OF THE SPREADER IF NECESSARY				MANDATORY		NOT APPLICABLE - COMPONENTS NOT INSTALLED
09-MAY-2012		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2012-08-07 PARA (G)	PERFORM A DETAILED INSPECTION FOR CRACKING OF THE CENTRAL AND LATERAL SPREADERS OF THE AFFECTED SEATS AND REPEAT THE DETAILED INSPECTION (IF NO CRACKING IS FOUND ON ANY CENTRAL SPREADER AND IF NO CRACKING OR ONLY CRACKS THAT ARE SHORTER THAN 8 MM (0.315 INCH) ARE FOUND ON ANY LATERAL SPREADER)				MANDATORY		NOT APPLICABLE - COMPONENTS NOT INSTALLED
09-MAY-2012		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2012-08-07 PARA (G)(3)	REPAIR THE AFFECTED SPREADER (IF ALL CRACKS FOUND ON ANY CENTRAL SPREADER ARE SHORTER THAN 8 MM (0.315 INCH)) / ACCOMPLISH THE DETAILED INSPECTION SPECIFIED IN PARA (G)				MANDATORY		NOT APPLICABLE - COMPONENTS NOT INSTALLED
09-MAY-2012		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2012-08-07 PARA (G)(4)	REPLACE THE AFFECTED SPREADER (IF ONE OR MORE CRACKS ARE FOUND THAT ARE 8 MM (0.315 INCH) OR LONGER ON ANY LATERAL OR CENTRAL SPREADER)				MANDATORY		NOT APPLICABLE - COMPONENTS NOT INSTALLED
09-MAY-2012		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2012-08-07 PARA (H)	PERFORM A DETAILED INSPECTION FOR CRACKING OF THE CENTRAL AND LATERAL SPREADERS OF THE AFFECTED SEATS AND REPEAT THE DETAILED INSPECTION (IF NO CRACKING IS FOUND ON ANY CENTRAL SPREADER AND IF NO CRACKING OR ONLY CRACKS THAT ARE SHORTER THAN 8 MM (0.315 INCH) ARE FOUND ON ANY LATERAL SPREADER)				MANDATORY		NOT APPLICABLE - COMPONENTS NOT INSTALLED
09-MAY-2012		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2012-08-07 PARA (H)(3)	REPAIR THE AFFECTED SPREADER (IF ALL CRACKS FOUND ON ANY CENTRAL SPREADER ARE SHORTER THAN 8 MM (0.315 INCH))				MANDATORY		NOT APPLICABLE - COMPONENTS NOT INSTALLED
09-MAY-2012		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2012-08-07 PARA (H)(4)	REPLACE THE AFFECTED SPREADER (IF ONE OR MORE CRACKS ARE FOUND THAT ARE 8 MM (0.315 INCH) OR LONGER ON ANY LATERAL OR CENTRAL SPREADER)				MANDATORY		NOT APPLICABLE - COMPONENTS NOT INSTALLED
09-MAY-2012		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2012-08-07 PARA (I)	TERMINATING ACTION REPLACING ALL CENTRAL AND LATERAL SPREADERS ON AN AFFECTED SEAT ASSEMBLY TERMINATES THE INSPECTIONS REQUIRED BY THIS AD FOR THAT SEAT ASSEMBLY				MANDATORY		NOT APPLICABLE - COMPONENTS NOT INSTALLED
09-MAY-2012		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2012-08-07 PARA (K)	NO PERSON MAY INSTALL ANY PASSENGER SEAT ASSEMBLY IDENTIFIED IN PARAGRAPH (C) OF THIS AD, ON ANY AIRPLANE, UNLESS IT HAS BEEN MODIFIED TO "AMENDMENT B" STANDARD IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS OF SICMA AERO SEAT SERVICE BULLETIN 94-25-012, REVISION 1, DATED JUNE 26, 2008.					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
09-MAY-2012		MOS		08-FEB-2019			
		HRS/MSC	- (s)		5066:42		
		AFL			4739		
FAA 2012-14-15	APPLIANCE AD - HONEYWELL INTERNATIONAL, INC. KGS200 MERCURY ² WIDE AREA AUGMENTATION SYSTEM (WAAS) GLOBAL NAVIGATION SATELLITE SENSOR UNITS (GNSSU)					MANDATORY	NOT APPLICABLE - AIRCRAFT NOT EQUIPPED
19-JUL-2012		MOS					
		HRS/MSC	-				
		AFL					
FAA 2012-14-15	APPLIANCE AD - HONEYWELL INTERNATIONAL, INC. KGS200 MERCURY ² SYSTEM SOFTWARE PROBLEM					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
		MOS		08-FEB-2019			
		HRS/MSC	-		5066:42		
		AFL			4739		
FAA 2012-14-15 (G)	INCORPORATE HONEYWELL INTERNATIONAL, INC. KGS200 MERCURY ² SYSTEM SOFTWARE PROBLEM LANGUAGE INTO THE LIMITATIONS SECTION OF THE AIRCRAFT FLIGHT MANUAL					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
		MOS		08-FEB-2019			
		HRS/MSC	-		5066:42		
		AFL			4739		
FAA 2012-14-15 (H)	FABRICATE HONEYWELL INTERNATIONAL, INC. KGS200 MERCURY ² SYSTEM SOFTWARE PROBLEM AND INSTALL A PLACARD					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
		DAYS	3 (s)	08-FEB-2019			
		HRS/MSC	-		5066:42		
		AFL			4739		
FAA 2012-14-15 PARA (G)	INCORPORATE LANGUAGE INTO THE LIMITATIONS SECTION OF THE AIRCRAFT FLIGHT MANUAL					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
19-JUL-2012		MOS		08-FEB-2019			
		HRS/MSC	-		5066:42		
		AFL			4739		
FAA 2012-14-15 PARA (H)	FABRICATE AND INSTALL A PLACARD					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
19-JUL-2012		DAYS		08-FEB-2019			
		HRS/MSC	-		5066:42		
		AFL			4739		
FAA 2012-17-01	APPLIANCE AD - GOODYEAR AVIATION TIRES					MANDATORY	NOT APPLICABLE - N/A BY PN OF TIRES.
		MOS		18-SEP-2012			
		HRS/MSC	-		4325:32		
		AFL			4113		
FAA 2012-26-15	APPLIANCE AD - IDENTIFY OUT OF SPEC AIR DATA COMPUTERS (ADC), AIRDATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS) AND DIGITAL AIR DATA COMPUTERS (DADC) (RESCINDED BY FAA 2012-26-15 R01)					MANDATORY	NOT APPLICABLE - BY SN AIR DATA COMPUTERS
24-JAN-2013		MOS		31-JAN-2013			
		HRS/MSC	-		4401:27		
		AFL			4170		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2012-26-15 PARA (G)(1)	REMOVE IDENTIFY OUT OF SPEC AIR DATA COMPUTERS (ADC), AIRDATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS) AND DIGITAL AIR DATA COMPUTERS (DADC) (RESCINDED BY FAA 2012-26-15 R01) AFFECTED ADC, ADM, ADAHRS, OR DADC					MANDATORY	NOT APPLICABLE - BY SN AIR DATA COMPUTERS
24-JAN-2013		DAYs		31-JAN-2013			
		HRS/MSC	-	4401:27			
		AFL		4170			
FAA 2012-26-15 PARA (G)(2)	PERFORM IDENTIFY OUT OF SPEC AIR DATA COMPUTERS (ADC), AIRDATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS) AND DIGITAL AIR DATA COMPUTERS (DADC) (RESCINDED BY FAA 2012-26-15 R01) PITOT-STATIC CERTIFICATION TEST					MANDATORY	NOT APPLICABLE - BY SN AIR DATA COMPUTERS
24-JAN-2013		DAYs		31-JAN-2013			
		HRS/MSC	-	4401:27			
		AFL		4170			
FAA 2012-26-15 R01	APPLIANCE AD - AIR DATA PRESSURE TRANSDUCERS, AS INSTALLED IN AIR DATA COMPUTERS (ADC), AIR DATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS), AND DIGITAL AIR DATA COMPUTERS (DADC)					MANDATORY	NOT APPLICABLE - R1 CANCELS AD 2012-26-15
03-DEC-2014		MOS		02-NOV-2014			
		HRS/MSC	-	4674:21			
		AFL		4389			
FAA 2014-05-27	APPLIANCE AD - ROCKWELL COLLINS, INC. TPR-720 AND TPR-900 MODE S TRANSPONDERS - TEST AND CALIBRATION					MANDATORY	NOT APPLICABLE - NOT MAINTAINED OR REPAIRED AFTER 28 SEP 2003
		MOS		08-APR-2014			
		HRS/MSC	-	4566:55			
		AFL		4303			
FAA 2014-17-02	APPLIANCE AD - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING DISCREPANCIES - HONEYWELL ASCA INC					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
09-SEP-2014		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNIKS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSSES					MANDATORY	COMPLIED WITH - BOTH DMF'S BEFORE 11-08
16-JUN-2015		MOS		02-JUN-2017			
		HRS/MSC	-	5052			
		AFL		4732			
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
12-JUN-2015		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
12-JUN-2015		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
12-JUN-2015		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
12-JUN-2015		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
01-JUL-2015		MOS HRS/MSC - AFL		08-FEB-2019 5066:42 4739			
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
18-MAY-2015		MOS HRS/MSC - AFL		30-JUN-2015 4794:57 4515			
FAA 2015-16-04	APPLIANCE AD - FIRE PROTECTION - MODIFY ALL KIDDE GRAVINGER HAND-OPERATED FIRE EXTINGUISHERS HAVING PART NUMBERS 56412-001 (34H), 56411-001 (35H), AND 56412-002 (38H)					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
15-SEP-2015		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNIKS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
28-DEC-2015		MOS HRS/MSC - AFL		08-FEB-2019 5066:42 4739			
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
28-DEC-2015		DAYs HRS/MSC - AFL		08-FEB-2019 5066:42 4739			
FAA 2015-23-09 PARA (H)(1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
28-DEC-2015		DAYs HRS/MSC - AFL		08-FEB-2019 5066:42 4739			
FAA 2015-23-09 PARA (H)(2)(I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
28-DEC-2015		DAYs HRS/MSC - AFL		08-FEB-2019 5066:42 4739			
FAA 2015-23-09 PARA (H)(2)(II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
28-DEC-2015		DAYs HRS/MSC - AFL		08-FEB-2019 5066:42 4739			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
28-DEC-2015		MOS HRS/MSC - AFL		08-FEB-2019 5066:42 4739			
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - BY PN PBE
15-JUL-2016		MOS HRS/MSC - AFL		16-JUN-2016 4967:11 4654			
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A..1 SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - BY PN PBE
15-JUL-2016		MOS HRS/MSC - AFL		16-JUN-2016 4967:11 4654			
FAA 2016-11-20 PARA (H)(1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - BY PN PBE
15-JUL-2016		MOS HRS/MSC - AFL		16-JUN-2016 4967:11 4654			
FAA 2016-11-20 PARA (H)(2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - BY PN PBE
15-JUL-2016		MOS HRS/MSC - AFL		16-JUN-2016 4967:11 4654			
FAA 2017-09-09	APPLIANCE AD - PASSENGER COMPARTMENT EQUIPMENT - REPLACEMENT OF ZODIAC SEATS CALIFORNIA LLC SEATING SYSTEMS					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
28-JUN-2017		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2017-11-11	APPLIANCE AD - NAVWORX, INC. AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST (ADS-B) UNIVERSAL ACCESS TRANSCEIVER UNITS - REMOVE, DISABLE, OR REVISE SOFTWARE TO BROADCAST A SIL OF 0					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
11-JUL-2017		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETITIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED
24-OCT-2017		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT						NOT APPLICABLE - COMPONENTS NOT INSTALLED
24-OCT-2017		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2017-19-05 PARA (F)(1)	INSPECT EACH SIEMENS SMOKE DETECTOR, OR REVIEW YOUR MAINTENANCE RECORDS, TO DETERMINE IF AN AFFECTED DETECTOR IS INSTALLED					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
31-OCT-2017		DAYS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2017-19-05 PARA (F)(2.1)	REPLACE CARGO COMPARTMENT SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (C)(1), SPECIFIED IN FIGURES 2 AND 3					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
31-OCT-2017		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2017-19-05 PARA (F)(2.2)	REPLACE PASSENGER, CABIN OR ANY OTHER LOCATION SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (C)(1), SPECIFIED IN FIGURE 4					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
31-OCT-2017		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2017-19-05 PARA (F)(3)	REPLACE REPAIRED SMOKE DETECTOR IDENTIFIED IN PARAGRAPH (C)(2), SPECIFIED FIGURE 1					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
31-OCT-2017		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2017-19-05 PARA (G)	DO NOT INSTALL ON ANY AIRPLANE A SMOKE DETECTOR WITH A MANUFACTURING DATE AND P/N LISTED IN FIGURE 2 OR 3 OR LISTED IN FIGURE 4 TO PARAGRAPH (F) OF THIS AD UNLESS THE DETECTOR IS MARKED "SIL PMC-26-002"					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
31-OCT-2017		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2017-22-02	APPLIANCE AD - FLIGHT COMPARTMENT EQUIPMENT - IPECO HOLDINGS LTD. -MODIFICATION AND REIDENTIFICATION OF PILOT'S AND CO-PILOT'S SEATS					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
12-DEC-2017		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			
FAA 2017-22-02 PARA (F)	MODIFY AND RE-IDENTIFY AFFECTED EACH PILOT AND CO-PILOT SEAT					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
12-DEC-2017		MOS		08-FEB-2019			
		HRS/MSC	-	5066:42			
		AFL		4739			
FAA 2017-22-02 PARA (G)	DO NOT INSTALL ANY PILOT OR CO-PILOT SEAT IDENTIFIED IN PARAGRAPH (C) OF THIS AD UNLESS THE SEAT IS MODIFIED AND REIDENTIFIED AS SPECIFIED IN PARAGRAPH (F)(2) OF THIS AD					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
12-DEC-2017		MOS		08-FEB-2019			
		HRS/MSC	-	5066:42			
		AFL		4739			
FAA 2017-22-14	APPLIANCE AD - NAVIGATION - INSTALLATION OF THE TSSA-4100 FLS UPGRADES ON THE ROCKWELL COLLINS, INC. TSS-4100 TRAFFIC SURVEILLANCE SYSTEM PROCESSING UNITS					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
20-DEC-2017		MOS		08-FEB-2019			
		HRS/MSC	- (s)	5066:42			
		AFL		4739			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2018-03-04	APPLIANCE AD - NAVIGATION - REPLACEMENT OF ROSEMOUNT AEROSPACE INC. MODEL 851AK PITOT PROBES REPAIRED BY CSI AEROSPACE INC					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
16-MAR-2018		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2018-03-04 PARA (G)	DETERMINE NUMBER OF AFFECTED PITOT PROBES INSTALLED					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
16-MAR-2018		DAYS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2018-03-04 PARA (H)(1)	REPLACE AFFECTED PITOT PROBES					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
16-MAR-2018		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2018-03-04 PARA (H)(2)	DO NOT INSTALL ON ANY AIRPLANE A PITOT PROBE HAVING A SERIAL NUMBER LISTED IN PARA (C)(1) OF THIS AD, UNLESS IT HAS BEEN PROPERLY REPAIRED, AND IF REPAIRED BY CSI AEROSPACE, INC., HAS A REPAIR DATE OF AUGUST 1, 2014, OR LATER					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
16-MAR-2018		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2018-16-13	APPLIANCE AD - EQUIPMENT/FURNISHINGS - INSPECT THE SAFETY BELT WEBBING, AND MODIFY AND RE-MARKING EACH AFFECTED CABIN ATTENDANT SEAT					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
26-OCT-2018		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2018-16-13 PARA (G)	INSPECT SAFETY BELT WEBBING, MODIFY AND RE-MARK EACH AFFECTED CABIN ATTENDANT SEAT USING ZODIAC SEATS FRANCE SERVICE INFORMATION LETTER 537-01					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
26-OCT-2018		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2018-16-13 PARA (H)	DO NOT INSTALL ANY AFFECTED ZODIAC SEATS FRANCE CABIN ATTENDANT SEAT ON ANY AIRCRAFT					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
26-OCT-2018		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2018-19-15	APPLIANCE AD - EQUIPMENT / FURNISHINGS - SAFETY BELT ATTACHMENT BOLTS - INSPECTION / TORQUE VERIFICATION / MODIFICATION					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
14-NOV-2018		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2018-21-14	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR HARNESS INFLATION HOSES - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - PER PART NUMBER MASK INSTALLED
27-MAR-2019		MOS HRS/MSC - (s) AFL		01-APR-2019 5066:42 4739			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2018-21-14 PARA (G)	REQUIRED ACTIONS					MANDATORY	NOT APPLICABLE - PER PART NUMBER MASK INSTALLED
27-MAR-2019		MOS HRS/MSC - AFL		01-APR-2019 5066:42 4739			
FAA 2018-21-14 PARA (H)	DO NOT INSTALL ON ANY AIRPLANE A FLIGHT CREW OXYGEN MASK REGULATOR WITH A P/N LISTED IN PLANNING INFORMATION, PARAGRAPH 1.A.(1), OF ZODIAC SB MC10-35-274 R02, DATED JUNE 25, 2014, UNLESS IT MEETS THE DEFINITION OF A PART ELIGIBLE FOR INSTALLATION IN PARA (I) OF THIS AD					MANDATORY	NOT APPLICABLE - PER PART NUMBER MASK INSTALLED
27-MAR-2019		MOS HRS/MSC - (s) AFL		01-APR-2019 5066:42 4739			
FAA 2018-23-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CABIN ATTENDANT SEAT - INSPECTION AND REPLACEMENT					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
28-DEC-2018		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2018-23-01 PARA (G)	INSPECT THE SEAT PAN STRUCTURE IN BOTH DEPLOYED AND STOWED POSITIONS (IF CRACKS ARE FOUND, REPLACE WITH REINFORCED SEAT PAN P/N F0511530 AND REMARK THE SEAT) (IF NO CRACKS ARE FOUND, REMARK THE SEAT AND REINSPECT OR REPLACE THE SEAT PAN WITH REINFORCED SEAT PAN P/N F0511530)					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
28-DEC-2018		MOS HRS/MSC - AFL	100 (s)	08-FEB-2019 5066:42 4739			
FAA 2018-23-01 PARA (H)	INSTALLATION OF A REINFORCED SEAT PAN, P/N F0511530, USING PARAGRAPH 2.B., ACCOMPLISHMENT INSTRUCTIONS, OF ZODIAC SEATS FRANCE SB NO. 536-25-003, REV. 3, DATED JUNE 2, 2017, IS TERMINATING ACTION TO THIS AD					MANDATORY	NOT APPLICABLE - COMPONENTS NOT INSTALLED.
28-DEC-2018		MOS HRS/MSC - (s) AFL		08-FEB-2019 5066:42 4739			
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT					MANDATORY	NOT APPLICABLE - N/A BY PN OF THE PART
11-MAY-2021		MOS HRS/MSC - AFL		14-SEP-2021 6755:02 5707			
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE					MANDATORY	NOT APPLICABLE - N/A BY P/N OF THE PART
11-MAY-2021		MOS HRS/MSC - AFL		14-SEP-2021 6755:02 5707			
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICHNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE					MANDATORY	NOT APPLICABLE - N/A BY PN OF THE PART
11-MAY-2021		MOS HRS/MSC - AFL		14-SEP-2021 6755:02 5707			
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER					MANDATORY	NOT APPLICABLE - N/A BY PN OF THE PART
11-MAY-2021		MOS HRS/MSC - AFL		14-SEP-2021 6755:02 5707			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS					MANDATORY	COMPLIED WITH - PRINTED AND PLACED TO THE AFM.
09-DEC-2021		MOS		04-JAN-2022			
		HRS/MSC	-	7081:52			
		AFL		5894			
FAA 2023-10-02 PARA (I)	REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)				30-JUN-2023 M	MANDATORY	
26-MAY-2023		MOS					
		HRS/MSC	BF/F				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - SB - 560XL-5230/OK-HAR							
ASL ASL560XL-26-01	FIRE PROTECTION - TRANSMITTAL OF MEGGITT SAFETY SYSTEMS SERVICE BULLETIN 26-36-THERMISTORS DETECTORS (SUPERSEDED BY ASL560XL-26-01 R01), ALERT SERVICE LETTER					MANDATORY	NOT APPLICABLE - NOT APPLICABLE
04-APR-2007		MOS HRS/MSC AFL		25-APR-2007 3118			
ASL ASL560XL-27-10	FLIGHT CONTROLS - TRANSMITTAL OF FAA APPROVED AIRPLANE FLIGHT MANUAL TEMPORARY CHANGE 56XFM TC-09-04, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
11-DEC-2002		MOS HRS/MSC AFL		09-MAY-2003 641			
ASL ASL560XL-27-12	FLIGHT CONTROLS - AILERON WING CABLE INSPECTION (SUPERSEDED BY ASL560XL-27-12 R01), ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
		MOS HRS/MSC AFL		18-DEC-2003 1110			
ASL ASL560XL-27-15	ELEVATOR TRIM CABLE INSPECTION, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
04-DEC-2006		MOS HRS/MSC AFL		06-APR-2007 3103			
ASL ASL560XL-32-13	LANDING GEAR - EMERGENCY BRAKE,FLAPS,EMERGENCY GEAR AND SPEED BRAKE HYDRAULIC/PNEUMATIC LINE CLAMP INSPECTION, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
08-AUG-2003		MOS HRS/MSC AFL		19-SEP-2003 943			
ASL ASL560XL-32-14	LANDING GEAR - NOSE LANDING GEAR OLEO PRESSURE INSPECTION, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
22-DEC-2004		MOS HRS/MSC AFL		15-FEB-2005 1913			
ASL ASL560XL-34-08	NAVIGATION - TRANSMITTAL OF HONEYWELL TECHNICAL NEWSLETTER A23-3850-001, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
17-FEB-2003		MOS HRS/MSC AFL		09-MAY-2003 641			
ASL ASL560XL-53-08	FUSELAGE - AFT CANTED BULKHEAD DRAIN INSTALLATION (SUPERSEDED BY ASL560XL-53-08 R01), ALERT SERVICE LETTER					MANDATORY	- SUPERSEDED BY REVISION 1
21-JAN-2011		DAY HRS/MSC AFL		(EFF)			
ASL ASL560XL-53-08 R01	FUSELAGE - AFT CANTED BULKHEAD DRAIN INSTALLATION, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
		DAY HRS/MSC AFL		11-APR-2011 4104:26 3924			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASL ASL560XL-72-19	LEFT ENGINE TRANSMITTAL OF P&WC SERVICE DOCUMENTS - INTERCOMPRESSOR BLEED VALVE/SERVO - VALVE - INSPECTION/REPLACEMENT OF, ALERT SERVICE LETTER				MANDATORY		NOT APPLICABLE - SB A30421 N/A (ENG. SN. DB0473 & DB0472 ARE PRE SB 30343 & 30404 . SB 30420 TO BE DONE WHEN ACCESS.
01-SEP-2010		MOS HRS/MSC AFL	A/R	19-NOV-2010 4049 3877			
ASL ASL560XL-72-19	RIGHT ENGINE TRANSMITTAL OF P&WC SERVICE DOCUMENTS - INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE-INSPECTION/REPLACEMENT OF, ALERT SERVICE LETTER				MANDATORY		NOT APPLICABLE - SB A30421 N/A (ENG. SN. DB0473 & DB0472 ARE PRE SB 30343 & 30404 . SB 30420 TO BE DONE WHEN ACCESS.
01-SEP-2010		MOS HRS/MSC AFL	A/R	19-NOV-2010 4049 3877			
ASL ASL560XL-73-11	LEFT ENGINE TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN A30319 TURBOFAN ENGINE NEW FUEL MANIFOLD-INTRODUCTION OF, ALERT SERVICE LETTER				MANDATORY		COMPLIED WITH
		MOS HRS/MSC AFL	A/R	13-NOV-2007 3405			
ASL ASL560XL-73-11	RIGHT ENGINE TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN A30319 TURBOFAN ENGINE NEW FUEL MANIFOLD-INTRODUCTION OF, ALERT SERVICE LETTER				MANDATORY		COMPLIED WITH
		MOS HRS/MSC AFL	A/R	13-NOV-2007 3405			
SB 560XL-21-04 R01	AIR CONDITIONING - EXHAUST DUCT CONDENSATION CONTAINMENT, SERVICE BULLETIN				RECOMMENDED		COMPLIED WITH - NOT APPLICABLE
30-AUG-2002		MOS HRS/MSC AFL	-	09-MAY-2003 641			
SB 560XL-21-11	AIR CONDITIONING - SERVICE PORT DRIP SHIELD IMPROVEMENT, SERVICE BULLETIN				RECOMMENDED		COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED
13-DEC-2001		MOS HRS/MSC AFL	-	11-OCT-2002 329			
SB 560XL-21-15	AIR CONDITIONING - COCKPIT TEMPERATURE SENSOR IMPROVEMENT, SERVICE BULLETIN				DISCRETIONARY		COMPLIED WITH
16-JUN-2003		MOS HRS/MSC AFL	-	29-APR-2005 2059			
SB 560XL-21-18 R01	AIR CONDITIONING - TEMPERATURE CONTROLLER UPGRADE, SERVICE BULLETIN				RECOMMENDED		COMPLIED WITH
14-MAY-2007		MOS HRS/MSC AFL	A/R	05-SEP-2008 3665			
SB 560XL-21-19	AIR CONDITIONING - EMERGENCY PRESSURIZATION OPERATION IMPROVEMENT (SUPERSEDED BY 560XL-21-19 R01), SERVICE BULLETIN				RECOMMENDED		COMPLIED WITH
08-FEB-2006		MOS HRS/MSC AFL	A/R	16-MAY-2006 2677			
SB 560XL-23-05	COMMUNICATIONS - RNZ-850 NAVIGATION RADIO UPGRADE (SUPERSEDED BY 560XL-23-05 R01), SERVICE BULLETIN				MANDATORY		COMPLIED WITH
		MOS HRS/MSC AFL	-	15-FEB-2005 1913			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 560XL-23-07 R03	COMMUNICATIONS - RADIO MANAGEMENT UNIT (RM855) INSTALLATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - RMU'S REPLACED, C/W SB 560XL-23-07R3
11-FEB-2013		MOS		03-NOV-2014			
		HRS/MSC	-	4674:21			
		AFL		4389			
SB 560XL-24-07	ELECTRICAL POWER - WING WIRE GROUND IMPROVEMENT (SUPERSEDED BY 560XL-24-07 R01) , SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		11-OCT-2002			
		HRS/MSC	A/R	329			
SB 560XL-24-14 R02	ELECTRICAL POWER - APU STARTER/GENERATOR WIRING IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
10-OCT-2009		MOS		10-OCT-2011			
		HRS/MSC	300 (s)	4149:35			
		AFL		3962			
SB 560XL-24-20	ELECTRICAL POWER - AC J-BOX WIRE BUNDLE ANCHOR INSTALLATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
03-OCT-2017		MOS		27-AUG-2019			
		HRS/MSC	-	5252:35			
		AFL		4867			
SB 560XL-25-08	EQUIPMENT/FURNISHINGS - AFT DIVIDER IMPROVEMENT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
15-MAY-2003		MOS		12-MAR-2004			
		HRS/MSC	-	1200			
SB 560XL-25-09	EQUIPMENT/FURNISHINGS - GALLEY STORAGE DOOR HINGE IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
06-NOV-2003		MOS		12-MAR-2004			
		HRS/MSC	-	1200			
SB 560XL-25-10	EQUIPMENT/FURNISHINGS - AFT DIVIDER DOOR SWITCH IMPROVEMENT (SUPERSEDED BY 560XL-25-10 R01), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
		MOS		23-JUL-2004			
		HRS/MSC	A/R	1489			
SB 560XL-25-11 R01	EQUIPMENT/FURNISHINGS - ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) (SUPERSEDED BY 560XL-25-11 R02), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - INCORPORATED AT MANUFACTURE
01-JUL-2010		MOS		30-JUN-2022			
		HRS/MSC	A/R	7399:24			
		AFL		6143			
SB 560XL-25-11 R02	EQUIPMENT/FURNISHINGS - ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) (SUPERSEDED BY 560XL-25-11 R03), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - SUPPRESSED BY 560XL-25-11 R01. INCORPORATED AT MANUFACTURE
		MOS		30-JUN-2022			
		HRS/MSC	A/R	7399:24			
		AFL		6143			
SB 560XL-25-11 R03	EQUIPMENT/FURNISHINGS - ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - SUPPRESSED BY 560XL-25-11 R01. INCORPORATED AT MANUFACTURE
18-APR-2012		MOS		30-JUN-2022			
		HRS/MSC	-	7399:24			
		AFL		6143			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 560XL-26-01	FIRE PROTECTION - TRANSMITTAL OF PACIFIC SCIENTIFIC SERVICE BULLETIN 26-03-35071497, INSPECTION AND REPLACEMENT OF TEMPERATURE COMPENSATED PRESSURE SWITCH (SUPERSEDED BY 560XL-26-01 R01), SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS HRS/MSC AFL		09-MAY-2003 641			
SB 560XL-26-02 R01	FIRE PROTECTION - FIRE BOTTLE WIRE IDENTIFICATION SLEEVE INSTALLATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
22-DEC-2004		MOS HRS/MSC AFL		15-FEB-2005 1913			
SB 560XL-27-13 R01	FLIGHT CONTROLS - AFT AILERON SECTOR TUBE FINISH IMPROVEMENT (SUPERSEDED BY 560XL-27-13 R02), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS HRS/MSC AFL		12-MAR-2004 1200			
SB 560XL-27-13 R02	FLIGHT CONTROLS - AFT AILERON SECTOR TUBE FINISH IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
08-APR-2004		MOS HRS/MSC AFL		23-JUL-2004 1489			
SB 560XL-27-17 R02	FLIGHT CONTROLS - ELEVATOR TRIM TAB INSPECTION/REPAIR, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
19-MAR-2003		MOS HRS/MSC AFL		07-OCT-2003 986			
SB 560XL-27-19	FLIGHT CONTROLS - STEEP APPROACH CERTIFICATION (SUPERSEDED BY 560XL-27-19 R01), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
		MOS HRS/MSC AFL		28-JUL-2004 1503			
SB 560XL-27-20	FLIGHT CONTROLS - RUDDER FAIRLEAD TUBE SUPPORT MODIFICATION (SUPERSEDED BY 560XL-27-20 R01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
20-JAN-2003		MOS HRS/MSC AFL		09-MAY-2003 641			
SB 560XL-27-21 R01	FLIGHT CONTROLS - AILERON PULLEY BRACKET ACCESS IMPROVEMENT, SERVICE BULLETIN					OPTIONAL	- SERVICE BULLETIN ON HOLD.
05-FEB-2008		MOS HRS/MSC AFL		(EFF)			
SB 560XL-27-22	FLIGHT CONTROLS - AILERON WING CABLE PULLEY BRACKET REPLACEMENT (SUPERSEDED BY 560XL-27-22 R01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
06-JUN-2005		MOS HRS/MSC AFL		20-DEC-2005 2464			
SB 560XL-27-22 R01	FLIGHT CONTROLS - AILERON WING CABLE PULLEY BRACKET REPLACEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS HRS/MSC AFL		16-MAY-2006 2677			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 560XL-27-26	FLIGHT CONTROLS - ELEVATOR TRIM WHEEL INSTALLATION IMPROVEMENT (SUPERSEDED BY 560XL-27-26 R01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS HRS/MSC AFL		20-DEC-2005 2464			
SB 560XL-27-26 R01	FLIGHT CONTROLS - ELEVATOR TRIM WHEEL INSTALLATION IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
18-OCT-2005		MOS HRS/MSC AFL		16-MAY-2006 2677			
SB 560XL-27-29 R01	FLIGHT CONTROLS - SPEED BRAKE ELECTRICAL CONNECTOR REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	DECLINED - DECLINED BY CAMO
07-MAR-2009		MOS HRS/MSC AFL	300 (s)	05-AUG-2011 4149:21 3962			
SB 560XL-27-32	FLIGHT CONTROLS - RUDDER PEDAL POSITION MODIFICATION (SUPERSEDED BY 560XL-27-32 R01), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY SERIAL NUMBER SUPERSEDED BY REVISION 1
27-AUG-2010		MOS HRS/MSC AFL					
SB 560XL-27-34	FLIGHT CONTROLS - ELEVATOR TRIM CABLE REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - N/A BY PART NR.
09-APR-2012		MOS HRS/MSC AFL		05-MAY-2012 4272:33 4072			
SB 560XL-28-02 R01	FUEL - WING FUEL BOOST PUMP FAIRING INSULATION INSTALLATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-JUL-2005		MOS HRS/MSC AFL		20-DEC-2005 2464			
SB 560XL-28-03	FUEL - WING FUEL BOOST PUMP FAIRING INSULATION INSTALLATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - NOT APPLICABLE
17-JAN-2005		MOS HRS/MSC AFL		15-FEB-2005 1913			
SB 560XL-29-04	HYDRAULIC POWER - WHEEL WELL HYDRAULIC LINE SUPPORT IMPROVEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
10-JUN-2004		MOS HRS/MSC AFL		05-NOV-2004 1768			
SB 560XL-30-04	ICE AND RAIN PROTECTION - WING LEADING EDGE PICCOLO TUBE IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
07-AUG-2002		MOS HRS/MSC AFL		09-MAY-2003 641			
SB 560XL-31-02	INDICATING/RECORDING SYSTEMS - STAB MISCOMPARE ANNUNCIATION IMPROVEMENT (SUPERSEDED BY 560XL-31-02 R01), SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS HRS/MSC AFL		12-MAR-2004 1200			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 560XL-31-02 R01	INDICATING/RECORDING SYSTEMS - STAB MISCOMPARE ANNUNCIATION IMPROVEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
13-MAY-2004	MOS HRS/MSC - AFL			16-MAY-2006 2677			
SB 560XL-32-20 R02	LANDING GEAR - NOSE GEAR TORQUE-LINK QUICK DISCONNECT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
08-MAY-2006	MOS HRS/MSC A/R AFL			05-SEP-2008 3665			
SB 560XL-32-24	LANDING GEAR - EMERGENCY GEAR EXTENSION BOTTLE ACTUATOR HANDLE PIVOT SCREW REPLACEMENT (SUPERSEDED BY 560XL-32-24 R01), SERVICE BULLETIN					MANDATORY	COMPLIED WITH
	MOS HRS/MSC A/R AFL			05-NOV-2004 1768			
SB 560XL-32-26 R02	LANDING GEAR - NOSE LANDING GEAR DOOR MECHANISM IMPROVEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
15-FEB-2006	MOS HRS/MSC A/R AFL			16-MAY-2006 2677			
SB 560XL-32-27	LANDING GEAR - MAIN LANDING GEAR TRAILING LINK PIVOT PIN RETENTION IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
31-JAN-2006	MOS HRS/MSC A/R AFL			20-JUL-2007 3274			
SB 560XL-32-32	LANDING GEAR - BRAKE HYDRAULIC PACK FILTER BOWL REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
26-APR-2006	MOS HRS/MSC A/R AFL			05-SEP-2008 3665			
SB 560XL-32-40	LANDING GEAR ANNUNCIATION WIRING MODIFICATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
31-OCT-2007	MOS HRS/MSC A/R AFL			05-SEP-2008 3665			
SB 560XL-32-41	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE BULLETIN 3-1571-32-7 (SUPERSEDED BY 560XL-32-41 R01), SERVICE BULLETIN					MANDATORY	COMPLIED WITH - PREVIOUSLY SEE R1
	MOS HRS/MSC A/R AFL			05-JUN-2012 4272:33 4072			
SB 560XL-32-41 R01	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE BULLETIN 3-1571-32-7, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - PREVIOUSLY
	MOS HRS/MSC A/R AFL			05-JUN-2012 4272:33 4072			
SB 560XL-33-05 R01	LIGHTS - LED TAIL POSITION LIGHT INSTALLATION (SUPERSEDED BY 560XL-33-05 R02), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
25-OCT-2005	MOS HRS/MSC - AFL			21-NOV-2008 3742			
SB 560XL-33-08 R01	LIGHTS - CHART LIGHT MODIFICATION (SUPERSEDED BY 560XL-33-08 R02), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
09-SEP-2005	MOS HRS/MSC - AFL			25-APR-2007 3118			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 560XL-33-08 R02	LIGHTS - CHART LIGHT MODIFICATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
12-APR-2007	MOS HRS/MSC AFL	A/R		22-JAN-2008 3487			
SB 560XL-33-09	LIGHTS - LIGHT EMITTING DIODE (LED) EMERGENCY OVERWING LIGHTING INSTALLATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
02-MAY-2005	MOS HRS/MSC AFL	-		05-SEP-2008 3665			
SB 560XL-34-16	NAVIGATION - MEGGITT SECONDARY FLIGHT DISPLAY SYSTEM CIRCUIT BREAKER CHANGE AND 7.5 AMP IN LINE FUSE INSTALLATION (SUPERSEDED BY 560XL-34-16 R01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
	MOS HRS/MSC AFL	A/R		17-FEB-2002 17 0			
SB 560XL-34-26 R01	NAVIGATION - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) COMPUTER SOFTWARE UPGRADE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
19-SEP-2002	MOS HRS/MSC AFL	-		12-MAR-2004 1200			
SB 560XL-34-27	NAVIGATION - UNIVERSAL AVIONICS PERFORMANCE DATABASE, SERVICE BULLETIN					OPTIONAL	- SERVICE BULLETIN ON HOLD.
01-MAY-2003	MOS HRS/MSC AFL	- (s)		(EFF)			
SB 560XL-34-29	NAVIGATION - HONEYWELL PRIMUS 1000 PHASE 3.0 SOFTWARE UPGRADE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
17-OCT-2002	MOS HRS/MSC AFL	-		15-FEB-2005 1913			
SB 560XL-34-30	NAVIGATION - HONEYWELL PRIMUS 1000 PHASE 3.0 SOFTWARE UPGRADE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED
21-JAN-2003	MOS HRS/MSC AFL	-		09-MAY-2003 641			
SB 560XL-34-44	NAVIGATION - HONEYWELL MODE S TRANSPONDER UPGRADE FOR ENHANCED SURVEILLANCE (SUPERSEDED BY 560XL-34-44 R01), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
15-SEP-2005	MOS HRS/MSC AFL	-		06-APR-2007 3103			
SB 560XL-34-44 R02	NAVIGATION - HONEYWELL MODE S TRANSPONDER UPGRADE FOR ENHANCED SURVEILLANCE (SUPERSEDED BY 560XL-34-44 R03), SERVICE BULLETIN					OPTIONAL	- SERVICE BULLETIN ON HOLD.
23-JUN-2008	MOS HRS/MSC AFL	A/R (s)		(EFF)			
SB 560XL-34-46	NAVIGATION - HONEYWELL CD-820 FLIGHT MANAGEMENT SYSTEM (FMS) WIRING MODIFICATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
21-OCT-2005	MOS HRS/MSC AFL	-		03-AUG-2006 2775			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 560XL-34-47	NAVIGATION - UNIVERSAL PERFORMANCE DATABASE DISABLEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - NOT APPLICABLE
20-MAY-2005		MOS HRS/MSC AFL		26-AUG-2005 2353			
SB 560XL-34-50	NAVIGATION - IC-615 VERTICAL GLIDE PATH AND FLIGHT DIRECTOR IMPROVEMENTS (SUPERSEDED BY 560XL-34-50 R01), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
05-APR-2007		MOS HRS/MSC AFL		29-NOV-2007 3440			
SB 560XL-34-50 R02	NAVIGATION - IC-615 VERTICAL GLIDE PATH AND FLIGHT DIRECTOR IMPROVEMENTS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
06-AUG-2009		MOS HRS/MSC AFL	300 (s)	10-OCT-2011 4149:35 3962			
SB 560XL-34-66	NAVIGATION - INSTALLATION OF SCN 802.8 FOR UNS-1 FMS (SUPERSEDED BY 560XL-34-66 R01), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - SOFTWARE SCN 604.4
27-APR-2011		MOS HRS/MSC AFL		10-OCT-2011 4149:35 3962			
SB 560XL-34-71	NAVIGATION - TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE FOR SOFTWARE VERSION 7.0 (SUPERSEDED BY 560XL-34-71 R01), SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - N/A NO TCAS 2000 INST.
		MOS HRS/MSC AFL		18-SEP-2012 4325:32 4113			
SB 560XL-34-75	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE (SUPERSEDED BY 560XL-34-75 R01), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - TCAS 7.1 UPGRADE PERFORMED
16-JUL-2015		MOS HRS/MSC AFL		14-DEC-2015 4899:21 4602			
SB 560XL-34-75 R01	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - TCAS 7.1 UPGRADE PERFORMED
28-OCT-2015		MOS HRS/MSC AFL		14-DEC-2015 4899:21 4602			
SB 560XL-34-79 R01	NAVIGATION - LCR-100 W/SYNCHRO AHRS UPGRADE, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
21-MAR-2017		MOS HRS/MSC AFL		17-JUN-2019 5110:47 4774			
SB 560XL-36-05 R01	PNEUMATIC - BLEED AIR OVERHEAT ANNUNCIATION IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
13-MAY-2003		MOS HRS/MSC AFL		12-MAR-2004 1200			
SB 560XL-49-09	AUXILIARY POWER UNIT PRINTED CIRCUIT BOARD IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
24-APR-2002		MOS HRS/MSC AFL		11-OCT-2002 329			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 560XL-49-10 R01	AUXILIARY POWER - APU TO ENGINE START IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
23-MAY-2002	MOS HRS/MSC - AFL			11-OCT-2002 329			
SB 560XL-49-11	AUXILIARY POWER UNIT GENERATOR CONTROL UNIT WIRING IMPROVEMENT (SUPERSEDED BY 560XL-49-11 R01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
	MOS HRS/MSC A/R AFL			09-MAY-2003 641			
SB 560XL-52-06	DOORS - CABIN DOOR UPPER LATCH PLATE INSPECTION (SUPERSEDED BY 560XL-52-06 R01), SERVICE BULLETIN					MANDATORY	COMPLIED WITH
	MOS HRS/MSC - AFL			11-OCT-2002 329			
SB 560XL-52-13 R02	DOORS - BAGGAGE DOOR HINGE CHANNEL IMPROVEMENT, SERVICE BULLETIN					DISCRETIONARY	COMPLIED WITH
11-MAY-2006	MOS HRS/MSC A/R AFL			05-SEP-2008 3665			
SB 560XL-52-14 R01	DOORS - CABIN DOOR REINFORCEMENT MODIFICATION, SERVICE BULLETIN					DISCRETIONARY	COMPLIED WITH - CHANGE IN WEIGHT AND BALANCE: WEIGHT INCREASE +0.50 POUNDS, RESULTANT MOMENT +98.98 INCH-POUNDS, MOMENT/100 +1 .00 INCH-POUNDS.
23-FEB-2010	MOS HRS/MSC A/R AFL			08-FEB-2019 5066:42 4739			
SB 560XL-52-15 R01	DOORS - CABIN ENTRY DOOR COUNTERBALANCE SPRING REPLACEMENT, SERVICE BULLETIN					DISCRETIONARY	COMPLIED WITH
03-MAY-2007	MOS HRS/MSC A/R AFL			07-MAR-2013 4403:58 4177			
Note: THIS SB SHOULD BE ACCOMPLISHED WITH THE PHASE 5 INSPECTION.							
SB 560XL-52-17 R01	DOORS - CABIN ENTRY DOOR OPERATION IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
20-JUN-2008	MOS HRS/MSC A/R AFL			05-SEP-2008 3665			
Note:							
SB 560XL-52-18	DOORS - AFT BAGGAGE DOOR HINGE MONEL RIVET REPLACEMENT (SUPERSEDED BY 560XL-52-18 R01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
30-JUL-2007	MOS HRS/MSC A/R AFL			05-SEP-2008 3665			
Note:							
SB 560XL-53-05	FUSELAGE - DORSAL FIN INLET SCOOP VANE INSPECTION/REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
14-APR-2000	MOS HRS/MSC - AFL			20-DEC-2005 2464			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 560XL-53-13	FUSELAGE - NOSE DRIP CAP BOND INSPECTION (SUPERSEDED BY 560XL-53-13 R01), SERVICE BULLETIN					MANDATORY	COMPLIED WITH
20-JUL-2011		MOS HRS/MSC AFL		10-OCT-2011 4149:35 3962			
Note:							
SB 560XL-53-16	FUSELAGE - STINGER DRAIN INSTALLATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS HRS/MSC AFL		05-MAY-2012 4272:33 4072			
Note:							
SB 560XL-57-03	WINGS - WING WIRE BUNDLE ANCHOR IMPROVEMENT (SUPERSEDED BY 560XL-57-03 R01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS HRS/MSC AFL		12-MAR-2004 1200			
Note:							
SB 560XL-57-03 R01	WINGS - WING WIRE BUNDLE ANCHOR IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
20-MAY-2004		MOS HRS/MSC AFL		16-MAY-2006 2677			
Note:							
SB 560XL-57-04 R02	WINGS - VORTEX GENERATOR ADHESIVE IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
10-JUN-2004		MOS HRS/MSC AFL		15-FEB-2005 1913			
Note:							
SB 560XL-71-06	POWER PLANT - COWLING IMPROVEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
07-MAR-2002		MOS HRS/MSC AFL		23-MAY-2002 155			
Note:							
SB 560XL-71-07	POWER PLANT - MOTIVE FLOW FUEL LINE/OIL LINE CLEARANCE IMPROVEMENT (SUPERSEDED BY 560XL-71-07 R01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-OCT-2004		MOS HRS/MSC AFL		29-APR-2005 2059			
Note:							
SB 560XL-71-09	POWER PLANT - ENGINE OIL DOOR DOUBLER INSTALLATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
09-JUL-2007		MOS HRS/MSC AFL		05-SEP-2008 3665			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 560XL-71-11 R01	POWER PLANT - ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
02-AUG-2012		MOS HRS/MSC - AFL		01-APR-2019 5066:42 4739			
Note:							
SB 560XL-73-01	ENGINE FUEL AND CONTROL - ENGINE FUEL LINE FITTING INSPECTION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
20-SEP-2002		MOS HRS/MSC - AFL		01-APR-2019 5066:42 4739			
Note:							
SB 560XL-80-03	STARTING - APU GENERATOR CONTROL UNIT (GCC) CURRENT LIMITING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
13-JAN-2005		MOS HRS/MSC - AFL		29-APR-2005 2059			
Note:							
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING, SERVICE LETTER					MANDATORY	NOT APPLICABLE - BY DATE CARTRIDGES
16-JUN-2016		MOS HRS/MSC - AFL		26-JAN-2017 4967:11 4654			
Note:							
SL CIL-34-02	NAVIGATION - TRANSMITTAL OF HONEYWELL SIL D201301000032, PRIMUS II INTEGRATED RADIO SYSTEM, SERVICE LETTER					MANDATORY	COMPLIED WITH - FOUND UNITS INSATLLED & MOD'S CARRIED OUT
18-MAR-2013		MOS HRS/MSC - AFL		18-APR-2013 4410:34 4181			
Note:							
SL CIL-34-03	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014300-22-16, MODIFICATION (MOD) R TO DU-870 DISPLAY UNIT PN 7014300-901 AND -902; DECREASE FAILURE RATE OF HIGH VOLTAGE POWER SUPPLY (HVPS) BECAUSE OF HIGH HUMIDITY (SUPERSEDED BY CIL-34-03 R01), SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - SUPERSEDED BY R1
10-OCT-2013		MOS HRS/MSC - AFL		02-NOV-2014 4674:21 4389			
Note:							
SL CIL-34-03 R01	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014300-22-16, MODIFICATION (MOD) R TO DU-870 DISPLAY UNIT PN 7014300-901 AND -902; DECREASE FAILURE RATE OF HIGH VOLTAGE POWER SUPPLY (HVPS) BECAUSE OF HIGH HUMIDITY (SUPERSEDED BY CIL-34-03 R02), SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - SUPERSEDED BY R2
13-NOV-2013		MOS HRS/MSC - AFL		02-NOV-2014 4674:21 4389			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001, SERVICE LETTER					MANDATORY	NOT APPLICABLE - BY PN AND SN OXYGEN MASK
08-JAN-2016		DAYs		23-JAN-2016			
		HRS/MSC	-	4914.06			
		AFL		4609			
Note:							
SL SL560XL-05-03	TIME LIMITS/MAINTENANCE CHECKS - CONVERSION FROM CALENDAR SCHEDULE MAINTENANCE PROGRAM TO MSG-3 SCHEDULE MAINTENANCE PROGRAM, SERVICE LETTER					OPTIONAL	COMPLIED WITH - SL560XL-05-03 WAS INCORPORATED ON 560XL-5230 WITHOUT BEING REMOVED FROM SERVICE. FROM THIS DATE FORWARD, THE CITATION XL MSG-3 MAINTENANCE PLAN APPLIES TO 560XL-5230. FOR QUESTIONS, CONTACT TEXTRON AVIATION MAINTENANCE ENGINEERING DEPARTMENT, WICHITA, KS AT +1 316-517-9370
17-JAN-2018		MOS		04-APR-2019			
		HRS/MSC	-	5066.42			
		AFL		4739			
Note:							
SL SL560XL-21-03	AIR CONDITIONING - TEMPERATURE SENSOR MODIFICATION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
16-JAN-2002		MOS		11-OCT-2002			
		HRS/MSC	-	329			
		AFL					
Note:							
SL SL560XL-21-04	AIR CONDITIONING - AIR CYCLE MACHINE ASPIRATOR TUBING INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
14-JUN-2002		MOS		11-OCT-2002			
		HRS/MSC	-	329			
		AFL					
Note:							
SL SL560XL-21-05	AIR CONDITIONING - R-134A AIR CONDITIONING SYSTEM WIRING INSPECTION, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE
31-MAY-2007		MOS		22-JAN-2008			
		HRS/MSC	A/R	3487			
		AFL					
Note:							
SL SL560XL-21-06	AIR CONDITIONING - DROPPED AISLE DUCT IMPROVEMENT, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
16-JUL-2002		MOS		11-OCT-2002			
		HRS/MSC	-	329			
		AFL					
Note:							
SL SL560XL-21-07	AIR CONDITIONING - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 2215460-21-2762, ENVIRONMENTAL CONTROL UNIT (ECU) - INSPECT AND REPLACE THE OVER TEMPERATURE SWITCH (SUPERSEDED BY SL560XL-21-07 R01), SERVICE LETTER					RECOMMENDED	COMPLIED WITH
		MOS		09-MAY-2003			
		HRS/MSC	A/R	641			
		AFL					
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL560XL-23-04 R01	COMMUNICATIONS - AIRSHOW RELIABILITY IMPROVEMENTS AND SERVICE PACK SOFTWARE UPGRADE, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - NOT APPLICABLE
11-MAR-2003		MOS HRS/MSC - AFL		09-MAY-2003 641			
Note:							
SL SL560XL-23-05	COMMUNICATIONS - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN A21-3851-001, RCZ INTEGRATED COMMUNICATION UNIT, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
03-APR-2003		MOS HRS/MSC - AFL		12-MAR-2004 1200			
Note:							
SL SL560XL-24-01	ELECTRICAL POWER - BATTERY DISCONNECT RELAY BUS BAR GROUNDING PLATE INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
24-JUL-2003		MOS HRS/MSC - AFL		12-MAR-2004 1200			
Note:							
SL SL560XL-24-02	ELECTRICAL POWER - MAIN ENGINE AND APU GROUND INSTALLATION INSPECTION AND BOND CHECK, SERVICE LETTER					DISCRETIONARY	COMPLIED WITH
25-MAR-2004		MOS HRS/MSC - AFL		29-APR-2005 2059			
Note:							
SL SL560XL-24-07	ELECTRICAL POWER - RIGHT AC GENERATOR WIRE ROUTING VERIFICATION, SERVICE LETTER					MANDATORY	COMPLIED WITH
13-JAN-2017		DAYS HRS/MSC - AFL		15-FEB-2017 4977:06 4666			
Note:							
SL SL560XL-25-02	EQUIPMENT/FURNISHINGS - TOILET SHROUD ASSEMBLY INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
02-FEB-2004		MOS HRS/MSC - AFL		23-JUL-2004 1489			
Note:							
SL SL560XL-25-10	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF PACIFIC SCIENTIFIC AEROSPACE SERVICE BULLETIN SB 25-1111432, INFORMATION REGARDING THE POTENTIAL FAILURE OF THE GUARDED ROTARY BUCKLE PLASTIC HANDLE, SERVICE LETTER					MANDATORY	COMPLIED WITH
10-DEC-2007		MOS HRS/MSC A/R AFL		05-SEP-2008 3665			
Note:							
SL SL560XL-27-06	FLIGHT CONTROLS - ELEVATOR ELECTRIC TRIM TAB ACTUATOR MOUNT INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
01-AUG-2002		MOS HRS/MSC - AFL		11-OCT-2002 329			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL560XL-27-08	FLIGHT CONTROLS - RUDDER ASSEMBLY CONDUIT TUBE INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
20-SEP-2002	MOS HRS/MSC - AFL			09-MAY-2003 641			
Note:							
SL SL560XL-27-13	FLIGHT CONTROLS - ELEVATOR TRIM CABLE INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
15-OCT-2004	MOS HRS/MSC - AFL			15-FEB-2005 1913			
Note:							
SL SL560XL-27-17	FLIGHT CONTROLS - ELEVATOR TRIM WHEEL INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - NO NOTES
01-DEC-2008	MOS HRS/MSC 300 (s) AFL			13-DEC-2010 4060 3887			
Note:							
SL SL560XL-27-20 R02	FLIGHT CONTROLS - RUDDER TORQUE TUBE/SECTOR ASSEMBLY GAP INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH - SHIM INSTALLED IAW SL560XL-27-20R2
18-JAN-2014	MOS HRS/MSC - AFL			19-MAR-2014 4566:55 4303			
Note:							
SL SL560XL-27-21	FLIGHT CONTROLS - RUDDER TORQUE TUBE/SECTOR ASSEMBLY INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH - NO PAINT CRACKS OR OTHER OBVIOUS FOUND
18-JAN-2014	MOS HRS/MSC - AFL			14-FEB-2014 4561:51 4299			
Note:							
SL SL560XL-27-33	FLIGHT CONTROLS - ELEVATOR CABLE INSPECTION AT THE AFT CANTED BULKHEAD, SERVICE LETTER					MANDATORY	COMPLIED WITH - INSPECTED AND FOUND CLEARANCE >0.10"
05-NOV-2014	MOS HRS/MSC - AFL			30-JAN-2015 4675:30 4392			
Note:							
SL SL560XL-27-34	FLIGHT CONTROLS - RIGHT OUTBOARD AILERON WING UP CABLE ASSEMBLY INSPECTION (SUPERSEDED BY SL560XL-27-34 R01), SERVICE LETTER					MANDATORY	COMPLIED WITH - CABLE WAS REPLACED AND FOUND IN COMPLIANCE
09-JAN-2015	MOS HRS/MSC - AFL			30-JAN-2015 4675:30 4392			
Note:							
SL SL560XL-27-34 R01	FLIGHT CONTROLS - RIGHT OUTBOARD AILERON WING UP CABLE ASSEMBLY INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH - R0 C/W
22-JAN-2015	MOS HRS/MSC - AFL			30-JAN-2015 4675:30 4392			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL560XL-27-34 R02	FLIGHT CONTROLS - RIGHT OUTBOARD AILERON WING UP CABLE ASSEMBLY INSPECTION, SERVICE LETTER					MANDATORY	NOT APPLICABLE - NOT APPLICABLE AS PER SL560XL-27-34 R01 COMPLIANCE
12-JUN-2019		MOS HRS/MSC - AFL		08-AUG-2019 5215:27 4849			
Note:							
SL SL560XL-27-35	FLIGHT CONTROLS - AFT AILERON SECTOR ASSEMBLY INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH
		DAYS HRS/MSC - AFL		26-JAN-2017 4967:11 4654			
Note:							
SL SL560XL-28-05 R01	FUEL - FUEL BOOST PUMP INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH - C/W FOUND PN LR55505-2 INST
12-DEC-2013		MOS HRS/MSC - AFL		19-MAR-2014 4566:55 4303			
Note:							
SL SL560XL-29-01	HYDRAULIC POWER - HYDRAULIC RESERVOIR INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
14-MAY-2002		MOS HRS/MSC - AFL		11-OCT-2002 329			
Note:							
SL SL560XL-29-03	HYDRAULIC POWER - ENGINE HYDRAULIC HOSE INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - BOTH HOSES , AFFECTED BY THIS SL , REPL. ON LH ENG. (WC2975)
10-JUN-2009		MOS HRS/MSC 300 (s) AFL		23-JUL-2010 3995 3837			
Note:							
SL SL560XL-29-05	HYDRAULIC POWER - ENGINE DRIVEN PUMP HYDRAULIC VERIFICATION, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - BY PN HYDRAULIC PUMP, PN 9912062-4 IS INSTALLED
14-JUN-2017		MOS HRS/MSC - AFL		21-SEP-2017 5052 4732			
Note:							
SL SL560XL-31-03	INDICATING/RECORDING SYSTEMS - INSTRUMENT PANEL INSTALLATION MODIFICATION (SUPERSEDED BY SL560XL-31-03 R01), SERVICE LETTER					DISCRETIONARY	COMPLIED WITH
17-OCT-2005		MOS HRS/MSC - AFL		16-MAY-2006 2677			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL560XL-31-05	INDICATING/RECORDING SYSTEMS - TRANSMITTAL OF L-3 COMMUNICATIONS ALERT BULLETIN NO. CESSNA SB 001, SERVICE LETTER				MANDATORY	NOT APPLICABLE - NA BY S/N INSTALLED	
04-AUG-2011		MOS HRS/MSC AFL	A/R	10-OCT-2011 4149:35 3962			
Note:							
SL SL560XL-32-18	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE BULLETINS 3-1571-32-2 AND 3-1571-32-3, SERVICE LETTER				RECOMMENDED	COMPLIED WITH	
02-AUG-2007		MOS HRS/MSC AFL	A/R	05-SEP-2008 3665 3583			
Note:							
SL SL560XL-32-20	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE LETTER 2056, SERVICE LETTER				RECOMMENDED	COMPLIED WITH	
02-AUG-2007		MOS HRS/MSC AFL	A/R	05-SEP-2008 3665 3583			
Note:							
SL SL560XL-32-23	LANDING GEAR - EMERGENCY GEAR RELEASE INSPECTION, SERVICE LETTER				RECOMMENDED	COMPLIED WITH - NO NOTES	
17-AUG-2009		MOS HRS/MSC AFL	150 (s)	13-DEC-2010 4060 3887			
Note:							
SL SL560XL-32-26	LANDING GEAR - REPLACEMENT OF THE COTTER PIN FOR THE EMERGENCY GEAR-RELEASE, SERVICE LETTER				MANDATORY	COMPLIED WITH	
06-AUG-2010		MOS HRS/MSC AFL	A/R	06-JUL-2011 4149:21 3957			
Note:							
SL SL560XL-33-10	LIGHTS - AFT SIDELEDGE DIVIDER LIGHT INSPECTION/REPLACEMENT, SERVICE LETTER				RECOMMENDED	COMPLIED WITH	
06-AUG-2010		MOS HRS/MSC AFL	A/R	10-OCT-2011 4149:35 3962			
Note:							
SL SL560XL-34-07	NAVIGATION - TRANSMITTAL OF HONEYWELL PUBLICATION NUMBER A21-3440-001, PRIMUS 1000/2000 INTEGRATED AVIONICS SYSTEM- AZ840/850 MICRO AIR DATA COMPUTER (MADC) - INSPECT FOR PRESENCE OF VENDOR SPECIFIC COMPONENTS AND REPLACE AS REQUIRED, SERVICE LETTER				RECOMMENDED	COMPLIED WITH	
27-OCT-2003		MOS HRS/MSC AFL	-	12-MAR-2004 1200			
Note:							
SL SL560XL-34-11	NAVIGATION - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014700-34-0040, SERVICE LETTER				RECOMMENDED	COMPLIED WITH - NOT APPLICABLE	
30-JUL-2003		MOS HRS/MSC AFL	-	12-MAR-2004 1200			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL560XL-34-13	NAVIGATION - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 965-0976-XXX-34-70, ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) (SUPERSEDED BY SL560XL-34-13 R01), SERVICE LETTER					DISCRETIONARY	COMPLIED WITH
MOS HRS/MSC A/R AFL							
12-MAR-2004 1200							
Note:							
SL SL560XL-34-14	NAVIGATION - FLUX VALVE INSPECTION CRITERIA, SERVICE LETTER					INFORMATIONAL	COMPLIED WITH - NO FLUX VALVE LEAKAGE FOUND AT THIS TIME ON THE LEFT OR RIGHT FLUX VALVES. NO FURTHER ACTION REQUIRED.
MOS HRS/MSC - (s) AFL							
08-FEB-2019 5066:42 4739							
Note:							
SL SL560XL-34-18	NAVIGATION - ELEMENTARY SURVEILLANCE TRANSPONDER PRODUCT IMPROVEMENT, SERVICE LETTER					MANDATORY	NOT APPLICABLE
MOS HRS/MSC - AFL							
06-APR-2007 3103							
Note:							
SL SL560XL-35-04	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SL560XL-35-04 R01), SERVICE LETTER					MANDATORY	NOT APPLICABLE - NA BY DATE OF MANUFACTURE
MOS HRS/MSC - AFL							
10-OCT-2011 4149:35 3962							
Note:							
SL SL560XL-35-04 R02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240, SERVICE LETTER					MANDATORY	NOT APPLICABLE - BY SN EQUIPMENT - SN 107073 & SN 93628 ARE INSTALLED
MOS HRS/MSC - AFL							
18-APR-2013 4410:34 4181							
Note:							
SL SL560XL-36-01 R01	PNEUMATIC - PARTICULATE TRAP DRAIN HOLE ADDITION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
MOS HRS/MSC - AFL							
11-OCT-2002 329							
Note:							
SL SL560XL-36-02	PNEUMATIC - ENGINE BLEED AIR COUPLING SAFETY WIRE ADDITION, SERVICE LETTER					MANDATORY	COMPLIED WITH
MOS HRS/MSC - AFL							
23-MAY-2002 155							
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL560XL-38-01	WATER/WASTE - TRANSMITTAL OF MONOGRAM SYSTEMS SERVICE INFORMATION LETTER SIL15900-023, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - SB560XL-38-02 WAS NOT PREV.COMPLIED WITH.
06-JAN-2011		MOS HRS/MSC AFL	A/R	05-AUG-2011 4149:21 3962			
Note:							
SL SL560XL-52-02	DOORS - EMERGENCY EXIT DOOR CHAFING INSPECTION AND REPAIR, SERVICE LETTER					MANDATORY	COMPLIED WITH
12-FEB-2004		MOS HRS/MSC AFL	-	23-JUL-2004 1489			
Note:							
SL SL560XL-52-03	DOORS - CABIN DOOR ANNUNCIATION IMPROVEMENT (SUPERSEDED BY SL560XL-52-03 R01), SERVICE LETTER					RECOMMENDED	COMPLIED WITH
29-MAR-2005		MOS HRS/MSC AFL	-	29-APR-2005 2059			
Note:							
SL SL560XL-52-08	DOORS - CABIN DOOR LINTEL FASTENER VERIFICATION, SERVICE LETTER					RECOMMENDED	DEFERRED
14-MAY-2020		MOS HRS/MSC AFL	-	16-JUN-2020 5628:59 5080			
Note:							
SL SL560XL-53-05	FUSELAGE STINGER DRAIN HOLE INSTALLATION, SERVICE LETTER					MANDATORY	COMPLIED WITH
01-APR-2005		MOS HRS/MSC AFL	A/R	29-APR-2005 2059			
Note:							
SL SL560XL-53-06	FUSELAGE FS 528.50 FRAME DRAIN HOLE INSTALLATION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
20-OCT-2005		MOS HRS/MSC AFL	-	16-MAY-2006 2677			
Note:							
SL SL560XL-53-17	FUSELAGE - DORSAL DUCT INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - NO DAMAGE NOTED DURING THE INSPECTION PHASE OF THE SERVICE LETTER. NO FURTHER ACTION REQUIRED AT THIS TIME.
20-NOV-2012		MOS HRS/MSC AFL	-	08-FEB-2019 5066:42 4739			
Note:							
SL SL560XL-55-01	STABILIZERS - PIVOT FITTING INSPECTION (SUPERSEDED BY SL560XL-55-01 R01), SERVICE LETTER					MANDATORY	NOT APPLICABLE - SUPERSEDED BY R1
		MOS HRS/MSC AFL	-	23-SEP-2016 4967:11 4654			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL560XL-55-01 R01	STABILIZERS - PIVOT FITTING INSPECTION (SUPERSEDED BY SL560XL-55-01 R02), SERVICE LETTER					MANDATORY	NOT APPLICABLE - SUPERSEDED BY R2
Note:							
SL SL560XL-55-01 R02	STABILIZERS - PIVOT FITTING INSPECTION (SUPERSEDED BY SL560XL-55-01 R03), SERVICE LETTER					MANDATORY	NOT APPLICABLE - SUPERSEDED BY R3
Note:							
SL SL560XL-55-01 R03	STABILIZERS - PIVOT FITTING INSPECTION, SERVICE LETTER					CANCELLED	NOT APPLICABLE - SL CANCELLED
09-JUN-2016				MOS	23-SEP-2016		
				HRS/MSC	-	4967:11	
				AFL		4654	
Note:							
SL SL560XL-56-01	WINDOWS - OPENABLE COCKPIT WINDOW HINGE AND LATCH INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH
30-AUG-2006				MOS	21-NOV-2006		
				HRS/MSC	A/R	2908	
				AFL			
Note:							
SL SL560XL-56-03	WINDOWS - OPENABLE COCKPIT WINDOW HINGE AND LATCH INSPECTION, SERVICE LETTER					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER SEE SERVICE LETTER FOR APPLICABILITY.
07-DEC-2010				MOS			
				HRS/MSC	A/R		
				AFL			
Note:							
SL SL560XL-71-02 R01	POWER PLANT - ENGINE ELECTRICAL GROUND INSPECTION FOR RTV, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
14-JAN-2003				MOS	09-MAY-2003		
				HRS/MSC	-	641	
				AFL			
Note:							
SL SL560XL-71-03	POWER PLANT - ENGINE MOUNT BOLT TORQUE INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH
21-MAR-2003				MOS	09-MAY-2003		
				HRS/MSC	-	641	
				AFL			
Note:							
SL SL560XL-71-04	POWER PLANT - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 30240 REPLACEMENT OF THE ALTERNATOR SHAFT PLAIN SEAL, SERVICE LETTER					DISCRETIONARY	COMPLIED WITH
25-JUN-2004				MOS	20-DEC-2005		
				HRS/MSC	-	2464	
				AFL			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL560XL-71-06	POWER PLANT - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW500-72-30248 TURBOFAN ENGINE FRONT FAN CASE ASSEMBLY VIBRATION DAMPER RING-INSTALLATION, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE
14-JUN-2005		MOS HRS/MSC AFL		03-AUG-2006 2775			
Note:							
SL SL560XL-71-07	POWER PLANT - TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SPECIAL INSTRUCTION NUMBER 17-2005, PW500 AUTO SHUT - OFF MECHANISM INSPECTION., SERVICE LETTER					MANDATORY	COMPLIED WITH
15-JUN-2005		MOS HRS/MSC AFL		16-MAY-2006 2677			
Note:							
SL SL560XL-71-08	POWER PLANT - BLEED AIR TUBE SLEEVING INSTALLATION IMPROVEMENT, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
15-JUN-2005		MOS HRS/MSC AFL		21-NOV-2006 2908			
Note:							
SL SL560XL-71-09	POWER PLANT - TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SB NUMBER 30294R2, TURBOFAN ENGINE OIL TANK FILLER CAP INSPECTION, SERVICE LETTER					INFORMATIONAL	COMPLIED WITH
15-JUN-2006		MOS HRS/MSC AFL		10-OCT-2006 2842			
Note:							
SL SL560XL-71-11 R01	POWER PLANT - INSPECT THE LEFT AND RIGHT ENGINE FORWARD UPPER AND LOWER ISOLATOR ASSEMBLY MOUNT BOLT HEADS FOR SAFETY WIRE HOLES, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
29-AUG-2019		MOS HRS/MSC AFL		11-OCT-2019 5321:40 4913			
Note:							
SL SL560XL-71-11 R02	POWER PLANT - INSPECT THE LEFT AND RIGHT ENGINE FORWARD UPPER AND LOWER ISOLATOR ASSEMBLY MOUNT BOLT HEADS FOR SAFETY WIRE HOLES, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - COMPLIED WITH AS PER SL560XL-71-11 R01 PERFORMED ON 11OCT 2019
23-OCT-2019		MOS HRS/MSC AFL		02-DEC-2019 5396:52 4953			
Note:							
SL SL560XL-72-03 R03	ENGINE - TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) PW500-72-30196, REVISION 3, TURBOFAN ENGINE - REPLACEMENT OF P3 BELLows SEALS, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - BY ENGINE SERIAL NUMBER
14-SEP-2004		MOS HRS/MSC AFL		16-APR-2013 4410:34 4181			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL560XL-72-04	ENGINE - TRANSMITTAL OF P&WC SERVICE BULLETIN PW500-72-30110R1, TURBOFAN ENGINE- OIL LEVEL INDICATOR- REPLACEMENT OF, SERVICE LETTER						NOT APPLICABLE - BY ENGINE SERIAL NUMBER
15-MAR-2001		MOS HRS/MSC - AFL		16-APR-2013 4410:34 4181			
Note:							
SL SL560XL-72-05	ENGINE - TRANSMITTAL OF P&WC SERVICE BULLETIN PW500-72-30135R1, TURBOFAN ENGINE- OIL FILLER CAP- REPLACEMENT OF, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - BY ENGINE SERIAL NUMBER
15-MAR-2001		MOS HRS/MSC - AFL		16-APR-2013 4410:34 4181			
Note:							
SL SL560XL-72-08	ENGINE - TRANSMITTAL OF P&WC SERVICE BULLETIN PW500-72-30203 REPLACEMENT OF ALTERNATOR SHAFT PLAIN SEAL, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
01-MAY-2002		MOS HRS/MSC - AFL		18-MAY-2004 1323			
Note:							
SL SL560XL-72-09	ENGINE - TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30217, TURBOFAN ENGINE FUEL TUBE - INSPECTION OF, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
03-JUN-2002		MOS HRS/MSC A/R AFL		22-AUG-2002 280			
Note:							
SL SL560XL-72-13	RIGHT ENGINE TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30335 TURBOFAN ENGINE GAS-GENERATOR-CASE TO INTERMEDIATE-CASE RETAINING-BOLTS BORESCOPE INSPECTION OF, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
27-NOV-2007		MOS HRS/MSC A/R AFL		05-SEP-2008 3665			
Note:							
SL SL560XL-72-13	LEFT ENGINE TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30335 TURBOFAN ENGINE GAS-GENERATOR-CASE TO INTERMEDIATE-CASE RETAINING-BOLTS BORESCOPE INSPECTION OF, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
27-NOV-2007		MOS HRS/MSC A/R AFL		05-SEP-2008 3665			
Note:							
SL SL560XL-72-14	LEFT ENGINE TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW500-72-30306 TURBOFAN ENGINE NEW TRANSFER TUBES WITH HEAT SHIELD, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - SB 30306R4 C/W
		MOS HRS/MSC A/R AFL		17-JUN-2012 4272:33 4072			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL560XL-72-14	RIGHT ENGINE TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW500-72-30306 TURBOFAN ENGINE RECOMMENDED NEW TRANSFER TUBES WITH HEAT SHIELD, SERVICE LETTER						COMPLIED WITH - SB 30306R4 PERFORMED
	MOS HRS/MSC A/R AFL			12-AUG-2011 4149:35 3962			
	Note:						
SL SL560XL-72-17	LEFT ENGINE TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT, MODIFICATION OF, SERVICE LETTER					MANDATORY	COMPLIED WITH - CESCOM ADJUSTED IAW LATEST REV. OF P&WC SB. 30409
	MOS HRS/MSC AFL		6 (s)	26-FEB-2010 3945 3796			
	Note: CESCOM DEFAULTS TO MOST RESTRICTIVE TBO. PLEASE NOTIFY CESCOM OF CORRECT DUE POINT FOR YOUR AIRCRAFT.						
SL SL560XL-72-17	RIGHT ENGINE TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT, MODIFICATION OF, SERVICE LETTER					MANDATORY	COMPLIED WITH - CESCOM ADJUSTED IAW LATEST REV. OF P&WC SB. 30409
	MOS HRS/MSC AFL		6 (s)	26-FEB-2010 3945 3796			
	Note: CESCOM DEFAULTS TO MOST RESTRICTIVE TBO. PLEASE NOTIFY CESCOM OF CORRECT DUE POINT FOR YOUR AIRCRAFT.						
SL SL560XL-73-03	ENGINE FUEL AND CONTROL - TRANSMITTAL OF P&WC SERVICE BULLETIN 30249 TURBOFAN ENGINE FUEL MANIFOLD - INSPECTION/REPLACEMENT OF AND COMMERCIAL SUPPORT PROGRAM NOTIFICATION (CSPN) A03008, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - NOT APPLICABLE
15-JAN-2004				MOS HRS/MSC - AFL	29-APR-2005 2059		
	Note:						
SL SL560XL-73-04	ENGINE FUEL AND CONTROL - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 30253: TURBOFAN ENGINE FUEL PRESSURE TUBE REPLACEMENT AND ATTENUATOR INTRODUCTION OF MODEL APPLICATION PW545A AND COMMERCIAL SUPPORT PROGRAM NOTIFICATION (CSPN) A03012 (SUPERSEDED BY SL560XL-73-04 R01), SERVICE LETTER					RECOMMENDED	COMPLIED WITH
	MOS HRS/MSC A/R AFL			06-JAN-2004 1130			
	Note:						
SL SL560XL-73-08	ENGINE FUEL AND CONTROL - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN NUMBER 30296R1, TURBOFAN ENGINE HFC RATIO UNIT SETSCREW ADJUSTMENT - INSPECTION OF, SERVICE LETTER					MANDATORY	COMPLIED WITH
	MOS HRS/MSC - AFL			07-MAY-2006 2677			
	Note:						
SL SL560XL-73-12	ENGINE FUEL AND CONTROL - TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30381R2, FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE/FAIRING/REPLACEMENT OF (SUPERSEDED BY SL560XL-73-12 R01), SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - SUPERSEDED BY R1
10-NOV-2009				MOS HRS/MSC A/R AFL	17-JUN-2012 4272:33 4072		
	Note:						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL560XL-73-12 R01	ENGINE FUEL AND CONTROL - TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30381R2, FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE/FAIRING/REPLACEMENT OF, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - SB 30381R2 C/W ON LH ENG AT 17 JUN 2012 ON RH ENG AT 12 AUG 2011
12-DEC-2011		MOS HRS/MSC AFL		17-JUN-2012 4272:33 4072			
Note:							
SL SL560XL-76-04	ENGINE CONTROLS - THROTTLE QUADRANT RVDT LINKAGE INSPECTION, SERVICE LETTER					MANDATORY	NOT APPLICABLE - N/A BY AIRCRAFT S/N
12-NOV-2020		MOS HRS/MSC AFL		17-JUN-2022 7366:02 6120			
Note:							
SL SL560XL-76-04 R01	ENGINE CONTROLS - THROTTLE QUADRANT RVDT LINKAGE INSPECTION, SERVICE LETTER					MANDATORY	NOT APPLICABLE - N/A BY AIRCRAFT S/N
24-NOV-2020		MOS HRS/MSC AFL		17-JUN-2022 7366:02 6120			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
APU - SB - P-268/3800722-1							
SB	3615880-49-8149 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN 3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS, SERVICE BULLETIN				RECOMMENDED	NOT APPLICABLE - BY PN TURBINE ROTOR
			20-OCT-2015	MOS HRS/MSC - AFL APUS	26-OCT-2015 2642:18 4898		
				Note:			
SB	3822101-49-8148 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, PN 3822101-1, ON MULTIPLE APUS, SERVICE BULLETIN				RECOMMENDED	NOT APPLICABLE - BY PN COMPRESSOR ROTOR
			20-OCT-2015	MOS HRS/MSC - APUS	26-OCT-2015 2642:18 4898		
				Note:			
SB	70721598-49-8168 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS, SERVICE BULLETIN				RECOMMENDED	NOT APPLICABLE - BY PN COMPRESSOR ROTOR
			20-OCT-2015	MOS HRS/MSC - APUS	26-OCT-2015 2642:18 4898		
				Note:			
SB	70721725-49-8152 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS, SERVICE BULLETIN				RECOMMENDED	NOT APPLICABLE - BY PN TURBINE ROTOR
			24-AUG-2015	MOS HRS/MSC - APUS	26-OCT-2015 2642:18 4898		
				Note:			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - AD - PCE-DB0473/31J1900-01							
FAA 2003-03-21	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ONE-TIME VISUAL INSPECTION AND RE-MARKING, OR IN LIEU OF INSPECTION, REPLACEMENT OF CERTAIN PART NUMBERS (P/N'S) OF THE FLEXIBLE FUEL TUBE LOCATED BETWEEN THE FUEL/OIL HEAT EXCHANGER AND THE INTEGRAL FUEL CONTROL UNIT-FUEL PUMP						COMPLIED WITH
	MOS HRS/MSC - APUS			07-APR-2003 567			
	Note:						
FAA 2010-18-09	NO. 1 ENGINE - INTERCOMPRESSOR BLEED VALVE/SERVO VALVE					MANDATORY	NOT APPLICABLE - NA ENGINE SN DB 0473 AND SN DB 0472 ARE PRE SB 30343 AND PRE 30404
	MOS HRS/MSC - ENC			09-NOV-2010 4049 3877			
	Note:						
FAA 2010-18-09 PARA (E)(2)	NO. 1 ENGINE - ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE REMOVE					MANDATORY	NOT APPLICABLE - NA ENGINE SN DB 0473 AND SN DB 0472 ARE PRE SB 30343 AND PRE 30404
	MOS HRS/MSC - ENC			09-NOV-2010 4049 3877			
	Note:						
FAA 2010-18-09 PARA (E)(3)	NO. 1 ENGINE - ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE ENGINE TESTING					MANDATORY	NOT APPLICABLE - NA ENGINE SN DB 0473 AND SN DB 0472 ARE PRE SB 30343 AND PRE 30404
	MOS HRS/MSC - ENC			09-NOV-2010 4049 3877			
	Note:						
TCCA CF-2002-42	NO. 1 ENGINE - PRATT & WHITNEY CANADA (P&WC) PW530A, PW535A, AND PW545A ENGINES - INSPECTION OF FLEXIBLE FUEL TUBES					MANDATORY	COMPLIED WITH - SUPERSEDED BY FAA 2003-03-21
14-OCT-2002	MOS HRS/MSC - ENC			09-JUN-2022 7350 6101			
	Note:						
TCCA CF-2010-19	NO. 1 ENGINE - INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION					MANDATORY	NOT APPLICABLE - SUPERSEDED BY ASB PW500-72-A30421 N/A - ENGINE S/N IS PRE SB 30343 AND SB 30404 REF. W.C 4201
	MOS HRS/MSC A/R ENC			09-JUN-2022 7350 6101			
	Note:						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2010-19 STEP A,B,C,D,E,F,G	NO. 1 ENGINE - INCORPORATION INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION OF ASB A30421					MANDATORY	NOT APPLICABLE - SUPERSEDED BY ASB PW500-72-A30421 N/A - ENGINE S/N IS PRE SB 30343 AND SB 30404 REF. W.C 4201
		MOS		09-JUN-2022			
		HRS/MSC	A/R	7350			
		ENC		6101			
Note:							
TCCA CF-2010-19 STEP H.	NO. 1 ENGINE - TEST INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION PROCEDURE PART A					MANDATORY	NOT APPLICABLE - SUPERSEDED BY ASB PW500-72-A30421 N/A - ENGINE S/N IS PRE SB 30343 AND SB 30404 REF. W.C 4201
		MOS		09-JUN-2022			
		HRS/MSC	A/R	7350			
		ENC		6101			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 2 - AD - PCE-DB0472/31J1900-01							
FAA 2003-03-21	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ONE-TIME VISUAL INSPECTION AND RE-MARKING, OR IN LIEU OF INSPECTION, REPLACEMENT OF CERTAIN PART NUMBERS (P/N'S) OF THE FLEXIBLE FUEL TUBE LOCATED BETWEEN THE FUEL/OIL HEAT EXCHANGER AND THE INTEGRAL FUEL CONTROL UNIT-FUEL PUMP						COMPLIED WITH
	MOS HRS/MSC - ENC			07-APR-2003 567			
	Note:						
FAA 2010-18-09	NO. 2 ENGINE - INTERCOMPRESSOR BLEED VALVE/SERVO VALVE					MANDATORY	NOT APPLICABLE - NA ENGINE SN DB 0473 AND SN DB 0472 ARE PRE SB 30343 AND PRE 30404
	MOS HRS/MSC - ENC			09-NOV-2010 4049 3877			
	Note:						
FAA 2010-18-09 PARA (E)(2)	NO. 2 ENGINE - ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE REMOVE					MANDATORY	NOT APPLICABLE - NA ENGINE SN DB 0473 AND SN DB 0472 ARE PRE SB 30343 AND PRE 30404
	MOS HRS/MSC - ENC			09-NOV-2010 4049 3877			
	Note:						
FAA 2010-18-09 PARA (E)(3)	NO. 2 ENGINE - ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE ENGINE TESTING					MANDATORY	NOT APPLICABLE - NA ENGINE SN DB 0473 AND SN DB 0472 ARE PRE SB 30343 AND PRE 30404
	MOS HRS/MSC - ENC			09-NOV-2010 4049 3877			
	Note:						
TCCA CF-2002-42	NO. 2 ENGINE - PRATT & WHITNEY CANADA (P&WC) PW530A, PW535A, AND PW545A ENGINES - INSPECTION OF FLEXIBLE FUEL TUBES					MANDATORY	COMPLIED WITH - SUPERSEDED BY FAA 2003-03-21
14-OCT-2002	MOS HRS/MSC - ENC			09-JUN-2022 7350 6101			
	Note:						
TCCA CF-2010-19	NO. 2 ENGINE - INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION					MANDATORY	NOT APPLICABLE - SUPERSEDED BY ASB PW500-72-A30421 N/A - ENGINE S/N IS PRE SB 30343 AND SB 30404 REF. W.C 4201
	MOS HRS/MSC A/R ENC			09-JUN-2022 7350 6101			
	Note:						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2010-19 STEP A,B,C,D,E,F,G	NO. 2 ENGINE - INCORPORATION INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION OF ASB A30421					MANDATORY	NOT APPLICABLE - SUPERSEDED BY ASB PW500-72-A30421 N/A - ENGINE S/N IS PRE SB 30343 AND SB 30404 REF. W.C 4201
		MOS		09-JUN-2022			
		HRS/MSC	A/R	7350			
		ENC		6101			
Note:							
TCCA CF-2010-19 STEP H.	NO. 2 ENGINE - TEST INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION PROCEDURE PART A					MANDATORY	NOT APPLICABLE - SUPERSEDED BY ASB PW500-72-A30421 N/A - ENGINE S/N IS PRE SB 30343 AND SB 30404 REF. W.C 4201
		MOS		09-JUN-2022			
		HRS/MSC	A/R	7350			
		ENC		6101			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - SB - PCE-DB0473/31J1900-01							
ASB	PW500-72-A30421	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R01), ALERT SERVICE BULLETIN				CATEGORY 3	NOT APPLICABLE - NA ENGINE SN DB 0473 AND SN DB 0472 ARE PRE SB 30343 AND PRE SB 30404 REF W.C 4201
		MOS		09-NOV-2010			
		HRS/MSC	-	4049			
		ENC		3877			
Note:							
ASB	PW500-72-A30421 R01	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R02), ALERT SERVICE BULLETIN				CATEGORY 3	NOT APPLICABLE - NA ENGINE SN DB 0473 AND SN 0472 ARE PRE SB 30343 AND PRE SB 30404 REF W.C 4201
		MOS		09-NOV-2010			
		HRS/MSC	-	4049			
		ENC		3877			
Note:							
SB	PW500-72-30110 R01	NO. 1 ENGINE - REPLACEMENT OF OIL LEVEL INDICATOR, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - BY ENGINE SERIAL NUMBER
	09-NOV-2000	MOS		16-APR-2013			
		HRS/MSC	-	4410:34			
		ENC		4181			
Note:							
SB	PW500-72-30135 R01	NO. 1 ENGINE - REPLACEMENT OF OIL FILLER CAP, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - BY ENGINE SERIAL NUMBER
	09-NOV-2000	MOS		16-APR-2013			
		HRS/MSC	-	4410:34			
		ENC		4181			
Note:							
SB	PW500-72-30196 R03	NO. 1 ENGINE - REPLACEMENT OF P3 BELLows SEALS, SERVICE BULLETIN				CATEGORY 3	NOT APPLICABLE - BY ENGINE SERIAL NUMBER
	23-JUN-2004	MOS		16-APR-2013			
		HRS/MSC	-	4410:34			
		ENC		4181			
Note:							
SB	PW500-72-30217 R03	NO. 1 ENGINE - INSPECTION OF FUEL TUBE, SERVICE BULLETIN				CATEGORY 3	COMPLIED WITH - E1 NOT Affected DUE TO P/N: 30J2757-01
	20-JUN-2018	MOS		27-AUG-2019			
		HRS/MSC	-	5252:35			
		ENC		4867			
Note:							
SB	PW500-72-30306 R04	NO. 1 ENGINE - NEW TRANSFER TUBES WITH HEAT SHIELD (SUPERSEDED BY PW500-72-30306 R05), SERVICE BULLETIN				CATEGORY 5	COMPLIED WITH
	18-MAY-2007	MOS		17-JUN-2012			
		HRS/MSC	-	4272			
		ENC		4072			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30340 R02	NO. 1 ENGINE - REPLACEMENT OF IGNITERS AND IGNITION CABLES, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
26-SEP-2008		MOS HRS/MSC - ENC		23-JUL-2010 3995:13 3837			
Note:							
SB PW500-72-30381 R02	NO. 1 ENGINE - REPLACEMENT OF FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
06-AUG-2009		MOS HRS/MSC ENC		17-JUN-2012 4272:33 4072			
Note:							
SB PW500-72-30409 R06	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R07), SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
28-SEP-2010		MOS HRS/MSC - ENC		10-OCT-2011 4149:35 3962			
Note:							
SB PW500-72-30409 R10	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - NO EFFECT PREVIOUS REVISION C/W
29-JUN-2010		MOS HRS/MSC - ENC		22-NOV-2015 4882:22 4589			
Note:							
SB PW500-72-30419	NO. 1 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30419 R01), SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - NEW COMBUSTION LINER INST. BY H&S WO 6448687
28-SEP-2010		MOS HRS/MSC - ENC		18-JUN-2012 4272:33 4072			
Note:							
SB PW500-72-30420	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R01), SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - SUPERSEDED SUPERSEDED BY REVISION 1
29-JUN-2010		MOS HRS/MSC - (s) ENC					
Note:							
SB PW500-72-30420 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R02), SERVICE BULLETIN					CATEGORY 6	- -SUPERSEDED BY REVISIOIN 2
29-SEP-2010		MOS HRS/MSC - ENC					
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30420 R03	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R04), SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - REPL BLEED VALVE SERVO VALVE
		MOS		19-MAR-2014			
		HRS/MSC	-	4566:55			
		ENC		4303			
Note:							
SB PW500-72-30479 R06	NO. 1 ENGINE - REPLACEMENT OF NO. 4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - SB 72-30479 R06 CARRIED OUT DURING ENGINE OVERHAUL
		MOS		19-MAR-2019			
20-MAY-2016		HRS/MSC	-				
		ENC					
Note:							
SB PW500-72-30505 R01	NO. 1 ENGINE - REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS (SUPERSEDED BY PW500-72-30505 R02), SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - REPLACED GASKETS & ATTACHMENT HARDWARE
		MOS		24-APR-2015			
07-NOV-2014		HRS/MSC	-	4732:50			
		ENC		4450			
Note:							
SB PW500-72-30512 R02	NO. 1 ENGINE - INSPECTION/ REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R03), SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - N/A - ENGINE IS PRE SB 30442
		MOS		08-MAY-2015			
		HRS/MSC	-	4740:52			
		ENC		4460			
Note:							
SB PW500-72-30545	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - SB PW500-72-30545 IS NOT APPLICABLE AS PER R02 PERFORMED ON 19MAR19
		MOS		19-MAR-2019			
28-SEP-2018		HRS/MSC	-				
		ENC		4739			
Note:							
SB PW500-72-30545 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT, SERVICE BULLETIN						NOT APPLICABLE - SB PW500-72-30545 R01 IS NOT APPLICABLE AS PER R02 PERFORMED ON 19MAR19
		MOS		19-MAR-2019			
08-FEB-2019		HRS/MSC	-				
		ENC		4739			
Note:							
SB PW500-72-30545 R02	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
		MOS		19-MAR-2019			
11-MAR-2019		HRS/MSC	-				
		ENC		4739			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30545 R03	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - SB PW500-72-30545 R03 IS NOT APPLICABLE AS PER R02 PERFORMED ON 19MAR19
28-MAY-2019		MOS HRS/MSC - ENC		19-MAR-2019 4739			
Note:							
SB PW500-72-30545 R04	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - SB PW500-72-30545 R04 IS NOT APPLICABLE AS PER R02 PERFORMED ON 19MAR19
09-AUG-2019		MOS HRS/MSC - ENC		19-MAR-2019 5066:42			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 2 - SB - PCE-DB0472/31J1900-01							
ASB PW500-72-A30421	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R01), ALERT SERVICE BULLETIN				CATEGORY 3	NOT APPLICABLE - NA ENGINE SN DB 0473 AND SN DB 0472 ARE PRE SB 30343 AND PRE SB 30404 REF W.C 4201	
	MOS			09-NOV-2010			
	HRS/MSC	-		4049			
	ENC			3877			
Note:							
ASB R01 PW500-72-A30421	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R02), ALERT SERVICE BULLETIN				CATEGORY 3	NOT APPLICABLE - NA ENGINE SN DB 0473 AND SN DB 0472 ARE PRE SB 30343 AND PRE 30404	
	MOS			09-NOV-2010			
	HRS/MSC	-		4049			
	ENC			3877			
Note:							
ASB R01 PW500-72-A30452	NO. 2 ENGINE - TURBOFAN ENGINE - OIL SYSTEM - SPECIAL INSPECTION OF MOP (SUPERSEDED BY PW500-72-A30452 R02), ALERT SERVICE BULLETIN				CATEGORY 3	COMPLIED WITH	
	MOS			18-JUN-2012			
	HRS/MSC	-		4272:33			
	ENC			4072			
Note:							
SB PW500-72-30110 R01	NO. 2 ENGINE - REPLACEMENT OF OIL LEVEL INDICATOR, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - BY ENGINE SERIAL NUMBER	
09-NOV-2000	MOS			16-APR-2013			
	HRS/MSC	-		4410:34			
	ENC			4181			
Note:							
SB PW500-72-30135 R01	NO. 2 ENGINE - REPLACEMENT OF OIL FILLER CAP, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - BY ENGINE SERIAL NUMBER	
09-NOV-2000	MOS			16-APR-2013			
	HRS/MSC	-		4410:34			
	ENC			4181			
Note:							
SB PW500-72-30196 R03	NO. 2 ENGINE - REPLACEMENT OF P3 BELLows SEALS, SERVICE BULLETIN				CATEGORY 3	NOT APPLICABLE - BY ENGINE SERIAL NUMBER	
23-JUN-2004	MOS			16-APR-2013			
	HRS/MSC	-		4410:34			
	ENC			4181			
Note:							
SB PW500-72-30217 R03	NO. 2 ENGINE - INSPECTION OF FUEL TUBE, SERVICE BULLETIN				CATEGORY 3	COMPLIED WITH - E2 NOT Affected DUE TO P/N: 30J2757-01	
20-JUN-2018	MOS			27-AUG-2019			
	HRS/MSC	-		5252:35			
	ENC			4867			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30218 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF FOKKER ELMO ENGINE HARNESS, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH
14-JUN-2002		MOS HRS/MSC - ENC		12-AUG-2011 4149:18 3962			
Note:							
SB PW500-72-30288 R01	NO. 2 ENGINE - MODIFICATION OF TURBINE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30288 R02), SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
22-FEB-2005		MOS HRS/MSC - ENC		12-AUG-2011 4149:18 3962			
Note:							
SB PW500-72-30306 R04	NO. 2 ENGINE - NEW TRANSFER TUBES WITH HEAT SHIELD (SUPERSEDED BY PW500-72-30306 R05), SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH
18-MAY-2007		MOS HRS/MSC - ENC		12-AUG-2011 4149:18 3962			
Note:							
SB PW500-72-30316 R01	NO. 2 ENGINE - REPLACEMENT OF TRANSFER TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH
18-JAN-2007		MOS HRS/MSC - ENC		12-AUG-2011 4149:18 3962			
Note:							
SB PW500-72-30331	NO. 2 ENGINE - MODIFICATION OF FUEL PRESSURE HOSE & TUBE ROUTING, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH
05-JUN-2007		MOS HRS/MSC - ENC		12-AUG-2011 4149:18 3962			
Note:							
SB PW500-72-30335 R01	NO. 2 ENGINE - BORESCOPE INSPECTION OF GAS-GENERATOR-CASE TO INTERMEDIATE-CASE RETAINING-BOLTS, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
		MOS HRS/MSC - ENC		12-AUG-2011 4149:18 3962			
Note:							
SB PW500-72-30340 R02	NO. 2 ENGINE - REPLACEMENT OF IGNITERS AND IGNITION CABLES, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
26-SEP-2008		MOS HRS/MSC - ENC		23-JUL-2010 3995:13 3837			
Note:							
SB PW500-72-30362	NO. 2 ENGINE - REPLACEMENT HP TURBINE DISK BALANCING ASSEMBLY WITH THICKER FEATHER SEALS , SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
05-JUN-2008		MOS HRS/MSC - ENC		12-AUG-2011 4149:18 3962			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30381 R02	NO. 2 ENGINE - REPLACEMENT OF FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
06-AUG-2009		MOS HRS/MSC ENC	A/R	12-AUG-2011 4149:18 3962			
Note:							
SB PW500-72-30384	NO. 2 ENGINE - REPLACEMENT OF AIR/OIL SEPARATOR (SUPERSEDED BY PW500-72-3084 R01), SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
02-FEB-2009		MOS HRS/MSC ENC	-	12-AUG-2011 4149:18 3962			
Note:							
SB PW500-72-30409 R06	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R07), SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
15-JUN-2011		MOS HRS/MSC ENC	-	10-OCT-2011 4149:35 3962			
Note:							
SB PW500-72-30409 R10	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - NO EFFECT PREVIOUS REVISION C/W
29-APR-2010		MOS HRS/MSC ENC	-	22-NOV-2015 4882:22 4589			
Note:							
SB PW500-72-30413 R03	NO. 2 ENGINE - INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R04), SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
15-JUN-2011		MOS HRS/MSC ENC	A/R	12-AUG-2011 4149:18 3962			
Note:							
SB PW500-72-30416	NO. 2 ENGINE - REPLACEMENT OF NO.4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30416 R01), SERVICE BULLETIN						COMPLIED WITH
29-APR-2010		MOS HRS/MSC ENC	A/R	12-AUG-2011 4149:18 3962			
Note:							
SB PW500-72-30420	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R01), SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - SUPERSEDED SUPERSEDED BY REVISION 1
29-JUN-2010		MOS HRS/MSC ENC	- (s)				
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30420 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R02), SERVICE BULLETIN					CATEGORY 6	- -SUPERSEDED BY REVISIOIN 2
29-SEP-2010		MOS HRS/MSC - ENC					
Note:							
SB PW500-72-30420 R03	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R04), SERVICE BULLETIN				19-MAR-2014	CATEGORY 3	COMPLIED WITH - REPL BLEED VALVE SERVO VALVE
		MOS HRS/MSC - ENC			4566:55 4303		
Note:							
SB PW500-72-30425	NO. 2 ENGINE - REPLACEMENT OF NO. 4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30425 R01), SERVICE BULLETIN				12-AUG-2011	CATEGORY 3	COMPLIED WITH
02-NOV-2010		MOS HRS/MSC A/R ENC			4149:18 3962		
Note:							
SB PW500-72-30429 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R02), SERVICE BULLETIN				12-AUG-2011	CATEGORY 6	COMPLIED WITH
15-JUN-2011		MOS HRS/MSC A/R ENC			4149:18 3962		
Note:							
SB PW500-72-30440 R02	NO. 2 ENGINE - REPLACEMENT OF TURBOFAN ENGINE NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R03), SERVICE BULLETIN				18-JUN-2012	CATEGORY 6	COMPLIED WITH
		MOS HRS/MSC A/R ENC			4272:33 4072		
Note:							
SB PW500-72-30479 R06	NO. 2 ENGINE - REPLACEMENT OF NO. 4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE, SERVICE BULLETIN				19-MAR-2019	CATEGORY 3	COMPLIED WITH - SB 72-30479 R06 CARRIED OUT DURING ENGINE OVERHAUL
20-MAY-2016		MOS HRS/MSC - ENC					
Note:							
SB PW500-72-30482	NO. 2 ENGINE - INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY PW500-72-30482 R01), SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - PRE SB 30419
		MOS HRS/MSC - ENC					
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30482 R02	NO. 2 ENGINE - INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY PW500-72-30482 R03), SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - PRE SB 30419
Note:							
SB PW500-72-30505 R01	NO. 2 ENGINE - REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS (SUPERSEDED BY PW500-72-30505 R02), SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - REPLACED GASKETS & ATTACHMENT HARDWARE
Note:							
07-NOV-2014		MOS		27-FEB-2014			
		HRS/MSC	-	4566:55			
		ENC		4303			
Note:							
SB PW500-72-30512 R02	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R03), SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - N/A - ENGINE IS PRE SB 30442
Note:							
SB PW500-72-30545	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - SB PW500-72-30545 IS NOT APPLICABLE AS PER R02 PERFORMED ON 19MAR19
28-SEP-2018		MOS		19-MAR-2019			
		HRS/MSC	-				
		ENC		4739			
Note:							
SB PW500-72-30545 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT, SERVICE BULLETIN						NOT APPLICABLE - SB PW500-72-30545 R01 IS NOT APPLICABLE AS PER R02 PERFORMED ON 19MAR19
08-FEB-2019		MOS		19-MAR-2019			
		HRS/MSC	-				
		ENC		4739			
Note:							
SB PW500-72-30545 R02	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
11-MAR-2019		MOS		19-MAR-2019			
		HRS/MSC	-				
		ENC		4739			
Note:							
SB PW500-72-30545 R03	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - SB PW500-72-30545 R03 IS NOT APPLICABLE AS PER R02 PERFORMED ON 19MAR19
28-MAY-2019		MOS		19-MAR-2019			
		HRS/MSC	-				
		ENC		4739			
Note:							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30545 R04	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - SB PW500-72-30545 R04 IS NOT APPLICABLE AS PER R02 PERFORMED ON 19MAR19
09-AUG-2019		MOS HRS/MSC - ENC		19-MAR-2019 5066:42			

Note: