

**Company**

 Owner: ABS Jets, a.s.  
 Operator:

**Major Assemblies**









<b>Airframe</b>	560XL (Citation XLS 560-6325 +)	13-Oct-2024	1359:56 Hrs	957 Ldg	923:54 Hrs(APU)	26 Start(APU)
<b>Eng 1</b>	PW545C	<b>PCE-DF0667</b>	13-Oct-2024	1359:56 Hrs	957 Enc	
<b>Eng 2</b>	PW545C	<b>PCE-DF0666</b>	13-Oct-2024	1026:48 Hrs	742 Enc	
<b>APU 1</b>	RE100[XL]	<b>P-1131</b>	01-Oct-2024	923:54 Hrs	26 APUS	








**Additional Information**













Program Type: MSG-3, General Categories: FAR 91,Extended TBO,Honeywell Avionics,Extended HSI











 Cost: 85+  
 Man Hrs: 1,003.55+












**Analyst:** Laurence Kirk [lkirk@jetsupport.com](mailto:lkirk@jetsupport.com)












Task No SEQ PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
▼ 2 - *Reserved for Airline Use										
<b>SL560XL-02-01</b>	<b>Year 2000 Readiness Disclosure</b>								T (A/R)	Informational
 2 A/F										
Eff: 03-Dec-1998										
<b>SL560XL-02-02</b>	<b>Airport Noise Abatement Information</b>								RE (-)	Recommended
 2 A/F										
Not Applicable	effective before manufacture									
<b>SL560XL-02-02 Rev 01</b>	<b>Airport Noise Abatement Information</b>								T (A/R)	Informational
 2 A/F										
Eff: 10-Jan-2002										
<b>SL560XL-02-03</b>	<b>Miscellaneous - Cessna CD-ROM Technical Library</b>								T (A/R)	Informational
 2 A/F										
Eff: 11-Nov-1999										
▼ 3 - *Reserved for Airline Use										
<b>CIL-03-01</b>	<b>Certification Requirements - Supplemental Type Certificate (STC)</b>								T (A/R)	Informational
 3 A/F										
Eff: 03-Jun-2013										
<b>SL560XL-03-01</b>	<b>Supplemental Type Certificate (STC) - CANCELLED</b>								RE (-)	Service Letter
 3 A/F										
<b>SL560XL-03-01 Rev 01</b>	<b>Supplemental Type Certificate (STC) - CANCELLED</b>								T (A/R)	Service Letter
 3 A/F										
Eff: 03-Jun-2013										
▼ 5 - TIME LIMITS/MAINTENANCE CHECKS										
<b>SL560XL-05-01</b>	<b>Time Limits/Maintenanance Checks - Transmittal of Pratt &amp; Whitney Canada Maintenance Manual Temporary Revision No. 05-6, Scheduled Maintenance Checks</b>								T (A/R)	Informational
 5 A/F										
Eff: 06-Dec-2002										

Task No		Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
SL560XL-05-02		Corrosive Environment Inspection						T (A/R)		Informational		
	5 A/F											
	Eff: 23-Feb-2006											
SL560XL-05-05		Time Limit/Maintenance Checks - MSG-3 Scheduled Maintenance Program Change Bridging Document						RE (-)		Service Letter		
	5 A/F											
	Eff: 08-Aug-2018											
SL560XL-05-05 Rev 1		Time Limit/Maintenance Checks - MSG-3 Scheduled Maintenance Program Change Bridging Document						RE (-)		Informational, Service Letter		
	5 A/F											
	Eff: 28-Sep-2018											
SL560XL-05-05 Rev 2		Time Limit/Maintenance Checks - MSG-3 Scheduled Maintenance Program Change Bridging Document						RE (-)		Informational, Service Letter		
	5 A/F											
	Eff: 31-Jan-2019											
SL560XL-05-06		Time Limits/Maintenance Checks - New AE13083-5 Engine and Auxiliary Power Unit Fire Extinguisher Cartridge Squib Interval Grace Period Implementation						T (A/R)		Informational, Service Letter		
	5 A/F											
	Eff: 31-Jan-2019											
▼ 11 - PLACARDS AND MARKINGS												
SL560XL-11-01		Model 560XL Illustrated Parts Catalog and Maintenance Manual Changes						T (A/R)		Informational		
	11 A/F											
	Eff: 01-Oct-2003											
▼ 20 - STANDARD PRACTICES – AIRFRAME												
560XL-20-04		Standard Practices - Cessna Standard Practices Manual						T (A/R)		Service Letter		
	20 A/F											
	Eff: 05-Oct-2017											
CIL-20-01		Standard Practices - Cessna Certification Of Nondestructive Testing Facilities/Personnel						RE (-)		Informational		
	20 A/F											
	Eff: 09-Apr-2012											
CIL-20-01 R3		Standard Practices - Cessna Certification of Nondestructive Testing Facilities/Personnel (This SL has been Cancelled)						RE (-)		Service Letter		
	20 A/F											
	Eff: 30-May-2023											
CIL-20-01 Revision 1		Standard Practices - Cessna Certification Of Nondestructive Testing Facilities/Personnel						RE (-)		Informational		
	20 A/F											
SL560XL-20-01		Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional		
	20 A/F											
SL560XL-20-01 Rev 01		Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional		
	20 A/F											










Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-20-01 Rev 02  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-20-01 Rev 03  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-20-01 Rev 04  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-20-01 Rev 05  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-20-01 Rev 06  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-20-01 Rev 07  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-20-01 Rev 08  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-20-01 Rev 09  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-20-01 Rev 10  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-20-01 Rev 11  20 A/F Eff: 21-Sep-2012	Cessna Certification of Nondestructive Testing Facilities/Personnel						T (A/R)		Informational	
					Mos					
					Hrs					
					Ldg					
▼ 21 - AIR CONDITIONING AND PRESSURIZATION										
2013-09-11  21 A/F Eff: 05-Jul-2013 Not Applicable (ISSUING AUTHORITY: FAA)	Air Conditioning Due to aircraft is not in suspect serial range						RE (-)		Mandatory	
					Mos	22-Jun-2022				
					Hrs	8				
					Ldg	6				
2013-09-11 Par. (m)  21 A/F Not Applicable (ISSUING AUTHORITY: FAA)	Air Conditioning - Replacement Of The Brushes On A/C Compressor Motors, Part Nos. 1134104-1/1134104-5, Or Deactivation Of The A/C System Parts Return And Reporting Requirements due to S/N						RE (-)		Mandatory	
					Mos	22-Jun-2022				
					Hrs					
					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>CIL-21-03</b>	<b>Air Conditioning - Transmittal of Honeywell Service Bulletin 2341316-21-2828, Inspection and Repair of the Interior Surfaces of the Water Separator, PN 2341316-2 and -3, for Corrosion</b>						T (-)		Informational	
 21 A/F Eff: 22-Oct-2015						Mos				
						Hrs				
						Ldg				
Note: This service letter is for informational purposes only.										
<b>CIL-21-03 R1</b>	<b>Air Conditioning - Transmittal of Honeywell Service Bulletin 2341316-21-2828, Inspection and Repair of the Interior Surfaces of the Water Separator, PN 2341316-2 and -3, for Corrosion</b>						T (A/R)		Informational	
 21 A/F Eff: 25-May-2022						Mos				
						Hrs				
						Ldg				
<b>SL560XL-21-07</b>	<b>Transmittal of Honeywell Service Bulletin 2215460-21-2762, Environmental Control Unit (ECU) - Inspect and Replace the Over Temperature Switch</b>						RE (-)		Optional	
 21 A/F						Mos				
						Hrs				
						Ldg				
<b>SL560XL-21-07 Rev 01</b>	<b>Transmittal of Honeywell Service Bulletin 2215460-21-2762, Environmental Control Unit (ECU) - Inspect and Replace the Over Temperature Switch</b>						RE (-)		Recommended	
 21 A/F Eff: 10-Feb-2004 Not Applicable	effective before manufacture					Mos	22-Jun-2022			
						Hrs	8			
						Ldg	6			
<b>SL560XL-21-12</b>	<b>Transmittal of Honeywells Service Bulletin 2215460-21-2814, Air Conditioning - Environmental Control Unit - Modification of Environmental Control Unit (ECU), PN 2215460-3 Series 1, By Replacement of Compressor Outlet Over Temperature Switch, PN 927223-2-2</b>						RE (-)		Informational	
 21 A/F Eff: 03-Jun-2010						Mos				
						Hrs				
						Ldg				
▼ 23 - COMMUNICATIONS										
<b>FA2100CVR SB024 Rev 4</b>	<b>MOD DOT 17 Introduction of New CSMU Part Number</b>						RE (-)		Recommended	
 23 A/F Eff: 15-Sep-2023 Complied With	MOD 17 already c/w					Mos	05-Oct-2023			
						Hrs	732:45			
						Ldg	484			
Note: CONCURRENT REQUIREMENTS: This Service Bulletin is eligible only for recorders with MOD DOT 14. For P/N 2100-1925-22, Service Bulletin FA2100CVR-033 (ATA No. 23-70-04-033) which installs Software Revision 12 and CSMU, Part No. 253E6995-06 must be completed after this Service Bulletin (SB).										
<b>SB560XL-23-10</b>	<b>Communications - Aviator 300 SATCOM Intermediate Gain Antenna (IGA) Replacement</b>						RE (-)		Optional	
 23 A/F Eff: 16-Jun-2021						Mos				
						Hrs				
						Ldg				
<b>SB560XL-23-11</b>	<b>Communications - ATN-B1 Controller Pilot Data Link Communications (CPDLC) Installation</b>						T (A/R)		Optional	
 23 A/F Eff: 07-Apr-2022						Mos				
						Hrs				
						Ldg				
<b>SL560XL-23-01</b>	<b>Communication - Transmittal Of Airshow Service Bulletin 920720-1 Airshow 400 Digital Interface Unit</b>						T (A/R)		Optional	
 23 A/F Eff: 04-Nov-1999						Mos				
						Hrs				
						Ldg				
<b>SL560XL-23-02</b>	<b>Communication - Transmittal Of Airshow Service Bulletin 20721-1 Genesys Data Communication Unit</b>						T (A/R)		Optional	
 23 A/F Eff: 04-Nov-1999						Mos				
						Hrs				
						Ldg				









Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>SL560XL-23-09</b>	<b>Communications - SITA Datalink Frequency Change for North America</b>						T (A/R)		Service Letter	
 23 A/F						Mos				
Eff: 12-May-2017						Hrs				
						Ldg				
Note: COMPLIANCE: This service document is for informational purposes only.										
<b>SL560XL-23-10</b>	<b>Communications - ATG 4000 Software Update</b>						RE (-)		Service Letter	
 23 A/F						Mos				
Eff: 12-Sep-2017						Hrs				
						Ldg				
<b>SL560XL-23-11</b>	<b>Communications - ATG 4000 Software Update To Version 2.8</b>						T (A/R)		Service Letter	
 23 A/F						Mos				
Eff: 25-Jan-2018						Hrs				
						Ldg				
<b>SL560XL-23-12</b>	<b>Communications - Installation of the Satcom Antenna Doublers</b>						RE (-)		Optional	
 23 A/F						Mos				
Eff: 12-Jul-2019						Hrs				
						Ldg				
<b>SL560XL-23-13</b>	<b>Communications - Cockpit Voice Recorder (CVR) Control Panel Replacement</b>						RE (-)		Recommended	
 23 A/F						Mos	22-Jun-2022			
Eff: 18-Aug-2021 Not Applicable	effective before manufacture					Hrs	8			
(AVG MAN HRS: 3)						Ldg	6			
<b>SL560XL-23-14</b>	<b>Communications - Transmittal of Collins Operators Bulletin - OPSB 0244-23 RIU-4010 CPDLC ATN-B1 Dropouts</b>						T (A/R)		Informational	
 23 A/F						Mos				
Eff: 27-Nov-2023						Hrs				
						Ldg				
Note: NOTE: This service letter is applicable to the aircraft serial numbers listed above that have complied with Optional Service Bulletin SB560XL-23-11 - Communication - ATN-B1 Controller Pilot Data Link Communications (CPDLC) Installation, original issue or latest.										
▼ 24 - ELECTRICAL POWER										
<b>2017-04-14</b>	<b>Electrical Power - Inspections of the Fuel Tube and Right Alternating Current (AC) Generator Wires</b>						RE (-)		Mandatory	
 24 A/F						Mos	22-Jun-2022			
Eff: 09-Mar-2017 Complied With						Hrs	8			
(AVG MAN HRS: 17) (ISSUING AUTHORITY: FAA)						Ldg	6			
<b>2017-04-14 Par. 2(g)</b>	<b>Electrical Power - Inspections of the Fuel Tube and Right Alternating Current (AC) Generator Wires - Inspections, Adjustments, and Corrective Actions</b>						RE (-)		Mandatory	
 24 A/F						Mos	22-Jun-2022			
Eff: 09-Mar-2017 Complied With						Hrs	8			
(AVG MAN HRS: 16) (ISSUING AUTHORITY: FAA)						Ldg	6			
<b>2017-04-14 Par. 2(h)</b>	<b>Electrical Power - Inspections of the Fuel Tube and Right Alternating Current (AC) Generator Wires - Reporting</b>						RE (-)		Mandatory	
 24 A/F						Mos	22-Jun-2022			
Eff: 09-Mar-2017 Complied With						Hrs	8			
(AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA)						Ldg	6			
<b>560XL-24-01</b>	<b>Electrical Power - Saft Battery Installation</b>						T (A/R)		Optional	
 24 A/F						Mos				
Eff: 13-May-1999						Hrs				
						Ldg				
<b>560XL-24-02</b>	<b>Electrical Power - Concorde Battery Installation</b>						RE (-)		Recommended	
 24 A/F						Mos	22-Jun-2022			
Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			












Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>560XL-24-02 Rev 01</b>	<b>Electrical Power - Concorde Battery Installation</b>						T (A/R)		Optional	
 24 A/F						Mos				
Eff: 20-Feb-2001						Hrs				
						Ldg				
<b>560XL-24-16</b>	<b>APU Starter/Generator Wiring Improvement</b>						RE (-)		Recommended	
 24 A/F						Mos	22-Jun-2022			
Eff: 15-Nov-2010 Not	effective before manufacture					Hrs	8			
Applicable						Ldg	6			
<b>560XL-24-17</b>	<b>Tailcone Inverter Relocation</b>						RE (-)		Discretionary	
 24 A/F						Mos				
Eff: 28-Jul-2010						Hrs				
						Ldg				
<b>560XL-24-18</b>	<b>Standby Power Wiring Modification</b>						RE (-)		Recommended	
 24 A/F						Mos	22-Jun-2022			
Eff: 03-Nov-2011 Not	effective before manufacture					Hrs	8			
Applicable						Ldg	6			
<b>560XL-24-19</b>	<b>Electrical Power - Right Hand Engine Wire Bundle Routing Improvement</b>						RE (-)		Recommended	
 24 A/F						Mos	22-Jun-2022			
Eff: 08-Mar-2017 Not	effective before manufacture					Hrs	8			
Applicable						Ldg	6			
(AVG MAN HRS: 1)										
<b>560XL-24-20</b>	<b>Electrical Power - AC J-Box Wire Bundle Anchor Installation</b>						RE (-)		Mandatory	
 24 A/F						Mos	22-Jun-2022			
Eff: 03-Oct-2017 Not	by S/N					Hrs	8			
Applicable						Ldg	6			
(AVG MAN HRS: 3)										
<b>SB560XL-24-21</b>	<b>Electrical Power - Install New Right Alternator Power Control Unit (PCU) (UE016) Mounting Bracket</b>						RE (-)	Recommended, Service Bulletin		
 24 A/F						Mos	22-Jun-2022			
Eff: 08-Nov-2019 Complied With						Hrs	8			
(AVG MAN HRS: 3)						Ldg	6			
<b>SB560XL-24-21 R1</b>	<b>Electrical Power - Install New Right Alternator Power Control Unit (PCU) (UE016) Mounting Bracket</b>						RE (-)	Recommended		
 24 A/F						Mos	22-Jun-2022			
Eff: 13-Mar-2020 Not	basic issue c/w					Hrs	8			
Applicable						Ldg	6			
(AVG MAN HRS: 3)										
<b>SL560XL-24-07</b>	<b>Electrical Power - Right Ac Generator Wire Routing Verification</b>						RE (-)		Mandatory	
 24 A/F						Mos	22-Jun-2022			
Eff: 13-Jan-2017 Not	by aircraft S/N					Hrs	8			
Applicable						Ldg	6			
(AVG MAN HRS: 16)										
<b>SL560XL-24-08</b>	<b>Starting - Engine Starter Generator and Auxiliary Power Unit (APU) Starter Generator Ground Repair</b>						RE (-)		Service Letter	
 24 A/F						Mos				
Eff: 02-Jan-2018						Hrs				
(AVG MAN HRS: 13)						Ldg				
<b>SL560XL-24-09</b>	<b>Electrical Power - Battery Temperature Indicator Gage Blanking Plate Installation</b>						RE (-)		Service Letter	
 24 A/F						Mos				
Eff: 30-Mar-2018						Hrs				
						Ldg				











Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
▼ 25 - EQUIPMENT/FURNISHINGS										
<b>2023-12-25</b>	<b>Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets</b>								RE (-)	Mandatory
25 A/F						Mos	08-Aug-2023			
Eff: 23-Aug-2023 Not Applicable	as per installed P/N					Hrs	616:39			
(ISSUING AUTHORITY: FAA)						Ldg	407			
Note: APPLICABILITY: This AD applies to Survitec Group Limited (RFD Beaufort Ltd.) life jackets identified in paragraphs (c) (1) and (2) of this AD, having a part number and serial number identified in tables 2 through 13 of Survitec [RFD] Alert Service Bulletin 25-207-A, Version 1, dated November 24, 2021, and a date of manufacture between October 1, 2018, and April 30, 2019, inclusive.										
<b>2023-12-25 Par. (g)</b>	<b>Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets - Inspection</b>								RE (-)	Mandatory
25 A/F						Mos	08-Aug-2023			
Eff: 23-Aug-2023 Not Applicable	as per installed P/N					Hrs	616:39			
(ISSUING AUTHORITY: FAA)						Ldg	407			
Note: COMPLIANCE: Within 4 months after the effective date of this AD, do a general visual inspection for a discrepancy (mismatch of the valise/container description and life jacket type) of the life jacket, in accordance with paragraphs 2.A. through 2.C. of the Accomplishment Instructions of Survitec [RFD] Alert Service Bulletin 25-207-A, Version 1, dated November 24, 2021.										
<b>2023-12-25 Par. (h)</b>	<b>Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets - Follow-On and Corrective Action</b>								RE (-)	Mandatory
25 A/F						Mos	08-Aug-2023			
Eff: 23-Aug-2023 Not Applicable	as per installed P/N					Hrs	616:39			
(ISSUING AUTHORITY: FAA)						Ldg	407			
Note: COMPLIANCE: Before further flight after accomplishing the requirements of paragraph (g) of this AD, do the applicable actions required by paragraph (h)(1) and (2) of this AD.										
<b>2023-14-10</b>	<b>Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats (Supersedes FAA AD 2019-21-06)</b>								RE (-)	Mandatory (Appliance AD)
25 A/F						Mos	08-Aug-2023			
Eff: 07-Sep-2023 Not Applicable	affected seats not installed					Hrs	616:39			
(ISSUING AUTHORITY: FAA)						Ldg	407			
Note: APPLICABILITY: (1) This AD applies to: (i) Ipeco Holdings Limited (Ipeco) pilot and co-pilot seats with a part number (P/N) listed in Paragraph 1.A., Planning Information, Tables 1 and 2, of Ipeco Service Bulletin (SB) Number 063-25-14, Revision 00, dated August 14, 2018, and (ii) Ipeco pilot seat P/N 3A063-0099-01-1 and Ipeco co-pilot seat P/N 3A063-0100-01-1. (2) These seats are installed on, but not limited to, ATR-GIE Avions de Transport Regional ATR 42 and ATR 72 airplanes.										
<b>2023-14-10 Par. (g)(1)</b>	<b>Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Modify and Re-Identify each Affected Pilot and Co-Pilot Seat</b>								RE (-)	Mandatory (Appliance AD)
25 A/F						Yrs	08-Aug-2023			
Eff: 12-Dec-2017 Not Applicable	affected seats not installed					Hrs	616:39			
(ISSUING AUTHORITY: FAA)						Ldg	407			
Note: COMPLIANCE: For seats that have not installed the track lock spring modification kit, within two years after December 12, 2017 (the effective date of AD 2017-22-02, Amendment 39-19082 (82 FR 51552, November 7, 2017)), modify and re-identify each affected pilot and co-pilot seat using the Accomplishment Instructions of Ipeco SB Number 063-25-08, Revision 00; Ipeco SB Number 063-25-09, Revision 00; or Ipeco SB Number 063-25-10, Revision 00; all dated May 31, 2016, as applicable to each affected seat.										
<b>2023-14-10 Par. (g)(2)(i)</b>	<b>Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Inspect the Track Lock Spring of Each Seat</b>								RE (-)	Mandatory (Appliance AD)
25 A/F						Mos	08-Aug-2023			
Eff: 07-Sep-2023 Not Applicable	affected seats not installed					Hrs	616:39			
(ISSUING AUTHORITY: FAA)						Ldg	407			
<b>2023-14-10 Par. (g)(2)(ii)</b>	<b>Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Replace both Track Lock Springs of the Affected Seat</b>								RE (-)	Mandatory (Appliance AD)
25 A/F						Mos	08-Aug-2023			
Eff: 07-Sep-2023 Not Applicable	affected seats not installed					Hrs	616:39			
(ISSUING AUTHORITY: FAA)						Ldg	407			
Note: COMPLIANCE: If, during any inspection as required by paragraph (g)(2)(i) of this AD, any damage on, or incorrect installation of, any track lock spring is found on the pilot or co-pilot seat, before further flight, replace both track lock springs of the affected seat with a part eligible for installation using the Accomplishment Instructions, paragraph 3.3.3.1 or 3.3.3.2, as applicable, of Ipeco SB Number 063-25-14, Revision 00, dated August 14, 2018.										












Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>2023-14-10 Par. (h)</b>		<b>Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - New Mandatory Terminating Action</b>						RE (-)		Mandatory (Appliance AD)	
	25 A/F	affected seats not installed  (ISSUING AUTHORITY: FAA) Note: COMPLIANCE: As a mandatory terminating action to the inspections required by paragraph (g)(2)(i) of this AD, within 12 months after the effective date of this AD, or at the next Base Maintenance check, whichever occurs later, modify and re-identify each affected seat in accordance with the Accomplishment Instructions of Ipeco SB Number 063-25-15, Issue 2; SB Number 063-25-16, Issue 2; SB Number 063-25-17, Issue 2; or SB Number 063-25-18, Issue 2; all dated March 8, 2022, as applicable to each affected seat.					Mos	08-Aug-2023			
	Eff: 07-Sep-2023 Not Applicable						Hrs	616:39			
							Ldg	407			
<b>560XL-25-12</b>		<b>Glareshield Leather Strip Installation</b>						RE (-)		Optional	
	25 A/F						Mos				
							Hrs				
							Ldg				
<b>560XL-25-12 Rev 01</b>		<b>Glareshield Leather Strip Installation</b>						T (A/R)		Optional	
	25 A/F	Eff: 24-Aug-2004					Mos				
							Hrs				
							Ldg				
<b>560XL-25-18</b>		<b>Equipment/Furnishings - Passenger Seat Web Guide Improvement</b>						RE (-)		Optional	
	25 A/F	Eff: 20-Aug-2015					Mos				
							Hrs				
							Ldg				
<b>74-08-09 R2</b>		<b>Equipment/furnishings - Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles</b>						RE (-)		Mandatory	
	25 A/F	Eff: 06-Aug-1974 Superseded (ISSUING AUTHORITY: FAA)					Mos	22-Jun-2022			
							Hrs	8			
							Ldg	6			
<b>74-08-09 R2 Paragraph (g)</b>		<b>Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - (1) Install a placard on each side of each lavatory door over the door knob, or on each side of each lavatory door, or adjacent to each side of each lavatory door. (2) Install a placard on or near each lavatory paper or linen waste disposal receptacle door, containing the legible words or symbology indicating "No Cigarette Disposal."</b>						RE (-)		Mandatory	
	25 A/F	Eff: 06-Aug-1974 Superseded (ISSUING AUTHORITY: FAA)					Mos	22-Jun-2022			
							Hrs	8			
							Ldg	6			
<b>74-08-09 R2 Paragraph (h)</b>		<b>Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - establish a procedure that requires that, no later than a time immediately after the "No Smoking" sign is extinguished following takeoff, an announcement be made by a crewmember to inform all aircraft occupants that smoking is prohibited in the aircraft lavatories; except that, if the aircraft is not equipped with a "No Smoking" sign, the required procedure must provide that the announcement be made prior to each takeoff.</b>						RE (-)		Mandatory	
	25 A/F	Eff: 06-Aug-1974 Superseded (ISSUING AUTHORITY: FAA)					Mos	22-Jun-2022			
							Hrs	8			
							Ldg	6			
<b>74-08-09 R2 Paragraph (i)</b>		<b>Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Install a self-contained, removable ashtray on or near the entry side of each lavatory door. One ashtray may serve more than one lavatory door if the ashtray can be seen readily from the cabin side of each lavatory door served.</b>						RE (-)		Mandatory	
	25 A/F	Eff: 06-Aug-1974 Superseded (ISSUING AUTHORITY: FAA)					Mos	22-Jun-2022			
							Hrs	8			
							Ldg	6			
<b>74-08-09 R2 Paragraph (j)</b>		<b>Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - An airplane with multiple lavatory doors may be operated with up to 50 percent of the lavatory door ashtrays missing or inoperative, provided 50 percent of the missing or inoperative ashtrays are replaced within 3 days and all remaining missing or inoperative ashtrays are replaced within 10 days. An airplane with only 1 lavatory door may be operated for a period of 10 days with the lavatory door ashtray missing or inoperative</b>						RE (-)		Mandatory	
	25 A/F	Eff: 06-Aug-1974 Superseded (ISSUING AUTHORITY: FAA)					Mos	22-Jun-2022			
							Hrs	8			
							Ldg	6			

























Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>74-08-09 R2 Paragraph (k)</b>		<b>Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Inspect all lavatory paper and linen waste receptacle enclosure access doors and disposal doors for proper operation, fit, sealing, and latching for the containment of possible trash fires.</b>						RE (-)		Mandatory	
	25 A/F					Mos	22-Jun-2022				
	Eff: 06-Aug-1974 Superseded					Hrs	8				
	(ISSUING AUTHORITY: FAA)					Ldg	6				
<b>74-08-09 R3</b>		<b>Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles</b>						RE (-)		Mandatory	
	25 A/F					Mos	18-Apr-2024				
	Eff: 28-Mar-2012 Complied	AD Not Adopted by EASA				Hrs	979:20				
	With					Ldg	667				
<b>74-08-09 R3 Paragraph (g)</b>		<b>Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - (1) Install a placard on each side of each lavatory door over the door knob, or on each side of each lavatory door, or adjacent to each side of each lavatory door. (2) Install a placard on or near each lavatory paper or linen waste disposal receptacle door, containing the legible words or symbology indicating "No Cigarette Disposal."</b>						RE (-)		Mandatory	
	25 A/F					Mos	18-Apr-2024				
	Eff: 06-Aug-1974 Complied	AD Not Adopted by EASA				Hrs	979:20				
	With					Ldg	667				
<b>74-08-09 R3 Paragraph (h)</b>		<b>Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - establish a procedure that requires that, no later than a time immediately after the "No Smoking" sign is extinguished following takeoff, an announcement be made by a crewmember to inform all aircraft occupants that smoking is prohibited in the aircraft lavatories; except that, if the aircraft is not equipped with a "No Smoking" sign, the required procedure must provide that the announcement be made prior to each takeoff.</b>						RE (-)		Mandatory	
	25 A/F					Mos	18-Apr-2024				
	Eff: 06-Aug-1974 Complied	AD Not Adopted by EASA				Hrs	979:20				
	With					Ldg	667				
<b>74-08-09 R3 Paragraph (i)</b>		<b>Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Install a self-contained, removable ashtray on or near the entry side of each lavatory door. One ashtray may serve more than one lavatory door if the ashtray can be seen readily from the cabin side of each lavatory door served.</b>						RE (-)		Mandatory	
	25 A/F					Mos	18-Apr-2024				
	Eff: 06-Aug-1974 Complied	AD Not Adopted by EASA				Hrs	979:20				
	With					Ldg	667				
<b>74-08-09 R3 Paragraph (j)</b>		<b>Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - An airplane with multiple lavatory doors may be operated with up to 50 percent of the lavatory door ashtrays missing or inoperative, provided 50 percent of the missing or inoperative ashtrays are replaced within 3 days and all remaining missing or inoperative ashtrays are replaced within 10 days. An airplane with only 1 lavatory door may be operated for a period of 10 days with the lavatory door ashtray missing or inoperative</b>						RE (-)		Mandatory	
	25 A/F					Mos	18-Apr-2024				
	Eff: 28-Mar-2012 Complied	AD Not Adopted by EASA				Hrs	979:20				
	With					Ldg	667				
		(ISSUING AUTHORITY: FAA)									
		Note: Note 1 to paragraph (j) of this AD; This AD permits a lavatory door ashtray to be missing, although the FAA-approved Master Minimum Equipment List (M MEL) may not allow such provision. In any case, the provisions of this AD prevail.									
<b>74-08-09 R3 Paragraph (k)</b>		<b>Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Inspect all lavatory paper and linen waste receptacle enclosure access doors and disposal doors for proper operation, fit, sealing, and latching for the containment of possible trash fires.</b>						RE		Mandatory	≈24-Aug-2025
	25 A/F					Mos	18-Apr-2024				
	Eff: 06-Aug-1974 Complied	AD Not Adopted by EASA				Hrs	979:20	1,000		1979:20	619:24 Hrs
	With					Ldg	667				
		(ISSUING AUTHORITY: FAA)									
<b>CF-48-05</b>		<b>Emergency Flare Installations (Previously issued as T/11/48)</b>						RE (-)		Mandatory	
	25 A/F					Mos	22-Jun-2022				
	Not Applicable	by installed equipment				Hrs	8				
	(ISSUING AUTHORITY: TC)					Ldg	6				












Task No	Description										Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	DUE	Remaining
<b>CF-59-01</b>		<b>Floor-Mounted Hand-Pump Type Fire Extinguishers</b>							RE (-)		Mandatory	
	25 A/F						Mos	22-Jun-2022				
	Eff: 31-Mar-1959 Not Applicable	by installed equipment					Hrs	8				
	(ISSUING AUTHORITY: TC)						Ldg	6				
<b>CF-83-31R2</b>		<b>Lavatory Flush Pump Motors</b>							RE (-)		Mandatory	
	25 A/F						Mos	22-Jun-2022				
	Eff: 07-Apr-1986 Not Applicable	by installed equipment					Hrs	8				
	(ISSUING AUTHORITY: TC)						Ldg	6				
<b>CIL-25-02</b>		<b>Equipment/Furnishings - Medaire Aircraft First Aid Kits with Medication Subject to Recall Notice</b>							RE (-)	Informational, Service Bulletin		
	25 A/F						Mos					
	Eff: 05-Nov-2019						Hrs					
							Ldg					
<b>CIL-25-03</b>		<b>Equipment/Furnishings - Seat Pan Tilt Blocking Tab Installation</b>							RE (-)	Informational, Service Letter		
	25 A/F						Mos					
	Eff: 12-Aug-2020						Hrs					
	(AVG MAN HRS: 0.25)						Ldg					
<b>CIL-25-03 R1</b>		<b>Equipment/Furnishings - Seat Pan Tilt Blocking Tab Installation</b>							RE (-)	Informational, Service Letter		
	25 A/F						Mos					
	Eff: 08-Oct-2020						Hrs					
	(AVG MAN HRS: 0.25)						Ldg					
<b>SB560XL-25-19</b>		<b>Equipment/Furnishings - Replacement of the 4569508-1 Water Barrier Assembly</b>							T (A/R)		Recommended	
	25 A/F						Mos	24-Jul-2024			[31-Jul-2026]	1.8 Years
	Eff: 15-Jul-2024 On Hold						Hrs					
	(AVG MAN HRS: 0.5)						Ldg					
<b>SL560XL-25-13</b>		<b>Transmittal of Rockwell Collins Aishow 4000 Service Bulletin 30, Correction of Hard Drive Mounting Screws - Mod U</b>							RE (-)		Recommended	
	25 A/F						Mos	22-Jun-2022				
	Eff: 22-Mar-2010 Not Applicable	effective before manufacture					Hrs	8				
							Ldg	6				
<b>SL560XL-25-15</b>		<b>Transmittal of Aircraft Belts Inc. SB-BUC062-A001 Inspection of Buckles for Proper Operation</b>							RE (-)		Optional	
	25 A/F						Mos					
							Hrs					
							Ldg					
<b>SL560XL-25-15 Rev 01</b>		<b>Transmittal of Aircraft Belts Inc. SB-BUC062-A001 Inspection of Buckles for Proper Operation</b>							RE (-)		Mandatory	
	25 A/F						Mos	22-Jun-2022				
	Eff: 16-Aug-2010 Not Applicable	by aircraft S/N					Hrs	8				
							Ldg	6				
<b>SL560XL-25-16</b>		<b>Transmittal of IPECO Service Bulletins 428-25-01, and 429-25-01, Addition of Cable Clip</b>							RE (-)		Recommended	
	25 A/F						Mos	22-Jun-2022				
	Eff: 13-Dec-2010 Not Applicable	effective before manufacture					Hrs	8				
							Ldg	6				
<b>SL560XL-25-17</b>		<b>Transmittal of Goodrich Service Bulletin 1423-25-003 Revision C Lumbar Assembly Cable Wear</b>							RE (-)		Recommended	
	25 A/F						Mos	22-Jun-2022				
	Eff: 03-Aug-2012 Not Applicable	by S/N					Hrs	8				
							Ldg	6				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>SL560XL-25-18</b>		<b>Equipment/Furnishings - Replacement of the Cabinet Spring Assembly Pins</b>						RE (-)		Recommended	
	25 A/F					Mos	22-Jun-2022				
	Eff: 18-Jul-2019 Not Applicable	effective before manufacture				Hrs	8				
	(AVG MAN HRS: 3)					Ldg	6				
<b>SL560XL-25-19</b>		<b>Equipment/Furnishings - Inspection of the Millennium Crew Seat Assemblies for Incorrectly Installed Seat Pan Tilt Mechanism Snap Rings (Millennium Service Bulletin SB2050-25-20-02)</b>						RE (-)		Recommended, Service Letter	
	25 A/F					Mos	22-Jun-2022				
	Eff: 11-Sep-2019 Not Applicable	by aircraft S/N				Hrs	8				
	(AVG MAN HRS: 1.8)					Ldg	6				
<b>SL560XL-25-19 R1</b>		<b>Equipment/Furnishings - Replacement of the Seat Pan Tilt Snap Rings (Millennium Service Bulletin SB2050-25-20-02B)</b>						RE (-)		Recommended, Service Letter	
	25 A/F					Mos	22-Jun-2022				
	Eff: 21-Nov-2019 Not Applicable	by aircraft S/N				Hrs	8				
	(AVG MAN HRS: 1.5)					Ldg	6				
<b>SL560XL-25-21</b>		<b>Equipment/Furnishings - Transmittal of Millennium Service Bulletin SB2050-25-20-09 Model 2050 Seating System Cross Tube Cover Installation</b>						RE (-)		Optional	
	25 A/F					Mos					
	Eff: 19-Dec-2022					Hrs					
	(AVG MAN HRS: 0.25)					Ldg					
<b>SL560XL-25-22</b>		<b>Equipment/Furnishings - Inspection of the SWI610-31 Entry Door Switch Indicator Light Emitting Diode (Led) Lights for Proper Indication</b>						RE (-)		Recommended	
	25 A/F					Mos	27-Oct-2023				
	Eff: 09-Jan-2023 Complied With					Hrs	763:53				
	(AVG MAN HRS: 3)					Ldg	505				
<b>SL560XL-25-23</b>		<b>Equipment/Furnishings - Passenger Seat Swivel Plate Swing Arm Assembly Fastener Inspection for Proper Adhesive Application</b>						RE (-)		Recommended	
	25 A/F					Mos	13-Sep-2023				
	Eff: 05-Apr-2023 Not Applicable	as per A/C S/N				Hrs	699:29				
	(AVG MAN HRS: 8)					Ldg	460				
<b>▼ 26 - FIRE PROTECTION</b>											
<b>2006-04-10</b>		<b>This AD Requires Installing Identification Sleeves On The Wires For The Positive And Negative Studs Of The Engine And/ Or (APU) Fire Extinguishing Bottles, As Applicable, And Reconnecting The Wires To The Correct Terminal Studs. (Superseded by AD 2007-11-17)</b>						RE (-)		Mandatory	
	26 A/F					Mos	22-Jun-2022				
	Eff: 24-Mar-2006 Superseded					Hrs	8				
	(ISSUING AUTHORITY: FAA)					Ldg	6				
<b>2007-11-17</b>		<b>Wires for the positive and negative terminal studs of the engine and/or auxiliary power unit (APU) fire extinguishing bottles.</b>						RE (-)		Mandatory	
	26 A/F					Mos	22-Jun-2022				
	Eff: 06-Jul-2007 Complied With					Hrs	8				
	(AVG MAN HRS: 4) (ISSUING AUTHORITY: FAA)					Ldg	6				
<b>2021-0185R2</b>		<b>Fire Protection - Hand-operated Fire Extinguishers - Inspection/Replacement</b>						RE (-)		Mandatory (Appliance AD)	
	26 A/F					Mos	12-Sep-2022				
	Eff: 14-Sep-2022 Not Applicable	affected P/N not installed				Hrs	129				
	(ISSUING AUTHORITY: EASA)					Ldg	90				
<b>560XL-26-03</b>		<b>Engine Fire Bottle Arm Annunciation Modification</b>						RE (-)		Mandatory	
	26 A/F					Mos	22-Jun-2022				
	Eff: 28-May-2009 Not Applicable	by S/N				Hrs	8				
						Ldg	6				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>CIL-26-01</b>		<b>Fire Protection - Fire Extinguisher Bottle Cartridge Ground Stud Torquing</b>						RE (-)		Mandatory	
	26 A/F					Mos	22-Jun-2022				
	Eff: 10-May-2016 Not Applicable	by aircraft S/N				Hrs	8				
	(AVG MAN HRS: 0.5)					Ldg	6				
<b>CIL-26-01 R1</b>		<b>Fire Protection - Fire Extinguisher Bottle Cartridge Ground Stud Torquing</b>						RE (-)		Mandatory	
	26 A/F					Mos	22-Jun-2022				
	Eff: 10-May-2016 Not Applicable	by aircraft S/N				Hrs	8				
	(AVG MAN HRS: 0.5)					Ldg	6				
<b>SB560XL-26-04</b>		<b>Fire Protection - Replacement of the Halon Type 1211 Portable Fire Extinguishers</b>						T (A/R)		Optional	
	26 A/F					Mos					
	Eff: 26-May-2022					Hrs					
						Ldg					
<b>SL560XL-26-02</b>		<b>Fire Protection - Fire Bottle Wire Verification and Test</b>						RE (-)		Mandatory	
	26 A/F					Mos	22-Jun-2022				
	Eff: 08-Jul-2021 Not Applicable	effective before manufacture				Hrs	8				
	(AVG MAN HRS: 3)					Ldg	6				
<b>SL560XL-26-02 R1</b>		<b>Fire Protection - Fire Bottle Wire Verification and Test</b>						RE (-)		Mandatory	
	26 A/F					Mos	19-Aug-2024				
	Eff: 31-Jul-2024 Not Applicable	N/A due to different aircraft SN				Hrs					
	(AVG MAN HRS: 3)					Ldg					
<b>▼ 27 - FLIGHT CONTROLS</b>											
<b>2000-15-51</b>		<b>Aileron Cable Fairlead Tube and Aileron Cable Sector</b>						RE (-)		Mandatory	
	27 A/F					Mos	22-Jun-2022				
	Eff: 14-Aug-2000 Complied With					Hrs	8				
	(ISSUING AUTHORITY: FAA)					Ldg	6				
<b>2000-15-51 Paragraph (a)</b>		<b>Aileron Cable Fairlead Tube - Pre-modification Inspection</b>						RE (-)		Mandatory	
	27 A/F					Mos	22-Jun-2022				
	Eff: 14-Aug-2000 Complied With					Hrs	8				
	(ISSUING AUTHORITY: FAA)					Ldg	6				
<b>2000-15-51 Paragraph (b)</b>		<b>Aileron Cable Fairlead Tube - Modification</b>						RE (-)		Mandatory	
	27 A/F					Mos	22-Jun-2022				
	Eff: 14-Aug-2000 Complied With					Hrs	8				
	(ISSUING AUTHORITY: FAA)					Ldg	6				
<b>2000-15-51 Paragraph (c)</b>		<b>Aileron Cable Fairlead Tube - Post-modification Inspection</b>						RE (-)		Mandatory	
	27 A/F					Mos	22-Jun-2022				
	Eff: 14-Aug-2000 Complied With	N/A as per documents from delivery of new A/C				Hrs	8				
	(ISSUING AUTHORITY: FAA)					Ldg	6				
<b>560XL-27-32</b>		<b>Rudder Pedal Position Modification</b>						RE (-)		Optional	
	27 A/F					Mos					
						Hrs					
						Ldg					
<b>560XL-27-32 Rev 01</b>		<b>Rudder Pedal Position Modification</b>						RE (-)		Optional	
	27 A/F					Mos					
						Hrs					
						Ldg					













Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>560XL-27-32 Rev 02</b>	<b>Rudder Pedal Position Modification</b>								RE (-)	Recommended
 27 A/F						Mos	22-Jun-2022			
Eff: 10-May-2011 Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			
<b>560XL-27-35</b>	<b>Flight Controls - Stainless Steel Hydraulic Tube Replacement</b>								RE (-)	Optional
 27 A/F						Mos				
						Hrs				
						Ldg				
<b>560XL-27-35 Rev 01</b>	<b>Flight Controls - Stainless Steel Hydraulic Tube Replacement</b>								RE (-)	Optional
 27 A/F						Mos				
Eff: 11-Nov-2014						Hrs				
						Ldg				
<b>SL560XL-27-05</b>	<b>Cable Fairlead Replacement</b>								RE (-)	Recommended
 27 A/F						Mos	22-Jun-2022			
Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			
<b>SL560XL-27-05 Rev 01</b>	<b>Cable Fairlead Replacement</b>								RE (-)	Recommended
 27 A/F						Mos	22-Jun-2022			
Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			
<b>SL560XL-27-05 Rev 02</b>	<b>Cable Fairlead Replacement</b>								RE (-)	Mandatory
 27 A/F						Mos	22-Jun-2022			
Eff: 05-Feb-2014 Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			
<b>SL560XL-27-14</b>	<b>Horizontal and Vertical Stabilizer Erosion Boot Installation</b>								T (A/R)	Optional
 27 A/F						Mos				
Eff: 30-Mar-2006						Hrs				
						Ldg				
<b>SL560XL-27-18</b>	<b>Elevator Trim Cable Replacement Intervals</b>								T (A/R)	Informational
 27 A/F						Mos				
Eff: 21-Feb-2012						Hrs				
						Ldg				
<b>SL560XL-27-20</b>	<b>Rudder Torque Tube/Sector Assembly Gap Inspection</b>								RE (-)	Recommended
 27 A/F						Mos	22-Jun-2022			
Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			
<b>SL560XL-27-20 Rev 01</b>	<b>Rudder Torque Tube/Sector Assembly Gap Inspection</b>								RE (-)	Recommended
 27 A/F						Mos	22-Jun-2022			
Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			
<b>SL560XL-27-20 Rev 02</b>	<b>Rudder Torque Tube/Sector Assembly Gap Inspection</b>								RE (-)	Mandatory
 27 A/F						Mos	22-Jun-2022			
Eff: 18-Jan-2014 Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			
<b>SL560XL-27-21</b>	<b>Rudder Torque Tube/Sector Assembly Inspection</b>								RE (-)	Mandatory
 27 A/F						Mos	22-Jun-2022			
Eff: 18-Jan-2014 Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			












Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>SL560XL-27-33</b>		<b>Flight Controls - Elevator Cable Inspection at the Aft Cantd Bulkhead</b>						RE (-)		Mandatory	
	27 A/F	Eff: 05-Nov-2014 Not Applicable by aircraft S/N					Mos	22-Jun-2022			
							Hrs	8			
							Ldg	6			
<b>SL560XL-27-34</b>		<b>Flight Controls - Right Outboard Aileron Wing Up Cable Assembly Inspection</b>						RE (-)		Recommended	
	27 A/F	Not Applicable by aircraft S/N					Mos	22-Jun-2022			
							Hrs	8			
							Ldg	6			
<b>SL560XL-27-34 Rev 01</b>		<b>Flight Controls - Right Outboard Aileron Wing Up Cable Assembly Inspection</b>						RE (-)		Mandatory	
	27 A/F	Eff: 22-Jan-2015 Not Applicable by aircraft S/N					Mos	22-Jun-2022			
							Hrs	8			
							Ldg	6			
<b>SL560XL-27-34 Rev 02</b>		<b>Flight Controls - Right Outboard Aileron Wing Up Cable Assembly Inspection</b>						RE (-)		Mandatory	
	27 A/F	Eff: 12-Jun-2019 Not Applicable (AVG MAN HRS: 3.2) by aircraft S/N					Mos	22-Jun-2022			
							Hrs	8			
							Ldg	6			
<b>SL560XL-27-35</b>		<b>Flight Controls - AFT Aileron Sector Assembly Inspection</b>						RE (-)		Mandatory	
	27 A/F	Eff: 16-Nov-2015 Not Applicable (AVG MAN HRS: 1) by aircraft S/N					Mos	22-Jun-2022			
							Hrs	8			
							Ldg	6			
<b>SL560XL-27-36</b>		<b>Flight Controls - Horizontal Stabilizer Actuator Bolt Inspection</b>						RE (-)		Mandatory	
	27 A/F	Eff: 26-Aug-2015 Not Applicable by aircraft S/N					Mos	22-Jun-2022			
							Hrs	8			
							Ldg	6			
<b>SL560XL-27-37</b>		<b>Flight Controls - Rudder Position Sensor Wire Routing Improvement</b>						RE (-)		Mandatory	
	27 A/F	Eff: 13-Jan-2016 Not Applicable (AVG MAN HRS: 1.5) by aircraft S/N					Mos	22-Jun-2022			
							Hrs	8			
							Ldg	6			
<b>SL560XL-27-37 Rev 01</b>		<b>Flight Controls - Rudder Position Sensor Wire Routing Improvement</b>						RE (-)		Mandatory	
	27 A/F	Eff: 25-Mar-2016 Not Applicable (AVG MAN HRS: 1.5) by aircraft S/N					Mos	22-Jun-2022			
							Hrs	8			
							Ldg	6			
<b>SL560XL-27-37 Rev 02</b>		<b>Flight Controls - Rudder Position Sensor Wire Routing Improvement</b>						RE (-)		Mandatory	
	27 A/F	Eff: 21-Jul-2016 Not Applicable (AVG MAN HRS: 1.5) by aircraft S/N					Mos	22-Jun-2022			
							Hrs	8			
							Ldg	6			
<b>SL560XL-27-38</b>		<b>Flight Controls - Inspection of the Horizontal Stabilizer Upper Scissor Link Fitting</b>						RE (-)		Recommended	
	27 A/F	Eff: 05-Oct-2022 Not Applicable as per A/C S/N					Mos	13-Sep-2023			
							Hrs	699:29			
							Ldg	460			
<b>SL560XL-27-39</b>		<b>Flight Controls - Control Lock Cable Assembly Swivel Seal Inspection</b>						T (A/R)		Recommended	
	27 A/F	Eff: 03-Sep-2024 (AVG MAN HRS: 7.5) KGR-WP-010 START 11-NOV-2024					Mos			[12-Nov-2024]	28 Days
							Hrs				
							Ldg				













Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
▼ 28 - FUEL										
<b>CIL-28-01</b>	<b>Fuel - Microbiological Contamination in Aircraft Fuel Tanks and Fuel Systems</b>						T (A/R)		Informational	
 28 A/F Eff: 24-Feb-2023					Mos					
					Hrs					
					Ldg					
<b>SIL-GEN-108</b>	<b>Jet Fuel Containing Fatty Acid Methyl Esters (FAME)</b>						RE (-)		Service Information Letter	
 28 ENG1					Mos					
					Hrs					
					Enc					
<b>SIL-GEN-108</b>	<b>Jet Fuel Containing Fatty Acid Methyl Esters (FAME)</b>						RE (-)		Service Information Letter	
 28 ENG2					Mos					
					Hrs					
					Enc					
<b>SIL-GEN-108 Rev 1</b>	<b>Jet Fuel Containing Fatty Acid Methyl Esters (FAME)</b>						RE (-)		Service Information Letter	
 28 ENG1					Mos					
					Hrs					
					Enc					
<b>SIL-GEN-108 Rev 1</b>	<b>Jet Fuel Containing Fatty Acid Methyl Esters (FAME)</b>						RE (-)		Service Information Letter	
 28 ENG2					Mos					
					Hrs					
					Enc					
<b>SIL-GEN-108 Rev 2</b>	<b>Jet Fuel Containing Fatty Acid Methyl Esters (FAME)</b>						T (A/R)		Service Information Letter	
 28 ENG1 Eff: 01-Nov-2017					Mos					
					Hrs					
					Enc					
<b>SIL-GEN-108 Rev 2</b>	<b>Jet Fuel Containing Fatty Acid Methyl Esters (FAME)</b>						T (A/R)		Service Information Letter	
 28 ENG2 Eff: 01-Nov-2017					Mos					
					Hrs					
					Enc					
<b>SL560XL-28-03</b>	<b>Motive Flow Shutoff Valve O-Ring Replacement</b>						RE (-)		Recommended	
 28 A/F Eff: 15-Nov-2010 Not Applicable	effective before manufacture				Mos	22-Jun-2022				
					Hrs	8				
					Ldg	6				
<b>SL560XL-28-06</b>	<b>Fuel - Fuel Hopper Panel Protection</b>						RE (-)		Service Letter	
 28 A/F Eff: 26-Feb-2018 (AVG MAN HRS: 6)					Mos					
					Hrs					
					Ldg					
<b>SL560XL-28-07</b>	<b>Fuel - 6621102-1 Left Web Corrosion Protection</b>						RE (-)		Recommended	
 28 A/F Eff: 16-May-2022 Not Applicable (AVG MAN HRS: 8)	effective before manufacture				Mos	22-Jun-2022				
					Hrs	8				
					Ldg	6				
▼ 29 - HYDRAULIC POWER										
<b>SL560XL-29-04</b>	<b>Hydraulic Power - Hydraulic Manifold Control Valve Wire Bundle Inspection</b>						RE (-)		Recommended	
 29 A/F Eff: 15-Jan-2015 Not Applicable	effective before manufacture				Mos	22-Jun-2022				
					Hrs	8				
					Ldg	6				



Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>SL560XL-29-04 Rev 1</b>		<b>Hydraulic Power - Hydraulic Manifold Control Valve Wire Bundle Inspection</b>						RE (-)		Recommended	
	29 A/F					Mos	22-Jun-2022				
	Eff: 12-Jun-2019 Not Applicable	effective before manufacture				Hrs	8				
	(AVG MAN HRS: 1.5)					Ldg	6				
<b>SL560XL-29-05</b>		<b>Engine Driven Pump Hydraulic Verification</b>						RE (-)		Recommended, Service Letter	
	29 A/F					Mos	22-Jun-2022				
	Eff: 14-Jun-2017 Not Applicable	effective before manufacture				Hrs	8				
						Ldg	6				
<b>▼ 30 - ICE AND RAIN PROTECTION</b>											
<b>2012-06-01</b>		<b>To Prevent Ice Accumulation on the Cables and Pulleys of the Stinger</b>						RE (-)		Mandatory	
	30 A/F					Mos	22-Jun-2022				
	Eff: 25-Apr-2012 Not Applicable	Due to aircraft is not in the suspect serial range				Hrs	8				
	(ISSUING AUTHORITY: FAA)					Ldg	6				
<b>560XL-30-06</b>		<b>Horizontal Stabilizer Deice System Pressure Switch Installation Improvement</b>						RE (-)		Discretionary	
	30 A/F					Mos					
	Eff: 15-Sep-2008					Hrs					
						Ldg					
<b>98-04-38</b>		<b>AFM - Limitations Section - Icing</b>						RE (-)		Mandatory	
	30 A/F					Mos	22-Jun-2022				
	Eff: 25-Mar-1998 Not Applicable	due to S/N				Hrs	8				
	(ISSUING AUTHORITY: FAA)					Ldg	6				
<b>CIL-30-01</b>		<b>Ice and Rain Protection - Approved Deicing Program Updates</b>						RE (-)		Informational	
	30 A/F					Mos					
						Hrs					
						Ldg					
<b>CIL-30-01 R1</b>		<b>Ice and Rain Protection - Approved Deicing Program Updates</b>						T (A/R)		Informational	
	30 A/F					Mos					
	Eff: 13-Sep-2013					Hrs					
						Ldg					
<b>SL560XL-30-01</b>		<b>Approved Deicing Program Updates</b>						RE (-)		Optional	
	30 A/F					Mos					
						Hrs					
						Ldg					
<b>SL560XL-30-01 Rev 01</b>		<b>Approved Deicing Program Updates</b>						RE (-)		Optional	
	30 A/F					Mos					
						Hrs					
						Ldg					
<b>SL560XL-30-01 Rev 02</b>		<b>Approved Deicing Program Updates</b>						RE (-)		Optional	
	30 A/F					Mos					
						Hrs					
						Ldg					
<b>SL560XL-30-01 Rev 03</b>		<b>Approved Deicing Program Updates</b>						RE (-)		Optional	
	30 A/F					Mos					
						Hrs					
						Ldg					














Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SL560XL-30-01 Rev 04	 30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
						Mos					
						Hrs					
SL560XL-30-01 Rev 05	 30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
						Mos					
						Hrs					
SL560XL-30-01 Rev 06	 30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
						Mos					
						Hrs					
SL560XL-30-01 Rev 07	 30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
						Mos					
						Hrs					
SL560XL-30-01 Rev 08	 30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
						Mos					
						Hrs					
SL560XL-30-01 Rev 09	 30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
						Mos					
						Hrs					
SL560XL-30-01 Rev 10	 30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
						Mos					
						Hrs					
SL560XL-30-01 Rev 11	 30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
						Mos					
						Hrs					
SL560XL-30-01 Rev 12	 30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
						Mos					
						Hrs					
SL560XL-30-01 Rev 13	 30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
						Mos					
						Hrs					
SL560XL-30-01 Rev 14	 30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
						Mos					
						Hrs					
SL560XL-30-01 Rev 15	 30 A/F Eff: 08-Oct-2012	Approved Deicing Program Updates						T (A/R)		Informational	
						Mos					
						Hrs					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
▼ 31 - INDICATING / RECORDING SYSTEM										
<b>560XL-31-05</b>	<b>Data Concentrator Unit Software Upgrade</b>						RE (-)		Mandatory	
 31 A/F						Mos	22-Jun-2022			
Eff: 03-Jun-2009 Not Applicable	by S/N					Hrs	8			
						Ldg	6			
<b>CIL-31-01</b>	<b>Indicating/Recording Systems - CVR, FDR, and CVDR 90-Day Battery Underwater Locator Beacon (ULB) Installation</b>						T (A/R)		Informational, Service Letter	
 31 A/F						Mos				
Eff: 02-Feb-2018						Hrs				
						Ldg				
Note: EFFECTIVITY: All Citation airplanes that are equipped with a Textron Aviation engineered CVR, FDR, or CVDR installation.										
<b>SB560XL-31-06</b>	<b>Indicating/Recording Systems - Option to Replace the Avionics Secondary Quick Access Recorder (QAR) with an L-3 Secondary Quick Access Recorder</b>						T (A/R)		Optional, Service Bulletin	
 31 A/F						Mos				
Eff: 28-Aug-2019						Hrs				
						Ldg				
<b>SL560XL-31-05</b>	<b>Transmittal of L-3 Communications Alert Bulletin No. Cessna SB 001</b>						RE (-)		Mandatory	
 31 A/F						Mos	22-Jun-2022			
Eff: 04-Aug-2011 Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			
<b>SL560XL-31-06</b>	<b>Inspection of the Position-Sensor Potentiometer for the Elevator Trim Tab</b>						RE (-)		Recommended	
 31 A/F						Mos	22-Jun-2022			
Eff: 22-Oct-2012 Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			
<b>SL560XL-31-07</b>	<b>Indicating/ Recording Systems - Rudder Surface Input Sensor Pushrod Lockwire Installation</b>						RE (-)		Recommended, Service Letter	
 31 A/F						Mos	22-Jun-2022			
Eff: 23-Jun-2017 Not Applicable	effective before manufacture					Hrs	8			
(AVG MAN HRS: 1.4)						Ldg	6			
<b>SL560XL-31-08</b>	<b>Indicating/Recording Systems - Collins Environmental Controller (IEC) and Power Supply (PWR) IAPS Modules Inspection/Replacement</b>						RE (-)		Recommended	
 31 A/F						Mos	13-Sep-2023			
Eff: 14-Jun-2023 Not Applicable	as per A/C S/N					Hrs	699:29			
(AVG MAN HRS: 4.5)						Ldg	460			
▼ 32 - LANDING GEAR										
<b>2012-09-01</b>	<b>To Prevent Brake Failure, Which Could Result in an Airplane Not Being Able to Stop on the Runway</b>						RE (-)		Mandatory	
 32 A/F						Mos	22-Jun-2022			
Eff: 07-Jun-2012 Not Applicable	Due to aircraft is not in suspect serial range					Hrs	8			
(ISSUING AUTHORITY: FAA)						Ldg	6			
<b>560XL-32-38</b>	<b>Landing Gear - Remove the Quick Disconnect from the Nose Landing Gear Torque Link</b>						RE (-)		Recommended	
 32 A/F						Mos	22-Jun-2022			
Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			
<b>560XL-32-38 Rev 01</b>	<b>Landing Gear - Remove the Quick Disconnect from the Nose Landing Gear Torque Link</b>						T (-)		Optional	
 32 A/F						Mos				
Eff: 07-Dec-2010						Hrs				
						Ldg				
<b>560XL-32-38 Rev 02</b>	<b>Landing Gear - Remove the Quick Disconnect from the Nose Landing Gear Torque Link</b>						T (A/R)		Optional	
 32 A/F						Mos				
Eff: 15-Feb-2019						Hrs				
						Ldg				













Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>560XL-32-41</b>	<b>Transmittal of Goodrich Service Bulletin 3-1571-32-7</b>								RE (-)	Recommended
 32 A/F					Mos	22-Jun-2022				
Not Applicable	effective before manufacture				Hrs	8				
					Ldg	6				
<b>560XL-32-41 Rev 01</b>	<b>Transmittal of Goodrich Service Bulletin 3-1571-32-7</b>								RE (-)	Mandatory
 32 A/F					Mos	22-Jun-2022				
Eff: 05-May-2011 Not Applicable	effective before manufacture				Hrs	8				
					Ldg	6				
Note: This service bulletin must be accomplished at the next tire change or one year from the date of receipt, whichever occurs first.										
<b>560XL-32-42</b>	<b>Landing Gear - Stainless Steel Hydraulic Tube Replacement</b>								RE (-)	Recommended
 32 A/F					Mos	22-Jun-2022				
Not Applicable	effective before manufacture				Hrs	8				
					Ldg	6				
<b>560XL-32-42 Rev 01</b>	<b>Landing Gear - Stainless Steel Hydraulic Tube Replacement</b>								RE (-)	Recommended
 32 A/F					Mos	22-Jun-2022				
Not Applicable	effective before manufacture				Hrs	8				
					Ldg	6				
<b>560XL-32-42 Rev 02</b>	<b>Landing Gear - Stainless Steel Hydraulic Tube Replacement</b>								RE (-)	Optional
 32 A/F					Mos					
Eff: 11-Nov-2014					Hrs					
					Ldg					
<b>CIL-32-01</b>	<b>Improved Nose Wheel Grease Seal</b>								RE (-)	Informational
 32 A/F					Mos					
Eff: 07-Feb-2013					Hrs					
					Ldg					
Note: With 3-1418OPT2 (9914069-2), 3-1418OPT3 (9914069-3), or 3-1418OPT4 (9914069-4) Nose Wheels installed.										
<b>CIL-32-04</b>	<b>Landing Gear - Wireless Tire Pressure Monitoring System Installation</b>							T (A/R)		Informational
 32 A/F					Mos					
Eff: 25-Sep-2014					Hrs					
					Ldg					
<b>CIL-32-06</b>	<b>Landing Gear - Wireless Tire Pressure Sensor Fill Valve Torque Verification</b>							T (A/R)		Informational
 32 A/F					Mos					
Eff: 09-Mar-2020					Hrs					
					Ldg					
<b>G-004-09-83</b>	<b>SUPERSEDED BY CAA UK AD 017-11-83</b>								RE (-)	Mandatory
 32 A/F					Mos	22-Jun-2022				
Eff: 12-Dec-1983 Superseded					Hrs	8				
(ISSUING AUTHORITY: EASA)					Ldg	6				
<b>G-005-09-83</b>	<b>SUPERSEDED BY CAA UK AD 016-11-83</b>								RE (-)	Mandatory
 32 A/F					Mos	22-Jun-2022				
Eff: 12-Dec-1983 Superseded					Hrs	8				
(ISSUING AUTHORITY: EASA)					Ldg	6				
<b>G-013-08-90</b>	<b>SUPERSEDED BY CAA UK AD 009-02-93</b>								RE (-)	Mandatory
 32 A/F					Mos	22-Jun-2022				
Eff: 20-Jan-1993 Superseded					Hrs	8				
(ISSUING AUTHORITY: EASA)					Ldg	6				
<b>SB560XL-32-44</b>	<b>Landing Gear - Nose Landing Gear Bearing Grease Fitting Installation</b>								T (-)	Optional
 32 A/F					Mos					
Eff: 07-Jun-2017					Hrs					
					Ldg					

Task No	Description									Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
<b>SB560XL-32-44 R1</b>  32 A/F Eff: 13-Nov-2018	Landing Gear - Nose Landing Gear Bearing Grease Fitting Installation						T (-)		Optional		
					Mos						
					Hrs						
<b>SB560XL-32-44 R2</b>  32 A/F Eff: 25-Nov-2019	Landing Gear - Nose Landing Gear Bearing Grease Fitting Installation						RE (-)		Optional, Service Bulletin		
					Mos						
					Hrs						
<b>SB560XL-32-47</b>  32 A/F Eff: 11-Sep-2023	Landing Gear - Main Landing Gear Brake Hydraulic Line Fitting Replacement						T (A/R)		Optional		
					Mos						
					Hrs						
<b>SL560XL-32-06</b>  32 A/F Eff: 08-Aug-2000	Landing Gear - Power Brake System Operation						T (A/R)		Informational		
					Mos						
					Hrs						
<b>SL560XL-32-08</b>  32 A/F Eff: 30-Oct-2000	Landing Gear - Transmittal Of BFGoodrich Service Letter SL1866 Landing Gear Main And Nose Wheels Approved Cleaners For Aluminum Wheel Assembly						T (A/R)		Informational		
					Mos						
					Hrs						
<b>SL560XL-32-09</b>  32 A/F Eff: 08-May-2001	Landing Gear - Transmittal Of BFGoodrich Service Letter SL1878, Effect Of Disinfectant On Wheel And Brake Assemblies						T (A/R)		Informational		
					Mos						
					Hrs						
<b>SL560XL-32-22</b>  32 A/F Eff: 10-Aug-2009	Landing Gear Component Placard Installation						RE (-)		Optional		
					Mos						
					Hrs						
<b>SL560XL-32-22 Rev 1</b>  32 A/F Eff: 03-May-2019	Landing Gear Component Placard Installation						RE (-)		Optional		
					Mos						
					Hrs						
<b>SL560XL-32-24</b>  32 A/F	Revision 1 Cancels Transmittal of Curtiss Wright SB 049801-32-01, Landing Gear Control - Alternate LED Lighting Bulb						RE (-)		Optional		
					Mos						
					Hrs						
<b>SL560XL-32-24 Rev 01</b>  32 A/F Eff: 01-May-2012	Revision 1 Cancels Transmittal of Curtiss Wright SB 049801-32-01, Landing Gear Control - Alternate LED Lighting Bulb						RE (-)		Informational		
					Mos						
					Hrs						
<b>SL560XL-32-25</b>  32 A/F Eff: 29-Jun-2010	Main Wheel Assembly, P/N 3-1571 Series - Model 560XL/XLS Series Aircraft - Improved Inspection Procedure						T (A/R)		Informational		
					Mos						
					Hrs						
<b>SL560XL-32-27</b>  32 A/F	Landing Gear - Hydraulic Loading Valve Wire Bundle Inspection						RE (-)		Optional		
					Mos						
					Hrs						












Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>SL560XL-32-27 Rev 01</b>		<b>Landing Gear - Hydraulic Loading Valve Wire Bundle Inspection</b>						RE (-)		Mandatory	
	32 A/F					Mos	22-Jun-2022				
	Eff: 15-Jan-2015 Not Applicable	by aircraft S/N				Hrs	8				
						Ldg	6				
<b>SL560XL-32-27 Rev 02</b>		<b>Landing Gear - Hydraulic Loading Valve Wire Bundle Inspection</b>						RE (-)		Mandatory	
	32 A/F					Mos	22-Jun-2022				
	Eff: 12-Jun-2019 Not Applicable	by aircraft S/N				Hrs	8				
	(AVG MAN HRS: 1.5)					Ldg	6				
<b>SL560XL-32-29</b>		<b>Main Landing Gear Actuator Lock Tab Verification</b>						RE (-)		Recommended	
	32 A/F					Mos	22-Jun-2022				
	Eff: 22-Dec-2016 Not Applicable	effective before manufacture				Hrs	8				
	(AVG MAN HRS: 5)					Ldg	6				
<b>SL560XL-32-30</b>		<b>Landing Gear - Brake Hydraulic Reservoir Sight Glass Fastener Torque Inspection</b>						RE (-)		Recommended	
	32 A/F					Mos	13-Sep-2023				
	Eff: 11-Sep-2023 Not Applicable	as per A/C S/N				Hrs	699:29				
	(AVG MAN HRS: 0.5)					Ldg	460				
<b>SL560XL-32-32</b>		<b>Landing Gear - Main Landing Gear Components Repair</b>						T (A/R)		Informational	
	32 A/F					Mos					
	Eff: 20-May-2024					Hrs					
						Ldg					
<b>▼ 33 - LIGHTS</b>											
<b>2001-14-09</b>		<b>Wiring of the Landing Light Switch and the J-Box Fairing Light Relays</b>						RE (-)		Mandatory (Appliance AD)	
	33 A/F					Mos	22-Jun-2022				
	Eff: 26-Jul-2001 Complied With					Hrs	8				
	(ISSUING AUTHORITY: FAA)					Ldg	6				
<b>CF-58-03</b>		<b>Emergency Lighting for Aircraft Cabin Interiors</b>						RE (-)		Mandatory	
	33 A/F					Mos	22-Jun-2022				
	Eff: 30-Jun-1959 Complied With					Hrs	8				
	(ISSUING AUTHORITY: TC)					Ldg	6				
<b>SL560XL-33-01</b>		<b>Lights - DeVore Logo Light Installation</b>						T (A/R)		Informational	
	33 A/F					Mos					
	Eff: 15-Sep-1999					Hrs					
						Ldg					
<b>▼ 34 - NAVIGATION</b>											
<b>2001-23-17</b>		<b>Garmin GNS 430 units</b>						RE (-)		Mandatory (Appliance AD)	
	34 A/F					Mos	22-Jun-2022				
	Eff: 28-Dec-2001 Not Applicable	Due to suspect parts are not installed on this aircraft				Hrs	8				
	Brand A:9990-2001-23-17 (ISSUING AUTHORITY: FAA)					Ldg	6				
<b>2007-23-13</b>		<b>Inspect - Adjustment Of Stall Warning System (Superseded by AD2008-26-04)</b>						RE (-)		Mandatory	
	34 A/F					Mos	22-Jun-2022				
	Eff: 30-Nov-2007 Not Applicable	to the model				Hrs	8				
	(ISSUING AUTHORITY: FAA)					Ldg	6				
<b>2010-07-02</b>		<b>Integrated Navigation Units (INUs) - Honeywell Primus II RNZ-850( )/-851( ) (This AD supersedes AD 2006-22-05)</b>						RE (-)		Mandatory (Appliance AD)	
	34 A/F					Mos	22-Jun-2022				
	Eff: 03-May-2010 Not Applicable	Due to suspect parts are not installed on this aircraft				Hrs	8				
	(ISSUING AUTHORITY: FAA)					Ldg	6				












Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>2012-26-15 R1</b>	<b>Honeywell International Inc. - Air Data Pressure Transducers (This action rescinds AD 2012-26-15, Amendment 39-17310 (78 FR 1735, January 9, 2013).)</b>								RE (-)	Mandatory (Appliance AD)
34 A/F						Mos	22-Jun-2022			
Eff: 03-Dec-2014 Not Applicable	Due to suspect parts are not installed on this aircraft					Hrs	8			
(ISSUING AUTHORITY: FAA)						Ldg	6			
<b>2014-18-01</b>	<b>Rockwell Collins, Inc. - Navigation - inspect the airplane type code category strapping setting for a value of zero (0) or one (1) following Rockwell Collins, Inc. Service Information Letter 07-2, 523-0810069-101000, TDR-94() SIL 07-02.</b>								RE (-)	Mandatory (Appliance AD)
34 A/F						Mos	22-Jun-2022			
Eff: 14-Oct-2014 Not Applicable	Due to pages 6 & 7 section (C) (3) (V) and ECR 58032					Hrs	8			
Brand A:9990-2014-18-01 (AVG MAN HRS: 4) (APX COST: 85) (ISSUING AUTHORITY: FAA)						Ldg	6			
<b>2020-10-05</b>	<b>Flight Management Computing Hardware System - Rockwell Collins Pro Line 4 and Pro Line 21 Flight Management Systems</b>								RE (-)	Mandatory (Appliance AD)
34 A/F						Mos	22-Jun-2022			
Eff: 24-Jun-2020 Not Applicable	Due to suspect parts are not programed for this option					Hrs	8			
(ISSUING AUTHORITY: FAA)						Ldg	6			
<b>2021-23-12</b>	<b>Indicating/Recording System, Navigation - Radio Altimeter (Transport and Commuter Category Airplanes) (This AD is Superseded by FAA AD 2023-10-02)</b>								RE (-)	Mandatory (Appliance AD)
34 A/F						Mos	22-Jun-2022			
Eff: 03-Jan-2022 Complied With						Hrs	8			
(ISSUING AUTHORITY: FAA)						Ldg	6			
Note: COMPLIANCE: On or before January 4, 2022: Revise the Limitations Section of the existing AFM by incorporating the limitations specified in figure 1 to paragraph (g) of this AD. This may be done by inserting a copy of this AD into the existing AFM.										
<b>2023-10-02</b>	<b>Navigation - Radio Altimeters (This AD Replaces AD 2021-23-12)</b>								RE (-)	Mandatory (Appliance AD)
34 A/F						Mos	15-Jun-2023			
Eff: 26-May-2023 Complied With						Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				
Note: APPLICABILITY: This AD applies to all transport and commuter category airplanes equipped with a radio (also known as radar) altimeter. These radio altimeters are installed on various transport and commuter category airplanes including, but not limited to, the airplanes for which the design approval holder is identified in paragraphs (c)(1) through (18) of this AD. (1) The Boeing Company (2) Airbus SAS (3) Bombardier Inc.(4) Embraer S.A. (including type certificates previously held by Yaborã Indústria Aeronáutica S.A., which are now held by Embraer S.A.) (5) Gulfstream Aerospace Corporation (6) Gulfstream Aerospace LP (7) Textron Aviation Inc. (8) Pilatus Aircraft Limited (9) Fokker Services B.V. (10) Saab AB, Support and Services (11) DeHavilland Aircraft of Canada Limited (12) Airbus Canada Limited Partnership (13) ATR-GIE Avions de Transport Régional (14) MHI RJ Aviation ULC (15) BAE Systems (Operations) Limited (16) Lockheed Martin Corporation/Lockheed Martin Aeronautics Company (17) Viking Air Limited (18) Dassault Aviation										
<b>2023-10-02 Par. (h)</b>	<b>Navigation - Radio Altimeters - Airplane Flight Manual (AFM) Revision Until June 30, 2023</b>								RE (-)	Mandatory (Appliance AD)
34 A/F						Mos	15-Jun-2023			
Eff: 25-May-2023 Complied With	Complied as per AD 2021-23-12 par(g)					Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				
Note: COMPLIANCE: For non-radio altimeter tolerant airplanes, before further flight, revise the Limitations Section of the existing AFM to include the information specified in figure 3 to paragraph (h) of this AD. This may be done by inserting a copy of figure 3 to paragraph (h) of this AD into the existing AFM. If an operator has complied with paragraph (g) of AD 2021-23-12, that action satisfies the requirements of this paragraph.										
<b>2023-10-02 Par. (i)</b>	<b>Navigation - Radio Altimeters - AFM Revision After June 30, 2023</b>								RE (-)	Mandatory (Appliance AD)
34 A/F						Mos	26-Jun-2023			
Eff: 29-Jun-2023 Complied With	AFM updated					Hrs	518:21			
(ISSUING AUTHORITY: FAA)						Ldg	348			
Note: COMPLIANCE: On or before June 30, 2023, revise the Limitations Section of the existing AFM to include the information specified in figure 4 to paragraph (i) of this AD. This may be done by inserting a copy of figure 4 to paragraph (i) of this AD into the existing AFM. Incorporating the AFM revision required by this paragraph terminates the AFM revision required by paragraph (h) of this AD. (2) Before further flight after incorporating the limitations specified in figure 4 to paragraph (i) of this AD, remove the AFM revision required by paragraph (h) of this AD.										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>2023-10-02 Par. (j)</b>	<b>Navigation - Radio Altimeters - Terminating Action for AFM Limitations</b>						T (A/R)		Mandatory (Appliance AD)	
34 A/F						Mos				
Eff: 26-May-2023						Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				
Note: COMPLIANCE: Modifying the airplane from a non-radio altimeter tolerant airplane to a radio altimeter tolerant airplane terminates the limitations in paragraph (i) of this AD for that airplane. After modifying the airplane to a radio altimeter tolerant airplane, the limitations specified by paragraph (i) of this AD may be removed from the AFM.										
<b>2023-21-05</b>	<b>Navigation - Thales AVS France SAS Flight Management Computer Navigation Modules (FMC2 NAVM)</b>						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	13-Nov-2023			
Eff: 12-Dec-2023 Not Applicable	affected P/N is not installed					Hrs	783:10			
(ISSUING AUTHORITY: FAA)						Ldg	518			
<b>2023-21-05 Par. (g)(1)</b>	<b>Navigation - Thales AVS France SAS Flight Management Computer Navigation Modules (FMC2 NAVM) - Revise the Limitations Section of the Existing Airplane Flight Manual</b>						RE (-)		Mandatory (Appliance AD)	
34 A/F						Days	13-Nov-2023			
Eff: 12-Dec-2023 Not Applicable	affected P/N is not installed					Hrs	783:10			
(ISSUING AUTHORITY: FAA)						Ldg	518			
Note: APPLICABILITY: This AD applies to Thales AVS France SAS flight management computer navigation modules (FMC2 NAVM), part number (P/N) C13084CA03, installed on, but not limited to airplanes, certificated in any category. COMPLIANCE: Within 30 days after the effective date of this AD, revise the Limitations Section of the existing airplane flight manual (AFM) for your airplane by adding the information in Table 1 to the introductory text of paragraph (g)(1) of this AD and Table 2 to the introductory text of paragraph (g)(1) of this AD.										
<b>2023-21-05 Par. (g)(2)</b>	<b>Navigation - Thales AVS France SAS Flight Management Computer Navigation Modules (FMC2 NAVM) - Update the Database for Thales FMC2 NAVM - P/N C13084CA03</b>						RE (-)		Mandatory (Appliance AD)	
34 A/F						Days	13-Nov-2023			
Eff: 12-Dec-2023 Not Applicable	affected P/N is not installed					Hrs	783:10			
(ISSUING AUTHORITY: FAA)						Ldg	518			
Note: APPLICABILITY: This AD applies to Thales AVS France SAS flight management computer navigation modules (FMC2 NAVM), part number (P/N) C13084CA03, installed on, but not limited to airplanes, certificated in any category. COMPLIANCE: Within 30 days after the effective date of this AD, update the database for your Thales FMC2 NAVM, P/N C13084CA03, with a database that does not contain the procedures specified in section II of Thales Service Information Letter F9111-J70859DN-00, issued January 18, 2022 (Thales SIL F9111-J70859DN-00).										
<b>2024-0024</b>	<b>Navigation - Digital Air Data Computer - Replacement</b>						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	26-Jan-2024			
Eff: 07-Feb-2024 Not Applicable	as per installed PN					Hrs	883			
(ISSUING AUTHORITY: EASA)						Ldg	593			
Note: COMPLIANCE: For Group 1 aircraft: Within 12 months after the effective date of this AD, remove each affected part from service and replace it with a serviceable part in accordance with the instructions of the SB.										
<b>560XL-34-27</b>	<b>Navigation - Universal Avionics Performance Database</b>						T (A/R)		Optional	
34 A/F						Mos				
Eff: 01-May-2003						Hrs				
						Ldg				
<b>560XL-34-37</b>	<b>Enhanced Ground Proximity Warning System (EGPWS) Steep Approach Switch Installation</b>						T (A/R)		Optional	
34 A/F						Mos				
Eff: 29-Mar-2004						Hrs				
						Ldg				
<b>560XL-34-40</b>	<b>Enhanced Ground Proximity Warning System (EGPWS) Runway Awareness Advisory System (RAAS) Upgrade</b>						RE (-)		Recommended	
34 A/F						Mos	22-Jun-2022			
Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			










Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>560XL-34-40 Rev 01</b>	<b>Enhanced Ground Proximity Warning System (EGPWS) Runway Awareness Advisory System (RAAS) Upgrade</b>						T (A/R)		Optional	
 34 A/F						Mos				
Eff: 05-Mar-2008						Hrs				
						Ldg				
<b>560XL-34-41</b>	<b>Honeywell Transponder Upgrade for Elementary Surveillance</b>						RE (-)		Recommended	
 34 A/F						Mos	22-Jun-2022			
Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			
<b>560XL-34-41 Rev 01</b>	<b>Honeywell Transponder Upgrade for Elementary Surveillance</b>						RE (-)		Recommended	
 34 A/F						Mos	22-Jun-2022			
Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			
<b>560XL-34-41 Rev 02</b>	<b>Honeywell Transponder Upgrade for Elementary Surveillance</b>						T (A/R)		Optional	
 34 A/F						Mos				
Eff: 15-Jun-2006						Hrs				
						Ldg				
<b>560XL-34-43</b>	<b>Universal Avionics Performance Database Upgrade</b>						RE (-)		Recommended	
 34 A/F						Mos	22-Jun-2022			
Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			
<b>560XL-34-43 Rev 01</b>	<b>Universal Avionics Performance Database Upgrade</b>						T (A/R)		Optional	
 34 A/F						Mos				
Eff: 27-Jan-2006						Hrs				
						Ldg				
<b>560XL-34-49</b>	<b>Runway Awareness Advisory System (RAAS) Audio Inhibit Switch Installation</b>						RE (-)		Mandatory	
 34 A/F						Mos	22-Jun-2022			
Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			
<b>560XL-34-49 Rev 01</b>	<b>Runway Awareness Advisory System (RAAS) Audio Inhibit Switch Installation</b>						T (A/R)		Optional	
 34 A/F						Mos				
Eff: 29-Nov-2007						Hrs				
						Ldg				
<b>560XL-34-63</b>	<b>XLS+ FMS 4.0 (WAAS) Upgrade and V-Speeds Database Installation</b>						RE (-)		Recommended	
 34 A/F						Mos	22-Jun-2022			
Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			
<b>560XL-34-63 Rev 01</b>	<b>XLS+ FMS 4.0 (WAAS) Upgrade and V-Speeds Database Installation</b>						RE (-)		Recommended	
 34 A/F						Mos	22-Jun-2022			
Eff: 30-Mar-2010 Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			
<b>560XL-34-64</b>	<b>CAT II Landing Operation Option</b>						T (A/R)		Optional	
 34 A/F						Mos				
Eff: 02-Dec-2009						Hrs				
						Ldg				
<b>560XL-34-65</b>	<b>XLS+ Adaptive Flight Displays (AFD) Software and Hardware</b>						RE (-)		Recommended	
 34 A/F						Mos	22-Jun-2022			
Eff: 02-Dec-2009 Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			






















Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>560XL-34-68</b>	<b>AFD AOA Configuration Wiring Installation</b>								RE (-)	Recommended
 34 A/F						Mos	22-Jun-2022			
Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			
<b>560XL-34-68 Rev 01</b>	<b>AFD AOA Configuration Wiring Installation</b>								RE (-)	Recommended
 34 A/F						Mos	22-Jun-2022			
Eff: 15-Jun-2011 Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			
<b>560XL-34-73</b>	<b>Traffic Surveillance System (TTR-4000) TCAS II Software 7.1 Upgrade</b>								RE (-)	Optional
 34 A/F						Mos				
Eff: 01-Aug-2012						Hrs				
						Ldg				
<b>560XL-34-74</b>	<b>Navigation - GPS-4000S Software Update</b>								RE (-)	Recommended
 34 A/F						Mos	22-Jun-2022			
Eff: 28-Apr-2014 Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			
<b>560XL-34-76</b>	<b>Navigation - Automatic Dependent Surveillance Broadcast (ADS-B) Out Transponder Installation</b>								RE (-)	Optional
 34 A/F						Mos				
Eff: 03-Mar-2016						Hrs				
						Ldg				
<b>94-01-04</b>	<b>Honeywell - Traffic Alert And Collision Avoidance System (TCAS) II</b>								RE (-)	Mandatory (Appliance AD)
 34 A/F						Mos	22-Jun-2022			
Eff: 04-Feb-1994 Complied With (ISSUING AUTHORITY: FAA)						Hrs	8			
						Ldg	6			
<b>96-24-06</b>	<b>Icing Condition or Ice on the Wing Addition to AFM (Superseded by AD 2000-03-09)</b>								RE (-)	Mandatory
 34 A/F						Mos	22-Jun-2022			
Eff: 05-Dec-1996 Not Applicable	Due to aircraft is not in the suspect serial range					Hrs	8			
(ISSUING AUTHORITY: FAA)						Ldg	6			
<b>98-25-02</b>	<b>BF Goodrich Avionics Systems, Inc. SKYWATCH SKY497 Installations with a Top-Mounted Antenna</b>								RE (-)	Mandatory (Appliance AD)
 34 A/F						Mos	22-Jun-2022			
Eff: 22-Dec-1998 Not Applicable	Due to suspect parts are not installed on this aircraft					Hrs	8			
(ISSUING AUTHORITY: FAA)						Ldg	6			
<b>CIL-34-04</b>	<b>Navigation - TDR-94/94D Transponder All - Call</b>								T (A/R)	Informational
 34 A/F						Mos				
Eff: 25-Sep-2014						Hrs				
						Ldg				
<b>CIL-34-08</b>	<b>Navigation - Transmittal of Collins Aerospace Service Bulletin ATL-4000-34-D, Navigation - ALT-4000 - Evaluation of Surface Mount Ferrite Bead Used on the Power Supply</b>								RE (-)	Recommended
 34 A/F						Mos	22-Jun-2022			
Eff: 18-May-2021 Not Applicable	effective before manufacture					Hrs	8			
(AVG MAN HRS: 2.5)						Ldg	6			
<b>CIL-34-11</b>	<b>Navigation - Transmittal of Collins Aerospace Service Bulletin ALT-4000-34-14, Navigation - ALT 4000 Power Supply Robustness Improvement</b>								RE (-)	Optional, Service Letter
 34 A/F						Mos				
Eff: 17-Oct-2022						Hrs				
(AVG MAN HRS: 2.5)						Ldg				














Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>ICA-560XL-34-00010</b>	<b>Honeywell ADS-B Out (ICA Supplement)</b>								RE (-)	Mandatory
 34 A/F						Mos	22-Jun-2022			
Eff: 26-Apr-2016 Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			
<b>ICA-560XL-34-00011</b>	<b>GH-3000/3900 Electronic Standby Instrument - System Update</b>						T (A/R)		ICA Supplement	
 34 A/F						Mos				
Eff: 22-Mar-2018						Hrs				
						Ldg				
<b>SB560XL-34-81</b>	<b>Navigation - FMS-3000 Flight Management System (FMS) Search and Rescue Upgrade</b>						T (A/R)		Optional	
 34 A/F						Mos				
Eff: 17-Dec-2018						Hrs				
						Ldg				
Note: NOTE: Airplanes -6002, -6004 thru -6013, -6015 thru -6023, -6025 thru -6028, -6030, -6032 thru -6035 and -6037 thru -6044 must incorporate SB560XL-34-63 Navigation - XLS+ FMS 4.0 (WAAS) Upgrade and V-Speeds Database Installation prior to or in conjunction with this service bulletin.										
<b>SB560XL-34-82</b>	<b>Navigation - Standby Flight Display (SFD) Weight on Wheels (WOW) Electrical Wiring Improvement</b>						RE (-)		Recommended	
 34 A/F						Mos	10-Jul-2023			
Eff: 22-May-2023 Not Applicable	as per aircraft s/n					Hrs	556:05			
(AVG MAN HRS: 3.5)						Ldg	369			
<b>SL560XL-34-01</b>	<b>Navigation - B-RNAV Operation Navigation System Approval</b>						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 27-Jul-1998						Hrs				
						Ldg				
<b>SL560XL-34-02</b>	<b>Reduced Vertical Separation Minimum (RVSM)</b>						RE (-)		Optional	
 34 A/F						Mos				
						Hrs				
						Ldg				
<b>SL560XL-34-02 Rev 01</b>	<b>Reduced Vertical Separation Minimum (RVSM)</b>						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 01-Dec-2004						Hrs				
						Ldg				
<b>SL560XL-34-04</b>	<b>Navigation - IC-600/IC-615 Integrated Avionics Computer Operational Check</b>						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 17-Sep-2001						Hrs				
						Ldg				
<b>SL560XL-34-05</b>	<b>Navigation - Transmittal of Meggitt Avionics Service Information Letter No. 17, Secondary Flight Displays Mark 2</b>						RE (-)		Optional	
 34 A/F						Mos				
						Hrs				
						Ldg				
<b>SL560XL-34-05 Rev 01</b>	<b>Navigation - Transmittal of Meggitt Avionics Service Information Letter No. 17, Secondary Flight Displays Mark 2</b>						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 21-Dec-2001						Hrs				
						Ldg				
<b>SL560XL-34-06</b>	<b>Navigation - TCAS Compatibility with RVSM Operations</b>						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 17-Jul-2002						Hrs				
						Ldg				









Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SL560XL-34-08A	34 A/F Eff: 17-Feb-2003 Not Applicable	Navigation - Transmittal of Honeywell Technical Newsletter A23-3850-001  by aircraft S/N						RE (-)		Mandatory	
						Mos	22-Jun-2022				
						Hrs	8				
						Ldg	6				
SL560XL-34-10	34 A/F Eff: 21-Apr-2003	Navigation - Pitot/Static Leak Check Update						T (A/R)		Informational	
						Mos					
						Hrs					
SL560XL-34-14	34 A/F Eff: 01-Apr-2004	Flux Valve Inspection Criteria						T (A/R)		Informational	
						Mos					
						Hrs					
SL560XL-34-15	34 A/F Eff: 01-Apr-2004	560XL Compass System Troubleshooting Procedures						T (A/R)		Informational	
						Mos					
						Hrs					
SL560XL-34-21	34 A/F Eff: 25-Feb-2009	Operational Compliance Summary for EASA Temporary Guidance Leaflet (TGL) -36 Approval of Electronic Flight Bags (EFB) for the Rockwell Collins Integrated Flight Information System (IFIS)						T (A/R)		Informational	
						Mos					
						Hrs					
SL560XL-34-25	34 A/F Eff: 22-Jun-2016	Navigation - Transmittal of Rockwell Collins Service Information Letter 16-1 - Function of Reset Override Mode Switch on XM Weather Receiver for Proline 21/Proline Fusion						RE (-)		Informational	
						Mos					
						Hrs					
SL560XL-34-26	34 A/F Eff: 13-Mar-2019 Not Applicable (AVG MAN HRS: 2)	Navigation - 822-2189-100 GPS-4000S SB15 Update  effective before manufacture						RE (-)	Recommended, Service Letter		
						Mos	22-Jun-2022				
						Hrs	8				
SL560XL-34-27	34 A/F Eff: 19-Aug-2020 Not Applicable	Navigation - GPS-4000S Global Positioning System Software Update  by aircraft S/N						RE (-)		Recommended	
						Mos	22-Jun-2022				
						Hrs	8				
SL560XL-34-27 R1	34 A/F Eff: 15-Mar-2021 Not Applicable	Navigation - GPS-4000s Global Positioning System Software Update  by aircraft S/N						RE (-)	Recommended, Service Letter		
						Mos	22-Jun-2022				
						Hrs	8				
SL560XL-34-27 R2	34 A/F Eff: 06-Oct-2021 Not Applicable	Navigation - GPS-4000s Global Positioning System Software Update  by aircraft S/N						RE (-)		Mandatory	
						Mos	22-Jun-2022				
						Hrs	8				
SL560XL-34-29	34 A/F Eff: 01-Sep-2020 Not Applicable (AVG MAN HRS: 0.5)	Navigation - Implement Airplane Flight Manual (AFM) Changes  by aircraft S/N						RE (-)	Mandatory, Service Letter		
						Mos	22-Jun-2022				
						Hrs	8				
						Ldg	6				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>SL560XL-34-30</b>	<b>Navigation - Transmittal of Collins Aerospace Service Bulletin FGC-3XXX-22-AA - Pitch Trim Failure and/or Chatter at Start-Up</b>						T (A/R)		Optional	
 34 A/F						Mos				
Eff: 26-Sep-2022						Hrs				
						Ldg				
Note: EFFECTIVITIY: 560XL (XLS+) 560-6001 thru 560-6044, that have incorporated SB 560XL-34-63.										
<b>SL560XL-53-20</b>	<b>Fuselage - Instrument Panel Support Fastener Verification</b>						RE (-)		Recommended	
 34 A/F						Mos	22-Jun-2022			
Eff: 03-Dec-2018 Not	effective before manufacture					Hrs	8			
Applicable						Ldg	6			
(AVG MAN HRS: 14)										
▼ 35 - OXYGEN										
<b>2023-13-11</b>	<b>Oxygen - AVOX Systems Inc. (Formerly Scott Aviation) Oxygen Cylinder and Valve Assemblies (Supersedes FAA AD 2022-04-09)</b>						RE (-)		Mandatory (Appliance AD)	
 35 A/F						Days	08-Aug-2023			
Eff: 05-Sep-2023 Not	as per P/Ns installed					Hrs	616:39			
Applicable						Ldg	407			
(ISSUING AUTHORITY: FAA)										
Note: APPLICABILITY: This AD applies to AVOX Systems Inc. (formerly Scott Aviation) oxygen cylinder and valve assemblies having part number (P/N) 89794077, 89794015, 891511-14, 806835-01, 807982-01, 808433-01, or 891311-14; and oxygen valve assemblies (body and gage assemblies) having P/N 807206-01. These assemblies might be installed on, but not limited to, the aircraft identified in paragraphs (c)(1) through (12) of this AD, certificated in any category.										
COMPLIANCE: Within 60 days after the effective date of this AD, inspect the oxygen valve assemblies, and oxygen cylinder and valve assemblies, to determine if the serial numbers of the valve, cylinder, and entire assembly, are listed in Appendix 1 or Appendix 2, "Affected Shipments," of the applicable service information identified in paragraphs (h)(1) through (3) of this AD. A review of airplane maintenance records is acceptable in lieu of this inspection if the serial numbers can be conclusively determined from that review.										
<b>CIL-35-02</b>	<b>Oxygen-Transmittal of Zodiac Aerotechnics Service Bulletin MC10-35-274</b>						RE (-)		Mandatory	
 35 A/F						Mos	22-Jun-2022			
Eff: 12-Jun-2015 Not	by aircraft S/N					Hrs	8			
Applicable						Ldg	6			
<b>CIL-35-05</b>	<b>Oxygen - Transmittal of Zodiac Aerospace Service Bulletin MCF-35-001</b>						RE (-)		Mandatory	
 35 A/F						Mos	22-Jun-2022			
Eff: 08-Jan-2016 Not	effective before manufacture					Hrs	8			
Applicable						Ldg	6			
(AVG MAN HRS: 3)										
Note: All Citation Models with flight crew oxygen mask regulators, having P/N MC10, MF10, MF20 series with S?N as listed in Zodiac Aerospace SB MCF-SBU-35-001										
<b>SB560XL-35-04</b>	<b>Oxygen - Oxygen System Pressure Switch Replacement for Chinese Registered Airplanes</b>						T (A/R)		Optional	
 35 A/F						Mos				
Eff: 13-Aug-2018						Hrs				
						Ldg				
<b>SL560XL-35-03</b>	<b>Transmittal of AVOX Systems Service Bulletin 36758-35-01</b>						RE (-)		Recommended	
 35 A/F						Mos	22-Jun-2022			
Eff: 23-Jul-2009 Not	effective before manufacture					Hrs	8			
Applicable						Ldg	6			
<b>SL560XL-35-04</b>	<b>Transmittal of Intertechnique Service Bulletin MXH-35-240 Revision 2</b>						RE (-)		Optional	
 35 A/F						Mos				
						Hrs				
						Ldg				
<b>SL560XL-35-04 Rev 01</b>	<b>Transmittal of Intertechnique Service Bulletin MXH-35-240 Revision 2</b>						RE (-)		Optional	
 35 A/F						Mos				
						Hrs				
						Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>SL560XL-35-04 Rev 02</b>	<b>Transmittal of Intertechnique Service Bulletin MXH-35-240 Revision 2</b>						RE (-)		Mandatory	
 35 A/F	by aircraft S/N				Mos	22-Jun-2022				
Eff: 25-Oct-2012 Not Applicable					Hrs	8				
					Ldg	6				
<b>▼ 38 - WATER/WASTE</b>										
<b>560XL-38-03</b>	<b>Toilet Override Relay Installation</b>						RE (-)		Optional	
 38 A/F					Mos					
Eff: 03-Mar-2014					Hrs					
					Ldg					
<b>SL560XL-38-01</b>	<b>Transmittal of Monogram Systems Service Information Letter SIL 15900-023</b>						RE (-)		Recommended	
 38 A/F	effective before manufacture				Mos	22-Jun-2022				
Eff: 06-Jan-2011 Not Applicable					Hrs	8				
					Ldg	6				
<b>▼ 49 - AIRBORNE AUXILIARY POWER</b>										
<b>3615880-49-8149</b>	<b>Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUs</b>						RE (-)		Recommended	
 49 APU1	effective before manufacture				Mos	22-Jun-2022				
Eff: 12-Jun-2015 Not Applicable					Hrs	09:06				
					APUS	26				
<b>3615880-49-8149 Rev 1</b>	<b>Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUs</b>						RE (-)		Recommended	
 49 APU1	effective before manufacture				Mos	22-Jun-2022				
Not Applicable					Hrs	09:06				
					APUS	26				
<b>3615880-49-8149 Rev 2</b>	<b>Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUs</b>						RE (-)		Recommended	
 49 APU1	effective before manufacture				Mos	22-Jun-2022				
Not Applicable					Hrs	09:06				
					APUS	26				
<b>3615880-49-8149 Rev 3</b>	<b>Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUs</b>						RE (-)		Recommended	
 49 APU1	effective before manufacture				Mos	22-Jun-2022				
Eff: 15-Dec-2017 Not Applicable					Hrs	09:06				
(AVG MAN HRS: 1.5)					APUS	26				
<b>3822101-49-8148 Rev 1</b>	<b>Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, P/N 3822101-1, on Multiple APU's</b>						RE (-)		Recommended	
 49 APU1	effective before manufacture				Mos	22-Jun-2022				
Eff: 20-Oct-2015 Not Applicable					Hrs	09:06				
					APUS	26				
<b>3881800-49-7523</b>	<b>Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS</b>						RE (-)		Recommended	
 49 APU1	effective before manufacture				Mos	22-Jun-2022				
Eff: 01-Feb-2000 Not Applicable					Hrs	09:06				
(AVG MAN HRS: 2)					APUS	26				
<b>3881800-49-7523 Rev 1</b>	<b>Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS</b>						RE (-)		Recommended	
 49 APU1	effective before manufacture				Mos	22-Jun-2022				
Eff: 05-May-2000 Not Applicable					Hrs	09:06				
(AVG MAN HRS: 2)					APUS	26				












Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
3881800-49-7523 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS						RE (-)		Recommended	
	49 APU1	effective before manufacture					Mos	22-Jun-2022			
	Eff: 26-Oct-2001 Not Applicable						Hrs	09:06			
	(AVG MAN HRS: 2)						APUS	26			
3881800-49-7523 Rev 3		Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS						RE (-)		Recommended	
	49 APU1	effective before manufacture					Mos	22-Jun-2022			
	Eff: 22-Feb-2002 Not Applicable						Hrs	09:06			
	(AVG MAN HRS: 2)						APUS	26			
3881800-49-7523 Rev 4		Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS						RE (-)		Recommended	
	49 APU1	effective before manufacture					Mos	22-Jun-2022			
	Eff: 30-Oct-2014 Not Applicable						Hrs	09:06			
	(AVG MAN HRS: 2)						APUS	26			
3883900-49-7976		Airborne Auxiliary Power - Main Fuel Control Unit (FCU) - Check Nameplate for Latest Change Number. Install Fuel Flow Deflector, PN 70720001-1, on the Fuel Control Differential Pressure (Delta P) Sleeve as Required at Next Auxiliary Power Unit (APU) Shop Visit						RE (-)		Recommended	
	49 APU1	effective before manufacture					Mos	22-Jun-2022			
	Eff: 25-Feb-2009 Not Applicable						Hrs	09:06			
	(AVG MAN HRS: 1)						APUS	26			
3883900-49-7976 Rev 1		Airborne Auxiliary Power - Main Fuel Control Unit (FCU) - Check Nameplate for Latest Change Number. Install Fuel Flow Deflector, PN 70720001-1, on the Fuel Control Differential Pressure (Delta P) Sleeve as Required at Next Auxiliary Power Unit (APU) Shop Visit						RE (-)		Recommended	
	49 APU1	effective before manufacture					Mos	22-Jun-2022			
	Eff: 10-Apr-2009 Not Applicable						Hrs	09:06			
	(AVG MAN HRS: 1)						APUS	26			
3883900-49-7976 Rev 2		Airborne Auxiliary Power - Main Fuel Control Unit (FCU) - Check Nameplate for Latest Change Number. Install Fuel Flow Deflector, PN 70720001-1, on the Fuel Control Differential Pressure (Delta P) Sleeve as Required at Next Auxiliary Power Unit (APU) Shop Visit						RE (-)		Recommended	
	49 APU1	effective before manufacture					Mos	22-Jun-2022			
	Eff: 11-May-2019 Not Applicable						Hrs	09:06			
	(AVG MAN HRS: 1)						APUS	26			
3883900-49-8297		Airborne Auxiliary Power - Gas Turbine Engine - Replace Oil Seal, PN 3883905-1, with PN 70722907-1 on the Fuel Control Unit (FCU), PN 3883900-1 for the RE100 APU						RE (-)		Recommended	
	49 APU1	effective before manufacture					Mos	22-Jun-2022			
	Eff: 24-Feb-2020 Not Applicable						Hrs	09:06			
							APUS	26			
		Note: COMPLIANCE: This service bulletin, recommended by Honeywell, is done on an attritional basis, oil seal to be replaced if a high leakage rate is present.									
49-7933		Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						RE (-)			
	49 APU1						Mos				
	Eff: 24-Apr-2007						Hrs				
							APUS				
49-7933 Rev 1		Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						RE (-)	Service Bulletin		
	49 APU1						Mos				
	Eff: 04-Jun-2007						Hrs				
							APUS				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>49-7933 Rev 10</b>		<b>Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils</b>						T (A/R)		Service Bulletin	
	49 APU1					Mos					
	Eff: 18-Jan-2022					Hrs					
						APUS					
<b>49-7933 Rev 2</b>		<b>Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils</b>						RE (-)		Service Bulletin	
	49 APU1					Mos					
	Eff: 09-Apr-2010					Hrs					
						APUS					
<b>49-7933 Rev 3</b>		<b>Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils</b>						RE (-)		Service Bulletin	
	49 APU1					Mos					
	Eff: 31-Oct-2011					Hrs					
						APUS					
<b>49-7933 Rev 4</b>		<b>Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils</b>						RE (-)		Service Bulletin	
	49 APU1					Mos					
	Eff: 12-Aug-2014					Hrs					
						APUS					
<b>49-7933 Rev 5</b>		<b>Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils</b>						T (-)		Service Bulletin	
	49 APU1					Mos					
	Eff: 23-Oct-2014					Hrs					
						APUS					
<b>49-7933 Rev 6</b>		<b>Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils</b>						RE (-)		Service Bulletin	
	49 APU1					Mos					
						Hrs					
						APUS					
<b>49-7933 Rev 7</b>		<b>Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils</b>						T (-)		Service Bulletin	
	49 APU1					Mos					
	Eff: 09-Feb-2017					Hrs					
						APUS					
<b>49-7933 Rev 8</b>		<b>Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils</b>						T (-)		Service Bulletin	
	49 APU1					Mos					
	Eff: 27-Jul-2017					Hrs					
						APUS					
<b>49-7933 Rev 9</b>		<b>Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils</b>						T (-)		Service Bulletin	
	49 APU1					Mos					
	Eff: 03-Apr-2020					Hrs					
						APUS					
<b>49-7992</b>		<b>Remove and Replace Electronic Control Unit, PN 2119552-2 or PN 2119552-3, with Electronic Control Unit, PN 2119552-4</b>						RE (-)		Optional	
	49 APU1					Mos					
						Hrs					
						APUS					
<b>49-7992 Rev 1</b>		<b>Remove and Replace Electronic Control Unit, PN 2119552-2 or PN 2119552-3, with Electronic Control Unit, PN 2119552-4</b>						RE (-)		Optional	
	49 APU1					Mos					
						Hrs					
						APUS					
<b>49-7997</b>		<b>Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines</b>						RE (-)		Service Bulletin	
	49 APU1					Mos					
	Eff: 16-Sep-2009					Hrs					
						APUS					
<b>49-7997 Rev 1</b>		<b>Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines</b>						RE (-)		Service Bulletin	
	49 APU1					Mos					
	Eff: 11-Feb-2010					Hrs					
						APUS					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>49-7997 Rev 2</b>	<b>Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines</b>								RE (-)	Service Bulletin
 49 APU1										
Eff: 22-Dec-2010										
<b>49-7997 Rev 3</b>	<b>Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines</b>								RE (-)	Service Bulletin
 49 APU1										
Eff: 16-Jan-2014										
<b>49-7997 Rev 4</b>	<b>Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines</b>								T (-)	Service Bulletin
 49 APU1										
Eff: 12-Jan-2015										
<b>49-7997 Rev 5</b>	<b>Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines</b>								T (-)	Service Bulletin
 49 APU1										
Eff: 03-Feb-2017										
<b>49-7997 Rev 6</b>	<b>Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines</b>								T (A/R)	Service Bulletin
 49 APU1										
Eff: 05-Nov-2020										
<b>49-8252</b>	<b>Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs</b>								T (-)	
 49 APU1										
Eff: 31-Aug-2018										
<b>49-8252 Rev 1</b>	<b>Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs</b>								T (-)	
 49 APU1										
Eff: 07-Mar-2019										
<b>49-8252 Rev 2</b>	<b>Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs</b>								T (A/R)	Service Bulletin
 49 APU1										
Eff: 13-Oct-2020										
<b>560XL-49-17</b>	<b>Auxiliary Power - Auxiliary Power Unit Mount Bolt Change</b>								RE (-)	Optional
 49 A/F										
Eff: 05-Oct-2015										
<b>70721597-49-8166</b>	<b>Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs</b>								RE (-)	Recommended
 49 APU1										
Eff: 02-Jul-2015 Not Applicable	effective before manufacture						22-Jun-2022			
							09:06			
							26			
<b>70721597-49-8166 Rev 1</b>	<b>Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs</b>								RE (-)	Recommended
 49 APU1										
Eff: 31-Aug-2015 Not Applicable	effective before manufacture						22-Jun-2022			
							09:06			
							26			
<b>70721597-49-8166 Rev 2</b>	<b>Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs</b>								RE (-)	Recommended
 49 APU1										
Eff: 25-Oct-2016 Not Applicable	effective before manufacture						22-Jun-2022			
							09:06			
							26			























Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>70721597-49-8166 Rev 3</b>		<b>Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs</b>						RE (-)		Recommended	
	49 APU1					Mos	22-Jun-2022				
	Eff: 13-Oct-2017 Not Applicable	effective before manufacture				Hrs	09:06				
	(AVG MAN HRS: 1)					APUS	26				
		Note: COMPLIANCE: Honeywell recommends this service bulletin be done for the balance repair of the compressor rotor, PN 70721597-1.									
<b>70721598-49-8168</b>		<b>Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs</b>						RE (-)		Recommended	
	49 APU1					Mos	22-Jun-2022				
	Eff: 02-Jul-2015 Not Applicable	effective before manufacture				Hrs	09:06				
						APUS	26				
<b>70721598-49-8168 Rev 1</b>		<b>Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs</b>						RE (-)		Recommended	
	49 APU1					Mos	22-Jun-2022				
	Eff: 20-Oct-2015 Not Applicable	effective before manufacture				Hrs	09:06				
						APUS	26				
<b>70721598-49-8168 Rev 2</b>		<b>Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs</b>						RE (-)		Recommended	
	49 APU1					Mos	22-Jun-2022				
	Eff: 10-Jan-2017 Not Applicable	effective before manufacture				Hrs	09:06				
						APUS	26				
<b>70721598-49-8168 Rev 3</b>		<b>Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs</b>						RE (-)		Recommended	
	49 APU1					Mos	22-Jun-2022				
	Eff: 14-Dec-2017 Not Applicable	effective before manufacture				Hrs	09:06				
	(AVG MAN HRS: 1)					APUS	26				
<b>70721725-49-8152</b>		<b>Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs</b>						RE (-)		Recommended	
	49 APU1					Mos	22-Jun-2022				
	Eff: 27-May-2015 Not Applicable	effective before manufacture				Hrs	09:06				
						APUS	26				
<b>70721725-49-8152 Rev 1</b>		<b>Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs</b>						RE (-)		Recommended	
	49 APU1					Mos	22-Jun-2022				
	Eff: 27-May-2015 Not Applicable	effective before manufacture				Hrs	09:06				
						APUS	26				
<b>70721725-49-8152 Rev 2</b>		<b>Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs</b>						RE (-)		Recommended	
	49 APU1					Mos	22-Jun-2022				
	Not Applicable	effective before manufacture				Hrs	09:06				
						APUS	26				
<b>70721725-49-8152 Rev 3</b>		<b>Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs</b>						RE (-)		Recommended	
	49 APU1					Mos	22-Jun-2022				
	Eff: 27-Nov-2017 Not Applicable	effective before manufacture				Hrs	09:06				
						APUS	26				
<b>70721725-49-8152 Rev 4</b>		<b>Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs</b>						RE (-)		Recommended	
	49 APU1					Mos	22-Jun-2022				
	Eff: 19-Dec-2017 Not Applicable	effective before manufacture				Hrs	09:06				
						APUS	26				
<b>D20110700024 Rev 1</b>		<b>Approved Use of Biofuel Blends for All Honeywell Commercial and Military Auxiliary Power Units (APU)</b>						T (A/R)		Service Information Letter	
	49 APU1					Mos					
	Eff: 03-Jun-2020					Hrs					
						APUS					












Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>D201112000050</b>	<b>Acceptance Criteria for On-Wing Borescope Inspections</b>						RE (-)		Service Information Letter	
 49 APU1						Mos				
Eff: 13-Jan-2012						Hrs				
						APUS				
<b>D201112000050 Rev 1</b>	<b>Acceptance Criteria for On-Wing Borescope Inspections</b>						T (A/R)		Service Information Letter	
 49 APU1						Mos				
Eff: 14-Aug-2012						Hrs				
						APUS				
<b>D201308000026</b>	<b>Uncommanded High Oil Temperature (HOT) Shutdown of the RE100[CS] and RE100[XL] AuxiliaryPower Units (APUs)</b>						RE (-)		Service Information Letter	
 49 APU1						Mos				
Eff: 10-Jan-2014						Hrs				
						APUS				
<b>D201308000026 Rev 1</b>	<b>Uncommanded High Oil Temperature (HOT) Shutdown of the RE100[CS] and RE100[XL] AuxiliaryPower Units (APUs)</b>						T (A/R)		Service Information Letter	
 49 APU1						Mos				
Eff: 30-Mar-2016						Hrs				
						APUS				
<b>D202207002674</b>	<b>Procedure to Determine if Hydro Pad Compressor Seal is Damaged and Evaluate if it was the Cause for Oil Leaks on the RE100 Series and 36-150 Series APUs</b>						T (A/R)		Service Information Letter	
 49 APU1						Mos				
Eff: 16-Aug-2022						Hrs				
						APUS				
Note: EFFECTIVITY: Please see Par. B for more details.										
<b>RE100-49-7400</b>	<b>Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, PN 3881739-2 with PN 3881800-1, Gearbox Housing, PN 3863409-4 with PN 3863409-2, and O-Ring, PN M83248/1-115 with PN M83248/1-116</b>						RE (-)		Optional	
 49 APU1						Mos				
Eff: 01-Feb-2000						Hrs				
						APUS				
<b>RE100-49-7400 Rev 1</b>	<b>Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, Part No. 3881739-2 with Part No. 3881800-1, Gearbox Housing, Part No. 3863409-1/-2 with Part No. 3863409-3/-4 (Respectively), and O-ring, Part No. M83248/1-116 with Part No. M83248/1-115</b>						T (A/R)		Optional	
 49 APU1						Mos				
Eff: 14-Jun-2000						Hrs				
						APUS				
<b>RE100-49-7465</b>	<b>Replace Thermocouple, Part No. 3876315-1</b>						RE (-)		Recommended	
 49 APU1						Mos	22-Jun-2022			
Not Applicable	effective before manufacture					Hrs	09:06			
						APUS	26			
<b>RE100-49-7489</b>	<b>Airborne Auxiliary Power - Gas Turbine Engine - Replace Oil Filler Neck And Cap, PN 2A1126 (527-510-9001) With Oil Filler Neck and Dipstick Cap, PN 2A7732 (361-530-9354)</b>						RE (-)		Optional	
 49 APU1						Mos				
Eff: 02-Feb-2000						Hrs				
						APUS				
<b>RE100-49-7530</b>	<b>Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, PN 3881800-1 with PN 3881825-1</b>						RE (-)		Recommended	
 49 APU1						Mos	22-Jun-2022			
Eff: 01-Feb-2000 Not Applicable	effective before manufacture					Hrs	09:06			
						APUS	26			
<b>RE100-49-7530 Rev 1</b>	<b>Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, PN 3881800-1 with PN 3881825-1</b>						RE (-)		Recommended	
 49 APU1						Mos	22-Jun-2022			
Not Applicable	effective before manufacture					Hrs	09:06			
						APUS	26			












Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
RE100-49-7530 Rev 2	Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, PN 3881800-1 with PN 3881825-1						RE (-)		Recommended	
49 APU1						Mos	22-Jun-2022			
Eff: 22-Feb-2002 Not Applicable	effective before manufacture					Hrs	09:06			
						APUS	26			
RE100-49-7535	Airborne Auxiliary Power - Gas Turbine Engine - Replace Flow Divider Tee, PN 3883921-1 with PN 3883921-2						RE (-)		Recommended	
49 APU1						Mos	22-Jun-2022			
Eff: 01-Oct-1999 Not Applicable	effective before manufacture					Hrs	09:06			
						APUS	26			
RE100-49-7563	Airborne Auxiliary Power - Gas Turbine Engine - Replace Generator Seal, PN 3863387-1 with PN 3863504-1						RE (-)		Recommended	
49 APU1						Mos	22-Jun-2022			
Eff: 11-May-2000 Not Applicable	effective before manufacture					Hrs	09:06			
						APUS	26			
RE100-49-7563 Rev 1	Airborne Auxiliary Power - Gas Turbine Engine - Replace Generator Seal, PN 3863387-1 with PN 3863504-1						RE (-)		Recommended	
49 APU1						Mos	22-Jun-2022			
Eff: 22-May-2002 Not Applicable	effective before manufacture					Hrs	09:06			
						APUS	26			
RE100-49-7773	Replace Electronic Control Unit (ECU), Part No. 2119552-2 with Part No. 2119552-3						RE (-)			
49 APU1						Mos				
						Hrs				
						APUS				
RE100-49-7787	Replace Low Oil Level Switch, Part No. 3876318-1 with Part No. 3876318-2						RE (-)		Optional	
49 APU1						Mos				
Eff: 21-Jun-2004						Hrs				
						APUS				
RE100-49-7855	Replace Low Oil Level Switch, Part No. 3876318-1 or Part No. 3876318-2 with Part No. 3876318-3						RE (-)		Optional	
49 APU1						Mos				
Eff: 09-Aug-2005						Hrs				
						APUS				
RE100-49-7896	Replace Oil Filler Neck and Cap						RE (-)		Optional	
49 APU1						Mos				
						Hrs				
						APUS				
RE100-49-7896 Rev 1	Airborne Auxiliary Power - Gas Turbine Engine - Replace Oil Filler Neck and (Dipstic) Cap, P/N 361-530-9354						T (A/R)		Optional	
49 APU1						Mos				
						Hrs				
						APUS				
RE100-49-8139	Airborne Auxiliary Power - Gas Turbine Engine - Increase the Installation Torque and add the Use of Locking Compound During Carbon Seal Assembly on the RE100 APU						RE (-)		Recommended	
49 APU1						Mos	22-Jun-2022			
Eff: 15-Aug-2014 Not Applicable	effective before manufacture					Hrs	09:06			
						APUS	26			
RE100-49-8250	Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Module, PN 3881825-1 with PN 3881825-2, for the RE100[CS] and RE100[XL] Auxiliary Power Unit (APU)						RE (-)			
49 APU1						Mos				
Eff: 11-Sep-2017						Hrs				
						APUS				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
RE100-49-8250 Rev 1	49 APU1 Eff: 15-Jun-2018	Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Module, PN 3881825-1 with PN 3881825-2 for the RE100[CS] and RE100[XL] Auxiliary Power Unit (APU)						RE (-)			
						Mos					
						Hrs					
						APUS					
RE100-49-8250 Rev 2	49 APU1 Eff: 30-Oct-2020	Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Module, PN 3881825-1 with PN 3881825-2, for the RE100[CS] and RE100[XL] Auxiliary Power Unit (APU)						RE (-)		Service Bulletin	
						Mos					
						Hrs					
						APUS					
RE100-49-8303	49 APU1 Eff: 24-Feb-2020	Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)						RE (-)		Optional	
						Mos					
						Hrs					
						APUS					
RE100-49-8303 Rev 1	49 APU1 Eff: 01-Jul-2020	Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)						RE (-)		Optional	
						Mos					
						Hrs					
						APUS					
RE100-49-8303 Rev 2	49 APU1 Eff: 28-Aug-2020	Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)						RE (-)		Optional	
						Mos					
						Hrs					
						APUS					
RE100-49-8303 Rev 3	49 APU1 Eff: 01-Sep-2020	Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)						RE (-)		Optional	
						Mos					
						Hrs					
						APUS					
RE100-49-8303 Rev 4	49 APU1 Eff: 18-May-2022	Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)						RE (-)		Optional	
						Mos					
						Hrs					
						APUS					
RE100-49-8360 Rev 1	49 APU1 Eff: 23-Feb-2022 Not Applicable (AVG MAN HRS: 1)	Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet PN M24243/6A401H with PN 627-504-9209 on Engines RE100[CS], RE100[LJ], and RE100[XL] effective before manufacture						RE (-)		Cat. 2 - Recommended	
						Mos	22-Jun-2022				
						Hrs	09:06				
						APUS	26				
RE100-49-8360 Rev 2	49 APU1 Eff: 29-Mar-2022 Not Applicable (AVG MAN HRS: 1)	Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet PN M24243/6A401H with PN 627-504-9209 on RE100 Engine Models effective before manufacture						RE (-)		Cat. 2 - Recommended	
						Mos	22-Jun-2022				
						Hrs	09:06				
						APUS	26				
RE100-49-8363	49 APU1 Eff: 10-May-2022	Airborne Auxiliary Power - Gas Turbine Engine - Replace Inlet Housing PN 3810880-1/-2 with PN 70724596-1 or PN 70724596-2, Gearbox Housing PN 3863409-6 with PN 70724597-1, Gearbox Housing PN 3863409-5 with PN 70724597-2 and Gearbox Housing PN 3863409-4 with PN 70724597-3 on the RE100 Auxiliary Power Unit (APU)						RE (-)		Optional	
						Mos					
						Hrs					
						APUS					










Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>RE100-49-8363 Rev 1</b>		<b>Airborne Auxiliary Power - Gas Turbine Engine - Replace Inlet Housing PN 3810880-1/-2 with PN 70724596-1 or PN 70724596-2, Gearbox Housing PN 3863409-6 with PN 70724597-1, Gearbox Housing PN 3863409-5 with PN 70724597-2 and Gearbox Housing PN 3863409-4 with PN 70724597-3 on the RE100 Auxiliary Power Unit (APU)</b>						T (A/R)		Optional	
	49 APU1										
	Eff: 04-Aug-2022										
	Note: EFFECTIVITY: Refer to Par. 1.A. of this SB for more information.										
<b>SIL APU-152</b>		<b>Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel</b>						RE (-)		Service Information Letter	
	49 APU1										
	Eff: 18-Jul-2008										
<b>SIL APU-152 Rev 1</b>		<b>Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel</b>						RE (-)		Service Information Letter	
	49 APU1										
	Eff: 24-Jul-2009										
<b>SIL APU-152 Rev 2</b>		<b>Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel</b>						RE (-)		Service Information Letter	
	49 APU1										
	Eff: 30-Nov-2010										
<b>SIL APU-152 Rev 3</b>		<b>Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel</b>						RE (-)		Service Information Letter	
	49 APU1										
	Eff: 19-Feb-2015										
<b>SIL APU-152 Rev 4</b>		<b>Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel</b>						T (A/R)		Service Information Letter	
	49 APU1										
	Eff: 08-Feb-2018										
<b>SIL APU-7</b>		<b>Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)</b>						RE (-)		Service Information Letter	
	49 APU1										
<b>SIL APU-7 Rev 1</b>		<b>Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)</b>						RE (-)		Service Information Letter	
	49 APU1										
	Eff: 03-Mar-1988										
<b>SIL APU-7 Rev 2</b>		<b>Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)</b>						T (A/R)		Service Information Letter	
	49 APU1										
	Eff: 02-Mar-2015										
<b>SIL APU-95 Rev 1</b>		<b>Uncommanded Protective Shutdown of the Auxiliary Power Unit (APU) with High Oil Temperature (HOT) Identified</b>						RE (-)		Cancelled	
	49 APU1										
	Eff: 13-Jul-2020										
<b>SIL D201701000026</b>		<b>Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine Worksheet for 36-100, 36-150, RE100, and RE220 APUs</b>						RE (-)		Service Information Letter	
	49 APU1										
	Eff: 30-Jan-2017										












Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	49 APU1 Eff: 23-Jan-2018	SIL D201701000026 Rev 1 Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine Worksheet for 36-100, 36-150, RE100, and RE220 APUs						T (-)		Service Information Letter	
	49 APU1 Eff: 21-Mar-2018	SIL D201701000026 Rev 2 Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine worksheet for 36-100, 36-150, RE100, and RE220 APUs						T (A/R)		Service Information Letter	
	49 APU1	SIL No. APU-49 Rev 10 Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)						RE (-)		Service Information Letter	
			Note: COMPLIANCE: Every Aircraft 'A' check or every 500 APU hours or per AMM or MM criteria (customer option).								
	49 APU1	SIL No. APU-49 Rev 11 Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units(APUs)						RE (-)		Service Information Letter	
			Note: Analyst/operator will need to manually set the calendar start. COMPLIANCE: Every Aircraft 'A' check or every 500 APU hours or per AMM or MM criteria (customer option).								
	49 APU1	SIL No. APU-49 Rev 12 Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)						RE (-)		Service Information Letter	
			Note: COMPLIANCE: First and subsequent oil and filter sample. Every Aircraft 'A' check or every 500 APU hours or per AMM or MM criteria (customer option).								
	49 APU1 Eff: 23-Nov-2023	SIL No. APU-49 Rev 13 Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APU)						T (A/R)		Service Information Letter	
	49 APU1	SIL No. APU-49 Rev 9 Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)						RE (-)		Service Information Letter	
			Note: The SOAP and filter analysis program was initially limited to the operators of the GTC36-100/-150 Series Auxiliary Power Units enrolled in the Honeywell Engines, Systems & Services APU Maintenance Service Plan (MSP). The program is now offered to all operators of the Honeywell GTC36-100/-150, RE100 and RE220 Series APUs.								
	49 A/F Eff: 08-Apr-2011	SL560XL-49-09 Transmittal of Honeywell Service Bulletin RE100-49-7992 Airborne Auxiliary Power - Gas Turbine Engine - Remove and Replace Electronic Control Unit, PN 2119552-2 or PN 2119552-3, with Electronic Control Unit, PN 2119552-4						RE (-)		Informational	
	49 A/F Eff: 08-May-2018	SL560XL-49-13 Auxiliary Power - Transmittal of Honeywell Service Bulletin RE100-49-8250 Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Module, PN 3881825-1 with PN 3881825-2, for the RE100[CS] and RE100[XL] Auxiliary Power Unit (APU)						RE (-)		Informational, Service Letter	
	49 A/F Eff: 13-Mar-2023	SL560XL-49-14 Auxiliary Power - Transmittal of Honeywell Service Bulletin RE100-49-8364 Auxiliary Airborne - Gas Turbine Engine - Replace Wiring Harness PN 3888395-2 with PN 3888395-3 on the RE100[XL] Auxiliary Power Unit (APU)						T (A/R)		Optional	













Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
▼ 52 - DOORS										
<b>SL560XL-52-07</b>	<b>Exterior Door Switch Improvement</b>								RE (-)	Informational
 52 A/F										
Eff: 03-Mar-2011										
<b>SL560XL-52-08</b>	<b>Doors - Cabin Door Lintel Fastener Verification</b>								RE (-)	Recommended
 52 A/F										
Eff: 14-May-2020 Not	effective before manufacture									
Applicable										
(AVG MAN HRS: 1)										
<b>SL560XL-52-09</b>	<b>Doors - Cabin Entry Door Fastener Verification</b>								RE (-)	Service Letter
 52 A/F										
Eff: 08-Dec-2017										
(AVG MAN HRS: 2)										
<b>SL560XL-52-11</b>	<b>Doors - Installation of Protective Sleeve on the Cabin Entry Door Step Light Wire Harness Assembly</b>								RE (-)	Recommended
 52 A/F										
Eff: 17-Jul-2023 Not	as per A/C S/N									
Applicable										
(AVG MAN HRS: 2)										
▼ 53 - FUSELAGE										
<b>560XL-53-13</b>	<b>Nose Drip Cap Bond Inspection</b>								RE (-)	Recommended
 53 A/F										
Not Applicable	by S/N									
<b>560XL-53-13 Rev 01</b>	<b>Nose Drip Cap Bond Inspection</b>								RE (-)	Mandatory
 53 A/F										
Eff: 05-Oct-2011 Not	by S/N									
Applicable										
<b>560XL-53-14</b>	<b>Carbon Fiber Strake Modification</b>								RE (-)	Optional
 53 A/F										
Eff: 09-Apr-2012										
<b>560XL-53-15</b>	<b>Fastener Installation F.S. 115.20</b>								RE (-)	Mandatory
 53 A/F										
Eff: 19-Jan-2011 Not	by S/N									
Applicable										
<b>560XL-53-16</b>	<b>Stinger Drain Installation</b>								RE (-)	Mandatory
 53 A/F										
Eff: 04-Oct-2011 Not	by aircraft S/N									
Applicable										
<b>ASL560XL-53-08A</b>	<b>Aft Canted Bulkhead Drain Installation</b>								RE (-)	Recommended
 53 A/F										
Not Applicable	by aircraft S/N									
<b>ASL560XL-53-08A Rev 01</b>	<b>Aft Canted Bulkhead Drain Installation</b>								RE (-)	Mandatory
 53 A/F										
Eff: 27-Jan-2011 Not	by aircraft S/N									
Applicable										













Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>CIL-53-01</b>		<b>Fuselage - Nose Radome Guide Pin Replacement</b>						RE (-)		Recommended, Service Letter	
	53 A/F						Mos	22-Jun-2022			
	Eff: 17-Dec-2020 Not Applicable	effective before manufacture					Hrs	8			
	(AVG MAN HRS: 1.5)						Ldg	6			
<b>CIL-53-01 R1</b>		<b>Fuselage - Nose Radome Guide Pin Replacement</b>						RE (-)		Recommended	
	53 A/F						Mos	22-Jun-2022			
	Eff: 17-Mar-2021 Not Applicable	effective before manufacture					Hrs	8			
	(AVG MAN HRS: 1.5)						Ldg	6			
<b>SL560XL-53-03</b>		<b>Fuselage - Lightning Diverter Strip Installation/Repair Procedure Change (Radome)</b>						T (A/R)		Informational	
	53 A/F						Mos				
	Eff: 14-Aug-2001						Hrs				
							Ldg				
<b>SL560XL-53-07</b>		<b>Lower Skin Assembly Fastener Inspection</b>						RE (-)		Mandatory	
	53 A/F						Mos	22-Jun-2022			
	Eff: 14-Apr-2009 Not Applicable	by aircraft S/N					Hrs	8			
							Ldg	6			
<b>SL560XL-53-16</b>		<b>Fastener Inspection/Installation</b>						RE (-)		Mandatory	
	53 A/F						Mos	22-Jun-2022			
	Eff: 16-Aug-2011 Not Applicable	by aircraft S/N					Hrs	8			
							Ldg	6			
<b>SL560XL-53-17</b>		<b>Dorsal Duct Inspection</b>						RE (-)		Recommended	
	53 A/F						Mos	22-Jun-2022			
	Eff: 20-Nov-2012 Not Applicable	effective before manufacture					Hrs	8			
							Ldg	6			
<b>SL560XL-53-18</b>		<b>Fuselage - Tailcone Missing Fastener Inspection and Installation</b>						RE (-)		Mandatory	
	53 A/F						Mos	22-Jun-2022			
	Eff: 13-Jan-2016 Not Applicable	by aircraft S/N					Hrs	8			
	(AVG MAN HRS: 2.2)						Ldg	6			
<b>SL560XL-53-18 Rev 01</b>		<b>Fuselage - Tailcone Missing Fastener Inspection and Installation</b>						RE (-)		Mandatory	
	53 A/F						Mos	22-Jun-2022			
	Eff: 22-Jun-2016 Not Applicable	by aircraft S/N					Hrs	8			
	(AVG MAN HRS: 2.2)						Ldg	6			
<b>SL560XL-53-19</b>		<b>Fuselage - Empennage Fastener Verification</b>						RE (-)		Recommended	
	53 A/F						Mos	22-Jun-2022			
	Eff: 14-May-2020 Not Applicable	effective before manufacture					Hrs	8			
	(AVG MAN HRS: 1)						Ldg	6			
<b>SL560XL-53-19 R1</b>		<b>Fuselage - Empennage Fastener Verification</b>						RE (-)		Recommended	
	53 A/F						Mos	22-Jun-2022			
	Eff: 19-Jun-2020 Not Applicable	effective before manufacture					Hrs	8			
	(AVG MAN HRS: 1)						Ldg	6			
<b>SL560XL-53-21</b>		<b>Fuselage - Inspection of the Tailcone Stinger Attach Nutplates for Damage</b>						RE (-)		Recommended, Service Letter	
	53 A/F						Mos	19-Jul-2024			
	Eff: 24-Jun-2024 Not Applicable	N/A Due to aircraft different SN					Hrs				
	(AVG MAN HRS: 4)						Ldg				
























Task No	Description										Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining		
▼ 55 - STABILIZERS												
<b>SL560XL-55-01</b>	<b>Stabilizers - Pivot Fitting Inspection</b>						RE (-)		Mandatory			
 55 A/F					Mos	22-Jun-2022						
Not Applicable	by aircraft S/N				Hrs	8						
					Ldg	6						
<b>SL560XL-55-01 Rev 01</b>	<b>Stabilizers - Pivot Fitting Inspection</b>						RE (-)		Mandatory			
 55 A/F					Mos	22-Jun-2022						
Not Applicable	by aircraft S/N				Hrs	8						
					Ldg	6						
<b>SL560XL-55-01 Rev 02</b>	<b>Stabilizers - Pivot Fitting Inspection</b>						RE (-)		Mandatory			
 55 A/F					Mos	22-Jun-2022						
Eff: 12-Jun-2015 Not Applicable	by aircraft S/N				Hrs	8						
					Ldg	6						
Note: This service letter must be accomplished on airplanes that have attained 6,000 flight hours or more within 600 flight hours or one year from the date of receipt of the original issue of service letter. Aircraft that are under 6,000 flight hours on the date of receipt of the original issue of this service letter will need to comply with this service letter upon attaining 6,000 flight hours but not exceeding 6,600 flight hours.												
<b>SL560XL-55-01 Rev 03</b>	<b>Stabilizers - Pivot Fitting Inspection (Cancelled)</b>						RE (-)		Mandatory			
 55 A/F					Mos	22-Jun-2022						
Eff: 09-Jun-2016 Not Applicable	by aircraft S/N				Hrs	8						
					Ldg	6						
Note: NOTE: The inspection requirement previously contained in this service letter can now be found in the Phase 71 and the Inspection Document 52 inspections in the Cessna Model 560XL Maintenance Manual Revision 40. NOTE: This revision replaces the original issue of SL560XL-55-01 and previous revisions in their entirety.												
<b>SL560XL-55-02</b>	<b>Stabilizers - Replacement of the Rudder Stop Block</b>						RE (-)	Recommended, Service Letter				
 55 A/F					Mos	22-Jun-2022						
Eff: 04-Nov-2019 Not Applicable	effective before manufacture				Hrs	8						
					Ldg	6						
<b>SL560XL-55-03</b>	<b>Stabilizers - Inspection of the Horizontal Stabilizer Upper and Lower Splice Plate Huck Bolt Fasteners</b>						RE (-)	Recommended				
 55 A/F					Mos	03-Oct-2022						
Eff: 16-May-2022 Not Applicable	as per A/Cs S/N				Hrs	167:53						
(AVG MAN HRS: 194)					Ldg	115						
<b>SL560XL-55-03 R1</b>	<b>Stabilizers - Inspection of the Horizontal Stabilizer Upper and Lower Splice Plate Huck Bolt Fasteners</b>						RE (-)	Recommended				
 55 A/F					Mos	03-Oct-2022						
Eff: 26-Sep-2022 Not Applicable	as per A/Cs S/N				Hrs	167:53						
(AVG MAN HRS: 194)					Ldg	115						
▼ 56 - WINDOWS												
<b>SL560XL-56-02</b>	<b>Windshield Delamination</b>						T (A/R)		Informational			
 56 A/F					Mos							
Eff: 31-Mar-2009					Hrs							
					Ldg							
<b>SL560XL-56-03</b>	<b>Openable Cockpit Window Hinge and Latch Inspection</b>						RE (-)		Mandatory			
 56 A/F					Mos	22-Jun-2022						
Eff: 07-Dec-2010 Not Applicable	by aircraft S/N				Hrs	8						
					Ldg	6						














Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
▼ 71 - POWER PLANT										
<b>560XL-71-11</b>	<b>Engine Fuel Manifold Drain Line Installation Revision 1</b>						RE (-)		Optional	
 71 A/F						Mos				
						Hrs				
						Ldg				
<b>560XL-71-11 Rev 01</b>	<b>Engine Fuel Manifold Drain Line Installation Revision 1</b>						T (A/R)		Optional	
 71 A/F						Mos				
Eff: 02-Aug-2012						Hrs				
						Ldg				
<b>560XL-71-12</b>	<b>Engine Fuel Manifold Drain Line Removal</b>						T (A/R)		Optional	
 71 A/F						Mos				
Eff: 01-Oct-2012						Hrs				
						Ldg				
<b>CIL-71-01</b>	<b>Transmittal of Pratt &amp; Whitney Canada Service Bulletin 30463</b>						RE (-)		Optional	
 71 A/F						Mos				
Eff: 29-Jan-2013						Hrs				
						Ldg				
<b>SIL-PW500-068</b>	<b>PW500 Engine Calibration Check</b>						T (A/R)		Service Information Letter	
 71 ENG1						Mos				
Eff: 31-May-2017						Hrs				
						Enc				
<b>SIL-PW500-068</b>	<b>PW500 Engine Calibration Check</b>						T (A/R)		Service Information Letter	
 71 ENG2						Mos				
Eff: 31-May-2017						Hrs				
						Enc				
<b>SL560XL-71-01</b>	<b>Power Plant - Transmittal Of Aeroquip Aerospace Service Bulletin ASB125 How To Repair Silicone Covered Hose Abrasions Using AE272 Flexwrap Firesleeve</b>						T (A/R)		Informational	
 71 A/F						Mos				
Eff: 21-Jan-2001						Hrs				
						Ldg				
<b>SL560XL-71-09</b>	<b>Transmittal of Pratt &amp; Whitney Canada (P&amp;WC) Service Bulletin Number 30294R2, Turbofan Engine Oil Tank Filler Cap Inspection Of</b>						T (A/R)		Informational	
 71 A/F						Mos				
Eff: 15-Jun-2006						Hrs				
						Ldg				
<b>SL560XL-71-11</b>	<b>Power Plant - Inspect the Left and Right Engine Forward Upper and Lower Isolator Assembly Mount Bolt Heads for Safety Wire Holes</b>						RE (-)		Recommended, Service Letter	
 71 A/F						Mos	22-Jun-2022			
Eff: 15-Aug-2019 Not Applicable	by aircraft S/N					Hrs	8			
(AVG MAN HRS: 4)						Ldg	6			
<b>SL560XL-71-11 R1</b>	<b>Power Plant - Inspect the Left and Right Engine Forward Upper and Lower Isolator Assembly Mount Bolt Heads for Safety Wire Holes</b>						RE (-)		Recommended, Service Letter	
 71 A/F						Mos	22-Jun-2022			
Eff: 29-Aug-2019 Not Applicable	by aircraft S/N					Hrs	8			
(AVG MAN HRS: 4)						Ldg	6			
<b>SL560XL-71-11 R2</b>	<b>Power Plant - Inspect the Left and Right Engine Forward Upper and Lower Isolator Assembly Mount Bolt Heads for Safety Wire Holes</b>						RE (-)		Recommended, Service Letter	
 71 A/F						Mos	22-Jun-2022			
Eff: 23-Oct-2019 Not Applicable	by aircraft S/N					Hrs	8			
(AVG MAN HRS: 4)						Ldg	6			













Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
▼ 72 - ENGINE										
<b>30325</b>	<b>Oil-Pump Plain Seal - Replacement</b>						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30325</b>	<b>Oil-Pump Plain Seal - Replacement</b>						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30325 Rev 1</b>	<b>Oil-Pump Plain Seal - Replacement</b>						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Eff: 12-Jun-2009 Complied With					Hrs					
					Enc					
<b>30325 Rev 1</b>	<b>Oil-Pump Plain Seal - Replacement</b>						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Eff: 12-Jun-2009 Complied With					Hrs					
					Enc					
<b>30325 Rev 3</b>	<b>Oil-Pump Plain Seal - Replacement</b>						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Eff: 30-Aug-2017 Complied With					Hrs					
(AVG MAN HRS: 2)					Enc					
<b>30325 Rev 3</b>	<b>Oil-Pump Plain Seal - Replacement</b>						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Eff: 30-Aug-2017 Complied With					Hrs					
(AVG MAN HRS: 2)					Enc					
<b>30333</b>	<b>Fan Rotor Balancing Assembly - Replacement / Modification</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 26-Jan-2010 Complied With					Hrs					
					Enc					
<b>30333</b>	<b>Fan Rotor Balancing Assembly - Replacement / Modification</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 26-Jan-2010 Complied With					Hrs					
					Enc					
<b>30354</b>	<b>Accessory-Gearbox Plain-Seal - Replacement</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30354</b>	<b>Accessory-Gearbox Plain-Seal - Replacement</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30354 Rev 1</b>	<b>Accessory-Gearbox Plain-Seal - Replacement</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 28-Apr-2008 Complied With					Hrs					
					Enc					
<b>30354 Rev 1</b>	<b>Accessory-Gearbox Plain-Seal - Replacement</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 28-Apr-2008 Complied With					Hrs					
					Enc					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
<b>30361</b>		<b>Outer Front Bypass Duct With New Studs - Replacement</b>					RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021			
	Eff: 05-May-2008 Complied With					Hrs				
						Enc				
<b>30361</b>		<b>Outer Front Bypass Duct With New Studs - Replacement</b>					RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021			
	Eff: 05-May-2008 Complied With					Hrs				
						Enc				
<b>30362</b>		<b>HP Turbine Disk Balancing Assembly with Thicker Feather Seals - Replacement</b>					RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021			
	Eff: 05-Jun-2008 Complied With					Hrs				
						Enc				
<b>30362</b>		<b>HP Turbine Disk Balancing Assembly with Thicker Feather Seals - Replacement</b>					RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021			
	Eff: 05-Jun-2008 Complied With					Hrs				
						Enc				
<b>30365</b>		<b>Inlet Pressure Oil Tube Assy - Replacement</b>					RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021			
	Eff: 09-May-2008 Complied With					Hrs				
						Enc				
<b>30365</b>		<b>Inlet Pressure Oil Tube Assy - Replacement</b>					RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021			
	Eff: 09-May-2008 Complied With					Hrs				
						Enc				
<b>30366</b>		<b>Air/Oil Separator - Replacement</b>					RE (-)		Category 7	
	72 ENG1					Mos				
	Eff: 01-May-2008 Complied With					Hrs				
						Enc				
<b>30366</b>		<b>Air/Oil Separator - Replacement</b>					RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021			
	Eff: 01-May-2008 Complied With					Hrs				
						Enc				
<b>30369</b>		<b>Oil Pump Assembly With A New Rear Oil Pump Housing - Replacement/Modification</b>					RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021			
	Complied With					Hrs				
						Enc				
<b>30369</b>		<b>Oil Pump Assembly With A New Rear Oil Pump Housing - Replacement/Modification</b>					RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021			
	Complied With					Hrs				
						Enc				
<b>30369 Rev 1</b>		<b>Oil Pump Assembly With A New Rear Oil Pump Housing - Replacement/Modification</b>					RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021			
	Eff: 02-Sep-2011 Complied With					Hrs				
						Enc				
<b>30369 Rev 1</b>		<b>Oil Pump Assembly With A New Rear Oil Pump Housing - Replacement/Modification</b>					RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021			
	Eff: 02-Sep-2011 Complied With					Hrs				
						Enc				
<b>30370</b>		<b>Fuel Metering Unit - Replacement</b>					RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021			
	Complied With					Hrs				
						Enc				









Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30370</b>		<b>Fuel Metering Unit - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30370 Rev 1</b>		<b>Fuel Metering Unit - Replacement</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 16-Feb-2009	Complied With				Hrs					
						Enc					
<b>30370 Rev 1</b>		<b>Fuel Metering Unit - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 16-Feb-2009	Complied With				Hrs					
						Enc					
<b>30371</b>		<b>Accessory Gearbox FCU - Starter Gearshaft Oil Baffle - Introduction</b>						RE (-)		Category 10	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30371</b>		<b>Accessory Gearbox FCU - Starter Gearshaft Oil Baffle - Introduction</b>						RE (-)		Category 10	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30371 Rev 1</b>		<b>Accessory Gearbox FCU - Starter Gearshaft Oil Baffle - Introduction</b>						RE (-)		Category 10	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30371 Rev 1</b>		<b>Accessory Gearbox FCU - Starter Gearshaft Oil Baffle - Introduction</b>						RE (-)		Category 10	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30371 Rev 2</b>		<b>Accessory Gearbox FCU - Starter Gearshaft Oil Baffle - Introduction</b>						RE (-)		Category 10	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 11-Mar-2014	Complied With				Hrs					
						Enc					
<b>30371 Rev 2</b>		<b>Accessory Gearbox FCU - Starter Gearshaft Oil Baffle - Introduction</b>						RE (-)		Category 10	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 11-Mar-2014	Complied With				Hrs					
						Enc					
<b>30373</b>		<b>Secondary Fuel Pressure Tube and Support Bracket - Replacement</b>						RE (-)		Category 3	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 15-Aug-2008	Complied With				Hrs					
						Enc					
<b>30373</b>		<b>Secondary Fuel Pressure Tube and Support Bracket - Replacement</b>						RE (-)		Category 3	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 15-Aug-2008	Complied With				Hrs					
						Enc					
<b>30376</b>		<b>Oil Pump Assembly and Oil-Pump-Drive Spur Gear - Replacement/Modification</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30376</b>		<b>Oil Pump Assembly and Oil-Pump-Drive Spur Gear - Replacement/Modification</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					














Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>30376 Rev 1</b>	<b>Oil Pump Assembly and Oil-Pump-Drive Spur Gear - Replacement/Modification</b>						RE (-)		Category 7	
 72 ENG1	Eff: 19-Dec-2011 Complied With				Mos	30-Dec-2021				
					Hrs					
					Enc					
<b>30376 Rev 1</b>	<b>Oil Pump Assembly and Oil-Pump-Drive Spur Gear - Replacement/Modification</b>						RE (-)		Category 7	
 72 ENG2	Eff: 19-Dec-2011 Complied With				Mos	31-Dec-2021				
					Hrs					
					Enc					
<b>30376 Rev 2</b>	<b>Oil Pump Assembly and Oil-Pump-Drive Spur Gear - Replacement/Modification</b>						RE (-)		Category 7	
 72 ENG1	Eff: 16-Jun-2016 Complied With				Mos	30-Dec-2021				
					Hrs					
					Enc					
<b>30376 Rev 2</b>	<b>Oil Pump Assembly and Oil-Pump-Drive Spur Gear - Replacement/Modification</b>						RE (-)		Category 7	
 72 ENG2	Eff: 16-Jun-2016 Complied With				Mos	31-Dec-2021				
					Hrs					
					Enc					
<b>30379</b>	<b>By-Pass Ducts - Replacement/Modification</b>						RE (-)		Category 7	
 72 ENG1	Complied With				Mos	30-Dec-2021				
					Hrs					
					Enc					
<b>30379</b>	<b>By-Pass Ducts - Replacement/Modification</b>						RE (-)		Category 7	
 72 ENG2	Complied With				Mos	31-Dec-2021				
					Hrs					
					Enc					
<b>30379 Rev 1</b>	<b>By-Pass Ducts - Replacement/Modification</b>						RE (-)		Category 7	
 72 ENG1	Eff: 11-Sep-2015 Complied With				Mos	30-Dec-2021				
					Hrs					
					Enc					
<b>30379 Rev 1</b>	<b>By-Pass Ducts - Replacement/Modification</b>						RE (-)		Category 7	
 72 ENG2	Eff: 11-Sep-2015 Complied With				Mos	31-Dec-2021				
					Hrs					
					Enc					
<b>30380</b>	<b>Gearbox-Drive-Shaft-Accessory Gearbox Drive Gearshaft-Assembly Gearbox Drive Spline Bevel- Gearshaft / Replacement</b>						RE (-)		Category 7	
 72 ENG1	Eff: 09-Dec-2008 Complied With				Mos	30-Dec-2021				
					Hrs					
					Enc					
<b>30380</b>	<b>Gearbox-Drive-Shaft-Accessory Gearbox Drive Gearshaft-Assembly Gearbox Drive Spline Bevel- Gearshaft / Replacement</b>						RE (-)		Category 7	
 72 ENG2	Eff: 09-Dec-2008 Complied With				Mos	31-Dec-2021				
					Hrs					
					Enc					
<b>30384</b>	<b>Air/Oil Separator - Replacement</b>						RE (-)		Category 6	
 72 ENG1	Complied With				Mos	30-Dec-2021				
					Hrs					
					Enc					
<b>30384</b>	<b>Air/Oil Separator - Replacement</b>						RE (-)		Category 6	
 72 ENG2	Complied With				Mos	31-Dec-2021				
					Hrs					
					Enc					
<b>30384 Rev 1</b>	<b>Air/Oil Separator - Replacement</b>						RE (-)		Category 6	
 72 ENG1	Eff: 02-Sep-2011 Complied With				Mos	30-Dec-2021				
					Hrs					
					Enc					














Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30384 Rev 1</b>	<b>Air/Oil Separator - Replacement</b>						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Eff: 02-Sep-2011 Complied With					Hrs					
					Enc					
<b>30385</b>	<b>Data Collection Unit - Replacement</b>						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Eff: 27-Jan-2009 Complied With					Hrs					
					Enc					
<b>30385</b>	<b>Data Collection Unit - Replacement</b>						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Eff: 27-Jan-2009 Complied With					Hrs					
					Enc					
<b>30389</b>	<b>Carbon Seal No. 4 Bearing - Replacement</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 05-Mar-2009 Complied With					Hrs					
					Enc					
<b>30389</b>	<b>Carbon Seal No. 4 Bearing - Replacement</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 05-Mar-2009 Complied With					Hrs					
					Enc					
<b>30391</b>	<b>Inlet Pressure Oil Tube Assy - Replacement</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 11-Jun-2009 Complied With					Hrs					
					Enc					
<b>30391</b>	<b>Inlet Pressure Oil Tube Assy - Replacement</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 11-Jun-2009 Complied With					Hrs					
					Enc					
<b>30392</b>	<b>Bolts - Replacement</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 25-Jun-2009 Complied With					Hrs					
					Enc					
<b>30392</b>	<b>Bolts - Replacement</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 25-Jun-2009 Complied With					Hrs					
					Enc					
<b>30393</b>	<b>EEC Support Brackets - Replacement</b>						RE (-)		Category 3	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30393</b>	<b>EEC Support Brackets - Replacement</b>						RE (-)		Category 3	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30393 Rev 1</b>	<b>EEC Support Brackets - Replacement</b>						RE (-)		Category 3	
 72 ENG1					Mos	30-Dec-2021				
Eff: 02-Jun-2010 Complied With					Hrs					
					Enc					
<b>30393 Rev 1</b>	<b>EEC Support Brackets - Replacement</b>						RE (-)		Category 3	
 72 ENG2					Mos	31-Dec-2021				
Eff: 02-Jun-2010 Complied With					Hrs					
					Enc					














Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30400</b>		<b>Intermediate Case Assembly and Intershaft Seal Carrier - Replacement</b>						RE (-)		Category 6, Category 7	
	72 ENG1						Mos	30-Dec-2021			
	Complied With						Hrs				
							Enc				
<b>30400</b>		<b>Intermediate Case Assembly and Intershaft Seal Carrier - Replacement</b>						RE (-)		Category 6, Category 7	
	72 ENG2						Mos	31-Dec-2021			
	Complied With						Hrs				
							Enc				
<b>30400 Rev 1</b>		<b>Intermediate Case Assembly and Intershaft Seal Carrier - Replacement</b>						RE (-)		Category 6, Category 7	
	72 ENG1						Mos	30-Dec-2021			
	Complied With						Hrs				
							Enc				
<b>30400 Rev 1</b>		<b>Intermediate Case Assembly and Intershaft Seal Carrier - Replacement</b>						RE (-)		Category 6, Category 7	
	72 ENG2						Mos	31-Dec-2021			
	Complied With						Hrs				
							Enc				
<b>30400 Rev 2</b>		<b>Intermediate Case Assembly and Intershaft Seal Carrier - Replacement</b>						RE (-)		Category 6, Category 7	
	72 ENG1						Mos	30-Dec-2021			
	Complied With						Hrs				
							Enc				
<b>30400 Rev 2</b>		<b>Intermediate Case Assembly and Intershaft Seal Carrier - Replacement</b>						RE (-)		Category 6, Category 7	
	72 ENG2						Mos	31-Dec-2021			
	Complied With						Hrs				
							Enc				
<b>30400 Rev 3</b>		<b>Intermediate Case Assembly and Intershaft Seal Carrier - Replacement</b>						RE (-)		Category 6, Category 7	
	72 ENG1						Mos	30-Dec-2021			
	Eff: 31-Oct-2012 Complied With						Hrs				
							Enc				
<b>30400 Rev 3</b>		<b>Intermediate Case Assembly and Intershaft Seal Carrier - Replacement</b>						RE (-)		Category 6, Category 7	
	72 ENG2						Mos	31-Dec-2021			
	Eff: 31-Oct-2012 Complied With						Hrs				
							Enc				
<b>30400 Rev 4</b>		<b>Intermediate Case Assembly and Intershaft Seal Carrier - Replacement</b>						RE (-)		Category 6, Category 7	
	72 ENG1						Mos	30-Dec-2021			
	Eff: 23-Nov-2016 Complied With						Hrs				
							Enc				
<b>30400 Rev 4</b>		<b>Intermediate Case Assembly and Intershaft Seal Carrier - Replacement</b>						RE (-)		Category 6, Category 7	
	72 ENG2						Mos	31-Dec-2021			
	Eff: 23-Nov-2016 Complied With						Hrs				
							Enc				
<b>30400 Rev 4 Part A</b>		<b>Intermediate Case Assembly - Replacement</b>						RE (-)		Category 6	
	72 ENG1						Mos	30-Dec-2021			
	Eff: 23-Nov-2016 Complied With						Hrs				
							Enc				
<b>30400 Rev 4 Part A</b>		<b>Intermediate Case Assembly - Replacement</b>						RE (-)		Category 6	
	72 ENG2						Mos	31-Dec-2021			
	Eff: 23-Nov-2016 Complied With						Hrs				
							Enc				
<b>30400 Rev 4 Part B</b>		<b>Intershaft Seal Carrier - Replacement</b>						RE (-)		Category 7	
	72 ENG1						Mos	30-Dec-2021			
	Eff: 23-Nov-2016 Complied With						Hrs				
							Enc				
















Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30400 Rev 4 Part B</b>		<b>Intershaft Seal Carrier - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 23-Nov-2016 Complied With					Hrs					
						Enc					
<b>30401</b>		<b>Electronic Engine Control Re-Programming / Replacement-Modification</b>						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
<b>30401</b>		<b>Electronic Engine Control Re-Programming / Replacement-Modification</b>						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
<b>30401 Rev 1</b>		<b>Electronic Engine Control Re-Programming / Replacement-Modification</b>						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
<b>30401 Rev 1</b>		<b>Electronic Engine Control Re-Programming / Replacement-Modification</b>						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
<b>30401 Rev 2</b>		<b>Electronic Engine Control Re-Programming / Replacement-Modification</b>						T (A/R)		Category 10	
	72 ENG1					Mos					
	Eff: 20-Aug-2015					Hrs					
						Enc					
<b>30401 Rev 2</b>		<b>Electronic Engine Control Re-Programming / Replacement-Modification</b>						T (A/R)		Category 10	
	72 ENG2					Mos					
	Eff: 20-Aug-2015					Hrs					
						Enc					
<b>30403</b>		<b>Replacement of Tee Head Bolt/1st - 2nd. Stage HP Compressor Assemblies</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30403</b>		<b>Replacement of Tee Head Bolt/1st - 2nd. Stage HP Compressor Assemblies</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30403 Rev 1</b>		<b>Replacement of Tee Head Bolt/1st - 2nd. Stage HP Compressor Assemblies</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 02-Oct-2009 Complied With					Hrs					
						Enc					
<b>30403 Rev 1</b>		<b>Replacement of Tee Head Bolt/1st - 2nd. Stage HP Compressor Assemblies</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 02-Oct-2009 Complied With					Hrs					
						Enc					
<b>30403 Rev 2</b>		<b>Replacement of Tee Head Bolt/1st - 2nd Stage HP Compressor Assemblies</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 20-Apr-2017 Complied With					Hrs					
						Enc					
<b>30403 Rev 2</b>		<b>Replacement of Tee Head Bolt/1st - 2nd Stage HP Compressor Assemblies</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 20-Apr-2017 Complied With					Hrs					
						Enc					




Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30403 Rev 3</b>		<b>Replacement of Tee Head Bolt/1st - 2nd Stage HP Compressor Assemblies</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 05-Mar-2018 Complied With					Hrs					
						Enc					
<b>30403 Rev 3</b>		<b>Replacement of Tee Head Bolt/1st - 2nd Stage HP Compressor Assemblies</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 05-Mar-2018 Complied With					Hrs					
						Enc					
<b>30403 Rev 4</b>		<b>Replacement of Tee Head Bolt/1st - 2nd Stage HP Compressor Assemblies</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 12-Feb-2019 Complied With					Hrs					
						Enc					
<b>30403 Rev 4</b>		<b>Replacement of Tee Head Bolt/1st - 2nd Stage HP Compressor Assemblies</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 12-Feb-2019 Complied With					Hrs					
						Enc					
<b>30404</b>		<b>Servo Valve For The Intercompressor Bleed-Valve - Replacement</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30404</b>		<b>Servo Valve For The Intercompressor Bleed-Valve - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30404 Rev 1</b>		<b>Servo Valve For The Intercompressor Bleed-Valve - Replacement</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30404 Rev 1</b>		<b>Servo Valve For The Intercompressor Bleed-Valve - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30404 Rev 2</b>		<b>Servo Valve For The Intercompressor Bleed-Valve - Replacement</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30404 Rev 2</b>		<b>Servo Valve For The Intercompressor Bleed-Valve - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30404 Rev 3</b>		<b>Servo Valve For The Intercompressor Bleed-Valve - Replacement</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 03-May-2010 Complied With					Hrs					
						Enc					
<b>30404 Rev 3</b>		<b>Servo Valve For The Intercompressor Bleed-Valve - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 03-May-2010 Complied With					Hrs					
						Enc					
<b>30407</b>		<b>Electronic Engine Control (EEC) - Replacement/Modification</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 12-Nov-2009 Complied With					Hrs					
						Enc					













Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30407</b>		<b>Electronic Engine Control (EEC) - Replacement/Modification</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 12-Nov-2009 Complied With					Hrs					
						Enc					
<b>30407 Rev 1</b>		<b>Electronic Engine Control (EEC) - Replacement/Modification</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 30-Aug-2017 Complied With					Hrs					
	(AVG MAN HRS: 2)					Enc					
<b>30407 Rev 1</b>		<b>Electronic Engine Control (EEC) - Replacement/Modification</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 30-Aug-2017 Complied With					Hrs					
	(AVG MAN HRS: 2)					Enc					
<b>30411</b>		<b>Gaskets - Replacement</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30411</b>		<b>Gaskets - Replacement</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30411 Rev 1</b>		<b>Gaskets - Replacement</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 22-Mar-2010 Complied With					Hrs					
						Enc					
<b>30411 Rev 1</b>		<b>Gaskets - Replacement</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 22-Mar-2010 Complied With					Hrs					
						Enc					
<b>30413</b>		<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30413</b>		<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30413 Rev 1</b>		<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30413 Rev 1</b>		<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30413 Rev 10</b>		<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 29-Aug-2017 Complied With					Hrs					
						Enc					
<b>30413 Rev 10</b>		<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 29-Aug-2017 Complied With					Hrs					
						Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30413 Rev 11</b>		<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 30-Nov-2018 Complied With					Hrs					
						Enc					
<b>30413 Rev 11</b>		<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 30-Nov-2018 Complied With					Hrs					
						Enc					
<b>30413 Rev 12</b>		<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 21-Dec-2021 Complied With					Hrs					
						Enc					
<b>30413 Rev 12</b>		<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 21-Dec-2021 Complied With					Hrs					
						Enc					
<b>30413 Rev 2</b>		<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30413 Rev 2</b>		<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30413 Rev 3</b>		<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30413 Rev 3</b>		<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30413 Rev 4</b>		<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30413 Rev 4</b>		<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30413 Rev 5</b>		<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30413 Rev 5</b>		<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30413 Rev 6</b>		<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30413 Rev 6</b>	<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
 72 ENG2	Complied With				Mos	31-Dec-2021				
					Hrs					
					Enc					
<b>30413 Rev 7</b>	<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
 72 ENG1	Eff: 08-Oct-2013 Complied With				Mos	30-Dec-2021				
					Hrs					
					Enc					
<b>30413 Rev 7</b>	<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
 72 ENG2	Eff: 08-Oct-2013 Complied With				Mos	31-Dec-2021				
					Hrs					
					Enc					
<b>30413 Rev 8</b>	<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
 72 ENG1	Eff: 08-Jan-2016 Complied With				Mos	30-Dec-2021				
					Hrs					
					Enc					
<b>30413 Rev 8</b>	<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
 72 ENG2	Eff: 08-Jan-2016 Complied With				Mos	31-Dec-2021				
					Hrs					
					Enc					
<b>30413 Rev 9</b>	<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
 72 ENG1	Eff: 10-Aug-2016 Complied With				Mos	30-Dec-2021				
					Hrs					
					Enc					
<b>30413 Rev 9</b>	<b>Introduction of Deeper Sump</b>						RE (-)		Category 6	
 72 ENG2	Eff: 10-Aug-2016 Complied With				Mos	31-Dec-2021				
					Hrs					
					Enc					
<b>30415</b>	<b>No. 4 Roller Bearing - Replacement</b>						RE (-)		Category 6	
 72 ENG1	Complied With				Mos	30-Dec-2021				
					Hrs					
					Enc					
<b>30415</b>	<b>No. 4 Roller Bearing - Replacement</b>						RE (-)		Category 6	
 72 ENG2	Complied With				Mos	31-Dec-2021				
					Hrs					
					Enc					
<b>30415 Rev 1</b>	<b>No. 4 Roller Bearing - Replacement</b>						RE (-)		Category 6	
 72 ENG1	Eff: 13-May-2013 Complied With				Mos	30-Dec-2021				
					Hrs					
					Enc					
<b>30415 Rev 1</b>	<b>No. 4 Roller Bearing - Replacement</b>						RE (-)		Category 6	
 72 ENG2	Eff: 13-May-2013 Complied With				Mos	31-Dec-2021				
					Hrs					
					Enc					
<b>30415 Rev 2</b>	<b>No. 4 Roller Bearing - Replacement</b>						RE (-)		Category 6	
 72 ENG1	Eff: 06-Jan-2016 Complied With				Mos	30-Dec-2021				
					Hrs					
					Enc					
<b>30415 Rev 2</b>	<b>No. 4 Roller Bearing - Replacement</b>						RE (-)		Category 6	
 72 ENG2	Eff: 06-Jan-2016 Complied With				Mos	31-Dec-2021				
					Hrs					
					Enc					




Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30415 Rev 3</b>		<b>Replacement of No. 4 Roller Bearing</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 13-Oct-2016	Complied With				Hrs					
						Enc					
<b>30415 Rev 3</b>		<b>Replacement of No. 4 Roller Bearing</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 13-Oct-2016	Complied With				Hrs					
						Enc					
<b>30415 Rev 4</b>		<b>Replacement of No. 4 Roller Bearing</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 06-Aug-2020	Complied With				Hrs					
						Enc					
<b>30415 Rev 4</b>		<b>Replacement of No. 4 Roller Bearing</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 06-Aug-2020	Complied With				Hrs					
						Enc					
<b>30416</b>		<b>No.4 Bearing Carbon Seal - Replacement</b>						RE (-)		Category 10	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30416</b>		<b>No.4 Bearing Carbon Seal - Replacement</b>						RE (-)		Category 10	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30416 Rev 1</b>		<b>No.4 Bearing Carbon Seal - Replacement</b>						RE (-)		Category 10	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 23-Oct-2013	Complied With				Hrs					
						Enc					
<b>30416 Rev 1</b>		<b>No.4 Bearing Carbon Seal - Replacement</b>						RE (-)		Category 10	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 23-Oct-2013	Complied With				Hrs					
						Enc					
<b>30417</b>		<b>Front Seal Runner No. 4 Bearing - Replacement</b>						RE (-)		Category 10	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30417</b>		<b>Front Seal Runner No. 4 Bearing - Replacement</b>						RE (-)		Category 10	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30417 Rev 1</b>		<b>Front Seal Runner No. 4 Bearing - Replacement</b>						RE (-)		Category 10	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30417 Rev 1</b>		<b>Front Seal Runner No. 4 Bearing - Replacement</b>						RE (-)		Category 10	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30417 Rev 2</b>		<b>Front Seal Runner No. 4 Bearing - Replacement</b>						RE (-)		Category 10	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					











Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30417 Rev 2</b>		<b>Front Seal Runner No. 4 Bearing - Replacement</b>						RE (-)		Category 10	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
<b>30417 Rev 3</b>		<b>Front Seal Runner No. 4 Bearing - Replacement</b>						RE (-)		Category 10	
	72 ENG1	Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
<b>30417 Rev 3</b>		<b>Front Seal Runner No. 4 Bearing - Replacement</b>						RE (-)		Category 10	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
<b>30417 Rev 4</b>		<b>Front Seal Runner No. 4 Bearing - Replacement</b>						RE (-)		Category 10	
	72 ENG1	Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
<b>30417 Rev 4</b>		<b>Front Seal Runner No. 4 Bearing - Replacement</b>						RE (-)		Category 10	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
<b>30417 Rev 5</b>		<b>Front Seal Runner No. 4 Bearing - Replacement</b>						RE (-)		Category 10	
	72 ENG1	Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
<b>30417 Rev 5</b>		<b>Front Seal Runner No. 4 Bearing - Replacement</b>						RE (-)		Category 10	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
<b>30417 Rev 6</b>		<b>Front Seal Runner No. 4 Bearing - Replacement</b>						RE (-)		Category 10	
	72 ENG1	Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
<b>30417 Rev 6</b>		<b>Front Seal Runner No. 4 Bearing - Replacement</b>						RE (-)		Category 10	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
<b>30417 Rev 7</b>		<b>Front Seal Runner No. 4 Bearing - Replacement</b>						RE (-)		Category 10	
	72 ENG1	Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
<b>30417 Rev 7</b>		<b>Front Seal Runner No. 4 Bearing - Replacement</b>						RE (-)		Category 10	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
<b>30417 Rev 8</b>		<b>Front Seal Runner No. 4 Bearing - Replacement</b>						RE (-)		Category 10	
	72 ENG1	Eff: 23-Nov-2012 Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
<b>30417 Rev 8</b>		<b>Front Seal Runner No. 4 Bearing - Replacement</b>						RE (-)		Category 10	
	72 ENG2	Eff: 23-Nov-2012 Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				







Task No	Description										Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
30418 	72 ENG1 Complied With	Electrical Wiring Harness (TT0 Sensor) - Replacement						RE (-)		Category 6		
					Mos	30-Dec-2021						
					Hrs							
					Enc							
30418 	72 ENG2 Complied With	Electrical Wiring Harness (TT0 Sensor) - Replacement						RE (-)		Category 6		
					Mos	31-Dec-2021						
					Hrs							
					Enc							
30418 Rev 1 	72 ENG1 Eff: 12-Apr-2011 Complied With	Electrical Wiring Harness (TT0 Sensor) - Replacement						RE (-)		Category 6		
					Mos	30-Dec-2021						
					Hrs							
					Enc							
30418 Rev 1 	72 ENG2 Eff: 12-Apr-2011 Complied With	Electrical Wiring Harness (TT0 Sensor) - Replacement						RE (-)		Category 6		
					Mos	31-Dec-2021						
					Hrs							
					Enc							
30419 	72 ENG1 Eff: 28-Sep-2010 Complied With	Combustion Chamber Liner - Replacement						RE (-)		Category 7		
					Mos	30-Dec-2021						
					Hrs							
					Enc							
30419 	72 ENG2 Eff: 28-Sep-2010 Complied With	Combustion Chamber Liner - Replacement						RE (-)		Category 7		
					Mos	31-Dec-2021						
					Hrs							
					Enc							
30419 Rev 1 	72 ENG1 Eff: 26-Feb-2016 Complied With	Combustion Chamber Liner - Replacement						RE (-)		Category 7		
					Mos	30-Dec-2021						
					Hrs							
					Enc							
30419 Rev 1 	72 ENG2 Eff: 26-Feb-2016 Complied With	Combustion Chamber Liner - Replacement						RE (-)		Category 7		
					Mos	31-Dec-2021						
					Hrs							
					Enc							
30420 	72 ENG1 Complied With	Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6		
					Mos	30-Dec-2021						
					Hrs							
					Enc							
30420 	72 ENG2 Complied With	Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6		
					Mos	31-Dec-2021						
					Hrs							
					Enc							
30420 Rev 1 	72 ENG1 Complied With	Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6		
					Mos	30-Dec-2021						
					Hrs							
					Enc							
30420 Rev 1 	72 ENG2 Complied With	Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6		
					Mos	31-Dec-2021						
					Hrs							
					Enc							
30420 Rev 2 	72 ENG1 Complied With	Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6		
					Mos	30-Dec-2021						
					Hrs							
					Enc							





























Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30420 Rev 2	72 ENG2 Complied With	Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6	
						Mos	31-Dec-2021				
						Hrs					
30420 Rev 3	72 ENG1 Complied With	Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6	
						Mos	30-Dec-2021				
						Hrs					
30420 Rev 3	72 ENG2 Complied With	Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6	
						Mos	31-Dec-2021				
						Hrs					
30420 Rev 4	72 ENG1 Eff: 18-Jun-2014 Complied With	Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6	
						Mos	30-Dec-2021				
						Hrs					
30420 Rev 4	72 ENG2 Eff: 18-Jun-2014 Complied With	Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6	
						Mos	31-Dec-2021				
						Hrs					
30420 Rev 5	72 ENG1 Eff: 20-Apr-2018 Complied With (AVG MAN HRS: 4)	Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6	
						Mos	30-Dec-2021				
						Hrs					
30420 Rev 5	72 ENG2 Eff: 20-Apr-2018 Complied With (AVG MAN HRS: 4)	Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6	
						Mos	31-Dec-2021				
						Hrs					
30420 Rev 6	72 ENG1 Eff: 16-Jul-2020 Complied With (AVG MAN HRS: 4)	Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6	
						Mos	30-Dec-2021				
						Hrs					
30420 Rev 6	72 ENG2 Eff: 16-Jul-2020 Complied With (AVG MAN HRS: 4)	Replacement Intercompressor Bleed Valve/Servo-Valve						RE (-)		Category 3, Category 6	
						Mos	31-Dec-2021				
						Hrs					
30423	72 ENG1 Complied With	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
						Mos	30-Dec-2021				
						Hrs					
30423	72 ENG2 Complied With	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
						Mos	31-Dec-2021				
						Hrs					
30423 Rev 1	72 ENG1 Eff: 17-Sep-2012 Complied With	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
						Mos	30-Dec-2021				
						Hrs					
30423 Rev 1	72 ENG2 Eff: 17-Sep-2012 Complied With	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
						Mos	31-Dec-2021				
						Hrs					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30425		No. 4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
30425		No. 4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
30425 Rev 1		No. 4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
30425 Rev 1		No. 4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
30425 Rev 2		No. 4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
30425 Rev 2		No. 4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
30425 Rev 3		No. 4 Bearing Carbon Seal - Replacement						T (A/R)		Category 10	
	72 ENG1					Mos					
	Eff: 23-Oct-2013					Hrs					
						Enc					
30425 Rev 3		No. 4 Bearing Carbon Seal - Replacement						T (A/R)		Category 10	
	72 ENG2					Mos					
	Eff: 23-Oct-2013					Hrs					
						Enc					
30426		Fan Case Assembly - Replacement						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 08-Jul-2011 Complied With					Hrs					
						Enc					
30426		Fan Case Assembly - Replacement						T (A/R)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 08-Jul-2011 Complied With					Hrs					
						Enc					
30427		Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
30427		Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
30427 Rev 1		Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					














Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>30427 Rev 1</b>	<b>Replacement/Modification of Intermediate Case Assembly</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30427 Rev 2</b>	<b>Replacement/Modification of Intermediate Case Assembly</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30427 Rev 2</b>	<b>Replacement/Modification of Intermediate Case Assembly</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30427 Rev 3</b>	<b>Intermediate Case Assembly - Replacement/Modification</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 13-Mar-2013 Complied With					Hrs					
					Enc					
<b>30427 Rev 3</b>	<b>Intermediate Case Assembly - Replacement/Modification</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 13-Mar-2013 Complied With					Hrs					
					Enc					
<b>30427 Rev 4</b>	<b>Replacement/Modification of Intermediate Case Assembly</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 06-Nov-2018 Complied With					Hrs					
(AVG MAN HRS: 3)					Enc					
<b>30427 Rev 4</b>	<b>Replacement/Modification of Intermediate Case Assembly</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 06-Nov-2018 Complied With					Hrs					
(AVG MAN HRS: 3)					Enc					
<b>30428</b>	<b>Replacement Fuel Manifold System Interface</b>						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30428</b>	<b>Replacement Fuel Manifold System Interface</b>						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30428 Rev 1</b>	<b>Replacement Fuel Manifold System Interface</b>						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30428 Rev 1</b>	<b>Replacement Fuel Manifold System Interface</b>						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30428 Rev 2</b>	<b>Replacement Fuel Manifold System Interface</b>						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30428 Rev 2</b>	<b>Replacement Fuel Manifold System Interface</b>						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30428 Rev 3</b>		<b>Replacement Fuel Manifold System Interface</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30428 Rev 3</b>		<b>Replacement Fuel Manifold System Interface</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30428 Rev 4</b>		<b>Replacement Fuel Manifold System Interface</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 03-May-2013 Complied With					Hrs					
						Enc					
<b>30428 Rev 4</b>		<b>Replacement Fuel Manifold System Interface</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 03-May-2013 Complied With					Hrs					
						Enc					
<b>30428 Rev 5</b>		<b>Replacement Fuel Manifold System Interface</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 19-Apr-2017 Complied With					Hrs					
	(AVG MAN HRS: 16)					Enc					
<b>30428 Rev 5</b>		<b>Replacement Fuel Manifold System Interface</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 19-Apr-2017 Complied With					Hrs					
	(AVG MAN HRS: 16)					Enc					
<b>30428 Rev 6</b>		<b>Replacement Fuel Manifold System Interface</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 08-Feb-2019 Complied With					Hrs					
	(AVG MAN HRS: 16)					Enc					
<b>30428 Rev 6</b>		<b>Replacement Fuel Manifold System Interface</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 08-Feb-2019 Complied With					Hrs					
	(AVG MAN HRS: 16)					Enc					
<b>30429</b>		<b>Intermediate Case Assembly - Replacement/Modification</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30429</b>		<b>Intermediate Case Assembly - Replacement/Modification</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30429 Rev 1</b>		<b>Intermediate Case Assembly - Replacement/Modification</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30429 Rev 1</b>		<b>Intermediate Case Assembly - Replacement/Modification</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30429 Rev 2</b>		<b>Intermediate Case Assembly - Replacement/Modification</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					














Task No	Description										Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining		
<b>30429 Rev 2</b>	<b>Intermediate Case Assembly - Replacement/Modification</b>						RE (-)		Category 6			
 72 ENG2	Complied With					Mos	31-Dec-2021					
						Hrs						
						Enc						
<b>30429 Rev 3</b>	<b>Intermediate Case Assembly - Replacement/Modification</b>						RE (-)		Category 6			
 72 ENG1	Eff: 22-Jun-2015 Complied With					Mos	30-Dec-2021					
						Hrs						
						Enc						
<b>30429 Rev 3</b>	<b>Intermediate Case Assembly - Replacement/Modification</b>						RE (-)		Category 6			
 72 ENG2	Eff: 22-Jun-2015 Complied With					Mos	31-Dec-2021					
						Hrs						
						Enc						
<b>30429 Rev 4</b>	<b>Intermediate Case Assembly - Replacement/Modification</b>						RE (-)		Category 6			
 72 ENG1	Eff: 14-Mar-2016 Complied With					Mos	30-Dec-2021					
						Hrs						
						Enc						
<b>30429 Rev 4</b>	<b>Intermediate Case Assembly - Replacement/Modification</b>						RE (-)		Category 6			
 72 ENG2	Eff: 14-Mar-2016 Complied With					Mos	31-Dec-2021					
						Hrs						
						Enc						
<b>30429 Rev 5</b>	<b>Replacement/Modification of Intermediate Case Assembly</b>						RE (-)		Category 6			
 72 ENG1	Eff: 10-Aug-2016 Complied With					Mos	30-Dec-2021					
						Hrs						
						Enc						
<b>30429 Rev 5</b>	<b>Replacement/Modification of Intermediate Case Assembly</b>						RE (-)		Category 6			
 72 ENG2	Eff: 10-Aug-2016 Complied With					Mos	31-Dec-2021					
						Hrs						
						Enc						
<b>30429 Rev 6</b>	<b>Replacement/Modification of Intermediate Case Assembly</b>						RE (-)		Category 6			
 72 ENG1	Eff: 02-Aug-2017 Complied With					Mos	30-Dec-2021					
						Hrs						
						Enc						
<b>30429 Rev 6</b>	<b>Replacement/Modification of Intermediate Case Assembly</b>						RE (-)		Category 6			
 72 ENG2	Eff: 02-Aug-2017 Complied With					Mos	31-Dec-2021					
						Hrs						
						Enc						
<b>30432</b>	<b>Plain Seal Accessory Gearbox - Replacement</b>						RE (-)		Category 7			
 72 ENG1	Complied With					Mos	30-Dec-2021					
						Hrs						
						Enc						
<b>30432</b>	<b>Plain Seal Accessory Gearbox - Replacement</b>						RE (-)		Category 7			
 72 ENG2	Complied With					Mos	31-Dec-2021					
						Hrs						
						Enc						
<b>30432 Rev 1</b>	<b>Plain Seal Accessory Gearbox - Replacement</b>						RE (-)		Category 7			
 72 ENG1	Eff: 12-May-2011 Complied With					Mos	30-Dec-2021					
						Hrs						
						Enc						
<b>30432 Rev 1</b>	<b>Plain Seal Accessory Gearbox - Replacement</b>						RE (-)		Category 7			
 72 ENG2	Eff: 12-May-2011 Complied With					Mos	31-Dec-2021					
						Hrs						
						Enc						














Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30434</b>		<b>Electronic Engine Control / Replacement-Modification</b>						RE (-)		Category 10	
	72 ENG1	Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
<b>30434</b>		<b>Electronic Engine Control / Replacement-Modification</b>						RE (-)		Category 10	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
<b>30434 Rev 1</b>		<b>Electronic Engine Control / Replacement-Modification</b>						RE (-)		Category 10	
	72 ENG1	Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
<b>30434 Rev 1</b>		<b>Electronic Engine Control / Replacement-Modification</b>						RE (-)		Category 10	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
<b>30434 Rev 2</b>		<b>Electronic Engine Control / Replacement-Modification</b>						RE (-)		Category 10	
	72 ENG1	Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
<b>30434 Rev 2</b>		<b>Electronic Engine Control / Replacement-Modification</b>						RE (-)		Category 10	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
<b>30434 Rev 3</b>		<b>Electronic Engine Control / Replacement-Modification</b>						RE (-)		Category 10	
	72 ENG1	Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
<b>30434 Rev 3</b>		<b>Electronic Engine Control / Replacement-Modification</b>						RE (-)		Category 10	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
<b>30434 Rev 4</b>		<b>Electronic Engine Control / Replacement-Modification</b>						RE (-)		Category 10	
	72 ENG1	Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
<b>30434 Rev 4</b>		<b>Electronic Engine Control / Replacement-Modification</b>						RE (-)		Category 10	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
<b>30434 Rev 5</b>		<b>Electronic Engine Control / Replacement-Modification</b>						RE (-)		Category 10	
	72 ENG1	Eff: 15-Jul-2015 Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
<b>30434 Rev 5</b>		<b>Electronic Engine Control / Replacement-Modification</b>						RE (-)		Category 10	
	72 ENG2	Eff: 15-Jul-2015 Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
<b>30436</b>		<b>LPT 2nd Stage Vane Assembly - Replacement/Modification</b>						RE (-)		Category 7	
	72 ENG1	Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				





Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30436	72 ENG2 Complied With	LPT 2nd Stage Vane Assembly - Replacement/Modification						RE (-)		Category 7	
						Mos	31-Dec-2021				
						Hrs					
30436 Rev 1	72 ENG1 Complied With	LPT 2nd Stage Vane Assembly - Replacement/Modification						RE (-)		Category 7	
						Mos	30-Dec-2021				
						Hrs					
30436 Rev 1	72 ENG2 Complied With	LPT 2nd Stage Vane Assembly - Replacement/Modification						RE (-)		Category 7	
						Mos	31-Dec-2021				
						Hrs					
30436 Rev 2	72 ENG1 Complied With	LPT 2nd Stage Vane Assembly - Replacement/Modification						RE (-)		Category 7	
						Mos	30-Dec-2021				
						Hrs					
30436 Rev 2	72 ENG2 Complied With	LPT 2nd Stage Vane Assembly - Replacement/Modification						RE (-)		Category 7	
						Mos	31-Dec-2021				
						Hrs					
30436 Rev 3	72 ENG1 Eff: 28-Jul-2015 Complied With	LPT 2nd Stage Vane Assembly - Replacement/Modification						RE (-)		Category 7	
						Mos	30-Dec-2021				
						Hrs					
30436 Rev 3	72 ENG2 Eff: 28-Jul-2015 Complied With	LPT 2nd Stage Vane Assembly - Replacement/Modification						RE (-)		Category 7	
						Mos	31-Dec-2021				
						Hrs					
30436 Rev 4	72 ENG1 Eff: 18-Apr-2018 Complied With	Replacement/Modification of LPT 2nd Stage Vane Assembly						RE (-)		Category 7	
						Mos	30-Dec-2021				
						Hrs					
30436 Rev 4	72 ENG2 Eff: 18-Apr-2018 Complied With	Replacement/Modification of LPT 2nd Stage Vane Assembly						RE (-)		Category 7	
						Mos	31-Dec-2021				
						Hrs					
30438	72 ENG1 Complied With	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
						Mos	30-Dec-2021				
						Hrs					
30438	72 ENG2 Complied With	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
						Mos	31-Dec-2021				
						Hrs					
30438 Rev 1	72 ENG1 Complied With	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
						Mos	30-Dec-2021				
						Hrs					
30438 Rev 1	72 ENG2 Complied With	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
						Mos	31-Dec-2021				
						Hrs					














Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>30438 Rev 2</b>	<b>Electronic Engine Control (EEC) - Replacement/Modification</b>						RE (-)		Category 10	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30438 Rev 2</b>	<b>Electronic Engine Control (EEC) - Replacement/Modification</b>						RE (-)		Category 10	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30438 Rev 3</b>	<b>Electronic Engine Control (EEC) - Replacement/Modification</b>						RE (-)		Category 10	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30438 Rev 3</b>	<b>Electronic Engine Control (EEC) - Replacement/Modification</b>						RE (-)		Category 10	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30438 Rev 4</b>	<b>Electronic Engine Control (EEC) - Replacement/Modification</b>						RE (-)		Category 10	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30438 Rev 4</b>	<b>Electronic Engine Control (EEC) - Replacement/Modification</b>						RE (-)		Category 10	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30438 Rev 5</b>	<b>Electronic Engine Control (EEC) - Replacement/Modification</b>						RE (-)		Category 10	
 72 ENG1					Mos	30-Dec-2021				
Eff: 15-Jul-2015 Complied With					Hrs					
					Enc					
<b>30438 Rev 5</b>	<b>Electronic Engine Control (EEC) - Replacement/Modification</b>						RE (-)		Category 10	
 72 ENG2					Mos	31-Dec-2021				
Eff: 15-Jul-2015 Complied With					Hrs					
					Enc					
<b>30440</b>	<b>Replacement of New or Modified Oil Tank Vent Tube Assembly</b>						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30440</b>	<b>Replacement of New or Modified Oil Tank Vent Tube Assembly</b>						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30440 Rev 1</b>	<b>Replacement of New or Modified Oil Tank Vent Tube Assembly</b>						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30440 Rev 1</b>	<b>Replacement of New or Modified Oil Tank Vent Tube Assembly</b>						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30440 Rev 2</b>	<b>Replacement of New or Modified Oil Tank Vent Tube Assembly</b>						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					












Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>30440 Rev 2</b>	<b>Replacement of New or Modified Oil Tank Vent Tube Assembly</b>						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
<b>30440 Rev 3</b>	<b>Replacement of New or Modified Oil Tank Vent Tube Assembly</b>						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
<b>30440 Rev 3</b>	<b>Replacement of New or Modified Oil Tank Vent Tube Assembly</b>						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
<b>30440 Rev 4</b>	<b>Replacement of New or Modified Oil Tank Vent Tube Assembly</b>						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 07-Oct-2013 Complied With						Hrs				
						Enc				
<b>30440 Rev 4</b>	<b>Replacement of New or Modified Oil Tank Vent Tube Assembly</b>						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 07-Oct-2013 Complied With						Hrs				
						Enc				
<b>30440 Rev 5</b>	<b>Replacement of New or Modified Oil Tank Vent Tube Assembly</b>						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 07-Jan-2016 Complied With						Hrs				
						Enc				
<b>30440 Rev 5</b>	<b>Replacement of New or Modified Oil Tank Vent Tube Assembly</b>						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 07-Jan-2016 Complied With						Hrs				
						Enc				
<b>30440 Rev 6</b>	<b>Replacement of New or Modified Oil Tank Vent Tube Assembly</b>						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 24-May-2019 Complied With						Hrs				
						Enc				
<b>30440 Rev 6</b>	<b>Replacement of New or Modified Oil Tank Vent Tube Assembly</b>						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 24-May-2019 Complied With						Hrs				
						Enc				
<b>30445</b>	<b>Electrical Wiring Harness - Replacement</b>						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 16-Sep-2011 Complied With						Hrs				
						Enc				
<b>30445</b>	<b>Electrical Wiring Harness - Replacement</b>						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 16-Sep-2011 Complied With						Hrs				
						Enc				
<b>30446</b>	<b>Low Pressure Compressor Shaft Balancing Assembly - Replacement</b>						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
<b>30446</b>	<b>Low Pressure Compressor Shaft Balancing Assembly - Replacement</b>						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				














Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30446 Rev 1</b>		<b>Low Pressure Compressor Shaft Balancing Assembly - Replacement</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30446 Rev 1</b>		<b>Low Pressure Compressor Shaft Balancing Assembly - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30446 Rev 2</b>		<b>Low Pressure Compressor Shaft Balancing Assembly - Replacement</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 11-Mar-2014 Complied With					Hrs					
						Enc					
<b>30446 Rev 2</b>		<b>Low Pressure Compressor Shaft Balancing Assembly - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 11-Mar-2014 Complied With					Hrs					
						Enc					
<b>30447</b>		<b>Gas Generator Case - New Coating Modification</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30447</b>		<b>Gas Generator Case - New Coating Modification</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30447 Rev 1</b>		<b>Gas Generator Case - New Coating Modification</b>						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 09-May-2012 Complied With					Hrs					
						Enc					
<b>30447 Rev 1</b>		<b>Gas Generator Case - New Coating Modification</b>						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 09-May-2012 Complied With					Hrs					
						Enc					
<b>30449</b>		<b>HP Turbine Disk Assembly - Replacement</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30449</b>		<b>HP Turbine Disk Assembly - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30449 Rev 1</b>		<b>HP Turbine Disk Assembly - Replacement</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30449 Rev 1</b>		<b>HP Turbine Disk Assembly - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30449 Rev 2</b>		<b>HP Turbine Disk Assembly - Replacement</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 11-Sep-2015 Complied With					Hrs					
						Enc					














Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30449 Rev 2</b>		<b>HP Turbine Disk Assembly - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 11-Sep-2015 Complied With					Hrs					
						Enc					
<b>30453</b>		<b>No. 4 Carbon Seal - Replacement</b>						RE (-)		Category 6, Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30453</b>		<b>No. 4 Carbon Seal - Replacement</b>						RE (-)		Category 6, Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30453 Rev 1</b>		<b>No. 4 Carbon Seal - Replacement</b>						RE (-)		Category 6, Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 31-Jan-2014 Complied With					Hrs					
						Enc					
<b>30453 Rev 1</b>		<b>No. 4 Carbon Seal - Replacement</b>						RE (-)		Category 6, Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 31-Jan-2014 Complied With					Hrs					
						Enc					
<b>30453 Rev 2</b>		<b>No. 4 Carbon Seal - Replacement</b>						RE (-)		Category 6, Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 23-Dec-2015 Complied With					Hrs					
						Enc					
<b>30453 Rev 2</b>		<b>No. 4 Carbon Seal - Replacement</b>						RE (-)		Category 6, Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 23-Dec-2015 Complied With					Hrs					
						Enc					
<b>30453 Rev 3</b>		<b>No. 4 Carbon Seal - Replacement</b>						RE (-)		Category 6, Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 11-Aug-2017 Complied With					Hrs					
						Enc					
<b>30453 Rev 3</b>		<b>No. 4 Carbon Seal - Replacement</b>						RE (-)		Category 6, Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 11-Aug-2017 Complied With					Hrs					
						Enc					
<b>30463</b>		<b>Accessory Drive Lip Seal - Replacement</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30463</b>		<b>Accessory Drive Lip Seal - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30463 Rev 1</b>		<b>Accessory Drive Lip Seal - Replacement</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 20-Nov-2012 Complied With					Hrs					
						Enc					
<b>30463 Rev 1</b>		<b>Accessory Drive Lip Seal - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 20-Nov-2012 Complied With					Hrs					
						Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30463 Rev 2</b>		<b>Replacement of Accessory Drive Lip Seal</b>						RE (-)		Category 7	
	72 ENG1						Mos	30-Dec-2021			
	Eff: 18-Aug-2016 Complied With						Hrs				
	(AVG MAN HRS: 1)						Enc				
<b>30463 Rev 2</b>		<b>Replacement of Accessory Drive Lip Seal</b>						RE (-)		Category 7	
	72 ENG2						Mos	31-Dec-2021			
	Eff: 18-Aug-2016 Complied With						Hrs				
	(AVG MAN HRS: 1)						Enc				
<b>30465</b>		<b>Fuel Manifold Tubes - Replacement</b>						RE (-)		Category 7	
	72 ENG1						Mos	30-Dec-2021			
	Complied With						Hrs				
							Enc				
<b>30465</b>		<b>Fuel Manifold Tubes - Replacement</b>						RE (-)		Category 7	
	72 ENG2						Mos	31-Dec-2021			
	Complied With						Hrs				
							Enc				
<b>30465 Rev 1</b>		<b>Fuel Manifold Tubes - Replacement</b>						RE (-)		Category 7	
	72 ENG1						Mos	30-Dec-2021			
	Eff: 26-Aug-2014 Complied With						Hrs				
							Enc				
<b>30465 Rev 1</b>		<b>Fuel Manifold Tubes - Replacement</b>						RE (-)		Category 7	
	72 ENG2						Mos	31-Dec-2021			
	Eff: 26-Aug-2014 Complied With						Hrs				
							Enc				
<b>30466</b>		<b>Replacement/Modification of 2nd Stage Turbine Vane Assy</b>						RE (-)		Category 7	
	72 ENG1						Mos	30-Dec-2021			
	Eff: 19-Sep-2012 Complied With						Hrs				
							Enc				
<b>30466</b>		<b>Replacement/Modification of 2nd Stage Turbine Vane Assy</b>						RE (-)		Category 7	
	72 ENG2						Mos	31-Dec-2021			
	Eff: 19-Sep-2012 Complied With						Hrs				
							Enc				
<b>30466 Rev 1</b>		<b>Replacement/Modification of 2nd Stage Turbine Vane Assy</b>						RE (-)		Category 7	
	72 ENG1						Mos	30-Dec-2021			
	Eff: 02-Mar-2016 Complied With						Hrs				
							Enc				
<b>30466 Rev 1</b>		<b>Replacement/Modification of 2nd Stage Turbine Vane Assy</b>						RE (-)		Category 7	
	72 ENG2						Mos	31-Dec-2021			
	Eff: 02-Mar-2016 Complied With						Hrs				
							Enc				
<b>30466 Rev 2</b>		<b>Replacement/Modification of 2nd Stage Turbine Vane Assy</b>						RE (-)		Category 7	
	72 ENG1						Mos	30-Dec-2021			
	Eff: 12-Jul-2018 Complied With						Hrs				
							Enc				
<b>30466 Rev 2</b>		<b>Replacement/Modification of 2nd Stage Turbine Vane Assy</b>						RE (-)		Category 7	
	72 ENG2						Mos	31-Dec-2021			
	Eff: 12-Jul-2018 Complied With						Hrs				
							Enc				
<b>30470</b>		<b>Data Collection Unit - Replacement</b>						RE (-)		Category 7	
	72 ENG1						Mos	30-Dec-2021			
	Complied With						Hrs				
							Enc				














Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>30470</b>	<b>Data Collection Unit - Replacement</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30470 Rev 1</b>	<b>Data Collection Unit - Replacement</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 31-Aug-2015	Complied With				Hrs					
					Enc					
<b>30470 Rev 1</b>	<b>Data Collection Unit - Replacement</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 31-Aug-2015	Complied With				Hrs					
					Enc					
<b>30474</b>	<b>Replacement of Electrical Wiring Harness</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 30-Jul-2013	Complied With				Hrs					
					Enc					
<b>30474</b>	<b>Replacement of Electrical Wiring Harness</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 30-Jul-2013	Complied With				Hrs					
					Enc					
<b>30474 Rev 1</b>	<b>Replacement of Electrical Wiring Harness</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 10-Nov-2015	Complied With				Hrs					
(AVG MAN HRS: 1.5)					Enc					
<b>30474 Rev 1</b>	<b>Replacement of Electrical Wiring Harness</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 10-Nov-2015	Complied With				Hrs					
(AVG MAN HRS: 1.5)					Enc					
<b>30475</b>	<b>Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly - Replacement</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30475</b>	<b>Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly - Replacement</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30475 Part A</b>	<b>Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Fuel Control Drive Gearshaft (Category 7)</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30475 Part A</b>	<b>Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Fuel Control Drive Gearshaft (Category 7)</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30475 Part B</b>	<b>Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Accessory Drive Gearshaft (Category 7)</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					














Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30475	Part B	Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Accessory Drive Gearshaft (Category 7)						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
30475	Rev 1	Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly - Replacement						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
30475	Rev 1	Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly - Replacement						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
30475	Rev 1 Part A	Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Fuel Control Drive Gearshaft (Category 7)						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
30475	Rev 1 Part A	Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Fuel Control Drive Gearshaft (Category 7)						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
30475	Rev 1 Part B	Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Accessory Drive Gearshaft (Category 7)						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
30475	Rev 1 Part B	Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Accessory Drive Gearshaft (Category 7)						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
30475	Rev 2	Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly - Replacement						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 18-Dec-2013	Complied With				Hrs					
						Enc					
30475	Rev 2	Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly - Replacement						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 18-Dec-2013	Complied With				Hrs					
						Enc					
30475	Rev 2 Part A	Replacement of Fuel Control Drive Spur Gearshaft Assembly						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
30475	Rev 2 Part A	Replacement of Fuel Control Drive Spur Gearshaft Assembly						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
30475	Rev 2 Part B	Replacement of Accessory Drive Gearshaft Assembly						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>30475 Rev 2 Part B</b>	<b>Replacement of Accessory Drive Gearshaft Assembly</b>						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
<b>30475 Rev 3</b>	<b>Replacement of Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly</b>						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 18-Aug-2016 Complied With						Hrs				
						Enc				
<b>30475 Rev 3</b>	<b>Replacement of Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly</b>						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 18-Aug-2016 Complied With						Hrs				
						Enc				
<b>30475 Rev 3 Part A</b>	<b>Replacement of Fuel Control Drive Spur Gearshaft Assembly</b>						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 18-Aug-2016 Complied With						Hrs				
						Enc				
<b>30475 Rev 3 Part A</b>	<b>Replacement of Fuel Control Drive Spur Gearshaft Assembly</b>						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 18-Aug-2016 Complied With						Hrs				
						Enc				
<b>30475 Rev 3 Part B</b>	<b>Replacement of Accessory Drive Gearshaft Assembly</b>						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 18-Aug-2016 Complied With						Hrs				
						Enc				
<b>30475 Rev 3 Part B</b>	<b>Replacement of Accessory Drive Gearshaft Assembly</b>						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 18-Aug-2016 Complied With						Hrs				
						Enc				
<b>30478</b>	<b>Electronic Engine Control (EEC) - Replacement/Field Modification</b>						RE (-)		Category 3	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
<b>30478</b>	<b>Electronic Engine Control (EEC) - Replacement/Field Modification</b>						RE (-)		Category 3	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
<b>30478 Rev 1</b>	<b>Electronic Engine Control (EEC) - Replacement/Field Modification</b>						RE (-)		Category 3	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
<b>30478 Rev 1</b>	<b>Electronic Engine Control (EEC) - Replacement/Field Modification</b>						RE (-)		Category 3	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
<b>30478 Rev 2</b>	<b>Electronic Engine Control (EEC) - Replacement/Field Modification</b>						RE (-)		Category 3	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
<b>30478 Rev 2</b>	<b>Electronic Engine Control (EEC) - Replacement/Field Modification</b>						RE (-)		Category 3	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30478 Rev 3</b>		<b>Electronic Engine Control (EEC) - Replacement/Field Modification</b>						RE (-)		Category 3	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 15-Jul-2015 Complied With					Hrs					
						Enc					
<b>30478 Rev 3</b>		<b>Electronic Engine Control (EEC) - Replacement/Field Modification</b>						RE (-)		Category 3	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 15-Jul-2015 Complied With					Hrs					
						Enc					
<b>30479</b>		<b>No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement</b>						RE (-)		Category 5	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30479</b>		<b>No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement</b>						RE (-)		Category 5	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30479 Rev 1</b>		<b>No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement</b>						RE (-)		Category 5	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30479 Rev 1</b>		<b>No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement</b>						RE (-)		Category 5	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30479 Rev 2</b>		<b>No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement</b>						RE (-)		Category 5	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30479 Rev 2</b>		<b>No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement</b>						RE (-)		Category 5	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30479 Rev 3</b>		<b>No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement</b>						RE (-)		Category 5	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 22-Jun-2015 Complied With					Hrs					
						Enc					
<b>30479 Rev 3</b>		<b>No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement</b>						RE (-)		Category 5	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 22-Jun-2015 Complied With					Hrs					
						Enc					
<b>30479 Rev 4</b>		<b>No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement</b>						RE (-)		Category 5	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 04-Jan-2016 Complied With					Hrs					
						Enc					
<b>30479 Rev 4</b>		<b>No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement</b>						RE (-)		Category 5	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 04-Jan-2016 Complied With					Hrs					
						Enc					
<b>30479 Rev 5</b>		<b>No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement</b>						RE (-)		Category 5	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 21-Jan-2016 Complied With					Hrs					
						Enc					





























Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30479 Rev 5</b>		<b>No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement</b>						RE (-)		Category 5	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 21-Jan-2016 Complied With					Hrs					
						Enc					
<b>30479 Rev 6</b>		<b>No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement</b>						RE (-)		Category 3	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 20-May-2016 Complied With					Hrs					
						Enc					
<b>30479 Rev 6</b>		<b>No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement</b>						RE (-)		Category 3	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 20-May-2016 Complied With					Hrs					
						Enc					
<b>30480</b>		<b>Rear Outer By-Pass Duct Silver Plated Nuts - Replacement</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 05-Dec-2013 Complied With					Hrs					
						Enc					
<b>30480</b>		<b>Rear Outer By-Pass Duct Silver Plated Nuts - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 05-Dec-2013 Complied With					Hrs					
						Enc					
<b>30481</b>		<b>Fuel Shut-Off Cable - Replacement</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 06-Dec-2013 Complied With					Hrs					
						Enc					
<b>30481</b>		<b>Fuel Shut-Off Cable - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 06-Dec-2013 Complied With					Hrs					
						Enc					
<b>30482</b>		<b>Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection</b>						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
<b>30482</b>		<b>Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection</b>						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
<b>30482 Rev 1</b>		<b>Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection</b>						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
<b>30482 Rev 1</b>		<b>Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection</b>						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
<b>30482 Rev 2</b>		<b>Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection</b>						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
<b>30482 Rev 2</b>		<b>Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection</b>						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					














Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30482 Rev 3</b>	<b>Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection</b>						T (A/R)		Category 10	
 72 ENG1						Mos				
Eff: 22-Oct-2014						Hrs				
						Enc				
<b>30482 Rev 3</b>	<b>Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection</b>						T (A/R)		Category 10	
 72 ENG2						Mos				
Eff: 22-Oct-2014						Hrs				
						Enc				
<b>30483</b>	<b>Combustion Chamber Liner Assembly - Replacement/Modification</b>						RE (-)		Category 10	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
<b>30483</b>	<b>Combustion Chamber Liner Assembly - Replacement/Modification</b>						RE (-)		Category 10	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
<b>30483 Rev 1</b>	<b>Combustion Chamber Liner Assembly - Replacement/Modification</b>						RE (-)		Category 10	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
<b>30483 Rev 1</b>	<b>Combustion Chamber Liner Assembly - Replacement/Modification</b>						RE (-)		Category 10	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
<b>30483 Rev 2</b>	<b>Combustion Chamber Liner Assembly - Replacement/Modification</b>						RE (-)		Category 10	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
<b>30483 Rev 2</b>	<b>Combustion Chamber Liner Assembly - Replacement/Modification</b>						RE (-)		Category 10	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
<b>30483 Rev 3</b>	<b>Combustion Chamber Liner Assembly - Replacement/Modification</b>						RE (-)		Category 10	
 72 ENG1						Mos	30-Dec-2021			
Eff: 22-Oct-2014 Complied With						Hrs				
						Enc				
<b>30483 Rev 3</b>	<b>Combustion Chamber Liner Assembly - Replacement/Modification</b>						RE (-)		Category 10	
 72 ENG2						Mos	31-Dec-2021			
Eff: 22-Oct-2014 Complied With						Hrs				
						Enc				
<b>30485</b>	<b>Rear Outer By-Pass Duct Hardware - Replacement</b>						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 19-Nov-2013 Complied With						Hrs				
						Enc				
<b>30485</b>	<b>Rear Outer By-Pass Duct Hardware - Replacement</b>						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 19-Nov-2013 Complied With						Hrs				
						Enc				
<b>30485 Rev 1</b>	<b>Rear Outer By-Pass Duct Hardware - Replacement</b>						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 31-May-2016 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				













Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30485 Rev 1</b>		<b>Rear Outer By-Pass Duct Hardware - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 31-May-2016 Complied With					Hrs					
	(AVG MAN HRS: 1)					Enc					
<b>30485 Rev 2</b>		<b>Rear Outer By-Pass Duct Hardware - Replacement</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 14-Aug-2017 Complied With					Hrs					
	(AVG MAN HRS: 1)					Enc					
<b>30485 Rev 2</b>		<b>Rear Outer By-Pass Duct Hardware - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 14-Aug-2017 Complied With					Hrs					
	(AVG MAN HRS: 1)					Enc					
<b>30487</b>		<b>Fuel Control Drive and Accessory Drive Lip Seal - Replacement</b>						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
<b>30487</b>		<b>Fuel Control Drive and Accessory Drive Lip Seal - Replacement</b>						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
<b>30487 Rev 1</b>		<b>Fuel Control Drive and Accessory Drive Lip Seal - Replacement</b>						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
<b>30487 Rev 1</b>		<b>Fuel Control Drive and Accessory Drive Lip Seal - Replacement</b>						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
<b>30487 Rev 2</b>		<b>Fuel Control Drive and Accessory Drive Lip Seal - Replacement</b>						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
<b>30487 Rev 2</b>		<b>Fuel Control Drive and Accessory Drive Lip Seal - Replacement</b>						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
<b>30487 Rev 3</b>		<b>Fuel Control Drive and Accessory Drive Lip Seal - Replacement</b>						T (A/R)		Category 10	
	72 ENG1					Mos					
	Eff: 09-Oct-2014					Hrs					
						Enc					
<b>30487 Rev 3</b>		<b>Fuel Control Drive and Accessory Drive Lip Seal - Replacement</b>						T (A/R)		Category 10	
	72 ENG2					Mos					
	Eff: 09-Oct-2014					Hrs					
						Enc					
<b>30491</b>		<b>Combustion Chamber Liner Assembly - Replacement/Modification</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30491</b>		<b>Combustion Chamber Liner Assembly - Replacement/Modification</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30491 Rev 1	72 ENG1 Complied With	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 7	
						Mos	30-Dec-2021				
						Hrs					
30491 Rev 1	72 ENG2 Complied With	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 7	
						Mos	31-Dec-2021				
						Hrs					
30491 Rev 2	72 ENG1 Eff: 27-Jul-2015 Complied With	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 7	
						Mos	30-Dec-2021				
						Hrs					
30491 Rev 2	72 ENG2 Eff: 27-Jul-2015 Complied With	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 7	
						Mos	31-Dec-2021				
						Hrs					
30492	72 ENG1 Complied With	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
						Mos	30-Dec-2021				
						Hrs					
30492	72 ENG2 Complied With	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
						Mos	31-Dec-2021				
						Hrs					
30492 Rev 1	72 ENG1 Complied With	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
						Mos	30-Dec-2021				
						Hrs					
30492 Rev 1	72 ENG2 Complied With	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
						Mos	31-Dec-2021				
						Hrs					
30492 Rev 2	72 ENG1 Complied With	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
						Mos	30-Dec-2021				
						Hrs					
30492 Rev 2	72 ENG2 Complied With	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
						Mos	31-Dec-2021				
						Hrs					
30492 Rev 3	72 ENG1 Eff: 27-Nov-2014 Complied With	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
						Mos	30-Dec-2021				
						Hrs					
30492 Rev 3	72 ENG2 Eff: 27-Nov-2014 Complied With	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
						Mos	31-Dec-2021				
						Hrs					
30492 Rev 4	72 ENG1 Eff: 10-Jan-2017 Complied With (AVG MAN HRS: 1.5)	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
						Mos	30-Dec-2021				
						Hrs					













Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>30492 Rev 4</b>	<b>Combustion Chamber Liner - Replacement / Modification</b>						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
	Eff: 10-Jan-2017 Complied With					Hrs				
	(AVG MAN HRS: 1.5)					Enc				
<b>30495</b>	<b>Accessory Gearbox Cover Bolt Torquing Procedure - Modification</b>						RE (-)		Category 10	
 72 ENG1						Mos	30-Dec-2021			
	Eff: 15-Sep-2014 Complied With					Hrs				
						Enc				
<b>30495</b>	<b>Accessory Gearbox Cover Bolt Torquing Procedure - Modification</b>						RE (-)		Category 10	
 72 ENG2						Mos	31-Dec-2021			
	Eff: 15-Sep-2014 Complied With					Hrs				
						Enc				
<b>30495 Rev 1</b>	<b>Accessory Gearbox Cover Bolt Torquing Procedure - Modification</b>						RE (-)		Category 10	
 72 ENG1						Mos	30-Dec-2021			
	Eff: 13-Oct-2016 Complied With					Hrs				
	(AVG MAN HRS: 1.5)					Enc				
<b>30495 Rev 1</b>	<b>Accessory Gearbox Cover Bolt Torquing Procedure - Modification</b>						RE (-)		Category 10	
 72 ENG2						Mos	31-Dec-2021			
	Eff: 13-Oct-2016 Complied With					Hrs				
	(AVG MAN HRS: 1.5)					Enc				
<b>30496</b>	<b>Replacement/Modification of Second Stage Turbine Vane</b>						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
	Eff: 12-Aug-2014 Complied With					Hrs				
						Enc				
<b>30496</b>	<b>Replacement/Modification of Second Stage Turbine Vane</b>						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
	Eff: 12-Aug-2014 Complied With					Hrs				
						Enc				
<b>30496 Rev 1</b>	<b>Replacement/Modification of Second Stage Turbine Vane</b>						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
	Eff: 01-Oct-2018 Complied With					Hrs				
	(AVG MAN HRS: 1.5)					Enc				
<b>30496 Rev 1</b>	<b>Replacement/Modification of Second Stage Turbine Vane</b>						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
	Eff: 01-Oct-2018 Complied With					Hrs				
	(AVG MAN HRS: 1.5)					Enc				
<b>30498</b>	<b>Intermediate Case Assembly - Replacement/Modification</b>						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
	Eff: 12-Sep-2014 Complied With					Hrs				
						Enc				
<b>30498</b>	<b>Intermediate Case Assembly - Replacement/Modification</b>						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
	Eff: 12-Sep-2014 Complied With					Hrs				
						Enc				
<b>30498 Rev 1</b>	<b>Intermediate Case Assembly - Replacement/Modification</b>						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
	Eff: 16-Nov-2016 Complied With					Hrs				
	(AVG MAN HRS: 1.5)					Enc				
<b>30498 Rev 1</b>	<b>Intermediate Case Assembly - Replacement/Modification</b>						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
	Eff: 16-Nov-2016 Complied With					Hrs				
	(AVG MAN HRS: 1.5)					Enc				














Task No	Description										Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining		
<b>30498 Rev 2</b>	<b>Replacement/Modification of Intermediate Case Assembly</b>						RE (-)		Category 7			
 72 ENG1						Mos	30-Dec-2021					
Eff: 10-Aug-2017 Complied With						Hrs						
(AVG MAN HRS: 1.5)						Enc						
<b>30498 Rev 2</b>	<b>Replacement/Modification of Intermediate Case Assembly</b>						RE (-)		Category 7			
 72 ENG2						Mos	31-Dec-2021					
Eff: 10-Aug-2017 Complied With						Hrs						
(AVG MAN HRS: 1.5)						Enc						
<b>30498 Rev 3</b>	<b>Replacement/Modification of Intermediate Case Assembly</b>						RE (-)		Category 7			
 72 ENG1						Mos	30-Dec-2021					
Eff: 20-Sep-2017 Complied With						Hrs						
(AVG MAN HRS: 1.5)						Enc						
<b>30498 Rev 3</b>	<b>Replacement/Modification of Intermediate Case Assembly</b>						RE (-)		Category 7			
 72 ENG2						Mos	31-Dec-2021					
Eff: 20-Sep-2017 Complied With						Hrs						
(AVG MAN HRS: 1.5)						Enc						
<b>30502</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement</b>						RE (-)		Category 7			
 72 ENG1						Mos	30-Dec-2021					
Complied With						Hrs						
						Enc						
<b>30502</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement</b>						RE (-)		Category 7			
 72 ENG2						Mos	31-Dec-2021					
Complied With						Hrs						
						Enc						
<b>30502 Rev 1</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement</b>						RE (-)		Category 7			
 72 ENG1						Mos	30-Dec-2021					
Complied With						Hrs						
						Enc						
<b>30502 Rev 1</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement</b>						RE (-)		Category 7			
 72 ENG2						Mos	31-Dec-2021					
Complied With						Hrs						
						Enc						
<b>30502 Rev 2</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement</b>						RE (-)		Category 7			
 72 ENG1						Mos	30-Dec-2021					
Eff: 02-Oct-2015 Complied With						Hrs						
						Enc						
<b>30502 Rev 2</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement</b>						RE (-)		Category 7			
 72 ENG2						Mos	31-Dec-2021					
Eff: 02-Oct-2015 Complied With						Hrs						
						Enc						
<b>30502 Rev 2 Part A</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Fuel Control Gearshaft Seal</b>						RE (-)		Category 7			
 72 ENG1						Mos	30-Dec-2021					
Complied With						Hrs						
						Enc						
<b>30502 Rev 2 Part A</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Fuel Control Gearshaft Seal</b>						RE (-)		Category 7			
 72 ENG2						Mos	31-Dec-2021					
Complied With						Hrs						
						Enc						
<b>30502 Rev 2 Part B</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Accessory Gearshaft Seal</b>						RE (-)		Category 7			
 72 ENG1						Mos	30-Dec-2021					
Complied With						Hrs						
						Enc						













Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>30502 Rev 2 Part B</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Accessory Gearshaft Seal</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
<b>30502 Rev 3</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 04-Jan-2016 Complied With					Hrs					
(AVG MAN HRS: 1)					Enc					
<b>30502 Rev 3</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 04-Jan-2016 Complied With					Hrs					
(AVG MAN HRS: 1)					Enc					
<b>30502 Rev 3 Part A</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Fuel Control Gearshaft Seal</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 04-Jan-2016 Complied With					Hrs					
					Enc					
<b>30502 Rev 3 Part A</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Fuel Control Gearshaft Seal</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 04-Jan-2016 Complied With					Hrs					
					Enc					
<b>30502 Rev 3 Part B</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Accessory Gearshaft Seal</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 04-Jan-2016 Complied With					Hrs					
					Enc					
<b>30502 Rev 3 Part B</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Accessory Gearshaft Seal</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 04-Jan-2016 Complied With					Hrs					
					Enc					
<b>30502 Rev 4</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 20-Oct-2016 Complied With					Hrs					
(AVG MAN HRS: 1)					Enc					
<b>30502 Rev 4</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 20-Oct-2016 Complied With					Hrs					
(AVG MAN HRS: 1)					Enc					
<b>30502 Rev 4 Part A</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Fuel Control Gearshaft Seal</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 20-Oct-2016 Complied With					Hrs					
(AVG MAN HRS: 1)					Enc					
<b>30502 Rev 4 Part A</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Fuel Control Gearshaft Seal</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 20-Oct-2016 Complied With					Hrs					
(AVG MAN HRS: 1)					Enc					
<b>30502 Rev 4 Part B</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Accessory Gearshaft Seal</b>						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 20-Oct-2016 Complied With					Hrs					
(AVG MAN HRS: 1)					Enc					
<b>30502 Rev 4 Part B</b>	<b>Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Accessory Gearshaft Seal</b>						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 20-Oct-2016 Complied With					Hrs					
(AVG MAN HRS: 1)					Enc					












Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30504</b>		<b>Replacement of Fuel/Oil Heat Exchanger</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30504</b>		<b>Replacement of Fuel/Oil Heat Exchanger</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30504 Rev 1</b>		<b>Replacement of Fuel/Oil Heat Exchanger</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 25-Sep-2015 Complied With					Hrs					
						Enc					
<b>30504 Rev 1</b>		<b>Replacement of Fuel/Oil Heat Exchanger</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 25-Sep-2015 Complied With					Hrs					
						Enc					
<b>30505</b>		<b>Replacement Bleed Off Valve (BOV) Gaskets</b>						RE (-)		Category 3	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30505</b>		<b>Replacement Bleed Off Valve (BOV) Gaskets</b>						RE (-)		Category 3	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30505 Rev 1</b>		<b>Replacement Bleed Off Valve (BOV) Gaskets</b>						RE (-)		Category 3	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30505 Rev 1</b>		<b>Replacement Bleed Off Valve (BOV) Gaskets</b>						RE (-)		Category 3	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
<b>30505 Rev 2</b>		<b>Replacement Bleed Off Valve (BOV) Gaskets</b>						RE (-)		Category 3	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 21-May-2015 Complied With					Hrs					
						Enc					
<b>30505 Rev 2</b>		<b>Replacement Bleed Off Valve (BOV) Gaskets</b>						RE (-)		Category 3	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 21-May-2015 Complied With					Hrs					
						Enc					
<b>30505 Rev 3</b>		<b>Replacement of Bleed Off Valve (BOV) Gaskets</b>						RE (-)		Category 3	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 16-Jul-2020 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30505 Rev 3</b>		<b>Replacement of Bleed Off Valve (BOV) Gaskets</b>						RE (-)		Category 3	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 16-Jul-2020 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					















Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30505 Rev 4</b>		<b>Replacement of Bleed Off Valve (BOV) Gaskets</b>						RE (-)		Category 3	
	72 ENG1	Eff: 16-Nov-2022 Not Applicable (AVG MAN HRS: 1.5) as per engine S/N					Mos	04-Jan-2023			
							Hrs	251:12			
							Enc	171			
<b>30505 Rev 4</b>		<b>Replacement of Bleed Off Valve (BOV) Gaskets</b>						RE (-)		Category 3	
	72 ENG2	Eff: 16-Nov-2022 Not Applicable (AVG MAN HRS: 1.5) as per engine S/N					Mos	08-Aug-2023			
							Hrs	283:31			
							Enc	192			
<b>30506</b>		<b>Fuel Manifold Adapters - Replacement</b>						RE (-)		Category 7	
	72 ENG1	Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
<b>30506</b>		<b>Fuel Manifold Adapters - Replacement</b>						RE (-)		Category 7	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
<b>30506 Rev 1</b>		<b>Fuel Manifold Adapters - Replacement</b>						RE (-)		Category 7	
	72 ENG1	Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
<b>30506 Rev 1</b>		<b>Fuel Manifold Adapters - Replacement</b>						RE (-)		Category 7	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
<b>30506 Rev 2</b>		<b>Fuel Manifold Adapters - Replacement</b>						RE (-)		Category 7	
	72 ENG1	Eff: 11-Sep-2015 Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
<b>30506 Rev 2</b>		<b>Fuel Manifold Adapters - Replacement</b>						RE (-)		Category 7	
	72 ENG2	Eff: 11-Sep-2015 Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
<b>30508</b>		<b>Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators</b>						RE (-)		Category 7	
	72 ENG1	Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
<b>30508</b>		<b>Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators</b>						RE (-)		Category 7	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
<b>30508 Rev 1</b>		<b>Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators</b>						RE (-)		Category 7	
	72 ENG1	Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
<b>30508 Rev 1</b>		<b>Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators</b>						RE (-)		Category 7	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>30508 Rev 2</b>	<b>Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators</b>						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 14-May-2015 Complied With						Hrs				
						Enc				
<b>30508 Rev 2</b>	<b>Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators</b>						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 14-May-2015 Complied With						Hrs				
						Enc				
<b>30508 Rev 3</b>	<b>Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators</b>						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 06-Dec-2018 Complied With						Hrs				
(AVG MAN HRS: 5)						Enc				
<b>30508 Rev 3</b>	<b>Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators</b>						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 06-Dec-2018 Complied With						Hrs				
(AVG MAN HRS: 5)						Enc				
<b>30508 Rev 4</b>	<b>Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators</b>						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 13-Apr-2020 Complied With						Hrs				
(AVG MAN HRS: 5)						Enc				
<b>30508 Rev 4</b>	<b>Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators</b>						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 13-Apr-2020 Complied With						Hrs				
(AVG MAN HRS: 5)						Enc				
<b>30510</b>	<b>Primary and Secondary Fuel Tube Support Bracket - Replacement</b>						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 29-Jan-2015 Complied With						Hrs				
						Enc				
<b>30510</b>	<b>Primary and Secondary Fuel Tube Support Bracket - Replacement</b>						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 29-Jan-2015 Complied With						Hrs				
						Enc				
<b>30511</b>	<b>AGB Cover Bolts or Nuts - Re-Torquing</b>						T (-)		Category 6	
 72 ENG1						Mos				
Eff: 31-Jul-2015						Hrs				
						Enc				
<b>30511</b>	<b>AGB Cover Bolts or Nuts - Re-Torquing</b>						T (-)		Category 6	
 72 ENG2						Mos				
Eff: 31-Jul-2015						Hrs				
						Enc				
<b>30511 Rev 1</b>	<b>Re-Torquing of AGB Cover Bolts or Nuts</b>						T (-)		Category 6	
 72 ENG1						Mos				
Eff: 14-Jun-2016						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30511 Rev 1</b>	<b>Re-Torquing of AGB Cover Bolts or Nuts</b>						T (-)		Category 6	
 72 ENG2						Mos				
Eff: 14-Jun-2016						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30511 Rev 2</b>	<b>Re-Torquing of AGB Cover Bolts or Nuts</b>						T (A/R)		Category 6	
 72 ENG1						Mos				
Eff: 02-Mar-2021						Hrs				
(AVG MAN HRS: 1.5)						Enc				














Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30511 Rev 2</b>		<b>Re-Torquing of AGB Cover Bolts or Nuts</b>						T (A/R)		Category 6	
	72 ENG2										
	Eff: 02-Mar-2021										
	(AVG MAN HRS: 1.5)										
<b>30516</b>		<b>HP Turbine Seal Rings - Replacement</b>						RE (-)		Category 7	
	72 ENG1										
	Complied With										
<b>30516</b>		<b>HP Turbine Seal Rings - Replacement</b>						RE (-)		Category 7	
	72 ENG2										
	Complied With										
<b>30516 Rev 1</b>		<b>HP Turbine Seal Rings - Replacement</b>						RE (-)		Category 7	
	72 ENG1										
	Complied With										
<b>30516 Rev 1</b>		<b>HP Turbine Seal Rings - Replacement</b>						RE (-)		Category 7	
	72 ENG2										
	Complied With										
<b>30516 Rev 2</b>		<b>HP Turbine Seal Rings - Replacement</b>						RE (-)		Category 7	
	72 ENG1										
	Eff: 22-Jun-2015 Complied With										
<b>30516 Rev 2</b>		<b>HP Turbine Seal Rings - Replacement</b>						RE (-)		Category 7	
	72 ENG2										
	Eff: 22-Jun-2015 Complied With										
<b>30517</b>		<b>Igniter Flange Gaskets - Deletion</b>						RE (-)		Category 6	
	72 ENG1										
	Eff: 09-Apr-2015 Complied With										
<b>30517</b>		<b>Igniter Flange Gaskets - Deletion</b>						RE (-)		Category 6	
	72 ENG2										
	Eff: 09-Apr-2015 Complied With										
<b>30517 Rev 1</b>		<b>Igniter Flange Gaskets - Deletion</b>						RE (-)		Category 6	
	72 ENG1										
	Eff: 05-Jan-2016 Complied With										
	(AVG MAN HRS: 1.5)										
<b>30517 Rev 1</b>		<b>Igniter Flange Gaskets - Deletion</b>						RE (-)		Category 6	
	72 ENG2										
	Eff: 05-Jan-2016 Complied With										
	(AVG MAN HRS: 1.5)										
<b>30518</b>		<b>Turbine Exhaust Case End Cone - Saleability Change</b>						T (A/R)		Category 9	
	72 ENG1										
	Eff: 13-Oct-2017										
<b>30518</b>		<b>Turbine Exhaust Case End Cone - Saleability Change</b>						T (A/R)		Category 9	
	72 ENG2										
	Eff: 13-Oct-2017										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30521</b>		<b>Replacement of Combustion Chamber Liner</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 20-Nov-2015 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30521</b>		<b>Replacement of Combustion Chamber Liner</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 20-Nov-2015 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30521 Rev 1</b>		<b>Replacement of Combustion Chamber Liner</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 18-Dec-2015 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30521 Rev 1</b>		<b>Replacement of Combustion Chamber Liner</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 18-Dec-2015 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30523</b>		<b>Accessory Gearbox Cover Gasket - Replacement</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 07-Aug-2015 Complied With					Hrs					
						Enc					
<b>30523</b>		<b>Accessory Gearbox Cover Gasket - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 07-Aug-2015 Complied With					Hrs					
						Enc					
<b>30523 Rev 1</b>		<b>Accessory Gearbox Cover Gasket - Replacement</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 30-May-2016 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30523 Rev 1</b>		<b>Accessory Gearbox Cover Gasket - Replacement</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 30-May-2016 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30526</b>		<b>Modification of Intermediate Case Assembly</b>						T (-)		Category 6	
	72 ENG1					Mos					
	Eff: 10-Aug-2016					Hrs					
						Enc					
	Note: NOTE: This service bulletin supersedes P&WC SB30429 at overhaul or heavy maintenance where sufficient access to the intermediate case is available.										
<b>30526</b>		<b>Modification of Intermediate Case Assembly</b>						T (-)		Category 6	
	72 ENG2					Mos					
	Eff: 10-Aug-2016					Hrs					
						Enc					
	Note: NOTE: This service bulletin supersedes P&WC SB30429 at overhaul or heavy maintenance where sufficient access to the intermediate case is available.										
<b>30526 Rev 1</b>		<b>Modification of Intermediate Case Assembly</b>						T (A/R)		Category 6	
	72 ENG1					Mos					
	Eff: 21-Dec-2021					Hrs					
	(AVG MAN HRS: 1)					Enc					
	Note: CONCURRENT REQUIREMENTS: Operators must incorporate SB 30413 prior to, or in conjunction with this service bulletin.										

Task No	Description										Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
30526 Rev 1		Modification of Intermediate Case Assembly						RE (-)		Category 6		
	72 ENG2					Mos	30-Jun-2023					
	Eff: 21-Dec-2021 Complied With					Hrs						
	(AVG MAN HRS: 1)					Enc						
	Note: CONCURRENT REQUIREMENTS: Operators must incorporate SB 30413 prior to, or in conjunction with this service bulletin.											
30527		Replacement of No.4 Roller Bearing						RE (-)		Category 9		
	72 ENG1					Mos						
	Eff: 01-Dec-2015					Hrs						
						Enc						
30527		Replacement of No.4 Roller Bearing						RE (-)		Category 9		
	72 ENG2					Mos						
	Eff: 01-Dec-2015					Hrs						
						Enc						
30535		Replacement of Engine Shipping Container						RE (-)		Category 7		
	72 ENG1					Mos	30-Dec-2021					
	Eff: 24-Aug-2017 Complied With					Hrs						
	(AVG MAN HRS: 1.5)					Enc						
30535		Replacement of Engine Shipping Container						RE (-)		Category 7		
	72 ENG2					Mos	31-Dec-2021					
	Eff: 24-Aug-2017 Complied With					Hrs						
	(AVG MAN HRS: 1.5)					Enc						
30535 Rev 1		Replacement of Engine Shipping Container						RE (-)		Category 7		
	72 ENG1					Mos	30-Dec-2021					
	Eff: 29-Sep-2017 Complied With					Hrs						
	(AVG MAN HRS: 1.5)					Enc						
30535 Rev 1		Replacement of Engine Shipping Container						RE (-)		Category 7		
	72 ENG2					Mos	31-Dec-2021					
	Eff: 29-Sep-2017 Complied With					Hrs						
	(AVG MAN HRS: 1.5)					Enc						
30535 Rev 2		Replacement of Engine Shipping Container						RE (-)		Category 7		
	72 ENG1					Mos						
	Eff: 15-Sep-2023					Hrs						
	(AVG MAN HRS: 1.5)					Enc						
30535 Rev 2		Replacement of Engine Shipping Container						RE (-)		Category 7		
	72 ENG2					Mos						
	Eff: 15-Sep-2023					Hrs						
	(AVG MAN HRS: 1.5)					Enc						
30540		Replacement of High Pressure Turbine Air Seal (CONTROLLED SERVICE USE NO. 0004160)						RE (-)				
	72 ENG1					Mos	30-Dec-2021					
	Eff: 26-Feb-2018 Complied With					Hrs						
	(AVG MAN HRS: 1.5)					Enc						
30540		Replacement of High Pressure Turbine Air Seal (CONTROLLED SERVICE USE NO. 0004160)						RE (-)				
	72 ENG2					Mos	31-Dec-2021					
	Eff: 26-Feb-2018 Complied With					Hrs						
	(AVG MAN HRS: 1.5)					Enc						
30540 Rev 1		Replacement of High Pressure Turbine Air Seal						RE (-)		Category 7		
	72 ENG1					Mos	30-Dec-2021					
	Eff: 12-Nov-2020 Complied With					Hrs						
	(AVG MAN HRS: 1.5)					Enc						

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30540 Rev 1</b>		<b>Replacement of High Pressure Turbine Air Seal</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 12-Nov-2020 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30540 Rev 2</b>		<b>Replacement of High Pressure Turbine Air Seal</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 26-Oct-2021 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30540 Rev 2</b>		<b>Replacement of High Pressure Turbine Air Seal</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 26-Oct-2021 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30540 Rev 3</b>		<b>Replacement of High Pressure Turbine Air Seal</b>						RE (-)		Category 7	
	72 ENG1					Mos					
	Eff: 25-Jul-2024					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30540 Rev 3</b>		<b>Replacement of High Pressure Turbine Air Seal</b>						RE (-)		Category 7	
	72 ENG2					Mos					
	Eff: 25-Jul-2024					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30541</b>		<b>Replacement of Fuel Control Drive and Accessory Drive Plain Seal</b>						RE (-)		Category 6, Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 07-Mar-2018 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30541</b>		<b>Replacement of Fuel Control Drive and Accessory Drive Plain Seal</b>						RE (-)		Category 6, Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 07-Mar-2018 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30541 Part A</b>		<b>Replacement of Fuel Control Gearshaft Seal</b>						RE (-)		Category 6, Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 07-Mar-2018 Complied With					Hrs					
						Enc					
<b>30541 Part A</b>		<b>Replacement of Fuel Control Gearshaft Seal</b>						RE (-)		Category 6, Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 07-Mar-2018 Complied With					Hrs					
						Enc					
<b>30541 Part B</b>		<b>Replacement of Accessory Drive Plain Seal</b>						RE (-)		Category 6, Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 07-Mar-2018 Complied With					Hrs					
						Enc					
<b>30541 Part B</b>		<b>Replacement of Accessory Drive Plain Seal</b>						RE (-)		Category 6, Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 07-Mar-2018 Complied With					Hrs					
						Enc					
<b>30541 Rev 1</b>		<b>Replacement of Fuel Control Drive and Accessory Drive Plain Seal</b>						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 12-Jun-2018 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30541 Rev 1</b>		<b>Replacement of Fuel Control Drive and Accessory Drive Plain Seal</b>						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 12-Jun-2018 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					













Task No	Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30541	Rev 1 Part A	Replacement of Fuel Control Gearshaft Seal						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 12-Jun-2018 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30541	Rev 1 Part A	Replacement of Fuel Control Gearshaft Seal						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 12-Jun-2018 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30541	Rev 1 Part B	Replacement of Accessory Drive Plain Seal						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 12-Jun-2018 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30541	Rev 1 Part B	Replacement of Accessory Drive Plain Seal						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 12-Jun-2018 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30546		Replacement of HPT Air Seal						RE (-)		Category 9	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 05-Sep-2019 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30546		Replacement of HPT Air Seal						RE (-)		Category 9	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 05-Sep-2019 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30546	Rev 1	Replacement of HPT Air Seal						RE (-)		Category 9	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 06-Nov-2019 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30546	Rev 1	Replacement of HPT Air Seal						RE (-)		Category 9	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 06-Nov-2019 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30546	Rev 2	Replacement of HPT Air Seal						RE (-)		Category 9	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 12-Apr-2021 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30546	Rev 2	Replacement of HPT Air Seal						RE (-)		Category 9	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 12-Apr-2021 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30550		Replacement of No. 4 Bearing Seal Runners						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 09-May-2019 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30550		Replacement of No. 4 Bearing Seal Runners						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 09-May-2019 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30550	Part A	Replacement of No. 4 Bearing Seal Runners - Front No.4 Bearing Seal Runner						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 09-May-2019 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					












Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>30550 Part A</b>	<b>Replacement of No. 4 Bearing Seal Runners - Front No.4 Bearing Seal Runner</b>						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 09-May-2019 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30550 Part B</b>	<b>Replacement of No. 4 Bearing Seal Runners - Rear No.4 Bearing Seal Runner</b>						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 09-May-2019 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30550 Part B</b>	<b>Replacement of No. 4 Bearing Seal Runners - Rear No.4 Bearing Seal Runner</b>						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 09-May-2019 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30562</b>	<b>Replacement of Mixer Assembly</b>						RE (-)		Category 9	
 72 ENG1						Mos	30-Dec-2021			
Eff: 18-May-2021 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30562</b>	<b>Replacement of Mixer Assembly</b>						RE (-)		Category 9	
 72 ENG2						Mos	31-Dec-2021			
Eff: 18-May-2021 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30562 Rev 1</b>	<b>Replacement of Mixer Assembly</b>						RE (-)		Category 9	
 72 ENG1						Mos	30-Dec-2021			
Eff: 27-May-2021 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30562 Rev 1</b>	<b>Replacement of Mixer Assembly</b>						RE (-)		Category 9	
 72 ENG2						Mos	31-Dec-2021			
Eff: 27-May-2021 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30562 Rev 2</b>	<b>Replacement of Mixer Assembly</b>						RE (-)		Category 9	
 72 ENG1						Mos	30-Dec-2021			
Eff: 26-Oct-2021 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30562 Rev 2</b>	<b>Replacement of Mixer Assembly</b>						RE (-)		Category 9	
 72 ENG2						Mos	31-Dec-2021			
Eff: 26-Oct-2021 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30562 Rev 3</b>	<b>Replacement of Mixer Assembly</b>						RE (-)		Category 9	
 72 ENG1						Mos	30-Dec-2021			
Eff: 04-Nov-2021 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30562 Rev 3</b>	<b>Replacement of Mixer Assembly</b>						RE (-)		Category 9	
 72 ENG2						Mos	31-Dec-2021			
Eff: 04-Nov-2021 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30564</b>	<b>Replacement of Lockbolt Collar</b>						T (-)		Category 9	
 72 ENG1						Mos				
Eff: 16-Sep-2022						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30564</b>	<b>Replacement of Lockbolt Collar</b>						T (-)		Category 9	
 72 ENG2						Mos				
Eff: 16-Sep-2022						Hrs				
(AVG MAN HRS: 1.5)						Enc				


















Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30564 Rev 1</b>		<b>Replacement of Lockbolt Collar</b>						T (-)		Category 9	
	72 ENG1										
	Eff: 21-Dec-2022										
	(AVG MAN HRS: 1.5)										
<b>30564 Rev 1</b>		<b>Replacement of Lockbolt Collar</b>						T (-)		Category 9	
	72 ENG2										
	Eff: 21-Dec-2022										
	(AVG MAN HRS: 1.5)										
<b>30564 Rev 2</b>		<b>Replacement/Modification of Second Stage Turbine Vane</b>						T (-)		Category 7	
	72 ENG1										
	Eff: 27-Jan-2023										
	(AVG MAN HRS: 1.5)										
<b>30564 Rev 2</b>		<b>Replacement/Modification of Second Stage Turbine Vane</b>						T (-)		Category 7	
	72 ENG2										
	Eff: 27-Jan-2023										
	(AVG MAN HRS: 1.5)										
<b>30564 Rev 3</b>		<b>Replacement/Modification of Second Stage Turbine Vane</b>						T (A/R)		Category 7	
	72 ENG1										
	Eff: 18-Sep-2023										
	(AVG MAN HRS: 1.5)										
<b>30564 Rev 3</b>		<b>Replacement/Modification of Second Stage Turbine Vane</b>						T (A/R)		Category 7	
	72 ENG2										
	Eff: 18-Sep-2023										
	(AVG MAN HRS: 1.5)										
<b>30568</b>		<b>Replacement of No. 4 Bearing Front and Rear Seal Runners</b>						T (-)		Category 7	
	72 ENG1										
	Eff: 17-Oct-2022										
	(AVG MAN HRS: 1.5)										
<b>30568</b>		<b>Replacement of No. 4 Bearing Front and Rear Seal Runners</b>						T (-)		Category 7	
	72 ENG2										
	Eff: 17-Oct-2022										
	(AVG MAN HRS: 1.5)										
<b>30568 Rev 1</b>		<b>Replacement of No. 4 Bearing Front and Rear Seal Runners</b>						RE (-)		Category 7	
	72 ENG1										
	Eff: 12-Jan-2023										
	(AVG MAN HRS: 1.5)										
<b>30568 Rev 1</b>		<b>Replacement of No. 4 Bearing Front and Rear Seal Runners</b>						RE (-)		Category 7	
	72 ENG2										
	Eff: 12-Jan-2023										
	(AVG MAN HRS: 1.5)										
<b>30568 Rev 1 Part A</b>		<b>Replacement of No. 4 Bearing Front and Rear Seal Runners - Replacement of the Front No. 4 Bearing Seal Runner</b>						T (A/R)		Category 7	
	72 ENG1										
	Eff: 12-Jan-2023										
<b>30568 Rev 1 Part A</b>		<b>Replacement of No. 4 Bearing Front and Rear Seal Runners - Replacement of the Front No. 4 Bearing Seal Runner</b>						T (A/R)		Category 7	
	72 ENG2										
	Eff: 12-Jan-2023										
<b>30568 Rev 1 Part B</b>		<b>Replacement of No. 4 Bearing Front and Rear Seal Runners - Replacement of the Rear No. 4 Bearing Seal Runner</b>						T (A/R)		Category 7	
	72 ENG1										
	Eff: 12-Jan-2023										











Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30568 Rev 1 Part B	72 ENG2 Eff: 12-Jan-2023	Replacement of No. 4 Bearing Front and Rear Seal Runners - Replacement of the Rear No. 4 Bearing Seal Runner						T (A/R)		Category 7	
						Mos					
						Hrs					
						Enc					
30569	72 ENG1	Replacement of Intermediate Case						RE (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30569	72 ENG2	Replacement of Intermediate Case						RE (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30569 Rev 1	72 ENG1 Eff: 24-Dec-2023	Replacement of Intermediate Case						T (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30569 Rev 1	72 ENG2 Eff: 24-Dec-2023	Replacement of Intermediate Case						T (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30569 Rev 2	72 ENG1 Eff: 18-Jan-2024	Replacement of Intermediate Case						T (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30569 Rev 2	72 ENG2 Eff: 18-Jan-2024	Replacement of Intermediate Case						T (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30569 Rev 3	72 ENG1 Eff: 31-Jan-2024	Replacement of Intermediate Case						T (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30569 Rev 3	72 ENG2 Eff: 31-Jan-2024	Replacement of Intermediate Case						T (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30569 Rev 4	72 ENG1 Eff: 22-Feb-2024	Replacement of Intermediate Case						T (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30569 Rev 4	72 ENG2 Eff: 22-Feb-2024	Replacement of Intermediate Case						T (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30569 Rev 5	72 ENG1 Eff: 15-Mar-2024	Replacement of Intermediate Case						T (-)		Category 7	
						Mos					
						Hrs					
						Enc					
30569 Rev 5	72 ENG2 Eff: 15-Mar-2024	Replacement of Intermediate Case						T (-)		Category 7	
						Mos					
						Hrs					
						Enc					














Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30569 Rev 6</b>		<b>Replacement of Intermediate Case</b>						T (-)		Category 7	
	72 ENG1					Mos					
	Eff: 10-Apr-2024					Hrs					
						Enc					
<b>30569 Rev 6</b>		<b>Replacement of Intermediate Case</b>						T (-)		Category 7	
	72 ENG2					Mos					
	Eff: 10-Apr-2024					Hrs					
						Enc					
<b>30569 Rev 7</b>		<b>Replacement of Intermediate Case</b>						T (-)		Category 7	
	72 ENG1					Mos					
	Eff: 26-Jul-2024					Hrs					
						Enc					
<b>30569 Rev 7</b>		<b>Replacement of Intermediate Case</b>						T (-)		Category 7	
	72 ENG2					Mos					
	Eff: 26-Jul-2024					Hrs					
						Enc					
<b>30569 Rev 8</b>		<b>Replacement of Intermediate Case</b>						T (A/R)		Category 7	
	72 ENG1					Mos					
	Eff: 20-Sep-2024					Hrs					
						Enc					
<b>30569 Rev 8</b>		<b>Replacement of Intermediate Case</b>						T (A/R)		Category 7	
	72 ENG2					Mos					
	Eff: 20-Sep-2024					Hrs					
						Enc					
<b>30572</b>		<b>Inspection of HP Turbine Disk</b>						T (A/R)		Category 5	
	72 ENG1					Mos					
	Eff: 31-Jul-2023					Hrs					
	(AVG MAN HRS: 2)					Enc					
	Note: EFFECTIVITY: Refer to Par. 1.A. of this SB for more information.										
<b>30572</b>		<b>Inspection of HP Turbine Disk</b>						T (A/R)		Category 5	
	72 ENG2					Mos					
	Eff: 31-Jul-2023					Hrs					
	(AVG MAN HRS: 2)					Enc					
	Note: EFFECTIVITY: Refer to Par. 1.A. of this SB for more information.										
<b>A30452</b>		<b>Oil System - Special Inspection of MOP</b>						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
<b>A30452</b>		<b>Oil System - Special Inspection of MOP</b>						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
<b>A30452 Rev 1</b>		<b>Oil System - Special Inspection of MOP</b>						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
<b>A30452 Rev 1</b>		<b>Oil System - Special Inspection of MOP</b>						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>A30452 Rev 2</b>		<b>Oil System - Special Inspection of MOP</b>						T (A/R)		Category 10	
	72 ENG1										
	Eff: 31-Jul-2015										
<b>A30452 Rev 2</b>		<b>Oil System - Special Inspection of MOP</b>						T (A/R)		Category 10	
	72 ENG2										
	Eff: 31-Jul-2015										
<b>SIL No. GEN-143</b>		<b>P&amp;WC Oil Analysis Technology Trial Program</b>						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 18-Aug-2016										
		Note: NOTE: The purpose of this Service Information Letter is to introduce P&WC operators to the new Oil Analysis Technology Trial program currently in progress for the next 18 to 24 months at P&WC.									
<b>SIL No. GEN-143</b>		<b>P&amp;WC Oil Analysis Technology Trial Program</b>						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 18-Aug-2016										
		Note: NOTE: The purpose of this Service Information Letter is to introduce P&WC operators to the new Oil Analysis Technology Trial program currently in progress for the next 18 to 24 months at P&WC.									
<b>SIL No. GEN-143 Rev 1</b>		<b>P&amp;WC Oil Analysis Technology Trial Program</b>						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 02-Feb-2017										
		Note: NOTE: It is recommended that this procedure be accomplished by the operator as soon as practicable upon first oil sampling kit reception and during scheduled maintenance.									
<b>SIL No. GEN-143 Rev 1</b>		<b>P&amp;WC Oil Analysis Technology Trial Program</b>						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 02-Feb-2017										
		Note: NOTE: It is recommended that this procedure be accomplished by the operator as soon as practicable upon first oil sampling kit reception and during scheduled maintenance.									
<b>SIL-GEN-015 R2</b>		<b>Shipment Discrepancies, New Non-Conforming Material and Material Returns</b>						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 23-Nov-2020										
<b>SIL-GEN-015 R2</b>		<b>Shipment Discrepancies, New Non-Conforming Material and Material Returns</b>						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 23-Nov-2020										
<b>SIL-GEN-016</b>		<b>Basic Unplanned Removals (BUR)</b>						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 01-Jun-1995										
<b>SIL-GEN-016</b>		<b>Basic Unplanned Removals (BUR)</b>						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 01-Jun-1995										
<b>SIL-GEN-016 Rev 1</b>		<b>Basic Unplanned Removals (BUR)</b>						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 22-Jun-2023										














Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>SIL-GEN-016 Rev 1</b>		<b>Basic Unplanned Removals (BUR)</b>						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 22-Jun-2023					Hrs					
						Enc					
<b>SIL-GEN-020 Rev 5</b>		<b>Vane Rings Airflow Rig Correlation and Calibration with P&amp;WC</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 15-Jul-2015					Hrs					
						Enc					
<b>SIL-GEN-020 Rev 5</b>		<b>Vane Rings Airflow Rig Correlation and Calibration with P&amp;WC</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 15-Jul-2015					Hrs					
						Enc					
<b>SIL-GEN-020 Rev 6</b>		<b>Vane Rings Airflow Rig Correlation and Calibration with P&amp;WC</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 27-Sep-2021					Hrs					
						Enc					
<b>SIL-GEN-020 Rev 6</b>		<b>Vane Rings Airflow Rig Correlation and Calibration with P&amp;WC</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 27-Sep-2021					Hrs					
						Enc					
<b>SIL-GEN-020 Rev 7</b>		<b>Vane Rings Airflow Rig Correlation and Calibration with P&amp;WC</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 09-Jan-2023					Hrs					
						Enc					
<b>SIL-GEN-020 Rev 7</b>		<b>Vane Rings Airflow Rig Correlation and Calibration with P&amp;WC</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 09-Jan-2023					Hrs					
						Enc					
<b>SIL-GEN-020 Rev 8</b>		<b>Vane Rings Airflow Rig Correlation and Calibration with P&amp;WC</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 10-Jan-2023					Hrs					
						Enc					
<b>SIL-GEN-020 Rev 8</b>		<b>Vane Rings Airflow Rig Correlation and Calibration with P&amp;WC</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 10-Jan-2023					Hrs					
						Enc					
<b>SIL-GEN-020 Rev 9</b>		<b>Vane Rings Airflow Rig Correlation and Calibration with P&amp;WC</b>						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 12-Jan-2024					Hrs					
						Enc					
<b>SIL-GEN-020 Rev 9</b>		<b>Vane Rings Airflow Rig Correlation and Calibration with P&amp;WC</b>						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 12-Jan-2024					Hrs					
						Enc					
<b>SIL-GEN-022 R10</b>		<b>P&amp;WC Service Tool Procurement</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 27-Apr-2020					Hrs					
						Enc					
<b>SIL-GEN-022 R10</b>		<b>P&amp;WC Service Tool Procurement</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 27-Apr-2020					Hrs					
						Enc					











Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>SIL-GEN-022 Rev 11</b>		<b>PWC Service Tool Procurement</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 27-Apr-2020					Hrs					
						Enc					
<b>SIL-GEN-022 Rev 11</b>		<b>PWC Service Tool Procurement</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 27-Apr-2020					Hrs					
						Enc					
<b>SIL-GEN-022 Rev 12</b>		<b>PWC Service Tool Procurement</b>						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 29-May-2023					Hrs					
						Enc					
	Note: Applicability: ALL P&WC ENGINE.										
<b>SIL-GEN-022 Rev 12</b>		<b>PWC Service Tool Procurement</b>						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 29-May-2023					Hrs					
						Enc					
	Note: Applicability: ALL P&WC ENGINE.										
<b>SIL-GEN-034 Rev 3</b>		<b>Engine Maintenance at other than Pratt and Whitney Canada Corp. ("PWC") Recommended Time Between Overhaul ("TBO")/Hot Section Inspection ("HSI") Intervals and the Effect on Warranty</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 10-Nov-2012					Hrs					
						Enc					
<b>SIL-GEN-034 Rev 3</b>		<b>Engine Maintenance at other than Pratt and Whitney Canada Corp. ("PWC") Recommended Time Between Overhaul ("TBO")/Hot Section Inspection ("HSI") Intervals and the Effect on Warranty</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 10-Nov-2012					Hrs					
						Enc					
<b>SIL-GEN-034 Rev 4</b>		<b>Engine Maintenance at other than Pratt and Whitney Canada Corp. ("PWC") Recommended Time Between Overhaul ("TBO")/Hot Section Inspection ("HSI") /Periodic Maintenance Intervals and the Effect on Warranty</b>						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 13-Jun-2023					Hrs					
						Enc					
<b>SIL-GEN-034 Rev 4</b>		<b>Engine Maintenance at other than Pratt and Whitney Canada Corp. ("PWC") Recommended Time Between Overhaul ("TBO")/Hot Section Inspection ("HSI") /Periodic Maintenance Intervals and the Effect on Warranty</b>						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 13-Jun-2023					Hrs					
						Enc					
<b>SIL-GEN-038 R4</b>		<b>Use of Non-Pratt and Whitney Canada (PWC) Supported Parts or Non-PWC Approved Repair Schemes</b>						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 13-Jun-2023					Hrs					
						Enc					
<b>SIL-GEN-038 R4</b>		<b>Use of Non-Pratt and Whitney Canada (PWC) Supported Parts or Non-PWC Approved Repair Schemes</b>						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 13-Jun-2023					Hrs					
						Enc					
<b>SIL-GEN-044</b>		<b>Return of Engine Parts to Pratt &amp; Whitney Canada Inc. (P&amp;WC) for Investigation - Evaluation</b>						RE (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 03-Jun-1998					Hrs					
						Enc					














Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>SIL-GEN-044</b>		<b>Return of Engine Parts to Pratt &amp; Whitney Canada Inc. (P&amp;WC) for Investigation - Evaluation</b>						RE (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 03-Jun-1998					Hrs					
						Enc					
<b>SIL-GEN-044 R1</b>		<b>Material Returned to PWC</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 16-Oct-2017					Hrs					
						Enc					
<b>SIL-GEN-044 R1</b>		<b>Material Returned to PWC</b>						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 16-Oct-2017					Hrs					
						Enc					
<b>SIL-GEN-044 Rev 2</b>		<b>Material Returned to PWC</b>						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 03-Aug-2023					Hrs					
						Enc					
<b>SIL-GEN-044 Rev 2</b>		<b>Material Returned to PWC</b>						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 03-Aug-2023					Hrs					
						Enc					
<b>SIL-GEN-049</b>		<b>Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code</b>						RE (-)		Service Information Letter	
	72 ENG1					Mos					
						Hrs					
						Enc					
<b>SIL-GEN-049</b>		<b>Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code</b>						RE (-)		Service Information Letter	
	72 ENG2					Mos					
						Hrs					
						Enc					
<b>SIL-GEN-049 R1</b>		<b>Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 02-Nov-2012					Hrs					
						Enc					
<b>SIL-GEN-049 R1</b>		<b>Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 02-Nov-2012					Hrs					
						Enc					
<b>SIL-GEN-049 R2</b>		<b>Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code</b>						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 13-Sep-2019					Hrs					
						Enc					
<b>SIL-GEN-049 R2</b>		<b>Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code</b>						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 13-Sep-2019					Hrs					
						Enc					
<b>SIL-GEN-055</b>		<b>Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon</b>						RE (-)		Service Information Letter	
	72 ENG1					Mos					
						Hrs					
						Enc					
<b>SIL-GEN-055</b>		<b>Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon</b>						RE (-)		Service Information Letter	
	72 ENG2					Mos					
						Hrs					
						Enc					














Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-055 R1  72 ENG1		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
											Mos
											Hrs
SIL-GEN-055 R1  72 ENG2		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon								Service Information Letter	Enc
								RE (-)			Mos
											Hrs
SIL-GEN-055 R10  72 ENG1 Eff: 13-Nov-2018		Guidelines and Standards for Subscribing and Utilizing the Internet-Based Engine Condition Trend Monitoring EHM Services								Service Information Letter	Enc
								T (A/R)			Mos
											Hrs
SIL-GEN-055 R10  72 ENG2 Eff: 13-Nov-2018		Guidelines and Standards for Subscribing and Utilizing the Internet-Based Engine Condition Trend Monitoring EHM Services								Service Information Letter	Enc
								T (A/R)			Mos
											Hrs
SIL-GEN-055 R2  72 ENG1		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	Enc
											Mos
											Hrs
SIL-GEN-055 R2  72 ENG2		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon								Service Information Letter	Enc
								RE (-)			Mos
											Hrs
SIL-GEN-055 R3  72 ENG1		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon								Service Information Letter	Enc
								RE (-)			Mos
											Hrs
SIL-GEN-055 R3  72 ENG2		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon								Service Information Letter	Enc
								RE (-)			Mos
											Hrs
SIL-GEN-055 R4  72 ENG1		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon								Service Information Letter	Enc
								RE (-)			Mos
											Hrs
SIL-GEN-055 R4  72 ENG2		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon								Service Information Letter	Enc
								RE (-)			Mos
											Hrs
SIL-GEN-055 R5  72 ENG1		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon								Service Information Letter	Enc
								RE (-)			Mos
											Hrs
SIL-GEN-055 R5  72 ENG2		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon								Service Information Letter	Enc
								RE (-)			Mos
											Hrs
SIL-GEN-055 R6  72 ENG1		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon								Service Information Letter	Enc
								RE (-)			Mos
											Hrs








Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-055 R6  72 ENG2		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
SIL-GEN-055 R8  72 ENG1 Eff: 06-Nov-2018		Guidelines and Standards for Subscribing and Utilizing the Internet-based Engine Condition Trend Monitoring EHM Services						T (-)		Service Information Letter	
SIL-GEN-055 R8  72 ENG2 Eff: 06-Nov-2018		Guidelines and Standards for Subscribing and Utilizing the Internet-based Engine Condition Trend Monitoring EHM Services						T (-)		Service Information Letter	
SIL-GEN-055 R9  72 ENG1 Eff: 08-Nov-2018		Guidelines and Standards for Subscribing and Utilizing the Internet-based Engine Condition Trend Monitoring EHM Services						T (-)		Service Information Letter	
SIL-GEN-055 R9  72 ENG2 Eff: 08-Nov-2018		Guidelines and Standards for Subscribing and Utilizing the Internet-based Engine Condition Trend Monitoring EHM Services						T (-)		Service Information Letter	
SIL-GEN-061  72 ENG1		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061  72 ENG2		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 1  72 ENG1		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 1  72 ENG2		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 10  72 ENG1 Eff: 25-Jan-2021		Engine Related Requests						T (-)		Service Information Letter	
SIL-GEN-061 Rev 10  72 ENG2 Eff: 25-Jan-2021		Engine Related Requests						T (-)		Service Information Letter	
SIL-GEN-061 Rev 11  72 ENG1 Eff: 19-Mar-2024		Engine Related Requests						T (A/R)		Service Information Letter	
SIL-GEN-061 Rev 11  72 ENG2 Eff: 19-Mar-2024		Engine Related Requests						T (A/R)		Service Information Letter	

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-061 Rev 2  72 ENG1		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 2  72 ENG2		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 3  72 ENG1		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 3  72 ENG2		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 4  72 ENG1		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 4  72 ENG2		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 5  72 ENG1		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 5  72 ENG2		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 6  72 ENG1		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 6  72 ENG2		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 7  72 ENG1		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 7  72 ENG2		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 8  72 ENG1 Eff: 10-Apr-2018		Engine Related Requests						T (-)		Service Information Letter	






Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>SIL-GEN-061 Rev 8</b>		<b>Engine Related Requests</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 10-Apr-2018					Hrs					
						Enc					
<b>SIL-GEN-061 Rev 9</b>		<b>Engine Related Requests</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 21-Mar-2019					Hrs					
						Enc					
<b>SIL-GEN-061 Rev 9</b>		<b>Engine Related Requests</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 21-Mar-2019					Hrs					
						Enc					
<b>SIL-GEN-065 Rev 1</b>		<b>Information Required to Process New Engine Accessory Warranty Claims</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 29-Jun-2023					Hrs					
						Enc					
<b>SIL-GEN-065 Rev 1</b>		<b>Information Required to Process New Engine Accessory Warranty Claims</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 29-Jun-2023					Hrs					
						Enc					
<b>SIL-GEN-065 Rev 2</b>		<b>Information Required to Process New Engine Accessory Warranty Claims</b>						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 13-Mar-2024					Hrs					
						Enc					
<b>SIL-GEN-065 Rev 2</b>		<b>Information Required to Process New Engine Accessory Warranty Claims</b>						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 13-Mar-2024					Hrs					
						Enc					
<b>SIL-GEN-093</b>		<b>Engine Preservation and Storage</b>						RE (-)		Informational	
	72 ENG1					Mos					
	Eff: 20-Mar-2009					Hrs					
						Enc					
<b>SIL-GEN-093</b>		<b>Engine Preservation and Storage</b>						RE (-)		Informational	
	72 ENG2					Mos					
	Eff: 20-Mar-2009					Hrs					
						Enc					
<b>SIL-GEN-093 R1</b>		<b>Engine Preservation and Storage</b>						T (-)		Informational	
	72 ENG1					Mos					
	Eff: 14-Apr-2016					Hrs					
						Enc					
<b>SIL-GEN-093 R1</b>		<b>Engine Preservation and Storage</b>						T (-)		Informational	
	72 ENG2					Mos					
	Eff: 14-Apr-2016					Hrs					
						Enc					
<b>SIL-GEN-093 R2</b>		<b>Engine Preservation and Storage</b>						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 22-Oct-2021					Hrs					
						Enc					
<b>SIL-GEN-093 R2</b>		<b>Engine Preservation and Storage</b>						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 22-Oct-2021					Hrs					
						Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-110  72 ENG1		Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						RE (-)		Service Information Letter	
SIL-GEN-110  72 ENG2		Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						RE (-)		Service Information Letter	
SIL-GEN-110 Rev 1  72 ENG1		Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						RE (-)		Service Information Letter	
SIL-GEN-110 Rev 1  72 ENG2		Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						RE (-)		Service Information Letter	
SIL-GEN-110 Rev 3  72 ENG1 Eff: 19-Dec-2018		Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						T (A/R)		Service Information Letter	
SIL-GEN-110 Rev 3  72 ENG2 Eff: 19-Dec-2018		Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						T (A/R)		Service Information Letter	
SIL-GEN-117 Rev 1  72 ENG1 Eff: 14-Apr-2023		Warranty Allowance for Consumable Materials and Miscellaneous Parts Used During Engine Line Maintenance Work in the Field						T (A/R)		Service Information Letter	
SIL-GEN-117 Rev 1  72 ENG2 Eff: 14-Apr-2023		Warranty Allowance for Consumable Materials and Miscellaneous Parts Used During Engine Line Maintenance Work in the Field						T (A/R)		Service Information Letter	
SIL-GEN-121 Rev 1  72 ENG1 Eff: 13-Apr-2023		Mobile Repair Team Travel Allowance Instructions for Warranty or ESP Program Coverage						T (A/R)		Service Information Letter	
SIL-GEN-121 Rev 1  72 ENG2 Eff: 13-Apr-2023		Mobile Repair Team Travel Allowance Instructions for Warranty or ESP Program Coverage						T (A/R)		Service Information Letter	
SIL-GEN-122  72 ENG1		Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
SIL-GEN-122  72 ENG2		Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
SIL-GEN-122 R1  72 ENG1		Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	














Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-122 R1	 72 ENG2	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-122 R10	 72 ENG1	Recovery Fee for Maintenance Deviation Letters						RE (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-122 R10	 72 ENG2	Recovery Fee for Maintenance Deviation Letters						RE (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-122 R11	 72 ENG1 Eff: 29-Jun-2022	Recovery Fee for Maintenance Deviation Letters						T (A/R)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-122 R11	 72 ENG2 Eff: 29-Jun-2022	Recovery Fee for Maintenance Deviation Letters						T (A/R)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-122 R2	 72 ENG1	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-122 R2	 72 ENG2	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-122 R3	 72 ENG1	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-122 R3	 72 ENG2	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-122 R4	 72 ENG1	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-122 R4	 72 ENG2	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-122 R5	 72 ENG1	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-122 R5	 72 ENG2	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
						Mos					
						Hrs					














Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>SIL-GEN-122 R6</b>		<b>Recovery Fee For Maintenance Deviation Letters</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 29-Dec-2017					Hrs					
						Enc					
<b>SIL-GEN-122 R6</b>		<b>Recovery Fee For Maintenance Deviation Letters</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 29-Dec-2017					Hrs					
						Enc					
<b>SIL-GEN-122 R7</b>		<b>Recovery Fee For Maintenance Deviation Letters</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 19-Dec-2018					Hrs					
						Enc					
<b>SIL-GEN-122 R7</b>		<b>Recovery Fee For Maintenance Deviation Letters</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 19-Dec-2018					Hrs					
						Enc					
<b>SIL-GEN-122 R8</b>		<b>Recovery Fee for Maintenance Deviation Letters</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 20-Dec-2019					Hrs					
						Enc					
<b>SIL-GEN-122 R8</b>		<b>Recovery Fee for Maintenance Deviation Letters</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 20-Dec-2019					Hrs					
						Enc					
<b>SIL-GEN-122 R9</b>		<b>Recovery Fee for Maintenance Deviation Letters</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 18-Dec-2020					Hrs					
						Enc					
<b>SIL-GEN-122 R9</b>		<b>Recovery Fee for Maintenance Deviation Letters</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 18-Dec-2020					Hrs					
						Enc					
<b>SIL-GEN-123</b>		<b>Qualified Engine Oil Analysis Laboratory List</b>						RE (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 21-Jan-2013					Hrs					
						Enc					
<b>SIL-GEN-123</b>		<b>Qualified Engine Oil Analysis Laboratory List</b>						RE (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 21-Jan-2013					Hrs					
						Enc					
<b>SIL-GEN-123 R1</b>		<b>Qualified Engine Oil Analysis Laboratory List</b>						RE (-)		Service Information Letter	
	72 ENG1					Mos					
						Hrs					
						Enc					
<b>SIL-GEN-123 R1</b>		<b>Qualified Engine Oil Analysis Laboratory List</b>						RE (-)		Service Information Letter	
	72 ENG2					Mos					
						Hrs					
						Enc					
<b>SIL-GEN-123 R2</b>		<b>Qualified Engine Oil Analysis Laboratory List</b>						RE (-)		Service Information Letter	
	72 ENG1					Mos					
						Hrs					
						Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-123 R2	72 ENG2	Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R3	72 ENG1	Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R3	72 ENG2	Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R4	72 ENG1	Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R4	72 ENG2	Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R5	72 ENG1	Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R5	72 ENG2	Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R6	72 ENG1	Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R6	72 ENG2	Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
SIL-GEN-123 R7	72 ENG1 Eff: 10-Jul-2018	Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	
SIL-GEN-123 R7	72 ENG2 Eff: 10-Jul-2018	Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	
SIL-GEN-123 Rev 10	72 ENG1 Eff: 13-Mar-2023	Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	
SIL-GEN-123 Rev 10	72 ENG2 Eff: 13-Mar-2023	Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	














Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>SIL-GEN-123 Rev 11</b>		<b>Qualified Engine Oil Analysis Laboratory List</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 12-Sep-2023					Hrs					
						Enc					
<b>SIL-GEN-123 Rev 11</b>		<b>Qualified Engine Oil Analysis Laboratory List</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 12-Sep-2023					Hrs					
						Enc					
<b>SIL-GEN-123 Rev 12</b>		<b>Qualified Engine Oil Analysis Laboratory List</b>						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 04-Dec-2023					Hrs					
						Enc					
<b>SIL-GEN-123 Rev 12</b>		<b>Qualified Engine Oil Analysis Laboratory List</b>						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 04-Dec-2023					Hrs					
						Enc					
<b>SIL-GEN-123 Rev 8</b>		<b>Qualified Engine Oil Analysis Laboratory List</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 25-Jul-2018					Hrs					
						Enc					
<b>SIL-GEN-123 Rev 8</b>		<b>Qualified Engine Oil Analysis Laboratory List</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 25-Jul-2018					Hrs					
						Enc					
<b>SIL-GEN-123 Rev 9</b>		<b>Qualified Engine Oil Analysis Laboratory List</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 14-Jul-2022					Hrs					
						Enc					
<b>SIL-GEN-123 Rev 9</b>		<b>Qualified Engine Oil Analysis Laboratory List</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 14-Jul-2022					Hrs					
						Enc					
<b>SIL-GEN-128 Rev 1</b>		<b>Limited Time Offer for P&amp;WC Engine Diagnostic System for Applicable P&amp;WC Turbofan Powered Aircraft</b>						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 15-Jul-2013					Hrs					
						Enc					
<b>SIL-GEN-128 Rev 1</b>		<b>Limited Time Offer for P&amp;WC Engine Diagnostic System for Applicable P&amp;WC Turbofan Powered Aircraft</b>						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 15-Jul-2013					Hrs					
						Enc					
<b>SIL-GEN-135</b>		<b>Aviation Accidents / Incidents - Return to Service of Affected P&amp;WC Products and the Effect on Engine Warranty and Service Policies Status (This Service Information Letter (SIL) supersedes SIL GEN-039)</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 21-Feb-2017					Hrs					
						Enc					
	Note: APPLICABILITY: All P&WC engines.										
<b>SIL-GEN-135</b>		<b>Aviation Accidents / Incidents - Return to Service of Affected P&amp;WC Products and the Effect on Engine Warranty and Service Policies Status (This Service Information Letter (SIL) supersedes SIL GEN-039)</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 21-Feb-2017					Hrs					
						Enc					
	Note: APPLICABILITY: All P&WC engines.										

























Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
 <b>SIL-GEN-135 Rev 1</b> 72 ENG1 Eff: 03-Jun-2021	Aviation Accidents / Incidents - Return to Service of Affected P&WC Products and the Effect on Engine Warranty and Service Policies Status							T (A/R)	Service Information Letter		
 <b>SIL-GEN-135 Rev 1</b> 72 ENG2 Eff: 03-Jun-2021	Aviation Accidents / Incidents - Return to Service of Affected P&WC Products and the Effect on Engine Warranty and Service Policies Status							T (A/R)	Service Information Letter		
 <b>SIL-GEN-143</b> 72 ENG1 Eff: 18-Aug-2016	P&WC'S Oil Analysis Technology Trial Program							RE (-)	Service Information Letter		
 <b>SIL-GEN-143</b> 72 ENG2 Eff: 18-Aug-2016	P&WC'S Oil Analysis Technology Trial Program							RE (-)	Service Information Letter		
 <b>SIL-GEN-143 R1</b> 72 ENG1	P&WC'S Oil Analysis Technology Trial Program							RE (-)	Service Information Letter		
 <b>SIL-GEN-143 R1</b> 72 ENG2	P&WC'S Oil Analysis Technology Trial Program							RE (-)	Service Information Letter		
 <b>SIL-GEN-143 R2</b> 72 ENG1 Eff: 09-Jul-2018	P&WC'S Oil Analysis Technology Trial Program							T (A/R)	Service Information Letter		
 <b>SIL-GEN-143 R2</b> 72 ENG2 Eff: 09-Jul-2018	P&WC'S Oil Analysis Technology Trial Program							T (A/R)	Service Information Letter		
 <b>SIL-GEN-153</b> 72 ENG1 Eff: 17-Jul-2018	P&WC's Oil Analysis Technology Program Logistics Information							T (-)	Service Information Letter		
 <b>SIL-GEN-153</b> 72 ENG2 Eff: 17-Jul-2018	P&WC's Oil Analysis Technology Program Logistics Information							T (-)	Service Information Letter		
 <b>SIL-GEN-153 Rev 1</b> 72 ENG1 Eff: 10-Mar-2019	P&WC's Oil Analysis Technology Program Logistics Information							T (-)	Service Information Letter		
 <b>SIL-GEN-153 Rev 1</b> 72 ENG2 Eff: 10-Mar-2019	P&WC's Oil Analysis Technology Program Logistics Information							T (-)	Service Information Letter		
 <b>SIL-GEN-153 Rev 10</b> 72 ENG1 Eff: 31-Oct-2022	P&WC's Oil Analysis Technology Service Logistics Information							T (-)	Service Information Letter		












Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>SIL-GEN-153 Rev 10</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 31-Oct-2022					Hrs					
						Enc					
<b>SIL-GEN-153 Rev 11</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 22-Dec-2022					Hrs					
						Enc					
<b>SIL-GEN-153 Rev 11</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 22-Dec-2022					Hrs					
						Enc					
<b>SIL-GEN-153 Rev 12</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 23-Jan-2024					Hrs					
						Enc					
<b>SIL-GEN-153 Rev 12</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 23-Jan-2024					Hrs					
						Enc					
<b>SIL-GEN-153 Rev 2</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 20-Jun-2019					Hrs					
						Enc					
<b>SIL-GEN-153 Rev 2</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 20-Jun-2019					Hrs					
						Enc					
<b>SIL-GEN-153 Rev 3</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 26-Sep-2019					Hrs					
						Enc					
<b>SIL-GEN-153 Rev 3</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 26-Sep-2019					Hrs					
						Enc					
<b>SIL-GEN-153 Rev 4</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 05-May-2020					Hrs					
						Enc					
<b>SIL-GEN-153 Rev 4</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 05-May-2020					Hrs					
						Enc					
<b>SIL-GEN-153 Rev 5</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 28-Sep-2020					Hrs					
						Enc					
<b>SIL-GEN-153 Rev 5</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 28-Sep-2020					Hrs					
						Enc					







Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>SIL-GEN-153 Rev 6</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 30-Oct-2020					Hrs					
						Enc					
<b>SIL-GEN-153 Rev 6</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 30-Oct-2020					Hrs					
						Enc					
<b>SIL-GEN-153 Rev 7</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 05-Jan-2021					Hrs					
						Enc					
<b>SIL-GEN-153 Rev 7</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 05-Jan-2021					Hrs					
						Enc					
<b>SIL-GEN-153 Rev 8</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 15-Sep-2021					Hrs					
						Enc					
<b>SIL-GEN-153 Rev 8</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 15-Sep-2021					Hrs					
						Enc					
<b>SIL-GEN-153 Rev 9</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 18-Jan-2022					Hrs					
						Enc					
<b>SIL-GEN-153 Rev 9</b>		<b>P&amp;WC's Oil Analysis Technology Service Logistics Information</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 18-Jan-2022					Hrs					
						Enc					
<b>SIL-GEN-155</b>		<b>Introduction of Hyperlinks in P&amp;WC Service Bulletins</b>						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 14-Jun-2019					Hrs					
						Enc					
<b>SIL-GEN-155</b>		<b>Introduction of Hyperlinks in P&amp;WC Service Bulletins</b>						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 14-Jun-2019					Hrs					
						Enc					
<b>SIL-GEN-156 R1</b>		<b>DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation</b>						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 02-Apr-2020					Hrs					
						Enc					
<b>SIL-GEN-156 R1</b>		<b>DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation</b>						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 02-Apr-2020					Hrs					
						Enc					
<b>SIL-GEN-156 R2</b>		<b>DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation</b>						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 07-Apr-2020					Hrs					
						Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>SIL-GEN-156 R2</b>		<b>DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation</b>						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 07-Apr-2020										
<b>SIL-GEN-157</b>		<b>Preservation - Engines Removed from Service on Temporary Basis</b>						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 18-Mar-2020										
<b>SIL-GEN-157</b>		<b>Preservation - Engines Removed from Service on Temporary Basis</b>						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 18-Mar-2020										
<b>SIL-GEN-158</b>		<b>Handling of Suspected Hexavalent Chromium Residue on Engine Parts During Maintenance, Repair and Overhaul</b>						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 20-Jul-2020										
<b>SIL-GEN-158</b>		<b>Handling of Suspected Hexavalent Chromium Residue on Engine Parts During Maintenance, Repair and Overhaul</b>						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 20-Jul-2020										
<b>SIL-GEN-159</b>		<b>Environmentally Assisted Cracking in Certain Aluminium Alloys</b>						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 08-Jul-2020										
<b>SIL-GEN-159</b>		<b>Environmentally Assisted Cracking in Certain Aluminium Alloys</b>						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 08-Jul-2020										
<b>SIL-GEN-160</b>		<b>Occasional Dust Plume Exposure</b>						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 30-Jun-2020										
<b>SIL-GEN-160</b>		<b>Occasional Dust Plume Exposure</b>						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 30-Jun-2020										
<b>SIL-GEN-161</b>		<b>Operations in Environments Affected by Wildfires, Bushfires and Forest Fires</b>						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 19-Oct-2020										
<b>SIL-GEN-161</b>		<b>Operations in Environments Affected by Wildfires, Bushfires and Forest Fires</b>						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 19-Oct-2020										
<b>SIL-GEN-166</b>		<b>Critical Component Accumulated Cycle Counting</b>						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 23-Jun-2021										
<b>SIL-GEN-166</b>		<b>Critical Component Accumulated Cycle Counting</b>						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 23-Jun-2021										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>SIL-GEN-168</b>		<b>Reminder Regarding Scheduled Maintenance Tasks at Engine Shop Visits</b>						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 23-Sep-2022										
<b>SIL-GEN-168</b>		<b>Reminder Regarding Scheduled Maintenance Tasks at Engine Shop Visits</b>						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 23-Sep-2022										
<b>SIL-GEN-169</b>		<b>PWC Generation 3 Recorder End of New Production</b>						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 27-Mar-2023										
<b>SIL-GEN-169</b>		<b>PWC Generation 3 Recorder End of New Production</b>						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 27-Mar-2023										
<b>SIL-PW200-004</b>		<b>New Engine Serial Numbering Methodology</b>						RE (-)		Service Information Letter	
	72 ENG1										
	Eff: 20-Jun-1996										
<b>SIL-PW200-004</b>		<b>New Engine Serial Numbering Methodology</b>						RE (-)		Service Information Letter	
	72 ENG2										
	Eff: 20-Jun-1996										
<b>SIL-PW200-004 R1</b>		<b>New Engine Serial Numbering Methodology</b>						RE (-)		Service Information Letter	
	72 ENG1										
	Eff: 23-Sep-1998										
<b>SIL-PW200-004 R1</b>		<b>New Engine Serial Numbering Methodology</b>						RE (-)		Service Information Letter	
	72 ENG2										
	Eff: 23-Sep-1998										
<b>SIL-PW200-004 R2</b>		<b>New Engine Serial Numbering Methodology</b>						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 12-Mar-2004										
<b>SIL-PW200-004 R2</b>		<b>New Engine Serial Numbering Methodology</b>						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 12-Mar-2004										
<b>SIL-PW300-007</b>		<b>New Engine Serial Numbering Methodology</b>						RE (-)		Service Information Letter	
	72 ENG1										
	Eff: 20-Jun-1996										
<b>SIL-PW300-007</b>		<b>New Engine Serial Numbering Methodology</b>						RE (-)		Service Information Letter	
	72 ENG2										
	Eff: 20-Jun-1996										
<b>SIL-PW300-007 Rev 1</b>		<b>New Engine Serial Numbering Methodology</b>						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 23-Sep-1998										














Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
 <b>SIL-PW300-007 Rev 1</b> 72 ENG2 Eff: 23-Sep-1998	New Engine Serial Numbering Methodology										T (A/R) Service Information Letter
 <b>SIL-PW500-022</b> 72 ENG1 Eff: 01-Jan-2006	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)										RE (-) Service Information Letter
 <b>SIL-PW500-022</b> 72 ENG2 Eff: 01-Jan-2006	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)										RE (-) Service Information Letter
 <b>SIL-PW500-022 Rev 1</b> 72 ENG1	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)										RE (-) Service Information Letter
 <b>SIL-PW500-022 Rev 1</b> 72 ENG2	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)										RE (-) Service Information Letter
 <b>SIL-PW500-022 Rev 2</b> 72 ENG1	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)										RE (-) Service Information Letter
 <b>SIL-PW500-022 Rev 2</b> 72 ENG2	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)										RE (-) Service Information Letter
 <b>SIL-PW500-022 Rev 3</b> 72 ENG1 Eff: 13-Sep-2019	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)										T (A/R) Service Information Letter
 <b>SIL-PW500-022 Rev 3</b> 72 ENG2 Eff: 13-Sep-2019	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)										T (A/R) Service Information Letter
 <b>SIL-PW500-067</b> 72 ENG1 Eff: 28-Feb-2017	High Compressor Rotor 2nd Stage										T (A/R) Service Information Letter
 <b>SIL-PW500-067</b> 72 ENG2 Eff: 28-Feb-2017	High Compressor Rotor 2nd Stage										T (A/R) Service Information Letter
 <b>SIL-PW500-069</b> 72 ENG1 Eff: 20-Jun-2017  Note: Note: CSPN 1006723R08 will close on 31 December 2017, operators are advised that P&WC does not plan to extend the program beyond this date.	Electronic Engine Control (EEC) Service Bulletin 30478										T (A/R) Service Information Letter













Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>SIL-PW500-069</b>		<b>Electronic Engine Control (EEC) Service Bulletin 30478</b>						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 20-Jun-2017										
		Note: Note: CSPN 1006723R08 will close on 31 December 2017, operators are advised that P&WC does not plan to extend the program beyond this date.									
<b>SIL-PW500-071</b>		<b>Electronic Data Analysis Service for Engine DCU Downloads</b>						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 21-Nov-2017										
<b>SIL-PW500-071</b>		<b>Electronic Data Analysis Service for Engine DCU Downloads</b>						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 21-Nov-2017										
<b>SIL-PW500-072</b>		<b>ACES Viper II Analyzer Introduction</b>						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 02-Oct-2018										
<b>SIL-PW500-072</b>		<b>ACES Viper II Analyzer Introduction</b>						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 02-Oct-2018										
<b>SIL-PW500-073</b>		<b>Oil Analysis Technology Solution Now available</b>						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 01-Aug-2019										
<b>SIL-PW500-073</b>		<b>Oil Analysis Technology Solution Now available</b>						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 01-Aug-2019										
<b>SIL-PW500-073 Rev 1</b>		<b>Oil Analysis Technology Solution Now Available</b>						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 04-Oct-2019										
<b>SIL-PW500-073 Rev 1</b>		<b>Oil Analysis Technology Solution Now Available</b>						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 04-Oct-2019										
<b>SIL-PW500-073 Rev 2</b>		<b>P&amp;WC's Oil Analysis Technology Solution Now Available</b>						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 08-Jan-2020										
<b>SIL-PW500-073 Rev 2</b>		<b>P&amp;WC's Oil Analysis Technology Solution Now Available</b>						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 08-Jan-2020										
<b>SIL-PW500-073 Rev 3</b>		<b>P&amp;WC's Oil Analysis Technology Solution Now Available</b>						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 05-Jan-2021										




Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>SIL-PW500-073 Rev 3</b>		<b>P&amp;WC's Oil Analysis Technology Solution Now Available</b>						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 05-Jan-2021					Hrs					
						Enc					
<b>SIL-PW500-075</b>		<b>BOV Servo Valve - New Revision to PW500 Maintenance Manuals, Section 05-20-00 Scheduled Maintenance Check - Engine Accessories at Engine Overhaul</b>						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 14-Dec-2021					Hrs					
						Enc					
<b>SIL-PW500-075</b>		<b>BOV Servo Valve - New Revision to PW500 Maintenance Manuals, Section 05-20-00 Scheduled Maintenance Check - Engine Accessories at Engine Overhaul</b>						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 14-Dec-2021					Hrs					
						Enc					
<b>SIL-PW500-078</b>		<b>Low Pressure Shaft Balancing Assembly - New revision to PW500 Maintenance Manuals, section 05-20-00 Scheduled Maintenance Check - Periodic Inspections</b>						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 04-Dec-2023					Hrs					
						Enc					
<b>SIL-PW500-078</b>		<b>Low Pressure Shaft Balancing Assembly - New revision to PW500 Maintenance Manuals, section 05-20-00 Scheduled Maintenance Check - Periodic Inspections</b>						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 04-Dec-2023					Hrs					
						Enc					
<b>SL560XL-72-04</b>		<b>Engine - Transmittal Of Pratt &amp; Whitney Canada Service Bulletin PW500-72-30110R1, Turbofan Engine - Oil Level Indicator - Replacement Of</b>						RE (-)		Recommended	
	72 A/F					Mos	22-Jun-2022				
	Eff: 15-Mar-2001 Not Applicable	effective before manufacture				Hrs	8				
						Ldg	6				
<b>SL560XL-72-05</b>		<b>Engine - Transmittal Of Pratt &amp; Whitney Canada Service Bulletin PW500-72-30135R1, Turbofan Engine - Oil Filler Cap - Replacement Of</b>						RE (-)		Recommended	
	72 A/F					Mos	22-Jun-2022				
	Eff: 15-Mar-2001 Not Applicable	effective before manufacture				Hrs	8				
						Ldg	6				
<b>SL560XL-72-07</b>		<b>Engine - Transmittal of Pratt &amp; Whitney Canada (PW&amp;C) Service Bulletins PW500-72-30193 and PW500-72-30193, Turbofan Engine Oil Leaks From No. 4 Bearing Pressure and Scavenge Transfer Tubes.</b>						T (A/R)		Informational	
	72 A/F					Mos					
	Eff: 17-Dec-2001					Hrs					
						Ldg					
<b>SL560XL-72-08</b>		<b>Engine - Transmittal of Pratt &amp; Whitney Canada (P&amp;WC) Service Bulletin PW500-72-30203, Replacement of Alternator Shaft Plain Seal</b>						RE (-)		Recommended	
	72 A/F					Mos	22-Jun-2022				
	Eff: 01-May-2002 Not Applicable	effective before manufacture				Hrs	8				
						Ldg	6				
<b>SL560XL-72-09</b>		<b>Engine - Transmittal of Pratt &amp; Whitney Canada Service Bulletin PW500-72-30217, Turbofan Engine Fuel Tube - Inspection Of</b>						RE (-)		Recommended	
	72 A/F					Mos	22-Jun-2022				
	Eff: 03-Jun-2002 Not Applicable	effective before manufacture				Hrs	8				
						Ldg	6				
<b>SL560XL-72-10</b>		<b>Transmittal of Pratt &amp; Whitney Canada (P&amp;WC) Service Information Letter PW500-015, PW545A Fan Case Extension Cracking</b>						T (A/R)		Informational	
	72 A/F					Mos					
	Eff: 11-Aug-2003					Hrs					
						Ldg					














Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SL560XL-72-11	72 A/F	Transmittal of Pratt & Whitney Canada Service Bulletin PW500-72-30252 Number Four Bearing Oil Pressure and Oil Scavenge Tubes - Replacement Of						RE (-)		Optional	
SL560XL-72-11 Rev 01	72 A/F	Transmittal of Pratt & Whitney Canada Service Bulletin PW500-72-30252 Number Four Bearing Oil Pressure and Oil Scavenge Tubes - Replacement Of						RE (-)		Recommended	
	Eff: 27-Nov-2007 Not Applicable	effective before manufacture									
Note: Cancelled - superseded by SL560XL-72-14											
▼ 73 - ENGINE - FUEL AND CONTROL											
30405	73 ENG1	Fuel Nozzle Manifold - Replacement						RE (-)		Category 6	
30405	73 ENG2	Fuel Nozzle Manifold - Replacement						RE (-)		Category 6	
30405 Rev 1	73 ENG1	Fuel Nozzle Manifold - Replacement						RE (-)		Category 6	
30405 Rev 1	73 ENG2	Fuel Nozzle Manifold - Replacement						RE (-)		Category 6	
30405 Rev 2	73 ENG1	Fuel Nozzle Manifold - Replacement						RE (-)		Category 6	
30405 Rev 2	73 ENG2	Fuel Nozzle Manifold - Replacement						RE (-)		Category 6	
30405 Rev 3	73 ENG1	Fuel Nozzle Manifold - Replacement						RE (-)		Category 6	
30405 Rev 3	73 ENG2	Fuel Nozzle Manifold - Replacement						RE (-)		Category 6	
30405 Rev 4	73 ENG1	Fuel Nozzle Manifold - Replacement						RE (-)		Category 6	
30405 Rev 4	73 ENG2	Fuel Nozzle Manifold - Replacement						RE (-)		Category 6	













Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30418 Rev 2</b>		<b>Replacement/ Modification of Electrical Wiring Harness (TT0 Sensor)</b>						RE (-)		Category 6	
	73 ENG1						Mos	30-Dec-2021			
	Eff: 12-May-2016 Complied With						Hrs				
	(AVG MAN HRS: 2.5)						Enc				
<b>30418 Rev 2</b>		<b>Replacement/ Modification of Electrical Wiring Harness (TT0 Sensor)</b>						RE (-)		Category 6	
	73 ENG2						Mos	31-Dec-2021			
	Eff: 12-May-2016 Complied With						Hrs				
	(AVG MAN HRS: 2.5)						Enc				
<b>30465 Rev 2</b>		<b>Replacement of Fuel Manifold Tubes</b>						RE (-)		Category 7	
	73 ENG1						Mos	30-Dec-2021			
	Eff: 08-Jul-2016 Complied With						Hrs				
	(AVG MAN HRS: 1.5)						Enc				
<b>30465 Rev 2</b>		<b>Replacement of Fuel Manifold Tubes</b>						RE (-)		Category 7	
	73 ENG2						Mos	31-Dec-2021			
	Eff: 08-Jul-2016 Complied With						Hrs				
	(AVG MAN HRS: 1.5)						Enc				
<b>30474 Rev 2</b>		<b>Replacement/ Modification of Electrical Wiring Harness</b>						RE (-)		Category 7	
	73 ENG1						Mos	30-Dec-2021			
	Eff: 12-May-2016 Complied With						Hrs				
	(AVG MAN HRS: 1.5)						Enc				
<b>30474 Rev 2</b>		<b>Replacement/ Modification of Electrical Wiring Harness</b>						RE (-)		Category 7	
	73 ENG2						Mos	31-Dec-2021			
	Eff: 12-May-2016 Complied With						Hrs				
	(AVG MAN HRS: 1.5)						Enc				
<b>30474 Rev 3</b>		<b>Replacement/ Modification of Electrical Wiring Harness</b>						RE (-)		Category 7	
	73 ENG1						Mos	30-Dec-2021			
	Eff: 16-Oct-2018 Complied With						Hrs				
	(AVG MAN HRS: 1.5)						Enc				
<b>30474 Rev 3</b>		<b>Replacement/ Modification of Electrical Wiring Harness</b>						RE (-)		Category 7	
	73 ENG2						Mos	31-Dec-2021			
	Eff: 16-Oct-2018 Complied With						Hrs				
	(AVG MAN HRS: 1.5)						Enc				
<b>30478 Rev 4</b>		<b>Electronic Engine Control (EEC) - Replacement/Field Modification</b>						RE (-)		Category 3	
	73 ENG1						Mos	30-Dec-2021			
	Eff: 01-Dec-2015 Complied With						Hrs				
	(AVG MAN HRS: 2.5)						Enc				
<b>30478 Rev 4</b>		<b>Electronic Engine Control (EEC) - Replacement/Field Modification</b>						RE (-)		Category 3	
	73 ENG2						Mos	31-Dec-2021			
	Eff: 01-Dec-2015 Complied With						Hrs				
	(AVG MAN HRS: 2.5)						Enc				
<b>30504 Rev 2</b>		<b>Replacement of Fuel/Oil Heat Exchanger</b>						RE (-)		Category 7	
	73 ENG1						Mos	30-Dec-2021			
	Eff: 04-Jan-2016 Complied With						Hrs				
	(AVG MAN HRS: 1.5)						Enc				
<b>30504 Rev 2</b>		<b>Replacement of Fuel/Oil Heat Exchanger</b>						RE (-)		Category 7	
	73 ENG2						Mos	31-Dec-2021			
	Eff: 04-Jan-2016 Complied With						Hrs				
	(AVG MAN HRS: 1.5)						Enc				
<b>30504 Rev 3</b>		<b>Replacement of Fuel/Oil Heat Exchanger</b>						RE (-)		Category 7	
	73 ENG1						Mos	30-Dec-2021			
	Eff: 15-Jan-2019 Complied With						Hrs				
	(AVG MAN HRS: 1.5)						Enc				











Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>30504 Rev 3</b>	<b>Replacement of Fuel/Oil Heat Exchanger</b>						RE (-)		Category 7	
 73 ENG2						Mos	31-Dec-2021			
Eff: 15-Jan-2019 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30539</b>	<b>Replacement of Fuel Supply Pad</b>						RE (-)		Category 7	
 73 ENG1						Mos	30-Dec-2021			
Eff: 26-Sep-2017 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30539</b>	<b>Replacement of Fuel Supply Pad</b>						RE (-)		Category 7	
 73 ENG2						Mos	31-Dec-2021			
Eff: 26-Sep-2017 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30539 Rev 1</b>	<b>Replacement of Fuel Supply Pad</b>						RE (-)		Category 7	
 73 ENG1						Mos	30-Dec-2021			
Eff: 01-Oct-2019 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30539 Rev 1</b>	<b>Replacement of Fuel Supply Pad</b>						RE (-)		Category 7	
 73 ENG2						Mos	31-Dec-2021			
Eff: 01-Oct-2019 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>SL560XL-73-06</b>	<b>Transmittal of ELDEC Corporation Service Letter SL9-231-73-04, Shipping Instructions for the 9-231-28 Fuel Flow Transmitters</b>						T (A/R)		Informational	
 73 A/F						Mos				
Eff: 21-Jun-2005						Hrs				
						Ldg				
<b>SL560XL-73-07</b>	<b>Transmittal of Pratt &amp; Whitney Canada (P&amp;WC) Service Bulletin 30197R4, Turbofan Engine New Fuel Manifold - Introduction Of</b>						RE (-)		Optional	
 73 A/F						Mos				
						Hrs				
						Ldg				
<b>SL560XL-73-07 Rev 01</b>	<b>Transmittal of Pratt &amp; Whitney Canada (P&amp;WC) Service Bulletin 30197R4, Turbofan Engine New Fuel Manifold - Introduction Of</b>						RE (-)		Optional	
 73 A/F						Mos				
						Hrs				
						Ldg				
<b>SL560XL-73-07 Rev 02</b>	<b>Transmittal of Pratt &amp; Whitney Canada (P&amp;WC) Service Bulletin 30197R4, Turbofan Engine New Fuel Manifold - Introduction Of</b>						T (A/R)		Informational	
 73 A/F						Mos				
Eff: 02-Jul-2007						Hrs				
						Ldg				
<b>▼ 74 - IGNITION</b>										
<b>30542</b>	<b>Replacement of Igniter Cables</b>						RE (-)		Category 7	
 74 ENG1						Mos	30-Dec-2021			
Eff: 25-Apr-2018 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30542</b>	<b>Replacement of Igniter Cables</b>						RE (-)		Category 7	
 74 ENG2						Mos	31-Dec-2021			
Eff: 25-Apr-2018 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>▼ 75 - BLEED AIR</b>										
<b>30548</b>	<b>Replacement/Modification of Anti-Icing Valve</b>						RE (-)		Category 7	
 75 ENG1						Mos	30-Dec-2021			
Eff: 03-Jul-2018 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>30548</b>	<b>Replacement/Modification of Anti-Icing Valve</b>						RE (-)		Category 7	
 75 ENG2						Mos	31-Dec-2021			
Eff: 03-Jul-2018 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				
<b>30548 R1</b>	<b>Replacement/Modification of Anti-Icing Valve</b>						RE (-)		Category 7	
 75 ENG1						Mos	30-Dec-2021			
Eff: 05-Sep-2018 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				
<b>30548 R1</b>	<b>Replacement/Modification of Anti-Icing Valve</b>						RE (-)		Category 7	
 75 ENG2						Mos	31-Dec-2021			
Eff: 05-Sep-2018 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				
<b>30548 R2</b>	<b>Replacement/Modification of Anti-Icing Valve</b>						RE (-)		Category 7	
 75 ENG1						Mos	30-Dec-2021			
Eff: 21-Sep-2018 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				
<b>30548 R2</b>	<b>Replacement/Modification of Anti-Icing Valve</b>						RE (-)		Category 7	
 75 ENG2						Mos	31-Dec-2021			
Eff: 21-Sep-2018 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				
<b>30554 Rev 1</b>	<b>Replacement of Intercompressor Bleed Valve/ Servo-Valve</b>						RE (-)		Category 7	
 75 ENG1						Mos	30-Dec-2021			
Eff: 03-Mar-2021 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30554 Rev 1</b>	<b>Replacement of Intercompressor Bleed Valve/ Servo-Valve</b>						RE (-)		Category 7	
 75 ENG2						Mos	31-Dec-2021			
Eff: 03-Mar-2021 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30554 Rev 2</b>	<b>Replacement of Intercompressor Bleed Valve/ Servo-Valve</b>						RE (-)		Category 7	
 75 ENG1						Mos	30-Dec-2021			
Eff: 26-Oct-2021 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
<b>30554 Rev 2</b>	<b>Replacement of Intercompressor Bleed Valve/ Servo-Valve</b>						RE (-)		Category 7	
 75 ENG2						Mos	31-Dec-2021			
Eff: 26-Oct-2021 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
▼ 76 - ENGINE CONTROLS										
<b>2020-26-05</b>	<b>Power Lever - Throttle Quadrant Inspection</b>						RE (-)		Mandatory	
 76 A/F						Mos	22-Jun-2022			
Eff: 17-Dec-2020 Not	Due to aircraft is not in suspect serial range					Hrs	8			
Applicable						Ldg	6			
(ISSUING AUTHORITY: FAA)										
<b>560XL-76-04</b>	<b>Transmittal of Pratt &amp; Whitney Canada (P&amp;WC) Service Bulletin 30434 Turbofan Engine - Electronic Engine Control/Replacement-Modification and P&amp;WC Service Bulletin 30438 Turbofan Engine Electronic Engine Control (EEC) - Replacement/Modifications Of</b>						RE (-)		Recommended	
 76 A/F						Mos	22-Jun-2022			
Eff: 07-Sep-2011 Not	effective before manufacture					Hrs	8			
Applicable						Ldg	6			
<b>SL560XL-76-03</b>	<b>Transmittal of Pratt &amp; Whitney Canada Service Bulletin 30438 Turbofan Electronic Engine Control (EEC) - Replacement/Modifications of</b>						RE (-)		Discretionary	
 76 A/F						Mos				
						Hrs				
						Ldg				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>SL560XL-76-03 Rev 02</b>		<b>Transmittal of Pratt &amp; Whitney Canada Service Bulletin 30438 Turbofan Electronic Engine Control (EEC) - Replacement/Modifications of</b>						RE (-)		Recommended	
	76 A/F					Mos	22-Jun-2022				
	Eff: 25-Sep-2015 Not Applicable	effective before manufacture				Hrs	8				
	(AVG MAN HRS: 2.5)					Ldg	6				
<b>SL560XL-76-03 Rev 1</b>		<b>Transmittal of Pratt &amp; Whitney Canada Service Bulletin 30438 Turbofan Electronic Engine Control (EEC) - Replacement/Modifications of</b>						RE (-)		Recommended	
	76 A/F					Mos	22-Jun-2022				
	Eff: 13-Sep-2011 Not Applicable	effective before manufacture				Hrs	8				
						Ldg	6				
<b>SL560XL-76-04</b>		<b>Engine Controls - Throttle Quadrant RVDT Linkage Inspection</b>						RE (-)		Mandatory	
	76 A/F					Mos	22-Jun-2022				
	Eff: 12-Nov-2020 Not Applicable	by aircraft S/N				Hrs	8				
	(AVG MAN HRS: 6)					Ldg	6				
<b>SL560XL-76-04 R1</b>		<b>Engine Controls - Throttle Quadrant RVDT Linkage Inspection</b>						RE (-)		Mandatory	
	76 A/F					Mos	22-Jun-2022				
	Eff: 24-Nov-2020 Not Applicable	by aircraft S/N				Hrs	8				
	(AVG MAN HRS: 6)					Ldg	6				
<b>SL560XL-76-05</b>		<b>Engine Controls - Inspection of the Right Engine Throttle Quadrant Rotary Variable Differential Transformer (RVDT) Electrical Wiring</b>						RE (-)		Mandatory	
	76 A/F					Mos	06-Feb-2023				
	Eff: 06-Feb-2023 Not Applicable	N/A per A/C SN				Hrs					
	(AVG MAN HRS: 45)					Ldg					
<b>▼ 77 - ENGINE INDICATING</b>											
<b>30534</b>		<b>Replacement of Data Collection Unit</b>						RE (-)		Category 7	
	77 ENG1					Mos	30-Dec-2021				
	Eff: 28-Mar-2017 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30534</b>		<b>Replacement of Data Collection Unit</b>						RE (-)		Category 7	
	77 ENG2					Mos	31-Dec-2021				
	Eff: 28-Mar-2017 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30534 Rev 1</b>		<b>Replacement of Data Collection Unit</b>						RE (-)		Category 7	
	77 ENG1					Mos	30-Dec-2021				
	Eff: 23-May-2017 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30534 Rev 1</b>		<b>Replacement of Data Collection Unit</b>						RE (-)		Category 7	
	77 ENG2					Mos	31-Dec-2021				
	Eff: 23-May-2017 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30534 Rev 2</b>		<b>Replacement of Data Collection Unit</b>						RE (-)		Category 7	
	77 ENG1					Mos	30-Dec-2021				
	Eff: 31-Oct-2017 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
<b>30534 Rev 2</b>		<b>Replacement of Data Collection Unit</b>						RE (-)		Category 7	
	77 ENG2					Mos	31-Dec-2021				
	Eff: 31-Oct-2017 Complied With					Hrs					
	(AVG MAN HRS: 1.5)					Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>30534 Rev 3</b>		<b>Replacement of Data Collection Unit</b>						RE (-)		Category 7	
	77 ENG1						Mos	30-Dec-2021			
	Eff: 06-Feb-2018 Complied With						Hrs				
	(AVG MAN HRS: 1.5)						Enc				
<b>30534 Rev 3</b>		<b>Replacement of Data Collection Unit</b>						RE (-)		Category 7	
	77 ENG2						Mos	31-Dec-2021			
	Eff: 06-Feb-2018 Complied With						Hrs				
	(AVG MAN HRS: 1.5)						Enc				
<b>30534 Rev 4</b>		<b>Replacement of Data Collection Unit</b>						RE (-)		Category 7	
	77 ENG1						Mos	30-Dec-2021			
	Eff: 29-Jun-2018 Complied With						Hrs				
	(AVG MAN HRS: 1.5)						Enc				
<b>30534 Rev 4</b>		<b>Replacement of Data Collection Unit</b>						RE (-)		Category 7	
	77 ENG2						Mos	31-Dec-2021			
	Eff: 29-Jun-2018 Complied With						Hrs				
	(AVG MAN HRS: 1.5)						Enc				
<b>SL560XL-77-01</b>		<b>Transmittal of Pratt &amp; Whitney Canada Service Information Letter PW500-016, PW545A ITT and N2 Splits in Climb</b>						T (A/R)		Informational	
	77 A/F						Mos				
	Eff: 25-Jun-2003						Hrs				
							Ldg				
<b>SL560XL-77-02</b>		<b>Transmittal of Pratt &amp; Whitney Canada (P&amp;WC) Service Information Letter PW500-018, PW500 High ITT</b>						T (A/R)		Informational	
	77 A/F						Mos				
	Eff: 11-Aug-2003						Hrs				
							Ldg				
<b>▼ 78 - EXHAUST</b>											
<b>SL560XL-78-04</b>		<b>Thrust Reverser Stow Limit Switch Test</b>						RE (-)		Discretionary	
	78 A/F						Mos				
							Hrs				
							Ldg				
<b>SL560XL-78-04 Rev 01</b>		<b>Thrust Reverser Stow Limit Switch Test</b>						RE (-)		Informational	
	78 A/F						Mos				
	Eff: 21-Mar-2007						Hrs				
							Ldg				
<b>▼ 79 - OIL</b>											
<b>30325 Rev 2</b>		<b>Oil-Pump Plain Seal - Replacement</b>						RE (-)		Category 6	
	79 ENG1						Mos	30-Dec-2021			
	Eff: 23-Dec-2015 Complied With						Hrs				
	(AVG MAN HRS: 2)						Enc				
<b>30325 Rev 2</b>		<b>Oil-Pump Plain Seal - Replacement</b>						RE (-)		Category 6	
	79 ENG2						Mos	31-Dec-2021			
	Eff: 23-Dec-2015 Complied With						Hrs				
	(AVG MAN HRS: 2)						Enc				
<b>▼ 99 - --</b>											
<b>CIL-99-01</b>		<b>Use of Corrosion Inhibiting Compounds</b>						RE (-)		Service Letter	
	99 A/F						Mos				
							Hrs				
							Ldg				
<b>CIL-99-01 R1</b>		<b>Use of Corrosion Inhibiting Compounds</b>						T (-)		Service Letter	
	99 A/F						Mos				
	Eff: 15-Feb-2013						Hrs				
							Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
<b>CIL-99-01 R2</b>	<b>Use of Corrosion Inhibiting Compounds</b>								T (-)	Service Letter
 99 A/F										
Eff: 02-Jul-2015										
<b>CIL-99-01 R3</b>	<b>Use of Corrosion Inhibiting Compounds (Cancels this Service Letter)</b>								RE (-)	Service Letter
 99 A/F										
Eff: 14-Aug-2019										
<b>CIL-99-02</b>	<b>Avoid Operations on Runways Treated with Runway De-Ice (RDI) Fluids. Aircraft Washing Recommended after Exposure to RDI Fluids</b>								T (-)	Service Letter
 99 A/F										
Eff: 23-May-2012										
Note: the airplane should be washed within 3 days of any exposure to RDI fluids										
<b>CIL-99-02 R1</b>	<b>Avoid Operations on Runways Treated with Runway De-Ice (RDI) Fluids. Aircraft Washing Recommended after Exposure to RDI Fluids - (Cancels this Service Letter)</b>								RE (-)	Service Letter
 99 A/F										
Eff: 14-Aug-2019										
<b>CIL-99-03</b>	<b>Miscellaneous - Corrosion Prevention and Control Program (CPCP)</b>								RE (-)	Recommended
 99 A/F										
Eff: 04-Jan-2013 Not	effective before manufacture									
Applicable										
Note: his service letter should be accomplished at a scheduled maintenance period or phase inspection.										
<b>CIL-99-03 R1</b>	<b>Miscellaneous - Corrosion Prevention and Control Program (CPCP)</b>								T (-)	Service Letter
 99 A/F										
Eff: 25-Mar-2013										
Note: This service letter should be accomplished at a scheduled maintenance period or phase inspection.										
<b>CIL-99-03 R2</b>	<b>Miscellaneous - Corrosion Prevention and Control Program (CPCP) (Cancels this Service Letter)</b>								RE (-)	Service Letter
 99 A/F										
Eff: 14-Aug-2019										
<b>CIL-99-04</b>	<b>Miscellaneous - Incremental Library Updates For Cesview, Service Letter</b>								RE (-)	Service Letter
 99 A/F										
Eff: 23-May-2012										
<b>CIL-99-04 R1</b>	<b>Miscellaneous - Incremental Library Updates For Cesview, Service Letter - (Cancels this Service Letter)</b>								RE (-)	Service Letter
 99 A/F										
Eff: 14-Aug-2019										
<b>SL560XL-99-03</b>	<b>Transmittal of Cessna's Certification Requirements for Personal Electronic Device Usage</b>								RE (-)	Discretionary
 99 A/F										
<b>SL560XL-99-03 Rev 01</b>	<b>Transmittal of Cessna's Certification Requirements for Personal Electronic Device Usage</b>								T (A/R)	Informational
 99 A/F										
Eff: 23-Aug-2013										
<b>SL560XL-99-04</b>	<b>Cessna Part Number Suffixes For Remanufactured Parts</b>								T (A/R)	Informational
 99 A/F										
Eff: 15-Nov-2011										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
<b>SL560XL-99-05</b>		<b>Cessna Service Document Change Notification</b>						T (A/R)		Informational	
	99 A/F					Mos					
	Eff: 22-Nov-2011					Hrs					
						Ldg					
<b>SL560XL-99-07</b>		<b>Miscellaneous - Transmittal of Rockwell Collins Operators Bulletin (OPSB) 0166-17 - The FMS May Turn In The Wrong Direction After Sequencing A "Climb To" Altitude That Was Manually Edited Or Temperature Compensated</b>						T (A/R)		Informational, Service Letter	
	99 A/F					Mos					
	Eff: 17-Aug-2017					Hrs					
						Ldg					
▼ 100 - GENERAL											
<b>CF-58-02</b>		<b>Radio Equipment Installed Directly Under an Engine Fuel Primer in Aircraft Must Be Relocated Owing to Fire Hazard (This cancels Airworthiness Directive 51-4)</b>						RE (-)		Mandatory	
	100 A/F					Mos	22-Jun-2022				
	Complied With					Hrs	8				
	(ISSUING AUTHORITY: TC)					Ldg	6				
	Note: COMPLIANCE: Compliance with this Directive is effective immediately for all aircraft affected by this order.										
<b>D202005000806</b>		<b>Biocide Treatment Process</b>						T (A/R)		Service Information Letter	
	100 APU1					Mos					
	Eff: 06-May-2020					Hrs					
						APUS					
<b>SIL-GEN-156</b>		<b>DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation</b>						T (-)		Service Information Letter	
	100 ENG1					Mos					
	Eff: 06-Aug-2019					Hrs					
						Enc					
<b>SIL-GEN-156</b>		<b>DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation</b>						T (-)		Service Information Letter	
	100 ENG2					Mos					
	Eff: 06-Aug-2019					Hrs					
						Enc					
<b>SIL-GEN-163</b>		<b>Removal of AWL Requirement to Mark Parts with Accumulated Cycles and/or Time</b>						T (A/R)		Service Information Letter	
	100 ENG1					Mos					
	Eff: 03-Mar-2021					Hrs					
						Enc					
<b>SIL-GEN-163</b>		<b>Removal of AWL Requirement to Mark Parts with Accumulated Cycles and/or Time</b>						T (A/R)		Service Information Letter	
	100 ENG2					Mos					
	Eff: 03-Mar-2021					Hrs					
						Enc					
<b>SIL-PW500-074</b>		<b>United States Parts Distribution</b>						T (A/R)		Service Information Letter	
	100 ENG1					Mos					
	Eff: 02-Jun-2021					Hrs					
						Enc					
<b>SIL-PW500-074</b>		<b>United States Parts Distribution</b>						T (A/R)		Service Information Letter	
	100 ENG2					Mos					
	Eff: 02-Jun-2021					Hrs					
						Enc					