



DueList Report

525B - CJ3

S/N 525B-0220 OK-UMO

OWNER: AEROPARTNER A.S.
ADDRESS: K LETISTI / HANGAR C
PRAGUE 161 00

OPERATOR: AEROPARTNER A.S.
ADDRESS: K LETISTI / HANGAR C
PRAGUE 161 00

OFFICE:
FAX:

OFFICE:
FAX:

ANALYST: GUILLAUME DUCLOS
EMAIL: GUILLAUME.DUCLOS@CAMPSYSTEMS.EU

+33-1.55.93.45.84 (DIRECT)
+33-1.55.93.45.80 (MAIN)
WWW.CAMPSYSTEMS.COM

PROJECTED: 2 MOS. to 30-SEP-2025

AIRCRAFT	SERIAL/REGNO: 525B-0220/OK-UMO	MODEL: 525B - CJ3	MANUFACTURER: TEXTRON AVIATION INC.
CERTIFICATION DATE: 20-FEB-2008		LAST ACTUALS:	PROJECTED:
		3036 A/C HRS as of 28-JUL-2025	3087:47
		2457 AFL as of 28-JUL-2025	2488
		1228:48 ACH as of 10-MAY-2024	1270:13
ENGINE NO. 1	SERIAL/PART: 141453/67000-200	MODEL: FJ44-3A	MANUFACTURER: WILLIAMS INTERNATIONAL
INSTALLED ON: 20-FEB-2008		LAST ACTUALS:	PROJECTED:
1 ENG. HRS 1 A/C HRS		3036 ENG. HRS as of 28-JUL-2025	3087:47
ENC		2462 ENC as of 28-JUL-2025	2493
ENGINE NO. 2	SERIAL/PART: 141454/67000-200	MODEL: FJ44-3A	MANUFACTURER: WILLIAMS INTERNATIONAL
INSTALLED ON: 20-FEB-2008		LAST ACTUALS:	PROJECTED:
1 ENG. HRS 1 A/C HRS		3036 ENG. HRS as of 28-JUL-2025	3087:47
ENC		2462 ENC as of 28-JUL-2025	2493



New Requirement/Flagged Items

Operator Review and Action Required

Model: 525B - CJ3 Serial: 525B-0220 RegNo: OK-UMO HRS: 3036 AFL: 2457 As Of: 28-Jul-2025 Operator: AEROPARTNER A.S.

Report Date: 29-Jul-2025

These tasks or requirements have been added newly to your aircraft status. Please review them and approve or modify as appropriate. Please pay particular attention to the Base and Next Due Times for these tasks. It is important to note that any task that has insufficient information (marked by ?), will never come due unless the necessary information is provided by you.

PN & SN	Effective Date	Unit	Interval	Base Time		Next Due (ENG/APU) A/C	Disposition
				Current	Change To		
E083-250609		NO. 1 ENGINE - REVIEW FJ44-3A/-3A-24 LMM REV 63					Service ATA:00
	09-Jun-25	MOS	-	20-Feb-08	_____	TAC:0	REQUIREMENT CHANGE FORMS
		HRS			_____	TAC:0	
		ENC			_____	TAC:0	
NEW REQUIREMENT ADDED ON 18-JUN-25. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.				REF: RCF E083			
E083-250609		NO. 2 ENGINE - REVIEW FJ44-3A/-3A-24 LMM REV 63					Service ATA:00
	09-Jun-25	MOS	-	20-Feb-08	_____	TAC:0	REQUIREMENT CHANGE FORMS
		HRS			_____	TAC:0	
		ENC			_____	TAC:0	
NEW REQUIREMENT ADDED ON 18-JUN-25. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.				REF: RCF E083			
E083-250625		NO. 1 ENGINE - REVIEW FJ44-3A/-3A-24 LMM REV 64					Service ATA:00
		MOS	-	20-Feb-08	_____		REQUIREMENT CHANGE FORMS
		HRS			_____		
		ENC			_____		
NEW REQUIREMENT ADDED ON 14-JUL-25. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.				REF: RCF E083			
E083-250625		NO. 2 ENGINE - REVIEW FJ44-3A/-3A-24 LMM REV 64					Service ATA:00
		MOS	-	20-Feb-08	_____		REQUIREMENT CHANGE FORMS
		HRS			_____		
		ENC			_____		
NEW REQUIREMENT ADDED ON 14-JUL-25. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.				REF: RCF E083			

Name: _____ Signature: _____ Cert.# _____ Date: _____

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: 525B - CJ3 Serial: 525B-0220 RegNo: OK-UMO HRS: 3036 AFL: 2457 As
Of: 28-Jul-2025 Operator: AEROPARTNER A.S.

Report Date: 29-Jul-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
B342101		PS-855 (LEAD ACID) STANDBY GYRO BATTERY PACK PERIODIC TEST						Service ATA:34
PN:501-1712-01	MOS	6 (+2m)		06-Dec-24	30-Jun-25	31-Aug-25	TOL (+33 d)	29-Jul-2025
SN:81518	HRS			2759:25				
	AFL			2249				
	ACH							
REF: AMM 34-21-00								
32-USER-03 ^U		PERFORM A DYE PENETRANT INSPECTION (OH) ON ALL AREAS OF RH MLGWHEEL HALVES PER CMM						Service ATA:32
	MOS	24		19-Jul-23	31-Jul-25		2 d	31-Jul-2025
	HRS			2222:29				
	AFL			1818				
	ACH							
REF:								
D243201		CAPACITY CHECK BATTERY (NICKEL-CADMIUM)						Service ATA:24
PN:30978-002 - 9914058 -6	MOS	12 (+2m)		03-May-25	31-May-26	31-Jul-26	306 d (+61)	21-Aug-2025
SN:12401107	HRS	200 (+30)		2855:56	3055:56	3085:56	19:56 (+30)	
	AFL			2326				
REF: AMM 24-32-00								
WO#: FEB 24								
FAA 2024-26-02 PARA (G)(1)		INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE						AD ATA:25
	MOS	T:6		EFF	07-Sep-25 *		40 d	07-Sep-2025
	HRS							
	AFL							
Disposition: MANDATORY								
REF: AD								
237000A		CVR LOCATOR BEACON BATTERY						Component ATA:23
PN:810-2007/K	MOS	72	TSN:0	04-Nov-19	30-Sep-25		63 d	30-Sep-2025
SN:02282014	HRS			1367:49				
	AFL		TSN:0	1202				
REF: GENERIC NO REF								
313106		FDR LOCATOR BEACON BATTERY						Component ATA:31
PN:810-2007/K	MOS	72	TSN:0	04-Nov-19	30-Sep-25		63 d	30-Sep-2025
SN:-	HRS			1367:49				
	AFL							
Disposition: REPLACE								
REF: GENERIC NO REF								
CAMP ^U		OIL CONSUMPTION CHECK						Service ATA:--
	MOS	2		10-Jul-25	30-Sep-25		63 d	30-Sep-2025
	HRS	100		2990:01	3090:01		54:01	
	AFL			2429				
REF:								

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time