

**OWNER:** JETBEE CZECH S.R.O  
**ADDRESS:** K LETISTI 1073/25  
 PRAGUE 6 161 00  
**PHONE:** 420 605 991 191  
**FAX:**

**OPERATOR:** JETBEE CZECH S.R.O  
**ADDRESS:** K LETISTI 1073/25  
 PRAGUE 6 161 00  
**PHONE:** +420 296 188 089  
**FAX:**

**OPERATOR:** AEROMANAGEMENT EUROPE S.R.L.  
**ADDRESS:** CIAMPINO ROME 00043  
**PHONE:** +39-06-793-41495  
**FAX:** +1-410-573-1205

**ANALYST:** PIERRE-ALEXIS DI ROSA  
**EMAIL:** PA.DIROSA@CAMPSYSTEMS.EU

+33-1.55.93.45.91 (DIRECT)  
 +33 (0) 1.55.93.45.80 (OFFICE)  
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST  
 ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO  
 CAMP.

**Filter Criteria:** Task Type In: ('AD','ADP','SB','SBP'); Group by Profile or Bulletin: Profile Type; Mode: With Compliance or Next Due; For: Airframe,Engine,APU Etc;

**AIRCRAFT** **SERIAL/REGNO:** RK-293/OK-BEE

**MODEL:** BEECHJET 400A

**MANUFACTURER:** TEXTRON AVIATION INC.

<b>DATES</b>	<b>LAST ACTUALS</b>		<b>CURRENT ACTUAL</b>	
CERTIFICATION DATE: 25-OCT-2000 INSERVICE DATE: 25-OCT-2000	6105:23 A/C HRS	as of 28-JUN-2021	_____ A/C HRS	as of ____/____/____
	5695 AFL	as of 28-JUN-2021	_____ AFL	as of ____/____/____
	623 ACH	as of 28-JUN-2021	_____ ACH	as of ____/____/____

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>AIRFRAME - AD - RK-293/OK-BEE</b>							
FAA 1974-08-09 R02	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION (SUPERSEDED BY FAA AD 1974-08-09 R3)						COMPLIED WITH
39-9680 29-JUL-1996	MOS HRS/MSC - AFL			16-MAR-2007 1993 2202			
FAA 1974-08-09 R03	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION					MANDATORY	COMPLIED WITH
39-16951	MOS HRS/MSC 1000 AFL			17-SEP-2020 5696:47 5441	6696:47		RECURRING
FAA 1992-16-14	TO PREVENT FIRE AND POTENTIAL EXPLOSION OF THE FUSELAGE FUEL TANKS					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
39-8323 09-SEP-1992	MOS HRS/MSC - AFL						
FAA 1993-01-07	TO PREVENT SNAGGING OF THE END CLEVIS FITTING AND KINKING (AND SUBSEQUENT FAILURE) OF THE EMERGENCY RELEASE CABLE OF THE MAIN LANDING GEAR					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
39-8461 02-MAR-1993	MOS HRS/MSC - AFL						
FAA 1993-02-12	TO PREVENT THE LOSS OF STANDBY POWER AND THE POSSIBILITY OF AN ELECTRICAL FIRE					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
39-8495 23-MAR-1993	MOS HRS/MSC - AFL						
FAA 1993-09-11	TO PREVENT REDUCED STRUCTURAL INTEGRITY OF THE AFT FUEL FILLER TANK INSTALLATION					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
39-8577 17-JUN-1993	MOS HRS/MSC - AFL						
FAA 1993-16-12	TO PREVENT STRUCTURAL FAILURE OF THE EMERGENCY DOOR FRAME SUPPORT					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
39-8670 13-OCT-1993	MOS HRS/MSC - AFL						
FAA 1993-20-01	TO PREVENT SMOKE AND/OR FIRE IN THE COCKPIT					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
39-8708 02-NOV-1993	MOS HRS/MSC - AFL						
FAA 1993-25-15	TO PREVENT REDUCED STRUCTURAL CAPABILITY OF THE AIRFRAME					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
39-8779 14-FEB-1994	MOS HRS/MSC - AFL						
FAA 1994-04-07 PARA (A1) L/H	DEGRADATION OR LOSS OF BRAKING PERFORMANCE					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
39-8827 07-MAR-1994	MOS HRS/MSC - AFL						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 1994-04-07 PARA (A1) R/H	DEGRADATION OR LOSS OF BRAKING PERFORMANCE					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
39-8827 07-MAR-1994		MOS HRS/MSC - AFL					
FAA 1994-04-07 PARA (A2) L/H	DEGRADATION OR LOSS OF BRAKING PERFORMANCE					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
39-8827 07-MAR-1994		MOS HRS/MSC - AFL					
FAA 1994-04-07 PARA (A2) R/H	DEGRADATION OR LOSS OF BRAKING PERFORMANCE					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
39-8827 07-MAR-1994		MOS HRS/MSC - AFL					
FAA 1994-05-09 39-8847 07-APR-1994	TO PREVENT SEPARATION OF THE CABIN SEAT FRAMES FROM THEIR BASES DURING AN EMERGENCY LANDING					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
		MOS HRS/MSC - AFL					
FAA 1994-11-09 39-8925 07-JUL-1994	TO PREVENT LOSS OF CONTROL OF THE FUEL SUPPLY TO THE ENGINE OR LOSS OF CONTROL OF THE RETRACTION/EXTENSION SYSTEM FOR THE MAIN LANDING GEAR (MLG) AND MLG DOOR					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
		MOS HRS/MSC - AFL					
FAA 1994-25-10 39-9094	ICING CONDITIONS					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY
		MOS HRS/MSC - AFL					
FAA 1995-18-04 39-9352 10-OCT-1995	TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
		MOS HRS/MSC - AFL					
FAA 1995-25-05 39-9450 16-JAN-1996	TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE AFTER TAKEOFF					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
		MOS HRS/MSC - AFL					
FAA 1995-25-06 39-9451 16-JAN-1996	TO ENSURE THAT THE STANDBY INSTRUMENT LIGHTING SYSTEM ADEQUATELY ILLUMINATES THE STANDBY INSTRUMENT					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
		MOS HRS/MSC - AFL					
FAA 1996-03-07 39-9504 13-MAR-1996	TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE DUE TO A SHIFTING OF THE FLIGHTCREW SEAT DURING FLIGHT					SUPERSEDED	NOT APPLICABLE - BY SERIAL NUMBER
		MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 1996-25-03	TO PREVENT LOSS OF ROLLER ATTACH NUTS AND THE FLAP ROLLER					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
39-9845 24-JAN-1997		MOS HRS/MSC - AFL					
FAA 1998-06-30	TO PREVENT CRACKING AND CONSEQUENT FAILURE OF THE OUTFLOW/SAFETY VALVES					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
39-10408		MOS HRS/MSC - AFL					
FAA 1998-25-10 R1	TO PREVENT FAILURE OF THE SEAT RESTRAINT SYSTEM DUE TO THE BUCKLE ASSEMBLY (BUCKLE) LOCKING MECHANISM NOT ENGAGING PROPERLY					MANDATORY	NOT APPLICABLE - N/A DUE TO AMSAFE INC. MODEL INSTALLED
39-11460		MOS HRS/MSC - AFL		01-OCT-2002 615 555			
FAA 1999-21-08	FUEL DRAIN TUBE ASSEMBLY					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
39-11351 12-NOV-1999		MOS HRS/MSC - AFL					
FAA 1999-21-26	TO PREVENT UNCOMMANDDED NOSE-DOWN PITCH AT CERTAIN FLAP SETTINGS DURING ICING CONDITIONS					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
39-11372 22-NOV-1999		MOS HRS/MSC - AFL					
FAA 1999-23-22 R2	TO PREVENT FALSE ADVISORIES THAT DIRECT THE FLIGHTCREW TO CHANGE COURSE AND EITHER CLIMB OR DESCEND						NOT APPLICABLE
39-11686		MOS HRS/MSC - AFL					
FAA 2000-05-06	TO PREVENT FAILURE OF THE ENGINE FIRE EXTINGUISHER BOTTLE TO DISCHARGE, OR DISCHARGE OF THE WRONG ENGINE FIRE EXTINGUISHER BOTTLE					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
39-11615 12-APR-2000		MOS HRS/MSC - AFL					
FAA 2000-07-27	TO PREVENT LOSS OF THE MAIN SOURCES OF ATTITUDE DATA, CONSEQUENT HIGH PILOT WORKLOAD, AND A SIGNIFICANT INCREASE IN THE LIKELIHOOD OF PILOT ERROR					MANDATORY	NOT APPLICABLE - NO ADIRU INSTALLED
39-11683		MOS HRS/MSC - AFL		01-OCT-2002 615 555			
FAA 2000-09-12	TO PREVENT DETACHMENT OR BREAKAGE OF WIRES IN THE TEMPERATURE SWITCH ASSEMBLIES OF THE WING ICE PROTECTION SYSTEM					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
39-11721 16-JUN-2000		MOS HRS/MSC - AFL					
FAA 2000-25-04	TO PREVENT AN ASYMMETRIC BRAKING CONDITION AND A LONGER STOPPING DISTANCE DUE TO SUDDEN LOSS OF NORMAL BRAKING TO THE LEFT WHEEL					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY BY A/C S/N
39-12038 17-JAN-2001		MOS HRS/MSC - AFL		11-FEB-2011 2427:54 2685			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2001-03-06	TO PREVENT THE BLEED AIR SUPPLY TUBE ASSEMBLY FROM DISCONNECTING AND CONTACTING OTHER PNEUMATIC OR ELECTRICAL SYSTEMS OF THE AIRPLANE OR EXPELLING HIGH TEMPERATURE AIR ON SURROUNDING SYSTEMS AND STRUCTURE					MANDATORY	COMPLIED WITH
39-12110	MOS HRS/MSC 400 AFL			17-SEP-2020 5696:47 5441	6105:23 M	RECURRING	
FAA 2001-14-51	EMERGENCY AD - TO PREVENT USE OF INCORRECT BEARING INFORMATION BY THE PILOT					MANDATORY	NOT APPLICABLE - COLLINS SYSTEM INSTALLED
39-12351	MOS HRS/MSC - AFL			01-OCT-2002 615 555			
FAA 2001-15-17	TO PREVENT ERRONEOUS ALTITUDE INTERPRETATIONS					MANDATORY	NOT APPLICABLE - NO CTL-92 INSTALLED
39-12352	MOS HRS/MSC - AFL			01-OCT-2002 615 555			
FAA 2001-18-05	TO PREVENT THE POTENTIAL OF THESE TIRES EXPERIENCING TREAD SEPARATIONS DURING OPERATION					MANDATORY	NOT APPLICABLE - AFFECTED TIRES NOT INSTALLED ON THIS A/C
39-12431	MOS HRS/MSC - AFL			01-OCT-2002 615 555			
FAA 2001-20-07	TO PREVENT ELECTRICAL ARCING OR OVERHEATING OF THE GROUND CONNECTION IN THE AFT FUSELAGE AREA					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY BY A/C S/N
39-12455 15-NOV-2001	MOS HRS/MSC - AFL			11-FEB-2011 2427:54 2685			
FAA 2001-22-14	TO PREVENT DAMAGE TO FIRE EXTINGUISHING SYSTEM COMPONENTS CAUSED BY A FIRE EXTINGUISHING SYSTEM BOTTLE CARTRIDGE ACTIVATING WITH EXCESSIVE ENERGETIC FORCE					MANDATORY	NOT APPLICABLE - FIRE BOTTLE CARTRIDGES INSTALLED P/N 304000187 NOT AFFECTED
39-12493	MOS HRS/MSC - AFL			01-OCT-2002 615 555			
FAA 2001-23-17	TO PREVENT EXTERNAL NOISE FROM CAUSING INACCURATE COURSE DEVIATION DISPLAYS IN THE GNS 430 UNIT'S COURSE DEVIATION INDICATOR (CDI) OR HORIZONTAL SITUATION INDICATOR (HSI)					MANDATORY	NOT APPLICABLE - A/C NOT EQUIPPED WITH GNS430
39-12516	MOS HRS/MSC - AFL			01-OCT-2002 615 555			
FAA 2001-24-11	AFM - EMERGENCY PROCEDURES SECTION - LOSS OF AIRSPEED					MANDATORY	COMPLIED WITH
11-DEC-2001	MOS HRS/MSC - AFL			11-FEB-2011 2427:54 2685			
FAA 2002-01-23	LEFT ENGINE FORWARD BEAM AFT CARRY-THROUGH MOUNT BRACKET					MANDATORY	COMPLIED WITH
39-12617	MOS HRS/MSC 200 AFL			10-MAR-2021 5907:44 5592	6107:44	RECURRING	
FAA 2002-13-07	TO ENSURE THE CORRECT TRANSITION OF THE IRU TO BATTERY POWER UPON THE LOSS OF PRIMARY POWER					MANDATORY	NOT APPLICABLE - AFFECTED EQUIPMENT NOT INSTALLED, COLLINS PROLINE 4 INSTALLED
39-12795	MOS HRS/MSC - AFL			01-OCT-2002 615 555			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2002-14-19	TO PREVENT AN UNWARRANTED DISPLAY OF THE ADC FLAG WHEN SWITCHING STATIC AIR SOURCES					MANDATORY	NOT APPLICABLE - BY PART NUMBER COLLINS P/N 822-0389-433 INSTALLED IN A/C
39-12819		MOS		01-OCT-2002			
		HRS/MSC	-	615			
		AFL		555			
FAA 2002-15-02	INTENDED TO MANDATE THE REPLACEMENT OF THE AFFECTED COMPRESSOR WHEELS,					MANDATORY	NOT APPLICABLE - A/C NOT AFFECTED
39-12830		MOS		09-MAY-2003			
		HRS/MSC	-	796			
		AFL		897			
FAA 2002-20-09	TO PREVENT PREMATURE FAILURE OF THE ASIC, WHICH COULD RESULT IN THE AFD-3010 UNIT DISPLAYING ERRONEOUS PRIMARY FLIGHT AND ENGINE PARAMETER INFORMATION.					MANDATORY	NOT APPLICABLE - A/C NOT AFFECTED
39-12906		MOS		09-MAY-2003			
		HRS/MSC	-	796			
		AFL		897			
FAA 2002-21-01	TO PREVENT A FIRE IN THE GALLEY COMPARTMENT DUE TO INADEQUATE CRIMPING OF THE ELECTRICAL TERMINAL CONTACT PINS, WHICH COULD RESULT IN SMOKE IN THE COCKPIT AND CABIN AND LOSS OF CONTROL OF THE AIRPLANE					MANDATORY	NOT APPLICABLE - A/C NOT AFFECTED
39-12907		MOS		09-MAY-2003			
		HRS/MSC	-	796			
		AFL		897			
FAA 2002-22-12	TO PREVENT FAILURE OF A HOSE WHEN EXPOSED TO FIRE					MANDATORY	NOT APPLICABLE - A/C NOT AFFECTED
39-12938		MOS		09-MAY-2003			
		HRS/MSC	-	796			
		AFL		897			
FAA 2003-04-06	TO ENSURE THAT THE FLIGHTCREW HAS AN ACCURATE GLIDESLOPE DEVIATION INDICATION					MANDATORY	NOT APPLICABLE - A/C NOT AFFECTED
39-13054		MOS		09-MAY-2003			
		HRS/MSC	-	796			
		AFL		897			
FAA 2003-10-13	TO PREVENT LEAKAGE OF OXYGEN FROM SCORED LOW-PRESSURE OXYGEN TUBING					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY BY A/C S/N
39-13158 01-JUL-2003		MOS		11-FEB-2011			
		HRS/MSC	-	2427:54			
		AFL		2685			
FAA 2004-03-35	TO PREVENT INTERMITTENT STICKING OF THE RELAYS ON THE ROLL TRIM PRINTED CIRCUIT BOARD (PCB)					MANDATORY	COMPLIED WITH
39-13479 24-MAR-2004		MOS		11-FEB-2011			
		HRS/MSC	-	2427:54			
		AFL		2685			
FAA 2004-08-16	TO PREVENT LOSS OF AIRCRAFT AIRSPACE SEPARATION AND THE POSSIBILITY OF MID-AIR COLLISION					MANDATORY	NOT APPLICABLE - NOT APPLICABLE AS PER G-02309/13; AFFECTED UNITS NOT INSTALLED ON BOARD
39-13586		MOS		01-MAY-2004			
		HRS/MSC	-				
		AFL					
FAA 2004-10-15	SUPERSEDED BY AD 2005-01-19					SUPERSEDED	NOT APPLICABLE - AFFECTED UNITS NOT INSTALLED ON A/C
39-13645		MOS					
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2004-13-20	TO PREVENT ERRONEOUS INFORMATION FROM PLACING AN EXCESSIVE WORKLOAD ON THE FLIGHTCREW WHILE THEY MONITOR OTHER AVAILABLE NAVIGATION DATA TO AVOID DEVIATING OFF COURSE					MANDATORY	NOT APPLICABLE - AFFECTED UNITS NOT INSTALLED ON A/C
39-13702		MOS HRS/MSC - AFL		01-JUN-2004			
FAA 2004-16-14	TO PREVENT THE TA/RA VSI-TCAS INDICATOR FROM DISPLAYING A CONFLICTING "RA FAIL" MESSAGE DURING A MULTI-AIRCRAFT ENCOUNTER					MANDATORY	NOT APPLICABLE - UNIT NOT INSTALLED ON A/C
39-13770		MOS HRS/MSC - AFL		01-AUG-2004			
FAA 2004-21-04	TO PREVENT DIFFICULTY IN COMMUNICATING WITH AIR TRAFFIC CONTROL AND OTHER AIRCRAFT DUE TO INTERMITTENT MALFUNCTIONING OF THE TRANSCEIVER					MANDATORY	NOT APPLICABLE - AFFECTED UNITS NOT INSTALLED ON BOARD
39-13825		MOS HRS/MSC - AFL					
FAA 2004-22-02	TO PREVENT THE ACCUMULATION OF FUEL AND/OR FUEL VAPOR IN THE SPOILER MIXER BAY AND/OR THE AFT FUSELAGE COMPARTMENT					MANDATORY	COMPLIED WITH - PREVIOUSLY BY MSB 53-3486, 11/4/03
39-13830 01-DEC-2004		MOS HRS/MSC - AFL		11-FEB-2011 2427:54 2685			
FAA 2005-01-19	TO PREVENT INTERROGATING AIRCRAFT FROM POSSIBLY RECEIVING INACCURATE REPLIES					MANDATORY	NOT APPLICABLE - N/A BY MODEL INSTALLED
39-13944		MOS HRS/MSC - AFL					
FAA 2006-15-16	TO PREVENT OVER-VOLTAGE CONDITIONS OF THE DC STARTER GENERATOR					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY BY A/C S/N
39-14697 05-SEP-2006		MOS HRS/MSC - AFL		11-FEB-2011 2427:54 2685			
FAA 2006-21-02	TO ADVISE THE FLIGHTCREW THAT THE BUILDUP OF ICE ON CERTAIN INTERNAL AREAS OF THE ENGINE COULD RESULT IN A DUAL-ENGINE FLAMEOUT					MANDATORY	COMPLIED WITH
39-14785 25-OCT-2006		DAYs HRS/MSC - AFL		11-FEB-2011 2427:54 2685			
FAA 2007-19-05	TO PREVENT FAILURE OF THE ATTACHMENT FASTENERS ON THE ENGINE COWLING PANELS					MANDATORY	COMPLIED WITH - PREVIOUSLY PER MSB 54-3788 ON 3/22/2007
23-OCT-2007		MOS HRS/MSC - AFL		07-FEB-2011 2427:54 2685			
FAA 2007-24-01	TO PREVENT OVERHEATING OF WIRE INSULATION AND CONSEQUENT FIRE OR SMOKE IN THE AIRPLANE CABIN					MANDATORY	COMPLIED WITH - IAW THE AD P/C/W SB 25-3758 @ACTT:1993 ACTC:2681 MAR/07
39-15267		MOS HRS/MSC - AFL		20-SEP-2010 2416 2681			
FAA 2009-07-02	INSTALL AN IMPROVED ADJUSTMENT MECHANISM ON THE FLIGHTCREW SEAT					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY BY A/C S/N
39-15861 13-MAR-1996		MOS HRS/MSC - AFL		11-FEB-2011 2427:54 2685			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2010-11-05	AVOX SYSTEMS AND B/E AEROSPACE OXYGEN CYLINDERS AS INSTALLED ON VARIOUS 14 CFR PART 23 AND CAR 3 AIRPLANES					MANDATORY	NOT APPLICABLE
		DAYs		11-FEB-2011			
		HRS/MSC	-	2427:54			
		AFL		2685			
FAA 2011-03-12	DO A DETAILED INSPECTION FOR APPROPRIATE COVERAGE OF FIREWALL SEALANT OF THE LEFT AND RIGHT PYLON FIREWALL STRUCTURE					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER N/A BY A/F SERIAL NUMBER
39-16596 14-MAR-2011		MOS		(EFF)			
		HRS/MSC	-				
		AFL					
FAA 2013-03-07	ELECTRICAL POWER SYSTEM WIRING - FUSE REPLACEMENT					MANDATORY	NOT APPLICABLE - AD2013-03-07 P/C/W BY HAWKER BEECHCRAFT SERVICE CRS# BWVR672C ON FEBRUARY 11, 2011. WORK ACCOMPLISHED IAW SB33-4002.
39-17342 19-MAR-2013		MOS		02-DEC-2015			
		HRS/MSC	-	3725:18			
		AFL		3735			
FAA 2014-15-15 PARA (G)	PERFORM A RADIOGRAPHIC (X-RAY) INSPECTION OR A BORESCOPE INSPECTION FOR CRACKING OF THE HORIZONTAL STABILIZER RIB ASSEMBLIES					MANDATORY	
05-SEP-2014		MOS		(EFF)		RECURRING	
		HRS/MSC	7400		7400 M		
		AFL					
FAA 2014-21-06	FLIGHT CONTROLS - INSPECTION\REPLACEMENT OF PTAS HAVING A CERTAIN SERIAL NUMBER AND PART NUMBER					MANDATORY	NOT APPLICABLE
28-NOV-2014		MOS		02-DEC-2015			
		HRS/MSC	-	3725:18			
		AFL		3735			
FAA 2014-21-06 PARA (G)(H)	INSPECT TO DETERMINE THE SERIAL NUMBER AND PART NUMBER OF THE PTA, IF ANY SERIAL NUMBER AND PART NUMBER FOUND REPLACE THE PTA WITH A SERVICEABLE PTA OR AN OVERHAULED PTA HAVING AN ACME NUT AND JACKSCREW REPLACED WITH A NEW ACME NUT AND JACKSCREW					MANDATORY	NOT APPLICABLE - AD2014-21-06 AND SB27-4100 ARE N/A BY S/N INSTALLED. VERIFIED P/N 45AS61023 S/N ET0167.
28-NOV-2014		MOS		02-DEC-2015			
		HRS/MSC	-	3725:18			
		AFL		3735			
FAA 2014-21-06 PARA (I)	REPLACE THE PTA WITH A NEW PTA OR AN OVERHAULED PTA HAVING THE ACME NUT AND JACKSCREW REPLACED WITH A NEW ACME NUT AND JACKSCREW REPEAT AT EVERY PTA OVERHAUL					MANDATORY	COMPLIED WITH
28-NOV-2014		MOS		17-SEP-2020		RECURRING	
		HRS/MSC	1800	5696:47	7496:47		
		AFL		5441			
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A..1 SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - NOT AFFECTED BY PART NUMBER
15-JUL-2016		MOS		05-SEP-2016			
		HRS/MSC	-	3934:50			
		AFL		3927			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>APPLIANCE - RK-293/OK-BEE</b>							
EASA 2019-0235	APPLIANCE AD - EQUIPMENT / FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER - INSPECTION / MODIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - NOT AFFECTED PART ACCORDING TO AD DEFINITION
04-OCT-2019		MOS HRS/MSC - (s) AFL		28-OCT-2019			
EASA 2019-0235 PARA (1) THRU (4)	CONCURRENTLY ACCOMPLISH PARAS (1.1) AND (1.2) OF THIS AD AND ACCOMPLISH APPLICABLE CORRECTIVE ACTION(S) (IF, DISCREPANCIES ARE DETECTED, AS IDENTIFIED IN THE SIL); OPERATORS MAY CONTINUE TO USE ELTS WITH THE ORIGINAL G-SWITCHES BY REDUCING THE INTERVAL OF THE G-SWITCH TESTING, AS REQUIRED BY PARA (1.1)					MANDATORY	NOT APPLICABLE - NOT AFFECTED PART ACCORDING TO AD DEFINITION
04-OCT-2019		DAY HRS/MSC - AFL		28-OCT-2019 5299:09 5171			
EASA 2019-0235 PARA (5)	REMOVE THE AFFECTED PART FROM SERVICE IAW THE INSTRUCTIONS OF SECTION 7 OF THE SB FOR THE PURPOSE OF IN-SHOP MODIFICATION					MANDATORY	NOT APPLICABLE - NOT AFFECTED PART ACCORDING TO AD DEFINITION
04-OCT-2019		MOS HRS/MSC - AFL		28-OCT-2019 5299:09 5171			
FAA 1994-01-06	APPLIANCE AD - TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY
39-8788 04-FEB-1996		MOS HRS/MSC - AFL					
FAA 1994-19-06	APPLIANCE AD - SWEEP-ON MODEL 2000 CREW OXYGEN MASKS					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY
		MOS HRS/MSC - AFL					
FAA 1999-08-21	APPLIANCE AD - OXYGEN MASK INSPECTION					MANDATORY	NOT APPLICABLE - BY MFG DATE
39-11130		MOS HRS/MSC - AFL					
FAA 2002-06-05	APPLIANCE AD - MODE C 621A-3 AIR TRAFFIC CONTROL (ATC) TRANSPONDERS					MANDATORY	NOT APPLICABLE - BY PART NUMBER
03-MAY-2002		MOS HRS/MSC - AFL		01-OCT-2002 615 555			
FAA 2002-06-06	APPLIANCE AD - ROCKWELL COLLINS TDR-94 AND TDR-94D MODE S TRANSPONDERS					MANDATORY	NOT APPLICABLE
03-MAY-2002		MOS HRS/MSC - AFL		09-JUL-2004 1217 1391			
FAA 2002-22-13	APPLIANCE AD - NAVIGATION - REPLACEMENT OF ROCKWELL COLLINS FMC-4200, FMC-5000 AND FMC-6000 COMPUTERS TO PREVENT THE FMC FROM RETAINING ORIGINAL INFORMATION WHEN AN EDIT IS MADE TO A PROCEDURE OR FLIGHT PLAN					MANDATORY	COMPLIED WITH - FOUND FMC-5000 P/N 822-0891-008, S/N IC-70 AND S/N INDD INSTALLED
39-12939 20-DEC-2002		MOS HRS/MSC - AFL		09-MAY-2003 796 897			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2003-13-08 39-13208 21-JUL-2003	APPLIANCE AD - GOODRICH AVIONICS SYSTEMS INC. TAWS8000 TERRAIN AWARENESS WARNING SYSTEM			MOS HRS/MSC - (s) AFL		SUPERSEDED	NOT APPLICABLE - BY EFFECTIVITY
FAA 2003-26-14 39-13413 20-FEB-2004	APPLIANCE AD - KIDDE AEROSPACE PART NUMBER (P/N) 898052 HAND-HELD HALON FIRE EXTINGUISHERS			MOS HRS/MSC - AFL	09-JUL-2004 1217 1391	MANDATORY	COMPLIED WITH
FAA 2004-08-15 39-13584 07-JUN-2004	APPLIANCE AD - TO PREVENT THE LOADING OF THE BARO SET POTENTIOMETER			MOS HRS/MSC - AFL	04-JUN-2004	MANDATORY	NOT APPLICABLE - AFFECTED UNITS NOT INSTALLED
FAA 2006-16-18 39-14718 25-SEP-2006	APPLIANCE AD - SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI) UNITS			MOS HRS/MSC - AFL	07-OCT-2006 1788:49 2027	MANDATORY	NOT APPLICABLE - N/A BY INSTALLED MODEL (NO SANDEL)
FAA 2006-16-18 PARA (F) 39-14718 25-SEP-2006	INSTALL SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI) UNITS PLACARD			DAYs HRS/MSC - AFL	07-OCT-2006 1788:49 2027	MANDATORY	NOT APPLICABLE - N/A BY INSTALLED MODEL (NO SANDEL)
FAA 2006-16-18 PARA (G) 39-14718 25-SEP-2006	REVISE SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI) UNITS AIRPLANE FLIGHT MANUAL (AFM)			DAYs HRS/MSC - AFL	07-OCT-2006 1788:49 2027	MANDATORY	NOT APPLICABLE - N/A BY MODEL (NO SANDEL)MODEL
FAA 2006-16-18 PARA (H) 39-14718 25-SEP-2006	UPDATE SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI) UNITS SOFTWARE			DAYs HRS/MSC - AFL	07-OCT-2006 1788:49 2027	MANDATORY	NOT APPLICABLE
FAA 2006-16-18 R01 39-15557 18-JUL-2008	APPLIANCE AD - SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI) UNITS			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY EFFECTIVITY
FAA 2006-16-18 R01 PARA (F) 39-15557 18-JUL-2008	INSTALL SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI) UNITS PLACARD			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY EFFECTIVITY
FAA 2006-16-18 R01 PARA (G) 39-15557 18-JUL-2008	REVISE SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI) UNITS AIRPLANE FLIGHT MANUAL (AFM)			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY EFFECTIVITY

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks \*-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2006-16-18 R01 PARA (H)	UPDATE SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI) UNITS SOFTWARE					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY
39-15557 18-JUL-2008		MOS HRS/MSC - AFL					
FAA 2010-01-03	APPLIANCE AD - REPLACE PORTABLE HALON 1211 (BCF) FIRE EXTINGUISHERS MANUFACTURED BY FIRE FIGHTING ENTERPRISES LIMITED WITH SERVICEABLE FIRE EXTINGUISHERS					MANDATORY	NOT APPLICABLE - FFE EXTINGUISHERS NOT INSTALLED
39-16159 20-JAN-2010		DAYs HRS/MSC - AFL		11-FEB-2011 2427:54 2685			
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION					MANDATORY	NOT APPLICABLE - NOT AFFECTED
14-OCT-2014		MOS HRS/MSC - AFL		05-SEP-2016 3934:50 3927			
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS					MANDATORY	NOT APPLICABLE
01-JUL-2015		MOS HRS/MSC - AFL		12-AUG-2019 5189:31 5089			
FAA 2015-10-51-E	APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.					MANDATORY	NOT APPLICABLE
18-MAY-2015		MOS HRS/MSC - AFL		12-AUG-2019 5189:31 5089			
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - NOT AFFECTED BY PART NUMBER
15-JUL-2016		MOS HRS/MSC - AFL		05-SEP-2016 3934:50 3927			
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - NOT AFFECTED BY PART NUMBER
15-JUL-2016		MOS HRS/MSC - AFL		05-SEP-2016 3934:50 3927			
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - NOT AFFECTED BY PART NUMBER
15-JUL-2016		MOS HRS/MSC - AFL		05-SEP-2016 3934:50 3927			
FAA 2017-04-06	APPLIANCE AD - CABIN SYSTEMS - REPLACEMENT OF UNITED INSTRUMENTS INC. 5934 SERIES ALTIMETERS MANUFACTURED BETWEEN JANUARY 2015 AND FEBRUARY 2016					MANDATORY	NOT APPLICABLE - BY P/N INSTALLED
07-APR-2017		MOS HRS/MSC - AFL		23-MAR-2018 4642:28 4579			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS						NOT APPLICABLE - INSTALLED ARTEX P/N 406-2
24-OCT-2017		MOS		30-OCT-2018			
		HRS/MSC	-	4936:35			
		AFL		4833			
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT					MANDATORY	NOT APPLICABLE - N/A BY MANUFACTURER
24-OCT-2017		MOS		30-OCT-2018			
		HRS/MSC	- (s)	4936:35			
		AFL		4833			
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.					MANDATORY	NOT APPLICABLE - BY P/N INSTALLED
16-OCT-2017		MOS		14-APR-2018			
		HRS/MSC	-	4674:45			
		AFL		4609			
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS					MANDATORY	
09-DEC-2021		MOS		04-JAN-2022 M			
		HRS/MSC	DUE				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>AIRFRAME - SB - RK-293/OK-BEE</b>							
#	CZ CAA			ARC RENEWAL (AIRWORTHINESS REVIEW CERTIFICATE RENEWAL)		AIRWORTHINESS	
		MOS	12	22-JAN-2021	31-OCT-2022 M	RECURRING	
		HRS/MSC		5844:29			
		AFL		5541			
COM	89	CREW SEAT RESTRAINT SYSTEM, COMMUNIQUE				RECOMMENDED	NOT APPLICABLE
		MOS		11-FEB-2011			
	17-APR-2009	HRS/MSC	-	2427:54			
		AFL		2685			
COM	89 PART A	INSPECT CREW SEAT RESTRAINT SYSTEM, COMMUNIQUE CREW SEAT RESTRAINT SYSTEM				RECOMMENDED	NOT APPLICABLE
		DAYS		11-FEB-2011			
	17-APR-2009	HRS/MSC	-	2427:54			
		AFL		2685			
COM	89 PART B	REPLACE CREW SEAT RESTRAINT SYSTEM, COMMUNIQUE CREW SEAT RESTRAINT SYSTEM				RECOMMENDED	NOT APPLICABLE
		MOS		11-FEB-2011			
	17-APR-2009	HRS/MSC	-	2427:54			
		AFL		2685			
COM	MC126	400/400A (HAWKER 400XP) COMMUNIQUE - FLIGHT CONTROLS - FLAP CABLE INSPECTION, COMMUNIQUE				COMPLIED WITH	
		MOS		09-DEC-2019			
	01-JUN-2018	HRS/MSC	-	5307:28			
		AFL		5175			
SB	11-3666	PLACARDS & MARKINGS - EXTERNAL AFT BAGGAGE COMPARTMENT CAPACITY DECAL MODIFICATION, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH
		MOS		09-JUL-2004			
	01-MAY-2004	HRS/MSC	-	1217			
		AFL		1391			
SB	11-3863	PLACARDS AND MARKINGS - AFT FUSELAGE FUEL TANK FILLER ACCESS DOOR DECAL REMOVAL, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH
		MOS		11-FEB-2011			
	01-NOV-2007	HRS/MSC	-	2427:54			
		AFL		2685			
SB	21-2461 R01	ENVIRONMENTAL/AIR CONDITIONING - CABIN AND COCKPIT TEMPERATURE SENSOR BLOWER REPLACEMENT, SERVICE BULLETIN				OPTIONAL	NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		AFL					
SB	21-3238	ENVIRONMENTAL/AIR CONDITIONING - INSPECTION/INSTALLATION OF BLEED AIR RUPTURE INSULATION, SERVICE BULLETIN				MANDATORY	NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		AFL					
SB	21-3258	AIR CONDITIONING - AFT EVAPORATOR DRAIN INSTALLATION, SERVICE BULLETIN				RECOMMENDED	NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 21-3283	AIR CONDITIONING-CABIN TEMPERATURE SENSOR RELOCATION AND CABIN WINDOW DRY AIR SYSTEM REMOVAL, SERVICE BULLETIN			MOS HRS/MSC - AFL		RECOMMENDED	NOT APPLICABLE
SB 21-3289	AIR CONDITIONING - AFT CABIN HEAT VENT TEMPERATURE REDUCTION, SERVICE BULLETIN		01-JUL-2004	MOS HRS/MSC - AFL		RECOMMENDED	NOT APPLICABLE
SB 22-3003	AUTOFLIGHT - ELEVATOR, SPOILER AND RUDDER SERVO MOUNT INSPECTION/CLEANING/REPLACEMENT, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 22-3003 R01	AUTOFLIGHT - ELEVATOR, SPOILER AND RUDDER SERVO MOUNT INSPECTION/CLEANING/REPLACEMENT, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE
SB 22-3332	AUTO FLIGHT - MODIFICATION OF THE COLLINS FLIGHT CONTROL COMPUTERS (FCC-850) TO PROVIDE ENHANCED ELEVATOR TRIM OPERATION, SERVICE BULLETIN			MOS HRS/MSC - AFL		RECOMMENDED	NOT APPLICABLE
SB 22-3501	AUTO PILOT - SERVO ENGAGE CLUTCH TEETH LUBRICATION, SERVICE BULLETIN			MOS HRS/MSC - AFL	11-FEB-2011 2427:54 2685	MANDATORY	COMPLIED WITH
SB 23-3353	COMMUNICATIONS - INTERNATIONAL CIVIL AVIATION ORGANIZATION (ICAO) REQUIREMENT FOR 8.33 KHZ VHF COMM SPACING (RAYTHEON AIRCRAFT COMPANY STC ST09573SC), SERVICE BULLETIN			MOS HRS/MSC - AFL		OPTIONAL	NOT APPLICABLE
SB 24-3004 R01	ELECTRICAL POWER - STANDBY BATTERY TEST CIRCUIT MODIFICATION, SERVICE BULLETIN			MOS HRS/MSC - AFL		OPTIONAL	NOT APPLICABLE
SB 24-3010	ELECTRICAL POWER - ADDITION OF BUS-BAR INSULATOR IN THE MAIN JUNCTION BOX ASSEMBLY, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE
SB 24-3151	ELECTRICAL POWER - BATTERY GROUND TERMINAL INSPECTION/WASHER INSTALLATION, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 24-3199	ELECTRICAL POWER - RELOCATION OF THE 28 VDC POWER FOR THE ADF 1 SYSTEM FROM THE ELECTRICAL LOAD BUS TO THE EMERGENCY BUS, SERVICE BULLETIN				12-AUG-2019	RECOMMENDED	NOT APPLICABLE
	MOS HRS/MSC - AFL						
SB 24-3199 R01	ELECTRICAL POWER - RELOCATION OF THE 28 VDC POWER FOR THE ADF 1 SYSTEM FROM THE ELECTRICAL LOAD BUS TO THE EMERGENCY BUS, SERVICE BULLETIN				12-AUG-2019	RECOMMENDED	NOT APPLICABLE
	MOS HRS/MSC - AFL						
SB 24-3253	ELECTRICAL POWER - BATTERY AND EXTERNAL POWER GROUND IMPROVEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
	MOS HRS/MSC - AFL						
SB 24-3574	ELECTRICAL POWER - DC POWER SUPPLY INSTALLATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
01-AUG-2004	MOS HRS/MSC - AFL						
SB 24-3574 PART I	INSTALL ELECTRICAL POWER - DC POWER SUPPLY INSTALLATION, SERVICE BULLETIN KIT NO. 128-3054-5					RECOMMENDED	NOT APPLICABLE
01-AUG-2004	MOS HRS/MSC - AFL						
SB 24-3574 PART II	INSTALL ELECTRICAL POWER - DC POWER SUPPLY INSTALLATION, SERVICE BULLETIN KIT NO. 128-3054-1					OPTIONAL	NOT APPLICABLE
01-AUG-2004	MOS HRS/MSC - AFL						
SB 24-3713	ELECTRICAL POWER - GENERATOR CONTROL UNIT INSTALLATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY BY A/C SERIAL NUMBER
	MOS HRS/MSC - AFL						
SB 2435	ELECTRICAL PANELS, PARTS AND INSTRUMENTS - REPLACEMENT OF CURRENT SENSORS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
	MOS HRS/MSC - AFL						
SB 2445	FUEL-INSPECTION/REPLACEMENT OF AFT FUEL TANK VENT FLAME ARRESTOR FILTER, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
	MOS HRS/MSC - AFL						
SB 2446	EQUIPMENT/FURNISHINGS - INSPECTION/MODIFICATION OF CABIN SEAT FRAMES, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
	MOS HRS/MSC - AFL						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 2447	LANDING GEAR - REPLACEMENT OF MAIN LANDING GEAR DOOR UPLOCK LINKS, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2448	ICE AND RAIN PROTECTION - WING CLOSURE RIB SEALING, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2448 R01	ICE AND RAIN PROTECTION - WING CLOSURE RIB SEALING, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2458	ELECTRICAL PANELS, PARTS AND INSTRUMENTS - LH ITT CIRCUIT BREAKER WIRING CHANGE, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2459	WATER/WASTE - INSPECTION/MODIFICATION OF TOILET WIRING, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2462	ENGINE CONTROLS - IMPROVED RETENTION OF THRUST REVERSER POWER LEVER BEARINGS, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2468	FUEL - INSPECTION/INSTALLATION OF AFT FUEL FILLER TANK CLIPS, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2471	FLIGHT CONTROLS - ELEVATOR TENSION SPRING INSPECTION, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2473	NAVIGATION/PITOT STATIC - INSPECTION/MODIFICATION OF RH STATIC PORT HOSE CONNECTIONS, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2477	OIL - REPLACEMENT OF THE ENGINE OIL TEMPERATURE SENSOR, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2478	DOORS - EMERGENCY EXIT HANDLE HOOK MARKINGS, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 2478 R01	DOORS - EMERGENCY EXIT HANDLE HOOK MARKINGS, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2479	ELECTRICAL POWER - MAIN WHEEL WELL WIRE HARNESS CLAMPING INSPECTION/MODIFICATION, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2479 R01	ELECTRICAL POWER - MAIN WHEEL WELL WIRE HARNESS CLAMPING INSPECTION/MODIFICATION, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2482	FUSELAGE - INSPECTION/INSTALLATION OF FUSELAGE RIVETS, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 25-2536 R02	EQUIPMENT/FURNISHINGS - CREW SEAT STRUCTURE AND SEAT TRACK ADJUSTMENT MECHANISM IMPROVEMENT, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE
SB 25-3012	EQUIPMENT/FURNISHINGS - REWORK OF CABIN SEAT ADJUSTMENT MECHANISM, SERVICE BULLETIN			MOS HRS/MSC - AFL		RECOMMENDED	NOT APPLICABLE
SB 25-3575	EQUIPMENT AND FURNISHINGS - PASSENGER SEAT RAIL INSPECTION AND MODIFICATION, SERVICE BULLETIN			MOS HRS/MSC - AFL	19-NOV-2003 1011 1052	RECOMMENDED	COMPLIED WITH
01-JUL-2003							
SB 25-3689	EQUIPMENT/FURNISHINGS - CABIN SWIVELING CHAIR FRAME SEAT MODIFICATION, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
01-NOV-2005							
SB 25-3758	EQUIPMENT/FURNISHINGS - GALLEY POWER CIRCUIT PROTECTION IMPROVEMENT, SERVICE BULLETIN			MOS HRS/MSC - AFL	16-MAR-2007 1993 2202	MANDATORY	COMPLIED WITH
SB 2502	PLACARDS AND MARKINGS - INSTALLATION OF A SPEED BRAKE WARNING DECAL, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 2509	FUSELAGE - INSPECTION/REPLACEMENT OF ESCAPE HATCH SUBSTRUCTURE RIVETS, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2517	ELECTRICAL POWER - AFT WIRE HARNESS CONVOLEX TUBING INSTALLATION, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2520	ELECTRICAL POWER - PART I - ENGINE EFC START CIRCUIT PROTECTION; PART II - MAIN CIRCUIT BREAKER PANEL PROTECTION, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2522	FLIGHT CONTROLS - INSPECTION/REPLACEMENT OF FLAP ROLLER RETENTION COMPONENTS, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2522 R01	FLIGHT CONTROLS - INSPECTION/REPLACEMENT OF FLAP ROLLER RETENTION COMPONENTS, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2522 R02	FLIGHT CONTROLS - INSPECTION/REPLACEMENT OF FLAP ROLLER RETENTION COMPONENTS, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE
SB 2533	AUTO FLIGHT - AUTOPILOT AND RUDDER BOOST INTERLOCK IMPROVEMENT, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2533 R01	AUTO FLIGHT - AUTOPILOT AND RUDDER BOOST INTERLOCK IMPROVEMENT, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2535	FLIGHT CONTROLS - REPLACEMENT OF ELEVATOR HORN LEVER ASSEMBLIES, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2536	EQUIPMENT/FURNISHINGS - CREW SEAT STRUCTURE AND SEAT TRACK ADJUSTMENT MECHANISM IMPROVEMENTS, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 2536 R01	EQUIPMENT/FURNISHINGS - CREW SEAT STRUCTURE AND SEAT TRACK ADJUSTMENT MECHANISM IMPROVEMENTS, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2549	RIGHT LANDING GEAR - WHEEL SPEED TRANSDUCER DRIVE CLIP INSTALLATION, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2549	LEFT LANDING GEAR - WHEEL SPEED TRANSDUCER DRIVE CLIP INSTALLATION, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2549 R01	RIGHT LANDING GEAR - WHEEL SPEED TRANSDUCER DRIVE CLIP INSTALLATION, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2549 R01	LEFT LANDING GEAR - WHEEL SPEED TRANSDUCER DRIVE CLIP INSTALLATION, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2552	FUSELAGE - CABIN SEAT TRACK RIVET INSPECTION/INSTALLATION, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2552 R01	FUSELAGE - CABIN SEAT TRACK RIVET INSPECTION/INSTALLATION, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2563	LIGHTS - STANDBY INSTRUMENT LIGHTING CONTROL, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2587	ELECTRICAL PANELS, PARTS & INSTRUMENTS - CURRENT SENSOR INSPECTION/REPLACEMENT, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 26-3250	FIRE PROTECTION - ENGINE FIRE EXTINGUISHER BOTTLE SQUIB WIRING INSPECTION, MODIFICATION, AND LABELING, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 26-3250 R01	FIRE PROTECTION - ENGINE FIRE EXTINGUISHER BOTTLE SQUIB WIRING INSPECTION, MODIFICATION, AND LABELING, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE
SB 26-3803	FIRE PROTECTION - INSPECTION/REPLACEMENT OF MEGGITT THERMISTOR DETECTORS, SERVICE BULLETIN			MOS HRS/MSC - AFL	22-MAR-2007 1993 2203	N/A BY SERIAL NUMBER	NOT APPLICABLE - BY EFFECTIVITY
01-OCT-2006							
SB 2600	ICE AND RAIN PROTECTION - HORIZONTAL STABILIZER ICE PROTECTION IMPROVEMENT MODIFICATION, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2600 R01	ICE AND RAIN PROTECTION - HORIZONTAL STABILIZER ICE PROTECTION IMPROVEMENT MODIFICATION, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2664	WINGS - SPOILER CENTER HINGE MOUNTING BOLT REPLACEMENT, AND SPOILER INBOARD AND OUTBOARD HINGE ASSEMBLY INSPECTION/REPLACEMENT, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 2675	ICE AND RAIN PROTECTION - COCKPIT SIDE WINDOW DEFOG WIRING MODIFICATION, SERVICE BULLETIN			MOS HRS/MSC - AFL	03-SEP-2010 2416 2681	RECOMMENDED	COMPLIED WITH
SB 27-3005	FLIGHT CONTROLS - INSTALLATION OF THE PITCH TRIM INTERFACE CONTROLLER KIT, SERVICE BULLETIN			MOS HRS/MSC - AFL	02-DEC-2015 3725:18 3735	RECOMMENDED	NOT APPLICABLE
SB 27-3045	FLIGHT CONTROLS - MAIN FLAP ROD ASSEMBLY RIVET INSPECTION/REPLACEMENT, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE
SB 27-3229	FLIGHT CONTROLS - INSPECTION/IMPROVEMENT OF ANGLE OF ATTACK PRESSURE TRANSDUCERS, SERVICE BULLETIN			MOS HRS/MSC - AFL		RECOMMENDED	NOT APPLICABLE
SB 27-3241 R01	FLIGHT CONTROLS - HORIZONTAL STABILIZER POSITION TRANSMITTER LINK ASSEMBLY REPLACEMENT, SERVICE BULLETIN			MOS HRS/MSC - AFL		RECOMMENDED	NOT APPLICABLE

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 27-3464	FLIGHT CONTROLS - REPLACEMENT OF A194 ROLL TRIM PRINTED CIRCUIT BOARD (PCB), SERVICE BULLETIN					MANDATORY	COMPLIED WITH
	MOS			11-FEB-2011			
	HRS/MSC	-		2427:54			
	AFL			2685			
SB 27-3579	FLIGHT CONTROLS - SPOILER CONTROL CABLE TURNBUCKLE RETENTION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
01-FEB-2005	MOS						
	HRS/MSC	-					
	AFL						
SB 27-3579 R01	FLIGHT CONTROLS - SPOILER CONTROL CABLE TURNBUCKLE RETENTION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
01-MAY-2005	MOS						
	HRS/MSC	-					
	AFL						
SB 27-3827	FLIGHT CONTROLS - FLAP ASYMMETRY DETECTOR INSPECTION AND REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-MAR-2007	MOS			11-FEB-2011			
	HRS/MSC	-		2427:54			
	AFL			2685			
SB 27-4100	FLIGHT CONTROLS - INSPECTION / REPLACEMENT OF PITCH TRIM ACTUATOR, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
01-MAR-2012	MOS			17-SEP-2020			
	HRS/MSC	-		5696:47			
	AFL			5441			
SB 2707	FLIGHT CONTROLS - AFT FLAP CONTROL ROD ASSEMBLIES INSPECTION/REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
	MOS						
	HRS/MSC	-					
	AFL						
SB 2707 R01	FLIGHT CONTROLS - AFT FLAP CONTROL ROD ASSEMBLIES INSPECTION/REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
	MOS						
	HRS/MSC	-					
	AFL						
SB 2731	EQUIPMENT/FURNISHINGS - IMPROVED FLIGHT CREW SEAT "V" CABLE ROUTING, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
	MOS						
	HRS/MSC	-					
	AFL						
SB 2742	LIFTING AND SHORING - BONDING OF THE WING JACK PAD ASSEMBLY, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
	MOS						
	HRS/MSC	-					
	AFL						
SB 28-3076	FUEL - AFT FUEL TANK DRAIN LINE MODIFICATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
	MOS						
	HRS/MSC	-					
	AFL						
SB 28-3085	FUEL - COLLECTOR TANK MANIFOLD INSPECTION/REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
	MOS						
	HRS/MSC	-					
	AFL						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 28-3203	NO. 2 ENGINE INSTALLATION OF IMPROVED FUEL NOZZLES, SERVICE BULLETIN			MOS HRS/MSC - AFL		RECOMMENDED	NOT APPLICABLE
SB 28-3203	NO. 1 ENGINE INSTALLATION OF IMPROVED FUEL NOZZLES, SERVICE BULLETIN			MOS HRS/MSC - AFL		RECOMMENDED	NOT APPLICABLE
SB 28-3237	FUEL - IMPROVED CENTER TANK FUEL FLOAT VENT VALVE/WING TIP SURGE TANK FLAPPER VALVE, SERVICE BULLETIN			MOS HRS/MSC - AFL		RECOMMENDED	NOT APPLICABLE
SB 28-3237 R01	FUEL - IMPROVED CENTER TANK FUEL FLOAT VENT VALVE/WING TIP SURGE TANK FLAPPER VALVE, SERVICE BULLETIN			MOS HRS/MSC - AFL		RECOMMENDED	NOT APPLICABLE
01-MAY-2003							
SB 28-3427	FUEL - MOTIVE FLOW SHUTOFF VALVE REPLACEMENT, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 28-3469	REPLACEMENT OF FUEL CROSSFEED VALVE AND FUEL SHUTOFF VALVES, SERVICE BULLETIN			MOS HRS/MSC - AFL	19-NOV-2003 1011 1052	RECOMMENDED	COMPLIED WITH
01-FEB-2003							
SB 30-2600 R02	ICE AND RAIN PROTECTION - HORIZONTAL STABILIZER ICE PROTECTION IMPROVEMENT, SERVICE BULLETIN			MOS HRS/MSC - AFL	10-OCT-2002 615 555	MANDATORY	COMPLIED WITH - PREVIOUSLY
SB 30-3008	ICE AND RAIN PROTECTION - WING TEMPERATURE THERMAL SWITCH ASSEMBLY REPLACEMENT, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
SB 30-3008 R01	ICE AND RAIN PROTECTION - WING TEMPERATURE THERMAL SWITCH ASSEMBLY REPLACEMENT, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE
SB 30-3198	ICE AND RAIN PROTECTION - HORIZONTAL STABILIZER DEICE HEATING ELEMENT WIRING MODIFICATION, SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 30-4073	ICE AND RAIN PROTECTION - INSPECTION / REPLACEMENT OF HORIZONTAL STABILIZER DEICE SYSTEM SOLID STATE CONTACTOR, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
01-AUG-2011		MOS		01-AUG-2012			
		HRS/MSC	-	3451			
		AFL		3519			
SB 32-3120	LANDING GEAR - BRAKE MASTER CYLINDER REWORK, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		AFL					
SB 32-3200	LANDING GEAR - REPLACEMENT OF MAIN LANDING GEAR (MLG) EMERGENCY UPLOCK RELEASE CABLES, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		AFL					
SB 32-3300	LANDING GEAR - PARKING BRAKE HYDRAULIC LINE CLAMP INSTALLATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		AFL					
SB 32-3416	REPLACEMENT OF MAIN LANDING GEAR CYLINDERS, P/N 46010-15, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS		10-OCT-2002			
		HRS/MSC	-	615			
		AFL		555			
SB 32-3468	INSPECTION/REPLACEMENT OF P/N C100169 BRAKE MIXING VALVES, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
01-OCT-2001		MOS		11-FEB-2011			
		HRS/MSC	-	2427:54			
		AFL		2685			
SB 32-3873	LANDING GEAR - POSITION SWITCH INSPECTION/ADJUSTMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
01-FEB-2008		MOS		11-FEB-2011			
		HRS/MSC	-	2427:54			
		AFL		2685			
SB 32-3924	LANDING GEAR - NOSE LANDING GEAR (NLG) UPPER CYLINDER ASSEMBLY INSPECTION/REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
01-JAN-2009		MOS					
		HRS/MSC	-				
		AFL					
SB 33-3252	LIGHTS - CABIN ENTRANCE AISLE LIGHT ASSEMBLY MODIFICATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		AFL					
SB 33-3298	LIGHTS - FLASHING BEACON HARDWARE KIT IMPROVEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 33-3429	LIGHTS - ELECTROLUMINESCENT PANEL CIRCUIT BREAKER COLOR RING CHANGE, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS		19-NOV-2003			
		HRS/MSC	DUE	1011			
		AFL		1052			
SB 33-3832 R01	LIGHTS - PILOT'S AND COPILOT'S UTILITY LIGHT WIRE HARNESS UPGRADE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-OCT-2007		MOS		06-NOV-2007			
		HRS/MSC	-	2198:59			
		AFL		2419			
SB 33-3900	LIGHTS - INSPECTION / REPLACEMENT OF THE MAIN ENTRY DOOR EMERGENCY EXIT LIGHT LAMPS, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - IAW THE SB
01-MAY-2008		MOS		07-SEP-2010			
		HRS/MSC	-	2416			
		AFL		2681			
SB 33-3911	LIGHTS - INSPECTION OF THE MAIN ENTRANCE EMERGENCY EXIT SIGN, SERVICE BULLETIN					RECOMMENDED	DECLINED
01-SEP-2008		MOS					
		HRS/MSC	-				
		AFL					
SB 33-4002	LIGHTS - INSTRUMENT LIGHTING POWER SUPPLY WIRING MODIFICATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - AD2013-03-07 P/C/W BY HAWKER BEECHCRAFT SERVICE CRS# BWVR672C ON FEBRUARY 11, 2011. WORK ACCOMPLISHED IAW SB33-4002.
		MOS		02-DEC-2015			
		HRS/MSC	-	3725:18			
		AFL		3735			
SB 34-3006	NAVIGATION/PITOT STATIC - NOISE REDUCTION IN NAVIGATION AND COMMUNICATION FREQUENCIES, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		AFL					
SB 34-3228	NAVIGATION/PITOT STATIC - ANNOUNCEMENT OF THE COLLINS FMS-97 UPDATE TO THE FACTORY INSTALLED AMS-5000 SYSTEM, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		AFL					
SB 34-3236 R01	NAVIGATION - YEAR 2000 SOFTWARE ANOMALY, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
		MOS					
		HRS/MSC	-				
		AFL					
SB 34-3236 R03	NAVIGATION - YEAR 2000 SOFTWARE ANOMALY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		AFL					
SB 34-3273	NAVIGATION - REIDENTIFICATION OF THE AMS-5000 INSTALLATION IN THE FLIGHT MANUAL SUPPLEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 34-3284	NAVIGATION - MODIFICATION OF THE COLLINS FLIGHT CONTROL COMPUTERS (FCC-4007) TO PROVIDE ENHANCED ELEVATOR TRIM OPERATION, SERVICE BULLETIN			MOS HRS/MSC - AFL		RECOMMENDED	NOT APPLICABLE
SB 34-3356	NAVIGATION - CORRECTION OF A Y2K RELATED WRITE-TO-DISK FEATURE OF THE AMS-5000 FLIGHT MANAGEMENT COMPUTERS, SERVICE BULLETIN			MOS HRS/MSC - AFL	10-OCT-2002 615 555	RECOMMENDED	COMPLIED WITH
SB 34-3379	NAVIGATION - MODIFICATION OF THE GPS-4000 GLOBAL POSITIONING SENSOR (GPS) COLLINS PART NUMBER (CPN) 822-0931-002 TO THE CPN 822-0931-003 STATUS, SERVICE BULLETIN			MOS HRS/MSC - AFL	10-OCT-2002 615 555	RECOMMENDED	COMPLIED WITH
SB 34-3380 R01	NAVIGATION - AIR DATA COMPUTER INCREASED ACCURACY (COLLINS AMS-850), SERVICE BULLETIN			MOS HRS/MSC - AFL		OPTIONAL	NOT APPLICABLE
SB 34-3422	NAVIGATION - AIR DATA COMPUTER INCREASED ACCURACY (COLLINS AMS-5000), SERVICE BULLETIN			MOS HRS/MSC - AFL		OPTIONAL	NOT APPLICABLE
SB 34-3431	NAVIGATION - REDUCED VERTICAL SEPARATION MINIMUM (RVSM) AIRFRAME INSPECTION/MODIFICATION, SERVICE BULLETIN			MOS HRS/MSC - AFL	12-DEC-2000	OPTIONAL	COMPLIED WITH
SB 34-3432	NAVIGATION - INTRODUCTION OF TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) CHANGE 7, SERVICE BULLETIN			MOS HRS/MSC - AFL	12-AUG-2019	OPTIONAL	NOT APPLICABLE - TTR-921 INSTALLED TCAS 7.1
SB 34-3628	NAVIGATION - INSTALLATION OF IMPROVED PITOT PROBES, SERVICE BULLETIN			MOS HRS/MSC - AFL	10-DEC-2004 1412 1599	RECOMMENDED	COMPLIED WITH
01-NOV-2003							
SB 34-3716	NAVIGATION - AVIONICS MODIFICATION FOR ENHANCED FLIGHT IDENTIFICATION, SERVICE BULLETIN			MOS HRS/MSC - AFL	06-NOV-2007 2198:59 2419	OPTIONAL	COMPLIED WITH
01-APR-2006							
SB 34-3846	NAVIGATION - TRANSPONDER WIRING MODIFICATION, SERVICE BULLETIN			MOS HRS/MSC - AFL	06-NOV-2007 2198:59 2419	SUPERSEDED	COMPLIED WITH
01-JUL-2007							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 34-3846 R01	NAVIGATION - TRANSPONDER WIRING MODIFICATION, SERVICE BULLETIN					RECOMMENDED	DECLINED - NO ACTION TAKEN BY CUSTOMERS REQUEST
01-NOV-2007		MOS HRS/MSC - AFL		20-SEP-2010 2416 2681			
SB 34-4079	NAVIGATION - DUAL MODE (EMER/NORM) STANDBY COMPASS ALIGNMENT PROCEDURE AND COMPASS CARD, SERVICE BULLETIN					RECOMMENDED	DECLINED
01-AUG-2011		MOS HRS/MSC - AFL		15-FEB-2013 3708 3722			
SB 35-3333	OXYGEN - OXYGEN GAGE FACE PLATE INSPECTION/MODIFICATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS HRS/MSC - AFL		10-OCT-2002 615 555			
SB 35-3406	OXYGEN - REPLACEMENT OF LOW PRESSURE OXYGEN TUBES, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS HRS/MSC - AFL					
SB 36-3376	PNEUMATIC - BLEED AIR V-BAND COUPLING BOLT REPLACEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS HRS/MSC - AFL		25-MAY-2001 199:24			
SB 36-3376 R01	PNEUMATIC - BLEED AIR V-BAND COUPLING BOLT REPLACEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS HRS/MSC - AFL		10-OCT-2002 615 555			
SB 400-71-01 R01	POWER PLANT - INSTALLATION OF PRATT & WHITNEY SERVICE BULLETIN NUMBERS 7646 AND 7649 - INLET FLANGE SUPPORT PLATES AND FAN CASE DAMPER RING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
25-OCT-2019		MOS HRS/MSC - AFL		09-DEC-2019			
SB 52-3560	CABIN STEP HARDWARE INSPECTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-JUL-2003		MOS HRS/MSC - AFL		19-NOV-2003 1011 1052			
SB 53-3486	FUSELAGE - INSTALLATION OF DRAIN HOLES IN THE MIXER BAY PANELS, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS HRS/MSC - AFL		19-NOV-2003 1011 1052			
SB 53-3559	FUSELAGE - CORROSION INSPECTION/DRILLING OF DRAIN HOLE IN FUSELAGE BULKHEAD FRAME AT CANTED FUSELAGE STATION (CFS) 464.87, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-MAY-2003		MOS HRS/MSC - AFL		19-NOV-2003 1011 1052			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 53-4025	FUSELAGE - INSPECTION/REPLACEMENT OF IMPROPER FASTENERS IN RIGHT FUSELAGE ESCAPE HATCH AREA, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
01-MAR-2010		MOS HRS/MSC - AFL					
SB 54-3788	NACELLES - ENGINE COWLING FASTENER MODIFICATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS HRS/MSC - AFL		21-MAY-2012 3248:18 3355			
SB 54-3946	NACELLES - LEFT AND RIGHT PYLON FIREWALL INSPECTION AND SEALING, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
01-FEB-2009		MOS HRS/MSC - AFL					
SB 54-3946 R01	NACELLES - LEFT AND RIGHT PYLON FIREWALL INSPECTION AND SEALING, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
01-MAY-2009		MOS HRS/MSC - AFL					
SB 54-3946 R02	NACELLES - LEFT AND RIGHT PYLON FIREWALL INSPECTION AND SEALING, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
		MOS HRS/MSC - AFL					
SB 55-3505	VERTICAL STABILIZER ATTACH BOLT INSPECTION/REPLACEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
01-JAN-2003		MOS HRS/MSC - AFL		19-NOV-2003 1011 1052			
SB 55-4162	STABILIZERS - HORIZONTAL STABILIZER PIVOT FITTING AND UPPER REAR SPAR INSPECTION, SERVICE BULLETIN					MANDATORY	
19-JAN-2017		MOS HRS/MSC 7400 AFL		(EFF) 7400			
SB 57-3449	WING BOLT REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
		MOS HRS/MSC - AFL					
SB 71-3311	NO. 2 ENGINE REPLACEMENT OF ENGINE ISOLATOR MOUNTS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS HRS/MSC - AFL					
SB 71-3311	NO. 1 ENGINE REPLACEMENT OF ENGINE ISOLATOR MOUNTS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS HRS/MSC - AFL					
SB 72-3853	ENGINE - INSPECTION/REPLACEMENT OF BLEED AIR DUCT GASKET, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
01-SEP-2007		MOS HRS/MSC - AFL		06-NOV-2007 2198:59 2419			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-3354	NO. 2 ENGINE PART I OF THE ENGINE HYDROMECHANICAL METERING UNIT (HMU) P3 AIR CONDENSATION TRAP: PART II, HMU P3 AIR VENT IMPROVEMENT., SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE
SB 73-3354	NO. 1 ENGINE PART I OF THE ENGINE HYDROMECHANICAL METERING UNIT (HMU) P3 AIR CONDENSATION TRAP: PART II, HMU P3 AIR VENT IMPROVEMENT., SERVICE BULLETIN			MOS HRS/MSC - AFL		MANDATORY	NOT APPLICABLE
SB 73-3888	NO. 1 ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (HMU) P3 AIR DELIVERY TUBING MODIFICATION, SERVICE BULLETIN			MOS HRS/MSC - AFL		SUPERSEDED	- SCHEDULED
SB 73-3888	NO. 2 FUEL AND CONTROL - HYDROMECHANICAL UNIT (HMU) P3 AIR DELIVERY TUBING MODIFICATION, SERVICE BULLETIN			MOS HRS/MSC - AFL		SUPERSEDED	- SCHEDULED
SB 73-3888 R01	NO.1 ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (HMU) P3 AIR DELIVERY TUBING MODIFICATION, SERVICE BULLETIN				20-SEP-2010 2416 2681	RECOMMENDED	COMPLIED WITH - IAW THE SB
01-JUL-2008		MOS HRS/MSC - AFL					
SB 73-3888 R01	NO.2 ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (HMU) P3 AIR DELIVERY TUBING MODIFICATION, SERVICE BULLETIN			MOS HRS/MSC - AFL	20-SEP-2010 2416 2681	RECOMMENDED	COMPLIED WITH - IAW THE SB
01-JUL-2008		MOS HRS/MSC - AFL					
SB 74-3290	IGNITION - ENGINE IGNITION SYSTEM IMPROVEMENT, SERVICE BULLETIN			MOS HRS/MSC - AFL	10-OCT-2002 615 555	RECOMMENDED	COMPLIED WITH
SB 77-3088	ENGINE INDICATING - ENGINE VIBRATION INDICATION IMPROVEMENT, SERVICE BULLETIN			MOS HRS/MSC - AFL		OPTIONAL	NOT APPLICABLE
		MOS HRS/MSC - AFL					
SB 78-3011	EXHAUST - REPLACEMENT OF THRUST REVERSER STOW SWITCH, SERVICE BULLETIN			MOS HRS/MSC - AFL		RECOMMENDED	COMPLIED WITH
		MOS HRS/MSC - AFL					
SC 189 R01	INSPECTION - LEFT ENGINE CARRY THROUGH MOUNT BRACKET CRACKS, SAFETY COMMUNIQUE			MOS HRS/MSC - AFL	07-OCT-2006 1788:49 2027	RECOMMENDED	COMPLIED WITH
		MOS HRS/MSC - AFL					