

OWNER: EISELE FLUGDIENST GMBH
ADDRESS: GAT - GEBAEUDE - FLUGHAFEN
 STUTTGART
 STUTTGART 70629
PHONE: 49-711-9988770
FAX: 49-711-9988772

OPERATOR: EISELE FLUGDIENST GMBH
ADDRESS: GAT - GEBAEUDE - FLUGHAFEN
 STUTTGART
 STUTTGART 70629
PHONE: 49-711-9988770
FAX: 49-711-9988772

ANALYST: PIERRE DEBLONDE +33.1.55.93.45.96 (DIRECT)
EMAIL: PIERRE.DEBLONDE@CAMPSYSTEMS.EU +33 (0) 1.55.93.45.80 (OFFICE)
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Task Type In: ('AD','ADP','SB','SBP'); Group by Profile or Bulletin: Profile Type; For: Airframe,Engine,APU Etc;

AIRCRAFT	SERIAL/REGNO:	680-0185/D-CEIS	MODEL:	680 - CITATION SOVEREIGN	MANUFACTURER:	TEXTRON AVIATION INC.
			DATES	LAST ACTUALS	CURRENT ACTUAL	
			CERTIFICATION DATE: 01-FEB-2008	9344:01 A/C HRS as of 12-MAR-2025	A/C HRS	as of ____/____/____
				8035 AFL as of 12-MAR-2025	AFL	as of ____/____/____
				3628 APH as of 26-APR-2025	APH	as of ____/____/____
				9068 APS as of 26-APR-2025	APS	as of ____/____/____
APU	SERIAL/PART:	P-353/3800785-1	MODEL:	RE100CS	MANUFACTURER:	HONEYWELL
			INSTALLED ON 01-FEB-2008	LAST ACTUALS	CURRENT ACTUAL	
			0 APU HRS	3628 APU HRS as of 26-APR-2025	APU HRS	as of ____/____/____
			0 APUS	9068 APUS as of 26-APR-2025	APUS	as of ____/____/____
ENGINE NO. 1	SERIAL/PART:	PCE-CG0375/30B4258-01	MODEL:	PW306C	MANUFACTURER:	PRATT & WHITNEY CANADA CORP.
			INSTALLED ON 25-MAR-2019	LAST ACTUALS	CURRENT ACTUAL	
			5955 ENG. HRS 6089:30 A/C HRS	9210:10 ENG. HRS as of 12-MAR-2025	ENG. HRS	as of ____/____/____
			5506 ENC	7890 ENC as of 12-MAR-2025	ENC	as of ____/____/____
ENGINE NO. 2	SERIAL/PART:	PCE-CG0376/30B4258-01	MODEL:	PW306C	MANUFACTURER:	PRATT & WHITNEY CANADA CORP.
			INSTALLED ON 01-JUL-2022	LAST ACTUALS	CURRENT ACTUAL	
			7578:07 ENG. HRS 7711:58 A/C HRS	9210:10 ENG. HRS as of 12-MAR-2025	ENG. HRS	as of ____/____/____
			6684 ENC	7890 ENC as of 12-MAR-2025	ENC	as of ____/____/____

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - AD - 680-0185/D-CEIS							
EASA 2009-0100	AUXILIARY POWER UNIT - EXHAUST THERMAL INSULATION - REPLACEMENT					MANDATORY	NOT APPLICABLE - BY TYPE AND MODEL
18-MAY-2009	MOS HRS/MSC - AFL			27-MAY-2014 3039:30 3409			
EASA 2009-0100 PARA PARA (1)	INSPECT AUXILIARY POWER UNIT - EXHAUST THERMAL INSULATION - REPLACEMENT					MANDATORY	NOT APPLICABLE - BY TYPE AND MODEL
18-MAY-2009	MOS HRS/MSC - AFL			27-MAY-2014 3039:30 3409			
EASA 2009-0100 PARA PARA (2)	REPLACE AUXILIARY POWER UNIT - EXHAUST THERMAL INSULATION - REPLACEMENT					MANDATORY	NOT APPLICABLE - BY TYPE AND MODEL
18-MAY-2009	MOS HRS/MSC - AFL			27-MAY-2014 3039:30 3409			
EASA 2016-0167 R01	EQUIPMENT / FURNISHINGS - REAR CABIN ATTENDANT SEAT - INSPECTION / REPAIR					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 09 MAR 2018 // WO CEIS-04/18
02-FEB-2018	MOS HRS/MSC - AFL APH APS						
EASA 2021-0185 R01	FIRE PROTECTION - HAND-OPERATED FIRE EXTINGUISHERS - INSPECTION / REPLACEMENT						NOT APPLICABLE - MAKE AND MODEL NOT INSTALLED // CHECKDATE 25 NOV 2021 // WO CEIS-19/21
	MOS HRS/MSC AFL APH APS						
FAA 2012-07-04	INSTALL A KIT, PART NUMBER (P/N) SB680-24-11, TO THE LEFT AND RIGHT MOTIVE FLOW RELAYS, IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS OF CESSNA SERVICE BULLETIN SB680-24-11, REVISION 1					MANDATORY	COMPLIED WITH - AD 2012-07-04 : SB ORIGINAL 680-24-11 C/W 22 FEB 11 AT 1540 H. AND R1 STEP 13 C/W 24 FEB 12 AT 2058 HOURS.
39-17010	MOS HRS/MSC - AFL			31-OCT-2012 2333:54 2601			
FAA 2012-11-09 R01	OXYGEN - INSTALLING A SUPPLEMENTAL OXYGEN SYSTEM IN AFFECTED LAVATORIES					MANDATORY	NOT APPLICABLE - NOT ADOPTED BY EASA PER DECISION AS OF 03 AUG 2015
27-JUL-2015	MOS HRS/MSC - AFL						
FAA 2012-11-09 R01 PARA (G)	ACTIVATE ALL CHEMICAL OXYGEN GENERATORS IN THE LAVATORIES UNTIL THE GENERATOR OXYGEN SUPPLY IS EXPENDED OR REMOVE THE OXYGEN GENERATOR (S) AND REMOVE OR RE-STOW THE OXYGEN MASKS AND CLOSE THE MASK DISPENSER DOOR (FOR EACH CHEMICAL OXYGEN GENERATOR, AFTER THE GENERATOR IS EXPENDED (OR REMOVED))					MANDATORY	NOT APPLICABLE - NOT ADOPTED BY EASA PER DECISION AS OF 03 AUG 2015
27-JUL-2015	MOS HRS/MSC - AFL						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2012-11-09 R01 PARA (L)	INSTALL A SUPPLEMENTAL OXYGEN SYSTEM THAT MEETS ALL APPLICABLE SECTIONS OF PARTS 25 AND 121 OF THE FEDERAL AVIATION REGULATIONS (14 CFR PART 25 AND 14 CFR PART 121) IN EACH LAVATORY			MOS HRS/MSC - AFL			NOT APPLICABLE - NOT ADOPTED BY EASA PER DECISION AS OF 03 AUG 2015
27-JUL-2015							
FAA 2014-05-27	NAVIGATION - ROCKWELL COLLINS, INC. TPR-720 AND TPR-900 MODE S TRANSPONDERS - TEST AND CALIBRATION			MOS HRS/MSC - AFL	24-APR-2014 3026 3394	MANDATORY	NOT APPLICABLE
18-MAY-2015							
FAA 2015-10-51-E	AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.			MOS HRS/MSC - AFL	31-MAY-2015 3481 3742	MANDATORY	NOT APPLICABLE - NOT APPLICABLE - EQUIPMENT NOT INSTALLED
39-18325 28-DEC-2015							
FAA 2015-23-09	OXYGEN - ZODIAC AEROTECHNIKS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS			MOS HRS/MSC - AFL	02-FEB-2016 4024 4118	MANDATORY	NOT APPLICABLE - NOT APPLICABLE - P/N NOT INSTALLED
39-18547 15-JUL-2016							
FAA 2016-11-20	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12			MOS HRS/MSC - AFL APH APS	02-AUG-2016 4327 4340 1769 4931	MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
15-JUL-2016							
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12			MOS HRS/MSC - AFL APH APS	02-AUG-2016 4327 4340 1769 4931	MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
15-JUL-2016							
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12			MOS HRS/MSC - AFL APH APS	02-AUG-2016 4327 4340 1769 4931	MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
15-JUL-2016							
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12			MOS HRS/MSC - AFL APH APS	02-AUG-2016 4327 4340 1769 4931	MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
15-JUL-2016							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2017-04-06	CABIN SYSTEMS - REPLACEMENT OF UNITED INSTRUMENTS INC. 5934 SERIES ALTIMETERS MANUFACTURED BETWEEN JANUARY 2015 AND FEBRUARY 2016					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
07-APR-2017		MOS		23-JAN-2018			
		HRS/MSC	-	5426:01			
		AFL		5094			
FAA 2017-06-13	PREVENTION OF DISBONDING OF THE HORIZONTAL AND VERTICAL STIFFENERS ON THE AFT CANTED BULKHEAD					MANDATORY	COMPLIED WITH - SB 680-53-08 - 18-APR-2016 AT 4097HRS AND 4165AFL
39-18837		MOS		13-APR-2017			
02-MAY-2017		HRS/MSC	-	4834:54			
		AFL		4676			
		APH		1937			
		APS		5302			
FAA 2017-06-13 PARA (G) (H)	PERFORM A GENERAL VISUAL INSPECTION FOR DISBONDING AND PAINT CRACKING AROUND THE EDGES OF THE STIFFENERS ON THE AFT CANTED BULKHEAD. IF ANY DISBONDING OR CRACKING PAINT IS FOUND OBTAIN AND ACCOMPLISH REPAIR INSTRUCTIONS.					MANDATORY	NOT APPLICABLE - MODIFICATION ALREADY PERFORMED WITH SB 680-53-08 - 18-APR-2016 AT 4097HRS AND 4165AFL
02-MAY-2017		MOS		13-APR-2017			
		HRS/MSC	-	4834:54			
		AFL		4676			
		APH		1937			
		APS		5302			
FAA 2017-06-13 PARA (I)	MODIFY THE AIRPLANE BY INSTALLING ADDITIONAL STIFFENERS ON THE AFT CANTED BULKHEAD					MANDATORY	COMPLIED WITH - SB 680-53-08 - 18-APR-2016 AT 4097HRS AND 4165AFL
02-MAY-2017		MOS		13-APR-2017			
		HRS/MSC	-	4834:54			
		AFL		4676			
		APH		1937			
		APS		5302			
FAA 2017-16-01	EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETITIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
39-18978		MOS		24-NOV-2017			
24-OCT-2017		HRS/MSC	-	5333:08			
		AFL		5026			
		APH		2101			
		APS		5693			
FAA 2017-18-12	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
39-19021		MOS		24-NOV-2017			
16-OCT-2017		HRS/MSC	-	5333:08			
		AFL		5026			
		APH		2101			
		APS		5693			
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
16-OCT-2017		MOS		24-NOV-2017			
		HRS/MSC	-	5333:08			
		AFL		5026			
		APH		2101			
		APS		5693			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
16-OCT-2017		MOS		24-NOV-2017			
		HRS/MSC	-	5333:08			
		AFL		5026			
		APH		2101			
		APS		5693			
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
16-OCT-2017		MOS		24-NOV-2017			
		HRS/MSC	-	5333:08			
		AFL		5026			
		APH		2101			
		APS		5693			
FAA 2017-22-14	NAVIGATION - INSTALLATION OF THE TSSA-4100 FLS UPGRADES ON THE ROCKWELL COLLINS, INC. TSS-4100 TRAFFIC SURVEILANCE SYSTEM PROCESSING UNITS					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
20-DEC-2017		MOS		23-JAN-2018			
		HRS/MSC	-	5426:01			
		AFL		5094			
FAA 2018-03-04	NAVIGATION - REPLACEMENT OF ROSEMOUNT AEROSPACE INC. MODEL 851AK PITOT PROBES REPAIRED BY CSI AEROSPACE INC					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 09 MAR 2018 // WO CEIS-04/18
16-MAR-2018		MOS					
		HRS/MSC	-				
		AFL					
		APH					
		APS					
FAA 2018-07-13	LANDING GEAR - INSPECTION OF THE BRAKE PAD WEAR INDICATOR PINS AND REPLACEMENT OF THE BRAKE ASSEMBLY IF ANY PIN IS FOUND TO HAVE AN INCORRECT LENGTH					MANDATORY	COMPLIED WITH - SL680-32-15 - 10 AUG 2017 AT 5117:47 HOURS AND 4874 CYCLES // CHECKDATE 12 JUN 2018 // WO CEIS-11/18
39-19244 15-MAY-2018		MOS					
		HRS/MSC	-				
		AFL					
FAA 2019-12-09	NAVIGATION - FDSA-6500 TCAS - AFM OR AFMS LIMITATIONS SECTION - REVISION / PLACARD INSTALLATION (SUPERSEDED BY FAA AD 2021-05-17)					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 16 SEP 2019 // WO CEIS-15/19
		DAYS					
		HRS/MSC	-				
		AFL					
		APH					
		APS					
FAA 2021-05-17	NAVIGATION - ROCKWELL COLLINS FDSA-6500 FLIGHT DISPLAY SYSTEM - OPERATING LIMITIATIONS / SOFTWARE UPGRADE					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 27 APR 2021 // WO CEIS-07/21
		MOS					
		HRS/MSC	-				
		AFL					
		APH					
		APS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2021-05-17 PARA (G)(1) & (G)(2)	REVISE THE AIRCRAFT FLIGHT MANUAL (AFM) OR AFM SUPPLEMENT (AFMS), FABRICATE A PLACARD FOR EACH PRIMARY FLIGHT DISPLAY AND INSTALL THE PLACARD ON THE BOTTOM OF EACH PRIMARY FLIGHT DISPLAY BEZEL (RESTATEMENT OF FAA AD 2019-12-09)					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 27 APR 2021 // WO CEIS-07/21
29-APR-2021		MOS HRS/MSC	-				
		AFL APH APS					
FAA 2021-05-17 PARA (G)(3)	UPGRADE THE FDSA-6500 FIELD LOADABLE SOFTWARE					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 27 APR 2021 // WO CEIS-07/21
29-APR-2021		MOS HRS/MSC	-				
		AFL APH APS					
FAA 2021-05-17 PARA (G)(5)	AS OF THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL A ROCKWELL COLLINS FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500 P/N 810-0234-1H0001, 810-0234-1H0002, 810-0234-1H0003, 810-0234-2H0001, 810-0234-2C0001, 810-0234-2C0002, OR 810-0234-4B0001 ON ANY AIRPLANE					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 27 APR 2021 // WO CEIS-07/21
29-APR-2021		MOS HRS/MSC	-				
		AFL APH APS					
FAA 2022-04-09	OXYGEN - OXYGEN VALVE ASSEMBLIES, AND OXYGEN CYLINDER AND VALVE ASSEMBLIES - INSPECT / REPLACE					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 22 JUN 2022 // WO CEIS-02/22
		MOS HRS/MSC	-				
		AFL APH APS					
FAA 2022-04-09 PARA (H) & (I)	INSPECT THE OXYGEN VALVE ASSEMBLIES, AND OXYGEN CYLINDER AND VALVE ASSEMBLIES, TO DETERMINE IF AN EFFECTED PART INSTALLED; IF INSTALLED, BEFORE FURTHER FLIGHT, DO A DETAILED INSPECTION FOR CORRECT SPACING OF THE GAP BETWEEN THE BOTTOM OF THE PACKING RETAINER AND TOP OF THE VALVE BODY AND PERFORM CORRECTIVE ACTIONS					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 22 JUN 2022 // WO CEIS-02/22
04-APR-2022		MOS HRS/MSC	-				
		AFL APH APS					
FAA 2022-04-09 PARA (J)	REPORT THE RESULTS OF THE INSPECTION					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 22 JUN 2022 // WO CEIS-02/22
04-APR-2022		MOS HRS/MSC	-				
		AFL APH APS					
LBA D-2012-192	ELECTRICAL POWER - MOTIVE FLOW RELAYS - INSTALLATION					MANDATORY	COMPLIED WITH - SB ORIGINAL 680-24-11 C/W 22 FEB 11 AT 1540 H. AND R1 STEP 13 C/W 24 FEB 12 AT 2058 HOURS.
17-APR-2012		MOS HRS/MSC	-	31-OCT-2012 2333:54 2601			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
APPLIANCE - 680-0185/D-CEIS							
CAA UK G-2021-0003	APPLIANCE AD - EQUIPMENT / FURNISHINGS - LIFE JACKET - INSPECTION					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 03 AUG 2021 // WO CEIS-16/21
		MOS					
		HRS/MSC					
		AFL					
		APH					
		APS					
CAA UK G-2021-0004	APPLIANCE AD - EQUIPMENT / FURNISHINGS - LIFE RAFT - INSPECTION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 03 AUG 2021 // WO CEIS-16/21
		MOS					
		HRS/MSC	-				
		AFL					
		APH					
		APS					
CAA UK G-2021-0004 PARA (1) & (2)	PERFORM INSPECTION AND FUNCTIONAL CHECK OF LIFE RAFT IN ACCORDANCE WITH ALERT SERVICE BULLETIN 25-197-A; IF DISCREPANCIES ARE DETECTED, REMOVE AND REPLACE THE AFFECTED PART WITH A NEW OR SERVICEABLE PART					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 03 AUG 2021 // WO CEIS-16/21
		MOS					
		HRS/MSC					
		AFL					
		APH					
		APS					
CAA UK G-2021-0004 PARA (4)	REPORT THE INSPECTION RESULTS (INCLUDING NO FINDINGS) TO SURVITEC					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 03 AUG 2021 // WO CEIS-16/21
		DAYS					
		HRS/MSC					
		AFL					
		APH					
		APS					
CAA UK G-2022-0009	APPLIANCE AD - EQUIPMENT / FURNISHINGS - LIFEJACKETS - INSPECTION					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 22 JUN 2022 // WO CEIS-02/22
		MOS					
		HRS/MSC	-				
		AFL					
		APH					
		APS					
CAA UK G-2022-0011	APPLIANCE AD - ATA 25 - EQUIPMENT / FURNISHINGS - PILOT & CO-PILOT SEATS - INSPECTION / MODIFICATION					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 18 AUG 2022 // WO CEIS-07/22
23-JUN-2022		MOS					
		HRS/MSC	-				
		AFL					
		APH					
		APS					
CAA UK G-2022-0011 PARA (1)	INSPECT ANY AFFECTED SPRING OF EACH AFFECTED SEAT IN ACCORDANCE WITH THE INSTRUCTIONS OF THE INSPECTION SB (SB 063-25-14)					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 18 AUG 2022 // WO CEIS-07/22
23-JUN-2022		MOS					
		HRS/MSC					
		AFL					
		APH					
		APS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CAA UK G-2022-0011 PARA (2)	REPLACE BOTH SPRINGS IN ACCORDANCE WITH THE INSTRUCTIONS OF THE INSPECTION SB (SB 063-25-14)					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 18 AUG 2022 // WO CEIS-07/22
23-JUN-2022		MOS HRS/MSC - AFL APH APS					
CAA UK G-2022-0011 PARA (4)	MODIFY AND RE-IDENTIFY EACH AFFECTED SEAT					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 18 AUG 2022 // WO CEIS-07/22
23-JUN-2022		MOS HRS/MSC AFL APH APS					
CAA UK G-2025-0002	APPLIANCE AD - PILOT & CO-PILOT SEATS - INSPECTION / MODIFICATION					MANDATORY	NOT APPLICABLE - MAKE AND MODEL NOT INSTALLED // CHECKDATE 25 APR 2025 // WO CEIS-05/25
25-APR-2025		MOS HRS/MSC - AFL APH APS					
EASA 2006-0334 R01	APPLIANCE AD - THALES COMMUNICATIONS VHF DATA RADIO MODIFICATION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
		MOS HRS/MSC - AFL		30-SEP-2014 3160 3512			
EASA 2008-0097	APPLIANCE AD - EQUIPMENT & FURNISHINGS – PASSENGER SEATS – INSPECTION / REPAIR / MODIFICATION - SICMA AERO SEAT					MANDATORY	NOT APPLICABLE - A/C NOT EQUIPPED WITH
		MOS HRS/MSC - AFL		17-FEB-2014 2972:12 3326			
EASA 2008-0135	APPLIANCE AD - EQUIPMENT & FURNISHINGS - PASSENGER SEAT BACKREST - REPLACEMENT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
		MOS HRS/MSC - AFL		17-FEB-2014 2972:12 3326			
EASA 2008-0158 R2	APPLIANCE AD - NAVIGATION – MODE-S TRANSPONDERS – LIMITATION - FILSER ELECTRONIC GMBH					MANDATORY	NOT APPLICABLE - A/C NOT EQUIPPED WITH
		MOS HRS/MSC - AFL		17-FEB-2014 2972:12 3326			
EASA 2008-0159	APPLIANCE AD - NAVIGATION SYSTEMS - MODE-S TRANSPONDER - MODIFICATION /REPLACEMENT					MANDATORY	NOT APPLICABLE - BY PART NUMBER (P/N 7517400-950).
08-SEP-2008		MOS HRS/MSC - AFL		17-FEB-2014 2972:12 3326			
EASA 2008-0183	APPLIANCE AD - NAVIGATION - MODE-S TRANSPONDERS - REPLACEMENT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
		MOS HRS/MSC - AFL		17-FEB-2014 2972:12 3326			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2009-0173	APPLIANCE AD - NAVIGATION - MODE S TRANSPONDER - MODIFICATION/REPLACEMENT					MANDATORY	NOT APPLICABLE - A/C NOT EQUIPPED WITH
		MOS		17-FEB-2014			
		HRS/MSC	-	2972:12			
		AFL		3326			
EASA 2009-0173 R1	APPLIANCE AD - NAVIGATION – MODE S TRANSPONDER – MODIFICATION / REPLACEMENT - ROCKWELL COLLINS INC.				MANDATORY		NOT APPLICABLE - A/C NOT EQUIPPED WITH
		MOS		17-FEB-2014			
		HRS/MSC	-	2972:12			
		AFL		3326			
EASA 2009-0251-E	APPLIANCE/EMERGENCY AD - PORTABLE HALON 1211 FIRE EXTINGUISHERS					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER FIRE EXTINGUISHER.
26-NOV-2009		MOS		17-FEB-2014			
		HRS/MSC	-	2972:12			
		AFL		3326			
EASA 2009-0262 R01	APPLIANCE AD - HALON 1211 FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - A/C NOT FITTED WITH THESE TYPE OF EQUIPMENT.
29-DEC-2009		MOS		17-FEB-2014			
		HRS/MSC	-	2972:12			
		AFL		3326			
EASA 2009-0278	APPLIANCE AD - FIRE PROTECTION - PORTABLE HALON 1211 FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - A/C NOT FITTED WITH THESE TYPE OF EQUIPMENT.
05-JAN-2010		MOS		17-FEB-2014			
		HRS/MSC	-	2972:12			
		AFL		3326			
EASA 2009-0278 PARA (1)	IDENTIFY FIRE PROTECTION - PORTABLE HALON 1211 FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT SERIAL NUMBER OF FIRE EXTINGUISHER					MANDATORY	NOT APPLICABLE - A/C NOT FITTED WITH THESE TYPE OF EQUIPMENT.
05-JAN-2010		DAYS		17-FEB-2014			
		HRS/MSC	-	2972:12			
		AFL		3326			
EASA 2009-0278 PARA (2)	RETURN FIRE PROTECTION - PORTABLE HALON 1211 FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT DEFECTIVE FIRE EXTINGUISHER					MANDATORY	NOT APPLICABLE - A/C NOT FITTED WITH THESE TYPE OF EQUIPMENT.
05-JAN-2010		DAYS		17-FEB-2014			
		HRS/MSC	-	2972:12			
		AFL		3326			
EASA 2010-0003 R02	APPLIANCE AD - NAVIGATION - MODE S TRANSPONDER AIRCRAFT TYPE MODE STRAPPING - CHECK / MODIFICATION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
14-OCT-2014		MOS		30-SEP-2014			
		HRS/MSC	-	3160			
		AFL		3512			
EASA 2010-0003 R02 PARA (1)	VERIFY AIRCRAFT TYPE MODE STRAPPING CODE S SET TO '0' (ZERO) OR '1', AS DEFINED IN ROCKWELL-COLLINS SERVICE LETTER TDR-94() SIL 07-2.					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
14-OCT-2014		MOS		30-SEP-2014			
		HRS/MSC	-	3160			
		AFL		3512			
EASA 2010-0003 R02 PARA (2)	EXEMPTIONS: DASSAULT AEROPLANES					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
14-OCT-2014		MOS		30-SEP-2014			
		HRS/MSC	-	3160			
		AFL		3512			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2010-0003 R02 PARA (3)	EXEMPTIONS: ATR 42 AND ATR 72 AEROPLANES					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
14-OCT-2014		MOS HRS/MSC - AFL		30-SEP-2014 3160 3512			
EASA 2010-0003 R02 PARA (4)	EXEMPTIONS: SAAB 2000 AEROPLANES					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
14-OCT-2014		MOS HRS/MSC - AFL		30-SEP-2014 3160 3512			
EASA 2010-0003 R02 PARA (5)	EXEMPTIONS: BOMBARDIER AEROSPACE (CANADAIR) AEROPLANES: CL-600-2B16 (604 VARIANT) AND CL-600-2B19 (RJ100 AND RJ200)					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
14-OCT-2014		MOS HRS/MSC - AFL		30-SEP-2014 3160 3512			
EASA 2010-0003 R02 PARA (6)	EXEMPTIONS: CESSNA AIRCRAFT COMPANY AEROPLANES: CESSNA MODEL 525, 525A, 525B, 560; 560XL					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
14-OCT-2014		MOS HRS/MSC - AFL		30-SEP-2014 3160 3512			
EASA 2010-0003 R02 PARA (7)	EXEMPTIONS: PIAGGIO AERO INDUSTRIES AEROPLANES: P.180 (AVANTI) AND P.180 (AVANTI II)					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
14-OCT-2014		MOS HRS/MSC - AFL		30-SEP-2014 3160 3512			
EASA 2010-0062 R1	APPLIANCE AD - FIRE PROTECTION - HALON 1211 FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT - FIRE FIGHTING ENTERPRISES LIMITED					MANDATORY	NOT APPLICABLE - A/C NOT FITTED WITH THESE TYPE OF EQUIPMENT.
		MOS HRS/MSC - AFL		17-FEB-2014 2972:12 3326			
EASA 2010-0067	APPLIANCE AD - NAVIGATION - MODE S TRANSPONDER - CHECK / MODIFICATION					MANDATORY	NOT APPLICABLE - BY PART NUMBER OF TRANSPONDERS.
06-MAY-2009		MOS HRS/MSC - AFL		17-FEB-2014 2972:12 3326			
EASA 2010-0152	APPLIANCE AD - EQUIPMENT AND FURNISHING - OXYGEN MASK REGULATOR - MODIFICATION - INTERTECHNIQUE					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT USED BY CESSNA
		MOS HRS/MSC - AFL		17-FEB-2014 2972:12 3326			
EASA 2010-0204	APPLIANCE AD - NAVIGATION SYSTEMS – MODE-S TRANSPONDER – MODIFICATION / REPLACEMENT - ROCKWELL-COLLINS INC.					MANDATORY	NOT APPLICABLE
		MOS HRS/MSC - AFL		17-FEB-2014 2972:12 3326			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2011-0090 R1	APPLIANCE AD - OXYGEN – OXYGEN MASK REGULATOR INFLATABLE HARNESS – IDENTIFICATION / REPLACEMENT - INTERTECHNIQUE (PART OF ZODIAC AEROSPACE), EROS					MANDATORY	COMPLIED WITH - AD EASA 2011-0090 R1 "OXYGEN – OXYGEN MASK REGULATOR INFLATABLE HARNESS – IDENTIFICATION / REPLACEMENT - INTERTECHNIQUE" COMPLIED WITH.
		MOS		02-DEC-2011			
		HRS/MSC	-	1941:36			
		AFL		2168			
EASA 2011-0094	APPLIANCE AD - EQUIPMENT & FURNISHINGS - LIFE JACKET VACUUM BAG - MODIFICATION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
		MOS		17-FEB-2014			
		HRS/MSC	-	2972:12			
		AFL		3326			
EASA 2011-0103	APPLIANCE AD - EQUIPMENT / FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER (ELT) ANTENNA - MODIFICATION / REPLACEMENT - CHELTON LIMITED					MANDATORY	NOT APPLICABLE - ANTENNA ELT P/N S65-8282-406 INSTALLED.
		DAYS		17-FEB-2014			
		HRS/MSC	-	2972:12			
		AFL		3326			
EASA 2011-0239	APPLIANCE AD - INSTRUMENTS - RADIO ALTIMETER INDICATOR - MODIFICATION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
		MOS		17-FEB-2014			
		HRS/MSC	-	2972:12			
		AFL		3326			
EASA 2012-0037	APPLIANCE AD - FIRE PROTECTION - HAND OPERATED FIRE EXTINGUISHER - MODIFICATION - KIDDE GRAVINE (A HAMILTON SUNDSTRAND COMPANY)					MANDATORY	NOT APPLICABLE - A/C NOT EQUIPPED WITH.
		MOS		17-FEB-2014			
		HRS/MSC	-	2972:12			
		AFL		3326			
EASA 2012-0038	APPLIANCE AD - EQUIPMENT & FURNISHINGS - PASSENGER SEAT BACKREST LINK - INSPECTION/REPLACEMENT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
		MOS		17-FEB-2014			
		HRS/MSC	-	2972:12			
		AFL		3326			
EASA 2012-0254	APPLIANCE AD - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR -IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
13-DEC-2012		MOS		02-FEB-2016			
		HRS/MSC	-	4024			
		AFL		4118			
EASA 2012-0254 PARA (1)	INSPECT/CHECK OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR -IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT OXYGEN MASK REGULATOR TO IDENTIFY THE P/N AND S/N					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
13-DEC-2012		MOS		02-FEB-2016			
		HRS/MSC	-	4024			
		AFL		4118			
EASA 2012-0254 PARA (2.1)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR -IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT AFFECTED OXYGEN MASK REGULATOR					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
13-DEC-2012		MOS		02-FEB-2016			
		HRS/MSC	-	4024			
		AFL		4118			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2012-0254 PARA (2.2)	AMEND OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT AIRCRAFT FLIGHT MANUAL (AFM)					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
13-DEC-2012		MOS		02-FEB-2016			
		HRS/MSC	-	4024			
		AFL		4118			
EASA 2012-0254 PARA (3)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR WITH A SERVICEABLE PART					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
13-DEC-2012		MOS		02-FEB-2016			
		HRS/MSC	-	4024			
		AFL		4118			
EASA 2012-0254 R01	APPLIANCE AD - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
21-DEC-2012		MOS		02-FEB-2016			
		HRS/MSC	-	4024			
		AFL		4118			
EASA 2012-0254 R01 PARA (1)	INSPECT OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT EACH FLIGHT CREW OXYGEN MASK REGULATOR TO IDENTIFY THE P/N AND S/N					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
21-DEC-2012		DAYS		02-FEB-2016			
		HRS/MSC	-	4024			
		AFL		4118			
EASA 2012-0254 R01 PARA (2.1)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR WITH A SERVICEABLE PART					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
21-DEC-2012		DAYS		02-FEB-2016			
		HRS/MSC	-	4024			
		AFL		4118			
EASA 2012-0254 R01 PARA (2.2)	AMEND OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT THE AIRCRAFT FLIGHT MANUAL (AFM) AND INSTALL A PLACARD					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
21-DEC-2012		DAYS		02-FEB-2016			
		HRS/MSC	-	4024			
		AFL		4118			
EASA 2012-0254 R01 PARA (3)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
21-DEC-2012		MOS		02-FEB-2016			
		HRS/MSC	-	4024			
		AFL		4118			
EASA 2013-0020 R04	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - ALL SEAT BELT SYSTEMS INSTALLED SINCE FACTORY / CF
11-JUL-2014		MOS		30-SEP-2014			
		HRS/MSC	-	3160			
		AFL		3512			
EASA 2013-0020 R04 PARA (1)	INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER					MANDATORY	NOT APPLICABLE - ALL SEAT BELT SYSTEMS INSTALLED SINCE FACTORY / CF
11-JUL-2014		MOS		30-SEP-2014			
		HRS/MSC	-	3160			
		AFL		3512			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2013-0020 R04 PARA (2)	VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD					MANDATORY	NOT APPLICABLE - ALL SEAT BELT SYSTEMS INSTALLED SINCE FACTORY / CF
11-JUL-2014		MOS HRS/MSC - AFL		30-SEP-2014 3160 3512			
EASA 2013-0020 R04 PARA (3)	REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE					MANDATORY	NOT APPLICABLE - ALL SEAT BELT SYSTEMS INSTALLED SINCE FACTORY / CF
11-JUL-2014		MOS HRS/MSC - AFL		30-SEP-2014 3160 3512			
EASA 2013-0020 R04 PARA (4)	AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD					MANDATORY	NOT APPLICABLE - ALL SEAT BELT SYSTEMS INSTALLED SINCE FACTORY / CF
11-JUL-2014		MOS HRS/MSC - AFL		30-SEP-2014 3160 3512			
EASA 2014-0019	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR - MODIFICATION AIRCRAFT FLIGHT MANUAL - AMENDMENT (SUPERSEDED BY EASA 2014-0095)					MANDATORY	NOT APPLICABLE
31-JAN-2014		MOS HRS/MSC - AFL		24-APR-2014 3026 3394			
EASA 2014-0019 PARA (1)	AMEND THE AFM OF THE AFFECTED AIRCRAFT					MANDATORY	NOT APPLICABLE
31-JAN-2014		DAYS HRS/MSC - AFL		24-APR-2014 3026 3394			
EASA 2014-0019 PARA (2)	REPLACE THE SYSTEM INTERFACE UNIT P/N 503-24-() OR 503-42-()					MANDATORY	NOT APPLICABLE
31-JAN-2014		MOS HRS/MSC - AFL		24-APR-2014 3026 3394			
EASA 2014-0019 PARA (3)	DO NOT INSTALL A HR SMITH (TECHNICAL DEVELOPMENTS) CPI SYSTEM SERIES 15-503-134 OR 15-503-134-1 EQUIPPED WITH CONTROL PANEL P/N 503-22-(), BEACON RELEASE UNIT P/N 503-21 AND SYSTEM INTERFACE UNIT P/N 503-24-() OR P/N 503-42-(), EXCLUDING SYSTEM INTERFACE UNIT P/N 503-24-A, OR 503-24-()A, OR 503-24-G, OR 503-24-()G, OR 503-42-A OR 503-42-()A OR 503-42-G OR 503-42-()G, ON AN AIRCRAFT, UNLESS IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD					MANDATORY	NOT APPLICABLE
31-JAN-2014		MOS HRS/MSC - AFL		24-APR-2014 3026 3394			
EASA 2014-0019 PARA (4)	REMOVE AFM AMENDMENT AND PLACARD AS REQUIRED BY PARAGRAPH (1) OF THIS AD					MANDATORY	NOT APPLICABLE
31-JAN-2014		MOS HRS/MSC - AFL		24-APR-2014 3026 3394			
EASA 2014-0088	APPLIANCE AD - COMMUNICATIONS - COCKPIT VOICE RECORDER - REPLACEMENT					MANDATORY	NOT APPLICABLE
29-APR-2014		MOS HRS/MSC - AFL		24-APR-2014 3026 3394			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2014-0088 PARA (1)	REMOVE THE TEAM CVR P/N AP71232101 OR P/N AP71231101, AS APPLICABLE, FROM THE AIRCRAFT AND, DEPENDING ON OPERATIONAL REGULATIONS, INSTALL A SERVICEABLE CVR IN ACCORDANCE WITH APPROVED AIRCRAFT MODIFICATION INSTRUCTIONS					MANDATORY	NOT APPLICABLE
29-APR-2014		MOS HRS/MSC AFL		24-APR-2014 3026 3394			
EASA 2014-0088 PARA (2)	DO NOT INSTALL ON ANY AIRCRAFT A TEAM CVR P/N AP71232101 OR P/N AP71231101, AS REQUIRED BY PARAGRAPH (2.1) OR (2.2) OF THIS AD, AS APPLICABLE					MANDATORY	NOT APPLICABLE
29-APR-2014		MOS HRS/MSC AFL		24-APR-2014 3026 3394			
EASA 2014-0095 R01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR - MODIFICATION AIRCRAFT FLIGHT MANUAL - AMENDMENT					MANDATORY	NOT APPLICABLE - BY AIRPLANE NOT EQUIPPED WITH HR SMITH CPI SYSTEM
12-MAY-2014		MOS HRS/MSC AFL		09-JUN-2014 3055:12 3428			
EASA 2014-0095 R01 PARA (1)	INSTALL A PLACARD "DO NOT USE TRANSMIT OVER WATER" NEXT TO THE CPI CONTROL PANEL/AMEND THE AFM OF THE AIRCRAFT					MANDATORY	NOT APPLICABLE - BY AIRPLANE NOT EQUIPPED WITH HR SMITH CPI SYSTEM
12-MAY-2014		MOS HRS/MSC AFL		09-JUN-2014 3055:12 3428			
EASA 2014-0095 R01 PARA (2)	INCORPORATION OF APPENDIX A OF THIS AD INTO THE EMERGENCY PROCEDURES SECTION OF THE AFM OF THE AIRCRAFT IS AN ACCEPTABLE METHOD TO COMPLY WITH THE REQUIREMENT OF PARAGRAPH (1.2) OF THIS AD					MANDATORY	NOT APPLICABLE - BY AIRPLANE NOT EQUIPPED WITH HR SMITH CPI SYSTEM
12-MAY-2014		MOS HRS/MSC AFL		09-JUN-2014 3055:12 3428			
EASA 2014-0095 R01 PARA (3)	REPLACE THE SYSTEM INTERFACE UNIT P/N 503-24-() (INCLUDING 503-24) OR P/N 503-42-() (INCLUDING 503-42) WITH AN IMPROVED PART P/N 503-24-A, OR P/N 503-24-()A, OR P/N 503-24-G, OR P/N 503-24-()G, OR P/N 503-42-A OR P/N 503-42-()A OR P/N 503-42-G OR P/N 503-42-()G (THAT INCORPORATES AUTOMATIC CPI DEPLOYMENT AFTER MANUAL ACTIVATION) IN ACCORDANCE WITH AN APPROVED AIRCRAFT MAINTENANCE INSTRUCTION					MANDATORY	NOT APPLICABLE - BY AIRPLANE NOT EQUIPPED WITH HR SMITH CPI SYSTEM
12-MAY-2014		MOS HRS/MSC AFL		09-JUN-2014 3055:12 3428			
EASA 2014-0095 R01 PARA (4)	DO NOT INSTALL A HR SMITH (TECHNICAL DEVELOPMENTS) CPI SYSTEM SERIES 15-503-134 OR 15-503-134-1 EQUIPPED WITH CONTROL PANEL P/N 503-22-(), BEACON RELEASE UNIT P/N 503-21 AND SYSTEM INTERFACE UNIT P/N 503-24-() (INCLUDING 503-24) OR P/N 503-42-() (INCLUDING 503-42) EXCLUDING SYSTEM INTERFACE UNIT P/N 503-24-A OR P/N 503-24-()A OR P/N 503-24-G OR P/N 503-24-()G OR P/N 503-42-A OR P/N 503-42-()A OR P/N 503-42-G OR P/N 503-42-()G ON AN AIRCRAFT UNLESS IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD					MANDATORY	NOT APPLICABLE - BY AIRPLANE NOT EQUIPPED WITH HR SMITH CPI SYSTEM
12-MAY-2014		MOS HRS/MSC AFL		09-JUN-2014 3055:12 3428			
EASA 2014-0095 R01 PARA (5)	REMOVE THE AFM AMENDMENT AND PLACARD AS REQUIRED BY PARAGRAPH (1) OF THIS AD					MANDATORY	NOT APPLICABLE - BY AIRPLANE NOT EQUIPPED WITH HR SMITH CPI SYSTEM
12-MAY-2014		MOS HRS/MSC AFL		09-JUN-2014 3055:12 3428			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2014-0125	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR SYSTEM - REPLACEMENT; AIRCRAFT FLIGHT MANUAL - AMENDMENT					MANDATORY	NOT APPLICABLE - BY AIRPLANE NOT EQUIPPED WITH HR SMITH CPI SYSTEM
22-MAY-2014		MOS HRS/MSC - AFL		09-JUN-2014 3055:12 3428			
EASA 2014-0125 PARA (1)	AMEND THE AFM OF AFFECTED AIRCRAFT TO INCORPORATE TEMPORARY CPI SIU OPERATING PROCEDURES BY INSERTING A COPY OF APPENDIX 1 OF THIS AD (OR ITS TEXT) INTO THE APPLICABLE NORMAL PROCEDURES SECTION OF THE AFM					MANDATORY	NOT APPLICABLE - BY AIRPLANE NOT EQUIPPED WITH HR SMITH CPI SYSTEM
22-MAY-2014		MOS HRS/MSC - AFL		09-JUN-2014 3055:12 3428			
EASA 2014-0125 PARA (2)	ACCOMPLISH THE COMPLETE START-UP PROCEDURE/APPLICABLE START-UP PROCEDURE/SHUTDOWN PROCEDURE					MANDATORY	NOT APPLICABLE - BY AIRPLANE NOT EQUIPPED WITH HR SMITH CPI SYSTEM
22-MAY-2014		MOS HRS/MSC - AFL		09-JUN-2014 3055:12 3428			
EASA 2014-0125 PARA (3)	COMPLIANCE WITH THE REQUIREMENTS OF PARAGRAPH (2) OF THIS AD					MANDATORY	NOT APPLICABLE - BY AIRPLANE NOT EQUIPPED WITH HR SMITH CPI SYSTEM
22-MAY-2014		MOS HRS/MSC - AFL		09-JUN-2014 3055:12 3428			
EASA 2014-0125 PARA (4)	REPLACE THE CPI SIU HAVING P/N 503-24 OR P/N 503-24-2 OR P/N 503-24-6 WITH AN IMPROVED UNIT P/N 503-24G OR P/N 503-24-2G OR P/N 503-24-6G IN ACCORDANCE WITH THE APPLICABLE AIRCRAFT DESIGN APPROVAL HOLDER SERVICE INSTRUCTIONS AND, CONCURRENTLY, REMOVE THE TEMPORARY AFM PROCEDURE AS REQUIRED BY PARAGRAPH (2) OF THIS AD					MANDATORY	NOT APPLICABLE - BY AIRPLANE NOT EQUIPPED WITH HR SMITH CPI SYSTEM
22-MAY-2014		MOS HRS/MSC - AFL		09-JUN-2014 3055:12 3428			
EASA 2014-0125 PARA (5)	MODIFICATION OF AN AIRCRAFT AS REQUIRED BY PARAGRAPH (4) OF THIS AD CONSTITUTES TERMINATING ACTION FOR ACCOMPLISHMENT OF THE PROCEDURES AS REQUIRED BY PARAGRAPH (2) OF THIS AD					MANDATORY	NOT APPLICABLE - BY AIRPLANE NOT EQUIPPED WITH HR SMITH CPI SYSTEM
22-MAY-2014		MOS HRS/MSC - AFL		09-JUN-2014 3055:12 3428			
EASA 2014-0125 PARA (6)	FROM THE EFFECTIVE DATE OF THIS AD, INSTALLATION ON AN AIRCRAFT OF AN HR SMITH (TECHNICAL DEVELOPMENTS) CPI SYSTEM SERIES 15-503-134-1 EQUIPPED WITH BRU P/N 503-21-1 AND SIU P/N 503-24 OR P/N 503-24-2 OR P/N 503-24-6 IS ALLOWED, PROVIDED THE AIRCRAFT IS OPERATED IN COMPLIANCE WITH THE PROCEDURES AS REQUIRED BY THIS AD					MANDATORY	NOT APPLICABLE - BY AIRPLANE NOT EQUIPPED WITH HR SMITH CPI SYSTEM
22-MAY-2014		MOS HRS/MSC - AFL		09-JUN-2014 3055:12 3428			
EASA 2014-0125 PARA (7)	AFTER REPLACEMENT OF THE CPI SIU ON AN AIRCRAFT AS REQUIRED BY PARAGRAPH (4) OF THIS AD, DO NOT INSTALL AN SIU P/N 503-24 OR P/N 503-24-2 OR P/N 503-24-6 ON THE CPI SYSTEM OF THAT AIRCRAFT					MANDATORY	NOT APPLICABLE - BY AIRPLANE NOT EQUIPPED WITH HR SMITH CPI SYSTEM
22-MAY-2014		MOS HRS/MSC - AFL		09-JUN-2014 3055:12 3428			
EASA 2014-0142	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE - IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - BY P/N. A/C EQUIPPED WITH MC20
18-JUN-2014		MOS HRS/MSC - AFL		25-JUL-2014 3068:42 3441			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2014-0142 PARA (1)	ACCOMPLISH ACCOMPLISH THE ACTIONS AS SPECIFIED IN PARAGRAPHS (1.1) AND (1.2) OF THIS AD - DETERMINE THE DATE OF MANUFACTURING / REPLACE THE HARNESS INFLATION HOSE P/N 445952 WITH A SERVICEABLE PART, OR REMOVE THE INFLATABLE HARNESS FROM THE MASK REGULATOR AND REPLACE IT WITH A SERVICEABLE HARNESS					MANDATORY	NOT APPLICABLE - BY P/N. A/C EQUIPPED WITH MC20
18-JUN-2014		MOS HRS/MSC - AFL		25-JUL-2014 3068:42 3441			
EASA 2014-0142 PARA (2)	ACCOMPLISH AN OXYGEN MASK REGULATOR EQUIPPED WITH A P/N MXH21-1 INFLATABLE HARNESS HAVING A DMF CODE OF NOVEMBER 2008 (0845-S OR 08/45-S) OR EARLIER, AND THOSE WITH A DMF OF JANUARY 2011 (1101-S OR 11/01-S) OR LATER, IS EXCLUDED FROM THE INSPECTION AND REPLACEMENT REQUIREMENTS OF PARAGRAPH (1) OF THIS AD					MANDATORY	NOT APPLICABLE - BY P/N. A/C EQUIPPED WITH MC20
18-JUN-2014		MOS HRS/MSC - AFL		25-JUL-2014 3068:42 3441			
EASA 2014-0142 PARA (3)	ACCOMPLISH IT IS ALLOWED TO INSTALL ON AN AEROPLANE A FLIGHT CREW OXYGEN MASK REGULATOR, HAVING A P/N AS IDENTIFIED IN SECTION 1.A.(1) OF ZODIAC AEROTECHNICS SB MC10-35-274, PROVIDED IT HAS BEEN DETERMINED THAT A P/N MXH21-31 INFLATABLE HARNESS IS INSTALLED, OR THAT THE P/N MXH21-1 INFLATABLE HARNESS INSTALLED ON THAT FLIGHT CREW OXYGEN MASK REGULATOR HAS BEEN CORRECTED, AS REQUIRED BY THIS AD.					MANDATORY	NOT APPLICABLE - BY P/N. A/C EQUIPPED WITH MC20
18-JUN-2014		MOS HRS/MSC - AFL		25-JUL-2014 3068:42 3441			
EASA 2014-0142 R01	APPLIANCE AD - OXYGEN – OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE – IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
18-JUN-2014		MOS HRS/MSC - AFL		30-SEP-2014 3160 3512			
EASA 2014-0142 R01 PARA (1)	ACCOMPLISH ACCOMPLISH THE ACTIONS AS SPECIFIED IN PARAGRAPHS (1.1) AND (1.2) OF THIS AD - DETERMINE THE DATE OF MANUFACTURING / REPLACE THE HARNESS INFLATION HOSE P/N 445186 OR P/N 445952, AS APPLICABLE, WITH A SERVICEABLE PART, OR REMOVE THE INFLATABLE HARNESS FROM THE MASK REGULATOR AND REPLACE IT WITH A SERVICEABLE HARNESS					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
18-JUN-2014		MOS HRS/MSC - AFL		30-SEP-2014 3160 3512			
EASA 2014-0142 R01 PARA (2)	ACCOMPLISH AN OXYGEN MASK REGULATOR EQUIPPED WITH A P/N MXH20-1 OR P/N MXH21-1 INFLATABLE HARNESS HAVING A DMF CODE OF NOVEMBER 2008 (0845-S OR 08/45-S) OR EARLIER, AND THOSE WITH A DMF OF JANUARY 2011 (1101-S OR 11/01-S) OR LATER, IS EXCLUDED FROM THE INSPECTION AND REPLACEMENT REQUIREMENTS OF PARAGRAPH (1) OF THIS AD					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
18-JUN-2014		MOS HRS/MSC - AFL		30-SEP-2014 3160 3512			
EASA 2014-0142 R01 PARA (3)	ACCOMPLISH IT IS ALLOWED TO INSTALL ON AN AEROPLANE A FLIGHT CREW OXYGEN MASK REGULATOR, HAVING A P/N AS IDENTIFIED IN SECTION 1.A.(1) OF ZODIAC AEROTECHNICS SB MC10-35-274, PROVIDED IT HAS BEEN DETERMINED THAT A P/N MXH21-31 INFLATABLE HARNESS IS INSTALLED, OR THAT THE P/N MXH20-1 OR P/N MXH21-1 INFLATABLE HARNESS INSTALLED ON THAT FLIGHT CREW OXYGEN MASK REGULATOR HAS BEEN CORRECTED, AS REQUIRED BY THIS AD					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
18-JUN-2014		MOS HRS/MSC - AFL		30-SEP-2014 3160 3512			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2014-0187	APPLIANCE AD - EQUIPMENT & FURNISHINGS – SAFETY BELT ATTACHMENT BOLTS – INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
03-SEP-2014		MOS		30-SEP-2014			
		HRS/MSC	-	3160			
		AFL		3512			
EASA 2014-0187 PARA (1)	INSPECT THE SAFETY BELT ATTACHMENT BOLTS					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
03-SEP-2014		MOS		30-SEP-2014			
		HRS/MSC	-	3160			
		AFL		3512			
EASA 2014-0187 PARA (2)	IF, DURING THE INSPECTION AS REQUIRED BY PARAGRAPH (1) OF THIS AD, DETACHED OR LOOSENED SAFETY BELT ATTACHMENT BOLTS ARE FOUND, BEFORE NEXT FLIGHT, RE-TORQUE THE AFFECTED BOLTS TO THE VALUE AS DEFINED IN, AND IN ACCORDANCE WITH THE INSTRUCTIONS OF, GEVEN SB NO. D103-25-004 REVISION 2.					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
03-SEP-2014		MOS		30-SEP-2014			
		HRS/MSC	-	3160			
		AFL		3512			
EASA 2014-0187 PARA (3)	FOR SPECIFIC D1-03 SEAT ASSEMBLIES (P/N AS IDENTIFIED IN TABLE 1.1.1 OF GEVEN SB NO. D103-25-004 REVISION 2, EFF CODE FROM AAA TO AUC), WITHIN 6 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD, MODIFY THE SEAT BELT ATTACHMENT ASSEMBLY ON THE AISLE SIDE SPREADER OF STANDARD AND LAST ROW SEATS IN ACCORDANCE WITH THE INSTRUCTIONS OF GEVEN SB NO. D103-25-004 REVISION 2.					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
03-SEP-2014		MOS		30-SEP-2014			
		HRS/MSC	-	3160			
		AFL		3512			
EASA 2014-0187 PARA (4)	AS AN ALTERNATIVE TO THE CORRECTIVE ACTIONS AS REQUIRED BY PARAGRAPH (1) OR (2) OF THIS AD, AS APPLICABLE, BEFORE NEXT FLIGHT, BLOCK EACH AFFECTED SEAT FOR OCCUPANCY, PENDING ACCOMPLISHMENT OF THE APPLICABLE CORRECTIVE ACTION(S).					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
03-SEP-2014		MOS		30-SEP-2014			
		HRS/MSC	-	3160			
		AFL		3512			
EASA 2014-0279	APPLIANCE AD - EQUIPMENT / FURNISHING - RESTRAINT SYSTEM ROTARY BUCKLE SUBASSEMBLY - IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - ITEMS NOT INSTALLED
02-JAN-2015		MOS		28-FEB-2015			
		HRS/MSC	-	3338			
		AFL		3643			
EASA 2014-0279 PARA (1)	INSPECT THE LABEL OF THE ROTARY BUCKLE SUB-ASSEMBLY TO DETERMINE ITS PART NUMBER (P/N) AND SERIAL NUMBER (S/N)					MANDATORY	NOT APPLICABLE - ITEMS NOT INSTALLED
02-JAN-2015		MOS		28-FEB-2015			
		HRS/MSC	-	3338			
		AFL		3643			
EASA 2014-0279 PARA (1.1)	REPLACE THE ROTARY BUCKLE SUB-ASSEMBLY WITH A SERVICEABLE PART					MANDATORY	NOT APPLICABLE - ITEMS NOT INSTALLED
02-JAN-2015		MOS		28-FEB-2015			
		HRS/MSC	-	3338			
		AFL		3643			
EASA 2014-0279 PARA (1.2)	MARK THE SEAT AS "INOPERATIVE" UNTIL REPLACEMENT OF THE ROTARY BUCKLE SUB-ASSEMBLY AS REQUIRED BY PARAGRAPH (2) OF THIS AD					MANDATORY	NOT APPLICABLE - ITEMS NOT INSTALLED
02-JAN-2015		MOS		28-FEB-2015			
		HRS/MSC	-	3338			
		AFL		3643			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2014-0279 PARA (2)	REPLACE EACH ROTARY BUCKLE SUB-ASSEMBLY HAVING A P/N AND S/N AS SPECIFIED IN ROMTEX ANJOU AERONAUTIQUE SB 358SB-14-101 WITH A SERVICEABLE PART					MANDATORY	NOT APPLICABLE - ITEMS NOT INSTALLED
02-JAN-2015		MOS		28-FEB-2015			
		HRS/MSC	-	3338			
		AFL		3643			
EASA 2014-0279 PARA (3)	DO NOT INSTALL: - ON ANY RESTRAINT SYSTEM A SPARE ROTARY BUCKLE SUB-ASSEMBLY, OR - ON ANY AIRCRAFT A RESTRAINT SYSTEM EQUIPPED WITH A ROTARY BUCKLE SUB-ASSEMBLY HAVING A P/N AND A S/N LISTED IN ROMTEX ANJOU AERONAUTIQUE SB 358SB-14-101, UNLESS THE SUB-ASSEMBLY HAS BEEN REPAIRED,					MANDATORY	NOT APPLICABLE - ITEMS NOT INSTALLED
02-JAN-2015		MOS		28-FEB-2015			
		HRS/MSC	-	3338			
		AFL		3643			
EASA 2015-0093	APPLIANCE AD - NAVIGATION – ATTITUDE HEADING REFERENCE SYSTEM – MODIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
10-JUN-2015		MOS		03-AUG-2015			
		HRS/MSC	-	3644			
		AFL		3860			
EASA 2015-0093 PARA (1)	AMEND THE AFM OF THE AIRCRAFT BY INSERTING A TEMPORARY REVISION (TR) TO THE AFM (SUPPLEMENT)					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
10-JUN-2015		MOS		03-AUG-2015			
		HRS/MSC	-	3644			
		AFL		3860			
EASA 2015-0093 PARA (2)	MODIFY THE AIRCRAFT BY REPLACING EACH AHRS UNIT HAVING A P/N SPECIFIED AS 'OLD' IN TABLE 2 OF THIS AD WITH A MODIFIED UNIT, HAVING A P/N SPECIFIED AS 'NEW' IN TABLE 2 OF THIS AD					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
10-JUN-2015		MOS		03-AUG-2015			
		HRS/MSC	-	3644			
		AFL		3860			
EASA 2015-0093 PARA (3)	CONCURRENT WITH MODIFICATION OF AN AIRCRAFT AS REQUIRED BY PARAGRAPH (2) OF THIS AD, THE AFM CHANGE, IF REQUIRED BY PARAGRAPH (1) OF THIS AD (SEE NOTE 1 OF THIS AD), CAN BE REMOVED FROM THAT AIRCRAFT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
10-JUN-2015		MOS		03-AUG-2015			
		HRS/MSC	-	3644			
		AFL		3860			
EASA 2015-0093 PARA (4)	DO NOT INSTALL ON ANY AIRCRAFT A LCR-100 AHRS UNIT, HAVING A P/N SPECIFIED AS 'OLD' IN TABLE 1 OF THIS AD					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
10-JUN-2015		MOS		03-AUG-2015			
		HRS/MSC	-	3644			
		AFL		3860			
EASA 2016-0024	APPLIANCE AD - FIRE PROTECTION - OPTICAL AND AMBIENT SMOKE DETECTORS - IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
01-FEB-2016		MOS		02-FEB-2016			
		HRS/MSC	-	4024			
		AFL		4118			
EASA 2016-0024 PARA (1)	INSPECT EACH SIEMENS SMOKE DETECTOR TO DETERMINE WHETHER IT IS AN AFFECTED PART					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
01-FEB-2016		MOS		02-FEB-2016			
		HRS/MSC	-	4024			
		AFL		4118			
EASA 2016-0024 PARA (2.1)	REPLACE CARGO COMPARTMENT SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 1 OR TABLE 2					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
01-FEB-2016		MOS		02-FEB-2016			
		HRS/MSC	-	4024			
		AFL		4118			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2016-0024 PARA (2.2)	REPLACE PASSENGER, CABIN OR ANY OTHER ON BOARD LOCATION SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 3					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
01-FEB-2016		MOS		02-FEB-2016			
		HRS/MSC	-	4024			
		AFL		4118			
EASA 2016-0024 PARA (2.3)	REPLACE REPAIRED SMOKE DETECTOR IDENTIFIED IN APPENDIX 1					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
01-FEB-2016		MOS		02-FEB-2016			
		HRS/MSC	-	4024			
		AFL		4118			
EASA 2016-0024 PARA (3)	FROM THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL ON ANY AEROPLANE AN AFFECTED P/N SMOKE DETECTOR UNLESS THE UNIT (GMC ONLY) IS MARKED 'SIL PMC-26-002'					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED
01-FEB-2016		MOS		02-FEB-2016			
		HRS/MSC	-	4024			
		AFL		4118			
EASA 2016-0044	APPLIANCE AD - ATA 26 - FIRE PROTECTION - ENGINE AND AUXILIARY POWER UNIT AUTOMATIC FIRE EXTINGUISHERS - INSPECTION/OVERHAUL					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
22-MAR-2016		MOS		02-AUG-2016			
		HRS/MSC	-	4327			
		AFL		4340			
		APH		1769			
		APS		4931			
EASA 2016-0044 PARA (1)	INSPECT EACH FIRE EXTINGUISHER, EXCEPT THOSE HAVING P/N 57333 SERIES, INSTALLED ON BAE146 AND RJ AEROPLANES, AND THOSE HAVING P/N 57183 SERIES, INSTALLED ON ATP AEROPLANES, AND DEPENDING ON FINDINGS, ACCOMPLISH CORRECTIVE ACTIONS IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SB 26-080 REVISION 1					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
22-MAR-2016		MOS		02-AUG-2016			
		HRS/MSC	-	4327			
		AFL		4340			
		APH		1769			
		APS		4931			
EASA 2016-0044 PARA (2)	ACCOMPLISHMENT OF AN OVERHAUL (SEE NOTE 2 OF THIS AD) OF A FIRE EXTINGUISHER BY KIDDE GRAVINGER OR HUGEN, OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SIL 01-10 OR IN ACCORDANCE WITH KG CMM 26-21-40 REVISION 14 OR LATER OR KG CMM 26-21-52 REVISION 13 OR LATER (AS APPLICABLE TO FIRE EXTINGUISHER P/N) IS ACCEPTABLE TO COMPLY WITH THE REQUIREMENT OF PARAGRAPH (1).					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
22-MAR-2016		MOS		02-AUG-2016			
		HRS/MSC	-	4327			
		AFL		4340			
		APH		1769			
		APS		4931			
EASA 2016-0044 PARA (3)	FROM THE EFFECTIVE DATE OF THIS AD DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED FIRE EXTINGUISHER, UNLESS IT IS NEW, OR HAS PASSED AN INSPECTION IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SB 26-080 REVISION 1, OR IT HAS BEEN OVERHAULED (SEE NOTE 2) BY KG, OR BY HUGEN OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SIL 01-10 OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG CMM 26-21-40 REVISION 14, OR OF KG CMM 26-21-52 REVISION 13, AS APPLICABLE TO FIRE EXTINGUISHER P/N					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
22-MAR-2016		MOS		02-AUG-2016			
		HRS/MSC	-	4327			
		AFL		4340			
		APH		1769			
		APS		4931			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2016-0163	APPLIANCE AD - EQUIPMENT & FURNISHINGS - CABIN ATTENDANT SEAT - MODIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
	MOS			23-JAN-2018			
	HRS/MSC	-		5426:01			
	AFL			5094			
EASA 2016-0167	APPLIANCE AD - EQUIPMENT & FURNISHINGS - REAR CABIN ATTENDANT SEAT - INSPECTION / REPAIR					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
	MOS			23-JAN-2018			
	HRS/MSC	-		5426:01			
	AFL			5094			
EASA 2016-0167 R01 (CORR)	APPLIANCE AD - EQUIPMENT / FURNISHINGS - REAR CABIN ATTENDANT SEAT - INSPECTION / REPAIR					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 12 JUN 2018 // WO CEIS-11/18
02-FEB-2018	MOS						
	HRS/MSC	-					
	AFL						
	APH						
	APS						
EASA 2016-0167 R01 PARA (1)	REMOVE SEAT FROM THE AEROPLANE AND ACCOMPLISH A DETAILED VISUAL INSPECTION (DVI)					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 09 MAR 2018 // WO CEIS-04/18
02-FEB-2018	MOS						
	HRS/MSC	-					
	AFL						
	APH						
	APS						
EASA 2016-0167 R01 PARA (2)	DETAILED VISUAL INSPECTION (DVI)					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 09 MAR 2018 // WO CEIS-04/18
02-FEB-2018	MOS						
	HRS/MSC	-					
	AFL						
	APH						
	APS						
EASA 2016-0167 R01 PARA (3)	ACCOMPLISH THE APPLICABLE TEMPORARY CORRECTIVE ACTIONS (IF, DURING ANY INSPECTION AS REQUIRED BY PARAS (1) OR (2) OF THIS AD, AS APPLICABLE, CORROSION OR OTHER DAMAGE IS FOUND)					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 09 MAR 2018 // WO CEIS-04/18
02-FEB-2018	MOS						
	HRS/MSC	-					
	AFL						
	APH						
	APS						
EASA 2016-0167 R01 PARA (4)	TEMPORARILY STOWING AND SECURING A DAMAGED ATTENDANT SEAT IN RETRACTED POSITION TO PREVENT OCCUPANCY, IN ACCORDANCE WITH THE PROVISIONS AND LIMITATIONS OF THE APPLICABLE MASTER MINIMUM EQUIPMENT LIST ITEM, IS AN ACCEPTABLE ALTERNATIVE METHOD TO DEFER COMPLIANCE WITH THE REQUIREMENTS OF PARA (3) OF THIS AD.					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 09 MAR 2018 // WO CEIS-04/18
02-FEB-2018	MOS						
	HRS/MSC	-					
	AFL						
	APH						
	APS						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2016-0167 R01 PARA (5)	IT IS ALLOWED TO INSTALL (SEE NOTE 2 OF THIS AD) ON ANY AEROPLANE AN AFFECTED SEAT, HAVING ACCUMULATED MORE THAN 14 MONTHS SINCE FIRST INSTALLATION ON AN AEROPLANE, PROVIDED THAT, BEFORE (RE)INSTALLATION, IT HAS PASSED AN INSPECTION IN ACCORDANCE WITH THE INSTRUCTIONS OF SECTION 2, SUBPART B, OF ZODIAC SEATS FRANCE SB NO. 536-25-002					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 09 MAR 2018 // WO CEIS-04/18
02-FEB-2018	MOS HRS/MSC - AFL APH APS						
EASA 2016-0167 R01 PARA (6)	MODIFICATION AND RE-IDENTIFICATION (P/N CHANGE) OF A SEAT IN ACCORDANCE WITH THE INSTRUCTIONS OF ZODIAC SEATS FRANCE SB NO. 536-25-004 CONSTITUTE TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS AS REQUIRED BY PARAS (1) AND (2) OF THIS AD FOR THAT SEAT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 09 MAR 2018 // WO CEIS-04/18
02-FEB-2018	MOS HRS/MSC - AFL APH APS						
EASA 2016-0210	APPLIANCE AD - EQUIPMENT / FURNISHINGS - SEAT ENERGY ABSORBER ASSEMBLY - REPLACEMENT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
	MOS HRS/MSC - AFL						
EASA 2016-0256	APPLIANCE AD - EQUIPMENT & FURNISHINGS - PILOT AND CO-PILOT SEATS - MODIFICATION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
	MOS HRS/MSC - AFL			23-JAN-2018 5426:01 5094			
EASA 2017-0001	APPLIANCE AD - EQUIPMENT & FURNISHINGS - CABIN ATTENDANT SEATS - INSPECTION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
	MOS HRS/MSC - AFL			23-JAN-2018 5426:01 5094			
EASA 2017-0192	APPLIANCE AD - EQUIPMENT & FURNISHINGS - PASSENGER SEATS - MODIFICATION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
	MOS HRS/MSC - AFL			23-JAN-2018 5426:01 5094			
EASA 2017-0225	APPLIANCE AD - EQUIPMENT / FURNISHINGS - SEAT RESTRAINT SYSTEMS - AFM AMENDMENT / MODIFICATION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
01-DEC-2017	MOS HRS/MSC - AFL APH APS			21-NOV-2017 5332:07 5025			
EASA 2017-0225 PARA (1)	INSTALL A PLACARD AS SPECIFIED IN TABLE 1 OF THIS AD IN FULL VIEW OF THE PILOT(S), AMEND THE APPLICABLE AFM, INFORM ALL FLIGHT CREWS AND, THEREAFTER, OPERATE THE AIRCRAFT ACCORDINGLY					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
01-DEC-2017	DAYs HRS/MSC - AFL			21-NOV-2017 5332:07 5025			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2017-0225 PARA (3)	DO NOT INSTALL AN AFFECTED PART ON ANY AIRCRAFT THAT, ACCORDING TO THE APPLICABLE AFM, IS CERTIFICATED IN THE AEROBATIC CATEGORY, AS REQUIRED BY PARAGRAPH (3.1) OR (3.2) OF THIS AD, AS APPLICABLE					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
01-DEC-2017		MOS HRS/MSC - AFL APH APS		21-NOV-2017 5332:07 5025			
EASA 2018-0195	APPLIANCE AD - EQUIPMENT / FURNISHINGS - RESTRAINT SYSTEMS ROTARY BUCKLE SUB ASSEMBLY - REMOVAL FROM SERVICE					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
18-SEP-2018		MOS HRS/MSC - AFL APH APS					
EASA 2018-0223	APPLIANCE AD - EQUIPMENT / FURNISHING - SEAT ENERGY ABSORBER ASSEMBLY - MODIFICATION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
31-OCT-2018		MOS HRS/MSC - AFL APH APS					
EASA 2018-0247	APPLIANCE AD - NAVIGATION - TRANSPONDERS - INSPECTION / MODIFICATION					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
27-NOV-2018		MOS HRS/MSC - AFL APH APS					
EASA 2018-0247 PARA (1)	INSPECT THE INSTALLATION OF THE AFFECTED PART ON THE AIRCRAFT					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
27-NOV-2018		MOS HRS/MSC - AFL APH APS					
EASA 2018-0247 PARA (2)	IF, DURING THE INSPECTION AS REQUIRED BY PARAGRAPH (1) OF THIS AD, IT IS DETERMINED THAT THE INSTALLATION IS NOT A CONVENTIONAL INSTALLATION, AS DEFINED IN THIS AD, BEFORE NEXT FLIGHT, REMOVE THE TRANSPONDER FROM SERVICE FOR IN-SHOP MODIFICATION.					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
27-NOV-2018		MOS HRS/MSC - AFL APH APS					
EASA 2018-0247 PARA (3)	RETURNING AN AFFECTED PART, REMOVED FROM AN AIRCRAFT AS REQUIRED BY PARAGRAPH (2) OF THIS AD, TO TRIG AVIONICS FOR MODIFICATION, AND RE-INSTALLATION OF THAT MODIFIED TRANSPONDER ON THAT AIRCRAFT IS AN ACCEPTABLE METHOD TO COMPLY WITH THE REQUIREMENTS OF THIS AD FOR THAT AIRCRAFT					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
27-NOV-2018		MOS HRS/MSC - AFL APH APS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2018-0247 PARA (4)	FROM THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL AN AFFECTED PART ON ANY AIRCRAFT, UNLESS THE INSTALLATION IS CONVENTIONAL, AS DEFINED IN THIS AD					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
27-NOV-2018				MOS HRS/MSC - AFL APH APS			
EASA 2018-0259	APPLIANCE AD - INFORMATION SYSTEMS - ELECTRONIC FLIGHT BAG UNIVERSAL SERIAL BUS RECEPTACLE - MODIFICATION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
14-DEC-2018				MOS HRS/MSC - AFL APH APS			
EASA 2018-0259 PARA (1)	MODIFY EACH AFFECTED PART IN ACCORDANCE WITH THE INSTRUCTIONS OF THE APPLICABLE SB/EB					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
14-DEC-2018				MOS HRS/MSC - AFL APH APS			
EASA 2018-0259 PARA (2)	AFTER MODIFICATION OF AN AEROPLANE AS REQUIRED BY PARAGRAPH (1) OF THIS AD, DO NOT INSTALL AN AFFECTED PART ON THAT AEROPLANE.					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
14-DEC-2018				MOS HRS/MSC - AFL APH APS			
EASA 2018-0262	APPLIANCE AD - EQUIPMENT / FURNISHINGS - PILOT AND CO-PILOTS SEATS - MODIFICATION / INSPECTION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 27 DEC 2018 // WO CEIS-16/18 REV 01
20-DEC-2018				MOS HRS/MSC - AFL APH APS			
EASA 2018-0262 PARA (1)	MODIFY AND RE-IDENTIFY EACH PRE-MOD SEAT (FOR GROUP 1 AEROPLANES) (RESTATEMENT OF EASA AD 2016-0256 (1))					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 27 DEC 2018 // WO CEIS-16/18 REV 01
20-DEC-2018				MOS HRS/MSC - AFL APH APS			
EASA 2018-0262 PARA (2)	DO NOT INSTALL A PRE-MOD SEAT ON ANY AEROPLANE (RESTATEMENT OF EASA AD 2016-0256 PARA (2))					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 27 DEC 2018 // WO CEIS-16/18 REV 01
20-DEC-2018				MOS HRS/MSC - AFL APH APS			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2018-0262 PARA (3)	INSPECT ANY AFFECTED SPRING OF EACH SEAT; REPLACE BOTH SPRINGS (IF, DURING ANY INSPECTION ANY DAMAGE OR INCORRECT INSTALLATION OF AN EFFECTED SPING IS FOUND)					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 27 DEC 2018 // WO CEIS-16/18 REV 01
20-DEC-2018		MOS HRS/MSC - AFL APH APS					
EASA 2018-0262 PARA (5)	IT IS ALLOWED TO DEFER ACCOMPLISHMENT OF CORRECTIVE ACTIONS REQUIRED BT PARA (4) OF THIS AD FOR THAT SEAT, PROVIDED A COPY OF THE ATR OEB IS INCLUDED IN THE APPLICABLE AFM, PILOTS ARE INFORMED, AND THE AEROPLANE IS OPERATED IAW THE INSTRUCTIONS OF THAT OEB (IF, DURING ANY INSPECTION AS REQ BY PARA (3) OF THIS AD, ANY DAMAGE OR INCORRECT INSTALLATION OF ONLY ONE AFFECTED SPRING IS FOUND ON THE PILOT OR CO-PILOT SEAT) (FOR ATR AEROPLANES)					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 27 DEC 2018 // WO CEIS-16/18 REV 01
20-DEC-2018		DAY HRS/MSC - AFL APH APS					
EASA 2018-0262 PARA (8)	IT IS ALLOWED TO INSTALL AN AFFECTED SPRING ON A SEAT INSTALLED ON AN AEROPLANE PROVIDED THAT, AFTER INSTALLATION, THAT SPRING PASSES AN INSPECTION (NO DEFECT FOUND)					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 27 DEC 2018 // WO CEIS-16/18 REV 01
20-DEC-2018		MOS HRS/MSC - AFL					
EASA 2018-0262 PARA (9) & REPORTING (10)						MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 27 DEC 2018 // WO CEIS-16/18 REV 01
20-DEC-2018		DAY HRS/MSC - AFL APH APS					
EASA 2018-0264	APPLIANCE AD - EQUIPMENT / FURNISHINGS - LIFE VEST POUCH - INSPECTION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 27 DEC 2018 // WO CEIS-16/18 REV 01
21-DEC-2018		MOS HRS/MSC - AFL APH APS					
EASA 2018-0264 R01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - LIFE VEST POUCH - INSPECTION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 28 JUN 2019 // WO CEIS-10/19
04-APR-2019		MOS HRS/MSC - AFL APH APS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2019-0004	APPLIANCE AD - NAVIGATION - GLOBAL NAVIGATION SATELLITE SYSTEM - OPERATIONAL LIMITATIONS					MANDATORY	NOT APPLICABLE - NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 04 FEB 2019 // WO CEIS-03/19
25-JAN-2019		DAY	-				
		HRS/MSC	-				
		AFL					
		APH					
		APS					
EASA 2019-0010	APPLIANCE AD - EQUIPMENT/FURNISHING - LIFE JACKET - REMOVAL/REPAIR					MANDATORY	NOT APPLICABLE - NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 04 FEB 2019 // WO CEIS-03/19
06-FEB-2019		MOS	-				
		HRS/MSC	-				
		AFL					
		APH					
		APS					
EASA 2019-0010 PARA (1)	REMOVE EACH AFFECTED PART FROM SERVICE AND REPLACE IT WITH A SERVICEABLE PART					MANDATORY	NOT APPLICABLE - NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 04 FEB 2019 // WO CEIS-03/19
06-FEB-2019		MOS	-				
		HRS/MSC	-				
		AFL					
		APH					
		APS					
EASA 2019-0010 PARA (2)	DO NOT INSTALL AN AFFECTED PART ON ANY AIRCRAFT					MANDATORY	NOT APPLICABLE - NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 04 FEB 2019 // WO CEIS-03/19
06-FEB-2019		MOS	-				
		HRS/MSC	-				
		AFL					
		APH					
		APS					
EASA 2019-0010 PARA (3)	DO NOT RELEASE TO SERVICE ANY AFFECTED PART, UNLESS IT HAS BEEN REPAIRED AND RE-IDENTIFIED					MANDATORY	NOT APPLICABLE - NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 04 FEB 2019 // WO CEIS-03/19
06-FEB-2019		MOS	-				
		HRS/MSC	-				
		AFL					
		APH					
		APS					
EASA 2019-0179	APPLIANCE AD - NAVIGATION – AIRBORNE COLLISION AVOIDANCE SYSTEM DISPLAY SOFTWARE – UPDATE					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 16 SEP 2019 // WO CEIS-15/19
31-JUL-2019		MOS	-				
		HRS/MSC	-				
		AFL					
		APH					
		APS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2019-0179 PARA (1)	AMEND THE APPLICABLE AFM(S) IN ACCORDNADCE WITH THE OPSB AND INSTALL THE APPROPRIATE PLACARD; VERIFY THAT A PRESSURE ALTITUDE REPORTING TRANSPONDER IS INSTALLED AND INTRODUCE PRE-FLIGHT CHECKS					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 16 SEP 2019 // WO CEIS-15/19
31-JUL-2019			DAYs				
			HRS/MSC	-			
			AFL				
			APH				
			APS				
EASA 2019-0179 PARA (2)	MODIFY THE AEROPLANE BY INSTALLING A SOFTWARE UPDATE THAT RECTIFIES THE UNSAFE CONDITION ADDRESSED BY THIS AD; BEFORE NEXT FLIGHT AFTER MODIFICATION REMOVE THE AFM CHANGES AND PLACARD AND CONCURRENT WITH REMOVAL OF THE AFM(S) CHANGE AND PLACARD INSERT THE APPLICABLE POST-SB MTB 34-02 AFM TC					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 16 SEP 2019 // WO CEIS-15/19
31-JUL-2019			MOS				
			HRS/MSC	-			
			AFL				
			APH				
			APS				
EASA 2019-0179 R01	APPLIANCE AD - NAVIGATION - AIRBORNE COLLISION AVOIDANCE SYSTEM DISPLAY SOFTWARE - UPDATE					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 06 MAY 2020 // WO CEIS-03/20
24-APR-2020			MOS				
			HRS/MSC	-			
			AFL				
			APH				
			APS				
EASA 2019-0179 R01 PARA (1)	AMEND THE APPLICABLE AFM(S) IAW THE OPSB AND INSTALL THE APPROPRIATE PLACARD; VERIFY THAT A PRESSURE ALTITUDE REPORTING TRANSPONDER IS INSTALLED; AND INTRODUCE PRE-FLIGHT CHECKS					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 06 MAY 2020 // WO CEIS-03/20
24-APR-2020			DAYs				
			HRS/MSC				
			AFL				
			APH				
			APS				
EASA 2019-0179 R01 PARA (2) & (4)	MODIFY THE AEROPLANE BY INSTALLING A SOFTWARE UPDATE THAT RECTIFIES THE UNSAFE CONDITION THEN REMOVE THE AFM(S) CHANGES AND PLACARD, AS REQUIRED BY PARA (1) OF THIS AD. CONCURRENTLY, FOR CERTAIN TEXTRON AVIATION AEROPLANES, INSERT THE THE APPLICABLE POST-SB MTB-34-02 AFM TC OR POST-MOD AFMS, AS IDENTIFIED IN APPENDIX 2 OF THIS AD					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 06 MAY 2020 // WO CEIS-03/20
24-APR-2020			MOS				
			HRS/MSC				
			AFL				
			APH				
			APS				
EASA 2019-0235	APPLIANCE AD - EQUIPMENT / FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER - INSPECTION / MODIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - P/N ELT NOT Affected // CHECKDATE 07 NOV 2019 // WO CEIS-17/19
04-OCT-2019			MOS				
			HRS/MSC	-			
			AFL				
			APH				
			APS				

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2019-0235 PARA (1) THRU (4)	CONCURRENTLY ACCOMPLISH PARAS (1.1) AND (1.2) OF THIS AD AND ACCOMPLISH APPLICABLE CORRECTIVE ACTION(S) (IF, DISCREPANCIES ARE DETECTED, AS IDENTIFIED IN THE SIL); OPERATORS MAY CONTINUE TO USE ELTS WITH THE ORIGINAL G-SWITCHES BY REDUCING THE INTERVAL OF THE G-SWITCH TESTING, AS REQUIRED BY PARA (1.1)					MANDATORY	NOT APPLICABLE - P/N ELT NOT Affected // CHECKDATE 07 NOV 2019 // WO CEIS-17/19
04-OCT-2019	MOS HRS/MSC - AFL APH APS						
EASA 2019-0235 PARA (5)	REMOVE THE Affected PART FROM SERVICE IAW THE INSTRUCTIONS OF SECTION 7 OF THE SB FOR THE PURPOSE OF IN-SHOP MODIFICATION					MANDATORY	NOT APPLICABLE - P/N ELT NOT Affected // CHECKDATE 07 NOV 2019 // WO CEIS-17/19
04-OCT-2019	MOS HRS/MSC - AFL APH APS						
EASA 2019-0235 PARA (6)	IN-SHOP CORRECTION OF AN Affected PART OR MODIFICATION INTO A SERVICEABLE PART IAW THE INSTRUCTIONS OF THE SB CONSTITUTES TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS AND TESTING AS REQUIRED BY THIS AD FOR THAT PART					MANDATORY	NOT APPLICABLE - P/N ELT NOT Affected // CHECKDATE 07 NOV 2019 // WO CEIS-17/19
04-OCT-2019	MOS HRS/MSC - AFL APH APS						
EASA 2019-0235 PARA (9)	DO NOT INSTALL ON ANY AIRCRAFT AN Affected PART THAT HAS ACCUMULATED 10 YEAR TIS OR MORE					MANDATORY	NOT APPLICABLE - P/N ELT NOT Affected // CHECKDATE 07 NOV 2019 // WO CEIS-17/19
04-OCT-2019	MOS HRS/MSC - AFL APH APS						
EASA 2020-0272	APPLIANCE AD - EQUIPMENT / FURNISHINGS - BUCKLE - MODIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 12 JAN 2021 // WO CEIS-03/21
23-DEC-2020	MOS HRS/MSC - AFL APH APS						
EASA 2020-0272 PARA (1)	MODIFY EACH Affected BUCKLE OR REPLACE THE Affected BUCKLE WITH A SERVICEABLE BUCKLE					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 12 JAN 2021 // WO CEIS-03/21
23-DEC-2020	MOS HRS/MSC AFL APH APS						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2020-0272 PARA (2)	REPLACE EACH AFFECTED BUCKLE WITH A SERVICEABLE BUCKLE (IF POST-MODIFICATION AND PRE-REPLACEMENT PER PARA (1))						NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 12 JAN 2021 // WO CEIS-03/21
		MOS					
	23-DEC-2020	HRS/MSC					
		AFL					
		APH					
		APS					
EASA 2021-0137	APPLIANCE AD - EQUIPMENT / FURNISHINGS - PILOT AND CO-PILOT SEATS / LONGITUDINAL LOCKING SYSTEM PINS - MEASUREMENT / ADJUSTMENT						NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 03 AUG 2021 // WO CEIS-16/21
		MOS					
	22-JUN-2021	HRS/MSC					
		AFL					
		APH					
		APS					
EASA 2021-0185 R02	APPLIANCE AD - FIRE PROTECTION - HAND-OPERATED FIRE EXTINGUISHERS - INSPECTION/REPLACEMENT					MANDATORY	NOT APPLICABLE - MAKE AND MODEL NOT INSTALLED // CHECKDATE 24 JAN 2023 // WO CEIS-02/23
		MOS					
	14-SEP-2022	HRS/MSC					
		AFL					
		APH					
		APS					
EASA 2022-0024	APPLIANCE AD - ATA 34 - NAVIGATION - FLIGHT MANAGEMENT COMPUTER 2 / NAVIGATION MODULES - OPERATIONAL LIMITATIONS / AMENDMENT						NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 22 JUN 2022 // WO CEIS-02/22
		MOS					
	18-FEB-2022	HRS/MSC					
		AFL					
		APH					
		APS					
EASA 2024-0024	APPLIANCE AD - NAVIGATION - DIGITAL AIR DATA COMPUTER - REPLACEMENT					MANDATORY	NOT APPLICABLE - PN NOT INTSALLED // CHECKDATE 09 FEB 2024 // WO CEIS-04/24
		MOS					
	07-FEB-2024	HRS/MSC	-				
		AFL					
		APH					
		APS					
EASA 2025-0088	APPLIANCE AD - NAVIGATION - SATELLITE BASED AUGMENTATION SYSTEMS / GLOBAL POSITIONING SYSTEM RECEIVER - REPLACEMENT					MANDATORY	NOT APPLICABLE - MAKE AND MODEL NOT INSTALLED // CHECKDATE 25 APR 2025 // WO CEIS-05/25
		MOS					
	30-APR-2025	HRS/MSC	-				
		AFL					
		APH					
		APS					
FAA 2006-16-18 R01	APPLIANCE AD - SANDEL ST3400 TAWS/RMI PLACARD					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
		MOS			30-SEP-2014		
	18-JUL-2008	HRS/MSC	-		3160		
		AFL			3512		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2008-06-28	APPLIANCE AD - TO PREVENT CERTAIN CONDITIONS FROM EXISTING WHEN PFDS DISPLAY INCORRECT ATTITUDE, ALTITUDE, AND AIRSPEED INFORMATION					MANDATORY	NOT APPLICABLE - A/C NOT EQUIPPED WITH
10-APR-2008		MOS HRS/MSC - AFL		17-FEB-2014 2972:12 3326			
FAA 2008-06-28 R01	APPLIANCE AD - TO PREVENT CERTAIN CONDITIONS FROM EXISTING WHEN PFDS DISPLAY INCORRECT ATTITUDE, ALTITUDE, AND AIRSPEED INFORMATION					MANDATORY	NOT APPLICABLE - A/C NOT EQUIPPED WITH
10-APR-2008		MOS HRS/MSC - AFL		17-FEB-2014 2972:12 3326			
FAA 2008-19-01	APPLIANCE AD - NAVIGATION - AFM - LIMITATION SECTION - AMENDMENT NAVIGATION - PITOT/AOA PROBE - TEST/REPLACEMENT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
		MOS HRS/MSC - AFL		17-FEB-2014 2972:12 3326			
FAA 2009-05-05	APPLIANCE AD - TO PREVENT CERTAIN CONDITIONS FROM EXISTING WHEN PFDS DISPLAY INCORRECT ATTITUDE, ALTITUDE, AND AIRSPEED INFORMATION					MANDATORY	NOT APPLICABLE - A/C NOT EQUIPPED WITH
		MOS HRS/MSC - AFL		17-FEB-2014 2972:12 3326			
FAA 2009-05-08	APPLIANCE AD - UPGRADE THE SYSTEM SOFTWARE OF ANY TRIMBLE OF FREEFLIGHT SYSTEMS 2101 I/O APPROACH PLUS GLOBAL POSITIONING SYSTEM (GPS) NAVIGATION SYSTEMS					MANDATORY	NOT APPLICABLE - A/C NOT EQUIPPED WITH
		MOS HRS/MSC - AFL		17-FEB-2014 2972:12 3326			
FAA 2009-08-01	APPLIANCE AD - HONEYWELL FLIGHT MANAGEMENT SYSTEMS (FMSS) EQUIPPED WITH HONEYWELL NZ-2000 NAVIGATION COMPUTERS AND HONEYWELL IC-800 OR IC-800E INTEGRATED AVIONICS COMPUTERS					MANDATORY	NOT APPLICABLE - A/C NOT EQUIPPED WITH
39-15874 14-MAY-2009		MOS HRS/MSC - AFL		17-FEB-2014 2972:12 3326			
FAA 2009-21-03	APPLIANCE AD - AIRBORNE AUXILIARY POWER - FULL-AUTHORITY DIGITAL CONTROLLER (FADEC) - SOFTWARE UPDATE					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
		MOS HRS/MSC - AFL		17-FEB-2014 2972:12 3326			
FAA 2009-21-10	APPLIANCE AD - INSPECT TO DETERMINE THE SERIAL NUMBER OF THE OXYGEN CYLINDER ASSEMBLIES INSTALLED IN THE AIRPLANE					MANDATORY	NOT APPLICABLE - BY MODEL
		MOS HRS/MSC - AFL		17-FEB-2014 2972:12 3326			
FAA 2009-21-10 R01	APPLIANCE AD - INSPECT TO DETERMINE THE SERIAL NUMBER OF THE OXYGEN CYLINDER ASSEMBLIES INSTALLED IN THE AIRPLANE					MANDATORY	NOT APPLICABLE - A/C NOT FITTED WITH THESE TYPES OF OXYGEN CYLINDERS.
17-DEC-2009		DAYs HRS/MSC - AFL		17-FEB-2014 2972:12 3326			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2010-01-03	APPLIANCE AD - IDENTIFY AND REMOVE FROM SERVICE ALL AFFECTED FIRE EXTINGUISHERS AND REPLACE WITH SERVICABLE UNITS					MANDATORY	NOT APPLICABLE - A/C NOT FITTED WITH THESE TYPE OF EQUIPMENT.
20-JAN-2010		MOS HRS/MSC - AFL		17-FEB-2014 2972:12 3326			
FAA 2010-02-06	APPLIANCE AD - SICMA AERO SEAT 90XX AND 92XX SERIES PASSENGER SEATS					MANDATORY	NOT APPLICABLE - NOT EQUIPPED WITH
		MOS HRS/MSC - AFL		27-MAY-2014 3039:30 3409			
FAA 2010-02-06 PARA (F.1)	PERFORM SICMA AERO SEAT 90XX AND 92XX SERIES PASSENGER SEATS VISUAL INSPECTION OF CENTRAL SPREADERS, P/N 92-000100-200-1 AND P/N 92-000101-200-1					MANDATORY	NOT APPLICABLE - NOT EQUIPPED WITH
		MOS HRS/MSC - AFL		27-MAY-2014 3039:30 3409			
FAA 2010-02-06 PARA (F.2)	INSTALL SICMA AERO SEAT 90XX AND 92XX SERIES PASSENGER SEATS DOUBLERS, P/N 00-6536, ON NEW CENTRAL SPREADERS					MANDATORY	NOT APPLICABLE - NOT EQUIPPED WITH
		MOS HRS/MSC - AFL		27-MAY-2014 3039:30 3409			
FAA 2010-04-16	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI					MANDATORY	NOT APPLICABLE - AD 2010-04-16 "TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI " NOT APPLICABLE BY MANUFACTURER.
08-MAR-2010		DAYs HRS/MSC - AFL		27-JUL-2010 1300:42 1448			
FAA 2010-04-16 PARA (G)	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI WITH SERVICABLE UNIT					MANDATORY	NOT APPLICABLE
08-MAR-2010		DAYs HRS/MSC - AFL		27-JUL-2010 1300:42 1448			
FAA 2010-04-16 PARA (H)	RETURN TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI THE AFFECTED FIRE EXTINGUISHER TO MANUFACTURER					MANDATORY	NOT APPLICABLE - A/C NOT FITTED WITH THESE TYPE OF EQUIPMENT.
08-MAR-2010		DAYs HRS/MSC - AFL		17-FEB-2014 2972:12 3326			
FAA 2010-07-02	APPLIANCE AD - HONEYWELL PRIMUS II RNZ-850/-851 INTEGRATED NAVIGATION UNITS					MANDATORY	NOT APPLICABLE - A/C NOT EQUIPPED WITH
		MOS HRS/MSC - AFL		17-FEB-2014 2972:12 3326			
FAA 2010-09-04	APPLIANCE AD - HONEYWELL INTERNATIONAL INC., PRIMUS EPIC AND PRIMUS APEX FLIGHT MANAGEMENT SYSTEMS.					MANDATORY	NOT APPLICABLE - A/C FITTED WITH FMS SW 7.01, EB 7031847-00109 AND TT7038645-138
		DAYs HRS/MSC - AFL		17-FEB-2014 2972:12 3326			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2010-11-05	APPLIANCE AD - INSPECT FOR AND REMOVE SUBSTANDARD OXYGEN CYLINDERS FROM AIRPLANE					MANDATORY	NOT APPLICABLE - OXYGEN CYLINDER MODEL LISTED IN THIS AD NOT USED ON THIS AIRPLANE.
06-JUL-2010		DAYs		17-FEB-2014			
		HRS/MSC	-	2972:12			
		AFL		3326			
FAA 2010-12-09	APPLIANCE AD - AIRBORNE AUXILIARY POWER - FUEL CONTROL UNIT (FCU) - INSPECTION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
		MOS		17-FEB-2014			
		HRS/MSC	-	2972:12			
		AFL		3326			
FAA 2011-01-09	APPLIANCE AD - B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE) UNITS HAVING PART NUMBER (P/N) 119003-11					MANDATORY	NOT APPLICABLE - BY PART NUMBER P.B.E
		DAYs		17-FEB-2014			
		HRS/MSC	-	2972:12			
		AFL		3326			
FAA 2011-14-08	APPLIANCE AD - B/E AEROSPACE, CONTINUOUS FLOW PASSENGER OXYGEN MASK ASSEMBLY					MANDATORY	COMPLIED WITH - AD 2011-14-08 "B/E AEROSPACE, CONTINUOUS FLOW PASSENGER OXYGEN MASK ASSEMBLY" COMPLIED WITH.
		MOS		02-DEC-2011			
		HRS/MSC	-	1941:36			
		AFL		2168			
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS					MANDATORY	COMPLIED WITH - AD 2012-02-08 "AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS : COMPLIED WITH PER ACCOMPLISHMENT OF THE SB 680-34-29 "TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE"
13-MAR-2012		MOS		03-JUL-2012			
		HRS/MSC	-	2218:18			
		AFL		2473			
FAA 2012-14-15	APPLIANCE AD - HONEYWELL INTERNATIONAL, INC. KGS200 MERCURY ² SYSTEM SOFTWARE PROBLEM					MANDATORY	NOT APPLICABLE - A/C NOT EQUIPPED.
		MOS		17-FEB-2014			
		HRS/MSC	-	2972:12			
		AFL		3326			
FAA 2012-14-15 (G)	INCORPORATE HONEYWELL INTERNATIONAL, INC. KGS200 MERCURY ² SYSTEM SOFTWARE PROBLEM LANGUAGE INTO THE LIMITATIONS SECTION OF THE AIRCRAFT FLIGHT MANUAL					MANDATORY	NOT APPLICABLE - A/C NOT EQUIPPED.
		MOS		17-FEB-2014			
		HRS/MSC	-	2972:12			
		AFL		3326			
FAA 2012-14-15 (H)	FABRICATE HONEYWELL INTERNATIONAL, INC. KGS200 MERCURY ² SYSTEM SOFTWARE PROBLEM AND INSTALL A PLACARD					MANDATORY	NOT APPLICABLE - A/C NOT EQUIPPED.
		DAYs		17-FEB-2014			
		HRS/MSC	-	2972:12			
		AFL		3326			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2013-18-09	APPLIANCE AD - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING DISCREPANCIES - HONEYWELL ASCA INC				MANDATORY		NOT APPLICABLE - BY MODEL
	(SUPERSEDED BY FAA AD 2014-17-02)						
		DAYS		27-MAY-2014			
		HRS/MSC	-	3039:30			
		AFL		3409			
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS				MANDATORY		NOT APPLICABLE - EQUIPMENT NOT INSTALLED
39-18183 01-JUL-2015		MOS		31-MAY-2015			
		HRS/MSC	-	3481			
		AFL		3742			
FAA 2017-06-03	APPLIANCE AD - HEATING SYSTEM - ACCOMPLISH REPETITIVE DETAILED INSPECTIONS AND PRESSURE DECAY TESTS OF THE COMBUSTION HEATER AND DISABLE / REMOVE IF NECESSARY				MANDATORY		NOT APPLICABLE - EQUIPMENT NOT INSTALLED
05-MAY-2017		MOS		23-JAN-2018			
		HRS/MSC	-	5426:01			
		AFL		5094			
FAA 2017-06-03 PARA (G)	PERFORM INSPECTIONS AND PRESSURE DECAY TEST (PDT) OF THE COMBUSTION HEATER				MANDATORY		NOT APPLICABLE - EQUIPMENT NOT INSTALLED
05-MAY-2017		MOS		23-JAN-2018			
		HRS/MSC	-	5426:01			
		AFL		5094			
FAA 2017-06-03 PARA (K)	DISABLE OR REMOVE COMBUSTION HEATER				MANDATORY		NOT APPLICABLE - EQUIPMENT NOT INSTALLED
05-MAY-2017		DAYS		23-JAN-2018			
		HRS/MSC	-	5426:01			
		AFL		5094			
FAA 2017-09-09	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SEATING SYSTEMS - REMOVAL				MANDATORY		NOT APPLICABLE - EQUIPMENT NOT INSTALLED
		MOS		23-JAN-2018			
		HRS/MSC	-	5426:01			
		AFL		5094			
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS				MANDATORY		NOT APPLICABLE - EQUIPMENT NOT INSTALLED
24-OCT-2017		MOS		24-NOV-2017			
		HRS/MSC	-	5333:08			
		AFL		5026			
		APH		2101			
		APS		5693			
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT				MANDATORY		NOT APPLICABLE - EQUIPMENT NOT INSTALLED
24-OCT-2017		MOS		24-NOV-2017			
		HRS/MSC	-	5333:08			
		AFL		5026			
		APH		2101			
		APS		5693			
FAA 2018-03-04 PARA (G)	DETERMINE NUMBER OF AFFECTED PITOT PROBES INSTALLED				MANDATORY		NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 09 MAR 2018 // WO CEIS-04/18
16-MAR-2018		DAYS					
		HRS/MSC	-				
		AFL					
		APH					
		APS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2018-03-04 PARA (H)(1)	REPLACE AFFECTED PITOT PROBES					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 09 MAR 2018 // WO CEIS-04/18
16-MAR-2018		MOS HRS/MSC - AFL APH APS					
FAA 2018-03-04 PARA (H)(2)	DO NOT INSTALL ON ANY AIRPLANE A PITOT PROBE HAVING A SERIAL NUMBER LISTED IN PARA (C)(1) OF THIS AD, UNLESS IT HAS BEEN PROPERLY REPAIRED, AND IF REPAIRED BY CSI AEROSPACE, INC., HAS A REPAIR DATE OF AUGUST 1, 2014, OR LATER					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 09 MAR 2018 // WO CEIS-04/18
16-MAR-2018		MOS HRS/MSC - AFL APH APS					
FAA 2018-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - SEAT ENERGY ABSORBER ASSEMBLY - REPLACEMENT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
31-AUG-2018		MOS HRS/MSC - AFL APH APS					
FAA 2018-16-01 PARA (G)	REVIEW EACH AFFECTED ATTENDANT SEAT NG AND PILOT SEAT 120/335, REMOVE AND REPLACE THE EA ASSEMBLIES ON EACH AFFECTED PILOT SEAT, AND REMOVE EACH AFFECTED ATTENDANT SEAT AND REPLACE WITH A REWORKED SEAT IN ACCORDANCE WITH B/E AEROSPACE FISCHER ASB NO. SB 9911-001, ISSUE B, DATED NOVEMBER 4, 2016					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
31-AUG-2018		DAY HRS/MSC - AFL APH APS					
FAA 2018-16-01 PARA (H)	DO NOT INSTALL AN AFFECTED SEAT ON AN AIRCRAFT UNLESS, PRIOR TO INSTALLATION, THE EA ASSEMBLIES ON THE SEAT HAVE BEEN REPLACED IN ACCORDANCE WITH B/E AEROSPACE FISCHER ASB NO. SB 9911-001, ISSUE B, DATED NOVEMBER 4, 2016					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
31-AUG-2018		MOS HRS/MSC - AFL APH APS					
FAA 2018-16-13	APPLIANCE AD - EQUIPMENT/FURNISHINGS - INSPECT THE SAFETY BELT WEBBING, AND MODIFY AND RE-MARKING EACH AFFECTED CABIN ATTENDANT SEAT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
26-OCT-2018		MOS HRS/MSC - AFL APH APS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2018-16-13 PARA (G)	INSPECT SAFETY BELT WEBBING, MODIFY AND RE-MARK EACH AFFECTED CABIN ATTENDANT SEAT USING ZODIAC SEATS FRANCE SERVICE INFORMATION LETTER 537-01					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
26-OCT-2018		MOS HRS/MSC - AFL APH APS					
FAA 2018-16-13 PARA (H)	DO NOT INSTALL ANY AFFECTED ZODIAC SEATS FRANCE CABIN ATTENDANT SEAT ON ANY AIRCRAFT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
26-OCT-2018		MOS HRS/MSC - AFL APH APS					
FAA 2018-19-15	APPLIANCE AD - EQUIPMENT / FURNISHINGS - SAFETY BELT ATTACHMENT BOLTS - INSPECTION / TORQUE VERIFICATION / MODIFICATION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
14-NOV-2018		MOS HRS/MSC - AFL APH APS					
FAA 2018-21-14	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR HARNESS INFLATION HOSES - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 22 MAR 2019 // WO CEIS-05/19
39-19472 27-MAR-2019		MOS HRS/MSC - AFL APH APS					
FAA 2018-21-14 PARA (G)	REQUIRED ACTIONS					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 22 MAR 2019 // WO CEIS-05/19
27-MAR-2019		MOS HRS/MSC - AFL APH APS					
FAA 2018-21-14 PARA (H)	DO NOT INSTALL ON ANY AIRPLANE A FLIGHT CREW OXYGEN MASK REGULATOR WITH A P/N LISTED IN PLANNING INFORMATION, PARAGRAPH 1.A.(1), OF ZODIAC SB MC10-35-274 R02, DATED JUNE 25, 2014, UNLESS IT MEETS THE DEFINITION OF A PART ELIGIBLE FOR INSTALLATION IN PARA (I) OF THIS AD					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 22 MAR 2019 // WO CEIS-05/19
27-MAR-2019		MOS HRS/MSC - AFL APH APS					
FAA 2018-23-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CABIN ATTENDANT SEAT - INSPECTION AND REPLACEMENT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
28-DEC-2018		MOS HRS/MSC - AFL APH APS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2018-23-01 PARA (G)	INSPECT THE SEAT PAN STRUCTURE IN BOTH DEPLOYED AND STOWED POSITIONS (IF CRACKS ARE FOUND, REPLACE WITH REINFORCED SEAT PAN P/N F0511530 AND REMARK THE SEAT) (IF NO CRACKS ARE FOUND, REMARK THE SEAT AND REINSPECT OR REPLACE THE SEAT PAN WITH REINFORCED SEAT PAN P/N F0511530)					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
28-DEC-2018		MOS HRS/MSC - AFL APH APS					
FAA 2018-23-01 PARA (H)	INSTALLATION OF A REINFORCED SEAT PAN, P/N F0511530, USING PARAGRAPH 2.B., ACCOMPLISHMENT INSTRUCTIONS, OF ZODIAC SEATS FRANCE SB NO. 536-25-003, REV. 3, DATED JUNE 2, 2017, IS TERMINATING ACTION TO THIS AD					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
28-DEC-2018		MOS HRS/MSC - AFL APH APS					
FAA 2018-23-12	APPLIANCE AD - EQUIPMENT / FURNISHINGS - INSPECTION AND REPLACEMENT OF ZODIAC AERO (ALSO KNOWN AS AIR CRUISERS COMPANY) EVACUATION SYSTEMS FUSIBLE PLUGS					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
28-DEC-2018		MOS HRS/MSC - AFL APH APS					
FAA 2018-23-12 PARA (G)	ACCOMPLISH AN INSPECTION TO DETERMINE IF ANY PLUG HAS PART NUMBER (P/N) B13984-3, STAMPED WITH LOT PA-21 OR PA-22					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
28-DEC-2018		MOS HRS/MSC - AFL APH APS					
FAA 2018-23-12 PARA (H)	REPLACE FUSIBLE PLUG WITH A SERVICEABLE FUSIBLE PLUG P/N B13984-3 THAT IS NOT STAMPED WITH LOT PA-21 OR PA-22					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
28-DEC-2018		MOS HRS/MSC - AFL APH APS					
FAA 2018-23-12 PARA (I)	NO PERSON SHALL INSTALL ON ANY AIRPLANE ANY FUSIBLE PLUG HAVING P/N B13984-3, STAMPED WITH LOT PA-21 OR PA-22					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 30 NOV 2018 // WO CEIS-16/18
28-DEC-2018		MOS HRS/MSC - AFL APH APS					
FAA 2019-01-02	APPLIANCE AD - NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) IN - AIRPLANE FLIGHT MANUAL SUPPLEMENT (AFMS) - DISABLE / REVISE					MANDATORY	NOT APPLICABLE - NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 04 FEB 2019 // WO CEIS-03/19
07-FEB-2019		MOS HRS/MSC - AFL APH APS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2019-01-02 PARA (G)(1)	DISABLE THE AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) IN FUNCTION IN EACH UNIT					MANDATORY	NOT APPLICABLE - NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 04 FEB 2019 // WO CEIS-03/19
07-FEB-2019	MOS HRS/MSC - AFL APH APS						
FAA 2019-01-02 PARA (G)(2)	REVISE THE AIRPLANE FLIGHT MANUAL SUPPLEMENT IN ACCORDANCE WITH PARAGRAPH 5.2.C OF SB2018-01					MANDATORY	NOT APPLICABLE - NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 04 FEB 2019 // WO CEIS-03/19
07-FEB-2019	MOS HRS/MSC - AFL APH APS						
FAA 2019-07-03	APPLIANCE AD - EQUIPMENT / FURNISHINGS - REAR CABIN ATTENDANT SEAT - INSPECTION / REPAIR					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 28 JUN 2019 // WO CEIS-10/19
16-MAY-2019	MOS HRS/MSC - AFL APH APS						
FAA 2019-07-03 PARA (G)	REMOVE THE SEAT FROM THE AIRCRAFT AND PERFORM A DETAILED VISUAL INSPECTION; IF CORROSION OR OTHER DAMAGE IS FOUND, BEFORE NEXT FLIGHT OR BEFORE (RE)INSTALLATION OF THE SEAT ON AN AIRCRAFT, AS APPLICABLE, REPAIR THE SEAT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 28 JUN 2019 // WO CEIS-10/19
16-MAY-2019	MOS HRS/MSC - AFL APH APS						
FAA 2019-07-03 PARA (H)	DO NOT INSTALL ON ANY AIRCRAFT AN Affected ZODIAC SEATS FRANCE 536-SERIES CABIN ATTENDANT SEAT THAT HAS ACCUMULATED MORE THAN 14 MONTHS SINCE FIRST INSTALLATION ON ANY AIRCRAFT, UNLESS IT HAS PASSED AN INSPECTION IAW THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH 2.B., OF ZODIAC SEATS FRANCE SB NO. 536-25-002, REVISION 3, DATED NOVEMBER 2, 2016					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 28 JUN 2019 // WO CEIS-10/19
16-MAY-2019	MOS HRS/MSC - AFL APH APS						
FAA 2019-07-03 PARA (I)	MODIFICATION AND RE-IDENTIFICATION (P/N CHANGE) OF A SEAT IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH 2.A., OF ZODIAC SEATS FRANCE SB NO. 536-25-004, REV. 0, DATED OCTOBER 19, 2017, CONSTITUTES A TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 28 JUN 2019 // WO CEIS-10/19
16-MAY-2019	MOS HRS/MSC - AFL APH APS						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2019-07-10	APPLIANCE AD - NAVIGATION - LITEF ATTITUDE HEADING AND REFERENCE SYSTEM (AHRS) - REMOVAL					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 28 JUN 2019 // WO CEIS-10/19
29-MAY-2019		MOS HRS/MSC - AFL APH APS					
FAA 2019-07-10 PARA (F)(1)	REMOVE THE AHRS UNIT FROM SERVICE					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 28 JUN 2019 // WO CEIS-10/19
29-MAY-2019		MOS HRS/MSC - AFL APH APS					
FAA 2019-07-10 PARA (F)(2)	REMOVAL FROM SERVICE OF P/N 145130-7100 TERMINATES THE REQUIREMENTS OF AD 2010-26-09 (75 FR 81424, DECEMBER 28, 2010)					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 28 JUN 2019 // WO CEIS-10/19
29-MAY-2019		MOS HRS/MSC - AFL APH APS					
FAA 2019-07-10 PARA (F)(3)	DO NOT INSTALL AN AHRS UNIT P/N 145130-2000, 145130-2001, 145130-7000, 145130-7001, OR 145130-7100 ON ANY AIRCRAFT					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 28 JUN 2019 // WO CEIS-10/19
29-MAY-2019		MOS HRS/MSC - AFL APH APS					
FAA 2019-08-01	APPLIANCE AD - EQUIPEMENT AND FURNISHINGS - MODIFICATION AND RE-IDENTIFICATION OF ALL AFFECTED RECARO AIRCRAFT SEATING GMBH & CO. KG MODEL PASSENGER SEATS					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 28 JUN 2019 // WO CEIS-10/19
21-MAY-2019		MOS HRS/MSC - AFL APH APS					
FAA 2019-08-01 PARA (G)	MODIFY THE AFFECTED PASSENGER SEAT AND RE-IDENTIFY EACH MODIFIED PASSENGER SEAT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 28 JUN 2019 // WO CEIS-10/19
21-MAY-2019		MOS HRS/MSC - AFL APH APS					
FAA 2019-08-01 PARA (H)	AFTER THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL AN AFFECTED RECARO MODEL PASSENGER SEAT ON ANY AIRCRAFT, UNLESS THE SEAT HAS BEEN MODIFIED AND RE-IDENTIFIED IN ACCORDANCE WITH PARAGRAPH (G)(2), (3), OR (4) OF THIS AD					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 28 JUN 2019 // WO CEIS-10/19
21-MAY-2019		MOS HRS/MSC - AFL APH APS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2019-13-03	APPLIANCE AD - TRIG AVIONICS LTD. - NAVIGATION - TRANSPONDERS INSTALLATION - INSPECTION / MODIFICATION				MANDATORY		NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 16 SEP 2019 // WO CEIS-15/19
27-AUG-2019		MOS HRS/MSC - AFL APH APS					
FAA 2019-13-03 PARA (G)	INSPECT THE TRANSPONDER INSTALLATION TO DETERMINE IF THE TRANSPONDER IS INSTALLED IN A CONVENTIONAL AFT-FACING AVIONICS RACK				MANDATORY		NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 16 SEP 2019 // WO CEIS-15/19
27-AUG-2019		DAY HRS/MSC - AFL APH APS					
FAA 2019-13-03 PARA (H)	DO NOT INSTALL AN AFFECTED TRANSPONDER ON ANY AIRCRAFT, UNLESS THE TRANSPONDER IS INSTALLED IN A CONVENTIONAL AFT-FACING AVIONICS RACK AS DEFINED IN THIS AD				MANDATORY		NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 16 SEP 2019 // WO CEIS-15/19
27-AUG-2019		MOS HRS/MSC - AFL APH APS					
FAA 2019-14-05	APPLIANCE AD - EQUIPMENT / FURNISHING - SEAT ENERGY ABSORBER ASSEMBLY - REPLACEMENT				MANDATORY		NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 16 SEP 2019 // WO CEIS-15/19
03-SEP-2019		MOS HRS/MSC - AFL APH APS					
FAA 2019-14-05 PARA (G)	REVIEW EACH AFFECTED B/E AEROSPACE FISCHER COMMON SEAT TO DETERMINE IF REWORK HAS ALREADY BEEN PERFORMED. IF THE REWORK HAS NOT BEEN PERFORMED REWORK THE AFFECTED SEATS AND MARK THE SEAT BY INSTALLING A PLACARD				MANDATORY		NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 16 SEP 2019 // WO CEIS-15/19
03-SEP-2019		MOS HRS/MSC - AFL APH APS					
FAA 2019-14-05 PARA (H)	DO NOT INSTALL ANY SEAT AFFECTED BY THIS AD ONTO ANY AIRCRAFT UNLESS THE SEAT IS MARKED WITH A PLACARD STATING COMPLETION OF B/E AEROSPACE FISCHER ASB NO. SB0718-004, ISSUE A, DATED JUNE 26, 2018				MANDATORY		NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 16 SEP 2019 // WO CEIS-15/19
03-SEP-2019		MOS HRS/MSC - AFL APH APS					
FAA 2019-15-10	APPLIANCE AD - EQUIPMENT / FURNISHING - LIFE JACKET - REMOVAL / REPAIR				MANDATORY		NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 16 SEP 2019 // WO CEIS-15/19
19-SEP-2019		MOS HRS/MSC - AFL APH APS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2019-15-10 PARA (G)	REMOVE EACH AFFECTED LIFE JACKET FROM THE AIRPLANE AND REPLACE THE LIFE JACKET WITH A LIFE JACKET ELIGIBLE FOR INSTALLATION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 16 SEP 2019 // WO CEIS-15/19
19-SEP-2019				MOS HRS/MSC - AFL APH APS			
FAA 2019-15-10 PARA (H)	DO NOT INSTALL ON ANY AIRPLANE AN AFFECTED LIFE JACKET UNLESS IT HAS BEEN REPAIRED AND MARKED TO INDICATE COMPLIANCE WITH SUCH REPAIR IN ACCORDANCE WITH ZODIAC AEROSPACE SERVICES SB 25-65-34, REVISION 01, DATED MARCH 15, 2019, OR ORIGINAL ISSUE, DATED JANUARY 8, 2019; OR A METHOD APPROVED BY THE FAA					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 16 SEP 2019 // WO CEIS-15/19
19-SEP-2019				MOS HRS/MSC - AFL APH APS			
FAA 2019-21-06	APPLIANCE AD - FLIGHT COMPARTMENT EQUIPMENT - IPECO HOLDINGS LTD. -MODIFICATION AND REIDENTIFICATION OF PILOT'S AND CO-PILOT'S SEATS					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 20 JAN 2020 // WO CEIS-02/20
13-DEC-2019				MOS HRS/MSC - AFL APH APS			
FAA 2019-21-06 PARA (G)(1)	MODIFY AND RE-IDENTIFY EACH AFFECTED PILOT AND CO-PILOT SEAT (RESTATEMENT OF FAA 2017-22-02)					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 20 JAN 2020 // WO CEIS-02/20
13-DEC-2019				MOS HRS/MSC - AFL APH APS			
FAA 2019-21-06 PARA (G)(2)	INSPECT ANY AFFECTED SPRING OF EACH SEAT; REPLACE BOTH SPRINGS (IF, DURING ANY INSPECTION ANY DAMAGE OR INCORRECT INSTALLATION OF AN EFFECTED SPING IS FOUND)					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 20 JAN 2020 // WO CEIS-02/20
13-DEC-2019				MOS HRS/MSC - AFL APH APS			
FAA 2019-21-06 PARA (G)(3)	SEND THE INSPECTION RESULTS, INCLUDING NO FINDINGS, TO IPECO AT TECHNICALSUPPORT@IPECO.COM					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 20 JAN 2020 // WO CEIS-02/20
13-DEC-2019				DAYs HRS/MSC - AFL APH APS			
FAA 2019-21-06 PARA (H)	DO NOT INSTALL ANY PILOT OR CO-PILOT SEAT IDENTIFIED IN PARAGRAPH (C)(1)(I) OF THIS AD UNLESS THE SEAT IS MODIFIED AND RE-IDENTIFIED AS SPECIFIED IN PARAGRAPH (G)(1) OF THIS AD					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 20 JAN 2020 // WO CEIS-02/20
13-DEC-2019				MOS HRS/MSC - AFL APH APS			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2019-21-09	APPLIANCE AD - EQUIPMENT / FURNISHINGS - LIFE VEST POUCH - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 20 JAN 2020 // WO CEIS-02/20
18-DEC-2019		MOS HRS/MSC - AFL APH APS					
FAA 2019-21-09 PARA (G)	INSPECT THE AFFECTED SEAT LIFE VEST POUCH ASSEMBLY; IF, DURING THE INSPECTION A LIFE VEST POUCH VELCRO STRIP IS FOUND DAMAGED OR WORN OR A LIFE VEST POUCH INSTALLATION IS NOT FOUND ACCEPTABLE, BEFORE FURTHER FLIGHT, REMOVE THE LIFE VEST POUCH FROM SERVICE AND REPLACE IT WITH A PART ELIGIBLE FOR INSTALLATION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 20 JAN 2020 // WO CEIS-02/20
18-DEC-2019		MOS HRS/MSC AFL APH APS					
FAA 2019-21-09 PARA (I)	AFTER THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL AN AVIOINTERIORS CENTAURUS ECONOMY CLASS PASSENGER SEAT WITH A P/N IDENTIFIED IN PARAGRAPH (C) OF THIS AD UNLESS THE AFFECTED SEAT LIFE VEST POUCH ASSEMBLY HAS BEEN INSPECTED IN ACCORDANCE WITH PARAGRAPH (G)(1) OF THIS AD					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 20 JAN 2020 // WO CEIS-02/20
18-DEC-2019		MOS HRS/MSC - AFL APH APS					
FAA 2020-08-02	APPLIANCE AD - NAVIGATION - THALES AVS FRANCE SAS - GLOBAL NAVIGATION SATELLITE SYSTEM - OPERATIONAL LIMITATIONS					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 06 MAY 2020 // WO CEIS-03/20
19-MAY-2020		MOS HRS/MSC - AFL APH APS					
FAA 2020-09-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ANJOU AERONAUTIQUE - RESTRAINT SYSTEMS ROTARY BUCKLE SUB ASSEMBLY - REPLACEMENT					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED // CHECKDATE 06 MAY 2020 // WO CEIS-03/20
29-MAY-2020		MOS HRS/MSC - AFL APH APS					
FAA 2020-09-02 PARA (G)(1)	INSPECT EACH RESTRAINT SYSTEM FOR PROPER RELEASE OF THE STRAPS FROM THE RESTRAINT SYSTEM AND, DEPENDING IF THE STRAPS RELEASE, PLACARD THE SEAT AS INOPERATIVE AND REMOVE AND REPLACE THE ROTARY BUCKLE SUB-ASSEMBLY (FOR THE RESTRAINT SYSTEMS LISTED IN THE EFFECTIVITY OF ANJOU AERO SB 358SB-14-101 R01, EXCEPT FOR S/N/S 1038-1048 (INCLUSIVE), 1050-1055 (INCLUSIVE), AND 1062-1073 (INCLUSIVE))					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED // CHECKDATE 06 MAY 2020 // WO CEIS-03/20
29-MAY-2020		MOS HRS/MSC AFL APH APS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2020-09-02 PARA (G)(2)	INSPECT EACH RESTRAINT SYSTEM FOR PROPER RELEASE OF THE STRAPS FROM THE RESTRAINT SYSTEM AND, DEPENDING IF THE STRAPS RELEASE, PLACARD THE SEAT AS INOPERATIVE AND REMOVE AND REPLACE THE RESTRAINT SYSTEM FROM SERVICE (FOR RESTRAINT SYSTEMS, P/N 358XX-XXX-YY-ZZZ (WHERE 358XX-XXX-YY-ZZZ CAN BE ANY COMBINATION OF NUMBERS AND/OR LETTERS), HAVING S/NS 738-1619 (INCLUSIVE))					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED // CHECKDATE 06 MAY 2020 // WO CEIS-03/20
29-MAY-2020	MOS HRS/MSC AFL APH APS						
FAA 2020-09-02 PARA (H)	DO NOT INSTALL ON ANY AIRCRAFT AN ANJOU AERONAUTIQUE RESTRAINT SYSTEM, P/N 358XX-XXX-YY-ZZZ, HAVING S/NS 738-1619 (INCLUSIVE), EVEN IF THE RESTRAINT SYSTEM IS LABELED IN COMPLIANCE WITH ANJOU AERO SB 358SB-14-101 R01, DATED DECEMBER 12, 2014					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED // CHECKDATE 06 MAY 2020 // WO CEIS-03/20
29-MAY-2020	MOS HRS/MSC - AFL APH APS						
FAA 2020-10-05	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED // CHECKDATE 06 AUG 2020 // WO CEIS-05/20
24-JUN-2020	MOS HRS/MSC AFL APH APS						
FAA 2020-16-08	APPLIANCE AD - ASPEN AVIONICS, INC. - EFD1000 FLIGHT DISPLAY SYSTEMS - AIRPLANE FLIGHT MANUAL - REVISION					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED // CHECKDATE 12 NOV 2020 // WO CEIS-08/20
17-AUG-2020	MOS HRS/MSC - AFL APH APS						
FAA 2020-18-51	APPLIANCE AD - SANDIA AEROSPACE - AIRPLANE FLIGHT MANUAL - SECTION LIMITATIONS - AMENDMENT					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED // CHECKDATE 12 NOV 2020 // WO CEIS-08/20
28-SEP-2020	MOS HRS/MSC - AFL APH APS						
FAA 2020-18-51-E	APPLIANCE/EMERGENCY AD - SANDIA AEROSPACE - AIRPLANE FLIGHT MANUAL - SECTION LIMITATIONS - AMENDMENT					MANDATORY	NOT APPLICABLE - P/N NOT INSTALLED // CHECKDATE 12 NOV 2020 // WO CEIS-08/20
31-AUG-2020	MOS HRS/MSC - AFL APH APS						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2020-21-02	APPLIANCE AD - FIRE PROTECTION - KIDDE AEROSPACE & DEFENSE CARGO FIRE EXTINGUISHER HALON BOTTLES - REPLACEMENT				MANDATORY		NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 12 NOV 2020 // WO CEIS-08/20
19-NOV-2020		MOS HRS/MSC AFL APH APS					
FAA 2020-21-02 PARA (H) & (I)	DO AN INSPECTION TO DETERMINE THE PART NUMBER AND SERIAL NUMBER OF THE CARGO FIRE EXTINGUISHER HALON BOTTLES INSTALLED IN THE CARGO COMPARTMENT AND REPLACE WITH A SERVICEABLE PART AS REQUIRED				MANDATORY		NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 12 NOV 2020 // WO CEIS-08/20
		MOS HRS/MSC AFL APH APS					
FAA 2020-21-02 PARA (J)	NO PERSON MAY INSTALL ON ANY AIRPLANE AN AFFECTED PART AS IDENTIFIED IN PARAGRAPH (G)(3) OF THIS AD UNLESS THAT PART HAS A CIRCLED LETTER "G" STAMPED AT A DISTANCE 8 OF APPROXIMATELY ONE INCH FROM THE LEFT EDGE OF THE PLACARD, INDICATING THAT THE CARGO FIRE EXTINGUISHER HALON BOTTLE HAS BEEN TESTED AND REFILLED				MANDATORY		NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 12 NOV 2020 // WO CEIS-08/20
		MOS HRS/MSC - AFL APH APS					
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT				MANDATORY		NOT APPLICABLE
39-21490 11-MAY-2021		MOS HRS/MSC - AFL		26-APR-2021 7171:58 6455			
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE				MANDATORY		NOT APPLICABLE
11-MAY-2021		MOS HRS/MSC - AFL		26-APR-2021 7171:58 6455			
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICHNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE				MANDATORY		NOT APPLICABLE
11-MAY-2021		MOS HRS/MSC - AFL		26-APR-2021 7171:58 6455			
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER				MANDATORY		NOT APPLICABLE
11-MAY-2021		MOS HRS/MSC - AFL		26-APR-2021 7171:58 6455			
FAA 2021-08-07	APPLIANCE AD - ROCKWELL COLLINS - GLOBAL POSITIONING SYSTEM GPS-4000S - UPGRADE				MANDATORY		NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 27 APR 2021 // WO CEIS-07/21
12-MAY-2021		MOS HRS/MSC - AFL APH APS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2021-08-07 PARA (G)(1)	REPLACE EACH GPS-4000S GPS P/N 822-2189-100 WITH A GPS THAT DOES NOT HAVE P/N 822-2189-100					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 27 APR 2021 // WO CEIS-07/21
12-MAY-2021	MOS HRS/MSC AFL APH APS						
FAA 2021-08-07 PARA (G)(2)	DO NOT INSTALL GPS-4000S GPS P/N 822-2189-100 ON ANY AIRPLANE					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 27 APR 2021 // WO CEIS-07/21
12-MAY-2021	MOS HRS/MSC AFL APH APS						
FAA 2021-08-15 39-21509; 17-MAY-2021	APPLIANCE AD - NAVIGATION - GARMIN INTERNATIONAL GMN-00962 GTS PROCESSOR UNITS, PART NUMBER 011-02571-0() - SOFTWARE UPDATE	MOS HRS/MSC AFL APH APS				MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 27 APR 2021 // WO CEIS-07/21
FAA 2021-22-07 18-NOV-2021	APPLIANCE AD - FIRE PROTECTION - HAND-OPERATED FIRE EXTINGUISHERS - INSPECTION / REPLACEMENT	MOS HRS/MSC AFL APH APS				MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 25 NOV 2021 // WO CEIS-19/21
FAA 2022-01-03 07-MAR-2022	APPLIANCE AD - FIRE PROTECTION - HAND-HELD FIRE EXTINGUISHERS - REPLACEMENT	MOS HRS/MSC AFL APH APS				MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 07 FEB 2022 // WO CEIS-01/22
FAA 2022-05-10	APPLIANCE AD - CABIN EQUIPMENT/FURNISHINGS - GOODRICH HOIST ASSEMBLY - INSPECT/REPLACE	MOS HRS/MSC AFL APH APS				MANDATORY	NOT APPLICABLE - BY TYPE OF AIRCRAFT // CHECKDATE 22 JUN 2022 // WO CEIS-02/22
FAA 2022-05-10 PARA (G)(2)	INSTALL PLACARDS AND REVIS THE EXISTING RFM	MOS HRS/MSC AFL				MANDATORY	NOT APPLICABLE - BY TYPE OF AIRCRAFT // CHECKDATE 22 JUN 2022 // WO CEIS-02/22

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2022-05-10 PARA (G)(3)	DEACTIVATE OR REMOVE THE HOIST IF PARTIAL PEEL OUT OCCURS					MANDATORY	NOT APPLICABLE - BY TYPE OF AIRCRAFT // CHECKDATE 22 JUN 2022 // WO CEIS-02/22
		MOS					
		HRS/MSC	-				
		AFL					
FAA 2022-05-10 PARA (G)(4)	REVIEW THE HELICOPTER'S HOIST SLIP LOAD TEST RECORDS					MANDATORY	NOT APPLICABLE - BY TYPE OF AIRCRAFT // CHECKDATE 22 JUN 2022 // WO CEIS-02/22
		MOS					
		HRS/MSC	-				
		AFL					
FAA 2022-05-10 PARA (G)(5)	INSPECT CABLE FROM THE HOOK ASSEMBLY, PERFORM CABLE CONDITIONING AND HOIST SLIP LOAD TEST					MANDATORY	NOT APPLICABLE - BY TYPE OF AIRCRAFT // CHECKDATE 22 JUN 2022 // WO CEIS-02/22
		MOS					
		HRS/MSC	-				
		AFL					
FAA 2022-05-10 PARA (G)(6)	REPORT HOIST SLIP LOAD TEST INFORMATION REQUESTED IN APPENDIX 1					MANDATORY	NOT APPLICABLE - BY TYPE OF AIRCRAFT // CHECKDATE 22 JUN 2022 // WO CEIS-02/22
		MOS					
		HRS/MSC	-				
		AFL					
FAA 2023-13-11	APPLIANCE AD - OXYGEN - OXYGEN VALVE ASSEMBLIES / OXYGEN CYLINDER AND VALVE ASSEMBLIES - INSPECTION/REPLACEMENT					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 09 SEP 2023 // WO CEIS-21/23
39-22496 05-SEP-2023		MOS					
		HRS/MSC	-				
		AFL					
		APH					
		APS					
FAA 2023-13-11 PARA (H)	INSPECT THE OXYGEN VALVE ASSEMBLIES AND OXYGEN CYLINDER AND VALVE ASSEMBLIES					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 09 SEP 2023 // WO CEIS-21/23
39-22496 05-SEP-2023		MOS					
		HRS/MSC	-				
		AFL					
		APH					
		APS					
FAA 2023-13-11 PARA (J)	REPORT THE RESULTS OF THE INSPECTION AND RETURN PARTS (AS REQUIRED)					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 09 SEP 2023 // WO CEIS-21/23
39-22496 05-SEP-2023		MOS					
		HRS/MSC	-				
		AFL					
		APH					
		APS					
FAA 2023-14-10	APPLIANCE AD - FLIGHT COMPARTMENT EQUIPMENT - IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS - INSPECTION/MODIFICATION					MANDATORY	NOT APPLICABLE - MAKE AND MODEL NOT INSTALLED // CHECKDATE 07 SEP 2023 // WO CEIS-21/23
39-22510 07-SEP-2023		MOS					
		HRS/MSC	-				
		AFL					
		APH					
		APS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2023-14-10 PARA (G)(1)	MODIFY AND RE-IDENTIFY EACH AFFECTED PILOT AND CO-PILOT SEAT (SEATS THAT HAVE NOT INSTALLED THE TRACK LOCK SPRING MODIFICATION KIT)					MANDATORY	NOT APPLICABLE - MAKE AND MODEL NOT INSTALLED // CHECKDATE 07 SEP 2023 // WO CEIS-21/23
07-SEP-2023		MOS HRS/MSC - AFL APH APS					
FAA 2023-14-10 PARA (G)(2)	INSPECT THE TRACK LOCK SPRING OF EACH SEAT					MANDATORY	NOT APPLICABLE - MAKE AND MODEL NOT INSTALLED // CHECKDATE 07 SEP 2023 // WO CEIS-21/23
07-SEP-2023		MOS HRS/MSC - AFL APH APS					
FAA 2023-14-10 PARA (G)(3)	SEND THE INSPECTION RESULTS, INCLUDING NO FINDINGS, TO IPECO					MANDATORY	NOT APPLICABLE - MAKE AND MODEL NOT INSTALLED // CHECKDATE 07 SEP 2023 // WO CEIS-21/23
07-SEP-2023		MOS HRS/MSC - AFL APH APS					
FAA 2023-14-10 PARA (H)	MODIFY AND RE-IDENTIFY EACH AFFECTED SEAT					MANDATORY	NOT APPLICABLE - MAKE AND MODEL NOT INSTALLED // CHECKDATE 07 SEP 2023 // WO CEIS-21/23
07-SEP-2023		MOS HRS/MSC - AFL APH APS					
FAA 2024-01-11	APPLIANCE AD - INSPECTION OF PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE ASSEMBLIES (P/N) 1111475 (ALL DASH NUMBERS) AND P/N 1111548-01					MANDATORY	NOT APPLICABLE - ONLY FOR HELICOPTER APPLICABLE // CHECKDATE 09 FEB 2024 // WO CEIS-04/24
39-22662 15-FEB-2024		MOS HRS/MSC - AFL APH APS					
FAA 2024-19-15	APPLIANCE AD - OXYGEN - OXYGEN VALVE ASSEMBLIES / OXYGEN CYLINDER AND VALVE ASSEMBLIES - INSPECTION/REPLACEMENT					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 20 DEC 2024 // WO CEIS-21/24
39-22857 26-NOV-2024		MOS HRS/MSC - AFL APH APS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2024-19-15 PARA (H)	INSPECT THE OXYGEN VALVE ASSEMBLIES, AND OXYGEN CYLINDER AND VALVE ASSEMBLIES, TO DETERMINE IF THE SERIAL NUMBERS OF THE VALVE, CYLINDER, AND ENTIRE ASSEMBLY, ARE LISTED IN APPENDIX 1 OR 2 (AFFECTED SHIPMENTS) OF THE APPLICABLE MATERIAL (THIS PARAGRAPH RESTATES FAA 2023-13-11 PARA (H))					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 20 DEC 2024 // WO CEIS-21/24
26-NOV-2024		MOS HRS/MSC	-	AFL APH APS			
FAA 2024-19-15 PARA (J)	RETAINED RETURN OF PARTS (THIS PARAAGRAPH RESTATES FAA 2023-13-11 PARA (J)(2))					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 20 DEC 2024 // WO CEIS-21/24
26-NOV-2024		MOS HRS/MSC	-	AFL APH APS			
FAA 2024-19-15 PARA (L)	INSPECT THE OXYGEN VALVE ASSEMBLIES, AND OXYGEN CYLINDER AND VALVE ASSEMBLIES, TO DETERMINE IF THE SERIAL NUMBERS OF THE VALVE, CYLINDER, AND ENTIRE ASSEMBLY, ARE LISTED IN APPENDIX 3 (AFFECTED SHIPMENTS) OF THE APPLICABLE MATERIAL					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 20 DEC 2024 // WO CEIS-21/24
26-NOV-2024		MOS HRS/MSC	-	AFL APH APS			
FAA 2024-19-15 PARA (N)	NEW RETURN OF ADDITIONAL PARTS					MANDATORY	NOT APPLICABLE - PN NOT INSTALLED // CHECKDATE 20 DEC 2024 // WO CEIS-21/24
26-NOV-2024		MOS HRS/MSC	-	AFL APH APS			
FAA 2024-20-04	APPLIANCE AD - EQUIPMENT / FURNINSHINGS - INSPECTION OF PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE ASSEMBLIES (P/N) 1111475 (ALL DASH NUMBERS) AND P/N 1111548-01					MANDATORY	NOT APPLICABLE - ONLY FOR HELICOPTERS // CHECKDATE 20 DEC 2024 // WO CEIS-21/24
39-22662 12-NOV-2024		MOS HRS/MSC	-	AFL APH APS			
FAA 2024-26-02	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT					MANDATORY	NOT APPLICABLE - MAKE AND MODEL NOT INSTALLED // CHECKDATE 11 FEB 2025 // WO CEIS-02/25
39-21490 07-MAR-2025		MOS HRS/MSC	-	AFL APH APS			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2024-26-02 PARA (G)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE					MANDATORY	NOT APPLICABLE - MAKE AND MODEL NOT INSTALLED // CHECKDATE 11 FEB 2025 // WO CEIS-02/25
07-MAR-2025		MOS HRS/MSC - AFL APH APS					
FAA 2024-26-02 PARA (G)(2)	MEASURE THE THICHNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE					MANDATORY	NOT APPLICABLE - MAKE AND MODEL NOT INSTALLED // CHECKDATE 11 FEB 2025 // WO CEIS-02/25
07-MAR-2025		MOS HRS/MSC - AFL APH APS					
FAA 2024-26-02 PARA (G)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER					MANDATORY	NOT APPLICABLE - MAKE AND MODEL NOT INSTALLED // CHECKDATE 11 FEB 2025 // WO CEIS-02/25
07-MAR-2025		MOS HRS/MSC - AFL APH APS					
FAA 2025-07-01	APPLIANCE AD - THOMMEN AIRCRAFT EQUIPMENT AG (THOMMEN) AC32 DIGITAL AIR DATA COMPUTERS (ADCS)					MANDATORY	NOT APPLICABLE - MAKE AND MODEL NOT INSTALLED // CHECKDATE 25 APR 2025 // WO CEIS-05/25
39-23002 15-MAY-2025		MOS HRS/MSC - AFL APH APS					
LBA D-2010-011 R01	APPLIANCE AD - NAVIGATION - MODE S TRANSPONDER AIRCRAFT TYPE MODE STRAPPING - CHECK / MODIFICATION					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED - REFER TO ALREADY PERFORMED EASA AD 2010-0003 R2 - 2014-09-30 - 3160HOURS AND 3512 CYCLES
12-NOV-2014		MOS HRS/MSC - AFL APH APS		02-AUG-2016 4327 4340 1769 4931			
LBA D-2012-445 R01	APPLIANCE AD - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
		MOS HRS/MSC - AFL		02-FEB-2016 4024 4118			
TCCA CF-2013-25 26-AUG-2013	APPLIANCE AD - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING INSTALLATION DISCREPANCIES					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
		DAYs HRS/MSC - AFL		17-FEB-2014 2972:12 3326			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - SB - 680-0185/D-CEIS							
ASL ASL680-27-03 R02	RUDDER LOWER RIB CRACK INSPECTION, ALERT SERVICE LETTER					MANDATORY	COMPLIED WITH
05-MAR-2009		MOS HRS/MSC AFL		30-APR-2009 A/R 651			
AW 240226	RADAR ALTIMETER INTERFERENCE WITH 5G GROUND-STATIONS, ADVISORY WIRE			MOS HRS/MSC AFL			
AW 241024	NUISANCE CAS MSG MACH TRIM FAIL ON GROUND, ADVISORY WIRE			MOS HRS/MSC AFL			
COM MC 680-001	WINDOWS; SURFACE SEAL COATING REFORMULATION, COMMUNIQUE					INFORMATIONAL	
01-JUN-2020		MOS HRS/MSC AFL					
COM MC 680-002	TRAFFIC COLLISION AND AVOIDANCE SYSTEM ANTENNAS, COMMUNIQUE					INFORMATIONAL	
01-MAR-2023		MOS HRS/MSC AFL					
COM MC 680-004	NEW FLEXIBLE COUPLING P/N: 99040-6-6, COMMUNIQUE					INFORMATIONAL	
01-AUG-2024		MOS HRS/MSC AFL					
COM MC 680-005	LIGHTING, COMMUNIQUE					INFORMATIONAL	
01-NOV-2024		MOS HRS/MSC AFL					
COM MC 680-006	EQUIPMENT AND FURNISHINGS - TOILET SEAT CORROSION PROTECTION PROCEDURES, COMMUNIQUE					INFORMATIONAL	
01-JAN-2025		MOS HRS/MSC AFL					
OSN 240222	CHECK OF ENGINE COWLING FASTENER DURING PRE-FLIGHT INSPECTION, OPERATIONAL SAFETY NOTICE			MOS HRS/MSC AFL			
OSN 240223	CESSNA REMINDER FOR ENGINE START, OPERATIONAL SAFETY NOTICE			MOS HRS/MSC AFL			
OSN 240414	PFI MLG OLEO-STRUT CHECK, OPERATIONAL SAFETY NOTICE			MOS HRS/MSC AFL			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 680-11-01	ANTISKID VALVE PLACARDS, SERVICE BULLETIN					DISCRETIONARY	NOT APPLICABLE - N/A BY AIRCRAFT SERIAL NUMBER
15-JUL-2008		MOS HRS/MSC AFL		19-MAR-2013 2491:42 2781			
SB 680-21-02 R01	BLEED AIR FLOW IMPROVEMENT, SERVICE BULLETIN					DISCRETIONARY	COMPLIED WITH - SB 680-21-02 R1 « BLEED AIR FLOW IMPROVEMENT » COMPLIED WITH.
06-AUG-2010		MOS HRS/MSC AFL		22-FEB-2011 1540:12 1735			
SB 680-21-02 R02	AIR CONDITIONING - BLEED AIR FLOW IMPROVEMENT, SERVICE BULLETIN					DISCRETIONARY	COMPLIED WITH - PREVIOUS REVISION 1 OF THIS SB AT 22 FEB 2011 - 1540:12 HRS AND 1735 CYCLS // CHECKDATE 28 JUN 2019 // WO CEIS-10/19
11-APR-2019		MOS HRS/MSC AFL					
SB 680-21-06	CABIN COLD AIR DISTRIBUTION IMPROVEMENT, SERVICE BULLETIN					DISCRETIONARY	DECLINED - SB NOT PERFORMED. NOT REQUESTED BY THE CUSTOMER.
07-MAY-2008		MOS HRS/MSC AFL		(EFF)			
SB 680-21-08	AIR CONDITIONING - DUCT IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	DEFERRED - WILL BE DONE AT A LATER TIME
02-DEC-2015		MOS HRS/MSC AFL		(EFF)			
SB 680-22-01	AUTOPILOT DISCONNECT AURAL POWER REBUSSING (FOR EASA REGISTERED AIRPLANES), SERVICE BULLETIN					DISCRETIONARY	NOT APPLICABLE - N/A BY AIRCRAFT SERIAL NUMBER
11-JUL-2008		MOS HRS/MSC AFL		19-MAR-2013 2491:42 2781			
SB 680-23-03	KHF-1050 RADIO IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT SERIAL NUMBER
15-APR-2008		MOS HRS/MSC AFL		19-MAR-2013 2491:42 2781			
SB 680-23-08	COMMUNICATIONS - AIRCELL ATG ANTENNA BONDING IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	
03-MAY-2017		MOS HRS/MSC AFL					
SB 680-23-09	COMMUNICATIONS - AVIATOR 300 SATCOM INTERMEDIATE GAIN ANTENNA (IGA) REPLACEMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - SN AIRCRAFT NOT AFFECTED - CHECKDATE 27 APR 2021 // WO CEIS-07/21
24-FEB-2021		MOS HRS/MSC AFL APH APS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 680-24-08 R02	POWER DISTRIBUTION PCB IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT SERIAL NUMBER
30-OCT-2008	MOS HRS/MSC A/R AFL			19-MAR-2013 2491:42 2781			
SB 680-24-10	AFT FAIRING WIRE ROUTING MODIFICATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
23-JUL-2009	MOS HRS/MSC A/R AFL			20-APR-2010 1134			
SB 680-24-10 R01	AFT FAIRING WIRE ROUTING MODIFICATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - SB 680-24-10 R1 "AFT FAIRING WIRE ROUTING MODIFICATION" : SB C/W PER ORIGINAL APRIL 20, 2010. R1 NOT AFFEFFECTED BY ORIGINAL.
23-FEB-2010	MOS HRS/MSC A/R AFL			08-SEP-2010 1327 1479			
SB 680-24-11	ELECTRICAL POWER - FUEL CROSSFEED IMPROVEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - SB 680-24-11 "ELECTRICAL POWER – FUEL CROSS FEED IMPROVEMENT" COMPLIED WITH.
16-DEC-2010	MOS HRS/MSC A/R AFL			22-FEB-2011 1540:12 1735			
SB 680-24-11 R01	ELECTRICAL POWER - FUEL CROSSFEED IMPROVEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - SB 680-24-11 R1 "FUEL CROSS FEED IMPROVEMENT – STEP 13" COMPLIED WITH.
27-APR-2011	MOS HRS/MSC A/R AFL			24-FEB-2012 2058:36 2291			
SB 680-26-02	FIRE PROTECTION - BAGGAGE FIRE BOTTLE SUPPRESSION SWITCH IMPROVEMENT, SERVICE BULLETIN					OPTIONAL	- TO BE PROPOSED TO THE CUSTOMER.
	MOS HRS/MSC A/R AFL						
SB 680-27-02	RIGHT AILERON TRIM-ACTUATOR INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - N/A BY AIRCRAFT SERIAL NUMBER
31-MAR-2009	MOS HRS/MSC - AFL			19-MAR-2013 2491:42 2781			
SB 680-27-05	STEEP APPROACH CERTIFICATION, SERVICE BULLETIN					DISCRETIONARY	NOT APPLICABLE - N/A BY AIRCRAFT SERIAL NUMBER
17-DEC-2009	MOS HRS/MSC A/R AFL			19-MAR-2013 2491:42 2781			
SB 680-27-09	RUDDER CABLE CLEARANCE IMPROVEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - SB 680-27-09 "RUDDER CABLE CLEARANCE IMPROVEMENT" COMPLIED WITH.
18-JUN-2010	MOS HRS/MSC A/R AFL			22-FEB-2011 1540:12 1735			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 680-27-11	RUDDER BIAS ACTUATOR IMPROVEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO AIRCRAFT SERIAL NUMBERS 680-0001 THRU 680-0159 ONLY.
04-AUG-2010		MOS HRS/MSC A/R AFL					
SB 680-27-12	RUDDER BIAS ACTUATOR IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
17-JUN-2013		MOS HRS/MSC - AFL		20-FEB-2014 2972:12 3326			
SB 680-27-12 R01	FLIGHT CONTROLS - RUDDER BIAS ACTUATOR IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	- COMPLIED WITH ORIGINAL VERSION OF THIS SB
		MOS HRS/MSC - AFL		(EFF)			
SB 680-27-13	FLAP HANDLE ASSEMBLY SCREW IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - SB 680-27-13 „FLAP HANDLE ASSEMBLY SCREW IMPROVEMENT“ COMPLIED WITH.
20-FEB-2012		MOS HRS/MSC - AFL		31-OCT-2012 2333:54 2601			
SB 680-27-14	FLIGHT CONTROLS - ELEVATOR TRIM ACTUATOR PIN IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	
01-AUG-2016		MOS HRS/MSC - AFL					
SB 680-27-15 R01	FLIGHT CONTROLS - MACH TRIP PCB IMPROVEMENT (CANCELLED), SERVICE BULLETIN					DISCRETIONARY	
20-JUL-2016		MOS HRS/MSC - AFL					
SB 680-27-15 R02	FLIGHT CONTROLS - MACH TRIP PCB IMPROVEMENT (CANCELLED), SERVICE BULLETIN					DISCRETIONARY	
27-APR-2017		MOS HRS/MSC - AFL					
SB 680-27-16	FLIGHT CONTROLS - MACH TRIM PCB IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	
17-JUL-2017		MOS HRS/MSC - AFL					
SB 680-27-16 R01	FLIGHT CONTROLS - MACH TRIM PCB IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	
15-DEC-2021		MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 680-27-17	FLIGHT CONTROLS - HORIZONTAL STABILIZER CONTROLLER WATER SHIELD INSTALLATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PERFORMED SERVICE BULLETIN 680-27-17 FLIGHT CONTROLS - HORIZONTAL STABILIZER CONTROLLER WATER SHIELD INSTALLATION IAW SB680-27-17 (ORIGINAL ISSUE, DATED DECEMBER 18,2023) AND C680 AMM (REV.33), CHAPTER 27-40-10 (REV.20) FOUND SATISFACTORY.
18-DEC-2023		MOS HRS/MSC - AFL		12-DEC-2024 9226:16 7930			
SB 680-28-01	FUEL HOSE ROUTING IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT SERIAL NUMBER
17-MAR-2008		MOS HRS/MSC A/R AFL		19-MAR-2013 2491:42 2781			
SB 680-28-02	PRIMARY EJECTOR PUMP CLAMPING IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - SB680-28-02 {PRIMARY EJECTOR PUMP CLAMPING IMPROVEMENT}, COMPLIED WITH.
08-JUN-2012		MOS HRS/MSC - AFL		31-OCT-2012 2333:54 2601			
SB 680-29-06	HYDRAULIC POWER - AUXILIARY PUMP MANIFOLD TRANSDUCER REPLACEMENT, SERVICE BULLETIN					OPTIONAL	
25-OCT-2018		MOS HRS/MSC - AFL					
SB 680-29-06 R01	HYDRAULIC POWER - AUXILIARY PUMP MANIFOLD OR AUXILIARY PUMP MANIFOLD PRESSURE TRANSDUCER REPLACEMENT, SERVICE BULLETIN					OPTIONAL	
18-SEP-2019		MOS HRS/MSC - AFL					
SB 680-30-04	6914060-15 WING ANTI-ICE TUBE ASSEMBLY REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - N/A BY AIRCRAFT SERIAL NUMBER
21-NOV-2008		MOS HRS/MSC - AFL		19-MAR-2013 2491:42 2781			
SB 680-30-05	ANTI-ICE TUBE CLAMP REPLACEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - SERVICE BULLETIN ON HOLD.
08-APR-2009		MOS HRS/MSC A/R AFL		20-APR-2010 1134			
SB 680-30-05 R01	ANTI-ICE TUBE CLAMP REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - ORIGINAL ISSUE COMPLIED WITH, R1 HAS NO EFFECT
		MOS HRS/MSC A/R AFL		09-JUN-2014 3055:12 3428			
SB 680-32-02	MAIN LANDING GEAR RELEASE HANDLE REPLACEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
09-DEC-2008		MOS HRS/MSC A/R AFL		31-JUL-2009 786			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 680-32-04	BRAKE METERING VALVE BEARING REPLACEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - SB680-32-04 "BRAKE METERING VALVE BEARING REPLACEMENT" COMPLIED WITH.
02-JUN-2010		MOS HRS/MSC AFL		22-FEB-2011 1540:12 1735			
SB 680-32-05	MAIN LANDING GEAR SIDE BRACE FITTING INSTALLATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
16-AUG-2013		MOS HRS/MSC AFL		20-MAY-2014 3026 3394			
SB 680-32-05 R01	MAIN LANDING GEAR SIDE BRACE FITTING INSTALLATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - ORIGINAL VERSION OF THIS SB
29-APR-2015		MOS HRS/MSC AFL APH APS		09-FEB-2017 4721:48 4594 1898 5206			
SB 680-32-05 R02	LANDING GEAR - MAIN LANDING GEAR SIDE BRACE FITTING INSTALLATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - ORIGINAL VERSION OF THIS SB
16-NOV-2016		MOS HRS/MSC AFL APH APS		09-FEB-2017 4721:48 4594 1898 5206			
SB 680-32-05 R03	LANDING GEAR - MAIN LANDING GEAR SIDE BRACE FITTING INSTALLATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - ORIGINAL REVISION OF THIS SB AT 20 MAY 2024 WITH 3026 HRS AND 3394 CYCLES // CHECKDATE 11 APR 2024 // WO CEIS-05/24
18-MAR-2024		MOS HRS/MSC AFL					
SB 680-32-06	NOSE LANDING GEAR ISOLATOR-PIN REPLACEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
17-OCT-2013		MOS HRS/MSC AFL		24-DEC-2013 2912:18 3262			
SB 680-32-07	LANDING GEAR - REPLACEMENT OF THE NOSE LANDING GEAR WIRE BUNDLE ASSEMBLY, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - S/N AIRCRAFT NOT Affected // CHECKDATE 06 MAY 2020 // WO CEIS-03/20
12-MAR-2020		MOS HRS/MSC AFL APH APS					
SB 680-33-03 R01	EMERGENCY EXIT LED LIGHT INSTALLATION, SERVICE BULLETIN					OPTIONAL	DECLINED - SB OPTIONAL NOT PERFORMED. NOT REQUESTED BY THE CUSTOMER.
13-MAY-2008		MOS HRS/MSC AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 680-33-04	BAGGAGE COMPARTMENT LIGHT ASSEMBLY REPLACEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
16-JUL-2008	MOS HRS/MSC A/R AFL			10-OCT-2008 393			
SB 680-33-05	EMERGENCY EGRESS LIGHTING IMPROVEMENT, SERVICE BULLETIN					DISCRETIONARY	DECLINED - AIRCRAFT IS OUT OF 5 YEARS AIRFRAME WARRANTY
14-AUG-2014	MOS HRS/MSC - AFL						
SB 680-33-05 R01	EMERGENCY EGRESS LIGHTING IMPROVEMENT, SERVICE BULLETIN					DISCRETIONARY	DECLINED - AIRCRAFT IS OUT OF 5 YEARS AIRFRAME WARRANTY
25-NOV-2014	MOS HRS/MSC - AFL						
SB 680-33-08	LANDING GEAR - LED TAXI LIGHT MODIFICATION, SERVICE BULLETIN					OPTIONAL	
28-SEP-2022	MOS HRS/MSC - AFL						
SB 680-34-05 R01	ENHANCED SURVEILLANCE TRANSPONDER UPGRADE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - SB 680-34-05 R1 "ENHANCED SURVEILLANCE TRANSPONDER UPGRADE" A/C EQUIPPED WITH.
05-APR-2007	MOS HRS/MSC - AFL			08-SEP-2010 1327 1479			
SB 680-34-07	PHASE 3 TAKE-OFF AND LANDING DATABASE (TOLD) SOFTWARE UPDATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - SB 680-34-07 "PHASE 3 T/O & LANDING UPDATE" : A/C DELIVERED WITH VERSION 4.1 AND A/C C/W WITH VERSION 4.2.
04-APR-2006	MOS HRS/MSC - AFL			08-SEP-2010 1327 1479			
SB 680-34-09	CATEGORY II OPERATIONS, SERVICE BULLETIN					OPTIONAL	DECLINED - SB OPTIONAL NOT PERFORMED. NOT REQUESTED BY THE CUSTOMER.
22-AUG-2007	MOS HRS/MSC - AFL			(EFF)			
SB 680-34-09 R01	CATEGORY II OPERATIONS, SERVICE BULLETIN					OPTIONAL	DECLINED - SB OPTIONAL NOT PERFORMED. NOT REQUESTED BY THE CUSTOMER.
30-AUG-2012	MOS HRS/MSC - AFL						
SB 680-34-09 R02	CATEGORY II OPERATIONS, SERVICE BULLETIN					OPTIONAL	
21-JAN-2015	MOS HRS/MSC - AFL						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 680-34-17 R01	EPIC PHASE 4 CHART INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - AIRCRAFT ALREADY EQUIPPED.
		MOS HRS/MSC AFL		(EFF)			
27-JAN-2009							
SB 680-34-17 R02	EPIC PHASE 4 CHART INSTALLATION, SERVICE BULLETIN					OPTIONAL	
		MOS HRS/MSC AFL					
30-OCT-2014							
SB 680-34-19	WEATHER UPLINK SOFTWARE INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - AIRCRAFT ALREADY EQUIPPED.
		MOS HRS/MSC AFL		(EFF)			
21-AUG-2008							
SB 680-34-19 R01	WEATHER UPLINK SOFTWARE INSTALLATION, SERVICE BULLETIN					OPTIONAL	
		MOS HRS/MSC AFL					
30-OCT-2014							
SB 680-34-20	EPIC PHASE 5 SOFTWARE UPGRADE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - SB 680-34-20 « EPIC PH. 5 SOFTWARE UPGRADE » COMPLIED WITH AND FLIGHT MANUAL UPDATED.
		MOS HRS/MSC AFL		22-FEB-2011 1540:12 1735			
25-JUN-2010							
SB 680-34-20 R01	EPIC PHASE 5.2 SOFTWARE UPGRADE, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - SB 680-34-20 R1 "EPIC PHASE 5.2 SOFTWARE UPGRADE" COMPLIED WITH. PILOT'S GUIDE UPDATED.
		MOS HRS/MSC AFL		03-JUL-2012 2218:18 2473			
SB 680-34-22 R01	EPIC PHASE 4.1 SOFTWARE UPGRADE AND DATABASE UPDATE INCLUDING TOLD UPDATES FOR GROSS WEIGHT INCREASE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT SERIAL NUMBER
		MOS HRS/MSC AFL		19-MAR-2013 2491:42 2781			
15-APR-2008							
SB 680-34-23 R01	EPIC PHASE 4.2 SOFTWARE UPGRADE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS HRS/MSC AFL		16-FEB-2009 560			
09-SEP-2008							
SB 680-34-24	COAXIAL CABLE ASSEMBLY REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT SERIAL NUMBER
		MOS HRS/MSC AFL		19-MAR-2013 2491:42 2781			
29-OCT-2008							
SB 680-34-27	WIDE AREA AUGMENTATION SYSTEM (WAAS) INSTALLATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
		MOS HRS/MSC AFL		04-MAY-2020 6659:50 6099			
25-JUN-2010							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 680-34-28	RUNWAY AWARENESS ADVISORY SYSTEM (RAAS) INSTALLATION, SERVICE BULLETIN					OPTIONAL	DECLINED - SB OPTIONAL NOT PERFORMED. NOT REQUESTED BY THE CUSTOMER.
25-JUN-2010		MOS HRS/MSC AFL					
SB 680-34-29	TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - AD 2012-02-08 "AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS : COMPLIED WITH PER ACCOMPLISHMENT OF THE SB 680-34-29 "TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE"
		MOS HRS/MSC AFL		03-JUL-2012 2218:18 2473			
SB 680-34-29 R01	TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE FOR SOFTWARE VERSION 7.0, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - ORIGINAL ISSUE C/W ON 03-JUL-12 AT 2218.3 . AIRPLANES PREVIOUSLY MODIFIED BY THIS SERVICE BULLETIN ARE NOT EFFECTED BY THIS REVISION.
		MOS HRS/MSC AFL					
SB 680-34-29 R02	NAVIGATION - TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE FOR SOFTWARE VERSION 7.0, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - ORIGINAL ISSUE C/W ON 03-JUL-12 AT 2218.3 . AIRPLANES PREVIOUSLY MODIFIED BY THIS SERVICE BULLETIN ARE NOT EFFECTED BY THIS REVISION.
24-OCT-2012		MOS HRS/MSC AFL					
SB 680-34-30	TCAS 2000 SOFTWARE UPDATE TO VERSION 7.1, SERVICE BULLETIN					OPTIONAL	- SUPERSEDED BY REVISION 1.
17-JUL-2012		MOS HRS/MSC AFL					
SB 680-34-30 R01	NAVIGATION - TCAS 2000 SOFTWARE UPDATE TO VERSION 7.1, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - PERFORMED SB680-34-30 REV1 IAW SB INSTRUCTIONS SAT.
24-OCT-2012		MOS HRS/MSC AFL		16-MAY-2015 3444:24 3715			
SB 680-34-32	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE, SERVICE BULLETIN						NOT APPLICABLE - EQUIPMENT NOT INSTALLED
16-JUL-2015		MOS HRS/MSC AFL					
SB 680-34-33 R02	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION, SERVICE BULLETIN					OPTIONAL	
28-FEB-2017		MOS HRS/MSC AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 680-34-33 R03	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
19-APR-2019		MOS HRS/MSC - AFL		04-MAY-2020 6659:50 6099			
SB 680-34-33 R04	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - C/W PREVIOUS REV 03 AT 6659:50 HRS AND 6099 LDGS - WO CEIS-01/20 - AIRPLANES PREV MODIFIED BY THIS SB ARE NOT AFFECTED BY THIS REV // CHECKDATE 12 NOV 2020 // WO CEIS-08/20
24-JUL-2020		MOS HRS/MSC - AFL					
SB 680-36-03	PYLON PRECOOLER EXHAUST SEAL IMPROVEMENT, SERVICE BULLETIN					DISCRETIONARY	COMPLIED WITH
07-MAY-2008		MOS HRS/MSC A/R AFL		31-JUL-2009 786			
SB 680-36-04	AIR EJECTOR MODIFICATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
15-JAN-2009		MOS HRS/MSC A/R AFL		31-JUL-2009 786			
SB 680-36-05	PNEUMATIC - SERVICE AIR VACUUM EJECTOR SYSTEM MODIFICATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
15-APR-2011		MOS HRS/MSC A/R AFL					
SB 680-38-01	TOILET OVERRIDE RELAY INSTALLATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - COMPLIED WITH CESSNA SB680-38-01 ON 680-0185 IAW SB INSTRUCTIONS
09-JUN-2014		MOS HRS/MSC - AFL		18-APR-2016 4097 4165			
SB 680-49-09	AUXILIARY POWER - APU GENERATOR CONTROL PCB IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - SB 680-49-09 "APU GENERATOR CONTROL PCB IMPROVEMENT" COMPLIED WITH.
04-MAY-2011		MOS HRS/MSC - AFL		02-DEC-2011 1941:36 2168			
SB 680-49-09 R01	APU GENERATOR CONTROL PCB IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - ORIGINAL ISSUE C/W ON 02-DEC-11 AT 1941.6 . AIRPLANES PREVIOUSLY MODIFIED BY THIS SERVICE LETTER ARE NOT AFFECTED BY THIS REVISION.
29-OCT-2012		MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 680-49-09 R02	APU GENERATOR CONTROL PCB IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	- COMPLIED WITH ORIGINAL VERSION OF THIS SB
		MOS					
	28-MAY-2014	HRS/MSC	-				
		AFL					
SB 680-52-04	MAIN CABIN DOOR REPAIR, SERVICE BULLETIN					DISCRETIONARY	COMPLIED WITH
		MOS		20-MAY-2014			
	14-JUN-2013	HRS/MSC	-	3026			
		AFL		3394			
SB 680-52-05	DOORS - CABIN DOOR SUPPORT STRUT FITTING MODIFICATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - COMPLIED WITH CESSNA SB680-52-05 IAW SB INSTRUCTIONS
		MOS		18-APR-2016			
	09-FEB-2016	HRS/MSC	-	4097			
		AFL		4165			
SB 680-52-06	DOORS - EMERGENCY EXIT DOOR INNER HANDLE HARDWARE REPLACEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		DAYS		04-MAY-2020			
	20-DEC-2019	HRS/MSC	-	6659:50			
		AFL		6099			
SB 680-52-07	DOORS - LAVATORY SERVICE DOOR PANEL PAN FLUID SEAL INSTALLATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - PERFORMED SERVICE BULLETIN 680-52-07 DOORS - LAVATORY SERVICE DOOR PANEL PAN FLUID SEAL INSTALLATION IAW. SB680-52-07 INSTRUCTIONS.
		MOS		12-DEC-2024			
	03-SEP-2024	HRS/MSC	-	9226:16			
		AFL		7930			
SB 680-53-02	APU INLET SCREEN IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		31-JUL-2009			
	19-AUG-2008	HRS/MSC	A/R	786			
SB 680-53-03	F.S. 58.30 FRAME MODIFICATION , SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - N/A BY AIRCRAFT SERIAL NUMBER
		MOS		19-MAR-2013			
	29-JUN-2010	HRS/MSC	A/R	2491:42			
		AFL		2781			
SB 680-53-04	FORWARD PRESSURE BULKHEAD FASTENER INSPECTION, SERVICE BULLETIN					MANDATORY	- SUPERSEDED BY R1
		MOS					
	19-MAY-2010	HRS/MSC	-				
		AFL					
SB 680-53-04 R01	FORWARD PRESSURE BULKHEAD FASTENER INSPECTION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - SB680-53-04 R1 "FWD PRESSURE BULKHEAD INSPECTION" COMPLIED WITH.
		MOS		22-FEB-2011			
	06-AUG-2010	HRS/MSC	-	1540:12			
		AFL		1735			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 680-53-05	NOSE DRIP CAP BOND INSPECTION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - BY COMPLIANCE OF REVISION 1 ON 02-DEC-11 AT 1941.6
		MOS					
20-JUL-2011		HRS/MSC	-				
		AFL					
SB 680-53-05 R01	NOSE DRIP CAP BOND INSPECTION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - SB 680-53-05R1 "FUSELAGE – NOSE DRIP CAP BOND INSPECTION" COMPLIED WITH.
		MOS		02-DEC-2011			
05-OCT-2011		HRS/MSC	-	1941:36			
		AFL		2168			
SB 680-53-06	STINGER DRAIN IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - SB 680-53-06 «FUSELAGE – STINGER DRAIN IMPROVEMENT » COMPLIED WITH.
		MOS		02-DEC-2011			
		HRS/MSC	-	1941:36			
		AFL		2168			
SB 680-53-06 R01	STINGER DRAIN IMPROVEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - SB PERFORMED
		MOS		08-NOV-2015			
		HRS/MSC	-	3852			
		AFL		4006			
SB 680-53-07	STINGER DRAIN TUBE INSTALLATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - SB PERFORMED
		MOS		08-NOV-2015			
08-JUL-2015		HRS/MSC	-	3852			
		AFL		4006			
SB 680-53-08	FUSELAGE - AFT CANTED BULKHEAD MODIFICATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - COMPLIED WITH CESSNA SB680-53-08 ON 680-0185 PER SB INSTRUCTIONS
		MOS		18-APR-2016			
		HRS/MSC	-	4097			
		AFL		4165			
SB 680-53-08 R02	FUSELAGE - AFT CANTED BULKHEAD MODIFICATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - ORIGINAL VERSION OF THIS SB
		MOS		09-FEB-2017			
02-NOV-2016		HRS/MSC	-	4721:48			
		AFL		4594			
		APH		1898			
		APS		5206			
SB 680-54-01	NACELLES/PYLONS - VORTEX GENERATOR INSTALLATION ON PYLONS AND NACELLES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
09-DEC-2015		HRS/MSC	-				
		AFL					
SB 680-55-02 R01	STABILIZERS - VERTICAL FIN DRAIN MODIFICATION, SERVICE BULLETIN					DISCRETIONARY	COMPLIED WITH
		MOS		22-NOV-2018			
17-MAY-2016		HRS/MSC	-	5955:39			
		AFL		5506			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 680-71-06	POWER PLANT - INSTALLATION OF THE 6957100-62 RIGHT HYDRAULIC PRESSURE TUBE AND REPLACEMENT OF ALUMINUM CLAMPS WITH CORROSION RESISTANT STEEL CLAMPS IN ENGINE BAY, SERVICE BULLETIN					RECOMMENDED	
07-AUG-2023	MOS HRS/MSC - AFL						
SB 680-71-06 R01	POWER PLANT - INSTALLATION OF THE 6957100-62 RIGHT HYDRAULIC PRESSURE TUBE AND REPLACEMENT OF THE LEFT AND RIGHT ALUMINUM CLAMPS WITH CORROSION RESISTANT STEEL CLAMPS IN THE LEFT AND RIGHT ENGINE BAY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PERFORMED SERVICE BULLETIN 680-71-06 R01 POWER PLANT -INSTALLATION OF THE 6957100-62 RIGHT HYDRAULIC PRESSURE TUBE AND REPLACEMENT OF THE LEFT AND RIGHT ALUMINUM CLAMPS WITH CORROSION RESISTANT STEEL CLAMPS IN THE LEFT AND RIGHT ENGINE BAY IAW. SB680-71-06 INSTRUCTIONS.
08-JAN-2024	MOS HRS/MSC - AFL			12-DEC-2024 9226:16 7930			
SB 680-76-02	ENGINE CONTROLS - MODIFICATION OF LEFT AND RIGHT FULL AUTHORITY DIGITAL ENGINE CONTROL (FADEC) WIRE HARNESS ASSEMBLY CLAMPING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
15-NOV-2019	MOS HRS/MSC - AFL			04-MAY-2020 6659:50 6099			
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC), SERVICE LETTER					INFORMATIONAL	
03-JUN-2013	MOS HRS/MSC - AFL						
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL, SERVICE LETTER					INFORMATIONAL	- CIL TOOK IN ACCOUNT.
09-APR-2012	MOS HRS/MSC - AFL						
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL, SERVICE LETTER					INFORMATIONAL	
18-MAR-2014	MOS HRS/MSC - AFL						
SL CIL-20-01 R03-CN	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL, SERVICE LETTER					INFORMATIONAL	
30-MAY-2023	MOS HRS/MSC - AFL						
SL CIL-21-03	AIR CONDITIONING - TRANSMITTAL OF HONEYWELL SB 2341316-21-2828, INSPECTION AND REPAIR OF THE INTERIOR SURFACES OF THE WATER SEPARATOR, PN 2341316-2 AND -3, FOR CORROSION, SERVICE LETTER					INFORMATIONAL	
22-OCT-2015	MOS HRS/MSC - AFL						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL CIL-21-03 R01	AIR CONDITIONING - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 2341316-21-2828, INSPECTION AND REPAIR OF THE INTERIOR SURFACES OF THE WATER SEPARATOR, PN 2341316-2 AND -3, FOR CORROSION, SERVICE LETTER					INFORMATIONAL	
25-MAY-2022		MOS HRS/MSC - AFL					
SL CIL-25-02	EQUIPMENT/FURNISHINGS - MEDAIRE AIRCRAFT FIRST AID KITS WITH MEDICATION SUBJECT TO RECALL NOTICE, SERVICE LETTER					INFORMATIONAL	NOT APPLICABLE - S/N AIRCRAFT NOT AFFECTED - CHECKDATE 20 JAN 2020 // WO CEIS-02/20
05-NOV-2019		MOS HRS/MSC - AFL APH APS					
SL CIL-25-03	EQUIPMENT/FURNISHINGS - SEAT PAN TILT BLOCKING TAB INSTALLATION, SERVICE LETTER					INFORMATIONAL	NOT APPLICABLE - S/N AIRCRAFT NOT AFFECTED // CHECKDATE 12 NOV 2020 // WO CEIS-08/20
12-AUG-2020		MOS HRS/MSC - AFL APH APS					
SL CIL-25-03 R01	EQUIPMENT/FURNISHINGS - SEAT PAN TILT BLOCKING TAB INSTALLATION, SERVICE LETTER					INFORMATIONAL	NOT APPLICABLE - S/N AIRCRAFT NOT AFFECTED // CHECKDATE 12 NOV 2020 // WO CEIS-08/20
08-OCT-2020		MOS HRS/MSC - AFL APH APS					
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING, SERVICE LETTER					MANDATORY	COMPLIED WITH - REVISION 1 OF THIS SB
10-MAY-2016		MOS HRS/MSC - AFL		(EFF)			
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING, SERVICE LETTER					MANDATORY	COMPLIED WITH
16-JUN-2016		MOS HRS/MSC - AFL APH APS		07-DEC-2016 4599:30 4511 1864 5129			
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS, SERVICE LETTER					INFORMATIONAL	
24-FEB-2023		MOS HRS/MSC - AFL					
SL CIL-30-01 R01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES, SERVICE LETTER					INFORMATIONAL	
13-SEP-2013		MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION, SERVICE LETTER						INFORMATIONAL
02-FEB-2018		MOS HRS/MSC - AFL					
SL CIL-32-02	NOSE LANDING GEAR ISOLATOR-PIN INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH - SL CIL 32-02 „NOSE LANDING GEAR ISOLATOR PIN INSPECTION“ COMPLIED WITH. NO DEFECT FOUND.
		DAY HRS/MSC - AFL		17-OCT-2013 2818 3148			
SL CIL-32-02 R01	NOSE LANDING GEAR ISOLATOR-PIN INSPECTION, SERVICE LETTER					MANDATORY	NOT APPLICABLE - BY SB 680-32-06 COMPLIED WITH
13-JUN-2013		DAY HRS/MSC - AFL		24-DEC-2013 2912:18 3262			
SL CIL-33-01	TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY, SERVICE LETTER						INFORMATIONAL
		MOS HRS/MSC - AFL					
SL CIL-34-06	NAVIGATION - TRANSMITTAL OF HONEYWELL SIL D20120600008R002, PRIMUS EPIC AND PRIMUS II MODE S TRANSPONDER; (1) TCAS, CHANGE 7.1, REPORTS AN EARLIER TCAS II VERSION NUMBER TO ATC GROUND STATIONS, (2) IMPROPER SUPPORT OF EHS IN MODE S RADAR COVERAGE USING A SI CODE, SERVICE LETTER						INFORMATIONAL
29-OCT-2015		MOS HRS/MSC - AFL					
SL CIL-34-06 R01	NAVIGATION - TRANSMITTAL OF HONEYWELL SIL D20120600008R002, PRIMUS EPIC AND PRIMUS II MODE S TRANSPONDER; (1) TCAS, CHANGE 7.1, REPORTS AN EARLIER TCAS II VERSION NUMBER TO ATC GROUND STATIONS, (2) IMPROPER SUPPORT OF EHS IN MODE S RADAR COVERAGE USING A SI CODE, SERVICE LETTER						INFORMATIONAL
13-JAN-2016		MOS HRS/MSC - AFL					
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001, SERVICE LETTER					MANDATORY	NOT APPLICABLE - NOT APPLICABLE - P/N NOT INSTALLED
08-JAN-2016		DAY HRS/MSC - AFL		02-FEB-2016 4024 4118			
SL CIL-53-01	FUSELAGE - NOSE RADOME GUIDE PIN REPLACEMENT, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - SN AIRCRAFT NOT AFFECTED // CHECKDATE 12 JAN 2021 // WO CEIS-03/21
17-DEC-2020		MOS HRS/MSC - AFL APH APS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL CIL-53-01 R01	FUSELAGE - NOSE RADOME GUIDE PIN REPLACEMENT, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - SN AIRCRAFT NOT AFFECTED - CHECKDATE 27 APR 2021 // WO CEIS-07/21
17-MAR-2021	MOS HRS/MSC - AFL APH APS						
SL CIL-76-01	ENGINE CONTROLS - TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW300-72-25462, TURBOFAN ENGINE INSPECTION OF OUTER ELECTRICAL HARNESS, SERVICE LETTER					INFORMATIONAL	COMPLIED WITH - SB PW300-72-25462 17 NOV 2021 AT 7490:26 HRS AND 6618 CYCLES // CHECKDATE 22 JUN 2022 // WO CEIS-02/22
25-MAR-2022	MOS HRS/MSC - AFL						
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS, SERVICE LETTER					INFORMATIONAL	COMPLIED WITH - COMPLIED WITH SL CIL99-01 REV1
12-JAN-2012	MOS HRS/MSC - AFL			16-MAY-2015 3444:24 3715			
SL CIL-99-01 R01	USE OF CORROSION INHIBITING COMPOUNDS, SERVICE LETTER					INFORMATIONAL	COMPLIED WITH - PERFORMED SL CIL99-01 REV1 ON BOTH HORIZONTAL AFT SPAR ASSYS, ON VERTICAL AFT SPAR ASSY, ON BOTH WING AFT SPAR ASSYS, ALL LANDING GEAR WHEEL WELLS, ALL UPPER (NON VISIBLE) PARTS OF LANDING GEARS AND IN BOTH MLG TRAILING LINK BORES AS PER CIL INSTRUCTIONS
15-FEB-2013	MOS HRS/MSC - AFL			16-MAY-2015 3444:24 3715			
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS, SERVICE LETTER					INFORMATIONAL	COMPLIED WITH - COMPLIED WITH CESSNA CIL99-01 REV2 IAW CIL INSTRUCTIONS SAT. FOR FURTHER DETAILS REFER TO CESSNA DUS REV 20002482 ORDER 10397562
02-JUL-2015	MOS HRS/MSC - AFL			18-APR-2016 4097 4165			
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS, SERVICE LETTER					INFORMATIONAL	
14-AUG-2019	MOS HRS/MSC - AFL						
SL CIL-99-02	AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS, SERVICE LETTER					RECOMMENDED	- CIL TOOK IN ACCOUNT.
23-MAY-2012	MOS HRS/MSC - AFL			(EFF)			
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS, SERVICE LETTER					INFORMATIONAL	
14-AUG-2019	MOS HRS/MSC - AFL						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL CIL-99-03	CORROSION PREVENTION AND CONTROL PROGRAM (CPCP), SERVICE LETTER					RECOMMENDED	- CIL TOOK IN ACCOUNT.
04-JAN-2013		MOS		(EFF)			
		HRS/MSC	-				
		AFL					
SL CIL-99-03 R01	CORROSION PREVENTION AND CONTROL PROGRAM (CPCP), SERVICE LETTER					RECOMMENDED	
25-MAR-2013		MOS					
		HRS/MSC	-				
		AFL					
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP), SERVICE LETTER					INFORMATIONAL	
14-AUG-2019		MOS					
		HRS/MSC	-				
		AFL					
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW, SERVICE LETTER					INFORMATIONAL	
29-JAN-2016		MOS					
		HRS/MSC	-				
		AFL					
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW, SERVICE LETTER					INFORMATIONAL	
14-AUG-2019		MOS					
		HRS/MSC	-				
		AFL					
SL CIL-99-05	MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS, SERVICE LETTER					INFORMATIONAL	
09-DEC-2024		MOS					
		HRS/MSC	-				
		AFL					
SL SL680-05-01	CORROSIVE ENVIRONMENT INSPECTION, SERVICE LETTER					INFORMATIONAL	
23-FEB-2006		MOS					
		HRS/MSC	O/C				
		AFL					
SL SL680-05-02	TIME LIMITS/MAINTENANCE CHECKS - MSG-3 SCHEDULED MAINTENANCE PROGRAM CHANGE BRIDGING DOCUMENT (SUPERSEDED BY SL680-05-02 R01), SERVICE LETTER					INFORMATIONAL	
08-DEC-2017		MOS					
		HRS/MSC	-				
		AFL					
SL SL680-05-02 R01	TIME LIMITS/MAINTENANCE CHECKS - MSG-3 SCHEDULED MAINTENANCE PROGRAM CHANGE BRIDGING DOCUMENT (SUPERSEDED BY SL680-05-02 R02), SERVICE LETTER					INFORMATIONAL	
07-FEB-2018		MOS					
		HRS/MSC	-				
		AFL					
SL SL680-05-02 R02	TIME LIMITS/MAINTENANCE CHECKS - MSG-3 SCHEDULED MAINTENANCE PROGRAM CHANGE BRIDGING DOCUMENT, SERVICE LETTER					INFORMATIONAL	
11-APR-2018		MOS					
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL680-05-03	TIME LIMITS/MAINTENANCE CHECKS – NEW INSPECTION TASK 53-30-00-2500 AND INSPECTION DOCUMENT 25 IMPLEMENTATION GRACE PERIOD, SERVICE LETTER					INFORMATIONAL	
13-DEC-2018	MOS HRS/MSC - AFL						
SL SL680-05-04	TIME LIMITS/MAINTENANCE CHECKS - NEW NOSEWHEEL STEERING HOSE REPLACEMENT INTERVAL IMPLEMENTATION GRACE PERIOD, SERVICE LETTER				04-MAY-2020 6659:50 6099	INFORMATIONAL	COMPLIED WITH
22-AUG-2019	MOS HRS/MSC - AFL						
SL SL680-20-01 R06	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL, SERVICE LETTER					INFORMATIONAL	- SL TOOK IN ACCOUNT.
07-DEC-2010	MOS HRS/MSC A/R AFL						
SL SL680-20-01 R07	SUPERSEDED BY CIL-20-01 R2, SERVICE LETTER					INFORMATIONAL	- INFORMATIONAL
21-SEP-2012	MOS HRS/MSC - AFL						
SL SL680-20-02	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL, SERVICE LETTER					INFORMATIONAL	
05-OCT-2017	MOS HRS/MSC - AFL						
SL SL680-21-04	TRANSMITTAL OF HONEYWELLS SERVICE BULLETIN 2215460-21-2814, AIR CONDITIONING - ENVIRONMENTAL CONTROL UNIT - MODIFICATION OF ENVIRONMENTAL CONTROL UNIT (ECU), PN 2215460-2 SERIES 2, OR PN 2215460-3 SERIES 1, BY REPLACEMENT OF COMPRESSOR OUTLET OVER TEMPERATURE SWITCH, PN 927223-2-2, SERVICE LETTER					INFORMATIONAL	- INFORMATIONAL
03-JUN-2010	MOS HRS/MSC A/R AFL						
SL SL680-23-02	ARINC DIRECT SERVICE FOR CMF, SERVICE LETTER					OPTIONAL	DECLINED - SL OPTIONAL NOT PERFORMED. NOT REQUESTED BY THE CUSTOMER.
10-SEP-2007	MOS HRS/MSC A/R AFL			(EFF)			
SL SL680-23-05	COMMUNICATIONS - ATG-4000 SOFTWARE UPDATE, SERVICE LETTER					RECOMMENDED	
03-MAY-2017	MOS HRS/MSC - AFL						
SL SL680-23-05 R01	COMMUNICATIONS - ATG-4000 SOFTWARE UPDATE, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - SN AIRCRAFT NOT AFFECTED // CHECKDATE 16 JUN 2023 // WO CEIS-12/23
22-MAY-2023	MOS HRS/MSC - AFL APH APS						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL680-23-06	COMMUNICATIONS - ATG 4000 SOFTWARE UPDATE, SERVICE LETTER					OPTIONAL	
12-SEP-2017		MOS HRS/MSC - AFL					
SL SL680-23-07	COMMUNICATIONS - ATG 4000 SOFTWARE UPDATE TO VERSION 2.8, SERVICE LETTER					OPTIONAL	NOT APPLICABLE - EQUIPMENT NOT INSTALLED // CHECKDATE 25 JUN 2018 // WO CEIS-11/18
25-JAN-2018		MOS HRS/MSC - AFL APH APS					
SL SL680-24-03	STARTER/GENERATOR GROUND INSPECTION, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT SERIAL NUMBER
07-APR-2008		MOS HRS/MSC A/R AFL		19-MAR-2013 2491:42 2781			
SL SL680-25-10	TRANSMITTAL OF ROCKWELL COLLINS AIRSHOW 4000 SERVICE BULLETIN 30, CORRECTION OF HARD DRIVE MOUNTING SCREWS - MOD U, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - SL680-25-10 "TRANSMITTAL OF ROCKWELL COLLINS AIRSHOW 4000 SERVICE BULLETIN 30" COMPLIED WITH. NOT APPLICABLE. A/C NOT EQUIPPED WITH.
22-MAR-2010		MOS HRS/MSC A/R (s) AFL		31-OCT-2012 2333:54 2601			
SL SL680-25-11	TRANSMITTAL OF AIRCRAFT BELTS INC. SB-BUC062-A001 INSPECTION OF BUCKLES FOR PROPER OPERATION, SERVICE LETTER					MANDATORY	COMPLIED WITH - C/W BY REVISION 1 ON 22-FEB-11 AT 1540.2 HOURS
06-AUG-2010		MOS HRS/MSC A/R AFL		(EFF)			
SL SL680-25-11 R01	TRANSMITTAL OF AIRCRAFT BELTS INC. SB-BUC062-A001 INSPECTION OF BUCKLES FOR PROPER OPERATION, SERVICE LETTER					MANDATORY	COMPLIED WITH - SL 680-25-11 R1 "TRANSMITTAL OF AIRCRAFT BELTS INSP. OF BUCKLES FOR PROPER OPERATION" COMPLIED WITH.
16-AUG-2010		MOS HRS/MSC A/R AFL		22-FEB-2011 1540:12 1735			
SL SL680-25-12	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 1423-25-003 REVISION C LUMBAR ASSEMBLY CABLE WEAR, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - SL 680-25-12 TRANSMITTAL GOODRICH SB 1423-25-003 REV. C LUMBAR ASSY CABLE WEAR COMPLIED WITH.
03-AUG-2012		MOS HRS/MSC - AFL		31-OCT-2012 2333:54 2601			
SL SL680-25-15	EQUIPMENT/FURNISHINGS - BAGGAGE COMPARTMENT FILLER BLOCK REPLACEMENT, SERVICE LETTER					OPTIONAL	
07-SEP-2017		MOS HRS/MSC - AFL					
SL SL680-25-15 R01	EQUIPMENT/FURNISHINGS - BAGGAGE COMPARTMENT FILLER BLOCK REPLACEMENT, SERVICE LETTER					OPTIONAL	
20-APR-2018		MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL680-25-17	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE SEAT PAN TILT SNAP RINGS (MILLENNIUM SERVICE BULLETIN SB2050-25-20-02B), SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - S/N AIRCRAFT NOT AFFECTED // CHECKDATE 20 JAN 2020 // WO CEIS-02/20
		MOS					
21-NOV-2019		HRS/MSC	-				
		AFL					
		APH					
		APS					
SL SL680-27-05	VERTICAL STABILIZER RUDDER HINGE CORROSION INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH - SL 680-27-05 "VERT. STAB RUDDER HINGE CORROSION INSP." COMPLIED WITH.
		MOS		22-FEB-2011			
06-JUL-2010		HRS/MSC	A/R	1540:12			
		AFL		1735			
SL SL680-27-06	SPEEDBRAKE CABLE INSTALLATION INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - SL 680-27-06 "SPEED BRAKE CABLE INST/INSPI." COMPLIED WITH.
		MOS		22-FEB-2011			
09-APR-2010		HRS/MSC	A/R (s)	1540:12			
		AFL		1735			
SL SL680-27-07 R01	CABLE FAIRLEAD REPLACEMENT, SERVICE LETTER					MANDATORY	NOT APPLICABLE
		MOS		23-MAY-2014			
03-MAR-2014		HRS/MSC	-				
		AFL					
SL SL680-27-14	FLIGHT CONTROLS - HORIZONTAL STABILIZER TRIM SYSTEM ADJUSTMENT SCREW REPLACEMENT, SERVICE LETTER			RECOMMENDED		NOT APPLICABLE - SN AIRCRAFT NOT AFFECTED // CHECKDATE 04 JAN 2024 // WO CEIS-03/24	
		MOS					
17-OCT-2023		HRS/MSC	-				
		AFL					
		APH					
		APS					
SL SL680-29-04	HYDRAULIC POWER - MISSING SEALS ON HYDRAULIC RESERVOIR SHROUD INSTALLATION, SERVICE LETTER					MANDATORY	COMPLIED WITH - REVISION 1 OF THIS SB
		MOS		06-JUL-2017			
01-JUN-2017		HRS/MSC	-	5005:48			
		AFL		4804			
		APH		2004			
		APS		5461			
SL SL680-29-04 R01	HYDRAULIC POWER - MISSING SEALS ON HYDRAULIC RESERVOIR SHROUD INSTALLATION, SERVICE LETTER					MANDATORY	COMPLIED WITH
		MOS		06-JUL-2017			
14-JUN-2017		HRS/MSC	-	5005:48			
		AFL		4804			
		APH		2004			
		APS		5461			
SL SL680-30-05	ICE AND RAIN PROTECTION - WING ANTI-ICE PRESSURE REGULATING SHUTOFF VALVE INSPECTION., SERVICE LETTER					MANDATORY	NOT APPLICABLE - N/A BY AIRCRAFT SERIAL NUMBER
		MOS		19-MAR-2013			
08-APR-2011		HRS/MSC	A/R	2491:42			
		AFL		2781			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL680-30-09	ICE AND RAIN PROTECTION - ADD SEALANT BETWEEN PICCOLO TUBES AND LANDING LIGHT BOX FASTENERS TO PREVENT CHAFING, SERVICE LETTER					DISCRETIONARY	COMPLIED WITH
		MOS		04-MAY-2020			
31-JAN-2020		HRS/MSC	-	6659:50			
		AFL		6099			
SL SL680-30-09 R01	ICE AND RAIN PROTECTION - ADD SEALANT BETWEEN PICCOLO TUBES AND LANDING LIGHT BOX FASTENERS TO PREVENT CHAFING, SERVICE LETTER					DISCRETIONARY	COMPLIED WITH - ORIGINAL REVISION OF THIS SB AT 04 MAY 2020 WITH 6659:50 HRS AND 6099 CYCLES. AIRPLANES PREVIOUSLY MODIFIED BY THIS SERVICE BULLETIN ARE NOT Affected BY THIS REVISION // CHECKDATE 22 JUN 2022 // WO CEIS-02/22
		MOS					
18-FEB-2022		HRS/MSC	-				
		AFL					
SL SL680-31-02	INDICATING/RECORDING SYSTEMS - TRANSMITTAL OF L-3 COMMUNICATIONS ALERT BULLETIN NO. CESSNA SB 001, SERVICE LETTER					MANDATORY	NOT APPLICABLE - SL 680-31-02 "CVR/FDR TRANSMITTAL L-3 COMM ASB CESSNA N° 1" COMPLIED WITH, NOT APPLICABLE BY S/N CVR AND FDR.
		MOS		02-DEC-2011			
04-AUG-2011		HRS/MSC	A/R	1941:36			
		AFL		2168			
SL SL680-32-07	TRANSMITTAL OF GOODRICH SERVICE LETTER SL2060, MAIN WHEEL ASSEMBLY INTRODUCTION OF AN IMPROVED OPTIONAL THERMAL RELIEF PLUG ASSEMBLY, SERVICE LETTER					OPTIONAL	COMPLIED WITH
		MOS		20-APR-2010			
19-FEB-2009		HRS/MSC	A/R	1134			
		AFL					
SL SL680-32-08	NOSE LANDING GEAR STRUT SEAL IMPROVEMENT, SERVICE LETTER					INFORMATIONAL	COMPLIED WITH - PERFORMED SL680-32-08 IAW SL INSTRUCTIONS SAT.
		MOS		16-MAY-2015			
11-DEC-2009		HRS/MSC	A/R	3444:24			
		AFL		3715			
SL SL680-32-09	TRANSMITTAL OF CURTISS WRIGHT SB 049801-32-01, LANDING GEAR CONTROL - ALTERNATE LED LIGHTING BULB, SERVICE LETTER					INFORMATIONAL	- INFORMATIONAL
		MOS					
04-AUG-2010		HRS/MSC	A/R				
		AFL					
SL SL680-32-10	NOSE WHEEL STEERING CABLE INSPECTION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
		MOS		20-MAY-2014			
14-NOV-2013		HRS/MSC	-	3026			
		AFL		3394			
SL SL680-32-12	LANDING GEAR - BRAKE ANTI SKID CONTROL VALVE WIRE BUNDLE INSPECTION AND PLUG SECURITY, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
		MOS		07-DEC-2016			
21-JUL-2016		HRS/MSC	-	4599:30			
		AFL		4511			
		APH		1864			
		APS		5129			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL680-32-14	LANDING GEAR - MAIN LANDING GEAR BRAKE VERIFICATION, SERVICE LETTER					MANDATORY	NOT APPLICABLE - SUSPECTED S/N NOT INSTALLED
17-FEB-2017		DAYs		21-FEB-2017			
		HRS/MSC	-	4747:54			
		AFL		4610			
SL SL680-32-15	LANDING GEAR - TRANSMIT GOODRICH SERVICE BULLETIN 2-1675-32-2 LANDING GEAR - MAIN BRAKE ASSEMBLY, - INTRODUCTION OF AN INSPECTION PROCEDURE TO MAKE SURE THE WEAR INDICATOR PINS WERE SET CORRECTLY, SERVICE LETTER					MANDATORY	COMPLIED WITH
21-JUL-2017		DAYs		10-AUG-2017			
		HRS/MSC	-	5117:47			
		AFL		4874			
		APH		2032			
		APS		5524			
SL SL680-32-16	LANDING GEAR - INSPECTION OF THE NOSE LANDING GEAR STRUT ASSEMBLY INTERNAL ORIFICE ASSEMBLY FOR CORRECT INSTALLATION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
02-JUL-2020		MOS		26-APR-2021			
		HRS/MSC	-	7171:58			
		AFL		6455			
SL SL680-32-16 R01	LANDING GEAR - INSPECTION OF THE NOSE LANDING GEAR STRUT ASSEMBLY INTERNAL ORIFICE ASSEMBLY FOR CORRECT INSTALLATION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - ORIGINAL REVISION OF THIS SL ON 26 APR 2021 AT 7171:58 HRS AND 6455 CYCLS - REV. 1 HAS NO AFFECT ON AIRPLANES PREVIOUSLY MODIFIED // CHECKDATE 24 JAN 2023 // WO CEIS-02/23
16-JAN-2023		MOS					
		HRS/MSC	-				
		AFL					
SL SL680-32-17	LANDING GEAR - PARKING BRAKE ASSEMBLY INSPECTION, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - SN AIRCRAFT NOT AFFECTED // CHECKDATE 06 AUG 2021 // WO CEIS-16/21
28-JUL-2021		MOS					
		HRS/MSC	-				
		AFL					
		APH					
		APS					
SL SL680-33-02	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 30-2900-33-0001, WING POSITION NAVIGATIONAL LIGHTS, SERVICE LETTER					DISCRETIONARY	COMPLIED WITH
03-OCT-2007		MOS		16-FEB-2009			
		HRS/MSC	A/R	560			
		AFL					
SL SL680-34-11	ANGLE-OF-ATTACK(AOA)/STALL WARNING COMPUTER SOFTWARE UPDATE, SERVICE LETTER					MANDATORY	COMPLIED WITH
02-DEC-2008		MOS		16-FEB-2009			
		HRS/MSC	-	560			
		AFL					
SL SL680-34-12	NAVIGATION - SERVICE INFORMATION FROM HONEYWELL, SERVICE LETTER					INFORMATIONAL	- INFORMATIONAL
06-JUN-2011		MOS					
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL680-34-12 R01	SERVICE INFORMATION FROM HONEYWELL, SERVICE LETTER					INFORMATIONAL	- SL INFORMATIONAL TOOK IN ACCOUNT.
23-JAN-2012		MOS					
		HRS/MSC	-				
		AFL					
SL SL680-34-13	NAVIGATION - TRANSMITTAL OF HONEYWELL SERVICE INFORMATION LETTER D20120500067, EQUIPMENT RESET UPON DATE/TIME INITIALIZATION ON CMA-4024-1 SPACED BASED AUGMENTATION SYSTEM, SERVICE LETTER					INFORMATIONAL	- SL INFORMATIONAL TOOK IN ACCOUNT.
13-JUN-2012		MOS					
		HRS/MSC	-				
		AFL					
SL SL680-35-01	TRANSMITTAL OF AVOX SYSTEMS SERVICE BULLETIN 36758-35-01, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - N/A BY AIRCRAFT SERIAL NUMBER
15-SEP-2009		MOS		19-MAR-2013			
		HRS/MSC	A/R	2491:42			
		AFL		2781			
SL SL680-35-02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240, SERVICE LETTER					MANDATORY	NOT APPLICABLE - SL 680-35-02 "OXYGEN SB INTERTECHNIQUE MXH-35-240 » COMPLIED WITH, NOT APPLICABLE BY P/N.
02-SEP-2011		MOS		02-DEC-2011			
		HRS/MSC	-	1941:36			
		AFL		2168			
SL SL680-35-02 R01	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240, SERVICE LETTER					MANDATORY	COMPLIED WITH - ORIGINAL ISSUE C/W ON 02-DEC-11 AT 1941.6 . AIRPLANES PREVIOUSLY MODIFIED BY THIS SERVICE LETTER ARE NOT AFFECTED BY THIS REVISION.
19-JAN-2012		MOS					
		HRS/MSC	-				
		AFL					
SL SL680-35-02 R02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240, SERVICE LETTER					MANDATORY	COMPLIED WITH - ORIGINAL ISSUE C/W ON 02-DEC-11 AT 1941.6 . AIRPLANES PREVIOUSLY MODIFIED BY THIS SERVICE LETTER ARE NOT AFFECTED BY THIS REVISION.
25-OCT-2012		MOS					
		HRS/MSC	-				
		AFL					
SL SL680-36-02	PYLON TEMPERATURE SENSOR O-RING INSPECTION, SERVICE LETTER					MANDATORY	NOT APPLICABLE - N/A BY AIRCRAFT SERIAL NUMBER
07-APR-2008		MOS		19-MAR-2013			
		HRS/MSC	A/R	2491:42			
		AFL		2781			
SL SL680-49-02	SLEEVE INSPECTION, SERVICE LETTER					MANDATORY	NOT APPLICABLE - N/A BY AIRCRAFT SERIAL NUMBER
08-MAY-2008		MOS		19-MAR-2013			
		HRS/MSC	A/R	2491:42			
		AFL		2781			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL680-49-03	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN RE100-49-7992 AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REMOVE AND REPLACE ELECTRONIC CONTROL UNIT, PN 2119552-2 OR PN 2119552-3, WITH ELECTRONIC CONTROL UNIT, PN 2119552-4, SERVICE LETTER					DISCRETIONARY	COMPLIED WITH - COMPLIED WITH CESSNA SL 680-49-03 ON APU RE100CS S/N: P353
08-APR-2011	MOS HRS/MSC A/R AFL			18-APR-2016 4097 4165			
SL SL680-49-04	APU FUEL LINE INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH - SL 680-49-04 "APU FUEL LINE INSPECTION" COMPLIED WITH.
28-MAR-2013	MOS HRS/MSC - AFL			23-JUN-2013 2634:30 2957			
SL SL680-49-04 R01	AUXILIARY POWER - APU FUEL LINE INSPECTION, SERVICE LETTER					MANDATORY	- COMPLIED WITH ORIGINAL VERSION OF THIS SB
07-AUG-2014	MOS HRS/MSC - AFL						
SL SL680-49-05	AUXILIARY POWER - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN RE100-49-8221 INSPECT AND REPLACE FUEL SHUTOFF VALVE (FSOV), PN 692545-18, ON RE100[CS] APUS, SERVICE LETTER					RECOMMENDED	
21-JUL-2016	MOS HRS/MSC - AFL						
SL SL680-49-08	AUXILIARY POWER - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN RE100-49-8250 AIRBORNE AUXILIARY POWER INFORMATIONAL - GAS TURBINE ENGINE - REPLACE LUBE MODULE, PN 3881825-1 WITH PN 3881825-2, FOR THE RE100[CS] AND RE100[XL] AUXILIARY POWER UNIT (APU), SERVICE LETTER						
08-MAY-2018	MOS HRS/MSC - AFL						
SL SL680-49-09	AUXILIARY POWER - INSPECTION OF THE AUXILIARY POWER UNIT (APU) INLET LEFT AND RIGHT FIRE SHIELD FILLET SEAL, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - S/N AIRCRAFT NOT AFFECTED // CHECKDATE 20 JAN 2020 // WO CEIS-02/20
03-JAN-2020	MOS HRS/MSC - AFL APH APS						
SL SL680-49-10	AUXILIARY POWER - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN RE100-49-8365 GAS TURBINE ENGINE - REPLACE WIRING HARNESS PN 3888487-2 WITH PN 3888487-3 ON THE RE100[CS] AUXILIARY POWER UNIT (APU), SERVICE LETTER					OPTIONAL	- DUE TIME TRACKED ON SB RE100-49-8365
10-APR-2023	MOS HRS/MSC - AFL						
SL SL680-52-05	MAIN CABIN DOOR INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH - SL 680-52-05 {MAIN CABIN DOOR INSPECTION} COMPLIED WITH.
	MOS HRS/MSC - AFL			28-AUG-2013 2714:42 3045			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL680-52-08	DOORS - INSPECTION OF THE NOSE LANDING GEAR (NLG) DOOR ACTUATION SYSTEM, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
13-JUN-2019	MOS HRS/MSC - AFL			19-OCT-2019 6451:01 5921			
SL SL680-52-09	DOORS - INSPECT AND TORQUE THE INNER EMERGENCY EXIT DOOR HANDLE BOLT AND NUT, SERVICE LETTER				21-NOV-2019 6509:10 5962	MANDATORY	COMPLIED WITH
18-NOV-2019	DAYS HRS/MSC - AFL						
SL SL680-53-03	TAILCONE MISSING FASTENER INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH
08-DEC-2008	MOS HRS/MSC A/R AFL			31-JUL-2009 786			
SL SL680-53-05 R02	FUSELAGE - AFT CANTED BULKHEAD INSPECTION, SERVICE LETTER					MANDATORY	NOT APPLICABLE - COMPLIED WITH CESSNA SB680-53-08 UNDER CESSNA DUS REV 20002482 ORDER 10396677 AND THEREFORE SL680-53-05 REV2 IS NOT LONGER APPLICABLE FOR 680-0185
	MOS HRS/MSC - AFL			18-APR-2016 4097 4165			
SL SL680-53-06	FUSELAGE - FUSELAGE RIVET INSTALLATION, SERVICE LETTER					RECOMMENDED	
03-MAY-2017	MOS HRS/MSC - AFL			(EFF)			
SL SL680-56-03	WINDOWS - OPENABLE COCKPIT WINDOW HINGE AND LATCH INSPECTION, SERVICE LETTER					MANDATORY	COMPLIED WITH - SL 680-56-03 "OPENABLE COCKPIT WINDOW HINGE AND LATCH INSPECTION" COMPLIED WITH.
07-DEC-2010	MOS HRS/MSC A/R AFL			22-FEB-2011 1540:12 1735			
SL SL680-71-05 R01	SLEEVE INSPECTION, SERVICE LETTER					MANDATORY	NOT APPLICABLE - N/A BY AIRCRAFT SERIAL NUMBER
19-MAR-2009	MOS HRS/MSC A/R AFL			19-MAR-2013 2491:42 2781			
SL SL680-71-06	TRANSMITTAL OF P&WC SERVICE BULLETIN 25353 - TURBOFAN ENGINE ALTERNATOR AND STARTER SEALS - REPLACEMENT OF, SERVICE LETTER					RECOMMENDED	COMPLIED WITH
15-DEC-2009	MOS HRS/MSC A/R AFL			04-MAR-2010 1077			
SL SL680-71-07	NO. 2 ENGINE PRATT & WHITNEY CANADA TURBOFAN ENGINE (P&WC SERVICE BULLETIN 72-25380 REV 1) REVISED TRIM VALUES FOR PW306C ELECTRONIC ENGINE CONTROL (EEC), SERVICE LETTER					MANDATORY	COMPLIED WITH - SL 680-71-07 / SB P&W 306C N° 72-25380 R1 "REVISED TRIM VALUES FOR PW306 EEC" COMPLIED WITH BOTH ENGINES.
27-JAN-2012	MOS HRS/MSC - AFL			13-AUG-2012 2254:30 2517			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL680-71-07	NO. 1 ENGINE PRATT & WHITNEY CANADA TURBOFAN ENGINE (P&WC SERVICE BULLETIN 72-25380 REV 1) REVISED TRIM VALUES FOR PW306C ELECTRONIC ENGINE CONTROL (EEC), SERVICE LETTER					MANDATORY	COMPLIED WITH - SL 680-71-07 / SB P&W 306C N° 72-25380 R1 "REVISED TRIM VALUES FOR PW306 EEC" COMPLIED WITH BOTH ENGINES.
27-JAN-2012		MOS HRS/MSC - AFL		13-AUG-2012 2254:30 2517			
SL SL680-71-10	POWER PLANT - TRANSMITTAL OF PRATT AND WHITNEY OF CANADA SERVICE INFORMATION LETTER PW300-219, SERVICE LETTER					INFORMATIONAL	
03-MAR-2025		MOS HRS/MSC - AFL					
SL SL680-73-01	ENGINE FUEL AND CONTROL - 6956100-85 FUEL TUBE ASSEMBLY REPLACEMENT, SERVICE LETTER					MANDATORY	NOT APPLICABLE - S/N AIRCRAFT NOT AFFECTED // CHECKDATE 06 AUG 2020 // WO CEIS-05/20
17-JUN-2020		MOS HRS/MSC AFL APH APS					
SL SL680-76-01	TURBOFAN ENGINE ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT REPLACEMENT/MODIFICATION OF, SERVICE LETTER					MANDATORY	COMPLIED WITH
03-DEC-2008		MOS HRS/MSC A/R AFL		04-MAR-2010 1077			
SL SL680-76-02	NO. 2 ENGINE TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW300-72-25412, TURBOFAN ENGINE ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTICS UNIT - REPLACEMENT/MODIFICATION, SERVICE LETTER					INFORMATIONAL	
12-MAR-2015		MOS HRS/MSC - AFL					
SL SL680-76-02	NO. 1 ENGINE TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW300-72-25412, TURBOFAN ENGINE ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTICS UNIT - REPLACEMENT/MODIFICATION, SERVICE LETTER					INFORMATIONAL	
12-MAR-2015		MOS HRS/MSC - AFL					
SL SL680-78-05 R01	TRANSMITTAL OF NORDAM SERVICE BULLETIN CIT SV 78-04 REVISION 1, THRUST REVERSER - ADD SAFETY WIRE TO LATCH HOOK BOLTS, SERVICE LETTER					MANDATORY	NOT APPLICABLE - N/A BY AIRCRAFT SERIAL NUMBER
28-MAY-2008		MOS HRS/MSC A/R AFL		19-MAR-2013 2491:42 2781			
SL SL680-99-02 R01	TRANSMITTAL OF CESSNA'S CERTIFICATION REQUIREMENTS FOR PORTABLE ELECTRONIC DEVICE USAGE, SERVICE LETTER					INFORMATIONAL	
23-AUG-2013		MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL SL680-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS, SERVICE LETTER					INFORMATIONAL	- SL TOOK IN ACCOUNT.
11-NOV-2011	MOS HRS/MSC A/R AFL						
SL SL680-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION, SERVICE LETTER					INFORMATIONAL	- SL TOOK IN ACCOUNT.
22-NOV-2011	MOS HRS/MSC A/R AFL						
SPI 000001	PROPARTS AND PROTECH+ ADDENDUM CONTRACT TERMINATION, SPECIAL INSTRUCTION					INFORMATIONAL	
	MOS 36 HRS/MSC 1800 AFL			15-DEC-2024 9226:53	15-DEC-2027 11026:53	RECURRING	

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
APU - SB - P-353/3800785-1							
SB 3615880-49-8149 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN 3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS, SERVICE BULLETIN					RECOMMENDED	
20-OCT-2015		MOS HRS/MSC - AFL		(EFF)			
SB 3615880-49-8149 R02	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN 3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS, SERVICE BULLETIN					RECOMMENDED	
25-OCT-2016		MOS HRS/MSC - APUS					
SB 3822101-49-8148 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, PN 3822101-1, ON MULTIPLE APUS, SERVICE BULLETIN					RECOMMENDED	
20-OCT-2015		MOS HRS/MSC - APUS		(EFF)			
SB 3822101-49-8148 R02	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, PN 3822101-1, ON MULTIPLE APUS, SERVICE BULLETIN					RECOMMENDED	
10-JAN-2017		MOS HRS/MSC - APUS					
SB 3883900-49-7976 R02	APU - AIRBORNE AUXILIARY POWER - MAIN FUEL CONTROL UNIT (FCU) - CHECK NAMEPLATE FOR LATEST CHANGE NUMBER. INSTALL FUEL FLOW DEFLECTOR, PN 70720001-1, ON THE FUEL CONTROL DIFFERENTIAL PRESSURE (DELTA P) SLEEVE AS REQUIRED AT NEXT AUXILIARY POWER UNIT (APU) SHOP VISIT, SERVICE BULLETIN					RECOMMENDED	
11-MAY-2019		MOS HRS/MSC - APUS	ESV 12000		12000		
SB 3883900-49-8297	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE OIL SEAL, PN 3883905-1, WITH PN 70722907-1 ON THE FUEL CONTROL UNIT (FCU), PN 3883900-1 FOR THE RE100 APU, SERVICE BULLETIN					RECOMMENDED	
24-FEB-2020		MOS HRS/MSC - APUS					
SB 49-7933 R03	APU - AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS, SERVICE BULLETIN					RECOMMENDED	- TOOK IN ACCOUNT.
31-OCT-2011		MOS HRS/MSC - APUS					
SB 49-7933 R04	APU - AIRBORNE AUXILIARY POWER UNIT (APU) OIL - GENERAL - APPROVED OILS, SERVICE BULLETIN					RECOMMENDED	
12-AUG-2014		MOS HRS/MSC - APUS					
SB 49-7933 R05	APU - AIRBORNE AUXILIARY POWER UNIT (APU) OIL - GENERAL - APPROVED OILS, SERVICE BULLETIN					RECOMMENDED	
23-OCT-2014		MOS HRS/MSC - APUS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 49-7933 R06	APU - AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS (SUPERSEDED BY 49-7933 R7), SERVICE BULLETIN					RECOMMENDED	
26-JAN-2016		MOS HRS/MSC - APUS					
SB 49-7933 R07	APU - AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS (SUPERSEDED BY 49-7933 R08), SERVICE BULLETIN					RECOMMENDED	
09-FEB-2017		MOS HRS/MSC - APUS					
SB 49-7933 R08	APU - AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS, SERVICE BULLETIN					RECOMMENDED	
27-JUL-2017		MOS HRS/MSC - APUS					
SB 49-7997 R02	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES, SERVICE BULLETIN					INFORMATIONAL	- CONCERN CUSTOMERS HAVE REQUESTED STANDARDIZED LONG-TERM PRESERVATION AND STORAGE PROCEDURES FOR HONEYWELL APU'S.
22-DEC-2010		MOS HRS/MSC - APUS					
SB 49-7997 R03	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES, SERVICE BULLETIN					INFORMATIONAL	
		MOS HRS/MSC - APUS					
SB 49-7997 R04	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES, SERVICE BULLETIN					INFORMATIONAL	
12-JAN-2015		MOS HRS/MSC - APUS					
SB 49-7997 R05	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES, SERVICE BULLETIN					INFORMATIONAL	
03-FEB-2017		MOS HRS/MSC - APUS					
SB 70721598-49-8168 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS, SERVICE BULLETIN					RECOMMENDED	
20-OCT-2015		MOS HRS/MSC - APUS					
SB 70721598-49-8168 R02	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS, SERVICE BULLETIN					RECOMMENDED	
10-JAN-2017		MOS HRS/MSC - APUS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 70721725-49-8152 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS, SERVICE BULLETIN					RECOMMENDED	
24-AUG-2015		MOS					
		HRS/MSC	-				
		APUS					
SB 70721725-49-8152 R02	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS, SERVICE BULLETIN					RECOMMENDED	
25-OCT-2016		MOS					
		HRS/MSC	-				
		APUS					
SB RE100-49-7992	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REMOVE AND REPLACE ELECTRONIC CONTROL UNIT, PN 2119552-2 OR PN 2119552-3, WITH ELECTRONIC CONTROL UNIT, PN 2119552-4, SERVICE BULLETIN				18-APR-2016	OPTIONAL	NOT APPLICABLE - REPLACED BY HONEYWELL SB 49-7992 REV1
02-JUL-2010		MOS					
		HRS/MSC	-		1675		
		APUS			4721		
SB RE100-49-7992 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REMOVE AND REPLACE ELECTRONIC CONTROL UNIT, PN 2119552-2 OR PN 2119552-3, WITH ELECTRONIC CONTROL UNIT, PN 2119552-4, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - COMPLIED WITH HONEYWELL SB49-7992 REV1 ON APU RE100CS S/N: P353
16-MAR-2011		MOS			18-APR-2016		
		HRS/MSC	-		1675		
		APUS			4721		
SB RE100-49-7994	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE EINGE - REMOVE AND REPLACE ELECTRONIC CONTROL UNIT, PN 2119552-3, WITH ELECTRONIC CONTROL UNIT, PN 2119552-4, SERVICE BULLETIN					OPTIONAL	- SB IS RELATED TO INSTALLATION IN GULFSTREAM G150
02-JUL-2010		MOS					
		HRS/MSC	-				
		APUS					
SB RE100-49-8139	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - INCREASE THE INSTALLATION TORQUE AND ADD THE USE OF LOCKING COMPOUND DURING CARBON SEAL ASSEMBLY ON THE RE100 APU, SERVICE BULLETIN					RECOMMENDED	
15-AUG-2014		MOS					
		HRS/MSC	-				
		APUS					
SB RE100-49-8221	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - INSPECT AND REPLACE FUEL SHUTOFF VALVE (FSOV), PN 692545-18, ON RE100[CS] APUS, SERVICE BULLETIN					RECOMMENDED	
20-APR-2016		MOS					
		HRS/MSC	-				
		APUS					
SB RE100-49-8250	APU - GAS TURBINE ENGINE - REPLACE LUBE MODULE PN 3881825-1 WITH PN 3881825-2 FOR THE RE100[CS] AND RE100[XL] AUXILIARY POWER UNIT (APU) , SERVICE BULLETIN					ATTRITION	
11-SEP-2017		MOS					
		HRS/MSC	-				
		APUS					
SB RE100-49-8250 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE LUBE MODULE, PN 3881825-1 WITH PN 3881825-2, FOR THE RE100[CS] AND RE100[XL] AUXILIARY POWER UNIT (APU), SERVICE BULLETIN					ATTRITION	
15-JUN-2018		MOS					
		HRS/MSC	-				
		APUS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB RE100-49-8250 R02	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE LUBE MODULE, PN 3881825-1 WITH PN 3881825-2, FOR THE RE100[CS] AND RE100[XL] AUXILIARY POWER UNIT (APU), SERVICE BULLETIN					ATTRITION	
		MOS					
30-OCT-2020		HRS/MSC	-				
		APUS					
SB RE100-49-8303	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REWORK AND REPAIR OF ENGINE FOR INCORPORATION OF IMPROVED COMPRESSOR CARBON SEAL AND RELATED COMPONENTS ON THE RE100 AUXILIARY POWER UNIT (APU), SERVICE BULLETIN					OPTIONAL	
		MOS					
24-FEB-2020		HRS/MSC	-				
		APUS					
SB RE100-49-8303 R03	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REWORK AND REPAIR OF ENGINE FOR INCORPORATION OF IMPROVED COMPRESSOR CARBON SEAL AND RELATED COMPONENTS ON THE RE100 AUXILIARY POWER UNIT (APU), SERVICE BULLETIN					OPTIONAL	
		MOS					
01-SEP-2020		HRS/MSC	-				
		APUS					
SB RE100-49-8303 R04	APU - GAS TURBINE ENGINE - REWORK AND REPAIR OF ENGINE FOR INCORPORATION OF IMPROVED COMPRESSOR CARBON SEAL AND RELATED COMPONENTS ON THE RE100 AUXILIARY POWER UNIT (APU), SERVICE BULLETIN					OPTIONAL	
		MOS					
18-MAY-2022		HRS/MSC	-				
		APUS			12000 M		
SB RE100-49-8360	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE RIVET PN M24243/6A401H WITH PN 627-504-9209 ON ENGINES RE100[CS], RE100[LJ], AND RE100[XL] MODELS, SERVICE BULLETIN					RECOMMENDED	
		MOS					
17-DEC-2021		HRS/MSC	-				
		APUS					
SB RE100-49-8360 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE RIVET PN M24243/6A401H WITH PN 627-504-9209 ON ENGINES RE100[CS], RE100[LJ], AND RE100[XL] MODELS, SERVICE BULLETIN					CATEGORY 2	
		MOS					
23-FEB-2022		HRS/MSC	-				
		APUS					
SB RE100-49-8360 R02	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE RIVET PN M24243/6A401H WITH PN 627-504-9209 ON RE100 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	COMPLIED WITH
		MOS		19-APR-2023			
29-MAR-2022		HRS/MSC	-	3127			
		APUS		8081			
SB RE100-49-8363 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE INLET HOUSING PN 3810880-1/-2 WITH PN 70724596-1 OR PN 70724596-2, GEARBOX HOUSING PN 3863409-6 WITH PN 70724597-1, GEARBOX HOUSING PN 3863409-5 WITH PN 70724597-2 AND GEARBOX HOUSING PN 3863409-4 WITH PN 70724597-3 ON THE RE100 AUXILIARY POWER UNIT (APU), SERVICE BULLETIN					OPTIONAL	
		MOS					
04-AUG-2022		HRS/MSC	-				
		APUS					
SB RE100-49-8365	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE WIRING HARNESS PN 3888487-2 WITH PN 3888487-3 ON THE RE100[CS] AUXILIARY POWER UNIT (APU), SERVICE BULLETIN						
		MOS					
28-JUL-2022		HRS/MSC	-				
		APUS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB RE100-49-8365 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE WIRING HARNESS PN 3888487-2 WITH PN 3888487-3 ON THE RE100[CS] AUXILIARY POWER UNIT (APU), SERVICE BULLETIN					CATEGORY 3	
30-MAR-2023	MOS HRS/MSC - APUS				12000 M		
SIL APU-49 R10	APU - IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS), SERVICE INFORMATION LETTER					RECOMMENDED	COMPLIED WITH
12-JAN-2018	MOS HRS/MSC - APUS			27-AUG-2020 2695:06 7043			
SIL APU-49 R11	APU - IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS), SERVICE INFORMATION LETTER					RECOMMENDED	
21-FEB-2022	MOS HRS/MSC - APUS						
SIL APU-49 R12	APU - IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS), SERVICE INFORMATION LETTER					RECOMMENDED	
02-JUN-2022	MOS HRS/MSC - APUS						
SIL APU-49 R13	APU - IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS), SERVICE INFORMATION LETTER					RECOMMENDED	
23-NOV-2023	MOS HRS/MSC - APUS						
SIL APU-49 R14	APU - IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS), SERVICE INFORMATION LETTER					RECOMMENDED	
12-FEB-2025	MOS HRS/MSC A/R APUS						
SIL D201112000050 R03	APU - ACCEPTANCE CRITERIA FOR ON-WING BORESCOPE INSPECTIONS, SERVICE INFORMATION LETTER					INFORMATIONAL	
11-MAR-2025	MOS HRS/MSC - APUS						
SPI 000004	APU - AUXADVANTAGE CONTRACT TERMINATION, SPECIAL INSTRUCTION					INFORMATIONAL	
	MOS 36 HRS/MSC 1800 APUS			15-DEC-2024 3570	15-DEC-2027 5370	RECURRING	

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - SB - PCE-CG0375/30B4258-01							
ASB R01	PW300-72-A25358 NO. 1 ENGINE - INSPECTION /REPLACEMENT OF ALTERNATOR AND STARTER MAGNETIC SEAL ASSEMBLIES, ALERT SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO POST SB25353
		MOS		21-FEB-2019			
		HRS/MSC	-	5955:36			
		APUS					
		ENC		5506			
SB	PW100-72-25428 NO. 1 ENGINE - INTRODUCTION OF SELF-LOCKING NUT (IC) OPTION, SERVICE BULLETIN					CATEGORY 9	
		MOS					
		HRS/MSC	-				
		ENC					
SB	PW300-72-25167 R02 NO. 1 ENGINE - HYDROMECHANICAL FUEL CONTROL - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ESN
		MOS		21-FEB-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB	PW300-72-25175 NO. 1 ENGINE - FIRST STAGE HIGH PRESSURE TURBINE (HPT) BLADES - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ESN
		MOS		21-FEB-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB	PW300-72-25177 R03 NO. 1 ENGINE - SECOND STAGE HIGH PRESSURE COMPRESSOR ROTOR - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ESN
		MOS		21-FEB-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB	PW300-72-25178 NO. 1 ENGINE - ATTACHMENT BOLTS FOR HIGH PRESSURE COMPRESSOR (HPC) REAR CASE - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ESN
		MOS		21-FEB-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB	PW300-72-25179 NO. 1 ENGINE - PREFORMED PACKINGS FOR THE N1 SPEED SENSORS OR PACKING COVERS - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ESN
		MOS		21-FEB-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB	PW300-72-25181 NO. 1 ENGINE - NO. 1 BEARING CARBON SEAL RUNNER - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 4	NOT APPLICABLE - DUE TO ESN
		MOS		21-FEB-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB	PW300-72-25182 NO. 1 ENGINE - P3 TRANSDUCER TUBE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ESN
		MOS		21-FEB-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB	PW300-72-25183 NO. 1 ENGINE - FIRE SENSOR CORE WIRING HARNESS - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ESN
		MOS		21-FEB-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25184	NO. 1 ENGINE - OUTER ELECTRICAL WIRING HARNESS - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 4	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
14-APR-2003		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25187	NO. 1 ENGINE - ACCESSORY GEARBOX (AGB) MAGNETIC FACE SEAL ASSEMBLY - REPLACEMENT/INTRODUCTION OF, SERVICE BULLETIN				CATEGORY 3		NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
15-DEC-2004		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25188	NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL (EEC) - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 6		NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
15-APR-2003		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25189	NO. 1 ENGINE - MODIFICATION OF MAIN DATA PLATE, SERVICE BULLETIN				CATEGORY 3		NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25190	NO. 1 ENGINE - INLET GUIDE VANE SHROUD SET - REPLACEMENT/MODIFICATION OF NO. 2 BEARING RETAINER - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 6		NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
07-APR-2003		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25195	NO. 1 ENGINE - REAR LOWER DUCT HALF ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN				CATEGORY 5		NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
16-MAY-2003		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25196 R03	NO. 1 ENGINE - REPLACEMENT OF FIRST STAGE HIGH PRESSURE TURBINE (HPT) BLADES, SERVICE BULLETIN				CATEGORY 3		NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
25-FEB-2004		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25198	NO. 1 ENGINE - OIL FILLER VENT TUBE BRACKET - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 3		NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
10-DEC-2004		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25201 R01	NO. 1 ENGINE - REPLACEMENT PREFORMED PACKING FOR COMBUSTION CHAMBER CASE DRAIN VALVE ADAPTER, SERVICE BULLETIN				CATEGORY 6		NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25202	NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL (EEC) AND ENGINE DIAGNOSTIC UNIT (EDU) - REPROGRAMMING/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
05-SEP-2003		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25211 R02	NO. 1 ENGINE - REPLACEMENT OF HIGH PRESSURE TURBINE AIR NOZZLE SUPPORT AND VANE ASSEMBLIES, SERVICE BULLETIN				CATEGORY 7	NOT APPLICABLE - N/A BY ENGINE SERIAL NUMBER	
27-AUG-2008		MOS HRS/MSC - ENC		19-MAR-2013 2491:42 2781			
SB PW300-72-25213	NO. 1 ENGINE - REDEFINED OIL FILLER NECK ASSEMBLY - INTRODUCTION OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER	
28-NOV-2003		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25215	NO. 1 ENGINE - FIRST STAGE HIGH PRESSURE TURBINE (HPT) BLADE AIR SEALS - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER	
28-JAN-2004		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25216 R01	NO. 1 ENGINE - OUTER COMBUSTION CHAMBER LINER ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER	
24-AUG-2005		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25218	NO. 1 ENGINE - NO.2 BEARING - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER	
27-FEB-2004		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25221	NO. 1 ENGINE - REDEFINED OIL FILLER NECK ASSEMBLY - REPLACEMENT/INTRODUCTION OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER	
29-MAR-2004		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25222	NO. 1 ENGINE - MOTIVE FLOW VALVE - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER	
19-FEB-2004		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25224 R01	NO. 1 ENGINE - FUEL NOZZLE - INSPECTION/REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER	
11-FEB-2005		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25225	NO. 1 ENGINE - ENVIRONMENTAL CONTROL SYSTEM (ECS) FAIRING BOLTS - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER	
27-FEB-2004		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25229 R04	NO. 1 ENGINE - HPT DISK BALANCING ASSEMBLY AND VANE ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER	
27-JUL-2007		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25229 R05	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF HPT DISK BALANCING ASSEMBLY AND VANE ASSEMBLY, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - N/A BY ENGINE S/N // CHECKDATE 12 NOV 2020 // WO CEIS-08/20	
04-NOV-2020		MOS HRS/MSC - ENC AFL					
SB PW300-72-25230 R03	NO. 1 ENGINE - TURBOFAN ENGINE - REPLACEMENT OF HPT DISK BALANCING ASSEMBLY, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER	
27-JUL-2007		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25233	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) FRONT COVER - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER	
30-APR-2004		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25234 R04	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) VANE ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER	
26-JUL-2011		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25235	NO. 1 ENGINE - FUEL MANIFOLD DRAIN ADAPTER BOLTS - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER	
		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25239	NO. 1 ENGINE - P0 TOTAL AIR PRESSURE TUBE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 3	NOT APPLICABLE - DUE TO ENGINE S/N	
31-AUG-2004		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25240	NO. 1 ENGINE - T4.5 TRIM ADJUSTMENT, SERVICE BULLETIN				CATEGORY 3	NOT APPLICABLE - DUE TO ENGINE S/N	
03-NOV-2004		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25247 R01	NO. 1 ENGINE - ENGINE DIAGNOSTIC UNIT (EDU) - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE S/N	
15-AUG-2005		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25249 R01	NO. 1 ENGINE - FUEL NOZZLES - MODIFICATION /REPLACEMENT OF (SUPERSEDED BY PW300-72-25249 R02), SERVICE BULLETIN				CATEGORY 5	COMPLIED WITH	
27-MAY-2005		MOS HRS/MSC - ENC		15-MAY-2014 3026 3394			
SB PW300-72-25249 R02	NO. 1 ENGINE - MODIFICATION /REPLACEMENT OF FUEL NOZZLES, SERVICE BULLETIN				CATEGORY 5	COMPLIED WITH - R1 OF THIS SB	
18-NOV-2014		MOS HRS/MSC - ENC					
SB PW300-72-25254 R01	NO. 1 ENGINE - HONEYCOMB SEAL RUNNER RETAINING RING - INSPECTION/CRIMPING OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE S/N	
27-JUL-2007		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25255 R03	NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN				CATEGORY 3	NOT APPLICABLE - DUE TO ENGINE S/N	
		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25256	NO. 1 ENGINE - T4.5 TRIM ADJUSTMENT, SERVICE BULLETIN				CATEGORY 3	NOT APPLICABLE - DUE TO ENGINE S/N	
12-MAY-2005		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25258 R02	NO. 1 ENGINE - OIL FILTER IMPENDING BYPASS SWITCH - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 7	NOT APPLICABLE - BY ENGINE SERIAL NUMBER - FACTORY EMBODIED	
21-MAR-2011		MOS HRS/MSC A/R ENC					
SB PW300-72-25262	NO. 1 ENGINE - T4.5 TRIM ADJUSTMENT, SERVICE BULLETIN				CATEGORY 3	NOT APPLICABLE - DUE TO ENGINE S/N	
02-JUN-2005		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25263	NO. 1 ENGINE - LOW COMPRESSOR SHAFT ASSEMBLY - INSPECTION/REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 3	NOT APPLICABLE - DUE TO ENGINE S/N	
15-AUG-2005		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25264 R01	NO. 1 ENGINE - IMPENDING FUEL FILTER BYPASS SWITCH - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 7	NOT APPLICABLE - BY ENGINE SERIAL NUMBER - FACTORY EMBODIED	
23-MAR-2011		MOS HRS/MSC A/R ENC					
SB PW300-72-25265 R01	NO. 1 ENGINE - WORKSCOPE FOR LOW UTILIZATION INSPECTION, SERVICE BULLETIN				CATEGORY 10		
09-MAR-2018		MOS HRS/MSC - ENC AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25267	NO. 1 ENGINE - TAB LOCKWASHERS - INTRODUCTION OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE S/N
16-DEC-2005		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25268 R01	NO. 1 ENGINE - ENGINE DIAGNOSTIC UNIT - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - PREVIOUSLY
		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25270 R01	NO. 1 ENGINE - INTRODUCTION OF NEW ENGINE ASSEMBLY PROCEDURES AND HARDWARE, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY ENGINE S/N // CHECKDATE 04 APR 2019 // WO CEIS-05/19 REV. 01
21-SEP-2014		MOS HRS/MSC - ENC					
SB PW300-72-25270 R02	NO. 1 ENGINE - INTRODUCTION OF NEW ENGINE ASSEMBLY PROCEDURES AND HARDWARE, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY ENGINE S/N // CHECKDATE 04 APR 2019 // WO CEIS-05/19 REV. 01
19-OCT-2018		MOS HRS/MSC - ENC AFL					
SB PW300-72-25273 R03	NO. 1 ENGINE - REPLACEMENT OF NO. 4 BEARING CARBON SEAL AND CARRIER(SUPERSEDED BY PW300-72-25273 R04), SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE S/N
27-OCT-2008		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25273 R04	NO. 1 ENGINE - REPLACEMENT OF NO. 4 BEARING CARBON SEAL AND CARRIER, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - BY ENGINE SERIAL NUMBER - FACTORY EMBODIED
26-AUG-2010		MOS HRS/MSC A/R ENC					
SB PW300-72-25274 R01	NO. 1 ENGINE - REPLACEMENT OF UPPER AND LOWER BYPASS DUCT ASSEMBLIES, FUEL NOZZLE COVER AND EXCITER MOUNTING BRACKET, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - N/A BY ENGINE SERIAL NUMBER
15-SEP-2008		MOS HRS/MSC - ENC		19-MAR-2013 2491:42 2781			
SB PW300-72-25274 R02	NO. 1 ENGINE - REPLACEMENT OF UPPER AND LOWER BYPASS DUCT ASSEMBLIES, FUEL NOZZLE COVER AND EXCITER MOUNTING BRACKET, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - SN ENGINE NOT Affected // CHECKDATE 04 JAN 2024 // WO CEIS-03/24
08-NOV-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25275	NO. 1 ENGINE - T4.5 TRIM ADJUSTMENT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO ENGINE S/N
17-NOV-2005		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25276 R01	NO. 1 ENGINE - INSPECTION OF PREFORMED PACKING ON FUEL AND OIL FILTERS, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO ENGINE S/N
23-DEC-2005		MOS		21-FEB-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25277	NO. 1 ENGINE - NO.1 BEARING SELA RUNNER - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ESN
		MOS		21-FEB-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25280 R01	NO. 1 ENGINE - INSPECTION OF HIGH PRESSURE TURBINE RETAINING NUT, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH
26-FEB-2008		MOS		21-FEB-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25281 R02	NO. 1 ENGINE - INSPECTION/ASSEMBLY OF OIL FILLER NECK ASSEMBLY, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO ENGINE S/N
16-MAR-2012		MOS		21-FEB-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25283 R02	NO. 1 ENGINE - REPLACEMENT OF CORE COWL SUPPORT BRACKETS, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE - DUE TO ENGINE S/N
17-JAN-2007		MOS		21-FEB-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25284 R03	NO. 1 ENGINE - REPLACEMENT OF MAGNETIC SEAL ASSEMBLIES, SERVICE BULLETIN					CATEGORY 7	
12-FEB-2016		MOS					
		HRS/MSC	-				
		ENC					
SB PW300-72-25292	NO. 1 ENGINE - T4.5 TRIM ADJUSTMENT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO ENGINE S/N
		MOS		21-FEB-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25296	NO. 1 ENGINE - REPLACEMENT OF OIL VENT TUBE RETAINING BOLT, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE S/N
22-SEP-2006		MOS		21-FEB-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25304	NO. 1 ENGINE - INTRODUCTION OF NEW OIL TANK VENT TUBE GASKET, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE S/N
22-JAN-2007		MOS		21-FEB-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25305	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR ROTOR BALANCING ASSEMBLY FLANGE BOLTS, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE S/N
19-JAN-2007		MOS		21-FEB-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25306	NO. 1 ENGINE - REPLACEMENT OF HIGH PRESSURE COMPRESSOR (HPC) TIE SHAFT RETAINING NUT, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE S/N
17-AUG-2007		MOS		21-FEB-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25307	NO. 1 ENGINE - T4.5 TRIM ADJUSTMENT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO ENGINE S/N
12-DEC-2006		MOS HRS/MSC ENC	BF/F	21-FEB-2019 5955:36 5506			
SB PW300-72-25309 R03	NO. 1 ENGINE - REPLACEMENT OF PRIMARY FUEL NOZZLE (SUPERSEDED BY PW300-72-25309 R04), SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - BY ENGINE SERIAL NUMBER - FACTORY EMBODIED
05-MAY-2010		MOS HRS/MSC ENC	A/R				
SB PW300-72-25309 R04	NO. 1 ENGINE - REPLACEMENT OF PRIMARY FUEL NOZZLE, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE S/N
23-JAN-2018		MOS HRS/MSC ENC	-	21-FEB-2019 5955:36 5506			
SB PW300-72-25311 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF PRIMARY FUEL NOZZLE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - ENGINE S/N // CHECKDATE 25 JUN 2018 // WO CEIS-11/18
15-JUN-2018		MOS HRS/MSC ENC AFL	-				
SB PW300-72-25312 R01	NO. 1 ENGINE - CONVERSION OF PW306A BUILD SPECIFICATION 853 TO 1241 OR CONVERSION OF PW306C BUILD SPECIFICATION 1026 TO 1240 (PROGRESSIVE MAINTENANCE PROGRAM) (SUPERSEDED BY PW300-72-25312 R02), SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE - N/A BY EFFECTIVITY
30-SEP-2009		MOS HRS/MSC ENC	-	19-MAR-2013 2491:42 2781			
SB PW300-72-25312 R02	NO. 1 ENGINE - CONVERSION OF PW306A BUILD SPECIFICATION 853 TO 1241 OR CONVERSION OF PW306C BUILD SPECIFICATION 1026 TO 1240 (PROGRESSIVE MAINTENANCE PROGRAM), SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE - REFER TO R1 OF THIS SB
23-MAR-2015		MOS HRS/MSC ENC	-				
SB PW300-72-25312 R03	NO. 1 ENGINE - CONVERSION OF PW306A BUILD SPECIFICATION 853 TO 1241 OR CONVERSION OF PW306C BUILD SPECIFICATION 1026 TO 1240 (PROGRESSIVE MAINTENANCE PROGRAM), SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE - N/A SB IS ONLY FOR ENGINES OPERATED BY NETJETS AVIATION INC // CHECKDATE 27 APR 2021 // WO CEIS-07/21
18-FEB-2021		MOS HRS/MSC ENC AFL	-				
SB PW300-72-25312 R03 PART A	NO. 1 ENGINE - ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF IDENTIFICATION PLATE (A NEW ENGINE BUILD SPECIFICATION (BS1241) FOR THE PW306A AND BUILD SPECIFICATION (BS1240) FOR THE PW306C, ARE INTRODUCED TO DISTINGUISH ENGINES ELIGIBLE FOR ENROLLMENT INTO THE NETJETS PROGRESSIVE MAINTENANCE PROGRAM)					CATEGORY 8	NOT APPLICABLE - N/A SB IS ONLY FOR ENGINES OPERATED BY NETJETS AVIATION INC // CHECKDATE 27 APR 2021 // WO CEIS-07/21
18-FEB-2021		MOS HRS/MSC ENC AFL	-				

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25312 R03 PART B	NO. 1 ENGINE - ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF IDENTIFICATION PLATE (FOR ENGINES THAT ARE NO LONGER INCLUDED WITHIN THE NETJETS PROGRESSIVE MAINTENANCE PROGRAM, THE POST-SB25312 REFERENCE DATA PLATE WITH ENGINE BUILD SPECIFICATION (BS1241 FOR THE PW306A OR BS1240 FOR THE PW306C) IS REMOVED AND REPLACED WITH A NEW DATA PLATE REFERENCING THE ORIGINAL ENGINE BUILD SPECIFICATION (BS853 FOR THE PW306A OR BS1026 FOR THE PW306C))					CATEGORY 8	NOT APPLICABLE - N/A SB IS ONLY FOR ENGINES OPERATED BY NETJETS AVIATION INC // CHECKDATE 27 APR 2021 // WO CEIS-07/21
18-FEB-2021	MOS HRS/MSC - ENC AFL						
SB PW300-72-25313	NO. 1 ENGINE - T4.5 TRIM ADJUSTMENT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO ENGINE S/N
29-MAR-2007	MOS HRS/MSC - ENC			21-FEB-2019 5955:36 5506			
SB PW300-72-25317	NO. 1 ENGINE - REPLACEMENT OF TAIL FAIRING BOLTS, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE S/N
04-JUN-2007	MOS HRS/MSC - ENC			21-FEB-2019 5955:36 5506			
SB PW300-72-25318 R01	NO. 1 ENGINE - INTRODUCTION OF NEW FUEL/OIL HEAT EXCHANGER (FOHE), SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE - DUE TO ENGINE S/N
18-AUG-2008	MOS HRS/MSC - ENC			21-FEB-2019 5955:36 5506			
SB PW300-72-25320	NO. 1 ENGINE - MODIFICATION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL UNIT (HMU), SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - PREVIOUSLY
10-OCT-2007	MOS HRS/MSC - ENC			21-FEB-2019 5955:36 5506			
SB PW300-72-25321 R02	NO. 1 ENGINE - MODIFICATION/REPLACEMENT OF ALTERNATOR SPUR GEARSHAFT ASYO, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - PREVIOUSLY
30-OCT-2009	MOS HRS/MSC A/R ENC			21-FEB-2019 5955:36 5506			
SB PW300-72-25323	NO. 1 ENGINE - HIGH PRESSURE TURBINE SHROUD AIR SEAL - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
23-OCT-2007	MOS HRS/MSC - ENC			21-FEB-2019 5955:36 5506			
SB PW300-72-25325 R02	NO. 1 ENGINE - REPLACEMENT OF HIGH-PRESSURE COMPRESSOR-CASE BOLTS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
19-FEB-2008	MOS HRS/MSC - ENC						
SB PW300-72-25326 R01	NO. 1 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
31-MAR-2011	MOS HRS/MSC A/R ENC						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25327 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX GEARSHAFTS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
14-JAN-2008	MOS HRS/MSC - ENC						
SB PW300-72-25328 R01	NO. 1 ENGINE - INTRODUCTION / REPLACEMENT OF CARBON FACE SEALS, SERVICE BULLETIN					NOT APPLICABLE - NOT CONCERNED	
05-MAY-2008	MOS HRS/MSC - ENC			19-MAR-2013 2491:42 2781			
SB PW300-72-25331 R01	NO. 1 ENGINE - REPLACEMENT OF FAN HUB SET, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
04-DEC-2012	MOS HRS/MSC - ENC						
SB PW300-72-25332	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF FUEL START AND DUMP VALVE, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
23-JAN-2008	MOS HRS/MSC - ENC			21-FEB-2019 5955:36 5506			
SB PW300-72-25333	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF HIGH PRESSURE COMPRESSOR CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER . DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
06-MAR-2008	MOS HRS/MSC - ENC						
SB PW300-72-25335	NO. 1 ENGINE - FAN HUB RETAINING NUT AND WASHER - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
13-MAY-2008	MOS HRS/MSC - ENC						
SB PW300-72-25337	NO. 1 ENGINE - INTRODUCTION OF LPT ROTOR & STATOR ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
15-JUL-2008	MOS HRS/MSC - ENC						
SB PW300-72-25338	NO. 1 ENGINE - REPLACEMENT OF FUEL WASTE EJECTOR, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
23-JUN-2008	MOS HRS/MSC - ENC						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25339	NO. 1 ENGINE - REPLACEMENT/INTRODUCTION OF SELF-LOCKING NUTS AND CAP SCREWS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
10-JUL-2008	MOS HRS/MSC - ENC						
SB PW300-72-25340	NO. 1 ENGINE - REPLACEMENT OF P2.8 AND P3 AIR TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
17-JUN-2008	MOS HRS/MSC - ENC			21-FEB-2019 5955:36 5506			
SB PW300-72-25341	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF HIGH PRESSURE TURBINE DISK ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
27-MAY-2008	MOS HRS/MSC - ENC			21-FEB-2019 5955:36 5506			
SB PW300-72-25342	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
24-NOV-2008	MOS HRS/MSC A/R ENC			04-MAR-2010 1077:06 1187			
SB PW300-72-25344	NO. 1 ENGINE - REPLACEMENT OF N1 SPEED SENSOR, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
02-SEP-2008	MOS HRS/MSC - ENC						
SB PW300-72-25345	NO. 1 ENGINE - REPLACEMENT OF HIGH PRESSURE TURBINE (HPT) SLEEVE SPACER, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
28-NOV-2008	MOS HRS/MSC - ENC						
SB PW300-72-25345 R01	NO. 1 ENGINE - REPLACEMENT OF HIGH PRESSURE TURBINE (HPT) SLEEVE SPACER, SERVICE BULLETIN					CATEGORY 7	
13-JAN-2021	MOS HRS/MSC - ENC AFL						
SB PW300-72-25346	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX (AGB) BREather TUBE ADAPTER GASKET (SUPERSEDED BY PW300-72-25346 R01), SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
21-NOV-2008	MOS HRS/MSC - ENC						
SB PW300-72-25346 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX (AGB) BREather TUBE ADAPTER GASKET, SERVICE BULLETIN					CATEGORY 7	
28-AUG-2018	MOS HRS/MSC - ENC AFL						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25347 R01	NO. 1 ENGINE - REPLACEMENT OF STARTER GENERATOR DRIVE SPUR GEARSHAFT (SUPERSEDED BY PW300-72-25347 R02), SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO PN
25-FEB-2013		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25347 R02	NO. 1 ENGINE - REPLACEMENT OF STARTER GENERATOR DRIVE SPUR GEARSHAFT, SERVICE BULLETIN					CATEGORY 6	- REFER TO R1 OF THIS SB
10-JUL-2015		MOS HRS/MSC - ENC					
SB PW300-72-25348	NO. 1 ENGINE - REPLACEMENT OF ANTI-ICING TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
02-DEC-2008		MOS HRS/MSC - ENC					
SB PW300-72-25348 R01	NO. 1 ENGINE - REPLACEMENT OF ANTI-ICING TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
09-DEC-2020		MOS HRS/MSC - ENC AFL					
SB PW300-72-25352	NO. 1 ENGINE - REPLACEMENT OF PREFORMED PACKINGS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
23-MAR-2009		MOS HRS/MSC - ENC					
SB PW300-72-25352 R01	NO. 1 ENGINE - SB PW300-72-25352 R01 - REPLACEMENT OF PREFORMED PACKINGS, SERVICE BULLETIN					CATEGORY 6	
22-OCT-2024		MOS HRS/MSC - ENC AFL		12055:36 M			
SB PW300-72-25353 R04	NO. 1 ENGINE - REPLACEMENT OF ALTERNATOR AND STARTER SEALS (SUPERSEDED BY PW300-72-25353 R05), SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH - SB PERFORMED BY P&W SEE S/O 122040 TSN 1077.1 CSN 1187
		MOS HRS/MSC A/R ENC					
SB PW300-72-25353 R05	NO. 1 ENGINE - REPLACEMENT OF ALTERNATOR AND STARTER SEALS, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH - PREVIOUSLY
05-FEB-2013		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25354 R01	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF PRIMARY FUEL NOZZLES, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - N/A BY ENGINE SERIAL NUMBER
16-JUN-2010		MOS HRS/MSC - ENC		19-MAR-2013 2491:42 2781			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25355	NO. 1 ENGINE - REPLACEMENT OF HIGH PRESSURE TURBINE SHROUD SEALS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
27-OCT-2009	MOS HRS/MSC - ENC						
SB PW300-72-25356	NO. 1 ENGINE - REPLACEMENT OF NO.1 BEARING COVER AND HOUSING ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
21-OCT-2009	MOS HRS/MSC - ENC						
SB PW300-72-25357	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX (AGB) MOUNTING PLATES AND ENGINE MOUNT PAD COVER BOLTS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
24-SEP-2009	MOS HRS/MSC - ENC						
SB PW300-72-25359 R01	NO. 1 ENGINE - REPLACEMENT OF VARIOUS COMPONENT ASSEMBLIES, BOLTS, BRACKETS (SUPERSEDED BY PW300-72-25359 R02), SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
03-MAY-2010	MOS HRS/MSC A/R ENC						
SB PW300-72-25359 R02	NO. 1 ENGINE - REPLACEMENT OF - VARIOUS COMPONENT ASSEMBLIES, BOLTS, BRACKETS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
09-JUL-2012	MOS HRS/MSC - ENC						
SB PW300-72-25360 R01	NO. 1 ENGINE - REPLACEMENT OF FUEL WASTE EJECTOR, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
06-MAY-2010	MOS HRS/MSC A/R ENC						
SB PW300-72-25361	NO. 1 ENGINE - AIR TRANSFER TUBES - REPLACEMENT OF (SUPERSEDED BY PW300-72-25361 R01), SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
01-MAR-2011	MOS HRS/MSC A/R ENC						
SB PW300-72-25361 R01	NO. 1 ENGINE - AIR TRANSFER TUBES - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
14-DEC-2011	MOS HRS/MSC A/R ENC			21-FEB-2019 5955:36 5506			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25362	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR BLEED SOLENOID VALVE, SERVICE BULLETIN					CATEGORY 8	DECLINED - SB OPTIONAL NOT PERFORMED. NOT REQUESTED BY THE CUSTOMER.
14-MAY-2010	MOS HRS/MSC A/R ENC						
SB PW300-72-25363	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF LOWER HALF BY-PASS DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
10-MAY-2010	MOS HRS/MSC A/R ENC						
SB PW300-72-25368	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY AND DIFFUSER EXIT DUCT (SUPERSEDED BY PW300-72-25368 R01), SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
16-JUN-2010	MOS HRS/MSC A/R ENC						
SB PW300-72-25368 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY AND DIFFUSER EXIT DUCT (SUPERSEDED BY PW300-72-25368 R02), SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
04-AUG-2011	MOS HRS/MSC - ENC						
SB PW300-72-25368 R02	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY AND DIFFUSER EXIT DUCT, SERVICE BULLETIN					CATEGORY 7	- REFER TO R1 OF THIS SB
23-MAY-2014	MOS HRS/MSC - ENC						
SB PW300-72-25369	NO. 1 ENGINE - REPLACEMENT OF SPEED SENSOR WIRING HARNESS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
14-JUN-2010	MOS HRS/MSC A/R ENC						
SB PW300-72-25370	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF NO. 1 BEARING HOUSING ASSEMBLY (SUPERSEDED BY PW300-72-25370 R01), SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
28-OCT-2011	MOS HRS/MSC A/R ENC						
SB PW300-72-25370 R01	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF NO. 1 BEARING HOUSING ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
01-FEB-2016	MOS HRS/MSC - ENC						
SB PW300-72-25371	NO. 1 ENGINE - INTERSHAFT OIL SEALS - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
28-SEP-2010	MOS HRS/MSC A/R ENC			21-FEB-2019 5955:36 5506			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25372	NO. 1 ENGINE - METAL GASKET - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
28-SEP-2010		MOS HRS/MSC ENC	A/R	21-FEB-2019 5955:36 5506			
SB PW300-72-25373	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF NO. 3 & 4 BEARING SCAVENGE PUMP HOUSING ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
28-OCT-2010		MOS HRS/MSC ENC	A/R				
SB PW300-72-25374	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF FUEL NOZZLES (SUPERSEDED BY PW300-72-25374 R01), SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
26-NOV-2010		MOS HRS/MSC ENC	A/R				
SB PW300-72-25374 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF FUEL NOZZLES, SERVICE BULLETIN					CATEGORY 7	- REFER TO ORIGINAL OF THIS SB
06-FEB-2015		MOS HRS/MSC ENC	-				
SB PW300-72-25375	NO. 1 ENGINE - REPLACEMENT OF SAFETY WIRE, SERVICE BULLETIN					CATEGORY 8	DECLINED - SB OPTIONAL NOT PERFORMED. NOT REQUESTED BY THE CUSTOMER.
15-DEC-2010		MOS HRS/MSC ENC	A/R				
SB PW300-72-25376	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMPRESSOR BLEED SOLENOID VALVE, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
21-JUN-2011		MOS HRS/MSC ENC	A/R				
SB PW300-72-25377	NO. 1 ENGINE - INSPECTION OF DAMPER SEAL INSTALLATION ON TURBINE ROTOR AIR SEAL, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE - BY ENGINE SERIAL NUMBER
04-OCT-2011		MOS HRS/MSC ENC	A/R				
SB PW300-72-25378	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF LOWER BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW300-72-25378 R01), SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
		MOS HRS/MSC ENC	A/R				
SB PW300-72-25378 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF LOWER BY-PASS DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
02-NOV-2012		MOS HRS/MSC ENC	-				

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25379	NO. 1 ENGINE - REPLACEMENT OF OUTER UPPER AND LOWER HALF BYPASS DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
31-OCT-2011	MOS HRS/MSC A/R ENC						
SB PW300-72-25380 R01	NO. 1 ENGINE - REVISED TRIM VALUES FOR PW306C ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW300-72-25380 R02), SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - SB 72-25380 R1 NO. 1 ENGINE - REVISED TRIM VALUES FOR PW306C ELECTRONIC ENGINE CONTROL (EEC) COMPLIED WITH.
09-NOV-2011	MOS HRS/MSC - ENC			13-AUG-2012 2254:30 2517			
SB PW300-72-25380 R02	NO. 1 ENGINE - REVISED TRIM VALUES FOR PW306C ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - ORIGINAL REVISION 1 OF THIS SB
16-DEC-2015	MOS HRS/MSC - ENC			09-FEB-2017 4721:48 4594			
SB PW300-72-25381	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX COVER ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
23-NOV-2012	MOS HRS/MSC - ENC						
SB PW300-72-25383	NO. 1 ENGINE - REPLACEMENT OF REAR LOWER BY-PASS DUCT FAIRING, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
02-DEC-2011	MOS HRS/MSC A/R ENC						
SB PW300-72-25384	NO. 1 ENGINE - REPLACEMENT OF BY-PASS DUCT SEGMENTS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
02-DEC-2011	MOS HRS/MSC A/R ENC						
SB PW300-72-25385	NO. 1 ENGINE - REPLACEMENT OF BY-PASS DUCT FAIRINGS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
08-MAY-2012	MOS HRS/MSC - ENC						
SB PW300-72-25386	NO. 1 ENGINE - REPLACEMENT OF FIRST STAGE VANE ACTUATOR RING SET, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
10-JUL-2012	MOS HRS/MSC - ENC						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25387	NO. 1 ENGINE - REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY PW300-72-25387 R01), SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
17-SEP-2012		MOS HRS/MSC - ENC					
SB PW300-72-25387 R01	NO. 1 ENGINE - REPLACEMENT OF FUEL NOZZLE, SERVICE BULLETIN					CATEGORY 7	- REFER TO ORIGINAL OF THIS SB
30-JAN-2015		MOS HRS/MSC - ENC					
SB PW300-72-25388	NO. 1 ENGINE - REPLACEMENT OF N1 AND N2 SPEED SENSORS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
16-AUG-2012		MOS HRS/MSC - ENC					
SB PW300-72-25389	NO. 1 ENGINE - REPLACEMENT OF HIGH PRESSURE COMPRESSOR CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
10-OCT-2012		MOS HRS/MSC - ENC					
SB PW300-72-25390	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE, SERVICE BULLETIN					CATEGORY 7	
28-JUN-2013		MOS HRS/MSC - ENC					
SB PW300-72-25391	NO. 1 ENGINE - REPLACEMENT OF SPEED SENSOR WIRING HARNESS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
14-FEB-2013		MOS HRS/MSC - ENC					
SB PW300-72-25395	NO. 1 ENGINE - REPLACEMENT OF ALTERNATOR AND STARTER SEALS (SUPERSEDED BY PW300-72-25395 R01), SERVICE BULLETIN						
18-SEP-2013		MOS HRS/MSC - ENC					
SB PW300-72-25395 R01	NO. 1 ENGINE - REPLACEMENT OF ALTERNATOR AND STARTER SEALS, SERVICE BULLETIN						
23-MAY-2014		MOS HRS/MSC - ENC					
SB PW300-72-25395 R02	NO. 1 ENGINE - REPLACEMENT OF ALTERNATOR AND STARTER SEALS (SUPERSEDED BY SB PW300-72-25395 R02), SERVICE BULLETIN					CATEGORY 10	
01-OCT-2019		MOS HRS/MSC - ENC AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25397	NO. 1 ENGINE - REPAIR/MODIFICATION OF ENGINE ELECTRONIC CONTROL (EEC), SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH
09-JAN-2014		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25398	NO. 1 ENGINE - REPLACEMENT OF NO. 2 BEARING REAR CARBON SEAL, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
15-JAN-2014		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25403	NO. 1 ENGINE - INTRODUCTION OF ACCESSORY GEARBOX SHAFT SHIELD (SUPERSEDED BY PW300-72-25403 R01), SERVICE BULLETIN					CATEGORY 6	
02-MAY-2014		MOS HRS/MSC - ENC					
SB PW300-72-25403 R01	NO. 1 ENGINE - INTRODUCTION OF ACCESSORY GEARBOX SHAFT SHIELD, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - PREVIOUSLY
14-MAY-2014		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25406	NO. 1 ENGINE - REPLACEMENT OF PROTECTIVE CAPS FOR ENGINE SHIPPING CONTAINER ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
23-JUN-2014		MOS HRS/MSC - ENC					
SB PW300-72-25408	NO. 1 ENGINE - REPLACEMENT OF TRANSFER TUBE AND PREFORMED PACKINGS (SUPERSEDED BY PW300-72-25408 R01), SERVICE BULLETIN					CATEGORY 6	
22-JUL-2014		MOS HRS/MSC - ENC					
SB PW300-72-25408 R01	NO. 1 ENGINE - REPLACEMENT OF TRANSFER TUBE AND PREFORMED PACKINGS (SUPERSEDED BY PW300-72-25408 R02), SERVICE BULLETIN					CATEGORY 6	
22-OCT-2014		MOS HRS/MSC - ENC					
SB PW300-72-25408 R02	NO. 1 ENGINE - REPLACEMENT OF TRANSFER TUBE AND PREFORMED PACKINGS, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
04-DEC-2014		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25409	NO. 1 ENGINE - RELOCATION OF OIL FILLER NECK VENT TUBE SUPPORT BRACKET, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
29-JUL-2014		MOS HRS/MSC - ENC		21-FEB-2019 5955:36 5506			
SB PW300-72-25410	NO. 1 ENGINE - REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT (SUPERSEDED BY PW300-72-25410 R01), SERVICE BULLETIN					CATEGORY 7	
27-JAN-2015		MOS HRS/MSC - ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25410 R01	NO. 1 ENGINE - REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT, SERVICE BULLETIN					CATEGORY 7	
07-JAN-2016		MOS HRS/MSC - ENC					
SB PW300-72-25411	NO. 1 ENGINE - REPLACEMENT OF ELECTRONIC ENGINE CONTROL (SUPERSEDED BY PW300-72-25411 R01), SERVICE BULLETIN				CATEGORY 7		
09-FEB-2015		MOS HRS/MSC - ENC					
SB PW300-72-25411 R01	NO. 1 ENGINE - REPLACEMENT OF ELECTRONIC ENGINE CONTROL, SERVICE BULLETIN					CATEGORY 7	
03-NOV-2015		MOS HRS/MSC - ENC					
SB PW300-72-25412	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT (SUPERSEDED BY PW300-72-25412 R01), SERVICE BULLETIN				CATEGORY 7		
05-MAR-2015		MOS HRS/MSC - ENC					
SB PW300-72-25412 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT (SUPERSEDED BY PW300-72-25412 R02), SERVICE BULLETIN				CATEGORY 7		
28-APR-2015		MOS HRS/MSC - ENC					
SB PW300-72-25412 R02	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT (SUPERSEDED BY PW300-72-25412 R03), SERVICE BULLETIN				CATEGORY 7		
10-NOV-2015		MOS HRS/MSC - ENC					
SB PW300-72-25412 R03	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT (SUPERSEDED BY PW300-72-25412 R04), SERVICE BULLETIN				CATEGORY 7		
13-NOV-2015		MOS HRS/MSC - ENC					
SB PW300-72-25412 R04	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT, SERVICE BULLETIN				CATEGORY 7		
18-MAR-2016		MOS HRS/MSC - ENC					
SB PW300-72-25412 R05	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT, SERVICE BULLETIN				CATEGORY 7		
21-JUL-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25413 R01	NO. 1 ENGINE - REPLACEMENT OF FIFTH STAGE LOW PRESSURE TURBINE DISK, SERVICE BULLETIN				CATEGORY 9		
22-JUN-2015		MOS HRS/MSC - ENC					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25415	NO. 1 ENGINE - REPLACEMENT OF NO. 2 BEARING OIL NOZZLE, SERVICE BULLETIN			MOS HRS/MSC - ENC		CATEGORY 7	
29-MAY-2015							
SB PW300-72-25417	NO. 1 ENGINE - REPLACEMENT OF HIGH PRESSURE TURBINE VANE INNER SUPPORT, SERVICE BULLETIN			MOS HRS/MSC - ENC		CATEGORY 7	
29-MAY-2015							
SB PW300-72-25420	NO. 1 ENGINE - CONVERSION OF PW306C (BS1026) ENGINE TO PW306D (BS1298) ENGINE CONFIGURATION, SERVICE BULLETIN			MOS HRS/MSC - ENC		CATEGORY 8	
04-DEC-2015							
SB PW300-72-25420 R01	NO. 1 ENGINE - CONVERSION OF PW306C (BS1026) ENGINE TO PW306D (BS1298) ENGINE CONFIGURATION, SERVICE BULLETIN			MOS HRS/MSC - ENC AFL		CATEGORY 8	
26-MAR-2019							
SB PW300-72-25420 R02	NO. 1 ENGINE - CONVERSION OF PW306C (BS1026) ENGINE TO PW306D (BS1298) ENGINE CONFIGURATION, SERVICE BULLETIN			MOS HRS/MSC - ENC AFL		CATEGORY 8	
15-OCT-2021							
SB PW300-72-25421	NO. 1 ENGINE - REPLACEMENT OF NO. 1 BEARING CARBON AIR SEAL, SERVICE BULLETIN			MOS HRS/MSC - ENC	21-FEB-2019 5955:36 5506	CATEGORY 9	COMPLIED WITH
13-NOV-2015							
SB PW300-72-25425	NO. 1 ENGINE - REPLACEMENT OF HIGH PRESSURE COMPRESSOR STATOR ASSEMBLY (SUPERSEDED BY PW300-72-25425 R01), SERVICE BULLETIN			MOS HRS/MSC - ENC		CATEGORY 6	
16-MAY-2016							
SB PW300-72-25425 R01	NO. 1 ENGINE - REPLACEMENT OF HIGH PRESSURE COMPRESSOR STATOR ASSEMBLY, SERVICE BULLETIN			MOS HRS/MSC - ENC	21-FEB-2019 5955:36 5506	CATEGORY 6	COMPLIED WITH
04-JUN-2017							
SB PW300-72-25431	NO. 1 ENGINE - INTRODUCTION OF LOW PRESSURE TURBINE (LPT) THIRD-STAGE VANE ASSEMBLY OUTER AIR SEAL RING (SUPERSEDED BY PW300-72-25431 R01), SERVICE BULLETIN			MOS HRS/MSC - ENC		CATEGORY 9	
13-FEB-2017							
SB PW300-72-25431 R01	NO. 1 ENGINE - INTRODUCTION OF LOW PRESSURE TURBINE (LPT) THIRD-STAGE VANE ASSEMBLY OUTER AIR SEAL RING, SERVICE BULLETIN			MOS HRS/MSC - ENC		CATEGORY 9	
13-APR-2017							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25433	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS (SUPERSEDED BY PW300-72-25433 R01), SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
13-FEB-2017		MOS HRS/MSC - ENC		10-AUG-2018 5789:15 5372			
SB PW300-72-25433 R01	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
07-JUN-2018		MOS HRS/MSC - ENC		10-AUG-2018 5789:15 5372			
SB PW300-72-25433 R02	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - PREVIOUS REVISION 1 ON 10 AUG 2018 AT 5789:15 HRS AND 5372 CYCLS - REVISION 2 HAS NO AFFECT ON PRIOR ACCOMPLISHMENT // CHECKDATE 17 AUG 2022 // WO CEIS-07/22
28-JUN-2022		MOS HRS/MSC - ENC AFL					
SB PW300-72-25434	NO. 1 ENGINE - INSPECTION OF OUTER BYPASS DUCT LOWER FAIRING, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY ENGINE S/N
26-APR-2017		MOS HRS/MSC - ENC		23-JAN-2018 5426:01 5094			
SB PW300-72-25434 R01	NO. 1 ENGINE - INSPECTION OF OUTER BYPASS DUCT LOWER FAIRING, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - SN ENGINE NOT AFFECTED // CHECKDATE 17 AUG 2022 // WO CEIS-07/22
28-JUN-2022		MOS HRS/MSC - ENC AFL					
SB PW300-72-25435 R01	NO. 1 ENGINE - REPLACEMENT OF PRESSURE AND TEMPERATURE SENSORS, SERVICE BULLETIN					CATEGORY 7	
29-MAY-2017		MOS HRS/MSC - ENC					
SB PW300-72-25436	NO. 1 ENGINE - INTRODUCTION OF ADD SEALANT, SERVICE BULLETIN					CATEGORY 6	
29-MAY-2017		MOS HRS/MSC - ENC					
SB PW300-72-25436 R01	NO. 1 ENGINE - INTRODUCTION OF ADD SEALANT, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - BULLETIN PERFORMED BY MTU MAINTENANCE BERLIN-BRANDENBURG GMBH. FOR MORE DETAILS REFER TO EASA FORM 1 D033/24 AND MTU WO 4500002492.
05-FEB-2019		MOS HRS/MSC - ENC		12-DEC-2024 9092:25 7785			
SB PW300-72-25440	NO. 1 ENGINE - REPLACEMENT OF WIRING HARNESS PREFORMED PACKING, SERVICE BULLETIN					CATEGORY 9	
16-NOV-2017		MOS HRS/MSC - ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25441	NO. 1 ENGINE - INTRODUCTION OF TURBINE EXHAUST CASE ASSEMBLY OPTION (IC), SERVICE BULLETIN					CATEGORY 9	
16-MAY-2018		MOS HRS/MSC - ENC AFL					
SB PW300-72-25444	NO. 1 ENGINE - REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW300-72-25444 R01), SERVICE BULLETIN					CATEGORY 8	
27-AUG-2018		MOS HRS/MSC - ENC AFL					
SB PW300-72-25444 R01	NO. 1 ENGINE - REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	
01-OCT-2018		MOS HRS/MSC - ENC AFL					
SB PW300-72-25444 R02	NO. 1 ENGINE - REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	
15-NOV-2018		MOS HRS/MSC - ENC AFL					
SB PW300-72-25444 R03	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	
06-FEB-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25446	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	
11-DEC-2018		MOS HRS/MSC - ENC AFL					
SB PW300-72-25446 R01	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	
10-JAN-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25446 R02	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	
14-FEB-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25446 R03	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	
04-MAR-2019		MOS HRS/MSC - ENC AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25446 R04	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	
25-JUN-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25446 R05	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF LOWER-HALF BYPASS DUCT ASSEMBLY, SERVICE BULLETIN				01-FEB-2008 0 0	CATEGORY 6	
20-AUG-2019		MOS HRS/MSC - ENC			12055:36 M		
SB PW300-72-25447	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE, SERVICE BULLETIN					CATEGORY 7	
08-JAN-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25447 R01	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE, SERVICE BULLETIN					CATEGORY 7	
22-JAN-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25447 R02	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE, SERVICE BULLETIN					CATEGORY 7	
11-FEB-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25447 R03	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE, SERVICE BULLETIN					CATEGORY 7	
10-JUL-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25447 R04	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE, SERVICE BULLETIN					CATEGORY 7	
24-NOV-2020		MOS HRS/MSC - ENC AFL					
SB PW300-72-25450	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR, SERVICE BULLETIN					CATEGORY 7	
10-JAN-2019		MOS HRS/MSC - ENC AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25450 R01	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR, SERVICE BULLETIN					CATEGORY 7	
21-JAN-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25450 R02	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR, SERVICE BULLETIN					CATEGORY 7	
05-FEB-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25450 R03	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR, SERVICE BULLETIN					CATEGORY 7	
01-DEC-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25450 R04	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR, SERVICE BULLETIN					CATEGORY 7	
06-MAR-2025		MOS HRS/MSC - ENC					
SB PW300-72-25451	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN					CATEGORY 7	
27-AUG-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25451 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN					CATEGORY 7	
06-APR-2020		MOS HRS/MSC - ENC AFL					
SB PW300-72-25451 R02	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN					CATEGORY 7	
13-NOV-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25452	NO. 1 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
16-SEP-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25452 R01	NO. 1 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
05-FEB-2020		MOS HRS/MSC - ENC AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25452 R02	NO. 1 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
18-FEB-2020		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25452 R03	NO. 1 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
19-MAR-2020		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25452 R04	NO. 1 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
08-JUL-2020		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25452 R05	NO. 1 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
28-AUG-2020		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25452 R06	NO. 1 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
26-MAY-2021		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25452 R07	NO. 1 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
24-JUN-2021		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25452 R08	NO. 1 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
06-NOV-2023		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25453	NO. 1 ENGINE - REPLACEMENT OF OUTER COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
28-MAY-2019		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25457	NO. 1 ENGINE - REPLACEMENT OF FIRE DETECTOR BRACKET HINGED CLAMP, SERVICE BULLETIN					CATEGORY 9	
25-MAY-2020		MOS					
		HRS/MSC	-				
		ENC					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25459	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS, SERVICE BULLETIN						NOT APPLICABLE - N/A SB IS ONLY FOR ENGINES OPERATED BY NETJETS AVIATION INC // CHECKDATE 27 APR 2021 // WO CEIS-07/21
15-JAN-2021		MOS HRS/MSC - ENC AFL					
SB PW300-72-25459 R01	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS, SERVICE BULLETIN						NOT APPLICABLE - N/A SB IS ONLY FOR ENGINES OPERATED BY NETJETS AVIATION INC // CHECKDATE 27 APR 2021 // WO CEIS-07/21
11-FEB-2021		MOS HRS/MSC - ENC AFL					
SB PW300-72-25459 R02	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
09-AUG-2023		MOS HRS/MSC - ENC		27-OCT-2023 8455:54 7327			
SB PW300-72-25459 R03	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - REVISION 02 OF THIS SB AT 27 OCT 2023 WITH 8455:54 HRS AND 7327 CYCLES. // CHECKDATE 21 OCT 2024 // WO CEIS-20/24
19-AUG-2024		MOS HRS/MSC - ENC					
SB PW300-72-25460 R01	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
22-FEB-2022		MOS HRS/MSC - ENC AFL					
SB PW300-72-25460 R02	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
25-MAY-2022		MOS HRS/MSC - ENC AFL					
SB PW300-72-25460 R03	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
28-JUN-2022		MOS HRS/MSC - ENC AFL					
SB PW300-72-25460 R04	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
19-AUG-2022		MOS HRS/MSC - ENC AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25460 R05	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
13-SEP-2022		MOS HRS/MSC - ENC AFL					
SB PW300-72-25460 R06	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
19-JAN-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25460 R07	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
24-OCT-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25460 R08	NO. 1 ENGINE - SB PW300-72-25460 R08 - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
28-NOV-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25460 R09	NO. 1 ENGINE - SB PW300-72-25460 R09 - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
28-MAR-2024		MOS HRS/MSC - ENC AFL					
SB PW300-72-25460 R10	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - SERVICE BULLETIN PERFORMED BY MTU MAINTENANCE BERLIN-BRANDENBURG GMBH. FOR MORE DETAILS REFER TO EASA FORM1 D033/24 AND MTU WO 4500002492.
07-MAY-2024		MOS HRS/MSC - ENC		12-DEC-2024 9092:25 7785			
SB PW300-72-25462	NO. 1 ENGINE - INSPECTION OF OUTER ELECTRICAL WIRING HARNESS, SERVICE BULLETIN					CATEGORY 4	COMPLIED WITH
22-SEP-2021		MOS HRS/MSC - ENC		17-NOV-2021 7490:26 6618			
SB PW300-72-25462 R01	NO. 1 ENGINE - INSPECTION OF OUTER ELECTRICAL WIRING HARNESS, SERVICE BULLETIN					CATEGORY 4	COMPLIED WITH - ORIGINAL REV. OF THIS SB 17 NOV 2021 AT 7490:26 HRS AND 6618 CYCLS. THIS REVISION HAS NO EFFECT ON ENGINES PREV. IN COMPLIANCE WITH THIS SERVICE DOC // CHECKDATE 22 JUN 2022 // WO CEIS-02/22
07-MAR-2022		MOS HRS/MSC - ENC AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25463	NO. 1 ENGINE - REPLACEMENT OF TIE ROD RETAINING NUT, SERVICE BULLETIN					CATEGORY 7	
02-SEP-2022		MOS HRS/MSC - ENC AFL					
SB PW300-72-25465	NO. 1 ENGINE - INSPECTION OF DUPLEX FUEL NOZZLE, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - BULLETIN PERFORMED BY MTU MAINTENANCE BERLIN-BRANDENBURG GMBH. FOR MORE DETAILS REFER TO EASA FORM 1 D033/24 AND MTU WO 4500002492.
13-SEP-2022		MOS HRS/MSC - ENC		12-DEC-2024 9092:25 7785			
SB PW300-72-25466	NO. 1 ENGINE - REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
22-AUG-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25466 R01	NO. 1 ENGINE - REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
01-DEC-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25466 R02	NO. 1 ENGINE - REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
31-JAN-2025		MOS HRS/MSC - ENC					
SB PW300-72-25466 R03	NO. 1 ENGINE - REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
23-APR-2025		MOS HRS/MSC - ENC					
SB PW300-72-25467	NO. 1 ENGINE - REPLACEMENT OF DUPLEX FUEL NOZZLE, SERVICE BULLETIN					CATEGORY 7	
19-JAN-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25471	NO. 1 ENGINE - SB PW300-72-25471 - INSPECTION OF INLET GUIDE VANE ACTUATING ARM ASSY, SERVICE BULLETIN					CATEGORY 6	
29-MAR-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25471 R01	NO. 1 ENGINE - SB PW300-72-25471 R01 - INSPECTION OF INLET GUIDE VANE ACTUATING ARM ASSY, SERVICE BULLETIN					CATEGORY 6	
14-MAR-2024		MOS HRS/MSC - ENC AFL		12055:36 M			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25475	NO. 1 ENGINE - REPLACEMENT OF INLET GUIDE VANE SHROUD SET, SERVICE BULLETIN			MOS HRS/MSC - ENC AFL	13-MAY-2024	CATEGORY 7	
SB PW300-72-25475 R01	NO. 1 ENGINE - REPLACEMENT OF INLET GUIDE VANE SHROUD SET, SERVICE BULLETIN			MOS HRS/MSC - ENC AFL	19-JUL-2024	CATEGORY 7	
SB PW300-72-25480	NO. 1 ENGINE - REPLACEMENT OF ACTUATOR SUPPORT-BRACKET, SERVICE BULLETIN			MOS HRS/MSC - ENC	28-MAR-2025	CATEGORY 7	
SB PW300-73-25462 R02	NO. 1 ENGINE - INSPECTION OF OUTER ELECTRICAL WIRING HARNESS, SERVICE BULLETIN			MOS HRS/MSC - ENC AFL	16-APR-2024	CATEGORY 4	COMPLIED WITH - ORIGINAL REV. OF THIS SB 17 NOV 2021 AT 7490:26 HRS AND 6618 CYCLS. THIS REVISION HAS NO EFFECT ON ENGINES PREV. IN COMPLIANCE WITH THIS SB.
SB PW300-75-25454	NO. 1 ENGINE - REPLACEMENT OF BLEED VALVE TUBE ASSEMBLY, SERVICE BULLETIN			MOS HRS/MSC - ENC AFL	24-OCT-2023	CATEGORY 7	
SB PW300-75-25454 R01	NO. 1 ENGINE - REPLACEMENT OF BLEED VALVE TUBE ASSEMBLY, SERVICE BULLETIN			MOS HRS/MSC - ENC AFL	06-NOV-2023	CATEGORY 7	
SB PW300-75-25454 R02	NO. 1 ENGINE - REPLACEMENT OF BLEED VALVE TUBE ASSEMBLY, SERVICE BULLETIN			MOS HRS/MSC - ENC AFL	23-AUG-2024	CATEGORY 7	
SB PW300-77-25474	NO. 1 ENGINE - REPLACEMENT / RE-IDENTIFICATION OF TC-T4.5 WIRING HARNESS, SERVICE BULLETIN			MOS HRS/MSC - ENC AFL	05-APR-2024	CATEGORY 7	
SB PW300-77-25474 R01	NO. 1 ENGINE - REPLACEMENT/RE-IDENTIFICATION OF TC-T4.5 WIRING HARNESS, SERVICE BULLETIN			MOS HRS/MSC - ENC AFL	19-JUL-2024	CATEGORY 7	

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-77-25474 R02	NO. 1 ENGINE - REPLACEMENT/RE-IDENTIFICATION OF TC-T4.5 WIRING HARNESS, SERVICE BULLETIN					CATEGORY 7	
26-AUG-2024		MOS HRS/MSC - ENC AFL					
SB PW300-77-25474 R03	NO. 1 ENGINE - REPLACEMENT/RE-IDENTIFICATION OF TC-T4.5 WIRING HARNESS, SERVICE BULLETIN					CATEGORY 7	
09-SEP-2024		MOS HRS/MSC - ENC AFL					
SIL GEN-153 R04	NO. 1 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R05), SERVICE INFORMATION LETTER					INFORMATIONAL	
05-MAY-2020		MOS HRS/MSC - ENC AFL					
SIL GEN-153 R05	NO. 1 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06), SERVICE INFORMATION LETTER					INFORMATIONAL	
28-SEP-2020		MOS HRS/MSC - ENC AFL					
SIL GEN-153 R06	NO. 1 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION, SERVICE INFORMATION LETTER					INFORMATIONAL	
30-OCT-2020		MOS HRS/MSC - ENC AFL					
SIL GEN-153 R07	NO. 1 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION, SERVICE INFORMATION LETTER					INFORMATIONAL	
05-JAN-2021		MOS HRS/MSC A/R ENC AFL					
SIL GEN-153 R08	NO. 1 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION, SERVICE INFORMATION LETTER					INFORMATIONAL	
15-SEP-2021		MOS HRS/MSC A/R ENC AFL					
SIL GEN-153 R09	NO. 1 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION, SERVICE INFORMATION LETTER					INFORMATIONAL	
18-JAN-2022		MOS HRS/MSC A/R ENC AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SIL GEN-153 R10	NO. 1 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION, SERVICE INFORMATION LETTER					INFORMATIONAL	
31-OCT-2022		MOS HRS/MSC ENC AFL	A/R				
SPI 000002	NO. 1 ENGINE - POWERADVANTAGE+ CONTRACT TERMINATION, SPECIAL INSTRUCTION					INFORMATIONAL	
		MOS HRS/MSC ENC	36 1800	15-DEC-2024 9093:02	15-DEC-2027 10893:02	RECURRING	

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 2 - SB - PCE-CG0376/30B4258-01							
ASB R01	PW300-72-A25358 NO. 2 ENGINE - INSPECTION /REPLACEMENT OF ALTERNATOR AND STARTER MAGNETIC SEAL ASSEMBLIES, ALERT SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 3	NOT APPLICABLE - DUE TO POST SB25353
SB 21-JUL-2016	PW100-72-25428 NO. 2 ENGINE - INTRODUCTION OF SELF-LOCKING NUT (IC) OPTION, SERVICE BULLETIN			MOS HRS/MSC - ENC		CATEGORY 9	
SB 17-MAR-2003	PW300-72-25167 R02 NO. 2 ENGINE - HYDROMECHANICAL FUEL CONTROL - REPLACEMENT OF, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 6	NOT APPLICABLE - DUE TO ESN
SB 14-JUN-2006	PW300-72-25177 R03 NO. 2 ENGINE - SECOND STAGE HIGH PRESSURE COMPRESSOR ROTOR - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 6	NOT APPLICABLE - DUE TO ESN
SB 19-MAR-2003	PW300-72-25178 NO. 2 ENGINE - ATTACHMENT BOLTS FOR HIGH PRESSURE COMPRESSOR (HPC) REAR CASE - REPLACEMENT OF, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 6	NOT APPLICABLE - DUE TO ESN
SB 15-APR-2003	PW300-72-25179 NO. 2 ENGINE - PREFORMED PACKINGS FOR THE N1 SPEED SENSORS OR PACKING COVERS - REPLACEMENT OF, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 6	NOT APPLICABLE - DUE TO ESN
SB 14-APR-2003	PW300-72-25181 NO. 2 ENGINE - NO. 1 BEARING CARBON SEAL RUNNER - REPLACEMENT OF, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 4	NOT APPLICABLE - DUE TO ESN
SB 15-APR-2003	PW300-72-25182 NO. 2 ENGINE - P3 TRANSDUCER TUBE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 6	NOT APPLICABLE - DUE TO ESN
SB 14-APR-2003	PW300-72-25183 NO. 2 ENGINE - FIRE SENSOR CORE WIRING HARNESS - REPLACEMENT OF, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 6	NOT APPLICABLE - DUE TO ESN

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25184	NO. 2 ENGINE - OUTER ELECTRICAL WIRING HARNESS - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 4	NOT APPLICABLE - DUE TO ESN
14-APR-2003	MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506					
SB PW300-72-25187	NO. 2 ENGINE - ACCESSORY GEARBOX (AGB) MAGNETIC FACE SEAL ASSEMBLY - REPLACEMENT/INTRODUCTION OF, SERVICE BULLETIN				CATEGORY 3	NOT APPLICABLE - DUE TO ESN	
15-DEC-2004	MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506					
SB PW300-72-25188	NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL (EEC) - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ESN	
15-APR-2003	MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506					
SB PW300-72-25189	NO. 2 ENGINE - MODIFICATION OF MAIN DATA PLATE, SERVICE BULLETIN				CATEGORY 3	NOT APPLICABLE - DUE TO ESN	
	MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506					
SB PW300-72-25190	NO. 2 ENGINE - INLET GUIDE VANE SHROUD SET - REPLACEMENT/MODIFICATION OF NO. 2 BEARING RETAINER - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ESN	
07-APR-2003	MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506					
SB PW300-72-25195	NO. 2 ENGINE - REAR LOWER DUCT HALF ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN				CATEGORY 5	NOT APPLICABLE - DUE TO ESN	
16-MAY-2003	MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506					
SB PW300-72-25196 R03	NO. 2 ENGINE - REPLACEMENT OF FIRST STAGE HIGH PRESSURE TURBINE (HPT) BLADES, SERVICE BULLETIN				CATEGORY 3	NOT APPLICABLE - DUE TO ESN	
25-FEB-2004	MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506					
SB PW300-72-25198	NO. 2 ENGINE - OIL FILLER VENT TUBE BRACKET - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 3	NOT APPLICABLE - DUE TO ESN	
10-DEC-2004	MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506					
SB PW300-72-25201 R01	NO. 2 ENGINE - REPLACEMENT PREFORMED PACKING FOR COMBUSTION CHAMBER CASE DRAIN VALVE ADAPTER, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ESN	
	MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506					
SB PW300-72-25202	NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL (EEC) AND ENGINE DIAGNOSTIC UNIT (EDU) - REPROGRAMMING/REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 3	NOT APPLICABLE - DUE TO ESN	
05-SEP-2003	MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25211 R02	NO. 2 ENGINE - REPLACEMENT OF HIGH PRESSURE TURBINE AIR NOZZLE SUPPORT AND VANE ASSEMBLIES, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - N/A BY ENGINE SERIAL NUMBER
27-AUG-2008		MOS HRS/MSC - ENC		19-MAR-2013 2491:42 2781			
SB PW300-72-25213	NO. 2 ENGINE - REDEFINED OIL FILLER NECK ASSEMBLY - INTRODUCTION OF, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 6	NOT APPLICABLE - DUE TO ESN
28-NOV-2003		MOS HRS/MSC - ENC		5955:36 5506			
SB PW300-72-25215	NO. 2 ENGINE - FIRST STAGE HIGH PRESSURE TURBINE (HPT) BLADE AIR SEALS - REPLACEMENT OF, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 6	NOT APPLICABLE - DUE TO ESN
28-JAN-2004		MOS HRS/MSC - ENC		5955:36 5506			
SB PW300-72-25216 R01	NO. 2 ENGINE - OUTER COMBUSTION CHAMBER LINER ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 6	NOT APPLICABLE - DUE TO ESN
24-AUG-2005		MOS HRS/MSC - ENC		5955:36 5506			
SB PW300-72-25218	NO. 2 ENGINE - NO.2 BEARING - REPLACEMENT OF, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 6	NOT APPLICABLE - DUE TO ESN
27-FEB-2004		MOS HRS/MSC - ENC		5955:36 5506			
SB PW300-72-25221	NO. 2 ENGINE - REDEFINED OIL FILLER NECK ASSEMBLY - REPLACEMENT/INTRODUCTION OF, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 6	NOT APPLICABLE - DUE TO ESN
29-MAR-2004		MOS HRS/MSC - ENC		5955:36 5506			
SB PW300-72-25222	NO. 2 ENGINE - MOTIVE FLOW VALVE - REPLACEMENT OF, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 6	NOT APPLICABLE - DUE TO ESN
19-FEB-2004		MOS HRS/MSC - ENC		5955:36 5506			
SB PW300-72-25224 R01	NO. 2 ENGINE - FUEL NOZZLE - INSPECTION/REPLACEMENT OF, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 6	NOT APPLICABLE - DUE TO ESN
11-FEB-2005		MOS HRS/MSC - ENC		5955:36 5506			
SB PW300-72-25225	NO. 2 ENGINE - ENVIRONMENTAL CONTROL SYSTEM (ECS) FAIRING BOLTS - REPLACEMENT OF, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 6	NOT APPLICABLE - DUE TO ESN
27-FEB-2004		MOS HRS/MSC - ENC		5955:36 5506			
SB PW300-72-25229 R04	NO. 2 ENGINE - HPT DISK BALANCING ASSEMBLY AND VANE ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 6	NOT APPLICABLE - DUE TO ESN
27-JUL-2007		MOS HRS/MSC - ENC		5955:36 5506			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25229 R05	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF HPT DISK BALANCING ASSEMBLY AND VANE ASSEMBLY, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - N/A BY ENGINE S/N //	CHECKDATE 12 NOV 2020 // WO CEIS-08/20
		MOS					
04-NOV-2020		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25230 R03	NO. 2 ENGINE - TURBOFAN ENGINE - REPLACEMENT OF HPT DISK BALANCING ASSEMBLY, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ESN	
		MOS		09-MAR-2019			
27-JUL-2007		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25233	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) FRONT COVER - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ESN	
		MOS		09-MAR-2019			
30-APR-2004		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25234 R04	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) VANE ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ESN	
		MOS		09-MAR-2019			
26-JUL-2011		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25235	NO. 2 ENGINE - FUEL MANIFOLD DRAIN ADAPTER BOLTS - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ESN	
		MOS		09-MAR-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25239	NO. 2 ENGINE - P0 TOTAL AIR PRESSURE TUBE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 3	NOT APPLICABLE - DUE TO ESN	
		MOS		09-MAR-2019			
31-AUG-2004		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25240	NO. 2 ENGINE - T4.5 TRIM ADJUSTMENT, SERVICE BULLETIN				CATEGORY 3	NOT APPLICABLE - DUE TO ESN	
		MOS		09-MAR-2019			
03-NOV-2004		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25247 R01	NO. 2 ENGINE - ENGINE DIAGNOSTIC UNIT (EDU) - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN				CATEGORY 6	NOT APPLICABLE - DUE TO ESN	
		MOS		09-MAR-2019			
15-AUG-2005		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25249 R01	NO. 2 ENGINE - FUEL NOZZLES - MODIFICATION /REPLACEMENT OF (SUPERSEDED BY PW300-72-25249 R02), SERVICE BULLETIN				CATEGORY 5	COMPLIED WITH	
		MOS		15-MAY-2014			
27-MAY-2005		HRS/MSC	-	3026			
		ENC		3394			
SB PW300-72-25249 R02	NO. 2 ENGINE - MODIFICATION /REPLACEMENT OF FUEL NOZZLES, SERVICE BULLETIN				CATEGORY 5	COMPLIED WITH - PREVIOUSLY	
		MOS		09-MAR-2019			
18-NOV-2014		HRS/MSC	-	5955:36			
		ENC		5506			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25254 R01	NO. 2 ENGINE - HONEYCOMB SEAL RUNNER RETAINING RING - INSPECTION/CRIMPING OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ESN
27-JUL-2007		MOS		09-MAR-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25255 R03	NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO ESN
		MOS		09-MAR-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25256	NO. 2 ENGINE - T4.5 TRIM ADJUSTMENT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO ESN
12-MAY-2005		MOS		09-MAR-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25258 R02	NO. 2 ENGINE - OIL FILTER IMPENDING BYPASS SWITCH - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY ENGINE SERIAL NUMBER - FACTORY EMBODIED
21-MAR-2011		MOS					
		HRS/MSC	A/R				
SB PW300-72-25262	NO. 2 ENGINE - T4.5 TRIM ADJUSTMENT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO ESN
02-JUN-2005		MOS		09-MAR-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25263	NO. 2 ENGINE - LOW COMPRESSOR SHAFT ASSEMBLY - INSPECTION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO ESN
15-AUG-2005		MOS		09-MAR-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25264 R01	NO. 2 ENGINE - IMPENDING FUEL FILTER BYPASS SWITCH - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY ENGINE SERIAL NUMBER - FACTORY EMBODIED
23-MAR-2011		MOS					
		HRS/MSC	A/R				
SB PW300-72-25265 R01	NO. 2 ENGINE - WORKSCOPE FOR LOW UTILIZATION INSPECTION, SERVICE BULLETIN					CATEGORY 10	
09-MAR-2018		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25267	NO. 2 ENGINE - TAB LOCKWASHERS - INTRODUCTION OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ESN
16-DEC-2005		MOS		09-MAR-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25268 R01	NO. 2 ENGINE - ENGINE DIAGNOSTIC UNIT - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - PREVIOUSLY
		MOS		09-MAR-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25270 R01	NO. 2 ENGINE - INTRODUCTION OF NEW ENGINE ASSEMBLY PROCEDURES AND HARDWARE, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY ENGINE S/N // CHECKDATE 04 APR 2019 // WO CEIS-05/19 REV. 01
21-SEP-2014		MOS HRS/MSC - ENC					
SB PW300-72-25270 R02	NO. 2 ENGINE - INTRODUCTION OF NEW ENGINE ASSEMBLY PROCEDURES AND HARDWARE, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY ENGINE S/N // CHECKDATE 04 APR 2019 // WO CEIS-05/19 REV. 01
19-OCT-2018		MOS HRS/MSC - ENC AFL					
SB PW300-72-25273 R03	NO. 2 ENGINE - REPLACEMENT OF NO. 4 BEARING CARBON SEAL AND CARRIER(SUPERSEDED BY PW300-72-25273 R04), SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ESN
27-OCT-2008		MOS HRS/MSC - ENC		09-MAR-2019 5955:36 5506			
SB PW300-72-25273 R04	NO. 2 ENGINE - REPLACEMENT OF NO. 4 BEARING CARBON SEAL AND CARRIER, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - BY ENGINE SERIAL NUMBER - FACTORY EMBODIED
26-AUG-2010		MOS HRS/MSC A/R ENC					
SB PW300-72-25274 R01	NO. 2 ENGINE - REPLACEMENT OF UPPER AND LOWER BYPASS DUCT ASSEMBLIES, FUEL NOZZLE COVER AND EXCITER MOUNTING BRACKET, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - N/A BY ENGINE SERIAL NUMBER
15-SEP-2008		MOS HRS/MSC - ENC		19-MAR-2013 2491:42 2781			
SB PW300-72-25274 R02	NO. 2 ENGINE - REPLACEMENT OF UPPER AND LOWER BYPASS DUCT ASSEMBLIES, FUEL NOZZLE COVER AND EXCITER MOUNTING BRACKET, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - SN ENGINE NOT Affected // CHECKDATE 04 JAN 2024 // WO CEIS-03/24
08-NOV-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25275	NO. 2 ENGINE - T4.5 TRIM ADJUSTMENT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO ESN
17-NOV-2005		MOS HRS/MSC - ENC		09-MAR-2019 5955:36 5506			
SB PW300-72-25276 R01	NO. 2 ENGINE - INSPECTION OF PREFORMED PACKING ON FUEL AND OIL FILTERS, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO ESN
23-DEC-2005		MOS HRS/MSC - ENC		09-MAR-2019 5955:36 5506			
SB PW300-72-25277	NO. 2 ENGINE - NO.1 BEARING SEAL RUNNER - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ESN
16-NOV-2005		MOS HRS/MSC - ENC		09-MAR-2019 5955:36 5506			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25280 R01	NO. 2 ENGINE - INSPECTION OF HIGH PRESSURE TURBINE RETAINING NUT, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH
26-FEB-2008		MOS		09-MAR-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25281 R02	NO. 2 ENGINE - INSPECTION/ASSEMBLY OF OIL FILLER NECK ASSEMBLY, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO ESN
16-MAR-2012		MOS		09-MAR-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25283 R02	NO. 2 ENGINE - REPLACEMENT OF CORE COWL SUPPORT BRACKETS, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE - DUE TO ESN
17-JAN-2007		MOS		09-MAR-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25284 R03	NO. 2 ENGINE - REPLACEMENT OF MAGNETIC SEAL ASSEMBLIES, SERVICE BULLETIN					CATEGORY 7	
12-FEB-2016		MOS					
		HRS/MSC	-				
		ENC					
SB PW300-72-25292	NO. 2 ENGINE - T4.5 TRIM ADJUSTMENT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO ESN
		MOS		09-MAR-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25296	NO. 2 ENGINE - REPLACEMENT OF OIL VENT TUBE RETAINING BOLT, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ESN
22-SEP-2006		MOS		09-MAR-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25304	NO. 2 ENGINE - INTRODUCTION OF NEW OIL TANK VENT TUBE GASKET, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ESN
22-JAN-2007		MOS		09-MAR-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25305	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR ROTOR BALANCING ASSEMBLY FLANGE BOLTS, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ESN
19-JAN-2007		MOS		09-MAR-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25306	NO. 2 ENGINE - REPLACEMENT OF HIGH PRESSURE COMPRESSOR (HPC) TIE SHAFT RETAINING NUT, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ESN
17-AUG-2007		MOS		09-MAR-2019			
		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25307	NO. 2 ENGINE - T4.5 TRIM ADJUSTMENT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO ESN
12-DEC-2006		MOS		09-MAR-2019			
		HRS/MSC	BF/F	5955:36			
		ENC		5506			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25309 R03	NO. 2 ENGINE - REPLACEMENT OF PRIMARY FUEL NOZZLE (SUPERSEDED BY PW300-72-25309 R04), SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - BY ENGINE SERIAL NUMBER - FACTORY EMBODIED
		MOS HRS/MSC ENC	05-MAY-2010	A/R			
SB PW300-72-25309 R04	NO. 2 ENGINE - REPLACEMENT OF PRIMARY FUEL NOZZLE, SERVICE BULLETIN			MOS HRS/MSC ENC	09-MAR-2019 5955:36 5506	CATEGORY 6	NOT APPLICABLE - DUE TO ESN
			23-JAN-2018				
SB PW300-72-25311 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF PRIMARY FUEL NOZZLE ASSEMBLY, SERVICE BULLETIN			MOS HRS/MSC ENC AFL		CATEGORY 7	NOT APPLICABLE - ENGINE S/N // CHECKDATE 25 JUN 2018 // WO CEIS-11/18
			15-JUN-2018				
SB PW300-72-25312 R01	NO. 2 ENGINE - CONVERSION OF PW306A BUILD SPECIFICATION 853 TO 1241 OR CONVERSION OF PW306C BUILD SPECIFICATION 1026 TO 1240 (PROGRESSIVE MAINTENANCE PROGRAM) (SUPERSEDED BY PW300-72-25312 R02), SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE - N/A BY EFFECTIVITY
		MOS HRS/MSC ENC	30-SEP-2009		19-MAR-2013 2491:42 2781		
SB PW300-72-25312 R02	NO. 2 ENGINE - CONVERSION OF PW306A BUILD SPECIFICATION 853 TO 1241 OR CONVERSION OF PW306C BUILD SPECIFICATION 1026 TO 1240 (PROGRESSIVE MAINTENANCE PROGRAM), SERVICE BULLETIN			MOS HRS/MSC ENC		CATEGORY 8	NOT APPLICABLE - REFER TO R1 OF THIS SB
			23-MAR-2015				
SB PW300-72-25312 R03	NO. 2 ENGINE - CONVERSION OF PW306A BUILD SPECIFICATION 853 TO 1241 OR CONVERSION OF PW306C BUILD SPECIFICATION 1026 TO 1240 (PROGRESSIVE MAINTENANCE PROGRAM), SERVICE BULLETIN			MOS HRS/MSC ENC AFL		CATEGORY 8	NOT APPLICABLE - N/A SB IS ONLY FOR ENGINES OPERATED BY NETJETS AVIATION INC // CHECKDATE 27 APR 2021 // WO CEIS-07/21
			18-FEB-2021				
SB PW300-72-25312 R03 PART A	NO. 2 ENGINE - ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF IDENTIFICATION PLATE (A NEW ENGINE BUILD SPECIFICATION (BS1241) FOR THE PW306A AND BUILD SPECIFICATION (BS1240) FOR THE PW306C, ARE INTRODUCED TO DISTINGUISH ENGINES ELIGIBLE FOR ENROLLMENT INTO THE NETJETS PROGRESSIVE MAINTENANCE PROGRAM)			MOS HRS/MSC ENC AFL		CATEGORY 8	NOT APPLICABLE - N/A SB IS ONLY FOR ENGINES OPERATED BY NETJETS AVIATION INC // CHECKDATE 27 APR 2021 // WO CEIS-07/21
			18-FEB-2021				
SB PW300-72-25312 R03 PART B	NO. 2 ENGINE - ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF IDENTIFICATION PLATE (FOR ENGINES THAT ARE NO LONGER INCLUDED WITHIN THE NETJETS PROGRESSIVE MAINTENANCE PROGRAM, THE POST-SB25312 REFERENCE DATA PLATE WITH ENGINE BUILD SPECIFICATION (BS1241 FOR THE PW306A OR BS1240 FOR THE PW306C) IS REMOVED AND REPLACED WITH A NEW DATA PLATE REFERENCING THE ORIGINAL ENGINE BUILD SPECIFICATION (BS853 FOR THE PW306A OR BS1026 FOR THE PW306C))			MOS HRS/MSC ENC AFL		CATEGORY 8	NOT APPLICABLE - N/A SB IS ONLY FOR ENGINES OPERATED BY NETJETS AVIATION INC // CHECKDATE 27 APR 2021 // WO CEIS-07/21
			18-FEB-2021				

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25313	NO. 2 ENGINE - T4.5 TRIM ADJUSTMENT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO ESN
29-MAR-2007	MOS HRS/MSC - ENC			09-MAR-2019 5955:36 5506			
SB PW300-72-25317	NO. 2 ENGINE - REPLACEMENT OF TAIL FAIRING BOLTS, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 6	NOT APPLICABLE - DUE TO ESN
04-JUN-2007							
SB PW300-72-25318 R01	NO. 2 ENGINE - INTRODUCTION OF NEW FUEL/OIL HEAT EXCHANGER (FOHE), SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 5	NOT APPLICABLE - DUE TO ESN
18-AUG-2008							
SB PW300-72-25320	NO. 2 ENGINE - MODIFICATION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL UNIT (HMU), SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 7	COMPLIED WITH
10-OCT-2007							
SB PW300-72-25321 R02	NO. 2 ENGINE - MODIFICATION/REPLACEMENT OF ALTERNATOR SPUR GEARSHAFT ASYO, SERVICE BULLETIN			MOS HRS/MSC A/R ENC	04-MAR-2010 1077:06 1187	CATEGORY 6	COMPLIED WITH
30-OCT-2009							
SB PW300-72-25323	NO. 2 ENGINE - HIGH PRESSURE TURBINE SHROUD AIR SEAL - REPLACEMENT OF, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 7	COMPLIED WITH
23-OCT-2007							
SB PW300-72-25325 R02	NO. 2 ENGINE - REPLACEMENT OF HIGH-PRESSURE COMPRESSOR-CASE BOLTS, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
19-FEB-2008							
SB PW300-72-25326 R01	NO. 2 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN			MOS HRS/MSC A/R ENC	09-MAR-2019 5955:36 5506	CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
31-MAR-2011							
SB PW300-72-25327 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX GEARSHAFTS, SERVICE BULLETIN			MOS HRS/MSC - ENC	09-MAR-2019 5955:36 5506	CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
14-JAN-2008							
SB PW300-72-25328 R01	NO. 2 ENGINE - INTRODUCTION / REPLACEMENT OF CARBON FACE SEALS, SERVICE BULLETIN			MOS HRS/MSC - ENC	19-MAR-2013 2491:42 2781		NOT APPLICABLE - NOT CONCERNED
05-MAY-2008							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25331 R01	NO. 2 ENGINE - REPLACEMENT OF FAN HUB SET, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
04-DEC-2012		MOS HRS/MSC - ENC					
SB PW300-72-25332	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF FUEL START AND DUMP VALVE, SERVICE BULLETIN				09-MAR-2019 5955:36 5506	CATEGORY 6	COMPLIED WITH
23-JAN-2008		MOS HRS/MSC - ENC					
SB PW300-72-25333	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF HIGH PRESSURE COMPRESSOR CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER . DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
06-MAR-2008		MOS HRS/MSC - ENC					
SB PW300-72-25335	NO. 2 ENGINE - FAN HUB RETAINING NUT AND WASHER - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
13-MAY-2008		MOS HRS/MSC - ENC					
SB PW300-72-25337	NO. 2 ENGINE - INTRODUCTION OF LPT ROTOR & STATOR ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
15-JUL-2008		MOS HRS/MSC - ENC					
SB PW300-72-25338	NO. 2 ENGINE - REPLACEMENT OF FUEL WASTE EJECTOR, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
23-JUN-2008		MOS HRS/MSC - ENC					
SB PW300-72-25339	NO. 2 ENGINE - REPLACEMENT/INTRODUCTION OF SELF-LOCKING NUTS AND CAP SCREWS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
10-JUL-2008		MOS HRS/MSC - ENC					
SB PW300-72-25340	NO. 2 ENGINE - REPLACEMENT OF P2.8 AND P3 AIR TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
17-JUN-2008		MOS HRS/MSC - ENC		09-MAR-2019 5955:36 5506			
SB PW300-72-25341	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF HIGH PRESSURE TURBINE DISK ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
27-MAY-2008		MOS HRS/MSC - ENC		09-MAR-2019 5955:36 5506			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25342	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
24-NOV-2008		MOS HRS/MSC ENC	A/R	04-MAR-2010 1077:06 1187			
SB PW300-72-25344	NO. 2 ENGINE - REPLACEMENT OF N1 SPEED SENSOR, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
02-SEP-2008		MOS HRS/MSC ENC	-				
SB PW300-72-25345	NO. 2 ENGINE - REPLACEMENT OF HIGH PRESSURE TURBINE (HPT) SLEEVE SPACER, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
28-NOV-2008		MOS HRS/MSC ENC	-				
SB PW300-72-25345 R01	NO. 2 ENGINE - REPLACEMENT OF HIGH PRESSURE TURBINE (HPT) SLEEVE SPACER, SERVICE BULLETIN					CATEGORY 7	
13-JAN-2021		MOS HRS/MSC ENC AFL	-				
SB PW300-72-25346	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX (AGB) BREather TUBE ADAPTER GASKET (SUPERSEDED BY PW300-72-25346 R01), SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
21-NOV-2008		MOS HRS/MSC ENC	-				
SB PW300-72-25346 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX (AGB) BREather TUBE ADAPTER GASKET, SERVICE BULLETIN					CATEGORY 7	
28-AUG-2018		MOS HRS/MSC ENC AFL	-				
SB PW300-72-25347 R01	NO. 2 ENGINE - REPLACEMENT OF STARTER GENERATOR DRIVE SPUR GEARSHAFT (SUPERSEDED BY PW300-72-25347 R02), SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
25-FEB-2013		MOS HRS/MSC ENC	-	09-MAR-2019 5955:36 5506			
SB PW300-72-25347 R02	NO. 2 ENGINE - REPLACEMENT OF STARTER GENERATOR DRIVE SPUR GEARSHAFT, SERVICE BULLETIN					CATEGORY 6	- REFER TO R1 OF THIS SB
10-JUL-2015		MOS HRS/MSC ENC	-				
SB PW300-72-25348	NO. 2 ENGINE - REPLACEMENT OF ANTI-ICING TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
02-DEC-2008		MOS HRS/MSC ENC	-				

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25348 R01	NO. 2 ENGINE - REPLACEMENT OF ANTI-ICING TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
09-DEC-2020		MOS HRS/MSC - ENC AFL					
SB PW300-72-25352	NO. 2 ENGINE - REPLACEMENT OF PREFORMED PACKINGS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
23-MAR-2009		MOS HRS/MSC - ENC					
SB PW300-72-25352 R01	NO. 2 ENGINE - SB PW300-72-25352 R01 - REPLACEMENT OF PREFORMED PACKINGS, SERVICE BULLETIN				12055:36 M	CATEGORY 6	
22-OCT-2024		MOS HRS/MSC - ENC AFL					
SB PW300-72-25353 R04	NO. 2 ENGINE - REPLACEMENT OF ALTERNATOR AND STARTER SEALS (SUPERSEDED BY PW300-72-25353 R05), SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH - SB PERFORMED BY P&W SEE S/O 122040 TSN 1077.1 CSN 1187
		MOS HRS/MSC A/R ENC					
SB PW300-72-25353 R05	NO. 2 ENGINE - REPLACEMENT OF ALTERNATOR AND STARTER SEALS, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH - PREVIOUSLY
05-FEB-2013		MOS HRS/MSC - ENC		09-MAR-2019 5955:36 5506			
SB PW300-72-25354 R01	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF PRIMARY FUEL NOZZLES, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - N/A BY ENGINE SERIAL NUMBER
16-JUN-2010		MOS HRS/MSC - ENC		19-MAR-2013 2491:42 2781			
SB PW300-72-25355	NO. 2 ENGINE - REPLACEMENT OF HIGH PRESSURE TURBINE SHROUD SEALS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
27-OCT-2009		MOS HRS/MSC - ENC					
SB PW300-72-25356	NO. 2 ENGINE - REPLACEMENT OF NO.1 BEARING COVER AND HOUSING ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
21-OCT-2009		MOS HRS/MSC - ENC					
SB PW300-72-25357	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX (AGB) MOUNTING PLATES AND ENGINE MOUNT PAD COVER BOLTS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PART IS FULLY USED
24-SEP-2009		MOS HRS/MSC - ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25359 R01	NO. 2 ENGINE - REPLACEMENT OF VARIOUS COMPONENT ASSEMBLIES, BOLTS, BRACKETS (SUPERSEDED BY PW300-72-25359 R02), SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
03-MAY-2010		MOS HRS/MSC ENC	A/R				
SB PW300-72-25359 R02	NO. 2 ENGINE - REPLACEMENT OF - VARIOUS COMPONENT ASSEMBLIES, BOLTS, BRACKETS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
09-JUL-2012		MOS HRS/MSC ENC	-				
SB PW300-72-25360 R01	NO. 2 ENGINE - REPLACEMENT OF FUEL WASTE EJECTOR, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
06-MAY-2010		MOS HRS/MSC ENC	A/R				
SB PW300-72-25361	NO. 2 ENGINE - AIR TRANSFER TUBES - REPLACEMENT OF (SUPERSEDED BY PW300-72-25361 R01), SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
01-MAR-2011		MOS HRS/MSC ENC	A/R				
SB PW300-72-25361 R01	NO. 2 ENGINE - AIR TRANSFER TUBES - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
14-DEC-2011		MOS HRS/MSC ENC	A/R	09-MAR-2019 5955:36 5506			
SB PW300-72-25362	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR BLEED SOLENOID VALVE, SERVICE BULLETIN					CATEGORY 8	- SB OPTIONAL NOT PERFORMED. NOT REQUESTED BY THE CUSTOMER.
14-MAY-2010		MOS HRS/MSC ENC	A/R				
SB PW300-72-25363	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF LOWER HALF BY-PASS DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
10-MAY-2010		MOS HRS/MSC ENC	A/R				
SB PW300-72-25368	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY AND DIFFUSER EXIT DUCT (SUPERSEDED BY PW300-72-25368 R01), SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
16-JUN-2010		MOS HRS/MSC ENC	A/R				

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25368 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY AND DIFFUSER EXIT DUCT (SUPERSEDED BY PW300-72-25368 R02), SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
04-AUG-2011		MOS HRS/MSC - ENC					
SB PW300-72-25368 R02	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY AND DIFFUSER EXIT DUCT, SERVICE BULLETIN					CATEGORY 7	- REFER TO R1 OF THIS SB
23-MAY-2014		MOS HRS/MSC - ENC					
SB PW300-72-25369	NO. 2 ENGINE - REPLACEMENT OF SPEED SENSOR WIRING HARNESS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
14-JUN-2010		MOS HRS/MSC A/R ENC					
SB PW300-72-25370	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF NO. 1 BEARING HOUSING ASSEMBLY (SUPERSEDED BY PW300-72-25370 R01), SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
28-OCT-2011		MOS HRS/MSC - ENC					
SB PW300-72-25370 R01	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF NO. 1 BEARING HOUSING ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
01-FEB-2016		MOS HRS/MSC - ENC					
SB PW300-72-25371	NO. 2 ENGINE - INTERSHAFT OIL SEALS - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
28-SEP-2010		MOS HRS/MSC A/R ENC		09-MAR-2019 5955:36 5506			
SB PW300-72-25372	NO. 2 ENGINE - METAL GASKET - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
28-SEP-2010		MOS HRS/MSC A/R ENC		09-MAR-2019 5955:36 5506			
SB PW300-72-25373	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF NO. 3 & 4 BEARING SCAVENGE PUMP HOUSING ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
28-OCT-2010		MOS HRS/MSC A/R ENC					
SB PW300-72-25374	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF FUEL NOZZLES (SUPERSEDED BY PW300-72-25374 R01), SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
26-NOV-2010		MOS HRS/MSC - ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25374 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF FUEL NOZZLES, SERVICE BULLETIN					CATEGORY 7	- REFER TO ORIGINAL OF THIS SB
06-FEB-2015		MOS HRS/MSC - ENC					
SB PW300-72-25375	NO. 2 ENGINE - REPLACEMENT OF SAFETY WIRE, SERVICE BULLETIN					CATEGORY 8	DECLINED - SB OPTIONAL NOT PERFORMED. NOT REQUESTED BY THE CUSTOMER.
15-DEC-2010		MOS HRS/MSC A/R ENC					
SB PW300-72-25376	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF COMPRESSOR BLEED SOLENOID VALVE, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
21-JUN-2011		MOS HRS/MSC A/R ENC					
SB PW300-72-25377	NO. 2 ENGINE - INSPECTION OF DAMPER SEAL INSTALLATION ON TURBINE ROTOR AIR SEAL, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE - BY ENGINE SERIAL NUMBER
04-OCT-2011		MOS HRS/MSC A/R ENC					
SB PW300-72-25378	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF LOWER BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW300-72-25378 R01), SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
		MOS HRS/MSC A/R ENC					
SB PW300-72-25378 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF LOWER BY-PASS DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
02-NOV-2012		MOS HRS/MSC - ENC					
SB PW300-72-25379	NO. 2 ENGINE - REPLACEMENT OF OUTER UPPER AND LOWER HALF BYPASS DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
31-OCT-2011		MOS HRS/MSC A/R ENC					
SB PW300-72-25380 R01	NO. 2 ENGINE - REVISED TRIM VALUES FOR PW306C ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW300-72-25380 R02), SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - SB 72-25380 R1 - NO. 2 ENGINE - REVISED TRIM VALUES FOR PW306C ELECTRONIC ENGINE CONTROL (EEC) COMPLIED WITH.
09-NOV-2011		MOS HRS/MSC - ENC		13-AUG-2012 2254:30 2517			
SB PW300-72-25380 R02	NO. 2 ENGINE - REVISED TRIM VALUES FOR PW306C ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - ORIGINAL REVISION 1 OF THIS SB
16-DEC-2015		MOS HRS/MSC - ENC		09-FEB-2017 4721:48 4594			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25381	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX COVER ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
23-NOV-2012		MOS HRS/MSC - ENC					
SB PW300-72-25383	NO. 2 ENGINE - REPLACEMENT OF REAR LOWER BY-PASS DUCT FAIRING, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
02-DEC-2011		MOS HRS/MSC A/R ENC					
SB PW300-72-25384	NO. 2 ENGINE - REPLACEMENT OF BY-PASS DUCT SEGMENTS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
02-DEC-2011		MOS HRS/MSC A/R ENC					
SB PW300-72-25385	NO. 2 ENGINE - REPLACEMENT OF BY-PASS DUCT FAIRINGS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
08-MAY-2012		MOS HRS/MSC - ENC					
SB PW300-72-25386	NO. 2 ENGINE - REPLACEMENT OF FIRST STAGE VANE ACTUATOR RING SET, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
10-JUL-2012		MOS HRS/MSC - ENC					
SB PW300-72-25387	NO. 2 ENGINE - REPLACEMENT OF FUEL NOZZLE (SUPERSEDED BY PW300-72-25387 R01), SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
17-SEP-2012		MOS HRS/MSC - ENC					
SB PW300-72-25387 R01	NO. 2 ENGINE - REPLACEMENT OF FUEL NOZZLE, SERVICE BULLETIN					CATEGORY 7	- REFER TO ORIGINAL OF THIS SB
30-JAN-2015		MOS HRS/MSC - ENC					
SB PW300-72-25388	NO. 2 ENGINE - REPLACEMENT OF N1 AND N2 SPEED SENSORS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
16-AUG-2012		MOS HRS/MSC - ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25389	NO. 2 ENGINE - REPLACEMENT OF HIGH PRESSURE COMPRESSOR CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
10-OCT-2012		MOS HRS/MSC - ENC					
SB PW300-72-25390	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE, SERVICE BULLETIN					CATEGORY 7	
28-JUN-2013		MOS HRS/MSC - ENC					
SB PW300-72-25391	NO. 2 ENGINE - REPLACEMENT OF SPEED SENSOR WIRING HARNESS, SERVICE BULLETIN					CATEGORY 7	- TO BE PROPOSED TO THE CUSTOMER. DO THIS SERVICE BULLETIN WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED.
14-FEB-2013		MOS HRS/MSC - ENC					
SB PW300-72-25395	NO. 2 ENGINE - REPLACEMENT OF ALTERNATOR AND STARTER SEALS (SUPERSEDED BY PW300-72-25395 R01), SERVICE BULLETIN						
18-SEP-2013		MOS HRS/MSC - ENC					
SB PW300-72-25395 R01	NO. 2 ENGINE - REPLACEMENT OF ALTERNATOR AND STARTER SEALS, SERVICE BULLETIN						
23-MAY-2014		MOS HRS/MSC - ENC					
SB PW300-72-25395 R02	NO. 2 ENGINE - REPLACEMENT OF ALTERNATOR AND STARTER SEALS (SUPERSEDED BY SB PW300-72-25395 R02), SERVICE BULLETIN					CATEGORY 10	
01-OCT-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25397	NO. 2 ENGINE - REPAIR/MODIFICATION OF ENGINE ELECTRONIC CONTROL (EEC), SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH - PREVIOUSLY
09-JAN-2014		MOS HRS/MSC - ENC		09-MAR-2019 5955:36 5506			
SB PW300-72-25398	NO. 2 ENGINE - REPLACEMENT OF NO. 2 BEARING REAR CARBON SEAL, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
15-JAN-2014		MOS HRS/MSC - ENC		09-MAR-2019 5955:36 5506			
SB PW300-72-25403	NO. 2 ENGINE - INTRODUCTION OF ACCESSORY GEARBOX SHAFT SHIELD (SUPERSEDED BY PW300-72-25403 R01), SERVICE BULLETIN					CATEGORY 6	
02-MAY-2014		MOS HRS/MSC - ENC					
SB PW300-72-25403 R01	NO. 2 ENGINE - INTRODUCTION OF ACCESSORY GEARBOX SHAFT SHIELD, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
14-MAY-2014		MOS HRS/MSC - ENC		09-MAR-2019 5955:36 5506			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25406	NO. 2 ENGINE - REPLACEMENT OF PROTECTIVE CAPS FOR ENGINE SHIPPING CONTAINER ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
		MOS					
23-JUN-2014		HRS/MSC	-				
		ENC					
SB PW300-72-25408	NO. 2 ENGINE - REPLACEMENT OF TRANSFER TUBE AND PREFORMED PACKINGS (SUPERSEDED BY PW300-72-25408 R01), SERVICE BULLETIN				CATEGORY 6		
		MOS					
22-JUL-2014		HRS/MSC	-				
		ENC					
SB PW300-72-25408 R01	NO. 2 ENGINE - REPLACEMENT OF TRANSFER TUBE AND PREFORMED PACKINGS (SUPERSEDED BY PW300-72-25408 R02), SERVICE BULLETIN				CATEGORY 6		
		MOS					
22-OCT-2014		HRS/MSC	-				
		ENC					
SB PW300-72-25408 R02	NO. 2 ENGINE - REPLACEMENT OF TRANSFER TUBE AND PREFORMED PACKINGS, SERVICE BULLETIN				CATEGORY 6	COMPLIED WITH	
		MOS		09-MAR-2019			
04-DEC-2014		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25409	NO. 2 ENGINE - RELOCATION OF OIL FILLER NECK VENT TUBE SUPPORT BRACKET, SERVICE BULLETIN				CATEGORY 6	COMPLIED WITH	
		MOS		09-MAR-2019			
29-JUL-2014		HRS/MSC	-	5955:36			
		ENC		5506			
SB PW300-72-25410	NO. 2 ENGINE - REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT (SUPERSEDED BY PW300-72-25410 R01), SERVICE BULLETIN				CATEGORY 7		
		MOS					
27-JAN-2015		HRS/MSC	-				
		ENC					
SB PW300-72-25410 R01	NO. 2 ENGINE - REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT, SERVICE BULLETIN				CATEGORY 7		
		MOS					
07-JAN-2016		HRS/MSC	-				
		ENC					
SB PW300-72-25411	NO. 2 ENGINE - REPLACEMENT OF ELECTRONIC ENGINE CONTROL (SUPERSEDED BY PW300-72-25411 R01), SERVICE BULLETIN				CATEGORY 7		
		MOS					
09-FEB-2015		HRS/MSC	-				
		ENC					
SB PW300-72-25411 R01	NO. 2 ENGINE - REPLACEMENT OF ELECTRONIC ENGINE CONTROL, SERVICE BULLETIN				CATEGORY 7		
		MOS					
03-NOV-2015		HRS/MSC	-				
		ENC					
SB PW300-72-25412	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT (SUPERSEDED BY PW300-72-25412 R01), SERVICE BULLETIN				CATEGORY 7		
		MOS					
05-MAR-2015		HRS/MSC	-				
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25412 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT (SUPERSEDED BY PW300-72-25412 R02), SERVICE BULLETIN					CATEGORY 7	
28-APR-2015		MOS HRS/MSC - ENC					
SB PW300-72-25412 R02	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT (SUPERSEDED BY PW300-72-25412 R03), SERVICE BULLETIN					CATEGORY 7	
10-NOV-2015		MOS HRS/MSC - ENC					
SB PW300-72-25412 R03	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT (SUPERSEDED BY PW300-72-25412 R04), SERVICE BULLETIN					CATEGORY 7	
13-NOV-2015		MOS HRS/MSC - ENC					
SB PW300-72-25412 R04	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT, SERVICE BULLETIN					CATEGORY 7	
18-MAR-2016		MOS HRS/MSC - ENC					
SB PW300-72-25412 R05	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL AND ENGINE DIAGNOSTIC UNIT, SERVICE BULLETIN					CATEGORY 7	
21-JUL-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25413 R01	NO. 2 ENGINE - REPLACEMENT OF FIFTH STAGE LOW PRESSURE TURBINE DISK, SERVICE BULLETIN					CATEGORY 9	
22-JUN-2015		MOS HRS/MSC - ENC					
SB PW300-72-25415	NO. 2 ENGINE - REPLACEMENT OF NO. 2 BEARING OIL NOZZLE, SERVICE BULLETIN					CATEGORY 7	
29-MAY-2015		MOS HRS/MSC - ENC					
SB PW300-72-25417	NO. 2 ENGINE - REPLACEMENT OF HIGH PRESSURE TURBINE VANE INNER SUPPORT, SERVICE BULLETIN					CATEGORY 7	
29-MAY-2015		MOS HRS/MSC - ENC					
SB PW300-72-25420	NO. 2 ENGINE - CONVERSION OF PW306C (BS1026) ENGINE TO PW306D (BS1298) ENGINE CONFIGURATION, SERVICE BULLETIN					CATEGORY 8	
04-DEC-2015		MOS HRS/MSC - ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25420 R01	NO. 2 ENGINE - CONVERSION OF PW306C (BS1026) ENGINE TO PW306D (BS1298) ENGINE CONFIGURATION, SERVICE BULLETIN				CATEGORY 8		
26-MAR-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25420 R02	NO. 2 ENGINE - CONVERSION OF PW306C (BS1026) ENGINE TO PW306D (BS1298) ENGINE CONFIGURATION, SERVICE BULLETIN				CATEGORY 8		
15-OCT-2021		MOS HRS/MSC - ENC AFL					
SB PW300-72-25421	NO. 2 ENGINE - REPLACEMENT OF NO. 1 BEARING CARBON AIR SEAL, SERVICE BULLETIN					CATEGORY 9	COMPLIED WITH
13-NOV-2015		MOS HRS/MSC - ENC		09-MAR-2019 5955:36 5506			
SB PW300-72-25425	NO. 2 ENGINE - REPLACEMENT OF HIGH PRESSURE COMPRESSOR STATOR ASSEMBLY (SUPERSEDED BY PW300-72-25425 R01), SERVICE BULLETIN				CATEGORY 6		
16-MAY-2016		MOS HRS/MSC - ENC					
SB PW300-72-25425 R01	NO. 2 ENGINE - REPLACEMENT OF HIGH PRESSURE COMPRESSOR STATOR ASSEMBLY, SERVICE BULLETIN				CATEGORY 6	COMPLIED WITH	
04-JUN-2017		MOS HRS/MSC - ENC		09-MAR-2019 5955:36 5506			
SB PW300-72-25431	NO. 2 ENGINE - INTRODUCTION OF LOW PRESSURE TURBINE (LPT) THIRD-STAGE VANE ASSEMBLY OUTER AIR SEAL RING (SUPERSEDED BY PW300-72-25431 R01), SERVICE BULLETIN				CATEGORY 9		
13-FEB-2017		MOS HRS/MSC - ENC					
SB PW300-72-25431 R01	NO. 2 ENGINE - INTRODUCTION OF LOW PRESSURE TURBINE (LPT) THIRD-STAGE VANE ASSEMBLY OUTER AIR SEAL RING, SERVICE BULLETIN				CATEGORY 9		
13-APR-2017		MOS HRS/MSC - ENC					
SB PW300-72-25433	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS (SUPERSEDED BY PW300-72-25433 R01), SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH	
13-FEB-2017		MOS HRS/MSC - ENC		10-AUG-2018 5789:15 5372			
SB PW300-72-25433 R01	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH	
07-JUN-2018		MOS HRS/MSC - ENC		10-AUG-2018 5789:15 5372			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25433 R02	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - PREVIOUS REVISION 1 ON 10 AUG 2018 AT 5789:15 HRS AND 5372 CYCLS - REVISION 2 HAS NO AFFECT ON PRIOR ACCOMPLISHMENT // CHECKDATE 17 AUG 2022 // WO CEIS-07/22
28-JUN-2022		MOS HRS/MSC - ENC AFL					
SB PW300-72-25434	NO. 2 ENGINE - INSPECTION OF OUTER BYPASS DUCT LOWER FAIRING, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY ENGINE S/N
26-APR-2017		MOS HRS/MSC - ENC		23-JAN-2018 5426:01 5094			
SB PW300-72-25434 R01	NO. 2 ENGINE - INSPECTION OF OUTER BYPASS DUCT LOWER FAIRING, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - SN ENGINE NOT AFFECTED // CHECKDATE 17 AUG 2022 // WO CEIS-07/22
28-JUN-2022		MOS HRS/MSC - ENC AFL					
SB PW300-72-25435 R01	NO. 2 ENGINE - REPLACEMENT OF PRESSURE AND TEMPERATURE SENSORS, SERVICE BULLETIN					CATEGORY 7	
29-MAY-2017		MOS HRS/MSC - ENC					
SB PW300-72-25436	NO. 2 ENGINE - INTRODUCTION OF ADD SEALANT, SERVICE BULLETIN					CATEGORY 6	
29-MAY-2017		MOS HRS/MSC - ENC					
SB PW300-72-25436 R01	NO. 2 ENGINE - INTRODUCTION OF ADD SEALANT, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - BULLETIN PERFORMED BY MTU MAINTENANCE BERLIN-BRANDENBURG GMBH. FOR MORE DETAILS REFER TO EASA FORM 1 D034/24 AND MTU WO 4500002493.
05-FEB-2019		MOS HRS/MSC - ENC		12-DEC-2024 9092:25 7785			
SB PW300-72-25440	NO. 2 ENGINE - REPLACEMENT OF WIRING HARNESS PREFORMED PACKING, SERVICE BULLETIN					CATEGORY 9	
16-NOV-2017		MOS HRS/MSC - ENC					
SB PW300-72-25441	NO. 2 ENGINE - INTRODUCTION OF TURBINE EXHAUST CASE ASSEMBLY OPTION (IC), SERVICE BULLETIN					CATEGORY 9	
16-MAY-2018		MOS HRS/MSC - ENC AFL					
SB PW300-72-25444	NO. 2 ENGINE - REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW300-72-25444 R01), SERVICE BULLETIN					CATEGORY 8	
27-AUG-2018		MOS HRS/MSC - ENC AFL					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25444 R01	NO. 2 ENGINE - REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	
01-OCT-2018		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25444 R02	NO. 2 ENGINE - REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	
15-NOV-2018		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25444 R03	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	
06-FEB-2019		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25446	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	
11-DEC-2018		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25446 R01	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	
10-JAN-2019		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25446 R02	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	
14-FEB-2019		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25446 R03	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	
04-MAR-2019		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25446 R04	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF LOWER HALF BYPASS DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	
25-JUN-2019		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25446 R05	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF LOWER-HALF BYPASS DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	
20-AUG-2019		MOS		01-FEB-2008			
		HRS/MSC	-	0	12055:36 M		
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25447	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE, SERVICE BULLETIN					CATEGORY 7	
08-JAN-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25447 R01	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE, SERVICE BULLETIN					CATEGORY 7	
22-JAN-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25447 R02	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE, SERVICE BULLETIN					CATEGORY 7	
11-FEB-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25447 R03	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE, SERVICE BULLETIN					CATEGORY 7	
10-JUL-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25447 R04	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF SECOND STAGE HIGH PRESSURE TURBINE BLADE, SERVICE BULLETIN					CATEGORY 7	
24-NOV-2020		MOS HRS/MSC - ENC AFL					
SB PW300-72-25450	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR, SERVICE BULLETIN					CATEGORY 7	
10-JAN-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25450 R01	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR, SERVICE BULLETIN					CATEGORY 7	
21-JAN-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25450 R02	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR, SERVICE BULLETIN					CATEGORY 7	
05-FEB-2019		MOS HRS/MSC - ENC AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25450 R03	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR, SERVICE BULLETIN					CATEGORY 7	
01-DEC-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25450 R04	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR, SERVICE BULLETIN					CATEGORY 7	
06-MAR-2025		MOS HRS/MSC - ENC					
SB PW300-72-25451	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN					CATEGORY 7	
27-AUG-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25451 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN					CATEGORY 7	
06-APR-2020		MOS HRS/MSC - ENC AFL					
SB PW300-72-25451 R02	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN					CATEGORY 7	
13-NOV-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25452	NO. 2 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
16-SEP-2019		MOS HRS/MSC - ENC AFL					
SB PW300-72-25452 R01	NO. 2 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
05-FEB-2020		MOS HRS/MSC - ENC AFL					
SB PW300-72-25452 R02	NO. 2 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
18-FEB-2020		MOS HRS/MSC - ENC AFL					
SB PW300-72-25452 R03	NO. 2 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
19-MAR-2020		MOS HRS/MSC - ENC AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25452 R04	NO. 2 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
08-JUL-2020		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25452 R05	NO. 2 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
28-AUG-2020		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25452 R06	NO. 2 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
26-MAY-2021		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25452 R07	NO. 2 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
24-JUN-2021		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25452 R08	NO. 2 ENGINE - REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
06-NOV-2023		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25453	NO. 2 ENGINE - REPLACEMENT OF OUTER COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
28-MAY-2019		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25457	NO. 2 ENGINE - REPLACEMENT OF FIRE DETECTOR BRACKET HINGED CLAMP, SERVICE BULLETIN					CATEGORY 9	
25-MAY-2020		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PW300-72-25459	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS, SERVICE BULLETIN					NOT APPLICABLE - N/A SB IS ONLY FOR ENGINES OPERATED BY NETJETS AVIATION INC // CHECKDATE 27 APR 2021 // WO CEIS-07/21	
15-JAN-2021		MOS					
		HRS/MSC	-				
		ENC					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25459 R01	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS, SERVICE BULLETIN						NOT APPLICABLE - N/A SB IS ONLY FOR ENGINES OPERATED BY NETJETS AVIATION INC // CHECKDATE 27 APR 2021 // WO CEIS-07/21
11-FEB-2021		MOS HRS/MSC - ENC AFL					
SB PW300-72-25459 R02	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH	
09-AUG-2023		MOS HRS/MSC - ENC		27-OCT-2023 8455:54 7327			
SB PW300-72-25459 R03	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX (AGB) ALTERNATOR AND STARTER SEALS, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - REVISION 02 OF THIS SB AT 27 OCT 2023 WITH 8455:54 HRS AND 7327 CYCLES. // CHECKDATE 21 OCT 2024 // WO CEIS-20/24	
19-AUG-2024		MOS HRS/MSC - ENC					
SB PW300-72-25460 R01	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN				CATEGORY 7		
22-FEB-2022		MOS HRS/MSC - ENC AFL					
SB PW300-72-25460 R02	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN				CATEGORY 7		
25-MAY-2022		MOS HRS/MSC - ENC AFL					
SB PW300-72-25460 R03	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN				CATEGORY 7		
28-JUN-2022		MOS HRS/MSC - ENC AFL					
SB PW300-72-25460 R04	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN				CATEGORY 7		
19-AUG-2022		MOS HRS/MSC - ENC AFL					
SB PW300-72-25460 R05	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN				CATEGORY 7		
13-SEP-2022		MOS HRS/MSC - ENC AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25460 R06	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
19-JAN-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25460 R07	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
24-OCT-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25460 R08	NO. 2 ENGINE - SB PW300-72-25460 R08 - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
28-NOV-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25460 R09	NO. 2 ENGINE - SB PW300-72-25460 R09 - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
28-MAR-2024		MOS HRS/MSC - ENC AFL					
SB PW300-72-25460 R10	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE HPT DISC ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - SERVICE BULLETIN PERFORMED BY MTU MAINTENANCE BERLIN-BRANDENBURG GMBH. FOR MORE DETAILS REFER TO EASA FORM 1 D034/24 AND MTU WO 4500002493.
07-MAY-2024		MOS HRS/MSC - ENC		12-DEC-2024 9092:25 7785			
SB PW300-72-25462	NO. 2 ENGINE - INSPECTION OF OUTER ELECTRICAL WIRING HARNESS, SERVICE BULLETIN					CATEGORY 4	COMPLIED WITH
22-SEP-2021		MOS HRS/MSC - ENC		17-NOV-2021 7490:26 6618			
SB PW300-72-25462 R01	NO. 2 ENGINE - INSPECTION OF OUTER ELECTRICAL WIRING HARNESS, SERVICE BULLETIN					CATEGORY 4	COMPLIED WITH - ORIGINAL REV. OF THIS SB 17 NOV 2021 AT 7490:26 HRS AND 6618 CYCLES. THIS REVISION HAS NO EFFECT ON ENGINES PREV. IN COMPLIANCE WITH THIS SERVICE DOC // CHECKDATE 22 JUN 2022 // WO CEIS-02/22
07-MAR-2022		MOS HRS/MSC - ENC AFL					
SB PW300-72-25463	NO. 2 ENGINE - REPLACEMENT OF TIE ROD RETAINING NUT, SERVICE BULLETIN					CATEGORY 7	
02-SEP-2022		MOS HRS/MSC - ENC AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25465	NO. 2 ENGINE - INSPECTION OF DUPLEX FUEL NOZZLE, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - SERVICE BULLETIN PERFORMED BY MTU MAINTENANCE BERLIN-BRANDENBURG GMBH. FOR MORE DETAILS REFER TO EASA FORM 1 D034/24 AND MTU WO 4500002493.
13-SEP-2022		MOS HRS/MSC - ENC		12-DEC-2024 9092:25 7785			
SB PW300-72-25466	NO. 2 ENGINE - REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
22-AUG-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25466 R01	NO. 2 ENGINE - REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
01-DEC-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25466 R02	NO. 2 ENGINE - REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
31-JAN-2025		MOS HRS/MSC - ENC					
SB PW300-72-25466 R03	NO. 2 ENGINE - REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
23-APR-2025		MOS HRS/MSC - ENC					
SB PW300-72-25467	NO. 2 ENGINE - REPLACEMENT OF DUPLEX FUEL NOZZLE, SERVICE BULLETIN					CATEGORY 7	
19-JAN-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25471	NO. 2 ENGINE - SB PW300-72-25471 - INSPECTION OF INLET GUIDE VANE ACTUATING ARM ASSY, SERVICE BULLETIN					CATEGORY 6	
29-MAR-2023		MOS HRS/MSC - ENC AFL					
SB PW300-72-25471 R01	NO. 2 ENGINE - SB PW300-72-25471 R01 - INSPECTION OF INLET GUIDE VANE ACTUATING ARM ASSY, SERVICE BULLETIN					CATEGORY 6	
14-MAR-2024		MOS HRS/MSC - ENC AFL		12055:36 M			
SB PW300-72-25475	NO. 2 ENGINE - REPLACEMENT OF INLET GUIDE VANE SHROUD SET, SERVICE BULLETIN					CATEGORY 7	
13-MAY-2024		MOS HRS/MSC - ENC AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-72-25475 R01	NO. 2 ENGINE - REPLACEMENT OF INLET GUIDE VANE SHROUD SET, SERVICE BULLETIN					CATEGORY 7	
19-JUL-2024		MOS HRS/MSC - ENC AFL					
SB PW300-72-25480	NO. 2 ENGINE - REPLACEMENT OF ACTUATOR SUPPORT-BRACKET, SERVICE BULLETIN					CATEGORY 7	
28-MAR-2025		MOS HRS/MSC - ENC					
SB PW300-73-25462 R02	NO. 2 ENGINE - INSPECTION OF OUTER ELECTRICAL WIRING HARNESS, SERVICE BULLETIN					CATEGORY 4	COMPLIED WITH - ORIGINAL REV. OF THIS SB 17 NOV 2021 AT 7490:26 HRS AND 6618 CYCLS. THIS REVISION HAS NO EFFECT ON ENGINES PREV. IN COMPLIANCE WITH THIS SB.
16-APR-2024		MOS HRS/MSC - ENC AFL					
SB PW300-75-25454	NO. 2 ENGINE - REPLACEMENT OF BLEED VALVE TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
24-OCT-2023		MOS HRS/MSC - ENC AFL					
SB PW300-75-25454 R01	NO. 2 ENGINE - REPLACEMENT OF BLEED VALVE TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
06-NOV-2023		MOS HRS/MSC - ENC AFL					
SB PW300-75-25454 R02	NO. 2 ENGINE - REPLACEMENT OF BLEED VALVE TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	
23-AUG-2024		MOS HRS/MSC - ENC AFL					
SB PW300-77-25474	NO. 2 ENGINE - REPLACEMENT / RE-IDENTIFICATION OF TC-T4.5 WIRING HARNESS, SERVICE BULLETIN					CATEGORY 7	
05-APR-2024		MOS HRS/MSC - ENC AFL					
SB PW300-77-25474 R01	NO. 2 ENGINE - REPLACEMENT/RE-IDENTIFICATION OF TC-T4.5 WIRING HARNESS, SERVICE BULLETIN					CATEGORY 7	
19-JUL-2024		MOS HRS/MSC - ENC AFL					
SB PW300-77-25474 R02	NO. 2 ENGINE - REPLACEMENT/RE-IDENTIFICATION OF TC-T4.5 WIRING HARNESS, SERVICE BULLETIN					CATEGORY 7	
26-AUG-2024		MOS HRS/MSC - ENC AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW300-77-25474 R03	NO. 2 ENGINE - REPLACEMENT/RE-IDENTIFICATION OF TC-T4.5 WIRING HARNESS, SERVICE BULLETIN					CATEGORY 7	
09-SEP-2024		MOS HRS/MSC - ENC AFL					
SIL GEN-153 R04	NO. 2 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R05), SERVICE INFORMATION LETTER					INFORMATIONAL	
05-MAY-2020		MOS HRS/MSC - ENC AFL					
SIL GEN-153 R05	NO. 2 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06), SERVICE INFORMATION LETTER					INFORMATIONAL	
28-SEP-2020		MOS HRS/MSC - ENC AFL					
SIL GEN-153 R06	NO. 2 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION, SERVICE INFORMATION LETTER					INFORMATIONAL	
30-OCT-2020		MOS HRS/MSC - ENC AFL					
SIL GEN-153 R07	NO. 2 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION, SERVICE INFORMATION LETTER					INFORMATIONAL	
05-JAN-2021		MOS HRS/MSC A/R ENC AFL					
SIL GEN-153 R08	NO. 2 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION, SERVICE INFORMATION LETTER					INFORMATIONAL	
15-SEP-2021		MOS HRS/MSC A/R ENC AFL					
SIL GEN-153 R09	NO. 2 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION, SERVICE INFORMATION LETTER					INFORMATIONAL	
18-JAN-2022		MOS HRS/MSC A/R ENC AFL					
SIL GEN-153 R10	NO. 2 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION, SERVICE INFORMATION LETTER					INFORMATIONAL	
31-OCT-2022		MOS HRS/MSC A/R ENC AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SPI 000003	NO. 2 ENGINE - POWERADVANTAGE+ CONTRACT TERMINATION, SPECIAL INSTRUCTION	MOS HRS/MSC ENC	36 1800	15-DEC-2024 9093:02	15-DEC-2027 10893:02	INFORMATIONAL RECURRING	