

OK-CAA CUSTOM  
AD REPORT

## Company

Owner: Airstream a.s.  
Operator: Airstream a.s.

## Major Assemblies

Airframe	560XL (Citation Excel)	<b>560-5183</b>	25-Jan-2024	7052:40 Hrs	4,653 Ldg	2029 Hrs(APU)	4,326 Start(APU)
Eng 1	PW545A	<b>PCE-DB0373</b>	25-Jan-2024	6742:55 Hrs	4,454 Enc		
Eng 2	PW545A	<b>PCE-DB0416</b>	25-Jan-2024	6155:30 Hrs	4,127 Enc		
APU 1	RE100[XL]	<b>P-233</b>	18-Jan-2024	2029 Hrs	4,326 APUS		

## Additional Information

Program Type: MSG-3, General Categories: Honeywell Avionics

Cost: 3,173.5+

Man Hrs: 69.2+

Analyst: Stephen Crosthwaite [scrosthwaite@traxxall.com](mailto:scrosthwaite@traxxall.com)

Task No SEQ	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
<b>▼ 21 - AIR CONDITIONING AND PRESSURIZATION</b>										
2013-09-11	Air Conditioning								RE (-)	Mandatory
	21 A/F Eff: 05-Jul-2013 Not Applicable					Mos	11-Jun-2013			
						Hrs	3699			
						Ldg	2,788			
2013-09-11 Par. (g), (h)	Air Conditioning - Inspection for P/N, Compressor Hour Meter and Maintenance Records								RE (-)	Mandatory
	21 A/F Eff: 05-Jul-2013 Not Applicable					Mos	11-Jun-2013			
						Hrs	3699			
						Ldg	2,788			
2013-09-11 Par. (i)	Air Conditioning - Motor Brushes Replacement								RE (-)	Mandatory
	21 A/F Eff: 05-Jul-2013 Not Applicable					Mos	11-Jun-2013			
						Hrs	3699			
						Ldg	2,788			
						ACH	1378			
2013-09-11 Par. (j)	Air Conditioning - Replacement Maintenance Manual Information								RE (-)	Mandatory
	21 A/F Eff: 05-Jul-2013 Not Applicable					Mos	11-Jun-2013			
						Hrs	3699			
						Ldg	2,788			
						ACH	1378			
2013-09-11 Par. (k)	Air Conditioning - Deactivation of A/C System								RE (-)	Mandatory
	21 A/F Eff: 05-Jul-2013 Not Applicable					Mos	11-Jun-2013			
						Hrs	3699			
						Ldg	2,788			
2013-09-11 Par. (l)	Air Conditioning - Reactivation of A/C System								RE (-)	Mandatory
	21 A/F Eff: 05-Jul-2013 Not Applicable					Mos	11-Jun-2013			
						Hrs	3699			
						Ldg	2,788			
2013-09-11 Par. (m)	Air Conditioning - Replacement Of The Brushes On A/C Compressor Motors, Part Nos. 1134104-1/1134104-5, Or Deactivation Of The A/C System Parts Return And Reporting Requirements								RE (-)	Mandatory
	21 A/F Not Applicable					Mos	11-Jun-2013			
						Hrs	3699			
						Ldg	2,788			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							Due	Remaining
<b>▼ 23 - COMMUNICATIONS</b>										
2005-0021	Honeywell RCZ-83() and RCZ-85() Communication Units (SUPERSEDED BY EASA AD 2007-0156)						RE (-)		Mandatory (Appliance AD)	
23 A/F	Eff: 01-Aug-2005 Complied With					Mos	03-Aug-2005			
						Hrs	1760			
						Ldg				
2006-19-04	Honeywell International, Inc - COM unit and Mode S transponder						RE (-)		Mandatory (Appliance AD)	
23 A/F	Eff: 17-Oct-2006 Not Applicable					Mos	25-Oct-2006			
	Brand A:9990-2006-19-04					Hrs	2486			
						Ldg				
2014-0088	Cobham Avionics - Communications - Cockpit Voice Recorder - Replacement						RE (-)		Mandatory (Appliance AD)	
23 A/F	Eff: 29-Apr-2014 Not Applicable	NOT INSTALLED				Mos	29-Apr-2014			
						Hrs	3843:30			
						Ldg	2,877			
2014-0088 PARA (1)	Remove The Team Cvr P/N Ap71232101 Or P/N Ap71231101, As Applicable, From The Aircraft And, Depending On Operational Regulations, Install A Serviceable Cvr In Accordance With Approved Aircraft Modification Instructions						RE (-)		Mandatory (Appliance AD)	
23 A/F	Not Applicable	NOT INSTALLED				Mos	29-Apr-2014			
						Hrs	3843:30			
						Ldg	2,877			
2014-0088 PARA (2)	Do Not Install On Any Aircraft A Team Cvr P/N Ap71232101 Or P/N Ap71231101, As Required By Paragraph (2.1) Or (2.2) Of This Ad, As Applicable						RE (-)		Mandatory (Appliance AD)	
23 A/F	Not Applicable	NOT INSTALLED				Mos	29-Apr-2014			
						Hrs	3843:30			
						Ldg	2,877			
<b>▼ 24 - ELECTRICAL POWER</b>										
2017-04-14	Electrical Power - Inspections of the Fuel Tube and Right Alternating Current (AC) Generator Wires						RE (-)		Mandatory	
24 A/F	Eff: 09-Mar-2017 Complied	NO DAMAGE FOUND				Mos	23-Jan-2017			
	With					Hrs				
		FAA AD:2017-03-09 (AVG MAN HRS: 17) (UPDATE NOTE: WIRE BUNDLE NO DAMAGE, 6616110-10 TUBE NO DAMAGE)				Ldg				
2017-04-14 Par. 2(g)	Electrical Power - Inspections of the Fuel Tube and Right Alternating Current (AC) Generator Wires - Inspections, Adjustments, and Corrective Actions						RE (-)		Mandatory	
24 A/F	Eff: 09-Mar-2017 Complied	NO DAMAGE FOUND				Mos	23-Jan-2017			
	With					Hrs				
		(AVG MAN HRS: 16) (UPDATE NOTE: WIRE BUNDLE NO DAMAGE, 6616110-10 TUBE NO DAMAGE)				Ldg				
2017-04-14 Par. 2(h)	Electrical Power - Inspections of the Fuel Tube and Right Alternating Current (AC) Generator Wires - Reporting						RE (-)		Mandatory	
24 A/F	Eff: 09-Mar-2017 Complied	NO DAMAGE FOUND				Mos	23-Jan-2017			
	With					Hrs				
		(AVG MAN HRS: 1) (UPDATE NOTE: NO DAMAGE FOUND - NO REPORT NEEDED)				Ldg				
<b>▼ 25 - EQUIPMENT/FURNISHINGS</b>										
2013-0020	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection / Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F	Eff: 14-Feb-2013 Not Applicable	SUPERSEDED BY REV1				Mos	13-Aug-2013			
						Hrs	3716:06			
						Ldg	2,798			
2013-0020R1	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection / Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F	Eff: 12-Mar-2013 Complied	SAFETY BELTS AND TORSO RESTRAINT SYSTEMS HAVE NOT BEEN MAINTAINED OR REPAIRED BY AN ORGANISATION OTHER THAN THE DESIGN APPROVAL HOLDER	With			Mos	18-Jun-2013			
						Hrs	3704:54			
						Ldg	2,792			

Task No SEQ	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2013-0020R1 Paragraph (1)	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 12-Mar-2013 Complied With						Mos Hrs Ldg	18-Jun-2013			
2013-0020R1 Paragraph (2)	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - verify if the organisation is listed among the authorized maintenance or repair organisation						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 12-Mar-2013 Complied With						Mos Hrs Ldg	18-Jun-2013			
2013-0020R1 Paragraph (3)	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 12-Mar-2013 Complied With PRIHODA CZ/006061548						Mos Hrs Ldg	18-Jun-2013			
2013-0020R1 Paragraph (4)	Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection / Replacement After 14 February 2013 [The Effective Date Of The Original Issue Of This Ad], Do Not Install Safety Belts Or Torso Restraint Systems On Any Aircraft, Unless Inspected And Corrected In Compliance With The Requirements Of This Ad.						RE (-)		Mandatory (Appliance AD)	
25 A/F Complied With						Mos Hrs Ldg	18-Jun-2013			
2013-0020R2	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection / Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 14-Feb-2013 Not Applicable						Mos Hrs Ldg	13-Aug-2013 3716:06 2,798			
2013-0020R2 Paragraph (1)	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 14-Feb-2013 Not Applicable						Mos Hrs Ldg	13-Aug-2013 3716:06 2,798			
2013-0020R2 Paragraph (2)	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - verify if the organisation is listed among the authorized maintenance or repair organisation						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 14-Feb-2013 Not Applicable						Mos Hrs Ldg	13-Aug-2013 3716:06 2,798			
2013-0020R2 Paragraph (3)	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 14-Feb-2013 Not Applicable						Mos Hrs Ldg	13-Aug-2013 3716:06 2,798			
2013-0020R2 Paragraph (4)	Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection / Replacement After 14 February 2013 [The Effective Date Of The Original Issue Of This Ad], Do Not Install Safety Belts Or Torso Restraint Systems On Any Aircraft, Unless Inspected And Corrected In Compliance With The Requirements Of This Ad						RE (-)		Mandatory (Appliance AD)	
25 A/F Not Applicable						Mos Hrs Ldg	13-Aug-2013 3716:06 2,798			
2013-0020R3	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection / Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 28-Mar-2014 Not Applicable	BY ORGINAL MANUFACTURER INSTALLED					Mos Hrs Ldg	09-Apr-2014 3836:12 2,874			

Task No SEQ	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2013-0020R3 PARA (4)	After 14 February 2013 [The Effective Date Of The Original Issue Of This Ad], Do Not Install Safety Belts Or Torso Restraint Systems On Any Aircraft, Unless Inspected And Corrected In Compliance With The Requirements Of This Ad (Mandatory)						RE (-)		Mandatory (Appliance AD)	
25 A/F Not Applicable	BY ORGINAL MANUFACTURER INSTALLED					Mos	09-Apr-2014			
						Hrs	3836:12			
						Ldg	2,874			
2013-0020R3 Paragraph (1)	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 28-Mar-2014 Not Applicable	BY ORGINAL MANUFACTURER INSTALLED					Mos	09-Apr-2014			
						Hrs	3836:12			
						Ldg	2,874			
2013-0020R3 Paragraph (2)	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - verify if the organisation is listed among the authorized maintenance or repair organisation						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 28-Mar-2014 Not Applicable	BY ORGINAL MANUFACTURER INSTALLED					Mos	09-Apr-2014			
						Hrs	3836:12			
						Ldg	2,874			
2013-0020R3 Paragraph (3)	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 28-Mar-2014 Not Applicable	BY ORGINAL MANUFACTURER INSTALLED					Mos	09-Apr-2014			
						Hrs	3836:12			
						Ldg	2,874			
2013-0020R4	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection / Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 11-Jul-2014 Not Applicable	BY ORGINAL MANUFACTURER INSTALLED					Mos	18-Jul-2014			
						Hrs				
						Ldg				
2013-0020R4 Paragraph (1)	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 11-Jul-2014 Not Applicable	BY ORGINAL MANUFACTURER INSTALLED					Mos	18-Jul-2014			
						Hrs				
						Ldg				
2013-0020R4 Paragraph (2)	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - verify if the organisation is listed among the authorized maintenance or repair organisation						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 11-Jul-2014 Not Applicable	BY ORGINAL MANUFACTURER INSTALLED					Mos	18-Jul-2014			
						Hrs				
						Ldg				
2013-0020R4 Paragraph (3)	AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 14-Feb-2013 Not Applicable	BY ORGINAL MANUFACTURER INSTALLED					Mos	18-Jul-2014			
						Hrs				
						Ldg				
2013-0020R4 Paragraph (4)	After 14 February 2013 [The Effective Date Of The Original Issue Of This Ad], Do Not Install Safety Belts Or Torso Restraint Systems On Any Aircraft, Unless Inspected And Corrected In Compliance With The Requirements Of This Ad						RE (-)		Mandatory (Appliance AD)	
25 A/F Not Applicable	BY ORGINAL MANUFACTURER INSTALLED					Mos	18-Jul-2014			
						Hrs				
						Ldg				

Task No SEQ	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2014-0019	Equipment / Furnishings - Crash Position Indicator - Modification Aircraft Flight Manual - Amendment (SUPERSEDED BY EASA AD 2014-0095)						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 31-Jan-2014 Not Applicable	NOT INSTALLED					Mos	04-Mar-2014			
						Hrs	3817:18			
						Ldg	2,863			
2014-0019 PARA (1)	Amend The Afm Of The Affected Aircraft (Mandatory)						RE (-)		Mandatory (Appliance AD)	
25 A/F Not Applicable	NOT INSTALLED					Mos	04-Mar-2014			
						Hrs	3817:18			
						Ldg	2,863			
2014-0019 PARA (2)	Replace The System Interface Unit P/N 503-24-() Or 503-42-() (Mandatory)						RE (Not Installed)		Mandatory (Appliance AD)	
25 A/F Not Applicable	NOT INSTALLED					Mos	04-Mar-2014			
						Hrs	3817:18			
						Ldg	2,863			
2014-0019 PARA (3)	Do Not Install A Hr Smith (Technical Developments) Cpi System Series 15-503-134 Or 15-503-134-1 Equipped With Control Panel P/N 503-22-(), Beacon Release Unit P/N 503-21 And System Interface Unit P/N 503-24-() Or P/N 503-42-(), Excluding System Interface Unit P/N 503-24-A, Or 503-24-()A, Or 503-24-G, Or 503-24-()G, Or 503-42-A Or 503-42-()A Or 503-42-G Or 503-42-()G, On An Aircraft, Unless In Compliance With The Requirements Of This Ad (Mandatory)						RE (-)		Mandatory (Appliance AD)	
25 A/F Not Applicable	NOT INSTALLED					Mos	04-Mar-2014			
						Hrs	3817:18			
						Ldg	2,863			
2014-0019 PARA (4)	Remove Afm Amendment And Placard As Required By Paragraph (1) Of This Ad (Mandatory)						RE (-)		Mandatory (Appliance AD)	
25 A/F Not Applicable	NOT INSTALLED					Mos	04-Mar-2014			
						Hrs	3817:18			
						Ldg	2,863			
2014-0095	HR Smith - Equipment / Furnishings - Crash Position Indicator - Modification - Aircraft Flight Manual - Amendment						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 07-May-2014 Not Applicable	NOT INSTALLED					Mos	29-Apr-2014			
						Hrs	3843:30			
						Ldg	2,877			
2014-0095 PARA (4)	Do Not Install A Hr Smith (Technical Developments) Cpi System Series 15-503-134 Or 15-503-134-1 Equipped With Control Panel P/N 503-22-(), Beacon Release Unit P/N 503-21 And System Interface Unit P/N 503-24-() (Including 503-24) Or P/N 503-42-() (Including 503-42) Excluding System Interface Unit P/N 503-24-A Or P/N 503-24-()A Or P/N 503-24-G Or P/N 503-24-()G Or P/N 503-42-A Or P/N 503-42-()A Or P/N 503-42-G Or P/N 503-42-()G On An Aircraft Unless In Compliance With The Requirements Of This Ad (Mandatory)						RE (-)		Mandatory	
25 A/F Not Applicable	NOT INSTALLED					Mos	29-Apr-2014			
						Hrs	3843:30			
						Ldg	2,877			
2014-0095 PARA (5)	Remove The Afm Amendment And Placard As Required By Paragraph (1) Of This Ad (Mandatory)						RE (-)		Mandatory	
25 A/F Not Applicable	NOT INSTALLED					Mos	29-Apr-2014			
						Hrs	3843:30			
						Ldg	2,877			
2014-0095 Paragraph (1)	HR Smith - Equipment / Furnishings - Crash Position Indicator - Modification - Install a placard "DO NOT USE TRANSMIT OVER WATER" next to the CPI control panel. / Amend the AFM of the aircraft, by inserting a copy of this AD into the Emergency Procedures Section of the AFM.						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 07-May-2014 Not Applicable	NOT INSTALLED					Mos	29-Apr-2014			
						Hrs	3843:30			
						Ldg	2,877			
2014-0095 Paragraph (2)	HR Smith - Equipment / Furnishings - Crash Position Indicator - Modification - Incorporation of Appendix A of this AD into the Emergency Procedures Section of the AFM of the aircraft						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 07-May-2014 Not Applicable	NOT INSTALLED					Mos	29-Apr-2014			
						Hrs	3843:30			
						Ldg	2,877			

Task No SEQ	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2014-0095 Paragraph (3)	HR Smith - Equipment / Furnishings - Crash Position Indicator - Modification - replace the System Interface Unit P/N 503-24-() (including 503-24) or P/N 503-42-() (including 503-42) with an improved part P/N 503-24-A, or P/N 503-24-() -A, or P/N 503-24-G, or P/N 503-24-() -G, or P/N 503-42-A or P/N 503-42-() -A or P/N 503-42-G or P/N 503-42-() -G.						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 07-May-2014 Not Applicable	NOT INSTALLED					Mos	29-Apr-2014			
						Hrs	3843:30			
						Ldg	2,877			
2014-0095 R1 Paragraph (4)	Do Not Install A Hr Smith (Technical Developments) Cpi System Series 15-503-134 Or 15-503-134-1 Equipped With Control Panel P/N 503-22-(), Beacon Release Unit P/N 503-21 And System Interface Unit P/N 503-24-() (Including 503-24) Or P/N 503-42-() (Including 503-42) Excluding System Interface Unit P/N 503-24-A Or P/N 503-24-() -A Or P/N 503-24-G Or P/N 503-24-() -G Or P/N 503-42-A Or P/N 503-42-() -A Or P/N 503-42-G Or P/N 503-42-() -G On An Aircraft Unless In Compliance With The Requirements Of This Ad						RE (-)		Mandatory (Appliance AD)	
25 A/F Not Applicable	EQUIPMENT NOT INSTALLED					Mos	21-May-2014			
						Hrs				
						Ldg				
2014-0095 R1 Paragraph (5)	Remove The Afm Amendment And Placard As Required By Paragraph (1) Of This Ad						RE (-)		Mandatory (Appliance AD)	
25 A/F Not Applicable	EQUIPMENT NOT INSTALLED					Mos	21-May-2014			
						Hrs				
						Ldg				
2014-0095R1	HR Smith - Equipment / Furnishings - Crash Position Indicator - Modification - Aircraft Flight Manual - Amendment						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 12-May-2014 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	21-May-2014			
						Hrs				
						Ldg				
2014-0095R1 Paragraph (1)	HR Smith - Equipment / Furnishings - Crash Position Indicator - Modification - Install a placard "DO NOT USE TRANSMIT OVER WATER" next to the CPI control panel. / Amend the AFM of the aircraft, by inserting a copy of this AD into the Emergency Procedures Section of the AFM.						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 12-May-2014 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	21-May-2014			
						Hrs				
						Ldg				
2014-0095R1 Paragraph (2)	HR Smith - Equipment / Furnishings - Crash Position Indicator - Modification - Incorporation of Appendix A of this AD into the Emergency Procedures Section of the AFM of the aircraft						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 12-May-2014 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	21-May-2014			
						Hrs				
						Ldg				
2014-0095R1 Paragraph (3)	HR Smith - Equipment / Furnishings - Crash Position Indicator - Modification - replace the System Interface Unit P/N 503-24-() (including 503-24) or P/N 503-42-() (including 503-42) with an improved part P/N 503-24-A, or P/N 503-24-() -A, or P/N 503-24-G, or P/N 503-24-() -G, or P/N 503-42-A or P/N 503-42-() -A or P/N 503-42-G or P/N 503-42-() -G.						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 31-Jan-2014 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	21-May-2014			
						Hrs				
						Ldg				
2014-0125	HR SMITH (Technical Developments - Equipment / Furnishings - Crash Position Indicator System - Replacement; Aircraft Flight Manual - Amendment						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 22-May-2014 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	11-Jun-2014			
						Hrs				
						Ldg				
2014-0125 Paragraph (1)	HR SMITH (Technical Developments - Equipment / Furnishings - Crash Position Indicator System - Aircraft Flight Manual - Amendment						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 22-May-2014 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	11-Jun-2014			
						Hrs				
						Ldg				

Task No SEQ	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2014-0125 Paragraph (2)	HR SMITH (Technical Developments - Equipment / Furnishings - Crash Position Indicator System - Complete Start-up procedure / Applicable Start-up procedure / Shutdown procedure						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 22-May-2014 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	11-Jun-2014			
						Hrs				
						Ldg				
2014-0125 Paragraph (3)	HR SMITH (Technical Developments - Equipment / Furnishings - Crash Position Indicator System - Other means of Compliance with the requirements of paragraph (2) of this AD						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 22-May-2014 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	11-Jun-2014			
						Hrs				
						Ldg				
2014-0125 Paragraph (4)	HR SMITH (Technical Developments - Equipment / Furnishings - Crash Position Indicator System - Replace the CPI SIU having P/N 503-24 or P/N 503-24-2 or P/N 503-24-6 with an improved unit P/N 503-24G or P/N 503-24-2G or P/N 503-24-6G						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 22-May-2014 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	11-Jun-2014			
						Hrs				
						Ldg				
2014-0125 Paragraph (5)	Modification Of An Aircraft As Required By Paragraph (4) Of This Ad Constitutes Terminating Action For Accomplishment Of The Procedures As Required By Paragraph (2) Of This Ad						RE (-)		Mandatory (Appliance AD)	
25 A/F Not Applicable	EQUIPMENT NOT INSTALLED					Mos	11-Jun-2014			
						Hrs				
						Ldg				
2014-0125 Paragraph (6)	From The Effective Date Of This Ad, Installation On An Aircraft Of An Hr Smith (Technical Developments) Cpi System Series 15-503-134-1 Equipped With Bru P/N 503-21-1 And Siu P/N 503-24 Or P/N 503-24-2 Or P/N 503-24-6 Is Allowed, Provided The Aircraft Is Operated In Compliance With The Procedures As Required By This Ad						RE (-)		Mandatory (Appliance AD)	
25 A/F Not Applicable	EQUIPMENT NOT INSTALLED					Mos	11-Jun-2014			
						Hrs				
						Ldg				
2014-0125 Paragraph (7)	After Replacement Of The Cpi Siu On An Aircraft As Required By Paragraph (4) Of This Ad, Do Not Install An Siu P/N 503-24 Or P/N 503-24-2 Or P/N 503-24-6 On The Cpi System Of That Aircraft						RE (-)		Mandatory (Appliance AD)	
25 A/F Not Applicable	EQUIPMENT NOT INSTALLED					Mos	11-Jun-2014			
						Hrs				
						Ldg				
2014-0187	Equipment & Furnishings - Safety Belt Attachment Bolts - Inspection / Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 03-Sep-2014 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	29-Sep-2014			
						Hrs				
						Ldg				
2014-0279	Equipment / Furnishing - Restraint System Rotary Buckle Sub-Assembly - Identification / Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 02-Jan-2015 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	12-Feb-2015			
						Hrs				
						Ldg				
2014-0279 Paragraph (1)	Equipment / Furnishing - Restraint System Rotary Buckle Sub-Assembly - Replacement or Mark the seat as "inoperative" until replacement of the rotary buckle sub-assembly						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 02-Jan-2015 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	12-Feb-2015			
						Hrs				
						Ldg				
2014-0279 Paragraph (2)	Equipment / Furnishing - Restraint System Rotary Buckle Sub-Assembly - Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 02-Jan-2015 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	12-Feb-2015			
						Hrs				
						Ldg				

Task No SEQ	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2014-0279 Paragraph (3)	Equipment / Furnishing - Restraint System Rotary Buckle Sub-Assembly - Do Not Install: - On Any Restraint System A Spare Rotary Buckle Sub-Assembly, Or - On Any Aircraft A Restraint System Equipped With A Rotary Buckle Sub-Assembly Having A P/N And A S/N Listed In Romtex Anjou Aeronautique Sb 358Sb-14-101, Unless The Sub-Assembly Has Been Repaired. (Mandatory)						RE (-)		Mandatory (Appliance AD)	
25 A/F Not Applicable	EQUIPMENT NOT INSTALLED					Mos Hrs Ldg	12-Feb-2015			
2016-0163	Cabin Attendant Seat - Modification/ Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 24-Aug-2016 Not Applicable	AIRCRAFT NOT EQUIPED WIT EODIAC FRANCE SEAT 537-SERIES					Mos Hrs Ldg				
2016-0164	Cabin Attendant Seat - Inspection (Superseded by AD 2017-0001)						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 24-Aug-2016 Not Applicable	AD SUPERSEDED BY AD 2017-0001					Mos Hrs Ldg				
2016-0167 R1	Rear Cabin Attendant Seat - Inspection / Repair (Duplicate)						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 02-Feb-2018 Not Applicable	AIRCRAFT NOT EQUIPPED WITH THIS KIND OF SEAT					Mos Hrs Ldg				
2017-0001	Cabin Attendant Seat - Inspection/ Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Not Applicable	AIRCRAFT NOT EQUIPPE WITH THIS KIND OF SEAT					Mos Hrs Ldg				
2017-16-01	Emergency Locator Beacon (Ameri-King Corporation) - Inspect/ Replace						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 24-Oct-2017 Not Applicable (AVG MAN HRS: 6)	AIRCRAFT EQUIPPED WITH A ARTEX ELT C406-2					Mos Hrs Ldg				
2017-16-04	Cabin Equipment/Furnishings - Romtex Torso Restraint Systems with a Rotary Buckle Subassembly (This AD has been superseded by AD 2020-09-02)						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 22-Sep-2017 Not Applicable	AIRCRAFT NOT EQUIPPED WITH ROMTEX ANJOU AERONAUTIQUE (ROMTEX) TORSO RESTRAINT SYSTEMS - SUPERSEDED BY AD 2020-09-02					Mos Hrs Ldg				
2017-22-02	Pilot and Co-Pilot Seats - Modification/ Re-Identification (This AD has been replaced by AD 2019-21-06)						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 12-Dec-2017 Not Applicable (AVG MAN HRS: 2) (NOTE: APPLICABILITY: This AD applies to Ipeco Holdings Ltd. (Ipeco) pilot and co-pilot seats with a part number listed in the Planning Information section of Ipeco Service Bulletins (SBs) Number 063-25-08, Revision 00; Number 063-25-09, Revision 00; and Number 063-25-10, Revision 00; all dated May 31, 2016.)	AIRCRAFT NOT EQUIPPED WITH THIS KIND OF CREW SEATS - AD SUPERSED BY AD 2019-21-06					Mos Hrs Ldg				
2018-0195	Equipment/ Furnishings - Restraint Systems Rotary Buckle Sub-Assembly - Removal from Service						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 18-Sep-2018 Not Applicable	AIRCRAFT NOT EQUIPPED WITH THIS KIND OF RESTRAINT SYSTEMS ROTARY BUCKLE SUB ASSEMBLY					Mos Hrs Ldg				
2018-0223	Equipment / Furnishing - Seat Energy Absorber Assembly - Modification						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 31-Oct-2018 Not Applicable (NOTE: NOTE: Refer to B/E Aerospace Fischer SB SB0718-004 Ausgabe (Issue) A dated 26 June 2018.)	AIRCRAFT NOT EQUIPPED WITH THIS KIND OF SEATS					Mos Hrs Ldg				

Task No SEQ	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2018-0262	IPECO HOLDING Ltd - Pilot and Co-pilot Seats - Modification / Inspection (This AD supersedes EASA AD 2016-0256)(This AD is superseded by AD G-2022-0011)  25 A/F Eff: 20-Dec-2018 Superseded AIRCRAFT NOT EQUIPPED WITH THESE KIND OF SEATS						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 21-Dec-2018 Not Applicable (NOTE: NOTE: Refer to Avointeriors SB 16/18 Rev 1 and SB 18/18 Rev 1.)	AIRCRAFT NOT EQUIPPED WITH THESE KIND OF SEATS					Mos Hrs Ldg				
2018-0264R1	Life Vest Pouch - Inspection/ Modify/ Replace						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 26-Oct-2018 Not Applicable (AVG MAN HRS: 0.5) (NOTE: NOTE: Refer to Zodiac Seats France Service Information Letter 537-01, dated July 31, 2015, and the Accomplishment Instructions, paragraphs 2.A. through 2.B., of Zodiac Seats France Service Bulletin No. 537-25-003, Revision 1, dated August 29, 2016.)	AIRCRAFT NOT EQUIPPED WITH THIS KIND OF SEAT					Mos Hrs Ldg				
2018-16-13	Zodiac Seats France - 537-Series Cabin Attendant Seats - Safety Belt Webbing - Inspection/ Modification						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 14-Nov-2018 Not Applicable (NOTE: NOTE: Refer to Geven SB No. D103-25-004, Revision 4, dated March 15, 2016.)	AIRCRAFT NOT EQUIPPED WITH THESE KIND OF SEATS					Mos Hrs Ldg				
2018-19-15	GEVEN S.p.A. (Geven) Type D1-02 and D1-03 In-Arm Table, Standard, and Last Row Seats - Modification						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 28-Dec-2018 Not Applicable (NOTE: NOTE: Refer to Safran Aerosystems Service Bulletin (SB) 25-65-33 and SB 25-65-34.)	AIRCRAFT NOT EQUIPPED WITH THIS KIND OF SEATS					Mos Hrs Ldg				
2018-23-01	Zodiac Seats France Cabin Attendant Seats, 536 Series, P/N 53600 with Seat Pan P/N F0433453 - Inspection/ Modification/ Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 06-Feb-2019 Not Applicable (NOTE: NOTE: Refer to Safran Aerosystems Service Bulletin (SB) 25-65-33 and SB 25-65-34.)	AIRCRAFT NOT EQUIPPED WITH THIS KIND OF LIFE JACKETS					Mos Hrs Ldg				
2019-0235	ACR ELECTRONICS, Inc. - Emergency Locator Transmitter - Inspection / Modification / Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 04-Oct-2019 Not Applicable ELT PART NUMBER 453-5000 SERIAL NUMBER 210-04997 WAS INSTALLED NEW IN FEBRUARY 2016. SO ELT NEVER HAS BEEN INSTALLED ON HELICOPTERS	AIRCRAFT NOT EQUIPPED WITH THIS KIND OF SEAT					Mos Hrs Ldg				
2019-07-03	Zodiac Seats France 536-Series Cabin Attendant Seats - Inspection/ Modification						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 16-May-2019 Not Applicable NEVER HAS BEEN INSTALLED ON HELICOPTERS	AIRCRAFT NOT EQUIPPED WITH THIS KIND OF SEAT					Mos Hrs Ldg				
2019-08-01	RECARO Aircraft Seating GmbH & Co. KG (RECARO) Model 3510A and 3510D Passenger Seats - Modification						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 21-May-2019 Not Applicable AIRCRAFT NOT EQUIPPED WITH THESE KIND OF SEATS	AIRCRAFT NOT EQUIPPED WITH THIS KIND OF SEATS					Mos Hrs Ldg				
2019-14-05	B/E Aerospace Fischer GmbH (B/E Aerospace Fischer) Common Seats 170/260 H160 - Inspect/ Rework/ Replace						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 03-Sep-2019 Not Applicable (AVG MAN HRS: 3.2) (NOTE: NOTE: From the effective date of this AD, do not install any seat affected by this AD onto any aircraft unless the seat is marked with a placard stating completion of B/E Aerospace Fischer ASB No. SB0718-004, Issue A, dated June 26, 2018.)	AIRCRAFT NOT EQUIPPED WITH THIS KIIND OF SEATS					Mos Hrs Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							Due	Remaining
2019-15-10	Safran Aerosystems Life Jackets with P/N 210225-2, P/N 216200-0, or P/N 216203-0 - Inspect/ Replace/ Repair						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 19-Sep-2019 Not Applicable	AIRCRAFT NOT EQUIPPED WITH THESE KIND OF LIFE JACKETS  (NOTE: NOTE: Refer to Zodiac Aerospace Services Service Bulletin (SB) 25-65-33, Revision 02, dated March 15, 2019.)					Mos Hrs Ldg				
2019-21-06	Ipeco Pilot and Co-Pilot Seats - Modification/ Re-Identification (This AD replaces AD 2017-22-02) (Superseded by FAA AD 2023-14-10)						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 13-Dec-2019 Superseded	AIRCRAFT NOT EQUIPPED WITH THESE KIND OF SEATS					Mos Hrs Ldg	13-Jul-2023			
2019-21-09	Aviointeriors S.p.A. (Aviointeriors) Centaurus Economy Class 13E, 13H, and 13K Passenger Seats with Life Vest Pouch, P/N 313907100004 - Inspection/ Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 18-Dec-2019 Not Applicable	AIRCRAFT NOT EQUIPPED WITH THIS KIND OF SEATS					Mos Hrs Ldg				
2020-0272	Equipment / Furnishings – Buckle – Modification / Replacement						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 23-Dec-2020 Not Applicable	AIRCRAFT NOT EQUIPPED WITH SCHROTH RESTRAINT SYSTEM					Mos Hrs Ldg				
2020-09-02	Cabin Equipment/Furnishings - Anjou Aeronautique Model 358 Torso Restraint Systems - Inspection/Replacement/Installation Prohibition (This AD replaces AD 2017-16-04)						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 29-May-2020 Not Applicable	AIRCRAFT NOT EQUIPPED WITH ROMTEX ANJOU AERONAUTIQUE (ROMTEX) TORSO RESTRAINT SYSTEMS					Mos Hrs Ldg				
2021-0137	Equipment/Furnishings - Pilot and Co-Pilot Seats/Longitudinal Locking System Pins - Measurement/Adjustment						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 22-Jun-2021 Not Applicable	AIRCRAFT NOT EQUIPPED WITH THESE KIND OF SEAT  (NOTE: APPLICABILITY: 191 series pilot seats, having Part Number (P/N) 19101-00-00, and 191 series co-pilot seats, having P/N 19102-00-00. COMPLIANCE: Within 750 flight hours after the effective date of this AD, measure the length of the LH and RH locking pin installed in the longitudinal seat locking system in accordance with the instructions of the SB.)					Mos Hrs Ldg				
2021-07-13 Par. (e)(1)	Pacific Scientific Company Rotary Buckle Assembly, P/Ns 1111430 and 1111475 - Inspect the Buckle Handle for a Crack						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 11-May-2021 Not Applicable	SEAT BELT BUCKLES INSPECTION PERFORMED AND FOUND NOT APPLICABLE - MANUFACTURING DATE IS 2001  (NOTE: COMPLIANCE: Within 6 months, inspect the buckle handle for a crack. If the buckle handle is cracked, before further flight, remove the buckle as depicted in Figure 5 and by following the Procedures, paragraph 9, of SB 25-1111432, and replace it with an airworthy buckle, except you are not required to return the removed buckle to Pacific Scientific.)					Mos Hrs Ldg	22-Nov-2021 5998:30 3,965			
2022-05-09	Parachute - MARS A.S. ATL-88/90-1B (Commercially known as ATL-15 SL) Emergency Parachutes (This AD is Superseded by FAA (AD) 2022-07-05)						T (-)		Mandatory (Appliance AD)	
25 A/F Eff: 13-Mar-2022 Superseded	EQUIPMENT NOT INSTALLED  (NOTE: APPLICABILITY: This AD applies to MARS A.S. ATL-88/90-1B (commercially known as ATL-15 SL) emergency parachutes with an extension of static line made of Microline cord and that meet any of the criterion in paragraph (c)(1), (2), or (3) of this AD: (1) The parachute has a date of manufacture between January 1, 2016, and December 31, 2020, inclusive; (2) The parachute has a serial number (S/N) 2145001 through S/N 2145005 inclusive, and S/N 2145023 through S/N 2145034 inclusive; or (3) The date of manufacture or the S/N of the parachute is unknown.)					Mos Hrs Ldg	11-Apr-2022			
2022-07-05	Parachute - MARS A.S. ATL-88/90-1B (Commercially known as ATL-15 SL) Emergency Parachutes						T (N/A)		Mandatory (Appliance AD)	
25 A/F Not Applicable	EQUIPMENT NOT INSTALLED					Mos Hrs Ldg	04-Apr-2022			

Task No SEQ	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2022-24-04	Parachute - Modify and Re-identify Emergency Parachute (P/N) 09994, P/N 09995 and P/N 09996  25 A/F Eff: 18-Dec-2022 Not Applicable EQUIPMENT NOT INSTALLED  (AVG MAN HRS: 6) (NOTE: APPLICABILITY: This AD applies to MarS A.S. ATL-88/90-1B (commercially known as ATL-15 SL) emergency parachutes part number (P/N) 09994, P/N 09995, and P/N 09996 (no dash number) that meet either of the criterion in paragraph (c)(1) or (2) of this AD: (1) The parachute has a date of manufacture of January 1, 2016, or later; or (2) The date of manufacture of the parachute is unknown. COMPLIANCE: As of the effective date of this AD, modify and re-identify each emergency parachute in accordance with the Service Bulletin Procedure, paragraph 7.b., of MarS a.s. Service Bulletin No. 01/04/2022, Rev. C, dated April 8, 2022.)					Mos Hrs Ldg	12-Dec-2022	RE (-)	Mandatory (Appliance AD)	
2023-12-25	Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets  25 A/F Not Applicable NOT APPLICABLE BY P/N AND MANUFACTURER					Mos Hrs Ldg	23-Aug-2023	RE (Not Installed)	Mandatory	
2023-12-25 Par. (g)	Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets - Inspection  25 A/F Not Applicable NOT APPLICABLE BY P/N AND MANUFACTURER					Mos Hrs Ldg	23-Aug-2023	T (Not Installed)	Mandatory	
2023-12-25 Par. (h)	Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets - Follow-On and Corrective Action  25 A/F Not Applicable N/A BY P/N AND MANUFACTURER					Mos Hrs Ldg	23-Aug-2023	T (Not Installed)	Mandatory	
2023-14-10	Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats (Supersedes FAA AD 2019-21-06)  25 A/F Not Applicable N/A BY P/N AND BY MANUFACTURER					Mos Hrs Ldg	13-Jul-2023	RE (N/A)	Mandatory (Appliance AD)	
2023-14-10 Par. (g)(1)	Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Modify and Re-Identify each Affected Pilot and Co-Pilot Seat  25 A/F Not Applicable N/A BY P/N AND MANUFACTURER					Mos Hrs Ldg	13-Jul-2023	T (N/A)	Mandatory (Appliance AD)	
2023-14-10 Par. (g)(2)(i)	Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Inspect the Track Lock Spring of Each Seat  25 A/F Not Applicable N/A BY P/N AND MANUFACTURER					Mos Hrs Ldg	13-Jul-2023	T (N/A)	Mandatory (Appliance AD)	
2023-14-10 Par. (g)(2)(ii)	Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Replace both Track Lock Springs of the Affected Seat  25 A/F Not Applicable N/A BY P/N AND MANUFACTURER					Mos Hrs Ldg	13-Jul-2023	T (N/A)	Mandatory (Appliance AD)	
2023-14-10 Par. (h)	Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - New Mandatory Terminating Action  25 A/F Not Applicable N/A BY P/N AND MANUFACTURER					Mos Hrs Ldg	13-Jul-2023	T (N/A)	Mandatory (Appliance AD)	
74-08-09 R2	Equipment/furnishings - Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles  25 A/F Eff: 06-Aug-1974 Complied With					Mos Hrs Ldg	23-Apr-2010 3118 2,457	RE (-)	Mandatory	
74-08-09 R2 Paragraph (g)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - (1) Install a placard on each side of each lavatory door over the door knob, or on each side of each lavatory door, or adjacent to each side of each lavatory door. (2) Install a placard on or near each lavatory paper or linen waste disposal receptacle door, containing the legible words or symbology indicating "No Cigarette Disposal."  25 A/F Eff: 06-Aug-1974 Not Applicable MFG DATE					Mos Hrs Ldg	23-Apr-2010	RE (-)	Mandatory	

Task No SEQ	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
74-08-09 R2 Paragraph (h)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - establish a procedure that requires that, no later than a time immediately after the "No Smoking" sign is extinguished following takeoff, an announcement be made by a crewmember to inform all aircraft occupants that smoking is prohibited in the aircraft lavatories; except that, if the aircraft is not equipped with a "No Smoking" sign, the required procedure must provide that the announcement be made prior to each takeoff.						RE (-)		Mandatory	
25 A/F Eff: 06-Aug-1974 Not Applicable	N/A BY MFG DATE					Mos	23-Apr-2010			
						Hrs				
						Ldg				
74-08-09 R2 Paragraph (i)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Install a self-contained, removable ashtray on or near the entry side of each lavatory door. One ashtray may serve more than one lavatory door if the ashtray can be seen readily from the cabin side of each lavatory door served.						RE (-)		Mandatory	
25 A/F Eff: 06-Aug-1974 Not Applicable	N/A BY MFG DATE					Mos	23-Apr-2010			
						Hrs				
						Ldg				
74-08-09 R2 Paragraph (j)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - An airplane with multiple lavatory doors may be operated with up to 50 percent of the lavatory door ashtrays missing or inoperative, provided 50 percent of the missing or inoperative ashtrays are replaced within 3 days and all remaining missing or inoperative ashtrays are replaced within 10 days. An airplane with only 1 lavatory door may be operated for a period of 10 days with the lavatory door ashtray missing or inoperative						RE (-)		Mandatory	
25 A/F Eff: 06-Aug-1974 Not Applicable	N/A BY MFG DATE					Mos	23-Apr-2010			
						Hrs				
						Ldg				
74-08-09 R2 Paragraph (k)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Inspect all lavatory paper and linen waste receptacle enclosure access doors and disposal doors for proper operation, fit, sealing, and latching for the containment of possible trash fires.						RE (-)		Mandatory	
25 A/F Eff: 06-Aug-1974 Complied With						Mos	23-Apr-2010			
						Hrs				
						Ldg				
74-08-09 R3	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles						RE (-)		Mandatory	
25 A/F Eff: 28-Mar-2012 Complied With						Mos	21-Sep-2018			
						Hrs	5455:30			
						Ldg	3,706			
74-08-09 R3 Paragraph (g)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - (1) Install a placard on each side of each lavatory door over the door knob, or on each side of each lavatory door, or adjacent to each side of each lavatory door. (2) Install a placard on or near each lavatory paper or linen waste disposal receptacle door, containing the legible words or symbology indicating "No Cigarette Disposal."						RE (-)		Mandatory	
25 A/F Eff: 06-Aug-1974 Not Applicable	MFG DATE					Mos	28-Mar-2012			
						Hrs				
						Ldg				
(UPDATE NOTE: MFG DATE)										
74-08-09 R3 Paragraph (h)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - establish a procedure that requires that, no later than a time immediately after the "No Smoking" sign is extinguished following takeoff, an announcement be made by a crewmember to inform all aircraft occupants that smoking is prohibited in the aircraft lavatories; except that, if the aircraft is not equipped with a "No Smoking" sign, the required procedure must provide that the announcement be made prior to each takeoff.						RE (-)		Mandatory	
25 A/F Eff: 06-Aug-1974 Not Applicable	MFG DATE					Mos	28-Mar-2012			
						Hrs				
						Ldg				
(UPDATE NOTE: MFG DATE)										
74-08-09 R3 Paragraph (i)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Install a self-contained, removable ashtray on or near the entry side of each lavatory door. One ashtray may serve more than one lavatory door if the ashtray can be seen readily from the cabin side of each lavatory door served.						RE (-)		Mandatory	
25 A/F Eff: 06-Aug-1974 Not Applicable	MFG DATE					Mos	28-Mar-2022			
						Hrs				
						Ldg				
(UPDATE NOTE: MFG DATE)										

Task No SEQ	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
74-08-09 R3 Paragraph (j)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - An airplane with multiple lavatory doors may be operated with up to 50 percent of the lavatory door ashtrays missing or inoperative, provided 50 percent of the missing or inoperative ashtrays are replaced within 3 days and all remaining missing or inoperative ashtrays are replaced within 10 days. An airplane with only 1 lavatory door may be operated for a period of 10 days with the lavatory door ashtray missing or inoperative						RE (-)		Mandatory	
25 A/F Eff: 28-Mar-2012 Not Applicable	NO MULTIPLE LAVATORY DOORS INSTALLED  (UPDATE NOTE: NO MULTIPLE LAVATORY DOORS INSTALLED) (NOTE: Note 1 to paragraph (j) of this AD: This AD permits a lavatory door ashtray to be missing, although the FAA-approved Master Minimum Equipment List (MMEL) may not allow such provision. In any case, the provisions of this AD prevail.)					Mos Hrs Ldg	28-Mar-2012			
74-08-09 R3 Paragraph (k)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Inspect all lavatory paper and linen waste receptacle enclosure access doors and disposal doors for proper operation, fit, sealing, and latching for the containment of possible trash fires.						RE (-)		Mandatory	
25 A/F Eff: 28-Mar-2012 Complied With						Days Hrs Ldg	21-Sep-2018 5455:30 3,706			
98-25-10	Aircraft Belts, Inc - Seat Restraint Systems 25-10 R1)	(Superseded by FAA AD 98-)					RE (-)		Mandatory (Appliance AD)	
25 A/F Not Applicable	EQUIPMENT NOT INSTALLED					Mos Hrs Ldg	23-Aug-2001 10			
G-2021-0003	Equipment/Furnishings - Life Jacket - Inspection						T (Not Installed)		Mandatory (Appliance AD)	
25 A/F Not Applicable	NOT EQUIPPED WITH THIS PNS. INSTALLED PN: P01074 SERIES					Mos Hrs Ldg				
G-2021-0004	Equipment/Furnishings - Life Raft - Inspection						RE (-)		Mandatory (Appliance AD)	
25 A/F Eff: 05-Jul-2021 Not Applicable	AIRCRAFT NOT EQUIPPED WITH LIFE RAFT					Mos Hrs Ldg				
(NOTE: APPLICABILITY: Survitec Group Limited (hereafter referred to as "Survitec" in this AD) Life Raft with packed assembly P/N 00051054 (Port) and 00051055 (Starboard). COMPLIANCE: Within 12 months after the effective date of this AD, perform inspection and functional check of life raft in accordance with Alert Service Bulletin 25-197-A.)										
▼ 26 - FIRE PROTECTION										
2006-04-10	This AD Requires Installing Identification Sleeves On The Wires For The Positive And Negative Studs Of The Engine And/ Or (APU) Fire Extinguishing Bottles, As Applicable, And Reconnecting The Wires To The Correct Terminal Studs. (Superseded by AD 2007-11-17)						RE (-)		Mandatory	
26 A/F Eff: 24-Mar-2006 Complied With						Mos Hrs Ldg	14-Mar-2006 2056			
2007-11-17	Wires for the positive and negative terminal studs of the engine and/or auxiliary power unit (APU) fire extinguishing bottles.						RE (-)		Mandatory	
26 A/F Eff: 06-Jul-2007 Complied With (AVG MAN HRS: 4)	INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.					Mos Hrs Ldg	19-Oct-2007 2492			
2009-0251-E	Fire Fighting Enterprises Ltd - Fire Protection - Portable Fire Extinguishers - Identification / Replacement						RE (-)		Mandatory (Appliance AD)	
26 A/F Eff: 26-Nov-2009 Not Applicable						Mos Hrs Ldg	23-Apr-2010 3118 2,457			
2009-0278	SICLI - Fire Protection - Portable Halon 1211 Fire Extinguishers - Identification / Replacement						RE (-)		Mandatory (Appliance AD)	
26 A/F Eff: 05-Jan-2010 Not Applicable						Mos Hrs Ldg	23-Apr-2010 3118 2,457			

Task No SEQ PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2009-0278 Par. (1)	SICLI - Fire Protection - Portable Halon 1211 Fire Extinguishers - Identification / Replacement  26 A/F Eff: 05-Jan-2010 Not Applicable					Mos Hrs Ldg	23-Apr-2010 3118 2,457	RE (-)	Mandatory (Appliance AD)	
2009-0278 Par. (2)	SICLI - Fire Protection - Portable Halon 1211 Fire Extinguishers - Return to SICLI for Disposal  26 A/F Not Applicable					Mos Hrs Ldg	23-Apr-2010 3118 2,457	RE (-)	Mandatory (Appliance AD)	
2010-0062	Fire Fighting Enterprises Limited - Fire Protection - Halon 1211 Fire Extinguishers - Identification /Replacement  26 A/F Eff: 14-Apr-2010 Not Applicable					Mos Hrs Ldg	23-Apr-2010 3118 2,457	RE (-)	Mandatory (Appliance AD)	
2010-01-03	Fire Fighting Enterprises Limited - Fire Protection  26 A/F Eff: 20-Jan-2010 Not Applicable Brand A:9990-2010-01-03					Mos Hrs Ldg	23-Apr-2010 3118 2,457	RE (-)	Mandatory (Appliance AD)	
2010-04-16	SICLI Halon 1211 Portable Fire Extinguishers as Installed on Various Airplanes and Rotorcraft  26 A/F Eff: 08-Mar-2010 Not Applicable Brand A:9990-2010-04-16 (NOTE: Applicability: This AD applies to Type H1-10 AIR Halon 1211 (BCF) portable fire extinguishers manufactured by SICLI, having part number (P/N) 1708337B4 and having any serial number listed in Table 1 of this AD.)					Mos Hrs Ldg	23-Apr-2010 3118 2,457	RE (-)	Mandatory	
2010-04-16 Par. (g)	SICLI Halon 1211 Portable Fire Extinguishers as Installed on Various Airplanes and Rotorcraft : Actions - Replacement  26 A/F Eff: 08-Mar-2010 Not Applicable (NOTE: COMPLIANCE: Within 90 days after the effective date of this AD, replace all Type H1-10 AIR Halon 1211 (BCF) portable fire extinguishers manufactured by SICLI, having P/N 1708337B4 and having any serial number listed in Table 1 of this AD, with serviceable fire extinguishers.)					Mos Hrs Ldg	23-Apr-2010 3118 2,457	RE (-)	Mandatory	
2010-04-16 Par. (h)	SICLI Halon 1211 Portable Fire Extinguishers as Installed on Various Airplanes and Rotorcraft: Actions - Return Fire Extinguishers  26 A/F Not Applicable (NOTE: COMPLIANCE: Within 90 days after doing any replacement required by paragraph (g) of this AD. Set calendar start to date when compliance is done to par (g).)					Mos Hrs Ldg	23-Apr-2010 3118 2,457	RE (-)	Mandatory	
2012-0037	Fire Protection - Hand Operated Fire Extinguisher - Modification  26 A/F Eff: 23-Mar-2012 Not Applicable BY PART NUMBER INSTALLED					Mos Hrs Ldg	11-Apr-2012 3542:12 2,698	RE (-)	Mandatory (Appliance AD)	
2016-0024	Fire Protection - Optical and Ambient Smoke Detectors - Identification / Replacement  26 A/F Eff: 01-Feb-2016 Not Applicable EQUIPMENT P/N NOT INSTALLED					Mos Hrs Ldg	02-Feb-2016	RE (-)	Mandatory (Appliance AD)	
2016-0044	Fire Protection - Engine and Auxiliary Power Unit Automatic Fire Extinguishers - Inspection/Overhaul  26 A/F Eff: 22-Mar-2016 Not Applicable BY INSTALLED P/N					Mos Hrs Ldg	11-Mar-2016 4409:18 3,196	RE (-)	Mandatory (Appliance AD)	
2016-0044 Paragraph (1)	Inspect Each Fire Extinguisher, Except Those Having P/N 57333 Series, Installed On Bae146 And Rj Aeroplanes, And Those Having P/N 57183 Series, Installed On Atp Aeroplanes, And Depending On Findings Accomplish Corrective Actions In Accordance With The Instructions Of Kg Sb 26-080 Revision 1  26 A/F Not Applicable BY INSTALLED P/N					Mos Hrs Ldg	11-Mar-2016 4409:18 3,196	RE (-)	Mandatory (Appliance AD)	

Task No SEQ	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2016-0044 Paragraph (2)	Accomplishment Of An Overhaul (See Note 2 Of This Ad) Of A Fire Extinguisher By Kiddie Graviner Or Hugen, Or In Accordance With The Instructions Of Kg Sil 01-10 Or In Accordance With Kg Cmm 26-21-40 Revision 14 Or Later Or Kg Cmm 26-21-52 Revision 13 Or Later (As Applicable To Fire Extinguisher P/N) Is Acceptable To Comply With The Requirement Of Paragraph (1)						RE (-)		Mandatory (Appliance AD)	
26 A/F Not Applicable	BY INSTALLED P/N					Mos Hrs Ldg	11-Mar-2016 4409:18 3,196			
2016-0044 Paragraph (3)	From The Effective Date Of This Ad Do Not Install On Any Aircraft An Affected Fire Extinguisher, Unless It Is New, Or Has Passed An Inspection In Accordance With The Instructions Of Kg Sb 26-080 Revision 1, Or It Has Been Overhauled (See Note 2) By Kg, Or By Hugen Or In Accordance With The Instructions Of Kg Sil 01-10 Or In Accordance With The Instructions Of Kg Cmm 26-21-40 Revision 14 Or Of Kg Cmm 26-21-52 Revision 13, As Applicable To Fire Extinguisher P/N						RE (-)		Mandatory (Appliance AD)	
26 A/F Not Applicable	BY INSTALLED P/N					Mos Hrs Ldg	11-Mar-2016 4409:18 3,196			
2017-19-05	<b>Smoke Detection - Inspection / Replacement</b>						RE (-)		Mandatory (Appliance AD)	
26 A/F Eff: 31-Oct-2017 Not Applicable (AVG MAN HRS: 1)	AIRCRAFT EQUIPPED WITH KIDDE TECHNOLOGIES SMOKE DETECTORS					Mos Hrs Ldg				
2020-21-02	<b>Fire protection - Kidde Aerospace &amp; Defense - Cargo Fire Extinguisher Halon Bottles</b>						RE (-)		Mandatory (Appliance AD)	
26 A/F Eff: 19-Nov-2020 Not Applicable	AIRCRAFT NOT EQUIPPED WITH CARGO FIRE EXTINGUISHER					Mos Hrs Ldg				
2021-0185R1	<b>Fire Protection - Hand-operated Fire Extinguishers - Inspection/Replacement</b>						RE (-)		Mandatory (Appliance AD)	
26 A/F Eff: 19-Aug-2021 Not Applicable	AIRCRAFT NOT EQUIPPED WITH HAFEX (HALON-FREE) HAND-HELD FIRE EXTINGUISHERS, HAVING PART NUMBER (P/N) P3APP003010A, P/N P3APP003010B OR P/N P3APP003010C (NOTE: APPLICABILITY: For aircraft with HAFEX (Halon-free) hand-held fire extinguishers, having Part Number (P/N) P3APP003010A, P/N P3APP003010B or P/N P3APP003010C, all serial numbers (s/n). COMPLIANCE: Within 30 days after the effective date of this AD, and, thereafter, at intervals not to exceed 6 months, inspect each affected fire extinguisher installed on any aircraft, in accordance with the instructions of paragraph 3.2.C of the VSB, or in accordance with equivalent maintenance instructions issued by the aircraft design (change) approval holder (see Note 1 of this AD).)					Mos Hrs Ldg				
2021-0185R2	<b>Fire Protection - Hand-operated Fire Extinguishers - Inspection/Replacement</b>						RE (-)		Mandatory (Appliance AD)	
26 A/F Not Applicable	N/A BY MFG AND P/N					Mos Hrs Ldg	14-Sep-2022			
2021-22-07	<b>Fire Protection - Impaired Fire Extinguisher</b>						RE (-)		Mandatory (Appliance AD)	
26 A/F Eff: 17-Nov-2021 Not Applicable	AIRCRAFT EQUIPPED WITH PORTABLE FIRE EXTINGUISHER AMEREX P/N C352					Mos Hrs Ldg				
<b>▼ 27 - FLIGHT CONTROLS</b>										
2000-15-51	<b>Aileron Cable Fairlead Tube and Aileron Cable Sector</b>						RE (-)		Mandatory	
27 A/F Eff: 14-Aug-2000 Not Applicable						Mos Hrs Ldg	23-Aug-2001			
2000-15-51 Paragraph (a)	<b>Aileron Cable Fairlead Tube - Pre-modification Inspection</b>						RE (-)		Mandatory	
27 A/F Eff: 14-Aug-2000 Not Applicable						Mos Hrs Ldg	23-Aug-2001			
2000-15-51 Paragraph (b)	<b>Aileron Cable Fairlead Tube - Modification</b>						RE (-)		Mandatory	
27 A/F Eff: 14-Aug-2000 Not Applicable						Mos Hrs Ldg	23-Aug-2001			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							Due	Remaining
2000-15-51	Paragraph (c) Aileron Cable Fairlead Tube - Post-modification Inspection						RE (-)		Mandatory	
	27 A/F Eff: 14-Aug-2000 Not Applicable					Mos	23-Aug-2001			
<b>▼ 30 - ICE AND RAIN PROTECTION</b>										
2012-06-01	To Prevent Ice Accumulation on the Cables and Pulleys of the Stinger						RE (-)		Mandatory	
	30 A/F Eff: 25-Apr-2012 Complied With SB:560XL-53-16					Mos	11-Apr-2012			
	COMPLETED BY SB560XL-53-16 AND ASL560XL-53-08 INSTALLED					Hrs	3542:12			
						Ldg	2,698			
98-04-38	AFM - Limitations Section - Icing						RE (-)		Mandatory	
	30 A/F Eff: 25-Mar-1998 Not Applicable (UPDATE NOTE: NO PNEUMATIC DEICING BOOTS INSTALLED)					Mos	23-Aug-2001			
	NO PNEUMATIC DEICING BOOTS INSTALLED					Hrs				
						Ldg				
<b>▼ 32 - LANDING GEAR</b>										
2012-09-01	To Prevent Brake Failure, Which Could Result in an Airplane Not Being Able to Stop on the Runway						RE (-)		Mandatory	
	32 A/F Eff: 07-Jun-2012 Complied With AD:2012-09-01					Mos	01-Mar-2013			
	COMPLETED BY SB560XL-32-41 R.0					Hrs	3654:48			
						Ldg	2,768			
G-004-09-83	SUPERSEDED BY CAA UK AD 017-11-83						T (-)		Mandatory	
	32 A/F Eff: 12-Dec-1983 Superseded					Mos				
						Hrs				
						Ldg				
G-005-09-83	SUPERSEDED BY CAA UK AD 016-11-83						T (-)		Mandatory	
	32 A/F Eff: 12-Dec-1983 Superseded					Mos				
						Hrs				
						Ldg				
G-013-08-90	SUPERSEDED BY CAA UK AD 009-02-93						T (-)		Mandatory	
	32 A/F Eff: 20-Jan-1993 Superseded					Mos				
						Hrs				
						Ldg				
<b>▼ 33 - LIGHTS</b>										
2001-14-09	Wiring of the Landing Light Switch and the J-Box Fairing Light Relays						RE (-)		Mandatory (Appliance AD)	
	33 A/F Eff: 26-Jul-2001 Not Applicable					Mos	23-Aug-2001			
	EQUIPMENT NOT INSTALLED					Hrs	12			
						Ldg				
95-22-01	Aerospace Lighting Corporation Power Units and Power Supplies - Fluorescent Lighting System						RE (-)		Mandatory (Appliance AD)	
	33 A/F Eff: 04-Dec-1995 Not Applicable					Mos	23-Aug-2001			
	EQUIPMENT NOT INSTALLED					Hrs	10			
						Ldg				
(NOTE: COMPLIANCE: Within 30 calendar days of the effective date of this airworthiness directive (AD), accomplish the following: Within 5 flights or 10 flight hours, whichever occurs first, of a cabin fluorescent lighting system components failure, repeat the removal and replacement procedures of paragraph (a)(2) of this AD.)										
<b>▼ 34 - NAVIGATION</b>										
2000-03-09	Residual Ice						RE (-)		Mandatory	
	34 A/F Eff: 03-Apr-2000 Not Applicable					Mos	23-Aug-2001			
						Hrs				
						Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							Due	Remaining
2001-23-17	Garmin GNS 430 units						RE (-)		Mandatory (Appliance AD)	
	34 A/F Eff: 28-Dec-2001 Not Applicable Brand A:9990-2001-23-17	EQUIPMENT NOT INSTALLED					Mos	30-Oct-2002		
							Hrs	490		
							Ldg			
2003-04-06	Inspect Primus Integrated Nav Unit/Revise AFM (SUPERSEDED BY AD 2006- 22-05)						RE (-)		Mandatory (Appliance AD)	
	34 A/F Eff: 11-Mar-2003 Complied With Brand A:9990-2003-04-06	EQUIPMENT NOT INSTALLED					Mos	14-Mar-2003		
							Hrs	601		
							Ldg			
2006-16-18	Sandel Avionics Incorporated - Installing a warning placard on the TAWS/RMI						RE (-)		Mandatory (Appliance AD)	
	34 A/F Eff: 25-Sep-2006 Not Applicable Brand A:9990-2006-16-18	EQUIPMENT NOT INSTALLED					Mos	22-Sep-2006		
							Hrs	2430		
							Ldg			
2006-22-05	Honeywell Primus II RNZ-850/-851 Integrated Navigation Unit (INU) - CANCELLED(SUPERCEDED BY AD 2010-07-02)						RE (-)		Mandatory (Appliance AD)	
	34 A/F Eff: 01-Dec-2006 Superseded SUPERSEDED BY AD 2010-07-02 (UPDATE NOTE: SUPERSEDED BY AD 2010-07-02)	EQUIPMENT NOT INSTALLED					Mos	31-Oct-2006		
							Hrs			
							Ldg			
2007-23-13	Inspect - Adjustment Of Stall Warning System (Superseded by AD2008-26-04)						RE (-)		Mandatory	
	34 A/F Eff: 30-Nov-2007 Superseded SUPERSEDED BY AD 2008-26-04 (UPDATE NOTE: SUPERSEDED BY AD 2008-26-04)	EQUIPMENT NOT INSTALLED					Mos	28-Jan-2009		
							Hrs			
							Ldg			
2010-0003 R02 PARA (1)	Verify Aircraft Type Mode Strapping Code S Set To '0' (Zero) Or '1', As Defined In Rockwell-Collins Service Letter Tdr-94( ) Sil 07-2. (Mandatory)						RE (-)		Mandatory	
	34 A/F Not Applicable	EQUIPMENT NOT INSTALLED, REF. FAA 2014-18-01					Mos	26-Sep-2014		
							Hrs			
							Ldg			
2010-0003 R02 PARA (2)	Exemptions: Dassault Aeroplanes (Mandatory)						RE (-)		Mandatory	
	34 A/F Not Applicable	EQUIPMENT NOT INSTALLED, REF. FAA 2014-18-01					Mos	26-Sep-2014		
							Hrs			
							Ldg			
2010-0003 R02 PARA (3)	Exemptions: Atr 42 And Atr 72 Aeroplanes (Mandatory)						RE (-)		Mandatory	
	34 A/F Not Applicable	EQUIPMENT NOT INSTALLED, REF. FAA 2014-18-01					Mos	26-Sep-2014		
							Hrs			
							Ldg			
2010-0003 R02 PARA (4)	Exemptions: Saab 2000 Aeroplanes (Mandatory)						RE (-)		Mandatory	
	34 A/F Not Applicable	EQUIPMENT NOT INSTALLED, REF. FAA 2014-18-01					Mos	26-Sep-2014		
							Hrs			
							Ldg			
2010-0003 R02 PARA (5)	Exemptions: Bombardier Aerospace (Canadair) Aeroplanes: Cl-600-2B16 (604 Variant) And Cl-600-2B19 (Rj100 And Rj200) (Mandatory)						RE (-)		Mandatory	
	34 A/F Not Applicable	EQUIPMENT NOT INSTALLED, REF. FAA 2014-18-01					Mos	26-Sep-2014		
							Hrs			
							Ldg			
2010-0003 R02 PARA (6)	Exemptions: Cessna Aircraft Company Aeroplanes: Cessna Model 525, 525A, 525B; And Cessna Model 525, 525A, 525B, 560; 560XI (Mandatory)						RE (-)		Mandatory	
	34 A/F Not Applicable	EQUIPMENT NOT INSTALLED, REF. FAA 2014-18-01					Mos	26-Sep-2014		
							Hrs			
							Ldg			
2010-0003 R02 PARA (7)	Exemptions: Piaggio Aero Industries Aeroplanes: P.180 (Avanti) And P.180 (Avanti II) (Mandatory)						RE (-)		Mandatory	
	34 A/F Not Applicable	EQUIPMENT NOT INSTALLED, REF. FAA 2014-18-01					Mos	26-Sep-2014		
							Hrs			
							Ldg			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							Due	Remaining
2010-0003R2	Rockwell Collins - Navigation - Mode S Transponder Aircraft Type Mode Strapping - Check / Modification						RE (-)		Mandatory (Appliance AD)	
34 A/F Eff: 14-Oct-2014 Not Applicable	EQUIPMENT NOT INSTALLED, REF. FAA 2014-18-01					Mos	26-Sep-2014			
						Hrs				
						Ldg				
2010-07-02	Integrated Navigation Units (INUs) - Honeywell Primus II RNZ-850( )/-851( ) (This AD supersedes AD 2006-22-05)						RE (-)		Mandatory (Appliance AD)	
34 A/F Eff: 03-May-2010 Complied With						Mos	23-Apr-2010			
						Hrs	3118			
						Ldg	2,457			
2012-02-08	Aviation Communication & Surveillance Systems (ACSS) Traffic Alert and Collision Avoidance System (TCAS) Units - Navigation					T (Not Installed)			Mandatory (Appliance AD)	
34 A/F Not Applicable	BY INSTALLED P/N, Brand A:9990-2012-02-08 (AVG MAN HRS: 2) (APX COST: 3,040)					Mos	11-Apr-2012			
						Hrs	3542:12			
						Ldg	2,698			
2012-26-15	Honeywell International Inc. - Air Data Pressure Transducers						RE (-)		Mandatory (Appliance AD)	
34 A/F Eff: 24-Jan-2013 Not Applicable	N/A BY INSTALLED UNITSGE Brand A:9990-2012-26-15					Mos	28-Feb-2013			
						Hrs				
						Ldg				
2012-26-15 Par. (g)(1)	Remove Identify Out of Spec ADC, ADM, ADAHRS, and DADC. (Rescinded By Faa 2012-26-15 R1) Affected ADC, ADM, ADAHRS, or DADC						RE (-)		Mandatory (Appliance AD)	
34 A/F Not Applicable	BY INSTALLED UNITSGE					Mos	28-Feb-2013			
						Hrs				
						Ldg				
2012-26-15 Par. (g)(2)	Perform Identify Out Of Spec ADC, ADM, ADAHRS, and DADC. (Rescinded By Faa 2012-26-15 R1) Pitot-Static Certification Test						RE (-)		Mandatory (Appliance AD)	
34 A/F Not Applicable	BY INSTALLED UNITSGE					Mos	28-Feb-2013			
						Hrs	3654:48			
						Ldg	2,768			
2012-26-15 R1	Honeywell International Inc. - Air Data Pressure Transducers (This action rescinds AD 2012-26-15, Amendment 39-17310 (78 FR 1735, January 9, 2013).)						RE (-)		Mandatory (Appliance AD)	
34 A/F Eff: 03-Dec-2014 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	04-Nov-2014			
						Hrs				
						Ldg				
2014-05-27	Rockwell Collins, Inc - Navigation - TPR-720 and TPR-900 Mode S transponders test and calibration						RE (-)		Mandatory (Appliance AD)	
34 A/F Eff: 02-May-2014 Not Applicable	NOT INSTALLED					Mos	29-Apr-2014			
						Hrs	3843:30			
						Ldg	2,877			
2014-18-01	Rockwell Collins, Inc. - Navigation - inspect the airplane type code category strapping setting for a value of zero (0) or one (1) following Rockwell Collins, Inc. Service Information Letter 07-2, 523-0810069-101000, TDR-94() SIL 07-02.						RE (-)		Mandatory (Appliance AD)	
34 A/F Eff: 14-Oct-2014 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	12-Sep-2014			
						Hrs				
						Ldg				
2015-0093	NORTHROP GRUMMAN LITEF GmbH - Navigation - Attitude Heading Reference System - Modification / Replacement						RE (-)		Mandatory (Appliance AD)	
34 A/F Eff: 10-Jun-2015 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	01-Jun-2015			
						Hrs				
						Ldg				
2015-0093 Paragraph (1)	NORTHROP GRUMMAN LITEF GmbH- Navigation - Attitude Heading Reference System - AFM Amendment						RE (-)		Mandatory (Appliance AD)	
34 A/F Eff: 10-Jun-2015 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	01-Jun-2015			
						Hrs				
						Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							Due	Remaining
2015-0093 Paragraph (2)	NORTHROP GRUMMAN LITEF GmbH - Navigation - Attitude Heading Reference System - Modification / Replacement						RE (-)		Mandatory (Appliance AD)	
34 A/F Eff: 10-Jun-2015 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	01-Jun-2015			
						Hrs				
						Ldg				
2015-0093 Paragraph (3)	NORTHROP GRUMMAN LITEF GmbH - Navigation - Attitude Heading Reference System - Concurrent with modification of an aircraft as required by paragraph (2) of this AD, the AFM change, if required by paragraph (1) of this AD (see Note 1 of this AD), can be removed from that aircraft.						RE (-)		Mandatory (Appliance AD)	
34 A/F Eff: 10-Jun-2015 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	01-Jun-2015			
						Hrs				
						Ldg				
2015-0093 Paragraph (4)	Do Not Install On Any Aircraft A Lcr-100 Ahrs Unit, Having A P/N Specified As 'Old' In Table 1 Of This Ad						RE (-)		Mandatory (Appliance AD)	
34 A/F Not Applicable	EQUIPMENT NOT INSTALLED					Mos	01-Jun-2015			
						Hrs				
						Ldg				
2015-10-51	Avidyne Integrated Flight Display (IFD) - Navigation - Incorporate Operational Limitations into Airplane Flight Manual (AFM) or Airplane Flight Manual Supplement (AFMS) Limitation.						RE (-)		Mandatory (Appliance AD)	
34 A/F Not Applicable Brand A:9990-2015-10-51	EQUIPMENT NOT INSTALLED					Mos				
						Hrs				
						Ldg				
2015-10-51-E	EMERGENCY AD - Avidyne Integrated Flight Display (IFD) - Navigation - Incorporate Operational Limitations into Airplane Flight Manual (AFM) or Airplane Flight Manual Supplement (AFMS) Limitation						RE (-)		Mandatory (Appliance AD)	
34 A/F Eff: 18-May-2015 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	18-May-2015			
						Hrs				
						Ldg				
2017-04-06	Altimeter - United Instruments Model 5934 Series - Slow Diaphragm Leak						RE (-)		Mandatory (Appliance AD)	
34 A/F Eff: 07-Apr-2017 Not Applicable	AIRCRAFT NOT EQUIPPED WITH THIS KIND OF ALTIMETER					Mos				
						Hrs				
						Ldg				
(AVG MAN HRS: 1) (NOTE: APPLICABILITY: This AD applies to United Instruments, Inc. 5934 series altimeters that were manufactured between January 2015 and February 2016 and installed in airplanes and helicopters. NOTE: Refer to United Instruments, Inc. Service Bulletin No. 13, dated March 25, 2016.)										
2017-22-14	Navigation - Upgrade the Rockwell Collins, Inc. TSSA-4100 FLS to RCPN 810-0052-013 or 810-0052-102						RE (-)		Mandatory (Appliance AD)	
34 A/F Eff: 20-Dec-2017 Not Applicable	AIRCRAFT NOT EQUIPPED WITH THIS SYSTEM					Mos				
						Hrs				
						Ldg				
(AVG MAN HRS: 1) (NOTE: NOTE: Refer to Rockwell Collins Service Information Letter, TSSA-4100-SIL-10-1, Revision No. 9, dated March 31, 2017; or Rockwell Collins Service Information Letter TSSA-4100-SIL-10-1, Revision No. 10, dated July 10, 2017.)										
2018-0247	Navigation - Transponders - Inspection / Modification						RE (-)		Mandatory (Appliance AD)	
34 A/F Eff: 27-Nov-2018 Not Applicable	AIRCRAFT NOT EQUIPPED WITH THIS KIND OF TRANSPONDERS					Mos				
						Hrs				
						Ldg				
(NOTE: APPLICABILITY: Trig Avionics TT31 Mode S transponders, P/N 00220-00-01, S/N 05767 to 09715 inclusive, except those having modification (mod) level 7 or higher embodied.)										
2018-03-04	Airspeed/Mach Indicator - Pitot Probe - Inspect/ Replace						RE (-)		Mandatory (Appliance AD)	
34 A/F Eff: 16-Mar-2018 Not Applicable	Not Equipped: Aircraft not Equipped with Pitot Tubes Model 851AK from ROSEMOUNT AEROSPACE					Mos				
						Hrs				
						Ldg				
(AVG MAN HRS: 2)										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							Due	Remaining
2019-0004	Navigation - Global Navigation Satellite System - Operational Limitations						RE (-)		Mandatory (Appliance AD)	
 34 A/F Eff: 25-Jan-2019 Not Applicable	AIRCRAFT NOT EQUIPPED WITH THIS KIND OF GPS					Mos				
						Hrs				
						Ldg				
2019-0179R1	Navigation - Airborne Collision Avoidance System Display Software - Update						RE (-)		Mandatory	
 34 A/F Eff: 24-Apr-2020 Not Applicable	AIRCRAFT NOT EQUIPPED WITH ROCKWELL COLLINS FDFA					Mos				
						Hrs				
						Ldg				
2019-07-10	Attitude and Directional Data System						RE (-)		Mandatory (Appliance AD)	
 34 A/F Eff: 29-May-2019 Not Applicable	AIRCRAFT NOT EQUIPPED WITH THESE KINDS OF AHRS					Mos				
						Hrs				
						Ldg				
2019-12-09	Navigation - Rockwell Collins, Inc. (Rockwell Collins) Flight Display System Application FDSA-6500 - Revise AFM/ Fabricate Placard (Superseded by AD 2021-05-17)						RE (-)		Mandatory (Appliance AD)	
 34 A/F Eff: 23-Jul-2019 Not Applicable	AIRCRAFT NOT EQUIPPED WITH ROCKWELL PROLINE FUSION SYSTEM - SUPERSEDED BY AD 2021-05-17					Mos				
						Hrs				
						Ldg				
	(NOTE: This AD applies to Rockwell Collins, Inc. (Rockwell Collins) Flight Display System Application FDSA-6500, P/N 810-0234-1H0001, 810-0234-1H0002, 810-0234-1H0003, 810-0234-2H0001, 810-0234-2C0001, 810-0234-2C0002, and 810-0234-4B0001.)									
2019-13-03	ATC Transponder System - Trig Avionics Limited TT31 Mode S Transponders/ Avidyne Corporation AXP340 Mode S Transponders / BendixKing/Honeywell International KT74 Mode S Transponders - Inspection						RE (-)		Mandatory (Appliance AD)	
 34 A/F Eff: 27-Aug-2019 Not Applicable	AIRCRAFT NOT EQUIPPED WITH THIS KIND OF TRANSPONDERS					Mos				
						Hrs				
						Ldg				
	(NOTE: This AD applies to: (1) Trig Avionics Limited TT31 Mode S transponders, part number (P/N) 00220-00-01 and P/N 00225-00-01, with a serial number (S/N) from 05767 to S/N 09715 inclusive, and Modification (Mod) Level 6 or below, installed. (2) Avidyne Corporation AXP340 Mode S transponders, P/N 200-00247-0000, also marked with Trig Avionics P/N 01155-00-01, with a S/N from 00801 to S/N 01377 inclusive, and Mod Level 0, installed. (3) BendixKing/Honeywell International KT74 Mode S transponders, P/N 89000007-002001, also marked with Trig Avionics P/N 01157-00-01, with a S/N from 01143 to S/N 02955 inclusive, and Mod Level 0, installed.)									
2020-08-02	Global Positioning System - Thales GPS/SBAS Receivers						RE (-)		Mandatory (Appliance AD)	
 34 A/F Eff: 19-May-2020 Not Applicable	AIRCRAFT NOT EQUIPPED WITH THALES AVS FRANCE SAS (THALES) GLOBAL POSITIONING SYSTEM/SATELLITE BASED AUGMENTATION SYSTEM (GPS/SBAS) RECEIVERS, TOPSTAR 200 LPV, PART NUMBERS (P/NS) C17149JA02 AND C17149HA01					Mos				
						Hrs				
						Ldg				
2020-10-05	Flight Management Computing Hardware System - Rockwell Collins Pro Line 4 and Pro Line 21 Flight Management Systems						RE (-)		Mandatory (Appliance AD)	
 34 A/F Eff: 24-Jun-2020 Not Applicable	DUE TO THE SAID ITEM IS NOT INSTALLED IN THIS AIRCRAFT 560XL-5183.					Mos	17-Jun-2021			
						Hrs	5979:12			
						Ldg	3,951			
2020-16-08	Flight Environment Data, Attitude and Direction Data System						RE (-)		Mandatory (Appliance AD)	
 34 A/F Eff: 16-Aug-2020 Not Applicable	INSTALLED HONEYWELL PFD & MFD					Mos				
						Hrs				
						Ldg				
	(NOTE: (1) Before further flight, revise the limitations section of the airplane flight manual (AFM) for your airplane by inserting a copy of this AD or by making a pen and ink change to add: "Operation under Instrument Flight Rules (IFR) or night Visual Flight Rules (VFR) is prohibited.")									

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories Due	Time Remaining
SEQ	PN/SN	MOC Note or Component Condition								
2020-18-51	Attitude and Direction Data System - BendixKing/Sandia						RE (-)		Mandatory (Appliance AD)	
	34 A/F					Mos				
	Eff: 28-Aug-2020 Not Applicable	AIRCRAFT NOT EQUIPPED WITH BENDIX KING KI-300 OR SANDIA MODEL SAI-340A				Hrs				
	(NOTE: (1) Before further flight, revise the limitations section of the existing Airplane Flight Manual (AFM) for your airplane by inserting a copy of this AD or by making a pen and ink change to add:)					Ldg				
2020-18-51-E	Attitude and Direction Data System						RE (-)		Mandatory (Appliance AD)	
	34 A/F					Mos				
	Eff: 27-Aug-2020 Not Applicable	AIRCRAFT NOT EQUIPPED WITH BENDIX KING KI-300 OR SANDIA MODEL SAI-340A				Hrs				
	(NOTE: Applicability: This AD applies to Sandia attitude indicator (attitude indicator) part number (P/N) 306171-10 or 306171-20. These attitude indicators may be marked as BendixKing Model KI-300 or Sandia Model SAI-340A. They may be installed on airplanes certificated in any category.)					Ldg				
2021-05-17	Navigation System - Rockwell Collins, Inc. (Rockwell Collins) Flight Display System Application FDSA-6500						RE (-)		Mandatory (Appliance AD)	
	34 A/F					Mos				
	Eff: 29-Apr-2021 Not Applicable	AIRCRAFT NOT EQUIPPED WITH COLLINS FDSA-6500 FLIGHT DISPLAY SYSTEM				Hrs				
	(NOTE: Applicability: This AD applies to Rockwell Collins, Inc. (Rockwell Collins) Flight Display System Application FDSA-6500 part numbers (P/Ns) 810-0234-1H0001, 810-0234-1H0002, 810-0234-1H0003, 810-0234-2H0001, 810-0234-2C0001, 810-0234-2C0002, and 810-0234-4B0001.)					Ldg				
2021-08-07	Navigation System - GPS-4000S Global Positioning System						RE (-)		Mandatory (Appliance AD)	
	34 A/F					Mos				
	Eff: 12-May-2021 Not Applicable	AIRCRAFT NOT EQUIPPED WITH GPS-4000S PART NIMBER 822-2189-100				Hrs				
	(NOTE: Applicability: This AD applies to Rockwell Collins, Inc. GPS-4000S Global Positioning System (GPS) part number (P/N) 822-2189-100 installed on airplanes, certificated in any category.)					Ldg				
2021-08-15	Garmin International GMN-00962 GTS Processor Units						RE (-)		Mandatory (Appliance AD)	
	34 A/F					Mos				
	Eff: 17-May-2021 Not Applicable	AIRCRAFT NOT EQUIPPED WITH GARMIN INTERNATIONAL GMN-00962 GTS PROCESSOR UNITS, PART NUMBER 011-02571-0() MARKETED AS THE GTS 825, GTS 855, OR GTS 8000				Hrs				
	(NOTE: Required Action and Compliance: Within 24 months after the effective date of this AD, update the GTS processor software to a version that is not 3.13 or earlier, except 3.12.1. Software version 3.12.1 does not contain the unsafe condition.)					Ldg				
2021-23-12	Indicating/Recording System, Navigation - Radio Altimeter (Transport and Commuter Category Airplanes) (This AD is Superseded by FAA AD 2023-10-02)						RE (-)		Mandatory (Appliance AD)	
	34 A/F					Mos	09-Feb-2022			
	Eff: 03-Jan-2022 Complied With	TEXT ADDED TO AFM				Hrs				
	(UPDATE NOTE: TEXT ADDED TO AFM) (NOTE: COMPLIANCE: On or before January 4, 2022: Revise the Limitations Section of the existing AFM by incorporating the limitations specified in figure 1 to paragraph (g) of this AD. This may be done by inserting a copy of this AD into the existing AFM.)					Ldg				
2022-0024	Navigation - Flight Management Computer 2 / Navigation Modules - Operational Limitations / Amendment						RE (-)		Mandatory (Appliance AD)	
	34 A/F					Mos	04-Feb-2022			
	Eff: 18-Feb-2022 Not Applicable	P/N NOT INSTALLED				Hrs				
	(UPDATE NOTE: P/N NOT INSTALLED) (NOTE: APPLICABILITY: Thales Flight Management Computer (FMC) 2 Navigation Modules (NAVM), identified by Part Number C13084CA03. These FMC2 NAVM are known to be installed on, but not limited to, Dassault (formerly Bréguet) Br.1150 Atlantique 2 (ATL2) maritime patrol aeroplanes.)					Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories Due	Time Remaining
SEQ	PN/SN									
2023-10-02	<b>Navigation - Radio Altimeters (This AD Replaces AD 2021-23-12)</b>						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	07-Jun-2023			
Eff: 26-May-2023 Not Applicable	REFER TO EASA POSITION ON FAA AD					Hrs	6518:05			
						Ldg	4,313			
	(NOTE: APPLICABILITY: This AD applies to all transport and commuter category airplanes equipped with a radio (also known as radar) altimeter. These radio altimeters are installed on various transport and commuter category airplanes including, but not limited to, the airplanes for which the design approval holder is identified in paragraphs (c)(1) through (18) of this AD. (1) The Boeing Company (2) Airbus SAS (3) Bombardier Inc.(4) Embraer S.A. (including type certificates previously held by Yaborá Indústria Aeronáutica S.A., which are now held by Embraer S.A.) (5) Gulfstream Aerospace Corporation (6) Textron Aviation Inc. (8) Pilatus Aircraft Limited (9) Fokker Services B.V. (10) Saab AB, Support and Services (11) DeHavilland Aircraft of Canada Limited (12) Airbus Canada Limited Partnership (13) ATR-GIE Avions de Transport Régional (14) MHI RJ Aviation ULC (15) BAE Systems (Operations) Limited (16) Lockheed Martin Corporation/Lockheed Martin Aeronautics Company (17) Viking Air Limited (18) Dassault Aviation)									
2023-10-02 Par. (h)	<b>Navigation - Radio Altimeters - Airplane Flight Manual (AFM) Revision Until June 30, 2023</b>						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	07-Jun-2023			
Eff: 25-May-2023 Not Applicable						Hrs	6518:05			
	(NOTE: COMPLIANCE: For non-radio altimeter tolerant airplanes, before further flight, revise the Limitations Section of the existing AFM to include the information specified in figure 3 to paragraph (h) of this AD. This may be done by inserting a copy of figure 3 to paragraph (h) of this AD into the existing AFM. If an operator has complied with paragraph (g) of AD 2021-23-12, that action satisfies the requirements of this paragraph.)					Ldg	4,313			
2023-10-02 Par. (i)	<b>Navigation - Radio Altimeters - AFM Revision After June 30, 2023</b>						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	07-Jun-2023			
Eff: 29-Jun-2023 Not Applicable	REFER TO EASA POSITION ON THIS FAA AD					Hrs	6518:05			
						Ldg	4,313			
	(NOTE: COMPLIANCE: On or before June 30, 2023, revise the Limitations Section of the existing AFM to include the information specified in figure 4 to paragraph (i) of this AD. This may be done by inserting a copy of figure 4 to paragraph (i) of this AD into the existing AFM. Incorporating the AFM revision required by this paragraph terminates the AFM revision required by paragraph (h) of this AD. (2) Before further flight after incorporating the limitations specified in figure 4 to paragraph (i) of this AD, remove the AFM revision required by paragraph (h) of this AD.)									
2023-21-05	<b>Navigation - Thales AVS France SAS Flight Management Computer Navigation Modules (FMC2 NAVM)</b>						RE (Not Installed)		Mandatory (Appliance AD)	
34 A/F						Mos	12-Dec-2023			
Not Applicable	N/A PART NOT INSTALLED					Hrs				
						Ldg				
2023-21-05 Par. (g)(1)	<b>Navigation - Thales AVS France SAS Flight Management Computer Navigation Modules (FMC2 NAVM) - Revise the Limitations Section of the Existing Airplane Flight Manual</b>						T (Not Installed)		Mandatory (Appliance AD)	
34 A/F						Mos	12-Dec-2023			
Not Applicable	N/A PART NOT INSTALLED					Hrs				
						Ldg				
2023-21-05 Par. (g)(2)	<b>Navigation - Thales AVS France SAS Flight Management Computer Navigation Modules (FMC2 NAVM) - Update the Database for Thales FMC2 NAVM - P/N C13084CA03</b>						T (Not Installed)		Mandatory (Appliance AD)	
34 A/F						Mos	12-Dec-2023			
Not Applicable	N/A P/N NOT INSTALLED					Hrs				
						Ldg				
94-01-04	<b>Traffic Alert and Collision Avoidance System (TCAS) II computer units; part numbers 4066010-901, -902, and -903;</b>						RE (-)			
34 A/F						Mos				
Not Applicable	P/N NOT INSTALLED					Hrs				
						Ldg				
96-24-06	<b>Icing Condition or Ice on the Wing Addition to AFM (Superseded by AD 2000-03-09)</b>						RE (-)		Mandatory	
34 A/F						Mos	23-Aug-2001			
Eff: 05-Dec-1996 Superseded	SUPERSEDED BY 2000-03-09					Hrs				
						Ldg				
97-05-03 R1	<b>AlliedSignal Avionics, Inc. Models GNS-XLS and GNS-XL Flight Management Systems</b>						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	23-Aug-2001			
Eff: 20-Apr-1999 Not Applicable	EQUIPMENT NOT INSTALLED					Hrs	10			
						Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							Due	Remaining
98-25-02	SKYWATCH SKY497 Installations with a Top-Mounted Antenna						RE (-)			
	34 A/F					Mos				
	Not Applicable	EQUIPMENT NOT INSTALLED				Hrs				
						Ldg				
▼ 35 - OXYGEN										
2011-0090 R1	Intertechnique Aircraft Systems - Oxygen - Oxygen Mask Regulator Inflatable Harness - Identification / Replacement						RE (-)		Mandatory (Appliance AD)	
	35 A/F					Mos	07-Dec-2011			
	Eff: 27-Jul-2011 Complied With	COMPLETED				Hrs	3505:12			
						Ldg	2,677			
2011-04-09	CHEMICAL OXYGEN GENERATOR INSTALLED IN LAVATORY - NOT ADOPTED						RE (-)			
	35 A/F					Mos	03-Mar-2011			
	Superseded	SUPERSEDED BY AD 2012-11-09				Hrs				
	(UPDATE NOTE: AD SURESEDED BY AD 2012-11-09)					Ldg				
2011-14-08	B/E Aerospace, Continuous Flow Passenger Oxygen Mask Assembly						RE (-)		Mandatory (Appliance AD)	
	35 A/F					Mos	11-Apr-2012			
	Eff: 19-Aug-2011 Not Applicable	BY PART NUMBER				Hrs	3542:12			
	Brand A:9990-2011-14-08 (AVG MAN HRS: 0.5) (APX COST: 48.5)					Ldg	2,698			
2012-0254	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - Flight Crew Oxygen Mask Regulator - Identification / Operational Procedure / Replacement						RE (-)		Mandatory (Appliance AD)	
	35 A/F					Mos	06-Dec-2012			
	Eff: 29-Nov-2012 Not Applicable	BY PN & SN FOR BOTH PILOT AND COPILOTOXYGEN MASK REGULATOR;L				Hrs	3640:06			
	(UPDATE NOTE: NEW P/N ALREADY INSTALLED)					Ldg	2,760			
2012-0254 Paragraph (1)	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - Flight Crew Oxygen Mask Regulator - Identification						RE (-)		Mandatory (Appliance AD)	
	35 A/F					Mos	06-Dec-2012			
	Eff: 29-Nov-2012 Not Applicable	NEW p/n ALREADY INSTALLED				Hrs	3640			
	(NOTE: BY PN & SN FOR BOTH PILOT AND COPILOTOXYGEN MASK REGULATOR;L)					Ldg	2,760			
2012-0254 Paragraph (2.1)	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - Replace each affected flight crew oxygen mask regulator with a serviceable part, not having a P/N and s/n as listed in Appendix 1 of this AD, or with a part that has passed the test in accordance with the instructions of paragraph 3.A.(4) of intertechnique SB MCF-SBU-35-001.						RE (-)		Mandatory (Appliance AD)	
	35 A/F					Mos	06-Dec-2012			
	Eff: 29-Nov-2012 Not Applicable					Hrs	3640			
						Ldg	2,760			
2012-0254 Paragraph (2.2)	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - Amend the Aircraft Flight Manual (AFM) and install a placard						RE (-)		Mandatory (Appliance AD)	
	35 A/F					Mos				
	Eff: 29-Nov-2012 Not Applicable					Hrs				
						Ldg				
2012-0254 Paragraph (3)	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - replace each affected flight crew oxygen mask regulator with a serviceable part, not having a P/N and s/n as listed in Appendix 1 of this AD, or with a part that has passed the test in accordance with the instructions of paragraph 3.A.(4) of intertechnique SB MCF-SBU-35-001						RE (-)		Mandatory (Appliance AD)	
	35 A/F					Mos	06-Dec-2012			
	Eff: 29-Nov-2012 Not Applicable					Hrs	3640			
						Ldg	2,760			
2012-0254R1	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - Flight Crew Oxygen Mask Regulator - Identification / Operational Procedure / Replacement						RE (-)		Mandatory (Appliance AD)	
	35 A/F					Mos	28-Feb-2013			
	Eff: 21-Dec-2012 Not Applicable	BY P/N INSTALLED				Hrs				
						Ldg				

Task No SEQ PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2012-0254R1 Paragraph (1)	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - Flight Crew Oxygen Mask Regulator - Identification 35 A/F Eff: 21-Dec-2012 Not Applicable BY P/N INSTALLED					Mos Hrs Ldg	RE (-)		Mandatory (Appliance AD)	
2012-0254R1 Paragraph (2.1)	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - Replace each affected flight crew oxygen mask regulator with a serviceable part, not having a P/N and s/n as listed in Appendix 1 of this AD, or with a part that has passed the test in accordance with the instructions of paragraph 3.A.(4) of intertechnique SB MCF-SBU-35-001. 35 A/F Eff: 21-Dec-2012 Not Applicable BY P/N INSTALLED					Mos Hrs Ldg	RE (-)		Mandatory (Appliance AD)	
2012-0254R1 Paragraph (2.2)	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - Amend the Aircraft Flight Manual (AFM) and install a placard 35 A/F Eff: 21-Dec-2012 Not Applicable BY P/N INSTALLED					Mos Hrs Ldg	RE (-)		Mandatory (Appliance AD)	
2012-0254R1 Paragraph (3)	ZODIAC AEROTECHNICS - Intertechnique Aircraft Systems - Oxygen - replace each affected flight crew oxygen mask regulator with a serviceable part, not having a P/N and s/n as listed in Appendix 1 of this AD, or with a part that has passed the test in accordance with the instructions of paragraph 3.A.(4) of Intertechnique SB MCF-SBU-35-001 35 A/F Eff: 21-Dec-2012 Not Applicable BY P/N INSTALLED					Mos Hrs Ldg	RE (-)		Mandatory (Appliance AD)	
2012-11-09 R1	<b>CHEMICAL OXYGEN GENERATORS - AD NOT ADOPTED BY EASA</b> 35 A/F Not Applicable FAA AD NOT ADOPTED BY EASA (UPDATE NOTE: FAA AD NOT ADOPTED BY EASA)					Mos Hrs Ldg	RE (-)			
2014-0142	<b>Oxygen - Oxygen Mask Regulator Inflatable Harness / Inflation Hose - Identification / Replacement</b> 35 A/F Eff: 04-Jun-2014 Not Applicable DUE TO MFD 1117S & 1231S					Mos Hrs Ldg	RE (-)		Mandatory (Appliance AD)	
2014-0142 Paragraph (1)	<b>Oxygen - Oxygen Mask Regulator Inflatable Harness / Inflation Hose - Identification</b> 35 A/F Eff: 04-Jun-2014 Not Applicable DUE TO MFD 1117S & 1231S					Mos Hrs Ldg	RE (-)		Mandatory (Appliance AD)	
2014-0142 Paragraph (2)	<b>Oxygen - Oxygen Mask Regulator Inflatable Harness / Inflation Hose - Replacement</b> 35 A/F Eff: 04-Jun-2014 Not Applicable DUE TO MFD 1117S & 1231S					Mos Hrs Ldg	RE (-)		Mandatory (Appliance AD)	
2014-0142 Paragraph (3)	<b>Accomplish It Is Allowed To Install On An Aeroplane A Flight Crew Oxygen Mask Regulator, Having A P/N As Identified In Section 1.A.(1) Of Zodiac Aerotechnics Sb Mc10-35-274, Provided It Has Been Determined That A P/N Mxh21-31 Inflatable Harness Is Installed, Or That The P/N Mxh21-1 Inflatable Harness Installed On That Flight Crew Oxygen Mask Regulator Has Been Corrected, As Required By This Ad. (Mandatory)</b> 35 A/F Not Applicable DUE TO MFD 1117S & 1231S					Mos Hrs Ldg	RE (-)		Mandatory (Appliance AD)	
2014-0142R1	<b>Oxygen - Oxygen Mask Regulator Inflatable Harness / Inflation Hose - Identification / Replacement</b> 35 A/F Eff: 18-Jun-2014 Not Applicable DUE TO MFD 1117S & 1231S					Mos Hrs Ldg	RE (-)		Mandatory (Appliance AD)	

Task No SEQ	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2014-0142R1 Paragraph (1)	Oxygen - Oxygen Mask Regulator Inflatable Harness / Inflation Hose - Identification  35 A/F Eff: 18-Jun-2014 Not Applicable DUE TO MFD 1117S & 1231S					Mos Hrs Ldg	17-Jul-2014 3904:36 2,912	RE (-)	Mandatory (Appliance AD)	
2014-0142R1 Paragraph (2)	Oxygen - Oxygen Mask Regulator Inflatable Harness / Inflation Hose - Replacement  35 A/F Eff: 18-Jun-2014 Not Applicable DUE TO MFD 1117S & 1231S					Mos Hrs Ldg	17-Jul-2014 3904:36 2,912	RE (-)	Mandatory (Appliance AD)	
2014-0142R1 Paragraph (3)	Accomplish It Is Allowed To Install On An Aeroplane A Flight Crew Oxygen Mask Regulator, Having A P/N As Identified In Section 1.A.(1) Of Zodiac Aerotechnics Sb Mc10-35-274, Provided It Has Been Determined That A P/N Mxh21-31 Inflatable Harness Is Installed, Or That The P/N Mxh20-1 Or P/N Mxh21-1 Inflatable Harness Installed On That Flight Crew Oxygen Mask Regulator Has Been Corrected, As Required By This Ad  35 A/F Not Applicable DUE TO MFD 1117S & 1231S					Mos Hrs Ldg	17-Jul-2014 3904:36 2,912	RE (-)	Mandatory (Appliance AD)	
2015-08-07	Zodiac Aerotechnics (formerly Intertechnique Aircraft Systems) - Oxygen - Flightcrew Oxygen Mask Regulators  35 A/F Eff: 16-Jun-2015 Not Applicable MC10-16-150 MASK REGULATOR NOT AFFECTED					Mos Hrs Ldg	26-May-2015	RE (-)	Mandatory (Appliance AD)	
2015-08-07 Paragraph (g)	Zodiac Aerotechnics (formerly Intertechnique Aircraft Systems) - Oxygen - Flightcrew Oxygen Mask Regulators - Inspection  35 A/F Not Applicable MC10-16-150 MASK REGULATOR NOT AFFECTED (NOTE: [24 MOS Initial Req.])					Mos Hrs Ldg	26-May-2015	RE (-)	Mandatory (Appliance AD)	
2015-08-07 Paragraph (h)	Zodiac Aerotechnics (formerly Intertechnique Aircraft Systems) - Oxygen - Flightcrew Oxygen Mask Regulators - Replacement  35 A/F Not Applicable MC10-16-150 MASK REGULATOR NOT AFFECTED (NOTE: [24 MOS Initial Req.])					Mos Hrs Ldg	26-May-2015	RE (-)	Mandatory (Appliance AD)	
2015-23-09	Oxygen - Zodiac Aerotechnics (Formerly Intertechnique Aircraft Systems) Flight Crew Oxygen Mask Regulators - Inspection / Replacement Of Oxygen Mask Regulators  35 A/F Eff: 28-Dec-2015 Not Applicable BY INSTALLED P/N MC10-16-150					Mos Hrs Ldg	04-Dec-2015 4334:12 3,154	RE (-)	Mandatory (Appliance AD)	
2015-23-09 Para (g)	Oxygen - Inspect Each Flightcrew Oxygen Mask Regulator To Identify The Part Number And Serial Number  35 A/F Eff: 28-Dec-2015 Not Applicable BY INSTALLED P/N MC10-16-150					Mos Hrs Ldg	04-Dec-2015 4334:12 3,154	RE (-)	Mandatory (Appliance AD)	
2015-23-09 Para (h)(1)	Replace Each Affected Flightcrew Oxygen Mask With A Part Identified In Paragraph (H)(1)(i) Or (H)(1)(ii).  35 A/F Not Applicable BY INSTALLED P/N MC10-16-150					Mos Hrs Ldg	04-Dec-2015 4334:12 3,154	RE (-)	Mandatory (Appliance AD)	
2015-23-09 Para (h)(2)(i)	Revise The Emergency Procedures Section Of The Airplane Flight Manual (AFM) By Inserting The Statement Provided In Figure 1  35 A/F Not Applicable BY INSTALLED P/N MC10-16-150					Mos Hrs Ldg	04-Dec-2015 4334:12 3,154	RE (-)	Mandatory (Appliance AD)	
2015-23-09 Para (h)(2)(ii)	Fabricate And Install A Placard On The Flightcrew Oxygen Mask Container That States: "Use Selector On 100% Or Emergency Only."  35 A/F Not Applicable BY INSTALLED P/N MC10-16-150					Mos Hrs Ldg	04-Dec-2015 4334:12 3,154	RE (-)	Mandatory (Appliance AD)	

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							Due	Remaining
2015-23-09 Para (i)	Oxygen - Regulator Replacement						RE (-)		Mandatory (Appliance AD)	
35 A/F Eff: 28-Dec-2015 Not Applicable	BY INSTALLED P/N MC10-16-150					Mos	04-Dec-2015			
						Hrs	4334:12			
						Ldg	3,154			
2016-11-20	Oxygen - Aerospace Protective Breathing Equipment (PBE), part number (P/N) 119003-11						RE (-)		Mandatory (Appliance AD)	
35 A/F Eff: 15-Jul-2016 Not Applicable	AD SUPERSEDED BY AD 2017-18-12					Mos				
						Hrs				
						Ldg				
2017-18-12	Oxygen - B/E Aerospace Protective Breathing Equipment (PBE) Units, P/N 119003-11 and 119003-21 - Inspect/ Replace (This AD replaces AD 2016-11-20)						RE (-)		Mandatory (Appliance AD)	
35 A/F Eff: 16-Oct-2017 Not Applicable (AVG MAN HRS: 2)	AIRCRAFT EQUIPPED WITH PBE MODEL MR-1051N					Mos				
						Hrs				
						Ldg				
2018-21-14	MC10 Series Crew Oxygen Mask Regulators - Inflatable Harness Assembly, P/N MXH20-1 or MXH21-1 - Inspection/ Replacement						RE (-)		Mandatory (Appliance AD)	
35 A/F Eff: 27-Mar-2019 Complied With (UPDATE NOTE: CRS AEROPARTNER 2906/22)						Mos	03-Sep-2022			
						Hrs	5999:12			
						Ldg	3,967			
2018-21-14 Par. (g)(1)	MC10 Series Crew Oxygen Mask Regulators - Inflatable Harness Assembly, P/N MXH20-1 or MXH21-1 - Inspection						RE (-)		Mandatory (Appliance AD)	
35 A/F Eff: 27-Mar-2019 Complied With (UPDATE NOTE: CRS AEROPARTNER 2906/22) (NOTE: NOTE: Refer to Zodiac Aerospace Service Bulletin (SB) MC10-35-274, Revision 02, dated June 25, 2014.)						Mos	03-Sep-2022			
						Hrs	5999:12			
						Ldg	3,967			
2018-21-14 Par. (g)(2)	MC10 Series Crew Oxygen Mask Regulators - Inflatable Harness Assembly, P/N MXH20-1 or MXH21-1 - Replacement						RE (-)		Mandatory (Appliance AD)	
35 A/F Eff: 27-Mar-2019 Complied With (UPDATE NOTE: CRS AEROPARTNER 2906/22) (NOTE: NOTE: Refer to Zodiac Aerospace Service Bulletin (SB) MC10-35-274, Revision 02, dated June 25, 2014.)						Mos	03-Sep-2022			
						Hrs	5999:12			
						Ldg	3,967			
2018-21-14 Par.(h)	MC10 Series Crew Oxygen Mask Regulators - Inflatable Harness Assembly, P/N MXH20-1 or MXH21-1 - Installation Prohibition						RE (-)		Mandatory (Appliance AD)	
35 A/F Eff: 27-Mar-2019 Complied With (UPDATE NOTE: CRS AEROPARTNER 2906/22) (NOTE: This AD applies to Zodiac Aerotechnics (Zodiac) MC10 series crew oxygen mask regulators fitted with an inflatable harness assembly, part number (P/N) MXH20-1 or MXH21-1.)						Mos	03-Sep-2022			
						Hrs	5999:12			
						Ldg	3,967			
2023-13-11	Oxygen - AVOX Systems Inc. (Formerly Scott Aviation) Oxygen Cylinder and Valve Assemblies (Supersedes FAA AD 2022-04-09)						T (Not Installed)		Mandatory (Appliance AD)	
35 A/F Not Applicable AD:2022-04-09	N/A BY P/N AND MANUFACTURER					Mos				
						Hrs				
						Ldg				
99-08-21	Puritan-Bennett Aero Systems Company C351-2000 Series Passenger Oxygen Masks and Portable Oxygen Masks - Passenger Oxygen Masks						RE (-)		Mandatory (Appliance AD)	
35 A/F Eff: 02-Jun-1999 Not Applicable Brand A:9990-1999-08-21	EQUIPMENT NOT INSTALLED					Mos	23-Aug-2001			
						Hrs	10			
						Ldg				
▼ 72 - ENGINE										
2010-18-09	Bleed valve/servo valve						RE (-)		Mandatory	
72 ENG1 Eff: 10-Sep-2010 Complied PREVIOUSLY With						Mos	19-Sep-2017			
						Hrs				
						Enc				
2010-18-09	Bleed valve/servo valve						RE (-)		Mandatory	
72 ENG2 Eff: 10-Sep-2010 Not Applicable						Mos	27-Sep-2017			
						Hrs	4972:48			
						Enc	3,474			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							Due	Remaining
<b>▼ 73 - ENGINE - FUEL AND CONTROL</b>										
2003-03-21	Flexible Fuel Tubes							RE (-)		Mandatory
	73 ENG1					Mos	19-Sep-2017			
	Eff: 20-Feb-2003 Not Applicable					Hrs				
						Enc				
2003-03-21	Flexible Fuel Tubes							RE (-)		Mandatory
	73 ENG2					Mos	27-Sep-2017			
	Eff: 20-Feb-2003 Not Applicable					Hrs	4972:48			
						Enc	3,474			
CF-2002-42	Inspection of Flexible Fuel Tubes							RE (-)		Mandatory
	73 ENG1					Mos	19-Sep-2017			
	Not Applicable					Hrs				
						Enc				
CF-2002-42	Inspection of Flexible Fuel Tubes							RE (-)		Mandatory
	73 ENG2					Mos	27-Sep-2017			
	Not Applicable					Hrs	4972:48			
						Enc	3,474			
<b>▼ 75 - BLEED AIR</b>										
CF-2010-19	Intercompressor Bleed Valve/Servo Valve Malfunction							RE (-)		Mandatory
	75 ENG1					Mos	19-Sep-2017			
	Eff: 22-Jul-2010 Complied	PREVIOUSLY				Hrs				
	With					Enc				
CF-2010-19	Intercompressor Bleed Valve/Servo Valve Malfunction							RE (-)		Mandatory
	75 ENG2					Mos	27-Sep-2017			
	Eff: 22-Jul-2010 Complied	PREVIOUSLY				Hrs	4972:48			
	With					Enc	3,474			
<b>▼ 76 - ENGINE CONTROLS</b>										
2020-26-05	Power Lever - Throttle Quadrant Inspection							RE (-)		Mandatory
	76 A/F					Mos				
	Eff: 17-Dec-2020 Not	BY AIRCRAFT SERIAL NUMBER				Hrs				
	Applicable					Ldg				