

# LISTE DES CONSIGNES DE NAVIGABILITE APPLIQUEES

SECTION: AIRFRAME

AIRCRAFT: HB-ZRO

Type: AIRBUS HELICOPTERS / EUROCOPTER, EC120 B / H120 B (R.508)

N° série: 1690

| N° AD       | N° Origine           | N° SB                           | Interval | Titre                                                            | Remarque      | Fait le:   | Fait par:                 |
|-------------|----------------------|---------------------------------|----------|------------------------------------------------------------------|---------------|------------|---------------------------|
| HB 1999-013 | FAA 98-25-10         |                                 |          | AIRCRAFT BELTS,INC/SEAT RESTRAINT SYSTEM-LOCKING MECHANISM/INSP. | N/A by s/s    | 25.01.2018 | <b>SHM</b>                |
| HB 1999-329 | DGAC 1999-151-001    | SB EC120 01-001                 |          | TAIL GEARBOX/INSP;REPLMNT.IF NECESSARY.                          | N/A by s/s    | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 1999-543 | DGAC 1999-349-002 R1 | TS EC120 05-001                 | 10h      | ENGINE-TO-MAIN GEAR BOX COUPLING/REPET.INSP.                     | N/A by s/s    | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2000-023 | FAA 98-25-10 R1      |                                 |          | AIRCRAFT BELTS,INC/SEAT RESTRAINT SYSTEM-LOCKING MECHANISM/INSP. | N/A by part   | 25.01.2018 | <b>SHM</b>                |
| HB 2000-093 | DGAC 1999-349-002 R2 | BS EC120 05-001                 | 10h      | ENGINE-TO-MAIN GEAR BOX COUPLING/REPET.INSP.                     | N/A by s/s    | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2000-298 | DGAC 2000-176-004    | TS EC120 05-003                 |          | ENGINE TO MAIN GEAR BOX COUPLING TUBE ASSY.                      | N/A by s/s    | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2000-327 | DGAC 2000-058-003    | SB EC120 01-002                 |          | ENGINE-TO-MAIN GEARBOX COUPLING TUBE                             | N/A by s/s    | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2000-348 | DGAC 2000-285-005    | TS RC120 05-005                 |          | CABIN SLIDING DOOR                                               | N/A by s/s    | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2000-404 | DGAC 2000-176-004 R1 | BS EC120 05-003                 |          | ENGINE TO MAIN GEAR BOX COUPLING TUBE ASSY                       | N/A by s/s    | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2000-477 | DGAC 2000-451-006    | AFM RR5B                        |          | FUEL ANTI-ICING ADDITIVE/AFM REVISION                            | N/A by date   | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2001-162 | DGAC 2000-285-005 R1 | ASB EC120 52A004                |          | CABIN SLIDING DOOR/ADJUSTM.;MODIF.                               | N/A by s/s    | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2001-446 | DGAC 2000-285-005 R2 | ASB EC120 05A005 R1 / 52A004 R1 |          | CABIN SLIDING DOOR/ADJUST.;MODIF.                                | N/A by date   | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2001-522 | DGAC 2001-318        | AS350 ASB 01.00.49              |          | SIREN LOAD RELEASE UNITS/REPET.INSP.                             | Cancelled     | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2001-627 | DGAC 2001-373-008    | ASB EC120 67A003                | 50h      | STICK YOKES-TORQUE TUBE/REPET.INSP.                              | N/A by serial | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2002-041 | DGAC 2000-058-003 R1 | ASB EC120 04A002                |          | ENGINE-TO-MGB COUPLING TUBE-COMPONENTS/LIMIT.                    | N/A by date   | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2002-040 | DGAC 1999-151-001 R1 | ASB EC120 04A001                |          | TAIL GEARBOX/INSP;REPLMNT.                                       | N/A by date   | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2002-039 | DGAC 2001-386-007    | ASB EC120 67A005                |          | YAW CONTROL/INSTAL.                                              | N/A by s/s    | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2002-042 | DGAC 2000-176-004 R2 | ASB EC120 05A003                |          | ENGINE-TO-MAIN GEAR BOX COUPLING TUBE ASSY                       | N/A by s/s    | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |

## LISTE DES CONSIGNES DE NAVIGABILITE APPLIQUEES

|             |                      |                                   |                                                          |             |            |                           |
|-------------|----------------------|-----------------------------------|----------------------------------------------------------|-------------|------------|---------------------------|
| HB 2002-143 | DGAC 2001-386-007 R1 | ASB EC120 67A00 / TA EC120 67A007 | YAW CONTROL/INSTAL.                                      | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2002-468 | DGAC 2002-282-009    | TA EC120 34A006                   | HORIZONTAL SITUATION INDICATOR KI525A/IDENT.             | N/A by s/s  | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2002-469 | DGAC 2002-371-010    | TA EC120 67A008                   | CYCLIC PITCH CONTROL STICKS/MODIF.                       | N/A by s/s  | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2002-705 | DGAC 2002-606        | TA EC120 67A009                   | COLLECTIVE PITCH LEVER FRICTION/MODIF;CHECK              | N/A by s/s  | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2003-408 | DGAC 2003-325 COR    | ASB EC120 05A003 R2 / 04A005      | ENGINE TO MGB-COUPLING TUBE ASSEMBLY/INSP.               | N/A by s/s  | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2003-407 | DGAC 2003-322        | AS350 ASB 67.00.25                | FLIGHT CONTROL STOP SCREWS-STOPS/INSP;SEALING            | N/A by s/s  | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2003-590 | DGAC 2003-465        | TA EC120B 65A004                  | TAIL ROTOR DRIVE SHAFT HALF-CLAMPS/INSP.                 | N/A by s/s  | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2004-079 | DGAC 2004-026        | TA EC120 67A014                   | COLLECTIVE TORQUE TUBE/INSP.                             | N/A by s/s  | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2004-097 | DGAC 2003-465 R1     | TA EC120 65A004 R1                | TAIL ROTOR DRIVE SHAFT HALF-CLAMPS/INSP.                 | N/A by s/s  | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2004-135 | DGAC 2002-282-009 R1 | ASB EC120 34A006                  | HORIZONTAL SITUATION INDICATOR KI525A/IDENT.             | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2004-204 | DGAC 2003-325 R1     | ASB 05A003 R3/005 SB 71.003/005   | ENGINE TO MGB-COUPLING TUBE ASSEMBLY/INSP.               | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2004-202 | DGAC 2004-059        | ASB EC120 67A011                  | PILOT'S CYCLIC STICK-THRUST WASHERS/REPLMNT.             | N/A by s/s  | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2004-203 | DGAC 2002-371-010 R1 | ASB EC120 67A008                  | CYCLIC PITCH CONTROL STICKS/MODIF.                       | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2004-306 | DGAC 2003-322 R1     | AS350 ASB 67.00.25                | FLIGHT CONTROL STOP SCREWS-STOPS/INSP;SEALING            | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2005-154 | DGAC 2002-606 R1     | ASB EC120 67A009                  | COLLECTIVE PITCH LEVER FRICTION/MODIF;CHECK              | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2005-267 | DGAC 2005-086        | ASB EC120 67A014                  | FLIGHT CONTROLS-COLLECTIVE TORQUE TUBE/INSP.             | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2005-256 | DGAC 2005-076        | TA EC120 05A006                   | TAIL ROTOR DRIVE SHAFT-FRICTION RING/INSP.               | N/A by s/s  | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2005-356 | DGAC 2003-465 R2     | ASB EC120B 65A004                 | TAIL ROTOR DRIVE SHAFT DAMPER-HALF-CLAMPS                | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2006-053 | DGAC 2006-040        | TA EC120 04A006                   | SPHERICAL THRUST BEARINGS/NONE-AIRWORTHINESS DECLARATION | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2006-073 | DGAC 2005-175        | ASB EC120 67A011 R1               | PILOTS CYCLIC STICK-THRUST WASHERS/REPLMNT.              | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |
| HB 2006-253 | EASA 2006-0093       | ASB EC120 76A006                  | TWIST GRIP ASSEMBLY                                      | N/A by s/s  | 23.01.2015 | <b>AIRBUS HELICOPTERS</b> |

## LISTE DES CONSIGNES DE NAVIGABILITE APPLIQUEES

|                       |                       |                               |      |                                                                                                     |             |            |                            |
|-----------------------|-----------------------|-------------------------------|------|-----------------------------------------------------------------------------------------------------|-------------|------------|----------------------------|
| HB 2006-480           | EASA 2006-0253        | ASB EC120<br>76A006 R1        |      | TWIST GRIP ASSEMBLY/CHECK                                                                           | N/A by s/s  | 23.01.2015 | <b>AIRBUS HELICOPTERS</b>  |
| HB 2007-403           | EASA 2007-0211        | ASB EC120<br>05A006           | 110h | TAIL ROTOR-REAR DRIVE SHAFT FRICTION RING/REPET.INSPECTION.                                         | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b>  |
| HB 2007-442           | EASA 2007-0256-CN     | SB 25-1111432                 |      | CANCELLED. Seat Restraint Plastic Rotary Buckle Handle. Rep. Insp. Repl.                            | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b>  |
| HB 2007-538           | EASA 2007-0311        | ASB EC120<br>25A023           |      | ENERGY ABSORBING SEAT & METALLISATION BRAID/MODIF.                                                  | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b>  |
| HB 2008-348           | EASA 2008-0177-E      | ASB 04A007                    |      | EMERGENCY FLOATATION GEAR/RFM REV;IN-FLIGHT CHECK                                                   | N/A by s/s  | 23.01.2015 | <b>AIRBUS HELICOPTERS</b>  |
| HB 2008-351           | EASA 2008-0185        | ASB EC120<br>76A005           |      | TWIST GRIP DRIVE TUBE/IDENT.OF P/N                                                                  | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b>  |
| EASA-2009-0190        | EASA 2009-0190        | ASB EC120<br>05A011           | 300h | EMERGENCY FLOATATION GEAR/REPET.INSPECTION.                                                         | N/A by s/s  | 23.01.2015 | <b>AIRBUS HELICOPTERS</b>  |
| EASA-2009-0251-E      | EASA 2009-0251-E      |                               |      | FIRE FIGHTING ENTERPRISES HALON 1211 FIRE EXTINGUISHERS/IDENT.                                      | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b>  |
| EASA-2009-0278        | EASA 2009-0278        |                               |      | SICLI MODEL H1-10 AIR PORTABLE FIRE EXTINGUISHERS/ IDENT.                                           | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b>  |
| EASA-2009-0262 R1     | EASA 2009-0262 R1     |                               |      | FIRE FIGHTING ENTERPRISES HALON 1211 FIRE EXTINGUISHERS/IDENT.                                      | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b>  |
| EASA-2009-0277 R1     | EASA 2009-0277 R1     | SB 863520-26-001              |      | HOTELLIER PORTABLE HALON 1211 FIRE EXTINGUISHERS/IDENT.                                             | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b>  |
| EASA-2010-0026-E      | EASA 2010-0026-E      | EASB EC120B<br>05A012         | 15h  | MAIN ROTOR HEAD HUB ASSEMBLY//INSPECTION.                                                           | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b>  |
| EASA-2010-0062 R1     | EASA 2010-0062 R1     | FFE Ltd ASB 26-116            |      | FIRE FIGHTING ENTERPRISES HALON 1211 FIRE EXTINGUISHERS/IDENT.                                      | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b>  |
| EASA-2010-0078-E      | EASA 2010-0078-E      | ASB EC120<br>24A012           |      | EMERGENCY SWITCH WIRING/MODIF.                                                                      | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b>  |
| EASA-2009-0122 R1     | EASA 2009-0122 R1     | ASB 04A004 /<br>ASB 01.00.49  |      | SIREN LOAD RELEASE UNITS/INSPECTION;MODIF.                                                          | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b>  |
| EASA-2011-0185        | EASA 2011-0185        | EC 120 ASB<br>05A011 / 25A026 | 300h | EMERGENCY FLOATATION GEAR/MODIF.                                                                    | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b>  |
| EASA-2011-0239        | EASA 2011-0239        | SIL 102-2100-34-001/002       |      | SMS-COBHAM AVIONICS IND201 RADIO ALTIMETER/MODIF.                                                   | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b>  |
| EASA-2013-0093 COR    | EASA 2013-0093 COR    | ASB EC120<br>52A014           |      | SLIDING DOOR STAR SUPPORT/MODIF.                                                                    | N/A by s/s  | 23.01.2015 | <b>AIRBUS HELICOPTERS</b>  |
| EASA-2013-0020 R4 COR | EASA 2013-0020 R4 COR |                               |      | AMSAFE;ANJOU AERONAUTIQUE;DAVIS AIRCRAFT;SCHROTH SAFETY;PACIFIC SCIENTIFIC SAFETY BELTS/INSPECTION. | Open        | 21.03.2015 | <b>AIRBUS HELICOPTERS</b>  |
| EASA-2014-0167        | EASA 2014-0167        | ASB EC120-<br>53A015,         |      | TAIL BOOM//INSPECTION.                                                                              | N/A by date | 23.01.2015 | <b>AIRBUS HELICOPTERS</b>  |
| EASA-2015-0020        | EASA 2015-0020        | ASB EC120<br>52A014           |      | SLIDING DOOR STAR SUPPORT/MODIF.                                                                    | N/A         | 31.03.2017 | <b>Héli-Maintenance AG</b> |
| FAA-2015-24-51        | FAA 2015-24-51        | STC SR00491DE                 |      | AIR COMM AIR CONTITIONING KIT (FAA STC SR00491DE)/REPLMNT.                                          | N/A         | 31.03.2017 | <b>Héli-Maintenance AG</b> |

## LISTE DES CONSIGNES DE NAVIGABILITE APPLIQUEES

|                   |                   |                       |          |                                                                                          |                 |            |                            |
|-------------------|-------------------|-----------------------|----------|------------------------------------------------------------------------------------------|-----------------|------------|----------------------------|
| EASA-2016-0180    | EASA 2016-0180    | EASB EC120<br>04A007  |          | EMERGENCY FLOATATION GEAR LACU PUSHBUTTON/REPLMNT.                                       | N/A             | 31.03.2017 | <b>Héli-Maintenance AG</b> |
| FAA-2017-16-01    | FAA 2017-16-01    |                       | 12m      | AMERI-KING CORPORATION/AK-450 & AK-451 EMERGENCY LOCATOR TRANSMITTERS (ELT)/REPET.INSNP. | N/A not install | 25.01.2018 | <b>SHM</b>                 |
| EASA-2018-0183    | EASA 2018-0183    | EC120-04A008          |          | Tail Rotor Blade Life Limit. Re-identification                                           | N/A by serial   | 07.01.2019 | <b>SHM</b>                 |
| EASA-2018-0186    | EASA 2018-0186    | EC120-62A020          |          | ATA 62 – Main Rotor – Hub Scissors Attachment Bolts – Inspection / Replacement           | Comply With     | 07.01.2019 | <b>SHM</b>                 |
| EASA-2019-0139    | EASA 2019-0139    | ASB 05A019            | 15h      | Main Rotor Hub. Scissors Attachment Bolts. Inspection, replacement                       | Comply With     | 18.06.2019 | <b>SHM</b>                 |
| EASA-2019-0272-E  | EASA 2019-0272-E  | ASB 05A020            | 15h      | TAIL ROTOR HUB BODY/REPET.INSNP. & PART REPLMNT                                          | Comply With     | 04.11.2019 | <b>Héli-Lausanne</b>       |
| EASA-2019-0272 R1 | EASA 2019-0272 R1 | ASB 05A020            | 15h      | Tail Rotor Hub. Inspection, Replacement.                                                 | Comply With     | 04.11.2019 | <b>Héli-Lausanne</b>       |
| EASA-2020-0064    | EASA 2020-0064    | ASB AS350-25.04.10 R1 |          | Equipment Furnishing. Emergency Floatation System                                        | N/A not install | 02.04.2020 | <b>Héli-Lausanne</b>       |
| EASA-2020-0095    | EASA 2020-0095    | ASB EC120-52A018      |          | Doors. Sliding Door Star Support Modification                                            | N/A by serial   | 30.04.2020 | <b>Héli-Lausanne</b>       |
| EASA-2020-0247    | EASA 2020-0247    | ASB 05A022            |          | Landing Gear. Skid Tubes Inspection.                                                     | N/A by serial   | 11.11.2020 | <b>Héli-Lausanne</b>       |
| EASA-2021-0015    | EASA 2021-0015    | ASB EC120-53A017 R1   |          | Tail Boom Inspection. Modification Repair.                                               | Comply With     | 24.02.2021 | <b>Rotortec AG</b>         |
| EASA-2021-0046    | EASA 2021-0046    | ASB EC120-62A020      | 15h      | Hub Scissors. Attachment bolts. Inspection. Replacement.                                 | Comply With     | 24.02.2021 | <b>Rotortec AG</b>         |
| EASA-2021-0079    | EASA 2021-0079    | ASB EC120-64A003      |          | Tail Rotor. Blades, Inspection.                                                          |                 | 24.02.2021 | <b>Rotortec AG</b>         |
| EASA-2021-0069    | EASA 2021-0069    | ASB 05A020 R2         | 15h      | Tail Rotor. Hub Body. Inspection, Replacement                                            |                 | 24.02.2021 | <b>Rotortec AG</b>         |
| FAA-2021-07-13    | FAA 2021-07-13    | SB 25-1111432         |          | Pacific Scientific Rotary Buckle Assembly. Insp.                                         |                 | 15.07.2021 | <b>Rotortec AG</b>         |
| EASA-2021-0168    | EASA 2021-0168    | ASB EC120-05A023      | 600h 24m | Indicating / Recording Systems-Control Unit-Inspection                                   | Comply With     | 02.11.2021 | <b>Rotortec AG</b>         |
| EASA-2022-0053    | EASA 2022-0053    | ASB EC120-32A014      |          | Landing Gear. Skid Type Landing Gear Inspection.                                         | Comply With     | 12.06.2023 | <b>Rotortec AG</b>         |
| EASA-2023-0036    | EASA 2023-0036    | ASB EC120-62A021      | 15h      | Main Rotor. Hub Scissors Assy. Attachment Bolts Inspection.                              | Comply With     | 12.06.2023 | <b>Rotortec AG</b>         |
| EASA-2023-0083    | EASA 2023-0083    | ALS                   |          | Time Limits. Maintenance Checks. ALS                                                     | Comply With     | 12.06.2023 | <b>Rotortec AG</b>         |

# LISTE DES CONSIGNES DE NAVIGABILITE APPLIQUEES

SECTION: ENGINE

AIRCRAFT: HB-ZRO

Type: TURBOMECA / SAFRAN, ARRIUS 2F (EASA.E.031)

N° série: 34789

| N° AD                | N° Origine           | N° SB                                   | Interval | Titre                                                    | Remarque    | Fait le:   | Fait par:                    |
|----------------------|----------------------|-----------------------------------------|----------|----------------------------------------------------------|-------------|------------|------------------------------|
| HB 1999-345          | DGAC 1999-233        | SB A319 73 4001                         |          | FUEL INJECTION MANIFOLDS/REPET.REPLMNT.                  | N/A by s/s  | 23.01.2015 | SAFRAN HELICOPTER<br>ENGINES |
| HB 2000-495          | DGAC 2000-482        | SB A319 73 4808                         |          | FUEL CONTROL UNIT/REWORK                                 | N/A by date | 23.01.2015 | SAFRAN HELICOPTER<br>ENGINES |
| HB 2003-308          | DGAC 2003-219        | SL<br>2239/03/ARRIUS2<br>F/22           |          | ENGINE ARRIUS 2F-S/N 34084/UNAIROWORTHY DECLAR           | N/A by date | 23.01.2015 | SAFRAN HELICOPTER<br>ENGINES |
| HB 2005-193          | DGAC 2005-073        | FA<br>057/05/DSO/TM                     |          | TURBOSH. ENGINE ARRIUS 2F/IMMEDIATE GROUNDING            | N/A by s/s  | 23.01.2015 | SAFRAN HELICOPTER<br>ENGINES |
| HB 2005-194          | DGAC 2005-073<br>R1  | FA<br>057/05/DSO/TM                     |          | TURBOSH.ENGINE ARRIUS 2F/IMMEDIATE GROUDNING             | N/A by date | 23.01.2015 | SAFRAN HELICOPTER<br>ENGINES |
| HB 2005-268          | DGAC 2005-088        | MSB A319 73<br>4823                     |          | ADJUSTED FUEL CONTROL UNIT-FUEL FILTER/CHECK             | N/A by date | 23.01.2015 | SAFRAN HELICOPTER<br>ENGINES |
| HB 2008-289          | EASA 2008-0134       | SB 319 75 4810                          |          | FUEL CONTROL UNIT - P3 AIR PIPE/INSP.                    | N/A by s/s  | 23.01.2015 | SAFRAN HELICOPTER<br>ENGINES |
| HB 2005-364          | DGAC 2005-122        | MSB A319 79<br>4802                     | 300h     | CHECK-VALVE PISTON O-RING/REPLMNT.                       | N/A by s/s  | 23.01.2015 | SAFRAN HELICOPTER<br>ENGINES |
| HB 2005-417          | DGAC 2005-143        | MSB A319 73<br>4825                     |          | FUEL CONTROL UNIT-CONSTANT DELTA P DIAPHRAGM             | N/A by date | 23.01.2015 | SAFRAN HELICOPTER<br>ENGINES |
| HB 2006-074          | DGAC 2005-143<br>R1  | MSB A319 73<br>4825                     |          | FUEL CONTROL UNIT (FCU)/REPLACEMENT                      | N/A by s/s  | 23.01.2015 | SAFRAN HELICOPTER<br>ENGINES |
| HB 2006-325          | EASA 2006-0141       | MSB A319 79<br>4802                     | 300h     | CHECK-VALVE PISTON O-RING/REPET.REPLMNT                  | N/A by date | 23.01.2015 | SAFRAN HELICOPTER<br>ENGINES |
| HB 2007-226          | EASA 2007-0057       | MSB 319 72 4012<br>N°1                  |          | GAS GENERATOR FRONT BEARING/MODIFICATION                 | N/A by date | 23.01.2015 | SAFRAN HELICOPTER<br>ENGINES |
| HB 2008-026          | EASA 2006-0237       | SB 319 73 4055 /<br>MSB A319 73<br>4825 |          | FCU-CONSTANT DELTA PRESS. VALVE DIAPHRAGM/REPLMNT.MODIF. | N/A by date | 23.01.2015 | SAFRAN HELICOPTER<br>ENGINES |
| HB 2008-347          | EASA 2008-0170       | SB 319 79 4075                          |          | LUBRICATION UNIT/MIDIF.                                  | N/A by date | 23.01.2015 | SAFRAN HELICOPTER<br>ENGINES |
| EASA-2008-0134<br>R1 | EASA 2008-0134<br>R1 | SB 319 75 4810                          |          | FUEL CONTROL UNIT - P3 AIR PIPE/INSP.                    | N/A by s/s  | 23.01.2015 | SAFRAN HELICOPTER<br>ENGINES |
| EASA-2011-0182<br>R1 | EASA 2011-0182<br>R1 | MSB 319 75 4810<br>B                    | 100h     | FUEL CONTROL UNIT - P3 AIR PIPE/INSP;MODIF.              | N/A by s/s  | 23.01.2015 | SAFRAN HELICOPTER<br>ENGINES |
| EASA-2012-0150       | EASA 2012-0150       | MSB A319 73<br>4001 K                   |          | ENGINE FUEL CONTROL PRIVILEGE INJECTOR/REPLMNT.          | N/A by s/s  | 23.01.2015 | SAFRAN HELICOPTER<br>ENGINES |

## LISTE DES CONSIGNES DE NAVIGABILITE APPLIQUEES

|                       |                       |                              |                                                                  |               |            |                                      |
|-----------------------|-----------------------|------------------------------|------------------------------------------------------------------|---------------|------------|--------------------------------------|
| EASA-2013-0243        | EASA 2013-0243        | SB 319 79 4835               | NOZZLE BONDING ON EJECTOR ASSEMBLY//INSP.                        | N/A by s/s    | 23.01.2015 | <b>SAFRAN HELICOPTER<br/>ENGINES</b> |
| EASA-2015-0049<br>COR | EASA 2015-0049<br>COR | SB 319 79 4834               | OIL PUMP DRIVE LINK LUBRICATING DEVICE//INSP.                    | N/A by model  | 09.04.2015 | <b>Part 145 Tiers</b>                |
| EASA-2015-0057        | EASA 2015-0057        | SB 319 79 4835               | NOZZLE BONDING ON EJECTOR ASSEMBLY//INSP.                        | N/A by serial | 09.04.2015 | <b>Part 145 Tiers</b>                |
| EASA-2016-0041        | EASA 2016-0041        | MSB 319 73 4077              | FUEL CONTROL UNIT ASSEMBLY/MODIF.                                | N/A           | 31.03.2017 | <b>Héli-Maintenance AG</b>           |
| EASA-2016-0138<br>R1  | EASA 2016-0138<br>R1  | ALS                          | ENGINE FUEL CONTROL PRIVILEGE INJECTOR.                          | N/A by s/s    | 26.04.2017 | <b>Héli-Maintenance AG</b>           |
| EASA-2017-0070        | EASA 2017-0070        | MSB 319.73.4839              | ENGINE FUEL CONTROL PIPE INJECTOR PREFERRED<br>ASSEMBLY/REPLMNT. | Comply With   | 26.04.2017 | <b>Héli-Maintenance AG</b>           |
| EASA-2018-0012-E      | EASA 2018-0012-<br>E  |                              | Eletric Magnetic Plug Inspection/Replacement                     | N/A by part   | 25.01.2018 | <b>SHM</b>                           |
| EASA-2007-0057<br>R1  | EASA 2007-0057<br>R1  | SB 319 72 4084 &<br>MOD TF84 | Gas Generator Front Bearing – Modification                       | N/A by date   | 26.03.2018 | <b>Héli-Lausanne</b>                 |

## **LISTE DES CONSIGNES DE NAVIGABILITE APPLIQUEES**