



Master AD/SI Report

HAWKER 400XP
S/N RK-552 OK-BZZ

OWNER:	TATRA LEASING, A.S.	OPERATOR:	JETBEE CZECH S.R.O
ADDRESS:	HODŽOVO NÁMESTIE 3 BRATISLAVA 81106	ADDRESS:	K LETISTI 1073/25 PRAGUE 6 161 00
PHONE:		PHONE:	420 605 991 191
FAX:		FAX:	
ANALYST:	PIERRE-ALEXIS DI ROSA	+33-1.55.93.45.91 (DIRECT)	PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.
EMAIL:	PA.DIROSA@CAMPSYSTEMS.EU	+33 (0) 1.55.93.45.80 (OFFICE)	
		WWW.CAMPSYSTEMS.COM	

Filter Criteria: Task Type In: ('AD','ADP','SB','SBP'); Group by Profile or Bulletin: Profile Type; Mode: With Compliance or Next Due; For: Airframe,Engine,APU Etc;

AIRCRAFT	SERIAL/REGNO: RK-552/OK-BZZ	MODEL: HAWKER 400XP	MANUFACTURER: TEXTRON AVIATION INC.
DATES		LAST ACTUALS	CURRENT ACTUAL
CERTIFICATION DATE: 17-MAR-2008		4607:07 A/C HRS as of 29-NOV-2022 _____	A/C HRS as of ____/____/____
		3829 AFL as of 29-NOV-2022 _____	AFL as of ____/____/____
		327 ACH as of 29-NOV-2022 _____	ACH as of ____/____/____
ENGINE NO. 1	SERIAL/PART: PCE-JG0091/JT15D-5R	MODEL: JT15D-5R	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON 15-FEB-2022		LAST ACTUALS	CURRENT ACTUAL
3611:42 ENG. HRS 3833:39 A/C HRS		4385:11 ENG. HRS as of 29-NOV-2022 _____	ENG. HRS as of ____/____/____
3222 ENC		3697 ENC as of 29-NOV-2022 _____	ENC as of ____/____/____
ENGINE NO. 2	SERIAL/PART: PCE-JG0092/JT15D-5R	MODEL: JT15D-5R	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON 15-FEB-2022		LAST ACTUALS	CURRENT ACTUAL
3611:42 ENG. HRS 3833:39 A/C HRS		4385:11 ENG. HRS as of 29-NOV-2022 _____	ENG. HRS as of ____/____/____
3222 ENC		3697 ENC as of 29-NOV-2022 _____	ENC as of ____/____/____



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - AD - RK-552/OK-BZZ							
EASA 2010-0204	NAVIGATION SYSTEMS-MODE-S TRANSPONDER-MODIFICATION/REPLACEMENT						NOT APPLICABLE - BY PART NUMBER ADC P/N 822-0389-633 NOT LISTED IN AD DOCUMENTATION
		MOS		20-JUL-2011			
		HRS/MSC -					
		AFL					
EASA 2011-0090R1	OXYGEN – OXYGEN MASK REGULATOR INFLATABLE HARNESS – IDENTIFICATION / REPLACEMENT						NOT APPLICABLE - N/A BY PART NUMBER FITTED
		MOS	24 (s)	11-FEB-2012			
		HRS/MSC					
		AFL					
FAA 1974-08-09 R02	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION (SUPERSEDED BY FAA AD 1974-08-09 R3)						
39-9680		MOS		17-MAR-2008			
29-JUL-1996		HRS/MSC -		0			
		AFL		0			
FAA 1992-16-14	TO PREVENT FIRE AND POTENTIAL EXPLOSION OF THE FUSELAGE FUEL TANKS					MANDATORY	NOT APPLICABLE
39-8323		MOS		17-MAR-2008			
09-SEP-1992		HRS/MSC -		0			
		AFL		0			
FAA 1993-01-07	TO PREVENT SNAGGING OF THE END CLEVIS FITTING AND KINKING (AND SUBSEQUENT FAILURE) OF THE EMERGENCY RELEASE CABLE OF THE MAIN LANDING GEAR					MANDATORY	NOT APPLICABLE
39-8461		MOS		17-MAR-2008			
02-MAR-1993		HRS/MSC -		0			
		AFL		0			
FAA 1993-02-12	TO PREVENT THE LOSS OF STANDBY POWER AND THE POSSIBILITY OF AN ELECTRICAL FIRE					MANDATORY	NOT APPLICABLE
39-8495		MOS		17-MAR-2008			
23-MAR-1993		HRS/MSC -		0			
		AFL		0			
FAA 1993-09-11	TO PREVENT REDUCED STRUCTURAL INTEGRITY OF THE AFT FUEL FILLER TANK INSTALLATION					MANDATORY	NOT APPLICABLE
39-8577		MOS		17-MAR-2008			
17-JUN-1993		HRS/MSC -		0			
		AFL		0			
FAA 1993-16-12	TO PREVENT STRUCTURAL FAILURE OF THE EMERGENCY DOOR FRAME SUPPORT					MANDATORY	NOT APPLICABLE
39-8670		MOS		17-MAR-2008			
13-OCT-1993		HRS/MSC -		0			
		AFL		0			
FAA 1993-20-01	TO PREVENT SMOKE AND/OR FIRE IN THE COCKPIT					MANDATORY	NOT APPLICABLE
39-8708		MOS		17-MAR-2008			
02-NOV-1993		HRS/MSC -		0			
		AFL		0			
FAA 1993-25-15	TO PREVENT REDUCED STRUCTURAL CAPABILITY OF THE AIRFRAME					MANDATORY	NOT APPLICABLE
39-8779		MOS		17-MAR-2008			
14-FEB-1994		HRS/MSC -		0			
		AFL		0			



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 1994-04-07 PARA (A1) L/H	DEGRADATION OR LOSS OF BRAKING PERFORMANCE					MANDATORY	NOT APPLICABLE
39-8827 07-MAR-1994		MOS HRS/MSC - AFL		17-MAR-2008 0 0			
FAA 1994-04-07 PARA (A1) R/H	DEGRADATION OR LOSS OF BRAKING PERFORMANCE					MANDATORY	NOT APPLICABLE
39-8827 07-MAR-1994		MOS HRS/MSC - AFL		17-MAR-2008 0 0			
FAA 1994-04-07 PARA (A2) L/H	DEGRADATION OR LOSS OF BRAKING PERFORMANCE					MANDATORY	NOT APPLICABLE
39-8827 07-MAR-1994		MOS HRS/MSC - AFL		17-MAR-2008 0 0			
FAA 1994-04-07 PARA (A2) R/H	DEGRADATION OR LOSS OF BRAKING PERFORMANCE					MANDATORY	NOT APPLICABLE
39-8827 07-MAR-1994		MOS HRS/MSC - AFL		17-MAR-2008 0 0			
FAA 1994-05-09	TO PREVENT SEPARATION OF THE CABIN SEAT FRAMES FROM THEIR BASES DURING AN EMERGENCY LANDING					MANDATORY	NOT APPLICABLE
39-8847 07-APR-1994		MOS HRS/MSC - AFL		17-MAR-2008 0 0			
FAA 1994-11-09	TO PREVENT LOSS OF CONTROL OF THE FUEL SUPPLY TO THE ENGINE OR LOSS OF CONTROL OF THE RETRACTION/EXTENSION SYSTEM FOR THE MAIN LANDING GEAR (MLG) AND MLG DOOR					MANDATORY	NOT APPLICABLE
39-8925 07-JUL-1994		MOS HRS/MSC - AFL		17-MAR-2008 0 0			
FAA 1995-18-04	TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE					MANDATORY	NOT APPLICABLE
39-9352 10-OCT-1995		MOS HRS/MSC - AFL		17-MAR-2008 0 0			
FAA 1995-25-06	TO ENSURE THAT THE STANDBY INSTRUMENT LIGHTING SYSTEM ADEQUATELY ILLUMINATES THE STANDBY INSTRUMENT					MANDATORY	NOT APPLICABLE
39-9451 16-JAN-1996		MOS HRS/MSC - AFL		17-MAR-2008 0 0			
FAA 1996-03-07	TO PREVENT REDUCED CONTROLLABILITY OF THE AIRPLANE DUE TO A SHIFTING OF THE FLIGHTCREW SEAT DURING FLIGHT					SUPERSEDED	NOT APPLICABLE
39-9504 13-MAR-1996		MOS HRS/MSC - AFL		17-MAR-2008 0 0			
FAA 1996-25-03	TO PREVENT LOSS OF ROLLER ATTACH NUTS AND THE FLAP ROLLER					MANDATORY	NOT APPLICABLE
39-9845 24-JAN-1997		MOS HRS/MSC - AFL		17-MAR-2008 0 0			



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 1998-06-30	TO PREVENT CRACKING AND CONSEQUENT FAILURE OF THE OUTFLOW/SAFETY VALVES					MANDATORY	NOT APPLICABLE
39-10408		MOS		17-MAR-2008			
		HRS/MSC	-	0			
		AFL		0			
FAA 1999-21-08	FUEL DRAIN TUBE ASSEMBLY					MANDATORY	NOT APPLICABLE
39-11351		MOS		17-MAR-2008			
12-NOV-1999		HRS/MSC	-	0			
		AFL		0			
FAA 1999-21-26	TO PREVENT UNCOMMANDED NOSE-DOWN PITCH AT CERTAIN FLAP SETTINGS DURING ICING CONDITIONS					MANDATORY	NOT APPLICABLE
39-11372		MOS		17-MAR-2008			
22-NOV-1999		HRS/MSC	-	0			
		AFL		0			
FAA 2000-05-06	TO PREVENT FAILURE OF THE ENGINE FIRE EXTINGUISHER BOTTLE TO DISCHARGE, OR DISCHARGE OF THE WRONG ENGINE FIRE EXTINGUISHER BOTTLE					MANDATORY	NOT APPLICABLE
39-11615		MOS		17-MAR-2008			
12-APR-2000		HRS/MSC	-	0			
		AFL		0			
FAA 2000-09-12	TO PREVENT DETACHMENT OR BREAKAGE OF WIRES IN THE TEMPERATURE SWITCH ASSEMBLIES OF THE WING ICE PROTECTION SYSTEM					MANDATORY	NOT APPLICABLE
39-11721		MOS		17-MAR-2008			
16-JUN-2000		HRS/MSC	-	0			
		AFL		0			
FAA 2000-25-04	TO PREVENT AN ASYMMETRIC BRAKING CONDITION AND A LONGER STOPPING DISTANCE DUE TO SUDDEN LOSS OF NORMAL BRAKING TO THE LEFT WHEEL					MANDATORY	NOT APPLICABLE
39-12038		MOS		17-MAR-2008			
17-JAN-2001		HRS/MSC	-	0			
		AFL		0			
FAA 2001-03-06	TO PREVENT THE BLEED AIR SUPPLY TUBE ASSEMBLY FROM DISCONNECTING AND CONTACTING OTHER PNEUMATIC OR ELECTRICAL SYSTEMS OF THE AIRPLANE OR EXPELLING HIGH TEMPERATURE AIR ON SURROUNDING SYSTEMS AND STRUCTURE					MANDATORY	COMPLIED WITH
39-12110		MOS		31-AUG-2022		RECURRING	
		HRS/MSC	400	4384:47	4784:47		
		AFL		3695			
FAA 2001-20-07	TO PREVENT ELECTRICAL ARCING OR OVERHEATING OF THE GROUND CONNECTION IN THE AFT FUSELAGE AREA					MANDATORY	NOT APPLICABLE
39-12455		MOS		17-MAR-2008			
15-NOV-2001		HRS/MSC	-	0			
		AFL		0			
FAA 2002-01-23	LEFT ENGINE FORWARD BEAM AFT CARRY-THROUGH MOUNT BRACKET					MANDATORY	COMPLIED WITH
39-12617		MOS		31-AUG-2022			
		HRS/MSC	200 (s)	4384:47			
		AFL		3695			
FAA 2003-10-13	TO PREVENT LEAKAGE OF OXYGEN FROM SCORED LOW-PRESSURE OXYGEN TUBING					MANDATORY	NOT APPLICABLE
39-13158		MOS		17-MAR-2008			
01-JUL-2003		HRS/MSC	-	0			
		AFL		0			



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2004-03-35	TO PREVENT INTERMITTENT STICKING OF THE RELAYS ON THE ROLL TRIM PRINTED CIRCUIT BOARD (PCB)					MANDATORY	NOT APPLICABLE - COMPLIED WITH AT BUILD SEE SB 27-3464
39-13479 24-MAR-2004		MOS HRS/MSC - AFL		17-MAR-2008 0 0			
FAA 2004-22-02	TO PREVENT THE ACCUMULATION OF FUEL AND/OR FUEL VAPOR IN THE SPOILER MIXER BAY AND/OR THE AFT FUSELAGE COMPARTMENT					MANDATORY	NOT APPLICABLE - COMPLIED WITH AT BUILD SEE SB 53-3486
39-13830 01-DEC-2004		MOS HRS/MSC - AFL		17-MAR-2008 0 0			
FAA 2006-15-16	TO PREVENT OVER-VOLTAGE CONDITIONS OF THE DC STARTER GENERATOR					MANDATORY	NOT APPLICABLE
39-14697 05-SEP-2006		MOS HRS/MSC - AFL		17-MAR-2008 0 0			
FAA 2007-19-05	TO PREVENT FAILURE OF THE ATTACHMENT FASTENERS ON THE ENGINE COWLING PANELS					MANDATORY	NOT APPLICABLE - COMPLIED WITH AT BUILD SEE SB 54-3788
23-OCT-2007		MOS HRS/MSC - AFL		17-MAR-2008 0 0			
FAA 2007-24-01	TO PREVENT OVERHEATING OF WIRE INSULATION AND CONSEQUENT FIRE OR SMOKE IN THE AIRPLANE CABIN					MANDATORY	NOT APPLICABLE - COMPLIED WITH AT BUILD SEE SB 25-3758
39-15267		MOS HRS/MSC - AFL		17-MAR-2008 0 0			
FAA 2009-07-02	INSTALL AN IMPROVED ADJUSTMENT MECHANISM ON THE FLIGHTCREW SEAT					MANDATORY	NOT APPLICABLE - N/A BY S/N
39-15861 13-MAR-1996		MOS HRS/MSC - AFL		25-NOV-2011			
FAA 2011-01-09	B/E AEROSPACE 119003-11 PBE (SMOKE HOODS) IDENT AND REPLACEMENT IF LISTED SERIAL NUMBER					MANDATORY	NOT APPLICABLE - BY PART NUMBER
		DAYS HRS/MSC AFL	120 (s)	17-JUN-2011			
FAA 2011-03-12	DO A DETAILED INSPECTION FOR APPROPRIATE COVERAGE OF FIREWALL SEALANT OF THE LEFT AND RIGHT PYLON FIREWALL STRUCTURE					MANDATORY	COMPLIED WITH
39-16596 14-MAR-2011		MOS HRS/MSC - AFL		23-AUG-2011 600:10 531			
FAA 2012-11-09 R01 PARA (L)	INSTALL A SUPPLEMENTAL OXYGEN SYSTEM THAT MEETS ALL APPLICABLE SECTIONS OF PARTS 25 AND 121 OF THE FEDERAL AVIATION REGULATIONS (14 CFR PART 25 AND 14 CFR PART 121) IN EACH LAVATORY					MANDATORY	NOT APPLICABLE - NO OXYGEN GENERATORS FITTED.
27-JUL-2015		MOS HRS/MSC - AFL		05-SEP-2015 2094:28 1802			
FAA 2013-03-07	ELECTRICAL POWER SYSTEM WIRING - FUSE REPLACEMENT					MANDATORY	COMPLIED WITH
39-17342 19-MAR-2013		MOS HRS/MSC - AFL		23-AUG-2013			



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2014-15-15 PARA (G)	PERFORM A RADIOGRAPHIC (X-RAY) INSPECTION OR A BORESCOPE INSPECTION FOR CRACKING OF THE HORIZONTAL STABILIZER RIB ASSEMBLIES					MANDATORY	
05-SEP-2014		MOS HRS/MSC 7400 AFL		(EFF)	7400 M	RECURRING	
FAA 2014-21-06	FLIGHT CONTROLS - INSPECTION/REPLACEMENT OF PTAS HAVING A CERTAIN SERIAL NUMBER AND PART NUMBER					MANDATORY	COMPLIED WITH
28-NOV-2014		MOS HRS/MSC - AFL		08-MAY-2018 2736:50 2454			
FAA 2014-21-06 PARA (G)(H)	INSPECT TO DETERMINE THE SERIAL NUMBER AND PART NUMBER OF THE PTA, IF ANY SERIAL NUMBER AND PART NUMBER FOUND REPLACE THE PTA WITH A SERVICEABLE PTA OR AN OVERHAULED PTA HAVING AN ACME NUT AND JACKSCREW REPLACED WITH A NEW ACME NUT AND JACKSCREW					MANDATORY	COMPLIED WITH
28-NOV-2014		MOS HRS/MSC - AFL		08-MAY-2018 2736:50 2454			
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A..1 SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - PART NUMBER FITTED 802300-14 IS NOT IN SB EFFECTIVITY. NO ACTION REQUIRED.
15-JUL-2016		MOS HRS/MSC - AFL		04-SEP-2016 2409:22 2103			



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
APPLIANCE - RK-552/OK-BZZ							
CAA UK G-2015-0001	APPLIANCE AD - FIRE PROTECTION - ENGINE AND APU AUTOMATIC FIRE EXTINGUISHERS - INSPECTION / OVERHAUL					MANDATORY	NOT APPLICABLE - NO KIDDE GRAVINER AUTO EXTINGUISHERS FITTED
20-OCT-2015		MOS HRS/MSC - AFL		05-SEP-2015 2094:28 1802			
CAA UK G-2015-0001 R01	APPLIANCE AD - FIRE PROTECTION - ENGINE AND APU AUTOMATIC FIRE EXTINGUISHERS - INSPECTION / OVERHAUL					MANDATORY	COMPLIED WITH - DUAL HEAD EXTINGUISHER FITTED P/N 30400018-1 S/N : #1 32757B1 #2 62852B1
23-MAY-2016		MOS HRS/MSC - AFL		04-SEP-2016 2409:22 2103			
EASA 2010-0003 R02	APPLIANCE AD - NAVIGATION - MODE S TRANSPONDER AIRCRAFT TYPE MODE STRAPPING - CHECK / MODIFICATION					MANDATORY	COMPLIED WITH
14-OCT-2014		MOS HRS/MSC - AFL		21-NOV-2015 2159:12 1866			
EASA 2010-0152	APPLIANCE AD - INTERTECHNIQUE OXYGEN MASK REGULATOR MODIFICATION					EASA	NOT APPLICABLE - NOT APPLICABLE TO MASKS INSTALLED BY PART NUMBER
		MOS HRS/MSC AFL	6 (s)	10-DEC-2010			
EASA 2012-0254	APPLIANCE AD - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR -IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT					MANDATORY	NOT APPLICABLE
13-DEC-2012		MOS HRS/MSC - AFL		03-JAN-2013			
EASA 2012-0254 PARA (1)	INSPECT/CHECK OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR -IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT OXYGEN MASK REGULATOR TO INDENTIFY THE P/N AND S/N					MANDATORY	NOT APPLICABLE
13-DEC-2012		DAYS HRS/MSC - AFL		03-JAN-2013			
EASA 2012-0254 PARA (2.1)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR -IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT AFFECTED OXYGEN MASK REGULATOR					MANDATORY	NOT APPLICABLE
13-DEC-2012		MOS HRS/MSC - AFL		03-JAN-2013			
EASA 2012-0254 PARA (2.2)	AMEND OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR -IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT AIRCRAFT FLIGHT MANUAL (AFM)					MANDATORY	NOT APPLICABLE
13-DEC-2012		MOS HRS/MSC - AFL		03-JAN-2013			
EASA 2012-0254 PARA (3)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR -IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR WITH A SERVICEABLE PART					MANDATORY	NOT APPLICABLE
13-DEC-2012		MOS HRS/MSC - AFL		03-JAN-2013			



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2013-0020 R01	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - NO REPAIRS CARRIED OUT SINCE NEW
12-MAR-2013		MOS HRS/MSC - AFL		01-JUN-2013			
EASA 2013-0020 R01 PARA (1)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER					MANDATORY	NOT APPLICABLE
12-MAR-2013		MOS HRS/MSC - AFL		01-JUN-2013			
EASA 2013-0020 R02 PARA (1)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER					MANDATORY	NOT APPLICABLE - COMPLIED WITH
11-JUL-2013		MOS HRS/MSC - AFL		31-JUL-2013 1313:06 1117			
EASA 2016-0024	APPLIANCE AD - FIRE PROTECTION - OPTICAL AND AMBIENT SMOKE DETECTORS - IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - NOT FITTED
01-FEB-2016		MOS HRS/MSC - AFL		10-OCT-2016 2444:26 2136			
EASA 2016-0024 PARA (1)	INSPECT EACH SIEMENS SMOKE DETECTOR TO DETERMINE WHETHER IT IS AN AFFECTED PART					MANDATORY	NOT APPLICABLE
01-FEB-2016		DAYS HRS/MSC - AFL		10-OCT-2016 2444:26 2136			
EASA 2016-0024 PARA (2.1)	REPLACE CARGO COMPARTMENT SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 1 OR TABLE 2					MANDATORY	NOT APPLICABLE
01-FEB-2016		MOS HRS/MSC - AFL		10-OCT-2016 2444:26 2136			
EASA 2016-0024 PARA (2.2)	REPLACE PASSENGER, CABIN OR ANY OTHER ON BOARD LOCATION SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 3					MANDATORY	NOT APPLICABLE
01-FEB-2016		MOS HRS/MSC - AFL		10-OCT-2016 2444:26 2136			
EASA 2016-0024 PARA (2.3)	REPLACE REPAIRED SMOKE DETECTOR IDENTIFIED IN APPENDIX 1					MANDATORY	NOT APPLICABLE
01-FEB-2016		MOS HRS/MSC - AFL		10-OCT-2016 2444:26 2136			
EASA 2016-0024 PARA (3)	FROM THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL ON ANY AEROPLANE AN AFFECTED P/N SMOKE DETECTOR UNLESS THE UNIT (GMC ONLY) IS MARKED 'SIL PMC-26-002'					MANDATORY	NOT APPLICABLE
01-FEB-2016		MOS HRS/MSC - AFL		10-OCT-2016 2444:26 2136			



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2019-0235	APPLIANCE AD - EQUIPMENT / FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER - INSPECTION / MODIFICATION / REPLACEMENT					MANDATORY	COMPLIED WITH - MODIFIED
04-OCT-2019		MOS HRS/MSC - (s) AFL		15-APR-2020 3278:39 2968			
EASA 2019-0235 PARA (1) THRU (4)	CONCURRENTLY ACCOMPLISH PARAS (1.1) AND (1.2) OF THIS AD AND ACCOMPLISH APPLICABLE CORRECTIVE ACTION(S) (IF, DISCREPANCIES ARE DETECTED, AS IDENTIFIED IN THE SIL); OPERATORS MAY CONTINUE TO USE ELTS WITH THE ORIGINAL G-SWITCHES BY REDUCING THE INTERVAL OF THE G-SWITCH TESTING, AS REQUIRED BY PARA (1.1)					MANDATORY	COMPLIED WITH
04-OCT-2019		DAYS HRS/MSC - AFL		15-APR-2020 3278:39 2968			
EASA 2019-0235 PARA (5)	REMOVE THE AFFECTED PART FROM SERVICE IAW THE INSTRUCTIONS OF SECTION 7 OF THE SB FOR THE PURPOSE OF IN-SHOP MODIFICATION					MANDATORY	COMPLIED WITH
04-OCT-2019		MOS HRS/MSC - AFL		15-APR-2020 3278:39 2968			
EASA 2019-0235 PARA (6)	IN-SHOP CORRECTION OF AN AFFECTED PART OR MODIFICATION INTO A SERVICEABLE PART IAW THE INSTRUCTIONS OF THE SB CONSTITUTES TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS AND TESTING AS REQUIRED BY THIS AD FOR THAT PART					MANDATORY	COMPLIED WITH
04-OCT-2019		MOS HRS/MSC - (s) AFL		15-APR-2020 3278:39 2968			
EASA 2019-0235 PARA (9)	DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED PART THAT HAS ACCUMULATED 10 YEAR TIS OR MORE					MANDATORY	COMPLIED WITH - MODIFIED
04-OCT-2019		MOS HRS/MSC - (s) AFL		15-APR-2020 3278:39 2968			
FAA 2003-26-14	APPLIANCE AD - KIDDE AEROSPACE PART NUMBER (P/N) 898052 HAND-HELD HALON FIRE EXTINGUISHERS					MANDATORY	NOT APPLICABLE - N/A BY PT.NO. FITTED.
39-13413 20-FEB-2004		MOS HRS/MSC - AFL		05-SEP-2015 2094:28 1802			
FAA 2010-01-03	APPLIANCE AD - REPLACE PORTABLE HALON 1211 (BCF) FIRE EXTINGUISHERS MANUFACTURED BY FIRE FIGHTING ENTERPRISES LIMITED WITH SERVICEABLE FIRE EXTINGUISHERS					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY
39-16159 20-JAN-2010		DAYS HRS/MSC - AFL		28-MAR-2010 222:33 176			
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS					MANDATORY	NOT APPLICABLE - BY MANUFACTURE OF TCAS UNIT
13-MAR-2012		MOS HRS/MSC - (s) AFL		18-MAY-2012			
FAA 2014-17-02	APPLIANCE AD - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING DISCREPANCIES - HONEYWELL ASCA INC					MANDATORY	NOT APPLICABLE - BY TYPE
09-SEP-2014		MOS HRS/MSC - (s) AFL		25-JAN-2015 1907:23			



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION					MANDATORY	COMPLIED WITH
14-OCT-2014		MOS HRS/MSC - AFL		04-SEP-2016 2409:22 2103			
FAA 2015-16-04	APPLIANCE AD - FIRE PROTECTION - MODIFY ALL KIDDE GRAVINER HAND-OPERATED FIRE EXTINGUISHERS HAVING PART NUMBERS 56412-001 (34H), 56411-001 (35H), AND 56412-002 (38H)					MANDATORY	NOT APPLICABLE - N/A BY PT.NO. FITTED.
15-SEP-2015		MOS HRS/MSC - (s) AFL		05-SEP-2015 2094:28 1802			
FAA 2017-04-06	APPLIANCE AD - CABIN SYSTEMS - REPLACEMENT OF UNITED INSTRUMENTS INC. 5934 SERIES ALTIMETERS MANUFACTURED BETWEEN JANUARY 2015 AND FEBRUARY 2016					MANDATORY	NOT APPLICABLE - BY P/N INSTALLED
07-APR-2017		MOS HRS/MSC - AFL		09-APR-2018 2721:25 2437			
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS						NOT APPLICABLE - ARTEX 406-2 INSTALLED
24-OCT-2017		MOS HRS/MSC - AFL		01-OCT-2020 3339:36 3032			
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.					MANDATORY	NOT APPLICABLE
16-OCT-2017		MOS HRS/MSC - AFL		08-MAY-2018 2736:50 2454			
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT					MANDATORY	NOT APPLICABLE - DUE DIFFERENT P/ N OF CMD/CO-PILOT SEAT BELTS INSTALLED.CURRENTLY INSTALLED CAPTAIN SEAT BELTS WAS P/N 502214-401 AND COPILOT SEAT BELTS WAS P/N 502214-403.
11-MAY-2021		MOS HRS/MSC - AFL		15-FEB-2022 3833:39 3354			
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE					MANDATORY	NOT APPLICABLE - DUE DIFFERENT P/ N OF CMD/CO-PILOT SEAT BELTS INSTALLED.CURRENTLY INSTALLED CAPTAIN SEAT BELTS WAS P/N 502214-401 AND COPILOT SEAT BELTS WAS P/N 502214-403.
11-MAY-2021		MOS HRS/MSC - AFL		15-FEB-2022 3833:39 3354			
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE					MANDATORY	NOT APPLICABLE - DUE DIFFERENT P/ N OF CMD/CO-PILOT SEAT BELTS INSTALLED.CURRENTLY INSTALLED CAPTAIN SEAT BELTS WAS P/N 502214-401 AND COPILOT SEAT BELTS WAS P/N 502214-403.
11-MAY-2021		MOS HRS/MSC - AFL		15-FEB-2022 3833:39 3354			



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER					MANDATORY	NOT APPLICABLE - DUE DIFFERENT P/ N OF CMD/CO-PILOT SEAT BELTS INSTALLED.CURRENTLY INSTALLED CAPTAIN SEAT BELTS WAS P/N 502214-401 AND COPILOT SEAT BELTS WAS P/N 502214-403.
11-MAY-2021		MOS HRS/MSC - AFL		15-FEB-2022 3833:39 3354			
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS					MANDATORY	NOT APPLICABLE
09-DEC-2021		MOS HRS/MSC - AFL		15-FEB-2022 3833:39 3354			



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - SB - RK-552/OK-BZZ							
# 25SAX01	IODINE WIPES TO BE ADDED TO FAK BY 31 MAR 2012						COMPLIED WITH - IODINE WIPES SUPPLIED
		MOS		11-APR-2012			
		HRS/MSC -		764:35			
		AFL		673			
COM 89 PART A	INSPECT CREW SEAT RESTRAINT SYSTEM, COMMUNIQUE CREW SEAT RESTRAINT SYSTEM					RECOMMENDED	COMPLIED WITH
		DAYS		28-APR-2010			
17-APR-2009		HRS/MSC -		222:33			
		AFL		176			
COM 89 PART B	REPLACE CREW SEAT RESTRAINT SYSTEM, COMMUNIQUE CREW SEAT RESTRAINT SYSTEM					RECOMMENDED	COMPLIED WITH - SEE WORK PACK GNR68001159
		MOS		25-MAR-2011			
17-APR-2009		HRS/MSC -		456:31			
		AFL		413			
COM MC109	L-3AR COCKPIT VOICE RECORDER, COMMUNIQUE					INFORMATIONAL	NOT APPLICABLE - BY S/N INSTALLED.
		MOS		25-OCT-2012			
01-OCT-2012		HRS/MSC -					
		AFL					
SB 21-3238	ENVIRONMENTAL/AIR CONDITIONING - INSPECTION/INSTALLATION OF BLEED AIR RUPTURE INSULATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 22-3003	AUTOFLIGHT - ELEVATOR, SPOILER AND RUDDER SERVO MOUNT INSPECTION/CLEANING/REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 22-3003 R01	AUTOFLIGHT - ELEVATOR, SPOILER AND RUDDER SERVO MOUNT INSPECTION/CLEANING/REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 22-3501	AUTO PILOT - SERVO ENGAGE CLUTCH TEETH LUBRICATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 24-3010	ELECTRICAL POWER - ADDITION OF BUS-BAR INSULATOR IN THE MAIN JUCTION BOX ASSEMBLY, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 24-3151	ELECTRICAL POWER - BATTERY GROUND TERMINAL INSPECTION/WASHER INSTALLATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 24-3253	ELECTRICAL POWER - BATTERY AND EXTERNAL POWER GROUND IMPROVEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 24-3713	ELECTRICAL POWER - GENERATOR CONTROL UNIT INSTALLATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2435	ELECTRICAL PANELS, PARTS AND INSTRUMENTS - REPLACEMENT OF CURRENT SENSORS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2445	FUEL-INSPECTION/REPLACEMENT OF AFT FUEL TANK VENT FLAME ARRESTOR FILTER, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2446	EQUIPMENT/FURNISHINGS - INSPECTION/MODIFICATION OF CABIN SEAT FRAMES, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2447	LANDING GEAR - REPLACEMENT OF MAIN LANDING GEAR DOOR UPLOCK LINKS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2448	ICE AND RAIN PROTECTION - WING CLOSURE RIB SEALING, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2448 R01	ICE AND RAIN PROTECTION - WING CLOSURE RIB SEALING, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2458	ELECTRICAL PANELS, PARTS AND INSTRUMENTS - LH ITT CIRCUIT BREAKER WIRING CHANGE, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2459	WATER/WASTE - INSPECTION/MODIFICATION OF TOILET WIRING, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2462	ENGINE CONTROLS - IMPROVED RETENTION OF THRUST REVERSER POWER LEVER BEARINGS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 2468	FUEL - INSPECTION/INSTALLATION OF AFT FUEL FILLER TANK CLIPS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2471	FLIGHT CONTROLS - ELEVATOR TENSION SPRING INSPECTION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2473	NAVIGATION/PITOT STATIC - INSPECTION/MODIFICATION OF RH STATIC PORT HOSE CONNECTIONS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2476	ENVIRONMENTAL/AIR CONDITIONING - OUTFLOW/SAFETY VALVE INSPECTION/REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2476 R01	ENVIRONMENTAL/AIR CONDITIONING - OUTFLOW/SAFETY VALVE INSPECTION/REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2476 R02	ENVIRONMENTAL/AIR CONDITIONING - OUTFLOW/SAFETY VALVE INSPECTION/REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2477	OIL - REPLACEMENT OF THE ENGINE OIL TEMPERATURE SENSOR, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2478	DOORS - EMERGENCY EXIT HANDLE HOOK MARKINGS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2478 R01	DOORS - EMERGENCY EXIT HANDLE HOOK MARKINGS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2479	ELECTRICAL POWER - MAIN WHEEL WELL WIRE HARNESS CLAMPING INSPECTION/MODIFICATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 2479 R01	ELECTRICAL POWER - MAIN WHEEL WELL WIRE HARNESS CLAMPING INSPECTION/MODIFICATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2482	FUSELAGE - INSPECTION/INSTALLATION OF FUSELAGE RIVITS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 25-2536 R02	EQUIPMENT/FURNISHINGS - CREW SEAT STRUCTURE AND SEAT TRACK ADJUSTMENT MECHANISM IMPROVEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 25-3689	EQUIPMENT/FURNISHINGS - CABIN SWIVELING CHAIR FRAME SEAT MODIFICATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
01-NOV-2005		HRS/MSC -		0			
		AFL		0			
SB 25-3758	EQUIPMENT/FURNISHINGS - GALLEY POWER CIRCUIT PROTECTION IMPROVEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2502	PLACARDS AND MARKINGS - INSTALLATION OF A SPEED BRAKE WARNING DECAL, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2509	FUSELAGE - INSPECTION/REPLACEMENT OF ESCAPE HATCH SUBSTRUCTURE RIVITS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2517	ELECTRICAL POWER - AFT WIRE HARNESS CONVOLEX TUBING INSTALLATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2520	ELECTRICAL POWER - PART I - ENGINE EFC START CIRCUIT PROTECTION; PART II - MAIN CIRCUIT BREAKER PANEL PROTECTION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2522	FLIGHT CONTROLS - INSPECTION/REPLACEMENT OF FLAP ROLLER RETENTION COMPONENTS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 2522 R01	FLIGHT CONTROLS - INSPECTION/REPLACEMENT OF FLAP ROLLER RETENTION COMPONENTS, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
		HRS/MSC -		0			
		AFL		0			
SB 2522 R02	FLIGHT CONTROLS - INSPECTION/REPLACEMENT OF FLAP ROLLER RETENTION COMPONENTS, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
		HRS/MSC -		0			
		AFL		0			
SB 2533	AUTO FLIGHT - AUTOPILOT AND RUDDER BOOST INTERLOCK IMPROVEMENT, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
		HRS/MSC -		0			
		AFL		0			
SB 2533 R01	AUTO FLIGHT - AUTOPILOT AND RUDDER BOOST INTERLOCK IMPROVEMENT, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
		HRS/MSC -		0			
		AFL		0			
SB 2535	FLIGHT CONTROLS - REPLACEMENT OF ELEVATOR HORN LEVER ASSEMBLIES, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
		HRS/MSC -		0			
		AFL		0			
SB 2536	EQUIPMENT/FURNISHINGS - CREW SEAT STRUCTURE AND SEAT TRACK ADJUSTMENT MECHANISM IMPROVEMENTS, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
		HRS/MSC -		0			
		AFL		0			
SB 2536 R01	EQUIPMENT/FURNISHINGS - CREW SEAT STRUCTURE AND SEAT TRACK ADJUSTMENT MECHANISM IMPROVEMENTS, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
		HRS/MSC -		0			
		AFL		0			
SB 2549	RIGHT LANDING GEAR - WHEEL SPEED TRANSDUCER DRIVE CLIP INSTALLATION, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
		HRS/MSC -		0			
		AFL		0			
SB 2549	LEFT LANDING GEAR - WHEEL SPEED TRANSDUCER DRIVE CLIP INSTALLATION, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
		HRS/MSC -		0			
		AFL		0			
SB 2549 R01	RIGHT LANDING GEAR - WHEEL SPEED TRANSDUCER DRIVE CLIP INSTALLATION, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
		HRS/MSC -		0			
		AFL		0			
SB 2549 R01	LEFT LANDING GEAR - WHEEL SPEED TRANSDUCER DRIVE CLIP INSTALLATION, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
		HRS/MSC -		0			
		AFL		0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 2552	FUSELAGE - CABIN SEAT TRACK RIVET INSPECTION/INSTALLATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2552 R01	FUSELAGE - CABIN SEAT TRACK RIVET INSPECTION/INSTALLATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2563	LIGHTS - STANDBY INSTRUMENT LIGHTING CONTROL, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2587	ELECTRICAL PANELS, PARTS & INSTRUMENTS - CURRENT SENSOR INSPECTION/REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 26-3250	FIRE PROTECTION - ENGINE FIRE EXTINGUISHER BOTTLE SQUIB WIRING INSPECTION, MODIFICATION, AND LABELING, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 26-3250 R01	FIRE PROTECTION - ENGINE FIRE EXTINGUISHER BOTTLE SQUIB WIRING INSPECTION, MODIFICATION, AND LABELING, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2600	ICE AND RAIN PROTECTION - HORIZONTAL STABILIZER ICE PROTECTION IMPROVEMENT MODIFICATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2600 R01	ICE AND RAIN PROTECTION - HORIZONTAL STABILIZER ICE PROTECTION IMPROVEMENT MODIFICATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2600 R02	ICE AND RAIN PROTECTION - HORIZONTAL STABILIZER ICE PROTECTION IMPROVEMENT MODIFICATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
01-JUN-2002		HRS/MSC -		0			
		AFL		0			
SB 2664	WINGS - SPOILER CENTER HINGE MOUNTING BOLT REPLACEMENT, AND SPOILER INBOARD AND OUTBOARD HINGE ASSEMBLY INSPECTION/REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 27-3005	FLIGHT CONTROLS - INSTALLATION OF THE PITCH TRIM INTERFACE CONTROLLER KIT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 27-3045	FLIGHT CONTROLS - MAIN FLAP ROD ASSEMBLY RIVET INSPECTION/REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 27-3464	FLIGHT CONTROLS - REPLACEMENT OF A194 ROLL TRIM PRINTED CIRCUIT BOARD (PCB), SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 27-3579	FLIGHT CONTROLS - SPOILER CONTROL CABLE TURNBUCKLE RETENTION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
01-FEB-2005		HRS/MSC -		0			
		AFL		0			
SB 27-3579 R01	FLIGHT CONTROLS - SPOILER CONTROL CABLE TURNBUCKLE RETENTION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
01-MAY-2005		HRS/MSC -		0			
		AFL		0			
SB 27-4100	FLIGHT CONTROLS - INSPECTION / REPLACEMENT OF PITCH TRIM ACTUATOR, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS		08-MAY-2018			
01-MAR-2012		HRS/MSC -		2736:50			
		AFL		2454			
SB 2707	FLIGHT CONTROLS - AFT FLAP CONTROL ROD ASSEMBLIES INSPECTION/REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2707 R01	FLIGHT CONTROLS - AFT FLAP CONTROL ROD ASSEMBLIES INSPECTION/REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 2742	LIFTING AND SHORING - BONDING OF THE WING JACK PAD ASSEMBLY, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 28-3076	FUEL - AFT FUEL TANK DRAIN LINE MODIFICATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 28-3427	FUEL - MOTIVE FLOW SHUTOFF VALVE REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC DUE		0			
		AFL		0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 30-3008	ICE AND RAIN PROTECTION - WING TEMPERATURE THERMAL SWITCH ASSEMBLY REPLACEMENT, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
		HRS/MSC -		0			
		AFL		0			
SB 30-3008 R01	ICE AND RAIN PROTECTION - WING TEMPERATURE THERMAL SWITCH ASSEMBLY REPLACEMENT, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
		HRS/MSC -		0			
		AFL		0			
SB 30-3198	ICE AND RAIN PROTECTION - HORIZONTAL STABILIZER DEICE HEATING ELEMENT WIRING MODIFICATION, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
		HRS/MSC -		0			
		AFL		0			
SB 32-3120	LANDING GEAR - BRAKE MASTER CYLINDER REWORK, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
		HRS/MSC -		0			
		AFL		0			
SB 32-3300	LANDING GEAR - PARKING BRAKE HYDRAULIC LINE CLAMP INSTALLATION, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
		HRS/MSC -		0			
		AFL		0			
SB 32-3416	REPLACEMENT OF MAIN LANDING GEAR CYLINDERS, P/N 46010-15, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
		HRS/MSC -		0			
		AFL		0			
SB 32-3468	INSPECTION/REPLACEMENT OF P/N C100169 BRAKE MIXING VALVES, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
01-OCT-2001		HRS/MSC -		0			
		AFL		0			
SB 32-3873	LANDING GEAR - POSITION SWITCH INSPECTION/ADJUSTMENT, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
01-FEB-2008		HRS/MSC -		0			
		AFL		0			
SB 33-3298	LIGHTS - FLASHING BEACON HARDWARE KIT IMPROVEMENT, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
		HRS/MSC -		0			
		AFL		0			
SB 33-3429	LIGHTS - ELECTROLUMINESCENT PANEL CIRCUIT BREAKER COLOR RING CHANGE, SERVICE BULLETIN	MOS		17-MAR-2008		MANDATORY	NOT APPLICABLE
		HRS/MSC DUE		0			
		AFL		0			



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 33-4002	LIGHTS - INSTRUMENT LIGHTING POWER SUPPLY WIRING MODIFICATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - IAW THE SB
		MOS		10-DEC-2010			
		HRS/MSC -		391:31			
		AFL		349			
SB 34-3992	NAVIGATION - INSTALLATION OF ROCKWELL COLLINS (RCI) GPS-4000S RECEIVER/SENSOR UNITS WITH TSO APPROVED SOFTWARE UPGRADE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - IAW THE SB
		MOS		10-DEC-2010			
01-MAR-2010		HRS/MSC -		391:31			
		AFL		349			
SB 34-4079	NAVIGATION - DUAL MODE (EMER/NORM) STANDBY COMPASS ALIGNMENT PROCEDURE AND COMPASS CARD, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - CARRIED OUT IAW FIELD SERVICE KIT 128-3418
		MOS		01-DEC-2011			
01-AUG-2011		HRS/MSC -		684			
		AFL		598			
SB 35-3406	OXYGEN - REPLACEMENT OF LOW PRESSURE OXYGEN TUBES, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 36-3376	PNEUMATIC - BLEED AIR V-BAND COUPLING BOLT REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 36-3376 R01	PNEUMATIC - BLEED AIR V-BAND COUPLING BOLT REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 53-3486	FUSELAGE - INSTALLATION OF DRAIN HOLES IN THE MIXER BAY PANELS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 54-3788	NACELLES - ENGINE COWLING FASTENER MODIFICATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 54-3946	NACELLES - LEFT AND RIGHT PYLON FIREWALL INSPECTION AND SEALING, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS		03-APR-2009			
01-FEB-2009		HRS/MSC -					
		AFL					
SB 54-3946 R01	NACELLES - LEFT AND RIGHT PYLON FIREWALL INSPECTION AND SEALING, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - PREVIOUSLY
		MOS		28-APR-2010			
01-MAY-2009		HRS/MSC -		222:33			
		AFL		176			
SB 54-3946 R02	NACELLES - LEFT AND RIGHT PYLON FIREWALL INSPECTION AND SEALING, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS		23-AUG-2011			
		HRS/MSC -		600:10			
		AFL		531			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 55-3505	VERTICAL STABILIZER ATTACH BOLT INSPECTION/REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
01-JAN-2003		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 55-4162	STABILIZERS - HORIZONTAL STABILIZER PIVOT FITTING AND UPPER REAR SPAR INSPECTION, SERVICE BULLETIN					MANDATORY	
19-JAN-2017		MOS		(EFF)			
		HRS/MSC	7400		7400		
		AFL					
SB 57-3449	WING BOLT REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 71-3311	NO. 1 ENGINE REPLACEMENT OF ENGINE ISOLATOR MOUNTS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 71-3311	NO. 2 ENGINE REPLACEMENT OF ENGINE ISOLATOR MOUNTS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 72-3853	ENGINE - INSPECTION/REPLACEMENT OF BLEED AIR DUCT GASKET, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
01-SEP-2007		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 73-3354	NO. 2 ENGINE PART I OF THE ENGINE HYDROMECHANICAL METERING UNIT (HMU) P3 AIR CONDENSATION TRAP: PART II, HMU P3 AIR VENT IMPROVEMENT., SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 73-3354	NO. 1 ENGINE PART I OF THE ENGINE HYDROMECHANICAL METERING UNIT (HMU) P3 AIR CONDENSATION TRAP: PART II, HMU P3 AIR VENT IMPROVEMENT., SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		17-MAR-2008			
		HRS/MSC -		0			
		AFL		0			
SB 73-3888	NO. 1 ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (HMU) P3 AIR DELIVERY TUBING MODIFICATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - 73-3888 R1
		MOS		04-JAN-2009			
		HRS/MSC -		201:42			
		AFL		146			
SB 73-3888	NO. 2 FUEL AND CONTROL - HYDROMECHANICAL UNIT (HMU) P3 AIR DELIVERY TUBING MODIFICATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - 73-3888 R1
		MOS		04-JAN-2009			
		HRS/MSC -		201:42			
		AFL		146			



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 73-3888 R01	NO.1 ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (HMU) P3 AIR DELIVERY TUBING MODIFICATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-JUL-2008		MOS HRS/MSC - AFL		04-JAN-2009 201:42 146			
SB 73-3888 R01	NO.2 ENGINE FUEL AND CONTROL - HYDROMECHANICAL UNIT (HMU) P3 AIR DELIVERY TUBING MODIFICATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-JUL-2008		MOS HRS/MSC - AFL		04-JAN-2009 201:42 146			



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - AD - PCE-JG0091/JT15D-5R							
TCCA CF-2008-23	NO. 1 ENGINE - ENGINE FLAMEOUT IN ICING					MANDATORY	COMPLIED WITH
18-JUL-2008		MOS		04-JAN-2009			
		HRS/MSC -		201:42			
		AFL					
		ENC		144			



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 2 - AD - PCE-JG0092/JT15D-5R							
TCCA CF-2008-23	NO. 2 ENGINE - ENGINE FLAMEOUT IN ICING					MANDATORY	COMPLIED WITH
18-JUL-2008		MOS		04-JAN-2009			
		HRS/MSC -		201:42			
		ENC		144			



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - SB - PCE-JG0091/JT15D-5R							
ASB A7295	NO. 1 ENGINE - INSPECTION OF HYDROMECHANICAL TURBOFAN FUEL CONTROL, ALERT SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS		09-JUL-2015			
	29-OCT-1990	HRS/MSC -		2041:02			
		ENC		1752			
ASB JT15D-72-A7611	NO. 1 ENGINE - INTRODUCTION OF NEW COMPRESSOR AIR TO HMU DELIVERY TUBE, ALERT SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - 73-3888 R1
		MOS		04-JAN-2009			
		HRS/MSC -		201:42			
		ENC		144			
ASB JT15D-72-A7611 R1	NO. 1 ENGINE - INTRODUCTION OF NEW COMPRESSOR AIR TO HMU DELIVERY TUBE, ALERT SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
		MOS		04-JAN-2009			
		HRS/MSC -		201:42			
		ENC		144			
SB JT15D-72-7292 R1	NO. 1 ENGINE - INTRODUCTION OF IMPROVED FUEL MANIFOLD TRANSFER TUBE LOCKING BRACKETS, SERVICE BULLETIN					CATEGORY 4	COMPLIED WITH - FOUND EMBODIED
		MOS		07-JAN-2022			
	30-MAY-2016	HRS/MSC -		3611:42			
		ENC		3222			
SB JT15D-72-7610	NO. 1 ENGINE - INTRODUCTION OF NEW LEFT AND RIGHT FUEL FILTER BRACKETS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
		MOS		17-MAR-2008			
	15-NOV-2007	HRS/MSC -		0			
		ENC		0			
SB JT15D-72-7617	NO. 1 ENGINE - OIL CHECK VALVE ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
		MOS		07-JAN-2022			
	07-MAR-2008	HRS/MSC -		3611:42			
		ENC		3222			
SB JT15D-72-7618 R03	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
		MOS		07-JAN-2022			
	15-APR-2019	HRS/MSC -		3611:42			
		ENC		3222			
SB JT15D-72-7625 R1	NO. 1 ENGINE - REPLACEMENT OF GASKET, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
		MOS		07-JAN-2022			
	26-NOV-2010	HRS/MSC -		3611:42			
		ENC		3222			
SB JT15D-72-7627	NO. 1 ENGINE - REPLACEMENT OF LOW PRESSURE TURBINE INTERSTAGE ROTOR AIR SEAL AND ROTOR AIR SEAL, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
		MOS		07-JAN-2022			
	05-MAR-2012	HRS/MSC -		3611:42			
		ENC		3222			
SB JT15D-72-7628 R3	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH
		MOS		07-JAN-2022			
	04-MAY-2015	HRS/MSC -		3611:42			
		ENC		3222			



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	JT15D-72-7630	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF FUEL COOLED OIL COOLER, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY S/N
	11-JUN-2012		MOS HRS/MSC - ENC			22-JUN-2012		



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT

All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 2 - SB - PCE-JG0092/JT15D-5R							
ASB A7295	NO. 2 ENGINE - INSPECTION OF HYDROMECHANICAL TURBOFAN FUEL CONTROL, ALERT SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS		09-JUL-2015			
	29-OCT-1990	HRS/MSC -		2041:02			
		ENC		1752			
ASB JT15D-72-A7611	NO. 2 ENGINE - INTRODUCTION OF NEW COMPRESSOR AIR TO HMU DELIVERY TUBE, ALERT SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - 73-3888 R1
		MOS		04-JAN-2009			
		HRS/MSC -		201:42			
		ENC		144			
ASB JT15D-72-A7611 R1	NO. 2 ENGINE - INTRODUCTION OF NEW COMPRESSOR AIR TO HMU DELIVERY TUBE, ALERT SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
		MOS		04-JAN-2009			
		HRS/MSC -		201:42			
		ENC		144			
SB JT15D-72-7292 R1	NO. 2 ENGINE - INTRODUCTION OF IMPROVED FUEL MANIFOLD TRANSFER TUBE LOCKING BRACKETS, SERVICE BULLETIN					CATEGORY 4	COMPLIED WITH - FOUND EMBODIED
		MOS		16-DEC-2021			
	30-MAY-2016	HRS/MSC -		3611:42			
		ENC		3222			
SB JT15D-72-7610	NO. 2 ENGINE - INTRODUCTION OF NEW LEFT AND RIGHT FUEL FILTER BRACKETS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
		MOS		17-MAR-2008			
	15-NOV-2007	HRS/MSC -		0			
		ENC		0			
SB JT15D-72-7617	NO. 2 ENGINE - OIL CHECK VALVE ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
		MOS		16-DEC-2021			
	07-MAR-2008	HRS/MSC -		3611:42			
		ENC		3222			
SB JT15D-72-7618 R03	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
		MOS		16-DEC-2021			
	15-APR-2019	HRS/MSC -		3611:42			
		ENC		3222			
SB JT15D-72-7625 R1	NO. 2 ENGINE - REPLACEMENT OF GASKET, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - FOUND EMBODIED
		MOS		16-DEC-2021			
	26-NOV-2010	HRS/MSC -		3611:42			
		ENC		3222			
SB JT15D-72-7627	NO. 2 ENGINE - REPLACEMENT OF LOW PRESSURE TURBINE INTERSTAGE ROTOR AIR SEAL AND ROTOR AIR SEAL, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
		MOS		16-DEC-2021			
	05-MAR-2012	HRS/MSC -		3611:42			
		ENC		3222			
SB JT15D-72-7628 R3	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH
		MOS		16-DEC-2021			
	04-MAY-2015	HRS/MSC -		3611:42			
		ENC		3222			



Master AD/SI Report

HAWKER 400XP S/N RK-552 (OK-BZZ): 4607:07HRS, 3829 AFL as of 29-Nov-2022

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 29-Nov-2022

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	JT15D-72-7630	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF FUEL COOLED OIL COOLER, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY S/N.
	11-JUN-2012		MOS HRS/MSC - ENC			22-JUN-2012		