

OWNER: AERODATA AG
ADDRESS: HERMANN-BLENK-STRASSE 34-36
 BRAUNSCHWEIG D-38108
PHONE: +49 531 2359 - 0
FAX: +49 531 2359 - 158

OPERATOR: AERODATA AG
ADDRESS: HERMANN-BLENK-STRASSE 34-36
 BRAUNSCHWEIG D-38108
PHONE: +49 531 2359 - 0
FAX: +49 531 2359 - 158

ANALYST: GUILLAUME DUCLOS +33-1.55.93.45.84 (DIRECT)
EMAIL: GUILLAUME.DUCLOS@CAMPSYSTEMS.EU +33 (0) 1.55.93.45.80 (OFFICE)
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Task Type In: ('AD','ADP','SB','SBP'); Group by Profile or Bulletin: Profile Type; Mode: With Compliance or Next Due; For: Airframe,Engine,APU Etc;

AIRCRAFT **SERIAL/REGNO:** FL-322/D-CCAM

MODEL: SUPER KING AIR B300 (350)

MANUFACTURER: TEXTRON AVIATION INC.

DATES	LAST ACTUALS		CURRENT ACTUAL	
MANUFACTURER DATE: 16-MAY-2001	3053:30 A/C HRS	as of 10-SEP-2021	_____ A/C HRS	as of ____/____/____
	2124 AFL	as of 10-SEP-2021	_____ AFL	as of ____/____/____

ENGINE NO. 1 **SERIAL/PART:** PCE-PK0384/3102700-01

MODEL: PT6A-60A

MANUFACTURER: PRATT & WHITNEY CANADA CORP.

INSTALLED ON 05-JUL-2001	LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	3053:30 ENG. HRS	as of 10-SEP-2021	_____ ENG. HRS as of ____/____/____
0 ENC		2124 ENC	as of 10-SEP-2021	_____ ENC as of ____/____/____

ENGINE NO. 2 **SERIAL/PART:** PCE-PK0385/3102700-01

MODEL: PT6A-60A

MANUFACTURER: PRATT & WHITNEY CANADA CORP.

INSTALLED ON 05-JUL-2001	LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	3053:30 ENG. HRS	as of 10-SEP-2021	_____ ENG. HRS as of ____/____/____
0 ENC		2124 ENC	as of 10-SEP-2021	_____ ENC as of ____/____/____

PROPELLER NO **SERIAL/PART:** FWA4142/HC-B4MP-3

MODEL: HC-B4MP-3

MANUFACTURER: HARTZELL PROPELLER INC.

INSTALLED ON 10-MAY-2019	LAST ACTUALS		CURRENT ACTUAL	
3668:36 PROP HRS	3051:35 A/C HRS	3670:31 PROP HRS	as of 10-SEP-2021	_____ PROP HRS as of ____/____/____

PROPELLER NO **SERIAL/PART:** FWA4127/HC-B4MP-3

MODEL: HC-B4MP-3

MANUFACTURER: HARTZELL PROPELLER INC.

INSTALLED ON 10-MAY-2019	LAST ACTUALS		CURRENT ACTUAL	
3668:36 PROP HRS	3051:35 A/C HRS	3670:31 PROP HRS	as of 10-SEP-2021	_____ PROP HRS as of ____/____/____

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - AD - FL-322/D-CCAM							
FAA 2002-23-11	TO PREVENT THE BALANCE WEIGHT ATTACHMENT SCREWS FROM BECOMING LOOSE					MANDATORY	NOT APPLICABLE - BY AIRCRAFT S/N
39-12955 10-JAN-2003	MOS HRS/MSC - AFL			01-APR-2003 55			
FAA 2003-02-03	TO ASSURE THAT CLEAR AND COMPLETE OPERATING INSTRUCTIONS ARE VISIBLE FOR OPENING THE AIRSTAIR DOOR AND EMERGENCY EXITS					MANDATORY	NOT APPLICABLE
39-13019 07-MAR-2003	MOS HRS/MSC - AFL			01-APR-2003 55			
FAA 2004-17-02	TO DETECT AND CORRECT LOOSE BOLTS NOT SECURING THE PEDESTAL CROSS SHAFT					MANDATORY	COMPLIED WITH - BY AIRCRAFT S/N
39-13774 04-OCT-2004	MOS HRS/MSC - AFL			01-DEC-2008			
FAA 2005-01-04 CORRECTION	TO PREVENT FUEL FLOW INTERRUPTION					MANDATORY	NOT APPLICABLE
39-13928 22-FEB-2005	MOS HRS/MSC - AFL			01-DEC-2008			
FAA 2005-01-18 CORRECTION	TO DETECT AND CORRECT ANY CRACKED FUSELAGE STRINGERS IN THE REAR PRESSURE BULKHEAD AREA						NOT APPLICABLE - BY AIRCRAFT S/N
39-13943	MOS HRS/MSC - AFL			01-DEC-2008			
FAA 2006-19-09	TO PREVENT THE PASSENGER SEATS FROM FAILING DURING EMERGENCY LANDING CONDITIONS WHEN HIGH INERTIAL LOADINGS OCCUR					MANDATORY	COMPLIED WITH - BY AERODATA(MSB 25-3640 R1)
39-14766 24-OCT-2006	MOS HRS/MSC - AFL			01-MAY-2005			
FAA 2006-23-02	TO DETECT AND CORRECT IMPROPERLY ASSEMBLED OR DAMAGED FLIGHT CONTROLS					MANDATORY	NOT APPLICABLE - BY AIRCRAFT S/N
39-14814 13-DEC-2006	MOS HRS/MSC - AFL			01-DEC-2008			
FAA 2007-12-06	TO DETECT AND CORRECT IMPROPERLY ASSEMBLED OR DAMAGED FLIGHT CONTROLS					MANDATORY	NOT APPLICABLE - BY AIRCRAFT S/N
39-14814 16-JUL-2007	MOS HRS/MSC - AFL			01-DEC-2008			
FAA 2008-07-10	TO PREVENT COLLAPSED PNEUMATIC SUPPLY TUBES					SUPERSEDED	NOT APPLICABLE - BY AIRCRAFT S/N
39-15451 10-APR-2008	MOS HRS/MSC - AFL			01-DEC-2008			
FAA 2010-05-10	OPERATIONAL CHECK OF THE LEFT AND RIGHT PITOT HEAT ANNUNCIATORS FOR ILLUMINATION					MANDATORY	NOT APPLICABLE - MSB 31-3948 CHECKED, A/C NOT AFFECTED
39-16220 08-APR-2010	MOS HRS/MSC - AFL			28-JUN-2010 1614 1237			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2010-26-03	REPLACE THE PNEUMATIC SUPPLY TUBING FROM THE REAR SPAR						NOT APPLICABLE - PER S/N
39-16542 20-DEC-2010		MOS HRS/MSC - AFL		01-DEC-2010			
FAA 2011-15-05 19-AUG-2011	TO CORRECT THE PUBLISHED DATA IN THE AIRPLANE FLIGHT MANUAL AND THE PILOT'S OPERATING HANDBOOK AND ENSURE IT CORRESPONDS WITH THE PUBLISHED DATA IN THE PILOT'S CHECKLIST				01-JUL-2011	MANDATORY	NOT APPLICABLE - PER POH P/N
		MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
APPLIANCE - FL-322/D-CCAM							
EASA 2009-0097	APPLIANCE AD - NAVIGATION - MODE S TRANSPONDER - CHECK / MODIFICATION (SUPERSEDED BY EASA AD 2010-0067)					MANDATORY	COMPLIED WITH
06-MAY-2009		MOS		04-NOV-2009			
		HRS/MSC	-	1611:20			
		AFL		1235			
EASA 2010-0067	APPLIANCE AD - NAVIGATION - MODE S TRANSPONDER - CHECK/MODIFICATION					MANDATORY	COMPLIED WITH
26-APR-2010		MOS		24-AUG-2010			
		HRS/MSC	-	1614:46			
		AFL		1237			
EASA 2013-0020 R01 PARA (1)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANIZATIONS OTHER THAN THE DESIGN APPROVAL HOLDER					MANDATORY	NOT APPLICABLE - THE AIRCRAFT WAS MANUFACTURED AFTER CERTIFICATION SPEC FAR PART 23 EFFECTIVE FEBRUARY 01, 1965
12-MAR-2013		MOS		01-APR-2013			
		HRS/MSC	-	2705			
		AFL		1958			
EASA 2019-0179 PARA (1)	AMEND THE APPLICABLE AFM(S) IN ACCORDANCE WITH THE OPSB AND INSTALL THE APPROPRIATE PLACARD; VERIFY THAT A PRESSURE ALTITUDE REPORTING TRANSPONDER IS INSTALLED AND INTRODUCE PRE-FLIGHT CHECKS					SUPERSEDED	NOT APPLICABLE - EQUIPMENT NOT INSTALLED
31-JUL-2019		DAYS		09-DEC-2019			
		HRS/MSC	-	3051:35			
		AFL		2122			
EASA 2019-0179 PARA (2)	MODIFY THE AEROPLANE BY INSTALLING A SOFTWARE UPDATE THAT RECTIFIES THE UNSAFE CONDITION ADDRESSED BY THIS AD; BEFORE NEXT FLIGHT AFTER MODIFICATION REMOVE THE AFM CHANGES AND PLACARD AND CONCURRENT WITH REMOVAL OF THE AFM(S) CHANGE AND PLACARD INSERT THE APPLICABLE POST-SB MTB 34-02 AFM TC					SUPERSEDED	NOT APPLICABLE
31-JUL-2019		MOS		06-JAN-2020			
		HRS/MSC	-	3051:35			
		AFL		2122			
EASA 2019-0179 R01	APPLIANCE AD - NAVIGATION - AIRBORNE COLLISION AVOIDANCE SYSTEM DISPLAY SOFTWARE - UPDATE					MANDATORY	NOT APPLICABLE
24-APR-2020		MOS		30-APR-2020			
		HRS/MSC	-	3051:35			
		AFL		2122			
EASA 2019-0179 R01 PARA (1)	AMEND THE APPLICABLE AFM(S) IAW THE OPSB AND INSTALL THE APPROPRIATE PLACARD; VERIFY THAT A PRESSURE ALTITUDE REPORTING TRANSPONDER IS INSTALLED; AND INTRODUCE PRE-FLIGHT CHECKS					MANDATORY	NOT APPLICABLE
24-APR-2020		DAYS		30-APR-2020			
		HRS/MSC	-	3051:35			
		AFL		2122			
EASA 2019-0179 R01 PARA (2) & (4)	MODIFY THE AEROPLANE BY INSTALLING A SOFTWARE UPDATE THAT RECTIFIES THE UNSAFE CONDITION THEN REMOVE THE AFM(S) CHANGES AND PLACARD, AS REQUIRED BY PARA (1) OF THIS AD. CONCURRENTLY, FOR CERTAIN TEXTRON AVIATION AEROPLANES, INSERT THE APPLICABLE POST-SB MTB-34-02 AFM TC OR POST-MOD AFMS, AS IDENTIFIED IN APPENDIX 2 OF THIS AD					MANDATORY	NOT APPLICABLE
24-APR-2020		MOS		30-APR-2020			
		HRS/MSC	-	3051:35			
		AFL		2122			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2019-0235	APPLIANCE AD - EQUIPMENT / FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER - INSPECTION / MODIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE
04-OCT-2019		MOS HRS/MSC - (s) AFL		29-OCT-2019 3051:35 2122			
EASA 2019-0235 PARA (1) THRU (4)	CONCURRENTLY ACCOMPLISH PARAS (1.1) AND (1.2) OF THIS AD AND ACCOMPLISH APPLICABLE CORRECTIVE ACTION(S) (IF, DISCREPANCIES ARE DETECTED, AS IDENTIFIED IN THE SIL); OPERATORS MAY CONTINUE TO USE ELTS WITH THE ORIGINAL G-SWITCHES BY REDUCING THE INTERVAL OF THE G-SWITCH TESTING, AS REQUIRED BY PARA (1.1)					MANDATORY	NOT APPLICABLE
04-OCT-2019		DAYS HRS/MSC - AFL		29-OCT-2019 3051:35 2122			
EASA 2019-0235 PARA (5)	REMOVE THE AFFECTED PART FROM SERVICE IAW THE INSTRUCTIONS OF SECTION 7 OF THE SB FOR THE PURPOSE OF IN-SHOP MODIFICATION					MANDATORY	NOT APPLICABLE
04-OCT-2019		MOS HRS/MSC - AFL		29-OCT-2019 3051:35 2122			
EASA 2019-0235 PARA (6)	IN-SHOP CORRECTION OF AN AFFECTED PART OR MODIFICATION INTO A SERVICEABLE PART IAW THE INSTRUCTIONS OF THE SB CONSTITUTES TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS AND TESTING AS REQUIRED BY THIS AD FOR THAT PART					MANDATORY	NOT APPLICABLE
04-OCT-2019		MOS HRS/MSC - (s) AFL		29-OCT-2019 3051:35 2122			
EASA 2019-0235 PARA (9)	DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED PART THAT HAS ACCUMULATED 10 YEAR TIS OR MORE					MANDATORY	NOT APPLICABLE
04-OCT-2019		MOS HRS/MSC - (s) AFL		29-OCT-2019 3051:35 2122			
FAA 2002-06-06	APPLIANCE AD - TDR-94 MODE S TRANSPONDERS (COLLINS PART NUMBER (CPN) 622-9352-004) AND TDR-94D MODE S TRANSPONDERS (CPN 622-9210-004)					NOT APPLICABLE	
39-12683 03-MAY-2002		MOS HRS/MSC - AFL		01-APR-2003 55			
FAA 2002-14-19	APPLIANCE AD - TO PREVENT AN UNWARRANTED DISPLAY OF THE ADC FLAG WHEN SWITCHING STATIC AIR SOURCES					MANDATORY	NOT APPLICABLE
39-12819 23-AUG-2002		MOS HRS/MSC - AFL		01-APR-2003 55			
FAA 2003-13-08	APPLIANCE AD - TO PREVENT THE LOADING OF THE BARO SET POTENTIOMETER					SUPERSEDED	NOT APPLICABLE - GOODRICH TAWS 8000 NOT INSTALLED
39-13208 21-JUL-2003		MOS HRS/MSC - AFL		08-JUN-2004 63:24 51			
FAA 2004-08-15	APPLIANCE AD - TO PREVENT THE LOADING OF THE BARO SET POTENTIOMETER					MANDATORY	NOT APPLICABLE - GOODRICH TAWS 8000 NOT INSTALLED
39-13584 07-JUN-2004		MOS HRS/MSC - AFL		08-JUN-2004 63:24 51			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2005-18-20	APPLIANCE AD - TO PREVENT GOODRICH "FASTPROP" PROPELLER DE-ICERS FROM DETACHING FROM THE PROPELLER BLADE					MANDATORY	COMPLIED WITH
39-14261		MOS HRS/MSC AFL	DAILY	13-JAN-2006 576:54 384			
FAA 2010-01-03	APPLIANCE AD - REPLACE PORTABLE HALON 1211 (BCF) FIRE EXTINGUISHERS MANUFACTURED BY FIRE FIGHTING ENTERPRISES LIMITED WITH SERVICEABLE FIRE EXTINGUISHERS					MANDATORY	NOT APPLICABLE
39-16159 20-JAN-2010		MOS HRS/MSC AFL	-	01-JUN-2010 1614 1237			
FAA 2011-14-08	APPLIANCE AD - INSPECTION/RECORDS CHECK TO DETERMINE THE MANUFACTURER AND PART NUMBER OF THE OXYGEN MASK ASSEMBLIES INSTALLED, AN INSPECTION TO DETERMINE THE MANUFACTURING DATE AND MODIFICATION STATUS IF CERTAIN OXYGEN MASK ASSEMBLIES ARE INSTALLED, AND CORRECTIVE ACTION FOR CERTAIN OXYGEN MASK ASSEMBLIES					MANDATORY	NOT APPLICABLE - BY PN INSTALLED
19-AUG-2011		MOS HRS/MSC AFL	-	05-APR-2012 2197:45 1639			
FAA 2011-14-08 PARA (H)	MODIFY THE OXYGEN MASK ASSEMBLY BY REPLACING THE IN-LINE FLOW INDICATOR (AFTER THE INSPECTION IN PARAGRAPH (G)(2) OF THIS AD AND IT WAS DETERMINED THE IN-LINE FLOW INDICATOR MUST BE REPLACED)					MANDATORY	COMPLIED WITH - ONE MASK FLOW INDICATOR REPLACED
19-AUG-2011		MOS HRS/MSC AFL	-	01-APR-2012 2197			
FAA 2019-12-09	APPLIANCE AD - NAVIGATION - FDSA-6500 TCAS - AFM OR AFMS LIMITATIONS SECTION - REVISION / PLACARD INSTALLATION					MANDATORY	NOT APPLICABLE
23-JUL-2019		DAYS HRS/MSC AFL	-	30-APR-2020 3051:35 2122			
FAA 2021-05-17	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS FDSA-6500 FLIGHT DISPLAY SYSTEM - OPERATING LIMITIATIONS / SOFTWARE UPGRADE					MANDATORY	NOT APPLICABLE
29-APR-2021		MOS HRS/MSC AFL	-	10-MAY-2021 3053:30 2124			
FAA 2021-05-17 PARA (G)(1) & (G)(2)	REVISE THE AIRCRAFT FLIGHT MANUAL (AFM) OR AFM SUPPLEMENT (AFMS), FABRICATE A PLACARD FOR EACH PRIMARY FLIGHT DISPLAY AND INSTALL THE PLACARD ON THE BOTTOM OF EACH PRIMARY FLIGHT DISPLAY BEZEL (RESTATEMENT OF FAA AD 2019-12-09)					MANDATORY	NOT APPLICABLE
29-APR-2021		MOS HRS/MSC AFL	-	10-MAY-2021 3053:30 2124			
FAA 2021-05-17 PARA (G)(3)	UPGRADE THE FDSA-6500 FIELD LOADABLE SOFTWARE					MANDATORY	NOT APPLICABLE
29-APR-2021		MOS HRS/MSC AFL	-	10-MAY-2021 3053:30 2124			
FAA 2021-05-17 PARA (G)(5)	AS OF THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL A ROCKWELL COLLINS FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500 P/N 810-0234-1H0001, 810-0234-1H0002, 810-0234-1H0003, 810-0234-2H0001, 810-0234-2C0001, 810-0234-2C0002, OR 810-0234-4B0001 ON ANY AIRPLANE					MANDATORY	NOT APPLICABLE
29-APR-2021		MOS HRS/MSC AFL	-	10-MAY-2021 3053:30 2124			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
LBA D-2019-192 R01	APPLIANCE AD - NAVIGATION - AIRBORNE COLLISION AVOIDANCE SYSTEM DISPLAY SOFTWARE - UPDATE					MANDATORY	NOT APPLICABLE
20-APR-2020		MOS		30-APR-2020			
		HRS/MSC	-		3051:35		
		AFL			2122		
LBA D-2019-249	APPLIANCE AD - EQUIPMENT / FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER - INSPECTION / MODIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE
27-SEP-2019		MOS		29-OCT-2019			
		HRS/MSC	-		3051:35		
		AFL			2122		
LBA D-2021-120	APPLIANCE AD - ROCKWELL COLLINS - NAVIGATION - GLOBAL POSITIONING SYSTEMS - UPGRADE					MANDATORY	NOT APPLICABLE
05-MAY-2021		MOS		10-MAY-2021			
		HRS/MSC	-		3053:30		
		AFL			2124		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - SB - FL-322/D-CCAM							
COM 2016-07	KING AIR SERIES MODEL COMMUNIQUE - XM WEATHER TAF DATA ON PRO LINE 21 KING AIRS WITH XM RECEIVER PART NUMBER 822-2031-002, COMMUNIQUE						NOT APPLICABLE
01-JUN-2016	MOS HRS/MSC - (s) AFL			01-NOV-2018 3051:35 2122			
SB 11-3211	PLACARDS & MARKINGS - MAIN AND AUXILIARY FUEL TANK USEABLE AND TOTAL FUEL QUANTITY DECAL INSTALLATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
01-NOV-1998	MOS HRS/MSC - AFL			01-APR-2003 55			
SB 21-3303 R01	AIR CONDITIONING - INSTALLATION OF NEW COMPRESSOR DRIVE QUILL SHAFT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
01-JUN-2000	MOS HRS/MSC - AFL			01-APR-2003 55			
SB 22-3180 R01	AUTO FLIGHT - ANNOUNCEMENT OF AN AIRWORTHINESS DIRECTIVE AGAINST ALLIED SIGNAL AEROSPACE BENDIX/KING MODEL KSA 470 AUTOPILOT SERVO ACTUATORS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
01-JUL-1999	MOS HRS/MSC - AFL			01-APR-2003 55			
SB 23-3270	COMMUNICATIONS - INTERNATIONAL CIVIL AVIATION ORGANIZATION (ICAO) REQUIREMENT FOR 8.33 KHZ VHF COMM SPACING (STC SA00782WI-D), SERVICE BULLETIN						COMPLIED WITH - PCW BY RYTHEON
01-AUG-1998	MOS HRS/MSC - AFL						
SB 24-3058 R01	ELECTRICAL POWER - GROUND INTERPHONE AMPLIFIER, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
01-JUL-2002	MOS HRS/MSC - AFL			01-APR-2003 55			
SB 24-3181	ELECTRICAL - GENERATOR CONTROL UNIT INSPECTION/REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
01-APR-1999	MOS HRS/MSC - AFL			01-APR-2003 55			
SB 24-3245	ELECTRICAL POWER - RELOCATION OF THE LANDING GEAR 60 AMP CIRCUIT BREAKER AND IMPROVEMENTS TO THE INBOARD WING LEADING EDGE INLET DUCT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
01-OCT-2000	MOS HRS/MSC - AFL			01-APR-2003 55			
SB 24-3363	ELECTRICAL - INSTALLATION OF EXTERNAL DC POWER SWITCH TRANSIENT SUPPRESSION KIT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
01-APR-2003	MOS HRS/MSC - AFL			01-APR-2003 55			
SB 24-3546	REPLACEMENT OF THE "00" AWG WIRE HARNESS ASSEMBLY, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
01-APR-2003	MOS HRS/MSC - AFL			01-APR-2003 55			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 24-3681	ELECTRICAL POWER - INSPECTION OF EXTERNAL POWER RELAY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-AUG-2004		MOS		27-JAN-2005			
		HRS/MSC	-	93:48			
		AFL		75			
SB 2472 R02	FUSELAGE - INSPECTION/MODIFICATION OF AFT FUSELAGE STRINGERS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		24-SEP-2019			
		HRS/MSC		3051:35			
		AFL	500 (s)	2122			
SB 25-3418	EQUIPMENT/FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER (ELT) PLACARD, SERVICE BULLETIN					COMPLIED WITH	
01-NOV-2002		MOS		01-APR-2003			
		HRS/MSC	-	55			
		AFL					
SB 25-3640	EQUIPMENT/FURNISHINGS - CABIN SWIVELING CHAIR FRAME MODIFICATION, SERVICE BULLETIN					SUPERSEDED	NOT APPLICABLE
01-MAY-2005		MOS		01-JUN-2005			
		HRS/MSC	-	195			
		AFL		274			
SB 2598 R02	EQUIPMENT/FURNISHINGS - EMERGENCY LOCATOR PLACARD INSTALLATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
01-JUN-2000		MOS		01-APR-2003			
		HRS/MSC	-	55			
		AFL					
SB 2635	LIGHTS - A125 ANNUNCIATOR CONTROL MODULE ASSEMBLY REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
01-JUN-1997		MOS		01-APR-2003			
		HRS/MSC	-	55			
		AFL					
SB 2658 R02 LT	LANDING GEAR - MAIN LANDING GEAR ACTUATOR BEARING SUPPORT BRACKET REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
01-MAY-1999		MOS		01-APR-2003			
		HRS/MSC	-	55			
		AFL					
SB 2658 R02 RT	LANDING GEAR - MAIN LANDING GEAR ACTUATOR BEARING SUPPORT BRACKET REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
01-MAY-1999		MOS		01-APR-2003			
		HRS/MSC	-	55			
		AFL					
SB 2676	ENVIRONMENTAL/AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM PNEUMATIC TUBING INSPECTION/REPAIR, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		01-APR-2003			
		HRS/MSC	-	55			
		AFL					
SB 27-3038	STABILIZERS - INSP OF RUDDER TORQUE SHAFT SUPPORT BEARING RETENTION NUT FOR THREAD ENGAGEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
01-MAR-2000		MOS		01-APR-2003			
		HRS/MSC	-	55			
		AFL					
SB 27-3044	FLIGHT CONTROLS - TRIM ACTUATOR LUBRICATION PLACARD, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
01-APR-2000		MOS		01-APR-2003			
		HRS/MSC	-	55			
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 27-3095	FLIGHT CONTROLS - ADDITION OF JUMPER WIRE TO STALL WARNING LIFT COMPUTER, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
01-NOV-2001		MOS		01-APR-2003			
		HRS/MSC	-	55			
		AFL					
SB 27-3232	FLIGHT CONTROLS - INSPECTION FOR CONTROL COLUMN INTERFERENCE WITH WIRING BEHIND THE INSTRUMENT PANEL, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		01-APR-2003			
		HRS/MSC	-	55			
		AFL					
SB 27-3459	FLIGHT CONTROL - FLIGHT CONTROL GUST LOCK INSPECTION/REPLACEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS		11-FEB-2020			
		HRS/MSC	-	3051:35			
		AFL		2122			
SB 27-3459 R02	FLIGHT CONTROLS - FLIGHT CONTROL (GUST) LOCK INSPECTION / REPLACEMENT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
01-NOV-2016		MOS	12 (s)	25-NOV-2020			
		HRS/MSC		3053:30			
		AFL		2124			
SB 27-3492	CONTROL COLUMN INSPECTION/MODIFICATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - PCW
01-OCT-2001		MOS		14-APR-2003			
		HRS/MSC	-	55:04			
		AFL		41			
SB 27-3668 R01	FLIGHT CONTROLS - INSPECTION/MODIFICATION OF AILERON OUTBOARD HINGE FITTING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-SEP-2004		MOS		27-JAN-2005			
		HRS/MSC	-	93:48			
		AFL		75			
SB 2715	COMMUNICATIONS - REPLACEMENT OF THE A017 COMPONENT PRINTED CIRCUIT BOARD, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
01-MAY-1997		MOS		01-APR-2003			
		HRS/MSC	-	55			
		AFL					
SB 2718 R02	FUEL - REPLACEMENT OF MIL-H-6000B HOSE MANUFACTURED BY BUCKEYE RUBBER PRODUCTS INC., SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		01-APR-2003			
		HRS/MSC	-	55			
		AFL					
SB 2728 R01 LT	LANDING GEAR - MAIN LANDING GEAR ACTUATOR CLEVIS REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		01-APR-2003			
		HRS/MSC	-	55			
		AFL					
SB 2728 R01 RT	LANDING GEAR - MAIN LANDING GEAR ACTUATOR CLEVIS REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
01-FEB-1998		MOS		01-APR-2003			
		HRS/MSC	-	55			
		AFL					
SB 28-3401	FUEL CELL COVER AND GASKET INSTALLATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
01-DEC-2001		MOS		01-APR-2003			
		HRS/MSC	-	55			
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 30-3471	ICE & RAIN PROTECTION - CABIN/COCKPIT WINDOW DEFROST SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
01-OCT-2001		MOS HRS/MSC - AFL		01-APR-2003 55			
SB 32-3057	LANDING GEAR - INSTALLATION OF THE LANDING GEAR HORN SILENCE SWITCH TO THE LEFT HAND POWER LEVER, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
01-JUL-1998		MOS HRS/MSC - AFL		01-APR-2003 55			
SB 32-3073 R01	LANDING GEAR - HAND PUMP INLET FILTER INSTALLATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS HRS/MSC - AFL		01-APR-2003 55			
SB 32-3340	LANDING GEAR - LANDING GEAR HYDRAULIC HAND PUMP REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
01-JAN-2000		MOS HRS/MSC - AFL		01-APR-2003 55			
SB 32-3662 RT	LANDING GEAR - MAIN LANDING GEAR (MLG) PISTON ASSEMBLY REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	- RECOMMENDED NEXT MLG INSPECTION
		MOS HRS/MSC - AFL					
SB 33-3410	LIGHTS - FLASHING BEACON HARDWARE KIT IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-NOV-2000		MOS HRS/MSC - AFL		01-APR-2003 55			
SB 33-3799	LIGHTS - CABIN INDIRECT LIGHTING MODIFICATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-JUL-2006		MOS HRS/MSC - AFL		01-JAN-2007 1114 736			
SB 34-3236 R03	NAVIGATION - YEAR 2000 SOFTWARE ANOMALY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - SAC AFTER
01-SEP-2000		MOS HRS/MSC - AFL		01-JAN-2000			
SB 34-3355	NAVIGATION / PITOT STATIC - AIR DATA FLAG WITH STATIC SOURCE SWITCHING, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
01-MAY-2002		MOS HRS/MSC - AFL		01-OCT-2002 55			
SB 34-3435	NAVIGATION - MODIFICATION OF COLLINS TDR-94/94D STATUS -004 TRANSPONDER, SERVICE BULLETIN					COMPLIED WITH	
03-MAY-2002		MOS HRS/MSC - AFL		01-OCT-2002 55			
SB 34-3507 R05	AIR DATA COMPUTER (COLLINS ADC-85A) INCREASED ACCURACY (RVSM) STC ST01070SE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
01-OCT-2003		MOS HRS/MSC - AFL		01-JUL-2004 76			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 39-3103	EDGELIGHT/OVERHEAD LIGHT CONTROL PANEL, SERVICE BULLETIN						NOT APPLICABLE
01-NOV-2002		MOS HRS/MSC - AFL		01-APR-2003 55			
SB 52-3096 R01	NEW EXTERNAL DOOR OPERATING INSTRUCTIONS PLACARD, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
01-DEC-2004		MOS HRS/MSC - AFL		01-APR-2003 55			
SB 52-3701	DOORS - CABIN/AIRSTAIR DOOR HOOK SWITCH INSTALLATION INSPECTION/MODIFICATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
01-JUL-2003		MOS HRS/MSC - AFL		27-JAN-2005 93:48 75			
SB 53-3400 R01	WING-TO-FUSELAGE FUEL QUANTITY WIRING CONDUIT SEALING MODIFICATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
01-JUL-2003		MOS HRS/MSC - AFL		01-JAN-2004			
SB 53-3592	INSPECTION/INSTALLATION OF MISSING STRINGER CLIPS, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
01-JUL-2003		MOS HRS/MSC - AFL		01-JAN-2004			
SB 55-3082	STABILIZERS - INSPECTION OF THE VERTICAL STABILIZER REAR SPAR ASSEMBLY, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
01-FEB-1998		MOS HRS/MSC - AFL		01-APR-2003 55			
SB 55-3551	ELEVATOR TRIM TAB ASSEMBLY RIVET INSPECTION/REPAIR, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
01-FEB-2003		MOS HRS/MSC - AFL		01-APR-2003 55			
SB 55-3552	RUDDER TRIM TAB ASSEMBLY RIVET INSPECTION/REPAIR, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
01-FEB-2003		MOS HRS/MSC - AFL		01-APR-2003 55			
SB 55-3835	STABILIZERS - INSTALLATION OF EMPENNAGE INSPECTION ACCESS PANELS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-JUN-2008		MOS HRS/MSC - AFL		12-NOV-2012 2525:47 1840			
SB 55-4106 R01	INSPECTION / INSTALLATION OF RIVETS ON THE VERTICAL STABILIZER AFT SPAR CAP, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL NUMBER
01-MAR-2013		MOS HRS/MSC - AFL		01-APR-2013			
SB 57-4126	WINGS - INSPECTION / REPLACEMENT OF INCORRECT RIVETS INSTALLED BY KIT P/N 101-4045, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
01-MAY-2013		MOS HRS/MSC - AFL		16-OCT-2019 3051:35 2122			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 57-4144	WINGS - AILERON HINGE SCREW INSPECTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-FEB-2015		MOS		28-JUL-2015			
		HRS/MSC	-	3051:35			
		AFL		2122			
SB 73-3634 PART II	ENGINE CONTROLS CROSS SHAFT/PEDESTAL MODIFICATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS		18-NOV-2004			
		HRS/MSC	-				
		AFL					
STC EASA 10039000R0-MCH5	STC EASA10039000R0-MCH5 UPGRADE FMS TO SBAS CAPABILITY (SCANDINAIAN AVIONICS), SUPPLEMENTAL TYPE CERTIFICATE						
		MOS		07-MAY-2020			
		HRS/MSC	O/C	3051:35			
		AFL		2122			
STC EASA 10053569R2 (FAA SA00907WI-D)	STC EASA 10053569R2 (FAA SA00907WI-D) TCAS II TRANCEIVER TO VERSION 7.1, SUPPLEMENTAL TYPE CERTIFICATE						
		MOS		07-MAY-2020			
		HRS/MSC	O/C	3051:35			
		AFL		2122			
STC EASA 10061022 (FAA SA0451CH)	TRANSPONDER UPGRADE TO ADS-B OUT CAPABILITY, SUPPLEMENTAL TYPE CERTIFICATE						
		MOS		07-MAY-2020			
		HRS/MSC	O/C	3051:35			
		AFL		2122			
STC SA 1264	STC SA 1264 INSTALLATION OF UNIVERSAL TWAS SYSTEM, SUPPLEMENTAL TYPE CERTIFICATE						
		MOS		27-JAN-2005			
		HRS/MSC	O/C				
		AFL					
STC SA483CH	STC SA483CHSOUND MANAGEMENT SYSTEM, SUPPLEMENTAL TYPE CERTIFICATE						
		MOS		16-MAY-2001			
		HRS/MSC	O/C				
		AFL					
STC SA5152NM	STC SA5152NM RAISBECK WING LOCKER INSTALLATION, SUPPLEMENTAL TYPE CERTIFICATE						
		MOS		16-MAY-2001			
		HRS/MSC	O/C				
		AFL					
STC STC SA2429CE	STC SA2429CE AVACON CAMERA PROVISION INSTALLATION, SUPPLEMENTAL TYPE CERTIFICATE						
		MOS		14-OCT-2013			
		HRS/MSC	O/C				
		AFL					
STC STC SA5151NM	STC SA5151NM DUAL AFT BODY STRAKES, SUPPLEMENTAL TYPE CERTIFICATE						
		MOS		08-MAY-2009			
		HRS/MSC	O/C				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
STC Z34-15-01	STC Z34-15-01 INSTALLATION OF COLLINS TCAS-4000 (ACAS-II) SYSTEM WITH DUAL TRANSPONDER TDR-94D, SUPPLEMENTAL TYPE CERTIFICATE	MOS HRS/MSC AFL	O/C		27-JAN-2005		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - AD - PCE-PK0384/3102700-01							
FAA 1997-04-12	NO. 1 ENGINE - ENGINE - COMPRESSOR BLEED-VALVES (BOV'S) - INSPECT / REPLACE					MANDATORY	COMPLIED WITH - AT MANUFACTURE
14-MAR-1997	MOS HRS/MSC - AFL ENC			17-NOV-2000 0			
FAA 2002-23-13	NO. 1 ENGINE - EXHAUST - INSPECT TURBINE EXHAUST DUCTS FOR LOW-QUALITY WELDS AND CRACKS					MANDATORY	NOT APPLICABLE
39-12957 31-DEC-2002	MOS HRS/MSC - ENC			01-APR-2003 55			
FAA 2004-25-18	NO. 1 ENGINE - PROPELLER GOVERNOR - WOODWARD PROPELLER GOVERNOR ASSEMBLIES, P/N 8210-212H - REPLACE					MANDATORY	NOT APPLICABLE
39-13906 18-JAN-2005	MOS HRS/MSC - ENC			01-DEC-2008			
FAA 2012-09-10	NO. 1 ENGINE - REMOVE FROM SERVICE PMA REPLACEMENT TAATI FIRST STAGE SUN GEAR AND THE PLANET GEARS FROM THE PROPELLER REDUCTION GEARBOX ASSEMBLY					MANDATORY	NOT APPLICABLE - PER ENGINE MODEL
	MOS HRS/MSC - ENC			01-MAY-2012 2245 1670			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 2 - AD - PCE-PK0385/3102700-01							
FAA 1997-04-12	NO. 2 ENGINE - ENGINE - COMPRESSOR BLEED-VALVES (BOV'S) - INSPECT / REPLACE					MANDATORY	COMPLIED WITH - AT MANUFACTURE
14-MAR-1997		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
FAA 2002-23-13	NO. 2 ENGINE - EXHAUST - INSPECT TURBINE EXHAUST DUCTS FOR LOW-QUALITY WELDS AND CRACKS					MANDATORY	NOT APPLICABLE
39-12957		MOS		01-APR-2003			
31-DEC-2002		HRS/MSC	-	55			
		ENC		1670			
FAA 2012-09-10	NO. 2 ENGINE - REMOVE FROM SERVICE PMA REPLACEMENT TAATI FIRST STAGE SUN GEAR AND THE PLANET GEARS FROM THE PROPELLER REDUCTION GEARBOX ASSEMBLY					MANDATORY	NOT APPLICABLE - PER ENGINE MODEL
		MOS		01-MAY-2012			
		HRS/MSC	-	2245			
		ENC		1670			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - SB - PCE-PK0384/3102700-01							
ASB	PT6A-72-A13397	NO. 1 ENGINE - REPLACEMENT OF BETA VALVE PACKING, PROPELLER GOVERNOR, ALERT SERVICE BULLETIN				CATEGORY 3	COMPLIED WITH
		MOS		01-JUN-2005			
		HRS/MSC	-	274			
		ENC		195			
SB	13006 R01	NO. 1 ENGINE - MODIFICATION OF OIL FILTER HOUSING CHECK VALVE, SERVICE BULLETIN				COMPLIED WITH - AT MANUFACTURE	
15-FEB-1984		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB	13008	NO. 1 ENGINE - INTRODUCTION OF IMPROVED NO. 3 AND NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY AND NEW NO. 4 BEARING, SERVICE BULLETIN				COMPLIED WITH - AT MANUFACTURE	
20-OCT-1983		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB	13009	NO. 1 ENGINE - INTRODUCTION OF PROPELLER SHAFT OIL SEAL IMPROVED SUPPORT (SUPERSEDED BY SB PT6A-72-13173 R2), SERVICE BULLETIN				COMPLIED WITH - AT MANUFACTURE	
09-APR-1984		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB	13010	NO. 1 ENGINE - REPLACEMENT OF GUIDE PIN REVERSING LEVER BRACKET ASSEMBLY, SERVICE BULLETIN				COMPLIED WITH - AT MANUFACTURE	
30-APR-1984		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB	13011 R02	NO. 1 ENGINE - REPLACEMENT OF OIL PRESSURE INDICATOR RESTRICTOR, SERVICE BULLETIN				COMPLIED WITH - AT MANUFACTURE	
15-SEP-1987		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB	13015	NO. 1 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE SHROUD HOUSING, SERVICE BULLETIN				COMPLIED WITH - AT MANUFACTURE	
16-AUG-1983		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB	13018	NO. 1 ENGINE - MODIFICATION OF TORQUEMETER CYLINDER, SERVICE BULLETIN				COMPLIED WITH - AT MANUFACTURE	
04-OCT-1984		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB	13019	NO. 1 ENGINE - INTRODUCTION OF IMPROVED POWER TURBINE SHROUD AND NO. 2 BEARING HOUSING COVER FLANGE, SERVICE BULLETIN				COMPLIED WITH - AT MANUFACTURE	
20-JAN-1984		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB	13021 R01	NO. 1 ENGINE - MODIFICATION OF PROPELLER REVERSING LEVER, SERVICE BULLETIN				COMPLIED WITH - AT MANUFACTURE	
14-APR-1987		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 13023	NO. 1 ENGINE - REPLACEMENT OF OIL TEMPERATURE BULB ADAPTER, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
28-NOV-1983		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13025 R01	NO. 1 ENGINE - MODIFICATION OF OUTER COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
10-APR-1987		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13026	NO. 1 ENGINE - INTRODUCTION OF NEW COMPRESSOR BEARING OIL NOZZLE AND STRAINER, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
09-APR-1984		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13028 R01	NO. 1 ENGINE - INTRODUCTION OF NEW NO. 3 AND NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
15-SEP-1987		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13032	NO. 1 ENGINE - REPLACEMENT OF REAR STATOR AIR SEAL ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
11-MAY-1984		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13034	NO. 1 ENGINE - INTRODUCTION OF NEW FUEL CONTROL UNIT INCORPORATING A SMALLER FUEL INLET FILTER, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
09-APR-1984		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13038 R01	NO. 1 ENGINE - INTRODUCTION OF T5 SINGLE THERMOCOUPLE AND DUAL BUS-BAR, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
20-AUG-1985		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13043	NO. 1 ENGINE - MODIFICATION OF COMPRESSOR TURBINE STATOR ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
28-FEB-1985		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13046 R01	NO. 1 ENGINE - INTRODUCTION OF POWER TURBINE HOUSING ASSEMBLY WITH FLOATING GROMMET, SERVICE BULLETIN						COMPLIED WITH
18-NOV-1986		MOS		01-NOV-2000			
		HRS/MSC	-				
		ENC					
SB 13047 R01	NO. 1 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE BLADES, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
28-FEB-1985		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 13048 R02	NO. 1 ENGINE - INTRODUCTION OF NEW FUEL PUMP UNIT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
18-FEB-1987		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13050	NO. 1 ENGINE - INTRODUCTION OF OIL TRANSFER PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
05-NOV-1984		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13052 R02	NO. 1 ENGINE - INTRODUCTION OF COMPRESSOR REAR HUB WITH INCREASED CYCLIC FATIGUE LIFE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
21-JUN-1988		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13053	NO. 1 ENGINE - INTRODUCTION OF IMPROVED FIRST-STAGE COMPRESSOR BLADES, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
11-OCT-1984		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13055	NO. 1 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR STATOR ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
15-MAR-1985		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13058	NO. 1 ENGINE - INTRODUCTION OF IMPROVED FIRST-STAGE COMPRESSOR BLADES, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
19-SEP-1985		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13059	NO. 1 ENGINE - INTRODUCTION OF NEW THIRD-STAGE TURBINE VANE RING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
30-APR-1985		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13062 R2	NO. 1 ENGINE - INTRODUCTION OF NEW IMPROVED SWING CHECK VALVE ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
25-MAR-1986		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13065 R06	NO. 1 ENGINE - REPLACEMENT OF SHROUD HOUSING ASSEMBLY AND SMALL EXIT DUCT ASSEMBLY, SERVICE BULLETIN					CODE 7	COMPLIED WITH - AT MANUFACTURE
25-JAN-1993		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13066	NO. 1 ENGINE - INTRODUCTION OF FINE MESH OIL FILTER ELEMENT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
19-SEP-1985		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 13067 R3	NO. 1 ENGINE - INTRODUCTION OF OUTER COMBUSTION CHAMBER LINER WITH IMPROVED SEALING FEATURE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
29-JUN-1988		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13068 R1	NO. 1 ENGINE - MODIFICATION OF COMPRESSOR AIR SEALS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
27-NOV-1990		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13069	NO. 1 ENGINE - INTRODUCTION OF IMPROVED ACCESSORY GEARBOX HOUSING ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
30-APR-1985		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13071 R1	NO. 1 ENGINE - MODIFICATION OF TACHOMETER DRIVE BEVEL GEARSHAFT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
08-JUL-1989		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13072 R1	NO. 1 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE DISK, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
15-SEP-1987		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13080 R01	NO. 1 ENGINE - INTRODUCTION OF NO. 3 BEARING COVER ANTIROTATION FEATURE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
03-NOV-1986		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13082	NO. 1 ENGINE - INTRODUCTION OF IMPROVED SPARK IGNITERS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
24-SEP-1985		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13086 R01	NO. 1 ENGINE - INTRODUCTION OF IMPROVED NO. 1 BEARING OUTER HOUSING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
27-AUG-1987		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13089 R01	NO. 1 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE BLADES, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
17-MAR-1986		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13093 R02	NO. 1 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR ROTOR BALANCING ASSEMBLY, SERVICE BULLETIN					GROUP/CODE B4	COMPLIED WITH - AT MANUFACTURE
12-MAR-1990		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13096 R01	NO. 1 ENGINE - INTRODUCTION OF IMPROVED REDUCTION GEARBOX REAR HOUSING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
02-SEP-1987		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 13105	NO. 1 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE SHROUD HOUSING AND COMPRESSOR TURBINE SHROUD SEGMENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-AUG-1987		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13108 R01	NO. 1 ENGINE - INTRODUCTION OF COMPRESSOR TURBINE STATOR AIR SEAL WITH CLASSIFIED DIAMETER, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
02-JUN-1987		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13109 R02	NO. 1 ENGINE - INTRODUCTION OF IMPROVED NO. 1 BEARING AIR SEALS, SERVICE BULLETIN					CODE 8	COMPLIED WITH - AT MANUFACTURE
18-SEP-1991		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13115	NO. 1 ENGINE - REPLACEMENT OF NO. 4 BEARING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
22-SEP-1987		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13116 R02	NO. 1 ENGINE - INTRODUCTION OF PROPELLER FLANGE SHIM, SERVICE BULLETIN						COMPLIED WITH
11-MAR-1988		MOS		01-NOV-2000			
		HRS/MSC	-				
		ENC					
SB 13121	NO. 1 ENGINE - INTRODUCTION OF COMPRESSOR TURBINE SHROUD RETAINING RING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
27-AUG-1987		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13124 R02	NO. 1 ENGINE - MODIFICATION OF NO. 2 BEARING HOUSING COVER FLANGE, SERVICE BULLETIN					CODE 6	COMPLIED WITH - AT MANUFACTURE
06-DEC-1991		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13126	NO. 1 ENGINE - INTRODUCTION OF PROPELLER SHAFT OIL SEAL RUNNER, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
02-AUG-1989		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13128	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE SHROUD SEGMENT RETAINING RING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
28-JAN-1988		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13129 R01	NO. 1 ENGINE - INTRODUCTION OF IMPROVED THERMOSTATIC BY-PASS VALVE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
26-APR-1991		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13130	NO. 1 ENGINE - REPLACEMENT OF NO. 3 BEARING COVER ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
25-JAN-1989		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 13131	NO. 1 ENGINE - INTRODUCTION OF BLEED AIR CASE ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
31-MAR-1988		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13135	NO. 1 ENGINE - INTRODUCTION OF LOCKING WASHERS FOR ITT TERMINAL BOLTS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
19-DEC-1988		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13136 R01	NO. 1 ENGINE - INTRODUCTION OF NEW COMPRESSOR TURBINE BOLT, SERVICE BULLETIN					GROUP/CODE B5	COMPLIED WITH - AT MANUFACTURE
21-SEP-1990		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13144	NO. 1 ENGINE - INTRODUCTION OF IMPROVED NO. 4 BEARING OIL SUPPLY SYSTEM, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
19-OCT-1989		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13155 R02	NO. 1 ENGINE - INTRODUCTION OF IMPROVED GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN					CODE 6	COMPLIED WITH - AT MANUFACTURE
11-MAY-1992		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13159 R01	NO. 1 ENGINE - INTRODUCTION OF MODIFIED PROPELLER SHAFT AND SLEEVE SET, SERVICE BULLETIN					CODE 7	COMPLIED WITH - AT MANUFACTURE
06-MAR-1992		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13163 R05	NO. 1 ENGINE - INTRODUCTION OF ACCESSORY GEARBOX CENTER BEARING SUPPORT SLEEVE, SERVICE BULLETIN				CODE 4		COMPLIED WITH - AT MANUFACTURE
		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13173 R01	NO. 1 ENGINE - INTRODUCTION OF PROPELLER SHAFT OIL SEAL DUST SEAL, SERVICE BULLETIN					CODE 8	COMPLIED WITH - AT MANUFACTURE
25-NOV-1991		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13174	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF NUMBER 3 & 4 BEARING PRESSURE OIL TUBE ASSEMBLY, SERVICE BULLETIN				CODE 6		COMPLIED WITH - AT MANUFACTURE
06-MAR-1991		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13181	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE STATOR ASSEMBLY AND SHROUD HOUSING, SERVICE BULLETIN				CODE 6		COMPLIED WITH - AT MANUFACTURE
06-NOV-1991		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13188 R1	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ROTOR ASSEMBLY, SERVICE BULLETIN				CODE 8		COMPLIED WITH - AT MANUFACTURE
29-MAR-1993		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 13189	NO. 1 ENGINE - REPLACEMENT OF FUEL CONTROL, SERVICE BULLETIN					CODE 8	COMPLIED WITH - AT MANUFACTURE
13-DEC-1991		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13190 R01	NO. 1 ENGINE - REPLACEMENT OF OIL-TO-FUEL HEATER, SERVICE BULLETIN					CODE 6	COMPLIED WITH - AT MANUFACTURE
12-MAY-1992		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13191	NO. 1 ENGINE - INTRODUCTION OF PROPELLER GEARBOX FRONT ACCESSORY DRIVE BEVEL GEAR AND ADJUSTING SPACER, SERVICE BULLETIN				CODE 7		COMPLIED WITH - AT MANUFACTURE
23-MAR-1992		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13192	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX HOUSING AND BEARING SUPPORT SLEEVE, SERVICE BULLETIN				CODE 6		COMPLIED WITH - AT MANUFACTURE
13-DEC-1991		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13193 R01	NO. 1 ENGINE - REPLACEMENT OF T5 IMMERSION THEROCOUPLES, SERVICE BULLETIN				CODE 7		COMPLIED WITH - AT MANUFACTURE
01-APR-1992		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13197 R01	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX HOUSING AND DIAPHRAGM ASSEMBLIES, KEYWASHERS AND CENTER BEARING RETAINING BOLTS, SERVICE BULLETIN				CODE 5		COMPLIED WITH - AT MANUFACTURE
28-MAY-1992		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13201 R01	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR ROTOR ASSEMBLY AND NO. 1 BEARING OIL NOZZLE, SERVICE BULLETIN				CODE 6		COMPLIED WITH - AT MANUFACTURE
16-OCT-1992		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13208	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE STATOR AIR SEAL AND GASKET, SERVICE BULLETIN				CODE 8		COMPLIED WITH - AT MANUFACTURE
29-JUL-1992		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13214	NO. 1 ENGINE - REPLACEMENT OF GASKETS CONTAINING ASBESTOS FIBERS, SERVICE BULLETIN				CODE 7		COMPLIED WITH - AT MANUFACTURE
02-DEC-1992		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13217	NO. 1 ENGINE - REPLACEMENT OF NO. 2 BEARING HOUSING COVER FLANGE, SERVICE BULLETIN				CODE 8		COMPLIED WITH - AT MANUFACTURE
12-JUL-1993		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 13221	NO. 1 ENGINE - REPLACEMENT OF NO. 2 BEARING HOUSING-COVER FLANGE RETAINING BOLTS, SERVICE BULLETIN				CODE 6	COMPLIED WITH - AT MANUFACTURE	
28-JUN-1993		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13223 R01	NO. 1 ENGINE - REPLACEMENT OF ASBESTOS FIBER GASKET, SERVICE BULLETIN				CODE 7	COMPLIED WITH - AT MANUFACTURE	
07-MAR-1994		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13224	NO. 1 ENGINE - REPLACEMENT OF ASBESTOS FIBER GASKET, SERVICE BULLETIN				CODE 7	COMPLIED WITH - AT MANUFACTURE	
12-AUG-1993		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13225	NO. 1 ENGINE - REPLACEMENT OF ASBESTOS FIBER GASKETS, SERVICE BULLETIN				CODE 7	COMPLIED WITH - AT MANUFACTURE	
19-OCT-1993		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13227	NO. 1 ENGINE - REPLACEMENT OF ASBESTOS FIBER INSULATION AND SHIELDS, SERVICE BULLETIN				CODE 7	COMPLIED WITH - AT MANUFACTURE	
04-NOV-1993		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13228	NO. 1 ENGINE - REPLACEMENT OF PRIMARY FUEL-PRESSURE-TUBE ASSEMBLY, SERVICE BULLETIN				CODE 6	COMPLIED WITH - AT MANUFACTURE	
15-SEP-1993		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13232	NO. 1 ENGINE - REPLACEMENT OF POWER-TURBINE ROTOR BALANCING ASSEMBLY, SERVICE BULLETIN				CODE 8	COMPLIED WITH	
21-FEB-1994		MOS		01-NOV-2000			
		HRS/MSC	-				
		ENC					
SB 13234	NO. 1 ENGINE - REPLACEMENT OF IGNITION CABLE ASSEMBLY, SERVICE BULLETIN				CODE 7	COMPLIED WITH - AT MANUFACTURE	
26-NOV-1993		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13235	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR-TURBINE STATOR ASSEMBLY, SERVICE BULLETIN				CODE 7	COMPLIED WITH - AT MANUFACTURE	
22-DEC-1993		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13241	NO. 1 ENGINE - INTRODUCTION OF COMPRESSOR STATOR ASSEMBLIES, SERVICE BULLETIN				CODE 8	COMPLIED WITH - AT MANUFACTURE	
21-MAR-1994		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13242	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR BLEED-VALVE ASSEMBLY, SERVICE BULLETIN				CODE 8	COMPLIED WITH - AT MANUFACTURE	
24-MAR-1994		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 13243	NO. 1 ENGINE - REPLACEMENT OF SCAVENGE PUMP HOUSING, SERVICE BULLETIN					CODE 8	COMPLIED WITH - AT MANUFACTURE
04-APR-1994		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13001 R11	NO. 1 ENGINE - APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS, SERVICE BULLETIN						COMPLIED WITH
02-JUN-1998		MOS		01-JUN-2005			
		HRS/MSC	-	274			
		ENC		195			
SB PT6A-72-13001 R12	NO. 1 ENGINE - APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS, SERVICE BULLETIN						COMPLIED WITH
12-MAY-2005		MOS		01-NOV-2005			
		HRS/MSC	-				
		ENC					
SB PT6A-72-13002 R13	NO. 1 ENGINE - ROTOR COMPONENTS - SERVICE LIFE, SERVICE BULLETIN						COMPLIED WITH
23-DEC-1999		MOS		01-JUN-2005			
		HRS/MSC	-	274			
		ENC		195			
SB PT6A-72-13002 R16	NO. 1 ENGINE - ROTOR COMPONENTS - SERVICE LIFE, SERVICE BULLETIN						COMPLIED WITH
		MOS		30-SEP-2010			
		HRS/MSC	A/R	1614:46			
		ENC		1237			
SB PT6A-72-13031	NO. 1 ENGINE - MODIFICATION OF EXHAUST DUCT ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
28-FEB-1985		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13044 R12	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						COMPLIED WITH
05-OCT-2009		MOS		30-SEP-2010			
		HRS/MSC	-	1614:46			
		ENC		1237			
SB PT6A-72-13044 R8	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						COMPLIED WITH
13-JAN-2004		MOS		01-JUN-2005			
		HRS/MSC	-	274			
		ENC		195			
SB PT6A-72-13044 R9	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						COMPLIED WITH
15-MAR-2005		MOS		01-JUN-2005			
		HRS/MSC	-	274			
		ENC		195			
SB PT6A-72-13134 R01	NO. 1 ENGINE - INTRODUCTION OF COMPRESSOR TURBINE SHROUD SEGMENT RETAINING RING STOP, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
08-OCT-1998		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13141 R03	NO. 1 ENGINE - INTRODUCTION OF NEW COMPRESSOR TURBINE SHROUD SEGMENTS, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
08-OCT-1998		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-13148 R2	NO. 1 ENGINE - INTRODUCTION OF NEW COMPRESSOR ROTOR REAR AIR SEAL, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
23-SEP-1997		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13152 R2	NO. 1 ENGINE - INTRODUCTION OF ACCESSORY GEARBOX DRIVE SHAFT COUPLING SPACER, SERVICE BULLETIN				CATEGORY 6	COMPLIED WITH - AT MANUFACTURE	
08-JUN-2000		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13161 R4	NO. 1 ENGINE - INTRODUCTION OF NEW ACCESSORY GEARBOX COUPLING SHAFT LOCKING FEATURE, SERVICE BULLETIN					COMPLIED WITH	
21-FEB-1994		MOS		01-NOV-2000			
		HRS/MSC	-				
		ENC					
SB PT6A-72-13172 R3	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLIES, SERVICE BULLETIN				CATEGORY 8	COMPLIED WITH - AT MANUFACTURE	
21-JAN-1998		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13175 R2	NO. 1 ENGINE - INTRODUCTION OF P3 AIR FILTER HOUSING AND COVER WITH DRAIN VALVE, SERVICE BULLETIN				CATEGORY 8	COMPLIED WITH - AT MANUFACTURE	
13-JUN-2000		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13177 R3	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF OUTER COMBUSTION - CHAMBER LINER ASSEMBLY, SERVICE BULLETIN				CATEGORY 5	COMPLIED WITH - AT MANUFACTURE	
18-JUN-1996		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13179 R1	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN				CATEGORY 8	COMPLIED WITH - AT MANUFACTURE	
08-DEC-1998		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13203 R2	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN					COMPLIED WITH	
11-FEB-2000		MOS		01-JUN-2005			
		HRS/MSC	-	274			
		ENC		195			
SB PT6A-72-13205 R1	NO. 1 ENGINE - REPLACEMENT OF NON-METALLIC RING SEAL, SERVICE BULLETIN				CATEGORY 8	COMPLIED WITH - AT MANUFACTURE	
08-JAN-1997		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13206 R2	NO. 1 ENGINE - INTRODUCTION OF ACCESSORY GEARBOX ASSEMBLY WITH SEPARATE COUPLING SHAFT AND DRIVE GEARSHAFT, SERVICE BULLETIN					COMPLIED WITH	
04-MAY-1995		MOS		01-NOV-2000			
		HRS/MSC	-				
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-13207 R2	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF GASKETS CONTAINING ASBESTOS FIBERS AND BLEED VALVE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
14-JUN-1996		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13226	NO. 1 ENGINE - REPLACEMENT OF ASBESTOS FIBER GASKETS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
18-OCT-1993		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13240 R01	NO. 1 ENGINE - COMPRESSOR ROTOR ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
22-JAN-1999		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13249 R2	NO. 1 ENGINE - REPLACEMENT OF THERMOCOUPLE WIRING HARNESS TERMINAL, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH - AT MANUFACTURE
24-NOV-1998		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13252 R1	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF SECOND AND THIRD STAGE COMPRESSOR BLADES, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
19-JUL-1995		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13255	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF FUEL CONTROL UNIT (FCU), SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
08-AUG-1994		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13256	NO. 1 ENGINE - REPLACEMENT OF POWER TURBINE BLADES, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
06-JUN-2006		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13258 R1	NO. 1 ENGINE - REPLACEMENT OF VANE-RING RETAINING RING, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
08-JAN-1997		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13263	NO. 1 ENGINE - MODIFICATION/INTRODUCTION OF ELECTRICAL GROUNDING PROVISION ON AGB HOUSING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
19-AUG-1996		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13266	NO. 1 ENGINE - REPLACEMENT OF MAIN SCAVENGE-PUMP SCREEN ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
03-MAR-1995		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-13267	NO. 1 ENGINE - INRODUCTION OF FUEL NOZZLE SHEATH, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
08-FEB-1995		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13268	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR-TURBINE SHROUD-HOUSING, SERVICE BULLETIN					COMPLIED WITH - AT MANUFACTURE	
07-FEB-1995		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13270	NO. 1 ENGINE - REPLACEMENT OF IGNITION CABLE BRACKET, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
14-MAR-1995		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13274 R2	NO. 1 ENGINE - REPLACEMENT OF NO.3 AND NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
25-JUN-1997		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13275 R1	NO. 1 ENGINE - MODIFICATION OF TURBINE EXHAUST DUCT, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13277	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY DRIVE PLAIN COVER, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
03-JUN-1996		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13280 R2	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF POWER TURBINE DISK ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
26-NOV-1999		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13282 R1	NO. 1 ENGINE - REPLACEMENT OF NO. 1 BEARING, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH - AT MANUFACTURE
09-OCT-1996		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13287 R01	NO. 1 ENGINE - ENGINE - INSPECT/REPLACE BLEED OFF VALVE COVER VALVE, SERVICE BULLETIN					CATEGORY 3	- SEE ENGINE LOG INCORPORATE AT MANUFACTURE
		MOS					
		HRS/MSC	-				
		ENC					
SB PT6A-72-13290	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF IDENTIFICATION SUPPORT PLATE, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
20-MAY-1997		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13293	NO. 1 ENGINE - REPLACEMENT OF NO. 4 BEARING, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
18-FEB-1997		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-13295 R1	NO. 1 ENGINE - INTRODUCTION OF FUEL NOZZLE "U" SEALS, SERVICE BULLETIN						NOT APPLICABLE
22-AUG-2002		MOS		01-JUN-2005			
		HRS/MSC	-	274			
		ENC		195			
SB PT6A-72-13297 R3	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF POWER TURBINE DISK ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
28-OCT-1999		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13301	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR DISK BALANCING ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
18-MAR-1998		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13302	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF PROPELLE REVERSING LEVER, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
15-OCT-1998		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13303 R11	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						COMPLIED WITH
07-MAY-2002		MOS		30-SEP-2010			
		HRS/MSC	-	1614:46			
		ENC		1237			
SB PT6A-72-13303 R12	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						COMPLIED WITH - INCORPORATED TO AIRCRAFT TIME LIMIT SCHEDULE
12-OCT-2012		MOS		01-NOV-2012			
		HRS/MSC	-				
		ENC					
SB PT6A-72-13303 R16	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						COMPLIED WITH
		MOS		01-JUN-2010			
		HRS/MSC	-	1614			
		ENC		1237			
SB PT6A-72-13307 R3	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF FUEL NOZZLES AND MANIFOLD ADAPTERS, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB PT6A-72-13310 R01	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF FUEL NOZZLES AND MANIFOLD ADAPTERS, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB PT6A-72-13312	NO. 1 ENGINE - REPLACEMENT OF GEARSHAFT FUEL CONTROL DRIVE AND FUEL PUMP, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
19-OCT-1998		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-13313	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX DIAPHRAGM ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
27-OCT-1998		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13319	NO. 1 ENGINE - REPLACEMENT OF NO. 2 BEARING SCAVENGE-TUBE SEAL-RETAINING-PLATE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
20-AUG-1998		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13321 R1	NO. 1 ENGINE - MODIFICATION OF SCAVENGE PUMP HOUSING ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
07-OCT-1998		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13323	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR DELIVERY AIR PRESSURE INSULATED TUBE ASSEMBLY AND CLAMP, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH - AT MANUFACTURE
04-DEC-1998		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13337	NO. 1 ENGINE - REPLACEMENT OF PROPELLER THRUST COVER ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
08-FEB-2000		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13338 R1	NO. 1 ENGINE - REPLACEMENT OF T-5 TRIM THERMOCOUPLE, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
10-JUL-2000		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13346 R1	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF OUTER/INNER LINER, SERVICE BULLETIN					CATEGORY 4	COMPLIED WITH - AT MANUFACTURE
26-OCT-2000		MOS		17-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13354	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF PROPELLER GOVERNOR, SERVICE BULLETIN						NOT APPLICABLE - NOT AFFECTED
06-JUL-2001		MOS		18-NOV-2004			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13354 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF PROPELLER GOVERNOR, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE
11-JUL-2003		MOS		01-JAN-2005			
		HRS/MSC	-	91			
		ENC					
SB PT6A-72-13361	NO. 1 ENGINE - INSPECTION OF INTERCONNECT ROD, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
02-AUG-2004		MOS		27-JAN-2005			
		HRS/MSC	-	93:48			
		ENC		75			
SB PT6A-72-13370 R1	NO. 1 ENGINE - INSPECTION OF PROPELLER REVERSING LEVER, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
06-JAN-2009		MOS		04-NOV-2009			
		HRS/MSC	-	1611:20			
		ENC		1235			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-13398 R1	NO. 1 ENGINE - INSPECTION OF OIL TANK FILLER CAP, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
29-SEP-2005		MOS HRS/MSC ENC		01-JAN-2006 576			
SB PT6A-72-13454 R1	NO. 1 ENGINE - GAS GENERATOR - INSPECTION OF , SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - TO INSTALLED ENGINE
16-NOV-2010		MOS HRS/MSC ENC		01-JUN-2011 1787:31 1383			
SB PT6A-72-13454 R2	NO. 1 ENGINE - INSPECTION OF GAS GENERATOR, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - PER S/N
23-APR-2013		MOS HRS/MSC ENC		01-MAY-2013 2731 1976			
SB PT6A-72-13465 R2	NO. 1 ENGINE - INSPECTION OF TURBOPROP ENGINE WITH HAMILTON SUNSTRAND FUEL PUMP, COUPLING SHAFT SPLINE, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY MANUFACTURER
17-AUG-2012		MOS HRS/MSC ENC		01-AUG-2012			
SB PT6A-72-13505 R02	NO. 1 ENGINE - INSPECTION OF FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
21-JUN-2019		MOS HRS/MSC ENC		16-OCT-2019 3051:35 2122			
SB PT6A-72-A13424 R1	NO. 1 ENGINE - PARK IGNITERS - INSPECTION OF, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
20-SEP-2007		MOS HRS/MSC ENC		30-SEP-2010 1614:46 1237			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 2 - SB - PCE-PK0385/3102700-01							
ASB	PT6A-72-A13397	NO. 2 ENGINE - REPLACEMENT OF BETA VALVE PACKING, PROPELLER GOVERNOR, ALERT SERVICE BULLETIN				CATEGORY 3	COMPLIED WITH
		MOS		01-JUN-2005			
		HRS/MSC	-	274			
		ENC		195			
SB	13006 R01	NO. 2 ENGINE - MODIFICATION OF OIL FILTER HOUSING CHECK VALVE, SERVICE BULLETIN				COMPLIED WITH - AT MANUFACTURE	
15-FEB-1984		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB	13008	NO. 2 ENGINE - INTRODUCTION OF IMPROVED NO. 3 AND NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY AND NEW NO. 4 BEARING, SERVICE BULLETIN				COMPLIED WITH - AT MANUFACTURE	
20-OCT-1983		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB	13009	NO. 2 ENGINE - INTRODUCTION OF PROPELLER SHAFT OIL SEAL IMPROVED SUPPORT (SUPERSEDED BY SB PT6A-72-13173 R2), SERVICE BULLETIN				COMPLIED WITH - AT MANUFACTURE	
09-APR-1984		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB	13010	NO. 2 ENGINE - REPLACEMENT OF GUIDE PIN REVERSING LEVER BRACKET ASSEMBLY, SERVICE BULLETIN				COMPLIED WITH - AT MANUFACTURE	
30-APR-1984		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB	13011 R02	NO. 2 ENGINE - REPLACEMENT OF OIL PRESSURE INDICATOR RESTRICTOR, SERVICE BULLETIN				COMPLIED WITH - AT MANUFACTURE	
15-SEP-1987		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB	13015	NO. 2 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE SHROUD HOUSING, SERVICE BULLETIN				COMPLIED WITH - AT MANUFACTURE	
16-AUG-1983		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB	13018	NO. 2 ENGINE - MODIFICATION OF TORQUEMETER CYLINDER, SERVICE BULLETIN				COMPLIED WITH - AT MANUFACTURE	
04-OCT-1984		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB	13019	NO. 2 ENGINE - INTRODUCTION OF IMPROVED POWER TURBINE SHROUD AND NO. 2 BEARING HOUSING COVER FLANGE, SERVICE BULLETIN				COMPLIED WITH - AT MANUFACTURE	
20-JAN-1984		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB	13021 R01	NO. 2 ENGINE - MODIFICATION OF PROPELLER REVERSING LEVER, SERVICE BULLETIN				COMPLIED WITH - AT MANUFACTURE	
14-APR-1987		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 13023	NO. 2 ENGINE - REPLACEMENT OF OIL TEMPERATURE BULB ADAPTER, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
28-NOV-1983		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13025 R01	NO. 2 ENGINE - MODIFICATION OF OUTER COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
10-APR-1987		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13026	NO. 2 ENGINE - INTRODUCTION OF NEW COMPRESSOR BEARING OIL NOZZLE AND STRAINER, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
09-APR-1984		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13028 R01	NO. 2 ENGINE - INTRODUCTION OF NEW NO. 3 AND NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
15-SEP-1987		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13032	NO. 2 ENGINE - REPLACEMENT OF REAR STATOR AIR SEAL ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
11-MAY-1984		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13034	NO. 2 ENGINE - INTRODUCTION OF NEW FUEL CONTROL UNIT INCORPORATING A SMALLER FUEL INLET FILTER, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
09-APR-1984		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13038 R01	NO. 2 ENGINE - INTRODUCTION OF T5 SINGLE THERMOCOUPLE AND DUAL BUS-BAR, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
20-AUG-1985		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13043	NO. 2 ENGINE - MODIFICATION OF COMPRESSOR TURBINE STATOR ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
28-FEB-1985		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13046 R01	NO. 2 ENGINE - INTRODUCTION OF POWER TURBINE HOUSING ASSEMBLY WITH FLOATING GROMMET, SERVICE BULLETIN						COMPLIED WITH
18-NOV-1986		MOS		11-JAN-2000			
		HRS/MSC	-				
		ENC					
SB 13047 R01	NO. 2 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE BLADES, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
28-FEB-1985		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 13048 R02	NO. 2 ENGINE - INTRODUCTION OF NEW FUEL PUMP UNIT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
18-FEB-1987		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13050	NO. 2 ENGINE - INTRODUCTION OF OIL TRANSFER PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
05-NOV-1984		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13052 R02	NO. 2 ENGINE - INTRODUCTION OF COMPRESSOR REAR HUB WITH INCREASED CYCLIC FATIGUE LIFE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
21-JUN-1988		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13053	NO. 2 ENGINE - INTRODUCTION OF IMPROVED FIRST-STAGE COMPRESSOR BLADES, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
11-OCT-1984		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13055	NO. 2 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR STATOR ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
15-MAR-1985		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13058	NO. 2 ENGINE - INTRODUCTION OF IMPROVED FIRST-STAGE COMPRESSOR BLADES, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
19-SEP-1985		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13059	NO. 2 ENGINE - INTRODUCTION OF NEW THIRD-STAGE TURBINE VANE RING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
30-APR-1985		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13062 R2	NO. 2 ENGINE - INTRODUCTION OF NEW IMPROVED SWING CHECK VALVE ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
25-MAR-1986		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13065 R06	NO. 2 ENGINE - REPLACEMENT OF SHROUD HOUSING ASSEMBLY AND SMALL EXIT DUCT ASSEMBLY, SERVICE BULLETIN					CODE 7	COMPLIED WITH - AT MANUFACTURE
25-JAN-1993		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13066	NO. 2 ENGINE - INTRODUCTION OF FINE MESH OIL FILTER ELEMENT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
19-SEP-1985		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 13067 R3	NO. 2 ENGINE - INTRODUCTION OF OUTER COMBUSTION CHAMBER LINER WITH IMPROVED SEALING FEATURE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
29-JUN-1988		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13068 R1	NO. 2 ENGINE - MODIFICATION OF COMPRESSOR AIR SEALS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
27-NOV-1990		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13069	NO. 2 ENGINE - INTRODUCTION OF IMPROVED ACCESSORY GEARBOX HOUSING ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
30-APR-1985		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13071 R1	NO. 2 ENGINE - MODIFICATION OF TACHOMETER DRIVE BEVEL GEARSHAFT, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
08-JUL-1989		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13072 R1	NO. 2 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE DISK, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
15-SEP-1987		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13080 R01	NO. 2 ENGINE - INTRODUCTION OF NO. 3 BEARING COVER ANTIROTATION FEATURE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
03-NOV-1986		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13082	NO. 2 ENGINE - INTRODUCTION OF IMPROVED SPARK IGNITERS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
24-SEP-1985		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13086 R01	NO. 2 ENGINE - INTRODUCTION OF IMPROVED NO. 1 BEARING OUTER HOUSING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
27-AUG-1987		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13089 R01	NO. 2 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE BLADES, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
17-MAR-1986		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13093 R02	NO. 2 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR ROTOR BALANCING ASSEMBLY, SERVICE BULLETIN					GROUP/CODE B4	COMPLIED WITH - AT MANUFACTURE
12-MAR-1990		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13096 R01	NO. 2 ENGINE - INTRODUCTION OF IMPROVED REDUCTION GEARBOX REAR HOUSING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
02-SEP-1987		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 13105	NO. 2 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE SHROUD HOUSING AND COMPRESSOR TURBINE SHROUD SEGMENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-AUG-1987		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13108 R01	NO. 2 ENGINE - INTRODUCTION OF COMPRESSOR TURBINE STATOR AIR SEAL WITH CLASSIFIED DIAMETER, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
02-JUN-1987		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13109 R02	NO. 2 ENGINE - INTRODUCTION OF IMPROVED NO. 1 BEARING AIR SEALS, SERVICE BULLETIN					CODE 8	COMPLIED WITH - AT MANUFACTURE
18-SEP-1991		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13115	NO. 2 ENGINE - REPLACEMENT OF NO. 4 BEARING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
22-SEP-1987		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13116 R02	NO. 2 ENGINE - INTRODUCTION OF PROPELLER FLANGE SHIM, SERVICE BULLETIN						COMPLIED WITH
11-MAR-1988		MOS		01-NOV-2000			
		HRS/MSC	-				
		ENC					
SB 13121	NO. 2 ENGINE - INTRODUCTION OF COMPRESSOR TURBINE SHROUD RETAINING RING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
27-AUG-1987		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13124 R02	NO. 2 ENGINE - MODIFICATION OF NO. 2 BEARING HOUSING COVER FLANGE, SERVICE BULLETIN					CODE 6	COMPLIED WITH - AT MANUFACTURE
06-DEC-1991		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13126	NO. 2 ENGINE - INTRODUCTION OF PROPELLER SHAFT OIL SEAL RUNNER, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
02-AUG-1989		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13128	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE SHROUD SEGMENT RETAINING RING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
28-JAN-1988		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13129 R01	NO. 2 ENGINE - INTRODUCTION OF IMPROVED THERMOSTATIC BY-PASS VALVE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
26-APR-1991		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13130	NO. 2 ENGINE - REPLACEMENT OF NO. 3 BEARING COVER ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
25-JAN-1989		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 13131	NO. 2 ENGINE - INTRODUCTION OF BLEED AIR CASE ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
31-MAR-1988		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13135	NO. 2 ENGINE - INTRODUCTION OF LOCKING WASHERS FOR ITT TERMINAL BOLTS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
19-DEC-1988		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13136 R01	NO. 2 ENGINE - INTRODUCTION OF NEW COMPRESSOR TURBINE BOLT, SERVICE BULLETIN					GROUP/CODE B5	COMPLIED WITH - AT MANUFACTURE
21-SEP-1990		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13144	NO. 2 ENGINE - INTRODUCTION OF IMPROVED NO. 4 BEARING OIL SUPPLY SYSTEM, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
19-OCT-1989		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13155 R02	NO. 2 ENGINE - INTRODUCTION OF IMPROVED GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN					CODE 6	COMPLIED WITH - AT MANUFACTURE
11-MAY-1992		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13159 R01	NO. 2 ENGINE - INTRODUCTION OF MODIFIED PROPELLER SHAFT AND SLEEVE SET, SERVICE BULLETIN					CODE 7	COMPLIED WITH - AT MANUFACTURE
06-MAR-1992		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13163 R05	NO. 2 ENGINE - INTRODUCTION OF ACCESSORY GEARBOX CENTER BEARING SUPPORT SLEEVE, SERVICE BULLETIN				CODE 4		COMPLIED WITH - AT MANUFACTURE
		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13173 R01	NO. 2 ENGINE - INTRODUCTION OF PROPELLER SHAFT OIL SEAL DUST SEAL, SERVICE BULLETIN					CODE 8	COMPLIED WITH - AT MANUFACTURE
25-NOV-1991		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13174	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF NUMBER 3 & 4 BEARING PRESSURE OIL TUBE ASSEMBLY, SERVICE BULLETIN				CODE 6		COMPLIED WITH - AT MANUFACTURE
06-MAR-1991		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13181	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE STATOR ASSEMBLY AND SHROUD HOUSING, SERVICE BULLETIN				CODE 6		COMPLIED WITH - AT MANUFACTURE
06-NOV-1991		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13188 R1	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ROTOR ASSEMBLY, SERVICE BULLETIN				CODE 8		COMPLIED WITH - AT MANUFACTURE
29-MAR-1993		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 13189	NO. 2 ENGINE - REPLACEMENT OF FUEL CONTROL, SERVICE BULLETIN					CODE 8	COMPLIED WITH - AT MANUFACTURE
13-DEC-1991		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13190 R01	NO. 2 ENGINE - REPLACEMENT OF OIL-TO-FUEL HEATER, SERVICE BULLETIN					CODE 6	COMPLIED WITH - AT MANUFACTURE
12-MAY-1992		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13191	NO. 2 ENGINE - INTRODUCTION OF PROPELLER GEARBOX FRONT ACCESSORY DRIVE BEVEL GEAR AND ADJUSTING SPACER, SERVICE BULLETIN				CODE 7		COMPLIED WITH - AT MANUFACTURE
23-MAR-1992		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13192	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX HOUSING AND BEARING SUPPORT SLEEVE, SERVICE BULLETIN				CODE 6		COMPLIED WITH - AT MANUFACTURE
13-DEC-1991		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13193 R01	NO. 2 ENGINE - REPLACEMENT OF T5 IMMERSION THEROCOUPLES, SERVICE BULLETIN				CODE 7		COMPLIED WITH - AT MANUFACTURE
01-APR-1992		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13197 R01	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX HOUSING AND DIAPHRAGM ASSEMBLIES, KEYWASHERS AND CENTER BEARING RETAINING BOLTS, SERVICE BULLETIN				CODE 5		COMPLIED WITH - AT MANUFACTURE
28-MAY-1992		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13201 R01	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR ROTOR ASSEMBLY AND NO. 1 BEARING OIL NOZZLE, SERVICE BULLETIN				CODE 6		COMPLIED WITH - AT MANUFACTURE
16-OCT-1992		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13208	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE STATOR AIR SEAL AND GASKET, SERVICE BULLETIN				CODE 8		COMPLIED WITH - AT MANUFACTURE
29-JUL-1992		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13214	NO. 2 ENGINE - REPLACEMENT OF GASKETS CONTAINING ASBESTOS FIBERS, SERVICE BULLETIN				CODE 7		COMPLIED WITH - AT MANUFACTURE
02-DEC-1992		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13217	NO. 2 ENGINE - REPLACEMENT OF NO. 2 BEARING HOUSING COVER FLANGE, SERVICE BULLETIN				CODE 8		COMPLIED WITH - AT MANUFACTURE
12-JUL-1993		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 13221	NO. 2 ENGINE - REPLACEMENT OF NO. 2 BEARING HOUSING-COVER FLANGE RETAINING BOLTS, SERVICE BULLETIN				CODE 6	COMPLIED WITH - AT MANUFACTURE	
28-JUN-1993		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13223 R01	NO. 2 ENGINE - REPLACEMENT OF ASBESTOS FIBER GASKET, SERVICE BULLETIN				CODE 7	COMPLIED WITH - AT MANUFACTURE	
07-MAR-1994		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13224	NO. 2 ENGINE - REPLACEMENT OF ASBESTOS FIBER GASKET, SERVICE BULLETIN				CODE 7	COMPLIED WITH - AT MANUFACTURE	
12-AUG-1993		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13225	NO. 2 ENGINE - REPLACEMENT OF ASBESTOS FIBER GASKETS, SERVICE BULLETIN				CODE 7	COMPLIED WITH - AT MANUFACTURE	
19-OCT-1993		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13227	NO. 2 ENGINE - REPLACEMENT OF ASBESTOS FIBER INSULATION AND SHIELDS, SERVICE BULLETIN				CODE 7	COMPLIED WITH - AT MANUFACTURE	
04-NOV-1993		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13228	NO. 2 ENGINE - REPLACEMENT OF PRIMARY FUEL-PRESSURE-TUBE ASSEMBLY, SERVICE BULLETIN				CODE 6	COMPLIED WITH - AT MANUFACTURE	
15-SEP-1993		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13232	NO. 2 ENGINE - REPLACEMENT OF POWER-TURBINE ROTOR BALANCING ASSEMBLY, SERVICE BULLETIN				CODE 8	COMPLIED WITH	
21-FEB-1994		MOS		01-NOV-2000			
		HRS/MSC	-				
		ENC					
SB 13234	NO. 2 ENGINE - REPLACEMENT OF IGNITION CABLE ASSEMBLY, SERVICE BULLETIN				CODE 7	COMPLIED WITH - AT MANUFACTURE	
26-NOV-1993		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13235	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR-TURBINE STATOR ASSEMBLY, SERVICE BULLETIN				CODE 7	COMPLIED WITH - AT MANUFACTURE	
22-DEC-1993		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13241	NO. 2 ENGINE - INTRODUCTION OF COMPRESSOR STATOR ASSEMBLIES, SERVICE BULLETIN				CODE 8	COMPLIED WITH - AT MANUFACTURE	
21-MAR-1994		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB 13242	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR BLEED-VALVE ASSEMBLY, SERVICE BULLETIN				CODE 8	COMPLIED WITH - AT MANUFACTURE	
24-MAR-1994		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 13243	NO. 2 ENGINE - REPLACEMENT OF SCAVENGE PUMP HOUSING, SERVICE BULLETIN					CODE 8	COMPLIED WITH - AT MANUFACTURE
04-APR-1994		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13001 R11	NO. 2 ENGINE - APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS, SERVICE BULLETIN						COMPLIED WITH
02-JUN-1998		MOS		01-JUN-2005			
		HRS/MSC	-	274			
		ENC		195			
SB PT6A-72-13001 R12	NO. 2 ENGINE - APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS, SERVICE BULLETIN						COMPLIED WITH
12-MAY-2005		MOS		01-NOV-2005			
		HRS/MSC	-				
		ENC					
SB PT6A-72-13002 R13	NO. 2 ENGINE - ROTOR COMPONENTS - SERVICE LIFE, SERVICE BULLETIN						COMPLIED WITH
23-DEC-1999		MOS		01-JUN-2005			
		HRS/MSC	-	274			
		ENC		195			
SB PT6A-72-13002 R16	NO. 2 ENGINE - ROTOR COMPONENTS - SERVICE LIFE, SERVICE BULLETIN						COMPLIED WITH
		MOS		03-SEP-2010			
		HRS/MSC	A/R	1614:46			
		ENC		1237			
SB PT6A-72-13031	NO. 2 ENGINE - MODIFICATION OF EXHAUST DUCT ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
28-FEB-1985		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13044 R12	NO. 2 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						COMPLIED WITH
05-OCT-2009		MOS		03-SEP-2010			
		HRS/MSC	-	1614:46			
		ENC		1237			
SB PT6A-72-13044 R8	NO. 2 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						COMPLIED WITH
13-JAN-2004		MOS		01-JUN-2005			
		HRS/MSC	-	274			
		ENC		195			
SB PT6A-72-13044 R9	NO. 2 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						COMPLIED WITH
15-MAR-2005		MOS		01-JUN-2005			
		HRS/MSC	-	274			
		ENC		195			
SB PT6A-72-13134 R01	NO. 2 ENGINE - INTRODUCTION OF COMPRESSOR TURBINE SHROUD SEGMENT RETAINING RING STOP, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
08-OCT-1998		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13141 R03	NO. 2 ENGINE - INTRODUCTION OF NEW COMPRESSOR TURBINE SHROUD SEGMENTS, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
08-OCT-1998		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-13148 R2	NO. 2 ENGINE - INTRODUCTION OF NEW COMPRESSOR ROTOR REAR AIR SEAL, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
23-SEP-1997		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13152 R2	NO. 2 ENGINE - INTRODUCTION OF ACCESSORY GEARBOX DRIVE SHAFT COUPLING SPACER, SERVICE BULLETIN				CATEGORY 6	COMPLIED WITH - AT MANUFACTURE	
08-JUN-2000		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13161 R4	NO. 2 ENGINE - INTRODUCTION OF NEW ACCESSORY GEARBOX COUPLING SHAFT LOCKING FEATURE, SERVICE BULLETIN					COMPLIED WITH	
21-FEB-1994		MOS		01-NOV-2000			
		HRS/MSC	-				
		ENC					
SB PT6A-72-13172 R3	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLIES, SERVICE BULLETIN				CATEGORY 8	COMPLIED WITH - AT MANUFACTURE	
21-JAN-1998		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13175 R2	NO. 2 ENGINE - INTRODUCTION OF P3 AIR FILTER HOUSING AND COVER WITH DRAIN VALVE, SERVICE BULLETIN				CATEGORY 8	COMPLIED WITH - AT MANUFACTURE	
13-JUN-2000		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13177 R3	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF OUTER COMBUSTION - CHAMBER LINER ASSEMBLY, SERVICE BULLETIN				CATEGORY 5	COMPLIED WITH - AT MANUFACTURE	
18-JUN-1996		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13179 R1	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN				CATEGORY 8	COMPLIED WITH - AT MANUFACTURE	
08-DEC-1998		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13203 R2	NO. 2 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN					COMPLIED WITH	
11-FEB-2000		MOS		01-JUN-2005			
		HRS/MSC	-	274			
		ENC		195			
SB PT6A-72-13205 R1	NO. 2 ENGINE - REPLACEMENT OF NON-METALLIC RING SEAL, SERVICE BULLETIN				CATEGORY 8	COMPLIED WITH - AT MANUFACTURE	
08-JAN-1997		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13206 R2	NO. 2 ENGINE - INTRODUCTION OF ACCESSORY GEARBOX ASSEMBLY WITH SEPARATE COUPLING SHAFT AND DRIVE GEARSHAFT, SERVICE BULLETIN					COMPLIED WITH	
04-MAY-1995		MOS		01-NOV-2000			
		HRS/MSC	-				
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-13207 R2	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF GASKETS CONTAINING ASBESTOS FIBERS AND BLEED VALVE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
14-JUN-1996		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13226	NO. 2 ENGINE - REPLACEMENT OF ASBESTOS FIBER GASKETS, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
18-OCT-1993		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13240 R01	NO. 2 ENGINE - COMPRESSOR ROTOR ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
22-JAN-1999		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13249 R2	NO. 2 ENGINE - REPLACEMENT OF THERMOCOUPLE WIRING HARNESS TERMINAL, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH - AT MANUFACTURE
24-NOV-1998		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13252 R1	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF SECOND AND THIRD STAGE COMPRESSOR BLADES, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
19-JUL-1995		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13255	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF FUEL CONTROL UNIT (FCU), SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
08-AUG-1994		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13256	NO. 2 ENGINE - REPLACEMENT OF POWER TURBINE BLADES, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
06-JUN-2006		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13258 R1	NO. 2 ENGINE - REPLACEMENT OF VANE-RING RETAINING RING, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
08-JAN-1997		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13263	NO. 2 ENGINE - MODIFICATION/INTRODUCTION OF ELECTRICAL GROUNDING PROVISION ON AGB HOUSING, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
19-AUG-1996		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13266	NO. 2 ENGINE - REPLACEMENT OF MAIN SCAVENGE-PUMP SCREEN ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
03-MAR-1995		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-13267	NO. 2 ENGINE - INRODUCTION OF FUEL NOZZLE SHEATH, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
08-FEB-1995		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13268	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR-TURBINE SHROUD-HOUSING, SERVICE BULLETIN					COMPLIED WITH - AT MANUFACTURE	
07-FEB-1995		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13270	NO. 2 ENGINE - REPLACEMENT OF IGNITION CABLE BRACKET, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
14-MAR-1995		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13274 R2	NO. 2 ENGINE - REPLACEMENT OF NO.3 AND NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
25-JUN-1997		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13275 R1	NO. 2 ENGINE - MODIFICATION OF TURBINE EXHAUST DUCT, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13277	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY DRIVE PLAIN COVER, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
03-JUN-1996		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13280 R2	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF POWER TURBINE DISK ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
26-NOV-1999		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13282 R1	NO. 2 ENGINE - REPLACEMENT OF NO. 1 BEARING, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH - AT MANUFACTURE
09-OCT-1996		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13287 R01	NO. 2 ENGINE - ENGINE - INSPECT/REPLACE BLEED OFF VALVE COVER VALVE, SERVICE BULLETIN					CATEGORY 3	- SEE ENGINE LOG INCORPORATE AT MANUFACTURE
		MOS					
		HRS/MSC	-				
		ENC					
SB PT6A-72-13290	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF IDENTIFICATION SUPPORT PLATE, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
20-MAY-1997		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13293	NO. 2 ENGINE - REPLACEMENT OF NO. 4 BEARING, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
18-FEB-1997		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-13295 R1	NO. 2 ENGINE - INTRODUCTION OF FUEL NOZZLE "U" SEALS, SERVICE BULLETIN						NOT APPLICABLE
22-AUG-2002		MOS		01-JUN-2005			
		HRS/MSC	-	274			
		ENC		195			
SB PT6A-72-13297 R3	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF POWER TURBINE DISK ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
28-OCT-1999		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13301	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR DISK BALANCING ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
18-MAR-1998		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13302	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF PROPELLE REVERSING LEVER, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
15-OCT-1998		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13303 R11	NO. 2 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						COMPLIED WITH
07-MAY-2002		MOS		03-SEP-2010			
		HRS/MSC	-	1614:46			
		ENC		1237			
SB PT6A-72-13303 R12	NO. 2 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						COMPLIED WITH - INCORPORATED TO AIRCRAFT TIME LIMIT SCHEDULE
12-OCT-2012		MOS		01-NOV-2012			
		HRS/MSC	-				
		ENC					
SB PT6A-72-13303 R16	NO. 2 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						COMPLIED WITH
		MOS		01-JUN-2010			
		HRS/MSC	-	1614			
		ENC		1237			
SB PT6A-72-13307 R3	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF FUEL NOZZLES AND MANIFOLD ADAPTERS, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB PT6A-72-13310 R01	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF FUEL NOZZLES AND MANIFOLD ADAPTERS, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
		MOS					
		HRS/MSC	-				
		ENC					
SB PT6A-72-13312	NO. 2 ENGINE - REPLACEMENT OF GEARSHAFT FUEL CONTROL DRIVE AND FUEL PUMP, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
19-OCT-1998		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-13313	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX DIAPHRAGM ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
27-OCT-1998		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13319	NO. 2 ENGINE - REPLACEMENT OF NO. 2 BEARING SCAVENGE-TUBE SEAL-RETAINING-PLATE, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
20-AUG-1998		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13321 R1	NO. 2 ENGINE - MODIFICATION OF SCAVENGE PUMP HOUSING ASSEMBLY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
07-OCT-1998		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13323	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR DELIVERY AIR PRESSURE INSULATED TUBE ASSEMBLY AND CLAMP, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH - AT MANUFACTURE
04-DEC-1998		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13337	NO. 2 ENGINE - REPLACEMENT OF PROPELLER THRUST COVER ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
08-FEB-2000		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13338 R1	NO. 2 ENGINE - REPLACEMENT OF T-5 TRIM THERMOCOUPLE, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
10-JUL-2000		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13346 R1	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF OUTER/INNER LINER, SERVICE BULLETIN					CATEGORY 4	COMPLIED WITH - AT MANUFACTURE
26-OCT-2000		MOS		22-NOV-2000			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13354	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF PROPELLER GOVERNOR, SERVICE BULLETIN						NOT APPLICABLE - NOT AFFECTED
06-JUL-2001		MOS		18-NOV-2004			
		HRS/MSC	-	0			
		ENC		0			
SB PT6A-72-13354 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF PROPELLER GOVERNOR, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE
11-JUL-2003		MOS		01-JAN-2005			
		HRS/MSC	-	91			
		ENC					
SB PT6A-72-13361	NO. 2 ENGINE - INSPECTION OF INTERCONNECT ROD, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
02-AUG-2004		MOS		27-JAN-2005			
		HRS/MSC	-	93:48			
		ENC		75			
SB PT6A-72-13370 R1	NO. 2 ENGINE - INSPECTION OF PROPELLER REVERSING LEVER, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
06-JAN-2009		MOS		04-NOV-2009			
		HRS/MSC	-	1611:20			
		ENC		1235			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-13398 R1	NO. 2 ENGINE - INSPECTION OF OIL TANK FILLER CAP, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
29-SEP-2005		MOS HRS/MSC - ENC		01-JAN-2006 576			
SB PT6A-72-13454 R1	NO. 2 ENGINE - GAS GENERATOR - INSPECTION OF , SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - TO INSTALLED ENGINE
16-NOV-2010		MOS HRS/MSC - ENC		01-JUN-2011 1787:31 1383			
SB PT6A-72-13454 R2	NO. 2 ENGINE - INSPECTION OF GAS GENERATOR, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - PER S/N
23-APR-2013		MOS HRS/MSC - ENC		01-MAY-2013 2731 1976			
SB PT6A-72-13465 R2	NO. 2 ENGINE - INSPECTION OF TURBOPROP ENGINE WITH HAMILTON SUNSTRAND FUEL PUMP, COUPLING SHAFT SPLINE, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
17-AUG-2012		MOS HRS/MSC - ENC		01-AUG-2012			
SB PT6A-72-13505 R02	NO. 2 ENGINE - INSPECTION OF FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
21-JUN-2019		MOS HRS/MSC - ENC		16-OCT-2019 3051:35 2122			
SB PT6A-72-A13424 R1	NO. 2 ENGINE - PARK IGNITERS - INSPECTION OF, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
20-SEP-2007		MOS HRS/MSC - ENC		03-SEP-2010 1614:46 1237			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
PROPELLER NO. 1 - AD - FWA4142/HC-B4MP-3							
FAA 1983-08-01 R02	NO. 1 PROPELLER - HARTZELL PROPELLER INC. (FORMERLY TRW HARTZELL PROPELLER) MODELS HC-B3TN-2, HC-B3TN-3, HC-B3TN-5, HC-B4TN-3, HC-B4TN-5, HC-B4MN-5, AND HC-B5MP-3 TURBOPROPELLERS					MANDATORY	COMPLIED WITH
39-14043 11-MAY-2005	MOS HRS/MSC - ENC PRC			10-JAN-2006 178:12 161			
FAA 2005-14-11	NO. 1 PROPELLER - PROPELLER - HARTZELL, MCCUALEY AND SENSENICH PROPELLERS RETURNED TO SERVICE BY SOUTHERN CALIFORNIA PROPELER SERVICE OF INGLEWOOD, CA - MAINTENANCE ACTIONS AMOUNTING TO AN OVERHAUL					MANDATORY	NOT APPLICABLE - N/A DUE TO PROPELLERS NEW OUT OF FACTORY ON DATE 10-18-04 PROP HRS 138.3 AS OF 23 AUG 05 N/A DUE TO PROPELLERS NEW OUT OF FACTORY ON DATE 10-18-04 PROP HRS 138.3 AS OF 23 AUG 05
39-14188 17-AUG-2005	MOS HRS/MSC - PRC			23-AUG-2005 138:18 112			
FAA 2005-14-12	NO. 1 PROPELLER - PROPELLER - HARTZELL PROPELLER MODELS HC-B3TN-2, HC-B3TN-3, HC-B3TN-5, HC-B3MN-3, HC-B4TN-3, HC-B4TN-5, HC-B4MN-5, HC-B4MP-3, HC-B4MP-5, AND HC-B5MP-3 MOUNTING BOLTS - INSPECT / REPLACE					MANDATORY	
39-14189 29-JUL-2005	MOS HRS/MSC -			03-AUG-2005 135:36			
FAA 2005-14-12 (F)	NO. 1 PROPELLER - VISUALLY INSPECT/CHECK PROPELLER - HARTZELL PROPELLER MODELS HC-B3TN-2, HC-B3TN-3, HC-B3TN-5, HC-B3MN-3, HC-B4TN-3, HC-B4TN-5, HC-B4MN-5, HC-B4MP-3, HC-B4MP-5, AND HC-B5MP-3 MOUNTING BOLTS - INSPECT / REPLACE					MANDATORY	NOT APPLICABLE - N/A BY PROP BOLT LOT NUMBER N/A BY PROP BOLT LOT NUMBER
39-14189 29-JUL-2005	MOS HRS/MSC - PRC			03-AUG-2005 135:36 110			
FAA 2005-14-12 (K)	NO. 1 PROPELLER - REPLACE PROPELLER - HARTZELL PROPELLER MODELS HC-B3TN-2, HC-B3TN-3, HC-B3TN-5, HC-B3MN-3, HC-B4TN-3, HC-B4TN-5, HC-B4MN-5, HC-B4MP-3, HC-B4MP-5, AND HC-B5MP-3 MOUNTING BOLTS - INSPECT / REPLACE					MANDATORY	NOT APPLICABLE - N/A BY PROP BOLT LOT NUMBER N/A BY PROP BOLT LOT NUMBER
39-14189 29-JUL-2005	MOS HRS/MSC - PRC			03-AUG-2005 135:36 110			
FAA 2006-24-07	NO. 1 PROPELLER - HARTZELL PROPELLER INC. PROPELLERS AND MCCUALEY PROPELLER SYSTEMS CONTROLLABLE PROPELLERS					MANDATORY	NOT APPLICABLE - BY P/N AND S/N
39-14836 03-JAN-2007	MOS HRS/MSC -			17-APR-2019 3668:36			
FAA 2009-10-14	NO. 1 PROPELLER - IDENTIFICATION AND REMOVAL OF ALL PROPELLER BLADE COUNTERWEIGHT SLUG BOLTS, P/N B-3386-14H LFC MANUFACTURING LOT 224, FROM SERVICE, AND INSTALLATION OF SERVICEABLE BOLTS					MANDATORY	COMPLIED WITH - AT OVERHAUL
	MOS HRS/MSC -			17-APR-2019 3668:36			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
PROPELLER NO. 2 - AD - FWA4127/HC-B4MP-3							
FAA 1983-08-01 R02	NO. 2 PROPELLER - HARTZELL PROPELLER INC. (FORMERLY TRW HARTZELL PROPELLER) MODELS HC-B3TN-2, HC-B3TN-3, HC-B3TN-5, HC-B4TN-3, HC-B4TN-5, HC-B4MN-5, AND HC-B5MP-3 TURBOPROPELLERS					MANDATORY	COMPLIED WITH
39-14043 11-MAY-2005	MOS HRS/MSC -			10-JAN-2006 178:12			
	PRC			161			
FAA 2005-14-11	NO. 2 PROPELLER - PROPELLER - HARTZELL, MCCUALEY AND SENSENICH PROPELLERS RETURNED TO SERVICE BY SOUTHERN CALIFORNIA PROPELER SERVICE OF INGLEWOOD, CA - MAINTENANCE ACTIONS AMOUNTING TO AN OVERHAUL				MANDATORY	NOT APPLICABLE - N/A DUE TO PROPELLERS NEW OUT OF FACTORY ON DATE 10-18-04 PROP HRS 138.3 AS OF 23 AUG 05 N/A DUE TO PROPELLERS NEW OUT OF FACTORY ON DATE 10-18-04 PROP HRS 138.3 AS OF 23 AUG 05	
39-14188 17-AUG-2005	MOS HRS/MSC -			23-AUG-2005 138:18			
	PRC			112			
FAA 2005-14-12	NO. 2 PROPELLER - PROPELLER - HARTZELL PROPELLER MODELS HC-B3TN-2, HC-B3TN-3, HC-B3TN-5, HC-B3MN-3, HC-B4TN-3, HC-B4TN-5, HC-B4MN-5, HC-B4MP-3, HC-B4MP-5, AND HC-B5MP-3 MOUNTING BOLTS - INSPECT / REPLACE				MANDATORY		
39-14189 29-JUL-2005	MOS HRS/MSC -			03-AUG-2005 135:36			
FAA 2005-14-12 (F)	NO. 2 PROPELLER - VISUALLY INSPECT/CHECK PROPELLER - HARTZELL PROPELLER MODELS HC-B3TN-2, HC-B3TN-3, HC-B3TN-5, HC-B3MN-3, HC-B4TN-3, HC-B4TN-5, HC-B4MN-5, HC-B4MP-3, HC-B4MP-5, AND HC-B5MP-3 MOUNTING BOLTS - INSPECT / REPLACE				MANDATORY	NOT APPLICABLE - N/A BY PROP BOLT LOT NUMBER	N/A BY PROP BOLT LOT NUMBER
39-14189 29-JUL-2005	MOS HRS/MSC -			03-AUG-2005 135:36			
	PRC			110			
FAA 2005-14-12 (K)	NO. 2 PROPELLER - REPLACE PROPELLER - HARTZELL PROPELLER MODELS HC-B3TN-2, HC-B3TN-3, HC-B3TN-5, HC-B3MN-3, HC-B4TN-3, HC-B4TN-5, HC-B4MN-5, HC-B4MP-3, HC-B4MP-5, AND HC-B5MP-3 MOUNTING BOLTS - INSPECT / REPLACE				MANDATORY	NOT APPLICABLE - N/A BY PROP BOLT LOT NUMBER	N/A BY PROP BOLT LOT NUMBER
39-14189 29-JUL-2005	MOS HRS/MSC -			03-AUG-2005 135:36			
	PRC			110			
FAA 2006-24-07	NO. 2 PROPELLER - HARTZELL PROPELLER INC. PROPELLERS AND MCCUALEY PROPELLER SYSTEMS CONTROLLABLE PROPELLERS				MANDATORY	NOT APPLICABLE - BY P/N AND S/N	
39-14836 03-JAN-2007	MOS HRS/MSC -			17-APR-2019 3668:36			
FAA 2009-10-14	NO. 2 PROPELLER - IDENTIFICATION AND REMOVAL OF ALL PROPELLER BLADE COUNTERWEIGHT SLUG BOLTS, P/N B-3386-14H LFC MANUFACTURING LOT 224, FROM SERVICE, AND INSTALLATION OF SERVICEABLE BOLTS				MANDATORY	COMPLIED WITH - AT OVERHAUL	
	MOS HRS/MSC -			17-APR-2019 3668:36			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
PROPELLER NO. 1 - SB - FWA4142/HC-B4MP-3							
ASB 61-313 R02	NO. 1 PROPELLER - PROPELLER - COUNTERWEIGHT SLUG BOLT INSPECTION, ALERT SERVICE BULLETIN						COMPLIED WITH - AT OVERHAUL
		MOS		17-APR-2019			
		HRS/MSC	-	3668:36			
ASB 61-313 R03	NO. 1 PROPELLER - PROPELLER - COUNTERWEIGHT SLUG BOLT INSPECTION, ALERT SERVICE BULLETIN						COMPLIED WITH - AT OVERHAUL
17-NOV-2008		MOS		17-APR-2019			
		HRS/MSC	-	3668:36			
SB HC-SB-61-364	NO. 1 PROPELLER - BLADE - 105030 BLADE SHANK WEAR STRIP, SERVICE BULLETIN						COMPLIED WITH - AT OVERHAUL
17-MAR-2015		MOS		17-APR-2019			
		HRS/MSC	-	3668:36			
SB HC-SB-61-374 R01	NO. 1 PROPELLER - BLADE BEARING RACE INSPECTION CRITERIA, SERVICE BULLETIN						COMPLIED WITH - AT OVERHAUL
01-AUG-2017		MOS		17-APR-2019			
		HRS/MSC	-	3668:36			
SL HC-SL-61-348	NO. 1 PROPELLER - PROPELLER - HUB CLAMPING BOLT INSPECTION, SERVICE LETTER						COMPLIED WITH - AT OVERHAUL
01-JUL-2015		MOS		17-APR-2019			
		HRS/MSC	DUE	3668:36			
SL HC-SL-61-351	NO. 1 PROPELLER - ALTERNATE BOLT (A-2051-1) FOR ATTACHING THE SPINNER MOUNTING PLATE, SERVICE LETTER						COMPLIED WITH - AT OVERHAUL
		MOS		17-APR-2019			
		HRS/MSC	DUE	3668:36			
SL HC-SL-61-354	NO. 1 PROPELLER - PROPELLER - LUBRICATION FITTINGS, SERVICE LETTER						COMPLIED WITH - AT OVERHAUL
01-AUG-2016		MOS		17-APR-2019			
		HRS/MSC	-	3668:36			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
PROPELLER NO. 2 - SB - FWA4127/HC-B4MP-3							
ASB 61-313 R02	NO. 2 PROPELLER - PROPELLER - COUNTERWEIGHT SLUG BOLT INSPECTION, ALERT SERVICE BULLETIN						COMPLIED WITH - AT OVERHAUL
		MOS		17-APR-2019			
		HRS/MSC	-	3668:36			
ASB 61-313 R03	NO. 2 PROPELLER - PROPELLER - COUNTERWEIGHT SLUG BOLT INSPECTION, ALERT SERVICE BULLETIN						COMPLIED WITH - AT OVERHAUL
17-NOV-2008		MOS		17-APR-2019			
		HRS/MSC	-	3668:36			
SB HC-SB-61-364	NO. 2 PROPELLER - BLADE - 105030 BLADE SHANK WEAR STRIP, SERVICE BULLETIN						COMPLIED WITH - AT OVERHAUL
17-MAR-2015		MOS		17-APR-2019			
		HRS/MSC	-	3668:36			
SB HC-SB-61-374 R01	NO. 2 PROPELLER - BLADE BEARING RACE INSPECTION CRITERIA, SERVICE BULLETIN						COMPLIED WITH - AT OVERHAUL
01-AUG-2017		MOS		17-APR-2019			
		HRS/MSC	-	3668:36			
SL HC-SL-61-348	NO. 2 PROPELLER - PROPELLER - HUB CLAMPING BOLT INSPECTION, SERVICE LETTER						COMPLIED WITH - AT OVERHAUL
01-JUL-2015		MOS		17-APR-2019			
		HRS/MSC	DUE	3668:36			
SL HC-SL-61-351	NO. 2 PROPELLER - ALTERNATE BOLT (A-2051-1) FOR ATTACHING THE SPINNER MOUNTING PLATE, SERVICE LETTER						COMPLIED WITH - AT OVERHAUL
		MOS		17-APR-2019			
		HRS/MSC	DUE	3668:36			
SL HC-SL-61-354	NO. 2 PROPELLER - PROPELLER - LUBRICATION FITTINGS, SERVICE LETTER						COMPLIED WITH - AT OVERHAUL
01-AUG-2016		MOS		17-APR-2019			
		HRS/MSC	-	3668:36			