

OWNER: PINNACLE ZONE LIMITED
ADDRESS: 14F, NO.237, SECTION 1, CHIEN-KUO S.
ROAD
10657

OPERATOR: SKYVISION AVIATION CORP.
ADDRESS: 12F NO 68 SEC. 3 NANJING E RD
10489

OPERATOR: SKYVISION AVIATION CORP.
ADDRESS: 8F, NO. 68, SEC. 3, NANJING E RD.
ZHONGSHAN DIST. TAIPEI CITY TAIWAN
10489

PHONE:

PHONE:

PHONE: 886-905-098-99
FAX:

ANALYST: SAICHANDU BATCHU +91-40-30275000 (OFFICE)
EMAIL: SAICHANDU.BATCHU@CAMPSYSTEMS.COM
WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP

Filter Criteria: Task Type In: ('AD','ADP','SB','SBP'); Group by ATA Chapter: CHECKED; Group by Profile or Bulletin: Profile Type; Mode: With Compliance or Next Due; For: Airframe,Engine,APU Etc;

AIRCRAFT **SERIAL/REGNO:** 9673/B-96999

MODEL: GLOBAL 6000

MANUFACTURER: BOMBARDIER AVIATION

DATES	LAST ACTUALS		CURRENT ACTUAL			
CERTIFICATION DATE: 18-DEC-2014 INSERVICE DATE: 30-DEC-2015	2232:56	A/C HRS	as of 20-JAN-2025	_____	A/C HRS	as of _____/_____/_____
	787	AFL	as of 20-JAN-2025	_____	AFL	as of _____/_____/_____

APU	SERIAL/PART: P-810/WE3800714-1	MODEL: RE220 (GX)	MANUFACTURER: HONEYWELL		
INSTALLED ON 11-NOV-2014		LAST ACTUALS		CURRENT ACTUAL	
0	APU HRS	2278	APU HRS as of 13-JAN-2025	_____	APU HRS as of _____/_____/____
0	APUS	2266	APUS as of 13-JAN-2025	_____	APUS as of _____/_____/____

ENGINE NO. 1 SERIAL/PART: 22467/DEL114	MODEL: BR700-710A2-20 (CIMMS)	MANUFACTURER: ROLLS-ROYCE DERBY PLC
INSTALLED ON 23-SEP-2014	LAST ACTUALS	CURRENT ACTUAL
0 ENG. HRS	0 A/C HRS	2232:56 ENG. HRS as of 20-JAN-2025
0 ENC	793 ENC	ENC as of 20-JAN-2025

ENGINE NO. 2 SERIAL/PART: 22466/DER114	MODEL: BR700-710A2-20 (CIMMS)	MANUFACTURER: ROLLS-ROYCE DERBY PLC
INSTALLED ON 14-OCT-2014	LAST ACTUALS	CURRENT ACTUAL
0 ENG. HRS	0 A/C HRS	2232:56 ENG. HRS as of 20-JAN-2025
0 ENC	793 ENC	ENC as of 20-JAN-2025

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - AD - 9673/B-96999							
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS							
FAA 2022-11-17	FLIGHT CONTROLS - INBOARD-FLAP SUSCEPTIBILITY TO CORROSION					MANDATORY	COMPLIED WITH - C/W - DUE TO TLMC TASK 57-51-00-201 (AMM TASK 57-51-00-290-801) WITH 60M INTERVAL ALREADY INCORPORATED INTO G6000 AMP AND CONTROLLED BY CAMP SYSTEM
22-JUL-2022		DAYs		15-JAN-2025			
		HRS/MSC	-				
		AFL					
FAA 2023-12-02	TIME LIMITS/MAINTENANCE CHECKS - REVISE THE EXISTING MAINTENANCE OR INSPECTION PROGRAM					MANDATORY	COMPLIED WITH - THE TASK 32-34-00-101, 32-42-25-11 AND 51-11-00-106, THREE TASKS AS ABOVE ARE IDENTIFIED IN TLMC REV 15 ALREADY INCORPORATED INTO G6000 AMP R03, ISSUE DATE 15-FEB-2023.
39-22460 07-AUG-2023		DAYs		05-JUL-2023			
		HRS/MSC	-	1866:30			
		AFL		665			
FAA 2024-23-02	MAINTENANCE OR INSPECTION PROGRAM REVISION					MANDATORY	COMPLIED WITH - C/W. TASKS 32-43-37-101 AND 32-44-05-101 ALREADY INCORPORATED INTO SVC G6000 AMP R02-TR02 (DATED 15 OCT 2024) AND SB 700-32-6020 REV 01 ACCOMPLISHED ON 16-MAY-2022.
39-22881 15-JAN-2025		DAYs		15-JAN-2025			
		HRS/MSC	-				
		AFL					
TCCA CF-2022-15	TIME LIMITS/MAINTENANCE CHECKS - INTRODUCTION OF CERTIFICATION MAINTENANCE REQUIREMENTS (CMR)					MANDATORY	COMPLIED WITH
21-APR-2022		DAYs		20-MAY-2022			
		HRS/MSC	-				
		AFL					
TCCA CF-2023-65	TIME LIMITS/MAINTENANCE CHECKS (TLMC) - TLMC MANUAL REVISION TO INTRODUCE NEW OR REVISED TASKS AFFECTING THE MAIN LANDING GEAR (MLG), NOSE LANDING GEAR (NLG) AND PITCH TRIM ACTUATOR					MANDATORY	COMPLIED WITH
17-OCT-2023		DAYs		12-OCT-2023			
		HRS/MSC	-				
		AFL					
TCCA CF-2025-01	TIME LIMITS/MAINTENANCE CHECKS (TLMC) - MID-LIFE - AIRWORTHINESS LIMITATIONS (AWL)					MANDATORY	COMPLIED WITH - GL6000 TLMC REV 17 (DATED 09 OCT 2024) ALREADY INCORPORATED INTO SVC G6000 AMP R02-TR02 (DATED 15 OCT 2024)
13-FEB-2025		MOS		16-JAN-2025			
		HRS/MSC	-				
		AFL					
CHAPTER 23 COMMUNICATIONS							
TCCA CF-2014-40	COMMUNICATIONS - COCKPIT VOICE RECORDER IMPACT SWITCH INADVERTENTLY ACTIVATING					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
24-NOV-2014		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
CHAPTER 24 ELECTRICAL POWER							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2010-23-08	ELECTRICAL POWER - RAM AIR TURBINE (RAT) NON-CONFORMING BALANCE WASHER SCREWS					MANDATORY	COMPLIED WITH - PARAGRAPHS (G), (H) AND (I) NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER. PARAGRAPH (J) COMPLIED WITH.
14-DEC-2010		MOS HRS/MSC - AFL		12-DEC-2014 0 0			
FAA 2019-12-02	ELECTRICAL POWER - VARIABLE FREQUENCY GENERATOR HARNESS LOW CLEARANCE TO HYDRAULIC/FUEL LINES						COMPLIED WITH - C/W BY THE ACCOMPLISHMENT OF SB 700-24-6014 BASIC ON 27-JUN-2018
12-AUG-2019		MOS HRS/MSC - AFL		15-JAN-2025			
FAA 2020-12-14 PARA (G)	INSPECTION TO DETERMINE THE SERIAL NUMBER (S/N) OF THE RAT DEPLOYMENT ACTUATOR, HAVING PART NUMBER (P/N) BZ02001-01 (GL456-1301-1)					MANDATORY	COMPLIED WITH - PVW SB 700-24-6015 BASIC ACCOMPLISHED ON 18-MAR-2019 AND FOUND RAT DEPLOYMENT ACTUATOR S/N 0780 NOT AFFECTED.
08-SEP-2020		MOS HRS/MSC - AFL		20-APR-2024 2152:26 742			
FAA 2020-12-14 PARA (H)	REPLACE THE RAT DEPLOYMENT ACTUATOR, HAVING P/N BZ02001-01 (GL456-1301-1), WITH AN UPGRADED PART (IF ANY RAT DEPLOYMENT ACTUATOR IS FOUND, POST PARA (G))					MANDATORY	COMPLIED WITH - PVW SB 700-24-6015 BASIC ACCOMPLISHED ON 18-MAR-2019 AND FOUND RAT DEPLOYMENT ACTUATOR S/N 0780 NOT AFFECTED.
08-SEP-2020		MOS HRS/MSC - (s) AFL		20-APR-2024 2152:26 742			
TCCA CF-2010-01 PART (I)	IDENTIFICATION RAM AIR TURBINE (RAT) - NON-CONFORMING BALANCE WASHER SCREWS CHECK						NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
16-FEB-2010		MOS HRS/MSC - AFL		18-DEC-2014 0 0			
TCCA CF-2010-01 PART (II)	REPLACEMENT RAM AIR TURBINE (RAT) - NON-CONFORMING BALANCE WASHER SCREWS OF THE BALANCE WASHER SCREWS AND IDENTIFICATION OF THE RAT						NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
16-FEB-2010		MOS HRS/MSC - AFL		18-DEC-2014 0 0			
TCCA CF-2010-01 PART (III)	REPLACEMENT OF PARTS					MANDATORY	COMPLIED WITH - AT MANUFACTURE
16-FEB-2010		MOS HRS/MSC - AFL		18-DEC-2014 0 0			
TCCA CF-2018-22	ELECTRICAL POWER - VARIABLE FREQUENCY GENERATOR HARNESS LOW CLEARANCE TO HYDRAULIC/FUEL LINES					MANDATORY	COMPLIED WITH - PCW SB 700-24-6014 BASIC REVISION ON 27 JUN 2018
16-AUG-2018		MOS HRS/MSC - AFL		27-JUN-2018 631:35 234			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2019-38	ELECTRICAL POWER - RAM AIR TURBINE (RAT) DEPLOYMENT ACTUATOR GALLING					MANDATORY	COMPLIED WITH - CARRIED OUT SB 700-24-6015 BASIC ISSUE, RAT DEPLOYMENT ACTUATOR SN NOT AFFECTED.
13-NOV-2019		MOS HRS/MSC - (s) AFL		12-NOV-2019			
TCCA CF-2019-38 PART I	CHECK THE AEROPLANE MAINTENANCE RECORDS TO DETERMINE THE SERIAL NUMBER OF THE RAT DEPLOYMENT ACTUATOR, PART NUMBER (P/N) BZ02001-01 (GL456-1301-1), INSTALLED ON THE AEROPLANE					MANDATORY	NOT APPLICABLE - BY C/W TCCA CF-2019-38 PART II
13-NOV-2019		MOS HRS/MSC - AFL		12-NOV-2019			
TCCA CF-2019-38 PART II	VERIFY THE SERIAL NUMBER OF THE RAT DEPLOYMENT ACTUATOR, P/N BZ02001-01 (GL456-1301-1)					MANDATORY	COMPLIED WITH - CARRIED OUT SB 700-24-6015 BASIC ISSUE, RAT DEPLOYMENT ACTUATOR SN NOT AFFECTED.
13-NOV-2019		MOS HRS/MSC - (s) AFL		12-NOV-2019			
TCCA CF-2019-38 PART III	REMOVE AND REPLACE THE RAT DEPLOYMENT ACTUATOR P/N BZ02001-01 (GL456-1301-1)					MANDATORY	NOT APPLICABLE - DUE TO SN OF RAT DEPLOYMENT ACTUATOR NOT AFFECTED.
13-NOV-2019		MOS HRS/MSC - (s) AFL		12-NOV-2019			
CHAPTER 25 EQUIPMENT/FURNISHINGS							
FAA 1974-08-09 R03	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION					MANDATORY	COMPLIED WITH
39-16951		MOS HRS/MSC 1000 AFL		09-MAR-2023 1793:47 638	2793:47	RECURRING	
CHAPTER 26 FIRE PROTECTION							
FAA 2014-20-03	FIRE PROTECTION - INSPECT TO DETERMINE THE PART NUMBER AND FOR ALL AFFECTED CHECK TEE FITTINGS MEASURE FOR CORRECT DEPTH, AND REPLACE IF NECESSARY					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
05-NOV-2014		MOS HRS/MSC - AFL		18-DEC-2014 0 0			
FAA 2018-22-08	FIRE PROTECTION - VISUAL INSPECTION OF CONNECTIONS BETWEEN THE FIREX SQUIB WIRE HARNESS CONNECTORS AND FIREX BOTTLE CONNECTORS, AND CORRECTIVE ACTION IF NECESSARY					MANDATORY	COMPLIED WITH - PCW SB 700-26-6003 REV 01 ON 27-JUN-2018 AT 631.58 HRS AND 234 AFL
10-DEC-2018		MOS HRS/MSC - AFL		09-MAR-2020			
TCCA CF-2013-41	FIREEX CHECK TEE FITTING - INCORRECT ASSEMBLY					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
		MOS HRS/MSC - AFL		18-DEC-2014 0 0			
TCCA CF-2013-41 PART I	VERIFICATION OF THE SERIAL NUMBER					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
		MOS HRS/MSC - AFL		18-DEC-2014 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2013-41 PART II	INSPECTION AND REPLACEMENT OF THE CHECK TEE FITTING					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
TCCA CF-2018-08 R01	FIRE PROTECTION - ENGINE FIRE EXTINGUISHERS SQUIB CONNECTOR WIRING LENGTH DISCREPANCY					MANDATORY	COMPLIED WITH
12-MAR-2018		MOS		27-JUN-2018			
		HRS/MSC	-	631:35			
		AFL		234			
CHAPTER 27 FLIGHT CONTROLS							
FAA 2009-15-03	INSPECTION AND LUBRICATION OF ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
19-AUG-2009		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
FAA 2009-15-03 PARA (G)(1)	FOR INSPECTION AND LUBRICATION OF ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS AIRPLANES IDENTIFIED IN PARAGRAPH (F)					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
19-AUG-2009		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
FAA 2009-15-03 PARA (G)(2)	FOR INSPECTION AND LUBRICATION OF ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS AIRPLANES NOT IDENTIFIED IN PARAGRAPH (F)					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
19-AUG-2009		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
FAA 2015-17-05	FLIGHT CONTROLS - INSPECTING FOR CORRECT CLEARANCE AND REWORK IF NECESSARY, AND, FOR CERTAIN OTHER AIRPLANES, INSTALLING A COVER FOR THE AILERON PULLEY ASSEMBLY					MANDATORY	NOT APPLICABLE - DUE TO S/N
29-SEP-2015		MOS		09-SEP-2015			
		HRS/MSC	-	15:36			
		AFL		6			
FAA 2015-17-05 PARA (G)	INSTALL A COVER FOR THE NO. 1 AILERON PULLEY, INCLUDING DOING A GVI FOR CORRECT CLEARANCE AND REWORK AS APPLICABLE					MANDATORY	NOT APPLICABLE - DUE TO S/N
29-SEP-2015		MOS		09-SEP-2015			
		HRS/MSC	-	15:36			
		AFL		6			
FAA 2015-17-05 PARA (H)	ACCOMPLISH A GVI FOR CORRECT CLEARANCE AND, REWORK, AS APPLICABLE					MANDATORY	NOT APPLICABLE - DUE TO S/N
29-SEP-2015		MOS		09-SEP-2015			
		HRS/MSC	-	15:36			
		AFL		6			
FAA 2015-17-05 PARA (I)	DO THE RE-IDENTIFICATION OF THE OVERWING PANELS					MANDATORY	NOT APPLICABLE - DUE TO S/N
29-SEP-2015		MOS		09-SEP-2015			
		HRS/MSC	-	15:36			
		AFL		6			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2017-14-15	FLIGHT CONTROLS - A REVISION TO THE MAINTENANCE OR INSPECTION PROGRAM TO INCORPORATE CERTIFICATION MAINTENANCE REQUIREMENT TASKS THAT INTRODUCE FUNCTIONAL TESTS OF THE CONTROL CABLE TENSION					MANDATORY	COMPLIED WITH
31-AUG-2017		MOS HRS/MSC - (s) AFL		30-SEP-2017 490:22 178			
FAA 2017-14-15 PARA (G)	REVISE THE MAINTENANCE OR INSPECTION PROGRAM					MANDATORY	COMPLIED WITH - TASK 27-11-35-101, 27-11-35-102 AND 27-21-27-101, THESE THREE TASKS ARE ALREADY INCLUDED IN ZATC GLOBAL 6000 AMP R01-TR01(20-FEB-2017).
31-AUG-2017		DAYs HRS/MSC - AFL		30-SEP-2017 490:22 178			
FAA 2017-14-15 PARA (H)	ACCOMPLISH CERTIFICATION MAINTENANCE REQUIREMENT (CMR) TASKS					MANDATORY	COMPLIED WITH - TASK 27-11-35-101, 27-11-35-102 AND 27-21-27-101, THESE THREE TASKS ARE ALREADY INCLUDED IN ZATC GLOBAL 6000 AMP R01-TR01(20-FEB-2017). AND THESE TASKS ALL ACCOMPLISHED BY BOMBARDIER SERVICE CENTER SINGAPORE ON 28-SEP-2017
31-AUG-2017		MOS HRS/MSC - AFL		30-SEP-2017 490:22 178			
FAA 2017-19-11	FLIGHT CONTROLS - AN OPERATIONAL TEST OF THE FCU BACK-UP MODULES AND REPAIR (IF ANY FCU FAILS ANY OPERATIONAL TEST REQUIRED BY THIS AD)					MANDATORY	
23-OCT-2017		MOS HRS/MSC 3000 AFL			3000		
FAA 2018-20-20	FLIGHT CONTROLS - ELEVATOR CONTROL SYSTEM BRACKET CRACKING					MANDATORY	COMPLIED WITH - PREVIOUSLY COMPLIED WITH
20-NOV-2018		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
FAA 2021-08-11	FLIGHT CONTROLS - ROLL CONTROL INPUT MODULES (RCIM) MAINTENANCE MANUAL / INSPECTION MANUAL INCORPORATION					MANDATORY	COMPLIED WITH - C/W BY GL6000 AMM REV38 (DATED FEBRUARY 22, 2021) OR LATER REVISIONS USED
27-APR-2021		MOS HRS/MSC - AFL		15-JAN-2025			
FAA 2021-10-02	FLIGHT CONTROLS - ELEVATOR CONTROL SYSTEM - VERTICAL TORQUE TUBE SEIZURE - SAND CONTAMINATION OF BEARING					MANDATORY	COMPLIED WITH - C/W BY THE ACCOMPLISHMENT OF SB 700-27-6012 REV 02 ON 08-JUN-2023 PER BASS WO# 258334.
		MOS HRS/MSC - (s) AFL		15-JAN-2025			
FAA 2021-10-02 PARA (G)	PERFORM A GENERAL VISUAL INSPECTION OF THE LEFT AND RIGHT-HAND ELEVATOR TORQUE TUBE BEARINGS FOR ANY SAND, DUST, OR CORROSION, PERFORM A FUNCTIONAL TEST OF THE ELEVATOR CONTROL SYSTEM AND ACCOMPLISH ALL APPLICABLE CORRECTIVE ACTIONS					MANDATORY	NOT APPLICABLE - N/A - BY PERFORMING TLMC TASK 27-31-19-101 PER FAA AD 2021-10-02 AMOC-2023-01788-T.
29-JUL-2021		MOS HRS/MSC - AFL		15-JAN-2025			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2021-10-02 PARA (H)	SUBMIT A REPORT OF ALL FINDINGS, POSITIVE AND NEGATIVE, OF EACH OF THE FIRST THREE INSPECTIONS					MANDATORY	NOT APPLICABLE - N/A - PER FAA AD 2021-10-02 AMOC-2023-01788-T.
29-JUL-2021					15-JAN-2025		
FAA 2022-24-01	REVISING THE EXISTING AFM TO CORRECT THE AFFECTED PERFORMANCE CHARTS					MANDATORY	COMPLIED WITH - C/W - GL6000 AFM UPDATED TO REV 44.
09-MAR-2023					15-JAN-2025		
FAA 2023-05-11	FLIGHT CONTROLS - AIRPLANE FLIGHT MANUAL - REVISION					MANDATORY	COMPLIED WITH - C/W - GL6000 AFM UPDATED TO REV.45.
FAA 39-22380 12-MAY-2023					15-JAN-2025		
FAA 2023-08-01 39-22416 20-JUN-2023	REVISE THE EXISTING AFM					MANDATORY	COMPLIED WITH
					16-JUN-2023		
TCCA CF-2008-31	ELEVATOR PCU ATTACHMENT BOLT FRACTURE - ALL PART NUMBER (P/N) GT411-3800-5 AND GT411-3800-7 PCU ATTACHMENT JOINTS						NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
31-JUL-2014					18-DEC-2014		
TCCA CF-2014-23	FLIGHT CONTROLS - RESTRICTED MOVEMENT OF THE AILERON PULLEY AND CONTROL CABLES					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
31-JUL-2014					18-DEC-2014		
TCCA CF-2014-23 PART I 31-JUL-2014	INSPECT, REWORK IF REQUIRED , AND INSTALL A COVER FOR THE NO. 1 AILERON PULLEY (PART I - APPLICABLE TO AEROPLANES THAT HAVE NOT INCORPORATED A COVER FOR THE NO. 1 AILERON PULLEY)					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
					18-DEC-2014		
TCCA CF-2014-23 PART II 31-JUL-2014	PERFORM AN INSPECTION AND REWORK AS REQUIRED (PART II: FOR AEROPLANES THAT HAVE INCORPORATED A COVER FOR THE NO1. AILERON PULLEY) / DO THE RE-IDENTIFICATION OF THE OVERWING PANELS FOR AEROPLANES THAT HAVE INCORPORATED THE SERVICE NON-INCORPORATED ENGINEERING ORDERS (SNIEO) OR SERVICE REQUESTS FOR PRODUCT SUPPORT ACTION (SRPSA)					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
					18-DEC-2014		
TCCA CF-2015-06 R01 22-APR-2015	FLIGHT CONTROLS – IMPROPERLY FORMULATED TASK IN THE AIRCRAFT MAINTENANCE MANUAL FOR THE FLIGHT CONTROL UNIT BACK-UP MODULE					MANDATORY	COMPLIED WITH - FOUND PREVIOUSLY COMPLIED WITH
					13-JUN-2023		
					1854:53		
					659		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2015-06 R01	NO. 1 FLIGHT CONTROL UNIT (FCU) BACK-UP MODULE OPERATIONAL CHECK					MANDATORY	
22-APR-2015	MOS HRS/MSC AFL			09-SEP-2015	3000		
TCCA CF-2015-06 R01	NO. 2 FLIGHT CONTROL UNIT (FCU) BACK-UP MODULE OPERATIONAL CHECK					MANDATORY	
22-APR-2015	MOS HRS/MSC AFL			09-SEP-2015	3000		
TCCA CF-2016-06 PART I	TIME LIMITS/MAINTENANCE CHECKS (TLMC) - MANUAL CHANGE					MANDATORY	COMPLIED WITH - THE MPD HAD BEEN REUSED ACCORDING TO THE TCCA AD CF 2016-06 PART I.
11-MAR-2016	DAYS HRS/MSC AFL			10-MAR-2016			
TCCA CF-2016-06 R01	FLIGHT CONTROLS - AILERON & RUDDER CONTROL SYSTEM - CABLE TENSION RELAXATION					MANDATORY	COMPLIED WITH
25-JUL-2016	MOS HRS/MSC AFL			28-SEP-2017 485:04 176			
TCCA CF-2016-06 R01 PART I	ACCOMPLISH TIME LIMITS / MAINTENANCE CHECKS (TLMC) - MANUAL CHANGE					MANDATORY	COMPLIED WITH
25-JUL-2016	DAYS HRS/MSC AFL			28-SEP-2017 485:04 176			
TCCA CF-2016-06 R01 PART II	ACCOMPLISH INSPECTION OF THE AILERON AND RUDDER CONTROL CABLE TENSION					MANDATORY	COMPLIED WITH
25-JUL-2016	MOS HRS/MSC AFL			28-SEP-2017 485:04 176			
TCCA CF-2017-32	FLIGHT CONTROLS - ELEVATOR CONTROL SYSTEM BRACKET CRACKING					MANDATORY	COMPLIED WITH
	MOS HRS/MSC AFL			27-JUN-2018 631:35 234			
TCCA CF-2020-29	FLIGHT CONTROLS - ELEVATOR CONTROL SYSTEM - VERTICAL TORQUE TUBE SEIZURE - SAND CONTAMINATION OF BEARING					MANDATORY	
04-SEP-2020	MOS HRS/MSC AFL			18-DEC-2014			
TCCA CF-2020-29 R01	FLIGHT CONTROLS - ELEVATOR CONTROL SYSTEM - VERTICAL TORQUE TUBE SEIZURE - SAND CONTAMINATION OF BEARING					MANDATORY	COMPLIED WITH - SB 700-27-6012 REV 02 CW ON 08-JUN-2023 PER WO#258334
03-NOV-2023	DAYS HRS/MSC AFL			27-OCT-2023			
TCCA CF-2020-35	FLIGHT CONTROLS - ROLL CONTROL INPUT-MODULES (RCIMS) INCORRECT INSTALLATION					MANDATORY	COMPLIED WITH
21-OCT-2020	DAYS HRS/MSC AFL			12-OCT-2020			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2020-49	FLIGHT CONTROLS - INBOARD-FLAP SUSCEPTIBILITY TO CORROSION					MANDATORY	COMPLIED WITH
03-DEC-2020	03-DEC-2020	03-DEC-2020	03-DEC-2020	03-DEC-2020	03-DEC-2020	03-DEC-2020	03-DEC-2020
		03-DEC-2020	03-DEC-2020	03-DEC-2020	03-DEC-2020	03-DEC-2020	03-DEC-2020
TCCA CF-2020-49 R01	FLIGHT CONTROLS - INBOARD-FLAP SUSCEPTIBILITY TO CORROSION					MANDATORY	COMPLIED WITH
03-JUN-2021	03-JUN-2021	03-JUN-2021	03-JUN-2021	03-JUN-2021	03-JUN-2021	03-JUN-2021	03-JUN-2021
		03-JUN-2021	03-JUN-2021	03-JUN-2021	03-JUN-2021	03-JUN-2021	03-JUN-2021
TCCA CF-2022-30	FLIGHT CONTROLS – FLAP FAIL ON APPROACH					MANDATORY	COMPLIED WITH - THIS AD PER EATC EO-BD700-27-22022R0.
17-JUN-2022	17-JUN-2022	17-JUN-2022	17-JUN-2022	17-JUN-2022	17-JUN-2022	17-JUN-2022	17-JUN-2022
		17-JUN-2022	17-JUN-2022	17-JUN-2022	17-JUN-2022	17-JUN-2022	17-JUN-2022
TCCA CF-2024-06	FLIGHT CONTROLS - INCORRECT AIRPLANE FLIGHT MANUAL (AFM) APPROACH SPEED ADDER AND LANDING DISTANCE FACTORS FOR SLAT-FLAP FAIL CAUTION CAS MESSAGE AND JAMMED OR INOPERATIVE SLAT/FLAP CONTROL LEVER (SFCL)					MANDATORY	COMPLIED WITH - BY AFM UPDATED TO REV 48.
05-MAR-2024	05-MAR-2024	05-MAR-2024	05-MAR-2024	05-MAR-2024	05-MAR-2024	05-MAR-2024	05-MAR-2024
		05-MAR-2024	05-MAR-2024	05-MAR-2024	05-MAR-2024	05-MAR-2024	05-MAR-2024
TCCA CF-2024-27	FLIGHT CONTROLS - INCORRECT AIRPLANE FLIGHT MANUAL (AFM) APPROACH SPEED ADDER AND LANDING DISTANCE FACTORS FOR SLAT-FLAP FAIL CAUTION CREW ALERTING SYSTEM (CAS) MESSAGE AND JAMMED OR INOPERATIVE SLAT/FLAP CONTROL LEVER (SFCL)					MANDATORY	COMPLIED WITH - G6000 AFM UPDATED TO REV 49 AND INFORMED ALL FLIGHT CREWS.
07-AUG-2024	07-AUG-2024	07-AUG-2024	07-AUG-2024	07-AUG-2024	07-AUG-2024	07-AUG-2024	07-AUG-2024
		07-AUG-2024	07-AUG-2024	07-AUG-2024	07-AUG-2024	07-AUG-2024	07-AUG-2024
CHAPTER 28	FUEL						
FAA 2021-10-22	FUEL - REFUEL DEFUEL TUBE - MISLOCATED BRACKET ASSEMBLY					MANDATORY	COMPLIED WITH - C/W BY THE ACCOMPLISHMENT OF SB 700-28-6006 BASIC ON 17-APR-2022 PER BASS WO/T 247911
06-JUL-2021	06-JUL-2021	06-JUL-2021	06-JUL-2021	06-JUL-2021	06-JUL-2021	06-JUL-2021	06-JUL-2021
		06-JUL-2021	06-JUL-2021	06-JUL-2021	06-JUL-2021	06-JUL-2021	06-JUL-2021
TCCA CF-2020-37	FUEL - REFUEL DEFUEL TUBE - MISLOCATED BRACKET ASSEMBLY					MANDATORY	COMPLIED WITH
23-OCT-2020	23-OCT-2020	23-OCT-2020	23-OCT-2020	23-OCT-2020	23-OCT-2020	23-OCT-2020	23-OCT-2020
		23-OCT-2020	23-OCT-2020	23-OCT-2020	23-OCT-2020	23-OCT-2020	23-OCT-2020
CHAPTER 29	HYDRAULIC POWER						
FAA 2011-01-10	HYDRAULIC SYSTEM LINES - RELOCATE THE NO. 2 AND NO. 3 HYDRAULIC SYSTEM LINES IN THE WING AUXILIARY SPAR AREA ON THE LEFT SIDE OF THE AIRCRAFT, AND MODIFY THE LEFT WING RIB AND LEFT AND RIGHT DEBRIS SHIELDS					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
09-FEB-2011	09-FEB-2011	09-FEB-2011	09-FEB-2011	09-FEB-2011	09-FEB-2011	09-FEB-2011	09-FEB-2011
		09-FEB-2011	09-FEB-2011	09-FEB-2011	09-FEB-2011	09-FEB-2011	09-FEB-2011
TCCA CF-2010-10	HYDRAULIC SYSTEMS NUMBER 2 AND 3: DAMAGE CAUSED BY MAIN LANDING GEAR TIRE FAILURE						NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2024-07	HYDRAULIC POWER - ENGINE DRIVEN PUMP HYDRAULIC HOSES FOULING WITH PYLON					MANDATORY	NOT APPLICABLE - BY AIRCRAFT S/N
06-MAR-2024	MOS HRS/MSC - AFL			22-FEB-2024			
CHAPTER 30 ICE AND RAIN PROTECTION							
FAA 2014-03-05	ICE AND RAIN PROTECTION - MODIFY THE AIR DATA PROBES AND SENSORS (SUPERSEDED BY FAA AD 2014-26-09)					MANDATORY	NOT APPLICABLE - IN ACCORDANCE WITH BOMBARDIER SERVICE BULLETIN 700-30-021, REVISION 01, DATED NOVEMBER21, 2012.
01-APR-2014	MOS HRS/MSC - AFL			18-DEC-2014 0 0			
FAA 2014-26-09	ICE AND RAIN PROTECTION - MODIFY THE AIR DATA PROBES AND SENSORS					MANDATORY	NOT APPLICABLE - IN ACCORDANCE WITH BOMBARDIER S/B 700-30-021 R1
19-FEB-2015	MOS HRS/MSC - AFL			09-SEP-2015 15:36 6			
FAA 2014-26-09 PARA (G)	MODIFY THE AIR DATA PROBES AND SENSORS (RETAINED MODIFICATION)					MANDATORY	NOT APPLICABLE - IN ACCORDANCE WITH BOMBARDIER S/B 700-30-021 R1
19-FEB-2015	MOS HRS/MSC - AFL			09-SEP-2015 15:36 6			
FAA 2014-26-09 PARA (H)	MODIFY THE AIR DATA PROBES AND SENSORS (NEW MODIFICATION)					MANDATORY	NOT APPLICABLE - IN ACCORDANCE WITH BOMBARDIER S/B 700-30-021 R1
19-FEB-2015	MOS HRS/MSC - AFL			09-SEP-2015 15:36 6			
TCCA CF-2012-32	ICE PROTECTION SYSTEM - INABILITY TO DETECT NUMBER 2 PITOT STATIC PROBE HEATER FAILURE					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
07-JAN-2013	MOS HRS/MSC - AFL			18-DEC-2014 0 0			
CHAPTER 31 INDICATING/RECORDING SYSTEMS							
TCCA CF-2024-14 PART II	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM					MANDATORY	COMPLIED WITH - BY INSERTING A COPY OF THE AD ITSELF INTO G6000 AFM AND INFORMED THE FLIGHT CREWS
	MOS HRS/MSC - AFL			22-MAY-2024			
TCCA CF-2025-03	INDICATING/RECORDING SYSTEMS - UNSECURED MAINTENANCE PORTS					MANDATORY	COMPLIED WITH - C/W BY ACCOMPLISHMENT OF SB 700-46-6008 BASIC ON 08-JUN-2023 PER BASS WO# 258334.
29-JAN-2025	MOS HRS/MSC - AFL			16-JAN-2025			
CHAPTER 32 LANDING GEAR							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2012-17-01	GOODYEAR AVIATION TIRES					AIRWORTHINESS DIRECTIVE	NOT APPLICABLE - NOT APPLICABLE PER PART NUMBER INSTALLED AT THIS TIME
		MOS HRS/MSC - AFL		09-SEP-2015			
FAA 2019-03-22	LANDING GEAR - SAFETY DEVICE MODIFICATION AT NOSE GEAR RETRACTION ACTUATOR TO MAIN FITTING JOINT					MANDATORY	NOT APPLICABLE - N/A BY A/C S/N
15-APR-2019		MOS HRS/MSC - (s) AFL		15-JAN-2025			
FAA 2019-03-22 PARA (G)	REVISE THE EXISTING MAINTENANCE OR INSPECTION PROGRAM, AS APPLICABLE AND ACCOMPLISH THE TASKS SPECIFIED IN AWL					MANDATORY	NOT APPLICABLE - N/A BY A/C S/N
15-APR-2019		DAY HRS/MSC - AFL		15-JAN-2025			
FAA 2019-03-22 PARA (H)(1)	PERFORM A GVI FOR DAMAGE OF THE COTTER PIN RETAINING THE BOLT THAT SECURES THE NLG RETRACTION ACTUATOR TO THE NLG STRUT, AND A GVI OF THE MODIFICATION NUMBER SHOWN ON THE IDENTIFICATION PLATE FOR THE NLG STRUT, AND, IF APPLICABLE, MARK THE CORRECT MODIFICATION NUMBER ON THE IDENTIFICATION PLATE OF THE NLG STRUT AND PERFORM THE MODIFICATION OF THE NLG RETRACTION ACTUATOR HARDWARE (IF DAMAGE TO THE COTTER PIN IS PRESENT)					MANDATORY	NOT APPLICABLE - N/A BY A/C S/N
15-APR-2019		MOS HRS/MSC - AFL		15-JAN-2025			
FAA 2020-03-21	LANDING GEAR - TRAILING ARM ASSEMBLY AXLE BORE CORROSION					MANDATORY	NOT APPLICABLE
12-MAR-2020		MOS HRS/MSC - (s) AFL		03-MAR-2020			
FAA 2020-03-21 PARA (H) LH	INSPECT THE LEFT HAND MLG TRAILING ARM ASSEMBLIES TO DETERMINE IF AN Affected MLG TRAILING ARM ASSEMBLY IS INSTALLED					MANDATORY	COMPLIED WITH - TRAILING ARM ASSEMBLY PN & SN NOT Affected.
12-MAR-2020		DAY HRS/MSC - AFL		03-MAR-2020			
FAA 2020-03-21 PARA (H) RH	INSPECT THE RIGHT HAND MLG TRAILING ARM ASSEMBLIES TO DETERMINE IF AN Affected MLG TRAILING ARM ASSEMBLY IS INSTALLED					MANDATORY	COMPLIED WITH - TRAILING ARM ASSEMBLY PN & SN NOT Affected.
12-MAR-2020		DAY HRS/MSC - AFL		03-MAR-2020			
FAA 2020-03-21 PARA (I)&(J) LH	ACCOMPLISH A DETAILED INSPECTION FOR SURFACE FINISH DISCREPANCIES ON THE INNER DIAMETER OF THE Affected MLG TRAILING ARM ASSEMBLY AXLE BORE (IF, DURING THE INSPECTION OR REVIEW REQUIRED BY PARA (H), IT IS DETERMINED THAT An Affected MLG TRAILING ARM ASSEMBLY IS INSTALLED) AND ACCOMPLISH ALL APPLICABLE CORRECTIVE ACTIONS						NOT APPLICABLE - DUE TO PNS & SNS OF TRAILING ARM ASSEMBLY NOT Affected
12-MAR-2020		MOS HRS/MSC - (s) AFL		03-MAR-2020			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2020-03-21 PARA (I)&(J) RH	ACCOMPLISH A DETAILED INSPECTION FOR SURFACE FINISH DISCREPANCIES ON THE INNER DIAMETER OF THE AFFECTED MLG TRAILING ARM ASSEMBLY AXLE BORE (IF, DURING THE INSPECTION OR REVIEW REQUIRED BY PARA (H), IT IS DETERMINED THAT AN AFFECTED MLG TRAILING ARM ASSEMBLY IS INSTALLED) AND ACCOMPLISH ALL APPLICABLE CORRECTIVE ACTIONS						NOT APPLICABLE - DUE TO PNS & SNS OF TRAILING ARM ASSEMBLY NOT Affected
12-MAR-2020	MOS HRS/MSC - (s) AFL			03-MAR-2020			
FAA 2020-03-21 PARA (K)	REPLACE THE PRIMER AND PAINT AND APPLY THE CORROSION PREVENTIVE COMPOUND ON THE INNER DIAMETER OF THE AXLE BORE ON ALL Affected MLG TRAILING ARM ASSEMBLIES				MANDATORY		NOT APPLICABLE - DUE TO PNS & SNS OF TRAILING ARM ASSEMBLY NOT Affected
12-MAR-2020	MOS HRS/MSC - AFL			03-MAR-2020			
FAA 2020-03-21 PARA (M)	SUBMIT A REPORT TO BOMBARDIER OF POSITIVE FINDINGS OF THE INSPECTIONS REQUIRED BY PARAGRAPHS (I) AND (J) OF THIS AD				MANDATORY		NOT APPLICABLE - DUE TO PNS & SNS OF TRAILING ARM ASSEMBLY NOT Affected
12-MAR-2020	DAYs HRS/MSC - (s) AFL			03-MAR-2020			
FAA 2023-24-08 39-22625 06-FEB-2024	NOSE WHEEL STEERING SELECTOR VALVE (SSV) REPLACEMENT				06-AUG-2029 5296:29 M	MANDATORY	
06-FEB-2018	MOS HRS/MSC - (s) AFL			29-JAN-2018			
TCCA CF-2018-05 06-FEB-2018	LANDING GEAR - SAFETY DEVICE MODIFICATION AT NOSE GEAR RETRACTION ACTUATOR TO MAIN FITTING JOINT				MANDATORY		NOT APPLICABLE - N/A DUE TO SERIAL NUMBER
TCCA CF-2018-05 PART I 06-FEB-2018	TIME LIMITS/MAINTENANCE CHECKS (TLMC) - MANUAL CHANGE				29-JAN-2018	MANDATORY	NOT APPLICABLE - N/A DUE TO SERIAL NUMBER
TCCA CF-2018-05 PART II 06-FEB-2018	VISUAL INSPECTION AND CONDITION-DEPENDENT MODIFICATION				29-JAN-2018	MANDATORY	NOT APPLICABLE - N/A DUE TO SERIAL NUMBER
TCCA CF-2018-05 PART III 06-FEB-2018	FUTURE MODIFICATIONS				29-JAN-2018	MANDATORY	NOT APPLICABLE - N/A DUE TO SERIAL NUMBER
TCCA CF-2018-05 PART III 06-FEB-2018	MOS HRS/MSC - AFL				29-JAN-2018		
TCCA CF-2019-33 27-SEP-2019	LANDING GEAR - TRAILING ARM ASSEMBLY AXLE BORE CORROSION				24-SEP-2019	MANDATORY	COMPLIED WITH - CARRIED OUT SB 700-32-6016 BASIC ISSUE, TRAILING ARM ASSEMBLY PN & SN NOT Affected.
	MOS HRS/MSC - (s) AFL						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2019-33 PART I	INSPECTION OF MLG TRAILING ARM ASSEMBLY P/N AND SERIAL NUMBER					MANDATORY	COMPLIED WITH - CARRIED OUT SB 700-32-6016 BASIC ISSUE, TRAILING ARM ASSEMBLY PN IS AFFECTED, HOWEVER, THE SNS ARE NOT LISTED IN TABLE 1 IN APPX 4 OF THIS SB
27-SEP-2019		MOS HRS/MSC - AFL		24-SEP-2019			
TCCA CF-2019-33 PART II	FIRST INSPECTION OF THE MLG TRAILING ARM ASSEMBLY SURFACE FINISH					MANDATORY	NOT APPLICABLE - DUE TO PNS & SNS OF TRAILING ARM ASSEMBLY NOT AFFECTED
27-SEP-2019		MOS HRS/MSC - AFL		24-SEP-2019			
TCCA CF-2019-33 PART III	SECOND INSPECTION OF THE MLG TRAILING ARM ASSEMBLY SURFACE FINISH					MANDATORY	NOT APPLICABLE - DUE TO PNS & SNS OF TRAILING ARM ASSEMBLY NOT AFFECTED
27-SEP-2019		MOS HRS/MSC - AFL		24-SEP-2019			
TCCA CF-2019-33 PART IV	PRIMER AND PAINT REPLACEMENT ON THE MLG TRAILING ARM ASSEMBLY AXLE BORE INNER DIAMETER					MANDATORY	NOT APPLICABLE - DUE TO PNS & SNS OF TRAILING ARM ASSEMBLY NOT AFFECTED
27-SEP-2019		MOS HRS/MSC - AFL		24-SEP-2019			
TCCA CF-2019-33 R01	LANDING GEAR - TRAILING ARM ASSEMBLY AXLE BORE CORROSION					MANDATORY	NOT APPLICABLE - CARRIED OUT PART I, PARTS II, III & IV NOT REQUIRED
06-FEB-2020		MOS HRS/MSC - (s) AFL		06-FEB-2020			
TCCA CF-2019-33 R01 PART I	INSPECTION OF MLG TRAILING ARM ASSEMBLY P/N AND SERIAL NUMBER					MANDATORY	COMPLIED WITH
06-FEB-2020		MOS HRS/MSC - AFL		06-FEB-2020			
TCCA CF-2019-33 R01 PART II	FIRST INSPECTION OF THE MLG TRAILING ARM ASSEMBLY SURFACE FINISH					MANDATORY	NOT APPLICABLE - NOT REQUIRED
06-FEB-2020		MOS HRS/MSC - (s) AFL		06-FEB-2020			
TCCA CF-2019-33 R01 PART III	SECOND INSPECTION OF THE MLG TRAILING ARM ASSEMBLY SURFACE FINISH					MANDATORY	NOT APPLICABLE - NOT REQUIRED
06-FEB-2020		MOS HRS/MSC - (s) AFL		06-FEB-2020			
TCCA CF-2019-33 R01 PART IV	PRIMER AND PAINT REPLACEMENT ON THE MLG TRAILING ARM ASSEMBLY AXLE BORE INNER DIAMETER					MANDATORY	NOT APPLICABLE - NOT REQUIRED
06-FEB-2020		MOS HRS/MSC - (s) AFL		06-FEB-2020			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2022-25	LANDING GEAR - INTRODUCTION OF NEW BRAKE ACCUMULATOR LIFE LIMIT					MANDATORY	COMPLIED WITH - COMPILED WITH THIS AD AS PER E0#BD700-32-22018R0.
17-MAY-2022		DAY(S) HRS/MSC - AFL		02-APR-2024			
TCCA CF-2022-53	LANDING GEAR - BRAKE CONTROL SYSTEM - UNCOMMANDDED BRAKE PRESSURE DUE TO BRAKE CONTROL UNIT (BCU) FAILURE					MANDATORY	
22-SEP-2022		MOS HRS/MSC AFL	48	(EFF)	22-SEP-2026		
TCCA CF-2023-02	LANDING GEAR - NOSE LANDING GEAR - STEERING SHUTOFF VALVE SLOW TO DEACTIVATE					MANDATORY	
25-JAN-2023		MOS HRS/MSC AFL	66 3200	(EFF)	25-JUL-2028 4964:21		
CHAPTER 33 LIGHTS							
FAA 2021-03-17	LIGHTS - EMERGENCY LIGHT BATTERY PACK CORROSION					MANDATORY	NOT APPLICABLE - N/A BY A/C S/N
30-MAR-2021		MOS HRS/MSC - (s) AFL		15-JAN-2025			
FAA 2021-03-17 PARA (G)	INSPECT THE ELB TO DETERMINE THE LAST REPLACEMENT DATE OR THE MANUFACTURING DATE, AS APPLICABLE, REPLACE THE ELB (IF, ANY DATE IS FOUND TO BE 4 YEARS OR OLDER)					MANDATORY	NOT APPLICABLE - N/A BY A/C S/N
30-MAR-2021		MOS HRS/MSC - AFL		15-JAN-2025			
FAA 2021-03-17 PARA (H)	REVISE THE EXISTING MAINTENANCE OR INSPECTION PROGRAM, AS APPLICABLE					MANDATORY	NOT APPLICABLE - N/A BY A/C S/N
30-MAR-2021		DAY(S) HRS/MSC - AFL		15-JAN-2025			
FAA 2021-03-17 PARA (J)	COMPLIANCE WITH RESTORATION TASK FOR AIRPLANES ON WHICH THE MISIDENTIFIED TASK WAS ACCOMPLISHED					MANDATORY	NOT APPLICABLE - N/A BY A/C S/N
30-MAR-2021		MOS HRS/MSC - (s) AFL		15-JAN-2025			
TCCA CF-2020-07	LIGHTS - EMERGENCY LIGHT BATTERY PACK CORROSION					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER
31-MAR-2020		MOS HRS/MSC - (s) AFL		16-FEB-2023			
CHAPTER 34 NAVIGATION							
FAA 2016-10-06	NAVIGATION - GENERAL VISUAL INSPECTION OF THE NETWORK INTERFACE INSTALLATION BETWEEN THE IMS AND CES TO DETERMINE IF PINS ARE PRESENT AT POSITIONS 25, 27, 48, 50 AND DISCONNECT THE INSTALLATION IF ANY PINS ARE PRESENT					MANDATORY	COMPLIED WITH - BY INCORPORATION OF SB 700-46-6005 R2 ON 07-AUG-2015
23-JUN-2016		MOS HRS/MSC - AFL		07-AUG-2015 9:12 4			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2022-13-05	NAVIGATION - AIRCRAFT FLIGHT MANUAL - REVISE					MANDATORY	COMPLIED WITH - C/W - GL6000 AFM PUBLICATION NO. CSP-700-1V UPDATED TO REV 42.
11-AUG-2022		DAYs		15-JAN-2025			
		HRS/MSC	-				
		AFL					
FAA 2023-03-06	NAVIGATION - AIRPLANE FLIGHT MANUAL (AFM) LIMITATIONS AND MASTER MINIMUM EQUIPMENT LIST (MMEL) ITEM PROHIBITION IN THE PRESENCE OF 5G C-BAND WIRELESS BROADBAND INTERFERENCE					MANDATORY	COMPLIED WITH - FAA AD 2023-03-06 C/W - BY INSERTING AD FIGURE 1 AND FIGURE 2 INTO GL6000 AFM REV 45.
13-MAR-2023		MOS		10-APR-2023			
		HRS/MSC	-				
		AFL					
FAA 2023-03-06 PARA (G)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM TO INCLUDE THE INFORMATION SPECIFIED IN FIGURE 1 TO PARA (G)					MANDATORY	COMPLIED WITH - FAA AD 2023-03-06 C/W - BY INSERTING AD FIGURE 1 INTO GL6000 AFM REV 45.
13-MAR-2023		DAYs		10-APR-2023			
		HRS/MSC	-				
		AFL					
FAA 2023-03-06 PARA (H)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM TO INCLUDE THE INFORMATION SPECIFIED IN FIGURE 2 TO PARA (H) OF THIS AD					MANDATORY	COMPLIED WITH - FAA AD 2023-03-06 C/W - BY INSERTING AD FIGURE 2 INTO GL6000 AFM REV 45.
13-MAR-2023		DAYs		10-APR-2023			
		HRS/MSC	-				
		AFL					
FAA 2023-13-15	MINIMUM EQUIPMENT LIST (MEL) ITEM PROHIBITION IN THE PRESENCE OF 5G C-BAND WIRELESS BROADBAND INTERFERENCE					MANDATORY	COMPLIED WITH - PARA (H) - FOR NON-RADIO ALTIMETER TOLERANT AIRPLANES, BEFORE FURTHER FLIGHT, REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM TO INCLUDE THE INFORMATION SPECIFIED IN FIGURE 3 TO PARAGRAPH (H) OF THIS AD. PARA(I) - FOR RADIO ALTIMETER TOLERANT AIRPLANES, BEFORE FURTHER FLIGHT, REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM TO INCLUDE THE INFORMATION SPECIFIED IN FIGURE 4 TO PARAGRAPH (I) OF THIS AD.
39-22500		MOS		26-JUL-2023			
27-JUL-2023		HRS/MSC	-				
		AFL					
TCCA CF-2020-50	NAVIGATION - FLIGHT INSTRUMENTS - UNRELIABLE AIR DATA IN THE COCKPIT					MANDATORY	COMPLIED WITH - COMPLETE B-96999 REV 33 AFM UPDATE, INCLUDE SUPPLEMENT 20. CURRENT AFM REVISION IS 36 (B-96999). THIS AD IS APPLICABLE TO OPERATION AT AIRCRAFT ELEVATION ABOVE 10,000 FT.
04-DEC-2020		DAYs		11-DEC-2020			
		HRS/MSC	-				
		AFL					
TCCA CF-2022-60	NAVIGATION - AIRPLANE FLIGHT MANUAL (AFM) LIMITATIONS AND MASTER MINIMUM EQUIPMENT LIST (MMEL) ITEM PROHIBITION IN THE PRESENCE OF 5G C-BAND WIRELESS BROADBAND INTERFERENCE					MANDATORY	COMPLIED WITH
18-NOV-2022		DAYs		25-NOV-2022			
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2023-44	MINIMUM EQUIPMENT LIST (MEL) ITEM PROHIBITION IN THE PRESENCE OF 5G C-BAND WIRELESS BROADBAND INTERFERENCE					MANDATORY	COMPLIED WITH
30-JUN-2023		MOS HRS/MSC - AFL		13-JUL-2023			
TCCA CF-2023-44 PART I	IT IS PROHIBITED TO DISPATCH OR RELEASE INTO OR OUT OF AIRPORTS IN THE U.S. AIRSPACE IN THE PRESENCE OF 5G C-BAND WIRELESS BROADBAND INTERFERENCE AS IDENTIFIED BY NOTAM					MANDATORY	COMPLIED WITH
30-JUN-2023		DAYS HRS/MSC - AFL		13-JUL-2023			
TCCA CF-2023-44 PART II	IT IS PROHIBITED TO DISPATCH OR RELEASE INTO OR OUT OF AIRPORTS IN THE CONTIGUOUS U.S. AIRSPACE UNDER THE APPLICABLE MEL					MANDATORY	COMPLIED WITH
30-JUN-2023		MOS HRS/MSC - AFL		13-JUL-2023			
CHAPTER 35 OXYGEN							
FAA 2012-03-05	DEFORMATION AT THE NECK OF THE PRESSURE REGULATOR BODY ON CERTAIN OXYGEN CYLINDER AND REGULATOR ASSEMBLIES (CRA)					MANDATORY	NOT APPLICABLE - BY COMPONENT SERIAL NUMBER
23-MAR-2012		MOS HRS/MSC - AFL		18-DEC-2014 0 0			
FAA 2012-03-05 PARA (G)	INSPECTION DEFORMATION AT THE NECK OF THE PRESSURE REGULATOR BODY ON CERTAIN OXYGEN CYLINDER AND REGULATOR ASSEMBLIES (CRA) OF OXYGEN PRESSURE REGULATORS					MANDATORY	NOT APPLICABLE - BY COMPONENT SERIAL NUMBER
23-MAR-2012		MOS HRS/MSC - AFL		18-DEC-2014 0 0			
FAA 2012-03-05 PARA (G)(1)	REPLACE DEFORMATION AT THE NECK OF THE PRESSURE REGULATOR BODY ON CERTAIN OXYGEN CYLINDER AND REGULATOR ASSEMBLIES (CRA) THE AFFECTED OXYGEN CRA					MANDATORY	NOT APPLICABLE - BY COMPONENT SERIAL NUMBER
23-MAR-2012		MOS HRS/MSC - AFL		18-DEC-2014 0 0			
FAA 2016-15-06	OXYGEN - REPLACEMENT OF FLEXIBLE RELIEF HOSES FOR THE CREW OXYGEN BOTTLES WITH NEW METAL DESIGN RELIEF HOSES					MANDATORY	COMPLIED WITH - PCW SB 700-35-6001 REV 01 ON 09-09-2015
08-SEP-2016		MOS HRS/MSC - (s) AFL		09-MAR-2020			
FAA 2016-15-06 PARA (G)	INCORPORATE BOMBARDIER MODSUM R700T400542 BY REPLACING THE OXYGEN FLEXIBLE RELIEF HOSES FOR THE CREW OXYGEN BOTTLES WITH NEW METAL DESIGN HOSES					MANDATORY	COMPLIED WITH - PCW SB 700-35-6001 REV 01 ON 09-09-2015
08-SEP-2016		MOS HRS/MSC - AFL		09-MAR-2020			
FAA 2020-02-15	OXYGEN SYSTEM - INSUFFICIENT ACCESSIBILITY TO THE PORTABLE OXYGEN BOTTLE					MANDATORY	NOT APPLICABLE - DUE TO THE AIRCRAFT SERIAL NUMBER
12-MAR-2020		MOS HRS/MSC - AFL		26-FEB-2020			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2022-12-01	OXYGEN - SUPPLY SYSTEM FLEXIBLE OXYGEN HOSE - INSPECTION AND REPLACEMENT					MANDATORY	COMPLIED WITH - C/W BY THE ACCOMPLISHMENT OF SB 700-35-6005 R01 ON 12-NOV-2021
19-JUL-2022	MOS HRS/MSC - AFL			15-JAN-2025			
FAA 2022-12-01 PARA (G)	DO AN INSPECTION OF THE OXYGEN HOSE ASSEMBLY TO DETERMINE IF ANY HOSE HAVING A PART NUMBER (P/N) IN THE 02C20T1 SERIES IS INSTALLED; IF P/N 02C20T1 SERIES INSTALLED OR ANY TEST FAILS, BEFORE FURTHER FLIGHT, REPLACE ALL THE OXYGEN HOSES					MANDATORY	COMPLIED WITH - C/W BY THE ACCOMPLISHMENT OF SB 700-35-6005 R01 ON 12-NOV-2021
19-JUL-2022	MOS HRS/MSC - AFL			15-JAN-2025			
FAA 2022-12-01 PARA (H)(1)	PERFORM OXYGEN SYSTEM TEST; REPLACE ALL P/N 02C20T1 SERIES HOSES BEFORE FURTHER FLIGHT AFTER ANY HOSE FAILS ANY TEST (OPTIONAL INTERIM TESTING FOR CERTAIN AIRCRAFT)					MANDATORY	NOT APPLICABLE - N/A - NO 02C20T1 SERIES HOSES INSTALLED.
19-JUL-2022	MOS HRS/MSC - (s) AFL			15-JAN-2025			
FAA 2022-12-01 PARA (H)(3)	REPLACE ALL P/N 02C20T1 HOSES (OPTIONAL INTERIM TESTING FOR CERTAIN AIRPLANES)					MANDATORY	NOT APPLICABLE - N/A - NO 02C20T1 SERIES HOSES INSTALLED.
19-JUL-2022	MOS HRS/MSC - (s) AFL			15-JAN-2025			
FAA 2022-14-07	OXYGEN - PASSENGER OXYGEN BOXES NON-CONFORMITY					MANDATORY	NOT APPLICABLE - N/A BY A/C S/N
19-AUG-2022	MOS HRS/MSC - AFL			15-JAN-2025			
FAA 2023-13-11	OXYGEN - OXYGEN VALVE ASSEMBLIES / OXYGEN CYLINDER AND VALVE ASSEMBLIES - INSPECTION/REPLACEMENT					MANDATORY	NOT APPLICABLE - ARE NOT AFFECTED BY THIS AD DUE TO INSTALLED OXYGEN CYLINDER AND REGULATOR ASSEMBLY P/N NOT LISTED IN AD PARA.(C) APPLICABILITY.
39-22496	MOS HRS/MSC - AFL			02-AUG-2023			
FAA 2023-13-11 PARA (H)	INSPECT THE OXYGEN VALVE ASSEMBLIES AND OXYGEN CYLINDER AND VALVE ASSEMBLIES					MANDATORY	NOT APPLICABLE - ARE NOT AFFECTED BY THIS AD DUE TO INSTALLED OXYGEN CYLINDER AND REGULATOR ASSEMBLY P/N NOT LISTED IN AD PARA.(C) APPLICABILITY.
39-22496 05-SEP-2023	DAYs HRS/MSC - AFL			02-AUG-2023			
FAA 2023-13-11 PARA (J)	REPORT THE RESULTS OF THE INSPECTION AND RETURN PARTS (AS REQUIRED)					MANDATORY	NOT APPLICABLE - ARE NOT AFFECTED BY THIS AD DUE TO INSTALLED OXYGEN CYLINDER AND REGULATOR ASSEMBLY P/N NOT LISTED IN AD PARA.(C) APPLICABILITY.
39-22496 05-SEP-2023	DAYs HRS/MSC - AFL			02-AUG-2023			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2011-10	OXYGEN SUPPLY SYSTEM – DEFORMATION OF THE PRESSURE REGULATOR ON THE OXYGEN CYLINDER AND REGULATOR ASSEMBLY						NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
26-MAY-2011		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
TCCA CF-2015-25	OXYGEN - OXYGEN SYSTEM FLEXIBLE HOSE - INCORRECT BURST PRESSURE					MANDATORY	COMPLIED WITH
10-SEP-2015		MOS		11-DEC-2015			
		HRS/MSC	-	0			
		AFL		0			
TCCA CF-2015-25 PART I	INCORPORATE MODSUM R700T400542 TO REPLACE THE CREW OXYGEN FLEXIBLE RELIEF HOSES (MODIFICATION)					MANDATORY	COMPLIED WITH - COMPLIED WITH BY INCORPORATION OF SERVICE BULLETIN 700-35-6001 REVISION 01, REFERENCE LOG ENTRY DATED SEPTEMBER 9, 2015.
10-SEP-2015		MOS		09-SEP-2015			
		HRS/MSC	-	0			
		AFL		0			
TCCA CF-2015-25 PART II	AS OF THE EFFECTIVE DATE OF THIS AD, IT IS PROHIBITED FOR ANYONE TO INSTALL OXYGEN HOSES IN THE LOW PRESSURE/HIGH PRESSURE DISCHARGE SYSTEM WITH PART NUMBERS LISTED IN THE "USED PART NO." COLUMN OF SECTION 3.A, KIT, OF THE APPLICABLE ABOVE-MENTIONED SBS					MANDATORY	COMPLIED WITH - COMPLIED WITH BY INCORPORATION OF SERVICE BULLETIN 700-35-6001 REVISION 01, REFERENCE LOG ENTRY DATED SEPTEMBER 9, 2015.
10-SEP-2015		MOS		09-SEP-2015			
		HRS/MSC	-	0			
		AFL		0			
TCCA CF-2019-18	OXYGEN SYSTEM - INSUFFICIENT ACCESSIBILITY TO THE PORTABLE OXYGEN BOTTLE - INSPECTION					MANDATORY	NOT APPLICABLE - BY THIS AD DUE TO THE AIRCRAFT SERIAL NUMBER
24-MAY-2019		MOS		14-MAY-2019			
		HRS/MSC	-				
		AFL					
TCCA CF-2021-17 R01	OXYGEN - SUPPLY SYSTEM FLEXIBLE OXYGEN HOSE - INSPECTION AND REPLACEMENT					MANDATORY	COMPLIED WITH - WORK DONE PART NUMBER NOT EFFECT
02-AUG-2021		MOS		12-NOV-2021			
		HRS/MSC	- (s)	1424:13			
		AFL		529			
TCCA CF-2021-17 R01 PART IA	COMPLETE THE INSPECTION OF THE HOSE ASSEMBLY INSTALLATIONS					MANDATORY	COMPLIED WITH - WORK DONE PART NUMBER NOT EFFECT
02-AUG-2021		MOS		12-NOV-2021			
		HRS/MSC	-	1424:13			
		AFL		529			
TCCA CF-2021-17 R01 PART IB	REMOVE AND REPLACE THE O2C20T1 SERIES HOSES (IF O2C20T1 SERIES OF HOSES ARE FOUND, REPLACEMENT OF THE HOSES IS REQUIRED) AND PERFORM INTERIM OXYGEN SYSTEM TESTING FOR HOSES THAT ARE NOT IMMEDIATELY REPLACED, AS SPECIFIED IN THE APPLICABLE SB					MANDATORY	NOT APPLICABLE
02-AUG-2021		MOS		12-NOV-2021			
		HRS/MSC	- (s)	1424:13			
		AFL		529			
TCCA CF-2025-02	THERAPEUTIC OXYGEN HOSES – INADEQUATE CLEARANCE FROM ELECTRICAL HARNESS					MANDATORY	NOT APPLICABLE - N/A BY AIRCRAFT S/N
28-JAN-2025		MOS		17-JAN-2025			
		HRS/MSC	-				
		AFL					

CHAPTER 36 PNEUMATIC

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2020-12-15 PARA (G)	MEASUREMENT OF THE TRUNNION NUT TORQUE OF THE V-BAND CLAMPS					MANDATORY	NOT APPLICABLE - N/A BY A/C S/N
24-JUL-2020		MOS HRS/MSC - (s) AFL		15-JAN-2025			
FAA 2020-12-15 PARA (H)(1)	DO A GENERAL VISUAL INSPECTION FOR CRACKING AND DEFORMATION, FOR SAFETY VALVES WITH A V-BAND CLAMP TRUNNION NUT TORQUE OF LESS THAN 80 LBF-IN; AND PERFORM CORRECTIVE ACTIONS					MANDATORY	NOT APPLICABLE - N/A BY A/C S/N
24-JUL-2020		MOS HRS/MSC - (s) AFL		15-JAN-2025			
FAA 2020-12-15 PARA (H)(2)	DO A MAGNIFICATION INSPECTION FOR ANY CRACKING AND DEFORMATION OF THE SAFETY VALVE AND AIRPLANE BULKHEAD FLANGE AREA, FOR SAFETY VALVES WITH A V-BAND CLAMP TRUNNION NUT TORQUE OF 80 LBF-IN OR HIGHER; PERFORM CORRECTIVE ACTIONS					MANDATORY	NOT APPLICABLE - N/A BY A/C S/N
24-JUL-2020		MOS HRS/MSC - (s) AFL		15-JAN-2025			
FAA 2024-03-08 PARA (H)	EXAMINE THE AIRPLANE MAINTENANCE RECORDS TO VERIFY WHETHER ANY Affected PART HAS BEEN INSTALLED SINCE THE AIRPLANE DATE OF MANUFACTURE					MANDATORY	NOT APPLICABLE - BY A/C S/N
39-22678 03-MAY-2024		DAYs HRS/MSC - AFL		01-APR-2024			
FAA 2024-03-08 PARA (I)	REVISE THE OPERATOR'S EXISTING MEL BY INCORPORATING THE INFORMATION SPECIFIED IN FIGURES 2 THROUGH 8 TO PARAGRAPH (I) OF THIS AD, AS APPLICABLE					MANDATORY	COMPLIED WITH - SVC MEL ALREADY REVISED BY INCORPORATING THE INFORMATION SPECIFIED IN FIGURES 2 THROUGH 8 TO PARAGRAPH (I) OF THIS AD PER TCCA AD CF-2023-17
39-22678 03-MAY-2024		DAYs HRS/MSC - AFL		01-APR-2024			
FAA 2024-03-08 PARA (J)	TEST THE OVERHEAT DETECTION SENSING ELEMENTS TO DETERMINE IF THEY ARE SERVICEABLE					MANDATORY	- OPEN
39-22678 03-MAY-2024		MOS 120 HRS/MSC 2000 AFL		03-MAY-2034 M 4142:15 M			
FAA FAA 2020-12-15	PNEUMATIC - CABIN-PRESSURE CONTROL SYSTEM - MODIFICATION/INSPECTION					MANDATORY	NOT APPLICABLE - N/A BY A/C S/N
		MOS HRS/MSC - (s) AFL		15-JAN-2025			
TCCA CF-2020-16	PNEUMATICS - CABIN PRESSURE CONTROL SYSTEM - SAFETY VALVE - OVERTORQUE					MANDATORY	NOT APPLICABLE - NOT Affected BY THIS AD
29-MAY-2020		MOS HRS/MSC - (s) AFL		21-MAY-2020			
TCCA CF-2020-16 PARA A	INSPECT THE V-BAND CLAMP TRUNNION NUT TORQUE ON BOTH CABIN PRESSURE CONTROL SYSTEM SAFETY VALVES (P/N GG435-3006-3)					MANDATORY	NOT APPLICABLE - NOT Affected BY THIS AD
29-MAY-2020		MOS HRS/MSC - AFL		21-MAY-2020			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2020-16 PARA B	PERFORM A VISUAL INSPECTION AND COMPLETE THE REMAINDER / REPLACE THE SAFETY VALVE (FOR SAFETY VALVES WITH A V-BAND CLAMP TRUNNION NUT TORQUE OF LESS THAN 80 LBF-IN)					MANDATORY	NOT APPLICABLE - NOT AFFECTED BY THIS AD
29-MAY-2020	MOS HRS/MSC - (s) AFL			21-MAY-2020			
TCCA CF-2020-16 PARA C	PERFORM A MAGNIFICATION INSPECTION AND COMPLETE THE REMAINDER / REPLACE THE SAFETY VALVE (FOR SAFETY VALVES WITH A V-BAND CLAMP TRUNNION NUT TORQUE OF 80 LBF-IN OR HIGHER)					MANDATORY	NOT APPLICABLE - NOT AFFECTED BY THIS AD
29-MAY-2020	MOS HRS/MSC - (s) AFL			21-MAY-2020			
TCCA CF-2022-38 R01	PNEUMATIC - NON-CONFORMING BLEED LEAK DETECTION SYSTEM SENSING ELEMENTS					MANDATORY	COMPLIED WITH - EATC TEMPORARILY REVISED B-96999 MEL R02-TR04 WHICH WAS APPROVED BY TAIWAN CAA ON 16/AUG/2022.
24-AUG-2022	MOS HRS/MSC - AFL			02-SEP-2022 1572:10 576			
TCCA CF-2023-17 PART III	MMEL OPERATIONAL RESTRICTIONS					MANDATORY	COMPLIED WITH
22-MAR-2023	DAYs HRS/MSC - AFL			27-APR-2023			
TCCA CF-2023-17 PART IV	TESTING AND REPLACEMENT OF Affected OVERHEAT DETECTION SENSING ELEMENTS					MANDATORY	
22-MAR-2023	MOS 120 HRS/MSC 2000 AFL			(EFF) 22-MAR-2033 3820:05			
CHAPTER 46 INFORMATION SYSTEMS							
TCCA CF-2015-19	INFORMATION SYSTEMS - POTENTIAL MISLEADING NAVIGATIONAL INFORMATION					MANDATORY	COMPLIED WITH - BY THE INCORPORATION OF SERVICE BULLETIN 700-46-6005 REVISION 2,
20-JUL-2015	MOS HRS/MSC - AFL			09-SEP-2015			
TCCA CF-2021-35	INFORMATION SYSTEMS - INCORRECT AIRPLANE FLIGHT MANUAL (AFM) WET AND CONTAMINATED RUNWAY STOPPING DISTANCE					MANDATORY	COMPLIED WITH - COMPLIED WITH TCCA AD CF-2021-35 PER EO NO. BD700-46-21028 R0 BY FLIGHT OPERATION DIVISION CHRIS HUANG
09-NOV-2021	DAYs HRS/MSC - AFL			04-NOV-2021			
TCCA CF-2022-49	INFORMATION SYSTEMS - INCORRECT AIRPLANE FLIGHT MANUAL (AFM) WET AND CONTAMINATED RUNWAY STOPPING DISTANCE					MANDATORY	COMPLIED WITH - EATC ACCOMPLISHED AFM REVISION 42 AND 43 WHICH WERE ACCEPTED BY TAIWAN CAA ON 19/AUG/2022.
06-SEP-2022	DAYs HRS/MSC - AFL			02-SEP-2022 1572:10 576			
CHAPTER 52 DOORS							
FAA 2016-01-12	DOORS - MODIFY THE AFT EQUIPMENT BAY					MANDATORY	NOT APPLICABLE - BY AC SN NUMBER
25-FEB-2016	MOS HRS/MSC - AFL			12-FEB-2018 575:12 214			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2016-15-03	DOORS - INCORPORATE THE NEW CONFIGURATION TO THE PASSENGER DOOR EXTERNAL HANDLE DETENT					MANDATORY	NOT APPLICABLE - N/A BY A/C S/N
31-AUG-2016	MOS HRS/MSC - AFL			15-JAN-2025			
FAA 2016-17-16	DOORS - REVISING THE MAINTENANCE OR INSPECTION PROGRAM TO INCORPORATE CERTAIN TEMPORARY REVISIONS, AND REPLACING THE PASSENGER DOOR TENSATOR SPRINGS WITH NEW SPRINGS					MANDATORY	COMPLIED WITH
05-OCT-2016	MOS HRS/MSC - (s) AFL			03-NOV-2016			
FAA 2016-17-16 PARA (G)	REVISE THE MAINTENANCE OR INSPECTION PROGRAM AS APPLICABLE					MANDATORY	COMPLIED WITH
05-OCT-2016	DAYS HRS/MSC - AFL			03-NOV-2016			
FAA 2016-17-16 PARA (I)	REPLACE THE PASSENGER DOOR TENSATOR SPRINGS HAVING PART NUMBER (P/N) GS321-0580-1, WITH NEW SPRINGS					MANDATORY	NOT APPLICABLE
05-OCT-2016	MOS HRS/MSC - AFL			03-NOV-2016			
FAA 2022-25-13	DOORS - MAINTENANCE OR INSPECTION PROGRAM TASK RESTRICTIONS					MANDATORY	COMPLIED WITH - C/W BY AMM REVISION 44 DATED AUG16/2022 OR LATER REVISIONS USED.
13-JAN-2023	DAYS HRS/MSC - AFL			15-JAN-2025			
FAA 2024-07-09	PASSENGER DOOR - REVISE THE EXISTING MAINTENANCE OR INSPECTION PROGRAM, AS APPLICABLE					MANDATORY	COMPLIED WITH - C/W - TLMC ITEM 52-11-00-201 WITH AMM TASK 52-11-00-720-801 ALREADY INCORPORATED INTO G6000 AMP R01 (DATED 15 FEB 2023).
39-22730 17-JUN-2024	DAYS HRS/MSC - AFL			15-JAN-2025			
TCCA CF-2010-14	PASSENGER DOOR - TENSATOR SPRINGS FAILURE (SUPERSEDED BY TCCA AD CF-2014-39)					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
	MOS HRS/MSC - AFL			18-DEC-2014 0 0			
TCCA CF-2014-25	DOORS - FUEL INGRESS INTO AFT EQUIPMENT BAY					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
21-AUG-2014	MOS HRS/MSC - AFL			18-DEC-2014 0 0			
TCCA CF-2014-39 PART I	AMEND THE TRANSPORT CANADA APPROVED MAINTENANCE SCHEDULE BY REVISING THE REPETITIVE DISCARD TASK, TASK NUMBER 52-11-41-101					MANDATORY	COMPLIED WITH - AT MANUFACTURE
18-NOV-2014	MOS HRS/MSC - AFL			18-DEC-2014 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2014-39 PART II	REPLACE THE PASSENGER DOOR TENSATOR SPRINGS, P/N GS321-0580-1					MANDATORY	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER.
18-NOV-2014		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
TCCA CF-2015-03	DOORS - PASSENGER DOOR EXTERNAL HANDLE DETENT SEIZURE					MANDATORY	NOT APPLICABLE - DUE TO THE SERIAL NUMBER OF THE AIRCRAFT.
26-MAR-2015		MOS		09-SEP-2015			
		HRS/MSC	-				
		AFL					
TCCA CF-2021-41	DOORS - PASSENGER DOOR - RAPID OPENING					MANDATORY	COMPLIED WITH - C/W THIS AD BY ADDRESSED TO MAINTENANCE PERSONNEL THROUGH EMAIL
08-DEC-2021		DAYS		01-DEC-2021			
		HRS/MSC	-				
		AFL					
TCCA CF-2023-25	DOORS - PASSENGER DOOR - DETENT MECHANISM AIRCRAFT MAINTENANCE MANUAL (AMM) PROCEDURE					MANDATORY	COMPLIED WITH - 8-96999 C/W AD REQUIREMENT - SVC WILL USE AMM TASK 52-11-00-720-801, DATED 16 AUGUST 2022, OR LATER REVISIONS WHEN PERFORMING TLMC ITEM 52-11-00-201 AS THE EFFECTIVE DATE (27-APR-2023) OF THIS AD.
27-APR-2023		DAYS		20-APR-2023			
		HRS/MSC	-				
		AFL					
CHAPTER 53 FUSELAGE							
FAA 2018-21-03	FUSELAGE - REPLACEMENT OF ATTACHMENTS FOR BELLY FAIRING ACCESS PANELS					MANDATORY	COMPLIED WITH - 700-53-6008 REV 01 ACCOMPLISHMENT
19-NOV-2018		MOS		23-SEP-2017			
		HRS/MSC	-	485:04			
		AFL		176			
FAA 2018-25-07	FUSELAGE - BELLY FAIRING - BLOCKED DRAINAGE HOLES					MANDATORY	COMPLIED WITH
15-JAN-2019		MOS		16-JUL-2018			
		HRS/MSC	-	673:02			
		AFL		243			
FAA 2020-05-27	AFT FUSELAGE - RUDDER QUADRANT SUPPORT CHANNEL CRACKING					MANDATORY	COMPLIED WITH - C/W BY THE ACCOMPLISHMENT OF SB 700-53-6010 BASIC ON 22-AUG-2019 PER BASS WO# 223594.
07-MAY-2020		MOS		15-JAN-2025			
		HRS/MSC	- (s)				
		AFL					
FAA 2020-05-27 PARA (G)	DETAILED VISUAL INSPECTION FOR CRACKING OF THE RUDDER QUADRANT BOX ASSEMBLY (FOR AIRPLANES THAT HAVE ACCUMULATED FEWER THAN 2,900 TOTAL FC AS OF THE EFFECTIVE DATE OF THIS AD, AND THAT HAVE NOT BEEN MODIFIED AS SPECIFIED IN PARA (I))						NOT APPLICABLE - N/A - BY POST SB 700-53-6010 (HAVE BEEN MODIFIED AS SPECIFIED IN PARA (1) OF THIS AD).
07-MAY-2020		MOS		15-JAN-2025			
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2020-05-27 PARA (H)	ACCOMPLISH THE ACTIONS SPECIFIED IN PARA (I) (IF ANY CRACKING IS FOUND DURING ANY INSPECTION SPECIFIED IN PARA (G))			MANDATORY			NOT APPLICABLE - N/A - BY POST SB 700-53-6010 (HAVE BEEN MODIFIED AS SPECIFIED IN PARA (1) OF THIS AD).
07-MAY-2020		MOS HRS/MSC - (s) AFL		15-JAN-2025			
FAA 2020-05-27 PARA (I)	MODIFY THE RUDDER QUADRANT BOX ASSEMBLY					MANDATORY	COMPLIED WITH - C/W BY THE ACCOMPLISHMENT OF SB 700-53-6010 BASIC ON 22-AUG-2019 PER BASS WO# 223594.
07-MAY-2020		MOS HRS/MSC - AFL		15-JAN-2025			
FAA 2020-05-27 PARA (K)	ACCOMPLISHING THE ACTIONS IN PARA (I) OR (J) OF THIS AD TERMINATES ALL OF THE REQUIREMENTS IN PARA (G)			MANDATORY			COMPLIED WITH
07-MAY-2020		MOS HRS/MSC - (s) AFL		15-JAN-2025			
TCCA CF-2017-31	FUSELAGE - REPLACEMENT OF ATTACHMENTS FOR BELLY FAIRING ACCESS PANELS					MANDATORY	COMPLIED WITH - COMPLIED WITH VIA SB 700-53-6008 REV 1
06-OCT-2017		MOS HRS/MSC - AFL		23-SEP-2017 485:04 176			
TCCA CF-2018-14	FUSELAGE - BELLY FAIRING - BLOCKED DRAINAGE HOLES					MANDATORY	COMPLIED WITH - CW SB 700-53-6009
15-MAY-2018		MOS HRS/MSC - AFL		16-JUL-2018 673:02 243			
TCCA CF-2019-11	AFT FUSELAGE - RUDDER QUADRANT SUPPORT CHANNEL CRACKING					MANDATORY	COMPLIED WITH
		MOS HRS/MSC - (s) AFL		22-AUG-2019 1064:58 367			
TCCA CF-2019-11 PART I	INSPECT THE RUDDER QUADRANT BOX ASSEMBLY (FOR AEROPLANES THAT HAVE ACCUMULATED LESS THAN 2900 TOTAL FC AS OF THE EFFECTIVE DATE OF THIS AD AND DO NOT MEET THE REQUIREMENTS OF PART II OF THIS AD)						NOT APPLICABLE
05-APR-2019		MOS HRS/MSC - AFL		22-AUG-2019 1064:58 367			
TCCA CF-2019-11 PART II	PERFORM THE INSPECTIONS, PART REPLACEMENTS AND REINFORCEMENTS OF THE RUDDER QUADRANT BOX ASSEMBLY					MANDATORY	COMPLIED WITH
05-APR-2019		MOS HRS/MSC - AFL		22-AUG-2019 1064:58 367			
CHAPTER 57 WINGS							
FAA 2024-02-05	NONDESTRUCTIVE TEST (NDT) PROCEDURE INSPECTION PROGRAM REVISION					MANDATORY	COMPLIED WITH - C/W - DUE TO THE PROCEDURE ET-57-51-009 OF THE NDTM REV.34 (DATED AUG 16/2022) IS USED WHEN PERFORMING AWL TASK 57-51-00-109 AS OF THE EFFECTIVE DATE (09-APR-2024) OF AD.
39-22669 09-APR-2024		DAYs HRS/MSC - AFL		15-JAN-2025			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2024-23-08	WINGS - INSPECTIONS FOR CRACKS OF THE ATTACHING ANGLES OF THE INBOARD FLAP SEAL PLATES AND REPLACEMENT					MANDATORY	NOT APPLICABLE - N/A BY A/C S/N
39-22887 06-JAN-2025		MOS HRS/MSC - AFL		15-JAN-2025			
FAA 2024-23-08 PARA (G) & (H)	DETAILED INSPECTION AND CORRECTIVE ACTIONS FOR INBOARD FLAP SEAL PLATES					MANDATORY	NOT APPLICABLE - N/A BY A/C S/N
39-22887 06-JAN-2025		MOS HRS/MSC - AFL		15-JAN-2025			
FAA 2024-23-08 PARA (I) & (J)	REPLACEMENT OF INBOARD FLAP SEAL PLATES AND REPAIR FOR FLAP INBOARD CLOSING RIBS AND TRAILING EDGES					MANDATORY	NOT APPLICABLE - N/A BY A/C S/N
39-22887 06-JAN-2025		MOS HRS/MSC - AFL		15-JAN-2025			
TCCA CF-2022-40	WINGS - REVISED NON-DESTRUCTIVE TESTING MANUAL PROCEDURE FOR AIRWORTHINESS LIMITATION TASK NUMBER 57-51-00-109					MANDATORY	COMPLIED WITH - ALWAYS USE BOMBARDIER ON-LINE MANUALS OF LATEST REVISION.
04-AUG-2022		MOS HRS/MSC - AFL		02-SEP-2022 1572:10 576			
TCCA CF-2023-42	WINGS - INBOARD FLAP SEAL PLATE LOST OR DAMAGED					MANDATORY	NOT APPLICABLE - NOT AFFECTED BY AIRCRAFT S/N
03-JUL-2023		MOS HRS/MSC - AFL		26-JUN-2023			
TCCA CF-2023-42 PARA A	PERFORM A DETAILED INSPECTION (DET) OF THE LHS AND RHS FLAP INNER SEAL PLATE ASSEMBLIES ATTACHING ANGLES FOR CRACKS					MANDATORY	NOT APPLICABLE - NOT AFFECTED BY AIRCRAFT S/N
03-JUL-2023		MOS HRS/MSC - AFL		26-JUN-2023			
TCCA CF-2023-42 PARA D	REPLACE THE INBOARD FLAP SEAL PLATE ASSEMBLIES WITH THE REDESIGNED ASSEMBLIES AND INSPECT FLAP INBOARD CLOSING RIBS AND TRAILING EDGES FOR DAMAGE					MANDATORY	NOT APPLICABLE - NOT AFFECTED BY AIRCRAFT S/N
03-JUL-2023		MOS HRS/MSC - AFL		26-JUN-2023			
CHAPTER 71 POWER PLANT							
FAA 2021-21-04	REDISTRIBUTION OF LOAD/STRESS ON THE MOUNT COMPONENTS					MANDATORY	COMPLIED WITH - C/W BY THE ACCOMPLISHMENT OF SB 700-71-6005 BASIC ON 17-APR-2022 PER BASS WO# 247911.
08-DEC-2021		MOS HRS/MSC - AFL		15-JAN-2025			
TCCA CF-2021-04	POWERPLANT - ENGINE MOUNT - BUSHING MISSING					MANDATORY	COMPLIED WITH
01-MAR-2021		MOS HRS/MSC - AFL		17-APR-2022 1468:03 546			
CHAPTER 72 ENGINE							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2016-25-18	ENGINE - INSPECTION FOR DISCREPANCIES OF THE ENGINE REAR MOUNT ASSEMBLIES AND REPLACE MISSING PARTS IF ANY DISCREPANCY IS DETECTED (INCLUDING MISSING OR BROKEN BOLTS, MISSING NUTS, INCORRECT TORQUE VALUES, AND AN INCORRECT GAP BETWEEN THE BUSHING AND WASHER) (SUPERSEDED BY FAA AD 2018-09-15)					MANDATORY	COMPLIED WITH
03-JAN-2017		MOS		28-JUN-2016			
		HRS/MSC	-		166:12		
		AFL			58		
FAA 2018-09-15	ENGINE - REAR MOUNT RETAINING BOLT FAILURE					MANDATORY	COMPLIED WITH
15-JUN-2018		MOS		19-SEP-2019			
		HRS/MSC	-				
		AFL					
FAA 2018-09-15 PARA (G)	INSPECTION FOR DISCREPANCIES OF THE ENGINE REAR MOUNT ASSEMBLIES (INCLUDING MISSING OR BROKEN BOLTS, MISSING NUTS, INCORRECT TORQUE VALUES, AND AN INCORRECT GAP BETWEEN THE BUSHING AND WASHER) AND REPLACE MISSING PARTS AND CORRECT NONCOMPLIANT GAPS AND BOLT TORQUE (IF ANY DISCREPANCY IS DETECTED DURING THE INSPECTION REQUIRED BY PARA (G)) (THIS PARA RESTATES THE REQUIREMENTS OF PARA (G) OF AD 2016-25-18, WITH NO CHANGES)					MANDATORY	COMPLIED WITH - CW SB 700-71-6002 BASIC 28-JUN-2016 166.2 FH & 58 FC
15-JUN-2018		MOS		19-SEP-2019			
		HRS/MSC	-				
		AFL					
FAA 2018-09-15 PARA (J)	MEASURE THE GAPS BETWEEN THE APPLICABLE SHOULDERED BUSHING FITTED ON THE MOUNT BEAM AND THE WASHER; AND BETWEEN THE APPLICABLE ENGINE RING LUG AND THE HEAD OF THE MOUNT PIN TO DETERMINE IF THE GAPS ARE WITHIN ACCEPTABLE LIMITS AND REPAIR (IF ANY GAP IS DETECTED, DURING ANY MEASUREMENT REQUIRED BY PARA (J) / (K), THAT IS NOT WITHIN THE APPLICABLE LIMITS SPECIFIED IN THE SERVICE INFORMATION SPECIFIED IN PARAS (J)(1) THRU (J)(4))					MANDATORY	COMPLIED WITH - CW SB 700-71-6003 BASIC 06-JAN-2017 303.28 FH & 120 FC
15-JUN-2018		MOS		19-SEP-2019			
		HRS/MSC	-				
		AFL					
FAA 2018-09-15 PARA (K)	REPLACE THE NUTS HAVING P/N AS54365 AND THE BOLTS HAVING P/N AS54020 AND AS54002 IN THE ENGINE REAR MOUNT ASSEMBLY WITH NEW NUTS AND NEW BOLTS; AND DO THE GAP MEASUREMENT TO DETERMINE IF THE GAP IS WITHIN ACCEPTABLE LIMITS AND REPAIR (IF ANY GAP IS DETECTED, DURING ANY MEASUREMENT REQUIRED BY PARA (J) / (K), THAT IS NOT WITHIN THE APPLICABLE LIMITS SPECIFIED IN THE SERVICE INFORMATION SPECIFIED IN PARAS (J)(1) THRU (J)(4))					MANDATORY	COMPLIED WITH - CW SB 700-71-6003 BASIC 06-JAN-2017 303.28 FH & 120 FC
15-JUN-2018		MOS		19-SEP-2019			
		HRS/MSC	-				
		AFL					
TCCA CF-2016-23	ENGINE - REAR MOUNT RETAINING BOLT FAILURE					MANDATORY	COMPLIED WITH - 700-71-6002
08-AUG-2016		MOS		28-JUN-2016			
		HRS/MSC	-				
		AFL					
TCCA CF-2016-23 R01	ENGINE - REAR MOUNT RETAINING BOLT FAILURE					MANDATORY	COMPLIED WITH - PART I WAS COMPLIANT WITH SB 700-71-6002 BASIC ISSUE ON 28-JUN-2016 / 166:12 FH & 58 CYCLE PART II WAS COMPLIANT WITH SB 700-71-6003 BASIC ISSUE ON 06-JAN-2017 / 1052:24 FH & 452 CYCLE
06-MAR-2017		MOS		01-MAR-2017			
		HRS/MSC	- (s)				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
	TCCA CF-2016-23 R01 PART I INSPECTION OF THE ENGINE REAR MOUNT ASSEMBLIES					MANDATORY	COMPLIED WITH - PART I WAS COMPLIANT WITH SB 700-71-6002 BASIC ISSUE ON 28-JUN-2016 / 166:12 FH & 58 CYCLE
06-MAR-2017		MOS HRS/MSC - AFL		01-MAR-2017			
	TCCA CF-2016-23 R01 PART II INSPECTION AND REPLACEMENT OF THE ENGINE REAR MOUNT ASSEMBLY HARDWARE					MANDATORY	COMPLIED WITH - PART II WAS COMPLIANT WITH SB 700-71-6003 BASIC ISSUE ON 06-JAN-2017 / 1052:24 FH & 452 CYCLE
06-MAR-2017		MOS HRS/MSC - AFL		01-MAR-2017			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - SB - 9673/B-96999							
CHAPTER 11 PLACARDS AND MARKINGS							
SB 700-11-6001	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
09-APR-2012		MOS HRS/MSC - AFL		07-AUG-2015 9:12 4			
SB 700-11-6001 REV 01	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
22-MAR-2013		MOS HRS/MSC - AFL					
SB 700-11-6001 REV 01 PART A	ACCOMPLISH OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN AIRCRAFT OPERATING AT AIRPORTS WITH A 74,955 LB (33,999 KG) MAXIMUM WEIGHT LIMITATION					OPTIONAL	NOT APPLICABLE
22-MAR-2013		MOS HRS/MSC - AFL					
SB 700-11-6001 REV 01 PART B	ACCOMPLISH OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN AIRCRAFT OPERATING AT AIRPORTS WITH A 75,000 LB (34,019 KG) MAXIMUM WEIGHT LIMITATION					OPTIONAL	NOT APPLICABLE
22-MAR-2013		MOS HRS/MSC - AFL					
SB 700-11-6001 REV 02	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - C/W SB R02 AT COMPLETION
26-JAN-2015		MOS HRS/MSC - AFL		08-DEC-2015			
SB 700-11-6001 REV 02 PART A	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN AIRCRAFT OPERATING AT AIRPORTS WITH A 75,000 LB (34,019 KG) MAXIMUM WEIGHT LIMITATION					OPTIONAL	COMPLIED WITH - C/W SB R02 AT COMPLETION
26-JAN-2015		MOS HRS/MSC - AFL		08-DEC-2015			
SB 700-11-6001 REV 02 PART B	OPERATIONS AT AIRPORTS WITH MAXIMUM WEIGHT RESTRICTIONS, SERVICE BULLETIN AIRCRAFT OPERATING AT AIRPORTS WITH A 74,955 LB (33,999 KG) MAXIMUM WEIGHT LIMITATION					OPTIONAL	COMPLIED WITH - C/W SB R02 AT COMPLETION
26-JAN-2015		MOS HRS/MSC - AFL		08-DEC-2015			
SB 700-11-6002	MODIFICATION - FLIGHT COMPARTMENT PLACARDS - INCREASED MAXIMUM TAKE-OFF WEIGHT (MTOW) TO 99,500 LBS (SUPERSEDED BY 700-11-6002 REV 01), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - C/W SB BASIC AT COMPLETION
13-APR-2012		MOS HRS/MSC - AFL		08-DEC-2015			
CHAPTER 21 AIR CONDITIONING							
SB 700-21-6005 REV 01	MODIFICATION - PASSENGER COMPARTMENT AND AIR DISTRIBUTION SYSTEM - MODIFICATION OF AIR GASPERS FOR NOISE REDUCTION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
04-JUN-2020		MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-21-6007	MODIFICATION - PASSENGER COMPARTMENT AND AIR DISTRIBUTION SYSTEM - INSTALLATION OF PLUGS AND INSERTS IN THE RHS/LHS SIDEWALL RECIRCULATION DUCT (SUPERSEDED BY 700-21-6007 REV 01), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
15-SEP-2017		MOS					
		HRS/MSC	-				
		AFL					
SB 700-21-6007 REV 01	MODIFICATION - PASSENGER COMPARTMENT AND AIR DISTRIBUTION SYSTEM - INSTALLATION OF PLUGS AND INSERTS IN THE RHS/LHS SIDEWALL RECIRCULATION DUCT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
13-APR-2018		MOS					
		HRS/MSC	-				
		AFL					
SB 700-21-6007 REV 02	MODIFICATION - PASSENGER COMPARTMENT AND AIR DISTRIBUTION SYSTEM - INSTALLATION OF PLUGS AND INSERTS IN THE RHS/LHS SIDEWALL RECIRCULATION DUCT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
27-JUN-2018		MOS					
		HRS/MSC	-				
		AFL					
SB 700-21-6007 REV 03	MODIFICATION - PASSENGER COMPARTMENT AND AIR DISTRIBUTION SYSTEM - INSTALLATION OF PLUGS AND INSERTS IN THE RHS/LHS SIDEWALL RECIRCULATION DUCT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
08-NOV-2018		MOS					
		HRS/MSC	-				
		AFL					
SB 700-21-6007 REV 04	MODIFICATION - PASSENGER COMPARTMENT AND AIR DISTRIBUTION SYSTEM - INSTALLATION OF PLUGS AND INSERTS IN THE RHS/LHS SIDEWALL RECIRCULATION DUCT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
17-DEC-2018		MOS					
		HRS/MSC	-				
		AFL					
SB 700-21-6008	MODIFICATION - TEMPERATURE CONTROL - REPLACEMENT OF THE AIR-CONDITIONING SYSTEM CONTROLLER (ACSC), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - REPLACE ACSC - 15 (ILLEGIBLE) TEST OK
06-APR-2018		MOS		05-NOV-2018			
		HRS/MSC	-	823:48			
		AFL		286			
SB 700-21-6009	SPECIAL CHECK/MODIFICATION - CABIN-PRESSURE CONTROL SYSTEM - SAFETY VALVE OVERTORQUE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
23-JAN-2020		MOS					
		HRS/MSC	-				
		AFL					
SB 700-21-6009 PART A	ACCOMPLISH, SERVICE BULLETIN INSPECTION / TORQUE CHECK OF LH AND RH SAFETY VALVES					RECOMMENDED	NOT APPLICABLE
23-JAN-2020		MOS					
		HRS/MSC	-				
		AFL					
SB 700-21-6009 PART B	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF LH AND RH SAFETY VALVES					RECOMMENDED	NOT APPLICABLE
23-JAN-2020		MOS					
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-21-6009 REV 01	SPECIAL CHECK/MODIFICATION - CABIN-PRESSURE CONTROL SYSTEM - SAFETY VALVE OVERTORQUE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
19-MAR-2020		MOS HRS/MSC - AFL					
SB 700-21-6009 REV 01	ACCOMPLISH, SERVICE BULLETIN INSPECTION / TORQUE CHECK OF LH AND RH SAFETY VALVES					RECOMMENDED	NOT APPLICABLE
PART A		MOS HRS/MSC - AFL					
19-MAR-2020							
SB 700-21-6009 REV 01	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF LH AND RH SAFETY VALVES					RECOMMENDED	NOT APPLICABLE
PART B		MOS HRS/MSC - (s) AFL					
19-MAR-2020							
SB 700-21-6009 REV 02	SPECIAL CHECK/MODIFICATION - CABIN-PRESSURE CONTROL SYSTEM - SAFETY VALVE OVERTORQUE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
31-MAR-2020		MOS HRS/MSC - AFL					
SB 700-21-6009 REV 02	ACCOMPLISH, SERVICE BULLETIN INSPECTION / TORQUE CHECK OF LH AND RH SAFETY VALVE					RECOMMENDED	NOT APPLICABLE
PART A		MOS HRS/MSC - AFL					
31-MAR-2020							
SB 700-21-6009 REV 02	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF LH AND RH SAFETY VALVES					RECOMMENDED	NOT APPLICABLE
PART B		MOS HRS/MSC - (s) AFL					
31-MAR-2020							
CHAPTER 22 AUTO FLIGHT							
SB 700-22-6001	SPECIAL CHECK/MODIFICATION - AUTOPILOT SYSTEM - AILERON AND ELEVATOR AUTOPILOT SERVO CABLE KEEPER WEAR, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
09-JAN-2013		MOS HRS/MSC - AFL					
SB 700-22-6001 PART A	INSPECTION SPECIAL CHECK/MODIFICATION - AUTOPILOT SYSTEM - AILERON AND ELEVATOR AUTOPILOT SERVO CABLE KEEPER WEAR, SERVICE BULLETIN OF THE CABLE KEEPERS AND MODIFICATION OF THE AILERON SERVO CABLE TENSION					RECOMMENDED	NOT APPLICABLE
09-JAN-2013		MOS HRS/MSC - AFL					
SB 700-22-6001 PART B	INSPECTION SPECIAL CHECK/MODIFICATION - AUTOPILOT SYSTEM - AILERON AND ELEVATOR AUTOPILOT SERVO CABLE KEEPER WEAR, SERVICE BULLETIN OF THE CABLE KEEPERS AND MODIFICATION OF THE ELEVATOR SERVO CABLE TENSION					RECOMMENDED	NOT APPLICABLE
09-JAN-2013		MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-22-6003	SPECIAL CHECK/MODIFICATION - AUTOMATIC FLIGHT-CONTROL SYSTEM - UPGRADE OF REMOTE ELECTRONICS UNIT (REU- 6000) PART NO. 822- 2461- 001, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
30-JUN-2016		MOS					
		HRS/MSC	-				
		AFL					
SB 700-22-6003 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - AUTOMATIC FLIGHT-CONTROL SYSTEM - UPGRADE OF REMOTE ELECTRONICS UNIT (REU- 6000) PART NO. 822- 2461- 001, SERVICE BULLETIN INSPECTION OF THE REU-6000 UNITS					RECOMMENDED	NOT APPLICABLE
30-JUN-2016		MOS					
		HRS/MSC	-				
		AFL					
SB 700-22-6003 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - AUTOMATIC FLIGHT-CONTROL SYSTEM - UPGRADE OF REMOTE ELECTRONICS UNIT (REU- 6000) PART NO. 822- 2461- 001, SERVICE BULLETIN REPLACEMENT OF THE REU-6000 UNIT(S)					RECOMMENDED	NOT APPLICABLE
30-JUN-2016		MOS					
		HRS/MSC	-				
		AFL					
CHAPTER 23 COMMUNICATIONS							
SB 700-23-6001 REV 08	MODIFICATION - AIRBORNE DATA-LINK SYSTEM - INSTALLATION OF A SECOND DATA-LINK SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - N/A
22-NOV-2024		MOS		15-JAN-2025			
		HRS/MSC	-				
		AFL					
SB 700-23-6002 REV 01	MODIFICATION - PRINTER SYSTEM - INSTALLATION OF A FLIGHT COMPARTMENT PRINTER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - C/W SB R01 AT COMPLETION
17-JAN-2013		MOS		12-AUG-2015			
		HRS/MSC	-	9:12			
		AFL		4			
SB 700-23-6002 REV 02	MODIFICATION - PRINTER SYSTEM - INSTALLATION OF A FLIGHT COMPARTMENT PRINTER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - N/R, C/W SB R01
01-JUN-2020		MOS		15-JAN-2025			
		HRS/MSC	-				
		AFL					
SB 700-23-6007	MODIFICATION - RADIO MANAGEMENT SYSTEM - INTRODUCTION OF A NEW RADIO INTERFACE UNIT (RIU) PART NUMBER TO SUPPORT FANS/CPDLC CONNECTION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
17-APR-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 700-23-6009 REV 03	MODIFICATION - AUDIO INTEGRATING SYSTEM - INTRODUCTION OF NEW AUDIO CONTROL PANEL ACP-6000 PART NO. 822-2928-500 (MOD 1) INSTEAD OF ACP-4120 PART NO. 822-1950-503, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
05-MAY-2014		MOS					
		HRS/MSC	-				
		AFL					
SB 700-23-6009 REV 04	ICA - MODIFICATION - AUDIO INTEGRATING SYSTEM - INTRODUCTION OF NEW AUDIO CONTROL PANEL ACP-6000 PART NO. 822-2928-500 (MOD 1) INSTEAD OF ACP-4120 PART NO. 822-1950-503, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
09-JUL-2014		MOS					
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-23-6010	MODIFICATION - VOICE RECORDER SYSTEM - COCKPIT VOICE RECORDER (CVR) - FA2100 CVR P/N 2100-1025-22 CHANGE TO P/N 2100-1025-24, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
19-SEP-2012		HRS/MSC	-				
		AFL					
SB 700-23-6010 REV 01	MODIFICATION - VOICE RECORDER SYSTEM - COCKPIT VOICE RECORDER (CVR) - FA2100 CVR P/N 2100-1025-22 CHANGE TO P/N 2100-1025-24, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
10-DEC-2012		HRS/MSC	-				
		AFL					
SB 700-23-6011	MODIFICATION - VOICE RECORDER SYSTEM - REPLACEMENT OF COCKPIT VOICE RECORDER CVR IMPACT SWITCH, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
04-MAR-2013		HRS/MSC	-				
		AFL					
SB 700-23-6011 REV 01	ICA - MODIFICATION - VOICE RECORDER SYSTEM - REPLACEMENT OF COCKPIT VOICE RECORDER CVR IMPACT SWITCH, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
01-OCT-2014		HRS/MSC	-				
		AFL					
SB 700-23-6012 REV 01	MODIFICATION - GENERAL - UPDATE TO SUPPORT IMPLEMENTATION OF ATN CPDLC CAPABILITY, SERVICE BULLETIN			OPTIONAL			NOT APPLICABLE
		MOS					
15-AUG-2014		HRS/MSC	-				
		AFL					
SB 700-23-6012 REV 02	MODIFICATION - GENERAL - UPDATE TO SUPPORT IMPLEMENTATION OF ATN CPDLC CAPABILITY, SERVICE BULLETIN			OPTIONAL			NOT APPLICABLE
		MOS					
13-NOV-2014		HRS/MSC	-				
		AFL					
SB 700-23-6013	ICA - SPECIAL CHECK/MODIFICATION - RADIO MANAGEMENT SYSTEM (RMS) - INSPECTION OF IMPROPERLY CRIMPED TERMINAL FORK CONTACTS ON RADIO INTERFACE UNIT (RIU) NO. 1 AND NO. 2, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
23-MAY-2013		HRS/MSC	-				
		AFL					
SB 700-23-6013 PART A	REMOVE/INSPECT ICA - SPECIAL CHECK/MODIFICATION - RADIO MANAGEMENT SYSTEM (RMS) - INSPECTION OF IMPROPERLY CRIMPED TERMINAL FORK CONTACTS ON RADIO INTERFACE UNIT (RIU) NO. 1 AND NO. 2, SERVICE BULLETIN AND REPLACE THE FORK CONTACTS P87 AND P88 ON RIU NO. 1 (A411P1 AND A411P2) AND RIU NO. 2 (A412P1 AND A412P2)					RECOMMENDED	NOT APPLICABLE
		MOS					
23-MAY-2013		HRS/MSC	-				
		AFL					
SB 700-23-6013 PART B	REMOVE/INSPECT ICA - SPECIAL CHECK/MODIFICATION - RADIO MANAGEMENT SYSTEM (RMS) - INSPECTION OF IMPROPERLY CRIMPED TERMINAL FORK CONTACTS ON RADIO INTERFACE UNIT (RIU) NO. 1 AND NO. 2, SERVICE BULLETIN AND REPLACE ALL OTHER FORK CONTACTS (NOT P87 AND P88) ON RIU NO. 1 (A411P1 AND A411P2) AND RIU NO. 2 (A412P1 AND A412P2)					RECOMMENDED	NOT APPLICABLE
		MOS					
23-MAY-2013		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-23-6013 REV 01	ICA - SPECIAL CHECK/MODIFICATION - RADIO MANAGEMENT SYSTEM (RMS) - INSPECTION OF IMPROPERLY CRIMPED TERMINAL FORK CONTACTS ON RADIO INTERFACE UNIT (RIU) NO. 1 AND NO. 2, SERVICE BULLETIN			RECOMMENDED		NOT APPLICABLE	
16-JAN-2014		MOS HRS/MSC - AFL					
SB 700-23-6013 REV 01 PART A	REMOVE/INSPECT ICA - SPECIAL CHECK/MODIFICATION - RADIO MANAGEMENT SYSTEM (RMS) - INSPECTION OF IMPROPERLY CRIMPED TERMINAL FORK CONTACTS ON RADIO INTERFACE UNIT (RIU) NO. 1 AND NO. 2, SERVICE BULLETIN AND REPLACE CONTACTS P87 AND P88 ON RIU NO. 1 (A411P1 AND A411P2) AND RIU NO. 2 (A412P1 AND A412P2)			RECOMMENDED		NOT APPLICABLE	
16-JAN-2014		MOS HRS/MSC - AFL					
SB 700-23-6013 REV 01 PART B	REMOVE/INSPECT ICA - SPECIAL CHECK/MODIFICATION - RADIO MANAGEMENT SYSTEM (RMS) - INSPECTION OF IMPROPERLY CRIMPED TERMINAL FORK CONTACTS ON RADIO INTERFACE UNIT (RIU) NO. 1 AND NO. 2, SERVICE BULLETIN AND REPLACE ALL OTHER CONTACTS (NOT P87 AND P88) ON RIU NO. 1 (A411P1 AND A411P2) AND RIU NO. 2 (A412P1 AND A412P2)			RECOMMENDED		NOT APPLICABLE	
16-JAN-2014		MOS HRS/MSC - AFL					
SB 700-23-6015	MODIFICATION - RADIO MANAGEMENT SYSTEM - REPLACE CTP-6000 PART NUMBER 822-2493-003 TO REDUCE OCCURANCE OF UN-COMMANDED BEHAVIOR, SERVICE BULLETIN			RECOMMENDED		NOT APPLICABLE	
17-FEB-2014		MOS HRS/MSC - AFL					
SB 700-23-6015 REV 01	ICA - MODIFICATION - RADIO MANAGEMENT SYSTEM - REPLACE CTP-6000 PART NUMBER 822-2493-003 TO REDUCE OCCURENCE OF UN-COMMANDED BEHAVIOR, SERVICE BULLETIN			RECOMMENDED		NOT APPLICABLE	
17-APR-2014		MOS HRS/MSC - AFL					
SB 700-23-6016	MODIFICATION - CABIN COMMUNICATION SYSTEM - REPLACEMENT OF CORDLESS HANDSET ASSEMBLY, SERVICE BULLETIN			OPTIONAL		NOT APPLICABLE	
27-MAR-2015		MOS HRS/MSC - AFL					
SB 700-23-6016 REV 01	MODIFICATION - CABIN COMMUNICATION SYSTEM - REPLACEMENT OF CORDLESS HANDSET ASSEMBLY, SERVICE BULLETIN			OPTIONAL		NOT APPLICABLE	
12-JUL-2016		MOS HRS/MSC - AFL					
SB 700-23-6016 REV 02	MODIFICATION - CABIN COMMUNICATION SYSTEM - REPLACEMENT OF CORDLESS HANDSET ASSEMBLY, SERVICE BULLETIN			OPTIONAL		NOT APPLICABLE	
28-MAY-2018		MOS HRS/MSC - AFL					
SB 700-23-6017 REV 03	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INTRODUCTION OF HONEYWELL JETWAVE KA-BAND RADOME FAIRING, SERVICE BULLETIN			OPTIONAL		NOT APPLICABLE - N/A	
03-MAY-2018		MOS HRS/MSC - AFL	15-JAN-2025				

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-23-6018 REV 01	MODIFICATION - AIRBORNE TELEPHONE SYSTEM - ASPIRE-100 CSU SOFTWARE UPGRADE (SUPERSEDED BY 700-23-6018 REV 02), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - 700-23-6018 REV 1 COMPLIED WITH
31-MAR-2017		MOS		28-SEP-2017			
		HRS/MSC	-	485:04			
		AFL		176			
SB 700-23-6018 REV 01 PART A	ACCOMPLISH MODIFICATION - AIRBORNE TELEPHONE SYSTEM - ASPIRE-100 CSU SOFTWARE UPGRADE (SUPERSEDED BY 700-23-6018 REV 02), SERVICE BULLETIN CSU SOFTWARE VALIDATION					RECOMMENDED	COMPLIED WITH
31-MAR-2017		MOS		28-SEP-2017			
		HRS/MSC	-	485:04			
		AFL		176			
SB 700-23-6018 REV 01 PART B	ACCOMPLISH MODIFICATION - AIRBORNE TELEPHONE SYSTEM - ASPIRE-100 CSU SOFTWARE UPGRADE (SUPERSEDED BY 700-23-6018 REV 02), SERVICE BULLETIN CSU SOFTWARE UPDATE					RECOMMENDED	COMPLIED WITH
31-MAR-2017		MOS		28-SEP-2017			
		HRS/MSC	-	485:04			
		AFL		176			
SB 700-23-6018 REV 01 PART C	ACCOMPLISH MODIFICATION - AIRBORNE TELEPHONE SYSTEM - ASPIRE-100 CSU SOFTWARE UPGRADE (SUPERSEDED BY 700-23-6018 REV 02), SERVICE BULLETIN REPLACEMENT OF THE CSU					RECOMMENDED	COMPLIED WITH
31-MAR-2017		MOS		28-SEP-2017			
		HRS/MSC	-	485:04			
		AFL		176			
SB 700-23-6018 REV 01 PART D	ACCOMPLISH MODIFICATION - AIRBORNE TELEPHONE SYSTEM - ASPIRE-100 CSU SOFTWARE UPGRADE (SUPERSEDED BY 700-23-6018 REV 02), SERVICE BULLETIN CONFIGURING THE CSU					RECOMMENDED	COMPLIED WITH
31-MAR-2017		MOS		28-SEP-2017			
		HRS/MSC	-	485:04			
		AFL		176			
SB 700-23-6018 REV 02	MODIFICATION - AIRBORNE TELEPHONE SYSTEM - ASPIRE-100 CSU SOFTWARE UPGRADE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - N/R, C/W SB R01
21-AUG-2019		MOS		15-JAN-2025			
		HRS/MSC	-				
		AFL					
SB 700-23-6018 REV 02 PART A	ACCOMPLISH MODIFICATION - AIRBORNE TELEPHONE SYSTEM - ASPIRE-100 CSU SOFTWARE UPGRADE, SERVICE BULLETIN CSU SOFTWARE VALIDATION					RECOMMENDED	COMPLIED WITH - N/R, C/W SB R01
21-AUG-2019		MOS		15-JAN-2025			
		HRS/MSC	-				
		AFL					
SB 700-23-6018 REV 02 PART B	ACCOMPLISH MODIFICATION - AIRBORNE TELEPHONE SYSTEM - ASPIRE-100 CSU SOFTWARE UPGRADE, SERVICE BULLETIN CSU SOFTWARE UPDATE					RECOMMENDED	COMPLIED WITH - N/R, C/W SB R01
21-AUG-2019		MOS		15-JAN-2025			
		HRS/MSC	-				
		AFL					
SB 700-23-6018 REV 02 PART C	ACCOMPLISH MODIFICATION - AIRBORNE TELEPHONE SYSTEM - ASPIRE-100 CSU SOFTWARE UPGRADE, SERVICE BULLETIN REPLACEMENT OF THE CSU					RECOMMENDED	COMPLIED WITH - N/R, C/W SB R01
21-AUG-2019		MOS		15-JAN-2025			
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-23-6018 REV 02 PART D	ACCOMPLISH MODIFICATION - AIRBORNE TELEPHONE SYSTEM - ASPIRE-100 CSU SOFTWARE UPGRADE, SERVICE BULLETIN CONFIGURING THE CSU					RECOMMENDED	COMPLIED WITH - N/R, C/W SB R01
21-AUG-2019		MOS HRS/MSC - AFL		15-JAN-2025			
SB 700-23-6019	MODIFICATION - CABIN COMMUNICATION SYSTEM - REPLACEMENT OF ICS 100/200 SERIES IRIDIUM TRANSCEIVER WITH ICS 120/220 A/AF/B/BF SERIES IRIDIUM TRANSCEIVER, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
07-JUL-2017		MOS HRS/MSC - AFL					
SB 700-23-6019 REV 01	MODIFICATION - CABIN COMMUNICATION SYSTEM - REPLACEMENT OF ICS 100/200 SERIES IRIDIUM TRANSCEIVER WITH ICS 120/220 A/AF/B/BF SERIES IRIDIUM TRANSCEIVER, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
29-MAR-2018		MOS HRS/MSC - AFL					
SB 700-23-6020	SPECIAL CHECK/REWORK - SATELLITE COMMUNICATIONS SYSTEM - INSPECTION OF SATCOM RF COAX CABLE FOR MINIMUM BEND RADIUS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - 700-23-6020 COMPLIED WITH
20-MAR-2017		MOS HRS/MSC - AFL		28-SEP-2017 485:04 176			
SB 700-23-6020 PART A	ACCOMPLISH SPECIAL CHECK/REWORK - SATELLITE COMMUNICATIONS SYSTEM - INSPECTION OF SATCOM RF COAX CABLE FOR MINIMUM BEND RADIUS, SERVICE BULLETIN VISUAL INSPECTION					RECOMMENDED	COMPLIED WITH
20-MAR-2017		MOS HRS/MSC - AFL		22-SEP-2017 485:04 176			
SB 700-23-6020 PART B	ACCOMPLISH SPECIAL CHECK/REWORK - SATELLITE COMMUNICATIONS SYSTEM - INSPECTION OF SATCOM RF COAX CABLE FOR MINIMUM BEND RADIUS, SERVICE BULLETIN COAXIAL CABLE BEND RADIUS REWORK					RECOMMENDED	COMPLIED WITH
20-MAR-2017		MOS HRS/MSC - AFL		22-SEP-2017 485:04 176			
SB 700-23-6021	SPECIAL CHECK/REWORK - SATELLITE COMMUNICATIONS SYSTEM - INSPECTION OF SATCOM RF COAX CABLE FOR MINIMUM BEND RADIUS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - 700-23-6021 COMPLIED WITH
29-JUN-2017		MOS HRS/MSC - AFL		28-SEP-2017 485:04 176			
SB 700-23-6021 PART A	ACCOMPLISH SPECIAL CHECK/REWORK - SATELLITE COMMUNICATIONS SYSTEM - INSPECTION OF SATCOM RF COAX CABLE FOR MINIMUM BEND RADIUS, SERVICE BULLETIN VISUAL INSPECTION OF THE COAXIAL CABLE BEND RADIUS					RECOMMENDED	COMPLIED WITH - SB 700-23-6021 PART A HAS BEEN COMPLIED WITH
29-JUN-2017		MOS HRS/MSC - AFL		22-SEP-2017 485:04 176			
SB 700-23-6021 PART B	ACCOMPLISH SPECIAL CHECK/REWORK - SATELLITE COMMUNICATIONS SYSTEM - INSPECTION OF SATCOM RF COAX CABLE FOR MINIMUM BEND RADIUS, SERVICE BULLETIN COAXIAL CABLE INSTALLATION REWORK					RECOMMENDED	COMPLIED WITH - SB 700-23-6021 PART B HAS BEEN COMPLIED WITH
29-JUN-2017		MOS HRS/MSC - AFL		22-SEP-2017 485:04 176			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-23-6021 REV 01	SPECIAL CHECK/REWORK - SATELLITE COMMUNICATIONS SYSTEM - INSPECTION OF SATCOM RF COAX CABLE FOR MINIMUM BEND RADIUS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - N/R, C/W SB BASIC
25-OCT-2018		MOS HRS/MSC - AFL		15-JAN-2025			
SB 700-23-6021 REV 01 PART A	ACCOMPLISH SPECIAL CHECK/REWORK - SATELLITE COMMUNICATIONS SYSTEM - INSPECTION OF SATCOM RF COAX CABLE FOR MINIMUM BEND RADIUS, SERVICE BULLETIN VISUAL INSPECTION OF THE COAXIAL CABLE BEND RADIUS					RECOMMENDED	COMPLIED WITH - N/R, C/W SB BASIC
25-OCT-2018		MOS HRS/MSC - AFL		15-JAN-2025			
SB 700-23-6021 REV 01 PART B	ACCOMPLISH SPECIAL CHECK/REWORK - SATELLITE COMMUNICATIONS SYSTEM - INSPECTION OF SATCOM RF COAX CABLE FOR MINIMUM BEND RADIUS, SERVICE BULLETIN COAXIAL CABLE INSTALLATION REWORK					RECOMMENDED	COMPLIED WITH - N/R, C/W SB BASIC
25-OCT-2018		MOS HRS/MSC - AFL		15-JAN-2025			
SB 700-23-6023	MODIFICATION - CABIN COMMUNICATION SYSTEM - SIGMA 7 HANDSETS REPLACEMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
23-DEC-2019		MOS HRS/MSC - AFL					
SB 700-23-6025	MODIFICATION - CABIN COMMUNICATION SYSTEM - ASPIRE-100 HANDSET REMOVAL IF NOT REQUIRED WITH CES, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
12-OCT-2020		MOS HRS/MSC - AFL					
SB 700-23-6026	MODIFICATION - CABIN COMMUNICATION SYSTEM - ASPIRE-100 HANDSET REMOVAL IF NOT REQUIRED WITH VENUE CABIN MANAGEMENT SYSTEM (CMS), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
12-OCT-2020		MOS HRS/MSC - AFL					
STC 10038659 REV2	INSTALLATION OF CLASS II ELECTRONIC FLIGHT BAG (DUAL) - L3 COMMUNICATIONS CREWMATE 840, SUPPLEMENTAL TYPE CERTIFICATE					COMPLIED WITH	
		MOS HRS/MSC - AFL		07-AUG-2015			
STC ST03108NY	INSTALLATION OF CLASS II ELECTRONIC FLIGHT BAG (SINGLE L3 COMMUNICATIONS CREWMATE 840). , SUPPLEMENTAL TYPE CERTIFICATE					STC-SUPPLEMENTAL TYPE CERTIFICATE	COMPLIED WITH
		MOS HRS/MSC - AFL		07-AUG-2015			
VSB 90403825 REV A	ASPIRE-100 (1492-A-3200-202) -ASPIRE-100 SOFTWARE UPGRADE, VENDOR SERVICE BULLETIN					COMPLIED WITH	
		MOS HRS/MSC - AFL		28-SEP-2017 485:04 176			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
VSB 90404347 REV A	ASPIRE 100 SOFTWARE UPGRADE, VENDOR SERVICE BULLETIN						COMPLIED WITH
		MOS		28-SEP-2017			
		HRS/MSC	-	485:04			
		AFL		176			
CHAPTER 24 ELECTRICAL POWER							
SB 700-24-6003	MODIFICATION - MAIN GENERATOR OIL SYSTEM - ADDITION OF HIGH CONDUCTIVITY OIL TO DISSIPATE ELECTRO STATIC DISCHARGE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - N/A BY A/C S/N
20-FEB-2012		MOS		15-JAN-2025			
		HRS/MSC	-				
		AFL					
SB 700-24-6004	MODIFICATION - MAIN GENERATOR OIL SYSTEM - INTRODUCTION OF NEW VARIABLE FREQUENCY GENERATOR (VFG) FILTER ELEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - N/A BY A/C S/N
20-FEB-2012		MOS		15-JAN-2025			
		HRS/MSC	-				
		AFL					
SB 700-24-6005	MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
30-APR-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 700-24-6005 PART A	CHECK MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
30-APR-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 700-24-6005 PART B	INSPECTION MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
30-APR-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 700-24-6005 PART C	REPLACEMENT MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
30-APR-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 700-24-6006 REV 01	SPECIAL CHECK - PRIMARY AC POWER SUPPLY - VFG VIBRATION GROUND TEST, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
05-NOV-2013		MOS					
		HRS/MSC	-				
		AFL					
SB 700-24-6006 REV 02	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - VFG VIBRATION GROUND TEST, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
10-OCT-2014		MOS					
		HRS/MSC	-				
		AFL					
SB 700-24-6006 REV 03	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - VARIABLE FREQUENCY GENERATOR (VFG) VIBRATION GROUND TEST, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
26-MAR-2015		MOS					
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-24-6007	MODIFICATION - ELECTRICAL POWER - BUS BAR HARNESS CLAMP REPLACEMENT IN THE LEFT HAND SIDE CIRCUIT BREAKER PANEL, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
09-OCT-2012		HRS/MSC	-				
		AFL					
SB 700-24-6008 REV 01	MODIFICATION - MAIN GENERATOR OIL SYSTEM - REPLACEMENT OF THE VARIABLE FREQUENCY GENERATOR, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
02-APR-2014		HRS/MSC	-				
		AFL					
SB 700-24-6009	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - REBALANCE OF VARIABLE FREQUENCY GENERATOR (VFG), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
28-MAY-2015		HRS/MSC	-				
		AFL					
SB 700-24-6009 PART A	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - REBALANCE OF VARIABLE FREQUENCY GENERATOR (VFG), SERVICE BULLETIN SPECIAL CHECK					RECOMMENDED	NOT APPLICABLE
		MOS					
28-MAY-2015		HRS/MSC	-				
		AFL					
SB 700-24-6009 PART B	SPECIAL CHECK - PRIMARY AC-POWER SUPPLY - REBALANCE OF VARIABLE FREQUENCY GENERATOR (VFG), SERVICE BULLETIN REPLACEMENT OF VFG(S)					RECOMMENDED	NOT APPLICABLE
		MOS					
28-MAY-2015		HRS/MSC	-				
		AFL					
SB 700-24-6010 REV 01	MODIFICATION - DC POWER CENTER (DCPC) - ADD CBC1 TERMINAL INSULATOR ON CHASSIS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
18-AUG-2016		HRS/MSC	-				
		AFL					
SB 700-24-6011	SPECIAL CHECK/MODIFICATION - ELECTRICAL GENERAL- REPLACEMENT OF ELECTRICAL OUTLETS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS		(EFF)			
27-JAN-2017		HRS/MSC	-				
		AFL					
SB 700-24-6011 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - ELECTRICAL GENERAL- REPLACEMENT OF ELECTRICAL OUTLETS, SERVICE BULLETIN VISUAL INSPECTION OF THE UNIVERSAL ELECTRICAL OUTLETS					RECOMMENDED	NOT APPLICABLE
		MOS		(EFF)			
27-JAN-2017		HRS/MSC	-				
		AFL					
SB 700-24-6011 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - ELECTRICAL GENERAL- REPLACEMENT OF ELECTRICAL OUTLETS, SERVICE BULLETIN REPLACEMENT OF THE UNIVERSAL ELECTRICAL OUTLETS					RECOMMENDED	NOT APPLICABLE
		MOS		(EFF)			
27-JAN-2017		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-24-6012	SPECIAL CHECK/MODIFICATION - PRIMARY AC-POWER SUPPLY - INSPECTION OF THE VARIABLE FREQUENCY GENERATOR (VFG) HOUSING WALL THICKNESS AND IF NECESSARY REPLACEMENT OF VFG, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
04-OCT-2017	MOS HRS/MSC - AFL			31-OCT-2017 521:10 188			
SB 700-24-6012 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - PRIMARY AC-POWER SUPPLY - INSPECTION OF THE VARIABLE FREQUENCY GENERATOR (VFG) HOUSING WALL THICKNESS AND IF NECESSARY REPLACEMENT OF VFG, SERVICE BULLETIN VFG TORQUE AND SERIAL NUMBER CHECK					RECOMMENDED	COMPLIED WITH - WORK DONE
04-OCT-2017	MOS HRS/MSC - AFL			31-OCT-2017 521:10 188			
SB 700-24-6012 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - PRIMARY AC-POWER SUPPLY - INSPECTION OF THE VARIABLE FREQUENCY GENERATOR (VFG) HOUSING WALL THICKNESS AND IF NECESSARY REPLACEMENT OF VFG, SERVICE BULLETIN INSPECT VFG HOUSING WALL THICKNESS					RECOMMENDED	- SUPERSEDED BY REV 1
04-OCT-2017	MOS HRS/MSC - AFL						
SB 700-24-6012 PART C	ACCOMPLISH SPECIAL CHECK/MODIFICATION - PRIMARY AC-POWER SUPPLY - INSPECTION OF THE VARIABLE FREQUENCY GENERATOR (VFG) HOUSING WALL THICKNESS AND IF NECESSARY REPLACEMENT OF VFG, SERVICE BULLETIN MODIFICATION - REPLACEMENT OF VFG					RECOMMENDED	- SUPERSEDED BY REV 1
04-OCT-2017	MOS HRS/MSC - (s) AFL						
SB 700-24-6012 REV 01	SPECIAL CHECK/MODIFICATION - PRIMARY AC-POWER SUPPLY - INSPECTION OF THE VARIABLE FREQUENCY GENERATOR (VFG) HOUSING WALL THICKNESS AND IF NECESSARY REPLACEMENT OF VFG, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - C/W BY PART B & N/A BY PART C
29-MAR-2018	MOS HRS/MSC - AFL			27-JUN-2018 631:35 234			
SB 700-24-6012 REV 01 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - PRIMARY AC-POWER SUPPLY - INSPECTION OF THE VARIABLE FREQUENCY GENERATOR (VFG) HOUSING WALL THICKNESS AND IF NECESSARY REPLACEMENT OF VFG, SERVICE BULLETIN VFG TORQUE AND SERIAL NUMBER CHECK					RECOMMENDED	NOT APPLICABLE - PCW SB 700-24-6012 BASIC REVISION PART A ON 10-31-2017
29-MAR-2018	MOS HRS/MSC - AFL			31-OCT-2017 521:10 188			
SB 700-24-6012 REV 01 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - PRIMARY AC-POWER SUPPLY - INSPECTION OF THE VARIABLE FREQUENCY GENERATOR (VFG) HOUSING WALL THICKNESS AND IF NECESSARY REPLACEMENT OF VFG, SERVICE BULLETIN INSPECT VFG HOUSING WALL THICKNESS					RECOMMENDED	COMPLIED WITH - SB 700-24-6012 R1 PART B COMPLIED WITH ON VFG #3 S/N 5221 ONLY
29-MAR-2018	MOS HRS/MSC - AFL			27-JUN-2018 631:35 234			
SB 700-24-6012 REV 01 PART C	ACCOMPLISH SPECIAL CHECK/MODIFICATION - PRIMARY AC-POWER SUPPLY - INSPECTION OF THE VARIABLE FREQUENCY GENERATOR (VFG) HOUSING WALL THICKNESS AND IF NECESSARY REPLACEMENT OF VFG, SERVICE BULLETIN MODIFICATION - REPLACEMENT OF VFG					RECOMMENDED	NOT APPLICABLE - SB 700-24-6012 R1 PART C NOT APPLICABLE DUE TO VFG #3 REMAINING THICKNESS IS WITHIN LIMIT
29-MAR-2018	MOS HRS/MSC - AFL			27-JUN-2018 631:35 234			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-24-6012 REV 02	SPECIAL CHECK/MODIFICATION - PRIMARY AC-POWER SUPPLY - INSPECTION OF THE VARIABLE FREQUENCY GENERATOR (VFG) HOUSING WALL THICKNESS AND IF NECESSARY REPLACEMENT OF VFG, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - N/R, C/W SB R01
06-FEB-2019		MOS HRS/MSC - AFL		15-JAN-2025			
SB 700-24-6012 REV 02 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - PRIMARY AC-POWER SUPPLY - INSPECTION OF THE VARIABLE FREQUENCY GENERATOR (VFG) HOUSING WALL THICKNESS AND IF NECESSARY REPLACEMENT OF VFG, SERVICE BULLETIN VFG TORQUE AND SERIAL NUMBER CHECK					RECOMMENDED	COMPLIED WITH - N/R, C/W SB R01
06-FEB-2019		MOS HRS/MSC - AFL		15-JAN-2025			
SB 700-24-6012 REV 02 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - PRIMARY AC-POWER SUPPLY - INSPECTION OF THE VARIABLE FREQUENCY GENERATOR (VFG) HOUSING WALL THICKNESS AND IF NECESSARY REPLACEMENT OF VFG, SERVICE BULLETIN INSPECT VFG HOUSING WALL THICKNESS					RECOMMENDED	COMPLIED WITH - N/R, C/W SB R01
06-FEB-2019		MOS HRS/MSC - AFL		15-JAN-2025			
SB 700-24-6012 REV 02 PART C	ACCOMPLISH SPECIAL CHECK/MODIFICATION - PRIMARY AC-POWER SUPPLY - INSPECTION OF THE VARIABLE FREQUENCY GENERATOR (VFG) HOUSING WALL THICKNESS AND IF NECESSARY REPLACEMENT OF VFG, SERVICE BULLETIN MODIFICATION - REPLACEMENT OF VFG					RECOMMENDED	COMPLIED WITH - N/R, C/W SB R01
06-FEB-2019		MOS HRS/MSC - (s) AFL		15-JAN-2025			
SB 700-24-6013 REV 01	MODIFICATION - CIRCUIT BREAKER - CABIN FIXED FREQUENCY MAIN CIRCUIT BREAKER, SERVICE BULLETIN						NOT APPLICABLE - N/A BY TCCA STC# SA12-40 / FAA STC#ST03228NY
22-NOV-2018		MOS HRS/MSC - AFL		15-JAN-2025			
SB 700-24-6013 REV 02	MODIFICATION - CIRCUIT BREAKER - CABIN FIXED FREQUENCY MAIN CIRCUIT BREAKER, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - N/A BY TCCA STC# SA12-40 / FAA STC#ST03228NY
19-JAN-2021		MOS HRS/MSC - AFL		15-JAN-2025			
SB 700-24-6014	MODIFICATION - VARIABLE FREQUENCY GENERATOR (VFG) - MODIFICATION TO THE VFG CABLES INSTALLATION, REAR FUSELAG, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - 700-24-6014 PART A COMPLIED WITH. PART B NOT REQUIRE
25-APR-2018		MOS HRS/MSC - AFL		27-JUN-2018 631:35 234			
SB 700-24-6014 PART A	ACCOMPLISH MODIFICATION - VARIABLE FREQUENCY GENERATOR (VFG) - MODIFICATION TO THE VFG CABLES INSTALLATION, REAR FUSELAG, SERVICE BULLETIN MODIFICATION - INSTALLATION OF ADDITIONAL CLAMPS					RECOMMENDED	COMPLIED WITH
25-APR-2018		MOS HRS/MSC - AFL		27-JUN-2018 631:35 234			
SB 700-24-6014 PART B	ACCOMPLISH MODIFICATION - VARIABLE FREQUENCY GENERATOR (VFG) - MODIFICATION TO THE VFG CABLES INSTALLATION, REAR FUSELAG, SERVICE BULLETIN MODIFICATION - CUTTING THE ELECTRICAL WIRES TO MEET INSTALLATION REQUIREMENTS (IF NECESSARY)					RECOMMENDED	NOT APPLICABLE - SB 700-24-6014 PART B FOUND NOT APPLICABLE
25-APR-2018		MOS HRS/MSC - AFL		27-JUN-2018 631:35 234			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-24-6014 REV 01	MODIFICATION - VARIABLE FREQUENCY GENERATOR (VFG) - MODIFICATION TO THE VFG CABLES INSTALLATION, REAR FUSELAGE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - N/R, C/W SB BASIC
21-AUG-2018		MOS HRS/MSC - AFL		15-JAN-2025			
SB 700-24-6014 REV 01 PART A	ACCOMPLISH MODIFICATION - VARIABLE FREQUENCY GENERATOR (VFG) - MODIFICATION TO THE VFG CABLES INSTALLATION, REAR FUSELAGE, SERVICE BULLETIN MODIFICATION - INSTALLATION OF ADDITIONAL CLAMPS					RECOMMENDED	COMPLIED WITH - N/R, C/W SB BASIC
21-AUG-2018		MOS HRS/MSC - AFL		15-JAN-2025			
SB 700-24-6014 REV 01 PART B	ACCOMPLISH MODIFICATION - VARIABLE FREQUENCY GENERATOR (VFG) - MODIFICATION TO THE VFG CABLES INSTALLATION, REAR FUSELAGE, SERVICE BULLETIN MODIFICATION - CUTTING THE ELECTRICAL WIRES TO MEET INSTALLATION REQUIREMENTS (IF NECESSARY)					RECOMMENDED	COMPLIED WITH - N/R, C/W SB BASIC
21-AUG-2018		MOS HRS/MSC - AFL		15-JAN-2025			
SB 700-24-6014 REV 02	MODIFICATION - VARIABLE FREQUENCY GENERATOR (VFG) - MODIFICATION TO THE VFG CABLES INSTALLATION, REAR FUSELAGE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - N/R, C/W SB BASIC
27-SEP-2018		MOS HRS/MSC - AFL		15-JAN-2025			
SB 700-24-6014 REV 02 PART A	ACCOMPLISH MODIFICATION - VARIABLE FREQUENCY GENERATOR (VFG) - MODIFICATION TO THE VFG CABLES INSTALLATION, REAR FUSELAGE, SERVICE BULLETIN MODIFICATION - INSTALLATION OF ADDITIONAL CLAMPS					RECOMMENDED	COMPLIED WITH - N/R, C/W SB BASIC
27-SEP-2018		MOS HRS/MSC - AFL		15-JAN-2025			
SB 700-24-6014 REV 02 PART B	ACCOMPLISH MODIFICATION - VARIABLE FREQUENCY GENERATOR (VFG) - MODIFICATION TO THE VFG CABLES INSTALLATION, REAR FUSELAGE, SERVICE BULLETIN MODIFICATION - CUTTING THE ELECTRICAL WIRES TO MEET INSTALLATION REQUIREMENTS (IF NECESSARY)					RECOMMENDED	COMPLIED WITH - N/R, C/W SB BASIC
27-SEP-2018		MOS HRS/MSC - AFL		15-JAN-2025			
SB 700-24-6015	SPECIAL CHECK/MODIFICATION - EMERGENCY AC-POWER SUPPLY - REPLACEMENT OF THE RAM AIR TURBINE (RAT) DEPLOYMENT ACTUATOR PART NO. BZ02001-01 (GL456-1301-1), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - CHECK COMPLETE
22-FEB-2019		MOS HRS/MSC - AFL		18-MAR-2019 909:57 319			
SB 700-24-6015 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - EMERGENCY AC-POWER SUPPLY - REPLACEMENT OF THE RAM AIR TURBINE (RAT) DEPLOYMENT ACTUATOR PART NO. BZ02001-01 (GL456-1301-1), SERVICE BULLETIN SPECIAL CHECK					RECOMMENDED	COMPLIED WITH - CHECK COMPLETE
22-FEB-2019		MOS HRS/MSC - AFL		18-MAR-2019 909:57 319			
SB 700-24-6015 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - EMERGENCY AC-POWER SUPPLY - REPLACEMENT OF THE RAM AIR TURBINE (RAT) DEPLOYMENT ACTUATOR PART NO. BZ02001-01 (GL456-1301-1), SERVICE BULLETIN MODIFICATION					RECOMMENDED	NOT APPLICABLE - N/A
22-FEB-2019		MOS HRS/MSC - AFL		18-MAR-2019 909:57 319			

CHAPTER 25 EQUIPMENT/FURNISHINGS

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-25-6005	MODIFICATION - BUFFET/GALLEY - MODIFICATION OF MICROWAVE OVEN PART NO. 400-1409-01-L OR 400-1409-01-R, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
24-JUL-2013		HRS/MSC	-				
		AFL					
SB 700-25-6006	SPECIAL CHECK/REWORK - GALLEY - REWORK OF THE COFFEE BREWER, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
05-SEP-2012		HRS/MSC	-				
		AFL					
SB 700-25-6008	MODIFICATION - EMERGENCY LOCATOR SYSTEM (ELT) - EMERGENCY LOCATOR TRANSMITTER REMOVAL/INSTALLATION IMPROVEMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
27-JUN-2013		HRS/MSC	-				
		AFL					
SB 700-25-6009	MODIFICATION - ENTRY AREA CURTAINS - REPLACEMENT OF COCKPIT CURTAIN ASSEMBLY PART NO. 70025212626-001 WITH CURTAIN ASSEMBLY PART NO. BAS67039356-3 OR BAS67039369-3, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
05-FEB-2014		HRS/MSC	-				
		AFL					
SB 700-25-6011	MODIFICATION - GALLEY - HOT CUP PLACARD INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
20-DEC-2013		HRS/MSC	-				
		AFL					
SB 700-25-6012	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (FORWARD), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
30-SEP-2014		HRS/MSC	-				
		AFL					
SB 700-25-6012 REV 01	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (FORWARD), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
26-JAN-2015		HRS/MSC	-				
		AFL					
SB 700-25-6013	MODIFICATION - CONFERENCE TABLES - HEIGHT ADJUSTMENT OF CONFERENCE TABLES, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
05-MAR-2014		HRS/MSC	-				
		AFL					
SB 700-25-6014	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (MID), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
30-SEP-2014		HRS/MSC	-				
		AFL					
SB 700-25-6014 REV 01	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR FOOTER MECHANISM (MID), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
26-JAN-2015		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-25-6015	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE MANUAL RELEASE POCKET-DOOR FOOTER MECHANISM (FORWARD), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
30-SEP-2014		HRS/MSC	-				
		AFL					
SB 700-25-6015 REV 01	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE MANUAL RELEASE POCKET-DOOR FOOTER MECHANISM (FORWARD), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
25-MAY-2015		HRS/MSC	-				
		AFL					
SB 700-25-6015 REV 02	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE MANUAL RELEASE POCKET-DOOR FOOTER MECHANISM (FORWARD), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
20-AUG-2015		HRS/MSC	-				
		AFL					
SB 700-25-6016	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE MANUAL RELEASE POCKET-DOOR FOOTER MECHANISM (MID), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
30-SEP-2014		HRS/MSC	-				
		AFL					
SB 700-25-6016 REV 02	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE MANUAL RELEASE POCKET-DOOR FOOTER MECHANISM (MID), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
20-AUG-2015		HRS/MSC	-				
		AFL					
SB 700-25-6017	MODIFICATION - PASSENGER COMPARTMENT - REPLACEMENT OF MICROSWITCH IN ELECTRICAL CONTROLS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
29-MAY-2014		HRS/MSC	-				
		AFL					
SB 700-25-6017 REV 01	MODIFICATION - PASSENGER COMPARTMENT - REPLACEMENT OF MICROSWITCH IN ELECTRICAL CONTROLS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
10-APR-2015		HRS/MSC	-				
		AFL					
SB 700-25-6018	ICA - SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - INSPECTION AND REPLACEMENT OF EJECTOR BASE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
23-FEB-2015		HRS/MSC	-				
		AFL					
SB 700-25-6018 PART A	VERIFICATION ICA - SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - INSPECTION AND REPLACEMENT OF EJECTOR BASE, SERVICE BULLETIN OF INSTALLED PARTS					RECOMMENDED	NOT APPLICABLE
		MOS					
23-FEB-2015		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-25-6018 PART B	REPLACEMENT ICA - SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - INSPECTION AND REPLACEMENT OF EJECTOR BASE, SERVICE BULLETIN OF THE EJECTOR BASE				RECOMMENDED	NOT APPLICABLE	
		MOS					
23-FEB-2015		HRS/MSC	-				
		AFL					
SB 700-25-6018 REV 01	ICA - SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - INSPECTION AND REPLACEMENT OF EJECTOR BASE, SERVICE BULLETIN				RECOMMENDED	NOT APPLICABLE	
		MOS					
21-APR-2015		HRS/MSC	-				
		AFL					
SB 700-25-6018 REV 01 PART A	VERIFICATION ICA - SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - INSPECTION AND REPLACEMENT OF EJECTOR BASE, SERVICE BULLETIN OF INSTALLED PARTS				RECOMMENDED	NOT APPLICABLE	
		MOS					
21-APR-2015		HRS/MSC	-				
		AFL					
SB 700-25-6018 REV 01 PART B	REPLACEMENT ICA - SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - INSPECTION AND REPLACEMENT OF EJECTOR BASE, SERVICE BULLETIN OF THE EJECTOR BASE				RECOMMENDED	NOT APPLICABLE	
		MOS					
21-APR-2015		HRS/MSC	-				
		AFL					
SB 700-25-6020	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR ASSEMBLY (MID), SERVICE BULLETIN				OPTIONAL	NOT APPLICABLE	
		MOS					
18-DEC-2014		HRS/MSC	-				
		AFL					
SB 700-25-6020 REV 02	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE ELECTRIC RELEASE POCKET-DOOR ASSEMBLY (MID), SERVICE BULLETIN				OPTIONAL	NOT APPLICABLE	
		MOS					
24-AUG-2015		HRS/MSC	-				
		AFL					
SB 700-25-6021	MODIFICATION - ENTRY AREA HEADLINER - IMPROVEMENT OF MAIN ENTRANCE HEADLINER ATTACHMENTS, SERVICE BULLETIN				OPTIONAL	NOT APPLICABLE	
		MOS					
07-JAN-2015		HRS/MSC	-				
		AFL					
SB 700-25-6022	MODIFICATION - PASSENGER COMPARTMENT - REPLACEMENT OF DRAWER LATCH AND WIRE STRIKER ON CABINETS, SERVICE BULLETIN				RECOMMENDED	NOT APPLICABLE	
		MOS					
26-SEP-2016		HRS/MSC	-				
		AFL					
SB 700-25-6022 PART A	ACCOMPLISH MODIFICATION - PASSENGER COMPARTMENT - REPLACEMENT OF DRAWER LATCH AND WIRE STRIKER ON CABINETS, SERVICE BULLETIN LATCH AND WIRE STRIKER INSPECTION				RECOMMENDED	NOT APPLICABLE	
		MOS					
26-SEP-2016		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-25-6022 PART B	ACCOMPLISH MODIFICATION - PASSENGER COMPARTMENT - REPLACEMENT OF DRAWER LATCH AND WIRE STRIKER ON CABINETS, SERVICE BULLETIN REPLACEMENT OF THE LATCHES			RECOMMENDED		NOT APPLICABLE	
		MOS					
26-SEP-2016		HRS/MSC	-				
		AFL					
SB 700-25-6022 PART C	ACCOMPLISH MODIFICATION - PASSENGER COMPARTMENT - REPLACEMENT OF DRAWER LATCH AND WIRE STRIKER ON CABINETS, SERVICE BULLETIN REPLACEMENT AND RIGGING OF THE WIRE STRIKERS			RECOMMENDED		NOT APPLICABLE	
		MOS					
26-SEP-2016		HRS/MSC	-				
		AFL					
SB 700-25-6023 REV 01	MODIFICATION - FLIGHT COMPARTMENT- INSTALLATION OF EFB TABLET HOLDER AND SMART CHARGER, SERVICE BULLETIN				OPTIONAL		NOT APPLICABLE
		MOS					
28-JUL-2017		HRS/MSC	-				
		AFL					
SB 700-25-6024	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE AFT LAVATORY DOOR HINGES, SERVICE BULLETIN				RECOMMENDED		NOT APPLICABLE
		MOS					
15-DEC-2016		HRS/MSC	-				
		AFL					
SB 700-25-6024 REV 01	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE AFT LAVATORY DOOR HINGES, SERVICE BULLETIN				RECOMMENDED		NOT APPLICABLE
		MOS					
11-AUG-2017		HRS/MSC	-				
		AFL					
SB 700-25-6024 REV 02	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE AFT LAVATORY DOOR HINGES, SERVICE BULLETIN				RECOMMENDED		NOT APPLICABLE
		MOS					
26-APR-2018		HRS/MSC	-				
		AFL					
SB 700-25-6024 REV 03	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE AFT LAVATORY DOOR HINGES, SERVICE BULLETIN				RECOMMENDED		NOT APPLICABLE
		MOS					
13-NOV-2018		HRS/MSC	-				
		AFL					
SB 700-25-6024 REV 04	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE AFT LAVATORY DOOR HINGES, SERVICE BULLETIN				RECOMMENDED		NOT APPLICABLE
		MOS					
04-FEB-2019		HRS/MSC	-				
		AFL					
SB 700-25-6025	MODIFICATION - GENERAL - GALLEY WORK SURFACE IMPROVEMENT (SUPERSEDED BY 700-25-6025 REV 01), SERVICE BULLETIN				OPTIONAL		NOT APPLICABLE
		MOS					
24-MAY-2017		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-25-6025 REV 01	MODIFICATION - GENERAL - GALLEY WORK SURFACE IMPROVEMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
03-JUN-2020		MOS					
		HRS/MSC	-				
		AFL					
SB 700-25-6027	MODIFICATION - PASSENGER COMPARTMENT - MODIFICATION OF THE FWD LAVATORY DOOR HINGES, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
18-SEP-2017		MOS					
		HRS/MSC	-				
		AFL					
SB 700-25-6028	MODIFICATION - MISCELLANEOUS EQUIPMENT- REPLACEMENT OF THE AIRSTAIR ANTI-SLIP MAT (ON HOLD), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
01-SEP-2017		MOS					
		HRS/MSC	-				
		AFL					
SB 700-25-6028 REV 03	MODIFICATION - MISCELLANEOUS EQUIPMENT - REPLACEMENT OF THE AIRSTAIR ANTI-SLIP MAT, SERVICE BULLETIN				OPTIONAL		NOT APPLICABLE - DUE TO A/C SERIAL NO (9673) OT AFFECTED.
24-APR-2023		MOS		13-JUN-2023			
		HRS/MSC	-	1854:53			
		AFL		659			
SB 700-25-6031	MODIFICATION - BUFFET/GALLEY - MODIFICATION OF THE GALLEY MICROWAVE COMPARTMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
28-MAR-2018		MOS					
		HRS/MSC	-				
		AFL					
SB 700-25-6031 REV 01	MODIFICATION - BUFFET/GALLEY - MODIFICATION OF THE GALLEY MICROWAVE COMPARTMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
30-APR-2018		MOS					
		HRS/MSC	-				
		AFL					
SB 700-25-6031 REV 02	MODIFICATION - GALLEY OR ANNEX/PANTRY - MODIFICATION OF THE MICROWAVE COMPARTMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
17-JAN-2019		MOS					
		HRS/MSC	-				
		AFL					
SB 700-25-6031 REV 03	MODIFICATION - GALLEY OR ANNEX/PANTRY - MODIFICATION OF THE MICROWAVE COMPARTMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
27-OCT-2022		MOS					
		HRS/MSC	-				
		AFL					
SB 700-25-6033	MODIFICATION - DOOR STOPPER - IMPROVEMENT OF THE DOOR STOPPER AND STAY OPEN FOR THE AFT LAVATORY DOOR AND THE BAGGAGE COMPARTMENT DOOR, SERVICE BULLETIN				OPTIONAL		NOT APPLICABLE
24-SEP-2018		MOS					
		HRS/MSC	-				
		AFL					
SB 700-25-6035	SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - REPLACEMENT OF THE SEAT BELT EJECTOR BASE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
18-DEC-2018		MOS					
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-25-6035 PART A	ACCOMPLISH, SERVICE BULLETIN VERIFICATION OF INSTALLED SEAT BELTS					RECOMMENDED	NOT APPLICABLE
18-DEC-2018		MOS					
		HRS/MSC	-				
		AFL					
SB 700-25-6035 PART B	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE SEAT BELTS WITH THE TEMPORARY PARTS /MODIFIED SEAT BELTS					RECOMMENDED	NOT APPLICABLE
18-DEC-2018		MOS					
		HRS/MSC	-				
		AFL					
SB 700-25-6035 PART C	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE TEMPORARY PART WITH THE MODIFIED SEAT BELTS					RECOMMENDED	NOT APPLICABLE
18-DEC-2018		MOS					
		HRS/MSC	-				
		AFL					
SB 700-25-6035 REV 01	SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - REPLACEMENT OF THE SEAT BELT EJECTOR BASE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
24-APR-2019		MOS					
		HRS/MSC	-				
		AFL					
SB 700-25-6035 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN VERIFICATION OF INSTALLED SEAT BELTS					RECOMMENDED	NOT APPLICABLE
24-APR-2019		MOS					
		HRS/MSC	-				
		AFL					
SB 700-25-6035 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE SEAT BELTS WITH THE TEMPORARY PARTS /MODIFIED SEAT BELTS					RECOMMENDED	NOT APPLICABLE
24-APR-2019		MOS					
		HRS/MSC	-				
		AFL					
SB 700-25-6035 REV 01 PART C	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE TEMPORARY PART WITH THE MODIFIED SEAT BELTS					RECOMMENDED	NOT APPLICABLE
24-APR-2019		MOS					
		HRS/MSC	-				
		AFL					
SB 700-25-6035 REV 02	SPECIAL CHECK/REWORK - PASSENGER COMPARTMENT - REPLACEMENT OF THE SEAT BELT EJECTOR BASE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - TO PART NUMBER OF SEAT BELT DIFFERENT P/N: BL/5-02-5G58C3TSAREVG
17-MAY-2019		MOS		13-JUN-2023			
		HRS/MSC	-	1854:53			
		AFL		659			
SB 700-25-6035 REV 02 PART A	ACCOMPLISH, SERVICE BULLETIN VERIFICATION OF INSTALLED SEAT BELTS					RECOMMENDED	NOT APPLICABLE - TO PART NUMBER OF SEAT BELT DIFFERENT P/N: BL/5-02-5G58C3TSAREVG
17-MAY-2019		MOS		13-JUN-2023			
		HRS/MSC	-	1854:53			
		AFL		659			
SB 700-25-6035 REV 02 PART B	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE SEAT BELTS WITH THE TEMPORARY PARTS /MODIFIED SEAT BELTS					RECOMMENDED	NOT APPLICABLE - TO PART NUMBER OF SEAT BELT DIFFERENT P/N: BL/5-02-5G58C3TSAREVG
17-MAY-2019		MOS		13-JUN-2023			
		HRS/MSC	-	1854:53			
		AFL		659			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-25-6035 REV 02 PART C	ACCOMPLISH, SERVICE BULLETIN REPLACEMENT OF THE TEMPORARY PART WITH THE MODIFIED SEAT BELTS					RECOMMENDED	NOT APPLICABLE - TO PART NUMBER OF SEAT BELT DIFFERENT P/N: BL/5-02-5G58C3TSAREVG
17-MAY-2019		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-25-6037	MODIFICATION - GALLEY - GALLEY TAMBOUR DOOR PROXIMITY SWITCHES (SUPERSEDED BY 700-25-6037 REV 01), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
13-NOV-2019		MOS HRS/MSC - AFL					
SB 700-25-6037 PART A	ACCOMPLISH MODIFICATION - GALLEY - GALLEY TAMBOUR DOOR PROXIMITY SWITCHES (SUPERSEDED BY 700-25-6037 REV 01), SERVICE BULLETIN MODIFICATION - GALLEY TAMBOUR DOOR PROXIMITY SWITCH MAGNET INSTALLATION, REFER - FIGURE 1					OPTIONAL	NOT APPLICABLE
13-NOV-2019		MOS HRS/MSC - AFL					
SB 700-25-6037 PART B	ACCOMPLISH MODIFICATION - GALLEY - GALLEY TAMBOUR DOOR PROXIMITY SWITCHES (SUPERSEDED BY 700-25-6037 REV 01), SERVICE BULLETIN GALLEY TAMBOUR DOOR STOPPER INSTALLATION, REFER - FIGURE 2					OPTIONAL	NOT APPLICABLE
13-NOV-2019		MOS HRS/MSC - AFL					
SB 700-25-6037 REV 01	MODIFICATION - GALLEY - GALLEY TAMBOUR DOOR PROXIMITY SWITCHES, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
25-MAY-2020		MOS HRS/MSC - AFL					
SB 700-25-6037 REV 01 PART A	ACCOMPLISH MODIFICATION - GALLEY - GALLEY TAMBOUR DOOR PROXIMITY SWITCHES, SERVICE BULLETIN MODIFICATION - GALLEY TAMBOUR DOOR PROXIMITY SWITCH MAGNET INSTALLATION, REFER TO FIGURE 1					OPTIONAL	NOT APPLICABLE
25-MAY-2020		MOS HRS/MSC - AFL					
SB 700-25-6037 REV 01 PART B	ACCOMPLISH MODIFICATION - GALLEY - GALLEY TAMBOUR DOOR PROXIMITY SWITCHES, SERVICE BULLETIN GALLEY TAMBOUR DOOR STOPPER INSTALLATION, REFER TO FIGURE 2					OPTIONAL	NOT APPLICABLE
25-MAY-2020		MOS HRS/MSC - AFL					
SB 700-25-6038	MODIFICATION - ELECTRONIC FLIGHT BAG (EFB) DISPLAY UNITS (DU) - MOD DOT 7: INTRODUCTION OF REPLACEMENT BATTERY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
11-OCT-2019		MOS HRS/MSC - AFL		(EFF)			
SB 700-25-6039	SPECIAL CHECK/MODIFICATION - UNDERWATER LOCATING DEVICE - INSPECTION OF THE DK180 LOW FREQUENCY (8.8KHZ) UNDERWATER LOCATING DEVICE (LF-ULD), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY PRE-SB 700-25-6029. (DK180 NOT INSTALLED)
29-OCT-2020		MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-25-6039 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - UNDERWATER LOCATING DEVICE - INSPECTION OF THE DK180 LOW FREQUENCY (8.8KHZ) UNDERWATER LOCATING DEVICE (LF-ULD), SERVICE BULLETIN SPECIAL CHECK - INSPECTION OF THE SERIAL NUMBER ON LF-ULD					RECOMMENDED	NOT APPLICABLE
29-OCT-2020		MOS HRS/MSC - AFL					
SB 700-25-6039 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - UNDERWATER LOCATING DEVICE - INSPECTION OF THE DK180 LOW FREQUENCY (8.8KHZ) UNDERWATER LOCATING DEVICE (LF-ULD), SERVICE BULLETIN MODIFICATION - REPLACEMENT OF THE LF-ULD					RECOMMENDED	NOT APPLICABLE
29-OCT-2020		MOS HRS/MSC - AFL					
SB 700-25-6041	MODIFICATION - PASSENGER SEATING - APPLICATION OF LOCTITE ON PASSENGER SEAT FRAME ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - N/A BY A/C S/N
19-DEC-2023		MOS HRS/MSC - AFL		15-JAN-2025			
SB 700-25-6042	MODIFICATION - FLIGHT CREW SEATS - REPLACEMENT OF COCKPIT ROLLER SHADE ASSEMBLY, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - B-96999, THIS SB IS NOT APPLICABLE BY AIRCRAFT S/N.
24-OCT-2024		MOS HRS/MSC - AFL		28-OCT-2024			
SB 700-25-6043	MODIFICATION - PASSENGER SEATING - REPLACEMENT OF TRACK AND SWIVEL (T&S) BEZEL ON OUTBOARD ARMREST OF DOUBLE SEAT ASSEMBLIES, SERVICE BULLETIN						NOT APPLICABLE - BY A/C S/N
		MOS HRS/MSC - AFL		27-JUN-2024			
SB 700-25-6044	MODIFICATION - FLIGHT CREW SEATS - REPLACEMENT OF COMPONENTS IN THE BUNK BED ASSEMBLY, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY AIRCRAFT S/N
03-JUN-2024		MOS HRS/MSC - AFL		18-JUN-2024			
SB 700-25-6044 REV 01	MODIFICATION - FLIGHT CREW SEATS - REPLACEMENT OF COMPONENTS IN THE BUNK BED ASSEMBLY, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - N/A BY A/C S/N
31-JUL-2024		MOS HRS/MSC - AFL		15-JAN-2025			
SB 700D25-6002 REV 02	MODIFICATION - CARGO COMPARTMENT - MODIFICATION TO FACILITATE INSTALLATION OF THE BAGGAGE COMPARTMENT (SUPERSEDED BY 700D25-6002 REV 03), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
17-NOV-2014		MOS HRS/MSC - AFL		07-AUG-2015 9:12 4			
SB 700D25-6002 REV 03	MODIFICATION - CARGO COMPARTMENT - MODIFICATION TO FACILITATE INSTALLATION OF THE BAGGAGE COMPARTMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - N/R, C/W SB R02
04-JUN-2020		MOS HRS/MSC - AFL		15-JAN-2025			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700D25-6003	MODIFICATION - PROVISIONS - CARGO COMPARTMENT - INSTALLATION OF NET AND SHELF IN THE BAGGAGE COMPARTMENT (SUPERSEDED BY 700D25-6003 REV 01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
30-MAR-2012		MOS		07-AUG-2015			
		HRS/MSC	-		9:12		
		AFL			4		
SB 700D25-6003 REV 01	MODIFICATION - PROVISIONS - CARGO COMPARTMENT - INSTALLATION OF NET AND SHELF IN THE BAGGAGE COMPARTMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - N/R, C/W SB BASIC
04-JUN-2020		MOS		15-JAN-2025			
		HRS/MSC	-				
		AFL					
STC 10042987 R1	INSTALLATION OF INSULATION BLANKETS., SUPPLEMENTAL TYPE CERTIFICATE						COMPLIED WITH
		MOS		07-AUG-2015			
		HRS/MSC	-				
		AFL					
STC 10044051	MANUFACTURE AND INSTALLATION OF A PASSENGER COMPLETE AIRCRAFT INTERIOR CONFIGURATION, SUPPLEMENTAL TYPE CERTIFICATE						COMPLIED WITH
		MOS		09-SEP-2015			
		HRS/MSC	-				
		AFL					
STC SA05-68 REV 3	THERMAL ACOUSTIC INSULATION INSTALLATION, SUPPLEMENTAL TYPE CERTIFICATE					STC-SUPPLEMEN	COMPLIED WITH
		MOS		07-AUG-2015		TAL TYPE	
		HRS/MSC	-			CERTIFICATE	
		AFL					
STC SA12-40 REV 1	INSTALLATION, COMPLETE CUSTOM AIRCRAFT INTERIOR, SUPPLEMENTAL TYPE CERTIFICATE					STC-SUPPLEMEN	COMPLIED WITH
		MOS		09-SEP-2015		TAL TYPE	
		HRS/MSC	-			CERTIFICATE	
		AFL					
STC ST02167NY	INSTALLATION OF INSULATION BLANKETS FOR BD-7001A10 AIRCRFAT MODELS, SUPPLEMENTAL TYPE CERTIFICATE					STC-SUPPLEMEN	COMPLIED WITH
		MOS		09-SEP-2015		TAL TYPE	
		HRS/MSC	-			CERTIFICATE	
		AFL					
STC ST03228NY	MANUFACTURE AND INSTALLATION OF A PASSENGER COMPLETE AIRCRAFT INTERIOR CONFIGURATION., SUPPLEMENTAL TYPE CERTIFICATE						COMPLIED WITH
		MOS		09-SEP-2015			
		HRS/MSC	-				
		AFL					

CHAPTER 26 FIRE PROTECTION

ASB A700-26-6002	SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT SERVICE BULLETIN		RECOMMENDED	NOT APPLICABLE
18-APR-2013		MOS		
		HRS/MSC	-	
		AFL		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASB A700-26-6002 PART A	- SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT SERVICE BULLETIN SERIAL NUMBER VERIFICATION					RECOMMENDED	NOT APPLICABLE
18-APR-2013		MOS					
		HRS/MSC	-				
		AFL					
ASB A700-26-6002 PART B	INSPECTION SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT SERVICE BULLETIN AND/OR REPLACEMENT OF CHECK TEE FITTING(S)					RECOMMENDED	NOT APPLICABLE
18-APR-2013		MOS					
		HRS/MSC	-				
		AFL					
ASB A700-26-6002 REV 01	ICA - SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
22-JAN-2015		MOS					
		HRS/MSC	-				
		AFL					
ASB A700-26-6002 REV 01 PART A	ICA - SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT SERVICE BULLETIN SERIAL NUMBER VERIFICATION					RECOMMENDED	NOT APPLICABLE
22-JAN-2015		MOS					
		HRS/MSC	-				
		AFL					
ASB A700-26-6002 REV 01 PART B	ICA - SPECIAL CHECK/REPLACEMENT - FIRE EXTINGUISHING SYSTEM - INSPECTION OF CHECK TEE, PART NO. 446651, ALERT SERVICE BULLETIN INSPECTION AND/OR REPLACEMENT OF CHECK TEE FITTING(S)					RECOMMENDED	NOT APPLICABLE
22-JAN-2015		MOS					
		HRS/MSC	-				
		AFL					
SB 700-26-6001	MODIFICATION - FIRE EXTINGUISHING SYSTEM - REPLACEMENT OF FIRE EXTINGUISHER CONTAINER PART NO. 473776-2, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
13-MAR-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 700-26-6003 REV 01	SPECIAL CHECK/MODIFICATION - FIRE EXTINGUISHING SYSTEM - SQUIB CONNECTORS A111P2, A112P1 AND A111P3 WIRE LENGTHS (SUPERSEDED BY 700-26-6003 REV 02), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
15-FEB-2018		MOS		27-JUN-2018			
		HRS/MSC	-	631:35			
		AFL		234			
CHAPTER 27 FLIGHT CONTROLS							
SB 700-27-6002	REWORK - AILERON CONTROL SYSTEM - REPLACEMENT OF THE FLANGED BUSHINGS AND HINGE BOLT ASSEMBLY ON THE INBOARD AND OUTBOARD SIDES OF THE AILERON, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
07-MAY-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 700-27-6004 REV 01	ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
16-JUL-2012		MOS					
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-27-6004 REV 01 PART A	INSPECTION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN AND REWORK					RECOMMENDED	NOT APPLICABLE
16-JUL-2012		MOS HRS/MSC - AFL					
SB 700-27-6004 REV 01 PART B	MODIFICATION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
16-JUL-2012		MOS HRS/MSC - AFL					
SB 700-27-6004 REV 02	ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
17-JUN-2014		MOS HRS/MSC - AFL					
SB 700-27-6004 REV 02 PART A	INSPECTION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN AND REWORK					RECOMMENDED	NOT APPLICABLE
17-JUN-2014		MOS HRS/MSC - AFL					
SB 700-27-6004 REV 02 PART B	MODIFICATION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
17-JUN-2014		MOS HRS/MSC - AFL					
SB 700-27-6004 REV 03	ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO. 1 AILERON PULLEY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
28-JUL-2014		MOS HRS/MSC - AFL					
SB 700-27-6004 REV 03 PART A	INSPECTION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO. 1 AILERON PULLEY, SERVICE BULLETIN AND REWORK					RECOMMENDED	NOT APPLICABLE
28-JUL-2014		MOS HRS/MSC - AFL					
SB 700-27-6004 REV 03 PART B	MODIFICATION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO. 1 AILERON PULLEY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
28-JUL-2014		MOS HRS/MSC - AFL					
SB 700-27-6004 REV 04	ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
04-SEP-2014		MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-27-6004 REV 04 PART A	INSPECTION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN AND REWORK					RECOMMENDED	NOT APPLICABLE
04-SEP-2014		MOS HRS/MSC - AFL					
SB 700-27-6004 REV 04 PART B	MODIFICATION ICA - MODIFICATION - AILERON CONTROL SYSTEM - INSTALLATION OF COVER FOR NO.1 AILERON PULLEY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
04-SEP-2014		MOS HRS/MSC - AFL					
SB 700-27-6009 REV 01 PART A	SPECIAL CHECK/MODIFICATION - ELEVATOR CONTROL SYSTEM - INSPECT AND REPLACE (IF NECESSARY) ELEVATOR BRACKETS, PART NO. GD248-8750-3 AND GD248-8750-4, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - C/W BY PART A & PART B IS N/A
18-JUL-2017		MOS HRS/MSC - AFL		27-JUN-2018 631:35 234			
SB 700-27-6009 REV 01 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - ELEVATOR CONTROL SYSTEM - INSPECT AND REPLACE (IF NECESSARY) ELEVATOR BRACKETS, PART NO. GD248-8750-3 AND GD248-8750-4, SERVICE BULLETIN INSPECTION / NDT OF THE ELEVATOR BRACKETS					RECOMMENDED	COMPLIED WITH
18-JUL-2017		MOS HRS/MSC - AFL		27-JUN-2018 631:35 234			
SB 700-27-6009 REV 01 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - ELEVATOR CONTROL SYSTEM - INSPECT AND REPLACE (IF NECESSARY) ELEVATOR BRACKETS, PART NO. GD248-8750-3 AND GD248-8750-4, SERVICE BULLETIN REPLACEMENT OF THE ELEVATOR BRACKETS					RECOMMENDED	NOT APPLICABLE - NOT APPLICABLE AS NO ELEVATOR BRACKET WAS REPLACED
18-JUL-2017		MOS HRS/MSC - AFL		27-JUN-2018 631:35 234			
SB 700-27-6010 17-MAR-2020	MODIFICATION - STALL PROTECTION SYSTEM - ENABLE THE STICK PUSHER OVERRIDE FUNCTION OF THE MASTER DISCONNECT SWITCH FOR CONFIGURATIONS OTHER THAN JAA, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
SB 700-27-6011 22-APR-2019	MODIFICATION - FLAP SYSTEM - MLG FLAP TORQUE TUBE FLAP CONTAINMENT IMPROVEMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
SB 700-27-6012 REV 02 11-JUL-2022	SPECIAL CHECK - ELEVATOR CONTROL SYSTEM - INSPECTION OF TORQUE TUBE BEARINGS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-27-6012 REV 02 PART A 11-JUL-2022	ACCOMPLISH SPECIAL CHECK - ELEVATOR CONTROL SYSTEM - INSPECTION OF TORQUE TUBE BEARINGS, SERVICE BULLETIN BEARINGS INSPECTION					RECOMMENDED	COMPLIED WITH
		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-27-6012 REV 02 PART B	ACCOMPLISH SPECIAL CHECK - ELEVATOR CONTROL SYSTEM - INSPECTION OF TORQUE TUBE BEARINGS, SERVICE BULLETIN BEARINGS REPLACEMENT					RECOMMENDED	NOT APPLICABLE - AS BEARING CONDITION FOUND SATISFACTORY
11-JUL-2022		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-27-6014	SPECIAL CHECK - FLAP SYSTEM - INSPECTION OF FORWARD AND AFT INBOARD FLAP SPIGOT TUBES FOR CORROSION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
31-MAR-2021		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
CHAPTER 28 FUEL							
SB 700-28-6003 REV 01	MODIFICATION - FUEL TRANSFER SYSTEM - DESIGN IMPROVEMENT TO THE CENTER TRANSFER PUMP, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
14-SEP-2012		MOS HRS/MSC - AFL					
SB 700-28-6006	MODIFICATION - REFUEL / DEFUEL SYSTEM - REFUEL/DEFUEL LINE BRACKET REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-JUN-2020		MOS HRS/MSC - AFL		17-APR-2022 1468:03 546			
CHAPTER 29 HYDRAULIC POWER							
SB 700-29-6002 PART A	INSPECTION SPECIAL CHECK/REWORK - NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEM - ADDITION OF CLAMPS TO HYDRAULIC TUBES IN MLG BAY AND UNDER ACCESS PANEL 185BL, SERVICE BULLETIN OF HYDRAULIC TUBES					RECOMMENDED	NOT APPLICABLE
19-MAR-2012		MOS HRS/MSC - AFL					
SB 700-29-6002 PART B	ADJUSTMENT SPECIAL CHECK/REWORK - NO. 1, NO. 2 AND NO. 3 HYDRAULIC SYSTEM - ADDITION OF CLAMPS TO HYDRAULIC TUBES IN MLG BAY AND UNDER ACCESS PANEL 185BL, SERVICE BULLETIN OF HYDRAULIC TUBES LOCATION					RECOMMENDED	NOT APPLICABLE
19-MAR-2012		MOS HRS/MSC - AFL					
SB 700-29-6003 PART A	ACCOMPLISH MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - REPLACEMENT OF ENGINE DRIVEN PUMP (EDP) V-BAND COUPLING CLAMP, SERVICE BULLETIN INSPECTION					RECOMMENDED	NOT APPLICABLE
06-OCT-2011		MOS HRS/MSC - AFL					
SB 700-29-6003 PART B	ACCOMPLISH MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - REPLACEMENT OF ENGINE DRIVEN PUMP (EDP) V-BAND COUPLING CLAMP, SERVICE BULLETIN EDP V-BAND COUPLING CLAMP REPLACEMENT					RECOMMENDED	NOT APPLICABLE
06-OCT-2011		MOS HRS/MSC - AFL					
SB 700-29-6005	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - HYDRAULIC FIREWALL SHUT-OFF VALVES (HFSOV) INTRODUCTION OF IMPROVED ACTUATOR AS A SEPARATE LRU PART NO. 975237-501 (GX473-0126-1), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
15-JUL-2013		MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-29-6006	MODIFICATION - NO. 3 HYDRAULIC SYSTEM - REPLACEMENT OF RAT ACCMULATOR, PART NO. GX473-0100-5 WITH RAT ACCUMULATOR, PART NO. GX473-0100-7, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
27-JUN-2014		MOS					
		HRS/MSC	-				
		AFL					
SB 700-29-6007	MODIFICATION - NO. 3 HYDRAULIC SYSTEM - INSPECTION OF RAT ACCUMULATOR END CAPS, PART NO. 900094-5 (GX473-0100-5), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
18-JUL-2014		MOS					
		HRS/MSC	-				
		AFL					
SB 700-29-6007 PART A	MODIFICATION MODIFICATION - NO. 3 HYDRAULIC SYSTEM - INSPECTION OF RAT ACCUMULATOR END CAPS, PART NO. 900094-5 (GX473-0100-5), SERVICE BULLETIN - MARKING OF SUFFIX "E" AT THE END OF ACCUMULATOR SERIAL NO.					RECOMMENDED	NOT APPLICABLE
18-JUL-2014		MOS					
		HRS/MSC	-				
		AFL					
SB 700-29-6007 PART B	MODIFICATION MODIFICATION - NO. 3 HYDRAULIC SYSTEM - INSPECTION OF RAT ACCUMULATOR END CAPS, PART NO. 900094-5 (GX473-0100-5), SERVICE BULLETIN - REMOVAL - INSTALLATION OF NEW ACCUMULATOR (FOR ALL ACCUMULATORS, PART NO. 900094-5 NOT LISTED IN PART A AND WITHOUT "E" OR "ENA" SUFFIX)					RECOMMENDED	NOT APPLICABLE
18-JUL-2014		MOS					
		HRS/MSC	-				
		AFL					
SB 700-29-6008	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - NEW PRESSURE LINE AND BRACKET IN AFT EQUIPMENT BAY HYDRAULIC SYSTEM NO. 1 (SUPERSEDED BY 700-29-6008 REV 01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - 700-29-6008 COMPLIED WITH
15-JUL-2016		MOS	28-SEP-2017				
		HRS/MSC	-	485:04			
		AFL		176			
SB 700-29-6008 REV 04	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - NEW PRESSURE LINE AND BRACKET IN AFT EQUIPMENT BAY HYDRAULIC SYSTEM NO. 1, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - C/W PART A PREVIOUSLY
26-APR-2021		MOS	13-JUN-2023				
		HRS/MSC	-	1854:53			
		AFL		659			
SB 700-29-6008 REV 04 PART A	ACCOMPLISH, SERVICE BULLETIN MODIFICATION APPLICABLE TO AIRCRAFT ON WHICH BASIC ISSUE OF THIS SERVICE BULLETIN IS NOT INCORPORATED					RECOMMENDED	COMPLIED WITH
26-APR-2021		MOS	13-JUN-2023				
		HRS/MSC	-	1854:53			
		AFL		659			
SB 700-29-6008 REV 04 PART B	ACCOMPLISH MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - NEW PRESSURE LINE AND BRACKET IN AFT EQUIPMENT BAY HYDRAULIC SYSTEM NO. 1, SERVICE BULLETIN RETROACTIVE ACTION OF THIS SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
26-APR-2021		MOS	13-JUN-2023				
		HRS/MSC	-	1854:53			
		AFL		659			
SB 700-29-6008 REV 04 PART C	ACCOMPLISH MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - NEW PRESSURE LINE AND BRACKET IN AFT EQUIPMENT BAY HYDRAULIC SYSTEM NO. 1, SERVICE BULLETIN INSPECTION IN PYLON					RECOMMENDED	COMPLIED WITH
26-APR-2021		MOS	13-JUN-2023				
		HRS/MSC	-	1854:53			
		AFL		659			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-29-6009 REV 02	MODIFICATION - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - ADDITION OF SUPPORT BRACKET ON THE CASE DRAIN LINE (SUPERSEDED BY 700-29-6009 REV 03), SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH	
22-JAN-2019		MOS		22-AUG-2019			
		HRS/MSC	-	1064:58			
		AFL		367			
SB 700-29-6010	SPECIAL CHECK/REWORK - QUICK DISCONNECTS - ADDITION OF CLAMPS TO HYDRAULIC TUBES IN MLG BAY AND UNDER ACCESS PANEL 165BZ, 165DZ, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - EO NO. BD700-29-19027 R0	
10-MAY-2019		MOS		05-JUL-2019			
		HRS/MSC	-	1031:18			
		AFL		358			
SB 700-29-6010 PART A	ACCOMPLISH SPECIAL CHECK/REWORK - QUICK DISCONNECTS - ADDITION OF CLAMPS TO HYDRAULIC TUBES IN MLG BAY AND UNDER ACCESS PANEL 165BZ, 165DZ, SERVICE BULLETIN INSPECTION OF HYDRAULIC TUBES			RECOMMENDED		COMPLIED WITH - EO NO. BD700-29-19027 R0	
10-MAY-2019		MOS		05-JUL-2019			
		HRS/MSC	-	1031:18			
		AFL		358			
SB 700-29-6010 PART B	ACCOMPLISH SPECIAL CHECK/REWORK - QUICK DISCONNECTS - ADDITION OF CLAMPS TO HYDRAULIC TUBES IN MLG BAY AND UNDER ACCESS PANEL 165BZ, 165DZ, SERVICE BULLETIN INSPECTION OF LINES FOR DAMAGES AND INSTALL THE CLAMPS ON HYDRAULIC LINES			RECOMMENDED		COMPLIED WITH - EO NO. BD700-29-19027 R0	
10-MAY-2019		MOS		05-JUL-2019			
		HRS/MSC	-	1031:18			
		AFL		358			
SB 700-29-6011	SPECIAL CHECK/REWORK - NO. 1 AND NO. 2 HYDRAULIC SYSTEMS - INSPECTION OF ENGINE DRIVEN PUMP HYDRAULIC HOSES CLEARANCE, SERVICE BULLETIN			RECOMMENDED		NOT APPLICABLE	
29-NOV-2023		MOS		(EFF)			
		HRS/MSC	-				
		AFL					
CHAPTER 30 ICE AND RAIN PROTECTION							
SB 700-30-6001 REV 01	MODIFICATION - ANTI-ICING SYSTEM - PART NO. CHANGE OF THE WING ANTI-ICE VALVE (WAIV) TO GG436-4001-13, SERVICE BULLETIN			OPTIONAL		NOT APPLICABLE	
04-APR-2014		MOS					
		HRS/MSC	-				
		AFL					
CHAPTER 31 INDICATING/RECORDING SYSTEMS							
SB 700-31-6001	MODIFICATION - FLIGHT DATA RECORDING-SYSTEM - INTRODUCTION OF A QUICK ACCESS RECORDER (A/C S/N 9002 TO 9999), SERVICE BULLETIN					COMPLIED WITH	
		MOS		07-AUG-2015			
		HRS/MSC	-				
		AFL					
SB 700-31-6002 REV 01	MODIFICATION - FLIGHT DATA RECORDING (FDR) SYSTEM - INSTALLATION OF THE FORCE TRANSDUCER UNITS (FTU) OPTIONAL AND ACTIVATION OF THE CREW FORCE MEASURING SYSTEM (CFMS) 2002, SERVICE BULLETIN			OPTIONAL		NOT APPLICABLE	
04-NOV-2016		MOS					
		HRS/MSC	-				
		AFL					
CHAPTER 32 LANDING GEAR							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 605-32-003 REV 2	SPECIAL CHECK/REWORK - MAIN LANDING GEAR (MLG) SYSTEM - IMPROVED OUTER BUSHING AT THE MAIN FITTING/TRAILING ARM JOINT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - THIS SERVICE BULLETIN HAS BEEN INCORPORATED BY MESSIER-DOWTY INC ON 13 JUNE 2016 UNDER WORK ORDER 6010025. WORK WAS PERFORMED ON LEFT AND RIGHT MAIN LANDING GEARS.
		MOS			13-JUN-2016		
		HRS/MSC	-				
		AFL					
SB 605-32-003 REV 2 PART A	MODIFICATION SPECIAL CHECK/REWORK - MAIN LANDING GEAR (MLG) SYSTEM - IMPROVED OUTER BUSHING AT THE MAIN FITTING/TRAILING ARM JOINT, SERVICE BULLETIN OF BUSHING					NOT APPLICABLE	
		MOS					
		HRS/MSC	-				
		AFL					
SB 605-32-003 REV 2 PART B	REPLACEMENT SPECIAL CHECK/REWORK - MAIN LANDING GEAR (MLG) SYSTEM - IMPROVED OUTER BUSHING AT THE MAIN FITTING/TRAILING ARM JOINT, SERVICE BULLETIN OF FITTINGS					NOT APPLICABLE	
		MOS					
		HRS/MSC	-				
		AFL					
SB 605-32-003 REV 2 PART B	REPLACEMENT SPECIAL CHECK/REWORK - MAIN LANDING GEAR (MLG) SYSTEM - IMPROVED OUTER BUSHING AT THE MAIN FITTING/TRAILING ARM JOINT, SERVICE BULLETIN OF FITTINGS					RECOMMENDED	COMPLIED WITH - THIS SERVICE BULLETIN HAS BEEN INCORPORATED BY MESSIER-DOWTY INC ON 13 JUNE 2016 UNDER WORK ORDER 6010025. WORK WAS PERFORMED ON LEFT AND RIGHT MAIN LANDING GEARS.
		MOS			13-JUN-2016		
		HRS/MSC	-				
		AFL					
SB 700-32-6004	ICA - SPECIAL CHECK/MODIFICATION - BRAKE CONTROL UNIT (BCU) - INSPECTION AND REPLACEMENT OF PART NUMBER 42-965-2 WITH INCORRECT ZENER DIODES INSTALLED, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
29-APR-2013		MOS					
		HRS/MSC	-				
		AFL					
SB 700-32-6004 PART A	INSPECTION ICA - SPECIAL CHECK/MODIFICATION - BRAKE CONTROL UNIT (BCU) - INSPECTION AND REPLACEMENT OF PART NUMBER 42-965-2 WITH INCORRECT ZENER DIODES INSTALLED, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
29-APR-2013		MOS					
		HRS/MSC	-				
		AFL					
SB 700-32-6004 PART B	REMOVE ICA - SPECIAL CHECK/MODIFICATION - BRAKE CONTROL UNIT (BCU) - INSPECTION AND REPLACEMENT OF PART NUMBER 42-965-2 WITH INCORRECT ZENER DIODES INSTALLED, SERVICE BULLETIN AND REPLACE THE BCU					RECOMMENDED	NOT APPLICABLE
29-APR-2013		MOS					
		HRS/MSC	-				
		AFL					
SB 700-32-6005	MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 2 OUTBOARD BRAKE ACCUMULATOR, PART NO. GW415-1250-1 (24550-101), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
08-OCT-2014		MOS					
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-32-6005 PART A	INSPECTION MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 2 OUTBOARD BRAKE ACCUMULATOR, PART NO. GW415-1250-1 (24550-101), SERVICE BULLETIN					RECOMMENDED	
08-OCT-2014		MOS HRS/MSC AFL	3500		3500		
SB 700-32-6005 PART B	MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 2 OUTBOARD BRAKE ACCUMULATOR, PART NO. GW415-1250-1 (24550-101), SERVICE BULLETIN MODIFICATION					RECOMMENDED	
08-OCT-2014		MOS HRS/MSC AFL	3500		3500		
SB 700-32-6006	MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 3 INBOARD BRAKE ACCUMULATOR, PART NO. GW415-1200-1 (33-119500), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
09-OCT-2014		MOS HRS/MSC - AFL					
SB 700-32-6006 PART A	MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 3 INBOARD BRAKE ACCUMULATOR, PART NO. GW415-1200-1 (33-119500), SERVICE BULLETIN MODIFICATION - MARKING OF SUFFIX "E" AT THE END OF ACCUMULATOR SERIAL NO					RECOMMENDED	NOT APPLICABLE
09-OCT-2014		MOS HRS/MSC - AFL					
SB 700-32-6006 PART B	MODIFICATION - BRAKE CONTROL SYSTEM - INSPECTION OF HYDRAULIC SYSTEM NO. 3 INBOARD BRAKE ACCUMULATOR, PART NO. GW415-1200-1 (33-119500), SERVICE BULLETIN MODIFICATION - REMOVAL - INSTALLATION OF NEW ACCUMULATOR					RECOMMENDED	NOT APPLICABLE
09-OCT-2014		MOS HRS/MSC - AFL					
SB 700-32-6007	MODIFICATION - BRAKE CONTROL SYSTEM - REPLACEMENT OF NO. 3 BRAKE ACCUMULATOR, PART NO. GW415-1200-1 WITH NO. 3 BRAKE ACCUMULATOR, PART NO. GW415-1200-3, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
08-OCT-2014		MOS HRS/MSC - AFL					
SB 700-32-6010	REWORK - BRAKE CONTROL SYSTEM - APPLICATION OF SEALANT AT THE AXLE TRAILING ARM AND WHEEL SPEED TRANSDUCER-HARNESS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - APPLICATION OF SEALANT AT THE AXLE TRAILING ARM AND WHEEL SPEED TRANSDUCER - HARNESS.
01-APR-2015		MOS HRS/MSC - AFL		09-SEP-2015			
SB 700-32-6011 PART A	ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN VISUAL INSPECTION OF THE BOLT THAT SECURES THE RETRACTION ACTUATOR TO THE NLG STRUT					RECOMMENDED	NOT APPLICABLE
13-MAY-2015		MOS HRS/MSC - AFL					
SB 700-32-6011 PART B	ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN NLG STRUT IDENTIFICATION PLATE MODIFICATION NUMBER CHECK					RECOMMENDED	NOT APPLICABLE
13-MAY-2015		MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-32-6011 PART C	ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN INSTALLATION OF THE NEW ATTACHMENT HARDWARE SECURING THE RETRACTION ACTUATOR TO NLG STRUT				RECOMMENDED	NOT APPLICABLE	
13-MAY-2015		MOS					
		HRS/MSC	-				
		AFL					
SB 700-32-6011 REV 01 PART C	INSTALLATION ICA - SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN OF THE NEW ATTACHMENT HARDWARE SECURING THE RETRACTION ACTUATOR TO NLG STRUT				RECOMMENDED	NOT APPLICABLE	
26-AUG-2015		MOS					
		HRS/MSC	-				
		AFL					
SB 700-32-6011 REV 02	SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN				RECOMMENDED	NOT APPLICABLE	
06-NOV-2017		MOS					
		HRS/MSC	-				
		AFL					
SB 700-32-6011 REV 02 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN VISUAL INSPECTION OF THE BOLT THAT SECURES THE RETRACTION ACTUATOR TO THE NLG STRUT				RECOMMENDED	NOT APPLICABLE	
06-NOV-2017		MOS					
		HRS/MSC	-				
		AFL					
SB 700-32-6011 REV 02 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN NLG STRUT IDENTIFICATION PLATE MODIFICATION NUMBER CHECK				RECOMMENDED	NOT APPLICABLE	
06-NOV-2017		MOS					
		HRS/MSC	-				
		AFL					
SB 700-32-6011 REV 02 PART C	ACCOMPLISH SPECIAL CHECK/MODIFICATION - NOSE LANDING GEAR (NLG) - SAFETY DEVICE MODIFICATION AT RETRACTION ACTUATOR TO MAIN FITTING JOINT, SERVICE BULLETIN INSTALLATION OF THE NEW ATTACHMENT HARDWARE SECURING THE RETRACTION ACTUATOR TO NLG STRUT				RECOMMENDED	NOT APPLICABLE	
06-NOV-2017		MOS					
		HRS/MSC	-				
		AFL					
SB 700-32-6014 REV 01	REPAIR - NOSE WHEEL STEERING CONTROL SYSTEM - NOSEWHEEL-STEERING CONTROL SYSTEM - REPAIR OF STEERING CYLINDER LVDT CONDUIT, PART NO. 9070A0036-01, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - 700-32-6014 REV 1 COMPLIED WITH	
04-JUL-2016		MOS	28-SEP-2017				
		HRS/MSC	-	485.04			
		AFL		176			
SB 700-32-6015	SPECIAL CHECK/REWORK - MAIN LANDING GEAR (MLG) - INSPECTION OF SEALANT AT THE AXLE END CAP, SERVICE BULLETIN				RECOMMENDED	NOT APPLICABLE	
16-JUN-2017		MOS					
		HRS/MSC	-				
		AFL					
SB 700-32-6015 PART A	ACCOMPLISH SPECIAL CHECK/REWORK - MAIN LANDING GEAR (MLG) - INSPECTION OF SEALANT AT THE AXLE END CAP, SERVICE BULLETIN VISUAL CHECK OF THE SEALANT AT THE AXLE END CAP				RECOMMENDED	NOT APPLICABLE	
16-JUN-2017		MOS	(EFF)				
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-32-6015 PART B	ACCOMPLISH SPECIAL CHECK/REWORK - MAIN LANDING GEAR (MLG) - INSPECTION OF SEALANT AT THE AXLE END CAP, SERVICE BULLETIN SEALANT APPLICATION					RECOMMENDED	NOT APPLICABLE
16-JUN-2017		MOS HRS/MSC - AFL		(EFF)			
SB 700-32-6016	SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - CHECK COMPLETE
03-MAY-2019		MOS HRS/MSC - AFL		04-JUN-2019 993:18 348			
SB 700-32-6016 PART A	ACCOMPLISH SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE, SERVICE BULLETIN INSPECTION OF PART NUMBER AND SERIAL NUMBER					RECOMMENDED	COMPLIED WITH - WORK DONE
03-MAY-2019		MOS HRS/MSC - AFL		04-JUN-2019 993:18 348			
SB 700-32-6016 PART B	ACCOMPLISH SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE, SERVICE BULLETIN FIRST INSPECTION					RECOMMENDED	NOT APPLICABLE - N/R
03-MAY-2019		MOS HRS/MSC - AFL		04-JUN-2019 993:18 348			
SB 700-32-6016 PART C	ACCOMPLISH SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE, SERVICE BULLETIN SECOND INSPECTION					RECOMMENDED	NOT APPLICABLE - N/R
03-MAY-2019		MOS HRS/MSC - (s) AFL		04-JUN-2019 993:18 348			
SB 700-32-6016 PART D	ACCOMPLISH SPECIAL CHECK - MAIN LANDING GEAR - TRAILING ARM ASSEMBLY INSPECTION OF THE PAINT IN THE AXLE BORE, SERVICE BULLETIN PRIMER AND PAINT REPLACEMENT					RECOMMENDED	NOT APPLICABLE - N/R
03-MAY-2019		MOS HRS/MSC - (s) AFL		04-JUN-2019 993:18 348			
SB 700-32-6017 REV 01	MODIFICATION - BRAKE CONTROL SYSTEM - LH AND RH ASSEMBLY REPLACEMENT OF THE SWIVEL JOINT ASSEMBLIES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
13-MAR-2023		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-32-6018 REV 01	MODIFICATION - NOSE LANDING GEAR (NLG) - LOWER DRAG BRACE GROUND LOCK PIN ERROR PROOFING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
16-MAR-2022		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-32-6019 REV 01	MODIFICATION - MLG - MAIN LANDING GEAR ASSEMBLY IMPROVED RESISTANCE TO WATER INGRESS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
11-FEB-2021		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-32-6021 REV 01	MODIFICATION - NOSEWHEEL-STEERING CONTROL SYSTEM - REPLACEMENT OF THE STEERING SOLENOID VALVE, SERVICE BULLETIN					RECOMMENDED	
07-DEC-2022		MOS HRS/MSC AFL	60	(EFF)	24-NOV-2027 M		
SB 700-32-6022	MODIFICATION - BRAKE CONTROL SYSTEM - REPLACEMENT OF BRAKE CONTROL UNIT (BCU), SERVICE BULLETIN				RECOMMENDED		
25-MAY-2022		MOS HRS/MSC AFL	48	(EFF)	25-MAY-2026		
SB 700-32-6023	MODIFICATION - BRAKE CONTROL SYSTEM - INTRODUCTION OF RESTRICTOR ON THE CYLINDER PORT OF BRAKE SHUT-OFF VALVE (BSOV), SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH	
20-APR-2023		MOS HRS/MSC AFL		13-JUN-2023 1854:53 659			
VSB SB09065 REV AF	SEAT MODIFICATION - OBSERVER SEAT, VENDOR SERVICE BULLETIN					COMPLIED WITH	
		MOS HRS/MSC AFL		18-JUN-2015			
CHAPTER 33 LIGHTS							
SB 700-33-6002	SPECIAL CHECK - SERVICE COMPARTMENT LIGHTING - TORQUE CHECK OF TOGGLE SWITCHES, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH	
30-JUN-2021		MOS HRS/MSC AFL		13-JUN-2023 1854:53 659			
CHAPTER 34 NAVIGATION							
SB 700-34-6002 REV 01	MODIFICATION - TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) - INSTALLATION OF LOWER DIRECTIONAL TRAFFIC SURVEILLANCE SYSTEM (TSS) ANTENNA, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH	
14-MAY-2013		MOS HRS/MSC AFL		07-AUG-2015 9:12 4			
SB 700-34-6003 REV 01	MODIFICATION - SYNTHETIC VISION SYSTEM - INSTALLATION OF A SECOND SYNTHETIC VISION SYSTEM, SERVICE BULLETIN				OPTIONAL	NOT APPLICABLE	
24-NOV-2015		MOS HRS/MSC AFL					
SB 700-34-6004	MODIFICATION - HEAD-UP DISPLAY (HUD) SYSTEM - INSTALLATION OF HEAD-UP DISPLAY (HUD) SYSTEM, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH	
12-APR-2012		MOS HRS/MSC AFL		07-AUG-2015 9:12 4			
SB 700-34-6005 REV 01	MODIFICATION - ENHANCED VISION SYSTEM (EVS) - INSTALLATION OF EVS, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH	
21-DEC-2012		MOS HRS/MSC AFL		07-AUG-2015 9:12 4			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-34-6006	MODIFICATION - FLIGHT MANAGEMENT SYSTEM - INTRODUCTION OF HARDWARE/SOFTWARE UPDATES TO SUPPORT VNAV FUNCTIONALITY, SERVICE BULLETIN				RECOMMENDED	NOT APPLICABLE	
16-APR-2012		MOS HRS/MSC - AFL					
SB 700-34-6008 REV 01	MODIFICATION - TERRAIN AWARENESS WARNING SYSTEM (TAWS) - ACTIVATION OF WINDSHEAR DETECTION ALERT AND WINDSHEAR ESCAPE GUIDANCE, SERVICE BULLETIN				RECOMMENDED	NOT APPLICABLE	
20-AUG-2012		MOS HRS/MSC - AFL					
SB 700-34-6009	MODIFICATION - FLIGHT MANAGEMENT SYSTEM (FMS) - ACTIVATION OF FMS SBAS WAAS/LPV FUNCTION, SERVICE BULLETIN				RECOMMENDED	NOT APPLICABLE	
04-DEC-2012		MOS HRS/MSC - AFL					
SB 700-34-6010 REV 01	MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES TO SUPPORT INTRODUCTION OF FMS 3, TOLD, ECL, FMS SPEED CONTROL AND RNP AR (SUPERSEDED BY SB 700-34-6017 REV 03), SERVICE BULLETIN				INFORMATIONAL	NOT APPLICABLE	
13-SEP-2013		MOS HRS/MSC - AFL					
SB 700-34-6012	SPECIAL CHECK/MODIFICATION - DISTANCE MEASURING EQUIPMENT (DME) AND VHF COMMUNICATIONS SYSTEMS - INSPECTION OF IMPROPERLY CRIMPED TERMINAL FORK CONTACTS ON DME NO. 1 AND NO. 2 AND VHF NO. 3, SERVICE BULLETIN				OPTIONAL	NOT APPLICABLE	
05-JUN-2013		MOS HRS/MSC - AFL					
SB 700-34-6013	SPECIAL CHECK/MODIFICATION - VHF COMMUNICATION AND VHF NAVIGATION SYSTEMS - INSPECTION OF IMPROPERLY CRIMPED TERMINAL FORK CONTACTS ON VHF COMMUNICATIONS UNIT NO. 1 AND VHF NAVIGATION UNIT NO. 1, SERVICE BULLETIN				OPTIONAL	NOT APPLICABLE	
12-JUN-2013		MOS HRS/MSC - AFL					
SB 700-34-6014	SPECIAL CHECK/MODIFICATION - VHF COMMUNICATION AND VHF NAVIGATION SYSTEMS - INSPECTION OF IMPROPERLY CRIMPED TERMINAL FORK CONTACTS ON VHF COMMUNICATION UNIT NO. 2, VHF NAVIGATION UNIT NO. 2 AND AIR TRAFFIC CONTROL (ATC) TRANSPONDER (TDR), SERVICE BULLETIN				OPTIONAL	NOT APPLICABLE	
17-JUN-2013		MOS HRS/MSC - AFL					
SB 700-34-6014 REV 01	SPECIAL CHECK/MODIFICATION - VHF COMMUNICATION AND VHF NAVIGATION SYSTEMS - INSPECTION OF IMPROPERLY CRIMPED TERMINAL FORK CONTACTS ON VHF COMMUNICATION UNIT NO. 2, VHF NAVIGATION UNIT NO. 2 AND AIR TRAFFIC CONTROL (ATC) TRANSPONDER (TDR), SERVICE BULLETIN				OPTIONAL	NOT APPLICABLE	
16-JAN-2014		MOS HRS/MSC - AFL					
SB 700-34-6015	SPECIAL CHECK/MODIFICATION - RADIO ALTIMETER SYSTEM - INSPECTION OF IMPROPERLY CRIMPED TERMINAL FORK CONTACTS ON RADIO ALTIMETER TRANSCIEVERS NO. 1 AND NO. 2, SERVICE BULLETIN				OPTIONAL	NOT APPLICABLE	
17-JUN-2013		MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-34-6016	MODIFICATION - GENERAL - ACTIVATION OF THE STEEP APPROACH OPTION - GLIDEPATH ANGLES FROM 4.5 TO 5.5 DEGREES (SUPERSEDED BY 700-34-6016 REV 01), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
17-FEB-2014		HRS/MSC	-				
		AFL					
SB 700-34-6016 REV 01	MODIFICATION - GENERAL - ACTIVATION OF THE STEEP APPROACH OPTION - GLIDEPATH ANGLES FROM 4.5 TO 5.5 DEGREES (SUPERSEDED BY 700-34-6016 REV 02), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
24-JUL-2014		HRS/MSC	-				
		AFL					
SB 700-34-6016 REV 03	MODIFICATION - GENERAL - ACTIVATION OF THE STEEP APPROACH OPTION GLIDEPATH ANGLES FROM 4.5 TO 5.5 DEGREES, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS					
12-FEB-2020		HRS/MSC	-				
		AFL					
SB 700-34-6017 REV 01	MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES AND REMOVAL OF SVS LIMITATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
12-SEP-2013		HRS/MSC	-				
		AFL					
SB 700-34-6017 REV 01 PART A	ACCOMPLISH MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES AND REMOVAL OF SVS LIMITATION, SERVICE BULLETIN CTP REPLACEMENT					RECOMMENDED	NOT APPLICABLE
		MOS					
12-SEP-2013		HRS/MSC	-				
		AFL					
SB 700-34-6017 REV 01 PART B	ACCOMPLISH MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES AND REMOVAL OF SVS LIMITATION, SERVICE BULLETIN SOFTWARE LOADING					RECOMMENDED	NOT APPLICABLE
		MOS					
12-SEP-2013		HRS/MSC	-				
		AFL					
SB 700-34-6017 REV 02	MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES AND REMOVAL OF SVS LIMITATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
28-OCT-2013		HRS/MSC	-				
		AFL					
SB 700-34-6017 REV 02 PART A	ACCOMPLISH MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES AND REMOVAL OF SVS LIMITATION, SERVICE BULLETIN CTP REPLACEMENT					RECOMMENDED	NOT APPLICABLE
		MOS					
28-OCT-2013		HRS/MSC	-				
		AFL					
SB 700-34-6017 REV 02 PART B	ACCOMPLISH MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES AND REMOVAL OF SVS LIMITATION, SERVICE BULLETIN SOFTWARE LOADING					RECOMMENDED	NOT APPLICABLE
		MOS					
28-OCT-2013		HRS/MSC	-				
		AFL					
SB 700-34-6017 REV 03	MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES AND REMOVAL OF SVS LIMITATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
19-NOV-2013		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-34-6017 REV 03 PART A	MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES AND REMOVAL OF SVS LIMITATION, SERVICE BULLETIN CTP REPLACEMENT					RECOMMENDED	NOT APPLICABLE
19-NOV-2013		MOS HRS/MSC - AFL					
SB 700-34-6017 REV 03 PART B	MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES AND REMOVAL OF SVS LIMITATION, SERVICE BULLETIN SOFTWARE LOADING					RECOMMENDED	NOT APPLICABLE
19-NOV-2013		MOS HRS/MSC - AFL					
SB 700-34-6017 REV 04 PART A	MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES AND REMOVAL OF SVS LIMITATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
27-AUG-2014		MOS HRS/MSC - AFL					
SB 700-34-6017 REV 04 PART A	CHECK MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES AND REMOVAL OF SVS LIMITATION, SERVICE BULLETIN THE CTP PART NUMBERS - TAKE APPROPRIATE ACTION					RECOMMENDED	NOT APPLICABLE
27-AUG-2014		MOS HRS/MSC - AFL					
SB 700-34-6017 REV 04 PART B	REPLACE MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES AND REMOVAL OF SVS LIMITATION, SERVICE BULLETIN BOTH CONTROL TUNING PANELS (CTP) - UPLOAD NEW SOFTWARE					RECOMMENDED	NOT APPLICABLE
27-AUG-2014		MOS HRS/MSC - AFL					
SB 700-34-6017 REV 05 PART A	MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES AND REMOVAL OF SVS LIMITATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
10-FEB-2021		MOS HRS/MSC - AFL					
SB 700-34-6017 REV 05 PART A	ACCOMPLISH MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES AND REMOVAL OF SVS LIMITATION, SERVICE BULLETIN REPLACEMENT OF THE CTP ON AIRCRAFT THAT ARE POST SB 700-34-6017					RECOMMENDED	NOT APPLICABLE
10-FEB-2021		MOS HRS/MSC - AFL					
SB 700-34-6017 REV 05 PART B	ACCOMPLISH MODIFICATION - GENERAL - AVIONIC SYSTEM UPDATES AND REMOVAL OF SVS LIMITATION, SERVICE BULLETIN USB PREPARATION FOR LOADING					RECOMMENDED	NOT APPLICABLE
10-FEB-2021		MOS HRS/MSC - AFL					
SB 700-34-6018 REV 01 PART A	MODIFICATION - GENERAL - IMPLEMENTATION OF AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST OUT (ADS-B OUT) (DO-260B) AND AERONAUTICAL TELECOMMUNICATIONS NETWORK (ATN) CONTROLLER PILOT DATA-LINK COMMUNICATIONS (CPDLC) CAPABILITY (LINK2000+) (SUPERSEDED BY 700-34-6018 REV 02), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
18-MAY-2017		MOS HRS/MSC - AFL		27-JUN-2018 631:35 234			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-34-6020 REV 01	MODIFICATION - TERRAIN AWARENESS AND WARNING SYSTEM (TAWS) - CCM CSO DATABASE CHANGE FOR MODE 6 AURAL WARNINGS +6DB VOLUME INCREASE, SERVICE BULLETIN				OPTIONAL		NOT APPLICABLE
		MOS					
07-NOV-2016		HRS/MSC	-				
		AFL					
SB 700-34-6021 REV 02	MODIFICATION - GENERAL - IMPLEMENTATION OF GLOBAL VISION FLIGHT DECK AVIONICS SOFTWARE VERSION 5, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - 700-34-6021 REV 2 COMPLIED WITH	
		MOS		28-SEP-2017			
08-MAR-2017		HRS/MSC	-	485:04			
		AFL		176			
SB 700-34-6022	SPECIAL CHECK/MODIFICATION - STANDBY COMPASS SYSTEM - INSPECTION AND REPLACEMENT OF ELECTRICAL LEAD ASSEMBLY FOR STANDBY COMPASS PART NO. WL1001KCA1, SERVICE BULLETIN				RECOMMENDED	NOT APPLICABLE	
		MOS					
27-JUN-2016		HRS/MSC	-				
		AFL					
SB 700-34-6022 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - STANDBY COMPASS SYSTEM - INSPECTION AND REPLACEMENT OF ELECTRICAL LEAD ASSEMBLY FOR STANDBY COMPASS PART NO. WL1001KCA1, SERVICE BULLETIN INSPECTION ON THE STANDBY COMPASS AND LEAD ASSEMBLY				RECOMMENDED	NOT APPLICABLE	
		MOS					
27-JUN-2016		HRS/MSC	-				
		AFL					
SB 700-34-6022 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - STANDBY COMPASS SYSTEM - INSPECTION AND REPLACEMENT OF ELECTRICAL LEAD ASSEMBLY FOR STANDBY COMPASS PART NO. WL1001KCA1, SERVICE BULLETIN VISUAL CHECK OF THE \downarrow Y \uparrow SOCKET END OF THE WIRE AND ACCOMPLISH INSULATION RESISTANCE TEST				RECOMMENDED	NOT APPLICABLE	
		MOS					
27-JUN-2016		HRS/MSC	-				
		AFL					
SB 700-34-6022 PART C	ACCOMPLISH SPECIAL CHECK/MODIFICATION - STANDBY COMPASS SYSTEM - INSPECTION AND REPLACEMENT OF ELECTRICAL LEAD ASSEMBLY FOR STANDBY COMPASS PART NO. WL1001KCA1, SERVICE BULLETIN REMOVAL / INSTALLATION OF THE NEW LEAD ASSEMBLY				RECOMMENDED	NOT APPLICABLE	
		MOS					
27-JUN-2016		HRS/MSC	-				
		AFL					
SB 700-34-6023	MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF NEW GPS-4000S PART NUMBER, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH	
		MOS		03-OCT-2016			
05-JUL-2016		HRS/MSC	-	237:37			
		AFL		90			
SB 700-34-6023 PART A	ACCOMPLISH MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF NEW GPS-4000S PART NUMBER, SERVICE BULLETIN INSPECTION				RECOMMENDED	COMPLIED WITH	
		MOS		03-OCT-2016			
05-JUL-2016		HRS/MSC	-	237:37			
		AFL		90			
SB 700-34-6023 PART B	ACCOMPLISH MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF NEW GPS-4000S PART NUMBER, SERVICE BULLETIN MODIFICATION				RECOMMENDED	COMPLIED WITH	
		MOS		03-OCT-2016			
05-JUL-2016		HRS/MSC	-	237:37			
		AFL		90			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-34-6025	MODIFICATION - SYNTHETIC VISION SYSTEM (SVS) - REPLACEMENT OF SYNTHETIC VISION MODULE FOR RELIABILITY ENHANCEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
29-NOV-2016		MOS					
		HRS/MSC	-				
		AFL					
SB 700-34-6025 PART A	ACCOMPLISH MODIFICATION - SYNTHETIC VISION SYSTEM (SVS) - REPLACEMENT OF SYNTHETIC VISION MODULE FOR RELIABILITY ENHANCEMENT, SERVICE BULLETIN INSPECTION OF THE SERIAL NO. FOR THE SVM-6110(H) MODULE					RECOMMENDED	NOT APPLICABLE
29-NOV-2016		MOS					
		HRS/MSC	-				
		AFL					
SB 700-34-6025 PART B	ACCOMPLISH MODIFICATION - SYNTHETIC VISION SYSTEM (SVS) - REPLACEMENT OF SYNTHETIC VISION MODULE FOR RELIABILITY ENHANCEMENT, SERVICE BULLETIN REPLACEMENT OF THE SVM-6110(H) MODULE					RECOMMENDED	NOT APPLICABLE
29-NOV-2016		MOS					
		HRS/MSC	-				
		AFL					
SB 700-34-6025 REV 01	MODIFICATION - SYNTHETIC VISION SYSTEM (SVS) - REPLACEMENT OF SYNTHETIC VISION MODULE FOR RELIABILITY ENHANCEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
16-MAY-2018		MOS					
		HRS/MSC	-				
		AFL					
SB 700-34-6025 REV 01 PART A	ACCOMPLISH MODIFICATION - SYNTHETIC VISION SYSTEM (SVS) - REPLACEMENT OF SYNTHETIC VISION MODULE FOR RELIABILITY ENHANCEMENT, SERVICE BULLETIN INSPECTION OF THE SERIAL NO. FOR THE SVM-6110(H) MODULE					RECOMMENDED	NOT APPLICABLE
16-MAY-2018		MOS					
		HRS/MSC	-				
		AFL					
SB 700-34-6025 REV 01 PART B	ACCOMPLISH MODIFICATION - SYNTHETIC VISION SYSTEM (SVS) - REPLACEMENT OF SYNTHETIC VISION MODULE FOR RELIABILITY ENHANCEMENT, SERVICE BULLETIN REPLACEMENT OF THE SVM-6110(H) MODULE					RECOMMENDED	NOT APPLICABLE
16-MAY-2018		MOS					
		HRS/MSC	-				
		AFL					
SB 700-34-6026	MODIFICATION - TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) - TSSA-4100 TSS COASTING ERROR FIX FOR DO-260A, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - B-96999/9673 IS NOT AFFECTED BY THIS SB BECAUSE THE S/W 810-0052-013 IS ALREADY INSTALLED IN 12-DEC-2017
15-DEC-2017		MOS		26-FEB-2019			
		HRS/MSC	-	895:54			
		AFL		314			
SB 700-34-6028	SPECIAL CHECK/MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF NEW GPS-4000S PART NUMBER 822-2189-101, SERVICE BULLETIN					SUPERSEDED	NOT APPLICABLE
		MOS		14-APR-2021			
		HRS/MSC	-				
		AFL					
SB 700-34-6028 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF NEW GPS-4000S PART NUMBER 822-2189-101, SERVICE BULLETIN INSPECTION					RECOMMENDED	NOT APPLICABLE
13-JUL-2020		MOS		14-APR-2021			
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-34-6028 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - GLOBAL POSITIONING SYSTEM (GPS) - INTRODUCTION OF NEW GPS-4000S PART NUMBER 822-2189-101, SERVICE BULLETIN MODIFICATION					RECOMMENDED	NOT APPLICABLE
13-JUL-2020		MOS		14-APR-2021			
		HRS/MSC	-				
		AFL					
SB 700-34-6029	MODIFICATION - WEATHER RADAR SYSTEM - RTA-4118 - DIGITAL SIGNAL PROCESSOR (DSP) COMMUNICATION (COM) FAULT RELIABILITY IMPROVEMENT COLLINS SB RTA-41XX-34-8, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		15-JUN-2024			
		HRS/MSC	-	2175:55			
		AFL		752			
SB 700-34-6040 PART A	ACCOMPLISH, SERVICE BULLETIN INSPECT THE PART NUMBER OF THE GPS CURRENTLY INSTALLED					RECOMMENDED	COMPLIED WITH - GPS CHECKED. NOT AFFECTED
30-SEP-2024		MOS		15-OCT-2024			
		HRS/MSC	-	2223:53			
		AFL		777			
SB 700-34-6040 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN INSPECT THE PART NUMBER OF THE GPS CURRENTLY INSTALLED					RECOMMENDED	COMPLIED WITH - GPS CHECKED. NOT AFFECTED
04-OCT-2024		MOS		15-OCT-2024			
		HRS/MSC	-	2223:53			
		AFL		777			
SB 700-34-6040 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN REPLACE THE GPS UNITS, PART NO. 822-2189-101 WITH PART NO. 822-2189-102					RECOMMENDED	
04-OCT-2024		MOS		(EFF)	31-MAR-2028 M		
		HRS/MSC	DUE				
		AFL					
STC SA12-24 REV 3	INSTALLATION OF CLASS II ELECTRONIC FLIGHT BAG (SINGLE L3 COMMUNICATIONS CREWMATE 840)., SUPPLEMENTAL TYPE CERTIFICATE					COMPLIED WITH	
		MOS		07-AUG-2015			
		HRS/MSC	-				
		AFL					
CHAPTER 35 OXYGEN							
SB 700-35-6001 REV 01	ICA - MODIFICATION - OXYGEN CREW - REPLACEMENT OF FLEXIBLE RELIEF HOSES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - OXYGEN CREW - REPLACEMENT OFFLEXIBLE RELIEFHOSES.
22-JUL-2015		MOS		09-SEP-2015			
		HRS/MSC	-				
		AFL					
SB 700-35-6002	ICA - MODIFICATION - PASSENGER OXYGEN SYSTEM - OXYGEN BOX - MANIFOLD REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
30-APR-2015		MOS					
		HRS/MSC	-				
		AFL					
SB 700-35-6003	MODIFICATION - PORTABLE OXYGEN PROVISION - REPLACEMENT OF THE BRACKET OF THE OXYGEN BOTTLE BRACKET (SUPERSEDED BY 700-35-6003 REV 01), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
03-JUL-2018		MOS					
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-35-6003 REV 01	MODIFICATION - PORTABLE OXYGEN PROVISION - REPLACEMENT OF THE BRACKET OF THE OXYGEN BOTTLE BRACKET (SUPERSEDED BY 700-35-6003 REV 02), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
05-SEP-2018		MOS					
		HRS/MSC	-				
		AFL					
SB 700-35-6003 REV 02	MODIFICATION - PORTABLE OXYGEN PROVISION - REPLACEMENT OF THE BRACKET OF THE OXYGEN BOTTLE BRACKET (SUPERSEDED BY 700-35-6003 REV 03), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
23-NOV-2018		MOS					
		HRS/MSC	-				
		AFL					
SB 700-35-6003 REV 03	MODIFICATION - PORTABLE OXYGEN PROVISION - REPLACEMENT OF THE BRACKET OF THE OXYGEN BOTTLE BRACKET, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
10-MAR-2020		MOS					
		HRS/MSC	-				
		AFL					
SB 700-35-6004	MODIFICATION - OXYGEN SUPPLY SYSTEM - OXYGEN BOX MANIFOLD REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
10-DEC-2018		MOS					
		HRS/MSC	-				
		AFL					
SB 700-35-6004 REV 01	MODIFICATION - OXYGEN SUPPLY SYSTEM - OXYGEN BOX MANIFOLD REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
16-JAN-2019		MOS					
		HRS/MSC	-				
		AFL					
SB 700-35-6004 REV 02	MODIFICATION - OXYGEN SUPPLY SYSTEM - OXYGEN BOX MANIFOLD REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
05-APR-2019		MOS					
		HRS/MSC	-				
		AFL					
SB 700-35-6004 REV 03	MODIFICATION - OXYGEN SUPPLY SYSTEM - OXYGEN BOX MANIFOLD REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
31-MAY-2019		MOS					
		HRS/MSC	-				
		AFL					
SB 700-35-6004 REV 04	MODIFICATION - OXYGEN SUPPLY SYSTEM - OXYGEN BOX MANIFOLD REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
29-NOV-2019		MOS					
		HRS/MSC	-				
		AFL					
SB 700-35-6004 REV 05	SPECIAL CHECK/MODIFICATION - OXYGEN SUPPLY SYSTEM - OXYGEN BOX MANIFOLD REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
27-AUG-2021		MOS					
		HRS/MSC	-				
		AFL					
SB 700-35-6005 REV 01	MODIFICATION - OXYGEN SUPPLY SYSTEM - FLEXIBLE OXYGEN HOSE REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - WORK DONE PART NUMBER NOT EFFECT
12-FEB-2021		MOS		12-NOV-2021			
		HRS/MSC	-	1424:13			
		AFL		529			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-35-6005 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN PART NUMBER INSPECTION ON EXISTING OXYGEN SYSTEM					RECOMMENDED	COMPLIED WITH - WORK DONE. PART NUMBER NOT EFFECT
12-FEB-2021	MOS HRS/MSC - AFL	12-NOV-2021 1424:13 529					
SB 700-35-6005 REV 01 PART B	ACCOMPLISH MODIFICATION - OXYGEN SUPPLY SYSTEM - FLEXIBLE OXYGEN HOSE REPLACEMENT, SERVICE BULLETIN SCHEDULED TESTING					RECOMMENDED	NOT APPLICABLE - N/R
12-FEB-2021	MOS HRS/MSC - AFL	12-NOV-2021 1424:13 529					
SB 700-35-6005 REV 01 PART C	ACCOMPLISH, SERVICE BULLETIN MODIFICATION - FLEXIBLE OXYGEN HOSE REPLACEMENT					RECOMMENDED	NOT APPLICABLE - N/R
12-FEB-2021	MOS HRS/MSC - AFL	12-NOV-2021 1424:13 529					
SB 700-35-6006	SPECIAL CHECK/REWORK - THERAPEUTIC OXYGEN HOSE - INSPECTION FOR MINIMUM CLEARANCE BETWEEN THE HARNESS AND OXYGEN HOSE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY A/C S/N
12-JUN-2024	MOS HRS/MSC - AFL	18-JUN-2024					
CHAPTER 36 PNEUMATIC							
SB 700-36-6001 REV 01	MODIFICATION - BLEED AIR SYSTEM - REPLACEMENT OF THE BLEED-PRESSURE REGULATING-AND-SHUTOFF VALVE (PRSOV), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - C/W SB AND FOUND SATISFACTORY
16-JAN-2019	MOS HRS/MSC - AFL	13-JUN-2023 1854:53 659					
SB 700-36-6002	SPECIAL CHECK/REWORK - BLEED-AIR LEAK-DETECTION SYSTEM - SPECIAL CHECK ON THE KIDDE LEAK DETECTION LOOP ELEMENTS, SERVICE BULLETIN					RECOMMENDED	
23-DEC-2022	MOS HRS/MSC AFL	120 2000	(EFF)	23-DEC-2032 M 3727:56 M			
CHAPTER 38 WATER/WASTE							
SB 700-38-6002	MODIFICATION - WASTE SYSTEM - ADDITION OF HEATER AND INSULATION BLANKET TO THE DELTA PRESSURE (DP) SENSOR OF THE WATER TANK ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
21-JAN-2013	MOS HRS/MSC - AFL						
SB 700-38-6003 REV 01	MODIFICATION - POTABLE WATER SYSTEM - QUICK DISCONNECT INSTALLATION AT POTABLE WATER TREATMENT UNIT (PWTU), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
20-OCT-2017	MOS HRS/MSC - AFL						
SB 700-38-6004	MODIFICATION - WASTE DISPOSAL - INTRODUCTION OF IMPROVED RINSE VALVE TO PREVENT RINSE VALVE LEAKAGE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
28-MAR-2013	MOS HRS/MSC - AFL						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-38-6004 REV 01	MODIFICATION - WASTE DISPOSAL - INTRODUCTION OF IMPROVED RINSE VALVE TO PREVENT RINSE VALVE LEAKAGE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
13-NOV-2013		MOS HRS/MSC - AFL					
SB 700-38-6005	MODIFICATION - POTABLE WATER SYSTEM - INSTALLATION OF WATER TREATMENT UNIT BYPASS SWITCH, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
24-APR-2014		MOS HRS/MSC - AFL					
SB 700D38-6001	REWORK - PROVISIONS - GENERAL - REWORK INTERIOR FURNISHINGS AND STRUCTURAL PROVISIONS FOR THE WATER SYSTEM KIT INSTALLATION (SUPERSEDED BY 700D38-6001 REV 01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
30-JAN-2012		MOS HRS/MSC - AFL		07-AUG-2015 9:12 4			
CHAPTER 44 CABIN SYSTEMS							
SB 700-44-6001	MODIFICATION - CABIN ELECTRONICS SYSTEM - WIRELESS PASSENGER CONTROL UNIT (WPCU) NEW IPOD TOUCH(5) INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
02-OCT-2014		MOS HRS/MSC - AFL					
SB 700-44-6004	MODIFICATION - SATELLITE COMMUNICATIONS SYSTEM - INSTALLATION OF MODMAN POWER RELAY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
08-DEC-2017		MOS HRS/MSC - AFL					
SB 700-44-6006	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INSTALLATION OF A HONEYWELL JETWAVE™ KA BAND SATELLITE DATA SYSTEM WITH VENUE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
10-OCT-2018		MOS HRS/MSC - AFL					
SB 700-44-6006 REV 01	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INSTALLATION OF A HONEYWELL JETWAVE™ KA BAND SATELLITE DATA SYSTEM WITH VENUE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
10-OCT-2018		MOS HRS/MSC - AFL					
SB 700-44-6006 REV 02	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INSTALLATION OF A HONEYWELL JETWAVE KA BAND SATELLITE DATA SYSTEM WITH VENUE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
17-JAN-2019		MOS HRS/MSC - AFL					
SB 700-44-6006 REV 03	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INSTALLATION OF A HONEYWELL JETWAVE™ KA BAND SATELLITE DATA SYSTEM WITH VENUE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
03-MAY-2019		MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-44-6006 REV 04	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - INSTALLATION OF A HONEYWELL JETWAVE KA BAND SATELLITE DATA SYSTEM WITH VENUE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
03-JUL-2019		MOS HRS/MSC - AFL					
SB 700-44-6007	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - HONEYWELL JETWAVE KA-BAND RADIO FREQUENCY UNIT (KRFU) REPLACEMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
23-OCT-2018		MOS HRS/MSC - AFL					
SB 700-44-6007 REV 01	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - HONEYWELL JETWAVE KA-BAND RADIO FREQUENCY UNIT (KRFU) REPLACEMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
23-OCT-2018		MOS HRS/MSC - AFL					
SB 700-44-6007 REV 02	MODIFICATION - SATELLITE COMMUNICATION SYSTEM - HONEYWELL JETWAVE KA-BAND RADIO FREQUENCY UNIT (KRFU) REPLACEMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
30-NOV-2018		MOS HRS/MSC - AFL					
SB 700-44-6008	MODIFICATION - CABIN SYSTEMS - JETWAVE SYSTEMS - BLV7.1 SOFTWARE UPDATE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
03-DEC-2018		MOS HRS/MSC - AFL					
SB 700-44-6008 REV 01	MODIFICATION - CABIN SYSTEMS - JETWAVE SYSTEMS - BLV7.1 SOFTWARE UPDATE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
16-FEB-2019		MOS HRS/MSC - AFL					
SB 700-44-6008 REV 02	MODIFICATION - CABIN SYSTEMS - JETWAVE SYSTEMS - BLV7.1 SOFTWARE UPDATE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
30-MAY-2019		MOS HRS/MSC - AFL					
SB 700-44-6009	MODIFICATION - CABIN SYSTEMS - POWER SUPPLY 200 MS HOLDUP CAPACITOR IMPROVEMENT - MOD 7, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
25-JUN-2019		MOS HRS/MSC - AFL					

CHAPTER 46 INFORMATION SYSTEMS

SB 700-46-6001 REV 01	MODIFICATION - INTEGRATED FLIGHT INFORMATION SYSTEM (IFIS) - INSTALLATION OF XM GRAPHICAL WEATHER RADAR, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
23-DEC-2013		MOS HRS/MSC - AFL					
SB 700-46-6002	MODIFICATION - INTEGRATED FLIGHT INFORMATION SYSTEM (IFIS) - INTRODUCTION OF DATALINK GRAPHICAL WEATHER SYSTEM, SERVICE BULLETIN				07-AUG-2015	OPTIONAL	COMPLIED WITH
		MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-46-6003 REV 01	MODIFICATION - INTEGRATED FLIGHT INFORMATION SYSTEM (IFIS) - INTRODUCTION OF A THIRD INTEGRATED FLIGHT INFORMATION SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
21-MAR-2013		MOS HRS/MSC - AFL					
SB 700-46-6003 REV 02	MODIFICATION - INTEGRATED FLIGHT INFORMATION SYSTEM (IFIS) - INTRODUCTION OF A THIRD INTEGRATED FLIGHT INFORMATION SYSTEM, SERVICE BULLETIN				12-AUG-2015 9:12 4	OPTIONAL	COMPLIED WITH
03-DEC-2014		MOS HRS/MSC - AFL					
SB 700-46-6005 REV 02	ICA - MODIFICATION - INFORMATION MANAGEMENT SYSTEM -DEACTIVATION OF CES ETHERNET INTERFACE TO CABIN PRINTER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
18-JUN-2015		MOS HRS/MSC - AFL			07-AUG-2015 9:12 4		
PART A	VERIFY ICA - MODIFICATION - INFORMATION MANAGEMENT SYSTEM -DEACTIVATION OF CES ETHERNET INTERFACE TO CABIN PRINTER, SERVICE BULLETIN CONNECTOR PINS ARE PRESENT					RECOMMENDED	COMPLIED WITH
18-JUN-2015		MOS HRS/MSC - AFL			07-AUG-2015 9:12 4		
PART B	ICA - MODIFICATION - INFORMATION MANAGEMENT SYSTEM -DEACTIVATION OF CES ETHERNET INTERFACE TO CABIN PRINTER, SERVICE BULLETIN MODIFICATION					RECOMMENDED	COMPLIED WITH
18-JUN-2015		MOS HRS/MSC - AFL			07-AUG-2015 9:12 4		
SB 700-46-6007 REV 01	MODIFICATION - INTEGRATED FLIGHT INFORMATION SYSTEM - IMPLEMENTATION OF GLOBAL VISION FLIGHT DECK SOFTWARE VERSION 5.5.1, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
22-FEB-2022		MOS HRS/MSC - AFL			13-JUN-2023 1854:53 659		
SB 700-46-6008	MODIFICATION - INFORMATION MANAGEMENT SYSTEM (IMS), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
20-JUL-2022		MOS HRS/MSC - AFL			13-JUN-2023 1854:53 659		
CHAPTER 49 AIRBORNE AUXILIARY POWER							
SB 700-49-6003	SPECIAL CHECK/MODIFICATION - AUTOMATIC CONTROL SYSTEM - VISUAL INSPECTION AND SEALANT APPLICATION METHOD FOR THE EXHAUST GAS TEMPERATURE (EGT) SENSOR, PART NUMBER WE3876352-1 AND WE3876352-2, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - 700-49-6003 COMPLIED WITH
29-JUN-2017		MOS HRS/MSC - AFL			28-SEP-2017 485:04 176		
CHAPTER 52 DOORS							
SB 700-52-6001 REV 01	MODIFICATION - PASSENGER DOOR - INSTALLATION OF AESTHETIC SIDE COVERS (SUPERSEDED BY 700-52-6001 REV 02), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
06-JUN-2013		MOS HRS/MSC - AFL			07-AUG-2015 9:12 4		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-52-6007	ICA - MODIFICATION - AFT EQUIPMENT-COMPARTMENT DOOR - MODIFICATION TO PREVENT FUEL INGRESS INTO THE RECOMMENDED AFT EQUIPMENT BAY, SERVICE BULLETIN						NOT APPLICABLE
		MOS					
	29-MAR-2012	HRS/MSC	-				
		AFL					
SB 700-52-6008	MODIFICATION - PASSENGER DOOR - RECONFIGURATION OF THE PASSENGER DOOR EXTERNAL HANDLE DETENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
	09-NOV-2012	HRS/MSC	-				
		AFL					
SB 700-52-6008 REV 01	MODIFICATION - PASSENGER DOOR - RECONFIGURATION OF THE PASSENGER DOOR EXTERNAL HANDLE DETENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
	03-FEB-2015	HRS/MSC	-				
		AFL					
SB 700-52-6011	MODIFICATION - PASSENGER DOOR - VENT FLAP BEAM REPLACEMENT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
		MOS		13-JUN-2023			
	16-OCT-2019	HRS/MSC	-	1854:53			
		AFL		659			
SB 700-52-6012	SPECIAL CHECK/REWORK - PASSENGER DOOR - INSPECTION OF PASSENGER DOOR ACTUATOR RIGGING AND TENSATOR SPRINGS INSTALLATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		13-JUN-2023			
	20-MAY-2022	HRS/MSC	-	1854:53			
		AFL		659			
SB 700-52-6012 PART A	ACCOMPLISH SPECIAL CHECK/REWORK - PASSENGER DOOR - INSPECTION OF PASSENGER DOOR ACTUATOR RIGGING AND TENSATOR SPRINGS INSTALLATION, SERVICE BULLETIN MODIFICATION - TENSATOR SPRINGS TENSION RELEASE					RECOMMENDED	COMPLIED WITH
		MOS		13-JUN-2023			
	20-MAY-2022	HRS/MSC	-	1854:53			
		AFL		659			
SB 700-52-6012 PART B	ACCOMPLISH SPECIAL CHECK/REWORK - PASSENGER DOOR - INSPECTION OF PASSENGER DOOR ACTUATOR RIGGING AND TENSATOR SPRINGS INSTALLATION, SERVICE BULLETIN MODIFICATION - TENSATOR SPRINGS PRE-TENSIONING AND TENSION SET FOR DOOR IN OPEN POSITION					RECOMMENDED	COMPLIED WITH
		MOS		13-JUN-2023			
	20-MAY-2022	HRS/MSC	-	1854:53			
		AFL		659			
SB 700-52-6012 PART C	ACCOMPLISH SPECIAL CHECK/REWORK - PASSENGER DOOR - INSPECTION OF PASSENGER DOOR ACTUATOR RIGGING AND TENSATOR SPRINGS INSTALLATION, SERVICE BULLETIN MODIFICATION - CABLES CONNECTION					RECOMMENDED	COMPLIED WITH
		MOS		13-JUN-2023			
	20-MAY-2022	HRS/MSC	-	1854:53			
		AFL		659			
CHAPTER 53 FUSELAGE							
ASB A700-53-6004	SPECIAL CHECK/REWORK - BELLY FAIRINGS - BELLY FAIRINGS FASTENERS ENGAGEMENT CHECK, ALERT SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS					
	22-FEB-2012	HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASB A700-53-6004 PART A	INSPECTION SPECIAL CHECK/REWORK - BELLY FAIRINGS - BELLY FAIRINGS FASTENERS ENGAGEMENT CHECK, ALERT SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
22-FEB-2012		DAY(S)					
		HRS/MSC	-				
		AFL					
ASB A700-53-6004 PART B	REWORK SPECIAL CHECK/REWORK - BELLY FAIRINGS - BELLY FAIRINGS FASTENERS ENGAGEMENT CHECK, ALERT SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
22-FEB-2012		DAY(S)					
		HRS/MSC	-				
		AFL					
ASB A700-53-6004 PART C	REPLACEMENT SPECIAL CHECK/REWORK - BELLY FAIRINGS - BELLY FAIRINGS FASTENERS ENGAGEMENT CHECK, ALERT SERVICE BULLETIN OF FAULTY FASTENERS					RECOMMENDED	NOT APPLICABLE
22-FEB-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 700-53-6006	SPECIAL CHECK/REWORK - AFT FUSELAGE - REWORK WING/FUSELAGE FAIRING SILL TO PREVENT CORROSION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
15-OCT-2012		MOS					
		HRS/MSC	-				
		AFL					
SB 700-53-6007 REV 01	SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY AND APU DOORS FOR CORROSION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
13-JAN-2017		MOS					
		HRS/MSC	-				
		AFL					
SB 700-53-6007 REV 01 PART A	ACCOMPLISH SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY AND APU DOORS FOR CORROSION, SERVICE BULLETIN DETAILED VISUAL INSPECTION (DVI) OF THE TAILCONE ASSEMBLY					RECOMMENDED	NOT APPLICABLE
13-JAN-2017		MOS		(EFF)			
		HRS/MSC	-				
		AFL					
SB 700-53-6007 REV 01 PART B	ACCOMPLISH SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY AND APU DOORS FOR CORROSION, SERVICE BULLETIN LOCAL REWORK OF THE TAILCONE ASSEMBLY					RECOMMENDED	NOT APPLICABLE
13-JAN-2017		MOS		(EFF)			
		HRS/MSC	-				
		AFL					
SB 700-53-6007 REV 01 PART C	ACCOMPLISH SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY AND APU DOORS FOR CORROSION, SERVICE BULLETIN MAJOR REWORK OF THE FORWARD/AFT TAILCONE AND END CAP SKINS					RECOMMENDED	NOT APPLICABLE
13-JAN-2017		MOS		(EFF)			
		HRS/MSC	-				
		AFL					
SB 700-53-6007 REV 01 PART D	ACCOMPLISH SPECIAL CHECK/REWORK - EMPENNAGE/TAIL - INSPECTION OF TAILCONE ASSEMBLY AND APU DOORS FOR CORROSION, SERVICE BULLETIN MAJOR REWORK OF THE APU DOOR SKINS					RECOMMENDED	NOT APPLICABLE
13-JAN-2017		MOS		(EFF)			
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-53-6008 REV 01	MODIFICATION - BELLY FAIRINGS - REPLACEMENT OF ATTACHMENTS FOR THE ACCESS PANELS, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - 700-53-6008 R1 COMPLIED WITH	
16-DEC-2016		MOS HRS/MSC - AFL		28-SEP-2017 485:04 176			
SB 700-53-6009	SPECIAL CHECK/REWORK - BELLY FAIRINGS - INSPECT FORWARD AND MIDDLE ACCESS PANEL (181BB) AND (183BB) FOR DRAINAGE HOLE BLOCKAGE, AND IF NECESSARY REMOVE SEALANT, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - CARRY OUT PART A DO NOT HAVE AERODYNAMIC SEALANT PART B N/A	
17-MAY-2017		MOS HRS/MSC - AFL		19-JUN-2017 430:01 157			
SB 700-53-6009 PART A	ACCOMPLISH SPECIAL CHECK/REWORK - BELLY FAIRINGS - INSPECT FORWARD AND MIDDLE ACCESS PANEL (181BB) AND (183BB) FOR DRAINAGE HOLE BLOCKAGE, AND IF NECESSARY REMOVE SEALANT, SERVICE BULLETIN INSPECTION OF SEALANT			RECOMMENDED		COMPLIED WITH - WORK ACCOMPLISHED AND DO NOT HAVE AERODYNAMIC SEALANT	
17-MAY-2017		MOS HRS/MSC - AFL		19-JUN-2017 430:01 157			
SB 700-53-6009 PART B	ACCOMPLISH SPECIAL CHECK/REWORK - BELLY FAIRINGS - INSPECT FORWARD AND MIDDLE ACCESS PANEL (181BB) AND (183BB) FOR DRAINAGE HOLE BLOCKAGE, AND IF NECESSARY REMOVE SEALANT, SERVICE BULLETIN REWORK - REMOVAL OF AERODYNAMIC SEALANT			RECOMMENDED		NOT APPLICABLE - N/A	
17-MAY-2017		MOS HRS/MSC - AFL		19-JUN-2017 430:01 157			
SB 700-53-6010	MODIFICATION - AFT FUSELAGE - REPLACEMENT AND REINFORCEMENT OF THE RUDDER QUADRANT BOX ASSEMBLY HALF RIBS, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH	
01-OCT-2018		MOS HRS/MSC - AFL		22-AUG-2019 1064:58 367			
SB 700-53-6012	SPECIAL CHECK - AFT FUSELAGE - INSPECTION OF THE RUDDER QUADRANT BOX ASSEMBLY, SERVICE BULLETIN					NOT APPLICABLE	
01-OCT-2018		MOS HRS/MSC - AFL		22-AUG-2019 1064:58 367			
SB 700-53-6013 REV 01	MODIFICATION - AUXILIARY POWER UNIT (APU) ACCESS DOORS - MODIFICATION OF APU ACCESS DOORS AND FORWARD/AFT TAILCONE TO IMPROVE DRAINAGE AND PREVENT CORROSION, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - PART B & C, PART A NOT APPLICABLE BY A/C SERIAL NUMBER	
03-APR-2019		MOS HRS/MSC - AFL		22-AUG-2019 1064:58 367			
SB 700-53-6013 REV 01 PART A	ACCOMPLISH, SERVICE BULLETIN LEFT AND RIGHT AFT TAILCONE SKIN MODIFICATION			RECOMMENDED		NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER	
03-APR-2019		MOS HRS/MSC - AFL		22-AUG-2019 1064:58 367			
SB 700-53-6013 REV 01 PART B	ACCOMPLISH, SERVICE BULLETIN APPLY THE CORROSION INHIBITING COMPOUND (CIC) ON FORWARD AND AFT TAILCONE STRUCTURES			RECOMMENDED		COMPLIED WITH	
03-APR-2019		MOS HRS/MSC - AFL		22-AUG-2019 1064:58 367			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-53-6013 REV 01 PART C	ACCOMPLISH, SERVICE BULLETIN APU ACCESS DOOR MODIFICATION AND APPLICATION OF CIC					RECOMMENDED	COMPLIED WITH
03-APR-2019	MOS HRS/MSC - AFL			22-AUG-2019 1064:58 367			
CHAPTER 55 STABILIZERS							
SB 700-55-6001	MODIFICATION - HORIZONTAL STABILIZER - ADDITION OF DRAINAGE HOLES TO ELIMINATE WATER ACCUMULATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
11-OCT-2012	MOS HRS/MSC - AFL						
SB 700-55-6002 REV 03 PART A	MODIFICATION - VERTICAL STABILIZER - MODIFICATION OF BULLET AND DORSAL FAIRINGS TO IMPROVE DRAINAGE AND PREVENT CORROSION, SERVICE BULLETIN (APPLICABLE TO AIRCRAFT SERIAL NO. 9313, 9381 AND 9432 TO 9805)					RECOMMENDED	COMPLIED WITH
17-MAY-2018	MOS HRS/MSC - AFL			22-AUG-2019 1064:58 367			
SB 700-55-6002 REV 03 PART B	ACCOMPLISH MODIFICATION - VERTICAL STABILIZER - MODIFICATION OF BULLET AND DORSAL FAIRINGS TO IMPROVE DRAINAGE AND PREVENT CORROSION, SERVICE BULLETIN REPLACEMENT OF THE NUTPLATE RETAINERS (APPLICABLE TO AIRCRAFT SERIAL NO. 9313, 9381 AND 9432 TO 9791)					RECOMMENDED	COMPLIED WITH
17-MAY-2018	MOS HRS/MSC - AFL			22-AUG-2019 1064:58 367			
SB 700-55-6002 REV 03 PART C	ACCOMPLISH MODIFICATION - VERTICAL STABILIZER - MODIFICATION OF BULLET AND DORSAL FAIRINGS TO IMPROVE DRAINAGE AND PREVENT CORROSION, SERVICE BULLETIN DORSAL FAIRING MODIFICATION (APPLICABLE TO AIRCRAFT SERIAL NO. 9313, 9381 AND 9432 TO 9791)					RECOMMENDED	COMPLIED WITH
17-MAY-2018	MOS HRS/MSC - AFL			22-AUG-2019 1064:58 367			
CHAPTER 56 WINDOWS							
SB 700-56-6001	SPECIAL CHECK/REWORK - FLIGHT COMPARTMENT - INSPECT THE WINDSHIELD/SIDE WINDOW AND IF NECESSARY REPAIR SEAL, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
28-MAR-2013	MOS HRS/MSC - AFL						
SB 700-56-6002 04-JUN-2018	MODIFICATION - ELECTRIC WINDOW SHADE ASSEMBLY - REPLACEMENT OF SHADE RAIL CLIP ASSEMBLY, PART NO. GXIV-14-83 WITH PART NO. GXIV-14-45 (ON HOLD), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
	MOS HRS/MSC - AFL						
CHAPTER 57 WINGS							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-57-6001	MODIFICATION - GENERAL - APPLICATION OF ADDITIONAL SEALANT AND ADD WATER DRAINAGE IN THE COLLECTOR BOX, SERVICE BULLETIN				RECOMMENDED	NOT APPLICABLE	
		MOS					
07-MAY-2012		HRS/MSC	-				
		AFL					
SB 700-57-6002	SPECIAL CHECK/MODIFICATION - LEADING EDGES -REPLACEMENT OF ATTACHMENT ANGLES AND MODIFICATION OF SHROUD PANEL MOUNTING HOLES, SERVICE BULLETIN				RECOMMENDED	NOT APPLICABLE	
		MOS					
08-NOV-2012		HRS/MSC	-				
		AFL					
SB 700-57-6003 REV 01	MODIFICATION - FLAPS - INSPECTION AND REPLACEMENT OF THE INNER FLAPS AUXILIARY-RIB BUSHING, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - C/W BY PART A & PART B IS N/A	
		MOS		27-JUN-2018			
18-OCT-2017		HRS/MSC	-	631:35			
		AFL		234			
SB 700-57-6003 REV 01 PART A	ACCOMPLISH MODIFICATION - FLAPS - INSPECTION AND REPLACEMENT OF THE INNER FLAPS AUXILIARY-RIB BUSHING, SERVICE BULLETIN INSPECTION OF THE SPIGOT TUBE BUSHING FOR MIGRATION				RECOMMENDED	COMPLIED WITH	
		MOS		27-JUN-2018			
18-OCT-2017		HRS/MSC	-	631:35			
		AFL		234			
SB 700-57-6003 REV 01 PART B	ACCOMPLISH MODIFICATION - FLAPS - INSPECTION AND REPLACEMENT OF THE INNER FLAPS AUXILIARY-RIB BUSHING, SERVICE BULLETIN REPLACEMENT OF THE SPIGOT TUBE BUSHING(S)				RECOMMENDED	NOT APPLICABLE - SB 700-57-6003 R1 PART B NOT APPLICABLE AS NO BUSHING MIGRATED FOUND ON PART A	
		MOS		27-JUN-2018			
18-OCT-2017		HRS/MSC	-	631:35			
		AFL		234			
SB 700-57-6005 REV 01	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INNER FLAPS, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - C/W BY PART A & PART B, PART C IS N/A	
		MOS		27-JUN-2018			
26-APR-2018		HRS/MSC	-	631:35			
		AFL		234			
SB 700-57-6005 REV 01 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INNER FLAPS, SERVICE BULLETIN INSPECTION OF INNER FLAP FOR CORROSION				RECOMMENDED	COMPLIED WITH	
		MOS		27-JUN-2018			
26-APR-2018		HRS/MSC	-	631:35			
		AFL		234			
SB 700-57-6005 REV 01 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INNER FLAPS, SERVICE BULLETIN INNER FLAP CORROSION PREVENTION				RECOMMENDED	COMPLIED WITH	
		MOS		27-JUN-2018			
26-APR-2018		HRS/MSC	-	631:35			
		AFL		234			
SB 700-57-6005 REV 01 PART C	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INNER FLAPS, SERVICE BULLETIN INNER FLAP - CORROSION REMOVAL REWORK				RECOMMENDED	NOT APPLICABLE - SB 700-57-6005 R1 PART C NOT APPLICABLE DUE TO NO CORROSION FOUND	
		MOS		27-JUN-2018			
26-APR-2018		HRS/MSC	-	631:35			
		AFL		234			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-57-6005 REV 02	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
09-JUL-2020		MOS		28-NOV-2020			
		HRS/MSC	-	1293:08			
		AFL		471			
SB 700-57-6005 REV 02 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN INSPECTION OF INBOARD FLAP FOR CORROSION					RECOMMENDED	COMPLIED WITH - REFER SOCN 0021 AND 0022 FOR DETAILS COMPLIED
09-JUL-2020		MOS		28-NOV-2020			
		HRS/MSC	-	1293:08			
		AFL		471			
SB 700-57-6005 REV 02 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN INBOARD FLAP DRAINAGE IMPROVEMENT					RECOMMENDED	NOT APPLICABLE - ALREADY PERFORMED TO CARRY OUT PART D ONLY
09-JUL-2020		MOS		28-NOV-2020			
		HRS/MSC	-	1293:08			
		AFL		471			
SB 700-57-6005 REV 02 PART C	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN INBOARD FLAP CORROSION PREVENTION					RECOMMENDED	NOT APPLICABLE - TO COMPLY PART D ONLY
09-JUL-2020		MOS		28-NOV-2020			
		HRS/MSC	-	1293:08			
		AFL		471			
SB 700-57-6005 REV 02 PART D	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN INBOARD FLAP - CORROSION REMOVAL/REWORK					RECOMMENDED	COMPLIED WITH - SATISFACTORY
09-JUL-2020		MOS		28-NOV-2020			
		HRS/MSC	-	1293:08			
		AFL		471			
SB 700-57-6005 REV 02 PART E	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN INBOARD FLAP DRAIN HOLE COVERS INSTALLATION					RECOMMENDED	NOT APPLICABLE - DUE ALREADY ACCOMPLISHED PREVIOUSLY
09-JUL-2020		MOS		28-NOV-2020			
		HRS/MSC	-	1293:08			
		AFL		471			
SB 700-57-6005 REV 03	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
11-DEC-2020		MOS		13-JUN-2023			
		HRS/MSC	-	1854:53			
		AFL		659			
SB 700-57-6005 REV 03 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN INSPECTION OF INBOARD FLAP FOR CORROSION					RECOMMENDED	COMPLIED WITH
11-DEC-2020		MOS		13-JUN-2023			
		HRS/MSC	-	1854:53			
		AFL		659			
SB 700-57-6005 REV 03 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN INBOARD FLAP DRAINAGE IMPROVEMENT					RECOMMENDED	NOT APPLICABLE - DUE TO COMPLIED WITH SB PART D
11-DEC-2020		MOS		13-JUN-2023			
		HRS/MSC	-	1854:53			
		AFL		659			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-57-6005 REV 03 PART C	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN INBOARD FLAP CORROSION PREVENTION					RECOMMENDED	NOT APPLICABLE - DUE TO PART D PERFORMED
11-DEC-2020		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-57-6005 REV 03 PART D	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN INBOARD FLAP - CORROSION REMOVAL/REWORK					RECOMMENDED	COMPLIED WITH - PREVIOUSLY COMPLIED WITH
11-DEC-2020		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-57-6005 REV 03 PART E	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - INBOARD FLAPS, SERVICE BULLETIN INBOARD FLAP DRAIN HOLE COVERS INSTALLATION					RECOMMENDED	NOT APPLICABLE - DUE TO PART D PERFORMED
11-DEC-2020		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-57-6006	SPECIAL CHECK/REWORK - FLAP - CHAFING PROTECTION AT FLAP CANOE FAIRING (W.S. 404.00) (SUPERSEDED BY 700-57-6006 REV 01), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
10-JAN-2018		MOS HRS/MSC - AFL		22-AUG-2019 1064:58 367			
SB 700-57-6007	MODIFICATION - GENERAL - WING-TANK ACCESS PANEL AND WING-PLANK FRETTING CORROSION PREVENTION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
03-MAR-2020		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-57-6008 REV 01	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - MIDDLE FLAP, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
28-SEP-2021		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-57-6008 REV 01 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - MIDDLE FLAP, SERVICE BULLETIN MIDDLE FLAP DRAINAGE IMPROVEMENT					RECOMMENDED	COMPLIED WITH
28-SEP-2021		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-57-6008 REV 01 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - MIDDLE FLAP, SERVICE BULLETIN INSPECTION OF MIDDLE FLAP FOR CORROSION					RECOMMENDED	COMPLIED WITH - FOUND CORROSION REFER TO SVO 12805625, 12804626, 12804627 FOR WORK DETAILS.
28-SEP-2021		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-57-6008 REV 01 PART C	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - MIDDLE FLAP, SERVICE BULLETIN MIDDLE FLAP CORROSION PREVENTION					RECOMMENDED	NOT APPLICABLE - DUE TO CORROSION FOUND DURING PART B INSPECTION
28-SEP-2021		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-57-6008 REV 01 PART D	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - MIDDLE FLAP, SERVICE BULLETIN MIDDLE FLAP - CORROSION REMOVAL/REWORK					RECOMMENDED	COMPLIED WITH
28-SEP-2021		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-57-6008 REV 01 PART E	ACCOMPLISH, SERVICE BULLETIN MIDDLE FLAP - LEADING EDGE REWORK					RECOMMENDED	COMPLIED WITH
28-SEP-2021		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-57-6008 REV 01 PART F	ACCOMPLISH, SERVICE BULLETIN MIDDLE FLAP - TRAILING EDGE REWORK					RECOMMENDED	COMPLIED WITH
28-SEP-2021		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-57-6009 REV 01	SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - OUTER FLAPS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
28-SEP-2021		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-57-6009 REV 01 PART A	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - OUTER FLAPS, SERVICE BULLETIN OUTER FLAP DRAINAGE IMPROVEMENT					RECOMMENDED	COMPLIED WITH
28-SEP-2021		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-57-6009 REV 01 PART B	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - OUTER FLAPS, SERVICE BULLETIN INSPECTION OF OUTER FLAP FOR CORROSION					RECOMMENDED	COMPLIED WITH
28-SEP-2021		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-57-6009 REV 01 PART C	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - OUTER FLAPS, SERVICE BULLETIN OUTER FLAP CORROSION PREVENTION					RECOMMENDED	NOT APPLICABLE - DUE TO CORROSION FOUND DURING PART B INSPECTION
28-SEP-2021		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-57-6009 REV 01 PART D	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - OUTER FLAPS, SERVICE BULLETIN OUTER FLAP - CORROSION REMOVAL/REWORK					RECOMMENDED	COMPLIED WITH
28-SEP-2021		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-57-6009 REV 01 PART E	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - OUTER FLAPS, SERVICE BULLETIN REPLACE THE NUTPLATES LOCATED IN THE LEADING EDGE					RECOMMENDED	COMPLIED WITH
28-SEP-2021		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-57-6009 REV 01 PART F	ACCOMPLISH SPECIAL CHECK/MODIFICATION - FLAPS - CORROSION PROTECTION AND DRAINAGE IMPROVEMENT FOR THE FLAPS - OUTER FLAPS, SERVICE BULLETIN REPLACE THE NUTPLATES LOCATED IN THE TRAILING EDGE					RECOMMENDED	COMPLIED WITH
28-SEP-2021		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
SB 700-57-6010	MODIFICATION - OUTER WING - INSTALLATION OF DRAIN HOLE COVERS ON MIDDLE AND OUTER FLAPS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
29-NOV-2021		MOS HRS/MSC - AFL		13-JUN-2023 1854:53 659			
CHAPTER 71 POWER PLANT							
SB 700-71-6001	MODIFICATION - FIXED COWLS - INTRODUCTION OF A DRAINAGE HOLE IN THE FRONT MOUNT ACCESS PANEL ON THE FIXED COWL, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
06-MAY-2013		MOS HRS/MSC - AFL					
SB 700-71-6001 REV 01	MODIFICATION - FIXED COWLS - INTRODUCTION OF A DRAINAGE HOLE IN THE FRONT MOUNT ACCESS PANEL ON THE FIXED COWL, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
10-FEB-2014		MOS HRS/MSC - AFL					
SB 700-71-6001 REV 01 PART A	REMOVE MODIFICATION - FIXED COWLS - INTRODUCTION OF A DRAINAGE HOLE IN THE FRONT MOUNT ACCESS PANEL ON THE FIXED COWL, SERVICE BULLETIN THE ACCESS PANEL - DRILL A DRAIN HOLE IN THE ACCESS PANEL AND FIXED COWL ON THE AIRCRAFT - IDENTIFY THE ACCESS PANEL AND FIXED COWL AND INSTALL THE ACCESS PANEL					RECOMMENDED	NOT APPLICABLE
10-FEB-2014		MOS HRS/MSC - AFL					
SB 700-71-6001 REV 01 PART B	REIDENTIFY MODIFICATION - FIXED COWLS - INTRODUCTION OF A DRAINAGE HOLE IN THE FRONT MOUNT ACCESS PANEL ON THE FIXED COWL, SERVICE BULLETIN THE FIXED COWL ACCESS PANEL ON THE RH NACELLE					RECOMMENDED	NOT APPLICABLE
10-FEB-2014		MOS HRS/MSC - AFL					
SB 700-71-6002	SPECIAL CHECK/REWORK - REAR MOUNT - INSPECT THE RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - INSPECT THE RETAINING BOLT AND NUT ON THE LOWER / UPPER ENGINE REAR MOUNT ASSEMBLY NORMAL.
31-MAY-2016		MOS HRS/MSC - AFL		28-JUN-2016 166:12 58			
SB 700-71-6002 PART A	ACCOMPLISH SPECIAL CHECK/REWORK - REAR MOUNT - INSPECT THE RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN INSPECTION OF THE ENGINE REAR MOUNT ASSEMBLIES					RECOMMENDED	COMPLIED WITH - INSPECT NORMAL
31-MAY-2016		MOS HRS/MSC - AFL		28-JUN-2016 166:12 58			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-71-6002 PART B	ACCOMPLISH SPECIAL CHECK/REWORK - REAR MOUNT - INSPECT THE RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN REPLACEMENT OF THE HARDWARE					RECOMMENDED	NOT APPLICABLE
31-MAY-2016		MOS		28-JUN-2016			
		HRS/MSC	-	166:12			
		AFL		58			
SB 700-71-6002 REV 01	SPECIAL CHECK/REWORK - REAR MOUNT - INSPECT THE RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - 700-71-6002
30-JUN-2016		MOS		28-JUN-2016			
		HRS/MSC	-	166:12			
		AFL		58			
SB 700-71-6002 REV 01 PART A	ACCOMPLISH SPECIAL CHECK/REWORK - REAR MOUNT - INSPECT THE RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN INSPECTION OF THE ENGINE REAR MOUNT ASSEMBLIES					RECOMMENDED	COMPLIED WITH - 700-71-6002
30-JUN-2016		MOS		28-JUN-2016			
		HRS/MSC	-	166:12			
		AFL		58			
SB 700-71-6002 REV 01 PART B	ACCOMPLISH SPECIAL CHECK/REWORK - REAR MOUNT - INSPECT THE RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN REPLACEMENT OF THE HARDWARE					RECOMMENDED	COMPLIED WITH - 700-71-6002
30-JUN-2016		MOS		28-JUN-2016			
		HRS/MSC	-	166:12			
SB 700-71-6003	MODIFICATION - REAR MOUNT - REPLACEMENT OF RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - WORK ACCOMPLISHED
05-DEC-2016		MOS		06-JAN-2017			
		HRS/MSC	-	303:17			
		AFL		120			
SB 700-71-6003 PART A	ACCOMPLISH MODIFICATION - REAR MOUNT - REPLACEMENT OF RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN MEASUREMENT OF THE GAPS ON THE ENGINE REAR MOUNT ASSEMBLY HARDWARE					RECOMMENDED	NOT APPLICABLE - N/A DUE TO POST SB 700-73-6002
05-DEC-2016		MOS		06-JAN-2017			
		HRS/MSC	-	303:17			
		AFL		120			
SB 700-71-6003 PART B	ACCOMPLISH MODIFICATION - REAR MOUNT - REPLACEMENT OF RETAINING BOLT AND NUT ON THE LOWER/UPPER ENGINE REAR MOUNT ASSEMBLY, SERVICE BULLETIN REPLACEMENT OF THE ENGINE REAR MOUNT ASSEMBLY HARDWARE					RECOMMENDED	COMPLIED WITH - WORK ACCOMPLISHED
05-DEC-2016		MOS		06-JAN-2017			
		HRS/MSC	-	303:17			
		AFL		120			
SB 700-71-6005	SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		17-APR-2022			
		HRS/MSC	-	1468:03			
		AFL		546			
SB 700-71-6005 PART A	ACCOMPLISH SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15811) AT THE UPPER AND LOWER SIDE OF FRONT MOUNT BEAM					RECOMMENDED	COMPLIED WITH
14-DEC-2020		MOS		17-APR-2022			
		HRS/MSC	-	1468:03			
		AFL		546			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 700-71-6005 PART B	ACCOMPLISH SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15808) AT THE THRUST STRUT FRONT LOCATION				RECOMMENDED	COMPLIED WITH	
14-DEC-2020		MOS HRS/MSC AFL		17-APR-2022 1468:03 546			
SB 700-71-6005 PART C	ACCOMPLISH SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15823) AT THE THRUST STRUT AIRCRAFT PYLON INTERFACE				RECOMMENDED	COMPLIED WITH	
14-DEC-2020		MOS HRS/MSC AFL		17-APR-2022 1468:03 546			
SB 700-71-6005 PART D	ACCOMPLISH SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15804) AT THE FRONT MOUNT BEAM INTERFACE WITH THE AIRCRAFT PYLON UPPER AND LOWER INSTALLATION				RECOMMENDED	COMPLIED WITH	
14-DEC-2020		MOS HRS/MSC AFL		17-APR-2022 1468:03 546			
SB 700-71-6005 PART E	ACCOMPLISH SPECIAL CHECK - FRONT AND REAR ENGINE MOUNT ASSEMBLIES - INSPECTION OF BUSHINGS ON THE ENGINE MOUNT SYSTEM, SERVICE BULLETIN INSPECTION OF SLIDING BUSHING (BRR15841) AT THE REAR MOUNT BEAM INTERFACE WITH THE AIRCRAFT PYLON UPPER AND LOWER INSTALLATION				RECOMMENDED	COMPLIED WITH	
14-DEC-2020		MOS HRS/MSC AFL		17-APR-2022 1468:03 546			
CHAPTER 72 ENGINE							
ASB A700-72-6001 REV 02	ICA - REWORK - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL-PUMP SPLINED COUPLING, ALERT SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH	
28-MAR-2017		MOS HRS/MSC AFL		18-DEC-2014		4000 M	
CHAPTER 73 ENGINE FUEL AND CONTROL							
SB 700-73-6002	MODIFICATION - FULL-AUTHORITY DIGITAL ENGINE-CONTROL (FADEC) SYSTEM - EEC SOFTWARE UPGRADE OF VERSION X2.0, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - C/W BY PART A & PART B	
04-OCT-2016		MOS HRS/MSC AFL		28-SEP-2017 485:04 176			
SB 700-73-6002 PART A	ACCOMPLISH MODIFICATION - FULL-AUTHORITY DIGITAL ENGINE-CONTROL (FADEC) SYSTEM - EEC SOFTWARE UPGRADE OF VERSION X2.0, SERVICE BULLETIN INSPECT THE EEC TYPE NO. AND AIRCRAFT SETUP				RECOMMENDED	COMPLIED WITH - 700-73-6002 PART A	
04-OCT-2016		MOS HRS/MSC AFL		28-SEP-2017 485:04 176			
SB 700-73-6002 PART B	ACCOMPLISH MODIFICATION - FULL-AUTHORITY DIGITAL ENGINE-CONTROL (FADEC) SYSTEM - EEC SOFTWARE UPGRADE OF VERSION X2.0, SERVICE BULLETIN MODIFICATION - UPGRADE OF THE EEC				RECOMMENDED	COMPLIED WITH - 700-73-6002 PART B	
04-OCT-2016		MOS HRS/MSC AFL		28-SEP-2017 485:04 176			
CHAPTER 901 QA AUDIT MISSING INFORMATION							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SRPSA 15630	NEEDING CLARIFICATION ON WING INBOARD LEADING EDGE SCREW HOLES	MOS HRS/MSC - AFL		12-AUG-2015		CUSTOMER CODE COMPLIED WITH	

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
APPLIANCE - 9673/B-96999							
CHAPTER 23 COMMUNICATIONS							
EASA 2007-0156	APPLIANCE AD - COMMUNICATION - COMM UNITS & TRANSPONDERS - MODIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT.
14-JUN-2007	MOS HRS/MSC - AFL			18-DEC-2014 0 0			
EASA 2007-0156 PARA (1)(A)	AMEND THE APPLICABLE AIRPLANE FLIGHT MANUAL (FOR AEROPLANES EQUIPPED WITH HONEYWELL RCZ-833J, RCZ-833K, RCZ-851J, RCZ-851K OR RCZ-854J COMMUNICATION UNITS, P/N's AS LISTED IN PART (1) OF THE APPLICABILITY SECTION OF THIS DIRECTIVE)					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT.
14-JUN-2007	MOS HRS/MSC - AFL			18-DEC-2014 0 0			
EASA 2007-0156 PARA (1)(B)	MODIFY THE AFFECTED COMMUNICATIONS UNITS (FOR AEROPLANES EQUIPPED WITH HONEYWELL RCZ-833J, RCZ-833K, RCZ-851J, RCZ-851K OR RCZ-854J COMMUNICATION UNITS, P/N's AS LISTED IN PART (1) OF THE APPLICABILITY SECTION OF THIS DIRECTIVE)					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT.
14-JUN-2007	MOS HRS/MSC - AFL			18-DEC-2014 0 0			
EASA 2007-0156 PARA (1)(C)	REPLACE THE XS-852E/F MODE S TRANSPONDER OF THE COM UNIT WITH A NEW OR MODIFIED XS-852E/F MODE S TRANSPONDER THAT HAS MOD V INSTALLED (FOR AEROPLANES EQUIPPED WITH HONEYWELL RCZ-833J, RCZ-833K, RCZ-851J, RCZ-851K OR RCZ-854J COMMUNICATION UNITS, P/N's AS LISTED IN PART (1) OF THE APPLICABILITY SECTION OF THIS DIRECTIVE)					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT.
14-JUN-2007	MOS HRS/MSC - AFL			18-DEC-2014 0 0			
EASA 2007-0156 PARA (2)	AMEND THE APPLICABLE AIRPLANE FLIGHT MANUAL (FOR ALL AIRPLANES)					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT.
14-JUN-2007	MOS HRS/MSC - AFL			18-DEC-2014 0 0			
EASA 2007-0156 PARA (3)(A)	REPLACE THE MODIFICATION PLATE OF THE TRANSPONDER WITH A NEW PLATE AND TEST THE TRANSPONDER & REINSTALL MOD Y INTO THE TRANSPONDER IF THE TRANSPONDER FAILS THE TEST (FOR AIRCRAFT EQUIPPED WITH HONEYWELL XS-856A, XS-856B OR XS-857A MODE S TRANSPONDER UNITS, P/N's AS LISTED IN PART (2) OF THE APPLICABILITY SECTION OF THIS DIRECTIVE)					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT.
14-JUN-2007	MOS HRS/MSC - AFL			18-DEC-2014 0 0			
EASA 2007-0156 PARA (3)(B)	INSTALL MOD Y INTO THE APPLICABLE MODE S TRANSPONDER (FOR AIRCRAFT EQUIPPED WITH HONEYWELL XS-856A, XS-856B OR XS-857A MODE S TRANSPONDER UNIS, P/N's AS LISTED IN PART (2) OF THE APPLICABILITY SECTION OF THIS DIRECTIVE)					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT.
14-JUN-2007	MOS HRS/MSC - AFL			18-DEC-2014 0 0			
EASA 2007-0156 PARA (4)	AFTER ACCOMPLISHING THE REPLACEMENTS OR MODIFICATIONS REQUIRED BY PARAGRAPH (1)(B) AND/OR (2)(B) AND (3) OF THIS DIRECTIVE, AS APPLICABLE, THE AFM AMENDMENT REQUIRED BY PARAGRAPH (1)(A) AND/OR (2)(A) OF THIS DIRECTIVE MAY BE REMOVED FROM THE AFM.					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT.
14-JUN-2007	MOS HRS/MSC - AFL			18-DEC-2014 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2014-0088	APPLIANCE AD - COMMUNICATIONS - COCKPIT VOICE RECORDER - REPLACEMENT					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
29-APR-2014		MOS		09-SEP-2015			
		HRS/MSC	-	15:36			
		AFL		6			
EASA 2014-0088 PARA (1)	REMOVE THE TEAM CVR P/N AP71232101 OR P/N AP71231101, AS APPLICABLE, FROM THE AIRCRAFT AND, DEPENDING ON OPERATIONAL REGULATIONS, INSTALL A SERVICEABLE CVR IN ACCORDANCE WITH APPROVED AIRCRAFT MODIFICATION INSTRUCTIONS					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
29-APR-2014		MOS		09-SEP-2015			
		HRS/MSC	-	15:36			
		AFL		6			
EASA 2014-0088 PARA (2)	DO NOT INSTALL ON ANY AIRCRAFT A TEAM CVR P/N AP71232101 OR P/N AP71231101, AS REQUIRED BY PARAGRAPH (2.1) OR (2.2) OF THIS AD, AS APPLICABLE					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
29-APR-2014		MOS		09-SEP-2015			
		HRS/MSC	-	15:36			
		AFL		6			
FAA 2014-17-02	APPLIANCE AD - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING DISCREPANCIES - HONEYWELL ASCA INC					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED
09-SEP-2014		MOS		09-SEP-2015			
		HRS/MSC	-	15:36			
		AFL		6			
TCCA CF-2013-25	APPLIANCE AD - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING INSTALLATION DISCREPANCIES					MANDATORY	NOT APPLICABLE - DUE TO THE SERIAL NUMBER OF THE AIRCRAFT.
26-AUG-2013		MOS		09-SEP-2015			
		HRS/MSC	-	15:36			
		AFL		6			
CHAPTER 24 ELECTRICAL POWER							
FAA 1972-19-04	APPLIANCE AD - NICKEL-CADMIUM BATTERY: AIRCRAFT HAVING A PRIMARY ELECTRICAL SYSTEM THAT INCLUDES A NICKEL-CADMIUM BATTERY						NOT APPLICABLE - BY DESIGN
		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
TCCA CF-1996-21	APPLIANCE AD - THIS AD CANCELS FAA AD 72-19-04 - RE NICAD BATTERY THERMAL RUNAWAYS					MANDATORY	NOT APPLICABLE - THIS AD CANCELS FAA AD 72-19-04.
12-NOV-1996		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
CHAPTER 25 EQUIPMENT/FURNISHINGS							
EASA 2010-0152	APPLIANCE AD - EQUIPMENT AND FURNISHING - OXYGEN MASK REGULATOR - MODIFICATION					MANDATORY	NOT APPLICABLE - OXYGEN MASK REGULATOR WITH DETACHABLE GOGGLES, PART NUMBER MLC20-5081 MLD20-508, INSTALLED.
09-AUG-2010		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
EASA 2010-0152 PARA (1)	REMOVE THE SUPPLY HOSE AND RADIO CORD ASSEMBLY OF THE MASK REGULATOR AND REPLACE WITH SERVICEABLE PARTS					MANDATORY	NOT APPLICABLE - OXYGEN MASK REGULATOR WITH DETACHABLE GOGGLES, PART NUMBER MLC20-5081 MLD20-508, INSTALLED.
09-AUG-2010		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2010-0152 PARA (2)	DO NOT INSTALL THE AFFECTED MASK REGULATORS ON ANY AEROPLANE, UNLESS MODIFIED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD						NOT APPLICABLE - OXYGEN MASK REGULATOR WITH DETACHABLE GOGGLES, PART NUMBER MLC20-5081 MLD20-508, INSTALLED.
09-AUG-2010		MOS HRS/MSC AFL	-	18-DEC-2014 0 0			
EASA 2011-0094	APPLIANCE AD - EQUIPMENT AND FURNISHING - LIFE JACKET VACUUM BAG - MODIFICATION					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
06-JUN-2011		MOS HRS/MSC AFL	-	09-SEP-2015 15:36 6			
EASA 2011-0094 PARA (1)	MODIFY THE VACUUM BAG OF ALL AFFECTED INFANT - SMALL CHILD LIFE JACKETS, AS IDENTIFIED BY P/N AND S/N IN THE APPLICABILITY SECTION OF THIS AD					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
06-JUN-2011		MOS HRS/MSC AFL	-	09-SEP-2015 15:36 6			
EASA 2011-0094 PARA (2)	DO NOT INSTALL ON AN AEROPLANE ANY INFANT - SMALL CHILD LIFE JACKET, AS IDENTIFIED BY P/N AND S/N IN THE APPLICABILITY SECTION OF THIS AD, UNLESS IT HAS BEEN DETERMINED THAT THE VACUUM BAG OF THAT INFANT - SMALL CHILD LIFE JACKET HAS BEEN MODIFIED					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
06-JUN-2011		MOS HRS/MSC AFL	-	09-SEP-2015 15:36 6			
EASA 2011-0103	APPLIANCE AD - EQUIPMENT / FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER (ELT) ANTENNA - MODIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
03-JUN-2011		MOS HRS/MSC AFL	-	09-SEP-2015 15:36 6			
EASA 2011-0103 PARA (1)	PERFORM A SELF-TEST OF THE ELT UNIT INTERCONNECTED WITH THE P/N 21-41 SERIES ANTENNA					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
03-JUN-2011		MOS HRS/MSC AFL	-	09-SEP-2015 15:36 6			
EASA 2011-0103 PARA (2)	MODIFY THE P/N 21-41 SERIES ANTENNA IN ACCORDANCE WITH THE INSTRUCTIONS OF CHELTON LTD SB 02/2011 ISSUE 1, OR REPLACE THE ANTENNA WITH A MODIFIED P/N 21-41 SERIES ANTENNA, OR WITH A P/N 21-41 SERIES ANTENNA WITH A S/N OF 13000 OR HIGHER					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
03-JUN-2011		MOS HRS/MSC AFL	-	09-SEP-2015 15:36 6			
EASA 2011-0103 PARA (3)	MODIFY THE P/N 21-41 SERIES ANTENNA IN ACCORDANCE WITH THE INSTRUCTIONS OF CHELTON LTD SB 02/2011 ISSUE 1, OR REPLACE THE ANTENNA WITH A MODIFIED P/N 21-41 SERIES ANTENNA, OR WITH A P/N 21-41 SERIES ANTENNA WITH A S/N OF 13000 OR HIGHER					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
03-JUN-2011		MOS HRS/MSC AFL	-	09-SEP-2015 15:36 6			
EASA 2011-0103 PARA (4)	PERFORM A SELF-TEST OF THE ELT UNIT INTERCONNECTED WITH THE P/N 21-41 SERIES ANTENNA					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
03-JUN-2011		MOS HRS/MSC AFL	-	09-SEP-2015 15:36 6			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2011-0103 PARA (5)	TERMINATING ACTION FOR THE REPETITIVE SELF-TESTS AS REQUIRED BY PARAGRAPH (1) OF THIS AD FOR THAT AIRCRAFT, WHEN AN INSTALLATION ON AN AIRCRAFT PASSES THE SELF-TEST AS REQUIRED BY PARAGRAPH (4) OF THIS AD					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
03-JUN-2011		MOS HRS/MSC AFL		09-SEP-2015 15:36 6			
EASA 2011-0103 PARA (6)	DO NOT INSTALL AN Affected P/N 21-41 SERIES ANTENNA WITH A S/N BELOW 13000 ON AN AIRCRAFT, UNLESS IT HAS BEEN MODIFIED IN ACCORDANCE WITH THE INSTRUCTIONS OF CHELTON LTD SB 02/2011 ISSUE 1					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
03-JUN-2011		MOS HRS/MSC AFL		09-SEP-2015 15:36 6			
EASA 2012-0038	APPLIANCE AD - EQUIPMENT & FURNISHINGS - PASSENGER SEAT BACKREST LINK - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
26-MAR-2012		MOS HRS/MSC AFL		09-SEP-2015 15:36 6			
EASA 2012-0038 PARA (1)	INSPECT THE SEAT BACKREST LINKS P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
26-MAR-2012		MOS HRS/MSC AFL		09-SEP-2015 15:36 6			
EASA 2012-0038 PARA (2)	REPLACE THE CRACKED LINKS					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
26-MAR-2012		MOS HRS/MSC AFL		09-SEP-2015 15:36 6			
EASA 2012-0038 PARA (3)	REPLACE ALL SEAT BACKREST LINKS P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2 (IN ANY CASE AFTER ACCOMPLISHMENT OF THE REQUIREMENTS OF PARAGRAPHS (1) AND (2) OF THIS AD)					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
26-MAR-2012		MOS HRS/MSC AFL		09-SEP-2015 15:36 6			
EASA 2013-0020 R04	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - RESTRAINTS ARE NEW EQUIPMENT AND HAVE NOT BEEN REPAIRED AT THIS TIME.
11-JUL-2014		MOS HRS/MSC AFL		09-SEP-2015			
EASA 2013-0020 R04 PARA (1)	INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER					MANDATORY	NOT APPLICABLE - RESTRAINTS ARE NEW EQUIPMENT AND HAVE NOT BEEN REPAIRED AT THIS TIME.
11-JUL-2014		MOS HRS/MSC AFL		09-SEP-2015			
EASA 2013-0020 R04 PARA (2)	VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD					MANDATORY	NOT APPLICABLE - RESTRAINTS ARE NEW EQUIPMENT AND HAVE NOT BEEN REPAIRED AT THIS TIME.
11-JUL-2014		MOS HRS/MSC AFL		09-SEP-2015			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2013-0020 R04 PARA (3)	REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE					MANDATORY	NOT APPLICABLE - RESTRAINTS ARE NEW EQUIPMENT AND HAVE NOT BEEN REPAIRED AT THIS TIME.
11-JUL-2014		MOS HRS/MSC - (s) AFL		09-SEP-2015			
EASA 2013-0020 R04 PARA (4)	AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD					MANDATORY	NOT APPLICABLE - RESTRAINTS ARE NEW EQUIPMENT AND HAVE NOT BEEN REPAIRED AT THIS TIME.
11-JUL-2014		MOS HRS/MSC - AFL		09-SEP-2015			
EASA 2013-0106	APPLIANCE AD - EQUIPMENT / FURNISHINGS - VARNISH ON VENEERED PANELS - INSPECTION / RE-FURNISHING					MANDATORY	NOT APPLICABLE - PER APPENDIX1 OF THE AD
28-MAY-2013		MOS HRS/MSC - AFL		09-SEP-2015			
EASA 2013-0106 PARA (1)	EQUIPMENT / FURNISHINGS - VARNISH ON VENEERED PANELS - INSPECTION / RE-FURNISHING REWORK THE VENEERED PARTS OF THE AEROPLANE INTERIOR					MANDATORY	NOT APPLICABLE - PER APPENDIX1 OF THE AD
28-MAY-2013		MOS HRS/MSC - AFL		09-SEP-2015			
EASA 2013-0106 PARA (2)	EQUIPMENT / FURNISHINGS - VARNISH ON VENEERED PANELS - INSPECTION / RE-FURNISHING INSPECT BY ACCOMPLISHING A CHEMICAL ANALYSIS, ALL VENEERED PARTS OF THE AEROPLANE INTERIOR					MANDATORY	NOT APPLICABLE - PER APPENDIX1 OF THE AD
28-MAY-2013		MOS HRS/MSC - AFL		09-SEP-2015			
EASA 2013-0106 PARA (3)	EQUIPMENT / FURNISHINGS - VARNISH ON VENEERED PANELS - INSPECTION / RE-FURNISHING REPLACE OR REPAIR ALL AFFECTED VENEERED CABIN PANELS					MANDATORY	NOT APPLICABLE - PER APPENDIX1 OF THE AD
28-MAY-2013		MOS HRS/MSC - AFL		09-SEP-2015			
EASA 2013-0106 PARA (4)	EQUIPMENT / FURNISHINGS - VARNISH ON VENEERED PANELS - INSPECTION / RE-FURNISHING INSPECTION OF AN AEROPLANE ACCOMPLISHED BEFORE EFFECTIVE DATE OF THIS AD					MANDATORY	NOT APPLICABLE - PER APPENDIX1 OF THE AD
28-MAY-2013		MOS HRS/MSC - AFL		09-SEP-2015			
FAA 1974-08-09 R02	APPLIANCE AD - LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION (SUPERSEDED BY FAA AD 1974-08-09 R03)						
29-JUL-1996		MOS HRS/MSC - AFL		18-DEC-2014 0 0			
FAA 2012-08-07	APPLIANCE AD - EQUIPMENT / FURNISHINGS - REPETITIVE DETAILED INSPECTIONS FOR CRACKING OF THE CENTRAL AND LATERAL SPREADERS OF THE AFFECTED SEATS, AND REPAIR OR REPLACEMENT OF THE SPREADER IF NECESSARY					MANDATORY	NOT APPLICABLE - PER PART NUMBER INSTALLED AT THIS TIME
09-MAY-2012		MOS HRS/MSC - AFL		09-SEP-2015 15:36 6			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2012-08-07 PARA (G)	PERFORM A DETAILED INSPECTION FOR CRACKING OF THE CENTRAL AND LATERAL SPREADERS OF THE AFFECTED SEATS - RETAINED INSPECTIONS				MANDATORY		NOT APPLICABLE - PER PART NUMBER INSTALLED AT THIS TIME
09-MAY-2012		MOS HRS/MSC - AFL		09-SEP-2015 15:36 6			
FAA 2012-08-07 PARA (H)	PERFORM A DETAILED INSPECTION FOR CRACKING OF THE CENTRAL AND LATERAL SPREADERS OF THE AFFECTED SEATS - NEW REQUIREMENTS				MANDATORY		NOT APPLICABLE - PER PART NUMBER INSTALLED AT THIS TIME
09-MAY-2012		MOS HRS/MSC - AFL		09-SEP-2015 15:36 6			
FAA 2012-08-07 PARA (I)	TERMINATING ACTION REPLACING ALL CENTRAL AND LATERAL SPREADERS ON AN AFFECTED SEAT ASSEMBLY (MODIFY TO "AMENDMENT B" STANDARD) TERMINATES THE INSPECTIONS REQUIRED BY THIS AD FOR THAT SEAT ASSEMBLY				MANDATORY		NOT APPLICABLE - PER PART NUMBER INSTALLED AT THIS TIME
09-MAY-2012		MOS HRS/MSC - AFL		09-SEP-2015 15:36 6			
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETITIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS				MANDATORY		NOT APPLICABLE - DUE TO ARTEX OR SATORI ELT INSTALLED
24-OCT-2017		MOS HRS/MSC - (s) AFL		29-SEP-2017			
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS						NOT APPLICABLE - DUE TO ARTEX OR SATORI ELT INSTALLED
24-OCT-2017		MOS HRS/MSC - AFL		29-SEP-2017			
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT				MANDATORY		NOT APPLICABLE - DUE TO ARTEX OR SATORI ELT INSTALLED
24-OCT-2017		MOS HRS/MSC - (s) AFL		29-SEP-2017			
FAA 2019-07-03	APPLIANCE AD - EQUIPMENT / FURNISHINGS - REAR CABIN ATTENDANT SEAT - INSPECTION / REPAIR				MANDATORY		NOT APPLICABLE - NOT Affected BY THIS AD DUE TO EQUIPPED WITH CABIN ATTENDANT SEATS
16-MAY-2019		MOS HRS/MSC - (s) AFL		16-APR-2019			
FAA 2019-07-03 PARA (G)	REMOVE THE SEAT FROM THE AIRCRAFT AND PERFORM A DETAILED VISUAL INSPECTION; IF CORROSION OR OTHER DAMAGE IS FOUND, BEFORE NEXT FLIGHT OR BEFORE (RE)INSTALLATION OF THE SEAT ON AN AIRCRAFT, AS APPLICABLE, REPAIR THE SEAT				MANDATORY		NOT APPLICABLE - NOT Affected BY THIS AD DUE TO EQUIPPED WITH CABIN ATTENDANT SEATS
16-MAY-2019		MOS HRS/MSC - (s) AFL		16-APR-2019			
FAA 2019-07-03 PARA (H)	DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED ZODIAC SEATS FRANCE 536-SERIES CABIN ATTENDANT SEAT THAT HAS ACCUMULATED MORE THAN 14 MONTHS SINCE FIRST INSTALLATION ON ANY AIRCRAFT, UNLESS IT HAS PASSED AN INSPECTION IAW THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH 2.B., OF ZODIAC SEATS FRANCE SB NO. 536-25-002, REVISION 3, DATED NOVEMBER 2, 2016				MANDATORY		NOT APPLICABLE - NOT Affected BY THIS AD DUE TO EQUIPPED WITH CABIN ATTENDANT SEATS
16-MAY-2019		MOS HRS/MSC - (s) AFL		16-APR-2019			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2019-07-03 PARA (I)	MODIFICATION AND RE-IDENTIFICATION (P/N CHANGE) OF A SEAT IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH 2.A., OF ZODIAC SEATS FRANCE SB NO. 536-25-004, REV. 0, DATED OCTOBER 19, 2017, CONSTITUTES A TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS					MANDATORY	NOT APPLICABLE - NOT AFFECTED BY THIS AD DUE TO EQUIPPED WITH CABIN ATTENDANT SEATS
16-MAY-2019	MOS HRS/MSC - (s) AFL			16-APR-2019			
FAA 2019-15-10	APPLIANCE AD - EQUIPMENT / FURNISHING - LIFE JACKET - REMOVAL / REPAIR					MANDATORY	NOT APPLICABLE
19-SEP-2019	MOS HRS/MSC - (s) AFL			09-MAR-2020			
FAA 2019-15-10 PARA (G)	REMOVE EACH AFFECTED LIFE JACKET FROM THE AIRPLANE AND REPLACE THE LIFE JACKET WITH A LIFE JACKET ELIGIBLE FOR INSTALLATION					MANDATORY	NOT APPLICABLE
19-SEP-2019	MOS HRS/MSC - AFL			09-MAR-2020			
FAA 2019-15-10 PARA (H)	DO NOT INSTALL ON ANY AIRPLANE AN AFFECTED LIFE JACKET UNLESS IT HAS BEEN REPAIRED AND MARKED TO INDICATE COMPLIANCE WITH SUCH REPAIR IN ACCORDANCE WITH ZODIAC AEROSPACE SERVICES SB 25-65-34, REVISION 01, DATED MARCH 15, 2019, OR ORIGINAL ISSUE, DATED JANUARY 8, 2019; OR A METHOD APPROVED BY THE FAA					MANDATORY	NOT APPLICABLE
19-SEP-2019	MOS HRS/MSC - (s) AFL			09-MAR-2020			
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT					MANDATORY	NOT APPLICABLE - DUE TO THE MANUFACTURE OF THE RESTRAINT SYSTEMS BEING USED ARE NOT PACIFIC SCIENTIFIC COMPANY. REF ATTACHED
	MOS HRS/MSC - AFL			04-JAN-2022 1425:43 534			
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE					MANDATORY	NOT APPLICABLE
11-MAY-2021	MOS HRS/MSC - AFL			04-JAN-2022 1425:43 534			
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE					MANDATORY	NOT APPLICABLE
11-MAY-2021	MOS HRS/MSC - AFL			04-JAN-2022 1425:43 534			
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER					MANDATORY	NOT APPLICABLE
11-MAY-2021	MOS HRS/MSC - AFL			04-JAN-2022 1425:43 534			

CHAPTER 26 FIRE PROTECTION

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2009-0278	APPLIANCE AD - FIRE PROTECTION - PORTABLE HALON 1211 FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT.
05-JAN-2010		DAYs		12-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
EASA 2012-0037	APPLIANCE AD - FIRE PROTECTION – HAND OPERATED FIRE EXTINGUISHER – MODIFICATION						NOT APPLICABLE - NOT APPLICABLE PER EQUIPMENT INSTALLED.
		MOS		09-SEP-2015			
		HRS/MSC	-				
		AFL					
FAA 2015-16-04	APPLIANCE AD - FIRE PROTECTION - MODIFY ALL KIDDE GRAVINGER HAND-OPERATED FIRE EXTINGUISHERS HAVING PART NUMBERS 56412-001 (34H), 56411-001 (35H), AND 56412-002 (38H)					MANDATORY	NOT APPLICABLE - DUE TO PART NUMBERS INSTALLED ON AIRCRAFT.
15-SEP-2015		MOS		08-DEC-2015			
		HRS/MSC	-				
		AFL					
CHAPTER 31 INDICATING/RECORDING SYSTEMS							
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS					MANDATORY	COMPLIED WITH - C/W PER EO NO. GEN-31-21030R0 BY FLIGHT OPERATION DIVISION
09-DEC-2021		MOS		03-JAN-2022			
		HRS/MSC	-				
		AFL					
FAA 2023-10-02	APPLIANCE AD - INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION					MANDATORY	COMPLIED WITH - C/W AD PARA (H) 7 PARA (I)
		MOS		29-JUN-2023			
		HRS/MSC	-				
		AFL					
FAA 2023-10-02 PARA (H)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30-JUNE- 2023 - SATISFIED BY FAA 2021-23-12)					MANDATORY	COMPLIED WITH
26-MAY-2023		MOS		29-JUN-2023			
		HRS/MSC	-				
		AFL					
FAA 2023-10-02 PARA (I)	REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)					MANDATORY	COMPLIED WITH
26-MAY-2023		MOS		29-JUN-2023			
		HRS/MSC	-				
		AFL					
CHAPTER 32 LANDING GEAR							
FAA 2006-18-08	APPLIANCE AD - GOODYEAR AVIATION TIRES - PART NUMBER 217K22-1 - INSPECTION TO DETERMINE SERIAL NUMBER (S/N), AND REPLACEMENT					MANDATORY	NOT APPLICABLE - BY TIRE SERIAL NUMBERS
		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
CHAPTER 34 NAVIGATION							
EASA 2024-0024	APPLIANCE AD - NAVIGATION - DIGITAL AIR DATA COMPUTER - REPLACEMENT					MANDATORY	NOT APPLICABLE - NOT APPLICABLE BY ADC MANUFACTURER
07-FEB-2024		MOS		05-FEB-2024			
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2006-19-04 PART (F)	APPLIANCE AD - HONEYWELL - COMMUNICATION (COM) UNIT / MODE S TRANSPONDER ERRONEOUSLY GOING INTO STANDBY MODE - REVISE AIRPLANE FLIGHT MANUAL (AFM)					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT
		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
FAA 2006-19-04 PART (G)	APPLIANCE AD - HONEYWELL - COMMUNICATION (COM) UNIT / MODE S TRANSPONDER ERRONEOUSLY GOING INTO STANDBY MODE - REPLACEMENT OF IDENTIFICATION PLATES FOR CERTAIN COM UNITS					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT
		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
FAA 2006-19-04 PART (H)	APPLIANCE AD - HONEYWELL - COMMUNICATION (COM) UNIT / MODE S TRANSPONDER ERRONEOUSLY GOING INTO STANDBY MODE - REPLACEMENT OF CERTAIN TRANSPONDERS					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT
		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
FAA 2010-07-02	APPLIANCE AD - HONEYWELL - PRIMUS II RNZ-850()-851() INTEGRATED NAVIGATION UNITS - INSPECTION TO DETERMINE P/N - MOD LEVEL - TO ENSURE ACCURATE LOCALIZER & GLIDESLOPE DEVIATION INDICATIONS					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT.
		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
FAA 2010-07-02 PARA (H) (AMOC)	REVISE THE LIMITATIONS SECTION OF THE AFM TO INCLUDE "FLIGHT LIMITATIONS"					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT.
		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
FAA 2010-07-02 PARA (L) (AMOC)	INSPECTION TO DETERMINE MOD LEVEL TO ENSURE THAT THE NRM IS AT MOD T CONFIGURATION					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT.
		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION & SURVEILLANCE SYSTEMS (ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS						NOT APPLICABLE - PER PART NUMBER INSTALLED AT THIS TIME
13-MAR-2012		MOS		09-SEP-2015			
		HRS/MSC	-	15:36			
		AFL		6			
FAA 2012-26-15 R01	APPLIANCE AD - AIR DATA PRESSURE TRANSDUCERS, AS INSTALLED IN AIR DATA COMPUTERS (ADC), AIR DATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS), AND DIGITAL AIR DATA COMPUTERS (DADC)					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED
03-DEC-2014		MOS		09-SEP-2015			
		HRS/MSC	-	15:36			
		AFL		6			
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED
14-OCT-2014		MOS		09-SEP-2015			
		HRS/MSC	-	15:36			
		AFL		6			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2017-22-14	APPLIANCE AD - NAVIGATION - INSTALLATION OF THE TSSA-4100 FLS UPGRADES ON THE ROCKWELL COLLINS, INC. TSS-4100 TRAFFIC SURVEILLANCE SYSTEM PROCESSING UNITS					MANDATORY	COMPLIED WITH - UPGRADE THE TSS-4100FLS TO RCPN 810-0052-013 COMPLETE.
20-DEC-2017		MOS HRS/MSC - AFL		02-JAN-2018 567:29 207			
FAA 2021-08-07	APPLIANCE AD - ROCKWELL COLLINS - GLOBAL POSITIONING SYSTEM GPS-4000S - UPGRADE					MANDATORY	NOT APPLICABLE - DUE TO INSTALLATION OF GPS PN ARE 822-2189-011
12-MAY-2021		MOS HRS/MSC - AFL		14-APR-2021			
FAA 2021-08-07 PARA (G)(1)	REPLACE EACH GPS-4000S GPS P/N 822-2189-100 WITH A GPS THAT DOES NOT HAVE P/N 822-2189-100					MANDATORY	NOT APPLICABLE - DUE TO INSTALLATION OF GPS PN ARE 822-2189-011
12-MAY-2021		MOS HRS/MSC - AFL		14-APR-2021			
FAA 2021-08-07 PARA (G)(2)	DO NOT INSTALL GPS-4000S GPS P/N 822-2189-100 ON ANY AIRPLANE					MANDATORY	NOT APPLICABLE - DUE TO INSTALLATION OF GPS PN ARE 822-2189-011
12-MAY-2021		MOS HRS/MSC - (s) AFL		14-APR-2021			
FAA 2023-21-05	APPLIANCE AD - NAVIGATION - FLIGHT MANAGEMENT COMPUTER 2/NAVIGATION MODULES - OPERATIONAL LIMITATIONS/AMENDMENT					MANDATORY	NOT APPLICABLE - NOT AFFECTED BY THIS AD DUE TO NO THALES FMC2 NAVIGATION MODULE INSTALLED.
39-22577 12-DEC-2023		DAYs HRS/MSC - AFL		16-NOV-2023			
TCCA CF-2021-52	APPLIANCE AD - NAVIGATION - AEROPLANE - PROHIBITION OF OPERATIONS REQUIRING RADIO ALTIMETER IN THE PRESENCE OF 5G C-BAND WIRELESS BROADBAND INTERFERENCE					MANDATORY	COMPLIED WITH - PREVIOUS C/W BY FOD TEAM PER EO NO. GEN-31-21030 R0
04-JAN-2022		MOS HRS/MSC - AFL		04-JAN-2022 1425:43 534			
TCCA CF-2023-46	APPLIANCE AD - NAVIGATION - AEROPLANE - PROHIBITION OF OPERATIONS REQUIRING RADIO ALTIMETER WHEN OPERATING IN THE CONTIGUOUS UNITED STATES DUE TO 5G C-BAND WIRELESS BROADBAND INTERFERENCE					MANDATORY	NOT APPLICABLE - BY NO CANADIAN-REGISTERED AEROPLANES IN SVC FLEET.
30-JUN-2023		MOS HRS/MSC - AFL		27-JUN-2023			
TCCA CF-2023-46 PART II	AIRPLANE/AIRCRAFT FLIGHT MANUAL (AFM) REVISION UNTIL 30 JUNE 2023					MANDATORY	NOT APPLICABLE - BY NO CANADIAN-REGISTERED AEROPLANES IN SVC FLEET.
30-JUN-2023		MOS HRS/MSC - AFL		27-JUN-2023			
TCCA CF-2023-46 PART III	AFM REVISION AFTER 30 JUNE 2023					MANDATORY	NOT APPLICABLE - BY NO CANADIAN-REGISTERED AEROPLANES IN SVC FLEET.
30-JUN-2023		MOS HRS/MSC - AFL		27-JUN-2023			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CHAPTER 35 OXYGEN							
EASA 2011-0090 R01	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR INFLATABLE HARNESS - IDENTIFICATION / REPLACEMENT				09-SEP-2015	MANDATORY	NOT APPLICABLE - PER SERIAL NUMBER
27-JUL-2011		MOS HRS/MSC - AFL					
EASA 2011-0090 R01 PARA (1)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHT CREW OXYGEN MASK REGULATOR THAT IS INSTALLED IN THE AEROPLANE TO IDENTIFY THE P/N AND BATCH NUMBER OF THAT HARNESS AND REMOVE THE INFLATABLE HARNESS FROM THE MASK REGULATOR AND REPLACE IT WITH A SERVICEABLE HARNESS (IF THE P/N AND BATCH NUMBER)				09-SEP-2015	MANDATORY	NOT APPLICABLE - PER SERIAL NUMBER
27-JUL-2011		MOS HRS/MSC - AFL					
EASA 2011-0090 R01 PARA (2)	OXYGEN MASK REGULATORS WITH A DATE OF MANUFACTURING (DMF) CODE OF NOVEMBER 2008 (112008 OR 11-08) OR EARLIER, AND THOSE WITH A DMF OF JANUARY 2011 (012011 OR 01-11) OR LATER, ARE EXCLUDED FROM THE INSPECTION AND REPLACEMENT REQUIREMENTS OF PARAGRAPH (1) OF THIS AD, PROVIDED IT CAN BE DEMONSTRATED THAT THE INFLATABLE HARNESS HAS NOT BEEN REPLACED ON THOSE MASKS				09-SEP-2015	MANDATORY	NOT APPLICABLE - PER SERIAL NUMBER
27-JUL-2011		MOS HRS/MSC - AFL					
EASA 2011-0090 R01 PARA (3)	DO NOT INSTALL A FLIGHT CREW OXYGEN MASK REGULATOR ON AN AEROPLANE					MANDATORY	NOT APPLICABLE - PER SERIAL NUMBER
27-JUL-2011		MOS HRS/MSC - AFL			09-SEP-2015		
EASA 2011-0090 R01 PARA (4)	FOR BOMBARDIER AEROPLANES, THE INSTRUCTIONS OF INTERTECHNIQUE SB MXH-35-241 (OR A LATER REVISION) MUST BE USED TO COMPLY WITH THE REQUIREMENTS OF PARAGRAPH (1) AND (3) OF THIS AD				09-SEP-2015	MANDATORY	NOT APPLICABLE - PER SERIAL NUMBER
27-JUL-2011		MOS HRS/MSC - AFL					
EASA 2012-0254 R01	APPLIANCE AD - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT.
21-DEC-2012		MOS HRS/MSC - AFL			18-DEC-2014 0 0		
EASA 2012-0254 R01 PARA (1)	INSPECT OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT EACH FLIGHT CREW OXYGEN MASK REGULATOR TO IDENTIFY THE P/N AND S/N				18-DEC-2014	MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT.
21-DEC-2012		MOS HRS/MSC - AFL			0 0 0		
EASA 2012-0254 R01 PARA (2.1)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR WITH A SERVICEABLE PART				18-DEC-2014	MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT.
21-DEC-2012		MOS HRS/MSC - AFL			0 0 0		
EASA 2012-0254 R01 PARA (2.2)	AMEND OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT THE AIRCRAFT FLIGHT MANUAL (AFM) AND INSTALL A PLACARD				18-DEC-2014	MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT.
21-DEC-2012		MOS HRS/MSC - AFL			0 0 0		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2012-0254 R01 PARA (3)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT.
21-DEC-2012		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
EASA 2014-0142 R01	APPLIANCE AD - OXYGEN – OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE – IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
18-JUN-2014		MOS		09-SEP-2015			
		HRS/MSC	-				
		AFL					
EASA 2014-0142 R01 PARA (1)	ACCOMPLISH ACCOMPLISH THE ACTIONS AS SPECIFIED IN PARAGRAPHS (1.1) AND (1.2) OF THIS AD - DETERMINE THE DATE OF MANUFACTURING / REPLACE THE HARNESS INFLATION HOSE P/N 445186 OR P/N 445952, AS APPLICABLE, WITH A SERVICEABLE PART, OR REMOVE THE INFLATABLE HARNESS FROM THE MASK REGULATOR AND REPLACE IT WITH A SERVICEABLE HARNESS					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
18-JUN-2014		MOS		09-SEP-2015			
		HRS/MSC	-				
		AFL					
EASA 2014-0142 R01 PARA (2)	ACCOMPLISH AN OXYGEN MASK REGULATOR EQUIPPED WITH A P/N MXH20-1 OR P/N MXH21-1 INFLATABLE HARNESS HAVING A DMF CODE OF NOVEMBER 2008 (0845-S OR 08/45-S) OR EARLIER, AND THOSE WITH A DMF OF JANUARY 2011 (1101-S OR 11/01-S) OR LATER, IS EXCLUDED FROM THE INSPECTION AND REPLACEMENT REQUIREMENTS OF PARAGRAPH (1) OF THIS AD					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
18-JUN-2014		MOS		09-SEP-2015			
		HRS/MSC	-				
		AFL					
EASA 2014-0142 R01 PARA (3)	ACCOMPLISH IT IS ALLOWED TO INSTALL ON AN AEROPLANE A FLIGHT CREW OXYGEN MASK REGULATOR, HAVING A P/N AS IDENTIFIED IN SECTION 1.A.(1) OF ZODIAC AEROTECHNIKS SB MC10-35-274, PROVIDED IT HAS BEEN DETERMINED THAT A P/N MXH21-31 INFLATABLE HARNESS IS INSTALLED, OR THAT THE P/N MXH20-1 OR P/N MXH21-1 INFLATABLE HARNESS INSTALLED ON THAT FLIGHT CREW OXYGEN MASK REGULATOR HAS BEEN CORRECTED, AS REQUIRED BY THIS AD					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
18-JUN-2014		MOS		09-SEP-2015			
		HRS/MSC	-				
		AFL					
FAA 1993-14-12	APPLIANCE AD - OXYGEN - REMOVE THE AFFECTED PBE UNIT, TO PREVENT LEAKAGE OF THE PBE NECK SEAL					MANDATORY	NOT APPLICABLE - PART NUMBER MR-10042N INSTALLED,
02-SEP-1993		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
FAA 1993-24-16	APPLIANCE AD - OXYGEN - INSPECT THE AFFECTED PBE UNIT FOR EXISTENCE OF A YELLOW LABEL ATTACHED TO THE RED RIP TAG. REMOVE FROM SERVICE ANY UNIT THAT DOES NOT HAVE THIS YELLOW LABEL					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT.
04-FEB-1994		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
FAA 1994-06-04	APPLIANCE AD - OXYGEN - REPLACEMENT OF THE FACE PIECE AND THE MASK SHELL SECURING SCREW					MANDATORY	NOT APPLICABLE - NOT APPLICABLE TO PILOT AND CO-PILOT OXYGEN MASK REGULATOR WITH DETACHABLE GOGGLES,
23-MAY-1994		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2011-01-09	APPLIANCE AD - B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE) PART NUMBER 119003-11 INSTALLED ON VARIOUS TRANSPORT AIRPLANES					MANDATORY	NOT APPLICABLE - NOT INSTALLED ON THIS AIRCRAFT.
09-FEB-2011		MOS		18-DEC-2014			
		HRS/MSC	-	0			
		AFL		0			
FAA 2012-11-09	APPLIANCE AD - OXYGEN - INSTALLING A SUPPLEMENTAL OXYGEN SYSTEM IN AFFECTED LAVATORIES					MANDATORY	NOT APPLICABLE - PER PART NUMBER INSTALLED AT THIS TIME
10-AUG-2012		MOS		09-SEP-2015			
		HRS/MSC	-	15:36			
		AFL		6			
FAA 2012-11-09 PARA (G)	ACTIVATE ALL CHEMICAL OXYGEN GENERATORS IN THE LAVATORIES UNTIL THE GENERATOR OXYGEN SUPPLY IS EXPENDED OR REMOVE THE OXYGEN GENERATOR (S) AND REMOVE OR RE-STOW THE OXYGEN MASKS AND CLOSE THE MASK DISPENSER DOOR (FOR EACH CHEMICAL OXYGEN GENERATOR, AFTER THE GENERATOR IS EXPENDED (OR REMOVED))					MANDATORY	NOT APPLICABLE - PER PART NUMBER INSTALLED AT THIS TIME
10-AUG-2012		MOS		09-SEP-2015			
		HRS/MSC	-	15:36			
		AFL		6			
FAA 2012-11-09 PARA (L)	INSTALL A SUPPLEMENTAL OXYGEN SYSTEM THAT MEETS ALL APPLICABLE SECTIONS OF PARTS 25 AND 121 OF THE FEDERAL AVIATION REGULATIONS (14 CFR PART 25 AND 14 CFR PART 121) IN EACH LAVATORY					MANDATORY	NOT APPLICABLE - PER PART NUMBER INSTALLED AT THIS TIME
10-AUG-2012		MOS		09-SEP-2015			
		HRS/MSC	-	15:36			
		AFL		6			
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSSES					MANDATORY	NOT APPLICABLE - MASK P/N: MC20-006 SIN: B097168 (JUMPSEAT), P/N:MLD20-508 S/N :B090594 AND P/N :MLD20-508 S/N B092146 NOT APPLICABLE PER SERIAL NUMBER
16-JUN-2015		MOS		09-SEP-2015			
		HRS/MSC	-	15:36			
		AFL		6			
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-241, REVISION 3, DATED JUNE 23, 2011					MANDATORY	NOT APPLICABLE - MASK P/N: MC20-006 SIN: B097168 (JUMPSEAT), P/N:MLD20-508 S/N :B090594 AND P/N :MLD20-508 S/N B092146 NOT APPLICABLE PER SERIAL NUMBER
16-JUN-2015		MOS		09-SEP-2015			
		HRS/MSC	-	15:36			
		AFL		6			
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PARAGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSSES					MANDATORY	NOT APPLICABLE - MASK P/N: MC20-006 SIN: B097168 (JUMPSEAT), P/N:MLD20-508 S/N :B090594 AND P/N :MLD20-508 S/N B092146 NOT APPLICABLE PER SERIAL NUMBER
16-JUN-2015		MOS		09-SEP-2015			
		HRS/MSC	-	15:36			
		AFL		6			
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS					MANDATORY	NOT APPLICABLE - DUE TO PART NUMBERS INSTALLED ON AIRCRAFT.
28-DEC-2015		MOS		08-DEC-2015			
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER					MANDATORY	NOT APPLICABLE - DUE TO PART NUMBERS INSTALLED ON AIRCRAFT.
28-DEC-2015		MOS HRS/MSC - AFL		08-DEC-2015			
FAA 2015-23-09 PARA (H)(1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).					MANDATORY	NOT APPLICABLE - DUE TO PART NUMBERS INSTALLED ON AIRCRAFT.
28-DEC-2015		MOS HRS/MSC - AFL		08-DEC-2015			
FAA 2015-23-09 PARA (H)(2)(I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1					MANDATORY	NOT APPLICABLE - DUE TO PART NUMBERS INSTALLED ON AIRCRAFT.
28-DEC-2015		MOS HRS/MSC - AFL		08-DEC-2015			
FAA 2015-23-09 PARA (H)(2)(II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."					MANDATORY	NOT APPLICABLE - DUE TO PART NUMBERS INSTALLED ON AIRCRAFT.
28-DEC-2015		MOS HRS/MSC - AFL		08-DEC-2015			
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT					MANDATORY	NOT APPLICABLE - DUE TO PART NUMBERS INSTALLED ON AIRCRAFT.
28-DEC-2015		MOS HRS/MSC - AFL		08-DEC-2015			
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - THIS AD IS NOT APPLICABLE PER INSTALLED PBE WITH PN: MR-10042N & MR-10034N
15-JUL-2016		MOS HRS/MSC - AFL		28-JUN-2016			
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A..1 SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - THIS AD IS NOT APPLICABLE PER INSTALLED PBE WITH PN: MR-10042N & MR-10034N
15-JUL-2016		MOS HRS/MSC - AFL		28-JUN-2016			
FAA 2016-11-20 PARA (H)(1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - THIS AD IS NOT APPLICABLE PER INSTALLED PBE WITH PN: MR-10042N & MR-10034N
15-JUL-2016		MOS HRS/MSC - (s) AFL		28-JUN-2016			
FAA 2016-11-20 PARA (H)(2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - THIS AD IS NOT APPLICABLE PER INSTALLED PBE WITH PN: MR-10042N & MR-10034N
15-JUL-2016		MOS HRS/MSC - AFL		28-JUN-2016			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES					MANDATORY	NOT APPLICABLE
16-OCT-2017	MOS HRS/MSC - (s) AFL			20-SEP-2017			
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED					MANDATORY	NOT APPLICABLE
16-OCT-2017	MOS HRS/MSC - (s) AFL			20-SEP-2017			
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED					MANDATORY	NOT APPLICABLE
16-OCT-2017	MOS HRS/MSC - (s) AFL			20-SEP-2017			
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.						NOT APPLICABLE
16-OCT-2017	MOS HRS/MSC - AFL			20-SEP-2017			
FAA 2024-19-15	APPLIANCE AD - OXYGEN - OXYGEN VALVE ASSEMBLIES / OXYGEN CYLINDER AND VALVE ASSEMBLIES - INSPECTION/REPLACEMENT					MANDATORY	NOT APPLICABLE - NOT AFFECTED BY THIS AD DUE TO INSTALLED OXYGEN CYLINDER AND REGULATOR ASSEMBLY P/N NOT LISTED IN AD PARA.(C) APPLICABILITY.
39-22857 26-NOV-2024	MOS HRS/MSC - AFL			20-JAN-2025			
FAA 2024-19-15 PARA (H)	INSPECT THE OXYGEN VALVE ASSEMBLIES, AND OXYGEN CYLINDER AND VALVE ASSEMBLIES, TO DETERMINE IF THE SERIAL NUMBERS OF THE VALVE, CYLINDER, AND ENTIRE ASSEMBLY, ARE LISTED IN APPENDIX 1 OR 2 (AFFECTED SHIPMENTS) OF THE APPLICABLE MATERIAL (THIS PARAGRAPH RESTATES FAA 2023-13-11 PARA (H))					MANDATORY	NOT APPLICABLE - NOT AFFECTED BY THIS AD DUE TO INSTALLED OXYGEN CYLINDER AND REGULATOR ASSEMBLY P/N NOT LISTED IN AD PARA.(C) APPLICABILITY.
26-NOV-2024	DAYs HRS/MSC - AFL			20-JAN-2025			
FAA 2024-19-15 PARA (J)	RETAINED RETURN OF PARTS (THIS PARAAGRAPH RESTATES FAA 2023-13-11 PARA (J)(2))					MANDATORY	NOT APPLICABLE - NOT AFFECTED BY THIS AD DUE TO INSTALLED OXYGEN CYLINDER AND REGULATOR ASSEMBLY P/N NOT LISTED IN AD PARA.(C) APPLICABILITY.
26-NOV-2024	DAYs HRS/MSC - AFL			20-JAN-2025			
FAA 2024-19-15 PARA (L)	INSPECT THE OXYGEN VALVE ASSEMBLIES, AND OXYGEN CYLINDER AND VALVE ASSEMBLIES, TO DETERMINE IF THE SERIAL NUMBERS OF THE VALVE, CYLINDER, AND ENTIRE ASSEMBLY, ARE LISTED IN APPENDIX 3 (AFFECTED SHIPMENTS) OF THE APPLICABLE MATERIAL					MANDATORY	NOT APPLICABLE - NOT AFFECTED BY THIS AD DUE TO INSTALLED OXYGEN CYLINDER AND REGULATOR ASSEMBLY P/N NOT LISTED IN AD PARA.(C) APPLICABILITY.
26-NOV-2024	DAYs HRS/MSC - AFL			20-JAN-2025			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2024-19-15 PARA (N)	NEW RETURN OF ADDITIONAL PARTS					MANDATORY	NOT APPLICABLE - NOT AFFECTED BY THIS AD DUE TO INSTALLED OXYGEN CYLINDER AND REGULATOR ASSEMBLY P/N NOT LISTED IN AD PARA.(C) APPLICABILITY.
26-NOV-2024		DAYs			20-JAN-2025		
		HRS/MSC	-				
		AFL					
CHAPTER 44 CABIN SYSTEMS							
FAA 2017-04-06	APPLIANCE AD - CABIN SYSTEMS - REPLACEMENT OF UNITED INSTRUMENTS INC. 5934 SERIES ALTIMETERS MANUFACTURED BETWEEN JANUARY 2015 AND FEBRUARY 2016					MANDATORY	NOT APPLICABLE - EAC FLEET ARE NOT AFFECTED BY THIS AD.
07-APR-2017		MOS			16-MAR-2017		
		HRS/MSC	- (s)				
		AFL					
CHAPTER 54 NACELLES/PYLONS							
EASA 2011-0239	APPLIANCE AD - NAVIGATION - RADIO ALTIMETER INDICATOR- MODIFICATION					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
29-DEC-2011		MOS			09-SEP-2015		
		HRS/MSC	-		15:36		
		AFL			6		
EASA 2011-0239 PARA (1)	VERIFY THAT THE DISPLAY SETTING OF THE RADIO ALTIMETER INDICATOR IS IN FEET. THE SELECTION OF THE INDICATION UNIT IN METERS OR FEET IS PERFORMED VIA PIN PROGRAMMING					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
29-DEC-2011		MOS			09-SEP-2015		
		HRS/MSC	-		15:36		
		AFL			6		
EASA 2011-0239 PARA (2)	MODIFY THE INSTALLATION TO SET UP THE INDICATOR IN FEET (THE INTERFACE CABLE) (IF THE INDICATOR DISPLAYS THE ALTITUDE IN METERS)					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
29-DEC-2011		MOS			09-SEP-2015		
		HRS/MSC	-		15:36		
		AFL			6		
EASA 2011-0239 PARA (3)	DO NOT INSTALL RADIO ALTIMETER INDICATOR IND201, P/N 102-2100, ON THAT AIRCRAFT, UNLESS THE INDICATOR HAS BEEN MODIFIED IN ACCORDANCE WITH THE INSTRUCTIONS OF SMS SB 102-2100-34-002					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
29-DEC-2011		MOS			09-SEP-2015		
		HRS/MSC	-		15:36		
		AFL			6		
EASA 2011-0239 PARA (4)	DO NOT INSTALL ON ANY AIRCRAFT A RADIO ALTIMETER INDICATOR IND201, P/N 102-2100, UNLESS THE INDICATOR HAS BEEN MODIFIED IN ACCORDANCE WITH THE INSTRUCTIONS OF SMS SB 102-2100-34-002					MANDATORY	NOT APPLICABLE - PER EQUIPMENT INSTALLED.
29-DEC-2011		MOS			09-SEP-2015		
		HRS/MSC	-		15:36		
		AFL			6		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
APU - SB - P-810/WE3800714-1							
CHAPTER 49	AIRBORNE AUXILIARY POWER						
SB RE220-49-7759 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - INSPECTION OF SPECIFIC FADEC CONTROLLER, PART NO. 2118990-3, SERVICE BULLETIN						RECOMMENDED
		MOS		11-NOV-2014			
		HRS/MSC	-	0			
		APUS		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - AD - 22467/DEL114							
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS							
EASA 2022-0033	NO. 1 ENGINE - ATA 05 - TIME LIMITS / MAINTENANCE CHECKS - TIME LIMITS MANUAL / MAINTENANCE PROGRAMME - AMENDMENT						COMPLIED WITH - THIS AD IS COMPLIED WITH PER PARAGRAPH (4) SINCE THE REQUIRED ACTION(S) AS MENTIONED IN PARAGRAPH (1) HAS BEEN ACCOMPLISHED PRIOR THE EFFECTIVE DATE FOR BOTH AIRCRAFT 8-99998 AND 8-96999.
17-MAR-2022		MOS HRS/MSC - ENC		09-MAR-2022			
CHAPTER 72 ENGINE							
EASA 2010-0075	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2 ASSEMBLY LIFE LIMITS - MODIFICATION					MANDATORY	COMPLIED WITH - AT MANUFACTURE
04-MAY-2010		MOS HRS/MSC - ENC		23-SEP-2015 0 0			
EASA 2010-0077	NO. 1 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT					MANDATORY	COMPLIED WITH
04-MAY-2010		MOS HRS/MSC - ENC		22-DEC-2014 5			
EASA 2012-0161	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING					MANDATORY	COMPLIED WITH - AT MANUFACTURE
19-SEP-2014		MOS HRS/MSC - ENC		23-SEP-2015 0 0			
EASA 2012-0161 R01	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING					MANDATORY	COMPLIED WITH
19-SEP-2014		MOS HRS/MSC - ENC		22-DEC-2014 5			
EASA 2012-0161 R01 PARA (1)	NO. 1 ENGINE - REPLACE EACH ENGINE FUEL PUMP SPLINED COUPLING WITH A SERVICEABLE PART					MANDATORY	
19-SEP-2014		MOS HRS/MSC - ENC		14-OCT-2014 0 0			
EASA 2012-0166	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR DISC STAGE 1 AND STAGE 2 LIFE LIMITATION - IMPLEMENTATION					MANDATORY	COMPLIED WITH - AT MANUFACTURE
13-SEP-2012		MOS HRS/MSC - ENC		23-SEP-2015 0 0			
EASA 2013-0296	NO. 1 ENGINE - ENGINE - HIGH PRESSURE COMPRESSOR AND COMBUSTION FAIRINGS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE
25-DEC-2013		MOS HRS/MSC - ENC		23-SEP-2015 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2013-0296 PARA (1)	NO. 1 ENGINE - INSPECT THE UPPER LEFT HPC FAIRING					MANDATORY	NOT APPLICABLE
25-DEC-2013		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
EASA 2013-0296 PARA (2)	NO. 1 ENGINE - REPLACE THE UPPER LEFT HPC FAIRING					MANDATORY	NOT APPLICABLE
25-DEC-2013		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
EASA 2013-0296 PARA (3)	NO. 1 ENGINE - REPLACE AN UPPER LEFT, UPPER RIGHT AND LOWER RIGHT COMBUSTION SECTION FAIRING					MANDATORY	NOT APPLICABLE
25-DEC-2013		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
EASA 2013-0296-CN	NO. 1 ENGINE - CANCELLED: ENGINE - HIGH PRESSURE COMPRESSOR AND COMBUSTION FAIRINGS - INSPECTION / REPLACEMENT					CANCELLED	NOT APPLICABLE
26-JUN-2014		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
EASA 2018-0268	NO. 1 ENGINE - ENGINE - LIFE-LIMITED CRITICAL PARTS - SERVICE LIFE CALCULATION / REPLACEMENT					MANDATORY	COMPLIED WITH
01-JAN-2019		MOS		18-DEC-2018			
		HRS/MSC	-				
		ENC					
EASA 2018-0268 PARA (1)	NO. 1 ENGINE - DETERMINE THE OPERATIONAL HISTORY OF THE LPC DISC AND, BASED ON THAT DETERMINATION, RE-CALCULATE THE CONSUMED (AND REMAINING) SERVICE LIFE OF THE LPC DISC (FOR EACH AFFECTED ENGINE)						COMPLIED WITH
01-JAN-2019		MOS		18-DEC-2018			
		HRS/MSC	-				
		ENC					
EASA 2018-0268 PARA (2)	NO. 1 ENGINE - ACCOMPLISH A ONE-TIME RE-CALCULATION OF THE SERVICE LIFE ACCUMULATED BY THE LPC DISC ON THAT AFFECTED ENGINE (FOR EACH AFFECTED ENGINE)					MANDATORY	COMPLIED WITH
01-JAN-2019		MOS		18-DEC-2018			
		HRS/MSC	-				
		ENC					
EASA 2018-0268 PARA (3)	NO. 1 ENGINE - RE-CALCULATE THE CONSUMED (AND REMAINING) SERVICE LIFE OF EACH AFFECTED LLP (FOLLOWING THE RE-CALCULATION OF THE SERVICE LIFE ACCUMULATED BY THE LPC DISC ON AN AFFECTED ENGINE, AS REQUIRED BY PARAGRAPH (2) OF THIS AD)						COMPLIED WITH
01-JAN-2019		MOS		18-DEC-2018			
		HRS/MSC	-				
		ENC					
EASA 2018-0268 PARA (4)	NO. 1 ENGINE - REPLACE THAT AFFECTED LLP WITH A SERVICEABLE PART					MANDATORY	COMPLIED WITH
01-JAN-2019		DAYs		18-DEC-2018			
		HRS/MSC	-				
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2018-0268 PARA (6)	NO. 1 ENGINE - TERMINATING ACTION: RE-CALCULATION OF THE CONSUMED (AND REMAINING) SERVICE LIFE OF EACH AFFECTED LLP ON AN AFFECTED ENGINE IN ACCORDANCE WITH THE INSTRUCTIONS OF PART B "REQUIREMENT 2" OF THE NMSB, AS REQUIRED BY PARAGRAPH (3) OF THIS AD, CONSTITUTES TERMINATING ACTION FOR THE REPETITIVE RE-CALCULATIONS OF THE LPC DISC LIFE AS REQUIRED BY PARAGRAPH (1) OF THIS AD FOR THAT AFFECTED ENGINE					MANDATORY	COMPLIED WITH
01-JAN-2019		MOS HRS/MSC - ENC		18-DEC-2018			
EASA 2018-0268 PARA (7)	NO. 1 ENGINE - TERMINATING ACTION: INSTALLATION OF AN AFFECTED ENGINE ON A POST-MOD AEROPLANE, AS DEFINED IN THIS AD, CONSTITUTES TERMINATING ACTION FOR THE REPETITIVE RE-CALCULATION REQUIREMENTS OF PARAGRAPH (3) OF THIS AD FOR THAT ENGINE, EXCEPT AS SPECIFIED IN PARAGRAPH (8) OF THIS AD					MANDATORY	COMPLIED WITH
01-JAN-2019		MOS HRS/MSC - ENC		18-DEC-2018			
EASA 2019-0299	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE STAGE 1 DISCS - LIFE LIMIT REDUCTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - THE EATC BR700-710A2-20 ENGINES ARE NOT AFFECTED BY THIS AD
24-DEC-2019		MOS HRS/MSC - (s) ENC		13-DEC-2019			
EASA 2019-0299 PARA (1)	NO. 1 ENGINE - DETERMINE WHETHER AN AFFECTED PART, AS DEFINED IN THIS AD, IS INSTALLED ON THE ENGINE					MANDATORY	NOT APPLICABLE - THE EATC BR700-710A2-20 ENGINES ARE NOT AFFECTED BY THIS AD
24-DEC-2019		DAYs HRS/MSC - ENC		13-DEC-2019			
EASA 2019-0299 PARA (2)	NO. 1 ENGINE - REMOVE THE ENGINE FROM SERVICE AND, BEFORE RELEASE TO SERVICE OF THAT ENGINE, REPLACE THE AFFECTED PART WITH A SERVICEABLE PART (FOR EACH ENGINE FOR WHICH IT HAS BEEN DETERMINED, AS REQUIRED BY PARAGRAPH (1) OF THIS AD, THAT AN AFFECTED PART IS INSTALLED)					MANDATORY	NOT APPLICABLE - THE EATC BR700-710A2-20 ENGINES ARE NOT AFFECTED BY THIS AD
24-DEC-2019		MOS HRS/MSC - (s) ENC		13-DEC-2019			
FAA 1998-24-03 R01	NO. 1 ENGINE - VISUAL INSPECTION OF ENGINE CORE FAIRING FASTENERS.						COMPLIED WITH - AT MANUFACTURE
27-DEC-1999		MOS HRS/MSC - ENC		23-SEP-2015 0 0			
FAA 2001-05-06 ULTRASONIC INSP	NO. 1 ENGINE - ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS					SUPERSEDED	NOT APPLICABLE - SUPERSEDED BY 2003-07-11
39-12142 14-MAR-2001		MOS HRS/MSC N/A ENC		23-SEP-2015 0			
FAA 2001-05-06 VISUAL INSP	NO. 1 ENGINE - VISUAL INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS					SUPERSEDED	NOT APPLICABLE
39-12142 14-MAR-2001		MOS HRS/MSC N/A ENC		23-SEP-2015 0 0			
FAA 2003-07-11 PART B	NO. 1 ENGINE - VISUAL OR ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS					SUPERSEDED	NOT APPLICABLE
39-13107		MOS HRS/MSC - ENC		23-SEP-2015 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2003-07-11 PART F	NO. 1 ENGINE - VISUAL AND ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS					SUPERSEDED	NOT APPLICABLE
	MOS			23-SEP-2015			
	HRS/MSC	-		0			
	ENC			0			
FAA 2005-21-05 PART 1	NO. 1 ENGINE - VISUAL OR ULTRASONIC INSPECTION OF THE FAN DISC					MANDATORY	NOT APPLICABLE
	MOS			23-SEP-2015			
	HRS/MSC	-		0			
	ENC			0			
FAA 2005-21-05 PART 2	NO. 1 ENGINE - ULTRASONIC AND VISUAL INSPECTION OF THE FAN DISC					MANDATORY	NOT APPLICABLE
	MOS			23-SEP-2015			
	HRS/MSC	-		0			
	ENC			0			
FAA 2005-21-05 PART L	NO. 1 ENGINE - VISUAL AND ULTRASONIC INSPECTION AS MANDATED IN RRD TIME LIMITS MANUAL T-710-2BR, CHAPTER 05-10-01 (BR700-710A2-20).					MANDATORY	NOT APPLICABLE
	MOS			23-SEP-2015			
	HRS/MSC	-		0			
	ENC			0			
FAA 2010-25-05	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2 ASSEMBLY LIFE LIMITS - MODIFICATION					MANDATORY	NOT APPLICABLE
39-16538		MOS		23-SEP-2015			
13-JAN-2011		HRS/MSC	-	0			
		ENC		0			
FAA 2011-22-01	NO. 1 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT					MANDATORY	NOT APPLICABLE - A/C NOT USED FOR PILOT TRAINING
39-16842		MOS		22-DEC-2014			
23-NOV-2011		HRS/MSC	-				
		ENC		5			
FAA 2011-22-01 PARA (E)(1) & (E)(2)	NO. 1 ENGINE - REVISE ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT THE AIRWORTHINESS LIMITATIONS SECTION (ALS) OF THE OPERATORS' APPROVED MAINTENANCE PROGRAM (REFERENCE THE TIME LIMITS MANUAL (TLM), CHAPTERS 05-00-01 AND 05-00-02 OF THE APPLICABLE ENGINE MANUALS (EMS))					MANDATORY	NOT APPLICABLE - A/C NOT USED FOR PILOT TRAINING
23-NOV-2011		MOS		22-DEC-2014			
		HRS/MSC	-				
		ENC		5			
FAA 2011-22-01 PARA (E)(3)	NO. 1 ENGINE - DETERMINE ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT THE NUMBER OF TOUCH-AND-GO'S AND OVERSHOTS THAT EACH INDIVIDUAL CRITICAL PART EXCEPT THE FAN SHAFT AND LP TURBINE ROTOR SHAFT HAS EXPERIENCED SINCE ENTRY INTO SERVICE FOR PILOT TRAINING					MANDATORY	NOT APPLICABLE - A/C NOT USED FOR PILOT TRAINING
23-NOV-2011		MOS		22-DEC-2014			
		HRS/MSC	-				
		ENC		5			
FAA 2013-03-17	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR DISC STAGE 1 AND STAGE 2 LIFE LIMITATION - IMPLEMENTATION					MANDATORY	COMPLIED WITH - AT MANUFACTURE
39-17351		MOS		23-SEP-2015			
21-MAR-2013		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2013-05-13	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING (SUPERSEDED BY FAA AD 2022-26-02)					MANDATORY	COMPLIED WITH - AT MANUFACTURE
24-APR-2013		MOS HRS/MSC ENC	4000	23-SEP-2015 0 0	4000	RECURRING	
FAA 2016-13-12	NO. 1 ENGINE - ENGINE - PAWL CARRIER PIVOT PINS, PART NUMBER (P/N) BRR17117, - REMOVE FROM SERVICE / REPLACE					MANDATORY	NOT APPLICABLE - N/A BY ESN
05-AUG-2016		MOS HRS/MSC ENC	-	16-JAN-2025			
FAA 2021-12-07	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE (HPT) STAGE 1 DISK - REPLACE					MANDATORY	NOT APPLICABLE - N/A - HPT STAGE 1 DISC P/N BRR23952 WITH S/N RRSUNDM941 NOT AFFECTED
12-AUG-2021		DAYS HRS/MSC ENC	-	16-JAN-2025			
FAA 2021-21-12	NO. 1 ENGINE - TURBINE ENGINE COMPRESSOR SECTION - LIFE-LIMITED CRITICAL PARTS - SERVICE LIFE CALCULATION / REPLACEMENT					MANDATORY	COMPLIED WITH - ASB BR700-72-A900584 R01 ALREADY INCORPORATED ON 02-NOV-2017
13-DEC-2021		MOS HRS/MSC ENC	-	16-JAN-2025			
FAA 2021-21-12 PARA (G)(1)	NO. 1 ENGINE - RECALCULATE THE CONSUMED AND REMAINING SERVICE LIFE OF EACH AFFECTED LLP					MANDATORY	COMPLIED WITH - ASB BR700-72-A900584 R01 ALREADY INCORPORATED ON 02-NOV-2017
13-DEC-2021		DAYS HRS/MSC ENC	-	16-JAN-2025			
FAA 2021-21-12 PARA (G)(2)	NO. 1 ENGINE - CALCULATE THE CONSUMED AND REMAINING SERVICE LIFE OF EACH AFFECTED LLP (FOR ENGINES INSTALLED AND OPERATED ON A PRE-MOD AIRPLANE, AFTER PERFORMING THE INITIAL RECALCULATIONS REQUIRED BY PARA (G)(1))					MANDATORY	COMPLIED WITH - ASB BR700-72-A900584 R01 ALREADY INCORPORATED ON 02-NOV-2017
13-DEC-2021		MOS HRS/MSC ENC	BF/F (s)	16-JAN-2025			
FAA 2021-21-12 PARA (G)(3)	NO. 1 ENGINE - REMOVE EACH AFFECTED LLP					MANDATORY	COMPLIED WITH - ASB BR700-72-A900584 R01 ALREADY INCORPORATED ON 02-NOV-2017
13-DEC-2021		MOS HRS/MSC ENC	-	16-JAN-2025			
FAA 2022-24-06	NO. 1 ENGINE - ENGINE - LOW PRESSURE COMPRESSOR ROTOR (FAN) DISC - INSPECTION					MANDATORY	NOT APPLICABLE - BY ESN AND AFFECTED PN IS NOT INSTALLED ON THE ENGINE. (LPC ROTOR (FAN) DISC P/N FW33927 INSTALLED)
39-22246 06-JAN-2023		DAYS HRS/MSC ENC	-	16-JAN-2025			
LBA D-1998-467	NO. 1 ENGINE - ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 1998-467/2
04-NOV-1998		MOS HRS/MSC ENC	-	12-DEC-2014 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
LBA D-1998-467 R02	NO. 1 ENGINE - ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 1998-467/3
26-MAR-1999		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-1998-467 R03	NO. 1 ENGINE - ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 1998-467/4
15-SEP-1999		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-1998-467 R04	NO. 1 ENGINE - ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION					MANDATORY	COMPLIED WITH - AT MANUFACTURE
19-SEP-2002		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-348	NO. 1 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/2
02-OCT-2000		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-348 R02	NO. 1 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/3
24-NOV-2000		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-348 R03	NO. 1 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/4
		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-348 R04	NO. 1 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/5
		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-348 R05	NO. 1 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/6
		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-348 R06	NO. 1 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					NOT APPLICABLE	
31-MAR-2005		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-348 REV 6 PART 4	NO. 1 ENGINE - VISUAL OR ULTRASONIC INSP FAN DISC, P/N BRR20791					NOT APPLICABLE	
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-348 REV 6 PART 5	NO. 1 ENGINE - VISUAL AND ULTRASONIC INSP OF FAN DISC, ALL P/NS					NOT APPLICABLE	
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
LBA D-2004-494	NO. 1 ENGINE - REDUCTION OF LIFE LIMITATION FOR THE HIGH PRESSURE COMPRESSOR (HPC) FRONT DRUM DUE TO AN INADVERTENT HEAT TREATMENT.					MANDATORY	NOT APPLICABLE
10-JAN-2005		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2007-352	NO. 1 ENGINE - REVERSE WIRED INDEPENDENT OVERSPEED PROTECTION COILS IN BR700 SERIES ENGINES					MANDATORY	NOT APPLICABLE
21-DEC-2007		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2008-222	NO. 1 ENGINE - BR700-710 - RE-USE OF POTENTIALLY DAMAGED ENGINE MATERIAL					MANDATORY	NOT APPLICABLE
23-JUN-2008		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2008-222 R01	NO. 1 ENGINE - BR700-710 - RE-USE OF POTENTIALLY DAMAGED ENGINE MATERIAL					CANCELLED	NOT APPLICABLE
25-SEP-2008		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2010-126	NO. 1 ENGINE - ENGINE – HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2 ASSEMBLY LIFE LIMITS – MODIFICATION					MANDATORY	COMPLIED WITH - AT MANUFACTURE
03-MAY-2010		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2010-130	NO. 1 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT					MANDATORY	COMPLIED WITH - AT MANUFACTURE
03-MAY-2010		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2012-340	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING					MANDATORY	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2012-346	NO. 1 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR DISC STAGE 1 AND STAGE 2 LIFE LIMITATION - IMPLEMENTATION					MANDATORY	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2013-366	NO. 1 ENGINE - ENGINE - HIGH PRESSURE COMPRESSOR AND COMBUSTION FAIRINGS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE
16-DEC-2013		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2013-366 R01	NO. 1 ENGINE - CANCELLED: ENGINE - HIGH PRESSURE COMPRESSOR AND COMBUSTION FAIRINGS - INSPECTION / REPLACEMENT					CANCELLED	NOT APPLICABLE
27-JUN-2014		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

CHAPTER 73 ENGINE FUEL AND CONTROL

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2017-0198	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER FIREBOX ASSEMBLY - REPLACEMENT (CANCELLED BY EASA AD 2017-0198-CN)					MANDATORY	COMPLIED WITH - WORK DONE
10-OCT-2017	MOS HRS/MSC - ENC			12-NOV-2018 823:40 292			
LBA D-2013-156	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - SPILL RETURN TO FUEL PUMP TUBE - REPLACEMENT					MANDATORY	NOT APPLICABLE
30-MAY-2013	MOS HRS/MSC - ENC			23-SEP-2015 0 0			
LBA D-2013-281 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL METERING UNIT - REPLACEMENT					MANDATORY	NOT APPLICABLE
	MOS HRS/MSC - ENC			23-SEP-2015 0 0			
CHAPTER 76 ENGINE CONTROLS							
FAA 2018-18-14	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER FIREBOX ASSEMBLY - REPLACEMENT					MANDATORY	COMPLIED WITH - ACCORDING WITH THE RECORD OF ROLLS-ROYCE ASB BR700-73-101977 R03 WHICH COMPLIANCE WITH AT NOV-2018.
12-OCT-2018	MOS HRS/MSC - ENC			03-FEB-2021			
CHAPTER 79 OIL							
FAA 2001-01-01	NO. 1 ENGINE - ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH - REPLACE						NOT APPLICABLE
31-JAN-2001	MOS HRS/MSC - ENC			23-SEP-2015 0 0			
LBA D-2000-257	NO. 1 ENGINE - ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-257/2
25-JUL-2000	MOS HRS/MSC - ENC			12-DEC-2014 0 0			
LBA D-2000-257 PART 1	NO. 1 ENGINE - PERFORM ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431 INSPECTION TO DETERMINE THE SERIAL NUMBER					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-257/2
25-JUL-2000	MOS HRS/MSC - ENC			12-DEC-2014 0 0			
LBA D-2000-257 PART 2 & 3	NO. 1 ENGINE - PERFORM ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431 REPLACE THE OIL FILTER DIFFERENTIAL PRESSURE SWITCH UNIT OR MARK THE OIL FILTER DIFFERENTIAL PRESSURE SWITCH UNIT WITH A STRIP OF A HIGH TEMPERATURE YELLOW PAINT.					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-257/2
25-JUL-2000	MOS HRS/MSC - ENC			12-DEC-2014 0 0			
LBA D-2000-257 R02	NO. 1 ENGINE - ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431					MANDATORY	NOT APPLICABLE
24-AUG-2000	MOS HRS/MSC - ENC			12-DEC-2014 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
LBA D-2000-257 R02 PART 1	NO. 1 ENGINE - PERFORM ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431 INSPECTION TO DETERMINE THE SERIAL NUMBER					MANDATORY	NOT APPLICABLE
24-AUG-2000		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-257 R02 PART 2	NO. 1 ENGINE - REPLACE ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431 THE OIL FILTER DIFFERENTIAL PRESSURE SWITCH UNIT					MANDATORY	NOT APPLICABLE
24-AUG-2000		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
CHAPTER 83 ACCESSORY GEAR-BOXES							
FAA 2022-26-02	NO. 1 ENGINE - ACCESSORY GEARBOXES - TIME LIMITS / MAINTENANCE CHECKS - TIME LIMITS MANUAL / MAINTENANCE PROGRAMME - AMENDMENT					MANDATORY	COMPLIED WITH - THE LIFE LIMITS AND MAINTENANCE TASKS ALREADY INCORPORATED INTO G6000 AMP AND CONTROLLED BY CAMP.
39-22280		MOS		16-JAN-2025			
27-JAN-2023		HRS/MSC	-				
		ENC					
FAA 2022-26-02 PARA (G) EASA (1.1)	NO. 1 ENGINE - REPLACE EACH COMPONENT BEFORE EXCEEDING THE APPLICABLE LIFE LIMIT OR BEFORE EXCEEDING THE APPLICABLE THRESHOLD, OR WITHIN THE SPECIAL COMPLIANCE TIMES SPECIFIED IN TABLE 1 OF THIS AD					MANDATORY	COMPLIED WITH - THE LIFE LIMITS AND MAINTENANCE TASKS ALREADY INCORPORATED INTO G6000 AMP AND CONTROLLED BY CAMP.
27-JAN-2023		MOS		16-JAN-2025			
		HRS/MSC	-				
		ENC					
FAA 2022-26-02 PARA (G) EASA (3)	NO. 1 ENGINE - INCORPORATING THE ACTIONS AND ASSOCIATED THRESHOLDS AND INTERVALS, INCLUDING LIFE LIMITS AND MAINTENANCE TASKS, INTO THE EXISTING APPROVED MAINTENANCE OR INSPECTION PROGRAM, AS APPLICABLE					MANDATORY	COMPLIED WITH - THE LIFE LIMITS AND MAINTENANCE TASKS ALREADY INCORPORATED INTO G6000 AMP AND CONTROLLED BY CAMP.
27-JAN-2023		DAYs		16-JAN-2025			
		HRS/MSC	-				
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - SB - 22467/DEL114							
CHAPTER 24 ELECTRICAL POWER							
SB	BR700-24-100166 R01	NO. 1 ENGINE - ELECTRICAL POWER - VARIABLE FREQUENCY GENERATOR OIL TRANSFER TUBES AND FITTINGS - REVISED OIL TRANSFER TUBE SELF LOCKING NUT TIGHTENING TORQUE, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
			01-DEC-2000	MOS HRS/MSC ENC	23-SEP-2015 0 0		
SB	BR700-24-100378	NO. 1 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR OIL COOLER - DELETION OF FIRE PROTECTION COVER PLATES, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE
			26-APR-1999	MOS HRS/MSC ENC	23-SEP-2015 0 0		
SB	BR700-24-100384 R01	NO. 1 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR SURFACE AIR COOLED OIL COOLER (SACOC) TRANSFER TUBES AND FITTINGS - INTRODUCTION OF A MODIFIED SACOC TO VARIABLE FREQUENCY GENERATOR (VFG) OIL TUBE, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE
			08-JUL-2014	MOS HRS/MSC ENC	23-SEP-2015 0 0		
SB	BR700-24-100472	NO. 1 ENGINE - POWER - ENGINE GENERATOR OIL COOLER - DELETION OF THE THERMOSTATIC CONTROL VALVE OF THE SURFACE AIR COOLED OIL COOLER AND ASSOCIATED DRESSINGS CHANGES, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE
			24-JAN-2002	MOS HRS/MSC ENC	23-SEP-2015 0 0		
SB	BR700-24-100961 R01	NO. 1 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR OIL COOLER - INTRODUCTION OF A NEW BUILD INSTRUCTION FOR THE FIRE SHIELDS OF THE OIL COOLER, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE
			10-APR-2001	MOS HRS/MSC ENC	23-SEP-2015 0 0		
SB	BR700-24-101483	NO. 1 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR OIL COOLER - INTRODUCTION OF NEW SURFACE AIR COOLED OIL COOLERS (SACOC), SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE
			11-FEB-2005	MOS HRS/MSC ENC	23-SEP-2015 0 0		
CHAPTER 26 FIRE PROTECTION							
SB	BR700-26-100396	NO. 1 ENGINE - FIRE PROTECTION - CORE ENGINE FIRE DETECTION SENSORS - INTRODUCTION OF REVISED CORE FIRE WIRE MOUNTING BRACKETS, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE
			26-APR-1999	MOS HRS/MSC ENC	23-SEP-2015 0 0		
SB	BR700-26-100434 R02	NO. 1 ENGINE - FIRE - PROTECTION - CORE ENGINE NOZZLE, TUBES AND FITTINGS - INTRODUCTION OF MODIFIED ZONE 2 TUBES AND ADDITIONAL CLIPPING, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
			31-JUL-2002	MOS HRS/MSC ENC	23-SEP-2015 0 0		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-26-100466	NO. 1 ENGINE - FIRE PROTECTION - ELECTRICAL HARNESSES - INTRODUCTION OF CLIPPING POSITION CHANGES TO SUIT MODIFIED FIRE EXTINGUISHER SYSTEM, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
03-SEP-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
CHAPTER 36 PNEUMATIC							
SB BR700-36-100142 R01	NO. 1 ENGINE - PNEUMATIC - CABIN AIR DUCTS - INTRODUCTION OF A REVISED HP5 CABIN AIR DUCT ASSEMBLY, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
25-JAN-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
CHAPTER 71 POWER PLANT							
SB BR700-71-100058	NO. 1 ENGINE - POWER PLANT - THRUST REVERSER UNIT (TRU) AND GENERAL SERVICES HARNESS ATTACHMENT FITTINGS - INTRODUCTION OF REVISED CLIPPING POINTS, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
29-APR-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100160	NO. 1 ENGINE - POWER PLANT - LEFT ENGINE HARNESS ATTACH FITTINGS - INTRODUCTION OF RE-ROUTED HARNESSES AND REPLACEMENT OF RELATED CLIPPING POINTS, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
31-JAN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100177	NO. 1 ENGINE - POWER PLANT - ELECTRICAL HARNESSES - INTRODUCTION OF ENGINE BUILD UP (EBU) EXTENSION CLIPS, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
20-SEP-1997		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100179	NO. 1 ENGINE - POWER PLANT - LEFT ENGINE HARNESS ATTACH FITTINGS - INTRODUCTION OF RE-ROUTED TRU HARNESS AND RELATED CLIPPING POINTS, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
19-JUN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100211	NO. 1 ENGINE - POWER PLANT - DRAINS TANK EJECTOR - INTRODUCTION OF REVISED MATERIAL, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
15-JUN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100242 R01	NO. 1 ENGINE - POWER PLANT - MINOR PODDING MODIFICATIONS, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
22-OCT-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100259	NO. 1 ENGINE - POWER PLANT - ADDITIONAL ACOC DELETION DRESSING MODIFICATIONS, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
24-JAN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-71-100298 R02	NO. 1 ENGINE - POWER PLANT - ADDITIONAL PRODUCTION ACOC DELETION DRESSING MODIFICATIONS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100307	NO. 1 ENGINE - POWER PLANT - EEC HARNESS - MINOR CONFIGURATION AMENDMENTS TO CLIPPING POINTS CP10733 AND CP10734, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100340	NO. 1 ENGINE - POWER PLANT - GEARBOX MOUNTED EBU BRACKETS - TRANSFER OF OWNERSHIP, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100341	NO. 1 ENGINE - POWER PLANT - VARIOUS - ADDITIONAL HARNESS CLIPPING MODIFICATIONS (NEUTRAL AND RIGHT HAND), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-MAR-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100351	NO. 1 ENGINE - POWER PLANT - GEARBOX MOUNTED EBU BRACKETS - INTRODUCTION OF SHORTER BOLTS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-MAR-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100426 R01	NO. 1 ENGINE - POWER PLANT - CORE/EXTERNAL DRAINS TUBES AND FITTINGS - INTRODUCTION OF REVISED CLEARANCES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-OCT-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100427 R01	NO. 1 ENGINE - POWER PLANT - EEC LANE A HARNESS 1A - RE-ORIENTATION OF HARNESS CONNECTOR BACKSHELLS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100428 R01	NO. 1 ENGINE - POWER PLANT - EEC LANE B HARNESS 1D - RE-ORIENTATION OF HARNESS CONNECTOR BACKSHELLS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100429 R01	NO. 1 ENGINE - POWER PLANT - EEC LANE B HARNESS 1E - RE-ORIENTATION OF HARNESS CONNECTOR BACKSHELLS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-71-100476	NO. 1 ENGINE - POWER PLANT - ELECTRICAL HARNESSSES - REROUTING OF HARNESS LOOMS TO CLEAR BYPASS DUCT ACCESS PANEL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
17-SEP-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100488	NO. 1 ENGINE - POWER PLANT - EEC LANES A AND B HARNESSSES - INTRODUCTION OF REVISED CLIPPING POINTS CP10022 AND CP10029, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100500	NO. 1 ENGINE - POWER PLANT - ELECTRICAL HARNESSSES - INTRODUCTION OF MINOR ASSOCIATED DRESSING CHANGES FOR THE EEC TROUGH DELETION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-SEP-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100530	NO. 1 ENGINE - POWER PLANT - EXTERNAL DRAIN TUBES AND FITTINGS - INTRODUCTION OF A CHANGE OF OWNERSHIP (INSTALLATION RESPONSIBILITY) FOR THE WET DRAINS BRACKETS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100585 R01	NO. 1 ENGINE - POWER PLANT - EEC LANE A HARNESS 1C - INTRODUCTION OF MODIFIED CLIPPING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100595 R01	NO. 1 ENGINE - POWER PLANT - GEARBOX MOUNTED EBU BRACKETS - INTRODUCTION OF REVISED LENGTH BOLTS TO ACCOMMODATE NEW STANDARD OF ACCESSORY GEARBOX MAIN HOUSING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-JUN-2005		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100602	NO. 1 ENGINE - POWER PLANT - FRONT SUSPENSION-ENGINE MOUNTED - INTRODUCTION OF THRUST TRUNNION FLANGE BOLTS WITH A THINNER HEAD, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
03-AUG-2016		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-71-100680 R02	NO. 1 ENGINE - POWER PLANT - GEARBOX MOUNTED ENGINE BUILD UNIT (EBU) BRACKETS - INTRODUCTION OF REVISED FIRERAIL SUPPORT BRACKET, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-NOV-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100892	NO. 1 ENGINE - POWER PLANT - LEFT AND RIGHT ENGINE EEC LANE A HARNESS 1C AND LANE B HARNESS 1F - INTRODUCTION OF ELECTRONIC ENGINE CONTROLLER (EEC) HARNESSSES WITH A RESISTOR IN THE ELECTRICAL SUPPLY LINE TO THE STARTER AIR VALVE (SAV) SOLENOID, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
13-OCT-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-71-101465	NO. 1 ENGINE - POWER PLANT - GENERAL - INTRODUCTION OF A NEW EXTENSION CLIP WITH A SIMPLIFIED DESIGN, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
27-JAN-2006		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-101581	NO. 1 ENGINE - INTRODUCTION OF AN OIL DRAIN TUBE SUPPORT BRACKET WITH A SLOTTED HOLE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
13-SEP-2007		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-101603	NO. 1 ENGINE - POWER PLANT - ENGINE ELECTRONIC CONTROLLER (EEC) LANE A HARNESS 1A - CLIP POSITION CHANGES FOR THE OIL LEVEL SENSOR CABLE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-FEB-2008		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-900675	NO. 1 ENGINE - POWER PLANT - GENERAL - ENGINE CONVERSION FROM A FLIGHT-TEST STANDARD ENGINE TO A PRODUCTION STANDARD ENGINE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
30-JAN-2020		MOS					
		HRS/MSC	-				
		ENC					
CHAPTER 72 ENGINE							
ASB R03 BR700-72-A101523	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, ALERT SERVICE BULLETIN					ALERT	NOT APPLICABLE
10-DEC-2015		MOS		07-MAR-2016			
		HRS/MSC	-				
		ENC					
ASB R07 BR700-72-A900229	NO. 1 ENGINE - BR700-72-A900229 R07 - LP COMPRESSOR - INSPECTION OF THE FAN - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN					ALERT	NOT APPLICABLE - BY ENGINE S/N
16-JUN-2023		MOS		20-JUN-2023			
		HRS/MSC	-				
		ENC					
ASB R07 PART 1 BR700-72-A900229	NO. 1 ENGINE - ACCOMPLISH BR700-72-A900229 R07 - LP COMPRESSOR - INSPECTION OF THE FAN - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN DO A VISUAL INSPECTION OF THE FAN DISC.					ALERT	NOT APPLICABLE - BY ENGINE S/N
16-JUN-2023		MOS		20-JUN-2023			
		HRS/MSC	-				
		ENC					
ASB R07 PART 2 BR700-72-A900229	NO. 1 ENGINE - ACCOMPLISH BR700-72-A900229 R07 - LP COMPRESSOR - INSPECTION OF THE FAN - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN DO AN ULTRASONIC INSPECTION OF THE FAN DISC.					ALERT	NOT APPLICABLE - BY ENGINE S/N
16-JUN-2023		MOS		20-JUN-2023			
		HRS/MSC	-				
		ENC					
ASB BR700-72-A900297	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR FAIRINGS - INSPECTION OF THE UPPER LEFT HP COMPRESSOR FAIRING FOR POTENTIAL PROFILE NON-CONFORMANCE AND REPLACEMENT OF NON-CONFORMING UPPER LEFT HP COMPRESSOR FAIRING - NON-MODIFICATION, ALERT SERVICE BULLETIN					ALERT	NOT APPLICABLE
02-SEP-2013		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASB BR700-72-A900298	NO. 1 ENGINE - ENGINE COMBUSTION FAIRINGS - REPLACEMENT OF NON-CONFORMING UPPER LEFT, UPPER RIGHT AND LOWER RIGHT COMBUSTION SECTION FAIRINGS - NON-MODIFICATION, ALERT SERVICE BULLETIN					ALERT	NOT APPLICABLE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
ASB BR700-72-A900497	NO. 1 ENGINE - HPT ROTOR DISCS - DECREASE OF TIME LIMITS MANUAL MAXIMUM APPROVED LIVES OF STG 1 & 2 DISCS, ALERT SERVICE BULLETIN					ALERT	COMPLIED WITH - AT MANUFACTURE
12-FEB-2010		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
ASB R01 BR700-72-A900504	NO. 1 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT, ALERT SERVICE BULLETIN					ALERT	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
ASB BR700-72-A900508	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 AND 2 DISCS DUE TO POTENTIAL STEEL INCLUSION - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
26-JUL-2012		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
ASB R03 BR700-72-A900509	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
ASB BR700-72-A900584	NO. 1 ENGINE - GENERAL - ENGINE INSTALLATION RESTRICTION AND CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN					ALERT	COMPLIED WITH - WORK ACCOMPLISHED
31-JAN-2017		MOS		07-APR-2017			
		HRS/MSC	-	383:54			
ASB R01 BR700-72-A900584	NO. 1 ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN					ALERT	COMPLIED WITH - WORK DONE
05-OCT-2017		MOS		02-NOV-2017			
		HRS/MSC	-	521:10			
		ENC		194			
ASB R01 PART A BR700-72-A900584	NO. 1 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN INSTRUCTIONS TO DETERMINE THE EFFECTIVE ENGINE POPULATION					ALERT	COMPLIED WITH - WORK DONE
05-OCT-2017		DAYs		02-NOV-2017			
		HRS/MSC	-	521:10			
		ENC		194			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASB BR700-72-A900584 R01 PART B	NO. 1 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN INSTRUCTIONS ON HOW TO CALCULATE THE LIVES FOR AFFECTED PARTS ON ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT HAVING BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 STANDARD INCORPORATED					ALERT	COMPLIED WITH - WORK DONE
05-OCT-2017		MOS HRS/MSC - ENC		02-NOV-2017 521:10 194			
ASB BR700-72-A900659	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN						NOT APPLICABLE
22-JUL-2019		MOS HRS/MSC - ENC					
ASB BR700-72-A900659 PART A	NO. 1 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REMOVAL OF THE ENGINE FOR INCORPORATION OF PART B OF THIS NON-MODIFICATION SERVICE BULLETIN						NOT APPLICABLE
22-JUL-2019		MOS HRS/MSC - ENC					
ASB BR700-72-A900659 PART B	NO. 1 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REPLACEMENT OF HIGH PRESSURE (HP) TURBINE STAGE 1 DISCS						NOT APPLICABLE
22-JUL-2019		MOS HRS/MSC - ENC					
ASB BR700-72-A900659 R01	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - ALERT SERVICE BULLETIN, ALERT SERVICE BULLETIN						NOT APPLICABLE
05-NOV-2019		MOS HRS/MSC - ENC					
ASB BR700-72-A900659 R01 PART A	NO. 1 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REMOVAL OF THE ENGINE FOR INCORPORATION OF PART B OF THIS NON-MODIFICATION SERVICE BULLETIN						NOT APPLICABLE
05-NOV-2019		MOS HRS/MSC - ENC					
ASB BR700-72-A900659 R01 PART B	NO. 1 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REPLACEMENT OF HIGH PRESSURE (HP) TURBINE STAGE 1 DISCS						NOT APPLICABLE
05-NOV-2019		MOS HRS/MSC - ENC					
ASB BR700-72-A900732 R01	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - VISUAL INSPECTION OF THE LP - COMPRESSOR ROTOR (FAN) DISC - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN				ALERT		NOT APPLICABLE - BY ENG S/N
16-JUN-2023		MOS HRS/MSC - ENC		20-JUN-2023			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100025 R02	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF HPC FRONT SPLIT CASING WITH INCREASED CAST BOSS DIAMETERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100044 R03	NO. 1 ENGINE - ENGINE - HP COMPRESSOR (HPC) - INTRODUCTION OF VARIABLE STATOR VANES SOLID TIE RODS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JAN-2012		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100109	NO. 1 ENGINE - ENGINE - HP COMPRESSOR (HPC) - INTRODUCTION OF VARIABLE STATOR VANES SOLID TIE RODS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-AUG-1997		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100110 R02	NO. 1 ENGINE - ENGINE - HP TURBINE - INTRODUCTION OF SILVER PLATING TREATMENT TO THREAD AND FLANK OF INTRASCOPE HOUSING BLANKING PLUG, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-JUL-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100138	NO. 1 ENGINE - ENGINE - LPC STATOR VANES - INTRODUCTION OF NEW LP COMPRESSOR STATOR VANE ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-OCT-1997		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100149	NO. 1 ENGINE - ENGINE - DRESSING AND NON DRESSING - MINOR ALTERATIONS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100150	NO. 1 ENGINE - ENGINE - FAIRING, INTAKE ROTATING - LP COMPRESSOR - INTRODUCTION OF A LIGHTWEIGHT LP COMPRESSOR NOSECONE FAIRING ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-SEP-1997		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100152 R01	NO. 1 ENGINE - ENGINE - ENGINE MOUNTING SUPPORT - INTRODUCTION OF A NEW REAR MOUNT RING ASSEMBLY WITH REDUCED WEIGHT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-NOV-1997		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100157	NO. 1 ENGINE - ENGINE - LP COMPRESSOR BLADES - INTRODUCTION OF LIGHTWEIGHT LP COMPRESSOR DISK SEALING PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-SEP-1997		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100158 R01	NO. 1 ENGINE - ENGINE - VANES, STATOR, EXIT GUIDE - LP COMPRESSOR - INTRODUCTION OF CAST ALUMINUM OUTLET GUIDE VANE ASSEMBLY WITH POTTED OUTER END AND DAMPED INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-SEP-2000		MOS HRS/MSC ENC	-	23-SEP-2015 0 0			
SB BR700-72-100159 R01	NO. 1 ENGINE - ENGINE - HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED HP 1 NOZZLE GUIDE VANES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-JUL-1998		MOS HRS/MSC ENC	-	23-SEP-2015 0 0			
SB BR700-72-100162	NO. 1 ENGINE - ENGINE - DISC, ROTOR - LP COMPRESSOR - INTRODUCTION OF A REDUCED WEIGHT ROTOR DISC WITH RE-PROFILED DOVETAIL SLOT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-OCT-1999		MOS HRS/MSC ENC	-	23-SEP-2015 0 0			
SB BR700-72-100164 R01	NO. 1 ENGINE - ENGINE - CASE AND FITTINGS - COMPRESSOR INTERMEDIATE (LP TO IP/HP) - INTRODUCTION OF ENGINE VIBRATION MONITOR TRANSDUCER MOUNTING PLATE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS HRS/MSC ENC	-	23-SEP-2015 0 0			
SB BR700-72-100172 R02	NO. 1 ENGINE - ENGINE - HPC REAR INNER CASE - INTRODUCTION OF A NEW ABRADABLE LINING MATERIAL ON THE ROTOR PATH LINERS OF HPC STAGE 5, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2003		MOS HRS/MSC ENC	-	23-SEP-2015 0 0			
SB BR700-72-100178	NO. 1 ENGINE - ENGINE - ATTACHING PARTS AND FITTINGS - BYPASS DUCT MODULE - REVISED ENGINE BUILD-UP (EBU) FLANGE BRACKETS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUL-1998		MOS HRS/MSC ENC	-	23-SEP-2015 0 0			
SB BR700-72-100186	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF VARIOUS IMPROVEMENTS TO THE GEARBOX ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
05-MAR-1998		MOS HRS/MSC ENC	-	23-SEP-2015 0 0			
SB BR700-72-100194 R01	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF REDUCED STAGE 4 TO 10 PLATFORM GAPS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
16-JUL-1998		MOS HRS/MSC ENC	-	23-SEP-2015 0 0			
SB BR700-72-100195	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE - FIRE DETECTOR AND OVERHEAT PROBE PROTECTOR TUBES - REVISED LOCATION FEATURE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
31-MAY-1997		MOS HRS/MSC ENC	-	23-SEP-2015 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100200 R02	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - FRONT BEARING AND SUPPORT - INTRODUCTION OF AN ALTERNATIVE NO. 3 BEARING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100202 R01	NO. 1 ENGINE - ENGINE - EXTERNALS - MINOR ENGINEERING MODIFICATIONS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
21-JUN-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100205	NO. 1 ENGINE - ENGINE - HP COMPRESSOR (HPC) - INTRODUCTION OF STAGE 7/8 HEATSHIELD WITH REDUCED CIRCUMFERENTIAL GAP, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
17-MAY-1997		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100207 R02	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF A TUBED VORTEX REDUCER AND A MODIFIED STAGE 7 TO 10 ROTOR ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100226	NO. 1 ENGINE - ENGINE - REPLACEMENT, DELETION OR INTRODUCTION OF NEW INSTRUCTIONS AND ARRANGEMENTS TO AMEND THE DIS10005., SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100229	NO. 1 ENGINE - ENGINE - SHAFT, ROTOR - LP TURBINE - INTRODUCTION OF LP TURBINE SHAFT IN SUPER S/CMV MATERIAL WITH REPROFILED INTERNAL BORE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-APR-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100233	NO. 1 ENGINE - ENGINE - RING, BLADE RETAINING - LP COMPRESSOR - INTRODUCTION OF A LIGHTWEIGHT RETAINING RING ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-SEP-1997		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100241	NO. 1 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF INTRASCOPE BLANK EXTRACTION FEATURE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
19-MAR-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100263	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A SLEEVE IN THE PRESSURE RELIEF VALVE BORE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-AUG-1997		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100263 R01	NO. 1 ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A SLEEVE IN THE PRESSURE RELIEF VALVE (PRV) HOUSING BORE OF THE ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
19-JAN-2016		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-72-100265 R03	NO. 1 ENGINE - ENGINE - TURBINE AND REAR SUPPORT - INTRODUCTION OF REVISED FUEL SHUT OFF CABLE SETTING INSTRUCTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100266	NO. 1 ENGINE - ENGINE - TURBINE AND REAR SUPPORT - INTRODUCTION OF REVISED LPT EXHAUST CASE FUEL SHUT OFF EXIT RADIUS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-JUN-1997		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100267	NO. 1 ENGINE - ENGINE - INTRODUCTION OF ADDITIONAL CLIPPING AMENDMENTS DUE TO PODDING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-APR-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100268	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF SILVER COATED STAGE 1, 3 AND 5 INTRASCOPE PLUGS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-FEB-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100280	NO. 1 ENGINE - ENGINE - EXHAUST CASE - INTRODUCTION OF WEIGHT REDUCED LP TURBINE OUTLET GUIDE VANE (OGV) AND DOUBLE ENDED UNIONS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100281	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED COMBUSTION CHAMBER INNER CASE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100284 R01	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF REDUCED WEIGHT HP COMPRESSOR REAR OUTER CASE AND REVISED INTRASCOPE HOUSINGS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
19-DEC-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100290	NO. 1 ENGINE - ENGINE - BYPASS SERVICES FAIRING - MINOR CONFIGURATION AMENDMENTS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
16-JUL-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100291	NO. 1 ENGINE - ENGINE - VARIOUS - ADDITIONAL DRESSING MODIFICATIONS RELATING TO THE DELETION OF THE AIR COOLED OIL COOLER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
02-JUN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100296 R01	NO. 1 ENGINE - ENGINE - SUPPORT, BEARING FRONT - LOW PRESSURE (LP) COMPRESSOR/DRIVEN ASSEMBLY - INTERNAL GEARBOX DRIVE - INTRODUCTION OF REVISED NO.1 AND NO.2 BEARING SUPPORT HOUSINGS AND ASSOCIATED COMPONENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-JAN-2009		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100299 R01	NO. 1 ENGINE - ENGINE - BYPASS DUCT, ELECTRICAL HARNESSES AND ELECTRONIC ENGINE CONTROLLER (EEC) - DELETION OF EEC TROUGH AND INTRODUCTION OF EEC FIRE BOX AND ASSOCIATED MODIFICATIONS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100301	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED STAGE 1 DISC, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100302 R01	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED STAGE 2 DISC, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100303	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED REAR HEATSHIELD ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-JAN-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100304	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED HP TURBINE CASE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-MAR-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100311	NO. 1 ENGINE - ENGINE - CASE LP COMPRESSOR - INTRODUCTION OF LP COMPRESSOR CASE ASSEMBLY WITH INCREASED THICKNESS FAN TRACK LINER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-APR-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100319	NO. 1 ENGINE - ENGINE - HP COMPRESSOR (HPC) - INTRODUCTION OF STAGE 6 BLADES WHICH INCORPORATE A FORGED PLATFORM RAMP, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
03-DEC-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100320	NO. 1 ENGINE - ENGINE - LP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED LP 1 BLADE DAMPERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
02-JUN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100322	NO. 1 ENGINE - ENGINE - MANIFOLD, IMPINGEMENT COOLING - HP TURBINE - ADDITIONAL LOAD SPREADING STRIPS ON THE FRONT AND REAR MOUNTING BRACKET SECURING FEATURES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-DEC-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100333	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF STAGE 10 BLADES WITH INCREASED PLATFORM WIDTH, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100336	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF STAGE 9 BLADES WITH INCREASED PLATFORM WIDTH AND ROOT DEPTH, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100337	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF STAGE 8 BLADES WITH INCREASED PLATFORM WIDTH AND ROOT DEPTH, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-MAR-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100346	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR - INTRODUCTION OF VARIABLE VANE INNER SHROUD BUSHES WITH REVISED TOLERANCES ON INNER AND OUTER DIAMETERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
02-JUN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100347	NO. 1 ENGINE - ENGINE - EXHAUST CASE - INTRODUCTION OF AN LP TURBINE OUTLET GUIDE VANE (OGV) ASSEMBLY WITH MODIFIED STAGE 2 SHROUD RETENTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100353	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF ALUMINUM ALLOY UNISON RING CENTRALIZERS FOR WEIGHT REDUCTION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100362	NO. 1 ENGINE - ENGINE - INTERMEDIATE CASE MODULE - INTRODUCTION OF A NEW LOW PRESSURE SHAFT SPEED PROBE WITHOUT FUSE WIRES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-MAR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100373	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE - INTRODUCTION OF A REAR BEARING SUPPORT STRUCTURE (RBSS) BEARING BORE OFFSET, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-NOV-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100380 R01	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF A WEIGHT REDUCED COMBUSTION CHAMBER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-SEP-2005		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100381	NO. 1 ENGINE - ENGINE - EEC LANE A HARNESS 2A - INTRODUCTION OF A REVISED HARNESS LENGTH, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100382 R01	NO. 1 ENGINE - ENGINE - LP TURBINE - INTRODUCTION OF WEIGHT REDUCED LP TURBINE STAGE 1 SHROUD SEGMENTS AND WEIGHT REDUCED LP TURBINE CASE WITH IMPROVED SURFACE PROTECTION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100383	NO. 1 ENGINE - ENGINE - HP TURBINE - INTRODUCTION OF WEIGHT-REDUCED HP TURBINE STAGE 2 NOZZLE GUIDE VANES WITH REVISED COOLING AIR FLOW CHARACTERISTICS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
25-NOV-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100387	NO. 1 ENGINE - ENGINE - HP COMPRESSOR MODULE - DELETION OF WASHERS ON FLANGE CB, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100393	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE ATTACHING PARTS AND FITTINGS - INTRODUCTION OF BRACKETS MADE OF INCO 718 MATERIAL, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100401	NO. 1 ENGINE - ENGINE - LP COMPRESSOR (FAN) MODULE - ATTACH PARTS AND FITTINGS - INTRODUCTION OF A REVISED LP COMPRESSOR ANTI-SCORE RING IN CORROSION RESISTANT STEEL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100405	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE AND ENGINE MOUNTING SUPPORT - MINOR AMENDMENTS TO BRING THE CONFIGURATION DATABASE IN LINE WITH THE ENGINES AS BUILT, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100408	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF A NEW VANE TIP GRINDING AND ROTOR PATH MACHINING INSTRUCTION, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100411	NO. 1 ENGINE - ENGINE - ATTACHING PARTS AND FITTINGS - INTRODUCTION OF WEIGHT REDUCED EBU BRACKETS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100419 R01	NO. 1 ENGINE - ENGINE - LP COMPRESSOR BLADES - INTRODUCTION OF FAN ANNULUS FILLERS WITH POSITIVE BUSH LOCATION AND REVISED SEALING STRIPS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-DEC-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100433 R02	NO. 1 ENGINE - ENGINE - CASE AND FITTINGS - COMPRESSOR INTERMEDIATE (LP TO IP/HP) - INTRODUCTION OF REVISED CASE WITH MODIFIED EARTHING BRACKETS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
11-JAN-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100461 R01	NO. 1 ENGINE - ENGINE - LP COMPRESSOR - INTRODUCTION OF LP COMPRESSOR BLADES WITH REVISED TRAILING EDGE, MOMENT LIMITS AND DEFINITION OF FREQUENCY LIMITS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-DEC-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100463	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF OIL-FILLING INSTRUCTION LABELS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100475 R02	NO. 1 ENGINE - ENGINE - HP COMPRESSOR MODULE - INTRODUCTION OF NEW VANES ON THE HPC STAGES 6 TO 9, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
03-APR-2003		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100494	NO. 1 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF A PRESSURE RECOVERY DEVICE IN THE PRECOOLER FAN AIR FLOW LINE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
09-SEP-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100506	NO. 1 ENGINE - ENGINE - LP COMPRESSOR CASE - INTRODUCTION OF A REVISED STARTER EFFLUX SHIELD WITH EDGE PROTECTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-JAN-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100544 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A MOUNT KIT WITH IMPROVED PROTECTION AND DELETION OF THE BREather COVER INSTRUMENTATION BOSS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
05-AUG-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100563 R01	NO. 1 ENGINE - LP/HP TURBINE SUPPORT AND OUTER BEARINGS - INTRODUCTION OF STAGE 4 AIR TUBES AND REAR BEARING SUPPORT STRUCTURE (RBSS) WITH INCREASED CONTACT AREA, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100564 R01	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - REMOVAL OF INSULATION STRIPS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-MAY-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100566 R02	NO. 1 ENGINE - ENGINE - HPC REAR INNER CASE - INTRODUCTION OF A NEW ABRADABLE LINING MATERIAL ON THE ROTOR PATH LINERS OF HPC STAGE 6, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2003		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100600 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A NEW STANDARD OF MAIN HOUSING AND ASSOCIATED ASSEMBLY IMPROVEMENTS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-JUN-2005		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100621	NO. 1 ENGINE - ENGINE - HP COMPRESSOR VARIABLE INLET GUIDE VANE ACTUATING MECHANISM - INTRODUCTION OF REDUCED LENGTH VARIABLE STATOR VANE ACTUATOR (VSVA) BRACKET CONNECTING DOWELS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100623	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF REDUCED WEIGHT HP COMPRESSOR STAGE 1 TO 6 ROTOR DISKS ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100635	NO. 1 ENGINE - ENGINE - HP COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) RINGS AND SEALS - INTRODUCTION OF A NEW VIGV INNER SHROUD, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-DEC-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100643	NO. 1 ENGINE - ENGINE - INTERMEDIATE CASE MODULE ATTACHING PARTS AND FITTINGS - INTRODUCTION OF REVISED FASTENERS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100671	NO. 1 ENGINE - ENGINE - HPT BLADES - INTRODUCTION OF HP TURBINE STAGE 2 BLADE DAMPERS WHICH ARE MANUFACTURED AS A PRECISION CASTING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-OCT-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100681 R01	NO. 1 ENGINE - ENGINE - LP COMPRESSOR INTAKE ROTATING FAIRING - INTRODUCTION OF REVISED NOSE CONE ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-OCT-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100686	NO. 1 ENGINE - ENGINE - NL SPEED PROBE HARNESS AND ACCESSORIES - REDUCED NUMBER OF SPEED PROBE WASHERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100704	NO. 1 ENGINE - ENGINE - COMBUSTION INNER CASE AND VANES - INTRODUCTION OF COMPRESSOR OUTLET GUIDE VANES (OGV)/DIFFUSER CASE WITH IMPROVED AIR FLOW CHARACTERISTICS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100712	NO. 1 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF NEW HP COMPRESSOR VSV SYSTEM DRIVE BRACKETS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
16-DEC-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100720 R01	NO. 1 ENGINE - ENGINE - HP COMPRESSOR BLADES - INTRODUCTION OF REVISED STAGES 6 TO 10 BLADE PLATFORM GAPS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-MAY-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100733	NO. 1 ENGINE - ENGINE - LPC FRONT AND REAR (NO. 1, 2 AND 3) BEARING AND SUPPORT - INTRODUCTION OF ALTERNATIVE SQUEEZE FILM PISTON RINGS., SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
16-DEC-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100770 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF SHOT PEENED GEARS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2003		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100785	NO. 1 ENGINE - ENGINE - HP TURBINE - INTRODUCTION OF DECREASED COLD BUILD CLEARANCE ON STAGE 1 HP TURBINE AND DELETION OF DRY FILM LUBRICANT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100805 R01	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF NEW PROCEDURE FOR TIP GRINDING OF HP COMPRESSOR VANES AND IN-SERVICE ROTOR BLADE NUMBERING PROCEDURE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100812	NO. 1 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF A VIGV UNISON RING WITH IMPROVED CORROSION RESISTANCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JAN-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100813	NO. 1 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF A VSV STAGE 1 UNISON RING WITH IMPROVED CORROSION RESISTANCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100814	NO. 1 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF A VSV STAGE 2 UNISON RING WITH IMPROVED CORROSION RESISTANCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JAN-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100815	NO. 1 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF A VSV STAGE 3 UNISON RING WITH IMPROVED CORROSION RESISTANCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100818	NO. 1 ENGINE - ENGINE - LP COMPRESSOR ROTOR SHAFT - INTRODUCTION OF FAN SHAFT ASSEMBLY WITH REVISED MATERIAL PHONIC WHEEL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-OCT-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100840	NO. 1 ENGINE - ENGINE - HP TURBINE ROTOR DISKS - INTRODUCTION OF A REVISED MANUFACTURING PROCESS FOR HPT STAGE 1 DISKS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100845 R02	NO. 1 ENGINE - ENGINE - NL SPEED PROBE HARNESS AND ACCESSORIES - INTRODUCTION OF A NEW HARNESS ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
16-MAY-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100848	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF AN ACCESSORY GEARBOX WITH ALL GEARS SHOT PEENED ON THE EXTERNAL SURFACES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-JUN-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100851 R02	NO. 1 ENGINE - ENGINE - LP COMPRESSOR (FAN) MODULE - INTRODUCTION OF A COMMON MASTER PART, SERVICE BULLETIN				INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE	
15-FEB-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100852 R02	NO. 1 ENGINE - ENGINE - LP COMPRESSOR CASE MODULE - INTRODUCTION OF A COMMON MASTER PART, SERVICE BULLETIN				INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE	
19-DEC-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100853 R01	NO. 1 ENGINE - ENGINE - LP TURBINE MODULE - INTRODUCTION OF A COMMON MASTER PART, SERVICE BULLETIN				INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE	
09-NOV-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100859	NO. 1 ENGINE - ENGINE - LPC REAR (NO.2) BEARING ASSEMBLY FRONT PANEL - INTRODUCTION OF REVISED MATERIAL SPEED PROBE SUPPORT BRACKET, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
16-DEC-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100865	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A NEW STANDARD OF INSERT IN THE HAND CRANK FLANGE OF THE BREATHER COVER, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
20-DEC-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100867	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - CHANGES TO THE CONTOUR OF THE GEARBOX MAIN HOUSING, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
08-NOV-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100879 R01	NO. 1 ENGINE - LP/HP TURBINE STATOR RETAINERS/SEALS - INTRODUCTION OF ABRADABLE LININGS WITH INCREASED CORROSION RESISTANCE, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - AT MANUFACTURE	
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100899 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF THINNER ADJUSTING SHIMS AT BEVEL GEAR LINE 1 AND 2, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
11-JUN-2003		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100900 R01	NO. 1 ENGINE - HP COMPRESSOR AND COMBUSTION FAIRINGS-INTRODUCTION OF NEW FAIRINGS WITH NEW ATTACHMENT FEATURES, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - AT MANUFACTURE	
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100901	NO. 1 ENGINE - ENGINE - HPC ROTOR HYDRAULIC SEAL - INTRODUCTION OF AN HP COMPRESSOR HYDRAULIC SEAL ASSEMBLY WITH INCREASED CLEARANCE BETWEEN THE SEAL AND THE LP TURBINE SHAFT, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
12-FEB-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100902	NO. 1 ENGINE - ENGINE - LPC PHONIC WHEEL - INTRODUCTION OF A REAR INNER BEARING ASSEMBLY WITH INCREASED CLEARANCE BETWEEN THE BEARING INNER RACE AND THE LP TURBINE SHAFT, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
11-OCT-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100903	NO. 1 ENGINE - ENGINE - HP TURBINE ROTOR SHAFT AND (NO 4) BEARING - INTRODUCTION OF ABRADABLE LINING WITH INCREASED CORROSION RESISTANCE, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
28-APR-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100913	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF ALTERNATIVE MOUNT WASHERS MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
28-APR-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100944 R03	NO. 1 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE ATTACH PARTS AND FITTINGS - DRESSING CHANGES FOR THE NEW HP COMPRESSOR AND COMBUSTION FAIRINGS, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
18-JAN-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100952 R01	NO. 1 ENGINE - ENGINE - LP TURBINE FAIRINGS - INTRODUCTION OF LP TURBINE FAIRINGS WITH INCREASED WIDTH RELIEF SLOTS, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
30-JUL-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100976 R03	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INCREASED CLEARANCE BETWEEN THE GENERATOR MAGNETIC SEALS AND THEIR RELATED AIR BLOWN SEALS AND BETWEEN THE ACCESSORY GEARBOX GEAR LINE 6 AND THE HYDRAULIC PUMP SPLINE, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
13-SEP-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100978 R01	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF DECREASED COLD BUILD TIP CLEARANCES FOR THE HP COMPRESSOR STAGES 5, 6, 7 AND 9 STATOR VANES, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
12-JUL-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100981 R01	NO. 1 ENGINE - ENGINE - LP COMPRESSOR - CASE - INTRODUCTION OF REVISED FAN TRACK LINER AND ICE IMPACT PANEL ADHESIVE AND FILLER, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
20-JAN-2004		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100985	NO. 1 ENGINE - ENGINE - HP COMPRESSOR BLADES - REMOVAL OF THE HP COMPRESSOR STAGES 1, 2 AND 3 ROTOR BLADE UNDERPLATFORM STRIP SEALS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-SEP-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101006	NO. 1 ENGINE - ENGINE - COMBUSTION FAIRINGS - INTRODUCTION OF NEW FASTENERS FOR COMBUSTION CENTRE CORE FAIRINGS AND LP TURBINE DIAPHRAGMS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
19-OCT-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101007	NO. 1 ENGINE - ENGINE - HPC FRONT (NO. 3) BEARING SUPPORT - INCREASED CLEARANCE BETWEEN THE NUMBER 2 RECOMMENDED BEARING HOUSING AND THE NUMBER 3 BEARING RETAINER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-JUL-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101019	NO. 1 ENGINE - ENGINE - LPC BEARING SEALS - INTRODUCTION OF NEW INTERNAL GEARBOX FORWARD AIR SEAL PISTON RING SEAL MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101020	NO. 1 ENGINE - ENGINE - LPC INTAKE ROTATING FAIRING - INTRODUCTION OF A NEW NOSE CONE FAIRING ASSEMBLY., SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
23-NOV-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101032	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW MATERIAL FOR MOUNT BUSHES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-JAN-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101037 R01	NO. 1 ENGINE - ENGINE - HPC REAR OUTER CASE - INTRODUCTION OF NEW HP COMPRESSOR STAGE 9 INTRASCOPE PLUG ASSEMBLIES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
04-SEP-2003		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101038	NO. 1 ENGINE - ENGINE - HPC REAR OUTER CASE - INTRODUCTION OF HP COMPRESSOR STAGE 5 INTRASCOPE PLUGS MADE FROM A DIFFERENT MATERIAL AND WITH A DECREASED THREAD DIAMETER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-FEB-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101057 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF CHANGES BECAUSE OF A SUPPLIER TRANSFER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
13-JUL-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101060 R01	NO. 1 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF A NEW ENGINE NAME PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-SEP-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101068	NO. 1 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF DECREASED COLD BUILD TIP CLEARANCES FOR HP COMPRESSOR ROTOR BLADES AND STATOR VANES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-FEB-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101069	NO. 1 ENGINE - ENGINE - HPC VARIABLE INLET GUIDE VANE (VIGV) ACTUATING MECHANISM - INTRODUCTION OF NUT RETAINERS WITH IMPROVED FEATURES FOR EASIER ASSEMBLY OF THE UNISON RINGS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-JUN-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101084 R01	NO. 1 ENGINE - ENGINE - LPC FRONT (NO. 1) BEARING AND SUPPORT - INTRODUCTION OF A NO. 1 BEARING WITH A NEW DIAMETRAL CLEARANCE AND A RADIUSED INNER SPLIT LINE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-NOV-2005		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101088	NO. 1 ENGINE - ENGINE - LPC STATOR VANES - INTRODUCTION OF AN ENGINE SECTION STATOR (ESS) WITH A NEW FILLER MATERIAL FOR THE PLATFORM, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-FEB-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101090 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW IDENTIFICATION PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUN-2003		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101091	NO. 1 ENGINE - ENGINE - HPT 1 NGV - INTRODUCTION OF HP TURBINE STAGE 1 NOZZLE GUIDE VANES WITH NEW FILM COOLING HOLE CONFIGURATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101100 R02	NO. 1 ENGINE - ENGINE - HPC ROTOR SHAFT - INTRODUCTION OF A NEW HP COMPRESSOR STUB SHAFT WITH AN IMPROVED BALANCING PROCEDURE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-SEP-2004		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101102	NO. 1 ENGINE - ENGINE - HPC ROTOR REAR DISKS - INTRODUCTION OF A NEW HP COMPRESSOR STAGE 7 TO 10 ROTOR ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
13-JUL-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101103	NO. 1 ENGINE - ENGINE - HPC ROTOR FRONT DISKS - INTRODUCTION OF A NEW HP COMPRESSOR STAGE 1 TO 6 ROTOR ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JAN-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101107 R01	NO. 1 ENGINE - ENGINE - INTERMEDIATE CASE MODULE - DELETION OF JOINTING COMPOUND ON ENGINE SECTION STATOR (ESS) AND THE INTERNAL GEARBOX (IGB) MATING FACES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101114 R04	NO. 1 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF A BYPASS DUCT WITH NEW INSERTS FOR INSTALLATION OF A FUEL RETURN TO TANK VALVE AND FOR A REPOSITIONED LP FUEL SWITCH, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-NOV-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101116	NO. 1 ENGINE - ENGINE - LPC REAR NO. 2 BEARING ASSY FRONT PANEL - INTRODUCTION OF NEW O-RINGS WITH A DECREASED INTERNAL DIAMETER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
24-JAN-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101117	NO. 1 ENGINE - ENGINE - HPT BLADES - INTRODUCTION OF HP TURBINE STAGE 1 BLADES WITH A NEW FILM COOLING HOLE CONFIGURATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-NOV-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101117 R01	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF HP TURBINE STAGE 1 BLADES WITH A NEW FILM COOLING HOLE CONFIGURATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
26-SEP-2018		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-72-101128 R01	NO. 1 ENGINE - ENGINE - HPT ROTOR SHAFT AND NO. 4 BEARING - INTRODUCTION OF AN HP TURBINE NO. 4 STUB SHAFT WITH IDENTITY MARKINGS PERMITTED ONLY ON THE REAR FACE OF THE SHAFT, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
25-MAR-2008		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101139 R01	NO. 1 ENGINE - HPC ROTOR SHAFT-INTRODUCTION OF A NEW FITTING INSTRUCTION FOR THE HP COMPRESSOR STUB SHAFT TO ALIGN WITH THE HP COMPRESSOR ROTOR, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-DEC-2006		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101144	NO. 1 ENGINE - ENGINE - COMBUSTION INNER CASE AND VANES - INTRODUCTION OF A NEW COMBUSTION INNER FRONT CASING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-JUN-2003		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101150	NO. 1 ENGINE - ENGINE - NL SPEED PROBES - INTRODUCTION OF LP COMPRESSOR TRIM BALANCE AND SPEED PROBES WHICH ARE MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-DEC-2003		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101157	NO. 1 ENGINE - ENGINE - TURBINE EXHAUST SUPPORTS - INTRODUCTION OF NEW REAR MOUNT SUPPORT STRUTS WITH A DIFFERENT COATING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-MAR-2008		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101167	NO. 1 ENGINE - ENGINE - LPC ROTOR SHAFT - INTRODUCTION OF FAN SHAFT BOLTS WITH INCREASED HEAD THICKNESS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-AUG-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101173	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP)/HIGH PRESSURE (HP) TURBINE STATOR RETAINERS/SEALS - INTRODUCTION OF A NEW REAR BEARING SUPPORT STRUCTURE (RBSS) VENT DUCT, REAR HEAT SHIELD AND LP TURBINE SEAL CARRIER WHICH ARE DECREASED IN WEIGHT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-MAR-2007		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101174	NO. 1 ENGINE - ENGINE - COMBUSTION FAIRINGS - INTRODUCTION OF A LEFT HAND LOWER COMBUSTION FAIRING WITH A STRENGTHENED PRESSURE RELIEF DOOR, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-FEB-2003		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101175	NO. 1 ENGINE - ENGINE - LPC EXIT GUIDE STATOR VANES - INTRODUCTION OF A NEW PART NUMBER FOR THE ALUMINIUM OUTLET GUIDE VANE (OGV) ASSEMBLY WITH CHANGED CLASSIFICATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
25-JAN-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101177 R01	NO. 1 ENGINE - ENGINE - COMBUSTION OUTER CASE - INTRODUCTION OF A NEW COMBUSTION CHAMBER OUTER CASING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101179 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - CHANGES TO OIL DISTRIBUTORS, PLUGS, O-RINGS, INSERTS AND RETAINING RINGS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-MAY-2004		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101180	NO. 1 ENGINE - ENGINE - HPC VIGV AND STAGES 1-4 STATOR VANES - INTRODUCTION OF A NEW VARIABLE INLET GUIDE VANE (VIGV) ASSEMBLY WHICH IS DECREASED IN WEIGHT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-AUG-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101181	NO. 1 ENGINE - ENGINE - HPC VIGV AND STAGES 1 - 4 STATOR VANES - INTRODUCTION OF A NEW STAGE 1 VANE ASSEMBLY WHICH IS DECREASED IN WEIGHT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-AUG-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101190	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF NEW ACCESSORY GEARBOX LINE 1 AND LINE 2 BEVEL GEARS WHICH ARE MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-FEB-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101193 R01	NO. 1 ENGINE - ENGINE - HIGH PRESSURE COMPRESSOR (HPC) FRONT CASE - INTRODUCTION OF A NEW HPC FRONT CASE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
19-JUN-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101197	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF THE FIRE SHIELD ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-MAR-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101203 R01	NO. 1 ENGINE - ENGINE - HIGH PRESSURE COMPRESSOR (HPC) VARIABLE INLET GUIDE VANES (VIGV) ACTUATING MECHANISM - INTRODUCTION OF NEW HPC LEVERS WITH CHANGED TOLERANCES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAR-2003		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101204	NO. 1 ENGINE - ENGINE - COMBUSTION REAR INNER CASE - INTRODUCTION OF NEW FRONT AND REAR COMBUSTION INNER CASINGS WHICH ARE DECREASED IN WEIGHT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-JUN-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101205	NO. 1 ENGINE - ENGINE - HPT1 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW PRESWIRL NOZZLE WITH A DECREASED COOLING AIR FLOW TO THE HP 1 TURBINE ROTOR DISC AND BLADES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-MAR-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101216	NO. 1 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF A NEW ENGINE NAME PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-FEB-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101218	NO. 1 ENGINE - ENGINE - LPT FUEL SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF MECHANISM PAWLS WHICH HAVE A LARGER SURFACE CONTACT AREA WITH THE FUEL SHUT-OFF REFERENCE TUBE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-APR-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101218 R01	NO. 1 ENGINE - LOW PRESSURE (LP) TURBINE FUEL SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF MECHANISM PAWLS WHICH HAVE A LARGER SURFACE CONTACT AREA WITH THE FUEL SHUT-OFF REFERENCE TUBE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
03-DEC-2020		MOS HRS/MSC ENC	-				
SB BR700-72-101222	NO. 1 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF NEW BUILD INSTRUCTIONS TO DECREASE HIGH PRESSURE (HP) VIBRATION LEVELS, SERVICE BULLETIN				23-SEP-2015	OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JAN-2009		MOS HRS/MSC ENC	-	0	0		
SB BR700-72-101223 R02	NO. 1 ENGINE - ENGINE - LPT FUEL SHUT-OFF CABLE AND FITTINGS - INTRODUCTION OF INCREASED CLEARANCES BETWEEN THE FUEL SHUT-OFF CABLE AND ADJACENT DRESSINGS, SERVICE BULLETIN				23-SEP-2015	RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-MAY-2004		MOS HRS/MSC ENC	-	0	0		
SB BR700-72-101246	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR DISC - INTRODUCTION OF A NEW FAN DISC DESIGN FOR LIFE ENHANCEMENT, SERVICE BULLETIN				23-SEP-2015	OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC ENC	-	0	0		
SB BR700-72-101246 R01	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR DISC - INTRODUCTION OF A NEW FAN DISC DESIGN FOR LIFE ENHANCEMENT, SERVICE BULLETIN				23-SEP-2015	OPTIONAL	NOT APPLICABLE
28-OCT-2016		MOS HRS/MSC ENC	-				
SB BR700-72-101252	NO. 1 ENGINE - ENGINE - COMBUSTION LINER - INTRODUCTION OF A NEW COMBUSTOR HEAT SHIELD, SERVICE BULLETIN				23-SEP-2015	OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-APR-2002		MOS HRS/MSC ENC	-	0	0		
SB BR700-72-101254	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF CHANGES TO THE MANUFACTURING PROCEDURE FOR THE ACCESSORY GEARBOX LINE 1 AND LINE 2 BEVEL GEARS, SERVICE BULLETIN				23-SEP-2015	OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-JUL-2003		MOS HRS/MSC ENC	-	0	0		
SB BR700-72-101258 R01	NO. 1 ENGINE - ENGINE - LP COMPRESSOR CASE - INTRODUCTION OF A LP COMPRESSOR CASE WHICH IS MADE FROM A FORGING, SERVICE BULLETIN				23-SEP-2015	OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-OCT-2008		MOS HRS/MSC ENC	-	0	0		
SB BR700-72-101260	NO. 1 ENGINE - ENGINE - HPT ROTOR SHAFT AND (NO. 4) BEARING - INTRODUCTION OF AN HP TURBINE STUB SHAFT WHICH IS DECREASED IN WEIGHT, SERVICE BULLETIN				23-SEP-2015	OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC ENC	-	0	0		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101270	NO. 1 ENGINE - ENGINE - LP/HP TURBINE SUPPORT AND OUTER BEARINGS - INTRODUCTION OF FRONT AND REAR BEARING CHAMBER PISTON RINGS WITH A SPECIFIED ROUNDNESS VALUE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-JAN-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101271	NO. 1 ENGINE - ENGINE - HPC FRONT (NO 3) BEARING SUPPORT - INTRODUCTION OF NEW BOLTS TO ATTACH THE REAR LABYRINTH SEAL, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
28-JUN-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101275	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ACCESSORY GEARBOX MAIN HOUSING WITH AN IMPROVED MANUFACTURING PROCEDURE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-NOV-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101285	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX INPUT HOUSING AND ADJUSTING SHIMS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
16-JUN-2003		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101286	NO. 1 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF BYPASS DUCT ACCESS COVERS WITH TITANIUM OUTER SKINS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2004		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101293	NO. 1 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF A BYPASS DUCT (BPD) WHICH IS MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JUN-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101326 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW SELF LOCKING NUT FOR THE ACCESSORY GEARBOX LINE NUMBER 9 BREather SHAFT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
17-NOV-2008		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101328	NO. 1 ENGINE - ENGINE - HPT 2 LINERS - INTRODUCTION OF NEW HP TURBINE STAGE 2 LINERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2004		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101331	NO. 1 ENGINE - ENGINE - LPT CASE - INTRODUCTION OF DECREASED SHROUD TIP CLEARANCES BETWEEN THE LP TURBINE STAGE 1 AND 2 ROTOR BLADES AND THEIR RELATED SHROUD SEGMENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-MAY-2003		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101333	NO. 1 ENGINE - ENGINE - HPT ROTOR DISCS - INTRODUCTION OF A NEW STANDARD OF CURVIC RING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JUN-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101349	NO. 1 ENGINE - ENGINE - LPT FUEL SHUT-OFF CABLE AND FITTINGS - INTRODUCTION OF A NEW FUEL SHUT-OFF (FSO) CABLE WITH BRAZED-ON CLIPS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-JUN-2003		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101351 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ALTERNATIVE LINE 9 IMPELLER SHAFT WITH A NEW EXTERNAL THREAD DIAMETER TOLERANCE, NEW IDENTITY MARKINGS AND AN ALTERNATIVE MATERIAL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-JUL-2003		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101369	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR BLADES - INTRODUCTION OF NEW HP COMPRESSOR STAGE 5 AND 6 BLADES MADE FROM A NEW MATERIAL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-JAN-2006		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101395	NO. 1 ENGINE - ENGINE - LP COMPRESSOR BLADES - INTRODUCTION OF A METCO 58 COATING ON THE LP COMPRESSOR BLADES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-MAY-2004		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101414	NO. 1 ENGINE - HPC FRONT CASE - INTRODUCTION OF NEW COATED BUSHES FOR IMPROVED CORROSION PROTECTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-SEP-2003		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101416 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX LINE 12 SPACER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-AUG-2003		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101417	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX LINE 12 GEAR SHAFT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
27-FEB-2004		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101419 R02	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) VARIABLE INLET GUIDE VANE (VIGV) ACTUATING MECHANISM - INTRODUCTION OF A NEW BUILD INSTRUCTION TO INCREASE END FLOAT AND CENTRALISER GAP, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-MAR-2012		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101420	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE CASE - APPLICATION OF ANTI-SEIZURE COMPOUND ON DESIGNATED PLUGS OF COMBUSTOR AND TURBINE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-MAY-2004		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101421	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE STAGE 1 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW REAR BEARING SUPPORT STRUCTURE (RBSS) VENT DUCT MADE FROM A FORGING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-MAR-2007		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101431	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 1 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW ONE PIECE PRESWIRL NOZZLE AND WEB SEAL ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-MAY-2006		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101436 R01	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) EXIT GUIDE STATOR VANES - FAN OUTLET GUIDE VANE (OGV) RE-SOURCING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
03-MAR-2010		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101440	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE AND GEARBOX RADIAL DRIVE - INTRODUCTION OF REVISED INSTALLATION PROCEDURE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-MAR-2009		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101453 R01	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR STATOR VANES - INTRODUCTION OF A FULLY MACHINED ENGINE SECTION STATOR (ESS) BLADE INTEGRATED RING (BLING), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-APR-2013		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101454	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW MATERIAL FOR THE HP TURBINE SUPPORT RING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-JAN-2005		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101456	NO. 1 ENGINE - ENGINE LOW PRESSURE (LP) TURBINE SHUT OFF PAWL CARRIER - DELETION OF AN UNUSED TRIM BALANCE FEATURE ON THE PAWL CARRIER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
09-SEP-2004		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101457	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW MATERIAL FOR THE HP TURBINE RIM SEAL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-JAN-2005		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101461	NO. 1 ENGINE - ENGINE - COMBUSTION FAIRINGS - INTRODUCTION OF A NEW CORE FAIRING WITH BLOW OPEN DOOR REMOVED, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
01-JUN-2005		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101463	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR INNER CASE - INTRODUCTION OF A NEW STAGE 5 TO 10 REAR INNER CASE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-APR-2006		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101469 R01	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VORTEX REDUCER - INTRODUCTION OF A NEW FORGING MATERIAL FOR THE HP COMPRESSOR VORTEX REDUCER RING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
29-AUG-2014		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101471 R02	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - INTRODUCTION OF METCO 58 COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
28-JUL-2005		MOS		23-SEP-2015			
		HRS/MSC	A/R	0			
		ENC		0			
SB BR700-72-101474	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101476 R01	NO. 1 ENGINE - COMBUSTION LINER - INTRODUCTION OF A NEW COMBUSTION CHAMBER WITHOUT COOLING RIBS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
29-AUG-2014		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101490	NO. 1 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF A NEW RADIAL DRIVE SHAFT (RDS) LOWER SUPPORT HOUSING (LSH), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-JUL-2006		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101492	NO. 1 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF NEW INTRASCOPE BLANKS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-NOV-2005		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101493	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR INNER CASE - DELETION OF THE HP VCOMPRESSOR STAGE 5 AND STAGE 7 TO 8 HEAT-SHIELDS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-NOV-2005		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101498	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF METAL TRANSPORTATION BLANKS WITH PLASTIC TRANSPORTATION BLANKS AND INTRODUCTION OF ALTERNATIVE ORIGINAL SUPPLIER PART NUMBERS FOR CERTAIN ACCESSORY GEARBOX COMPONENTS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAR-2012		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101500	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101522	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW METHOD OF MANUFACTURE FOR ACCESSORY GEARBOX COMPONENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-FEB-2008		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101523 R02	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
19-DEC-2013		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101525	NO. 1 ENGINE - INTERMEDIATE CASE MODULE - INTRODUCTION OF NEW AND RE-IDENTIFIED INTERNAL GEARBOX COMPONENTS BECAUSE OF DESIGN RESPONSIBILITY CHANGE (SUPERSEDED BY SB BR700-72-101939), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-SEP-2006		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101526	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW LP TURBINE AXIAL SETTING PROCEDURE WITH AN INCREASED RANGE OF ADJUSTING RINGS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-NOV-2008		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101527	NO. 1 ENGINE - INTERMEDIATE CASE MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW AIR TURBINE STARTER BRACKET ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2007		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101531	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF NEW MANUFACTURING PROCEDURES FOR ACCESSORY GEARBOX COMPONENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-FEB-2008		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101540 R04	NO. 1 ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
29-AUG-2014		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101548	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INTRODUCTION OF A NEW LP COMPRESSOR CASE WITH NEW IMPROVED SEALING OF THE REAR PANEL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101551	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF BREATHER FILTER AND CHANGES TO BREATHER COVER, TANK COVERS AND OBTURATOR PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-MAY-2007		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101573	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR - INCREASED TIP CLEARANCE FOR HP COMPRESSOR STAGE 4 STATOR VANES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-SEP-2006		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101577	NO. 1 ENGINE - ENGINE - BYPASS DUCT ATTACHING PARTS AND FITTINGS - INTRODUCTION OF NEW BYPASS DUCT FRONT AND REAR LOAD SPREADER PLATE ASSEMBLIES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-JUL-2008		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101580	NO. 1 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF A NEW ENGINE NAME PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-SEP-2008		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101589	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ACCESSORY GEARBOX MAIN HOUSING MADE FROM ALUMINUM, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-FEB-2008		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101604 R01	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR BLADES - INTRODUCTION OF HP COMPRESSOR STAGE 1 BLADES WITH A THICKER LEADING EDGE CONTOUR, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
03-MAR-2010		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101618	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ACCESSORY GEARBOX OIL TANK OIL FILL INSTRUCTION LABEL SUITABLE FOR USE WITH AN ALUMINUM ACCESSORY GEARBOX MAIN HOUSING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-NOV-2007		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101623	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW LUBRICLONE FOR THE ACCESSORY GEARBOX, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
19-SEP-2007		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101663	NO. 1 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY AND LOW PRESSURE (LP) COMPRESSOR/INTERNAL GEARBOX OIL DISTRIBUTION TUBES - INTRODUCTION OF REVISED OIL JET HOUSINGS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
19-FEB-2010		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101664 R02	NO. 1 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF A NEW NO.2 BEARING SUPPORT HOUSING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
02-SEP-2010		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101669	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF NUTS WITH SILVER COATED THREAD ONLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-JAN-2010		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101699	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - INTRODUCTION OF A NEW LP COMPRESSOR ANNULUS FILLER WITH AN INTEGRAL HOOK DESIGN, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101705	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR ROTOR AND SHAFT DISCS - INTRODUCTION OF A NEW HP COMPRESSOR FRONT ROTOR ASSEMBLY WITH SHANK NUTS HAVING SILVER COATED THREADS ONLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
14-JAN-2011		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101722	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 ONWARD NOZZLE GUIDE SEALS - INTRODUCTION OF A DIFFERENT STANDARD HP TURBINE RIM SEAL ASSEMBLY AND HP TURBINE SUPPORT RING ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101728	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF A NEW MOUNTING BRACKET ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101734	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF CHANGES TO THE HP COMPRESSOR VARIABLE STATOR VANE (VSV) SYSTEM COMPONENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-JAN-2014		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101774	NO. 1 ENGINE - ENGINE - CORE ENGINE FAIRINGS - INTRODUCTION OF A NEW STANDARD OF CORE ENGINE FAIRINGS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101794	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) RINGS AND SEALS - INTRODUCTION OF NUTS WITH SILVER COATED THREADS ONLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
	MOS			23-SEP-2015			
	HRS/MSC	-		0			
	ENC			0			
SB BR700-72-101805 R04	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW STANDARD OF PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
	MOS			23-SEP-2015			
	HRS/MSC	-		0			
	ENC			0			
SB BR700-72-101813	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 1 LINER - INTRODUCTION OF NEW HP TURBINE STAGE 1 LINER SEGMENTS WITH AN INCREASED HONEYCOMB AREA (SUPERSEDED BY SB BR700-72-101971), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
	MOS			23-SEP-2015			
	HRS/MSC	-		0			
	ENC			0			
SB BR700-72-101817 R01	NO. 1 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - RECONFIGURATION OF THE VESPEL COUPLINGS AND THE RETAINING RINGS USED FOR INSTALLATION OF THE FUEL PUMP AND OIL PUMP AS NON-MODULAR PARTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
	MOS			23-SEP-2015			
	HRS/MSC	-		0			
	ENC			0			
SB BR700-72-101858	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-AUG-2014	MOS			23-SEP-2015			
	HRS/MSC	-		0			
	ENC			0			
SB BR700-72-101881	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ALTERNATIVE PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
	MOS			23-SEP-2015			
	HRS/MSC	-		0			
	ENC			0			
SB BR700-72-101884	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR OUTER CASE - INTRODUCTION OF AN ALTERNATIVE HP COMPRESSOR REAR OUTER CASE ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-MAY-2014	MOS			23-SEP-2015			
	HRS/MSC	-		0			
	ENC			0			
SB BR700-72-101887	NO. 1 ENGINE - HIGH PRESSURE (HP) COMPRESSOR MODULE - INTRODUCTION OF INCREASED TIP CLEARANCES FOR THE HP COMPRESSOR STAGES 6 TO 9 STATOR VANES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
	MOS			23-SEP-2015			
	HRS/MSC	-		0			
	ENC			0			
SB BR700-72-101953	NO. 1 ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF AN INSTRUCTION FOR MATCHED TIP GRINDING OF THE HP TURBINE STAGE 2 BLADES DURING NEW PRODUCTION OF THE ENGINE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
11-MAR-2016	MOS						
	HRS/MSC	-					
	ENC						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-900062 R02	NO. 1 ENGINE - ENGINE - INSTALLATION CHECK OF THE FASTENERS ON THE ENGINE COMPRESSOR AND COMBUSTION SECTION CORE FAIRINGS NON-MODIFICATION, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900062 R03	NO. 1 ENGINE - ENGINE - INSTALLATION CHECK OF THE FASTENERS ON THE ENGINE COMPRESSOR AND COMBUSTION SECTION CORE FAIRINGS NON-MODIFICATION, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
22-APR-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900062 R04	NO. 1 ENGINE - ENGINE - INSTALLATION CHECK OF THE FASTENERS ON THE ENGINE COMPRESSOR AND COMBUSTION SECTION CORE FAIRINGS NON-MODIFICATION, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
06-MAR-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900229 R01	NO. 1 ENGINE - LP COMPRESSOR INSPECTION OF FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900229 R02	NO. 1 ENGINE - LP COMPRESSOR INSPECTION OF FAN DISC, SERVICE BULLETIN						NOT APPLICABLE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900229 R03	NO. 1 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900229 R04	NO. 1 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN						NOT APPLICABLE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900229 R05	NO. 1 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN						NOT APPLICABLE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900229 R06	NO. 1 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
23-FEB-2005		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900229 R06	NO. 1 ENGINE - VISUAL INSPECTION OF THE FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
PART 1		MOS		23-SEP-2015			
23-FEB-2005		HRS/MSC	N/A	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-900229 R06	NO. 1 ENGINE - ULTRASONIC INSPECTION OF THE FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
PART 2							
23-FEB-2005		MOS		23-SEP-2015			
		HRS/MSC	N/A	0			
		ENC		0			
SB BR700-72-900455 R02	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN					RECOMMENDED	
PART A							
		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900455 R02	NO. 1 ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN					RECOMMENDED	
PART B							
		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900455 R03	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN					RECOMMENDED	
PART A							
		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900455 R03	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN					RECOMMENDED	
PART B							
		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900455 R04	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN					RECOMMENDED	
PART A							
		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900521 R04	NO. 1 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN					COMPLIED WITH - BR700-72-101699	
		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-72-900580 R01	NO. 1 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE OIL FILLER ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
04-APR-2016		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-72-900637	NO. 1 ENGINE - INTERMEDIATE CASE MODULE - INSPECTION OF THE RETENTION BOLTS OF THE NO.2/NO.3 BEARING HOUSINGS TO THE INTERMEDIATE CASE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
15-FEB-2018		MOS					
		HRS/MSC	-				
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-900743	NO. 1 ENGINE - BR700-72-900743 - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - ULTRASONIC INSPECTION OF THE LP COMPRESSOR ROTOR (FAN) DISC - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY ENG S/N
16-JUN-2023		MOS HRS/MSC - ENC		20-JUN-2023			
CHAPTER 73 ENGINE FUEL AND CONTROL							
ASB R03 BR700-73-A101977	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM, ALERT SERVICE BULLETIN					COMPLIED WITH - WORK DONE	
10-JUL-2017		MOS HRS/MSC - ENC		12-NOV-2018 823:40 292			
ASB BR700-73-A900083	NO. 1 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION, ALERT SERVICE BULLETIN					ALERT	NOT APPLICABLE
09-MAR-2015		MOS HRS/MSC - ENC					
ASB R01 BR700-73-A900083	NO. 1 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN					ALERT	NOT APPLICABLE
22-MAR-2017		MOS HRS/MSC - ENC					
ASB R02 BR700-73-A900083	NO. 1 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN					ALERT	NOT APPLICABLE
14-DEC-2018		MOS HRS/MSC - ENC					
ASB BR700-73-A900451	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL METERING UNIT (FMU) - COMBINED OVERSPEED SHUTOFF SOLENOID (COSS) SCREENING FOR REVERSE WIRED INDEPENDENT OVERSPEED PROTECTION (IOP) COILS, ALERT SERVICE BULLETIN					ALERT	NOT APPLICABLE
		MOS HRS/MSC - ENC		23-SEP-2015 0 0			
SB BR700-73-100148 R02	NO. 1 ENGINE - FUEL AND CONTROL - DRAINS EJECTOR FUEL FILTER - INTRODUCTION OF A FILTER IN THE LINE TO THE FUEL DRAINS EJECTOR PUMP AND RELATED DRESSINGS CHANGES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-JUL-1998		MOS HRS/MSC - ENC		23-SEP-2015 0 0			
SB BR700-73-100190	NO. 1 ENGINE - FUEL AND CONTROL - ELECTRONIC ENGINE CONTROL (EEC) - INTRODUCTION OF REVISED HARDWARE STANDARD, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
22-MAR-1997		MOS HRS/MSC - ENC		23-SEP-2015 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-100206	NO. 1 ENGINE - ENGINE FUEL AND CONTROL-TUBES AND FITTINGS, AIR-ENGINE FUEL CONTROL SYSTEM (EXTERNAL)-INTRODUCTION OF A REVISED P30 TUBE ASSEMBLY WITH BLEED HOLE IN MOISTURE TRAP, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
11-OCT-1997		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100219	NO. 1 ENGINE - FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF C3.1.1. SOFTWARE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-SEP-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100247	NO. 1 ENGINE - FUEL AND CONTROL - OVERSPEED SPLITTER UNIT - INTRODUCTION OF A NEW UNIT FEATURING AN IMPROVED SAFETY LOCK FEATURE BASED ON RING LOCKED FITTINGS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-FEB-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100271 R01	NO. 1 ENGINE - FUEL AND CONTROL - TUBES AND FITTINGS - INTRODUCTION OF MODIFIED TUBE ASSEMBLY END FITTINGS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100283 R02	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH - INTRODUCTION OF UNITS INCORPORATING A HERMETICALLY SEALED MICRO-SWITCH, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100352	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - CORE FUEL SYSTEM TUBES AND FITTINGS - INTRODUCTION OF REVISED BOLT LENGTH (CONFIGURATION SCHEME), SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100357	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF AN REVISED MOTIVE FUEL FILTER TUBE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
29-APR-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100363	NO. 1 ENGINE - FUEL AND CONTROL - FUEL METERING UNIT (FMU) - INTRODUCTION OF A NEW OPTIMISED FUEL METERING UNIT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-JUL-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100371 R02	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL LOW PRESSURE SWITCH - INTRODUCTION OF UNITS INCORPORATING A HERMETICALLY SEALED MICRO-SWITCH, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-100414	NO. 1 ENGINE - FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF C4.0 SOFTWARE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
03-JUL-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100440	NO. 1 ENGINE - FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF SOFTWARE VERSION C5.1.1, SERVICE BULLETIN				23-SEP-2015	RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-AUG-1998		MOS					
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100459 R01	NO. 1 ENGINE - FUEL AND CONTROL - FUEL SPRAY NOZZLES - INTRODUCTION OF A FUEL SPRAY NOZZLE ASSEMBLY WITH MODIFIED INTERNAL PARTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-SEP-2005		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100497	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF DRESSING CHANGES TO SUIT MODIFIED THERMAL ANTI-ICING VALVE AND MUSCLE LINE (NEUTRAL ENGINES), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-SEP-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100596	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROL (EEC) - INTRODUCTION OF IMPROVED EEC FIREBOX HANDLING ACCESS, SERVICE BULLETIN				23-SEP-2015	OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS					
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100689	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - HP FUEL FILTER - INTRODUCTION OF IMPROVED REMOVAL / INSTALLATION FEATURES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100709	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH C5.2.1 SOFTWARE STANDARD, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100732	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF AN AIR FEED RESTRICTOR TO THE CONFIGURATION DATABASE AND THE ENGINE DOCUMENTATION, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100827 R01	NO. 1 ENGINE - FUEL FLOW TRANSMITTER - INTRODUCTION OF A NEW UNIT WITH A MORE ACCURATE CALIBRATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	A/R	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-100835 R02	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - DATA ENTRY PLUG - INTRODUCTION OF A RE-TRIMMED DATA ENTRY PLUG TO INCREASE THE PERMITTED STATOR OUTLET TEMPERATURE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
10-APR-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100927 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH 05 OR 05R HARDWARE STANDARD, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100938	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF SOFTWARE C5.2.3. INTO AN EEC WITH 04 STANDARD HARDWARE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
20-OCT-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100964 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL MANIFOLD - INSTALLATION OF A DAMPER WIRE BETWEEN THE LEFT HAND (LH) AND RIGHT HAND (RH) FUEL MANIFOLD, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-OCT-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100970	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - INTRODUCTION OF NEW FITTING INSTRUCTIONS FOR ACCESSORY GEARBOX MOUNTED ACCESSORIES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
24-JAN-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101085 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL RETURN TO TANK VALVE - INTRODUCTION OF A FUEL RETURN TO TANK VALVE WITH RELATED DRESSING CHANGES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-OCT-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101094	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF A NEW FUEL TUBE WITH INCREASED CLEARANCE TO THE BUFFER AIR TUBE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-AUG-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101106 R01	NO. 1 ENGINE - ENGINE AND FUEL CONTROL - FUEL METERING UNIT - INTRODUCTION OF A NEW FUEL METERING UNIT WITH CHANGES TO THE COMBINED OVERSPEED AND SHUT-OFF SOLENOID, THE PRESSURE RAISING VALVE AND ELECTRO HYDRAULIC SERVO VALVE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-MAR-2001		MOS		23-SEP-2015			
		HRS/MSC	A/R	0			
		ENC		0			
SB BR700-73-101145 R03	NO. 1 ENGINE - ENGINE AND FUEL CONTROL-ENGINE ELECTRIC CONTROLLER-INTRODUCTION OF C6.0 SOFTWARE STANDARD INTO AN EEC WITH 05 OR 05B HARDWARE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	A/R	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101359	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF A FUEL TUBE WITH A NEW ROUTING TO INCREASE THE CLEARANCE BETWEEN THE TUBE AND THE V-BAND CLAMP FOR THE HP STAGE 5 BLEED, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
17-DEC-2002		MOS HRS/MSC ENC		23-SEP-2015 0 0			
SB BR700-73-101362	NO. 1 ENGINE - ENGINE - FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC HARDWARE STANDARD, SERVICE BULLETIN			OPTIONAL	OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
02-OCT-2002		MOS HRS/MSC ENC		23-SEP-2015 0 0			
SB BR700-73-101367	NO. 1 ENGINE - INTRODUCTION OF AN EEC WITH A NEW HARDWARE STANDARD (08), SERVICE BULLETIN			OPTIONAL	OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
		MOS HRS/MSC ENC		23-SEP-2015 0 0			
SB BR700-73-101386	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL MANIFOLD - CHANGE OF SUPPLIER SOURCE FOR THE FUEL MANIFOLD DAMPER WIRE, SERVICE BULLETIN			OPTIONAL	OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
06-JUL-2005		MOS HRS/MSC ENC		23-SEP-2015 0 0			
SB BR700-73-101396	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF NEW PART NUMBERS FOR TWO FUEL TUBE ASSEMBLIES, SERVICE BULLETIN			OPTIONAL	OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
22-MAR-2004		MOS HRS/MSC ENC		23-SEP-2015 0 0			
SB BR700-73-101415	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - CHANGE OF SUPPLIER SOURCE FOR THE FUEL SYSTEM P20, P30 AND P50 FLEXIBLE AIR TUBES, SERVICE BULLETIN			OPTIONAL	OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
05-MAY-2006		MOS HRS/MSC ENC		23-SEP-2015 0 0			
SB BR700-73-101429	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - DEDICATED GENERATOR - INTRODUCTION OF A NEW DEDICATED GENERATOR ROTOR WITH REDUCED OUT-OF-BALANCE (OOB) LIMITS, SERVICE BULLETIN			RECOMMENDED	RECOMMENDED	COMPLIED WITH - AT MANUFACTURE	
20-JAN-2004		MOS HRS/MSC ENC		23-SEP-2015 0 0			
SB BR700-73-101443	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - DATA ENTRY PLUG (DEP) - INTRODUCTION OF A NEW DEP, SERVICE BULLETIN			OPTIONAL	OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
05-MAY-2006		MOS HRS/MSC ENC		23-SEP-2015 0 0			
SB BR700-73-101451	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW LOCATION OF THE EEC CONNECT MODULE CAPACITOR, SERVICE BULLETIN			OPTIONAL	OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
08-JUN-2004		MOS HRS/MSC ENC		23-SEP-2015 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101472 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C7.0.2, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-NOV-2004		MOS		23-SEP-2015			
		HRS/MSC	A/R	0			
		ENC		0			
SB BR700-73-101477	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - T30 THERMOCOUPLES - INTRODUCTION OF A NEW T30 THERMOCOUPLE PROBE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-APR-2005		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101504	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW STANDARD OF EEC HARDWARE AND SOFTWARE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
19-NOV-2007		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101504 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW STANDARD OF EEC HARDWARE AND SOFTWARE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
10-JUL-2017		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-73-101505	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER (FFT) - INTRODUCTION OF A NEW FFT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-SEP-2005		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101509	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH PRINTED CIRCUIT BOARDS FROM A NEW SOURCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	A/R	0			
		ENC		0			
SB BR700-73-101558 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER (FFT) - INTRODUCTION OF A NEW FFT WITH IMPROVED ACCURACY LIMITS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
09-NOV-2007		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101559 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
27-FEB-2012		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101559 R02	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
10-JUL-2017		MOS					
		HRS/MSC	-				
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101559 R03	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
10-MAR-2021		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-73-101617 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER (FFT) - INTRODUCTION OF A FFT WITH A NEW CALIBRATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101628 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH X1.1 SOFTWARE STANDARD, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101634 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
10-JUL-2017		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-73-101634 R02	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
10-MAR-2021		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-73-101806 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X1.2 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101833 R02	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL PUMP - INTRODUCTION OF A REVISED DRIVE SHAFT CONNECTION FOR THE FUEL PUMP, SERVICE BULLETIN					CANCELLED	COMPLIED WITH - AT MANUFACTURE
		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101856	NO. 1 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - DEDICATED GENERATOR - INTRODUCTION OF A NEW VARNISH FOR THE WINDINGS OF THE PERMANENT MAGNETIC ALTERNATOR (PMA), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAR-2014		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101856 R02	NO. 1 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - DEDICATED GENERATOR - INTRODUCTION OF A NEW VARNISH FOR THE WINDINGS OF THE PERMANENT MAGNETIC ALTERNATOR (PMA), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
24-OCT-2016		MOS					
		HRS/MSC	-				
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101966 R02	NO. 1 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X2.0 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - BR700-73-101966 REV 2 COMPLIED WITH
21-DEC-2016		MOS		28-SEP-2017			
		HRS/MSC	-	485:04			
		ENC		176			
SB BR700-73-900423 R03	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
22-DEC-2016		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-73-900423 R04	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN (THIS NON-MODIFICATION SB-BR700-73-9000423 IS NO LONGER VALID AND CAN BE CLOSED), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
25-FEB-2021		MOS					
		HRS/MSC	-				
		ENC					
SB R03 BR700-73-A900083	NO. 1 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN (THIS SB IS NO LONGER VALID AND CAN BE CLOSED), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
28-JAN-2021		MOS					
		HRS/MSC	-				
		ENC					
CHAPTER 74 IGNITION							
SB BR700-74-100199	NO. 1 ENGINE - IGNITION - IGNITION UNIT - HIGH ENERGY - REVISED IGNITER BOX ATTACHING PARTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-FEB-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-74-100248	NO. 1 ENGINE - IGNITION - IGNITION LEADS - INTRODUCTION OF REVISED CLIPPING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-74-100316	NO. 1 ENGINE - IGNITION - IGNITER LEAD - INTRODUCTION OF SILVER PLATING ON CONNECTING NUT THREADS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
28-APR-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-74-100355	NO. 1 ENGINE - IGNITION - IGNITER PLUG - INTRODUCTION OF A SECOND SOURCE IGNITER PLUG, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-APR-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-74-100550	NO. 1 ENGINE - IGNITION - RIGHT ENGINE IGNITION LEAD ATTACHING FITTINGS - INTRODUCTION OF DRESSING CHANGES TO SUIT MODIFIED THERMAL ANTI-ICING VALVE AND MUSCLE LINE (RIGHT HAND ENGINES), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-SEP-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-74-100551	NO. 1 ENGINE - IGNITION - LEFT ENGINE IGNITION LEAD ATTACHING FITTINGS - INTRODUCTION OF TWO ADDITIONAL CLIPPING POINTS AND TRANSFER OF A BRACKET TO A LEFT ENGINE SECTION, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - AT MANUFACTURE	
15-SEP-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-74-101073 R01	NO. 1 ENGINE - IGNITION - IGNITER PLUG - INTRODUCTION OF A STANDARD LENGTH IGNITER PLUG ADAPTOR AND RELATED ADJUSTING WASHERS, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
10-OCT-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-74-101280	NO. 1 ENGINE - IGNITION - HIGH ENERGY IGNITION UNITS - INTRODUCTION OF A NEW IGNITION UNIT WITH CHANGES TO THE PRINTED CIRCUIT BOARD, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - AT MANUFACTURE	
04-OCT-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-74-101378	NO. 1 ENGINE - IGNITION - LEFT ENGINE IGNITION LEAD ATTACHING FITTINGS - INCREASED CLEARANCE BETWEEN CLIPPING POINT CP10373 AND AN ADJACENT OIL PIPE, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - AT MANUFACTURE	
25-FEB-2003		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
CHAPTER 75 AIR							
SB BR700-75-100212 R01	NO. 1 ENGINE - AIR - BLEED VALVES - INTRODUCTION OF HIGH PRESSURE COMPRESSOR (HPC) BLEED VALVES WITH STEEL BUSHES, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - AT MANUFACTURE	
11-APR-2003		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-75-100228 R01	NO. 1 ENGINE - AIR - VSV ACTUATOR - INTRODUCTION OF ONE HANDED 'ROSAN' LOCKING FEATURE, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-75-100270	NO. 1 ENGINE - AIR - AIR TUBES AND FITTINGS - MINOR CONFIGURATION AMENDMENTS, SERVICE BULLETIN				INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE	
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-75-100297 R01	NO. 1 ENGINE - AIR - VALVE CONTROL AIR BLEED - INTRODUCTION OF REVISED TORQUE TIGHTENING VALUES FOR BLEED VALVE BOLTS, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - AT MANUFACTURE	
12-JUL-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-75-100332 R01	NO. 1 ENGINE - AIR - SOLENOID CONTROL - AIR BLEED - INTRODUCTION OF REVISED BLEED VALVE SOLENOID CONTROL BLOCK MOUNTING BRACKETS AND ASSOCIATED AIR TUBES, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - AT MANUFACTURE	
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-75-100366 R01	NO. 1 ENGINE - AIR - SOLENOID CONTROL - AIR BLEED - INTRODUCTION OF A REVISED BLEED VALVE SOLENOID CONTROL BLOCK, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-75-100385 R01	NO. 1 ENGINE - AIR-BLEED VALVES AND SOLENOID CONTROL BLOCK - INTRODUCTION OF AN IMPROVED DESIGN OF BLEED VALVE AND SOLENOID CONTROL BLOCK, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
22-OCT-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-75-100392	NO. 1 ENGINE - AIR - VSV ACTUATOR - INTRODUCTION OF A VARIABLE STATOR VANE ACTUATOR MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
14-SEP-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-75-100465 R01	NO. 1 ENGINE - AIR - BUFFER AIR VALVE - INTRODUCTION OF A NEW BUFFER AIR VALVE FROM A DIFFERENT SUPPLIER AND WITH IMPROVED CORROSION PROTECTION, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - AT MANUFACTURE	
19-JUL-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-75-101096	NO. 1 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF TRANSFER TUBES BETWEEN THE BLEED VALVE SOLENOID BLOCK VENT VALVE BODY AND THE SOLENOID CAPS, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - AT MANUFACTURE	
12-JUL-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-75-101097	NO. 1 ENGINE - AIR - CORE AIR TUBES AND FITTINGS - INTRODUCTION OF A NEW AIR TUBE WITH A DIFFERENT ROUTING FROM THE BUFFER AIR VALVE TO THE ACCESSORY GEARBOX AND AN ADDITIONAL CLIP POINT CP40402, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
03-FEB-2004		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-75-101130 R01	NO. 1 ENGINE - AIR - BLEED VALVES - INTRODUCTION OF NEW HP 8 HANDLING BLEED VALVE INNER AND OUTER ATTENUATORS TO PREVENT DAMAGE TO BYPASS DUCT, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - AT MANUFACTURE	
22-JUN-2001		MOS		23-SEP-2015			
		HRS/MSC	A/R	0			
		ENC		0			
SB BR700-75-101161 R01	NO. 1 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK-INTRODUCTION OF HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - AT MANUFACTURE	
07-FEB-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-75-101161 R02	NO. 1 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF A HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN				RECOMMENDED	NOT APPLICABLE	
07-OCT-2017		MOS					
		HRS/MSC	-				
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-75-101161 R03	NO. 1 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF A HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
07-SEP-2018	MOS HRS/MSC - ENC						
SB BR700-75-101207	NO. 1 ENGINE - AIR - AIR TUBES AND FITTINGS - INTRODUCTION OF A P30 AIR TUBE WITH A NEW ROUTING TO INCREASE THE CLEARANCE BETWEEN THE TUBE AND THE FUEL MANIFOLD, SERVICE BULLETIN				23-SEP-2015	RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
20-JUN-2002	MOS HRS/MSC - ENC				0 0		
SB BR700-75-101228	NO. 1 ENGINE - AIR - CORE AIR TUBES AND FITTINGS - INTRODUCTION OF NEW HP2/HP4 AIR SYSTEM TUBE ASSEMBLIES WHICH ARE DECREASED IN WEIGHT, SERVICE BULLETIN				23-SEP-2015	OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-APR-2002	MOS HRS/MSC - ENC				0 0		
SB BR700-75-101381 R01	NO. 1 ENGINE - AIR - BLEED VALVES - INTRODUCTION OF NEW TRIPLE SEALS AND A CARBON BUSH TO REPLACE THE EXISTING STEEL COMPONENTS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
09-OCT-2018	MOS HRS/MSC - ENC						
SB BR700-75-101447 R02	NO. 1 ENGINE - AIR - VSV ACTUATOR - INTRODUCTION OF A MODIFIED VARIABLE STATOR VANE (VSV) ACTUATOR, SERVICE BULLETIN				23-SEP-2015	OPTIONAL	COMPLIED WITH - AT MANUFACTURE
	MOS HRS/MSC - ENC				0 0		
SB BR700-75-101694	NO. 1 ENGINE - AIR - AIR BLEED CONTROL SOLENOID - INTRODUCTION OF WASHERS WITH A SMALLER OUTER DIAMETER FOR THE INSTALLATION OF THE HANDLING BLEED VALVE SOLENOID CONTROL BLOCK, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-APR-2010	MOS HRS/MSC - ENC				23-SEP-2015		
0 0							
SB BR700-75-900633	NO. 1 ENGINE - CAMPAIGN SB - AIR - VSV ACTUATOR - REPLACEMENT OF LUCAS VARIABLE STATOR VANE (VSV) ACTUATORS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
19-JUN-2018	MOS HRS/MSC - ENC						
SB BR700-75-900633 R01	NO. 1 ENGINE - CAMPAIGN SB - AIR - VSV ACTUATOR - REPLACEMENT OF LUCAS VARIABLE STATOR VANE (VSV) ACTUATORS - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
11-DEC-2018	MOS HRS/MSC - ENC						
SB BR700-75-900693	NO. 1 ENGINE - CAMPAIGN SB - AIR - VSV ACTUATOR - REPLACEMENT OF VARIABLE STATOR VANE (VSV) ACTUATORS - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
25-MAR-2021	MOS HRS/MSC - ENC						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-77-100556	NO. 1 ENGINE - ENGINE INDICATING - TURBINE OVERHEAT/OIL FIRE DETECTION THERMOCOUPLE - INTRODUCTION OF STRENGTHENED TERMINALS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-NOV-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-77-101105	NO. 1 ENGINE - ENGINE INDICATING - TGT HARNESS - INTRODUCTION OF TORQUE TIGHTENING VALUES FOR THE NUTS WHICH ATTACH THE TURBINE GAS TEMPERATURE (TGT) HARNESS TO THE TGT PROBES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
10-APR-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-77-101534	NO. 1 ENGINE - ENGINE INDICATING - TURBINE GAS TEMPERATURE (TGT) THERMOCOUPLE - INTRODUCTION OF NEW TGT PROBES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-SEP-2006		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-77-101536	NO. 1 ENGINE - ENGINE INDICATING - TURBINE GAS TEMPERATURE (TGT) HARNESS - INTRODUCTION OF A NEW TGT HARNESS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-JUL-2006		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-77-101544	NO. 1 ENGINE - ENGINE INDICATING - VIBRATION TRANSDUCER AND CABLE - INTRODUCTION OF A NEW ENGINE VIBRATION MONITORING SYSTEM (EVMS) ACCELEROMETER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
02-NOV-2007		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-77-101553	NO. 1 ENGINE - ENGINE INDICATING - VIBRATION TRANSDUCER AND CABLE - INTRODUCTION OF A NEW ENGINE VIBRATION MONITORING SYSTEM (EVMS) CABLE ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-MAR-2009		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-77-101875	NO. 1 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INTRODUCTION OF NEW ATTACHING BOLTS WITH SHORTER LENGTH, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
03-JUL-2014		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-77-101875 R02	NO. 1 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INTRODUCTION OF NEW ATTACHING BOLTS WITH SHORTER LENGTH, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
29-JAN-2019		MOS					
		HRS/MSC	-				
		ENC					
CHAPTER 78 EXHAUST							
SB BR700-78-100165 R01	NO. 1 ENGINE - THRUST REVERSER - LH AND RH ENGINES - INTRODUCTION OF BEARINGS WITH A TEFLON LINER FOR THE LINEAR VARIABLE TRANSDUCER (LVT) ROD ENDS, THE PRIMARY DOOR LOCK AND THE INHIBITION BOLT RECEPTACLE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-78-100196 R02	NO. 1 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - LH AND RH ENGINES - INTRODUCTION ON THE LH AND RH ENGINE OF SPHERICAL BEARINGS WITH A HIGH TEMPERATURE TEFLO LINER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-100224 R01	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF A CHANGE OF OWNERSHIP (INSTALLATION RESPONSIBILITY) FOR THE WET DRAINS BRACKETS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-100225	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - REPLACEMENT OF THE FIRE PROTECTION ABLATIVE COATING ON THE THRUST REVERSER FRONT FRAME TORQUE BOX WITH FIRE BLANKETS (HUREL DUBOIS SB 04MOD0077), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-100236 R01	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF REVISED PIVOT DOOR ACTUATORS AND DYNAMIC SEALS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-100252 R01	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF 'NEXTEL' FROM PIVOT DOORS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-100358	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF THE THRUST REVERSER STOW SWITCH ACCESS PANELS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-100359	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF UPPER DOOR HOISTING POINTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-MAR-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-100360	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF THE NEXTEL LAYER ON THE FAN DUCT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-100361	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF THE NEXTEL LAYER ON FRAME 1, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-100389 R01	NO. 1 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) - CHANGE OF THE LINEAR VARIABLE TRANSFORMER (LVT) TO ENSURE IMPROVED PERFORMANCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-78-100390	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF SIMPLIFIED TORQUE BOX AND LATERAL BEAM JOINT FOR WEIGHT REDUCTION PURPOSES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-100417	NO. 1 ENGINE - EXHAUST - LEFT ENGINE THRUST REVERSER - INTRODUCTION OF LONGER HYDRAULIC HOSES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-DEC-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-100502	NO. 1 ENGINE - EXHAUST - ISOLATION CONTROL UNIT (ICU) - INTRODUCTION OF A NEW ICU WHICH HAVE A RETARDED THRUST REVERSER UNIT (TRU) PRESSURISATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-SEP-2008		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-100593 R01	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - CHANGE OF THRUST REVERSER PIVOT DOOR HONEYCOMB MATERIAL AND INTRODUCTION OF WEIGHT REDUCTION FEATURES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-100599	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF A WEIGHT REDUCED GEARBOX AIR BREATHER PIPE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-100641	NO. 1 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A NEW MATERIAL FOR THE JUNCTION SPLICE BETWEEN THE NOZZLE AND BEAM, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
17-MAY-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-100642 R01	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - IMPROVED ELECTRICAL BONDING OF THE THRUST REVERSER MAIN DOOR, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-100783 R05	NO. 1 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - MATERIAL CHANGE OF THE PIVOTING DOOR SEAL DEPRESSOR AND CARRIER SEGMENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-NOV-2009		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-100898	NO. 1 ENGINE - EXHAUST - EXHAUST CONE - INTRODUCTION OF A ONE PIECE EXHAUST CONE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
13-JUL-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-78-100935 R01	NO. 1 ENGINE - EXHAUST - TERTIARY LOCK - INTRODUCTION OF TERTIARY LOCKS WITH A BETTER MANUAL RELEASE MECHANISM AND INCREASED SOLENOID FORCE, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
04-JUL-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-100987 R01	NO. 1 ENGINE - EXHAUST - LEFT AND RIGHT THRUST REVERSER HYDRAULIC TUBES - CHANGES TO THE MAIN-DOOR-ACTUATOR HOSES (THE ACTUATOR HOSES) OF THE THRUST REVERSER UNIT (TRU), SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
20-SEP-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-101009	NO. 1 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - INTRODUCTION OF NEW SHIMS FOR THE SEAL LANDS ON THE INTERFACE OF THE THRUST REVERSER AND THE UPPER AND LOWER COWL DOOR, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
16-OCT-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-101061 R04	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF THRUST REVERSER FLOW DISCOURAGER SEALS BETWEEN THE PIVOT DOORS AND THE FIXED STRUCTURE, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
03-MAY-2001		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-101129 R01	NO. 1 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER FIXED STRUCTURE - REORIENTATION OF THE FASTENERS AT THE THRUST REVERSER FRONT FRAME TO INCREASE THE CLEARANCE TO THE S-HOOK, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
16-OCT-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-101387	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF STOW SWITCHES MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
20-MAR-2003		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-101442	NO. 1 ENGINE - EXHAUST - EXHAUST NOZZLE - INTRODUCTION OF A NEW EXHAUST NOZZLE ASSEMBLY WITHOUT SPACERS BETWEEN THE FRONT SUPPORT BRACKETS AND THE NOZZLE SKIN, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
29-OCT-2004		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-101501	NO. 1 ENGINE - EXHAUST - ISOLATION CONTROL UNIT (ICU) - INTRODUCTION OF AN ISOLATION CONTROL UNIT WITH IMPROVED BONDING RESISTANCE, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
28-JUL-2005		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-101512	NO. 1 ENGINE - EXHAUST - THRUST REVERSER PIVOTING DOORS - INSTRUCTION OF VARIOUS IMPROVEMENTS TO THE THRUST REVERSER PIVOTING DOORS, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
27-APR-2006		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-78-101514	NO. 1 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A NEW UPPER INHIBITION BOLT FITTING MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
27-APR-2006		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-101515	NO. 1 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A NEW 'Y' STOP FITTING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-JAN-2007		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-101607 R01	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF A NEW THRUST REVERSER UNIT (TRU), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-OCT-2013		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-101635	NO. 1 ENGINE - EXHAUST - THRUST REVERSER DOOR STOW SWITCH - INTRODUCTION OF A DOOR STOW SWITCH WITH IMPROVED SEALING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
01-AUG-2008		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-101772	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF VARIOUS MINOR CHANGES TO THE MANUFACTURING AND ASSEMBLY PROCESS FOR THE THRUST REVERSER UNIT (TRU), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-JUL-2014		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-78-102008 R01	NO. 1 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE THRUST REVERSER FIXED STRUCTURE TO PREVENT CORROSION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
19-JAN-2018		MOS		27-JUN-2018			
		HRS/MSC	-	631:35			
		ENC		240			
SB BR700-78-900350 R02	NO. 1 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) - INSPECTION OF THE SPHERICAL BEARING OF THE PRIMARY DOOR LOCK ACTUATOR (PDLA) AND CLEANING OF THE S-HOOK ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
18-DEC-2018		MOS		09-MAR-2020			
		HRS/MSC	-				
		ENC					
SB BR700-78-900474	NO. 1 ENGINE - EXHAUST - THRUST REVERSER - INSPECTION OF FIXED STRUCTURE TORQUE BOX DRAINAGE HOLES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
		HRS/MSC	-				
		ENC		0			
CHAPTER 79 OIL							
SB BR700-79-100118 R01	NO. 1 ENGINE - OIL - COOLER - ENGINE LUBRICATING OIL (AIR COOLED) DELETION OF AIR COOLED OIL COOLER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
29-SEP-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-79-100221	NO. 1 ENGINE - OIL - OIL TANK AND EXTERNAL OIL TUBES - INTRODUCTION OF A SCUPPER DRAIN TUBE AND A MODIFIED OIL FILLER ASSEMBLY AND THE DELETION OF BLANKING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
19-JUN-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-100294	NO. 1 ENGINE - OIL - FUEL COOLED OIL COOLER - REMOVAL OF LIFE LIMITATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
25-FEB-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-100323 R01	NO. 1 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF A REVISED ANTI-SYPHON OIL TUBE ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
14-MAR-2014		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-100403	NO. 1 ENGINE - OIL - OIL DIFFERENTIAL PRESSURE TRANSDUCER- INTRODUCTION OF A NEW OIL DIFFERENTIAL PRESSURE TRANSDUCER UNIT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-100406 R01	NO. 1 ENGINE - OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH - INTRODUCTION OF A UNIT INCORPORATING A HERMETICALLY SEALED MICRO-SWITCH, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
09-DEC-1998		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-100413	NO. 1 ENGINE - OIL - FUEL COOLED OIL COOLER - INTRODUCTION OF A NEW UNIT FEATURING A CAST VERSION OF THE OIL FILTER HOUSING COVER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-100478	NO. 1 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF REVISED CLIPPING POINTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-100798 R01	NO. 1 ENGINE - OIL - FUEL COOLED OIL COOLER - INTRODUCTION OF NEW ELECTRICAL BONDING LEAD FITTING INSTRUCTIONS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
22-SEP-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101083	NO. 1 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF A NEW OIL VENT TUBE WITH BETTER SEALING PROPERTIES BETWEEN THE OIL VENT PIPE AND THE ACCESSORY GEARBOX, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
01-DEC-2000		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-79-101188 R01	NO. 1 ENGINE - OIL - OIL DIFFERENTIAL PRESURE SWITCH - INTRODUCTION OF A NEW OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH A THICKER COVER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUL-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101287	NO. 1 ENGINE - OIL - OIL PUMPS - INTRODUCTION OF A NEW OIL PUMP WITH A SMALLER SPILL RETURN ORIFICE WHICH INCREASES THE PUMP DISCHARGE OIL FLOW, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-FEB-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101292	NO. 1 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF A NEW OIL TUBE BETWEEN THE GEARBOX OIL PUMP AND THE FUEL COOLED OIL COOLER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-NOV-2002		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101445	NO. 1 ENGINE - OIL - OIL PUMP - INTRODUCTION OF A NEW STATIC ANTI LEAK VALVE (SALV) INTO THE OIL PUMP UNIT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
16-APR-2004		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101449	NO. 1 ENGINE - OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH - INTRODUCTION OF A NEW OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH A CHANGE TO THE SWITCH SET POINT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-MAY-2004		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101458	NO. 1 ENGINE - OIL - PRESSURE FILTER ELEMENT - INTRODUCTION OF A NEW OIL FILTER ELEMENT WITH INCREASED DIRT HOLDING CAPACITY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
17-MAY-2004		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101470	NO. 1 ENGINE - OIL - FUEL COOLED OIL COOLER (FCOC) - INTRODUCTION OF A NEW FRONT SUPPORT BRACKET, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-NOV-2005		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101482	NO. 1 ENGINE - OIL - FUEL COOLED OIL COOLER (FCOC) - INTRODUCTION OF A NEW FUEL COOLED OIL COOLER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-MAR-2005		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101739	NO. 1 ENGINE - OIL - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW SEALING PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-FEB-2011		MOS		23-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-79-101744 R01	NO. 1 ENGINE - OIL - FUEL COOLED OIL COOLER (FCOC) - INTRODUCTION OF A NEW FCOC WITH IMPROVED ICING PROTECTION CAPABILITY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
	MOS HRS/MSC - ENC			23-SEP-2015 0 0			
SB BR700-79-101803 R01	NO. 1 ENGINE - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW OIL PUMP UNIT WITH IMPROVED GEARS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
29-AUG-2014	MOS HRS/MSC - ENC			23-SEP-2015 0 0			
SB BR700-79-900215 R01	NO. 1 ENGINE - OIL - EXCHANGE OF OIL FILTER DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
	MOS HRS/MSC - ENC			23-SEP-2015 0 0			
SB BR700-79-900215 R02	NO. 1 ENGINE - OIL - EXCHANGE OF OIL FILTER DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
	MOS HRS/MSC - ENC			23-SEP-2015 0 0			
CHAPTER 80 STARTING							
SB BR700-80-100077	NO. 1 ENGINE - STARTING - AIR TURBINE STARTER - REPLACEMENT OF OUTPUT SHAFT ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
19-FEB-1998	MOS HRS/MSC - ENC			23-SEP-2015 0 0			
SB BR700-80-100470	NO. 1 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A DUAL-PLANE BALANCED TURBINE WHEEL AND A REVISED METHOD OF MAGNETIC CHIP DETECTOR ATTACHMENT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
29-SEP-1998	MOS HRS/MSC - ENC			23-SEP-2015 0 0			
SB BR700-80-100640	NO. 1 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW STANDARD OF AIR TURBINE STARTER UNIT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
11-MAR-1999	MOS HRS/MSC - ENC			23-SEP-2015 0 0			
SB BR700-80-101018 R03	NO. 1 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
05-SEP-2005	MOS HRS/MSC - ENC			23-SEP-2015 0 0			
SB BR700-80-101729	NO. 1 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH MODIFIED TURBINE THRUST BEARING, SEAL AND RETAINING RING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
	MOS HRS/MSC - ENC			23-SEP-2015 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-80-101741	NO. 1 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH MODIFIED OIL FILL PORTS TO IMPROVE THE MAINTENANCE OIL FILL PROCEDURE, SERVICE BULLETIN				23-SEP-2015	OPTIONAL	COMPLIED WITH - AT MANUFACTURE
	MOS				0		
	HRS/MSC	-			0		
	ENC				0		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 2 - AD - 22466/DER114							
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS							
EASA 2022-0033	NO. 2 ENGINE - ATA 05 - TIME LIMITS / MAINTENANCE CHECKS - TIME LIMITS MANUAL / MAINTENANCE PROGRAMME - AMENDMENT						COMPLIED WITH - THIS AD IS COMPLIED WITH PER PARAGRAPH (4) SINCE THE REQUIRED ACTION(S) AS MENTIONED IN PARAGRAPH (1) HAS BEEN ACCOMPLISHED PRIOR THE EFFECTIVE DATE FOR BOTH AIRCRAFT 8-99998 AND 8-96999.
17-MAR-2022		MOS HRS/MSC - ENC		09-MAR-2022			
CHAPTER 72 ENGINE							
EASA 2010-0075	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2 ASSEMBLY LIFE LIMITS - MODIFICATION					MANDATORY	COMPLIED WITH - AT MANUFACTURE
04-MAY-2010		MOS HRS/MSC - ENC		14-OCT-2014 0 0			
EASA 2010-0077	NO. 2 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT					MANDATORY	COMPLIED WITH
04-MAY-2010		MOS HRS/MSC - ENC		22-DEC-2014 5			
EASA 2012-0161	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING					MANDATORY	NOT APPLICABLE - REVISED BY 2012-0161R1
19-SEP-2014		MOS HRS/MSC - ENC		14-OCT-2014 0 0			
EASA 2012-0161 R01	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING					MANDATORY	COMPLIED WITH - AT MANUFACTURE
19-SEP-2014		MOS HRS/MSC - ENC		14-OCT-2014 0 0			
EASA 2012-0161 R01 PARA (1)	NO. 2 ENGINE - REPLACE EACH ENGINE FUEL PUMP SPLINED COUPLING WITH A SERVICEABLE PART					MANDATORY	
19-SEP-2014		MOS HRS/MSC - ENC		14-OCT-2014 0 0			
EASA 2012-0166	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR DISC STAGE 1 AND STAGE 2 LIFE LIMITATION - IMPLEMENTATION					MANDATORY	COMPLIED WITH - AT MANUFACTURE
13-SEP-2012		MOS HRS/MSC - ENC		14-OCT-2014 0 0			
EASA 2013-0296	NO. 2 ENGINE - ENGINE - HIGH PRESSURE COMPRESSOR AND COMBUSTION FAIRINGS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE
25-DEC-2013		MOS HRS/MSC - ENC		14-OCT-2014 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2013-0296 PARA (1)	NO. 2 ENGINE - INSPECT THE UPPER LEFT HPC FAIRING					MANDATORY	NOT APPLICABLE
25-DEC-2013		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
EASA 2013-0296 PARA (2)	NO. 2 ENGINE - REPLACE THE UPPER LEFT HPC FAIRING					MANDATORY	NOT APPLICABLE
25-DEC-2013		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
EASA 2013-0296 PARA (3)	NO. 2 ENGINE - REPLACE AN UPPER LEFT, UPPER RIGHT AND LOWER RIGHT COMBUSTION SECTION FAIRING					MANDATORY	NOT APPLICABLE
25-DEC-2013		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
EASA 2013-0296-CN	NO. 2 ENGINE - CANCELLED: ENGINE - HIGH PRESSURE COMPRESSOR AND COMBUSTION FAIRINGS - INSPECTION / REPLACEMENT					CANCELLED	NOT APPLICABLE - CANCELLATION OF 2013-0296
26-JUN-2014		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
EASA 2018-0268	NO. 2 ENGINE - ENGINE - LIFE-LIMITED CRITICAL PARTS - SERVICE LIFE CALCULATION / REPLACEMENT					MANDATORY	COMPLIED WITH
01-JAN-2019		MOS		18-DEC-2018			
		HRS/MSC	-				
		ENC					
EASA 2018-0268 PARA (1)	NO. 2 ENGINE - DETERMINE THE OPERATIONAL HISTORY OF THE LPC DISC AND, BASED ON THAT DETERMINATION, RE-CALCULATE THE CONSUMED (AND REMAINING) SERVICE LIFE OF THE LPC DISC (FOR EACH AFFECTED ENGINE)						COMPLIED WITH
01-JAN-2019		MOS		18-DEC-2018			
		HRS/MSC	-				
		ENC					
EASA 2018-0268 PARA (2)	NO. 2 ENGINE - ACCOMPLISH A ONE-TIME RE-CALCULATION OF THE SERVICE LIFE ACCUMULATED BY THE LPC DISC ON THAT AFFECTED ENGINE (FOR EACH AFFECTED ENGINE)					MANDATORY	COMPLIED WITH
01-JAN-2019		MOS		18-DEC-2018			
		HRS/MSC	-				
		ENC					
EASA 2018-0268 PARA (3)	NO. 2 ENGINE - RE-CALCULATE THE CONSUMED (AND REMAINING) SERVICE LIFE OF EACH AFFECTED LLP (FOLLOWING THE RE-CALCULATION OF THE SERVICE LIFE ACCUMULATED BY THE LPC DISC ON AN AFFECTED ENGINE, AS REQUIRED BY PARAGRAPH (2) OF THIS AD)						COMPLIED WITH
01-JAN-2019		MOS		18-DEC-2018			
		HRS/MSC	-				
		ENC					
EASA 2018-0268 PARA (4)	NO. 2 ENGINE - REPLACE THAT AFFECTED LLP WITH A SERVICEABLE PART					MANDATORY	COMPLIED WITH
01-JAN-2019		DAYs		18-DEC-2018			
		HRS/MSC	-				
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2018-0268 PARA (6)	NO. 2 ENGINE - TERMINATING ACTION: RE-CALCULATION OF THE CONSUMED (AND REMAINING) SERVICE LIFE OF EACH AFFECTED LLP ON AN AFFECTED ENGINE IN ACCORDANCE WITH THE INSTRUCTIONS OF PART B "REQUIREMENT 2" OF THE NMSB, AS REQUIRED BY PARAGRAPH (3) OF THIS AD, CONSTITUTES TERMINATING ACTION FOR THE REPETITIVE RE-CALCULATIONS OF THE LPC DISC LIFE AS REQUIRED BY PARAGRAPH (1) OF THIS AD FOR THAT AFFECTED ENGINE					MANDATORY	COMPLIED WITH
01-JAN-2019		MOS HRS/MSC - ENC		18-DEC-2018			
EASA 2018-0268 PARA (7)	NO. 2 ENGINE - TERMINATING ACTION: INSTALLATION OF AN AFFECTED ENGINE ON A POST-MOD AEROPLANE, AS DEFINED IN THIS AD, CONSTITUTES TERMINATING ACTION FOR THE REPETITIVE RE-CALCULATION REQUIREMENTS OF PARAGRAPH (3) OF THIS AD FOR THAT ENGINE, EXCEPT AS SPECIFIED IN PARAGRAPH (8) OF THIS AD					MANDATORY	COMPLIED WITH
01-JAN-2019		MOS HRS/MSC - ENC		18-DEC-2018			
EASA 2019-0299	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE STAGE 1 DISCS - LIFE LIMIT REDUCTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - THE EATC BR700-710A2-20 ENGINES ARE NOT AFFECTED BY THIS AD
24-DEC-2019		MOS HRS/MSC - (s) ENC		13-DEC-2019			
EASA 2019-0299 PARA (1)	NO. 2 ENGINE - DETERMINE WHETHER AN AFFECTED PART, AS DEFINED IN THIS AD, IS INSTALLED ON THE ENGINE					MANDATORY	NOT APPLICABLE - THE EATC BR700-710A2-20 ENGINES ARE NOT AFFECTED BY THIS AD
24-DEC-2019		DAYs HRS/MSC - ENC		13-DEC-2019			
EASA 2019-0299 PARA (2)	NO. 2 ENGINE - REMOVE THE ENGINE FROM SERVICE AND, BEFORE RELEASE TO SERVICE OF THAT ENGINE, REPLACE THE AFFECTED PART WITH A SERVICEABLE PART (FOR EACH ENGINE FOR WHICH IT HAS BEEN DETERMINED, AS REQUIRED BY PARAGRAPH (1) OF THIS AD, THAT AN AFFECTED PART IS INSTALLED)					MANDATORY	NOT APPLICABLE - THE EATC BR700-710A2-20 ENGINES ARE NOT AFFECTED BY THIS AD
24-DEC-2019		MOS HRS/MSC - (s) ENC		13-DEC-2019			
FAA 1998-24-03 R01	NO. 2 ENGINE - VISUAL INSPECTION OF ENGINE CORE FAIRING FASTENERS.						COMPLIED WITH - AT MANUFACTURE
27-DEC-1999		MOS HRS/MSC - ENC		14-OCT-2014 0 0			
FAA 2001-05-06 ULTRASONIC INSP	NO. 2 ENGINE - ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS					SUPERSEDED	NOT APPLICABLE - SUPERSEDED BY 2003-07-11
39-12142 14-MAR-2001		MOS HRS/MSC N/A ENC		14-OCT-2014 0			
FAA 2001-05-06 VISUAL INSP	NO. 2 ENGINE - VISUAL INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS					SUPERSEDED	NOT APPLICABLE - SUPERSEDED BY 2003-07-11
39-12142 14-MAR-2001		MOS HRS/MSC N/A ENC		14-OCT-2014 0 0			
FAA 2003-07-11 PART B	NO. 2 ENGINE - VISUAL OR ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS					SUPERSEDED	NOT APPLICABLE - SUPERSEDED BY 2005-21-05
39-13107		MOS HRS/MSC - ENC		14-OCT-2014 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2003-07-11 PART F	NO. 2 ENGINE - VISUAL AND ULTRASONIC INSPECTION OF THE LP COMPRESSOR FAN DISC FOR CRACKS					SUPERSEDED	NOT APPLICABLE - SUPERSEDED BY 2005-21-05
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
FAA 2005-21-05 PART 1	NO. 2 ENGINE - VISUAL OR ULTRASONIC INSPECTION OF THE FAN DISC					MANDATORY	NOT APPLICABLE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
FAA 2005-21-05 PART 2	NO. 2 ENGINE - ULTRASONIC AND VISUAL INSPECTION OF THE FAN DISC					MANDATORY	NOT APPLICABLE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
FAA 2005-21-05 PART L	NO. 2 ENGINE - VISUAL AND ULTRASONIC INSPECTION AS MANDATED IN RRD TIME LIMITS MANUAL T-710-2BR, CHAPTER 05-10-01 (BR700-710A2-20).						NOT APPLICABLE
		MOS		14-OCT-2014			
		HRS/MSC	N/A	0			
		ENC		0			
FAA 2010-25-05	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2 ASSEMBLY LIFE LIMITS - MODIFICATION					MANDATORY	NOT APPLICABLE
39-16538 13-JAN-2011		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
FAA 2011-22-01	NO. 2 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT					MANDATORY	NOT APPLICABLE - AIRCRAFT NOT USED FOR PILOT TRAINING
39-16842 23-NOV-2011		MOS		22-DEC-2014			
		HRS/MSC	-				
		ENC		5			
FAA 2011-22-01 PARA (E)(1) & (E)(2)	NO. 2 ENGINE - REVISE ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT THE AIRWORTHINESS LIMITATIONS SECTION (ALS) OF THE OPERATORS' APPROVED MAINTENANCE PROGRAM (REFERENCE THE TIME LIMITS MANUAL (TLM), CHAPTERS 05-00-01 AND 05-00-02 OF THE APPLICABLE ENGINE MANUALS (EMS))					MANDATORY	NOT APPLICABLE - AIRCRAFT NOT USED FOR PILOT TRAINING
23-NOV-2011		MOS		22-DEC-2014			
		HRS/MSC	-				
		ENC		5			
FAA 2011-22-01 PARA (E)(3)	NO. 2 ENGINE - DETERMINE ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT THE NUMBER OF TOUCH-AND-GO'S AND OVERSHOTS THAT EACH INDIVIDUAL CRITICAL PART EXCEPT THE FAN SHAFT AND LP TURBINE ROTOR SHAFT HAS EXPERIENCED SINCE ENTRY INTO SERVICE FOR PILOT TRAINING					MANDATORY	NOT APPLICABLE - AIRCRAFT NOT USED FOR PILOT TRAINING
23-NOV-2011		MOS		22-DEC-2014			
		HRS/MSC	-				
		ENC		5			
FAA 2013-03-17	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR DISC STAGE 1 AND STAGE 2 LIFE LIMITATION - IMPLEMENTATION					MANDATORY	COMPLIED WITH - AT MANUFACTURE
39-17351 21-MAR-2013		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2013-05-13	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING (SUPERSEDED BY FAA AD 2022-26-02)					MANDATORY	COMPLIED WITH - AT MANUFACTURE
24-APR-2013		MOS HRS/MSC ENC	4000	14-OCT-2014 0 0	4000	RECURRING	
FAA 2016-13-12	NO. 2 ENGINE - ENGINE - PAWL CARRIER PIVOT PINS, PART NUMBER (P/N) BRR17117, - REMOVE FROM SERVICE / REPLACE					MANDATORY	NOT APPLICABLE - N/A BY ESN
05-AUG-2016		MOS HRS/MSC ENC	-	16-JAN-2025			
FAA 2021-12-07	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE (HPT) STAGE 1 DISK - REPLACE					MANDATORY	NOT APPLICABLE - N/A - HPT STAGE 1 DISC P/N BRR23952 WITH S/N RRSUNDR078 NOT AFFECTED
12-AUG-2021		DAYS HRS/MSC ENC	-	16-JAN-2025			
FAA 2021-21-12	NO. 2 ENGINE - TURBINE ENGINE COMPRESSOR SECTION - LIFE-LIMITED CRITICAL PARTS - SERVICE LIFE CALCULATION / REPLACEMENT					MANDATORY	COMPLIED WITH - ASB BR700-72-A900584 R01 ALREADY INCORPORATED ON 02-NOV-2017
13-DEC-2021		MOS HRS/MSC ENC	-	16-JAN-2025			
FAA 2021-21-12 PARA (G)(1)	NO. 2 ENGINE - RECALCULATE THE CONSUMED AND REMAINING SERVICE LIFE OF EACH AFFECTED LLP					MANDATORY	COMPLIED WITH - ASB BR700-72-A900584 R01 ALREADY INCORPORATED ON 02-NOV-2017
13-DEC-2021		DAYS HRS/MSC ENC	-	16-JAN-2025			
FAA 2021-21-12 PARA (G)(2)	NO. 2 ENGINE - CALCULATE THE CONSUMED AND REMAINING SERVICE LIFE OF EACH AFFECTED LLP (FOR ENGINES INSTALLED AND OPERATED ON A PRE-MOD AIRPLANE, AFTER PERFORMING THE INITIAL RECALCULATIONS REQUIRED BY PARA (G)(1))					MANDATORY	COMPLIED WITH - ASB BR700-72-A900584 R01 ALREADY INCORPORATED ON 02-NOV-2017
13-DEC-2021		MOS HRS/MSC ENC	BF/F (s)	16-JAN-2025			
FAA 2021-21-12 PARA (G)(3)	NO. 2 ENGINE - REMOVE EACH AFFECTED LLP					MANDATORY	COMPLIED WITH - ASB BR700-72-A900584 R01 ALREADY INCORPORATED ON 02-NOV-2017
13-DEC-2021		MOS HRS/MSC ENC	-	16-JAN-2025			
FAA 2022-24-06	NO. 2 ENGINE - ENGINE - LOW PRESSURE COMPRESSOR ROTOR (FAN) DISC - INSPECTION					MANDATORY	NOT APPLICABLE - BY ESN AND AFFECTED PN IS NOT INSTALLED ON THE ENGINE. (LPC ROTOR (FAN) DISC P/N FW33927 INSTALLED)
39-22246 06-JAN-2023		DAYS HRS/MSC ENC	-	16-JAN-2025			
LBA D-1998-467	NO. 2 ENGINE - ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 1998-467/2
04-NOV-1998		MOS HRS/MSC ENC	-	12-DEC-2014 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
LBA D-1998-467 R02	NO. 2 ENGINE - ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 1998-467/3
26-MAR-1999		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-1998-467 R03	NO. 2 ENGINE - ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 1998-467/4
15-SEP-1999		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-1998-467 R04	NO. 2 ENGINE - ENGINE - SEPARATION OF THE ENGINE CORE FAIRINGS DUE TO INCORRECT INSTALLATION					MANDATORY	COMPLIED WITH - CLOSE OUT ACTION OF 1998-467/3
19-SEP-2002		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-348	NO. 2 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/2
02-OCT-2000		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-348 R02	NO. 2 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/3
24-NOV-2000		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-348 R03	NO. 2 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/4
		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-348 R04	NO. 2 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/5
		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-348 R05	NO. 2 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-348/6
		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-348 R06	NO. 2 ENGINE - ENGINE - LP COMPRESSOR - FAN DISC CRACKS (ATA 72)					NOT APPLICABLE	
31-MAR-2005		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-348 REV 6 PART 4	NO. 2 ENGINE - VISUAL OR ULTRASONIC INSP FAN DISC, P/N BRR20791					NOT APPLICABLE	
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
LBA D-2000-348 REV 6 PART 5	NO. 2 ENGINE - VISUAL AND ULTRASONIC INSP OF FAN DISC, ALL P/NS						NOT APPLICABLE
LBA D-2004-494	NO. 2 ENGINE - REDUCTION OF LIFE LIMITATION FOR THE HIGH PRESSURE COMPRESSOR (HPC) FRONT DRUM DUE TO AN INADVERTENT HEAT TREATMENT.					MANDATORY	NOT APPLICABLE
10-JAN-2005		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2007-352	NO. 2 ENGINE - REVERSE WIRED INDEPENDENT OVERSPEED PROTECTION COILS IN BR700 SERIES ENGINES					MANDATORY	NOT APPLICABLE
21-DEC-2007		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2008-222	NO. 2 ENGINE - BR700-710 - RE-USE OF POTENTIALLY DAMAGED ENGINE MATERIAL					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 20008-222R1
23-JUN-2008		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2008-222 R01	NO. 2 ENGINE - BR700-710 - RE-USE OF POTENTIALLY DAMAGED ENGINE MATERIAL					CANCELLED	NOT APPLICABLE
25-SEP-2008		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2010-126	NO. 2 ENGINE - ENGINE – HIGH PRESSURE (HP) TURBINE DISCS STAGE 1 AND 2 ASSEMBLY LIFE LIMITS – MODIFICATION					MANDATORY	COMPLIED WITH - AT MANUFACTURE
03-MAY-2010		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2010-130	NO. 2 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE CYCLE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT					MANDATORY	COMPLIED WITH - AT MANUFACTURE
03-MAY-2010		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2012-340	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING					MANDATORY	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2012-346	NO. 2 ENGINE - ENGINE - HIGH PRESSURE TURBINE ROTOR DISC STAGE 1 AND STAGE 2 LIFE LIMITATION - IMPLEMENTATION					MANDATORY	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2013-366	NO. 2 ENGINE - ENGINE - HIGH PRESSURE COMPRESSOR AND COMBUSTION FAIRINGS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE
16-DEC-2013		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
LBA D-2013-366 R01	NO. 2 ENGINE - CANCELLED: ENGINE - HIGH PRESSURE COMPRESSOR AND COMBUSTION FAIRINGS - INSPECTION / REPLACEMENT					CANCELLED	NOT APPLICABLE
27-JUN-2014		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
CHAPTER 73 ENGINE FUEL AND CONTROL							
EASA 2017-0198	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER FIREBOX ASSEMBLY - REPLACEMENT (CANCELLED BY EASA AD 2017-0198-CN)					MANDATORY	COMPLIED WITH - WORK DONE
10-OCT-2017		MOS		12-NOV-2018			
		HRS/MSC	-	823:40			
		ENC		292			
LBA D-2013-156	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - SPILL RETURN TO FUEL PUMP TUBE - REPLACEMENT					MANDATORY	NOT APPLICABLE
30-MAY-2013		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2013-281 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL METERING UNIT - REPLACEMENT					MANDATORY	NOT APPLICABLE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
CHAPTER 76 ENGINE CONTROLS							
FAA 2018-18-14	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER FIREBOX ASSEMBLY - REPLACEMENT					MANDATORY	COMPLIED WITH - ACCORDING WITH THE RECORD OF ROLLS-ROYCE ASB BR700-73-101977 R03 WHICH COMPLIANCE WITH AT NOV-2018.
12-OCT-2018		MOS		03-FEB-2021			
		HRS/MSC	-				
		ENC					
CHAPTER 79 OIL							
FAA 2001-01-01	NO. 2 ENGINE - ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH - REPLACE						NOT APPLICABLE
31-JAN-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-257	NO. 2 ENGINE - ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-257/2
25-JUL-2000		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-257 PART 1	NO. 2 ENGINE - PERFORM ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431 INSPECTION TO DETERMINE THE SERIAL NUMBER					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-257/2
25-JUL-2000		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-257 PART 2 & 3	NO. 2 ENGINE - PERFORM ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431 REPLACE THE OIL FILTER DIFFERENTIAL PRESSURE SWITCH UNIT OR MARK THE OIL FILTER DIFFERENTIAL PRESSURE SWITCH UNIT WITH A STRIP OF A HIGH TEMPERATURE YELLOW PAINT.					MANDATORY	NOT APPLICABLE - SUPERSEDED BY 2000-257/2
25-JUL-2000		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
LBA D-2000-257 R02	NO. 2 ENGINE - ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431						NOT APPLICABLE
24-AUG-2000		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-257 R02 PART 1	NO. 2 ENGINE - PERFORM ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431 INSPECTION TO DETERMINE THE SERIAL NUMBER					MANDATORY	NOT APPLICABLE
24-AUG-2000		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
LBA D-2000-257 R02 PART 2	NO. 2 ENGINE - REPLACE ENGINE OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH PART-NUMBER (P/N) 21SN04-419 OR -431 THE OIL FILTER DIFFERENTIAL PRESSURE SWITCH UNIT					MANDATORY	NOT APPLICABLE
24-AUG-2000		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			
CHAPTER 83 ACCESSORY GEAR-BOXES							
FAA 2022-26-02	NO. 2 ENGINE - ACCESSORY GEARBOXES - TIME LIMITS / MAINTENANCE CHECKS - TIME LIMITS MANUAL / MAINTENANCE PROGRAMME - AMENDMENT					MANDATORY	COMPLIED WITH - THE LIFE LIMITS AND MAINTENANCE TASKS ALREADY INCORPORATED INTO G6000 AMP AND CONTROLLED BY CAMP.
39-22280		MOS		16-JAN-2025			
27-JAN-2023		HRS/MSC	-				
		ENC					
FAA 2022-26-02 PARA (G) EASA (1.1)	NO. 2 ENGINE - REPLACE EACH COMPONENT BEFORE EXCEEDING THE APPLICABLE LIFE LIMIT OR BEFORE EXCEEDING THE APPLICABLE THRESHOLD, OR WITHIN THE SPECIAL COMPLIANCE TIMES SPECIFIED IN TABLE 1 OF THIS AD					MANDATORY	COMPLIED WITH - THE LIFE LIMITS AND MAINTENANCE TASKS ALREADY INCORPORATED INTO G6000 AMP AND CONTROLLED BY CAMP.
27-JAN-2023		MOS		16-JAN-2025			
		HRS/MSC	-				
		ENC					
FAA 2022-26-02 PARA (G) EASA (3)	NO. 2 ENGINE - INCORPORATING THE ACTIONS AND ASSOCIATED THRESHOLDS AND INTERVALS, INCLUDING LIFE LIMITS AND MAINTENANCE TASKS, INTO THE EXISTING APPROVED MAINTENANCE OR INSPECTION PROGRAM, AS APPLICABLE					MANDATORY	COMPLIED WITH - THE LIFE LIMITS AND MAINTENANCE TASKS ALREADY INCORPORATED INTO G6000 AMP AND CONTROLLED BY CAMP.
27-JAN-2023		DAYs		16-JAN-2025			
		HRS/MSC	-				
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 2 - SB - 22466/DER114							
CHAPTER 24 ELECTRICAL POWER							
SB	BR700-24-100166 R01	NO. 2 ENGINE - ELECTRICAL POWER - VARIABLE FREQUENCY GENERATOR OIL TRANSFER TUBES AND FITTINGS - REVISED OIL TRANSFER TUBE SELF LOCKING NUT TIGHTENING TORQUE, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
			01-DEC-2000	MOS HRS/MSC ENC	14-OCT-2014 0 0		
SB	BR700-24-100378	NO. 2 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR OIL COOLER - DELETION OF FIRE PROTECTION COVER PLATES, SERVICE BULLETIN			OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
			26-APR-1999	MOS HRS/MSC ENC	14-OCT-2014 0 0		
SB	BR700-24-100384 R01	NO. 2 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR SURFACE AIR COOLED OIL COOLER (SACOC) TRANSFER TUBES AND FITTINGS - INTRODUCTION OF A MODIFIED SACOC TO VARIABLE FREQUENCY GENERATOR (VFG) OIL TUBE, SERVICE BULLETIN			OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
			08-JUL-2014	MOS HRS/MSC ENC	14-OCT-2014 0 0		
SB	BR700-24-100472	NO. 2 ENGINE - POWER - ENGINE GENERATOR OIL COOLER - DELETION OF THE THERMOSTATIC CONTROL VALVE OF THE SURFACE AIR COOLED OIL COOLER AND ASSOCIATED DRESSINGS CHANGES, SERVICE BULLETIN			OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
			24-JAN-2002	MOS HRS/MSC ENC	14-OCT-2014 0 0		
SB	BR700-24-100961 R01	NO. 2 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR OIL COOLER - INTRODUCTION OF A NEW BUILD INSTRUCTION FOR THE FIRE SHIELDS OF THE OIL COOLER, SERVICE BULLETIN			OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
			10-APR-2001	MOS HRS/MSC ENC	14-OCT-2014 0 0		
SB	BR700-24-101483	NO. 2 ENGINE - ELECTRICAL POWER - ENGINE GENERATOR OIL COOLER - INTRODUCTION OF NEW SURFACE AIR COOLED OIL COOLERS (SACOC), SERVICE BULLETIN			OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
			11-FEB-2005	MOS HRS/MSC ENC	14-OCT-2014 0 0		
CHAPTER 26 FIRE PROTECTION							
SB	BR700-26-100396	NO. 2 ENGINE - FIRE PROTECTION - CORE ENGINE FIRE DETECTION SENSORS - INTRODUCTION OF REVISED CORE FIRE WIRE MOUNTING BRACKETS, SERVICE BULLETIN			OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
			26-APR-1999	MOS HRS/MSC ENC	14-OCT-2014 0 0		
SB	BR700-26-100434 R02	NO. 2 ENGINE - FIRE - PROTECTION - CORE ENGINE NOZZLE, TUBES AND FITTINGS - INTRODUCTION OF MODIFIED ZONE 2 TUBES AND ADDITIONAL CLIPPING, SERVICE BULLETIN			RECOMMENDED	COMPLIED WITH - AT MANUFACTURE	
			31-JUL-2002	MOS HRS/MSC ENC	14-OCT-2014 0 0		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-26-100466	NO. 2 ENGINE - FIRE PROTECTION - ELECTRICAL HARNESSES - INTRODUCTION OF CLIPPING POSITION CHANGES TO SUIT MODIFIED FIRE EXTINGUISHER SYSTEM, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
03-SEP-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
CHAPTER 36 PNEUMATIC							
SB BR700-36-100142 R01	NO. 2 ENGINE - PNEUMATIC - CABIN AIR DUCTS - INTRODUCTION OF A REVISED HP5 CABIN AIR DUCT ASSEMBLY, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
25-JAN-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
CHAPTER 71 POWER PLANT							
SB BR700-71-100058	NO. 2 ENGINE - POWER PLANT - THRUST REVERSER UNIT (TRU) AND GENERAL SERVICES HARNESS ATTACHMENT FITTINGS - INTRODUCTION OF REVISED CLIPPING POINTS, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
29-APR-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100161	NO. 2 ENGINE - POWER PLANT - RIGHT ENGINE HARNESS ATTACH FITTINGS - INTRODUCTION OF RE-ROUTED HARNESSES AND REPLACEMENT OF RELATED CLIPPING POINTS, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
24-JAN-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100177	NO. 2 ENGINE - POWER PLANT - ELECTRICAL HARNESSES - INTRODUCTION OF ENGINE BUILD UP (EBU) EXTENSION CLIPS, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
20-SEP-1997		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100180	NO. 2 ENGINE - POWER PLANT - RIGHT ENGINE HARNESS ATTACH FITTINGS - INTRODUCTION OF RE-ROUTED TRU HARNESS AND RELATED CLIPPING POINTS, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
15-JUN-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100211	NO. 2 ENGINE - POWER PLANT - DRAINS TANK EJECTOR - INTRODUCTION OF REVISED MATERIAL, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
15-JUN-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100242 R01	NO. 2 ENGINE - POWER PLANT - MINOR PODDING MODIFICATIONS, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
22-OCT-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100259	NO. 2 ENGINE - POWER PLANT - ADDITIONAL ACOC DELETION DRESSING MODIFICATIONS, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
24-JAN-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-71-100298 R02	NO. 2 ENGINE - POWER PLANT - ADDITIONAL PRODUCTION ACOC DELETION DRESSING MODIFICATIONS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100340	NO. 2 ENGINE - POWER PLANT - GEARBOX MOUNTED EBU BRACKETS - TRANSFER OF OWNERSHIP, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100341	NO. 2 ENGINE - POWER PLANT - VARIOUS - ADDITIONAL HARNESS CLIPPING MODIFICATIONS (NEUTRAL AND RIGHT HAND), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-MAR-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100351	NO. 2 ENGINE - POWER PLANT - GEARBOX MOUNTED EBU BRACKETS - INTRODUCTION OF SHORTER BOLTS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-MAR-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100426 R01	NO. 2 ENGINE - POWER PLANT - CORE/EXTERNAL DRAINS TUBES AND FITTINGS - INTRODUCTION OF REVISED CLEARANCES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-OCT-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100427 R01	NO. 2 ENGINE - POWER PLANT - EEC LANE A HARNESS 1A - RE-ORIENTATION OF HARNESS CONNECTOR BACKSHELLS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100428 R01	NO. 2 ENGINE - POWER PLANT - EEC LANE B HARNESS 1D - RE-ORIENTATION OF HARNESS CONNECTOR BACKSHELLS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100429 R01	NO. 2 ENGINE - POWER PLANT - EEC LANE B HARNESS 1E - RE-ORIENTATION OF HARNESS CONNECTOR BACKSHELLS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100476	NO. 2 ENGINE - POWER PLANT - ELECTRICAL HARNESSSES - REROUTING OF HARNESS LOOMS TO CLEAR BYPASS DUCT ACCESS PANEL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
17-SEP-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-71-100488	NO. 2 ENGINE - POWER PLANT - EEC LANES A AND B HARNESSSES - INTRODUCTION OF REVISED CLIPPING POINTS CP10022 AND CP10029, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100500	NO. 2 ENGINE - POWER PLANT - ELECTRICAL HARNESSSES - INTRODUCTION OF MINOR ASSOCIATED DRESSING CHANGES FOR THE EEC TROUGH DELETION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-SEP-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100530	NO. 2 ENGINE - POWER PLANT - EXTERNAL DRAIN TUBES AND FITTINGS - INTRODUCTION OF A CHANGE OF OWNERSHIP (INSTALLATION RESPONSIBILITY) FOR THE WET DRAINS BRACKETS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-APR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100585 R01	NO. 2 ENGINE - POWER PLANT - EEC LANE A HARNESS 1C - INTRODUCTION OF MODIFIED CLIPPING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100595 R01	NO. 2 ENGINE - POWER PLANT - GEARBOX MOUNTED EBU BRACKETS - INTRODUCTION OF REVISED LENGTH BOLTS TO ACCOMMODATE NEW STANDARD OF ACCESSORY GEARBOX MAIN HOUSING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-JUN-2005		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100602	NO. 2 ENGINE - POWER PLANT - FRONT SUSPENSION-ENGINE MOUNTED - INTRODUCTION OF THRUST TRUNNION FLANGE BOLTS WITH A THINNER HEAD, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
03-AUG-2016		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-71-100680 R02	NO. 2 ENGINE - POWER PLANT - GEARBOX MOUNTED ENGINE BUILD UNIT (EBU) BRACKETS - INTRODUCTION OF REVISED FIRERAIL SUPPORT BRACKET, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-NOV-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-100892	NO. 2 ENGINE - POWER PLANT - LEFT AND RIGHT ENGINE EEC LANE A HARNESS 1C AND LANE B HARNESS 1F - INTRODUCTION OF ELECTRONIC ENGINE CONTROLLER (EEC) HARNESSSES WITH A RESISTOR IN THE ELECTRICAL SUPPLY LINE TO THE STARTER AIR VALVE (SAV) SOLENOID, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
13-OCT-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-101465	NO. 2 ENGINE - POWER PLANT - GENERAL - INTRODUCTION OF A NEW EXTENSION CLIP WITH A SIMPLIFIED DESIGN, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
27-JAN-2006		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-71-101581	NO. 2 ENGINE - INTRODUCTION OF AN OIL DRAIN TUBE SUPPORT BRACKET WITH A SLOTTED HOLE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
13-SEP-2007		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-101603	NO. 2 ENGINE - POWER PLANT - ENGINE ELECTRONIC CONTROLLER (EEC) LANE A HARNESS 1A - CLIP POSITION CHANGES FOR THE OIL LEVEL SENSOR CABLE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-FEB-2008		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-71-900675	NO. 2 ENGINE - POWER PLANT - GENERAL - ENGINE CONVERSION FROM A FLIGHT-TEST STANDARD ENGINE TO A PRODUCTION STANDARD ENGINE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
30-JAN-2020		MOS					
		HRS/MSC	-				
		ENC					
CHAPTER 72 ENGINE							
ASB R03 BR700-72-A101523	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, ALERT SERVICE BULLETIN					ALERT	NOT APPLICABLE
10-DEC-2015		MOS		07-MAR-2016			
		HRS/MSC	-				
		ENC					
ASB R07 BR700-72-A900229	NO. 2 ENGINE - BR700-72-A900229 R07 - LP COMPRESSOR - INSPECTION OF THE FAN - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN					ALERT	NOT APPLICABLE - BY ENGINE S/N
16-JUN-2023		MOS		20-JUN-2023			
		HRS/MSC	-				
		ENC					
ASB R07 PART 1 BR700-72-A900229	NO. 2 ENGINE - ACCOMPLISH BR700-72-A900229 R07 - LP COMPRESSOR - INSPECTION OF THE FAN - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN DO A VISUAL INSPECTION OF THE FAN DISC.					ALERT	NOT APPLICABLE - BY ENGINE S/N
16-JUN-2023		MOS		20-JUN-2023			
		HRS/MSC	-				
		ENC					
ASB R07 PART 2 BR700-72-A900229	NO. 2 ENGINE - ACCOMPLISH BR700-72-A900229 R07 - LP COMPRESSOR - INSPECTION OF THE FAN - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN DO AN ULTRASONIC INSPECTION OF THE FAN DISC.					ALERT	NOT APPLICABLE - BY ENGINE S/N
16-JUN-2023		MOS		20-JUN-2023			
		HRS/MSC	-				
		ENC					
ASB BR700-72-A900297	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR FAIRINGS - INSPECTION OF THE UPPER LEFT HP COMPRESSOR FAIRING FOR POTENTIAL PROFILE NON-CONFORMANCE AND REPLACEMENT OF NON-CONFORMING UPPER LEFT HP COMPRESSOR FAIRING - NON-MODIFICATION, ALERT SERVICE BULLETIN					ALERT	NOT APPLICABLE
02-SEP-2013		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
ASB BR700-72-A900298	NO. 2 ENGINE - ENGINE - ENGINE COMBUSTION FAIRINGS - REPLACEMENT OF NON-CONFORMING UPPER LEFT, UPPER RIGHT AND LOWER RIGHT COMBUSTION SECTION FAIRINGS - NON-MODIFICATION, ALERT SERVICE BULLETIN					ALERT	NOT APPLICABLE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASB R01	BR700-72-A900497 NO. 2 ENGINE - HPT ROTOR DISCS - DECREASE OF TIME LIMITS MANUAL MAXIMUM APPROVED LIVES OF STG 1 & 2 DISCS, ALERT SERVICE BULLETIN					ALERT	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
	12-FEB-2010	HRS/MSC	-	0			
		ENC		0			
ASB R01	BR700-72-A900504 NO. 2 ENGINE - ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR TOUCH-AND-GO AND OVERSHOOT, ALERT SERVICE BULLETIN					ALERT	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
ASB R03	BR700-72-A900508 NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 AND 2 DISCS DUE TO POTENTIAL STEEL INCLUSION - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
	26-JUL-2012	HRS/MSC	-	0			
		ENC		0			
ASB R03	BR700-72-A900509 NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE FUEL PUMP SPLINED COUPLING - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
ASB R01	BR700-72-A900584 NO. 2 ENGINE - GENERAL - ENGINE INSTALLATION RESTRICTION AND CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN					ALERT	COMPLIED WITH - WORK ACCOMPLISHED
		MOS		07-APR-2017			
	31-JAN-2017	HRS/MSC	-	383:54			
		ENC					
ASB R01	BR700-72-A900584 NO. 2 ENGINE - GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN					ALERT	COMPLIED WITH - WORK DONE
		MOS		02-NOV-2017			
	05-OCT-2017	HRS/MSC	-	521:10			
		ENC		194			
ASB R01 PART A	BR700-72-A900584 NO. 2 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN INSTRUCTIONS TO DETERMINE THE EFFECTIVE ENGINE POPULATION					ALERT	COMPLIED WITH - WORK DONE
		DAYs		02-NOV-2017			
	05-OCT-2017	HRS/MSC	-	521:10			
		ENC		194			
ASB R01 PART B	BR700-72-A900584 NO. 2 ENGINE - ACCOMPLISH GENERAL - CHANGE OF LIFE COUNTING METHOD FOR ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 INCORPORATED - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN INSTRUCTIONS ON HOW TO CALCULATE THE LIVES FOR Affected PARTS ON ENGINES INSTALLED ON AIRCRAFT WITH ROCKWELL COLLINS AVIONICS WITHOUT HAVING BOMBARDIER SERVICE BULLETINS SB700-34-5021 OR SB700-34-6021 STANDARD INCORPORATED					ALERT	COMPLIED WITH - WORK DONE
		MOS		02-NOV-2017			
	05-OCT-2017	HRS/MSC	-	521:10			
		ENC		194			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASB BR700-72-A900659	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN						NOT APPLICABLE
22-JUL-2019		MOS HRS/MSC - ENC					
ASB BR700-72-A900659 PART A	NO. 2 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REMOVAL OF THE ENGINE FOR INCORPORATION OF PART B OF THIS NON-MODIFICATION SERVICE BULLETIN						NOT APPLICABLE
22-JUL-2019		MOS HRS/MSC - ENC					
ASB BR700-72-A900659 PART B	NO. 2 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REPLACEMENT OF HIGH PRESSURE (HP) TURBINE STAGE 1 DISCS						NOT APPLICABLE
22-JUL-2019		MOS HRS/MSC - ENC					
ASB R01 BR700-72-A900659	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN						NOT APPLICABLE
05-NOV-2019		MOS HRS/MSC - ENC					
ASB R01 PART A BR700-72-A900659	NO. 2 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REMOVAL OF THE ENGINE FOR INCORPORATION OF PART B OF THIS NON-MODIFICATION SERVICE BULLETIN						NOT APPLICABLE
05-NOV-2019		MOS HRS/MSC - ENC					
ASB R01 PART B BR700-72-A900659	NO. 2 ENGINE - ACCOMPLISH HIGH PRESSURE (HP) TURBINE ROTOR DISCS - REPLACEMENT OF THE HP TURBINE STAGE 1 DISCS - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN REPLACEMENT OF HIGH PRESSURE (HP) TURBINE STAGE 1 DISCS						NOT APPLICABLE
05-NOV-2019		MOS HRS/MSC - ENC					
ASB R01 BR700-72-A900732	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - VISUAL INSPECTION OF THE LP - COMPRESSOR ROTOR (FAN) DISC - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN				ALERT		NOT APPLICABLE - BY ENG S/N
16-JUN-2023		MOS HRS/MSC - ENC	20-JUN-2023				
SB BR700-72-100025 R02	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF HPC FRONT SPLIT CASING WITH INCREASED CAST BOSS DIAMETERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS HRS/MSC - ENC	14-OCT-2014 0 0				
SB BR700-72-100044 R03	NO. 2 ENGINE - ENGINE - HP COMPRESSOR (HPC) - INTRODUCTION OF VARIABLE STATOR VANES SOLID TIE RODS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JAN-2012		MOS HRS/MSC - ENC	14-OCT-2014 0 0				

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100109	NO. 2 ENGINE - ENGINE - HP COMPRESSOR (HPC) - INTRODUCTION OF VARIABLE STATOR VANES SOLID TIE RODS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-AUG-1997		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100110 R02	NO. 2 ENGINE - ENGINE - HP TURBINE - INTRODUCTION OF SILVER PLATING TREATMENT TO THREAD AND FLANK OF INTRASCOPE HOUSING BLANKING PLUG, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-JUL-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100138	NO. 2 ENGINE - ENGINE - LPC STATOR VANES - INTRODUCTION OF NEW LP COMPRESSOR STATOR VANE ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-OCT-1997		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100149	NO. 2 ENGINE - ENGINE - DRESSING AND NON DRESSING - MINOR ALTERATIONS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100150	NO. 2 ENGINE - ENGINE - FAIRING, INTAKE ROTATING - LP COMPRESSOR - INTRODUCTION OF A LIGHTWEIGHT LP COMPRESSOR NOSECONE FAIRING ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-SEP-1997		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100152 R01	NO. 2 ENGINE - ENGINE - ENGINE MOUNTING SUPPORT - INTRODUCTION OF A NEW REAR MOUNT RING ASSEMBLY WITH REDUCED WEIGHT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-NOV-1997		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100157	NO. 2 ENGINE - ENGINE - LP COMPRESSOR BLADES - INTRODUCTION OF LIGHTWEIGHT LP COMPRESSOR DISK SEALING PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-SEP-1997		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100158 R01	NO. 2 ENGINE - ENGINE - VANES, STATOR, EXIT GUIDE - LP COMPRESSOR - INTRODUCTION OF CAST ALUMINUM OUTLET GUIDE VANE ASSEMBLY WITH POTTED OUTER END AND DAMPED INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-SEP-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100159 R01	NO. 2 ENGINE - ENGINE - HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED HP 1 NOZZLE GUIDE VANES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-JUL-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100162	NO. 2 ENGINE - ENGINE - DISC, ROTOR - LP COMPRESSOR - INTRODUCTION OF A REDUCED WEIGHT ROTOR DISC WITH RE-PROFILED DOVETAIL SLOT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-OCT-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100164 R01	NO. 2 ENGINE - ENGINE - CASE AND FITTINGS - COMPRESSOR INTERMEDIATE (LP TO IP/HP) - INTRODUCTION OF ENGINE VIBRATION MONITOR TRANSDUCER MOUNTING PLATE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100172 R02	NO. 2 ENGINE - ENGINE - HPC REAR INNER CASE - INTRODUCTION OF A NEW ABRADABLE LINING MATERIAL ON THE ROTOR PATH LINERS OF HPC STAGE 5, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2003		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100178	NO. 2 ENGINE - ENGINE - ATTACHING PARTS AND FITTINGS - BYPASS DUCT MODULE - REVISED ENGINE BUILD-UP (EBU) FLANGE BRACKETS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUL-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100186	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF VARIOUS IMPROVEMENTS TO THE GEARBOX ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
05-MAR-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100194 R01	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF REDUCED STAGE 4 TO 10 PLATFORM GAPS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
16-JUL-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100195	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE - FIRE DETECTOR AND OVERHEAT PROBE PROTECTOR TUBES - REVISED LOCATION FEATURE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
31-MAY-1997		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100200 R02	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - FRONT BEARING AND SUPPORT - INTRODUCTION OF AN ALTERNATIVE NO. 3 BEARING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100202 R01	NO. 2 ENGINE - ENGINE - EXTERNALS - MINOR ENGINEERING MODIFICATIONS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
21-JUN-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100205	NO. 2 ENGINE - ENGINE - HP COMPRESSOR (HPC) - INTRODUCTION OF STAGE 7/8 HEATSHIELD WITH REDUCED CIRCUMFERENTIAL GAP, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
17-MAY-1997		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100207 R02	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF A TUBED VORTEX REDUCER AND A MODIFIED STAGE 7 TO 10 ROTOR ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100226	NO. 2 ENGINE - ENGINE - REPLACEMENT, DELETION OR INTRODUCTION OF NEW INSTRUCTIONS AND ARRANGEMENTS TO AMEND THE DIS10005., SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100229	NO. 2 ENGINE - ENGINE - SHAFT, ROTOR - LP TURBINE - INTRODUCTION OF LP TURBINE SHAFT IN SUPER S/CMV MATERIAL WITH REPROFILED INTERNAL BORE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-APR-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100233	NO. 2 ENGINE - ENGINE - RING, BLADE RETAINING - LP COMPRESSOR - INTRODUCTION OF A LIGHTWEIGHT RETAINING RING ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-SEP-1997		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100241	NO. 2 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF INTRASCOPE BLANK EXTRACTION FEATURE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
19-MAR-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100263	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A SLEEVE IN THE PRESSURE RELIEF VALVE BORE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-AUG-1997		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100263 R01	NO. 2 ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A SLEEVE IN THE PRESSURE RELIEF VALVE (PRV) HOUSING BORE OF THE ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
19-JAN-2016		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100265 R03	NO. 2 ENGINE - ENGINE - TURBINE AND REAR SUPPORT - INTRODUCTION OF REVISED FUEL SHUT OFF CABLE SETTING INSTRUCTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100266	NO. 2 ENGINE - ENGINE - TURBINE AND REAR SUPPORT - INTRODUCTION OF REVISED LPT EXHAUST CASE FUEL SHUT OFF EXIT RADIUS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-JUN-1997		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100267	NO. 2 ENGINE - ENGINE - INTRODUCTION OF ADDITIONAL CLIPPING AMENDMENTS DUE TO PODDING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-APR-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100268	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF SILVER COATED STAGE 1, 3 AND 5 INTRASCOPE PLUGS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-FEB-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100280	NO. 2 ENGINE - ENGINE - EXHAUST CASE - INTRODUCTION OF WEIGHT REDUCED LP TURBINE OUTLET GUIDE VANE (OGV) AND DOUBLE ENDED UNIONS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100281	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED COMBUSTION CHAMBER INNER CASE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100284 R01	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF REDUCED WEIGHT HP COMPRESSOR REAR OUTER CASE AND REVISED INTRASCOPE HOUSINGS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
19-DEC-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100290	NO. 2 ENGINE - ENGINE - BYPASS SERVICES FAIRING - MINOR CONFIGURATION AMENDMENTS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
16-JUL-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100291	NO. 2 ENGINE - ENGINE - VARIOUS - ADDITIONAL DRESSING MODIFICATIONS RELATING TO THE DELETION OF THE AIR COOLED OIL COOLER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
02-JUN-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100296 R01	NO. 2 ENGINE - ENGINE - SUPPORT, BEARING FRONT - LOW PRESSURE (LP) COMPRESSOR/DRIVEN ASSEMBLY - INTERNAL GEARBOX DRIVE - INTRODUCTION OF REVISED NO.1 AND NO.2 BEARING SUPPORT HOUSINGS AND ASSOCIATED COMPONENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-JAN-2009		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100299 R01	NO. 2 ENGINE - ENGINE - BYPASS DUCT, ELECTRICAL HARNESSSES AND ELECTRONIC ENGINE CONTROLLER (EEC) - DELETION OF EEC TROUGH AND INTRODUCTION OF EEC FIRE BOX AND ASSOCIATED MODIFICATIONS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS HRS/MSC ENC	-	14-OCT-2014 0 0			
SB BR700-72-100301	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED STAGE 1 DISC, SERVICE BULLETIN				14-OCT-2014	OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS HRS/MSC ENC	-	0 0 0			
SB BR700-72-100302 R01	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED STAGE 2 DISC, SERVICE BULLETIN				14-OCT-2014	OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS HRS/MSC ENC	-	0 0 0			
SB BR700-72-100303	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED REAR HEATSHIELD ASSEMBLY, SERVICE BULLETIN				14-OCT-2014	OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-JAN-1999		MOS HRS/MSC ENC	-	0 0 0			
SB BR700-72-100304	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED HP TURBINE CASE, SERVICE BULLETIN				14-OCT-2014	OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-MAR-1998		MOS HRS/MSC ENC	-	0 0 0			
SB BR700-72-100311	NO. 2 ENGINE - ENGINE - CASE LP COMPRESSOR - INTRODUCTION OF LP COMPRESSOR CASE ASSEMBLY WITH INCREASED THICKNESS FAN TRACK LINER, SERVICE BULLETIN				14-OCT-2014	RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-APR-1998		MOS HRS/MSC ENC	-	0 0 0			
SB BR700-72-100319	NO. 2 ENGINE - ENGINE - HP COMPRESSOR (HPC) - INTRODUCTION OF STAGE 6 BLADES WHICH INCORPORATE A FORGED PLATFORM RAMP, SERVICE BULLETIN				14-OCT-2014	OPTIONAL	COMPLIED WITH - AT MANUFACTURE
03-DEC-1998		MOS HRS/MSC ENC	-	0 0 0			
SB BR700-72-100320	NO. 2 ENGINE - ENGINE - LP TURBINE MODULE - INTRODUCTION OF WEIGHT REDUCED LP 1 BLADE DAMPERS, SERVICE BULLETIN				14-OCT-2014	OPTIONAL	COMPLIED WITH - AT MANUFACTURE
02-JUN-1998		MOS HRS/MSC ENC	-	0 0 0			
SB BR700-72-100322	NO. 2 ENGINE - ENGINE - MANIFOLD, IMPINGEMENT COOLING - HP TURBINE - ADDITIONAL LOAD SPREADING STRIPS ON THE FRONT AND REAR MOUNTING BRACKET SECURING FEATURES, SERVICE BULLETIN				14-OCT-2014	RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-DEC-1998		MOS HRS/MSC ENC	-	0 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100333	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF STAGE 10 BLADES WITH INCREASED PLATFORM WIDTH, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100336	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF STAGE 9 BLADES WITH INCREASED PLATFORM WIDTH AND ROOT DEPTH, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100337	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF STAGE 8 BLADES WITH INCREASED PLATFORM WIDTH AND ROOT DEPTH, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-MAR-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100346	NO. 2 ENGINE - ENGINE -HIGH PRESSURE (HP) COMPRESSOR - INTRODUCTION OF VARIABLE VANE INNER SHROUD BUSHES WITH REVISED TOLERANCES ON INNER AND OUTER DIAMETERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
02-JUN-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100347	NO. 2 ENGINE - ENGINE - EXHAUST CASE - INTRODUCTION OF AN LP TURBINE OUTLET GUIDE VANE (OGV) ASSEMBLY WITH MODIFIED STAGE 2 SHROUD RETENTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100353	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF ALUMINUM ALLOY UNISON RING CENTRALIZERS FOR WEIGHT REDUCTION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100362	NO. 2 ENGINE - ENGINE - INTERMEDIATE CASE MODULE - INTRODUCTION OF A NEW LOW PRESSURE SHAFT SPEED PROBE WITHOUT FUSE WIRES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-MAR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100373	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE - INTRODUCTION OF A REAR BEARING SUPPORT STRUCTURE (RBSS) BEARING BORE OFFSET, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-NOV-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100380 R01	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - INTRODUCTION OF A WEIGHT REDUCED COMBUSTION CHAMBER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-SEP-2005		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100381	NO. 2 ENGINE - ENGINE - EEC LANE A HARNESS 2A - INTRODUCTION OF A REVISED HARNESS LENGTH, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100382 R01	NO. 2 ENGINE - ENGINE - LP TURBINE - INTRODUCTION OF WEIGHT REDUCED LP TURBINE STAGE 1 SHROUD SEGMENTS AND WEIGHT REDUCED LP TURBINE CASE WITH IMPROVED SURFACE PROTECTION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100383	NO. 2 ENGINE - ENGINE - HP TURBINE - INTRODUCTION OF WEIGHT-REDUCED HP TURBINE STAGE 2 NOZZLE GUIDE VANES WITH REVISED COOLING AIR FLOW CHARACTERISTICS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
25-NOV-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100387	NO. 2 ENGINE - ENGINE - HP COMPRESSOR MODULE - DELETION OF WASHERS ON FLANGE CB, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100393	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE ATTACHING PARTS AND FITTINGS - INTRODUCTION OF BRACKETS MADE OF INCO 718 MATERIAL, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100401	NO. 2 ENGINE - ENGINE - LP COMPRESSOR (FAN) MODULE - ATTACH PARTS AND FITTINGS - INTRODUCTION OF A REVISED LP COMPRESSOR ANTI-SCORE RING IN CORROSION RESISTANT STEEL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100405	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE AND ENGINE MOUNTING SUPPORT - MINOR AMENDMENTS TO BRING THE CONFIGURATION DATABASE IN LINE WITH THE ENGINES AS BUILT, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100408	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF A NEW VANE TIP GRINDING AND ROTOR PATH MACHINING INSTRUCTION, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100411	NO. 2 ENGINE - ENGINE - ATTACHING PARTS AND FITTINGS - INTRODUCTION OF WEIGHT REDUCED EBU BRACKETS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100419 R01	NO. 2 ENGINE - ENGINE - LP COMPRESSOR BLADES - INTRODUCTION OF FAN ANNULUS FILLERS WITH POSITIVE BUSH LOCATION AND REVISED SEALING STRIPS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-DEC-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100433 R02	NO. 2 ENGINE - ENGINE - CASE AND FITTINGS - COMPRESSOR INTERMEDIATE (LP TO IP/HP) - INTRODUCTION OF REVISED CASE WITH MODIFIED EARTHING BRACKETS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
11-JAN-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100461 R01	NO. 2 ENGINE - ENGINE - LP COMPRESSOR - INTRODUCTION OF LP COMPRESSOR BLADES WITH REVISED TRAILING EDGE, MOMENT LIMITS AND DEFINITION OF FREQUENCY LIMITS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-DEC-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100463	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF OIL-FILLING INSTRUCTION LABELS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100475 R02	NO. 2 ENGINE - ENGINE - HP COMPRESSOR MODULE - INTRODUCTION OF NEW VANES ON THE HPC STAGES 6 TO 9, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
03-APR-2003		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100494	NO. 2 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF A PRESSURE RECOVERY DEVICE IN THE PRECOOLER FAN AIR FLOW LINE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
09-SEP-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100506	NO. 2 ENGINE - ENGINE - LP COMPRESSOR CASE - INTRODUCTION OF A REVISED STARTER EFFLUX SHIELD WITH EDGE PROTECTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-JAN-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100544 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A MOUNT KIT WITH IMPROVED PROTECTION AND DELETION OF THE BREather COVER INSTRUMENTATION BOSS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
05-AUG-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100563 R01	NO. 2 ENGINE - LP/HP TURBINE SUPPORT AND OUTER BEARINGS - INTRODUCTION OF STAGE 4 AIR TUBES AND REAR BEARING SUPPORT STRUCTURE (RBSS) WITH INCREASED CONTACT AREA, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100564 R01	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE - REMOVAL OF INSULATION STRIPS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-MAY-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100566 R02	NO. 2 ENGINE - ENGINE - HPC REAR INNER CASE - INTRODUCTION OF A NEW ABRADABLE LINING MATERIAL ON THE ROTOR PATH LINERS OF HPC STAGE 6, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2003		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100600 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A NEW STANDARD OF MAIN HOUSING AND ASSOCIATED ASSEMBLY IMPROVEMENTS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-JUN-2005		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100621	NO. 2 ENGINE - ENGINE - HP COMPRESSOR VARIABLE INLET GUIDE VANE ACTUATING MECHANISM - INTRODUCTION OF REDUCED LENGTH VARIABLE STATOR VANE ACTUATOR (VSVA) BRACKET CONNECTING DOWELS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100623	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF REDUCED WEIGHT HP COMPRESSOR STAGE 1 TO 6 ROTOR DISKS ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100635	NO. 2 ENGINE - ENGINE - HP COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) RINGS AND SEALS - INTRODUCTION OF A NEW VIGV INNER SHROUD, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-DEC-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100643	NO. 2 ENGINE - ENGINE - INTERMEDIATE CASE MODULE ATTACHING PARTS AND FITTINGS - INTRODUCTION OF REVISED FASTENERS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
30-APR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100671	NO. 2 ENGINE - ENGINE - HPT BLADES - INTRODUCTION OF HP TURBINE STAGE 2 BLADE DAMPERS WHICH ARE MANUFACTURED AS A PRECISION CASTING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-OCT-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100681 R01	NO. 2 ENGINE - ENGINE - LP COMPRESSOR INTAKE ROTATING FAIRING - INTRODUCTION OF REVISED NOSE CONE ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-OCT-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100686	NO. 2 ENGINE - ENGINE - NL SPEED PROBE HARNESS AND ACCESSORIES - REDUCED NUMBER OF SPEED PROBE WASHERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100704	NO. 2 ENGINE - ENGINE - COMBUSTION INNER CASE AND VANES - INTRODUCTION OF COMPRESSOR OUTLET GUIDE VANES (OGV)/DIFFUSER CASE WITH IMPROVED AIR FLOW CHARACTERISTICS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100712	NO. 2 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF NEW HP COMPRESSOR VSV SYSTEM DRIVE BRACKETS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
16-DEC-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100720 R01	NO. 2 ENGINE - ENGINE - HP COMPRESSOR BLADES - INTRODUCTION OF REVISED STAGES 6 TO 10 BLADE PLATFORM GAPS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-MAY-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100733	NO. 2 ENGINE - ENGINE - LPC FRONT AND REAR (NO. 1, 2 AND 3) BEARING AND SUPPORT - INTRODUCTION OF ALTERNATIVE SQUEEZE FILM PISTON RINGS., SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
16-DEC-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100770 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF SHOT PEENED GEARS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2003		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100785	NO. 2 ENGINE - ENGINE - HP TURBINE - INTRODUCTION OF DECREASED COLD BUILD CLEARANCE ON STAGE 1 HP TURBINE AND DELETION OF DRY FILM LUBRICANT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100805 R01	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF NEW PROCEDURE FOR TIP GRINDING OF HP COMPRESSOR VANES AND IN-SERVICE ROTOR BLADE NUMBERING PROCEDURE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100812	NO. 2 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF A VIGV UNISON RING WITH IMPROVED CORROSION RESISTANCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JAN-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100813	NO. 2 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF A VSV STAGE 1 UNISON RING WITH IMPROVED CORROSION RESISTANCE, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
22-MAR-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100814	NO. 2 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF A VSV STAGE 2 UNISON RING WITH IMPROVED CORROSION RESISTANCE, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
28-JAN-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100815	NO. 2 ENGINE - ENGINE - HPC VIGV ACTUATING MECHANISM - INTRODUCTION OF A VSV STAGE 3 UNISON RING WITH IMPROVED CORROSION RESISTANCE, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
22-MAR-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100818	NO. 2 ENGINE - ENGINE - LP COMPRESSOR ROTOR SHAFT - INTRODUCTION OF FAN SHAFT ASSEMBLY WITH REVISED MATERIAL PHONIC WHEEL, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
20-OCT-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100840	NO. 2 ENGINE - ENGINE - HP TURBINE ROTOR DISKS - INTRODUCTION OF A REVISED MANUFACTURING PROCESS FOR HPT STAGE 1 DISKS, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
18-JUN-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100845 R02	NO. 2 ENGINE - ENGINE - NL SPEED PROBE HARNESS AND ACCESSORIES - INTRODUCTION OF A NEW HARNESS ASSEMBLY, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
16-MAY-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100848	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF AN ACCESSORY GEARBOX WITH ALL GEARS SHOT PEENED ON THE EXTERNAL SURFACES, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
21-JUN-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100851 R02	NO. 2 ENGINE - ENGINE - LP COMPRESSOR (FAN) MODULE - INTRODUCTION OF A COMMON MASTER PART, SERVICE BULLETIN			INFORMATIONAL		COMPLIED WITH - AT MANUFACTURE	
15-FEB-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100852 R02	NO. 2 ENGINE - ENGINE - LP COMPRESSOR CASE MODULE - INTRODUCTION OF A COMMON MASTER PART, SERVICE BULLETIN			INFORMATIONAL		COMPLIED WITH - AT MANUFACTURE	
19-DEC-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100853 R01	NO. 2 ENGINE - ENGINE - LP TURBINE MODULE - INTRODUCTION OF A COMMON MASTER PART, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
09-NOV-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100859	NO. 2 ENGINE - ENGINE - LPC REAR (NO.2) BEARING ASSEMBLY FRONT PANEL - INTRODUCTION OF REVISED MATERIAL SPEED PROBE SUPPORT BRACKET, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
16-DEC-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100865	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF A NEW STANDARD OF INSERT IN THE HAND CRANK FLANGE OF THE BREATHER COVER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-DEC-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100867	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - CHANGES TO THE CONTOUR OF THE GEARBOX MAIN HOUSING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-NOV-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100879 R01	NO. 2 ENGINE - LP/HP TURBINE STATOR RETAINERS/SEALS - INTRODUCTION OF ABRADABLE LININGS WITH INCREASED CORROSION RESISTANCE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100899 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF THINNER ADJUSTING SHIMS AT BEVEL GEAR LINE 1 AND 2, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-JUN-2003		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100900 R01	NO. 2 ENGINE - HP COMPRESSOR AND COMBUSTION FAIRINGS-INTRODUCTION OF NEW FAIRINGS WITH NEW ATTACHMENT FEATURES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100901	NO. 2 ENGINE - ENGINE - HPC ROTOR HYDRAULIC SEAL - INTRODUCTION OF AN HP COMPRESSOR HYDRAULIC SEAL ASSEMBLY WITH INCREASED CLEARANCE BETWEEN THE SEAL AND THE LP TURBINE SHAFT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-FEB-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100902	NO. 2 ENGINE - ENGINE - LPC PHONIC WHEEL - INTRODUCTION OF A REAR INNER BEARING ASSEMBLY WITH INCREASED CLEARANCE BETWEEN THE BEARING INNER RACE AND THE LP TURBINE SHAFT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-OCT-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-100903	NO. 2 ENGINE - ENGINE - HP TURBINE ROTOR SHAFT AND (NO 4) BEARING - INTRODUCTION OF ABRADABLE LINING WITH INCREASED CORROSION RESISTANCE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
28-APR-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100913	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF ALTERNATIVE MOUNT WASHERS MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-APR-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100944 R03	NO. 2 ENGINE - ENGINE - COMBUSTION AND HP TURBINE MODULE ATTACH PARTS AND FITTINGS - DRESSING CHANGES FOR THE NEW HP COMPRESSOR AND COMBUSTION FAIRINGS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-JAN-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100952 R01	NO. 2 ENGINE - ENGINE - LP TURBINE FAIRINGS - INTRODUCTION OF LP TURBINE FAIRINGS WITH INCREASED WIDTH RELIEF SLOTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
30-JUL-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100976 R03	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INCREASED CLEARANCE BETWEEN THE GENERATOR MAGNETIC SEALS AND THEIR RELATED AIR BLOWN SEALS AND BETWEEN THE ACCESSORY GEARBOX GEAR LINE 6 AND THE HYDRAULIC PUMP SPLINE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
13-SEP-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100978 R01	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF DECREASED COLD BUILD TIP CLEARANCES FOR THE HP COMPRESSOR STAGES 5, 6, 7 AND 9 STATOR VANES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100981 R01	NO. 2 ENGINE - ENGINE - LP COMPRESSOR - CASE - INTRODUCTION OF REVISED FAN TRACK LINER AND ICE IMPACT PANEL ADHESIVE AND FILLER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-JAN-2004		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-100985	NO. 2 ENGINE - ENGINE - HP COMPRESSOR BLADES - REMOVAL OF THE HP COMPRESSOR STAGES 1, 2 AND 3 ROTOR BLADE UNDERPLATFORM STRIP SEALS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-SEP-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101006	NO. 2 ENGINE - ENGINE - COMBUSTION FAIRINGS - INTRODUCTION OF NEW FASTENERS FOR COMBUSTION CENTRE CORE FAIRINGS AND LP TURBINE DIAPHRAGMS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
19-OCT-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101007	NO. 2 ENGINE - ENGINE - HPC FRONT (NO. 3) BEARING SUPPORT - INCREASED CLEARANCE BETWEEN THE NUMBER 2 RECOMMENDED BEARING HOUSING AND THE NUMBER 3 BEARING RETAINER, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
12-JUL-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101019	NO. 2 ENGINE - ENGINE - LPC BEARING SEALS - INTRODUCTION OF NEW INTERNAL GEARBOX FORWARD AIR SEAL PISTON RING SEAL MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101020	NO. 2 ENGINE - ENGINE - LPC INTAKE ROTATING FAIRING - INTRODUCTION OF A NEW NOSE CONE FAIRING ASSEMBLY., SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
23-NOV-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101032	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW MATERIAL FOR MOUNT BUSHES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-JAN-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101037 R01	NO. 2 ENGINE - ENGINE - HPC REAR OUTER CASE - INTRODUCTION OF NEW HP COMPRESSOR STAGE 9 INTRASCOPE PLUG ASSEMBLIES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
04-SEP-2003		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101038	NO. 2 ENGINE - ENGINE - HPC REAR OUTER CASE - INTRODUCTION OF HP COMPRESSOR STAGE 5 INTRASCOPE PLUGS MADE FROM A DIFFERENT MATERIAL AND WITH A DECREASED THREAD DIAMETER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-FEB-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101057 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX - INTRODUCTION OF CHANGES BECAUSE OF A SUPPLIER TRANSFER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
13-JUL-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101060 R01	NO. 2 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF A NEW ENGINE NAME PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-SEP-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101068	NO. 2 ENGINE - ENGINE - HP COMPRESSOR - INTRODUCTION OF DECREASED COLD BUILD TIP CLEARANCES FOR HP COMPRESSOR ROTOR BLADES AND STATOR VANES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-FEB-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101069	NO. 2 ENGINE - ENGINE - HPC VARIABLE INLET GUIDE VANE (VIGV) ACTUATING MECHANISM - INTRODUCTION OF NUT RETAINERS WITH IMPROVED FEATURES FOR EASIER ASSEMBLY OF THE UNISON RINGS, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
21-JUN-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101084 R01	NO. 2 ENGINE - ENGINE - LPC FRONT (NO. 1) BEARING AND SUPPORT - INTRODUCTION OF A NO. 1 BEARING WITH A NEW DIAMETRAL CLEARANCE AND A RADIUSED INNER SPLIT LINE, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
26-NOV-2005		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101088	NO. 2 ENGINE - ENGINE - LPC STATOR VANES - INTRODUCTION OF AN ENGINE SECTION STATOR (ESS) WITH A NEW FILLER MATERIAL FOR THE PLATFORM, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
07-FEB-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101090 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW IDENTIFICATION PLATE, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
12-JUN-2003		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101091	NO. 2 ENGINE - ENGINE - HPT 1 NGV - INTRODUCTION OF HP TURBINE STAGE 1 NOZZLE GUIDE VANES WITH NEW FILM COOLING HOLE CONFIGURATION, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
12-JUL-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101100 R02	NO. 2 ENGINE - ENGINE - HPC ROTOR SHAFT - INTRODUCTION OF A NEW HP COMPRESSOR STUB SHAFT WITH AN IMPROVED BALANCING PROCEDURE, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
21-SEP-2004		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101102	NO. 2 ENGINE - ENGINE - HPC ROTOR REAR DISKS - INTRODUCTION OF A NEW HP COMPRESSOR STAGE 7 TO 10 ROTOR ASSEMBLY, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
13-JUL-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101103	NO. 2 ENGINE - ENGINE - HPC ROTOR FRONT DISKS - INTRODUCTION OF A NEW HP COMPRESSOR STAGE 1 TO 6 ROTOR ASSEMBLY, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
28-JAN-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101107 R01	NO. 2 ENGINE - ENGINE - INTERMEDIATE CASE MODULE - DELETION OF JOINTING COMPOUND ON ENGINE SECTION STATOR (ESS) AND THE INTERNAL GEARBOX (IGB) MATING FACES, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
12-JUL-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101114 R04	NO. 2 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF A BYPASS DUCT WITH NEW INSERTS FOR INSTALLATION OF A FUEL RETURN TO TANK VALVE AND FOR A REPOSITIONED LP FUEL SWITCH, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-NOV-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101116	NO. 2 ENGINE - ENGINE - LPC REAR NO.2 BEARING ASSY FRONT PANEL - INTRODUCTION OF NEW O-RINGS WITH A DECREASED INTERNAL DIAMETER, SERVICE BULLETIN				14-OCT-2014	RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
24-JAN-2001		MOS					
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101117	NO. 2 ENGINE - ENGINE - HPT BLADES - INTRODUCTION OF HP TURBINE STAGE 1 BLADES WITH A NEW FILM COOLING HOLE CONFIGURATION, SERVICE BULLETIN				14-OCT-2014	OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-NOV-2001		MOS					
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101117 R01	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF HP TURBINE STAGE 1 BLADES WITH A NEW FILM COOLING HOLE CONFIGURATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
26-SEP-2018		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-72-101128 R01	NO. 2 ENGINE - ENGINE - HPT ROTOR SHAFT AND NO. 4 BEARING - INTRODUCTION OF AN HP TURBINE NO. 4 STUB SHAFT WITH IDENTITY MARKINGS PERMITTED ONLY ON THE REAR FACE OF THE SHAFT, SERVICE BULLETIN				14-OCT-2014	INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
25-MAR-2008		MOS					
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101139 R01	NO. 2 ENGINE - HPC ROTOR SHAFT-INTRODUCTION OF A NEW FITTING INSTRUCTION FOR THE HP COMPRESSOR STUB SHAFT TO ALIGN WITH THE HP COMPRESSOR ROTOR, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-DEC-2006		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101144	NO. 2 ENGINE - ENGINE - COMBUSTION INNER CASE AND VANES - INTRODUCTION OF A NEW COMBUSTION INNER FRONT CASING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-JUN-2003		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101150	NO. 2 ENGINE - ENGINE - NL SPEED PROBES - INTRODUCTION OF LP COMPRESSOR TRIM BALANCE AND SPEED PROBES WHICH ARE MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN				14-OCT-2014	OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-DEC-2003		MOS					
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101157	NO. 2 ENGINE - ENGINE - TURBINE EXHAUST SUPPORTS - INTRODUCTION OF NEW REAR MOUNT SUPPORT STRUTS WITH A DIFFERENT COATING, SERVICE BULLETIN				14-OCT-2014	OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-MAR-2008		MOS					
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101167	NO. 2 ENGINE - ENGINE - LPC ROTOR SHAFT - INTRODUCTION OF FAN SHAFT BOLTS WITH INCREASED HEAD THICKNESS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-AUG-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101173	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP)/HIGH PRESSURE (HP) TURBINE STATOR RETAINERS/SEALS - INTRODUCTION OF A NEW REAR BEARING SUPPORT STRUCTURE (RBSS) VENT DUCT, REAR HEAT SHIELD AND LP TURBINE SEAL CARRIER WHICH ARE DECREASED IN WEIGHT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-MAR-2007		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101174	NO. 2 ENGINE - ENGINE - COMBUSTION FAIRINGS - INTRODUCTION OF A LEFT HAND LOWER COMBUSTION FAIRING WITH A STRENGTHENED PRESSURE RELIEF DOOR, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-FEB-2003		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101175	NO. 2 ENGINE - ENGINE - LPC EXIT GUIDE STATOR VANES - INTRODUCTION OF A NEW PART NUMBER FOR THE ALUMINIUM OUTLET GUIDE VANE (OGV) ASSEMBLY WITH CHANGED CLASSIFICATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
25-JAN-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101177 R01	NO. 2 ENGINE - ENGINE - COMBUSTION OUTER CASE - INTRODUCTION OF A NEW COMBUSTION CHAMBER OUTER CASING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101179 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - CHANGES TO OIL DISTRIBUTORS, PLUGS, O-RINGS, INSERTS AND RETAINING RINGS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-MAY-2004		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101180	NO. 2 ENGINE - ENGINE - HPC VIGV AND STAGES 1-4 STATOR VANES - INTRODUCTION OF A NEW VARIABLE INLET GUIDE VANE (VIGV) ASSEMBLY WHICH IS DECREASED IN WEIGHT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-AUG-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101181	NO. 2 ENGINE - ENGINE - HPC VIGV AND STAGES 1 - 4 STATOR VANES - INTRODUCTION OF A NEW STAGE 1 VANE ASSEMBLY WHICH IS DECREASED IN WEIGHT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-AUG-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101190	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF NEW ACCESSORY GEARBOX LINE 1 AND LINE 2 BEVEL GEARS WHICH ARE MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-FEB-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101193 R01	NO. 2 ENGINE - ENGINE - HIGH PRESSURE COMPRESSOR (HPC) FRONT CASE - INTRODUCTION OF A NEW HPC FRONT CASE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
19-JUN-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101197	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF THE FIRE SHIELD ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-MAR-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101203 R01	NO. 2 ENGINE - ENGINE - HIGH PRESSURE COMPRESSOR (HPC) VARIABLE INLET GUIDE VANES (VIGV) ACTUATING MECHANISM - INTRODUCTION OF NEW HPC LEVERS WITH CHANGED TOLERANCES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAR-2003		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101204	NO. 2 ENGINE - ENGINE - COMBUSTION REAR INNER CASE - INTRODUCTION OF NEW FRONT AND REAR COMBUSTION INNER CASINGS WHICH ARE DECREASED IN WEIGHT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-JUN-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101205	NO. 2 ENGINE - ENGINE - HPT1 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW PRESWIRL NOZZLE WITH A DECREASED COOLING AIR FLOW TO THE HP 1 TURBINE ROTOR DISC AND BLADES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-MAR-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101216	NO. 2 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF A NEW ENGINE NAME PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-FEB-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101218	NO. 2 ENGINE - ENGINE - LPT FUEL SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF MECHANISM PAWLS WHICH HAVE A LARGER SURFACE CONTACT AREA WITH THE FUEL SHUT-OFF REFERENCE TUBE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-APR-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101218 R01	NO. 2 ENGINE - LOW PRESSURE (LP) TURBINE FUEL SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF MECHANISM PAWLS WHICH HAVE A LARGER SURFACE CONTACT AREA WITH THE FUEL SHUT-OFF REFERENCE TUBE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
03-DEC-2020		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-72-101222	NO. 2 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF NEW BUILD INSTRUCTIONS TO DECREASE HIGH PRESSURE (HP) VIBRATION LEVELS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JAN-2009		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101223 R02	NO. 2 ENGINE - ENGINE - LPT FUEL SHUT-OFF CABLE AND FITTINGS - INTRODUCTION OF INCREASED CLEARANCES BETWEEN THE FUEL SHUT-OFF CABLE AND ADJACENT DRESSINGS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-MAY-2004		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101246	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR DISC - INTRODUCTION OF A NEW FAN DISC DESIGN FOR LIFE ENHANCEMENT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-OCT-2016		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101246 R01	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR DISC - INTRODUCTION OF A NEW FAN DISC DESIGN FOR LIFE ENHANCEMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
12-APR-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101252	NO. 2 ENGINE - ENGINE - COMBUSTION LINER - INTRODUCTION OF A NEW COMBUSTOR HEAT SHIELD, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-JUL-2003		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101254	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF CHANGES TO THE MANUFACTURING PROCEDURE FOR THE ACCESSORY GEARBOX LINE 1 AND LINE 2 BEVEL GEARS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-OCT-2008		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101258 R01	NO. 2 ENGINE - ENGINE - LP COMPRESSOR CASE - INTRODUCTION OF A LP COMPRESSOR CASE WHICH IS MADE FROM A FORGING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
25-JAN-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101260	NO. 2 ENGINE - ENGINE - HPT ROTOR SHAFT AND (NO. 4) BEARING - INTRODUCTION OF AN HP TURBINE STUB SHAFT WHICH IS DECREASED IN WEIGHT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JUN-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101270	NO. 2 ENGINE - ENGINE - LP/HP TURBINE SUPPORT AND OUTER BEARINGS - INTRODUCTION OF FRONT AND REAR BEARING CHAMBER PISTON RINGS WITH A SPECIFIED ROUNDNESS VALUE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
28-JUN-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101271	NO. 2 ENGINE - ENGINE - HPC FRONT (NO 3) BEARING SUPPORT - INTRODUCTION OF NEW BOLTS TO ATTACH THE REAR LABYRINTH SEAL, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
28-JUN-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101275	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ACCESSORY GEARBOX MAIN HOUSING WITH AN IMPROVED MANUFACTURING PROCEDURE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-NOV-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101285	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX INPUT HOUSING AND ADJUSTING SHIMS, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
16-JUN-2003		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101286	NO. 2 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF BYPASS DUCT ACCESS COVERS WITH TITANIUM OUTER SKINS, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
22-MAR-2004		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101293	NO. 2 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF A BYPASS DUCT (BPD) WHICH IS MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
28-JUN-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101326 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW SELF LOCKING NUT FOR THE ACCESSORY GEARBOX LINE NUMBER 9 BREather SHAFT, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
17-NOV-2008		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101328	NO. 2 ENGINE - ENGINE - HPT 2 LINERS - INTRODUCTION OF NEW HP TURBINE STAGE 2 LINERS, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
22-MAR-2004		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101331	NO. 2 ENGINE - ENGINE - LPT CASE - INTRODUCTION OF DECREASED SHROUD TIP CLEARANCES BETWEEN THE LP TURBINE STAGE 1 AND 2 ROTOR BLADES AND THEIR RELATED SHROUD SEGMENTS, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
23-MAY-2003		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101333	NO. 2 ENGINE - ENGINE - HPT ROTOR DISCS - INTRODUCTION OF A NEW STANDARD OF CURVIC RING, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
28-JUN-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101349	NO. 2 ENGINE - ENGINE - LPT FUEL SHUT-OFF CABLE AND FITTINGS - INTRODUCTION OF A NEW FUEL SHUT-OFF (FSO) CABLE WITH BRAZED-ON CLIPS, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
24-JUN-2003		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101351 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ALTERNATIVE LINE 9 IMPELLER SHAFT WITH A NEW EXTERNAL THREAD DIAMETER TOLERANCE, NEW IDENTITY MARKINGS AND AN ALTERNATIVE MATERIAL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-JUL-2003		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-72-101369	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR BLADES - INTRODUCTION OF NEW HP COMPRESSOR STAGE 5 AND 6 BLADES MADE FROM A NEW MATERIAL, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
26-JAN-2006		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-72-101395	NO. 2 ENGINE - ENGINE - LP COMPRESSOR BLADES - INTRODUCTION OF A METCO 58 COATING ON THE LP COMPRESSOR BLADES, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
10-MAY-2004		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-72-101414	NO. 2 ENGINE - HPC FRONT CASE - INTRODUCTION OF NEW COATED BUSHES FOR IMPROVED CORROSION PROTECTION, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - AT MANUFACTURE	
15-SEP-2003		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-72-101416 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX LINE 12 SPACER, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
11-AUG-2003		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-72-101417	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX LINE 12 GEAR SHAFT, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
27-FEB-2004		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-72-101419 R02	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) VARIABLE INLET GUIDE VANE (VIGV) ACTUATING MECHANISM - INTRODUCTION OF A NEW BUILD INSTRUCTION TO INCREASE END FLOAT AND CENTRALISER GAP, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - AT MANUFACTURE	
15-MAR-2012		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-72-101420	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE CASE - APPLICATION OF ANTI-SEIZURE COMPOUND ON DESIGNATED PLUGS OF COMBUSTOR AND TURBINE, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH - AT MANUFACTURE	
07-MAY-2004		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-72-101421	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE STAGE 1 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW REAR BEARING SUPPORT STRUCTURE (RBSS) VENT DUCT MADE FROM A FORGING, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - AT MANUFACTURE	
20-MAR-2007		MOS HRS/MSC ENC		14-OCT-2014 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101431	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 1 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW ONE PIECE PRESWIRL NOZZLE AND WEB SEAL ASSEMBLY, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
08-MAY-2006		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101436 R01	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) EXIT GUIDE STATOR VANES - FAN OUTLET GUIDE VANE (OGV) RE-SOURCING, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
03-MAR-2010		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101440	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE AND GEARBOX RADIAL DRIVE - INTRODUCTION OF REVISED INSTALLATION PROCEDURE, SERVICE BULLETIN				RECOMMENDED		COMPLIED WITH - AT MANUFACTURE
30-MAR-2009		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101453 R01	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR STATOR VANES - INTRODUCTION OF A FULLY MACHINED ENGINE SECTION STATOR (ESS) BLADE INTEGRATED RING (BLING), SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
23-APR-2013		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101454	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW MATERIAL FOR THE HP TURBINE SUPPORT RING, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
10-JAN-2005		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101456	NO. 2 ENGINE - ENGINE LOW PRESSURE (LP) TURBINE SHUT OFF PAWL CARRIER - DELETION OF AN UNUSED TRIM BALANCE FEATURE ON THE PAWL CARRIER, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
09-SEP-2004		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101457	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 NOZZLE GUIDE SEALS - INTRODUCTION OF A NEW MATERIAL FOR THE HP TURBINE RIM SEAL, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
10-JAN-2005		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101461	NO. 2 ENGINE - ENGINE - COMBUSTION FAIRINGS - INTRODUCTION OF A NEW CORE FAIRING WITH BLOW OPEN DOOR REMOVED, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
01-JUN-2005		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101463	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR INNER CASE - INTRODUCTION OF A NEW STAGE 5 TO 10 REAR INNER CASE, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
26-APR-2006		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101469 R01	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VORTEX REDUCER - INTRODUCTION OF A NEW FORGING MATERIAL FOR THE HP COMPRESSOR VORTEX REDUCER RING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
29-AUG-2014		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101471 R02	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - INTRODUCTION OF METCO 58 COATED LP COMPRESSOR BLADES WITH A TRANSITION STRIP, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
28-JUL-2005		MOS		14-OCT-2014			
		HRS/MSC	A/R	0			
		ENC		0			
SB BR700-72-101474	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - INTRODUCTION OF A LASER SHOCK PEENED (LSP) LP COMPRESSOR ROTOR DISC WITH A NEW PART NUMBER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101476 R01	NO. 2 ENGINE - COMBUSTION LINER - INTRODUCTION OF A NEW COMBUSTION CHAMBER WITHOUT COOLING RIBS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
29-AUG-2014		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101490	NO. 2 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF A NEW RADIAL DRIVE SHAFT (RDS) LOWER SUPPORT HOUSING (LSH), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-JUL-2006		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101492	NO. 2 ENGINE - ENGINE - BYPASS DUCT - INTRODUCTION OF NEW INTRASCOPE BLANKS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-NOV-2005		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101493	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR INNER CASE - DELETION OF THE HP VCOMPRESSOR STAGE 5 AND STAGE 7 TO 8 HEAT-SHIELDS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-NOV-2005		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101498	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF METAL TRANSPORTATION BLANKS WITH PLASTIC TRANSPORTATION BLANKS AND INTRODUCTION OF ALTERNATIVE ORIGINAL SUPPLIER PART NUMBERS FOR CERTAIN ACCESSORY GEARBOX COMPONENTS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAR-2012		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101500	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW ACCESSORY GEARBOX MAIN HOUSING ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101522	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW METHOD OF MANUFACTURE FOR ACCESSORY GEARBOX COMPONENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-FEB-2008		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101523 R02	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE SHUT-OFF PAWL CARRIER - INTRODUCTION OF FUEL SHUT-OFF PAWL CARRIER PIVOT PINS MADE FROM A DIFFERENT MATERIAL WITH IMPROVED CORROSION PROTECTION PROPERTIES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
19-DEC-2013		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101525	NO. 2 ENGINE - INTERMEDIATE CASE MODULE - INTRODUCTION OF NEW AND RE-IDENTIFIED INTERNAL GEARBOX COMPONENTS BECAUSE OF DESIGN RESPONSIBILITY CHANGE (SUPERSEDED BY SB BR700-72-101939), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-SEP-2006		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101526	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) TURBINE MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW LP TURBINE AXIAL SETTING PROCEDURE WITH AN INCREASED RANGE OF ADJUSTING RINGS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
11-NOV-2008		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101527	NO. 2 ENGINE - INTERMEDIATE CASE MODULE ATTACH PARTS AND FITTINGS - INTRODUCTION OF A NEW AIR TURBINE STARTER BRACKET ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-AUG-2007		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101531	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF NEW MANUFACTURING PROCEDURES FOR ACCESSORY GEARBOX COMPONENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-FEB-2008		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101540 R04	NO. 2 ENGINE - EXHAUST CASE - INTRODUCTION OF AN OUTLET GUIDE VANE (OGV) HOUSING ASSEMBLY MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
29-AUG-2014		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101548	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR CASE - INTRODUCTION OF A NEW LP COMPRESSOR CASE WITH NEW IMPROVED SEALING OF THE REAR PANEL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101551	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - DELETION OF BREather FILTER AND CHANGES TO BREather COVER, TANK COVERS AND OBTURATOR PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-MAY-2007		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101573	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR - INCREASED TIP CLEARANCE FOR HP COMPRESSOR STAGE 4 STATOR VANES, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
11-SEP-2006		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-72-101577	NO. 2 ENGINE - ENGINE - BYPASS DUCT ATTACHING PARTS AND FITTINGS - INTRODUCTION OF NEW BYPASS DUCT FRONT AND REAR LOAD SPREADER PLATE ASSEMBLIES, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
30-JUL-2008		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-72-101580	NO. 2 ENGINE - ENGINE - COMPRESSOR INTERMEDIATE CASE AND FITTINGS - INTRODUCTION OF A NEW ENGINE NAME PLATE, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
24-SEP-2008		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-72-101589	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ACCESSORY GEARBOX MAIN HOUSING MADE FROM ALUMINUM, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
05-FEB-2008		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-72-101604 R01	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR BLADES - INTRODUCTION OF HP COMPRESSOR STAGE 1 BLADES WITH A THICKER LEADING EDGE CONTOUR, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
03-MAR-2010		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-72-101618	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ACCESSORY GEARBOX OIL TANK OIL FILL INSTRUCTION LABEL SUITABLE FOR USE WITH AN ALUMINUM ACCESSORY GEARBOX MAIN HOUSING, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
30-NOV-2007		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-72-101623	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW LUBRICLONE FOR THE ACCESSORY GEARBOX, SERVICE BULLETIN				RECOMMENDED		COMPLIED WITH - AT MANUFACTURE
19-SEP-2007		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-72-101663	NO. 2 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY AND LOW PRESSURE (LP) COMPRESSOR/INTERNAL GEARBOX OIL DISTRIBUTION TUBES - INTRODUCTION OF REVISED OIL JET HOUSINGS, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
19-FEB-2010		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-72-101664 R02	NO. 2 ENGINE - ENGINE - INTERNAL GEARBOX DRIVE-DRIVEN ASSEMBLY - INTRODUCTION OF A NEW NO.2 BEARING SUPPORT HOUSING, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
02-SEP-2010		MOS HRS/MSC ENC		14-OCT-2014 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101669	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF NUTS WITH SILVER COATED THREAD ONLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-JAN-2010		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101699	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - INTRODUCTION OF A NEW LP COMPRESSOR ANNULUS FILLER WITH AN INTEGRAL HOOK DESIGN, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101705	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR ROTOR AND SHAFT DISCS - INTRODUCTION OF A NEW HP COMPRESSOR FRONT ROTOR ASSEMBLY WITH SHANK NUTS HAVING SILVER COATED THREADS ONLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
14-JAN-2011		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101722	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 2 ONWARD NOZZLE GUIDE SEALS - INTRODUCTION OF A DIFFERENT STANDARD HP TURBINE RIM SEAL ASSEMBLY AND HP TURBINE SUPPORT RING ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101728	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF A NEW MOUNTING BRACKET ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101734	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) ACTUATING RINGS AND LEVERS - INTRODUCTION OF CHANGES TO THE HP COMPRESSOR VARIABLE STATOR VANE (VSV) SYSTEM COMPONENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-JAN-2014		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101774	NO. 2 ENGINE - ENGINE - CORE ENGINE FAIRINGS - INTRODUCTION OF A NEW STANDARD OF CORE ENGINE FAIRINGS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101794	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) COMPRESSOR VARIABLE INLET GUIDE VANE (VIGV) RINGS AND SEALS - INTRODUCTION OF NUTS WITH SILVER COATED THREADS ONLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101805 R04	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF A NEW STANDARD OF PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-101813	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE STAGE 1 LINER - INTRODUCTION OF NEW HP TURBINE STAGE 1 LINER SEGMENTS WITH AN INCREASED HONEYCOMB AREA (SUPERSEDED BY SB BR700-72-101971), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101817 R01	NO. 2 ENGINE - ENGINE - ACCESSORY GEARBOX MODULE - RECONFIGURATION OF THE VESPEL COUPLINGS AND THE RETAINING RINGS USED FOR INSTALLATION OF THE FUEL PUMP AND OIL PUMP AS NON-MODULAR PARTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101858	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR ROTOR DISCS - INTRODUCTION OF A HP COMPRESSOR STAGES 7 TO 10 ROTOR DISC ASSEMBLY WITH REVISED LINER COATING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-AUG-2014		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101881	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - INTRODUCTION OF AN ALTERNATIVE PRESSURE RELIEF VALVE (PRV), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101884	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR REAR OUTER CASE - INTRODUCTION OF AN ALTERNATIVE HP COMPRESSOR REAR OUTER CASE ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-MAY-2014		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101887	NO. 2 ENGINE - HIGH PRESSURE (HP) COMPRESSOR MODULE - INTRODUCTION OF INCREASED TIP CLEARANCES FOR THE HP COMPRESSOR STAGES 6 TO 9 STATOR VANES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-101953	NO. 2 ENGINE - HIGH PRESSURE (HP) TURBINE BLADES - INTRODUCTION OF AN INSTRUCTION FOR MATCHED TIP GRINDING OF THE HP TURBINE STAGE 2 BLADES DURING NEW PRODUCTION OF THE ENGINE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
11-MAR-2016		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-72-900062 R02	NO. 2 ENGINE - ENGINE - INSTALLATION CHECK OF THE FASTENERS ON THE ENGINE COMPRESSOR AND COMBUSTION SECTION CORE FAIRINGS NON-MODIFICATION, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900062 R03	NO. 2 ENGINE - ENGINE - INSTALLATION CHECK OF THE FASTENERS ON THE ENGINE COMPRESSOR AND COMBUSTION SECTION CORE FAIRINGS NON-MODIFICATION, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
22-APR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-900062 R04	NO. 2 ENGINE - ENGINE - INSTALLATION CHECK OF THE FASTENERS ON THE ENGINE COMPRESSOR AND COMBUSTION SECTION CORE FAIRINGS NON-MODIFICATION, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
06-MAR-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900229 R01	NO. 2 ENGINE - LP COMPRESSOR INSPECTION OF FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900229 R02	NO. 2 ENGINE - LP COMPRESSOR INSPECTION OF FAN DISC, SERVICE BULLETIN						NOT APPLICABLE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900229 R03	NO. 2 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900229 R04	NO. 2 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN						NOT APPLICABLE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900229 R05	NO. 2 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN						NOT APPLICABLE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900229 R06	NO. 2 ENGINE - LP COMPRESSOR - INSPECTION OF FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
23-FEB-2005		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900229 R06	NO. 2 ENGINE - VISUAL INSPECTION OF THE FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
PART 1		MOS		14-OCT-2014			
23-FEB-2005		HRS/MSC	-	0			
		ENC		0			
SB BR700-72-900229 R06	NO. 2 ENGINE - VISUAL INSPECTION OF THE FAN DISC, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
PART 2		MOS		14-OCT-2014			
23-FEB-2005		HRS/MSC	N/A	0			
		ENC		0			
SB BR700-72-900455 R02	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN					RECOMMENDED	
PART A		MOS		12-DEC-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-900455 R02 PART B	NO. 2 ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN					RECOMMENDED	
	MOS HRS/MSC - ENC			12-DEC-2014 0 0			
SB BR700-72-900455 R03 PART A	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN					RECOMMENDED	
	MOS HRS/MSC - ENC			12-DEC-2014 0 0			
SB BR700-72-900455 R03 PART B	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN					RECOMMENDED	
	MOS HRS/MSC - ENC			12-DEC-2014 0 0			
SB BR700-72-900455 R04 PART A	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - VISUAL INSPECTION OF THE LOW PRESSURE (LP) COMPRESSOR ANNULUS FILLERS, SERVICE BULLETIN					RECOMMENDED	
	MOS HRS/MSC - ENC			12-DEC-2014 0 0			
SB BR700-72-900521 R04	NO. 2 ENGINE - ENGINE - LOW PRESSURE (LP) COMPRESSOR BLADES - EDDY CURRENT INSPECTION OF THE LP COMPRESSOR ANNULUS FILLERS - NON-MODIFICATION, SERVICE BULLETIN					COMPLIED WITH - BR700-72-101699	
	MOS HRS/MSC - ENC						
SB BR700-72-900580 R01	NO. 2 ENGINE - ACCESSORY GEARBOX MODULE - REPLACEMENT OF THE OIL FILLER ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
04-APR-2016	MOS HRS/MSC - ENC						
SB BR700-72-900637	NO. 2 ENGINE - INTERMEDIATE CASE MODULE - INSPECTION OF THE RETENTION BOLTS OF THE NO.2/NO.3 BEARING HOUSINGS TO THE INTERMEDIATE CASE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
15-FEB-2018	MOS HRS/MSC - ENC						
SB BR700-72-900743	NO. 2 ENGINE - BR700-72-900743 - LOW PRESSURE (LP) COMPRESSOR ROTOR DISC - ULTRASONIC INSPECTION OF THE LP COMPRESSOR ROTOR (FAN) DISC - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY ENG S/N
16-JUN-2023	MOS HRS/MSC - ENC			20-JUN-2023			
CHAPTER 73 ENGINE FUEL AND CONTROL							
ASB BR700-73-A101977 R03	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC FIREBOX ASSEMBLY WITH A REVISED PAINT SYSTEM, ALERT SERVICE BULLETIN					COMPLIED WITH - WORK DONE	
10-JUL-2017	MOS HRS/MSC - ENC			12-NOV-2018 823:40 292			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASB BR700-73-A900083	NO. 2 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION, ALERT SERVICE BULLETIN					ALERT	NOT APPLICABLE
09-MAR-2015		MOS HRS/MSC - ENC					
ASB R01 BR700-73-A900083	NO. 2 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN					ALERT	NOT APPLICABLE
22-MAR-2017		MOS HRS/MSC - ENC					
ASB R02 BR700-73-A900083	NO. 2 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN, ALERT SERVICE BULLETIN					ALERT	NOT APPLICABLE
14-DEC-2018		MOS HRS/MSC - ENC					
ASB BR700-73-A900451	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL METERING UNIT (FMU) - COMBINED OVERSPEED SHUTOFF SOLENOID (COSS) SCREENING FOR REVERSE WIRED INDEPENDENT OVERSPEED PROTECTION (IOP) COILS, ALERT SERVICE BULLETIN					ALERT	NOT APPLICABLE
		MOS HRS/MSC - ENC		14-OCT-2014 0 0			
SB BR700-73-100148 R02	NO. 2 ENGINE - FUEL AND CONTROL - DRAINS EJECTOR FUEL FILTER - INTRODUCTION OF A FILTER IN THE LINE TO THE FUEL DRAINS EJECTOR PUMP AND RELATED DRESSINGS CHANGES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
06-JUL-1998		MOS HRS/MSC - ENC		14-OCT-2014 0 0			
SB BR700-73-100190	NO. 2 ENGINE - FUEL AND CONTROL - ELECTRONIC ENGINE CONTROL (EEC) - INTRODUCTION OF REVISED HARDWARE STANDARD, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
22-MAR-1997		MOS HRS/MSC - ENC		14-OCT-2014 0 0			
SB BR700-73-100206	NO. 2 ENGINE - ENGINE FUEL AND CONTROL-TUBES AND FITTINGS, AIR-ENGINE FUEL CONTROL SYSTEM (EXTERNAL)-INTRODUCTION OF A REVISED P30 TUBE ASSEMBLY WITH BLEED HOLE IN MOISTURE TRAP, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
11-OCT-1997		MOS HRS/MSC - ENC		14-OCT-2014 0 0			
SB BR700-73-100219	NO. 2 ENGINE - FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF C3.1.1. SOFTWARE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-SEP-1998		MOS HRS/MSC - ENC		14-OCT-2014 0 0			
SB BR700-73-100247	NO. 2 ENGINE - FUEL AND CONTROL - OVERSPEED SPLITTER UNIT - INTRODUCTION OF A NEW UNIT FEATURING AN IMPROVED SAFETY LOCK FEATURE BASED ON RING LOCKED FITTINGS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-FEB-1998		MOS HRS/MSC - ENC		14-OCT-2014 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-100271 R01	NO. 2 ENGINE - FUEL AND CONTROL - TUBES AND FITTINGS - INTRODUCTION OF MODIFIED TUBE ASSEMBLY END FITTINGS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100283 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH - INTRODUCTION OF UNITS INCORPORATING A HERMETICALLY SEALED MICRO-SWITCH, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100352	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - CORE FUEL SYSTEM TUBES AND FITTINGS - INTRODUCTION OF REVISED BOLT LENGTH (CONFIGURATION SCHEME), SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100357	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF AN REVISED MOTIVE FUEL FILTER TUBE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
29-APR-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100363	NO. 2 ENGINE - FUEL AND CONTROL - FUEL METERING UNIT (FMU) - INTRODUCTION OF A NEW OPTIMISED FUEL METERING UNIT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-JUL-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100371 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL LOW PRESSURE SWITCH - INTRODUCTION OF UNITS INCORPORATING A HERMETICALLY SEALED MICRO-SWITCH, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100414	NO. 2 ENGINE - FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF C4.0 SOFTWARE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
03-JUL-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100440	NO. 2 ENGINE - FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF SOFTWARE VERSION C5.1.1, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
18-AUG-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100459 R01	NO. 2 ENGINE - FUEL AND CONTROL - FUEL SPRAY NOZZLES - INTRODUCTION OF A FUEL SPRAY NOZZLE ASSEMBLY WITH MODIFIED INTERNAL PARTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-SEP-2005		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-100497	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF DRESSING CHANGES TO SUIT MODIFIED THERMAL ANTI-ICING VALVE AND MUSCLE LINE (NEUTRAL ENGINES), SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
25-SEP-1998		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-73-100596	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROL (EEC) - INTRODUCTION OF IMPROVED EEC FIREBOX HANDLING ACCESS, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
18-JUN-1999		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-73-100689	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - HP FUEL FILTER - INTRODUCTION OF IMPROVED REMOVAL / INSTALLATION FEATURES, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
21-MAY-1999		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-73-100709	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH C5.2.1 SOFTWARE STANDARD, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
21-MAY-1999		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-73-100732	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF AN AIR FEED RESTRICTOR TO THE CONFIGURATION DATABASE AND THE ENGINE DOCUMENTATION, SERVICE BULLETIN			INFORMATIONAL		COMPLIED WITH - AT MANUFACTURE	
18-JUN-1999		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-73-100827 R01	NO. 2 ENGINE - FUEL FLOW TRANSMITTER - INTRODUCTION OF A NEW UNIT WITH A MORE ACCURATE CALIBRATION, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
		MOS HRS/MSC ENC	A/R	14-OCT-2014 0 0			
SB BR700-73-100835 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - DATA ENTRY PLUG - INTRODUCTION OF A RE-TRIMMED DATA ENTRY PLUG TO INCREASE THE PERMITTED STATOR OUTLET TEMPERATURE, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
10-APR-2001		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-73-100927 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH 05 OR 05R HARDWARE STANDARD, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
21-MAY-2000		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-73-100938	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ELECTRONIC ENGINE CONTROLLER (EEC) - INTRODUCTION OF SOFTWARE C5.2.3. INTO AN EEC WITH 04 STANDARD HARDWARE, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
20-OCT-1999		MOS HRS/MSC ENC		14-OCT-2014 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-100964 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL MANIFOLD - INSTALLATION OF A DAMPER WIRE BETWEEN THE LEFT HAND (LH) AND RIGHT HAND (RH) FUEL MANIFOLD, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-OCT-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-100970	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - INTRODUCTION OF NEW FITTING INSTRUCTIONS FOR ACCESSORY GEARBOX MOUNTED ACCESSORIES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
24-JAN-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101085 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL RETURN TO TANK VALVE - INTRODUCTION OF A FUEL RETURN TO TANK VALVE WITH RELATED DRESSING CHANGES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-OCT-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101094	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF A NEW FUEL TUBE WITH INCREASED CLEARANCE TO THE BUFFER AIR TUBE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-AUG-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101106 R01	NO. 2 ENGINE - ENGINE AND FUEL CONTROL - FUEL METERING UNIT - INTRODUCTION OF A NEW FUEL METERING UNIT WITH CHANGES TO THE COMBINED OVERSPEED AND SHUT-OFF SOLENOID, THE PRESSURE RAISING VALVE AND ELECTRO HYDRAULIC SERVO VALVE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-MAR-2001		MOS		14-OCT-2014			
		HRS/MSC	A/R	0			
		ENC		0			
SB BR700-73-101145 R03	NO. 2 ENGINE - ENGINE AND FUEL CONTROL-ENGINE ELECTRIC CONTROLLER-INTRODUCTION OF C6.0 SOFTWARE STANDARD INTO AN EEC WITH 05 OR 05B HARDWARE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	A/R	0			
		ENC		0			
SB BR700-73-101359	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF A FUEL TUBE WITH A NEW ROUTING TO INCREASE THE CLEARANCE BETWEEN THE TUBE AND THE V-BAND CLAMP FOR THE HP STAGE 5 BLEED, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
17-DEC-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101362	NO. 2 ENGINE - ENGINE - FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW EEC HARDWARE STANDARD, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
02-OCT-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101367	NO. 2 ENGINE - INTRODUCTION OF AN EEC WITH A NEW HARDWARE STANDARD (08), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	A/R	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101386	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL MANIFOLD - CHANGE OF SUPPLIER SOURCE FOR THE FUEL MANIFOLD DAMPER WIRE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-JUL-2005		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101396	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL DISTRIBUTION TUBES AND FITTINGS - INTRODUCTION OF NEW PART NUMBERS FOR TWO FUEL TUBE ASSEMBLIES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-MAR-2004		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101415	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - CHANGE OF SUPPLIER SOURCE FOR THE FUEL SYSTEM P20, P30 AND P50 FLEXIBLE AIR TUBES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-MAY-2006		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101429	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - DEDICATED GENERATOR - INTRODUCTION OF A NEW DEDICATED GENERATOR ROTOR WITH REDUCED OUT-OF-BALANCE (OOB) LIMITS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
20-JAN-2004		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101443	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - DATA ENTRY PLUG (DEP) - INTRODUCTION OF A NEW DEP, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-MAY-2006		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101451	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW LOCATION OF THE EEC CONNECT MODULE CAPACITOR, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-JUN-2004		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101472 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF THE NEW EEC SOFTWARE STANDARD C7.0.2, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-NOV-2004		MOS		14-OCT-2014			
		HRS/MSC	A/R	0			
		ENC		0			
SB BR700-73-101477	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - T30 THERMOCOUPLES - INTRODUCTION OF A NEW T30 THERMOCOUPLE PROBE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-APR-2005		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101504	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW STANDARD OF EEC HARDWARE AND SOFTWARE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
19-NOV-2007		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101504 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF A NEW STANDARD OF EEC HARDWARE AND SOFTWARE, SERVICE BULLETIN				OPTIONAL		NOT APPLICABLE
10-JUL-2017		MOS HRS/MSC ENC					
SB BR700-73-101505	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER (FFT) - INTRODUCTION OF A NEW FFT, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
05-SEP-2005		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-73-101509	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH PRINTED CIRCUIT BOARDS FROM A NEW SOURCE, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-73-101558 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER (FFT) - INTRODUCTION OF A NEW FFT WITH IMPROVED ACCURACY LIMITS, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
09-NOV-2007		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-73-101559 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
27-FEB-2012		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-73-101559 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN				OPTIONAL		NOT APPLICABLE
10-JUL-2017		MOS HRS/MSC ENC					
SB BR700-73-101559 R03	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN				OPTIONAL		NOT APPLICABLE
10-MAR-2021		MOS HRS/MSC ENC					
SB BR700-73-101617 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW TRANSMITTER (FFT) - INTRODUCTION OF A FFT WITH A NEW CALIBRATION, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-73-101628 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF AN EEC WITH X1.1 SOFTWARE STANDARD, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC ENC		14-OCT-2014 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101634 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
10-JUL-2017		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-73-101634 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - EXTERNAL FUEL SYSTEM AIR TUBES AND FITTINGS - INTRODUCTION OF EXTERNAL DRESSINGS CHANGES FOR NEW STANDARD OF ENGINE ELECTRONIC CONTROLLER (EEC), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
10-MAR-2021		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-73-101806 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X1.2 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101833 R02	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - FUEL PUMP - INTRODUCTION OF A REVISED DRIVE SHAFT CONNECTION FOR THE FUEL PUMP, SERVICE BULLETIN					CANCELLED	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101856	NO. 2 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - DEDICATED GENERATOR - INTRODUCTION OF A NEW VARNISH FOR THE WINDINGS OF THE PERMANENT MAGNETIC ALTERNATOR (PMA), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAR-2014		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-73-101856 R02	NO. 2 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - DEDICATED GENERATOR - INTRODUCTION OF A NEW VARNISH FOR THE WINDINGS OF THE PERMANENT MAGNETIC ALTERNATOR (PMA), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
24-OCT-2016		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-73-101966 R02	NO. 2 ENGINE - CAMPAIGN SB - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - INTRODUCTION OF X2.0 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD EECU1000-01, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - BR700-73-101966 REV 2 COMPLIED WITH
21-DEC-2016		MOS		28-SEP-2017			
		HRS/MSC	-	485:04			
		ENC		176			
SB BR700-73-900423 R03	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
22-DEC-2016		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-73-900423 R04	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - ENGINE ELECTRONIC CONTROLLER (EEC) - ONE-TIME INSPECTION OF THE EEC FIREBOX ASSEMBLY FOR PAINT DAMAGE - NON-MODIFICATION SERVICE BULLETIN (THIS NON-MODIFICATION SB-BR700-73-9000423 IS NO LONGER VALID AND CAN BE CLOSED), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
25-FEB-2021		MOS					
		HRS/MSC	-				
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB R03	NO. 2 ENGINE - ENGINE FUEL AND CONTROL ENGINE ELECTRONIC CONTROLLER (EEC) - REPLACEMENT OF NON-CONFORMING PARTS OF THE EEC FIREBOX ASSEMBLY - NON-MODIFICATION SERVICE BULLETIN (THIS SB IS NO LONGER VALID AND CAN BE CLOSED), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
28-JAN-2021	MOS HRS/MSC - ENC						
CHAPTER 74 IGNITION							
SB	BR700-74-100199 NO. 2 ENGINE - IGNITION - IGNITION UNIT - HIGH ENERGY - REVISED IGNITER BOX ATTACHING PARTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-FEB-1998	MOS HRS/MSC - ENC			14-OCT-2014 0 0			
SB	BR700-74-100248 NO. 2 ENGINE - IGNITION - IGNITION LEADS - INTRODUCTION OF REVISED CLIPPING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUN-1998	MOS HRS/MSC - ENC			14-OCT-2014 0 0			
SB	BR700-74-100316 NO. 2 ENGINE - IGNITION - IGNITER LEAD - INTRODUCTION OF SILVER PLATING ON CONNECTING NUT THREADS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
28-APR-2000	MOS HRS/MSC - ENC			14-OCT-2014 0 0			
SB	BR700-74-100355 NO. 2 ENGINE - IGNITION - IGNITER PLUG - INTRODUCTION OF A SECOND SOURCE IGNITER PLUG, SERVICE BULLETIN				OPTIONAL		COMPLIED WITH - AT MANUFACTURE
28-APR-1998	MOS HRS/MSC - ENC			14-OCT-2014 0 0			
SB	BR700-74-100550 NO. 2 ENGINE - IGNITION - RIGHT ENGINE IGNITION LEAD ATTACHING FITTINGS - INTRODUCTION OF DRESSING CHANGES TO SUIT MODIFIED THERMAL ANTI-ICING VALVE AND MUSCLE LINE (RIGHT HAND ENGINES), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-SEP-1998	MOS HRS/MSC - ENC			14-OCT-2014 0 0			
SB	BR700-74-100551 NO. 2 ENGINE - IGNITION - LEFT ENGINE IGNITION LEAD ATTACHING FITTINGS - INTRODUCTION OF TWO ADDITIONAL CLIPPING POINTS AND TRANSFER OF A BRACKET TO A LEFT ENGINE SECTION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-SEP-1998	MOS HRS/MSC - ENC			14-OCT-2014 0 0			
SB	BR700-74-101073 R01 NO. 2 ENGINE - IGNITION - IGNITER PLUG - INTRODUCTION OF A STANDARD LENGTH IGNITER PLUG ADAPTOR AND RELATED ADJUSTING WASHERS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-OCT-2001	MOS HRS/MSC - ENC			14-OCT-2014 0 0			
SB	BR700-74-101280 NO. 2 ENGINE - IGNITION - HIGH ENERGY IGNITION UNITS - INTRODUCTION OF A NEW IGNITION UNIT WITH CHANGES TO THE PRINTED CIRCUIT BOARD, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
04-OCT-2001	MOS HRS/MSC - ENC			14-OCT-2014 0 0			
CHAPTER 75 AIR							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-75-100212 R01	NO. 2 ENGINE - AIR - BLEED VALVES - INTRODUCTION OF HIGH PRESSURE COMPRESSOR (HPC) BLEED VALVES WITH STEEL BUSHES, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
11-APR-2003		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-75-100228 R01	NO. 2 ENGINE - AIR - VSV ACTUATOR - INTRODUCTION OF ONE HANDED 'ROSAN' LOCKING FEATURE, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
21-MAY-1999		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-75-100270	NO. 2 ENGINE - AIR - AIR TUBES AND FITTINGS - MINOR CONFIGURATION AMENDMENTS, SERVICE BULLETIN			INFORMATIONAL		COMPLIED WITH - AT MANUFACTURE	
21-MAY-1999		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-75-100297 R01	NO. 2 ENGINE - AIR - VALVE CONTROL AIR BLEED - INTRODUCTION OF REVISED TORQUE TIGHTENING VALUES FOR BLEED VALVE BOLTS, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
12-JUL-2001		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-75-100332 R01	NO. 2 ENGINE - AIR - SOLENOID CONTROL - AIR BLEED - INTRODUCTION OF REVISED BLEED VALVE SOLENOID CONTROL BLOCK MOUNTING BRACKETS AND ASSOCIATED AIR TUBES, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
21-MAY-1999		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-75-100366 R01	NO. 2 ENGINE - AIR - SOLENOID CONTROL - AIR BLEED - INTRODUCTION OF A REVISED BLEED VALVE SOLENOID CONTROL BLOCK, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
15-JUN-1998		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-75-100385 R01	NO. 2 ENGINE - AIR-BLEED VALVES AND SOLENOID CONTROL BLOCK - INTRODUCTION OF AN IMPROVED DESIGN OF BLEED VALVE AND SOLENOID CONTROL BLOCK, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
22-OCT-1999		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-75-100392	NO. 2 ENGINE - AIR - VSV ACTUATOR - INTRODUCTION OF A VARIABLE STATOR VANE ACTUATOR MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN			OPTIONAL		COMPLIED WITH - AT MANUFACTURE	
14-SEP-1998		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-75-100465 R01	NO. 2 ENGINE - AIR - BUFFER AIR VALVE - INTRODUCTION OF A NEW BUFFER AIR VALVE FROM A DIFFERENT SUPPLIER AND WITH IMPROVED CORROSION PROTECTION, SERVICE BULLETIN			RECOMMENDED		COMPLIED WITH - AT MANUFACTURE	
19-JUL-2002		MOS HRS/MSC ENC		14-OCT-2014 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-75-101096	NO. 2 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF TRANSFER TUBES BETWEEN THE BLEED VALVE SOLENOID BLOCK VENT VALVE BODY AND THE SOLENOID CAPS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
12-JUL-2000	MOS HRS/MSC - ENC			14-OCT-2014 0 0			
SB BR700-75-101097	NO. 2 ENGINE - AIR - CORE AIR TUBES AND FITTINGS - INTRODUCTION OF A NEW AIR TUBE WITH A DIFFERENT ROUTING FROM THE BUFFER AIR VALVE TO THE ACCESSORY GEARBOX AND AN ADDITIONAL CLIP POINT CP40402, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
03-FEB-2004	MOS HRS/MSC - ENC			14-OCT-2014 0 0			
SB BR700-75-101130 R01	NO. 2 ENGINE - AIR - BLEED VALVES - INTRODUCTION OF NEW HP 8 HANDLING BLEED VALVE INNER AND OUTER ATTENUATORS TO PREVENT DAMAGE TO BYPASS DUCT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
22-JUN-2001	MOS HRS/MSC A/R ENC			14-OCT-2014 0 0			
SB BR700-75-101161 R01	NO. 2 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK-INTRODUCTION OF HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
07-FEB-2001	MOS HRS/MSC - ENC			14-OCT-2014 0 0			
SB BR700-75-101161 R02	NO. 2 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF A HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
07-OCT-2017	MOS HRS/MSC - ENC						
SB BR700-75-101161 R03	NO. 2 ENGINE - AIR - BLEED VALVE SOLENOID CONTROL BLOCK - INTRODUCTION OF A HANDLING BLEED VALVE SOLENOID WITH SOLENOID SERVO VALVES WHICH OPERATE AT LOWER CURRENT FLOWS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
07-SEP-2018	MOS HRS/MSC - ENC						
SB BR700-75-101207	NO. 2 ENGINE - AIR - AIR TUBES AND FITTINGS - INTRODUCTION OF A P30 AIR TUBE WITH A NEW ROUTING TO INCREASE THE CLEARANCE BETWEEN THE TUBE AND THE FUEL MANIFOLD, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
20-JUN-2002	MOS HRS/MSC - ENC			14-OCT-2014 0 0			
SB BR700-75-101228	NO. 2 ENGINE - AIR - CORE AIR TUBES AND FITTINGS - INTRODUCTION OF NEW HP2/HP4 AIR SYSTEM TUBE ASSEMBLIES WHICH ARE DECREASED IN WEIGHT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-APR-2002	MOS HRS/MSC - ENC			14-OCT-2014 0 0			
SB BR700-75-101381 R01	NO. 2 ENGINE - AIR - BLEED VALVES - INTRODUCTION OF NEW TRIPLE SEALS AND A CARBON BUSH TO REPLACE THE EXISTING STEEL COMPONENTS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
09-OCT-2018	MOS HRS/MSC - ENC						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-75-101447 R02	NO. 2 ENGINE - AIR - VSV ACTUATOR - INTRODUCTION OF A MODIFIED VARIABLE STATOR VANE (VSV) ACTUATOR, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-75-101694	NO. 2 ENGINE - AIR - AIR BLEED CONTROL SOLENOID - INTRODUCTION OF WASHERS WITH A SMALLER OUTER DIAMETER FOR THE INSTALLATION OF THE HANDLING BLEED VALVE SOLENOID CONTROL BLOCK, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-APR-2010		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-75-900633	NO. 2 ENGINE - CAMPAIGN SB - AIR - VSV ACTUATOR - REPLACEMENT OF LUCAS VARIABLE STATOR VANE (VSV) ACTUATORS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
19-JUN-2018		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-75-900633 R01	NO. 2 ENGINE - CAMPAIGN SB - AIR - VSV ACTUATOR - REPLACEMENT OF LUCAS VARIABLE STATOR VANE (VSV) ACTUATORS - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
11-DEC-2018		MOS					
		HRS/MSC	-				
		ENC					
SB BR700-75-900693	NO. 2 ENGINE - CAMPAIGN SB - AIR - VSV ACTUATOR - REPLACEMENT OF VARIABLE STATOR VANE (VSV) ACTUATORS - NON-MODIFICATION SERVICE BULLETIN, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
25-MAR-2021		MOS					
		HRS/MSC	-				
		ENC					
CHAPTER 77 ENGINE INDICATING							
SB BR700-77-100556	NO. 2 ENGINE - ENGINE INDICATING - TURBINE OVERHEAT/OIL FIRE DETECTION THERMOCOUPLE - INTRODUCTION OF STRENGTHENED TERMINALS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
10-NOV-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-77-101105	NO. 2 ENGINE - ENGINE INDICATING - TGT HARNESS - INTRODUCTION OF TORQUE TIGHTENING VALUES FOR THE NUTS WHICH ATTACH THE TURBINE GAS TEMPERATURE (TGT) HARNESS TO THE TGT PROBES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
10-APR-2001		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-77-101534	NO. 2 ENGINE - ENGINE INDICATING - TURBINE GAS TEMPERATURE (TGT) THERMOCOUPLE - INTRODUCTION OF NEW TGT PROBES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-SEP-2006		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-77-101536	NO. 2 ENGINE - ENGINE INDICATING - TURBINE GAS TEMPERATURE (TGT) HARNESS - INTRODUCTION OF A NEW TGT HARNESS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
14-JUL-2006		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-77-101544	NO. 2 ENGINE - ENGINE INDICATING - VIBRATION TRANSDUCER AND CABLE - INTRODUCTION OF A NEW ENGINE VIBRATION MONITORING SYSTEM (EVMS) ACCELEROMETER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
02-NOV-2007		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-77-101553	NO. 2 ENGINE - ENGINE INDICATING - VIBRATION TRANSDUCER AND CABLE - INTRODUCTION OF A NEW ENGINE VIBRATION MONITORING SYSTEM (EVMS) CABLE ASSEMBLY, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
24-MAR-2009		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-77-101875	NO. 2 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INTRODUCTION OF NEW ATTACHING BOLTS WITH SHORTER LENGTH, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
03-JUL-2014		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-77-101875 R02	NO. 2 ENGINE - ENGINE INDICATING - N2 SPEED PROBES - INTRODUCTION OF NEW ATTACHING BOLTS WITH SHORTER LENGTH, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
29-JAN-2019		MOS					
		HRS/MSC	-				
		ENC					
CHAPTER 78 EXHAUST							
SB BR700-78-100165 R01	NO. 2 ENGINE - THRUST REVERSER - LH AND RH ENGINES - INTRODUCTION OF BEARINGS WITH A TEFLON LINER FOR THE LINEAR VARIABLE TRANSDUCER (LVT) ROD ENDS, THE PRIMARY DOOR LOCK AND THE INHIBITION BOLT RECEPTACLE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		27-OCT-2014			
		HRS/MSC	-				
		ENC					
SB BR700-78-100196 R02	NO. 2 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - LH AND RH ENGINES - INTRODUCTION ON THE LH AND RH ENGINE OF SPHERICAL BEARINGS WITH A HIGH TEMPERATURE TEFLON LINER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
22-MAR-2000		MOS		27-OCT-2014			
		HRS/MSC	-				
		ENC					
SB BR700-78-100224 R01	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF A CHANGE OF OWNERSHIP (INSTALLATION RESPONSIBILITY) FOR THE WET DRAINS BRACKETS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		27-OCT-2014			
		HRS/MSC	-				
		ENC					
SB BR700-78-100225	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - REPLACEMENT OF THE FIRE PROTECTION ABLATIVE COATING ON THE THRUST REVERSER FRONT FRAME TORQUE BOX WITH FIRE BLANKETS (HUREL DUBOIS SB 04MOD0077), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
05-JUN-1998		MOS		27-OCT-2014			
		HRS/MSC	-				
		ENC					
SB BR700-78-100236 R01	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF REVISED PIVOT DOOR ACTUATORS AND DYNAMIC SEALS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		27-OCT-2014			
		HRS/MSC	-				
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-78-100252 R01	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF 'NEXTEL' FROM PIVOT DOORS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		27-OCT-2014			
SB BR700-78-100358	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF THE THRUST REVERSER STOW SWITCH ACCESS PANELS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		27-OCT-2014			
SB BR700-78-100359	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF UPPER DOOR HOISTING POINTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
05-MAR-2002		MOS HRS/MSC - ENC		27-OCT-2014			
SB BR700-78-100360	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF THE NEXTEL LAYER ON THE FAN DUCT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		27-OCT-2014			
SB BR700-78-100361	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - DELETION OF THE NEXTEL LAYER ON FRAME 1, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		27-OCT-2014			
SB BR700-78-100389 R01	NO. 2 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) - CHANGE OF THE LINEAR VARIABLE TRANSFORMER (LVT) TO ENSURE IMPROVED PERFORMANCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		27-OCT-2014			
SB BR700-78-100390	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF SIMPLIFIED TORQUE BOX AND LATERAL BEAM JOINT FOR WEIGHT REDUCTION PURPOSES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS HRS/MSC - ENC		27-OCT-2014			
SB BR700-78-100502	NO. 2 ENGINE - EXHAUST - ISOLATION CONTROL UNIT (ICU) - INTRODUCTION OF A NEW ICU WHICH HAVE A RETARDED THRUST REVERSER UNIT (TRU) PRESSURISATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
25-SEP-2008		MOS HRS/MSC - ENC		27-OCT-2014			
SB BR700-78-100593 R01	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - CHANGE OF THRUST REVERSER PIVOT DOOR HONEYCOMB MATERIAL AND INTRODUCTION OF WEIGHT REDUCTION FEATURES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
12-JUL-2000		MOS HRS/MSC - ENC		27-OCT-2014			
SB BR700-78-100599	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF A WEIGHT REDUCED GEARBOX AIR BREATHER PIPE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC - ENC		27-OCT-2014			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-78-100641	NO. 2 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A NEW MATERIAL FOR THE JUNCTION SPLICE BETWEEN THE NOZZLE AND BEAM, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
17-MAY-2001		MOS HRS/MSC ENC		27-OCT-2014			
SB BR700-78-100642 R01	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - IMPROVED ELECTRICAL BONDING OF THE THRUST REVERSER MAIN DOOR, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS HRS/MSC ENC		27-OCT-2014			
SB BR700-78-100783 R05	NO. 2 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - MATERIAL CHANGE OF THE PIVOTING DOOR SEAL DEPRESSOR AND CARRIER SEGMENTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
23-NOV-2009		MOS HRS/MSC ENC		27-OCT-2014			
SB BR700-78-100898	NO. 2 ENGINE - EXHAUST - EXHAUST CONE - INTRODUCTION OF A ONE PIECE EXHAUST CONE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
13-JUL-2001		MOS HRS/MSC ENC		14-OCT-2014 0 0			
SB BR700-78-100935 R01	NO. 2 ENGINE - EXHAUST - TERTIARY LOCK - INTRODUCTION OF TERTIARY LOCKS WITH A BETTER MANUAL RELEASE MECHANISM AND INCREASED SOLENOID FORCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
04-JUL-2002		MOS HRS/MSC ENC		27-OCT-2014			
SB BR700-78-100987 R01	NO. 2 ENGINE - EXHAUST - LEFT AND RIGHT THRUST REVERSER HYDRAULIC TUBES - CHANGES TO THE MAIN-DOOR-ACTUATOR HOSES (THE ACTUATOR HOSES) OF THE THRUST REVERSER UNIT (TRU), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-SEP-2000		MOS HRS/MSC ENC		27-OCT-2014			
SB BR700-78-101009	NO. 2 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER - INTRODUCTION OF NEW SHIMS FOR THE SEAL LANDS ON THE INTERFACE OF THE THRUST REVERSER AND THE UPPER AND LOWER COWL DOOR, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
16-OCT-2000		MOS HRS/MSC ENC		27-OCT-2014			
SB BR700-78-101061 R04	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF THRUST REVERSER FLOW DISCOURAGER SEALS BETWEEN THE PIVOT DOORS AND THE FIXED STRUCTURE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
03-MAY-2001		MOS HRS/MSC ENC		27-OCT-2014			
SB BR700-78-101129 R01	NO. 2 ENGINE - EXHAUST - LEFT AND RIGHT ENGINE THRUST REVERSER FIXED STRUCTURE - REORIENTATION OF THE FASTENERS AT THE THRUST REVERSER FRONT FRAME TO INCREASE THE CLEARANCE TO THE S-HOOK, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
16-OCT-2000		MOS HRS/MSC ENC		27-OCT-2014			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-78-101387	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF STOW SWITCHES MANUFACTURED BY A NEW SUPPLIER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
20-MAR-2003		MOS HRS/MSC - ENC		27-OCT-2014			
SB BR700-78-101442	NO. 2 ENGINE - EXHAUST - EXHAUST NOZZLE - INTRODUCTION OF A NEW EXHAUST NOZZLE ASSEMBLY WITHOUT SPACERS BETWEEN THE FRONT SUPPORT BRACKETS AND THE NOZZLE SKIN, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
29-OCT-2004		MOS HRS/MSC - ENC		14-OCT-2014 0 0			
SB BR700-78-101501	NO. 2 ENGINE - EXHAUST - ISOLATION CONTROL UNIT (ICU) - INTRODUCTION OF AN ISOLATION CONTROL UNIT WITH IMPROVED BONDING RESISTANCE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
28-JUL-2005		MOS HRS/MSC - ENC		27-OCT-2014			
SB BR700-78-101512	NO. 2 ENGINE - EXHAUST - THRUST REVERSER PIVOTING DOORS - INSTRUCTION OF VARIOUS IMPROVEMENTS TO THE THRUST REVERSER PIVOTING DOORS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
27-APR-2006		MOS HRS/MSC - ENC		27-OCT-2014			
SB BR700-78-101514	NO. 2 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A NEW UPPER INHIBITION BOLT FITTING MADE FROM A DIFFERENT MATERIAL, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
27-APR-2006		MOS HRS/MSC - ENC		27-OCT-2014			
SB BR700-78-101515	NO. 2 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A NEW 'Y' STOP FITTING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-JAN-2007		MOS HRS/MSC - ENC		27-OCT-2014			
SB BR700-78-101607 R01	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF A NEW THRUST REVERSER UNIT (TRU), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
15-OCT-2013		MOS HRS/MSC - ENC		27-OCT-2014			
SB BR700-78-101635	NO. 2 ENGINE - EXHAUST - THRUST REVERSER DOOR STOW SWITCH - INTRODUCTION OF A DOOR STOW SWITCH WITH IMPROVED SEALING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
01-AUG-2008		MOS HRS/MSC - ENC		27-OCT-2014			
SB BR700-78-101772	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - INTRODUCTION OF VARIOUS MINOR CHANGES TO THE MANUFACTURING AND ASSEMBLY PROCESS FOR THE THRUST REVERSER UNIT (TRU), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-JUL-2014		MOS HRS/MSC - ENC		27-OCT-2014			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-78-102008 R01	NO. 2 ENGINE - EXHAUST - THRUST REVERSER FIXED STRUCTURE - INTRODUCTION OF A DRAINAGE HOLE WITHIN THE THRUST REVERSER FIXED STRUCTURE TO PREVENT CORROSION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
19-JAN-2018		MOS		27-JUN-2018			
		HRS/MSC	-	631:35			
		ENC		240			
SB BR700-78-900350 R02	NO. 2 ENGINE - EXHAUST - THRUST REVERSER UNIT (TRU) - INSPECTION OF THE SPHERICAL BEARING OF THE PRIMARY DOOR LOCK ACTUATOR (PDLA) AND CLEANING OF THE S-HOOK ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
18-DEC-2018		MOS					
		HRS/MSC	-	(EFF)			
ENC							
SB BR700-78-900474	NO. 2 ENGINE - EXHAUST - THRUST REVERSER - INSPECTION OF FIXED STRUCTURE TORQUE BOX DRAINAGE HOLES, SERVICE BULLETIN					RECOMMENDED	
		MOS					
		HRS/MSC	-				
		ENC		0			
CHAPTER 79 OIL							
SB BR700-79-100118 R01	NO. 2 ENGINE - OIL - COOLER - ENGINE LUBRICATING OIL (AIR COOLED) DELETION OF AIR COOLED OIL COOLER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
29-SEP-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-100221	NO. 2 ENGINE - OIL - OIL TANK AND EXTERNAL OIL TUBES - INTRODUCTION OF A SCUPPER DRAIN TUBE AND A MODIFIED OIL FILLER ASSEMBLY AND THE DELETION OF BLANKING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
19-JUN-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-100294	NO. 2 ENGINE - OIL - FUEL COOLED OIL COOLER - REMOVAL OF LIFE LIMITATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
25-FEB-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-100323 R01	NO. 2 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF A REVISED ANTI-SYPHON OIL TUBE ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
14-MAR-2014		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-100403	NO. 2 ENGINE - OIL - OIL DIFFERENTIAL PRESSURE TRANSDUCER- INTRODUCTION OF A NEW OIL DIFFERENTIAL PRESSURE TRANSDUCER UNIT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-100406 R01	NO. 2 ENGINE - OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH - INTRODUCTION OF A UNIT INCORPORATING A HERMETICALLY SEALED MICRO-SWITCH, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
09-DEC-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-79-100413	NO. 2 ENGINE - OIL - FUEL COOLED OIL COOLER - INTRODUCTION OF A NEW UNIT FEATURING A CAST VERSION OF THE OIL FILTER HOUSING COVER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-JUN-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-100478	NO. 2 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF REVISED CLIPPING POINTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
21-MAY-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-100798 R01	NO. 2 ENGINE - OIL - FUEL COOLED OIL COOLER - INTRODUCTION OF NEW ELECTRICAL BONDING LEAD FITTING INSTRUCTIONS, SERVICE BULLETIN					INFORMATIONAL	COMPLIED WITH - AT MANUFACTURE
22-SEP-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101083	NO. 2 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF A NEW OIL VENT TUBE WITH BETTER SEALING PROPERTIES BETWEEN THE OIL VENT PIPE AND THE ACCESSORY GEARBOX, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
01-DEC-2000		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101188 R01	NO. 2 ENGINE - OIL - OIL DIFFERENTIAL PRESURE SWITCH - INTRODUCTION OF A NEW OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH A THICKER COVER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-JUL-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101287	NO. 2 ENGINE - OIL - OIL PUMPS - INTRODUCTION OF A NEW OIL PUMP WITH A SMALLER SPILL RETURN ORIFICE WHICH INCREASES THE PUMP DISCHARGE OIL FLOW, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-FEB-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101292	NO. 2 ENGINE - OIL - EXTERNAL OIL TUBES AND FITTINGS - INTRODUCTION OF A NEW OIL TUBE BETWEEN THE GEARBOX OIL PUMP AND THE FUEL COOLED OIL COOLER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
08-NOV-2002		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101445	NO. 2 ENGINE - OIL - OIL PUMP - INTRODUCTION OF A NEW STATIC ANTI LEAK VALVE (SALV) INTO THE OIL PUMP UNIT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
16-APR-2004		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101449	NO. 2 ENGINE - OIL - OIL FILTER DIFFERENTIAL PRESSURE SWITCH - INTRODUCTION OF A NEW OIL FILTER DIFFERENTIAL PRESSURE SWITCH WITH A CHANGE TO THE SWITCH SET POINT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
18-MAY-2004		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-79-101458	NO. 2 ENGINE - OIL - PRESSURE FILTER ELEMENT - INTRODUCTION OF A NEW OIL FILTER ELEMENT WITH INCREASED OPTIONAL DIRT HOLDING CAPACITY, SERVICE BULLETIN						COMPLIED WITH - AT MANUFACTURE
17-MAY-2004		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101470	NO. 2 ENGINE - OIL - FUEL COOLED OIL COOLER (FCOC) - INTRODUCTION OF A NEW FRONT SUPPORT BRACKET, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
26-NOV-2005		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101482	NO. 2 ENGINE - OIL - FUEL COOLED OIL COOLER (FCOC) - INTRODUCTION OF A NEW FUEL COOLED OIL COOLER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
07-MAR-2005		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101739	NO. 2 ENGINE - OIL - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW SEALING PLATE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
22-FEB-2011		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101744 R01	NO. 2 ENGINE - OIL - FUEL COOLED OIL COOLER (FCOC) - INTRODUCTION OF A NEW FCOC WITH IMPROVED ICING PROTECTION CAPABILITY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-101803 R01	NO. 2 ENGINE - ENGINE LUBRICATING OIL PUMP UNIT (PRESSURE AND SCAVENGE PUMPS) - INTRODUCTION OF A NEW OIL PUMP UNIT WITH IMPROVED GEARS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
29-AUG-2014		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-900215 R01	NO. 2 ENGINE - OIL - EXCHANGE OF OIL FILTER DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-79-900215 R02	NO. 2 ENGINE - OIL - EXCHANGE OF OIL FILTER DIFFERENTIAL PRESSURE SWITCH, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
CHAPTER 80 STARTING							
SB BR700-80-100077	NO. 2 ENGINE - STARTING - AIR TURBINE STARTER - REPLACEMENT OF OUTPUT SHAFT ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
19-FEB-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-80-100470	NO. 2 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A DUAL-PLANE BALANCED TURBINE WHEEL AND A REVISED METHOD OF MAGNETIC CHIP DETECTOR ATTACHMENT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
29-SEP-1998		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-80-100640	NO. 2 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW STANDARD OF AIR TURBINE STARTER UNIT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
11-MAR-1999		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-80-101018 R03	NO. 2 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
05-SEP-2005		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-80-101729	NO. 2 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH MODIFIED TURBINE THRUST BEARING, SEAL AND RETAINING RING, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			
SB BR700-80-101741	NO. 2 ENGINE - STARTING - AIR TURBINE STARTER - INTRODUCTION OF A NEW AIR TURBINE STARTER WITH MODIFIED OIL FILL PORTS TO IMPROVE THE MAINTENANCE OIL FILL PROCEDURE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		14-OCT-2014			
		HRS/MSC	-	0			
		ENC		0			