

SERVICE REPORT

16 AUG 2026

AURORA / SCHEDULED INSPECTION + WASH

MARINA KOPER / D-17

01

SERVICE OVERVIEW

Visit summary and key findings

Key outcomes from the completed service.



ATTENTION RECOMMENDED

ONE ITEM REQUIRES REVIEW

1

ATTENTION ITEM

36

CHECKS COMPLETED

01

ITEM TO REVIEW

00

URGENT ITEMS

05

PHOTOS RECORDED

ITEM REQUIRING ATTENTION

YELLOW

RECOMMENDED

Port aft mooring line

Light chafe visible where the line bears against the fairlead.

Inspect or replace

before the next departure.

SERVICE NOTES

Scheduled inspection and exterior wash completed. The yacht was left secure and presentation-ready.

No water ingress, shore-power fault or interior security concern was observed.

WEATHER

Partly cloudy / 8 kt NE / 27 C

ARRIVAL POSITION

45.537944, 13.712317

02

CHECKLIST RESULTS

Completed checks and recorded results

Results are grouped by inspection area. Items requiring attention are highlighted for review.

ARRIVAL & ACCESS

- Boat access Accessed normally
- Arrival condition photo Recorded

EXTERIOR & MOORINGS

- Visible mooring lines Port aft line - light chafe
- Fenders and placement
- Covers and securing
- Deck and coachroof

SHORE POWER & BATTERIES

- Shore connection and cable
- Breaker and charger status
- Battery-status indicators Normal

BILGE / LEAKS / HUMIDITY

- Accessible bilges Dry / normal
- Visible water ingress None observed
- Moisture and ventilation

WASH & PRESENTATION

- Fresh-water exterior rinse Completed
- Deck and cockpit wash Completed
- Windows and stainless finish Completed

INTERIOR & DEPARTURE

- Interior condition
- Hatches and doors secure
- Departure photo and final security Recorded

● SATISFACTORY

● ATTENTION

● URGENT

● NOT APPLICABLE

03

PHOTOGRAPHIC RECORD


Photographic evidence and completion

Arrival, departure and relevant service photographs recorded during the visit.

ARRIVAL AND DEPARTURE



SERVICE EVIDENCE



SERVICE NOTES

Exterior wash completed. Yacht left clean, orderly and secure.

Port aft mooring line repositioned; owner review recommended before departure.

COMPLETED BY

Luka Kosem

COMPLETED

16 Aug 2026

DOCUMENT

Report 01 / Client v1