ODC Daily Coaling Plan

20/08/2025

Geologist Contact: 0473 223 132

Discover • Accountable • Respectful • Empowered

THIESS

Coal Locations

Location	Coal Type	Destination	Comments
T02	C_VU1_VU3	SP_C	
T03	C_VU1_VU3	SP_G/SP_N	SP_N (new) for overflow if G fills up
	C_LL1	SP_B	Thin seam – take care when mining Tip Stockpile South to North
	C_LL2T_LL2B		
	C_LL3B	SP_M	Thin seam – take care when mining.
T04	C_LL1	SP_B (west)	Thin seam – take care when mining
	C_LL2T_LL2B	SP_P	
	C_LL3B	SP_Q	
	C_VU1_VU3	SP_O	
T05	C_LL1	SP_B (east)	Thin seam – take care when mining
	C_LL2T_LL2B	SP_D	
	C_LL3B	SP-R	Thin seam – take care when mining
	C_VU1_VU3	SP_A	

All VL1 to go to the VL Pad

THIESS

Ideal Roof and Floor Conditions



THIESS

T03/S01

COAL CODE	STOCKPILE	COMMENTS
C_LL1	SP_B	Thin seam – take care when mining
C_LL2B_LL2T		
C_LL3B	SP_M	Separated to OX Coal
C_VU1_VU3	SP_G/SP_N	SP_N overflow

Morning 19/08

RL95 Mining Feedback:

- Good work in this area, roof and floor clean ups great
- Minor issues with VL1 parting pushed down on coal, and dozer padding out coal to sit on.
- SP-G appears clean on the ROM and initial feed ash results are good.



T03/S01 North Ramp De-stack

COAL CODE	STOCKPILE	COMMENTS
C_LL1	SP_B	Thin seam – take care when mining
C_LL2B_LL2T		
C_LL3B	SP_M	Separated to OX Coal
C_VU1_VU3	SP_G/SP_N	SP_N overflow





T03/S02

COAL CODE	STOCKPILE	COMMENTS
C_LL1	SP_B	Thin seam – take care when mining
C_LL2B_LL2T		
C_LL3B	SP_M	Separated to OX Coal
C_VU1_VU3	SP_G/SP_N	SP_N overflow





T04/S01 Ramp 5 De-Stack

COAL CODE	STOCKPILE	COMMENTS
C_VU1_VU3	SP_O	
C_LL1	SP_B	Thin seam – take care when mining
C_LL2B_LL2T	SP_P	
C_LL3B	SP_Q	



20/08/25

T04/S01

COAL CODE	STOCKPILE	COMMENTS
C_VU1_VU3	SP_O	
C_LL1	SP_B	Thin seam – take care when mining
C_LL2B_LL2T	SP_P	
C_LL3B	SP_M	Keep a gap between existing OX coal please



THIESS

T04/S01

Mine VL1 to VL Pad

COAL CODE	STOCKPILE	COMMENTS
C_VU1_VU3	SP_O	
C_LL1	SP_B	Thin seam – take care when mining
C_LL2B_LL2T	SP_P	
C_LL3B	SP_M	Keep a gap between existing OX coal please



THIESS

T05/S01 Ramp 6 De-Stack

COAL CODE	STOCKPILE	COMMENTS
C_LL1	SP_B	Thin seam – take care when mining
C_LL2T_LL2B	SP_D	
C_LL3B	SP_R	Eastern Side
C_VU1_VU3	SP_A	

T05/S01 Ramp 6 De-Stack

COAL CODE	STOCKPILE	COMMENTS
C_LL1	SP_B	Thin seam – take care when mining
C_LL2T_LL2B	SP_D	
C_LL3B	SP_R	Eastern Side
C_VU1_VU3	SP_A	

VU Southern end

T05/S01 Ramp 6 De-Stack

COAL CODE	STOCKPILE	COMMENTS
C_LL1	SP_B	Thin seam – take care when mining
C_LL2T_LL2B	SP_D	
C_LL3B	SP_R	Eastern Side
C_VU1_VU3	SP_A	

VU Northern end



ROM



THIESS

Tip Stockpiles South to North

ROM



ROM


SP-O VU T04
SP-P LL2 T04
SP-Q LL3 T04
East
SP-B LL1 T05
SP-N VU T03
SP-B LL1 T04
West
These were tipped next to each other, please demarcate and maintain separation between Terraces in future
Tip future T04 LL1 on west
SP-A VU T05
SP-M LL3 T03
N
20/08/25

CHPP Coal Feed Sequence

Communicate any direct feed start and finish time to CHPP control.

Comments

Currently on Blend 2

Once stockpile O exhausted change to Blend 3

Notes:

	Blends							
	Feed 1	Feed 2	Feed 3	Ratio	ROM Loaders	ROM Trucks	Direct Feed	Comments
Blend 1								
Blend 2	SP-O			Straight	1	2	No	VU (T04S01)
Blend 3	SP-G	SP-N		1:1	1	2	No	1 x VU (T03S01) : 1 x VU (T02S01)
Blend 4								
Blend 5	SP-G	SP-O		2:1	1	2	No	2 x VU (T03S01) : 1 x VU (T04S01)
Blend 6								
Wet weather	SP-G			Straight	1	2	No	VU (T03S01)

	Plant Settings											
	Primary DMC	Sec DMC	Reflux	Planned Feed Ash	Gate 401	Coke Stacker	Thermal Stacker	Primary Yield	Secondary Yield	Primary Ash	Primary Moisture	Expected CSN
Blend 1												
Blend 2	1.34				To Primary			63%	15%	10.4%	11.0%	6
Blend 3	1.38				To Primary			63%	15%	10.4%	11.0%	6
Blend 4												
Blend 5	1.4				To Primary			63%	15%	10.4%	11.0%	6
Blend 6												
Wet weather	1.4				To Primary			63%	15%	10.4%	11.0%	6

GEOTECHNICAL HAZARD MAP WITH PREDICTED FAULTS

Olive Downs Complex | Wednesday, August 13, 2025 | THIESS | BlueView

Geotech Hazard ID	Location	TARP Status	Description	Additional Controls
GH23	T5/S1 Low wall	AMBER	Circular Failure, and further low wall failure	• 5m Crest Standoff • 10m Toe Standoff • JSA required prior to work in the area • Inspections as per Amber TARP requirements
GH004	T01/S01-2 Highwall	YELLOW	Highwall Washouts	• No access to YELLOW TARP eastern highwall crest without OCE approval • 10m standoff from Northern end wall crest, with 1.8m high bund • Weekly inspection by OCE
GH015	T03/S01 Low-wall	AMBER	Planar slide and associated slumping on VU roof inT03 low-wall	• Remediation works to stabilise area. JA/JSEA required, • 10m standoff from crest and toe • Daily monitoring during operations in area
GH018	T04/S01 Low-wall	AMBER	Slumping/Planar failure along bedding shears	• 5m Crest Standoff • 10m Toe Standoff • JSA required prior to work in the area • Inspections as per Amber TARP requirements
GH026	T03/S02 Eastern Highwall	AMBER	Wedge failure near Ivan fault	• 10m Crest Standoff • 10m Toe Standoff • JSA required prior to work in the area • Daily Geotech inspection until stabilise • 2.8m bunding within 10m standoff from toe.
GH021	T02/S02 Highwall	Red	Fault Intersection	• 20m Crest Standoff • 35m Exclusion zone from the toe • Inspections as per RED TARP requirements • 3m high risk bunding outside of 35m exclusion zone
GH027	T02/S01 Endwall	Amber	Wedge Failure on Genghis Fault	• 5m Crest Standoff • 10m Toe Standoff • JSA required prior to work in the area • Inspections as per Amber TARP requirements

637,500 638,000 638,500 639,000 639,500 640,000 640,500 641,000 641,500 642,000

7,548,000 7,547,500 7,547,000 7,546,500 7,546,000 7,545,500

N

0 100 200 300 400 500
Metres

Scale @ A3: 1:12,000

Coordinate System: GDA 1994 MGA Zone 55

LEGEND

Red TARP Hazard
Amber TARP Hazard
Yellow TARP Hazard
Unassigned TARP Hazard
SSE Area of Responsibility
Predicted Faults
New Fault
Hannibal
Mugabe
Caesar
Churchill
Cyrus
Ghengis
Kim