



Emnor Mechanical Inc.
20 Depew Street
Hamilton, Ontario
L8L 7H8

REPAIR OF GEAR PUMP

Scope of work was to manufacture new gears, repair the damage to the housing and shafts



Worn Housing



Worn Gear



Sleeves for Bores



Sleeves Welded Into Housing



New Gears Installed



Assembled Pump