



Emnor Mechanical Inc.
20 Depew Street
Hamilton, Ontario
L8L 7H8

REPAIR OF HIDROSTAL SUBMERSIBLE PUMP

Scope of work was to manufacture a new cooling jacket, machine the suction cone and impeller, repair bearing housing bore, recondition the motor and mechanical seals.



Pump as Received



Damaged Cooling Jacket



Damaged Bearing Housing Bore



Damaged Motor



Cone Wear



Completed Repair