




Emnor Mechanical Inc.
20 Depew Street
Hamilton, Ontario
L8L 7H8

Repair 14X14X22 Volute



Worn Volute



Flange Weld



Welded



Finished



Finished with new plate

The above volute was repaired at considerable savings to new. The suction side plate and volute were tungsten carbide coated for extended life in an abrasive application. Please contact Emnor to discuss repair procedures that will save money and increase pump life.