Preliminary smoke testing has been completed, and the City is communicating directly with homeowners where infiltration issues were identified. Additional smoke testing will be conducted once the ground dries out and conditions are suitable for further testing.

