

*issues***INFORMATION BULLETIN No. RTC-038b R8**

**TECHNICAL CONTENT OF THIS DOCUMENT IS APPROVED
UNDER THE AUTHORITY OF THE DOA REF. EASA.21J.057.**

- 1. CONCERNING TO:** All SporStar RTC aircraft.
- 2. REASON:** Issue of Revision 8 of Airplane Maintenance Manual for SportStar RTC, Issue 02, Doc No. ERTC021-10-AS / ERTC022-10-AS.
- 3. REQUIRED ACTIONS:** Operator / owner will download Airplane Maintenance Manual for SportStar RTC, Issue 02, Doc. No. ERTC021-10-AS, Revision 8 / ERTC022-10-AS, Revision No. 8.
- 4. LATEST DAY OF THE ACTION:** Immediately after receiving this bulletin.
- 5. CARRIED OUT BY:** Operator / owner of the aircraft.
- 6. COSTS COVERED BY:** Operator / owner of the aircraft.
- 7. NECESSARY MATERIAL:** Airplane Maintenance Manual for SportStar RTC, Issue 02, Doc. No. ERTC021-10-AS, Revision 8 / ERTC022-10-AS, Revision No. 8.
- 8. WORK PROCEDURE:**

Replace the existing Airplane Maintenance Manual with the new Maintenance Manual for SportStar RTC, Issue 02, Doc. No. ERTC021-10-AS, Revision 8 / ERTC022-10-AS, Revision No. 8, which is available at <https://www.evektor.com/documentation/sportstar-rtc>, under the "Aircraft documents" section.

If the operator / owner maintains the Maintenance Manual in printed form, they shall replace the obsolete pages of the manual with the new (revised) pages and record the date and signature into the Record of Revisions.
- 9. APPENDICES:** None.

Valid from: 18. 09. 2026