Phone: +1-912-298-1294
Fax: 1-912-963-0265/1-800-944-1775
Analyst: Gregory Hart

Status Detail Report

Report Created On: 28 Jul 2025

Gulfstream Aerospace Corporation
G200-MSG3
N597RB

S/N: 068
Regulation: PART 91.409(F)(3)
Airworthiness Date: 01 Aug 2002

Airframe & Component Times					Total Time	
Logbook	Position	Description	Serial No.	Log Date	Hours	Cycles
Airframe		GULFSTREAM AEROSPACE CORPORATION G200-MSG3	068	07 Jul 2025	6400.3	4214
Engine	1	PRATT & WHITNEY CANADA CORP. PW306A	PCE-CC0358	07 Jul 2025	3181.7	1977
Engine	2	PRATT & WHITNEY CANADA CORP. PW306A	PCE-CC-0279	07 Jul 2025	2816.3	1790
APU		HONEYWELL GTCP36-150(IAI)	P-103	07 Jul 2025	3235	1673

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
Logbook Position	Part Number	Serial Number									
	HW	SW									
	MM Ref										
	Ops Number(s)										
00 - General											
000000U	Medeco Key Code		HRS								0
	8M56943	8M56943	AFL								0
			MOS		2.3			19 May 2025			
Airframe			MSC				O/C				
000001U	Paint Scheme and Codes		HRS								0
			AFL								0
			DATE				0d**				
Airframe											
Notes: See dropdown for documents											
000002U	Interior Refurbish Documents (Burn Certs)		HRS								0
			AFL								0
			DATE				0d**				
Airframe											
Notes: See dropdown for documents											
01 - Watch List											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
010010	Service Center Maintenance Induction Checklist	HRS		1179.9			5220.4			0
		AFL		732			3482			0
		MOS		58.2			23 Sep 2020			
Airframe		MSC				O/C				
05 - Time Limits/Maintenance Checks										
055039	Alternator Fail Indication (Left Engine)	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
055040	Alternator Fail Indication (Right Engine)	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
055101	Lightning Strike - Inspection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
055102	Hard or Overweight Landing - Inspection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
055103	High Energy Stop on Landing or Takeoff - Inspection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
055104	Bird Strike - Inspection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
055105	Severe Turbulence / Maneuver - Inspection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
055106	Exceeding Design Speed - Inspection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
055107	High Velocity Ground Gusts - Inspection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
055108	Hail Damage to Aircraft / Engine - Inspection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
055109	APU FIRE - Inspection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
055110	AIR Brakes Extended In Flight AT High Speed - Inspection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
055111	Residual Anti-Icing / De-Icing Fluid - Inspection / Cleaning	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
055112	Engine FIRE Extinguisher Discharge - Follow-Up Requirements	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				

07 - Lifting and Shoring

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
070004 Airframe	Aircraft Jacking Procedure	HRS AFL MOS MSC		1179.9 732 57.9		 O/C	5220.4 3482 30 Sep 2020			0 0
11 - Placards and Markings										
110010 Airframe	Inspection Placards	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		30.4 19 2.1		 12	6369.9 4195 26 May 2025	31 May 2026	30 Jun 2026	0 0
111111 Airframe	Exterior Strip and Paint	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
12 - Servicing										
121001 Airframe	Defueling	HRS AFL MOS MSC		1363.9 834 71.3		 O/C	5036.4 3380 20 Aug 2019			0 0
121002 Airframe	Fuel System - Draining	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
121501 Airframe	Hydraulic Power System - Servicing	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
121502 Airframe	Brake and Thrust Reverser Accumulator - Charging	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
121503 Airframe	Landing Gear Emergency Extension Bottle - Charging	HRS AFL MOS MSC		1179.9 732 55.5		 O/C	5220.4 3482 13 Dec 2020			0 0
121602 APU	APU - APU Oil - Drain and Discard	HRS APUS MOS		119 160 11.9		750 24	3116 1513 30 Jul 2024	3866 31 Jul 2026	3916 31 Aug 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
121701 Airframe	Engine Oil - Servicing	HRS AFL MOS MSC		296.2 192 19.4		 O/C	6104.1 4022 16 Dec 2023			0 0
122203 Airframe	Flap Ballscrew Actuators (Left) - Lubrication (Post Sb 200-05-280)	HRS AFL MOS		343.7 211 21.7		500 36	6056.6 4003 05 Oct 2023	6556.6 31 Oct 2026	6606.6 30 Nov 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
122204 Airframe	Flap Ballscrew Actuators (Right) - Lubrication (Post Sb 200-05-280)	HRS AFL MOS		343.7 211 21.7		500 36	6056.6 4003 05 Oct 2023	6556.6 31 Oct 2026	6606.6 30 Nov 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
122205 Airframe	Flap Roller Bearings (Left) - Lubrication (Post Sb 200-05-280)	HRS AFL MOS		1179.9 732 58.1		1500 72	5220.4 3482 25 Sep 2020	6720.4 30 Sep 2026	6770.4 31 Oct 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
122206 Airframe	Flap Roller Bearings (Right) - Lubrication (Post Sb 200-05-280)	HRS AFL MOS		1179.9 732 58.1		1500 72	5220.4 3482 25 Sep 2020	6720.4 30 Sep 2026	6770.4 31 Oct 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
122213 Airframe	Slat Ballscrew Actuators (Left) - Lubrication (Post Sb 200-05-280)	HRS AFL MOS		343.7 211 21.7		500 36	6056.6 4003 05 Oct 2023	6556.6 31 Oct 2026	6606.6 30 Nov 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
122214 Airframe	Slat Ballscrew Actuators (Right) - Lubrication (Post Sb 200-05-280)	HRS AFL MOS		343.7 211 21.7		500 36	6056.6 4003 05 Oct 2023	6556.6 31 Oct 2026	6606.6 30 Nov 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
122215 Airframe	Slat Roller Bearings (Left) - Lubrication (Post Sb 200-05-280)	HRS AFL MOS		343.7 211 21.7	 -27	1500 72	6056.6 4003 05 Oct 2023	7556.6 30 Sep 2029*	7606.6 31 Oct 2029	0 0
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
122216 Airframe	Slat Roller Bearings (Right) - Lubrication (Post Sb 200-05-280)	HRS AFL MOS		343.7 211 21.7	 -27	1500 72	6056.6 4003 05 Oct 2023	7556.6 30 Sep 2029*	7606.6 31 Oct 2029	0 0
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
122223 Airframe	Main Landing Gear Assembly (Left) - Lubrication (Post Sb 200-05-280)	HRS AFL MOS		343.7 211 21.7		500 36	6056.6 4003 05 Oct 2023	6556.6 31 Oct 2026	6606.6 30 Nov 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
122224 Airframe	Main Landing Gear Assembly (Right) - Lubrication (Post Sb 200-05-280)	HRS AFL MOS		343.7 211 21.7		500 36	6056.6 4003 05 Oct 2023	6556.6 31 Oct 2026	6606.6 30 Nov 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
122226 Airframe	Nose Landing Gear Assembly - Lubrication (Post Sb 200-05-280)	HRS AFL MOS		343.7 211 21.7		500 36	6056.6 4003 05 Oct 2023	6556.6 31 Oct 2026	6606.6 30 Nov 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
122251	Emergency Exit - Lubrication (Post Sb 200-05-280)	HRS		177			6223.3			0
		AFL		113			4101			0
		MOS		11.9		24	30 Jul 2024	31 Jul 2026	31 Aug 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
122253	APU Inlet Door Hinge - Lubrication	HRS		30.4			6369.9			0
		AFL		19			4195			0
		MOS		2.1		12	26 May 2025	31 May 2026	30 Jun 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: REF TO 19.94 FOR OP CHECK										
20 - Standard Practices - Airframe										
200093	Post Maintenance - Servicing	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
21 - AIR Conditioning										
210023	Shut-Off Valves - Operational Test (Cmr**)	HRS		117.2			6283.1			0
		AFL		71			4143			0
		MOS		5.6			10 Feb 2025			
Airframe		MSC				N/A				
Notes: REACTIVATED AND FREQ REMOVED. NO FREQ REQ"D FOR MSG3 AIRCRAFT GRH 17 NOV 10										
210025	Bleed AIR Flow - Low-Pressure Check	HRS		6061.3			339			0
		AFL		4043			171			0
		MOS		258			27 Jan 2004			
Airframe		MSC				O/C				
210035	Precooler Bypass Valve - Operational Test	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		265.1			25 Jun 2003			
Airframe		MSC				O/C				
210036	Temperature Control System - Functional Test	HRS		1477.9			4922.4			0
		AFL		896			3318			0
		MOS		80			29 Nov 2018			
Airframe		MSC				O/C				

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
210037 Airframe	Duct Leakage Test During Engine Run-Up	HRS AFL MOS MSC		1477.9 896 80		 O/C	4922.4 3318 29 Nov 2018			0 0
210039 Airframe	Environmental Control System - Operational Test	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
211007 Airframe	L/H Duct Leakage Test During Engine Run-Up	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
211008 Airframe	R/H Duct Leakage Test During Engine Run-Up	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
211020 Airframe	Turbine Bypass Valve - Removal / Installation PN NOT INSTALLED	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
211030 Airframe	APU Check Valve - Removal / Installation PN NOT INSTALLED	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
211101 Airframe	Temperature Sensor - Removal / Installation 129852-1 251	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
211102 Airframe	Trim AIR Valve (Left) - Removal / Installation 3291292-1 253	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
211103	Trim AIR Valve (Right) - Removal / Installation		HRS		6400.3			0			0
	3291292-1	256	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
211110	Switch, Duct Temp Limit (Left)		HRS		6400.3			0			0
	PN	NOT INSTALLED	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
211111	Switch, Duct Temp Limit (Right)		HRS		6400.3			0			0
	PN	NOT INSTALLED	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
211115	Switch, Duct Temp Limit (Aft)		HRS		6400.3			0			0
	PN	NOT INSTALLED	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
211121	APU Shut-Off Valve - Removal / Installation		HRS		6400.3			0			0
	109812-12	3578	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
Notes: REPLACED APU CODE 495201											
211141	Low Pressure Bleed AIR Check Valve (Left) - Detailed Inspection		HRS		1179.9		2000	5220.4	7220.4	7270.4	0
			AFL		732			3482			0
			MOS		58.1			24 Sep 2020			
			[HRS: +50/-50]								
Airframe											
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.											
211142	Low Pressure Bleed AIR Check Valve (Right) - Detailed Inspection		HRS		1179.9		2000	5220.4	7220.4	7270.4	0
			AFL		732			3482			0
			MOS		58.1			24 Sep 2020			
			[HRS: +50/-50]								
Airframe											
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
211171	Bleed AIR Overtemperature Switch (Forward) - Functional Check	HRS AFL MOS		1477.9 896 80.8		5000	4922.4 3318 02 Nov 2018	9922.4	9972.4	0 0
	[HRS: +50/-50]									
Airframe										
211172	Bleed AIR Overtemperature Switch (Aft) - Functional Check	HRS AFL MOS		1477.9 896 80.8		5000	4922.4 3318 02 Nov 2018	9922.4	9972.4	0 0
	[HRS: +50/-50]									
Airframe										
211181	Bleed AIR Overpressure Switch - Functional Check	HRS AFL MOS		1477.9 896 80.8		5000	4922.4 3318 02 Nov 2018	9922.4	9972.4	0 0
	[HRS: +50/-50]									
Airframe										
211202	Emergency Bleed AIR Valve and Emergency Ram AIR Shut-Off Valve (Post Sb 200-05-280) - Operational Check	HRS AFL MOS		33.1 21 2.2	 -4	1000 24	6367.2 4193 23 May 2025	7367.2 31 May 2027*	7417.2 30 Jun 2027	0 0
	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									
Airframe										
211203	Ram AIR Check Valve - Detailed Inspection	HRS AFL MOS		1477.9 896 80.7		5000	4922.4 3318 05 Nov 2018	9922.4	9972.4	0 0
	[HRS: +50/-50]									
Airframe										
211403	Emergency Ram AIR Shut-Off Valve - Removal / Installation PN NOT INSTALLED	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
212002	Pressure Relief Shut-Off Valve Indication - Operational Check	HRS AFL MOS		1179.9 732 55.6		2000	5220.4 3482 10 Dec 2020	7220.4	7270.4	0 0
	[HRS: +50/-50]									
Airframe										

Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
213002 Airframe	Emergency AIR Shut-Off Valve - Removal / Installation 327955-5 079	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
213003 Airframe	Regulator, Service Pressure - Removal / Installation 3215650-1 154	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
213004 Airframe	Precooler Bypass Valve - Removal / Installation 3291250-1 249	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
213006 Airframe	High Pressure Prsov (Left) - Removal / Installation MAP932-001A VS685	HRS AFL MOS MSC		3222.2 2168 174		O/C	3178.1 2046 27 Jan 2011			0 0 GULFSTREAM DALLAS
213007 Airframe	High Pressure Prsov (Right) - Removal / Installation MAP932-001 VW482	HRS AFL MOS MSC		4515.3 3136 209.2		O/C	1885 1078 23 Feb 2008			0 0 GULFSTREAM DALLAS
213008 Airframe	Outflow Valve - Removal / Installation 4222206-1001 00179	HRS AFL MOS MSC	TSN:41 TSN:15 TSN:10	6359.3 4199 266		O/C	41 15 28 May 2003			0 0
213009 Airframe	Precooler Bypass Valve Filter - Removal / Installation PN NOT INSTALLED	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
213010 Airframe	Cabin / Baggage Compartment - Leakage Test	HRS AFL MOS MSC		6300.3 4168 263.1		O/C	100 46 26 Aug 2003			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
213022	Ram AIR Check Valve - Removal / Installation 4AS7810018-007 1101	HRS AFL MOS MSC	TSN:4922.4 TSN:3318 TSN:195	1477.9 896 80.7		 O/C	4922.4 3318 05 Nov 2018			0 0
Airframe										
213023	Emergency AIR Supply Drain Line - Operational Check	HRS AFL MOS		177 113 11.9		 24	6223.3 4101 30 Jul 2024	 31 Jul 2026	 31 Aug 2026	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m]									
Notes: SB 200-21-312 is complied with.										
213050	Discrete Eicas Display Outputs - Interface Test (Aircraft Post Sb 200-05-280) (Cmr**)	HRS AFL MOS		445.3 275 24.7		1000	5955 3939 05 Jul 2023	6955	7005	0 0
Airframe	[HRS: +50/-50]									
Notes: DPS 450 C/N 567911 CAL DUE: 03/2020MANUAL BARFIELD C/N 563526 CAL DUE: 09/2019										
213051	Manual Pressurization Control System - Operational Check	HRS AFL MOS		177 113 11.9		2500 24	6223.3 4101 30 Jul 2024	8723.3 31 Jul 2026	8773.3 31 Aug 2026	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									
213052	Safety Valve - Functional Check (Aircraft Post Sb 200-05-280) (Cmr*)	HRS AFL MOS		2378.1 1547 144.2		2500 	4022.2 2667 22 Jul 2013	6522.2 	6572.2 	0 0
Airframe	[HRS: +50/-50]									
213053	Baggage Compartment Pressure Relief Valve - Functional Check	HRS AFL MOS		157.9 100 9.8		 24	6242.4 4114 03 Oct 2024	 31 Oct 2026	 30 Nov 2026	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m]									
213054	Smoke Isolation Valve - Operational Check	HRS AFL MOS		177 113 11.9		2000 24	6223.3 4101 30 Jul 2024	8223.3 31 Jul 2026	8273.3 31 Aug 2026	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
213055	Ram Function - Operational Check	HRS		157.9			6242.4			0
		AFL		100			4114			0
		MOS		9.8		24	03 Oct 2024	31 Oct 2026	30 Nov 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
213056	Cabin Altitude High Warning - Functional Test	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
		MSC				O/C				
Airframe										
213101	Pressure Regulating Shut-Off Valve (Left) - Removal / Installation	HRS		6400.3			0			0
		AFL		4214			0			0
	3215644-1 259	MOS		275.9			01 Aug 2002			GULFSTREAM
		MSC				O/C				DALLAS
Airframe										
213102	Pressure Regulating Shut-Off Valve (Right) - Removal / Installation	HRS		6400.3			0			0
		AFL		4214			0			0
	3215644-1 261	MOS		275.9			01 Aug 2002			GULFSTREAM
		MSC				O/C				DALLAS
Airframe										
213103	Pack Pressure Regulating Shut-Off Valve - Removal / Installation	HRS		6400.3			0			0
		AFL		4214			0			0
	3215646-1 177	MOS		275.9			01 Aug 2002			HONEYWELL
		MSC				O/C				ENGINES SYSTEMS & SERVICE
Airframe										
213104	Pressure Regulator Shut-Off Valves High / Low Setting - Operational Test	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
		MSC				O/C				
Airframe										
213105	Pressure Regulating Shut-Off Valve AIR Filter Element - Removal / Installation	HRS		6400.3			0			0
		AFL		4214			0			0
	PN SN-UNKNOWN	MOS		275.9			01 Aug 2002			
		MSC				O/C				
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
213106	Pack Pressure Regulating Shut-Off Valve AIR Filter Element - Removal / Installation		HRS		6400.3			0			0
	PN	SN-UNKNOWN	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
213301	Cabin Pressure Controller - Removal / Installation		HRS		2378.1			4022.2			0
	2119922-8	65-G0007	AFL		1547			2667			0
			MOS		144.2			22 Jul 2013			GULFSTREAM
			MSC				O/C				DALLAS
Airframe											
213302	Aneroid Switch - Functional Check (Cmr**)		HRS		2674.9			3725.4			0
			AFL		1776			2438			0
			MOS		156.3			18 Jul 2012			
Airframe											
Notes: PN: 2119922-6 / 4AS7810052-00 SN: <NONE>.											
213305	Cabin Pressurization System In Manual and Automatic MODE - Operational Check		HRS		2378.1			4022.2			0
			AFL		1547			2667			0
			MOS		144.2			22 Jul 2013			
Airframe											
213309	Safety Valve - Removal / Installation		HRS		4417.5			1982.8			0
	103842-3	54-B0024	AFL		3074			1140			0
			MOS		206.6			08 May 2008			HONEYWELL
			MSC				O/C				
Airframe											
213310	Safety Valve - Functional Check		HRS		6400.3			0			0
	PN	SN-UNKNOWN	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
214201	Foot Warmer Valve - Removal / Installation		HRS		6400.3			0			0
	329045	76	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
215002 Airframe	Refrigeration Unit - Removal / Installation 2215160-1 167	HRS AFL MOS MSC		2845.8 1897 162.5		 O/C	3554.5 2317 11 Jan 2012			0 0
215501 Airframe	Precooler - Removal / Installation 2341170-1 158	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
215502 Airframe	Emergency Heat Exchanger - Removal / Installation 8221-1 T0070	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
216101 Airframe	Temperature Controller - Removal / Installation 1151930-2-2SER2 1151930-00261	HRS AFL MOS MSC		3222.2 2168 174		 O/C	3178.1 2046 28 Jan 2011			0 0
216105 Airframe	Temperature Selector - Removal / Installation 4AS8450001 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
216501 Airframe	Overtemperature Switch (No. 1) - Removal / Installation 641180-1 128	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
216502 Airframe	Overtemperature Switch (No. 2) - Removal / Installation 641180-1 131	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
217002 Airframe	Ozone Converter - Functional Check	HRS AFL MOS		1477.9 896 80		2500 	4922.4 3318 29 Nov 2018	7422.4		0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
217101 Airframe	Ozone Converter - Removal / Installation 43261001 6015	HRS AFL MOS MSC		1179.9 732 56.3		 O/C	5220.4 3482 18 Nov 2020			0 0
217201 Airframe	Defog Valve - Removal / Installation 327985 69	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
22 - Auto Flight										
220001 Airframe	Autopilot - Aileron Servo Motor Actuator (Roll) - Visual Inspection	HRS AFL MOS MSC		6400.3 4214 265.1		 O/C	0 0 25 Jun 2003			0 0
220002 Airframe	Autopilot - Elevator Servo Motor Actuator (Pitch) - Visual Inspection	HRS AFL MOS MSC		6400.3 4214 265.1		 O/C	0 0 25 Jun 2003			0 0
220003 Airframe	Autopilot - Rudder Servo Motor (Yaw Damper) - Visual Check	HRS AFL MOS MSC		6400.3 4214 265.1		 O/C	0 0 25 Jun 2003			0 0
221000 Airframe	Autopilot Aileron Servo Mount (SMT-85B) - Removal / Installation 622-5029-102 J4PF	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
221001 Airframe	Autopilot Elevator Servo Mount (SMT-85B) - Removal / Installation 622-5029-102 YYGB	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
221002	Autopilot Rudder Servo Mount (SMT-85C) - Removal / Installation 622-6718-102 J3HL	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
221005	Autopilot Rudder Servo Motor Cables Tension - Detailed Inspection	HRS AFL MOS [HRS: +50/-50]		296.2 192 19.8	38.9	500	6104.1 4022 04 Dec 2023	6643*	6693	0 0
Airframe										
221006	Autopilot Aileron Servo Motor (Svo-85B) - Removal / Installation 622-5027-102 1KT9G	HRS AFL MOS MSC		445.3 275 25.9		 O/C	5955 3939 30 May 2023			0 0
Airframe										
221007	Autopilot Elevator Servo Motor (Svo-85B) and Mount (SMT-85B) - Removal / Installation 622-5027-102 2X98L	HRS AFL MOS MSC		445.3 275 25.9		 O/C	5955 3939 30 May 2023			0 0
Airframe										
221008	Autopilot Rudder Servo Motor (Svo-85C) and Mount (SMT -85C) - Removal / Installation 622-6717-104 15NG	HRS AFL MOS MSC		445.3 275 25.9		 O/C	5955 3939 30 May 2023			0 0
Airframe										
221013	Aileron Primary Servo Actuator (Svo-85B) - Lubrication	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		445.3 275 26.1		 48	5955 3939 25 May 2023	31 May 2027	30 Jun 2027	0 0
Airframe										
221014	Elevator Primary Servo Actuator (Svo-85B) - Lubrication	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		445.3 275 26.1		 48	5955 3939 25 May 2023	31 May 2027	30 Jun 2027	0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
221015	Rudder Primary Servo Actuator (Svo-85C) - Lubrication	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.1		48	25 May 2023	31 May 2027	30 Jun 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
221016	Autopilot Servo Test (Aileron) - Adjustment Test	HRS		1361.7			5038.6			0
		AFL		832			3382			0
		MOS		68.8			03 Nov 2019			
Airframe		MSC				O/C				
221017	Autopilot Servo Test (Rudder) - Adjustment Test	HRS		1361.7			5038.6			0
		AFL		832			3382			0
		MOS		68.8			03 Nov 2019			
Airframe		MSC				O/C				
221018	Autopilot Servo Test (Elevator) - Adjustment Test	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		69.6			09 Oct 2019			
Airframe		MSC				O/C				
221025	Autopilot Rudder Servo Motor Cables - Removal / Installation (Aircraft 105 Thru Aircraft 999 and Aircraft 004 Thru Aircraft 104 Post Sb 200-22-249)	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
	PN NOT INSTALLED	MSC				O/C				
Airframe										
224001	Flight Control Computer (FCC-4005) No. 1 - Removal / Installation	HRS		2306			4094.3			0
		AFL		1488			2726			0
	822-0807-129 2HRPK	MOS		139.3			19 Dec 2013			ROCKWELL COLLINS
		MSC				O/C				
Airframe										
Notes: FAULT YAW SERVO AMPLIFIER										
224002	Flight Control Computer (FCC-4005) No. 2 - Removal / Installation	HRS		2306			4094.3			0
		AFL		1488			2726			0
	822-0807-129 288CP	MOS		139.3			19 Dec 2013			ROCKWELL COLLINS
		MSC				O/C				
Airframe										
Notes: FAULT YAW SERVO AMPLIFIER										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
224003	Flight Control Panel (Fcp-4004) - Removal / Installation 822-0385-002 34LKN	HRS AFL MOS MSC		157.9 100 9.8		 O/C	6242.4 4114 03 Oct 2024			0 0
Airframe										
224005	Fcp Left Wiring Harness and Ground Points - General Visual Inspection	HRS AFL MOS MSC		445.3 275 26.1		 O/C	5955 3939 24 May 2023			0 0
Airframe										
224006	Fcp Right Wiring Harness and Ground Points - General Visual Inspection	HRS AFL MOS MSC		445.3 275 26.1		 O/C	5955 3939 24 May 2023			0 0
Airframe										
224010	Autopilot and Flight Director - Functional Test	HRS AFL MOS MSC		2306 1488 139.3		 O/C	4094.3 2726 19 Dec 2013			0 0
Airframe										
Notes: AUTOPILOT AND FLIGHT DIRECTOR- FUNCTIONAL TEST C/W. NO DEFECTS NOTED. TEST PERFORMED BY COSGROVE AIRCRAFT SERVICES FAA REPAIR STATION 25CR671Y W/O# T3482 DATED 12/19/13.										
23 - Communications										
230002	ELT - Battery Condition	HRS AFL MOS MSC		6400.3 4214 265.1		 O/C	0 0 25 Jun 2003			0 0
Airframe										
Notes: REV 3 MAY 2003										
230025	Entertainment Components - Inspection	HRS AFL MOS	177 113 11.9		-2.9	1000	6223.3 4101 30 Jul 2024	7220.4*	7245.4	0 0
Airframe		[HRS: +25/-25]								
Notes: STC ICA GA22801A068 REV A - NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
231001	Radio Tuning Unit (Rtu) No. 1 - Removal / Installation 872-0730-234	228XT	HRS AFL MOS MSC		3992 2766 195		O/C	2408.3 1448 29 Apr 2009			0 0 ROCKWELL COLLINS
Airframe											
231002	Radio Tuning Unit (Rtu) No. 2 - Removal / Installation 822-0730-234	H9DT	HRS AFL MOS MSC		3992 2766 195		O/C	2408.3 1448 29 Apr 2009			0 0 ROCKWELL COLLINS
Airframe											
231007	Tray, Artu 724868-802	SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0 TELEDYNE CONTROLS
Airframe											
231010	Antenna, Magnastar 902131-1	01227	HRS AFL MOS MSC	TSN:5036.4 TSN:3380 TSN:205	1363.9 834 70.9		O/C	5036.4 3380 01 Sep 2019			0 0 N/A
Airframe											
Notes: GA DOC# 30-3200008, REV IR DATED 7/19/05											
231101	VHF Comm 1 Wiring Harness and Ground Points - Detailed Inspection		HRS AFL MOS		1363.9 834 71.2	-21	96	5036.4 3380 21 Aug 2019	31 Jul 2027*	31 Aug 2027	0 0
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: COMPLIED WITH CMP G200 231101 VHF COMM 1 WIRING HARNESS AND GROUND POINTS - DETAILED INSPECTION											
231102	VHF Comm 2 Wiring Harness and Ground Points - Detailed Inspection		HRS AFL MOS		1363.9 834 71.2	-21	96	5036.4 3380 21 Aug 2019	31 Jul 2027*	31 Aug 2027	0 0
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: COMPLIED WITH CMP G200 231102 VHF COMM 2 WIRING HARNESS AND GROUND POINTS - DETAILED INSPECTION											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
231110	Radio Tuning Unit - Test	HRS		3992			2408.3			0
		AFL		2766			1448			0
		MOS		195			29 Apr 2009			
		MSC				O/C				
Airframe										
231201	Transceiver, VHF No. 1 - Removal / Installation 822-1116-021 7DJ	HRS		254.5			6145.8			0
		AFL		166			4048			0
		MOS		14.7			07 May 2024			
		MSC				O/C				
Airframe										
231202	Transceiver, VHF No. 2 - Removal / Installation 822-1115-021 (VHF-422D) 13XTH	HRS		3032.5			3367.8			0
		AFL		2033			2181			0
		MOS		169.2			22 Jun 2011			
		MSC				O/C				
Airframe										
Notes: CORRECT P/N 822-1116-021										
231204	VHF Comm No. 1 Antenna - Removal / Installation 21-38-8 8148	HRS	TSN:5036.4	1363.9			5036.4			0
		AFL	TSN:3380	834			3380			0
		MOS	TSN:204	70.9			30 Aug 2019			N/A
		MSC				O/C				
Airframe										
231205	VHF Comm No. 2 Antenna - Removal / Installation 21-38-8 50388	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS	TSN:11	70.6			08 Sep 2019			N/A
		MSC				O/C				
Airframe										
231207	VHF Comm No. 3 Antenna - Removal / Installation 21-38-8 8155	HRS	TSN:5036.4	1363.9			5036.4			0
		AFL	TSN:3380	834			3380			0
		MOS	TSN:204	70.9			30 Aug 2019			N/A
		MSC				O/C				
Airframe										
Notes: DLRO - 561063, 11/20.										
231210	VHF Comm 1 and Comm 2 Systems - Operational Test	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		68.8			02 Nov 2019			
		MSC				O/C				
Airframe										
231212	VHF Transceiver Emergency Tune - Functional Check	HRS		177			6223.3			0
		AFL		113			4101			0
		MOS		11.9		24	30 Jul 2024	31 Jul 2026	31 Aug 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
231301 Airframe	Control Unit, HF No. 1 - Removal / Installation 064-1016-03 12574	HRS AFL MOS MSC		805.6 488 35.1		O/C	5594.7 3726 25 Aug 2022			0 0
231302 Airframe	Coupler, HF No. 1 Antenna - Removal / Installation 064-1017-02 P10337	HRS AFL MOS MSC		3023.6 2026 168.3		O/C	3376.7 2188 19 Jul 2011			0 0 DEUTSCH ENGINEERED CONNECTING DEVICES
231303 Airframe	Capacitor, HF No. 1 External - Removal / Installation 071-1270-01 2417	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
231304 Airframe	Receiver / Exciter, HF No. 1 - Removal / Installation 064-1015-01(KTR-953) 26165	HRS AFL MOS MSC		4771.6 3307 218.4		O/C	1628.7 907 17 May 2007			0 0
231305 Airframe	Control Unit, HF No. 2 - Removal / Installation 064-1016-03 11734	HRS AFL MOS MSC	TSN:5594.7 TSN:3726	805.6 488 35.1		O/C	5594.7 3726 25 Aug 2022			0 0
231308 Airframe	Receiver / Exciter, HF No. 2 - Removal / Installation 064-1015-01 28530	HRS AFL MOS MSC		4553.8 3161 210		O/C	1846.5 1053 27 Jan 2008			0 0 GULFSTREAM DALLAS
231309 Airframe	Amplifier, HF Bridging No. 1 071-0019-0000 3340	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
231310 Airframe	Amplifier, HF Bridging No. 2 071-0019-0000 4000	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
231311 Airframe	Khf 950 HF Communication System - Functional Test	HRS AFL MOS MSC		3023.6 2026 168.3		O/C	3376.7 2188 19 Jul 2011			0 0
231409 Airframe	Handset Power Controller, Cabin 744802 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
231503 Airframe	Dual Iridium Filter (Aircell Axxess SATCOM) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
231504 Airframe	Aircell Ctr Cabin Router (Aircell) - Removal / Installation P12083-001 1208371043	HRS AFL MOS MSC		3023.6 2026 168.5		O/C	3376.7 2188 13 Jul 2011			0 0 Aircell
231505 Airframe	Axxess Handset Interface (Aircell Axxess SATCOM) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
231506 Airframe	Axxess Configuration Module (Aircell) - Removal / Installation P14126 1412610846	HRS AFL MOS MSC		3023.6 2026 168.5		O/C	3376.7 2188 13 Jul 2011			0 0 Aircell

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs
	Part Number	Serial Number									Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
231507	Atg 4000 Transciever (Aircell) - Removal / Installation		HRS		2128.6			4271.7			0
	P13989	1398914016	AFL		1354			2860			0
		L	MOS		130.4			17 Sep 2014			Aircell
			MSC				O/C				
Airframe											
Notes: NO LED"S OR FAN RUNNING. NO WIFI OR IRIDIUM PHONE.											
231508	Atg Mounting Tray (Aircell) - Removal / Installation		HRS		6400.3			0			0
	P14291	SN-UNKNOWN	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			Aircell
			MSC				O/C				
Airframe											
231509	Atg Antenna, Lower Forward (Aircell) - Removal / Installation		HRS	TSN:520.2	1363.9			5036.4			0
			AFL	TSN:346	834			3380			0
	P12949	479369	MOS	TSN:49	71.1			25 Aug 2019			N/A
			MSC				O/C				
Airframe											
Notes: G200 DOC# GA24203A001 REV DREF: 19.64.17 FOR OPERATIONAL CHECKREF: 19.64.18 FOR SEALANT CURE											
231510	Atg Antenna, Lower Aft (Aircell) - Removal / Installation		HRS		1363.9			5036.4			0
	P12949	355100	AFL		834			3380			0
			MOS		70.9			31 Aug 2019			N/A
			MSC				O/C				
Airframe											
Notes: G200 DOC# GA24203A001 REV DREF: 19.64.17 FOR OPERATIONAL CHECKREF: 19.64.22 FOR SEALANT CURE											
231511	High Speed Data Antenna (Aircell Axxess SATCOM) - Removal / Installation		HRS		6400.3			0			0
			AFL		4214			0			0
	PN	SN-UNKNOWN	MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
231512	Antenna (Aircell Axxess SATCOM) - Removal / Installation		HRS		6400.3			0			0
	PN	SN-UNKNOWN	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
231513	Diu (Aircell Axxess SATCOM) - Removal / Installation		HRS		6400.3			0			0
	PN	SN-UNKNOWN	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
231514	Alerter Aca-Ii (Aircell Axxess SATCOM) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										
231515	Ipod Docking Switch Panel (Aircell Axxess SATCOM) - Removal Installation PN SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										
231516	Ipod Docking Station (Aircell Axxess SATCOM) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										
231517	Fan (Aircell Axxess SATCOM) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										
231518	Atg 5000 Transceiver (Aircell) - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										
231521	Antenna (Aircell Axxess SATCOM) - Inspection / Check	HRS AFL MOS [HRS: +50/-50]		33.1 21 2.2	-20.7	1000	6367.2 4193 23 May 2025	7346.5*	7396.5	0 0
Airframe										
231522	Dual Iridium Filter (Aircell Axxess SATCOM) - Inspection / Check	HRS AFL MOS [HRS: +50/-50]		33.1 21 2.2	-20.7	1000	6367.2 4193 23 May 2025	7346.5*	7396.5	0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
231523 Logbook Position	Transceiver (Aircell Axxess SATCOM) - Inspection / Check	HRS AFL MOS [HRS: +50/-50]		33.1 21 2.2	-20.7	1000	6367.2 4193 23 May 2025	7346.5*	7396.5	0 0
Airframe										
231524	Data Interface Unit (Aircell Axxess SATCOM) - Inspection / Check	HRS AFL MOS [HRS: +50/-50]		33.1 21 2.2	-20.7	1000	6367.2 4193 23 May 2025	7346.5*	7396.5	0 0
Airframe										
231525	Cabin Telecommunications Router (Aircell Axxess SATCOM) - Inspection / Check	HRS AFL MOS [HRS: +50/-50]		33.1 21 2.2	-20.7	1000	6367.2 4193 23 May 2025	7346.5*	7396.5	0 0
Airframe										
231526	Aircell Axxess Ii Airborne SATCOM - Structural Support Installations - Inspection / Check	HRS AFL MOS [HRS: +50/-50]		3023.6 2026 168.3		3500	3376.7 2188 19 Jul 2011	6876.7	6926.7	0 0
Airframe										
231527	Dual Patch Antenna Connector Holes (Aircell Axxess SATCOM) - Eddy Current Inspection	HRS AFL MOS		2143.4 1363 131.7		4710	4256.9 2851 07 Aug 2014	7561		0 0
Airframe										
231528	Dual Patch Antenna Fastener Holes (Aircell Axxess SATCOM) - Eddy Current Inspection	HRS AFL MOS		2143.4 1363 131.7		2950	4256.9 2851 07 Aug 2014	5801		0 0
Airframe										
231529	Atg Transceiver (Aircell Axxess SATCOM) - Inspection / Check	HRS AFL MOS [HRS: +50/-50]		33.1 21 2.2	-20.7	1000	6367.2 4193 23 May 2025	7346.5*	7396.5	0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
231530 Airframe	Atg Configuration Module (Aircell Axxess SATCOM) - Inspection / Check	HRS AFL MOS [HRS: +50/-50]		33.1 21 2.2	-20.7	1000	6367.2 4193 23 May 2025	7346.5*	7396.5	0 0
231533 Airframe	Aircell Ctr Tray - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
231534 Airframe	Aircell Fwd Adapter - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
231535 Airframe	Aircell Aft Adapter - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
231568 Airframe	Antenna, Xm Satellite Radio CI420-1 337114	HRS AFL MOS MSC		1363.9 834 70.5		 O/C	5036.4 3380 13 Sep 2019			0 0 N/A
Notes: G200 DOC# GA24607A000 REV B AND DWG# CEB11250001 REV. AREF. ITEM 6.14 FOR OPERATIONAL CHECK.										
231569U Airframe	Xm Satellite Antenna Fastener Holes - Eddy Curr FS 203	HRS AFL MOS		2143.4 1363 131.7		 3450 	4256.9 2851 07 Aug 2014	 6301 		0 0
Notes: PN: CI420-1 SN: <NONE>.										
231591U Airframe	Atg-4000 - Dual Patch Antenna (FS 243.46) Connector Holes Eddy Current Inspection	HRS AFL MOS		 2026 		 4083 	 2188 	 6271 		0 0
Notes: Installed at 2188 FC, next due 6271 FC. Rev attached ICA for inspection requirements										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
231592[U]	Atg - 4000 Dual Patch Antenna (FS 243.46) Fastener Holes Eddy Current Inspection	HRS AFL MOS		2026		3550	2188	5738		0 0
Airframe										
Notes: Installed at 2188 FC, next due 5738 FC. Rev attached ICA for inspection requirements										
232201	Decoder, Selcal - Removal / Installation 1200006-008 1439	HRS AFL MOS MSC	TSN:28 TSN:9 TSN:4	6372.3 4205 271.5		O/C	28 9 11 Dec 2002			0 0 ISRAEL AIRCRAFT INDUSTRIES
Airframe										
232203	Selective Calling (Coltech Csd-10 Selcal) System - Operational Test	HRS AFL MOS MSC		6372.3 4205 268.8		O/C	28 9 04 Mar 2003			0 0
Airframe										
233003	Chime, Passenger Address 990-1254-163 02050004689	HRS AFL MOS MSC		6372.3 4205 269.2		O/C	28 9 21 Feb 2003			0 0
Airframe										
233101	Vga-2 Splitter 990-5700-002 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0 Baker
Airframe										
233102	Rosen View Panel 0603-001 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0 Rosen
Airframe										
233201	Flight Compartment Audio Control Panel, Pilot - Removal / Installation B1045F546GWR7MOD11 02030002361	HRS AFL MOS MSC		817.9 494 35.5		O/C	5582.4 3720 11 Aug 2022			0 0
Airframe										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
233202	Flight Compartment Audio Control Panel, Copilot - Removal / Installation		HRS AFL MOS MSC	817.9 494 35.5			O/C	5582.4 3720 11 Aug 2022			0 0
	990-3333-300	2020001851									
Airframe											
233210	Audio Control System, Flight Compartment - Functional Test		HRS AFL MOS MSC	5271 3631 237.5			O/C	1129.3 583 13 Oct 2005			0 0
Airframe											
233301	Microphone, AREA (Gray)		HRS AFL MOS MSC	6400.3 4214 275.9			O/C	0 0 01 Aug 2002			0 0 AVIALL
	16301-01	1168									
Airframe											
233401	AMP, Speaker No. 1		HRS AFL MOS MSC	6372.3 4205 270.1			O/C	28 9 25 Jan 2003			0 0
	102013-1	950802									
Airframe											
233402	AMP, Speaker No. 2		HRS AFL MOS MSC	6372.3 4205 270.1			O/C	28 9 25 Jan 2003			0 0
	102030-1	940802									
Airframe											
233422	Monitor, Aft		HRS AFL MOS MSC	6372.3 4205 269			O/C	28 9 27 Feb 2003			0 0 ROSEN AVIATION DISPLAYS, LLC
	1402-007	02077G005									
Airframe											
233425	Processor, Video System		HRS AFL MOS MSC	6372.3 4205 269.5			O/C	28 9 13 Feb 2003			0 0 GULFSTREAM DALLAS
	3070-00-00	253									
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
233426	DVD Player 1050030-1	210902	HRS AFL MOS MSC		6400.3 4214 265.1		 O/C	0 0 25 Jun 2003			0 0 MID CONTINENT CONTROLS INC.
Airframe											
233429	Video Cassette Recorder (Vcr) 105029-1	110902	HRS AFL MOS MSC	TSN:10 TSN:5 TSN:1	6362.3 4200 267.3		 O/C	38 14 20 Apr 2003			0 0
Airframe											
233431	CD Controller CRA-1667	NSN	HRS AFL MOS MSC		6372.3 4205 268.6		 O/C	28 9 10 Mar 2003			0 0
Airframe											
233432	Changer, CD CHA-1214	NSN	HRS AFL MOS MSC		6372.3 4205 268.5		 O/C	28 9 13 Mar 2003			0 0
Airframe											
233436	AMP, Audio Distribution 102006-1	670802	HRS AFL MOS MSC	TSN:13 TSN:6 TSN:4	6359.3 4199 266.3		 O/C	41 15 20 May 2003			0 0 NORDAM GROUP MANUFACTURING DIVISION
Airframe											
233437	AMP, Audio Distribution 102008-1	2230802	HRS AFL MOS MSC		6372.3 4205 268.8		 O/C	28 9 02 Mar 2003			0 0 DPI LABS INC
Airframe											
233438	AMP, Audio Distribution 103006-1	1210102	HRS AFL MOS MSC		6372.3 4205 270.1		 O/C	28 9 25 Jan 2003			0 0 SCANDVIK, INC.
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
233440	Box, Relay 106019-1	480802	HRS AFL MOS MSC	6372.3 4205 270.1			O/C	28 9 25 Jan 2003			0 0
Airframe											
233442	Infrared (Ir) Translator 106023-1	420802	HRS AFL MOS MSC	6372.3 4205 270			O/C	28 9 28 Jan 2003			0 0
Airframe											
233443	Infrared (Ir) Device 30703	190	HRS AFL MOS MSC	6372.3 4205 268.3			O/C	28 9 20 Mar 2003			0 0
Airframe											
233458	Preamp, Audio 990-3393-001	02010000231	HRS AFL MOS MSC	6372.3 4205 270			O/C	28 9 28 Jan 2003			0 0
Airframe											
233460	Speaker DT-A8GA-MTP	02032072	HRS AFL MOS MSC	6372.3 4205 270			O/C	28 9 29 Jan 2003			0 0
Airframe											
233461	Speaker DT-A8GA-MTP	02032069	HRS AFL MOS MSC	6372.3 4205 270			O/C	28 9 29 Jan 2003			0 0
Airframe											
233462	Speaker DT-A8GA-MTP	02032073	HRS AFL MOS MSC	6372.3 4205 270			O/C	28 9 29 Jan 2003			0 0
Airframe											
233463	Speaker DT-A8GA-MTP	02032072	HRS AFL MOS MSC	6372.3 4205 270			O/C	28 9 29 Jan 2003			0 0
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
233464	Speaker DT-A8GA-MTP	02032070	HRS AFL MOS MSC		6372.3 4205 270		 O/C	28 9 29 Jan 2003			0 0
Airframe											
233465	Speaker DT-A8GA-MTP	02032070	HRS AFL MOS MSC		6372.3 4205 270		 O/C	28 9 29 Jan 2003			0 0
Airframe											
233466	Speaker DT-A8GA-MTP	02032071	HRS AFL MOS MSC		6372.3 4205 270		 O/C	28 9 29 Jan 2003			0 0
Airframe											
233467	Speaker DT-A8GA-MTP	02032071	HRS AFL MOS MSC		6372.3 4205 270		 O/C	28 9 29 Jan 2003			0 0
Airframe											
233475	Sub-Woofer DT-AUFW-1G-PT2	02091303	HRS AFL MOS MSC		6372.3 4205 269.3		 O/C	28 9 18 Feb 2003			0 0
Airframe											
233476	Sub-Woofer DT-AUFW-1G-PT2	02091302	HRS AFL MOS MSC		6372.3 4205 269.3		 O/C	28 9 18 Feb 2003			0 0
Airframe											
233502	Monitor, Aft 1402-007	02087G018	HRS AFL MOS MSC		6372.3 4205 269.1		 O/C	28 9 24 Feb 2003			0 0 ROSEN AVIATION DISPLAYS, LLC
Airframe											
233521	Panel, Entertainment Audio Control (No. 1) 101513-1	1320302	HRS AFL MOS MSC		6372.3 4205 270		 O/C	28 9 29 Jan 2003			0 0 GULFSTREAM DALLAS
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
233522 Airframe	Panel, Entertainment Audio Control (No. 2) 101514-1 1320802	HRS AFL MOS MSC		6372.3 4205 270		O/C	28 9 29 Jan 2003			0 0 GULFSTREAM DALLAS
233523 Airframe	Panel, Entertainment Audio Control (No. 3) 101530-1 450802	HRS AFL MOS MSC	TSN:13 TSN:6 TSN:4	6359.3 4199 266.3		O/C	41 15 20 May 2003			0 0 GULFSTREAM DALLAS
233524 Airframe	Panel, Entertainment Audio Control (No. 4) 101514-1 1290802	HRS AFL MOS MSC		6372.3 4205 270		O/C	28 9 29 Jan 2003			0 0 GULFSTREAM DALLAS
233525 Airframe	Panel, Entertainment Audio Control (No. 5) 101513-1 1300802	HRS AFL MOS MSC		6372.3 4205 270		O/C	28 9 29 Jan 2003			0 0 GULFSTREAM DALLAS
233526 Airframe	Panel, Entertainment Audio Control (No. 6) 101514-1 1300802	HRS AFL MOS MSC		6372.3 4205 270		O/C	28 9 29 Jan 2003			0 0 GULFSTREAM DALLAS
233527 Airframe	Panel, Entertainment Audio Control (No. 7) 101513-1 1330802	HRS AFL MOS MSC		6372.3 4205 270		O/C	28 9 29 Jan 2003			0 0 GULFSTREAM DALLAS
233535 Airframe	Control, Flight Deck Ttd Airshow 1720-01 372	HRS AFL MOS MSC	TSN:453.9 TSN:235 TSN:15	5918.4 3970 253.8		O/C	481.9 244 04 Jun 2004			0 0 ELECTRO ENTERPRISES INC

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
233536 Airframe	Computer, Airshow (Dcu) 920060 1901	HRS AFL MOS MSC		1695.4 1043 92.8		 O/C	4704.9 3171 03 Nov 2017			0 0
235105 Airframe	Audio Control Panel Emergency Function - Operational Check	HRS AFL MOS		177 113 11.9		 24	6223.3 4101 30 Jul 2024	 31 Jul 2026	 31 Aug 2026	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
235201 Airframe	Briefing Controller 0300-412 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
236026 Airframe	Static Discharge Wick (Vertical Stab Tip CAP) 10-900-49 3168-2	HRS AFL MOS MSC		6359.3 4199 266.3		 O/C	41 15 20 May 2003			0 0 GULFSTREAM DALLAS
236031 Airframe	Static Discharging, Wing (Left) - Resistance Check (Post-Sb 200-05-280)	HRS AFL MOS		296.2 192 19.9	38.9	500	6104.1 4022 01 Dec 2023	6643*	6693	0 0
	[HRS: +50/-50]									
236032 Airframe	Static Discharging, Wing (Right) - Resistance Check (Post -Sb 200-05-280)	HRS AFL MOS		296.2 192 19.9	38.9	500	6104.1 4022 01 Dec 2023	6643*	6693	0 0
	[HRS: +50/-50]									
Notes: MEGGER 560814, 06/2020										
236033 Airframe	Static Discharging, Winglet (Left) - Resistance Check (Post-Sb 200-05-280)	HRS AFL MOS		296.2 192 19.9	38.9	500	6104.1 4022 01 Dec 2023	6643*	6693	0 0
	[HRS: +50/-50]									
Notes: MEGGER 560814, 06/2020										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
236034	Static Discharging, Winglet (Right) - Resistance Check (Post-Sb 200-05-280)	HRS AFL MOS [HRS: +50/-50]		296.2 192 19.9	38.9	500	6104.1 4022 01 Dec 2023	6643*	6693	0 0
Airframe										
Notes: MEGGER 560814, 06/2020										
236035	Static Discharging, Horizontal Stabilizer (Left) - Resistance Check (Post-Sb 200-05-280)	HRS AFL MOS [HRS: +50/-50]		296.2 192 19.8	38.9	500	6104.1 4022 04 Dec 2023	6643*	6693	0 0
Airframe										
Notes: MEGGER 560814, 06/2020										
236036	Static Discharging, Horizontal Stabilizer (Right) - Resistance Check (Post-Sb 200-05-280)	HRS AFL MOS [HRS: +50/-50]		296.2 192 19.7	38.9	500	6104.1 4022 05 Dec 2023	6643*	6693	0 0
Airframe										
Notes: MEGGER 560814, 06/2020										
236037	Static Discharging, Rudder - Resistance Check (Post-Sb 200-05-280)	HRS AFL MOS [HRS: +50/-50]		296.2 192 19.8	38.9	500	6104.1 4022 04 Dec 2023	6643*	6693	0 0
Airframe										
Notes: MEGGER 560814, 06/2020										
236038	Static Discharging, Vertical Stabilizer- Resistance Check (Post-Sb 200-05-280)	HRS AFL MOS [HRS: +50/-50]		296.2 192 19.8	38.9	500	6104.1 4022 04 Dec 2023	6643*	6693	0 0
Airframe										
Notes: MEGGER 560814, 06/2020										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
237101	Cockpit Voice Recorder - Functional Check (Post Sb 200-05-280)	HRS		33.1			6367.2			0
		AFL		21			4193			0
		MOS		2.2		12	23 May 2025	31 May 2026	30 Jun 2026	
		[End Of Month Item] [MOS: +1m/-1m]								
	Airframe									
	Notes: COMPLIED WITH CMP G200 237101 COCKPIT VOICE RECORDER - FUNCTIONAL CHECK (POST SB 200-05-280)BATTERY EXP DATE: APR 2025. MULTIMETER S/N 556106 EXP DATE 09/19									
237200	Cockpit Voice Recorder (Post MOD 7005 or Post MOD 7252) - Removal / Installation 1603-02-03 1051	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
		MSC				O/C				
	Airframe									
237201	Control Unit, Cvr - Removal / Installation 1632-01 250	HRS	TSN:28	6372.3			28			0
		AFL	TSN:9	4205			9			0
		MOS		267.9			30 Mar 2003			
		MSC				O/C				
	Airframe									
237202	Inertial G Switch (Post MOD 7005 or Post MOD 7257) - Removal / Installation 6895D3X4-4 3867	HRS	TSN:28	6372.3			28			0
		AFL	TSN:9	4205			9			0
		MOS	TSN:5	271.4			16 Dec 2002			GULFSTREAM
		MSC				O/C				DALLAS
	Airframe									
237203	Inertial G Switch (Post MOD 7005 or Post MOD 7252) - Functional Check	HRS		6372.3			28			0
		AFL		4205			9			0
		MOS		268.8			04 Mar 2003	30 Nov 2029		
		MSC				DUE				EXPIRATION
	Airframe	[End Of Month Item]								
237208	Cvr Underwater Locator Beacon (Dukane) - Functional Test	HRS		343.7			6056.6			0
		AFL		211			4003			0
		MOS		21.7		24	05 Oct 2023	31 Oct 2025	30 Nov 2025	
		[End Of Month Item] [MOS: +1m/-1m]								
	Airframe									
	Notes: PN: DK 120 SN: SC97542. VOLTAGE 3.321VDC EXPIRATION 08/2023MULTIMETER C/N 320440 CAL DUE: 07/2020									

ATA / U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
237209	Cvr Underwater Locator Beacon - Removal / Installation	HRS		6400.3			0			0
	PN NOT INSTALLED	AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
Notes: The ULB is installed on the CVR located in the aft fuselage service compartment at FS 677.80 (17,217mm) behind access door 310AB.										
237210	Cvr Underwater Locator Beacon Battery - Discard	HRS		33.1			6367.2			0
	DK120/90 AT223947	AFL		21			4193			0
		MOS	TSN:1	2.2		72	23 May 2025	31 May 2032		
Airframe		[End Of Month Item]								EXPIRATION
Notes: The ULB is installed on the CVR located in the aft fuselage service compartment at FS 677.80 (17,217mm) behind access door 310AB.										
237211	Cvr Underwater Locator Beacon - Cleaning	HRS		33.1			6367.2			0
		AFL		21			4193			0
		MOS		2.2		24	23 May 2025	31 May 2027		
Airframe		[End Of Month Item]								
238003	Antenna, SATCOM (Aero-1)	HRS		1363.9			5036.4			0
	S67-1575-165 1325	AFL		834			3380			0
		MOS		70.4			16 Sep 2019			N/A
Airframe		MSC				O/C				
238101[U]	Satellite Transceiver(Aircell)	HRS		3023.6			3376.7			0
	P12023 1202310268	AFL		2026			2188			0
		MOS		168.5			13 Jul 2011			
Airframe		MSC				-				
238103[U]	Mounting Tray(Aircell)	HRS		4935.4			1464.9			0
	P12107 N/A	AFL		3426			788			0
		MOS		223.3			19 Dec 2006			
Airframe		MSC				-				
238104[U]	Dual-Patch Antenna(Aircell)	HRS		4935.4			1464.9			0
	015-11203-001 1325	AFL		3426			788			0
		MOS		223.3			19 Dec 2006			
Airframe		MSC				-				
238105[U]	Call Alerter(Aircell)	HRS		4935.4			1464.9			0
	P12347 1234710023	AFL		3426			788			0
		MOS		223.3			19 Dec 2006			
Airframe		MSC				-				

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
238106U	Ahi-1(Aircell)		HRS		4935.4			1464.9			0
	P12339	1233910035	AFL		3426			788			0
			MOS		223.3			19 Dec 2006			
			MSC				-				
Airframe											
238107U	Ahi-2 #1(Aircell)		HRS		4935.4			1464.9			0
	P12346	1234610026	AFL		3426			788			0
			MOS		223.3			19 Dec 2006			
			MSC				-				
Airframe											
238108U	Ahi-2 #2(Aircell)		HRS		4935.4			1464.9			0
	P12346	1234610049	AFL		3426			788			0
			MOS		223.3			19 Dec 2006			
			MSC				-				
Airframe											
238109U	Handset Cockpit(Aircell)		HRS		4553.8			1846.5			0
	P12793-001	1279310016	AFL		3161			1053			0
			MOS		210			27 Jan 2008			Aircell
Airframe											
238110	Data Loader (Airsat)		HRS		6400.3			0			0
	822-1631-003	SN-UNKNOWN	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
238111U	Handset Cabin #1(Aircell)		HRS		4935.4			1464.9			0
	P12192-002	1219210960	AFL		3426			788			0
			MOS		223.3			19 Dec 2006			
			MSC				-				
Airframe											
238112U	Handset Cabin #2(Aircell)		HRS		4935.4			1464.9			0
	P12192-002	1219210964	AFL		3426			788			0
			MOS		223.3			19 Dec 2006			
			MSC				-				
Airframe											

24 - Electrical Power

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
240001	Generator Control Unit (Left) - Removal / Installation 51525-001C Y3114	HRS AFL MOS MSC	TSN:1278.1 TSN:683 TSN:44	5122.2 3542 231.1		 O/C	1278.1 672 26 Apr 2006			0 0 GOODRICH CORPORATION
Airframe										
240002	Generator Control Unit (Right) - Removal / Installation 51525-001C P1048	HRS AFL MOS MSC		5103.3 3531 230.3		 O/C	1297 683 19 May 2006			0 0 GOODRICH CORPORATION
Airframe										
240003	Generator Control Unit (APU) - Removal / Installation 51525-001C P1395	HRS AFL MOS MSC		445.3 275 24.5		 O/C	5955 3939 11 Jul 2023			0 0
Airframe										
243001	Goodrich Main Starter-Generator (Left) - Removal / Installation 23291-006 Y10009	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
Airframe										
243002	Goodrich Main Starter-Generator (Right) - Removal / Installation 23291-006 Y0020	HRS AFL MOS MSC		496.6 314 27.5		 O/C	5903.7 3900 14 Apr 2023			0 0
Airframe										
243003	See 494401 23091-004 P1056	HRS AFL MOS MSC		4374.2 3045 204.8		 O/C	2026.1 1169 03 Jul 2008			0 0
Airframe										
243008	Load Shedding - Operational Test (Post Sb 200-05-280) (Cmr**)	HRS AFL MOS [HRS: +50/-50]		296.2 192 19.7	38.9	500	6104.1 4022 06 Dec 2023	6643*	6693	0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
243009 Airframe	Goodrich Main Starter-Generator (Left) - Restore 23291-006 Y10009	HRS AFL MOS		496.6 314 27.5		1000	5903.7 3900 14 Apr 2023	6903.7		0 0
243010 Airframe	Goodrich Main Starter-Generator (Right) - Restore 23291-006 Y0020	HRS AFL MOS		496.6 314 27.5		1000	5903.7 3900 14 Apr 2023	6903.7		0 0
Notes: THIS STARTER/GENERATOR IS A ZERO TIME OVERHAULED UNIT.										
243013 Airframe	Main Battery (Left) - Capacity Test (Post Sb 200-05-280)	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]		12.5 8 1.3		500 12	6387.8 4206 20 Jun 2025	6887.8 30 Jun 2026	6937.8 31 Jul 2026	0 0
243014 Airframe	Main Battery (Right) - Capacity Test (Post Sb 200-05-280)	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]		12.5 8 1.3		500 12	6387.8 4206 20 Jun 2025	6887.8 30 Jun 2026	6937.8 31 Jul 2026	0 0
243015 Airframe	Main Battery No. 1 - Removal / Installation 40178-21 X02576	HRS AFL MOS MSC		12.5 8 1.3		O/C	6387.8 4206 20 Jun 2025			0 0
243016 Airframe	Main Battery No. 2 - Removal / Installation 40178-21 S01670	HRS AFL MOS MSC		12.5 8 1.3		O/C	6387.8 4206 20 Jun 2025			0 0
243019 Airframe	Emergency Battery - Removal / Installation 2778-18 P00121	HRS AFL MOS MSC		12.5 8 1.3		O/C	6387.8 4206 20 Jun 2025			0 0
Notes: COMPLIED WITH CMP G200 243019 EMERGENCY BATTERY - REMOVAL / INSTALLATION										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
243020	Emergency Battery - Capacity Test (Cmr**)	HRS		12.5		300	6387.8	6687.8	6737.8	0
		AFL		8			4206			0
		MOS		1.3		6	20 Jun 2025	31 Dec 2025	31 Jan 2026	N/A
Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Notes: PN: 2778-18 SN: P00121.										
243022	Emergency Batteries (Capacity / Deep Cycle) - Functional Check (Post Sb 200-05-280)	HRS		2014.9			4385.4			0
		AFL		1280			2934			0
		MOS		125.7			05 Feb 2015			
		MSC				O/C				
Airframe										
Notes: EMERGENCY BATTERY DEEP CYCLE/CAP TEST C/W. NO DEFECTS NOTED. I/A/W G200 CMP 243020 AND SAFT BATTERY MAINT. MANUAL 24-30-99 PAGE 5007..										
243027	Goodrich Main Starter-Generator Brushes (Left) - Detailed Inspection (Post Sb 200-05-280)	HRS		33.1	36.5	500	6367.2	6903.7*	6953.7	0
		AFL		21			4193			0
		MOS		2.2			23 May 2025			
		[HRS: +50/-50]								
Airframe										
243028	Goodrich Main Starter-Generator Brushes (Right) - Detailed Inspection (Post Sb 200-05-280)	HRS		33.1	36.5	500	6367.2	6903.7*	6953.7	0
		AFL		21			4193			0
		MOS		2.2			23 May 2025			
		[HRS: +50/-50]								
Airframe										
Notes: PN: 23291-006 SN: P1074.										
243029	Contactor and Relay Boxes - Visual Inspection (Post Sb 200-05-280) (Cmr**)	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.1		48	25 May 2023	31 May 2027	30 Jun 2027	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
243060	Engine-Driven Generator / Generator Control Unit - Operational Test	HRS		496.6			5903.7			0
		AFL		314			3900			0
		MOS		27.5			14 Apr 2023			
		MSC				O/C				
Airframe										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer
Logbook Position	HW	SW									Date Type
	MM Ref										
	Ops Number(s)										
244410	Gfci - Operational Check		HRS		177	-2.9	1000	6223.3	7220.4*	7245.4	0
			AFL		113			4101			0
			MOS		11.9			30 Jul 2024			
Airframe			[HRS: +25/-25]								
Notes: STC ICA GA22801A068 REV A - NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.											
245001	Inverter, AC Electrical		HRS		607.5			5792.8			0
	SS200	2054	AFL		382			3832			0
			MOS		30.3			18 Jan 2023			
Airframe			MSC				O/C				
245301	Power Supply		HRS		6372.3			28			0
	30300256	060100285	AFL		4205			9			0
			MOS		269.5			13 Feb 2003			
Airframe			MSC				O/C				
25 - Equipment/Furnishings											
250004	Pilot / Copilot Seat - Cleaning / Painting		HRS		6400.3			0			0
			AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
Airframe			MSC				O/C				
250021	Lavatory Systems - Operational Test		HRS		6400.3			0			0
			AFL		4214			0			0
			MOS		265.1			25 Jun 2003			
Airframe			MSC				O/C				
250101	Water Lines / Drains - Galley Above Floor - Inspection		HRS		445.3		1000	5955	6955	6980	0
			AFL		275			3939			0
			MOS		26.3			19 May 2023			
Airframe			[HRS: +25/-25]								
250102	Water Lines / Drains - Vanity Above Floor - Inspection		HRS		177			6223.3			0
			AFL		113			4101			0
			MOS		11.9		24	30 Jul 2024	31 Jul 2026	31 Aug 2026	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
250103 Logbook Position	Lavatory (Above Floor) - Condition and Security	HRS AFL MOS		445.3 275 25.9		48	5955 3939 31 May 2023	31 May 2027	30 Jun 2027	0 0
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: G200-068 ICA GA22801A068 REV. A.										
250104 Airframe	Water Lines / Connections - Lavatory Above Floor - Insp	HRS AFL MOS [HRS: +25/-25]		177 113 11.9	-2.9	1000	6223.3 4101 30 Jul 2024	7220.4*	7245.4	0 0
Notes: WATER LINES/CONNECTIONS LAVATORY ABOVE FLOOR INSPECTION C/W. NO DEFECTS NOTED. I/A/W GULFSTREAM CABIN INTERIOR STC09851SC GULFSTREAM ICA DOCUMENT GA22801A068 REV.A										
250105 Airframe	Galley - Sink and Water Heater Conn/Drain - Leak Check	HRS AFL MOS [HRS: +25/-25]		177 113 11.9	-2.9	1000	6223.3 4101 30 Jul 2024	7220.4*	7245.4	0 0
Notes: STC ICA GA22801A068 REV A - NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
250106 Airframe	Galley - Sink and Water Heater Conn/Drain - Corr/Discolor	HRS AFL MOS [HRS: +25/-25]		177 113 11.9	-2.9	1000	6223.3 4101 30 Jul 2024	7220.4*	7245.4	0 0
Notes: STC ICA GA22801A068 REV A - NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
250107 Airframe	Galley Water Heater - Overhaul MRX-1000-201A-S 1051-606A-S	HRS AFL MOS		472.2 296 27.1	-19.6	3000	5928.1 3918 24 Apr 2023	8908.5*		0 0
Notes: STC ICA GA22801A068 REV A										
250108 Airframe	Heater, Water (Galley) PN NOT INSTALLED	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0

ATA U=Custom / Logbook Position	Description / Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
250109	Vanity - Sink and Water Heater Conn/Drain - Leak Check	HRS		177	-2.9	1000	6223.3	7220.4*	7245.4	0
		AFL		113			4101			0
		MOS		11.9			30 Jul 2024			
Airframe		[HRS: +25/-25]								
Notes: STC ICA GA22801A068 REV A - NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
250110	Vanity - Sink and Water Heater Conn/Drain - Corr/Discolor	HRS		177	-2.9	1000	6223.3	7220.4*	7245.4	0
		AFL		113			4101			0
		MOS		11.9			30 Jul 2024			
Airframe		[HRS: +25/-25]								
Notes: STC ICA GA22801A068 REV A - NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
250111	Vanity (Lavatory) Water Heater - Overhaul	HRS		472.2		3000	5928.1	8928.1	8953.1	0
	MRX-1000-501A-S 1051-605A-S	AFL		296			3918			0
		MOS		27.1			24 Apr 2023			
Airframe		[HRS: +25/-25]								
Notes: STC ICA GA22801A068 REV A										
250112	Heater, Water (Lavatory)	HRS		6400.3			0			0
	PN NOT INSTALLED	AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
251001	Galley Condition and Security - Inspection	HRS		177	-2.9	1000	6223.3	7220.4*	7245.4	0
		AFL		113			4101			0
		MOS		11.9			30 Jul 2024			
Airframe		[HRS: +25/-25]								
Notes: STC ICA GA22801A068 REV A - NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
251002	Galley Doors / Latches - Operational Test	HRS		177	-2.9	1000	6223.3	7220.4*	7245.4	0
		AFL		113			4101			0
		MOS		11.9			30 Jul 2024			
Airframe		[HRS: +25/-25]								
Notes: STC ICA GA22801A068 REV A - NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
251003	Galley Trash Bin Doors / Latches - Inspection	HRS		177	-2.9	1000	6223.3	7220.4*	7245.4	0
		AFL		113			4101			0
		MOS		11.9			30 Jul 2024			
Airframe		[HRS: +25/-25]								
Notes: GALLEY TRASH BIN DOORS/LATCHES INSPECTION C/W. NO DEFECTS NOTED. I/A/W GULFSTREAM CABIN INTERIOR STC09851SC GULFSTREAM ICA DOCUMENT GA22801A068 REV.A										

ATA U=Custom / Logbook Position	Description / Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
251004	Bulkhead Condition and Security - Inspection	HRS		177	-2.9	1000	6223.3	7220.4*	7245.4	0
		AFL		113			4101			0
		MOS		11.9			30 Jul 2024			
Airframe		[HRS: +25/-25]								
Notes: STC ICA GA22801A068 REV A - NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
251005	Interior Doors for Condition / Security - Inspection	HRS		177	-2.9	1000	6223.3	7220.4*	7245.4	0
		AFL		113			4101			0
		MOS		11.9			30 Jul 2024			
Airframe		[HRS: +25/-25]								
Notes: STC ICA GA22801A068 REV A - NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
251007	Console / Tables Condition and Security - Inspection	HRS		177	-2.9	1000	6223.3	7220.4*	7245.4	0
		AFL		113			4101			0
		MOS		11.9			30 Jul 2024			
Airframe		[HRS: +25/-25]								
Notes: CONSOLE/TABLES CONDITION & SECURITY INSPECTION C/W. NO DEFECTS NOTED. I/A/W GULFSTREAM CABIN INTERIOR STC09851SC GULFSTREAM ICA DOCUMENT GA22801A068 REV.A										
251008	Vanity Condition and Security - Inspection	HRS		177	-2.9	1000	6223.3	7220.4*	7245.4	0
		AFL		113			4101			0
		MOS		11.9			30 Jul 2024			
Airframe		[HRS: +25/-25]								
Notes: VANITY CONDITION AND SECURITY INSPECTION C/W. NO DEFECTS NOTED. I/A/W GULFSTREAM CABIN INTERIOR STC09851SC GULFSTREAM ICA DOCUMENT GA22801A068 REV.A										
251009	Vanity Doors / Latches Condition and Security - Insp	HRS		177	-2.9	1000	6223.3	7220.4*	7245.4	0
		AFL		113			4101			0
		MOS		11.9			30 Jul 2024			
Airframe		[HRS: +25/-25]								
Notes: VANITY DOORS/LATCHES CONDITION & SECURITY INSPECTION C/W. NO DEFECTS NOTED. I/A/W GULFSTREAM CABIN INTERIOR STC09851SC GULFSTREAM ICA DOCUMENT GA22801A068 REV.A										
251010	Vanity Trash Bin Doors / Latches - Inspection	HRS		581		1000	5819.3	6819.3	6844.3	0
		AFL		366			3848			0
		MOS		28.6			10 Mar 2023			
Airframe		[HRS: +25/-25]								
251020	First AID / Medical Kit (No. 1)	HRS		437.6			5962.7			0
	AAMK 063023002	AFL		272			3942			0
		MOS		24.4			15 Jul 2023			
		MSC				O/C				
Airframe										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
251100	Restraint System (Pilot)		HRS		6400.3			0			0
	506001-401-2396	SN-UNKNOWN	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
251101	Restraint System (CO-Pilot)		HRS		6400.3			0			0
	506001-402-2396	SN-UNKNOWN	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
251103	Pilot Seat - Removal / Installation		HRS	TSN:5219.9	1179.9			5220.4			0
	3A243-0007-01-1	38485	AFL	TSN:3482	732			3482			0
			MOS	TSN:218	58.1			24 Sep 2020			
			MSC				O/C				
Airframe											
251104	Copilot Seat - Removal / Installation		HRS	TSN:5219.9	1179.9			5220.4			0
	3A243-0008-01-1	38488	AFL	TSN:3482	732			3482			0
			MOS	TSN:218	58.1			24 Sep 2020			
			MSC				O/C				
Airframe											
251105	Jumpseat		HRS	TSN:4995.4	1363.9			5036.4			0
	403034-1	20308	AFL	TSN:3365	834			3380			0
			MOS	TSN:195	70.3			20 Sep 2019			AVOX SYSTEM, INC.
			MSC				O/C				
Airframe											
Notes: PROCEDURE REFERENCE: STC ST09749SC											
251106	Forward Seat Track (Jumpseat)		HRS		6359.3			41			0
	30-4340003-5	NSN	AFL		4199			15			0
			MOS		265.7			05 Jun 2003			
			MSC				O/C				
Airframe											
251107	Aft Seat Track (Jumpseat)		HRS		6359.3			41			0
	30-4340003-13	NSN	AFL		4199			15			0
			MOS		265.7			05 Jun 2003			
			MSC				O/C				
Airframe											
251108	Jumpseat Placards - Visual Inspection		HRS		296.2		500	6104.1	6604.1	6629.1	0
			AFL		192			4022			0
			MOS		19.8			04 Dec 2023			
Airframe			[HRS: +25/-25]								

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
251109 Airframe	Jumpseat - Inspection / Check	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m] [HRS: +25/-25]		30.4 19 2.1		500 12	6369.9 4195 26 May 2025	6869.9 31 May 2026	6894.9 30 Jun 2026	0 0
251110 Airframe	Jumpseat - Seat Track Condition and Security - Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m] [HRS: +25/-25]		30.4 19 2.1		500 12	6369.9 4195 26 May 2025	6869.9 31 May 2026	6894.9 30 Jun 2026	0 0
251111 Airframe	Crew Seat Inertial Reel (Pilot) - Operational Check	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		177 113 11.9		 24	6223.3 4101 30 Jul 2024	 31 Jul 2026	 31 Aug 2026	0 0
251112 Airframe	Crew Seat Inertial Reel (Copilot) - Operational Check	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		177 113 11.9		 24	6223.3 4101 30 Jul 2024	 31 Jul 2026	 31 Aug 2026	0 0
251113 Airframe	Crew Seat Restraint (Pilot) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		177 113 11.9		 24	6223.3 4101 30 Jul 2024	 31 Jul 2026	 31 Aug 2026	0 0
251114 Airframe	Crew Seat Restraint (Copilot) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		177 113 11.9		 24	6223.3 4101 30 Jul 2024	 31 Jul 2026	 31 Aug 2026	0 0
251115 Airframe	Crew Seat Locking (Pilot) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		445.3 275 26.2		 48	5955 3939 22 May 2023	 31 May 2027	 30 Jun 2027	0 0
251116 Airframe	Crew Seat Locking (Copilot) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		445.3 275 26.2		 48	5955 3939 22 May 2023	 31 May 2027	 30 Jun 2027	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
251310 Airframe	Glareshield - Removal / Installation 4AS3581160-513 NSN	HRS AFL MOS MSC		6359.3 4199 265.7		O/C	41 15 05 Jun 2003			0 0 ISRAEL AIRCRAFT INDUSTRIES
252001 Airframe	Passenger Seats - Detailed Inspection	HRS AFL MOS MSC		6400.3 4214 265.1		O/C	0 0 25 Jun 2003			0 0
252023 Airframe	Shade, Window No. 2 (Left) GALX-113M006-1 3150	HRS AFL MOS MSC		6372.3 4205 271.7		O/C	28 9 05 Dec 2002			0 0
252024 Airframe	Shade, Window No. 2 (Right) GALX-113M006-1 3149	HRS AFL MOS MSC		6372.3 4205 271.7		O/C	28 9 05 Dec 2002			0 0
252025 Airframe	Shade, Window No. 3 (Left) GALX-113M006-1 3146	HRS AFL MOS MSC		6372.3 4205 271.7		O/C	28 9 05 Dec 2002			0 0
252026 Airframe	Shade, Window No. 3 (Right) GALX-113M006-1 3154	HRS AFL MOS MSC		6372.3 4205 271.7		O/C	28 9 05 Dec 2002			0 0
252027 Airframe	Shade, Window No. 4 (Left) GALX-113M006-1 3147	HRS AFL MOS MSC		6372.3 4205 271.7		O/C	28 9 05 Dec 2002			0 0
252028 Airframe	Shade, Window No. 4 (Right) GALX-113M006-1 3153	HRS AFL MOS MSC		6372.3 4205 271.7		O/C	28 9 05 Dec 2002			0 0

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
252029	Shade, Window No. 5 (Left)		HRS		6372.3			28			0
	GALX-113M006-1	3145	AFL		4205			9			0
			MOS		271.7			05 Dec 2002			
			MSC				O/C				
Airframe											
252030	Shade, Window No. 5 (Right)		HRS		6372.3			28			0
	GALX-113M006-1	3148	AFL		4205			9			0
			MOS		271.7			05 Dec 2002			
			MSC				O/C				
Airframe											
252031	Shade, Window No. 6 (Left)		HRS		6372.3			28			0
	GALX-113M006-1	3155	AFL		4205			9			0
			MOS		271.7			05 Dec 2002			
			MSC				O/C				
Airframe											
252032	Shade, Window No. 6 (Right)		HRS		6372.3			28			0
	GALX-113M006-1	3152	AFL		4205			9			0
			MOS		271.7			05 Dec 2002			
			MSC				O/C				
Airframe											
252033	Shade, Window No. 7 (Left)		HRS		6372.3			28			0
	GALX-113M006-1	3151	AFL		4205			9			0
			MOS		271.7			05 Dec 2002			
			MSC				O/C				
Airframe											
252035	Shade, Emergency Window		HRS		6372.3			28			0
	GALX-113M006-1	3144	AFL		4205			9			0
			MOS		271.7			05 Dec 2002			
			MSC				O/C				
Airframe											
252041	Executive Table No. 1 - Removal / Installation		HRS		6372.3			28			0
	20241-2	16111	AFL		4205			9			0
			MOS		268.1			25 Mar 2003			
			MSC				O/C				
Airframe											
252042	Executive Table No. 2 - Removal / Installation		HRS		6372.3			28			0
	54400-26	14730	AFL		4205			9			0
			MOS		268.3			20 Mar 2003			
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
252043	Executive Table No. 3 - Removal / Installation 54400-26 16290	HRS		6372.3			28			0
		AFL		4205			9			0
		MOS		268.3			20 Mar 2003			
Airframe		MSC				O/C				
252091	Passenger Seat Inertial Reels - Operational Check	HRS		177			6223.3			0
		AFL		113			4101			0
		MOS		11.9		24	30 Jul 2024	31 Jul 2026	31 Aug 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
252092	Passenger Seat Restraints - Detailed Inspection	HRS		177			6223.3			0
		AFL		113			4101			0
		MOS		11.9		24	30 Jul 2024	31 Jul 2026	31 Aug 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
252093	Passenger Seats - Detailed Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.2		48	22 May 2023	31 May 2027	30 Jun 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
252100	Executive Seat No. 1 - Removal / Installation 2524.556.01-257C 020913-3	HRS	TSN:5008.4	1363.9			5036.4			0
		AFL	TSN:3371	834			3380			0
		MOS	TSN:198	70.1			26 Sep 2019			N/A
Airframe		MSC				O/C				
252101	Executive Seat No. 2 - Removal / Installation 2524.555.01-257B 020913-2	HRS	TSN:5008.4	1363.9			5036.4			0
		AFL	TSN:3371	834			3380			0
		MOS	TSN:198	70.1			26 Sep 2019			N/A
Airframe		MSC				O/C				
252102	Executive Seat No. 3 - Removal / Installation 252455601-257D 020913-4	HRS	TSN:5008.4	1363.9			5036.4			0
		AFL	TSN:3371	834			3380			0
		MOS	TSN:198	70.1			26 Sep 2019			N/A
Airframe		MSC				O/C				
252103	Executive Seat No. 4 - Removal / Installation 2524.555.01-257A 020912-1	HRS	TSN:5008.4	1363.9			5036.4			0
		AFL	TSN:3371	834			3380			0
		MOS	TSN:198	70.1			26 Sep 2019			N/A
Airframe		MSC				O/C				

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
252104 Airframe	Executive Seat No. 5 - Removal / Installation 403142-5 21263	HRS AFL MOS MSC		1363.9 834 70.1		O/C	5036.4 3380 26 Sep 2019			0 0 N/A
252105 Airframe	Executive Seat No. 6 - Removal / Installation 403142-7A 21264	HRS AFL MOS MSC		1363.9 834 70.1		O/C	5036.4 3380 26 Sep 2019			0 0 N/A
252106 Airframe	Executive Seat No. 7 - Removal / Installation 403142-1 21265	HRS AFL MOS MSC		1363.9 834 70.1		O/C	5036.4 3380 26 Sep 2019			0 0 N/A
252107 Airframe	Executive Seat No. 8 - Removal / Installation 403142-3 21266	HRS AFL MOS MSC	TSN:5008.4 TSN:3371 TSN:198	1363.9 834 70.1		O/C	5036.4 3380 26 Sep 2019			0 0
252112 Airframe	Divan No. 1 - Removal / Installation 26098-2-25-P3 21270	HRS AFL MOS MSC		6372.3 4205 268.3		O/C	28 9 18 Mar 2003			0 0
252113 Airframe	Divan No. 2 - Removal / Installation 260018-2-25-P1 21269	HRS AFL MOS MSC		6372.3 4205 268.3		O/C	28 9 18 Mar 2003			0 0
252114 Airframe	Divan No. 3 - Removal / Installation 261012-12 21271	HRS AFL MOS MSC		6372.3 4205 268.3		O/C	28 9 18 Mar 2003			0 0
252118 Airframe	Toilet Assembly (Aft) - Removal / Installation 4620-104 007	HRS AFL MOS MSC		6372.3 4205 269.5		O/C	28 9 13 Feb 2003			0 0

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
252120	Switch, Toilet Timer 10159-64	SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 270.9		 O/C	0 0 01 Jan 2003			0 0
Airframe											
252125	Dump Cable - Removal / Installation X	SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 ISRAEL AIRCRAFT INDUSTRIES
Airframe											
252201	Seat Single Placard - Inspection / Check		HRS AFL MOS		177 113 11.9		 24	6223.3 4101 30 Jul 2024	 31 Jul 2026	 31 Aug 2026	0 0
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
252202	Seat, Single - Structural Condition & Security - Insp		HRS AFL MOS		445.3 275 26.2		 48	5955 3939 22 May 2023	 31 May 2027	 30 Jun 2027	0 0
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
Notes: G200-068 ICA GA22801A068 REV. A.											
252203	Seat Pan Cable - Inspection		HRS AFL MOS		177 113 11.9		 24	6223.3 4101 30 Jul 2024	 31 Jul 2026	 31 Aug 2026	0 0
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
Notes: G200-068 ICA GA22801A068 REV. A.											
252204	Seat Track Swivel - Mechanical Operational Check		HRS AFL MOS		177 113 11.9		 24	6223.3 4101 30 Jul 2024	 31 Jul 2026	 31 Aug 2026	0 0
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
Notes: G200-068 ICA GA22801A068 REV. A.											
252205	Seat Recline - Mechanical Check		HRS AFL MOS		177 113 11.9		 24	6223.3 4101 30 Jul 2024	 31 Jul 2026	 31 Aug 2026	0 0
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
Notes: G200-068 ICA GA22801A068 REV. A.											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
252206 Airframe	Seat Armrest - Mechanical Check	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
Notes: G200-068 ICA GA22801A068 REV. A.										
252207 Airframe	Seat Lumbar - Mechanical Check	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
Notes: G200-068 ICA GA22801A068 REV. A.										
252208 Airframe	Seat Belt Latch - Condition and Security	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
Notes: G200-068 ICA GA22801A068 REV. A.										
252209 Airframe	Seat Belt Web - Condition and Security	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
Notes: G200-068 ICA GA22801A068 REV. A.										
252210 Airframe	Seat Cover - Check Condition	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
Notes: G200-068 ICA GA22801A068 REV. A.										
252211 Airframe	Seat Cushions - Check Condition	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
Notes: G200-068 ICA GA22801A068 REV. A.										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
252212 Airframe	Cabin Seat Frame, Backrest, Struct - Insp / Check	HRS AFL MOS		445.3 275 26.2		48	5955 3939 22 May 2023	31 May 2027	30 Jun 2027	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Notes: G200-068 ICA GA22801A068 REV. A.										
252215 Airframe	Cabin Seat Track - Check / Inspect	HRS AFL MOS		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
252301 Airframe	Double Cabin Seat(S) Mountings - Condition & Security	HRS AFL MOS		445.3 275 26.2		48	5955 3939 22 May 2023	31 May 2027	30 Jun 2027	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Notes: G200-068 ICA GA22801A068 REV. A.										
252302 Airframe	Double Cabin Seat(S) - Bushings - Inspection / Check	HRS AFL MOS		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Notes: G200-068 ICA GA22801A068 REV. A.										
252303 Airframe	Double Cabin Seat(S) - Cover Condition Check	HRS AFL MOS		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Notes: G200-068 ICA GA22801A068 REV. A.										
252304 Airframe	Double Cabin Seat(S) - Foam Condition Check	HRS AFL MOS		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Notes: G200-068 ICA GA22801A068 REV. A.										
252305 Airframe	Double Cabin Seat(S) Placards - Insp/Check	HRS AFL MOS		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
252306 Airframe	Double Cabin Seat(S) Frame/Struct - Insp/Check	HRS AFL MOS		177 113 11.9		48	6223.3 4101 30 Jul 2024	31 Jul 2028	31 Aug 2028	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Notes: STC ST10020SC-D - NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
252307 Airframe	Seat Belt Latches - Insp/Check (Double Seats)	HRS AFL MOS		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Notes: G200-068 ICA GA22801A068 REV. A.										
252308 Airframe	Seat Belt Webbing - Insp/Check (Double Seats)	HRS AFL MOS		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Notes: G200-068 ICA GA22801A068 REV. A.										
252309 Airframe	Seat Belt Inertia Reels - OPS Check (Double Seats)	HRS AFL MOS		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Notes: G200-068 ICA GA22801A068 REV. A.										
252310 Airframe	Seat Restraints - Detailed Inspection (Double Seats)	HRS AFL MOS		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Notes: G200-068 ICA GA22801A068 REV. A.										
252311 Airframe	Double Seats - Seat Track - Check/Inspect	HRS AFL MOS		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
252312 Airframe	Double Cabin Seat(S) - Wear Surfaces - Inspection / Check	HRS AFL MOS		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Notes: G200-068 ICA GA22801A068 REV. A.										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
252341	Divan Mountings - Condition/Security	HRS		33.1		500	6367.2	6867.2	6892.2	0
		AFL		21			4193			0
		MOS		2.2	-4	12	23 May 2025	31 May 2026*	30 Jun 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +25/-25]								
Notes: G200-068 ICA GA22801A068 REV. A.										
252342	Divan Fittings - Lubrication	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		264.3			18 Jul 2003			
Airframe		MSC				O/C				
Notes: STC ST09848SC - OCCASIONAL LUBRICATION WILL ENSURE TROUBLE-FREE OPERATION (REF: DECRANE MANUAL M3181)										
253200	Coffee Maker 500-0619-05 99-6-25563	HRS		3212.5			3187.8			0
		AFL		2160			2054			0
		MOS		173.9			01 Feb 2011			
Airframe		MSC				O/C				
253702	Microwave Oven 400-1409-026 02-8-32035	HRS		6372.3			28			0
		AFL		4205			9			0
		MOS		268.5			11 Mar 2003			TIA, A DIVISION OF THE RICHARDS CO.
Airframe		MSC				O/C				
256001	Crash Axe and Sheath - Detailed Inspection	HRS		33.1			6367.2			0
		AFL		21			4193			0
		MOS		2.2		12	23 May 2025	31 May 2026	30 Jun 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256002	Ditching Line - Detailed Inspection	HRS		757.3			5643			0
		AFL		461			3753			0
		MOS		31.9	-29	48	30 Nov 2022	30 Nov 2026*	31 Dec 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256006	Crash Axe D56 NSN	HRS		6362.3			38			0
		AFL		4200			14			0
		MOS		266.3			20 May 2003			
Airframe		MSC				O/C				

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
256025	Smoke Goggles (Pilot) - Removal / Installation	HRS		6400.3			0			0
	PN NOT INSTALLED	AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
256026	Smoke Goggles (Copilot) - Removal / Installation	HRS		6400.3			0			0
	PN NOT INSTALLED	AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
256027	Smoke Goggles - Detailed Inspection	HRS		343.7			6056.6			0
		AFL		211			4003			0
		MOS		21.7	-21	36	05 Oct 2023	30 Sep 2026*	31 Oct 2026	
Airframe	[End Of Month Item] [MOS: +1m/-1m]									
256061	Flashlight No. 1	HRS		6400.3			0			0
	PN NOT INSTALLED	AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
256062	Flashlight No. 2	HRS		6400.3			0			0
	PN NOT INSTALLED	AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
256066	Flashlight No. 1 - Battery Discard	HRS		3904.4			2495.9			0
	P4-01-0030 NSN	AFL		2705			1509			0
		MOS		192.4			17 Jul 2009			ELECTRO ENTERPRISES INC
Airframe		MSC				O/C				
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
256067	Flashlight No. 2 - Battery Discard	HRS		3904.4			2495.9			0
	P4-01-0030 SN-UNKNOWN	AFL		2705			1509			0
		MOS		192.4			17 Jul 2009			
Airframe		MSC				O/C				
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										

ATA / U=Custom / Logbook Position	Description	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
	Part Number / Serial Number									
	HW / SW									
	MM Ref									
	Ops Number(s)									
256071	Flashlight No. 1 - Operational Check	HRS		33.1			6367.2			0
		AFL		21			4193			0
		MOS		2.2	-4	12	23 May 2025	31 May 2026*	30 Jun 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256072	Flashlight No. 2 - Operational Check	HRS		33.1			6367.2			0
		AFL		21			4193			0
		MOS		2.2	-4	12	23 May 2025	31 May 2026*	30 Jun 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256081	Flashlight Mounting - Inspect Condition and Security	HRS		33.1			6367.2			0
		AFL		21			4193			0
		MOS		2.2	-4	12	23 May 2025	31 May 2026*	30 Jun 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: G200-068 ICA GA22801A068 REV. A.										
256090	First AID / Medical Kit Time Limited Supplies - Discard	HRS		12.5			6387.8			0
	AFAK 1.0 101813002	AFL		8			4206			0
		MOS		1.3		12	20 Jun 2025	30 Jun 2026		
Airframe		[End Of Month Item]								EXPIRATION
256091	First AID Kits - Detailed Inspection	HRS		30.4			6369.9			0
		AFL		19			4195			0
		MOS		2.1		12	26 May 2025	31 May 2026	30 Jun 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256093	Life Vests - Detailed Inspection	HRS		30.4			6369.9			0
		AFL		19			4195			0
		MOS		2.1		12	26 May 2025	31 May 2026	30 Jun 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: CABIN AND COCKPIT EXPIRES: 7/2022										
256095	Life Raft No. 1 - Detailed Inspection	HRS		30.4			6369.9			0
		AFL		19			4195			0
		MOS		2.1		12	26 May 2025	31 May 2026	30 Jun 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256096	Life Raft No. 2 - Detailed Inspection	HRS		30.4			6369.9			0
		AFL		19			4195			0
		MOS		2.1		12	26 May 2025	31 May 2026	30 Jun 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
256097	Life Raft No. 3 - Detailed Inspection	HRS		30.4			6369.9			0
		AFL		19			4195			0
		MOS		2.1		12	26 May 2025	31 May 2026	30 Jun 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
256104	Life Raft No. 1 - Removal / Installation 57FASA-691-1-315 5SA-00105	HRS	TSN:1363.9	0			6400.3			0
		AFL	TSN:834	0			4214			0
		MOS	TSN:67	1.3			19 Jun 2025			
		MSC				O/C				
Airframe										
Notes: ELT BAT EXP DATE= 09/2025										
256105	Life Raft No. 2 - Removal / Installation 46FASA-23-1-604 5UL-00243	HRS		0			6400.3			0
		AFL		0			4214			0
		MOS		1.3			19 Jun 2025			
		MSC				O/C				
Airframe										
256106	Life Raft No. 3 - Removal / Installation 57FASA-691-1-315 5UL-00242	HRS		71.1			6329.2			0
		AFL		40			4174			0
		MOS		3.9			31 Mar 2025			
		MSC				O/C				
Airframe										
256107	Life Raft No. 1 - Restore	HRS		0			6400.3			0
		AFL		0			4214			0
		MOS		1.3		36	19 Jun 2025	30 Jun 2028		N/A
Airframe		[End Of Month Item]								EXPIRATION
Notes: PN: 57FASA-691-1-315 SN: 5SA-00105.										
256108	Life Raft No. 2 - Restore	HRS		0			6400.3			0
		AFL		0			4214			0
		MOS		1.3		36	19 Jun 2025	30 Jun 2028		
Airframe		[End Of Month Item]								EXPIRATION
Notes: PN: 57FASA-291-1-325 SN: 5UL-00243. LIFE RAFT RESTORE/OVERHAUL WAS C/W. BY FLIGHTPATH SERVICES CRS# JG1R243K W/O# R46416 . NEW EXPIRATION DATE IS 04/31/2019.										
256109	Life Raft No. 3 - Restore	HRS		71.1			6329.2			0
		AFL		40			4174			0
		MOS		3.9		36	31 Mar 2025	28 Feb 2028		N/A
Airframe		[End Of Month Item]								EXPIRATION
Notes: PN: 57FASA-691-1-315 SN: 5UL-00242.										

ATA / U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
256111	Protective Breathing Equip No. 1 802300-14 E11040977	HRS AFL MOS MSC	TSN:1699.9 TSN:1229 TSN:101	1363.9 834 69.3		 O/C	5036.4 3380 18 Oct 2019			0 0 AVOX SYSTEM, INC.
Airframe										
256116	Protective Breathing Equipment No. 1 - Discard 802300-14 E20070048	HRS AFL MOS	 TSN:3	1179.9 732 57.9		 120	5220.4 3482 30 Sep 2020	 31 Jul 2030		0 0 EXPIRATION
Airframe	[End Of Month Item]									
256125	Protective Breathing Equipment No. 1 - Detailed Inspection	HRS AFL MOS		33.1 21 2.2	 1	500 12	6367.2 4193 23 May 2025	6867.2 31 May 2026*	6917.2 30 Jun 2026	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									
Notes: EXPIRES: 4/2021										
256147	ELT - Life Raft No. 1 P3-03-0041-101 150301	HRS AFL MOS MSC		0 0 1.3		 O/C	6400.3 4214 19 Jun 2025			0 0 DME SRB-406
Airframe										
256148	ELT - Life Raft No. 2 500-12Y 12917	HRS AFL MOS MSC		0 0 1.3		 O/C	6400.3 4214 19 Jun 2025			0 0
Airframe										
256149	ELT - Life Raft No. 3 P3-03-0041-101 137973	HRS AFL MOS MSC		71.1 40 3.9		 O/C	6329.2 4174 31 Mar 2025			0 0
Airframe										
256150	Life Raft No. 1 ELT Battery - Scrap UNKNOWN NSN	HRS AFL MOS MSC		0 0 1.3		 DUE	6400.3 4214 19 Jun 2025	 30 Sep 2030		0 0 EXPIRATION
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
256151	Life Raft No. 2 ELT Battery - Scrap UNKNOWN NSN	HRS AFL MOS MSC		0 0 1.3		 DUE	6400.3 4214 19 Jun 2025	 30 Apr 2030		0 0 EXPIRATION
Airframe										
256152	Life Raft No. 3 ELT Battery - Scrap P4-03-0001-001 137973	HRS AFL MOS MSC	 TSN:1 	71.1 40 3.9 	 	 DUE	6329.2 4174 31 Mar 2025	 30 Jun 2030		0 0 EXPIRATION
Airframe										
256203	Life Vest (Pilot) - Removal / Installation 63600-505 L5329419	HRS AFL MOS MSC		862.1 530 36.3		 O/C	5538.2 3684 20 Jul 2022			0 0
Airframe										
Notes: DUE TO 07/2022										
256204	Life Vest (Copilot) - Removal / Installation 63600-505 L5329416	HRS AFL MOS MSC		862.1 530 36.3		 O/C	5538.2 3684 20 Jul 2022			0 0
Airframe										
Notes: DUE TO 07/2022										
256205	Life Vest (No. 1) - Removal / Installation P01074-101 22060580046	HRS AFL MOS MSC		862.1 530 36.3		 O/C	5538.2 3684 20 Jul 2022			0 0
Airframe										
256206	Life Vest (No. 2) - Removal / Installation P01074-101 22060580047	HRS AFL MOS MSC		862.1 530 36.3		 O/C	5538.2 3684 20 Jul 2022			0 0
Airframe										
Notes: DUE TO 07/2022										
256207	Life Vest (No. 3) - Removal / Installation P01074-101 22060580031	HRS AFL MOS MSC		862.1 530 36.3		 O/C	5538.2 3684 20 Jul 2022			0 0
Airframe										
Notes: DUE TO 7/2022										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
256208	Life Vest (No. 4) - Removal / Installation P01074-101	22060580033	HRS AFL MOS MSC		862.1 530 36.3		O/C	5538.2 3684 20 Jul 2022			0 0
Airframe											
Notes: DUE TO 07/2022											
256209	Life Vest (No. 5) - Removal / Installation P01074-101	22060580032	HRS AFL MOS MSC		862.1 530 36.3		O/C	5538.2 3684 20 Jul 2022			0 0
Airframe											
Notes: DUE TO 7/2022											
256210	Life Vest (No. 6) - Removal / Installation P01074-101	22060580013	HRS AFL MOS MSC		862.1 530 36.3		O/C	5538.2 3684 20 Jul 2022			0 0
Airframe											
Notes: DUE TO 7/2022											
256211	Life Vest (No. 7) - Removal / Installation P01074-101	22060580020	HRS AFL MOS MSC		862.1 530 36.3		O/C	5538.2 3684 20 Jul 2022			0 0
Airframe											
Notes: DUE TO 7/2022											
256212	Life Vest (No. 8) - Removal / Installation P01074-101	22060580014	HRS AFL MOS MSC		862.1 530 36.3		O/C	5538.2 3684 20 Jul 2022			0 0
Airframe											
Notes: DUE TO 7/2022											
256213	Life Vest (No. 9) - Removal / Installation P01074-101	22060580023	HRS AFL MOS MSC		862.1 530 36.3		O/C	5538.2 3684 20 Jul 2022			0 0
Airframe											
Notes: DUE TO 7/2022											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number; HW / SW; MM Ref; Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
256214	Life Vest (No. 10) - Removal / Installation P01074-101 22060680021	HRS AFL MOS MSC		862.1 530 36.3		 O/C	5538.2 3684 20 Jul 2022			0 0
Airframe										
Notes: DUE TO 7/2022										
256215	Life Vest (No. 11) - Removal / Installation P01074-101 2208050010	HRS AFL MOS MSC		862.1 530 36.3		 O/C	5538.2 3684 20 Jul 2022			0 0
Airframe										
Notes: DUE TO 7/2022										
256220	Life Vest (Jumpseat) - Removal / Installation 63600-505 L5765028	HRS AFL MOS MSC	 TSN:5 	399 249 23.4		 O/C	6001.3 3965 17 Aug 2023			0 0
Airframe										
Notes: DOM: 02/01/03										
256223	Life Vest (Pilot) - Restore 63600-505 L5329419	HRS AFL MOS MSC		862.1 1530 36.3		 DUE	5538.2 2684 20 Jul 2022	 31 Jul 2031 		0 0 EXPIRATION
Airframe										
256224	Life Vest (Copilot) - Restore 63600-505 L5329416	HRS AFL MOS MSC		862.1 1530 36.3		 DUE	5538.2 2684 20 Jul 2022	 31 Jul 2031 		0 0 EXPIRATION
Airframe										
256225	Life Vest (No. 1) - Restore P01074-101 22060580046	HRS AFL MOS MSC		862.1 1530 36.3		 DUE	5538.2 2684 20 Jul 2022	 31 Jul 2027 		0 0 EXPIRATION
Airframe										
256226	Life Vest (No. 2) - Restore PO1074-101 22060580047	HRS AFL MOS MSC		862.1 1530 36.3		 DUE	5538.2 2684 20 Jul 2022	 31 Jul 2027 		0 0 EXPIRATION
Airframe										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
256227	Life Vest (No. 3) - Restore		HRS		862.1			5538.2			0
	P01074-101	22060580031	AFL		1530			2684			0
			MOS		36.3			20 Jul 2022	31 Jul 2027		
			MSC				DUE				EXPIRATION
Airframe											
256228	Life Vest (No. 4) - Restore		HRS		862.1			5538.2			0
	PO1074-101	22060580033	AFL		1530			2684			0
			MOS		36.3			20 Jul 2022	31 Jul 2027		
			MSC				DUE				EXPIRATION
Airframe											
256229	Life Vest (No. 5) - Restore		HRS		862.1			5538.2			0
	PO1074-101	22060580032	AFL		1530			2684			0
			MOS		36.3			20 Jul 2022	31 Jul 2027		
			MSC				DUE				EXPIRATION
Airframe											
256230	Life Vest (No. 6) - Restore		HRS		862.1			5538.2			0
	PO1074-101	22060580013	AFL		1530			2684			0
			MOS		36.3			20 Jul 2022	31 Jul 2027		
			MSC				DUE				EXPIRATION
Airframe											
256231	Life Vest (No. 7) - Restore		HRS		862.1			5538.2			0
	P01074-101	22060580020	AFL		1530			2684			0
			MOS		36.3			20 Jul 2022	31 Jul 2027		
			MSC				DUE				EXPIRATION
Airframe											
256232	Life Vest (No. 8) - Restore		HRS		862.1			5538.2			0
	PO1074-101	22060580014	AFL		1530			2684			0
			MOS		36.3			20 Jul 2022	31 Jul 2027		
			MSC				DUE				EXPIRATION
Airframe											
256233	Life Vest (No. 9) - Restore		HRS		862.1			5538.2			0
	PO1074-101	22060580023	AFL		1530			2684			0
			MOS		36.3			20 Jul 2022	31 Jul 2027		
			MSC				DUE				EXPIRATION
Airframe											
256234	Life Vest (No. 10) - Restore		HRS		862.1			5538.2			0
	P01074-101	22060680021	AFL		1530			2684			0
			MOS		36.3			20 Jul 2022	31 Jul 2027		
			MSC				DUE				EXPIRATION
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
256235	Life Vest (No. 11) - Restore P01074-101 22080580010	HRS AFL MOS MSC		862.1 1530 36.3		 DUE	5538.2 2684 20 Jul 2022	 31 Jul 2027		0 0 EXPIRATION
Airframe										
256240	Life Vest (Jumpseat) - Restore 6300-505 L5765028	HRS AFL MOS MSC	 TSN:5	399 249 23.4		 DUE	6001.3 3965 17 Aug 2023	 30 Apr 2033		0 0 EXPIRATION
Airframe										
256300	Emergency Locator Transmitter - Removal / Installation 453-5000-999 14671	HRS AFL MOS MSC	TSN:4029 TSN:2854 TSN:182	1053.8 664 45.8		 O/C	5346.5 3550 04 Oct 2021			0 0
Airframe										
256301	ELT/Nav Interface Unit 453-6500 00264	HRS AFL MOS MSC		5082.4 3518 227		 O/C	1317.9 696 29 Aug 2006			0 0 ARTEX AIRCRAFT SUPPLIES
Airframe										
256302	Emergency Locator Transmitter Antenna - Removal / Installation 110-333 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
256304	Emergency Locator Transmitter Battery - Removal / Installation 452-0133 1012576-001	HRS AFL MOS MSC	 TSN:2	157.9 100 9.8		 O/C	6242.4 4114 03 Oct 2024			0 0
Airframe										
Notes: EXPIRATION DATE: 07/2021 TORQUE WRENCH C/N 555430 CAL DUE: 12/2019										
256312	Emergency Locator Transmitter Battery Pack - Discard 452-0133 1012576-001	HRS AFL MOS MSC	 TSN:2	157.9 100 9.8		 DUE	6242.4 4114 03 Oct 2024	 30 Nov 2029		0 0 EXPIRATION
Airframe										
Notes: CODE ADDED AND SET TO BATTERY EXP DATE.										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
256315 Airframe	Emergency Locator Transmitter - Functional Check	HRS AFL MOS [End Of Month Item]		157.9 100 9.8		12	6242.4 4114 03 Oct 2024	31 Oct 2025		0 0
Notes: PN: 453-5000-999 SN: 14671. BATTERY PN: 452-0133 SN: 370085-010 EXPIRATION DATE: 07/2021										
256318 Airframe	ELT - RE-Registration	HRS AFL MOS		223.7 141 13.4		24	6176.6 4073 17 Jun 2024	17 Jun 2026		0 0
256319 Airframe	406 MHZ ELT, Life Raft (No. 1) - Registration	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
256320 Airframe	406 MHZ ELT, Life Raft (No. 2) - Registration	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
256321 Airframe	406 MHZ ELT, Life Raft (No. 3) - Registration	HRS AFL MOS MSC		71.1 40 3.9		O/C	6329.2 4174 31 Mar 2025			0 0
258000 Airframe	Aircraft RE-Registration (FAA Rule)	HRS AFL MOS MSC		293.8 190 15.8		DUE	6106.5 4024 04 Apr 2024	31 Jan 2031		0 0 EXPIRATION
259001[U] Airframe	Heartsine 350P Defibrillator 350-BAC-US-10 W/EXT 23D90009742B23	HRS AFL MOS MSC		437.6 272 24.4		1 O/C	5962.7 3942 15 Jul 2023	31 Oct 2026		0 0
259002[U] Airframe	Heartsine 350P Defibrillator - "Replace Main PAD-Pak"	HRS AFL MOS MSC		402.6 251 23.6		DUE	5997.7 3963 09 Aug 2023	11 Jan 2026		0 0 EXPIRATION

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
259003[U]	Heartsine 350P Defibrillator - "Replace Spare PAD-Pak"	HRS		399			6001.3			0
		AFL		249			3965			0
		MOS		23.4			17 Aug 2023	01 Mar 2027		
		MSC				DUE				EXPIRATION
Airframe										
26 - FIRE Protection										
260001	FIRE Extinguishing Bottle Firing Circuit (Left) - Operational Check	HRS		1053.8			5346.5			0
		AFL		664			3550			0
		MOS		45.8			04 Oct 2021			
		MSC				O/C				
Airframe										
260002	FIRE Extinguishing Bottle Firing Circuit (Right) - Operational Check	HRS		1053.8			5346.5			0
		AFL		664			3550			0
		MOS		45.8			04 Oct 2021			
		MSC				O/C				
Airframe										
260005	Engine FIRE Push Button Switches Harness and Ground Points - General Visual Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.1			24 May 2023			
		MSC				O/C				
Airframe										
261005	Engine FIRE and Overheat Detection System - Operational Test	HRS		1053.8			5346.5			0
		AFL		664			3550			0
		MOS		45.8			04 Oct 2021			
		MSC				O/C				
Airframe										
261010	APU FIRE Detection System - Operational Test	HRS		1179.9			5220.4			0
		AFL		732			3482			0
		MOS		57.5			11 Oct 2020			
		MSC				O/C				
Airframe										

Notes: PN: 35009-20 SN: D6689. APU FIRE DETECTION SYSTEM OPERATIONAL TEST C/W. NO DEFECTS NOTED. I/A/W G200 CMP CODE 261010 PAGE 1-3.

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
261011 Logbook Position	Zone 1, Engine FIRE Detector Loop (Left) - Operational Check	HRS AFL MOS [HRS: +250]		117.2 71 5.6	-64.5	3000	6283.1 4143 10 Feb 2025	9218.6*	9468.6	0 0
Airframe										
Notes: Aligned with #1 Eng hot section insp										
261012 Logbook Position	Zone 1, Engine FIRE Detector Loop (Right) - Operational Check	HRS AFL MOS [HRS: +250]		117.2 71 5.6	-64.5	3000	6283.1 4143 10 Feb 2025	9218.6*	9468.6	0 0
Airframe										
Notes: Aligned with #1 Eng hot section insp										
261013 Logbook Position	Zone 2, Engine FIRE Detector Loop (Left) - Operational Check	HRS AFL MOS [HRS: +250]		117.2 71 5.6	-64.5	3000	6283.1 4143 10 Feb 2025	9218.6*	9468.6	0 0
Airframe										
Notes: Aligned with #1 Eng hot section insp										
261014 Logbook Position	Zone 2, Engine FIRE Detector Loop (Right) - Operational Check	HRS AFL MOS [HRS: +250]		293.8 190 15.9		3000	6106.5 4024 30 Mar 2024	9106.5	9356.5	0 0
Airframe										
Notes: Aligned with #1 Eng hot section insp										
261018 Logbook Position	APU FIRE Detector Loop - Operational Check	HRS AFL MOS [HRS: +50/-50]		1179.9 732 58.4		2000	5220.4 3482 16 Sep 2020	7220.4	7270.4	0 0
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
261021 Logbook Position	Engine FIRE Detection Extinguishing System - Test	HRS AFL MOS MSC		5491.9 3754 243.5		 O/C	908.4 460 12 Apr 2005			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
261101	Zone 2 Engine FIRE-Overheat Detector (Left) - Removal / Installation 7101-77-1050-730-7 100850	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
261102	Zone 2 Engine FIRE-Overheat Detector (Right) - Removal / Installation 7101-77-1050-730-7 8909	HRS AFL MOS MSC		5491.9 3754 243.5		 O/C	908.4 460 12 Apr 2005			0 0
Airframe										
261103	Detector, FIRE Zone 1 (Left) - Removal / Installation 3101-17-1000-450-7 200915	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
261104	Detector, FIRE Zone 1 (Right) - Removal / Installation 3101-17-1000-450-7 201042	HRS AFL MOS MSC	TSN:908.4 TSN:460 TSN:32	5491.9 3754 243.5		 O/C	908.4 460 12 Apr 2005			0 0 GULFSTREAM DALLAS
Airframe										
261501	Detector, APU FIRE - Removal / Installation 3001-148-950-450-9 83882	HRS AFL MOS MSC	TSN:42 TSN:16	6359.3 4199 266.3		 O/C	41 15 20 May 2003			0 0
Airframe										
261502	Bleed AIR Leak Detection Controller - Removal / Installation (APU) 35009-20 D6689	HRS AFL MOS MSC	 TSN:2	2701.7 1797 158.4		 O/C	3698.6 2417 15 May 2012			0 0
Airframe										
Notes: INTERMITTANT TEST OK MESSAGE										
261503	Bleed AIR Leak Detection Controller - Removal / Installation (Left) 35009-20 D1872	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
261504	Bleed AIR Leak Detection Controller - Removal / Installation (Right) 35009-20 D7363	HRS AFL MOS MSC	TSN:8	2066.4 1325 128.1		O/C	4333.9 2889 24 Nov 2014			0 0
Airframe										
Notes: COULDN"T GET RIGHT ENGINE BLEED AIR LEAK MESSAGE TO ILLUMINATE										
261505	Smoke Isolation Valve - Removal / Installation 4AS7810037-001 0078	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										
261506	Smoke Detector, Baggage Compartment - Removal / Installation 473057 1077	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
261510	Baggage Compartment Smoke Detection System - Functional Test	HRS AFL MOS MSC		6372.3 4205 267.6		O/C	28 9 10 Apr 2003			0 0
Airframe										
262002	FIRE Extinguishing Container (Right) - Removal / Installation 473779-3 0300BC	HRS AFL MOS MSC	TSN:74	847.3 511 36.2		O/C	5553 3703 21 Jul 2022			0 0
Airframe										
262003	FIRE Extinguishing Container (Left) - Removal / Installation 473779-4 20987EL	HRS AFL MOS MSC	TSN:231	1053.8 664 45.8		O/C	5346.5 3550 04 Oct 2021			0 0
Airframe										
262004	FIRE Extinguishing Container Cartridge (Left Bottle, Left Squib) - Removal / Installation 446582-2 AFF1301	HRS AFL MOS MSC	TSN:126.1 TSN:68	1053.8 664 45.8		O/C	5346.5 3550 04 Oct 2021			0 0 MANUFACTURE
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
262005 Logbook Position	FIRE Extinguishing Container Cartridge (Left Bottle, Right Squib) - Removal / Installation 446582-3 AFB0083	HRS AFL MOS MSC	TSN:126.1 TSN:68	1053.8 664 45.8		 O/C	5346.5 3550 04 Oct 2021			0 0 MANUFACTURE
Airframe										
262007 Logbook Position	FIRE Extinguishing Container Cartridge (Right Bottle, Left Squib) - Removal / Installation 446582-3 AEI6864	HRS AFL MOS MSC		847.3 511 36.2		 O/C	5553 3703 21 Jul 2022			0 0 MANUFACTURE
Airframe										
262008 Logbook Position	FIRE Extinguishing Container Cartridge (Right Bottle, Right Squib) - Removal / Installation 446582-1 AEI8511	HRS AFL MOS MSC		847.3 511 36.2		 O/C	5553 3703 21 Jul 2022			0 0 MANUFACTURE
Airframe										
262009 Logbook Position	FIRE Extinguishing Container Cartridge (Right Bottle, APU Squib) - Removal / Installation 446582-2 AEH8162	HRS AFL MOS MSC		847.3 511 36.2		 O/C	5553 3703 21 Jul 2022			0 0 MANUFACTURE
Airframe										
262011 Logbook Position	FIRE Extinguishing Container Gage (Left) - Visual Check	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		30.4 19 2.1		 12	6369.9 4195 26 May 2025	31 May 2026	30 Jun 2026	0 0
Airframe										
262012 Logbook Position	FIRE Extinguishing Container Gage (Right) - Visual Check	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		30.4 19 2.1		 12	6369.9 4195 26 May 2025	31 May 2026	30 Jun 2026	0 0
Airframe										
262013 Logbook Position	FIRE Extinguishing Container (Weight Check) (Left) - Functional Check	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1053.8 664 45.8		 60	5346.5 3550 04 Oct 2021	31 Oct 2026	30 Nov 2026	0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
262014 Logbook Position	FIRE Extinguishing Container (Weight Check) (Right) - Functional Check	HRS AFL MOS		847.3 511 36.2		60	5553 3703 21 Jul 2022	31 Jul 2027	31 Aug 2027	0 0
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
262021 Airframe	FIRE Extinguishing Container (Left) - (Hydrostatic) Functional Check	HRS AFL MOS MSC [End Of Month Item]		1053.8 664 45.7		O/C	5346.5 3550 05 Oct 2021			0 0 HYDRO CHECK
Notes: PN: 473779-4 SN: 0579BC. NEXT HYDRO 7/2022-Can you reapply the 60M requirement for the hydro on the engine fire bottles? They are tasks 262021 and 22.										
262022 Airframe	FIRE Extinguishing Container (Right) - (Hydrostatic) Functional Check	HRS AFL MOS MSC [End Of Month Item]		847.3 511 36.2		O/C	5553 3703 21 Jul 2022			0 0 HYDRO CHECK
Notes: PN: 473779-3 SN: 2094EL. NEXT HYDRO DUE 07/2022-Can you reapply the 60M requirement for the hydro on the engine fire bottles? They are tasks 262021 and 22.										
262030 Airframe	Thermal Discharge Indicator Disk - Removal / Installation 13159 SN-UNKNOWN	HRS AFL MOS MSC		757.3 461 31.9		O/C	5643 3753 30 Nov 2022			0 0
262041 Airframe	Two-Way Check Valve (Left) - Removal / Installation 897682-01 SN-N/A	HRS AFL MOS MSC		1053.8 664 45.8		O/C	5346.5 3550 04 Oct 2021			0 0
262042 Airframe	Two-Way Check Valve (Right) - Removal / Installation 897862-01 SN-N/A	HRS AFL MOS MSC		1053.8 664 45.8		O/C	5346.5 3550 04 Oct 2021			0 0
262043 Airframe	Two-Way Check Valve (Left) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1053.8 664 45.8		120	5346.5 3550 04 Oct 2021	31 Oct 2031	30 Nov 2031	0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
262044	Two-Way Check Valve (Right) - Detailed Inspection	HRS		1053.8			5346.5			0
		AFL		664			3550			0
		MOS		45.8		120	04 Oct 2021	31 Oct 2031	30 Nov 2031	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
262091	APU FIRE Protection Fuse Replacement - Retrofit Directive	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
		MSC				O/C				
Airframe										
262101	FIRE Extinguishing Container Cartridges (Left Bottle, Left Squib) - Discard	HRS		1179.9			5220.4			0
		AFL		732			3482			0
	446582-2 AFF1301	MOS		57.5		120	11 Oct 2020	28 Feb 2029		
		[End Of Month Item]								MANUFACTURE
Airframe										
262102	FIRE Extinguishing Container Cartridges (Right Bottle, Left Squib) - Discard	HRS		847.3			5553			0
		AFL		511			3703			0
	446582-2 AEI6864	MOS		36.2		120	21 Jul 2022	31 Jul 2026		
		[End Of Month Item]								MANUFACTURE
Airframe										
262103	FIRE Extinguishing Container Cartridges (Left Bottle, Right Squib) - Discard	HRS		1179.9			5220.4			0
		AFL		732			3482			0
	446582-3 AFB0083	MOS		57.5		120	11 Oct 2020	30 Sep 2028		
		[End Of Month Item]								MANUFACTURE
Airframe										
262104	FIRE Extinguishing Container Cartridges (Right Bottle, Right Squib) - Discard	HRS		847.3			5553			0
		AFL		511			3703			0
	446582-1 AEI8511	MOS		36.2		120	21 Jul 2022	31 Aug 2026		
		[End Of Month Item]								MANUFACTURE
Airframe										
262201	FIRE Extinguishing Container Cartridges (Right Bottle, APU Squib) - Discard	HRS		847.3			5553			0
		AFL		511			3703			0
	446852-2 AEH8162	MOS		36.2		120	21 Jul 2022	30 Jun 2026		
		[End Of Month Item]								MANUFACTURE
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
262401	Extinguisher, Portable FIRE No. 1 (Cockpit) C352TS G-40532287	HRS AFL MOS MSC		1053 663 44.7		 O/C	5347.3 3551 05 Nov 2021			0 0
Airframe										
262402	Extinguisher, Portable FIRE No. 2 (Cabin) C354TS I-24623754	HRS AFL MOS MSC		283.5 185 15.6		 O/C	6116.8 4029 09 Apr 2024			0 0
Airframe										
262406	Portable FIRE Extinguisher (Cockpit) - Detailed Inspection	HRS AFL MOS		30.4 19 2.1		 12	6369.9 4195 26 May 2025	31 May 2026	30 Jun 2026	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m]									
262407	Portable FIRE Extinguisher (Cabin) - Detailed Inspection	HRS AFL MOS		33.1 21 2.2	 -44	 12	6367.2 4193 23 May 2025	30 Apr 2026*	31 May 2026	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m]									
262411	Portable FIRE Extinguisher (Cockpit) - Visual Inspection	HRS AFL MOS		0 0 .7		 1	6400.3 4214 07 Jul 2025	31 Aug 2025	15 Sep 2025	0 0
Airframe	[End Of Month Item] [+15d]									
262412	Portable FIRE Extinguisher (Cabin) - Visual Inspection	HRS AFL MOS		0 0 .7		 1	6400.3 4214 07 Jul 2025	31 Aug 2025	15 Sep 2025	0 0
Airframe	[End Of Month Item] [+15d]									
262421	Portable FIRE Extinguisher (Cockpit) - Weight Check	HRS AFL MOS		30.4 19 2.1		 12	6369.9 4195 26 May 2025	31 May 2026	30 Jun 2026	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m]									WEIGHT CHECK
262422	Portable FIRE Extinguisher (Cabin) - Weight Check	HRS AFL MOS		33.1 21 2.2	 -44	 12	6367.2 4193 23 May 2025	30 Apr 2026*	31 May 2026	0 0 H3R
Airframe	[End Of Month Item] [MOS: +1m/-1m]									WEIGHT CHECK

Notes: PN: C354TS SN: E-92813994.

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
262431	Valve, FIRE Extinguisher (No. 1) - Restore C352TS G-40532287	HRS AFL MOS MSC		1053 663 44.7		 O/C	5347.3 3551 05 Nov 2021			0 0
Airframe										
262432	Valve, FIRE Extinguisher (No. 2) - Restore C352TS Y-649354	HRS AFL MOS MSC		2143.4 1363 131.9		 O/C	4256.9 2851 31 Jul 2014			0 0
Airframe										
262441	Portable FIRE Extinguisher (Cockpit) - (Hydrostatic) Functional Check	HRS AFL MOS [End Of Month Item]		1053 663 44.7		 144	5347.3 3551 05 Nov 2021	 30 Nov 2033		0 0 HYDRO CHECK
Airframe										
262442	Portable FIRE Extinguisher (Cabin) - (Hydrostatic) Functional Check	HRS AFL MOS [End Of Month Item]		283.5 185 15.6		 144	6116.8 4029 09 Apr 2024	 31 Jan 2036		0 0 HYDRO CHECK
Airframe										
Notes: CMP UPDATE ONLY										
262451	Portable FIRE Extn(S) Mounting - Insp Cond & Security	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		30.4 19 2.1		 12	6369.9 4195 26 May 2025	 31 May 2026	30 Jun 2026	0 0
Airframe										
262452	Portable FIRE Extn(S) - Visual Inspection	HRS AFL MOS MSC [End Of Month Item]		259.1 170 14.9	22	 O/C	6141.2 4044 30 Apr 2024			0 0
Airframe										
Notes: Tracked using 262406, 262407, 262421, 262422										
262461	Halon Portable FIRE Extinguisher (Cockpit) - 6 Year Maintenance C352TS G-40532287	HRS AFL MOS		1053 663 44.7		 72	5347.3 3551 05 Nov 2021	 05 Nov 2027		0 0 OVERHAUL
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
262462	Halon Portable FIRE Extinguisher (Cabin) - 6 Year Maintenance	HRS		283.5			6116.8			0
		AFL		185			4029			0
	C354TS I-24623754	MOS		15.6		72	09 Apr 2024	31 Jan 2030		
										OVERHAUL
Airframe										
264002	Trash Container Enclosure - Detailed Inspection	HRS		30.4			6369.9			0
		AFL		19			4195			0
		MOS		2.1		12	26 May 2025	31 May 2026	30 Jun 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
27 - Flight Controls										
271002	Aileron (Left) - Removal / Installation	HRS	TSN:1084.9	5315.4			1084.9			0
	4AS1810001-501 275	AFL	TSN:556	3658			556			0
		MOS		238.5			12 Sep 2005			ISRAEL AIRCRAFT INDUSTRIES
Airframe		MSC				O/C				
271003	Aileron (Right) - Removal / Installation	HRS	TSN:1084.9	5315.4			1084.9			0
	4AS181101-502 271	AFL	TSN:556	3658			556			0
		MOS	TSN:38	238.5			12 Sep 2005			
Airframe		MSC				O/C				
271006	Control Column - Detailed Inspection	HRS		1179.9			5220.4			0
		AFL		732			3482			0
		MOS		58.2		72	23 Sep 2020	30 Sep 2026	31 Oct 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
271011	Aileron Travel Limit Stops and Control Cables - Detailed Inspection (Post Sb 200-05-280)	HRS		1179.9			5220.4			0
		AFL		732			3482			0
		MOS		58.2		72	23 Sep 2020	30 Sep 2026	31 Oct 2026	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
271019 Airframe	Aileron Disconnect System - Operational Test (Cmr*)	HRS AFL MOS [HRS: +50/-50]		445.3 275 26.3		1000	5955 3939 18 May 2023	6955	7005	0 0
Notes: PUSH PULL GAUGE C/N: 56920 CAL DUE: 12/2019										
271027 Airframe	Aileron Mechanical Control Linkage (Left) - General Visual Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]		445.3 275 25.9	-46.5	3000 72	5955 3939 31 May 2023	8908.5* 31 May 2029	8958.5 30 Jun 2029	0 0
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
271028 Airframe	Aileron Mechanical Control Linkage (Right) - General Visual Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]		445.3 275 25.9	-46.5	3000 72	5955 3939 31 May 2023	8908.5* 31 May 2029	8958.5 30 Jun 2029	0 0
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
271036 Airframe	Aileron Trim Control System - Functional Test	HRS AFL MOS MSC		6372.3 4205 267.6		 O/C	28 9 10 Apr 2003			0 0
271041 Airframe	Aileron Actuator Microswitch - Operational Check	HRS AFL MOS [HRS: +50/-50]		445.3 275 25.9	-46.5	3000	5955 3939 30 May 2023	8908.5*	8958.5	0 0
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
271051 Airframe	Aileron Artificial Feel Spring Unit - Lubrication	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]		157.9 100 9.8	 16	500 12	6242.4 4114 03 Oct 2024	6742.4 31 Oct 2025*	6792.4 30 Nov 2025	0 0
271056 Airframe	Aileron Servo Actuator Centering Spring ROD - General Visual Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71.2	 -23	 192	5036.4 3380 23 Aug 2019	 31 Jul 2035*	 31 Aug 2035	0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
271060	Aileron Travel Limit Stops and Control Cables - Visual Inspection	HRS AFL MOS MSC		6400.3 4214 265.1		 O/C	0 0 25 Jun 2003			0 0
Airframe										
271080	Aileron Linear Ball Bearing Assembly - Visual Inspection	HRS AFL MOS MSC		6400.3 4214 265.1		 O/C	0 0 25 Jun 2003			0 0
Airframe										
271091	Aileron Trim Actuator - Removal / Installation 223000-2M01 075	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
271401	Aileron Servo Actuator (Left) - Removal / Installation 4010-0000-000 IL-124	HRS AFL MOS MSC		445.3 275 25.4		 O/C	5955 3939 15 Jun 2023			0 0
Airframe										
271402	Aileron Servo Actuator (Right) - Removal / Installation 4010-0000-000 IL-071	HRS AFL MOS MSC		445.3 275 25.4		 O/C	5955 3939 16 Jun 2023			0 0
Airframe										
271407	Aileron Servo Actuator (Left) - Operational Check	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
271408	Aileron Servo Actuator (Right) - Operational Check	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
271409	Aileron Hydraulic Compensator (Left) - Removal / Installation 7313-2 594	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
271410	Aileron Hydraulic Compensator (Right) - Removal / Installation 7313-2 0586	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
271411	Elevator Hydraulic Compensator (Left) - Removal / Installation 7313-2 616	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
271412	Elevator Hydraulic Compensator (Right) - Removal / Installation 7313-2 515	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
271423	Aileron Hydraulic System Volume and Dampener (Left, Post Sb 200-05-280) - Inspection (Cmr*)	HRS AFL MOS [HRS: +50/-50]		445.3 275 25.8	-46.5	3000	5955 3939 02 Jun 2023	8908.5*	8958.5	0 0
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
271424	Aileron Hydraulic System Volume and Dampener (Right, Post Sb 200-05-280) - Inspection (Cmr*)	HRS AFL MOS [HRS: +50/-50]		445.3 275 25.8	-46.5	3000	5955 3939 02 Jun 2023	8908.5*	8958.5	0 0
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
272002	Rudder - Removal / Installation 4AS4202201-501 068	HRS AFL MOS MSC	TSN:28 TSN:9	6372.3 4205 267.8		 O/C	28 9 03 Apr 2003			0 0 GULFSTREAM DALLAS
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
272004 Airframe	Actuator, Rudder Bias 90-10192-01 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
272006 Airframe	Switch, Rudder Bias 16395-010 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
272011 Airframe	Rudder Bias Activation / Deactivation - Operational Check [HRS: +50/-50]	HRS AFL MOS		1179.9 732 55.6		2000	5220.4 3482 10 Dec 2020	7220.4	7270.4	0 0
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
272021 Airframe	Rudder Pedestal Assembly, Condition and Security - Inspection	HRS AFL MOS MSC		6400.3 4214 265.1		 O/C	0 0 25 Jun 2003			0 0
272026 Airframe	Rudder Mechanical Linkage - Detailed Inspection [HRS: +50/-50]	HRS AFL MOS		445.3 275 25.9		1000	5955 3939 01 Jun 2023	6955	7005	0 0
272027 Airframe	Rudder Control Circuit Linkages / Attachments - General Visual Inspection [End Of Month Item] [MOS: +1m/-1m]	HRS AFL MOS		1179.9 732 58.2		 72	5220.4 3482 23 Sep 2020	30 Sep 2026	31 Oct 2026	0 0
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
272041 Airframe	Rudder Trim Tab - Removal / Installation 4AS4203101-501 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
272043 Airframe	Rudder Trim Tab Potentiometer - Adjustment	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
272044 Airframe	Trim Tab Connections - Detailed Inspection	HRS AFL MOS [HRS: +50/-50]		445.3 275 25.9		1000	5955 3939 01 Jun 2023	6955	7005	0 0
272046 Airframe	Rudder Trim Actuator Attach Points and Electrical Connectors - Inspection (Cmr*)	HRS AFL MOS [HRS: +50/-50]		445.3 275 25.9		1000	5955 3939 01 Jun 2023	6955	7005	0 0
272047 Airframe	Rudder Trim Tab Freeplay - Functional Check	HRS AFL MOS [HRS: +50/-50]		445.3 275 25.9		1000	5955 3939 01 Jun 2023	6955	7005	0 0
Notes: DO NOT COMPLY TILL HARDWARE REPLACED. REF 16.8DIAL INDICATOR - 569253 CAL DUE 08/20PUSH/PULL SCALE - 569620 CAL DUE 12/19										
272050 Airframe	Rudder Trim Control System - Functional Test	HRS AFL MOS MSC		1363.9 834 69.8		 N/A	5036.4 3380 02 Oct 2019			0 0
272057 Airframe	Rudder Trim Lower Flexible Shaft - Removal / Installation 4204014-523 0337	HRS AFL MOS MSC	 TSN:37	1363.9 834 69.8		 O/C	5036.4 3380 02 Oct 2019			0 0 N/A
272058 Airframe	Rudder Trim Upper Flexible Shaft - Removal / Installation 4204014-521 076 N/A N/A	HRS AFL MOS MSC	TSN:2540.5 TSN:1871 TSN:121	1363.9 834 71.2		 O/C	5036.4 3380 22 Aug 2019			0 0 N/A
Notes: T/W: 558036, CAL: 06/20										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
272062 Logbook Position	Rudder Trim Flexible Cable Shaft Core - Lubrication (Post Sb 200-05-280)	HRS		445.3		1000	5955	6955	7005	0
		AFL		275			3939			0
		MOS		25.8		48	02 Jun 2023	30 Jun 2027	31 Jul 2027	
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe										
Notes: REF. 15.47 FOR LOWER FLEX SHAFT R&IREF. 15.48 FOR UPPER FLEX SHAFT R&I										
272204	Rudder Bias Actuator - Removal / Installation 4AS7120040-003 F0208	HRS		1155.1			5245.2			0
		AFL		719			3495			0
		MOS		54.9			01 Jan 2021			
		MSC				O/C				
Airframe										
272205	Rudder Trim Lower Actuator - Removal / Installation (Aircraft 004 Thru Aircraft 144 Post Sb 200-27-298 and Aircraft 145 Thru Aircraft 999) 4204002-527 SIL-076	HRS	TSN:3507.5	3904.4			2495.9			0
		AFL	TSN:2145	2705			1509			0
		MOS		192.1			24 Jul 2009			SHL DIVISION
		MSC				O/C				
Airframe										
272206	Rudder Trim Upper Actuator - Removal / Installation (Aircraft 004 Thru 144 Post Sb 200-27-298 and Aircraft 145 and Sub) 4204002-529 IL004	HRS	TSN:2297.6	3904.4			2495.9			0
		AFL	TSN:1304	2705			1509			0
		MOS	TSN:5	192.2			23 Jul 2009			SHL DIVISION
		MSC				O/C				
Airframe										
272207	Rudder Trim Intermediate Actuator - Removal / Installation, A/C 004 - 144 Post MOD 10113 / Post Sb 200 -27-298, 145 - 999 4204002-508 IL079	HRS		3904.4			2495.9			0
		AFL		2705			1509			0
		MOS		192.2			23 Jul 2009			SHL DIVISION
		MSC				O/C				
Airframe										
273002	Elevator (Left) - Removal / Installation 4AS4601001-503 265	HRS	TSN:28	6372.3			28			0
		AFL	TSN:9	4205			9			0
		MOS		269.4			17 Feb 2003			
		MSC				O/C				
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
273003 Airframe	Elevator (Right) - Removal / Installation 4AS4601001-504 268	HRS AFL MOS MSC	TSN:5036.4 TSN:3380	1363.9 834 69.5		O/C	5036.4 3380 11 Oct 2019			0 0 N/A
Notes: TORQUE WRENCH: 558041 CALIBRATION DUE: 05/2020										
273006 Airframe	Elevator Control Cables - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 70.9	-30	96	5036.4 3380 30 Aug 2019	31 Jul 2027*	31 Aug 2027	0 0
273014 Airframe	Q-Feel Actuator - Removal / Installation 4AS7130020-003 IL-112	HRS AFL MOS MSC		5049.1 3494 226.1		O/C	1351.2 720 26 Sep 2006			0 0 GULFSTREAM DALLAS
273016 Airframe	Q-Feel Shut-Off Valve - Removal / Installation 6920-3 289	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
273018 Airframe	Elevator Servo Actuator Attachments - General Visual Inspection	HRS AFL MOS [HRS: +50/-50]		506.3 322 27.8	14.5	3000	5894 3892 03 Apr 2023	8908.5*	8958.5	0 0
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
273020 Airframe	Elevator Pitch Disconnect Function - Operational Check (Cmr*)	HRS AFL MOS [HRS: +50/-50]		445.3 275 26.3		1000	5955 3939 18 May 2023	6955	7005	0 0
Notes: PUSH PULL GAUGE C/N: 56920 CAL DUE: 12/2019										
273031 Airframe	Elevator Servo Actuator Centering Spring ROD - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71	-28	192	5036.4 3380 28 Aug 2019	31 Jul 2035*	31 Aug 2035	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
273038 Airframe	Stick Pusher Actuator - Removal / Installation ZHA2 01120366	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
273043 Airframe	Elevator Travel Stop Bolts / Stop Pads - Inspection	HRS AFL MOS MSC		6400.3 4214 265.1		 O/C	0 0 25 Jun 2003			0 0
273055 Airframe	Elevator Actuator Microswitch - Operational Check [HRS: +50/-50]	HRS AFL MOS	445.3 275 25.8		-46.5	3000	5955 3939 02 Jun 2023	8908.5*	8958.5	0 0
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
273301 Airframe	Stick Shaker (Pilot) 0050P 149	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
273302 Airframe	Stick Shaker (CO-Pilot) 0050P 151	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
273403 Airframe	Elevator Servo Actuator (Left) - Functional Check	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
273404 Airframe	Elevator Servo Actuator (Right) - Functional Check	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
273407 Airframe	Elevator Servo Actuator (Left) - Operational Test	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
273408	Elevator Servo Actuator (Right) - Operational Test	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
273409	Elevator Servo Actuator (Left) - Removal / Installation 4007-0000-000 IL-045	HRS AFL MOS MSC		4515.3 3136 209.1		 O/C	1885 1078 24 Feb 2008			0 0 GULFSTREAM DALLAS
Airframe										
273410	Elevator Servo Actuator (Right) - Removal / Installation 4008-0000-000 IL-162	HRS AFL MOS MSC	 TSN:4	4901.2 3397 222.6		 O/C	1499.1 817 10 Jan 2007			0 0
Airframe										
273411	Elevator Servo Actuator Compensator Volume and Dampener (Left, Post Sb 200-05-280) - Check (Cmr*)	HRS AFL MOS [HRS: +50/-50]		445.3 275 25.8	-46.5	3000	5955 3939 02 Jun 2023	8908.5*	8958.5	0 0
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
273412	Elevator Servo Actuator Compensator Volume and Dampener (Right, Post Sb 200-05-280) - Check (Cmr*)	HRS AFL MOS [HRS: +50/-50]		445.3 275 25.8	-46.5	3000	5955 3939 02 Jun 2023	8908.5*	8958.5	0 0
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
274002	Horizontal Stabilizer Trim System (Post Sb 200-05-280) - Interference Test	HRS AFL MOS [HRS: +50/-50]		3023.6 2026 168.8		4000	3376.7 2188 02 Jul 2011	7376.7	7426.7	0 0
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
274003 Logbook Position	Horizontal Stabilizer Trim Actuator Wiring Harnesses and Ground Points - General Visual Inspection	HRS AFL MOS		1363.9 834 71.1	-26	96	5036.4 3380 26 Aug 2019	31 Jul 2027*	31 Aug 2027	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: COMPLIED WITH CMP G200 274003 HORIZONTAL STABILIZER TRIM ACTUATOR WIRING HARNESSES AND GROUND POINTS - GENERAL VISUAL INSPECTION										
274005	Horizontal Stabilizer Trim System - Functional Test	HRS AFL MOS MSC		1363.9 834 69.8		N/A	5036.4 3380 03 Oct 2019			0 0
Airframe										
274006	Horizontal Stabilizer Trim Actuator (Post Sb 200-05-280) - Load Path Check	HRS AFL MOS		3023.6 2026 168.8		4000	3376.7 2188 02 Jul 2011	7376.7	7426.7	0 0
		[HRS: +50/-50]								
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
274007	Horizontal Stabilizer Actuator Attachments - General Visual Inspection	HRS AFL MOS		1179.9 732 58.2		72	5220.4 3482 23 Sep 2020	30 Sep 2026	31 Oct 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
274016	Horizontal Stabilizer Trim Actuator Dynamic Braking (Post Sb 200-05-280) - Functional Check	HRS AFL MOS		3023.6 2026 168.8		4000	3376.7 2188 02 Jul 2011	7376.7	7426.7	0 0
		[HRS: +50/-50]								
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
274301	Horizontal Stabilizer Trim Actuator - Removal / Installation 376700-1021 0074	HRS AFL MOS MSC	TSN:6985.3 TSN:3988	1377.1 842 72		O/C	5023.2 3372 27 Jul 2019			0 0
Airframe										
Notes: TW 40-200 85342 DUE 10-04-19TW 200-1000 85343 DUE 02-07-20FEELER GAUGE 85644 DUE 12-05-2019										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
274302 Airframe	Horizontal Stabilizer Trim Actuator - Restore 376700-1021 0074	HRS AFL MOS	TSN:6985.3 TSN:3988	1377.1 842 72		7000	5023.2 3372 27 Jul 2019	12023.2		0 0
275005 Airframe	Flap Ballscrew Actuators - Lubrication	HRS AFL MOS MSC		1709.6 1051 94.5		O/C	4690.7 3163 11 Sep 2017			0 0
275006 Airframe	Inner Flap Assembly (Left) - Removal / Installation 25W191001-453 019/068	HRS AFL MOS MSC		445.3 275 25.9		O/C	5955 3939 01 Jun 2023			0 0
275007 Airframe	Inner Flap Assembly (Right) - Removal / Installation 25W191001-454 022/068	HRS AFL MOS MSC		445.3 275 25.9		O/C	5955 3939 01 Jun 2023			0 0
275008 Airframe	Outer Flap Assembly (Left) - Removal / Installation 25W192001-459 069	HRS AFL MOS MSC		445.3 275 25.9		O/C	5955 3939 01 Jun 2023			0 0
275009 Airframe	Outer Flap Assembly (Right) - Removal / Installation 25W192001-460 068	HRS AFL MOS MSC		445.3 275 25.9		O/C	5955 3939 01 Jun 2023			0 0
275010 Airframe	Flap Actuator Electrical Brakes - Operational Test	HRS AFL MOS MSC		6400.3 4214 265.1		O/C	0 0 25 Jun 2003			0 0
275041 Airframe	Krueger Flap Selector Valve - Removal / Installation HP848900-1 NEED S/N	HRS AFL MOS MSC		5082.4 3518 226.7		O/C	1317.9 696 06 Sep 2006			0 0 GULFSTREAM DALLAS

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
275042	Krueger Flap Actuator (Left) - Removal / Installation CE500130-0013 C103	HRS AFL MOS MSC		2378.1 1547 144.3		O/C	4022.2 2667 19 Jul 2013			0 0
Airframe										
275043	Krueger Flap Actuator (Right) - Removal / Installation CE500130-0013 C487	HRS AFL MOS MSC		1709.6 1051 94.5		O/C	4690.7 3163 13 Sep 2017			0 0
Airframe										
275044	Krueger Flap (Left) - Removal / Installation 4AS2310001-501 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										
275045	Krueger Flap (Right) - Removal / Installation 4AS2310001-502 SN-UNKNOWN	HRS AFL MOS MSC	TSN:4690.7 TSN:3163 TSN:182	1709.6 1051 93.8		O/C	4690.7 3163 02 Oct 2017			0 0
Airframe										
275046	Krueger Flaps System (Aircraft Post Sb 200-05-280) - Functional Test	HRS AFL MOS MSC		2378.1 1547 144.3		O/C	4022.2 2667 19 Jul 2013			0 0
Airframe										
275047	Krueger Flaps System - Rigging	HRS AFL MOS MSC		1709.6 1051 93.8		O/C	4690.7 3163 04 Oct 2017			0 0
Airframe										
275100	Fsecu/Flap System - See Cmp Code 275209 4AS8420021-003 00169	HRS AFL MOS MSC		6372.3 4205 270		O/C	28 9 28 Jan 2003			0 0
Airframe										
275101	Flap / Slat Control and Drive System - Functional Test	HRS AFL MOS MSC		757.3 461 31.9		O/C	5643 3753 30 Nov 2022			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
275102 Logbook Position	Flap / Slat Power Drive Unit Transmission Brake - Operational Check	HRS AFL MOS		757.3 461 31.9		1500	5643 3753 30 Nov 2022	7143	7193	0 0
		[HRS: +50/-50]								
	Airframe									
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
275103	Fsecu Integrity - Functional Check	HRS AFL MOS		48.5 30 2.9		1000 12	6351.8 4184 30 Apr 2025	7351.8 30 Apr 2026	7401.8 31 May 2026	0 0
	Airframe	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
275114	Flap Power Drive Unit (Fpdu) - Detailed Inspection	HRS AFL MOS		757.3 461 31.9		1500	5643 3753 30 Nov 2022	7143	7193	0 0
	Airframe	[HRS: +50/-50]								
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
275120	Flap Flex Shaft Ends - Visual Inspection	HRS AFL MOS MSC		6400.3 4214 265.1		 O/C	0 0 25 Jun 2003			0 0
	Airframe									
275141	Flaps / Slats Flexible Shafts (Left) - Lubrication (Post Sb 200-05-280)	HRS AFL MOS		445.3 275 25.9		1500 72	5955 3939 30 May 2023	7455 31 May 2029	7505 30 Jun 2029	0 0
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
	Airframe									
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
275142	Flaps / Slats Flexible Shafts (Right) - Lubrication (Post Sb 200-05-280)	HRS AFL MOS		445.3 275 25.9		1500 72	5955 3939 30 May 2023	7455 31 May 2029	7505 30 Jun 2029	0 0
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
	Airframe									
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
275143	Flap / Slat Flexible Shafts (Left) - Detailed Inspection	HRS AFL MOS [HRS: +50/-50]		757.3 461 31.9		1500	5643 3753 30 Nov 2022	7143	7193	0 0
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
275144	Flap / Slat Flexible Shafts (Right) - Detailed Inspection	HRS AFL MOS [HRS: +50/-50]		757.3 461 31.9		1500	5643 3753 30 Nov 2022	7143	7193	0 0
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
275203	Krueger Flap Relay (431C) - Functional Check	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
275207	Flaps / Slats Selector Switch - Removal / Installation 777701-11 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
275209	Flap / Slat Electronic Control Unit (Fsecu) - Removal / Installation 1250A0000-02 00169	HRS AFL MOS MSC	TSN:28 TSN:9	6372.3 4205 267.9		 O/C	28 9 31 Mar 2003			0 0 LIEBHERR-AEROSPACE SALINE CO.
Airframe										
275210	Flap Power Drive Unit (Fpdu) - Removal / Installation 1242A0000-01 00182	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
275211	Flap Ballscrew Actuator No. 1 (Left) - Removal / Installation 1243A0000-04 00206	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
275212 Logbook Position	Flap Ballscrew Actuator No. 1 (Right) - Removal / Installation 1243A0000-04 00210	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
275213 Logbook Position	Flap Ballscrew Actuator No. 2 (Left) - Removal / Installation 1244A0000-04 00203	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
275214 Logbook Position	Flap Ballscrew Actuator No. 2 (Right) - Removal / Installation 1244A0000-04 00208	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
275215 Logbook Position	Flap Ballscrew Actuators No. 3 (Left) - Removal / Installation 1245A0000-04 00214	HRS AFL MOS MSC		2143.4 1363 131.6		 O/C	4256.9 2851 08 Aug 2014			0 0 GULFSTREAM DALLAS
Airframe										
275216 Logbook Position	Flap Ballscrew Actuators No. 3 (Right) - Removal / Installation 1245B0000-04 00195	HRS AFL MOS MSC		1884.1 1180 119		 O/C	4516.2 3034 29 Aug 2015			0 0 GULFSTREAM DALLAS
Airframe										
275223 Logbook Position	Slat Ballscrew Actuator No. 1 (Left) - Removal / Installation 1253A0000-04 00201	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
275224 Logbook Position	Slat Ballscrew Actuator No. 1 (Right) - Removal / Installation 1253A0000-04 00206	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number; HW / SW; MM Ref; Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
275225	Slat Ballscrew Actuator No. 2 (Left) - Removal / Installation 1254A0000-04 00207	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
275226	Slat Ballscrew Actuator No. 2 (Right) - Removal / Installation 1254A0000-04 00212	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
275227	Slat Ballscrew Actuators No. 3 (Left) - Removal / Installation 1255A0000-04 00150	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
275228	Slat Ballscrew Actuators No. 3 (Right) - Removal / Installation 1255B0000-04 00153	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
275234	Slat Ballscrew Actuator (Right, No. 3) - Backlash Check	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
275235	Slat Flexshaft No. 1 (Left) - Overhaul 4AS5130220-011 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
275236	Slat Flexshaft No. 1 (Right) - Overhaul 4AS5130220-011 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
275243	Slat Torque Limiter Brake Unit (Left) - Removal / Installation 1258A0000-02 00528	HRS AFL MOS MSC		757.3 461 31.9		 O/C	5643 3753 30 Nov 2022			0 0
Airframe										
275244	Slat Torque Limiter Brake Unit (Right) - Removal / Installation 1258A0000-02 00278	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
275245	Slat Torque Limiter (Left) - Overhaul 1258A0000-02 00335	HRS AFL MOS MSC		5091.1 3522 230		 O/C	1309.2 692 27 May 2006			0 0
Airframe										
Notes: PN = O-C										
275246	Slat Torque Limiter (Right) - Overhaul 1258A0000-02 00278	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
Notes: PN = O-C										
275247	Flap Ballscrew Actuator No. 1 (Left) - Removal / Installation 4AS5120211-005 00206	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
275248	Flap Ballscrew Actuator No. 1 (Right) - Removal / Installation 4AS5120211-005 00210	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
275249	Flap Ballscrew Actuator No. 2 (Left) - Removal / Installation 4AS5120212-005 00203	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
275250	Flap Ballscrew Actuator No. 2 (Right) - Removal / Installation 4AS5120212-005 00208	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
275251	Flap Ballscrew Actuator No. 3 (Left) - Removal / Installation 4AS5120213-005 00157	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
275252	Flap Ballscrew Actuator No. 3 (Right) - Removal / Installation 4AS5120213-006 00153	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
275253	Actuator, Slat Ballscrew No. 1 (Left) - Restore 4AS5130211-005 00201	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
275254	Actuator, Slat Ballscrew No. 1 (Right) - Restore 4AS5130211-005 00206	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
275255	Actuator, Slat Ballscrew No. 2 (Left) - Restore 4AS5130212-005 00207	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
275256	Actuator, Slat Ballscrew No. 2 (Right) - Restore 4AS5130212-005 00212	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
275257	Actuator, Slat Ballscrew No. 3 (Left) - Restore 4AS5130213-005 00150	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
275258	Actuator, Slat Ballscrew No. 3 (Right) - Restore 4AS5130213-006 00153	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
275259	Slat Flexible Shaft No. 1 (Left) - Removal / Installation 9148B0009-02 SN-UNKNOWN	HRS AFL MOS MSC		1732.7 1064 95.6		 O/C	4667.6 3150 09 Aug 2017			0 0 GULFSTREAM DALLAS
Airframe										
275260	Slat Flexible Shaft No. 1 (Right) - Removal / Installation 9148B0009-002 SN-UNKNOWN	HRS AFL MOS MSC		1732.7 1064 95.6		 O/C	4667.6 3150 09 Aug 2017			0 0 GULFSTREAM DALLAS
Airframe										
275261	Slat Flexible Shaft No. 2 (Left) - Removal / Installation 9148B0010-002 SN-UNKNOWN	HRS AFL MOS MSC		1732.7 1064 95.6		 O/C	4667.6 3150 09 Aug 2017			0 0
Airframe										
275262	Slat Flexible Shaft No. 2 (Right) - Removal / Installation 9148B0010-002 SN-UNKNOWN	HRS AFL MOS MSC		1732.7 1064 95.6		 O/C	4667.6 3150 09 Aug 2017			0 0
Airframe										
275263	Slat Flexible Shaft No. 3 (Left) - Removal / Installation 9148B0011-002 SN-UNKNOWN	HRS AFL MOS MSC		1732.7 1064 95.6		 O/C	4667.6 3150 09 Aug 2017			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
275264 Airframe	Slat Flexible Shaft No. 3 (Right) - Removal / Installation 9148B0011-002 SN-UNKNOWN	HRS AFL MOS MSC		1732.7 1064 95.6		 O/C	4667.6 3150 09 Aug 2017			0 0
275265 Airframe	Slat Flexible Shaft No. 4 (Left) - Removal / Installation 9148B0012-002 SN-UNKNOWN	HRS AFL MOS MSC		1732.7 1064 95.6		 O/C	4667.6 3150 09 Aug 2017			0 0
275266 Airframe	Slat Flexible Shaft No. 4 (Right) - Removal / Installation 9148B0012-002 SN-UNKNOWN	HRS AFL MOS MSC		1732.7 1064 95.6		 O/C	4667.6 3150 09 Aug 2017			0 0
275267 Airframe	Krueger Flap, Hinges and Actuator Attachments (Left) - General Visual Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		6400.3 4214 264.3		 72	0 0 18 Jul 2003	30 Jun 2027	31 Jul 2027	0 0
275268 Airframe	Krueger Flap, Hinges and Actuator Attachments (Right) - General Visual Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		6400.3 4214 264.3		 72	0 0 18 Jul 2003	30 Jun 2027	31 Jul 2027	0 0
275269 Airframe	Flaps and Slats Actuator Attach Points (Left) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]		157.9 100 9.8		4000 72	6242.4 4114 03 Oct 2024	10242.4 31 Oct 2030	10292.4 30 Nov 2030	0 0
275270 Airframe	Flaps and Slats Actuator Attach Points (Right) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]		157.9 100 9.8		4000 72	6242.4 4114 03 Oct 2024	10242.4 31 Oct 2030	10292.4 30 Nov 2030	0 0

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
276006	AIR Brake Selector Valve (Right) - Removal / Installation 70455-3	570	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe											
276007	AIR Brake Selector Valve (Left) - Removal / Installation 70455-3	573	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe											
276008	AIR Brake Actuator No. 1 (Left) - Removal / Installation 90-10191-02	F0543	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
276009	AIR Brake Actuator No. 1 (Right) - Removal / Installation 90-10191-02	F0547	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
276010	AIR Brake Actuator No. 2 (Left) - Removal / Installation 90-10191-02	F0548	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
276011	AIR Brake Actuator No. 2 (Right) - Removal / Installation 90-10191-02	F0549	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
276012	AIR Brake Actuator No. 3 (Left) - Removal / Installation 4AS7130060-005	F0451	HRS AFL MOS MSC		4787.6 3321 219		 O/C	1612.7 893 27 Apr 2007			0 0
Airframe											
276013	AIR Brake Actuator No. 3 (Right) - Removal / Installation 90-10191-02	F0561	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
276014	AIR Brake Actuator No. 4 (Left) - Removal / Installation 90-10191-02 F0562	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
276015	AIR Brake Actuator No. 4 (Right) - Removal / Installation 4AS7130060-005 F0644	HRS AFL MOS MSC		4787.6 3321 219		 O/C	1612.7 893 27 Apr 2007			0 0
Airframe										
276016	AIR Brakes System - Functional Test	HRS AFL MOS MSC		6372.3 4205 267.8		 O/C	28 9 03 Apr 2003			0 0
Airframe										
276027	AIR Brake - Operational Test	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
276029	AIR Brake Automatic Retraction - Operational Check	HRS AFL MOS		157.9 100 9.8	 -3	 24	6242.4 4114 03 Oct 2024	 30 Sep 2026*	 31 Oct 2026	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m]									
Notes: Jack Aircraft / Hyd Mule										
278001	Slat Systems - Functional Test	HRS AFL MOS MSC		6400.3 4214 265.1		 O/C	0 0 25 Jun 2003			0 0
Airframe										
278002	Slat (Left) - Removal / Installation 25W201001-457 007/068	HRS AFL MOS MSC		445.3 275 25.4		 O/C	5955 3939 15 Jun 2023			0 0
Airframe										
278003	Slat (Right) - Removal / Installation 25W201001-458 007/068	HRS AFL MOS MSC		445.3 275 25.4		 O/C	5955 3939 15 Jun 2023			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
278004	Slat System Bypass Function - Operational Check	HRS		157.9			6242.4			0
		AFL		100			4114			0
		MOS		9.8	-4	12	03 Oct 2024	30 Sep 2025*	31 Oct 2025	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: Hyd Mule										
278007	Slat Torque Limiter Brakes - Operational Test	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		265.1			25 Jun 2003			
Airframe		MSC				O/C				
278008	Torque Limiter - Removal / Installation 1258A0000-01 SN-UNKNOWN	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
278009	Slats Flex Shaft Free Rotation - Functional Test	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		265.1			25 Jun 2003			
Airframe		MSC				O/C				
278014	Slat Power Drive Unit - Detailed Inspection	HRS		757.3		1500	5643	7143	7193	0
		AFL		461			3753			0
		MOS		31.9			30 Nov 2022			
Airframe		[HRS: +50/-50]								
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
278019	Flaps / Slats Flexible Shafts - Servicing	HRS		5315.4			1084.9			0
		AFL		3658			556			0
		MOS		239.1			24 Aug 2005			
Airframe		MSC				O/C				
278040	Slat Power Drive Unit (Spdu) - Removal / Installation 1252A0000-01 00163	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			LIEBHERR-AEROSPACE SALINE CO.
Airframe		MSC				O/C				

28 - Fuel

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
281011	Fuel Tank Internal Surfaces (Non Metallic Parts) - Detailed Inspection	HRS								0
		AFL								0
		MOS				96		31 Aug 2027	30 Sep 2027	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: Per remarks, aligned with 531032										
281012	Fuel Tank External Surfaces (Non Metallic Parts) - Detailed Inspection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9		192	01 Aug 2002	31 Jul 2035	31 Aug 2035	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: Per remarks, aligned with 531034										
281013	Forward Fuel Tank Internal Surfaces (Tank Installed) - Detailed Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		25.9		96	01 Jun 2023	30 Jun 2031	31 Jul 2031	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
281015	Microbiological Contamination Test of Fuel Tank - Special Detailed Inspection	HRS		12.5			6387.8			0
		AFL		8			4206			0
		MOS		1.3	5	4	20 Jun 2025	31 Oct 2025*	30 Nov 2025	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
281101	Feed Tank Probe (263Q, Left) - Removal / Installation 020-990-007 0150	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
		MSC				O/C				
Airframe										
281102	Feed Tank Probe (264Q, Right) - Removal / Installation 020-990-007 0149	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
		MSC				O/C				
Airframe										
281103	Tank Unit 043-001-001 0091	HRS	TSN:5036.4	1363.9			5036.4			0
		AFL	TSN:3380	834			3380			0
		MOS	TSN:205	70.2			22 Sep 2019			N/A
		MSC				O/C				
Airframe										
Notes: PROCEDURE REFERENCE: 28-40-30: FUSELAGE TANK PROBE (273Q) — REMOVAL / INSTALLATION REVISION 22, DATED OCTOBER 31/11TW#562713 CAL 03/20										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
Logbook Position	Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW									
281104	Fuselage Fuel Tank - Removal / Installation 4AS3550200-510	89603	HRS AFL MOS MSC		1363.9 834 70.2		 O/C	5036.4 3380 23 Sep 2019			0 0 N/A
Airframe											
Notes: TW: 562713 CAL: 03/20TW: 567922 CAL: 04/20REF: OPEN/CLOSE CARDS FOR PANEL CLOSUREREF: 11.52 FOR FOLLOW ON ENGINE RUNS AND 29.8 FOR FUEL LEAK CHECK											
281105	Forward Fuel Tank - Removal / Installation 11-751796-2 (AMEND A)	075	HRS AFL MOS MSC	TSN:5036.4 TSN:3380 TSN:205	1363.9 834 70.6		 O/C	5036.4 3380 08 Sep 2019			0 0 N/A
Airframe											
Notes: TW: 557730 CAL: 10/19											
281106	Fuel Quantity Measurement Computer Wing Fuel Tank Units (249Q, Left Probe) - Removal / Installation 020-990-005	143	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
281107	Fuel Quantity Measurement Computer Wing Fuel Tank Units (250Q, Right Probe) - Removal / Installation 020-990-005	0144	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
281108	Fuel Quantity Measurement Computer Wing Fuel Tank Units (251Q, Left Probe) - Removal / Installation 020-990-001	133	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
281109	Fuel Quantity Measurement Computer Wing Fuel Tank Units (252Q, Right Probe) - Removal / Installation 020-990-001	0138	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
281110	Fuel Quantity Measurement Computer Wing Fuel Tank Units (253Q, Left Probe) - Removal / Installation 020-990-002	129	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
281111	Fuel Quantity Measurement Computer Wing Fuel Tank Units (254Q, Right Probe) - Removal / Installation 020-990-002 0143	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
281112	Fuel Quantity Measurement Computer Wing Fuel Tank Units (255Q, Left Probe) - Removal / Installation 020-990-003 141	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
281113	Fuel Quantity Measurement Computer Wing Fuel Tank Units (256Q, Right Probe) - Removal / Installation 020-990-003 0140	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
281114	Fuel Quantity Measurement Computer Wing Fuel Tank Units (257Q, Left Probe) - Removal / Installation 020-990-004 161	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
281115	Fuel Quantity Measurement Computer Wing Fuel Tank Units (258Q, Right Probe) - Removal / Installation 020-990-004 0172	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
281116	Fuel Quantity Measurement Computer Wing Fuel Tank Units (259Q, Left Compensator) - Removal / Installation 021-936-001 665	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
281117	Fuel Quantity Measurement Computer Wing Fuel Tank Units (260Q, Right Compensator) - Removal / Installation 021-936-001 654	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
281118	Tank Unit 020-990-006	174	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
281119	Tank Unit 020-990-006	0176	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
281120	Tank Unit 040-901-004	0065	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
281121	Tank Unit 040-901-005	0093	HRS AFL MOS MSC	TSN:5036.4 TSN:3380 TSN:205	1363.9 834 70.2		 O/C	5036.4 3380 22 Sep 2019			0 0 N/A
Airframe											
Notes: PROCEDURE REFERENCE: 28-40-30: FUSELAGE TANK PROBE (273Q) — REMOVAL / INSTALLATION REVISION 22, DATED OCTOBER 31/11TW#562713 CAL 03/20											
281155	Wing Tank Float Valves (Left, 51Q) - Detailed Inspection		HRS AFL MOS		1363.9 834 71.2	 -22	 96	5036.4 3380 22 Aug 2019	 31 Jul 2027*	 31 Aug 2027	0 0
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
281156	Wing Tank Float Valves (Right, 52Q) - Detailed Inspection		HRS AFL MOS		1363.9 834 71.2	 -22	 96	5036.4 3380 22 Aug 2019	 31 Jul 2027*	 31 Aug 2027	0 0
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
281501	Wing Tank Float Valve (51Q Left) - Removal / Installation V25W652004-505	599	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe											
281502	Wing Tank Float Valve (52Q Right) - Removal / Installation V25W652004-505	0598	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
281503	Float Vent Pump 102-0005-03 0071		HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
281504	Vent Jet Pump 101Q (Left) - Removal / Installation 2940059-101 0137		HRS AFL MOS MSC	TSN:5036.4 TSN:3380 TSN:205	1363.9 834 70.2		 O/C	5036.4 3380 22 Sep 2019			0 0 N/A
Airframe											
Notes: REFER TO ITEM 29.8 FOR LEAK CHECK											
281505	Vent Jet Pump 101Q (Right) - Removal / Installation 2940059-101 0142		HRS AFL MOS MSC	TSN:5036.4 TSN:3380 TSN:205	1363.9 834 70.2		 O/C	5036.4 3380 22 Sep 2019			0 0 N/A
Airframe											
282007	Fuel Interconnect Valve - Operational Test		HRS AFL MOS MSC		6400.3 4214 265.1		 O/C	0 0 25 Jun 2003			0 0
Airframe											
282008	Pilot Float Valve - Removal / Installation 5153-2 T071		HRS AFL MOS MSC	TSN:5036.4 TSN:3380 TSN:205	1363.9 834 70.2		 O/C	5036.4 3380 22 Sep 2019			0 0 N/A
Airframe											
Notes: TW: 562713 CAL: 03/20REF: 8.8 AND 11.52 FOR OPERATIONAL CHECK											
282009	Diverter, Fuel Flow 5207-1 T071		HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
282011	Fuel Balance - Check		HRS AFL MOS MSC		5315.4 3658 239.1		 N/A	1084.9 556 24 Aug 2005			0 0
Airframe											
Notes: REACTIVATED AND FREQ REMOVED. NO FREQ REQ"D FOR MSG3 AIRCRAFT GRH 17 NOV 10											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
282101	Refuel / Defuel Control Panel Assembly (283Q) - Removal / Installation 366-930-001 180	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										
282102	Refuel / Defuel Indicator (283QB) - Removal / Installation 366-931-001 176	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0 PARKER HANNIFIN CORPORATION
Airframe										
282110	Fuel/Defuel Panel Bit Test	HRS AFL MOS MSC		6362.3 4200 265.8		O/C	38 14 04 Jun 2003			0 0
Airframe										
282201	Valve, Inline Fuel Shut-Off (44Q) and Restrictor (42Q) - Removal / Installation 5200-1 079	HRS AFL MOS MSC	TSN:5036.4 TSN:3380 TSN:205	1363.9 834 70.2		O/C	5036.4 3380 21 Sep 2019			0 0 N/A
Airframe										
Notes: REF: 29.8 FOR LEAK CHECK										
282202	Engine Fuel Shut-Off Valve (13Q, Left) - Removal / Installation 4AS6520006-003 202263	HRS AFL MOS MSC	TSN:5036.4 TSN:3380 TSN:205	1363.9 834 70.2		O/C	5036.4 3380 23 Sep 2019			0 0 N/A
Airframe										
Notes: REF: 11.52 FOR FOLLOW ON OPS CHECK										
282203	Engine Fuel Shut-Off Valve (14Q, Right) - Removal / Installation 4AS6520006-003 20130	HRS AFL MOS MSC	TSN:5036.4 TSN:3380 TSN:205	1363.9 834 70.2		O/C	5036.4 3380 21 Sep 2019			0 0 N/A
Airframe										
Notes: REF 11.52 FOR OPS CHECK										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
282204 Airframe	Valve, Fuel Jettison Shut-Off (25Q) - Removal / Installation ZMV24 00612275	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
282205 Airframe	Valve, Engine FIRE Shutoff (13Q) {Left} ZMV24 11116432	HRS AFL MOS MSC		5491.9 3754 243.5		 O/C	908.4 460 12 Apr 2005			0 0 GULFSTREAM DALLAS
282206 Airframe	Valve, Engine FIRE Shutoff (14Q) {Right} ZMV24 10608172	HRS AFL MOS MSC		5491.9 3754 243.5		 O/C	908.4 460 12 Apr 2005			0 0 GULFSTREAM DALLAS
282207 Airframe	Valve, Fuel Jettison Shutoff (26Q) {Right} ZMV24 201305	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
282208 Airframe	Valve, APU FIRE Shut-Off (22Q) - Removal / Installation ZMV75 06-1220116	HRS AFL MOS MSC		1884.1 1180 119.4		 O/C	4516.2 3034 17 Aug 2015			0 0
282209 Airframe	Fuel FIRE Shut-Off Valve (13Q) - Operational Check (Post Sb 200-05-280)	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		157.9 100 9.8		 24	6242.4 4114 03 Oct 2024	31 Oct 2026	30 Nov 2026	0 0
282210 Airframe	Fuel FIRE Shut-Off Valve (14Q) - Operational Check (Post Sb 200-05-280)	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		157.9 100 9.8		 24	6242.4 4114 03 Oct 2024	31 Oct 2026	30 Nov 2026	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
282211 Airframe	APU FIRE Shut-Off Valve (22Q) - Operational Check (Post Sb 200-05-280) [End Of Month Item] [MOS: +1m/-1m]	HRS AFL MOS		157.9 100 9.8		 24	6242.4 4114 03 Oct 2024	 31 Oct 2026	 30 Nov 2026	0 0
282401 Airframe	Jet Pump, Forward Left (67Q) - Removal / Installation 2940058-101 0118	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
282402 Airframe	Jet Pump, Forward Right (66Q) - Removal / Installation 2940058-101 0120	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
282403 Airframe	Fuel Transfer Pump, Center (Left) - Removal / Installation 2940057-101 0151	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
282404 Airframe	Fuel Transfer Pump, Center (Right) - Removal / Installation 2940057-101 0144	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
282405 Airframe	Pump, Wing Jet (Left) - Removal / Installation 2940056-101 0131	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
282406 Airframe	Pump, Wing Jet (Right) - Removal / Installation 2940056-101 0135	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
282407	Wing Interconnect Valve (118Q) - Removal / Installation 4AS6520005-003 11116432	HRS AFL MOS MSC		5492.3 3754 243.6		 O/C	908 460 09 Apr 2005			0 0 KGS ELECTRONICS
Airframe										
282408	Feed Interconnect Valve (21Q) - Removal / Installation ZMV20 11210100	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 KGS ELECTRONICS
Airframe										
282601	Feed Booster Pump (Left 1Q) - Removal / Installation 2940055-101 0130	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
282602	Feed Booster Pump (Right 2Q) - Removal / Installation 2940055-101 0143	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
282603	Feed Pump, Left Standby (3Q) and Check Valve (137Q) - Removal / Installation 2C40-5 1BD4	HRS AFL MOS MSC		1363.9 834 69.6		 O/C	5036.4 3380 10 Oct 2019			0 0 N/A
Airframe										
Notes: TW# 561417 DUE CAL 11/19, REF. 8.11.4 FOR SEALANT CURE AND 8.11.5 FOR REFUEL AND LEAK CHECK OF ACCESS PANEL 143AZ										
282604	Feed Pump, Right Standby (4Q) and Check Valve (138Q) - Removal / Installation 2C40-5 8AU47	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
282605	Fuselage Jet Pump 2940060-101 0137	HRS AFL MOS MSC	TSN:5036.4 TSN:3380 TSN:205	1363.9 834 70.2		 O/C	5036.4 3380 22 Sep 2019			0 0 N/A
Airframe										
Notes: PROCEDURE REFERENCE: G200 AMM 28-10-10 REVISION 31 JUL 2017										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
282606 Airframe	Fuselage Jet Pump 2940060-101 0131	HRS AFL MOS MSC	TSN:5036.4 TSN:3380 TSN:205	1363.9 834 70.2		O/C	5036.4 3380 22 Sep 2019			0 0 N/A
Notes: PROCEDURE REFERENCE: G200 AMM 28-10-10 REVISION 31 JUL 2017										
283005 Airframe	Fuel Dump Valve (Left) - Operational Check	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71.3	-20	96	5036.4 3380 20 Aug 2019	31 Jul 2027*	31 Aug 2027	0 0
283006 Airframe	Fuel Dump Valve (Right) - Operational Check	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71.3	-20	96	5036.4 3380 20 Aug 2019	31 Jul 2027*	31 Aug 2027	0 0
284020 Airframe	Fuel Transfer and Feed Systems - Engine Run-Up Check	HRS AFL MOS MSC		117.2 71 5.6		O/C	6283.1 4143 10 Feb 2025			0 0
284087 Airframe	Fuel Quantity Measurement Computer Wing Fuel Tank Units (247Q, Left Low-Level Sensor) - Removal / Installation 041-901-001 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
284088 Airframe	Fuel Quantity Measurement Computer Wing Fuel Tank Units (248Q, Right Low-Level Sensor) - Removal / Installation 041-901-001 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
284089 Airframe	Center Fuel Tank Compensator (267Q) - Removal / Installation 041-901-001 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
284090	Fuel Quantity Measurement Computer Wing Fuel Tank Units (250Q, Right Probe) - Removal / Installation 041-901-001 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
284091	Fuel Quantity Measurement Computer Wing Fuel Tank Units (251Q, Left Probe) - Removal / Installation 041-901-001 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
284092	Fuel Quantity Measurement Computer Wing Fuel Tank Units (252Q, Right Probe) - Removal / Installation 041-901-001 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
284093	Fuel Quantity Measurement Computer Wing Fuel Tank Units (253Q, Left Probe) - Removal / Installation 041-901-001 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
284094	Fuel Quantity Measurement Computer Wing Fuel Tank Units (254Q, Right Probe) - Removal / Installation 041-901-001 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
284095	Fuel Quantity Measurement Computer Wing Fuel Tank Units (255Q, Left Probe) - Removal / Installation 041-901-001 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
284096	Fuel Quantity Measurement Computer Wing Fuel Tank Units (256Q, Right Probe) - Removal / Installation 041-901-001 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
284097	Fuel Quantity Measurement Computer Wing Fuel Tank Units (257Q, Left Probe) - Removal / Installation		HRS		6400.3			0			0
			AFL		4214			0			0
	041-901-001	SN-UNKNOWN	MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
284098	Fuel Quantity Measurement Computer Wing Fuel Tank Units (258Q, Right Probe) - Removal / Installation		HRS		6400.3			0			0
			AFL		4214			0			0
	041-901-001	SN-UNKNOWN	MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
284099	Fuel Quantity Measurement Computer Wing Fuel Tank Units (261Q, Left Probe) - Removal / Installation		HRS		6400.3			0			0
			AFL		4214			0			0
	041-901-001	SN-UNKNOWN	MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
284101	Fluid Quantity Management Computer (Fqmc) - Removal / Installation		HRS		6372.3			28			0
			AFL		4205			9			0
	4ASS8840001-003	0103	MOS		270			29 Jan 2003			
			MSC				O/C				
Airframe											
284102	Fuel Quantity Measurement Computer Wing Fuel Tank Units (262Q, Right Probe) - Removal / Installation		HRS		6400.3			0			0
			AFL		4214			0			0
	041-901-001	0096	MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
284103	Low Level Sensor		HRS		6400.3			0			0
	041-906-001	819	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
284104	Low Level Sensor		HRS		6400.3			0			0
	041-906-001	818	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
284110	Fluid Quantity Management Computer (Fqmc) - Bit Operational Check	HRS AFL MOS MSC		6372.3 4205 267		 O/C	28 9 27 Apr 2003			0 0
Airframe										
284201	Fuel Quantity Probe Wiring (Clamping Wire Separation) - Detailed Inspection	HRS AFL MOS		445.3 275 25.9		 48	5955 3939 01 Jun 2023	 30 Jun 2027	 31 Jul 2027	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: REFERENCE FOR INSPECTION CAN BE FOUND IN GA214686001 IN PDOCM										
284202	Fuel Quantity Probe Wiring (Sagging / Positive Separation) - Detailed Inspection	HRS AFL MOS		445.3 275 25.9		 48	5955 3939 01 Jun 2023	 30 Jun 2027	 31 Jul 2027	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: REFERENCE FOR INSPECTION CAN BE FOUND IN GA214686001 IN PDOCM										
284301	Fuel Temperature Detector (246Q) - Removal / Installation V25W652026-501 E0580	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
29 - Hydraulic Power										
290001	Hydraulic Fluid (Left) - Sampling	HRS AFL MOS MSC		5315.4 3658 239.1		 N/A	1084.9 556 24 Aug 2005			0 0
Airframe										
Notes: REACTIVATED AND FREQ REMOVED. NO FREQ REQ"D FOR MSG3 AIRCRAFT GRH 17 NOV 10										
290002	Hydraulic Fluid (Right) - Sampling	HRS AFL MOS MSC		5315.4 3658 239.1		 N/A	1084.9 556 24 Aug 2005			0 0
Airframe										
Notes: REACTIVATED AND FREQ REMOVED. NO FREQ REQ"D FOR MSG3 AIRCRAFT GRH 17 NOV 10										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
Logbook Position	Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW									
290007	Main Hydraulic Power System Filters (Left Return) - Functional Test		HRS AFL MOS MSC		5082.4 3518 227		 O/C	1317.9 696 29 Aug 2006			0 0
Airframe											
290008	Main Hydraulic Power System Filters (Right Return) - Functional Test		HRS AFL MOS MSC		5082.4 3518 227		 O/C	1317.9 696 29 Aug 2006			0 0
Airframe											
290009	Hydraulic System Reservior (Left) - Fluid Check		HRS AFL MOS MSC		4787.6 3321 219		 N/A	1612.7 893 27 Apr 2007			0 0
Airframe											
Notes: REACTIVATED AND FREQ REMOVED. NO FREQ REQ"D FOR MSG3 AIRCRAFT GRH 17 NOV 10											
290010	Hydraulic System Reservior (Right) - Fluid Check		HRS AFL MOS MSC		4787.6 3321 219		 N/A	1612.7 893 27 Apr 2007			0 0
Airframe											
Notes: REACTIVATED AND FREQ REMOVED. NO FREQ REQ"D FOR MSG3 AIRCRAFT GRH 17 NOV 10											
290025	Hydraulic System Filters and Filter Elements (Left Return) - Removal / Installation PN	NOT INSTALLED	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
290026	Hydraulic System Filters and Filter Elements (Right Return) - Removal / Installation AC-9607F-8	NSN	HRS AFL MOS MSC		817.9 494 35.5		 O/C	5582.4 3720 11 Aug 2022			0 0
Airframe											
291012	Main Hydraulic AIR Pressurization System - Purging		HRS AFL MOS [HRS: +50/-50]		445.3 275 25.7		1000 	5955 3939 06 Jun 2023	6955	7005	0 0 N/A
Airframe											
Notes: PN: 39645 SN: NSN.											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
291013 Airframe	Left FIRE Shut-Off Valve - Removal / Installation ZMV28 20122112	HRS AFL MOS MSC	TSN:10 TSN:5 TSN:5	6362.3 4200 266		O/C	38 14 28 May 2003			0 0 GULFSTREAM DALLAS
291014 Airframe	Right FIRE Shut-Off Valve - Removal / Installation 4AS7120140-001 2100386	HRS AFL MOS MSC		6362.3 4200 266		O/C	38 14 28 May 2003			0 0 GULFSTREAM DALLAS
291015 Airframe	Hydraulic System FIRE Shut-Off Valve - Operational Check (Post Sb 200-05-280)	HRS AFL MOS		445.3 275 26.2		4000 48	5955 3939 22 May 2023	9955 31 May 2027	10005 30 Jun 2027	0 0
	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									
291019 Airframe	Valve, Rotary Shutoff (Left) 341975 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
291020 Airframe	Valve, Rotary Shutoff (Right) 341975 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
291201 Airframe	Engine-Driven Pump (Left) - Removal / Installation 4018301 BR789A	HRS AFL MOS MSC	TSN:1928.6 TSN:1146	2378.1 1547 144.2		O/C	4022.2 2667 22 Jul 2013			0 0
291202 Airframe	Engine-Driven Pump (Right) - Removal / Installation 4018301 AH-6577A	HRS AFL MOS MSC	TSN:4570.9	2378.1 1547 144.2		O/C	4022.2 2667 22 Jul 2013			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
291301 Airframe	AIR Pressure Regulator - Removal / Installation 5115 385	HRS AFL MOS MSC		3104.7 2094 171.7		 O/C	3295.6 2120 07 Apr 2011			0 0
291302 Airframe	Bleed Valve (Left) - Removal / Installation HV50-17 1121758	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 CIRCLE SEAL CONTROLS INC
291303 Airframe	Bleed Valve (Right) - Removal / Installation HV50-17 04-0617521	HRS AFL MOS MSC		5389.9 3695 241.1		 O/C	1010.4 519 24 Jun 2005			0 0 CIRCLE SEAL CONTROLS INC
291304 Airframe	Hydraulic Pressure Transmitter (Left) - Removal / Installation IPTE16-1000-4000A 0087	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 KULITE SEMICONDUCTOR PRODUCTS INC
291601 Airframe	Left Hydraulic Reservoir - Removal / Installation 231-0012-07 0075	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
291602 Airframe	Right Hydraulic Reservoir - Removal / Installation 231-0014-07 0065	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
292001 Airframe	Electrical Motor Pump Brush Wear Sensor - Operational Check	HRS AFL MOS [HRS: +50/-50]	1053.8 664 45.8		-176.7	3000	5346.5 3550 04 Oct 2021	8169.8*	8219.8	0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
292101	Electrical Motor Pump - Removal / Installation 4211402 AK656	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0 ISRAEL AIRCRAFT INDUSTRIES
Airframe										
30 - Ice and Rain Protection										
300002	Ejector Flow Control Valve Heater Blanket (Forward) - Removal / Installation 3D3606-1 1074	HRS AFL MOS MSC		4787.6 3321 219.3		O/C	1612.7 893 20 Apr 2007			0 0 GOODRICH
Airframe										
300003	Ejector Flow Control Valve Heater Blanket (Aft) - Removal / Installation 3D3606-1/(4AS7870015-003) 1296	HRS AFL MOS MSC		4787.6 3321 219		O/C	1612.7 893 27 Apr 2007			0 0 GOODRICH
Airframe										
300004	Ejector Flow Control Valve (Efcv) Heater Blanket - Removal / Installation 3D3506-1 (4AS7870015-003) 1299	HRS AFL MOS MSC		4787.6 3321 219		O/C	1612.7 893 27 Apr 2007			0 0 GOODRICH
Airframe										
300010	Ejector Flow Control Valve Heater Blanket - Test	HRS AFL MOS MSC		2311.1 1492 139.5		O/C	4089.2 2722 12 Dec 2013			0 0
Airframe										
Notes: EJECTOR FLOW CONTROL HEAT BLANKET TEST C/W. NO DEFECTS NOTED. I/A/W G200 AMM 30-10-10 PAGE 501-506.										
301000	Airfoil De-Icing System - Leakage Test (With Engine Operating)	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
301001	Airfoil De-Icing System - Functional Test	HRS		1053.8			5346.5			0
		AFL		664			3550			0
		MOS		45.8			04 Oct 2021			
		MSC				N/A				
Airframe		[End Of Month Item]								
Notes: REF TO 16.23 FOR SQUAWK.										
301002	Pressure Regulator - Removal / Installation 4D2095-183 N0198	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
		MSC				O/C				
Airframe										
301003	Ejector Flow Control Valve (Forward Left) - Removal / Installation 3D2381-64 N041618	HRS		5603.3			797			0
		AFL		3809			405			0
		MOS		246.7			06 Jan 2005			GULFSTREAM
		MSC				O/C				DALLAS
Airframe										
301004	Ejector Flow Control Valve (Forward Right) - Removal / Installation 3D2381-64 N041866	HRS		5603.3			797			0
		AFL		3809			405			0
		MOS		246.7			06 Jan 2005			GULFSTREAM
		MSC				O/C				DALLAS
Airframe										
301006	Ejector Flow Control Valve (Aft) - Removal / Installation 3D2381-64 N288	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			GULFSTREAM
		MSC				O/C				DALLAS
Airframe										
301007	Black De-Icer Boots (Left Inboard Forward Leading Edge) - Removal / Installation 25S4D5139-17 NCI0360	HRS		1884.1			4516.2			0
		AFL		1180			3034			0
		MOS	TSN:9	118.9			31 Aug 2015			GULFSTREAM
		MSC				O/C				DALLAS
Airframe										
301008	Black De-Icer Boots (Right Inboard Forward Leading Edge) - Removal / Installation 255-405139-18 NCH3980	HRS		1884.1			4516.2			0
		AFL		1180			3034			0
		MOS	TSN:11	118.9			31 Aug 2015			GULFSTREAM
		MSC				O/C				DALLAS
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
301011	Black De-Icer Boots (Left Horizontal Stabilizer) - Removal / Installation 25S4D5139-21 NFY3690	HRS AFL MOS MSC	TSN:16	445.3 275 24.5		O/C	5955 3939 11 Jul 2023			0 0
Airframe										
301012	Black De-Icer Boots (Right Horizontal Stabilizer) - Removal / Installation 25S-4D5139-22 NET4150	HRS AFL MOS MSC	TSN:10	1363.9 834 69.4		O/C	5036.4 3380 15 Oct 2019			0 0 N/A
Airframe										
301013	Black De-Icer Boots (Left Krueger Flap) - Removal / Installation 25S4D5139-23 NCN4500	HRS AFL MOS MSC	TSN:8	1884.1 1180 118.8		O/C	4516.2 3034 02 Sep 2015			0 0 GULFSTREAM DALLAS
Airframe										
301014	Black De-Icer Boots (Right Krueger Flap) - Removal / Installation 25S4D5139-24 NDB6570	HRS AFL MOS MSC	TSN:1	1709.6 1051 93.8		O/C	4690.7 3163 02 Oct 2017			0 0 GULFSTREAM DALLAS
Airframe										
301016	Black De-Icer Boots (Left Slat) - Removal / Installation 25S-7D5139-15 NFK0190	HRS AFL MOS MSC	TSN:18	1053.8 664 45.8		O/C	5346.5 3550 04 Oct 2021			0 0
Airframe										
301017	Black De-Icer Boots (Right Slat) - Removal / Installation 25S-7D5139-16 NFF7270	HRS AFL MOS MSC	TSN:21	1053.8 664 45.8		O/C	5346.5 3550 04 Oct 2021			0 0
Airframe										
301021	De-Icing Timer (Main) - Removal / Installation 4D2037-04 U132	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
301022 Airframe	De-Icing Timer (Alternate) - Removal / Installation 4D2037-04 U137	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
301026 Airframe	De-Icing High-Pressure - Removal / Installation 3D3533-03 0064	HRS AFL MOS MSC	TSN:4922.4 TSN:3318 TSN:195	1477.9 896 79.9		 O/C	4922.4 3318 30 Nov 2018			0 0 GOODRICH
301027 Airframe	Switch, Low Pressure (Aircraft 004 - 100 Pre MOD G2-20133) - Removal / Installation 3D3552-01 166	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
301028 Airframe	De-Icer Pressure Switch (Left Krueger) - Removal / Installation 3D3533-01 1935	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
301029 Airframe	De-Icer Pressure Switch (Right Krueger) - Removal / Installation 3D3533-01 1966	HRS AFL MOS MSC	TSN:797 TSN:405 TSN:29	5603.3 3809 246.7		 O/C	797 405 06 Jan 2005			0 0 GULFSTREAM DALLAS
301030 Airframe	De-Icer Pressure Switch (Slats) - Removal / Installation 3D3533-01 1488	HRS AFL MOS MSC		5603.3 3809 246.7		 O/C	797 405 06 Jan 2005			0 0 GULFSTREAM DALLAS
301031 Airframe	De-Icer Pressure Switch (Horizontal Stabilizer) - Removal / Installation 3D3533-01 1956	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS

ATA / U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
301036	Bleed AIR Check Valve (Left) - Removal / Installation 3D3571-1 N092055	HRS AFL MOS MSC	TSN:11	3491.8 2388 183.1		O/C	2908.5 1826 25 Apr 2010			0 0
Airframe										
301038	Bleed AIR Check Valve - Operational Check	HRS AFL MOS		445.3 275 25.9	-46.5	3000	5955 3939 31 May 2023	8908.5*	8958.5	0 0
Airframe		[HRS: +50/-50]								
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
301039	High-Pressure Switch - Operational Check	HRS AFL MOS		1477.9 896 80.7		5000	4922.4 3318 06 Nov 2018	9922.4	9972.4	0 0
Airframe		[HRS: +50/-50]								
301041	De-Icer Boots - General Visual Inspection (Post Sb 200-05-280)	HRS AFL MOS		445.3 275 26.2		1000 48	5955 3939 23 May 2023	6955 31 May 2027	7005 30 Jun 2027	0 0
Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
301042	De-Icer Boots Surface Coating - Restore	HRS AFL MOS		296.2 192 19.4	38.9	1000	6104.1 4022 16 Dec 2023	7143*	7193	0 0
Airframe		[HRS: +50/-50]								
302001	Transponder, Engine Anti-Icing Pressure (Left) 12423 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										
302002	Transponder, Engine Anti-Icing Pressure (Right) 12423 7459-5-27	HRS AFL MOS MSC	TSN:23	3151.9 2123 172.5		O/C	3248.4 2091 11 Mar 2011			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
302005	Nacelle Pressure Regulating Shut-Off Valve (Left) - Removal / Installation		HRS		2749			3651.3			0
			AFL		1831			2383			0
	288D0211-5	0128	MOS		159.7			05 Apr 2012			NORDAM GROUP MANUFACTURING DIV
			MSC				O/C				
Airframe											
Notes: VALVE FAILED TO CLOSE											
302006	Nacelle Pressure Regulating Shut-Off Valve (Right) - Removal / Installation		HRS		3151.9			3248.4			0
			AFL		2123			2091			0
	288D0211-5	0287	MOS		172.5			11 Mar 2011			NORDAM GROUP MANUFACTURING DIV
			MSC				O/C				
Airframe											
Notes: ENGINE NACELLE ANTI-ICE LIGHT COMES ON WHEN VALVE WAS NOT ACTIVATED.											
302007	Nacelle Anti-Ice Pressure Sense Tube (Left) - Removal / Installation		HRS		6400.3			0			0
			AFL		4214			0			0
	266-0398-503	SN-UNKNOWN	MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
302008	Nacelle Anti-Ice Pressure Sense Tube (Right) - Removal / Installation		HRS		6400.3			0			0
			AFL		4214			0			0
	266-0398-505	SN-UNKNOWN	MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
302009	Aft Nacelle Anti-Ice Pressure Duct (Left) - Removal / Installation		HRS		6400.3			0			0
			AFL		4214			0			0
	266D0340-505	SN-UNKNOWN	MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
302010	Aft Nacelle Anti-Ice Pressure Duct (Right) - Removal / Installation		HRS		6400.3			0			0
			AFL		4214			0			0
	266D0340-508	SN-UNKNOWN	MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
302011	Forward Nacelle Anti-Ice Pressure Duct (Left) - Removal / Installation 266-0318-507 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
302012	Forward Nacelle Anti-Ice Pressure Duct (Right) - Removal / Installation 266-0318-507 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
302013	High Pressure Bleed Duct (Left) - Removal / Installation 266-0316-513 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
302014	High Pressure Bleed Duct (Right) - Removal / Installation 266-0316-515 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
302025	AIR Intakes Anti-Icing System - Functional Test	HRS AFL MOS MSC		1363.9 834 69.6		 O/C	5036.4 3380 09 Oct 2019			0 0
Airframe										
303010	Probes Heating System - Functional Test	HRS AFL MOS MSC		2066.4 1325 128.2		 O/C	4333.9 2889 22 Nov 2014			0 0
Airframe										
Notes: PROBES HEATING FUNCTIONAL TEST C/W. NO DEFECTS NOTED. I/A/W G200 CMP CODE 303010 PAGES 1-4.										
304001	Windshield Heating System - Functional Test	HRS AFL MOS MSC		4787.6 3321 219		 N/A	1612.7 893 27 Apr 2007			0 0
Airframe										
Notes: REACTIVATED AND FREQ REMOVED. NO FREQ REQ"D FOR MSG3 AIRCRAFT GRH 17 NOV 10										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
304002	Windshield Wiper Motor Converter (Left) - Removal / Installation		HRS		4373.4			2026.9			0
			AFL		3044			1170			0
	PERM REMOVED	PERM REMOVED	MOS		204.4			15 Jul 2008			
			MSC				O/C				
Airframe											
Notes: REMOVED PER G200 SB #200-30-331, CMP 973310											
304003	Windshield Wiper Motor Converter (Right) - Removal / Installation		HRS		4373.4			2026.9			0
			AFL		3044			1170			0
	PERM REMOVED	PERM REMOVED	MOS		204.4			15 Jul 2008			
			MSC				O/C				
Airframe											
Notes: REMOVED PER G200 SB #200-30-331, CMP 973310											
304004	Windshield Temperature Controller (Left Windshield) - Removal / Installation		HRS		157.9			6242.4			0
			AFL		100			4114			0
	SYLZ50993	485D	MOS		9.8			03 Oct 2024			
			MSC				O/C				
Airframe											
304005	Windshield Temperature Controller (Left Side Window) - Removal / Installation		HRS		157.9			6242.4			0
			AFL		100			4114			0
	SYLZ50993	498D	MOS		10.3			20 Sep 2024			
			MSC				O/C				
Airframe											
304006	Windshield Temperature Controller (Right Windshield) - Removal / Installation		HRS		146.1			6254.2			0
			AFL		89			4125			0
	SYLZ50993	1034D	MOS		9.1			25 Oct 2024			
			MSC				O/C				
Airframe											
304007	Windshield Temperature Controller (Right Side Window) - Removal / Installation		HRS		157.9			6242.4			0
			AFL		100			4114			0
	SYLZ50993	509D	MOS		10.3			20 Sep 2024			
			MSC				O/C				
Airframe											

ATA / U=Custom / Logbook Position	Description: Part Number / Serial Number; HW / SW; MM Ref; Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
304009	Wiper Blade (Pilot) - Removal / Installation PERM REMOVED PERM REMOVED	HRS AFL MOS MSC		4373.4 3044 204.4		 O/C	2026.9 1170 15 Jul 2008			0 0 AIRLIFT HYDRAULICS INCORPORATED
Airframe										
304010	Wiper Blade (Copilot) - Removal / Installation PERM REMOVED PERM REMOVED	HRS AFL MOS MSC		4373.4 3044 204.4		 O/C	2026.9 1170 15 Jul 2008			0 0 AIRLIFT HYDRAULICS INCORPORATED
Airframe										
Notes: REMOVED PER G200 SB #200-30-331, CMP 973310										
308001	Ice Detector (Left) - Removal / Installation 0871HR2 0208	HRS AFL MOS MSC		1671.2 1022 91.8		 O/C	4729.1 3192 02 Dec 2017			0 0
Airframe										
308002	Ice Detector (Right) - Removal / Installation 0871HR2 0339	HRS AFL MOS MSC		2311.1 1492 139.5		 O/C	4089.2 2722 12 Dec 2013			0 0 GULFSTREAM DALLAS
Airframe										
Notes: FAILS PREFLIGHT TEST AND 1 FAIL INFLIGHT.										
308010	Ice Detectors - Functional Test	HRS AFL MOS MSC		2311.1 1492 139.5		 O/C	4089.2 2722 12 Dec 2013			0 0
Airframe										
Notes: ICE DETECTORS FUNCTIONAL TEST C/W. NO DEFECTS NOTED. I/A/W G200 CMP CODE 308010 PAGE 1-2.										
31 - Indicating/Recording Systems										
311005	Left Instrument Panel - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
311010	Center Instrument Panel - Removal / Installation		HRS		6400.3			0			0
	PN	SN-UNKNOWN	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
311015	Right Instrument Panel		HRS		6400.3			0			0
	PN	SN-UNKNOWN	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
311020	Glareshield Instrument Panel - Removal / Installation		HRS		1363.9			5036.4			0
	NPN	NSN	AFL		834			3380			0
			MOS		70.2			23 Sep 2019			N/A
			MSC				O/C				
Airframe											
311025	Overhead Panel - Removal / Installation		HRS		6400.3			0			0
	PN	SN-UNKNOWN	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
311033	Overlay, Pedestal Panel		HRS		6400.3			0			0
	4AS3581320-509	NSN	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
311040	Standby Attitude Indicator Wiring Harness and Ground Points - General Visual Inspection		HRS		445.3			5955			0
			AFL		275			3939			0
			MOS		26.1			24 May 2023			
			MSC				O/C				
Airframe											
311041	Pilot Pfd Wiring Harness and Ground Points - General Visual Inspection		HRS		445.3			5955			0
			AFL		275			3939			0
			MOS		26.1			24 May 2023			
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
311042	Pilot Mfd Wiring Harness and Ground Points - General Visual Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.1			24 May 2023			
		MSC				O/C				
Airframe										
311043	Pilot Rsp Wiring Harness and Ground Points - General Visual Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.1			24 May 2023			
		MSC				O/C				
Airframe										
311044	Radio Altimeter Wiring Harness and Ground Points - Detailed Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71.2	-21	96	21 Aug 2019	31 Jul 2027*	31 Aug 2027	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: COMPLIED WITH CMP G200 311044 RADIO ALTIMETER WIRING HARNESS AND GROUND POINTS - DETAILED INSPECTION										
311045	Rtu 1 Wiring Harness and Ground Points - General Visual Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.1			24 May 2023			
		MSC				O/C				
Airframe										
311046	Rtu 2 Wiring Harness and Ground Points - General Visual Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.1			24 May 2023			
		MSC				O/C				
Airframe										
311047	Eicas Display Wiring Harness and Ground Points - General Visual Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.1			24 May 2023			
		MSC				O/C				
Airframe										
311048	CO-Pilot Mfd Wiring Harness and Ground Points - General Visual Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.1			24 May 2023			
		MSC				O/C				
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
311049 Airframe	CO-Pilot Pfd Wiring Harness and Ground Points - General Visual Inspection	HRS AFL MOS MSC		445.3 275 26.1		 O/C	5955 3939 24 May 2023			0 0
311050 Airframe	CO-Pilot Rsp Wiring Harness and Ground Points - General Visual Inspection	HRS AFL MOS MSC		445.3 275 26.1		 O/C	5955 3939 24 May 2023			0 0
312001 Airframe	Digital Clock (Pilot) - Removal / Installation M850 A7848	HRS AFL MOS MSC	TSN:964.8 TSN:585 TSN:52	399 249 23.4		 O/C	6001.3 3965 17 Aug 2023			0 0
312002 Airframe	Digital Clock (Copilot) - Removal / Installation M850 A7362	HRS AFL MOS MSC		399 249 23.4		 O/C	6001.3 3965 17 Aug 2023			0 0
312003 Airframe	Digital Clock Battery (Pilot) - Discard E90 NSN	HRS AFL MOS [End Of Month Item]		146.1 89 9.1		 12	6254.2 4125 25 Oct 2024	31 Oct 2025		0 0
312004 Airframe	Digital Clock Battery (CO-Pilot) - Discard E90 NSN	HRS AFL MOS [End Of Month Item]		146.1 89 9.1		 12	6254.2 4125 25 Oct 2024	31 Oct 2025		0 0
312010 Airframe	Digital Clocks - Adjustment / Test	HRS AFL MOS MSC		1179.9 732 58.5		 O/C	5220.4 3482 14 Sep 2020			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
313001 Logbook Position	Computer, Maintenance Diagnostic - Removal / Installation 522-9818-653 J6LP	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
313002	Data Base Unit (Dbu-4100) - Removal / Installation 822-2215-002 2YMBL	HRS AFL MOS MSC		1071.6 676 48.5		 O/C	5328.7 3538 12 Jul 2021			0 0
Airframe										
313100	Flight Data Recorder - Removal / Installation 980-4710-003 0356	HRS AFL MOS MSC		3023.6 2026 168.4		 O/C	3376.7 2188 15 Jul 2011			0 0
Airframe										
313103	Switch, Inertial (Flight Data Recorder (FDR)) 6895-D-3-X-4.4 3370-3384	HRS AFL MOS MSC		6372.3 4205 267.9		 O/C	28 9 31 Mar 2003			0 0
Airframe										
313107	FDR Underwater Locator Beacon Battery - Discard DK120 DU5393	HRS AFL MOS		445.3 275 25.9		 72	5955 3939 30 May 2023	28 Feb 2029		0 0
Airframe	[End Of Month Item]									EXPIRATION
Notes: The Underwater Locator Beacon (ULB) is installed on the FDR located in the aft fuselage, right side between FS 677.8 and FS 690.8 (17,217.0 and 17,547.0 mm) behind access door 310AB.										
313109	Potentiometer, Control Wheel Position - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
313110	Potentiometer, Control Column Position - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
313111	Potentiometer, Rudder Pedal Position - Removal / Installation		HRS		6400.3			0			0
			AFL		4214			0			0
	PN	SN-UNKNOWN	MOS		275.9			01 Aug 2002			GULFSTREAM
			MSC				O/C				DALLAS
Airframe											
313112	Aileron Position Potentiometer (Optional) - Removal / Installation		HRS		6400.3			0			0
			AFL		4214			0			0
	PN	SN-UNKNOWN	MOS		275.9			01 Aug 2002			GULFSTREAM
			MSC				O/C				DALLAS
Airframe											
313113	Potentiometer, Elevator Position - Removal / Installation		HRS		6400.3			0			0
	PN	SN-UNKNOWN	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			GULFSTREAM
			MSC				O/C				DALLAS
Airframe											
313114	Potentiometer, Rudder Position - Removal / Installation		HRS		6400.3			0			0
	PN	SN-UNKNOWN	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			GULFSTREAM
			MSC				O/C				DALLAS
Airframe											
313115	FDR Underwater Locator Beacon (FDR - Dukane) (Optional) - Removal / Installation		HRS		1732.7			4667.6			0
			AFL		1064			3150			0
	DK120	SC97542	MOS		95.6			09 Aug 2017			
			MSC				O/C				
Airframe											
Notes: The Underwater Locator Beacon (ULB) is installed on the FDR located in the aft fuselage, right side between FS 677.8 and FS 690.8 (17,217.0 and 17,547.0 mm) behind access door 310AB.											
313116	FDR Underwater Locator Beacon (Dukane) (Optional) - Functional Check		HRS		33.1			6367.2			0
			AFL		21			4193			0
			MOS		2.2		24	23 May 2025	31 May 2027		
			[End Of Month Item]								
Airframe											
Notes: COMPLIED WITH CMP G200 313116 FDR UNDERWATER LOCATOR BEACON (DUKANE) - FUNCTIONAL CHECKBATTERY EXP DATE: AUG 2023FLUKE 556106 CAL DUE 09/19											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
313117 Airframe	Switch, Impact - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
313118 Airframe	Inertial Impact Switch - Functional Test	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
313125 Airframe	FDR Underwater Locator Beacon - Cleaning	HRS AFL MOS [End Of Month Item]		33.1 21 2.2		24	6367.2 4193 23 May 2025	31 May 2027		0 0
313142 Airframe Notes: SET PER REV 19	FDR System (57 Parameter) (Optional) - Functional Test	HRS AFL MOS [MOS: +1m/-1m]		399 249 23.4	14	24	6001.3 3965 17 Aug 2023	31 Aug 2025*	30 Sep 2025	0 0
313151 Airframe	Flight Data Recorder (FDR) - Download and Analyse Whole Flight Recording (EASA EUROCAE)	HRS AFL MOS MSC		399 249 23.4		O/C	6001.3 3965 17 Aug 2023			0 0
313201 Airframe	Acquisition Unit, Digital Flight Data (Dfdau) - Removal / Installation 967-0320-001 0272	HRS AFL MOS MSC		5067 3506 226.6		O/C	1333.3 708 09 Sep 2006			0 0 HONEYWELL COMMERCIAL ELECTRONICS SYSTEMS
314001 Airframe	Data Concentration Unit - Removal / Installation 822-0838-003 2RKPN	HRS AFL MOS MSC		121.5 73 6.6		O/C	6278.8 4141 09 Jan 2025			0 0

ATA / U=Custom / Logbook Position	Description (Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s))	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
314010	Data Concentration Unit - Operational Check	HRS		3023.6			3376.7			0
		AFL		2026			2188			0
		MOS		168.4			16 Jul 2011			
Airframe		MSC				O/C				
315001	Cooling AIR Inlet Screen - Visual Inspection	HRS		445.3		1000	5955	6955	7005	0
		AFL		275			3939			0
		MOS		26.1			25 May 2023			
Airframe		[HRS: +50/-50]								
315010	Eicas - Operational Test	HRS		3407.3			2993			0
		AFL		2304			1910			0
		MOS		178.6			10 Sep 2010			
Airframe		MSC				O/C				
Notes: EICAS SYSTEM TEST C/W. NO DEFECTS NOTED. I/A/W G200 CMP CODE 315010 PAGES 3-20										
315015	Panel, Switch (Eicas)	HRS	TSN:28	6372.3			28			0
	4AS8144400-521 070	AFL	TSN:9	4205			9			0
		MOS	TSN:8	267.9			30 Mar 2003			
Airframe		MSC				O/C				
315020	Eicas Switch Panel - Operational Test	HRS		6372.3			28			0
		AFL		4205			9			0
		MOS		267			27 Apr 2003			
Airframe		MSC				O/C				
315101	Take-Off Warning System - Functional Test	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
316701	Xm Weather Data Antenna - Removal / Installation	HRS		3023.6			3376.7			0
	CI1420-1 NSN	AFL		2026			2188			0
		MOS		168.3			19 Jul 2011			
Airframe		MSC				O/C				
316705[U]	Xm Weather Components - Inspection	HRS		30.4			6369.9			0
		AFL		19			4195			0
		MOS		2.1		12	26 May 2025	31 May 2026		
Airframe		[End Of Month Item]								
Notes: Ref ICA attached for inspection details										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
32 - Landing Gear										
320004	Main Landing Gear Assembly - Visual Check	HRS		6061.3			339			0
		AFL		4043			171			0
		MOS		258.4			16 Jan 2004			
Airframe		MSC				O/C				
320010	Nose Landing Gear Tire Pressure - Servicing	HRS		117.2			6283.1			0
		AFL		71			4143			0
		MOS		5.6			10 Feb 2025			
Airframe		MSC				O/C				
320011	Main Landing Gear Assembly - Lubrication	HRS		5082.4			1317.9			0
		AFL		3518			696			0
		MOS		227			29 Aug 2006			
Airframe		MSC				O/C				
320012	Main Landing Gear Tire Pressure - Servicing	HRS		117.2			6283.1			0
		AFL		71			4143			0
		MOS		5.6			10 Feb 2025			
Airframe		MSC				O/C				
Notes: SERVICED #1 AND #4 WHEEL ASSEMBLIES. STAND OFF GAUGE: 560545 CAL DUE: 03/19TIRE GAUGE: 10593358 CAL DUE: 02/19										
320015	Main Landing Gear Shock Absorber - Servicing	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		25.9		48	01 Jun 2023	30 Jun 2027	31 Jul 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: TORQUE WRENCH S/N: 558036 CAL DATE DUE: 06/20STRUT GAUGE S/N: 574908 CAL DATE DUE: 02/20										
320020	Main Landing Gear Forward / Aft Uplocks - Visual Inspection	HRS		6061.3			339			0
		AFL		4043			171			0
		MOS		258.4			16 Jan 2004			
Airframe		MSC				O/C				
320025	Main Landing Gear Doors Mechanism - Visual Inspection	HRS		6061.3			339			0
		AFL		4043			171			0
		MOS		258.4			16 Jan 2004			
Airframe		MSC				O/C				

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
320101 Airframe	NLG 1 Nose Landing Gear Trunnion Attach Fittings - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
320102 Airframe	NLG 2 Nose Landing Gear Drag Brace Attach Fittings - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
320103 Airframe	MLG 1 Main Landing Gear Side Brace Supporting Structure - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
320104 Airframe	MLG 2 Main Landing Gear Trunnion Attach Fitting on Rear Spar - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
320105 Airframe	MLG 3 Main Landing Gear Trunnion Attach Fitting on Center Spar - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
321001 Airframe	Main Landing Gear (Left) - Removal / Installation 4AS2520100-505 IL-071	HRS AFL MOS MSC		1709.6 1051 93.8		O/C	4690.7 3163 04 Oct 2017			0 0
321002 Airframe	Main Landing Gear (Right) - Removal / Installation 4AS2520100-506 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
321003	Main Landing Gear Hydraulic Actuator (Left) - Removal / Installation 26300-000-05 IL-113A	HRS AFL MOS MSC	TSN:3974.1 TSN:2090	1736.4 1065 104.2		 O/C	4663.9 3149 22 Nov 2016			0 0 SHL DIVISION
Airframe										
321004	Main Landing Gear Hydraulic Actuator (Right) - Removal / Installation 27300-000-04 IL-169	HRS AFL MOS MSC	TSN:484.4 TSN:225	4417.5 3074 206.7		 O/C	1982.8 1140 07 May 2008			0 0 SHL DIVISION
Airframe										
321005	Main Landing Gear Uplock Actuator (Left Forward) - Removal / Installation 4A1000 0133	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
321006	Main Landing Gear Uplock Actuator (Right Forward) - Removal / Installation 4A1000 C4309	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
321007	Main Landing Gear Uplock Actuator (Left Aft) - Removal / Installation 4A1001 0148	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
321008	Main Landing Gear Uplock Actuator (Right Aft) - Removal / Installation 4A1001 0147	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
321019	Main Landing Gear (Left) - Disassembly / Assembly 26100-100-00 IL071	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
321020 Airframe	Main Landing Gear (Right) - Disassembly / Assembly 27100-100-00 IL069	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
321021 Airframe	Main Landing Gear Shock Strut Assembly (Left) - Discard 26100-100-00 IL071	HRS AFL MOS		6400.3 4214 275.9		17500	0 0 01 Aug 2002	17500		0 0
321022 Airframe	Main Landing Gear Shock Strut Assembly (Right) - Discard 27100-100-00 IL069	HRS AFL MOS		6400.3 4214 275.9		17500	0 0 01 Aug 2002	17500		0 0
321023 Airframe	Main Landing Gear AREA Components (Left) - Detailed Inspection	HRS AFL MOS		445.3 275 26.1		1000 48	5955 3939 25 May 2023	6955 31 May 2027	7005 30 Jun 2027	0 0
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
321024 Airframe	Main Landing Gear AREA Components (Right) - Detailed Inspection	HRS AFL MOS		445.3 275 26.1		1000 48	5955 3939 25 May 2023	6955 31 May 2027	7005 30 Jun 2027	0 0
		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
321025 Airframe	Main Landing Gear Shock Absorber (Left) - Discard 26200-000-01 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		17500	0 0 01 Aug 2002	17500		0 0
321026 Airframe	Main Landing Gear Shock Absorber (Right) - Discard 26200-100-00 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		17500	0 0 01 Aug 2002	17500		0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
321027 Airframe	Main Landing Gear Actuator (Left) - Discard 26300-000-XX SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		17500	0 0 01 Aug 2002	17500		0 0
321028 Airframe	Main Landing Gear Actuator (Right) - Discard 27300-000-XX SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		17500	0 0 01 Aug 2002	17500		0 0
321029 Airframe	Main Landing Gear Actuator Attachment Bushing (Left) - Discard 4AS2530005-001 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		17500	0 0 01 Aug 2002	17500		0 0
321030 Airframe	Main Landing Gear Actuator Attachment Bushing (Right) - Discard 4AS2530005-001 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		17500	0 0 01 Aug 2002	17500		0 0
321031 Airframe	Main Landing Gear Actuator Attachment Pin (Left) - Discard 4AS2530004-001 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		17500	0 0 01 Aug 2002	17500		0 0
321032 Airframe	Main Landing Gear Actuator Attachment Pin (Right) - Discard 4AS2530004-001 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		17500	0 0 01 Aug 2002	17500		0 0
321033 Airframe	Main Landing Gear Trunnion Pin (Left Forward) - Discard 26022-000-00 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		17500	0 0 01 Aug 2002	17500		0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
321034	Main Landing Gear Trunnion Pin (Right Forward) - Discard 26022-000-00 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		17500	0 0 01 Aug 2002	17500		0 0
Airframe										
321035	Main Landing Gear Trunnion Pin (Left Aft) - Discard 26021-000-00 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		17500	0 0 01 Aug 2002	17500		0 0
Airframe										
321036	Main Landing Gear Trunnion Pin (Right Aft) - Discard 26021-000-00 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		17500	0 0 01 Aug 2002	17500		0 0
Airframe										
321041	Main Landing Gear Lower Shock Absorber Attachment Cross Bolt (Left) - Discard NAS6204-34D N/A	HRS AFL MOS		445.3 275 25.9		800	5955 3939 30 May 2023	4739		0 0
Airframe										
321042	Main Landing Gear Lower Shock Absorber Attachment Cross Bolt (Right) - Discard NAS6204-34D NSN	HRS AFL MOS		117.2 71 5.6		800	6283.1 4143 10 Feb 2025	4943		0 0
Airframe										
Notes: ADDED CODE AND SET TO GEAR LUBE SCHED PER REV 17										
321051	Main Landing Gear Hydraulic Actuator (Left) - Draining	HRS AFL MOS		296.2 192 19.8	38.9	500	6104.1 4022 04 Dec 2023	6643*	6693	0 0
Airframe		[HRS: +50/-50]								
Notes: TW: 562028DUE DATE:09/19										
321052	Main Landing Gear Hydraulic Actuator (Right) - Draining	HRS AFL MOS		296.2 192 19.7	38.9	500	6104.1 4022 05 Dec 2023	6643*	6693	0 0
Airframe		[HRS: +50/-50]								
Notes: TW: 562028DUE DATE:09/19										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
321303	Main Landing Gear Trailing Link Assembly (Left) - Discard 26125-000-00 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		 17500	0 0 01 Aug 2002	 17500		0 0
Airframe										
321304	Main Landing Gear Trailing Link Assembly (Right) - Discard 27125-000-00 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		 17500	0 0 01 Aug 2002	 17500		0 0
Airframe										
321307	Main Landing Gear Trailing Link Pin (Left) - Discard 26023-000-00 330	HRS AFL MOS	 TSN:1	1709.6 1051 93.8		 17500	4690.7 3163 04 Oct 2017	 20663		0 0
Airframe										
321308	Main Landing Gear Trailing Link Pin (Right) - Discard 26023-000-00 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		 17500	0 0 01 Aug 2002	 17500		0 0
Airframe										
321601	Harness, Main Landing Gear (Left) PN NOT INSTALLED	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
321602	Harness, Main Landing Gear (Right) 27380-003-01 R1158	HRS AFL MOS MSC		4372.7 3043 204.2		 O/C	2027.6 1171 23 Jul 2008			0 0 GULFSTREAM DALLAS
Airframe										
321611	Harness, Main Landing Gear (MLG) Downlock (Left) 26380-000-01 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
321612	Harness, Main Landing Gear (MLG) Downlock (Right) 27380-000-01 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
322002 Airframe	Nose Landing Gear - Removal / Installation 4AS2710000-501 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
322003 Airframe	Nose Landing Gear Assembly - Lubrication	HRS AFL MOS MSC		4515.3 3136 209.1		 O/C	1885 1078 26 Feb 2008			0 0
322004 Airframe	Nose Landing Gear Attach Points - Visual Inspection	HRS AFL MOS MSC		6061.3 4043 258.4		 O/C	339 171 16 Jan 2004			0 0
322005 Airframe	Nose Landing Gear Shock Absorber - Servicing [End Of Month Item] [MOS: +1m/-1m]	HRS AFL MOS		445.3 275 25.9		 48	5955 3939 01 Jun 2023	30 Jun 2027	31 Jul 2027	0 0
Notes: TORQUE WRENCH S/N: 558036 CAL DATE DUE: 06/20STRUT GAUGE S/N: 574908 CAL DATE DUE: 02/20										
322006 Airframe	Nose Landing Gear Uplock / Downlock - Visual Inspection	HRS AFL MOS MSC		5699.3 3867 250.1		 O/C	701 347 26 Sep 2004			0 0
322007 Airframe	Nose Landing Gear Door Mechanism - Visual Inspection	HRS AFL MOS MSC		5699.3 3867 250.1		 O/C	701 347 26 Sep 2004			0 0
322008 Airframe	Nose Landing Gear Hydraulic Actuator - Removal / Installation 28300-000-00 IL-075A	HRS AFL MOS MSC	TSN:1317.9 TSN:696	5082.4 3518 227		 O/C	1317.9 696 29 Aug 2006			0 0 GULFSTREAM DALLAS

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
322009	Nose Landing Gear Uplock Assembly - Removal / Installation 28400-000-00 IL077	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
322016	Nose Landing Gear Shock Absorber - Removal / Installation 28100-100-00 IL071	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
322017	Nose Landing Gear AREA Components - Detailed Inspection	HRS AFL MOS		445.3 275 26.1		1000 48	5955 3939 25 May 2023	6955 31 May 2027	7005 30 Jun 2027	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									
322018	Nose Landing Gear Shock Absorber - Discard 2710000 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		 20000 	0 0 01 Aug 2002	 20000 		0 0 GULFSTREAM DALLAS
Airframe										
322021	Nose Landing Gear Drag Brace Assembly - Discard 28200-000-00 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		 20000 	0 0 01 Aug 2002	 20000 		0 0
Airframe										
322023	Nose Landing Gear Drag Brace Trunnion Pin (Left) - Discard 23211-000-00 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		 20000 	0 0 01 Aug 2002	 20000 		0 0
Airframe										
322024	Nose Landing Gear Drag Brace Trunnion Pin (Right) - Discard 23211-000-00 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		 20000 	0 0 01 Aug 2002	 20000 		0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
322029 Airframe	Nose Landing Gear Upper Torque Link Pin - Removal / Installation 23343-000-00 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
322030 Airframe	Nose Landing Gear Torque Link Pin (Lower) - Discard 23343-000-00 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		 20000 	0 0 01 Aug 2002	 20000 		0 0
322031 Airframe	Nose Landing Gear Upper Torque Link - Removal / Installation 28190-000-00 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
322032 Airframe	Nose Landing Gear Upper Torque Link - Discard 28190-000-00 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		 20000 	0 0 01 Aug 2002	 20000 		0 0
322033 Airframe	Nose Landing Gear Lower Torque Link - Removal / Installation 23115-000-00 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
322034 Airframe	Nose Landing Gear Lower Torque Link - Discard 23115-000-00 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		 20000 	0 0 01 Aug 2002	 20000 		0 0
322035 Airframe	Nose Landing Gear Torque Link Pin - Removal / Installation 23343-000-00 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
322036	Nose Landing Gear Torque Link Pin (Upper) - Discard 23343-000-00 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		20000	0 0 01 Aug 2002	20000		0 0
Airframe										
322052	Nose Landing Gear Drag Brace Strut Pin - Discard 23202-000-00 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		20000	0 0 01 Aug 2002	20000		0 0
Airframe										
322057	Nose Landing Gear Strut Trunnion Pin (Left) - Discard 28113-000-01 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		20000	0 0 01 Aug 2002	20000		0 0
Airframe										
322058	Nose Landing Gear Strut Trunnion Pin (Right) - Discard 28113-000-01 SN-UNKNOWN	HRS AFL MOS		6400.3 4214 275.9		20000	0 0 01 Aug 2002	20000		0 0
Airframe										
323001	Landing Gear Extension and Retraction - Normal Functional Test	HRS AFL MOS MSC		1179.9 732 55.5		N/A	5220.4 3482 13 Dec 2020			0 0
Airframe										
323002	Landing Gear Selector Valve - Removal / Installation 4017 IL071	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										
323003	Emergency Dump Valve - Removal / Installation 283279-0001 REV-F 321	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										
323004	Emergency Extension Bottle - Removal / Installation PN NOT INSTALLED	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
323005 Airframe	Emergency Selector Valve - Removal / Installation 2381228 33	HRS AFL MOS MSC		5491.9 3754 243.7		 O/C	908.4 460 06 Apr 2005			0 0
323007 Airframe	Actuator, MLG Side Brace (Left) - Restore	HRS AFL MOS MSC		6372.3 4205 268.8		 O/C	28 9 03 Mar 2003			0 0
Notes: PN: 26300-000-04 SN: IL085. NO FREQUENCY AS -04 INSTALLED										
323008 Airframe	Actuator, MLG Side Brace (Right) - Restore	HRS AFL MOS MSC		6372.3 4205 268.8		 O/C	28 9 03 Mar 2003			0 0
Notes: PN: 27300-000-04 SN: IL-084. NO FREQUENCY AS -04 INSTALLED										
323009 Airframe	Emergency Landing Gear System - Functional Check (Post Sb 200-05-280) (Cmr**)	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]		343.7 211 21.6		2000 36	6056.6 4003 10 Oct 2023	8056.6 31 Oct 2026	8106.6 30 Nov 2026	0 0
323010 Airframe	Downlock Solenoid / Override Switch - Operational Check	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		343.7 211 21.6		 36	6056.6 4003 10 Oct 2023	 31 Oct 2026	 30 Nov 2026	0 0
323015 Airframe	Main Landing Gear Uplock Roller Assembly (Left) - Detailed Inspection	HRS AFL MOS [HRS: +50/-50]		296.2 192 19.8	38.9	500 	6104.1 4022 02 Dec 2023	6643* 	6693 	0 0
323016 Airframe	Main Landing Gear Uplock Roller Assembly (Right) - Detailed Inspection	HRS AFL MOS [HRS: +50/-50]		296.2 192 19.8	38.9	500 	6104.1 4022 02 Dec 2023	6643* 	6693 	0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
323902	Landing Gear Emergency Extension Bottle - Removal / Installation 41004563-1 00089	HRS AFL MOS MSC		157.9 100 9.8		 O/C	6242.4 4114 03 Oct 2024			0 0
Airframe										
323903	Accumulated Water Drain - Inspection	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
323904	Landing Gear Emergency Extension Bottle - Hydrostatic Test	HRS AFL MOS [End Of Month Item]		157.9 100 9.8		 36	6242.4 4114 03 Oct 2024	 30 Sep 2027		0 0 HYDRO CHECK
Airframe										
Notes: Jack Aircraft / Hyd Mule										
323907	Landing Gear Emergency Extension Bottle - Discard 41004563-1 00089	HRS AFL MOS [End Of Month Item]		1884.1 1180 119.9		 288	4516.2 3034 30 Jul 2015	 31 Jul 2030		0 0 IAI PARTNERSHIP MANUFACTURE
Airframe										
Notes: DATA FROM CODE 323902 TAGS										
324002	Power Brake Valve - Removal / Installation 6006883-6 MAY00-0033	HRS AFL MOS MSC		4704 3259 214.3		 O/C	1696.3 955 18 Sep 2007			0 0 AIRCRAFT BRAKING SYSTEMS
Airframe										
324003	Valve, Antiskid Control (Left) - Removal / Installation 6006882 NOV01-0140	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										

ATA U=Custom / Logbook Position	Description	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
324004	Valve, Antiskid Control (Right) - Removal / Installation Part Number: 6006882 Serial Number: DEC01-0147 HW: SW: MM Ref: Ops Number(s):	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
324005	Normal Brake System - Bleeding	HRS AFL MOS MSC		954 598 40.3		 O/C	5446.3 3616 19 Mar 2022			0 0
Airframe										
324007	Hydraulic Fuse and Shuttle Valve Module (Left) - Removal / Installation Part Number: 6006881-2 Serial Number: JAN02-0161	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
324008	Hydraulic Fuse and Shuttle Valve Module (Right) - Removal / Installation Part Number: 6006881-2 Serial Number: FEB02-0168	HRS AFL MOS MSC		3023.6 2026 168.6		 O/C	3376.7 2188 08 Jul 2011			0 0 GULFSTREAM DALLAS
Airframe										
324010	Tire Wear - Visual Inspection	HRS AFL MOS MSC		6061.3 4043 258.3		 O/C	339 171 20 Jan 2004			0 0
Airframe										
324011	Parking Valve - Removal / Installation Part Number: ZMV81 Serial Number: 20118157	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										
324012	Emergency Brake Valve - Removal / Installation Part Number: 4022 Serial Number: IL020	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
324013	Emergency Brake Accumulator - Removal / Installation 2770571-103 EFS1058A	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
324014	Parking Brake Accumulator - Removal / Installation 2770571-103 EFS1059A	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
324015	Pressure Release Valve - Removal / Installation 3464 IL289	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
324016	Valve, Release 3464 IL299	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
324017	Normal Brakes - Functional Test	HRS AFL MOS MSC		954 598 40.3		 O/C	5446.3 3616 19 Mar 2022			0 0
Airframe										
324018	Hydraulic Fuse and Shuttle Valve Module - Functional Check	HRS AFL MOS		157.9 100 9.8		 24	6242.4 4114 03 Oct 2024	 31 Oct 2026	 30 Nov 2026	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m]									
324019	Brake Wear Indicator - Detailed Inspection	HRS AFL MOS		296.2 192 19.8	38.9	500	6104.1 4022 04 Dec 2023	6643*	6693	0 0
Airframe	[HRS: +50/-50]									
Notes: BRAKE ASSEMBLY#1: 11/32"#2: 1/2"#3: 1/2"#4: 1/8"										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
324020	Emergency Brakes - Operational Check	HRS		1179.9		2000	5220.4	7220.4	7270.4	0
		AFL		732			3482			0
		MOS		57.9			30 Sep 2020			
Airframe		[HRS: +50/-50]								
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
324021	Emergency Brake Accumulator - Restore 2770571-103 EFS1058A	HRS		6400.3			0			0
		AFL		4214		5000	0	5000		0
		MOS		275.9			01 Aug 2002			
Airframe										
324022	Parking Brake Accumulator - Restore 2770571-103 EFS1059A	HRS		6400.3			0			0
		AFL		4214		5000	0	5000		0
		MOS		275.9			01 Aug 2002			
Airframe										
Notes: P/N CORRECTED 24 JUN 10										
324046	Power Brake Valve Linkage - General Visual Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71.2	-21	96	21 Aug 2019	31 Jul 2027*	31 Aug 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
324051	Main Wheel and Tire Assembly (Left Outboard) - Removal / Installation 5009029 JUN10-2860	HRS		117.2			6283.1			0
		AFL		71			4143			0
		MOS		5.6			10 Feb 2025			
		MSC				O/C				
Airframe										
324052	Main Wheel and Tire Assembly (Left Inboard) - Removal / Installation 5009029 FEB02-1719	HRS		117.2			6283.1			0
		AFL		71			4143			0
		MOS		5.6			10 Feb 2025			
		MSC				O/C				
Airframe										
324053	Main Wheel and Tire Assembly (Right Inboard) - Removal / Installation 5009029 MAR01868	HRS		117.2			6283.1			0
		AFL		71			4143			0
		MOS		5.6			10 Feb 2025			
		MSC				O/C				
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
324054 Airframe	Main Wheel and Tire Assembly (Right Outboard) - Removal / Installation 5009029 MAR04-1860	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
324061 Airframe	Nose Wheel and Tire Assembly (Left) - Removal / Installation 501062 FEB08-6954	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
324062 Airframe	Nose Wheel and Tire Assembly (Right) - Removal / Installation 5010598 MAY08-7070	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
324101 Airframe	Nose Wheel (Left) - Removal / Installation 4AS2760100-501 FE08-6954	HRS AFL MOS MSC		913.9 568 38.8		 O/C	5486.4 3646 04 May 2022			0 0
324102 Airframe	Nose Wheel (Right) - Removal / Installation 4AS2760100-501 MAY08-7070	HRS AFL MOS MSC		913.9 568 38.8		 O/C	5486.4 3646 04 May 2022			0 0
324103 Airframe	Nose Tire (Left) - Removal / Installation 031-613-4 3118T00317	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
324104 Airframe	Nose Tire (Right) - Removal / Installation 031-613-4 3120T00281	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
324107	Landing Gear Wheels - Visual Inspection	HRS		506.3			5894			0
		AFL		322			3892			0
		MOS		27.8			03 Apr 2023			
		MSC				N/A				
Airframe										
324111	Nose Wheel Assembly (Left) - Special Detailed Inspection (Ndt)	HRS		117.2			6283.1			0
		AFL		71			4143			0
		MOS		5.6			10 Feb 2025			
		MSC				O/C				
Airframe										
Notes: LEFT NOSE WHEEL NDT PERFORMED BY COSGROVE AIRCRAFT SERVICES CRS# FE1R136K W/O# 54316 DATED 01/12/15. NO DEFECTS NOTED.										
324112	Nose Wheel Assembly (Right) - Special Detailed Inspection (Ndt)	HRS		117.2			6283.1			0
		AFL		71			4143			0
		MOS		5.6			10 Feb 2025			
		MSC				O/C				
Airframe										
Notes: RIGHT NOSE WHEEL NDT PERFORMED BY COSGROVE AIRCRAFT SERVICES CRS# FE1R136K W/O# 54317 DATED 01/12/15. NO DEFECTS NOTED.										
324115	Nose Wheel Assembly (Left) - Overhaul 4AS2760100-501 FEB08-6954	HRS		913.9			5486.4			0
		AFL		568			3646			0
		MOS		38.8			04 May 2022			
		MSC				O/C				
Airframe										
Notes: ADDED PER REV 17										
324116	Nose Wheel Assembly (Right) - Overhaul 4AS2760100-501 MAY08-7070	HRS		913.9			5486.4			0
		AFL		568			3646			0
		MOS		38.8			04 May 2022			
		MSC				O/C				
Airframe										
Notes: ADDED PER REV 17										
324201	Main Wheel (Left Outboard) - Removal / Installation 5009029 JUN10-2860	HRS		545.1			5855.2			0
		AFL		346			3868			0
		MOS		28.2			22 Mar 2023			
		MSC				O/C				
Airframe										
324202	Main Wheel (Left Inboard) - Removal / Installation 5009029 FEB02-1719	HRS		805.6			5594.7			0
		AFL		488			3726			0
		MOS		35.1			25 Aug 2022			
		MSC				O/C				
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
324203	Main Wheel (Right Inboard) - Removal / Installation 5009029 MAR04-1868	HRS AFL MOS MSC		506.3 322 27.8		 O/C	5894 3892 03 Apr 2023			0 0
Airframe										
Notes: REMOVED #3 WHEEL ASSY. DUE TO TIRE WEAR. INSTALLED OVERHAULED WHEEL ASSY. WHEEL ASSY. OVERHAULED BY COSGROVE AIRCRAFT SERVICES.CRS FE1R136K WO # 55532 DATED 26 OCT 2015 IAW G200 CMP 324203										
324204	Main Wheel (Right Outboard) - Removal / Installation 5009029 MAR04-1860	HRS AFL MOS MSC		545.1 346 28.2		 O/C	5855.2 3868 22 Mar 2023			0 0
Airframe										
324205	Main Tire (Left Outboard) - Removal / Installation M08401 4073T182	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
Airframe										
324206	Main Tire (Left Inboard) - Removal / Installation M08401 4070T283	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
Airframe										
324207	Main Tire (Right Inboard) - Removal / Installation M08401 4072T389	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
Airframe										
Notes: NEW MICHELLIN TIRE INTALLED ON OVERHAULED WHEEL ASSY. SN: DEC04-1943, BY COSGROVE AIRCRAFT SERVICES CRS# FE1R136K, WO# 55532 DATED 26OCT2015.										
324208	Main Tire (Right Outboard) - Removal / Installation M08401 4154T365	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
Airframe										
324211	Main Wheel Assembly (Left Outboard) - Special Detailed Inspection (Ndt)	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
Airframe										
Notes: NDT PERFORMED BY COSGROVE AIRCRAFT SERVICES CRS# FE1R136K W/O# 53768 DATED 09/15/14. NO DEFECTS NOTED.										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
324212	Main Wheel Assembly (Left Inboard) - Special Detailed Inspection (Ndt)	HRS		117.2			6283.1			0
		AFL		71			4143			0
		MOS		5.6			10 Feb 2025			
		MSC				O/C				
Airframe										
324213	Main Wheel Assembly (Right Inboard) - Special Detailed Inspection (Ndt)	HRS		117.2			6283.1			0
		AFL		71			4143			0
		MOS		5.6			10 Feb 2025			
		MSC				O/C				
Airframe										
Notes: MAIN WHEEL ASSY. SPECIAL DETAILED INSPECTION PERFORMED BY COSGROVE AIRCRAFT SERVICES CRS# FE1R136K W/O# 55532 DATED 26 OCT 2015. NO DEFECTS NOTED.										
324214	Main Wheel Assembly (Right Outboard) - Special Detailed Inspection (Ndt)	HRS		117.2			6283.1			0
		AFL		71			4143			0
		MOS		5.6			10 Feb 2025			
		MSC				O/C				
Airframe										
Notes: NDT PERFORMED BY COSGROVE AIRCRAFT SERVICES CRS# FE1R136K W/O# 54647 DATED 04/06/15. NO DEFECTS NOTED.										
324221	Main Wheel Assembly (Left Outboard) - Overhaul 5009029 JUN10-2860	HRS		545.1			5855.2			0
		AFL		346			3868			0
		MOS		28.2			22 Mar 2023			
		MSC				O/C				
Airframe										
324222	Main Wheel Assembly (Left Inboard) - Overhaul 5009029 FEB02-1719	HRS		805.6			5594.7			0
		AFL		488			3726			0
		MOS		35.1			25 Aug 2022			
		MSC				O/C				
Airframe										
324223	Main Wheel Assembly (Right Inboard) - Overhaul 5009029 JUL08-2748	HRS		913.9			5486.4			0
		AFL		568			3646			0
		MOS		38.8			04 May 2022			
		MSC				O/C				
Airframe										
324224	Main Wheel Assembly (Right Outboard) - Overhaul 5009029 MAR04-1860	HRS		545.1			5855.2			0
		AFL		346			3868			0
		MOS		28.2			22 Mar 2023			
		MSC				O/C				
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
324301	Brake Assembly (Left Outboard, No. 1) - Removal / Installation 5012889-2 JUNE07-0806	HRS AFL MOS MSC		445.3 275 24.7		 O/C	5955 3939 06 Jul 2023			0 0
Airframe										
324302	Brake Assembly (Left Inboard, No. 2) - Removal / Installation 5012889-2 S-NOV13-0105	HRS AFL MOS MSC		1709.6 1051 93.8		 O/C	4690.7 3163 02 Oct 2017			0 0 AIRCRAFT BRAKING SYSTEMS
Airframe										
324303	Brake Assembly (Right Inboard, No. 3) - Removal / Installation 5012889-2 S-NOV13-0100	HRS AFL MOS MSC		2205.2 1411 135.1		 O/C	4195.1 2803 26 Apr 2014			0 0 AIRCRAFT BRAKING SYSTEMS
Airframe										
324304	Brake Assembly (Right Outboard, No. 4) - Removal / Installation 5012889-2 S-AUG11-0021	HRS AFL MOS MSC		954 598 40.3		 O/C	5446.3 3616 19 Mar 2022			0 0 N/A
Airframe										
Notes: BRAKE PUCK SEAL BLOWN OUT										
324501	Antiskid Control Box - Removal / Installation 6006878-2 NOV01-0071	HRS AFL MOS MSC	TSN:1464.9 TSN:788	4935.4 3426 223.3		 O/C	1464.9 788 20 Dec 2006			0 0 GULFSTREAM DALLAS
Airframe										
324502	Wheel Speed Transducer (No. 1) - Removal / Installation 6006568 NOV01-1643	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
324503 Airframe	Wheel Speed Transducer (No. 2) - Removal / Installation 6006568 NOV01-1646	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
324504 Airframe	Wheel Speed Transducer (No. 3) - Removal / Installation 6006568 DEC01-1658	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
324505 Airframe	Wheel Speed Transducer (No. 4) - Removal / Installation 6006568 SEPT02 0998	HRS AFL MOS MSC		4704.8 3260 214.3		 O/C	1695.5 954 18 Sep 2007			0 0 GULFSTREAM DALLAS
325002 Airframe	Nose Wheel Steering Free Swiveling - Functional Test	HRS AFL MOS MSC		757.3 461 31.9		 N/A	5643 3753 30 Nov 2022			0 0
325003 Airframe	Electronic Control Unit - Removal / Installation 28600-000-01 IL-0093	HRS AFL MOS MSC		6359.3 4199 265.7		 O/C	41 15 05 Jun 2003			0 0 GULFSTREAM - APPLETON
325010 Airframe	Torque Link to Collar Connection - Lubrication	HRS AFL MOS MSC		6061.3 4043 258.3		 O/C	339 171 20 Jan 2004			0 0
326001 Airframe	Landing Gear Extension Warning System - Operational Check	HRS AFL MOS		343.7 211 21.6		 36	6056.6 4003 10 Oct 2023	31 Oct 2026	30 Nov 2026	0 0
	[End Of Month Item] [MOS: +1m/-1m]									

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
326020 Airframe	Switch, Uplock (Left MLG, Forward) 4AS2651140-501 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
326021 Airframe	Switch, Uplock (Right MLG, Forward) 4AS2651140-501 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
33 - Lights										
330001 Airframe	Protected Power Supply No. 1 - Removal / Installation AL2026 794	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
330002 Airframe	Protected Power Supply No. 2 - Removal / Installation AL2026 793	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
330003 Airframe	Protected Power Supply No. 3 - Removal / Installation AL-2026 3017	HRS AFL MOS MSC	 TSN:8	1363.9 834 70.6		 O/C	5036.4 3380 08 Sep 2019			0 0 N/A
330004 Airframe	Protected Power Supply No. 4 - Removal / Installation AL2026 389	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
330005 Airframe	Dimming Interface Module (Aircraft 004 Thru Aircraft 072 Pre-MOD 7243) - Removal / Installation AL2030 343	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 METROPOLE PRODUCTS INC

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
330006	Converter, Dc / Dc (No. 1) XLD75-5-1245	LXU01059	HRS AFL MOS MSC	6400.3 4214 275.9			O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe											
330007	Converter, Dc / Dc (No. 2) XLD75-5-1245	LXU01054	HRS AFL MOS MSC	6400.3 4214 275.9			O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe											
330008	Converter, Dc / Dc (No. 3) XLD75-5-1245	LXU01048	HRS AFL MOS MSC	6400.3 4214 275.9			O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe											
330009	Converter, Dc / Dc (No. 4) XLD75-5-1245	LXU01046	HRS AFL MOS MSC	6400.3 4214 275.9			O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe											
330010	Converter, Dc / Dc (No. 5) XLD75-5-1245	LXU01041	HRS AFL MOS MSC	6400.3 4214 275.9			O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
Airframe											
330015	Annunciator Dim / Test Unit 92-7001-3	496	HRS AFL MOS MSC	6372.3 4205 269.2			O/C	28 9 21 Feb 2003			0 0 GULFSTREAM BRN SPARES IPT
Airframe											
331001	Flight Compartment Floodlight No. 1 - Removal / Installation 10-701-2L/R8.00G	3009	HRS AFL MOS MSC	1363.9 834 71			O/C	5036.4 3380 28 Aug 2019			0 0 N/A
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
331002 Airframe	Flight Compartment Floodlight No. 2 - Removal / Installation 10-701-2LR8-00G 389	HRS AFL MOS MSC		5774.3 3906 251.1		 O/C	626 308 25 Aug 2004			0 0
331003 Airframe	Flight Compartment Floodlight No. 3 - Removal / Installation 10-701-2L-R10.00G 404	HRS AFL MOS MSC		1363.9 834 70.6		 O/C	5036.4 3380 08 Sep 2019			0 0 N/A
331010 Airframe	Flight Compartment Instrument Lights - Operational Test	HRS AFL MOS MSC		6372.3 4205 268.8		 O/C	28 9 04 Mar 2003			0 0
331015 Airframe	Flight Compartment Edge Lighted Panels - Operational Test	HRS AFL MOS MSC		6372.3 4205 268.8		 O/C	28 9 04 Mar 2003			0 0
331035 Airframe	Flight Compartment Floodlights - Test	HRS AFL MOS MSC		5492.3 3754 243.5		 O/C	908 460 11 Apr 2005			0 0
331045 Airframe	Flight Compartment Step Lights - Operational Test	HRS AFL MOS MSC		6372.3 4205 268		 O/C	28 9 28 Mar 2003			0 0
331055 Airframe	Flight Compartment, MAP and Dome Lights - Operational Test	HRS AFL MOS MSC		6372.3 4205 268		 O/C	28 9 28 Mar 2003			0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
331060 Airframe	Day / Night System - Operational Test		HRS AFL MOS MSC		6372.3 4205 268.8		 O/C	28 9 04 Mar 2003			0 0
332010 Airframe	Entrance and Airstair Lights - Operational Test		HRS AFL MOS MSC		1363.9 834 69.6		 O/C	5036.4 3380 09 Oct 2019			0 0
332201 Airframe	Power Supply, Cabin (No. 1) AL2000	29907	HRS AFL MOS MSC		6372.3 4205 270		 O/C	28 9 28 Jan 2003			0 0 B/E AEROSPACE LIGHTING CORPORATION
332202 Airframe	Power Supply, Cabin (No. 2) AL2000	34965	HRS AFL MOS MSC		6372.3 4205 270		 O/C	28 9 28 Jan 2003			0 0 B/E AEROSPACE LIGHTING CORPORATION
332203 Airframe	Power Supply, Cabin (No. 3) AL2000	39015	HRS AFL MOS MSC		6372.3 4205 268.5		 O/C	28 9 13 Mar 2003			0 0 B/E AEROSPACE LIGHTING CORPORATION
334001 Airframe	Pulse Control Unit - Removal / Installation 2400-25-4-4-2	KA00499	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
334002 Airframe	Strobe Light (Left) - Removal / Installation 702680-003	AB0353	HRS AFL MOS MSC		1053.8 664 45.8		 O/C	5346.5 3550 04 Oct 2021			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
334003 Airframe	Strobe Light (Right) - Removal / Installation 702680-004 AB0351	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
334004 Airframe	Lens Assembly, Left Strobe 702682-001 980162	HRS AFL MOS MSC	TSN:4720.5 TSN:3242 TSN:206	1053.8 664 45.8		 O/C	5346.5 3550 04 Oct 2021			0 0
334005 Airframe	Lens Assembly, Right Strobe 702682-002 AB0307	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
334006 Airframe	Wing Position and Strobe Power Supply (Left) - Removal / Installation 702669 4868832	HRS AFL MOS MSC	 TSN:3	1053.8 664 45.8		 O/C	5346.5 3550 04 Oct 2021			0 0
334007 Airframe	Wing Position and Strobe Power Supply (Right) - Removal / Installation 702669 AB0292	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS
334010 Airframe	Position and Strobe Lights - Operational Test	HRS AFL MOS MSC		954 598 39.7		 O/C	5446.3 3616 07 Apr 2022			0 0
334017 Airframe	Wing Position and Strobe Lights Lenses (Left) - Detailed Inspection [End Of Month Item] [MOS: +1m/-1m]	HRS AFL MOS		177 113 11.9		 24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
334018 Airframe	Wing Position and Strobe Lights Lenses (Right) - Detailed Inspection	HRS AFL MOS		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
334020 Airframe	Anticollision Lights - Operational Test	HRS AFL MOS MSC		6372.3 4205 268.8		O/C	28 9 04 Mar 2003			0 0
334041 Airframe	Logo Light (Right) - Removal / Installation 4AS8488011-002 SN-UNKNOWN	HRS AFL MOS MSC		6246.3 4128 261.4		O/C	154 86 15 Oct 2003			0 0
334045 Airframe	Wing Inspection and Logo Lights - Operational Test	HRS AFL MOS MSC		6372.3 4205 268.8		O/C	28 9 04 Mar 2003			0 0
334085 Airframe	Pylon Lights - Operational Test	HRS AFL MOS MSC		6372.3 4205 268		O/C	28 9 28 Mar 2003			0 0
334200 Airframe	Wing Position Light Assembly (Right) - Removal / Installation 702705-006 AB0339	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
334201 Airframe	Wing Position Light Assembly (Left) - Removal / Installation 702705-005 AC0372	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
334205 Airframe	Tail Position Light Bulb - Removal / Installation MS35478-1683 NSN	HRS AFL MOS MSC		954 598 39.7		 O/C	5446.3 3616 07 Apr 2022			0 0 N/A
334301 Airframe	Landing Light (Left) - Removal / Installation PERMANENT REMOVAL	HRS AFL MOS MSC		1363.9 834 69.1		 O/C	5036.4 3380 25 Oct 2019			0 0
Notes: PERMANENT REMOVAL										
334302 Airframe	Landing Light (Right) - Removal / Installation PERMANENT REMOVAL	HRS AFL MOS MSC		1363.9 834 69.1		 O/C	5036.4 3380 25 Oct 2019			0 0
Notes: PERMANENT REMOVAL [REF 12.1]										
334303 Airframe	Taxi Light (Left) - Removal / Installation PERMANENT REMOVAL	HRS AFL MOS MSC		1363.9 834 69.1		 O/C	5036.4 3380 25 Oct 2019			0 0
Notes: REFER TO 11.80 FOR INSTALLATION.										
334304 Airframe	Taxi Light (Right) - Removal / Installation PERMANENT REMOVAL	HRS AFL MOS MSC		1363.9 834 69.1		 O/C	5036.4 3380 25 Oct 2019			0 0
Notes: REFER TO 11.80 CMP 334305 FOR INSTALLATION.										
334305 Airframe	Light, Taxi Led Left - Removal / Installation TAE0528-2 00678	HRS AFL MOS MSC	 TSN:15	1363.9 834 69		 O/C	5036.4 3380 27 Oct 2019			0 0 Talon
Notes: PROCEDURE REFERENCE: TALON AEROSPACE DOC# INS-728-01										
334306 Airframe	Light, Taxi Led Right - Removal / Installation TAE0528-2 00684	HRS AFL MOS MSC	 TSN:15	1363.9 834 69		 O/C	5036.4 3380 27 Oct 2019			0 0 Talon
Notes: PROCEDURE REFERENCE: TALON AEROSPACE DOC# INS-728-01										

ATA / U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
334307	Led Landing Light Assy, (Left) - Removal / Installation TAE0628-1 00522	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS	TSN:7	69			27 Oct 2019			Talon
		MSC				O/C				
Airframe										
Notes: PROCEDURE REFERENCE: TALON AEROSPACE DOC# INS-728-01										
334308	Led Landing Light Assy, (Right) - Removal / Installation TAE0628-1 00269	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS	TSN:33	69			27 Oct 2019			Talon
		MSC				O/C				
Airframe										
Notes: PROCEDURE REFERENCE: TALON AEROSPACE DOC# INS-728-01										
334320	Landing and Taxi Lights - Operational Test	HRS		1709.6			4690.7			0
		AFL		1051			3163			0
		MOS		94.6			08 Sep 2017			
		MSC				O/C				
Airframe										
335000	Cabin Lighting - Operational Test	HRS		177			6223.3			0
		AFL		113			4101			0
		MOS		11.9		24	30 Jul 2024	31 Jul 2026	31 Aug 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: COMPLIED WITH CMP G200 335000 CABIN LIGHTING - OPERATIONAL TEST										
335011	Battery, Securaplane (No. 1) 100-0540-02 1019	HRS		157.9			6242.4			0
		AFL		100			4114			0
		MOS		9.8			03 Oct 2024			
		MSC				O/C				
Airframe										
335012	Battery, Securaplane (No. 2) 100-0540-02 0703291	HRS		157.9			6242.4			0
		AFL		100			4114			0
		MOS		9.8			03 Oct 2024			
		MSC				O/C				
Airframe										
Notes: ICA GA21 486A001										
335013	Module, Battery (Securaplane #1) - Discard 140-0742-03 PT05240338	HRS		157.9			6242.4			0
		AFL		100			4114			0
		MOS	TSN:4	9.8		48	03 Oct 2024	30 Jun 2028	31 Jul 2028	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: Top assembly part number: 100-0540-02, PROCEDURE REFERENCE: G200 DOC# GA21486A001, REV. B DATED 9/19/02.										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
335014 Airframe	Module, Battery (Securaplane #2) - Discard 140-0742-03 PT05240340	HRS		157.9			6242.4			0
		AFL		100			4114			0
		MOS	TSN:4	9.8		48	03 Oct 2024	30 Jun 2028	31 Jul 2028	
		[End Of Month Item] [MOS: +1m/-1m]								
Notes: Top assembly part number: 100-0540-02, PROCEDURE REFERENCE: G200 DOC# GA21486A001, REV. B DATED 9/19/02.										
335016 Airframe	Emergency Light (Emergency Exit) BR9067-002 SN-UNKNOWN	HRS		6359.3			41			0
		AFL		4199			15			0
		MOS		265.7			05 Jun 2003			
		MSC				O/C				
335020 Airframe	Securaplane Battery No. 1 - Level Test	HRS		33.1			6367.2			0
		AFL		21			4193			0
		MOS		2.2	8	12	23 May 2025	31 May 2026*	30 Jun 2026	
		[End Of Month Item] [MOS: +1m/-1m]								
335024 Airframe	Securaplane Battery No. 2 - Level Test	HRS		33.1			6367.2			0
		AFL		21			4193			0
		MOS		2.2	8	12	23 May 2025	31 May 2026*	30 Jun 2026	
		[End Of Month Item] [MOS: +1m/-1m]								
335025 Airframe	Emergency Light Distance Unit (Forward) GCB24950001-XXX SN-UNKNOWN	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		265.8			02 Jun 2003			
		MSC				O/C				
335026 Airframe	Emergency Light Distance Unit (Aft) GCB249550001-XXX SN-UNKNOWN	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		265.7			06 Jun 2003			
		MSC				O/C				
335027 Airframe	Emergency Light Battery Mounting - Condition/Security	HRS		33.1			6367.2			0
		AFL		21			4193			0
		MOS		2.2	8	12	23 May 2025	31 May 2026*	30 Jun 2026	
		[End Of Month Item] [MOS: +1m/-1m]								
335028 Airframe	Emergency Lighting - Functional Check (STC)	HRS		30.4			6369.9			0
		AFL		19			4195			0
		MOS		2.1		12	26 May 2025	31 May 2026	30 Jun 2026	
		[End Of Month Item] [MOS: +1m/-1m]								
Notes: ICA GA21486A001										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
335030	Wire Separation of Battery and Eldu from Fqmc	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		24.5	20	48	11 Jul 2023	31 Jul 2027*	31 Aug 2027	
Airframe		[End Of Month Item] [MOS: -1m]								
335035	Emergency Lights - Operational Check	HRS		177			6223.3			0
		AFL		113			4101			0
		MOS		11.9		24	30 Jul 2024	31 Jul 2026	31 Aug 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
337001	Landing, Taxi, Turn, Scan and Logo Lights Condition L/H - Inspection (Talon Aerospace)	HRS		343.7			6056.6			0
		AFL		211			4003			0
		MOS		21.7		24	05 Oct 2023	31 Oct 2025	30 Nov 2025	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
337002	Landing, Taxi, Turn, Scan and Logo Lights Condition R/H - Inspection (Talon Aerospace)	HRS		343.7			6056.6			0
		AFL		211			4003			0
		MOS		21.7		24	05 Oct 2023	31 Oct 2025	30 Nov 2025	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
34 - Navigation										
340002	External Compensation Unit (Ecu-3000) - Removal / Installation	HRS		6400.3			0			0
		AFL		4214			0			0
	822-1200-001 H08B	MOS		275.9			01 Aug 2002			
		MSC				O/C				
Airframe										
340003	External Compensation Unit (Ecu-3000), No. 2	HRS		6400.3			0			0
	822-1200-001 GVLD	AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
340010	AIR Data Instrument Validation - Functional Test	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		265.1			25 Jun 2003			
Airframe		MSC				O/C				

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
340014 Airframe	Altitude Accuracy Test for Operation In Reduced Vertical Separation Minimums Airspace - Test	HRS AFL MOS [End Of Month Item]		157.9 100 9.8		24	6242.4 4114 03 Oct 2024	31 Oct 2026		0 0
340015 Airframe	Verify Validity RVSM Requirements - Inspection	HRS AFL MOS MSC		6400.3 4214 265.1		O/C	0 0 25 Jun 2003			0 0
340020 Airframe	AIR Data Instrument Components - Functional Test	HRS AFL MOS MSC		6400.3 4214 265.1		O/C	0 0 25 Jun 2003			0 0
340060 Airframe	Electronic Flight Instrument System - Validation Check	HRS AFL MOS MSC		6400.3 4214 265.1		O/C	0 0 25 Jun 2003			0 0
341060 Airframe	Standby Compass (Magnetic) - Removal / Installation PAI-700 36158P	HRS AFL MOS MSC		5049.1 3494 226.1		O/C	1351.2 720 26 Sep 2006			0 0 ISRAEL AIRCRAFT INDUSTRIES
341061 Airframe	Standby Compass - Compensating Swing	HRS AFL MOS MSC		5049.1 3494 226		O/C	1351.2 720 27 Sep 2006			0 0
341101 Airframe	Standby Altimeter Indicator - Removal / Installation 8047/10 8652B	HRS AFL MOS MSC		157.9 100 9.8		O/C	6242.4 4114 03 Oct 2024			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
341102	Standby Altimeter Indicator - Calibration / Test	HRS		157.9			6242.4			0
		AFL		100			4114			0
		MOS		9.8		24	03 Oct 2024	30 Sep 2026		
Airframe		[End Of Month Item]								CALIBRATION
Notes: COMPLIED BY PACIFIC SOUTHWEST INSTRUMENTS CERT# FAA=KD3R627L SEE ATTACHED REPORT AND 8130.										
341103	Standby Airspeed Indicator - Removal / Installation 8059-2B 10035	HRS		157.9			6242.4			0
		AFL		100			4114			0
		MOS		9.8			03 Oct 2024			
Airframe		MSC				O/C				
Notes: INDICATOR REMOVED AND REPLACED BY TERRY NILGES JET AVIATION CRS# R03R822L.										
341105	Standby Airspeed Indicator - Functional Test	HRS		2371.2			4029.1			0
		AFL		1541			2673			0
		MOS		143.2			23 Aug 2013			
Airframe		MSC				O/C				
Notes: STANDBY AIRSPEED INDICATOR FUNCTIONAL TEST C/W. NO DEFECTS NOTED. PERFORMED BY TERRY NIGLES JET AVIATION CRS# R03R822L.										
341201	Computer, AIR Data No. 1 - Removal / Installation 822-0374-457 1MNVY	HRS		157.9			6242.4			0
		AFL		100			4114			0
		MOS		9.8			03 Oct 2024			
Airframe		MSC				O/C				CALIBRATION
341202	Computer, AIR Data No. 2 - Removal / Installation 822-0374-457 1MOHW	HRS		157.9			6242.4			0
		AFL		100			4114			0
		MOS		9.8			03 Oct 2024			
Airframe		MSC				O/C				CALIBRATION
341203	Pitot-Static and AIR Data Computer (ADC No. 1) - Operational / Recertification Test (FAR 91.411)	HRS		157.9			6242.4			0
		AFL		100			4114			0
		MOS		9.8		24	03 Oct 2024	31 Oct 2026		
Airframe		[End Of Month Item]								CALIBRATION
341204	Static Port Flushness Measurement Requirements for Aircraft Operating In Reduced Vertical Separation Minimums Airspace - Inspection	HRS		33.1			6367.2			0
		AFL		21			4193			0
		MOS		2.2		12	23 May 2025	31 May 2026	30 Jun 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
341205	Skin Contour Measurements for Aircraft Operating In Reduced Vertical Seperation Minimum Airspace - Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.1		96	26 May 2023	31 May 2031	30 Jun 2031	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: NOT C/W 22 JUL PER NOTE ON TASK CARD. SET 96 MONTHS FROM AUG 2007 COMPLIANCE. GRH 1 APR 10										
341206	Reference Panel, AIR Data No. 1 - Removal / Installation 822-0326-002(ARP4002) JBJB	HRS	TSN:28	6372.3			28			0
		AFL	TSN:9	4205			9			0
		MOS		267.9			30 Mar 2003			
		MSC				O/C				
Airframe										
341207	Reference Panel, AIR Data No. 2 - Removal / Installation 822-0326-002 J8TT	HRS	TSN:28	6372.3			28			0
		AFL	TSN:9	4205			9			0
		MOS	TSN:8	267.9			30 Mar 2003			
		MSC				O/C				
Airframe										
341208	Probe, Total AIR Temperature - Removal / Installation 102AU1AG A58639	HRS		3101			3299.3			0
		AFL		2091			2123			0
		MOS	TSN:72	171.6			10 Apr 2011			GOODRICH SENSOR SYSTEMS
		MSC				O/C				
Airframe										
Notes: PART INSTALLED BY STANDARD AERO AVIATION SERVICES CRS# GW4R221M W/O# 276959 DATED 04/10/11.										
341209	Indexer, Angle of Attack No. 1 - Removal / Installation 0031AE 159	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			DILLON - MORGANS
		MSC				O/C				
Airframe										
341210	Indexer, Angle of Attack No. 2 - Removal / Installation 0031AE 166	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			DILLON - MORGANS
		MSC				O/C				
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
341211 Logbook Position	Pitot-Static and AIR Data Computer (ADC No. 2) - Operational / Recertification Test (FAR 91.411)	HRS AFL MOS [End Of Month Item]		157.9 100 9.8		24	6242.4 4114 03 Oct 2024	31 Oct 2026		0 0 CALIBRATION
Airframe										
341212	AIR Data Computer No. 1 - Functional Test	HRS AFL MOS MSC		4787.6 3321 219.2		O/C	1612.7 893 23 Apr 2007			0 0
Airframe										
341213	AIR Data Computer No. 2 - Functional Test	HRS AFL MOS MSC		6372.3 4205 268.8		O/C	28 9 04 Mar 2003			0 0
Airframe										
341215	Pitot-Static Lines - Leakage Test	HRS AFL MOS MSC		157.9 100 9.8		O/C	6242.4 4114 03 Oct 2024			0 0
Airframe										
341216	Pitot-Static Lines Drainage - Inspection	HRS AFL MOS MSC		6372.3 4205 268.8		O/C	28 9 04 Mar 2003			0 0
Airframe										
341220	Pitot-Static System (FAR 91.411) - Reconnect Check	HRS AFL MOS MSC		757.3 461 31.9		O/C	5643 3753 30 Nov 2022			0 0
Airframe										
341221	Pitot-Static System (Pilot) - Reconnect Check	HRS AFL MOS [End Of Month Item]		157.9 100 9.8		24	6242.4 4114 03 Oct 2024	31 Oct 2026		0 0
Airframe										
341222	Pitot-Static System (Copilot) - Reconnect Check	HRS AFL MOS [End Of Month Item]		157.9 100 9.8		24	6242.4 4114 03 Oct 2024	31 Oct 2026		0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
341223	Pitot-Static System (Standby) - Reconnect Check	HRS		157.9			6242.4			0
		AFL		100			4114			0
		MOS		9.8		24	03 Oct 2024	31 Oct 2026		
Airframe		[End Of Month Item]								
Notes: STBY ALTIMETER P/N: 8047/10, S/N: 8652B.DPS 450 CN: 567911 CAL DUE: 3/20										
341231	ADC 1 Wiring Harness and Ground Points - Detailed Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71.2	-21	96	21 Aug 2019	31 Jul 2027*	31 Aug 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: COMPLIED WITH CMP G200 341231 ADC 1 WIRING HARNESS AND GROUND POINTS - DETAILED INSPECTION										
341232	ADC 2 Wiring Harness and Ground Points - Detailed Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71.2	-21	96	21 Aug 2019	31 Jul 2027*	31 Aug 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: COMPLIED WITH CMP G200 341232 ADC 2 WIRING HARNESS AND GROUND POINTS - DETAILED INSPECTION										
341235	AIR Data Computer (No. 1) - Restore 822-0374-457 1MNVY	HRS		157.9			6242.4			0
		AFL		100			4114			0
		MOS		9.8	-3	96	03 Oct 2024	31 Aug 2032*		
Airframe		[End Of Month Item]								
341236	AIR Data Computer (No. 2) - Restore 822-0374-457 1M0HW	HRS		157.9			6242.4			0
		AFL		100			4114			0
		MOS		9.8	-3	96	03 Oct 2024	31 Aug 2032*		
Airframe		[End Of Month Item]								
341301	Pitot Probe (Left) - Removal / Installation 851Y 210435	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
341302	Pitot Probe (Right) - Removal / Installation 851W 210514	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
341304	Static Port, S1 (Left) - Removal / Installation ST300-2PTG 142	HRS AFL MOS MSC		6372.3 4205 269.9		O/C	28 9 30 Jan 2003			0 0
Airframe										
341305	Static Port, S2 (Left) - Removal / Installation ST300-2PTG 143	HRS AFL MOS MSC		6372.3 4205 269.9		O/C	28 9 30 Jan 2003			0 0
Airframe										
341306	Static Port, S3 (Left) - Removal / Installation ST300-2PTG 144	HRS AFL MOS MSC		6372.3 4205 269.9		O/C	28 9 30 Jan 2003			0 0
Airframe										
341307	Static Port, S1 (Right) - Removal / Installation ST300-2PTG 145	HRS AFL MOS MSC		6372.3 4205 269.9		O/C	28 9 30 Jan 2003			0 0
Airframe										
341308	Static Port, S2 (Right) - Removal / Installation ST300-2PTG 146	HRS AFL MOS MSC		6372.3 4205 269.9		O/C	28 9 30 Jan 2003			0 0
Airframe										
341309	Static Port, S3 (Right) - Removal / Installation ST300-2PTG 149	HRS AFL MOS MSC		6372.3 4205 269.9		O/C	28 9 30 Jan 2003			0 0
Airframe										
341501	Stall Protection and Q-Feel Computer Nonvolatile Memory / Fault Log - Clearing	HRS AFL MOS [HRS: +50/-50]		275.5 178 15.3	18.2	500	6124.8 4036 19 Apr 2024	6643*	6693	0 0
Airframe										
341601	Computer, Stall Protection and Q-Feel (Sqpc) - Removal / Installation 0020CV6 70	HRS AFL MOS MSC		5635.3 3831 247.8		O/C	765 383 03 Dec 2004			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
341602 Logbook Position	Angle of Attack Sensor (Left) - Removal / Installation 0861GA 228	HRS AFL MOS MSC		2066.4 1325 128.2		O/C	4333.9 2889 22 Nov 2014			0 0 GULFSTREAM DALLAS
Airframe										
Notes: OLD UNIT REMOVED DUE TO BURNT PINS P AND R. HAD TO REPLACE CANNON PLUG AS WELL.										
341603	Angle of Attack Sensor (Right) - Removal / Installation 0861GA 137	HRS AFL MOS MSC		5271 3631 237.5		O/C	1129.3 583 13 Oct 2005			0 0 GULFSTREAM DALLAS
Airframe										
341605	Stall Protection and Q-Feel System - Functional Test	HRS AFL MOS MSC		2066.4 1325 128.2		O/C	4333.9 2889 22 Nov 2014			0 0
Airframe										
Notes: STALL PROTECTION AND Q-FEEL SYSTEM FUNCTIONAL TEST C/W. NO DEFECTS NOTED. I/A/W G200 CMP CODE 346105 PAGE 1-13.										
342101	Computer, Attitude Heading No. 1 - Removal / Installation 822-1110-001 (AHC-3000) HMTC	HRS AFL MOS MSC	TSN:28 TSN:9	6372.3 4205 267.9		O/C	28 9 30 Mar 2003			0 0
Airframe										
342102	Computer, Attitude Heading No. 2 - Removal / Installation 822-1110-001 (AHC-3000) H04K	HRS AFL MOS MSC		1587.3 966 87.2		O/C	4813 3248 23 Apr 2018			0 0
Airframe										
342103	Flux Detector Unit No. 1 - Removal / Installation 822-1193-001 (FDU-3000) 26836	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										
342104	Flux Detector Unit No. 2 - Removal / Installation 822-1193-001 (FDU-3000) 306035	HRS AFL MOS MSC	TSN:3	1179.9 732 55.5		O/C	5220.4 3482 12 Dec 2020			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
342108	Flux Detector Unit No. 1 Wiring Harness and Ground Points - General Visual Inspection		HRS		1363.9			5036.4			0
			AFL		834			3380			0
			MOS		71.2	-23	96	23 Aug 2019	31 Jul 2027*	31 Aug 2027	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: COMPLIED WITH CMP G200 342108 FLUX DETECTOR UNIT NO. 1 WIRING HARNESS AND GROUND POINTS - GENERAL VISUAL INSPECTION											
342109	Flux Detector Unit No. 2 Wiring Harness and Ground Points - General Visual Inspection		HRS		1363.9			5036.4			0
			AFL		834			3380			0
			MOS		71.2	-23	96	23 Aug 2019	31 Jul 2027*	31 Aug 2027	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: COMPLIED WITH CMP G200 342109 FLUX DETECTOR UNIT NO. 2 WIRING HARNESS AND GROUND POINTS - GENERAL VISUAL INSPECTION											
342110	Attitude and Heading Reference - Functional Test		HRS		1179.9			5220.4			0
			AFL		732			3482			0
			MOS		55.6			10 Dec 2020			
			MSC				O/C				
Airframe											
342120	Fdu #1 Compensation - Calibration / Check		HRS		6372.3			28			0
			AFL		4205			9			0
			MOS		267			27 Apr 2003			
			MSC				O/C				
Airframe											
342121	Fdu #2 Compensation - Calibration / Check		HRS		6372.3			28			0
			AFL		4205			9			0
			MOS		267			27 Apr 2003			
			MSC				O/C				
Airframe											
342122	Attitude Heading Reference Alignment No. 1 - Heading Check		HRS		1179.9			5220.4			0
			AFL		732			3482			0
			MOS		55.5			12 Dec 2020			
			MSC				O/C				
Airframe											
342201	See Code 342704 501-1197-29	9106	HRS		2580.3			3820			0
			AFL		1693			2521			0
			MOS		151.7			05 Dec 2012			
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
342301	Display No. 1, Pilot Pfd - Removal / Installation 622-9978-408 1250C	HRS AFL MOS MSC		1363.9 834 70.2		 O/C	5036.4 3380 21 Sep 2019			0 0 N/A
Airframe										
342302	Display No. 2, Pilot Mfd - Removal / Installation 622-9978-408 2TBGV	HRS AFL MOS MSC		1363.9 834 70.2		 O/C	5036.4 3380 21 Sep 2019			0 0 N/A
Airframe										
342303	Display No. 3, Eicas - Removal / Installation 622-9978-408 1L7VK	HRS AFL MOS MSC		954 598 40.5		 O/C	5446.3 3616 13 Mar 2022			0 0 N/A
Airframe										
342304	Display No. 4, Copilot Mfd - Removal / Installation 622-9978-408 J5PT	HRS AFL MOS MSC		954 598 39.8		 O/C	5446.3 3616 02 Apr 2022			0 0 N/A
Airframe										
342305	Display No. 5, Copilot Pfd - Removal / Installation 622 9978-408 2DCDC	HRS AFL MOS MSC		445.3 275 24.5		 O/C	5955 3939 11 Jul 2023			0 0
Airframe										
342306	Panel, Display Controller No. 1 - Removal / Installation 822-0321-008(DCP-4002) YXHV	HRS AFL MOS MSC	TSN:28 TSN:9 TSN:8	6372.3 4205 267.9		 O/C	28 9 30 Mar 2003			0 0
Airframe										
342307	Panel, Display Controller No. 2 - Removal / Installation 822-0321-008(DCP-4002) YXHX	HRS AFL MOS MSC	TSN:28 TSN:9 TSN:8	6372.3 4205 267.9		 O/C	28 9 30 Mar 2003			0 0
Airframe										
342308	Panel, Reversionary No. 1 - Removal / Installation 822-0273-004 179	HRS AFL MOS MSC		157.9 100 9.8		 O/C	6242.4 4114 03 Oct 2024			0 0
Airframe										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
342309	Panel, Reversionary No. 2 - Removal / Installation 822-0273-004	NPJL	HRS AFL MOS MSC		6372.3 4205 267.9		O/C	28 9 30 Mar 2003			0 0
Airframe											
342310	Inc-4000 Inclinometer 622-9996-002	HYKX	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe											
342312	Electronic Flight Instrument System (EFIS, V6.1) Aircraft 052 Thru Aircraft 999 - Functional Test		HRS AFL MOS MSC		6372.3 4205 268.8		O/C	28 9 04 Mar 2003			0 0
Airframe											
342313	Inc-4000 Inclinometer (No. 2) 622-9996-002	SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe											
342390[U]	Electronic Flt Display Fan VK24B3	NSN	HRS AFL MOS MSC		954 598 39.9		O/C	5446.3 3616 31 Mar 2022			0 0 N/A
Airframe											
342501	Lhp-4000/4001 (No. 1) - Removal / Installation 822-0287-201(LHP4000)	JB1R	HRS AFL MOS MSC		1587.3 966 87.1		O/C	4813 3248 24 Apr 2018			0 0
Airframe											
Notes: UPDATE CORRECT INFORMATION FOR INSTALLED PART.											
342502	Lhp-4000/4001 (No. 2) - Removal / Installation 822-0332-201 (LHP-4001)	HLGB	HRS AFL MOS MSC		1587.3 966 87.1		O/C	4813 3248 24 Apr 2018			0 0
Airframe											
342503	Csu-4000 (No. 1) - Removal / Installation 822-0049-002	H7NC	HRS AFL MOS MSC		4935.4 3426 223.3		O/C	1464.9 788 19 Dec 2006			0 0
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
342504	Csu-4000 (No. 2) - Removal / Installation 822-0049-002 HHMV	HRS AFL MOS MSC		4935.4 3426 223.3		 O/C	1464.9 788 19 Dec 2006			0 0
Airframe										
342505	Iaps, Card Cage Assembly - Removal / Installation 800-1407-001 (ICC-4009) YXYG	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
342506	Pwr-4000 (No. 1) - Removal / Installation 622-9945-021 (PWR-4000) 02CG	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
342507	Pwr-4000 (No. 2) - Removal / Installation 622-9945-021 (PWR-4000) 02CD	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
342508	Pwr-4000 (No. 3) - Removal / Installation 622-9945-021 (PWR-4000) 02CF	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
342509	Pwr-4000 (No. 4) - Removal / Installation 622-9945-021 (PWR-4000) 00PC	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
342510	Iec-4001 (No. 1) - Removal / Installation 822-0333-001 (IEC-4001) YYND	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
342511	Iec-4001 (No. 2) - Removal / Installation 822-0333-001 (IEC-4001) YYNK	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
Logbook Position	Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW									
342512	IOC-4000 (No. 1) - Removal / Installation 622-9814-312 NJPP		HRS AFL MOS MSC		4935.4 3426 223.3		O/C	1464.9 788 20 Dec 2006			0 0
Airframe											
342513	IOC-4000 (No. 2) - Removal / Installation 622-9814-312 NGWC		HRS AFL MOS MSC		4935.4 3426 223.3		O/C	1464.9 788 19 Dec 2006			0 0
Airframe											
342514	IOC-4000 (No. 3) - Removal / Installation 622-9814-312 NGWD		HRS AFL MOS MSC		4935.4 3426 223.3		O/C	1464.9 788 20 Dec 2006			0 0
Airframe											
342515	IOC-4000 (No. 4) - Removal / Installation 622-9814-312 NGWF		HRS AFL MOS MSC		4935.4 3426 223.3		O/C	1464.9 788 19 Dec 2006			0 0
Airframe											
342520	Csu-4000 - Programming		HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe											
342521	Icc Wiring Harness and Ground Points - Detailed Inspection		HRS AFL MOS		1363.9 834 71.2	 -21	 96	5036.4 3380 21 Aug 2019	 31 Jul 2027*	 31 Aug 2027	0 0
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
Notes: COMPLIED WITH CMP G200 342521 ICC WIRING HARNESS AND GROUND POINTS - DETAILED INSPECTION											
342701	Power Supply, Ps-855 Emergency - Removal / Installation 501-1712-02 81487		HRS AFL MOS MSC		757.3 461 31.9		O/C	5643 3753 30 Nov 2022			0 0
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
342703	Standby Instrument Emergency Power Supply (Ps-855) - Functional Check	HRS		177			6223.3			0
		AFL		113			4101			0
		MOS		11.9		12	30 Jul 2024	31 Jul 2025	31 Aug 2025	N/A
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: PN: 501-1712-02 SN: 81487. REF ITEM 31.1 FOR FUNCTIONAL / CAP CHECK.										
342705	Standby Attitude Reference System - Operational Test	HRS		399			6001.3			0
		AFL		249			3965			0
		MOS		23.4			17 Aug 2023			
		MSC				O/C				
Airframe										
344201	Weather Radar, Rta-858 - Removal / Installation 622-8441-004 27BBD	HRS		1071.6			5328.7			0
		AFL		676			3538			0
		MOS		48.5			12 Jul 2021			
		MSC				O/C				
Airframe										
344202	Panel, Weather Radar No. 1 - Removal / Installation 622-9932-002 (WHR-4220) YXJJ	HRS	TSN:28	6372.3			28			0
		AFL	TSN:9	4205			9			0
		MOS	TSN:8	267.9			30 Mar 2003			
		MSC				O/C				
Airframe										
344203	Panel, Weather Radar No. 2 - Removal / Installation 622-9932-002 NHGK	HRS	TSN:28	6372.3			28			0
		AFL	TSN:9	4205			9			0
		MOS	TSN:8	267.9			30 Mar 2003			
		MSC				O/C				
Airframe										
344205	Weather Radar System - Functional Test	HRS		1709.6			4690.7			0
		AFL		1051			3163			0
		MOS		93.8			04 Oct 2017			
		MSC				O/C				
Airframe										
344402	Transceiver, Radio Altimeter (Alt-4000) - Removal / Installation 822-0615-315 4TTM5	HRS		1377.1			5023.2			0
		AFL		842			3372			0
		MOS		72.1			26 Jul 2019			
		MSC				O/C				
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
344403	Antenna, Radio Altimeter, No. 1 - Removal / Installation S67-2002 543-66560	HRS AFL MOS MSC	 TSN:80 	1363.9 834 70.6 	 	 O/C	5036.4 3380 08 Sep 2019 	 	 	0 0 N/A
Airframe										
344405	Antenna, Radio Altimeter, No. 2 - Removal / Installation S67-2002 23534	HRS AFL MOS MSC	TSN:5036.4 TSN:3380 TSN:205 	1363.9 834 70.6 	 	 O/C	5036.4 3380 08 Sep 2019 	 	 	0 0 N/A
Airframe										
344410	Radio Altimeter System - Functional Test	HRS AFL MOS MSC	 	1363.9 834 70.5 	 	 O/C	5036.4 3380 14 Sep 2019 	 	 	0 0
Airframe										
344601	Egpws Computer - Removal / Installation 965-0976-040-213-213 12800	HRS AFL MOS MSC	TSN:28 TSN:9 TSN:8 	6372.3 4205 267.9 	 	 O/C	28 9 30 Mar 2003 	 	 	0 0 HONEYWELL
Airframe										
344610	Enhanced Ground Proximity Warning System (Egpws V6.1) Aircraft 051 Thru Aircraft 999 - Functional Test	HRS AFL MOS MSC	 	6372.3 4205 268.8 	 	 O/C	28 9 04 Mar 2003 	 	 	0 0
Airframe										
344620	Egpws Terrain Database - Update	HRS AFL MOS MSC	 	356.5 545 22 	 	 O/C	6043.8 3669 27 Sep 2023 	 	 	0 0
Airframe										
344701	Transceiver, TCAS - Removal / Installation 822-1294-032 158228	HRS AFL MOS MSC	 	223.7 141 13.9 	 	 O/C	6176.6 4073 31 May 2024 	 	 	0 0
Airframe										
Notes: TCAS TRANSCEIVER WOULD SHOW FAIL MESSAGE EVERY 10 TO 20 SECONDS IN FLIGHT.										
344702	Antenna, TCAS Omnidirectional - Removal / Installation DMNI50-6-2 19833	HRS AFL MOS MSC	TSN:5036.4 TSN:3380 TSN:205 	1363.9 834 70.6 	 	 O/C	5036.4 3380 08 Sep 2019 	 	 	0 0 N/A
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
344703	TCAS Directional Antenna - Removal / Installation 622-8973-001 3TNWW	HRS AFL MOS MSC	TSN:1659.7 TSN:1192 TSN:103	1363.9 834 70.9		O/C	5036.4 3380 30 Aug 2019			0 0 N/A
Airframe										
344704	Traffic Alert and Collision Avoidance System - Functional Test	HRS AFL MOS MSC		1363.9 834 70.3		O/C	5036.4 3380 18 Sep 2019			0 0
Airframe										
344710	TCAS - Test	HRS AFL MOS MSC		1953.3 1230 123.6		O/C	4447 2984 08 Apr 2015			0 0
Airframe										
Notes: PN: 822-1294-002 SN: 170411. TCAS FUNCTIONAL TEST C/W. NO DEFECTS NOTED. I/A/W G200CMP CODE 344710 & 344704 PAGES 1-5.										
345204	GPS Antenna (No. 1) - Removal / Installation S67-1575-137 773-6131	HRS AFL MOS MSC	TSN:9	1363.9 834 70.6		O/C	5036.4 3380 09 Sep 2019			0 0 Sensor System Inc.
Airframe										
Notes: COMPLIED WITH CMP G200 345204 ANTENNA, GPS (NO. 1) OFF: P/N S67-1575-39 S/N 13489 WGT 5OZ ON: P/N S67-1575-137 S/N 773-6131 WGT 8OZ										
345205	GPS Antenna (No. 2) - Removal / Installation S67-1575-137 773-5609	HRS AFL MOS MSC	TSN:15	1363.9 834 70.6		O/C	5036.4 3380 09 Sep 2019			0 0 Sensor System Inc.
Airframe										
Notes: COMPLIED WITH CMP G200 345205 ANTENNA, GPS (NO. 2) OFF: P/N S67-1575-39 S/N 13407 WGT 5OZ ON: P/N S67-1575-137 S/N 773-5609 WGT 8OZ										
345206	Receiver, GPS-4000 No. 1 - Removal / Installation 822-2189-101 22C9K	HRS AFL MOS MSC		581 366 28.6		O/C	5819.3 3848 10 Mar 2023			0 0
Airframe										
345207	Receiver, GPS-4000 No. 2 - Removal / Installation 822-2189-100 26WCW	HRS AFL MOS MSC		581 366 28.6		O/C	5819.3 3848 10 Mar 2023			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
345208	Control Display Unit, No. 1 - Removal / Installation 822-1354-102 J6TX	HRS AFL MOS MSC		1363.9 834 69.9		 O/C	5036.4 3380 01 Oct 2019			0 0 N/A
Airframe										
345209	Control Display Unit, No. 2 - Removal / Installation 822-1354-102 NLHD	HRS AFL MOS MSC		3023.6 2026 168.5		 O/C	3376.7 2188 13 Jul 2011			0 0
Airframe										
345210	Uns-1 FMS	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
345213	GPS 1 Wiring Harness and Ground Points - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71.2	 -21	 96	5036.4 3380 21 Aug 2019	 31 Jul 2027*	 31 Aug 2027	0 0
Airframe										
Notes: COMPLIED WITH CMP G200 345213 GPS 1 WIRING HARNESS AND GROUND POINTS - DETAILED INSPECTION										
345214	GPS 2 Wiring Harness and Ground Points - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 69.9	 -62	 96	5036.4 3380 01 Oct 2019	 31 Jul 2027*	 31 Aug 2027	0 0
Airframe										
345220	Flight Management System (FMS-6100) - Functional Test	HRS AFL MOS MSC		393.5 245 22.9		 O/C	6006.8 3969 30 Aug 2023			0 0
Airframe										
345221	Computer, Flight Management (No. 1) - Removal / Installation 822-0868-073 1115V	HRS AFL MOS MSC		393.5 245 22.9		 O/C	6006.8 3969 30 Aug 2023			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
345222	Computer, Flight Management (No. 2) - Removal / Installation 822-0868-073 HJMT	HRS AFL MOS MSC		393.5 245 22.9		 O/C	6006.8 3969 30 Aug 2023			0 0
Airframe										
345301	Diplexer, VOR / Locator - Removal / Installation 7-78B 7082	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 CHELTON INC
Airframe										
345302	Diplexer, Marker Beacon - Removal / Installation 10-520-10 1550	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
345303	VHF Navigation Receiver No. 1 - Removal / Installation 622-7194-201 YYCT	HRS AFL MOS MSC	TSN:28	6372.3 4205 268		 O/C	28 9 27 Mar 2003			0 0
Airframe										
345304	VHF Navigation Receiver No. 2 - Removal / Installation 622-7194-201 NGHF	HRS AFL MOS MSC	TSN:28 TSN:9	6372.3 4205 268		 O/C	28 9 27 Mar 2003			0 0
Airframe										
345305	Marker Beacon Antenna - Removal / Installation DMN27-1A 9854	HRS AFL MOS MSC	TSN:5036.4 TSN:3380 TSN:205	1363.9 834 70		 O/C	5036.4 3380 29 Sep 2019			0 0 N/A
Airframe										
345306	Antenna, VOR / LOC / GS No. 1 - Removal / Installation PN NOT INSTALLED	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
345307	Antenna, VOR / LOC / GS No. 2 - Removal / Installation 19-28 50244	HRS AFL MOS MSC	 TSN:4	1884.1 1180 119.9		 O/C	4516.2 3034 31 Jul 2015			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
345308	VHF Nav 1 Wiring Harness and Ground Points - Detailed Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71.2	-21	96	21 Aug 2019	31 Jul 2027*	31 Aug 2027	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: COMPLIED WITH CMP G200 345308 VHF NAV 1 WIRING HARNESS AND GROUND POINTS - DETAILED INSPECTION										
345309	VHF Nav 2 Wiring Harness and Ground Points - Detailed Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		69.9	-62	96	01 Oct 2019	31 Jul 2027*	31 Aug 2027	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
345310	VHF Navigation System - Functional Test	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		70.5			14 Sep 2019			
		MSC				O/C				
Airframe										
Notes: TIC BOX C/N: 557216 CAL DUE: 10, 2019.										
345401	Automatic Direction Finder System (ADF-462) No. 1 - Removal / Installation	HRS	TSN:28	6372.3			28			0
		AFL	TSN:9	4205			9			0
	622-7382-101 JC1K	MOS	TSN:8	267.9			30 Mar 2003			ROCKWELL COLLINS
		MSC				O/C				
Airframe										
345403	ADF Antenna (No. 1) - Removal / Installation	HRS	TSN:1659.7	1363.9			5036.4			0
	622-7384-001 463RK	AFL	TSN:1192	834			3380			0
		MOS	TSN:101	70.9			30 Aug 2019			N/A
		MSC				O/C				
Airframe										
345409	ADF (ADF-462) - Functional Test (Pre MOD G2-10052)	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		70.5			14 Sep 2019			
		MSC				O/C				
Airframe										
345501	ATC Transponder No. 1 - Removal / Installation	HRS		1363.9			5036.4			0
	622-9210-501 4PRFK	AFL		834			3380			0
	N/A N/A	MOS		70.9			30 Aug 2019			Collins
		MSC				O/C				
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
345502 Airframe	ATC Transponder No. 2 - Removal / Installation 622-9210-501 3MPA N/A N/A	HRS AFL MOS MSC		1363.9 834 70.9		 O/C	5036.4 3380 30 Aug 2019			0 0 Collins
345503 Airframe	Vir-432 - Removal / Installation 622-7194-201 YYCT	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
345504 Airframe	Vir-432 622-7194-201 NGHF	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
345505 Airframe	Antenna, ATC Transponder (Top) - Removal / Installation DMNI50-6-2 19613	HRS AFL MOS MSC	TSN:5036.4 TSN:3380 TSN:204	1363.9 834 70.9		 O/C	5036.4 3380 30 Aug 2019			0 0 N/A
345506 Airframe	Antenna, ATC Transponder (Bottom) - Removal / Installation DMNI50-6-2 19924	HRS AFL MOS MSC	TSN:5036.4 TSN:3380 TSN:205	1363.9 834 70.6		 O/C	5036.4 3380 08 Sep 2019			0 0 N/A
345508 Airframe	AIR Traffic Control (ATC) - SELF Test	HRS AFL MOS MSC		1732.7 1064 95.6		 O/C	4667.6 3150 09 Aug 2017			0 0
345512 Airframe	AIR Traffic Control Transponder No. 1 (FAR 91.413) - Ramp Test	HRS AFL MOS [End Of Month Item]		157.9 100 9.8		 24	6242.4 4114 03 Oct 2024	30 Sep 2026		0 0 CALIBRATION

Notes: IFR 6000 C/N: 563472, CAL DUE: 03/20

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
345513 Logbook Position	AIR Traffic Control Transponder No. 2 (FAR 91.413) - Ramp Test	HRS AFL MOS [End Of Month Item]		157.9 100 9.8		24	6242.4 4114 03 Oct 2024	30 Sep 2026		0 0 CALIBRATION
Airframe										
Notes: IFR 6000 C/N: 563472, CAL DUE: 03/20										
345516 Logbook Position	ATC Tdr 1 Wiring Harness and Ground Points - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71.2	-21	96	5036.4 3380 21 Aug 2019	31 Jul 2027*	31 Aug 2027	0 0
Airframe										
Notes: COMPLIED WITH CMP G200 345516 ATC TDR 1 WIRING HARNESS AND GROUND POINTS - DETAILED INSPECTION										
345517 Logbook Position	ATC Tdr 2 Wiring Harness and Ground Points - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71.2	-21	96	5036.4 3380 21 Aug 2019	31 Jul 2027*	31 Aug 2027	0 0
Airframe										
Notes: COMPLIED WITH CMP G200 345517 ATC TDR 2 WIRING HARNESS AND GROUND POINTS - DETAILED INSPECTION										
345550[U] Logbook Position	ADS-B Out Components - General Visual Inspection of Wiring, DDA, ADS-B Annunciator	HRS AFL MOS		177 113 11.9		60	6223.3 4101 30 Jul 2024	30 Jul 2029		0 0
Airframe										
Notes: Ref ICA attached for inspection details										
345551[U] Logbook Position	Digital Discrete Adapter (DDA) 08090021-6 1305	HRS AFL MOS MSC	TSN:1	1363.9 834 70.5		- -	5036.4 3380 14 Sep 2019			0 0 Sky Light Avionics
Airframe										
Notes: CMP G200 345551* DIGITAL DISCRETE ADAPTER (DDA)INSTALLATION PROCEDURE FAA STC ST03424CH REV K DATED 1/17/2019										
345601 Logbook Position	DME-442 No. 1 - Removal / Installation 622-7309-101 12H5D	HRS AFL MOS MSC		2674.9 1776 156.2		O/C	3725.4 2438 23 Jul 2012			0 0
Airframe										

ATA / U=Custom / Logbook Position	Description	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
345602	DME-442 No. 2 - Removal / Installation Part Number: 622-7309-101 SN: 027P	HRS		3985.2			2415.1			0
		AFL		2759			1455			0
		MOS		194.7			06 May 2009			
		MSC				O/C				
Airframe										
Notes: INTERMITTANT ON DISTANCE. PICKS UP VOR STATIONS WITH NO PROBLEM.										
345603	Antenna, DME No. 1 - Removal / Installation Part Number: DMNI50-6-2 SN: 19905	HRS	TSN:5036.4	1363.9			5036.4			0
		AFL	TSN:3380	834			3380			0
		MOS	TSN:205	70.6			08 Sep 2019			N/A
		MSC				O/C				
Airframe										
345604	Antenna, DME No. 2 - Removal / Installation Part Number: DMNI50-6-2 SN: 19938	HRS	TSN:5036.4	1363.9			5036.4			0
		AFL	TSN:3380	834			3380			0
		MOS	TSN:205	70.6			08 Sep 2019			N/A
		MSC				O/C				
Airframe										
345605	DME 1 Wiring Harness and Ground Points - Detailed Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71.2	-21	96	21 Aug 2019	31 Jul 2027*	31 Aug 2027	
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe										
Notes: COMPLIED WITH CMP G200 345605 DME 1 WIRING HARNESS AND GROUND POINTS - DETAILED INSPECTION										
345606	DME 2 Wiring Harness and Ground Points - Detailed Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71.2	-21	96	21 Aug 2019	31 Jul 2027*	31 Aug 2027	
	[End Of Month Item] [MOS: +1m/-1m]									
Airframe										
Notes: COMPLIED WITH CMP G200 345606 DME 2 WIRING HARNESS AND GROUND POINTS - DETAILED INSPECTION										
345610	Distance Measuring Equipment (DME) - Functional Test	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		70.5			14 Sep 2019			
		MSC				O/C				
Airframe										
Notes: TIC BOX C/N: 557216 CAL DUE: 10, 2019.										
346002	Configuration Module Part Number: 30701 SN: 216	HRS		6372.3			28			0
		AFL		4205			9			0
		MOS		268.2			21 Mar 2003			
		MSC				O/C				
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
347001 Airframe	Data Management Unit - Removal / Installation 400-045500-0211 M466	HRS AFL MOS MSC		4973.1 3430 224.4		O/C	1427.2 784 15 Nov 2006			0 0 GULFSTREAM BRN SPARES IPT
347002 Airframe	Dmu Configuration Module - Removal / Installation 31990-1-MOD1 10491	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
347010 Airframe	Airborne Flight Information System With FMS-Uns-1C (Aircraft 005 Thru Aircraft 051 Post MOD 7025) - Functional Test	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
347020 Airframe	Airborne Flight Information System With FMS-6100 - Functional Test	HRS AFL MOS MSC		6372.3 4205 267.9		O/C	28 9 30 Mar 2003			0 0
347021[U] Airframe	Data Converter 933612-02 1284	HRS AFL MOS MSC		3023.6 2026 168.5		-	3376.7 2188 14 Jul 2011			0 0
35 - Oxygen										
350001 Airframe	Oxygen Cylinder - Removal / Installation 806369-11 ALT282-38134	HRS AFL MOS MSC	TSN:84	343.7 211 21.5		O/C	6056.6 4003 12 Oct 2023			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
350002 Airframe	Valve, Shutoff Toggle No. 1 - Removal / Installation 170001 14114	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM SAV COMPLETION IPTS
350003 Airframe	Valve, Shutoff Toggle No. 2 - Removal / Installation 170001 14141	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 GULFSTREAM SAV COMPLETION IPTS
350004 Airframe	Pressure Switch - Removal / Installation 9152 079	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
350005 Airframe	Oxygen Cylinder - Discard 806369-11 ALT282-38134	HRS AFL MOS [End Of Month Item]		343.7 211 21.5		 180	6056.6 4003 12 Oct 2023	31 Dec 2031		0 0 MANUFACTURE
350006 Airframe	Oxygen Bottle / Regulator Assembly - Restore	HRS AFL MOS MSC [End Of Month Item]		343.7 211 21.5		 O/C	6056.6 4003 12 Oct 2023			0 0 HYDRO CHECK
350012 Airframe	Oxygen System - Servicing	HRS AFL MOS MSC		437.6 272 24.4		 O/C	5962.7 3942 15 Jul 2023			0 0
350020 Airframe	Oxygen Lines Security and Chaffing - Inspection	HRS AFL MOS MSC		6400.3 4214 265.1		 O/C	0 0 25 Jun 2003			0 0

Notes: NOTE: ON-CONDITION, AFTER MAINTENANCE, REPAIRS, REMOVAL, ETC.

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
350022	Oxygen Lines - Leak Test	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
		MSC				O/C				
Airframe										
Notes: NOTE: ON-CONDITION, AFTER MAINTENANCE, REPAIRS, REMOVAL, ETC.										
350025	Oxygen Fill System - Operational Check (Ccmr)	HRS		1477.9		4500	4922.4	9422.4	9472.4	0
		AFL		896			3318			0
		MOS		80.3			18 Nov 2018			
Airframe		[End Of Month Item] [HRS: +50/-50]								
351003	Crew Oxygen Mask Stowage Box (Pilot) - Removal / Installation	HRS		3686.5			2713.8			0
		AFL		2519			1695			0
	MXP347-7 SE26390	MOS		186.5			13 Jan 2010			INTERTECHNIQUE
		MSC				O/C				
Airframe										
Notes: BLINKER WOULD NOT FLASH WHEN TESTED.										
351004	Crew Oxygen Mask Stowage Box (Copilot) - Removal / Installation	HRS		3904.4			2495.9			0
		AFL		2705			1509			0
	MXP347-7 25916	MOS		192			27 Jul 2009			INTERTECHNIQUE
		MSC				O/C				
Airframe										
351005	Crew Oxygen Mask (Pilot) - Restore	HRS		343.7			6056.6			0
	MC10-13-150 SE64629	AFL		211			4003			0
		MOS		21.5		72	12 Oct 2023	31 Aug 2029		
Airframe		[End Of Month Item]								OVERHAUL
351006	Crew Oxygen Mask (Copilot) - Restore	HRS		343.7			6056.6			0
	MC10-13-150 SE57806	AFL		211			4003			0
		MOS		21.5		72	12 Oct 2023	30 Apr 2028		
Airframe		[End Of Month Item]								OVERHAUL
351007	Crew Oxygen Mask (Pilot) - Removal / Installation	HRS		343.7			6056.6			0
	MC10-13-150 SE64629	AFL		211			4003			0
		MOS		21.5			12 Oct 2023			
		MSC				O/C				
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
351008	Crew Oxygen Mask (Copilot) - Removal / Installation MC10-13-150 SE57806	HRS AFL MOS MSC		343.7 211 21.7		 O/C	6056.6 4003 05 Oct 2023			0 0
Airframe										
351011	Storage Box, Jumpseat Oxygen Mask MXB220 1593	HRS AFL MOS MSC		6372.3 4205 267.6		 O/C	28 9 10 Apr 2003			0 0 INTERTECHNIQUE
Airframe										
351012	Mask, Oxygen (Jumpseat) MW37-40 NSN	HRS AFL MOS MSC		343.7 211 21.5		 O/C	6056.6 4003 12 Oct 2023			0 0
Airframe										
351015	Crew Oxygen Masks (Pilot) - Detailed Inspection	HRS AFL MOS		343.7 211 21.7	 -21	 36	6056.6 4003 05 Oct 2023	 30 Sep 2026*	 31 Oct 2026	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m]									
351016	Crew Oxygen Masks (Copilot) - Detailed Inspection	HRS AFL MOS		343.7 211 21.7	 -21	 36	6056.6 4003 05 Oct 2023	 30 Sep 2026*	 31 Oct 2026	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m]									
351019	Crew Oxygen System - Operational Check	HRS AFL MOS		343.7 211 21.7	 -7	 36	6056.6 4003 05 Oct 2023	 30 Sep 2026*	 31 Oct 2026	0 0
Airframe	[End Of Month Item] [MOS: +1m/-1m]									
351022	Oxygen Mask Stowage Box (Jumpseat) - Visual Insp	HRS AFL MOS		296.2 192 19.8		500 	6104.1 4022 04 Dec 2023	6604.1	6629.1	0 0
Airframe	[HRS: +25/-25]									
351023	Oxygen Mask (Jumpseat) - Visual Inspection	HRS AFL MOS		296.2 192 19.8		500 	6104.1 4022 04 Dec 2023	6604.1	6629.1	0 0
Airframe	[HRS: +25/-25]									

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
352002 Logbook Position	Passenger Oxygen Control Panel - Removal / Installation 119077-14 059	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0 HONEYWELL HPG
Airframe										
352003 Airframe	Passenger Oxygen Regulator - Removal / Installation 4AS7510705-501 068	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
352007 Airframe	Passenger Mask Automatic Drop Down Function - Functional Check	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		343.7 211 21.7	-7	36	6056.6 4003 05 Oct 2023	30 Sep 2026*	31 Oct 2026	0 0
352008 Airframe	Passenger Oxygen System - Operational Check	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]		343.7 211 21.7	-6	1500 36	6056.6 4003 05 Oct 2023	7556.6 30 Sep 2026*	7606.6 31 Oct 2026	0 0
352009 Airframe	Passenger Oxygen Masks - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		343.7 211 21.7	-8	36	6056.6 4003 05 Oct 2023	30 Sep 2026*	31 Oct 2026	0 0
352022 Airframe	Therapeutic Oxygen Mask - Discard 801978-01 NSN	HRS AFL MOS [End Of Month Item]	TSN:10	177 113 11.9		36	6223.3 4101 30 Jul 2024	30 Sep 2026		0 0
352027 Airframe	Therapeutic Oxygen System - Operational Check	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		343.7 211 21.6	-12	36	6056.6 4003 10 Oct 2023	30 Sep 2026*	31 Oct 2026	0 0
352028 Airframe	Therapeutic Oxygen Mask - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		343.7 211 21.6	-12	36	6056.6 4003 10 Oct 2023	30 Sep 2026*	31 Oct 2026	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
352100 Airframe	Headliner, O2 Box (No. 1) MXB314 2832	HRS AFL MOS MSC		3904.4 2705 192.2		O/C	2495.9 1509 21 Jul 2009			0 0 GULFSTREAM DALLAS
352101 Airframe	Headliner, O2 Box (No. 2) MXB314 2837	HRS AFL MOS MSC		3904.4 2705 192.2		O/C	2495.9 1509 21 Jul 2009			0 0 GULFSTREAM DALLAS
352102 Airframe	Headliner, O2 Box (No. 3) MXB314 3800	HRS AFL MOS MSC		2674.9 1776 156.3		O/C	3725.4 2438 20 Jul 2012			0 0 GULFSTREAM DALLAS
352103 Airframe	Headliner, O2 Box (No. 4) MXB314 2822	HRS AFL MOS MSC		6372.3 4205 270		O/C	28 9 29 Jan 2003			0 0 GULFSTREAM DALLAS
352104 Airframe	Headliner, O2 Box (No. 5) MXB314 2824	HRS AFL MOS MSC		6372.3 4205 270		O/C	28 9 29 Jan 2003			0 0 GULFSTREAM DALLAS
352107 Airframe	Headliner, O2 Box (Lavatory) MXB220 1822	HRS AFL MOS MSC		2674.9 1776 156.3		O/C	3725.4 2438 20 Jul 2012			0 0 GULFSTREAM DALLAS
352120 Airframe	Masks, Headliner O2 Box (No. 1) - Life Limit MW37-40 NSN	HRS AFL MOS [End Of Month Item]		1179.9 732 58		72	5220.4 3482 27 Sep 2020	31 Oct 2025		0 0 N/A MANUFACTURE

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
Logbook Position	Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW									
352121	Masks, Headliner O2 Box (No. 2) - Life Limit MW37-40	NSN	HRS AFL MOS [End Of Month Item]	1179.9 732 58			72	5220.4 3482 27 Sep 2020	31 Oct 2025		0 0 N/A MANUFACTURE
Airframe											
352122	Masks, Headliner O2 Box (No. 3) - Life Limit MW37-40	NSN	HRS AFL MOS [End Of Month Item]	1179.9 732 58			72	5220.4 3482 27 Sep 2020	31 Oct 2025		0 0 N/A MANUFACTURE
Airframe											
352123	Masks, Headliner O2 Box (No. 4) - Life Limit MW37-40	NSN	HRS AFL MOS [End Of Month Item]	1179.9 732 58		477	72	5220.4 3482 27 Sep 2020	31 Aug 2026*		0 0 N/A MANUFACTURE
Airframe											
352124	Masks, Headliner O2 Box (No. 5) - Life Limit MW37-40	NSN	HRS AFL MOS [End Of Month Item]	1179.9 732 58		325	72	5220.4 3482 27 Sep 2020	31 Aug 2026*		0 0 N/A MANUFACTURE
Airframe											
352127	Masks, Headliner O2 Box (Lavatory) - Life Limit MW37-40	NSN	HRS AFL MOS [End Of Month Item]	1179.9 732 58		444	72	5220.4 3482 27 Sep 2020	31 Aug 2026*		0 0 N/A MANUFACTURE
Airframe											
352128	Masks, Headliner O2 Box (Jumpseat) - Life Limit MW37-40	NSN	HRS AFL MOS [End Of Month Item]	343.7 211 21.6			72	6056.6 4003 10 Oct 2023	31 Oct 2028		0 0 MANUFACTURE
Airframe											
352141	Mask, Headliner O2 (No.1) PN	SN-UNKNOWN	HRS AFL MOS MSC	6400.3 4214 275.9			O/C	0 0 01 Aug 2002			0 0
Airframe											
352142	Mask, Headliner O2 (No.2) PN	SN-UNKNOWN	HRS AFL MOS MSC	6400.3 4214 275.9			O/C	0 0 01 Aug 2002			0 0
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
352143	Mask, Headliner O2 (No.3) MW37-40	NSN	HRS AFL MOS MSC	TSN:12	1179.9 732 58		O/C	5220.4 3482 27 Sep 2020			0 0 N/A
Airframe											
352144	Mask, Headliner O2 (No.4) MW37-40	NSN	HRS AFL MOS MSC	TSN:12	1179.9 732 58		O/C	5220.4 3482 27 Sep 2020			0 0 N/A
Airframe											
352145	Mask, Headliner O2 (No.5) PN	SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe											
352146	Mask, Headliner O2 (No.6) MW37-40	NSN	HRS AFL MOS MSC	TSN:12	1179.9 732 58		O/C	5220.4 3482 27 Sep 2020			0 0 N/A
Airframe											
352147	Mask, Headliner O2 (No.7) PN	SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe											
352148	Mask, Headliner O2 (No.8) PN	SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe											
352149	Mask, Headliner O2 (No.9) MW37-40	NSN	HRS AFL MOS MSC	TSN:12	1179.9 732 58		O/C	5220.4 3482 27 Sep 2020			0 0 N/A
Airframe											
352150	Mask, Headliner O2 (No.10) PN	SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
352151	Mask, Headliner O2 (No.11)		HRS		6400.3			0			0
	PN	SN-UNKNOWN	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
352152	Mask, Headliner O2 (No.12)		HRS		1179.9			5220.4			0
	MW37-40	NSN	AFL		732			3482			0
			MOS	TSN:16	58			27 Sep 2020			N/A
			MSC				O/C				
Airframe											
352153	Mask, Headliner O2 (No.13)		HRS		1179.9			5220.4			0
	MW37-40	NSN	AFL		732			3482			0
			MOS	TSN:16	58			27 Sep 2020			N/A
			MSC				O/C				
Airframe											
352154	Mask, Headliner O2 (No.14)		HRS		1179.9			5220.4			0
	MW37-40	NSN	AFL		732			3482			0
			MOS	TSN:16	58			27 Sep 2020			N/A
			MSC				O/C				
Airframe											
352155	Mask, Headliner O2 (No.15)		HRS		1179.9			5220.4			0
	MW37-40	NSN	AFL		732			3482			0
			MOS	TSN:12	58			27 Sep 2020			N/A
			MSC				O/C				
Airframe											
352156	Mask, Headliner O2 (No.16)		HRS		1179.9			5220.4			0
	MW37-40	NSN	AFL		732			3482			0
			MOS	TSN:12	58			27 Sep 2020			N/A
			MSC				O/C				
Airframe											
352157	Mask, Headliner O2 (No.17)		HRS		1179.9			5220.4			0
	MW37-40	NSN	AFL		732			3482			0
			MOS	TSN:16	58			27 Sep 2020			N/A
			MSC				O/C				
Airframe											
352158	Mask, Headliner O2 (No.18)		HRS		1179.9			5220.4			0
	MW37-40	NSN	AFL		732			3482			0
			MOS	TSN:16	58			27 Sep 2020			N/A
			MSC				O/C				
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
352159	Mask, Headliner O2 (No.19) MW37-40 NSN	HRS AFL MOS MSC	TSN:12	1179.9 732 58		O/C	5220.4 3482 27 Sep 2020			0 0 N/A
Airframe										
352300	Passenger Oxygen Regulator - Removal / Installation 803333-01 068	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0 GULFSTREAM DALLAS MANUFACTURE
Airframe										
352306	Regulator, Passenger Oxygen (No. 2) 4AS7510706-001 3588	HRS AFL MOS MSC		6359.3 4199 266.3		O/C	41 15 20 May 2003			0 0 GULFSTREAM DALLAS
Airframe										
38 - Water/Waste										
380003	Waste Drain Sys (Below Floor) - Cond/Security of Mounting	HRS AFL MOS [HRS: +25/-25]		177 113 11.9	-2.9	1000	6223.3 4101 30 Jul 2024	7220.4*	7245.4	0 0
Airframe										
Notes: STC ICA GA22801A068 REV A - NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
380004	Waste Drain Sys (Below Floor) - Corrosion Insp	HRS AFL MOS [HRS: +25/-25]		177 113 11.9	-2.9	1000	6223.3 4101 30 Jul 2024	7220.4*	7245.4	0 0
Airframe										
Notes: STC ICA GA22801A068 REV A - NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
380006	Water Supply Sys Below Floor - Cond/Security of Mounting	HRS AFL MOS [HRS: +25/-25]		177 113 11.9	-2.9	1000	6223.3 4101 30 Jul 2024	7220.4*	7245.4	0 0
Airframe										
Notes: STC ICA GA22801A068 REV A - NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
380007 Airframe	Water Supply System - Leak Check	HRS AFL MOS [HRS: +25/-25]		445.3 275 25.2		1000	5955 3939 22 Jun 2023	6955	6980	0 0 N/A
Notes: PN: NPN SN: NSN.										
380010 Airframe	Water Fill Port Screens - Visual Inspection	HRS AFL MOS MSC		6061.3 4043 258.4		 O/C	339 171 16 Jan 2004			0 0
380030 Airframe	Drain Mast - Operational Test	HRS AFL MOS MSC		6400.3 4214 265.1		 O/C	0 0 25 Jun 2003			0 0
380040 Airframe	Heating Element Water Lines - Operational Check	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Notes: REMOVED REV 3										
381101 Airframe	Filter, Potable Water System - Replacement EV949000 NSN	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m] [HRS: +25/-25]		12.5 8 1.3		500 12	6387.8 4206 20 Jun 2025	6887.8 30 Jun 2026	6912.8 31 Jul 2026	0 0
Notes: PROCEDURE REFERENCE: G200 AMM 38-11-10: WATER FILTER — REMOVAL / INSTALLATION.										
381104 Airframe	Water Supply System - Purge	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m] [HRS: +25/-25]		12.5 8 1.3		500 12	6387.8 4206 20 Jun 2025	6887.8 30 Jun 2026	6912.8 31 Jul 2026	0 0
381201 Airframe	Two-Way Motor Operated Shut-Off Valve (Drain) - Removal / Installation D05A00 74	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 AAR COMPOSITES

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
381202	Four-Way Motor Operated Shut-Off Valve (Fill) - Removal / Installation D06E00 3769	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
381205	Water Level Probe - Removal / Installation 4AS1270084-003 0321	HRS AFL MOS MSC		3023.6 2026 168.5		 O/C	3376.7 2188 14 Jul 2011			0 0
Airframe										
381401	Water Tank - Removal / Installation 11-751800 067	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
381591	Water Supply Sys - Sink/Heater Conn/Drain - Corr/Discolor	HRS AFL MOS [HRS: +25/-25]		177 113 11.9	-2.9	1000	6223.3 4101 30 Jul 2024	7220.4*	7245.4	0 0
Airframe										
Notes: STC ICA GA22801A068 REV A - NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
381592	Water Supply Sys - Water Heater - Bonding Check	HRS AFL MOS [HRS: +25/-25]		177 113 11.9	-2.9	1000	6223.3 4101 30 Jul 2024	7220.4*	7245.4	0 0
Airframe										
Notes: STC ICA GA22801A068 REV A - NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
383001	Drain Mast - Removal / Installation 70WS001-210 BF8332	HRS AFL MOS MSC	TSN:9	1363.9 834 69.4		 O/C	5036.4 3380 17 Oct 2019			0 0 N/A
Airframe										
384002	AIR Manual Shut-Off Valve - Removal / Installation 6BS1008 0071	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										

45 - Central Maint System

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
451001 Airframe	Selecting Mfd Page PN SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
451003 Airframe	View Line Replacement Units (Lru) Fault History	HRS AFL MOS MSC		6372.3 4205 268.8		 O/C	28 9 04 Mar 2003			0 0
451009 Airframe	View Clock SET Operation	HRS AFL MOS MSC		6372.3 4205 267.9		 O/C	28 9 31 Mar 2003			0 0
451010 Airframe	View Aircraft SET Identification Operations	HRS AFL MOS MSC		6372.3 4205 267.9		 O/C	28 9 30 Mar 2003			0 0
451012 Airframe	View Report MODE Diagnostic	HRS AFL MOS MSC		6372.3 4205 268.8		 O/C	28 9 04 Mar 2003			0 0
451050 Airframe Notes: DEAD MEMORY BATTERY	Computer, Main Diagnostic (Mdc) - Removal / Installation 622-9818-653 36P4Y	HRS AFL MOS MSC		1732.7 1064 95.6		 O/C	4667.6 3150 09 Aug 2017			0 0 ROCKWELL COLLINS
453100 Airframe	Engine Indication and Crew Alerting System (Eicas) System Diagnostic	HRS AFL MOS MSC		6372.3 4205 267		 O/C	28 9 27 Apr 2003			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
459001	Engine Indication / Diagnostic Download	HRS		5253.3			1147			0
		AFL		3619			595			0
		MOS		236.3			18 Nov 2005			
Airframe		MSC				O/C				
49 - Airborne Auxiliary Power										
490001	APU - APU - Removal / Installation 3800710-1 P-103	HRS	TSN:1592	1643			1592			0
		APUS		1673			0			0
		MOS	TSN:11	92.7			06 Nov 2017			N/A
APU		MSC				O/C				
490003	APU - APU Hot Section - Inspection	HRS		2069			1166			0
		APUS		1673			0			0
		MOS		183.9			01 Apr 2010			
APU		MSC				O/C				
490004	APU - APU Inspection	HRS		3235			0			0
		APUS		1673			0			0
		MOS		316.8			04 Mar 1999			
APU		MSC				O/C				
490010	APU - APU Engine Operation - Functional Test	HRS		729			2506			0
		APUS		921			752			0
		MOS		45.7			05 Oct 2021			
APU		MSC				O/C				
491005	APU Mount (Left) - General Visual Inspection	HRS		1695.4			4704.9			0
		AFL		1043			3171			0
		MOS		92.8			03 Nov 2017			
Airframe		MSC				O/C				
491006	APU Mount (Right) - General Visual Inspection	HRS		1695.4			4704.9			0
		AFL		1043			3171			0
		MOS		92.8			03 Nov 2017			
Airframe		MSC				O/C				
491007	APU Mount (Top) - General Visual Inspection	HRS		1695.4			4704.9			0
		AFL		1043			3171			0
		MOS		92.8			03 Nov 2017			
Airframe		MSC				O/C				

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
491101 Airframe	APU Inlet Duct (External) - General Visual Inspection	HRS AFL MOS [HRS: +50/-50]		296.2 192 19.8	38.9	500	6104.1 4022 02 Dec 2023	6643*	6693	0 0
491203 APU	APU - APU Drain Lines - General Visual Inspection	HRS APUS MOS [HRS: +50/-50]		492.6 816 31.9	-10.4	1500	2742.4 857 30 Nov 2022	4232*	4282	0 0
Notes: DATA OBTAINED FROM APU S/N: P-103 LOGBOOK										
491204 APU	APU - APU Gearbox Vent Tube - Detailed Inspection	HRS APUS MOS [HRS: +50/-50]		492.6 816 31.9	-10.4	1500	2742.4 857 30 Nov 2022	4232*	4282	0 0
Notes: DATA OBTAINED FROM APU S/N: P-103 LOGBOOK										
492102 APU	APU - APU Inlet Duct (Internal) - General Visual Inspection	HRS APUS MOS [HRS: +50/-50]		492.6 816 31.9	-10.4	1500	2742.4 857 30 Nov 2022	4232*	4282	0 0
Notes: DATA OBTAINED FROM APU S/N: P-103 LOGBOOK										
492301 APU	APU - Compressor Rotor - Visual Inspection	HRS APUS MOS MSC		1750 1669 141.2		 O/C	1485 4 23 Oct 2013			0 0
Notes: DATA OBTAINED FROM APU S/N: P-103 LOGBOOK										
492302 APU	APU - APU Compressor Rotor - Discard 3822101-1 960350102713	HRS APUS MOS	TSN:1232 TSN:158	2003 1673 175.6		100000 100000	1232 0 09 Dec 2010	100000 100000		0 0 TURBINE ENGINE CONSULTANTS
Notes: DATA OBTAINED FROM APU S/N: P-103 LOGBOOK										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
492501 APU	APU - APU Turbine Rotor - Discard 3842064-1 961321601624	HRS APUS MOS	TSN:1232 TSN:158	2003 1673 175.6		5000 5000	1232 0 09 Dec 2010	5000 5000		0 0
Notes: DATA OBTAINED FROM APU S/N: P-103 LOGBOOK										
492602 APU	APU - APU Gearbox - General Visual Inspection	HRS APUS MOS [HRS: +50/-50]		307.3 674 25.9		1000	2927.7 999 31 May 2023	3927.7	3977.7	0 0
493001 APU	APU - APU Fuel Filter - Replacement 3882440-1 N/A	HRS APUS MOS [HRS: +50/-50]		307.3 674 25.7		1500	2927.7 999 06 Jun 2023	4427.7	4477.7	0 0
Notes: DATA OBTAINED FROM APU S/N: P-103 LOGBOOK										
493003 APU	APU - Fuel Control Unit (APU) 3882730-8 16900	HRS APUS MOS MSC		2003 1673 175.6		 O/C	1232 0 09 Dec 2010			0 0
Notes: DATA OBTAINED FROM APU S/N: P-103 LOGBOOK										
493004 APU	APU - APU Fuel Shutoff Valve 692545-17 SN-UNKNOWN	HRS APUS MOS MSC		3235 1673 316.8		 O/C	0 0 04 Mar 1999			0 0
493008 APU	APU - APU Fuel System Components - General Visual Inspection	HRS APUS MOS [HRS: +50/-50]		492.6 816 31.9	-10.4	1500	2742.4 857 30 Nov 2022	4232*	4282	0 0
Notes: DATA OBTAINED FROM APU S/N: P-103 LOGBOOK										
494001 APU	APU - APU Igniter Plug - Clean / Inspect	HRS APUS MOS MSC		2003 1673 175.6		 O/C	1232 0 09 Dec 2010			0 0
Notes: DATA OBTAINED FROM APU S/N: P-103 LOGBOOK										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
494002	APU - Control Unit, APU Generator		HRS		758			2477			0
	23091-004	Y20099	APUS		922			751			0
			MOS		69.8			02 Oct 2019			
			MSC				O/C				
APU											
Notes: AIRFRAME ITEM											
494003	APU - Ignition Unit (APU)		HRS	TSN:1232	2003			1232			0
	3888000-3	96404153	APUS		1673			0			0
			MOS	TSN:141	175.6			09 Dec 2010			HONEYWELL AVIATION AFTERMARKET SERVICES
			MSC				O/C				
APU											
Notes: DATA OBTAINED FROM APU S/N: P-103 LOGBOOK											
494005	APU - Lead, Ignition (APU)		HRS		3235			0			0
	3888302-6	NSN	APUS		1673			0			0
			MOS		316.8			04 Mar 1999			HONEYWELL ENGINES SYSTEMS & SERVICE
			MSC				O/C				
APU											
494006	APU - APU Igniter Plug - Removal / Installation		HRS		9			3226			0
	3888002-5	NSN	APUS		7			1666			0
			MOS		1.3			20 Jun 2025			
			MSC				O/C				
APU											
494101	APU - Engine Control Unit - Removal / Installation		HRS		1781			1454			0
	2118988-2	116-C0166	APUS		327			1346			0
			MOS		142.7			06 Sep 2013			HONEYWELL AVIATION AFTERMARKET SERVICES
			MSC				O/C				
APU											
494401	APU - APU Starter-Generator - Removal / Installation		HRS		307.3			2927.7			0
	23091-004	P1077	APUS		674			999			0
			MOS		25.7			07 Jun 2023			
			MSC				O/C				
APU											
Notes: TW 10-50567922 CAL DUE 04/20TW 40-200558036 CAL DUE 06/20TW 200-1000560380 CAL DUE 08/20TD 5-35562713 CAL DUE 03/20											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
494402 Logbook Position	APU - Goodrich APU Starter-Generator Brushes - Detailed Inspection	HRS APUS MOS [HRS: +50/-50]		307.3 674 25.7		500	2927.7 999 07 Jun 2023	3427.7	3477.7	0 0
APU										
Notes: PN: G3666-230 SN: 1193A. C/W AT INSTALLATION ON APU S/N P-103 12/13/2010. THIS UNIT O/H"D 3/30/2010 AND REMOVED FROM P-181 12/13/2010, WITH 393 APU HRS TSO.										
494403 APU	APU - APU Starter-Generator (Goodrich) - Restore 23091-004 P1077	HRS APUS MOS		307.3 674 25.9		900	2927.7 999 01 Jun 2023	3827.7		0 0
495001 Airframe	APU Door Actuator - Removal / Installation 221400-2M00 076	HRS AFL MOS MSC	TSN:23 TSN:15 TSN:10	4525.7 4214 265.7		O/C	1874.6 0 05 Jun 2003			0 0
495002 APU	APU - Valve, Surge (APU) 3884538-6 0252	HRS APUS MOS MSC		1751.9 1673 140.5		O/C	1483.1 0 14 Nov 2013			0 0 HONEYWELL ENGINES SYSTEMS & SERVICE
495201 APU	APU - Valve, Shutoff (APU Load Control) 109812-12 3619	HRS APUS MOS MSC		2201 1673 206.4		O/C	1034 0 16 May 2008			0 0
497007 APU	APU - APU Hourmeter Reading	HRS APUS MOS MSC		709 914 43		O/C	2526 759 29 Dec 2021			0 0
Notes: PN: 1232.0 HRS TSN SN: P-103. 1437.0 APU HRS										
498002 APU	APU - APU Exhaust Duct - General Visual Inspection	HRS APUS MOS [HRS: +50/-50]		729 921 44.7		1500	2506 752 05 Nov 2021	4006	4056	0 0
Notes: AIRFRAME ITEM										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
498003[U]	APU - APU - APU Exhaust Duct - General Visual Inspection (STC ST03570AT)	HRS APUS MOS				1500		4006	4056	0 0
APU		[HRS: +50/-50]								
Notes: Ref ICA attached for inspection details on pg 6 section 9. Next due aligned with 498002										
499001	APU - APU Drain Plug Magnetic Element - Inspection	HRS APUS MOS		25 26 2.2	 -23	750 12	3210 1647 23 May 2025	3960 30 Apr 2026*		0 0
APU		[End Of Month Item]								
499003	APU - APU Oil Filter - Discard 3608765-1 NSN	HRS APUS MOS		9 7 1.3	 -14	750 24	3226 1666 20 Jun 2025	3976 30 Jun 2027*	4026 31 Jul 2027	0 0
APU		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Notes: REF TO 25.88 FOR COMPLIANCE										
499004	APU - Oil Analysis (APU)	HRS APUS MOS MSC		9 7 1.3		 O/C	3226 1666 20 Jun 2025			0 0
APU										
Notes: DATA OBTAINED FROM APU S/N: P-103 LOGBOOK										
499007	APU - APU Magnetic Chip Detector - Detailed Inspection	HRS APUS MOS		9 7 1.3	 -5	750 24	3226 1666 20 Jun 2025	3976 30 Jun 2027*	4026 31 Jul 2027	0 0
APU		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
499010	APU - Sensor, APU Oil Level 2E3249 0094	HRS APUS MOS MSC	TSN:1811 TSN:3243 TSN:92	2003 1673 175.5		 O/C	1232 0 13 Dec 2010			0 0 EATON AEROSPACE
APU										
Notes: INSTALLED UNIT REMOVED FROM APU S/N:P-181										
49APU1	APU 3800710-1 P-103	HRS AFL MOS MSC	TSN:1592	1695.4 1043 92.8		 E/C	4704.9 3171 03 Nov 2017			0 0
Airframe										

ATA / U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
Logbook Position	Part Number	Serial Number									
	HW	SW									
	MM Ref										
	Ops Number(s)										
51 - STD Practices and Struct-Genrl											
510002	External Composite Components - Detailed Inspection		HRS		1363.9			5036.4			0
			AFL		834			3380			0
			MOS		71.2	-22	96	22 Aug 2019	31 Jul 2027*	31 Aug 2027	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
52 - Doors											
521002	Passenger / Crew Door - Removal / Installation		HRS		6300.3			100			0
	4AS3360080-430	SN-UNKNOWN	AFL		4168			46			0
			MOS		263.1			26 Aug 2003			
Airframe			MSC				O/C				
521003	Airstair Door Actuator - Removal / Installation		HRS		6400.3			0			0
	4013-4000-000-A-B-1	073	AFL		4214			0			0
			MOS		275.9			01 Aug 2002			
Airframe			MSC				O/C				
521004	Capstan - Removal / Installation		HRS	TSN:5036.4	1363.9			5036.4			0
	4AS3360010-011	012	AFL	TSN:3380	834			3380			0
			MOS	TSN:206	69.6			10 Oct 2019			N/A
Airframe			MSC				O/C				
521005	Capstan Spring - Restoration		HRS		6400.3			0			0
	4013-8000-000	SN-UNKNOWN	AFL		4214		10000	0	10000		0
			MOS		275.9			01 Aug 2002			
Airframe											
521007	Airstairs Assembly - Removal / Installation		HRS	TSN:5036.4	1363.9			5036.4			0
	4AS3360070-501	NSN	AFL	TSN:3380	834			3380			0
			MOS	TSN:205	70.2			21 Sep 2019			N/A
Airframe			MSC				O/C				
521008	Main Entrance Door Guide Tracks and Stops - Lubrication		HRS		296.2	38.9	500	6104.1	6643*	6693	0
			AFL		192			4022			0
			MOS		19.8			04 Dec 2023			
Airframe			[HRS: +50/-50]								

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
521009	Main Entry Door Axle Bearings - Cleaning	HRS		177			6223.3			0
		AFL		113			4101			0
		MOS		11.9		24	30 Jul 2024	31 Jul 2026	31 Aug 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
521010	Door, Forward Airspring Snubber 4AS3360106-009 NSN	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		25.4			16 Jun 2023			
Airframe		MSC				O/C				
521011	Door, Aft Airspring Snubber 4AS336016-009 NSN	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		25.4			16 Jun 2023			
Airframe		MSC				O/C				
521017	Main Entrance Door Drain Valve - Detailed Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71	-27	192	27 Aug 2019	31 Jul 2035*	31 Aug 2035	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
521022	Door Seals - Detailed Inspection	HRS		177		1500	6223.3	7723.3	7773.3	0
		AFL		113			4101			0
		MOS		11.9		12	30 Jul 2024	31 Jul 2025	31 Aug 2025	
Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
521023	Passenger / Crew Door Seal Pressurization - Operational Check	HRS		1179.9			5220.4			0
		AFL		732			3482			0
		MOS		55.4			16 Dec 2020			
Airframe		MSC				O/C				
521024	Passenger / Crew Door Tension Springs (Forward) - Discard 4AS3360289-001 SN-UNKNOWN	HRS								0
		AFL								0
		MOS								
Airframe		MSC				O/C				
		[End Of Month Item]								

Notes: Pn 4AS3360289-001 Is O/C

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
521025	Lifting Actuator Mechanical Slip Clutch - Operational Test	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		265.1			25 Jun 2003			
		MSC				O/C				
Airframe										
521031	Main Entrance Door Internal - Detailed Inspection	HRS		1179.9			5220.4			0
		AFL		732			3482			0
		MOS		58.1		72	25 Sep 2020	30 Sep 2026	31 Oct 2026	
Airframe	[End Of Month Item] [MOS: +1m/-1m]									
521032	Main Entrance Door Latching / Locking - Detailed Inspection	HRS		1179.9			5220.4			0
		AFL		732			3482			0
		MOS		58.1		72	25 Sep 2020	30 Sep 2026	31 Oct 2026	
Airframe	[End Of Month Item] [MOS: +1m/-1m]									
521033	Passenger / Crew Door Locking Mechanism Airsprings - Operational Check	HRS		445.3			5955			0
		AFL		275		1000	3939	4939		0
		MOS		26.2			22 May 2023			
Airframe										
521034	Passenger / Crew Door Tension Springs (Aft) - Discard	HRS		445.3			5955			0
	4AS3360289-001 NSN	AFL		275			3939			0
		MOS		25.4			16 Jun 2023			
		MSC				O/C				
Airframe										
Notes: Pn 4AS3360289-001 Is O/C										
521041	Passenger / Crew Door Airspring (Forward) - Removal / Installation	HRS		445.3			5955			0
		AFL		275			3939			0
	4AS3360276-503P B-1379	MOS		25.4			16 Jun 2023			
		MSC				O/C				
Airframe										
521042	Passenger / Crew Door Airspring (Aft) - Removal / Installation	HRS		445.3			5955			0
		AFL		275			3939			0
	4AS3360276-503P B-1380	MOS		25.4			16 Jun 2023			
		MSC				O/C				
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
521043	Passenger / Crew Door Interlock Device - Adjustment	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										
521044	Passenger / Crew Door Outer Operating Handle Stirrup - Operational Check	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										
521045	Passenger / Crew Door Outer Operating Handle - Operational Check	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										
521046	Passenger / Crew Door Inner Operating Handle Stirrup - Operational Check	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										
521047	Passenger / Crew Door Inner Operating Handle - Operational Check	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										
521048	Passenger / Crew Door Handles Interlock Latch - Operational Check	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										
521049	Passenger / Crew Door Pressure Plate - Operational Check	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
521050	Passenger / Crew Door Side Stops - Operational Check		HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
521051	Passenger / Crew Door Locking Cams - Operational Check		HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
521052	Passenger / Crew Door Raising Handle - Operational Check		HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
521053	Passenger / Crew Door Cam Followers - Operational Check		HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
521054	Passenger / Crew Door Handrail - Operational Check		HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
521055	Passenger / Crew Door Flapper-Sill - Operational Check		HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											
521056	Entry Door Telescopic Rods - Cleaning		HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
521057	Electrical Motor Actuator Assembly - Functional Test	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
		MSC				O/C				
Airframe										
521058	Passenger / Crew Door Limit Switch 21L - Removal / Installation MS27240-6 SN-UNKNOWN	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
		MSC				O/C				
Airframe										
522002	Emergency Exit Door - Removal / Installation 4AS3320036-001 CP4776	HRS		1179.9			5220.4			0
		AFL		732			3482			0
		MOS		58.4			15 Sep 2020			N/A
		MSC				O/C				
Airframe										
522003	Emergency Exit Door Microswitch - Removal / Installation PN SN-UNKNOWN	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
		MSC				O/C				
Airframe										
522004	Emergency Exit Door - Rigging	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
		MSC				O/C				
Airframe										
522006	Emergency Exit Door Release Mechanism - Operational Check	HRS		177			6223.3			0
		AFL		113			4101			0
		MOS		11.9		24	30 Jul 2024	31 Jul 2026	31 Aug 2026	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
522007	Emergency Exit Door Interior - Detailed Inspection	HRS		1884.1			4516.2			0
		AFL		1180			3034			0
		MOS		120.1	5	144	26 Jul 2015	31 Jul 2027*	31 Aug 2027	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										

Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
522202 Airframe	Ff 32B Emergency Exit Door Stop Fittings Attachment - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
522203 Airframe	Ff 32C Emergency Exit Door Stop Fittings - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 265.1		10000**	0 25 Jun 2003	10000	10500	0 0
522204 Airframe	Ff 33 Emergency Door Stoppers - Ndt Inspection	HRS AFL MOS [AFL: +250]		6400.3 275.9		5000**	0 01 Aug 2002	5000	5250	0 0
523002 Airframe	Cargo Compartment Door - Removal / Installation 4AS3330500-501 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
523003 Airframe	Cargo Compartment Door Seal - Removal / Installation 4AS3190432-007 NSN	HRS AFL MOS MSC	 TSN:4	1363.9 834 69.6		 O/C	5036.4 3380 09 Oct 2019			0 0
523006 Airframe	Cargo Compartment Door Balance Springs (Forward) - Removal / Installation 4AS3330440-505 NSN	HRS AFL MOS MSC		4417.5 3074 206.7		 O/C	1982.8 1140 06 May 2008			0 0
523008 Airframe	Cargo Door Weather Seal - Replacement PN SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
523009	Cargo Compartment Door - Operation Check	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
523012	Baggage Door (Door Open) - General Visual Inspection	HRS		296.2	38.9	500	6104.1	6643*	6693	0
		AFL		192			4022			0
		MOS		19.8			02 Dec 2023			
Airframe		[HRS: +50/-50]								
523013	Baggage Door Switches - Operational Check	HRS		757.3		5000	5643	10643	10693	0
		AFL		461			3753			0
		MOS		31.9			30 Nov 2022			
Airframe		[HRS: +50/-50]								
523014	Forward / Aft Baggage Door Hinge Assemblies - Detailed Inspection	HRS		1884.1			4516.2			0
		AFL		1180			3034			0
		MOS		120.1	6	144	25 Jul 2015	31 Jul 2027*	31 Aug 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
523015	Baggage Door Interior Structure - Detailed Inspection	HRS		1884.1			4516.2			0
		AFL		1180			3034			0
		MOS		120.1	6	144	25 Jul 2015	31 Jul 2027*	31 Aug 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
523016	Forward / Aft Baggage Door Hook Latch Assemblies - Detailed Inspection	HRS		1884.1			4516.2			0
		AFL		1180			3034			0
		MOS		120.1	6	144	25 Jul 2015	31 Jul 2027*	31 Aug 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
523017	Baggage Door Seal Landings - General Visual Inspection	HRS		1884.1			4516.2			0
		AFL		1180			3034			0
		MOS		120.1	6	144	25 Jul 2015	31 Jul 2027*	31 Aug 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
523018 Airframe	Cargo Compartment Door Locking Mechanism - Operation Check	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
523019 Airframe	Cargo Compartment Door Telescopic Tie ROD - Removal / Installation PN SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
524002 Airframe	Service Compartment Door - Removal / Installation 4AS3170200-430 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
524003 Airframe Notes: INFORMATION NOT PROVIDED	Environmental Control System Compartment Panel - Removal / Installation 4AS3170300-501 NSN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
524004 Airframe	Nose Avionics Door (Left) - Removal / Installation 4AS3112240-431 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
524006 Airframe	Nose Avionics Door (Right) - Removal / Installation 4AS3112240-432 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
524007 Airframe	Nose Avionics Compartment (Left) - Visual Inspection	HRS AFL MOS MSC		6400.3 4214 267.9		 O/C	0 0 30 Mar 2003			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
524008	Nose Avionics Compartment (Right) - Visual Inspection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		267.9			30 Mar 2003			
Airframe		MSC				O/C				
524009	Avionics Compartment Doors - General Visual Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71.3	-20	144	20 Aug 2019	31 Jul 2031*	31 Aug 2031	
Airframe	[End Of Month Item] [MOS: +1m/-1m]									
524011	Service Doors - Functional Test	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
524031	Refuel / Defuel Door Microswitch - Rigging	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
524032	Refuel Door Access Panel Microswitch - Removal / Installation	HRS		6400.3			0			0
	PN SN-UNKNOWN	AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
524033	Refuel Door Microswitch - Adjustment / Test	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
524053	Lower Cowl Door (Left) - Visual Inspection	HRS		6061.3			339			0
		AFL		4043			171			0
		MOS		258.3			20 Jan 2004			
Airframe		MSC				O/C				
524054	Lower Cowl Door (Right) - Visual Inspection	HRS		6061.3			339			0
		AFL		4043			171			0
		MOS		258.3			20 Jan 2004			
Airframe		MSC				O/C				

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
Logbook Position	Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW									
528001	Main Landing Gear Outboard Door (Left) - Removal / Installation		HRS	TSN:28	6372.3			28			0
			AFL	TSN:9	4205			9			0
	4AS2650201-501	278	MOS		267			29 Apr 2003			
			MSC				O/C				
Airframe											
528002	Main Landing Gear Inboard Door (Left) - Removal / Installation		HRS		6359.3			41			0
			AFL		4199			15			0
	4AS2610200-501	999C	MOS		266.3			20 May 2003			
			MSC				O/C				
Airframe											
528003	Main Landing Gear Outboard Door (Right) - Removal / Installation		HRS		6400.3			0			0
			AFL		4214			0			0
	4AS2650200-431	SN-UNKNOWN	MOS		275.9			01 Aug 2002			GULFSTREAM - MEMPHIS
			MSC				O/C				
Airframe											
528004	Main Landing Gear Inboard Door (Right) - Removal / Installation		HRS		6400.3			0			0
			AFL		4214			0			0
	4AS2650200-432	SN-UNKNOWN	MOS		275.9			01 Aug 2002			IAI PARTNERSHIP
			MSC				O/C				
Airframe											
53 - Fuselage											
530000	Aircraft Design Service Life		HRS		6400.3			0			0
	PN	NOT INSTALLED	AFL				20000**		20000		0
			MOS		264.3			18 Jul 2003			
Airframe											
530006	Bleed AIR Lines Inside of Service Compartment - Detailed Inspection		HRS		445.3			5955			0
			AFL		275			3939			0
			MOS		26.2		48	23 May 2023	31 May 2027	30 Jun 2027	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
530007	Bleed AIR Lines Inside of Ecs Panel - Detailed Inspection		HRS		445.3			5955			0
			AFL		275			3939			0
			MOS		26.2		48	23 May 2023	31 May 2027	30 Jun 2027	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
530008 Airframe	Nose Avionics Compartment (Internal) - Zonal Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		445.3 275 26.2		48	5955 3939 22 May 2023	31 May 2027	30 Jun 2027	0 0
530011 Airframe	Radome - Removal / Installation 4AS3110000-437 452	HRS AFL MOS MSC		1071.6 676 48.5		O/C	5328.7 3538 12 Jul 2021			0 0
530013 Airframe	Landing Gear and Doors - Zonal Inspection	HRS AFL MOS [HRS: +50/-50]	296.2 192 19.8		38.9	500	6104.1 4022 02 Dec 2023	6643*	6693	0 0
530014 Airframe	Nose Landing Gear Wheel Well and Doors - General Visual Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		6400.3 4214 264.3		144	0 0 18 Jul 2003	31 Jul 2025	31 Aug 2025	0 0
Notes: Per remarks, Next due 24 mos from Rev 36 date of 31 July 2023, then every 192 mos thereafter										
530025 Airframe	Main Entrance Door Frame Seals, Stopper - Inspection / Check	HRS AFL MOS MSC		6061.3 4043 258.4		O/C	339 171 16 Jan 2004			0 0
530026 Airframe	Baggage Door Frame Seals, Stoppers - Inspection / Check	HRS AFL MOS MSC		6061.3 4043 258.3		O/C	339 171 20 Jan 2004			0 0
530027 Airframe	Nose Section Upper Antenna Interface - Detailed Inspection	HRS AFL MOS MSC		3023.6 2026 168.9		O/C	3376.7 2188 01 Jul 2011			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
530028	Cockpit and Entrance Upper Antenna Interface - Detailed Inspection	HRS AFL MOS MSC		3023.6 2026 169		 O/C	3376.7 2188 28 Jun 2011			0 0
Airframe										
530029	Cockpit and Entrance Lower Antenna Interface - Detailed Inspection	HRS AFL MOS MSC		3023.6 2026 168.9		 O/C	3376.7 2188 01 Jul 2011			0 0
Airframe										
530030	Avionics and Service Compartment Door Seals - Inspection / Check	HRS AFL MOS MSC		6061.3 4043 258.4		 O/C	339 171 16 Jan 2004			0 0
Airframe										
530031	Aft Cabin Upper Antenna Interface - Detailed Inspection	HRS AFL MOS MSC		3023.6 2026 168.9		 O/C	3376.7 2188 01 Jul 2011			0 0
Airframe										
530032	Aft Cabin Above Floor Structures and Penetrations - Detailed Inspection	HRS AFL MOS MSC		1884.1 1180 120	 4 	 O/C	4516.2 3034 27 Jul 2015			0 0
Airframe		[End Of Month Item]								
530033	Aft Cabin Window Frames - Detailed Inspection	HRS AFL MOS		1884.1 1180 120.1	 6	 192	4516.2 3034 25 Jul 2015	31 Jul 2031*	31 Aug 2031	0 0
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
530034	Emergency Exit Cutout Frames (Upper and Lower Sills) - Detailed Inspection	HRS AFL MOS		1884.1 1180 120.1	 5	 192	4516.2 3034 26 Jul 2015	31 Jul 2031*	31 Aug 2031	0 0
Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
530035	Forward Cabin Upper Antenna Interface - Detailed Inspection	HRS AFL MOS MSC		3023.6 2026 168.9		 O/C	3376.7 2188 01 Jul 2011			0 0
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
530036	Aft Fuselage Upper Antenna Interface - Detailed Inspection	HRS AFL MOS MSC		3023.6 2026 168.9		 O/C	3376.7 2188 01 Jul 2011			0 0
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
530037	Aft Cabin Above Floor Antennas Penetration - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1884.1 1180 120	 4	 192	4516.2 3034 27 Jul 2015	 31 Jul 2031*	 31 Aug 2031	0 0
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
530038	Aft Fuselage Lower Antenna Interface - Detailed Inspection	HRS AFL MOS MSC		3023.6 2026 168.9		 O/C	3376.7 2188 01 Jul 2011			0 0
Airframe										
530041	Cockpit Above Floor - Zonal Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 70.4	 -47	 192	5036.4 3380 16 Sep 2019	 31 Jul 2035*	 31 Aug 2035	0 0
Airframe										
530042	Cabin Entrance Above Floor - Zonal Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71	 -29	 192	5036.4 3380 29 Aug 2019	 31 Jul 2035*	 31 Aug 2035	0 0
Airframe										
530043	Forward Cabin Above Floor - Zonal Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 70.4	 -47	 192	5036.4 3380 16 Sep 2019	 31 Jul 2035*	 31 Aug 2035	0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
530044 Airframe	Aft Cabin Above Floor - Zonal Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 70.9	-30	192	5036.4 3380 30 Aug 2019	31 Jul 2035*	31 Aug 2035	0 0
530045 Airframe	Lower Fuselage Aft Fairings - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		445.3 275 26.2		48	5955 3939 22 May 2023	31 May 2027	30 Jun 2027	0 0
530046 Airframe	Lower Fuselage Main Battery Compartment - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		445.3 275 26.1		48	5955 3939 25 May 2023	31 May 2027	30 Jun 2027	0 0
530047 Airframe	Aft Cabin Lavatory Above Floor - Cleaning	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 70.9	-30	192	5036.4 3380 30 Aug 2019	31 Jul 2035*	31 Aug 2035	0 0
530048 Airframe	Cabin Seat Tracks - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		6400.3 4214 264.3		96	0 0 18 Jul 2003	31 Jul 2025	31 Aug 2025	0 0
Notes: Per remarks, Next due 24 mos from Rev 36 date of 31 July 2023, then every 96 mos therafter										
530050 Airframe	Upper Antenna and Penetration Interface - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 70.9	-30	96	5036.4 3380 30 Aug 2019	31 Jul 2027*	31 Aug 2027	0 0
530051 Airframe	Lower Antenna and Penetration Interface - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 69.8	-63	96	5036.4 3380 02 Oct 2019	31 Jul 2027*	31 Aug 2027	0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
530052	Exterior Upper Antenna Doublers - Detailed Inspection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		264.3		192	18 Jul 2003	31 Jul 2027	31 Aug 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: Per Remarks, Aligned with 530050 then every 16C thereafter										
530053	Exterior Lower Antenna Doublers - Detailed Inspection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		264.3		192	18 Jul 2003	31 Jul 2027	31 Aug 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: Per Remarks, Aligned with 530051 then every 16C thereafter										
530055	Fuselage Drain Valve, Frame 4 and Frame 11 - Detailed Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71.2	-22	192	22 Aug 2019	31 Jul 2035*	31 Aug 2035	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
530056	Fuselage Drain Valve, Frame 29 - General Visual Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71	-27	192	27 Aug 2019	31 Jul 2035*	31 Aug 2035	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: REF ITEM 20.16 THIS WORK ORDER FOR SQUAWK										
530057	Fuselage Drain Valve, Frame 29 - Detailed Inspection	HRS		445.3		1000	5955	6955	7005	0
		AFL		275			3939			0
		MOS		26.3			19 May 2023			
Airframe		[HRS: +50/-50]								
530058	Baggage Compartment Drain Valve - Detailed Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71	-27	192	27 Aug 2019	31 Jul 2035*	31 Aug 2035	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
530059	Fuselage Drain Holes - General Visual Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71.3	-20	192	20 Aug 2019	31 Jul 2035*	31 Aug 2035	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
531001 Airframe	Ff 1A Forward Pressure Bulkhead - Ndt / Visual Inspection	HRS AFL MOS [AFL: +250]		6400.3 275.9		5000**	0 01 Aug 2002	5000	5250	0 0
531002 Airframe	Ff 2.1 Canopy Posts and Sills - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
531003 Airframe	Ff 3 Nose Landing Gear Wheel Well Cutout - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
531004 Airframe	Ff 4 Nose Landing Gear Lower Longerons - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
531005 Airframe	Ff 5 Entrance Door Cutout - Ndt Inspection	HRS AFL MOS [AFL: +250]		6400.3 275.9		5000**	0 01 Aug 2002	5000	5250	0 0
531006 Airframe	Ff 6 Emergency Exit Cutout - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
531007 Airframe	Ff 1B Forward Pressure Bulkhead - Ndt / Visual Inspection	HRS AFL MOS [AFL: +250]		6400.3 265.7		5000**	0 05 Jun 2003	5000	5250	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
531008 Airframe	Ff 1C Forward Pressure Bulkhead AT FS 105.07 (2669 MM) - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 265.7		10000**	0 05 Jun 2003	10000	10500	0 0
531009 Airframe	Ff 2.2 Cockpit Lower Sill Beam - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 265.7		10000**	0 05 Jun 2003	10000	10500	0 0
531010 Airframe	Ff 2.3 Canopy Frame FS 156.8 (3982 MM) - Ndt Inspection	HRS AFL MOS [AFL: +375]		6400.3 262.9		7500**	0 30 Aug 2003	7500	7875	0 0
531011 Airframe	Ff 2.4 Canopy Cockpit Lower Sill Beam - Ndt Inspection	HRS AFL MOS [AFL: +250]		6400.3 275.9		5000**	0 01 Aug 2002	5000	5250	0 0
531021 Airframe	Lower Fuselage FS 38.89 - FS 482.67 (988 MM - 12260 MM) - Zonal Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
531022 Airframe	Upper Fuselage External FS 65.5 - FS 483 (1633 MM - 12260 MM) (Viewed from Ground) - Zonal Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
531023 Airframe	External Aft Fuselage FS 482.67 - FS 760 (12260 MM - 19304 MM) (Viewed from Ground) - Zonal Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
531024	Service Compartment Above Floor (Internal) - Zonal Inspection	HRS		177			6223.3			0
		AFL		113			4101			0
		MOS		11.9		24	30 Jul 2024	31 Jul 2026	31 Aug 2026	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
531025	Right Side Emergency Exit Door - Zonal Inspection	HRS		177			6223.3			0
		AFL		113			4101			0
		MOS		11.9		24	30 Jul 2024	31 Jul 2026	31 Aug 2026	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531026	Upper Fuselage (from Stand) - Zonal Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.2		48	22 May 2023	31 May 2027	30 Jun 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531027	Aft Fuselage External (from Platform) - Zonal Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.2		48	22 May 2023	31 May 2027	30 Jun 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531031	Fuel Tank Bladder Fuel Probe Wire Harnesses - Detailed Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71.1	-25	96	25 Aug 2019	31 Jul 2027*	31 Aug 2027	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
531032	Fuel Tank Bladder Internal - Zonal Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71.1		96	25 Aug 2019	31 Aug 2027	30 Sep 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
531033	Above Fuselage Tank - Zonal Inspection	HRS		1884.1			4516.2			0
		AFL		1180			3034			0
		MOS		120	2	144	29 Jul 2015	31 Jul 2027*	31 Aug 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								

Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
531034	Fuel Tank Surround Structure - Zonal Inspection		HRS		1363.9			5036.4			0
			AFL		834			3380			0
			MOS		71.1	-25	192	25 Aug 2019	31 Jul 2035*	31 Aug 2035	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
531035	Baggage Compartment (Internal) - Zonal Inspection		HRS		1363.9			5036.4			0
			AFL		834			3380			0
			MOS		71	-27	96	27 Aug 2019	31 Jul 2027*	31 Aug 2027	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
531036	Baggage Compartment Below Floor (Internal) - Zonal Inspection		HRS		1363.9			5036.4			0
			AFL		834			3380			0
			MOS		71	-27	96	27 Aug 2019	31 Jul 2027*	31 Aug 2027	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
531037	Baggage Compartment Door Including Visible Portions of the Jamb - General Visual Inspection		HRS		1363.9			5036.4			0
			AFL		834			3380			0
			MOS		71	-27	96	27 Aug 2019	31 Jul 2027*	31 Aug 2027	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
531041	Ecs Compartment (Internal) - Zonal Inspection		HRS		177			6223.3			0
			AFL		113			4101			0
			MOS		11.9		24	30 Jul 2024	31 Jul 2026	31 Aug 2026	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
531043	Main Entrance Door Including Visible Portions of the Jamb - Zonal Inspection		HRS		1363.9			5036.4			0
			AFL		834			3380			0
			MOS		71.1	-26	96	26 Aug 2019	31 Jul 2027*	31 Aug 2027	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
Notes: SEE SQUAWKS 20.24, 20.25, 20.26											
531044	Service Compartment Door - Zonal Inspection		HRS		1363.9			5036.4			0
			AFL		834			3380			0
			MOS		71.2	-21	96	21 Aug 2019	31 Jul 2027*	31 Aug 2027	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
531045 Airframe	APU Service Door - Zonal Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71.2	-21	96	5036.4 3380 21 Aug 2019	31 Jul 2027*	31 Aug 2027	0 0
531051 Airframe	Fixed Window Frames - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1884.1 1180 120.1		192	4516.2 3034 26 Jul 2015	31 Jul 2031	31 Aug 2031	0 0
Notes: NEW FREQUENCY. ADJUSTED PER REV. 22										
531101 Airframe	Nose Avionics Compartment Upper and Lower Areas - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		6400.3 4214 264.3		192	0 0 18 Jul 2003	31 Jul 2025	31 Aug 2025	0 0
Notes: Per remarks, Next due 24 mos from Rev 36 date of 31 July 2023, then every 192 mos thereafter										
531201 Airframe	Side Frame AT Cockpit	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
531202 Airframe	Cts 1 Spars Lower Flanges to Lower Skin Attachment - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
531203 Airframe	Cts 2 Front Spar - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
531204 Airframe	Cts 3 Aft and Rear Spar Webs - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
531205 Logbook Position	Cts 4 Lower Skin to Wing Attachment - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe										
531206	Cts 5 Corner Beam - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe										
531207	Cts 6 Lower Skin Panels - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe										
531208	Cts 7 Shear Clips AT Cts Rib 925, Left and Right Side - Ndt Inspection	HRS AFL MOS [AFL: +250]		6400.3 275.9		 5000** 	0 01 Aug 2002	 5000 	 5250 	0 0
Airframe										
531210	Ff 31.2 Cockpit Side Frame AT FS 113.03 - FS 177.87 (2871 MM - 4518 MM) - Ndt Inspection	HRS AFL MOS [AFL: +250]		6400.3 275.9		 5000** 	0 01 Aug 2002	 5000 	 5250 	0 0
Airframe										
Notes: SET TO MASTER PER REV 17										
531211	Ff 31.1 Side Frame FS 139 (3533 MM) - Ndt Inspection	HRS AFL MOS [AFL: +250]		6400.3 275.9		 5000** 	0 01 Aug 2002	 5000 	 5250 	0 0
Airframe										
531215	Forward Pressure Bulkhead Aft Face - General Visual Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		319.5 200 20.6		 144	6080.8 4014 08 Nov 2023	 30 Nov 2035	 31 Dec 2035	0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
531301	Forward Cabin Upper Panel Assembly Internal, Including Skin, Substructure and Antennas Penetration - Detailed Inspection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		264.3	4518	192	18 Jul 2003	31 Jul 2027*	31 Aug 2027	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
531310	Lower Skin Underneath Forward Fuel Tank and Forward Fairing - General Visual Inspection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		264.3		192	18 Jul 2003	31 Jul 2035	31 Aug 2035	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: Per remarks, Next due 24 mos from Rev 36 date of 31 July 2023, then every 192 mos thereafter										
531501	Ff 30 Flight Compartment Below Floor - Visual Inspection	HRS		6400.3			0			0
		AFL				10000**		10000	10500	0
		MOS		275.9			01 Aug 2002			
Airframe		[AFL: +500]								
532001	Ff 7 Cabin Window Cutouts - Visual Inspection	HRS		6400.3			0			0
		AFL				10000**		10000	10500	0
		MOS		275.9			01 Aug 2002			
Airframe		[AFL: +500]								
532004	Cockpit Below Floor - Zonal Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		25.9		48	01 Jun 2023	30 Jun 2027	31 Jul 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
532006	Cabin Entrance Below Floor - Zonal Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		25.9		48	01 Jun 2023	30 Jun 2027	31 Jul 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
532007	Aft Cabin Below Floor - Zonal Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		25.9		48	01 Jun 2023	30 Jun 2027	31 Jul 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
532011 Airframe	Entrance AREA Interior Skin and Substructure on Aft Panel FS 178 - FS 229.20 (4521.20 - 5821 MM) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]	1363.9 834 71	-29	96	5036.4 3380 29 Aug 2019	31 Jul 2027*	31 Aug 2027	0 0
532012 Airframe	Entrance AREA Interior Skin and Substructure Below Floor - Detailed Inspection	HRS AFL MOS MSC [End Of Month Item]	1363.9 834 71	-29	O/C	5036.4 3380 29 Aug 2019			0 0
532015 Airframe	Main Entrance Door Surround Panel - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]	1363.9 834 71	-27	192	5036.4 3380 27 Aug 2019	31 Jul 2035*	31 Aug 2035	0 0
532017 Airframe	Interior Skin and Substructure Below Floor - Detailed Inspection	HRS AFL MOS MSC [End Of Month Item]	1363.9 834 70.9	-30	O/C	5036.4 3380 30 Aug 2019			0 0
532019 Airframe	Lower Panel Interior Skin and Substructure Below Floor - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]	1363.9 834 70.9	-30	96	5036.4 3380 30 Aug 2019	31 Jul 2027*	31 Aug 2027	0 0
532021 Airframe	Cockpit Interior Skin and Substructure Below Floor - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]	1363.9 834 70.9	-30	96	5036.4 3380 30 Aug 2019	31 Jul 2027*	31 Aug 2027	0 0
532023 Airframe	Forward Fuselage Interior Floor - General Visual Inspection	HRS AFL MOS MSC [End Of Month Item]	1363.9 834 71.3	-20	O/C	5036.4 3380 20 Aug 2019			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
532024	Forward Cabin Floor Support Structure - Detailed Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		70.9	-30	96	30 Aug 2019	31 Jul 2027*	31 Aug 2027	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
532025	Forward Cabin Below Floor - Zonal Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		70.9	-30	96	30 Aug 2019	31 Jul 2027*	31 Aug 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
532031	Radome Internal - Zonal Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71.3	-20	96	20 Aug 2019	31 Jul 2027*	31 Aug 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
532035	APU Enclosure Interior - Zonal Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71.2	-21	96	21 Aug 2019	31 Jul 2027*	31 Aug 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
532041	Forward Fuselage Lower Antenna Penetration - Detailed Inspection	HRS		1884.1			4516.2			0
		AFL		1180			3034			0
		MOS		120			27 Jul 2015			
		MSC				O/C				
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
532043	Forward Cabin Side Panel Assembly Internal, Including Interior Skin and Substructure Above Floor - Detailed Inspection	HRS		1884.1			4516.2			0
		AFL		1180			3034			0
		MOS		120	2	192	29 Jul 2015	31 Jul 2031*	31 Aug 2031	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
532044	Posts / Sills - General Visual Inspection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
		MSC				O/C				
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
532045 Airframe	Cockpit Interior Skin and Substructure Above Floor - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 70.4	-47	192	5036.4 3380 16 Sep 2019	31 Jul 2035*	31 Aug 2035	0 0
532046 Airframe	Forward Panel Interior Skin, Floor Structures, Antennas Penetration and Frames - Detailed Inspection	HRS AFL MOS MSC [End Of Month Item]		1363.9 834 70.9	-30	O/C	5036.4 3380 30 Aug 2019			0 0
532047 Airframe	Entrance AREA Interior Skin and Substructure Above Floor - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 70.1		192	5036.4 3380 25 Sep 2019	30 Sep 2035	31 Oct 2035	0 0
532048 Airframe	Upper Panel Assembly - Detailed Inspection	HRS AFL MOS MSC [End Of Month Item]		1363.9 834 70.4	-47	O/C	5036.4 3380 16 Sep 2019			0 0
532049 Airframe	Canopy Interior Skin - General Visual Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 70.9	-30	144	5036.4 3380 30 Aug 2019	31 Jul 2031*	31 Aug 2031	0 0
532051 Airframe Notes: NEW FREQUENCY. REV. 22	Posts / Sills (Pilot Windshield) - General Visual Inspection	HRS AFL MOS [End Of Month Item]		3023.6 2026 168.6		192	3376.7 2188 09 Jul 2011	31 Jul 2027		0 0
532052 Airframe Notes: NEW FREQUENCY. REV. 22	Posts / Sills (Copilot Windshield) - General Visual Inspection	HRS AFL MOS [End Of Month Item]		3023.6 2026 168.6		192	3376.7 2188 09 Jul 2011	31 Jul 2027		0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
532053	Posts / Sills (Pilot Side Window) - General Visual Inspection	HRS AFL MOS [End Of Month Item]		757.3 461 31.9		 192	5643 3753 30 Nov 2022	 30 Nov 2038		0 0
Airframe										
532054	Posts / Sills (Copilot Side Window) - General Visual Inspection	HRS AFL MOS [End Of Month Item]		757.3 461 31.9		 192	5643 3753 30 Nov 2022	 30 Nov 2038		0 0
Airframe										
532101	Cabin Skin to Aft Pressure Bulkhead	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
532102	Ff 18 Cabin Skin Longitudinal Splices - Visual Inspection	HRS AFL MOS [AFL: +500]	6400.3	 275.9		 10000**	0 01 Aug 2002	 10000	 10500	0 0
Airframe										
532201	Ff 11 Cabin Frame Splices - Visual Inspection	HRS AFL MOS [AFL: +500]	6400.3	 275.9		 10000**	0 01 Aug 2002	 10000	 10500	0 0
Airframe										
532202	Ff 12, Ff 13 Fuselage Frame Fittings and Splices - Visual Inspection	HRS AFL MOS [AFL: +500]	6400.3	 275.9		 10000**	0 01 Aug 2002	 10000	 10500	0 0
Airframe										
532203	Ff 40 Upper Main Entrance Door Stop Fittings - Ndt / Visual Inspection	HRS AFL MOS [AFL: +250]	6400.3	 275.9		 5000**	0 01 Aug 2002	 5000	 5250	0 0
Airframe										
Notes: REPEAT 5K LDG										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
532204 Airframe	Side Frame Attach to Pressure Floor Fittings	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
532206 Airframe	Ff 42 Cockpit Side Window Retainer - Visual Inspection	HRS AFL MOS [AFL: +250]		6400.3 275.9		5000**	0 01 Aug 2002	5000	5250	0 0
532207 Airframe	Ff 44 Nose Landing Gear Bay Bulkheads - Ndt Inspection	HRS AFL MOS [AFL: +250]		6400.3 275.9		5000**	0 01 Aug 2002	5000	5250	0 0
532208 Airframe	Ff 45 Nose Landing Gear Walls - Ndt Inspection	HRS AFL MOS [AFL: +250]		6400.3 275.9		5000**	0 01 Aug 2002	5000	5250	0 0
532209 Airframe	Ff 47 Fuselage Skin Frame Attachment - Ndt Inspection	HRS AFL MOS [AFL: +375]		6400.3 275.9		7500**	0 01 Aug 2002	7500	7875	0 0
532215 Airframe	Cts Lower Skin External Surface - General Visual Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]				192		31 Jul 2027	31 Aug 2027	0 0
532301 Airframe	Ff 9 Upper J-Longeron Splices - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
532302 Airframe	Ff 10 J-Longeron AT Aft Bulkhead - Ndt Inspection	HRS AFL MOS [AFL: +250]		6400.3 275.9		5000**	0 01 Aug 2002	5000	5250	0 0

Notes: SET TO MASTER PER REV 17

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
532501 Airframe	Ff 16A Pressure Floor to Aft Pressure Bulkhead Attachment - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
532502 Airframe	Ff 23 Pressure Floor Beams and Skin FS 461.34 - FS 471.26 (11718 - 11970 MM) - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
532503 Airframe	Ff 14 Side Frame Attachments - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
532504 Airframe	Ff 16B Pressure Floor Fitting Attachment - Ndt Inspection	HRS AFL MOS [AFL: +250]		6400.3 275.9		5000**	0 01 Aug 2002	5000	5250	0 0
533000 Airframe	Aft Fuselage Keel Beam Lower Skin Penetrations Internal, Below Aft Fuel Tank - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		6400.3 4214 264.3		144	0 0 18 Jul 2003	31 Jul 2025	31 Aug 2025	0 0
533001 Airframe	Cargo Comp Door Hinges - Visual Inspection	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
533002 Airframe	Ecs and Service Compartment Internal - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		6400.3 4214 264.3		144	0 0 18 Jul 2003	31 Jul 2025	31 Aug 2025	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
533005 Airframe	Nose Landing Gear Wheel Well - Zonal Inspection	HRS AFL MOS		296.2 192 19.8		500 96	6104.1 4022 02 Dec 2023	6604.1 31 Dec 2031	6654.1 31 Jan 2032	0 0
	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									
533007 Airframe	Main Landing Gear Wheel Wells (Left) - Zonal Inspection	HRS AFL MOS		296.2 192 19.8		500 72	6104.1 4022 02 Dec 2023	6604.1 31 Dec 2029	6654.1 31 Jan 2030	0 0
	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									
533008 Airframe	Main Landing Gear Wheel Wells (Right) - Zonal Inspection	HRS AFL MOS		296.2 192 19.8		500 72	6104.1 4022 02 Dec 2023	6604.1 31 Dec 2029	6654.1 31 Jan 2030	0 0
	[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]									
533010 Airframe	Cts Internal Surfaces - Detailed Inspection	HRS AFL MOS				 96		 31 Jul 2027	 31 Aug 2027	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
533011 Airframe	Cts Center Wing Box Wiring Connections Internal - Detailed Inspection	HRS AFL MOS		1363.9 834 71.1	 -25	 96	5036.4 3380 25 Aug 2019	 31 Jul 2027*	 31 Aug 2027	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
533012 Airframe	Cts Internal - Zonal Inspection	HRS AFL MOS		1363.9 834 71.1	 -25	 96	5036.4 3380 25 Aug 2019	 31 Jul 2027*	 31 Aug 2027	0 0
	[End Of Month Item] [MOS: +1m/-1m]									
Notes: REFER TO 20.35 AND 20.38 FOR SQUAWK										
533015 Airframe	Forward Fuel Tank Mating Surface and Attachment Fitting - General Visual Inspection	HRS AFL MOS		1363.9 834 71.2	 -23	 192	5036.4 3380 23 Aug 2019	 31 Jul 2035*	 31 Aug 2035	0 0
	[End Of Month Item] [MOS: +1m/-1m]									

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
533020 Airframe	Aft Pressure Bulkhead Aft Web - General Visual Inspection	HRS AFL MOS MSC		3904.4 2705 191.7		O/C	2495.9 1509 06 Aug 2009			0 0
533021 Airframe	Aft Pressure Bulkhead Forward Web - General Visual Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 70.9	-30	144	5036.4 3380 30 Aug 2019	31 Jul 2031*	31 Aug 2031	0 0
533022 Airframe	Aft Pressure Bulkhead Machined Lower Frame Forward Face - General Visual Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71.1	-25	144	5036.4 3380 25 Aug 2019	31 Jul 2031*	31 Aug 2031	0 0
533023 Airframe	Aft Pressure Bulkhead Machined Lower Frame Aft Face - General Visual Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71.1	-25	144	5036.4 3380 25 Aug 2019	31 Jul 2031*	31 Aug 2031	0 0
533025 Airframe	Baggage Compartment Forward Bulkhead Forward Face - General Visual Inspection	HRS AFL MOS MSC		3904.4 2705 191.7		O/C	2495.9 1509 06 Aug 2009			0 0
533101 Airframe Notes: ADDED PER REV 19	AF 1.4.1 Fuel Tank Bulkhead FS 520.47 (13220 MM) for Aircraft 047 Thru Aircraft 999 - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
533102 Airframe	AF 1.3.1 Stiffener Bl + / - 9.05 (+ / - 230 MM) AT Wl 82.06 (2085 MM) - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
533103 Airframe	AF 1.5 Fuel Tank Bulkhead FS 520.46 (13220 MM) Upper and Lower Shroud Fittings - Ndt Inspection	HRS AFL MOS [AFL: +250]		6400.3 275.9		5000**	0 01 Aug 2002	5000	5250	0 0
533104 Airframe	AF 2.3 Outer Skin Attachments to Right Side Frames FS 530.70 - FS 567.91 (13480 - 14425 MM) - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
533105 Airframe	AF 8 Fuselage Skin Lower Cutout Corner - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
533106 Airframe	AF 1.1, AF 1.2 Fuel Bulkhead FS 520.46 (13220 MM), Stiffeners Attachment to Bulkhead Web - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
533108 Airframe	AF 1.4.2 Fuel Tank Bulkhead FS 520.47 (13220 MM) - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
533109 Airframe	AF 1.4.3 Fuel Tank Bulkhead FS 520.47 (13220 MM) - X-Ray Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
533115	AF 1.3.3 Fuel Tank Bulkhead FS 520.47 (13220 MM) Stiffeners - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 262.9		 10000** 	0 30 Aug 2003	 10000 	 10500 	0 0
Airframe										
Notes: REPEAT 5K LDG										
533120	AF 1.6.1 Fuel Tank Bulkhead FS 520.47 (13220 MM) Upper AREA - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe										
533125	AF 1.6.2 Fuel Tank Bulkhead FS 520.47 (13220 MM) - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 258.9		 10000** 	0 31 Dec 2003	 10000 	 10500 	0 0
Airframe										
533200	Aft Fuselage Keel Beam Lower Skin Penetrations Internal, Below Baggage Compartment - General Visual Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		6400.3 4214 264.3		 144	0 0 18 Jul 2003	 31 Jul 2025	 31 Aug 2025	0 0
Airframe										
533201	Baggage Compartment Antenna Penetration Internal - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		6400.3 4214 264.3		 192	0 0 18 Jul 2003	 31 Jul 2025	 31 Aug 2025	0 0
Airframe										
533202	AF 2.1 Upper Frame FS 530.70 - FS 567.91 (13480 - 14425 MM) - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe										
533203	AF 2.2, AF 2.2A Side Frames FS 530.70 - FS 567.91 (13480 - 14425 MM) - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
533204 Airframe	AF 2.4 Baggage Compartment Side Frame Attachments - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
533205 Airframe Notes: REPEAT 5K LDG	AF 2.5 Baggage Compartment Inner Skin to Frame Splice - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
533206 Airframe	AF 2.6 Baggage Compartment Left Side Frame to Upper Segment Attachments - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
533207 Airframe	AF 2.7 Baggage Compartment Left Side Frame Outer Flange Attachments - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
533208 Airframe	HAT Section Stiffeners - Visual Inspection	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
533209 Airframe	AF 3.4, AF 3.5, AF 3.6, AF 3.7 and AF 3.8 Pressure Bulkhead AT FS 582 (14783 MM) - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
533210 Airframe	AF 3.5 Aft Upper Frames Segment - Visual Inspection	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
533211	AF 3.6 Aft Lower Flange Segment, Bl 280 - Visual Inspection	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
533212	AF 3.7 Aft Upper Flange Segment, Bl 450 - Visual Inspection	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
533213	AF 4 Baggage Door Cutout - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	10000	10500	0 0
Airframe										
533215	AF 5.1 Forward Engine Support Adapter Plate - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	10000	10500	0 0
Airframe										
533216	AF 5.2 Forward Engine Support Adapter Plate Walls and Ribs - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	10000	10500	0 0
Airframe										
533217	AF 5.3 Adapter Plate Shear Pin Holes - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	10000	10500	0 0
Airframe										
533218	AF 5.4 Forward Engine Support End Plate - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	10000	10500	0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
533219 Airframe	AF 5.5 Forward Beam to Fuselage Bulkhead Attachment - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
533221 Airframe	AF 5.6 Forward Beam Web - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
533222 Airframe	AF 5.7 Forward Engine Mount Adapter Plate Bolts and Shear Pins - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
533223 Airframe	AF 6.1 Aft Engine Support Fitting - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
533224 Airframe	AF 6.2 Aft Engine Support Fitting - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
533226 Airframe	AF 9 Frame FS 664.83 (FS 16887 MM) - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
533227 Airframe	Aft Fuselage Frame Station 16887 - Eddy Current	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
533228	AF 10 Frame FS 703.77 (17876 MM) Flange - Visual Inspection		HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe											
Notes: REPEAT 5K LDG											
533229	AF 11 Frame FS 717.36 (18221 MM) - Visual Inspection		HRS AFL MOS [AFL: +500]		6400.3 258.9		 10000** 	0 31 Dec 2003	 10000 	 10500 	0 0
Airframe											
Notes: REPEAT 5K LDG											
533230	AF 2.8 Inner Flange and Strap and Corner Fitting - Visual Inspection		HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe											
533231	AF 12 Aft Fuselage Diverter - Visual Inspection		HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe											
533235	AF 3.8 Peripheral Angle - Visual Inspection		HRS AFL MOS MSC		6400.3 4214 275.9 		 O/C	0 0 01 Aug 2002 	 	 	0 0
Airframe											
533240	AF 7.1 Baggage Door Hinges and Goosenecks - Visual Inspection		HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe											
533241	AF 7.2 Baggage Door Latch and Shaft - Ndt Inspection		HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
533301	Ff 20.1 Aft Pressure Bulkhead FS 482.67 (12260 MM) Circumferential Splice of Cabin Skin - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe										
Notes: REPEAT 5000										
533302	Ff 20.2 Aft Pressure Bulkhead AT FS 482.67 (12260 MM) Upper AREA - Ndt Inspection	HRS AFL MOS [AFL: +250]		6400.3 275.9		 5000** 	0 01 Aug 2002	 5000 	 5250 	0 0
Airframe										
533303	Ff 20.2 Aft Pressure Bulkhead AT FS 482.67 (12260 MM) Upper AREA - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe										
533304	Ff 20.3 Aft Pressure Bulkhead AT FS 482.67 (12260 MM) Upper AREA - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe										
533305	Ff 20.4 Aft Pressure Bulkhead Upper AREA - Ndt / X-Ray Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe										
533306	FF20.5 Longeron Attach Vis	HRS AFL MOS MSC		6400.3 4214 275.9 		 O/C	0 0 01 Aug 2002 			0 0
Airframe										
533307	Forward Beam Assembly - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		445.3 275 26.2		 192	5955 3939 23 May 2023	 31 May 2039	 30 Jun 2039	0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
533602	AF 3.1 Baggage Compartment Inner Skin Attachment to Pressure Bulkhead - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe										
533603	AF 3.2 Pressure Bulkhead FS 582 (14783 MM) Forward / Aft Webs Attachment to Upper / Lower CAP Crossbeams - Ndt / Visual	HRS AFL MOS [AFL: +250]		6400.3 275.9		 5000** 	0 01 Aug 2002	 5000 	 5250 	0 0
Airframe										
533605	AF 3.3.2 HAT Section Stiffeners on Pressure Bulkhead AT FS 583.96 (14833 MM) - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe										
533606	AF 3.3.3 HAT Section Stiffeners on Pressure Bulkhead AT FS 583.96 (14833 MM) - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe										
533608	AF 3.2.1 Pressure Bulkhead FS 582 (14783 MM) Aft Crossbeam Fingerplate Attachment (A/C 022 - 999) - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe										
535001	Forward Fairing (Internal) - Zonal Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		445.3 275 26.1		 48	5955 3939 26 May 2023	 31 May 2027	 30 Jun 2027	0 0
Airframe										
535002	Forward Fuel Tank (Internal) - Zonal Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		445.3 275 25.9		 48	5955 3939 30 May 2023	 31 May 2027	 30 Jun 2027	0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
535003	Upper Wing Fairings - Zonal Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.1		48	26 May 2023	31 May 2027	30 Jun 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
535004	Above Lower Wing Fairing - General Visual Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71.2	-22	96	22 Aug 2019	31 Jul 2027*	31 Aug 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
536001	Aft Beam Assembly - Detailed Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71	-27	192	27 Aug 2019	30 Sep 2036*	31 Oct 2036	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
539701	Tail Cone - Removal / Installation	HRS		1363.9			5036.4			0
	4AS6900010-501 067	AFL		834			3380			0
	NA NA	MOS		70.6			08 Sep 2019			N/A
Airframe		MSC				O/C				
54 - Nacelles/Pylons										
540005	Engine Inlet Ducts (Left) - Visual Inspection	HRS		6061.3			339			0
		AFL		4043			171			0
		MOS		258.3			20 Jan 2004			
Airframe		MSC				O/C				
540006	Engine Inlet Ducts (Right) - Visual Inspection	HRS		6061.3			339			0
		AFL		4043			171			0
		MOS		258.3			20 Jan 2004			
Airframe		MSC				O/C				
540013	Ignition Access Panel Fastener (Left) - Inspection	HRS		6061.3			339			0
		AFL		4043			171			0
		MOS		258.4			16 Jan 2004			
Airframe		MSC				O/C				
540014	Ignition Access Panel Fastener (Right) - Inspection	HRS		6061.3			339			0
		AFL		4043			171			0
		MOS		258.4			16 Jan 2004			
Airframe		MSC				O/C				

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
541001	Powerplant and Cowl Doors (Left) - Internal Zonal Inspection	HRS AFL MOS		296.2 192 19.8	38.9	500	6104.1 4022 03 Dec 2023	6643*	6693	0 0
Airframe		[HRS: +50/-50]								
541002	Powerplant and Cowl Doors (Right) - Internal Zonal Inspection	HRS AFL MOS		296.2 192 19.8	38.9	500	6104.1 4022 03 Dec 2023	6643*	6693	0 0
Airframe		[HRS: +50/-50]								
541003	Thrust Reverser and Exhaust (Left) - Zonal Inspection	HRS AFL MOS		296.2 192 19.8	38.9	500	6104.1 4022 03 Dec 2023	6643*	6693	0 0
Airframe		[HRS: +50/-50]								
Notes: SEE 16.11 FOR MINOR CORROSION. 16.12 FOR LOOSE RIVET										
541004	Thrust Reverser and Exhaust (Right) - Zonal Inspection	HRS AFL MOS		296.2 192 19.8	38.9	500	6104.1 4022 03 Dec 2023	6643*	6693	0 0
Airframe		[HRS: +50/-50]								
Notes: #2 ENGINE THRUST REVERSER HAS SURFACE CORROSION ON INNER AFT- MARKEDREF:15.30										
541005	Left Powerplant (Viewed from Ground) - Zonal Inspection	HRS AFL MOS		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
541006	Right Powerplant (Viewed from Ground) - Zonal Inspection	HRS AFL MOS		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
541007	Nose Cowl Inlet (Left) - Zonal Inspection	HRS AFL MOS		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
Airframe		[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
541008	Nose Cowl Inlet (Right) - Zonal Inspection		HRS		177			6223.3			0
			AFL		113			4101			0
			MOS		11.9		24	30 Jul 2024	31 Jul 2026	31 Aug 2026	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
541009	Left Powerplant (Viewed from Platform) - Zonal Inspection		HRS		445.3			5955			0
			AFL		275			3939			0
			MOS		25.9		48	30 May 2023	31 May 2027	30 Jun 2027	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
Notes: NO SQUAWKS											
541010	Right Powerplant (Viewed from Platform) - Zonal Inspection		HRS		445.3			5955			0
			AFL		275			3939			0
			MOS		25.9		48	30 May 2023	31 May 2027	30 Jun 2027	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
545001	Pylon (Internal) (Left) - Zonal Inspection		HRS		445.3			5955			0
			AFL		275			3939			0
			MOS		26.1		48	26 May 2023	31 May 2027	30 Jun 2027	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
545002	Pylon (Internal) (Right) - Zonal Inspection		HRS		445.3			5955			0
			AFL		275			3939			0
			MOS		26.1		48	26 May 2023	31 May 2027	30 Jun 2027	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
545003	Pylon (Internal Visible Portions) (Left) - Detailed Inspection		HRS		445.3			5955			0
			AFL		275			3939			0
			MOS		26.2		192	23 May 2023	31 May 2039	30 Jun 2039	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								
545004	Pylon (Internal Visible Portions) (Right) - Detailed Inspection		HRS		445.3			5955			0
			AFL		275			3939			0
			MOS		26.2		192	23 May 2023	31 May 2039	30 Jun 2039	
Airframe			[End Of Month Item] [MOS: +1m/-1m]								

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
545005	Pylon (Internal Borescope) (Left) - Special Detailed Inspection	HRS		1053.8			5346.5			0
		AFL		664			3550			0
		MOS		45.8		192	04 Oct 2021	04 Oct 2037	04 Nov 2037	
		[MOS: +1m/-1m]								
Airframe										
545006	Pylon (Internal Borescope) (Right) - Special Detailed Inspection	HRS		1053.8			5346.5			0
		AFL		664			3550			0
		MOS		45.8		192	04 Oct 2021	04 Oct 2037	04 Nov 2037	
		[MOS: +1m/-1m]								
Airframe										
55 - Stabilizers										
550003	External Horizontal Stabilizers and Elevators (Viewed from Ground) - Zonal Inspection	HRS		177			6223.3			0
		AFL		113			4101			0
		MOS		11.9		24	30 Jul 2024	31 Jul 2026	31 Aug 2026	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
550006	Horizontal Stabilizer Aft Face of Rear Spar and Elevator - Zonal Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71.2	-21	96	21 Aug 2019	31 Jul 2027*	31 Aug 2027	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
550007	Vertical Stabilizer Aft Face of Rear Spar and Rudder - Zonal Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71.2	-21	96	21 Aug 2019	31 Jul 2027*	31 Aug 2027	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
550011	Horizontal Stabilizer Scissor - Lubrication	HRS		445.3		1000	5955	6955	7005	0
		AFL		275			3939			0
		MOS		25.9		48	01 Jun 2023	30 Jun 2027	31 Jul 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
550012	Horizontal Stabilizer Hinge Aft Fitting - Lubrication	HRS		445.3		1000	5955	6955	7005	0
		AFL		275			3939			0
		MOS		25.9		48	01 Jun 2023	30 Jun 2027	31 Jul 2027	
Airframe		[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
550013	Horizontal Stabilizer - Vertical Deflection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
550016	Elevator Lower Surface - Visual Inspection	HRS		4787.6			1612.7			0
		AFL		3321			893			0
		MOS		219			27 Apr 2007			
Airframe		MSC				O/C				
550025	External Horizontal Stabilizers and Elevators (Viewed from Platform) - Zonal Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		25.9		48	01 Jun 2023	30 Jun 2027	31 Jul 2027	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
550026	External Vertical Stabilizer and Rudder (Viewed from Platform) - Zonal Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		25.9		48	01 Jun 2023	30 Jun 2027	31 Jul 2027	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
550027	Stabilizers, Rudder and Elevator Attachment Fittings - Detailed Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71	-27	144	27 Aug 2019	31 Jul 2031*	31 Aug 2031	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: REF: 20.40, 20.41, & 20.42										
550028	Elevator Leading Edge Ribs - General Visual Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71	-27	144	27 Aug 2019	31 Jul 2031*	31 Aug 2031	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
551001	Horizontal Stabilizer - Removal / Installation 4AS4500001-505 068	HRS	TSN:5036.4	1363.9			5036.4			0
		AFL	TSN:3380	834			3380			0
		MOS	TSN:206	69.8			03 Oct 2019			N/A
Airframe		MSC				O/C				
Notes: TORQUE WRENCH 555689 CALBRATION DUE: 09/2020TORQUE WRENCH 560380 CALIBRATION DUE: 08/2020										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
551002 Airframe	E 8.1 Horizontal Stabilizer Actuator, Lower Attachment - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
551003 Airframe	E 8.2 Center U-Fitting 3/8 Inch Bolt Hole - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
551004 Airframe	E 8.3 Center U-Fitting 5/16 Inch Bolt Hole - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
551015 Airframe	Horizontal Stabilizer Tip - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71.2	-21	192	5036.4 3380 21 Aug 2019	31 Jul 2035*	31 Aug 2035	0 0
551016 Airframe	Horizontal Stabilizer Box (Internal) - Zonal Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71	-27	192	5036.4 3380 27 Aug 2019	31 Jul 2035*	31 Aug 2035	0 0
551020 Airframe	E 1.4A Horizontal Stabilizer Aft Attachment Sleeves and Pins - Visual Inspection	HRS AFL MOS [AFL: +250]		6400.3 275.9		5000**	0 01 Aug 2002	5000	5250	0 0
551101 Airframe	E 4 Horizontal Stabilizer Upper Skin Cutout - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
551201 Airframe	E 3 Horizontal Stabilizer Skin / Spar Attachments - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
551402 Airframe	E 1.1 Horizontal Stabilizer Aft Attachment Lug Fittings - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
551403 Airframe	E 1.2 Horizontal Stabilizer Attachment Fittings - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
551404 Airframe	E 1.3 Vertical Stabilizer Attachment Fittings - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
551405 Airframe	E 1.4 Horizontal Stabilizer Aft Attachment Sleeves and Pins - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
551407 Airframe	E 2 Horizontal Stabilizer Actuator, Upper Attachment - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
551408 Airframe	E 1.6 Vertical Stabilizer Fitting Attachment Bolts - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
551410	E 1.5A Horizontal Stabilizer Aft Spar (Aircraft 028 Thru Aircraft 999) - Ndt Inspection		HRS AFL MOS [AFL: +500]		6400.3 258.9		 10000** 	0 31 Dec 2003	 10000 	 10500 	0 0
Airframe											
Notes: REPEAT 5K LDG											
551411	E 1.5B Horizontal Stabilizer Aft Spar - Ndt Inspection		HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe											
552001	E 11.1 Elevator Attachment Lugs - Visual Inspection		HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe											
552002	E 11.2 Elevator External Structure - Ndt / Visual Inspection		HRS AFL MOS [AFL: +375]		6400.3 275.9		 7500** 	0 01 Aug 2002	 7500 	 7875 	0 0
Airframe											
Notes: AFTER 17,500 INSPECTION RESET FREQ TO 20,000 LDGS PER REV 17											
552003	E11.3 - Composite Material Skin - Ultrasonic		HRS AFL MOS MSC		6400.3 4214 275.9 		 O/C	0 0 01 Aug 2002 	 	 	0 0
Airframe											
552005	External Vertical Stabilizer and Rudder (Viewed from Ground) - Zonal Inspection		HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		177 113 11.9		 24	6223.3 4101 30 Jul 2024	 31 Jul 2026	 31 Aug 2026	0 0
Airframe											
552006	Elevator External - Detailed Inspection		HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1884.1 1180 120.1	6	 144	4516.2 3034 25 Jul 2015	 31 Jul 2027*	 31 Aug 2027	0 0
Airframe											
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
552007	Elevator Box Structure (Internal) - Zonal Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71	-27	192	27 Aug 2019	31 Jul 2035*	31 Aug 2035	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
552401	E 5.1 Elevator Support Structure Hinge Support Fittings - Visual Inspection	HRS		6400.3			0			0
		AFL				10000**		10000	10500	0
		MOS		275.9			01 Aug 2002			
Airframe		[AFL: +500]								
552405	E 5.2 Elevator Support Structures, Actuator and Link Fittings - Visual Inspection	HRS		6400.3			0			0
		AFL				10000**		10000	10500	0
		MOS		275.9			01 Aug 2002			
Airframe		[AFL: +500]								
Notes: REPEAT 5K LDG										
553001	Rudder Support Structures, Hinge Support Fittings (Inspection Point E9)- Visual Inspection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
		MSC				O/C				
Airframe										
553002	E9.2 Support Fitting B on Vert Stab Aft Spar	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
		MSC				O/C				
Airframe										
553003	E9.3 Support Fitting C on Vert Stab Aft Spar	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
		MSC				O/C				
Airframe										
553004	E9.4 Support Fitting D on Vert Stab Aft Spar	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
		MSC				O/C				
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
553005	E 9 Rudder Support Structures, Hinge Support Fittings - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
Airframe										
553011	Vertical Stabilizer Box (Internal) - Zonal Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71	-27	192	5036.4 3380 27 Aug 2019	31 Jul 2035*	31 Aug 2035	0 0
Airframe										
553201	E 7 Vertical Stabilizer Rib No. 1 Cutouts - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
Airframe										
553402	E 6.1 Vertical Stabilizer Aft Spar Attachment AT FS 704 (17876 MM) - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
Airframe										
553403	E 6.2 Vertical Stabilizer Forward Spar Attachment AT FS 665 (16886 MM) - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
Airframe										
553404	E 6.3 Vertical Stabilizer Aft Spar Attachment AT FS 704 (17876 MM) - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
Airframe										
553405	E 6.4 Vertical Stabilizer Forward Spar Attachment AT FS 665 (16886 MM) - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
553406 Airframe	E 6.5 Vertical Stabilizer Aft Spar Attachment AT FS 665 (16886 MM) and FS 704 (17876 MM) - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
554001 Airframe	Rudder (Internal) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1884.1 1180 120.1	5	144	4516.2 3034 26 Jul 2015	31 Jul 2027*	31 Aug 2027	0 0
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
554002 Airframe	Rudder Box Structure (Internal) - Zonal Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71	-27	192	5036.4 3380 27 Aug 2019	31 Jul 2035*	31 Aug 2035	0 0
554101 Airframe	E 10.2 Rudder External Structure - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
554102 Airframe	E10.3 - Rudder External Surface - Ndt Inspection	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
554402 Airframe	E 10.1 Rudder Attachment Lugs - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
56 - Windows										
561004 Airframe	Flight Compartment Windshield (Pilot) - Removal / Installation NP-178201-23 24086H4255	HRS AFL MOS MSC	TSN:6	157.9 100 9.8		 O/C	6242.4 4114 03 Oct 2024			0 0

ATA U=Custom / Logbook Position	Description / Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
561005	Flight Compartment Windshield (Copilot) - Removal / Installation		HRS		146.1			6254.2			0
			AFL		89			4125			0
	NP178201-12	24262H1975	MOS		9.1			25 Oct 2024			
			MSC				O/C				
	Airframe										
561006	Flight Compartment Side Window (Pilot) - Removal / Installation		HRS		757.3			5643			0
			AFL		461			3753			0
	NP-178202-15	22259H4777	MOS	TSN:1	31.9			30 Nov 2022			
			MSC				O/C				
	Airframe										
Notes: TW-562028 DUE- 09/19											
561007	Flight Compartment Side Window (Copilot) - Removal / Installation		HRS		757.3			5643			0
			AFL		461			3753			0
	NP-178202-16	22314H9155	MOS		31.9			30 Nov 2022			
			MSC				O/C				
	Airframe										
561045	Cockpit Windows Exterior Moisture Seal - Detailed Inspection		HRS		33.1		500	6367.2	6867.2	6917.2	0
			AFL		21			4193			0
			MOS		2.2	8	12	23 May 2025	31 May 2026*	30 Jun 2026	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
	Airframe										
561101	Flight Compartment Windows Hydrophobic Coating (Post Sb 200-05-280) - Detailed Inspection		HRS		33.1		500	6367.2	6867.2	6917.2	0
			AFL		21			4193			0
			MOS		2.2	-4	12	23 May 2025	31 May 2026*	30 Jun 2026	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
	Airframe										
57 - Wings											
570005	Left Wing Upper and Lower Skin (Exterior) - Zonal Inspection		HRS		177			6223.3			0
			AFL		113			4101			0
			MOS		11.9		24	30 Jul 2024	31 Jul 2026	31 Aug 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
	Airframe										

ATA U=Custom / Logbook Position	Description / Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
570006	Right Wing Upper and Lower Skin (Exterior) - Zonal Inspection		HRS		177			6223.3			0
			AFL		113			4101			0
			MOS		11.9		24	30 Jul 2024	31 Jul 2026	31 Aug 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
570015	Leading Edge Composite Component Surfaces (External Left) - Detailed Inspection		HRS		177			6223.3			0
			AFL		113			4101			0
			MOS		11.9		24	30 Jul 2024	31 Jul 2026	31 Aug 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
570016	Leading Edge Composite Component Surfaces (External Right) - Detailed Inspection		HRS		177			6223.3			0
			AFL		113			4101			0
			MOS		11.9		24	30 Jul 2024	31 Jul 2026	31 Aug 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
570017	Leading Edge Composite Component Surfaces (Internal Left) - Detailed Inspection		HRS		157.9			6242.4			0
			AFL		100			4114			0
			MOS		9.8	-15	24	03 Oct 2024	30 Sep 2026*	31 Oct 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: Hyd Mule											
570018	Leading Edge Composite Component Surfaces (Internal Right) - Detailed Inspection		HRS		157.9			6242.4			0
			AFL		100			4114			0
			MOS		9.8	-15	24	03 Oct 2024	30 Sep 2026*	31 Oct 2026	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											
Notes: Hyd Mule											
570019	Wing Box Internal Surfaces, Cts Web to Rib 18 (Left) - Detailed Inspection		HRS								0
			AFL								0
			MOS				96		31 Jul 2027	31 Aug 2027	
			[End Of Month Item] [MOS: +1m/-1m]								
Airframe											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
570023 Airframe	Wing Rear Spar (Left) - Zonal Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		445.3 275 25.9		48	5955 3939 01 Jun 2023	30 Jun 2027	31 Jul 2027	0 0
570024 Airframe	Wing Rear Spar (Right) - Zonal Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		445.3 275 25.9		48	5955 3939 01 Jun 2023	30 Jun 2027	31 Jul 2027	0 0
570025 Airframe	Wing Box Structure Internal (Left) - General Visual Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71.1	-24	96	5036.4 3380 24 Aug 2019	31 Jul 2027*	31 Aug 2027	0 0
570026 Airframe	Wing Box Structure Internal (Right) - General Visual Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71.1	-24	96	5036.4 3380 24 Aug 2019	31 Jul 2027*	31 Aug 2027	0 0
570027 Airframe Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.	Wing Leading Edge Forward Spar Front Face (Left) - General Visual Inspection	HRS AFL MOS [MOS: +1m/-1m]		6400.3 4214 71		144	0 0 27 Aug 2019	27 Aug 2031	27 Sep 2031	0 0
570028 Airframe Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.	Wing Leading Edge Forward Spar Front Face (Right) - General Visual Inspection	HRS AFL MOS [MOS: +1m/-1m]		6400.3 4214 71		144	0 0 27 Aug 2019	27 Aug 2031	27 Sep 2031	0 0

ATA U=Custom / Logbook Position	Description / Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
570029	Wing Extension (Winglet, Left) Exterior - Detailed Inspection	HRS		1884.1			4516.2			0
		AFL		1180			3034			0
		MOS		120.1	6	144	25 Jul 2015	31 Jul 2027*	31 Aug 2027	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
570030	Wing Extension Exterior (Winglet, Right) - Detailed Inspection	HRS		1884.1			4516.2			0
		AFL		1180			3034			0
		MOS		120.1	6	144	25 Jul 2015	31 Jul 2027*	31 Aug 2027	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
570031	External Front Spar (Left) - Zonal Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71	-27	192	27 Aug 2019	31 Jul 2035*	31 Aug 2035	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
570032	External Front Spar (Right) - Zonal Inspection	HRS		1363.9			5036.4			0
		AFL		834			3380			0
		MOS		71	-27	192	27 Aug 2019	31 Jul 2035*	31 Aug 2035	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
570035	Flap Support / Attach Fittings (Left) - Detailed Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.2		96	23 May 2023	31 May 2031	30 Jun 2031	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
570036	Flap Support / Attach Fittings (Right) - Detailed Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.2		96	23 May 2023	31 May 2031	30 Jun 2031	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
570037	AIR Brake / Aileron Hinges (Left) - Detailed Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.3		96	19 May 2023	31 May 2031	30 Jun 2031	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
570038	AIR Brake / Aileron Hinges (Right) - Detailed Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.3		96	19 May 2023	31 May 2031	30 Jun 2031	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
570039	Aileron Support / Attach Fittings (Left) - General Visual Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.3		96	19 May 2023	31 May 2031	30 Jun 2031	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
570040	Aileron Support / Attach Fittings (Right) - General Visual Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.3		96	19 May 2023	31 May 2031	30 Jun 2031	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
570045	Wing Box Internal Surfaces, Rib 18 to Rib 23 (Left) - Detailed Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.3		192	19 May 2023	31 May 2039	30 Jun 2039	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
570046	Wing Box Internal Surfaces, Rib 18 to Rib 23 (Right) - Detailed Inspection	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		26.3		192	19 May 2023	31 May 2039	30 Jun 2039	
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
570050	W 22 Front Spar Web Cutouts Between Ribs 6 - 22 - Ndt Inspection	HRS		6400.3			0			0
		AFL		4214		10000**	0	10000		0
		MOS		275.9			01 Aug 2002			
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
571101 Airframe	W 3 Lower Skin Access Cutout Edges - Ndt Inspection	HRS AFL MOS [AFL: +250]		6400.3 275.9		5000**	0 01 Aug 2002	5000	5250	0 0
Notes: SET TO REV 17										
571102 Airframe	W 4.1 Lower Skin Splice AT Rib 2 - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
Notes: REPEAT 5K LDG										
571106 Airframe	W 7 Wing Lower Skin Panels - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
571107 Airframe	W 4.5 Lower Skin Center Spar Attachment - Ndt Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
571109 Airframe	W 4.6 Center Spar Lower Flange Aircraft 038 Thru Aircraft 999 - Ndt Inspection	HRS AFL MOS [AFL: +250]		6400.3 275.9		5000**	0 01 Aug 2002	5000	5250	0 0
571201 Airframe	W 5 Front Spar Splice AT Rib 6 - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
571202 Airframe	W 6 Rear Spar Splice AT Rib 6 - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
571203	W 8 Lower Skin AT Front Spar Attachment Between Rib 2 and Rib 18 - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
Airframe										
571204	W 9 Lower Skin AT Rear Spar Attachment Between Rib 2 and Rib 18 - Ndt / Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
Airframe										
571206	W 17 Open Holes In Rear Spar Web Between Rib 18 and Rib 19 - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
Airframe										
571301	W 18 Cutouts In Front Spar Web Between Rib 18 and Rib 19 - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 258.9		10000**	0 31 Dec 2003	10000	10500	0 0
Airframe										
Notes: REPEAT 5K LDG										
571302	W 19 Wing Lower Skin Longitudinal Splices - Ndt Inspection	HRS AFL MOS		6400.3 275.9		10000**	0 01 Aug 2002	10000		0 0
Airframe										
571303	W 20 Rear Spar Web - Ndt Inspection	HRS AFL MOS [AFL: +250]		6400.3 275.9		5000**	0 01 Aug 2002	5000	5250	0 0
Airframe										
571304	W 21.1 AIR Brakes Hinge - Ndt Inspection	HRS AFL MOS		6400.3 275.9		10000**	0 01 Aug 2002	10000		0 0
Airframe										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
571305	W 21.2 AIR Brakes Actuator Fitting - Ndt Inspection		HRS AFL MOS		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 		0 0
Airframe											
571501	W 16 Wing Lower Skin - Drain Hole Near Rib 0 - Visual Inspection		HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	10500	0 0
Airframe											
571601	W 1 Front Spar to Cts Attachment - Ndt / Visual Inspection		HRS AFL MOS [AFL: +500]		6400.3 265.1		 10000** 	0 25 Jun 2003	 10000 	10500	0 0
Airframe											
571602	W 2 Center Spar to Cts Attachment - Ndt / Visual Inspection		HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	10500	0 0
Airframe											
573401	W 11 Winglet Attachment - Ndt / Visual Inspection		HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	10500	0 0
Airframe											
573402	W 12 Krueger Flap Attachment Fittings and Krueger Actuator Fitting - Visual Inspection		HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	10500	0 0
Airframe											
573403	W 13.1 Flap Rails - Visual Inspection		HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	10500	0 0
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
573404	W 13.2 Flap Actuator Access Panels and Rib No. 10 - No. 11 Flange Connect to Intermediate Panel - Visual Inspection	HRS AFL MOS		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
		[AFL: +500]								
Airframe										
573405	W 13.3 Outboard Flap Upper Surface - Ndt Inspection	HRS AFL MOS		6400.3 275.9		10000**	0 01 Aug 2002	10000	10500	0 0
		[AFL: +500]								
Airframe										
574001	Wing Extension Exterior Structure Leading Edge Panel (Left) - Zonal Inspection	HRS AFL MOS	177 113 11.9			24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
574002	Wing Extension Exterior Structure Leading Edge Panel (Right) - Zonal Inspection	HRS AFL MOS	177 113 11.9			24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
574003	Wing Inboard Leading Edges (Internal) and Upper Surfaces of Krueger Flaps (Left) - Zonal Inspection	HRS AFL MOS	157.9 100 9.8		-15	24	6242.4 4114 03 Oct 2024	30 Sep 2026*	31 Oct 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
574004	Wing Inboard Leading Edges (Internal) and Upper Surfaces of Krueger Flaps (Right) - Zonal Inspection	HRS AFL MOS	157.9 100 9.8		-15	24	6242.4 4114 03 Oct 2024	30 Sep 2026*	31 Oct 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
574005	Wing Inboard Leading Edges (External) and Surfaces of Krueger Flaps (Left) - Zonal Inspection	HRS AFL MOS	157.9 100 9.8		-18	24	6242.4 4114 03 Oct 2024	30 Sep 2026*	31 Oct 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
574006 Logbook Position	Wing Inboard Leading Edges (External) and Surfaces of Krueger Flaps (Right) - Zonal Inspection	HRS AFL MOS		157.9 100 9.8	-18	24	6242.4 4114 03 Oct 2024	30 Sep 2026*	31 Oct 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
574007 Logbook Position	Wing Outboard Leading Edges and Slats Surface (External, Left) - Zonal Inspection	HRS AFL MOS		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
574008 Logbook Position	Wing Outboard Leading Edges and Slats Surface (External, Right) - Zonal Inspection	HRS AFL MOS		177 113 11.9		24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
574009 Logbook Position	Wing Outboard Leading Edge / Slats (Internal, Left) - General Visual Inspection	HRS AFL MOS		1884.1 1180 120	3	144	4516.2 3034 28 Jul 2015	31 Jul 2027*	31 Aug 2027	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
574010 Logbook Position	Wing Outboard Leading Edge / Slats (Internal, Right) - General Visual Inspection	HRS AFL MOS		1884.1 1180 120	3	144	4516.2 3034 28 Jul 2015	31 Jul 2027*	31 Aug 2027	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
574011 Logbook Position	Slat Rails / Stops (Left) - General Visual Inspection	HRS AFL MOS		1884.1 1180 120	3	144	4516.2 3034 28 Jul 2015	31 Jul 2027*	31 Aug 2027	0 0
		[End Of Month Item] [MOS: +1m/-1m]								
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
574012 Logbook Position	Slat Rails / Stops (Right) - General Visual Inspection	HRS AFL MOS		1884.1 1180 120	3	144	4516.2 3034 28 Jul 2015	31 Jul 2027*	31 Aug 2027	0 0
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
574013 Airframe	Wing Inboard Leading Edge / Exterior (Composite Components) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71.2	-23	96	5036.4 3380 23 Aug 2019	31 Jul 2027*	31 Aug 2027	0 0
574014 Airframe	Wing Inboard Leading Edge / Exterior (Composite Components) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71.2	-23	96	5036.4 3380 23 Aug 2019	31 Jul 2027*	31 Aug 2027	0 0
574015 Airframe	Wing Outboard Leading Edge / Slats Exterior (Composite Components) (Left) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71.2	-23	96	5036.4 3380 23 Aug 2019	31 Jul 2027*	31 Aug 2027	0 0
574016 Airframe	Wing Outboard Leading Edge / Slats Exterior (Composite Components) (Right) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1363.9 834 71.2	-23	96	5036.4 3380 23 Aug 2019	31 Jul 2027*	31 Aug 2027	0 0
574017 Airframe	Wing Inboard Leading Edge Interior (Composite Components) (Left) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1884.1 1180 120	3	144	4516.2 3034 28 Jul 2015	31 Jul 2027*	31 Aug 2027	0 0
574018 Airframe	Wing Inboard Leading Edge Interior (Composite Components) (Right) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1884.1 1180 120	3	144	4516.2 3034 28 Jul 2015	31 Jul 2027*	31 Aug 2027	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
574019 Airframe	Wing Outboard Leading Edge / Slats Interior (Composite Components) (Left) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1884.1 1180 120	3	144	4516.2 3034 28 Jul 2015	31 Jul 2027*	31 Aug 2027	0 0
574020 Airframe	Wing Outboard Leading Edge / Slats Interior (Composite Components) (Right) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		1884.1 1180 120	3	144	4516.2 3034 28 Jul 2015	31 Jul 2027*	31 Aug 2027	0 0
574031 Airframe	Leading Edge Assy, Inboard (Left) 4AS1770200-501 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
574032 Airframe	Leading Edge Assy, Inboard (Right) 4AS1770200-501 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
575001 Airframe	Exterior Surfaces of Inboard and Outboard Flaps (Left) - Zonal Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		177 113 11.9		 24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
575002 Airframe	Exterior Surfaces of Inboard and Outboard Flaps (Right) - Zonal Inspection	HRS AFL MOS [End Of Month Item] [MOS: +1m/-1m]		177 113 11.9		 24	6223.3 4101 30 Jul 2024	31 Jul 2026	31 Aug 2026	0 0
575101 Airframe	W 14.1 Slat Lower Spar, Flange / Skin Attachment - Visual Inspection	HRS AFL MOS [AFL: +500]		6400.3 275.9		 10000** 	0 01 Aug 2002	10000	10500	0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
575102	W 14.2 Slat Rails - Visual Inspection	HRS AFL MOS		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe		[AFL: +500]								
576002	W 15.2 Aileron External Structure - Ndt / Visual Inspection	HRS AFL MOS		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe		[AFL: +500]								
Notes: REPEAT 5K LDG										
576003	W 15.3 Aileron Actuator Bracket Lug - Ndt / Visual Inspection	HRS AFL MOS		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe		[AFL: +500]								
576004	W 15.1A Aileron Main Fitting of Actuator (Aircraft 035 Thru Aircraft 999) - Visual Inspection	HRS AFL MOS		6400.3 275.9		 10000** 	0 01 Aug 2002	 10000 	 10500 	0 0
Airframe		[AFL: +500]								
576005	W15.4 - Aileron Actuator Bracket - Visual /NDI	HRS AFL MOS MSC		6400.3 4214 275.9 		 O/C	0 0 01 Aug 2002 	 	 	0 0
Airframe										
577001	AIR Brakes, AIR Brake Hinges and Aileron Surfaces (External, Left) - Zonal Inspection	HRS AFL MOS		177 113 11.9		 24	6223.3 4101 30 Jul 2024	 31 Jul 2026	 31 Aug 2026	0 0
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
577002	AIR Brakes, AIR Brake Hinges and Aileron Surfaces (External, Right) - Zonal Inspection	HRS AFL MOS		177 113 11.9		 24	6223.3 4101 30 Jul 2024	 31 Jul 2026	 31 Aug 2026	0 0
Airframe		[End Of Month Item] [MOS: +1m/-1m]								

71 - Power Plant

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
710001 Airframe	Powerplant (Left) - Removal / Installation 31B5180-02 PCE-CC0358	HRS AFL MOS MSC	TSN:3075.6 TSN:1907	117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
Notes: VERIFIED COMPLIANCE OF CMP710001 UNDER PRATT & WHITNEY WORK ORDER NUMBER 212385 DATED 05/25/19. THIS DOCUMENTATION IS FOR CMP DATA BASE UPDATE ONLY - NO MAINTENANCE ACCOMPLISHED BY GAC.										
710002 Airframe	Powerplant (Right) - Removal / Installation 31B5180-02 PCE-CC0136	HRS AFL MOS MSC	TSN:3092.3 TSN:2003	3063.8 2063 170.4		 O/C	3336.5 2151 16 May 2011			0 0
710003 Engine	No. 1 Engine - Engine Hot Section - Inspection	HRS ENC MOS [HRS: +250]		117.2 71 5.6		3000	3064.5 1906 10 Feb 2025	6064.5	6314.5	0 0
Notes: PN: 31B5180-02 SN: PCE-CC0358.										
710003 (710004) Engine	No. 2 Engine - Engine Hot Section - Inspection	HRS ENC MOS [HRS: +250]		805 654 35.3		3000	2011.3 1136 19 Aug 2022	5011.3	5261.3	0 0
710005 Engine	No. 1 Engine - Engine - Overhaul 31B5180-02 PCE-CC0358	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
710005 (710006) Engine	No. 2 Engine - Engine - Overhaul PW306A PCE-CC-0279	HRS ENC MOS [HRS: +100]		2816.3 1790 234.1		6000	0 0 26 Jan 2006	6000	6100	0 0
710010 Airframe	Engine Maintenance MODE Switch (Left) - Maintenance Practices	HRS AFL MOS MSC		117.2 71 5.6		 N/A	6283.1 4143 10 Feb 2025			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
710011	Engine Maintenance MODE Switch (Right) - Maintenance Practices	HRS AFL MOS MSC		1179.9 732 55.6		 N/A	5220.4 3482 10 Dec 2020			0 0
Airframe										
710013	No. 1 Engine - Engine Low Utilization Inspection Program	HRS ENC MOS		117.2 71 5.6		 24	3064.5 1906 10 Feb 2025	10 Feb 2027	10 Feb 2028	0 0
Engine		[MOS: +12m]								
710013 (710014)	No. 2 Engine - Engine Low Utilization Inspection Program	HRS ENC MOS		293.8 190 16.5		 24	2522.5 1600 14 Mar 2024	31 Mar 2026	31 Mar 2027	0 0
Engine		[End Of Month Item] [MOS: +12m]								
710030	No. 1 Engine - Engine Tubing and Connections - Leak Check	HRS ENC MOS		117.2 71 5.6		500 	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Engine		[HRS: +50/-50]								
Notes: CMP UPDATE ONLY										
710030 (710031)	No. 2 Engine - Engine Tubing and Connections - Leak Check	HRS ENC MOS		327.25 224 19.7	22.25	500 	2489.05 1566 05 Dec 2023	3011.3*	3061.3	0 0
Engine		[HRS: +50/-50]								
710061	No. 1 Engine - Engine Maintenance Program Declaration	HRS ENC MOS MSC		3181.7 1977 306.9		 O/C	0 0 01 Jan 2000			0 0
Engine										
710067	Engine Calibration	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
710069 Airframe	Engine Anti-Icing System Check	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
710071 Airframe	Thrust Reverser - Functional Check	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
711001 Airframe	Fixed Cowl Apron (Left) - Removal / Installation 288-0213-5 906	HRS AFL MOS MSC	TSN:339 TSN:171 TSN:17	6061.3 4043 258		 O/C	339 171 27 Jan 2004			0 0
711002 Airframe	Fixed Cowl Apron (Right) - Removal / Installation 288-0213-6 807	HRS AFL MOS MSC	TSN:339 TSN:171 TSN:17	6061.3 4043 258		 O/C	339 171 27 Jan 2004			0 0
711003 Airframe	Pylon Apron (Left) - General Visual Inspection	HRS AFL MOS [HRS: +50/-50]		1179.9 732 58.2		2000	5220.4 3482 23 Sep 2020	7220.4	7270.4	0 0
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
711004 Airframe	Pylon Apron (Right) - General Visual Inspection	HRS AFL MOS [HRS: +50/-50]		1179.9 732 58.2		2000	5220.4 3482 23 Sep 2020	7220.4	7270.4	0 0
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
711005 Airframe	Engine Inlet Cowl (Left) - General Visual Inspection	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
711006 Airframe	Engine Inlet Cowl (Right) - General Visual Inspection	HRS AFL MOS MSC		3063.8 2063 170.5		 O/C	3336.5 2151 11 May 2011			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
711007 Logbook Position	Lower Inlet Cowl Starter / Generator Ducting (Left) - General Visual Inspection	HRS AFL MOS [HRS: +50/-50]		296.2 192 19.8	38.9	500	6104.1 4022 04 Dec 2023	6643*	6693	0 0
Airframe										
Notes: SEE SQUAWK										
711008 Airframe	Lower Inlet Cowl Starter / Generator Ducting (Right) - General Visual Inspection	HRS AFL MOS [HRS: +50/-50]		296.2 192 19.8	38.9	500	6104.1 4022 04 Dec 2023	6643*	6693	0 0
711009 Airframe	Upper Cowl Door (Left) - General Visual Inspection	HRS AFL MOS [HRS: +50/-50]		1179.9 732 58.2		2000	5220.4 3482 23 Sep 2020	7220.4	7270.4	0 0
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
711010 Airframe	Upper Cowl Door (Right) - General Visual Inspection	HRS AFL MOS [HRS: +50/-50]		1179.9 732 58.2		2000	5220.4 3482 23 Sep 2020	7220.4	7270.4	0 0
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
711011 Airframe	Lower Cowl Door (Left) - General Visual Inspection	HRS AFL MOS [HRS: +50/-50]		1179.9 732 58.2		2000	5220.4 3482 23 Sep 2020	7220.4	7270.4	0 0
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
711012 Airframe	Lower Cowl Door (Right) - General Visual Inspection	HRS AFL MOS [HRS: +50/-50]		1179.9 732 58.2		2000	5220.4 3482 23 Sep 2020	7220.4	7270.4	0 0
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
711015 Airframe	Core Cowl (Left) - General Visual Inspection	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
711016 Airframe	Core Cowl (Right) - General Visual Inspection	HRS AFL MOS MSC		3063.8 2063 170.5		 O/C	3336.5 2151 11 May 2011			0 0
711101 Airframe	Upper Engine Access Cowling (Left) - Removal / Installation 288-0208-1 0135	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
711102 Airframe	Upper Engine Access Cowling (Right) - Removal / Installation 288-0208-2 0136	HRS AFL MOS MSC	TSN:184 TSN:102 TSN:15	1179.9 732 55.4		 O/C	5220.4 3482 16 Dec 2020			0 0
711103 Airframe	Lower Engine Access Cowling (Left) - Removal / Installation 288-0209-1 0133	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
711104 Airframe	Lower Engine Access Cowling (Right) - Removal / Installation 288-0209-2 0134	HRS AFL MOS MSC	TSN:184 TSN:102 TSN:15	1179.9 732 55.4		 O/C	5220.4 3482 16 Dec 2020			0 0
711301 Airframe	Inlet Cowl (Left) - Removal / Installation 288-0101-505M GY0048-100	HRS AFL MOS MSC		1905.1 1197 121.4		 O/C	4495.2 3017 16 Jun 2015			0 0
Notes: REMOVED FOR ACOUSTIC MESH LINER CORROSION										
711302 Airframe	Inlet Cowl (Right) - Removal / Installation 288-0101-503M 0050	HRS AFL MOS MSC		1363.9 834 69.9		 O/C	5036.4 3380 01 Oct 2019			0 0 N/A
Notes: TW S/N 558036 CAL DUE 06/20TW S/N 558034 CAL DUE 06/20										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
712001	Forward Engine Mount Vibration Isolator (Upper Left) - Removal / Installation 266D0820-501 LK0937	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
Airframe										
712002	Forward Engine Mount Vibration Isolator (Lower Right) - Removal / Installation 266D0820-501 LK1638	HRS AFL MOS MSC	TSN:158.4 TSN:105 TSN:4	3063.8 2063 170.5		 O/C	3336.5 2151 12 May 2011			0 0 NORDAM GROUP MANUFACTURING DIV
Airframe										
712003	Forward Engine Mount Vibration Isolator (Lower Left) - Removal / Installation 266D0820-505 LK0913	HRS AFL MOS MSC	TSN:6283.1 TSN:4143 TSN:271	117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
Airframe										
712004	Forward Engine Mount Vibration Isolator (Upper Right) - Removal / Installation 266D0820-501 LK1638	HRS AFL MOS MSC		3063.8 2063 170.5		 O/C	3336.5 2151 12 May 2011			0 0
Airframe										
712005	No. 1 Engine - Isolator, Aft (Upper) 31B480-01 LK0558	HRS ENC MOS MSC		3131.8 1952 211.9		 O/C	49.9 25 01 Dec 2007			0 0
Engine										
712007	No. 1 Engine - Isolator, Aft (Lower) 31B480-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
712009	Mount, Engine Resilient (Left) 31B5480-02 LK0786	HRS AFL MOS MSC		3222.2 2168 174.1		 O/C	3178.1 2046 26 Jan 2011			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
712010 Airframe	Mount, Engine Resilient (Right) 31B5480-02 LK0146	HRS AFL MOS MSC		1884.1 1180 119.5		 O/C	4516.2 3034 12 Aug 2015			0 0
712015 Airframe	Engine Mounts (Left Forward) - Detailed Inspection	HRS AFL MOS [HRS: +50/-50]	296.2 192 19.8		38.9	500	6104.1 4022 02 Dec 2023	6643*	6693	0 0
712016 Airframe	Engine Mounts (Right Forward) - Detailed Inspection	HRS AFL MOS [HRS: +50/-50]	296.2 192 19.8		38.9	500	6104.1 4022 02 Dec 2023	6643*	6693	0 0
712017 Airframe	Engine Mounts (Left Aft) - Detailed Inspection	HRS AFL MOS [HRS: +50/-50]	296.2 192 19.8		38.9	500	6104.1 4022 02 Dec 2023	6643*	6693	0 0
712018 Airframe	Engine Mounts (Right Aft) - Detailed Inspection	HRS AFL MOS [HRS: +50/-50]	296.2 192 19.8		38.9	500	6104.1 4022 02 Dec 2023	6643*	6693	0 0
712020[U] Engine	No. 1 Engine - Aft Pylon Mount Assembly 4AS3177301-503 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
712023 Airframe	Forward Engine Mount (Yoke) Assembly (Left) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [+1d/-1d]	1884.1 1180 119.1			 192	4516.2 3034 24 Aug 2015	31 Aug 2031	01 Sep 2031	0 0
712024 Airframe	Forward Engine Mount (Yoke) Assembly (Right) - Detailed Inspection	HRS AFL MOS [End Of Month Item] [+1d/-1d]	1179.9 732 58.2			 192	5220.4 3482 23 Sep 2020	30 Sep 2036	01 Oct 2036	0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
712025	Aft Engine Mount Assembly (Left) - Detailed Inspection	HRS		1884.1			4516.2			0
		AFL		1180			3034			0
		MOS		119.1		192	24 Aug 2015	31 Aug 2031	30 Sep 2031	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
712026	Aft Engine Mount Assembly (Right) - Detailed Inspection	HRS		1179.9			5220.4			0
		AFL		732			3482			0
		MOS		58.2		192	23 Sep 2020	30 Sep 2036	31 Oct 2036	
Airframe		[End Of Month Item] [MOS: +1m/-1m]								
712027	Forward and Aft Engine Mount Assemblies (Engines Removed) (Left) - Detailed Inspection	HRS		117.2			6283.1			0
		AFL		71			4143			0
		MOS		5.6			10 Feb 2025			
		MSC				O/C				
Airframe		[End Of Month Item]								
712028	Forward and Aft Engine Mount Assemblies (Engines Removed) (Right) - Detailed Inspection	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		264.3			18 Jul 2003			
		MSC				O/C				
Airframe		[End Of Month Item]								
713001	Starter / Generator Outlet Scoop FIRE Seal (Left) - General Visual Inspection	HRS		1179.9		2000	5220.4	7220.4	7270.4	0
		AFL		732			3482			0
		MOS		58.2			23 Sep 2020			
		[HRS: +50/-50]								
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
713002	Starter / Generator Outlet Scoop FIRE Seal (Right) - General Visual Inspection	HRS		1179.9		2000	5220.4	7220.4	7270.4	0
		AFL		732			3482			0
		MOS		58.2			23 Sep 2020			
		[HRS: +50/-50]								
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
713003	Drain Mast FIRE Seal (Left) - General Visual Inspection	HRS		1179.9		2000	5220.4	7220.4	7270.4	0
		AFL		732			3482			0
		MOS		58.2			23 Sep 2020			
		[HRS: +50/-50]								
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
713004 Logbook Position	Drain Mast FIRE Seal (Right) - General Visual Inspection	HRS AFL MOS [HRS: +50/-50]		1179.9 732 58.2		2000	5220.4 3482 23 Sep 2020	7220.4	7270.4	0 0
Airframe										
Notes: NEXT DUE TIMES ARE BASED ON MSG3 CONVERSION DATE/TIMES.										
714201 Airframe	Forward Core Cowling (Left, Left Engine) - Removal / Installation 266-0261-517 B0010-486	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
714202 Airframe	Forward Core Cowling (Left, Right Engine) - Removal / Installation 266-0261-517 B0010-487	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
714203 Airframe	Forward Core Cowling (Right, Left Engine) - Removal / Installation 266-0261-519 B0011-484	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
714204 Airframe	Forward Core Cowling (Right, Right Engine) - Removal / Installation 266-0261-519 B0011-487	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
714209 Airframe	Forward Engine Mount Yoke (Left) - Removal / Installation 266-0803-503 CDF5160HSM	HRS AFL MOS MSC	TSN:339 TSN:171	6061.3 4043 258		O/C	339 171 27 Jan 2004			0 0
714210 Airframe	Forward Engine Mount Yoke (Right) - Removal / Installation 266-0803-503 CDF5071HSM	HRS AFL MOS MSC	TSN:339 TSN:171 TSN:18	6061.3 4043 258		O/C	339 171 27 Jan 2004			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
715001 Engine	No. 1 Engine - Wiring - Inspection	HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY										
715001 (715002) Engine	No. 2 Engine - Wiring - Inspection	HRS ENC MOS [HRS: +50/-50]		327.25 224 19.7	0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
715003 Engine	No. 1 Engine - Engine Electrical Harness - Inspection / Check	HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Notes: CMP UPDATE ONLY										
715003 (715004) Engine	No. 2 Engine - Engine Electrical Harness - Inspection / Check	HRS ENC MOS [HRS: +50/-50]		327.25 224 19.7	22.25	500	2489.05 1566 05 Dec 2023	3011.3*	3061.3	0 0
715005 Airframe	Left Engine, Channel A, Main, Electrical Harness - Removal / Installation 288D0431-517 UFK1538	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
715006 Airframe	Right Engine, Channel A, Main, Electrical Harness - Removal / Installation 288D0431-521 UFK1545	HRS AFL MOS MSC	TSN:908.4 TSN:460 TSN:32	5491.9 3754 243.5		 O/C	908.4 460 12 Apr 2005			0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
715007	Left Engine, Channel B, Branched, Electrical Harness - Removal / Installation		HRS		6400.3			0			0
			AFL		4214			0			0
	288D0431-547	UFK1593	MOS		275.9			01 Aug 2002			NORDAM GROUP MANUFACTURING DIV
			MSC				O/C				
Airframe											
715008	Right Engine, Channel B, Branched, Electrical Harness - Removal / Installation		HRS	TSN:908.4	5491.9			908.4			0
			AFL	TSN:460	3754			460			0
	288D0431-527	UFK1560	MOS	TSN:32	243.5			12 Apr 2005			NORDAM GROUP MANUFACTURING DIV
			MSC				O/C				
Airframe											
715009	Left Engine, Channel B, Main, Electrical Harness - Removal / Installation		HRS		6400.3			0			0
			AFL		4214			0			0
	288D0431-533	UFK1546	MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
715010	Right Engine, Channel B, Main, Electrical Harness - Removal / Installation		HRS	TSN:908.4	5491.9			908.4			0
			AFL	TSN:460	3754			460			0
	288D0431-535	UFK1552	MOS	TSN:32	243.5			12 Apr 2005			
			MSC				O/C				
Airframe											
715011	Left Engine, Channel A, Branched, Electrical Harness - Removal / Installation		HRS		6400.3			0			0
			AFL		4214			0			0
	288D0431-543	UFK1589	MOS		275.9			01 Aug 2002			
			MSC				O/C				
Airframe											
715012	Right Engine, Channel A, Branched, Electrical Harness - Removal / Installation		HRS	TSN:908.4	5491.9			908.4			0
			AFL	TSN:460	3754			460			0
	288D0431-545	UFK1592	MOS	TSN:32	243.5			12 Apr 2005			
			MSC				O/C				
Airframe											
715013	No. 1 Engine - Harness, Electrical Wiring (Rear)		HRS	TSN:49.9	3131.8			49.9			0
	31B3766-01	AA1388	ENC	TSN:25	1952			25			0
			MOS		211.8			02 Dec 2007			
			MSC				O/C				
Engine											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
715013 (715014)	No. 2 Engine - Harness, Electrical Wiring (Rear)		HRS		2816.3			0			0
	31B3766-01	AA56799	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
715015	No. 1 Engine - Harness, Electrical Wiring (Front) - Removal / Installation		HRS	TSN:49.9	3131.8			49.9			0
			ENC	TSN:25	1952			25			0
	31B6184-02	AA13911	MOS		211.8			03 Dec 2007			
			MSC				O/C				
Engine											
715015 (715016)	No. 2 Engine - Harness, Electrical Wiring (Front) - Removal / Installation		HRS		2816.3			0			0
			ENC		1790			0			0
	31B6184-02	AA56840	MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
715017	No. 1 Engine - Harness, Electrical Wiring (Outer)		HRS		3181.7			0			0
	30B3039-01	AA80847	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
715020	No. 1 Engine - PMA Harness Connectors - Inspection		HRS		117.2		1000	3064.5	4064.5	4114.5	0
			ENC		71			1906			0
			MOS		5.6			10 Feb 2025			
Engine			[HRS: +50/-50]								
715020 (715021)	No. 2 Engine - PMA Harness Connectors - Inspection		HRS		327.25		1000	2489.05	3489.05	3539.05	0
			ENC		224			1566			0
			MOS		19.7			05 Dec 2023			
Engine			[HRS: +50/-50]								
715022	No. 1 Engine - Harness, Electrical Wiring (Front) - Discard		HRS		1563.4	-118.3		1618.3			0
	30B7320-03	EFA079400234	ENC		979			998			0
			MOS		89.9			01 Feb 2018			
			MSC				O/C				
Engine											

Notes: POST SB 25407 See drop down log entry.

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
715024 (715025) Engine	No. 2 Engine - Wiring Harness - Inspect Per Abbreviated Cmm	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
715026 Engine	No. 1 Engine - Harness, Electrical Wiring (Front) - Check for Security	HRS ENC MOS [HRS: +250]		117.2 71 5.6	-64.5	3000 3000	3064.5 1906 10 Feb 2025	6000* 4906	6250	0 0
715026 (715027) Engine	No. 2 Engine - Harness, Electrical Wiring (Front) - Check for Security	HRS ENC MOS [HRS: +250]		1227.6 858 109.9		3000 3000	1588.7 932 01 Jun 2016	4539.2 3911	4789.2	0 0
Notes: AIRCRAFT ACCOMPLISHED SB25401										
71EN1 Airframe	No. 1 Engine 31B5180-02 PCE-CC0358	HRS AFL MOS MSC	TSN:1796.4 TSN:1128	1396.4 850 74.1		 E/C	5003.9 3364 25 May 2019			0 0
71EN2 Airframe	No. 2 Engine 31B5180-02 PCE-CC-0279	HRS AFL MOS MSC	TSN:2522.28 TSN:1600 TSN:1	293.8 190 15.9		 E/C	6106.5 4024 30 Mar 2024			0 0
72 - Engine										
720001 Engine	No. 1 Engine - Engine Fan Blades - Inspection / Check	HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY										
720001 (720002) Engine	No. 2 Engine - Engine Fan Blades - Inspection / Check	HRS ENC MOS [HRS: +50/-50]		327.25 224 19.7	0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
720003	No. 1 Engine - Case / Fan Assembly - Removal / Installation 30B4795-01 BDAA002A215	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
720003 (720004)	No. 2 Engine - Case / Fan Assembly - Removal / Installation 30B4795-01 BDAA000A036	HRS ENC MOS MSC		47.5 30 2.9		 O/C	2768.8 1760 30 Apr 2025			0 0
Engine										
723001	No. 1 Engine - Engine Fan Case Compressor Inlet - Inspection / Check	HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Engine										
Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY										
723001 (723002)	No. 2 Engine - Engine Fan Case Compressor Inlet - Inspection / Check	HRS ENC MOS [HRS: +50/-50]		327.25 224 19.7	0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
Engine										
723003	No. 1 Engine - Engine Low-Pressure (Lp) Turbine AREA and Exhaust Mixer - Inspection	HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Engine										
Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY										
723003 (723004)	No. 2 Engine - Engine Low-Pressure (Lp) Turbine AREA and Exhaust Mixer - Inspection	HRS ENC MOS [HRS: +50/-50]		327.25 224 19.7	0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
723005	No. 1 Engine - Hp Compressor Impeller Shroud - Special Detailed Inspection (Borescope)	HRS		3181.7			0			0
		ENC		1977			0			0
		MOS		218.1			25 May 2007			
		MSC				O/C				
Engine										
723005 (723006)	No. 2 Engine - Hp Compressor Impeller Shroud - Special Detailed Inspection (Borescope)	HRS		2816.3			0			0
		ENC		1790			0			0
		MOS		234.1			26 Jan 2006			
		MSC				O/C				
Engine										
723007	No. 1 Engine - Case Assembly, Intermediate - Removal / Installation 30B6472-01 AAWA000A389	HRS		3181.7			0			0
		ENC		1977			0			0
		MOS		218.1			25 May 2007			
		MSC				O/C				
Engine										
723007 (723008)	No. 2 Engine - Case Assembly, Intermediate - Removal / Installation 30B-4945-01 AAWA000A089	HRS		2816.3			0			0
		ENC		1790			0			0
		MOS		234.1			26 Jan 2006			
		MSC				O/C				
Engine										
723009	No. 1 Engine - Annular Ball Bearing - Removal / Installation 30B5409-01 FAA0713905	HRS		3181.7			0			0
		ENC		1977			0			0
		MOS		218.1			25 May 2007			
		MSC				O/C				
Engine										
723009 (723010)	No. 2 Engine - Annular Ball Bearing - Removal / Installation 30B3692-01 SN-UNKNOWN	HRS		2816.3			0			0
		ENC		1790			0			0
		MOS		234.1			26 Jan 2006			
		MSC				O/C				
Engine										
723011	No. 1 Engine - Hub, Fan - Removal / Installation 30B4080-01 A0022CM4	HRS	TSN:1618.3	1563.4			1618.3			0
		ENC	TSN:1557	979			998	8974		0
		MOS		89.9			01 Feb 2018			
		ACCC	TSN:1557			14000	0			
Engine										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
723011 (723012) Engine	No. 2 Engine - Hub, Fan - Removal / Installation 30B4080-01 A001WL8M	HRS ENC MOS ACCC	TSN:2011.4 TSN:1772 TSN:198 TSN:1772	805 654 36.7		 14000	2011.3 1136 07 Jul 2022 0	8974		0 0
723013 Engine	No. 1 Engine - Blade, Engine Fan (No. 1) 30B4934-01 TNAA021A049	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
723013 (723035) Engine	No. 2 Engine - Blade, Engine Fan (No. 1) 30B4934-01 TNAA011A227	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
723014 Engine	No. 1 Engine - Blade, Engine Fan (No. 2) 30B4934-01 TNAA021A112	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
723014 (723036) Engine	No. 2 Engine - Blade, Engine Fan (No. 2) 30B4934-01 TNAA010A770	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
723015 Engine	No. 1 Engine - Blade, Engine Fan (No. 3) 30B4934-01 TNAA021A136	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
723015 (723037) Engine	No. 2 Engine - Blade, Engine Fan (No. 3) 30B4934-01 TNAA010A915	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
723016 Engine	No. 1 Engine - Blade, Engine Fan (No. 4) 30B4934-01 TNAA021A139	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
723016 (723038) Engine	No. 2 Engine - Blade, Engine Fan (No. 4) 30B4934-01 TNAA011A222	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
723017 Engine	No. 1 Engine - Blade, Engine Fan (No. 5) 30B4934-01 TNAA021A302	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
723017 (723039) Engine	No. 2 Engine - Blade, Engine Fan (No. 5) 30B4934-01 TNAA011A242	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
723018 Engine	No. 1 Engine - Blade, Engine Fan (No. 6) 30B4934-01 TNAA021A314	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
723018 (723040) Engine	No. 2 Engine - Blade, Engine Fan (No. 6) 30B4934-01 TNAA011A272	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
723019 Engine	No. 1 Engine - Blade, Engine Fan (No. 7) 30B4934-01 TNAA021A346	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
723019 (723041) Engine	No. 2 Engine - Blade, Engine Fan (No. 7) 30B4934-01 TNAA010A689	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
723020 Engine	No. 1 Engine - Blade, Engine Fan (No. 8) 30B4934-01 TNAA021A347	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
723020 (723042) Engine	No. 2 Engine - Blade, Engine Fan (No. 8) 30B4934-01 TNAA010A763	HRS ENC MOS MSC		2816.3 1790 234.1		O/C	0 0 26 Jan 2006			0 0
723021 Engine	No. 1 Engine - Blade, Engine Fan (No. 9) 30B3865-01 TNAA021A348	HRS ENC MOS MSC		3181.7 1977 218.1		O/C	0 0 25 May 2007			0 0
723021 (723043) Engine	No. 2 Engine - Blade, Engine Fan (No. 9) 30B4934-01 TNAA011A224	HRS ENC MOS MSC		2816.3 1790 234.1		O/C	0 0 26 Jan 2006			0 0
723022 Engine	No. 1 Engine - Blade, Engine Fan (No. 10) 30B4934-01 TNAA021A358	HRS ENC MOS MSC		3181.7 1977 218.1		O/C	0 0 25 May 2007			0 0
723022 (723044) Engine	No. 2 Engine - Blade, Engine Fan (No. 10) 30B4934-01 TNAA011A270	HRS ENC MOS MSC		2816.3 1790 234.1		O/C	0 0 26 Jan 2006			0 0
723023 Engine	No. 1 Engine - Blade, Engine Fan (No. 11) 30B4934-01 TNAA021A401	HRS ENC MOS MSC		3181.7 1977 218.1		O/C	0 0 25 May 2007			0 0
723023 (723045) Engine	No. 2 Engine - Blade, Engine Fan (No. 11) 30B4934-01 TNAA010A917	HRS ENC MOS MSC		2816.3 1790 234.1		O/C	0 0 26 Jan 2006			0 0
723024 Engine	No. 1 Engine - Blade, Engine Fan (No. 12) 30B4934-01 TNAA021A493	HRS ENC MOS MSC		3181.7 1977 218.1		O/C	0 0 25 May 2007			0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
723024 (723046)	No. 2 Engine - Blade, Engine Fan (No. 12)		HRS		2816.3			0			0
	30B4934-01	TNAA010A607	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
723025	No. 1 Engine - Blade, Engine Fan (No. 13)		HRS		3181.7			0			0
	30B4934-01	TNAA021A494	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
723025 (723047)	No. 2 Engine - Blade, Engine Fan (No. 13)		HRS		2816.3			0			0
	30B4934-01	TNAA011A207	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
723026	No. 1 Engine - Blade, Engine Fan (No. 14)		HRS		3181.7			0			0
	30B4934-01	TNAA021A497	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
723026 (723048)	No. 2 Engine - Blade, Engine Fan (No. 14)		HRS		2816.3			0			0
	30B4934-01	TNAA011A223	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
723027	No. 1 Engine - Blade, Engine Fan (No. 15)		HRS		3181.7			0			0
	30B4934-01	TNAA021A499	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
723027 (723049)	No. 2 Engine - Blade, Engine Fan (No. 15)		HRS		2816.3			0			0
	30B4934-01	TNAA011A225	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
723028	No. 1 Engine - Blade, Engine Fan (No. 16)		HRS		3181.7			0			0
	30B4934-01	TNAA021A500	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
723028 (723050) Engine	No. 2 Engine - Blade, Engine Fan (No. 16) 30B4934-01 TNAA011A226	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
723029 Engine	No. 1 Engine - Blade, Engine Fan (No. 17) 30B4934-01 TNAA021A504	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
723029 (723051) Engine	No. 2 Engine - Blade, Engine Fan (No. 17) 30B4934-01 TNAA011A205	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
723030 Engine	No. 1 Engine - Blade, Engine Fan (No. 18) 30B4934-01 TNAA021A505	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
723030 (723052) Engine	No. 2 Engine - Blade, Engine Fan (No. 18) 30B4934-01 TNAA011A220	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
723031 Engine	No. 1 Engine - Blade, Engine Fan (No. 19) 30B3865-01 TNAA021A507	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
723031 (723053) Engine	No. 2 Engine - Blade, Engine Fan (No. 19) 30B4934-01 TNAA010A777	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
723032 Engine	No. 1 Engine - Blade, Engine Fan (No. 20) 30B4934-01 TNAA021A508	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
723032 (723054) Engine	No. 2 Engine - Blade, Engine Fan (No. 20) 30B4934-01 TNAA011A245	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
723033 Engine	No. 1 Engine - Blade, Engine Fan (No. 21) 30B4934-01 TNAA021A510	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
723033 (723055) Engine	No. 2 Engine - Blade, Engine Fan (No. 21) 30B4934-01 TNAA010A916	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
723034 Engine	No. 1 Engine - Blade, Engine Fan (No. 22) 30B4934-01 TNAA021A512	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
723034 (723056) Engine	No. 2 Engine - Blade, Engine Fan (No. 22) 30B4934-01 TNAA011A271	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
723057 Engine	No. 1 Engine - Bearing, Cylindrical Roller 31B1401-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
723059 Engine	No. 1 Engine - Gearshaft Spline Bev Gearbox Drive 31B2495-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
723059 (723060) Engine	No. 2 Engine - Gearshaft Spline Bev Gearbox Drive 31B2495-01 PKAAA011223	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
723061 Engine	No. 1 Engine - Case Assy, Gas Generator 30B6546-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
723061 (723062) Engine	No. 2 Engine - Case Assy, Gas Generator 30B4092-01 A001W4FX	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
723063 Engine	No. 1 Engine - Hp Compressor Third Stage Rotor - Discard 30B3933-01 TXA182394	HRS ENC MOS ACCC		3181.7 1977 218.1		 15000	0 0 25 May 2007 0	15000		0 0
723063 (723064) Engine	No. 2 Engine - Hp Compressor Third Stage Rotor - Discard 30B3933-01 TXA1A8022	HRS ENC MOS ACCC		2816.3 1790 234.1		 15000	0 0 26 Jan 2006 0	15000		0 0
723065 Engine	No. 1 Engine - Hp Compressor Second Stage Rotor - Discard 30B6082-01 A0025XHW	HRS ENC MOS ACCC		3181.7 1977 218.1		 15000	0 0 25 May 2007 0	15000		0 0
723065 (723066) Engine	No. 2 Engine - Hp Compressor Second Stage Rotor - Discard 30B6082-01 A001TYEF	HRS ENC MOS ACCC		2816.3 1790 234.1		 15000	0 0 26 Jan 2006 0	15000		0 0
723067 Engine	No. 1 Engine - Hp Compressor Fourth Stage Rotor - Discard 30B3934-01 TXA182738	HRS ENC MOS ACCC		3181.7 1977 218.1		 15000	0 0 25 May 2007 0	15000		0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
723067 (723068)	No. 2 Engine - Hp Compressor Fourth Stage Rotor - Discard		HRS		2816.3			0			0
			ENC		1790			0	15000		0
	30B3934-01	TXA1A8284	MOS		234.1			26 Jan 2006			
			ACCC				15000	0			
Engine											
723069	No. 1 Engine - Hp Compressor Case Assy		HRS		3181.7			0			0
	30B3891-01	ABCA000A637	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
723069 (723070)	No. 2 Engine - Hp Compressor Case Assy		HRS		2816.3			0			0
	30B3891-01	A001WD37	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
723071	No. 1 Engine - Shaft, Lp Compressor		HRS		3181.7			0			0
	31B6165-01	DDAA005A453	ENC		1977			0	24000		0
			MOS		218.1			25 May 2007			
			ACCC				24000	0			
Engine											
723071 (723072)	No. 2 Engine - Shaft, Lp Compressor		HRS		2816.3			0			0
	31B6165-01	DDAA003A836	ENC		1790			0	24000		0
			MOS		234.1			26 Jan 2006			
			ACCC				24000	0			
Engine											
723073	No. 1 Engine - Hp Compressor First Stage Rotor - Discard		HRS		3181.7			0			0
	30B4811-01	A0025X82	ENC		1977			0	15000		0
			MOS		218.1			25 May 2007			
			ACCC				15000	0			
Engine											
723073 (723074)	No. 2 Engine - Hp Compressor First Stage Rotor - Discard		HRS		2816.3			0			0
	30B4811-01	A001WH06	ENC		1790			0	15000		0
			MOS		234.1			26 Jan 2006			
			ACCC				15000	0			
Engine											
723075	No. 1 Engine - Rotor, Drum Hp Compressor Assy		HRS		3181.7			0			0
	30B4149-01	SN-UNKNOWN	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
723075 (723076)	No. 2 Engine - Rotor, Drum Hp Compressor Assy 30B4149-01 NSN	HRS ENC MOS ACCC		2816.3 1790 234.1		 3000	0 0 26 Jan 2006 0	 3333		0 0
Engine										
Notes: 880950 SB 25095 C/W										
723077	No. 1 Engine - Linear - Combustion Chamber 30B4561-01 A00269MY	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
723077 (723078)	No. 2 Engine - Linear - Combustion Chamber 30B4561-01 A001W69R	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
723079	No. 1 Engine - Stator, Compressor (2ND Stage) 30B4163-01 PKAAA108833	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
723081	No. 1 Engine - Compressor Stator SET - Hp 30B4162-01 PKAAA112448	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
723083	No. 1 Engine - Hp Compressor Impeller - Discard 30B4796-01 A0025A5M	HRS ENC MOS ACCC		3181.7 1977 218.1		 6000	0 0 25 May 2007 0	 6000		0 0
Engine										
723083 (723084)	No. 2 Engine - Hp Compressor Impeller - Discard 30B4796-01 A001WE5A	HRS ENC MOS ACCC		2816.3 1790 234.1		 6000	0 0 26 Jan 2006 0	 6000		0 0
Engine										
723085	No. 1 Engine - Stator, Compressor (3RD Stage) PN NOT INSTALLED	HRS ENC MOS MSC		3181.7 1977 306.9		 O/C	0 0 01 Jan 2000			0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
723087	No. 1 Engine - Bearing, Ball Annular PN NOT INSTALLED	HRS ENC MOS MSC		3181.7 1977 306.9		 O/C	0 0 01 Jan 2000			0 0
Engine										
723089	No. 1 Engine - Case Hp Compressor, Front 30B4935-01 A0024391	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
723091	No. 1 Engine - Washer, Key 30B5115-01 YUAA001A305	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
723091 (723092)	No. 2 Engine - Washer, Key 30B5115-01 A000A433	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
723093	No. 1 Engine - Gears, Spl Bev Accessory Gearbox Drive 31B6006-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
723093 (723094)	No. 2 Engine - Gears, Spl Bev Accessory Gearbox Drive 31B6006-01 PKAAA005858	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
723097	No. 1 Engine - Seal, Hp Turbine Rotor 31B6205-01 AWE010263	HRS ENC MOS ACCC		3181.7 1977 218.1		 15000	0 0 25 May 2007 0	15000		0 0
Engine										
723097 (723098)	No. 2 Engine - Seal, Hp Turbine Rotor 31B6205-01 AWE008050	HRS ENC MOS ACCC		2816.3 1790 234.1		 15000	0 0 26 Jan 2006 0	15000		0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
723099	No. 1 Engine - Vane, Ring Turbine - 2ND Stage 30B2822 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
723101	No. 1 Engine - Bearing, Roller Cylindrical 31B4767-02 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
723101 (723102)	No. 2 Engine - Bearing, Roller Cylindrical 31B4767-02 FCN157735	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
723103	No. 1 Engine - Bearing, Ball Annular 30B6147-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
723105	No. 1 Engine - Shaft, Inlet - Hp Compressor 30B4697-01 EAAAD00B667	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
723107	No. 1 Engine - Shaft, Stub - Compressor Rotor 30B4737-01 EAAA000B577	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
723109	No. 1 Engine - Igv Case Assy - Vane,Inlet 30B4966-01 A0025YY6	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
723111	No. 1 Engine - Stator, Compressor (4TH Stage) 30B6104-01 PKAAA105746	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
723113 (723114)	No. 2 Engine - Compressor Inlet Stator - Inspection / Check	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
723115 (723116)	No. 2 Engine - Intermediate Case - Inspection / Check	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
723120	No. 1 Engine - 1ST Stage Hp Turbine Blades - Borescope Inspection	HRS ENC MOS		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0 N/A
Engine		[End Of Month Item] [HRS: +50/-50]								
Notes: PN: 31B5168-01 SN: NSN.										
723120 (723121)	No. 2 Engine - 1ST Stage Hp Turbine Blades - Borescope Inspection	HRS ENC MOS		327.25 224 19.7		500	2489.05 1566 05 Dec 2023	2989.05	3039.05	0 0
Engine		[HRS: +50/-50]								
723122	No. 1 Engine - Hp Turbine L Seal - Borescope Inspection	HRS ENC MOS MSC		1053.8 664 45.8		 O/C	2127.9 1313 04 Oct 2021			0 0
Engine										
Notes: N/A by engine SN										
723122 (723123)	No. 2 Engine - Hp Turbine L Seal - Borescope Inspection	HRS ENC MOS		1614.2 1057 147.6		 	1202.1 733 09 Apr 2013			0 0
Engine										
Notes: EFF: ENGINE POST SB25104 PRE SB25229 ONLY // INITIAL INSP AT 1200 FH OR CYCLES SINCE NEW, HSI OR OVERHAUL, WHICHEVER COMES FIRST / SUBSEQUENT INSP AT 150 HOURS / 150 CYCLES WHICHEVER COMES FIRST // ENGINES POST SB 25229 (ENGINE S/N CC0253 & SUBS ARE										
723125 (723126)	No. 2 Engine - Nose Cone - Inspection / Check	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
723127 (723128)	No. 2 Engine - Agb Mount Pads - Visual Inspection	HRS		2816.3			0			0
		ENC		1790			0			0
		MOS		234.1			26 Jan 2006			
		MSC				O/C				
Engine										
724005	No. 1 Engine - Liner Assy, Combustion Chamber 30B6146-01 A0025L64	HRS		3181.7			0			0
		ENC		1977			0			0
		MOS		218.1			25 May 2007			
		MSC				O/C				
Engine										
724007 (724008)	No. 2 Engine - Combustion Chamber - Borescope Inspection	HRS		2816.3			0			0
		ENC		1790			0			0
		MOS		234.1			26 Jan 2006			
		MSC				O/C				
Engine										
725001	No. 1 Engine - Rotor and Stator Assy - Lp Turbine 31B2140-01 SN-UNKNOWN	HRS		3181.7			0			0
		ENC		1977			0			0
		MOS		218.1			25 May 2007			
		MSC				O/C				
Engine										
725001 (725001)	No. 2 Engine - Rotor and Stator Assy - Lp Turbine 31A2140-02 RSA360714	HRS		2816.3			0			0
		ENC		1790			0			0
		MOS		234.1			26 Jan 2006			
		MSC				O/C				
Engine										
725003	No. 1 Engine - Disc, Turbine - Hp Turbine - 1ST Stage 30B6351-01 A002664B	HRS		3181.7			0			0
		ENC		1977			0	15000		0
		MOS		218.1			25 May 2007			
		ACCC				15000	0			
Engine										
725003 (725004)	No. 2 Engine - Disc, Turbine - Hp Turbine - 1ST Stage 30B6351-01 A002T2EC	HRS	TSN:1189.1	805			2011.3			0
		ENC	TSN:615	654			1136	15521		0
		MOS		36.7			07 Jul 2022			
		ACCC	TSN:615			15000	0			
Engine										
725005	No. 1 Engine - Disc, Turbine - Hp Turbine - 2ND Stage 30B4642-01 A0025FF4	HRS		3181.7			0			0
		ENC		1977			0	10000		0
		MOS		218.1			25 May 2007			
		ACCC				10000	0			
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
725005 (725006)	No. 2 Engine - Disc, Turbine - Hp Turbine - 2ND Stage	HRS		2816.3			0			0
	30B4642-01 A001WMPH	ENC		1790			0	10000		0
		MOS		234.1			26 Jan 2006			
Engine		ACCC				10000	0			
725007	No. 1 Engine - Cover, Hp Turbine Rear	HRS		3181.7			0			0
	30B5619-01 A0025TCM	ENC		1977			0	15000		0
		MOS		218.1			25 May 2007			
Engine		ACCC				15000	0			
725007 (725008)	No. 2 Engine - Cover, Hp Turbine Rear	HRS		2816.3			0			0
	30B4012-01 A001WNAT	ENC		1790			0	15000		0
		MOS		234.1			26 Jan 2006			
Engine		ACCC				15000	0			
725009	No. 1 Engine - Housing Assy, Hp Turbine	HRS		3181.7			0			0
	30B4617-01 EDA00533P	ENC		1977			0			0
		MOS		218.1			25 May 2007			
Engine		MSC				O/C				
725009 (725010)	No. 2 Engine - Housing Assy, Hp Turbine	HRS		2816.3			0			0
	30B4617-01 EDA00387D	ENC		1790			0			0
		MOS		234.1			26 Jan 2006			
Engine		MSC				O/C				
725011	No. 1 Engine - Cover, Hp Turbine Front	HRS		3181.7			0			0
	30B6202-01 A0025WN8	ENC		1977			0	15000		0
		MOS		218.1			25 May 2007			
Engine		ACCC				15000	0			
725011 (725012)	No. 2 Engine - Cover, Hp Turbine Front	HRS	TSN:1189.1	805			2011.3			0
	30B6202-01 A002FH7B	ENC	TSN:615	654			1136	15521		0
		MOS		36.7			07 Jul 2022			
Engine		ACCC	TSN:615			15000	0			
725013	No. 1 Engine - Case Assy, Turbine	HRS		3181.7			0			0
	30A2015 MTU86076	ENC		1977			0			0
		MOS		218.1			25 May 2007			
Engine		MSC				O/C				

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
725013 (725014)	No. 2 Engine - Case Assy, Turbine		HRS		2816.3			0			0
	30A2015	MTU49428	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
725015	No. 1 Engine - Disc, Turbine - 4TH Stage		HRS	TSN:1618.3	1563.4			1618.3			0
	30A2324	MAA42831	ENC	TSN:1248	979			998	11999		0
			MOS		89.9			01 Feb 2018			
			ACCC	TSN:1248			15000	0			
Engine											
725015 (725016)	No. 2 Engine - Disc, Turbine - 4TH Stage		HRS	TSN:2011.3	805			2011.3			0
	30A2324	MAA14014	ENC	TSN:1136	654			1136	12227		0
			MOS		36.7			07 Jul 2022			
			ACCC	TSN:1136			15000	0			
Engine											
725017	No. 1 Engine - Disc, Turbine - 3RD Stage		HRS	TSN:1618.3	1563.4			1618.3			0
	30A2323	MAA44057	ENC	TSN:1248	979			998	11999		0
			MOS		89.9			01 Feb 2018			
			ACCC	TSN:1248			15000	0			
Engine											
725017 (725018)	No. 2 Engine - Disc, Turbine - 3RD Stage		HRS	TSN:2011.3	805			2011.3			0
	30A2323	MAA13707	ENC	TSN:1136	654			1136	12227		0
			MOS	TSN:198	36.7			07 Jul 2022			
			ACCC	TSN:1136			15000	0			
Engine											
725019	No. 1 Engine - Disc, Turbine - 5TH Stage		HRS	TSN:1618.3	1563.4			1618.3			0
	30A2305	MAA42506	ENC	TSN:1248	979			998	11999		0
			MOS		89.9			01 Feb 2018			
			ACCC	TSN:1248			15000	0			
Engine											
725019 (725020)	No. 2 Engine - Disc, Turbine - 5TH Stage		HRS	TSN:2011.3	805			2011.3			0
	30A2305	MAA30581	ENC	TSN:1136	654			1136	12227		0
			MOS	TSN:198	36.7			07 Jul 2022			
			ACCC	TSN:1136			15000	0			
Engine											
725021	No. 1 Engine - Case Assy, Turbine Exhaust		HRS		3181.7			0			0
	31A2060-08	SN-UNKNOWN	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
725021 (725022)	No. 2 Engine - Case Assy, Turbine Exhaust 31A2060-08 TEC360708	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
725023 (725024)	No. 2 Engine - 1ST Stage Hp Turbine Vane - Borescope Inspection	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
725025	No. 1 Engine - Vane, A/O Multi Turbine - Stage 4 31A2141-02 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
725025 (725026)	No. 2 Engine - Vane, A/O Multi Turbine - Stage 4 31A2141-02 MYU49399	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
725027	No. 1 Engine - Vane, A/O Multi Turbine - Stage 3 31A2161-03 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
725027 (725028)	No. 2 Engine - Vane, A/O Multi Turbine - Stage 3 31A2161-04 MTU48871	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
725029	No. 1 Engine - Vane, A/O Multi Turbine - Stage 5 31A2145-03 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
725029 (725030)	No. 2 Engine - Vane, A/O Multi Turbine - Stage 5 31A2145-05 MYU47244	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
725031	No. 1 Engine - Shaft Coupling, Accessory Gearbox Drive 31B1289-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
725033	No. 1 Engine - Case Assy, Turbine Exhaust 31A2120-03 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
725033 (725034)	No. 2 Engine - Case Assy, Turbine Exhaust 31A2120-03 MTU45454	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
725035	No. 1 Engine - L Seal, Hp Turbine 30B3540-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
725035 (725036)	No. 2 Engine - L Seal, Hp Turbine 30B3540-01 SN-UNKNOWN	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
725037	No. 1 Engine - Hp Turbine L Seal - Discard 30B3540-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
Notes: POST SB 25104 P/C/W July 31, 2006 45.5-AFTT/ 16-AFTL										
725037 (725038)	No. 2 Engine - Hp Turbine L Seal - Discard 30B3540-01 SN-UNKNOWN	HRS ENC MOS		2816.3 1790 234.1			0 0 26 Jan 2006			0 0
Engine										
Notes: CUSTOMER ADVISED NOT REQUIRED AND CANCEL IT										
725039	No. 1 Engine - Nozzle-AIR, Turbine Disc Assy 30B5127-01 RWA79A239	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
725041	No. 1 Engine - Blades, 1ST Stage Hp Turbine (SET of 45)		HRS		3181.7			0			0
	30B6501-01	SN-UNKNOWN	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
725041 (725042)	No. 2 Engine - Blades, 1ST Stage Hp Turbine (SET of 45)		HRS	TSN:1189.1	805			2011.3			0
	30B6501-01	N/D	ENC	TSN:615	654			1136			0
			MOS		36.7			07 Jul 2022			
			MSC				O/C				
Engine											
725043	No. 1 Engine - 1ST Stage Hp Turbine Blades (SET of 45) - Discard		HRS		117.2		3000	3064.5	6064.5	6314.5	0
			ENC		71			1906			0
	30B6501-01	VARIOUS	MOS		5.6			10 Feb 2025			
			[HRS: +250]								
Engine											
725043 (725044)	No. 2 Engine - 1ST Stage Hp Turbine Blades (SET of 45) - Discard		HRS	TSN:1189.1	805		3000	2011.3	3822.2	3922.2	0
			ENC	TSN:615	654		3000	1136	3521		0
	30B6501-01	N/D	MOS		36.7			07 Jul 2022			
			[HRS: +100]								
Engine											
Notes: P/N 30B4271-01 (PRE-SB25104) / 30B6501-01 (POST SB 25269) / P/N 30B6361-01 (POST SB25230) = 3000 HOURS/CYCLES // P/N 30B5221-01, 30B6141-01, 30B6211-01 = 1800 HOURS/CYCLES / (SEE PART CODE (725041/42) FOR SB REFERENCES FOR PART NUMBERS)											
725045	No. 1 Engine - Blades, 2ND Stage Hp Turbine (SET of 45)		HRS		3181.7			0			0
	30B4782-01	SN-UNKNOWN	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
725045 (725046)	No. 2 Engine - Blades, 2ND Stage Hp Turbine (SET of 45)		HRS	TSN:1189.1	805			2011.3			0
	30B3732-01	N/D	ENC	TSN:615	654			1136			0
			MOS		36.7			07 Jul 2022			
			MSC				O/C				
Engine											
725047	No. 1 Engine - 2ND Stage Hp Turbine Blades (SET of 45) - Discard		HRS		117.2		3000	3064.5	6064.5	6314.5	0
			ENC		71		3000	1906	4906		0
	30B4782-01	VARIOUS	MOS		5.6			10 Feb 2025			
			[HRS: +250]								
Engine											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
725047 (725048)	No. 2 Engine - 2ND Stage Hp Turbine Blades (SET of 45) - Discard		HRS	TSN:1189.1	805		3000	2011.3	3822.2	3922.2	0
			ENC	TSN:615	654		3000	1136	3521		0
	30B3732-01	N/D	MOS		36.7			07 Jul 2022			
			[HRS: +100]								
Engine											
Notes: ALIGN WITH ENGINE HOT SECTION INSPECTION											
725049	No. 1 Engine - 2ND Stage Hp Turbine Blades - Borescope Inspection		HRS		117.2		500	3064.5	3564.5	3614.5	0
			ENC		71			1906			0
			MOS		5.6			10 Feb 2025			
			[HRS: +50/-50]								
Engine											
725049 (725050)	No. 2 Engine - 2ND Stage Hp Turbine Blades - Borescope Inspection		HRS		327.25		500	2489.05	2989.05	3039.05	0
			ENC		224			1566			0
			MOS		19.7			05 Dec 2023			
			[HRS: +50/-50]								
Engine											
725051	No. 1 Engine - Vane Assy, Hp Turbine (No. 1)		HRS		3181.7			0			0
	30B6321CL01	HK815	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
725051 (725052)	No. 2 Engine - Vane Assy, Hp Turbine (No. 1)		HRS		2816.3			0			0
	30B6321CL01	SN-UNKNOWN	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
725053	No. 1 Engine - Vane Assy, Hp Turbine (No. 2)		HRS		3181.7			0			0
	30B6321CL01	HK821	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
725055	No. 1 Engine - Vane Assy, Hp Turbine (No. 3)		HRS		3181.7			0			0
	30B6321CL01	HK827	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
725057	No. 1 Engine - Vane Assy, Hp Turbine (No. 4)		HRS		3181.7			0			0
	30B6321CL01	HK833	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
725059	No. 1 Engine - Vane Assy, Hp Turbine (No. 5)		HRS		3181.7			0			0
	30B6321CL01	850	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
725061	No. 1 Engine - Vane Assy, Hp Turbine (No. 6)		HRS		3181.7			0			0
	30B6321CL01	875	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
725063	No. 1 Engine - Vane Assy, Hp Turbine (No. 7)		HRS		3181.7			0			0
	30B6321CL01	HK907	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
725065	No. 1 Engine - Vane Assy, Hp Turbine (No. 8)		HRS		3181.7			0			0
	30B6321CL01	HK909	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
725067	No. 1 Engine - Vane Assy, Hp Turbine (No. 9)		HRS		3181.7			0			0
	30B6321CL01	HK963	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
725069	No. 1 Engine - Vane Assy, Hp Turbine (No. 10)		HRS		3181.7			0			0
	30B6321CL02	3L666	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
725071	No. 1 Engine - Vane Segment Assy - Hpt (No. 1)		HRS		3181.7			0			0
	30B5042CL01	OM893	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
725073	No. 1 Engine - Vane Segment Assy - Hpt (No. 2) 30B5042CL01 OM896	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
725075	No. 1 Engine - Vane Segment Assy - Hpt (No. 3) 30B5042CL01 CN028	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
725077	No. 1 Engine - Vane Segment Assy - Hpt (No. 4) 30B5042CL01 CN189	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
725079	No. 1 Engine - Vane Segment Assy - Hpt (No. 5) 30B5042CL01 CN192	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
725081	No. 1 Engine - Vane Segment Assy - Hpt (No. 6) 30B5042CL01 CN195	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
725083	No. 1 Engine - Vane Segment Assy - Hpt (No. 7) 30B5042CL01 CN197	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
725085	No. 1 Engine - Vane Segment Assy - Hpt (No. 8) 30B5042CL01 CN284	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
725087	No. 1 Engine - Vane Segment Assy - Hpt (No. 9) 30B5042CL01 CN357	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
725089	No. 1 Engine - Vane Segment Assy - Hpt (No. 10) 30B5042CL01 CN410	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
725091 (725092)	No. 2 Engine - 3RD Stage Lp Turbine Blades and Stator - Borescope Inspection	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
725093 (725094)	No. 2 Engine - 5TH Stage Lp Turbine Blades and Stator - Borescope Inspection	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
726001	No. 1 Engine - Engine Accessories - Inspection / Check	HRS ENC MOS [HRS: +50/-50]	117.2 71 5.6			500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Engine										
Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY										
726001 (726002)	No. 2 Engine - Engine Accessories - Inspection / Check	HRS ENC MOS [HRS: +50/-50]	327.25 224 19.7		0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
Engine										
726003	No. 1 Engine - Gearshaft Spl Bev Gearbox Drive 31B1880-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
726003 (726004)	No. 2 Engine - Gearshaft Spl Bev Gearbox Drive 31B1880-01 PKAA039A685	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
726005 Engine	No. 1 Engine - Rotor, AC Generator 31B5958-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
726005 (726006) Engine	No. 2 Engine - Rotor, AC Generator 31B5958-01 00490A	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
726007 Engine	No. 1 Engine - Housing Assy, Accessory Gearbox 30B4810-01 A0025TTM	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
726007 (726008) Engine	No. 2 Engine - Housing Assy, Accessory Gearbox 30B4810-01 A001WE88	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
726009 Engine	No. 1 Engine - Bearing, Roller (Flanged) 30B5806-01 FCN188511	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
726011 Engine	No. 1 Engine - Bearing, Roller (Flanged) 30B5806-01 FCN188524	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
726013 Engine	No. 1 Engine - Bearing, Roller (Flanged) 31B3936-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
726015 Engine	No. 1 Engine - Bearing, Roller 31B4253-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
726017	No. 1 Engine - Bearing, Roller 31B4253-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
726019	No. 1 Engine - Bearing, Roller (Flanged) 31B4252-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
726021	No. 1 Engine - Bearing, Roller (Flanged) 31B4252-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
726023	No. 1 Engine - Gearshaft, Start Drive 30B4406-01 PKAAA078494	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
726023 (726024)	No. 2 Engine - Gearshaft, Start Drive 30B4406-01 PKAA039A627	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
726025	No. 1 Engine - Bearing, Ball (Alternator Shaft) 31B5470-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
726028	No. 1 Engine - Diffuser, Gas Generator 30B6554-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
726028 (726029)	No. 2 Engine - Diffuser, Gas Generator 30B4093-01 A001W059	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
726030 Engine	No. 1 Engine - Stator/Housing, AC Generator 30B3040-03 00398A	HRS ENC MOS MSC	TSN:1272.7 TSN:759 TSN:109	1909 1218 109.7		O/C	1272.7 759 07 Jun 2016			0 0
726030 (726031) Engine	No. 2 Engine - Stator/Housing, AC Generator 30B3040-03 00309A	HRS ENC MOS MSC		2816.3 1790 234.1		O/C	0 0 26 Jan 2006			0 0
726033 Engine	No. 1 Engine - AC Generator (PMA) - General Visual Inspection / Functional Check	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
726035 Engine	No. 1 Engine - Gearshaft, Spur (Hydr Pump DR.) 31B4250-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		O/C	0 0 25 May 2007			0 0
726037 Engine	No. 1 Engine - Gearshaft, Spur (Fuel Pump) 31B4250-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		O/C	0 0 25 May 2007			0 0
726040 Engine	No. 1 Engine - Hp Compressor Tie Shaft 30B4054-01 EAAA000B747	HRS ENC MOS MSC		3181.7 1977 218.1		O/C	0 0 25 May 2007			0 0
726040 (726041) Engine	No. 2 Engine - Hp Compressor Tie Shaft 30B4054-01 EAAA000P266	HRS ENC MOS MSC		2816.3 1790 234.1		O/C	0 0 26 Jan 2006			0 0
726201 Engine	No. 1 Engine - Bearing, Ball Annular Flanged 31B2772-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		O/C	0 0 25 May 2007			0 0

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
726202	No. 1 Engine - Bearing, Ball Annular Flanged 31B2772-01	SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine											
726203	No. 1 Engine - Bearing, Ball Annular Flanged 31B2772-01	SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine											
727001	No. 1 Engine - Engine Bypass Ducts - Inspection / Check		HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Engine											
727001 (727002)	No. 2 Engine - Engine Bypass Ducts - Inspection / Check		HRS ENC MOS [HRS: +50/-50]		327.25 224 19.7	0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
Engine											
727003	No. 1 Engine - Engine Fan Exit Stator Vanes - Inspection / Check		HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Engine											
Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY											
727003 (727004)	No. 2 Engine - Engine Fan Exit Stator Vanes - Inspection / Check		HRS ENC MOS [HRS: +50/-50]		327.25 224 19.7		500	2489.05 1566 05 Dec 2023	2989.05	3039.05	0 0
Engine											
727005	No. 1 Engine - Duct Assy, Segment Bypass (Upper Right) 30B5919-01	BLAA011A743	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
727007	No. 1 Engine - Duct Assy, Segment Bypass (Lower Left)		HRS		3181.7			0			0
	30B5920-01	BLAA012A253	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
727009	No. 1 Engine - Duct Half-Bypass, Lower Assy		HRS		3181.7			0			0
	30B5873-01	SN-UNKNOWN	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
727011	No. 1 Engine - Door Access Assy		HRS		3181.7			0			0
	30B6297-01	SN-UNKNOWN	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
727011 (727012)	No. 2 Engine - Door Access Assy		HRS		2816.3			0			0
	30B5651-01	BLAA005A708	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
727013	No. 1 Engine - Duct Half-Bypass, Upper Assy		HRS		3181.7			0			0
	30B6304-01	SN-UNKNOWN	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
727015	No. 1 Engine - Duct, Bypass Outer Rear		HRS		3181.7			0			0
	30B6294-01	SN-UNKNOWN	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
727016[U]	No. 1 Engine - Duct, Bypass Outer Rear		HRS	TSN:49.9	3131.8			49.9			0
	30B3974-01	BIAA006A965	ENC	TSN:25	1952			25			0
			MOS		211.8			03 Dec 2007			
			MSC				O/C				
Engine											
727017	No. 1 Engine - Duct Assy, Segment Bypass (Upper Left)		HRS		3181.7			0			0
	30B6343-01	BLAA012A945	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
727019	No. 1 Engine - Duct Assy, Segment Bypass (Lwr Top Right) 30B6083-01 BLAA010A708	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
727021	No. 1 Engine - Duct Assy, Segment Bypass (Lower Right) 30B6459-01 BLAA010A160	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
729001	No. 1 Engine - Engine Diagnostic Unit (Edu) - Removal / Installation PN NOT INSTALLED	HRS ENC MOS MSC		3181.7 1977 306.9		 O/C	0 0 01 Jan 2000			0 0
Engine										
729001 (729002)	No. 2 Engine - Engine Diagnostic Unit (Edu) - Removal / Installation PN SN-UNKNOWN	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
73 - Engine Fuel and Control										
731001	No. 1 Engine - Nozzle, Engine Fuel (No. 1) 30B4951-01 DE1APF0560	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
731001 (731022)	No. 2 Engine - Nozzle, Engine Fuel (No. 1) 30B4951-01 DE1AHB2204	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
731002	No. 1 Engine - Nozzle, Engine Fuel (No. 2) 30B4951-01 DE1APF0561	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
731002 (731023) Engine	No. 2 Engine - Nozzle, Engine Fuel (No. 2) 30B4951-01 DE1AHB2208	HRS ENC MOS MSC		2816.3 1790 234.1		O/C	0 0 26 Jan 2006			0 0
731003 Engine	No. 1 Engine - Nozzle, Engine Fuel (No. 3) 30B4951-01 DE1APF0562	HRS ENC MOS MSC		3181.7 1977 218.1		O/C	0 0 25 May 2007			0 0
731003 (731024) Engine	No. 2 Engine - Nozzle, Engine Fuel (No. 3) 30B4951-01 DE1AHF2427	HRS ENC MOS MSC		2816.3 1790 234.1		O/C	0 0 26 Jan 2006			0 0
731004 Engine	No. 1 Engine - Nozzle, Engine Fuel (No. 4) 30B4951-01 DE1APF0563	HRS ENC MOS MSC		3181.7 1977 218.1		O/C	0 0 25 May 2007			0 0
731004 (731025) Engine	No. 2 Engine - Nozzle, Engine Fuel (No. 4) 30B4951-01 DE1AHF2583	HRS ENC MOS MSC		2816.3 1790 234.1		O/C	0 0 26 Jan 2006			0 0
731005 Engine	No. 1 Engine - Nozzle, Engine Fuel (No. 5) 30B4951-01 DE1APF0565	HRS ENC MOS MSC		3181.7 1977 218.1		O/C	0 0 25 May 2007			0 0
731005 (731026) Engine	No. 2 Engine - Nozzle, Engine Fuel (No. 5) 30B4951-01 DE1AHM1137	HRS ENC MOS MSC		2816.3 1790 234.1		O/C	0 0 26 Jan 2006			0 0
731006 Engine	No. 1 Engine - Nozzle, Engine Fuel (No. 6) 30B4951-01 DE1APF0566	HRS ENC MOS MSC		3181.7 1977 218.1		O/C	0 0 25 May 2007			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
731006 (731027)	No. 2 Engine - Nozzle, Engine Fuel (No. 6) 30B4951-01 DE1AHM1827	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
731007	No. 1 Engine - Nozzle, Engine Fuel (No. 7) 30B4951-01 DE1APF0568	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
731007 (731028)	No. 2 Engine - Nozzle, Engine Fuel (No. 7) 30B4951-01 DE1AHN1416	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
731008	No. 1 Engine - Nozzle, Engine Fuel (No. 8) 30B4951-01 DE1APF0569	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
731008 (731029)	No. 2 Engine - Nozzle, Engine Fuel (No. 8) 30B4951-01 DE1AHP2773	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
731009	No. 1 Engine - Nozzle, Engine Fuel (No. 9) 30B4951-01 DE1APF0570	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
731009 (731030)	No. 2 Engine - Nozzle, Engine Fuel (No. 9) 30B4951-01 DE1AHP2774	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
731010	No. 1 Engine - Nozzle, Engine Fuel (No. 10) 30B4951-01 DE1APF0571	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
731010 (731031)	No. 2 Engine - Nozzle, Engine Fuel (No. 10)		HRS		2816.3			0			0
	30B4951-01	DE1AHP2775	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
Engine			MSC				O/C				
731011	No. 1 Engine - Nozzle, Engine Fuel (No. 11)		HRS		3181.7			0			0
	30B4951-01	DE1APF0572	ENC		1977			0			0
			MOS		218.1			25 May 2007			
Engine			MSC				O/C				
731011 (731032)	No. 2 Engine - Nozzle, Engine Fuel (No. 11)		HRS		2816.3			0			0
	30B4951-01	DE1AHP2776	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
Engine			MSC				O/C				
731012	No. 1 Engine - Nozzle, Engine Fuel (No. 12)		HRS		3181.7			0			0
	30B4951-01	DE1APF0573	ENC		1977			0			0
			MOS		218.1			25 May 2007			
Engine			MSC				O/C				
731012 (731033)	No. 2 Engine - Nozzle, Engine Fuel (No. 12)		HRS		2816.3			0			0
	30B4951-01	DE1AHP2777	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
Engine			MSC				O/C				
731013	No. 1 Engine - Nozzle, Engine Fuel (No. 13)		HRS		3181.7			0			0
	30B4951-01	DE1APF0574	ENC		1977			0			0
			MOS		218.1			25 May 2007			
Engine			MSC				O/C				
731013 (731034)	No. 2 Engine - Nozzle, Engine Fuel (No. 13)		HRS		2816.3			0			0
	30B4951-01	DE1AHP2778	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
Engine			MSC				O/C				
731014	No. 1 Engine - Nozzle, Engine Fuel (No. 14)		HRS		3181.7			0			0
	30B4951-01	DE1APF0575	ENC		1977			0			0
			MOS		218.1			25 May 2007			
Engine			MSC				O/C				

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
731014 (731035)	No. 2 Engine - Nozzle, Engine Fuel (No. 14)		HRS		2816.3			0			0
	30B4951-01	DE1AHP2781	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
Engine			MSC				O/C				
731015	No. 1 Engine - Nozzle, Engine Fuel (No. 15)		HRS		3181.7			0			0
	30B4951-01	DE1APF0576	ENC		1977			0			0
			MOS		218.1			25 May 2007			
Engine			MSC				O/C				
731015 (731036)	No. 2 Engine - Nozzle, Engine Fuel (No. 15)		HRS		2816.3			0			0
	30B4951-01	DE1AHP2782	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
Engine			MSC				O/C				
731016	No. 1 Engine - Nozzle, Engine Fuel (No. 16)		HRS		3181.7			0			0
	30B4951-01	DE1APF0577	ENC		1977			0			0
			MOS		218.1			25 May 2007			
Engine			MSC				O/C				
731016 (731037)	No. 2 Engine - Nozzle, Engine Fuel (No. 16)		HRS		2816.3			0			0
	30B4951-01	DE1AHP2783	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
Engine			MSC				O/C				
731017	No. 1 Engine - Nozzle, Engine Fuel (No. 17)		HRS		3181.7			0			0
	30B4951-01	DE1APF0578	ENC		1977			0			0
			MOS		218.1			25 May 2007			
Engine			MSC				O/C				
731017 (731038)	No. 2 Engine - Nozzle, Engine Fuel (No. 17)		HRS		2816.3			0			0
	30B4951-01	DE1AHP2784	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
Engine			MSC				O/C				
731018	No. 1 Engine - Nozzle, Engine Fuel (No. 18)		HRS		3181.7			0			0
	30B4951-01	DE1APF0579	ENC		1977			0			0
			MOS		218.1			25 May 2007			
Engine			MSC				O/C				

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
731018 (731039)	No. 2 Engine - Nozzle, Engine Fuel (No. 18)		HRS		2816.3			0			0
	30B4951-01	DE1AHR0356	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
731019	No. 1 Engine - Nozzle, Engine Fuel (No. 19)		HRS		3181.7			0			0
	30B4951-01	DE1APF0580	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
731019 (731040)	No. 2 Engine - Nozzle, Engine Fuel (No. 19)		HRS		2816.3			0			0
	30B4951-01	DE1AHR0727	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
731020	No. 1 Engine - Nozzle, Engine Fuel (No. 20)		HRS		3181.7			0			0
	30B4951-01	DE1APF0581	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
731020 (731041)	No. 2 Engine - Nozzle, Engine Fuel (No. 20)		HRS		2816.3			0			0
	30B4951-01	DE1AHR0728	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
731021	No. 1 Engine - Nozzle, Engine Fuel (No. 21)		HRS		3181.7			0			0
	30B4951-01	DE1APF0582	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
731021 (731042)	No. 2 Engine - Nozzle, Engine Fuel (No. 21)		HRS		2816.3			0			0
	30B4951-01	DE1AHR0733	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
731043	No. 1 Engine - Pump Assembly, Fuel		HRS	TSN:1272.7	1909			1272.7			0
	3030649-001	MX708666	ENC	TSN:759	1218			759			0
			MOS	TSN:109	109.7			07 Jun 2016			
			MSC				O/C				
Engine											

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
731043 (731044)	No. 2 Engine - Pump Assembly, Fuel 31B4944-02	MX693979	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine											
731045	No. 1 Engine - Valve, Motive Flow 30B3478-02	SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine											
731045 (731046)	No. 2 Engine - Valve, Motive Flow 30B3478-02	Y0029	HRS ENC MOS MSC	 TSN:8	995.5 758 73.1		 O/C	1820.8 1032 24 Jun 2019			0 0
Engine											
731047	No. 1 Engine - Switch, Fuel Filter Differential Pressure 30B3500-03	HE1324	HRS ENC MOS MSC	TSN:1618.3 	1563.4 979 89.9		 O/C	1618.3 998 01 Feb 2018			0 0
Engine											
731047 (731048)	No. 2 Engine - Switch, Fuel Filter Differential Pressure 30B3500-03	HE0950	HRS ENC MOS MSC	 	805 654 36.7		 O/C	2011.3 1136 07 Jul 2022			0 0
Engine											
731049	No. 1 Engine - Ejector, Fuel Waste 31B5132-01	9959510581	HRS ENC MOS MSC	TSN:1618.3 	1563.4 979 89.9		 O/C	1618.3 998 01 Feb 2018			0 0
Engine											
731049 (731050)	No. 2 Engine - Ejector, Fuel Waste 8700-015	30242	HRS ENC MOS MSC	 TSN:2 	1775 1151 157.9		 O/C	1041.3 639 31 May 2012			0 0
Engine											
731051	No. 1 Engine - Nozzle, Fuel Inlet 30B4952-01	DE1APM0253	HRS ENC MOS MSC	 	3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
731051 (731052) Engine	No. 2 Engine - Nozzle, Fuel Inlet 30B4952-01 DE1AHP0620	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
731053 Engine	No. 1 Engine - Valve, Fuel Start and Dump 31B5131-01 9959516521	HRS ENC MOS MSC	TSN:1272.7 TSN:759 TSN:109	1909 1218 109.7		 O/C	1272.7 759 07 Jun 2016			0 0
731053 (731054) Engine	No. 2 Engine - Valve, Fuel Start and Dump 31B5131-01 99595196234	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
731055 Engine	No. 1 Engine - Control, Hydromechanical Fuel 8060-508 15173126	HRS ENC MOS MSC		1563.4 979 89.9		 O/C	1618.3 998 01 Feb 2018			0 0
731055 (731056) Engine	No. 2 Engine - Control, Hydromechanical Fuel 31B5354-06 SHU05-188	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
731057 Engine	No. 1 Engine - Nozzle, Fuel (Primary - Upper) 30B6456-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
731057 (731058) Engine	No. 2 Engine - Nozzle, Fuel (Primary - Upper) 31B5207-01 DE1AHN1426	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
731059 Engine	No. 1 Engine - Nozzle, Fuel (Primary - Lower) 30B6456-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
731059 (731060) Engine	No. 2 Engine - Nozzle, Fuel (Primary - Lower) 31B5207-01 DE1AHN1429	HRS ENC MOS MSC		2816.3 1790 234.1		O/C	0 0 26 Jan 2006			0 0
731061 Engine	No. 1 Engine - Primary Fuel Nozzles - Clean	HRS ENC MOS [HRS: +250]		117.2 71 5.6		3000	3064.5 1906 10 Feb 2025	6064.5	6314.5	0 0
731061 (731062) Engine	No. 2 Engine - Primary Fuel Nozzles - Clean	HRS ENC MOS [HRS: +250]		2816.3 1790 234.1		3000	0 0 26 Jan 2006	3000	3250	0 0
Notes: NOT LIST IN CURRENT MP										
731063 (731064) Engine	No. 2 Engine - Secondary Fuel Nozzle - Visual Inspection	HRS ENC MOS MSC		2816.3 1790 234.1		O/C	0 0 26 Jan 2006			0 0
731065 Engine	No. 1 Engine - Motive Flow Valve (Pre-SB25290) - General Visual Inspection / Functional Check	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
731067 Engine	No. 1 Engine - Fuel Waste Ejector Tank - General Visual Inspection / Functional Check	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
731069 Engine	No. 1 Engine - Fuel Pump (Pre-SB25290) - Overhaul PN NOT INSTALLED	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
731071 (731072) Engine	No. 2 Engine - Fuel System Components and Tubing - Check	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
731073 Engine	No. 1 Engine - Fuel Nozzle - Inlet - Overhaul PN NOT INSTALLED	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
731075 (731076) Engine	No. 2 Engine - Motive Flow Valve - Inspect Per Abbreviated Cmm	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
731077 Engine	No. 1 Engine - Fuel Dump / Start Valve - General Visual Inspection / Functional Check	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
731079 Engine	No. 1 Engine - Fuel Nozzle - Secondary - Overhaul PN NOT INSTALLED	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
731081 Airframe	Forward Main Fuel Tube Assembly (Left Engine) - Removal / Installation 266D0335-515 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
731082 Airframe	Forward Main Fuel Tube Assembly (Right Engine) - Removal / Installation 266D0335-515 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
731083	Right Forward Main Fuel Tube Assembly (Left Eng) - Removal / Installation 266D0335-508 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
731084	Right Forward Main Fuel Tube Assembly (Right Eng) - Removal / Installation 266D0335-508 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
731085	Aft Main Fuel Tube Assembly (Left Engine) - Removal / Installation 266D0335-509 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
731086	Aft Main Fuel Tube Assembly (Right Engine) - Removal / Installation 266D0335-509 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
731087	Right Aft Main Fuel Tube Assembly (Left Eng) - Removal / Installation 266D0335-510 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
731088	Right Aft Main Fuel Tube Assembly (Right Eng) - Removal / Installation 266D0335-510 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										
731089	Motive Fuel Tube Assembly (Left Engine) - Removal / Installation 266D0335-517 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
731090 Airframe	Left Motive Fuel Tube Assembly (Right Eng) - Removal / Installation 266D0335-517 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
731091 Airframe	Right Forward Motive Fuel Tube Assembly (Left Eng) - Removal / Installation 266D0335-527 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
731092 Airframe	Forward Motive Fuel Tube Assembly (Right Engine) - Removal / Installation 266D0335-527 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
731093 Airframe	Right Aft Motive Fuel Tube Assembly (Left Eng) - Removal / Installation 266D0335-525 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
731094 Airframe	Aft Motive Fuel Tube Assembly (Right Engine) - Removal / Installation 266D0335-525 SN-UNKNOWN	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
731097 Engine	No. 1 Engine - Secondary Fuel Nozzles - Borescope Inspection	HRS ENC DATE MSC				 O/C				0 0
731201 Engine	No. 1 Engine - Hydromechanical Fuel Control - Check	HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0

Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
731201 (731202) Logbook Position: Engine	No. 2 Engine - Hydromechanical Fuel Control - Check	HRS ENC MOS [HRS: +50/-50]		327.25 224 19.7	0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
731203 Logbook Position: Engine	No. 1 Engine - Engine Fuel Filter - Check	HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Notes: CMP UPDATE ONLY										
731203 (731204) Logbook Position: Engine	No. 2 Engine - Engine Fuel Filter - Check	HRS ENC MOS [HRS: +50/-50]		327.25 224 19.7	0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
731205 Logbook Position: Engine	No. 1 Engine - Fuel Filter - Replacement 30B6653-01 NSN	HRS ENC MOS [HRS: +25/-25]		117.2 71 5.6		1200	3064.5 1906 10 Feb 2025	4264.5	4289.5	0 0
Notes: CMP UPDATE ONLY										
731205 (731206) Logbook Position: Engine	No. 2 Engine - Fuel Filter - Replacement 30B6653-01 SN-UNKNOWN	HRS ENC MOS [HRS: +50/-50]		805 654 35.7		1000	2011.3 1136 06 Aug 2022	3011.3	3061.3	0 0
731207 (731208) Logbook Position: Engine	No. 2 Engine - Fuel Filter Bypass - Check	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
731209 (731210) Logbook Position: Engine	No. 2 Engine - Fuel Filter Bypass - Check Seating	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
731211 (731212)	No. 2 Engine - Fuel Filter Bypass - Inspect Per Abbreviated Cmm	HRS ENC MOS MSC		2816.3 1790 234.1		O/C	0 0 26 Jan 2006			0 0
Engine										
731213	No. 1 Engine - Fuel Filter Bypass Switch - General Visual Inspection / Functional Check	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
Engine										
731221 (731222)	No. 2 Engine - Hmu and Fuel Pump - Inspect Per Abbreviated Cmm	HRS ENC MOS MSC		2816.3 1790 234.1		O/C	0 0 26 Jan 2006			0 0
Engine										
731223	No. 1 Engine - Hmu - Visual Inspection / Overhaul PN NOT INSTALLED	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
Engine										
731301	No. 1 Engine - Engine Dump Valve - Visual Inspection	HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Engine										
Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY										
731301 (731302)	No. 2 Engine - Engine Dump Valve - Visual Inspection	HRS ENC MOS [HRS: +50/-50]		327.25 224 19.7	0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
Engine										
731303	No. 1 Engine - Fuel Shutoff Valve Linkage - Visual Inspection	HRS ENC MOS [HRS: +250]		117.2 71 5.6		3000	3064.5 1906 10 Feb 2025	6064.5	6314.5	0 0
Engine										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
731303 (731304) Engine	No. 2 Engine - Fuel Shutoff Valve Linkage - Visual Inspection	HRS ENC MOS [HRS: +250]		2816.3 1790 234.1		3000	0 0 26 Jan 2006	3000	3250	0 0
731305 Engine	No. 1 Engine - Fuel / Oil Heat Exchanger - Inspection	HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY										
731305 (731306) Engine	No. 2 Engine - Fuel / Oil Heat Exchanger - Inspection	HRS ENC MOS [HRS: +50/-50]		327.25 224 19.7	0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
731307 Engine	No. 1 Engine - Fuel Waste Ejector - Inspection	HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY										
731307 (731308) Engine	No. 2 Engine - Fuel Waste Ejector - Inspection	HRS ENC MOS [HRS: +50/-50]		327.25 224 19.7	0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
731309 (731310) Engine	No. 2 Engine - Fuel Waste Ejector - Inspect Per Abbreviated Cmm	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
731315 (731316) Engine	No. 2 Engine - Fuel / Oil Heat Exchanger - Inspect Per Abbreviated Cmm	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
731321 Engine	No. 1 Engine - Valve, Fuel Shutoff 30B5892-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
731321 (731322) Engine	No. 2 Engine - Valve, Fuel Shutoff 30B5892-01 SN-UNKNOWN	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
731323 Engine	No. 1 Engine - Fuel Shutoff Valve Assembly- Functional Check	HRS ENC MOS MSC		3181.7 1977 306.9		 O/C	0 0 01 Jan 2000			0 0
731325 (731326) Engine	No. 2 Engine - Fuel Shut Off Valve - Visual Inspection	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
731327 Engine	No. 1 Engine - Fuel Shutoff Valve - Overhaul PN NOT INSTALLED	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000 	0 0 25 May 2007	6000	6100	0 0
731329 Engine	No. 1 Engine - Fuel Shutoff Cable - Discard PN NOT INSTALLED	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000 	0 0 25 May 2007	6000	6100	0 0
731331 (731332) Engine	No. 2 Engine - Fuel Start and Dump Valve - Inspect Per Abbreviated Cmm	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
732001	No. 1 Engine - Engine Electronic Control - Removal / Installation 822825-6-009 00011422	HRS ENC MOS MSC		1563.4 979 89.9		 O/C	1618.3 998 01 Feb 2018			0 0
Engine										
732001 (732002)	No. 2 Engine - Engine Electronic Control - Removal / Installation 822825-7-009 02058895	HRS ENC MOS MSC		1162.7 830 102.6		 O/C	1653.6 960 10 Jan 2017			0 0
Engine										
732003	No. 1 Engine - Harness, Electrical Wiring (Outer) 30B3039-01 AA80847	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
732003 (732004)	No. 2 Engine - Harness, Electrical Wiring (Outer) 30B3039-01 AA58347	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
732007 (732008)	No. 2 Engine - Control, Engine Electronic (Eec) - Functional Check Through EDS Download	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
732009	No. 1 Engine - Eec - General Visual Inspection / Functional Check	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
Engine										
732011	No. 1 Engine - Wiring Harnesses (Outer, Inner, Front and Rear) - General Visual Inspection / Functional Check	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
Engine										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
733101 Airframe	Fuel Flowmeter (Left) - Removal / Installation 9-127-55 J9487	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
733102 Airframe	Fuel Flowmeter (Right) - Removal / Installation 9-127-55 J9504	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
733301 Airframe	Engine Fuel Pressure Gauge Switch (Left) - Removal / Installation 98505-12H00590 0265	HRS AFL MOS MSC		4787.6 3321 219.1		 O/C	1612.7 893 26 Apr 2007			0 0 GULFSTREAM DALLAS
733302 Airframe	Engine Fuel Pressure Gauge Switch (Right) - Removal / Installation 98505-12H00590 0266	HRS AFL MOS MSC		4787.6 3321 219.1		 O/C	1612.7 893 26 Apr 2007			0 0 GULFSTREAM DALLAS
74 - Ignition										
741002 Engine	No. 1 Engine - Igniter No. 1 - Removal / Installation 31B5168-01 SN-UNKNOWN	HRS ENC MOS MSC	TSN:2012.9 TSN:1256 TSN:161	1168.9 721 57.9		 O/C	2012.8 1256 30 Sep 2020			0 0
741002 (741053) Engine	No. 2 Engine - Igniter No. 1 - Removal / Installation 31B5168-01 NSN	HRS ENC MOS MSC		327.25 224 21.5		 O/C	2489.05 1566 13 Oct 2023			0 0
741003 Engine	No. 1 Engine - Exciter No. 1 - Removal / Installation 31B4636-02 NNA07174707	HRS ENC MOS MSC	TSN:1272.7 TSN:759 TSN:109	1909 1218 109.7		 O/C	1272.7 759 07 Jun 2016			0 0 GULFSTREAM DALLAS

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
741003 (741101)	No. 2 Engine - Exciter No. 1 - Removal / Installation 31B4636-02	NNA05444760	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0 GULFSTREAM DALLAS
Engine											
741004	No. 1 Engine - Igniter No. 2 - Removal / Installation 31B5168-01	SN-UNKNOWN	HRS ENC MOS MSC	TSN:2012.9 TSN:1256 TSN:161	1168.8 721 57.9		 O/C	2012.9 1256 30 Sep 2020			0 0
Engine											
741004 (741054)	No. 2 Engine - Igniter No. 2 - Removal / Installation 31B5168-01	NSN	HRS ENC MOS MSC		327.25 224 21.5		 O/C	2489.05 1566 13 Oct 2023			0 0
Engine											
741005	No. 1 Engine - Exciter No. 2 - Removal / Installation 31B4636-02	NNA07174708	HRS ENC MOS MSC	TSN:1272.7 TSN:759 TSN:109	1909 1218 109.7		 O/C	1272.7 759 07 Jun 2016			0 0 GULFSTREAM DALLAS
Engine											
741005 (741103)	No. 2 Engine - Exciter No. 2 - Removal / Installation 31B4636-02	NNA05465912	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0 GULFSTREAM DALLAS
Engine											
741007	No. 1 Engine - No. 1 Ignition Exciter Box - General Visual Inspection / Functional Check		HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000 	0 0 25 May 2007	6000	6100	0 0
Engine											
741009	No. 1 Engine - No. 2 Ignition Exciter Box - General Visual Inspection / Functional Check		HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000 	0 0 25 May 2007	6000	6100	0 0
Engine											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
741011	No. 1 Engine - Igniter Plugs - Replace PN NOT INSTALLED	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
Engine										
741013	No. 1 Engine - Ignition Cables - General Visual Inspection / Functional Check -	HRS ENC MOS [HRS: +100]		3181.7 1977 306.9		6000	0 0 01 Jan 2000	6000	6100	0 0
Engine										
742101	No. 1 Engine - Ignition Exciters - Visual Inspection	HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Engine										
Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY										
742101 (742102)	No. 2 Engine - Ignition Exciters - Visual Inspection	HRS ENC MOS [HRS: +50/-50]	327.25 224 19.7		0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
Engine										
742103	No. 1 Engine - Ignition Cables - Visual Inspection	HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Engine										
Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY										
742103 (742104)	No. 2 Engine - Ignition Cables - Visual Inspection	HRS ENC MOS [HRS: +50/-50]	327.25 224 19.7		0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
Engine										
742105	No. 1 Engine - Engine Audible Spark Igniter - Operational Test	HRS ENC MOS [HRS: +50/-50]	296.2 192 19.7		38.9	500	2885.5 1785 06 Dec 2023	3424.4*	3474.4	0 0
Engine										
Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
742105 (742106)	No. 2 Engine - Engine Audible Spark Igniter - Operational Test	HRS ENC MOS [HRS: +50/-50]		327.25 224 19.7		500	2489.05 1566 05 Dec 2023	2989.05	3039.05	0 0
Engine										
742107	No. 1 Engine - Spark Igniter - Inspection	HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Engine										
Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY										
742107 (742108)	No. 2 Engine - Spark Igniter - Inspection	HRS ENC MOS [HRS: +50/-50]		327.25 224 19.7		500	2489.05 1566 05 Dec 2023	2989.05	3039.05	0 0
Engine										
742111 (742112)	No. 2 Engine - Ignition Exciters - Inspect Per Abbreviated Cmm	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
75 - AIR										
750001	No. 1 Engine - Engine P1, P3 AIR Tube - Visual Inspection	HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Engine										
Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY										
750001 (750002)	No. 2 Engine - Engine P1, P3 AIR Tube - Visual Inspection	HRS ENC MOS [HRS: +50/-50]		327.25 224 19.7	0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
Engine										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
750005 Engine	No. 1 Engine - Engine P2.5 and P2.8 Bleed Valves - Visual Inspection / Operations Check	HRS ENC MOS [HRS: +300]		117.2 71 5.6		1500	3064.5 1906 10 Feb 2025	4564.5	4864.5	0 0
750005 (750006) Engine	No. 2 Engine - Engine P2.5 and P2.8 Bleed Valves - Visual Inspection / Operations Check	HRS ENC MOS [HRS: +300]		117.2 71 5.5	-157.8	1500	2699.1 1719 11 Feb 2025	4041.3*	4341.3	0 0
750007 (750008) Engine	No. 2 Engine - Engine P2.5 and P2.8 Bleed Valves - Inspect Per Abbreviated Cmm	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
751003 Airframe	Transmitter, Anti-Ice Pressure (Left) - Removal / Installation APTE319-1000-125A 6342-11-214	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
751004 Airframe	Transmitter, Anti-Ice Pressure (Right) - Removal / Installation APTE319-1000-125A 6342-11-211	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0
751005 (751006) Engine	No. 2 Engine - Anti Icing Valve - Inspect / Clean Per Abbreviated Cmm	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
751007 Engine	No. 1 Engine - Anti-Icing Valve - Overhaul PN NOT INSTALLED	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
751011 (751012)	No. 2 Engine - P3 Bleed System - Leak Check	HRS		2816.3			0			0
		ENC		1790			0			0
		MOS		234.1			26 Jan 2006			
		MSC				O/C				
Engine										
753001	No. 1 Engine - Compressor Bleed Valve Solenoid (Upper) - Discard 30B7178-02 AGJ12340526	HRS		117.2		1500	3064.5	4564.5	4864.5	0
		ENC		71			1906			0
		MOS		5.6			10 Feb 2025			
		[HRS: +300/-300]								
Engine										
Notes: REV 24 SOLENOID P/N OTHER THAN 31B4197-06 FREQ IS 300 HRS FROM REVISION 24 DATE 11/09/2007.										
753001 (753002)	No. 2 Engine - Compressor Bleed Valve Solenoid (Upper) - Discard 30B7178-02 AGJ12430499	HRS		1359.4		3000	1456.9	4456.9	4756.9	0
		ENC		921		3000	869	3869		0
		MOS		121.5			12 Jun 2015			
		[HRS: +300]								
Engine										
Notes: POST-SB25401										
753003	No. 1 Engine - Valve, Solenoid Anti-Icing - Removal / Installation 304427426022383040 AL2369	HRS		117.2			3064.5			0
		ENC		71			1906			0
		MOS		5.6			10 Feb 2025			
		MSC				O/C				
Engine										
753003 (753004)	No. 2 Engine - Valve, Solenoid Anti-Icing - Removal / Installation 30B5553-01 AL2305	HRS		2816.3			0			0
		ENC		1790			0			0
		MOS		234.1			26 Jan 2006			
		MSC				O/C				
Engine										
753005	No. 1 Engine - Actuator, Linear - Removal / Installation 31B5255-01 SAU06-106	HRS		3181.7			0			0
		ENC		1977			0			0
		MOS		218.1			25 May 2007			
		MSC				O/C				
Engine										
753005 (753006)	No. 2 Engine - Actuator, Linear - Removal / Installation 31B5255-01 SAU05-175	HRS		2816.3			0			0
		ENC		1790			0			0
		MOS		234.1			26 Jan 2006			
		MSC				O/C				
Engine										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
753007 Engine	No. 1 Engine - Compressor Bleed Valve (P2.8 Upper) - Removal / Installation 31B5756-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0 PRATT & WHITNEY CANADA CORP.
753007 (753009) Engine	No. 2 Engine - Compressor Bleed Valve (P2.8 Upper) - Removal / Installation 31B5756-01 AHX004536	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0 PRATT & WHITNEY CANADA CORP.
753008 Engine	No. 1 Engine - Compressor Bleed Valve (P2.8 Lower) - Removal / Installation 31B5756-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0 PRATT & WHITNEY CANADA CORP.
753008 (753010) Engine	No. 2 Engine - Compressor Bleed Valve (P2.8 Lower) - Removal / Installation 31B5756-01 AHX004602	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0 PRATT & WHITNEY CANADA CORP.
753011 Engine	No. 1 Engine - Compressor Bleed Valve (P2.5 Left) - Removal / Installation 31B5759-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
753011 (753013) Engine	No. 2 Engine - Compressor Bleed Valve (P2.5 Left) - Removal / Installation 31B5759-01 AHX004804	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
753012	No. 1 Engine - Compressor Bleed Valve (P2.5 Right) - Removal / Installation		HRS		3181.7			0			0
			ENC		1977			0			0
	31B5759-01	SN-UNKNOWN	MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
753012 (753014)	No. 2 Engine - Compressor Bleed Valve (P2.5 Right) - Removal / Installation		HRS		2816.3			0			0
			ENC		1790			0			0
	31B5759-01	AHX004813	MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
753015	No. 1 Engine - Compressor Bleed Valve Solenoid (Lower) - Discard		HRS		117.2		1500	3064.5	4564.5	4864.5	0
			ENC		71			1906			0
	30B7178-02	AGJ12430527	MOS		5.6			10 Feb 2025			
			[HRS: +300/-300]								
Engine											
753015 (753016)	No. 2 Engine - Compressor Bleed Valve Solenoid (Lower) - Discard		HRS		1359.4		3000	1456.9	4456.9	4756.9	0
			ENC		921		3000	869	3869		0
	30B7178-02	AGJ12430494	MOS		121.5			12 Jun 2015			
			[HRS: +300]								
Engine											
Notes: POST-SB25401											
753017 (753018)	No. 2 Engine - Bov Solenoid Strainer Element - Replace		HRS		117.2		3000	2699.1	5699.1	5999.1	0
	30B7375-01	NSN	ENC		71		3000	1719	4719		0
			MOS		5.6			10 Feb 2025			
Engine			[HRS: +300]								
753021 (753022)	No. 2 Engine - Linear Stator Vane Actuator - Inspect Per Abbreviated Cmm		HRS		2816.3			0			0
			ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
753023	No. 1 Engine - Linear Stator Vane Actuator - General Visual Inspection / Functional Check		HRS		3181.7		6000	0	6000	6100	0
			ENC		1977			0			0
			MOS		218.1			25 May 2007			
			[HRS: +100]								
Engine											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
753027	No. 1 Engine - Compressor Bleed Valve (P2.8 Upper) - Discard		HRS		117.2		3000	3064.5	6064.5	6314.5	0
			ENC		71			1906			0
	31B5756-01	AHX3402072	MOS		5.6			10 Feb 2025			
			[HRS: +250]								
Engine											
753027 (753029)	No. 2 Engine - Compressor Bleed Valve (P2.8 Upper) - Discard		HRS		2816.3		3000	0	3000	3250	0
			ENC		1790			0			0
	PN	SN-UNKNOWN	MOS		234.1			26 Jan 2006			
			[HRS: +250]								
Engine											
753028	No. 1 Engine - Compressor Bleed Valve (P2.8 Lower) - Discard		HRS		117.2		3000	3064.5	6064.5	6314.5	0
			ENC		71			1906			0
	31B5756-01	AHX3402071	MOS		5.6			10 Feb 2025			
			[HRS: +250]								
Engine											
753028 (753030)	No. 2 Engine - Compressor Bleed Valve (P2.8 Lower) - Discard		HRS		2816.3		3000	0	3000	3250	0
			ENC		1790			0			0
	PN	SN-UNKNOWN	MOS		234.1			26 Jan 2006			
			[HRS: +250]								
Engine											
753031	No. 1 Engine - Compressor Bleed Valve (P2.5 Left) - Discard		HRS		117.2			3064.5			0
			ENC		71			1906			0
	31B5759-01	AHX3502084	MOS		5.6			10 Feb 2025			
			MSC				O/C				
Engine											
753031 (753033)	No. 2 Engine - Compressor Bleed Valve (P2.5 Left) - Discard		HRS		2816.3		3000	0	3000	3250	0
			ENC		1790			0			0
	PN	SN-UNKNOWN	MOS		234.1			26 Jan 2006			
			[HRS: +250]								
Engine											
753032	No. 1 Engine - Compressor Bleed Valve (P2.5 Right) - Discard		HRS		117.2			3064.5			0
			ENC		71			1906			0
	31B5759-01	AHX3502084	MOS		5.6			10 Feb 2025			
			MSC				O/C				
Engine											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
753032 (753034)	No. 2 Engine - Compressor Bleed Valve (P2.5 Right) - Discard PN SN-UNKNOWN [HRS: +250]	HRS ENC MOS		2816.3 1790 234.1		3000	0 0 26 Jan 2006	3000	3250	0 0
Engine										
753047	No. 1 Engine - P2.5 and P2.8 Bleed Valve (P2.8 Upper) - Restore PN NOT INSTALLED [HRS: +100]	HRS ENC MOS		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
Engine										
753048	No. 1 Engine - P2.5 and P2.8 Bleed Valve (P2.8 Lower) - Restore PN NOT INSTALLED [HRS: +100]	HRS ENC MOS		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
Engine										
753051	No. 1 Engine - P2.5 and P2.8 Bleed Valve (P2.5 Left) - Restore PN NOT INSTALLED [HRS: +100]	HRS ENC MOS		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
Engine										
753052	No. 1 Engine - P2.5 and P2.8 Bleed Valve (P2.5 Right) - Restore PN NOT INSTALLED [HRS: +100]	HRS ENC MOS		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
Engine										
754001	No. 1 Engine - P3 Pressure Transducer 30B3033-03 KL07046206	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
754001 (754002)	No. 2 Engine - P3 Pressure Transducer 30B3033-03 KL05124862	HRS ENC MOS MSC		805 654 36.7		 O/C	2011.3 1136 07 Jul 2022			0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
754003 (754004)	No. 2 Engine - P3 Transducer - Inspect Per Abbreviated Cmm		HRS		2816.3			0			0
			ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
754005	No. 1 Engine - P3 Transducer - General Visual Inspection / Function Check		HRS		3181.7		6000	0	6000	6100	0
			ENC		1977			0			0
			MOS		218.1			25 May 2007			
			[HRS: +100]								
Engine											
77 - Engine Indicating											
770009	No. 1 Engine - Sensor, Pressure and Temperature (P1/T1) {No. 1}		HRS		1563.4			1618.3			0
	30B5895-02	ADXAB001632	ENC		979			998			0
			MOS		89.9			01 Feb 2018			
			MSC				O/C				
Engine											
770009 (770010)	No. 2 Engine - Sensor, Pressure and Temperature (P1/T1) {No. 1}		HRS	TSN:2011.3	805			2011.3			0
	30B5895-02	ADXAB000836	ENC	TSN:1136	654			1136			0
			MOS	TSN:198	36.6			08 Jul 2022			
			MSC				O/C				
Engine											
770011	No. 1 Engine - Sensor, Pressure and Temperature (P1/T1) {No. 2}		HRS		1563.4			1618.3			0
	30B5895-02	ADXAB001623	ENC		979			998			0
			MOS		89.9			01 Feb 2018			
			MSC				O/C				
Engine											
770011 (770012)	No. 2 Engine - Sensor, Pressure and Temperature (P1/T1) {No. 2}		HRS	TSN:1189	805			2011.3			0
	30B5895-02	ADXAB000842	ENC	TSN:615	654			1136			0
			MOS	TSN:142	36.6			08 Jul 2022			
			MSC				O/C				
Engine											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
771001	No. 1 Engine - Engine P1 / T1 Sensors - Visual Check	HRS ENC MOS		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Engine		[HRS: +50/-50]								
Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY										
771001 (771002)	No. 2 Engine - Engine P1 / T1 Sensors - Visual Check	HRS ENC MOS		327.25 224 19.7	0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
Engine		[HRS: +50/-50]								
771003	No. 1 Engine - Engine N1 / N2 Speed Sensors - Visual Check	HRS ENC MOS		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Engine		[HRS: +50/-50]								
Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY										
771003 (771004)	No. 2 Engine - Engine N1 / N2 Speed Sensors - Visual Check	HRS ENC MOS		327.25 224 19.7	0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
Engine		[HRS: +50/-50]								
771005	No. 1 Engine - Engine T4.5 Probes - Visual Check	HRS ENC MOS		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Engine		[HRS: +50/-50]								
Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY										
771005 (771006)	No. 2 Engine - Engine T4.5 Probes - Visual Check	HRS ENC MOS		327.25 224 19.7	0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
Engine		[HRS: +50/-50]								
771007	No. 1 Engine - N1 Speed Sensor - Inspection	HRS ENC MOS		117.2 71 5.6		3000	3064.5 1906 10 Feb 2025	6064.5	6314.5	0 0
Engine		[HRS: +250]								

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
771007 (771008) Engine	No. 2 Engine - N1 Speed Sensor - Inspection	HRS ENC MOS [HRS: +250]		2816.3 1790 234.1		3000	0 0 26 Jan 2006	3000	3250	0 0
771011 Engine	No. 1 Engine - N2 Speed Sensor (No. 1) 30B1449 CH4146	HRS ENC MOS MSC	TSN:1272.7 TSN:759 TSN:109	1909 1218 109.7		 O/C	1272.7 759 07 Jun 2016			0 0
771011 (771012) Engine	No. 2 Engine - N2 Speed Sensor (No. 1) 30B1449 CH3570	HRS ENC MOS MSC		805 654 36.7		 O/C	2011.3 1136 07 Jul 2022			0 0
771013 Engine	No. 1 Engine - N2 Speed Sensor (No. 2) 30B1449 CH4174	HRS ENC MOS MSC	TSN:1272.7 TSN:759 TSN:109	1909 1218 109.7		 O/C	1272.7 759 07 Jun 2016			0 0
771013 (771014) Engine	No. 2 Engine - N2 Speed Sensor (No. 2) 30B1449 CH3553	HRS ENC MOS MSC		805 654 36.7		 O/C	2011.3 1136 07 Jul 2022			0 0
771015 Engine	No. 1 Engine - N1 Engine Speed Sensor, Channel A - Removal / Installation 31B5743-02 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0 GULFSTREAM DALLAS
771015 (771017) Engine	No. 2 Engine - N1 Engine Speed Sensor, Channel A - Removal / Installation 31B5743-02 NSN	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0 GULFSTREAM DALLAS

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
771016	No. 1 Engine - N1 Engine Speed Sensor, Channel B - Removal / Installation		HRS		3181.7			0			0
			ENC		1977			0			0
	31B5742-02	SN-UNKNOWN	MOS		218.1			25 May 2007			GULFSTREAM
			MSC				O/C				DALLAS
Engine											
771016 (771018)	No. 2 Engine - N1 Engine Speed Sensor, Channel B - Removal / Installation		HRS		2816.3			0			0
			ENC		1790			0			0
	31B5742-02	NSN	MOS		234.1			26 Jan 2006			GULFSTREAM
			MSC				O/C				DALLAS
Engine											
771021 (771022)	No. 2 Engine - Engine P1 / T1 Sensors - Inspect Per Abbreviated Cmm		HRS		2816.3			0			0
			ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
771025	No. 1 Engine - Wiring Harness Speed Sensor - General Visual Inspection / Functional Check		HRS		3181.7		6000	0	6000	6100	0
			ENC		1977			0			0
			MOS		218.1			25 May 2007			
			[HRS: +100]								
Engine											
771027 (771028)	No. 2 Engine - Engine N1 / N2 Speed Sensors - Inspect Per Abbreviated Cmm		HRS		2816.3			0			0
			ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
771031 (771032)	No. 2 Engine - Engine N1 / T4.5 Terminal Block - Check		HRS		2816.3			0			0
			ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
771033 (771034)	No. 2 Engine - Engine N1 / T4.5 Terminal Block - Inspect Per Abbreviated Cmm		HRS		2816.3			0			0
			ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											

ATA U=Custom Logbook Position	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
771041 Engine	No. 1 Engine - N2 Speed Sensor (No. 1) - General Visual Inspection / Functional Check	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
771043 Engine	No. 1 Engine - N2 Speed Sensor (No. 2) - General Visual Inspection / Functional Check	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
771045 Engine	No. 1 Engine - N1 Engine Speed Sensor, Channel A - General Visual Inspection / Functional Check	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
771047 Engine	No. 1 Engine - N1 Engine Speed Sensor, Channel B - General Visual Inspection / Functional Check	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
772003 (772004) Engine	No. 2 Engine - Engine T4.5 Wiring Harness - Inspect Per Abbreviated Cmm	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
772005 (772006) Engine	No. 2 Engine - T4.5 System - Operational Test	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
772007 Engine	No. 1 Engine - T4.5 Harnesses and Terminal Box - Examine / Functional Check	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
772009 Engine	No. 1 Engine - Pressure and Temperature Sensor (P1/T1) No. 1 - General Visual Inspection / Functional Check	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
772011 Engine	No. 1 Engine - Pressure and Temperature Sensor (P1/T1) No. 2 - General Visual Inspection / Functional Check	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
772015[U] Engine	No. 1 Engine - T4.5 Wiring Harness (Upper) - Removal and Installation 31B5744-04 EM554111	HRS ENC MOS MSC		117.2 71 5.6		O/C	3064.5 1906 10 Feb 2025			0 0
772016[U] Engine	No. 1 Engine - T4.5 Wiring Harness (Lower) - Removal and Installation 31B5744-04 SS4120	HRS ENC MOS MSC		117.2 71 5.6		O/C	3064.5 1906 10 Feb 2025			0 0
773011 Airframe	Computer, Engine Vibration 241-242-000-021 AA04441	HRS AFL MOS MSC		4202.1 2923 199.1		O/C	2198.2 1291 26 Dec 2008			0 0
773201 Airframe	Accelerometer (Left) - Removal / Installation 144-158-000-011 00278	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
773202 Airframe	Accelerometer (Right) - Removal / Installation 144-158-000-011 00269	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
774001	No. 1 Engine - Engine Diagnostic Unit - Removal / Installation 822500-6-007 02035406	HRS ENC MOS MSC	TSN:1272.7	1909 1218 109.7		 O/C	1272.7 759 07 Jun 2016			0 0
Engine										
774001 (774002)	No. 2 Engine - Engine Diagnostic Unit - Removal / Installation 30B2995-08 05062894	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
774003	No. 1 Engine - Engine Diagnostic Unit (Edu) - Download	HRS ENC MOS [End Of Month Item] [+15d]		0 0 .7		 1	3181.7 1977 07 Jul 2025	31 Aug 2025	15 Sep 2025	0 0
Engine										
Notes: SN: CC0358 (FILE #CO358000.BRDSN: CC0136 (FILE #CO136000.BRD										
774003 (774004)	No. 2 Engine - Engine Diagnostic Unit (Edu) - Download	HRS ENC MOS [End Of Month Item] [+15d]		0 0 .7	 -15	 1	2816.3 1790 07 Jul 2025	 31 Jul 2025*	 15 Aug 2025	0 0
Engine										
774005	No. 1 Engine - Engine Diagnostic Unit - General Visual Inspection / Functional Check	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
Engine										
774005 (774006)	No. 2 Engine - Engine Diagnostic Unit - General Visual Inspection / Functional Check	HRS ENC MOS [HRS: +100]		2816.3 1790 234.1		6000	0 0 26 Jan 2006	6000	6100	0 0
Engine										
78 - Exhaust										
780009	Thrust Reverser Hydraulic System (Left) - Bleeding	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
780010	Thrust Reverser Hydraulic System (Right) - Bleeding	HRS		2378.1			4022.2			0
		AFL		1547			2667			0
		MOS		144.2			22 Jul 2013			
Airframe		MSC				O/C				
783005	Thrust Reverser Doors (Left) - Removal / Installation 288-0003-1-01 0133	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
783006	Thrust Reverser Doors (Right) - Removal / Installation 288-0003-3-01 0134	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
783007	Lower Door, Thrust Reverser (Left) 288-0004-503-01 0133	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
783008	Lower Door, Thrust Reverser (Right) 288-0004-504-01 0134	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				
783009	Thrust Reverser Assembly (Left) - Removal / Installation 288-0002-509 0133	HRS	TSN:6283.1	117.2			6283.1			0
		AFL	TSN:4143	71			4143			0
		MOS	TSN:270	5.6			10 Feb 2025			
Airframe		MSC				O/C				
783010	Thrust Reverser Assembly (Right) - Removal / Installation 288-0002-511 0134	HRS	TSN:908.4	5491.9			908.4			0
		AFL	TSN:460	3754			460			0
		MOS		243.5			12 Apr 2005			
Airframe		MSC				O/C				
783011	Thrust Reverser Restrictor Valve (Left) - Removal / Installation 288D0340-501 0149	HRS		6400.3			0			0
		AFL		4214			0			0
		MOS		275.9			01 Aug 2002			
Airframe		MSC				O/C				

ATA U=Custom / Logbook Position	Description / Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
783012	Thrust Reverser Restrictor Valve (Right) - Removal / Installation		HRS		6400.3			0			0
			AFL		4214			0			0
	288D0340-501	0144	MOS		275.9			01 Aug 2002			
			MSC				O/C				
	Airframe										
783013	Thrust Reverser Actuator Mechanism (Left) - Visual Inspection (Post Sb 200-05-280) (Cmr**)		HRS		296.2	38.9	500	6104.1	6643*	6693	0
			AFL		192			4022			0
			MOS		19.8			02 Dec 2023			
			[HRS: +50/-50]								
	Airframe										
783014	Thrust Reverser Actuator Mechanism (Right) - Visual Inspection (Post Sb 200-05-280) (Cmr**)		HRS		296.2	38.9	500	6104.1	6643*	6693	0
			AFL		192			4022			0
			MOS		19.8			02 Dec 2023			
			[HRS: +50/-50]								
	Airframe										
783015	Thrust Reverser Actuator (Left) - Visual Inspection (Post Sb 200-05-280) (Cmr**)		HRS		296.2	38.9	500	6104.1	6643*	6693	0
			AFL		192			4022			0
			MOS		19.8			02 Dec 2023			
			[HRS: +50/-50]								
	Airframe										
783016	Thrust Reverser Actuator (Right) - Visual Inspection (Post Sb 200-05-280) (Cmr**)		HRS		296.2	38.9	500	6104.1	6643*	6693	0
			AFL		192			4022			0
			MOS		19.8			02 Dec 2023			
			[HRS: +50/-50]								
	Airframe										
Notes: SQUAWK:26.11											
783017	Thrust Reverser Hydraulic Control Unit (Left) - Visual Inspection (Post Sb 200-05-280) (Cmr**)		HRS		296.2	38.9	500	6104.1	6643*	6693	0
			AFL		192			4022			0
			MOS		19.8			02 Dec 2023			
			[HRS: +50/-50]								
	Airframe										
Notes: SEE SQUAWK 26.9											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
783018	Thrust Reverser Hydraulic Control Unit (Right) - Visual Inspection (Post Sb 200-05-280) (Cmr**)	HRS AFL MOS [HRS: +50/-50]		296.2 192 19.8	38.9	500	6104.1 4022 02 Dec 2023	6643*	6693	0 0
Airframe										
783023	Thrust Reverser Doors, Stangs and Nozzles (Left) - General Visual Inspection	HRS AFL MOS MSC		1477.9 896 80.8	-14.1	 O/C	4922.4 3318 02 Nov 2018			0 0
Airframe										
783024	Thrust Reverser Doors, Stangs and Nozzles (Right) - General Visual Inspection	HRS AFL MOS MSC		1477.9 896 80.8	-14.1	 O/C	4922.4 3318 02 Nov 2018			0 0
Airframe										
783037	Thrust Reverser (Left) - Operational Test	HRS AFL MOS MSC		117.2 71 5.6		 O/C	6283.1 4143 10 Feb 2025			0 0
Airframe										
783038	Thrust Reverser (Right) - Operational Test	HRS AFL MOS MSC		157.9 100 9.8		 N/A	6242.4 4114 03 Oct 2024			0 0
Airframe										
783043	Secondary Lock Electrical Harness (Left) - Removal / Installation PW306AG7805-552 SN-UNKNOWN	HRS AFL MOS MSC		5086 3519 227.4		 O/C	1314.3 695 16 Aug 2006			0 0 NORDAM
Airframe										
783044	Secondary Lock Electrical Harness (Right) - Removal / Installation PW306AG7805-552 NSN	HRS AFL MOS MSC		5086 3519 227.4		 O/C	1314.3 695 16 Aug 2006			0 0 NORDAM
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
783045	Thrust Reverser Secondary Latches Blocker Plates and Microswitches (Left) - Restore / Clean		HRS		157.9		500	6242.4	6742.4	6792.4	0
			AFL		100			4114			0
			MOS		9.8	19	12	03 Oct 2024	31 Oct 2025*	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
783046	Thrust Reverser Secondary Latches Blocker Plates and Microswitches (Right) - Restore / Clean		HRS		157.9		500	6242.4	6742.4	6792.4	0
			AFL		100			4114			0
			MOS		9.8	19	12	03 Oct 2024	31 Oct 2025*	30 Nov 2025	
			[End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]								
Airframe											
783047	Thrust Reverser Barrel Assembly Rear Flange (Left) - General Visual Inspection		HRS		117.2			6283.1			0
			AFL		71			4143			0
			MOS		5.6			10 Feb 2025			
			MSC				O/C				
Airframe											
783048	Thrust Reverser Barrel Assembly Rear Flange (Right) - General Visual Inspection		HRS		3063.8			3336.5			0
			AFL		2063			2151			0
			MOS		170.5			11 May 2011			
			MSC				O/C				
Airframe											
783049	Thrust Reverser Linkage (Left) - Lubrication (Post Sb 200-05-280)		HRS		296.2	38.9	500	6104.1	6643*	6693	0
			AFL		192			4022			0
			MOS		19.8			02 Dec 2023			
			[HRS: +50/-50]								
Airframe											
783050	Thrust Reverser Linkage (Right) - Lubrication (Post Sb 200-05-280)		HRS		296.2	38.9	500	6104.1	6643*	6693	0
			AFL		192			4022			0
			MOS		19.8			02 Dec 2023			
			[HRS: +50/-50]								
Airframe											
783061	Thrust Reverser Stang Fairing (Left, Outboard) - Removal / Installation		HRS	TSN:5346.5	1053.8			5346.5			0
	288-0602 NSN		AFL	TSN:3550	664			3550			0
			MOS	TSN:11	45.8			04 Oct 2021			
			MSC				O/C				
Airframe											

Notes: SEE SQUAWK 26.6 TORQUE SCREWDRIVER: 561417 CAL DUE:11/19

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
783062	Thrust Reverser Stang Fairing (Right, Outboard) - Removal / Installation	HRS	TSN:184	1179.9			5220.4			0
		AFL	TSN:102	732			3482			0
	288-0602-502 NSN	MOS	TSN:15	55.6			08 Dec 2020			
		MSC				O/C				
Airframe										
783063	Thrust Reverser Stang Fairing (Left, Inner) - Removal / Installation	HRS	TSN:5346.5	1053.8			5346.5			0
		AFL	TSN:3550	664			3550			0
	288-0601 NSN	MOS	TSN:11	45.8			04 Oct 2021			
		MSC				O/C				
Airframe										
Notes: SEE SQUAWK 26.5 TORQUE SCREWDRIVER: 561417 CAL DUE:11/19										
783064	Thrust Reverser Stang Fairing (Right, Inner) - Removal / Installation	HRS	TSN:184	1179.9			5220.4			0
		AFL	TSN:102	732			3482			0
	288-0601-502 NSN	MOS	TSN:15	55.6			10 Dec 2020			
		MSC				O/C				
Airframe										
783081	Stow and Deploy Switches (Left) - Cleaning	HRS		157.9			6242.4			0
		AFL		100			4114			0
		MOS		9.8			03 Oct 2024			
		MSC				O/C				
Airframe										
783082	Stow and Deploy Switches (Right) - Cleaning	HRS		157.9			6242.4			0
		AFL		100			4114			0
		MOS		9.8			03 Oct 2024			
		MSC				O/C				
Airframe										
783085	Secondary Latch Actuator and Secondary Latch Switch (Left) - Cleaning	HRS		157.9			6242.4			0
		AFL		100			4114			0
		MOS		9.8			03 Oct 2024			
		MSC				O/C				
Airframe										
783086	Secondary Latch Actuator and Secondary Latch Switch (Right) - Cleaning	HRS		157.9			6242.4			0
		AFL		100			4114			0
		MOS		9.8			03 Oct 2024			
		MSC				O/C				
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
783091 Airframe	Blocker ARM (Left) - Removal / Installation 50934 SN-UNKNOWN	HRS AFL MOS MSC		157.9 100 9.8		 O/C	6242.4 4114 03 Oct 2024			0 0
783092 Airframe	Blocker ARM (Right) - Removal / Installation 50934 SN-UNKNOWN	HRS AFL MOS MSC		157.9 100 9.8		 O/C	6242.4 4114 03 Oct 2024			0 0
783201 Airframe	Thrust Reverser Hydraulic Control Unit (Left) - Removal / Installation 71739-1 0144	HRS AFL MOS MSC		157.9 100 9.8		 O/C	6242.4 4114 03 Oct 2024			0 0
783202 Airframe	Thrust Reverser Hydraulic Control Unit (Right) - Removal / Installation 71739-1 0157	HRS AFL MOS MSC		157.9 100 9.8		 O/C	6242.4 4114 03 Oct 2024			0 0
783203 Airframe	Thrust Reverser Actuator (Left Outboard) - Removal / Installation 288D0067-501 0269	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 NORDAM GROUP MANUFACTURING DIVISION
783204 Airframe	Thrust Reverser Actuator (Right Outboard) - Removal / Installation 288D0067-501 0276	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 NORDAM GROUP MANUFACTURING DIVISION
783205 Airframe	Thrust Reverser Actuator (Left Inboard) - Removal / Installation 288D0067-501 0275	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 NORDAM GROUP MANUFACTURING DIVISION

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
783206	Thrust Reverser Actuator (Right Inboard) - Removal / Installation 288D0067-501	0274	HRS AFL MOS MSC		6400.3 4214 275.9		 O/C	0 0 01 Aug 2002			0 0 NORDAM GROUP MANUFACTURING DIVISION
Airframe											
783207	Thrust Reverser Upper Secondary Latch Actuator (Left) - Removal / Installation 288D0487-511	0256	HRS AFL MOS MSC		4373.4 3044 204.5		 O/C	2026.9 1170 14 Jul 2008			0 0 NORDAM GROUP MANUFACTURING DIVISION
Airframe											
783208	Thrust Reverser Upper Secondary Latch Actuator (Right) - Removal / Installation 288D0487-511	0262	HRS AFL MOS MSC		4373.4 3044 204.5		 O/C	2026.9 1170 14 Jul 2008			0 0 NORDAM GROUP MANUFACTURING DIVISION
Airframe											
783209	Thrust Reverser Lower Secondary Latch Actuator (Left) - Removal / Installation 288D0487-511	0263	HRS AFL MOS MSC		4373.4 3044 204.5		 O/C	2026.9 1170 14 Jul 2008			0 0 NORDAM GROUP MANUFACTURING DIVISION
Airframe											
783210	Thrust Reverser Lower Secondary Latch Actuator (Right) - Removal / Installation 288D0487-511	0267	HRS AFL MOS MSC		4373.4 3044 204.5		 O/C	2026.9 1170 14 Jul 2008			0 0 NORDAM GROUP MANUFACTURING DIVISION
Airframe											
783211	Thrust Reverser Isolation Valve (Left) - Removal / Installation 288D0489-505	145	HRS AFL MOS MSC		259.1 170 14.9		 O/C	6141.2 4044 30 Apr 2024			0 0
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
783212	Thrust Reverser Isolation Valve (Right) - Removal / Installation 288D0489-505 007	HRS AFL MOS MSC		757.3 461 31.9		 O/C	5643 3753 30 Nov 2022			0 0
Airframe										
79 - Oil										
791001	No. 1 Engine - Engine Oil Quantity - Check	HRS ENC MOS		296.2 192 19.7	38.9	500	2885.5 1785 05 Dec 2023	3424.4*	3474.4	0 0
Engine		[HRS: +50/-50]								
Notes: CMP UPDATE ONLY										
791001 (791002)	No. 2 Engine - Engine Oil Quantity - Check	HRS ENC MOS		327.25 224 19.7	0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
Engine		[HRS: +50/-50]								
791003 (791004)	No. 2 Engine - Oil Filler CAP - Check	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
791201	No. 1 Engine - Engine Oil Filter Element - Inspection	HRS ENC MOS		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Engine		[HRS: +50/-50]								
Notes: CMP UPDATE ONLY										
791201 (791202)	No. 2 Engine - Engine Oil Filter Element - Inspection	HRS ENC MOS		327.25 224 19.7	0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
Engine		[HRS: +50/-50]								
791205	No. 1 Engine - Engine Oil Filter Element - Discard 30B6652-01 NSN	HRS ENC MOS		117.2 71 5.6		1200	3064.5 1906 10 Feb 2025	4264.5	4289.5	0 0
Engine		[HRS: +25/-25]								
Notes: CMP UPDATE ONLY										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
791205 (791206) Engine	No. 2 Engine - Engine Oil Filter Element - Discard 30B6652-01 SN-UNKNOWN	HRS ENC MOS [HRS: +25/-25]		805 654 35.7		1200	2011.3 1136 06 Aug 2022	3211.3	3236.3	0 0
791211 Engine	No. 1 Engine - Engine - Oil Change Interval	HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		1200	3064.5 1906 10 Feb 2025	4264.5	4314.5	0 0
Notes: CMP UPDATE ONLY										
791211 (791212) Engine	No. 2 Engine - Engine - Oil Change Interval	HRS ENC MOS [HRS: +50/-50]		327.25 224 19.7		1000	2489.05 1566 05 Dec 2023	3489.05	3539.05	0 0
Notes: NOTE: PRE SB 200-05-280 = 1200 HRS (+/- 50 HRS) / POST SB 200-05-280 = 1000 HRS (+/- 50 HRS)										
792001 Engine	No. 1 Engine - No. 3 Bearing Scavenge Oil Tube - Visual Inspection	HRS ENC MOS [HRS: +25/-25]		117.2 71 5.6		1200	3064.5 1906 10 Feb 2025	4264.5	4289.5	0 0
792001 (792002) Engine	No. 2 Engine - No. 3 Bearing Scavenge Oil Tube - Visual Inspection	HRS ENC MOS [HRS: +50/-50]		805 654 36.6		1000	2011.3 1136 08 Jul 2022	3011.3	3061.3	0 0
792003 Engine	No. 1 Engine - Indicator, Oil Over Pressure Pickup - Inspection	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
792003 (792004) Engine	No. 2 Engine - Indicator, Oil Over Pressure Pickup - Inspection	HRS ENC MOS MSC		1822.6 1178 168.6		 O/C	993.7 612 08 Jul 2011			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
792005	No. 1 Engine - Engine Accessory Gearbox PAD Seals (Agb) - Check	HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Engine										
Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY										
792005 (792006)	No. 2 Engine - Engine Accessory Gearbox PAD Seals (Agb) - Check	HRS ENC MOS [HRS: +50/-50]		327.25 224 19.7	0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
Engine										
792009	No. 1 Engine - Heat Exchanger, Fuel / Oil - Removal / Installation 31B5790-01 2095	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
792009 (792010)	No. 2 Engine - Heat Exchanger, Fuel / Oil - Removal / Installation 31B5790-01 1690	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
792011	No. 1 Engine - Switch, Impending Bypass Oil Filter - Removal / Installation 30B3507-02 HE1624	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
792011 (792012)	No. 2 Engine - Switch, Impending Bypass Oil Filter - Removal / Installation 30B3507-02 HE1205	HRS ENC MOS MSC		805 654 36.7		 O/C	2011.3 1136 07 Jul 2022			0 0
Engine										
792013	No. 1 Engine - Oil Pump Assembly - Removal / Installation 30B6793-01 22A737	HRS ENC MOS MSC		757.3 461 31.9		 O/C	2424.4 1516 30 Nov 2022			0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
792013 (792014) Engine	No. 2 Engine - Oil Pump Assembly - Removal / Installation 30B6793-01 4A104	HRS ENC MOS MSC		995.5 758 72.2		 O/C	1820.8 1032 23 Jul 2019			0 0 PRATT & WHITNEY CANADA CORP.
Notes: FAILED										
792015 (792016) Engine	No. 2 Engine - Switch, Engine Oil Differential Pressure - Inspect Per Abbreviated Cmm	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
792017 Engine	No. 1 Engine - Oil Filter Bypass Switch - General Visual Inspection / Functional Check	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000 	0 0 25 May 2007	6000	6100	0 0
792019 Engine	No. 1 Engine - Switch, Low Oil Pressure 30B3724-01 HE1548	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
792019 (792020) Engine	No. 2 Engine - Switch, Low Oil Pressure 30B3724-01 HE1153	HRS ENC MOS MSC		805 654 36.7		 O/C	2011.3 1136 07 Jul 2022			0 0
792021 (792022) Engine	No. 2 Engine - Oil System Components - Inspection / Check	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
792023 Engine	No. 1 Engine - Transducer (Switch), Differential Oil Pressure 31B5984-01 KL07046222	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
792023 (792024)	No. 2 Engine - Transducer (Switch), Differential Oil Pressure 31B5984-01 KL05074427	HRS ENC MOS MSC		805 654 36.7		 O/C	2011.3 1136 07 Jul 2022			0 0
Engine										
792025	No. 1 Engine - Fuel / Oil Heater Exchanger - Visual Inspection / Flush	HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
Engine										
793001	No. 1 Engine - Chip Detector - Operational Check	HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
Engine										
Notes: MINOR PERIODIC INSPECTION C/W, REF KCI W/O #6330 CMP UPDATE ONLY										
793001 (793002)	No. 2 Engine - Chip Detector - Operational Check	HRS ENC MOS [HRS: +50/-50]		327.25 224 19.7	0.45	500	2489.05 1566 05 Dec 2023	2989.5*	3039.5	0 0
Engine										
793003 (793004)	No. 2 Engine - Chip Detector - Inspect Per Abbreviated Cmm	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										
793007	No. 1 Engine - Indicator, Oil Level 31B3555-01 SN-UNKNOWN	HRS ENC MOS MSC		3181.7 1977 218.1		 O/C	0 0 25 May 2007			0 0
Engine										
793007 (793008)	No. 2 Engine - Indicator, Oil Level 31B3555-01 NSN	HRS ENC MOS MSC		2816.3 1790 234.1		 O/C	0 0 26 Jan 2006			0 0
Engine										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
793009	No. 1 Engine - Sensor, Oil Level		HRS		3181.7			0			0
	30B3851	SN-UNKNOWN	ENC		1977			0			0
			MOS		218.1			25 May 2007			
			MSC				O/C				
Engine											
793009 (793010)	No. 2 Engine - Sensor, Oil Level		HRS		2816.3			0			0
	30B3851	NSN	ENC		1790			0			0
			MOS		234.1			26 Jan 2006			
			MSC				O/C				
Engine											
793011	No. 1 Engine - Oil Level Sensor - General Visual Inspection / Functional Check		HRS		3181.7		6000	0	6000	6100	0
			ENC		1977			0			0
			MOS		218.1			25 May 2007			
			[HRS: +100]								
Engine											
793013	No. 1 Engine - Chip Detector - Discard		HRS		3181.7		6000	0	6000	6100	0
	PN	NOT INSTALLED	ENC		1977			0			0
			MOS		218.1			25 May 2007			
Engine			[HRS: +100]								
793015	No. 1 Engine - Oil Tank Filler CAP - General Visual Inspection / Functional Check		HRS		3181.7		6000	0	6000	6100	0
			ENC		1977			0			0
			MOS		218.1			25 May 2007			
			[HRS: +100]								
Engine											
793019	No. 1 Engine - Low Oil Pressure Switch - General Visual Inspection / Functional Check		HRS		3181.7		6000	0	6000	6100	0
			ENC		1977			0			0
			MOS		218.1			25 May 2007			
			[HRS: +100]								
Engine											
793021	No. 1 Engine - Oil Pressure Differential Indicator (POP-Up) - General Visual Inspection / Functional Check		HRS		3181.7		6000	0	6000	6100	0
			ENC		1977			0			0
			MOS		218.1			25 May 2007			
			[HRS: +100]								
Engine											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
793023	No. 1 Engine - Differential Oil Pressure Transducer - General Visual Inspection / Functional Check		HRS ENC MOS [HRS: +100]		3181.7 1977 218.1		6000	0 0 25 May 2007	6000	6100	0 0
Engine											
793201	Sensor, Oil Temperature (Left) - Removal / Installation 26D00328-501	00278	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe											
793202	Sensor, Oil Temperature (Right) - Removal / Installation 26D00328-501	00269	HRS AFL MOS MSC		6400.3 4214 275.9		O/C	0 0 01 Aug 2002			0 0
Airframe											
AD - Airworthiness Directives											
2022-01-03U	FAA AD 2022-01-03, Amdt 39-21891, Umlaut Halogen Free Hand Held FIRE Extinguishers		HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe											
Notes: N/A due to affected equipment not installed											
CAA IL 27-10-11-03 (993075)	Israel CAA AD 27-10-11-03 - Inspection of Aileron & Elevator Servo Actuator Spring Rods		HRS AFL MOS MSC		3063.8 2063 170.4		-	3336.5 2151 16 May 2011			0 0
Airframe											
CAA IL ISR-I-57-2021-12-4 (990383)	CAA Il Isr-I-57-2021-12-4 - Wings-Flaps-Fairing Seal Repair		HRS AFL MOS MSC		296.2 192 19.4		-	6104.1 4022 16 Dec 2023			0 0
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
FAA 1974-08-09 R02 (997405) Airframe	FAA 1974-08-09 R02 - Lavatory Paper or Linen Waste Receptacle FIRE Prevention		HRS AFL MOS MSC	3511.8 2405 183.5			-	2888.5 1809 12 Apr 2010			0 0
Notes: AD 1974-08-09R2 LAV PAPER OR LINEN RECEPTACLE C/W. ALL REQUIRED PLACARDS ARE IN PLACE AND ALL DOORS OPERATE NORMALLY. ALL ASHTRAY RECEPTACLES ARE IN PLACE AS WELL. NO DEFECTS NOTED. I/A/W AD 74-08-09R2 DATED 29 JULY 1996. NEXT INSPECTION DUE @ 3888.5											
FAA 1974-08-09 R03 PARA (K) (994002) Airframe	FAA 1974-08-09 R03 Para (K) - Inspect All Lavatory Paper and Linen Waste Receptacle Enclosure Access Doors and Disposal Doors for Proper Operation, Fit, Sealing, and Latching for the Containment of Possible Trash Fires		HRS AFL MOS	581 366 28.6			1000	5819.3 3848 10 Mar 2023	6819.3		0 0
FAA 1982-21-04 (998204) Airframe	FAA 1982-21-04 - Electrical Power - to Prevent A Flase Indication that Emergency Power Is Available		HRS AFL MOS MSC	6359.3 4199 267.6			-	41 15 10 Apr 2003			0 0
FAA 1987-06-09 (998725) Airframe	FAA 1987-06-09 - Electrical Power - Visually Inspect for Installation In Aircraft of Any of the Applicable Circuit Breakers and Determine that None of the Applicable Circuit Breakers Are Installed In Aircraft By an Examination of Maintenance and/or Purchasing Records.		HRS AFL MOS MSC	6359.3 4199 267.6			-	41 15 10 Apr 2003			0 0
FAA 1988-11-08 (998825) Airframe	FAA 1988-11-08 - Lights - Install A Fuse Assembly for Each Affected Ballast		HRS AFL MOS MSC	6359.3 4200 267.6			-	41 14 10 Apr 2003			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 1990-07-08 R01 (999025) Airframe	FAA 1990-07-08 R01 - Lights - to Prevent Smoke, FIRE, and Possible Electrical Shock, or Electromagnetic Interference to Flight Critical or Essential Systems	HRS AFL MOS MSC	6359.3 4199 267.6			- -	41 15 10 Apr 2003			0 0
FAA 1990-09-10 (999050) Airframe	FAA 1990-09-10 - Electrical Power - Replace Texas Instruments Circuit Breaker Models 6TC67.5 and 10 and Models 6TC207.5 and 10, All With Date Codes 8150 and Earlier	HRS AFL MOS MSC	6359.3 4199 267.6			- -	41 15 10 Apr 2003			0 0
FAA 1995-25-08 (999505) Airframe	FAA 1995-25-08 - Equipments/Furnishings - Install A Pressure Relief Valve	HRS AFL MOS MSC	6359.3 4199 267.6			- -	41 15 10 Apr 2003			0 0
FAA 1995-26-15 R01 (999510) Airframe	FAA 1995-26-15 R01 - Navigation - Revision to Airplane Flight Manual (Afm) to Provide the Flight Crew With Procedures to Cycle Power to the TCAS Processor Via the Circuit Breaker or Power Bus, and to Perform A TCAS Functional Test to Verify Proper Operation of the TCAS	HRS AFL MOS MSC	6359.3 4199 267.6			- -	41 15 10 Apr 2003			0 0
FAA 1996-12-09 (999605) Airframe	FAA 1996-12-09 - Equipments/Furnishings - Remove the Footrest Assembly Arms and the Installa A Conversion Kit on Each PTC Model 950 Series Passenger Seat Equipped With Footrest Assembly	HRS AFL MOS MSC	6359.3 4199 267.6			- -	41 15 10 Apr 2003			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 1997-01-12 (999705) Airframe	FAA 1997-01-12 - Remove and Replace Centaurus Model C3-100 Ground Proximity Warning System (GPWS) Equipment	HRS AFL MOS MSC		6359.3 4199 267.6		-	41 15 10 Apr 2003			0 0
FAA 1997-04-15 (999710) Airframe	FAA 1997-04-15 - FIRE Protection - Perform One-Time Inspection of the Electrical Receptacle of These FIRE Extinguisher Bottle Cartridges and Their Mating Connectors to Detect the Presence of Aluminum Foil In the AREA of the Pins of the Cartridges and the Connectors, and Removal of Any Aluminum Foil that Is Present	HRS AFL MOS MSC		6359.3 4199 267.6		-	41 15 10 Apr 2003			0 0
FAA 1997-05-03 R01 (999715) Airframe	FAA 1997-05-03 R01 - Navigation - Insert A Limitation Into the Operations Limitation Section of the Airplane Flight Manual (Afm) or Flight Manual Supplement for All Owners/Operators of Aircraft Equipped With an Alliedsignal Avionics, Inc. (Alliedsignal) Models Gns-Xls or Gns-Xl Global Positioning Systems (GPS) Flight Management System.	HRS AFL MOS MSC		6359.3 4199 267.6		-	41 15 10 Apr 2003			0 0
FAA 1997-11-10 (999720) Airframe	FAA 1997-11-10 - Oxygen - Remove Any Passenger Oxygen Mask With the Applicable Part Number and Manufacturing Date and Replace With an FAA-Approved Oxygen Mask that Incorporates A Part Number Not Covered By This AD.	HRS AFL MOS MSC		6359.3 4199 267.6		-	41 15 10 Apr 2003			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 1997-18-03 (999725) Airframe	FAA 1997-18-03 - Oxygen - Replace Any Cone and Seal Assembly Referenced In the Applicability Section of This AD With an FAA-Approved Assembly Not Covered By This AD	HRS AFL MOS MSC		6359.3 4199 267.6		-	41 15 10 Apr 2003			0 0
FAA 1998-20-17 (999805) Airframe	FAA 1998-20-17 - Electrical Power - Replace All Battery Terminal Screws, Verify that the Battery Contains Design Specification Cells and Replace the Cells IF the Battery Contains Non-Design Specification Cells (Superseded By FAA AD 2005-13-18)	HRS AFL MOS MSC		6359.3 4199 267.6		-	41 15 10 Apr 2003			0 0
FAA 1998-25-10 R01 (999810) Airframe	FAA 1998-25-10 R01 - Equipments/Furnishings - Visually Check All Affected Seat Restraint Systems to Determine IF the Locking Mechanism Is Engaging Properly and Replace the Buckle With an Airworthy Buckle (IF the Locking Mechanism Does Not Seat Properly)	HRS AFL MOS MSC		6359.3 4199 267.6		-	41 15 10 Apr 2003			0 0
FAA 1999-01-14 (999905) Airframe	FAA 1999-01-14 - Equipments/Furnishings - Modification of the Integrated Avionics Computers	HRS AFL MOS MSC		6359.3 4199 267.6		-	41 15 10 Apr 2003			0 0
FAA 1999-04-10 (999915) Airframe	FAA 1999-04-10 - Lights - Visual Inspection to Determine the Type of Fluorescent Light Ballasts Installed In the Cabin Sidewall, and the Replacement of Suspect Ballasts With New or Serviceable Ballasts	HRS AFL MOS MSC		6359.3 4199 267.6		-	41 15 10 Apr 2003			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
FAA 1999-23-22 R02 (999925) Airframe	FAA 1999-23-22 R02 - Navigation - Perform Repetitive Tests to Detect Discrepancies of the MODE C Transponder(S), AIR Data Computer, and Certain Wiring Connections; and Corrective Actions, IF Necessary	HRS AFL MOS MSC		6359.3 4199 267.6		- -	41 15 10 Apr 2003			0 0
FAA 2001-03-01 (990130) Airframe	FAA 2001-03-01 - Doors - Revise the Airplane Flight Manual to Advise of the Proper Operation of the Main Entry Door	HRS AFL MOS MSC		6359.3 4199 267.6		- -	41 15 10 Apr 2003			0 0
FAA 2001-03-02 (990135) Airframe	AD 2001-03-02 Engine Life Limits PAR	HRS AFL MOS MSC		6359.3 4199 267.6		- -	41 15 10 Apr 2003			0 0
FAA 2001-10-09U Airframe Notes: N/A due to affected equipment not installed	FAA AD 2001-10-09 Amdt 39-12235 Honeywell Afcs	HRS AFL MOS MSC		445.3 275 24.5		O/C	5955 3939 11 Jul 2023			0 0
FAA 2001-14-51 (990115) Airframe Notes: N/A - Collins equipment installed	FAA 2001-14-51-E - Navigation - Determine what Version of Digital Signal Processor (DSP) Software the UPS Aviation Technologies, Inc., Model Apollo SL30 VHF Nav/Comm Radio Is Using and Install A Placard for Not to Use	HRS AFL DATE MSC		6400.3 4214		- -	0 0			0 0
FAA 2001-15-17 (990120) Airframe Notes: N/A - Part not installed	FAA 2001-15-17 - Navigation - Modify the Altitude Encoder Inputs of the Ctl-92 Transponder Control Panels	HRS AFL DATE MSC		6400.3 4214		- -	0 0			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 2001-18-05[U]	FAA AD 2001-18-05 Amdt 39-12431 Flight Eagle Ture 34X9.25 18PR 210 Mph	HRS AFL MOS MSC		445.3 275 24.5		 O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2001-22-14	FAA 2001-22-14 - Overland Aviation Services FIRE Extinguishing System Bottle Cartridges	HRS AFL MOS MSC		6359.3 4199 267.6		 -	41 15 10 Apr 2003			0 0
(990140) Airframe										
FAA 2001-23-17	FAA 2001-23-17 - Navigation - Modify the Affected Gns 430 Unit to Incorporate Circuitry Changes to the Deviation and Flag Outputs	HRS AFL MOS MSC		6359.3 4199 267.6		 -	41 15 10 Apr 2003			0 0
(990145) Airframe										
FAA 2002-06-05	FAA 2002-06-06 - Navigation - Modify Unit to Prevent Erroneous Altitude Reporting	HRS AFL MOS MSC		6359.3 4199 267.6		 -	41 15 10 Apr 2003			0 0
(992215) Airframe										
FAA 2002-06-06	FAA 2002-06-06 - Navigation - Modify Unit to Prevent Erroneous Altitude Reporting	HRS AFL MOS MSC		6359.3 4199 267.6		 -	41 15 10 Apr 2003			0 0
(992220) Airframe										
FAA 2002-07-02	FAA 2002-07-02 - Landing Gear - Perform Repetitive Inspections of the Main Landing Gear (MLG) Actuators for Leakage of Hydraulic Fluid, A One-Time Inspection of the MLG Actuators for Internal Abrasions or Scratches, and Replacement of the MLG Actuator With A New or Serviceable or New, Improved Actuator, IF Necessary	HRS AFL DATE MSC		6400.3 4214		 -	0 0			0 0
(992202) Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 2002-10-09	FAA 2002-10-09 - Fuel - Repetitive Inspections for Evidence of Fuel Accumulation Inside of the Aft Service Compartment; and Follow-on Actions, IF Necessary	HRS AFL MOS MSC		6359.3 4199 267.6		-	41 15 10 Apr 2003			0 0
(992210) Airframe										
FAA 2002-13-07	FAA 2002-13-07 - Electrical Power - Inspect the Affected Irus for Proper Function and Remove the Iru Either Immediately or AT A Certain Time Depending on the Result of the Inspection	HRS AFL MOS MSC		6359.3 4199 266.3		-	41 15 20 May 2003			0 0
(992203) Airframe Notes: N/A - Not Installed										
FAA 2002-14-19	FAA 2002-14-19 - Navigation - Replace Any Affected AIR Data Computer (ADC) With One that Has A Reprogrammed and Tested Central Processing Unit (Cpu) Circuit Card and Circuit Card Assembly	HRS AFL MOS MSC		6359.3 4199 267.6		-	41 15 10 Apr 2003			0 0
(990219) Airframe										
FAA 2002-15-02[U]	FAA AD 2002-15-02 Amdt 39-12830 Hamilton Sundstrand Auxilary Power Units	HRS AFL MOS MSC		445.3 275 24.5		O/C	5955 3939 11 Jul 2023			0 0
Airframe Notes: N/A due to affected equipment not installed										
FAA 2002-20-09[U]	FAA AD 2002-20-09 Amdt 39-12906 Collins Afd-3010 Adaptive Flight Display Units	HRS AFL MOS MSC		445.3 275 24.5		O/C	5955 3939 11 Jul 2023			0 0
Airframe Notes: N/A due to affected equipment not installed										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
FAA 2002-21-01	FAA 2002-21-01 - Equipments/Furnishings - Inspecting the Wiring for Indications of Overheating or Electrical Arcing, and IF Indications Are Found, Replacing the Wiring	HRS AFL MOS MSC		6359.3 4199 267.6		-	41 15 10 Apr 2003			0 0
(992204)										
Airframe										
FAA 2002-22-12U	FAA AD 2002-22-12 Amdt 39-12938 Titeflex High and Medium Pressure Hoses	HRS AFL MOS MSC		445.3 275 24.5		O/C	5955 3939 11 Jul 2023			0 0
Airframe										
FAA 2002-22-13	FAA 2002-22-13 - Navigation - Replacement of Rockwell Collins FMC-4200, FMC-5000 and FMC-6000 Computers to Prevent the FMC from Retaining Original Information when an Edit Is Made to A Procedure or Flight Plan	HRS AFL MOS MSC		6359.3 4199 267.6		-	41 15 10 Apr 2003			0 0
(992206)										
Airframe										
FAA 2002-23-01	FAA 2002-23-01 - Fuselage - One-Time Inspection for Evidence of Damage to the Forward Engine Cross Spar Assembly; and Repair IF Necessary	HRS AFL MOS MSC		6359.3 4199 267.6		-	41 15 10 Apr 2003			0 0
(992205)										
Airframe										
FAA 2003-15-07U	FAA AD 2003-15-07 Amdt 39-13250 RE220 (Rj) Auxiliary Power Units	HRS AFL MOS MSC		445.3 275 24.5		O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2003-26-06U	FAA AD 2003-26-06 Amdt 39-13403 Anjou Aeronautique Safety Belts and Restraints	HRS AFL MOS MSC		445.3 275 24.5		O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 2003-26-14 (992310) Airframe	FAA 2003-26-14 - FIRE Protection - Remove the Affected FIRE Extinguishers from Service and Would Prevent You from Using Them In the Future	HRS AFL MOS MSC		6029.3 4026 257		- -	371 188 27 Feb 2004			0 0
FAA 2004-08-15U Airframe Notes: N/A due to affected equipment not installed	FAA AD 2004-08-15 Amdt 39-13584 Goodrich TAWS - 8000 Terrain Awareness Warning Systems	HRS AFL MOS MSC		445.3 275 24.5		O/C	5955 3939 11 Jul 2023			0 0
FAA 2004-09-24 (992407) Airframe	FAA 2004-09-24 - Flight Controls - Perform Detailed Visual Inspection for Proper Lubrication of the Internal and External Spring Sleeves of the Aileron Afu and Lubricate the Internal and External Spring Sleeves and the Face of the Nut of the Afu With Dow Corning 55 Grease, IF the Afu Sleeves Are Not Properly Lubricated	HRS AFL MOS [End Of Month Item] [HRS: +50/-50]		157.9 100 9.8		500 12	6242.4 4114 03 Oct 2024	6742.4 03 Oct 2025	6792.4	0 0
FAA 2004-13-20U Airframe Notes: N/A due to affected equipment not installed	FAA AD 2004-13-20 Amdt 39-13702 Garmin AT Global Positioning System (GPS)	HRS AFL MOS MSC		445.3 275 24.5		O/C	5955 3939 11 Jul 2023			0 0
FAA 2004-16-03 (992410) Airframe	FAA 2004-16-03 - Flight Controls - Onetime Detailed Inspection of the Wing Flap Actuators for Proper Bonding of the Flap Actuator Fairings to the Lower Skin of the Wings, and Related Corrective or Preventative Actions	HRS AFL MOS MSC		5774.3 3906 251.1		- -	626 308 24 Aug 2004			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 2004-16-04[U]	FAA AD 2004-16-14 Amdt 39-13770 Thales TCAS Ii Resolution Advisory	HRS AFL MOS MSC		445.3 275 24.5		O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed. Collins TCAS PN 822-1294-002 installed										
FAA 2004-24-03[U]	FAA AD 2004-24-03 Amdt 39-13879 Hamilton Sundstrand T-62T Series APU	HRS AFL MOS MSC		445.3 275 24.5		O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2004-26-16R1[U]	FAA AD 2004-25-16R1 Amdt 39-14076 Fuel Regulator Shutoff Valve	HRS AFL MOS MSC		445.3 275 24.5		O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2005-01-19[U]	FAA AD 2005-01-19 Amdt 39-13944 Garmin GTX33. 33D. 330. 330D MODE S Transponders	HRS AFL MOS MSC		445.3 275 24.5		O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2005-16-13	FAA 2005-16-13 - Electrical Power - Perform A General Visual Inspection to Detect Damage of the Wiring, Splice, Connector, or Pins of the Left and Right Fuel Standby Feed Pumps and Replacement of Any Damaged Wiring, Splice, Connector, or Pin and Replacement of the Power and Ground Wires for the Fuel Standby Feed Pumps	HRS AFL MOS MSC		5322.1 3662 239.4		-	1078.2 552 17 Aug 2005			0 0
(992510)										
Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
FAA 2005-20-26[U]	FAA AD 2005-20-26 Amdt 39-14323 Aviointeriors Model 312 Box Mounted Seats	HRS AFL MOS MSC		445.3 275 24.5		 O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2005-23-11[U]	FAA AD 2005-23-11 Amdt 39-14369 Hamilton Sundstrand T-62T Series APU	HRS AFL MOS MSC		445.3 275 24.5		 O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2005-25-08 [U]	FAA AD 2005-25-08 Amdt 39-14401 Shadin ADC=2000 AIR Data Computers - Incorrect Altitude Information	HRS AFL MOS MSC		445.3 275 24.5		 O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2006-04-04[U]	FAA AD 2006-04-04 Amdt 39-14485 Meggitt Model 602 Smoke Detectors	HRS AFL MOS MSC		445.3 275 24.5		 O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed. Kidde PN 473057 Installed										
FAA 2006-08-03[U]	FAA AD 2006-08-03 Amdt 39-14557 Sicma Aero Seat, Cabin Attendant Seat Serirs 150 and 151	HRS AFL MOS MSC		445.3 275 24.5		 O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2006-10-18	FAA 2006-10-18 - Engine - Revise the Limitations Section of the Airplane Flight Manual (Afm) By Incorporating Revised Takeoff Performance Tables	HRS AFL MOS MSC		5086 3519 227.4		 -	1314.3 695 15 Aug 2006			0 0
(992605)										
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 2006-12-25[U]	FAA AD 2006-12-25 Amdt 39-14651, General Maching-Diecron, Actuator Nut Assy on Rh MLG	HRS AFL MOS MSC		445.3 275 24.5		 O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2006-16-18 R1[U]	FAA AD 2006-16-18 R1 Amdt 39-15557, Sandal TAWS-Rmi Model ST3400	HRS AFL MOS MSC		445.3 275 24.5		 O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2006-17-13[U]	FAA AD 2006-17-13 Amdt 39-14734 Recaro Aircraft Seating Model 3410 Seats. Seat Belt Detachment	HRS AFL MOS MSC		445.3 275 24.5		 O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2006-18-08[U]	FAA AD 2006-18-08 Amdt 39-14746 Goodyear Tire Pn 217K22-1	HRS AFL MOS MSC		445.3 275 24.5		 O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2006-19-04[U]	FAA AD 2006-19-04 Amdt 39-14761 Honeywell Comm Unit Rcz-833J and MODE S Trnasponders	HRS AFL MOS MSC		445.3 275 24.5		 O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2006-25-15 [U]	FAA AD 2006-25-15 Amdt 39-14856 Sicma Aero Seat, Third Occupant Seat Assemblies, 133 Series	HRS AFL MOS MSC		445.3 275 24.5		 O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 2007-04-15[U]	FAA AD 2007-04-15 Amdt 39-14947 Sicma Aero Seat Passenger Seat Assemblies	HRS AFL MOS MSC		445.3 275 24.5		O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2007-07-11	FAA 2007-07-11 - Fuel - Replace the Wiring and Do A General Visual Inspection for Other Components Damaged By Overheating and Replace All Damaged Components	HRS AFL MOS MSC		6400.3 4214 219.3		-	0 0 18 Apr 2007			0 0
(992705)										
Airframe										
Notes: N/A BY A/C EFFECTIVITY										
FAA 2007-07-13	FAA 2007-07-13 - Instruments - Inspect the Wiring Harness for Chafing and Perform Repairs and Inspect to Make Sure the Wire Harnesses Have Proper Clearance and Reroute/Relocate Wire Harnesses to Obtain Proper Clearance	HRS AFL MOS MSC		6400.3 4214 222.3		-	0 0 19 Jan 2007			0 0
(992706)										
Airframe										
Notes: N/A BY A/C EFFECTIVITY										
FAA 2007-14-06[U]	FAA AD 2007-14-06 Amdt 39-15128 Aerotechnic/Honeywell CAS67A ACAS Ii System	HRS AFL MOS MSC		445.3 275 24.5		O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2007-17-16	FAA 2007-17-16 - AIR Conditioning - Replace the Pressurization Safety Valve, Part Number 103842-3	HRS AFL MOS MSC		6400.3 4214 213.8		-	0 0 02 Oct 2007			0 0
(992709)										
Airframe										
Notes: N/A BY A/C S/N										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 2007-19-12[U]	FAA AD 2007-19-12 Amdt 39-15203 Sicma Aero Seat 50XXX Passenger Seats	HRS AFL MOS MSC		445.3 275 24.5		 O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2007-26-11[U]	FAA AD 2007-26-11 Amdt 39-15313 Zodiac Oxygen Cylinder	HRS AFL MOS MSC		445.3 275 24.5		 O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2008-06-27[U]	FAA AD 2008-06-27 Amdt 39-15439 Goodrice Evacuation Systems Approved Undet TSO-C69 Series	HRS AFL MOS MSC		445.3 275 24.5		 O/C	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2008-07-09[U]	Prevent the Potential of Ignition Sources Inside Fuel Tanks (Mandatory)	HRS AFL MOS MSC		445.3 275 24.5		 -	5955 3939 11 Jul 2023			0 0
Airframe										
FAA 2008-07-09 PARA (F)[U]	Submit Report to FAA (Mandatory)	HRS AFL DATE MSC		445.3 275 748 d		 -	5955 3939 11 Jul 2023			0 0
Airframe										
FAA 2008-07-09 PARA (G)[U]	Deactivation of Auxiliary Fuel Tanks (Mandatory)	HRS AFL MOS MSC		445.3 275 24.5		 -	5955 3939 11 Jul 2023			0 0
Airframe										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
FAA 2008-16-10 PARA (F)(1) (992810) Airframe	FAA 2008-16-10 Para (F)(1) - Hydraulic Tubes - Supporting Blocks Visual Inspection		HRS AFL MOS	3916 2713 192.7				2484.3 1501 06 Jul 2009			0 0
Notes: A.D. 2008-16-10 HYDRAULIC TUBES-SUPPORTING BLOCKS AMENDMENT 39-15628 IS COMPLIED WITH GULFSTREAM SERVICE BULLETIN 200-29-316 DATED 29 JUNE 2007. SERVICE BULLETIN WAS INCORPERATED BY GDAS CRS# LEGR039G ON 8/14/2007 @ 1667.9 AIRCRAFT HOURS AND 936 AIRC											
FAA 2008-16-10 PARA (F)(2) (992811) Airframe	FAA 2008-16-10 Para (F)(2) - Hydraulic Power - Replace Teflon Clamping Blocks (Terminating Action)		HRS AFL MOS MSC	3916 2713 192.7			- -	2484.3 1501 06 Jul 2009			0 0
Notes: A.D. 2008-16-10 HYDRAULIC TUBES-SUPPORTING BLOCKS (TERMINATING ACTION)AMENDMENT 39-15628 IS COMPLIED WITH GULFSTREAM SERVICE BULLETIN 200-29-316 DATED 29 JUNE 2007. SERVICE BULLETIN WAS INCORPERATED BY GDAS CRS# LEGR039G ON 8/14/2007 @ 1667.9 AIRCRAF											
FAA 2009-05-08U Airframe	FAA AD 2009-05-08 , Amdt 39 - 15832, Trimble or Freeflight I/O Approach Plus GPS		HRS AFL MOS MSC	445.3 275 24.5			- -	5955 3939 11 Jul 2023			0 0
Notes: N/A due to affected equipment not installed											
FAA 2009-08-01U Airframe	FAA AD 2009-08-01 - Amdt 39-15874, Honeywell Nz-2000 -IC-800(E)		HRS AFL MOS MSC	445.3 275 24.5			- -	5955 3939 11 Jul 2023			0 0
FAA 2009-13-09U Airframe	FAA AD 2009-13-09 Amdt 39-15948, Microturbo SA Saphir 2 Model 016 APU		HRS AFL MOS MSC	445.3 275 24.5			- -	5955 3939 11 Jul 2023			0 0
Notes: N/A due to affected equipment not installed											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 2009-21-10 R1[U]	FAA AD 2009-21-10 R1, Amdt 39-16179, Avox Systems and B/E Aerospace Oxygen Cylinders	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2010-01-03	FAA 2010-01-03 - Identify and Remove from Service All Affected FIRE Extinguishers and Replace With Servicable Units	HRS AFL MOS MSC		3656.2 2498 185.9		-	2744.1 1716 30 Jan 2010			0 0
(993001)										
Airframe										
Notes: PN: ANY SN: <NONE>. AIRWORTHINESS DIRECTIVE 2010-01-03 FIRE FIGHTING ENTERPRISES LIMITED. PERFORMED INSPECTION OF BOTH COCKPIT AND CABIN PORTABLE HALON BOTTLES. BOTH FITRE BOTTLES WERE MANUFACTURED BY COMPANIES OTHER THAN FIRE FIGHTING ENTERPRISES. NO DEFECTS NOTED. NO										
FAA 2010-04-16[U]	FAA AD 2010-04-16, Amdt 39-16209 - Sicli H1-10 Portable Halon 1211 FIRE Extinguishers	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2010-07-02[U]	FAA AD 2010-07-02 Amdt 39-16246 , Honeywell Primus Ii Rnz-850() -851() Integrated Nav Units	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2010-09-04[U]	FAA AD 2010-09-04 Amdt 39-16269, Honeywell Primus Epic and Primus Apex FMS	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
FAA 2010-11-05U	FAA AD 2010-11-05, Amdt 39-16310, Avox Systems and B/E Aerospace Oxygen Cylinders		HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe											
Notes: N/A due to affected equipment not installed. Zodiac P/N 806369-11 is installed											
FAA 2010-20-04	FAA 2010-20-04 - Flight Controls - Revise the Limitations Section of the Gulfstream 200 Afm		HRS AFL MOS MSC		3349.2 2258 176.6		-	3051.1 1956 08 Nov 2010			0 0
(993006)											
Airframe											
Notes: AD 2010-20-04 EXTENSION OF AIRBRAKES ABOVE 360 KIAS IS COMPLIED WITH. AFM REV.14 IS INSTALLED IN THE MANUAL. NO FURTHER ACTION IS REQUIRED. I/A/W AD 2010-20-04 AMENDMENT 39-16438 PARA. G NOTES 1 AND 2.											
FAA 2011-01-09	FAA 2011-01-09 - Oxygen - Inspect to Determine the Serial Number of the Pbe Units Installed In the Aircraft and Replace the Pbe With A Serviceable Pbe IF Any Pbe that Has A Serial Number from 003-50730M to 003-51329M Inclusive		HRS AFL MOS MSC		3023.6 2026 168.7		-	3376.7 2188 06 Jul 2011			0 0
(993009)											
Airframe											
FAA 2011-14-08U	FAA AD 2011-14-08 Amdt 39-16743, B/E Aerospace Passenger Oxygen Masks		HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe											
Notes: N/A due to affected equipment not installed. Zodiac mask P/N MW37-40 is installed											
FAA 2011-20-04	FAA 2011-20-04 - Standard Practices/Structures - Replace Nuts Having Part Number (P/N) MS21042L3 In the Applicable Areas and Do A Radiographic Inspection for Cracking of Nuts		HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
(993015)											
Airframe											
Notes: N/A per AC SN effectivity											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 2011-21-08[U]	FAA AD 2011-21-08, Amdt 39-16831, Sicma Aero Passenger Seat Assemblies	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2011-23-07	FAA 2011-23-07 - Flight Controls - One-Time Detailed Inspection of the Aileron and Elevator Control Servo Actuators to Detect Fractured or Broken Centering Spring Rods and Replace the Centering Spring ROD IF Any Centering Spring ROD Is Found Fractured or Broken During Any Inspection	HRS AFL MOS MSC		2569.6 1686 151.5		-	3830.7 2528 13 Dec 2012			0 0
(993018)										
Airframe										
Notes: AD2011-23-07 AMENDMENT39-16858 AILERON SERVO ACTUATOR CENTERING SPRING ROD INSPECTION IS COMPLIED WITH AND PREVIOUSLY COMPLIED WITH BY GULFSTREAM SERVICE BULLETIN 200-27-374 R1 ON 11 MAY 2011 3336.5 ACFT. HRS 2151 LANDINGS. NO DEFECTS NOTED.										
FAA 2012-02-08[U]	FAA AD 2012-21-08, Amdt 39-16931, Acss TCAS Units	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed. Collins P/N 822-1294-002 installed										
FAA 2012-06-25[U]	FAA AD 2012-06-25, Amdt 39-17006, Goodrich Evacuation Systems Pressure Relief Valves Do Not Seal.	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2012-14-15[U]	FAA AD 2012-14-15, Amdt 39-17129, Honeywell Inc. Gnssu - to Prevent Misleading Information During Approach	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
FAA 2012-17-01U	FAA AD 2012-17-01, Amdt 39-17164, Goodyear Aviation Tires Pn 299K63-1	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		24.5			11 Jul 2023			
		MSC				-				
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2014-05-27U	FAA AD 2014-05-17, Amdt 39-17799, Rockwell Collins MODE S Transponders Model TPR-720 and TPR-900.	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		24.5			11 Jul 2023			
		MSC				-				
Airframe										
Notes: N/A due to affected equipment not installed. Transponder P/N 622-9210-501 installed										
FAA 2014-17-02U	FAA AD 2014-17-02, Amdt 39-17955, Honeywell Asca ELT Model Rescu 406AF and 406 Afn	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		24.5			11 Jul 2023			
		MSC				-				
Airframe										
Notes: N/A due to affected equipment not installed. Artex C406M ELT installed										
FAA 2014-18-01	FAA 2014-18-01 - Navigation - Rockwell Collins, Inc. MODE S Transponders - Inspection / Modification	HRS		1737.1			4663.2			0
		AFL		1066			3148			0
		MOS		105.8			03 Oct 2016			
(994015)		MSC				-				
Airframe										
FAA 2015-08-07	FAA 2015-08-07 - Oxygen - Zodiac Aerotechnics (Formerly Intertechnique Aircraft Systems) Flightcrew Oxygen Mask Regulators - Inspection / Replacement of Inflatable Harnesses	HRS		1915.4			4484.9			0
		AFL		1200			3014			0
		MOS		121.9			31 May 2015			
(994018)		MSC				-				
Airframe										
Notes: AD2015-08-17 ZODIAC AEROTECHNICS- OXYGEN MASK REGULATOR INFLATABLE HARNESS- IDENTIFICATION/REPLACEMENT IS NOT APPLICABLE DUE TO ZODIAC AEROSPACE S/B MXH-35-240 PAGES 1-42. ESPECIALLY APPENDIX II AS P/N ON THIS AIRPLANE IS NOT AFFECTED.										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
FAA 2015-10-02U	FAA AD 2015-10-02, Amdt 39-18157, Zodiac Sicma Aero Passenger Seats France		HRS AFL MOS MSC		445.3 275 24.5		- -	5955 3939 11 Jul 2023			0 0
Airframe											
Notes: N/A due to affected equipment not installed											
FAA 2015-10-51U	FAA AD 2015-10-51, Amdt 39-18183, Avidyne Integrated Flight Displays		HRS AFL MOS MSC				- -				0 0
Airframe											
Notes: N/A due to affected equipment not installed											
FAA 2015-16-04	FAA 2015-16-04 - FIRE Protection - Modifying the Affected FIRE Extinguishers		HRS AFL MOS MSC		1802.5 1111 113		- -	4597.8 3103 27 Feb 2016			0 0
(994019)											
Airframe											
Notes: AD 2015-16-04 KIDDE GRAVINERIS NOT APPLICABLE TO THE FIRE EXTINGUISHER CURRENTLY INSTALLED ON BOARD OF N360SJ SN 68											
FAA 2015-23-09 INSPECT	AD 2015-23-09 Zodiac Aerotechnics Flightcrew Oxygen Mask Regulators (Part 1 - Inspect)		HRS AFL MOS MSC		1833.2 1136 115		- -	4567.1 3078 29 Dec 2015			0 0
(994022)											
Airframe											
FAA 2015-23-09 REPLACE	AD 2015-23-09 Zodiac Aerotechnics Flightcrew Oxygen Mask Regulators (Part 2 - Replace)		HRS AFL MOS MSC		1732.7 1064 96.5		- -	4667.6 3150 12 Jul 2017			0 0
(994023)											
Airframe											
Notes: INSPECTION PER AD 2015-23-09. AD IS NOT APPLICABLE DUE TO REGULATORS PART NUMBER ARE NOT LISTED IN APPENDIX 1 OF SB MCF-SBU-35-001.(ZODIAC AEROSPACE)PILOT AND CO-PILOT REGULATOR PART NUMBER ARE MC10-13-150.											
FAA 2016-11-20	FAA 2016-11-20 - Oxygen - Inspection and Replacement of B/E Aerospace Protective Breathing Equipment (Pbe), Part Number 119003-11 that Are Installed on Airplanes. Superseded By FAA AD 2017-18-12		HRS AFL MOS MSC		1737.1 1066 105.8		- -	4663.2 3148 03 Oct 2016			0 0
(994026)											
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
FAA 2017-04-06U	FAA AD 2017-04-06, Amdt 39-18801, United Instruments 5934 Series Altimeters	HRS AFL MOS MSC		445.3 275 24.5		--	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2017-11-11U	FAA AD 2017-11-11, Amdt 39-18910, Navworx ADS-B Universal Access Tracsceiver Units	HRS AFL MOS MSC		445.3 275 24.5		--	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2017-16-01U	FAA AD 2017-16-01, Amdt 39-18978, Ameri-King CORP. ELT Ak-450/Ak-451 Series Failure to Operate	HRS AFL MOS MSC		445.3 275 24.5		--	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed. Artex C406-2 ELT Installed										
FAA 2017-18-12	FAA 2017-18-12 - Oxygen - Inspection and Replacement of B/E Aerospace Protective Breathing Equipment (Pbe), Part Number 119003-11 and 119003-21 that Are Installed on Airplanes	HRS AFL MOS MSC		1477.9 896 80.4		--	4922.4 3318 16 Nov 2018			0 0
(994042)										
Airframe										
FAA 2017-22-14U	FAA AD 2017-22-14, Amdt 39-19094, Rockwell Collins Traffic Surveillance System Preocessing Unit Software.	HRS AFL MOS MSC				--				0 0
Airframe										
Notes: N/A due to affected equipment not installed. Collins TCAS P/N 822-1294-002 installed.										
FAA 2018-03-04U	FAA AD 2018-03-04, Amdt 39-19177, Rosemont Pitot Probes	HRS AFL MOS MSC		445.3 275 24.5		--	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed. Installed probe P/N and S/N's not listed in para (c)(1) and (c)(2) effectivity.										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
FAA 2018-21-14	FAA 2018-21-14 - Oxygen - Oxygen Mask Regulator Harness Inflation Hoses - Inspection / Replacement		HRS AFL MOS MSC		1053.8 664 45.8		-	5346.5 3550 04 Oct 2021			0 0
(994070)											
Airframe											
FAA 2019-07-03U	FAA AD 2019-07-03, Amdt 39-19614, Zodiac Seats France, 536 Series Cabin Attendant Seats		HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe											
Notes: N/A due to affected equipment not installed											
FAA 2019-07-10U	FAA AD 2019-07-10, Amdt 39-19621, Morthrup Grumman Litef Ahrs System Misleading Information.		HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe											
Notes: N/A due to affected equipment not installed											
FAA 2019-13-03U	FAA AD 2019-13-03, Amdt 39-19676, Trig Avionics TT31, Avidyne AXP340, and Bendix-King KT74 Transponders.		HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe											
Notes: N/A due to affected equipment not installed											
FAA 2019-14-05U	FAA AD 2019-14-05, Amdt 39-19683, B/E Aerospace Seat Energy Absorber		HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe											
Notes: N/A due to affected equipment not installed											
FAA 2019-15-10U	FAA AD 2019-15-10 Amdt 39-19703, Safran Aerosystems Life Jackets		HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe											
Notes: N/A due to affected equipment not installed											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
FAA 2019-21-06U	FAA AD 2019-21-06, Amdt 39-19722, Ipeco Holdings Pilot/Copilot Seats	HRS AFL MOS MSC		445.3 275 24.5		- - - -	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2019-21-09U	FAA AD 2019-21-09, Amdt 39-19775, Aviointeriors Life Vest Pouches	HRS AFL MOS MSC		445.3 275 24.5		- - - -	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2020-08-02U	FAA AD 2020-08-02, Amdt 39-21108, Thales Avionics Topstar 200 LPV GPS/Sbas Receiver	HRS AFL MOS MSC		445.3 275 24.5		- - - -	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2020-09-02U	FAA AD 2020-09-02, Amdt 39-21116,Anjou Aeronautique Model 358 Torso Restraint Systems	HRS AFL MOS MSC		445.3 275 24.5		- - - -	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2020-10-05U	FAA AD 2020-10-05, Amdt 39-21123, Pro Line 4 and Pro Line 21 Flight Management Systems	HRS AFL MOS MSC		445.3 275 24.5		- - - -	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed. FMS computer installed is P/N 822-0868-073, not listed in Para (c)(1) p/n effectivity										
FAA 2020-16-08U	FAA AD 2020-16-08, Amdt 39-21192, Aspen Avionics Primary Fligh Display/Multi Funcion Displays.	HRS AFL MOS MSC		445.3 275 24.5		- - - -	5955 3939 11 Jul 2023			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 2020-18-51U Logbook Position	FAA AD 2020-18-51, Amdt 39-21249, Sandia Attitude Indicators	HRS AFL MOS MSC		445.3 275 24.5		--	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2020-21-02U Logbook Position	FAA AD 2020-21-02, Amdt 39-21275, Kidde Aerospace Cargo Halon Extinguisher Bottles	HRS AFL MOS MSC		445.3 275 24.5		--	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2021-05-17U Logbook Position	FAA AD 2021-05-17, Amdt 39-21460, Rockwell Collins Flight Display System Application Fdsa-6500.	HRS AFL MOS MSC		445.3 275 24.5		--	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2021-07-13U Logbook Position	FAA AD 2021-07-13, Amdt 39-21490, Pacific Scientific CO. Rotary Buckle Assemblies	HRS AFL MOS MSC		445.3 275 24.5		--	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2021-08-07 (990807) Logbook Position	FAA 2021-08-07 - Rockwell Collins - Global Positioning System GPS-4000S - Upgrade	HRS AFL MOS MSC		445.3 275 24.5		--	5955 3939 11 Jul 2023	0 0		0 0
Airframe										
Notes: N/A due to affected equipment not installed. GPS P/N HG021KB02 Installed										
FAA 2021-08-07 PARA (G)(1) Logbook Position	FAA 2021-08-07 Para (G)(1) - Replace Each GPS-4000S GPS P/N 822-2189-100 With A GPS that Does Not Have P/N 822-2189-100	HRS AFL MOS MSC		581 366 28.6		--	5819.3 3848 10 Mar 2023			0 0
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 2021-08-15U	FAA AD 2021-08-15 Amdt 39-21509, Garmin International Gmn -00962 Gts Prcessor P/N 011-02571-0	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2021-22-07U	FAA AD 2021-22-07 Amdt 39-21780, Umlaut Halon Free Hand Held FIRE Extinguishers	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2021-23-12	FAA 2021-23-12 - Indicating / Recording / Navigation - Radio (Radar) Altimeter - Afm Revision to Incorporate Limitations	HRS AFL MOS MSC	1034.7 649 43	5365.6 3565		- 28 Dec 2021				0 0
(992199)										
Airframe										
FAA 2021-23-13U	FAA AD 2021-23-13, Amdt 39-21811 Helicopter Radio Altimeters 5G Interference	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										
FAA 2022-04-09U	FAA AD 2022-04-09 Amdt 39-21951 Avox Oxygen Cylinders and Valves	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed. Zodiac PN 895-18050 & PN 895-18015 O2 Cylinders installed										
FAA 2022-05-10U	FAA AD 2022-05-10 Amdt 39-21952, Goodrich Externally Mounted Hoist Assembly	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe										
Notes: N/A due to affected equipment not installed										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
FAA 2023-06-09 Airframe	Wings-Flaps-Fairing Seal Repair (Mandatory)	HRS AFL MOS MSC		33.1 21 2.2		-	6367.2 4193 23 May 2025			0 0
Notes: SB 200-57-426 C/W May 31, 2023 AFTT 5955, AFTL 3939										
FAA 2023-10-02 (992312) Airframe	Appliance AD - FAA 2023-10-02 - Indicating/Recording System/Navigation - Radio Altimeter - Afm Revision (Mandatory)	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
FAA 2023-10-02 PARA (H) (992313) Airframe	FAA 2023-10-02 Para (H) - Revise the Limitations Section of the Existing Afm (until 30-June- 2023 - Satisfied By FAA 2021-23-12)	HRS AFL DATE MSC				-				0 0
FAA 2023-10-02 PARA (I) (992314) Airframe	FAA 2023-10-02 Para (I) - Revise the Limitations Section and Remove the Afm Revision Required By Para (H) (after 30 Jun 2023) (Mandatory)	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
FAA 2023-11-07[U] Airframe	FAA AD 2023-11-07 Amdt 39-21962, Helicopters Radio Altimeters 5G Interferecnce	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Notes: N/A - This AD applies to helicopters only										
FAA 2023-13-11[U] Airframe	FAA AD 2023-13-11, Amdt 39-22496, Avox Systems Oxygen Cylinders and Valves	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Notes: N/A due to affected equipment not installed										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
FAA AD 2005-07-27[U] Airframe	FAA AD 2005-07-27 Amdt 39-14052 Aviointeriors Model 312 Seats		HRS AFL MOS MSC		445.3 275 24.5		O/C	5955 3939 11 Jul 2023			0 0
Notes: N/A due to affected equipment not installed											
TCCA CF-2000-27 (990004) Engine	No. 1 Engine - Tcca Cf-2000-27 - the Tad References the Airworthiness Limitations Section (ALS) In the Maintenance Manual P/N 30B1412 for the PW306A, and the Airworthiness Limitations Manual P/N 30B2978 for the PW306B.		HRS ENC MOS MSC		2682.4 1724 138.7		-	499.3 253 06 Jan 2014			0 0
TCCA CF-2000-27 (990004) Engine	No. 2 Engine - Tcca Cf-2000-27 - the Tad References the Airworthiness Limitations Section (ALS) In the Maintenance Manual P/N 30B1412 for the PW306A, and the Airworthiness Limitations Manual P/N 30B2978 for the PW306B.		HRS ENC MOS MSC		805 654 35.7		-	2011.3 1136 06 Aug 2022			0 0
SIAC - Service Information/Bulletins											
200-00-248 (972480) Airframe	Sb 200-00-248 - Aircraft General - Operating Weights - Increase of Maximum Takeoff Weight (Mtow)		HRS AFL MOS MSC		4487.1 3123 208.6		-	1913.2 1091 10 Mar 2008			0 0
200-00-248 R01 (972481) Airframe	Sb 200-00-248 R01 - Aircraft General - Operating Weights - Increase Maximum Takeoff Weight (Mtow)		HRS AFL MOS MSC		4487.1 3123 208.6		-	1913.2 1091 10 Mar 2008			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-05-280 (972800) Airframe	Sb 200-05-280 - General (ATA 05) - Transition from Existing Msg-3 Revision 2 Maintenance Inspection Program to Msg-3 Revision 2003.1 Maintenance Inspection Program	HRS AFL MOS MSC	4787.6 3321 219			-	1612.7 893 27 Apr 2007			0 0
200-11-151 (971510) Airframe	Sb 200-11-151 - Placards and Markings(ATA 11) - Aft Fuselage - Add Caution Placard on Water Service Panel	HRS AFL MOS MSC	6359.3 4199 267.6			-	41 15 10 Apr 2003			0 0
200-11-156 (971560) Airframe	Sb 200-11-156 - Placards and Markings(ATA 11) - Electronic Control Unit - Placard for Maintenance of Fsecu	HRS AFL MOS MSC	6359.3 4199 267.6			-	41 15 10 Apr 2003			0 0
200-11-181 (971810) Airframe	Sb 200-11-181 - Placards and Markings (ATA 11) Ground Power Unit - Installation of Placard Limiting Gpu Output to 800 Amps for Engine Starting	HRS AFL DATE MSC	6400.3 4214			-	0 0			0 0
200-11-187 (971870) Airframe	Sb 200-11-187 - Placards and Markings (ATA 11) - Engine Oil and Hydraulic Fluid Servicing - Installation of Caution Placards to Ensure Engine Oil Caps Are Properly Secured and Hydraulic Reservoirs Are Serviced With the Correct Hydraulic Fluid	HRS AFL MOS MSC	6359.3 4199 264.8			-	41 15 03 Jul 2003			0 0
200-11-215 (972150) Airframe	Sb 200-11-215 - Placards and Markings (ATA 11) Aft Fuselage - Installation of Ground Placard AT the Gravity Refueling Door	HRS AFL MOS MSC	5082.4 3518 227			-	1317.9 696 29 Aug 2006			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-11-237 (982370) Airframe	Sb 200-11-237 - Placards and Markings (ATA 11) Flight Compartment - Installation of Aileron and Elevator Disconnect Placard	HRS AFL MOS MSC		5774.3 3906 251.3		- -	626 308 20 Aug 2004			0 0
200-11-275 (972750) Airframe	Sb 200-11-275 - Placards and Markings - Passenger/Crew Door - Installation of Placards to Meet European Aviation Safety Agency (EASA) Certification Requirements	HRS AFL MOS MSC		4935.4 3426 223.2		- -	1464.9 788 22 Dec 2006			0 0
200-11-277 R01 (972771) Airframe	Sb 200-11-277 R01 - Placards and Markings (ATA 11) - Fuselage - Left and Right Hydraulic Accumulator Gauges - Remove and Replace Existing Placards	HRS AFL MOS MSC		5082.4 3518 227		- -	1317.9 696 29 Aug 2006			0 0
200-11-288 (972880) Airframe	Sb 200-11-288 - Placards and Markings (ATA 11) - Passenger/Crew Door - Install Two New Instructional Placards	HRS AFL MOS MSC		4787.6 3321 219.3		- -	1612.7 893 18 Apr 2007			0 0
200-11-324 (983240) Airframe	Sb 200-11-324 - Placards and Markings (ATA 11) - Placard Installation for Flammable Fluid Zone	HRS AFL MOS MSC		3023.6 2026 168.5		- -	3376.7 2188 11 Jul 2011			0 0
200-11-336 (983360) Airframe	Sb 200-11-336 - Placards and Markings (ATA 11) - Main Entrance Door - Installation of Two Placards	HRS AFL MOS MSC		4373.4 3044 204.4		- -	2026.9 1170 16 Jul 2008			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-11-357 (983570) Airframe	Sb 200-11-357 - Placards and Markings (ATA 11) - Auxiliary Power Unit - Replacement of Kill Switch Placards	HRS AFL DATE MSC		6400.3 4214		- 	0 0			0 0
200-11-357 R01 (983571) Airframe	Sb 200-11-357 R01 - Placards and Markings (ATA 11) - Auxiliary Power Unit - Replacement of Kill Switch Placards	HRS AFL DATE MSC		6400.3 4214		- 	0 0			0 0
200-11-364 (983640) Airframe	Sb 200-11-364 - Placards and Markings (ATA 11) - Main Entrance Door (Med) - Installation of Instructional Placard on Med Step Riser	HRS AFL MOS MSC		3432.5 2332 180.7		- 	2967.8 1882 07 Jul 2010			0 0
200-11-379 (983790) Airframe	Sb 200-11-379 - Placards and Markings - (ATA 11) - Exterior Placards and Markings - Installation of Engine Oil Service Placard	HRS AFL MOS MSC		3023.6 2026 168.9		- 	3376.7 2188 01 Jul 2011			0 0
200-11-383 (983830) Airframe	Sb 200-11-383 - Placards and Markings (ATA 11) Operating Speed Limitation Placards	HRS AFL MOS MSC		2624.5 1729 154.1		- 	3775.8 2485 24 Sep 2012			0 0
Notes: S/B 200-11-383 OPERATING SPEED LIMITATIONS PLACARD C/W. REMOVED EXISTING COCKPIT PLACARD AND INSTALLED 2 EACH P/N 4AS3851132-089 ON COCKPIT LEFT AND RIGHT SIDE WALLS. NO FURHTHER ACTION REQUIRED. I/A/W S/B 200-11-383 PAGE 1-7.										
200-11A-217 (990270) Airframe	Sb 200-11A-217 - Placards and Markings (ATA 11) - Interior - Installation of Lavatory Limitation Placard	HRS AFL MOS MSC		5774.3 3906 251.2		- 	626 308 21 Aug 2004			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
200-21-079	Sb 200-21-079 - AIR Conditioning - Baggage Compartment - Reduced Pressure In Baggage Compartment	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
(970790)										
Airframe										
Notes: N/A by Aircraft S/N										
200-21-206	Sb 200-21-206 - AIR Conditioning/Pressurization (ATA 21) Ecs - Improvement to Ecs Duct Connections	HRS AFL MOS MSC		5315.4 3658 239.1		-	1084.9 556 26 Aug 2005			0 0
(972060)										
Airframe										
200-21-229	Sb 200-21-229 - AIR Conditioning (ATA 21) - Ram AIR Supply Ram AIR Duct With Check Valve Installation	HRS AFL MOS MSC		5315.4 3658 238.5		-	1084.9 556 12 Sep 2005			0 0
(972290)										
Airframe										
200-21-257	Sb 200-21-257 - AIR Conditioning (ATA 21) - Cabin Pressure Control System (CPCS) Controller- Upgrade	HRS AFL MOS MSC		5082.4 3518 227		-	1317.9 696 29 Aug 2006			0 0
(972570)										
Airframe										
200-21-257 R01	Sb 200-21-257 R01 - AIR Conditioning - Cabin Pressure Control System (CPCS) Controller- Upgrade	HRS AFL MOS MSC		5082.4 3518 227		-	1317.9 696 29 Aug 2006			0 0
(972571)										
Airframe										
200-21-281 R01	Sb 200-21-281 R01 - AIR Conditioning (ATA 21) - Cabin Pressure Control System (CPCS) - Outflow Valve - Installation Provisions for Replacement Outflow Valve P/N 25G7810024-003/-005	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
(982811)										
Airframe										
Notes: PN: 25G7810024-005 SN: <NONE>.										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
200-21-308	Sb 200-21-308 - AIR Conditioning / Pressurization (ATA 21) - Safety Valve Replacment		HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
(983080)											
Airframe											
Notes: N/A by Aircraft S/N											
200-21-311	Sb 200-21-311 - AIR Conditioning (ATA 21) - Improvement of Baggage Compartment Pressurization		HRS AFL MOS MSC		4373.4 3044 204.5		-	2026.9 1170 14 Jul 2008			0 0
(973110)											
Airframe											
200-21-312	Sb 200-21-312 - AIR Conditioning (ATA 21) - Emergency Heat Exchanger Ram AIR Inlet Duct Installation of New Drain Line		HRS AFL MOS MSC		4373.4 3044 204.5		-	2026.9 1170 14 Jul 2008			0 0
(973120)											
Airframe											
200-21-312 R01	Sb 200-21-312 R01 - AIR Conditioning (ATA 21) - Emergency Heat Exchanger Ram AIR Inlet Duct Installation of Drain Line		HRS AFL MOS MSC		4108.4 2860 197.3		-	2291.9 1354 18 Feb 2009			0 0
(983121)											
Airframe											
Notes: SB200-21-312 REV 1 REQUIRES NO FURTHER ACTION DUE TO COMPLETION OF SB200-21-312 ON 7/14/2008 @ 2026.9 AIRCRAFT HOURS AND 1170 AIRCRAFT LANDINGS. I/A/W G200 SB200-21-312 REV 1 TRANSMITTAL SHEET.											
200-21-327	Sb 200-21-327 - AIR Conditioning (ATA 21) - Cabin Pressure Controller - Test of Cabin Pressure Controller		HRS AFL MOS MSC		4732.4 3278 215.5		-	1667.9 936 14 Aug 2007			0 0
(983270)											
Airframe											
200-21-327 R01	Sb 200-21-327 R01 - AIR Conditioning (ATA 21) - Cabin Pressure Controller - Test of Cabin Pressure Controller		HRS AFL MOS MSC		4612.2 3195 211.2		-	1788.1 1019 21 Dec 2007			0 0
(983271)											
Airframe											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
200-21-356	Sb 200-21-356 - AIR Conditioning (ATA 21) - Cockpit Lower Supply Duct - Airflow Modification	HRS AFL MOS MSC		3904.4 2705 192.4		-	2495.9 1509 16 Jul 2009			0 0
(983560)										
Airframe										
200-21-378	Sb 200-21-378 - AIR Conditioning - (ATA 21) - Cabin Pressurization Control System - Cabin Pressurization Controller (CPC) Replacement	HRS AFL MOS MSC		2378.1 1547 144.2		-	4022.2 2667 22 Jul 2013			0 0
(983780)										
Airframe										
200-21-385	Sb 200-21-385 - AIR Conditioning (ATA 21) - Duct Temperature Limiter - Installation Improvement	HRS AFL MOS MSC		2674.9 1776 156.3		-	3725.4 2438 18 Jul 2012			0 0
(983850)										
Airframe										
Notes: PN: 3171574-1 SN: <NONE>.										
200-21-387	Sb 200-21-387 - AIR Conditioning (ATA 21) - Environmental Control System (Ecs) Aft Fuselage Duct Insulation - Rework	HRS AFL MOS MSC		6400.3 4214 134.8		-	0 0 02 May 2014			0 0
(983870)										
Airframe										
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
200-21-387 R01	Sb 200-21-387 R01 - AIR Conditioning (ATA 21) - Environmental Control System (Ecs) Aft Fuselage Duct Insulation - Rework	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
(983871)										
Airframe										
200-22-246	Sb 200-22-246 - Autopilot (ATA 22) - Flight Control Computers - Replace the Existing Dual Flight Control Computers (FCC-4005) P/N 822- 0807-029 With P/N 822-0807-129 (Software Updated)	HRS AFL MOS MSC		5315.4 3658 238.5		-	1084.9 556 12 Sep 2005			0 0
(972460)										
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-22-249 (972490) Airframe	Sb 200-22-249 - Autopilot (ATA 22) - Rudder (Yaw Damper) Servo Motor Cables - Replace Existing Cables P/N 4AS5300133-503 With P/N 4AS5330576-501	HRS AFL MOS MSC		5315.4 3658 238.7		- -	1084.9 556 06 Sep 2005			0 0
200-23-165 (971650) Airframe	Sb 200-23-165 - Communications (ATA 23) - Radio Tuning Control System - Radio Tuning Unit (Rtu) Diagnostic Correction	HRS AFL DATE MSC		6400.3 4214		- -	0 0			0 0
200-23-232 (972320) Airframe	Sb 200-23-232 - Communications (ATA 23) - Radio Tuning Unit - Correct Operation of the Dimming Control	HRS AFL MOS MSC		5082.4 3518 227		- -	1317.9 696 29 Aug 2006			0 0
200-24-211 PART A (972110) Airframe	Sb 200-24-211 Part A - Electrical Power (ATA 24) Starter/Generator - Replacement	HRS AFL MOS MSC		5931.3 3975 252.2		- -	469 239 22 Jul 2004			0 0
200-24-211 PART B (972111) Airframe	Sb 200-24-211 Part B - Electrical Power (ATA 24) Starter/Generator - Replacement	HRS AFL MOS MSC		5958.3 3994 255.4		- -	442 220 15 Apr 2004			0 0
200-24-214 (972140) Airframe	Sb 200-24-214 - Electrical Power (ATA 24) Electrical Harness - Additional Clamping of Electrical Harness In Cabin	HRS AFL DATE MSC		6400.3 4214		- -	0 0			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
200-24-254	Sb 200-24-254 - Electrical Power (ATA 24) - Main and Emergency Batteries - Installation of Battery Discharge Warning Circuit	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
(972540) Airframe										
200-24-263	Sb 200-24-263 - Electrical Power (ATA 24) - Overhead Panel - Improvement of Harness Protection	HRS AFL MOS MSC		5086 3519 227.9		-	1314.3 695 31 Jul 2006			0 0
(972630) Airframe										
200-24-294	Sb 200-24-294 - Electrical Power (ATA 24) - Start Circuit Start Contactor Reliability Improvement	HRS AFL MOS MSC		4787.6 3321 219		-	1612.7 893 27 Apr 2007			0 0
(972940) Airframe										
200-24-326	Sb 200-24-326 - Electrical Power (ATA 24) - Installation of Thales Starter-Generator	HRS AFL MOS MSC		6400.3 4214 203.9		-	0 0 31 Jul 2008			0 0
(983260) Airframe										
200-24-326 R01	Sb 200-24-326 R01 - Electrical Power (ATA 24) - Installation of Thales Starter-Generator	HRS AFL MOS MSC		6400.3 4214 137.1		-	0 0 24 Feb 2014			0 0
(983261) Airframe										
Notes: THIS CODE HAS BEEN CANCELLED.										
200-24-326 R02	Sb 200-24-326 R02 - Electrical Power (ATA 24) - Installation of Thales Starter-Generator	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
(983262) Airframe										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
200-24-351	Sb 200-24-351 - Electrical Power (ATA 24) - Right Aft Contactor Box - Improvement of Cable Routing	HRS AFL MOS MSC		3904.4 2705 192.4		-	2495.9 1509 17 Jul 2009			0 0
(983510) Airframe										
200-24-355	Sb 200-24-355 - Electrical Power (ATA 24) - Goodrich Starter-Generator - Inspection of Terminal Block and Feeder Cables	HRS AFL MOS MSC		3904.4 2705 192.3		-	2495.9 1509 20 Jul 2009			0 0
(983550) Airframe										
200-24-375	Sb 200-24-375 - Electrical Power - (ATA 24) - Overhead Panel - Emergency AIR Circuit Breaker Power Source Change	HRS AFL MOS MSC		3063.8 2063 170.4		-	3336.5 2151 16 May 2011			0 0
(983750) Airframe										
200-24-415	Sb 200-24-415 - Electrical Power (ATA 24) - Installation of Extension Collars for Emergency Bus Circuit Breakers In Overhead Panel	HRS AFL MOS MSC		1878.6 1175 117.9		-	4521.7 3039 30 Sep 2015			0 0
(984150) Airframe										
Notes: S/B 200-24-415 INSTALLATION OF EXTENSION COLLARS FOR EMERGENCY BUS CIRCUIT BREAKERS IN OVERHEAD PANEL C/W. INSTALLED 3 EACH Y307 004 01 COLLARS ON L MAIN, R MAIN, AND BATT CIRCUIT BREAKERS. NO FURTHER ACTION REQUIRED. I/A/W G200 S/B 200-24-415.										
200-25-124 R02 PART B	Sb 200-25-124 R02 Part B - Equipment / Furnishings (ATA 25) - Baggage Compartment - Baggage Compartment Interior Improvements	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
(971245) Airframe										
200-25-124 R02 PART C	Sb 200-25-124 R02 Part C - Equipment / Furnishings (ATA 25) - Baggage Compartment - Baggage Compartment Interior Improvements	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
(971246) Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-25-124 R02 PART D (971247) Airframe	Sb 200-25-124 R02 Part D - Equipment / Furnishings (ATA 25) - Baggage Compartment - Baggage Compartment Interior Improvements	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
200-25-199 (981990) Airframe	Sb 200-25-199 - Equipment/Furnishings (ATA 25) Buffet/Galley - Replace Acrylic Glass Componets With Lexan Material	HRS AFL MOS MSC		6400.3 4214 267.4		-	0 0 15 Apr 2003			0 0
200-25-330 (973300) Airframe	Sb 200-25-330 - Equipment/Furnishings (ATA 25) - Passenger/Crew Door Stair Threshold Plate - Slip Resistant Tape Installation	HRS AFL MOS MSC		4732.4 3278 215.5		-	1667.9 936 13 Aug 2007			0 0
200-25-330 R01 (973301) Airframe	Sb 200-25-330 R01 - Equipment/Furnishings (ATA 25) - Passenger/Crew Door Stair Threshold Plate - Slip Resistant Tape Installation	HRS AFL MOS MSC		4373.4 3044 204.6		-	2026.9 1170 10 Jul 2008			0 0
200-25-330 R02 (983302) Airframe	Sb 200-25-330 R02 - Equipment/Furnishings (ATA 25) - Passenger/Crew Door Stair Threshold Plate - Slip Resistant Tape Installation	HRS AFL MOS MSC		4108.4 2860 197.3		-	2291.9 1354 18 Feb 2009			0 0

Notes: SB200-25-330 REV 2 IS COMPLIED WITH. REMOVED SLIP RESISTANT TAPE AS PER STEPS 5 AND 6. OF SERVICE BULLETIN. NO FURTHER ACTION REQUIRED. NO DEFECTS NOTED. I/A/W G200 SB200-25-330 REV 2 DATED 11/28/2008 PAGES 1-7.

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
200-25-330 R03	Sb 200-25-330 R03 - Equipment/Furnishings (ATA 25) - Passenger/Crew Door Stair Threshold Plate - Slip Resistant Tape Installation	HRS		3023.6			3376.7			0
		AFL		2026			2188			0
		MOS		168.9			01 Jul 2011			
		MSC				-				
(983303)										
Airframe										
200-25-418	Sb 200-25-418 - Equipment/Furnishings (ATA 25) - Emergency Escape Hatch Cabin Management System (Cms) Electrical Connectors - Inspection for Friction Only Installation of Electrical Connectors	HRS		1732.7			4667.6			0
		AFL		1064			3150			0
		MOS		95.6			09 Aug 2017			
		MSC				-				
(984180)										
Airframe										
200-25-420	Sb 200-25-420 - Equipment / Furnishings (ATA 25) - Vanity Water Heater - Electrical Connector Improvement	HRS		1477.9			4922.4			0
		AFL		896			3318			0
		MOS		80			27 Nov 2018			
(984200)		MSC				-				
Airframe										
200-27-052[U]	Sb 200-27-052 Idler Pulley Installation FS 480.7	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		24.5			11 Jul 2023			
		MSC				O/C				
Airframe										
Notes: N/A by Aircraft S/N										
200-27-055[U]	Sb 200-27-055 Replace Fasteners - Pedal Torque Tube	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		24.5			11 Jul 2023			
		MSC				O/C				
Airframe										
Notes: N/A by Aircraft S/N										
200-27-057[U]	Sb 200-27-057 - Replace Bolt In Rh Tension Regulator Lower Case Guard	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		24.5			11 Jul 2023			
		MSC				O/C				
Airframe										
Notes: N/A by aircraft S/N										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-27-158 (971580) Airframe	Sb 200-27-158 - Flight Controls (ATA 27) - Slats - Improve Routing of Slats Power Drive Unit (Pdu) Electrical Power Cable	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
200-27-218 (972180) Airframe	Sb 200-27-218 - Flight Controls (ATA 27) Rudder - Repair Backlash In Rudder Mechanism	HRS AFL MOS MSC		5315.4 3658 238.5		-	1084.9 556 12 Sep 2005			0 0
200-27-225 (972250) Airframe	Sb 200-27-225 - Flight Controls (ATA 27) Rudder Trim Tab - Repair Backlash In Rudder Trim Tab Mechanism	HRS AFL MOS MSC		5315.4 3658 239		-	1084.9 556 29 Aug 2005			0 0
200-27-255 (972550) Airframe	Sb 200-27-255 - Flight Controls (ATA 27) - Aileron and Elevator Disconnect Cable - Prevention of Excessive Force During Disconnect Operation	HRS AFL MOS MSC		5086 3519 227.9		-	1314.3 695 31 Jul 2006			0 0
200-27-289 (972890) Airframe	Sb 200-27-289 - Flight Controls (ATA 27) - Rudder Bias System - Heater Blanket Circuit Breaker Replacement	HRS AFL MOS MSC		4787.6 3321 219.3		-	1612.7 893 20 Apr 2007			0 0
200-27-291 (972910) Airframe	Sb 200-27-291 - Flight Controls (ATA 27) Rudder Trim Tab System ROD End Replacement	HRS AFL MOS MSC		4787.6 3321 219.3		-	1612.7 893 18 Apr 2007			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-27-298 (982980) Airframe	Sb 200-27-298 - Flight Controls (ATA 27) - Improved Rudder Trim Actuators and Flexible Shafts Installation	HRS AFL MOS MSC		3904.4 2705 191.9		-	2495.9 1509 30 Jul 2009			0 0
200-27-302 (983020) Airframe	Sb 200-27-302 - Flight Controls (ATA 27) Horizontal Stabilizer Trim System Contactor Replacement	HRS AFL MOS MSC		4787.6 3321 219.1		-	1612.7 893 26 Apr 2007			0 0
200-27-362 (983620) Airframe	Sb 200-27-362 - Flight Controls (ATA 27) - Elevator and Rudder Control Rods In Vertical Stabilizer - Installation Inspection	HRS AFL MOS MSC [End Of Month Item]		3222.2 2168 174		-	3178.1 2046 28 Jan 2011			0 0
200-27-374 (983740) Airframe	Sb 200-27-374 - Flight Controls - (ATA 27) - Aileron and Elevator Systems - Visual Inspection of Centering Spring ROD	HRS AFL MOS MSC		3063.8 2063 170.4		-	3336.5 2151 16 May 2011			0 0
200-27-374 R01 (983741) Airframe Notes: WHEN COMPLYING WITH THIS CODE ALSO COMPLY WITH 993075!!	Sb 200-27-374 R01 - Flight Controls - (ATA 27) - Aileron and Elevator Systems - Visual Inspection of Centering Spring ROD	HRS AFL MOS MSC		3063.8 2063 170.5		-	3336.5 2151 11 May 2011			0 0
200-27-411 (984110) Airframe	Sb 200-27-411 - Flight Controls (ATA 27) - Autopilot, Rudder Servo Motor Cables and Sector - Inspection/Rework	HRS AFL MOS MSC		1884.1 1180 120		-	4516.2 3034 29 Jul 2015			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-27A-230 (990250) Airframe	Sb 200-27A-230 - Flight Controls (ATA 27) Ailerons - Visual Inspection of Aileron Artificial Feel Spring Unit for Proper Lubrication and Application of Dow Corning 55 Grease on the Spring Sleeve and Nut	HRS AFL MOS MSC		3491.8 2388 183.1		- -	2908.5 1826 24 Apr 2010			0 0
200-28-160 (971600) Airframe	Sb 200-28-160 - Fuel (ATA 28) - Fuel Draining - Installation of Fuel System Vent Plenum	HRS AFL DATE MSC		6400.3 4214		- -	0 0			0 0
200-28-205 R01 (972051) Airframe	Sb 200-28-205 R01 - Fuel (ATA 28) - Bladder Fuel Tank - Prevention of Weather Cracking to the Rubber Vent Tubes	HRS AFL MOS MSC		5082.4 3518 227		- -	1317.9 696 29 Aug 2006			0 0
200-28-242 (972420) Airframe	Sb 200-28-242 - Fuel (ATA 28) - APU Fuel Feed System - Fuel Line Installation Improvement AT Sta 14833.00	HRS AFL MOS MSC		5082.4 3518 227		- -	1317.9 696 29 Aug 2006			0 0
200-28-253 (972530) Airframe	Sb 200-28-253 - Fuel (ATA 28) - Indicating-Refuel/Defuel Panel Messages Improvement	HRS AFL MOS MSC		5086 3519 227.4		- -	1314.3 695 15 Aug 2006			0 0
200-28-260 (972600) Airframe	Sb 200-28-260 - Fuel (ATA 28) Bladder (Fuselage) Tank - Rubber Vent Fitting Repair	HRS AFL MOS MSC		5086 3519 227.4		- -	1314.3 695 16 Aug 2006			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
200-28-266	Sb 200-28-266 - Fuel (ATA 28) - Feed Tank - Inspection for Interference Between Fuel Probe Harness and Fuel Tube and Improvement of Clearance	HRS		5086			1314.3			0
		AFL		3519			695			0
		MOS		227.4			15 Aug 2006			
		MSC				-				
(972660)										
Airframe										
200-28-344	Sb 200-28-344 - Fuel (ATA 28) - Right Feed Tank Manifold Clearance Inspection	HRS		4373.4			2026.9			0
		AFL		3044			1170			0
		MOS		204.4			15 Jul 2008			
(983440)		MSC				-				
Airframe										
200-28-344 R01	Sb 200-28-344 R01 - Fuel (ATA 28) - Right Feed Tank Manifold Clearance Inspection	HRS		3904.4			2495.9			0
		AFL		2705			1509			0
		MOS		192.4			16 Jul 2009			
(983441)		MSC				-				
Airframe										
200-28A-130[U]	Sb 200-28A-130 - Fuel on Service Door and In Service Compartment	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		24.5			11 Jul 2023			
		MSC				O/C				
Airframe										
Notes: N/A by aircraft S/N										
200-28A-261	Sb 200-28A-261 - Fuel (ATA 28) - Standby Feed Pump Plugs (3Q1 and 4Q1), Electrical Wiring - Inspection and Repair	HRS		5322.1			1078.2			0
		AFL		3662			552			0
		MOS		239.4			17 Aug 2005			
		MSC				-				
(990290)										
Airframe										
200-28A-315	Sb 200-28A-315 - (ATA 28) Fuel - Right Standby Fuel Pump Connector (4Q1) - Electrical Wiring - Modification	HRS		445.3			5955			0
		AFL		275			3939			0
		MOS		24.5			11 Jul 2023			
(990340)		MSC				-				
Airframe										
Notes: N/A by aircraft S/N										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-29-028 (970280) Airframe	Sb 200-29-028 - Hydraulic Power - Fluid Quantity Measurement System - Upgrade the Fqmc and Hydraulic Reservoir Quantity Transmitters	HRS AFL MOS MSC		6359.3 4199 265.7		- -	41 15 05 Jun 2003			0 0
200-29-152 (971520) Airframe	Sb 200-29-152 - Hydraulic Power (ATA 29) - Hydraulic Line - Sampling Valve Moved from Pressure Line to Return Line	HRS AFL DATE MSC		6400.3 4214		- -	0 0			0 0
200-29-152 R01 (981521) Airframe	Sb 200-29-152 R01 - Hydraulic Power (ATA 29) - Hydraulic Line - Sampling Valve Moved from Pressure Line to Return Line	HRS AFL MOS MSC		5199.2 3585 234.1		- -	1201.1 629 26 Jan 2006			0 0
200-29-189 (971890) Airframe	Sb 200-29-189 - Hydraulic Power (ATA 29) - Hydraulic Line Installation - Installation of New Hydraulic Line Supports AT Sta 14783	HRS AFL MOS MSC		5082.4 3518 227		- -	1317.9 696 29 Aug 2006			0 0
200-29-251 (972510) Airframe	Sb 200-29-251 - Hydraulic Power (ATA 29) Nose Section - Improved Power Brake Valve Housing	HRS AFL MOS MSC		5086 3519 227.9		- -	1314.3 695 31 Jul 2006			0 0
200-29-269 (972690) Airframe	Sb 200-29-269 - Hydraulics (ATA 29) Auxiliary Hydraulic Pump Installation of Time-Delay Relay to Prevent Unnecessary Operation of Auxiliary Hydraulic Pump	HRS AFL DATE MSC		6400.3 4214		- -	0 0			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-29-269 R01 (972691) Airframe	Sb 200-29-269 R01 - Hydraulics (ATA 29) Auxiliary Hydraulic Pump Addition of Time - Delay Relay to Prevent Unnecessary Operation of Auxiliary Hydraulic Pump	HRS AFL DATE MSC	6400.3 4214			-	0 0			0 0
200-29-304 (973040) Airframe	Sb 200-29-304 - Hydraulic Power (ATA 29) - Engine Driven Hydraulic Pump Replacement	HRS AFL MOS MSC	2378.1 1547 144.2			-	4022.2 2667 22 Jul 2013			0 0
200-29-316 (983160) Airframe	Sb 200-29-316 - Hydraulic Power (ATA 29) - Hydraulic Line Clamping Blocks - Replacement	HRS AFL MOS MSC	4732.4 3278 215.5			-	1667.9 936 14 Aug 2007			0 0
200-29-412 (984120) Airframe	Sb 200-29-412 - Hydraulic Power (ATA 29) - Aft Fuselage Environmental Control System (Ecs) Bay, Lhs and Rhs - Replacement of Line Blocks	HRS AFL MOS MSC	1477.9 896 80.4			-	4922.4 3318 16 Nov 2018			0 0
200-29A-292 (990320) Airframe	Sb 200-29A-292 - Hydraulics (ATA 29) Auxiliary Hydraulic Pump - Inspection of Remote Control Circuit Breaker (Rccb) 101C	HRS AFL MOS MSC	5086 3519 228.1			-	1314.3 695 26 Jul 2006			0 0
200-30-135 (971350) Airframe	Sb 200-30-135 - Ice and Rain Protection (ATA 30) - Cockpit Side Windows - Full Electrical Heating Improvement	HRS AFL DATE MSC	6400.3 4214			-	0 0			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-30-221 R01 (972211) Airframe	Sb 200-30-221 R01 - Ice and Rain Protection (ATA 30) Airfoil De-Icing System - Removal of the Left Krueger De-Ice Pressure Switch	HRS AFL MOS MSC		5086 3519 227.9		-	1314.3 695 31 Jul 2006			0 0
200-30-247 (972470) Airframe	Sb 200-30-247 - Ice and Rain Protection (ATA 30) De-Icing System - Removal of Low Pressure Switch P/N 4AS7870019-001	HRS AFL MOS MSC		5315.4 3658 239.1		-	1084.9 556 24 Aug 2005			0 0
Notes: PN: 4AS7870019-001 SN: <NONE>.										
200-30-306 (973060) Airframe	Sb 200-30-306 - Ice and Rain Protection (ATA 30) - De-Icing Ejector Flow Control Valve (Efcv) Heater Blanket Replacement	HRS AFL MOS MSC		4787.6 3321 219.1		-	1612.7 893 26 Apr 2007			0 0
200-30-331 (973310) Airframe	Sb 200-30-331 - Ice and Rain Protection (ATA 30) - Removal of Windshield Wiper System	HRS AFL MOS MSC		4373.4 3044 204.4		-	2026.9 1170 15 Jul 2008			0 0
200-30-331 R01 (973311) Airframe	Sb 200-30-331 R01 - Ice and Rain Protection (ATA 30) - Removal of Windshield Wiper System	HRS AFL MOS MSC		3904.4 2705 192.2		-	2495.9 1509 22 Jul 2009			0 0
200-30-333 (983330) Airframe	Sb 200-30-333 - Ice and Rain Protection (ATA 30) - Windshields and Windows - Replacement of Existing Temperature Controllers With Dual Channel Controllers	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
200-30-376	Sb 200-30-376 - Ice & Rain Protection (ATA 30) - Windshield and Windows Heating System - Window Heat Terminal Board Rework	HRS AFL MOS MSC		3023.6 2026 168.5		-	3376.7 2188 14 Jul 2011			0 0
(983760)										
Airframe										
200-31-178	Sb 200-31-178 - Indicating/Recording Systems (ATA 31) - Overhead Panel - Correct Marking and Wire Connection of the Position and Strobe Light Circuit Breakers	HRS AFL MOS MSC		6400.3 4214 265.7		-	0 0 05 Jun 2003			0 0
(981780)										
Airframe										
200-31-207	Sb 200-31-207 - Indicating / Recording Systems (ATA 31) Overhead Panel - Correction of Circuit Breaker Location	HRS AFL MOS MSC		5082.4 3518 227		-	1317.9 696 29 Aug 2006			0 0
(972070)										
Airframe										
200-31-267	Sb 200-31-267 - Indicating - Engine Indication Crew Alert System (Eicas) Display - Wiring Connection Improvement	HRS AFL MOS MSC		5086 3519 227.9		-	1314.3 695 01 Aug 2006			0 0
(972670)										
Airframe										
200-32-153	Sb 200-32-153 - Landing Gear - (ATA 32) - MLG Trunnion Aft Bearing Nut- Change Tightening and Securing	HRS AFL MOS MSC		6400.3 4214 265.7		-	0 0 05 Jun 2003			0 0
(971530)										
Airframe										
Notes: ACCOMPLISHED AT IAI										
200-32-172	Sb 200-32-172 - Landing Gear (ATA 32) Nose Wheel Steering - Rudder Pedals Steering Potentiometer Cover Screws Replacement	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
(971720)										
Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-32-174 (971740) Airframe	Sb 200-32-174 - Landing Gear (ATA 32) Main Landing Gear - Weight on Wheel (Wow) Switch Adjustment	HRS AFL MOS MSC		6359.3 4199 264.8		-	41 15 03 Jul 2003			0 0
200-32-176 (971760) Airframe	Sb 200-32-176 - Landing Gear - Nose Landing Gear - Steering Potentiometer Harness Inspection and Sealing	HRS AFL MOS MSC		6359.3 4199 265.3		-	41 15 20 Jun 2003			0 0
200-32-222 R01 (972221) Airframe	Sb 200-32-222 R01 - Landing Gear (ATA 32) Nose Wheel Steering - Addition of Drain Holes In the Potentiometer Cover	HRS AFL MOS MSC		5774.3 3906 251.2		-	626 308 21 Aug 2004			0 0
200-32-226 R01 PART A (972262) Airframe	Sb 200-32-226 R01 Part A - Landing Gear - Main Landing Gear Doors - Uplock and Indication Improvement	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
200-32-226 R01 PART B (972263) Airframe	Sb 200-32-226 R01 Part B - Landing Gear - Main Landing Gear Doors - Uplock and Indication Improvement	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
200-32-227 (982270) Airframe	Sb 200-32-227 - Landing Gear - (ATA 32) - Parking Valve - Installation of Check Valve on Parking Valve Return Port	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
200-32-228 R01 (972281) Airframe	Sb 200-32-228 R01 - Landing Gear (ATA 32) Wheels and Brakes - Power Brake Valve Inspection	HRS AFL MOS MSC		5082.4 3518 227		-	1317.9 696 29 Aug 2006			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
200-32-231 (972310) Airframe	Sb 200-32-231 - Landing Gear (ATA 23) Nose Landing Gear - Reclamping of Harnesses Near the Right NLG Trunnion	HRS AFL MOS MSC		5082.4 3518 227		-	1317.9 696 29 Aug 2006			0 0
200-32-252 (982520) Airframe	Sb 200-32-252 - Landing Gear - Wheels and Brakes - Power Brake Valve Inspection	HRS AFL MOS MSC		5315.4 3658 239.1		-	1084.9 556 26 Aug 2005			0 0 Aircraft Braking System Corp
Notes: PN: 6006883-4 SN: <NONE>.										
200-32-256 (972560) Airframe	Sb 200-32-256 - Landing Gear (ATA 32) - Main Landing Gear Outboard Door - Doors Reinforcement	HRS AFL MOS MSC		5086 3519 227.4		-	1314.3 695 16 Aug 2006			0 0
200-32-314 (983140) Airframe	Sb 200-32-314 - Landing Gear (ATA 32) - Main Landing Gear - Inspection of Wheel De-Spin Pressures	HRS AFL MOS MSC		4704 3259 214.3		-	1696.3 955 19 Sep 2007			0 0
200-32-317 R02 (973172) Airframe	Sb 200-32-317 R02 - Landing Gear (ATA 32) - Replacement of Brake Assembly Attachment Hardware	HRS AFL MOS MSC [End Of Month Item]		4417.5 3074 206.7		-	1982.8 1140 06 May 2008			0 0
200-32-321 (973210) Airframe	Sb 200-32-321 - Landing Gear (ATA 32) - Power Brake Valve - Installation of Lockwired Threaded Plugs	HRS AFL MOS MSC		4373.4 3044 204.6		-	2026.9 1170 10 Jul 2008			0 0
Notes: N/A DUE TO PBU P/N APPLICABILITY.										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-32-334 (983340) Airframe	Sb 200-32-334 - Landing Gear (ATA 32) - Main Landing Gear - Torque of Retraction Actuator ROD End Jam Nut	HRS AFL MOS MSC		4417.5 3074 206.7		-	1982.8 1140 06 May 2008			0 0
200-32-334 R01 (983341) Airframe	Sb 200-32-334 R01 - Landing Gear (ATA 32) - Main Landing Gear - Torque of Retraction Actuator ROD End Jam Nut	HRS AFL MOS MSC		4417.5 3074 206.7		-	1982.8 1140 06 May 2008			0 0
Notes: C/W @ GDAS WESTFIELD WO# SC2019										
200-32-340 (983400) Airframe	Sb 200-32-340 - Landing Gear (ATA 32) - Main Landing Gear Actuators - Inspection	HRS AFL MOS MSC		4373.4 3044 204.6		-	2026.9 1170 10 Jul 2008			0 0
200-32-380 (983800) Airframe	Sb 200-32-380 - Landing Gear - (ATA 32) - Nose Landing Gear (NLG) Actuator - Visual Inspection	HRS AFL MOS MSC		3023.6 2026 168.6		-	3376.7 2188 08 Jul 2011			0 0
200-32-380 R01 (983801) Airframe	Sb 200-32-380 R01 - Landing Gear - (ATA 32) - Nose Landing Gear (NLG) Actuator - Visual Inspection	HRS AFL MOS MSC		2674.9 1776 156.3		-	3725.4 2438 18 Jul 2012			0 0
200-32-384 (983840) Airframe	Sb 200-32-384 - Landing Gear - (ATA 32) - Nose Landing Gear (NLG) and Main Landing Gear (MLG) Connectors - Water Intrusion Inspection and Prevention	HRS AFL MOS MSC		2674.9 1776 156.4		-	3725.4 2438 17 Jul 2012			0 0

ATA U=Custom	Description		UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
Logbook Position	Part Number / HW / MM Ref / Ops Number(s)	Serial Number / SW									
200-32-384 R01	Sb 200-32-384 R01 - Landing Gear - (ATA 32) - Nose Landing Gear (NLG) and Main Landing Gear (MLG) Connectors - Water Intrusion Inspection and Prevention		HRS AFL MOS MSC	2378.1 1547 144.3			- -	4022.2 2667 19 Jul 2013			0 0
(983841)											
Airframe											
200-32-389	Sb 200-32-389 - Landing Gear (ATA 32) - Brake Assembly - Brake Wear Indicator Pin - Detailed Inspection / Modification		HRS AFL MOS MSC	6400.3 4214 165.3			- -	0 0 20 Oct 2011			0 0
(983890)											
Airframe											
200-32-389 R01	Sb 200-32-389 R01 - Landing Gear (ATA 32) - Brake Assembly - Brake Wear Indicator Pin - Detailed Inspection / Modification		HRS AFL MOS MSC	2865.6 1913 163.2			- -	3534.7 2301 23 Dec 2011			0 0
(983891)											
Airframe											
Notes: S/B 200-32-389R1 LANDING GEAR BRAKE ASSEMBLY, BRAKE WEAR INDICATOR PIN, DETAILED INSPECTION/MODIFICATION C/W. ALL FOUR BRAKE ASSEMBLIES BRAKE WEAR INDICATOR PIN CUT TO LENGTH SPECIFIED IN STEP 6 OF PAGE 4. NO FURTHER ACTION REQUIRED. I/A/W G200 S/B 2											
200-32-397	Sb 200-32-397 - Landing Gear (ATA 32) - Extension and Retraction - NLG Actuator - Inspection of ROD End Securing Washer		HRS AFL MOS MSC	6400.3 4214 142.4			- -	0 0 16 Sep 2013			0 0
(983970)											
Airframe											
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
200-32-397 R01	Sb 200-32-397 R01 - Landing Gear (ATA 32) - Extension and Retraction - NLG Actuator - Inspection of ROD End Securing Washer		HRS AFL MOS MSC	2354.9 1528 141.7			- -	4045.4 2686 07 Oct 2013			0 0
(983971)											
Airframe											
Notes: S/B 200-32-397 R1 LANDING GEAR EXTENSION & RETRACTION INSPECTION OF ROD END SECURING WASHER IS COMPLIED WITH. WASHER WAS BENT UPON INITIAL INSPECTION. SEALANT PR-1750B2 WAS APPLIED. NO FURTHER ACTION REQUIRED.											

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-32-417 (984170) Airframe	Sb 200-32-417 - Landing Gear (ATA 32) - Main Landing Gear (MLG) - Indication Harness Repair and Rerouting	HRS AFL MOS MSC		1363.9 834 69.9		-	5036.4 3380 01 Oct 2019			0 0
200-32A-125 R1U Airframe	Sb 200-32A-125 R1 - Mkg Hyd Actuator Check for Leakage and Scratches	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Notes: N/A by aircraft S/N										
200-33-268 R01 (972681) Airframe	Sb 200-33-268 R01 - Lights (ATA 33) - Wing Position Lights - Replace Existing Wing Position Lights and Lens With New Led Light Assemblies (Honeywell)	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
200-33-273 (972730) Airframe	Sb 200-33-273 - Lights (ATA 33) - Landing Light - Mounting and Cooling Improvement	HRS AFL MOS MSC		6400.3 4214 204.8		-	0 0 02 Jul 2008			0 0
200-33-273 R01 (972731) Airframe	Sb 200-33-273 R01 - Lights (ATA 33) - Landing Light - Mounting and Cooling Improvement	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
200-34-022 R02 (970222) Airframe	Sb 200-34-022 R02 - Navigation - Reduced Vertical Separation Minimum (RVSM) Requirements	HRS AFL MOS MSC		6359.3 4199 265.7		-	41 15 05 Jun 2003			0 0
Notes: STC ICA GA22801A068										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
200-34-166	Sb 200-34-166 - Navigation (ATA 34) Stall Protection and Q-Feel Computer (Spqc) - Software Upgrade		HRS AFL MOS MSC		5315.4 3658 239		-	1084.9 556 29 Aug 2005			0 0
(971660)											
Airframe											
200-34-191	Sb 200-34-191 - Navigation (ATA 34) - Flight Management Computer (FMC-6000) and Electronic Flight Display (Efd-4077) Rockwell Collins Software Update		HRS AFL MOS MSC		6061.3 4043 258		-	339 171 27 Jan 2004			0 0
(971910)											
Airframe											
200-34-223	Sb 200-34-223 - Navigation (ATA 34) AIR Data Computer (ADC-850C) - Incorporation of Rockwell Collins Service Bulletins No.63 Revision 4 and No. 517 Revision 2		HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
(972230)											
Airframe											
200-34-223 R01	Sb 200-34-223 R01 - Navigation (ATA 34) AIR Data Computer (ADC-850C) - Incorporation of Rockwell Collins Service Bulletins No.63 Revision 4 and No. 517 Revision 2		HRS AFL MOS MSC		5774.3 3906 251.2		-	626 308 21 Aug 2004			0 0
(972231)											
Airframe											
200-34-258 R01 PART A	Sb 200-34-258 R01 Part A - Navigation (ATA 34) Flight Management System (FMS - 6100) - Replace the Existing Dual Flight Management Computers (FMC 6000) P/N 822 -0868-046 With P/N 822-0868-073 (Software and Performance Data Base Updated)		HRS AFL MOS MSC		5081.4 3518 227		-	1318.9 696 28 Aug 2006			0 0
(972581)											
Airframe											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
200-34-258 R01 PART B (972582) Airframe	Sb 200-34-258 R01 Part B - Navigation (ATA 34) Flight Management System (FMS - 6100) - Replace the Existing Dual Flight Management Computers (FMC 6000) P/N 822 -0868-046 With P/N 822-0868-073 (Software and Performance Data Base Updated)		HRS AFL MOS MSC		4487.1 3123 208.6		- -	1913.2 1091 10 Mar 2008			0 0
200-34-287 PART A (972870) Airframe	Sb 200-34-287 Part A - Navigation (ATA 34) - Flight Management System (FMS-6100) - Vspeed Data Base (Vdb) Update		HRS AFL MOS MSC		4787.6 3321 219.1		- -	1612.7 893 26 Apr 2007			0 0
200-34-287 PART B (972871) Airframe	Sb 200-34-287 Part B - Navigation (ATA 34) - Flight Management System (FMS-6100) - Vspeed Data Base (Vdb) Update		HRS AFL MOS MSC		4787.6 3321 219.1		- -	1612.7 893 26 Apr 2007			0 0
200-34-335 R01 (973351) Airframe	Sb 200-34-335 R01 - Navigation (ATA 34) - Electronic Flight Display (Efd) - Reversionary Software Dataload Upgrade		HRS AFL MOS MSC		4417.5 3074 206.6		- -	1982.8 1140 08 May 2008			0 0
200-34-353 (983530) Airframe	Sb 200-34-353 - Navigation (ATA 24) - Pitot Probes - Inspection of Left and Right Pitot Probe Connectors		HRS AFL MOS MSC		3222.2 2168 174		- -	3178.1 2046 27 Jan 2011			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-34-381 (983810) Airframe	Sb 200-34-381 - Navigation - (ATA 34) - Flight Management System (FMS - 6100) - Vspeed Database (Vdb) Update	HRS AFL MOS MSC		6400.3 4214 144.2		-	0 0 22 Jul 2013			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
200-34-381 R01 (983811) Airframe	Sb 200-34-381 R01 - Navigation - (ATA 34) - Flight Management System (FMS - 6100) - Vspeed Database (Vdb) Update	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
200-34-388 (983880) Airframe	Sb 200-34-388 - Navigation - (ATA 34) - Flight Management System (FMS - 6100) - Vspeed Database (Vdb) Reversion	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
200-34-402 (984020) Airframe	Sb 200-34-402 - Navigation (ATA 34) - Independent Position Determining - Traffic Alert and Collision Avoidance (TCAS) - Transceiver Ttr-920 or Ttr-4000 Upgrade to 7.1 Version	HRS AFL DATE MSC		223.7 141 423 d		-	6176.6 4073 31 May 2024			0 0
200-34-409 (984090) Airframe	Sb 200-34-409 - Navigation (ATA 34) - Flight Management System (FMS-6100) - Vspeed Data Base (Vdb) Update	HRS AFL MOS MSC		1477.9 896 80		-	4922.4 3318 27 Nov 2018			0 0
200-34-410 (984100) Airframe	Sb 200-34-410 - Navigation (ATA 34) - Flight Management System (FMS - 6100) - Vspeed Data Base (Vdb) Update	HRS AFL MOS MSC		1732.7 1064 95.6		-	4667.6 3150 09 Aug 2017			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-34-428 (984280) Airframe	Sb 200-34-428 - Sb 200-34-428 - Navigation - GPS-4000S No. 1 and No. 2 Replacement P/N 822-2189-100 With P/N 822-2189-101	HRS AFL MOS MSC		581 366 28.6		-	5819.3 3848 10 Mar 2023			0 0
200-35-392 (983920) Airframe	Sb 200-35-392 - Oxygen - (ATA 35) - Passenger Oxygen Drop Box Flexible Hoses - Interference With Electrical Harness - Inspection/Rework	HRS AFL MOS MSC		6400.3 4214 154.7		-	0 0 06 Sep 2012			0 0
200-35-392 R01 (983921) Airframe	Sb 200-35-392 R01 - Oxygen - (ATA 35) - Passenger Oxygen Drop Box Flexible Hoses - Interference With Electrical Harness - Inspection/Rework	HRS AFL MOS MSC		2378.1 1547 144.3		-	4022.2 2667 19 Jul 2013			0 0
200-35-396 (983960) Airframe	Sb 200-35-396 - Oxygen (ATA 35) - Oxygen System - Inspection Decay Check	HRS AFL MOS MSC		6400.3 4214 147.2		-	0 0 22 Apr 2013			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
200-35-396 R01 (983961) Airframe	Sb 200-35-396 R01 - Oxygen (ATA 35) - Oxygen System - Inspection Decay Check	HRS AFL MOS MSC		2378.1 1547 144.3		-	4022.2 2667 19 Jul 2013			0 0
200-35-401 (984010) Airframe	Sb 200-35-401 - Oxygen (ATA 35) - Replacement - Oxygen System Flexible Hoses, P/N O2C20T1	HRS AFL MOS MSC		2143.4 1363 131.7		96 -	4256.9 2851 06 Aug 2014			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-35A-202 R01 PART B (990211) Airframe	Sb 200-35A-202 R01 Part B - Oxygen (ATA 35) Pilot/Copilot Oxygen Mask Stowage Box - Supply Line Inspection and Replacement	HRS AFL MOS MSC		6061.3 4043 258		-	339 171 27 Jan 2004			0 0
200-35A-208 (990240) Airframe	Sb 200-35A-208 - Oxygen (ATA 35) Passenger Oxygen System - Improve Flow Capacity	HRS AFL MOS MSC		5774.3 3906 251.2		-	626 308 21 Aug 2004			0 0
200-35A-234 (990260) Airframe	Sb 200-35A-234 - Oxygen (ATA 35) Flight Compartment - Replacement of Hydraflow Flexible Oxygen Hoses	HRS AFL MOS MSC		5774.3 3906 251.1		-	626 308 25 Aug 2004			0 0
200-38-162 (971620) Airframe	Sb 200-38-162 - Water / Waste (ATA 38) - Potable Water-Water Service Wiring Change	HRS AFL MOS MSC		5774.3 3906 251.3		-	626 308 18 Aug 2004			0 0
200-38-167 (971670) Airframe	Sb 200-38-167 - Water/Waste (ATA 38) Potable Water and Drain Systems - Insulation of Ribbon Heaters and Thermal Cut-Off Switches	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
200-38-310 PART A (973100) Airframe	Sb 200-38-310 Part A - Water and Waste (ATA 38) - Replacement of Galley/Lavatory Water Heater	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
200-38-310 PART B (973101) Airframe	Sb 200-38-310 Part B - Water and Waste (ATA 38) - Replacement of Galley/Lavatory Water Heater	HRS AFL DATE MSC		6400.3 4214		- 	0 0			0 0
200-38-391 (983910) Airframe	Sb 200-38-391 - Water/Waste - (ATA 38) - Potable Water Tank - Installation of Drip Pan Assembly	HRS AFL DATE MSC		6400.3 4214		- 	0 0			0 0
200-45-338 (983380) Airframe	Sb 200-45-338 - Central Maintenance Computer (ATA 45) - Replacement, Relocation and Unification of Engine Data Recorder Switches (Pilot Manual Request Buttons)	HRS AFL DATE MSC		6400.3 4214		- 	0 0			0 0
200-49-030 R02 (970302) Airframe	Sb 200-49-030 R02 - Auxiliary Power (ATA 49) - Installation of Auxiliary Power Unit and APU Engine Control Unit	HRS AFL MOS MSC		6400.3 4214 203.9		- 	0 0 31 Jul 2008			0 0
200-49-030 R03 (970303) Airframe Notes: THIS CODE HAS BEEN CANCELLED.	Sb 200-49-030 R03 - Auxiliary Power (ATA 49) - Installation of Auxiliary Power Unit and APU Engine Control Unit	HRS AFL MOS MSC		6400.3 4214 137.1		- 	0 0 24 Feb 2014			0 0
200-49-030 R04 (970304) Airframe	Sb 200-49-030 R04 - Auxiliary Power (ATA 49) - Installation of Auxiliary Power Unit and APU Engine Control Unit	HRS AFL DATE MSC		6400.3 4214		- 	0 0			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
200-49-132 R02	Sb 200-49-132 R02 - Airborne Auxiliary Power (ATA 49) - APU Flex Bleed AIR Duct	HRS AFL MOS MSC		6359.3 4199 264.8		-	41 15 03 Jul 2003			0 0
(971322) Airframe										
200-49-157	Sb 200-49-157 - Airborne Auxiliary Power (ATA 49) - APU - Electrical Cables Additional Attachment	HRS AFL MOS MSC		6359.3 4199 267.6		-	41 15 10 Apr 2003			0 0
(971570) Airframe										
200-49-322	Sb 200-49-322 - Auxiliary Power (ATA 49) - Installation of Thales Starter-Generator	HRS AFL MOS MSC		6400.3 4214 203.9		-	0 0 31 Jul 2008			0 0
(973220) Airframe										
200-49-322 R01	Sb 200-49-322 R01 - Auxiliary Power (ATA 49) - Installation of Thales Starter-Generator	HRS AFL MOS MSC		6400.3 4214 137.1		-	0 0 24 Feb 2014			0 0
(983221) Airframe										
Notes: THIS CODE HAS BEEN CANCELLED.										
200-49-322 R02	Sb 200-49-322 R02 - Auxiliary Power (ATA 49) - Installation of Thales Starter-Generator	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
(983222) Airframe										
200-49A-219	Sb 200-49A-219 - Airborne Auxiliary Power (ATA 49) Fuel Shutoff Valve - Inspection and Leak Check of APU Fuel Shutoff Valve, P/N 692545-18	HRS AFL MOS MSC		6061.3 4043 258.2		-	339 171 22 Jan 2004			0 0
(990230) Airframe										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-51-366 (983660) Airframe	Sb 200-51-366 - Standard Practices and Structures (ATA 51) - Attachment Hardware - Nut Replacement	HRS AFL MOS MSC				- -				0 0
Notes: N/A by aircraft S/N										
200-51-372 R01 PART B (983722) Airframe	Sb 200-51-372 R01 Part B - Standard Practices and Structures - (ATA 51) - Attachment Hardware - Nut Inspection and Replacement In Select Non Critical Installations	HRS AFL DATE MSC	6400.3 4214			- -	0 0			0 0
200-52-040^{U} Airframe	Sb 200-52-040 - Rework Brackets on Emergency Exit Door	HRS AFL MOS MSC	445.3 275 24.5			- -	5955 3939 11 Jul 2023			0 0
Notes: N/A by aircraft S/N										
200-52-100 (981000) Airframe	Sb 200-52-100 - Doors(ATA52) - Passenger/Crew - New Drian Holes Are provided to Improve Drainage from Door	HRS AFL MOS MSC	6359.3 4199 265.7			- -	41 15 05 Jun 2003			0 0
200-52-155 (971550) Airframe	Sb 200-52-155 - Doors (ATA 52) Service Doors - Door Inspection and Improvement	HRS AFL MOS MSC	5774.3 3906 251.3			- -	626 308 19 Aug 2004			0 0
200-52-185 (971850) Airframe	Sb 200-52-185 - Doors (ATA 52) - Passenger/Crew Door Prevention of Interference and Installation of Improved Airspring Attach Brackets	HRS AFL MOS MSC	5315.4 3658 238.5			- -	1084.9 556 12 Sep 2005			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-52-197 (981970) Airframe	Sb 200-52-197 - Doors (ATA 52) Passenger/Crew Door Improve Passenger Cabin Door Drainage and Insulation	HRS AFL MOS MSC		5315.4 3658 238.5		-	1084.9 556 12 Sep 2005			0 0
200-52-201 (972010) Airframe	Sb 200-52-201 - Doors (ATA 52) Passenger / Crew Door - Prevent Door Lift Cable and Capstan Reel Cover from Chafing	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
200-52-210 (972100) Airframe	Sb 200-52-210 - Doors (ATA 52) Passenger/Crew Door - Reverse Installation of the Telescopic Tie ROD	HRS AFL MOS MSC		5774.3 3906 251.3		-	626 308 20 Aug 2004			0 0
200-52-224 (972240) Airframe	Sb 200-52-224 - Doors (ATA 52) - Passenger/Crew Door - Improvement of the Door Interlock Mechanism	HRS AFL MOS MSC		5086 3519 228.2		-	1314.3 695 21 Jul 2006			0 0
200-52-236 (972360) Airframe	Sb 200-52-236 - Doors (ATA 52) APU Inlet Door - Lower Connection Redesign	HRS AFL MOS MSC		5315.4 3658 238.7		-	1084.9 556 06 Sep 2005			0 0
200-52-239 (972390) Airframe	Sb 200-52-239 - Doors (ATA 52)- Passenger/Crew Door - Addition of Louvered Covers Over the Open Holes on Both Sides of the Passenger/Crew Door	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
200-52-239 R01 (972391) Airframe	Sb 200-52-239 R01 - Doors (ATA 52)- Passenger/Crew Door - Addition of Louvered Covers Over the Open Holes on Both Sides of the Passenger/Crew Door	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
200-52-329 PART A (983290) Airframe	Sb 200-52-329 Part A - Doors (ATA 52) - Main Entry Door (Med) - Improvements	HRS AFL MOS MSC		3023.6 2026 168.3		-	3376.7 2188 18 Jul 2011			0 0
200-52-329 PART B (983291) Airframe	Sb 200-52-329 Part B - Doors (ATA 52) - Main Entry Door (Med) - Improvements	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
200-52-329 PART C (983292) Airframe	Sb 200-52-329 Part C - Doors (ATA 52) - Main Entry Door (Med) - Improvements	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
200-52-369 (983690) Airframe	Sb 200-52-369 - Doors (ATA 52) - Baggage Compartment Door - Replacement of Existing Folding Step Quick Release Pin	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
200-52-398 (983980) Airframe	Sb 200-52-398 - Doors (ATA 52) - Main Entrance Door (Med) - Telescopic ROD - Quick Release Pin Installation	HRS AFL MOS MSC		6400.3 4214 140.1		-	0 0 25 Nov 2013			0 0

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
200-52-398 R01	Sb 200-52-398 R01 - Doors (ATA 52) - Main Entrance Door (Med) - Telescopic ROD - Quick Release Pin Installation	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
(983981)										
Airframe										
200-52-403	Sb 200-52-403 - Doors (ATA 52) - APU Door - Door Latch Installation Inspection	HRS AFL MOS MSC		1915.4 1200 121.9		-	4484.9 3014 31 May 2015			0 0
(984030)										
Airframe										
Notes: S/B 200-52-403 APU DOOR- DOOR LATCH INSTALLATION INSPECTION C/W. RESULTS ARE ANNOTATED ON PAGE 7.										
200-52-404	Sb 200-52-404 - Doors - Main Entrance Door (Med) - Telescopic ROD - Quick Release Pin Installation	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
(984040)										
Airframe										
200-52-405	Sb 200-52-405 - Doors (ATA 52) - Passenger / Crew Door - Main Axle Assembly, Hinges and Bearings Improvement	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
(984050)										
Airframe										
200-53-039 R01	Sb 200-53-039 R01 - Fuselage (ATA 53) - Baggage Compartment Bulkhead - Install Reinforcing Stiffeners AT Bulkhead Sta 14783	HRS AFL MOS MSC		6359.3 4199 265.7		-	41 15 05 Jun 2003			0 0
(970391)										
Airframe										
200-53-061	Sb 200-53-061 - Fuselage (ATA 53) Forward Fuselage - Install Forward Pressure Bulkhead Stiffener and Canopy Lower Sill Reinforcements	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
(970610)										
Airframe										
Notes: N/A by aircraft S/N										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
200-53-075	Sb 200-53-075 - Fuselage (ATA 53) Pressure Bulkhead - Reinforcement of Pressure Bulkhead AT Fuselage Station 12260		HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
(970750)											
Airframe											
Notes: N/A by aircraft S/N											
200-53-081	Sb 200-53-081 - Fuselage (ATA 53) Baggage Compartment Bulkhead - Replace Centeral Splice and Modify Shroud Structural Joint AT Fuselage Station 13220		HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
(970810)											
Airframe											
Notes: N/A by aircraft S/N											
200-53-105[U]	Sb 200-53-105 - Nose Landing Gear Surface Finish		HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Airframe											
Notes: N/A by aircraft S/N											
200-53-108	Sb 200-53-108 - Fuselage (ATA 53) - Cockpit Floor - Replacement of Fasteners In Cockpit Floor		HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
(971080)											
Airframe											
Notes: N/A by aircraft S/N											
200-53-116	Sb 200-53-116 - Fuselage (ATA 53) Upper Skin Assembly - Material Change of Upper Longeron Splice		HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
(971160)											
Airframe											
Notes: N/A by aircraft S/N											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
200-53-121 (971210) Airframe	Sb 200-53-121 - Fuselage (ATA 53) - Canopy - Canopy Lower Sill Reinforcement	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Notes: N/A by aircraft S/N										
200-53-127 PART A (981270) Airframe	Sb 200-53-127 Part A - Fuselage - Drainage - Drainage Improvement and Prevention of Fluid Penetration Into Service Compartment	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
Notes: N/A by aircraft S/N										
200-53-127 PART B (981271) Airframe	Sb 200-53-127 Part B - Fuselage - Drainage - Drainage Improvement and Prevention of Fluid Penetration Into Service Compartment	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
Notes: N/A by aircraft S/N										
200-53-128 (981280) Airframe	Sb 200-53-128 - Fuselage - (ATA 53) Forward Cross Assembly - Inspection of Forward Engine Spar Assembly AT Sta 582.00 (14783)	HRS AFL MOS MSC		6359.3 4199 267.6		- -	41 15 10 Apr 2003			0 0
200-53-144 (971440) Airframe	Sb 200-53-144 - Fuselage (ATA 53) - Aft Pressure Bulkhead Station 12260 Rework	HRS AFL DATE [HRS: +200]		4214		7000**	0	7000	7200	0 0
200-53-144 R01 (971441) Airframe	Sb 200-53-144 R01 - (ATA 53) - Fuselage - Aft Pressure Bulkhead Sta 12260 - Rework	HRS AFL MOS MSC [HRS: +200]		6400.3 4214		7000**	0 0	7000	7200	0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
200-53-220 (982200) Airframe	Sb 200-53-220 - Fuselage (ATA 53) Forward Engine Mount - Adapter Plate Washer Replacement and Sealing	HRS AFL MOS MSC		6061.3 4043 258.2		-	339 171 22 Jan 2004			0 0
200-53-271 (982710) Airframe	Sb 200-53-271 - Fuselage (ATA 53) - Aft Fuselage - Aft Lower Skin Diverter Installation Reinforcement	HRS AFL MOS		5122.2 3542 231.4			1278.1 672 16 Apr 2006			0 0
200-53-271 R01 PART A (972711) Airframe	Sb 200-53-271 R01 Part A - Fuselage (ATA 53) - Aft Fuselage - Aft Lower Skin Diverter Installation Reinforcement	HRS AFL MOS MSC		4732.4 3278 215.5		-	1667.9 936 13 Aug 2007			0 0
200-53-271 R01 PART B (972712) Airframe	Sb 200-53-271 R01 Part B - Fuselage (ATA 53) - Aft Fuselage - Aft Lower Skin Diverter Installation Reinforcement	HRS AFL MOS MSC		4732.4 3278 215.5		-	1667.9 936 13 Aug 2007			0 0
200-53-400 (984000) Airframe	Sb 200-53-400 - Fuselage (ATA 53) - Canopy Assembly - Inspection and Repair	HRS AFL MOS MSC		2143.4 1363 131.7		-	4256.9 2851 06 Aug 2014			0 0
200-53-406 (984060) Airframe	Sb 200-53-406 - Fuselage (ATA 53) - Fuselage - Cabin Drains - Beneath Cabin Floorboard - Inspection / Check	HRS AFL MOS MSC		1884.1 1180 120		-	4516.2 3034 28 Jul 2015			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-53-414 (984140) Airframe	Sb 200-53-414 - Fuselage (ATA 53) - Ecs Compartment Fwd Bulkhead - Inspection and Repair of Overheated Fasteners	HRS AFL MOS MSC		1477.9 896 80.7		--	4922.4 3318 05 Nov 2018			0 0
200-53A-270 (990300) Airframe	Sb 200-53A-270 - Fuselage (ATA 53) - Main Frame - Aft Lower Skin Inspection of Diverter Rivet Holes for Cracks	HRS AFL MOS MSC		5253.3 3619 236.3		--	1147 595 18 Nov 2005			0 0
200-55-042[U] Airframe Notes: N/A by aircraft S/N	Sb 200-55-042 - Passivated Washers on Vert. Stab Attach Fittings	HRS AFL MOS MSC		445.3 275 24.5		--	5955 3939 11 Jul 2023			0 0
200-55-175 (971750) Airframe	Sb 200-55-175 - Stabilizers (ATA 55) - Horizontal Stabizer - Elevator Actuator Drainage Improvement	HRS AFL MOS MSC		5082.4 3518 227		--	1317.9 696 29 Aug 2006			0 0
200-55-188 (971880) Airframe	Sb 200-55-188 - Stabilizers (ATA 55) - Vertical Stabilizer - Installation of Drain Hole In Vertical Stabilizer Rib 4	HRS AFL MOS MSC		5082.4 3518 227		--	1317.9 696 29 Aug 2006			0 0
200-55-243 (972430) Airframe	Sb 200-55-243 - Stabilizers (ATA 55) - Elevator - Actuator ROD End Fairing Removal	HRS AFL MOS MSC		5315.4 3658 239		--	1084.9 556 29 Aug 2005			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
200-55-276 (972760) Airframe	Sb 200-55-276 - Stabilizers (ATA 55) - Installation of New Symmetric Fairing on Both Sides of the Rudder Contour	HRS AFL MOS MSC		5082.4 3518 227		-	1317.9 696 29 Aug 2006			0 0
200-55-309 (973090) Airframe	Sb 200-55-309 - Stabilizers (ATA 55) - Horizontal Stabilizer - Rubber CAST Fairing Installation	HRS AFL MOS MSC		4373.4 3044 204.4		-	2026.9 1170 15 Jul 2008			0 0
200-55-413 (984130) Airframe	Sb 200-55-413 - Stabilizers (ATA 55) - Horizontal / Vertical Stabilizers - Attachment Fittings - Inspection for Migrating Bushings and Repair	HRS AFL MOS MSC		6400.3 4214 105.7		-	0 0 06 Oct 2016			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
200-55-413 R01 (984131) Airframe	Sb 200-55-413 R01 - Stabilizers (ATA 55) - Horizontal / Vertical Stabilizers - Attachment Fittings - Inspection for Migrating Bushings and Repair	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
200-55-423 (984230) Airframe	Sb 200-55-423 - Stabilizers (ATA 55) - Vertical Stabilizer - Rear Attachment Bolts Torque Values Inspection and Repair	HRS AFL MOS MSC		6400.3 4214 96		-	0 0 28 Jul 2017			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
200-57-161 R01 PART A[U] (981612) Airframe	Asb 200-57A-161 R1 PT A - Wing Flap ACT Fairing	HRS AFL MOS MSC		6359.3 4199 267.6		-	41 15 10 Apr 2003			0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
200-57-233 (972330) Airframe	Sb 200-57-233 - Wings (ATA 57) Slat Actuator No. 3 Access Door - Inspection and Replacement of Fasteners		HRS AFL MOS MSC		5082.4 3518 227		-	1317.9 696 29 Aug 2006			0 0
200-57-244 (972440) Airframe	Sb 200-57-244 - Wings (ATA 57) - Outboard Flap RAIL No. 6- Replace Existing Stoppers, P/N 25W1900004-007, With P/N 4AS1900004-005		HRS AFL MOS MSC		5086 3519 227.9		-	1314.3 695 31 Jul 2006			0 0
200-57-264 (972640) Airframe	Sb 200-57-264 - Wings (ATA 57) - Slat Assembly - Replacement of Inner Skin Doubler With A Thicker Doubler		HRS AFL MOS MSC		5086 3519 227.9		-	1314.3 695 31 Jul 2006			0 0
200-57-283 (982830) Airframe	Sb 200-57-283 - Wings (ATA 57) - Upper Skin - Increase Clearance Between Hydraulic Tubes and Wing Upper Skin Stringers Near Rib 12		HRS AFL MOS MSC		4935.4 3426 223.5		-	1464.9 788 14 Dec 2006			0 0
200-57-323 (983230) Airframe	Sb 200-57-323 - Wings (ATA 57) - Wing Lower Skin Rib 2 - Replacement of Titanium Fasteners With Stainless Steel Fasteners		HRS AFL MOS MSC		6400.3 4214 197.5		-	0 0 11 Feb 2009			0 0
200-57-323 R01 (983231) Airframe	Sb 200-57-323 R01 - Wings (ATA 57) - Wing Lower Skin Rib 2 - Replacement of Titanium Fasteners With Stainless Steel Fasteners		HRS AFL MOS MSC		6400.3 4214 191.7		-	0 0 07 Aug 2009			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-57-323 R02 (983232) Airframe	Sb 200-57-323 R02 - Wings (ATA 57) - Wing Lower Skin Rib 2 - Replacement of Titanium Fasteners With Stainless Steel Fasteners	HRS AFL MOS MSC		3904.4 2705 191.7		- -	2495.9 1509 07 Aug 2009			0 0
200-57-341 (983410) Airframe	Sb 200-57-341 - Wings (ATA 57) - Wing Position and Strobe Lights Power Supply - Reinforcement of Mounting Brackets	HRS AFL MOS MSC		3904.4 2705 192.2		- -	2495.9 1509 22 Jul 2009			0 0
200-57-342 (983420) Airframe	Sb 200-57-342 - Wings (ATA 57) - Installation of Aerodynamic Disturbance Forward of Naca Scoop	HRS AFL DATE MSC		6400.3 4214		- -	0 0			0 0
200-57-345 (983450) Airframe	Sb 200-57-345 - Wings (ATA 57) - Jack Pads - Replacement of Screw Fasteners With Bolt Fasteners and Adding of Dummy Plate and Placard	HRS AFL MOS MSC		3904.4 2705 192.4		- -	2495.9 1509 16 Jul 2009			0 0
200-57-365 (983650) Airframe	Sb 200-57-365 - Wings (ATA 57) - Left and Right No. 1 and No. 2 AIR Brakes - Inspection for Interference Between AIR Brake Hinge Fittings and Wing Trailing Edge	HRS AFL MOS MSC		3491.8 2388 183.1		- -	2908.5 1826 24 Apr 2010			0 0
200-57-371 (983710) Airframe	Sb 200-57-371 - Wings - (ATA 57) - Slat Assembly - Addition of Cover Plates on the Slat RAIL Tongues	HRS AFL DATE MSC		6400.3 4214		- -	0 0			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-57-386 (983860) Airframe	Sb 200-57-386 - Wings - (ATA 57) - Wing Trailing Edge - Inboard Trailing Edge (T/E) Fairing Cone Assembly Clearance Inspection	HRS AFL MOS MSC		2674.9 1776 156.4		- -	3725.4 2438 17 Jul 2012			0 0
200-57-386 R01 (983861) Airframe	Sb 200-57-386 R01 - Wings - (ATA 57) - Wing Trailing Edge - Inboard Trailing Edge (T/E) Fairing Cone Assembly Clearance Inspection	HRS AFL DATE MSC		6400.3 4214		- -	0 0			0 0
200-57-426 (984260) Airframe	Sb 200-57-426 - Sb 200-57-426 - Wings (ATA 57) - Flaps - Fairing Seal Inspection Repair	HRS AFL MOS MSC		757.3 461 31.9		- -	5643 3753 30 Nov 2022			0 0
200-57-426 R02 (989426) Airframe Notes: FAA 2023-06-09	Sb 200-57-426 R02 - Sb 200-57-426 R02 - Wings (ATA 57) - Flaps - Fairing Seal Repair	HRS AFL MOS MSC		445.3 275 25.9		- -	5955 3939 31 May 2023			0 0
200-57-426 R02 (LHS RIB #03) (984265) Airframe Notes: FAA 2023-06-09	Sb 200-57-426 R02 (Lhs Rib #03) -	HRS AFL MOS MSC		445.3 275 25.9		- -	5955 3939 31 May 2023			0 0
200-57-426 R02 (LHS RIB #11) (984266) Airframe Notes: FAA 2023-06-09	Sb 200-57-426 R02 (Lhs Rib #11) -	HRS AFL MOS MSC		445.3 275 25.9		- -	5955 3939 31 May 2023			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-57-426 R02 (RHS RIB #03) (984267) Airframe	Sb 200-57-426 R02 (Rhs Rib #03) -	HRS AFL MOS MSC		445.3 275 25.9		--	5955 3939 31 May 2023			0 0
Notes: FAA 2023-06-09										
200-57-426 R02 (RHS RIB #11) (984268) Airframe	Sb 200-57-426 R02 (Rhs Rib #11) -	HRS AFL MOS MSC		445.3 275 25.9		--	5955 3939 31 May 2023			0 0
Notes: FAA 2023-06-09										
200-57A-161 R01 PART B (981613) Airframe	Sb 200-57A-161 R01 Part B - Wing - (ATA 57) Flap Actuator Fairing - Inspection and Repair Flap Actuator Fairing Bonding to Lower Wing Skin	HRS AFL MOS MSC		6359.3 4199 267.6		--	41 15 10 Apr 2003			0 0
200-71-173 (981730) Airframe	Sb 200-71-173 - Power Plant (ATA 71) - Forward Engine Mount - Engine Mount Yoke Attachment Bolts and Nuts Replacement	HRS AFL MOS MSC		6061.3 4043 258		--	339 171 27 Jan 2004			0 0
200-71-245 (982450) Airframe	Sb 200-71-245 - Power Plant (ATA 71) - Drain and Vent System - Inspection of Generator Drive PAD Drain Tube and Installation of Additional Clamp	HRS AFL MOS MSC		5017.3 3475 225.1		--	1383 739 24 Oct 2006			0 0
200-71-262 (972620) Airframe	Sb 200-71-262 - Power Plant (ATA 71) - Channel B Main Wire Harness - Installation of Protective Tape	HRS AFL MOS MSC		5315.4 3658 239.1		--	1084.9 556 26 Aug 2005			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-71-394 (983940) Airframe	Sb 200-71-394 - Power Plant - (ATA 71) - Lower Engine Access Cowling - Hold Open ROD Bracket - Interference With Hydraulic Tube	HRS AFL DATE MSC		6400.3 4214		--	0 0			0 0
200-72-339 (983390) Airframe	Sb 200-72-339 - Engine (ATA 72) - Engine Maintenance MODE Switches (Emms) - Replacement and Relocation	HRS AFL DATE MSC		6400.3 4214		--	0 0			0 0
200-73-134 R02 (971342) Airframe Notes: C/W	Sb 200-73-134 R02 - Engine Fuel and Control (ATA 73) - Electronic Engine Control (Eec) Revised Software	HRS AFL MOS MSC		5683.3 3859 249.4		--	717 355 15 Oct 2004			0 0
200-73-290 LH (972900) Airframe	Sb 200-73-290 Lh - Engine Fuel and Control (ATA 73) - Replacement of Engine Fuel Low Pressure Switch	HRS AFL MOS MSC		4787.6 3321 219		--	1612.7 893 27 Apr 2007			0 0
200-73-290 RH (972901) Airframe	Sb 200-73-290 Rh - Engine Fuel and Control (ATA 73) - Replacement of Engine Fuel Low Pressure Switch	HRS AFL MOS MSC		4787.6 3321 219.1		--	1612.7 893 26 Apr 2007			0 0
200-75-305 (973050) Airframe	Sb 200-75-305 - Engine AIR (ATA 75) - Engine Anti Ice and Pressure Regulating Shutoff Valve (Prsov) Inspection	HRS AFL MOS MSC		4787.6 3321 219.1		--	1612.7 893 26 Apr 2007			0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
200-77-238 PART A (982380) Airframe	Sb 200-77-238 Part A - Engine Indicating (ATA 77) - Interrogation of the Mdc/Edu for Suppressed N1 Major Fault Codes and Replacement of N1 Speed Sensors		HRS AFL MOS MSC		5416.6 3711 241.5		- -	983.7 503 13 Jun 2005			0 0
Notes: C/W BY GULFSTREAM 8/24/2002											
200-77-238 PART B (982381) Airframe	Sb 200-77-238 Part B - Engine Indicating (ATA 77) - Interrogation of the Mdc/Edu for Suppressed N1 Major Fault Codes and Replacement of N1 Speed Sensors		HRS AFL MOS MSC		5774.3 3906 251.1		- -	626 308 24 Aug 2004			0 0
200-78-096 (970960) Airframe	Sb 200-78-096 - Exhaust (ATA 78) Thrust Reverser - Installation of Time Delay Relays to Eliminate Uncommanded RE-Stow of Thrust Reversers During Landing		HRS AFL MOS MSC		445.3 275 24.5		- -	5955 3939 11 Jul 2023			0 0
Notes: N/A by aircraft S/N											
200-78-123 (971230) Airframe	Sb 200-78-123 - Exhaust (ATA 78) - Thrust Reverser - Replacement of the Thrust Reverser Lockout Device (Nordam Service Bulletin PW306AG 78-3)		HRS AFL DATE MSC		6400.3 4214		- -	0 0			0 0
Notes: MOD 7244											
200-78-272 (972720) Airframe	Sb 200-78-272 - Exhaust (ATA 78) Thrust Reverser - Electrical Lock-Out of Thrust Reverser		HRS AFL DATE MSC		6400.3 4214		- -	0 0			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-78-278 (972780) Airframe	Sb 200-78-278 - Exhaust (ATA 78) - Thrust Reverser - Replacement of Thrust Reverser Electrical Harnesses	HRS AFL MOS MSC		5086 3519 227.4		-	1314.3 695 15 Aug 2006			0 0
200-78-279 (972790) Airframe	Sb 200-78-279 - Exhaust (ATA 78) - Thrust Reverser Replacement of the Outer Stang Fairings	HRS AFL DATE MSC		6400.3 4214		-	0 0			0 0
200-78-297 (972970) Airframe	Sb 200-78-297 - Exhaust (ATA 78) - Thrust Reverser - Isolation Valve Replacement	HRS AFL MOS MSC		757.3 461 31.9		-	5643 3753 30 Nov 2022			0 0
200-78-303 R01 (973031) Airframe	Sb 200-78-303 R01 - Exhaust (ATA 78) - Thrust Reverser - Secondary Latch Actuator Modification	HRS AFL MOS MSC		4373.4 3044 204.5		-	2026.9 1170 14 Jul 2008			0 0
200-78-337 (973370) Airframe	Sb 200-78-337 - Exhaust (ATA 78) - Thrust Reverser - Secondary Latch Actuator - Replace Blocker Plate Spring	HRS AFL MOS MSC		4373.4 3044 204.5		-	2026.9 1170 14 Jul 2008			0 0
200-78-337 R01 (973371) Airframe	Sb 200-78-337 R01 - Exhaust (ATA 78) - Thrust Reverser - Secondary Latch Actuator - Replace Blocker Plate Spring	HRS AFL MOS MSC		4373.4 3044 204.5		-	2026.9 1170 14 Jul 2008			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
200-79-184 R01 (971841) Airframe	Sb 200-79-184 R01 - Oil (ATA 79) - Oil Filler Neck Assembly Installation of Oil Filler Neck Assembly With Integral Non-Escape Valve	HRS AFL DATE MSC		6400.3 4214		--	0 0			0 0
25[U] (345224) Airframe	Rockwell Collins Sb 25 Navigation Circuit Card Assembly A2 - Extend Battery Life Capability	HRS AFL MOS MSC		6400.3 4214		--	0 0			0 0
941400 (941400) Airframe	Sb 941400 - FAA NEXTGEN Program Mandate: ADS-B Out Compliance	HRS AFL MOS MSC		1363.9 834 69.8		--	5036.4 3380 03 Oct 2019			0 0
Notes: COMPLIED WITH CMP G200 941400 FAA NEXTGEN PROGRAM MANDATE: ADS-B OUT COMPLIANCE.FOR CUSTOMER NOTIFICATION ONLY										
941401 (941401) Airframe	Sb 941401 - FAA NEXTGEN Program Mandate: FANS 1/A+ Compliance	HRS AFL MOS MSC		1363.9 834 69.8		--	5036.4 3380 03 Oct 2019			0 0
Notes: COMPLIED WITH CMP G200 941401 FAA NEXTGEN PROGRAM MANDATE: FANS 1/A+ COMPLIANCEFOR CUSTOMER NOTIFICATION ONLY										
GALAXY-23-070 (970700) Airframe	Sb Galaxy-23-070 - Communications - Very High Frequency (VHF) - Upgrade to VHF-422D Communication System Extended Frequency Range and 8.33 KHZ Channel Spacing	HRS AFL MOS MSC		6400.3 4214 267.6		--	0 0 10 Apr 2003			0 0
GALAXY-25-090 (970900) Airframe	Sb Galaxy-25-090 - Equipment/Furnishings - Cockpit - Cockpit Interior Improvements	HRS AFL MOS MSC		6359.3 4199 267.6		--	41 15 10 Apr 2003			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
GALAXY-31-097 (970970) Airframe	Sb Galaxy-31-097 - Indicating/Recording Systems - Flight Data Recorder - Installation of 57 Parameters Flight Data Recorder (FDR) System	HRS AFL MOS MSC		6359.3 4199 267.6		-	41 15 10 Apr 2003			0 0
GALAXY-53-084 (970840) Airframe	Sb Galaxy-53-084 - Fuselage - Rudder Control ARM Mounting Brackets - Rework Rudder Control ARM Intercostal Structure AT Sta 15025	HRS AFL MOS MSC		6359.3 4199 265.7		-	41 15 05 Jun 2003			0 0
GALAXY-53A-054 (980540) Airframe	Sb Galaxy-53A-054 - Fuselage - OMEGA Assembly - Check and Replace OMEGA Assemblies to Improve Electrical Grounding of Power Cables	HRS AFL MOS MSC		6359.3 4199 265.7		-	41 15 05 Jun 2003			0 0
GTCP36-GTE1267 (951267) Airframe	Sb GTCP36-GTE1267 - Sb GTCP36-GTE1267	HRS AFL MOS MSC		1878.6 1175 119.3		-	4521.7 3039 20 Aug 2015			0 0
Notes: PN: GTCP-36-150(IAI) SN: P-171.										
SB 200-53-061A^{U} Airframe	Sb 200-53-061A - Frame Reinforcement AT FS 156.8 - Canopy L & R Side	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Notes: N/A by Aircraft S/N										
SB 200-53-061B^{U} Airframe	Sb 200-53-061B - Reinforcement of Fwd Pressure Bulkhead Stiffeners	HRS AFL MOS MSC		445.3 275 24.5		-	5955 3939 11 Jul 2023			0 0
Notes: N/A by Aircraft S/N										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
ST01433WI-D (901059) Airframe	STC ST01433WI-D - Modification of A Rockwell Collins GPS	HRS AFL MOS MSC		1363.9 834 70.6		--	5036.4 3380 08 Sep 2019			0 0
ST01833WI (901061) Airframe	STC ST01833WI - Installation of Rockwell Collins Global Positioning System (GPS)	HRS AFL MOS MSC		1363.9 834 70.6		--	5036.4 3380 08 Sep 2019			0 0
ST03424CH (901058) Airframe	STC ST03424CH - Certification of ADS-B System With Rockwell Collins Tdr-94 / 94D Transponders	HRS AFL MOS MSC		1363.9 834 69.4		--	5036.4 3380 17 Oct 2019			0 0
ST04177AT (901402) Airframe	STC ST04177AT - Talon Aerospace Led Replacement	HRS AFL MOS MSC		1363.9 834 69		--	5036.4 3380 27 Oct 2019			0 0
Notes: LED LANDING A TAXI LIGHTS PER TALON AEROSPACE DOCUMENT #INS-728-01 REV 3..										
ST09749SC (901007) Airframe	STC ST09749SC - Jumpseat	HRS AFL MOS MSC		6359.3 4199 265.7		--	41 15 05 Jun 2003			0 0
ST09809SC-D (901019) Airframe	STC ST09809SC-D - Emergency Light Cabin	HRS AFL MOS MSC		6359.3 4199 265.7		--	41 15 05 Jun 2003			0 0
ST09848SC (901012) Airframe	STC ST09848SC - Side Face Divan	HRS AFL MOS MSC		6371.3 4204 267.6		--	29 10 09 Apr 2003			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
ST09851SC (901016) Airframe	STC ST09851SC - Interior	HRS AFL MOS MSC		6371.3 4204 267.6		--	29 10 09 Apr 2003			0 0
ST10016SC-D (901020) Airframe	STC ST10016SC-D - Cabin Single Seat Installation (B/E Aerospace)	HRS AFL MOS MSC		6359.3 4199 265.7		--	41 15 05 Jun 2003			0 0
ST10020SC-D (901022) Airframe	STC ST10020SC-D - Erda Cabin Seats (Double Seats)	HRS AFL MOS MSC		6359.3 4199 265.7		--	41 15 05 Jun 2003			0 0
ST10760SC-D (901048) Airframe	STC ST10760SC-D - Installation of Aircell Axxess Ii Airborne SATCOM System	HRS AFL MOS MSC		 168.3		--	 19 Jul 2011			0 0
SIAE - APU/Engine Service Information/Bulletins										
118-2014 R01 (791215) Engine	No. 1 Engine - Si 118-2014 R01 - Oil Sampling Program	HRS ENC MOS [HRS: +50/-50]		117.2 71 5.6		500	3064.5 1906 10 Feb 2025	3564.5	3614.5	0 0
118-2014 R01 (791216) (791215) Engine	No. 2 Engine - Si 118-2014 R01 - Oil Sampling Program	HRS ENC MOS [HRS: +25/-25]		117.2 71 5.6		250	2699.1 1719 10 Feb 2025	2949.1	2974.1	0 0
36-49-8119 R03 (958121) APU	APU - Sb 36-49-8119 R03 - Airborne Auxiliary Power - Gas Turbine Engine - Rotating Group Balance Procedure on 36-150[F] [R] [W] [Bd] [Cx] [Dd] [Hh] [Rr] [F2M] and [Iai] Auxiliary Power Units (Apus).	HRS APUS MOS MSC		1750 1669 140.5		--	1485 4 14 Nov 2013			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
36-49-8190 R02 (957203) APU	APU - Sb 36-49-8190 R02 - Airborne Auxiliary Power - Gas Turbine Engine - Group Balance and Assembly of the Power Section for 36-150[lai] APU, Pn 3800710-1, -2, and -3	HRS APUS DATE MSC		3235 1673		- 	0 0			0 0
36-49-8361 R02 (953612) APU	APU - Sb 36-49-8361 R02 - Sb 36-49-8361 R02 - Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet Pn M24243/6A401H With Rivet Pn 627-504-9209 on 36-150 Engine Models	HRS APUS DATE MSC				- 				0 0
36-49-8361 R03 (953613) APU	APU - Sb 36-49-8361 R03 - Sb 36-49-8361 R03 - Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet Pn M24243/6A401H With Rivet Pn 627-504-9209 on 36-150 Engine Models	HRS APUS DATE MSC				- 				0 0
36-49-8361 R04 (953614) APU	APU - Sb 36-49-8361 R04 - Sb 36-49-8361 R04 - Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet Pn M24243/6A401H With Rivet Pn 627-504-9209 on 36-150 Engine Models	HRS APUS DATE MSC				- 				0 0
3822101-49-8148 R03 (958148) APU	APU - Sb 3822101-49-8148 R03 - Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, Pn 3822101-1, on Multiple Apus	HRS APUS DATE MSC		3235 1673		 DUE**	0 0			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
3880021-49-8206 (958206) APU	APU - Sb 3880021-49-8206 - Airborne Auxiliary Power - Gas Turbine Engine - Rework Fluid Pressure Regulating Valve, Pn 3880021-2, -5 Thru -17 to Pn 70721587-4, on Multiple Apus (Export Controlled)	HRS APUS DATE MSC		3235 1673		- 	0 0			0 0
3882730-49-7974 R02 (957975) APU	APU - Sb 3882730-49-7974 R02 - Main Fuel Control Unit (Fcu) - Install Fuel Flow Deflector, Pn 70720001-1 on the Fuel Control Differential Pressure (Delta P) Sleeve as Required AT Next APU Shop Visit. Check Nameplate for Latest Change Number Prior to the Fcu Removal	HRS APUS DATE MSC		3235 1673		- 	0 0			0 0
49-7933 R04 (957934) APU	APU - Sb 49-7933 R04 - Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils.	HRS APUS DATE MSC		3235 1673		- 	0 0			0 0
49-7933 R05 (957935) APU	APU - Sb 49-7933 R05 - Airborne Auxiliary Power Unit (APU) Oil - General - Approved Oils	HRS APUS DATE MSC		3235 1673		- 	0 0			0 0
49-7933 R06 (957936) APU	APU - Sb 49-7933 R06 - Airborne Auxiliary Power Unit (APU) Oil - General - Approved Oils	HRS APUS DATE MSC		3235 1673		- 	0 0			0 0
49-7933 R08 (957938) APU	APU - Sb 49-7933 R08 - Airborne Auxiliary Power Unit (APU) Oil - General - Approved Oils	HRS APUS DATE MSC		3235 1673		- 	0 0			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
49-7997 R04 (957997) APU	APU - Sb 49-7997 R04 - Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines	HRS APUS MOS MSC		1981 1669 174		-	1254 4 29 Jan 2011			0 0
Notes: UPDATED FROM APU LOGBOOK FOR P-103										
49-8252 (958252) APU	APU - Sb 49-8252 - Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial Apus	HRS APUS DATE MSC		3235 1673		-	0 0			0 0
APU-49 R11 APU	APU - Sil APU-49 R11 - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus)	HRS APUS DATE MSC				-				0 0
APU-49 R13 (950012) APU	APU - Sil APU-49 R13 - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus), Service Information Letter (Recommended)	HRS APUS DATE MSC				-				0 0
APU-49 R14 (959549) APU	APU - Sil APU-49 R14 - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus), Service Information Letter	HRS APUS MOS MSC		9 7 1.3		O/C	3226 1666 20 Jun 2025			0 0
Notes: Soap sample recommended to resample in 100 hrs. Due 3312 hrs. See attached Soap report for details										

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
GTCP36-49-7717 R02 (957717) APU	APU - Sb GTCP36-49-7717 R02 - Airborne Auxiliary Power - Gas Turbine Engine - Inspection/Replacement of the Coupling Clamp, Part No. 234-511-9059, T-Bolt (Fuel Control to Lube Pump Flanges)	HRS APUS MOS MSC		1854 1673 151.2		- -	1381 0 21 Dec 2012			0 0
GTCP36-49-7969 R01 (957969) APU	APU - Sb GTCP36-49-7969 R01 - Airborne Auxiliary Power - Gas Turbine Engine - Replace the Plain Seal (Compressor Seal), Part Number 3616650-1 With Plain Seal (Compressor Seal), Part Number 3616650-3	HRS APUS MOS MSC		2003 1669 175.6		- -	1232 4 08 Dec 2010			0 0
Notes: PN: 3616650-3 SN: <NONE>. UPDATED FROM APU LOGBOOK FOR P-103										
GTCP36-49-8191 (958191) APU	APU - Sb GTCP36-49-8191 - Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine 36-150[Iai] Pn 3800710-1 and Pn 3800710-2 for Incorporation of Improved Compressor Carbon Seal and Related Components	HRS APUS MOS MSC		3235 1673 77.6		- -	0 0 08 Feb 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
GTCP36-49-8191 R01 (958192) APU	APU - Sb GTCP36-49-8191 R01 - Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine 36-150[Iai], Pn 3800710-1 and Pn 3800710-2, for Incorporation of Improved Compressor Carbon Seal and Related Components	HRS APUS DATE MSC		3235 1673		- - -	0 0			0 0
GTCP36-49-8318 (958318) APU	APU - Sb GTCP36-49-8318 - Airborne Auxiliary Power - Gas Turbine Engine - Replace Fuel Nozzle Assembly, Pn 3610004-3 and 3610004-4 With Fuel Nozzle Assembly Pn 3610004-5 and 3610004-6 on Affected APU Models	HRS APUS DATE MSC				- - -				0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
GTCP36-49-8332 (950201) APU	APU - Sb GTCP36-49-8332 - Airborne Auxiliary Power - Gas Turbine Engine - Replace Ring Gear, Pn 3860331-1 With Ring Gear Pn 3860331-2 on Affected APU Models	HRS APUS DATE MSC				- 				0 0
GTCP36-49-A7758 R02 (957582) APU	APU - Sb GTCP36-49-A7758 R02 - Airborne Auxiliary Power - Gas Turbine Engine - One Time Inspection/Leak Check on the Down Stream Side of the APU Fuel Shutoff Valve, Part No. 692545-17	HRS APUS MOS MSC	2739 1673 243.7			- 	496 0 06 Apr 2005			0 0
PW300-72-25005 (880051) Engine	No. 1 Engine - Sb PW300-72-25005 - Conv of PW306B to PW306A Engine Model	HRS ENC DATE MSC	3181.7 1977			- 	0 0			0 0
PW300-72-25005 (890051) (880051) Engine	No. 2 Engine - Sb PW300-72-25005 - Conv of PW306B to PW306A Engine Model	HRS ENC MOS MSC	2765.2 1771 227.8			- 	51.1 19 04 Aug 2006			0 0
PW300-72-25034 (880340) Engine	No. 1 Engine - Sb PW300-72-25034 - Inspection of Engine Diagnostic Unit (Edu)	HRS ENC DATE MSC	3181.7 1977			- 	0 0			0 0
PW300-72-25034 (890340) (880340) Engine	No. 2 Engine - Sb PW300-72-25034 - Inspection of Engine Diagnostic Unit (Edu)	HRS ENC DATE MSC				- 				0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
PW300-72-25035 (880350) Engine	No. 1 Engine - Sb PW300-72-25035 - Inspection/Replacement of Engine Diagnostic Units (Edu)	HRS ENC DATE MSC		3181.7 1977		-	0 0			0 0
PW300-72-25035 (890350) (880350) Engine	No. 2 Engine - Sb PW300-72-25035 - Inspection/Replacement of Engine Diagnostic Units (Edu)	HRS ENC DATE MSC				-				0 0
PW300-72-25054 R02 (890542) (880542) Engine	No. 2 Engine - Sb PW300-72-25054 R02 - Replacement of Front Core Electrical Wiring Harness	HRS ENC MOS MSC		2770.8 1774 227.9		-	45.5 16 31 Jul 2006			0 0
PW300-72-25062 R01 (890621) (880621) Engine	No. 2 Engine - Sb PW300-72-25062 R01 - Introduction of Shield for Starter Drive Shaft	HRS ENC MOS MSC		2770.8 1774 227.9		-	45.5 16 31 Jul 2006			0 0
PW300-72-25065 (880650) Engine	No. 1 Engine - Sb PW300-72-25065 - Replacement of Low Pressure Turbine (Lpt) Fourth Stage Vane Assembly	HRS ENC DATE MSC		3181.7 1977		-	0 0			0 0
PW300-72-25086 R01 (890861) (880861) Engine	No. 2 Engine - Sb PW300-72-25086 R01 - Replacement/Modification of Compressor Bleed Solenoid Valve	HRS ENC MOS MSC		2770.8 1774 227.9		-	45.5 16 31 Jul 2006			0 0
PW300-72-25095 (890950) (880950) Engine	No. 2 Engine - Sb PW300-72-25095 - Introduction of High Pressure Compressor (Hpc) With Tie-Shaft	HRS ENC MOS MSC		2770.8 1774 227.9		-	45.5 16 31 Jul 2006			0 0

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
PW300-72-25104	No. 1 Engine - Sb PW300-72-25104 - Replacement of High Pressure Turbine Vane Assembly		HRS ENC MOS MSC		3181.7 1977 216.7			0 0 07 Jul 2007			0 0
(881040) Engine							-				
Notes: N/A BY S/N. APPLIES TO S/N PCE-CC0093 AND PRIOR.											
PW300-72-25104 (891040)	No. 2 Engine - Sb PW300-72-25104 - Replacement of High Pressure Turbine Vane Assembly		HRS ENC MOS MSC		2770.8 1774 227.9			45.5 16 31 Jul 2006			0 0
(881040) Engine							-				
PW300-72-25105	No. 1 Engine - Sb PW300-72-25105 - Inspection/Replacement of Electronic Engine Control (Eec)		HRS ENC MOS MSC		3181.7 1977 137.1			0 0 24 Feb 2014			0 0
(881050) Engine							-				
Notes: THIS CODE HAS BEEN CANCELLED.											
PW300-72-25105 R01	No. 1 Engine - Sb PW300-72-25105 R01 - Inspection/Replacement of Electronic Engine Control (Eec)		HRS ENC DATE MSC		3181.7 1977			0 0			0 0
(881051) Engine							-				
PW300-72-25108 (891080)	No. 2 Engine - Sb PW300-72-25108 - Turbofan Engine - Combustion Chamber Liner With Separate Inner and Outer Liner Assemblies - Introduction of		HRS ENC MOS MSC		2770.8 1774 227.9			45.5 16 31 Jul 2006			0 0
(881080) Engine							-				
PW300-72-25111	No. 1 Engine - Sb PW300-72-25111 - Replacement of Skid Base Components for Engine Shipping Container		HRS ENC DATE MSC		3181.7 1977			0 0			0 0
(881110) Engine							-				

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW300-72-25130	No. 1 Engine - Sb PW300-72-25130 - Investigation of Overspeed Solenoid Valve Installed on Hydromechanical Unit (Hmu)		HRS ENC MOS MSC		3181.7 1977 137.1		-	0 0 24 Feb 2014			0 0
(881300)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED.											
PW300-72-25130 R01	No. 1 Engine - Sb PW300-72-25130 R01 - Investigation of Overspeed Solenoid Valve Installed on Hydromechanical Unit (Hmu)		HRS ENC MOS MSC		3181.7 1977 137.1		-	0 0 24 Feb 2014			0 0
(881301)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED.											
PW300-72-25130 R02	No. 1 Engine - Sb PW300-72-25130 R02 - Investigation of Overspeed Solenoid Valve Installed on Hydromechanical Unit (Hmu)		HRS ENC DATE MSC		3181.7 1977		-	0 0			0 0
(881302)											
Engine											
PW300-72-25134	No. 1 Engine - Sb PW300-72-25134 - Inspection/Replacement of Electronic Engine Control (Eec)		HRS ENC MOS MSC		3181.7 1977 137.1		-	0 0 24 Feb 2014			0 0
(881340)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED.											
PW300-72-25134 R01	No. 1 Engine - Sb PW300-72-25134 R01 - Inspection/Replacement of Electronic Engine Control (Eec)		HRS ENC MOS MSC		3181.7 1977 137.1		-	0 0 24 Feb 2014			0 0
(881341)											
Engine											
Notes: THIS CODE HAS BEEN CANCELLED.											

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW300-72-25134 R02 (881342) Engine	No. 1 Engine - Sb PW300-72-25134 R02 - Inspection/Replacement of Electronic Engine Control (Eec)		HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25152 (891520) (881520) Engine	No. 2 Engine - Sb PW300-72-25152 - Replacement of Compressor Bleed Solenoid Valve		HRS ENC MOS MSC		2770.8 1774 227.9		- - -	45.5 16 31 Jul 2006			0 0
PW300-72-25156 R01 (891561) (881561) Engine	No. 2 Engine - Sb PW300-72-25156 R01 - Replacement/Modification of High Pressure Turbine (Hpt) Vane Assembly		HRS ENC MOS MSC		2770.8 1774 227.9		- - -	45.5 16 31 Jul 2006			0 0
PW300-72-25161 (881610) Engine	No. 1 Engine - Sb PW300-72-25161 - Inspection/Replacement of Electronic Engine Control (Eec)		HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25177 R03 (891773) (881773) Engine	No. 2 Engine - Sb PW300-72-25177 R03 - Second Stage High Pressure Compressor Rotor - Replacement/Modification of		HRS ENC MOS MSC		2770.8 1774 227.9		- - -	45.5 16 31 Jul 2006			0 0
PW300-72-25200 (892000) (882000) Engine	No. 2 Engine - Sb PW300-72-25200 - Replacement of First Stage High Pressure Turbine (Hpt) Blades		HRS ENC MOS MSC		2770.8 1774 227.9		- - -	45.5 16 31 Jul 2006			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
PW300-72-25201 R01 PART (A) (882012) Engine	No. 1 Engine - Sb PW300-72-25201 R01 Part (A) - Combustion Chamber Case Drain Valve	HRS ENC DATE MSC				- -				0 0
PW300-72-25201 R01 PART (A) (892012) (882012) Engine	No. 2 Engine - Sb PW300-72-25201 R01 Part (A) - Combustion Chamber Case Drain Valve	HRS ENC DATE MSC				- -				0 0
PW300-72-25201 R01 PART (B) (882013) Engine	No. 1 Engine - Sb PW300-72-25201 R01 Part (B) - Combustion Chamber Case Drain Valve	HRS ENC DATE MSC				- -				0 0
PW300-72-25201 R01 PART (B) (892013) (882013) Engine	No. 2 Engine - Sb PW300-72-25201 R01 Part (B) - Combustion Chamber Case Drain Valve	HRS ENC DATE MSC				- -				0 0
PW300-72-25203 R04 (892034) (882034) Engine	No. 2 Engine - Sb PW300-72-25203 R04 - Electronic Engine Control (Eec) - Revised Software	HRS ENC MOS MSC	2770.8 1774 227.9			- -	45.5 16 31 Jul 2006			0 0
PW300-72-25206 (892060) (882060) Engine	No. 2 Engine - Sb PW300-72-25206 - Introduction of Redefined Oil Filler Neck Assembly	HRS ENC MOS MSC	2770.8 1774 227.9			- -	45.5 16 31 Jul 2006			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
PW300-72-25219 (892190) (882190) Engine	No. 2 Engine - Sb PW300-72-25219 - Replacement/Introduction of Redefined Oil Filler Neck Assembly	HRS ENC MOS MSC		2770.8 1774 227.9		- -	45.5 16 31 Jul 2006			0 0
PW300-72-25222 (892220) (882220) Engine	No. 2 Engine - Sb PW300-72-25222 - Replacement of Motive Flow Valve	HRS ENC MOS MSC		2770.8 1774 227.9		- -	45.5 16 31 Jul 2006			0 0
PW300-72-25223 (882230) Engine	No. 1 Engine - Sb PW300-72-25223 - Replacement of Ecology Tank Washers	HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25228 R02 (882282) Engine Notes: N/A BY S/N. APPLIES TO S/N PCE-CC0201 AND PRIOR.	No. 1 Engine - Sb PW300-72-25228 R02 - Replacement of N1 Rotational Speed Sensor	HRS ENC MOS MSC		3181.7 1977 216.7		- -	0 0 07 Jul 2007			0 0
PW300-72-25228 R02 (892282) (882282) Engine	No. 2 Engine - Sb PW300-72-25228 R02 - Replacement of N1 Rotational Speed Sensor	HRS ENC MOS MSC		2770.8 1774 227.9		- -	45.5 16 31 Jul 2006			0 0
PW300-72-25229 R03 (882293) Engine Notes: N/A BY S/N. APPLIES TO S/N PCE-CC0256 AND PRIOR.	No. 1 Engine - Sb PW300-72-25229 R03 - Replacement/Modification Hpt Disk Balancing Assembly and Vane Assembly	HRS ENC MOS MSC		3181.7 1977 216.7		- -	0 0 07 Jul 2007			0 0

ATA U=Custom Logbook Position	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
PW300-72-25229 R03 (892293) (882293) Engine	No. 2 Engine - Sb PW300-72-25229 R03 - Replacement/Modification Hpt Disk Balancing Assembly and Vane Assembly	HRS ENC MOS MSC		2770.8 1774 227.9		-	45.5 16 31 Jul 2006			0 0
PW300-72-25229 R05 (84535) Engine	No. 1 Engine - Sb PW300-72-25229 R05 - Replacement/Modification of Hpt Disk Balancing Assembly and Vane Assembly	HRS ENC DATE MSC				-				0 0
PW300-72-25229 R05 (84535) Engine	No. 2 Engine - Sb PW300-72-25229 R05 - Replacement/Modification of Hpt Disk Balancing Assembly and Vane Assembly	HRS ENC DATE MSC				-				0 0
PW300-72-25230 R02 (882302) Engine	No. 1 Engine - Sb PW300-72-25230 R02 - Turbofan Engine-Replacement of Hpt Disk Balancing Assembly	HRS ENC MOS MSC		3181.7 1977 216.7		-	0 0 07 Jul 2007			0 0
Notes: N/A BY S/N. APPLIES TO S/N PCE-CC0256 AND PRIOR.										
PW300-72-25230 R02 (892302) (882302) Engine	No. 2 Engine - Sb PW300-72-25230 R02 - Turbofan Engine-Replacement of Hpt Disk Balancing Assembly	HRS ENC MOS MSC		2770.8 1774 227.9		-	45.5 16 31 Jul 2006			0 0
PW300-72-25236 (882360) Engine	No. 1 Engine - Sb PW300-72-25236 - Replacement of N1 Rotational Speed Sensor	HRS ENC DATE MSC		3181.7 1977		-	0 0			0 0

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
PW300-72-25247 R01 (892471) (882471) Engine	No. 2 Engine - Sb PW300-72-25247 R01 - Replacement/Modification of Engine Diagnostic Unit (Edu)		HRS ENC MOS MSC		2770.8 1774 227.9		-	45.5 16 31 Jul 2006			0 0
PW300-72-25249 (882490) Engine	No. 1 Engine - Sb PW300-72-25249 - Modification /Replacement of Fuel Nozzles		HRS ENC MOS MSC		3181.7 1977 137.1		-	0 0 24 Feb 2014			0 0
Notes: THIS CODE HAS BEEN CANCELLED.											
PW300-72-25249 R01 (882491) Engine	No. 1 Engine - Sb PW300-72-25249 R01 - Modification /Replacement of Fuel Nozzles		HRS ENC DATE MSC		3181.7 1977		-	0 0			0 0
PW300-72-25249 R02 (882492) Engine	No. 1 Engine - Sb PW300-72-25249 R02 - Modification /Replacement of Fuel Nozzles		HRS ENC DATE MSC		3181.7 1977		-	0 0			0 0
PW300-72-25249 R02 (892492) (882492) Engine	No. 2 Engine - Sb PW300-72-25249 R02 - Modification /Replacement of Fuel Nozzles		HRS ENC DATE MSC		2816.3 1790		-	0 0			0 0
PW300-72-25258 (892580) (882580) Engine	No. 2 Engine - Sb PW300-72-25258 - Replacement of Oil Filter Impending Bypass Switch		HRS ENC MOS MSC		2770.8 1774 227.9		-	45.5 16 31 Jul 2006			0 0
PW300-72-25258 R01 (892581) (882581) Engine	No. 2 Engine - Sb PW300-72-25258 R01 - Replacement of Oil Filter Impending Bypass Switch		HRS ENC MOS MSC		2770.8 1774 227.9		-	45.5 16 31 Jul 2006			0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW300-72-25265 R01 (882651) Engine	No. 1 Engine - Sb PW300-72-25265 R01 - Workscope for Low Utilization Inspection		HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25265 R01 (892651) (882651) Engine	No. 2 Engine - Sb PW300-72-25265 R01 - Workscope for Low Utilization Inspection		HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0
PW300-72-25269 (882690) Engine	No. 1 Engine - Sb PW300-72-25269 - Hpt Disk Balancing Assembly - Modification/Replacement of		HRS ENC MOS MSC		3181.7 1977 216.7		- - -	0 0 07 Jul 2007			0 0
Notes: N/A BY S/N. APPLIES TO S/N PCE-CC0270 AND PRIOR.											
PW300-72-25270 R02 (882702) Engine	No. 1 Engine - Sb PW300-72-25270 R02 - Introduction of New Engine Assembly Procedures and Hardware		HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25270 R02 (892702) (882702) Engine	No. 2 Engine - Sb PW300-72-25270 R02 - Introduction of New Engine Assembly Procedures and Hardware		HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0
PW300-72-25273 R04 (892734) (882734) Engine	No. 2 Engine - Sb PW300-72-25273 R04 - Replacement of No. 4 Bearing Carbon Seal and Carrier		HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
PW300-72-25274 R02 (884555) Engine	No. 1 Engine - Sb PW300-72-25274 R02 - Replacement of Upper and Lower Bypass Duct Assemblies, Fuel Nozzle Cover and Exciter Mounting Bracket, Service Bulletin (Category 7)		HRS ENC DATE MSC				- -				0 0
PW300-72-25274 R02 (884555) Engine	No. 2 Engine - Sb PW300-72-25274 R02 - Replacement of Upper and Lower Bypass Duct Assemblies, Fuel Nozzle Cover and Exciter Mounting Bracket, Service Bulletin (Category 7)		HRS ENC DATE MSC				- -				0 0
PW300-72-25278 (892780) (882780) Engine	No. 2 Engine - Sb PW300-72-25278 - Replacement of Bypass Duct Segment Assembly		HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0
PW300-72-25279 (892790) (882790) Engine	No. 2 Engine - Sb PW300-72-25279 - P3 Tube Sensing Assembly - Replacement of		HRS ENC MOS MSC		2816.3 1790 89.3		- -	0 0 19 Feb 2018			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
PW300-72-25279 R01 (892791) (882791) Engine	No. 2 Engine - Sb PW300-72-25279 R01 - Replacement of P3 Tube Sensing Assembly		HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0
Notes: PN: 30B6488-01 SN: <NONE>.											
PW300-72-25279 R02 (884553) Engine	No. 1 Engine - Sb PW300-72-25279 R02 - Replacement of P3 Sensing Tube Assembly, Service Bulletin (Category 3)		HRS ENC MOS MSC				- -				0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW MM Ref Ops Number(s)	SW									Manufacturer Date Type
PW300-72-25279 R02 (894553) (884553) Engine	No. 2 Engine - Sb PW300-72-25279 R02 - Replacement of P3 Sensing Tube Assembly, Service Bulletin (Category 3)		HRS ENC DATE MSC				- -				0 0
PW300-72-25280 (882800) Engine	No. 1 Engine - Sb PW300-72-25280 - Inspection of High Pressure Tubine Retaining Nut		HRS ENC MOS MSC	3181.7 1977 137.1			- - -	0 0 24 Feb 2014			0 0
Notes: THIS CODE HAS BEEN CANCELLED.											
PW300-72-25280 (892800) (882800) Engine	No. 2 Engine - Sb PW300-72-25280 - Inspection of High Pressure Tubine Retaining Nut		HRS ENC MOS MSC	1994 1269 182.6			- - -	822.3 521 10 May 2010			0 0
PW300-72-25280 R01 (882801) Engine	No. 1 Engine - Sb PW300-72-25280 R01 - Inspection of High Pressure Tubine Retaining Nut		HRS ENC DATE MSC				- -				0 0
PW300-72-25282 (892820) (882820) Engine	No. 2 Engine - Sb PW300-72-25282 - Replacement of Intermediate Case Assembly		HRS ENC MOS MSC	1994 1269 182.6			- - -	822.3 521 10 May 2010			0 0
PW300-72-25282 R01 (892821) (882821) Engine	No. 2 Engine - Sb PW300-72-25282 R01 - Replacement of Intermediate Case Assembly		HRS ENC DATE MSC	2816.3 1790			- -	0 0			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
PW300-72-25291 (882910) Engine	No. 1 Engine - Sb PW300-72-25291 - Compressor Bleed Solenoid Valve - Inspection/Replacement of	HRS ENC MOS MSC		3181.7 1977 137.1		-	0 0 24 Feb 2014			0 0
Notes: THIS CODE HAS BEEN CANCELLED.										
PW300-72-25291 R01 (882911) Engine	No. 1 Engine - Sb PW300-72-25291 R01 - Inspection/Replacement of Compressor Bleed Solenoid Valve	HRS ENC DATE MSC		3181.7 1977		-	0 0			0 0
PW300-72-25293 (882930) Engine	No. 1 Engine - Sb PW300-72-25293 - Replacement of Primary Fuel Nozzle	HRS ENC MOS MSC		3181.7 1977 137.1		-	0 0 24 Feb 2014			0 0
Notes: THIS CODE HAS BEEN CANCELLED.										
PW300-72-25293 R02 (882932) Engine	No. 1 Engine - Sb PW300-72-25293 R02 - Replacement of Primary Fuel Nozzle	HRS ENC MOS MSC		3181.7 1977 134.4		-	0 0 15 May 2014			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
PW300-72-25293 R02 (892932) (882932) Engine	No. 2 Engine - Sb PW300-72-25293 R02 - Replacement of Primary Fuel Nozzle	HRS ENC MOS MSC		1775 1151 157.6		-	1041.3 639 08 Jun 2012			0 0
PW300-72-25293 R05 (892935) (882935) Engine	No. 2 Engine - Sb PW300-72-25293 R05 - Replacement of Primary Fuel Nozzle	HRS ENC DATE MSC		2816.3 1790		-	0 0			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
PW300-72-25294 R01 (884540) Engine	No. 1 Engine - Sb PW300-72-25294 R01 - Sb PW300-72-25294 R01 - Replacement of Core Cowl Support Brackets	HRS ENC DATE MSC				- -				0 0
PW300-72-25294 R01 (884540) Engine	No. 2 Engine - Sb PW300-72-25294 R01 - Sb PW300-72-25294 R01 - Replacement of Core Cowl Support Brackets	HRS ENC DATE MSC				- -				0 0
PW300-72-25297 R01 (882971) Engine	No. 1 Engine - Sb PW300-72-25297 R01 - Introduction of Compressor Bleed Solenoid Valve Support Brackets - Superseded	HRS ENC MOS MSC	3181.7 1977 137.1			- -	0 0 24 Feb 2014			0 0
Notes: THIS CODE HAS BEEN CANCELLED.										
PW300-72-25297 R03 (892973) (882973) Engine	No. 2 Engine - Sb PW300-72-25297 R03 - Introduction of Compressor Bleed Solenoid Valve Support Brackets	HRS ENC MOS MSC	2536.5 1616 217.4			- -	279.8 174 16 Jun 2007			0 0
PW300-72-25298 R01 (882981) Engine	No. 1 Engine - Sb PW300-72-25298 R01 - Replacement of Oil Filler Neck Assembly	HRS ENC DATE MSC	3181.7 1977			- -	0 0			0 0
PW300-72-25298 R01 (892981) (882981) Engine	No. 2 Engine - Sb PW300-72-25298 R01 - Replacement of Oil Filler Neck Assembly	HRS ENC DATE MSC	2816.3 1790			- -	0 0			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
PW300-72-25299 (882990) Engine	No. 1 Engine - Sb PW300-72-25299 - Replacement/Modification of Oil Pump Assembly	HRS ENC DATE MSC		3181.7 1977		--	0 0			0 0
PW300-72-25299 (882990) (882990) Engine	No. 2 Engine - Sb PW300-72-25299 - Replacement/Modification of Oil Pump Assembly	HRS ENC DATE MSC		2816.3 1790		--	0 0			0 0
PW300-72-25303 (883030) Engine	No. 1 Engine - Sb PW300-72-25303 - Inspection/Modification of Electronic Engine Control Unit	HRS ENC DATE MSC		3181.7 1977		--	0 0			0 0
PW300-72-25311 R01 (893111) (883111) Engine	No. 2 Engine - Sb PW300-72-25311 R01 - Replacement/Modification of Primary Fuel Nozzle Assembly	HRS ENC DATE MSC		2816.3 1790		--	0 0			0 0
PW300-72-25312 R03 PART A (884537) Engine	No. 1 Engine - Sb PW300-72-25312 R03 Part A - Sb PW300-72-25312 R03 Part A - Conversion of PW306A Build Specification 853 to 1241 or Conversion of PW306C Build Specification 1026 to 1240 (Progressive Maintenance Program)	HRS ENC DATE MSC				--				0 0
PW300-72-25312 R03 PART A (884537) Engine	No. 2 Engine - Sb PW300-72-25312 R03 Part A - Sb PW300-72-25312 R03 Part A - Conversion of PW306A Build Specification 853 to 1241 or Conversion of PW306C Build Specification 1026 to 1240 (Progressive Maintenance Program)	HRS ENC DATE MSC				--				0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
PW300-72-25312 R03 PART B (884538) Engine	No. 1 Engine - Sb PW300-72-25312 R03 Part B - PW300-72-25312 R03 Part B - Conversion of PW306A Build Specification 853 to 1241 or Conversion of PW306C Build Specification 1026 to 1240 (Progressive Maintenance Program)	HRS ENC DATE MSC				- 				0 0
PW300-72-25312 R03 PART B (884538) Engine	No. 2 Engine - Sb PW300-72-25312 R03 Part B - PW300-72-25312 R03 Part B - Conversion of PW306A Build Specification 853 to 1241 or Conversion of PW306C Build Specification 1026 to 1240 (Progressive Maintenance Program)	HRS ENC DATE MSC				- 				0 0
PW300-72-25315 (883150) Engine	No. 1 Engine - Sb PW300-72-25315 - Replacement of Oil Level Sensor	HRS ENC MOS MSC	3181.7 1977 137.1			- 	0 0 24 Feb 2014			0 0
Notes: THIS CODE HAS BEEN CANCELLED.										
PW300-72-25315 R01 (883151) Engine	No. 1 Engine - Sb PW300-72-25315 R01 - Replacement of Oil Level Sensor	HRS ENC DATE MSC	3181.7 1977			- 	0 0			0 0
PW300-72-25318 (883180) Engine	No. 1 Engine - Sb PW300-72-25318 - Introduction of New Fuel/Oil Heat Exchanger (Fohe)	HRS ENC DATE MSC				- 				0 0
PW300-72-25318 R01 (883181) Engine	No. 1 Engine - Sb PW300-72-25318 R01 - Introduction of New Fuel/Oil Heat Exchanger (Fohe)	HRS ENC DATE				3300** 		3300		0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW300-72-25322 R01 (883221) Engine	No. 1 Engine - Sb PW300-72-25322 R01 - Replacement of P3 Sensing Tube Assembly		HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25322 R01 (893221) (883221) Engine	No. 2 Engine - Sb PW300-72-25322 R01 - Replacement of P3 Sensing Tube Assembly		HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0
PW300-72-25326 R01 (883261) Engine	No. 1 Engine - Sb PW300-72-25326 R01 - Replacement of Turbine Exhaust Case Assembly		HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25326 R01 (893261) (883261) Engine	No. 2 Engine - Sb PW300-72-25326 R01 - Replacement of Turbine Exhaust Case Assembly		HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0
PW300-72-25331 R01 (883311) Engine	No. 1 Engine - Sb PW300-72-25331 R01 - Replacement of Fan Hub SET		HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25331 R01 (893311) (883311) Engine	No. 2 Engine - Sb PW300-72-25331 R01 - Replacement of Fan Hub SET		HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0
PW300-72-25332 (883320) Engine	No. 1 Engine - Sb PW300-72-25332 - Replacement/Modification of Fuel Start and Dump Valve		HRS ENC DATE MSC				- -				0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
PW300-72-25345 R01 (884536) Engine	No. 1 Engine - Sb PW300-72-25345 R01 - Replacement of High Pressure Turbine (Hpt) Sleeve Spacer	HRS ENC DATE MSC				- -				0 0
PW300-72-25345 R01 (884536) Engine	No. 2 Engine - Sb PW300-72-25345 R01 - Replacement of High Pressure Turbine (Hpt) Sleeve Spacer	HRS ENC DATE MSC				- -				0 0
PW300-72-25347 R01 (883471) Engine	No. 1 Engine - Sb PW300-72-25347 R01 - Replacement of Starter Generator Drive Spur Gearshaft	HRS ENC DATE MSC	3181.7 1977			- -	0 0			0 0
PW300-72-25347 R01 (893741) (883471) Engine	No. 2 Engine - Sb PW300-72-25347 R01 - Replacement of Starter Generator Drive Spur Gearshaft	HRS ENC MOS MSC	2816.3 1790 120.2			- - -	0 0 21 Jul 2015			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
PW300-72-25348 R01 (883481) Engine	No. 1 Engine - Sb PW300-72-25348 R01 - Replacement of Anti-Icing Tube Assembly	HRS ENC DATE MSC				- -				0 0
PW300-72-25348 R01 (893481) (883481) Engine	No. 2 Engine - Sb PW300-72-25348 R01 - Replacement of Anti-Icing Tube Assembly	HRS ENC DATE MSC				- -				0 0
PW300-72-25351 R01 (883511) Engine	No. 1 Engine - Sb PW300-72-25351 R01 - Replacement of Attaching Bolts on Solenoid Bleed Valve Bracket	HRS ENC DATE MSC	3181.7 1977			- -	0 0			0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW300-72-25351 R01 (893511) (883511) Engine	No. 2 Engine - Sb PW300-72-25351 R01 - Replacement of Attaching Bolts on Solenoid Bleed Valve Bracket		HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0
PW300-72-25352 R01 (884570) Engine	No. 1 Engine - Sb PW300-72-25352 R01 - Replacement of Preformed Packings, Service Bulletin (Category 6)		HRS ENC DATE MSC				- -				0 0
PW300-72-25352 R01 (894570) (884570) Engine	No. 2 Engine - Sb PW300-72-25352 R01 - Replacement of Preformed Packings, Service Bulletin (Category 6)		HRS ENC DATE MSC				- -				0 0
PW300-72-25359 (883590) Engine	No. 1 Engine - Sb PW300-72-25359 - Replacement of Various Component Assemblies, Bolts, Brackets		HRS ENC MOS MSC		3181.7 1977 137.1		- - -	0 0 24 Feb 2014			0 0
Notes: THIS CODE HAS BEEN CANCELLED.											
PW300-72-25359 (893590) (883590) Engine	No. 2 Engine - Sb PW300-72-25359 - Replacement of Various Component Assemblies, Bolts, Brackets		HRS ENC MOS MSC		1994 1269 182.6		- - -	822.3 521 10 May 2010			0 0
PW300-72-25359 R01 (883591) Engine	No. 1 Engine - Sb PW300-72-25359 R01 - Replacement of Various Component Assemblies, Bolts, Brackets		HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25359 R01 (893591) (883591) Engine	No. 2 Engine - Sb PW300-72-25359 R01 - Replacement of Various Component Assemblies, Bolts, Brackets		HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
PW300-72-25359 R02 (883592) Engine	No. 1 Engine - Sb PW300-72-25359 R02 - Replacement of - Various Component Assemblies, Bolts, Brackets	HRS ENC MOS MSC		757.3 461 31.9		- -	2424.4 1516 30 Nov 2022			0 0
PW300-72-25359 R02 (893592) (883592) Engine	No. 2 Engine - Sb PW300-72-25359 R02 - Replacement of - Various Component Assemblies, Bolts, Brackets	HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0
PW300-72-25360 R01 (883601) Engine	No. 1 Engine - Sb PW300-72-25360 R01 - Replacement of Fuel Waste Ejector	HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25360 R01 (893601) (883601) Engine	No. 2 Engine - Sb PW300-72-25360 R01 - Replacement of Fuel Waste Ejector	HRS ENC MOS MSC		1775 1151 157.9		- -	1041.3 639 31 May 2012			0 0
PW300-72-25361 (883610) Engine Notes: THIS CODE HAS BEEN CANCELLED.	No. 1 Engine - Sb PW300-72-25361 - AIR Transfer Tubes - Replacement of	HRS ENC MOS MSC		3181.7 1977 137.1		- -	0 0 24 Feb 2014			0 0
PW300-72-25361 (893610) (883610) Engine	No. 2 Engine - Sb PW300-72-25361 - AIR Transfer Tubes - Replacement of	HRS ENC MOS MSC		2816.3 1790 163.5		- -	0 0 14 Dec 2011			0 0
PW300-72-25361 R01 (883611) Engine	No. 1 Engine - Sb PW300-72-25361 R01 - AIR Transfer Tubes - Replacement of	HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
PW300-72-25361 R01 (893611) (883611) Engine	No. 2 Engine - Sb PW300-72-25361 R01 - AIR Transfer Tubes - Replacement of	HRS ENC DATE MSC		2816.3 1790		-	0 0			0 0
PW300-72-25364 (883640) Engine Notes: THIS CODE HAS BEEN CANCELLED.	No. 1 Engine - Sb PW300-72-25364 - Inspection of Bleed Off Valve (Bov) P3 AIR Tube Assemblies	HRS ENC MOS MSC		3181.7 1977 137.1		-	0 0 24 Feb 2014			0 0
PW300-72-25364 (893640) (883640) Engine	No. 2 Engine - Sb PW300-72-25364 - Inspection of Bleed Off Valve (Bov) P3 AIR Tube Assemblies	HRS ENC MOS MSC		1994 1269 182.6		-	822.3 521 10 May 2010			0 0
PW300-72-25365 R01 (883651) Engine Notes: THIS CODE HAS BEEN CANCELLED.	No. 1 Engine - Sb PW300-72-25365 R01 - Replacement of Rear Mount	HRS ENC MOS MSC		3181.7 1977 137.1		-	0 0 24 Feb 2014			0 0
PW300-72-25365 R01 (893651) (883651) Engine	No. 2 Engine - Sb PW300-72-25365 R01 - Replacement of Rear Mount	HRS ENC MOS MSC		1775 1151 156.7		-	1041.3 639 05 Jul 2012			0 0
PW300-72-25366 R01 (883661) Engine Notes: THIS CODE HAS BEEN CANCELLED.	No. 1 Engine - Sb PW300-72-25366 R01 - Replacement/Modification of Engine Diagnostic Unit (Edu)	HRS ENC MOS MSC		3181.7 1977 137.1		-	0 0 24 Feb 2014			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
PW300-72-25366 R01 (893661) (883661) Engine	No. 2 Engine - Sb PW300-72-25366 R01 - Replacement/Modification of Engine Diagnostic Unit (Edu)	HRS ENC MOS MSC		2816.3 1790 175.4		-	0 0 16 Dec 2010			0 0
PW300-72-25366 R02 (883662) Engine	No. 1 Engine - Sb PW300-72-25366 R02 - Replacement/Modification of Engine Diagnostic Unit (Edu)	HRS ENC MOS MSC		3181.7 1977 137.1		-	0 0 24 Feb 2014			0 0
Notes: THIS CODE HAS BEEN CANCELLED.										
PW300-72-25366 R02 (893662) (883662) Engine	No. 2 Engine - Sb PW300-72-25366 R02 - Replacement/Modification of Engine Diagnostic Unit (Edu)	HRS ENC MOS MSC		2816.3 1790 171.4		-	0 0 15 Apr 2011			0 0
PW300-72-25368 R02 (883682) Engine	No. 1 Engine - Sb PW300-72-25368 R02 - Replacement/Modification of Gas Generator Case Assembly and Diffuser Exit Duct	HRS ENC DATE MSC		3181.7 1977		-	0 0			0 0
PW300-72-25368 R02 (893682) (883682) Engine	No. 2 Engine - Sb PW300-72-25368 R02 - Replacement/Modification of Gas Generator Case Assembly and Diffuser Exit Duct	HRS ENC DATE MSC		2816.3 1790		-	0 0			0 0
PW300-72-25372 (883720) Engine	No. 1 Engine - Sb PW300-72-25372 - Metal Gasket - Replacement of	HRS ENC DATE MSC				-				0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
PW300-72-25373 (883730) Engine	No. 1 Engine - Sb PW300-72-25373 - Replacement/Modification of No. 3 & 4 Bearing Scavenge Pump Housing Assembly	HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25373 (893730) (883730) Engine	No. 2 Engine - Sb PW300-72-25373 - Replacement/Modification of No. 3 & 4 Bearing Scavenge Pump Housing Assembly	HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0
PW300-72-25378 R01 (883781) Engine	No. 1 Engine - Sb PW300-72-25378 R01 - Replacement/Modification of Lower By-PASS Duct Assembly	HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25378 R01 (893781) (883781) Engine	No. 2 Engine - Sb PW300-72-25378 R01 - Replacement/Modification of Lower By-PASS Duct Assembly	HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0
PW300-72-25382 (883820) Engine	No. 1 Engine - Sb PW300-72-25382 - Replacement of Bracket Assembly, Electronic Engine Control Lower Support	HRS ENC MOS MSC		3181.7 1977 137.1		- -	0 0 24 Feb 2014			0 0

Notes: THIS CODE HAS BEEN CANCELLED.

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
PW300-72-25382 (893820) (883820) Engine	No. 2 Engine - Sb PW300-72-25382 - Replacement of Bracket Assembly, Electronic Engine Control Lower Support	HRS ENC MOS MSC		2816.3 1790 137.1		- -	0 0 24 Feb 2014			0 0
Notes: THIS CODE HAS BEEN CANCELLED.										
PW300-72-25382 R01 (883821) Engine	No. 1 Engine - Sb PW300-72-25382 R01 - Replacement of Bracket Assembly, Electronic Engine Control Lower Support	HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25382 R01 (893821) (883821) Engine	No. 2 Engine - Sb PW300-72-25382 R01 - Replacement of Bracket Assembly, Electronic Engine Control Lower Support	HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0
PW300-72-25382 R02 (884532) Engine	No. 1 Engine - Sb PW300-72-25382 R02 - Replacement of Bracket Assembly, Electronic Engine Control Lower Support	HRS ENC DATE MSC				- -				0 0
PW300-72-25382 R02 (894532) (884532) Engine	No. 2 Engine - Sb PW300-72-25382 R02 - Replacement of Bracket Assembly, Electronic Engine Control Lower Support	HRS ENC DATE MSC				- -				0 0
PW300-72-25382 R03 (884572) Engine	No. 1 Engine - PW300-72-25382 R03 - Replacement of Bracket Assembly, Electronic Engine Control Lower Support, Service Bulletin (Category 7)	HRS ENC DATE MSC				- -				0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW300-72-25382 R03 (894572) (884572) Engine	No. 2 Engine - PW300-72-25382 R03 - Replacement of Bracket Assembly, Electronic Engine Control Lower Support, Service Bulletin (Category 7)		HRS ENC DATE MSC				- -				0 0
PW300-72-25383 (883830) Engine	No. 1 Engine - Sb PW300-72-25383 - Replacement of Rear Lower By-PASS Duct Fairing		HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25383 (893830) (883830) Engine	No. 2 Engine - Sb PW300-72-25383 - Replacement of Rear Lower By-PASS Duct Fairing		HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0
PW300-72-25385 (883850) Engine	No. 1 Engine - Sb PW300-72-25385 - Replacement of By-PASS Duct Fairings		HRS ENC MOS MSC		1563.4 979 90.1		- -	1618.3 998 26 Jan 2018			0 0
PW300-72-25385 (893850) (883850) Engine	No. 2 Engine - Sb PW300-72-25385 - Replacement of By-PASS Duct Fairings		HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0
PW300-72-25386 (883860) Engine	No. 1 Engine - Sb PW300-72-25386 - Replacement of First Stage Vane Actuator Ring SET		HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25386 (893860) (883860) Engine	No. 2 Engine - Sb PW300-72-25386 - Replacement of First Stage Vane Actuator Ring SET		HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
PW300-72-25397 (883970) Engine	No. 1 Engine - Sb PW300-72-25397 - Repair/Modification of Engine Electronic Control (Eec)	HRS ENC DATE MSC		3181.7 1977		-	0 0			0 0
PW300-72-25397 (893970) (883970) Engine	No. 2 Engine - Sb PW300-72-25397 - Repair/Modification of Engine Electronic Control (Eec)	HRS ENC MOS MSC		1162.7 830 102.6		-	1653.6 960 10 Jan 2017			0 0
PW300-72-25401 R01 (884011) Engine	No. 1 Engine - Sb PW300-72-25401 R01 - Replacement of Compressor Bleed Solenoid Valve and Front Electrical Wiring Harness	HRS ENC DATE MSC		3181.7 1977		-	0 0			0 0
PW300-72-25401 R01 (894011) (884011) Engine	No. 2 Engine - Sb PW300-72-25401 R01 - Replacement of Compressor Bleed Solenoid Valve and Front Electrical Wiring Harness	HRS ENC MOS MSC		2816.3 1790 129.1		-	0 0 24 Oct 2014			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
PW300-72-25401 R02 (884012) Engine	No. 1 Engine - Sb PW300-72-25401 R02 - Replacement of Compressor Bleed Solenoid Valve and Front Electrical Wiring Harness	HRS ENC DATE MSC		3181.7 1977		-	0 0			0 0
PW300-72-25401 R02 (894012) (884012) Engine	No. 2 Engine - Sb PW300-72-25401 R02 - Replacement of Compressor Bleed Solenoid Valve and Front Electrical Wiring Harness	HRS ENC MOS MSC		1359.4 921 121.5		-	1456.9 869 12 Jun 2015			0 0
Notes: INSTALLED NEW WIRING HARNES P/N 30B7320-03 S/N EFA079400225 PER P&WC SB #25407R1 DATED 10-28-2014										

ATA U=Custom / Logbook Position	Description: Part Number / HW / MM Ref / Ops Number(s)	Description: Serial Number / SW	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
PW300-72-25401 R03 (884013) Engine	No. 1 Engine - Sb PW300-72-25401 R03 - Replacement of Compressor Bleed Solenoid Valve and Front Electrical Wiring Harness		HRS ENC MOS MSC		3181.7 1977 112		-	0 0 29 Mar 2016			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
PW300-72-25401 R03 (894013) (884013) Engine	No. 2 Engine - Sb PW300-72-25401 R03 - Replacement of Compressor Bleed Solenoid Valve and Front Electrical Wiring Harness		HRS ENC MOS MSC		2816.3 1790 112		-	0 0 29 Mar 2016			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
PW300-72-25401 R05 (884015) Engine	No. 1 Engine - Sb PW300-72-25401 R05 - Replacement of Compressor Bleed Solenoid Valve and Front Electrical Wiring Harness		HRS ENC DATE MSC		3181.7 1977		-	0 0			0 0
PW300-72-25401 R05 (894015) (884015) Engine	No. 2 Engine - Sb PW300-72-25401 R05 - Replacement of Compressor Bleed Solenoid Valve and Front Electrical Wiring Harness		HRS ENC MOS MSC		2816.3 1790 74.1		-	0 0 24 May 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
PW300-72-25401 R06 (884016) Engine	No. 1 Engine - Sb PW300-72-25401 R06 - Replacement of Compressor Bleed Solenoid Valve and Front Electrical Wiring Harness		HRS ENC DATE MSC		3181.7 1977		-	0 0			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
PW300-72-25401 R06 (894016) (884016) Engine	No. 2 Engine - Sb PW300-72-25401 R06 - Replacement of Compressor Bleed Solenoid Valve and Front Electrical Wiring Harness	HRS ENC DATE MSC	2816.3 1790			-	0 0			0 0
PW300-72-25401 R07 (884534) Engine	No. 1 Engine - Sb PW300-72-25401 R07 - Replacement of Compressor Bleed Solenoid Valve and Front Electrical Wiring Harness	HRS ENC DATE MSC				-				0 0
PW300-72-25401 R07 (884534) Engine	No. 2 Engine - Sb PW300-72-25401 R07 - Replacement of Compressor Bleed Solenoid Valve and Front Electrical Wiring Harness	HRS ENC DATE MSC				-				0 0
PW300-72-25404 (884040) Engine	No. 1 Engine - Sb PW300-72-25404 - Replacement of Shipping Caps for Shipping Containers	HRS ENC DATE MSC	3181.7 1977			-	0 0			0 0
PW300-72-25404 (894040) (884040) Engine	No. 2 Engine - Sb PW300-72-25404 - Replacement of Shipping Caps for Shipping Containers	HRS ENC MOS MSC	805 654 37			-	2011.3 1136 27 Jun 2022			0 0
PW300-72-25405 (884050) Engine	No. 1 Engine - Sb PW300-72-25405 - Replacement of Plain Seal	HRS ENC DATE MSC	3181.7 1977			-	0 0			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
PW300-72-25405 (894050) (884050) Engine	No. 2 Engine - Sb PW300-72-25405 - Replacement of Plain Seal	HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0
PW300-72-25406 (884060) Engine	No. 1 Engine - Sb PW300-72-25406 - Replacement of Protective Caps for Engine Shipping Container Assembly	HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25406 (894060) (884060) Engine	No. 2 Engine - Sb PW300-72-25406 - Replacement of Protective Caps for Engine Shipping Container Assembly	HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0
PW300-72-25407 (884070) Engine	No. 1 Engine - Sb PW300-72-25407 - Replacement of Front Core Electrical Wiring Harness	HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25407 (894070) (884070) Engine	No. 2 Engine - Sb PW300-72-25407 - Replacement of Front Core Electrical Wiring Harness	HRS ENC MOS MSC		2816.3 1790 125.6		- - 09 Feb 2015	0 0			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
PW300-72-25407 R01 (884071) Engine	No. 1 Engine - Sb PW300-72-25407 R01 - Replacement of Front Core Electrical Wiring Harness	HRS ENC MOS MSC		1563.4 979 90.2		- - 23 Jan 2018	1618.3 998			0 0
PW300-72-25407 R01 (894071) (884071) Engine	No. 2 Engine - Sb PW300-72-25407 R01 - Replacement of Front Core Electrical Wiring Harness	HRS ENC MOS MSC		1359.4 921 121.5		- - 12 Jun 2015	1456.9 869			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
PW300-72-25408 R01 (884081) Engine	No. 1 Engine - Sb PW300-72-25408 R01 - Replacement of Transfer Tube and Preformed Packings	HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25408 R01 (894081) (884081) Engine	No. 2 Engine - Sb PW300-72-25408 R01 - Replacement of Transfer Tube and Preformed Packings	HRS ENC MOS MSC		2816.3 1790 127.7		- -	0 0 05 Dec 2014			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
PW300-72-25436 (884360) Engine	No. 1 Engine - Sb PW300-72-25436 - Introduction of Add Sealant	HRS ENC DATE MSC				- -				0 0
PW300-72-25436 R01 (884361) Engine	No. 1 Engine - Sb PW300-72-25436 R01 - Introduction of Add Sealant	HRS ENC DATE MSC				- -				0 0
PW300-72-25441 (884410) Engine	No. 1 Engine - Sb PW300-72-25441 - Introduction of Turbine Exhaust Case Assembly Option (IC)	HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
Notes: PN: 30B1414 SN: <NONE>.										
PW300-72-25441 (894410) (884410) Engine	No. 2 Engine - Sb PW300-72-25441 - Introduction of Turbine Exhaust Case Assembly Option (IC)	HRS ENC DATE MSC		2816.3 1790		- -	0 0			0 0
Notes: PN: 30B1414 SN: <NONE>.										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
PW300-72-25444 (884440) Engine	No. 1 Engine - Sb PW300-72-25444 - Replacement of Intermediate Case Assembly	HRS ENC MOS MSC		3181.7 1977 77.7		- - -	0 0 06 Feb 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
PW300-72-25444 (894440) (884440) Engine	No. 2 Engine - Sb PW300-72-25444 - Replacement of Intermediate Case Assembly	HRS ENC MOS MSC		2816.3 1790 77.7		- - -	0 0 06 Feb 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
PW300-72-25444 R03 (884443) Engine	No. 1 Engine - Sb PW300-72-25444 R03 - Replacement/Modification of Intermediate Case Assembly	HRS ENC DATE MSC		3181.7 1977		- - -	0 0			0 0
PW300-72-25444 R03 (894443) (884443) Engine	No. 2 Engine - Sb PW300-72-25444 R03 - Replacement/Modification of Intermediate Case Assembly	HRS ENC DATE MSC		2816.3 1790		- - -	0 0			0 0
PW300-72-25446 (884460) Engine	No. 1 Engine - Sb PW300-72-25446 - Replacement / Modification of Lower Half Bypass Duct Assembly	HRS ENC MOS MSC		3181.7 1977 78.6		- - -	0 0 10 Jan 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
PW300-72-25446 (894460) (884460) Engine	No. 2 Engine - Sb PW300-72-25446 - Replacement / Modification of Lower Half Bypass Duct Assembly	HRS ENC MOS MSC		2816.3 1790 78.6		- - -	0 0 10 Jan 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW300-72-25446 R01 (884461) Engine	No. 1 Engine - Sb PW300-72-25446 R01 - Replacement / Modification of Lower Half Bypass Duct Assembly		HRS ENC MOS MSC		3181.7 1977 77.4		- -	0 0 15 Feb 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
PW300-72-25446 R01 (894461) (884461) Engine	No. 2 Engine - Sb PW300-72-25446 R01 - Replacement / Modification of Lower Half Bypass Duct Assembly		HRS ENC MOS MSC		2816.3 1790 77.4		- -	0 0 15 Feb 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
PW300-72-25446 R02 (884462) Engine	No. 1 Engine - Sb PW300-72-25446 R02 - Replacement / Modification of Lower Half Bypass Duct Assembly		HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25446 R02 (894462) (884462) Engine	No. 2 Engine - Sb PW300-72-25446 R02 - Replacement / Modification of Lower Half Bypass Duct Assembly		HRS ENC MOS MSC		2816.3 1790 76.7		- -	0 0 05 Mar 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											
PW300-72-25446 R03 (884463) Engine	No. 1 Engine - Sb PW300-72-25446 R03 - Replacement / Modification of Lower Half Bypass Duct Assembly		HRS ENC DATE MSC		3181.7 1977		- -	0 0			0 0
PW300-72-25446 R03 (894463) (884463) Engine	No. 2 Engine - Sb PW300-72-25446 R03 - Replacement / Modification of Lower Half Bypass Duct Assembly		HRS ENC MOS MSC		2816.3 1790 73.1		- -	0 0 25 Jun 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.											

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
PW300-72-25446 R04 (884464) Engine	No. 1 Engine - Sb PW300-72-25446 R04 - Replacement / Modification of Lower Half Bypass Duct Assembly	HRS ENC MOS MSC		3181.7 1977 71.3		-	0 0 20 Aug 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
PW300-72-25446 R04 (894464) (884464) Engine	No. 2 Engine - Sb PW300-72-25446 R04 - Replacement / Modification of Lower Half Bypass Duct Assembly	HRS ENC MOS MSC		2816.3 1790 71.3		-	0 0 20 Aug 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
PW300-72-25446 R05 (884465) Engine	No. 1 Engine - Sb PW300-72-25446 R05 - Replacement / Modification of Lower-Half Bypass Duct Assembly	HRS ENC DATE MSC		3181.7 1977		-	0 0			0 0
PW300-72-25446 R05 (894465) (884465) Engine	No. 2 Engine - Sb PW300-72-25446 R05 - Replacement / Modification of Lower-Half Bypass Duct Assembly	HRS ENC DATE MSC		2816.3 1790		-	0 0			0 0
PW300-72-25447 (884470) Engine	No. 1 Engine - Sb PW300-72-25447 - Replacement / Modification of Second Stage High Pressure Turbine Blade	HRS ENC MOS MSC		3181.7 1977 78.2		-	0 0 22 Jan 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
PW300-72-25447 (894470) (884470) Engine	No. 2 Engine - Sb PW300-72-25447 - Replacement / Modification of Second Stage High Pressure Turbine Blade	HRS ENC MOS MSC		2816.3 1790 78.2		-	0 0 22 Jan 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
PW300-72-25447 R01 (884471) Engine	No. 1 Engine - Sb PW300-72-25447 R01 - Replacement / Modification of Second Stage High Pressure Turbine Blade	HRS ENC MOS MSC		3181.7 1977 77.5		 -	0 0 11 Feb 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
PW300-72-25447 R01 (894471) (884471) Engine	No. 2 Engine - Sb PW300-72-25447 R01 - Replacement / Modification of Second Stage High Pressure Turbine Blade	HRS ENC MOS MSC		997.5 759 78.2		 -	1818.8 1031 23 Jan 2019			0 0
PW300-72-25447 R02 (884472) Engine	No. 1 Engine - Sb PW300-72-25447 R02 - Replacement / Modification of Second Stage High Pressure Turbine Blade	HRS ENC DATE MSC		3181.7 1977		 -	0 0			0 0
PW300-72-25447 R02 (894472) (884472) Engine	No. 2 Engine - Sb PW300-72-25447 R02 - Replacement / Modification of Second Stage High Pressure Turbine Blade	HRS ENC MOS MSC		2816.3 1790 72.5		 -	0 0 11 Jul 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
PW300-72-25447 R03 (884473) Engine	No. 1 Engine - Sb PW300-72-25447 R03 - Replacement / Modification of Second Stage High Pressure Turbine Blade	HRS ENC DATE MSC		3181.7 1977		 -	0 0			0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
PW300-72-25447 R03 (894473) (884473) Engine	No. 2 Engine - Sb PW300-72-25447 R03 - Replacement / Modification of Second Stage High Pressure Turbine Blade	HRS ENC DATE MSC		2816.3 1790		--	0 0			0 0
PW300-72-25447 R04 (84536) Engine	No. 1 Engine - Sb PW300-72-25447 R04 - Replacement / Modification of Second Stage High Pressure Turbine Blade	HRS ENC DATE MSC				--				0 0
PW300-72-25447 R04 (84536) Engine	No. 2 Engine - Sb PW300-72-25447 R04 - Replacement / Modification of Second Stage High Pressure Turbine Blade	HRS ENC DATE MSC				--				0 0
PW300-72-25450 (884500) Engine	No. 1 Engine - Sb PW300-72-25450 - Replacement / Modification of Oil Level Indicator	HRS ENC MOS MSC		3181.7 1977 78.2		-- --	0 0 22 Jan 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
PW300-72-25450 (894500) (884500) Engine	No. 2 Engine - Sb PW300-72-25450 - Replacement / Modification of Oil Level Indicator	HRS ENC MOS MSC		2816.3 1790 78.2		-- --	0 0 22 Jan 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
PW300-72-25450 R01 (884501) Engine	No. 1 Engine - Sb PW300-72-25450 R01 - Replacement / Modification of Oil Level Indicator	HRS ENC MOS MSC		3181.7 1977 77.7		-- --	0 0 06 Feb 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
PW300-72-25450 R01 (894501) (884501) Engine	No. 2 Engine - Sb PW300-72-25450 R01 - Replacement / Modification of Oil Level Indicator	HRS ENC MOS MSC		2816.3 1790 77.7		-	0 0 06 Feb 2019			0 0
Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.										
PW300-72-25450 R02 (884502) Engine	No. 1 Engine - Sb PW300-72-25450 R02 - Replacement / Modification of Oil Level Indicator	HRS ENC DATE MSC		3181.7 1977		-	0 0			0 0
PW300-72-25450 R02 (894502) (884502) Engine	No. 2 Engine - Sb PW300-72-25450 R02 - Replacement / Modification of Oil Level Indicator	HRS ENC DATE MSC		2816.3 1790		-	0 0			0 0
PW300-72-25450 R03 (884559) Engine	No. 1 Engine - Sb PW300-72-25450 R03 - Replacement / Modification of Oil Level Indicator, Service Bulletin (Category 7)	HRS ENC DATE MSC				-				0 0
PW300-72-25450 R03 (894559) (884559) Engine	No. 2 Engine - Sb PW300-72-25450 R03 - Replacement / Modification of Oil Level Indicator, Service Bulletin (Category 7)	HRS ENC DATE MSC				-				0 0
PW300-72-25450 R04 (884573) Engine	No. 1 Engine - Sb PW300-72-25450 R04 - Replacement / Modification of Oil Level Indicator, Service Bulletin (Category 7)	HRS ENC MOS MSC				-				0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
PW300-72-25450 R04 (894573) (884573) Engine	No. 2 Engine - Sb PW300-72-25450 R04 - Replacement / Modification of Oil Level Indicator, Service Bulletin (Category 7)	HRS ENC MOS MSC				- -				0 0
PW300-72-25451 (884510) Engine	No. 1 Engine - Sb PW300-72-25451 -	HRS ENC DATE MSC	3181.7 1977			- -	0 0			0 0
PW300-72-25451 (894510) (884510) Engine	No. 2 Engine - Sb PW300-72-25451 -	HRS ENC DATE MSC	2816.3 1790			- -	0 0			0 0
PW300-72-25451 R01 (884531) Engine	No. 1 Engine - Sb PW300-72-25451 R01 - Replacement/Modification of Electronic Engine Control (Eec)	HRS ENC DATE MSC				- -				0 0
PW300-72-25451 R01 (894531) (884531) Engine	No. 2 Engine - Sb PW300-72-25451 R01 - Replacement/Modification of Electronic Engine Control (Eec)	HRS ENC DATE MSC				- -				0 0
PW300-72-25451 R02 (884556) Engine	No. 1 Engine - Sb PW300-72-25451 R02 - Replacement/Modification of Electronic Engine Control (Eec), Service Bulletin (Category 7)	HRS ENC DATE MSC				- -				0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer
Logbook Position	HW	SW									Date Type
	MM Ref										
	Ops Number(s)										
PW300-72-25451 R02 (894556) (884556) Engine	No. 2 Engine - Sb PW300-72-25451 R02 - Replacement/Modification of Electronic Engine Control (Eec), Service Bulletin (Category 7)		HRS ENC DATE MSC				- -				0 0
PW300-72-25453 (884530) Engine	No. 1 Engine - Sb PW300-72-25453 - Replacement of Outer Combustion Chamber Liner Assembly		HRS ENC DATE MSC				- -				0 0
PW300-72-25457 (884533) Engine	No. 1 Engine - Sb PW300-72-25457 - Replacement of FIRE Detector Bracket Hinged Clamp		HRS ENC DATE MSC				- -				0 0
PW300-72-25457 (884533) Engine	No. 2 Engine - Sb PW300-72-25457 - Replacement of FIRE Detector Bracket Hinged Clamp		HRS ENC DATE MSC				- -				0 0
PW300-72-25460 (884541) Engine	No. 1 Engine - Sb PW300-72-25460 - Sb PW300-72-25460 - Replacement / Modification of 2ND Stage Hpt Disk Assembly		HRS ENC DATE MSC				- -				0 0
PW300-72-25460 (884541) Engine	No. 2 Engine - Sb PW300-72-25460 - Sb PW300-72-25460 - Replacement / Modification of 2ND Stage Hpt Disk Assembly		HRS ENC DATE MSC				- -				0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW300-72-25460 R01 (884542) Engine	No. 1 Engine - Sb PW300-72-25460 R01 - Sb PW300-72-25460 R01 - Replacement / Modification of 2ND Stage Hpt Disc Assembly		HRS ENC DATE MSC				- -				0 0
PW300-72-25460 R01 (884542) Engine	No. 2 Engine - Sb PW300-72-25460 R01 - Sb PW300-72-25460 R01 - Replacement / Modification of 2ND Stage Hpt Disc Assembly		HRS ENC DATE MSC				- -				0 0
PW300-72-25460 R02 (884543) Engine	No. 1 Engine - Sb PW300-72-25460 R02 - Sb PW300-72-25460 R02 - Replacement / Modification of 2ND Stage Hpt Disc Assembly		HRS ENC DATE MSC				- -				0 0
PW300-72-25460 R02 (884543) Engine	No. 2 Engine - Sb PW300-72-25460 R02 - Sb PW300-72-25460 R02 - Replacement / Modification of 2ND Stage Hpt Disc Assembly		HRS ENC DATE MSC				- -				0 0
PW300-72-25460 R03 (884544) Engine	No. 1 Engine - Sb PW300-72-25460 R03 - Sb PW300-72-25460 R03 - Replacement / Modification of 2ND Stage Hpt Disc Assembly		HRS ENC DATE MSC				- -				0 0
PW300-72-25460 R03 (894544) (884544) Engine	No. 2 Engine - Sb PW300-72-25460 R03 - Sb PW300-72-25460 R03 - Replacement / Modification of 2ND Stage Hpt Disc Assembly		HRS ENC DATE MSC				- -				0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
PW300-72-25460 R04 (884545) Engine	No. 1 Engine - Sb PW300-72-25460 R04 - Sb PW300-72-25460 R04 - Replacement / Modification of 2ND Stage Hpt Disc Assembly		HRS ENC DATE MSC				- -				0 0
PW300-72-25460 R04 (894545) (884545) Engine	No. 2 Engine - Sb PW300-72-25460 R04 - Sb PW300-72-25460 R04 - Replacement / Modification of 2ND Stage Hpt Disc Assembly		HRS ENC DATE MSC				- -				0 0
PW300-72-25460 R05 (884547) Engine	No. 1 Engine - Sb PW300-72-25460 R05 - Sb PW300-72-25460 R05 - Replacement / Modification of 2ND Stage Hpt Disc Assembly		HRS ENC DATE MSC				- -				0 0
PW300-72-25460 R05 (894547) (884547) Engine	No. 2 Engine - Sb PW300-72-25460 R05 - Sb PW300-72-25460 R05 - Replacement / Modification of 2ND Stage Hpt Disc Assembly		HRS ENC DATE MSC				- -				0 0
PW300-72-25460 R06 (884549) Engine	No. 1 Engine - Sb PW300-72-25460 R06 - Sb PW300-72-25460 R06 - Replacement / Modification of 2ND Stage Hpt Disc Assembly		HRS ENC DATE MSC				- -				0 0
PW300-72-25460 R06 (894549) (884549) Engine	No. 2 Engine - Sb PW300-72-25460 R06 - Sb PW300-72-25460 R06 - Replacement / Modification of 2ND Stage Hpt Disc Assembly		HRS ENC DATE MSC				- -				0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
PW300-72-25460 R07 (884554) Engine	No. 1 Engine - Sb PW300-72-25460 R07 - Replacement / Modification of 2ND Stage Hpt Disc Assembly, Service Bulletin (Category 6)	HRS ENC DATE MSC				- 				0 0
PW300-72-25460 R07 (894554) (884554) Engine	No. 2 Engine - Sb PW300-72-25460 R07 - Replacement / Modification of 2ND Stage Hpt Disc Assembly, Service Bulletin (Category 6)	HRS ENC DATE MSC				- 				0 0
PW300-72-25460 R08 (884557) Engine	No. 1 Engine - Sb PW300-72-25460 R08 - Replacement / Modification of 2ND Stage Hpt Disc Assembly, Service Bulletin (Category 6)	HRS ENC DATE MSC				- 				0 0
PW300-72-25460 R08 (894557) (884557) Engine	No. 2 Engine - Sb PW300-72-25460 R08 - Replacement / Modification of 2ND Stage Hpt Disc Assembly, Service Bulletin (Category 6)	HRS ENC DATE MSC				- 				0 0
PW300-72-25460 R09 (884561) Engine	No. 1 Engine - Sb PW300-72-25460 R09 - Replacement / Modification of 2ND Stage Hpt Disc Assembly, Service Bulletin (Category 6)	HRS ENC DATE MSC				- 				0 0
PW300-72-25460 R09 (894561) (884561) Engine	No. 2 Engine - Sb PW300-72-25460 R09 - Replacement / Modification of 2ND Stage Hpt Disc Assembly, Service Bulletin (Category 6)	HRS ENC DATE MSC				- 				0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW300-72-25460 R10 (884563) Engine	No. 1 Engine - Sb PW300-72-25460 R10 - Replacement / Modification of 2ND Stage Hpt Disc Assembly, Service Bulletin (Category 6)		HRS ENC DATE MSC				- -				0 0
PW300-72-25460 R10 (894563) (884563) Engine	No. 2 Engine - Sb PW300-72-25460 R10 - Replacement / Modification of 2ND Stage Hpt Disc Assembly, Service Bulletin (Category 6)		HRS ENC DATE MSC				- -				0 0
PW300-72-25460 R11 (884783) Engine	No. 1 Engine - Sb PW300-72-25460 R11 - Replacement/Modification of 2ND-Stage High-Pressure-Turbine Disk-Assembly, Service Bulletin (Category 5)		HRS ENC MOS MSC				- -				0 0
PW300-72-25460 R11 (894783) (884783) Engine	No. 2 Engine - Sb PW300-72-25460 R11 - Replacement/Modification of 2ND-Stage High-Pressure-Turbine Disk-Assembly, Service Bulletin (Category 5)		HRS ENC MOS MSC				- -				0 0
PW300-72-25461 (884539) Engine	No. 1 Engine - Sb PW300-72-25461 - PW300-72-25461 - Replacement of Compressor Bleed Solenoid Valve		HRS ENC DATE MSC				- -				0 0
PW300-72-25461 (884539) Engine	No. 2 Engine - Sb PW300-72-25461 - PW300-72-25461 - Replacement of Compressor Bleed Solenoid Valve		HRS ENC DATE MSC				- -				0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price
Logbook Position	HW	SW									Manufacturer
	MM Ref										Date Type
	Ops Number(s)										
PW300-72-25463 (884546) Engine	No. 1 Engine - Sb PW300-72-25463 - PW300-72-25463 - Replacement of Tie ROD Retaining Nut		HRS ENC DATE MSC				- -				0 0
PW300-72-25463 (894546) (884546) Engine	No. 2 Engine - Sb PW300-72-25463 - PW300-72-25463 - Replacement of Tie ROD Retaining Nut		HRS ENC DATE MSC				- -				0 0
PW300-72-25465 (884548) Engine	No. 1 Engine - Sb PW300-72-25465 - Sb PW300-72-25465 - Inspection of Duplex Fuel Nozzle		HRS ENC DATE MSC				- -				0 0
PW300-72-25465 (894548) (884548) Engine	No. 2 Engine - Sb PW300-72-25465 - Sb PW300-72-25465 - Inspection of Duplex Fuel Nozzle		HRS ENC DATE MSC				- -				0 0
PW300-72-25466 (884552) Engine	No. 1 Engine - PW300-72-25466 - Replacement of Gas Generator Case Assembly, Service Bulletin (Category 7)		HRS ENC DATE MSC				- -				0 0
PW300-72-25466 (894552) (884552) Engine	No. 2 Engine - PW300-72-25466 - Replacement of Gas Generator Case Assembly, Service Bulletin (Category 7)		HRS ENC DATE MSC				- -				0 0
PW300-72-25466 R01 (884558) Engine	No. 1 Engine - Sb PW300-72-25466 R01 - Replacement of Gas Generator Case Assembly, Service Bulletin (Category 7)		HRS ENC DATE MSC				- -				0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
PW300-72-25466 R01 (894558) (884558) Engine	No. 2 Engine - Sb PW300-72-25466 R01 - Replacement of Gas Generator Case Assembly, Service Bulletin (Category 7)	HRS ENC DATE MSC				--				0 0
PW300-72-25466 R02 (884571) Engine	No. 1 Engine - Sb PW300-72-25466 R02 - Replacement of Gas Generator Case Assembly, Service Bulletin (Category 7)	HRS ENC DATE MSC				--				0 0
PW300-72-25466 R02 (894571) (884571) Engine	No. 2 Engine - Sb PW300-72-25466 R02 - Replacement of Gas Generator Case Assembly, Service Bulletin (Category 7)	HRS ENC DATE MSC				--				0 0
PW300-72-25466 R03 (884575) Engine	No. 1 Engine - Sb PW300-72-25466 R03 - Replacement of Gas Generator Case Assembly, Service Bulletin (Category 7)	HRS ENC MOS MSC				--				0 0
PW300-72-25466 R03 (894575) (884575) Engine	No. 2 Engine - Sb PW300-72-25466 R03 - Replacement of Gas Generator Case Assembly, Service Bulletin (Category 7)	HRS ENC MOS MSC				--				0 0
PW300-72-25467 (884550) Engine	No. 1 Engine - Sb PW300-72-25467 - Sb PW300-72-25467 - Replacement of Duplex Fuel Nozzle	HRS ENC DATE MSC				--				0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
PW300-72-25467 (894550) (884550) Engine	No. 2 Engine - Sb PW300-72-25467 - Sb PW300-72-25467 - Replacement of Duplex Fuel Nozzle	HRS ENC DATE MSC				- -				0 0
PW300-72-25471 (884551) Engine	No. 1 Engine - Sb PW300-72-25471 - Sb PW300-72-25471 - Inspection of Inlet Guide Vane Actuating ARM Assy	HRS ENC DATE MSC				- -				0 0
PW300-72-25471 (894551) (884551) Engine	No. 2 Engine - Sb PW300-72-25471 - Sb PW300-72-25471 - Inspection of Inlet Guide Vane Actuating ARM Assy	HRS ENC DATE MSC				- -				0 0
PW300-72-25471 R01 (884560) Engine	No. 1 Engine - Sb PW300-72-25471 R01 - Inspection of Inlet Guide Vane Actuating ARM Assy, Service Bulletin (Category 6)	HRS ENC DATE MSC				- -				0 0
PW300-72-25471 R01 (894560) (884560) Engine	No. 2 Engine - Sb PW300-72-25471 R01 - Inspection of Inlet Guide Vane Actuating ARM Assy, Service Bulletin (Category 6)	HRS ENC DATE MSC				- -				0 0
PW300-72-25473 (884565) Engine	No. 1 Engine - Sb PW300-72-25473 - Replacement of High-Pressure Turbine First-Stage Disk, Service Bulletin (Category 3)	HRS ENC MOS MSC	 1977 218.1			- -	 0 25 May 2007			0 0

ATA U=Custom	Description Part Number / Serial Number HW / SW MM Ref Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
PW300-72-25473 (894565) (884565) Engine	No. 2 Engine - Sb PW300-72-25473 - Replacement of High-Pressure Turbine First-Stage Disk, Service Bulletin (Category 3)	HRS ENC MOS MSC		1790 234.1		-	0 26 Jan 2006			0 0
PW300-72-25475 (884564) Engine	No. 1 Engine - Sb PW300-72-25475 - Replacement of Inlet Guide Vane Shroud SET, Service Bulletin (Category 7)	HRS ENC DATE MSC				-				0 0
PW300-72-25475 (894564) (884564) Engine	No. 2 Engine - Sb PW300-72-25475 - Replacement of Inlet Guide Vane Shroud SET, Service Bulletin (Category 7)	HRS ENC DATE MSC				-				0 0
PW300-72-25475 R01 (884567 R01) Engine	No. 1 Engine - Sb PW300-72-25475 R01 - Replacement of Inlet Guide Vane Shroud SET, Service Bulletin (Category 7)	HRS ENC DATE MSC				-				0 0
PW300-72-25475 R01 (894567 R01) (884567 R01) Engine	No. 2 Engine - Sb PW300-72-25475 R01 - Replacement of Inlet Guide Vane Shroud SET, Service Bulletin (Category 7)	HRS ENC DATE MSC				-				0 0
PW300-72-25478 (884576) Engine	No. 1 Engine - Sb PW300-72-25478 - Replacement of First-Stage High-Pressure-Turbine Blades, Service Bulletin (Category 7)	HRS ENC DATE MSC				-				0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
PW300-72-25478 (894576) (884576) Engine	No. 2 Engine - Sb PW300-72-25478 - Replacement of First-Stage High-Pressure-Turbine Blades, Service Bulletin (Category 7)		HRS ENC DATE MSC				- -				0 0
PW300-72-25478 R01 (884577) Engine	No. 1 Engine - Sb PW300-72-25478 R01 - Replacement of First-Stage High-Pressure-Turbine Blades, Service Bulletin (Category 7)		HRS ENC MOS MSC				- -				0 0
PW300-72-25478 R01 (894577) (884577) Engine	No. 2 Engine - Sb PW300-72-25478 R01 - Replacement of First-Stage High-Pressure-Turbine Blades, Service Bulletin (Category 7)		HRS ENC MOS MSC				- -				0 0
PW300-72-25478 R02 (884782) Engine	No. 1 Engine - Sb PW300-72-25478 R02 - Replacement of First-Stage High-Pressure-Turbine Blades, Service Bulletin (Category 7)		HRS ENC MOS MSC				- -				0 0
PW300-72-25478 R02 (894782) (884782) Engine	No. 2 Engine - Sb PW300-72-25478 R02 - Replacement of First-Stage High-Pressure-Turbine Blades, Service Bulletin (Category 7)		HRS ENC MOS MSC				- -				0 0
PW300-72-25478 R03 (884783) Engine	No. 1 Engine - Sb PW300-72-25478 R03 - Replacement of First-Stage High-Pressure-Turbine Blades, Service Bulletin (Category 7)		HRS ENC MOS MSC				- -				0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer
Logbook Position	HW	SW									Date Type
	MM Ref										
	Ops Number(s)										
PW300-72-25478 R03 (894783) (884783) Engine	No. 2 Engine - Sb PW300-72-25478 R03 - Replacement of First-Stage High-Pressure-Turbine Blades, Service Bulletin (Category 7)		HRS ENC MOS MSC				- -				0 0
PW300-72-25480 (884574) Engine	No. 1 Engine - Sb PW300-72-25480 - Replacement of Actuator Support-Bracket, Service Bulletin (Category 7)		HRS ENC DATE MSC				- -				0 0
PW300-72-25480 (894574) (884574) Engine	No. 2 Engine - Sb PW300-72-25480 - Replacement of Actuator Support-Bracket, Service Bulletin (Category 7)		HRS ENC DATE MSC				- -				0 0
PW300-72-25480 R01 (884801) Engine	No. 1 Engine - Sb PW300-72-25480 R01 - Replacement of Actuator Support-Bracket, Service Bulletin (Category 7)		HRS ENC MOS MSC				- -				0 0
PW300-72-25480 R01 (894801) (884801) Engine	No. 2 Engine - Sb PW300-72-25480 R01 - Replacement of Actuator Support-Bracket, Service Bulletin (Category 7)		HRS ENC MOS MSC				- -				0 0
PW300-72-25480 R02 (884802) Engine	No. 1 Engine - Sb PW300-72-25480 R02 - Replacement of Actuator Support-Bracket, Service Bulletin (Category 7)		HRS ENC DATE MSC				- -				0 0

ATA U=Custom / Logbook Position	Description: Part Number / Serial Number / HW / SW / MM Ref / Ops Number(s)	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs / Approx Price / Manufacturer / Date Type
PW300-72-25480 R02 (894802) (884802) Engine	No. 2 Engine - Sb PW300-72-25480 R02 - Replacement of Actuator Support-Bracket, Service Bulletin (Category 7)	HRS ENC DATE MSC				- -				0 0
PW300-72-A25072 (890720) (880720) Engine	No. 2 Engine - Sb PW300-72-A25072 - Inspection of P3 Transducer and Condensation Trap	HRS ENC MOS MSC	2770.7 1774 227.9			- - -	45.6 16 31 Jul 2006			0 0
Notes: N/A BY COMPLIANCE WITH S/B 25143 - NEW CAP WITH DRAIN HOLE INSTALLED										
PW300-72-A25251 (882510) Engine	No. 1 Engine - Sb PW300-72-A25251 - Inspection of First Stage Hpt L - Seal and Blades Borescope (Superseded By PW300-72-A25286)	HRS ENC MOS MSC	3181.7 1977 137.1			- - -	0 0 24 Feb 2014			0 0
Notes: THIS CODE HAS BEEN CANCELLED.										
PW300-77-25474 (884562) Engine	No. 1 Engine - PW300-77-25474 - Replacement / RE-Identification Oftc-T4.5 Wiring Harness, Service Bulletin (Category 7)	HRS ENC DATE MSC				- -				0 0
PW300-77-25474 (894562) (884562) Engine	No. 2 Engine - PW300-77-25474 - Replacement / RE-Identification Oftc-T4.5 Wiring Harness, Service Bulletin (Category 7)	HRS ENC DATE MSC				- -				0 0
PW300-77-25474 R01 (884566 R01) Engine	No. 1 Engine - Sb PW300-77-25474 R01 - Replacement/RE-Identification of Tc-T4.5 Wiring Harness, Service Bulletin (Category 7)	HRS ENC DATE MSC				- -				0 0

ATA U=Custom	Description Part Number	Serial Number	UOM	Times Since	Time Accrued	Adj	Required Freq	Last C/W	Next Due (*=Adj)	Max Due	Avg Man Hrs Approx Price Manufacturer Date Type
Logbook Position	HW	SW									
	MM Ref										
	Ops Number(s)										
PW300-77-25474 R01 (894566 R01) (884566 R01) Engine	No. 2 Engine - Sb PW300-77-25474 R01 - Replacement/RE-Identification of Tc-T4.5 Wiring Harness, Service Bulletin (Category 7)		HRS ENC DATE MSC				- -				0 0
PW300-77-25474 R02 (884568) Engine	No. 1 Engine - Sb PW300-77-25474 R02 - Replacement/RE-Identification of Tc-T4.5 Wiring Harness, Service Bulletin (Category 7)		HRS ENC DATE MSC				- -				0 0
PW300-77-25474 R02 (884568) Engine	No. 2 Engine - Sb PW300-77-25474 R02 - Replacement/RE-Identification of Tc-T4.5 Wiring Harness, Service Bulletin (Category 7)		HRS ENC DATE MSC				- -				0 0
PW300-77-25474 R03 (884569) Engine	No. 1 Engine - Sb PW300-77-25474 R03 - Replacement/RE-Identification of Tc-T4.5 Wiring Harness, Service Bulletin (Category 7)		HRS ENC DATE MSC				- -				0 0
PW300-77-25474 R03 (894569) (884569) Engine	No. 2 Engine - Sb PW300-77-25474 R03 - Replacement/RE-Identification of Tc-T4.5 Wiring Harness, Service Bulletin (Category 7)		HRS ENC DATE MSC				- -				0 0