CESCOM 20 - Projected Maintenance Due

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/ Landings	Date	Average	Projected	Hours	Events/ Landings	Days	Months
AIRCRAFT	**1651:47**	**1136**	**14-Sep-2025**	**0:27**	**0.66**	**124:16**	**93**	**189**	**6**
ENG 1	**1651:47**	**1136**	**14-Sep-2025**	**0:27**	**0.66**	**124:16**	**93**	**189**	**6**
ENG 2	**1651:47**	**1136**	**14-Sep-2025**	**0:27**	**0.66**	**124:16**	**93**	**189**	**6**
AIR COND	**497:12**		**14-Sep-2025**	**0:54**	**0.33**	**62:07**		**189**	**6**

***** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.***

Scheduled Maintenance Tasks

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No		C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
A256003	DETAILED INSPECTION FIRST AID KIT FIRST AID KIT: INSPECTION DOCUMENT 02										
				BR8524	MTH	05-Feb-2025		12		28-Jan-2026	4 m 5 d
				MX597	HRS	1519:42					
					LDG	1047					
FXT-7	PERFORM 1ST EXTENSION OF AIRWORTHINESS REVIEW CERTIFICATE										
					MTH	08-Oct-2024		36		11-Oct-2025	18 d
					HRS	1427:29					
					LDG	980					
FXT-8	PERFORM 2ND EXTENSION OF AIRWORTHINESS REVIEW CERTIFICATE										
					MTH			36 MTH		11-Oct-2025	18 d
B243603	LEAD ACID BATTERY FUNCTIONAL CHECK (CAPACITY CHECK) NOTE: THE INSPECTION SCHEDULE MAY BE ADJUSTED AFTER THE USEFUL BATTERY LIFE IS ESTABLISHED, BASED ON OPERATIONS. TASK 24-36-15-720										
		EKBI		RG-380E/44LA5 - S3597-8	MTH	07-Jun-2025		4		31-Oct-2025	1 m 8 d
				41238130	HRS	1606:16		200		1806:16	154:29
					LDG	1104					
5-12-08	INSPECTION DOCUMENT 08				MTH	19-Sep-2024		24		30-Sep-2026	12 m 7 d
		UNK			HRS	1411:13		300		1711:13	59:26
					LDG	965					
5-12-36	INSPECTION DOCUMENT 36				MTH	07-Jun-2025		6		31-Dec-2025	3 m 8 d
		EKBI			HRS	1606:16					
					LDG	1104					
052003	FJ44 CHECK 3				MTH	16-Nov-2015					
E1					HRS	0		1750		(1750)1750	98:13
052003	FJ44 CHECK 3				MTH	16-Nov-2015					
E2					HRS	0		1750		(1750)1750	98:13
5-12-02	INSPECTION DOCUMENT 02				MTH	05-Feb-2025		12		28-Feb-2026	5 m 5 d
		LFPB			HRS	1519:42					
					LDG	1047					
5-12-12	INSPECTION DOCUMENT 12 (14 CFR 91.207)				MTH	05-Feb-2025		12		28-Feb-2026	5 m 5 d
		LFPB			HRS	1519:42					
					LDG	1047					
5-12-33	INSPECTION DOCUMENT 33				MTH	05-Feb-2025		12		28-Feb-2026	5 m 5 d
		LFPB			HRS	1519:42		300		1819:42	167:55
					LDG	1047					
5-12-MP	INSPECTION DOCUMENT MP				MTH	05-Feb-2025		12		28-Feb-2026	5 m 5 d
		LFPB			HRS	1519:42		250		1769:42	117:55
					LDG	1047					
A256201	DETAILED INSPECTION EMERGENCY LOCATOR TRANSMITTER ARTEX (ELT): INSPECTION DOCUMENT 12										
		LFPB		453-5060	MTH	05-Feb-2025		12		28-Feb-2026	5 m 5 d
				16014	HRS	1519:42					
					LDG	1047					
B256203	OPERATIONAL CHECK ARTEX C406-N EMERGENCY LOCATOR TRANSMITTER: INSPECTION DOCUMENT 12										
		LFPB			MTH	05-Feb-2025		12		28-Feb-2026	5 m 5 d
					HRS	1519:42					
					LDG	1047					
B262201	FUNCTIONAL (WEIGHT) CHECK PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 2										
CABIN		LFPB		C352CS	MTH	05-Feb-2025		12		28-Feb-2026	5 m 5 d
				I-27696359	HRS	1519:42					
					LDG	1047					
B243603	LEAD ACID BATTERY FUNCTIONAL CHECK (CAPACITY CHECK) NOTE: THE INSPECTION SCHEDULE MAY BE ADJUSTED AFTER THE USEFUL BATTERY LIFE IS ESTABLISHED, BASED ON OPERATIONS. TASK 24-36-15-720										
		EKBI		RG-380E/44LA5 - S3597-8	MTH	07-Jun-2025		4		28-Feb-2026	5 m 5 d
				41238130							

NOTE: Item codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference).

CESCOM 20 - Projected Maintenance Due

Owner: **STARJET APS**
Aircraft Model: **525-CITATION M2**
Aircraft Serial: **525-0893**
Unit: Reg No: **OY-TPJ**
Airworthiness: **16-Nov-2015**
Print Date: **23-Sep-2025 2:21PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/ Landings	Date	Average	Projected	Hours	Events/ Landings	Days	Months
AIRCRAFT	**1651:47**	**1136**	**14-Sep-2025**	**0:27**	**0.66**	**124:16**	**93**	**189**	**6**
ENG 1	**1651:47**	**1136**	**14-Sep-2025**	**0:27**	**0.66**	**124:16**	**93**	**189**	**6**
ENG 2	**1651:47**	**1136**	**14-Sep-2025**	**0:27**	**0.66**	**124:16**	**93**	**189**	**6**
AIR COND	**497:12**		**14-Sep-2025**	**0:54**	**0.33**	**62:07**		**189**	**6**

***** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.***

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No		C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB WI-75-1001 R02	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE				MTH						
E1					HRS					(3500)3500	1848:13
				RECOMMENDED	MSC			-			
SB WI-75-1001 R02	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE				MTH						
E2					HRS					(3500)3500	1848:13
				RECOMMENDED	MSC			-			
SB WI-73-1040 R03	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE										
E1					MTH						
					HRS					(8000)8000	6348:13
					MSC			DUE			
SB WI-73-1040 R03	ENGINE FUEL AND CONTROL - FUEL DELIVERY UNIT - REPLACE										
E2					MTH						
					HRS					(8000)8000	6348:13
					MSC			DUE			
SB 525-27-26	FLIGHT CONTROLS - TAILCONE STRINGER FAIRLEAD INSTALLATION										
					MTH						
				RECOMMENDED	MSC			-			
SB 525-27-26 R01	FLIGHT CONTROLS - TAILCONE STRINGER FAIRLEAD INSTALLATION										
					MTH						
				RECOMMENDED	MSC			-			
SB 525-27-28	FLIGHT CONTROLS - ELEVATOR TRIM WHEEL INSPECTION										
					MTH						
				RECOMMENDED	MSC			-			
SB 525-34-111	NAVIGATION - TOLD DATABASE UPDATE				MTH						
					MSC			-			
				RECOMMENDED							
SL 525-21-06	AIR CONDITIONING - CABIN PRESSURIZATION CONTROLLER IMPROVEMENT										
					MTH						
				RECOMMENDED	MSC			-			
SL 525-23-08 R01	COMMUNICATIONS - GARMIN GMA 36 MODIFICATION LEVEL VERIFICATION										
					MTH						
				RECOMMENDED	MSC			-			
SL 525-23-09	COMMUNICATIONS - LINK 2000+ CPDLC AND VHF ACARS CONFIGURATION VERIFICATION										
					MSC			-			
				RECOMMENDED							
SL 525-26-01	FIRE PROTECTION - ENGINE FIRE EXTINGUISHER BOTTLE ORIENTATION VERIFICATION										
					MTH						
				RECOMMENDED	MSC			-			
SL 525-27-11	FLIGHT CONTROLS - CONTROL WHEEL ADAPTER AND SHAFT INSPECTION										
					MTH						
				RECOMMENDED	MSC			-			
SL 525-34-38	NAVIGATION - STORMSCOPE PROCESSOR MODIFICATION (MOD) LEVEL INSPECTION										
					MTH						
				RECOMMENDED	MSC			-			
SL 525-52-04	DOORS - MAIN CABIN DOOR GROMMET INSTALLATION				MTH						
					MSC			-			
				RECOMMENDED							
SL 525-53-12	FUSELAGE - CONTROL PEDESTAL WIRE HARNESS ANCHOR VERIFICATION										
					MTH						
				RECOMMENDED	MSC			-			
SL 525-71-08	POWER PLANT - INSTALLATION OF A MISSING FASTENER ON THE ENGINE INLET FORWARD FIREWALL										
					MTH						
				RECOMMENDED	MSC			-			
SL 525-71-08 R01	POWER PLANT - INSTALLATION OF A MISSING FASTENER ON THE ENGINE INLET FORWARD FIREWALL										
					MTH						
				RECOMMENDED	MSC			-			
SL 525-71-08 R02	POWER PLANT - INSTALLATION OF A MISSING FASTENER ON THE ENGINE INLET FORWARD FIREWALL										
					MSC			-			
				RECOMMENDED							

NOTE: Item codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference).