

OWNER: WHISKEY TANGO L.L.C.	OPERATOR: BASIN AVIATION INC.	OPERATOR: WHISKEY TANGO L.L.C.
ADDRESS: C/O BASIN AVIATION MIDLAND TX 79710	ADDRESS: P. O. BOX 50547 MIDLAND TX 79710	ADDRESS: C/O BASIN AVIATION MIDLAND TX 79710
OFFICE: 432-685-7000	OFFICE: 432-685-7000	OFFICE: 432-685-7000
FAX: 432-683-8851	FAX: 432-683-8851	FAX: 432-683-8851
ANALYST: KIRK WILLIAMS	+1-316-462-2403 (DIRECT)	800-787-9749 (EFAX-CARDS)
EMAIL: K WILLIAMS@CAMPSYSTEMS.COM	+1-631-588-3200 (MAIN)	631-980-4222 (EFAX-CARDS)
	WWW.CAMPSYSTEMS.COM	
PROJECTED: 6 MOS. to 03/30/2027		

AIRCRAFT	SERIAL / REGNO: 45-456/N157MW	MODEL: LEARJET 75	MANUFACTURER: BOMBARDIER AVIATION
CERTIFICATION DATE: 21-NOV-2013		LAST ACTUALS:	PROJECTED:
		1931.28 A/C HRS as of 28-SEP-2026	1990.80
		1750 AFL as of 28-SEP-2026	1809
		876.75 APH as of 24-JUN-2026	936
		1899 APS as of 24-JUN-2026	1958

APU	SERIAL / PART: P-494/3800726-1	MODEL: RE100 (CIMMS)	MANUFACTURER: HONEYWELL
INSTALLED ON: 20-NOV-2013		LAST ACTUALS:	PROJECTED:
0 APU HRS	0 A/C HRS	876.75 APU HRS as of 24-JUN-2026	936.27
0 APUS		1899 APUS as of 24-JUN-2026	1958

ENGINE NO. 1	SERIAL / PART: P-137153/3062075-1	MODEL: TFE731-40BR-1B	MANUFACTURER: HONEYWELL
INSTALLED ON: 08-JUL-2014		LAST ACTUALS:	PROJECTED:
89 ENG. HRS	89 A/C HRS	1931.3 ENG. HRS as of 28-SEP-2026	1990.82
87 ENC		1753 ENC as of 28-SEP-2026	1812

ENGINE NO. 2	SERIAL / PART: P-137154/3062075-1	MODEL: TFE731-40BR-1B	MANUFACTURER: HONEYWELL
INSTALLED ON: 08-JUL-2014		LAST ACTUALS:	PROJECTED:
89 ENG. HRS	89 A/C HRS	1931.3 ENG. HRS as of 28-SEP-2026	1990.82
87 ENC		1753 ENC as of 28-SEP-2026	1812

New Requirement/Flagged Items

Operator Review and Action Required

Model: LEARJET 75 Serial: 45-456 RegNo: N157MW HRS: 1931.28 AFL: 1750 As Of: 28-Sep-2026 Operator: BASIN AVIATION INC.
These tasks or requirements have been added newly to your aircraft status. Please review them and approve or modify as appropriate. Please pay particular attention to the Base and Next Due Times for these tasks. It is important to note that any task that has insufficient information (marked by ?), will never come due unless the necessary information is provided by you.

Report Date: 30-Sep-2026

PN & SN	Effective Date	Unit	Interval	Base Time		Next Due (ENG/APU) A/C	Disposition	
				Current	Change To			
FAA 2026-13-02 PARA (H)		AIRPLANE FLIGHT MANUAL (AFM) REVISION					AD	ATA:31
	01-Jul-26	MOS	T:BF/F	01-Jul-26			MANDATORY	
		HRS						
		AFL						
NEW REQUIREMENT ADDED ON 30-JUN-26. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.					REF: AD			

Name: Signature: Cert.# Date:

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time

Due List Report

Model: LEARJET 75 Serial: 45-456 RegNo: N157MW HRS: 1931.28 AFL: 1750 As
Of: 28-Sep-2026 Operator: BASIN AVIATION INC.

Report Date: 30-Sep-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
057110		NO. 1 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS						Package ATA:05
	MOS			07-Jan-26				
	HRS	150 (+100)		1680.3	(1830.3)1830.28	1930.3	OVD	
	ENC			1539				
		REF: LMM 72-00-00						
057110		NO. 2 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS						Package ATA:05
	MOS			07-Jan-26				
	HRS	150 (+100)		1680.3	(1830.3)1830.28	1930.3	OVD	
	ENC			1538				
		REF: LMM 72-00-00						
SB 75-27-06 R04		FLIGHT CONTROLS - INSPECTION/MODIFICATION OF THE AILERON, SERVICE BULLETIN						Bulletin ATA:27
	MOS	T:6			22-Jul-26 (M)		OVD	
	HRS							
	AFL							
Disposition: RECOMMENDED			REF: BULLETINS					
256076		FIRST AID KIT						Component ATA:25
PN:AFK 1.0	MOS	12		23-Sep-25	30-Sep-26 (M)		0 d	30-Sep-2026
SN:011422004	HRS			1619.5				
	AFL			1486				
Disposition: CUSTOMER OPTION			REF: GENERIC NO REF					
0000001		12 MONTH SERVICING CHECKS						Package ATA:05
	MOS	12 (+14d/-14d)		07-Nov-25	07-Nov-26	21-Nov-26	38 d (+14)	07-Nov-2026
	HRS			1642.2				
	AFL			1509				
		REF: EMP PACKAGES						
256109F ^U		RENEW C406-N ELT EMERGENCY LOCATOR TRANSMITTER ELT REGISTRATION						Service ATA:25
PN:453-5060	MOS	22 (+2m)		14-Jan-25	14-Nov-26	14-Jan-27	45 d (+61)	14-Nov-2026
SN:12892	HRS			1465.1				
	AFL			1355				
Disposition: INFORMATIONAL			REF:					
2710052		* AILERON BALANCE WEIGHT SUPPORT BRACKETS - PERFORM EDDY CURRENT INSPECTION.						Service ATA:27
	MOS	T:6		EFF	30-Dec-26 * (M)		91 d	30-Dec-2026
	HRS							
	AFL							
Disposition: AIRWORTHINESS			REF:					

Due List Report

Model: LEARJET 75 Serial: 45-456 RegNo: N157MW HRS: 1931.28 AFL: 1750 As
Of: 28-Sep-2026 Operator: BASIN AVIATION INC.

Report Date: 30-Sep-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
2561002		INSPECT LAV LIFE VEST						Service ATA:25
PN:63600-105	MOS	12		07-Jan-26	06-Jan-27		98 d	06-Jan-2027
SN:L5472772	HRS			1680.3				
	AFL			1539				
REF: AMM 25-60-01								
2561002		INSPECT NO. 1 LIFE VEST						Service ATA:25
PN:63600-105	MOS	12		07-Jan-26	06-Jan-27		98 d	06-Jan-2027
SN:L5472774	HRS			1680.3				
	AFL			1539				
REF: AMM 25-60-01								
2561002		INSPECT NO. 2 LIFE VEST						Service ATA:25
PN:63600-105	MOS	12		07-Jan-26	06-Jan-27		98 d	06-Jan-2027
SN:L5472776	HRS			1680.3				
	AFL			1539				
REF: AMM 25-60-01								
2561002		INSPECT NO. 3 LIFE VEST						Service ATA:25
PN:63600-105	MOS	12		07-Jan-26	06-Jan-27		98 d	06-Jan-2027
SN:L5472773	HRS			1680.3				
	AFL			1539				
REF: AMM 25-60-01								
2561002		INSPECT NO. 4 LIFE VEST						Service ATA:25
PN:63600-101	MOS	12		07-Jan-26	06-Jan-27		98 d	06-Jan-2027
SN:L5472771	HRS			1680.3				
	AFL			1539				
REF: AMM 25-60-01								
2561002		INSPECT NO. 5 LIFE VEST						Service ATA:25
PN:63600-105	MOS	12		07-Jan-26	06-Jan-27		98 d	06-Jan-2027
SN:L5472775	HRS			1680.3				
	AFL			1539				
REF: AMM 25-60-01								
2561002		INSPECT NO. 6 LIFE VEST						Service ATA:25
PN:63600-105	MOS	12		07-Jan-26	06-Jan-27		98 d	06-Jan-2027
SN:L5472777	HRS			1680.3				
	AFL			1539				
REF: AMM 25-60-01								

Due List Report

Model: LEARJET 75 Serial: 45-456 RegNo: N157MW HRS: 1931.28 AFL: 1750 As
Of: 28-Sep-2026 Operator: BASIN AVIATION INC.

Report Date: 30-Sep-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
2561002		INSPECT NO. 7 LIFE VEST						Service ATA:25
PN:63600-105	MOS	12		07-Jan-26	06-Jan-27		98 d	06-Jan-2027
SN:L5472779	HRS			1680.3				
	AFL			1539				
REF: AMM 25-60-01								
2561002		INSPECT NO. 8 LIFE VEST						Service ATA:25
PN:63600-105	MOS	12		07-Jan-26	06-Jan-27		98 d	06-Jan-2027
SN:L5472778	HRS			1680.3				
	AFL			1539				
REF: AMM 25-60-01								
2561002		INSPECT PILOT LIFE VEST						Service ATA:25
PN:63600-105	MOS	12		07-Jan-26	06-Jan-27		98 d	06-Jan-2027
SN:L5472774	HRS			1680.3				
	AFL			1539				
REF: AMM 25-60-01								
2561002		INSPECT CO-PILOT LIFE VEST						Service ATA:25
PN:63600-105	MOS	12		07-Jan-26	07-Jan-27		99 d	07-Jan-2027
SN:L5472778	HRS			1680.3				
	AFL			1539				
	APH							
	APS							
REF: AMM 25-60-01								
256109B		INSPECT EMERGENCY LOCATOR TRANSMITTER (ELT)						Service ATA:25
PN:453-5060	MOS	12		07-Jan-26	07-Jan-27		99 d	07-Jan-2027
SN:12892	HRS			1680.3				
	AFL			1539				
	APH							
	APS							
REF: GENERIC NO REF, FAR 91.207								
340001-RVSM		CHECK RVSM HEIGHT MONITORING						Service ATA:34
	MOS	24		14-Jan-25	14-Jan-27		106 d	14-Jan-2027
	HRS			1465.1				
	AFL			1355				
REF: GENERIC NO REF, FAR AGHME - ADSB HEIGHT MONITORING								

Due List Report

Model: LEARJET 75 Serial: 45-456 RegNo: N157MW HRS: 1931.28 AFL: 1750 As
Of: 28-Sep-2026 Operator: BASIN AVIATION INC.

Report Date: 30-Sep-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
3020005		LEFT	* ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.					Service ATA:30
	MOS			24-Mar-26				15-Jan-2027
	HRS	250		1716.5	1966.5		35.2	
	AFL			1563				
Disposition: CMR*		REF: GENERIC NO REF						
3020005		RIGHT	* ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.					Service ATA:30
	MOS			24-Mar-26				15-Jan-2027
	HRS	250		1716.5	1966.5		35.2	
	AFL			1563				
Disposition: CMR*		REF: GENERIC NO REF						
2910018		REPLACE MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS						Service ATA:29
	MOS			12-Dec-25				19-Jan-2027
	HRS	300 (+25/-25)	Adj.:3	1667.5	1967.8	1992.8	36.5 (+25)	
	AFL			1529				
		REF: AMM 29-10-03						
2431068		BATTERY - PERFORM CAPACITY CHECK						Service ATA:24
PN:RG-380E/40L	MOS	6 (+1m/-1m)		05-Aug-26	05-Feb-27	05-Mar-27	128 d (+28)	05-Feb-2027
SN:70056572	HRS			1855.6				
	AFL			1685				
		REF: AMM 24-31-06, CMM 24-30-71						
2431068		BATTERY - PERFORM CAPACITY CHECK						Service ATA:24
PN:RG-380E/40L	MOS	6 (+1m/-1m)		05-Aug-26	05-Feb-27	05-Mar-27	128 d (+28)	05-Feb-2027
SN:70056573	HRS			1855.6				
	AFL			1685				
		REF: AMM 24-31-06, CMM 24-30-71						
761330A		NO. 1 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM						Service ATA:76
PN:2118882-8001	MOS			19-Jul-26				12-Mar-2027
SN:53-BP0033	HRS	150		1834.7	(1984.7)1984.68		53.4	
	ENC			1677				
		REF: MSC CAMP EHM ADENDUM						
761330A		NO. 2 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM						Service ATA:76
PN:2118882-8001	MOS			19-Jul-26				12-Mar-2027
SN:53-BP0034	HRS	150		1834.7	(1984.7)1984.68		53.4	
	ENC			1677				
		REF: MSC CAMP EHM ADENDUM						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time