



DueList Report

LEARJET 45

S/N 45-400 N145MW

OWNER: WHISKEY TANGO L.L.C.
ADDRESS: C/O BASIN AVIATION
MIDLAND TX 79710
OFFICE: 432-685-7000
FAX: 432-683-8851

OPERATOR: WHISKEY TANGO L.L.C.
ADDRESS: C/O BASIN AVIATION
MIDLAND TX 79710
OFFICE: 432-685-7000
FAX: 432-683-8851

ANALYST: KIRK WILLIAMS
EMAIL: KWILLIAMS@CAMPSYSTEMS.COM

+1-316-462-2403 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PROJECTED: 6 MOS. to 04/01/2027

AIRCRAFT	SERIAL / REGNO: 45-400/N145MW		MODEL:	LEARJET 45		MANUFACTURER: BOMBARDIER AVIATION	
	CERTIFICATION DATE: 29-APR-2009			LAST ACTUALS:		PROJECTED:	
				3612.8	A/C HRS	as of 02-AUG-2026	3762.38
				3261	AFL	as of 02-AUG-2026	3410
				1920.37	APH	as of 23-JUN-2026	2010
APU	SERIAL / PART: P-436/3800726-1		MODEL:	RE100 (CIMMS)		MANUFACTURER: HONEYWELL	
	INSTALLED ON: 12-JUL-2024			LAST ACTUALS:		PROJECTED:	
	1713.68	APU HRS	3187	A/C HRS			
	2928	APUS					
				1920.37	APU HRS	as of 23-JUN-2026	2010.12
				3321	APUS	as of 23-JUN-2026	3470
ENGINE NO. 1	SERIAL / PART: P-132158C/3060084-1		MODEL:	TFE731-20BR-1B		MANUFACTURER: HONEYWELL	
	INSTALLED ON: 20-JAN-2009			LAST ACTUALS:		PROJECTED:	
	0	ENG. HRS	0	A/C HRS			
	0	ENC					
				3612.8	ENG. HRS	as of 02-AUG-2026	3762.38
				3262	ENC	as of 02-AUG-2026	3411
ENGINE NO. 2	SERIAL / PART: P-132157C/3060084-1		MODEL:	TFE731-20BR-1B		MANUFACTURER: HONEYWELL	
	INSTALLED ON: 19-JAN-2009			LAST ACTUALS:		PROJECTED:	
	0	ENG. HRS	0	A/C HRS			
	0	ENC					
				3612.8	ENG. HRS	as of 02-AUG-2026	3762.38
				3262	ENC	as of 02-AUG-2026	3411



Insufficient Items

Operator Review and Action Required

Model: LEARJET 45 Serial: 45-400 RegNo: N145MW HRS: 3612.8 AFL: 3261 As Of: 02-Aug-2026 Operator: WHISKEY TANGO L.L.C.

Report Date: 01-Oct-2026

These tasks have insufficient information for calculating next due. Please provide the missing information (marked by ?) so that they can be setup properly. It is important to note that any task that has insufficient information, will not come due correctly unless the necessary information is provided by you.

PN & SN	Unit	Effective Date	Interval	C/W	TSX/Adj.	Next Due (ENG/APU) A/C	Disposition
O3510006		PILOTS OXYGEN MASK - E.R.O.S. CREW OXYGEN MASKS - COMPLY WITH FACTORY OVERHAUL					Service ATA:35
PN:MC10-15-166	MOS		72 (+14d/-14d)	30-Jun-26		?	
SN:84004	HRS			3569.1			
	AFL			3234			
REF: GENERIC NO REF							

Name: _____ Signature: _____ Cert.#: _____ Date: _____

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



New Requirement/Flagged Items

Operator Review and Action Required

Model: LEARJET 45 Serial: 45-400 RegNo: N145MW HRS: 3612.8 AFL: 3261 As Of: 02-Aug-2026 Operator: WHISKEY TANGO L.L.C.
These tasks or requirements have been added newly to your aircraft status. Please review them and approve or modify as appropriate. Please pay particular attention to the Base and Next Due Times for these tasks. It is important to note that any task that has insufficient information (marked by ?), will never come due unless the necessary information is provided by you.

Report Date: 01-Oct-2026

PN & SN	Effective Date	Unit	Interval	Base Time		Next Due (ENG/APU) A/C	Disposition	
				Current	Change To			
AF2710051		* AILERON BALANCE WEIGHT SUPPORT BRACKETS - PERFORM EDDY CURRENT INSPECTION					Service	ATA:27
	28-Apr-26	MOS	T:6 (+14d/-14d)	28-Apr-26		28-Oct-26 *	AIRWORTHINESS	
		HRS						
		AFL						
NEW REQUIREMENT ADDED ON 02-SEP-26. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.					REF: GENERIC NO REF			
FAA 2026-13-02 PARA (H)		AIRPLANE FLIGHT MANUAL (AFM) REVISION					AD	ATA:31
	01-Jul-26	MOS	T:BF/F	01-Jul-26			MANDATORY	
		HRS						
		AFL						
NEW REQUIREMENT ADDED ON 30-JUN-26. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.					REF: AD			

Name: _____ Signature: _____ Cert.# _____ Date: _____

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time

Due List Report

Model: LEARJET 45 Serial: 45-400 RegNo: N145MW HRS: 3612.8 AFL: 3261 As Of:
02-Aug-2026 Operator: WHISKEY TANGO L.L.C.

Report Date: 01-Oct-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
051101	PHASE A1-300 HOUR CHECKS							Package ATA:05
	MOS	12 (+14d/-14d)		05-Sep-25	05-Sep-26	19-Sep-26	OVD	
	HRS	300 (+25/-25)		3327	3627	3652	14.2 (+25)	
	AFL			3014				
	REF: AMM 05-10-00, AMM 05-11-01							
051102	PHASE A2-300 HOUR CHECKS							Package ATA:05
	MOS	12 (+14d/-14d)		05-Sep-25	05-Sep-26	19-Sep-26	OVD	
	HRS	300 (+25/-25)		3327	3627	3652	14.2 (+25)	
	AFL			3014				
	REF: AMM 05-10-00, AMM 05-11-02							
051103	PHASE A3-300 HOUR CHECKS							Package ATA:05
	MOS	12 (+14d/-14d)		05-Sep-25	05-Sep-26	19-Sep-26	OVD	
	HRS	300 (+25/-25)		3327	3627	3652	14.2 (+25)	
	AFL			3014				
	REF: AMM 05-10-00, AMM 05-11-03							
051104	PHASE A4-300 HOUR CHECKS							Package ATA:05
	MOS	12 (+14d/-14d)		05-Sep-25	05-Sep-26	19-Sep-26	OVD	
	HRS	300 (+25/-25)		3327	3627	3652	14.2 (+25)	
	AFL			3014				
	REF: AMM 05-10-00, AMM 05-11-04							
051105	PHASE A5-300 HOUR CHECKS							Package ATA:05
	MOS	12 (+14d/-14d)		05-Sep-25	05-Sep-26	19-Sep-26	OVD	
	HRS	300 (+25/-25)		3327	3627	3652	14.2 (+25)	
	AFL			3014				
	REF: AMM 05-10-00, AMM 05-11-05							
051106	PHASE A6-300 HOUR CHECKS							Package ATA:05
	MOS	12 (+14d/-14d)		05-Sep-25	05-Sep-26	19-Sep-26	OVD	
	HRS	300 (+25/-25)		3327	3627	3652	14.2 (+25)	
	AFL			3014				
	REF: AMM 05-10-00, AMM 05-11-06							
057110	NO. 1 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package ATA:05
	MOS			05-Sep-25				
	HRS	150 (+100)		3327	(3477)3477	3577	OVD	
	ENC			3014				
	REF: LMM 72-00-00							

Due List Report

Model: LEARJET 45 Serial: 45-400 RegNo: N145MW HRS: 3612.8 AFL: 3261 As Of:
02-Aug-2026 Operator: WHISKEY TANGO L.L.C.

Report Date: 01-Oct-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
057110		NO. 2 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS						Package ATA:05
	MOS			05-Sep-25				
	HRS	150 (+100)		3327	(3477)3477	3577	OVD	
	ENC			3014				
		REF: LMM 72-00-00						
256076A		FIRST AID KIT - VISUALLY INSPECT PER MANUFACTURER INSTRUCTIONS						Service ATA:25
PN:500939	MOS	6		23-Feb-26	23-Aug-26		OVD	
SN:121902048B	HRS			3457.5				
	AFL			3136				
Disposition: CUSTOMER CODE		REF: GENERIC NO REF						
7120006 ^U		REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING						Service ATA:71
PN:LM-833-SA18	MOS		TAC:0	29-Apr-09				
SN:LK1802	HRS	3500 (+100/-100)	TAC:0	0	3500	3600	OVD	
	AFL		TAC:0	0				
Disposition: LIFE LIMIT		REF:						
7120006		REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING						Service ATA:71
	MOS		TAC:0	29-Apr-09				
	HRS	3500	TAC:0, Ext:100	0	3600		OVD	
	AFL		TAC:0	0				
Disposition: LIFE LIMIT		REF:						
7120006 ^U		REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING						Service ATA:71
	MOS		TAC:0	29-Apr-09				
	HRS	3500	TAC:0, Ext:100	0	3600		OVD	
	AFL		TAC:0	0				
Disposition: LIFE LIMIT		REF:						
72-AS-720005		NO. 1 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS						Service ATA:72
	MOS			19-Dec-08				
	HRS	3500 (+100)		0	(3500)3500	3600	OVD	
	ENC			0				
		REF: LMM 72-00-00						
72-AS-720005		NO. 2 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS						Service ATA:72
	MOS			18-Dec-08				
	HRS	3500 (+100)		0	(3500)3500	3600	OVD	
	ENC			0				
		REF: LMM 72-00-00						

Due List Report

Model: LEARJET 45 Serial: 45-400 RegNo: N145MW HRS: 3612.8 AFL: 3261 As Of:
02-Aug-2026 Operator: WHISKEY TANGO L.L.C.

Report Date: 01-Oct-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
AD7120006 NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING Service ATA:71								
PN:LM-833-45	MOS		TAC:0	29-Apr-09				
SN:LK6683	HRS	3500 (+100/-100)	TAC:0	0	3500	3600	OVD	
	AFL		TAC:0	0				
Disposition: LIFE LIMIT REF: AMM 71-20-00								
AD7120006 NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING Service ATA:71								
PN:LM-833-45	MOS		TAC:0	29-Apr-09				
SN:LK6686	HRS	3500 (+100/-100)	TAC:0	0	3500	3600	OVD	
	AFL		TAC:0	0				
Disposition: LIFE LIMIT REF: AMM 71-20-00								
AD7120006 NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING Service ATA:71								
PN:LM-833-45	MOS		TAC:0	29-Apr-09				
SN:LK6677	HRS	3500 (+100/-100)	TAC:0	0	3500	3600	OVD	
	AFL		TAC:0	0				
Disposition: LIFE LIMIT REF: AMM 71-20-00								
AD7120006 ^U REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING Service ATA:71								
PN:LM-833-SA18	MOS		TAC:0	29-Apr-09				
SN:LK1801	HRS	3500 (+100/-100)	TAC:0	0	3500	3600	OVD	
	AFL		TAC:0	0				
Disposition: LIFE LIMIT REF:								
AD7120006 NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING Service ATA:71								
PN:LM-833-45	MOS		TAC:0	29-Apr-09				
SN:LK6672	HRS	3500	TAC:0, Ext:100	0	3600		OVD	
	AFL		TAC:0	0				
Disposition: LIFE LIMIT REF: AMM 71-20-00								
AD7120075 NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF AFT ISOLATOR ASSEMBLY AND ASSOCIATED PARTS Service ATA:71								
	MOS							
	HRS	3500	Ext:100	0	3600		OVD	
	AFL							
REF: AMM 71-20-00								
AD7120075 NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF AFT ISOLATOR ASSEMBLY AND ASSOCIATED PARTS Service ATA:71								
	MOS							
	HRS	3500	Ext:100	0	3600		OVD	
	AFL							
REF: AMM 71-20-00								

Due List Report

Model: LEARJET 45 Serial: 45-400 RegNo: N145MW HRS: 3612.8 AFL: 3261 As Of:
02-Aug-2026 Operator: WHISKEY TANGO L.L.C.

Report Date: 01-Oct-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
FAA 2025-16-09 PARA (G)(1)		INSPECT EACH BUCKLE SCREW FOR CRACKED, LOOSE, AND MISSING SCREW HEADS BY FOLLOWING THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPHS B.(1) AND (2), OF PARKER MEGGITT SERVICE BULLETIN SB 1111475-25-001-2023, REVISION 002, DATED APRIL 1, 2024 (SB 1111475-25-001-2023 REV 002) - FOR AIRPLANES WITH BUCKLE P/N 1111475 (ALL DASH NUMBERS)						AD ATA:25
	MOS	T:12		EFF	22-Sep-26 *		OVD	
	HRS							
	AFL							
Disposition: MANDATORY		REF: AD						
FAA 2025-16-09 PARA (G)(2)		INSPECT EACH BUCKLE SCREW FOR CRACKED, LOOSE, AND MISSING SCREW HEADS BY FOLLOWING THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH B.(1), OF PARKER MEGGITT SB 1111548-25-001-2023, REVISION 002, DATED APRIL 1, 2024 (SB 1111548-25-001-2023 REV 002) - AIRPLANES WITH BUCKLE P/N 1111548-01						AD ATA:25
	MOS	T:12		EFF	22-Sep-26 *		OVD	
	HRS							
	AFL							
Disposition: MANDATORY		REF: AD						
FAA 2025-16-09 PARA (G)(3)		CREWMEMBER SEAT OR PASSENGER SEAT (AS AN OPTION FOR THE ACTIONS REQUIRED BY PARAGRAPH (G)(1) OR (2) OF THIS AD) - REMOVE MALE SIDE FROM THE LAP OF THE RESTRAINT SYSTEM AND FABRICATE A PLACARD STATING SEAT IS INOPERATIVE						AD ATA:25
	MOS	T:12		EFF	22-Sep-26 *		OVD	
	HRS							
	AFL							
Disposition: MANDATORY		REF: AD						
O2610001		NO. 1 ENGINE HOT SECTION FIRE DETECTOR ELEMENT - PERFORM VISUAL INSPECTION						Service ATA:26
	MOS			29-Apr-09				
	HRS	3500 (+100/-100)		0	3500	3600	OVD	
	AFL			0				
		REF: AMM 05-10-00						
O2610001		NO. 2 ENGINE HOT SECTION FIRE DETECTOR ELEMENT - PERFORM VISUAL INSPECTION						Service ATA:26
	MOS			29-Apr-09				
	HRS	3500 (+100/-100)		0	3500	3600	OVD	
	AFL			0				
		REF: AMM 05-10-00						
P2430003		NO. 1 STARTER/GENERATOR - PERFORM OVERHAUL						Service ATA:24
PN:23280-067	MOS			03-Jul-26				
SN:P1805/CA	HRS	1200 (+25/-25)	TAC:1211	3576.7	3576.7	3601.7	OVD	
	AFL			3237				
		REF: GENERIC NO REF						

Due List Report

Model: LEARJET 45 Serial: 45-400 RegNo: N145MW HRS: 3612.8 AFL: 3261 As Of:
02-Aug-2026 Operator: WHISKEY TANGO L.L.C.

Report Date: 01-Oct-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
P3610048 LEFT HIGH PRESSURE BLEED AIR MANIFOLD - PERFORM VISUAL INSPECTION Service ATA:36								
PN:LJ01212-001	MOS			29-Apr-09				
SN:171108-001	HRS	3500 (+100/-100)		0	3500	3600	OVD	
	AFL			0				
REF: AMM 05-10-00								
P3610048 RIGHT HIGH PRESSURE BLEED AIR MANIFOLD - PERFORM VISUAL INSPECTION Service ATA:36								
PN:LJ01212-002	MOS			29-Apr-09				
SN:221108-001	HRS	3500 (+100/-100)		0	3500	3600	OVD	
	AFL			0				
REF: AMM 05-10-00								
Q7110004 NO. 1 ENGINE INLET - PERFORM TAP TEST Service ATA:71								
	MOS			27-Apr-13				
	HRS	3500 (+100/-100)		1197	3500 (M)	3600	OVD	
	AFL			1122				
REF: AMM 71-10-01								
Q7110004 NO. 2 ENGINE INLET - PERFORM TAP TEST Service ATA:71								
	MOS			27-Apr-13				
	HRS	3500 (+100/-100)		1197	3500 (M)	3600	OVD	
	AFL			1122				
REF: AMM 71-10-01								
SB 45-27-54 R04 FLIGHT CONTROLS - INSPECTION/MODIFICATION OF THE AILERON, SERVICE BULLETIN Bulletin ATA:27								
	MOS	T:6			22-Jul-26 (M)		OVD	
	HRS							
	AFL							
Disposition: RECOMMENDED REF: BULLETINS								
SB TFE731-72-5158 R02 NO. 1 ENGINE - ENGINE - BY-PASS SECTION - INSTALL AN IMPROVED FAN DISC, FAN SHAFT, AND FAN ROLLER BEARING TO ENHANCE FAN BALANCE RETENTION, SERVICE BULLETIN Bulletin ATA:72								
	MOS							
	HRS	T:3000 (+100)		0	(3500)3500 (M)	3600	OVD	
	ENC							
Disposition: CATEGORY 3 REF: BULLETINS								
SB TFE731-72-5158 R02 NO. 2 ENGINE - ENGINE - BY-PASS SECTION - INSTALL AN IMPROVED FAN DISC, FAN SHAFT, AND FAN ROLLER BEARING TO ENHANCE FAN BALANCE RETENTION, SERVICE BULLETIN Bulletin ATA:72								
	MOS							
	HRS	T:3000 (+100)		0	(3500)3500 (M)	3600	OVD	
	ENC							
Disposition: CATEGORY 3 REF: BULLETINS								

Due List Report

Model: LEARJET 45 Serial: 45-400 RegNo: N145MW HRS: 3612.8 AFL: 3261 As Of:
02-Aug-2026 Operator: WHISKEY TANGO L.L.C.

Report Date: 01-Oct-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
SB TFE731-72-5172 R05		NO. 1 ENGINE - TURBINE SECTION - HPT AND LPT BLADE HOUR TRACKING AND RECOMMENDED BLADE REPLACEMENT INTERVALS FOR TFE731-20, -40, -50, -60 SERIES ENGINE MODELS, SERVICE BULLETIN						Bulletin ATA:72
	MOS	T:MPI		EFF				
	HRS		Ext:100		(3600)3600 * (M)		OVD	
	ENC							
Disposition: CATEGORY 2		REF: BULLETINS						
SB TFE731-72-5172 R05		NO. 2 ENGINE - TURBINE SECTION - HPT AND LPT BLADE HOUR TRACKING AND RECOMMENDED BLADE REPLACEMENT INTERVALS FOR TFE731-20, -40, -50, -60 SERIES ENGINE MODELS, SERVICE BULLETIN						Bulletin ATA:72
	MOS	T:MPI		EFF				
	HRS		Ext:100		(3600)3600 * (M)		OVD	
	ENC							
Disposition: CATEGORY 2		REF: BULLETINS						
SB TFE731-72-5216 R01		NO. 1 ENGINE - ENGINE - ACCESSORY DRIVES SECTION - INSTALL IMPROVED PLAIN ENCASED SEAL, PN 3020052-26, SERVICE BULLETIN						Bulletin ATA:72
	MOS	T:DUE		EFF				
	HRS		Ext:100		(3600)3600 * (M)		OVD	
	ENC							
Disposition: CATEGORY 2		REF: BULLETINS						
SB TFE731-72-5216 R01		NO. 2 ENGINE - ENGINE - ACCESSORY DRIVES SECTION - INSTALL IMPROVED PLAIN ENCASED SEAL, PN 3020052-26, SERVICE BULLETIN						Bulletin ATA:72
	MOS	T:DUE		EFF				
	HRS		Ext:100		(3600)3600 * (M)		OVD	
	ENC							
Disposition: CATEGORY 2		REF: BULLETINS						
SB TFE731-72-5223 R01		NO. 1 ENGINE - BYPASS SECTION - APPLY PROTECTIVE COATING TO THE AFT FLANGE OF THE COMPOSITE BYPASS DUCT ON TFE731-20, -40, -50, AND -60 ENGINE MODELS, SERVICE BULLETIN						Bulletin ATA:72
	MOS	T:DUE		EFF				
	HRS		Ext:100		(3600)3600 * (M)		OVD	
	ENC							
Disposition: CATEGORY 2		REF: BULLETINS						
SB TFE731-72-5223 R01		NO. 2 ENGINE - BYPASS SECTION - APPLY PROTECTIVE COATING TO THE AFT FLANGE OF THE COMPOSITE BYPASS DUCT ON TFE731-20, -40, -50, AND -60 ENGINE MODELS, SERVICE BULLETIN						Bulletin ATA:72
	MOS	T:DUE		EFF				
	HRS		Ext:100		(3600)3600 * (M)		OVD	
	ENC							
Disposition: CATEGORY 2		REF: BULLETINS						

Due List Report

Model: LEARJET 45 Serial: 45-400 RegNo: N145MW HRS: 3612.8 AFL: 3261 As Of:
02-Aug-2026 Operator: WHISKEY TANGO L.L.C.

Report Date: 01-Oct-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
SB TFE731-72-5251		NO. 1 ENGINE - TURBINE SECTION - ACCOMPLISH EDDY CURRENT INSPECTION OF SPECIFIC SECOND STAGE LOW PRESSURE TURBINE (LPT2) BLADES, PN 3075424, ON TFE731-20, -40, -50, -60 MODEL ENGINES, SERVICE BULLETIN						Bulletin ATA:72
	MOS	T:DUE		EFF				
	HRS		Ext:100		(3600)3600 * (M)		OVD	
	ENC							
Disposition: CATEGORY 2		REF: BULLETINS						
SB TFE731-72-5251		NO. 2 ENGINE - TURBINE SECTION - ACCOMPLISH EDDY CURRENT INSPECTION OF SPECIFIC SECOND STAGE LOW PRESSURE TURBINE (LPT2) BLADES, PN 3075424, ON TFE731-20, -40, -50, -60 MODEL ENGINES, SERVICE BULLETIN						Bulletin ATA:72
	MOS	T:DUE		EFF				
	HRS		Ext:100		(3600)3600 * (M)		OVD	
	ENC							
Disposition: CATEGORY 2		REF: BULLETINS						
SB TFE731-73-5146 R01		NO. 1 ENGINE - ENGINE FUEL AND CONTROL - CONTROLLING - INSTALL IMPROVED FUEL CONTROL ASSEMBLY (FCA), PN 3070800-28, -30, -37, -47, -69, AND -79, WITH IMPROVED SOLENOID ATTACHMENT SCREWS ON TFE731-20, -40, -50, AND -60 ENGINE MODELS, SERVICE BULLETIN						Bulletin ATA:73
	MOS	T:DUE		EFF				
	HRS		Ext:100		(3600)3600 * (M)		OVD	
	ENC							
Disposition: CATEGORY 2		REF: BULLETINS						
SB TFE731-73-5146 R01		NO. 2 ENGINE - ENGINE FUEL AND CONTROL - CONTROLLING - INSTALL IMPROVED FUEL CONTROL ASSEMBLY (FCA), PN 3070800-28, -30, -37, -47, -69, AND -79, WITH IMPROVED SOLENOID ATTACHMENT SCREWS ON TFE731-20, -40, -50, AND -60 ENGINE MODELS, SERVICE BULLETIN						Bulletin ATA:73
	MOS	T:DUE		EFF				
	HRS		Ext:100		(3600)3600 * (M)		OVD	
	ENC							
Disposition: CATEGORY 2		REF: BULLETINS						
SB TFE731-79-5129		NO. 1 ENGINE - OIL - STORAGE - INSTALL IMPROVED OIL TANK INSTRUCTION PLATE TO PREVENT OIL TANK OVERSERVICING ON TFE731-20, -40, -60 MODEL ENGINES, SERVICE BULLETIN						Bulletin ATA:79
	MOS	T:DUE		EFF				
	HRS		Ext:100		(3600)3600 * (M)		OVD	
	ENC							
Disposition: CATEGORY 2		REF: BULLETINS						
SB TFE731-79-5129		NO. 2 ENGINE - OIL - STORAGE - INSTALL IMPROVED OIL TANK INSTRUCTION PLATE TO PREVENT OIL TANK OVERSERVICING ON TFE731-20, -40, -60 MODEL ENGINES, SERVICE BULLETIN						Bulletin ATA:79
	MOS	T:DUE		EFF				
	HRS		Ext:100		(3600)3600 * (M)		OVD	
	ENC							
Disposition: CATEGORY 2		REF: BULLETINS						

Due List Report

Model: LEARJET 45 Serial: 45-400 RegNo: N145MW HRS: 3612.8 AFL: 3261 As Of:
02-Aug-2026 Operator: WHISKEY TANGO L.L.C.

Report Date: 01-Oct-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
W5600002		** WINDSHIELD - PERFORM RAIN REMOVAL COATING EFFECTIVENESS TEST						Service ATA:56
	MOS	12 (+14d/-14d)		05-Sep-25	05-Sep-26	19-Sep-26	OVD	
	HRS			3327				
	AFL			3014				
	APH							
Disposition: AIRWORTHINESS		REF: AMM 56-10-01						
057130		NO. 1 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS						Package ATA:05
	MOS			05-Jun-23				01-Oct-2026
	HRS	600 (+50/-100)		3006.7	(3606.7)3606.7	3656.7	TOL (+43.9)	
	ENC			2677				
		REF: LMM 72-00-00						
057130		NO. 2 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS						Package ATA:05
	MOS			05-Jun-23				01-Oct-2026
	HRS	600 (+50/-100)		3006.7	(3606.7)3606.7	3656.7	TOL (+43.9)	
	ENC			2677				
		REF: LMM 72-00-00						
057150		NO. 1 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS						Package ATA:05
	MOS			16-Jul-19				08-Oct-2026
	HRS	1200 (+100/-200)		2419.3	(3619.3)3619.3	3719.3	6.5 (+100)	
	ENC			2132				
		REF: LMM 72-00-00						
057150		NO. 2 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS						Package ATA:05
	MOS			16-Jul-19				08-Oct-2026
	HRS	1200 (+100/-200)		2419.3	(3619.3)3619.3	3719.3	6.5 (+100)	
	ENC			2132				
		REF: LMM 72-00-00						
Y2130065		CABIN PRESSURIZATION SYSTEM - PERFORM CABIN LEAKAGE TEST						Service ATA:21
	MOS			23-Jul-19				11-Oct-2026
	HRS	1200 (+25/-25)		2421.5	3621.5	3646.5	8.7 (+25)	
	AFL			2136				
		REF: AMM 21-30-00						
D2910018		MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS - REPLACE						Service ATA:29
	MOS			05-Sep-25				18-Oct-2026
	HRS	300 (+25/-25)		3327	3627	3652	14.2 (+25)	
	AFL			3014				
		REF: AMM 29-10-03						

Due List Report

Model: LEARJET 45 Serial: 45-400 RegNo: N145MW HRS: 3612.8 AFL: 3261 As Of: 02-Aug-2026 Operator: WHISKEY TANGO L.L.C.

Report Date: 01-Oct-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
Y2431005	BATTERY CABLES AND RECEPTACLES - PERFORM BATTERY CONNECTOR TOLERANCE CHECK							Service ATA:24
	MOS			05-Sep-25				18-Oct-2026
	HRS	300 (+25/-25)		3327	3627	3652	14.2 (+25)	
	AFL			3014				
	APH							
	REF: AMM 24-31-00							
H5323032	* EXTERIOR CABIN WINDOW COAMINGS (UNPAINTED) - PERFORM EDDY CURRENT INSPECTION							Service ATA:53
	MOS	24		11-Nov-24	11-Nov-26		41 d	11-Nov-2026
	HRS	2400		3235.5	5635.5		2022.7	
	AFL							
Disposition: AIRWORTHINESS REF: NDT PART 6/56-20-01								
FAA 2008-02-19	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - INSPECT/REPLACE							AD ATA:72
	MOS							16-Nov-2026
	HRS							
	ENC	T:3300			(3300)3299		38	
Disposition: MANDATORY REF: AD								
FAA 2008-02-19	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - INSPECT/REPLACE							AD ATA:72
	MOS							16-Nov-2026
	HRS							
	ENC	T:3300			(3300)3299		38	
Disposition: MANDATORY REF: AD								
T1222004	NO. 2 MAIN BATTERY - LEAD-ACID BATTERIES - PERFORM BATTERY CAPACITY CHECK							Service ATA:12
PN:RG-380E/40L	MOS	T:12 (+1m/-1m)		26-Nov-25	26-Nov-26	26-Dec-26	56 d (+30)	26-Nov-2026(2)
SN:70059664	HRS			3404.3				
	AFL			3093				
	REF: AMM 12-22-00, CMM 24-30-71							
256109F	(ELT) EMERGENCY LOCATOR TRANSMITTER - RENEW REGISTRATION							Service ATA:25
PN:453-5000-366	MOS	24		21-Jan-25	06-Dec-26		66 d	06-Dec-2026
SN:170-08615	HRS			3262.2				
	AFL			2949				
	REF: MSC ELT REGISTRATION							
256109A	(ELT) EMERGENCY LOCATOR TRANSMITTER - PERFORM NATIONALY REQUIRED FUNCTIONAL TEST							Service ATA:25
PN:453-5000-366	MOS	12		11-Dec-25	11-Dec-26		71 d	11-Dec-2026
SN:170-08615	HRS			3411.6				
	AFL			3102				
	REF: AMM 25-62-00, FAR FAR 91.207							

Due List Report

Model: LEARJET 45 Serial: 45-400 RegNo: N145MW HRS: 3612.8 AFL: 3261 As Of:
02-Aug-2026 Operator: WHISKEY TANGO L.L.C.

Report Date: 01-Oct-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
256109B (ELT) EMERGENCY LOCATOR TRANSMITTER - INSPECT ELT BATTERIES								
PN:453-5000-366	MOS	12		11-Dec-25	11-Dec-26		71 d	11-Dec-2026
SN:170-08615	HRS			3411.6				
	AFL			3102				
REF: AMM 25-62-00, FAR FAR 91.207								
312011 PILOTS DAVTRON M850 DIGITAL CLOCK BATTERY								
PN:E90	MOS	12 (+14d/-14d)	TSN:0	11-Dec-25	11-Dec-26	25-Dec-26	71 d (+14)	11-Dec-2026
SN:NA	HRS		TSN:0	3411.6				
	AFL		TSN:0	3102				
Disposition: LIFE LIMIT REF: AMM 31-21-02								
312012 COPILOTS DAVTRON M850 DIGITAL CLOCK BATTERY								
PN:E90	MOS	12 (+14d/-14d)	TSN:0	11-Dec-25	11-Dec-26	25-Dec-26	71 d (+14)	11-Dec-2026
SN:NA	HRS		TSN:0	3411.6				
	AFL		TSN:0	3102				
Disposition: LIFE LIMIT REF: AMM 31-21-02								
AB2431062 EMERGENCY BATTERY - PERFORM CAPACITY CHECK								
PN:RG145-2	MOS	12		11-Dec-25	11-Dec-26		71 d	11-Dec-2026
SN:41368203	HRS	1000 (+100/-100)		3411.6	4411.6	4511.6	798.8 (+100)	
	AFL			3102				
REF:								
231021A TEST/INSPECT ATC TRANSPONDER								
	MOS	24		12-Dec-24	12-Dec-26		72 d	12-Dec-2026
	HRS			3258.5				
	AFL			2945				
REF: AMM 23-11-00, FAR FAR 91.413								
231022A TEST/INSPECT ATC TRANSPONDER								
	MOS	24		12-Dec-24	12-Dec-26		72 d	12-Dec-2026
	HRS			3258.5				
	AFL			2945				
REF: AMM 23-11-00, FAR FAR 91.413								
341001A TEST/INSPECT NO. 1 AIR DATA COMPUTER								
PN:7030700-71704	MOS	24		12-Dec-24	12-Dec-26		72 d	12-Dec-2026
SN:08112143	HRS			3258.5				
	AFL			2945				
REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP E								

Due List Report

Model: LEARJET 45 Serial: 45-400 RegNo: N145MW HRS: 3612.8 AFL: 3261 As Of:
02-Aug-2026 Operator: WHISKEY TANGO L.L.C.

Report Date: 01-Oct-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP E								
341002A		TEST/INSPECT NO. 2 AIR DATA COMPUTER						Service ATA:34
PN:7030700-71704	MOS	24		12-Dec-24	12-Dec-26		72 d	12-Dec-2026
SN:08112144	HRS			3258.5				
	AFL			2945				
REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP E								
341025A		TEST/INSPECT STANDBY ALTIMETER						Service ATA:34
PN:16650-1142	MOS	24		12-Dec-24	12-Dec-26		72 d	12-Dec-2026
SN:167843	HRS			3258.5				
	AFL			2944				
REF: FAR FAR 91.411, AMM 34-15-01, CFR 14 CFR PART 43 APP E								
341037A		LEFT PRIMARY PITOT/STATIC PROBE - PERFORM NATIONALLY REQUIRED EQUIPMENT TESTS AND INSPECTIONS						Service ATA:34
PN:0856TJ1	MOS	24		12-Dec-24	12-Dec-26		72 d	12-Dec-2026
SN:256862	HRS			3258.5				
	AFL			2945				
REF: GENERIC NO REF, FAR FAR 91.411, CFR 14 CFR PART 43 APP E								
341038A		RIGHT PRIMARY PITOT/STATIC PROBE - PERFORM NATIONALLY REQUIRED EQUIPMENT TESTS AND INSPECTIONS						Service ATA:34
PN:0856TJ2	MOS	24		12-Dec-24	12-Dec-26		72 d	12-Dec-2026
SN:256525	HRS			3258.5				
	AFL			2945				
REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP E								
341049A		TEST/INSPECT STANDBY PITOT/STATIC PROBE						Service ATA:34
	MOS	24		12-Dec-24	12-Dec-26		72 d	12-Dec-2026
	HRS			3258.5				
	AFL			2945				
REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP E								
L3411062		LEFT PRIMARY PITOT/STATIC PROBE - PERFORM DETAILED VISUAL INSPECTION						Service ATA:34
PN:0856TJ1	MOS	24 (+14d/-14d)		12-Dec-24	12-Dec-26	26-Dec-26	72 d (+14)	12-Dec-2026
SN:256862	HRS							
	AFL							
REF: AMM 34-11-01								
U3411060		AIR DATA SYSTEM - PERFORM FUNCTIONAL TEST						Service ATA:34
	MOS	24 (+14d/-14d)		12-Dec-24	12-Dec-26	26-Dec-26	72 d (+14)	12-Dec-2026
	HRS			3258.5				
	AFL			2945				
REF: AMM 34-17-00								

Due List Report

Model: LEARJET 45 Serial: 45-400 RegNo: N145MW HRS: 3612.8 AFL: 3261 As Of:
02-Aug-2026 Operator: WHISKEY TANGO L.L.C.

Report Date: 01-Oct-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
M3411052 LEFT PRIMARY PITOT/STATIC PROBE - VERIFY PITCH, ROLL, AND YAW ALIGNMENT Service ATA:34								
PN:0856TJ1	MOS	24 (+14d/-14d)		09-Jan-25	09-Jan-27	23-Jan-27	100 d (+14)	09-Jan-2027
SN:256862	HRS			3262.1				
	AFL			2948				
REF: AMM 34-11-01								
M5240004 AVIONIC ACCESS DOORS - PERFORM AVIONICS DOOR GAP AND MISMATCH INSPECTION Service ATA:52								
	MOS	24 (+14d/-14d)		09-Jan-25	09-Jan-27	23-Jan-27	100 d (+14)	09-Jan-2027
	HRS			3262.1				
	AFL			2948				
REF: AMM 52-40-01								
M5313001 FORWARD FUSELAGE SKIN - PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK Service ATA:53								
	MOS	24 (+14d/-14d)		09-Jan-25	09-Jan-27	23-Jan-27	100 d (+14)	09-Jan-2027
	HRS			3262.1				
	AFL			2948				
REF: AMM 53-00-01								
Z3020005 * NO. 1 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS. Service ATA:30								
	MOS			07-May-26				29-Mar-2027
	HRS	250		3510.2	3760.2		147.4	
	AFL			3178				
	APH							
Disposition: AIRWORTHINESS REF: AMM 30-20-00								
Z3020005 * NO. 2 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS. Service ATA:30								
	MOS			07-May-26				29-Mar-2027
	HRS	250		3510.2	3760.2		147.4	
	AFL			3178				
	APH							
Disposition: AIRWORTHINESS REF: AMM 30-20-00								
SB 45-57-16 WINGS - WING TANK DRAIN VALVE CORROSION INSPECTION, SERVICE BULLETIN Bulletin ATA:57								
	MOS	T:24		EFF	31-Mar-27 *		181 d	31-Mar-2027
	HRS							
	AFL							
Disposition: RECOMMENDED REF: BULLETINS								