CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Program Types

AIRCRAFT	**SERIAL/REGNO:**	510-0021 / N968W	**MODEL:**	510 - CITATION MUSTANG	**MANUFACTURER:**	TEXTRON AVIATION INC.
UTILIZATION:	MODERATE OR SEVERE CORROSION ENVIRONMENT					
OPERATING REGULATION:	N/A					
REGION OF OPERATION:	N/A					
OPTIONAL EQUIPMENT:	N/A					
ENGINE NO. 1	**SERIAL/PART:**	PCE-LB0039 / 35C0510 -01	**MODEL:**	PW615F-A	**MANUFACTURER:**	PRATT & WHITNEY CANADA CORP.
UTILIZATION:	N/A					
OPERATING REGULATION:	N/A					
REGION OF OPERATION:	N/A					
OPTIONAL EQUIPMENT:	N/A					
ENGINE NO. 2	**SERIAL/PART:**	PCE-LB0003 / 35C0510 -01	**MODEL:**	PW615F-A	**MANUFACTURER:**	PRATT & WHITNEY CANADA CORP.
UTILIZATION:	N/A					
OPERATING REGULATION:	N/A					
REGION OF OPERATION:	N/A					
OPTIONAL EQUIPMENT:	N/A					

These program types are defined in the OEM manual and can differ from your other settings. These selections will impact the active OEM interval defined on the aircraft status.

As an example,

1. Your aircraft might be EASA registered but you choose to follow the OEM recommended interval for Transport Canada. In that case the operating regulation would be TCCA and can be set to EASA if OEM did not specify intervals for EASA operation.
2. Region of Operation is driven from the OEM manual and the selection between Airframe, Engine and APU can differ since the OEM manual can have requirements dependent on different regions of operation.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Maintenance Inspections

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
AIRWORTHINESS	CONTINUED AIRWORTHINESS OF THE AIRFRAME VALIDATION				MTH						
					HRS			25000		25000	21844.2
					LDG			25000		25000	21986
0534NXI	INSP/CHECK G1000 NXI UPGRADE STC SA01896WI (XPONDER 91.413)				MTH	20-Oct-2026		24		31-Oct-2028	23 m 21 d
					HRS	3145.5					
					LDG	3010					
055001	ACCOMPLISH HARD/OVERWEIGHT LANDINGS CHECK							A/R			
055002	ACCOMPLISH OVERSPEED CHECK							A/R			
055003	ACCOMPLISH DANGEROUS AIR TURBULANCE CHECK							A/R			
055004	ACCOMPLISH LIGHTNING STRIKE CHECK							A/R			
055005	ACCOMPLISH FOREIGN OBJECT DAMAGE CHECK							A/R			
055006	ACCOMPLISH TOWING WITH FUEL UNBALANCE OR HIGH DRAG/SIDE LOADS CHECK							A/R			
055007	ACCOMPLISH TOWING BEYOND MECHANICAL LIMITS WITH GUST LOCK ENGAGED CHECK							A/R			
055008	ACCOMPLISH TOWING BEYOND MECHANICAL LIMITS WITH GUST LOCK DISENGAGED CHECK							A/R			
5-12-01	INSPECTION DOCUMENT 01				MTH	18-Nov-2025					
051201		KGJT			HRS	3075.3		450		3525.3	369.5
					LDG	2967					
5-12-02	INSPECTION DOCUMENT 02				MTH	15-Aug-2022					
051202		KGMU			HRS	2660.1		900		3560.1	404.3
					LDG	2592					
5-12-03	INSPECTION DOCUMENT 03				MTH	15-Aug-2022					
051203		KGMU			HRS	2660.1		1350		4010.1	854.3
					LDG	2592					
5-12-04	INSPECTION DOCUMENT 04				MTH	06-Feb-2018					
051204		KAQW			HRS	1771		1800		3571	415.2
					LDG	1411					
5-12-05	INSPECTION DOCUMENT 05				MTH	18-Nov-2025					
051205		KGJT			HRS	3075.3		3150		6225.3	3069.5
					LDG	2967					
5-12-06	INSPECTION DOCUMENT 06				MTH	16-Jun-2026		12		30-Jun-2027	7 m 20 d
051206		KGJT			HRS	3110.9					
					LDG	2986					
B262100	FUNCTIONAL CHECK PORTABLE FIRE EXTINGUISHER (WEIGHT CHECK)										
		KGJT		C352TS	MTH	16-Jun-2026		12		30-Jun-2027	7 m 20 d
				I-58082085	HRS	3110.9					
					LDG	2986					
5-12-07	INSPECTION DOCUMENT 07				MTH	18-Nov-2025		24		30-Nov-2027	12 m 20 d
051207		KGJT			HRS	3075.3					
					LDG	2967					

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Maintenance Inspections

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
5-12-10	INSPECTION DOCUMENT 10 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)										
		KGJT			MTH	16-Jun-2026		60			
					HRS	3110.9					
					LDG	2986					
B262004	RESTORATION FIRE EXTINGUISHER BOTTLE (HYDROSTATIC TEST)										
051210 : FB		KGJT		30401102-2	MTH	16-Jun-2026		60		30-Apr-2031	53 m 20 d
				55737B1	HRS	3110.9					
					LDG	2986					
Hydro Check Date: 20-Apr-2026											
5-12-11	INSPECTION DOCUMENT 11				MTH	18-Nov-2025		72		30-Nov-2031	60 m 20 d
051211		KGJT			HRS	3075.3					
					LDG	2967					
A262100	RESTORATION PORTABLE FIRE EXTINGUISHER (INTERNAL INSPECTION)										
		KGJT		C352TS	MTH	18-Nov-2025		72		30-Nov-2031	60 m 20 d
				I-58082085	HRS	3075.3					
					LDG	2967					
5-12-12	INSPECTION DOCUMENT 12 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)										
					MTH	01-Oct-2019		144			
B262101	RESTORATION PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST)										
051212		KGJT		C352TS	MTH	18-Nov-2025		144		30-Nov-2037	132 m 20 d
				I-58082085	HRS	3075.3					
					LDG	2967					
Hydro Check Date: 03-Nov-2025											
5-12-13	INSPECTION DOCUMENT 13				MTH	16-Jun-2026		12		30-Jun-2027	7 m 20 d
051213		KGJT			HRS	3110.9		450		3560.9	405.1
					LDG	2986					
5-12-14	INSPECTION DOCUMENT 14				MTH	16-Jun-2026		12		30-Jun-2027	7 m 20 d
051214		KGJT			HRS	3110.9		900		4010.9	855.1
					LDG	2986					
5-12-15	INSPECTION DOCUMENT 15				MTH	18-Nov-2025		24		30-Nov-2027	12 m 20 d
051215		KGJT			HRS	3075.3		1350		4425.3	1269.5
					LDG	2967					
5-12-16	INSPECTION DOCUMENT 16				MTH	18-Nov-2025		36		30-Nov-2028	24 m 20 d
051216		KGJT			HRS	3075.3		1350		4425.3	1269.5
					LDG	2967					
B291001	HYDRAULIC PACK ASSEMBLY (LEAK) FUNCTIONAL CHECK TASK 29-10-00-720										
		KGJT		HM50C-3	MTH	18-Nov-2025		36		30-Nov-2028	24 m 20 d
				044B	HRS	3075.3		1350		4425.3	1269.5
					LDG	2967					
5-12-17	INSPECTION DOCUMENT 17				MTH	18-Nov-2025		36		30-Nov-2028	24 m 20 d
051217		KGJT			HRS	3075.3		1800		4875.3	1719.5
					LDG	2967					
5-12-18	INSPECTION DOCUMENT 18				MTH	18-Nov-2025		36		30-Nov-2028	24 m 20 d
051218		KGJT			HRS	3075.3		2250		5325.3	2169.5
					LDG	2967					
5-12-20	INSPECTION DOCUMENT 20				MTH	09-Nov-2023		48		30-Nov-2027	12 m 20 d
051220		UNK			HRS	2897.6		2700		5597.6	2441.8
5-12-21	INSPECTION DOCUMENT 21				MTH	20-Oct-2026		12		31-Oct-2027	11 m 21 d
051221					HRS	3145.5					
					LDG	3010					
5-12-22	INSPECTION DOCUMENT 22 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)										
					MTH	20-Oct-2026		24			
					HRS	3145.5					
					LDG	3010					
051222	INSPECT DOCUMENT 22 (B341001)				MTH	20-Oct-2026		24		31-Oct-2028	23 m 21 d
RVSM					HRS	3145.5					
					LDG	3010					

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Maintenance Inspections

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
B341001	CALIBRATION TEST INDICATOR 14 CFR PART 91.411				MTH	20-Oct-2026		24		31-Oct-2028	23 m 21 d
AIRSPEED				261440-1143	HRS	3145.5					
051222 : A/S				286403A	LDG	3010					
Calibration Date: 20-Oct-2026											
B341001	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411										
NO. 1				011-01110-00	MTH	20-Oct-2026		24		31-Oct-2028	23 m 21 d
051222 : ADC				43800392	HRS	3145.5					
					LDG	3010					
Calibration Date: 20-Oct-2026											
B341001	CALIBRATION TEST GDC 74B AIRDATA SYSTEM 14 CFR PART 91.411										
NO. 2				011-01110-00	MTH	20-Oct-2026		24		31-Oct-2028	23 m 21 d
051222 : ADC#2				43800429	HRS	3145.5					
					LDG	3010					
Calibration Date: 20-Oct-2026											
B341001	CALIBRATION TEST ALTIMETER 14 CFR PART 91.411				MTH	20-Oct-2026		24		31-Oct-2028	23 m 21 d
STANDBY				162350-1161	HRS	3145.5					
051222 : STDBY				1001194C	LDG	3010					
Calibration Date: 20-Oct-2026											
B341001	FUNCTIONAL CHECK PITOT-STATIC SYSTEM (AIRPLANES WITH AIR DATA COMPUTER P/N 011-01110-00 OR 011-01110-01)										
					MTH	20-Oct-2026		24		31-Oct-2028	23 m 21 d
					HRS	3145.5					
					LDG	3010					
B345000	CALIBRATION TEST TRANSPONDER 14 CFR PART 91.413				MTH	20-Oct-2026		24		31-Oct-2028	23 m 21 d
LEFT				011-00779-21	HRS	3145.5					
051222 : XPDR1				84801127	LDG	3010					
Calibration Date: 20-Oct-2026											
B345000	G1000 NXI UPGRADE STC SA01896WI (XPNDR 91.413)				MTH	20-Oct-2026		24		31-Oct-2028	23 m 21 d
RIGHT				011-03303-00	HRS	3145.5					
051222 : XPDR2				3EH025027	LDG	3010					
Calibration Date: 20-Oct-2026											
5-12-23	INSPECTION DOCUMENT 23 (NOT USED)				MTH	19-Sep-2012		N/R			
051223		KAQW			HRS	635.8					
					LDG	510					
B324000	DETAILED INSPECTION MAIN LANDING GEAR WHEEL SPECIAL (NDI)										
LEFT		GSO		3-1640	MTH	16-Jun-2024		A/R			
				0048	HRS	2928.5					
					LDG	2890					
B324000	DETAILED INSPECTION NOSE LANDING GEAR WHEEL SPECIAL (NDI)										
NOSE		GSO		3-1642	MTH	16-Jun-2024		A/R			
				0032	HRS	2928.5					
					LDG	2890					
B324000	DETAILED INSPECTION MAIN LANDING GEAR WHEEL SPECIAL (NDI)										
RIGHT		GSO		3-1640	MTH	16-Jun-2024		A/R			
				0036	HRS	2928.5					
					LDG	2890					
5-12-30	INSPECTION DOCUMENT 30				MTH	09-Nov-2023		48		30-Nov-2027	12 m 20 d
051230		UNK			HRS	2897.6		1800		4697.6	1541.8
5-12-31	INSPECTION DOCUMENT 31				MTH	18-Nov-2025					
051231		KGJT			HRS	3075.3		450		3525.3	369.5
					LDG	2967					
5-12-32	INSPECTION DOCUMENT 32				MTH	05-Oct-2020		72		31-Oct-2026	-10 d
051232		KGYH			HRS	2276.8					
					LDG	1881		1800		3681	667
											Over Due

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Maintenance Inspections

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
5-12-35	INSPECTION DOCUMENT 35	KGJT			MTH HRS LDG	16-Jun-2026 3110.9 2986		6		31-Dec-2026	1 m 21 d
5-12-37	INSPECTION DOCUMENT 37	KAQW			MTH HRS LDG	16-Dec-2016 1521.9 1252		7200		8721.9	5566.1
5-12-38	INSPECTION DOCUMENT 38 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KGJT			MTH HRS LDG	16-Jun-2026 3110.9 2986		6			
B243000 *051224B*	CONCORDE (RG-390E) LEAD-ACID BATTERY FUNCTIONALCHECK (CAPACITY CHECK)	KGJT		RG-390E/30 41473114	MTH HRS LDG	16-Jun-2026 3110.9 2986		6		31-Dec-2026	1 m 21 d
5-12-39	INSPECTION DOCUMENT 39				MTH HRS	16-Aug-2007 0		11700		11700	8544.2
5-12-40	INSPECTION DOCUMENT 40				MTH HRS	16-Aug-2007 0		10500		10500	7344.2
5-12-41	INSPECTION DOCUMENT 41				MTH HRS	16-Aug-2007 0		15300		15300	12144.2
5-12-MA *0512MA*	INSPECTION DOCUMENT MA	KGMU			MTH HRS LDG	05-May-2023 2815.6 2751		500		3315.6	159.8
5-12-MB *0512MB*	INSPECTION DOCUMENT MB	KGMU			MTH HRS LDG	13-Dec-2022 2729.4 2655		950		3679.4	523.6
5-12-MC *0512MC*	INSPECTION DOCUMENT MC	*CF			MTH HRS	16-Aug-2007 0		4000		4000	844.2
5-12-ME *0512ME*	INSPECTION DOCUMENT ME	KGJT			MTH HRS LDG	18-Nov-2025 3075.3 2967		36 1400		30-Nov-2028 4475.3	24 m 20 d 1319.5
5-12-MF *0512MF*	INSPECTION DOCUMENT MF	*CF			MTH HRS	16-Aug-2007 0		12000		12000	8844.2
5-12-MG *0512MG*	INSPECTION DOCUMENT MG	*CF			MTH HRS	16-Aug-2007 0		5000		5000	1844.2
5-12-MH *0512MH*	INSPECTION DOCUMENT MH	*CF			MTH HRS			23850		23850	20694.2
5-12-ML	INSPECTION DOCUMENT ML				MTH HRS			15750		15750	12594.2
5-12-MM	INSPECTION DOCUMENT MM				MTH HRS			8550		8550	5394.2
5-12-MN	INSPECTION DOCUMENT MN				MTH HRS			20250		20250	17094.2
5-12-MO	INSPECTION DOCUMENT MO				MTH HRS			15750		15750	12594.2
5-12-MP	INSPECTION DOCUMENT MP				MTH HRS			14400		14400	11244.2
5-12-MQ	INSPECTION DOCUMENT MQ				MTH HRS			11250		11250	8094.2
5-12-MR	INSPECTION DOCUMENT MR				MTH HRS			13500		13500	10344.2
5-12-MS	INSPECTION DOCUMENT MS				MTH HRS			20250		20250	17094.2
5-12-MT	INSPECTION DOCUMENT MT				MTH HRS			13500		13500	10344.2
5-12-MU	INSPECTION DOCUMENT MU				MTH HRS			20250		20250	17094.2

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Maintenance Inspections

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
5-12-MV	INSPECTION DOCUMENT MV				MTH HRS			 13950		 13950	 10794.2
5-12-MW	INSPECTION DOCUMENT MW				MTH HRS			 22500		 22500	 19344.2
5-12-MX	INSPECTION DOCUMENT MX				MTH HRS			 15750		 15750	 12594.2
5-12-MY	INSPECTION DOCUMENT MY				MTH HRS			 22050		 22050	 18894.2
12-26-00-601	15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH	KGMU			DAYS HRS LDG	30-Aug-2019 2069.2 1659		A/R			
12-26-00-602	45 DAY MEDIUM EXPOSURE AREAS - AIRPLANE ZONE 2 WASH	KGMU			DAYS HRS LDG	30-Aug-2019 2069.2 1659		A/R			
12-26-00-603	90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH	KGMU			DAYS HRS LDG	07-Aug-2019 2064.9 1657		A/R			
262003A LEFT *262003 : L*	REPLACE FIRE EXT CARTRIDGE	KGMU		13083-5 ESD26E057-001	MTH HRS LDG	16-Jun-2026 3110.9 2986		72	1	31-May-2032	66 m 21 d
262003A RIGHT *262003 : R*	REPLACE FIRE EXT CARTRIDGE	KGMU		13083-5 ESD26E057-001	MTH HRS LDG	16-Jun-2026 3110.9 2986		72	1	31-May-2032	66 m 21 d
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)	KGMU			MTH HRS LDG	30-Aug-2019 2069.2 1659		A/R			
28-00-02-221	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)				MTH	16-Aug-2007		A/R			
32-30-40-960 *051208 : LG*	RESTORATION LANDING GEAR EMERGENCY PNEUMATIC BOTTLE (HYDROSTATIC TEST)	GSO		40005369-2 6625	MTH HRS LDG	23-May-2024 2928.5 2890		36		31-May-2027	6 m 21 d
Hydro Check Date: 23-May-2024											
32-40-00-960 *051208 : EB*	RESTORATION EMERGENCY BRAKE PNEUMATIC BOTTLE (HYDROSTATIC TEST)	KGJT		40005399-1 6234	MTH	05-Mar-2024		36		31-Mar-2027	4 m 21 d
Hydro Check Date: 05-Mar-2024											
35-00-00-960 *051210 : OXY*	RESTORATION OXYGEN BOTTLE HYDROSTATIC TEST	KGJT		4441073-040 0751-230	MTH	28-Jun-2024		60		30-Jun-2029	31 m 20 d
Hydro Check Date: 28-Jun-2024											
710010A	DESALINATION WASH / RINSE							A/R			
052001 E1	ENGINE 450 HOUR/ 12 MONTH INSPECTION	KGJT			MTH HRS LDG	16-Jun-2026 3110.9 2986		12 450		30-Jun-2027 (3560.9)3560.9	7 m 20 d 405.1
052001 E2	ENGINE 450 HOUR/ 12 MONTH INSPECTION	KGJT			MTH HRS LDG	16-Jun-2026 3110.9 2986		12 450		30-Jun-2027 (2862.6)3560.9	7 m 20 d 405.1

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Maintenance Inspections

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
710005A E1	VISUAL INSPECTION OF THE #1 ENGINE ABRAIDABLE LINER	BTV			MTH HRS LDG	08-Dec-2017 1752.6 1398		1750		(3502.6)3502.6	346.8
710010 E1	COMPRESSOR DESALINATION WASH	KGJT			MTH HRS LDG	18-Nov-2025 3075.3 2967		A/R			
SEE ENGINE MANUFACTURER FOR COMPRESSOR WASH REQUIREMENTS.											
710010 E2	COMPRESSOR DESALINATION WASH	KGJT			MTH HRS LDG	18-Nov-2025 3075.3 2967		A/R			
710010A E1	DESALINATION WASH / RINSE	SWF			MTH HRS LDG	12-Dec-2011 418.6 262		A/R			
710010A E2	DESALINATION WASH / FRESH WATER RINSE							A/R			
72-00-00-620-804-01 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS				MTH	16-Aug-2007		A/R			
72-00-00-620-804-01 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS				MTH	13-Apr-2007		A/R			
72-00-00-620-804-02 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)				MTH	16-Aug-2007		A/R			
72-00-00-620-804-02 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)				MTH	13-Apr-2007		A/R			
72-00-00-620-804-03 E1	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)				MTH	16-Aug-2007		A/R			
72-00-00-620-804-03 E2	ALTERNATIVE PRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)				MTH	13-Apr-2007		A/R			
72-00-00-620-805-01 E1	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS				MTH	16-Aug-2007		A/R			
72-00-00-620-805-01 E2	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 14 DAYS				MTH	13-Apr-2007		A/R			
72-00-00-620-805-02 E1	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 28 DAYS				MTH	16-Aug-2007		A/R			
72-00-00-620-805-02 E2	PRESERVATION FOR UNPRESERVED INACTIVE ON-WING ENGINES - 1 TO 28 DAYS				MTH	13-Apr-2007		A/R			
72-00-00-620-806-01 E1	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 TO 90 DAYS				MTH	16-Aug-2007		A/R			
72-00-00-620-806-01 E2	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 0 TO 90 DAYS				MTH	13-Apr-2007		A/R			
72-00-00-620-806-02 E1	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER				MTH	16-Aug-2007		A/R			

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Maintenance Inspections

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
72-00-00-620-806-02 E2	PRESERVATION FOR ENGINES AT A SERVICE FACILITY - 91 DAYS AND OVER				MTH 13-Apr-2007		A/R			
72-00-00-630-804-01 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS				MTH 16-Aug-2007		A/R			
72-00-00-630-804-01 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 14 DAYS				MTH 13-Apr-2007		A/R			
72-00-00-630-804-02 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)				MTH 16-Aug-2007		A/R			
72-00-00-630-804-02 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED IN A HANGAR)				MTH 13-Apr-2007		A/R			
72-00-00-630-804-03 E1	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)				MTH 16-Aug-2007		A/R			
72-00-00-630-804-03 E2	ALTERNATIVE DEPRESERVATION FOR INACTIVE IN-SERVICE ENGINES - 1 TO 28 DAYS (STORED OUTSIDE)				MTH 13-Apr-2007		A/R			
72-00-00-630-805-01 E1	DEPRESERVATION FOR ENGINES AT A SERVICE FACILITY				MTH 16-Aug-2007		A/R			
72-00-00-630-805-01 E2	DEPRESERVATION FOR ENGINES AT A SERVICE FACILITY				MTH 13-Apr-2007		A/R			
720000 E1	PERFORM ENGINE OVERHAUL				MTH 16-Aug-2007 HRS 0		3500		(3500)3500	344.2
720000 E2	PERFORM ENGINE OVERHAUL				MTH 13-Apr-2007 HRS 698.3		3500		(3500)4198.3	1042.5
720001 E1	PERFORM ENGINE HOT SECTION INSPECTION	BTV			MTH 08-Dec-2017 HRS 1752.6 ENC 1282		1750		(3502.6)3502.6	346.8
720001 E2	PERFORM ENGINE HOT SECTION INSPECTION	KICT			MTH 22-Nov-2021 HRS 2486 LDG 2111		1750		(3537.7)4236	1080.2
720003 E1	INSPECT LOW UTILIZATION ENGINE	KGJT			MTH 24-Jun-2025 HRS 3022.9 LDG 2940		24		30-Jun-2027	7 m 20 d
720003 E2	INSPECT LOW UTILIZATION ENGINE	KGJT			MTH 24-Jun-2025 HRS 3022.9 LDG 2940		24		30-Jun-2027	7 m 20 d
721030 E1	HP TURBINE RETAINING NUT KEY WASHER - REMOVE, DISCARD AND REPLACE KEYWASHER				MTH HRS		1750		(3502.6)3502.6	346.8
721030 E2	HP TURBINE RETAINING NUT KEY WASHER - REMOVE, DISCARD AND REPLACE KEYWASHER				MTH HRS		1750		(3537.7)4236	1080.2
726040 E1	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER	BTV			MTH 08-Dec-2017 HRS 1752.6 LDG 1398		1750		(3502.6)3502.6	346.8
726040 E2	REPLACE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER	KICT			MTH 22-Nov-2021 HRS 2486 LDG 2111		1750		(3537.7)4236	1080.2

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Maintenance Inspections

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
731020	CHECK AND REPLACE FUEL FILTER ELEMENT				MTH	16-Jun-2026		12		30-Jun-2027	7 m 20 d
E1		KGJT			HRS	3110.9		900		(4010.9)4010.9	855.1
					LDG	2986					
731020	CHECK AND REPLACE FUEL FILTER ELEMENT				MTH	16-Jun-2026		12		30-Jun-2027	7 m 20 d
E2		KGJT			HRS	3110.9		900		(3312.6)4010.9	855.1
					LDG	2986					
731055	REPLACE FUEL MANIFOLD			35C6160-01	MTH	08-Dec-2017					
E1		BTV		DEAAAA39742	HRS	1752.6		1750		(3502.6)3502.6	346.8
					LDG	1398					
731055	REPLACE FUEL MANIFOLD			PN	MTH	22-Nov-2021					
E2		KICT		SN-UNKNOWN	HRS	2486		1750		(3537.7)4236	1080.2
					LDG	2111					
733020	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH										
E1		UNK		35C3388-01	MTH	08-Dec-2017					
				SN-UNKNOWN	HRS	1752.6		1750		(3502.6)3502.6	346.8
					LDG	1398					
733020	FUNCTIONAL TEST FUEL FILTER IMPENDING BYPASS SWITCH										
E2		KICT		35C3388-01	MTH	22-Nov-2021					
				WDA100997	HRS	2486		1750		(3537.7)4236	1080.2
					LDG	2111					
772001	FUNCTIONAL TEST OF THE T6 WIRING HARNESS AND ASSEMBLY										
E1		BTV		PN	MTH	08-Dec-2017					
				SN-UNKNOWN	HRS	1752.6		1750		(3502.6)3502.6	346.8
					LDG	1398					
772001	FUNCTIONAL TEST OF THE T6 WIRING HARNESS AND ASSEMBLY										
E2		KICT		PN	MTH	22-Nov-2021					
				SN-UNKNOWN	HRS	2486		1750		(3537.7)4236	1080.2
					LDG	2111					
790010	CHANGE ENGINE OIL/MONITOR /ANALYZE OIL QUALITY				MTH	07-Mar-2012		O/C			
E1		KAQW			HRS	491.4					
					LDG	345					
790010	CHANGE ENGINE OIL/MONITOR /ANALYZE OIL QUALITY				MTH	30-Jun-2010		O/C			
E2		KBDN			HRS	1017					
					LDG	645					
790015	REPLACE OIL FILTER ELEMENT				MTH	15-Aug-2022					
E1		KGMU			HRS	2660.1		900		(3560.1)3560.1	404.3
					LDG	2592					
790015	REPLACE OIL FILTER ELEMENT				MTH	15-Aug-2022					
E2		KGMU			HRS	2660.1		900		(2862.7)3560.1	404.3
					LDG	2592					
793015	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS										
E1		KGJT		PN	MTH	16-Jun-2026		6		31-Dec-2026	1 m 21 d
				SN-UNKNOWN	HRS	3110.9		100		(3210.9)3210.9	55.1
					LDG	2986					
793015	REMOVE CHIP COLLECTOR AND EXAMINE FOR METALLIC DEBRIS										
E2		KGJT		35C0412-01	MTH	16-Jun-2026		6		31-Dec-2026	1 m 21 d
				AB0029	HRS	3110.9		100		(2512.6)3210.9	55.1
					LDG	2986					
794020	REPLACE NO. 4 BEARING FRONT CARBON SEAL				MTH	08-Dec-2017					
E1		BTV			HRS	1752.6		1750		(3502.6)3502.6	346.8
					LDG	1398					
794020	REPLACE NO. 4 BEARING FRONT CARBON SEAL				MTH	22-Nov-2021					
E2		KICT			HRS	2486		1750		(3537.7)4236	1080.2
					LDG	2111					

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
212002	UNDER FLOOR BLOWER ASSY.	*CF		0113-12 1120	MTH	16-Aug-2007		O/C			
213001	KAPS II CONTROLLER 9912661-6	*CF		52811-102 855	MTH	16-Aug-2007		O/C			
213002 NO. 1	KAPS II OUTFLOW VALVE 9912661-7	KAQW		52812-102 926	MTH HRS LDG	04-Dec-2015 1252.8 1016		O/C	3 0 0		
213002 NO. 2	KAPS II OUTFLOW VALVE 9912661-7	KAQW		52812-102 843	MTH HRS LDG	04-Dec-2015 1252.8 1016		O/C			
215001	AIR CONDITIONING COMPRESSOR MODULE 9912660-14	KAQW		1133610-4 410	MTH HRS LDG	24-Apr-2018 1826.2 1452		O/C			
215002	CONDENSOR ASSEMBLY 9912660-3	UNK		1134620-5 933	MTH HRS	14-Apr-2020 2206.5		O/C	0 0		
215003	RECEIVER DRYER ASSY 9912583-3	*CF		1134275-1 1353	MTH	16-Aug-2007		O/C			
215004 NO. 1	(BRUSHLESS) EVAPORATOR 9912660-7	*CF		1133300-1 178	MTH	16-Aug-2007		O/C			
215004 NO. 2	(BRUSHLESS) EVAPORATOR 9912660-7	*CF		1133300-1 177	MTH	16-Aug-2007		O/C			
215005	VANE AXIAL BLOWER ASSY.	KAQW		1250435-5 3382	MTH HRS LDG	14-Jul-2016 1421.4 1170		O/C	1 0 0		
215006A	COMPRESSOR DRIVE BELT	KGJT		5MR535-25 NA	MTH HRS LDG	24-Jun-2025 3022.9 2940		O/C	0 0 0		
215008	COMPRESSOR DRIVE MOTOR BRUSHES DISCARD			PN SN-UNKNOWN	MTH HRS LDG ACH	24-Apr-2018 1826.2 1452 0		 800	0 0 0 0	800	621.8
221001 AILERON	GSA 80 TORQUE SERVO	*CF		011-00877-00 66301033	MTH	16-Aug-2007		O/C			
221001 RUDDER	GSA 80 TORQUE SERVO	KGYH		011-00877-00 66308001	MTH HRS LDG	01-Jul-2019 2047.7 1647		O/C	0 0		
221002 ELEVATOR	GSA 81 TORQUE SERVO	KGYH		011-00878-10 71308561	MTH HRS LDG	05-Nov-2018 1939.4 1542		O/C	0 0 0		
221002 ELEVATOR TRIM	TAB GSA 81 TORQUE SERVO	DUS		011-00878-10 71306972	MTH HRS LDG	17-Aug-2011 402 255		O/C	1 0 0		
221003 AILERON	GSM 85A SERVO MOUNT	*CF		011-01436-A2 10900136	MTH	16-Aug-2007		O/C			
221003 ELEVATOR	GSM 85A SERVO MOUNT	KGYH		011-01436-A0 11205102	MTH HRS LDG	05-Nov-2018 1939.4 1542		O/C	0 0 0		
221003 ELEVATOR TRIM	GSM 85A SERVO MOUNT	*CF		011-01436-A1 11300125	MTH	16-Aug-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
221003 RUDDER	GSM 85 SERVO MOUNT	*CF		011-01436-A3 11000149	MTH	16-Aug-2007		O/C			
221004	GMC 710 AFCS CONTROLLER	UNK		011-01020-00 87805175	MTH	14-Feb-2012		O/C	17		
231002 NO. 1	NO. 1 GARMIN GMA 1360D AUDIO PANEL WITH BLUE TOOTH	KGSO		011-03568-20 4QF105527	MTH HRS LDG	24-Oct-2019 2093.6 1681		O/C	0 0 0		
231002 NO. 2	NO. 2 GARMIN GMA 1360D AUDIO PANEL WITH BLUE TOOTH	KGSO		011-03568-20 4QF105533	MTH HRS LDG	24-Oct-2019 2093.6 1681		O/C	0 0 0		
231003 NO. 1	VHF COMM ANTENNA	*CF		VHF10-829 0078	MTH	16-Aug-2007		O/C			
231003 NO. 2	VHF COMM ANTENNA	*CF		VHF10-829 0084	MTH	16-Aug-2007		O/C			
243001 LEFT	DIGITAL GCU 9912682-1	KDXR		GCSG550-4 1078H	MTH HRS LDG	14-Sep-2017 1693.4 1368		O/C	1693.4		
243001 RIGHT	DIGITAL GCU 9912682-1	KDXR		GCSG550-4 1079H	MTH HRS LDG	14-Sep-2017 1693.4 1368		O/C	1693.4		
243002	EMER INST BATTERY	GSO		CBS24 00899	MTH HRS LDG	16-Jun-2024 2928.5 2890		O/C			
243007	MAIN SHIP BATTERY CONCORDE (LEAD ACID)	KGJT		RG-390E/30 41473114	MTH HRS LDG	18-Nov-2025 3075.3 2967		O/C	0 0 0		
243015	RELAY DISCONNECT BATTERY S3155-1	*CF		A-931F CN-79399	MTH	16-Aug-2007		O/C			
245002 LEFT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY	*CF		7018920-5 0128	MTH	16-Aug-2007		O/C			
245002 RIGHT	PCB ASSEMBLY - FUEL CONTROL ASSEMBLY	*CF		7018920-5 0152	MTH	16-Aug-2007		O/C			
245003	FLAP CONTROL MODULE	*CF		7018916-9 0139	MTH	16-Aug-2007		O/C			
245005 LEFT	ICE PROTECTION CONTROL	*CF		7018917-9 0118	MTH	16-Aug-2007		O/C			
245005 RIGHT	ICE PROTECTION CONTROL	*CF		7018918-13 0129	MTH	16-Aug-2007		O/C			
245006 LEFT	COCKPIT/CABIN ENVIROMENTAL CONTROL	*CF		7018919-9 0137	MTH	16-Aug-2007		O/C			
245006 RIGHT	COCKPIT/CABIN ENVIROMENTAL CONTROL	*CF		7018919-9 0125	MTH	16-Aug-2007		O/C			
245008	DOOR MONITOR-	*CF		7018921-5 0128	MTH	16-Aug-2007		O/C			
245009	LANDING GEAR MONITOR-	*CF		7018923-10 0126	MTH	16-Aug-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
245010 LEFT	START CONTROL	*CF		7018924-5 0131	MTH	16-Aug-2007		O/C			
245010 RIGHT	START CONTROL	*CF		7018924-5 0144	MTH	16-Aug-2007		O/C			
245011	FLAP MONITOR-	*CF		7018925-11 0122	MTH	16-Aug-2007		O/C			
245012 LEFT	SPEEDBRAKE ASSY	*CF		7018926-1 0175	MTH	16-Aug-2007		O/C			
245012 RIGHT	SPEEDBRAKE ASSY	*CF		7018926-1 0187	MTH	16-Aug-2007		O/C			
245013	DIAGNOSTIC UNIT	*CF		7018927-7 0145	MTH	16-Aug-2007		O/C			
245014	FUEL FLOW SIGNAL PCB UNIT 9912417-3	*CF		85-230-2 NSN	MTH	16-Aug-2007		O/C			
245015	MASTER INTERIOR SSR UNIT UZ100	*CF		10747P03E25 07041610	MTH	16-Aug-2007		O/C			
245016 RIGHT	AVN BUS #1 SENSOR UZ102	*CF		10747P03E25 07041612	MTH	16-Aug-2007		O/C			
245017 LEFT	AVN SENSOR UZ103	*CF		10747P03E25 07041603	MTH	16-Aug-2007		O/C			
245018 RIGHT	AVN BUS #2 SENSOR UZ104	*CF		10747P03E25 07041640	MTH	16-Aug-2007		O/C			
245019 LEFT	IGN #1 SENSOR UZ105	*CF		10747P03E10 07041807	MTH	16-Aug-2007		O/C			
245019 RIGHT	IGN #1 SENSOR UZ106	*CF		10747P03E10 07041688	MTH	16-Aug-2007		O/C			
245020 LEFT	IGN #2 SENSOR UZ107	*CF		10747P03E10 07041805	MTH	16-Aug-2007		O/C			
245020 RIGHT	IGN #2 SENSOR UZ108	*CF		10747P03E10 07041797	MTH	16-Aug-2007		O/C			
245021	COCKPIT FAN SENSOR UZ109	*CF		10747P03E25 07041627	MTH	16-Aug-2007		O/C			
245022	CABIN FAN SENSOR UZ110	*CF		10747P03E25 07041600	MTH	16-Aug-2007		O/C			
245023 LEFT	LH BOOST PUMP SENSOR UZ114	*CF		10747P03E25 07041632	MTH	16-Aug-2007		O/C			
245023 RIGHT	RH BOOST PUMP SENSOR UZ111	*CF		10747P03E25 07041663	MTH	16-Aug-2007		O/C			
245024	CONDENSER FAN SENSOR UZ112	*CF		10747P03E25 07041618	MTH	16-Aug-2007		O/C			
245025	DC-DC CONVERTER UZ116	*CF		10747P03E10 07041808	MTH	16-Aug-2007		O/C			
245026	AVN EMERG SENSOR UZ200	*CF		10747P03E25 07041642	MTH	16-Aug-2007		O/C			
251001	GLARESHIELD ASSEMBLY	*CF		4319027-13 93383-1	MTH	16-Aug-2007		O/C			
256001 CARGO NO1	LIFE VEST	KGMU		P01074-207 11051390077	MTH HRS LDG	29-Jun-2021 2410.5 2018		120	0	30-Jun-2031	55 m 20 d
256001 CARGO NO 2	LIFE VEST	KGMU		P01074-207 11051390078	MTH HRS LDG	29-Jun-2021 2410.5 2018		120	0	30-Jun-2031	55 m 20 d
256001 NO. 1 *256001A : 1*	LIFE VEST	KGMU		P01074-207 11051390079	MTH HRS LDG	29-Jun-2021 2410.5 2018		120	0	30-Jun-2031	55 m 20 d
256001 NO. 2 *256001A : 2*	LIFE VEST	KGMU		P01074-207 11051390083	MTH HRS LDG	29-Jun-2021 2410.5 2018		120	0	30-Jun-2031	55 m 20 d

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
256001 NO. 3 *256001A : 3*	LIFE VEST	KGMU		P01074-207 11051390084	MTH HRS LDG	29-Jun-2021 2410.5 2018		120	0	30-Jun-2031	55 m 20 d
256001 NO. 4 *256001A : 4*	LIFE VEST	KGMU		P01074-207 11051390080	MTH HRS LDG	29-Jun-2021 2410.5 2018		120	0	30-Jun-2031	55 m 20 d
256001 NO. 5 *256001A : 5*	LIFE VEST	KGMU		P01074-207 11051390082	MTH HRS LDG	29-Jun-2021 2410.5 2018		120	0	30-Jun-2031	55 m 20 d
256001 NO. 6 *256001A : 6*	LIFE VEST	KGMU		P01074-207 11051390081	MTH HRS LDG	29-Jun-2021 2410.5 2018		120	0	30-Jun-2031	55 m 20 d
256002	ELT BATTERY	UNK		452-0133 1004774-020	MTH HRS	09-Nov-2023 2897.6		60	0 0	28-Feb-2029	27 m 18 d
256003A	FIRST AID KIT --	KGJT		42 KIT NA	MTH HRS LDG	16-Jun-2026 3110.9 2986		12	12 88 46	30-Jun-2027	7 m 20 d
256004	ELT ANTENNA	*CF		110-340 151212	MTH	16-Aug-2007		O/C			
256007 *256001*	ELT PROCESSOR C406N			453-5060 07412	MTH HRS LDG	27-Oct-2015 1215.8 976		O/C			
261002 NO. 1	FIRE -ENGINE LOOP DETECTOR 9912416-1	*CF		3001-212-1004/455-9 207507	MTH	16-Aug-2007		O/C			
261002 NO. 2	FIRE -ENGINE LOOP DETECTOR 9912416-1	*CF		3001-212-1004/455-9 207458	MTH	16-Aug-2007		O/C			
262001	FIRE EXTINGUISHER BOTTLE 9912048-6	KGJT		30401102-2 55737B1	MTH HRS LDG	16-Jun-2026 3110.9 2986		O/C	237 0 0		
262003 LEFT Manufacture Date: 27-May-2026	FIRE EXT CARTRIDGE	KGJT		13083-5 ESD26E057-001	MTH HRS LDG	16-Jun-2026 3110.9 2986		72	1	31-May-2032	66 m 21 d
262003 RIGHT Manufacture Date: 27-May-2026	FIRE EXT CARTRIDGE	KGJT		13083-5 ESD26E057-001	MTH HRS LDG	16-Jun-2026 3110.9 2986		72	1	31-May-2032	66 m 21 d
262004	PORTABLE FIRE EXTINGUISHER	KGJT		C352TS I-58082085	MTH HRS LDG	18-Nov-2025 3075.3 2967		O/C	0 0 0		
271001 LEFT	CONTROL WHEEL ASSY	*CF		4319065-1 1163	MTH	16-Aug-2007		O/C			
271001 RIGHT	CONTROL WHEEL ASSY	*CF		4319065-2 1182	MTH	16-Aug-2007		O/C			
271002 --	ELEVATOR TRIM TAB ACTUATOR			PN SN-UNKNOWN	MTH	16-Aug-2007		H/T H/T	0		
273001	RUDDER TRIM ACTUATOR 9912639-2	*CF		SYLC-53361-1 0051	MTH	16-Aug-2007		O/C			
273002	AILERON TRIM ACTUATOR 9912639-2	*CF		SYLC-53361-1 0051	MTH	16-Aug-2007		O/C			
275001	FLAP PDU (POWER DRIVE UNIT) UNIT 9912642-1	*CF		MP50Y-1 049	MTH	16-Aug-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
275002 LEFT	FLAP ACTUATOR 9912640-1	LIML		41013930-101 0211	MTH HRS LDG	01-Oct-2010 387 243		O/C	0 0		
275002 RIGHT	FLAP ACTUATOR 9912640-2	HUR		41013930-106 0204	MTH HRS	28-Jul-2009 276		O/C	0		
275201 LEFT	FLAP FLEX SHAFT ASSEMBLY 9914344-52	*CF		140527-5200 0113	MTH	16-Aug-2007		O/C			
275201 RIGHT	FLAP FLEX SHAFT ASSEMBLY 9914344-52	*CF		140527-5200 0119	MTH	16-Aug-2007		O/C			
276001 LEFT	SPEED BRAKE ACTUATOR 9912641-2	*CF		41014070-103 0084	MTH	16-Aug-2007		O/C			
276001 RIGHT	SPEED BRAKE ACTUATOR	KGMU		9912641-3 0624	MTH HRS LDG	07-Sep-2022 2668.8 2605		O/C			
282001 LEFT	PRIMARY EJECTOR 9912190-5	*CF		LR45300A C1236	MTH	16-Aug-2007		O/C			
282001 RIGHT	PRIMARY EJECTOR 9912190-5	*CF		LR45300A C1245	MTH	16-Aug-2007		O/C			
282002	TRANSFER VALVE 9914103-6	*CF		ZSV57 06-0914112	MTH	16-Aug-2007		O/C			
282003 LEFT	DC FUEL PUMP 9912553-1	*CF		1C7-23 11BB201	MTH	16-Aug-2007		O/C			
282003 RIGHT	DC FUEL PUMP 9912553-1	*CF		1C7-23 9BB176	MTH	16-Aug-2007		O/C			
282004 L1	SCAVENGE EJECTOR 9912190-2	*CF		RG45310 B9995	MTH	16-Aug-2007		O/C			
282004 L2	SCAVENGE EJECTOR 9912190-2	*CF		RG45310 C-005	MTH	16-Aug-2007		O/C			
282004 R1	SCAVENGE EJECTOR 9912190-2	*CF		RG45310 C-095	MTH	16-Aug-2007		O/C			
282004 R2	SCAVENGE EJECTOR 9912190-2	*CF		RG45310 C-058	MTH	16-Aug-2007		O/C			
282005 LEFT	VALVE-FUEL MOTOR 9912014-3	*CF		AV24B1507 AA92505	MTH	16-Aug-2007		O/C			
282005 RIGHT	VALVE-FUEL MOTOR 9912014-3	*CF		AV24B1507 AA92502	MTH	16-Aug-2007		O/C			
284001 L1	FUEL PROBE 9912664-1	*CF		020-251-001 0143	MTH	16-Aug-2007		O/C			
284001 L2	FUEL PROBE 9912664-2	*CF		020-251-002 0151	MTH	16-Aug-2007		O/C			
284001 L3	FUEL PROBE 9912664-3	*CF		020-251-003 0141	MTH	16-Aug-2007		O/C			
284001 L4	FUEL PROBE 9912664-4	*CF		020-251-004 0183	MTH	16-Aug-2007		O/C			
284001 L5	FUEL PROBE 9912664-5	*CF		020-251-005 0146	MTH	16-Aug-2007		O/C			
284001 R1	FUEL PROBE 9912664-1	*CF		020-251-001 0144	MTH	16-Aug-2007		O/C			
284001 R2	FUEL PROBE 9912664-2	*CF		020-251-002 0152	MTH	16-Aug-2007		O/C			
284001 R3	FUEL PROBE 9912664-3	*CF		020-251-003 0142	MTH	16-Aug-2007		O/C			
284001 R4	FUEL PROBE 9912664-4	*CF		020-251-004 0123	MTH	16-Aug-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
284001 R5	FUEL PROBE 9912664-5	*CF		020-251-005 0147	MTH	16-Aug-2007		O/C			
284002	SIGNAL CONDITIONER 9912664-6	*CF		367-350-001 NSN	MTH	16-Aug-2007		O/C			
291001	HYDRAULIC POWER PACK ASSEMBLY 9912652-2	*CF		HM50C-3 044B	MTH	16-Aug-2007		O/C			
291002	HYDRAULIC CHECK VALVE	*CF		CV02-267 NSN	MTH	16-Aug-2007		O/C			
291003	HYDRAULIC SYS PRESSURE GAUGE	*CF		19940933-1 -	MTH	16-Aug-2007		O/C			
291005	HYD POWER PACK PRESSURE SWITCH 9912657-4	*CF		80665 NSN	MTH	16-Aug-2007		O/C			
291007	HYDRAULIC MANIFOLD 9912657-14	*CF		8257-3 0042	MTH	16-Aug-2007		O/C			
291008	HYDRAULIC RELIEF VALVE 9912657-2	*CF		2672 NSN	MTH	16-Aug-2007		O/C			
291009	BRAKE PRESSURE SWITCH 9912657-3	*CF		80664 NSN	MTH	16-Aug-2007		O/C			
291010 EXTEND	HYD SOLENOID CONTROL VALVE 9912657-5	*CF		4251 NSN	MTH	16-Aug-2007		O/C			
291010 RETRACT	HYD SOLENOID CONTROL VALVE 9912657-7	*CF		4252 NSN	MTH	16-Aug-2007		O/C			
291011	HYDRAULIC DUMP VALVE 9912657-15	*CF		9625-1 NSN	MTH	16-Aug-2007		O/C			
291012	HYDRAULIC RESERVOIR ASSEMBLY	*CF		7017005-24 NSN	MTH	16-Aug-2007		O/C			
291013	HYDRAULIC ACCUMULATOR ASSEMBLY 9912644-2	KAQW		7550-2 0865	MTH HRS LDG	09-Oct-2013 854.9 667		O/C	0 0 0		
301001 LEFT	WING DE-ICE BOOT 9912662-17	KAQW		P35-4D5317-17 NDQ3540	MTH HRS LDG	21-Jun-2017 1636.8 1319		O/C	0 0		
301001 RIGHT	WING DE-ICE BOOT 9912662-18	KAQW		P35-4D5317-18 NDT1650	MTH HRS LDG	21-Jun-2017 1636.8 1319		O/C	0 0		
301003 LEFT	HORIZONTAL STAB DE-ICE BOOT 9912662-3	KGMU		P29S4D5317-05 NEQ0140	MTH HRS LDG	25-Mar-2019 1995.2 1596		O/C	0 0		
301003 RIGHT	HORIZONTAL STAB DE-ICE BOOT 9912662-4	KGMU		P29S4D5317-06 NEQ0850	MTH HRS LDG	25-Mar-2019 1995.2 1596		O/C	0 0		
301004 L1	DE-ICE PRESSURE SWITCH	*CF		1106P55-1 4301A	MTH	16-Aug-2007		O/C			
301004 L2	DE-ICE PRESSURE SWITCH	*CF		1106P55-1 4356A	MTH	16-Aug-2007		O/C			
301004 L3	DE-ICE PRESSURE SWITCH	*CF		1106P55-1 4344A	MTH	16-Aug-2007		O/C			
301004 R1	DE-ICE PRESSURE SWITCH	*CF		1106P55-1 4271A	MTH	16-Aug-2007		O/C			
301004 R2	DE-ICE PRESSURE SWITCH	*CF		1106P55-1 4266A	MTH	16-Aug-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
301004 R3	DE-ICE PRESSURE SWITCH	*CF		1106P55-1 4267A	MTH	16-Aug-2007		O/C			
301004	VERT DE-ICE BOOT 9912662-13	KAQW		P29S4D5317-13 NDW1720	MTH HRS LDG	21-Jun-2017 1636.8 1319		O/C	0 0		
302001 LEFT	PRESS REG/SHUTOFF VALVE ASSY	*CF		5285-00-3 1151	MTH	16-Aug-2007		O/C			
302001 RIGHT	PRESS REG/SHUTOFF VALVE ASSY	*CF		5285-00-3 1063	MTH	16-Aug-2007		O/C			
302002 LEFT	TEMP SWITCH	*CF		1173T0759 3800	MTH	16-Aug-2007		O/C			
302002 RIGHT	TEMP SWITCH	*CF		1173T0759 NSN	MTH	16-Aug-2007		O/C			
304001 L1	DE-ICE VALVE	*CF		3D2353-06 N060998	MTH	16-Aug-2007		O/C			
304001 L2	DE-ICE VALVE	*CF		3D2353-06 N064788	MTH	16-Aug-2007		O/C			
304002 LEFT	WINDSHIELD CONTROLLER	KAQW		7018108-30 0144	MTH HRS LDG	03-Mar-2016 1306.9 1060		O/C	0 0 0		
304002 RIGHT	WINDSHIELD CONTROLLER	KAQW		7018108-30 0148	MTH HRS LDG	03-Mar-2016 1306.9 1060		O/C	0 0 0		
321001 LEFT	MAIN LANDING GEAR TRUNNION ASSEMBLY	*CF		7041020-5 NSN	MTH LDG	16-Aug-2007 0		20000	0	20000	16986
321001 RIGHT	MAIN LANDING GEAR TRUNNION ASSEMBLY	KAQW		7041020-6 24475948F	MTH HRS LDG	02-Oct-2014 1003.6 820		20000	0	20820	17806
321001	NOSE LANDING GEAR TRUNNION	*CF		7042020-1 14	MTH	16-Aug-2007		O/C			
321002 LEFT	MAIN LANDING GEAR OLEO ASSEMBLY	KAQW		7041050-5 24310011C	MTH HRS LDG	02-Oct-2014 1003.6 820		12000	0	12820	9806
321002 RIGHT	MAIN LANDING GEAR OLEO ASSEMBLY	KAQW		7041050-5 24226751C	MTH HRS LDG	02-Oct-2014 1003.6 820		12000	0	12820	9806
321003 LEFT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY	*CF		7041030-1 19	MTH LDG	16-Aug-2007 0		20000	0	20000	16986
321003 RIGHT	MAIN LANDING GEAR TRAILING LINK ASSEMBLY	*CF		7041030-2 19	MTH LDG	16-Aug-2007 0		20000	0	20000	16986
322001 LEFT	MAIN GEAR ACTUATOR UPLOCK	*CF		6327504-6 1362	MTH	16-Aug-2007		O/C			
322001 RIGHT	MAIN GEAR ACTUATOR UPLOCK	*CF		6327504-6 1132	MTH	16-Aug-2007		O/C			
322002	NOSE GEAR FORK & PISTON ASSEMBLY	*CF		7042040-1 NSN	MTH	16-Aug-2007		O/C			
322005	NOSE LANDING GEAR DOWNLOCK RELEASE ACTUATOR 9912655-1	*CF		FA100036-001 FA100036-1-0025	MTH LDG	16-Aug-2007 0		12000	0	12000	8986

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
322010	MAIN LANDING GEAR HYDRAULIC ACTUATOR				MTH	16-Aug-2007					
LEFT	9912653-5	*CF		FA100104-001	LDG	0		12000	0	12000	8986
				FA100104-1-0022							
322010	MAIN LANDING GEAR HYDRAULIC ACTUATOR				MTH	16-Aug-2007					
RIGHT	9912653-6	*CF		FA100105-001	LDG	0		12000	0	12000	8986
				FA100091-1-0014							
322011	NOSE LANDING GEAR ACTUATOR			FA100087-001	MTH	16-Aug-2007					
	9912654-2	*CF		FA100036-1-0038	LDG	0		12000	0	12000	8986
322202	SHIMMY DAMPER	*CF		7042030-2	MTH	16-Aug-2007		O/C			
				NSN							
322205	LANDING GEAR STRUT ASSEMBLY			7042010-4	MTH	16-Aug-2007					
NOSE		*CF		NSN	LDG	0		20000	0	20000	16986
322206	LANDING GEAR DRAG BRACE ASSY			7042120-1	MTH	16-Aug-2007					
NOSE		*CF		NSN	LDG	0		20000	0	20000	16986
323001	LANDING GEAR ASSEMBLY			7041010-3	MTH	16-Aug-2007		O/C			
LEFT		*CF		10							
323001	LANDING GEAR ASSEMBLY			7041010-4	MTH	16-Aug-2007		O/C			
RIGHT		*CF		10							
323001	LANDING GEAR EMERGENCY PNEUMATIC BOTTLE				MTH	17-Jun-2021		288	150	31-Dec-2032	73 m 21 d
	9914678-3	KGMU		40005369-2	HRS	2404.5					
				6625	LDG	2014					
Manufacture Date: 01-Dec-2008											
323002	EMERGENCY BRAKE PNEUMATIC BOTTLE				MTH	01-Nov-2024		288		31-May-2032	66 m 21 d
	9914678-4	KGJT		40005399-1	HRS	2981.9					
				6234	LDG	2920					
Manufacture Date: 01-May-2008											
323003	EMER BLOW DOWN BTL PRESSURE GAUGE				MTH	16-Aug-2007		O/C			
		*CF		19940931-1							
				-							
324001	MAIN LANDING GEAR TIRE			021-523-0	MTH	16-Jun-2024		O/C	0		
LEFT	9912646-1	GSO		2349T00347	HRS	2928.5			0		
					LDG	2890			0		
324001	MAIN LANDING GEAR TIRE			021-523-0	MTH	16-Jun-2024		O/C	0		
RIGHT	9912646-1	GSO		3056T00447	HRS	2928.5			0		
					LDG	2890			0		
324002	NOSE LANDING GEAR TIRE			079-606-0	MTH	16-Jun-2024		O/C	0		
	9912649-1	GSO		2202T00274	HRS	2928.5			0		
					LDG	2890			0		
324003	MAIN LANDING GEAR WHEEL			3-1640	MTH	16-Jun-2024		O/C	0		
LEFT	9912645-1	GSO		0048	HRS	2928.5			0		
					LDG	2890			0		
324003	MAIN LANDING GEAR WHEEL			3-1640	MTH	16-Jun-2024		O/C	84		
RIGHT	9912645-1	GSO		0036	HRS	2928.5			1291.7		
					LDG	2890			1571		
324004	NOSE LANDING GEAR WHEEL			3-1642	MTH	16-Jun-2024		O/C	0		
NOSE	9912648-1	GSO		0032	HRS	2928.5			0		
					LDG	2890			0		
324005	MAIN LANDING GEAR BRAKE ASSY			2-1706-1	MTH	16-Jun-2024		O/C	0		
LEFT	9912645-3	GSO		0387A	HRS	2928.5			0		
					LDG	2890			0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
324005 RIGHT	MAIN LANDING GEAR BRAKE ASSY 9912645-3	KGJT		2-1706-1 1108	MTH HRS LDG	18-Nov-2025 3075.3 2967		O/C	0 0 0		
324006 LEFT	SHUTTLE VALVE 9914689-4	*CF		5145-1 0036	MTH	16-Aug-2007		O/C			
324006 RIGHT	SHUTTLE VALVE 9914689-4	*CF		5145-1 0041	MTH	16-Aug-2007		O/C			
324007	BRAKE METERING VALVE 9912650-9	*CF		84-75 0021	MTH	16-Aug-2007		O/C			
324101 LEFT	WHEEL SPEED SENSOR 9912650-5	*CF		466-23-1 0042	MTH	16-Aug-2007		O/C			
324101 RIGHT	WHEEL SPEED SENSOR 9912650-5	*CF		466-23-1 NSN	MTH	16-Aug-2007		O/C			
324101	PARKING BRAKE VALVE 9912388-10	*CF		98433-1 0044	MTH	16-Aug-2007		O/C			
324102	ANTISKID CONTROL UNIT 9912650-1	KAQW		556-3 302829516	MTH HRS LDG	15-Jun-2018 1859.2 1471		O/C			
324103	ANTISKID CONTROL VALVE 9912650-6	*CF		211-134-1 0027	MTH	16-Aug-2007		O/C			
324104	EMERGENCY BRAKE VALVE 9912651-1	*CF		72298 0038	MTH	16-Aug-2007		O/C			
324105	EMER BRAKE BOTTLE PRESSURE GAUGE	*CF		19940931-1 -	MTH	16-Aug-2007		O/C			
325001	BUNGE ASSEMBLY	*CF		7042072-9 NSN	MTH	16-Aug-2007		O/C			
334000 L/H	LANDING/TAXI LIGHT	KAQW		9912677-1 000747	MTH HRS LDG	14-Jul-2016 1421.4 1170		O/C	0 0 0		
334001 LEFT	POWER SUPPLY	KGJT		9912677-3 001382	MTH HRS LDG	10-Jul-2026 3127.6 2995		O/C	0 0 0		
334001 RIGHT	POWER SUPPLY 9912677-3	KGJT		82004-1 000308	MTH HRS LDG	13-Aug-2026 3142.2 3003		O/C			
334002	GROUND RECOGNITION LIGHT	KAQW		9912677-2 000746	MTH HRS LDG	14-Jul-2016 1421.4 1170		O/C	0 0 0		
334003 LEFT	ANTI-COLLISION LIGHT	GSO		9912679-7 001700	MTH HRS LDG	16-Jun-2024 2928.5 2890		8000	0 0 0	10928.5	7772.7
334003 RIGHT	ANTI-COLLISION LIGHT	GSO		9912679-8 001179	MTH HRS LDG	16-Jun-2024 2928.5 2890		8000	0 0 0	10928.5	7772.7
341001	SWAAT UNIT 9912689-1	*CF		0863B2 59	MTH	16-Aug-2007		O/C			
341002 NO. 1	GDC 74B AIRDATA SYSTEM	LIML		011-01110-00 43800392	MTH HRS LDG	24-Sep-2010 387 243		O/C			
341002 NO. 2	GDC 74B AIRDATA SYSTEM	*CF		011-01110-00 43800429	MTH	16-Aug-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
341003 NO. 1	GTP 59 OAT PROBE SYSTEM	*CF		011-00978-00 47907560	MTH	16-Aug-2007		O/C			
341003 NO. 2	GTP 59 OAT PROBE SYSTEM	*CF		011-00978-00 4790798	MTH	16-Aug-2007		O/C			
341004 LEFT	PITOT PROBE 9912678-1	*CF		0851LN 250244	MTH	16-Aug-2007		O/C			
341004 RIGHT	PITOT PROBE 9912678-1	*CF		0851LN 248945	MTH	16-Aug-2007		O/C			
342001 STANDBY	ALTIMETER S3100-465	KGYH		162350-1161 1001194C	MTH HRS LDG	11-Sep-2020 2263.4 1863		O/C			
342002 AIRSPEED	INDICATOR	*CF		261440-1143 286403A	MTH	16-Aug-2007		O/C			
342003 NO. 1	GEA 71 ENG/AIRFRAME INTERFACE	KGMU		011-00831-00 46708064	MTH HRS LDG	25-Mar-2019 1995.2 1596		O/C			
342003 NO. 2	GEA 71 ENG/AIRFRAME INTERFACE	*CF		011-00831-00 46704832	MTH	16-Aug-2007		O/C			
342003	MAGNETIC COMPASS	KGJT		S2800-821 NA	MTH HRS LDG	18-Nov-2025 3075.3 2967		O/C	0 0 0		
342004 NO. 1	NO. 1 GARMIN GDU 1050A DISPLAY	KGSO		011-03470-10 494105438	MTH HRS LDG	24-Oct-2019 2093.6 1681		O/C	0 0 0		
342004 NO. 2	NO. 2 GARMIN GDU 1050A DISPLAY	KGSO		011-03470-10 494105442	MTH HRS LDG	24-Oct-2019 2093.6 1681		O/C	0 0 0		
342005 NO. 1	GRS 77 AHRS UNIT S3100-483/S3100-517	*CF		011-00868-10 42005440	MTH	16-Aug-2007		O/C			
342005 NO. 2	GRS 77 AHRS UNIT S3100-483/S3100-517	*CF		011-00868-10 42005441	MTH	16-Aug-2007		O/C			
342006 NO. 1	GMU 44 MAGNETOMETER	GSO		011-00870-00 47509171	MTH HRS LDG	16-Jun-2024 2928.5 2890		O/C	34 501.6 844		
342006 NO. 2	GMU 44 MAGNETOMETER	GSO		011-00870-00 47518424	MTH HRS LDG	16-Jun-2024 2928.5 2890		O/C	48 703.4 1062		
342007	GARMIN GDU 1050A DISPLAY	KGSO		011-03472-00 496001576	MTH HRS LDG	24-Oct-2019 2093.6 1681		O/C	0 0 0		
342008	ATTITUDE INDICATOR S3100-513	*CF		4200-21 G06-11068	MTH	16-Aug-2007		O/C			
344001	GWX 68 WEATHER RADAR	DUS		011-00883-20 47202641	MTH HRS LDG	17-Aug-2011 402 255		O/C	1 0 0		
344002	GARMIN GDL-69A DATA LINK	*CF		011-00987-00 47756991	MTH	16-Aug-2007		O/C			
345001	GPS/WAAS/XM ANTENNA	LIN		013-00245-00 5572	MTH HRS	16-Sep-2008 161		O/C	 0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
345002 RIGHT	NO. 2 GARMIN GTX345R TRANSPONDER	KGSO		011-03303-00 3EH025027	MTH HRS LDG	24-Oct-2019 2093.6 1681		O/C	0 0 0		
345003 LEFT	TRANSPONDER	KSWF		011-00779-21 84801127	MTH HRS LDG	12-Nov-2016 1505.7 1236		O/C			
345004	GARMIN GCU 475 FLIGHT MANAGEMENT CONTROL UNIT	KGSO		011-04475-00 48V000456	MTH HRS LDG	24-Oct-2019 2093.6 1681		O/C	0 0 0		
345005	ADF RECEIVER	*CF		013-00166-00 2438	MTH	16-Aug-2007		O/C			
345006	ADF ANTENNA	*CF		013-00165-00 2808	MTH	16-Aug-2007		O/C			
345007	MARKER BEACON ANTENNA	*CF		MB10-754-2 0045	MTH	16-Aug-2007		O/C			
345008	GLIDE SLOPE ANTENNA	*CF		RGS10-48 NSN	MTH	16-Aug-2007		O/C			
345009 LEFT	L-BAND TRANSPONDER ANTENNA	*CF		L10-611-14 0249	MTH	16-Aug-2007		O/C			
345009 RIGHT	L-BAND TRANSPONDER ANTENNA	*CF		L10-611-14 0242	MTH	16-Aug-2007		O/C			
345009 UPPER	L-BAND TRANSPONDER ANTENNA	*CF		L10-611-14 0097	MTH	16-Aug-2007		O/C			
345009 UPPER NO. 2	L-BAND TRANSPONDER ANTENNA	KSWF		L10-611-14 5074	MTH HRS LDG	12-Nov-2016 1505.7 1236		O/C	0 0 0		
345010	VOR/LOC ANTENNA	*CF		VT10-767-3 0258	MTH	16-Aug-2007		O/C			
345011	KN63 DME TRANSCEIVER	*CF		066-01070-0001 30597	MTH	16-Aug-2007		O/C			
345012 FORWARD	CABIN USB PORT			6430202-12 C20-11331	MTH HRS	14-Apr-2020 2206.5		O/C	0 0		
345012 REAR	CABIN USB PORT			6430202-12 C20-11332	MTH HRS	14-Apr-2020 2206.5		O/C	0 0		
345013	RMI CONVERTER	*CF		013-00167-00 0467	MTH	16-Aug-2007		O/C			
345014	GPS/WAAS/ ANTENNA	LIN		013-00244-00 5420	MTH HRS	16-Sep-2008 161		O/C	0		
345015	DME ANTENNA	*CF		L10-611-14 0247	MTH	16-Aug-2007		O/C			
345016	ILS APPROACH COUPLER			DRC20-35-5 2444	MTH HRS LDG	14-Apr-2020 2206.5 1803		O/C	0 0 0		
346010	TAS PROCESSOR	*CF		066-01152-0101 1494	MTH	16-Aug-2007		O/C			
346011 BOTTOM	TAS ANTENNA	*CF		L10-611-14 0250	MTH	16-Aug-2007		O/C			
346011 TOP	TAS ANTENNA	*CF		071-01599-0100 16535	MTH	16-Aug-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
346014 NO. 1	GIA 63W NAV/COMM/LS/GPS UNIT	*CF		011-01105-00 68501010	MTH	16-Aug-2007		O/C	0		
346014 NO. 2	GIA 63W NAV/COMM/LS/GPS UNIT	KSWF		011-01105-00 68501406	MTH HRS LDG	12-Nov-2016 1505.7 1236		O/C			
350001	OXYGEN BOTTLE	KGJT		4441073-040 0751-230	MTH HRS LDG	01-Nov-2024 2981.9 2920		180		30-Sep-2033	82 m 20 d
Manufacture Date: 28-Sep-2018											
350002	OXYGEN PRESSURE GAUGE C668512-0101	*CF		MD97-1 NSN	MTH	16-Aug-2007		O/C			
351001 LEFT	CREW OXYGEN MASK 9914067-41	KGMU		MC10-16-101 110386	MTH HRS LDG	10-Nov-2022 2705.6 2639		72	1	31-Oct-2028	23 m 21 d
351001 RIGHT	CREW OXYGEN MASK 9914067-41	GSO		MC10-16-101 85015	MTH HRS LDG	16-Jun-2024 2928.5 2890		72	2 0 0	30-Apr-2030	41 m 20 d
361001 LEFT	PRECOOLER 9914402-7	*CF		8315-2 T0067	MTH	16-Aug-2007		O/C			
361001 RIGHT	PRECOOLER 9914402-7	*CF		8315-2 T0075	MTH	16-Aug-2007		O/C			
361002 LEFT	VARIABLE VENTURI VALVE ASSY	*CF		2601-34 00065A	MTH	16-Aug-2007		O/C			
361002 RIGHT	VARIABLE VENTURI VALVE ASSY	*CF		2601-34 00025A	MTH	16-Aug-2007		O/C			
361003	SERVICE AIR REGULATOR ASSY 9912510-2	*CF		1H75-23 11BB28	MTH	16-Aug-2007		O/C			
361004 LEFT	B/A SHUTOFF VALVE	*CF		5253-00-1 1339	MTH	16-Aug-2007		O/C			
361004 RIGHT	B/A SHUTOFF VALVE	*CF		5253-00-1 1483	MTH	16-Aug-2007		O/C			
361101 R1	DE-ICE VALVE	*CF		3D2353-06 N064382	MTH	16-Aug-2007		O/C			
361101 R2	DE-ICE VALVE	*CF		3D2353-06 N064791	MTH	16-Aug-2007		O/C			
522001	CABIN DOOR SEAL 9912674-3	*CF		S-22560-3 NSN	MTH	16-Aug-2007		O/C			
522002	ESCAPE HATCH SEAL 9912675-1	KGYH		S-22561 75345/32419-081	MTH HRS LDG	05-Oct-2020 2276.8 1881		O/C	1 0 0		
531001 LEFT	NOSE LANDING GEAR ATTACH FITTING ASSY	*CF		7013022-3 NSN	MTH LDG	16-Aug-2007 0		20000	0	20000	16986
531001 RIGHT	NOSE LANDING GEAR ATTACH FITTING ASSY	*CF		7013022-4 NSN	MTH LDG	16-Aug-2007 0		20000	0	20000	16986
531002 LEFT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY	*CF		7013022-11 NSN	MTH LDG	16-Aug-2007 0		20000	0	20000	16986
531002 RIGHT	NOSE LANDING GEAR DRAG BRACE FITTING ASSY	*CF		7013022-10 NSN	MTH LDG	16-Aug-2007 0		20000	0	20000	16986
534101 FWD	ENGINE BEAM	*CF		7012061-2 23	MTH	16-Aug-2007		O/C			
552001 LEFT	ELEVATOR ASSEMBLY	*CF		7034001-7 -	MTH	16-Aug-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
552001 RIGHT	ELEVATOR ASSEMBLY *CF			7034001-8 000011	MTH	16-Aug-2007		O/C			
553001	VERTICAL STABILIZER ASSY *CF			7031001-801-7 0000014	MTH	16-Aug-2007		O/C			
561001 LEFT	WINDSHIELD ASSY, (LH) 9912745-7	*CF		P03100-7 00242	MTH	16-Aug-2007		O/C			
561001 RIGHT	WINDSHIELD ASSY, (RH) 9912745-8	*CF		P03100-8 00231	MTH	16-Aug-2007		O/C			
561002 LEFT	FLIGHT COMPARTMENT SIDE WINDOW 9912746-1	*CF		93310-1 1085	MTH	16-Aug-2007		O/C			
561002 RIGHT	FLIGHT COMPARTMENT SIDE WINDOW 9912746-2	*CF		93310-2 1062	MTH	16-Aug-2007		O/C			
562003 L1	CABIN WINDOW 9912747-1	*CF		93320-1 1251	MTH	16-Aug-2007		O/C			
562003 L2	CABIN WINDOW 9912747-1	*CF		93320-1 1262	MTH	16-Aug-2007		O/C			
562003 L3	CABIN WINDOW 9912747-1	*CF		93320-1 1242	MTH	16-Aug-2007		O/C			
562003 R1	CABIN WINDOW 9912747-1	*CF		93320-1 1260	MTH	16-Aug-2007		O/C			
562003 R2	CABIN (ESCAPE HATCH) WINDOW 9912747-1	*CF		93320-1 NSN	MTH	16-Aug-2007		O/C			
562003 R3	CABIN WINDOW 9912747-1	*CF		93320-1 1238	MTH	16-Aug-2007		O/C			
572001 LEFT WING	FWD SPAR	*CF		7022022-1 32244	MTH	16-Aug-2007		O/C			
572001 RIGHT WING	FWD SPAR	*CF		7022022-2 32279	MTH	16-Aug-2007		O/C			
572002 LEFT WING	REAR SPAR	*CF		7022032-3 21799	MTH	16-Aug-2007		O/C			
572002 RIGHT WING	REAR SPAR	*CF		7022032-4 9221	MTH	16-Aug-2007		O/C			
572003 LEFT WING	MAIN SPAR	*CF		7022027-1 32247	MTH	16-Aug-2007		O/C			
572003 RIGHT WING	MAIN SPAR	*CF		7022027-2 32249	MTH	16-Aug-2007		O/C			
572004 LEFT MAIN GEAR	AFT TRUNNION FITTING ASSY *CF			7041165-1 NSN	MTH LDG	16-Aug-2007 0		20000	0	20000	16986
572004 RIGHT MAIN GEAR	AFT TRUNNION FITTING ASSY *CF			7041165-2 NSN	MTH LDG	16-Aug-2007 0		20000	0	20000	16986
572005 LEFT MAIN GEAR	FWD TRUNNION FITTING ASSY *CF			7041155-5 NSN	MTH LDG	16-Aug-2007 0		20000	0	20000	16986
572005 RIGHT MAIN GEAR	FWD TRUNNION FITTING ASSY *CF			7041155-6 NSN	MTH LDG	16-Aug-2007 0		20000	0	20000	16986
572006 LEFT MAIN GEAR	SIDE BRACE FITTING ASSY *CF			7041175-5 NSN	MTH LDG	16-Aug-2007 0		20000	0	20000	16986
572006 RIGHT MAIN GEAR	SIDE BRACE FITTING ASSY *CF			7041175-6 NSN	MTH LDG	16-Aug-2007 0		20000	0	20000	16986
712001 LEFT	ENG CHANNEL-FWD MOUNT 7051001-1			7051001-1 00021	MTH	16-Aug-2007		O/C			
712001 LEFT BOTTOM	FWD ENGINE ISOLATOR SYSTEM 9912647-1	*CF		LM-471-SA12 0203	MTH HRS	16-Aug-2007 0		4000	0	4000	844.2
712001 LEFT TOP	FWD ENGINE ISOLATOR SYSTEM 9912647-1	*CF		LM-471-SA12 0239	MTH HRS	16-Aug-2007 0		4000	0	4000	844.2
712001 RIGHT	ENG CHANNEL-FWD MOUNT *CF			7051001-2 00011	MTH	16-Aug-2007		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
712001 RIGHT BOTTOM	FWD ENGINE ISOLATOR SYSTEM 9912647-1	*CF		LM-471-SA12 0235	MTH HRS	16-Aug-2007 0		4000	0	4000	844.2
712001 RIGHT TOP	FWD ENGINE ISOLATOR SYSTEM 9912647-1	*CF		LM-471-SA12 0195	MTH HRS	16-Aug-2007 0		4000	0	4000	844.2
712002 LEFT	AFT ENGINE ISOLATOR ASSEMBLY 9912647-3	*CF		LM-471-SA4 LK1578	MTH HRS	16-Aug-2007 0		8000	0	8000	4844.2
712002 RIGHT	AFT ENGINE ISOLATOR ASSEMBLY 9912647-3	*CF		LM-471-SA4 LK1622	MTH HRS	16-Aug-2007 0		8000	0	8000	4844.2
712003 AFT	ENGINE BEAM	*CF		7012066-2 21	MTH	16-Aug-2007		O/C			
712003 LEFT	AFT ENGINE MOUNT CHANNEL	*CF		7051001-3 00012	MTH	16-Aug-2007		O/C			
712003 RIGHT	AFT ENGINE MOUNT CHANNEL	*CF		7051001-4 00014	MTH	16-Aug-2007		O/C			
71EN1 NO. 1 *710001 : E1**L*	ENGINE	*CF		35C0510-01 PCE-LB0039	MTH	16-Aug-2007		E/C			
71EN2 NO. 2 *710001 : E2**R*	ENGINE	KDXR		35C0510-01 PCE-LB0003	MTH HRS LDG	14-Sep-2017 1693.4 1368		E/C	993		
720010 E1	FAN ROTOR	*CF		35C1940-01 TXA1B1120	MTH LDG ACCC YC	16-Aug-2007 0		10500	0	(10500)10500	7486 7486
720010 E2	FAN ROTOR			35C1940-01 TXA1A8561	MTH HRS LDG ACCC YC	30-Jun-2010 1017 645		10500	265 265	(10500)10880	7866 7866
721010 E1	HP TURBINE DISK	*CF		35C2311-01 A00221KM	MTH LDG ACCC YC	16-Aug-2007 0		5250	0	(5250)5250	2236 2236
721010 E2	HP TURBINE DISK			35C2311-01 AA001X94H	MTH HRS LDG ACCC YC	30-Jun-2010 1017 645		5250	265 265	(5250)5630	2616 2616
721020 E1	LP TURBINE DISK	*CF		35C2372-01 A0023YA0	MTH LDG ACCC YC	16-Aug-2007 0		10500	0	(10500)10500	7486 7486
721020 E2	LP TURBINE DISK			35C2372-01 A0021P0T	MTH HRS LDG ACCC YC	30-Jun-2010 1017 645		10500	265 265	(10500)10880	7866 7866
723010 E1	IMPELLER AND SHAFT ASSEMBLY	*CF		35C3656-01 A0022Y1K	MTH LDG ACCC YC	16-Aug-2007 0		10500	0	(10500)10500	7486 7486
723010 E2	IMPELLER AND SHAFT ASSEMBLY			35C3656-01 A001WA3X	MTH HRS LDG ACCC YC	30-Jun-2010 1017 645		10500	265 265	(10500)10880	7866 7866

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
725010	HP COMPRESSOR ROTOR			35C3661-01	MTH	16-Aug-2007					
E1		*CF		TXA1B1389	LDG	0			0	(10500)10500	7486
					ACCC			10500			7486
					YC						
725010	HP COMPRESSOR ROTOR			35C3661-01	MTH	30-Jun-2010					
E2				TXA1A8772	HRS	1017					
					LDG	645			265	(10500)10880	7866
					ACCC			10500	265		7866
					YC						
726010	AGB STARTER MAGNETIC SEAL			35C1022-01	MTH	08-Dec-2017			0		
E1		UNK		SN-UNKNOWN	HRS	1752.6		1750	0	(3502.6)3502.6	346.8
					LDG	1398			0		
726010	AGB STARTER MAGNETIC SEAL			PN	MTH	22-Nov-2021			0		
E2		KICT		SN-UNKNOWN	HRS	2486		1750	0	(3537.7)4236	1080.2
					LDG	2111			0		
730001	ENGINE FUEL PRESSURE SWITCH			1103P0448	MTH	16-Aug-2007		O/C			
LEFT	9912033-2	*CF		7491							
730001	ENGINE FUEL PRESSURE SWITCH			1103P0448	MTH	16-Aug-2007		O/C			
RIGHT	9912033-2	*CF		7524							
733001	FUEL FLOW TRANSMITTER			TFF1573-4	MTH	16-Aug-2007		O/C			
LEFT	9912417-1	*CF		2265							
733001	FUEL FLOW TRANSMITTER			TFF1573-4	MTH	16-Aug-2007		O/C			
RIGHT	9912417-1	*CF		2262							
731050	FUEL MANIFOLD	BTV		35C6160-01	MTH	08-Dec-2017		O/C	0		
E1				DEAAAA39742	HRS	1752.6			0		
					LDG	1398			0		
731050	FUEL MANIFOLD			PN	MTH	13-Apr-2007		O/C	0		
E2				SN-UNKNOWN							
732101	FUEL METERING UNIT (F.M.U.)			35C0794-03	MTH	04-Nov-2009		H/T			
E1		HUR		15458697	HRS	310		H/T	101		
								H/T			
732101	FUEL METERING UNIT (F.M.U.)			8060-626	MTH	18-Apr-2012		H/T			
E2				14791473	HRS	1261.6		H/T	244.6		
					LDG	868		H/T			
								H/T			
733010	FUEL FILTER IMPENDING BYPASS SWITCH				MTH	08-Dec-2017		O/C			
E1		UNK		35C3388-01	HRS	1752.6					
				SN-UNKNOWN	LDG	1398					
733010	FUEL FILTER IMPENDING BYPASS SWITCH				MTH	18-Apr-2012		O/C			
E2				35C3388-01	HRS	1261.6			244.6		
				WDA100997	LDG	868					
741001	IGNITION EXCITER	*CF		35C3895-01	MTH	16-Aug-2007		O/C			
E1				14980930							
741001	IGNITION EXCITER			35C3895-01	MTH	30-Jun-2010		O/C			
E2				14807007	HRS	1017			318.7		
					LDG	645					
741002	IGNITER CABLE	*CF		35C0844-01	MTH	16-Aug-2007		O/C			
E1 LEFT				NSN							
741002	IGNITER CABLE			35C0844-01	MTH	30-Jun-2010		O/C			
E2 LEFT				SN-UNKNOWN	HRS	1017			318.7		
					LDG	645					
741003	IGNITER CABLE	*CF		35C0799-01	MTH	16-Aug-2007		O/C			
E1 RIGHT				NSN							

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
741003 E2 RIGHT	IGNITER CABLE			35C0799-01 SN-UNKNOWN	MTH HRS LDG	30-Jun-2010 1017 645		O/C	 318.7		
741004 E1 INBOARD	SPARK IGNITER	KAQW		35C2353-02 NSN	MTH HRS LDG	06-Feb-2018 1771 1411		O/C	0 0		
741004 E2 INBOARD	SPARK IGNITER			35C2353-01 WDA105859	MTH HRS LDG	18-Apr-2012 1261.6 868		O/C			
741005 E1 OUTBOARD	SPARK IGNITER	KAQW		35C2353-02 NSN	MTH HRS LDG	06-Feb-2018 1771 1411		O/C	0 0		
741005 E2 OUTBOARD	SPARK IGNITER			35C2353-01 WDA105860	MTH HRS LDG	18-Apr-2012 1261.6 868		O/C			
751003 E1	BLEED VALVE ACTUATOR	*CF		35C2851-01 14867863	MTH	16-Aug-2007		H/T H/T			
751003 E2	BLEED VALVE ACTUATOR			35C2851-01 14610504	MTH HRS LDG	30-Jun-2010 1017 645		H/T H/T H/T H/T	 318.7		
761002A	RVDT SENSOR	KSWF		3A21200096 B4233	MTH HRS LDG	08-Dec-2013 903 697		O/C	0 0 0		
761001 E1	FADEC 9912637-2	LIML		35C4035-04 08-462	MTH HRS LDG	29-Nov-2010 387 243		O/C			
761001 E2	FADEC 9912637-2	YSBK		35C4035-03 06-105	MTH	13-May-2016		O/C			
791001 E1	FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.)	*CF		35C3778-01 WA24698	MTH	16-Aug-2007		H/T H/T			
791001 E2	FUEL-TO-OIL HEAT EXCHANGER (F.O.H.E.)			35C3778-03 WA35356	MTH HRS LDG	18-Apr-2012 1261.6 868		H/T H/T H/T H/T	 244.6		
793001 E1	OIL TEMP SENSOR	*CF		102-00083 05787	MTH	16-Aug-2007		O/C			
793001 E2	OIL TEMP SENSOR			PN SN-UNKNOWN	MTH	13-Apr-2007		O/C	0		
793002 E1	OIL PRESSURE TRANSMITER	*CF		APTE-304A-250G 7365-10-575	MTH	16-Aug-2007		O/C			
793002 E2	OIL PRESSURE TRANSMITER			PN SN-UNKNOWN	MTH	13-Apr-2007		O/C	0		
793010 E1	CHIP COLLECTOR			PN SN-UNKNOWN	MTH	16-Aug-2007		O/C	0		
793010 E2	CHIP COLLECTOR			35C0412-01 AB0029	MTH	13-Apr-2007		O/C	0		
801000 LEFT	STARTER GENERATOR 9912676-1	KDXR		MG94E-1 552D	MTH HRS LDG	14-Sep-2017 1693.4 1368		 1500	0 0 0	3193.4	37.6

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
801000 RIGHT	STARTER GENERATOR	KGMU		9912676-1 1032D	MTH HRS LDG	14-May-2021 2388.5 1999		1500	0	3888.5	732.7

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC) (THIS SL REPLACES SL510-99-02 R2)			INFORMATIONAL				-			
	MOC :										
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED				-			
	MOC :										
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 REV 01)			RECOMMENDED				-			
	MOC :										
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL				-			
	MOC :										
SL 510-99-02 REV 02	CESCOM PRICING (SUPERSEDED BY CIL-03-01)			INFORMATIONAL				-			
	MOC :										
SL 510-99-03 *99SL-03*	TUBE ASSEMBLY SLEEVE INSPECTION	LIN		RECOMMENDED	MTH HRS	16-Sep-2008 161		A/R			Complete
	MOC : COMPLIED WITH										
SL 510-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL				A/R			
	MOC :										
SL 510-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL				A/R			
	MOC :										
SL 510-05-02	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS INTERVALS UPDATE			MANDATORY	MTH HRS			12 150		16-Jul-2027 3278.63	8 m 6 d 122.83
	MOC :										
SL 510-11-01 *11SL-01*	INSPECTION OF THE LOWER SPEED BRAKE PLACARD	LIN		RECOMMENDED	MTH HRS	16-Sep-2008 161		A/R			Complete
	MOC : COMPLIED WITH										
SL CIL-99-01 REV 01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 REV 02)			INFORMATIONAL				-			
	MOC :										
SL CIL-99-01 REV 02	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL				-			
	MOC :										
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 REV 01)			INFORMATIONAL				-			
	MOC :										
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			RECOMMENDED	MTH			-			
	MOC :										
SB 510-20-02	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL (SUPERSEDED BY SL510-20-02 R01)			INFORMATIONAL				-			
	MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains
SL CIL-20-01 REV 02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 REV 01)			INFORMATIONAL			-			
	MOC :									
SL 510-20-01 REV 04	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL510-20-01 REV 05)			INFORMATIONAL			A/R			
	MOC :									
SL 510-20-02 R01	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL			INFORMATIONAL			-			
	MOC :									
SL 510-21-01 *21SL-01*	COMPRESSOR ISOLATOR MOUNT INSPECTION	HUR		RECOMMENDED	MTH 17-Dec-2009 HRS 324		A/R			Complete
	MOC : COMPLIED WITH									
SL 510-21-02 REV 01	CABIN ALTITUDE MODULE INSPECTION			MANDATORY	MTH		A/R			N/A
	MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO -0061 THRU -0181.									
SL 510-21-04	AIR CONDITIONING - CABIN PRESSURIZATION CONTROLLER IMPROVEMENT	KGMU		RECOMMENDED	MTH 30-Aug-2019 HRS 2069.2 LDG 1659		-			N/A
	MOC : NOT APPLICABLE - P/N 9912661-6/52811-102, S/N 0855 IS INSTALLED. THEREFORE, THIS SERVICE LETTER IS NOT APPLICABLE.WORK WAS ALSO PERFORMED BY HAROLD BEKEMEYER.									
SL 510-21-05	AIR CONDITIONING - AIR CONDITIONING COMPRESSOR MOTOR FAN REPLACEMENT			OPTIONAL			-			
	MOC :									
ASL 510-22-01 *22ASL01*	AUTOPILOT SERVO GUARD PIN INSPECTION	LIN		MANDATORY	MTH 16-Sep-2008 HRS 161		A/R			Complete
	MOC : COMPLIED WITH									
SB 510-23-02	COMMUNICATIONS - ENABLE XM RADIO IN THE COCKPIT			OPTIONAL			A/R			
	MOC :									
SL 510-24-06 *24SL-06*	FUSE LIMITER INSPECTION	HUR		MANDATORY	MTH 18-Sep-2009 HRS 289		-			Complete
	MOC : COMPLIED WITH									
SL 510-24-08 REV 01	STARTER/GENERATOR INSPECTION	LIML		MANDATORY	MTH 01-Oct-2010 HRS 387 LDG 243		A/R			N/A
	MOC : NOT APPLICABLE - BY SERIAL NUMBER N/A PER STARTER GENERATOR SERIAL NUMBER									
SL 510-24-08 *24SL-08*	STARTER/GENERATOR INSPECTION (SUPERSEDED BY SL510-24-08 REV 01)	LIML		MANDATORY	MTH 05-Aug-2010 HRS 387 LDG 243		A/R			N/A
	MOC : NOT APPLICABLE - BY SERIAL NUMBER SL510-24-08 R1 - ELECTRICAL POWER-STATER/GENERATOR INSPECTION - N/A FOR ST./GEN S/N INSTALLED (LH ST./GEN SN: 089; RH ST./GEN SN: 092)									
SL 510-24-10	CONTROL WHEEL ELECTRICAL CONNECTOR INSPECTION			MANDATORY	MTH		A/R			N/A
	MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS 510-0226 THRU 510-0256 ONLY.									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SL 510-24-11 REV 01	RIGHT CIRCUIT BREAKER PANEL BUS BAR INSPECTION			MANDATORY	MTH		A/R			N/A
	MOC : NOT APPLICABLE - BY SERIAL NUMBER -									
SL 510-24-11	RIGHT CIRCUIT BREAKER PANEL BUS BAR INSPECTION (SUPERSEDED BY SL510-24-11 REV 01)			MANDATORY			A/R			N/A
	MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS 510-0153 THRU 51-0279, -0281 THRU -0285, -0291 THRU -0294, AND -0296 ONLY.									
SL 510-24-12	CONTROL COLUMN TIE STRAP INSPECTION			MANDATORY	MTH		A/R			N/A
	MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO SERIAL NUMBERS 510-0253 THRU 510-0323 ONLY.									
SL 510-24-13	ELECTRICAL POWER - THROTTLE QUADRANT WIRE BUNDLE INSPECTION	DUS		MANDATORY	MTH 31-Oct-2011 HRS 403 LDG 255		A/R			Complete
	MOC : COMPLIED WITH									
SL 510-24-14 REV 01	ELECTRICAL POWER - PRINTED CIRCUIT BOARD VERIFICATION	KAQW		MANDATORY	DAYS 16-Dec-2016 HRS 1521.9 LDG 1252		-			N/A
	MOC : NOT APPLICABLE - BY PCB DATE CODES									
SB 510-25-02	EQUIPMENT/FURNISHINGS - AFT CABIN CURTAIN IMPROVEMENT			OPTIONAL			A/R			
	MOC :									
SB 510-25-03	EQUIPMENT/FURNISHINGS - REMOVAL OF THE CABIN SIDEWALL AIR DIFFUSER			DISCRETIONARY			A/R			
	MOC :									
SB 510-25-04	EQUIPMENT/FURNISHINGS - CABIN COMFORT IMPROVEMENTS			OPTIONAL			-			
	MOC :									
SL 510-25-02	CREW SEAT CONTROL ASSEMBLY SCREW INSPECTION	LIML		MANDATORY	DAYS 01-Oct-2010 HRS 387 LDG 243		A/R			Complete
	MOC : COMPLIED WITH - PREVIOUSLY PCW CTA WR 198/10									
SL 510-25-03 REV 01	EQUIPMENT/FURNISHINGS - CREW SEAT INSPECTION	SWF		MANDATORY	MTH 17-Aug-2012 HRS 619.5 LDG 475		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SL510-25-03 R1 CREW SEAT INSPECTION. INSPECTED PER ACCOMPLISHMENT INSTRUCTIONS AND FOUND REINFORCEMENT TEES INSTALLED ON BOTH SEATS.									
SL 510-25-03	EQUIPMENT/FURNISHINGS - CREW SEAT INSPECTION (SUPERSEDED BY SL510-25-03 REV 01)	DUS		MANDATORY	MTH 31-Oct-2011 HRS 403 LDG 255		A/R			Complete
	MOC : COMPLIED WITH									
SB 510-27-01 *27SB-01*	AILERON SHIELD SEALANT REVISION	HUR		MANDATORY	MTH 18-Sep-2009 HRS 289		-			Complete
	MOC : COMPLIED WITH									
SB 510-27-02	SPEED BRAKE MECHANICAL SWITCH CONVERSION	KSWF		RECOMMENDED	MTH 17-Apr-2014 HRS 957.6 LDG 742		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SB510-27-02 SPEED BRAKE MECHANICAL SWITCH CONVERSION PER ACCOMPLISHMENT INSTRUCTIONS.									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SL 510-27-01 *27SL-01*	FLAP ACTUATOR INSTALLATION SETSCREW INSPECTION	LIN		RECOMMENDED	MTH HRS	05-Dec-2008 188		A/R			Complete
	MOC : COMPLIED WITH										
SL 510-27-02 *27SL-02*	CONTROL YOKE ASSEMBLY TIE STRAP INSPECTION	LIN		MANDATORY	MTH HRS	24-Nov-2008 185		A/R			Complete
	MOC : COMPLIED WITH										
SL 510-27-05 *27SL-05*	FLAP ACTUATOR INSPECTION	HUR		MANDATORY	MTH HRS	18-Sep-2009 289		-			Complete
	MOC : COMPLIED WITH										
SB 510-28-02 *28SB-02*	LOCKING FUEL CAP INSTALLATION			OPTIONAL	MTH			A/R			
	MOC :										
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS			INFORMATIONAL				-			
	MOC :										
SL 510-28-01 *28SL-01*	LEFT AND RIGHT FUEL PROBE WIRE BUNDLE ASSEMBLY INSPECTION	HUR		MANDATORY	MTH HRS	18-Sep-2009 289		A/R			Complete
	MOC : COMPLIED WITH										
SB 510-29-01 *29SB-01*	HYDRAULIC SYSTEM NOISE REDUCTION	GSO		OPTIONAL	MTH HRS LDG	16-Jun-2024 2928.5 2890		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH CITATION SERVICE BULLETIN SB510-29-01.										
SB 510-30-01 *30SB-01*	WINDSHIELD CONTROLLER WIRING HARNESS INSTALLATION	HUR		OPTIONAL	MTH HRS	17-Dec-2009 324		A/R			Complete
	MOC : COMPLIED WITH										
SB 510-30-02 REV 01	PPG WINDSHIELD ANTI-ICE SYSTEM IMPROVEMENT			DISCRETIONARY				-			
	MOC :										
SB 510-30-02	ICE AND RAIN PROTECTION - PPG WINDSHIELD ANTI-ICE SYSTEM IMPROVEMENT (SUPERSEDED BY 510-30-02 REV 01)			DISCRETIONARY				-			
	MOC :										
SB 510-30-03 REV 01	ICE AND RAIN PROTECTION - WINDSHIELD CONNECTOR CLIP ASSEMBLY IMPROVEMENT			DISCRETIONARY				A/R			
	MOC :										
SB 510-30-03	ICE AND RAIN PROTECTION - WINDSHIELD CONNECTOR CLIP ASSEMBLY IMPROVEMENT (SUPERSEDED BY 510-30-03 REV 01)			DISCRETIONARY				A/R			
	MOC :										
SB 510-30-04	ICE AND RAIN PROTECTION - WINDSHIELD CONTROLLER CONTACT REPLACEMENT	DUS		MANDATORY	MTH HRS LDG	17-Aug-2011 403 255		A/R			Complete
	MOC : COMPLIED WITH										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB 510-30-05	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROL UNIT MODIFICATION	SWF		MANDATORY	MTH 17-Aug-2012 HRS 619.5 LDG 475		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SB510-30-05 WINDSHIELD TEMPERATURE CONTROL UNIT MODIFICATIION. REPLACED THE JACK POSTS PER ACCOMPLISHMENT INSTRUCTIONS.									
SB 510-30-06 REV 01	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT			RECOMMENDED	MTH		-			
	MOC :									
SB 510-30-06	ICE AND RAIN PROTECTION - WINDSHIELD TEMPERATURE CONTROLLER ENHANCEMENT (SUPERSEDED BY 510-30-06 REV 01)	KAQW		RECOMMENDED	MTH 03-Mar-2016 HRS 1306.9 LDG 1060		-			Complete
	MOC : COMPLIED WITH									
ASL 510-30-02 *30ASL02*	WATER SEPARATOR DRAIN CAP	LIN		MANDATORY	MTH 19-May-2008 HRS 123		A/R			Complete
	MOC : COMPLIED WITH									
SL CIL-30-01 REV 01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES			INFORMATIONAL			-			
	MOC :									
SL 510-30-01 REV 03	APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY (SUPERSEDED BY SL510-30-01 REV 04)			INFORMATIONAL			A/R			
	MOC :									
SB 510-31-01 *31SB-01*	MASTER CAUTION WARNING LIGHT WIRING MODIFICATION			DISCRETIONARY	MTH		A/R			
	MOC :									
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION			INFORMATIONAL			-			
	MOC :									
SL 510-31-03	COCKPIT SWITCH WIRE BUNDLE ASSEMBLY (WBA) INSPECTION			MANDATORY	MTH		A/R			N/A
	MOC : NOT APPLICABLE - BY SERIAL NUMBER APPLICABLE TO AIRCRAFT SERIAL NUMBERS -0156 THRU -0164, -0167 THRU -0191, -0193 THRU -0215, -0218 THRU -0220, -0223, -0225 THRU -0227.									
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION			INFORMATIONAL			-			
	MOC :									
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION			INFORMATIONAL			-			
	MOC :									
SL 510-32-02 REV 01 *32SL-02 : 510R1*	EMERGENCY GEAR RELEASE INSPECTION	HUR		MANDATORY	MTH 13-Feb-2010 HRS 336 LDG 217		A/R			Complete
	MOC : COMPLIED WITH - SL510-32-02 R1 COMPLETED.									
SL 510-32-02	EMERGENCY GEAR RELEASE INSPECTION (SUPERSEDED BY SL510-32-02 REV 01)	HUR		MANDATORY	MTH 13-Feb-2010 HRS 336 LDG 217		A/R			Complete
	MOC : COMPLIED WITH - SL510-32-02 COMPLETED.									

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SL 510-32-03 *32SL-03*	RIGHT BRAKE STOP BRACKET INSPECTION	HUR		MANDATORY	MTH HRS	17-Dec-2009 324		A/R			Complete
	MOC : COMPLIED WITH										
SL 510-32-05	LANDING GEAR - NOSE LANDING GEAR DOWNLOCK SWITCH WIRING INSPECTION	KAQW		RECOMMENDED	MTH HRS LDG	19-Sep-2012 635.8 510		-			Complete
	MOC : COMPLIED WITH - SL510-32-05 NOSE LANDING GEAR DOWNLOCK SWITCH WIRING - COMPLIED WITH BY MODIFICATION PER SL, INCLUDING RELOCATION OF SIDWALL PIVOT ANCHOR, AND WIRE LENGTHENING. LANDING GEAR CHECKS COMPLETED.										
SL 510-32-07	LANDING GEAR - MAIN LANDING GEAR BRAKE VERIFICATION	KAQW		MANDATORY	DAYS HRS LDG	30-Mar-2017 1557.4 1287		-			N/A
	MOC : NOT APPLICABLE - BY BRAKE SERIAL NUMBERS, LEFT AND RIGHT. CURRENT LEFT BRAKE S/N: 299, RIGHT BRAKE S/N: 307										
SL 510-32-08	LANDING GEAR - TRANSMIT GOODRICH SERVICE BULLETIN 2-1706-1-32-1 LANDING GEAR - MAIN BRAKE ASSEMBLY, - INTRODUCTION OF AN INSPECTION PROCEDURE TO MAKE SURE THE WEAR INDICATOR PINS WERE SET CORRECTLY			MANDATORY	DAYS HRS LDG	24-Apr-2018 1826.2 1452		-			Complete
	MOC : COMPLIED WITH - AD 2018-07-13 COMPLIED WITH BY INSPECTION PER AD AND UTC SB 2-1706-07-13, REV. 1. PIN MEASUREMENTS BELOW .165". PAINTED PINT ENDS YELLOW.										
SB 510-33-01	LIGHTS - LANDING/TAXI LIGHT IMPROVEMENT			OPTIONAL				-			
	MOC :										
SB 510-34-02 *34SB-02*	HARDWARE AND SOFTWARE UPDATE FOR GARMIN G1000 AVIONICS	LIN		MANDATORY	MTH HRS	16-Sep-2008 161		A/R			Complete
	MOC : COMPLIED WITH										
SB 510-34-05 *34SB-05*	DUAL DIVERSITY TRANSPONDER INSTALLATION	KSWF		OPTIONAL	MTH HRS LDG	12-Nov-2016 1505.7 1236		A/R			Complete
	MOC : COMPLIED WITH										
SB 510-34-08 *34SB-08*	GARMIN TRANSPONDER HARDWARE IMPROVEMENT	LIN		MANDATORY	MTH HRS	16-Sep-2008 161		A/R			Complete
	MOC : COMPLIED WITH										
SB 510-34-09 *34SB-09*	GARMIN G1000 SOFTWARE VERSION 010-00435-16 UPGRADE	HUR		RECOMMENDED	MTH HRS	18-Sep-2009 289		A/R			Complete
	MOC : COMPLIED WITH										
SB 510-34-10 *34SB-10*	GARMIN SYNTHETIC VISION TECHNOLOGY INSTALLATION	GSO		OPTIONAL	MTH HRS LDG	16-Jun-2024 2928.5 2890		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SERVICE BULLETIN SB510-34-10SYNTHETIC VISION TECHNOLOGY INSTALLATION. VERIFIED AFT SUPPLEMENT IS AT REVISION 2. OPERATIONAL CHECKS GOOD.										
SB 510-34-11 REV 01	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-21 UPGRADE	DUS		MANDATORY	MTH HRS LDG	17-Aug-2011 403 255		A/R			Complete
	MOC : COMPLIED WITH										

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB 510-34-12 REV 01	GARMIN DISPLAY IMPROVEMENT	SWF		MANDATORY	MTH HRS LDG	17-Aug-2012 619.5 475		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SB510-34-12 R1 GARMIN DISPLAY IMPROVEMENT. CHANGED THE DIMING SWITCH WIRING PER ACCOMPLISHMENT INSTRUCTIONS.										
SB 510-34-12	GARMIN DISPLAY IMPROVEMENT (SUPERSEDED BY 510-34-12 REV 01)			MANDATORY	MTH			-			
	MOC :										
SB 510-34-14	NAVIGATION - GARMIN G1000 SOFTWARE VERSION 010-00435-24 UPGRADE	SWF		MANDATORY	MTH HRS LDG	17-Aug-2012 619.5 475		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SB510-34-14 GARMIN G1000 SOFTWARE VERSION 010-00435-24 UPGRADE PER ACCOMPLISHMENT INSTRUCTIONS.										
SB 510-34-16 REV 01	NAVIGATION - GARMIN GRS-77 AHRS SOFTWARE UPDATE	KAQW		MANDATORY	MTH HRS LDG	16-Dec-2016 1521.9 1252		-			Complete
	MOC : COMPLIED WITH - THE REQUIREMENTS OF THIS SB ARE FOUND MET BY PREVIOUS COMPLETION SOFTWARE UPDATES COMPLETED IN SB 510-34-17 R1 ON NOVEMBER 12, 2016										
SB 510-34-17 REV 01	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY 510-34-17 REV 02)	KSWF		OPTIONAL	MTH HRS LDG	12-Nov-2016 1505.7 1236		-			Complete
	MOC : COMPLIED WITH										
SB 510-34-17 REV 02	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE (SUPERSEDED BY SB 510-34-17 REV 03)			OPTIONAL				-			
	MOC :										
SB 510-34-17 REV 03	NAVIGATION - GARMIN G1000 ADS-B OUT INSTALLATION WITH SOFTWARE UPGRADE			OPTIONAL				-			
	MOC :										
SB 510-34-18	NAVIGATION - GARMIN G1000 ADS-B OUT SOFTWARE UPDATE	KGYH		RECOMMENDED	MTH HRS LDG	05-Oct-2020 2276.8 1881		-			N/A
	MOC : NOT APPLICABLE - 1.13) THIS SB IS NOT APPLICABLE TO THIS AIRCRAFT AS IT HAS A G1000 NXI FLIGHT DECK.										
SL CIL-34-07	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1604 WORLDWIDE NAVIGATION DATABASE			INFORMATIONAL				-			
	MOC :										
COM MC ALL - 007	GPS/SBAS APPROACH DOWNGRADES DUE TO GEOMAGNETIC ACTIVITY			INFORMATIONAL	MTH			-			
	MOC :										
SL 510-34-03 *34SL-03*	TRANSMITTAL OF GARMIN SERVICE ADVISORY NUMBER 0745 REVISION A, G1000 WAAS GPS CDI SCALING			INFORMATIONAL	MTH			A/R			
	MOC :										
SL 510-34-04 *34SL-04*	TRANSMITTAL OF GARMIN SERVICE ALERT NO. 0816	LIN		MANDATORY	MTH HRS	05-Dec-2008 188		A/R			Complete
	MOC : COMPLIED WITH										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SL 510-34-09 *34SL-09*	GROUNDING STRIP INSPECTION	HUR		MANDATORY	MTH HRS	17-Dec-2009 324		A/R			Complete
	MOC : COMPLIED WITH										
SL 510-34-11	STORED FLIGHT PLAN DELETION PER GARMIN SERVICE ADVISORY 0929 REV A			INFORMATIONAL				A/R			
	MOC :										
SL 510-34-15	TRANSMITTAL OF GARMIN SERVICE BULLETIN 1017 GWX 68 WEATHER RADAR MOD 1	DUS		RECOMMENDED	MTH HRS LDG	17-Aug-2011 403 255		A/R			Complete
	MOC : COMPLIED WITH										
SL 510-34-16	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1041 - GDL 69/69A NEXRAD WEATHER REPORTING ISSUE			INFORMATIONAL				A/R			
	MOC :										
SL 510-34-17	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1101 - GDL 69/69A TFR (TEMPORARY FLIGHT RESTRICTIONS) REPORTING ISSSUE			INFORMATIONAL				A/R			
	MOC :										
SL 510-34-18	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1107 - ANOMALIES IN GREENLAND TERRAIN DATA MAY INHIBIT OPERATIONAL CAPABILITY AND GARMIN TERRAIN DATA ALERT - ANOMALIES IN GREENLAND TERRAIN DATA			INFORMATIONAL				A/R			
	MOC :										
SL 510-34-19	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1118 - MOMENTARY FAILURE INDICATIONS (RED X) CAN OCCUR WHEN SORTING STORED FLIGHT PLANS			INFORMATIONAL				A/R			
	MOC :										
SL 510-34-20	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO. 1129 - MOMENTARY LOSS OF GRS 77/77H AND GDC 74A/74B/74H FUNCTIONS			INFORMATIONAL				A/R			
	MOC :										
SL 510-34-21	GARMIN G1000 GRS77 AHRS HEADING DRIFT CONDITION			INFORMATIONAL				-			
	MOC :										
SL 510-34-22	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY NO 1612 2015 IGRF (INTERNATIONAL GEOMAGNETIC REFERENCE FIELD) MAGNETIC FIELD MODEL			INFORMATIONAL				-			
	MOC :										
SL 510-34-23	NAVIGATION - GARMIN G1000 DATABASE CARD REPLACEMENT	KAQW		RECOMMENDED	MTH HRS LDG	21-Jun-2017 1636.8 1319		-			Complete
	MOC : COMPLIED WITH - INSPECTED; FOUND AIRCRAFT IN COMPLIANCE WITH SL-510-34-23.										
SL 510-34-24	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1729 (REV A) LOCKED WAYPOINTS			INFORMATIONAL				-			
	MOC :										
SL 510-34-25	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1838 EMERGENCY DESCENT MODE (EDM)			INFORMATIONAL				-			
	MOC :										
SL 510-34-26	NAVIGATION - TRANSMITTAL OF GARMIN SERVICE ADVISORY 1802 INCORRECT DIRECT-TO NAVIGATION FOLLOWING INTERCEPT (INTRCPT) LEG			INFORMATIONAL				-			
	MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SL 510-34-27	NAVIGATION - TRANSMITTAL OF GARMIN SB 2046, GRS 77 SOFTWARE VERSION 3.04 - PITCH/ROLL OFFSET CALIBRATION PROCEDURE (G1000 WITH DUAL GRS AND THREE DISPLAYS)			INFORMATIONAL			-			
	MOC :									
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	KAQW	MANDATORY		MTH DAYS 04-Dec-2015 HRS 1252.8 LDG 1016		-			N/A
	MOC : NOT APPLICABLE - BY PART NUMBERS AND SERIAL NUMBERS, PILOT AND COPILOT MASKS									
SL 510-35-01 REV 01	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SL510-35-01 REV 02)	SWF	MANDATORY		MTH 17-Aug-2012 HRS 619.5 LDG 475		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SL510-35-01 R1 TRANSMITTAL OF INTERECHNIQUE SERVICE BULLETIN MXH-35-240. INSPECTED AND FOUND PILOTS AND CO-PILOTS MASKS REQUIRE REPLACEMENT.									
SL 510-35-01 REV 02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240		MANDATORY				-			
	MOC :									
SL 510-35-01	INSPECTION FOR POTENTIAL DEFECTIVE COMPONENT - OXYGEN - HARNESS ASSEMBLY (SUPERSEDED BY SL510-35-01REV 01)		MANDATORY				-			
	MOC :									
SB 510-52-03 *52SB-03*	NOSE BAGGAGE DOOR HINGE IMPROVEMENT	LIN	RECOMMENDED		MTH 16-Sep-2008 HRS 161		A/R			Complete
	MOC : COMPLIED WITH									
SB 510-52-05	AFT BAGGAGE DOOR MODIFICATION	SWF	DISCRETIONARY		MTH 12-Sep-2012 HRS 635.4 LDG 509		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SB510-52-05, AFT BAGGAGE DOOR MODIFICATION SERVICE BULLETIN PER ACCOMPLISHMENT INSTRUCTIONS.									
MSB 510-52-06	DOORS - EMERGENCY ESCAPE HATCH INNER HANDLE HARDWARE REPLACEMENT	KGMU	MANDATORY		DAYS 16-Jul-2020 HRS 2225.1 LDG 1829		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SERVICE BULLETIN SB510-52-06.WORK WAS ALSO PERFORMED BY CHRISTOPHER NELSON.									
SL 510-52-01 REV 01	CABIN ENTRY DOOR HINGE FASTENER INSPECTION	DUS	MANDATORY		MTH 31-Oct-2011 HRS 403 LDG 255		A/R			Complete
	MOC : COMPLIED WITH									
SL 510-52-01 *52SL-01*	CABIN ENTRY DOOR HINGE FASTENER INSPECTION (SUPERSEDED BY SL510-52-01 REV 01)	HUR	MANDATORY		MTH 18-Sep-2009 HRS 289		A/R			Complete
	MOC : COMPLIED WITH									
SL 510-52-04	DOORS - CABIN ENTRY DOOR PIN REPAIR		INFORMATIONAL				A/R			
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SL 510-52-06	DOORS - INSPECT AND TORQUE THE INNER ESCAPE HATCH HANDLE BOLT AND NUT	KGMU		MANDATORY	DAYS 23-Jan-2020 HRS 2153.6 LDG 1739		-			Complete
	MOC : COMPLIED WITH - 1.4) COMPLIED WITH SL 510-52-06: INSPECTED AND TORQUED THE INNER ESCAPE HATCH HANDLE AND BOLT. NO DEFECTS NOTED.									
SB 510-53-01 *53SB-01*	AFT CABIN STRUCTURE INSPECTION	HUR		MANDATORY	MTH 17-Dec-2009 HRS 324		A/R			Complete
	MOC : COMPLIED WITH									
ASL 510-53-02 *53ASL02*	TAILCONE SEALANT INSPECTION (SUPERSEDED BY ASL510-53-02 REV 01)	LIN		MANDATORY	MTH 24-Nov-2008 HRS 185		-			Complete
	MOC : COMPLIED WITH									
SL 510-53-01 *53SL-01*	FORWARD PRESSURE BULKHEAD INSPECTION	LIN		RECOMMENDED	MTH 16-Sep-2008 HRS 161		A/R			Complete
	MOC : COMPLIED WITH									
SL 510-53-03	FUSELAGE - DRAIN HOLE INSPECTION	DUS		MANDATORY	MTH 17-Aug-2011 HRS 403 LDG 255		A/R			Complete
	MOC : COMPLIED WITH									
SB 510-54-01 REV 01	PYLON SKIN IMPROVEMENTS			DISCRETIONARY			-			
	MOC :									
ASL 510-54-01 *54ASL01*	PYLON RAM AIR DUCT VISUAL INSPECTION	LIN		MANDATORY	MTH 12-Mar-2008 HRS 109		A/R			Complete
	MOC : COMPLIED WITH									
SL 510-55-02 REV 01	HORIZONTAL STABILIZER SEALANT INSPECTION (SUPERSEDED BY SL510-55-02 REV 02)			MANDATORY	DAYS		A/R			
	MOC :									
SL 510-55-02 REV 02	HORIZONTAL STABILIZER SEALANT INSPECTION	DUS		MANDATORY	DAYS 31-Oct-2011 HRS 403 LDG 255		A/R			Complete
	MOC : COMPLIED WITH									
SL 510-55-02	STABILIZERS - HORIZONTAL STABILIZER SEALANT INSPECTION (SUPERSEDED BY SL510-55-02 REV 01)			MANDATORY			A/R			
	MOC :									
SB 510-56-01 *56SB-01*	WINDSHIELD SCREW SEALING IMPROVEMENT	LIN		MANDATORY	MTH 19-May-2008 HRS 123		A/R			Complete
	MOC : COMPLIED WITH									
SB 510-56-02 *56SB-02*	CABIN WINDOW FROST PANE MODIFICATION	HUR		DISCRETIONARY	MTH 18-Sep-2009 HRS 289		A/R			Complete
	MOC : COMPLIED WITH									
SL 510-56-01 *56SL-01*	WINDSHIELD WIRE BUNDLE ASSEMBLY INSPECTION	HUR		MANDATORY	MTH 18-Sep-2009 HRS 289		A/R			Complete
	MOC : COMPLIED WITH									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SL 510-57-01 REV 01 *57SL-01 : 510R1*	FLAP HINGE INSPECTION	HUR		MANDATORY	MTH HRS	17-Dec-2009 324		-			Complete
	MOC : COMPLIED WITH										
SB PW600-72-63002 E1	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS			CATEGORY 5	MTH	23-Mar-2007		-			Complete
	MOC : COMPLIED WITH										
SB PW600-72-63002 E2	REPLACEMENT OF TURBINE EXHAUST CASE (TEC) COWL BRACKETS	UNK		CATEGORY 5	MTH	13-Apr-2017		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63003 E1	INTRODUCTION OF ADDITIONAL BALANCING WEIGHTS FOR THE FAN TRIM BALANCE			CATEGORY 9	MTH	23-Mar-2007		-			Complete
	MOC : COMPLIED WITH										
SB PW600-72-63005 E1	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING			CATEGORY 5	MTH	23-Mar-2007		-			Complete
	MOC : COMPLIED WITH										
SB PW600-72-63005 E2	REPLACEMENT OF BLEED-VALVE-ASSEMBLY BALL BEARING	UNK		CATEGORY 5	MTH	13-Apr-2017		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63006 E1	REPLACEMENT OF SHIPPING CONTAINER HARDWARE			CATEGORY 9	MTH	23-Mar-2007		-			Complete
	MOC : COMPLIED WITH										
SB PW600-72-63006 E2	REPLACEMENT OF SHIPPING CONTAINER HARDWARE	UNK		CATEGORY 9	MTH	13-Apr-2017		-			Complete
	MOC : COMPLIED WITH - AT MANUFACTURE										
SB PW600-72-63007 E1	REPLACEMENT OF TURBINE EXHAUST CASE COWL ASSEMBLY			CATEGORY 7	MTH	23-Mar-2007		-			Complete
	MOC : COMPLIED WITH										
SB PW600-72-63010 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY			CATEGORY 8	MTH			-			
	MOC :										
SB PW600-72-63012 R01 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY			CATEGORY 7				A/R			
	MOC :										
SB PW600-72-63012 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY (SUPERSEDED BY PW600-72-63012 R01)			CATEGORY 6	MTH	23-Mar-2007		-			Complete
	MOC : COMPLIED WITH										
SB PW600-72-63013 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7				-			
	MOC :										
SB PW600-72-63013 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63013 R01)	*CF		CATEGORY 7	MTH			-			
	MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB PW600-72-63016 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER ASSEMBLY	*CF		CATEGORY 7	MTH			-			
	MOC :										
SB PW600-72-63017 R01 E1	INTRODUCTION OF CLASSIFIED SPACERS			CATEGORY 7				-			
	MOC :										
SB PW600-72-63017 R01 E2	INTRODUCTION OF CLASSIFIED SPACERS			CATEGORY 7	MTH			-			
	MOC :										
SB PW600-72-63017 E1	INTRODUCTION OF CLASSIFIED SPACERS (SUPERSEDED BY PW600-72-63017 R01)	*CF		CATEGORY 7	MTH			-			
	MOC :										
SB PW600-72-63019 R01 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY			CATEGORY 6				-			
	MOC :										
SB PW600-72-63019 R01 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY			CATEGORY 6	MTH			-			
	MOC :										
SB PW600-72-63019 E1	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01)			CATEGORY 9	MTH			-			
	MOC :										
SB PW600-72-63019 E2	INTRODUCTION OF SHIPPING BRACKET ASSEMBLY (SUPERSEDED BY PW600-72-63019 R01)	UNK		CATEGORY 9	MTH HRS LDG	21-Dec-2007 1019.2 718		-			Complete
	MOC : COMPLIED WITH										
SB PW600-72-63022 R01 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02)			CATEGORY 7				-			
	MOC :										
SB PW600-72-63022 R01 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R02)			CATEGORY 7				-			
	MOC :										
SB PW600-72-63022 R02 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7				-			
	MOC :										
SB PW600-72-63022 R02 E2	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY			CATEGORY 7				-			
	MOC :										
SB PW600-72-63022 E1	REPLACEMENT OF COMPRESSOR IMPELLER AND SHAFT ASSEMBLY (SUPERSEDED BY PW600-72-63022 R01)	*CF		CATEGORY 7	MTH			-			
	MOC :										
SB PW600-72-63024 E1	REPLACEMENT OF NO. 4 ROLLER BEARING	*CF		CATEGORY 7	MTH			-			
	MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB PW600-72-63025 E1	REPLACEMENT OF SEAL RUNNER	*CF		CATEGORY 7	MTH			-			
	MOC :										
SB PW600-72-63026 E1	REPLACEMENT OF SHIPPING CONTAINER ASSEMBLY			CATEGORY 9	MTH			-			
	MOC :										
SB PW600-72-63027 R01 E1	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY	*CF		CATEGORY 8	MTH			-			
	MOC :										
SB PW600-72-63027 R01 E2	INSPECTION OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY	UNK		CATEGORY 8	MTH HRS LDG	21-Dec-2007 1019.2 718		-			Complete
	MOC : COMPLIED WITH										
SB PW600-72-63028 R01 E1	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY			CATEGORY 5	MTH			-			
	MOC :										
SB PW600-72-63028 E2	REPLACEMENT OF NO.1-BEARING AIR-SEAL-RUNNER ASSEMBLY (SUPERSEDED BY PW600-72-63028 R01)	UNK		CATEGORY 5	MTH HRS LDG	21-Dec-2007 1019.2 718		-			Complete
	MOC : COMPLIED WITH										
SB PW600-72-63031 R01 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY			CATEGORY 7				A/R			
	MOC :										
SB PW600-72-63031 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63031 R01)			CATEGORY 7	MTH			-			
	MOC :										
SB PW600-72-63032 E1	REPLACEMENT OF HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR BALANCING RING	*CF		CATEGORY 7	MTH			-			
	MOC :										
SB PW600-72-63034 R01 E1	REPLACEMENT OF OIL PUMP PLATE			CATEGORY 6				-			
	MOC :										
SB PW600-72-63034 R01 E2	REPLACEMENT OF OIL PUMP PLATE			CATEGORY 6				-			
	MOC :										
SB PW600-72-63034 E1	REPLACEMENT OF OIL PUMP PLATE	*CF		CATEGORY 8	MTH			-			
	MOC :										
SB PW600-72-63035 E1	REPLACEMENT OF NO. 1 BEARING SUPPORT ASSEMBLY			CATEGORY 7	MTH			-			
	MOC :										

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB PW600-72-63037 R01 E1	REPLACEMENT OF ENGINE MOUNT BRACKET ASSEMBLY **MOC :**			CATEGORY 7	MTH			-			
SB PW600-72-63039 E1	REPLACEMENT OF LPT VANE RING ASSEMBLY **MOC :**			CATEGORY 7	MTH			-			
SB PW600-72-63040 E1	MODIFICATION/REPLACEMENT OF FRONT OUTER BYPASS DUCT ASSEMBLY **MOC :**			CATEGORY 7	MTH			-			
SB PW600-72-63041 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSEMBLY **MOC :**			CATEGORY 7	MTH			-			
SB PW600-72-63042 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY **MOC :**			CATEGORY 7	MTH			-			
SB PW600-72-63043 R01 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER (SUPERSEDED BY PW600-72-63043 R02) **MOC :**			CATEGORY 6	MTH			-			
SB PW600-72-63043 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY AND NOSE CONE SHIPPING COVER (SUPERSEDED BY PW600-72-63043 R01) **MOC :** COMPLIED WITH - PREVIOUSLY	UNK		CATEGORY 6	MTH HRS LDG	23-Apr-2007 1019.2 718		-			Complete
SB PW600-72-63044 E1	INSPECTION OF EXTERNAL JUNCTION BOX BRACKET ASSEMBLY **MOC :**			CATEGORY 6				-			
SB PW600-72-63045 R01 E1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY **MOC :**							-			
SB PW600-72-63045 E1	REPLACEMENT OF OIL NOZZLE HOUSING ASSEMBLY (SUPERSEDED BY PW600-72-63045 R01) **MOC :**			CATEGORY 7	MTH			-			
SB PW600-72-63051 R01 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R02) **MOC :**			CATEGORY 7	MTH			-			
SB PW600-72-63051 R02 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBE ASSEMBLIES (SUPERSEDED BY PW600-72-63051 R03) **MOC :**			CATEGORY 6				-			
SB PW600-72-63051 R03 E1	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBEASSEMBLIES **MOC :**			CATEGORY 6				-			
SB PW600-72-63051 R03 E2	REPLACEMENT OF DIFFUSER CASE ASSEMBLY, NO. 4 BEARING OIL PRESSURE AND SCAVENGE TUBEASSEMBLIES **MOC :**			CATEGORY 6				-			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB PW600-72-63052 R01 E1	COMPRESSOR CASE ASSEMBLY AND NO. 1 TO NO. 3 BEARING OIL-PRESSURE TUBE-ASSEMBLY - REPLACEMENT OF			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63052 E1	REPLACEMENT OF COMPRESSOR CASE ASSEMBLY AND NO. 123 BEARING OIL-PRESSURE TUBE-ASSEMBLY (SUPERSEDED BY PW600-72-63052 R01)			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63053 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS			CATEGORY 7			-			
	MOC :									
SB PW600-72-63053 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR SEAL RUNNERS (SUPERSEDED BY PW600-72-63053 R01)			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63057 E1	REPLACEMENT OF NO. 5 BEARING SEAL RUNNER			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63058 E1	PARTS SUBSTITUTION LIST			CATEGORY 9			-			
	MOC :									
SB PW600-72-63058 E2	PARTS SUBSTITUTION LIST			CATEGORY 9			-			
	MOC :									
SB PW600-72-63059 R01 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R02)			CATEGORY 6			-			
	MOC :									
SB PW600-72-63059 R02 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY						-			
	MOC :									
SB PW600-72-63059 E1	MODIFICATION/REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY (SUPERSEDED BY PW600-72-63059 R01)			CATEGORY 6	MTH		-			
	MOC :									
SB PW600-72-63062 R01 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL						A/R			
	MOC :									
SB PW600-72-63062 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL (SUPERSEDED BY PW600-72-63062 R01)			CATEGORY 7	MTH		-			
	MOC :									
SB PW600-72-63063 E1	INTRODUCTION OF NO.1 TO 3 BEARING OIL-PRESSURE TUBE GASKET			CATEGORY 8			-			
	MOC :									
SB PW600-72-63063 E2	INTRODUCTION OF NO.1 TO 3 BEARING OIL-PRESSURE TUBE GASKET			CATEGORY 8			-			
	MOC :									

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB PW600-72-63064 R01 E1	REPLACEMENT/MODIFICATION OF N0. 4 BEARING OIL PRESSURE TUBE ASSEMBLY(SUPERSEDED BY PW600-72-63064 R02) CATEGORY 6						A/R			
	MOC :									
SB PW600-72-63064 R02 E1	REPLACEMENT/MODIFICATION OF N0. 4 BEARING OIL PRESSURE TUBE ASSEMBLY						-			
	MOC :									
SB PW600-72-63064 E1	REPLACEMENT/MODIFICATION OF N0. 4 BEARING OIL PRESSURE TUBE ASSEMBLY (SUPERSEDED BY PW600-72-63064 R01) CATEGORY 6			MTH			-			
	MOC :									
SB PW600-72-63065 R01 E1	NO. 5 ANNULAR ROLLER BEARING - REPLACEMENT OF CATEGORY 7						-			
	MOC :									
SB PW600-72-63066 E1	REPLACEMENT OF IGNITER CATEGORY 7			MTH			-			
	MOC :									
SB PW600-72-63068 R01 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY CATEGORY 6	KAQW		MTH 16-Mar-2012 HRS 499 LDG 349			A/R			Complete
	MOC : COMPLIED WITH									
SB PW600-72-63070 E1	DELETION OF FIRE-INSULATION BLANKET ASSEMBLY CATEGORY 6			MTH			A/R			
	MOC :									
SB PW600-72-63072 R01 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING CATEGORY 7						-			
	MOC :									
SB PW600-72-63072 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING (SUPERSEDED BY PW600-72-63072 R01) CATEGORY 7						A/R			
	MOC :									
SB PW600-72-63074 R01 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW600-72-63074 R01 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 6						-			
	MOC :									
SB PW600-72-63074 R02 E1	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 6			MTH			-			
	MOC :									
SB PW600-72-63074 R02 E2	REPLACEMENT OF IMPELLER HOUSING ASSEMBLY CATEGORY 6			MTH			-			
	MOC :									
SB PW600-72-63076 R01 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY CATEGORY 7						-			
	MOC :									

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB PW600-72-63076 R01 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW600-72-63077 R01 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63077 R02 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR			CATEGORY 6			-			
	MOC :									
SB PW600-72-63077 R02 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR			CATEGORY 6			-			
	MOC :									
SB PW600-72-63077 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT AND SPIRAL BEVEL GEAR (SUPERSEDED BY PW600-72-63077 R01)			CATEGORY 6			A/R			
	MOC :									
SB PW600-72-63078 E1	REPLACEMENT OF HIGH PRESSURE IMPELLER			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63080 R02 E1	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR)			CATEGORY 6			-			
	MOC :									
SB PW600-72-63080 R02 E2	REPLACEMENT / MODIFICATION OF ELECTRICAL WIRING HARNESS (TT0 SENSOR)			CATEGORY 6			-			
	MOC :									
SB PW600-72-63081 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL			CATEGORY 5			A/R			
	MOC :									
SB PW600-72-63081 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63081 R01)			CATEGORY 5			A/R			
	MOC :									
SB PW600-72-63083 R01 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL			CATEGORY 7			-			
	MOC :									
SB PW600-72-63083 E1	REPLACEMENT OF NO.4-BEARING FRONT AND REAR CARBON SEAL (SUPERSEDED BY PW600-72-63083 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63084 E1	REPLACEMENT OF FLANGE DUPLEX BEARING (IC)			CATEGORY 7			A/R			
	MOC :									
SB PW600-72-63085 E1	TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - MODIFICATION/REPLACEMENT OF			CATEGORY 7			-			
	MOC :									
SB PW600-72-63086 E1	REPLACEMENT OF TURBOFAN ENGINE DIFFUSER EXIT DUCT ASSEMBLY			CATEGORY 7			A/R			
	MOC :									

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB PW600-72-63087 R01 E1	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL (SUPERSEDED BY PW600-72-63087 R02)	SWF		CATEGORY 3	MTH HRS LDG	17-Aug-2012 619.5 475		- 			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SB510-76-01 REV 1, TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW600-72-63087, UPDATE OF FADEC SOFTWARE, PERACCOMPLISHMENT INSTRUCTIONS. OPERATIONAL CHECKS GOOD.										
SB PW600-72-63087 R02 E1	REPLACEMENT/MODIFICATION OF ENGINE ELECTRONIC CONTROL			CATEGORY 3	MTH			-			
	MOC :										
SB PW600-72-63088 E1	REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY			CATEGORY 7				A/R			
	MOC :										
SB PW600-72-63089 R01 E1	FUEL METERING UNIT - REPLACMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R02)			CATEGORY 6				A/R			
	MOC :										
SB PW600-72-63089 R02 E1	FUEL METERING UNIT - REPLACEMENT/MODIFICATION OF			CATEGORY 6				-			
	MOC :										
SB PW600-72-63089 E1	FUEL METERING UNIT - REPLACMENT/MODIFICATION OF (SUPERSEDED BY PW600-72-63089 R01)			CATEGORY 6				-			
	MOC :										
SB PW600-72-63090 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC)			CATEGORY 7				A/R			
	MOC :										
SB PW600-72-63091 R01 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS (SUPERSEDED BY PW600-72-63091 R02)			CATEGORY 6				-			
	MOC :										
SB PW600-72-63091 R02 E1	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS			CATEGORY 6				-			
	MOC :										
SB PW600-72-63091 R02 E2	INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS			CATEGORY 6				-			
	MOC :										
SB PW600-72-63091 E1	PRIMARY AND SECONDARY FUEL FAIRING REDUCERS - INSPECTION OF (SUPERSEDED BY PW600-72-63091 R01)			CATEGORY 6				-			
	MOC :										
SB PW600-72-63092 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT			CATEGORY 7				-			
	MOC :										
SB PW600-72-63093 E1	REPOSITIONING OF OIL FILLER CAP ASSEMBLY BRACKET			CATEGORY 6				A/R			
	MOC :										
SB PW600-72-63094 R01 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS			CATEGORY 7				-			
	MOC :										

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB PW600-72-63094 E1	REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-72-63094 R01) CATEGORY 7 **MOC :**						-			
SB PW600-72-63095 E1	TURBOFAN ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF CATEGORY 7 **MOC :**						-			
SB PW600-72-63096 E1	REPLACEMENT OF OIL NOZZLE ASSEMBLY CATEGORY 7 **MOC :**						-			
SB PW600-72-63097 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) **MOC :**						-			
SB PW600-72-63097 R02 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 6 **MOC :**						-			
SB PW600-72-63097 R02 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 6 **MOC :**						-			
SB PW600-72-63097 E1	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-63097 R01) **MOC :**						-			
SB PW600-72-63098 R01 E1	INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY CATEGORY 3 **MOC :**		MTH				HSI HSI			
SB PW600-72-63098 R01 E2	INSPECTION OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY CATEGORY 3 **MOC :**		MTH				HSI HSI			
SB PW600-72-63098 E1	INSPECTION OF - HP DIFFUSER CASE ASSY CATEGORY 5 **MOC :**						-			
SB PW600-72-63099 E1	REPLACEMENT OF BLEED VALVE ACTUATOR BRACKET CATEGORY 7 **MOC :**						-			
SB PW600-72-63100 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT **MOC :**						-			
SB PW600-72-63101 R01 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 5 **MOC :**						-			
SB PW600-72-63101 R01 E2	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY CATEGORY 5 **MOC :**						-			

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB PW600-72-63101 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY	UNK		RECOMMENDED	MTH HRS LDG	08-Dec-2017 1752.6 1398		-			Complete
	MOC : COMPLIED WITH										
SB PW600-72-63102 R01 E1	REPLACEMENT OF NO.4 - BEARING FRONT AND REAR CARBON SEAL			RECOMMENDED				-			
	MOC :										
SB PW600-72-63103 E1	REPLACEMENT OF FUEL FILTER IMPENDING BYPASS SWITCH							-			
	MOC :										
SB PW600-72-63104 E1	REPLACEMENT/MODIFICATION OF FAN CASE			CATEGORY 7				-			
	MOC :										
SB PW600-72-63105 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)			CATEGORY 7				-			
	MOC :										
SB PW600-72-63105 R01 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)			CATEGORY 7				-			
	MOC :										
SB PW600-72-63105 R02 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)			CATEGORY 7				-			
	MOC :										
SB PW600-72-63105 R02 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE)			CATEGORY 7				-			
	MOC :										
SB PW600-72-63105 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01)			CATEGORY 7				-			
	MOC :										
SB PW600-72-63105 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) (SUPERSEDED BY PW600-72-63105 R01)			CATEGORY 7	MTH			-			
	MOC :										
SB PW600-72-63106 R01 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER			CATEGORY 5				-			
	MOC :										
SB PW600-72-63106 R01 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER			CATEGORY 5				-			
	MOC :										
SB PW600-72-63106 E1	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01)			CATEGORY 5				-			
	MOC :										
SB PW600-72-63106 E2	RE-IDENTIFICATION OF AGB HOUSING AND COVER (SUPERSEDED BY PW600-72-63106 R01)			CATEGORY 5	MTH			-			
	MOC :										

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB PW600-72-63107 E1	REPLACEMENT OF TURBINE EXHAUST CASE			CATEGORY 7				-			
	MOC :										
SB PW600-72-63107 E2	REPLACEMENT OF TURBINE EXHAUST CASE			CATEGORY 7	MTH			-			
	MOC :										
SB PW600-72-63108 R01 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7				-			
	MOC :										
SB PW600-72-63108 R01 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7				-			
	MOC :										
SB PW600-72-63108 E1	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7				-			
	MOC :										
SB PW600-72-63108 E2	REPLACEMENT OF NO. 3 FLANGED BALL BEARING			CATEGORY 7				-			
	MOC :										
SB PW600-72-63109 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE			CATEGORY 5				-			
	MOC :										
SB PW600-72-63109 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEALS AND IMPELLER BAFFLE			CATEGORY 5				-			
	MOC :										
SB PW600-72-63110 E1	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE			CATEGORY 5				-			
	MOC :										
SB PW600-72-63110 E2	VALIDATION OF NO. 3 BEARING ASSEMBLY PROCEDURE			CATEGORY 5				-			
	MOC :										
SB PW600-72-63111 E1	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING	KGSO		CATEGORY 3	MTH HRS LDG	24-Oct-2019 2093.6 1565		-			N/A
	MOC : NOT APPLICABLE - SB PW600-72-63111 DOES NOT APPLY DUE TO PN# AND SN# INSTALLED.										
SB PW600-72-63111 E2	INSPECTION OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE PACKING	KGSO		CATEGORY 3	MTH HRS LDG	24-Oct-2019 2091.4 1607		-			N/A
	MOC : NOT APPLICABLE - SB PW600-72-63111 DOES NOT APPLY DUE TO PN# AND SN# INSTALLED.										
SB PW600-72-63112 E1	INSPECTION OF ACCESSORY GEARBOX BREATHER SEAL	KGMU		CATEGORY 3	MTH HRS LDG	15-Aug-2022 2660.1 2592		-			N/A
	MOC : NOT APPLICABLE - NO APPLICABLE, PART HAS NOT BEEN CHANGED DURING THE TIME FRAME CALLED OUT.										

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB PW600-72-63112 E2	INSPECTION OF ACCESSORY GEARBOX BREATHER SEAL	KGMU		CATEGORY 3	MTH HRS LDG	15-Aug-2022 2661 2512		-			N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE, PART HAS NOT BEEN CHANGED DURING THE TIME FRAME CALLED OUT.										
SB PW600-72-63113 E1	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL	KGMU		CATEGORY 7	MTH HRS LDG	03-Mar-2023 2775.4 2681		-			Complete
	MOC : COMPLIED WITH - R&R NO. 1 ENGINE AGB PLAIN SEAL WITH A NEW SEAL P/N 35C6535. LEAK CHECK GOOD.										
SB PW600-72-63113 E2	REPLACEMENT OF ACCESSORY-GEARBOX (AGB) PLAIN SEAL			CATEGORY 7				-			
	MOC :										
SB PW600-72-63114 R01 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 5				-			
	MOC :										
SB PW600-72-63114 R01 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 5				-			
	MOC :										
SB PW600-72-63114 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 7				-			
	MOC :										
SB PW600-72-63114 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 7				-			
	MOC :										
SB PW600-72-63116 R01 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY			CATEGORY 7				-			
	MOC :										
SB PW600-72-63116 R01 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY			CATEGORY 7				-			
	MOC :										
SB PW600-72-63116 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY			CATEGORY 7				-			
	MOC :										
SB PW600-72-63116 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY			CATEGORY 7				-			
	MOC :										
SB PW600-72-63117 E1	INTRODUCTION OF NUT INTERCHANGEABILITY CONTROL (IC) NUMBER			CATEGORY 9				-			
	MOC :										
SB PW600-72-63117 E2	INTRODUCTION OF NUT INTERCHANGEABILITY CONTROL (IC) NUMBER			CATEGORY 9				-			
	MOC :										
SB PW600-72-63119 E1	REPLACEMENT OF IMPELLER-BAFFLE RETAINING RING			CATEGORY 5				-			
	MOC :										

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB PW600-72-63119 E2	REPLACEMENT OF IMPELLER-BAFFLE RETAINING RING			CATEGORY 5			-			
	MOC :									
SB PW600-72-63120 E1	INSPECTION OF GEARBOX-DRIVE SPIRAL-BEVEL GEARSHAFT			CATEGORY 3			-			
	MOC :									
SB PW600-72-63120 E2	INSPECTION OF GEARBOX-DRIVE SPIRAL-BEVEL GEARSHAFT			CATEGORY 3			-			
	MOC :									
ASB PW600-72-A63071 R01 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63071 R02)	HUR		CATEGORY 3	MTH 13-Feb-2010 HRS 336 LDG 217		A/R			Complete
	MOC : COMPLIED WITH - PW ASB 63071 COMPLETED.									
ASB PW600-72-A63071 R02 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE			CATEGORY 3			-			
	MOC :									
ASB PW600-72-A63071 R02 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE			CATEGORY 3			-			
	MOC :									
SB PW600-73-63030 R01 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS			CATEGORY 7			A/R			
	MOC :									
ASL 510-73-01 LEFT *73ASL01 : L*	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	HUR		MANDATORY	MTH 04-Nov-2009 HRS 310 LDG 195		A/R			Complete
	MOC : COMPLIED WITH - ASL510-73-01 COMPLETED AS PW ASB 63069 CARRIED OUT.									
ASL 510-73-01 RIGHT *73ASL01 : R*	TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 TITLED, TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	HUR		MANDATORY	MTH 15-Mar-2010 HRS 347 LDG 221		-			N/A
	MOC : NOT APPLICABLE - RIGHT TRANSMITTAL OF PRATT AND WHITNEY CANADA ALERT SERVICE BULLETIN A63069 - N/A SUPERSEEDED BY P&WC SB NO A63071									
ASL 510-73-02 LEFT ENGINE	TRANSMITTAL OF P&WC SERVICE BULLETIN A63071 - REPLACEMENT OF TURBOFANENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	LIML		MANDATORY	MTH 01-Oct-2010 HRS 387 LDG 243		A/R			Complete
	MOC : COMPLIED WITH - PREVIOUSLY FOUND PCW FOUND INSTALLED PN: 10940GA SN LH WA24698									
ASL 510-73-02 RIGHT ENGINE	TRANSMITTAL OF P&WC SERVICE BULLETIN A63071 - REPLACEMENT OF TURBOFAN ENGINE FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	LIML		MANDATORY	MTH 01-Oct-2010 HRS 387 LDG 243		A/R			Complete
	MOC : COMPLIED WITH - PREVIOUSLY FOUND PCW FOUND INSTALLED PN: 10940GA SN RH WA24575									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB PW600-1007-63009 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 8				MTH			-			
	MOC :										
SB PW600-72-63073 E1	REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE CATEGORY 6	UNK			MTH HRS LDG	08-Dec-2017 1752.6 1398		A/R			Complete
	MOC : COMPLIED WITH										
SB PW600-72-63075 E1	REPLACEMENT/MODIFICATION OF FUEL OIL/HEATER EXCHANGER (FOHE) CATEGORY 7							A/R			
	MOC :										
SB PW600-72-63079 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY CATEGORY 7							A/R			
	MOC :										
SB PW600-72-63080 R01 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R02) CATEGORY 6							A/R			
	MOC :										
SB PW600-72-63080 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR) (SUPERSEDED BY PW600-72-63080 R01) CATEGORY 6							A/R			
	MOC :										
SB PW600-72-63082 E1	INSPECTION OF BYPASS-DUCT FUEL FAIRING CATEGORY 5				MTH			A/R			
	MOC :										
ASB PW600-72-A63061 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R02) CATEGORY 3							A/R			
	MOC :										
ASB PW600-72-A63061 R02 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 3							A/R			
	MOC :										
ASB PW600-72-A63061 E1	REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY PW600-72-A63061 R01) CATEGORY 3							-			
	MOC :										
ASB PW600-72-A63069 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE (SUPERSEDED BY PW600-72-A63069 R01) CATEGORY 3	HUR			MTH HRS	04-Nov-2009 310		-			Complete
	MOC : COMPLIED WITH										
SB PW600-73-63004 E1	REPLACEMENT OF FUEL-SHUT-OFF-VALVE PIN CATEGORY 7				MTH	23-Mar-2007		-			Complete
	MOC : COMPLIED WITH										
SB PW600-73-63011 R01 E1	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) CATEGORY 8				MTH	23-Mar-2007		-			Complete
	MOC : COMPLIED WITH										

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB PW600-73-63011 R01 E2	REPROGRAMMING/ REPLACEMENT OF ELECTRONIC ENGINE CONTROL (EEC) **MOC :** COMPLIED WITH	UNK		CATEGORY 8	MTH 21-Dec-2007 HRS 1019.2 LDG 718		-			Complete
SB PW600-73-63014 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY **MOC :**	*CF		CATEGORY 7	MTH		-			
SB PW600-73-63020 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT **MOC :**	*CF		CATEGORY 8	MTH		-			
SB PW600-73-63020 E2	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT **MOC :** COMPLIED WITH	UNK		CATEGORY 8	MTH 24-Mar-2010 HRS 1019.2 LDG 718		-			Complete
SB PW600-73-63023 E1	REPLACEMENT OF FUEL SHUT-OFF CABLE ASSEMBLY **MOC :**	*CF		CATEGORY 7	MTH		-			
SB PW600-73-63029 E1	REPLACEMENT OF FUEL MANIFOLD ASSEMBLY **MOC :**	*CF		CATEGORY 7	MTH		-			
SB PW600-73-63030 E1	MODIFICATION/REPLACEMENT OF ELECTRICAL WIRING HARNESS (SUPERSEDED BY PW600-73-63030 R01) **MOC :**			CATEGORY 8	MTH		-			
SB PW600-73-63036 E1	REPLACEMENT OF FUEL DRAIN VALVE ADAPTER **MOC :**			CATEGORY 7	MTH		-			
SB PW600-73-63038 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) **MOC :**			CATEGORY 7	MTH		-			
SB PW600-73-63038 E2	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) **MOC :** COMPLIED WITH	UNK		CATEGORY 7	MTH 24-Mar-2010 HRS 1019.2 LDG 718		-			Complete
SB PW600-73-63048 E1	REPLACEMENT/MODIFICATION OF FUEL METERING UNIT **MOC :**			CATEGORY 7	MTH		-			
SB PW600-73-63049 E1	REPLACEMENT OF FUEL-SHUT-OFF LEVER SUPPORT **MOC :**			CATEGORY 7	MTH		-			
SB PW600-73-63115 R01 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL **MOC :**			CATEGORY 7	MTH		-			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB PW600-73-63115 R01 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL			CATEGORY 7	MTH			-			
	MOC :										
SB PW600-73-63115 E1	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL			CATEGORY 7				-			
	MOC :										
SB PW600-73-63115 E2	REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL			CATEGORY 7				-			
	MOC :										
SB PW600-74-63056 E1	REPLACEMENT OF IGNITION EXCITER			CATEGORY 7	MTH			-			
	MOC :										
SB PW600-74-63056 E2	REPLACEMENT OF IGNITION EXCITER			CATEGORY 7	MTH			-			
	MOC :										
SB PW600-72-63060 E1	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS			CATEGORY 6	MTH			-			
	MOC :										
SB PW600-72-63060 E2	REPLACEMENT OF BLEED-VALVE-ACTUATOR (BVA) BRACKET BOLTS			CATEGORY 6	MTH			-			
	MOC :										
SB PW600-75-63054 R01 E1	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA)			CATEGORY 7	MTH			-			
	MOC :										
SB PW600-75-63054 R01 E2	REPLACEMENT OF BLEED VALVE ACTUATOR (BVA)			CATEGORY 7	MTH			-			
	MOC :										
SB 510-76-01 REV 01	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW600-72-63087 (SUPERSEDED BY 510-76-01 REV 02)	SWF		MANDATORY	MTH HRS LDG	17-Aug-2012 619.5 475		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SB510-76-01 REV 1, TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW600-72-63087, UPDATE OF FADEC SOFTWARE, PER ACCOMPLISHMENT INSTRUCTIONS. OPERATIONAL CHECKS GOOD.										
SB 510-76-01 REV 02	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETN PW600-72-63087			MANDATORY	MTH			-			
	MOC :										
SB 510-76-02 REV 01	ENGINE CONTROLS - ANTI-ICE FADEC WIRING IMPROVEMENT			RECOMMENDED	MTH			-			
	MOC :										
SB 510-76-02	ENGINE CONTROLS - ANTI-ICE FADEC WIRING IMPROVEMENT			RECOMMENDED	MTH			-			
	MOC :										
SB PW600-77-63033 E1	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS			CATEGORY 8	MTH			-			
	MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB PW600-77-63033 E2	REPLACEMENT OF T6 THERMOCOUPLE WIRING HARNESS			CATEGORY 8	MTH			-			
	MOC :										
SB 510-79-02 *79SB-02*	OIL TEMPERATURE PROBE O-RING REPLACEMENT	LIN		RECOMMENDED	MTH HRS	16-Sep-2008 161		A/R			Complete
	MOC : COMPLIED WITH										
SB 510-79-03	OIL - OIL PRESSURE TRANSDUCER REPLACEMENT			OPTIONAL				-			
	MOC :										
SL 510-79-01 *79SL-01*	OIL PRESSURE TRANSMITTER INSPECTION	HUR		MANDATORY	MTH HRS	18-Sep-2009 289		-			Complete
	MOC : COMPLIED WITH										
SL 510-79-02	OIL PRESSURE TRANSMITTER CONNECTOR INSPECTION	DUS		MANDATORY	DAYS HRS LDG	17-Aug-2011 403 255		A/R			Complete
	MOC : COMPLIED WITH										
SIL GEN-153 R05 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06)			INFORMATIONAL				-			
	MOC :										
SIL GEN-153 R05 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06)			INFORMATIONAL				-			
	MOC :										
SIL GEN-153 R06 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL				-			
	MOC :										
SIL GEN-153 R06 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL				-			
	MOC :										
SIL GEN-153 R07 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL				-			
	MOC :										
SIL GEN-153 R07 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL				-			
	MOC :										
SIL GEN-153 R08 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION							-			
	MOC :										
SIL GEN-153 R08 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION							-			
	MOC :										
SIL GEN-153 R09 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL				-			
	MOC :										
SIL GEN-153 R09 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL				-			
	MOC :										
SIL GEN-153 R10 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL				-			
	MOC :										
SIL GEN-153 R10 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL				-			
	MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB PW600-72-63055 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER			CATEGORY 7	MTH			-			
	MOC :										
SB PW600-72-63055 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER			CATEGORY 7	MTH			-			
	MOC :										
SB PW600-72-63076 E1	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01)			CATEGORY 7				A/R			
	MOC :										
SB PW600-72-63076 E2	REPLACEMENT/MODIFICATION OF OIL FILLER AND INDICATOR ASSEMBLY (SUPERSEDED BY PW600-72-63076 R01)			CATEGORY 7	MTH			A/R			
	MOC :										
SB PW600-79-63008 E1	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R01)				MTH	23-Mar-2007		-			Complete
	MOC : COMPLIED WITH										
SB PW600-79-63008 E2	REPLACEMENT OF OIL PUMP HOUSING AND SPUR GEARS (SUPERSEDED BY PW600-79-63008 R01)	UNK			MTH HRS LDG	21-Dec-2007 1019.2 718		-			Complete
	MOC : COMPLIED WITH										
SB PW600-79-63015 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER			CATEGORY 7	MTH			-			
	MOC :										
SB PW600-79-63015 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER			CATEGORY 7	MTH			-			
	MOC :										
SB PW600-79-63018 E1	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER			CATEGORY 7	MTH			-			
	MOC :										
SB PW600-79-63018 E2	REPLACEMENT/MODIFICATION OF AIR COOLED OIL COOLER			CATEGORY 7	MTH			-			
	MOC :										
SB PW600-79-63046 E1	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH			CATEGORY 7	MTH			-			
	MOC :										
SB PW600-79-63046 E2	REPLACEMENT OF OIL FILTER IMPENDING BYPASS SWITCH			CATEGORY 7	MTH			-			
	MOC :										
SB PW600-79-63047 R01 E1	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R02)	LIN		CATEGORY 3	MTH HRS	19-May-2008 123		-			Complete
	MOC : COMPLIED WITH										

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
SB PW600-79-63047 R01 E2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R02)	UNK		CATEGORY 3	MTH 23-Apr-2007 HRS 1019.2 LDG 718		-			Complete
	MOC : COMPLIED WITH									
SB PW600-79-63047 R02 E1	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R03)	LIML		CATEGORY 3	MTH 01-Oct-2010 HRS 387 LDG 243		-			Complete
	MOC : COMPLIED WITH - PREVIOUSLY PCW CTA WR 095/08. NO ACTION REQUIRED BECAUSE PREVIOUS ISSUE AS BEEN COMPLIED WITH									
SB PW600-79-63047 R03 E1	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS			CATEGORY 3			-			
	MOC :									
SB PW600-79-63047 R03 E2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS			CATEGORY 3			-			
	MOC :									
SB PW600-79-63047 E2	REPLACEMENT OF AIR-COOLED OIL-COOLER PRESSURE-OIL-TUBE BOLTS (SUPERSEDED BY PW600-79-63047 R01)	UNK			MTH 23-Apr-2008 HRS 1019.2 LDG 718		-			Complete
	MOC : COMPLIED WITH									
SL 510-80-02	STARTING - STARTER/GENERATOR REPLACEMENT PROGRAM	KGYH		RECOMMENDED	MTH 05-Oct-2020 HRS 2276.8 LDG 1881		-			Complete
	MOC : COMPLIED WITH - 1.14) ACCOMPLISHED SL510-80-02 ON RIGHT ENGINE ONLY. REMOVED RIGHT STARTER/GENERATOR P/N 9912676-1, S/N 586C AND INSTALLED OVERHAULED STARTER/GENERATOR P/N 9912676-1, S/N 830D IN ACCORDANCE WITH CESSNA 510 MAINTENANCE MANUAL CHAPTER 80-10-10. STARTER OVERHAULED BY AMETEK ADVANCED INDUSTRIES INC. 4550 SOUTHEAST BLVD. WICHITA, KS 67210, CRS# OO2R064L, UNDER WO V1252277, DATED 29/JUN/2020.									
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
	MOC :									
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS						-			
				CANCELLED						
	MOC :									
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
	MOC :									
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
	MOC :									
SL CIL-99-05 REV 1	MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS			INFORMATIONAL	MTH		-			
	MOC :									
SL CIL-99-05	MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS			INFORMATIONAL			-			
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
FAA 2014-17-02	APPLIANCE AD - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING DISCREPANCIES - HONEYWELL ASCA INC	KAQW		MANDATORY	MTH 02-Oct-2014 HRS 1003.6 LDG 820	-				N/A
	MOC : NOT APPLICABLE - BY ELT MANUFACTURER AND MODEL NUMBER. (ONE TIME)									
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2	GSO		MANDATORY	MTH 16-Jun-2024 HRS 2928.5 LDG 2890	-				N/A
	MOC : NOT APPLICABLE - FAA 2015-10-02 PARA (G) GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2 DOES NOT APPLY. EQUIPMENT NOT INSTALLED.									
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK	GSO		MANDATORY	MTH 16-Jun-2024 HRS 2928.5 LDG 2890	-				N/A
	MOC : NOT APPLICABLE - FAA 2015-10-02 PARA (H) CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK DOES NOT APPLY. EQUIPMENT NOT INSTALLED.									
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS	GSO		MANDATORY	MTH 16-Jun-2024 HRS 2928.5 LDG 2890	-				N/A
	MOC : NOT APPLICABLE - FAA 2015-10-02 PARA (I) REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS DOES NOT APPLY. EQUIPMENT NOT INSTALLED.									
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT	GSO		MANDATORY	MTH 16-Jun-2024 HRS 2928.5 LDG 2890	-				N/A
	MOC : NOT APPLICABLE - FAA 2015-10-02 APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT DOES NOT APPLY. EQUIPMENT NOT INSTALLED.									
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	KAQW			MTH 11-Dec-2017 HRS 1753 LDG 1399	-				N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE, AMERI-KING ELT NOT INSTALLED.									
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	KAQW		MANDATORY	MTH 11-Dec-2017 HRS 1753 LDG 1399	-				N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE, AMERI-KING ELT NOT INSTALLED.									
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	KAQW		MANDATORY	MTH 11-Dec-2017 HRS 1753 LDG 1399	-				N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE, AMERI-KING ELT NOT INSTALLED.									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	GSO		MANDATORY	MTH HRS LDG	16-Jun-2024 2928.5 2890		-			N/A
	MOC : NOT APPLICABLE - FAA 2021-07-13 PARA (E)(1) INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE DOES NOT APPLY. EQUIPMENT NOT INSTALLED.										
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICHNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	GSO		MANDATORY	MTH HRS LDG	16-Jun-2024 2928.5 2890		-			N/A
	MOC : NOT APPLICABLE - FAA 2021-07-13 PARA (E)(2) MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE DOES NOT APPLY. EQUIPMENT NOT INSTALLED.										
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER	GSO		MANDATORY	MTH HRS LDG	16-Jun-2024 2928.5 2890		-			N/A
	MOC : NOT APPLICABLE - FAA 2021-07-13 PARA (E)(3) DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER DOES NOT APPLY. EQUIPMENT NOT INSTALLED.										
FAA 2021-07-13	EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	GSO		MANDATORY	MTH HRS LDG	16-Jun-2024 2928.5 2890		-			N/A
	MOC : NOT APPLICABLE - FAA 2021-07-13 APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT DOES NOT APPLY. EQUIPMENT NOT INSTALLED.										
FAA 2024-26-02 PARA (G)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH			-			
	MOC :										
FAA 2024-26-02 PARA (G)(2)	MEASURE THE THICHNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE			MANDATORY	MTH			-			
	MOC :										
FAA 2024-26-02 PARA (G)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER			MANDATORY				-			
	MOC :										
FAA 2024-26-02	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT			MANDATORY				-			
	MOC :										
FAA 2010-04-16 PARA (G)	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERSMANUFACTURED BY SICLI WITH SERVICABLE UNIT	HUR		MANDATORY	DAYS HRS LDG	14-Mar-2010 347 221		A/R			N/A
	MOC : NOT APPLICABLE - N/A BY EQUIP										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
FAA 2010-04-16 PARA (H)	RETURN TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERSMANUFACTURED BY SICLI THE AFFECTED FIRE EXTINGUISHER TO MANUFACTURER	HUR	MANDATORY		DAYS 14-Mar-2010 HRS 347 LDG 221		A/R			N/A
	MOC : NOT APPLICABLE - N/A BY EQUIP									
FAA 2010-04-16	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERSMANUFACTURED BY SICLI	HUR	MANDATORY		MTH 14-Mar-2010 HRS 347 LDG 221		A/R			N/A
	MOC : NOT APPLICABLE - N/A BY EQUIP									
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS	KGMU	MANDATORY		MTH 03-Jan-2022 HRS 2506.2 LDG 2131		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH AD 2021-23-12 BY INSERTING FIGURE 1 TO PARAGRAPH (G) INTO THE LIMITATIONS SECTION OF THE EXISTING AIRPLANE FLIGHT MANUAL. THE EFFECTIVE DATE OF THIS AD IS 12/09/2021.WORK WAS ALSO PERFORMED BY RANDY KNOWLTON.									
FAA 2018-07-13	LANDING GEAR - INSPECTION OF THE BRAKE PAD WEAR INDICATOR PINS AND REPLACEMENT OF THE BRAKE ASSEMBLY IF ANY PIN IS FOUND TO HAVE AN INCORRECT LENGTH	KDXR	MANDATORY		DAYS 24-Apr-2018 HRS 1826.2 LDG 1452		-			Complete
	MOC : COMPLIED WITH - AD 2018-07-13 COMPLIED WITH BY INSPECTION PER AD AND UTC SB 2-1706-07-13, REV. 1. PIN MEASUREMENTS BELOW .165". PAINTED PINT ENDS YELLOW.									
FAA 2010-07-02	PERFORM A ONE-TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR THE HONEYWELL PRIMUS II NV-850 NAVIGATION RECEIVER MODULE (NRM)	HUR	MANDATORY		MTH 14-Mar-2010 HRS 347.5 LDG 221		A/R			N/A
	MOC : NOT APPLICABLE - N/A BY EQUIPMENT.									
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	KAQW	MANDATORY		MTH 02-Oct-2014 HRS 1003.6 LDG 820		-			N/A
	MOC : NOT APPLICABLE - BY MANUFACTURER AND PART NUMBERS OF #1 AND #2 TRANSPONDERS. (ONE TIME)									
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	GSO	MANDATORY		MTH 16-Jun-2024 HRS 2928.5 LDG 2890		-			N/A
	MOC : NOT APPLICABLE - FAA 2015-10-51-E APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFMOR AFMS DOES NOT APPLY. EQUIPMENT NOT INSTALLED.									
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	GSO	MANDATORY		MTH 16-Jun-2024 HRS 2928.5 LDG 2890		-			N/A
	MOC : NOT APPLICABLE - FAA 2015-10-51 APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFMOR AFMS DOES NOT APPLY. EQUIPMENT NOT INSTALLED.									

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
FAA 2018-03-04 PARA (G)	DETERMINE NUMBER OF AFFECTED PITOT PROBES INSTALLED	KAQW		MANDATORY	DAYS 07-Aug-2018 HRS 1887.4 LDG 1493		-			N/A
	MOC : NOT APPLICABLE - AD 2018-03-04 ROSEMOUNT PITOT TUBES- NOT APPLICABLE BY PITOT TUBE MODEL NUMBERS, L&R.									
FAA 2018-03-04 PARA (H)(1)	REPLACE AFFECTED PITOT PROBES	KAQW		MANDATORY	MTH 07-Aug-2018 HRS 1887.4 LDG 1493		-			N/A
	MOC : NOT APPLICABLE - AD 2018-03-04 ROSEMOUNT PITOT TUBES- NOT APPLICABLE BY PITOT TUBE MODEL NUMBERS, L&R.									
FAA 2018-03-04 PARA (H)(2)	DO NOT INSTALL ON ANY AIRPLANE A PITOT PROBE HAVING A SERIAL NUMBER LISTED IN PARA (C)(1) OF THIS AD, UNLESS IT HAS BEEN PROPERLY REPAIRED, AND IF REPAIRED BY CSI AEROSPACE, INC., HAS A REPAIR DATE OF AUGUST 1, 2014, OR LATER	KAQW		MANDATORY	MTH 07-Aug-2018 HRS 1887.4 LDG 1493		-			N/A
	MOC : NOT APPLICABLE - AD 2018-03-04 ROSEMOUNT PITOT TUBES- NOT APPLICABLE BY PITOT TUBE MODEL NUMBERS, L&R.									
FAA 2018-03-04	APPLIANCE AD - NAVIGATION - REPLACEMENT OF ROSEMOUNT AEROSPACE INC. MODEL 851AK PITOT PROBES REPAIRED BY CSI AEROSPACE INC	KAQW		MANDATORY	MTH 07-Aug-2018 HRS 1887.4 LDG 1493		-			N/A
	MOC : NOT APPLICABLE - AD 2018-03-04 ROSEMOUNT PITOT TUBES- NOT APPLICABLE BY PITOT TUBE MODEL NUMBERS, L&R.									
FAA 2009-21-10 R01	APPLIANCE AD - INSPECT TO DETERMINE THE SERIAL NUMBER OF THE OXYGEN CYLINDER ASSEMBLIES INSTALLED IN THE AIRPLANE	HUR		MANDATORY	DAYS 11-Feb-2010 HRS 336 LDG 217		A/R			N/A
	MOC : NOT APPLICABLE - FAA AD 2009-21-10 R0/R1 AVOX SYSTEMS OXYGEN BOTTLE - N/A BY EQUIP									
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	KAQW		MANDATORY	MTH 04-Dec-2015 HRS 1252.8 LDG 1016		-			Complete
	MOC : COMPLIED WITH - PILOT'S MASK NOT APPLICABLE BY SERIAL NUMBER. COPILOTS MASK PREVIOUSLY COMPLIED WITH AT OVERHAUL, MASK S/N SE27934									
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPRGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES	KAQW		MANDATORY	MTH 04-Dec-2015 HRS 1252.8 LDG 1016		-			Complete
	MOC : COMPLIED WITH - PILOT'S MASK NOT APPLICABLE BY SERIAL NUMBER. COPILOTS MASK PREVIOUSLY COMPLIED WITH AT OVERHAUL, MASK S/N SE27934									
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES	KAQW		MANDATORY	MTH 04-Dec-2015 HRS 1252.8 LDG 1016		-			Complete
	MOC : COMPLIED WITH - PILOT'S MASK NOT APPLICABLE BY SERIAL NUMBER. COPILOTS MASK PREVIOUSLY COMPLIED WITH AT OVERHAUL, MASK S/N SE27934									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	KAQW		MANDATORY	MTH DAYS 04-Dec-2015 HRS 1252.8 LDG 1016		-			N/A
	MOC : NOT APPLICABLE - BY PART NUMBERS AND SERIAL NUMBERS, PILOT AND COPILOT MASKS									
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	KAQW		MANDATORY	MTH DAYS 04-Dec-2015 HRS 1252.8 LDG 1016		-			N/A
	MOC : NOT APPLICABLE - BY PART NUMBERS AND SERIAL NUMBERS, PILOT AND COPILOT MASKS									
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	KAQW		MANDATORY	MTH DAYS 04-Dec-2015 HRS 1252.8 LDG 1016		-			N/A
	MOC : NOT APPLICABLE - BY PART NUMBERS AND SERIAL NUMBERS, PILOT AND COPILOT MASKS									
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	KAQW		MANDATORY	MTH DAYS 04-Dec-2015 HRS 1252.8 LDG 1016		-			N/A
	MOC : NOT APPLICABLE - BY PART NUMBERS AND SERIAL NUMBERS, PILOT AND COPILOT MASKS									
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	KAQW		MANDATORY	MTH 04-Dec-2015 HRS 1252.8 LDG 1016		-			N/A
	MOC : NOT APPLICABLE - BY PART NUMBERS AND SERIAL NUMBERS, PILOT AND COPILOT MASKS									
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	KAQW		MANDATORY	MTH 04-Dec-2015 HRS 1252.8 LDG 1016		-			N/A
	MOC : NOT APPLICABLE - BY PART NUMBERS AND SERIAL NUMBERS, PILOT AND COPILOT MASKS									
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	KAQW		MANDATORY	MTH 14-Jul-2016 HRS 1421.4 LDG 1170		-			N/A
	MOC : NOT APPLICABLE - PROTECTIVE BREATHING EQUIPMENT NOT INSTALLED									
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	KAQW		MANDATORY	MTH 14-Jul-2016 HRS 1421.4 LDG 1170		-			N/A
	MOC : NOT APPLICABLE - PROTECTIVE BREATHING EQUIPMENT NOT INSTALLED									
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	KAQW		MANDATORY	MTH 14-Jul-2016 HRS 1421.4 LDG 1170		-			N/A
	MOC : NOT APPLICABLE - PROTECTIVE BREATHING EQUIPMENT NOT INSTALLED									

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12	KAQW	MANDATORY	MTH 14-Jul-2016 HRS 1421.4 LDG 1170		-				N/A
	MOC : NOT APPLICABLE - PROTECTIVE BREATHING EQUIPMENT NOT INSTALLED									
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KAQW	MANDATORY	MTH 18-Sep-2017 HRS 1694.7 LDG 1370		-				N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE, B/E AEROSPACE PBE NOT INSTALLED.									
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KAQW	MANDATORY	MTH 18-Sep-2017 HRS 1694.7 LDG 1370		-				N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE, B/E AEROSPACE PBE NOT INSTALLED.									
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	KAQW	MANDATORY	MTH 18-Sep-2017 HRS 1694.7 LDG 1370		-				N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE, B/E AEROSPACE PBE NOT INSTALLED.									
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES	KAQW	MANDATORY	MTH 18-Sep-2017 HRS 1694.7 LDG 1370		-				N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE, B/E AEROSPACE PBE NOT INSTALLED.									
FAA 2025-25-02	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - OPERATIONAL INSTRUCTIONS		MANDATORY	DAYS		-				
	MOC :									
FAA 2025-26-06	APPLIANCE AD - INCORRECT USAGE OF PORTABLE BREATHING EQUIPMENT	KGJT	MANDATORY	DAYS 16-Jun-2026 HRS 3110.9 LDG 2986		-				N/A
	MOC : NOT APPLICABLE - AD 2025-26-06 - AEROSPACE & DEFENSE OXYGEN SYSTEMS SAS (PART OF SAFRAN AEROSYSTEMS) (FORMERLY KNOWN AS AIR LIQUIDE), EFFECTIVE DATE JANUARY 14, 2026 IS NOT APPLICABLE TO THIS AIRCRAFT, EQUIPMENT IS NOT INSTALLED.									
FAA 2026-03-09 PARA (G) EASA (1)	REPLACE THE AFFECTED PBE WITH A PBE NOT AFFECTED BY THIS AD	KGJT	MANDATORY	DAYS 16-Jun-2026 HRS 3110.9 LDG 2986		-				N/A
	MOC : NOT APPLICABLE - AD 2026-03-09 - AEROSPACE & DEFENSE OXYGEN SYSTEMS SAS (PART OF SAFRAN AEROSYSTEMS) (FORMERLY KNOWN AS AIR LIQUIDE), EFFECTIVE DATE MARCH 12, 2026 IS NOT APPLICABLE TO THIS AIRCRAFT, EQUIPMENT IS NOT INSTALLED.									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **N1968, LLC**
Aircraft Model: **510 - CITATION MUSTANG**
Aircraft Serial: **510-0021**
Unit: **0021** Reg No: **N968W**
Airworthiness: **16-Aug-2007**
Print Date: **10-Nov-2026 12:46PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 1	**3155.8**	**3014**	**30-Oct-2026**	**.23**
ENG 2	**2457.5**	**2634**	**30-Oct-2026**	**.23**
AIR COND	**178.2**		**30-Oct-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	(ENG) DUE 1 / (ENG) DUE 2	Remains / Remains
FAA 2026-03-09 PARA (G) EASA (2)	ACCOMPLISHMENT OF THE ACTION AS REQUIRED BY PARA (1) OF THIS AD CAN BE DEFERRED IN ACCORDANCE WITH THE APPLICABLE INSTRUCTIONS AND LIMITATIONS OF THE APPLICABLE AIRCRAFT MMEL ITEMS, PROVIDED THAT THOSE MMEL ITEMS ARE INCLUDED IN THE OPERATOR APPROVED MEL, AND THAT THE MINIMUM REQUIRED INSTALLED PBES ARE CONFIRMED NOT AFFECTED BY THIS AD	KGJT		MANDATORY	MTH 16-Jun-2026 HRS 3110.9 LDG 2986	-				N/A
	MOC : NOT APPLICABLE - AD 2026-03-09 - AEROSPACE & DEFENSE OXYGEN SYSTEMS SAS (PART OF SAFRAN AEROSYSTEMS) (FORMERLY KNOWN AS AIR LIQUIDE), EFFECTIVE DATE MARCH 12, 2026 IS NOT APPLICABLE TO THIS AIRCRAFT, EQUIPMENT IS NOT INSTALLED.									
FAA 2026-03-09 PARA (G) EASA (3)	PART INSTALLATION: STARTING FROM THE APPLICABILITY DATE AS IDENTIFIED IN TABLE 1 OF THIS AD, AS APPLICABLE, DEPENDING ON PBE LOCATION, DO NOT INSTALL AN AFFECTED PBE ON ANY AIRCRAFT	KGJT		MANDATORY	DAYS 16-Jun-2026 HRS 3110.9 LDG 2986	-				N/A
	MOC : NOT APPLICABLE - AD 2026-03-09 - AEROSPACE & DEFENSE OXYGEN SYSTEMS SAS (PART OF SAFRAN AEROSYSTEMS) (FORMERLY KNOWN AS AIR LIQUIDE), EFFECTIVE DATE MARCH 12, 2026 IS NOT APPLICABLE TO THIS AIRCRAFT, EQUIPMENT IS NOT INSTALLED.									
FAA 2026-03-09 PARA (G) EASA (4)	LIFE LIMIT: REMOVE FROM SERVICE	KGJT		MANDATORY	MTH 16-Jun-2026 HRS 3110.9 LDG 2986	-				N/A
	MOC : NOT APPLICABLE - AD 2026-03-09 - AEROSPACE & DEFENSE OXYGEN SYSTEMS SAS (PART OF SAFRAN AEROSYSTEMS) (FORMERLY KNOWN AS AIR LIQUIDE), EFFECTIVE DATE MARCH 12, 2026 IS NOT APPLICABLE TO THIS AIRCRAFT, EQUIPMENT IS NOT INSTALLED.									
FAA 2026-03-09	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - REMOVAL FROM SERVICE	KGJT		MANDATORY	MTH 16-Jun-2026 HRS 3110.9 LDG 2986	-				N/A
	MOC : NOT APPLICABLE - AD 2026-03-09 - AEROSPACE & DEFENSE OXYGEN SYSTEMS SAS (PART OF SAFRAN AEROSYSTEMS) (FORMERLY KNOWN AS AIR LIQUIDE), EFFECTIVE DATE MARCH 12, 2026 IS NOT APPLICABLE TO THIS AIRCRAFT, EQUIPMENT IS NOT INSTALLED.									
TCCA CF-2010-03 E1	FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE WEAR	HUR		MANDATORY	MTH 13-Feb-2010 HRS 336 LDG 217	-				Complete
	MOC : COMPLIED WITH - CF AD2010-03 CARRIED OUT BY COMPLETION OF PW ASB 63071.									
FAA 2010-17-06 E1	REPLACEMENT OF FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE	LIML		MANDATORY	MTH 01-Oct-2010 HRS 387 LDG 243	-				Complete
	MOC : COMPLIED WITH - PREVIOUSLY PCW AS SB A63071R1 (FOUND INSTALLED PN: 10940GA SN LH WA24698)									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.