1.18.0
Improvements:
- WiFi Functionality Updates
- Enable new humidity sensor
- Sensor only integration with Hub units
- Clear output blocking if in an alarm state

Fixes:
- Shade with light adjustments
- Updates over the radio
- Header adjustments for readability

1.17.0
Fixes:
- WeatherBoss negative ˚C temperatures
- Manual set point override in zone 2

1.16.0
Improvements:
- Hub:
  - Increase max number of clients to 52
- ClimateBoss GHK or RWL:
  - Introduce advanced shade settings)
    - Shade Back Off (retract shade when vent open)
    - Stage B Energy (allow Stage A to act in shade mode, Stage B in energy mode)

1.14.0
Improvements:
- Hub:
  - Faster client list retrieval and ordered by serial number.
- ClimateBoss GHK or RWL:
  - Added a humidify option in dehumidification menu
    - Humidify mode controls timer 2 based on the user selected set point
  - Support for variable frequency drive integration

Fixes:
- Fix issue where Weather Boss wind status did not show correctly.

1.13.0
Improvements:
- ClimateBoss GHK or RWL:
  - Heat 3 Option for RWL
  - Optional override to fully closed on weather override (not default or recommended)

Fixes:
- Shade temp set point for ˚C

1.12.0
Improvements:
- ClimateBoss GHK or RWL:
  - Allow user to use temperature set point when Timer 1 in shade mode
  - Allow alarm temperature down to 0˚F

- WeatherBoss:
  - Client limit to 32

Fixes:
- Limit check accounts for hysteresis

1.11.0
- ClimateBoss GHK or RWL:
  - Mister on time limit now 255 seconds.

Fixes:
- Improved advanced WiFi menu details
- Detect enterprise networks (not supported)
- Negative ˚C temperature conversions
- Headgrower change of On to Auto recognition

1.10.0
Improvements:
- ClimateBoss GHK or RWL:
  - Add calibration menu for offsets and humidity calibration
- Hub:
  - Add Over The Air updates to download new firmware at Hub and send to Clients via radio

1.9.0
Improvements:
- All Controllers:
  - Add more diagnostics on WiFi status screen
  - Software Reset Option

Fixes:
- Show only zone 1 alarm when in 1 zone mode
- Manual timer cycle overrides light setting

1.7.0, 1.8.0
- Development release

1.6.0
Improvements:
- Hub Controller
  - Increase max clients from 10 to 12

Fixes:
- Timing dehumidification adjustments
- Zone 2 set point on number of zone changes