GLLS COMPLEXITY, SIMPLIFIED.

STANDARDS

Laser marks are on the side facing to LEDs which are rolled outward in the blister plate.

02

01

Laser marks are outwards

02End

NOTICE

UNPACKING - FLAT PACK

| Step 1 | Step 2 | Step 3 | Step 4 | Step 5 | Step 6 | Step 7 | Step 8 |

PULL

UNPACKING - REEL

GLLS.COM | 1.888.580.6366
GLLS reserves the right to make any design changes for continuous improvement which will not affect the overall appearance or performance. REV 20250730

1