



SIKORSKY S-92A

FOR SALE OR LEASE

SERIAL NUMBER
920206

MANUFACTURED
2013

LOCATION
USA

PRICE
Make an offer

TOTAL TIME
10,253 Hrs

AVAILABLE
Immediately

EQUIPMENT

- | | | |
|----------------------------------|--|---------------------|
| • Two (2) Life rafts | • Pop out windows | • HISL |
| • HEELS | • Precise Flight pulse lights | • Windshield wipers |
| • High intensity strobe | • Anti-collision lights | |
| • Emergency floats - Sea State 4 | • Crew headset holders | |
| • Air conditioning | • Hoist access door with locking latch | |
| • Baggage bay liner | • First aid kit | |
| • Pressure refuelling | • Baggage bay Kydex protectors | |

HIGHLIGHTS

- Offshore configuration
- GE PBH programs

INTERIOR

- Offshore configuration
- Nineteen (19) passenger seats
- Cabin carpet

AVIONICS

• AFCS	<i>Rig approach</i>
• VHF FM Transceiver	<i>Technisonic TFM 550</i>
• UHF transceiver	<i>SART</i>
• MPFR	<i>Dual power with ULB and RIPS</i>
• ADEL T	
• SSQAR	
• Satellite tracking	<i>Skyconnect</i>
• Dual air data computer	
• AHRS	
• Weather radar	<i>Honeywell Primus 660</i>
• EGPWS	<i>Honeywell MK XXII</i>
• Dual transponder	<i>TDR-94D, ADS-B out</i>
• Dual VHF NAV	<i>Collins VIR 432</i>
• ADF	
• Flight management system	<i>Universal UNS 1ESPW</i>
• Passenger briefing system	<i>PBS 250</i>
• TCAS I	
• HUMS	
• FDM/HOMP	<i>PBS 253</i>
• Dual GPS	<i>with Flight plan management system</i>
• HF Transceiver	<i>HF 1050</i>



MAJOR COMPONENTS	LIMIT	REMAINING	%
Main rotor blade	22,000	18,340.0	83.4%
Main rotor blade	22,000	14,935.0	67.9%
Main rotor blade	22,000	10,761.2	48.9%
Main rotor blade	22,000	13,632.3	62.0%
Hub assembly	15,000	8,173.7	54.5%
Main gearbox	10,500	6,806.8	64.8%
Main rotor shaft	10,500	6,154.3	58.6%
IGB centre housing	12,200	12,152.0	99.6%
TGB output housing	17,000	7,343.8	43.2%
Tail rotor blade, flex beam	10,000	8,831.9	88.3%
Tail rotor blade, flex beam	10,000	5,019.0	50.2%
Tail rotor blade, flex beam	10,000	7,787.5	77.9%
Tail rotor blade, flex beam	10,000	8,946.8	89.5%
Main rotor servo	17,000	9,136.6	53.7%
Main rotor servo	17,000	9,217.2	54.2%
Main rotor servo	17,000	12,159.9	71.5%
Stationary swashplate assembly	14,000	9,351.2	66.8%
APU rotor assembly	10,000	7,963.0	79.6%
CT87-8A - inspection	1,500	1,500.0	100.0%
CT87-8A - inspection	1,500	1,452.0	96.8%

* Aircraft details provided are based on the information provided and subject to verification during the purchase process


CONTACT
**P. +1 604 669 6406
C. +1 778 989 8306**
E. brad@intaviation.ca
www.intaviation.com