

Due Diligence					
Report Date	17/09/2026	Inspected By	RONAR	Supervisor	RONAR
Y.O.M	2019	Make & Model	TOYOTA HARRIER	Model Code	
Reg. No. (if appl.)		VIN Number	ZSUG0-017521	Engine No.	
Mileage (Km)	64,488km	Mileage Verified		Use Country	JAPAN
Logbook Ver. (If appl.)		Previous Owners		Priv. / comm	PRIVATE
Spare Tyre, Jack, Tools	✓✓✓	Original Handbook		Spare Key	TBC
Service History Ver.		Last Service (Km)		Next Service (Km)	64,488km

Body/Exterior Inspection	
	D = Dent S = Scratch M = Missing Trim RP = Repainted SR = Surface Rust R = Moderate Rust CR = Corrosion C = Crack / Chip
	General Comments: MINOR SCRATCHES
	Structural & Underbody Comments: NO RUST / CORROSION
	Exterior Grade (%) 80%
	Structural & Underbody Grade (%) 85%

Interior Inspection			
Upholstery	✓	Dash & Plastics	✓
Seats Fuct. (inc belts)	✓	Floor Mats	✓
Comments: MINOR SCRATCHES ON DASH & PLASTICS		Smoked In	NO
		Interior Grade (%)	85%

Mechanical Inspection			
Exterior Lights	✓	Wipers	✓
Elec. Interior Equip.	✓	Infotainment	✓
Eng. Ancillary Cpts.	✓	Eng. Blowby	NO
Cooling System Test	✓	Heat Exchangers	✓
Fuses & relays	✓	Fluids	
Shocks & Springs	✓	Sus. Bushings	COMMENT
Ball Joints / Tie Rods	✓	Column & Rack	✓
Rubber Mountings	✓	Brake Pads (F/R)	50% / 50%
Comments:		Tyre Tread Depth	✓ 80% MISMATCHED
		HVAC System	✓
		Eng. Oil Leaks	NO
		Other leaks	NO
		Exhaust System	✓
		Boots & Shafts	✓
		Hubs & W. Brgs	✓
		Brake Discs (F/R)	70% / 70%
		Modifications	Y / (N)
		Mech Grade (%)	85%

Road Test Report			
Engine Start Up	✓	Braking	✓
Engine Perf. & Acc.	✓	Gear Shifting	✓
4WD / L. Range	X / X	Diff Locks(s)	X
Comments:		NVH	NO
		Warning Lights	NO
		Steering Feedback	✓

Recommended Repairs and/or Final Comments	
NEW BATTERY FRONT AND REAR TIRES DIFFERENT BRAND FRONT LOWER ARM BUSHES SLIGHTLY WORN	

WA Final Assessment / %				WA Warranty
Practically As-new/	Excellent /	Good / 80%	Fair /	Needs Work /
				TBC