DDR4 Reuse: Sourcing Through Validated CXL Delivery

1

Configuration review

Confirm DDR4 suitability, host CXL capability and workload requirements before harvesting.


Customer-supplied DDR4

Customer harvests owned DIMMs.

2

Receive and inspect

Ship DIMMs from either source to Penguin for inspection and inventory.



3

Zefr™ Qualification

DIMMs undergo a proprietary Zefr screening process before proceeding to system validation.



4

Install and validate

Install passing DIMMs in the AIC. Validate it in a CXL host system.



5

Deliver the complete AIC

Ship the fully validated CXL assembly to the customer.



PENGUIN SOLUTIONS

© 2026 Penguin Solutions, Inc. All rights reserved. |