Company

Owner: Eclair Aviation s.r.o.
Operator: Eclair Aviation s.r.o.

Major Assemblies

Airframe	G280	**2253**	28-Aug-2024	1058 Hrs	618 Ldg
Eng 1	AS907-2-1G	**P130647**	28-Aug-2024	1033:36 Hrs	613 Enc
Eng 2	AS907-2-1G	**P130648**	28-Aug-2024	1053:36 Hrs	625 Enc
APU 1	GTCP36-150 [IAI]	**P-362**	02-Sep-2024	629 Hrs	850 APUS

Additional Information

Program Type: Standard, General Categories: RVSM,EMM,EASA

Cost: 3,125+
Man Hrs: 4,487+

Analyst: Laurence Kirk lkirk@jetsupport.com

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 1. RE -										Man Hours: 3,498+	
G25-02039	**G25-02039 , Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-02213	**Brakes Accumulator And Landing Gear Pressure Vessel Nitrogen Charging Instructions - Correct Factors Used For Ambient Temperature Corrections, Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-02247	**Rudder Closeout Ribs Installation - Rivet Instead Of Bond, To Prevent Need For Rework, Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-02285	**G25-02285, Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-02317	**G25-02317, H/S - V/S Pivot Freeplay Assurance - Change MODIFICATION**							RE (-)			
0 A/F						Mos	22-Nov-2022				
Complied With						Hrs					
						Ldg					
G25-10074	**G25-10074 , Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10078	**G25-10078 , Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20145	**G25-20145 , Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20166	**Mfsa Piston Seal And Rod End Bearing Redesign, Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G25-20173	**Cvr Crew Ares Microphone (Cam) Replacement, Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20178	**Fft- Relocation Of Stiffener On Forward Fuel Tank, Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20180	**G25-20180 , Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20181	**G25-20181 , Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20184	**Gps-400S Software Update (Tso) , Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20185	**New Ecs Insulation Blankets From Jahier, Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20187	**G25-20187 , Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20189	**G25-20189 , Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20191	**Potable Water Contrlol Unit Sw Change For Improved Quantity Indication Accuracy, Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20193	**Heating Control Module Software Changes, Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20196	**New Thermal Anti Ice Valve With Improved Reliability, Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20201	**G25-20201 , Modification**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
IL ISR-I-04-2020-06-02 R01	**Revision Of Table 9 - Temporary Limitations And Inspection Requirements Of The Section 05-10-10 (Airworthiness Limitations Section) Of The G280 Airplane Maintenance Manual- Addition Of Awl-3 Task (Mandatory)**							RE (-)			
4 A/F						Mos	09-Nov-2022				
Complied With	AWL-3 TASK ADDED TO TABLE 9 OF ALS 05-10-10					Hrs					
						Ldg					
070004	**Aircraft Jacking Procedure**							RE (-)			
7 A/F						Mos					
						Hrs					
Ref#:07-10-00-MP						Ldg					
280-11-028	**Placards And Markings - Exterior Placards And Markings - Relocation Of "After Maintenance / Test Verify That Pitot / Static Drains Are Positively Closed" Placard (MODG25-0029)**							RE (-)		Recommended	
11 A/F						Mos	10-Feb-2023				
Eff: 23-Aug-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-11-035	**Placards And Markings - Replacement Of Existing Bottle Preload Pressure, Reservoir Fill And Hydraulic Reservoir LHS / RHS Placards With New Placards (MODG25-00241)**							RE (-)		Recommended	
11 A/F						Mos	10-Feb-2023				
Eff: 23-Aug-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-11-088	**Placards And Markings - Replacement Of Existing Life Line , Raft Line Attach Point Placards With New Placards (MODG25-00443)**							RE (-)		Recommended	
11 A/F						Mos	10-Feb-2023				
Eff: 28-Feb-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-11-160	**Placards And Markings - Interior Placards And Markings - Removal Of Placards Prohibiting Wing Anti-Ice Auto Mode Operation (MODG25-20073)**							RE (-)		Recommended	
11 A/F						Mos	10-Feb-2023				
Eff: 19-Jan-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-11-252	**Placards and Markings - Baggage Compartment Access Above 40,000 Feet (12,192 M)**							RE (-)		Optional	
11 A/F						Mos					
Eff: 12-Aug-2020						Hrs					
(AVG MAN HRS: 2)						Ldg					
121301	**Refueling**							RE (-)			
12 A/F						Mos					
						Hrs					
Mfg#:12-13-00-SE						Ldg					
121302	**Gravity Refueling**							RE (-)			
12 A/F						Mos					
						Hrs					
Mfg#:12-13-00-SE						Ldg					
121303	**Defueling**							RE (-)			
12 A/F						Mos	17-Jan-2023				
						Hrs	22:54				
Mfg#:12-13-00-SE						Ldg	6				
121304	**Fuel System Draining**							RE (-)			
12 A/F						Mos	17-Jan-2023				
						Hrs	22:54				
Mfg#:12-13-00-SE						Ldg	6				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
121401		**Engine - Servicing**							RE (-)			
	12 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:12-14-00						Ldg	10				
121405		**Auxiliary Power Unit - Servicing**							RE (-)			
	12 A/F						Mos					
							Hrs					
	Mfg#:12-14-00						Ldg					
121407		**Engine Air Turbine Starter Oil (Left) - Servicing**							RE (-)			
	12 A/F						Mos	20-Oct-2023				
							Hrs	490:27				
	Mfg#:12-14-00						Ldg	293				
121408		**Engine Air Turbine Starter Oil (Right) - Servicing**							RE (-)			
	12 A/F						Mos	20-Oct-2023				
							Hrs	490:27				
	Mfg#:12-14-00						Ldg	293				
121501		**Hydraulic System Reservoir (Left) - Servicing**							RE (-)			
	12 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:12-15-00						Ldg	10				
121502		**Hydraulic System Reservoir (Right) - Servicing**							RE (-)			
	12 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:12-15-00						Ldg	10				
121601		**Brake Accumulator - Servicing**							RE (-)			
	12 A/F						Mos					
							Hrs					
	Mfg#:12-16-00-SE						Ldg					
121901		**Oxygen Cylinder - Servicing**							RE (-)			
	12 A/F						Mos					
							Hrs					
	ATA Ref::12-19-00, Mfg#:12-19-00-SE						Ldg					
122001		**Safe Ground Maintenance Procedure**							RE (-)			
	12 A/F						Mos	19-Jan-2023				
							Hrs	22:54				
	Mfg#:20-00-00-MP						Ldg	6				
122202		**Nose Tire Assembly - Servicing**							RE (-)			
	12 A/F						Mos					
							Hrs					
	Mfg#:12-22-00-SE						Ldg					
122207		**Main Landing Gear Tire Assembly - Servicing**							RE (-)			
	12 A/F						Mos					
							Hrs					
	Mfg#:12-22-00-SE						Ldg					
122208		**Landing Gear - Cleaning**							RE (-)			
	12 A/F						Mos					
							Hrs					
	Mfg#:12-22-00-SE						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
122801		**Potable Water System - Filling**							RE (-)			
	12 A/F						Mos					
							Hrs					
	ATA Ref::12-28-00, Mfg#:12-28-00						Ldg					
122802		**Potable Water System - Draining**							RE (-)			
	12 A/F						Mos					
							Hrs					
	ATA Ref::12-28-00, Mfg#:12-28-00						Ldg					
122805		**Waste Water System - Servicing**							RE (-)			
	12 A/F						Mos					
							Hrs					
	ATA Ref::12-28-00, Mfg#:12-28-00						Ldg					
212103		**Pack Inlet Valve - Operational Test**							RE (-)			
	21 A/F						Mos					
							Hrs					
	Mfg#:21-21-01						Ldg					
212113		**Defog Valve - Operational Test**							RE (-)			
	21 A/F						Mos					
							Hrs					
	Mfg#:21-21-03						Ldg					
212117		**Foot Warmer Valve - Operational Test**							RE (-)			
	21 A/F						Mos					
							Hrs					
	Mfg#:21-21-04						Ldg					
213001		**Cabin Pressure Control System - Operational Test**							RE (-)			
	21 A/F						Mos					
							Hrs					
	Mfg#:21-30-00-AT						Ldg					
213002		**Cabin and Baggage Compartment (Using Engines or APU) - Leakage Test**							RE (-)			
	21 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:21-30-00-AT						Ldg	10				
213003		**Cabin and Baggage Compartment (Using External Pressure) - Leakage Test**							RE (-)			
	21 A/F						Mos					
							Hrs					
	Mfg#:21-30-00-AT						Ldg					
213100		**Manual Pressurization Control System (DUMP / DITCH Function) - Operational Check**							RE (-)			
	21 A/F						Mos					
							Hrs					
							Ldg					
213102		**Automatic Pressure Control System - Operational Test**							RE (-)			
	21 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:21-31-00-AT						Ldg	10				
213108		**Verify Mode - Operational Test**							RE (-)			
	21 A/F						Mos					
							Hrs					
	Mfg#:21-31-00-AT						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
213109		**Delta-P Display - Operational Test**							RE (-)			
21 A/F							Mos					
							Hrs					
	Mfg#:21-31-00-AT						Ldg					
213117		**Outflow Valve - Operational Test**							RE (-)			
21 A/F							Mos					
							Hrs					
	Mfg#:21-31-03-AT						Ldg					
213205		**Alternate Pressure Regulating Shutoff Valve - Functional Test**							RE (-)			
21 A/F							Mos					
							Hrs					
	Mfg#:21-32-01						Ldg					
215201		**Nose Deck Cooling - Functional Test**							RE (-)			
21 A/F							Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:21-52-00						Ldg	10				
215202		**Cockpit Cooling - Functional Test**							RE (-)			
21 A/F							Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:21-52-00						Ldg	10				
215301		**Radio Rack Cooling - Functional Test**							RE (-)			
21 A/F							Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:21-53-00						Ldg	10				
216101		**Temperature Control System - Functional Test**							RE (-)			
21 A/F							Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:21-60-00						Ldg	10				
216115		**Cockpit and Cabin Temperature Sensor Fan - Operational Test**							RE (-)			
21 A/F							Mos					
							Hrs					
	Mfg#:21-61-03						Ldg					
221001		**Autopilot and Flight Director - Functional Test**							RE (-)			
22 A/F							Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:22-10-00						Ldg	10				
221103		**Flight Control Panel - Operational Test**							RE (-)			
22 A/F							Mos					
							Hrs					
	Ref#:22-11-00						Ldg					
221201		**Autopilot Servo - Operational Test**							RE (-)			
22 A/F							Mos					
							Hrs					
	Mfg#:22-12-00						Ldg					
221202		**Slip Clutch Breakaway Torque (Aileron) - Adjustment**							RE (-)			
22 A/F							Mos					
							Hrs					
	Mfg#:22-12-00						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
221207	**Slip Clutch Breakaway Torque (Elevator) - Adjustment**							RE (-)			
22 A/F						Mos					
						Hrs					
Mfg#:22-12-00						Ldg					
221215	**Autopilot Control Cables (Aileron) - Adjustment**							RE (-)			
22 A/F						Mos					
						Hrs					
Mfg#:22-12-03						Ldg					
221216	**Autopilot Control Cables (Elevator) - Adjustment**							RE (-)			
22 A/F						Mos					
						Hrs					
Ref#:22-12-03						Ldg					
2013-18-09	**HONEYWELL ASCA INC - Emergency Locator Transmitter - Battery Wiring Discrepancies (Superseded by FAA AD 2014-17-02)**							RE (-)		Mandatory (Appliance AD)	
23 A/F						Mos	10-Feb-2023				
Not Applicable	NOT INSTALLED					Hrs	24:24				
						Ldg	7				
2014-17-02	**Communications - ELT Model RESCU 406AF and 406AFN (This AD Replaces AD 2013-18-09)**							RE (-)		Mandatory (Appliance AD)	
23 A/F						Mos	10-Feb-2023				
Eff: 09-Sep-2014 Not Applicable	NOT INSTALLED					Hrs	24:24				
(AVG MAN HRS: 1)						Ldg	7				
231107	**VHF Communications System - Operational Test**							RE (-)			
23 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:23-11-00-AT						Ldg	10				
231205	**HF Communications - Operational Test**							RE (-)			
23 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:23-12-00						Ldg	10				
235001	**Audio System - Functional Tests**							RE (-)			
23 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
ATA Ref::23-50-00, Mfg#:23-50-00						Ldg	10				
235118	**Audio Options Panel - Operational Test**							RE (-)			
23 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
ATA Ref::23-51-01, Mfg#:23-51-02-AT						Ldg	10				
235120	**Radio Interface Unit - Operational Check**							RE (-)			
23 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
ATA Ref::23-51-03, Mfg#:23-51-03						Ldg	10				
280-23-003	**Communications - Audio System - Installation Of Third Audio System (MODG25- 10004)**							RE (-)		Optional	
23 A/F						Mos					
Eff: 13-Nov-2012						Hrs					
						Ldg					
240001	**Electrical Power System - Functional Test**							RE (-)			
24 A/F						Mos					
						Hrs					
Mfg#:24-00-00						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
242103	**60Hz Static Inverter - Functional Test**							RE (-)			
24 A/F						Mos					
						Hrs					
Mfg#:24-21-01-AT						Ldg					
242104	**60Hz Static Inverter - Operational Test**							RE (-)			
24 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:24-21-01-AT						Ldg	10				
243107	**Engine Generator (Left) - Operational Test**							RE (-)			
24 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:24-31-01						Ldg	10				
243108	**Engine Generator (Right) - Operational Test**							RE (-)			
24 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:24-31-01						Ldg	10				
243115	**Engine Generator Control Unit (Left) - Voltage Adjustment**							RE (-)			
24 A/F						Mos					
						Hrs					
Mfg#:24-31-02-AT						Ldg					
243116	**Engine Generator Control Unit (Right) - Voltage Adjustment**							RE (-)			
24 A/F						Mos					
						Hrs					
Mfg#:24-31-02-AT						Ldg					
243125	**Engine Generator (Left) - Functional Test**							RE (-)			
24 A/F						Mos					
						Hrs					
Mfg#:24-31-01						Ldg					
243126	**Engine Generator (Right) - Functional Test**							RE (-)			
24 A/F						Mos					
						Hrs					
Mfg#:24-31-01						Ldg					
243207	**APU Starter-Generator - Operational Test**							RE (-)			
24 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:24-32-01						Ldg	10				
243208	**APU Starter-Generator - Functional Test**							RE (-)			
24 A/F						Mos					
						Hrs					
Mfg#:24-32-01						Ldg					
243209	**APU Starter-Generator Control Unit - Voltage Adjustment**							RE (-)			
24 A/F						Mos					
						Hrs					
Mfg#:24-32-02						Ldg					
243307	**Main Battery (Left) - Functional Test**							RE (-)			
24 A/F						Mos					
						Hrs					
Mfg#:24-33-01-AT						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
243308		**Main Battery (Right) - Functional Test**							RE (-)			
24 A/F							Mos					
							Hrs					
	Mfg#:24-33-01-AT						Ldg					
243309		**Main Battery (Left) - Operational Test**							RE (-)			
24 A/F							Mos	20-Oct-2023				
							Hrs	490:27				
	Mfg#:24-33-01-AT						Ldg	293				
243310		**Main Battery (Right) - Operational Test**							RE (-)			
24 A/F							Mos	20-Oct-2023				
							Hrs	490:27				
	Mfg#:24-33-01-AT						Ldg	293				
243505		**Emergency Power Supply Distribution - Operational Test**							RE (-)			
24 A/F							Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:24-35-00-AT						Ldg	10				
244101		**DC External Power - Operational Test**							RE (-)			
24 A/F							Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:24-41-00						Ldg	10				
244102		**DC External Power - Functional Test**							RE (-)			
24 A/F							Mos					
							Hrs					
	Mfg#:24-41-00						Ldg					
246105		**Left DC Box - Operational Test**							RE (-)			
24 A/F							Mos	20-Apr-2023				
							Hrs	124:16				
	Mfg#:24-61-01						Ldg	71				
246106		**Right DC Box - Operational Test**							RE (-)			
24 A/F							Mos	20-Apr-2023				
							Hrs	124:16				
	Mfg#:24-61-02						Ldg	71				
246301		**Emergency DC Box - Operational Test**							RE (-)			
24 A/F							Mos					
							Hrs					
	Mfg#:24-63-01						Ldg					
280-24-037		**Electrical Power - DC Electrical Load Distribution - Replacement Of Existing Left, Right And Emergency DC Boxes (MODG25-20040)**							RE (-)		Recommended	
24 A/F							Mos	10-Feb-2023				
Eff: 26-Apr-2013 Not Applicable		PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
							Ldg	7				
280-24-061		**Electrical Power - APU Starter - Generator Cables - Inspection - Sealing Rework (30P817582002)**							RE (-)		Recommended	
24 A/F							Mos	10-Feb-2023				
Eff: 16-May-2013 Not Applicable		PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
							Ldg	7				
280-24-073		**Electrical Power - Addition Of Electrical Bonding On Forward Fuselage Structure Between Column Assembly And Seat Track (MODG25-00342)**							RE (-)		Recommended	
24 A/F							Mos	10-Feb-2023				
Eff: 30-Oct-2015 Not Applicable		PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
							Ldg	7				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-24-075	**Electrical Power - Harness 1302 - Local Split And Rerouting Above Forward Right Side Radio Rack (MODG25-00389)**							RE (-)		Recommended	
24 A/F						Mos	10-Feb-2023				
Eff: 17-Jan-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-24-077	**Electrical Power - Wing Center Tank Fluid Quantity Measurement System (FQMS) - Wire Harness Installation Verification/Retrofit (MODG25-07092)**							RE (-)		Mandatory	
24 A/F						Mos	10-Feb-2023				
Eff: 04-Oct-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-24-080	**Electrical Power - Cabin Power Bus Controller (CPBC) , Galley Power Bus Controller (GPBC)- Feeder Cable - Inspection**							RE (-)		Recommended	
24 A/F						Mos	10-Feb-2023				
Eff: 21-Jun-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-24-085 Rev 1	**Electrical Power - DC Generation - Replacement of the Existing APU Digital Generator Control Unit (DGCU) MODS A and B with an Upgraded DGCU, MOD D (MODG25-20050)**							RE (-)		Recommended	
24 A/F						Mos	10-Feb-2023				
Eff: 28-Feb-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
(NOTE: This revision cancels this SB. Compliance is no longer required.)											
280-24-115	**Electrical Power - Cabin Power Bus Controller (CPBC) - Feeder And Supply Cable - Replacement Of Terminal Lug**							RE (-)		Recommended	
24 A/F						Mos	10-Feb-2023				
Eff: 21-Nov-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-24-194	**Electrical Power - Left Hand Distribution Bus - Add New Logic For Dual Generators Failure**							RE (-)		Optional	
24 A/F						Mos					
Eff: 09-Jun-2018						Hrs					
						Ldg					
280-24-201	**Electrical Power - Inspection Of Left And Right Main Battery Bay - Fuse Holder Installation (MODG25-01156)**							RE (-)		Recommended	
24 A/F						Mos	10-Feb-2023				
Eff: 16-Oct-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-24-208	**Electrical Power - Cabin Amplifier - Fault Protection For Cabin Power Bus Controller Improvement**							RE (-)		Recommended	
24 A/F						Mos	10-Feb-2023				
Eff: 18-Mar-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-24-241	**Electrical Power - Refuel/Defuel Panel - Electrical Connector 283Q1 Backshell Repositioning**							RE (-)		Recommended	
24 A/F						Mos	19-Apr-2023				
Eff: 06-Oct-2017 Not Applicable	as per A/C S/N					Hrs	124:16				
						Ldg	71				
(AVG MAN HRS: 13)											
280-24-241 Rev 1	**Electrical Power - Refuel/Defuel Panel - Electrical Connector 283Q1 Backshell Repositioning**							RE (-)		Recommended	
24 A/F						Mos	10-Feb-2023				
Eff: 10-Apr-2018 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
(AVG MAN HRS: 13)											

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-24-251	**Electrical Power (ATA 24) - DC Generation - Replacement of the Existing Engine and APU Digital Generator Control Unit (DGCU) MOD's A, B, C and/or D with an Upgraded DGCU, MOD E**							RE (-)		Recommended	
24 A/F						Mos	10-Feb-2023				
Eff: 29-Sep-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 6)						Ldg	7				
ST04469AT	**Installation Of The Concorde Lead Acid Battery Rg-380E , SupplementalType Certificate**							RE (-)			
24 A/F						Mos	10-Feb-2023				
Complied With						Hrs	24:24				
						Ldg	7				
	Infant Life Vest							RE (-)			
25 A/F						Mos				01-Oct-2028	4.1 Years
P0640-101	New					Hrs					
23060200045						Ldg					
Expiration Date 01-Oct-2028											
	Infant Life Vest							RE (-)			
25 A/F						Mos				01-Oct-2028	4.1 Years
P0640-101	New					Hrs					
23060200046						Ldg					
Expiration Date 01-Oct-2028											
2023-12-25	**Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets**							RE (-)		Mandatory	
25 A/F						Mos	10-Aug-2023				
Eff: 23-Aug-2023 Not Applicable						Hrs					
(UPDATE NOTE: N/A by type of the Life Jackets. Current Life Jackets made by ZODIAC AEROSPACE) (NOTE: APPLICABILITY: This AD applies to Survitec Group Limited (RFD Beaufort Ltd.) life jackets identified in paragraphs (c) (1) and (2) of this AD, having a part number and serial number identified in tables 2 through 13 of Survitec [RFD] Alert Service Bulletin 25-207-A, Version 1, dated November 24, 2021, and a date of manufacture between October 1, 2018, and April 30, 2019, inclusive.)						Ldg					
2023-14-10	**Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats (Supersedes FAA AD 2019-21-06)**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	10-Aug-2023				
Eff: 07-Sep-2023 Not Applicable						Hrs					
(UPDATE NOTE: N/A by SN of the pilot/co-pilot seats) (NOTE: APPLICABILITY: (1) This AD applies to: (i) Ipeco Holdings Limited (Ipeco) pilot and co-pilot seats with a part number (P/N) listed in Paragraph 1.A., Planning Information, Tables 1 and 2, of Ipeco Service Bulletin (SB) Number 063-25-14, Revision 00, dated August 14, 2018, and (ii) Ipeco pilot seat P/N 3A063-0099-01-1 and Ipeco co-pilot seat P/N 3A063-0100-01-1. (2) These seats are installed on, but not limited to, ATR-GIE Avions de Transport Regional ATR 42 and ATR 72 airplanes.)						Ldg					
2023-14-10 Par. (g)(2)(i)	**Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Inspect the Track Lock Spring of Each Seat**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	10-Aug-2023				
Not Applicable						Hrs	0				
(UPDATE NOTE: N/A by SN of the pilot/co-pilot seats)						Ldg					
256140	**Emergency Locator Transmitter Battery (Life Raft) - Scrap**							RE (-)			
25 A/F						Mos					
						Hrs					
						Ldg					
280-25-053 Rev 1	**Equipment And Furnishings - Baggage Compartment - Light Switch Angle Support Assembly Installation - Rework (MODG25-00319)**							RE (-)		Recommended	
25 A/F						Mos	10-Feb-2023				
Eff: 02-Jul-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-25-148	**Equipment And Furnishings - Flight Compartment - Installation Of Modification Label On Pilot And Copilot Seats (MODG25-00718)**							RE (-)		Recommended	
25 A/F						Mos	10-Feb-2023				
Eff: 02-Jul-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-25-175	**Equipment And Furnishings - Replacement Of Cockpit Airworthiness Certificate Holder**							RE (-)		Recommended	
25 A/F						Mos	10-Feb-2023				
Eff: 08-May-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-25-212	**Equipment and Furnishings - Baggage Compartment - Modified Configuration of Baggage Restraining System**							RE (-)		Recommended	
25 A/F						Mos	10-Feb-2023				
Eff: 23-Apr-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 12)						Ldg	7				
280-25-213	**Equipment/Furnishings - Emergency Escape Hatch Cabin Management System (CMS) Electrical Connectors - Inspection For Friction Only Installation Of Electrical Connectors**							RE (-)		Recommended	
25 A/F						Mos	10-Feb-2023				
Eff: 11-Dec-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-25-220	**Equipment / Furnishings - Cabin Window Shade Improvement**							RE (-)		Recommended	
25 A/F						Mos	10-Feb-2023				
Eff: 13-Apr-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-25-255	**Equipment / Furnishings - Microwave Installation**							RE (-)		Optional	
25 A/F						Mos					
Eff: 20-Nov-2017						Hrs					
(AVG MAN HRS: 236)						Ldg					
280-25-255 Rev 1	**Equipment/Furnishings - Microwave Installation**							RE (-)		Optional	
25 A/F						Mos					
Eff: 22-Aug-2018						Hrs					
(AVG MAN HRS: 236)						Ldg					
280-25-309	**Equipment / Furnishings - Baggage No Entry Sign**							RE (-)		Recommended	
25 A/F						Mos	10-Feb-2023				
Eff: 10-Aug-2022 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 60)						Ldg	7				
2017-19-05	**Smoke Detection - Inspection / Replacement**							RE (-)		Mandatory (Appliance AD)	
26 A/F						Mos	10-Feb-2023				
Eff: 31-Oct-2017 Not Applicable	PART NUMBER NOT INSTALLED.					Hrs	24:24				
(AVG MAN HRS: 1)						Ldg	7				
260003	**Fire Protection Control Unit - Operational Test**							RE (-)			
26 A/F						Mos					
						Hrs					
Mfg#:26-00-01-AT						Ldg					
261001	**Fire Detection System - Functional Test**							RE (-)			
26 A/F						Mos					
						Hrs					
Mfg#:26-10-00-AT						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
261002	**Fire Test - Operational Test**							RE (-)			
26 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:26-10-00-AT						Ldg	10				
261303	**Baggage Compartment Smoke Detection - Operational Test**							RE (-)			
26 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:26-13-00						Ldg	10				
261455	**Bleed Leak / Overheat Detectors - Operational Test**							RE (-)			
26 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:26-14-00						Ldg	10				
262201	**Baggage Compartment Smoke Evacuation - Functional Test**							RE (-)			
26 A/F						Mos					
						Hrs					
Mfg#:26-22-00						Ldg					
280-26-052	**Fire Protection - Engine Fire Detection - Correction Of Wiring And Replacement Of Incorrectly Installed Pylon Fire Sensor BRD Labels (MODG25-00321**							RE (-)		Recommended	
26 A/F						Mos	10-Feb-2023				
Eff: 21-Nov-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-26-246	**Fire Protection - Fire Protection Control Unit (FPCU) - Replacement of Existing FPCUP/N 30P841300000-001 or FPCU P/N 30P841300000-003 with FPCU P/N 30P841300000-005**							RE (-)		Recommended	
26 A/F						Mos	10-Feb-2023				
Eff: 24-Apr-2018 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 3)						Ldg	7				
280-26-304	**Fire Protection - Bleed Leak Detection Sensors - Inspection and Replacement in Aft Service Compartment**							RE (-)		Recommended	
26 A/F						Mos	10-Aug-2023				
Eff: 16-Jun-2023 Not Applicable						Hrs					
(AVG MAN HRS: 14) (UPDATE NOTE: N/A by SN of the aircraft)						Ldg					
280-26-307	**Fire Protection - Bleed Leak Detection Sensors - Inspection and Replacement in Pylons and Baggage Compartment**							RE (-)		Recommended	
26 A/F						Mos	10-Aug-2023				
Eff: 16-Jun-2023 Not Applicable						Hrs					
(AVG MAN HRS: 22) (UPDATE NOTE: N/A by SN of the aircraft)						Ldg					
280-26-308	**Fire Protection - Bleed Leak Detection Sensors - Inspection and Replacement Under Upper Fuselage Wing and Aft Fairings**							RE (-)		Recommended	
26 A/F						Mos	10-Aug-2023				
Eff: 16-Jun-2023 Not Applicable						Hrs					
(AVG MAN HRS: 22) (UPDATE NOTE: N/A by SN of the aircraft)						Ldg					
270001	**Flight Control Electronic Control Unit - Functional Test**							RE (-)			
27 A/F						Mos	05-May-2023				
						Hrs	142:54				
Mfg#:27-00-01						Ldg	81				
270002	**Flight Control Electronic Control Unit - Functional Test**							RE (-)			
27 A/F						Mos	05-May-2023				
						Hrs	142:54				
Mfg#:27-00-01						Ldg	81				
270005	**Electronic Rigging Setup**							RE (-)			
27 A/F						Mos					
						Hrs					
Mfg#:27-00-00						Ldg					

Task No / SEQ	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
270006	**Flight Control Surface Position - Check**							RE (-)			
27 A/F						Mos					
						Hrs					
Mfg#:27-00-00						Ldg					
271001	**Aileron and Trim - Operational Test**							RE (-)			
27 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:27-10-00-AT						Ldg	10				
271003	**Aileron - Rigging**							RE (-)			
27 A/F						Mos					
						Hrs					
Mfg#:27-10-00-AT						Ldg					
271101	**Aileron Control System - Travel Test**							RE (-)			
27 A/F						Mos					
						Hrs					
Mfg#:27-11-00						Ldg					
271102	**Aileron - Breakout Force Check**							RE (-)			
27 A/F						Mos					
						Hrs					
Mfg#:27-11-00						Ldg					
271103	**Aileron - Backlash Test**							RE (-)			
27 A/F						Mos					
						Hrs					
Mfg#:27-11-00						Ldg					
271203	**Aileron Trim Actuator Dual Output Shaft - Functional Check**							RE (-)			
27 A/F						Mos					
						Hrs					
Mfg#:27-12-01						Ldg					
271313	**Aileron Trim Tab - Travel Test**							RE (-)			
27 A/F						Mos					
						Hrs					
Mfg#:27-13-02						Ldg					
271314	**Aileron Trim Tab Free Play - Test**							RE (-)			
27 A/F						Mos					
						Hrs					
Mfg#:27-13-02						Ldg					
271315	**Aileron Trim Tab - Rigging**							RE (-)			
27 A/F						Mos					
						Hrs					
Mfg#:27-13-02						Ldg					
271325	**Aileron Gear Tab - Travel Test**							RE (-)			
27 A/F						Mos					
						Hrs					
Mfg#:27-13-03						Ldg					
271326	**Aileron Gear Tab (Right) - Travel Test**							RE (-)			
27 A/F						Mos					
						Hrs					
Mfg#:27-13-03						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
271327		**Aileron Gear Tab - Clearance Check**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-13-03						Ldg					
271328		**Aileron Gear Tab - Clearance Check**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-13-03						Ldg					
271329		**Aileron Gear Tab - Rigging**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-13-03						Ldg					
271330		**Aileron Gear Tab - Rigging**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-13-03						Ldg					
271333		**Aileron Gear Tab - Free Play Test**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-13-03						Ldg					
271334		**Aileron Gear Tab - Free Play Test**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-13-03						Ldg					
272001		**Rudder and Trim - Operational Test**							RE (-)			
	27 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:27-20-00						Ldg	10				
272002		**Rudder System Zero Position Verification**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-20-00-AT						Ldg					
272003		**Rudder System Interference and Clearance Check**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-20-00-AT						Ldg					
272004		**Rudder Feel Trim Unit - Functional Test**							RE (-)			
	27 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:27-20-00-AT						Ldg	10				
272005		**Rudder Interconnection - Functional Test**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-20-00-AT						Ldg					
272006		**Rudder Limitation at Various Airspeeds - Functional Test**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-20-00-AT						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
272007		**Rudder Trim Limitation at Various Airspeeds - Functional Test**							RE (-)			
27 A/F							Mos					
							Hrs					
	Mfg#:27-20-00-AT						Ldg					
272008		**Rudder Thrust Asymmetry Compensation - Functional Test**							RE (-)			
27 A/F							Mos					
							Hrs					
	Mfg#:27-20-00-AT						Ldg					
272009		**Rudder Command Roll Spoilers Response - Functional Test**							RE (-)			
27 A/F							Mos					
							Hrs					
	Mfg#:27-20-00-AT						Ldg					
272010		**Rudder Take Off Green Band - Functional Test**							RE (-)			
27 A/F							Mos					
							Hrs					
	Mfg#:27-20-00-AT						Ldg					
272011		**Rudder Strokes Validation Test**							RE (-)			
27 A/F							Mos					
							Hrs					
	Mfg#:27-20-00-AT						Ldg					
272012		**Rudder Pedals Backlash Test**							RE (-)			
27 A/F							Mos					
							Hrs					
	Mfg#:27-20-00-AT						Ldg					
272013		**Rudder Pedals Breakout and Force Test**							RE (-)			
27 A/F							Mos					
							Hrs					
	Mfg#:27-20-00-AT						Ldg					
272014		**Rudder Trim Switch Authority Test**							RE (-)			
27 A/F							Mos					
							Hrs					
	Mfg#:27-20-00-AT						Ldg					
272015		**Rudder - Rigging**							RE (-)			
27 A/F							Mos					
							Hrs					
	Mfg#:27-20-00-AT						Ldg					
272133		**Rudder Pedals - Adjustment**							RE (-)			
27 A/F							Mos					
							Hrs					
	Mfg#:27-21-03						Ldg					
273001		**Elevator Control System - Operational Test**							RE (-)			
27 A/F							Mos					
							Hrs					
	Mfg#:27-30-00						Ldg					
273002		**Elevator Control Cables Tension - Adjustment**							RE (-)			
27 A/F							Mos					
							Hrs					
	Mfg#:27-30-00						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
273003		**Elevator Control System - Rigging**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-30-00						Ldg					
273101		**Elevator Control System - Travel Test**							RE (-)			
	27 A/F						Mos	05-May-2023				
							Hrs	142:54				
	Mfg#:27-31-00-AT						Ldg	81				
273102		**Elevator Control Loop Backlash - Test**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-31-00-AT						Ldg					
273103		**Pilot Force vs Elevator Travel - Test**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-31-00-AT						Ldg					
273104		**Elevator Friction Band and Breakout Force - Test**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-31-00-AT						Ldg					
273105		**Elevator Free Play - Test**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-31-00-AT						Ldg					
273139		**Elevator Servo Actuator - Discard**							RE (-)			
	27 A/F	Left					Mos					
	CA49494-004						Hrs					
	B0590						Ldg					
	Mfg#:27-31-04-RI											
273140		**Elevator Servo Actuator - Discard**							RE (-)			
	27 A/F	Right					Mos					
	CA50298-004						Hrs					
	B0632						Ldg					
	Mfg#:27-31-04-RI											
273307		**Q-feel Actuator - Operational Test**							RE (-)			
	27 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:27-33-02						Ldg	10				
274001		**Horizontal Stabilizer - Operational Test**							RE (-)			
	27 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:27-40-00-AT						Ldg	10				
274002		**Horizontal Stabilizer - Interference Test**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-40-00-AT						Ldg					
274003		**Horizontal Stabilizer - Functional Test**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-40-00-AT						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
274115		**Horizontal Stabilizer Trim Actuator No-Back Pawl - Operational Check**							RE (-)			
	27 A/F						Mos					
							Hrs					
							Ldg					
275001		**Flaps - Travel Test**							RE (-)			
	27 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:27-50-00-AT						Ldg	10				
275002		**Flaps Normal Mode - Functional Test**							RE (-)			
	27 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:27-50-00-AT						Ldg	10				
275005		**Flaps - Alignment / Rigging**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-50-00-AT						Ldg					
275006		**Flap Free Play - Adjustment / Test**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-50-00-AT						Ldg					
275007		**Track to Roller Side Gaps - Adjustment / Test**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-50-00-AT						Ldg					
275008		**Flap Roller to Track Gap / Actuator - Overtravel Up Stop Test**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-50-00-AT						Ldg					
275009		**Actuator Overtravel - Down Stop Test**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-50-00-AT						Ldg					
275010		**Turn Down Hook - Rigging**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-50-00-AT						Ldg					
275115		**Flap Actuator - Discard**							RE (-)		05-10-10 Life Limited Components	
	27 A/F	Left Inboard					Mos					
	C64897-003						Hrs					
	B0356A						Ldg					
	ATA Ref:27-51-02 (SOURCE: G280 AMM)											
275116		**Flap Actuator - Discard**							RE (-)		05-10-10 Life Limited Components	
	27 A/F	Right Inboard					Mos					
	C64897-003						Hrs					
	B0361A						Ldg					
	ATA Ref:27-51-02 (SOURCE: G280 AMM)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
276002		**Spoiler System - Functional Test**							RE (-)			
	27 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:27-60-00-AT						Ldg	10				
276003		**Roll Assist Mode - Operational Test**							RE (-)			
	27 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:27-60-00-AT						Ldg	10				
276005		**Pilot Authority Disconnect Switch - Operational Test**							RE (-)			
	27 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:27-60-00-AT						Ldg	10				
276006		**Flap to Roll Assist Interconnection - Operational Test**							RE (-)			
	27 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:27-60-00-AT						Ldg	10				
276007		**Air Brake Mode - Functional Test**							RE (-)			
	27 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:27-60-00-AT						Ldg	10				
276008		**Combined Mode - Functional Test**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-60-00-AT						Ldg					
276009		**Ground Brake Mode - Functional Test**							RE (-)			
	27 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:27-60-00-AT						Ldg	10				
276205		**Spoiler Boards - Rigging**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-60-00-AT						Ldg					
276215		**Spoiler Position Sensors - Rigging**							RE (-)			
	27 A/F						Mos					
							Hrs					
	Mfg#:27-60-00-AT						Ldg					
280-27-056		**Flight Controls - Multi-Function Spoiler Actuator (MFSA) And Ground Spoiler Actuator (GSA) - Gland Retainer Ring Inspection (MODG25-00242)**							RE (-)		Recommended	
	27 A/F						Mos	10-Feb-2023				
	Eff: 26-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
							Ldg	7				
280-27-067		**Flight Controls - Aileron Trim - Inspection Of Aileron Trim Actuator Inner And Outer Output Shafts (MODG25-00377)**							RE (-)		Mandatory	
	27 A/F						Mos	10-Feb-2023				
	Eff: 12-Apr-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
							Ldg	7				
280-27-068 Rev 1		**Flight Controls - Aileron Trim - Rework Of Aileron Trim Actuator Output Shaft Arms (MODG25-00382)**							RE (-)		Recommended	
	27 A/F						Mos	10-Feb-2023				
	Eff: 21-Jun-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
							Ldg	7				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-27-081	**Flight Controls - Flap Hydraulic Control Module (HCM) - Replacement (MODG25- 00433)**							RE (-)		Recommended	
27 A/F						Mos	10-Feb-2023				
Eff: 17-Apr-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-27-113	**Flight Controls - Pilot/Copilot Control Wheel - Horizontal Trim Switch Replacement (MODG25-20063)**							RE (-)		Recommended	
27 A/F						Mos	10-Feb-2023				
Eff: 21-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-27-123	**Flight Controls - Flap Drive Shaft Assemblies - Inspection And Reattachment (MODG25-00608)**							RE (-)		Recommended	
27 A/F						Mos	10-Feb-2023				
Eff: 24-Jan-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-27-141	**Flight Controls - Flap Actuators - Drainage Improvement (MODG25-20069)**							RE (-)		Recommended	
27 A/F						Mos	10-Feb-2023				
Eff: 16-Oct-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-27-144	**Flight Controls - Aileron Controls - Prevention Of Possible Interference Between Fuselage To Wing Control Rod Bolt And Bird Strike Plate (MODG25-07148)**							RE (-)		Recommended	
27 A/F						Mos	10-Feb-2023				
Eff: 30-Oct-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-27-165	**Flight Controls - Horizontal Stabilizer Trim Actuator (HSTA) - Secondary Motor Cap Screw Interference (MODG25-20078)**							RE (-)		Recommended	
27 A/F						Mos	10-Feb-2023				
Eff: 08-Jul-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-27-198	**Flight Controls - Rudder Servo Actuator - Replacement (MODG25-20096)**							RE (-)		Recommended	
27 A/F						Mos	19-Apr-2023				
Eff: 09-Jun-2016 Not Applicable	as per A/C S/N					Hrs	124:16				
						Ldg	71				
280-27-198 Rev1	**Flight Controls - Rudder Servo Actuator - Replacement (MODG25-20096)**							RE (-)		Recommended	
27 A/F						Mos	10-Feb-2023				
Eff: 29-Jun-2018 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 15)						Ldg	7				
280-27-210	**Flight Controls (ATA 27) Flight Control Electronic Control Unit (FCECU) #1 and #2 - Inspection and Replacement**							RE (-)		Recommended	
27 A/F						Mos	19-Apr-2023				
Eff: 11-Jul-2019 Not Applicable	as per A/C S/N					Hrs	124:16				
(AVG MAN HRS: 50)						Ldg	71				
280-27-210 Rev 1	**Flight Controls (ATA 27) - Flight Control Electronic Control Unit (FCECU) #1 - Inspection and Replacement**							RE (-)		Recommended	
27 A/F						Mos	10-Feb-2023				
Eff: 18-Oct-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 14)						Ldg	7				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-27-286	**Flight Controls - Flight Control Electronic Control Unit (FCECU) #2 - Inspection and Replacement**							RE (-)		Recommended	
27 A/F						Mos	10-Feb-2023				
Eff: 18-Oct-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 12)						Ldg	7				
280-27-303	**Flight Controls - Ground Spoiler Actuator (GSA) Rod - End Torque**							RE (-)		Recommended	
27 A/F						Mos	10-Feb-2023				
Eff: 28-Oct-2022 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 4)						Ldg	7				
280-27-310	**Flight Controls - Flaps - Actuator Mechanism Clearance Inspection and Rework**							RE (-)		Recommended	
27 A/F						Mos	10-Sep-2024				
Eff: 14-Jun-2024 Not Applicable						Hrs					
(AVG MAN HRS: 10)						Ldg					
280003	**Fuel Quantity Measurement System - Operational Test**							RE (-)			
28 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:28-00-00-AT						Ldg	10				
280006	**High Level Sensor - Functional Test**							RE (-)			
28 A/F						Mos	01-Jun-2024				
						Hrs	848:22				
Mfg#:28-00-00-AT						Ldg	497				
280007	**Gravity Cross-flow Valve - Functional Test**							RE (-)			
28 A/F						Mos					
						Hrs					
Mfg#:28-00-00-AT						Ldg					
280008	**Pressure Refueling System - Operational Test**							RE (-)			
28 A/F						Mos					
						Hrs					
Mfg#:28-00-00-AT						Ldg					
280-28-044	**Fuel - Fluid Quantity Measuring Computer - Software Update (MODG25-20025)**							RE (-)		Recommended	
28 A/F						Mos	10-Feb-2023				
Eff: 27-Jun-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-28-062	**Fuel - Wing Inboard Fuel Tank To Feed Tank Flapper Valve Sealing/Leakage Check (MODG25-00364)**							RE (-)		Recommended	
28 A/F						Mos	10-Feb-2023				
Eff: 02-Jul-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-28-063	**Fuel - Fuel Distribution - Center Fuel Tank Tubing - Validation And Replacement Of Fuel Tubes (MODG25-00375)**							RE (-)		Recommended	
28 A/F						Mos	10-Feb-2023				
Eff: 26-Jul-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-28-065	**Fuel - Fuel Storage - Positive/Negative Pressure Relief Valve - Updated Operational Check (MODG25-00368)**							RE (-)		Recommended	
28 A/F						Mos	10-Feb-2023				
Eff: 13-Dec-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-28-138	**Fuel - Distribution - Wing Float Valve - Quality Conformance Inspection (MODG25- 00674)**							RE (-)		Recommended	
28 A/F						Mos	10-Feb-2023				
Eff: 26-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-28-168	**Fuel - Engine Fuel Feed Line - Re-Torque Of Engine Fuel Feed Line Fittings (MODG25-00855)**							RE (-)		Recommended	
28 A/F						Mos	10-Feb-2023				
Eff: 03-Oct-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-28-237	**Fuel - Forward Fuel Tank - Access Panels Jumper Attachments Sealing Improvement (MOD G25-20132**							RE (-)		Recommended	
28 A/F						Mos	10-Feb-2023				
Eff: 22-Aug-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
281105	**Fuel Tank Wiring Installations - Detailed Inspection**							RE (-)			
28 A/F						Mos					
						Hrs					
Mfg#:28-11-01						Ldg					
281106	**Fuel Tank Wiring Installations - Detailed Inspection**							RE (-)			
28 A/F						Mos					
						Hrs					
Mfg#:28-11-02						Ldg					
281107	**Center Fuel Tank Wiring Installations - Detailed Inspection**							RE (-)			
28 A/F						Mos					
						Hrs					
Mfg#:28-11-03						Ldg					
281108	**Wing Fuel Tank Wiring Installations (Left) - Detailed Inspection**							RE (-)			
28 A/F						Mos					
						Hrs					
Mfg#:28-11-04						Ldg					
281109	**Wing Fuel Tank Wiring Installations (Right) - Detailed Inspection**							RE (-)			
28 A/F						Mos					
						Hrs					
Mfg#:28-11-04						Ldg					
281321	**Drain Valve (Feed Tank, Left) - Operational Test**							RE (-)			
28 A/F						Mos					
						Hrs					
Mfg#:28-13-01						Ldg					
281322	**Drain Valve (Feed Tank, Right) - Operational Test**							RE (-)			
28 A/F						Mos					
						Hrs					
Mfg#:28-13-01						Ldg					
281323	**Drain Valve (Wing Vent, Left) - Operational Test**							RE (-)			
28 A/F						Mos					
						Hrs					
Mfg#:28-13-01						Ldg					
281324	**Drain Valve (Wing Vent, Right) - Operational Test**							RE (-)			
28 A/F						Mos					
						Hrs					
Mfg#:28-13-01						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
281325		**Drain Valve (Rib 2, Left) - Operational Test**							RE (-)			
	28 A/F						Mos					
							Hrs					
	Mfg#:28-13-01						Ldg					
281326		**Drain Valve (Rib 2, Right) - Operational Test**							RE (-)			
	28 A/F						Mos					
							Hrs					
	Mfg#:28-13-01						Ldg					
281328		**Drain Valve (Center Tank) - Operational Test**							RE (-)			
	28 A/F						Mos					
							Hrs					
	Mfg#:28-13-01						Ldg					
281329		**Drain Valve (Forward Tank) - Operational Test**							RE (-)			
	28 A/F						Mos					
							Hrs					
	Mfg#:28-13-01						Ldg					
281330		**Drain Valve (Aft Tank) - Operational Test**							RE (-)			
	28 A/F						Mos					
							Hrs					
	Mfg#:28-13-01						Ldg					
281332		**Drain Valve - Repair**							RE (-)			
	28 A/F						Mos					
							Hrs					
	Mfg#:28-13-01						Ldg					
282113		**Boost Pump - Operational Test**							RE (-)			
	28 A/F						Mos	06-Nov-2023				
							Hrs	515:44				
	Mfg#:28-21-02						Ldg	304				
282133		**Fuel Shut-off Valve - Operational Check**							RE (-)			
	28 A/F						Mos					
							Hrs					
	Mfg#:28-21-04						Ldg					
284101		**Fuel Quantity Measurement System - Functional Test**							RE (-)			
	28 A/F						Mos					
							Hrs					
	Mfg#:28-00-00-AT (SOURCE: 28-00-00)						Ldg					
284103		**Fluid Quantity Measurement Computer Wiring Installation - Detailed Inspection**							RE (-)			
	28 A/F						Mos					
							Hrs					
	Mfg#:28-41-01						Ldg					
284104		**Fuel Quantity Measuring Computer (FQMC) - Functional Test**							RE (-)			
	28 A/F						Mos					
							Hrs					
							Ldg					
284105		**Fuel Quantity Measurement System - Capacitance / Resistance Check**							RE (-)			
	28 A/F						Mos					
							Hrs					
	Mfg#:28-41-00						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-29-072	**Hydraulic Power - Fluid Quantity Measuring Computer (FQMC) - Correction Of Wiring In Plug 218Q3 And Replacement Of Incorrectly Installed BRD Labels 165C And 167C In Aft Fuselage (MODG25-00369)**							RE (-)		Recommended	
29 A/F						Mos	10-Feb-2023				
Eff: 13-Dec-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-29-176	**Hydraulic Power - Aft Fuselage - Right Hydraulic System Tube Chaffing (MODG25- 00917)**							RE (-)		Recommended	
29 A/F						Mos	10-Feb-2023				
Eff: 22-Nov-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-29-214	**Hydraulic Power - Vertical Stabilizer - Creating Positive Separation between Hydraulic Hoses and Electrical Harnesses**							RE (-)		Recommended	
29 A/F						Mos	10-Feb-2023				
Eff: 17-Oct-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 8)						Ldg	7				
280-29-300	**Hydraulic Power (ATA 29) - Charging Placards**							RE (-)		Recommended	
29 A/F						Mos	10-Feb-2023				
Eff: 09-Dec-2022 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 4)						Ldg	7				
291001	**Hydraulic System (Left) - Bleed**							RE (-)			
29 A/F						Mos					
						Hrs					
Mfg#:29-10-00						Ldg					
291002	**Hydraulic System (Right) - Bleed**							RE (-)			
29 A/F						Mos					
						Hrs					
Mfg#:29-10-00						Ldg					
291105	**Engine-Driven Pump (Left) - Operational Test**							RE (-)			
29 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:29-11-01						Ldg	10				
291106	**Engine-Driven Pump (Right) - Operational Test**							RE (-)			
29 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:29-11-01						Ldg	10				
291111	**Electric Motor Pump (Left) - Operational Test**							RE (-)			
29 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:29-11-02						Ldg	10				
291112	**Electric Motor Pump (Right) - Operational Test**							RE (-)			
29 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:29-11-02						Ldg	10				
291217	**Hydraulic Fire Shut-off Valve - Operational Test**							RE (-)			
29 A/F						Mos					
						Hrs					
Mfg#:29-12-03						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
291223	**Manifold Relief Valve (Left) - Operational Test**							RE (-)			
29 A/F						Mos					
						Hrs					
Mfg#:29-12-04						Ldg					
291224	**Manifold Relief Valve (Right) - Operational Test**							RE (-)			
29 A/F						Mos					
						Hrs					
Mfg#:29-12-04						Ldg					
291317	**Hydraulic System Pressure Filter - Operational Test**							RE (-)			
29 A/F						Mos					
						Hrs					
Mfg#:29-13-01						Ldg					
291329	**Hydraulic System Return Filter - Operational Test**							RE (-)			
29 A/F						Mos					
						Hrs					
Mfg#:29-13-02						Ldg					
293101	**Fluid Level Indicator (Left) - Operational Test**							RE (-)			
29 A/F						Mos					
						Hrs					
Mfg#:29-31-01						Ldg					
293102	**Fluid Level Indicator (Right) - Operational Test**							RE (-)			
29 A/F						Mos					
						Hrs					
Mfg#:29-31-01						Ldg					
293107	**Hydraulic Temperature Sensor (Left) - Operational Test**							RE (-)			
29 A/F						Mos					
						Hrs					
Mfg#:29-31-02						Ldg					
293108	**Hydraulic Temperature Sensor (Right) - Operational Test**							RE (-)			
29 A/F						Mos					
						Hrs					
Mfg#:29-31-02						Ldg					
293121	**Engine-driven Pump Manifold Pressure Switch - Operational Test**							RE (-)			
29 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:29-31-03						Ldg	10				
293122	**Electric Motor Pump Manifold Pressure Switch - Operational Test**							RE (-)			
29 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:29-31-03						Ldg	10				
280-30-017 Part A	**Ice And Rain Protection - Wing Anti-Ice (WAI) System -Air Flow And General Aviation Digital Controller Modifications - Installation Of System Crossover Valve (Cancelled)**							RE (-)		Mandatory	
30 A/F						Mos	17-Apr-2023				
Not Applicable	as per a/c S/N					Hrs	122:11				
						Ldg	69				
280-30-017 Part B	**Ice And Rain Protection - Wing Anti-Ice (WAI) System -Air Flow And General Aviation Digital Controller Modifications - Installation Of System Crossover Valve (Cancelled)**							RE (-)		Mandatory	
30 A/F						Mos	17-Apr-2023				
Not Applicable	as per a/c S/N					Hrs	122:11				
						Ldg	69				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-30-017 Part C		**Ice And Rain Protection - Wing Anti-Ice (WAI) System -Air Flow And General Aviation Digital Controller Modifications - Installation Of System Crossover Valve (Cancelled)**							RE (-)		Mandatory	
30 A/F							Mos	17-Apr-2023				
Not Applicable		as per a/c S/N					Hrs	122:11				
							Ldg	69				
280-30-017 Part D		**Ice And Rain Protection - Wing Anti-Ice (WAI) System -Air Flow And General Aviation Digital Controller Modifications - Installation Of System Crossover Valve (Cancelled)**							RE (-)		Mandatory	
30 A/F							Mos	17-Apr-2023				
Not Applicable		as per a/c S/N					Hrs	122:11				
							Ldg	69				
280-30-017 Rev 1		**Ice and Rain Protection - Wing Anti-Ice (WAI) Sytem - Air Flow And General Aviation Digital Controller (GADC) Modifications - Installation Of System Crossover Valve And New General Aviation Digital Controller (GADC-4) (MODG25-00262)**							RE (-)		Mandatory	
30 A/F							Mos	17-Apr-2023				
Eff: 12-Dec-2014 Not Applicable		as per a/c S/N					Hrs	122:11				
							Ldg	69				
280-30-017 Rev 1 Part A		**SB 280-30-017R1 Part A Wing Anti Ice System - Air Flow and General Aviation Digital Controller Modifications - Installation of System Crossover Valve**							RE (-)		Mandatory	
30 A/F							Mos	10-Feb-2023				
Eff: 12-Dec-2014 Not Applicable		PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
							Ldg	7				
280-30-017 Rev 1 Part B		**SB 280-30-017R1 Part B Wing Anti Ice System - Air Flow and General Aviation Digital Controller Modifications - Installation of System Crossover Valve**							RE (-)		Mandatory	
30 A/F							Mos	10-Feb-2023				
Eff: 12-Dec-2014 Not Applicable		PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
							Ldg	7				
280-30-017 Rev 1 Part C		**SB 280-30-017R1 Part C Wing Anti Ice System - Air Flow and General Aviation Digital Controller Modifications - Installation of System Crossover Valve**							RE (-)		Mandatory	
30 A/F							Mos	10-Feb-2023				
Eff: 12-Dec-2014 Not Applicable		PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
							Ldg	7				
280-30-017 Rev 1 Part D		**SB 280-30-017R1 Part D Wing Anti Ice System - Air Flow and General Aviation Digital Controller Modifications - Installation of System Crossover Valve**							RE (-)		Mandatory	
30 A/F							Mos	10-Feb-2023				
Eff: 12-Dec-2014 Not Applicable		PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
							Ldg	7				
280-30-157		**Ice/Rain Protection - Windshield De-Ice Control System - Replacement Of The Existing Controllers (5H AND 6H) P/N 25G8460007-003 With Modified Controllers P/N 25G8460007-005 (MODG25-20071)**							RE (-)		Recommended	
30 A/F							Mos	10-Feb-2023				
Eff: 14-May-2015 Not Applicable		PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
							Ldg	7				
280-30-158		**Ice and Rain Protection - Addintional Wing Anti-Ice Manifold Pressure Sensor - Removal (MOD G25-20071)**							RE (-)		Recommended	
30 A/F							Mos	10-Feb-2023				
Eff: 15-Dec-2015 Not Applicable		PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
							Ldg	7				
280-30-253		**Ice and Rain Protection - Replacement of Wing Anti-Ice Crossover Valve - P/N 30P781007000-001 (P/N 63292106-2)**							RE (-)		Recommended	
30 A/F							Mos	19-Apr-2023				
Eff: 01-Oct-2019 Not Applicable		as per A/C S/N					Hrs	124:16				
(AVG MAN HRS: 14)							Ldg	71				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-30-253 Rev 1		**Ice and Rain Protection - Replacement of Wing Anti-Ice Crossover Valve - P/N 30P781007000-001 (P/N 63292106-2)**							RE (-)		Recommended	
30 A/F							Mos	10-Feb-2023				
Eff: 29-Oct-2020 Not Applicable		PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 14)							Ldg	7				
300001		**Anti-ice System (Pre-SB 280-30-017) - Functional Check**							RE (-)			
30 A/F							Mos					
							Hrs					
Mfg#:30-00-00-AT (SOURCE: G280 AMM)							Ldg					
300002		**Anti-ice System (Post SB 280-30-017) - Functional Check**							RE (-)			
30 A/F							Mos	02-Mar-2023				
							Hrs	34:12				
Ref#:30-00-00-AT (SOURCE: G280 AMM)							Ldg	10				
302111		**Engine Anti-ice System (Left) - Functional Test**							RE (-)			
30 A/F							Mos	02-Mar-2023				
							Hrs	34:12				
Mfg#:30-21-00							Ldg	10				
302112		**Engine Anti-ice System (Right) - Functional Test**							RE (-)			
30 A/F							Mos	02-Mar-2023				
							Hrs	34:12				
Mfg#:30-21-00							Ldg	10				
303001		**Probes Heating - Operational Test**							RE (-)			
30 A/F							Mos	02-Mar-2023				
							Hrs	34:12				
Mfg#:30-30-00							Ldg	10				
304105		**Windshield Heat - Functional Test**							RE (-)			
30 A/F							Mos	02-Mar-2023				
							Hrs	34:12				
Mfg#:30-41-00							Ldg	10				
308105		**Ice Detector - Functional Test**							RE (-)			
30 A/F							Mos	02-Mar-2023				
							Hrs	34:12				
Mfg#:30-81-01							Ldg	10				
280-31-011		**Indicating/Recording - Cockpit Voice Recorder (CVR) - Installation Of Recorder Independent Power Supply (RIPS) (MODG25-10020)**							RE (-)		Recommended	
31 A/F							Mos	19-Apr-2023				
Eff: 30-Oct-2015 Not Applicable		as per A/C S/N					Hrs	124:16				
							Ldg	71				
280-31-043		**Indicating/Recording - Replacement Of Existing Cockpit Voice Recorder (CVR) Independent Power Supply (RIPS) P/N 100-3010-000 With Upgraded RIPS P/N 100- 3010-001 (MODG25-20029)**							RE (-)		Recommended	
31 A/F							Mos	10-Feb-2023				
Eff: 09-Apr-2015 Not Applicable		PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
							Ldg	7				
280-31-283		**Indicating/Recording Systems - Adaptive Flight Display (AFD-6510) Inspection and Replacement**							RE (-)		Recommended	
31 A/F							Mos	10-Sep-2024				
Eff: 03-Mar-2023 Not Applicable							Hrs					
(AVG MAN HRS: 4)							Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-31-283 Rev 1	**Indicating/Recording Systems - Adaptive Flight Display (AFD-6510) Inspection and Replacement**							RE (-)		Recommended	
31 A/F						Mos	10-Sep-2024				
Eff: 07-Jun-2024 Not Applicable						Hrs					
(AVG MAN HRS: 4)						Ldg					
280-31-297	**Indicating/Recording Systems - Adaptive Flight Display (AFD 6510-141) - Upgrade**							RE (-)		Recommended	
31 A/F						Mos	10-Feb-2023				
Eff: 23-Apr-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 4)						Ldg	7				
313119	**Flight Data Recorder - Operational Test**							RE (-)			
31 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:31-31-00-AT						Ldg	10				
313121	**Inertial Switch - Operational Test**							RE (-)			
31 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:31-31-04-AT						Ldg	10				
313122	**Inertial Switch - Operational Test**							RE (-)			
31 A/F						Mos					
						Hrs					
Ref#:31-31-04-AT						Ldg					
313125	**Underwater Locator Beacon Battery (No. 1) - Inspection / Check**							RE (-)			
31 A/F						Mos					
						Hrs					
Mfg#:31-31-05						Ldg					
313130	**Underwater Locator Beacon Battery (No. 2) - Inspection / Check**							RE (-)			
31 A/F						Mos					
						Hrs					
ATA Ref::31-31-05, Ref#:31-31-05						Ldg					
314117	**Integrated Flight Information System (No. 1) - Operational Test**							RE (-)			
31 A/F						Mos					
						Hrs					
Mfg#:31-41-01						Ldg					
314118	**Integrated Flight Information System (No. 2) - Operational Test**							RE (-)			
31 A/F						Mos					
						Hrs					
Ref#:31-41-01						Ldg					
314119	**Cover and Environmental Module (IPC No. 1) - Operational Test**							RE (-)			
31 A/F						Mos					
						Hrs					
Mfg#:31-41-01						Ldg					
314120	**Cover and Environmental Module (IPC No. 2) - Operational Test**							RE (-)			
31 A/F						Mos					
						Hrs					
Ref#:31-41-01						Ldg					
314121	**Cover and Environmental Module (IPC No. 3) - Operational Test**							RE (-)			
31 A/F						Mos					
						Hrs					
Ref#:31-41-01						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
315120	**Cover and Environmental Module (DCU No. 1) - Operational Test**							RE (-)			
31 A/F						Mos					
						Hrs					
Mfg#:31-51-01-AT						Ldg					
315121	**Data Concentration Unit (No. 1) - Operational Test**							RE (-)			
31 A/F						Mos					
						Hrs					
Ref#:31-51-01-AT						Ldg					
315122	**Cover and Environmental Module (DCU No. 2) - Operational Test**							RE (-)			
31 A/F						Mos					
						Hrs					
Ref#:31-51-01-AT						Ldg					
315123	**Data Concentration Unit (No. 2) - Operational Test**							RE (-)			
31 A/F						Mos					
						Hrs					
Ref#:31-51-01-AT						Ldg					
315160	**Engine Indicating and Crew Alerting System - Operational Test**							RE (-)			
31 A/F						Mos					
						Hrs					
Mfg#:31-51-01-AT						Ldg					
315305	**Master Warning / Caution Panel - Operational Test**							RE (-)			
31 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:31-53-01						Ldg	10				
316001	**Central Display Sytem - Operational Test**							RE (-)			
31 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:31-60-00						Ldg	10				
316005	**Standby Multifunction Controller (No. 1) - Operational Test**							RE (-)			
31 A/F						Mos					
						Hrs					
Ref#:31-60-00						Ldg					
316006	**Standby Multifunction Controller (No. 2) - Operational Test**							RE (-)			
31 A/F						Mos					
						Hrs					
Ref#:31-60-00						Ldg					
316327	**Cursor Control Device - Operational Test**							RE (-)			
31 A/F						Mos					
						Hrs					
						Ldg					
316328	**Central Display System - Operational Test**							RE (-)			
31 A/F						Mos					
						Hrs					
						Ldg					
280-32-025 Rev 1	**Landing Gear - Wheels And Brakes - Park / Emergency Brake Cable Replacement (MODG25-00122)**							RE (-)		Recommended	
32 A/F						Mos	10-Feb-2023				
Eff: 13-Sep-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-32-030	**Landing Gear - Main Landing Gear (MLG) - Inboard And Outboard Harness - Improve Routing (MODG25-00235)**							RE (-)		Recommended	
32 A/F						Mos	10-Feb-2023				
Eff: 13-Sep-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-32-045	**Landing Gear - Main Landing Gear (MLG) - Inboard Door Mechanism Lower Rod Replacement (MODG25-20019)**							RE (-)		Recommended	
32 A/F						Mos	10-Feb-2023				
Eff: 14-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-32-048	**Landing Gear - Main Landing Gear (MLG) - Shock Strut Replacement (MODG25- 10023)**							RE (-)		Recommended	
32 A/F						Mos	10-Feb-2023				
Eff: 14-Nov-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-32-064	**Landing Gear - Extension and Retraction - NLG Actuator - Inspection Of Rod End Securing Washer (MODG25-00393)**							RE (-)		Recommended	
32 A/F						Mos	10-Feb-2023				
Eff: 13-Dec-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-32-169	**Landing Gear - Main Landing Gear (MLG) - Improved Routing And Support Of MLG Door Uplock Harness (MODG25-07182)**							RE (-)		Recommended	
32 A/F						Mos	10-Feb-2023				
Eff: 15-Nov-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-32-170	**Landing Gear - Main Landing Gear (MLG) - Harness Routing Modification (MODG25- 00903)**							RE (-)		Recommended	
32 A/F						Mos	10-Feb-2023				
Eff: 30-Oct-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-32-190	**Landing Gear - Modification Of Upper Jury Brace On NLG Brace Assembly (MODG25-20091)**							RE (-)		Recommended	
32 A/F						Mos	10-Feb-2023				
Eff: 14-Nov-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-32-202	**Landing Gear - Nose Landing Gear (NLG) - Downlock Springs Replacement (MODG25-00995)**							RE (-)		Mandatory	
32 A/F						Mos	10-Feb-2023				
Eff: 15-Jan-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-32-225	**Nose Landing Gear (NLG) – Modifying NLG Gear Up Hose Installation to Prevent Close Proximity with Structure**							RE (-)		Recommended	
32 A/F						Mos	10-Feb-2023				
Eff: 11-Apr-2018 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 12)						Ldg	7				
280-32-228	**Landing Gear - Nose Landing Gear - Electrical Harness Routing Improvement (MODG25-01355)**							RE (-)		Recommended	
32 A/F						Mos	10-Feb-2023				
Eff: 22-Aug-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-32-279	**Landing Gear - Nose Landing Gear Wheel Well - Dual Parking Brake Valve (DPBV) Replacement**							RE (-)		Recommended	
32 A/F						Mos	10-Feb-2023				
Eff: 09-Apr-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 4)						Ldg	7				
320001	**Landing Gear - Functional Test**							RE (-)			
32 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:32-00-00-AT						Ldg	10				
320002	**Landing Gear Cycling - Operational Test**							RE (-)			
32 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:32-00-00-AT						Ldg	10				
321113	**Main Landing Gear Shock Absorber (Left) - Repack**							RE (-)			
32 A/F						Mos					
						Hrs					
Mfg#:32-11-02-SE						Ldg					
321114	**Main Landing Gear Shock Absorber (Right) - Repack**							RE (-)			
32 A/F						Mos					
						Hrs					
Mfg#:32-11-02-SE						Ldg					
321301	**Main Landing Gear Inboard Door (Left) - Adjustment**							RE (-)			
32 A/F						Mos					
						Hrs					
Mfg#:32-13-00-AT						Ldg					
321302	**Main Landing Gear Inboard Door (Right) - Adjustment**							RE (-)			
32 A/F						Mos					
						Hrs					
Mfg#:32-13-00-AT						Ldg					
321303	**Main Landing Gear Outboard Door (Left) - Adjustment**							RE (-)			
32 A/F						Mos					
						Hrs					
Mfg#:32-13-00-AT						Ldg					
321304	**Main Landing Gear Outboard Door (Right) - Adjustment**							RE (-)			
32 A/F						Mos					
						Hrs					
Mfg#:32-13-00-AT						Ldg					
322103	**Nose Landing Gear Shock Strut - Functional Test**							RE (-)			
32 A/F						Mos					
						Hrs					
Mfg#:32-21-01						Ldg					
322105	**Nose Landing Gear Shock Strut - Repack**							RE (-)			
32 A/F						Mos					
						Hrs					
Mfg#:32-21-01-SE						Ldg					
322205	**Nose Landing Gear Forward Doors - Adjustment**							RE (-)			
32 A/F						Mos					
						Hrs					
Mfg#:32-22-01						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
322209	**Nose Landing Gear Aft Door - Adjustment**							RE (-)			
32 A/F						Mos					
						Hrs					
Mfg#:32-22-02						Ldg					
323309	**Nose Landing Gear Uplock Assembly - Adjustment**							RE (-)			
32 A/F						Mos					
						Hrs					
Mfg#:32-33-03						Ldg					
323402	**Emergency Landing Gear Pressure Vessel - Servicing**							RE (-)			
32 A/F						Mos					
						Hrs					
Mfg#:32-34-01						Ldg					
323406	**Emergency Landing Gear Pressure Vessel - Restore**							RE (-)	05-10-00 Time Limits, 05-10-10 Life Limited Components		
32 A/F						Mos					
31-Mar-2022						Hrs					
	ATA Ref:32-34-01, MRB Ref:32-30-00/07 (SOURCE: G280 AMM) (NOTE: See Life Limited Components, 05-10-10, Airworthiness Limitations Section P/N G280-1001-3-2. Pacific Scientific (P/N 41004664-2) and GAC / IAI (P/N 30P716016001-501) every 3 years. Accomplish hydrostatic functional check at 3 years. The count for hydrostatic test shall commence every 3 years from date of last hydrostatic test inspection or original hydrostatic test date.)					Ldg					
324401	**Brake System - Bleeding**							RE (-)			
32 A/F						Mos					
						Hrs					
Mfg#:32-44-00						Ldg					
324402	**Brake System - Operational Check**							RE (-)			
32 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:32-44-00						Ldg	10				
324403	**Pressure Transducer - Operational Test**							RE (-)			
32 A/F						Mos					
						Hrs					
Mfg#:32-44-00						Ldg					
324459	**Autobrake System - Functional Test**							RE (-)			
32 A/F						Mos					
						Hrs					
Mfg#:32-44-11						Ldg					
324501	**Parking / Emergency Brake - Operational Test**							RE (-)			
32 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:32-45-00						Ldg	10				
324507	**Park / Emergency Brake Accumulator (Left) - Operational Test**							RE (-)			
32 A/F						Mos					
						Hrs					
Mfg#:32-45-01						Ldg					
324508	**Park / Emergency Brake Accumulator (Right) - Operational Test**							RE (-)			
32 A/F						Mos					
						Hrs					
Mfg#:32-45-01						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
324611		**Antiskid Sytem - Operational Test**							RE (-)			
	32 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:32-46-00-AT						Ldg	10				
324612		**Locked Wheel Protection Test - Operational Test**							RE (-)			
	32 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:32-46-00-AT						Ldg	10				
324613		**Touchdown Protection - Functional Test**							RE (-)			
	32 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:32-46-00-AT						Ldg	10				
325002		**Nose Wheel Steering - Functional Test**							RE (-)			
	32 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:32-50-00						Ldg	10				
325105		**Nose Wheel Steering Control Handle - Functional Test**							RE (-)			
	32 A/F						Mos					
							Hrs					
	Mfg#:32-51-01						Ldg					
325207		**Feedback Potentiometers - Adjustment**							RE (-)			
	32 A/F						Mos					
							Hrs					
	Mfg#:32-52-05						Ldg					
326002		**Landing Gear Indication - Functional Test**							RE (-)			
	32 A/F						Mos					
							Hrs					
	Mfg#:32-60-00						Ldg					
326105		**Main Landing Gear Downlock Switch (Left) - Adjustment**							RE (-)			
	32 A/F						Mos					
							Hrs					
	Mfg#:32-61-01						Ldg					
326106		**Main Landing Gear Downlock Switch (Right) - Adjustment**							RE (-)			
	32 A/F						Mos					
							Hrs					
	Mfg#:32-61-01						Ldg					
326107		**Nose Landing Gear Downlock Switch - Adjustment**							RE (-)			
	32 A/F						Mos					
							Hrs					
	Mfg#:32-61-02						Ldg					
326205		**Main Landing Gear Uplock Switch (Left) - Adjustment**							RE (-)			
	32 A/F						Mos					
							Hrs					
	Mfg#:32-62-01						Ldg					
326206		**Main Landing Gear Uplock Switch (Right) - Adjustment**							RE (-)			
	32 A/F						Mos					
							Hrs					
	Mfg#:32-62-01						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
326209		**Nose Landing Gear Uplock Switch - Adjustment**							RE (-)			
32 A/F							Mos					
							Hrs					
	Mfg#:32-62-02						Ldg					
326301		**Thrust Reverser Weight on Wheels Switch - Adjustment**							RE (-)			
32 A/F							Mos					
							Hrs					
	Mfg#:32-63-02-AT						Ldg					
326302		**Weight on Wheels Switches - Operational Test**							RE (-)			
32 A/F							Mos					
							Hrs					
	Mfg#:32-63-00						Ldg					
326303		**Main Landing Gear Weight on Wheels (Left Outboard) - Adjustment**							RE (-)			
32 A/F							Mos					
							Hrs					
	Mfg#:32-63-01						Ldg					
326304		**Main Landing Gear Weight on Wheels (Left Inboard) - Adjustment**							RE (-)			
32 A/F							Mos					
							Hrs					
	Mfg#:32-63-01						Ldg					
326305		**Main Landing Gear Weight on Wheels (Right Inboard) - Adjustment**							RE (-)			
32 A/F							Mos					
							Hrs					
	Mfg#:32-63-01						Ldg					
326306		**Main Landing Gear Weight on Wheels (Right Outboard) - Adjustment**							RE (-)			
32 A/F							Mos					
							Hrs					
	Mfg#:32-63-01						Ldg					
326307		**Nose Landing Gear Weight on Wheels Switch (Left) - Adjustment**							RE (-)			
32 A/F							Mos					
							Hrs					
	Mfg#:32-63-02-AT						Ldg					
326308		**Nose Landing Gear Weight on Wheels Switch (Right) - Adjustment**							RE (-)			
32 A/F							Mos					
							Hrs					
	Mfg#:32-63-02-AT						Ldg					
326403		**Nose Wheel Oversteer - Operational Test**							RE (-)			
32 A/F							Mos					
							Hrs					
	Mfg#:32-64-01						Ldg					
326404		**Nose Wheel Steering Limit Switch - Adjustment**							RE (-)			
32 A/F							Mos					
							Hrs					
	Mfg#:32-64-02						Ldg					
326410		**Nose Wheel Steering Proximity Switch - Adjustment**							RE (-)			
32 A/F							Mos					
							Hrs					
	Mfg#:32-64-02						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-33-121 Rev 1	**Lights - Strobe Light - Addition Of Cap To Receptacle 57L (MODG25-00590)**							RE (-)		Recommended	
33 A/F						Mos	10-Feb-2023				
Eff: 14-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
331121	**Instrument Lights - Operational Test**							RE (-)			
33 A/F						Mos	20-Apr-2023				
						Hrs	124:16				
ATA Ref::33-11-00, Mfg#:33-11-00						Ldg	71				
331122	**Map, Dome and Step Lights - Operational Test**							RE (-)			
33 A/F						Mos					
						Hrs					
ATA Ref::33-11-00, Mfg#:33-11-00						Ldg					
332001	**Airstair Lights - Operational Check**							RE (-)			
33 A/F						Mos					
						Hrs					
ATA Ref::33-11-05, Mfg#:33-20-00						Ldg					
333001	**Baggage Compartment Lights - Operational Test**							RE (-)			
33 A/F						Mos					
						Hrs					
ATA Ref::33-30-00, Mfg#:33-30-00						Ldg					
333011	**Service Panel Lights - Operational Test**							RE (-)			
33 A/F						Mos					
						Hrs					
Mfg#:33-30-00						Ldg					
334021	**Landing Lights - Operational Test**							RE (-)			
33 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:33-40-00-AT						Ldg	10				
334022	**Taxi Lights - Operational Test**							RE (-)			
33 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:33-40-00-AT						Ldg	10				
334031	**Wing Ice Inspection and Logo Lights - Operational Test**							RE (-)			
33 A/F						Mos					
						Hrs					
Mfg#:33-40-00-AT						Ldg					
334041	**Tail Beacon / Recognition Light - Operational Test**							RE (-)			
33 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:33-40-00-AT						Ldg	10				
334105	**Taxi Light - Lamp Replacement**							RE (-)			
33 A/F					4	Mos	13-Dec-2022				
						Hrs	21:24				
Mfg#:33-41-01-SE						Ldg	5				
334106	**Taxi Light - Lamp Replacement**							RE (-)			
33 A/F					4	Mos	13-Dec-2022				
						Hrs	21:24				
Mfg#:33-41-01-SE						Ldg	5				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2000-07-27	**Honeywell - Prevent Loss Of Air Data Sources**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	10-Feb-2023				
Not Applicable	NO ADIRU INSTALLED					Hrs	24:24				
						Ldg	7				
2014-05-27	**Rockwell Collins, Inc - Navigation - TPR-720 and TPR-900 Mode S transponders test and calibration**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	10-Feb-2023				
Eff: 02-May-2014 Not Applicable	BY MODEL AND P/N INSTALLED					Hrs	24:24				
Brand A:9990-2014-05-27						Ldg	7				
2020-08-02	**Global Positioning System - Thales GPS/SBAS Receivers**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	10-Feb-2023				
Eff: 19-May-2020 Not Applicable	NOT INSTALLED					Hrs	24:24				
						Ldg	7				
2023-10-02	**Navigation - Radio Altimeters (This AD Replaces AD 2021-23-12)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	10-Aug-2023				
Eff: 26-May-2023 Complied With						Hrs					
(UPDATE NOTE: BY REVISING AFM LIMITATIONS BY REV. 9) (NOTE: APPLICABILITY: This AD applies to all transport and commuter category airplanes equipped with a radio (also known as radar) altimeter. These radio altimeters are installed on various transport and commuter category airplanes including, but not limited to, the airplanes for which the design approval holder is identified in paragraphs (c)(1) through (18) of this AD. (1) The Boeing Company (2) Airbus SAS (3) Bombardier Inc.(4) Embraer S.A. (including type certificates previously held by Yaborã Indústria Aeronáutica S.A., which are now held by Embraer S.A.) (5) Gulfstream Aerospace Corporation (6) Gulfstream Aerospace LP (7) Textron Aviation Inc. (8) Pilatus Aircraft Limited (9) Fokker Services B.V. (10) Saab AB, Support and Services (11) DeHavilland Aircraft of Canada Limited (12) Airbus Canada Limited Partnership (13) ATR–GIE Avions de Transport Régional (14) MHI RJ Aviation ULC (15) BAE Systems (Operations) Limited (16) Lockheed Martin Corporation/Lockheed Martin Aeronautics Company (17) Viking Air Limited (18) Dassault Aviation)					Ldg					
2023-21-05	**Navigation - Thales AVS France SAS Flight Management Computer Navigation Modules (FMC2 NAVM)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	20-Nov-2023				
Eff: 12-Dec-2023 Not Applicable						Hrs					
(UPDATE NOTE: Thales AVS France SAS flight management computer navigation modules (FMC2 NAVM), part number (P/N) C13084CA03 - Not installed on the aircraft)						Ldg					
280-34-018	**Navigation - Reduced Vertical Separation Minimum (RVSM) - Group Approval (MODG25-10024)**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 21-Nov-2012 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-34-029	**Navigation - Flight Environment Data - Improve Conductivity Of Static Ports (MODG25-00279)**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 11-Apr-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-34-093 Rev 1	**Navigation - Flight Management System - (FMS) - Performance Database (PDB) Upload (MODG25-20053)**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 11-Apr-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-34-094	**Navigation - Flight Management System (FMS) - Vspeed Database (VDB) Incorporation Of Software Version 3.2.1 (MODG25-20054)**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 12-Sep-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-34-097 Rev 1	**Navigation - Independent Position Determining - Automatic Dependent Surveillance - Broadcast (ADS-B) - Air Traffic Control (ATC) Transponder (TDR-94D) No. 2 Activation (MODG-00426 , MODG25-00771)**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 17-Apr-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-34-106	**Navigation - Installation of Rockwell Collins Avionics Software Version V3.6 Configuration, Performance and V-Speed Databases - Retrofit (MODG25-10032)**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 15-Dec-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-34-122 Rev 1	**Navigation - Attitude And Direction - MGR-3000 Magnetometer - Extreme Temperature Improvement (MODG25-00607)**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 26-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-34-167	**Navigation - Pitot/Static System - Modification Of Static Port Holes (MODG25-20075)**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 10-Jul-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-34-204	**Navigation - Flight Management System - Cancellation of FMS Predicted Steps Function Activation in the Aircraft Personality Module 3rd Party Option File (MODG25- 20105)**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 27-Apr-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-34-236	**Navigation - Information Management System (IMS-6000) - Software Update**							RE (-)		Recommended	
34 A/F						Mos	19-Apr-2023				
Eff: 02-Oct-2017 Not Applicable	as per A/C S/N					Hrs	124:16				
(AVG MAN HRS: 6)						Ldg	71				
280-34-236 Rev 1	**Navigation - Information Management System (IMS-6000) - Software Update**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 25-Jul-2018 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 6)						Ldg	7				
280-34-239	**Navigation - TSSA-4100 Software Update (MOD G25-20133)**							RE (-)		Recommended	
34 A/F						Mos	19-Apr-2023				
Eff: 10-May-2017 Not Applicable	as per A/C S/N					Hrs	124:16				
						Ldg	71				
280-34-239 Rev 1	**Navigation Systems - Traffic Surveillance System Application (TSSA-4100) - Software Update**							RE (-)		Mandatory	
34 A/F						Mos	10-Feb-2023				
Eff: 20-Dec-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 1.5)						Ldg	7				
280-34-256	**Navigation - Flight Management System (FMS) - Equal Time Point (ETP) Feature Disabling**							RE (-)		Recommended	
34 A/F						Mos	19-Apr-2023				
Eff: 10-Jul-2018 Not Applicable	as per A/C S/N					Hrs	124:16				
(AVG MAN HRS: 3)						Ldg	71				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-34-256 Rev 1	**Navigation - Flight Management System (FMS) - Equal Time Point (ETP) Feature Disabling**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 27-May-2021 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 3)						Ldg	7				
280-34-264	**Common Computing Module (CCM-5110) - Upgrade**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 22-Feb-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 5)						Ldg	7				
280-34-265	**NAV-4500 - Upgrade**							RE (-)		Recommended	
34 A/F						Mos	19-Apr-2023				
Eff: 22-Feb-2019 Not Applicable	as per A/C S/N					Hrs	124:16				
(AVG MAN HRS: 3.5)						Ldg	71				
280-34-265 Rev 1	**NAV-4500 - Upgrade**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 09-May-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 3.5)						Ldg	7				
280-34-266	**NAV-4000 - Upgrade**							RE (-)		Recommended	
34 A/F						Mos	19-Apr-2023				
Eff: 22-Feb-2019 Not Applicable	as per A/C S/N					Hrs	124:16				
(AVG MAN HRS: 3.5)						Ldg	71				
280-34-266 Rev 1	**NAV-4000 - Upgrade**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 09-May-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 3.5)						Ldg	7				
280-34-268	**Navigation - Information Management System (IMS-6000) - Upgrade**							RE (-)		Recommended	
34 A/F						Mos	19-Apr-2023				
Eff: 22-Feb-2019 Not Applicable	as per A/C S/N					Hrs	124:16				
(AVG MAN HRS: 6.5)						Ldg	71				
280-34-268 Rev 1	**Navigation - Information Management System (IMS-6000) - Upgrade**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 12-May-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 6.5)						Ldg	7				
280-34-269	**Digital Switching Module (DSM-5110) - Upgrade**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 22-Feb-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 6)						Ldg	7				
280-34-273	**Navigation (ATA 34) - V3.6.1 Software Upgrade**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 05-May-2021 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 20)						Ldg	7				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-34-292	**Navigation - Enhanced Data Load**							RE (-)		Optional	
34 A/F						Mos					
Eff: 27-May-2021						Hrs					
(AVG MAN HRS: 20)						Ldg					
280-34-293	**Navigation - GPS-4000S No. 1 and No. 2 Replacement P/N 822-2189-100 with P/N 822-2189-101**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 16-Jul-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 4)						Ldg	7				
280-34-295	**Navigation - Weather Radar NVM Reset for RTA-4118**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 09-Apr-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 4)						Ldg	7				
280-34-295 Rev 1	**Navigation - Weather Radar NVM Reset for RTA-4118**							RE (-)		Recommended	
34 A/F						Mos	19-Apr-2023				
Eff: 27-May-2021 Not Applicable	as per A/C S/N					Hrs	124:16				
(AVG MAN HRS: 4)						Ldg	71				
280-34-301	**Navigation - ALT-4000 No. 2, P/N 822-0615-315 Inspection and Replacement**							RE (-)		Recommended	
34 A/F						Mos	10-Feb-2023				
Eff: 29-Oct-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 4)						Ldg	7				
280-34-302	**Navigation - Information Management System (IMS) - IMS-6000 Replacement with IMS-6010**							RE (-)		Optional	
34 A/F						Mos	20-Nov-2023				
Eff: 27-May-2021 Not Applicable						Hrs					
(AVG MAN HRS: 20) (UPDATE NOTE: PER AIRCRAFT SERIAL NUMBER)						Ldg					
280-34-302 Rev 1	**Navigation - Information Management System (IMS) - IMS-6000 Replacement with IMS-6010**							RE (-)		Optional	
34 A/F						Mos	20-Nov-2023				
Eff: 23-Oct-2023 Not Applicable						Hrs					
(AVG MAN HRS: 20) (UPDATE NOTE: PER AIRCRAFT SERIAL NUMBER)						Ldg					
280-34-305	**Navigation - SXM Weather Upgrade**							RE (-)		Optional	
34 A/F						Mos	10-Feb-2023				
Eff: 27-May-2021 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 18)						Ldg	7				
280-34-333	**Navigation - Information Management System (IMS) - IMS-6010 SB 5 Verification**							RE (-)		Recommended	
34 A/F						Mos					
Eff: 02-Aug-2024						Hrs					
(AVG MAN HRS: 4)						Ldg					
341213	**Static Port Flushness - Check**							RE (-)			
34 A/F						Mos					
						Hrs					
Ref#:34-12-02-IC						Ldg					
341303	**Static Air Temperature / Total Air Sensor Probe - Operational Test**							RE (-)			
34 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:34-13-00-AT						Ldg	10				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
341401		**Angle of Attack Probe - Operational Test (Left)**							RE (-)			
	34 A/F						Mos					
							Hrs					
	Ref#:34-14-00						Ldg					
341402		**Angle of Attack Probe - Operational Test (Right)**							RE (-)			
	34 A/F						Mos					
							Hrs					
	Ref#:34-14-00						Ldg					
341410		**Stall Protection System - Operational Test**							RE (-)			
	34 A/F						Mos					
							Hrs					
	Mfg#:34-14-00						Ldg					
342001		**Attitude Heading Reference System - Functional Test**							RE (-)			
	34 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:34-20-00						Ldg	10				
342002		**Attitude Heading Reference System Tray - Alignment**							RE (-)			
	34 A/F						Mos					
							Hrs					
	Mfg#:34-20-00						Ldg					
342728		**Standby Flight Instrument System - Airspeed Test**							RE (-)			
	34 A/F						Mos					
							Hrs					
	Ref#:34-27-00-AT						Ldg					
342729		**Standby Flight Instrument System - Copy Data**							RE (-)			
	34 A/F						Mos					
							Hrs					
	Ref#:34-27-00-MP						Ldg					
342730		**Standby Flight Instrument System - Functional Test**							RE (-)			
	34 A/F						Mos					
							Hrs					
	Ref#:34-27-00-AT						Ldg					
342731		**Standby Flight Instrument System - Calibration**							RE (-)			
	34 A/F						Mos					
							Hrs					
	Mfg#:34-27-00-AT						Ldg					
342733		**Magnetometer - Calibration**							RE (-)			
	34 A/F						Mos					
							Hrs					
	Ref#:34-27-00-AT						Ldg					
342735		**Magnetometer - Swing**							RE (-)			
	34 A/F						Mos					
							Hrs					
	Ref#:34-27-00-AT						Ldg					
344101		**Radio Altimeter - Functional Check**							RE (-)			
	34 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:34-41-00						Ldg	10				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
344201		**Weather Radar - Functional Test**							RE (-)			
	34 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:34-42-00						Ldg	10				
344202		**Weather Radar Receiver / Transmitter / Antenna - Lubrication**							RE (-)			
	34 A/F						Mos					
							Hrs					
	Mfg#:34-42-00						Ldg					
344301		**Terrain Awareness and Warning System - Operational Check**							RE (-)			
	34 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:34-43-00						Ldg	10				
344403		**TCAS - Operational Test**							RE (-)			
	34 A/F						Mos					
							Hrs					
	Ref#:34-44-00-AT						Ldg					
345101		**GPS - Operational Test**							RE (-)			
	34 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:34-51-00						Ldg	10				
345201		**Automatic Direction Finder - Functional Test**							RE (-)			
	34 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:34-52-00						Ldg	10				
345302		**TCAS Transponder Mode S Address Code - Programming**							RE (-)			
	34 A/F						Mos					
							Hrs					
	Mfg#:34-44-00-AT						Ldg					
345401		**Distance Measuring Equipment - Functional Test**							RE (-)			
	34 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:34-54-00						Ldg	10				
346001		**Flight Management System (No.1) - Operational Test**							RE (-)			
	34 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:34-60-00-AT						Ldg	10				
346002		**Flight Management System (No.2)- Operational Test**							RE (-)			
	34 A/F						Mos					
							Hrs					
	Ref#:34-60-00-AT						Ldg					
346003		**Flight Management System (No.3) - Operational Test**							RE (-)			
	34 A/F						Mos					
							Hrs					
	Ref#:34-60-00-AT						Ldg					
346026		**VOR - IFR Check (FAR 91.171)**							RE (-)			
	34 A/F						Days	02-Mar-2023				
							Hrs	34:12				
	(Manual Adjustment: -11d) (NOTE: PreFlight Check)						Ldg	10				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
346027	**Flight Management System - Pilot Defined Database Backup**							RE (-)			
34 A/F						Mos					
						Hrs					
(SOURCE: 34-60-00)						Ldg					
346028	**Flight Management System - Pilot Defined Database Restore**							RE (-)			
34 A/F						Mos					
						Hrs					
(SOURCE: 34-60-00)						Ldg					
346029	**Charts - Subscription Key Entry**							RE (-)			
34 A/F						Mos					
						Hrs					
Ref#:34-60-00-MP (SOURCE: 34-60-00)						Ldg					
CF-2024-14	**Navigation - Aeroplane - Limitations of Operations with Non-Tolerant Radio Altimeter when Operating in Canada due to 5G C-Band Wireless Broadband Interference**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	27-May-2024				
Eff: 29-May-2024 Complied With	AFM updated					Hrs	842:13				
						Ldg	496				
(NOTE: APPLICABILITY: This AD applies to all transport and commuter category aeroplanes equipped with a radio (also known as radar) altimeter. These radio altimeters are installed on various transport and commuter category aeroplanes including, but not limited to, the aeroplanes for which the design approval holder is identified in this AD.)											
STC ST04339AT-D	**Gulfstream Air Ionization System Installation**							RE (-)			
34 A/F						Mos	10-Feb-2023				
Complied With						Hrs	24:24				
						Ldg	7				
2012-11-09 R1	**Chemical Oxygen Generator Installation**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	10-Feb-2023				
Eff: 27-Jul-2015 Not Applicable	NOT INSTALLED					Hrs	24:24				
Brand A:9990-2012-11-09R1						Ldg	7				
2015-08-07	**Zodiac Aerotechnics (formerly Intertechnique Aircraft Systems) - Oxygen - Flightcrew Oxygen Mask Regulators**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	10-Feb-2023				
Eff: 16-Jun-2015 Not Applicable	PER MASK SERIAL NUMBER, REF. APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240 REV. 7					Hrs	24:24				
						Ldg	7				
2017-18-12	**Oxygen - B/E Aerospace Protective Breathing Equipment (PBE) Units, P/N 119003-11 and 119003-21 - Inspect/ Replace (This AD replaces AD 2016-11-20)**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	10-Feb-2023				
Eff: 16-Oct-2017 Not Applicable	NOT INSTALLED					Hrs	24:24				
(AVG MAN HRS: 2)						Ldg	7				
2018-21-14	**MC10 Series Crew Oxygen Mask Regulators - Inflatable Harness Assembly, P/N MXH20-1 or MXH21-1 - Inspection/ Replacement**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	10-Feb-2023				
Eff: 27-Mar-2019 Not Applicable	PER MASK PART NUMBER					Hrs	24:24				
						Ldg	7				
280-35-184	**Oxygen - Enlarge Clearance Between Oxygen Tube And Right Side Forward Radio Rack Structure (MODG25-00966)**							RE (-)		Recommended	
35 A/F						Mos	10-Feb-2023				
Eff: 22-Nov-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
350001	**Oxygen System - Leakage Test**							RE (-)			
35 A/F						Mos	19-Jan-2023				
						Hrs	22:54				
Mfg#:35-00-00						Ldg	6				
350002	**Oxygen System - Purging**							RE (-)			
35 A/F						Mos					
						Hrs					
Mfg#:35-00-00						Ldg					
351111	**Oxygen Pressure Switch - Functional Test**							RE (-)			
35 A/F						Mos					
9H0018-1G 0274						Hrs					
Mfg#:35-11-03						Ldg					
352103	**Passenger Oxygen Controller - Functional Test**							RE (-)			
35 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:35-21-01						Ldg	10				
280-36-143	**Pneumatics - Correct Interference Between Nose ECS System Installation And Structure (MODG25-00689)**							RE (-)		Recommended	
36 A/F						Mos	10-Feb-2023				
Eff: 01-Jun-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
360001	**Bleed Air System - Functional Test**							RE (-)			
36 A/F						Mos					
						Hrs					
Mfg#:36-00-00-AT						Ldg					
361115	**Bleed Air Isolation Valve - Functional Test**							RE (-)			
36 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:36-11-04						Ldg	10				
361116	**Bleed Air Ducts - Leakage Test**							RE (-)			
36 A/F						Mos					
						Hrs					
Mfg#:36-11-00-AT						Ldg					
280-38-086	**Water/Waste System - System Heater Control Module (SHCM), Water Control Unit (WLS) And Potable Water Pump (PWP) Replacement (MODG25-20048, G25-20049 G25-20055 , G25-20070)**							RE (-)		Recommended	
38 A/F						Mos	10-Feb-2023				
Eff: 21-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-38-281	**Potable Water Tank Fill Nozzle Circlip Inspection and Replacement**							RE (-)		Recommended	
38 A/F						Mos	10-Feb-2023				
Eff: 16-Jul-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 4)						Ldg	7				
280-38-294	**Water/Waste System - Waste Tank Rinse Nozzle Reinforcement**							RE (-)		Recommended	
38 A/F						Mos	10-Feb-2023				
Eff: 18-Mar-2021 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 8.5)						Ldg	7				

Task No / SEQ	Description / PN/SN / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
380003	**Water / Waste System Heating Control Module - Functional Test**							RE (-)			
38 A/F						Mos					
						Hrs					
	Mfg#:38-00-01					Ldg					
381001	**Potable Water System - Operational Test**							RE (-)			
38 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
	ATA Ref::38-10-00, Mfg#:38-10-00					Ldg	10				
381002	**Potable Water System - Leakage Test**							RE (-)			
38 A/F						Mos					
						Hrs					
	ATA Ref::38-10-00, Mfg#:38-10-00					Ldg					
383001	**Waste System - Operational Test**							RE (-)			
38 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
	Mfg#:38-30-00					Ldg	10				
383002	**Waste System - Leakage Test**							RE (-)			
38 A/F						Mos					
						Hrs					
	Mfg#:38-30-00					Ldg					
G25-20206	**G25-20206, Modification**							RE (-)			
38 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
CE-CSB-2014	**Cabin Systems (ATA 44) Advanced Cabin Server (ACS) (Gen 4) Cabinview Software Upgrade V2.2.3**							RE (-)		Cabin Service Bulletin	
44 A/F						Mos					
Eff: 03-Dec-2019						Hrs					
(AVG MAN HRS: 2)						Ldg					
CSB 021	**Cabin Systems - Advanced Cabin Server (ACS) (Gen 4) / Cabin Processor Unit (CPU) (GEN 5) Cabin View Software Update**							RE (-)		Cabin Service Bulletin, Recommended	
44 A/F						Mos	14-Apr-2023				
Eff: 06-Jul-2022 Not Applicable	by aircraft S/N					Hrs	112:17				
(AVG MAN HRS: 4)						Ldg	61				
450001	**Onboard Maintenance System - Data Backup**							RE (-)			
45 A/F						Mos					
						Hrs					
	Mfg#:45-00-00					Ldg					
457602	**Engine / Electronic Control Unit - Initialization**							RE (-)			
45 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
	Mfg#:45-76-00					Ldg	10				
280-46-041	**Information Systems - Electronic Checklist (ECL) Database Update (MODG25-10035)**							RE (-)		Recommended	
46 A/F						Mos	10-Feb-2023				
Eff: 11-Apr-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-46-316	**Information Systems (ATA 46) - Information Management System (IMS) - IMS-6010 Software Update**							RE (-)		Optional	
46 A/F						Mos					
Eff: 10-Feb-2023						Hrs					
(AVG MAN HRS: 2)						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
463101	**Information Management System - Operational Test**							RE (-)			
46 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:46-31-00						Ldg	10				
463104	**Information Management System Unit - Load Operation System**							RE (-)			
46 A/F						Mos					
						Hrs					
(SOURCE: 46-00-00)						Ldg					
463109	**Adaptive Flight Display - Reload Software**							RE (-)			
46 A/F						Mos					
						Hrs					
						Ldg					
463112	**Data Concentration Module Channel A (DCU No. 1) - Reload Software**							RE (-)			
46 A/F						Mos					
						Hrs					
Ref#:46-00-00-MP						Ldg					
463113	**Data Concentration Module Channel A (DCU No. 2) - Reload Software**							RE (-)			
46 A/F						Mos					
						Hrs					
Ref#:46-00-00-MP						Ldg					
463114	**Data Concentration Module Channel B (DCU No. 1) - Reload Software**							RE (-)			
46 A/F						Mos					
						Hrs					
Ref#:46-00-00-MP						Ldg					
463115	**Data Concentration Module Channel B (DCU No. 2) - Reload Software**							RE (-)			
46 A/F						Mos					
						Hrs					
Ref#:46-00-00-MP						Ldg					
463116	**Digital Switching Module (No. 1) - Reload Software**							RE (-)			
46 A/F						Mos					
						Hrs					
ATA Ref::46-00-00, Ref#:46-00-00-MP						Ldg					
463117	**Digital Switching Module (No. 2) - Reload Software**							RE (-)			
46 A/F						Mos					
						Hrs					
ATA Ref::46-00-00, Ref#:46-00-00-MP						Ldg					
463118	**Digital Switching Module (No. 3) - Reload Software**							RE (-)			
46 A/F						Mos					
						Hrs					
ATA Ref::46-00-00, Ref#:46-00-00-MP						Ldg					
463119	**Flight Management System (No. 1) - Reload Software**							RE (-)			
46 A/F						Mos					
						Hrs					
46-00-00:ATA Ref:, Ref#:46-00-00-MP						Ldg					
463120	**Flight Management System (No. 2) - Reload Software**							RE (-)			
46 A/F						Mos					
						Hrs					
ATA Ref::46-00-00, Ref#:46-00-00-MP						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
463121		**Flight Management System (No. 3) - Reload Software**							RE (-)			
	46 A/F						Mos					
							Hrs					
		ATA Ref::46-00-00, Ref#:46-00-00-MP					Ldg					
463122		**Integrated Flight Information Systems (No. 1) - Reload Software**							RE (-)			
	46 A/F						Mos					
							Hrs					
		ATA Ref::46-00-00, Ref#:46-00-00-MP					Ldg					
463123		**Integrated Flight Information Systems (No. 2) - Reload Software**							RE (-)			
	46 A/F						Mos					
							Hrs					
		ATA Ref::46-00-00, Ref#:46-00-00-MP					Ldg					
463124		**Onboard Maintenance System - Reload Software**							RE (-)			
	46 A/F						Mos					
							Hrs					
		ATA Ref::46-00-00, Ref#:46-00-00-MP					Ldg					
463125		**Terrain Awareness and Warning System - Reload Software**							RE (-)			
	46 A/F						Mos					
							Hrs					
		Ref#:46-00-00-MP (SOURCE: 46-00-00)					Ldg					
463126		**Data Concentration Unit Aircraft Personality Module (Left) - Update Configuration Files**							RE (-)			
	46 A/F						Mos					
							Hrs					
		Ref#:46-00-00-MP					Ldg					
463127		**Data Concentration Unit Aircraft Personality Module (Right) - Update Configuration Files**							RE (-)			
	46 A/F						Mos					
							Hrs					
		Ref#:46-00-00-MP					Ldg					
463130		**Display Control Panel (No. 1) - Field Load Software**							RE (-)			
	46 A/F						Mos					
							Hrs					
		(SOURCE: 46-00-00)					Ldg					
463131		**Display Control Panel (No. 2) - Field Load Software**							RE (-)			
	46 A/F						Mos					
							Hrs					
		Ref#:46-00-00-MP (SOURCE: 46-00-00)					Ldg					
463132		**Standby Flight Information System - Field Load Software (Avionics Version 3.6 and Above)**							RE (-)			
	46 A/F						Mos					
							Hrs					
		(SOURCE: 46-00-00)					Ldg					
463133		**Traffic Surveillance System - Field Load Software (Avionics Version 3.6 and Above)**							RE (-)			
	46 A/F						Mos					
							Hrs					
		(SOURCE: 46-00-00)					Ldg					
463140		**Information Management System Unit - Restore Mediasets**							RE (-)			
	46 A/F						Mos					
							Hrs					
		Ref#:46-00-00-MP					Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
463145	**Integrated Modular Avionics Application - Software Load Verification**							RE (-)			
46 A/F						Mos					
						Hrs					
Ref#:46-00-00-MP						Ldg					
463146	**Data Concentration Unit Aircraft Personality Module (Left) - Enter Electronic Activation Keys**							RE (-)			
46 A/F						Mos					
						Hrs					
Ref#:46-00-00						Ldg					
463147	**Data Concentration Unit Aircraft Personality Module (Right) - Enter Electronic Activation Keys**							RE (-)			
46 A/F						Mos					
						Hrs					
Ref#:46-00-00						Ldg					
280-49-249	**Airborne Auxiliary Power - Firewall - Frame 64 Assembly and Structure Sealing (MODG25-01543)**							RE (-)		Recommended	
49 A/F						Mos	10-Feb-2023				
Eff: 06-Sep-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
3822101-49-8148	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, P/N 3822101-1, on Multiple APU's**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 10-Jul-2015 Not Applicable	as per compressor rotor P/N					Hrs					
						APUS					
3822101-49-8148 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, P/N 3822101-1, on Multiple APU's**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 10-Jan-2017 Not Applicable	as per compressor rotor P/N					Hrs					
						APUS					
3822632-49-8146	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 3822632-1, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 02-Jul-2015 Not Applicable	as per compressor rotor P/N					Hrs					
						APUS					
3822632-49-8146 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 3822632-1, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 24-Jul-2015 Not Applicable	as per compressor rotor P/N					Hrs					
						APUS					
3822632-49-8146 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 3822632-1, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 31-Aug-2015 Not Applicable	as per compressor rotor P/N					Hrs					
						APUS					
3822632-49-8146 Rev 3	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 3822632-1, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 25-Oct-2016 Not Applicable	as per compressor rotor P/N					Hrs					
						APUS					
3842064-49-8193	**AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Balance Repair of the Turbine Rotors PN 3842064-1 and PN 3842064-5 on Multiple Auxiliary Power Units (APUs)**							RE (-)	Recommended, Service Bulletin		
49 APU1						Mos	17-Apr-2023				
Eff: 23-Feb-2017 Not Applicable	Turbine rotor P/N not installed					Hrs					
						APUS					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
490003	**APU - Operational Check**							RE (-)			
49 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:49-00-00						Ldg	10				
490004	**APU - Deactivation / Activation Procedure**							RE (-)			
49 APU1						Mos	20-Oct-2023				
						Hrs					
Mfg#:49-00-00-MP						APUS					
490011	**APU Engine Build-Up Configuration**							RE (-)			
49 APU1						Mos					
						Hrs					
Mfg#:49-00-00-RI						APUS					
491111	**APU Upper Link - Adjustment**							RE (-)			
49 APU1						Mos					
						Hrs					
Mfg#:49-11-01-AT						APUS					
495102	**APU Air Inlet Door Actuator - Adjustment**							RE (-)			
49 A/F						Mos					
						Hrs					
Mfg#:49-51-02						Ldg					
49-7933 Rev 6	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**							RE (-)		Service Bulletin	
49 APU1						Mos					
						Hrs					
						APUS					
49-7997	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							RE (-)		Service Bulletin	
49 APU1						Mos	09-Apr-2024				
Eff: 16-Sep-2009 Complied With						Hrs	443				
						APUS	626				
49-7997 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							RE (-)		Service Bulletin	
49 APU1						Mos					
Eff: 11-Feb-2010						Hrs					
						APUS					
49-7997 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							RE (-)		Service Bulletin	
49 APU1						Mos					
Eff: 22-Dec-2010						Hrs					
						APUS					
49-7997 Rev 3	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							RE (-)		Service Bulletin	
49 APU1						Mos					
Eff: 16-Jan-2014						Hrs					
						APUS					
499203	**Auxiliary Power Unit Oil Filter - Discard**							RE (-)			
49 APU1						Mos	09-Apr-2024				
3608765-1 NSN						Hrs	443				
						APUS	626				
Mfg#:49-92-01											
70721597-49-8166	**Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 02-Jul-2015 Not Applicable	as per rotor P/N					Hrs					
						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
70721597-49-8166 Rev 1	**Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 31-Aug-2015 Not Applicable	as per rotor P/N					Hrs					
						APUS					
70721597-49-8166 Rev 2	**Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 25-Oct-2016 Not Applicable	as per rotor P/N					Hrs					
						APUS					
70721598-49-8168	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 02-Jul-2015 Not Applicable	before manufacture					Hrs					
						APUS					
70721725-49-8152	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 27-May-2015 Not Applicable						Hrs					
						APUS					
APU 1	**Honeywell - GTCP36-150 [IAI]**							RE (-)			
49 A/F						Mos	24-Apr-2024				
3800710-3 P-362	Time at install: 443 Hrs, 626 APUS					Hrs	778:25				
						Ldg	454				
APU-41	**PRECAUTIONARY MEASURES TO PREVENT EXCESSIVE AXIAL LOADING OF APUGENERATOR OUTPUT SHAFT SEALS AND BEARINGS**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 05-May-1989						Hrs					
						APUS					
APU-7	**Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 03-Mar-1988						Hrs					
						APUS					
APU-7 Rev 1	**Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 03-Mar-1988						Hrs					
						APUS					
APU-78	**Auxiliary Power Unit (APU) Operational Instructions**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 05-Aug-2003						Hrs					
						APUS					
APU-78 Rev 1	**Auxiliary Power Unit (APU) Operational Instructions**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 30-Sep-2004						Hrs					
						APUS					
APU-83	**SPOTLIGHT TROUBLESHOOTING SYSTEM**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 24-Dec-2003						Hrs					
						APUS					
APU-83 Rev 1	**SPOTLIGHT TROUBLESHOOTING SYSTEM**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 31-Jan-2007						Hrs					
						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
D201012000013	**General Handling Information for Ignition Exciters Containing the Radioactive Element Krypton-85(Krypton 85) Above 10,000 Becquerels**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 08-Mar-2011						Hrs					
						APUS					
D201112000050	**Acceptance Criteria for On-Wing Borescope Inspections**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 13-Jan-2012						Hrs					
						APUS					
GTCP36-49-8096 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Replace the Fuel Supply Tube Assembly PN 3882732-1 with PN 3882732-2**							RE (-)		Recommended, Service Bulletin	
49 APU1						Mos	14-Apr-2023				
Eff: 24-Sep-2015 Not Applicable	as per APU S/N					Hrs					
						APUS					
GTCP36-49-8332	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Ring Gear, PN 3860331-1 with Ring Gear PN 3860331-2 on Affected APU Models**							RE (-)		Mandatory	
49 APU1						Mos	17-Apr-2023				
Eff: 31-Jul-2020 Not Applicable	per APU P/N					Hrs					
						APUS					
SIL APU-152	**Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 18-Jul-2008						Hrs					
						APUS					
SIL APU-152 Rev 1	**Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 24-Jul-2009						Hrs					
						APUS					
SIL APU-152 Rev 2	**Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 30-Nov-2010						Hrs					
						APUS					
SIL APU-152 Rev 3	**Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 19-Feb-2015						Hrs					
						APUS					
SIL D201701000026	**Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine Worksheet for 36-100, 36-150, RE100, and RE220 APUs**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 30-Jan-2017						Hrs					
						APUS					
SIL No. APU-49 Rev 10	**Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)**							RE (-)		Service Information Letter	
49 APU1						Mos					
						Hrs					
(NOTE: COMPLIANCE: Every Aircraft 'A' check or every 500 APU hours or per AMM or MM criteria (customer option).)						APUS					
SIL No. APU-49 Rev 11	**Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units(APUs)**							RE (-)		Service Information Letter	
49 APU1						Mos					
						Hrs					
(NOTE: Analyst/operator will need to manually set the calendar start. COMPLIANCE: Every Aircraft 'A' check or every 500 APU hours or per AMM or MM criteria (customer option).)						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
SIL No. APU-49 Rev 12	**Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)**							RE (-)		Service Information Letter	
49 APU1						Mos					
						Hrs					
(NOTE: COMPLIANCE: First and subsequent oil and filter sample. Every Aircraft 'A' check or every 500 APU hours or per AMM or MM criteria (customer option).)						APUS					
510013	**Exterior Metallic Surfaces - Polishing**							RE (-)			
51 A/F						Mos					
						Hrs					
Ref#:51-00-00-MP						Ldg					
280-52-027	**Doors Replacement Of The Existing Door Locks With New Door Locks On Aft Fuselage Service Door, Waste System Service Door And Air Turbine Starter (ATS) Door (MODG25-00172)**							RE (-)		Recommended	
52 A/F						Mos	10-Feb-2023				
Eff: 31-Jan-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-52-034	**Doors - Baggage Door Mechanism - Replacement Of The Existing Track Rollers With Improved Track Rollers (MODG25-00496)**							RE (-)		Recommended	
52 A/F						Mos	10-Feb-2023				
Eff: 12-Dec-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-52-039	**Doors - Auxiliary Bulkhead Door Lock Mechanism - Addition Of Arm Stopper (MODG25-00217)**							RE (-)		Recommended	
52 A/F						Mos	10-Feb-2023				
Eff: 05-Mar-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-52-090	**Doors - Waste Panel Door Assembly Rework (MODG25-00450)**							RE (-)		Recommended	
52 A/F						Mos	10-Feb-2023				
Eff: 21-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-52-103	**Doors - Main Entrance Door - Door Holder Mechanism Spring - Inspection And Replacement (MODG25-00439)**							RE (-)		Recommended	
52 A/F						Mos	10-Feb-2023				
Eff: 12-Dec-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-52-116 Rev 1	**Doors - Fuselage Fairing Doors - Wing Tank Drain Valve Door Hinge Rework (MODG25-00579)**							RE (-)		Recommended	
52 A/F						Mos	10-Feb-2023				
Eff: 26-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-52-126 Rev 1	**Doors - Auxiliary Bulkhead Door Lock Mechanism - D-Ring And Bolt Replacement (MODG25-00619)**							RE (-)		Recommended	
52 A/F						Mos	10-Feb-2023				
Eff: 05-Mar-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-52-136	**Doors - APU Door - Door Latch Installation Inspection**							RE (-)		Recommended	
52 A/F						Mos	10-Feb-2023				
Eff: 30-May-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-52-137	**Doors - Air Turbine Starter (ATS) Door - Contour - Rework (MODG25-00671)**							RE (-)		Recommended	
52 A/F						Mos	10-Feb-2023				
Eff: 25-Sep-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-52-139	**Doors - Emergency Exit Door - Inspection Of Brackets, P/N 30P332003600-001 (MODG25-00397)**							RE (-)		Recommended	
52 A/F						Mos	10-Feb-2023				
Eff: 15-Nov-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-52-163	**Doors - Exterior Door Locks Rework (MODG25-00847 , G25-01342)**							RE (-)		Optional	
52 A/F						Mos					
Eff: 06-Apr-2016						Hrs					
						Ldg					
280-52-319	**Doors - Main Entrance Door - Door Safety and Door Close Switches and Connectors - Replacement**							RE (-)		Recommended	
52 A/F						Mos	10-Feb-2023				
Eff: 10-Aug-2022 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 60)						Ldg	7				
521001	**Main Entrance Door Position - Alignment / Adjustment**							RE (-)			
52 A/F						Mos					
						Hrs					
Mfg#:52-10-00-AT						Ldg					
521002	**Main Entrance Door Opening - Test**							RE (-)			
52 A/F						Mos					
						Hrs					
Mfg#:52-10-00-AT						Ldg					
521003	**Main Entrance Door Closing - Test**							RE (-)			
52 A/F						Mos					
						Hrs					
Mfg#:52-10-00-AT						Ldg					
521004	**Main Entrance Door - Functional Test**							RE (-)			
52 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:52-10-00-AT						Ldg	10				
521005	**Main Entrance Door Hold Mechanism - Adjustment**							RE (-)			
52 A/F						Mos					
						Hrs					
Ref#:52-10-00-AT						Ldg					
521301	**Main Entrance Door Outer Operating Handle Stirrup - Test**							RE (-)			
52 A/F						Mos					
						Hrs					
Mfg#:52-13-01-AT						Ldg					
521302	**Main Entrance Door Outer Operating Handle - Test**							RE (-)			
52 A/F						Mos					
						Hrs					
Mfg#:52-13-01-AT						Ldg					
521303	**Main Entrance Door Inner Operating Handle Stirrup - Test**							RE (-)			
52 A/F						Mos					
						Hrs					
Mfg#:52-13-01-AT						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
521304		**Main Entrance Door Inner Operating Handle - Test**							RE (-)			
52 A/F							Mos					
							Hrs					
	Mfg#:52-13-01-AT						Ldg					
521305		**Main Entrance Door Handrail - Check**							RE (-)			
52 A/F							Mos					
							Hrs					
	Mfg#:52-13-01-AT						Ldg					
521306		**Main Entrance Door Handles Interlock Latch - Test**							RE (-)			
52 A/F							Mos					
							Hrs					
	Mfg#:52-13-02						Ldg					
521307		**Main Entrance Door Pressure Plate - Test**							RE (-)			
52 A/F							Mos					
							Hrs					
	Mfg#:52-13-02						Ldg					
521308		**Main Entrance Door Flapper - Test**							RE (-)			
52 A/F							Mos					
							Hrs					
	Mfg#:52-13-02						Ldg					
521309		**Main Entrance Door Side Stops - Test**							RE (-)			
52 A/F							Mos					
							Hrs					
	Mfg#:52-13-03-AT						Ldg					
521310		**Main Entrance Door Locking Cams - Test**							RE (-)			
52 A/F							Mos					
							Hrs					
	Mfg#:52-13-04						Ldg					
521329		**Main Entrance Door Telescoping Rods - Test**							RE (-)			
52 A/F							Mos					
							Hrs					
	Mfg#:52-13-07						Ldg					
522104		**Emergency Exit Door - Alignment / Adjustment**							RE (-)			
52 A/F							Mos					
							Hrs					
	Mfg#:52-21-01						Ldg					
523103		**External Baggage Door - Alignment / Adjustment**							RE (-)			
52 A/F							Mos					
							Hrs					
	Mfg#:52-31-01						Ldg					
523104		**Baggage Door Stopppers - Adjustment / Test**							RE (-)			
52 A/F							Mos					
							Hrs					
	Mfg#:52-31-01						Ldg					
523105		**Baggage Door Track Rollers - Adjustment / Test**							RE (-)			
52 A/F							Mos					
							Hrs					
	Mfg#:52-31-01						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
523106		**Baggage Door Interlock - Adjustment / Test**							RE (-)			
	52 A/F						Mos					
							Hrs					
	Mfg#:52-31-01						Ldg					
523107		**Baggage Door Opening - Adjustment / Test**							RE (-)			
	52 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:52-31-01						Ldg	10				
523108		**Baggage Door Outer Handle and Trigger - Adjustment / Test**							RE (-)			
	52 A/F						Mos					
							Hrs					
	Mfg#:52-31-01						Ldg					
523109		**Baggage Door Inner Handle and Trigger - Adjustment / Test**							RE (-)			
	52 A/F						Mos					
							Hrs					
	Mfg#:52-31-01						Ldg					
525103		**Auxiliary Bulkhead Door - Adjustment / Test**							RE (-)			
	52 A/F						Mos					
							Hrs					
	Mfg#:52-51-01						Ldg					
525107		**Auxiliary Bulkhead Door Switch - Operational Test**							RE (-)			
	52 A/F						Mos					
							Hrs					
	Mfg#:52-71-01						Ldg					
527001		**Door Warning System - Operational Test**							RE (-)			
	52 A/F						Mos	02-Mar-2023				
							Hrs	34:12				
	Mfg#:52-70-00-AT						Ldg	10				
527115		**Emergency Exit Door Switch - Operational Test**							RE (-)			
	52 A/F						Mos					
							Hrs					
	Mfg#:52-71-01						Ldg					
527116		**External Baggage Door Switch - Operational Test**							RE (-)			
	52 A/F						Mos					
							Hrs					
	Mfg#:52-71-01						Ldg					
527118		**Main Entrance Door Switch - Operational Test**							RE (-)			
	52 A/F						Mos					
							Hrs					
	Mfg#:52-71-01						Ldg					
527151		**Tail Compartment Door Switch - Operational Test**							RE (-)			
	52 A/F						Mos					
							Hrs					
	Mfg#:52-71-02						Ldg					
527152		**Left Avionics Door Switch - Operational Test**							RE (-)			
	52 A/F						Mos					
							Hrs					
	Mfg#:52-71-02						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
527153	**Right Avionics Door Switch - Operational Test**							RE (-)			
52 A/F						Mos					
						Hrs					
Mfg#:52-71-02						Ldg					
527154	**Refuel Adapter Door Switch - Operational Test**							RE (-)			
52 A/F						Mos					
						Hrs					
Mfg#:52-71-02						Ldg					
527155	**Refuel Control Panel Door Switch - Operational Test**							RE (-)			
52 A/F						Mos					
						Hrs					
Mfg#:52-71-02						Ldg					
527156	**Hydraulic Service Door Switch - Operational Test**							RE (-)			
52 A/F						Mos					
						Hrs					
Mfg#:52-71-02						Ldg					
527157	**Left Battery Door Switch - Operational Test**							RE (-)			
52 A/F						Mos					
						Hrs					
Mfg#:52-71-02						Ldg					
527158	**Right Battery Door Switch - Operational Test**							RE (-)			
52 A/F						Mos					
						Hrs					
Mfg#:52-71-02						Ldg					
527159	**Water Service Door Switch - Operational Test**							RE (-)			
52 A/F						Mos					
						Hrs					
Mfg#:52-71-02						Ldg					
527160	**Waste System Door Switch - Operational Test**							RE (-)			
52 A/F						Mos					
						Hrs					
Mfg#:52-71-02						Ldg					
527161	**ATS Door Switch - Operational Test**							RE (-)			
52 A/F						Mos					
						Hrs					
Mfg#:52-71-02						Ldg					
527162	**APU Service Door Switch - Operational Test**							RE (-)			
52 A/F						Mos					
						Hrs					
Mfg#:52-71-02						Ldg					
527163	**External Power Door Switch - Operational Test**							RE (-)			
52 A/F						Mos					
						Hrs					
Mfg#:52-71-02						Ldg					
2020-15-02	**Fuselage - FWD Fuel Tank Probes Clearance Verification**							RE (-)		Mandatory	
53 A/F						Mos	10-Feb-2023				
Eff: 27-Aug-2020 Not Applicable	PER CAAI ISRAEL AD NO. ISR-I-53-19-10-5.					Hrs	24:24				
						Ldg	7				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-53-020	**Fuselage - Joining Assembly Bulkhead Aft Fuselage - Rework (MODG25-00255)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 13-Sep-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-023	**Fuselage - Forward Pressure Bulkhead - Rework (MODG25-00210)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 13-Sep-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-031	**Fuselage - Wing To Fuselage Connection, Right Side - Installation Of A New Bracket And Clamps To Support Electrical Harness (MODG25-00225)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 26-Jul-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-032	**Fuselage - Joining, Forward Fuselage To Center Fuselage - Installation Of A New Bracket And Clamp To Support Water System Hose Near Floor Structure (MODG25- 00204)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 24-Jan-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-042	**Fuselage - Replacement Of Anti-Rotation Washers On Wing To Fuselage Links (MODG25-20032)**							RE (-)		Mandatory	
53 A/F						Mos	10-Feb-2023				
Eff: 13-Sep-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-051	**Fuselage - Cockpit - Left And Right Side Console Structure - Replacement Of Existing Aircraft Personality Module (APM) Attachment Nut Plates (MODG25-00337)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 02-Aug-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-069	**Fuselage - Nose Structure - Avionics Bay Rework (MODG25-00396)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 04-Oct-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-070	**Fuselage - Aft Fuselage Left Side Panel - Installation Of Clamp To Support Electrical Harness Near R/T HF9030 Support Assembly (MODG25-00395)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 04-Oct-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-074	**Fuselage - Right Side Fuselage - Forward Fuel Tank Fairing - Rework (MODG25- 00387)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 30-Oct-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-084	**Fuselage - Right Side Forward Fairing - Installation Of Additional Clamps To Improve Attachment Of Electrical Harness 1527 To Fairing (MODG25-00405)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 10-Jan-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-53-092	**Fuselage - Aft Fuselage - Electrical Bonding Improvement Of Service Panel Light (MODG25-00424)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 26-Jun-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-096 Rev 1	**Fuselage - Forward Right Side - Fuel Tank Assembly Rework And Electrical Harness Routing Modification (MODG25-20057)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 07-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-104	**Fuselage - Cockpit - Fuselage Stations 1663-4518 - Nose Landing Gear (NLG) Pivot Guide Tube Rework (MODG25-00454)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 19-Dec-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-112	**Fuselage - Forward Fuselage Bulkheads And Frames - Rudder Bellcrank And Support Fittings Rework (MODG25-00511)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 12-Dec-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-119	**Fuselage Structure - Center Fuselage - Flange Between Frames 32 Through 36 Under Escape Door Cold Work (MODG25-10039)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 16-Nov-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-134	**Fuselage - Forward Fuel Tank And Forward Lower Fairing - Improvement Of Installation Process When Replacing Forward Fuel Tank (MODG25-00648)**							RE (-)		Recommended	
53 A/F						Mos					
						Hrs					
(NOTE: not found)						Ldg					
280-53-140	**Fuselage - Baggage Compartment Structure - Replacement Of Existing Stoppers And Serrated Plates (MODG25-10046)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 30-Oct-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-147	**Fuselage - Aft Fuselage - High Frequency (HF) - Antenna Coax Cable Electrical Bonding - Rework (MODG25-00708)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 30-Oct-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-149	**Fuselage - Right Aft Fuselage - Inspection For Possible Interference Between Angle And Skin At Frame 59 (MODG25-00739)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 30-Oct-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-162 Rev 1	**Fuselage - Tail Compartment - Installation of a Water Collection and Drainage Diversion at Frame 63 (MODG25-00841)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 02-Feb-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-171	**Fuselage - Aft Fuselage - Installation Of A New Bonding Jumper Between Frame 60 And Elevator Force Disconnect Unit (MODG25-00902)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 19-Jun-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-53-183	**Fuselage - Aft Fuselage - Inverter/CVR Tray Assembly - Replacement of Fasteners Attaching Grounding Bracket And Modify Static Inverter Electrical Bonding Area (MODG25-00956)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 19-Jun-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-192	**Fuselage - Cockpit Pedestal - Cockpit Floor Inspection and Repair**							RE (-)		Recommended	
53 A/F						Mos	14-Apr-2023				
Eff: 13-Jul-2022 Not Applicable	as per a/c S/N					Hrs	112:17				
(AVG MAN HRS: 55)						Ldg	61				
280-53-218	**Fuselage - Forward Fuselage - ATC Coax Cable under Forward Radio Rack Routing - Rework**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 24-Oct-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 8.5)						Ldg	7				
280-53-250	**Structure - HF Radio Box and Hydraulic Tube Riding Condition (MODG25-01544)**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 22-Aug-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-53-263	**Fuselage (ATA 53) - AFT Fuselage - Preventing Fluid Accumulation in Frame 64**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 09-Dec-2022 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 16)						Ldg	7				
280-53-282	**Fuselage - Left Nose Avionics Equipment Bay - Thermal Switches Bracket Rework**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 09-Apr-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 5)						Ldg	7				
280-53-287	**Fuselage - Forward Fuel Tank Probe Clearance Verification**							RE (-)		Mandatory, Service Bulletin	
53 A/F						Mos	10-Feb-2023				
Eff: 19-Feb-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 20)						Ldg	7				
280-53-312	**Fuselage - Aft Fuselage - Avionic Harness Rerouting at Frame 63**							RE (-)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 11-Nov-2022 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 5)						Ldg	7				
280-53A-033	**Fuselage Structure - Side Brace Fitting Bolts - Inspection And Repair (MODG25- 00304)**							RE (-)		Mandatory	
53 A/F						Mos	10-Feb-2023				
Eff: 23-Jan-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
530030	**Fuselage Watertightness - Functional Test**							RE (-)			
53 A/F						Mos					
						Hrs					
Mfg#:53-00-00 (SOURCE: 53-00-00)						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
531003		**FF4.3 Forward Fuselage Skin Panel Right Side FS 177.87 - FS 229.21 (4518 - 5822 mm) - NDT Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-10-01						Ldg					
531313		**FF9.3 Forward Cabin External Doubler FS 297.56 - FS 346.38 (7558 - 8798 mm) - NDT Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-13-01-IC						Ldg					
531314		**FF9.4 Forward Cabin Stringer FS 258.50 - FS 346.38 (6566 - 8798 mm) - NDT Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-13-01-IC						Ldg					
531315		**FF9.5 Forward Cabin to Aft Cabin Joining Fitting at Frame 27 - NDT Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-13-01-IC						Ldg					
532050		**CF6.1 Emergency Exit Frame 33 - NDT / Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-20-02						Ldg					
532051		**CF6.2 Emergency Exit Frame 35 - NDT / Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-20-02						Ldg					
533303		**AF4.1 Aft Fuselage Upper Longerons Frame 51 - Frame 55 (Left) - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533304		**AF4.2 Aft Fuselage Upper Longerons Frame 51 - Frame 55 (Right) - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533305		**AF4.3 Aft Fuselage Upper Longerons Frame 55 - Frame 56 - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533308		**AF4.6 Aft Fuselage Left Upper Longeron Frame 60 - Frame 63 - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533309		**AF4.7 Aft Fuselage Right Upper Longeron Frame 60 - Frame 63 - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533310		**AF4.8 Aft Fuselage Left Upper Longeron Frame 63 - Frame 64 - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
533311		**AF5.1 Aft Fuselage Frame 51 Splice - NDT Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533312		**AF5.2 Aft Fuselage Frame 55 - Frame 56 Splice - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533313		**AF5.3 Aft Fuselage Upper Longeron Bathtub Fitting - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533314		**AF5.4 Aft Fuselage Upper Longeron Fitting to Frame 55 (Forward) - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533315		**AF5.5 Aft Fuselage Upper Longeron Fitting to Frame 55 (Aft) - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533317		**AF6.2 Aft Fuselage Joint Splice Frame 60 FS 676.30 (17,178 mm) - NDT Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533318		**AF6.3 Aft Fuselage Joint Splice Frame 63 FS 702.36 (17,840 mm) - NDT Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533319		**AF7.1 Aft Fuselage Frame 56 Forward Angle Clip - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533320		**AF7.2 Aft Fuselage Frame 60 Forward Angle Clip - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533321		**AF7.3 Aft Fuselage Frame 56 Flat Splice - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533322		**AF7.4 Aft Fuselage Frame 60 Flat Splice - NDT Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533323		**AF7.5 Aft Fuselage Frame 63 Flat Splice - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
533325		**AF11.2 Aft Fuselage Lower Frame 56 - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533326		**AF11.3 Aft Fuselage Frame 56 Splices (Left) - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533327		**AF11.4 Aft Fuselage Frame 56 Splices (Right) - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533330		**AF13.1 Aft Fuselage Forward Side Left and Right Longeron Splice Fitting Frame 51 - Frame 55 - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533331		**AF13.2 Aft Fuselage Side Longeron Splice Fitting Frame 55 - Frame 56 (Left) - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533332		**AF13.3 Aft Fuselage Side Longeron Splice Fitting Frame 55 - Frame 56 (Right) - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533333		**AF13.4 Aft Fuselage Mid Side Longeron Frame 56 - Frame 57 - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533334		**AF13.5 Aft Fuselage Mid Side Longeron Frame 58 - Frame 60 - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533335		**AF13.6 Aft Fuselage Aft Side Longeron Frame 60 - Frame 63 (Left) - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533336		**AF13.7 Aft Fuselage Aft Side Longeron Frame 60 - Frame 63 (Right) - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533337		**AF15.1 Aft Fuselage Frame 55 FS 627.48 (15,938 mm) Side Longeron Splice Fitting (Left) - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					
533338		**AF15.2 Aft Fuselage Frame 55 FS 627.48 (15,938 mm) Side Longeron Splice Fitting (Right) - Visual Inspection**							RE (-)			
	53 A/F						Mos					
							Hrs					
	Mfg#:53-33-02-IC						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
533339	**AF15.3 Aft Fuselage Frame 51 Side Longeron Splice Fitting - Visual Inspection**							RE (-)			
53 A/F						Mos					
						Hrs					
Mfg#:53-33-02-IC						Ldg					
ISR-I-53-19-10-5	**Forward Fuel Tank Probes Clearance Verification**							RE (-)		Mandatory	
53 A/F						Mos	09-Nov-2022				
Eff: 30-Nov-2019 Not Applicable	BY AIRCRAFT SERIAL NUMBER					Hrs					
						Ldg					
541102	**Nose Cowling (Right) Leading Edge Polishing / Corrosion Prevention (Recurring / In-Service Application)**							RE (-)			
54 A/F						Mos					
						Hrs					
Mfg#:54-11-00						Ldg					
280-55-021	**Stabilizers - Vertical Stabilizer (V/S) And Horizontal Stabilizer (H/S) - Structure Joining Assemblies Repair (MODG25-00212)**							RE (-)		Recommended	
55 A/F						Mos	10-Feb-2023				
Eff: 12-Dec-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-55-024	**Stabilizers - Horizontal Stabilizer - Brace Assembly Rework - Addition Of Chamfer To Scissor Attachment Bolts (Empennage) (MODG25-00236)**							RE (-)		Recommended	
55 A/F						Mos	10-Feb-2023				
Eff: 06-Feb-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-55-026	**Stabilizers - Horizontal Stabilizer Trim Actuator (HSTA) - Front Upper Attachment Assembly - Shear Rings - Rework (MODG25-00214)**							RE (-)		Recommended	
55 A/F						Mos	10-Feb-2023				
Eff: 12-Dec-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-55-203	**Stabilizers - Rudder Hinge - Drainage Holes Corrosion Protection On Middle Fitting (MODG25-01175)**							RE (-)		Recommended	
55 A/F						Mos	10-Feb-2023				
Eff: 26-Jan-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-55-260	**Stabilizers (ATA 55) - Horizontal Stabilizer - Inspection and Repair of the LH and RH Outer Front Spar Beam**							RE (-)		Recommended	
55 A/F						Mos	27-May-2024				
Eff: 24-May-2024 Not Applicable	as per aircraft S/N					Hrs	842:13				
(AVG MAN HRS: 31)						Ldg	496				
553013	**Vertical Stabilizer Leading Edge - General Visual Inspection**							RE (-)			
55 A/F						Mos					
						Hrs					
Mfg#:55-30-00-IC						Ldg					
280-56-016	**Windows - Cockpit Windshield - Modification Of Windshield De-Ice Cable Routing To Match New Terminal Board Position (MODG25-00164)**							RE (-)		Recommended	
56 A/F						Mos	10-Feb-2023				
Eff: 13-Dec-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-56-016 PART A	**Windows - Pilot - Cockpit Windshield - Modification Of Windshield De-Ice Cable Routing To Match New Terminal Board Position**							RE (-)			
56 A/F						Mos	10-Feb-2023				
Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
561001	**Window Surface Seal (Pilot Windshield) - Restore**							RE (-)			
56 A/F						Mos					
						Hrs					
Ref#:56-10-00						Ldg					
561002	**Window Surface Seal (Copilot Windshield) - Restore**							RE (-)			
56 A/F						Mos					
						Hrs					
Ref#:56-10-00						Ldg					
561009	**Flight Compartment Windows (Pilot Windshield) - Cleaning**							RE (-)			
56 A/F						Mos					
						Hrs					
Mfg#:56-10-00						Ldg					
561010	**Flight Compartment Windows (Copilot Windshield) - Cleaning**							RE (-)			
56 A/F						Mos					
						Hrs					
Mfg#:56-10-00						Ldg					
561011	**Flight Compartment Windows (Pilot Side Window) - Cleaning**							RE (-)			
56 A/F						Mos					
						Hrs					
Mfg#:56-10-00						Ldg					
561012	**Flight Compartment Windows (Copilot Side Window) - Cleaning**							RE (-)			
56 A/F						Mos					
						Hrs					
Mfg#:56-10-00						Ldg					
561013	**Flight Compartment Windows Water Repellent Coating Application (Pilot Windshield)**							RE (-)			
56 A/F						Mos					
						Hrs					
Mfg#:56-10-00						Ldg					
561014	**Flight Compartment Windows Water Repellent Coating Application (Copilot Windshield)**							RE (-)			
56 A/F						Mos					
						Hrs					
Mfg#:56-10-00						Ldg					
561015	**Flight Compartment Windows Water Repellent Coating Application (Pilot Side Window)**							RE (-)			
56 A/F						Mos					
						Hrs					
Mfg#:56-10-00						Ldg					
561016	**Flight Compartment Windows Water Repellent Coating Application (Copilot Side Window)**							RE (-)			
56 A/F						Mos					
						Hrs					
Mfg#:56-10-00						Ldg					
561017	**Flight Compartment Window Heating Element / Sensor - Resistance Check**							RE (-)			
56 A/F						Mos					
						Hrs					
Ref#:56-10-00						Ldg					
561018	**Flight Compartment Windows - Visual Check / Damage Limit**							RE (-)			
56 A/F						Mos					
						Hrs					
Ref#:56-10-00						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
561102	**Windshield Moisture Seal - Repair**							RE (-)			
56 A/F						Mos					
						Hrs					
Mfg#:56-11-01						Ldg					
562118	**Cabin Windows - Cleaning**							RE (-)			
56 A/F						Mos					
						Hrs					
Ref#:56-21-01						Ldg					
562119	**Cabin Windows - Visual Check / Damage Limit**							RE (-)			
56 A/F						Mos					
						Hrs					
Ref#:56-21-01						Ldg					
562120	**Cabin Windows - Repair**							RE (-)			
56 A/F						Mos					
						Hrs					
Mfg#:56-21-01						Ldg					
2021-17-14	**Wings - Crack at the Area of the Wing Rib 0 to the Front Spar**							RE (-)		Mandatory	
57 A/F						Mos	09-Nov-2022				
Eff: 14-Oct-2021 Not Applicable	BY AIRCRAFT SERIAL NUMBER					Hrs	0				
						Ldg	0				
280-57-036	**Wings - Wing Wiring Harness Installation Retrofit (MODG25-10706 , MODG25- 00469)**							RE (-)		Mandatory	
57 A/F						Mos	10-Feb-2023				
Eff: 26-Jul-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
Ref:AWL-1 (SOURCE: 05-10-10 - Table 10: Temporary Limitation and Inspection Requirements) (NOTE: MOD G25- 10706 MOD G25- 00469 SB 280-57- 036)											
280-57-040	**Wings - Wing Flap Track C Modification And Scuff Plate Installation (MODG25- 20713)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 19-Jan-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-047 Rev 1	**Wings - Wing Flap Track D Roller Fittings Retrofit (MODG25-10708 , MODG25- 07112)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 19-Jan-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-059	**Wings - Aileron - Aileron Position Sensor Bracket, Eccentric Bushing and Retainer Retrofit**							RE (-)		Recommended	
57 A/F						Mos	27-May-2024				
Eff: 19-Apr-2024 Not Applicable	as per aircraft S/N					Hrs	842:13				
						Ldg	496				
(AVG MAN HRS: 18)											
280-57-060	**Wings - Wing Flap Track A , D Turn Down Hooks Retrofit (MODG25-10705)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 19-Jan-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-57-071	**Wings - Electrical Harnesses Routing Improvements Of Left And Right Wing Leading Edge Inboard Area And Left And Right Trailing Edge Near Spoiler Number 3 (MODG25-20047, MODG25-00469 , MODG25-00487)**							RE (-)		Mandatory	
57 A/F						Mos	10-Feb-2023				
Eff: 26-Jul-2023 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
Ref:AWL-2 (SOURCE: 05-10-10 - Table 10: Temporary Limitation and Inspection Requirements) (NOTE: MOD G25- 20047 MOD G25- 00469 MOD G25- 00487 SB 280-57- 071)											
280-57-078	**Wings - Aileron - Divide Aileron Upper Cove Panel And Lower Seal Panel Into 3 Pieces**							RE (-)		Recommended	
57 A/F						Mos					
						Hrs					
(NOTE: not found)						Ldg					
280-57-099	**Adding a Doubler to the Forward Spar and Rib 0 Attachment**							RE (-)		Mandatory	
57 A/F						Mos	10-Feb-2023				
Eff: 26-Feb-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
(AVG MAN HRS: 80)											
280-57-100	**Wings - Flaps - Retrofit Of Track D With Cres Track - And Rework Of Flap Tracks A, B, C And D (MODG25-20716, MODG25-070137 , MODG25-07141)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 19-Jan-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-101	**Wings - Flaps - Track B Outboard , Track C Inboard Roller Attach Fasteners Retrofit (MODG25-20717)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 31-Jan-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-102	**Wings - Fuel Drain Valves - Addition Of Sealant (Overcoating) To Drain Valve Fasteners (MODG25-07096)**							RE (-)		Mandatory	
57 A/F						Mos	10-Feb-2023				
Eff: 04-Oct-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-110	**Wings- Wing Flap Track A , D Trailing Edge Roller Fitting Retrofit (MODG25-07081)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 04-Oct-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-125	**Wings - Install a New Bracket and Move the Existing P-Clamp to Prevent Wire Harness Proximity to Main Landing Gear (MLG)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 29-Oct-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
(AVG MAN HRS: 20)											
280-57-127	**Wings - Wing Anti-Ice Tubes - Adding Chamfer to Wing Anti-Ice Piccolo Tube Capture Brackets on the RH Wing Per MOD G25-07135**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 19-Dec-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-130	**Wings - Re-Route Brake Line Hydraulic Tube To Provide Adequate Clearance To The Tire Burst Shield Bracket (MODG25-07062)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 08-Jul-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-57-133 Rev 1	**Wings - Wing Flap Track A Inboard And Outboard Roller Fittings Retrofit (MODG25- 10710)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 19-Jan-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-142	**Wings - Relocation Of Saddle Clamp Attaching Fuel Tube To Rib 1 Stiffener In The Left Hand Wing Fuel Tank (MODG25-07147)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 15-Dec-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-145	**Wings - Shorten Wing Anti-Ice (WAI) Grounding Screw Length in Gap Band 1 and 3 (MODG25-07151)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 19-Dec-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-150	**Wings - Wing Leading Edge Access Panels - Fastener Retrofit (MODG25-07153)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 30-Oct-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-151	**Reduce Spoiler Hinge Bolt Torque**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 04-Dec-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 35)						Ldg	7				
280-57-152	**Wings - Modifying Bracket On Stringer To Prevent Interference Between Bracket And Stringer (MODG25-07162)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 17-Nov-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-155	**Wings - Retrofitting Electrical Bracket On The Jettison Rib To Eliminate Fastener Interference (MOD G25-07165)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 26-Jan-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-156	**Wings - Wing Fuel Tank - Addition Of Drain Hole In Dry Bay (MODG25-20721)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 30-Oct-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-159	**Wings - Re-Torque Winglet Cap Attach Fasteners**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 16-Nov-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 3)						Ldg	7				
280-57-161	**Wings - Ensure Clearance Between RHS FQMS Wire Harness P-Clamp Bolt And Stringer (MODG25-07179)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 16-Nov-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-57-166	**Wings - Main Landing Gear (MLG) Sponson - Retorquing of Aft Lug Bearing (MODG25-00851)**							RE (-)		Required	
57 A/F						Mos	10-Feb-2023				
Eff: 20-Nov-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-177	**Wings - Addition of Bracket To Right Side Wing Inboard Leading Edge Wire Harness Assembly (MODG25-07189)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 01-Jun-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-181	**Wings - Lower Cove Panel Seals - Modification To Prevent Deflection (MODG25- 07192 , MODG25-07231)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 01-Jun-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-182	**Wings - Enlarging Holes on Feed Tank Bracket**							RE (-)		Recommended	
57 A/F						Mos	10-Aug-2023				
Eff: 23-Jun-2023 Not Applicable						Hrs					
(AVG MAN HRS: 120) (UPDATE NOTE: N/A by SN of the aircraft)						Ldg					
280-57-185	**Wings - Wing Access Panels Installation - Modification for Improved Electrical Bonding**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 29-Oct-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 75)						Ldg	7				
280-57-187	**Wings - Rework The Mating Surface Under Flapper Valves On Wing Rib 6 (MODG25- 07203)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 15-Dec-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-188	**Wings - Adding A Clamp On The Center Tank FQMS Harness To Ensure Adequate Clearance With Fuel Tube (MODG25-07204)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 15-Dec-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-193	**Replace Shrink Splices on Landing Light Wire Harness**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 01-Feb-2018 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-57-199	**Wings - Torsion Box Fuel Tube Bracketry Grounding Improvement (MODG25-07215)**							RE (-)		Recommended	
57 A/F						Mos					
						Hrs					
(NOTE: not found)						Ldg					
280-57-221	**Installing Missing Flap Fasteners on G280 Flap**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 14-Feb-2018 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 4)						Ldg	7				
280-57-222 Rev 1	**Wings - Inspection and / or Repair of Flap Spar Cracks On Track D (MODG25-01308)**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 13-May-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-57-227	**Wings - Correct Sealant and Electrical Bonding for Scavenger Ejector Pump Installs**							RE (-)		Recommended	
57 A/F						Mos	10-Aug-2023				
Eff: 28-Jul-2023 Not Applicable						Hrs					
(AVG MAN HRS: 58) (UPDATE NOTE: N/A by SN of the aircraft)						Ldg					
280-57-231	**Wings - Retrofit Rear Spar Brackets for Missing EBL Requirements and Apply Fillet Seal**							RE (-)		Recommended	
57 A/F						Mos	10-Aug-2023				
Eff: 28-Jul-2023 Not Applicable						Hrs					
(AVG MAN HRS: 10) (UPDATE NOTE: N/A by SN of the aircraft)						Ldg					
280-57-238	**Ground Spoiler Actuator Attachment Hardware Change**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 25-Feb-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 5)						Ldg	7				
280-57-242	**Wings - Inspection and Retrofit of the Trailing Edge Wire Harness on Inboard Aileron**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 16-Jan-2023 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 17)						Ldg	7				
280-57-274	**Wings - Inspection for Corrosion Between Aileron Gear Tab Adjuster Nut and Gear Tab Control Rod and Replacement of Non-Conforming Nuts**							RE (-)		Recommended	
57 A/F						Mos					
Eff: 28-May-2024						Hrs					
(AVG MAN HRS: 30)						Ldg					
280-57-275	**Wings - Apply Protective Coating to Areas Under Flapper Valves on Rib 2**							RE (-)		Recommended	
57 A/F						Mos	10-Aug-2023				
Eff: 05-May-2023 Not Applicable						Hrs					
(AVG MAN HRS: 35) (UPDATE NOTE: N/A by SN of the aircraft)						Ldg					
280-57-276	**Wings - FQMS Wire Harness Bend Radius Verification and Retrofit at Rib 2 and Rib 10**							RE (-)		Recommended	
57 A/F						Mos	14-Apr-2023				
Eff: 09-Apr-2020 Not Applicable	as per aircraft S/N					Hrs	112:17				
(AVG MAN HRS: 14)						Ldg	61				
280-57-276 Rev 1	**Wings - FQMS Wire Harness Bend Radius Verification and Retrofit at Rib 2 and Rib 10**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 12-May-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 14)						Ldg	7				
280-57-277	**Wings - Cold Working of Holes in Lower Skin Stringer 3 Common to Outboard Feed Tank Lower Bracket**							RE (-)		Recommended	
57 A/F						Mos	10-Aug-2023				
Eff: 23-Jun-2023 Not Applicable						Hrs					
(AVG MAN HRS: 109) (UPDATE NOTE: N/A by SN of the aircraft)						Ldg					
280-57-280	**Wings - Trimming Rib 2 Cutout for Stringer 5 on Aft Lower Skin to Improve Fatigue Resistance**							RE (-)		Recommended	
57 A/F						Mos	10-Sep-2024				
Eff: 19-Jul-2024 Not Applicable						Hrs					
(AVG MAN HRS: 115) (UPDATE NOTE: NA by SN of the aircraft)						Ldg					
280-57-284	**Wings - Applying Coating on Leading Edge Ground Studs**							RE (-)		Recommended	
57 A/F						Mos	20-Nov-2023				
Eff: 05-Apr-2023 Not Applicable						Hrs					
(AVG MAN HRS: 55) (UPDATE NOTE: NOT APPLICABLE to aircraft serial number)						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-57-288	**Wings (ATA 57) - Aileron Lower Seal Panels Sealant Inspection and Repair**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 13-Jan-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 1)						Ldg	7				
280-57-289	**Wings - Re-Torquing the Ground Stud Fasteners Located in the Wing Tank OB of Rib 15 on the LHS and RHS FWD Spars**							RE (-)		Recommended	
57 A/F						Mos	10-Feb-2023				
Eff: 29-Oct-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
(AVG MAN HRS: 4)						Ldg	7				
280-57-296	**Wings - Access Panels - Add Conductive Finish to Lower Wing Skin and Access Panels and Retainers**							RE (-)		Recommended	
57 A/F						Mos	10-Aug-2023				
Eff: 23-Jun-2023 Not Applicable						Hrs					
(AVG MAN HRS: 83) (UPDATE NOTE: N/A by SN of the aircraft)						Ldg					
280-57-299	**Wings - Flapper Valve - Fatigue Crack Preventing on Rib 2**							RE (-)		Recommended	
57 A/F						Mos	10-Aug-2023				
Eff: 23-Jun-2023 Not Applicable						Hrs					
(AVG MAN HRS: 50) (UPDATE NOTE: N/A by SN of the aircraft)						Ldg					
280-57-313	**Wings (ATA 57) - Fuel Access Panels - Grommet Replacement on LH & RH Wing Rib 6 Area**							RE (-)		Service Bulletin	
57 A/F						Mos	17-Apr-2023				
Eff: 24-Feb-2023 Not Applicable	as per a/c S/N					Hrs	122:11				
(AVG MAN HRS: 8)						Ldg	69				
280-57-314	**Wings - Trailing Edge and Trailing Edge Devices - Flap Track A and D Trailing Edge Roller Fitting Assembly Fasteners Sealant and Torque**							RE (-)		Recommended	
57 A/F						Mos	29-Nov-2023				
Eff: 09-Oct-2023 Not Applicable						Hrs					
(AVG MAN HRS: 1.5) (UPDATE NOTE: N/A by SN of the aircraft)						Ldg					
571006	**CP36 Rib 0 (Right) - Visual / NDT Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
Mfg#:57-10-00-IC						Ldg					
571017	**CP53 Butterfly Clips of Rib 1 (Right) - Visual Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
Ref#:57-10-00-IC						Ldg					
571018	**CP53 Butterfly Clips of Rib 2 (Left) - Visual Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
Ref#:57-10-00-IC						Ldg					
571019	**CP53 Butterfly Clips of Rib 2 (Right) - Visual Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
Ref#:57-10-00-IC						Ldg					
571611	**Wing to Fuselage Forward Vertical / Lateral Support (Left) - Detailed Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					
571612	**Wing to Fuselage Aft Vertical / Lateral Support (Left) - Detailed Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
571613	**Wing to Fuselage Drag Support (Left) - Detailed Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					
571614	**Wing to Fuselage Drag Support (Right) - Detailed Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					
571615	**Wing to Fuselage Forward Vertical Support (Right) - Detailed Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					
571616	**Wing to Fuselage Aft Vertical Support (Right) - Detailed Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					
571617	**Wing to Fuselage Attachment Point (Left, Frame 27) - Detailed Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					
571618	**Wing to Fuselage Attachment Point (Right, Frame 27) - Detailed Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					
571619	**Wing to Fuselage Attachment Point (Left, Frame 29) - Detailed Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					
571620	**Wing to Fuselage Attachment Point (Right, Frame 29) - Detailed Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					
571621	**Wing to Fuselage Attachment Point (Left, Frame 38) - Detailed Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					
571622	**Wing to Fuselage Attachment Point (Right, Frame 38) - Detailed Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					
571623	**Wing to Fuselage Attachment Point Horizontal Fitting Link (Left, Rear Frame 38) - Detailed Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					
575013	**CP20 Flap Track C and Backup Structure - NDT Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
575014	**CP20 Flap Track D and Backup Structure - NDT Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					
575081	**CP21 Flap Tracks B (Left) - NDT Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
Ref#:57-50-00-IC						Ldg					
575082	**CP21 Flap Tracks B (Right) - NDT Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
Ref#:57-50-00-IC						Ldg					
575083	**CP22 Flap Tracks C (Left) - NDT Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
Ref#:57-50-00-IC						Ldg					
575084	**CP22 Flap Tracks C (Right) - NDT Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
Ref#:57-50-00-IC						Ldg					
575085	**CP23 Flap Tracks D (Left) - NDT Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
Ref#:57-50-00-IC						Ldg					
575086	**CP23 Flap Tracks D (Right) - NDT Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
Ref#:57-50-00-IC						Ldg					
575087	**CP22 Flap Tracks C Roller Fitting (Left) - NDT Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
Ref#:57-50-00-IC						Ldg					
575088	**CP22 Flap Tracks C Roller Fitting (Right) - NDT Inspection**							RE (-)			
57 A/F						Mos					
						Hrs					
Ref#:57-50-00-IC						Ldg					
IL ISR-I-57-2020-06-01	**Instructions To Install A Doubler At The Attachment Location Of The Wing Rib 0 And The Front Spar (Mandatory)**							RE (-)			
57 A/F						Mos	09-Nov-2022				
Not Applicable	BY AIRCRAFT SERIAL NUMBER					Hrs					
						Ldg					
710025	**Powerplant (Left) - Maintenance Practices**							RE (-)			
71 A/F						Mos					
						Hrs					
Mfg#:71-00-00-MP						Ldg					
710026	**Powerplant (Right) - Maintenance Practices**							RE (-)			
71 A/F						Mos					
						Hrs					
Mfg#:71-00-00-MP						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
710027	**Dry Motor Engine (Left) - Maintenance Practices**							RE (-)			
71 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:71-00-00-MP						Ldg	10				
710028	**Dry Motor Engine (Right) - Maintenance Practices**							RE (-)			
71 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:71-00-00-MP						Ldg	10				
710029	**Wet Motor Engine (Left) - Maintenance Practices**							RE (-)			
71 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:71-00-00-MP						Ldg	10				
710030	**Wet Motor Engine (Right) - Maintenance Practices**							RE (-)			
71 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:71-00-00-MP						Ldg	10				
710031	**Engine Run for Leak Check (Left) - Maintenance Practices**							RE (-)			
71 A/F						Mos					
						Hrs					
Mfg#:71-00-00-MP						Ldg					
710032	**Engine Run for Leak Check (Right) - Maintenance Practices**							RE (-)			
71 A/F						Mos					
						Hrs					
Mfg#:71-00-00-MP						Ldg					
710033	**Engine Power Assurance Run (Left) - Functional Check**							RE (-)			
71 A/F						Mos					
						Hrs					
Mfg#:71-00-00-MP						Ldg					
710034	**Engine Power Assurance Run (Right) - Functional Check**							RE (-)			
71 A/F						Mos					
						Hrs					
Mfg#:71-00-00-MP						Ldg					
711001	**Cowl Door (Left) - Adjustment**							RE (-)			
71 A/F						Mos					
						Hrs					
Mfg#:71-10-00						Ldg					
711002	**Cowl Door (Right) - Adjustment**							RE (-)			
71 A/F						Mos					
						Hrs					
Mfg#:71-10-00						Ldg					
711003	**External Cowling (Left) - General Visual Inspection**							RE (-)			
71 A/F						Mos					
						Hrs					
Mfg#:71-10-00						Ldg					
711004	**External Cowling (Right) - General Visual Inspection**							RE (-)			
71 A/F						Mos					
						Hrs					
Mfg#:71-10-00						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
711005	**Engine Lower Cowl Door (Left) - Open and Close Procedure**							RE (-)			
71 A/F						Mos	20-Oct-2023				
						Hrs	490:27				
Mfg#:71-10-00-MP						Ldg	293				
711006	**Engine Lower Cowl Door (Right) - Open and Close Procedure**							RE (-)			
71 A/F						Mos	20-Oct-2023				
						Hrs	490:27				
Mfg#:71-10-00-MP						Ldg	293				
711141	**Fan Cowl Door Tie Rod (Forward, Left) - Adjustment**							RE (-)			
71 A/F						Mos					
						Hrs					
Mfg#:71-11-05						Ldg					
711142	**Fan Cowl Door Tie Rod (Forward, Right) - Adjustment**							RE (-)			
71 A/F						Mos					
						Hrs					
Mfg#:71-11-05						Ldg					
711143	**Fan Cowl Door Tie Rod (Forward Mid, Left) - Adjustment**							RE (-)			
71 A/F						Mos					
						Hrs					
Mfg#:71-11-05						Ldg					
711144	**Fan Cowl Door Tie Rod (Forward Mid, Right) - Adjustment**							RE (-)			
71 A/F						Mos					
						Hrs					
Mfg#:71-11-05						Ldg					
711145	**Fan Cowl Door Tie Rod (Aft Mid, Left) - Adjustment**							RE (-)			
71 A/F						Mos					
						Hrs					
Mfg#:71-11-05						Ldg					
711146	**Fan Cowl Door Tie Rod (Aft Mid, Right) - Adjustment**							RE (-)			
71 A/F						Mos					
						Hrs					
Mfg#:71-11-05						Ldg					
711147	**Fan Cowl Door Tie Rod (Aft, Left) - Adjustment**							RE (-)			
71 A/F						Mos					
						Hrs					
Mfg#:71-11-05						Ldg					
711148	**Fan Cowl Door Tie Rod (Aft, Right) - Adjustment**							RE (-)			
71 A/F						Mos					
						Hrs					
Mfg#:71-11-05						Ldg					
D201406000102	**Setup Instructions for Electronic Engine Interface (EEI) Kit, PN 5837831-4, on all AS907 (HTF) Turbofan Engines**							RE (-)		Service Information Letter	
71 ENG1						Mos					
Eff: 08-Jul-2014						Hrs					
						Enc					
D201406000102	**Setup Instructions for Electronic Engine Interface (EEI) Kit, PN 5837831-4, on all AS907 (HTF) Turbofan Engines**							RE (-)		Service Information Letter	
71 ENG2						Mos					
Eff: 08-Jul-2014						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-3	**AS907 Jet-Care Trend Monitoring System**							RE (-)		Service Information Letter	
72 ENG1						Mos					
Eff: 23-Oct-2003						Hrs					
						Enc					
AS907-3	**AS907 Jet-Care Trend Monitoring System**							RE (-)		Service Information Letter	
72 ENG2						Mos					
Eff: 23-Oct-2003						Hrs					
						Enc					
AS907-3 Rev 1	**AS907 Jet-Care Trend Monitoring System**							RE (-)		Service Information Letter	
72 ENG1						Mos					
Eff: 05-Mar-2014						Hrs					
						Enc					
AS907-3 Rev 1	**AS907 Jet-Care Trend Monitoring System**							RE (-)		Service Information Letter	
72 ENG2						Mos					
Eff: 05-Mar-2014						Hrs					
						Enc					
AS907-72-9001 Rev 1	**Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	17-Apr-2023				
Eff: 04-May-2017 Not Applicable	as per engine S/N					Hrs	97:47				
(AVG MAN HRS: 5)						Enc	64				
AS907-72-9001 Rev 1	**Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 04-May-2017 Not Applicable	as per engine S/N					Hrs	117:47				
(AVG MAN HRS: 5)						Enc	76				
AS907-72-9001 Rev 3	**Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	17-Apr-2023				
Eff: 28-Sep-2020 Not Applicable	as per engine S/N					Hrs	97:47				
(AVG MAN HRS: 5)						Enc	64				
AS907-72-9001 Rev 3	**Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 28-Sep-2020 Not Applicable	as per engine S/N					Hrs	117:47				
(AVG MAN HRS: 5)						Enc	76				
AS907-72-9001 Rev 4	**Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	17-Apr-2023				
Eff: 21-Dec-2020 Not Applicable	as per engine S/N					Hrs	97:47				
(AVG MAN HRS: 5)						Enc	64				
AS907-72-9001 Rev 4	**Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 21-Dec-2020 Not Applicable	as per engine S/N					Hrs	117:47				
(AVG MAN HRS: 5)						Enc	76				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-72-9001 Rev 5	**Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	17-Apr-2023				
Eff: 05-May-2022 Not Applicable	as per engine S/N					Hrs	97:47				
(AVG MAN HRS: 5)						Enc	64				
AS907-72-9001 Rev 5	**Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 05-May-2022 Not Applicable	as per engine S/N					Hrs	117:47				
(AVG MAN HRS: 5)						Enc	76				
AS907-72-9001 Rev 6	**Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	17-Apr-2023				
Eff: 07-Mar-2023 Not Applicable	as per engine S/N					Hrs	97:47				
(AVG MAN HRS: 5)						Enc	64				
AS907-72-9001 Rev 6	**Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 07-Mar-2023 Not Applicable	as per engine S/N					Hrs	117:47				
(AVG MAN HRS: 5)						Enc	76				
AS907-72-9045 Rev 1	**Compressor Section - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2, -4**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	17-Apr-2023				
Not Applicable	as per engine S/N					Hrs	97:47				
(AVG MAN HRS: 2)						Enc	64				
AS907-72-9045 Rev 1	**Compressor Section - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2, -4**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	17-Apr-2023				
Not Applicable	as per engine S/N					Hrs	117:47				
(AVG MAN HRS: 2)						Enc	76				
AS907-72-9045 Rev 3	**Engine - Compressor Section - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2, -4 or -6**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	26-Jan-2023				
Eff: 18-Dec-2018 Complied With	AT MANUFACTURE					Hrs	0				
(AVG MAN HRS: 2)						Enc	0				
AS907-72-9045 Rev 3	**Engine - Compressor Section - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2, -4 or -6**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	20-Jan-2023				
Eff: 18-Dec-2018 Complied With	AT MANUFACTURE					Hrs	0				
(AVG MAN HRS: 2)						Enc	0				
AS907-72-9046 Rev 1	**HP Turbine Section - Install New HP Turbine Stage 2 Nozzle Segments PN 3035141-3, -4 on AS907 Engine Models**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	26-Jan-2023				
Eff: 29-Mar-2018 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
AS907-72-9046 Rev 1	**HP Turbine Section - Install New HP Turbine Stage 2 Nozzle Segments PN 3035141-3, -4 on AS907 Engine Models**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	20-Jan-2023				
Eff: 29-Mar-2018 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-72-9055 Rev 1	**Engine - High Pressure Compressor Assembly - Install New Stage 1 Variable Compressor Vanes, P/N 70040795-1, on AS907 Engines**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	10-Feb-2023				
Eff: 20-Dec-2017 Not Applicable	PER ENGINE PART NUMBE					Hrs					
						Enc					
AS907-72-9055 Rev 1	**Engine - High Pressure Compressor Assembly - Install New Stage 1 Variable Compressor Vanes, P/N 70040795-1, on AS907 Engines**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	10-Feb-2023				
Eff: 20-Dec-2017 Not Applicable	PER ENGINE PART NUMBER					Hrs					
						Enc					
AS907-72-9057 Rev 1	**Engine - HP Turbine Section - Install New Forward Vane Baffle, PN 70040799-1, on AS907-1-1A and AS907-2-1G Model Engines**							RE (-)		Cat.2-Reliability, Cat.3-Product Improvement	
72 ENG1						Mos	10-Apr-2023				
Eff: 05-Dec-2019 Not Applicable	per S/N					Hrs	84:18				
						Enc	54				
AS907-72-9057 Rev 1	**Engine - HP Turbine Section - Install New Forward Vane Baffle, PN 70040799-1, on AS907-1-1A and AS907-2-1G Model Engines**							RE (-)		Cat.2-Reliability, Cat.3-Product Improvement	
72 ENG2						Mos	10-Apr-2023				
Eff: 05-Dec-2019 Not Applicable	per S/N					Hrs	104:18				
						Enc	66				
AS907-72-9063 Rev 1	**Engine - HP Compressor - Install New Centrifugal Compressor Rotor, PN 3033207-1, Shroud, 70040911-1 or PN 70041133-1, and Diffuser, PN 70040018-1, for AS907-2-1G Engine Models**							RE (-)		Category 3, Optional	
72 ENG1						Mos	24-Jan-2024				
Eff: 31-Jul-2019 Not Applicable						Hrs					
(UPDATE NOTE: N/A as per installed ECU on OK_GTX)						Enc					
AS907-72-9063 Rev 1	**Engine - HP Compressor - Install New Centrifugal Compressor Rotor, PN 3033207-1, Shroud, 70040911-1 or PN 70041133-1, and Diffuser, PN 70040018-1, for AS907-2-1G Engine Models**							RE (-)		Category 3, Optional	
72 ENG2						Mos	24-Jan-2024				
Eff: 31-Jul-2019 Not Applicable						Hrs					
(UPDATE NOTE: N/A as per installed ECU on OK_GTX)						Enc					
AS907-72-9065	**Engine - Hp Compressor - Install New Compressor Case(s) with Reduced Number of Borescope Plugs on AS907 Engine Models**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	17-Apr-2023				
Eff: 08-Feb-2019 Not Applicable	as per engine S/N					Hrs	97:47				
						Enc	64				
AS907-72-9065	**Engine - Hp Compressor - Install New Compressor Case(s) with Reduced Number of Borescope Plugs on AS907 Engine Models**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	17-Apr-2023				
Eff: 08-Feb-2019 Not Applicable	as per engine S/N					Hrs	117:47				
						Enc	76				
AS907-72-9068	**Engine - HP Compressor - New Investment Cast Front Frame Assemblies, PN 70040792-4, and PN 70040939-2, for AS907 Engine Models**							RE (-)		Category 3, Optional	
72 ENG1						Mos					
Eff: 22-Aug-2019						Hrs					
						Enc					
AS907-72-9068	**Engine - HP Compressor - New Investment Cast Front Frame Assemblies, PN 70040792-4, and PN 70040939-2, for AS907 Engine Models**							RE (-)		Category 3, Optional	
72 ENG2						Mos					
Eff: 22-Aug-2019						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-72-9071	**Engine - HP Compressor - Install New Centrifugal Compressor Case (Impeller Shroud) PN 70041125-1 on AS907 Engine Models**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	17-Apr-2023				
Eff: 12-Jun-2018 Not Applicable	as per engine S/N					Hrs	97:47				
						Enc	64				
AS907-72-9071	**Engine - HP Compressor - Install New Centrifugal Compressor Case (Impeller Shroud) PN 70041125-1 on AS907 Engine Models**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	17-Apr-2023				
Eff: 12-Jun-2018 Not Applicable	as per engine S/N					Hrs	117:47				
						Enc	76				
AS907-72-9071 Rev 1	**Engine - HP Compressor - Install New Centrifugal Compressor Case (Impeller Shroud) PN 70041125-1, and PN 70041133-1, on AS907 Engine Models**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	17-Apr-2023				
Eff: 07-Dec-2018 Not Applicable	as per engine S/N					Hrs	97:47				
						Enc	64				
AS907-72-9071 Rev 1	**Engine - HP Compressor - Install New Centrifugal Compressor Case (Impeller Shroud) PN 70041125-1, and PN 70041133-1, on AS907 Engine Models**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	17-Apr-2023				
Eff: 07-Dec-2018 Not Applicable	as per engine S/N					Hrs	117:47				
						Enc	76				
AS907-72-9076	**Engine - Turbine Section - Install New Stage 1 Shroud Segments, PN 70041107-1, with HPT First Stage Seals, PN 70041109-1 and PN 70041110-1 on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	17-Apr-2023				
Eff: 07-Mar-2019 Not Applicable	as per engine S/N					Hrs	97:47				
						Enc	64				
AS907-72-9076	**Engine - Turbine Section - Install New Stage 1 Shroud Segments, PN 70041107-1, with HPT First Stage Seals, PN 70041109-1 and PN 70041110-1 on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 07-Mar-2019 Not Applicable	as per engine S/N					Hrs	117:47				
						Enc	76				
AS907-72-9076 Rev 1	**Engine - Turbine Section - Install New Stage 1 Shroud Segments, PN 70041107-1, with High Pressure Turbine (HPT) First Stage Seals, PN 70041109-1 and PN 70041110-1 on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	10-Apr-2023				
Eff: 17-Oct-2019 Complied With	AT MANUFACTURE					Hrs	84:18				
						Enc	54				
AS907-72-9076 Rev 1	**Engine - Turbine Section - Install New Stage 1 Shroud Segments, PN 70041107-1, with High Pressure Turbine (HPT) First Stage Seals, PN 70041109-1 and PN 70041110-1 on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	10-Apr-2023				
Eff: 17-Oct-2019 Complied With	AT MANUFACTURE					Hrs	104:18				
						Enc	66				
AS907-72-9076 Rev 3	**Engine - Turbine Section - Install New Stage 1 Shroud Segments, PN 70041107-1, with High Pressure Turbine (HPT) First Stage Seals, PN 70041109-1 and PN 70041110-1 on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	27-May-2024				
Eff: 08-Apr-2024 Not Applicable	as per engine S/N					Hrs	817:49				
						Enc	491				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-72-9076 Rev 3	**Engine - Turbine Section - Install New Stage 1 Shroud Segments, PN 70041107-1, with High Pressure Turbine (HPT) First Stage Seals, PN 70041109-1 and PN 70041110-1 on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	27-May-2024				
Eff: 08-Apr-2024 Not Applicable	as per engine S/N					Hrs	837:49				
						Enc	503				
AS907-72-9077	**Engine - Bypass Section - Install New Fan Rotor Assembly and Fan Stator Vane Assembly with Fan Stator Static Baffle on AS907-2-1G and AS907-3-1E Model Engines**							RE (-)		Category 3, Optional	
72 ENG1						Mos					
Eff: 03-Sep-2019 (AVG MAN HRS: 8)						Hrs					
						Enc					
AS907-72-9077	**Engine - Bypass Section - Install New Fan Rotor Assembly and Fan Stator Vane Assembly with Fan Stator Static Baffle on AS907-2-1G and AS907-3-1E Model Engines**							RE (-)		Category 3, Optional	
72 ENG2						Mos					
Eff: 03-Sep-2019 (AVG MAN HRS: 8)						Hrs					
						Enc					
AS907-72-9077 Rev 1	**Engine - Bypass Section - Install New Fan Rotor Assembly and Fan Stator Vane Assembly with Fan Stator Static Baffle on AS907-2-1A, AS907-2-1G, AS907-2-1S, and AS907-3-1E Model Engines**							RE (-)		Category 3	
72 ENG1						Mos	17-Apr-2023				
Eff: 23-Nov-2022 Not Applicable (AVG MAN HRS: 8)	as per engine S/N					Hrs	97:47				
						Enc	64				
AS907-72-9077 Rev 1	**Engine - Bypass Section - Install New Fan Rotor Assembly and Fan Stator Vane Assembly with Fan Stator Static Baffle on AS907-2-1A, AS907-2-1G, AS907-2-1S, and AS907-3-1E Model Engines**							RE (-)		Category 3	
72 ENG2						Mos	17-Apr-2023				
Eff: 23-Nov-2022 Not Applicable (AVG MAN HRS: 8)	as per engine S/N					Hrs	117:47				
						Enc	76				
AS907-72-9079	**Engine - Combustion Section - Install New Combustion Chamber Assembly, PN 3034088-6, on AS907 Model Engines**							RE (-)		Category 3	
72 ENG1						Mos	17-Apr-2023				
Eff: 18-Dec-2018 Not Applicable	as per engine S/N					Hrs	97:47				
						Enc	64				
AS907-72-9079	**Engine - Combustion Section - Install New Combustion Chamber Assembly, PN 3034088-6, on AS907 Model Engines**							RE (-)		Category 3	
72 ENG2						Mos	17-Apr-2023				
Eff: 18-Dec-2018 Not Applicable	as per engine S/N					Hrs	117:47				
						Enc	76				
AS907-72-9080	**Engine - Turbine Section - Install Improved No. 4 Roller Bearing PN 3035647-7 on AS907 Model Engines**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	17-Apr-2023				
Eff: 20-Sep-2018 Not Applicable (AVG MAN HRS: 74)	as per engine S/N					Hrs	97:47				
						Enc	64				
AS907-72-9080	**Engine - Turbine Section - Install Improved No. 4 Roller Bearing PN 3035647-7 on AS907 Model Engines**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	17-Apr-2023				
Eff: 20-Sep-2018 Not Applicable (AVG MAN HRS: 74)	as per engine S/N					Hrs	117:47				
						Enc	76				
AS907-72-9080 Rev 1	**Engine - Turbine Section - Install Improved No. 4 Roller Bearing, PN 3035647-7, on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	26-Jan-2023				
Eff: 22-Nov-2019 Complied With (AVG MAN HRS: 74)	AT MANUFACTURE					Hrs	0				
						Enc	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-72-9080 Rev 1	**Engine - Turbine Section - Install Improved No. 4 Roller Bearing, PN 3035647-7, on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	20-Jan-2023				
Eff: 22-Nov-2019 Complied With	AT MANUFACTURE					Hrs	0				
(AVG MAN HRS: 74)						Enc	0				
AS907-72-9081	**Engine - HP Compressor - Install Improved Compressor Stator Vanes PN 70040972-2, 70040973-3, 70040947-2, 70040899-3 and 70040036-5 on AS907 Model Engines**							RE (-)		Category 3, Optional	
72 ENG1						Mos					
Eff: 25-Sep-2018						Hrs					
(AVG MAN HRS: 175)						Enc					
AS907-72-9081	**Engine - HP Compressor - Install Improved Compressor Stator Vanes PN 70040972-2, 70040973-3, 70040947-2, 70040899-3 and 70040036-5 on AS907 Model Engines**							RE (-)		Category 3, Optional	
72 ENG2						Mos					
Eff: 25-Sep-2018						Hrs					
(AVG MAN HRS: 175)						Enc					
AS907-72-9081 Rev 1	**Engine - HP Compressor - Install Improved Compressor Stator Vanes PN 70040972-2, 70040973-3, 70040947-2, 70040899-3, 70040899-4, 70040036-5, and 70040036-6 on AS907 Model Engines**							RE (-)		Category 3, Optional	
72 ENG1						Mos	26-Jan-2023				
Eff: 22-Jan-2019 Complied With	AT MANUFACTURE					Hrs	0				
(AVG MAN HRS: 175)						Enc	0				
AS907-72-9081 Rev 1	**Engine - HP Compressor - Install Improved Compressor Stator Vanes PN 70040972-2, 70040973-3, 70040947-2, 70040899-3, 70040899-4, 70040036-5, and 70040036-6 on AS907 Model Engines**							RE (-)		Category 3, Optional	
72 ENG2						Mos	20-Jan-2023				
Eff: 22-Jan-2019 Complied With	AT MANUFACTURE					Hrs	0				
(AVG MAN HRS: 175)						Enc	0				
AS907-72-9082	**Engine - LP Turbine Section - Install Reworked or New Stage 2 Low Pressure Turbine (LPT) Rotor Assembly, PN 3035660-2, with Stage 2 LPT Blades, PN 3035602-2 and/or Reworked Stage 2 LPT Blades, PN 70041201-1, on AS907 Model Engines**							RE (-)		Category 2	
72 ENG1						Mos	17-Apr-2023				
Eff: 06-Jul-2020 Not Applicable	as per engine S/N					Hrs	97:47				
(AVG MAN HRS: 3)						Enc	64				
AS907-72-9082	**Engine - LP Turbine Section - Install Reworked or New Stage 2 Low Pressure Turbine (LPT) Rotor Assembly, PN 3035660-2, with Stage 2 LPT Blades, PN 3035602-2 and/or Reworked Stage 2 LPT Blades, PN 70041201-1, on AS907 Model Engines**							RE (-)		Category 2	
72 ENG2						Mos	17-Apr-2023				
Eff: 06-Jul-2020 Not Applicable	as per engine S/N					Hrs	117:47				
(AVG MAN HRS: 3)						Enc	76				
AS907-72-9084 Rev 1	**Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	17-Apr-2023				
Eff: 21-Feb-2020 Not Applicable	as per engine S/N					Hrs	97:47				
						Enc	64				
AS907-72-9084 Rev 1	**Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 21-Feb-2020 Not Applicable	as per engine S/N					Hrs	117:47				
						Enc	76				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-72-9084 Rev 2	**Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	17-Apr-2023				
Eff: 03-Apr-2020 Not Applicable	as per engine S/N					Hrs	97:47				
(AVG MAN HRS: 2)						Enc	64				
AS907-72-9084 Rev 2	**Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 03-Apr-2020 Not Applicable	as per engine S/N					Hrs	117:47				
(AVG MAN HRS: 2)						Enc	76				
AS907-72-9084 Rev 3	**Engine - Servicing - Reduce Time Interval for Oil Filter Replacement or Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	17-Apr-2023				
Eff: 26-Jun-2021 Not Applicable	as per engine S/N					Hrs	97:47				
(AVG MAN HRS: 2)						Enc	64				
AS907-72-9084 Rev 3	**Engine - Servicing - Reduce Time Interval for Oil Filter Replacement or Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 26-Jun-2021 Not Applicable	as per engine S/N					Hrs	117:47				
(AVG MAN HRS: 2)						Enc	76				
AS907-72-9084 Rev 3 Par. E.(2) Part 1	**Engine - Servicing - Reduce Time Interval for Oil Filter Replacement or Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components - (EEI) Download**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	17-Apr-2023				
Eff: 26-Jun-2021 Not Applicable	as per engine S/N					Hrs	97:47				
						Enc	64				
AS907-72-9084 Rev 3 Par. E.(2) Part 1	**Engine - Servicing - Reduce Time Interval for Oil Filter Replacement or Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components - (EEI) Download**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 26-Jun-2021 Not Applicable	as per engine S/N					Hrs	117:47				
						Enc	76				
AS907-72-9084 Rev 3 Par. E.(2) Part 2	**Engine - Servicing - Reduce Time Interval for Oil Filter Replacement or Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components - Oil Filter Analysis**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	17-Apr-2023				
Eff: 26-Jun-2021 Not Applicable	as per engine S/N					Hrs	97:47				
						Enc	64				
AS907-72-9084 Rev 3 Par. E.(2) Part 2	**Engine - Servicing - Reduce Time Interval for Oil Filter Replacement or Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components - Oil Filter Analysis**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 26-Jun-2021 Not Applicable	as per engine S/N					Hrs	117:47				
						Enc	76				
AS907-72-9085	**Engine - LP Turbine Section - Install Reworked or New Stage 3 Low Pressure Turbine (LPT) Rotor Assembly, PN 3035662-3, with Stage 3 LPT Blades, PN 3035609-3, and/or Reworked Stage 3 LPT Blades, PN 70041202-1, on AS907 Model Engines**							RE (-)		Category 2	
72 ENG1						Mos	17-Apr-2023				
Eff: 11-May-2021 Not Applicable	as per engine S/N					Hrs	97:47				
(AVG MAN HRS: 4)						Enc	64				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-72-9085	**Engine - LP Turbine Section - Install Reworked or New Stage 3 Low Pressure Turbine (LPT) Rotor Assembly, PN 3035662-3, with Stage 3 LPT Blades, PN 3035609-3, and/or Reworked Stage 3 LPT Blades, PN 70041202-1, on AS907 Model Engines**							RE (-)		Category 2	
72 ENG2						Mos	17-Apr-2023				
Eff: 11-May-2021 Not Applicable	as per engine S/N					Hrs	117:47				
(AVG MAN HRS: 4)						Enc	76				
AS907-72-9086	**Engine - LP Turbine Section - Install Reworked or New Stage 1 Low Pressure Turbine (LPT) Rotor Assembly, PN 3035692-2, with Stage 1 LPT Blades, PN 3035693-2, and/or Reworked Stage 1 LPT Blades, PN 70041200-1, on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	17-Apr-2023				
Eff: 14-May-2021 Not Applicable	as per engine S/N					Hrs	97:47				
						Enc	64				
AS907-72-9086	**Engine - LP Turbine Section - Install Reworked or New Stage 1 Low Pressure Turbine (LPT) Rotor Assembly, PN 3035692-2, with Stage 1 LPT Blades, PN 3035693-2, and/or Reworked Stage 1 LPT Blades, PN 70041200-1, on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 14-May-2021 Not Applicable	as per engine S/N					Hrs	117:47				
						Enc	76				
AS907-72-9090	**Engine - LP Turbine Section - Install New No. 4 Bearing Carbon Seal on AS907 Model Engines**							RE (-)		Category 3, Optional	
72 ENG1						Mos					
Eff: 28-Mar-2020						Hrs					
						Enc					
AS907-72-9090	**Engine - LP Turbine Section - Install New No. 4 Bearing Carbon Seal on AS907 Model Engines**							RE (-)		Category 3, Optional	
72 ENG2						Mos					
Eff: 28-Mar-2020						Hrs					
						Enc					
AS907-72-9090 Rev 1	**Engine - LP Turbine Section - Install New No. 4 Bearing Carbon Seal on AS907 Model Engines**							RE (-)		Category 3, Optional	
72 ENG1						Mos					
Eff: 16-Dec-2020						Hrs					
						Enc					
AS907-72-9090 Rev 1	**Engine - LP Turbine Section - Install New No. 4 Bearing Carbon Seal on AS907 Model Engines**							RE (-)		Category 3, Optional	
72 ENG2						Mos					
Eff: 16-Dec-2020						Hrs					
						Enc					
AS907-72-9090 Rev 2	**Engine - LP Turbine Section - Install New No. 4 Bearing Carbon Seal on AS907 Model Engines (Inactive for Further Accomplishment)**							RE (-)		Category 3, Optional	
72 ENG1						Mos					
Eff: 25-Nov-2021						Hrs					
						Enc					
AS907-72-9090 Rev 2	**Engine - LP Turbine Section - Install New No. 4 Bearing Carbon Seal on AS907 Model Engines (Inactive for Further Accomplishment)**							RE (-)		Category 3, Optional	
72 ENG2						Mos					
Eff: 25-Nov-2021						Hrs					
						Enc					
AS907-72-9092	**Engine - Compressor Section - Installation of Improved Stage 2 Compressor Stator Vane, PN 70040972-3 and 70040035-3 and Enhanced Inspection with Reporting for the Stage 2 Compressor Stator Vane and Stage 3 Compressor Stator Vane of Select Identified Part Numbers**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	17-Apr-2023				
Eff: 16-Jun-2021 Not Applicable	as per engine S/N					Hrs	97:47				
(AVG MAN HRS: 2)						Enc	64				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-72-9092	**Engine - Compressor Section - Installation of Improved Stage 2 Compressor Stator Vane, PN 70040972-3 and 70040035-3 and Enhanced Inspection with Reporting for the Stage 2 Compressor Stator Vane and Stage 3 Compressor Stator Vane of Select Identified Part Numbers**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 16-Jun-2021 Not Applicable	as per engine S/N					Hrs	117:47				
(AVG MAN HRS: 2)						Enc	76				
AS907-72-9094	**Engine - Turbine Section - Install Improved No. 4 Bearing Carbon Seal, PN 70041289-2, on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	17-Apr-2023				
Eff: 01-Feb-2021 Not Applicable	as per engine S/N					Hrs	97:47				
						Enc	64				
AS907-72-9094	**Engine - Turbine Section - Install Improved No. 4 Bearing Carbon Seal, PN 70041289-2, on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 01-Feb-2021 Not Applicable	as per engine S/N					Hrs	117:47				
						Enc	76				
AS907-72-9096	**Engine - Turbine Section - Install New No. 5 Segmented Carbon Seal, PN 3035687-3, and Packing, PN AS3209-163, on all AS907 Engine Models**							RE (-)		Cat. 3 - Optional	
72 ENG1						Mos					
Eff: 04-Jul-2022						Hrs					
						Enc					
AS907-72-9096	**Engine - Turbine Section - Install New No. 5 Segmented Carbon Seal, PN 3035687-3, and Packing, PN AS3209-163, on all AS907 Engine Models**							RE (-)		Cat. 3 - Optional	
72 ENG2						Mos					
Eff: 04-Jul-2022						Hrs					
						Enc					
D201603000064	**AS907 Engine Ground Start Procedure Following Shutdown (Quick Turn Around)**							RE (-)		Service Information Letter	
72 ENG1						Mos					
Eff: 17-May-2016						Hrs					
						Enc					
D201603000064	**AS907 Engine Ground Start Procedure Following Shutdown (Quick Turn Around)**							RE (-)		Service Information Letter	
72 ENG2						Mos					
Eff: 17-May-2016						Hrs					
						Enc					
Engine 1	**Honeywell - AS907-2-1G**							RE (-)			
72 A/F						Mos	09-Feb-2023				
3030002-2 P130647	Time at install:					Hrs	24:24				
						Ldg	7				
Engine 2	**Honeywell - AS907-2-1G**							RE (-)			
72 A/F						Mos	09-Feb-2023				
3030002-2 P130648	Time at install:					Hrs	24:24				
						Ldg	7				
2023-24-04	**Engine Fuel and Control - Electronic Control Unit (ECU) Software Version - Replacement**							RE (-)		Mandatory	
73 ENG1						Mos	24-Jan-2024				
Eff: 10-Jan-2024 Not Applicable						Hrs					
(UPDATE NOTE: N/A as per installed ECU on OK_GTX) (NOTE: APPLICABILITY: This AD applies to Honeywell International Inc. (Honeywell) Model AS907-1-1A and AS907-2-1G engines.)						Enc					
2023-24-04	**Engine Fuel and Control - Electronic Control Unit (ECU) Software Version - Replacement**							RE (-)		Mandatory	
73 ENG2						Mos	24-Jan-2024				
Eff: 10-Jan-2024 Not Applicable						Hrs					
(UPDATE NOTE: N/A as per installed ECU on OK_GTX) (NOTE: APPLICABILITY: This AD applies to Honeywell International Inc. (Honeywell) Model AS907-1-1A and AS907-2-1G engines.)						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2023-24-04 Par. (g)(2)	**Engine Fuel and Control - Electronic Control Unit (ECU) Software Version - Replacement - Model AS907-2-1G Engines**							RE (-)		Mandatory	
73 ENG1						Mos	24-Jan-2024				
Eff: 10-Jan-2024 Not Applicable						Hrs					
	(UPDATE NOTE: N/A as per installed ECU on OK_GTX)					Enc					
2023-24-04 Par. (g)(2)	**Engine Fuel and Control - Electronic Control Unit (ECU) Software Version - Replacement - Model AS907-2-1G Engines**							RE (-)		Mandatory	
73 ENG2						Mos	24-Jan-2024				
Eff: 10-Jan-2024 Not Applicable						Hrs					
	(UPDATE NOTE: N/A as per installed ECU on OK_GTX)					Enc					
731015	**Engine Feed Fuel Shut-off Valve - Closing / Opening Operation**							RE (-)			
73 A/F						Mos					
						Hrs					
Mfg#:73-10-00						Ldg					
AS907-73-9007	**Engine Fuel and Control - Distribution - Replace Non-Conforming Fuel Hose Assemblies on AS907 Engine Models**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos	10-Feb-2023				
Eff: 14-Aug-2018 Not Applicable	PER ENGINE PART NUMBER					Hrs					
						Enc					
(AVG MAN HRS: 18)											
AS907-73-9007	**Engine Fuel and Control - Distribution - Replace Non-Conforming Fuel Hose Assemblies on AS907 Engine Models**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos	10-Feb-2023				
Eff: 14-Aug-2018 Not Applicable	PER ENGINE PART NUMBER					Hrs					
						Enc					
(AVG MAN HRS: 18)											
740001	**Engine Ignition System - Operational Test**							RE (-)			
74 ENG1						Mos	02-Mar-2023				
						Hrs	29:48				
Mfg#:74-00-00						Enc	17				
740001	**Engine Ignition System - Operational Test**							RE (-)			
74 ENG2						Mos	02-Mar-2023				
						Hrs	09:48				
Mfg#:74-00-00						Enc	5				
AS907-75-9005	**Air - Cooling - Install New Buffer Air Metal Tube Assemblies PN 70040490-1 for AS907 Model Engines**							RE (-)		Cat.3-Product Improvement	
75 ENG1						Mos	10-Feb-2023				
Eff: 05-Sep-2018 Not Applicable	PER ENGINE PART NUMBER					Hrs					
						Enc					
AS907-75-9005	**Air - Cooling - Install New Buffer Air Metal Tube Assemblies PN 70040490-1 for AS907 Model Engines**							RE (-)		Cat.3-Product Improvement	
75 ENG2						Mos	10-Feb-2023				
Eff: 05-Sep-2018 Not Applicable	PER ENGINE PART NUMBER					Hrs					
						Enc					
280-76-089	**Engine Controls - Replacement Of The Existing Throttle Quadrant Assembly P/N 30P551100003-001 With New Throttle Quadrant Assembly P/N 30P551100004-001 (MODG25-20051)**							RE (-)		Recommended	
76 A/F						Mos	10-Feb-2023				
Eff: 19-Jun-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-76-111	**Engine Controls - Power Controls - Install Software Version 90721G0201 In Engine Electronic Control Unit (ECU) (MODG25-20061)**							RE (-)		Recommended	
76 A/F						Mos	10-Feb-2023				
Eff: 17-Jan-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-76-128	**Engine Controls (ATA 76) - Power Controls - Install Improved Electronic Control Unit (ECU) P/N 2119576-3202 on AS907-2-1G Model Engines**							RE (-)		Optional	
76 A/F						Mos					
Eff: 06-Oct-2020						Hrs					
(AVG MAN HRS: 18)						Ldg					
280-76-128 Rev 1	**Engine Controls (ATA 76) - Power Controls - Install Improved Electronic Control Unit (ECU) P/N 2119576-3202 on AS907-2-1G Model Engines**							RE (-)		Optional	
76 A/F						Mos					
Eff: 21-Feb-2023						Hrs					
(AVG MAN HRS: 18)						Ldg					
280-76-219 (Left)	**Engine Controls - Power Controls - Replacement of the Overspeed Shutoff Detector (OSSD) P/N 3034256-2 With New OSSD P/N 3034256-4**							RE (-)		Recommended	
76 A/F						Mos	10-Feb-2023				
Eff: 19-Feb-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-76-219 (Right)	**Engine Controls - Power Controls - Replacement of the Overspeed Shutoff Detector (OSSD) P/N 3034256-2 With New OSSD P/N 3034256-4**							RE (-)		Recommended	
76 A/F						Mos	10-Feb-2023				
Eff: 19-Feb-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280-76-267	**Throttle Quadrant Assembly (TQA) - Replacement / Upgrade**							RE (-)		Recommended	
76 A/F						Mos	10-Feb-2023				
Eff: 22-Feb-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs					
(AVG MAN HRS: 37)						Ldg					
AS907-76-9014 Rev 2	**Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines**							RE (-)		Cat.3-Product Improvement	
76 ENG1						Mos	10-Feb-2023				
Eff: 30-Jan-2018 Not Applicable						Hrs					
(AVG MAN HRS: 6) (UPDATE NOTE: NA by ENG Part Number)						Enc					
AS907-76-9014 Rev 2	**Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines**							RE (-)		Cat.3-Product Improvement	
76 ENG2						Mos	10-Feb-2023				
Eff: 30-Jan-2018 Not Applicable						Hrs					
(AVG MAN HRS: 6) (UPDATE NOTE: NA by ENG Part Number)						Enc					
AS907-76-9014 Rev 3	**Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines**							RE (-)		Category 3, Optional	
76 ENG1						Mos					
Eff: 22-Nov-2019						Hrs					
(AVG MAN HRS: 6)						Enc					
AS907-76-9014 Rev 3	**Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines**							RE (-)		Category 3, Optional	
76 ENG2						Mos					
Eff: 22-Nov-2019						Hrs					
(AVG MAN HRS: 6)						Enc					
AS907-76-9014 Rev 4	**Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines**							RE (-)		Category 2	
76 ENG1						Mos	17-Apr-2023				
Eff: 04-Aug-2020 Not Applicable	as per engine S/N					Hrs	97:47				
(AVG MAN HRS: 6)						Enc	64				
AS907-76-9014 Rev 4	**Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines**							RE (-)		Category 2	
76 ENG2						Mos	17-Apr-2023				
Eff: 04-Aug-2020 Not Applicable	as per engine S/N					Hrs	117:47				
(AVG MAN HRS: 6)						Enc	76				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-76-9014 Rev 5	**Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines**							RE (-)		Category 2, Recommended	
76 ENG1						Mos	17-Apr-2023				
Eff: 09-Sep-2022 Not Applicable	as per engine S/N					Hrs	97:47				
(AVG MAN HRS: 6)						Enc	64				
AS907-76-9014 Rev 5	**Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines**							RE (-)		Category 2, Recommended	
76 ENG2						Mos	17-Apr-2023				
Eff: 09-Sep-2022 Not Applicable	as per engine S/N					Hrs	117:47				
(AVG MAN HRS: 6)						Enc	76				
AS907-76-9014 Rev 6	**Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines**							RE (-)		Cat. 2 - Recommended	
76 ENG1						Mos	10-Apr-2023				
Eff: 10-Oct-2022 Not Applicable	per S/N					Hrs	84:18				
(AVG MAN HRS: 6)						Enc	54				
AS907-76-9014 Rev 6	**Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines**							RE (-)		Cat. 2 - Recommended	
76 ENG2						Mos	10-Apr-2023				
Eff: 10-Oct-2022 Not Applicable	per S/N					Hrs	104:18				
(AVG MAN HRS: 6)						Enc	66				
AS907-76-9021 Rev 1	**ENGINE CONTROLS - POWER CONTROLS - Apply Sealant to Prevent Water Entry into Electronic Control Unit (ECU) on AS907 Model Engines**							RE (-)			
76 ENG1						Mos	26-Jan-2023				
Eff: 13-May-2016 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
AS907-76-9021 Rev 1	**ENGINE CONTROLS - POWER CONTROLS - Apply Sealant to Prevent Water Entry into Electronic Control Unit (ECU) on AS907 Model Engines**							RE (-)			
76 ENG2						Mos	20-Jan-2023				
Eff: 13-May-2016 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
AS907-76-9023	**Engine Controls - Power Controls - Install New Anti-Ice Dual Pressure Switch Bracket, P/N 3038453-8, on AS907 Model Engines**							RE (-)		Cat.3-Product Improvement	
76 ENG1						Mos	17-Apr-2023				
Eff: 20-Dec-2017 Not Applicable	as per engine S/N					Hrs	97:47				
						Enc	64				
AS907-76-9023	**Engine Controls - Power Controls - Install New Anti-Ice Dual Pressure Switch Bracket, P/N 3038453-8, on AS907 Model Engines**							RE (-)		Cat.3-Product Improvement	
76 ENG2						Mos	17-Apr-2023				
Eff: 20-Dec-2017 Not Applicable	as per engine S/N					Hrs	117:47				
						Enc	76				
AS907-76-9023 Rev 1	**Engine Controls - Power Controls - Install New Anti-Ice Dual Pressure Switch Bracket, PN 3038453-8, on AS907 Model Engines**							RE (-)		Category 3, Optional	
76 ENG1						Mos	26-Jan-2023				
Eff: 13-May-2020 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
AS907-76-9023 Rev 1	**Engine Controls - Power Controls - Install New Anti-Ice Dual Pressure Switch Bracket, PN 3038453-8, on AS907 Model Engines**							RE (-)		Category 3, Optional	
76 ENG2						Mos	20-Jan-2023				
Eff: 13-May-2020 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-76-9024	**Engine Controls - Power Controls - New P3 Tube Assemblies PN 3038480-4 and PN 3038481-4 on AS907 Model Engines**							RE (-)		Category 3, Optional	
76 ENG1						Mos	26-Jan-2023				
Eff: 11-Feb-2019 Complied With	AT MANUFACTURE					Hrs	0				
(AVG MAN HRS: 2)						Enc	0				
AS907-76-9024	**Engine Controls - Power Controls - New P3 Tube Assemblies PN 3038480-4 and PN 3038481-4 on AS907 Model Engines**							RE (-)		Category 3, Optional	
76 ENG2						Mos	20-Jan-2023				
Eff: 11-Feb-2019 Complied With	AT MANUFACTURE					Hrs	0				
(AVG MAN HRS: 2)						Enc	0				
AS907-76-9025	**Install Improved Electronic Control Units on AS907 Model Engines**							RE (-)		Cat.3-Product Improvement	
76 ENG1						Mos	26-Jan-2023				
Eff: 18-Apr-2018 Complied With	AT MANUFACTURE					Hrs	0				
(AVG MAN HRS: 2)						Enc	0				
AS907-76-9025	**Install Improved Electronic Control Units on AS907 Model Engines**							RE (-)		Cat.3-Product Improvement	
76 ENG2						Mos	20-Jan-2023				
Eff: 18-Apr-2018 Complied With	AT MANUFACTURE					Hrs	0				
(AVG MAN HRS: 2)						Enc	0				
AS907-76-9032	**Engine Controls - Power Controls - Tube Assembly, Metal P3 Air TEE to Channel A PN 3038480-4 and Tube Assembly, Metal P3 Air TEE to Channel B PN 3038481-4 - Optional Removal of MIL-STD-1247 Function Tape as Necessary**							RE (-)		Category 3, Optional	
76 ENG1						Mos					
Eff: 15-Apr-2021						Hrs					
						Enc					
AS907-76-9032	**Engine Controls - Power Controls - Tube Assembly, Metal P3 Air TEE to Channel A PN 3038480-4 and Tube Assembly, Metal P3 Air TEE to Channel B PN 3038481-4 - Optional Removal of MIL-STD-1247 Function Tape as Necessary**							RE (-)		Category 3, Optional	
76 ENG2						Mos					
Eff: 15-Apr-2021						Hrs					
						Enc					
772001	**EGT Probes - Operational Test**							RE (-)			
77 ENG1						Mos					
						Hrs					
Mfg#:77-20-01						Enc					
772001	**EGT Probes - Operational Test**							RE (-)			
77 ENG2						Mos					
						Hrs					
Mfg#:77-20-01						Enc					
AS907-77-9002	**Engine Indicating - Vibration - Install a Bracket, PN MS9593-562, and Loop Clamp, PN 211-592-9004, to Hold the Cable of the Vibration Sensor Transducer on AS907 Model Engines**							RE (-)		Cat.3-Product Improvement	
77 ENG1						Mos	17-Apr-2023				
Eff: 23-Jan-2019 Not Applicable	as per engine S/N					Hrs	97:47				
(AVG MAN HRS: 2)						Enc	64				
AS907-77-9002	**Engine Indicating - Vibration - Install a Bracket, PN MS9593-562, and Loop Clamp, PN 211-592-9004, to Hold the Cable of the Vibration Sensor Transducer on AS907 Model Engines**							RE (-)		Cat.3-Product Improvement	
77 ENG2						Mos	17-Apr-2023				
Eff: 23-Jan-2019 Not Applicable	as per engine S/N					Hrs	117:47				
(AVG MAN HRS: 2)						Enc	76				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-78-022	**Exhaust - Thrust Reverser (TR) - Pivot Door Kicker Plate Modification / Strap Repair (MODG25-00222)**							RE (-)		Recommended	
78 A/F						Mos	10-Feb-2023				
Eff: 12-Dec-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
783005	**Thrust Reverser (Left) - Operational Test**							RE (-)			
78 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:78-30-00-AT						Ldg	10				
783006	**Thrust Reverser (Right) - Operational Test**							RE (-)			
78 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Mfg#:78-30-00-AT						Ldg	10				
783007	**Thrust Reverser (Left) - Recovery Procedure**							RE (-)			
78 A/F						Mos					
						Hrs					
(SOURCE: 78-30-00)						Ldg					
783008	**Thrust Reverser (Right) - Recovery Procedure**							RE (-)			
78 A/F						Mos					
						Hrs					
(SOURCE: 78-30-00)						Ldg					
783113	**Pivot Doors (Left) - Opening / Closing**							RE (-)			
78 A/F						Mos					
						Hrs					
Mfg#:78-31-00						Ldg					
783114	**Pivot Doors (Right) - Opening / Closing**							RE (-)			
78 A/F						Mos					
						Hrs					
Mfg#:78-31-00						Ldg					
783207	**Thrust Reverser Electro-Hydraulic Primary Lock (Left) - Operational Test**							RE (-)			
78 A/F						Mos					
						Hrs					
Mfg#:78-32-06-AT						Ldg					
783208	**Thrust Reverser Electro-Hydraulic Primary Lock (Right) - Operational Test**							RE (-)			
78 A/F						Mos					
						Hrs					
Mfg#:78-32-06-AT						Ldg					
792105	**Oil Filter - Discard**							RE (-)			
79 ENG1						Mos					
3038727-3						Hrs					
22-162287-03389						Enc					
Mfg#:79-21-02-RI											
792105	**Oil Filter - Discard**							RE (-)			
79 ENG2						Mos					
3038727-3						Hrs					
22-162287-03390						Enc					
Mfg#:79-21-02-RI											

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-79-9007 Rev 3	**Rework Oil Filler Cap Assembly Part No. 3036061-3 to Prevent Chain Interference During Oil Supply Servicing**							RE (-)		Cat.2-Reliability	
79 ENG1						Mos	26-Jan-2023				
Eff: 29-Jan-2018 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
AS907-79-9007 Rev 3	**Rework Oil Filler Cap Assembly Part No. 3036061-3 to Prevent Chain Interference During Oil Supply Servicing**							RE (-)		Cat.2-Reliability	
79 ENG2						Mos	20-Jan-2023				
Eff: 29-Jan-2018 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
AS907-79-9010	**Oil - Distribution - Replace Non-Conforming Oil Hose and Tube Assemblies on AS907 Engine Models**							RE (-)		Cat.2-Reliability	
79 ENG1						Mos	10-Feb-2023				
Eff: 28-Aug-2018 Not Applicable	PER ENGINE PART NUMBER					Hrs					
(AVG MAN HRS: 2)						Enc					
AS907-79-9010	**Oil - Distribution - Replace Non-Conforming Oil Hose and Tube Assemblies on AS907 Engine Models**							RE (-)		Cat.2-Reliability	
79 ENG2						Mos	10-Feb-2023				
Eff: 28-Aug-2018 Not Applicable	PER ENGINE PART NUMBER					Hrs					
(AVG MAN HRS: 2)						Enc					
AS907-79-9012	**Oil - Distribution - Replace Lubricating Pump, PN 3038704-3 or PN 3038704-5 with PN 3038704-6**							RE (-)		Category 3, Optional	
79 ENG1						Mos					
Eff: 18-Feb-2019						Hrs					
(AVG MAN HRS: 6)						Enc					
AS907-79-9012	**Oil - Distribution - Replace Lubricating Pump, PN 3038704-3 or PN 3038704-5 with PN 3038704-6**							RE (-)		Category 3, Optional	
79 ENG2						Mos					
Eff: 18-Feb-2019						Hrs					
(AVG MAN HRS: 6)						Enc					
AS907-79-9012 Rev 1	**Oil - Distribution - Replace Lubricating Pump, PN 3038704-3 or PN 3038704-5 with PN 3038704-6**							RE (-)		Category 3, Optional	
79 ENG1						Mos	26-Jan-2023				
Eff: 09-May-2019 Complied With	AT MANUFACTURE					Hrs	0				
(AVG MAN HRS: 6)						Enc	0				
AS907-79-9012 Rev 1	**Oil - Distribution - Replace Lubricating Pump, PN 3038704-3 or PN 3038704-5 with PN 3038704-6**							RE (-)		Category 3, Optional	
79 ENG2						Mos	20-Jan-2023				
Eff: 09-May-2019 Complied With	AT MANUFACTURE					Hrs	0				
(AVG MAN HRS: 6)						Enc	0				
949001	**Brake Control Unit (Retrofit Program) (Cancelled)**							RE (-)			
94 A/F						Mos					
						Hrs					
						Ldg					
981060	**SB 280-34-106 Navigation (ATA 34) - Installation Of Rockwell Collins Avionics Software Ver V3.6 Configuration**							RE (-)		Mandatory	
98 A/F						Mos	17-Apr-2023				
Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	122:11				
						Ldg	69				
D202011001451 Rev 2	**Thrust Reverser Unit (TRU) - MAPAERO Overview**							RE (-)		Service Information Letter	
100 ENG1						Mos					
Eff: 13-Jul-2022						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
D202011001451 Rev 2	**Thrust Reverser Unit (TRU) - MAPAERO Overview**							RE (-)		Service Information Letter	
100 ENG2						Mos					
Eff: 13-Jul-2022						Hrs					
						Enc					
G25-02030	**Med Gooseneck Bolt - New Material Due Obsolesence, Modification**							RE (-)			
100 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-07339	**G25-07339, Modification**							RE (-)			
100 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20183	**G25-20183, Modification**							RE (-)			
100 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20188	**G25-20188, Modification**							RE (-)			
100 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20194	**G25-20194, Modification**							RE (-)			
100 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20197	**G25-20197, Modification**							RE (-)			
100 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20200	**Aft Press BH Smoke Evacuation Tube Sponge Ring - Alternate Material, Modification**							RE (-)			
100 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20202	**Waste Drain Valve - New Manufacturer - Improved Obtainability, Modification**							RE (-)			
100 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20209	**G25-20209, Modification**							RE (-)			
100 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
▼ 1. RE 1 Mos, 200 Hrs											
457601	**Engine FADEC - Data Download**							RE			
45 A/F						Mos	25-Aug-2024	1		25-Sep-2024	15 Days
						Hrs	1045:40	200		1245:40	187:40 Hrs
Mfg#:45-76-00						Ldg	614				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 1. RE 10 Yrs											
262133	**Fire Extinguishing Bottle Cartridge (Left Cartridge) - Discard**							RE		05-10-00 Time Limits	
26 A/F	Left Bottle					Yrs		10		31-Jan-2032	7.4 Years
446582-3						Hrs					
AGE0730						Ldg					
Manufactured Date 31-Jan-2022											
ATA Ref:26-21-02, MRB Ref:26-20-00/02, MRB Ref:26-20-00/03 (SOURCE: G280 AMM) (NOTE: NOTE: 10 years from date of manufacture.)											
262134	**Fire Extinguishing Bottle Cartridge (Right Cartridge) - Discard**							RE		05-10-00 Time Limits	
26 A/F	Left Bottle					Yrs		10		31-Jan-2032	7.4 Years
446582-2						Hrs					
AGF0488						Ldg					
Manufactured Date 31-Jan-2022											
ATA Ref:26-21-02, MRB Ref:26-20-00/02, MRB Ref:26-20-00/03 (SOURCE: G280 AMM) (NOTE: NOTE: 10 years from date of manufacture.)											
262135	**Fire Extinguishing Bottle Cartridge (Left Cartridge) - Discard**							RE		05-10-00 Time Limits	
26 A/F	Right Bottle					Yrs		10		31-Jan-2032	7.4 Years
446582-3						Hrs					
AGE0735						Ldg					
Manufactured Date 31-Jan-2022											
ATA Ref:26-21-02, MRB Ref:26-20-00/02, MRB Ref:26-20-00/03 (SOURCE: G280 AMM) (NOTE: NOTE: 10 years from date of manufacture.)											
262136	**Fire Extinguishing Bottle Cartridge (Right Cartridge) - Discard**							RE		05-10-00 Time Limits	
26 A/F	Right Bottle					Yrs		10		31-Jan-2032	7.4 Years
446582-2						Hrs					
AGF0499						Ldg					
Manufactured Date 31-Jan-2022											
ATA Ref:26-21-02, MRB Ref:26-20-00/02, MRB Ref:26-20-00/03 (SOURCE: G280 AMM) (NOTE: NOTE: 10 years from date of manufacture.)											
262137	**Fire Extinguishing Bottle Cartridge (APU Cartridge) - Discard**							RE		05-10-00 Time Limits	
26 A/F	Right Bottle					Yrs		10		31-Jan-2032	7.4 Years
446582-1						Hrs					
AGE1742						Ldg					
Manufactured Date 31-Jan-2022											
ATA Ref:26-21-02, MRB Ref:26-20-00/02, MRB Ref:26-20-00/03 (SOURCE: G280 AMM) (NOTE: NOTE: 10 years from date of manufacture.)											
262307	**Engine Fire Extinguishing Double Check Tee Valve - Detailed Inspection**							RE		05-20-00 Scheduled Maintenance Checks	
26 A/F						Yrs		10		31-Mar-2033	8.6 Years
						Hrs					
ATA Ref:26-23-01, MRB Ref:26-20-00-07 (SOURCE: G280 AMM) (NOTE: At fire bottle discharge, excluding thermal discharge not to exceed 10 years.)						Ldg					
262308	**Engine Fire Extinguishing Double Check Tee Valve - Detailed Inspection**							RE		05-20-00 Scheduled Maintenance Checks	
26 A/F						Yrs		10		31-Mar-2033	8.6 Years
						Hrs					
ATA Ref:26-23-01, MRB Ref:26-20-00-07 (SOURCE: G280 AMM) (NOTE: At fire bottle discharge, excluding thermal discharge not to exceed 10 years.)						Ldg					
▼ 1. RE 1000 Hrs											
121403	**Engine Oil - Drain and Discard**							RE		05-20-00 Scheduled Maintenance Checks	**≈02-Dec-2025**
12 ENG1						Mos	26-Jul-2024				
						Hrs	943:01	1,000	-/+50	1943:01	909:25 Hrs (+50)
ATA Ref:12-14-00, MRB Ref:79-20-00/02, MRB Ref:79-20-00/03 (SOURCE: G280 AMM)						Enc	557				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
121403		**Engine Oil - Drain and Discard**							RE	05-20-00 Scheduled Maintenance Checks		**≈22-Dec-2025**
	12 ENG2						Mos	26-Jul-2024				
							Hrs	963:01	1,000	-/+50	2000	946:24 Hrs (+50)
		ATA Ref:12-14-00, MRB Ref:79-20-00/02, MRB Ref:79-20-00/03 (Tol. Adjustment: 37 Hrs) (SOURCE: G280 AMM)					Enc	569				
122301		**Flaps Ballnut (Left) - Lubrication**							RE	05-20-00 Scheduled Maintenance Checks		**≈02-Dec-2025**
	12 A/F						Mos	26-Jul-2024				
							Hrs	967:25	1,000	-/+50	1967:25	909:25 Hrs (+50)
		ATA Ref:12-23-00, MRB Ref:27-50-00/02 (SOURCE: G280 AMM)					Ldg	562				
122302		**Flaps Ballnut (Right) - Lubrication**							RE	05-20-00 Scheduled Maintenance Checks		**≈02-Dec-2025**
	12 A/F						Mos	26-Jul-2024				
							Hrs	967:25	1,000	-/+50	1967:25	909:25 Hrs (+50)
		ATA Ref:12-23-00, MRB Ref:27-50-00/02 (SOURCE: G280 AMM)					Ldg	562				
213103		**Cabin Altitude Limit Warning - Functional Check**							RE		05-10-10 CMR	**≈02-Dec-2025**
	21 A/F						Mos	26-Jul-2024				
							Hrs	967:25	1,000		1967:25	909:25 Hrs
		ATA Ref:21-31-00, CMR Ref:21-30-03 (SOURCE: G280 AMM) (NOTE: CMR (*) - The task and interval specified are mandatory and cannot be changed, escalated or deleted without the concurrence of the Civil Aviation Authority of Israel (CAAI).)					Ldg	562				
213201		**Alternate Air Pressurization System - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		**≈02-Dec-2025**
	21 A/F						Mos	26-Jul-2024				
							Hrs	967:25	1,000	-/+50	1967:25	909:25 Hrs (+50)
		ATA Ref:21-32-00, MRB Ref:21-10-00-02 (SOURCE: G280 AMM)					Ldg	562				
243203		**APU Starter-Generator - Restore**							RE		05-10-00 Time Limits	**≈14-Sep-2025**
	24 APU1						Mos					
	G3666-400						Hrs		1,000		1000	371 Hrs
	2144B						APUS					
		ATA Ref:24-32-01, MRB Ref:24-30-00/03 (SOURCE: G280 AMM)										
262102		**APU Fire Extinguishing System - Functional Check (**CMR)**							RE	05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks		**≈19-Dec-2025**
	26 A/F						Mos	26-Jul-2024				
							Hrs	967:25	1,000	-/+50	2000	942 Hrs (+50)
		ATA Ref:26-21-00, CMR Ref:26-00-03 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM) (NOTE: Accomplish at 1000 flight hours or 6A, whichever occurs first. (1)Task satisfies the Fuel System Airworthiness Limitations Inspections requirement.)					Ldg	562				
276004		**Roll Assist Disconnect Switch - Operational Check (*CMR)**							RE		05-10-10 CMR	**≈02-Dec-2025**
	27 A/F						Mos	26-Jul-2024				
							Hrs	967:25	1,000	-/+50	1967:25	909:25 Hrs (+50)
		ATA Ref:27-60-00, CMR Ref:27-10-02 (SOURCE: G280 AMM)					Ldg	562				
321009		**Main Landing Gear and Doors (Left) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈19-Dec-2025**
	32 A/F						Mos	26-Jul-2024				
							Hrs	967:25	1,000	-/+50	2000	942 Hrs (+50)
		ATA Ref:32-10-00, MRB Ref:32-10-00/02, MRB Ref:32-10-00/04, MRB Ref:32-10-00/06, MRB Ref:32-10-00/07, MRB Ref:32-10-00/08 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)					Ldg	562				
321010		**Main Landing Gear and Doors (Right) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈19-Dec-2025**
	32 A/F						Mos	26-Jul-2024				
							Hrs	967:25	1,000	-/+50	2000	942 Hrs (+50)
		ATA Ref:32-10-00, MRB Ref:32-10-00/02, MRB Ref:32-10-00/04, MRB Ref:32-10-00/06, MRB Ref:32-10-00/07, MRB Ref:32-10-00/08 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)					Ldg	562				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
322005		**Nose Landing Gear and Doors - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈19-Dec-2025**
	32 A/F						Mos	26-Jul-2024				
							Hrs	967:25	1,000	-/+50	2000	942 Hrs (+50)
		ATA Ref:32-20-00, MRB Ref:32-20-00/02, MRB Ref:32-20-00/03, MRB Ref:32-20-00/04, MRB Ref:32-20-00/06 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)					Ldg	562				
492601		**APU Gearbox - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Sep-2025**
	49 APU1						Mos					
							Hrs		1,000	-/+50	1000	371 Hrs (+50)
		ATA Ref:49-26-00, MRB Ref:49-26-00/01 (SOURCE: G280 AMM)					APUS					
531503		**Fuselage Drain Valve, Frame 27 - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		**≈19-Dec-2025**
	53 A/F						Mos	26-Jul-2024				
							Hrs	967:25	1,000	-/+50	2000	942 Hrs (+50)
		ATA Ref:53-00-00, MRB Ref:53-00-00-02 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM) (NOTE: Accomplish at 2A Check, not to exceed 1000 hours from date of Revision 8 (see List of Revisions) and every 2A thereafter.)					Ldg	562				
712005		**Engine Mounts (Left) - General Visual Inspection (*CMR)**							RE		05-10-10 CMR	**≈19-Dec-2025**
	71 A/F						Mos	26-Jul-2024				
							Hrs	967:25	1,000	-/+50	2000	942 Hrs (+50)
		ATA Ref:71-20-00, CMR Ref:72-00-01 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)					Ldg	562				
712006		**Engine Mounts (Right) - General Visual Inspection (*CMR)**							RE		05-10-10 CMR	**≈19-Dec-2025**
	71 A/F						Mos	26-Jul-2024				
							Hrs	967:25	1,000	-/+50	2000	942 Hrs (+50)
		ATA Ref:71-20-00, CMR Ref:72-00-01 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)					Ldg	562				
716105		**Engine Nacelle Inlet (Left) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈19-Dec-2025**
	71 A/F						Mos	26-Jul-2024				
							Hrs	967:25	1,000	-/+50	2000	942 Hrs (+50)
		ATA Ref:71-61-01, MRB Ref:71-60-00/01 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)					Ldg	562				
716106		**Engine Nacelle Inlet (Right) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈19-Dec-2025**
	71 A/F						Mos	26-Jul-2024				
							Hrs	967:25	1,000	-/+50	2000	942 Hrs (+50)
		ATA Ref:71-61-01, MRB Ref:71-60-00/01 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)					Ldg	562				
783001		**Thrust Reverser (Deployed) (Left) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈19-Dec-2025**
	78 A/F						Mos	26-Jul-2024				
							Hrs	967:25	1,000	-/+50	2000	942 Hrs (+50)
		ATA Ref:78-30-00, MRB Ref:71-400-05 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)					Ldg	562				
783002		**Thrust Reverser (Deployed) (Right) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈19-Dec-2025**
	78 A/F						Mos	26-Jul-2024				
							Hrs	967:25	1,000	-/+50	2000	942 Hrs (+50)
		ATA Ref:78-30-00, MRB Ref:71-400-05 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)					Ldg	562				
▼ 1. RE 10000 Hrs												
272105		**Rudder Servo Actuator - Functional Check (**CMR)**							RE	05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks		**≈07-Feb-2037**
	27 A/F						Mos					
							Hrs		10,000	-/+50	10000	8942 Hrs (+50)
		ATA Ref:27-21-01, CMR Ref:27-20-02 (SOURCE: G280 AMM) (NOTE: Accomplish at 20,000 flight hours or 20A, whichever occurs first.)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
272107		**Rudder Servo Actuators Damping Orifice - Operational Check (**CMR)**							RE		05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks	**≈07-Feb-2037**
	27 A/F						Mos					
							Hrs		10,000	-/+50	10000	8942 Hrs (+50)
		ATA Ref:27-21-01, CMR Ref:27-20-01 (SOURCE: G280 AMM) (NOTE: Accomplish at 20,000 flight hours or 20A, whichever occurs first.)					Ldg					
273143		**Elevator Servo Actuator Compensator Volume (Left) - Functional Check (*CMR)**							RE		05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks	**≈07-Feb-2037**
	27 A/F						Mos					
							Hrs		10,000	-/+50	10000	8942 Hrs (+50)
		ATA Ref:27-31-04, CMR Ref:27-30-07 (SOURCE: G280 AMM) (NOTE: Accomplish at 20,000 flight hours or 20A, whichever occurs first.)					Ldg					
273144		**Elevator Servo Actuator Compensator Volume (Right) - Functional Check (*CMR)**							RE		05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks	**≈07-Feb-2037**
	27 A/F						Mos					
							Hrs		10,000	-/+50	10000	8942 Hrs (+50)
		ATA Ref:27-31-04, CMR Ref:27-30-07 (SOURCE: G280 AMM) (NOTE: Accomplish at 20,000 flight hours or 20A, whichever occurs first.)					Ldg					
273147		**Elevator Damping Orifice (Left) - Operational Check (**CMR)**							RE		05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks	**≈07-Feb-2037**
	27 A/F						Mos					
							Hrs		10,000	-/+50	10000	8942 Hrs (+50)
		ATA Ref:27-31-04, CMR Ref:27-30-02 (SOURCE: G280 AMM) (NOTE: Accomplish at 20,000 flight hours or 20A, whichever occurs first.)					Ldg					
273148		**Elevator Damping Orifice (Right) - Operational Check (**CMR)**							RE		05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks	**≈07-Feb-2037**
	27 A/F						Mos					
							Hrs		10,000	-/+50	10000	8942 Hrs (+50)
		ATA Ref:27-31-04, CMR Ref:27-30-02 (SOURCE: G280 AMM) (NOTE: Accomplish at 20,000 flight hours or 20A, whichever occurs first.)					Ldg					
▼ 1. RE 10000 Hrs, 10000 APUS												
492401		**APU Turbine Rotor - Discard**							RE		05-10-00 Time Limits	**≈30-Jan-2045**
	49 APU1						Mos	09-Apr-2024				
	70721725-2	New	0				Hrs	443	10,000		10443	9814 Hrs
	23-156101-07109		0				APUS	626	10,000		10,626	9,776 APUS
		ATA Ref:49-24-00, MRB Ref:49-24-00-01 (SOURCE: G280 AMM) (NOTE: Accomplish at 10,000 APU hours or 10,000 APU cycles, whichever occurs first.)										
▼ 1. RE 10000 Ldg												
275117		**Flap Actuator - Discard**							RE		05-10-10 Life Limited Components	**≈30-Mar-2044**
	27 A/F	Left Outboard					Mos					
	C64899-003						Hrs					
	B0181A						Ldg		10,000		10,000	9,382 Ldg
		ATA Ref:27-51-02 (SOURCE: G280 AMM)										
275118		**Flap Actuator - Discard**							RE		05-10-10 Life Limited Components	**≈30-Mar-2044**
	27 A/F	Right Outboard					Mos					
	C64899-004						Hrs					
	B0181A						Ldg		10,000		10,000	9,382 Ldg
		ATA Ref:27-51-02 (SOURCE: G280 AMM)										
▼ 1. RE 100000 Hrs, 100000 APUS												
492202		**APU Compressor Rotor - Discard**							RE		05-10-00 Time Limits	**≈24-Jul-2190**
	49 APU1		0				Mos	16-Aug-2022				
	70721598-1	New	0				Hrs	0	100,000		100000	99371 Hrs
	22-181967-00053		0				APUS	0	100,000		100,000	99,150 APUS
		ATA Ref:49-22-00, MRB Ref:49-22-00-01 (SOURCE: G280 AMM) (NOTE: APU hours or cycles, depending on operator tracking method. If both hours and cycles are tracked, life limit is applicable to the first limit achieved.)										

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 1. RE 12 Mos											
05-00-03	**Airworthiness Review Certificate Renewal / Extension**							RE			
5 A/F						Mos	05-Mar-2024	12		05-Mar-2025	5.9 Months
						Hrs					
						Ldg					
113001	**Cockpit, Cabin, Lavatory, and Baggage Compartment Placards - Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
11 A/F						Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
ATA Ref:11-30-00 (Tol. Adjustment: -11d) (SOURCE: G280 AOMM) (NOTE: See Interior Placards, refer to Aircraft Illustrated Parts Catalog, 11-30-00, Fig. 1, Forward Fuselage Interior Placards, Aircraft Illustrated Parts Catalog, 11-30-00, Fig. 2, Center Fuselage Interior Placards, Aircraft Maintenance Manual, Line Markings and Color Schemes, 11-10-00, Maintenance Practices and aircraft Final Phase Engineering Drawings.)						Hrs	678:36				
						Ldg	405				
256018	**Fire / Crash Axe - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
25 A/F D56 NSN						Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
ATA Ref:25-66-01 (Tol. Adjustment: -11d) (SOURCE: G280 AOMM) (NOTE: This item applies if installed.)						Hrs	678:36				
						Ldg	405				
256021	**Flashlight - Operational Test**							RE	05-20-00 Scheduled Maintenance Checks		
25 A/F						Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
ATA Ref:25-60-01 (Tol. Adjustment: -11d) (SOURCE: G280 AOMM)						Hrs	678:36				
						Ldg	405				
256112	**Emergency Locator Transmitter (ELT) - Functional Check (Per CFR 91.207(d) or National Aviation Authority.)**							RE	05-20-00 Scheduled Maintenance Checks		
25 A/F						Mos	13-Mar-2024	12		13-Mar-2025	6.1 Months
453-5060 252-06760						Hrs	678:36				
ATA Ref:25-61-01, MRB Ref:25-60-00-04 (SOURCE: G280 AMM) (NOTE: CAA Requirement)						Ldg	405				
256129	**Life Raft(s) (expiration date) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
25 A/F						Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
ATA Ref:25-61-03 (Tol. Adjustment: -11d) (SOURCE: G280 AOMM) (NOTE: See Life Raft(s) - Detailed Inspection.)						Hrs	678:36				
						Ldg	405				
256207	**Life Vest - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
25 A/F						Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
ATA Ref:25-62-01, MRB Ref:25-60-00/02 (Tol. Adjustment: -11d) (SOURCE: G280 AMM / G280 AOMM) (NOTE: Do not open if sealed.)						Hrs	678:36				
						Ldg	405				
256275	**Life Vest(s) Expiration Date - Detailed Inspection**							RE			
25 A/F						Mos	13-Mar-2024	12		31-Mar-2025	6.7 Months
						Hrs	678:36				
						Ldg	405				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
256404		**First Aid Kit - Detailed Inspection (do not open if sealed)**							RE	05-20-00 Scheduled Maintenance Checks		
	25 A/F						Mos	19-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	502950						Hrs					
	020223004						Ldg					
	ATA Ref:25-64-01 (Tol. Adjustment: -17d) (SOURCE: G280 AOMM) (NOTE: See First Aid Kit(s) - Detailed Inspection. This item applies if installed.)											
256616		**Protective Breathing Equipment - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	25 A/F						Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	ATA Ref:25-62-01 (Tol. Adjustment: -11d) (SOURCE: G280 AOMM) (NOTE: This item applies if installed.)						Hrs	678:36				
							Ldg	405				
257001		**Trash Container Enclosure (Galley) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	26 A/F						Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	ATA Ref:26-25-01 (Tol. Adjustment: -11d) (SOURCE: G280 AOMM) (NOTE: See Galley Trash Receptacle Enclosure, Lavatory Trash Receptacle Enclosure - Detailed Inspection.)						Hrs	678:36				
							Ldg	405				
257002		**Trash Container Enclosure (Lavatory) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	26 A/F						Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	ATA Ref:26-25-01 (Tol. Adjustment: -11d) (SOURCE: G280 AOMM) (NOTE: See Galley Trash Receptacle Enclosure, Lavatory Trash Receptacle Enclosure - Detailed Inspection.)						Hrs	678:36				
							Ldg	405				
262105		**Fire Extinguisher Bottle - Visual Check**							RE	05-20-00 Scheduled Maintenance Checks		
	26 A/F	Left					Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	474789-2						Hrs	678:36				
	AGF7198						Ldg	405				
	ATA Ref:26-21-01, MRB Ref.:26-20-00-12 (Tol. Adjustment: -11d) (SOURCE: G280 AMM) (NOTE: Accomplish within 14 months from date of Revision 14 (see List of Revisions) and at every 1C thereafter.)											
262106		**Fire Extinguisher Bottle - Visual Check**							RE	05-20-00 Scheduled Maintenance Checks		
	26 A/F	Right					Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	474789-1						Hrs	678:36				
	AGF7193						Ldg	405				
	ATA Ref:26-21-01, MRB Ref.:26-20-00-12 (Tol. Adjustment: -11d) (SOURCE: G280 AMM) (NOTE: Accomplish within 14 months from date of Revision 14 (see List of Revisions) and at every 1C thereafter.)											
262403		**Portable Fire Extinguishing Bottle - Weight Check**							RE	05-20-00 Scheduled Maintenance Checks		
	26 A/F	Cockpit					Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	347TS						Hrs	678:36				
	G-98646801						Ldg	405				
	Weighed Date 13-Mar-2024											
	ATA Ref:26-24-01, MRB Ref:25-60-00/01 (Tol. Adjustment: -11d) (SOURCE: G280 AMM / G280 AOMM)											
262405		**Portable Fire Extinguisher - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	26 A/F	Cockpit					Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	347TS						Hrs	678:36				
	G-98646801						Ldg	405				
	AOMM ATA Ref:26-24-00, ATA Ref:26-24-01, MRB Ref:25-60-00-06 (Tol. Adjustment: -11d) (SOURCE: G280 AMM / G280 AOMM) (NOTE: AMM NOTE: Accomplish within 14 months from date of Revision 14 (see List of Revisions) and at every 1C thereafter. AOMM NOTE: This item applies if installed.)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
262413		**Portable Fire Extinguishing Bottle - Weight Check**							RE	05-20-00 Scheduled Maintenance Checks		
	26 A/F 349TS	Fwd Cabin					Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	H-11788969						Hrs	678:36				
	Weighed Date 13-Mar-2024						Ldg	405				
	ATA Ref:26-24-01, MRB Ref:25-60-00/01 (Tol. Adjustment: -11d) (SOURCE: G280 AMM / G280 AOMM)											
262415		**Portable Fire Extinguisher - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	26 A/F 349TS	Fwd Cabin					Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	H-11788969						Hrs	678:36				
	AOMM ATA Ref:26-24-00, ATA Ref:26-24-01, MRB Ref:25-60-00-06 (Tol. Adjustment: -11d) (SOURCE: G280 AMM / G280 AOMM) (NOTE: AMM NOTE: Accomplish within 14 months from date of Revision 14 (see List of Revisions) and at every 1C thereafter. AOMM NOTE: This item applies if installed.)						Ldg	405				
262423		**Portable Fire Extinguishing Bottle - Weight Check**							RE	05-20-00 Scheduled Maintenance Checks		
	26 A/F 351	Aft Cabin					Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	H-21682620						Hrs	678:36				
	Weighed Date 13-Mar-2024						Ldg	405				
	ATA Ref:26-24-01, MRB Ref:25-60-00/01 (Tol. Adjustment: -11d) (SOURCE: G280 AMM / G280 AOMM)											
262425		**Portable Fire Extinguisher - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	26 A/F 351	Aft Cabin					Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	H-21682620						Hrs	678:36				
	AOMM ATA Ref:26-24-00, ATA Ref:26-24-01, MRB Ref:25-60-00-06 (Tol. Adjustment: -11d) (SOURCE: G280 AMM) (NOTE: AMM NOTE: Accomplish within 14 months from date of Revision 14 (see List of Revisions) and at every 1C thereafter. AOMM NOTE: This item applies if installed.)						Ldg	405				
262435		**Portable Water Fire Extinguisher - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	26 A/F 892480	Cabin - Left					Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	47852						Hrs	678:36				
	ATA Ref:26-00-00 (Tol. Adjustment: 10d) (SOURCE: G280 AOMM)						Ldg	405				
277103		**Gust Lock - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		
	27 A/F						Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	ATA Ref:27-70-00, MRB Ref:27-70-00-01 (SOURCE: G280 AMM)						Hrs	678:36				
							Ldg	405				
313101		**Cockpit Voice Recorder - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		
	31 A/F						Mos	04-Jun-2024	12	-/+1m	30-Jun-2025	9.8 Months (+30 Days)
	ATA Ref:31-31-00, MRB Ref:31-31-00/01 (SOURCE: G280 AMM)						Hrs	866:28				
							Ldg	501				
313109		**Recorder Independent Power Supply - Functional Check**							RE	05-20-00 Scheduled Maintenance Checks		
	31 A/F						Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	ATA Ref:31-31-00, MRB Ref:31-31-00/07 (Tol. Adjustment: -11d) (SOURCE: G280 AMM)						Hrs	678:36				
							Ldg	405				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
321007		**Main Landing Gear Components (Left) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	32 A/F						Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:32-10-00, MRB Ref:32.00.00/03 (Tol. Adjustment: -11d) (SOURCE: G280 AMM)					Hrs	678:36				
							Ldg	405				
321008		**Main Landing Gear Components (Right) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	32 A/F						Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:32-10-00, MRB Ref:32.00.00/03 (Tol. Adjustment: -11d) (SOURCE: G280 AMM)					Hrs	678:36				
							Ldg	405				
322004		**Nose Landing Gear Components - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	32 A/F						Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:32-20-00, MRB Ref:32.00.01/03 (Tol. Adjustment: -11d) (SOURCE: G280 AMM)					Hrs	678:36				
							Ldg	405				
344005		**Inspection Of Desiccant On Overhead Unit - Detailed Inspection**							RE			
	34 A/F						Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		(Tol. Adjustment: -11d)					Hrs	678:36				
							Ldg	405				
345202		**VHF Navigation System - Functional Test**							RE			
	34 A/F						Mos	13-Mar-2024	12		13-Mar-2025	6.1 Months
							Hrs	678:36				
		Mfg#:34-52-00 (NOTE: CAA Requirement)					Ldg	405				
521009		**Baggage Door Lock Bolts and Door Guides Mating Surfaces - Lubrication**							RE	05-20-00 Scheduled Maintenance Checks		
	52 A/F						Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:52-31-01, MRB Ref:52-30-00/03 (Tol. Adjustment: -11d) (SOURCE: G280 AMM)					Hrs	678:36				
							Ldg	405				
521115		**Main Entrance Door Seals - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	52 A/F						Mos	13-Mar-2024	12	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:52-11-02, MRB Ref:52-10-00/01 (Tol. Adjustment: -11d) (SOURCE: G280 AMM)					Hrs	678:36				
							Ldg	405				
		Compass Swing							RE			
	97 A/F						Mos	13-Mar-2024	12		13-Mar-2025	6.1 Months
							Hrs	678:36				
		(NOTE: CAA Requirement)					Ldg	405				
▼ 1. RE 12 Mos, 500 Hrs												
243504		**Emergency Power Supply - Functional Check (Capacity)**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Apr-2025**
	24 A/F						Mos	26-Jul-2024	12	-/+1m	31-Jul-2025	10.8 Months (+31 Days)
		ATA Ref:24-35-00, MRB Ref:24-30-00/02 (Tol. Adjustment: 42.4 Hrs) (SOURCE: G280 AMM)					Hrs	967:25	500	-/+50	1509:48	451:48 Hrs (+50)
							Ldg	562				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
561005		**Flight Compartment Windows Hydrophobic Coating (Pilot Windshield) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
	56 A/F						Mos	26-Jul-2024	12	-/+1m	31-Jul-2025	10.8 Months (+31 Days)
		ATA Ref:56-10-00, MRB Ref:56-10-00-01 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM) (NOTE: Accomplish at 1A or 1C, whichever occurs first.)					Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
							Ldg	562				
561006		**Flight Compartment Windows Hydrophobic Coating (Copilot Windshield) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
	56 A/F						Mos	26-Jul-2024	12	-/+1m	31-Jul-2025	10.8 Months (+31 Days)
		ATA Ref:56-10-00, MRB Ref:56-10-00-01 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM) (NOTE: Accomplish at 1A or 1C, whichever occurs first.)					Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
							Ldg	562				
561007		**Flight Compartment Windows Hydrophobic Coating (Pilot Side Window) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
	56 A/F						Mos	26-Jul-2024	12	-/+1m	31-Jul-2025	10.8 Months (+31 Days)
		ATA Ref:56-10-00, MRB Ref:56-10-00-01 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM) (NOTE: Accomplish at 1A or 1C, whichever occurs first.)					Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
							Ldg	562				
561008		**Flight Compartment Windows Hydrophobic Coating (Copilot Side Window) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
	56 A/F						Mos	26-Jul-2024	12	-/+1m	31-Jul-2025	10.8 Months (+31 Days)
		ATA Ref:56-10-00, MRB Ref:56-10-00-01 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM) (NOTE: Accomplish at 1A or 1C, whichever occurs first.)					Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
							Ldg	562				
▼ 1. RE 12 Mos, 600 Hrs												
232742		**Ka-Band Radome (Exterior) - Visual Inspection**							RE			**≈13-May-2025**
	23 A/F						Mos	26-Jul-2024	12		31-Jul-2025	10.8 Months
							Hrs	967:25	600		1567:25	509:25 Hrs
							Ldg	562				
232744		**Ka-Band System - Operational Check**							RE			**≈13-May-2025**
	23 A/F						Mos	26-Jul-2024	12		31-Jul-2025	10.8 Months
							Hrs	967:25	600		1567:25	509:25 Hrs
							Ldg	562				
232745		**KA-Band Radome Moisture Special Detailed Inspection**							RE			**≈13-May-2025**
	23 A/F						Mos	26-Jul-2024	12		31-Jul-2025	10.8 Months
							Hrs	967:25	600		1567:25	509:25 Hrs
							Ldg	562				
▼ 1. RE 12 Yrs												
262455		**Portable Fire Extinguisher - Discard**							RE	05-10-00 Time Limits		
	26 A/F	Cockpit	9				Yrs	10-Feb-2023	12		31-May-2034	9.7 Years
	347TS						Hrs	24:24				
	G-98646801						Ldg	7				
	Manufactured Date 09-May-2022											
	ATA Ref:26-24-00 (SOURCE: G280 AOMM)											
262459		**Portable Fire Extinguisher - Discard**							RE	05-10-00 Time Limits		
	26 A/F	Fwd Cabin	3				Yrs	10-Feb-2023	12		31-Oct-2034	10.1 Years
	349TS		0				Hrs	24:24				
	H-11788969		0				Ldg	7				
	Manufactured Date 31-Oct-2022											
	ATA Ref:26-24-00 (SOURCE: G280 AOMM) (NOTE: Life limit per 49 CFR § 180.205 or National Aviation Authority. This item applies if installed.)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
262463		**Portable Fire Extinguisher - Discard**							RE		05-10-00 Time Limits	
	26 A/F	Aft Cabin	3				Yrs	10-Feb-2023	12		31-Oct-2034	10.1 Years
	351						Hrs	24:24				
	H-21682620						Ldg	7				
	Manufactured Date 31-Oct-2022											
	ATA Ref:26-24-00 (SOURCE: G280 AOMM)											
341113		**Air Data Computer - Restore**							RE		05-10-00 Time Limits	
	34 A/F	No.1				0.25	Yrs		12		31-Aug-2034	10 Years
	822-2083-001						Hrs					
	4MRM48						Ldg					
	Restored Date 31-Aug-2022											
	ATA Ref:34-11-00, MRB Ref:34-11-00-01 (SOURCE: G280 AMM) (NOTE: Aircraft having ADC-30X0 without SB6, if more than 6 years since new or last ADC replacement, whichever is later, recommend accomplish battery replacement within 24 months from Revision 15 and every 8 years thereafter. See List of Revisions. Otherwise accomplish at every 8 years since new or last ADC replacement, whichever is later. Aircraft having ADC-30X0 with SB6, accomplish at every 12 years since new or last ADC replacement, whichever is later.)											
341114		**Air Data Computer - Restore**							RE		05-10-00 Time Limits	
	34 A/F	No.2				0.25	Yrs		12		31-Aug-2034	10 Years
	822-2083-001						Hrs					
	4P5NT1						Ldg					
	Restored Date 31-Aug-2022											
	ATA Ref:34-11-00, MRB Ref:34-11-00-01 (SOURCE: G280 AMM) (NOTE: Aircraft having ADC-30X0 without SB6, if more than 6 years since new or last ADC replacement, whichever is later, recommend accomplish battery replacement within 24 months from Revision 15 and every 8 years thereafter. See List of Revisions. Otherwise accomplish at every 8 years since new or last ADC replacement, whichever is later. Aircraft having ADC-30X0 with SB6, accomplish at every 12 years since new or last ADC replacement, whichever is later.)											
▼ 1. RE 120 Mos												
256205		**Life Vest - Restore**							RE		05-10-00 Time Limits	
	25 A/F	Pilot				6	Mos	10-Feb-2023	120		31-Aug-2032	8 Years
	63600-505						Hrs	24:24				
	L5553372						Ldg	7				
	Restored Date 31-Aug-2022											
	ATA Ref:25-62-01, MRB Ref:25-60-00/03 (SOURCE: G280 AMM / G280-AOMM) (NOTE: Air Cruisers (Red, Crew Life Vests) P/N 63600-505, 63600-597: Life vests certified in vacuum bag, send to authorized repair station every 10 years. Life vests certified in sewn packaging, send to authorized repair station every 5 years. This item applies if installed.)											
256206		**Life Vest - Restore**							RE		05-10-00 Time Limits	
	25 A/F	Copilot				6	Mos	10-Feb-2023	120		31-Aug-2032	8 Years
	63600-505						Hrs	24:24				
	L5553373						Ldg	7				
	Restored Date 31-Aug-2022											
	ATA Ref:25-62-01, MRB Ref:25-60-00/03 (SOURCE: G280 AMM / G280-AOMM) (NOTE: Air Cruisers (Red, Crew Life Vests) P/N 63600-505, 63600-597: Life vests certified in vacuum bag, send to authorized repair station every 10 years. Life vests certified in sewn packaging, send to authorized repair station every 5 years. This item applies if installed.)											
256210		**Life Vest - Restore**							RE		05-10-00 Time Limits	
	25 A/F	3rd Crewmember				6	Mos	10-Feb-2023	120		31-Aug-2032	8 Years
	63600-505						Hrs	24:24				
	L5553375						Ldg	7				
	Restored Date 31-Aug-2022											
	ATA Ref::25-61-01 (SOURCE: G280 AOMM) (NOTE: Air Cruisers (Red, Crew Life Vests) P/N 63600-505, 63600-597: Life vests certified in vacuum bag, send to authorized repair station every 10 years. Life vests certified in sewn packaging, send to authorized repair station every 5 years. This item applies if installed.)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
256211		**Life Vest - Restore**							RE		05-10-00 Time Limits	
	25 A/F	Left No.1				7	Mos	10-Feb-2023	120		31-Jul-2032	7.9 Years
	63600-105						Hrs	24:24				
	L5530635						Ldg	7				
	Restored Date 31-Jul-2022											
	ATA Ref::25-61-01 (SOURCE: G280 AOMM) (NOTE: Air Cruisers (Yellow, Passenger Life Vests) P/N 63600-105, 63600-197: Life vests certified in vacuum bag, send to authorized repair station every 10 years. Life vests certified in sewn packaging, send to authorized repair station every 5 years. This item applies if installed.)											
256212		**Life Vest - Restore**							RE		05-10-00 Time Limits	
	25 A/F	Right No.1				4	Mos	10-Feb-2023	120		31-Oct-2032	8.1 Years
	63600-105						Hrs	24:24				
	L5611822						Ldg	7				
	Restored Date 31-Oct-2022											
	ATA Ref::25-61-01 (SOURCE: G280 AOMM) (NOTE: Air Cruisers (Yellow, Passenger Life Vests) P/N 63600-105, 63600-197: Life vests certified in vacuum bag, send to authorized repair station every 10 years. Life vests certified in sewn packaging, send to authorized repair station every 5 years. This item applies if installed.)											
256213		**Life Vest - Restore**							RE		05-10-00 Time Limits	
	25 A/F	Left No.2				7	Mos	10-Feb-2023	120		31-Jul-2032	7.9 Years
	63600-105						Hrs	24:24				
	L5530660						Ldg	7				
	Restored Date 31-Jul-2022											
	ATA Ref::25-61-01 (SOURCE: G280 AOMM) (NOTE: Air Cruisers (Yellow, Passenger Life Vests) P/N 63600-105, 63600-197: Life vests certified in vacuum bag, send to authorized repair station every 10 years. Life vests certified in sewn packaging, send to authorized repair station every 5 years. This item applies if installed.)											
256214		**Life Vest - Restore**							RE		05-10-00 Time Limits	
	25 A/F	Right No.2				4	Mos	10-Feb-2023	120		31-Oct-2032	8.1 Years
	63600-105						Hrs	24:24				
	L5611823						Ldg	7				
	Restored Date 31-Oct-2022											
	ATA Ref::25-61-01 (SOURCE: G280 AOMM) (NOTE: Air Cruisers (Yellow, Passenger Life Vests) P/N 63600-105, 63600-197: Life vests certified in vacuum bag, send to authorized repair station every 10 years. Life vests certified in sewn packaging, send to authorized repair station every 5 years. This item applies if installed.)											
256215		**Life Vest - Restore**							RE		05-10-00 Time Limits	
	25 A/F	Left No.3				7	Mos	10-Feb-2023	120		31-Jul-2032	7.9 Years
	63600-105						Hrs	24:24				
	L5530661						Ldg	7				
	Restored Date 31-Jul-2022											
	ATA Ref::25-61-01 (SOURCE: G280 AOMM) (NOTE: Air Cruisers (Yellow, Passenger Life Vests) P/N 63600-105, 63600-197: Life vests certified in vacuum bag, send to authorized repair station every 10 years. Life vests certified in sewn packaging, send to authorized repair station every 5 years. This item applies if installed.)											
256216		**Life Vest - Restore**							RE		05-10-00 Time Limits	
	25 A/F	Right No.3				7	Mos	10-Feb-2023	120		31-Jul-2032	7.9 Years
	63600-105						Hrs	24:24				
	L5530662						Ldg	7				
	Restored Date 31-Jul-2022											
	ATA Ref::25-61-01 (SOURCE: G280 AOMM) (NOTE: Air Cruisers (Yellow, Passenger Life Vests) P/N 63600-105, 63600-197: Life vests certified in vacuum bag, send to authorized repair station every 10 years. Life vests certified in sewn packaging, send to authorized repair station every 5 years. This item applies if installed.)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
256217		**Life Vest - Restore**							RE		05-10-00 Time Limits	
	25 A/F	Left No.4				7	Mos	10-Feb-2023	120		31-Jul-2032	7.9 Years
	63600-105						Hrs	24:24				
	L5530668						Ldg	7				
	Restored Date 31-Jul-2022											
	ATA Ref::25-61-01 (SOURCE: G280 AOMM) (NOTE: Air Cruisers (Yellow, Passenger Life Vests) P/N 63600-105, 63600-197: Life vests certified in vacuum bag, send to authorized repair station every 10 years. Life vests certified in sewn packaging, send to authorized repair station every 5 years. This item applies if installed.)											
256218		**Life Vest - Restore**							RE		05-10-00 Time Limits	
	25 A/F	Right No.4				4	Mos	10-Feb-2023	120		31-Oct-2032	8.1 Years
	63600-105						Hrs	24:24				
	L5611821						Ldg	7				
	Restored Date 31-Oct-2022											
	ATA Ref::25-61-01 (SOURCE: G280 AOMM) (NOTE: Air Cruisers (Yellow, Passenger Life Vests) P/N 63600-105, 63600-197: Life vests certified in vacuum bag, send to authorized repair station every 10 years. Life vests certified in sewn packaging, send to authorized repair station every 5 years. This item applies if installed.)											
256221		**Life Vest - Restore**							RE		05-10-00 Time Limits	
	25 A/F	Divan - Fwd				0	Mos		120		30-Nov-2032	8.2 Years
	63600-105					0	Hrs					
	L5611851					0	Ldg					
	Restored Date 30-Nov-2022											
	ATA Ref::25-61-01 (SOURCE: G280 AOMM) (NOTE: Air Cruisers (Yellow, Passenger Life Vests) P/N 63600-105, 63600-197: Life vests certified in vacuum bag, send to authorized repair station every 10 years. Life vests certified in sewn packaging, send to authorized repair station every 5 years. This item applies if installed.)											
256222		**Life Vest - Restore**							RE		05-10-00 Time Limits	
	25 A/F	Divan - Aft				4	Mos	10-Feb-2023	120		31-Oct-2032	8.1 Years
	63600-105						Hrs	24:24				
	L5611850						Ldg	7				
	Restored Date 31-Oct-2022											
	ATA Ref::25-61-01 (SOURCE: G280 AOMM) (NOTE: Air Cruisers (Yellow, Passenger Life Vests) P/N 63600-105, 63600-197: Life vests certified in vacuum bag, send to authorized repair station every 10 years. Life vests certified in sewn packaging, send to authorized repair station every 5 years. This item applies if installed.)											
256223		**Life Vest - Restore**							RE		05-10-00 Time Limits	
	25 A/F	Divan - Mid				4	Mos	10-Feb-2023	120		31-Oct-2032	8.1 Years
	63600-105						Hrs	24:24				
	L5611851						Ldg	7				
	Restored Date 31-Oct-2022											
	ATA Ref::25-61-01 (SOURCE: G280 AOMM) (NOTE: Air Cruisers (Yellow, Passenger Life Vests) P/N 63600-105, 63600-197: Life vests certified in vacuum bag, send to authorized repair station every 10 years. Life vests certified in sewn packaging, send to authorized repair station every 5 years. This item applies if installed.)											
▼ 1. RE 126 Mos												
256603		**Protective Breathing Equipment (PBE) - Discard**							RE		05-10-00 Time Limits	
	25 A/F	No.1					Mos		126		30-Jun-2033	8.8 Years
	MR-10051N						Hrs					
	E2207262						Ldg					
	Manufactured Date 01-Dec-2022											
	(SOURCE: G280 AOMM) (NOTE: Discard 10 years and 6 months from date of manufacture. This item applies if installed.)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
256606		**Protective Breathing Equipment (PBE) - Discard**							RE		05-10-00 Time Limits	
25 A/F	MR-10051N E-2206591	No.2 Manufactured Date 10-Feb-2023 (SOURCE: G280 AOMM) (NOTE: Discard 10 years and 6 months from date of manufacture. This item applies if installed.)				3	Mos Hrs Ldg	10-Feb-2023 24:24 7	126		31-May-2033	8.7 Years
▼ 1. RE 144 Mos												
301121		**Wing Anti-ice Temperature Switches - Operational Check**							RE	05-20-00	Scheduled Maintenance Checks	
30 A/F		ATA Ref:30-11-02, MRB Ref:30-11-00/02, MRB Ref:30-11-00/01 (SOURCE: G280 AMM)					Mos Hrs Ldg		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
301122		**Wing Anti-ice Temperature Switches - Operational Check**							RE	05-20-00	Scheduled Maintenance Checks	
30 A/F		ATA Ref:30-11-02, MRB Ref:30-11-00/01, MRB Ref:30-11-00/02 (SOURCE: G280 AMM)					Mos Hrs Ldg		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
321011		**Main Landing Gear Components (Left) - Detailed Inspection**							RE	05-20-00	Scheduled Maintenance Checks	
32 A/F		ATA Ref:32-10-00, MRB Ref:32.00.00/02 (SOURCE: G280 AMM)					Mos Hrs Ldg		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
321012		**Main Landing Gear Components (Right) - Detailed Inspection**							RE	05-20-00	Scheduled Maintenance Checks	
32 A/F		ATA Ref:32-10-00, MRB Ref:32.00.00/02 (SOURCE: G280 AMM)					Mos Hrs Ldg		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
322006		**Nose Landing Gear Components - Detailed Inspection**							RE	05-20-00	Scheduled Maintenance Checks	
32 A/F		ATA Ref:32-20-00, MRB Ref:32.00.01/02 (SOURCE: G280 AMM)					Mos Hrs Ldg		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
522107		**Emergency Exit Door - Detailed Inspection**							RE	05-20-00	Scheduled Maintenance Checks	
52 A/F		ATA Ref:52-21-01, MRB Ref:52.20.00/04, MRB Ref:52.20.00/02 (SOURCE: G280 AMM)					Mos Hrs Ldg		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
522201		**Emergency Exit Door Locking Mechanism - General Visual Inspection**							RE	05-20-00	Scheduled Maintenance Checks	
52 A/F		ATA Ref:52-22-00, MRB Ref:52-20-00/03 (SOURCE: G280 AMM)					Mos Hrs Ldg		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
531040		**Forward Fuselage Skin Under Forward Fuel Tank and Forward Fairing - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
		ATA Ref:53-10-01, MRB Ref:53.23.00 / 14 (SOURCE: G280 AMM) (NOTE: NOTE: Accomplish at 12C from EIS or next fwd fuel tank removal, whichever occurs first. Aircraft beyond 120 months since EIS, accomplish at next fwd fuel tank removal or within 24 months from the date of Revision 19 (see List of Revisions), whichever occurs first, and at every 12C or fwd fuel tank removal, whichever occurs first, thereafter.)					Hrs					
							Ldg					
531105		**Radome Internal - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
		ATA Ref:53-11-01, MRB Ref:53-100-01 (SOURCE: G280 AMM)					Hrs					
							Ldg					
533103		**APU Enclosure Frame 64 - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
		ATA Ref:53-31-01, MRB Ref:53.50.04/02 (SOURCE: G280 AMM)					Hrs					
							Ldg					
545005		**Firewall Environmental Deterioration - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
54 A/F							Mos	02-Mar-2023	144		31-Mar-2035	10.6 Years
							Hrs	34:12				
		ATA Ref:54-50-00, MRB Ref:54.51.00/02 (Manual Adjustment: 20d) (SOURCE: G280 AMM)					Ldg	10				
545006		**Firewall Environmental Deterioration - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
54 A/F							Mos	02-Mar-2023	144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
		ATA Ref:54-50-00, MRB Ref:54.51.00/02 (Manual Adjustment: 20d) (SOURCE: G280 AMM)					Hrs	34:12				
							Ldg	10				
551115		**Horizontal Stabilizer Leading Edge (Leading Edge Removed) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
		ATA Ref:55-11-01, MRB Ref:55.11.00/02 (SOURCE: G280 AMM)					Hrs					
							Ldg					
551117		**Horizontal Stabilizer Front Spar (Leading Edges Removed) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
		ATA Ref:55-11-01, MRB Ref:55.11.00/04 (SOURCE: G280 AMM)					Hrs					
							Ldg					
553011		**Vertical Stabilizer Box Structure (Internal) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
		ATA Ref:55-30-00, MRB Ref:55.31.00/01 (SOURCE: G280 AMM)					Hrs					
							Ldg					
553012		**Vertical Stabilizer Forward Face of Front Spar - Special Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
		ATA Ref:55-30-00, MRB Ref:55.31.00/02 (SOURCE: G280 AMM)					Hrs					
							Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
570211		**Wing Torsion Box Forward Spar and Spar Splices - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
		ATA Ref:57-02-00, MRB Ref:57.02.00/04 (SOURCE: G280 AMM)					Hrs					
							Ldg					
570212		**Wing Torsion Box Forward Spar and Spar Splices - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
		ATA Ref:57-02-00, MRB Ref:57.02.00/04 (SOURCE: G280 AMM)					Hrs					
							Ldg					
574003		**Wing Leading Edge (Internal) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
		ATA Ref:57-40-00, MRB Ref:57.40.00/02 (SOURCE: G280 AMM)					Hrs					
							Ldg					
574004		**Wing Leading Edge (Internal) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
		ATA Ref:57-40-00, MRB Ref:57.40.00/02 (SOURCE: G280 AMM)					Hrs					
							Ldg					
▼ 1. RE 15 Yrs												
324121		**Main Tire - Removal / Installation**							RE			
32 A/F		Left Outboard	1				Yrs	03-Aug-2024	15		03-Aug-2038	13.9 Years
M08401 IND03		New	0				Hrs	985:12				
477123			0				Ldg	575				
Mfg#:32-41-02-RI												
324122		**Main Tire - Removal / Installation**							RE			
32 A/F		Left Inboard	1				Yrs	03-Aug-2024	15		03-Aug-2038	13.9 Years
M08401 IND03		New	0				Hrs	985:12				
477134			0				Ldg	575				
Mfg#:32-41-02-RI												
324123		**Main Tire - Removal / Installation**							RE			
32 A/F		Right Inboard	0				Yrs	28-Aug-2024	15		28-Aug-2039	15 Years
M08401 IND03		New	0				Hrs	1058				
3072T166			0				Ldg	618				
Mfg#:32-41-02-RI												
324124		**Main Tire - Removal / Installation**							RE			
32 A/F		Right Outboard	0				Yrs	28-Aug-2024	15		28-Aug-2039	15 Years
M08401 IND03		New	0				Hrs	1058				
3074T187			0				Ldg	618				
Mfg#:32-41-02-RI												
324211		**Nose Tire - Removal / Installation**							RE			
32 A/F		Left	0				Yrs	28-Aug-2024	15		28-Aug-2039	15 Years
027-614-0		New	0				Hrs	1058				
2298T00492			0				Ldg	618				
Mfg#:32-42-02												

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
324212		**Nose Tire - Removal / Installation**							RE			
32 A/F		Right	0				Yrs	28-Aug-2024	15		28-Aug-2039	15 Years
027-614-0		New	0				Hrs	1058				
2300T00444			0				Ldg	618				
Mfg#:32-42-02												
351103		**Oxygen Cylinder - Discard**							RE		05-10-00 Time Limits	
35 A/F							Yrs	19-Jan-2023	15		30-Apr-2037	12.6 Years
807435-02						0	Hrs	22:54				
C22040248						0	Ldg	6				
Manufactured Date 22-Apr-2022												
ATA Ref:35-11-01, MRB Ref:35-10-00-04 (SOURCE: G280 AMM) (NOTE: NOTE: 15 years from date of manufacture.)												
▼ 1. RE 1500 Hrs												
274102		**Horizontal Stabilizer Trim Actuator - Lubrication**							RE	05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
27 A/F							Mos					
							Hrs		1,500	-/+50	1500	442 Hrs (+50)
ATA Ref:27-41-01, MRB Ref:27-40-00/02 (SOURCE: G280 AMM)							Ldg					
274117		**Horizontal Stabilizer Trim Actuator - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
27 A/F							Mos					
							Hrs		1,500	-/+50	1500	442 Hrs (+50)
ATA Ref:27-41-01, MRB Ref:27-40-00/01 (SOURCE: G280 AMM)							Ldg					
280001		**Cross-side Jettison - Operational Check (MRB Ref: 28-20-00-04, Operational Check of the power crossflow system at 3A)**							RE	05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
28 A/F							Mos					
							Hrs		1,500	-/+50	1500	442 Hrs (+50)
ATA Ref:28-00-00, CMR Ref:28-00-01, MRB Ref:28-20-00-04 (SOURCE: G280 AMM) (NOTE: MRB Ref: 28-20-00-04, Operational Check of the power crossflow system at 3A. CMR Ref: 28-00-01 at 2000 flight hours.)							Ldg					
322133		**Nose Landing Gear Downlock Springs (Left) - General Visual Inspection (**CMR)**							RE		05-10-10 CMR	**≈09-Apr-2025**
32 A/F							Mos					
							Hrs		1,500	-/+50	1500	442 Hrs (+50)
ATA Ref:32-21-05, CMR Ref:32-00-02 (SOURCE: G280 AMM)							Ldg					
322134		**Nose Landing Gear Downlock Springs (Right) - General Visual Inspection (**CMR)**							RE		05-10-10 CMR	**≈09-Apr-2025**
32 A/F							Mos					
							Hrs		1,500	-/+50	1500	442 Hrs (+50)
ATA Ref:32-21-05, CMR Ref:32-00-02 (SOURCE: G280 AMM)							Ldg					
352001		**Passenger Oxygen System - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Apr-2025**
35 A/F							Mos	02-Mar-2023				
							Hrs	34:12	1,500	-/+50	1509:48	451:48 Hrs (+50)
ATA Ref:35-20-00, MRB Ref:35-20-00-02 (Manual Adjustment: -24.4 Hrs) (SOURCE: G280 AMM / G280 AOMM)							Ldg	10				
491113		**APU Drain and Vent Lines - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈29-Apr-2028**
49 APU1							Mos	09-Apr-2024				
							Hrs	443	1,500	-/+50	1943	1314 Hrs (+50)
ATA Ref:49-20-00, MRB Ref:49-13-00/01 (SOURCE: G280 AMM)							APUS	626				
493001		**APU Fuel System - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈29-Apr-2028**
49 APU1							Mos	09-Apr-2024				
							Hrs	443	1,500	-/+50	1943	1314 Hrs (+50)
ATA Ref:49-30-00, MRB Ref:49-30-00/02 (SOURCE: G280 AMM)							APUS	626				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
493203		**APU Fuel Filter - Discard**							RE		05-10-00 Time Limits	**≈29-Apr-2028**
	49 APU1						Mos	09-Apr-2024				
	3882440-1						Hrs	443	1,500		1943	1314 Hrs
	NSN						APUS	626				
		ATA Ref:49-32-01, MRB Ref:49-30-00/01 (SOURCE: G280 AMM)										
498101		**APU Exhaust Duct - General Visual Inspection**							RE	05-20-00	Scheduled Maintenance Checks	**≈29-Apr-2028**
	49 APU1						Mos	09-Apr-2024				
							Hrs	443	1,500	-/+50	1943	1314 Hrs (+50)
		ATA Ref:49-81-01, MRB Ref:49-80-00/01 (SOURCE: G280 AMM)					APUS	626				
551101		**Horizontal Stabilizer Scissors and Hinge Pivot - Lubrication**							RE	05-20-00	Scheduled Maintenance Checks	**≈09-Apr-2025**
	55 A/F						Mos					
							Hrs		1,500	-/+50	1500	442 Hrs (+50)
		ATA Ref:55-11-01, MRB Ref:27-40-00/06 (SOURCE: G280 AMM)					Ldg					
783201		**Pivot Door Actuator Internal Lock (Left) - Operational Check (**CMR)**							RE		05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks	**≈09-Apr-2025**
	78 A/F						Mos					
							Hrs		1,500	-/+50	1500	442 Hrs (+50)
		ATA Ref:78-32-00, CMR Ref:78-00-01 (SOURCE: G280 AMM) (NOTE: Accomplish at 2000 flight hours or 3A, whichever occurs first.)					Ldg					
783202		**Pivot Door Actuator Internal Lock (Right) - Operational Check (**CMR)**							RE		05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks	**≈09-Apr-2025**
	78 A/F						Mos					
							Hrs		1,500	-/+50	1500	442 Hrs (+50)
		ATA Ref:78-32-00, CMR Ref:78-00-01 (SOURCE: G280 AMM) (NOTE: Accomplish at 2000 flight hours or 3A, whichever occurs first.)					Ldg					
▼ 1. RE 15000 Enc											Man Hours: 20+	
723001		**Vortex Spoiler Assembly - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	70040037-2	New	0				Hrs	0				
	22-162045-00319		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-30-00, MRB Ref:72-30-00-05 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)										
723001		**Vortex Spoiler Assembly - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	70040037-2	New	0				Hrs	0				
	22-162045-00250		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-30-00, MRB Ref:72-30-00-05 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)										
723003		**Compressor Blisks (Stage 1) - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	3033053-7	New	0				Hrs	0				
	2218244938573		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-30-00, MRB Ref:72-30-00/04 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)										
723003		**Compressor Blisks (Stage 1) - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	3033053-7	New	0				Hrs	0				
	2118244936482		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-30-00, MRB Ref:72-30-00/04 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)										
723004		**Compressor Blisks (Stage 2) - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	3033063-4	New	0				Hrs	0				
	2218244938258		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-30-00, MRB Ref:72-30-00/04 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
723004		**Compressor Blisks (Stage 2) - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	3033063-4	New	0				Hrs	0				
	2218244939459		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-30-00, MRB Ref:72-30-00/04 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)										
723005		**Compressor Blisks (Stage 3) - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	3033067-9	New	0				Hrs	0				
	2218244940017		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-30-00, MRB Ref:72-30-00/04 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)										
723005		**Compressor Blisks (Stage 3) - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	3033067-9	New	0				Hrs	0				
	2218244939587		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-30-00, MRB Ref:72-30-00/04 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)										
723006		**Compressor Blisks (Stage 4) - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	3033072-4	New	0				Hrs	0				
	2218244039522		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-30-00, MRB Ref:72-30-00/04 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)										
723006		**Compressor Blisks (Stage 4) - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	3033072-4	New	0				Hrs	0				
	2218244940075		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-30-00, MRB Ref:72-30-00/04 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)										
723007		**Compressor Rotating Seal (Stage 2 - 3) - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	3033069-3	New	0				Hrs	0				
	22-122065-00961		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-30-00, MRB Ref:72-30-00/03 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)										
723007		**Compressor Rotating Seal (Stage 2 - 3) - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	3033069-3	New	0				Hrs	0				
	22-122065-01058		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-30-00, MRB Ref:72-30-00/03 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)										
723008		**Compressor Rotating Seal (Stage 3 - 4) - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	3033070-3	New	0				Hrs	0				
	21-156113-26931		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-30-00, MRB Ref:72-30-00/03 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)										
723008		**Compressor Rotating Seal (Stage 3 - 4) - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	3033070-3	New	0				Hrs	0				
	21-156113-26889		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-30-00, MRB Ref:72-30-00/03 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)										
723009		**Compressor Impeller - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	3033207-1	New	0				Hrs	0				
	2218244940218		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-30-00, MRB Ref:72-30-00/06 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
723009		**Compressor Impeller - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	3033207-1	New	0				Hrs	0				
	21-162246-02182		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-30-00, MRB Ref:72-30-00/06 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
723010		**HP Shaft - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	3033084-5	New	0				Hrs	0				
	20-102045-09267		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-30-00, MRB Ref:72-51-00/08, MRB Ref:72-30-00/10 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
723010		**HP Shaft - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	3033084-5	New	0				Hrs	0				
	22-124722-00159		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-30-00, MRB Ref:72-51-00/08, MRB Ref:72-30-00/10 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
723011		**HP Turbine Fwd Couplers - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	3033133-2	New	0				Hrs	0				
	22-1034-39268		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-51-00/05 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
723011		**HP Turbine Fwd Couplers - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	3033133-2	New	0				Hrs	0				
	22-1034-39118		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:72-51-00/05 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725103		**(HPT 1) HP Turbine Disks - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	3035136-4	New	0				Hrs	0				
	2218244937936		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-51-00-03 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations.)											
725103		**(HPT 1) HP Turbine Disks - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	3035136-4	New	0				Hrs	0				
	2218244939926		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:72-51-00-03 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations.)											
725104		**(HPT 2) HP Turbine Disks - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	3035123-1	New	0				Hrs	0				
	2218244940576		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-51-00-03 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations.)											
725104		**(HPT 2) HP Turbine Disks - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	3035123-1	New	0				Hrs	0				
	2218244939337		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:72-51-00-03 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations.)											
725105		**HP Turbine (HPT 1) Seal Plate Assemblies - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	70040044-1	New	0				Hrs	0				
	2218244940152		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:75-21-00/03, MRB Ref:72-51-00/04 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725105		**HP Turbine (HPT 1) Seal Plate Assemblies - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
72 ENG2			0				Mos	20-Jan-2023				
	70040044-1	New	0				Hrs	0				
	2218244940137		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:75-21-00/03, MRB Ref:72-51-00/04 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725106		**HP Turbine (HPT 2) Seal Plate Assemblies - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
72 ENG1			0				Mos	26-Jan-2023				
	3035109-1	New	0				Hrs	0				
	2213244939806		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-51-00/04, MRB Ref:75-21-00/03 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725106		**HP Turbine (HPT 2) Seal Plate Assemblies - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
72 ENG2			0				Mos	20-Jan-2023				
	3035109-1	New	0				Hrs	0				
	2218244939807		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:75-21-00/03, MRB Ref:72-51-00/04 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725107		**HP Turbine (HPT1) Seal Plate Coupler (drive arm) - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
72 ENG1			0				Mos	26-Jan-2023				
	3035030-3	New	0				Hrs	0				
	22-162246-02209		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-51-00/05 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725107		**HP Turbine (HPT1) Seal Plate Coupler (drive arm) - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
72 ENG2			0				Mos	20-Jan-2023				
	3035030-3	New	0				Hrs	0				
	22-162246-02249		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:72-51-00/05 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725108		**HP Turbine (HPT 2) Coupler - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
72 ENG1			0				Mos	26-Jan-2023				
	3035053-2	New	0				Hrs	0				
	22-1034-38356		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-51-00/05 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725108		**HP Turbine (HPT 2) Coupler - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
72 ENG2			0				Mos	20-Jan-2023				
	3035053-2	New	0				Hrs	0				
	22-1034-38363		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:72-51-00/05 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725109		**HP Turbine Interstage Seal - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
72 ENG1			0				Mos	26-Jan-2023				
	3035134-3	New	0				Hrs	0				
	22-162045-00603		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:75-21-00/02, MRB Ref:72-51-00/06 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725109		**HP Turbine Interstage Seal - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
72 ENG2			0				Mos	20-Jan-2023				
	3035134-3	New	0				Hrs	0				
	22-162045-00492		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:75-21-00/02, MRB Ref:72-51-00/06 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725501		**LP Turbine Shaft - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	3035689-2	New	0				Hrs	0				
	22-169163-02081		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-71-00/03, MRB Ref:72-55-00/06 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725501		**LP Turbine Shaft - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	3035689-2	New	0				Hrs	0				
	22-169163-02085		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:72-71-00/03, MRB Ref:72-55-00/06 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725502		**LP Turbine Drive Arm - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	3035610-2	New	0				Hrs	0				
	2218244940704		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/05, MRB Ref:72-71-00/04, MRB Ref:75-21-00/07 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725502		**LP Turbine Drive Arm - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	3035610-2	New	0				Hrs	0				
	2218244940707		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/05, MRB Ref:72-71-00/04, MRB Ref:75-21-00/07 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725503		**LP Turbine (LPT 1/ LPT 2) Interstage Rotating Seal - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	3035595-1	New	0				Hrs	0				
	2218244939777		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/07 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725503		**LP Turbine (LPT 1/ LPT 2) Interstage Rotating Seal - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	3035595-1	New	0				Hrs	0				
	2218244939974		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/07 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725504		**LP Turbine Stub Shaft - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	3035691-1	New	0				Hrs	0				
	19-162246-04058		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-71-00/05, MRB Ref:72-55-00/04 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725504		**LP Turbine Stub Shaft - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	3035691-1	New	0				Hrs	0				
	19-162246-02349		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:72-71-00/05, MRB Ref:72-55-00/04 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725508		**LP Turbine (LPT 1) Disks - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	3035593-1	New	0				Hrs	0				
	21-162246-05074		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/09 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725508		**LP Turbine (LPT 1) Disks - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	3035593-1	New	0				Hrs	0				
	21-162246-05063		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/09 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725509		**LP Turbine (LPT 2) Disks - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	3035661-1	New	0				Hrs	0				
	21-162246-04280		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/09 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725509		**LP Turbine (LPT 2) Disks - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	3035661-1	New	0				Hrs	0				
	21-162246-04600		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/09 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725510		**LP Turbine (LPT 3) Disks - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	3035663-1	New	0				Hrs	0				
	21-162246-03556		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/09 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
725510		**LP Turbine (LPT 3) Disks - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	3035663-1	New	0				Hrs	0				
	21-162246-05266		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/09 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
727101		**Spinner Inner Ring - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	70040459-1	New	0				Hrs	0				
	22-1034-39109		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-70-00, MRB Ref:72-71-00/12 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
727101		**Spinner Inner Ring - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	70040459-1	New	0				Hrs	0				
	22-1034-39113		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-70-00, MRB Ref:72-71-00/12 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
727102		**Spinner Cover Ring - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	70040460-1	New	0				Hrs	0				
	22-1034-34268		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-70-00, MRB Ref:72-71-00/11 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
727102		**Spinner Cover Ring - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	70040460-1	New	0				Hrs	0				
	22-1034-37470		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-70-00, MRB Ref:72-71-00/11 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
727103		**Fan Disk - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	70041043-1	New	0				Hrs	0				
	2218244940372		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-70-00, MRB Ref:72-71-00-06 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations.)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
727103		**Fan Disk - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	70041043-1	New	0				Hrs	0				
	2218244940509		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-70-00, MRB Ref:72-71-00-06 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations.)											
727104		**Fan Rotor Air Seal Plate - Discard**							RE		LMM 05-10-00 Airworthiness Limitations	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	70040470-1	New	0				Hrs	0				
	NSN		0				Enc	0	15,000		15,000	14,387 Enc
	(SOURCE: AS907-2-1G LMM (72-05-16))											
727104		**Fan Rotor Air Seal Plate - Discard**							RE		LMM 05-10-00 Airworthiness Limitations	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	70040470-1	New	0				Hrs	0				
	NSN		0				Enc	0	15,000		15,000	14,375 Enc
	(SOURCE: AS907-2-1G LMM (72-05-16))											
727105		**Fan Stub Shaft - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1		0				Mos	26-Jan-2023				
	3037099-1	New	0				Hrs	0				
	20-102045-09419		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-70-00, MRB Ref:72-71-00/09 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
727105		**Fan Stub Shaft - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2		0				Mos	20-Jan-2023				
	3037099-1	New	0				Hrs	0				
	20-102045-09379		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-70-00, MRB Ref:72-71-00/09 (SOURCE: G280 AMM) (NOTE: NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations)											
727106		**Engine Fan Blades - Special Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈11-Sep-2054**
	72 ENG1						Mos					
							Hrs					
	ATA Ref:72-71-00, MRB Ref:72-71-00-02 (SOURCE: G280 AMM)						Enc		15,000		15,000	14,387 Enc
727106		**Engine Fan Blades - Special Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈02-Sep-2054**
	72 ENG2						Mos					
							Hrs					
	ATA Ref:72-71-00, MRB Ref:72-71-00-02 (SOURCE: G280 AMM)						Enc		15,000		15,000	14,375 Enc
729101		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.1	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43368		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)											
729101		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.1	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43880		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)											
729102		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.2	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43369		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729102		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.2	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43881		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729103		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.3	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43370		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729103		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.3	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43891		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729104		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.4	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43371		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729104		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.4	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49834		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729105		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.5	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43372		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729105		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.5	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49835		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729106		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.6	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43373		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729106		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.6	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49836		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729107		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.7	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43374		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729107		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.7	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49837		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729108		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.8	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43375		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729108		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.8	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49838		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729109		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.9	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43376		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729109		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.9	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49839		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729110		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.10	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43377		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729110		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.10	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49840		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729111		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.11	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43378		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729111		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.11	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49841		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729112		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.12	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43379		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729112		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.12	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49842		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729113		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.13	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43380		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729113		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.13	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49843		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729114		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.14	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43381		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729114		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.14	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49844		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729115		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.15	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43382		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729115		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.15	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49845		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729116		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.16	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43383		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729116		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.16	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49846		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729117		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.17	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43384		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729117		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.17	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49847		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729118		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.18	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43385		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729118		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.18	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49848		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729119		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.19	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43386		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729119		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.19	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49849		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729120		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.20	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43387		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729120		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.20	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49850		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729121		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.21	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43388		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729121		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.21	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49851		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729122		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.22	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43389		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729122		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.22	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49852		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729123		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.23	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43390		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729123		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.23	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49853		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729124		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.24	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43391		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729124		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.24	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49854		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729125		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.25	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM43392		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729125		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.25	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49855		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729126		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.26	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44793		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729126		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.26	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49856		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729127		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.27	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44794		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729127		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.27	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49857		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729128		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.28	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44795		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729128		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.28	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM49858		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729129		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.29	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44796		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729129		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.29	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51234		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729130		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.30	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44797		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729130		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.30	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51235		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729131		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.31	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44798		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729131		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.31	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51236		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729132		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.32	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44799		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729132		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.32	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51237		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729133		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.33	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44800		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729133		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.33	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51238		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729134		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.34	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44801		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729134		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.34	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51239		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729135		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.35	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44802		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729135		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.35	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51240		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729136		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.36	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44803		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729136		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.36	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51241		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729137		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.37	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44804		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729137		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.37	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51242		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729138		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.38	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44805		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729138		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.38	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51243		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729139		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.39	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44806		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729139		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.39	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51244		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729140		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.40	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44807		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729140		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.40	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51245		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729141		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.41	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44808		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729141		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.41	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51246		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729142		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.42	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44809		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729142		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.42	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51247		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729143		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.43	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44810		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729143		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.43	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51248		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729144		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.44	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44811		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729144		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.44	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51249		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729145		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.45	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44812		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729145		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.45	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51250		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729146		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.46	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44813		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729146		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.46	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51251		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729147		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.47	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44814		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729147		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.47	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51252		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729148		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.48	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44815		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729148		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.48	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51253		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729149		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.49	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44816		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729149		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.49	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51254		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729150		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.50	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM44817		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729150		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.50	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51255		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729151		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.51	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM54067		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729151		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.51	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51256		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729152		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.52	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM54069		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729152		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.52	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51257		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729153		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.53	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM54070		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729153		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.53	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM51258		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729154		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.54	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM54071		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729154		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.54	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM52959		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729155		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.55	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM54074		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729155		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.55	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM52972		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729156		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.56	0				Mos	26-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM54076		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729156		**LP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.56	0				Mos	20-Jan-2023				
	3035693-2	New	0				Hrs	0				
	22HM53371		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729201		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.1	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55327		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729201		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.1	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55377		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729202		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.2	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55328		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729202		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.2	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55378		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729203		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.3	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55329		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729203		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.3	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55379		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729204		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.4	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55330		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729204		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.4	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55380		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729205		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.5	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55331		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729205		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.5	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55381		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729206		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.6	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55332		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729206		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.6	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55382		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729207		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.7	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55333		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729207		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.7	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55389		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729208		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.8	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55334		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729208		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.8	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55390		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729209		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.9	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55335		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729209		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.9	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55391		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729210		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.10	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55336		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729210		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.10	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55392		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729211		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.11	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55337		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729211		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.11	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55398		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729212		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.12	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55338		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729212		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.12	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55399		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729213		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.13	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55339		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729213		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.13	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56527		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729214		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.14	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55880		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729214		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.14	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56528		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729215		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.15	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55881		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729215		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.15	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56529		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729216		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.16	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55882		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729216		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.16	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56530		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729217		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.17	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55883		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729217		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.17	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56531		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729218		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.18	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55884		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729218		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.18	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56532		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729219		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.19	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55885		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729219		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.19	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56533		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729220		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.20	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55886		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729220		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.20	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56534		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729221		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.21	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55887		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729221		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.21	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56535		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729222		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.22	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55888		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729222		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.22	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56536		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729223		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.23	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55893		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729223		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.23	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56537		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729224		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.24	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55896		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729224		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.24	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56538		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729225		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.25	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55897		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729225		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.25	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56539		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729226		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.26	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM55898		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729226		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.26	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56540		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729227		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.27	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56752		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729227		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.27	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56541		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729228		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.28	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56753		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729228		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.28	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56542		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729229		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.29	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56754		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729229		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.29	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56543		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729230		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.30	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56755		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729230		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.30	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56544		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729231		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.31	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56756		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729231		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.31	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56545		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729232		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.32	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56757		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729232		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.32	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56546		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729233		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.33	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56758		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729233		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.33	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56547		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729234		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.34	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56759		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729234		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.34	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56548		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729235		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.35	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56760		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729235		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.35	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56549		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729236		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.36	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56761		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729236		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.36	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56550		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729237		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.37	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56762		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729237		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.37	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56551		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729238		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.38	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56763		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729238		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.38	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58052		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729239		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.39	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56764		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729239		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.39	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58053		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729240		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.40	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56765		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729240		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.40	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58054		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729241		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.41	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56766		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729241		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.41	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58055		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729242		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.42	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56767		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729242		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.42	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58056		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729243		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.43	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56768		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (AVG MAN HRS: 1) (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729243		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.43	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58057		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (AVG MAN HRS: 1) (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729244		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.44	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56769		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729244		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.44	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58058		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729245		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.45	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56770		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729245		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.45	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58059		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729246		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.46	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56771		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729246		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.46	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58060		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729247		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.47	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56772		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729247		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.47	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58061		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729248		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.48	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56773		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729248		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.48	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58062		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729249		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.49	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56774		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729249		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.49	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58063		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729250		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.50	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56775		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729250		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.50	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58064		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729251		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.51	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56776		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729251		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.51	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58065		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729252		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.52	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56902		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729252		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.52	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58066		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729253		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.53	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56903		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729253		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.53	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58067		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729254		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.54	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56904		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729254		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.54	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58068		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729255		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.55	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56905		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729255		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.55	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58069		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729256		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.56	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56906		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729256		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.56	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58070		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729257		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.57	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56907		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729257		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.57	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58071		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729258		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.58	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56908		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729258		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.58	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58072		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729259		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.59	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56909		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729259		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.59	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58073		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729260		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.60	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56910		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729260		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.60	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58074		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729261		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.61	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56914		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729261		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.61	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58075		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729262		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.62	0				Mos	26-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM56915		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729262		**LP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.62	0				Mos	20-Jan-2023				
	3035602-2	New	0				Hrs	0				
	22HM58076		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729301		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.1	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59759		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729301		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.1	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54104		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729302		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.2	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59760		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729302		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.2	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54105		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729303		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.3	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59761		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729303		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.3	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54106		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729304		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.4	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59762		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729304		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.4	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54107		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)											
729305		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.5	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59763		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)											
729305		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.5	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54108		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)											
729306		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.6	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59764		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)											
729306		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.6	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54109		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)											
729307		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.7	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59765		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)											
729307		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.7	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54110		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)											
729308		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.8	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59766		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)											
729308		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.8	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54116		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)											
729309		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.9	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59767		0				Enc	0	15,000		15,000	14,387 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729309		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.9	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54119		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729310		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.10	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59768		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729310		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.10	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54152		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729311		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.11	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59769		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729311		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.11	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54153		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729312		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.12	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59770		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729312		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.12	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54154		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729313		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.13	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59771		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729313		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.13	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54155		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729314		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.14	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59772		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729314		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.14	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54156		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729315		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.15	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59773		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729315		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.15	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54157		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729316		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.16	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59774		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729316		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.16	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54158		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729317		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.17	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59775		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729317		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.17	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54159		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729318		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.18	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59776		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729318		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.18	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54160		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729319		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.19	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59777		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729319		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.19	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54161		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729320		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.20	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59778		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729320		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.20	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54162		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729321		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.21	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59779		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729321		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.21	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54163		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729322		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.22	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59780		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729322		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.22	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54164		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729323		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.23	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59781		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729323		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.23	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54165		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729324		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.24	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59782		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729324		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.24	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54166		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729325		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.25	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59783		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729325		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.25	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54167		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729326		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.26	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59859		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729326		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.26	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54168		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729327		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.27	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59860		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729327		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.27	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54169		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729328		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.28	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59861		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729328		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.28	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54170		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729329		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.29	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59862		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729329		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.29	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54171		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729330		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.30	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59863		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729330		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.30	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54172		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729331		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.31	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59864		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729331		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.31	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54173		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729332		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.32	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59865		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729332		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.32	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54174		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729333		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.33	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59866		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729333		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.33	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54175		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729334		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.34	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59867		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729334		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.34	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54176		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729335		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.35	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59868		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (AVG MAN HRS: 2) (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729335		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.35	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54518		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (AVG MAN HRS: 2) (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729336		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.36	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59869		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729336		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.36	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54519		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729337		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.37	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59870		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729337		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.37	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54727		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729338		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.38	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59871		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729338		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.38	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54728		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729339		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.39	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59872		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (AVG MAN HRS: 7) (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729339		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.39	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54729		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (AVG MAN HRS: 7) (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729340		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.40	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59873		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729340		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.40	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54730		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729341		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.41	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59874		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729341		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.41	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54731		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729342		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.42	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59875		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729342		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.42	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54732		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729343		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.43	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59876		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729343		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.43	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54733		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729344		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.44	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59877		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729344		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.44	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54734		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729345		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.45	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59878		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729345		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.45	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54735		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729346		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.46	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59879		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729346		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.46	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54736		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729347		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.47	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59880		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729347		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.47	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54737		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729348		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.48	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59881		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729348		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.48	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54738		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729349		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.49	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59882		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729349		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.49	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54739		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729350		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.50	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM59883		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729350		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.50	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54740		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729351		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.51	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60459		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729351		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.51	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54741		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729352		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.52	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60460		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729352		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.52	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54742		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729353		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.53	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60461		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729353		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.53	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54743		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729354		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.54	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60462		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729354		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.54	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54744		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729355		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.55	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60463		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729355		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.55	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54745		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729356		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.56	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60464		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729356		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.56	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54746		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729357		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.57	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60465		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729357		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.57	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54747		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729358		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.58	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60466		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729358		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.58	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54748		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729359		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.59	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60467		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729359		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.59	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54749		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729360		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.60	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60468		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729360		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.60	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54750		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729361		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.61	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60469		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729361		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.61	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54751		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729362		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.62	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60470		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729362		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.62	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54927		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729363		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.63	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60471		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729363		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.63	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54928		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729364		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.64	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60472		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729364		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.64	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54929		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729365		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.65	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60473		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729365		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.65	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54930		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729366		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.66	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60474		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729366		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.66	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54931		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729367		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.67	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60475		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729367		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.67	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54932		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729368		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.68	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60476		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729368		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.68	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54933		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729369		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.69	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60477		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729369		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.69	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54934		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729370		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.70	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60478		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729370		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.70	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54935		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729371		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.71	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60479		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729371		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.71	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54936		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729372		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.72	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60480		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729372		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.72	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54937		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729373		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.73	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60481		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729373		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
	72 ENG2	No.73	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54938		0				Enc	0	15,000		15,000	14,375 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										
729374		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈11-Sep-2054**
	72 ENG1	No.74	0				Mos	26-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM60482		0				Enc	0	15,000		15,000	14,387 Enc
		ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729374		**LP Turbine Stage 3 Blades - Discard**							RE		05-10-00 Time Limits	**≈02-Sep-2054**
72 ENG2		No.74	0				Mos	20-Jan-2023				
	3035609-3	New	0				Hrs	0				
	22HM54939		0				Enc	0	15,000		15,000	14,375 Enc
	ATA Ref:72-50-00, MRB Ref:72-55-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003)											
▼ 1. RE 15000 Hrs												
728101		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
72 ENG1		No.1	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M14765		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728101		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
72 ENG2		No.1	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M15811		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728102		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
72 ENG1		No.2	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M15193		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728102		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
72 ENG2		No.2	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M15812		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728103		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
72 ENG1		No.3	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M15234		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728103		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
72 ENG2		No.3	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M15813		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728104		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
72 ENG1		No.4	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M15533		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
728104		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.4	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M15816		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728105		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.5	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M15536		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728105		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.5	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M15817		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728106		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.6	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M15722		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728106		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.6	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M15818		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728107		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.7	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M15794		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728107		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.7	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M15819		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728108		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.8	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M15800		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728108		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.8	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M21276		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
728109		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.9	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M15889		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728109		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.9	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M21277		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728110		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.10	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M15890		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728110		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.10	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M21279		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728111		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.11	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M15891		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728111		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.11	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M21281		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728112		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.12	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M15892		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728112		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.12	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M21288		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728113		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.13	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M15893		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
728113		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.13	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M23676		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728114		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.14	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M15894		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728114		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.14	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M23679		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728115		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.15	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M15895		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728115		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.15	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M23875		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728116		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.16	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M15903		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728116		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.16	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M23879		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728117		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.17	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M15920		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728117		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.17	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M23880		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
728118		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
72 ENG1		No.18	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M15942		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728118		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
72 ENG2		No.18	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M23996		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728119		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
72 ENG1		No.19	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M15973		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728119		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
72 ENG2		No.19	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M23998		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728120		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
72 ENG1		No.20	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M16117		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728120		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
72 ENG2		No.20	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M33624		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728121		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
72 ENG1		No.21	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M16180		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728121		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
72 ENG2		No.21	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M33711		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728122		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
72 ENG1		No.22	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M16199		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
728122		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
72 ENG2		No.22	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M33712		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728123		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
72 ENG1		No.23	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M16200		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728123		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
72 ENG2		No.23	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	22M21338		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728124		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
72 ENG1		No.24	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M16201		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728124		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
72 ENG2		No.24	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	22M21339		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728125		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
72 ENG1		No.25	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M16209		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728125		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
72 ENG2		No.25	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	22M21344		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728126		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
72 ENG1		No.26	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M16211		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728126		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
72 ENG2		No.26	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	22M21600		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
728127		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.27	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M16756		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728127		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.27	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	22M21601		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728128		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.28	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M16757		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728128		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.28	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	22M22021		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728129		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.29	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M16758		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728129		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.29	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	22M22066		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728130		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.30	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M16760		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728130		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.30	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	22M22072		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728131		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.31	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M16762		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
728131		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.31	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	22M22078		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728132		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.32	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M16763		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728132		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.32	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	22M22535		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728133		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.33	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M16764		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728133		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.33	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	22M22555		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728134		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.34	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M16766		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728134		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.34	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	22M22560		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728135		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.35	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M16768		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728135		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.35	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	22M22563		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
728136		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.36	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M31600		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728136		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.36	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	22M22594		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728137		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.37	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M34077		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728137		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.37	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	22M22595		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728138		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.38	0				Mos	26-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M03260		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728138		**HP Turbine Stage 1 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.38	0				Mos	20-Jan-2023				
	70040871-1	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	22M22893		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728201		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.1	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M26917		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728201		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.1	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M41281		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728202		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.2	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M26953		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
728202		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.2	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M41292		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728203		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.3	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M26954		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728203		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.3	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M41311		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728204		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.4	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M26955		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728204		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.4	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M41644		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728205		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.5	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M41738		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728205		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.5	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M41687		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728206		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.6	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M45412		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728206		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.6	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M41688		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728207		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.7	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M46854		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
728207		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.7	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M41689		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728208		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.8	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M55404		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728208		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.8	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M41850		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728209		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.9	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M55578		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728209		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.9	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M41851		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728210		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.10	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M55585		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728210		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.10	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M41852		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728211		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.11	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M66251		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728211		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.11	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M41918		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728212		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.12	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M66254		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
728212		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.12	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M41919		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728213		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.13	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M66259		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728213		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.13	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M41922		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728214		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.14	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M66261		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728214		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.14	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M41938		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728215		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.15	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	21M66262		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728215		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.15	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M41941		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728216		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.16	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M21497		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728216		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.16	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M42692		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728217		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.17	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M21506		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
728217		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.17	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M55685		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728218		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.18	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M21508		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728218		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.18	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M57712		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728219		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.19	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M21510		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728219		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.19	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M64312		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728220		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.20	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M21511		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728220		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.20	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M64313		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728221		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.21	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M21512		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728221		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.21	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M64314		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											
728222		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.22	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M21702		0				Enc	0				
	ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
728222		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.22	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M64317		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728223		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.23	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M22392		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728223		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.23	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M64319		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728224		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.24	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M22393		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728224		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.24	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M64320		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728225		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.25	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M22618		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728225		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.25	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M64329		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728226		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.26	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M22622		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728226		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.26	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M64330		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728227		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.27	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M22625		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
728227		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.27	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M65857		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728228		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.28	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M22627		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728228		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.28	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M65858		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728229		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.29	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M22679		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728229		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.29	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M65983		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728230		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.30	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M22682		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728230		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.30	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M65984		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728231		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.31	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M22689		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728231		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.31	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M65989		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728232		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.32	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M22692		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
728232		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.32	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M65991		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728233		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.33	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M22693		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728233		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.33	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M65997		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728234		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	72 ENG1	No.34	0				Mos	26-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22M22729		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
728234		**HP Turbine Stage 2 Blades - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	72 ENG2	No.34	0				Mos	20-Jan-2023				
	3035049-5	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	21M66317		0				Enc	0				
		ATA Ref:72-50-00, MRB Ref:72-51-00/02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G LMM, 05-20 Table 8003.)										
762101		**N1 Overspeed Shut-off Detector - Discard**							RE		05-10-00 Time Limits	**≈05-Feb-2044**
	76 ENG1		0				Mos	26-Jan-2023				
	3034256-4	New	0				Hrs	0	15,000		15000	13966:24 Hrs
	22-162151-00639		0				Enc	0				
		ATA Ref:76-21-00, MRB Ref:76-21-00-02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations.)										
762101		**N1 Overspeed Shut-off Detector - Discard**							RE		05-10-00 Time Limits	**≈26-Jan-2044**
	76 ENG2		0				Mos	20-Jan-2023				
	3034256-4	New	0				Hrs	0	15,000		15000	13946:24 Hrs
	22-162151-00917		0				Enc	0				
		ATA Ref:76-21-00, MRB Ref:76-21-00-02 (SOURCE: G280 AMM) (NOTE: Per Honeywell AS907-2-1G Airworthiness Limitations.)										
▼ 1. RE 16 Yrs												
344014		**EVS Inspection Of Interior Skin, Filler and Doubler (FS 76 - FS 102) for Environmental Deterioration**							RE			
	34 A/F						Yrs		16		31-Mar-2039	14.6 Years
							Hrs					
							Ldg					
344015		**Inspection Interior EVS Frames, Intercoastal and Camera Support For Environmental Deterioration**							RE			
	34 A/F						Yrs		16		31-Mar-2039	14.6 Years
							Hrs					
							Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 1. RE 18000 Hrs, 10 Yrs											
274101	**Horizontal Stabilizer Trim Actuator Mid Life Verification - Restore (*CMR)**							RE		05-10-10 CMR, 05-10-10 Life Limited Components, 05-20-00 Scheduled Maintenance Checks	
27 A/F					0	Yrs	20-Nov-2022	10		30-Nov-2032	8.2 Years
CA51580-006					0	Hrs	0	18,000		18000	16942 Hrs
0265					0	Ldg	0				
Restored Date 20-Nov-2022											
ATA Ref:27-41-01, CMR Ref:27-40-01 (SOURCE: G280 AMM) (NOTE: For Production installed actuators, comply with every 18,000 flight hours or 10 years from aircraft airworthiness date, whichever occurs first. For replacement actuators, comply with every 18,000 flight hours or 10 years, whichever occurs first, from actuator manufacture date or last Mid-Life Verification Restore, the latest applies.)											
▼ 1. RE 18800 Ldg											
322003	**Nose Landing Gear Assembly - Discard**							RE		05-10-00 Time Limits, 05-10-10 Life Limited Components	**≈14-Aug-2062**
32 A/F						Mos					
30A2720150-503						Hrs					
257						Ldg		18,800		18,800	18,182 Ldg
ATA Ref:32-20-00, MRB Ref:32-20-00-08 (SOURCE: G280 AMM) (NOTE: See Life Limited Components, 05-10-10, Airworthiness Limitations Section P/N G280-1001-3-2.)											
▼ 1. RE 192 Mos											
232741	**Ka-Band Equipment & Wiring (Vertical Stab Radome) - Visual Inspection**							RE			
23 A/F						Mos	02-Mar-2023	192		31-Mar-2039	14.6 Years
						Hrs	34:12				
						Ldg	10				
272106	**Rudder Servo Actuator Attach Points - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
27 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
ATA Ref:27-21-01, MRB Ref:27-20-00/04 (SOURCE: G280 AMM)						Hrs					
						Ldg					
273149	**Elevator Servo Actuator Attach Points - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
27 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
ATA Ref:27-31-04, MRB Ref:27-30-00/06 (SOURCE: G280 AMM)						Hrs					
						Ldg					
273150	**Elevator Servo Actuator Attach Points - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
27 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
ATA Ref:27-31-04, MRB Ref:27-30-00/06 (SOURCE: G280 AMM)						Hrs					
						Ldg					
530012	**Fuselage Door Section Upper Interior Skin Surface - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
ATA Ref:53-00-00, MRB Ref:53.21.00/03 (SOURCE: G280 AMM)						Hrs					
						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
530035		**Fuselage Door Section Upper Antenna Doublers - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-00-00, MRB Ref:53.21.00 / 15 (SOURCE: G280 AMM) (NOTE: NOTE: Remove antennas and all underlying attachments and riveted doublers. Initial compliance at 16C from EIS and every 16C thereafter. Aircraft beyond 168 months from EIS at date of Revision 19 (see List of Revisions), accomplish at next due compliance of Fuselage Door Section Upper Exterior Skin Under Antennas - Detailed Inspection, 53-00-00, Inspection / Check or Code 530011 and at every 16C thereafter.)					Hrs					
							Ldg					
531111		**Nose Section Lower Antenna Doublers - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-11-00, MRB Ref:53.10.00 / 11 (SOURCE: G280 AMM) (NOTE: NOTE: Doublers / contour plates removed. Initial compliance at 16C from EIS and every 16C thereafter. Aircraft beyond 168 months from EIS at date of Revision 19 (see List of Revisions), accomplish at next due compliance of Fuselage Door Section Lower Exterior Under Antennas - Detailed Inspection, 53-00-00, Inspection / Check or Code 530015 and at every 16C thereafter.)					Hrs					
							Ldg					
531203		**Cockpit Interior Above Headliner - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-12-01, MRB Ref:53-200-03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
531212		**Cockpit External Skin - General Visual Inspection**							RE			
	53 A/F						Mos		192		31-Mar-2039	14.6 Years
							Hrs					
							Ldg					
531215		**Cockpit Window Structure (Internal) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-12-02, MRB Ref:53.17.00/04 (SOURCE: G280 AMM) (NOTE: Perform at windshield removal not to exceed 16C.)					Hrs					
							Ldg					
531218		**Cockpit Window Internal Surface - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-12-02, MRB Ref:53.17.00/08 (SOURCE: G280 AMM) (NOTE: Perform at windshield removal not to exceed 16C.)					Hrs					
							Ldg					
531251		**Cockpit Lower Antenna Doublers - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-12-01, MRB Ref:53.11.00 / 16 (SOURCE: G280 AMM) (NOTE: NOTE: Remove antennas and all underlying attachments and riveted doublers. Initial compliance at 16C from EIS and every 16C thereafter. Aircraft beyond 168 months from EIS at date of Revision 19 (see List of Revisions), accomplish at next due compliance of Fuselage Door Section Lower Exterior Under Antennas - Detailed Inspection, 53-00-00, Inspection / Check or Code 530015 and at every 16C thereafter.)					Hrs					
							Ldg					
531305		**Cabin Entrance Above Floor - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-13-01, MRB Ref:53-200-05 (SOURCE: G280 AMM)					Hrs					
							Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
531307		**Forward Cabin Above Floor - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-13-01, MRB Ref:53-200-06 (SOURCE: G280 AMM)					Hrs					
							Ldg					
531311		**Upper Fuselage Internal Including Antenna Penetrations - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-13-01, MRB Ref:53.23.00/08 (SOURCE: G280 AMM)					Hrs					
							Ldg					
531340		**Forward Cabin Antenna Doublers - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-13-01, MRB Ref:53.23.00 / 15 (SOURCE: G280 AMM) (NOTE: NOTE: Remove antennas and all underlying attachments and riveted doublers. Initial compliance at 16C from EIS and every 16C thereafter. Aircraft beyond 168 months from EIS at date of Revision 19 (see list of revisions), accomplish at next due compliance of Forward Cabin Skin Under Antenna - Detailed Inspection, 53-13-01, Inspection / Check or Code 531308 Forward Cabin Skin Under Antenna - Detailed Inspection or code 531308 and at every 16C thereafter.)					Hrs						
							Ldg					
531409		**Forward Fuel Tank - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-14-00, MRB Ref:53.30.01/03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
531501		**Fuselage Drain Valve, Frame 4 and Frame 12 - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-00-00, MRB Ref:53-00-00/03 (SOURCE: G280 AMM) (NOTE: Accomplish at 16C since new.)					Hrs					
							Ldg					
531502		**Fuselage Drain Valve, Frame 27 - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-00-00, MRB Ref:53-00-00/01 (SOURCE: G280 AMM) (NOTE: Accomplish at 16C since new.)					Hrs					
							Ldg					
531504		**Baggage Compartment Drain Valve, Frame 43 - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-00-00, MRB Ref:53-00-00/05 (SOURCE: G280 AMM) (NOTE: Accomplish at 16C since new.)					Hrs					
							Ldg					
531505		**Fuselage Drain Holes - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-00-00, MRB Ref:53-00-00/07 (SOURCE: G280 AMM) (NOTE: Accomplish at 16C since new.)					Hrs					
							Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
532017		**Lavatory Area Upper Fuselage Internal Skin Including Antenna Penetrations - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-20-00, MRB Ref:53.27.00 / 03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
532099		**Exterior Upper Antenna Doublers - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref :53-20-00, MRB Ref:53.25.00 / 15 (SOURCE: G280 AMM) (NOTE: NOTE: Remove antennas and all underlying attachments and riveted doublers. Initial compliance at 16C from EIS and every 16C thereafter. Aircraft beyond 168 months from EIS at date of Revision 19 (see list of revisions), accomplish at next due compliance of Exterior Upper Skin Under Antennas - Detailed Inspection, 53-20-00, Inspection / Check or Code 532011 and at every 16C thereafter.)					Hrs					
							Ldg					
532102		**Lavatory and Aft Radio Rack - Cleaning**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-21-01, MRB Ref:53-200-EZIP-06 (SOURCE: G280 AMM)					Hrs					
							Ldg					
532105		**Aft Cabin Above Floor (Internal) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-21-01, MRB Ref:53-200-07 (SOURCE: G280 AMM)					Hrs					
							Ldg					
532106		**Aft Cabin Lavatory Area (Above Floor) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-21-01, MRB Ref:53-200-08 (SOURCE: G280 AMM)					Hrs					
							Ldg					
532112		**Upper Fuselage Internal Including Antenna Penetrations and Doublers - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-21-01, MRB Ref:53.25.00 / 03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
532118		**Auxiliary Pressure Bulkhead Aft Side Wall - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-21-02, MRB Ref:53.05.00/05 (SOURCE: G280 AMM)					Hrs					
							Ldg					
532120		**Auxiliary Pressure Bulkhead Forward Right Side Wall - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-21-02, MRB Ref:53.05.00/07 (SOURCE: G280 AMM)					Hrs					
							Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
532121		**Auxiliary Pressure Bulkhead Forward Left Side Wall - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-21-02, MRB Ref:53.05.00/08 (SOURCE: G280 AMM)					Hrs					
							Ldg					
532126		**Aft Cabin Floor Structure and Surrounding Area Above WL 12.99 - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-21-02, MRB Ref:53.25.00/09 (SOURCE: G280 AMM)					Hrs					
							Ldg					
532204		**Baggage Compartment Internal Upper Skin and Penetrations - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-22-01, MRB Ref:53.40.02 / 03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
532304		**Aft Fuel Tank - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-23-00, MRB Ref:53.30.03/03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
533003		**ECS Compartment Interior Lower Skin Panel and VHF 3 Antenna Skin Penetration - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-30-00, MRB Ref:553.50.01 / 05 (SOURCE: G280 AMM)					Hrs					
							Ldg					
533005		**Aft Pressure Bulkhead - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-30-00, MRB Ref:53.50.01/09 (SOURCE: G280 AMM)					Hrs					
							Ldg					
551112		**Horizontal Stabilizer Pivot Points (Horizontal Stabilizer Installed) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:55-11-01, MRB Ref:55.02.00/06 (SOURCE: G280 AMM)					Hrs					
							Ldg					
551118		**Horizontal Stabilizer Box Structure - Special Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:55-11-01, MRB Ref:55.11.00/07 (SOURCE: G280 AMM)					Hrs					
							Ldg					
551121		**Horizontal Stabilizer Box Structure External Rib 4 - Rib 10 - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:55-11-01, MRB Ref:55.11.00/11 (SOURCE: G280 AMM)					Hrs					
							Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
551123		**Horizontal Stabilizer Inner Torsion Box (Internal) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:55-11-01, MRB Ref:55-300-04 (SOURCE: G280 AMM)					Hrs					
							Ldg					
552001		**Elevator Torsion Box External Surface (Left) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:55-20-00, MRB Ref:55.21.00/02 (SOURCE: G280 AMM)					Hrs					
							Ldg					
552002		**Elevator Torsion Box External Surface (Right) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:55-20-00, MRB Ref:55.21.00/02 (SOURCE: G280 AMM)					Hrs					
							Ldg					
552005		**Elevator Box Structure (Left) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:55-20-00, MRB Ref:55.21.00/04 (SOURCE: G280 AMM)					Hrs					
							Ldg					
552006		**Elevator Box Structure (Right) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:55-20-00, MRB Ref:55.21.00/04 (SOURCE: G280 AMM)					Hrs					
							Ldg					
553016		**Vertical Stabilizer Box Structure (Composite Components) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:55-30-00, MRB Ref:55.31.00/07 (SOURCE: G280 AMM)					Hrs					
							Ldg					
553103		**Vertical Stabilizer Box (Internal) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:55-31-01, MRB Ref:55-300-06 (SOURCE: G280 AMM)					Hrs					
							Ldg					
554002		**Rudder (Internal) - Special Detailed Inspection (NDT)**							RE	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:55-40-00, MRB Ref:55.41.00/03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
554004		**Rudder Structure - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:55-40-00, MRB Ref:55.41.00/05 (SOURCE: G280 AMM)					Hrs					
							Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
570013		**Wing Leading Edge Front Spar - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-00-00, MRB Ref:57-500-03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
570014		**Wing Leading Edge Front Spar - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-00-00, MRB Ref:57-500-03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
570015		**Winglet Attachment - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-00-00, MRB Ref:57-500-06 (SOURCE: G280 AMM)					Hrs					
							Ldg					
570016		**Winglet Attachment - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-00-00, MRB Ref:57-500-06 (SOURCE: G280 AMM)					Hrs					
							Ldg					
571603		**Wing to Fuselage Attachment Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-16-00, MRB Ref:57.16.00/01, MRB Ref:57.16.00/02, MRB Ref:57.16.00/03, MRB Ref:57.16.00/04, MRB Ref:57.16.00/05, MRB Ref:57.16.00/06, MRB Ref:57.16.00/07 (SOURCE: G280 AMM)					Hrs					
							Ldg					
571604		**Wing to Fuselage Attachment Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-16-00, MRB Ref:57.16.00/01, MRB Ref:57.16.00/02, MRB Ref:57.16.00/03, MRB Ref:57.16.00/04, MRB Ref:57.16.00/05, MRB Ref:57.16.00/06, MRB Ref:57.16.00/07 (SOURCE: G280 AMM)					Hrs					
							Ldg					
573107		**Winglet Forward and Aft Shear Supports - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-31-01, MRB Ref:57.15.00/02 (SOURCE: G280 AMM)					Hrs					
							Ldg					
573108		**Winglet Forward and Aft Shear Supports - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-31-01, MRB Ref:57.15.00/02 (SOURCE: G280 AMM)					Hrs					
							Ldg					
573109		**Winglet Assembly - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-31-01, MRB Ref:57.15.00/03 (SOURCE: G280 AMM)					Hrs					
							Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
573110		**Winglet Assembly - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-31-01, MRB Ref:57.15.00/03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
573111		**Winglet Bonded Assembly and Winglet Leading Edge Skin - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-31-01, MRB Ref:57.15.00/05 (SOURCE: G280 AMM)					Hrs					
							Ldg					
573112		**Winglet Bonded Assembly and Winglet Leading Edge Skin - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-31-01, MRB Ref:57.15.00/05 (SOURCE: G280 AMM)					Hrs					
							Ldg					
575001		**Inboard Fixed Trailing Edge Bonded Assemblies - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-50-00, MRB Ref:57.50.02/03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
575002		**Inboard Fixed Trailing Edge Bonded Assemblies - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-50-00, MRB Ref:57.50.02/03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
575103		**Main Landing Gear Door (Bonded Assembly) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-51-00, MRB Ref:57.14.00/03, MRB Ref:57.14.00/05 (SOURCE: G280 AMM)					Hrs					
							Ldg					
575104		**Main Landing Gear Door (Bonded Assembly) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-51-00, MRB Ref:57.14.00/05, MRB Ref:57.14.00/03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
576005		**Aileron Torsion Box and Trailing Edge - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-60-00, MRB Ref:57.50.01/04 (SOURCE: G280 AMM)					Hrs					
							Ldg					
576006		**Aileron Torsion Box and Trailing Edge - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-60-00, MRB Ref:57.50.01/04 (SOURCE: G280 AMM)					Hrs					
							Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
712003	**Forward Engine Mount, Yoke, Link, Fittings and Bolts - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
71 A/F						Mos	02-Mar-2023	192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
	ATA Ref:71-20-00, MRB Ref:71.20.01/02, MRB Ref:71.20.02/02, MRB Ref:71.20.01/05, MRB Ref:71.20.02/03 (Manual Adjustment: 20d) (SOURCE: G280 AMM)					Hrs	34:12				
						Ldg	10				
712004	**Forward Engine Mount, Yoke, Link, Fittings and Bolts - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
71 A/F						Mos	02-Mar-2023	192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
	ATA Ref:71-20-00, MRB Ref:71.20.01/02, MRB Ref:71.20.02/02, MRB Ref:71.20.01/05, MRB Ref:71.20.02/03 (Manual Adjustment: 20d) (SOURCE: G280 AMM)					Hrs	34:12				
						Ldg	10				
712007	**Engine Mount Assemblies - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
71 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
	ATA Ref:71-20-00, MRB Ref:71.20.02/01, MRB Ref:71.20.01/03, MRB Ref:71.20.01/01 (SOURCE: G280 AMM)					Hrs					
						Ldg					
712008	**Engine Mount Assemblies - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
71 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
	ATA Ref:71-20-00, MRB Ref:71.20.02/01, MRB Ref:71.20.01/03, MRB Ref:71.20.01/01 (SOURCE: G280 AMM)					Hrs					
						Ldg					
▼ 1. RE 2000 Hrs											
212123	**Ram Air Check Valve - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈19-Dec-2025**
21 A/F						Mos					
						Hrs		2,000	-/+50	2000	942 Hrs (+50)
	ATA Ref:21-21-05, MRB Ref:21-10-00-01 (SOURCE: G280 AMM) (NOTE: Task satisfies CCMR 21-30-04 at 4A. Note (1) Escalations are not permitted which would exceed the Candidate CMR (CCMR) interval.)					Ldg					
213123	**Baggage Compartment Differential Pressure Switch - Functional Check**							RE	05-20-00 Scheduled Maintenance Checks		**≈19-Dec-2025**
21 A/F						Mos					
						Hrs		2,000	-/+50	2000	942 Hrs (+50)
	ATA Ref:21-31-04, MRB Ref:21-35-00/02 (SOURCE: G280 AMM)					Ldg					
273415	**Eddy Current Damper - Functional Check (*CMR)**							RE	05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks		**≈19-Dec-2025**
27 A/F						Mos					
						Hrs		2,000	-/+50	2000	942 Hrs (+50)
	ATA Ref:27-34-03, CMR Ref:27-30-03 (SOURCE: G280 AMM)					Ldg					
280001	**Cross-side Jettison - Operational Check (CMR**)**							RE		05-10-10 CMR	**≈19-Dec-2025**
28 A/F						Mos					
						Hrs		2,000		2000	942 Hrs
	ATA Ref:28-00-00, CMR Ref:28-00-01, MRB Ref:28-30-00-01, MRB Ref:28-20-00-04 (SOURCE: G280 AMM) (NOTE: Applies to Aircraft 2001 thru Aircraft 2264.)					Ldg					
280002	**Fuel Jettison System - Functional Check (**CMR)**							RE		05-10-10 CMR	**≈19-Dec-2025**
28 A/F						Mos					
						Hrs		2,000	-/+50	2000	942 Hrs (+50)
	ATA Ref:28-00-00, CMR Ref:28-00-04 (SOURCE: G280 AMM) (NOTE: NOTE: Applies to Aircraft 2001 thru Aircraft 2264.)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
281113		**Wing Aft Spar (Left) - Detailed Inspection (**CMR)**							RE		05-10-10 CMR	**≈19-Dec-2025**
	28 A/F						Mos					
							Hrs		2,000	-/+50	2000	942 Hrs (+50)
		ATA Ref:28-11-04, CMR Ref:28-00-07 (SOURCE: G280 AMM) (NOTE: (1) Task satisfies the Fuel System Airworthiness Limitations Inspections requirement.)					Ldg					
281114		**Wing Aft Spar (Right) - Detailed Inspection (**CMR)**							RE		05-10-10 CMR	**≈19-Dec-2025**
	28 A/F						Mos					
							Hrs		2,000	-/+50	2000	942 Hrs (+50)
		ATA Ref:28-11-04, CMR Ref:28-00-07 (SOURCE: G280 AMM) (NOTE: (1) Task satisfies the Fuel System Airworthiness Limitations Inspections requirement.)					Ldg					
725009		**Turbine Stage 1 Rotor Blade and Aft Flow Discourager - Special Detailed Inspection**							RE	05-20-00	Scheduled Maintenance Checks	**≈01-Jan-2026**
	72 ENG1						Mos					
							Hrs		2,000	-/+50	2000	966:24 Hrs (+50)
		ATA Ref:72-00-00, MRB Ref:72-51-00-09 (SOURCE: G280 AMM) (NOTE: Accomplish at 4A since new. Aircraft past 1500 flight hours, accomplish within 500 flight hours from date of Revision 8 (see List of Revisions) and every 4A thereafter.)					Enc					
725009		**Turbine Stage 1 Rotor Blade and Aft Flow Discourager - Special Detailed Inspection**							RE	05-20-00	Scheduled Maintenance Checks	**≈22-Dec-2025**
	72 ENG2						Mos					
							Hrs		2,000	-/+50	2000	946:24 Hrs (+50)
		ATA Ref:72-00-00, MRB Ref:72-51-00-09 (SOURCE: G280 AMM) (NOTE: Accomplish at 4A since new. Aircraft past 1500 flight hours, accomplish within 500 flight hours from date of Revision 8 (see List of Revisions) and every 4A thereafter.)					Enc					
783205		**Electro-Hydraulic Lock Assembly (Left) - Operational Check (**CMR)**							RE		05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks	**≈19-Dec-2025**
	78 A/F						Mos					
							Hrs		2,000	-/+50	2000	942 Hrs (+50)
		ATA Ref:78-32-00, CMR Ref:78-00-02 (SOURCE: G280 AMM) (NOTE: Accomplish at 2000 flight hours or 8A, whichever occurs first.)					Ldg					
783206		**Electro-Hydraulic Lock Assembly (Right) - Operational Check (**CMR)**							RE		05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks	**≈19-Dec-2025**
	78 A/F						Mos					
							Hrs		2,000	-/+50	2000	942 Hrs (+50)
		ATA Ref:78-32-00, CMR Ref:78-00-02 (SOURCE: G280 AMM) (NOTE: Accomplish at 2000 flight hours or 8A, whichever occurs first.)					Ldg					
▼ 1. RE 2000 Ldg												
321327		**Main Landing Gear Door Lower Rod Assembly - Discard**							RE		05-10-10 Life Limited Components	**≈17-Jul-2027**
	32 A/F	Left					Mos					
	30P265036001-501 NSN						Hrs					
							Ldg		2,000		2,000	1,382 Ldg
		ATA Ref:32-13-03 (SOURCE: G280 AMM)										
321328		**Main Landing Gear Door Lower Rod Assembly - Discard**							RE		05-10-10 Life Limited Components	**≈17-Jul-2027**
	32 A/F	Right					Mos					
	30P265036001-501 NSN						Hrs					
							Ldg		2,000		2,000	1,382 Ldg
		ATA Ref:32-13-03 (SOURCE: G280 AMM)										
▼ 1. RE 20000 Hrs												
273407		**Force Disconnect Unit - Detailed Inspection (*CMR)**							RE		05-10-10 CMR	**≈09-Jan-2051**
	27 A/F						Mos					
							Hrs		20,000	-/+50	20000	18942 Hrs (+50)
		ATA Ref:27-34-01, CMR Ref:27-30-04 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
275111		**Flap Actuator - Restore (*CMR)**							RE		05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks	**≈09-Jan-2051**
	27 A/F	Left Inboard					Mos					
	C64897-003						Hrs		20,000	-/+50	20000	18942 Hrs (+50)
	B0356A						Ldg					
	ATA Ref:27-51-02, CMR Ref:27-50-01 (SOURCE: G280 AMM)											
275112		**Flap Actuator - Restore (*CMR)**							RE		05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks	**≈09-Jan-2051**
	27 A/F	Right Inboard					Mos					
	C64897-003						Hrs		20,000	-/+50	20000	18942 Hrs (+50)
	B0361A						Ldg					
	ATA Ref:27-51-02, CMR Ref:27-50-01 (SOURCE: G280 AMM)											
275113		**Flap Actuator - Restore (*CMR)**							RE		05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks	**≈09-Jan-2051**
	27 A/F	Left Outboard					Mos					
	C64899-003						Hrs		20,000	-/+50	20000	18942 Hrs (+50)
	B0181A						Ldg					
	ATA Ref:27-51-02, CMR Ref:27-50-01 (SOURCE: G280 AMM)											
275114		**Flap Actuator - Restore (*CMR)**							RE		05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks	**≈09-Jan-2051**
	27 A/F	Right Outboard					Mos					
	C64899-004						Hrs		20,000	-/+50	20000	18942 Hrs (+50)
	B0181A						Ldg					
	ATA Ref:27-51-02, CMR Ref:27-50-01 (SOURCE: G280 AMM)											
▼ 1. RE 20000 Ldg												
321119		**Main Landing Gear Installation - Discard**							RE		05-10-00 Time Limits, 05-10-10 Life Limited Components	**≈14-Feb-2065**
	32 A/F	Left					Mos					
	30A2520100-509						Hrs					
	257						Ldg		20,000		20,000	19,382 Ldg
	MRB Ref:32-10-00-09, Ref#:32-10-00-RI (SOURCE: G280 AMM) (NOTE: 05-10-00 NOTE: See Life Limited Components, 05-10-10, Airworthiness Limitations Section P/N G280-1001-3-2. 05-10-10 NOTE: For any flight operation where there is a landing after a steep approach which is greater than 4.5 degrees, the life status tracking of this part / assembly shall be updated to record the cycle as 2.8 flight cycles. Therefore, a record of such approaches should be kept.)											
321120		**Main Landing Gear Installation - Discard**							RE		05-10-00 Time Limits, 05-10-10 Life Limited Components	**≈14-Feb-2065**
	32 A/F	Right					Mos					
	30A2520100-510						Hrs					
	257						Ldg		20,000		20,000	19,382 Ldg
	MRB Ref:32-10-00-09, Ref#:32-10-00-RI (SOURCE: G280 AMM) (NOTE: 05-10-00 NOTE: See Life Limited Components, 05-10-10, Airworthiness Limitations Section P/N G280-1001-3-2. 05-10-10 NOTE: For any flight operation where there is a landing after a steep approach which is greater than 4.5 degrees, the life status tracking of this part / assembly shall be updated to record the cycle as 2.8 flight cycles. Therefore, a record of such approaches should be kept.)											
▼ 1. RE 24 Mos												
213209		**Alternate Heat Exchanger Inlet - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	21 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	ATA Ref:21-32-02, MRB Ref:21-10-00/04 (SOURCE: G280 AMM)						Hrs					
							Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
213213		**Alternate Air Check Valve - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
21 A/F							Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:21-32-03, MRB Ref:21-10-00/03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
232740		**Ka-Band Equipment & Wiring (Aft Fuselage Accy) - Visual Inspection**							RE			
23 A/F							Mos		24		[31-Mar-2025]	6.7 Months
							Hrs					
							Ldg					
235109		**Audio Options Panel Emergency / Normal Switch and 121.5 / Communication Switch - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		
23 A/F							Mos	02-Mar-2023	24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:23-51-02, MRB Ref:23-82-00/01, MRB Ref:23-82-00/02 (Manual Adjustment: 20d) (SOURCE: G280 AMM)					Hrs	34:12				
							Ldg	10				
236101		**Static Discharger - Functional Check**							RE	05-20-00 Scheduled Maintenance Checks		
23 A/F							Mos	02-Mar-2023	24	-/+1m	30-Apr-2025	7.7 Months (+30 Days)
		ATA Ref:23-61-01, MRB Ref:23-60-00/01 (Manual Adjustment: 44d) (SOURCE: G280 AMM)					Hrs	34:12				
							Ldg	10				
251206		**Crew Seat Inertia Reels - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		
25 A/F							Mos	02-Mar-2023	24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:25-12-01, MRB Ref:25-11-00/01 (Manual Adjustment: 20d) (SOURCE: G280 AMM)					Hrs	34:12				
							Ldg	10				
251207		**Crew Seat Restraints - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
25 A/F							Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:25-12-01, MRB Ref:25-11-00/02 (SOURCE: G280 AMM)					Hrs					
							Ldg					
252142		**Passenger Seat (including divan if installed) Restraints - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
25 A/F							Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:25-21-03, ATA Ref:25-21-01 (SOURCE: G280 AOMM) (NOTE: See Passenger Seats Restraints - Detailed Inspection.)					Hrs					
							Ldg					
252143		**Passenger Seats Inertia Reels - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		
25 A/F							Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:25-12-01 (SOURCE: G280 AOMM)					Hrs					
							Ldg					
256031		**Ditching Line - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
25 A/F							Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:25-60-00 (SOURCE: G280 AOMM)					Hrs					
							Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
261201		**APU Fire Detection System Unattended Mode - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		
	26 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:26-12-00, MRB Ref:26-10-00/01 (SOURCE: G280 AMM)					Hrs					
							Ldg					
275011		**Flap Drive System - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	27 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:27-51-00, MRB Ref:27-50-00/03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
276001		**Aircraft Configuration Message - Operational Test**							RE	05-20-00 Scheduled Maintenance Checks		
	27 A/F						Mos	02-Mar-2023	24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:27-60-00, MRB Ref:27-60-00/01 (Manual Adjustment: 20d) (SOURCE: G280 AMM)					Hrs	34:12				
							Ldg	10				
276010		**Air Brake Retraction - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		
	27 A/F						Mos	02-Mar-2023	24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:27-60-00, MRB Ref:27-60-00/02 (Manual Adjustment: 20d) (SOURCE: G280 AMM)					Hrs	34:12				
							Ldg	10				
276115		**Spoiler Actuator Installation (Left Inboard Multifunction) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	27 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:27-61-01, MRB Ref:27-60-00/03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
276116		**Spoiler Actuator Installation (Left Outboard Multifunction) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	27 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:27-61-01, MRB Ref:27-60-00/03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
276117		**Spoiler Actuator Installation (Left Ground) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	27 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:27-61-01, MRB Ref:27-60-00/03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
276118		**Spoiler Actuator Installation (Right Inboard Multifunction) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	27 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:27-61-01, MRB Ref:27-60-00/03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
276119		**Spoiler Actuator Installation (Right Outboard Multifunction) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	27 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:27-61-01, MRB Ref:27-60-00/03 (SOURCE: G280 AMM)					Hrs					
							Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
276120		**Spoiler Actuator Installation (Right Ground) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	27 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:27-61-01, MRB Ref:27-60-00/03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
276121		**Multifunction Spoiler Board Freeplay - Functional Check**							RE			
	27 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:27-60-00, Mfg#:27-60-00-AT (NOTE: NOTE: Accomplish at 2C from EIS. Aircraft beyond 12 months from EIS at the date of Revision 19 (see List of Revisions), accomplish at next compliance of Aircraft Configuration Message - Operational Test, 27-60-00, Adjustment / Test or Code 276001 and at every 2C thereafter.)					Hrs					
							Ldg					
276122		**Multifunction Spoiler Board Freeplay - Functional Check**							RE			
	27 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:27-60-00, Mfg#:27-60-00-AT (NOTE: NOTE: Accomplish at 2C from EIS. Aircraft beyond 12 months from EIS at the date of Revision 19 (see List of Revisions), accomplish at next compliance of Aircraft Configuration Message - Operational Test, 27-60-00, Adjustment / Test or Code 276001 and at every 2C thereafter.)					Hrs					
							Ldg					
276123		**Multifunction Spoiler Board Freeplay - Functional Check**							RE			
	27 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:27-60-00, Mfg#:27-60-00-AT (NOTE: NOTE: Accomplish at 2C from EIS. Aircraft beyond 12 months from EIS at the date of Revision 19 (see List of Revisions), accomplish at next compliance of Aircraft Configuration Message - Operational Test, 27-60-00, Adjustment / Test or Code 276001 and at every 2C thereafter.)					Hrs					
							Ldg					
276124		**Multifunction Spoiler Board Freeplay - Functional Check**							RE			
	27 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:27-60-00, Mfg#:27-60-00-AT (NOTE: NOTE: Accomplish at 2C from EIS. Aircraft beyond 12 months from EIS at the date of Revision 19 (see List of Revisions), accomplish at next compliance of Aircraft Configuration Message - Operational Test, 27-60-00, Adjustment / Test or Code 276001 and at every 2C thereafter.)					Hrs					
							Ldg					
313102		**Flight Data Recorder - Functional Check**							RE	05-20-00 Scheduled Maintenance Checks		
	31 A/F						Mos	04-Jun-2024	24	-/+1m	30-Jun-2026	1.8 Years (+30 Days)
		ATA Ref:31-31-00, MRB Ref:31-31-00/04 (SOURCE: G280 AMM) (NOTE: Applicable to Aircraft S/N 2003 and Aircraft with SB 280-31-009. As required by CFR or National Aviation Authority requirement.)					Hrs	866:28				
							Ldg	501				
313118		**Underwater Locator Beacon - Functional Check**							RE	05-20-00 Scheduled Maintenance Checks		
	31 A/F	No.1					Mos	31-Mar-2023	24		30-Apr-2025	7.7 Months
	Unknown						Hrs	34:12				
	Unknown	ATA Ref:31-31-05, MRB Ref:31-31-00-03 (Manual Adjustment: 20d) (SOURCE: G280 AMM) (NOTE: Accomplish at EMPFR ULB installation and every 24 Months thereafter.)					Ldg	10				
313129		**Underwater Locator Beacon - Functional Check**							RE	05-20-00 Scheduled Maintenance Checks		
	31 A/F	No.2					Mos	31-Mar-2023	24		31-Mar-2025	6.7 Months
	Unknown						Hrs					
	Unknown	ATA Ref:31-31-05, MRB Ref:31-31-00-03 (SOURCE: G280 AMM) (NOTE: Accomplish at EMPFR ULB installation and every 24 Months thereafter.)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
313132		**Underwater Locator Beacon - Switch Cleaning**							RE	05-20-00 Scheduled Maintenance Checks		
	31 A/F	No.1					Mos	31-Mar-2023	24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	Unknown											
	Unknown						Hrs					
	ATA Ref:31-31-05, MRB Ref:31-31-00-08 (SOURCE: G280 AMM) (NOTE: Accomplish at EMPFR ULB installation and every 24 Months thereafter.)						Ldg					
313133		**Underwater Locator Beacon - Switch Cleaning**							RE	05-20-00 Scheduled Maintenance Checks		
	31 A/F	No.2					Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	Unknown											
	Unknown						Hrs					
	ATA Ref:31-31-05, MRB Ref:31-31-00-08 (SOURCE: G280 AMM) (NOTE: Accomplish at EMPFR ULB installation and every 24 Months thereafter.)						Ldg					
324439		**Hydraulic Fuses - Functional Check**							RE	05-20-00 Scheduled Maintenance Checks		
	32 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	ATA Ref:32-44-05, MRB Ref:32-41-00/01 (SOURCE: G280 AMM)						Hrs					
							Ldg					
333101		**Baggage Compartment Door "No Entry" Illuminated sign - Operational Test**							RE	05-20-00 Scheduled Maintenance Checks		
	33 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	ATA Ref:33-27-00 (SOURCE: G280 AOMM) (NOTE: See No Entry Sign - Operational Check.)						Hrs					
							Ldg					
334003		**Wing Tip Light Lens (Left) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	33 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	ATA Ref:33-40-00, MRB Ref:33-40-00/02 (SOURCE: G280 AMM)						Hrs					
							Ldg					
334004		**Wing Tip Light Lens (Right) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	33 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	ATA Ref:33-40-00, MRB Ref:33-40-00/02 (SOURCE: G280 AMM)						Hrs					
							Ldg					
335005		**Cabin Emergency Lighting - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		
	33 A/F						Mos	02-Mar-2023	24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	ATA Ref:33-50-00, ATA Ref:33-51-00, MRB Ref:33-50-00/01 (Manual Adjustment: 20d) (SOURCE: G280 AMM / G280 AOMM)						Hrs	34:12				
							Ldg	10				
341101		**Altitude Accuracy Test (No. 1 Air Data System)**							RE	05-20-00 Scheduled Maintenance Checks		
	34 A/F						Mos	02-Mar-2023	24		31-Mar-2025	6.7 Months
	Tested Date 02-Mar-2023						Hrs	34:12				
	ATA Ref:34-11-00 (SOURCE: G280 AMM)						Ldg	10				
341103		**Pitot / Static System - Reconnect Check, Functional check (Per CFR 91.411 or National Aviation Authority. RVSM requirement.)**							RE	05-20-00 Scheduled Maintenance Checks		
	34 A/F						Mos	02-Mar-2023	24		31-Mar-2025	6.7 Months
	Certified Date 02-Mar-2023						Hrs	34:12				
	ATA Ref:34-11-00 (SOURCE: G280 AMM) (NOTE: CAA Requirement)						Ldg	10				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
341104		**Altitude Accuracy Test (No. 2 Air Data System)**							RE	05-20-00 Scheduled Maintenance Checks		
		34 A/F					Mos		24		30-Nov-2024	81 Days
		Tested Date 20-Nov-2022				0	Hrs					
		ATA Ref:34-11-00 (SOURCE: G280 AMM) (NOTE: Per CFR 91.411 or National Aviation Authority. RVSM requirement. Perform 24 months after initial inspection and repetitively thereafter. Allowable windows do not apply.)				0	Ldg					
341105		**Air Data Computer (No. 1) - Functional Check**							RE			
		34 A/F					Mos	02-Mar-2023	24		31-Mar-2025	6.7 Months
							Hrs	34:12				
		Mfg#:34-11-00 (NOTE: CAA Requirement)					Ldg	10				
341106		**Air Data Computer (No. 2) - Functional Check**							RE			
		34 A/F					Mos	02-Mar-2023	24		31-Mar-2025	6.7 Months
							Hrs	34:12				
		Mfg#:34-11-00 (NOTE: CAA Requirement)					Ldg	10				
342701		**Standby Instrument System - Altitude Accuracy Test (Per CFR 91.411 or National Aviation Authority.)**							RE	05-20-00 Scheduled Maintenance Checks		
		34 A/F					Mos	02-Mar-2023	24		31-Mar-2025	6.7 Months
		Certified Date 02-Mar-2023					Hrs	34:12				
		ATA Ref:34-27-00 (SOURCE: G280 AMM) (NOTE: Perform 24 months after initial inspection and repetitively thereafter. Allowable windows do not apply.)					Ldg	10				
344401		**TCAS - Functional Test**							RE	05-20-00 Scheduled Maintenance Checks		
		34 A/F					Mos	02-Mar-2023	24		31-Mar-2025	6.7 Months
		Certified Date 02-Mar-2023					Hrs	34:12				
		ATA Ref:34-44-00 (SOURCE: G280 AMM) (NOTE: RVSM requirement. Perform 24 months after initial inspection and repetitively thereafter.)					Ldg	10				
3444041		**Transponder System Functional Check**							RE			
		34 A/F					Mos	02-Mar-2023	24		02-Mar-2025	5.8 Months
							Hrs	34:12				
							Ldg	10				
345301		**Air Traffic Control System - Functional Test (Per CFR 91.413 or National Aviation Authority. RVSM requirement.)**							RE	05-20-00 Scheduled Maintenance Checks		
		34 A/F No.1					Mos	02-Mar-2023	24		31-Mar-2025	6.7 Months
		622-9210-501					Hrs	34:12				
		4L0V9T					Ldg	10				
		Certified Date 02-Mar-2023										
		ATA Ref:34-53-00 (SOURCE: G280 AMM)										
345304		**Air Traffic Control System - Functional Test (Per CFR 91.413 or National Aviation Authority. RVSM requirement.)**							RE	05-20-00 Scheduled Maintenance Checks		
		34 A/F No.2					Mos		24		30-Nov-2024	81 Days
		Unknown				0	Hrs					
		Unknown				0	Ldg					
		Certified Date 20-Nov-2022										
		ATA Ref:34-53-00 (SOURCE: G280 AMM) (NOTE: Perform 24 months after initial inspection and repetitively thereafter. Allowable windows do not apply.)										
3453061		**Transponder System Functional Check**							RE			
		34 A/F					Mos	02-Mar-2023	24		31-Mar-2025	6.7 Months
							Hrs	34:12				
		(NOTE: CAA Requirement)					Ldg	10				
345320		**Ads-B Out System Verification Check (Stc St04026At- D) (Ads-B Out V2 - Do-260B)**							RE			
		34 A/F					Mos		24		31-Mar-2025	6.7 Months
							Hrs					
							Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
352002		**Passenger Mask Automatic Drop-Down Function - Functional Check**							RE	05-20-00 Scheduled Maintenance Checks		
	35 A/F						Mos	02-Mar-2023	24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:35-20-00 (Manual Adjustment: 20d) (SOURCE: G280 AMM / G280 AOMM)					Hrs	34:12				
							Ldg	10				
352104		**Passenger Oxygen Mask - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	35 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:35-21-02 (SOURCE: G280 AMM / G280 AOMM) (NOTE: NOTE: Refer to applicable STC ICA requirements. 24 Mos Requirement Per AOMM Chapter 05-20-00)					Hrs					
							Ldg					
352204		**Therapeutic Oxygen Mask - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	35 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:35-22-01 (SOURCE: G280 AMM / G280 AOMM) (NOTE: NOTE: Refer to applicable STC ICA requirements. 24 Mos Requirement Per AOMM Chapter 05-20-00)					Hrs					
							Ldg					
352205		**Therapeutic Oxygen System - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		
	35 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:35-22-01 (SOURCE: G280 AMM / G280 AOMM) (NOTE: NOTE: Refer to applicable STC ICA requirements. 24 Mos Requirement Per AOMM Chapter 05-20-00)					Hrs					
							Ldg					
381535		**Galley Water Filter Cartridge - Discard**							RE	05-10-00 Time Limits		
	38 A/F	Galley	0				Mos	10-Feb-2023	24		[31-Mar-2025]	6.7 Months
	770006	New	0				Hrs	24:24				
	NSN		0				Ldg	7				
		ATA Ref:38-10-00 (Manual Adjustment: 1d) (SOURCE: G280 AOMM) (NOTE: Perform at water system sterilization, not to exceed 2C. For aircraft beyond 12 months since EIS, accomplish within 12 months following date of Revision 12 (see List of Revisions). This item applies if installed.)										
522103		**Emergency Exit Door - Lubrication**							RE	05-20-00 Scheduled Maintenance Checks		
	52 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:52-21-01, MRB Ref:52-20-00/01 (SOURCE: G280 AMM)					Hrs					
							Ldg					
522105		**Emergency Exit Door - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		
	52 A/F						Mos	02-Mar-2023	24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:52-21-01, MRB Ref:52-20-00/02 (Manual Adjustment: 20d) (SOURCE: G280 AMM)					Hrs	34:12				
							Ldg	10				
522108		**Emergency Exit Door Including Visible Portions of the Jamb - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	52 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:52-21-01, MRB Ref:52-800-02 (SOURCE: G280 AMM)					Hrs					
							Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
525104		**Auxiliary Bulkhead Door Indication Circuit - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		
52 A/F							Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:52-51-01, MRB Ref:52-70-00-01, MRB Ref:52-50-00-03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
525105		**Auxiliary Bulkhead Door Seal - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
52 A/F							Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:52-51-01, MRB Ref:52-50-00/01 (SOURCE: G280 AMM)					Hrs					
							Ldg					
525106		**Auxiliary Bulkhead Door Blowout Panel - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
52 A/F							Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:52-51-02, MRB Ref:52-50-00/02 (SOURCE: G280 AMM)					Hrs					
							Ldg					
530007		**Upper Fuselage External (From Ground) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:53-00-00, MRB Ref:53-200-01 (SOURCE: G280 AMM)					Hrs					
							Ldg					
5300XX		**G280 AMM Rev 16 Alignment Code. Do Not Add To Profiles.**							RE			
53 A/F							Mos		24		31-Mar-2025	6.7 Months
							Hrs					
							Ldg					
533001		**Aft Fuselage External (From Ground) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:53-30-00, MRB Ref:55-300-01 (SOURCE: G280 AMM)					Hrs					
							Ldg					
533008		**ECS Compartment Internal - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:53-30-00, MRB Ref:53-300-01 (SOURCE: G280 AMM)					Hrs					
							Ldg					
533009		**Service Compartment (Internal) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:53-30-00, MRB Ref:53-300-02 (SOURCE: G280 AMM)					Hrs					
							Ldg					
533012		**ECS Compartment Drain Holes - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:53-30-00, MRB Ref:53-300-EZIP-02 (SOURCE: G280 AMM)					Hrs					
							Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
533014	**Service Compartment Drain Holes - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
53 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	ATA Ref:53-30-00, MRB Ref:53-300-EZIP-04 (SOURCE: G280 AMM)					Hrs					
						Ldg					
564003	**Main Entrance Door Viewport - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		
56 A/F						Mos	02-Mar-2023	24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	ATA Ref:56-40-01, MRB Ref:56-40-00/01 (Manual Adjustment: 20d) (SOURCE: G280 AMM)					Hrs	34:12				
						Ldg	10				
570001	**Wing External (Left) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	ATA Ref:57-00-00, MRB Ref:57-500-01 (SOURCE: G280 AMM)					Hrs					
						Ldg					
570002	**Wing External (Right) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	ATA Ref:57-00-00, MRB Ref:57-500-01 (SOURCE: G280 AMM)					Hrs					
						Ldg					
570215	**Upper and Lower Wing Skins and Access Panels - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	ATA Ref:57-02-00, MRB Ref:57.02.00 / 15 (SOURCE: G280 AMM) (NOTE: Accomplish at next schedule accomplishment of Zonal task 57-500 -01 (CMP 570001, 570002) or 2C from last compliance of zonal task 57-500-01 (CMP 570001, 570002), whichever occurs later, and at every 2C thereafter.)					Hrs					
						Ldg					
570216	**Upper and Lower Wing Skins and Access Panels - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	ATA Ref:57-02-00, MRB Ref:57.02.00 / 15 (SOURCE: G280 AMM) (NOTE: Accomplish at next schedule accomplishment of Zonal task 57-500 -01 (CMP 570001, 570002) or 2C from last compliance of zonal task 57-500-01 (CMP 570001, 570002), whichever occurs later, and at every 2C thereafter.)					Hrs					
						Ldg					
710011	**Powerplant External (View from ground) (Left) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
71 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	ATA Ref:71-00-00, MRB Ref:71-400-01 (SOURCE: G280 AMM)					Hrs					
						Ldg					
710012	**Powerplant External (View from ground) (Right) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
71 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
	ATA Ref:71-00-00, MRB Ref:71-400-01 (SOURCE: G280 AMM)					Hrs					
						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
716107	**Engine Nacelle Inlet (Left) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
71 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
ATA Ref:71-61-01, MRB Ref:71-400-03 (SOURCE: G280 AMM)						Hrs					
						Ldg					
716108	**Engine Nacelle Inlet (Right) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
71 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
ATA Ref:71-61-01, MRB Ref:71-400-03 (SOURCE: G280 AMM)						Hrs					
						Ldg					
▼ 1. RE 24 Mos, 1000 Hrs											
262104	**APU Fire Shut-off Valve - Operational Check (**CMR)**							RE	05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks		**≈24-Dec-2025**
26 A/F						Mos	26-Jul-2024	24	-/+1m	31-Jul-2026	1.9 Years (+31 Days)
						Hrs	967:25	1,000	-/+50	2009:48	951:48 Hrs (+50)
ATA Ref:26-21-00, CMR Ref:26-00-03 (Tol. Adjustment: 42.4 Hrs) (SOURCE: G280 AMM)						Ldg	562				
▼ 1. RE 24 Mos, 1000 Hrs (later)											
340100	**Reduced Vertical Separation Minimum (RVSM) Monitoring Policy**							RE			
34 A/F						Mos	02-Mar-2023	24		31-Mar-2025	6.7 Months
						Hrs	34:12	1,000		1034:12	-23:48 Hrs
						Ldg	10				
▼ 1. RE 24 Mos, 1500 Hrs											
213113	**Safety Valve - Functional Check (*CMR)**							RE	05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks		
21 A/F						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
ATA Ref:21-31-02, CMR Ref:21-30-01 (SOURCE: G280 AMM) (NOTE: Accomplish at 1500 flight hours or 2C, whichever occurs first.)						Hrs		1,500	-/+50	1500	442 Hrs (+50)
						Ldg					
▼ 1. RE 24 Mos, 2000 Hrs											
213101	**Manual Pressurization Control System - Operational Check (*CMR)**							RE	05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks		
21 A/F						Mos	02-Mar-2023	24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
ATA Ref:21-31-00, CMR Ref:21-30-02 (Manual Adjustment: 20d, -24.4 Hrs) (SOURCE: G280 AMM)						Hrs	34:12	2,000	-/+50	2009:48	951:48 Hrs (+50)
						Ldg	10				
271137	**Aileron Disconnect Mechanism - Operational Check (*CMR)**							RE	05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks		
27 A/F						Mos	02-Mar-2023	24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
ATA Ref:27-11-05, CMR Ref:27-10-01 (Manual Adjustment: 20d, -24.4 Hrs) (SOURCE: G280 AMM)						Hrs	34:12	2,000	-/+50	2009:48	951:48 Hrs (+50)
						Ldg	10				
273106	**Elevator Force Disconnect Unit - Functional Check (*CMR)**							RE	05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks		
27 A/F						Mos	02-Mar-2023	24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
ATA Ref:27-31-00, CMR Ref:27-30-01 (Manual Adjustment: 20d, -24.4 Hrs) (SOURCE: G280 AMM)						Hrs	34:12	2,000	-/+50	2009:48	951:48 Hrs (+50)
						Ldg	10				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 1. RE 24 Mos, 500 Hrs												
262103		**Engine Fire Shut-off Valves - Operational Check (*CMR)**							RE		05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks	**≈14-Apr-2025**
	26 A/F						Mos	26-Jul-2024	24	-/+1m	31-Jul-2026	1.9 Years (+31 Days)
							Hrs	967:25	500	-/+50	1509:48	451:48 Hrs (+50)
		ATA Ref:26-21-00, CMR Ref:26-00-02 (Tol. Adjustment: 42.4 Hrs) (SOURCE: G280 AMM)					Ldg	562				
561105		**Cockpit Windows Exterior Moisture Seal - Detailed Inspection**							RE		05-20-00 Scheduled Maintenance Checks	**≈09-Apr-2025**
	56 A/F						Mos	26-Jul-2024	24	-/+1m	31-Jul-2026	1.9 Years (+31 Days)
							Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
		ATA Ref:56-10-00, Ref:MRIP (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM) (NOTE: Accomplish at 1A or 2C, whichever occurs first.)					Ldg	562				
▼ 1. RE 24 Mos, 750 Hrs												
121406		**Auxiliary Power Unit Oil - Drain and Discard**							RE		05-20-00 Scheduled Maintenance Checks	**≈03-Jan-2025**
	12 APU1						Mos		24	-/+1m	31-Mar-2025	6.7 Months (+30 Days)
		ATA Ref:12-14-00, MRB Ref:49-90-00-02, MRB Ref:49-90-00-01 (SOURCE: G280 AMM) (NOTE: 750 APU hours or 24 months, whichever occurs first. For operators enrolled in SOAP per Honeywell SIL APU-49, discard oil and filter as determined by oil analysis.)					Hrs		750	-/+50	750	121 Hrs (+50)
							APUS					
499204		**APU Magnetic Chip Detector - Detailed Inspection**							RE		05-20-00 Scheduled Maintenance Checks	**≈28-Mar-2026**
	49 APU1						Mos	09-Apr-2024	24	-/+1m	30-Apr-2026	1.6 Years (+30 Days)
	P91						Hrs	443	750	-/+50	1193	564 Hrs (+50)
	NSN						APUS	626				
		ATA Ref:49-92-02, MRB Ref:49-26-00-02 (SOURCE: G280 AMM) (NOTE: Accomplish at 750 APU hours or 24 months, whichever occurs first.)										
49-SOAP-001		**SOAP Sample Check**							RE			**≈28-Mar-2026**
	49 APU1						Mos	09-Apr-2024	24	-/+1m	30-Apr-2026	1.6 Years (+30 Days)
							Hrs	443	750	-/+50	1193	564 Hrs (+50)
							APUS	626				
▼ 1. RE 2400 Hrs												
732049		**(Start) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈23-Jul-2026**
	73 ENG1	No.1					Mos					
	3034073-1						Hrs		2,400		2400	1366:24 Hrs
	22-169016-02888						Enc					
		ATA Ref:73-13-01, MRB Ref:72-40-00-02, MRB Ref:73-10-00/01 (SOURCE: G280 AMM) (NOTE: NOTE: For additional interval allowance,, refer to Honeywell LMM AS907-2-1G, 05-20-00.)										
732049		**(Start) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈12-Jul-2026**
	73 ENG2	No.1					Mos					
	3034073-1						Hrs		2,400		2400	1346:24 Hrs
	22-169016-02466						Enc					
		ATA Ref:73-13-01, MRB Ref:72-40-00-02, MRB Ref:73-10-00/01 (SOURCE: G280 AMM) (NOTE: NOTE: For additional interval allowance,, refer to Honeywell LMM AS907-2-1G, 05-20-00.)										
732050		**(Start) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈23-Jul-2026**
	73 ENG1	No.2					Mos					
	3034073-1						Hrs		2,400		2400	1366:24 Hrs
	22-169016-02891						Enc					
		ATA Ref:73-13-01, MRB Ref:72-40-00-02, MRB Ref:73-10-00/01 (SOURCE: G280 AMM) (NOTE: NOTE: For additional interval allowance,, refer to Honeywell LMM AS907-2-1G, 05-20-00.)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
732050		**(Start) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈12-Jul-2026**
	73 ENG2	No.2					Mos					
	3034073-1						Hrs		2,400		2400	1346:24 Hrs
	22-169016-02492						Enc					
		ATA Ref:73-13-01, MRB Ref:72-40-00-02, MRB Ref:73-10-00/01 (SOURCE: G280 AMM) (NOTE: NOTE: For additional interval allowance,, refer to Honeywell LMM AS907-2-1G, 05-20-00.)										
732051		**(Start) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈23-Jul-2026**
	73 ENG1	No.3					Mos					
	3034073-1						Hrs		2,400		2400	1366:24 Hrs
	22-169016-02892						Enc					
		ATA Ref:73-13-01, MRB Ref:72-40-00-02, MRB Ref:73-10-00/01 (SOURCE: G280 AMM) (NOTE: NOTE: For additional interval allowance,, refer to Honeywell LMM AS907-2-1G, 05-20-00.)										
732051		**(Start) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈12-Jul-2026**
	73 ENG2	No.3					Mos					
	3034073-1						Hrs		2,400		2400	1346:24 Hrs
	22-169016-02496						Enc					
		ATA Ref:73-13-01, MRB Ref:72-40-00-02, MRB Ref:73-10-00/01 (SOURCE: G280 AMM) (NOTE: NOTE: For additional interval allowance,, refer to Honeywell LMM AS907-2-1G, 05-20-00.)										
732052		**(Start) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈23-Jul-2026**
	73 ENG1	No.4					Mos					
	3034073-1						Hrs		2,400		2400	1366:24 Hrs
	22-169016-02893						Enc					
		ATA Ref:73-13-01, MRB Ref:72-40-00-02, MRB Ref:73-10-00/01 (SOURCE: G280 AMM) (NOTE: NOTE: For additional interval allowance,, refer to Honeywell LMM AS907-2-1G, 05-20-00.)										
732052		**(Start) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈12-Jul-2026**
	73 ENG2	No.4					Mos					
	3034073-1						Hrs		2,400		2400	1346:24 Hrs
	22-169016-02499						Enc					
		ATA Ref:73-13-01, MRB Ref:72-40-00-02, MRB Ref:73-10-00/01 (SOURCE: G280 AMM) (NOTE: NOTE: For additional interval allowance,, refer to Honeywell LMM AS907-2-1G, 05-20-00.)										
▼ 1. RE 2500 Hrs												
217203		**Ozone Converter - Functional Check**							RE		05-20-00 Scheduled Maintenance Checks	**≈31-Aug-2026**
	21 A/F						Mos					
							Hrs		2,500	-/+50	2500	1442 Hrs (+50)
		ATA Ref:21-72-01, MRB Ref:21-50-00/01 (SOURCE: G280 AMM) (NOTE: BASF (P/N 43261001) & GAC / IAI (P/N 4AS7810033-001) at 5A.)					Ldg					
710017		**Engine Fan Cowl Doors, Access Panels, Latches and Attachment Hardware - Detailed Inspection**							RE		05-20-00 Scheduled Maintenance Checks	**≈31-Aug-2026**
	71 A/F						Mos					
							Hrs		2,500	-/+50	2500	1442 Hrs (+50)
		ATA Ref:71-00-00, MRB Ref:71-10-00-01 (SOURCE: G280 AMM) (NOTE: Task satisfies CCMR 72-00-02 at 5A. Note (1) Escalations are not permitted which would exceed the Candidate CMR (CCMR) interval.)					Ldg					
710018		**Engine Fan Cowl Doors, Access Panels, Latches and Attachment Hardware - Detailed Inspection**							RE		05-20-00 Scheduled Maintenance Checks	**≈31-Aug-2026**
	71 A/F						Mos					
							Hrs		2,500	-/+50	2500	1442 Hrs (+50)
		ATA Ref:71-00-00, MRB Ref:71-10-00-01 (SOURCE: G280 AMM) (NOTE: Task satisfies CCMR 72-00-02 at 5A. Note (1) Escalations are not permitted which would exceed the Candidate CMR (CCMR) interval.)					Ldg					
710019		**Engine Fan Cowl Door Seals - Detailed Inspection**							RE		05-20-00 Scheduled Maintenance Checks	**≈31-Aug-2026**
	71 A/F						Mos					
							Hrs		2,500	-/+50	2500	1442 Hrs (+50)
		ATA Ref:71-00-00, MRB Ref:71-10-00/02 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
710020	**Engine Fan Cowl Door Seals - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈31-Aug-2026**
71 A/F						Mos					
						Hrs		2,500	-/+50	2500	1442 Hrs (+50)
	ATA Ref:71-00-00, MRB Ref:71-10-00/02 (SOURCE: G280 AMM)					Ldg					
▼ 1. RE 3 Mos											
38-31-01	**Waste Tank Module — Cleaning (Scale Softening with Honey Bee)**							RE			
38 A/F						Mos	05-Jul-2024	3		05-Oct-2024	25 Days
						Hrs					
						Ldg					
▼ 1. RE 3000 Hrs											
243105	**Engine Generator - Restore**							RE		05-10-00 Time Limits	**≈11-May-2027**
24 A/F	Left					Mos					
A3579-801						Hrs		3,000		3000	1942 Hrs
2967						Ldg					
	ATA Ref:24-31-01, MRB Ref:24-30-00/04 (SOURCE: G280 AMM)										
243106	**Engine Generator - Restore**							RE		05-10-00 Time Limits	**≈11-May-2027**
24 A/F	Right					Mos					
A3579-801						Hrs		3,000		3000	1942 Hrs
2965						Ldg					
	ATA Ref:24-31-01, MRB Ref:24-30-00/04 (SOURCE: G280 AMM)										
271104	**Aileron Control Loop - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈11-May-2027**
27 A/F						Mos					
						Hrs		3,000	-/+50	3000	1942 Hrs (+50)
	ATA Ref:27-11-00, MRB Ref:27-10-00/02 (SOURCE: G280 AMM)					Ldg					
271123	**Aileron Actuating Link - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈11-May-2027**
27 A/F						Mos					
						Hrs		3,000	-/+50	3000	1942 Hrs (+50)
	ATA Ref:27-11-02, MRB Ref:27-10-00/03 (SOURCE: G280 AMM)					Ldg					
271331	**Aileron Gear Tab Linkage (Left) - Detailed Inspection (*CMR)**							RE	05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks		**≈11-May-2027**
27 A/F						Mos					
						Hrs		3,000	-/+50	3000	1942 Hrs (+50)
	ATA Ref:27-13-03, CMR Ref:27-10-03 (SOURCE: G280 AMM) (NOTE: Accomplish at 3000 flight hours or 6A, whichever occurs first.)					Ldg					
271332	**Aileron Gear Tab Linkage (Right) - Detailed Inspection (*CMR)**							RE	05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks		**≈11-May-2027**
27 A/F						Mos					
						Hrs		3,000	-/+50	3000	1942 Hrs (+50)
	ATA Ref:27-13-03, CMR Ref:27-10-03 (SOURCE: G280 AMM) (NOTE: Accomplish at 3000 flight hours or 6A, whichever occurs first.)					Ldg					
272124	**Rudder Free Play - Functional Check (*CMR)**							RE		05-10-10 CMR	**≈11-May-2027**
27 A/F						Mos					
						Hrs		3,000	-/+50	3000	1942 Hrs (+50)
	ATA Ref:27-20-00, CMR Ref:27-20-03 (SOURCE: G280 AMM)					Ldg					
274116	**Horizontal Stabilizer Trim Actuator Torque Limiter - Functional Check (**CMR)**							RE	05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks		**≈11-May-2027**
27 A/F						Mos					
						Hrs		3,000	-/+50	3000	1942 Hrs (+50)
	ATA Ref:27-41-01, CMR Ref:27-40-03 (SOURCE: G280 AMM) (NOTE: Accomplish at 4500 flight hours or 6A, whichever occurs first.)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
523117		**Baggage Door Seal - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈11-May-2027**
	52 A/F						Mos					
							Hrs		3,000	-/+50	3000	1942 Hrs (+50)
		ATA Ref:52-31-02, MRB Ref:52-30-00/01 (SOURCE: G280 AMM)					Ldg					
▼ 1. RE 36 Mos												
256123		**Life Raft - Restore**							RE	05-10-00 Time Limits		
	25 A/F	No.1				0	Mos	18-Feb-2023	36		28-Feb-2026	1.5 Years
	57FPSA-HK4-1-907					0	Hrs	28				
	5PA-00705					0	Ldg	8				
		Restored Date 18-Feb-2023										
		(SOURCE: G280 AOMM) (NOTE: Life rafts packed in vacuum bag, send to authorized repair station every 3 years effective March 2003 (Winslow SB 22). Life rafts manufactured between May 1, 2000 and March 30, 2003 not packed in vacuum bag, send to authorized repair station the 2nd, 4th, 5th year and every year following the 5th year while raft remains in service. Life rafts manufactured prior to May 1, 2000 not packed in vacuum bag, send to authorized repair station yearly (Winslow SB 10). This item applies if installed.)										
256124		**Life Raft - Restore**							RE	05-10-00 Time Limits		
	25 A/F	No.2				0	Mos	18-Feb-2023	36		28-Feb-2026	1.5 Years
	46FPSA-1K4-1908					0	Hrs	28				
	4PA-00401					0	Ldg	8				
		Restored Date 18-Feb-2023										
		(SOURCE: G280 AOMM) (NOTE: Life rafts packed in vacuum bag, send to authorized repair station every 3 years effective March 2003 (Winslow SB 22). Life rafts manufactured between May 1, 2000 and March 30, 2003 not packed in vacuum bag, send to authorized repair station the 2nd, 4th, 5th year and every year following the 5th year while raft remains in service. Life rafts manufactured prior to May 1, 2000 not packed in vacuum bag, send to authorized repair station yearly (Winslow SB 10). This item applies if installed.)										
256125		**Life Raft - Restore**							RE	05-10-00 Time Limits		
	25 A/F	No.3				0	Mos	18-Feb-2023	36		28-Feb-2026	1.5 Years
	57FPSA-HK5-1-912					0	Hrs	28				
	5PA-00706					0	Ldg	8				
		Restored Date 18-Feb-2023										
		(SOURCE: G280 AOMM) (NOTE: Life rafts packed in vacuum bag, send to authorized repair station every 3 years effective March 2003 (Winslow SB 22). Life rafts manufactured between May 1, 2000 and March 30, 2003 not packed in vacuum bag, send to authorized repair station the 2nd, 4th, 5th year and every year following the 5th year while raft remains in service. Life rafts manufactured prior to May 1, 2000 not packed in vacuum bag, send to authorized repair station yearly (Winslow SB 10). This item applies if installed.)										
323107		**Downlock Solenoid and Override Switch - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		
	32 A/F						Mos		36	-/+1m	31-Mar-2026	1.6 Years (+30 Days)
							Hrs					
		ATA Ref:32-31-00, MRB Ref:32-30-00/08 (SOURCE: G280 AMM)					Ldg					
326001		**Landing Gear Extension Warning System - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		
	32 A/F						Mos	02-Mar-2023	36	-/+1m	31-Mar-2026	1.6 Years (+30 Days)
							Hrs	34:12				
		ATA Ref:32-60-00, MRB Ref:32-60-00/01 (Manual Adjustment: 20d) (SOURCE: G280 AMM)					Ldg	10				
351001		**Crew Oxygen System - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		
	35 A/F						Mos	02-Mar-2023	36	-/+1m	31-Mar-2026	1.6 Years (+30 Days)
							Hrs	34:12				
		ATA Ref:35-10-00, MRB Ref:35-10-00/05 (Manual Adjustment: 20d) (SOURCE: G280 AMM)					Ldg	10				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
351207		**Crew Oxygen Masks and Smoke Goggles - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	35 A/F						Mos		36	-/+1m	31-Mar-2026	1.6 Years (+30 Days)
							Hrs					
		ATA Ref:35-12-01, MRB Ref:35-10-00-01 (SOURCE: G280 AMM)					Ldg					
351208		**Crew Oxygen Masks and Smoke Goggles - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	35 A/F						Mos		36	-/+1m	31-Mar-2026	1.6 Years (+30 Days)
							Hrs					
		ATA Ref:35-12-01, MRB Ref:35-10-00-01 (SOURCE: G280 AMM)					Ldg					
▼ 1. RE 36 Mos, 1500 Hrs												
323401		**Emergency Landing Gear Extension - Functional Check**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Apr-2025**
	32 A/F						Mos	02-Mar-2023	36	-/+1m	31-Mar-2026	1.6 Years (+30 Days)
							Hrs	34:12	1,500	-/+50	1509:48	451:48 Hrs (+50)
		ATA Ref:32-34-00, MRB Ref:32-30-00-06 (Manual Adjustment: 20d, -24.4 Hrs) (SOURCE: G280 AMM)					Ldg	10				
▼ 1. RE 36 Mos, 500 Hrs												
122201		**Nose Landing Gear and Gear Door - Lubrication**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Apr-2025**
	12 A/F						Mos	26-Jul-2024	36	-/+1m	31-Jul-2027	2.9 Years (+31 Days)
							Hrs	967:25	500	-/+50	1511:18	453:18 Hrs (+50)
		ATA Ref:12-22-00, MRB Ref:32-20-00/01, MRB Ref:32-20-00/05, MRB Ref:32-20-00/09, MRB Ref:32-20-00/10, MRB Ref:32-30-00/01, MRB Ref:32-30-00/02 (Tol. Adjustment: 43.9 Hrs) (SOURCE: G280 AMM)					Ldg	562				
122205		**Main Landing Gear and Gear Door - Lubrication**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Apr-2025**
	12 A/F						Mos	26-Jul-2024	36	-/+1m	31-Jul-2027	2.9 Years (+31 Days)
							Hrs	967:25	500	-/+50	1511:18	453:18 Hrs (+50)
		ATA Ref:12-22-00, MRB Ref:32-10-00/01, MRB Ref:32-10-00/03, MRB Ref:32-10-00/05, MRB Ref:32-30-00/03, MRB Ref:32-30-00/05 (Tol. Adjustment: 43.9 Hrs) (SOURCE: G280 AMM)					Ldg	562				
122206		**Main Landing Gear and Gear Door - Lubrication**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Apr-2025**
	12 A/F						Mos	26-Jul-2024	36	-/+1m	31-Jul-2027	2.9 Years (+31 Days)
							Hrs	967:25	500	-/+50	1511:18	453:18 Hrs (+50)
		ATA Ref:12-22-00, MRB Ref:32-10-00/01, MRB Ref:32-10-00/03, MRB Ref:32-10-00/05, MRB Ref:32-30-00/03, MRB Ref:32-30-00/05 (Tol. Adjustment: 43.9 Hrs) (SOURCE: G280 AMM)					Ldg	562				
▼ 1. RE 4 Mos												
280018		**Microbial Contamination Test of Fuel Tank - Special Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	28 A/F						Mos	30-Aug-2024	4	-/+1m	30-Nov-2024	81 Days (+30)
							Hrs					
		ATA Ref:28-00-00, MRB Ref:53.30.01/05, MRB Ref:53.30.03/05, MRB Ref:57.02.00/18 (Tol. Adjustment: -58d) (SOURCE: G280 AMM)					Ldg					
▼ 1. RE 4000 Hrs												
262202		**Baggage Compartment Smoke Evacuation - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		**≈18-Oct-2028**
	26 A/F						Mos	02-Mar-2023				
							Hrs	34:12	4,000	-/+50	4034:12	2976:12 Hrs (+50)
		ATA Ref:26-22-00, MRB Ref:21-35-00-01 (SOURCE: G280 AMM)					Ldg	10				
273145		**Elevator Servo Actuator Compensator Damping and Stiffness (Left) - Functional Check (*CMR)**							RE	05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks		**≈01-Oct-2028**
	27 A/F						Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:27-31-04, CMR Ref:27-30-06 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
273146		**Elevator Servo Actuator Compensator Damping and Stiffness (Right) - Functional Check (*CMR)**							RE		05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks	**≈01-Oct-2028**
	27 A/F						Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:27-31-04, CMR Ref:27-30-06 (SOURCE: G280 AMM)					Ldg					
273151		**Elevator Surface Linkage (Left) - Visual Inspection and Free Play Check (*CMR)**							RE		05-10-10 CMR	**≈01-Oct-2028**
	27 A/F						Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:27-31-04, CMR Ref:27-30-05 (SOURCE: G280 AMM)					Ldg					
273152		**Elevator Surface Linkage (Right) - Visual Inspection and Free Play Check (*CMR)**							RE		05-10-10 CMR	**≈01-Oct-2028**
	27 A/F						Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:27-31-04, CMR Ref:27-30-05 (SOURCE: G280 AMM)					Ldg					
274118		**Horizontal Stabilizer Trim Actuator No-Back Operational Check**							RE		05-10-10 Temporary Limitation and Inspection Requirements, 05-20-00 Scheduled Maintenance Checks	**≈01-Oct-2028**
	27 A/F						Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:27-41-01, AWL No.:AWL-3, MRB Ref:27-40-00-03 (SOURCE: G280 AMM) (NOTE: Task satisfies CCMR 27-40-02 at 8A. Note (1) Escalations are not permitted which would exceed the Candidate CMR (CCMR) interval.)					Ldg					
281005		**Fuel Tanks Internal (Forward) - Detailed Inspection (**CMR)**							RE		05-10-10 CMR	**≈01-Oct-2028**
	28 A/F						Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:28-10-00, CMR Ref:28-00-05 (SOURCE: G280 AMM) (NOTE: (1) Task satisfies the Fuel System Airworthiness Limitations Inspections requirement.)					Ldg					
281006		**Fuel Tanks Internal (Aft) - Detailed Inspection (**CMR)**							RE		05-10-10 CMR	**≈01-Oct-2028**
	28 A/F						Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:28-10-00, CMR Ref:28-00-05 (SOURCE: G280 AMM) (NOTE: (1) Task satisfies the Fuel System Airworthiness Limitations Inspections requirement.)					Ldg					
281007		**Fuel Tanks Internal (Center) - Detailed Inspection (**CMR)**							RE		05-10-10 CMR	**≈01-Oct-2028**
	28 A/F						Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:28-10-00, CMR Ref:28-00-05 (SOURCE: G280 AMM) (NOTE: (1) Task satisfies the Fuel System Airworthiness Limitations Inspections requirement.)					Ldg					
281008		**Fuel Tanks Internal (Left Wing) - Detailed Inspection (**CMR)**							RE		05-10-10 CMR	**≈01-Oct-2028**
	28 A/F						Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:28-10-00, CMR Ref:28-00-05 (SOURCE: G280 AMM) (NOTE: (1) Task satisfies the Fuel System Airworthiness Limitations Inspections requirement.)					Ldg					
281009		**Fuel Tanks Internal (Right Wing) - Detailed Inspection (**CMR)**							RE		05-10-10 CMR	**≈01-Oct-2028**
	28 A/F						Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:28-10-00, CMR Ref:28-00-05 (SOURCE: G280 AMM) (NOTE: (1) Task satisfies the Fuel System Airworthiness Limitations Inspections requirement.)					Ldg					
281010		**Lower Fuselage Bay - Detailed Inspection (**CMR)**							RE		05-10-10 CMR	**≈01-Oct-2028**
	28 A/F						Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:28-10-00, CMR Ref:28-00-08 (SOURCE: G280 AMM) (NOTE: (1) Task satisfies the Fuel System Airworthiness Limitations Inspections requirement.)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
281011		**Zone between Forward Fuel Tank and Wing Fuel Tanks (Left) - Detailed Inspection (**CMR)**							RE		05-10-10 CMR	**≈01-Oct-2028**
	28 A/F						Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:28-10-00, CMR Ref:28-00-09 (SOURCE: G280 AMM) (NOTE: (1) Task satisfies the Fuel System Airworthiness Limitations Inspections requirement.)					Ldg					
281012		**Zone between Forward Fuel Tank and Wing Fuel Tanks (Right) - Detailed Inspection (**CMR)**							RE		05-10-10 CMR	**≈01-Oct-2028**
	28 A/F						Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:28-10-00, CMR Ref:28-00-09 (SOURCE: G280 AMM) (NOTE: (1) Task satisfies the Fuel System Airworthiness Limitations Inspections requirement.)					Ldg					
281013		**Zone between Aft Fuel Tank and Wing Fuel Tanks (Left) - Detailed Inspection (**CMR)**							RE		05-10-10 CMR	**≈01-Oct-2028**
	28 A/F						Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:28-10-00, CMR Ref:28-00-09 (SOURCE: G280 AMM) (NOTE: (1) Task satisfies the Fuel System Airworthiness Limitations Inspections requirement.)					Ldg					
281014		**Zone between Aft Fuel Tank and Wing Fuel Tanks (Right) - Detailed Inspection (**CMR)**							RE		05-10-10 CMR	**≈01-Oct-2028**
	28 A/F						Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:28-10-00, CMR Ref:28-00-09 (SOURCE: G280 AMM) (NOTE: (1) Task satisfies the Fuel System Airworthiness Limitations Inspections requirement.)					Ldg					
281015		**Zone between Feed Tank and Engine - Detailed Inspection (**CMR)**							RE		05-10-10 CMR	**≈01-Oct-2028**
	28 A/F						Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:28-10-00, CMR Ref:28-00-10 (SOURCE: G280 AMM) (NOTE: (1) Task satisfies the Fuel System Airworthiness Limitations Inspections requirement.)					Ldg					
281111		**Wing Forward Spar (Left) - Detailed Inspection (**CMR)**							RE		05-10-10 CMR	**≈01-Oct-2028**
	28 A/F						Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:28-11-04, CMR Ref:28-00-06 (SOURCE: G280 AMM) (NOTE: (1) Task satisfies the Fuel System Airworthiness Limitations Inspections requirement.)					Ldg					
281112		**Wing Forward Spar (Right) - Detailed Inspection (**CMR)**							RE		05-10-10 CMR	**≈01-Oct-2028**
	28 A/F						Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:28-11-04, CMR Ref:28-00-06 (SOURCE: G280 AMM) (NOTE: (1) Task satisfies the Fuel System Airworthiness Limitations Inspections requirement.)					Ldg					
753121		**Compressor Variable Geometry Actuator (CVGA) System - General Visual Inspection**							RE	05-20-00	Scheduled Maintenance Checks	**≈13-Oct-2028**
	75 ENG1						Mos					
							Hrs		4,000	-/+50	4000	2966:24 Hrs (+50)
		ATA Ref:75-31-01, MRB Ref:72-30-00-01 (SOURCE: G280 AMM) (NOTE: Pre SB AS 907-72-9001 at 8A.)					Enc					
753121		**Compressor Variable Geometry Actuator (CVGA) System - General Visual Inspection**							RE	05-20-00	Scheduled Maintenance Checks	**≈03-Oct-2028**
	75 ENG2						Mos					
							Hrs		4,000	-/+50	4000	2946:24 Hrs (+50)
		ATA Ref:75-31-01, MRB Ref:72-30-00-01 (SOURCE: G280 AMM) (NOTE: Pre SB AS 907-72-9001 at 8A.)					Enc					
783203		**Thrust Reverser Firewall - General Visual Inspection**							RE	05-20-00	Scheduled Maintenance Checks	**≈01-Oct-2028**
	78 A/F						Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:78-30-00, MRB Ref:78-30-00/07 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
783204		**Thrust Reverser Firewall - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈01-Oct-2028**
78 A/F							Mos					
							Hrs		4,000	-/+50	4000	2942 Hrs (+50)
		ATA Ref:78-30-00, MRB Ref:78-30-00/07 (SOURCE: G280 AMM)					Ldg					
▼ 1. RE 4000 Ldg												
321005		**Main Landing Gear Shock Strut Assembly - Discard**							RE	05-10-10 Life Limited Components		**≈19-Sep-2031**
32 A/F		Left	0				Mos	20-Nov-2022				
30P252001002-501		New	0				Hrs	0				
NSN			0				Ldg	0	4,000		4,000	3,382 Ldg
		ATA Ref:32-10-00, MRB Ref:32-10-00/09 (SOURCE: G280 AMM) (NOTE: For any flight operation where there is a landing after a steep approach which is greater than 4.5 degrees, the life status tracking of this part / assembly shall be updated to record the cycle as 2.8 flight cycles. Therefore, a record of such approaches should be kept. Discarded assembly includes the following components: • 30P252001002-501 / -502 • 30P252001003-501 / -502 • 30P252001004-501 / -502 • 30P252002001-501 / -502)										
321006		**Main Landing Gear Shock Strut Assembly - Discard**							RE	05-10-10 Life Limited Components		**≈19-Sep-2031**
32 A/F		Right	0				Mos	20-Nov-2022				
30P252001002-502		New	0				Hrs	0				
NSN			0				Ldg	0	4,000		4,000	3,382 Ldg
		ATA Ref:32-10-00, MRB Ref:32-10-00/09 (SOURCE: G280 AMM) (NOTE: For any flight operation where there is a landing after a steep approach which is greater than 4.5 degrees, the life status tracking of this part / assembly shall be updated to record the cycle as 2.8 flight cycles. Therefore, a record of such approaches should be kept. Discarded assembly includes the following components: • 30P252001002-501 / -502 • 30P252001003-501 / -502 • 30P252001004-501 / -502 • 30P252002001-501 / -502)										
▼ 1. RE 4500 Hrs												
351105		**Oxygen Fill System - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		**≈23-Jun-2029**
35 A/F							Mos	19-Jan-2023				
							Hrs	22:54	4,500	-/+50	4522:54	3464:54 Hrs (+50)
		ATA:35-00-00, MRB:35-10-00-08 (SOURCE: G280 AMM) (NOTE: Accomplish at every bottle installation not to exceed 4500 flight hours. Aircraft past 4500 flight hours since new, accomplish within 4500 flight hours from last compliance of "Oxygen Bottle - Removal / Installation", if there is no previous compliance of "Oxygen Bottle - Removal / Installation", accomplish within 450 flight hours or 12 calendar months whichever occurs first, from date of Revision 10, (see List of Revisions) and then at every "Oxygen Bottle -Removal / Installation", not to exceed 4500 flight hours thereafter.)					Ldg	6				
▼ 1. RE 48 Mos												
080001		**Aircraft Weight and Balance**							RE			
8 A/F							Mos	02-Mar-2023	48		31-Mar-2027	2.6 Years
							Hrs	34:12				
		(NOTE: CAA Requirement)					Ldg	10				
251205		**Crew Seats Locking Mechanism and Seat Tracks - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
25 A/F							Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:25-12-01, MRB Ref:25-11-00/03 (SOURCE: G280 AMM)					Ldg					
252141		**Passenger Seats (including divan if installed) for attachments / locking to structure - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
25 A/F							Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:25-21-00, ATA Ref:25-21-03 (SOURCE: G280 AOMM) (NOTE: See Passenger Seats Attachments and Locking - Detailed Inspection.)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
313113		**Recorder Independent Power Supply Battery Pack - Discard (Applicable to Post SB 280-31-011 or SB 280-31-043 or aircraft SN 2033 and Sub.)**							RE		05-10-00 Time Limits	
31 A/F	100-3010-001 002425	ATA Ref:31-31-05, MRB Ref:31-31-00-06 (SOURCE: G280 AMM) (NOTE: Accomplish at 48 months from aircraft Entry Into Service (EIS). For aircraft beyond 48 months from EIS or last compliance, accomplish no later than 14 months from date of Revision 14 and every 48 months thereafter ± 1 month. See List of Revisions. For all other recurring battery replacements, time starts with date of aircraft installation.)					Mos Hrs Ldg	02-Mar-2023 34:12 10	48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
321111		**Main Landing Gear Shock Absorber (Left) - Servicing**							RE		05-20-00 Scheduled Maintenance Checks	
32 A/F		ATA Ref:32-11-02, MRB Ref:32-10-00-10 (SOURCE: G280 AMM) (NOTE: For aircraft beyond 36 months from EIS, accomplish within 12 months from date of Revision 10, (see List of Revisions) and every 4C thereafter.)					Mos Hrs Ldg		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
321112		**Main Landing Gear Shock Absorber (Right) - Servicing**							RE		05-20-00 Scheduled Maintenance Checks	
32 A/F		ATA Ref:32-11-02, MRB Ref:32-10-00-10 (SOURCE: G280 AMM) (NOTE: For aircraft beyond 36 months from EIS, accomplish within 12 months from date of Revision 10, (see List of Revisions) and every 4C thereafter.)					Mos Hrs Ldg		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
322104		**Nose Landing Gear Shock Strut - Servicing**							RE		05-20-00 Scheduled Maintenance Checks	
32 A/F		ATA Ref:32-21-01, MRB Ref:32-20-00-11 (SOURCE: G280 AMM) (NOTE: For aircraft beyond 36 months from EIS, accomplish within 12 months from date of Revision 10, (see List of Revisions) and every 4C thereafter.)					Mos Hrs Ldg		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
335109		**Emergency Lighting System Battery - Restore**							RE		05-10-00 Time Limits	
33 A/F	100-1080-02 1214416	No.1 Restored Date 30-Sep-2022 (SOURCE: G280 AOMM)				5	Mos Hrs Ldg	02-Mar-2023 34:12 10	48		30-Sep-2026	2.1 Years
335110		**Emergency Lighting System Battery - Restore**							RE		05-10-00 Time Limits	
33 A/F	100-1088-02 1214417	No.2 Restored Date 26-Sep-2022 (SOURCE: G280 AOMM)				0 0 0	Mos Hrs Ldg		48		30-Sep-2026	2.1 Years
381107		**Potable Water Pumps - General Visual Inspection**							RE		05-20-00 Scheduled Maintenance Checks	
38 A/F	PWP9282-02 04220674	No.1 ATA Ref:38-11-01, MRB Ref:38-10-00/02 (SOURCE: G280 AMM)					Mos Hrs Ldg		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
381108		**Potable Water Pumps - General Visual Inspection**							RE		05-20-00 Scheduled Maintenance Checks	
38 A/F	PWP9282-02 04220670	No.2 ATA Ref:38-11-01, MRB Ref:38-10-00/02 (SOURCE: G280 AMM)					Mos Hrs Ldg		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
381303		**Potable Water Tank Module - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	38 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:38-13-01, MRB Ref:38-10-00/01 (SOURCE: G280 AMM)					Ldg					
381307		**Potable Water Pressure Reservoir - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	38 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:38-13-02, MRB Ref:38-10-00/03 (SOURCE: G280 AMM)					Ldg					
381503		**Potable Water Fill / Drain Valve - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	38 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:38-15-01, MRB Ref:38-10-00/04 (SOURCE: G280 AMM)					Ldg					
383301		**Vacuum Toilet Assembly - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	38 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:38-33-00, MRB Ref:38-30-00/02 (SOURCE: G280 AMM)					Ldg					
522109		**Emergency Exit Door - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	52 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:52-21-01, MRB Ref:53.25.00/13 (SOURCE: G280 AMM)					Ldg					
530005		**Lower Fuselage External - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-00-00, MRB Ref:53-100-02 (SOURCE: G280 AMM)					Ldg					
530008		**Upper Fuselage External (From Stand) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-00-00, MRB Ref:53-200-02 (SOURCE: G280 AMM)					Ldg					
530009		**Aft Fuselage External (From Stand) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-00-00, MRB Ref:55-300-02 (SOURCE: G280 AMM)					Ldg					
530016		**Fuselage Door Section Interior Skin Below WL 12.99 (330 mm) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-00-00, MRB Ref:53.21.00/09 (SOURCE: G280 AMM)					Ldg					
530018		**Door Section Exterior Skin - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-00-00, MRB Ref:53.21.00/13 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
530021		**Cabin Floor Structure Below WL 12.99 (330 mm) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-00-00, MRB Ref:53.21.00/14 (SOURCE: G280 AMM)					Ldg					
531101		**Nose Section Structure (Internal) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-11-00, MRB Ref:53.10.00/08 (SOURCE: G280 AMM)					Ldg					
531302		**Cabin Entrance Below Floor Wiring Installations - Cleaning**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-13-01, MRB Ref:53-100-EZIP-03 (SOURCE: G280 AMM)					Ldg					
531303		**Cabin Entrance Below Floor - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-13-01, MRB Ref:53-100-06 (SOURCE: G280 AMM)					Ldg					
531408		**Lower Fairing Drain Holes - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-14-00, MRB Ref:53-100-EZIP-07 (SOURCE: G280 AMM)					Ldg					
532001		**Lower Compartment Bays - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-20-00, MRB Ref:53-100-17 (SOURCE: G280 AMM)					Ldg					
532002		**Lower Compartment Bays Wiring Installations - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-20-00, MRB Ref:53-100-EZIP-09 (SOURCE: G280 AMM)					Ldg					
532003		**Lower Compartment Bays Panel Drain Holes - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-20-00, MRB Ref:53-100-EZIP-10 (SOURCE: G280 AMM)					Ldg					
532004		**Forward Center Bay Interior - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-20-00, MRB Ref:53-100-20 (SOURCE: G280 AMM)					Ldg					
532005		**Lower Wing Fairing and Center Fuel Tank - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-20-00, MRB Ref:57-100-01 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
532006		**Center Fuel Tank Wiring - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-20-00, MRB Ref:53-100-EZIP-08 (SOURCE: G280 AMM)					Ldg					
532016		**Lavatory Interior Skin Below Floor - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-20-00, MRB Ref:53.27.00/07 (SOURCE: G280 AMM)					Ldg					
532104		**Aft Cabin Lavatory Below Floor - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-21-01, MRB Ref:53-100-10 (SOURCE: G280 AMM)					Ldg					
532205		**Baggage Compartment Internal Side Skin - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-22-01, MRB Ref:53.40.02/11 (SOURCE: G280 AMM)					Ldg					
532206		**Baggage Compartment Internal Side Skin - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-22-01, MRB Ref:53.40.02/12 (SOURCE: G280 AMM)					Ldg					
532207		**Baggage Door Sill - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-22-01, MRB Ref:53.40.02/10 (SOURCE: G280 AMM)					Ldg					
532303		**Aft Fuel Tank Fairing Internal - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-23-00, MRB Ref:53-100-19 (SOURCE: G280 AMM)					Ldg					
533007		**Service Compartment Internal Lower Skin - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-30-00, MRB Ref:53.50.02/10 (SOURCE: G280 AMM)					Ldg					
533011		**ECS Compartment Wiring Installations - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-30-00, MRB Ref:53-300-EZIP-01 (SOURCE: G280 AMM)					Ldg					
533013		**Service Compartment Wiring Installations - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-30-00, MRB Ref:53-300-EZIP-03 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
533015		**ECS Compartment Interior Skin Surface - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-30-00, MRB Ref:53.50.01/13 (SOURCE: G280 AMM)					Ldg					
545007		**Left and Right Pylon (Interior) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	54 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:54-50-00, MRB Ref:54-400-01 (SOURCE: G280 AMM)					Ldg					
545008		**Left and Right Pylon (Interior) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	54 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:54-50-00, MRB Ref:54-400-01 (SOURCE: G280 AMM)					Ldg					
570003		**Wing Spar Aft Face - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-00-00, MRB Ref:57-500-05 (SOURCE: G280 AMM)					Ldg					
570004		**Wing Spar Aft Face - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-00-00, MRB Ref:57-500-05 (SOURCE: G280 AMM)					Ldg					
571001		**Wing Center and Feed Tanks (Internal) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-10-00, MRB Ref:57.02.00/14, MRB Ref:57.02.00/07, MRB Ref:57.02.00/06 (SOURCE: G280 AMM)					Ldg					
575005		**Wing Trailing Edge Wiring Installations - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-00-00, MRB Ref:53-500-EZIP-03 (SOURCE: G280 AMM)					Ldg					
575006		**Wing Trailing Edge Wiring Installations - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-00-00, MRB Ref:53-500-EZIP-03 (SOURCE: G280 AMM)					Ldg					
710013		**Powerplant External (View from platform) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	71 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:71-00-00, MRB Ref:71-400-02 (SOURCE: G280 AMM)					Ldg					
710014		**Powerplant External (View from platform) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	71 A/F						Mos		48	-/+1m	31-Mar-2027	2.6 Years (+30 Days)
							Hrs					
		ATA Ref:71-00-00, MRB Ref:71-400-02 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 1. RE 48 Mos, 500 Hrs												
530001		**Main Landing Gear Wheel Wells (Internal) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
	53 A/F						Mos	26-Jul-2024	48	-/+1m	31-Jul-2028	3.9 Years (+31 Days)
							Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
		ATA Ref:53-00-00, MRB Ref:53-100-16 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM) (NOTE: Accomplish at 1A or 4C, whichever occurs first. Aircraft beyond 2C from EIS, without a prior compliance or 2C from last compliance at date of Revision 16 (see List of Revisions), accomplish at 1A or 24 months from EIS or last compliance as applicable and every 1A or 4C, whichever occurs first thereafter.)					Ldg	562				
530002		**Main Landing Gear Wheel Wells (Internal) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
	53 A/F						Mos	26-Jul-2024	48	-/+1m	31-Jul-2028	3.9 Years (+31 Days)
							Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
		ATA Ref:53-00-00, MRB Ref:53-100-16 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM) (NOTE: Accomplish at 1A or 4C, whichever occurs first. Aircraft beyond 2C from EIS, without a prior compliance or 2C from last compliance at date of Revision 16 (see List of Revisions), accomplish at 1A or 24 months from EIS or last compliance as applicable and every 1A or 4C, whichever occurs first thereafter.)					Ldg	562				
▼ 1. RE 4800 Hrs												
712001		**Engine Mount Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈12-Nov-2029**
	71 A/F						Mos					
							Hrs		4,800	-/+50	4800	3742 Hrs (+50)
		ATA Ref:71-20-00, MRB Ref:72-71-00-08 (SOURCE: G280 AMM)					Ldg					
712002		**Engine Mount Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈12-Nov-2029**
	71 A/F						Mos					
							Hrs		4,800	-/+50	4800	3742 Hrs (+50)
		ATA Ref:71-20-00, MRB Ref:72-71-00-08 (SOURCE: G280 AMM)					Ldg					
717001		**Engine Drain System / Attachment Fittings - General Visual Inspection**							RE	LMM 05-20-00 Periodic Inspections		**≈24-Nov-2029**
	71 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
		(SOURCE: AS907-2-1G LMM (72-05-16))					Enc					
717001		**Engine Drain System / Attachment Fittings - General Visual Inspection**							RE	LMM 05-20-00 Periodic Inspections		**≈14-Nov-2029**
	71 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
		(SOURCE: AS907-2-1G LMM (72-05-16))					Enc					
722103		**Fan Containment Housing Assembly - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈24-Nov-2029**
	72 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
		ATA Ref:72-21-01, MRB Ref:72-71-00/07 (SOURCE: G280 AMM)					Enc					
722103		**Fan Containment Housing Assembly - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Nov-2029**
	72 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
		ATA Ref:72-21-01, MRB Ref:72-71-00/07 (SOURCE: G280 AMM)					Enc					
722104		**Fan Rotor Assembly - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈24-Nov-2029**
	72 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
		ATA Ref:72-21-01, MRB Ref:72-71-00-01 (SOURCE: G280 AMM)					Enc					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
722104		**Fan Rotor Assembly - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Nov-2029**
	72 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
		ATA Ref:72-21-01, MRB Ref:72-71-00-01 (SOURCE: G280 AMM)					Enc					
722105		**Fan Stub Shaft and Fan Retention Hardware - Functional Check**							RE	05-20-00 Scheduled Maintenance Checks		**≈24-Nov-2029**
	72 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
		ATA Ref:72-21-01, MRB Ref:72-71-00-10 (SOURCE: G280 AMM)					Enc					
722105		**Fan Stub Shaft and Fan Retention Hardware - Functional Check**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Nov-2029**
	72 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
		ATA Ref:72-21-01, MRB Ref:72-71-00-10 (SOURCE: G280 AMM)					Enc					
723012		**Engine Compressor Case - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈24-Nov-2029**
	72 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
		ATA Ref:72-30-00, MRB Ref:72-30-00/08 (SOURCE: G280 AMM)					Enc					
723012		**Engine Compressor Case - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Nov-2029**
	72 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
		ATA Ref:72-30-00, MRB Ref:72-30-00/08 (SOURCE: G280 AMM)					Enc					
723013		**HP/LP Bleed Air Ducts - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈24-Nov-2029**
	72 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
		ATA Ref:72-30-00, MRB Ref:72-30-00/07 (SOURCE: G280 AMM)					Enc					
723013		**HP/LP Bleed Air Ducts - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Nov-2029**
	72 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
		ATA Ref:72-30-00, MRB Ref:72-30-00/07 (SOURCE: G280 AMM)					Enc					
723017		**Air Turbine Starter (ATS) Ducts - General Visual Inspection**							RE	LMM 05-20-00 Periodic Inspections		**≈24-Nov-2029**
	72 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
		(SOURCE: AS907-2-1G LMM (72-05-16))					Enc					
723017		**Air Turbine Starter (ATS) Ducts - General Visual Inspection**							RE	LMM 05-20-00 Periodic Inspections		**≈14-Nov-2029**
	72 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
		(SOURCE: AS907-2-1G LMM (72-05-16))					Enc					
724003		**Engine Combustor Case - General Visual Inspection**							RE	LMM 05-20-00 Periodic Inspections		**≈24-Nov-2029**
	72 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
		(SOURCE: AS907-2-1G LMM (72-05-16))					Enc					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
724003		**Engine Combustor Case - General Visual Inspection**							RE		LMM 05-20-00 Periodic Inspections	**≈14-Nov-2029**
	72 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
	(SOURCE: AS907-2-1G LMM (72-05-16))						Enc					
724101		**Engine Combustor Module - Special Detailed Inspection**							RE		05-20-00 Scheduled Maintenance Checks	**≈24-Nov-2029**
	72 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
	ATA Ref:72-41-00, MRB Ref:72-40-00/01 (SOURCE: G280 AMM)						Enc					
724101		**Engine Combustor Module - Special Detailed Inspection**							RE		05-20-00 Scheduled Maintenance Checks	**≈14-Nov-2029**
	72 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
	ATA Ref:72-41-00, MRB Ref:72-40-00/01 (SOURCE: G280 AMM)						Enc					
725001		**Engine LP Turbine Module - Special Detailed Inspection**							RE		05-20-00 Scheduled Maintenance Checks	**≈24-Nov-2029**
	72 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
	ATA Ref:72-50-00, MRB Ref:72-55-00/01, MRB Ref:75-21-00/04 (SOURCE: G280 AMM)						Enc					
725001		**Engine LP Turbine Module - Special Detailed Inspection**							RE		05-20-00 Scheduled Maintenance Checks	**≈14-Nov-2029**
	72 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
	ATA Ref:72-50-00, MRB Ref:72-55-00/01, MRB Ref:75-21-00/04 (SOURCE: G280 AMM)						Enc					
725002		**Engine LP Turbine Case - General Visual Inspection**							RE		05-20-00 Scheduled Maintenance Checks	**≈24-Nov-2029**
	72 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
	ATA Ref:72-50-00, MRB Ref:72-55-00/03, MRB Ref:75-21-00/05 (SOURCE: G280 AMM)						Enc					
725002		**Engine LP Turbine Case - General Visual Inspection**							RE		05-20-00 Scheduled Maintenance Checks	**≈14-Nov-2029**
	72 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
	ATA Ref:72-50-00, MRB Ref:75-21-00/05, MRB Ref:72-55-00/03 (SOURCE: G280 AMM)						Enc					
725003		**Engine HP Turbine Module (Borescope) - Special Detailed Inspection**							RE		05-20-00 Scheduled Maintenance Checks	**≈24-Nov-2029**
	72 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
	ATA Ref:72-50-00, MRB Ref:75-21-00-01 (SOURCE: G280 AMM)						Enc					
725003		**Engine HP Turbine Module (Borescope) - Special Detailed Inspection**							RE		05-20-00 Scheduled Maintenance Checks	**≈14-Nov-2029**
	72 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
	ATA Ref:72-50-00, MRB Ref:75-21-00-01 (SOURCE: G280 AMM)						Enc					
725004		**Engine Exit Guide Vane Assembly - Detailed Inspection**							RE		05-20-00 Scheduled Maintenance Checks	**≈24-Nov-2029**
	72 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
	ATA Ref:72-50-00, MRB Ref:72-55-00/11 (SOURCE: G280 AMM)						Enc					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725004		**Engine Exit Guide Vane Assembly - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Nov-2029**
	72 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
		ATA Ref:72-50-00, MRB Ref:72-55-00/11 (SOURCE: G280 AMM)					Enc					
725005		**Engine Aft Mount Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈24-Nov-2029**
	72 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
		ATA Ref:72-50-00, MRB Ref:72-55-00/12 (SOURCE: G280 AMM)					Enc					
725005		**Engine Aft Mount Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Nov-2029**
	72 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
		ATA Ref:72-50-00, MRB Ref:72-55-00/12 (SOURCE: G280 AMM)					Enc					
726003		**Accessory Gearbox Assembly (AGB) - General Visual Inspection**							RE	LMM 05-20-00 Periodic Inspections		**≈24-Nov-2029**
	72 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
		(SOURCE: AS907-2-1G LMM (72-05-16))					Enc					
726003		**Accessory Gearbox Assembly (AGB) - General Visual Inspection**							RE	LMM 05-20-00 Periodic Inspections		**≈14-Nov-2029**
	72 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
		(SOURCE: AS907-2-1G LMM (72-05-16))					Enc					
727107		**Rear Engine Mount Strut Seals - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈24-Nov-2029**
	72 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
		ATA Ref:72-71-00, MRB Ref:72-72-00/03 (SOURCE: G280 AMM)					Enc					
727107		**Rear Engine Mount Strut Seals - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Nov-2029**
	72 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
		ATA Ref:72-71-00, MRB Ref:72-72-00/03 (SOURCE: G280 AMM)					Enc					
727108		**Engine Inner and Outer Fan Bypass Ducts - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈24-Nov-2029**
	72 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
		ATA Ref:72-71-00, MRB Ref:72-72-00/01 (SOURCE: G280 AMM)					Enc					
727108		**Engine Inner and Outer Fan Bypass Ducts - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Nov-2029**
	72 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
		ATA Ref:72-71-00, MRB Ref:72-72-00/01 (SOURCE: G280 AMM)					Enc					
731301		**Engine Fuel System Components and Tubing - General Visual Inspection**							RE	LMM 05-20-00 Periodic Inspections		**≈24-Nov-2029**
	73 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
		(SOURCE: AS907-2-1G LMM (72-05-16))					Enc					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
731301		**Engine Fuel System Components and Tubing - General Visual Inspection**							RE		LMM 05-20-00 Periodic Inspections	**≈14-Nov-2029**
	73 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
	(SOURCE: AS907-2-1G LMM (72-05-16))						Enc					
732025		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈24-Nov-2029**
	73 ENG1	No.1					Mos					
	70040941-1						Hrs		4,800		4800	3766:24 Hrs
	AAF45051						Enc					
	ATA Ref:73-13-01, MRB Ref:72-40-00-04, MRB Ref:73-10-00/05 (SOURCE: G280 AMM)											
732025		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈14-Nov-2029**
	73 ENG2	No.1					Mos					
	70040941-1						Hrs		4,800		4800	3746:24 Hrs
	AAF52392						Enc					
	ATA Ref:73-13-01, MRB Ref:72-40-00-04, MRB Ref:73-10-00/05 (SOURCE: G280 AMM)											
732026		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈24-Nov-2029**
	73 ENG1	No.2					Mos					
	70040941-1						Hrs		4,800		4800	3766:24 Hrs
	AAF45052						Enc					
	ATA Ref:73-13-01, MRB Ref:72-40-00-04, MRB Ref:73-10-00/05 (SOURCE: G280 AMM)											
732026		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈14-Nov-2029**
	73 ENG2	No.2					Mos					
	70040941-1						Hrs		4,800		4800	3746:24 Hrs
	AAF52394						Enc					
	ATA Ref:73-13-01, MRB Ref:72-40-00-04, MRB Ref:73-10-00/05 (SOURCE: G280 AMM)											
732027		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈24-Nov-2029**
	73 ENG1	No.3					Mos					
	70040941-1						Hrs		4,800		4800	3766:24 Hrs
	AAF45054						Enc					
	ATA Ref:73-13-01, MRB Ref:73-10-00/05, MRB Ref:72-40-00-04 (SOURCE: G280 AMM)											
732027		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈14-Nov-2029**
	73 ENG2	No.3					Mos					
	70040941-1						Hrs		4,800		4800	3746:24 Hrs
	AAF53830						Enc					
	ATA Ref:73-13-01, MRB Ref:73-10-00/05, MRB Ref:72-40-00-04 (SOURCE: G280 AMM)											
732028		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈24-Nov-2029**
	73 ENG1	No.4					Mos					
	70040941-1						Hrs		4,800		4800	3766:24 Hrs
	AAF45055						Enc					
	ATA Ref:73-13-01, MRB Ref:73-10-00/05, MRB Ref:72-40-00-04 (SOURCE: G280 AMM)											
732028		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈14-Nov-2029**
	73 ENG2	No.4					Mos					
	70040941-1						Hrs		4,800		4800	3746:24 Hrs
	AAF53832						Enc					
	ATA Ref:73-13-01, MRB Ref:73-10-00/05, MRB Ref:72-40-00-04 (SOURCE: G280 AMM)											
732029		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈24-Nov-2029**
	73 ENG1	No.5					Mos					
	70040941-1						Hrs		4,800		4800	3766:24 Hrs
	AAF45056						Enc					
	ATA Ref:73-13-01, MRB Ref:73-10-00/05, MRB Ref:72-40-00-04 (SOURCE: G280 AMM)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
732029		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈14-Nov-2029**
	73 ENG2	No.5					Mos					
	70040941-1						Hrs		4,800		4800	3746:24 Hrs
	AAF53833						Enc					
	ATA Ref:73-13-01, MRB Ref:73-10-00/05, MRB Ref:72-40-00-04 (SOURCE: G280 AMM)											
732030		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈24-Nov-2029**
	73 ENG1	No.6					Mos					
	70040941-1						Hrs		4,800		4800	3766:24 Hrs
	AAF45057						Enc					
	ATA Ref:73-13-01, MRB Ref:73-10-00/05, MRB Ref:72-40-00-04 (SOURCE: G280 AMM)											
732030		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈14-Nov-2029**
	73 ENG2	No.6					Mos					
	70040941-1						Hrs		4,800		4800	3746:24 Hrs
	AAF53834						Enc					
	ATA Ref:73-13-01, MRB Ref:73-10-00/05, MRB Ref:72-40-00-04 (SOURCE: G280 AMM)											
732031		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈24-Nov-2029**
	73 ENG1	No.7					Mos					
	70040941-1						Hrs		4,800		4800	3766:24 Hrs
	AAF45059						Enc					
	ATA Ref:73-13-01, MRB Ref:73-10-00/05, MRB Ref:72-40-00-04 (SOURCE: G280 AMM)											
732031		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈14-Nov-2029**
	73 ENG2	No.7					Mos					
	70040941-1						Hrs		4,800		4800	3746:24 Hrs
	AAF53835						Enc					
	ATA Ref:73-13-01, MRB Ref:73-10-00/05, MRB Ref:72-40-00-04 (SOURCE: G280 AMM)											
732032		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈24-Nov-2029**
	73 ENG1	No.8					Mos					
	70040941-1						Hrs		4,800		4800	3766:24 Hrs
	AAF45060						Enc					
	ATA Ref:73-13-01, MRB Ref:73-10-00/05, MRB Ref:72-40-00-04 (SOURCE: G280 AMM)											
732032		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈14-Nov-2029**
	73 ENG2	No.8					Mos					
	70040941-1						Hrs		4,800		4800	3746:24 Hrs
	AAF53836						Enc					
	ATA Ref:73-13-01, MRB Ref:72-40-00-04, MRB Ref:73-10-00/05 (SOURCE: G280 AMM)											
732033		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈24-Nov-2029**
	73 ENG1	No.9					Mos					
	70040941-1						Hrs		4,800		4800	3766:24 Hrs
	AAF45063						Enc					
	ATA Ref:73-13-01, MRB Ref:72-40-00-04, MRB Ref:73-10-00/05 (SOURCE: G280 AMM)											
732033		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈14-Nov-2029**
	73 ENG2	No.9					Mos					
	70040941-1						Hrs		4,800		4800	3746:24 Hrs
	AAF53838						Enc					
	ATA Ref:73-13-01, MRB Ref:72-40-00-04, MRB Ref:73-10-00/05 (SOURCE: G280 AMM)											
732034		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈24-Nov-2029**
	73 ENG1	No.10					Mos					
	70040941-1						Hrs		4,800		4800	3766:24 Hrs
	AAF45064						Enc					
	ATA Ref:73-13-01, MRB Ref:72-40-00-04, MRB Ref:73-10-00/05 (SOURCE: G280 AMM)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
732034		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈14-Nov-2029**
	73 ENG2	No.10					Mos					
	70040941-1						Hrs		4,800		4800	3746:24 Hrs
	AAF53839						Enc					
	ATA Ref:73-13-01, MRB Ref:72-40-00-04, MRB Ref:73-10-00/05 (SOURCE: G280 AMM)											
732035		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈24-Nov-2029**
	73 ENG1	No.11					Mos					
	70040941-1						Hrs		4,800		4800	3766:24 Hrs
	AAF45065						Enc					
	ATA Ref:73-13-01, MRB Ref:72-40-00-04, MRB Ref:73-10-00/05 (SOURCE: G280 AMM)											
732035		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈14-Nov-2029**
	73 ENG2	No.11					Mos					
	70040941-1						Hrs		4,800		4800	3746:24 Hrs
	AAF53840						Enc					
	ATA Ref:73-13-01, MRB Ref:73-10-00/05, MRB Ref:72-40-00-04 (SOURCE: G280 AMM)											
732036		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈24-Nov-2029**
	73 ENG1	No.12					Mos					
	70040941-1						Hrs		4,800		4800	3766:24 Hrs
	AAF51746						Enc					
	ATA Ref:73-13-01, MRB Ref:73-10-00/05, MRB Ref:72-40-00-04 (SOURCE: G280 AMM)											
732036		**(Main Hi-Temp Injection) Fuel Nozzles - Restoration**							RE		05-10-00 Time Limits	**≈14-Nov-2029**
	73 ENG2	No.12					Mos					
	70040941-1						Hrs		4,800		4800	3746:24 Hrs
	AAF53842						Enc					
	ATA Ref:73-13-01, MRB Ref:73-10-00/05, MRB Ref:72-40-00-04 (SOURCE: G280 AMM)											
732061		**Engine P3 Sensor Line - Detailed Inspection**							RE	05-20-00	Scheduled Maintenance Checks	**≈24-Nov-2029**
	73 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
	ATA Ref:73-20-00, MRB Ref:73-20-00/02 (SOURCE: G280 AMM)						Enc					
732061		**Engine P3 Sensor Line - Detailed Inspection**							RE	05-20-00	Scheduled Maintenance Checks	**≈14-Nov-2029**
	73 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
	ATA Ref:73-20-00, MRB Ref:73-20-00/02 (SOURCE: G280 AMM)						Enc					
732105		**Fuel Filter Element - Discard**							RE		05-10-00 Time Limits	**≈24-Nov-2029**
	73 ENG1						Mos					
	2687159						Hrs		4,800		4800	3766:24 Hrs
	NSN						Enc					
	ATA Ref:73-10-05, MRB Ref:73-10-00-03 (SOURCE: G280 AMM)											
732105		**Fuel Filter Element - Discard**							RE		05-10-00 Time Limits	**≈14-Nov-2029**
	73 ENG2						Mos					
	2687159						Hrs		4,800		4800	3746:24 Hrs
	NSN						Enc					
	ATA Ref:73-10-05, MRB Ref:73-10-00-03 (SOURCE: G280 AMM)											
752001		**Engine LP Turbine Cooling Tubes and Attachment Hardware - General Visual Inspection**							RE	05-20-00	Scheduled Maintenance Checks	**≈24-Nov-2029**
	75 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
	ATA Ref:75-20-00, MRB Ref:75-21-00/08 (SOURCE: G280 AMM)						Enc					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
752001		**Engine LP Turbine Cooling Tubes and Attachment Hardware - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Nov-2029**
	75 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
		ATA Ref:75-20-00, MRB Ref:75-21-00/08 (SOURCE: G280 AMM)					Enc					
752002		**LP Turbine Cooling Tube Assemblies - Functional Check**							RE	05-20-00 Scheduled Maintenance Checks		**≈24-Nov-2029**
	75 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
		ATA Ref:75-20-00, MRB Ref:75-21-00/09 (SOURCE: G280 AMM)					Enc					
752002		**LP Turbine Cooling Tube Assemblies - Functional Check**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Nov-2029**
	75 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
		ATA Ref:75-20-00, MRB Ref:75-21-00/09 (SOURCE: G280 AMM)					Enc					
752021		**Engine Buffer Air Tubes - General Visual Inspection**							RE	LMM 05-20-00 Periodic Inspections		**≈24-Nov-2029**
	75 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
		(SOURCE: AS907-2-1G LMM (72-05-16))					Enc					
752021		**Engine Buffer Air Tubes - General Visual Inspection**							RE	LMM 05-20-00 Periodic Inspections		**≈14-Nov-2029**
	75 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
		(SOURCE: AS907-2-1G LMM (72-05-16))					Enc					
761007		**Electronic Control Unit (Channel A) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈24-Nov-2029**
	76 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
		ATA Ref:76-21-00, MRB Ref:76-21-00-03 (SOURCE: G280 AMM) (NOTE: Post SB AS907-76-9021R1 at 4800 flight hours.)					Enc					
761007		**Electronic Control Unit (Channel A) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Nov-2029**
	76 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
		ATA Ref:76-21-00, MRB Ref:76-21-00-03 (SOURCE: G280 AMM) (NOTE: Post SB AS907-76-9021R1 at 4800 flight hours.)					Enc					
761008		**Electronic Control Unit (Channel B) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈24-Nov-2029**
	76 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
		ATA Ref:76-21-00, MRB Ref:76-21-00-03 (SOURCE: G280 AMM) (NOTE: Post SB AS907-76-9021R1 at 4800 flight hours.)					Enc					
761008		**Electronic Control Unit (Channel B) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Nov-2029**
	76 ENG2						Mos					
							Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
		ATA Ref:76-21-00, MRB Ref:76-21-00-03 (SOURCE: G280 AMM) (NOTE: Post SB AS907-76-9021R1 at 4800 flight hours.)					Enc					
761021		**Engine Wiring Harness - General Visual Inspection**							RE	LMM 05-20-00 Periodic Inspections		**≈24-Nov-2029**
	76 ENG1						Mos					
							Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
		(SOURCE: AS907-2-1G LMM (72-05-16))					Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
761021	**Engine Wiring Harness - General Visual Inspection**							RE		LMM 05-20-00 Periodic Inspections	**≈14-Nov-2029**
76 ENG2						Mos					
						Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
(SOURCE: AS907-2-1G LMM (72-05-16))						Enc					
781109	**Engine Mixer Nozzle (Left) - General Visual Inspection**							RE			**≈12-Nov-2029**
78 A/F						Mos					
						Hrs		4,800	-/+50	4800	3742 Hrs (+50)
(SOURCE: 05-20-00 Table 8009)						Ldg					
781110	**Engine Mixer Nozzle (Right) - General Visual Inspection**							RE			**≈12-Nov-2029**
78 A/F						Mos					
						Hrs		4,800	-/+50	4800	3742 Hrs (+50)
(SOURCE: 05-20-00 Table 8009)						Ldg					
792301	**Engine Oil System External Plumbing - General Visual Inspection**							RE		LMM 05-20-00 Periodic Inspections	**≈24-Nov-2029**
79 ENG1						Mos					
						Hrs		4,800	-/+50	4800	3766:24 Hrs (+50)
(SOURCE: AS907-2-1G LMM (72-05-16))						Enc					
792301	**Engine Oil System External Plumbing - General Visual Inspection**							RE		LMM 05-20-00 Periodic Inspections	**≈14-Nov-2029**
79 ENG2						Mos					
						Hrs		4,800	-/+50	4800	3746:24 Hrs (+50)
(SOURCE: AS907-2-1G LMM (72-05-16))						Enc					
▼ 1. RE 5 Yrs											
262115	**Fire Extinguishing Bottle - (Hydrostatic) Functional Check**							RE		05-00-00 MRIP, 05-10-00 Time Limits	
26 A/F	Left					Yrs		5		31-Mar-2027	2.6 Years
474789-2						Hrs					
AGF7198						Ldg					
Hydrostatic Tested Date 31-Mar-2022											
(SOURCE: G280 AMM) (NOTE: Hydrostatic Test / re-qualification 5 years from new or since last hydrostatic test / re-qualification. Note (1) Operators may elect to accomplish the Hydrostatic test re-qualification of these bottles at the interval published in the table above or per their National Aviation Authority requirements. Based upon National Aviation Authority requirements, it may be acceptable for these bottles to remain in service beyond the Hydrostatic test / requalification due date until they are removed from the aircraft.)											
262116	**Fire Extinguishing Bottle - (Hydrostatic) Functional Check**							RE		05-00-00 MRIP, 05-10-00 Time Limits	
26 A/F	Right					Yrs		5		31-Mar-2027	2.6 Years
474789-1						Hrs					
AGF7193						Ldg					
Hydrostatic Tested Date 31-Mar-2022											
(SOURCE: G280 AMM) (NOTE: Hydrostatic Test / re-qualification 5 years from new or since last hydrostatic test / re-qualification. Note (1) Operators may elect to accomplish the Hydrostatic test re-qualification of these bottles at the interval published in the table above or per their National Aviation Authority requirements. Based upon National Aviation Authority requirements, it may be acceptable for these bottles to remain in service beyond the Hydrostatic test / requalification due date until they are removed from the aircraft.)											

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
351104	**Oxygen Bottle / Regulator Assembly - Restore**							RE	05-00-00 MRIP, 05-10-00 Time Limits		
35 A/F						Yrs	19-Jan-2023	5		31-Jan-2028	3.4 Years
807435-02						Hrs					
C22040248						Ldg					
	Hydrostatic Tested Date 19-Jan-2023										
	ATA Ref:35-11-01, Ref:MRIP (SOURCE: G280 AMM) (NOTE: Hydrostatic Test / re-qualification 5 years from new or since last hydrostatic test / re-qualification. Note (1) Operators may elect to accomplish the Hydrostatic test re-qualification of these bottles at the interval published in the table above or per their National Aviation Authority requirements. Based upon National Aviation Authority requirements, it may be acceptable for these bottles to remain in service beyond the Hydrostatic test / requalification due date until they are removed from the aircraft.)										
▼ 1. RE 500 Hrs											
243204	**APU Starter-Generator Brushes - Functional Check**							RE	05-20-00 Scheduled Maintenance Checks		**≈25-Oct-2025**
24 APU1						Mos	09-Jul-2024				
G3666-400						Hrs	541	500	-/+50	1041	412 Hrs (+50)
2144B						APUS	742				
	ATA Ref:24-32-01, MRB Ref:24-30-00/05, MRB Ref:49-40-00/01 (Manual Adjustment: 0 Hrs) (SOURCE: G280 AMM)										
262101	**Engine Fire Extinguishing System - Functional Check (*CMR)**							RE	05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
26 A/F						Mos	26-Jul-2024				
						Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
	ATA Ref:26-21-00, CMR Ref:26-00-02 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM) (NOTE: Accomplish at 500 flight hours or 6A, whichever occurs first.)					Ldg	562				
320005	**Main Landing Gear and Doors (Left) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
32 A/F						Mos	26-Jul-2024				
						Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
	ATA Ref:32-00-00, MRB Ref:32-700-01 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)					Ldg	562				
320006	**Main Landing Gear and Doors (Right) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
32 A/F						Mos	26-Jul-2024				
						Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
	ATA Ref:32-00-00, MRB Ref:32-700-01 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)					Ldg	562				
320007	**Nose Landing Gear and Doors - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
32 A/F						Mos	26-Jul-2024				
						Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
	ATA Ref:32-00-00, MRB Ref:32-700-01 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)					Ldg	562				
323211	**Main Landing Gear Uplock Roller Assembly (Left) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
32 A/F						Mos	26-Jul-2024				
						Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
	ATA Ref:32-32-02, MRB Ref:32-30-00-11 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM) (NOTE: Accomplish at 1A Check, not to exceed 500 hours from date of Revision 8 (see List of Revisions) and every 1A thereafter.)					Ldg	562				
323212	**Main Landing Gear Uplock Roller Assembly (Right) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
32 A/F						Mos	26-Jul-2024				
						Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
	ATA Ref:32-32-02, MRB Ref:32-30-00-11 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM) (NOTE: Accomplish at 1A Check, not to exceed 500 hours from date of Revision 8 (see List of Revisions) and every 1A thereafter.)					Ldg	562				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
326409		**Nose Wheel Steering Proximity Switch - Operational Check**					RE	05-20-00 Scheduled Maintenance Checks				**≈23-Mar-2025**
	32 A/F						Mos	26-Jul-2024				
							Hrs	967:25	500	-/+50	1467:25	409:25 Hrs (+50)
		ATA Ref:32-64-02, MRB Ref:32-50-00-02 (SOURCE: G280 AMM)					Ldg	562				
334001		**Strobe and Navigation Lights - Operational Check**					RE	05-20-00 Scheduled Maintenance Checks				**≈23-Mar-2025**
	33 A/F						Mos	26-Jul-2024				
							Hrs	967:25	500	-/+50	1467:25	409:25 Hrs (+50)
		ATA Ref:33-40-00, MRB Ref:33-40-00/01 (SOURCE: G280 AMM)					Ldg	562				
335107		**Operational Check of Battery Energy Level Test (BITE)**					RE	05-20-00 Scheduled Maintenance Checks				**≈09-Apr-2025**
	33 A/F						Mos	26-Jul-2024				
							Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
		ATA Ref:33-51-00 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AOMM) (NOTE: Securaplane Lead Acid battery only. See Cabin Emergency Lighting.)					Ldg	562				
335108		**Operational Check of Battery Energy Level Test (BITE)**					RE	05-20-00 Scheduled Maintenance Checks				**≈09-Apr-2025**
	33 A/F						Mos	26-Jul-2024				
							Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
		ATA Ref:33-51-00 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AOMM) (NOTE: Securaplane Lead Acid battery only. See Cabin Emergency Lighting.)					Ldg	562				
495101		**APU Inlet Duct - General Visual Inspection**					RE	05-20-00 Scheduled Maintenance Checks				**≈09-Apr-2025**
	49 A/F						Mos	26-Jul-2024				
							Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
		ATA Ref:49-51-00, MRB Ref:49-12-00/01 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)					Ldg	562				
521008		**Main Entrance Door Guide Tracks - Lubrication**					RE	05-20-00 Scheduled Maintenance Checks				**≈09-Apr-2025**
	52 A/F						Mos	26-Jul-2024				
							Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
		ATA Ref:52-10-00, MRB Ref:52-10-00/04 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)					Ldg	562				
710015		**Powerplant and Cowl Doors (Internal) (Left) - Zonal Inspection**					RE	05-20-00 Scheduled Maintenance Checks				**≈09-Apr-2025**
	71 A/F						Mos	26-Jul-2024				
							Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
		ATA Ref:71-00-00, MRB Ref:71-400-04 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)					Ldg	562				
710016		**Powerplant and Cowl Doors (Internal) (Right) - Zonal Inspection**					RE	05-20-00 Scheduled Maintenance Checks				**≈09-Apr-2025**
	71 A/F						Mos	26-Jul-2024				
							Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
		ATA Ref:71-00-00, MRB Ref:71-400-04 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)					Ldg	562				
722106		**Fan Stator Assembly - General Visual Inspection**					RE	05-20-00 Scheduled Maintenance Checks				**≈23-Mar-2025**
	72 ENG1						Mos	26-Jul-2024				
							Hrs	943:01	500	-/+50	1443:01	409:25 Hrs (+50)
		ATA Ref:72-21-01, MRB Ref:72-71-00/13 (SOURCE: G280 AMM)					Enc	557				
722106		**Fan Stator Assembly - General Visual Inspection**					RE	05-20-00 Scheduled Maintenance Checks				**≈11-Apr-2025**
	72 ENG2						Mos	26-Jul-2024				
							Hrs	963:01	500	-/+50	1500	446:24 Hrs (+50)
		ATA Ref:72-21-01, MRB Ref:72-71-00/13 (Tol. Adjustment: 37 Hrs) (SOURCE: G280 AMM)					Enc	569				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
732106	**Engine Fuel Filter Mechanical Differential Pressure Indicator (DPI) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈23-Mar-2025**
73 ENG1						Mos	26-Jul-2024				
						Hrs	943:01	500	-/+50	1443:01	409:25 Hrs (+50)
ATA Ref:73-10-05, MRB Ref:73-10-00/04 (SOURCE: G280 AMM)						Enc	557				
732106	**Engine Fuel Filter Mechanical Differential Pressure Indicator (DPI) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈11-Apr-2025**
73 ENG2						Mos	26-Jul-2024				
						Hrs	963:01	500	-/+50	1500	446:24 Hrs (+50)
ATA Ref:73-10-05, MRB Ref:73-10-00/04 (Tol. Adjustment: 37 Hrs) (SOURCE: G280 AMM)						Enc	569				
801113	**Magnetic Drain Plug on the Engine Air Turbine Starter (Left) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
80 A/F						Mos	26-Jul-2024				
						Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
ATA Ref:80-11-00, MRB Ref:80-11-00/02 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)						Ldg	562				
801114	**Magnetic Drain Plug on the Engine Air Turbine Starter (Right) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
80 A/F						Mos	26-Jul-2024				
						Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
ATA Ref:80-11-00, MRB Ref:80-11-00/02 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)						Ldg	562				
801115	**Air Turbine Starter Oil System (Left) - Draining**							RE	05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
80 A/F						Mos	26-Jul-2024				
						Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
ATA Ref:80-11-01, MRB Ref:80-11-00/01 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)						Ldg	562				
801116	**Air Turbine Starter Oil System (Right) - Draining**							RE	05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
80 A/F						Mos	26-Jul-2024				
						Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
ATA Ref:80-11-01, MRB Ref:80-11-00/01 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)						Ldg	562				
▼ 1. RE 500 Hrs, 300 Ldg											
324309	**Brake Wear Indicator - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈01-Mar-2025**
32 A/F						Mos	26-Jul-2024				
						Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
ATA Ref:32-43-00, MRB Ref:32-49-00-05 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)						Ldg	562	300		862	244 Ldg
324310	**Brake Wear Indicator - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈01-Mar-2025**
32 A/F						Mos	26-Jul-2024				
						Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
ATA Ref:32-43-00, MRB Ref:32-49-00-05 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)						Ldg	562	300		862	244 Ldg
324311	**Brake Wear Indicator - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈01-Mar-2025**
32 A/F						Mos	26-Jul-2024				
						Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
ATA Ref:32-43-00, MRB Ref:32-49-00-05 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)						Ldg	562	300		862	244 Ldg
324312	**Brake Wear Indicator - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈01-Mar-2025**
32 A/F						Mos	26-Jul-2024				
						Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
ATA Ref:32-43-00, MRB Ref:32-49-00-05 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM)						Ldg	562	300		862	244 Ldg

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 1. RE 5000 Hrs												
273417		**Eddy Current Damper - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈21-Feb-2030**
	27 A/F						Mos					
							Hrs		5,000	-/+50	5000	3942 Hrs (+50)
		ATA Ref:27-34-03, MRB Ref:27-30-00/04 (SOURCE: G280 AMM)					Ldg					
275003		**Alternate Flap Channel Verification - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		**≈10-Mar-2030**
	27 A/F						Mos	02-Mar-2023				
							Hrs	34:12	5,000	-/+50	5034:12	3976:12 Hrs (+50)
		ATA Ref:27-50-00, MRB Ref:27-50-00/01 (SOURCE: G280 AMM)					Ldg	10				
280005		**Refuel / Defuel Power - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		**≈04-Mar-2030**
	28 A/F						Mos	17-Jan-2023				
							Hrs	22:54	5,000	-/+50	5022:54	3964:54 Hrs (+50)
		ATA Ref:28-00-00, Ref:MRIP (SOURCE: G280 AMM)					Ldg	6				
325001		**Nose Landing Gear Free Castor Mode - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		**≈21-Feb-2030**
	32 A/F						Mos					
							Hrs		5,000	-/+50	5000	3942 Hrs (+50)
		ATA Ref:32-50-00, MRB Ref:32-50-00/01 (SOURCE: G280 AMM)					Ldg					
344013		**EVS Sapphire WIndow Functional Check**							RE			**≈21-Feb-2030**
	34 A/F						Mos					
							Hrs		5,000	-/+50	5000	3942 Hrs (+50)
							Ldg					
491112		**APU Mounting System - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈11-Mar-2031**
	49 A/F						Mos	09-Apr-2024				
							Hrs	752:50	5,000	-/+50	5752:50	4694:50 Hrs (+50)
		ATA Ref:49-11-01, MRB Ref:53.50.04/04, MRB Ref:49-11-00-01 (SOURCE: G280 AMM) (NOTE: Task satisfies CCMR 49-00-02 at 10A. NOTE: ± 50 flight hour window applies. NOTE: Perform at APU removal from airframe, not to exceed 10A.)					Ldg	442				
496103		**APU Electronic Control Unit - Restore (**CMR)**							RE		05-10-10 CMR	**≈02-Nov-2036**
	49 APU1						Mos					
							Hrs		5,000	-/+50	5000	4371 Hrs (+50)
		ATA Ref:49-61-01, CMR Ref:49-00-01 (SOURCE: G280 AMM)					APUS					
▼ 1. RE 6 Mos												
		Ipad holder - suction mount exchange							RE			
	0 A/F						Mos	10-Sep-2024	6		10-Mar-2025	6 Months
							Hrs					
		(NOTE: CAA requirement)					Ldg					
Interior Care - Seats		**Interior Care - Seats**							RE			
	0 A/F						Mos	15-Aug-2024	6		15-Feb-2025	5.3 Months
							Hrs					
							Ldg					
541101		**Nose Cowling (Left) Leading Edge Polishing / Corrosion Prevention (Recurring / In-Service Application)**							RE			
	54 A/F						Mos	03-Apr-2024	6		31-Oct-2024	51 Days
							Hrs					
		Mfg#:54-11-00					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
551108		**Horizontal Stabilizer Leading Edge - Polishing**							RE			
	55 A/F						Mos	03-Apr-2024	6		31-Oct-2024	51 Days
							Hrs					
	Ref#:55-10-00-CP						Ldg					
574161		**Wing Leading Edge (Left) - Polishing**							RE			
	57 A/F						Mos	03-Apr-2024	6		31-Oct-2024	51 Days
							Hrs					
	Mfg#:57-41-01-CP						Ldg					
574162		**Wing Leading Edge (Right) - Polishing**							RE			
	57 A/F						Mos	03-Apr-2024	6		31-Oct-2024	51 Days
							Hrs					
	Mfg#:57-41-01-CP						Ldg					
▼ 1. RE 60 Mos												
262117		**Fire Extinguishing Bottle - Weight Check**							RE	05-20-00 Scheduled Maintenance Checks		
	26 A/F	Left					Mos		60	-/+1m	31-Mar-2028	3.6 Years (+30 Days)
	474789-2						Hrs					
	AGF7198						Ldg					
	Weighed Date 02-Mar-2023											
	ATA Ref:26-21-01, MRB Ref:26-20-00-09 (SOURCE: G280 AMM) (NOTE: Accomplish 60 months from date of manufacture and every 60 months thereafter.)											
262118		**Fire Extinguishing Bottle - Weight Check**							RE	05-20-00 Scheduled Maintenance Checks		
	26 A/F	Right					Mos		60	-/+1m	31-Mar-2028	3.6 Years (+30 Days)
	474789-1						Hrs					
	AGF7193						Ldg					
	Weighed Date 02-Mar-2023											
	ATA Ref:26-21-01, MRB Ref:26-20-00/09 (SOURCE: G280 AMM) (NOTE: Accomplish 60 months from date of manufacture and every 60 months thereafter.)											
262434		**Portable Water Fire Extinguisher (Proof Pressure Test) - Functional Check**							RE	05-10-00 Time Limits		
	26 A/F	Cabin - Left					Mos	10-Feb-2023	60		31-May-2027	2.7 Years
	892480						Hrs	24:24				
	47852						Ldg	7				
	Hydrostatic Tested Date 31-May-2022											
	ATA Ref:26-24-03 (SOURCE: G280 AOMM) (NOTE: This item applies if installed.)											
353103		**Portable Oxygen Cylinder - Hydrostatic Functional Check**							RE	05-10-00 Time Limits		
	35 A/F						Mos	02-Aug-2023	60		29-Feb-2028	3.5 Years
	Hydrostatic Tested Date 02-Feb-2023						Hrs					
	ATA Ref:35-31-01, MRB Ref:35-30-00/02 (SOURCE: G280 AMM) (NOTE: (1) Operators may elect to accomplish the Hydrostatic test re-qualifcation of these bottles at the interval published in the table above or per their National Aviation Authority requirements. Based upon National Aviation Authority requirements, it may be acceptable for these bottles to remain in service beyond the Hydrostatic test / requalification due date until they are removed from the aircraft.)						Ldg					
▼ 1. RE 6000 Hrs												
262301		**Fire Extinguishing Plumbing - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈14-Jul-2031**
	26 A/F						Mos					
							Hrs		6,000	-/+50	6000	4942 Hrs (+50)
	ATA Ref:26-23-00, MRB Ref:26-20-00-05, MRB Ref:26-20-00-08 (SOURCE: G280 AMM) (NOTE: Task satisfies CCMR 26-00-01A and CCMR 26-00-01B at 12A. ± 50 flight hour window applies. Perform at fire bottle removal not to exceed 12A.)						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 1. RE 6500 Hrs												
271204		**Aileron Trim Actuator Output Shaft and Aileron Trim Tab Free Play - Functional Check (*CMR)**							RE		05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks	**≈25-Mar-2032**
	27 A/F						Mos					
							Hrs		6,500	-/+50	6500	5442 Hrs (+50)
	ATA Ref:27-12-01, CMR Ref:27-10-04 (SOURCE: G280 AMM)						Ldg					
▼ 1. RE 7000 Hrs												
731103		**Fuel Pump - Inspection**							RE		LMM 05-20-00 Periodic Inspections	**≈17-Dec-2032**
	73 ENG1						Mos					
							Hrs		7,000	-/+60	7000	5966:24 Hrs (+60)
	(SOURCE: AS907-2-1G LMM (72-05-16))						Enc					
731103		**Fuel Pump - Inspection**							RE		LMM 05-20-00 Periodic Inspections	**≈06-Dec-2032**
	73 ENG2						Mos					
							Hrs		7,000	-/+60	7000	5946:24 Hrs (+60)
	(SOURCE: AS907-2-1G LMM (72-05-16))						Enc					
732059		**Hydromechanical Unit - Restore**							RE		05-10-00 Time Limits	**≈17-Dec-2032**
	73 ENG1						Mos					
	442661						Hrs		7,000		7000	5966:24 Hrs
	FHC3415						Enc					
	ATA Ref:73-20-01, MRB Ref:73-10-00-06 (SOURCE: G280 AMM) (NOTE: NOTE: For additional interval allowance,, refer to Honeywell LMM AS907-2-1G, 05-20-00.)											
732059		**Hydromechanical Unit - Restore**							RE		05-10-00 Time Limits	**≈06-Dec-2032**
	73 ENG2						Mos					
	442661						Hrs		7,000		7000	5946:24 Hrs
	FHC3416						Enc					
	ATA Ref:73-20-01, MRB Ref:73-10-00-06 (SOURCE: G280 AMM) (NOTE: NOTE: For additional interval allowance,, refer to Honeywell LMM AS907-2-1G, 05-20-00.)											
▼ 1. RE 72 Mos												
351205		**Crew Oxygen Mask - Restore**							RE		05-10-00 Time Limits	
	35 A/F	Pilot					Mos		72		31-Mar-2028	3.6 Years
	MLD20-563					0	Hrs					
	B179327					0	Ldg					
	Restored Date 31-Mar-2022											
	ATA Ref:35-12-01, MRB Ref:35-10-00-02 (SOURCE: G280 AMM)											
351206		**Crew Oxygen Mask - Restore**							RE		05-10-00 Time Limits	
	35 A/F	Copilot					Mos		72		31-Jul-2028	3.9 Years
	MLD20-563					0	Hrs					
	B182837					0	Ldg					
	Restored Date 31-Jul-2022											
	ATA Ref:35-12-01, MRB Ref:35-10-00-02 (SOURCE: G280 AMM)											
352105		**Passenger Oxygen Controller - Restore**							RE		05-10-00 Time Limits	
	35 A/F						Mos		72		30-Nov-2028	4.2 Years
	P27096						Hrs					
	R22050339						Ldg					
	Certified Date 10-Nov-2022											
	ATA:35-21-01, MRB:35-10-00-07 (SOURCE: G280 AMM) (NOTE: Per manufacturer recommendation.)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
521107		**Main Entrance Door Locking Mechanism - General Visual Inspection**							RE		05-20-00 - Scheduled Maintenance Checks	
	52 A/F						Mos	02-Mar-2023	72	-/+1m	31-Mar-2029	4.6 Years (+30 Days)
							Hrs					
		ATA Ref:52-11-01, MRB Ref:52-10-00-03 (SOURCE: G280 AMM) (NOTE: NOTE: Accomplish at 6C since entry into service and every 6C thereafter. For aircraft beyond 4C since entry into service at date of revision 16, see list of revisions, accomplish within 24 months following date of revision 16 and every 6C thereafter.)					Ldg					
531301		**Forward Equipment Racks Wiring Installations - Cleaning**							RE		05-20-00 Scheduled Maintenance Checks	
	53 A/F						Mos		72	-/+1m	31-Mar-2029	4.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-13-01, MRB Ref:53-200-EZIP-03 (SOURCE: G280 AMM)					Ldg					
531306		**Forward Equipment Rack Wiring - General Visual Inspection**							RE		05-20-00 Scheduled Maintenance Checks	
	53 A/F						Mos		72	-/+1m	31-Mar-2029	4.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-13-01, MRB Ref:53-200-EZIP-02 (SOURCE: G280 AMM)					Ldg					
532101		**Aft Equipment Racks Wiring Installations - Cleaning**							RE		05-20-00 Scheduled Maintenance Checks	
	53 A/F						Mos		72	-/+1m	31-Mar-2029	4.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-21-01, MRB Ref:53-200-EZIP-05 (SOURCE: G280 AMM)					Ldg					
532111		**Wiring Installations in Area of Aft Radio Racks - General Visual Inspection**							RE		05-20-00 Scheduled Maintenance Checks	
	53 A/F						Mos		72	-/+1m	31-Mar-2029	4.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-21-01, MRB Ref:53-200-EZIP-04 (SOURCE: G280 AMM)					Ldg					
570201		**Wing Aft Spar External - Detailed Inspection**							RE		05-20-00 Scheduled Maintenance Checks	
	57 A/F						Mos		72	-/+1m	31-Mar-2029	4.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-02-00, MRB Ref:57.02.00/17 (SOURCE: G280 AMM)					Ldg					
570202		**Wing Aft Spar External - Detailed Inspection**							RE		05-20-00 Scheduled Maintenance Checks	
	57 A/F						Mos		72	-/+1m	31-Mar-2029	4.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-02-00, MRB Ref:57.02.00/17 (SOURCE: G280 AMM)					Ldg					
▼ 1. RE 7200 Hrs												
732058		**Hydromechanical Unit (HMU) - Do a complete inspection of the hydromechanical unit. The inspection includes the component disassembly, cleaning, inspection, assembly and test.**							RE		LMM 05-20-00 Periodic Inspections	**≈28-Mar-2033**
	73 ENG1						Mos					
	442661						Hrs		7,200	+600	7200	6166:24 Hrs (+600)
	FHC3415						Enc					
		(SOURCE: AS907-2-1G LMM (72-05-16)) (NOTE: For HMU inspection, per Table 8011, and additional 600 hours is permitted to provide operators schedule flexibility beyond the specific inspection interval given in hours.)										
732058		**Hydromechanical Unit (HMU) - Do a complete inspection of the hydromechanical unit. The inspection includes the component disassembly, cleaning, inspection, assembly and test.**							RE		LMM 05-20-00 Periodic Inspections	**≈18-Mar-2033**
	73 ENG2						Mos					
	442661						Hrs		7,200	+600	7200	6146:24 Hrs (+600)
	FHC3416						Enc					
		(SOURCE: AS907-2-1G LMM (72-05-16)) (NOTE: For HMU inspection, per Table 8011, and additional 600 hours is permitted to provide operators schedule flexibility beyond the specific inspection interval given in hours.)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 1. RE 750 Hrs												
494002		**APU Igniter Plug - Clean / Inspect**							RE			**≈28-Mar-2026**
49 APU1							Mos	09-Apr-2024				
							Hrs	443	750	+45	1193	564 Hrs (+45)
Ref:APU MM : 49-20-00 (SOURCE: APU Manual)							APUS	626				
▼ 1. RE 800 Ldg												
274125		**Horizontal Trim Switch - Discard**							RE		05-10-10 Life Limited Components	**≈14-Jan-2025**
27 A/F		Pilot					Mos					
83460205							Hrs					
NSN							Ldg		800		800	182 Ldg
ATA Ref:27-41-03 (SOURCE: G280 AMM)												
274126		**Horizontal Trim Switch - Discard**							RE		05-10-10 Life Limited Components	**≈14-Jan-2025**
27 A/F		Copilot					Mos					
83460205							Hrs					
NSN							Ldg		800		800	182 Ldg
ATA Ref:27-41-03 (SOURCE: G280 AMM)												
▼ 1. RE 90 Days												
12-20-35-603		**90 Day Low Exposure Area Wash**							RE		05-19-00, Discretionary Maintenance	
12 A/F							Days	02-Aug-2024	90		31-Oct-2024	51 Days
							Hrs					
(SOURCE: Model 680A MM) (NOTE: Aircraft washing is a key component of any CPCP. Washing removes corrosive agents from the surface of the airplane. These wash intervals are a baseline aircraft wash schedule. If an aircraft flies into any Severe Corrosion Areas during its operation route, it may be necessary to increase the frequency of the wash schedule. Textron Aviation Inc. strongly recommends washing or rinsing the airplane as soon as possible, no later than three days, after any operation that exposes the airplane to Runway De-Icing (RDI) fluids. Any delay can result in the greater likelihood of corrosion. Operators can refer to the Exterior Cleaning procedures in Chapter 12, Exterior Cleaning (Wash/Rinse) - Servicing in this manual. Operators can refer to the Citation Standard Practices Manual for the Description and Operation of Corrosion, refer to Chapter 51, Corrosion - Description and Operation and the Corrosion Severity Maps can be found in Chapter 51, Corrosion Severity Maps - Description and Operation.)							Ldg					
▼ 1. RE 96 Mos												
122305		**Rudder Pedal Assembly (Left) - Lubrication**							RE	05-20-00	Scheduled Maintenance Checks	
12 A/F							Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
ATA Ref:12-23-00, MRB Ref:27-20-00/03 (SOURCE: G280 AMM)							Ldg					
122306		**Rudder Pedal Assembly (Right) - Lubrication**							RE	05-20-00	Scheduled Maintenance Checks	
12 A/F							Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
ATA Ref:12-23-00, MRB Ref:27-20-00/03 (SOURCE: G280 AMM)							Ldg					
221003		**Flight Control Panel Ground Points (Left) - General Visual Inspection**							RE	05-20-00	Scheduled Maintenance Checks	
22 A/F							Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
ATA Ref:22-10-00, MRB Ref:HIRF-22-10-03 (SOURCE: G280 AMM)							Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
221004		**Flight Control Panel Ground Points (Right) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	22 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:22-10-00, MRB Ref:HIRF-22-10-04 (SOURCE: G280 AMM)					Ldg					
231108		**VHF COM 1 Ground Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	23 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:23-11-01, MRB Ref:HIRF-34-00-01 (SOURCE: G280 AMM)					Ldg					
231109		**VHF COM 2 Ground Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	23 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:23-11-01, MRB Ref:HIRF-34-00-08 (SOURCE: G280 AMM)					Ldg					
231110		**VHF COM 3 Ground Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	23 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:23-11-01, MRB Ref:HIRF-34-00-02 (SOURCE: G280 AMM)					Ldg					
257503		**Electrical Equipment and Installations - Wire Inspection and Separation**							RE	05-20-00 Scheduled Maintenance Checks		
	25 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:20-15-00 (SOURCE: G280 AOMM) (NOTE: See Wire Condition and Separation, 20-15-00, Inspection / Check.)					Ldg					
271002		**Lateral Roll Control System - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	27 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:27-10-00, MRB Ref:27-10-00/01 (SOURCE: G280 AMM)					Ldg					
272123		**Rudder Pedal Assembly - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	27 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:27-21-03, MRB Ref:27-20-00/02 (SOURCE: G280 AMM)					Ldg					
273107		**Elevator Control Cables - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	27 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:27-31-01, MRB Ref:27-30-00/02 (SOURCE: G280 AMM)					Ldg					
276013		**Spoiler Skin - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	27 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:27-60-00, MRB Ref:57.70.00/02 (SOURCE: G280 AMM)					Ldg					
276014		**Spoiler Skin - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	27 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:27-60-00, MRB Ref:57.70.00/02 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280001		**Cross-side Jettison - Operational Check (MRB Ref: 28-30-00-01, Operational Check of the jettison shut-off valve at 8C)**							RE	05-20-00 Scheduled Maintenance Checks		
	28 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:28-20-00, CMR Ref:28-00-01, MRB Ref:28-30-00-01 (SOURCE: G280 AMM) (NOTE: Applies to Aircraft 2001 thru Aircraft 2264.)					Ldg					
281002		**Pressure Relief Valve Seal and Body - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	28 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:28-10-00, MRB Ref:28-10-00/04 (SOURCE: G280 AMM)					Ldg					
281421		**Vent Check Valve - Operational Check**							RE	05-20-00 Scheduled Maintenance Checks		
	28 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:28-14-03, MRB Ref:28-10-00/01 (SOURCE: G280 AMM)					Ldg					
314100		**Integrated Processing Cabinet 1 Ground Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	31 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:31-41-00, MRB Ref:HIRF-22-10-01 (SOURCE: G280 AMM)					Ldg					
314101		**Integrated Processing Cabinet 2 Ground Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	31 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:31-41-00, MRB Ref:HIRF-22-10-02 (SOURCE: G280 AMM)					Ldg					
316003		**Adaptive Flight Display Ground Points (Left and Center) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	31 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:31-60-00, MRB Ref:HIRF-34-10-03 (SOURCE: G280 AMM)					Ldg					
316004		**Adaptive Flight Display Ground Points (Right) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	31 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:31-60-00, MRB Ref:HIRF-34-10-04 (SOURCE: G280 AMM)					Ldg					
341111		**Air Data Computer 1 Ground Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	34 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:31-11-00, MRB Ref:HIRF-34-10-01 (SOURCE: G280 AMM)					Ldg					
341112		**Air Data Computer 2 Ground Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	34 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:31-11-00, MRB Ref:HIRF-34-10-02 (SOURCE: G280 AMM)					Ldg					
341211		**Skin Contour Measurements - Inspection (RVSM requirement.)**							RE	05-20-00 Scheduled Maintenance Checks		
	34 A/F						Mos	02-Mar-2023	96		31-Mar-2031	6.6 Years
							Hrs	34:12				
		ATA Ref:34-12-00 (SOURCE: G280 AMM) (NOTE: RVSM requirement. Aircraft with EIS prior to Revision 15, (see List of Revisions) accomplish at next scheduled 24 month Skin Contour Measurements - Inspection. Results of the skin contour evaluation by Aeromech, Inc. will determine if inspection interval can be extended to every 96 months thereafter or remain at 24 months. Aircraft with EIS on or after Revision 15, accomplish at 96 months from initial accomplishment and every 96 months thereafter.)					Ldg	10					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
341212		**Static Port Flushness and Angularity Requirements - Inspection (RVSM requirement.)**							RE	05-20-00 Scheduled Maintenance Checks		
	34 A/F						Mos	02-Mar-2023	96		31-Mar-2031	6.6 Years
							Hrs	34:12				
		ATA Ref:34-12-02 (SOURCE: G280 AMM)					Ldg	10				
344103		**Radio Altimeter 1 Ground Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	34 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:34-41-00, MRB Ref:HIRF-34-00-07 (SOURCE: G280 AMM)					Ldg					
344104		**Radio Altimeter 2 Ground Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	34 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:34-41-00, MRB Ref:HIRF-34-00-13 (SOURCE: G280 AMM) (NOTE: If installed.)					Ldg					
344402		**Traffic Surveillance System Traffic Alert and Collision Avoidance System Air Traffic Control System Ground Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	34 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:34-44-00, MRB Ref:HIRF-34-00-05 (SOURCE: G280 AMM)					Ldg					
345103		**Global Positioning System 1 Receiver Ground Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	34 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:34-51-00, MRB Ref:HIRF-34-00-06 (SOURCE: G280 AMM)					Ldg					
345104		**Global Positioning System 2 Receiver Ground Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	34 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:34-51-00, MRB Ref:HIRF-34-00-12 (SOURCE: G280 AMM)					Ldg					
345204		**VHF NAV 1 Receiver Ground Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	34 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:34-52-00, MRB Ref:HIRF-34-00-03 (SOURCE: G280 AMM)					Ldg					
345205		**VHF NAV 2 Receiver Ground Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	34 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:34-52-00, MRB Ref:HIRF-34-00-09 (SOURCE: G280 AMM)					Ldg					
345206		**Weather Radar Ground Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	34 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:34-42-00, MRB Ref:HIRF-34-00-14 (SOURCE: G280 AMM)					Ldg					
345303		**Air Traffic Control Transponder Ground Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	34 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:34-53-00, MRB Ref:HIRF-34-00-11 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
345403		**DME 1 Transceiver Ground Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	34 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:34-54-00, MRB Ref:HIRF-34-00-04 (SOURCE: G280 AMM)					Ldg					
345404		**DME 2 Transceiver Ground Points - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	34 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:34-54-00, MRB Ref:HIRF-34-00-10 (SOURCE: G280 AMM)					Ldg					
521104		**Main Entrance Door Including Visible Portions of the Jamb - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	52 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:52-11-01, MRB Ref:52-800-01 (SOURCE: G280 AMM)					Ldg					
521105		**Main Entrance Door Inner Skin - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	52 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:52-11-01, MRB Ref:52.11.01/02 (SOURCE: G280 AMM)					Ldg					
521106		**Main Entrance Door Stops - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	52 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:52-11-01, MRB Ref:52.11.01/03 (SOURCE: G280 AMM)					Ldg					
523111		**Baggage Compartment Door Including Visible Portions of the Jamb - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	52 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:52-31-01, MRB Ref:52-800-03 (SOURCE: G280 AMM)					Ldg					
525111		**Aft Fuselage Service Door Including Visible Portions of the Jamb - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	52 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:52-40-00, MRB Ref:52-800-04 (SOURCE: G280 AMM)					Ldg					
525113		**APU Service Door Including Visible Portions of the Jamb - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	52 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:52-40-00, MRB Ref:52-800-05 (SOURCE: G280 AMM)					Ldg					
530011		**Fuselage Door Section Upper Exterior Skin Under Antennas - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-00-00, MRB Ref:53.21.00/02 (SOURCE: G280 AMM) (NOTE: NOTE: Antennas and all underlying attachments removed.)					Ldg					
530014		**Fuselage Door Section Interior Door Surround - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-00-00, MRB Ref:53.21.00/06 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
530015		**Fuselage Door Section Lower Exterior Under Antennas - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-00-00, MRB Ref:53.21.00/08 (SOURCE: G280 AMM) (NOTE: NOTE: Antennas and all underlying attachments removed.)					Ldg					
530025		**Upper Fuselage Wing / Aft Fairings (Internal) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-00-00, MRB Ref:53-100-15 (SOURCE: G280 AMM)					Ldg					
531102		**Nose Landing Gear Bay - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-12-01, MRB Ref:53.11.00/14 (SOURCE: G280 AMM)					Ldg					
531106		**Nose Avionics Bay Internal - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-11-02, MRB Ref:53-100-03 (SOURCE: G280 AMM)					Ldg					
531110		**Nose Section Lower Exterior Skin Under Antennas - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-11-00, MRB Ref:53.10.00 / 10 (SOURCE: G280 AMM) (NOTE: NOTE: Antennas and all underlying attachments removed. Accomplish at 8C from EIS and every 8C thereafter. Aircraft beyond 72 months from EIS at the date of Revision 19 (see List of Revisions), accomplish at next compliance of Fuselage Door Section Lower Exterior Under Antennas - Detailed Inspection, 53-00-00, Inspection / Check or Code 530015 and at every 8C thereafter.)					Ldg					
531112		**Nose Section Internal, Upper and Lower Portions Including Antenna Penetrations - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-11-00, MRB Ref:53.10.00 / 12 (SOURCE: G280 AMM) (NOTE: NOTE: Initial compliance at 8C from EIS and at every 8C thereafter. Aircraft beyond 72 months from EIS at the date of Revision 19 (see List of Revisions), accomplish at next due compliance of Nose Avionics Bay Internal - Zonal Inspection, 53-11-02, Inspection / Check or Code 531106 and every 8C thereafter.)					Ldg					
531201		**Cockpit Below Floor (Internal) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-12-01, MRB Ref:53-100-05 (SOURCE: G280 AMM)					Ldg					
531202		**Cockpit Below Floor Wiring - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-12-01, MRB Ref:53-100-EZIP-01 (SOURCE: G280 AMM)					Ldg					
531204		**Cockpit Interior Above Floor To Windows - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-12-01, MRB Ref:53-200-04 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
531205		**Cockpit Above Floor Wiring - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-12-01, MRB Ref:53-200-EZIP-01 (SOURCE: G280 AMM)					Ldg					
531217		**Cockpit Window Skin (External) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-12-02, MRB Ref:53.17.00/07 (SOURCE: G280 AMM)					Ldg					
531219		**Cockpit Below Floor Wiring Installations - Cleaning**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-12-01, MRB Ref:53-100-EZIP-02 (SOURCE: G280 AMM)					Ldg					
531250		**Cockpit Lower Exterior Skin Under Antennas - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		MRB Ref:53.11.00 / 15 (SOURCE: G280 AMM) (NOTE: NOTE: Antennas and all underlying attachments removed. Accomplish at 8C from EIS and every 8C thereafter. Aircraft beyond 72 months from EIS at the date of Revision 19 (see List of Revisions), accomplish at next compliance of Fuselage Door Section Lower Exterior Under Antennas - Detailed Inspection, 53-00-00, Inspection / Check or Code 530015 and at every 8C thereafter.)					Ldg					
531304		**Forward Cabin Below Floor Internal - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-13-01, MRB Ref:53-100-07 (SOURCE: G280 AMM)					Ldg					
531308		**Forward Cabin Skin Under Antenna - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-13-01, MRB Ref:53.23.00/02 (SOURCE: G280 AMM) (NOTE: NOTE: Antennas and all underlying attachments removed.)					Ldg					
531310		**Forward Fuselage Floor Structure - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-13-01, MRB Ref:53.23.00/06, MRB Ref:53.23.00/07, MRB Ref:53.23.00/12 (SOURCE: G280 AMM)					Ldg					
531401		**Forward Fuel Tank Internal - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-14-00, MRB Ref:53-100-08 (SOURCE: G280 AMM)					Ldg					
531402		**Forward Fuel Tank Wiring Harness - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-14-00, MRB Ref:53-100-EZIP-04 (SOURCE: G280 AMM)					Ldg					
531403		**Forward Wraparound Fairing (Ahead of Forward Fuel Tank) Internal - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-14-00, MRB Ref:53-100-12 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
531404		**Forward Fuel Tanks Fairings Internal - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-14-00, MRB Ref:53-100-13 (SOURCE: G280 AMM)					Ldg					
531405		**Refuel / Defuel Control Panel Wiring - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-14-00, MRB Ref:53-100-EZIP-05 (SOURCE: G280 AMM)					Ldg					
531406		**Lower Fuselage Bay Between Forward Fuel Tank and Wing - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-14-00, MRB Ref:53-100-14 (SOURCE: G280 AMM)					Ldg					
531407		**Wiring Harness Between Forward Fuel Tank and Wing - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-14-00, MRB Ref:53-100-EZIP-06 (SOURCE: G280 AMM)					Ldg					
531410		**Forward Fuel Tank Internal Surfaces and Structures - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-14-00, MRB Ref:53.30.01/02 (SOURCE: G280 AMM) (NOTE: Accomplish at 8C, from EIS and at every 8C thereafter. Aircraft beyond 90 months at the date of Revision 14 (see List of Revisions), accomplishment may be at next Forward Fuel Tank Internal - Zonal Inspection, 53-14-00, Inspection / Check or Code 531401 and at every 8C thereafter.)					Ldg					
532007		**Door Structure Surround (Interior) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-00-00, MRB Ref:53.21.00/12 (SOURCE: G280 AMM)					Ldg					
532011		**Exterior Upper Skin Under Antennas - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-20-00, MRB Ref:53.25.00/02 (SOURCE: G280 AMM) (NOTE: NOTE: Antennas and all underlying attachments removed.)					Ldg					
532012		**Exterior Skin Under XM Weather Antenna - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-20-00, MRB Ref:53.27.00/02 (SOURCE: G280 AMM) (NOTE: NOTE: Antennas and all underlying attachments removed.)					Ldg					
532015		**Lavatory Waste Duct Area (Interior) Skin - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-20-00, MRB Ref:53.27.00/06 (SOURCE: G280 AMM)					Ldg					
532018		**Lavatory Interior Structure Behind Closeouts - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-20-00, MRB Ref:53.27.00/11 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
532103		**Aft Cabin Below Floor - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-21-01, MRB Ref:53-100-09 (SOURCE: G280 AMM)					Ldg					
532114		**Auxiliary Pressure Bulkhead Above and Below Floor - General Visual Inspection**							RE	05-20-00 - Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-21-02, MRB Ref:53.05.00 / 03 (SOURCE: G280 AMM) (NOTE: NOTE: Accomplish at 8C since entry into service and every 8C thereafter. For aircraft beyond 6C since entry into service at date of revision 16, see list of revisions, accomplish within 24 months following date of revision 16 and every 8C thereafter.)					Ldg					
532117		**Auxiliary Pressure Bulkhead Aft Side Wall - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-21-02, MRB Ref:53.05.00/04 (SOURCE: G280 AMM)					Ldg					
532119		**Auxiliary Pressure Bulkhead Forward Right Side Wall - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-21-02, MRB Ref:53.05.00/06 (SOURCE: G280 AMM)					Ldg					
532125		**Aft Cabin Interior Below WL 12.99 (330 mm) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-21-02, MRB Ref:53.25.00/14, MRB Ref:53.25.00/10, MRB Ref:53.25.00/08 (SOURCE: G280 AMM)					Ldg					
532201		**Baggage Compartment Below Floor - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-22-01, MRB Ref:53-100-11 (SOURCE: G280 AMM)					Ldg					
532202		**Baggage Compartment Above Floor - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-22-01, MRB Ref:53-200-09 (SOURCE: G280 AMM)					Ldg					
532203		**Baggage Compartment Upper Skin Under ELT Antenna - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-22-01, MRB Ref:53.40.02/02 (SOURCE: G280 AMM) (NOTE: NOTE: Antennas and all underlying attachments removed.)					Ldg					
532301		**Aft Fuel Tank Internal - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-23-00, MRB Ref:53-100-18 (SOURCE: G280 AMM)					Ldg					
532302		**Aft Fuel Tank Quantity Wiring Harness - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-23-00, MRB Ref:53-100-EZIP-11 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
532305		**Aft Fuel Tank Internal Surfaces and Structures - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-23-00, MRB Ref:53.30.03/02 (SOURCE: G280 AMM) (NOTE: Accomplish at 8C, from EIS and at every 8C thereafter. Aircraft beyond 90 months at the date of Revision 14 (see List of Revisions), accomplishment may be at next Aft Fuel Tank Internal - Zonal Inspection, 53-23-00, Inspection / Check or Code 532301 and at every 8C thereafter.)					Ldg					
533004		**Exterior Skin Below VHF COMM 3 Antenna - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-30-00, MRB Ref:53.50.01/08 (SOURCE: G280 AMM) (NOTE: NOTE: Antennas and all underlying attachments removed.)					Ldg					
533006		**Aft Pressure Bulkhead Forward and Aft Faces - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-30-00, MRB Ref:53.50.01/15 (SOURCE: G280 AMM)					Ldg					
533101		**APU Enclosure and Tail Cone (Internal) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	53 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:53-31-01, MRB Ref:53-300-03 (SOURCE: G280 AMM)					Ldg					
551119		**Horizontal Stabilizer Internal Box Structure Rib 1 to Rib 4 - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	55 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:55-11-01, MRB Ref:55.11.00/09 (SOURCE: G280 AMM)					Ldg					
551120		**Horizontal Stabilizer Box Structure External Rib 4 - Rib 10 - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	55 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:55-11-01, MRB Ref:55.11.00/10 (SOURCE: G280 AMM)					Ldg					
551122		**Horizontal Stabilizer Rear Spar, Trailing Edge and Elevator (Internal) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	55 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:55-11-01, MRB Ref:55-300-03 (SOURCE: G280 AMM)					Ldg					
551125		**Horizontal Stabilizer Actuator Lower Structural Fitting - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	55 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:55-11-02, MRB Ref:55.02.01/01 (SOURCE: G280 AMM)					Ldg					
551127		**Horizontal Stabilizer Actuator Gimbal and Upper Structural Attachment - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	55 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:55-11-02, MRB Ref:55.02.01/03 (SOURCE: G280 AMM)					Ldg					
551129		**Horizontal Stabilizer Actuator Attachments - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	55 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:55-11-02, MRB Ref:55.02.01/05 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
552003		**Elevator Box Structure (Left) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	55 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:55-20-00, MRB Ref:55.21.00/03 (SOURCE: G280 AMM)					Ldg					
552004		**Elevator Box Structure (Right) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	55 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:55-20-00, MRB Ref:55.21.00/03 (SOURCE: G280 AMM)					Ldg					
553014		**Vertical Stabilizer Box Structure (Internal) - Special Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	55 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:55-30-00, MRB Ref:55.31.00/05 (SOURCE: G280 AMM)					Ldg					
553015		**Vertical Stabilizer (Composite Components) - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	55 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:55-30-00, MRB Ref:55.31.00/06 (SOURCE: G280 AMM)					Ldg					
553102		**Vertical Stabilizer Box (Flight Control Areas) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	55 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:55-31-01, MRB Ref:55-300-05 (SOURCE: G280 AMM)					Ldg					
553104		**Vertical Stabilizer Rear Spar and Rudder Leading Edge (Internal) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	55 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:55-31-01, MRB Ref:55-300-07 (SOURCE: G280 AMM)					Ldg					
554001		**Rudder (External) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	55 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:55-40-00, MRB Ref:55.41.00/02 (SOURCE: G280 AMM)					Ldg					
554003		**Rudder Structure - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	55 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:55-40-00, MRB Ref:55.41.00/04 (SOURCE: G280 AMM)					Ldg					
570005		**Wing Leading Edge (Gap Bands Removed) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-00-00, MRB Ref:57-500-02 (SOURCE: G280 AMM)					Ldg					
570006		**Wing Leading Edge (Gap Bands Removed) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-00-00, MRB Ref:57-500-02 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
570007		**Wing Leading Edge Wiring - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-00-00, MRB Ref:53-500-EZIP-01 (SOURCE: G280 AMM)					Ldg					
570008		**Wing Leading Edge Wiring - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-00-00, MRB Ref:53-500-EZIP-01 (SOURCE: G280 AMM)					Ldg					
570009		**Wing Box FQMS Wiring Installations - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-00-00, MRB Ref:53-500-EZIP-02 (SOURCE: G280 AMM)					Ldg					
570010		**Wing Box FQMS Wiring Installations - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-00-00, MRB Ref:53-500-EZIP-02 (SOURCE: G280 AMM)					Ldg					
570011		**Wing Box (Internal) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-00-00, MRB Ref:57-500-04 (SOURCE: G280 AMM)					Ldg					
570012		**Wing Box (Internal) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-00-00, MRB Ref:57-500-04 (SOURCE: G280 AMM)					Ldg					
570205		**Wing Torsion Box Forward Spar Splices - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-02-00, MRB Ref:57.02.00/03 (SOURCE: G280 AMM)					Ldg					
570206		**Wing Torsion Box Forward Spar Splices - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-02-00, MRB Ref:57.02.00/03 (SOURCE: G280 AMM)					Ldg					
570207		**Wing Torsion Box Aft Spar and Splices - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-02-00, MRB Ref:57.02.00/05 (SOURCE: G280 AMM)					Ldg					
570208		**Wing Torsion Box Aft Spar and Splices - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-02-00, MRB Ref:57.02.00/05 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
570209		**Wing Fuel Tank (Internal) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-02-00, MRB Ref:57.02.00/08, MRB Ref:57.02.00/09, MRB Ref:57.02.00/10 (SOURCE: G280 AMM)					Ldg					
570210		**Wing Fuel Tank (Internal) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-02-00, MRB Ref:57.02.00/08, MRB Ref:57.02.00/09, MRB Ref:57.02.00/10 (SOURCE: G280 AMM)					Ldg					
571601		**Wing to Fuselage Supports - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-16-00, MRB Ref:57.02.00/12 (SOURCE: G280 AMM)					Ldg					
571602		**Wing to Fuselage Supports - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-16-00, MRB Ref:57.02.00/12 (SOURCE: G280 AMM)					Ldg					
573105		**Winglet Assembly and Winglet Leading Edge Skin - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-31-01, MRB Ref:57.15.00/04 (SOURCE: G280 AMM)					Ldg					
573106		**Winglet Assembly and Winglet Leading Edge Skin - General Visual Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-31-01, MRB Ref:57.15.00/04 (SOURCE: G280 AMM)					Ldg					
574001		**Wing Inboard Leading Edge (Internal) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-40-00, MRB Ref:57.40.00/01 (SOURCE: G280 AMM)					Ldg					
574002		**Wing Inboard Leading Edge (Internal) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-40-00, MRB Ref:57.40.00/01 (SOURCE: G280 AMM)					Ldg					
575101		**Sponson and Main Landing Gear Door Hinge Support - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-51-00, MRB Ref:57.14.00/01 (SOURCE: G280 AMM)					Ldg					
575102		**Sponson and Main Landing Gear Door Hinge Support - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
	57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
							Hrs					
		ATA Ref:57-51-00, MRB Ref:57.14.00/01 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
576001	**Aileron Push Pull Rod Tunnel (Internal) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
						Hrs					
	ATA Ref:57-60-00, MRB Ref:57.02.00/11 (SOURCE: G280 AMM)					Ldg					
576002	**Aileron Push Pull Rod Tunnel (Internal) - Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		
57 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
						Hrs					
	ATA Ref:57-60-00, MRB Ref:57.02.00/11 (SOURCE: G280 AMM)					Ldg					
▼ 1. RE 96 Mos, 4000 Hrs											
281001	**Positive / Negative Relief Valve - Operational Check (**CMR)**							RE	05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks		**≈06-Oct-2028**
28 A/F						Mos	02-Mar-2023	96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
						Hrs	34:12	4,000	-/+50	4009:48	2951:48 Hrs (+50)
	ATA Ref:28-10-00, CMR Ref:28-00-02 (Manual Adjustment: 20d, -24.4 Hrs) (SOURCE: G280 AMM)					Ldg	10				
281431	**Flame Arrestor - Detailed Inspection (**CMR)**							RE	05-10-10 CMR, 05-20-00 Scheduled Maintenance Checks		**≈01-Oct-2028**
28 A/F						Mos		96	-/+1m	31-Mar-2031	6.6 Years (+30 Days)
						Hrs		4,000	-/+50	4000	2942 Hrs (+50)
	ATA Ref:28-14-00, CMR Ref:28-00-03 (SOURCE: G280 AMM) (NOTE: Accomplish at 4000 flight hours or 8C, whichever occurs first. (1) Task satisfies the Fuel System Airworthiness Limitations Inspections requirement.)					Ldg					
▼ 1. RE 96 Mos, 500 Hrs											
530003	**Nose Landing Gear Wheel Well (Internal) - Zonal Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈09-Apr-2025**
53 A/F						Mos	26-Jul-2024	96	-/+1m	31-Jul-2032	7.9 Years (+31 Days)
						Hrs	967:25	500	-/+50	1500	442 Hrs (+50)
	ATA Ref:53-00-00, MRB Ref:53-100-04 (Tol. Adjustment: 32.6 Hrs) (SOURCE: G280 AMM) (NOTE: Accomplish at 1A or 8C, whichever occurs first. Aircraft beyond 6C from EIS, without a prior compliance or 6C from last compliance at date of Revision 16 (see List of Revisions), accomplish at 1A or 24 months from EIS or last compliance as applicable and every 1A or 8C, whichever occurs first thereafter.)					Ldg	562				
▼ 1. RE 9600 Hrs											
723014	**Engine Compressor Section - Special Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈30-Jul-2036**
72 ENG1						Mos					
						Hrs		9,600	-/+50	9600	8566:24 Hrs (+50)
	ATA Ref:72-30-00, MRB Ref:72-30-00-02 (SOURCE: G280 AMM)					Enc					
723014	**Engine Compressor Section - Special Detailed Inspection**							RE	05-20-00 Scheduled Maintenance Checks		**≈20-Jul-2036**
72 ENG2						Mos					
						Hrs		9,600	-/+50	9600	8546:24 Hrs (+50)
	ATA Ref:72-30-00, MRB Ref:72-30-00-02 (SOURCE: G280 AMM)					Enc					
▼ 1. RE A/R											
05-50-00-01	**Lightning Strike - Inspection**							RE (A/R)	05-50-00 Special Inspections After Specific Occurrence		
5 A/F						Mos					
						Hrs					
	AMM Ref:05-50-00 (SOURCE: G280 AMM)					Ldg					
05-50-00-02	**Hard / Overweight Landing - Inspection**							RE (A/R)	05-50-00 Special Inspections After Specific Occurrence		
5 A/F						Mos					
						Hrs					
	AMM Ref:05-50-00 (SOURCE: G280 AMM)					Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
05-50-00-03	**High Energy Stop on Landing or Takeoff - Inspection**							RE (A/R)	05-50-00	Special Inspections After Specific Occurrence	
5 A/F						Mos					
						Hrs					
AMM Ref:05-50-00 (SOURCE: G280 AMM)						Ldg					
05-50-00-04	**Bird Strike - Inspection**							RE (A/R)	05-50-00	Special Inspections After Specific Occurrence	
5 A/F						Mos					
						Hrs					
AMM Ref:05-50-00 (SOURCE: G280 AMM)						Ldg					
05-50-00-05	**Severe Turbulence / Maneuver - Inspection**							RE (A/R)	05-50-00	Special Inspections After Specific Occurrence	
5 A/F						Mos					
						Hrs					
AMM Ref:05-50-00 (SOURCE: G280 AMM)						Ldg					
05-50-00-06	**Exceeding Design Speed - Inspection**							RE (A/R)	05-50-00	Special Inspections After Specific Occurrence	
5 A/F						Mos					
						Hrs					
AMM Ref:05-50-00 (SOURCE: G280 AMM)						Ldg					
05-50-00-07	**Landing Gear Airspeed Exceedance - Inspection**							RE (A/R)	05-50-00	Special Inspections After Specific Occurrence	
5 A/F						Mos					
						Hrs					
(SOURCE: G280 AMM)						Ldg					
05-50-00-08	**Flap Airspeed Exceedances - Inspection**							RE (A/R)	05-50-00	Special Inspections After Specific Occurrence	
5 A/F						Mos					
						Hrs					
(SOURCE: G280 AMM)						Ldg					
05-50-00-09	**High Velocity Ground Gusts - Inspection**							RE (A/R)	05-50-00	Special Inspections After Specific Occurrence	
5 A/F						Mos					
						Hrs					
AMM Ref:05-50-00 (SOURCE: G280 AMM)						Ldg					
05-50-00-10	**Hail Damage to Aircraft / Engine - Inspection**							RE (A/R)	05-50-00	Special Inspections After Specific Occurrence	
5 A/F						Mos					
						Hrs					
AMM Ref:05-50-00 (SOURCE: G280 AMM)						Ldg					
05-50-00-11	**APU Fire - Inspection**							RE (A/R)	05-50-00	Special Inspections After Specific Occurrence	
5 A/F						Mos					
						Hrs					
AMM Ref:05-50-00 (SOURCE: G280 AMM)						Ldg					
05-50-00-12	**Engine After In-Flight Shutdown - Detailed Inspection**							RE (A/R)	05-50-00	Special Inspections After Specific Occurrence	
5 A/F						Mos					
						Hrs					
AMM Ref:05-50-00 (SOURCE: G280 AMM)						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
05-50-00-13	**Residual Anti-Icing / De-Icing Fluid - Inspection**						RE (A/R)	05-50-00	Special Inspections After Specific Occurrence	
5 A/F						Mos				
						Hrs				
AMM Ref:05-50-00 (SOURCE: G280 AMM)						Ldg				
05-50-00-14	**Engine Fire Extinguisher Discharge - Follow Up Requirements**						RE (A/R)	05-50-00	Special Inspections After Specific Occurrence	
5 A/F						Mos				
						Hrs				
AMM Ref:05-50-00 (SOURCE: G280 AMM)						Ldg				
10-10-00(1)-001	**Flight Ready Storage - 7 Day Inspection**						RE (A/R)			
10 A/F						Mos				
						Hrs				
						Ldg				
10-10-00(1)-002	**Flight Ready Storage - 15 Day Inspection**						RE (A/R)			
10 A/F						Mos				
						Hrs				
						Ldg				
10-10-00(1)-003	**Flight Ready Storage - 30 Day Inspection**						RE (A/R)			
10 A/F						Mos				
						Hrs				
						Ldg				
10-10-00(1)-004	**Flight Ready Storage - 60 Day Inspection**						RE (A/R)			
10 A/F						Mos				
						Hrs				
						Ldg				
10-10-00(2)-001	**Short Term Storage - 7 Day Inspection**						RE (A/R)			
10 A/F						Mos				
						Hrs				
						Ldg				
10-10-00(2)-002	**Short Term Storage - 15 Day Inspection**						RE (A/R)			
10 A/F						Mos				
						Hrs				
						Ldg				
10-10-00(2)-003	**Short Term Storage - 30 Day Inspection**						RE (A/R)			
10 A/F						Mos				
						Hrs				
						Ldg				
10-10-00(2)-004	**Short Term Storage - 60 Day Inspection**						RE (A/R)			
10 A/F						Mos				
						Hrs				
						Ldg				
10-10-00(3)-001	**Long Term Storage - 7 Day Inspection**						RE (A/R)			
10 A/F						Mos				
						Hrs				
						Ldg				
10-10-00(3)-002	**Long Term Storage - 15 Day Inspection**						RE (A/R)			
10 A/F						Mos				
						Hrs				
						Ldg				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
10-10-00(3)-003	**Long Term Storage - 30 Day Inspection**							RE (A/R)			
10 A/F						Mos					
						Hrs					
						Ldg					
10-10-00(3)-004	**Long Term Storage - 60 Day Inspection**							RE (A/R)			
10 A/F						Mos					
						Hrs					
						Ldg					
10-10-00-001	**Aircraft Storage - 90 Day Periodic Inspections - Flight Controls**							RE (A/R)			
10 A/F						Mos					
						Hrs					
						Ldg					
200091	**Pre Maintenance - Checklist**							RE (A/R)			
20 A/F						Mos	04-Mar-2023				
						Hrs	35:48				
						Ldg	11				
200092	**Post Maintenance - Checklist**							RE (A/R)			
20 A/F						Mos	05-Mar-2023				
						Hrs	35:48				
						Ldg	11				
280-24-207	**Electrical Power - Emergency Battery System - Impact Switch Installation Modification**							RE (A/R)		Recommended	
24 A/F						Mos	10-Feb-2023				
Eff: 18-Mar-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
280017	**Fuel Tank - Sumping (Optional)**							RE (A/R)			
28 A/F						Days	02-Mar-2023				
						Hrs	34:12				
						Ldg	10				
317050	**Quick Access Recorder (QAR) Download**							RE (A/R)			
31 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
						Ldg	10				
280-53-117	**Fuselage - Forward Fuselage - Potable Water Line Routing Modification (MODG25- 00580)**							RE (A/R)		Recommended	
53 A/F						Mos	10-Feb-2023				
Eff: 30-Oct-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
▼ 1. RE APU Removal											
492201	**APU Compressor Inlet Housing - General Visual Inspection**							RE (APU Removal)	05-20-00 Scheduled Maintenance Checks		
49 A/F						Mos					
						Hrs					
ATA Ref:49-22-00, MRB Ref:49-21-00/01 (SOURCE: G280 AMM) (NOTE: Perform at APU removal from airframe.)						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 1. RE Due												
233803		**Cabin Processor Unit Lithium Battery - Discard**							RE (Due)		05-10-00 Time Limits	
23 A/F							Mos	10-Feb-2023			01-Jan-2027	2.3 Years
CR2032							Hrs	24:24				
NSN							Ldg	7				
Expiration Date 01-Jan-2027												
		ATA Ref:23-38-00 (SOURCE: G280 AOMM) (NOTE: Accomplish battery discard in accordance with battery expiration date placard on CPU. This item applies to CPU part number CPU-01-004, if installed.)										
251031		**Defibrillator Electrode Pad - Scrap**							RE (Due)		ICA	
25 A/F		No.1					Mos	20-Nov-2022			28-Feb-2028	3.5 Years
710095							Hrs	0				
Unknown							Ldg	0				
Expiration Date 28-Feb-2028												
		(SOURCE: Cabin Interior ICA)										
251034		**Defibrillator Battery - Scrap**							RE (Due)		ICA	
25 A/F		No.1					Mos	20-Nov-2022			28-Feb-2027	2.5 Years
710094							Hrs	0				
02377P							Ldg	0				
Expiration Date 28-Feb-2027												
		(SOURCE: Cabin Interior ICA)										
256105		**Emergency Locator Transmitter Battery - Discard**							RE (Due)		05-10-00 Time Limits	
25 A/F						0	Mos				31-Jan-2027	2.4 Years
452-0133						0	Hrs					
393042-030						0	Ldg					
Expiration Date 31-Jan-2027												
		ATA Ref:25-61-01, MRB Ref:25-60-00/05 (SOURCE: G280 AMM) (NOTE: Per battery expiration date label)										
256139		**Emergency Locator Transmitter Battery (Life Raft) - Scrap**							RE (Due)			
25 A/F		No.1				0	Mos	18-Feb-2023			01-Dec-2029	5.2 Years
500-32-2Y-HA							Hrs	28				
13905							Ldg	8				
Expiration Date 01-Dec-2029												
256141		**Emergency Locator Transmitter Battery (Life Raft) - Scrap**							RE (Due)			
25 A/F		No.3					Mos	18-Feb-2023			01-Dec-2029	5.2 Years
500-32-2Y-HA							Hrs	28				
13916							Ldg	8				
Expiration Date 01-Dec-2029												
256403		**First Aid Kit Time Limited Supplies - Discard**							RE (Due)		05-10-00 Time Limits	
25 A/F							Mos	19-Mar-2024			30-Jun-2025	9.8 Months
502950							Hrs					
020223004							Ldg					
Expiration Date 30-Jun-2025												
		(SOURCE: G280 AOMM) (NOTE: Discard by date of expiration. This item applies if installed.)										
258000		**Aircraft Re-registration (FAA Rule)**							RE (Due)			
25 A/F							Mos				30-Nov-2025	1.2 Years
Expiration Date 20-Nov-2025							Hrs					
							Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
313128		**Underwater Locator Beacon Battery - Discard**							RE (Due)		05-10-00 Time Limits	
31 A/F	DK290-11 JM005679	No.2					Mos Hrs Ldg	04-Jun-2024 866:28 501			31-May-2029	4.7 Years
		Expiration Date 31-May-2029 ATA Ref:31-31-05, MRB Ref:31-31-00-02 (SOURCE: G280 AMM) (NOTE: In accordance with battery expiration date stamped on ULB label. Note (1) Battery replacement is required on or before date printed on battery replacement date label on outside of the beacon case.)										
▼ 1. RE Engine Removal												
545001		**Firewall (External) - General Visual Inspection**						RE (Engine Removal)			05-20-00 Scheduled Maintenance Checks	
54 A/F							Mos Hrs Ldg	02-Mar-2023 34:12 10				
		ATA Ref:54-50-00, MRB Ref:54.51.00/04 (SOURCE: G280 AMM)										
545002		**Firewall (External) - General Visual Inspection**						RE (Engine Removal)			05-20-00 Scheduled Maintenance Checks	
54 A/F							Mos Hrs Ldg	02-Mar-2023 34:12 10				
		ATA Ref:54-50-00, MRB Ref:54.51.00/04 (SOURCE: G280 AMM)										
▼ 1. RE N/A												
233601		**Advanced Cabin Server - Restore**							RE (N/A)		05-10-00 Time Limits	
23 A/F							Mos Hrs Ldg					
		ATA Ref:23-29-00 (SOURCE: G280 AOMM)										
233801		**Cabin Processor Unit - Restore (AEIS P/N: CPU-01-001)**							RE (N/A)		05-10-00 Time Limits	
23 A/F	CPU-01-004 00317						Mos Hrs Ldg					
		ATA Ref:23-38-00 (SOURCE: G280 AOMM)										
243503		**Emergency Power Supply (XL246-C) - Discard**							RE (N/A)			
24 A/F	100-0202-03 1211798					10 21:06 5	Mos Hrs Ldg	19-Jan-2023 22:54 6				
256219		**Life Vest - Restore**							RE (N/A)		05-10-00 Time Limits	
25 A/F	Unknown Unknown	Left No.5					Mos Hrs Ldg					
		ATA Ref::25-61-01 (SOURCE: G280 AOMM)										
256220		**Life Vest - Restore**							RE (N/A)		05-10-00 Time Limits	
25 A/F	Unknown Unknown	Right No.5					Mos Hrs Ldg					
		ATA Ref::25-61-01 (SOURCE: G280 AOMM)										
256224		**Life Vest - Restore**							RE (N/A)		05-10-00 Time Limits	
25 A/F	Unknown Unknown	Aft Lavatory					Mos Hrs Ldg					
		ATA Ref::25-61-01 (SOURCE: G280 AOMM)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
256225		**Conference Group Life Vest (Aft Facing) - Restore**							RE (N/A)		05-10-00 Time Limits	
	25 A/F	Outboard					Mos					
	63600-105						Hrs					
	L5530662						Ldg					
	ATA Ref::25-61-01 (SOURCE: G280 AOMM)											
256226		**Conference Group Life Vest (Aft Facing) - Restore**							RE (N/A)		05-10-00 Time Limits	
	25 A/F	Inboard					Mos					
	63600-105						Hrs					
	L5530661						Ldg					
	ATA Ref::25-61-01 (SOURCE: G280 AOMM)											
256227		**Conference Group Life Vest (Fwd Facing) - Restore**							RE (N/A)		05-10-00 Time Limits	
	25 A/F	Outboard					Mos					
	63600-105						Hrs					
	L5611821						Ldg					
	ATA Ref::25-61-01 (SOURCE: G280 AOMM)											
256228		**Conference Group Life Vest (Fwd Facing) - Restore**							RE (N/A)		05-10-00 Time Limits	
	25 A/F	Inboard					Mos					
	63600-105						Hrs					
	L5530668						Ldg					
	ATA Ref::25-61-01 (SOURCE: G280 AOMM)											
256407		**Emergency Medical Kit Time Limited Supplies - Discard**							RE (N/A)		05-10-00 Time Limits	
	25 A/F						Mos					
	Unknown						Hrs					
	Unknown						Ldg					
	(SOURCE: G280 AOMM)											
256408		**Emergency Medical Kit - Detailed Inspection (do not open if sealed)**							RE (N/A)	05-20-00	Scheduled Maintenance Checks	
	25 A/F						Mos					
	Unknown						Hrs					
	Unknown						Ldg					
	ATA Ref:25-64-01 (SOURCE: G280 AOMM)											
256435		**Defibrillator Time Limited Supplies - Discard**							RE (N/A)		05-10-00 Time Limits	
	25 A/F						Mos					
							Hrs					
	(SOURCE: G280 AOMM)						Ldg					
256608		**Protective Breathing Equipment (PBE) - Discard**							RE (N/A)		05-10-00 Time Limits	
	25 A/F						Mos					
							Hrs					
	(SOURCE: G280 AOMM)						Ldg					
262404		**Portable Fire Extinguisher - (Hydrostatic) Functional Check**							RE (N/A)		05-10-00 Time Limits	
	26 A/F	Cockpit					Mos	02-Mar-2023				
	347TS						Hrs	34:12				
	G-98646801						Ldg	10				
	ATA Ref:26-24-00 (SOURCE: G280 AOMM)											
262414		**Portable Fire Extinguisher - (Hydrostatic) Functional Check**							RE (N/A)		05-10-00 Time Limits	
	26 A/F	Fwd Cabin					Mos	02-Mar-2023				
	349TS						Hrs	34:12				
	H-11788969						Ldg	10				
	ATA Ref:26-24-00 (SOURCE: G280 AOMM)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
262424		**Portable Fire Extinguisher - (Hydrostatic) Functional Check**							RE (N/A)		05-10-00 Time Limits	
26 A/F		Aft Cabin					Mos	02-Mar-2023				
351							Hrs	34:12				
H-21682620							Ldg	10				
ATA Ref:26-24-00 (SOURCE: G280 AOMM)												
274118		**Horizontal Stabilizer Trim Actuator No - Back Operational Check**							RE (N/A)		05-10-10	
27 A/F							Mos					
							Hrs					
Ref:AWL-3 (SOURCE: G280 AMM)							Ldg					
313117		**Underwater Locator Beacon Battery - Discard**							RE (N/A)		05-10-00 Time Limits	
31 A/F		No.1					Mos	01-Jun-2024			31-Jan-2029	4.4 Years
DK290-11							Hrs	848:22				
JM004064							Ldg	497				
Expiration Date 31-Jan-2029												
ATA Ref:31-31-05, MRB Ref:31-31-00-02 (SOURCE: G280 AMM) (NOTE: In accordance with battery expiration date stamped on ULB label. Note (1) Battery replacement is required on or before date printed on battery replacement date label on outside of the beacon case.)												
323405		**Landing Gear Blowdown Bottle - Discard**							RE (N/A)		05-10-00 Time Limits	
32 A/F							Mos					
41004664							Hrs					
E4356D1							Ldg					
ATA Ref:32-34-01, MRB Ref:MSI 32-30-00-12 (SOURCE: G280 AMM)												
335001		**Battery Capacitance (Marathon Batteries) - Functional Check**							RE (N/A)		05-20-00 Scheduled Maintenance Checks	
33 A/F							Mos					
							Hrs					
ATA Ref:33-50-00, MRB Ref:33-50-00/02 (SOURCE: G280 AMM)							Ldg					
346025		**FMS NAV Database - Update**							RE (N/A)			
34 A/F							Mos	01-Mar-2023				
22-Mar-2023							Hrs	34:12				
							Ldg	10				
353001		**Portable Oxygen Mask - Detailed Inspection**							RE (N/A)		05-20-00 Scheduled Maintenance Checks	
35 A/F							Mos					
							Hrs					
ATA Ref:35-30-00, MRB Ref:35-30-00/04 (SOURCE: G280 AMM)							Ldg					
353104		**Portable Oxygen Cylinder - Operational Check**							RE (N/A)		05-20-00 Scheduled Maintenance Checks	
35 A/F							Mos					
							Hrs					
ATA Ref:35-31-01, MRB Ref:35-30-00/03 (SOURCE: G280 AMM)							Ldg					
353105		**Portable Oxygen Cylinder Pressure Gage - Visual Inspection**							RE (N/A)		05-20-00 Scheduled Maintenance Checks	
35 A/F							Mos					
							Hrs					
ATA Ref:35-31-01, MRB Ref:35-30-00/01 (SOURCE: G280 AMM)							Ldg					
CE-CSB-2007		**Cabin Service Bulletins (ATA 44) GCMS Cabin System Firmware Update**							RE (N/A)		Recommended	
44 A/F							Mos	19-Apr-2023				
Eff: 07-Dec-2017 Not Applicable		before aircraft manufacture					Hrs	124:16				
							Ldg	71				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
570241		**Stringer 3 Aft Skin at Fuel Partition Brackets CP9 Stinger 3 Aft Skin at Fuel Partition Brackets - Visual Inspection - [Visual]**							RE (N/A)		05-10-10 Airworthiness Limitations	
		57 A/F					Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W5.3) (SOURCE: G280 AMM)					Ldg					
570242		**Stringer 3 Aft Skin at Fuel Partition Brackets CP9 Stinger 3 Aft Skin at Fuel Partition Brackets - Visual Inspection - [Visual]**							RE (N/A)		05-10-10 Airworthiness Limitations	
		57 A/F					Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W5.3) (SOURCE: G280 AMM)					Ldg					
575011		**Flap Track B and C Roller Fitting CP21, CP22 Flap Track B and C Roller Fitting - NDT Inspection - [HFEC]**							RE (N/A)		05-10-10 Airworthiness Limitations	
		57 A/F					Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W10.7, W11.8) (SOURCE: G280 AMM) (NOTE: Applies to Aircraft Pre-Mod G25-20725 having the following flap assembly part numbers: • 30P191000002-501 / -502 • 30P191000003-501 / -502 • 30P191000004-501 / -502 • 30P191000005-501 / -502 • 30P191000006-501 / -502 • 30P191000007-501 / -502 • 30P191000008-501 / -502 • 30P191000009-501 / -502 • 30P191000010-501 / -502 • 30P191000011-501 / -502)					Ldg					
575012		**Flap Track B and C Roller Fitting CP21, CP22 Flap Track B and C Roller Fitting - NDT Inspection - [HFEC]**							RE (N/A)		05-10-10 Airworthiness Limitations	
		57 A/F					Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W10.7, W11.8) (SOURCE: G280 AMM) (NOTE: Applies to Aircraft Pre-Mod G25-20725 having the following flap assembly part numbers: • 30P191000002-501 / -502 • 30P191000003-501 / -502 • 30P191000004-501 / -502 • 30P191000005-501 / -502 • 30P191000006-501 / -502 • 30P191000007-501 / -502 • 30P191000008-501 / -502 • 30P191000009-501 / -502 • 30P191000010-501 / -502 • 30P191000011-501 / -502)					Ldg					
575029		**Flap Track D Roller Fittings CP23 Flap Track D Roller Fittings - NDT Inspection - [BHEC / HFEC]**							RE (N/A)		05-10-10 Airworthiness Limitations	
		57 A/F					Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W12.6, W12.7) (SOURCE: G280 AMM)					Ldg					
575030		**Flap Track D Roller Fittings CP23 Flap Track D Roller Fittings - NDT Inspection - [BHEC / HFEC]**							RE (N/A)		05-10-10 Airworthiness Limitations	
		57 A/F					Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W12.6, W12.7) (SOURCE: G280 AMM)					Ldg					
575031		**Spoiler No. 1 Upper Skin Center Lug CP25 Spoiler No. 1 Upper Skin Center Lug Radius - NDT Inspection - [HFEC]**							RE (N/A)		05-10-10 Airworthiness Limitations	
		57 A/F					Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W14.1) (SOURCE: G280 AMM)					Ldg					
575032		**Spoiler No. 1 Upper Skin Center Lug CP25 Spoiler No. 1 Upper Skin Center Lug Radius - NDT Inspection - [HFEC]**							RE (N/A)		05-10-10 Airworthiness Limitations	
		57 A/F					Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W14.1) (SOURCE: G280 AMM)					Ldg					
575033		**Flap Track A Roller Fitting CP20 Flap Track A Roller Fittings (Left) - NDT Inspection - [BHEC / HFEC]**							RE (N/A)		05-10-10 Airworthiness Limitations	
		57 A/F					Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W9.6, W9.7) (SOURCE: G280 AMM)					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
575034		**Flap Track A Roller Fitting CP20 Flap Track A Roller Fittings (Right) - NDT Inspection - [BHEC / HFEC]**							RE (N/A)		05-10-10 Airworthiness Limitations	
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W9.6, W9.7) (SOURCE: G280 AMM)					Ldg					
760010		**ECU PN 2119576-3002 and 2119576-3102 (DUAL CHANNEL - CHANNEL A) - Detailed Inspection**							RE (N/A)		LMM 05-20-00 Periodic Inspections	
	76 ENG1						Mos					
							Hrs					
		ATA Ref:76-10-05 (SOURCE: AS907-2-1G LMM (72-05-16)) (NOTE: Note: Periodic Insp at 4,800 Eng HRS allowed for an ENG in compliance with SB AS907-76-9021R1,AS907-72-9001R2, and sub FAA approved revisions, as applicable. ENG that are PRE SB 72-9001 R2/76-9021 R2, req. is 4000 engine hours.)					Enc					
760010		**ECU PN 2119576-3002 and 2119576-3102 (DUAL CHANNEL - CHANNEL A) - Detailed Inspection**							RE (N/A)		LMM 05-20-00 Periodic Inspections	
	76 ENG2						Mos					
							Hrs					
		ATA Ref:76-10-05 (SOURCE: AS907-2-1G LMM (72-05-16)) (NOTE: Note: Periodic Insp at 4,800 Eng HRS allowed for an ENG in compliance with SB AS907-76-9021R1,AS907-72-9001R2, and sub FAA approved revisions, as applicable. ENG that are PRE SB 72-9001 R2/76-9021 R2, req. is 4000 engine hours.)					Enc					
760011		**ECU PN 2119576-3002 and 2119576-3102 (DUAL CHANNEL - CHANNEL B) - Detailed Inspection**							RE (N/A)		LMM 05-20-00 Periodic Inspections	
	76 ENG1						Mos					
							Hrs					
		ATA Ref:76-10-05 (SOURCE: AS907-2-1G LMM (72-05-16)) (NOTE: Note: Periodic Insp at 4,800 Eng HRS allowed for an ENG in compliance with SB AS907-76-9021R1,AS907-72-9001R2, and sub FAA approved revisions, as applicable. ENG that are PRE SB 72-9001 R2/76-9021 R2, req. is 4000 engine hours.)					Enc					
760011		**ECU PN 2119576-3002 and 2119576-3102 (DUAL CHANNEL - CHANNEL B) - Detailed Inspection**							RE (N/A)		LMM 05-20-00 Periodic Inspections	
	76 ENG2						Mos					
							Hrs					
		ATA Ref:76-10-05 (SOURCE: AS907-2-1G LMM (72-05-16)) (NOTE: Note: Periodic Insp at 4,800 Eng HRS allowed for an ENG in compliance with SB AS907-76-9021R1,AS907-72-9001R2, and sub FAA approved revisions, as applicable. ENG that are PRE SB 72-9001 R2/76-9021 R2, req. is 4000 engine hours.)					Enc					
▼ 1. RE O/C												
111000		**Exterior Paint 1**							RE (O/C)			
	11 A/F						Mos	11-Jan-2023				
	Unknown						Hrs	22:54				
	Unknown						Ldg	6				
111001		**Exterior Paint 2**							RE (O/C)			
	11 A/F						Mos	11-Jan-2023				
	Unknown						Hrs	22:54				
	Unknown						Ldg	6				
111002		**Exterior Paint 3**							RE (O/C)			
	11 A/F						Mos	11-Jan-2023				
	Unknown						Hrs	22:54				
	Unknown						Ldg	6				
111003		**Exterior Paint 4**							RE (O/C)			
	11 A/F						Mos	11-Jan-2023				
	Unknown						Hrs	22:54				
	Unknown						Ldg	6				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
111004		**Exterior Paint 5**							RE (O/C)			
	11 A/F						Mos	11-Jan-2023				
	Unknown						Hrs	22:54				
	Unknown						Ldg	6				
210008		**Air Management System Controller - Removal / Installation**							RE (O/C)			
	21 A/F		0				Mos	20-Nov-2022				
	1153462-4 SERIES 1	New	0				Hrs	0				
	1153462-00526		0				Ldg	0				
	Mfg#:21-00-01											
212102		**Pack Inlet Valve - Removal / Installation**							RE (O/C)			
	21 A/F		0				Mos	20-Nov-2022				
	3291936-1	New	0				Hrs	0				
	373		0				Ldg	0				
	Mfg#:21-21-01											
212106		**Service Pressure Regulator - Removal / Installation**							RE (O/C)			
	21 A/F		0				Mos	20-Nov-2022				
	3215650-1	New	0				Hrs	0				
	779		0				Ldg	0				
	Mfg#:21-21-02											
212112		**Defog Valve - Removal / Installation**							RE (O/C)			
	21 A/F		0				Mos	20-Nov-2022				
	329045	New	0				Hrs	0				
	0661		0				Ldg	0				
	Mfg#:21-21-03											
212116		**Foot Warmer Valve - Removal / Installation**							RE (O/C)			
	21 A/F		0				Mos	20-Nov-2022				
	327985	New	0				Hrs	0				
	0657		0				Ldg	0				
	Mfg#:21-21-04											
212122		**Ram Air Check Valve - Removal / Installation**							RE (O/C)			
	21 A/F		0				Mos	20-Nov-2022				
	3202770-1	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:21-21-05-RI											
212127		**Cabin Air Check Valve - Removal / Installation**							RE (O/C)			
	21 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:21-21-05-RI											
212128		**Cabin Air Check Valve - Removal / Installation**							RE (O/C)			
	21 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:21-21-05-RI											
212130		**Cockpit Air Check Valve - Removal / Installation**							RE (O/C)			
	21 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:21-21-05-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
212133		**Gasper Air Check Valve - Removal / Installation**							RE (O/C)			
21 A/F		Left					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
	Mfg#:21-21-05-RI											
212134		**Gasper Air Check Valve - Removal / Installation**							RE (O/C)			
21 A/F		Right					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
	Mfg#:21-21-05-RI											
212137		**Pack Inlet Check Valve - Removal / Installation**							RE (O/C)			
21 A/F		Left	0				Mos	20-Nov-2022				
3202764-2		New	0				Hrs	0				
NSN			0				Ldg	0				
	Mfg#:21-21-05-RI											
212138		**Pack Inlet Check Valve - Removal / Installation**							RE (O/C)			
21 A/F		Right	0				Mos	20-Nov-2022				
3202764-2		New	0				Hrs	0				
NSN			0				Ldg	0				
	Mfg#:21-21-05-RI											
212140		**Flow Control Venturi - Removal / Installation**							RE (O/C)			
21 A/F			0				Mos	20-Nov-2022				
396708-1		New	0				Hrs	0				
361			0				Ldg	0				
	Mfg#:21-21-06											
212142		**Flow Control Venturi Differential Pressure Sensor - Removal / Installation**							RE (O/C)			
21 A/F			0				Mos	20-Nov-2022				
1153442-1		New	0				Hrs	0				
1153442-00849			0				Ldg	0				
	Mfg#:21-21-06											
213106		**Cabin Pressure Controller - Removal / Installation**							RE (O/C)			
21 A/F			0				Mos	20-Nov-2022				
2119312-1		New	0				Hrs	0				
2119312-00270			0				Ldg	0				
	Mfg#:21-31-01											
213112		**Safety Valve - Removal / Installation**							RE (O/C)			
21 A/F			0				Mos	20-Nov-2022				
103926-2		New	0				Hrs	0				
103926-00281			0				Ldg	0				
	Mfg#:21-31-02											
213116		**Outflow Valve - Removal / Installation**							RE (O/C)			
21 A/F			0				Mos	20-Nov-2022				
4222366-1003		New	0				Hrs	0				
01034			0				Ldg	0				
	Mfg#:21-31-03											
213122		**Baggage Compartment Differential Pressure Switch - Removal / Installation**							RE (O/C)			
21 A/F			0				Mos	20-Nov-2022				
55723-3234		New	0				Hrs	0				
0270			0				Ldg	0				
	Mfg#:21-31-04											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
213124		**Barometric Pressure Switch - Removal / Installation**							RE (O/C)			
	21 A/F		0				Mos	10-Feb-2023				
	GBC300-164	New	0				Hrs	24:24				
	2207226		0				Ldg	7				
213204		**Alternate Air Pressure Regulating Shutoff Valve - Removal / Installation**							RE (O/C)			
	21 A/F		0				Mos	20-Nov-2022				
	424255	New	0				Hrs	0				
	0260		0				Ldg	0				
	Mfg#:21-32-01											
213208		**Alernate Air Heat Exchanger - Removal / Installation**							RE (O/C)			
	21 A/F		0				Mos	20-Nov-2022				
	8221-1	New	0				Hrs	0				
	T0494		0				Ldg	0				
	Mfg#:21-32-02											
213212		**Alternate Air Check Valve - Removal / Installation**							RE (O/C)			
	21 A/F		0				Mos	20-Nov-2022				
	3202766-1	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:21-32-03											
215102		**Environmental Control Unit - Removal / Installation**							RE (O/C)			
	21 A/F		0				Mos	20-Nov-2022				
	5849520-1	New	0				Hrs	0				
	360		0				Ldg	0				
	Mfg#:21-51-01											
215104		**Primary Heat Exchanger - Removal / Installation**							RE (O/C)			
	21 A/F		0				Mos	20-Nov-2022				
	2342134-1	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:21-51-03											
215106		**Secondary Heat Exchanger - Removal / Installation**							RE (O/C)			
	21 A/F		0				Mos	20-Nov-2022				
	2342136-1	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:21-51-03											
215108		**Reheater / Condenser - Removal / Installation**							RE (O/C)			
	21 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:21-51-04											
215110		**Low Limit Temperature Control Valve - Removal / Installation**							RE (O/C)			
	21 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:21-51-05											
215112		**Turbine Inlet Temperature Control Valve - Removal / Installation**							RE (O/C)			
	21 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:21-51-06											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
215114		**Air Cycle Machine - Removal / Installation**							RE (O/C)			
21 A/F			0				Mos	20-Nov-2022				
	2222252-1	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:21-51-07											
215116		**Environmental Control Unit Plenum Assembly - Removal / Installation**							RE (O/C)			
21 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:21-51-08-RI											
215118		**Compressor Outlet Temperature Sensor - Removal / Installation**							RE (O/C)			
21 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:21-51-09											
215120		**Compressor Bypass Check Valve - Removal / Installation**							RE (O/C)			
21 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:21-51-10											
215121		**Water Spray Nozzle Tube - Removal / Installation**							RE (O/C)			
21 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Ref#:21-51-08-RI											
215205		**Nose Deck Thermal Switch (318H) - Removal / Installation**							RE (O/C)			
21 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:21-52-01											
215206		**Nose Deck Thermal Switch (320H) - Removal / Installation**							RE (O/C)			
21 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:21-52-01											
215209		**Cockpit Thermal Switch (316H) - Removal / Installation**							RE (O/C)			
21 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:21-52-01											
215210		**Cockpit Thermal Switch (327H) - Removal / Installation**							RE (O/C)			
21 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:21-52-01											
215213		**Nose Deck Cooling Fan (313H) - Removal / Installation**							RE (O/C)			
21 A/F			0				Mos	20-Nov-2022				
	SF9DCAAP51A0	New	0				Hrs	0				
	L500504153		0				Ldg	0				
	Mfg#:21-52-02											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
215214		**Nose Deck Cooling Fan (314H) - Removal / Installation**							RE (O/C)			
21 A/F			0				Mos	20-Nov-2022				
	SF9DCAAP51A0	New	0				Hrs	0				
	L500504150		0				Ldg	0				
	Mfg#:21-52-02											
215216		**Cockpit Cooling Fan (315H) - Removal / Installation**							RE (O/C)			
21 A/F			0				Mos	20-Nov-2022				
	SF9DCAAP51A0	New	0				Hrs	0				
	L500504154		0				Ldg	0				
	Mfg#:21-52-02											
215305		**Aft Radio Rack Thermal Switch - Removal / Installation**							RE (O/C)			
21 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:21-53-01											
215306		**Forward Radio Rack Thermal Switch - Removal / Installation**							RE (O/C)			
21 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:21-53-01											
215308		**Radio Rack Cooling Fan - Removal / Installation**							RE (O/C)			
21 A/F			0				Mos	20-Nov-2022				
	SF9DCAAP51A0	New	0				Hrs	0				
	L500504149		0				Ldg	0				
	Mfg#:21-53-02											
216105		**Trim Air Valve - Removal / Installation**							RE (O/C)			
21 A/F		Cockpit	0				Mos	20-Nov-2022				
	3291292-1	New	0				Hrs	0				
	1286		0				Ldg	0				
	Mfg#:21-61-01											
216106		**Trim Air Valve - Removal / Installation**							RE (O/C)			
21 A/F		Cabin	0				Mos	20-Nov-2022				
	3291292-1	New	0				Hrs	0				
	1285		0				Ldg	0				
	Mfg#:21-61-01											
216109		**Cockpit Temperature Sensor - Removal / Installation**							RE (O/C)			
21 A/F			0				Mos	20-Nov-2022				
	1151834-1	New	0				Hrs	0				
	1151834-19460		0				Ldg	0				
	Mfg#:21-61-02											
216110		**Cabin Temperature Sensor - Removal / Installation**							RE (O/C)			
21 A/F			0				Mos	20-Nov-2022				
	1151834-1	New	0				Hrs	0				
	1151834-21109		0				Ldg	0				
	Mfg#:21-61-02											
216113		**Cockpit Temperature Sensor Fan - Removal / Installation**							RE (O/C)			
21 A/F			0				Mos	20-Nov-2022				
	2215737-1	New	0				Hrs	0				
	1433		0				Ldg	0				
	Mfg#:21-61-03											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
216114		**Cabin Temperature Sensor Fan - Removal / Installation**							RE (O/C)			
21 A/F			0				Mos	20-Nov-2022				
	2215737-1	New	0				Hrs	0				
	1434		0				Ldg	0				
	Mfg#:21-61-03											
216120		**Duct Temperature Limiter - Removal / Installation**							RE (O/C)			
21 A/F		Cockpit	0				Mos	20-Nov-2022				
	129856-1	New	0				Hrs	0				
	1836		0				Ldg	0				
	Mfg#:21-61-04											
216121		**Duct Temperature Limiter - Removal / Installation**							RE (O/C)			
21 A/F		Cabin	0				Mos	20-Nov-2022				
	129856-1	New	0				Hrs	0				
	1834		0				Ldg	0				
	Mfg#:21-61-04											
216122		**Duct Temperature Limiter (Plenum) - Removal / Installation**							RE (O/C)			
21 A/F			0				Mos	20-Nov-2022				
	129856-1	New	0				Hrs	0				
	1835		0				Ldg	0				
	Mfg#:21-61-04											
216126		**Duct Temperature Sensor - Removal / Installation**							RE (O/C)			
21 A/F		Cockpit	0				Mos	20-Nov-2022				
	1151834-1	New	0				Hrs	0				
	1151834-19760		0				Ldg	0				
	Mfg#:21-61-04											
216127		**Duct Temperature Sensor - Removal / Installation**							RE (O/C)			
21 A/F		Cabin	0				Mos	20-Nov-2022				
	1151834-1	New	0				Hrs	0				
	1151834-21043		0				Ldg	0				
	Mfg#:21-61-04											
216128		**Duct Temperature Sensor (Plenum) - Removal / Installation**							RE (O/C)			
21 A/F			0				Mos	20-Nov-2022				
	1151834-1	New	0				Hrs	0				
	1151834-20949		0				Ldg	0				
	Mfg#:21-61-04											
216130		**Pack Inlet Temperature Sensor - Removal / Installation**							RE (O/C)			
21 A/F			0				Mos	20-Nov-2022				
	1150124-2-2	New	0				Hrs	0				
	1150124-18916		0				Ldg	0				
	Mfg#:21-61-05											
217102		**Water Extractor - Removal / Installation**							RE (O/C)			
21 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:21-71-01											
217202		**Ozone Converter - Removal / Installation**							RE (O/C)			
21 A/F			0				Mos	20-Nov-2022				
	43261001	New	0				Hrs	0				
	6705		0				Ldg	0				
	Mfg#:21-72-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
219101		**Air Ionizer (Stc St04339At-D) - Removal / Installation**							RE (O/C)			
21 A/F		Left	0				Mos	10-Feb-2023				
	CEM728001284-301	New	0				Hrs	24:24				
	E21187819		0				Ldg	7				
219102		**Air Ionizer (Stc St04339At-D) - Removal / Installation**							RE (O/C)			
21 A/F		Right	0				Mos	10-Feb-2023				
	CEM728001284-301	New	0				Hrs	24:24				
	E21187821		0				Ldg	7				
221102		**Flight Control Panel - Removal / Installation**							RE (O/C)			
22 A/F			0				Mos	20-Nov-2022				
	822-2358-001	New	0				Hrs	0				
	4R61V1		0				Ldg	0				
	Mfg#:22-11-01											
221204		**Aileron Servo - Removal / Installation**							RE (O/C)			
22 A/F			0				Mos	20-Nov-2022				
	822-2136-001	New	0				Hrs	0				
	4P53LF		0				Ldg	0				
	Mfg#:22-12-01											
221206		**Aileron Servo Mount - Removal / Installation**							RE (O/C)			
22 A/F			0				Mos	20-Nov-2022				
	622-5735-102	New	0				Hrs	0				
	4MD437		0				Ldg	0				
	Mfg#:22-12-03											
221208		**Elevator Servo - Removal / Installation**							RE (O/C)			
22 A/F			0				Mos	20-Nov-2022				
	822-2136-001	New	0				Hrs	0				
	4P546T		0				Ldg	0				
	Mfg#:22-12-02											
221210		**Elevator Servo Mount - Removal / Installation**							RE (O/C)			
22 A/F			0				Mos	20-Nov-2022				
	622-5735-102	New	0				Hrs	0				
	4MD5F2		0				Ldg	0				
	Mfg#:22-12-03											
221212		**Autopilot Control Cables (Aileron) - Removal / Installation**							RE (O/C)			
22 A/F			0				Mos	20-Nov-2022				
	30P530011401-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:22-12-04											
221214		**Autopilot Control Cables (Elevator) - Removal / Installation**							RE (O/C)			
22 A/F			0				Mos	20-Nov-2022				
	30P530011301-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:22-12-04											
231104		**VHF COM Transceiver - Removal / Installation**							RE (O/C)			
23 A/F		No.1	0				Mos	20-Nov-2022				
	822-1872-390	New	0				Hrs	0				
	791PF		0				Ldg	0				
	Mfg#:23-11-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
231105		**VHF COM Transceiver - Removal / Installation**							RE (O/C)			
	23 A/F	No.2	0				Mos	20-Nov-2022				
	822-1872-390	New	0				Hrs	0				
	791PC		0				Ldg	0				
	Mfg#:23-11-01											
231106		**VHF COM Transceiver - Removal / Installation**							RE (O/C)			
	23 A/F	No.3	0				Mos	20-Nov-2022				
	822-1872-390	New	0				Hrs	0				
	791PB		0				Ldg	0				
	Mfg#:23-11-01											
231114		**VHF COM Antenna - Removal / Installation**							RE (O/C)			
	23 A/F	No.1	0				Mos	20-Nov-2022				
	S65-8280-42	New	0				Hrs	0				
	323-2997		0				Ldg	0				
	Mfg#:23-11-02											
231115		**VHF COM Antenna - Removal / Installation**							RE (O/C)			
	23 A/F	No.2	0				Mos	20-Nov-2022				
	S65-8280-42	New	0				Hrs	0				
	323-2950		0				Ldg	0				
	Mfg#:23-11-02											
231116		**VHF COM Antenna - Removal / Installation**							RE (O/C)			
	23 A/F	No.3	0				Mos	20-Nov-2022				
	S65-8280-42	New	0				Hrs	0				
	323-2920		0				Ldg	0				
	Mfg#:23-11-02											
231203		**HF Transceiver - Removal / Installation**							RE (O/C)			
	23 A/F	No.1	0				Mos	20-Nov-2022				
	822-0101-002	New	0				Hrs	0				
	4PRYV6		0				Ldg	0				
	Mfg#:23-12-01											
231204		**HF Transceiver - Removal / Installation**							RE (O/C)			
	23 A/F	No.2	0				Mos	10-Feb-2023				
	822-0101-002	New	0				Hrs	24:24				
	4TL0G5		0				Ldg	7				
	Mfg#:23-12-01											
231215		**HF Antenna Coupler - Removal / Installation**							RE (O/C)			
	23 A/F	No.1	0				Mos	20-Nov-2022				
	622-8114-002	New	0				Hrs	0				
	4RLGG9		0				Ldg	0				
	Mfg#:23-12-03											
231216		**HF Antenna Coupler - Removal / Installation**							RE (O/C)			
	23 A/F	No.2	0				Mos	10-Feb-2023				
	622-8114-002	New	0				Hrs	24:24				
	4TL36P		0				Ldg	7				
	Mfg#:23-12-03											
231221		**Coupler Tray - Removal / Installation**							RE (O/C)			
	23 A/F		0				Mos	10-Feb-2023				
	622-8122-001	New	0				Hrs	24:24				
	4T1DKX		0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
231222		**Receiver Tray - Removal / Installation**							RE (O/C)			
	23 A/F		0				Mos	10-Feb-2023				
	622-8116-001	New	0				Hrs	24:24				
	4T1D3P		0				Ldg	7				
231508		**Handset - Removal / Installation**							RE (O/C)			
	23 A/F	Cockpit	0				Mos	10-Feb-2023				
	TN2003-100	New	0				Hrs	24:24				
	1142		0				Ldg	7				
231532		**SATCOM Antenna - Removal / Installation**							RE (O/C)			
	23 A/F		0				Mos	10-Feb-2023				
	S67-1575-365	New	0				Hrs	24:24				
	915-2571		0				Ldg	7				
231561		**VIASAT Antenna Power Supply (APSU) - Removal / Installation**							RE (O/C)			
	23 A/F		0				Mos	10-Feb-2023				
	1243532	New	0				Hrs	24:24				
	D77722310381		0				Ldg	7				
231562		**KA Band Tray - Removal / Installation**							RE (O/C)			
	23 A/F		0				Mos	10-Feb-2023				
	1259484-002	New	0				Hrs	24:24				
	NSN		0				Ldg	7				
231563		**Viasat MBR-5502-001 Modem - Removal / Installation**							RE (O/C)			
	23 A/F		0				Mos	10-Feb-2023				
	1248795-DC	New	0				Hrs	24:24				
	H29719500078		0				Ldg	7				
231564		**SATCOM Direct Router Gateway (SDR-G) - Removal / Installation**							RE (O/C)			
	23 A/F		0				Mos	10-Feb-2023				
	TN2000-7772	New	0				Hrs	24:24				
	1217		0				Ldg	7				
231565		**VIASAT G-12KA Antenna - Removal / Installation**							RE (O/C)			
	23 A/F						Mos	31-Dec-2023				
	1209814-001	Repaired				0	Hrs	599:44				
	50204-G00152					0	Ldg	360				
231566		**Saint-Gobain Vertical Stabilizer Radome - Removal / Installation**							RE (O/C)			
	23 A/F						Mos	13-Mar-2024				
	5288-100	New	0				Hrs	678:36				
	081		0				Ldg	405				
231567		**WiFi - Antenna Mimo - Removal / Installation**							RE (O/C)			
	23 A/F		0				Mos	10-Feb-2023				
	TN2008-200	New	0				Hrs	24:24				
	526		0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
231568		**Wideband Antenna (WBA)(TNC) - Removal / Installation**							RE (O/C)			
	23 A/F		0				Mos	10-Feb-2023				
	900120	New	0				Hrs	24:24				
	3307		0				Ldg	7				
231569		**Sdr Gateway Personality Module - Removal / Installation**							RE (O/C)			
	23 A/F		0				Mos	10-Feb-2023				
	TN2301-100	New	0				Hrs	24:24				
	996		0				Ldg	7				
231570		**Cable Network Distribution Unit - Removal / Installation**							RE (O/C)			
	23 A/F		0				Mos	10-Feb-2023				
	TN1002-100	New	0				Hrs	24:24				
	2161		0				Ldg	7				
231571		**Datalink Unit - Removal / Installation**							RE (O/C)			
	23 A/F		0				Mos	10-Feb-2023				
	TN1007-100	New	0				Hrs	24:24				
	757		0				Ldg	7				
232720		**ATG Mounting Tray - Removal / Installation**							RE (O/C)			
	23 A/F		0				Mos	10-Feb-2023				
	P14291	New	0				Hrs	24:24				
	NSN		0				Ldg	7				
233023		**Subwoofer - Removal / Installation**							RE (O/C)			
	23 A/F	No.1	0				Mos	10-Feb-2023				
	106511-259-4G6001	New	0				Hrs	24:24				
	270735		0				Ldg	7				
233024		**Subwoofer - Removal / Installation**							RE (O/C)			
	23 A/F	No.2	0				Mos	10-Feb-2023				
	106511-259-4G6001	New	0				Hrs	24:24				
	270730		0				Ldg	7				
233030		**Audio Amp - Removal / Installation**							RE (O/C)			
	23 A/F		0				Mos	10-Feb-2023				
	106500-0620-10000	New	0				Hrs	24:24				
	090305		0				Ldg	7				
233037		**Touch Screen Control Panel - Removal / Installation**							RE (O/C)			
	23 A/F		0				Mos	10-Feb-2023				
	CTS100-101MOD 01	New	0				Hrs	24:24				
	22110256		0				Ldg	7				
233044		**Cabin Controller - Removal / Installation**							RE (O/C)			
	23 A/F		0				Mos	10-Feb-2023				
	CPBC-01-001	New	0				Hrs	24:24				
	00824		0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
233048		**Cabin Management Controller (Sidewall / 569A204) - Removal / Installation**							RE (O/C)			
23 A/F		Cabin	0				Mos	10-Feb-2023				
	GCMS-02-002	New	0				Hrs	24:24				
	06780		0				Ldg	7				
233071		**Switch Control Panel (Entry) - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	A2615	New	0				Hrs	24:24				
	000304		0				Ldg	7				
233085		**Switch Control Panel - Removal / Installation**							RE (O/C)			
23 A/F		Lavatory	0				Mos	10-Feb-2023				
	A2480	New	0				Hrs	24:24				
	005265		0				Ldg	7				
233086		**Switch Control Panel (Flush) - Removal / Installation**							RE (O/C)			
23 A/F		Lavatory	0				Mos	10-Feb-2023				
	A2485	New	0				Hrs	24:24				
	005409		0				Ldg	7				
233090		**Avionics Rack GCMS Switching Node - Removal / Installation**							RE (O/C)			
23 A/F		Left	0				Mos	10-Feb-2023				
	GCMS-01-001	New	0				Hrs	24:24				
	23300		0				Ldg	7				
233092		**Avionics Rack GCMS Switching Node - Removal / Installation**							RE (O/C)			
23 A/F		Right					Mos	06-Mar-2023				
	GCMS-01-001	Repaired				0	Hrs	35:48				
	08125					0	Ldg	11				
233094		**GCMS Equipment Cooling Fan - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	011035000	New	0				Hrs	24:24				
	I22400553		0				Ldg	7				
233100		**Fixed User Interface (FUI) (Jumpseat PSU) - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	LA16500-1	New	0				Hrs	24:24				
	FL-23010141		0				Ldg	7				
233106		**Fixed User Interface (FUI) (L/H No. 1 PSU) - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	LA16500-2	New	0				Hrs	24:24				
	FL-23010138		0				Ldg	7				
233107		**Fixed User Interface (FUI) (L/H No. 2 PSU) - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	LA16500-3	New	0				Hrs	24:24				
	FL-23010135		0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
233108		**Fixed User Interface (FUI) (L/H No. 3 PSU) - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	LA16500-2	New	0				Hrs	24:24				
	FL-23010139		0				Ldg	7				
233109		**Fixed User Interface (FUI) (L/H No. 4 PSU) - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	LA16500-3	New	0				Hrs	24:24				
	FL-23010136		0				Ldg	7				
233116		**Fixed User Interface (FUI) (R/H No. 1 PSU) - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	LA16500-3	New	0				Hrs	24:24				
	FL-23010137		0				Ldg	7				
233117		**Fixed User Interface (FUI) (R/H No. 2 PSU) - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	LA16500-2	New	0				Hrs	24:24				
	FL-23010140		0				Ldg	7				
233118		**Fixed User Interface (FUI) (R/H No. 3 PSU) - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	LA16500-3	New	0				Hrs	24:24				
	FL-23010131		0				Ldg	7				
233119		**Fixed User Interface (FUI) (R/H No. 4 PSU) - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	LA16500-2	New	0				Hrs	24:24				
	FL-23010132		0				Ldg	7				
233120		**Fixed User Interface (FUI) (Lavatory PSU) - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	LA16500-6	New	0				Hrs	24:24				
	FL-23010134		0				Ldg	7				
233124		**Cabin Management Controller (Cabin Sidewall / 569A202) - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	GCMS-02-002	New	0				Hrs	24:24				
	06888		0				Ldg	7				
233128		**Cabin Management Controller (Cabin Sidewall / 569A107) - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	GCMS-02-002	New	0				Hrs	24:24				
	06785		0				Ldg	7				
233130		**Cabin Management Controller (Cabin Sidewall / 569A105) - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	GCMS-02-002	New	0				Hrs	24:24				
	06791		0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
233131		**Cabin Management Controller (Cabin Sidewall / 569A110) - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
GCMS-02-002		New	0				Hrs	24:24				
06793			0				Ldg	7				
233135		**Galley Power Bus Controller (Closet) - Removal / Installation**							RE (O/C)			
23 A/F		Left Fwd	0				Mos	10-Feb-2023				
GPBC-01-001		New	0				Hrs	24:24				
00794			0				Ldg	7				
233152		**Cabin Management Switch Node (Cabin Sidewall / 569A104) - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
GCMS-01-001		New	0				Hrs	24:24				
23357			0				Ldg	7				
233172		**Entertainment Control Unit (Chair 101) - Removal / Installation**							RE (O/C)			
23 A/F		Left	0				Mos	10-Feb-2023				
RCO36789		New	0				Hrs	24:24				
2128			0				Ldg	7				
233174		**Entertainment Control Unit (Chair 102) - Removal / Installation**							RE (O/C)			
23 A/F		Left	0				Mos	10-Feb-2023				
RCO36790		New	0				Hrs	24:24				
3782			0				Ldg	7				
233176		**Entertainment Control Unit (Chair 201) - Removal / Installation**							RE (O/C)			
23 A/F		Right	0				Mos	10-Feb-2023				
RCO36790		New	0				Hrs	24:24				
3784			0				Ldg	7				
233178		**Entertainment Control Unit (Chair 202) - Removal / Installation**							RE (O/C)			
23 A/F		Right	0				Mos	10-Feb-2023				
RCO36789		New	0				Hrs	24:24				
2159			0				Ldg	7				
233184		**Entertainment Control Unit - Removal / Installation**							RE (O/C)			
23 A/F		Divan - Fwd	0				Mos	10-Feb-2023				
RCO36789		New	0				Hrs	24:24				
2169			0				Ldg	7				
233186		**Entertainment Control Unit - Removal / Installation**							RE (O/C)			
23 A/F		Divan - Aft	0				Mos	10-Feb-2023				
RCO36790		New	0				Hrs	24:24				
3785			0				Ldg	7				
233194		**Entertainment Control Unit (Chair 103) - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
RCO36789		New	0				Hrs	24:24				
2156			0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
233196		**Entertainment Control Unit (Chair 104) - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	RCO36790	New	0				Hrs	24:24				
	3783		0				Ldg	7				
233302		**Briefing Control Panel - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	0300-421	New	0				Hrs	24:24				
	22110039		0				Ldg	7				
233312		**Cabin Emergency Lighting Inertia Switch - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	3LO-871/5-1	New	0				Hrs	24:24				
	127833		0				Ldg	7				
233506		**Cabin 19" Monitor - Removal / Installation**							RE (O/C)			
23 A/F		Left Fwd	0				Mos	10-Feb-2023				
	SDM220-111 MOD 00	New	0				Hrs	24:24				
	22110051		0				Ldg	7				
233528		**Blue-Ray DVD with Media Server - Removal / Installation**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	0602-200	New	0				Hrs	24:24				
	22090064		0				Ldg	7				
233537		**Cabin Audio Visual Display System - Removal / Installation**							RE (O/C)			
23 A/F		Left Fwd	0				Mos	10-Feb-2023				
	100-0061-01	New	0				Hrs	24:24				
	177256N0001		0				Ldg	7				
233539		**Cabin Audio Visual Display System - Removal / Installation**							RE (O/C)			
23 A/F		Left Aft	0				Mos	10-Feb-2023				
	100-0062-02	New	0				Hrs	24:24				
	130632N0001		0				Ldg	7				
233800		**Cabin Processor Unit**							RE (O/C)			
23 A/F			0				Mos	10-Feb-2023				
	CPU-01-004	New	0				Hrs	24:24				
	00317		0				Ldg	7				
	ATA Ref:23-38-00											
235105		**Audio Control Panel - Removal / Installation**							RE (O/C)			
23 A/F		No.1					Mos	10-Feb-2023				
	822-2928-751						Hrs	24:24				
	4R60Y9						Ldg	7				
	ATA Ref::23-51-01, Mfg#:23-51-01											
235106		**Audio Control Panel - Removal / Installation**							RE (O/C)			
23 A/F		No.2					Mos	10-Feb-2023				
	822-2928-751						Hrs	24:24				
	4R60K0						Ldg	7				
	ATA Ref::23-51-01, Mfg#:23-51-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
235107		**Audio Control Panel - Removal / Installation**							RE (O/C)			
	23 A/F	No.3	0				Mos	10-Feb-2023				
	822-2928-751	New	0				Hrs	24:24				
	4R60GK		0				Ldg	7				
	ATA Ref::23-51-01, Ref#:23-51-01											
235115		**Audio Control Panel - Removal / Installation**							RE (O/C)			
	23 A/F	No.1	0				Mos	20-Nov-2022				
	822-1947-020	New	0				Hrs	0				
	4P55VT		0				Ldg	0				
	ATA Ref::23-51-01, Mfg#:23-51-02											
235116		**Audio Control Panel - Removal / Installation**							RE (O/C)			
	23 A/F	No.2	0				Mos	20-Nov-2022				
	822-1947-020	New	0				Hrs	0				
	4P56C3		0				Ldg	0				
	ATA Ref::23-51-01, Mfg#:23-51-02											
235117		**Audio Control Panel - Removal / Installation**							RE (O/C)			
	23 A/F	No.3	0				Mos	10-Feb-2023				
	822-1947-020	New	0				Hrs	24:24				
	4T0L6L		0				Ldg	7				
	ATA Ref::23-51-01, Ref#:23-51-02											
235123		**Radio Interface Unit - Removal / Installation**							RE (O/C)			
	23 A/F	No.1					Mos	13-Mar-2024				
	822-1863-681	Overhauled		0			Hrs	678:36				
	4GPT26			0			Ldg	405				
	ATA Ref::23-51-03, Mfg#:23-51-03											
235124		**Radio Interface Unit - Removal / Installation**							RE (O/C)			
	23 A/F	No.2					Mos	10-Feb-2023				
	822-1863-681						Hrs	24:24				
	4RGR9V						Ldg	7				
	ATA Ref::23-51-03, Mfg#:23-51-03											
235127		**Radio Interface Unit External Compensation Unit - Removal / Installation**							RE (O/C)			
	23 A/F	No.1	0				Mos	20-Nov-2022				
	822-1200-996	New	0				Hrs	0				
	4RK2H0		0				Ldg	0				
	ATA Ref::23-51-04, Mfg#:23-51-04											
235128		**Radio Interface Unit External Compensation Unit - Removal / Installation**							RE (O/C)			
	23 A/F	No.2	0				Mos	10-Feb-2023				
	822-1200-996	New	0				Hrs	24:24				
	4MTC5H		0				Ldg	7				
	ATA Ref::23-51-04, Mfg#:23-51-04											
236103		**Static Discharger - Removal / Installation**							RE (O/C)			
	23 A/F						Mos	17-Jan-2023				
	UKN						Hrs	22:54				
	NSN						Ldg	6				
	Mfg#:23-61-01											
236105		**Static Discharger Base (Riveted) - Removal / Installation**							RE (O/C)			
	23 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	(SOURCE: 23-61-01)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
236106		**Static Discharger Base (Bonded) - Removal / Installation**							RE (O/C)			
	23 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	(SOURCE: 23-61-01)											
242102		**60 Hz Static Inverter - Removal / Installation**							RE (O/C)			
	24 A/F		0				Mos	20-Nov-2022				
	2G2000-1A-2161	New	0				Hrs	0				
	KB000287		0				Ldg	0				
	Mfg#:24-21-01											
243103		**Engine Generator - Removal / Installation**							RE (O/C)			
	24 A/F	Left	2				Mos	08-Feb-2023				
	A3579-801		24:24				Hrs	24:24				
	2967		7				Ldg	7				
	Mfg#:24-31-01-RI											
243104		**Engine Generator - Removal / Installation**							RE (O/C)			
	24 A/F	Right	2				Mos	26-Jan-2023				
	A3579-801		24:24				Hrs	24:24				
	2965		7				Ldg	7				
	Mfg#:24-31-01-RI											
243113		**Engine Generator Control Unit - Removal / Installation**							RE (O/C)			
	24 A/F	Left	0				Mos	20-Nov-2022				
	R-3887-100 MOD E	New	0				Hrs	0				
	2711E		0				Ldg	0				
	Mfg#:24-31-02											
243114		**Engine Generator Control Unit - Removal / Installation**							RE (O/C)			
	24 A/F	Right	0				Mos	20-Nov-2022				
	R-3887-100 MOD E	New	0				Hrs	0				
	2716E		0				Ldg	0				
	Mfg#:24-31-02											
243123		**Engine Generator Hall Effect Current Sensor - Removal / Installation**							RE (O/C)			
	24 A/F	Left	0				Mos	20-Nov-2022				
	117GC04Y02	New	0				Hrs	0				
	1041		0				Ldg	0				
	Mfg#:24-31-02											
243124		**Engine Generator Hall Effect Current Sensor - Removal / Installation**							RE (O/C)			
	24 A/F	Right	0				Mos	20-Nov-2022				
	117GC04Y02	New	0				Hrs	0				
	1040		0				Ldg	0				
	Mfg#:24-31-02											
243202		**APU Starter-Generator - Removal / Installation**							RE (O/C)			
	24 A/F		0				Mos	20-Nov-2022				
	G3666-400	New	0				Hrs	0				
	2144B		0				Ldg	0				
	Mfg#:24-32-01-RI											
243206		**APU Starter-Generator Brushes - Removal / Installation**							RE (O/C)			
	24 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:24-32-01-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
243212		**APU Generator Control Unit - Removal / Installation**							RE (O/C)			
	24 A/F		0				Mos	20-Nov-2022				
	R-3887-100 MOD E	New	0				Hrs	0				
	2713E		0				Ldg	0				
	Mfg#:24-32-02-RI											
243216		**APU Generator Control Unit External Hall Effect Current Sensor - Removal / Installation**							RE (O/C)			
	24 A/F		0				Mos	20-Nov-2022				
	117GC04Y02	New	0				Hrs	0				
	1014		0				Ldg	0				
	Mfg#:24-32-02-RI											
243220		**APU Starter/Generator Control Harness - Removal / Installation**							RE (O/C)			
	24 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
243303		**Main Battery - Removal / Installation**							RE (O/C)			
	24 A/F	Left					Mos	20-Oct-2023				
	RG-380E/53GH-6	Tested/Inspected	380:36				Hrs	490:27				
	41280033		233				Ldg	293				
	Mfg#:24-33-01-RI											
243304		**Main Battery - Removal / Installation**							RE (O/C)			
	24 A/F	Right					Mos	20-Oct-2023				
	RG-380E/53GH-6	Tested/Inspected	392:13				Hrs	490:27				
	41284436		240				Ldg	293				
	Mfg#:24-33-01-RI											
243502		**Emergency Power Supply - Removal / Installation**							RE (O/C)			
	24 A/F						Mos	02-Mar-2023				
	100-0202-03		21:42				Hrs	34:12				
	1213604		5				Ldg	10				
243502		**Emergency Power Supply (XL246-C) - Removal / Installation**							RE (O/C)			
	24 A/F		10				Mos	19-Jan-2023				
	100-0202-03		21:06				Hrs	22:54				
	1211798		5				Ldg	6				
	Mfg#:24-35-01											
244011		**Noise Filter (PSU) - Removal / Installation**							RE (O/C)			
	24 A/F	Left	0				Mos	10-Feb-2023				
	122253-10A	New	0				Hrs	24:24				
	002-019670		0				Ldg	7				
244012		**Noise Filter (PSU) - Removal / Installation**							RE (O/C)			
	24 A/F	Right	0				Mos	10-Feb-2023				
	122253-10A	New	0				Hrs	24:24				
	002-019654		0				Ldg	7				
244013		**Noise Filter, Psu - Removal / Installation**							RE (O/C)			
	24 A/F	Left - Aft	0				Mos	10-Feb-2023				
	122253-10A	New	0				Hrs	24:24				
	002-019672		0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
244014		**Noise Filter, Psu - Removal / Installation**							RE (O/C)			
24 A/F		Right - Aft	0				Mos	10-Feb-2023				
	122253-10A	New	0				Hrs	24:24				
	002-019880		0				Ldg	7				
245010		**AC Power Controller (Table) - Removal / Installation**							RE (O/C)			
24 A/F		Right Fwd	0				Mos	10-Feb-2023				
	106354-2	New	0				Hrs	24:24				
	6470822		0				Ldg	7				
245015		**AC Power Controller - Removal / Installation**							RE (O/C)			
24 A/F		Aft Lavatory - Right	0				Mos	10-Feb-2023				
	106354-2	New	0				Hrs	24:24				
	6810922		0				Ldg	7				
245023		**110 Outlet - Removal / Installation**							RE (O/C)			
24 A/F		Galley	0				Mos	10-Feb-2023				
	106356-2	New	0				Hrs	24:24				
	26771122		0				Ldg	7				
245024		**110 Outlet - Removal / Installation**							RE (O/C)			
24 A/F		Aft Lavatory	0				Mos	10-Feb-2023				
	106356-2	New	0				Hrs	24:24				
	26601022		0				Ldg	7				
245028		**110 Outlet - Removal / Installation**							RE (O/C)			
24 A/F		Galley - No.3	0				Mos	10-Feb-2023				
	106356-2	New	0				Hrs	24:24				
	26521022		0				Ldg	7				
245034		**Closet AC Power Supply - Removal / Installation**							RE (O/C)			
24 A/F		Left	0				Mos	10-Feb-2023				
	106354-2	New	0				Hrs	24:24				
	6800922		0				Ldg	7				
245316		**Cabin 60 Hz Outlet - Removal / Installation**							RE (O/C)			
24 A/F		Left No.1	0				Mos	10-Feb-2023				
	106356-2	New	0				Hrs	24:24				
	26531022		0				Ldg	7				
245317		**Cabin 60 Hz Outlet - Removal / Installation**							RE (O/C)			
24 A/F		Left No.2	0				Mos	10-Feb-2023				
	106356-2	New	0				Hrs	24:24				
	26541022		0				Ldg	7				
245318		**Cabin 60 Hz Outlet - Removal / Installation**							RE (O/C)			
24 A/F		Left No.3	0				Mos	10-Feb-2023				
	106356-2	New	0				Hrs	24:24				
	26551022		0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
245319		**Cabin 60 Hz Outlet - Removal / Installation**							RE (O/C)			
24 A/F		Left No.4	0				Mos	10-Feb-2023				
	106356-2	New	0				Hrs	24:24				
	26561022		0				Ldg	7				
245323		**GFCI - Removal / Installation**							RE (O/C)			
24 A/F		Upper	0				Mos	10-Feb-2023				
	106355-1	New	0				Hrs	24:24				
	2640922		0				Ldg	7				
245326		**Cabin 60 Hz Outlet - Removal / Installation**							RE (O/C)			
24 A/F		Right No.1	0				Mos	10-Feb-2023				
	106356-2	New	0				Hrs	24:24				
	26571022		0				Ldg	7				
245327		**Cabin 60 Hz Outlet - Removal / Installation**							RE (O/C)			
24 A/F		Right No.2	0				Mos	10-Feb-2023				
	106356-2	New	0				Hrs	24:24				
	26581022		0				Ldg	7				
245329		**Cabin 60 Hz Outlet - Removal / Installation**							RE (O/C)			
24 A/F		Right No.4	0				Mos	10-Feb-2023				
	106356-2	New	0				Hrs	24:24				
	26591022		0				Ldg	7				
245411		**PSU Power Supply (Chair 101) - Removal / Installation**							RE (O/C)			
24 A/F			0				Mos	10-Feb-2023				
	PS18125-1	New	0				Hrs	24:24				
	NSN		0				Ldg	7				
245417		**PSU Power Supply (Chair 104) - Removal / Installation**							RE (O/C)			
24 A/F			0				Mos	10-Feb-2023				
	PS18125-1	New	0				Hrs	24:24				
	NSN		0				Ldg	7				
246103		**DC Box - Removal / Installation**							RE (O/C)			
24 A/F		Left	0				Mos	10-Feb-2023				
	109GC04Y03	New	0				Hrs	24:24				
	0282		0				Ldg	7				
	Mfg#:24-61-01											
246104		**DC Box - Removal / Installation**							RE (O/C)			
24 A/F		Right	0				Mos	20-Nov-2022				
	110GC04Y03	New	0				Hrs	0				
	0271		0				Ldg	0				
	Mfg#:24-61-02											
246203		**Relay Box - Removal / Installation**							RE (O/C)			
24 A/F		Left - Front	0				Mos	20-Nov-2022				
	FE 3028-534	New	0				Hrs	0				
	549		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
246204		**Relay Box - Removal / Installation**							RE (O/C)			
24 A/F		Right - Front	0				Mos	20-Nov-2022				
FE 3029-532		New	0				Hrs	0				
546			0				Ldg	0				
246207		**Relay Box - Removal / Installation**							RE (O/C)			
24 A/F		Left - Rear	0				Mos	20-Nov-2022				
FE 3026-522		New	0				Hrs	0				
545			0				Ldg	0				
246208		**Relay Box - Removal / Installation**							RE (O/C)			
24 A/F		Right - Rear	0				Mos	20-Nov-2022				
FE 3027-524		New	0				Hrs	0				
544			0				Ldg	0				
246303		**Emergency DC Box - Removal / Installation**							RE (O/C)			
24 A/F			0				Mos	20-Nov-2022				
108GC04Y02		New	0				Hrs	0				
0268			0				Ldg	0				
Mfg#:24-63-01												
246403		**Cockpit Overhead Circuit Breaker Panel - Removal / Installation**							RE (O/C)			
24 A/F							Mos	10-Feb-2023				
GA441940001-15							Hrs	24:24				
0280							Ldg	7				
Mfg#:24-64-01												
246412		**Circuit Breaker Panel Light Plates - Removal / Installation**							RE (O/C)			
24 A/F		Left No.2			0		Mos	10-Feb-2023				
143ND02Y04		Repaired			0		Hrs	24:24				
0271					0		Ldg	7				
246413		**Circuit Breaker Panel Light Plates - Removal / Installation**							RE (O/C)			
24 A/F		Right No.1					Mos	10-Feb-2023				
GA441940001-19							Hrs	24:24				
0255							Ldg	7				
247003		**Heater Control Unit Concorde Battery (Stc-St04469At) - Removal / Installation**							RE (O/C)			
24 A/F		Left					Mos	13-Mar-2024				
5-0600		New	0				Hrs	678:36				
41366871			0				Ldg	405				
247004		**Heater Control Unit Concorde Battery (Stc-St04469At) - Removal / Installation**							RE (O/C)			
24 A/F		Right					Mos	13-Mar-2024				
5-0600		New	0				Hrs	678:36				
41366874			0				Ldg	405				
250012		**Aircraft Tow Bar - Removal / Installation**							RE (O/C)			
25 A/F			5				Mos	10-Feb-2023				
WY-3501							Hrs	24:24				
9442							Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
250014		**Aircraft Tow Bar Head - Removal / Installation**							RE (O/C)			
	25 A/F			2			Mos	10-Feb-2023				
	WY-3502						Hrs	24:24				
	9462						Ldg	7				
251030		**Defibrillator - Removal / Installation**							RE (O/C)			
	25 A/F						Mos	20-Nov-2022				
	710114/710115	New					Hrs	0				
	B22I-13052						Ldg	0				
251102		**Instrument Panel - Removal / Installation**							RE (O/C)			
	25 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:25-11-01											
251104		**Glareshield - Removal / Installation**							RE (O/C)			
	25 A/F						Mos	02-Mar-2023				
	30P352116003-501	Tested/Inspected					Hrs	34:12				
	182						Ldg	10				
	Mfg#:25-11-02											
251203		**Crew Seat - Removal / Installation**							RE (O/C)			
	25 A/F	Pilot		0			Mos	20-Nov-2022				
	GPS421000-501	New		0			Hrs	0				
	274			0			Ldg	0				
	Mfg#:25-12-01-RI											
251204		**Crew Seat - Removal / Installation**							RE (O/C)			
	25 A/F	Copilot		0			Mos	20-Nov-2022				
	GPS421000-502	New		0			Hrs	0				
	273			0			Ldg	0				
	Mfg#:25-12-01-RI											
251212		**Jumpseat - Removal / Installation**							RE (O/C)			
	25 A/F			0			Mos	10-Feb-2023				
	403179-1	New		0			Hrs	24:24				
	68870			0			Ldg	7				
251603		**Cockpit Ceiling Panel - Removal / Installation**							RE (O/C)			
	25 A/F	Pilot					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::25-16-00, Mfg#:25-16-00											
251606		**Visor Assembly - Removal / Installation**							RE (O/C)			
	25 A/F	Cockpit		0			Mos	10-Feb-2023				
	R1951200-0	New		0			Hrs	24:24				
	M268644			0			Ldg	7				
252116		**Passenger Seat - Removal / Installation**							RE (O/C)			
	25 A/F	Left No.1		0			Mos	10-Feb-2023				
	3AEF0120002	New		0			Hrs	24:24				
	4000627910			0			Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
252118		**Passenger Seat - Removal / Installation**							RE (O/C)			
25 A/F	3AEF0120001	Right No.1	0				Mos	10-Feb-2023				
	4000627908	New	0				Hrs	24:24				
			0				Ldg	7				
252119		**Passenger Seat - Removal / Installation**							RE (O/C)			
25 A/F	3AEF0120001	Left No.2	0				Mos	10-Feb-2023				
	4000627909	New	0				Hrs	24:24				
			0				Ldg	7				
252120		**Passenger Seat - Removal / Installation**							RE (O/C)			
25 A/F	3AEF0120002	Right No.2	0				Mos	10-Feb-2023				
	4000627911	New	0				Hrs	24:24				
			0				Ldg	7				
252121		**Passenger Seat - Removal / Installation**							RE (O/C)			
25 A/F	3AEF0220006	Left No.3	0				Mos	10-Feb-2023				
	4000627913	New	0				Hrs	24:24				
			0				Ldg	7				
252123		**Passenger Seat - Removal / Installation**							RE (O/C)			
25 A/F	3AEF0220005	Left No.4	0				Mos	10-Feb-2023				
	4000627912	New	0				Hrs	24:24				
			0				Ldg	7				
252135		**Divan - Removal / Installation**							RE (O/C)			
25 A/F	3DEF0220004	No.1	0				Mos	10-Feb-2023				
	4000629535	New	0				Hrs	24:24				
			0				Ldg	7				
252136		**Divan - Removal / Installation**							RE (O/C)			
25 A/F	3DEF0120004	No.2	0				Mos	10-Feb-2023				
	4000629534	New	0				Hrs	24:24				
			0				Ldg	7				
252413		**Blank Window Shade Assembly - Removal / Installation**							RE (O/C)			
25 A/F	G280II-01-010-C1-2	Left No.1	0				Mos	10-Feb-2023				
	NSN	New	0				Hrs	24:24				
			0				Ldg	7				
252414		**Cabin Window Shade Assemby - Removal / Installation**							RE (O/C)			
25 A/F	G280II-01-010-G1-1	Right No.1	0				Mos	10-Feb-2023				
	NSN	New	0				Hrs	24:24				
			0				Ldg	7				
252415		**Cabin Window Shade Assemby - Removal / Installation**							RE (O/C)			
25 A/F	G280II-01-14-2	Left No.2	0				Mos	10-Feb-2023				
	886	New	0				Hrs	24:24				
			0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
252416		**Cabin Window Shade Assembly - Removal / Installation**							RE (O/C)			
25 A/F		Right No.2	0				Mos	10-Feb-2023				
	G280II-01-010-G1-1	New	0				Hrs	24:24				
	NSN		0				Ldg	7				
252417		**Cabin Window Shade Assembly - Removal / Installation**							RE (O/C)			
25 A/F		Left No.3	0				Mos	10-Feb-2023				
	G280II-01-14-2	New	0				Hrs	24:24				
	887		0				Ldg	7				
252418		**Cabin Window Shade Assembly - Removal / Installation**							RE (O/C)			
25 A/F		Right No.3	0				Mos	10-Feb-2023				
	G280II-01-014-1	New	0				Hrs	24:24				
	879		0				Ldg	7				
252419		**Cabin Window Shade Assembly - Removal / Installation**							RE (O/C)			
25 A/F		Left No.4	0				Mos	10-Feb-2023				
	G280II-01-14-2	New	0				Hrs	24:24				
	888		0				Ldg	7				
252420		**Cabin Window Shade Assembly - Removal / Installation**							RE (O/C)			
25 A/F		Right No.4	0				Mos	10-Feb-2023				
	G280II-01-014-1	New	0				Hrs	24:24				
	880		0				Ldg	7				
252421		**Cabin Window Shade Assembly - Removal / Installation**							RE (O/C)			
25 A/F		Left No.5	0				Mos	10-Feb-2023				
	G280II-01-14-2	New	0				Hrs	24:24				
	889		0				Ldg	7				
252422		**Cabin Window Shade Assembly - Removal / Installation**							RE (O/C)			
25 A/F		Right No.5	0				Mos	10-Feb-2023				
	G280II-01-014-1	New	0				Hrs	24:24				
	881		0				Ldg	7				
252424		**Cabin Window Shade Assembly - Removal / Installation**							RE (O/C)			
25 A/F		Emergency	0				Mos	10-Feb-2023				
	G280II-01-014-1	New	0				Hrs	24:24				
	885		0				Ldg	7				
252441		**Cabin Window Shade Assembly - Removal / Installation**							RE (O/C)			
25 A/F		Left No.6	0				Mos	10-Feb-2023				
	G280II-01-14-2	New	0				Hrs	24:24				
	890		0				Ldg	7				
252442		**Cabin Window Shade Assembly - Removal / Installation**							RE (O/C)			
25 A/F		Right No.6	0				Mos	10-Feb-2023				
	G280II-01-014-1	New	0				Hrs	24:24				
	882		0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
252443		**Cabin Window Shade Assemby - Removal / Installation**							RE (O/C)			
25 A/F		Left No.7	0				Mos	10-Feb-2023				
	G280II-01-14-2	New	0				Hrs	24:24				
	891		0				Ldg	7				
252444		**Cabin Window Shade Assemby - Removal / Installation**							RE (O/C)			
25 A/F		Right No.7	0				Mos	10-Feb-2023				
	G280II-01-014-1	New	0				Hrs	24:24				
	883		0				Ldg	7				
252445		**Cabin Window Shade Assemby - Removal / Installation**							RE (O/C)			
25 A/F		Left No.8	0				Mos	10-Feb-2023				
	G280II-01-014-AFT-2	New	0				Hrs	24:24				
	893		0				Ldg	7				
252447		**Lavatory Window Shade Assemby - Removal / Installation**							RE (O/C)			
25 A/F		Left	0				Mos	10-Feb-2023				
	G280II-01-014-VAN-2	New	0				Hrs	24:24				
	894		0				Ldg	7				
252448		**Lavatory Window Shade Assemby - Removal / Installation**							RE (O/C)			
25 A/F		Right	0				Mos	10-Feb-2023				
	G280II-01-014-AFT-1	New	0				Hrs	24:24				
	892		0				Ldg	7				
252451		**Cockpit Side Window Shade Assembly - Removal / Installation**							RE (O/C)			
25 A/F		Left	0				Mos	10-Feb-2023				
	1-6174-100	New	0				Hrs	24:24				
	104280		0				Ldg	7				
252452		**Cockpit Side Window Shade Assembly - Removal / Installation**							RE (O/C)			
25 A/F		Right	0				Mos	10-Feb-2023				
	1-6173-100	New	0				Hrs	24:24				
	104484		0				Ldg	7				
252456		**Cabin Window Shade Assemby - Removal / Installation**							RE (O/C)			
25 A/F		Right No.8	0				Mos	10-Feb-2023				
	G280II-01-014-1	New	0				Hrs	24:24				
	884		0				Ldg	7				
252502		**Conference Table - Removal / Installation**							RE (O/C)			
25 A/F		No.1	0				Mos	10-Feb-2023				
	80120-01	New	0				Hrs	24:24				
	79569-5		0				Ldg	7				
253602		**Oxygen Nebullizer - Removal / Installation**							RE (O/C)			
25 A/F		No.1	0				Mos	10-Feb-2023				
	O2C33K08-01-030	New	0				Hrs	24:24				
	9245-001-01		0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
253604		**Oxygen Nebullizer Therapeutic Mask - Removal / Installation**							RE (O/C)			
25 A/F		No.1	0				Mos	10-Feb-2023				
	O2C52T10-12-144	New	0				Hrs	24:24				
	NSN		0				Ldg	7				
253702		**Microwave Oven - Removal / Installation**							RE (O/C)			
25 A/F							Mos	08-Dec-2023				
	DMO-1000-105	Repaired			0		Hrs	562:47				
	DMO105-077				0		Ldg	338				
256002		**Rechargeable Flashlight - Removal / Installation**							RE (O/C)			
25 A/F		No.1	0				Mos	10-Feb-2023				
	P2-07-0022-001	New	0				Hrs	24:24				
	NSN		0				Ldg	7				
256004		**Rechargeable Flashlight - Removal / Installation**							RE (O/C)			
25 A/F		No.2	0				Mos	10-Feb-2023				
	P2-07-0022-001	New	0				Hrs	24:24				
	NSN		0				Ldg	7				
256017		**Fire / Crash Axe - Removal / Installation**							RE (O/C)			
25 A/F			13				Mos	13-Mar-2024				
	D56		654:12				Hrs	678:36				
	NSN		398				Ldg	405				
256051		**Emergency Vision Assurance System (EVAS) - Removal / Installation**							RE (O/C)			
25 A/F		Left	0				Mos	06-Feb-2023				
	107STC-271	New	0				Hrs	24:24				
	009HH01P		0				Ldg	7				
	(NOTE: ST00892LA)											
256052		**Emergency Vision Assurance System (EVAS) - Removal / Installation**							RE (O/C)			
25 A/F		Right	0				Mos	06-Feb-2023				
	107STC-272	New	0				Hrs	24:24				
	010HH01P		0				Ldg	7				
	(NOTE: ST00892LA)											
256102		**Emergency Locator Transmitter - Removal / Installation**							RE (O/C)			
25 A/F			6				Mos	03-Mar-2023				
	453-5060		35:48				Hrs	35:48				
	252-06760		11				Ldg	11				
	ATA Ref::25-61-01, Mfg#:25-61-01											
256104		**Emergency Locator Transmitter Battery - Removal / Installation**							RE (O/C)			
25 A/F			3				Mos	03-Mar-2023				
	452-0133		35:48				Hrs	35:48				
	393042-030		11				Ldg	11				
	ATA Ref::25-61-01, Ref#:25-61-01											
256110		**Emergency Locator Transmitter Antenna - Removal / Installation**							RE (O/C)			
25 A/F			0				Mos	20-Nov-2022				
	110-340	New	0				Hrs	0				
	666211		0				Ldg	0				
	ATA Ref::25-61-01, Mfg#:25-61-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
256119		**Life Raft - Removal / Installation**							RE (O/C)			
	25 A/F	No.1	0				Mos	21-Feb-2023				
	57FPSA-HK4-1-907	New	0				Hrs	28				
	5PA-00705		0				Ldg	8				
256120		**Life Raft - Removal / Installation**							RE (O/C)			
	25 A/F	No.2	0				Mos	18-Feb-2023				
	46FPSA-1K4-1908	New	0				Hrs	28				
	4PA-00401		0				Ldg	8				
256121		**Life Raft - Removal / Installation**							RE (O/C)			
	25 A/F	No.3	0				Mos	18-Feb-2023				
	57FPSA-HK5-1-912	New	0				Hrs	28				
	5PA-00706		0				Ldg	8				
256135		**Emergency Locator Transmitter (Life Raft) - Removal / Installation**							RE (O/C)			
	25 A/F	No.1	0				Mos	18-Feb-2023				
	500-32-2Y-HA	New	0				Hrs	28				
	13905		0				Ldg	8				
256137		**Emergency Locator Transmitter (Life Raft) - Removal / Installation**							RE (O/C)			
	25 A/F	No.3	0				Mos	18-Feb-2023				
	500-32-2Y-HA	New	0				Hrs	28				
	13916		0				Ldg	8				
256142		**Emergency Locator Transmitter (Life Raft) Battery - Removal / Installation**							RE (O/C)			
	25 A/F	No.1	0				Mos	18-Feb-2023				
	500-32-2Y-HA	New	0				Hrs	28				
	13905		0				Ldg	8				
256143		**Emergency Locator Transmitter (Life Raft) Battery - Removal / Installation**							RE (O/C)			
	25 A/F	No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
256144		**Emergency Locator Transmitter (Life Raft) Battery - Removal / Installation**							RE (O/C)			
	25 A/F	No.3	0				Mos	18-Feb-2023				
	500-32-2Y-HA	New	0				Hrs	28				
	13916		0				Ldg	8				
256203		**Life Vest - Removal / Installation**							RE (O/C)			
	25 A/F	Pilot	6				Mos	10-Feb-2023				
	63600-505						Hrs	24:24				
	L5553372						Ldg	7				
	ATA Ref::25-62-01, Mfg#:25-62-01											
256204		**Life Vest - Removal / Installation**							RE (O/C)			
	25 A/F	Copilot	6				Mos	10-Feb-2023				
	63600-505						Hrs	24:24				
	L5553373						Ldg	7				
	ATA Ref::25-62-01, Mfg#:25-62-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
256209		**Life Vest - Removal / Installation**							RE (O/C)			
	25 A/F	3rd Crewmember	6				Mos	10-Feb-2023				
	63600-505						Hrs	24:24				
	L5553375						Ldg	7				
	ATA Ref::25-62-01, Ref#:25-62-01											
256231		**Life Vest - Removal / Installation**							RE (O/C)			
	25 A/F	Left No.1	7				Mos	10-Feb-2023				
	63600-105						Hrs	24:24				
	L5530635						Ldg	7				
	ATA Ref::25-62-01, Mfg#:25-62-01											
256232		**Life Vest - Removal / Installation**							RE (O/C)			
	25 A/F	Right No.1	4				Mos	10-Feb-2023				
	63600-105						Hrs	24:24				
	L5611822						Ldg	7				
	ATA Ref::25-62-01, Mfg#:25-62-01											
256233		**Life Vest - Removal / Installation**							RE (O/C)			
	25 A/F	Left No.2	7				Mos	10-Feb-2023				
	63600-105						Hrs	24:24				
	L5530660						Ldg	7				
	ATA Ref::25-62-01, Mfg#:25-62-01											
256234		**Life Vest - Removal / Installation**							RE (O/C)			
	25 A/F	Right No.2	4				Mos	10-Feb-2023				
	63600-105						Hrs	24:24				
	L5611823						Ldg	7				
	ATA Ref::25-62-01, Mfg#:25-62-01											
256235		**Life Vest - Removal / Installation**							RE (O/C)			
	25 A/F	Left No.3	7				Mos	10-Feb-2023				
	63600-105						Hrs	24:24				
	L5530661						Ldg	7				
	ATA Ref::25-62-01, Ref#:25-62-01											
256236		**Life Vest - Removal / Installation**							RE (O/C)			
	25 A/F	Right No.3	7				Mos	10-Feb-2023				
	63600-105						Hrs	24:24				
	L5530662						Ldg	7				
	ATA Ref::25-62-01, Ref#:25-62-01											
256237		**Life Vest - Removal / Installation**							RE (O/C)			
	25 A/F	Left No.4	7				Mos	10-Feb-2023				
	63600-105						Hrs	24:24				
	L5530668						Ldg	7				
	ATA Ref::25-62-01, Ref#:25-62-01											
256238		**Life Vest - Removal / Installation**							RE (O/C)			
	25 A/F	Right No.4	4				Mos	10-Feb-2023				
	63600-105						Hrs	24:24				
	L5611821						Ldg	7				
	ATA Ref::25-62-01, Ref#:25-62-01											
256239		**Life Vest - Removal / Installation**							RE (O/C)			
	25 A/F	Left No.5					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::25-62-01, Ref#:25-62-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
256240		**Life Vest - Removal / Installation**							RE (O/C)			
	25 A/F	Right No.5					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::25-62-01, Ref#:25-62-01											
256243		**Life Vest - Removal / Installation**							RE (O/C)			
	25 A/F	Divan - Fwd		4			Mos	10-Feb-2023				
	63600-105						Hrs	24:24				
	L5611851						Ldg	7				
	ATA Ref::25-62-01, Mfg#:25-62-01											
256244		**Life Vest - Removal / Installation**							RE (O/C)			
	25 A/F	Divan - Aft		4			Mos	10-Feb-2023				
	63600-105						Hrs	24:24				
	L5611850						Ldg	7				
	ATA Ref::25-62-01, Mfg#:25-62-01											
256245		**Life Vest - Removal / Installation**							RE (O/C)			
	25 A/F	Divan - Mid		3			Mos	06-Feb-2023				
	63600-105						Hrs	24:24				
	L5611851						Ldg	7				
	ATA Ref::25-62-01, Mfg#:25-62-01											
256246		**Life Vest - Removal / Installation**							RE (O/C)			
	25 A/F	Aft Lavatory					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::25-62-01, Mfg#:25-62-01											
256247		**Conference Group Life Vest (Aft Facing) - Removal / Installation**							RE (O/C)			
	25 A/F	Outboard		6			Mos	06-Feb-2023				
	63600-105						Hrs	24:24				
	L5530662						Ldg	7				
	Mfg#:25-62-01											
256248		**Conference Group Life Vest (Aft Facing) - Removal / Installation**							RE (O/C)			
	25 A/F	Inboard		6			Mos	06-Feb-2023				
	63600-105						Hrs	24:24				
	L5530661						Ldg	7				
	Mfg#:25-62-01											
256249		**Conference Group Life Vest (Fwd Facing) - Removal / Installation**							RE (O/C)			
	25 A/F	Outboard		3			Mos	06-Feb-2023				
	63600-105						Hrs	24:24				
	L5611821						Ldg	7				
	Mfg#:25-62-01											
256250		**Conference Group Life Vest (Fwd Facing) - Removal / Installation**							RE (O/C)			
	25 A/F	Inboard		6			Mos	06-Feb-2023				
	63600-105						Hrs	24:24				
	L5530668						Ldg	7				
	Mfg#:25-62-01											
256402		**First Aid Kit - Removal / Installation**							RE (O/C)			
	25 A/F						Mos	19-Mar-2024			[30-Jun-2025]	9.8 Months
	502950	Modified					Hrs					
	020223004						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
256406	**Emergncy Medical Kit - Removal / Installation**							RE (O/C)			
25 A/F						Mos	20-Nov-2022				
Unknown						Hrs	0				
Unknown						Ldg	0				
256602	**Protective Breathing Equipment (PBE) - Removal / Installation**							RE (O/C)			
25 A/F	No.1	2				Mos	10-Feb-2023				
MR-10051N						Hrs	24:24				
E2207262						Ldg	7				
256605	**Protective Breathing Equipment (PBE) - Removal / Installation**							RE (O/C)			
25 A/F	No.2	3				Mos	10-Feb-2023				
MR-10051N						Hrs	24:24				
E-2206591						Ldg	7				
260002	**Fire Protection Control Unit - Removal / Installation**							RE (O/C)			
26 A/F		0				Mos	20-Nov-2022				
474360-12	New	0				Hrs	0				
AGE9263		0				Ldg	0				
Mfg#:26-00-01											
261105	**Engine Fire Detector Loop Zone 1 Gearbox (Loop A) - Removal / Installation**							RE (O/C)			
26 A/F	Left Engine	2				Mos	08-Feb-2023				
446952-4		24:24				Hrs	24:24				
NSN		7				Ldg	7				
Mfg#:26-11-01-RI											
261106	**Engine Fire Detector Loop Zone 1 Gearbox (Loop B) - Removal / Installation**							RE (O/C)			
26 A/F	Left Engine	2				Mos	08-Feb-2023				
446952-4		24:24				Hrs	24:24				
NSN		7				Ldg	7				
Mfg#:26-11-01-RI											
261107	**Engine Fire Detector Loop Zone 1 Gearbox (Loop A) - Removal / Installation**							RE (O/C)			
26 A/F	Right Engine	2				Mos	27-Jan-2023				
446952-4		24:24				Hrs	24:24				
NSN		7				Ldg	7				
Mfg#:26-11-01-RI											
261108	**Engine Fire Detector Loop Zone 1 Gearbox (Loop B) - Removal / Installation**							RE (O/C)			
26 A/F	Right Engine	2				Mos	27-Jan-2023				
446952-4		24:24				Hrs	24:24				
NSN		7				Ldg	7				
Mfg#:26-11-01-RI											
261113	**Engine Fire Detector Loop Zone 1 Fan Inlet Housing (Loop A) - Removal / Installation**							RE (O/C)			
26 A/F	Left Engine	2				Mos	08-Feb-2023				
446952-3		24:24				Hrs	24:24				
00920221176		7				Ldg	7				
Mfg#:26-11-01-RI											
261114	**Engine Fire Detector Loop Zone 1 Fan Inlet Housing (Loop B) - Removal / Installation**							RE (O/C)			
26 A/F	Left Engine	2				Mos	08-Feb-2023				
446952-3		24:24				Hrs	24:24				
01220196913		7				Ldg	7				
Mfg#:26-11-01-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
261115		**Engine Fire Detector Loop Zone 1 Fan Inlet Housing (Loop A) - Removal / Installation**							RE (O/C)			
26 A/F		Right Engine	2				Mos	27-Jan-2023				
	446952-2		24:24				Hrs	24:24				
	NSN		7				Ldg	7				
	Mfg#:26-11-01-RI											
261116		**Engine Fire Detector Loop Zone 1 Fan Inlet Housing (Loop B) - Removal / Installation**							RE (O/C)			
26 A/F		Right Engine	2				Mos	27-Jan-2023				
	446952-2		24:24				Hrs	24:24				
	NSN		7				Ldg	7				
	Mfg#:26-11-01-RI											
261121		**Fire Detector Loop Zone 1 Pylon (Loop A) - Removal / Installation**							RE (O/C)			
26 A/F		Left	0				Mos	20-Nov-2022				
	446952-3	New	0				Hrs	0				
	00920221176		0				Ldg	0				
	Mfg#:26-11-01-RI											
261122		**Fire Detector Loop Zone 1 Pylon (Loop B) - Removal / Installation**							RE (O/C)			
26 A/F		Left	0				Mos	20-Nov-2022				
	446952-3	New	0				Hrs	0				
	01220196913		0				Ldg	0				
	Mfg#:26-11-01-RI											
261123		**Fire Detector Loop Zone 1 Pylon (Loop A) - Removal / Installation**							RE (O/C)			
26 A/F		Right	0				Mos	20-Nov-2022				
	446952-3	New	0				Hrs	0				
	01120208518		0				Ldg	0				
	Mfg#:26-11-01-RI											
261124		**Fire Detector Loop Zone 1 Pylon (Loop B) - Removal / Installation**							RE (O/C)			
26 A/F		Right	0				Mos	20-Nov-2022				
	446952-3	New	0				Hrs	0				
	01220208518		0				Ldg	0				
	Mfg#:26-11-01-RI											
261129		**Engine Fire Detector Loop Zone 2 (Loop A) - Removal / Installation**							RE (O/C)			
26 A/F		Left Engine					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-11-01-RI											
261130		**Engine Fire Detector Loop Zone 2 (Loop B) - Removal / Installation**							RE (O/C)			
26 A/F		Left Engine					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-11-01-RI											
261131		**Engine Fire Detector Loop Zone 2 (Loop A) - Removal / Installation**							RE (O/C)			
26 A/F		Right Engine					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-11-01-RI											
261132		**Engine Fire Detector Loop Zone 2 (Loop B) - Removal / Installation**							RE (O/C)			
26 A/F		Right Engine					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-11-01-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
261205		**APU Fire Detector Loop (Loop A) - Removal / Installation**							RE (O/C)			
26 A/F			0				Mos	20-Nov-2022				
	446952-5	New	0				Hrs	0				
	8143-007		0				Ldg	0				
	Mfg#:26-12-01-RI											
261206		**APU Fire Detector Loop (Loop B) - Removal / Installation**							RE (O/C)			
26 A/F			0				Mos	20-Nov-2022				
	446952-5	New	0				Hrs	0				
	8918-002		0				Ldg	0				
	Mfg#:26-12-01-RI											
261208		**APU Crew Warning Horn - Removal / Installation**							RE (O/C)			
26 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-12-02											
261302		**Baggage Compartment Smoke Detector - Removal / Installation**							RE (O/C)			
26 A/F			0				Mos	20-Nov-2022				
	473597-30	New	0				Hrs	0				
	SKA0163		0				Ldg	0				
	Mfg#:26-13-01											
261404		**Bleed Leak Sensor (120W) - Removal / Installation**							RE (O/C)			
26 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-14-01											
261405		**Bleed Leak Sensor (122W) - Removal / Installation**							RE (O/C)			
26 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-14-01											
261406		**Bleed Leak Sensor (124W) - Removal / Installation**							RE (O/C)			
26 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-14-01											
261410		**Bleed Leak Sensor (121W) - Removal / Installation**							RE (O/C)			
26 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-14-02											
261411		**Bleed Leak Sensor (123W) - Removal / Installation**							RE (O/C)			
26 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-14-02											
261412		**Bleed Leak Sensor (125W) - Removal / Installation**							RE (O/C)			
26 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-14-02											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
261416		**Bleed Air Duct Leak Sensor (110W) - Removal / Installation**							RE (O/C)			
	26 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-14-03											
261417		**Bleed Air Duct Leak Sensor (112W) - Removal / Installation**							RE (O/C)			
	26 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-14-03											
261418		**Bleed Air Duct Leak Sensor (114W) - Removal / Installation**							RE (O/C)			
	26 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-14-03											
261421		**Bleed Air Duct Leak Sensor (113W) - Removal / Installation**							RE (O/C)			
	26 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-14-04											
261422		**Bleed Air Duct Leak Sensor (115W) - Removal / Installation**							RE (O/C)			
	26 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-14-04											
261424		**Bleed Leak Sensor (126W) - Removal / Installation**							RE (O/C)			
	26 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-14-05											
261427		**Bleed Leak Sensor (100W) - Removal / Installation**							RE (O/C)			
	26 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-14-06											
261428		**Bleed Leak Sensor (102W) - Removal / Installation**							RE (O/C)			
	26 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-14-06											
261431		**Bleed Leak Sensor (103W) - Removal / Installation**							RE (O/C)			
	26 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-14-07											
261432		**Bleed Leak Sensor (105W) - Removal / Installation**							RE (O/C)			
	26 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:26-14-07											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
261436		**Bleed Leak Sensor (104W) - Removal / Installation**							RE (O/C)			
26 A/F							Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:26-14-08												
261437		**Bleed Leak Detector (106W) - Removal / Installation**							RE (O/C)			
26 A/F			0				Mos	20-Nov-2022				
04-90031-9315A		New	0				Hrs	0				
BZR2222			0				Ldg	0				
Mfg#:26-14-08												
261438		**Bleed Leak Detector (108W) - Removal / Installation**							RE (O/C)			
26 A/F			0				Mos	20-Nov-2022				
04-90031-9274A		New	0				Hrs	0				
BZI1691			0				Ldg	0				
Mfg#:26-14-08												
261442		**Bleed Leak Detector (107W) - Removal / Installation**							RE (O/C)			
26 A/F			0				Mos	20-Nov-2022				
04-90031-9315A		New	0				Hrs	0				
BZR2227			0				Ldg	0				
Mfg#:26-14-09												
261443		**Bleed Leak Detector (109W) - Removal / Installation**							RE (O/C)			
26 A/F							Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Ref#:26-14-09												
261444		**Bleed Leak Sensor (111W) - Removal / Installation**							RE (O/C)			
26 A/F			0				Mos	20-Nov-2022				
04-90031-9274A		New	0				Hrs	0				
BZI3252			0				Ldg	0				
Mfg#:26-14-09												
261447		**Bleed Leak Sensor (116W) - Removal / Installation**							RE (O/C)			
26 A/F							Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:26-14-10												
261448		**Bleed Leak Sensor (118W) - Removal / Installation**							RE (O/C)			
26 A/F							Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:26-14-10												
261451		**Bleed Leak Sensor (117W) - Removal / Installation**							RE (O/C)			
26 A/F							Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:26-14-11												
261452		**Bleed Leak Sensor (119W) - Removal / Installation**							RE (O/C)			
26 A/F							Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:26-14-11												

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
262113		**Fire Extinguishing Bottle - Removal / Installation**							RE (O/C)			
26 A/F	474789-2	Left	9				Mos	20-Nov-2022				
	AGF7198						Hrs	0				
	Mfg#:26-21-01-RI						Ldg	0				
262114		**Fire Extinguishing Bottle - Removal / Installation**							RE (O/C)			
26 A/F	474789-1	Right	9				Mos	20-Nov-2022				
	AGF7193						Hrs	0				
	Mfg#:26-21-01-RI						Ldg	0				
262127		**Fire Extinguishing Bottle Cartridge (Left Cartridge) - Removal / Installation**							RE (O/C)			
26 A/F	446582-3	Left Bottle	11				Mos	20-Nov-2022				
	AGE0730						Hrs	0				
	Mfg#:26-21-02-RI						Ldg	0				
262128		**Fire Extinguishing Bottle Cartridge (Right Cartridge) - Removal / Installation**							RE (O/C)			
26 A/F	446582-2	Left Bottle	11				Mos	20-Nov-2022				
	AGF0488						Hrs	0				
	Mfg#:26-21-02-RI						Ldg	0				
262129		**Fire Extinguishing Bottle Cartridge (Left Cartridge) - Removal / Installation**							RE (O/C)			
26 A/F	446582-3	Right Bottle	11				Mos	20-Nov-2022				
	AGE0735						Hrs	0				
	Mfg#:26-21-02-RI						Ldg	0				
262130		**Fire Extinguishing Bottle Cartridge (Right Cartridge) - Removal / Installation**							RE (O/C)			
26 A/F	446582-2	Right Bottle	11				Mos	20-Nov-2022				
	AGF0499						Hrs	0				
	Mfg#:26-21-02-RI						Ldg	0				
262131		**Fire Extinguishing Bottle Cartridge (APU Cartridge) - Removal / Installation**							RE (O/C)			
26 A/F	446582-1	Right Bottle	11				Mos	20-Nov-2022				
	AGE1742						Hrs	0				
	Mfg#:26-21-02-RI						Ldg	0				
262143		**Engine Fire Shut-Off Handle - Removal / Installation**							RE (O/C)			
26 A/F	D533-53-001	Left New	0				Mos	20-Nov-2022				
	5355795		0				Hrs	0				
	Mfg#:26-21-03		0				Ldg	0				
262144		**Engine Fire Shut-Off Handle - Removal / Installation**							RE (O/C)			
26 A/F	D533-54-001	Right New	0				Mos	20-Nov-2022				
	5431847		0				Hrs	0				
	Mfg#:26-21-03		0				Ldg	0				
262204		**Baggage Compartment Isolation Valve - Removal / Installation**							RE (O/C)			
26 A/F	327965						Mos	10-Feb-2023				
	0776						Hrs	24:24				
	Mfg#:26-22-01						Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
262206		**Baggage Compartment Dump Valve - Removal / Installation**							RE (O/C)			
26 A/F			0				Mos	20-Nov-2022				
	327965	New	0				Hrs	0				
	0771		0				Ldg	0				
	Mfg#:26-22-02											
262304		**Two-way Check Valve - Removal / Installation**							RE (O/C)			
26 A/F		Left	0				Mos	20-Nov-2022				
	446651	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:26-23-01											
262306		**Two-way Check Valve - Removal / Installation**							RE (O/C)			
26 A/F		Right	0				Mos	20-Nov-2022				
	446651	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:26-23-01											
262402		**Portable Fire Extinguisher - Removal / Installation**							RE (O/C)			
26 A/F		Cockpit	9				Mos	10-Feb-2023				
	347TS		0				Hrs	24:24				
	G-98646801		0				Ldg	7				
	Mfg#:26-24-01-RI (SOURCE: 26-24-01)											
262412		**Portable Fire Extinguisher - Removal / Installation**							RE (O/C)			
26 A/F		Fwd Cabin	3				Mos	10-Feb-2023				
	349TS		0				Hrs	24:24				
	H-11788969		0				Ldg	7				
	Mfg#:26-24-01-RI (SOURCE: 26-24-01)											
262422		**Portable Fire Extinguisher - Removal / Installation**							RE (O/C)			
26 A/F		Aft Cabin	3				Mos	10-Feb-2023				
	351		0				Hrs	24:24				
	H-21682620		0				Ldg	7				
	Mfg#:26-24-01-RI (SOURCE: 26-24-01)											
262432		**Portable Water Fire Extinguisher - Removal / Installation**							RE (O/C)			
26 A/F		Cabin - Left	9				Mos	10-Feb-2023				
	892480						Hrs	24:24				
	47852						Ldg	7				
270003		**Flight Control Electronic Control Unit - Removal / Installation**							RE (O/C)			
27 A/F		No.1	0				Mos	20-Nov-2022				
	CA51642-009	New	0				Hrs	0				
	0680		0				Ldg	0				
	Mfg#:27-00-01											
270004		**Flight Control Electronic Control Unit - Removal / Installation**							RE (O/C)			
27 A/F		No.2	0				Mos	20-Nov-2022				
	CA59117-013	New	0				Hrs	0				
	0680		0				Ldg	0				
	Mfg#:27-00-01											
271117		**Aileron Sliding Control Rod - Removal / Installation**							RE (O/C)			
27 A/F		Left No.1					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
271118		**Aileron Sliding Control Rod - Removal / Installation**							RE (O/C)			
	27 A/F	Right No.1					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271119		**Aileron Sliding Control Rod - Removal / Installation**							RE (O/C)			
	27 A/F	Left No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271120		**Aileron Sliding Control Rod - Removal / Installation**							RE (O/C)			
	27 A/F	Right No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271121		**Aileron Sliding Control Rod - Removal / Installation**							RE (O/C)			
	27 A/F	Left No.3					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271122		**Aileron Sliding Control Rod - Removal / Installation**							RE (O/C)			
	27 A/F	Right No.3					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271127		**Control Wheel - Removal / Installation**							RE (O/C)			
	27 A/F	Pilot	0				Mos	20-Nov-2022				
	FT83912146	New	0				Hrs	0				
	00190		0				Ldg	0				
	Mfg#:27-11-03											
271128		**Control Wheel - Removal / Installation**							RE (O/C)			
	27 A/F	Copilot	0				Mos	20-Nov-2022				
	FT83912047	New	0				Hrs	0				
	00268		0				Ldg	0				
	Mfg#:27-11-03											
271133		**Pilot Control Wheel Sensor - Removal / Installation**							RE (O/C)			
	27 A/F	Left	0				Mos	20-Nov-2022				
	CA55583-001	New	0				Hrs	0				
	0593		0				Ldg	0				
	Mfg#:27-11-04											
271134		**Pilot Control Wheel Sensor - Removal / Installation**							RE (O/C)			
	27 A/F	Right	0				Mos	20-Nov-2022				
	CA55583-001	New	0				Hrs	0				
	0492		0				Ldg	0				
	Mfg#:27-11-04											
271136		**Aileron Disconnect Mechanism - Removal / Installation**							RE (O/C)			
	27 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-05											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
271161		**Aileron Control Rods (Cockpit, Pilot) - Removal / Installation**							RE (O/C)			
27 A/F		Fwd	0				Mos	10-Feb-2023				
30P530014200-501		New	0				Hrs	24:24				
TY439			0				Ldg	7				
Mfg#:27-11-02												
271162		**Aileron Control Rods (Cockpit, Copilot) - Removal / Installation**							RE (O/C)			
27 A/F		Fwd	0				Mos	10-Feb-2023				
30P530014200-501		New	0				Hrs	24:24				
TY440			0				Ldg	7				
Mfg#:27-11-02												
271163		**Aileron Control Rods (Cockpit, Pilot) - Removal / Installation**							RE (O/C)			
27 A/F		Aft					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-11-02												
271164		**Aileron Control Rods (Cockpit, Copilot) - Removal / Installation**							RE (O/C)			
27 A/F		Aft					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-11-02												
271165		**Aileron Control Rods (Autopilot) - Removal / Installation**							RE (O/C)			
27 A/F							Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-11-02												
271166		**Aileron Control Rods (Cabin) - Removal / Installation**							RE (O/C)			
27 A/F		No.1					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-11-02												
271167		**Aileron Control Rods (Cabin) - Removal / Installation**							RE (O/C)			
27 A/F		No.2					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-11-02												
271168		**Aileron Control Rods (Cabin) - Removal / Installation**							RE (O/C)			
27 A/F		No.3					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-11-02												
271169		**Aileron Control Rods (Cabin) - Removal / Installation**							RE (O/C)			
27 A/F		No.4					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-11-02												
271170		**Aileron Control Rods (Cabin to Wing) - Removal / Installation**							RE (O/C)			
27 A/F							Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-11-02												

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
271171		**Aileron Control Rods (Pilot Fuselage to Wing) - Removal / Installation**							RE (O/C)			
	27 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271172		**Aileron Control Rods (Copilot Fuselage to Wing) - Removal / Installation**							RE (O/C)			
	27 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271173		**Aileron Control Rods (Wing) - Removal / Installation**							RE (O/C)			
	27 A/F	Left No.1					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271174		**Aileron Control Rods (Wing) - Removal / Installation**							RE (O/C)			
	27 A/F	Right No.1					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271175		**Aileron Control Rods (Wing) - Removal / Installation**							RE (O/C)			
	27 A/F	Left No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271176		**Aileron Control Rods (Wing) - Removal / Installation**							RE (O/C)			
	27 A/F	Right No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271177		**Aileron Control Rods (Wing) - Removal / Installation**							RE (O/C)			
	27 A/F	Left No.3					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271178		**Aileron Control Rods (Wing) - Removal / Installation**							RE (O/C)			
	27 A/F	Right No.3					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271179		**Aileron Control Rods (Wing) - Removal / Installation**							RE (O/C)			
	27 A/F	Left No.4					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271180		**Aileron Control Rods (Wing) - Removal / Installation**							RE (O/C)			
	27 A/F	Right No.4					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
271181		**Aileron Control Rods (Wing Tunnel) - Removal / Installation**							RE (O/C)			
	27 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271182		**Aileron Control Rods (Wing Tunnel) - Removal / Installation**							RE (O/C)			
	27 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271189		**Aileron Control Bellcranks (Leading Edge) - Removal / Installation**							RE (O/C)			
	27 A/F	Left Inboard					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271190		**Aileron Control Bellcranks (Leading Edge) - Removal / Installation**							RE (O/C)			
	27 A/F	Right Inboard					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271191		**Aileron Control Bellcranks (Leading Edge) - Removal / Installation**							RE (O/C)			
	27 A/F	Left Outboard					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271192		**Aileron Control Bellcranks (Leading Edge) - Removal / Installation**							RE (O/C)			
	27 A/F	Right Outboard					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271193		**Aileron Control Bellcranks (Left Aft) - Removal / Installation**							RE (O/C)			
	27 A/F	Left Aft					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271194		**Aileron Control Bellcranks (Right Aft) - Removal / Installation**							RE (O/C)			
	27 A/F	Right Aft					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271197		**Aileron Actuating Link - Removal / Installation**							RE (O/C)			
	27 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											
271198		**Aileron Actuating Link - Removal / Installation**							RE (O/C)			
	27 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-11-02											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
271202		**Aileron Trim Actuator - Removal / Installation**							RE (O/C)			
	27 A/F		0				Mos	20-Nov-2022				
	CA51121-002	New	0				Hrs	0				
	B0145		0				Ldg	0				
	Mfg#:27-12-01											
271206		**Aileron Trim Switch - Removal / Installation**							RE (O/C)			
	27 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-12-02											
271303		**Aileron - Removal / Installation**							RE (O/C)			
	27 A/F	Left	1				Mos	19-Jan-2023				
	30P181000008-501		22:54				Hrs	22:54				
	0031		6				Ldg	6				
	Mfg#:27-13-01-RI											
271304		**Aileron - Removal / Installation**							RE (O/C)			
	27 A/F	Right	1				Mos	19-Jan-2023				
	30P181200008-501		22:54				Hrs	22:54				
	RH-0020		6				Ldg	6				
	Mfg#:27-13-01-RI											
271312		**Aileron Trim Tab - Removal / Installation**							RE (O/C)			
	27 A/F		0				Mos	20-Nov-2022				
	30P181120000-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:27-13-02											
271323		**Aileron Gear Tab - Removal / Installation**							RE (O/C)			
	27 A/F	Left	0				Mos	20-Nov-2022				
	30P181130000-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:27-13-03											
271324		**Aileron Gear Tab - Removal / Installation**							RE (O/C)			
	27 A/F	Right	0				Mos	20-Nov-2022				
	30P181130000-502	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:27-13-03											
271403		**Aileron Position Sensor - Removal / Installation**							RE (O/C)			
	27 A/F	Left	0				Mos	20-Nov-2022				
	CA57245-001	New	0				Hrs	0				
	A1701		0				Ldg	0				
	Mfg#:27-14-01-RI											
271404		**Aileron Position Sensor - Removal / Installation**							RE (O/C)			
	27 A/F	Right	0				Mos	20-Nov-2022				
	CA57245-001	New	0				Hrs	0				
	A1709		0				Ldg	0				
	Mfg#:27-14-01-RI											
271405		**Aileron Control Position Potentiometer - Removal / Installation**							RE (O/C)			
	27 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-14-01-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
271406		**Aileron Control Potentiometer (Below Cockpit Floor) - Removal / Installation**							RE (O/C)			
27 A/F		Cockpit					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
272103		**Rudder Servo Actuator (No. 2) - Removal / Installation**							RE (O/C)			
27 A/F		Top					Mos	26-Jul-2024				
CA43143-004		Repaired				0	Hrs	967:25				
B0696						0	Ldg	562				
Mfg#:27-21-01-RI												
272104		**Rudder Servo Actuator (No. 1) - Removal / Installation**							RE (O/C)			
27 A/F		Bottom					Mos	26-Jul-2024				
CA43143-004		Repaired				0	Hrs	967:25				
B0697						0	Ldg	562				
Mfg#:27-21-01-RI												
272110		**Rudder Feel and Trim Unit Assembly - Removal / Installation**							RE (O/C)			
27 A/F			0				Mos	20-Nov-2022				
CA51480-003		New	0				Hrs	0				
B0153			0				Ldg	0				
Mfg#:27-21-02-RI												
272114		**Rudder Pedal Feedback Actuator - Removal / Installation**							RE (O/C)			
27 A/F							Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-21-02-RI												
272119		**Rudder Pedal LVDT - Removal / Installation**							RE (O/C)			
27 A/F		No.1					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-21-02-RI												
272120		**Rudder Pedal LVDT - Removal / Installation**							RE (O/C)			
27 A/F		No.2					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-21-02-RI												
272121		**Rudder Pedal LVDT - Removal / Installation**							RE (O/C)			
27 A/F		No.3					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-21-02-RI												
272122		**Rudder Pedal LVDT - Removal / Installation**							RE (O/C)			
27 A/F		No.4					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-21-02-RI												
272129		**Rudder Pedal Assembly (Pilot) - Removal / Installation**							RE (O/C)			
27 A/F		Left					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-21-03-RI												

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
272130		**Rudder Pedal Assembly (Pilot) - Removal / Installation**							RE (O/C)			
27 A/F		Right					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-21-03-RI												
272131		**Rudder Pedal Assembly (Copilot) - Removal / Installation**							RE (O/C)			
27 A/F		Left					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-21-03-RI												
272132		**Rudder Pedal Assembly (Copilot) - Removal / Installation**							RE (O/C)			
27 A/F		Right					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-21-03-RI												
272139		**Rudder Pedal (Pilot) - Removal / Installation**							RE (O/C)			
27 A/F		Left					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-21-03-RI												
272140		**Rudder Pedal (Pilot) - Removal / Installation**							RE (O/C)			
27 A/F		Right					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-21-03-RI												
272141		**Rudder Pedal (Copilot) - Removal / Installation**							RE (O/C)			
27 A/F		Left					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-21-03-RI												
272142		**Rudder Pedal (Copilot) - Removal / Installation**							RE (O/C)			
27 A/F		Right					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-21-03-RI												
272202		**Rudder Trim Switch - Removal / Installation**							RE (O/C)			
27 A/F							Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-22-01												
272302		**Rudder Control Surface - Removal / Installation**							RE (O/C)			
27 A/F			0				Mos	20-Nov-2022				
30P420000002-501		New	0				Hrs	0				
2253			0				Ldg	0				
Mfg#:27-23-01-RI												
273117		**Pilot Elevator Control Cable - Removal / Installation**							RE (O/C)			
27 A/F		Fwd					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:27-31-01												

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
273118		**Copilot Elevator Control Cable - Removal / Installation**							RE (O/C)			
	27 A/F	Fwd					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-31-01											
273119		**Pilot Elevator Control Cable - Removal / Installation**							RE (O/C)			
	27 A/F	Center					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-31-01											
273120		**Copliot Elevator Control Cable - Removal / Installation**							RE (O/C)			
	27 A/F	Center					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-31-01											
273121		**Pilot Elevator Control Cable - Removal / Installation**							RE (O/C)			
	27 A/F	Aft					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-31-01											
273122		**Copilot Elevator Control Cable - Removal / Installation**							RE (O/C)			
	27 A/F	Aft					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-31-01											
273127		**Elevator Cable Tension Regulator - Removal / Installation**							RE (O/C)			
	27 A/F	Pilot					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-31-01											
273128		**Elevator Cable Tension Regulator - Removal / Installation**							RE (O/C)			
	27 A/F	Copilot					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-31-01											
273133		**Control Column - Removal / Installation**							RE (O/C)			
	27 A/F	Pilot					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-31-03-RI											
273134		**Control Column - Removal / Installation**							RE (O/C)			
	27 A/F	Copilot					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-31-03-RI											
273137		**Elevator Dual Servo Actuator - Removal / Installation**							RE (O/C)			
	27 A/F	Left	0				Mos	20-Nov-2022				
	CA49494-004	New	0				Hrs	0				
	B0590		0				Ldg	0				
	Mfg#:27-31-04-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
273138		**Elevator Dual Servo Actuator - Removal / Installation**							RE (O/C)			
27 A/F		Right	0				Mos	20-Nov-2022				
	CA50298-004	New	0				Hrs	0				
	B0632		0				Ldg	0				
	Mfg#:27-31-04-RI											
273161		**Elevator Control Rod - Removal / Installation**							RE (O/C)			
27 A/F		Left	0				Mos	10-Feb-2023				
	30P530014100-501	New	0				Hrs	24:24				
	TY436		0				Ldg	7				
273162		**Elevator Control Rod - Removal / Installation**							RE (O/C)			
27 A/F		Right	0				Mos	10-Feb-2023				
	30P530014100-501	New	0				Hrs	24:24				
	TY131		0				Ldg	7				
273203		**Elevator Control Surface - Removal / Installation**							RE (O/C)			
27 A/F		Left	0				Mos	20-Nov-2022				
	30P460100002-501	New	0				Hrs	0				
	2253		0				Ldg	0				
	Mfg#:27-32-01											
273204		**Elevator Control Surface - Removal / Installation**							RE (O/C)			
27 A/F		Right	0				Mos	20-Nov-2022				
	30P460100002-502	New	0				Hrs	0				
	2253		0				Ldg	0				
	Mfg#:27-32-01											
273303		**Elevator Artificial Feel Spring - Removal / Installation**							RE (O/C)			
27 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-33-01											
273304		**Elevator Artificial Feel Spring - Removal / Installation**							RE (O/C)			
27 A/F		Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-33-01											
273306		**Q-feel Actuator - Removal / Installation**							RE (O/C)			
27 A/F			0				Mos	20-Nov-2022				
	4012-MOD/A	New	0				Hrs	0				
	IL-562		0				Ldg	0				
	Mfg#:27-33-02											
273310		**Q-feel Spring - Removal / Installation**							RE (O/C)			
27 A/F			0				Mos	20-Nov-2022				
	4AS5320430-511	New	0				Hrs	0				
	261		0				Ldg	0				
	Mfg#:27-33-03											
273312		**Q-feel Shut-off Valve - Removal / Installation**							RE (O/C)			
27 A/F			0				Mos	20-Nov-2022				
	6920-3	New	0				Hrs	0				
	0825		0				Ldg	0				
	Mfg#:27-33-04											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
273402		**Force Disconnect Unit - Removal / Installation**							RE (O/C)			
27 A/F			0				Mos	20-Nov-2022				
	C64895-004	New	0				Hrs	0				
	B0168		0				Ldg	0				
	Mfg#:27-34-01											
273405		**Force Sensor Assembly - Removal / Installation**							RE (O/C)			
27 A/F		Left					Mos	05-May-2023				
	FT12108-3						Hrs	142:54				
	1372						Ldg	81				
	Mfg#:27-34-02											
273406		**Force Sensor Assembly- Removal / Installation**							RE (O/C)			
27 A/F		Right					Mos	05-May-2023				
	FT12108-3						Hrs	142:54				
	1382						Ldg	81				
	Mfg#:27-34-02											
273413		**Eddy Current Damper - Removal / Installation**							RE (O/C)			
27 A/F			0				Mos	20-Nov-2022				
	CZ09609025	New	0				Hrs	0				
	0269		0				Ldg	0				
	Mfg#:27-34-03											
273422		**Force Sensor Demodulator - Removal / Installation**							RE (O/C)			
27 A/F			0				Mos	20-Nov-2022				
	GA12295-1	New	0				Hrs	0				
	2311		0				Ldg	0				
	Mfg#:27-34-04											
273503		**Stick Shaker - Removal / Installation**							RE (O/C)			
27 A/F		Left	0				Mos	20-Nov-2022				
	0050P	New	0				Hrs	0				
	1812		0				Ldg	0				
	Mfg#:27-35-01											
273504		**Stick Shaker - Removal / Installation**							RE (O/C)			
27 A/F		Right	0				Mos	20-Nov-2022				
	0050P	New	0				Hrs	0				
	1830		0				Ldg	0				
	Mfg#:27-35-01											
273511		**Elevator Control Position Potentiometer - Removal / Installation**							RE (O/C)			
27 A/F		Pilot	0				Mos	10-Feb-2023				
	4AS5300152-001	New	0				Hrs	24:24				
	1192		0				Ldg	7				
	Mfg#:27-31-03-RI											
273512		**Elevator Control Position Potentiometer - Removal / Installation**							RE (O/C)			
27 A/F		Copilot					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-31-03-RI											
274104		**Horizontal Stabilizer Trim Actuator - Removal / Installation**							RE (O/C)			
27 A/F			0				Mos	20-Nov-2022				
	CA51580-006	New	0				Hrs	0				
	0265		0				Ldg	0				
	Mfg#:27-41-01-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
274106		**Horizontal Stabilizer Trim Actuator Primary Motor with Brake - Removal / Installation**							RE (O/C)			
	27 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-41-01-RI											
274108		**Horizontal Stabilizer Trim Actuator Secondary Motor - Removal / Installation**							RE (O/C)			
	27 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-41-01-RI											
274113		**Horizontal Stabilizer Trim Actuator LVDT Position Sensor (Primary) - Removal / Installation**							RE (O/C)			
	27 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-41-01-RI											
274114		**Horizontal Stabilizer Trim Actuator LVDT Position Sensor (Secondary) - Removal / Installation**							RE (O/C)			
	27 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-41-01-RI											
274120		**Horizontal Stabilizer Motor Control Unit - Removal / Installation**							RE (O/C)			
	27 A/F		0				Mos	20-Nov-2022				
	CA51640-006	New	0				Hrs	0				
	270		0				Ldg	0				
	Mfg#:27-41-02											
274123		**Horizontal Trim Switch - Removal / Installation**							RE (O/C)			
	27 A/F	Pilot	0				Mos	20-Nov-2022				
	83460205	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:27-41-03											
274124		**Horizontal Trim Switch - Removal / Installation**							RE (O/C)			
	27 A/F	Copilot	0				Mos	20-Nov-2022				
	83460205	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:27-41-03											
275102		**Flap Handle Control Module - Removal / Installation**							RE (O/C)			
	27 A/F		0				Mos	20-Nov-2022				
	4260-0045-1	New	0				Hrs	0				
	252254		0				Ldg	0				
	Mfg#:27-51-01-RI											
275107		**Flap Actuator - Removal / Installation**							RE (O/C)			
	27 A/F	Left Inboard	0				Mos	20-Nov-2022				
	C64897-003	New	0				Hrs	0				
	B0356A		0				Ldg	0				
	Mfg#:27-51-02-RI											
275108		**Flap Actuator - Removal / Installation**							RE (O/C)			
	27 A/F	Right Inboard	0				Mos	20-Nov-2022				
	C64897-003	New	0				Hrs	0				
	B0361A		0				Ldg	0				
	Mfg#:27-51-02-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
275109		**Flap Actuator - Removal / Installation**							RE (O/C)			
	27 A/F	Left Outboard	0				Mos	20-Nov-2022				
	C64899-003	New	0				Hrs	0				
	B0181A		0				Ldg	0				
	Mfg#:27-51-02-RI											
275110		**Flap Actuator - Removal / Installation**							RE (O/C)			
	27 A/F	Right Outboard	0				Mos	20-Nov-2022				
	C64899-004	New	0				Hrs	0				
	B0181A		0				Ldg	0				
	Mfg#:27-51-02-RI											
275135		**Flap Driveshaft Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Left No.1	0				Mos	20-Nov-2022				
	CA66621-011	New	0				Hrs	0				
	0531		0				Ldg	0				
	ATA Ref::27-51-03, Mfg#:27-51-03-RI											
275136		**Flap Driveshaft Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Right No.1	0				Mos	20-Nov-2022				
	CA66621-011	New	0				Hrs	0				
	0541		0				Ldg	0				
	ATA Ref::27-51-03, Mfg#:27-51-03-RI											
275137		**Flap Driveshaft Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Left No.2	0				Mos	20-Nov-2022				
	CA66621-012	New	0				Hrs	0				
	1006		0				Ldg	0				
	ATA Ref::27-51-03, Mfg#:27-51-03-RI											
275138		**Flap Driveshaft Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Right No.2	0				Mos	20-Nov-2022				
	CA66621-012	New	0				Hrs	0				
	1028		0				Ldg	0				
	ATA Ref::27-51-03, Mfg#:27-51-03-RI											
275139		**Flap Driveshaft Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Left No.3	0				Mos	20-Nov-2022				
	CA66621-013	New	0				Hrs	0				
	0458		0				Ldg	0				
	ATA Ref::27-51-03, Mfg#:27-51-03-RI											
275140		**Flap Driveshaft Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Right No.3	0				Mos	20-Nov-2022				
	CA66621-013	New	0				Hrs	0				
	0492		0				Ldg	0				
	ATA Ref::27-51-03, Mfg#:27-51-03-RI											
275141		**Flap Driveshaft Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Left No.4	0				Mos	20-Nov-2022				
	CA66621-014	New	0				Hrs	0				
	0526		0				Ldg	0				
	ATA Ref::27-51-03, Mfg#:27-51-03-RI											
275142		**Flap Driveshaft Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Right No.4	0				Mos	20-Nov-2022				
	CA66621-014	New	0				Hrs	0				
	0528		0				Ldg	0				
	ATA Ref::27-51-03, Mfg#:27-51-03-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
275143		**Flap Driveshaft Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Left No.5	0				Mos	20-Nov-2022				
	CA66621-015	New	0				Hrs	0				
	1034		0				Ldg	0				
	ATA Ref::27-51-03, Mfg#:27-51-03-RI											
275144		**Flap Driveshaft Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Right No.5	0				Mos	20-Nov-2022				
	CA66621-015	New	0				Hrs	0				
	1045		0				Ldg	0				
	ATA Ref::27-51-03, Mfg#:27-51-03-RI											
275145		**Flap Driveshaft Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Left No.6	0				Mos	20-Nov-2022				
	CA66621-015	New	0				Hrs	0				
	1044		0				Ldg	0				
	ATA Ref::27-51-03, Mfg#:27-51-03-RI											
275146		**Flap Driveshaft Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Right No.6	0				Mos	20-Nov-2022				
	CA66621-015	New	0				Hrs	0				
	1061		0				Ldg	0				
	ATA Ref::27-51-03, Mfg#:27-51-03-RI											
275147		**Flap Driveshaft Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Left No.7	0				Mos	20-Nov-2022				
	CA66621-012	New	0				Hrs	0				
	1007		0				Ldg	0				
	ATA Ref::27-51-03, Mfg#:27-51-03-RI											
275148		**Flap Driveshaft Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Right No.7	0				Mos	20-Nov-2022				
	CA66621-012	New	0				Hrs	0				
	1056		0				Ldg	0				
	ATA Ref::27-51-03, Mfg#:27-51-03-RI											
275161		**Pillow Block Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Left No.1					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-51-04, Mfg#:27-51-04-RI											
275162		**Pillow Block Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Right No.1					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-51-04, Mfg#:27-51-04-RI											
275163		**Pillow Block Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Left No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-51-04, Mfg#:27-51-04-RI											
275164		**Pillow Block Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Right No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-51-04, Mfg#:27-51-04-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
275165		**Pillow Block Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Left No.3					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-51-04, Mfg#:27-51-04-RI											
275166		**Pillow Block Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Right No.3					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-51-04, Mfg#:27-51-04-RI											
275167		**Pillow Block Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Left No.4					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-51-04, Mfg#:27-51-04-RI											
275168		**Pillow Block Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Right No.4					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-51-04, Mfg#:27-51-04-RI											
275169		**Pillow Block Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Left No.5					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-51-04, Mfg#:27-51-04-RI											
275170		**Pillow Block Assemblies - Removal / Installation**							RE (O/C)			
	27 A/F	Right No.5					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-51-04, Mfg#:27-51-04-RI											
275202		**Flap Power Drive Unit - Removal / Installation**							RE (O/C)			
	27 A/F		0				Mos	20-Nov-2022				
	C64903-001	New	0				Hrs	0				
	0284		0				Ldg	0				
	ATA Ref::27-52-01, Mfg#:27-52-01											
275204		**Flap Hydraulic Control Module - Removal / Installation**							RE (O/C)			
	27 A/F		0				Mos	20-Nov-2022				
	CA53511-005	New	0				Hrs	0				
	B0394		0				Ldg	0				
	ATA Ref::27-52-02, Mfg#:27-52-02											
275303		**Wing Flap Assembly - Removal / Installation**							RE (O/C)			
	27 A/F	Left	0				Mos	20-Nov-2022				
	30P191000017-501	New	0				Hrs	0				
	K0040		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275304		**Wing Flap Assembly - Removal / Installation**							RE (O/C)			
	27 A/F	Right	0				Mos	20-Nov-2022				
	30P191000017-502	New	0				Hrs	0				
	K0040		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
275325		**Flap Track Roller Assemblies (Track A) - Removal / Installation**							RE (O/C)			
27 A/F		Left Inboard	0				Mos	20-Nov-2022				
	30P191300000-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275326		**Flap Track Roller Assemblies (Track A) - Removal / Installation**							RE (O/C)			
27 A/F		Left Outboard	0				Mos	20-Nov-2022				
	30P191310002-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:27-53-01-RI											
275327		**Flap Track Roller Assemblies (Track B) - Removal / Installation**							RE (O/C)			
27 A/F		Left Inboard	0				Mos	20-Nov-2022				
	30P191330000-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275328		**Flap Track Roller Assemblies (Track B, Forward) - Removal / Installation**							RE (O/C)			
27 A/F		Left Outboard	0				Mos	20-Nov-2022				
	30P191340000-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275329		**Flap Track Roller Assemblies (Track B, Aft) - Removal / Installation**							RE (O/C)			
27 A/F		Left Outboard	0				Mos	20-Nov-2022				
	30P191320001-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275330		**Flap Track Roller Assemblies (Track C, Forward) - Removal / Installation**							RE (O/C)			
27 A/F		Left Inboard	0				Mos	20-Nov-2022				
	30P191360000-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275331		**Flap Track Roller Assemblies (Track C, Aft) - Removal / Installation**							RE (O/C)			
27 A/F		Left Inboard	0				Mos	20-Nov-2022				
	30P191350001-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275332		**Flap Track Roller Assemblies (Track C) - Removal / Installation**							RE (O/C)			
27 A/F		Left Outboard	0				Mos	20-Nov-2022				
	30P191370000-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275333		**Flap Track Roller Assemblies (Track D) - Removal / Installation**							RE (O/C)			
27 A/F		Left Inboard	0				Mos	20-Nov-2022				
	30P191380000-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275334		**Flap Track Roller Assemblies (Track D) - Removal / Installation**							RE (O/C)			
27 A/F		Left Outboard	0				Mos	20-Nov-2022				
	30P191390000-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
275335		**Flap Track Roller Assemblies (Track A) - Removal / Installation**							RE (O/C)			
27 A/F		Right Inboard	0				Mos	20-Nov-2022				
	30P191300000-502	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275336		**Flap Track Roller Assemblies (Track A) - Removal / Installation**							RE (O/C)			
27 A/F		Right Outboard	0				Mos	20-Nov-2022				
	30P191310002-502	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275337		**Flap Track Roller Assemblies (Track B) - Removal / Installation**							RE (O/C)			
27 A/F		Right Inboard	0				Mos	20-Nov-2022				
	30P191330000-502	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275338		**Flap Track Roller Assemblies (Track B, Forward) - Removal / Installation**							RE (O/C)			
27 A/F		Right Outboard	0				Mos	20-Nov-2022				
	30P191340000-502	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275339		**Flap Track Roller Assemblies (Track B, Aft) - Removal / Installation**							RE (O/C)			
27 A/F		Right Outboard	0				Mos	20-Nov-2022				
	30P191320001-502	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275340		**Flap Track Roller Assemblies (Track C) - Removal / Installation**							RE (O/C)			
27 A/F		Right Inboard	0				Mos	20-Nov-2022				
	30P191360000-502	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275341		**Flap Track Roller Assemblies (Track C, Aft) - Removal / Installation**							RE (O/C)			
27 A/F		Right Inboard	0				Mos	20-Nov-2022				
	30P191350001-502	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275342		**Flap Track Roller Assemblies (Track C) - Removal / Installation**							RE (O/C)			
27 A/F		Right Outboard	0				Mos	20-Nov-2022				
	30P191370001-502	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275343		**Flap Track Roller Assemblies (Track D) - Removal / Installation**							RE (O/C)			
27 A/F		Right Inboard	0				Mos	20-Nov-2022				
	30P191380000-502	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275344		**Flap Track Roller Assemblies (Track D) - Removal / Installation**							RE (O/C)			
27 A/F		Right Outboard	0				Mos	20-Nov-2022				
	30P191390000-502	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
275373		**Flap Track Roller (Track A) - Removal / Installation**							RE (O/C)			
27 A/F		Left Inboard	0				Mos	20-Nov-2022				
	30P191300700-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275374		**Flap Track Roller (Track A) - Removal / Installation**							RE (O/C)			
27 A/F		Left Outboard	0				Mos	20-Nov-2022				
	30P191300700-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275375		**Flap Track Roller (Track B) - Removal / Installation**							RE (O/C)			
27 A/F		Left Inboard	0				Mos	20-Nov-2022				
	30P191300400-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275376		**Flap Track Roller (Track B) - Removal / Installation**							RE (O/C)			
27 A/F		Left Inboard	0				Mos	20-Nov-2022				
	30P191300301-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275377		**Flap Track Roller (Track B) - Removal / Installation**							RE (O/C)			
27 A/F		Left Outboard	0				Mos	20-Nov-2022				
	30P191300400-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275378		**Flap Track Roller (Track B) - Removal / Installation**							RE (O/C)			
27 A/F		Left Outboard	0				Mos	20-Nov-2022				
	30P191300301-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275379		**Flap Track Roller (Track B, Lower Guide) - Removal / Installation**							RE (O/C)			
27 A/F		Left	0				Mos	20-Nov-2022				
	30P191300500-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275380		**Flap Track Roller (Track C, Forward) - Removal / Installation**							RE (O/C)			
27 A/F		Left Inboard	0				Mos	20-Nov-2022				
	30P191300400-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275381		**Flap Track Roller (Track C, Aft) - Removal / Installation**							RE (O/C)			
27 A/F		Left Inboard	0				Mos	20-Nov-2022				
	30P191300301-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275382		**Flap Track Roller (Track C, Forward) - Removal / Installation**							RE (O/C)			
27 A/F		Left Outboard	0				Mos	20-Nov-2022				
	30P191300400-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
275383		**Flap Track Roller (Track C, Aft) - Removal / Installation**							RE (O/C)			
27 A/F		Left Outboard	0				Mos	20-Nov-2022				
	30P191300301-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275384		**Flap Track Roller (Track C, Lower Guide) - Removal / Installation**							RE (O/C)			
27 A/F		Left	0				Mos	20-Nov-2022				
	30P191300500-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275385		**Flap Track Roller (Track D) - Removal / Installation**							RE (O/C)			
27 A/F		Left Inboard	0				Mos	20-Nov-2022				
	30P191300201-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275386		**Flap Track Roller (Track D) - Removal / Installation**							RE (O/C)			
27 A/F		Left Outboard	0				Mos	20-Nov-2022				
	30P191300201-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275387		**Flap Track Roller (Track A) - Removal / Installation**							RE (O/C)			
27 A/F		Right Inboard	0				Mos	20-Nov-2022				
	30P191300700-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275388		**Flap Track Roller (Track A) - Removal / Installation**							RE (O/C)			
27 A/F		Right Outboard	0				Mos	20-Nov-2022				
	30P191300700-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275389		**Flap Track Roller (Track B, Forward) - Removal / Installation**							RE (O/C)			
27 A/F		Right Inboard	0				Mos	20-Nov-2022				
	30P191300400-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275390		**Flap Track Roller (Track B, Aft) - Removal / Installation**							RE (O/C)			
27 A/F		Right Inboard	0				Mos	20-Nov-2022				
	30P191300301-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275391		**Flap Track Roller (Track B, Forward) - Removal / Installation**							RE (O/C)			
27 A/F		Right Outboard	0				Mos	20-Nov-2022				
	30P191300400-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275392		**Flap Track Roller (Track B, Aft) - Removal / Installation**							RE (O/C)			
27 A/F		Right Outboard	0				Mos	20-Nov-2022				
	30P191300301-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
275393		**Flap Track Roller (Track B, Lower Guide) - Removal / Installation**							RE (O/C)			
27 A/F		Right	0				Mos	20-Nov-2022				
	30P191300500-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275394		**Flap Track Roller (Track C, Forward) - Removal / Installation**							RE (O/C)			
27 A/F		Right Inboard	0				Mos	20-Nov-2022				
	30P191300400-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275395		**Flap Track Roller (Track C, Aft) - Removal / Installation**							RE (O/C)			
27 A/F		Right Inboard	0				Mos	20-Nov-2022				
	30P191300301-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275396		**Flap Track Roller (Track C, Forward) - Removal / Installation**							RE (O/C)			
27 A/F		Right Outboard	0				Mos	20-Nov-2022				
	30P191300400-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275397		**Flap Track Roller (Track C, Aft) - Removal / Installation**							RE (O/C)			
27 A/F		Right Outboard	0				Mos	20-Nov-2022				
	30P191300301-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275398		**Flap Track Roller (Track C, Lower Guide) - Removal / Installation**							RE (O/C)			
27 A/F		Right	0				Mos	20-Nov-2022				
	30P191300500-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275399		**Flap Track Roller (Track D) - Removal / Installation**							RE (O/C)			
27 A/F		Right Inboard	0				Mos	20-Nov-2022				
	30P191300201-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275400		**Flap Track Roller (Track D) - Removal / Installation**							RE (O/C)			
27 A/F		Right Outboard	0				Mos	20-Nov-2022				
	30P191300201-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275403		**Flap Position Resolver - Removal / Installation**							RE (O/C)			
27 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-54-01, Mfg#:27-54-01											
275404		**Flap Position Resolver - Removal / Installation**							RE (O/C)			
27 A/F		Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-54-01, Mfg#:27-54-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
275413		**Flap Track Stops (Track A) - Removal / Installation**							RE (O/C)			
	27 A/F	Left Inboard					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275414		**Flap Track Stops (Track A) - Removal / Installation**							RE (O/C)			
	27 A/F	Left Outboard					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275415		**Flap Track Stops (Track D) - Removal / Installation**							RE (O/C)			
	27 A/F	Left Inboard					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275416		**Flap Track Stops (Track D) - Removal / Installation**							RE (O/C)			
	27 A/F	Left Outboard					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275417		**Flap Track Stops (Track A) - Removal / Installation**							RE (O/C)			
	27 A/F	Right Inboard					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275418		**Flap Track Stops (Track A) - Removal / Installation**							RE (O/C)			
	27 A/F	Right Outboard					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275419		**Flap Track Stops (Track D) - Removal / Installation**							RE (O/C)			
	27 A/F	Right Inboard					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
275420		**Flap Track Stops (Track D) - Removal / Installation**							RE (O/C)			
	27 A/F	Right Outboard					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::27-53-01, Mfg#:27-53-01-RI											
276103		**Ground Spoiler Actuator - Removal / Installation**							RE (O/C)			
	27 A/F	Left	0				Mos	20-Nov-2022				
	CA49710-003	New	0				Hrs	0				
	03030		0				Ldg	0				
	Mfg#:27-61-01-RI											
276104		**Ground Spoiler Actuator - Removal / Installation**							RE (O/C)			
	27 A/F	Right	0				Mos	20-Nov-2022				
	CA49710-003	New	0				Hrs	0				
	02067		0				Ldg	0				
	Mfg#:27-61-01-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
276109		**Multifunction Spoiler Actuator - Removal / Installation**							RE (O/C)			
27 A/F		Left Inboard	0				Mos	20-Nov-2022				
	CA48495-009	New	0				Hrs	0				
	02281		0				Ldg	0				
	Mfg#:27-61-01-RI											
276110		**Multifunction Spoiler Actuator - Removal / Installation**							RE (O/C)			
27 A/F		Right Inboard	0				Mos	20-Nov-2022				
	CA48495-009	New	0				Hrs	0				
	04060		0				Ldg	0				
	Mfg#:27-61-01-RI											
276111		**Multifunction Spoiler Actuator - Removal / Installation**							RE (O/C)			
27 A/F		Left Outboard	0				Mos	20-Nov-2022				
	CA48495-009	New	0				Hrs	0				
	02286		0				Ldg	0				
	Mfg#:27-61-01-RI											
276112		**Multifunction Spoiler Actuator - Removal / Installation**							RE (O/C)			
27 A/F		Right Outboard	0				Mos	20-Nov-2022				
	CA48495-009	New	0				Hrs	0				
	04065		0				Ldg	0				
	Mfg#:27-61-01-RI											
276127		**Spoiler Control Module - Removal / Installation**							RE (O/C)			
27 A/F		No.1	0				Mos	20-Nov-2022				
	CA51241-001	New	0				Hrs	0				
	02013		0				Ldg	0				
	Mfg#:27-61-02											
276128		**Spoiler Control Module - Removal / Installation**							RE (O/C)			
27 A/F		No.2	0				Mos	20-Nov-2022				
	CA51420-001	New	0				Hrs	0				
	02012		0				Ldg	0				
	Mfg#:27-61-02											
276130		**Air Brake Handle - Removal / Installation**							RE (O/C)			
27 A/F			0				Mos	20-Nov-2022				
	CA52759-002	New	0				Hrs	0				
	02295		0				Ldg	0				
	Mfg#:27-61-03											
276132		**Ground Spoiler Disarm Switch - Removal / Installation**							RE (O/C)			
27 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-61-05											
276136		**Pilot Authority Disconnect Switch - Removal / Installation**							RE (O/C)			
27 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-61-06											
276203		**Ground Spoiler Board - Removal / Installation**							RE (O/C)			
27 A/F		Left	0				Mos	20-Nov-2022				
	30P213100004-501	New	0				Hrs	0				
	K0038		0				Ldg	0				
	Mfg#:27-62-01-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
276204		**Ground Spoiler Board - Removal / Installation**							RE (O/C)			
27 A/F		Right	0				Mos	20-Nov-2022				
	30P213100004-502	New	0				Hrs	0				
	K0038		0				Ldg	0				
	Mfg#:27-62-01-RI											
276211		**Multifunction Spoiler Board - Removal / Installation**							RE (O/C)			
27 A/F		Left Inboard	0				Mos	20-Nov-2022				
	30P213200005-501	New	0				Hrs	0				
	K0039		0				Ldg	0				
	Mfg#:27-62-02-RI											
276212		**Multifunction Spoiler Board - Removal / Installation**							RE (O/C)			
27 A/F		Right Inboard	0				Mos	20-Nov-2022				
	30P213200005-502	New	0				Hrs	0				
	K0039		0				Ldg	0				
	Mfg#:27-62-02-RI											
276213		**Multifunction Spoiler Board - Removal / Installation**							RE (O/C)			
27 A/F		Left Outboard	0				Mos	20-Nov-2022				
	30P213300004-501	New	0				Hrs	0				
	K0039		0				Ldg	0				
	Mfg#:27-62-02-RI											
276214		**Multifunction Spoiler Board - Removal / Installation**							RE (O/C)			
27 A/F		Right Outboard	0				Mos	20-Nov-2022				
	30P213300004-502	New	0				Hrs	0				
	K0038		0				Ldg	0				
	Mfg#:27-62-02-RI											
276305		**Multifunction Spoiler Position Sensor - Removal / Installation**							RE (O/C)			
27 A/F		Left Outboard	0				Mos	20-Nov-2022				
	CA57245-001	New	0				Hrs	0				
	A1691		0				Ldg	0				
	Mfg#:27-63-02											
276306		**Multifunction Spoiler Position Sensor - Removal / Installation**							RE (O/C)			
27 A/F		Left Inboard	0				Mos	20-Nov-2022				
	CA57245-001	New	0				Hrs	0				
	A1684		0				Ldg	0				
	Mfg#:27-63-02											
276307		**Multifunction Spoiler Position Sensor - Removal / Installation**							RE (O/C)			
27 A/F		Right Inboard	0				Mos	20-Nov-2022				
	CA57245-001	New	0				Hrs	0				
	A1704		0				Ldg	0				
	Mfg#:27-63-02											
276308		**Multifunction Spoiler Position Sensor - Removal / Installation**							RE (O/C)			
27 A/F		Right Outboard	0				Mos	20-Nov-2022				
	CA57245-001	New	0				Hrs	0				
	A1706		0				Ldg	0				
	Mfg#:27-63-02											
276317		**Ground Spoiler Proximity Sensor - Removal / Installation**							RE (O/C)			
27 A/F		Left	0				Mos	20-Nov-2022				
	CA55667-001	New	0				Hrs	0				
	00593		0				Ldg	0				
	Mfg#:27-63-03											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
276318		**Ground Spoiler Proximity Sensor - Removal / Installation**							RE (O/C)			
27 A/F		Right	0				Mos	20-Nov-2022				
	CA55667-001	New	0				Hrs	0				
	00601		0				Ldg	0				
	Mfg#:27-63-03											
277102		**Gust Lock Handle - Removal / Installation**							RE (O/C)			
27 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:27-71-01											
281102		**Fuel Tank - Removal / Installation**							RE (O/C)			
28 A/F		Fwd	0				Mos	20-Nov-2022				
	30P371100009-501	New	0				Hrs	0				
	2253		0				Ldg	0				
	Mfg#:28-11-01-RI											
281104		**Fuel Tank - Removal / Installation**							RE (O/C)			
28 A/F		Aft	0				Mos	20-Nov-2022				
	4507-300-507	New	0				Hrs	0				
	260		0				Ldg	0				
	Mfg#:28-11-02											
281202		**Flapper Valve - Removal / Installation**							RE (O/C)			
28 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:28-12-00-RI											
281303		**Drain Valve (Feed Tank) - Removal / Installation**							RE (O/C)			
28 A/F		Left	0				Mos	20-Nov-2022				
	L83A13-632	New	0				Hrs	0				
	M57833		0				Ldg	0				
	Mfg#:28-13-01-RI											
281304		**Drain Valve (Feed Tank) - Removal / Installation**							RE (O/C)			
28 A/F		Right	0				Mos	20-Nov-2022				
	L83A13-632	New	0				Hrs	0				
	M57892		0				Ldg	0				
	Mfg#:28-13-01-RI											
281307		**Drain Valve (Wing Vent) - Removal / Installation**							RE (O/C)			
28 A/F		Left	0				Mos	20-Nov-2022				
	L83A13-632	New	0				Hrs	0				
	M51720		0				Ldg	0				
	Mfg#:28-13-01-RI											
281308		**Drain Valve (Wing Vent) - Removal / Installation**							RE (O/C)			
28 A/F		Right	0				Mos	20-Nov-2022				
	L83A13-632	New	0				Hrs	0				
	M48042		0				Ldg	0				
	Mfg#:28-13-01-RI											
281311		**Drain Valve (Rib 2) - Removal / Installation**							RE (O/C)			
28 A/F		Left	0				Mos	20-Nov-2022				
	L83A13-632	New	0				Hrs	0				
	M51731		0				Ldg	0				
	Mfg#:28-13-01-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
281312		**Drain Valve (Rib 2) - Removal / Installation**							RE (O/C)			
	28 A/F	Right	0				Mos	20-Nov-2022				
	L83A13-632	New	0				Hrs	0				
	M48037		0				Ldg	0				
	Mfg#:28-13-01-RI											
281314		**Drain Valve (Center Tank) - Removal / Installation**							RE (O/C)			
	28 A/F		0				Mos	20-Nov-2022				
	L83A13-631	New	0				Hrs	0				
	M83771		0				Ldg	0				
	Mfg#:28-13-01-RI											
281316		**Water Drain Valve (Center Tank) - Removal / Installation**							RE (O/C)			
	28 A/F		0				Mos	20-Nov-2022				
	L83A13-632	New	0				Hrs	0				
	M62689		0				Ldg	0				
	Mfg#:28-13-01-RI											
281318		**Water Drain Valve (Forward Tank) - Removal / Installation**							RE (O/C)			
	28 A/F		0				Mos	20-Nov-2022				
	L83A13-631	New	0				Hrs	0				
	M61226		0				Ldg	0				
	Mfg#:28-13-01-RI											
281320		**Water Drain Valve (Aft Tank) - Removal / Installation**							RE (O/C)			
	28 A/F		0				Mos	20-Nov-2022				
	L83A13-631	New	0				Hrs	0				
	M47481		0				Ldg	0				
	Mfg#:28-13-01-RI											
281403		**Float Valve - Removal / Installation**							RE (O/C)			
	28 A/F	Left Fwd					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
281404		**Float Valve - Removal / Installation**							RE (O/C)			
	28 A/F	Right Fwd					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
281407		**Float Valve - Removal / Installation**							RE (O/C)			
	28 A/F	Left	0				Mos	20-Nov-2022				
	L87-13-004	New	0				Hrs	0				
	L69072		0				Ldg	0				
	Mfg#:28-14-01											
281408		**Float Valve - Removal / Installation**							RE (O/C)			
	28 A/F	Right	0				Mos	20-Nov-2022				
	L87-13-004	New	0				Hrs	0				
	L71430		0				Ldg	0				
	Mfg#:28-14-01											
281411		**Bladder Vent Valve - Removal / Installation**							RE (O/C)			
	28 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
281412		**Bladder Vent Valve - Removal / Installation**							RE (O/C)			
	28 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
281415		**Bladder Valve - Removal / Installation**							RE (O/C)			
	28 A/F	Fwd					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:28-14-02											
281416		**Bladder Valve - Removal / Installation**							RE (O/C)			
	28 A/F	Aft					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:28-14-02											
281419		**Vent Check Valve - Removal / Installation**							RE (O/C)			
	28 A/F	Left	0				Mos	20-Nov-2022				
	30P652008010-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:28-14-03-RI											
281420		**Vent Check Valve - Removal / Installation**							RE (O/C)			
	28 A/F	Right	0				Mos	20-Nov-2022				
	30P652008010-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:28-14-03-RI											
281425		**In-line Check Valve - Removal / Installation**							RE (O/C)			
	28 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:28-14-03-RI											
281426		**In-line Check Valve - Removal / Installation**							RE (O/C)			
	28 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:28-14-03-RI											
281429		**Flame Arrestor - Removal / Installation**							RE (O/C)			
	28 A/F	Left	0				Mos	20-Nov-2022				
	786091-2-0	New	0				Hrs	0				
	786091IN00667		0				Ldg	0				
	Mfg#:28-14-04-RI											
281430		**Flame Arrestor - Removal / Installation**							RE (O/C)			
	28 A/F	Right	0				Mos	20-Nov-2022				
	786091-2-0	New	0				Hrs	0				
	786091IN00679		0				Ldg	0				
	Mfg#:28-14-04-RI											
281437		**Positive / Negative Pressure Relief Valve - Removal / Installation**							RE (O/C)			
	28 A/F	Left	0				Mos	20-Nov-2022				
	L97L31-601P3	New	0				Hrs	0				
	K53986		0				Ldg	0				
	Mfg#:28-14-04-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
281438		**Positive / Negative Pressure Relief Valve - Removal / Installation**							RE (O/C)			
28 A/F		Right	0				Mos	20-Nov-2022				
	L97L31-601P3	New	0				Hrs	0				
	K54525		0				Ldg	0				
	Mfg#:28-14-04-RI											
282103		**Feed Ejector - Removal / Installation**							RE (O/C)			
28 A/F		Left	0				Mos	20-Nov-2022				
	T99B31-602	New	0				Hrs	0				
	L50353		0				Ldg	0				
	Mfg#:28-21-01											
282104		**Feed Ejector - Removal / Installation**							RE (O/C)			
28 A/F		Right	0				Mos	20-Nov-2022				
	T99B31-602	New	0				Hrs	0				
	L55059		0				Ldg	0				
	Mfg#:28-21-01											
282107		**Boost Pump Cannister - Removal / Installation**							RE (O/C)			
28 A/F		Left	0				Mos	20-Nov-2022				
	C93R31-606	New	0				Hrs	0				
	L68160		0				Ldg	0				
	Mfg#:28-21-02											
282108		**Boost Pump Cannister - Removal / Installation**							RE (O/C)			
28 A/F		Right	0				Mos	20-Nov-2022				
	C93R31-606	New	0				Hrs	0				
	L73625		0				Ldg	0				
	Mfg#:28-21-02											
282111		**Boost Pump Cartridge - Removal / Installation**							RE (O/C)			
28 A/F		Left					Mos	06-Nov-2023				
	P99C31-617	Repaired				0	Hrs	515:44				
	L23041					0	Ldg	304				
	Mfg#:28-21-02											
282112		**Boost Pump Cartridge - Removal / Installation**							RE (O/C)			
28 A/F		Right	0				Mos	20-Nov-2022				
	P99C31-617	New	0				Hrs	0				
	L79257		0				Ldg	0				
	Mfg#:28-21-02											
282119		**Feed Pressure Switch - Removal / Installation**							RE (O/C)			
28 A/F		Left Engine	0				Mos	20-Nov-2022				
	1103P1097-01	New	0				Hrs	0				
	4190		0				Ldg	0				
	Mfg#:28-21-03											
282120		**Feed Pressure Switch - Removal / Installation**							RE (O/C)			
28 A/F		Right Engine	0				Mos	20-Nov-2022				
	1103P1097-01	New	0				Hrs	0				
	4173		0				Ldg	0				
	Mfg#:28-21-03											
282123		**Engine Fuel Shut-off Valve - Removal / Installation**							RE (O/C)			
28 A/F		Left	0				Mos	20-Nov-2022				
	B97-31-615	New	0				Hrs	0				
	L95367		0				Ldg	0				
	Mfg#:28-21-04											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
282124		**Engine Fuel Shut-off Valve - Removal / Installation**							RE (O/C)			
28 A/F		Right	0				Mos	20-Nov-2022				
	B97-31-615	New	0				Hrs	0				
	L95368		0				Ldg	0				
	Mfg#:28-21-04											
282127		**Engine Fuel Shut-off Actuator - Removal / Installation**							RE (O/C)			
28 A/F		Left	0				Mos	20-Nov-2022				
	D97C00-674	New	0				Hrs	0				
	N09772		0				Ldg	0				
282128		**Engine Fuel Shut-off Actuator - Removal / Installation**							RE (O/C)			
28 A/F		Right	0				Mos	20-Nov-2022				
	D97C00-674	New	0				Hrs	0				
	N10272		0				Ldg	0				
282130		**APU Fuel Shut-off Valve - Removal / Installation**							RE (O/C)			
28 A/F			0				Mos	20-Nov-2022				
	B97-09-602	New	0				Hrs	0				
	L72675		0				Ldg	0				
	Mfg#:28-21-04											
282132		**Engine Fuel Shut-off Actuator - Removal / Installation**							RE (O/C)			
28 A/F		APU	0				Mos	20-Nov-2022				
	D97C00-674	New	0				Hrs	0				
	L77421		0				Ldg	0				
282137		**Fuel Supply Hose - Removal / Installation**							RE (O/C)			
28 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:28-21-50											
282138		**Fuel Supply Hose - Removal / Installation**							RE (O/C)			
28 A/F		Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:28-21-50											
282141		**Fuel Motive Flow Hose - Removal / Installation**							RE (O/C)			
28 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:28-21-50											
282142		**Fuel Motive Flow Hose - Removal / Installation**							RE (O/C)			
28 A/F		Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:28-21-50											
282203		**Forward Tank Scavenge Ejector - Removal / Installation**							RE (O/C)			
28 A/F		Left	0				Mos	20-Nov-2022				
	T99B25-606	New	0				Hrs	0				
	L81255		0				Ldg	0				
	Mfg#:28-22-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
282204		**Forward Tank Scavenge Ejector - Removal / Installation**							RE (O/C)			
	28 A/F	Right	0				Mos	20-Nov-2022				
	T99B25-606	New	0				Hrs	0				
	L81257		0				Ldg	0				
	Mfg#:28-22-01											
282207		**Center Tank Scavenge Ejector - Removal / Installation**							RE (O/C)			
	28 A/F	Left	0				Mos	20-Nov-2022				
	T99B25-605	New	0				Hrs	0				
	L75531		0				Ldg	0				
	Mfg#:28-22-01											
282208		**Center Tank Scavenge Ejector - Removal / Installation**							RE (O/C)			
	28 A/F	Right	0				Mos	20-Nov-2022				
	T99B25-605	New	0				Hrs	0				
	L75538		0				Ldg	0				
	Mfg#:28-22-01											
282211		**Aft Tank Scavenge Ejector - Removal / Installation**							RE (O/C)			
	28 A/F	Left	0				Mos	20-Nov-2022				
	T99B25-605	New	0				Hrs	0				
	L62431		0				Ldg	0				
	Mfg#:28-22-01											
282212		**Aft Tank Scavenge Ejector - Removal / Installation**							RE (O/C)			
	28 A/F	Right	0				Mos	20-Nov-2022				
	T99B25-605	New	0				Hrs	0				
	L59150		0				Ldg	0				
	Mfg#:28-22-01											
282215		**Wing Tank Scavenge Ejector - Removal / Installation**							RE (O/C)			
	28 A/F	Left	0				Mos	20-Nov-2022				
	T99A25-603	New	0				Hrs	0				
	L66740		0				Ldg	0				
	Mfg#:28-22-01											
282216		**Wing Tank Scavenge Ejector - Removal / Installation**							RE (O/C)			
	28 A/F	Right	0				Mos	20-Nov-2022				
	T99A25-603	New	0				Hrs	0				
	L68602		0				Ldg	0				
	Mfg#:28-22-01											
282219		**Forward Tank Scavenge Ejector In-line Filter - Removal / Installation**							RE (O/C)			
	28 A/F	Left	0				Mos	20-Nov-2022				
	C99-26-002	New	0				Hrs	0				
	K70619		0				Ldg	0				
	Mfg#:28-22-01											
282220		**Forward Tank Scavenge Ejector In-line Filter - Removal / Installation**							RE (O/C)			
	28 A/F	Right	0				Mos	20-Nov-2022				
	C99-26-002	New	0				Hrs	0				
	K70618		0				Ldg	0				
	Mfg#:28-22-01											
282223		**Gravity Cross-flow Shut-off Valve - Removal / Installation**							RE (O/C)			
	28 A/F		0				Mos	20-Nov-2022				
	B97-51-604	New	0				Hrs	0				
	L69097		0				Ldg	0				
	Mfg#:28-22-02-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
282224		**Power Cross-flow Shut-off Valve - Removal / Installation**							RE (O/C)			
28 A/F			0				Mos	20-Nov-2022				
	B97-19-6051	New	0				Hrs	0				
	L68299		0				Ldg	0				
	Mfg#:28-22-02-RI											
282228		**Gravity Cross-flow Motor Actuator - Removal / Installation**							RE (O/C)			
28 A/F			0				Mos	20-Nov-2022				
	D97C00-674	New	0				Hrs	0				
	L91499		0				Ldg	0				
	Mfg#:28-22-02-RI											
282230		**Power Cross-flow Motor Actuator - Removal / Installation**							RE (O/C)			
28 A/F			0				Mos	20-Nov-2022				
	D97C00-674	New	0				Hrs	0				
	L77560		0				Ldg	0				
	Mfg#:28-22-02-RI											
282303		**Refuel Valve - Removal / Installation**							RE (O/C)			
28 A/F		Left	0				Mos	20-Nov-2022				
	L94K31-601	New	0				Hrs	0				
	L62350		0				Ldg	0				
	Mfg#:28-23-01											
282304		**Refuel Valve - Removal / Installation**							RE (O/C)			
28 A/F		Right					Mos	10-Feb-2023				
	L94K31-601						Hrs	24:24				
	L75297						Ldg	7				
	Mfg#:28-23-01-RI											
282313		**Gravity Fill Adapter Cap - Removal / Installation**							RE (O/C)			
28 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:28-23-01-RI											
282314		**Gravity Fill Adapter Cap - Removal / Installation**							RE (O/C)			
28 A/F		Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:28-23-01-RI											
282317		**Gravity Filler Basket - Removal / Installation**							RE (O/C)			
28 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:28-23-01-RI											
282318		**Gravity Filler Basket - Removal / Installation**							RE (O/C)			
28 A/F		Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:28-23-01-RI											
282322		**Forward Fuel Tank Dump / Drain Valve - Removal / Installation**							RE (O/C)			
28 A/F			0				Mos	20-Nov-2022				
	V98A38-001	New	0				Hrs	0				
	M65058		0				Ldg	0				
	Mfg#:28-23-02-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
282324		**Center Fuel Tank Dump / Drain Valve - Removal / Installation**							RE (O/C)			
28 A/F			0				Mos	20-Nov-2022				
V98A38-002		New	0				Hrs	0				
M57826			0				Ldg	0				
Mfg#:28-23-02-RI												
282327		**Feed Tank Dump Valve - Removal / Installation**							RE (O/C)			
28 A/F		Left	0				Mos	20-Nov-2022				
V98A38-003		New	0				Hrs	0				
M41979			0				Ldg	0				
Mfg#:28-23-02-RI												
282328		**Feed Tank Dump Valve - Removal / Installation**							RE (O/C)			
28 A/F		Right	0				Mos	20-Nov-2022				
V98A38-003		New	0				Hrs	0				
M60286			0				Ldg	0				
Mfg#:28-23-02-RI												
282330		**Aft Fuel Tank Dump / Drain Valve - Removal / Installation**							RE (O/C)			
28 A/F			0				Mos	20-Nov-2022				
V98A38-001		New	0				Hrs	0				
M43606			0				Ldg	0				
Mfg#:28-23-02-RI												
282336		**Refuel / Defuel Panel - Removal / Installation**							RE (O/C)			
28 A/F			0				Mos	20-Nov-2022				
742397-1-1		New	0				Hrs	0				
742397IN00363			0				Ldg	0				
Mfg#:28-23-03												
282338		**Refuel / Defuel Adapter - Removal / Installation**							RE (O/C)			
28 A/F			0				Mos	20-Nov-2022				
K97-45-601		New	0				Hrs	0				
K69195			0				Ldg	0				
Mfg#:28-23-04												
283103		**Jettison Shut-off Valve - Removal / Installation**							RE (O/C)			
28 A/F		Left	0				Mos	20-Nov-2022				
B97H25-603		New	0				Hrs	0				
L72384			0				Ldg	0				
Mfg#:28-31-01-RI												
283104		**Jettison Shut-off Valve - Removal / Installation**							RE (O/C)			
28 A/F		Right	0				Mos	20-Nov-2022				
B97H25-603		New	0				Hrs	0				
L73682			0				Ldg	0				
Mfg#:28-31-01-RI												
283107		**Jettison Shut-off Valve Motor Actuator - Removal / Installation**							RE (O/C)			
28 A/F		Left	0				Mos	20-Nov-2022				
D97C00-674		New	0				Hrs	0				
L69559			0				Ldg	0				
Mfg#:28-31-01-RI												
283108		**Jettison Shut-off Valve Motor Actuator - Removal / Installation**							RE (O/C)			
28 A/F		Right	0				Mos	20-Nov-2022				
D97C00-674		New	0				Hrs	0				
L77557			0				Ldg	0				
Mfg#:28-31-01-RI												

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
284110		**Fluid Quantity Measurement Computer - Removal / Installation**							RE (O/C)			
	28 A/F		0				Mos	20-Nov-2022				
	738721-1-4	New	0				Hrs	0				
	738721IN00373		0				Ldg	0				
	Mfg#:28-41-01											
284113		**Compensator Probe - Removal / Installation**							RE (O/C)			
	28 A/F	Left	0				Mos	20-Nov-2022				
	765939-1-0	New	0				Hrs	0				
	765939IN00674		0				Ldg	0				
	Mfg#:28-41-02-RI											
284114		**Compensator Probe - Removal / Installation**							RE (O/C)			
	28 A/F	Right	0				Mos	20-Nov-2022				
	765939-1-0	New	0				Hrs	0				
	765939IN00692		0				Ldg	0				
	Mfg#:28-41-02-RI											
284118		**Forward Tank Fuel Probe - Removal / Installation**							RE (O/C)			
	28 A/F	No.1	0				Mos	20-Nov-2022				
	765923-1-0	New	0				Hrs	0				
	765923IN00442		0				Ldg	0				
	Mfg#:28-41-02-RI											
284119		**Forward Tank Fuel Probe - Removal / Installation**							RE (O/C)			
	28 A/F	No.2	0				Mos	20-Nov-2022				
	765924-1-0	New	0				Hrs	0				
	765924IN00463		0				Ldg	0				
	Mfg#:28-41-02-RI											
284120		**Forward Tank Fuel Probe - Removal / Installation**							RE (O/C)			
	28 A/F	No.3	0				Mos	20-Nov-2022				
	765925-1-0	New	0				Hrs	0				
	765925IN00466		0				Ldg	0				
	Mfg#:28-41-02-RI											
284123		**Aft Tank Fuel Probe - Removal / Installation**							RE (O/C)			
	28 A/F	No.1	0				Mos	20-Nov-2022				
	765929-1-0	New	0				Hrs	0				
	765929IN00423		0				Ldg	0				
	Mfg#:28-41-02-RI											
284124		**Aft Tank Fuel Probe - Removal / Installation**							RE (O/C)			
	28 A/F	No.2	0				Mos	20-Nov-2022				
	765930-1-0	New	0				Hrs	0				
	765930IN00402		0				Ldg	0				
	Mfg#:28-41-02-RI											
284133		**Wing Outer Tank Fuel Probe - Removal / Installation**							RE (O/C)			
	28 A/F	Left No.1	0				Mos	20-Nov-2022				
	765931-1-0	New	0				Hrs	0				
	765931IN00652		0				Ldg	0				
	Mfg#:28-41-02-RI											
284134		**Wing Outer Tank Fuel Probe - Removal / Installation**							RE (O/C)			
	28 A/F	Right No.1	0				Mos	20-Nov-2022				
	765931-1-0	New	0				Hrs	0				
	765931IN00699		0				Ldg	0				
	Mfg#:28-41-02-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
284135		**Wing Outer Tank Fuel Probe - Removal / Installation**							RE (O/C)			
28 A/F		Left No.2	0				Mos	20-Nov-2022				
	765932-1-0	New	0				Hrs	0				
	765932IN00719		0				Ldg	0				
	Mfg#:28-41-02-RI											
284136		**Wing Outer Tank Fuel Probe - Removal / Installation**							RE (O/C)			
28 A/F		Right No.2	0				Mos	20-Nov-2022				
	765932-1-0	New	0				Hrs	0				
	765932IN00692		0				Ldg	0				
	Mfg#:28-41-02-RI											
284137		**Wing Outer Tank Fuel Probe - Removal / Installation**							RE (O/C)			
28 A/F		Left No.3	0				Mos	20-Nov-2022				
	765933-1-0	New	0				Hrs	0				
	765933IN00624		0				Ldg	0				
	Mfg#:28-41-02-RI											
284138		**Wing Outer Tank Fuel Probe - Removal / Installation**							RE (O/C)			
28 A/F		Right No.3	0				Mos	20-Nov-2022				
	765933-1-0	New	0				Hrs	0				
	765933IN00625		0				Ldg	0				
	Mfg#:28-41-02-RI											
284139		**Wing Outer Tank Fuel Probe - Removal / Installation**							RE (O/C)			
28 A/F		Left No.4	0				Mos	20-Nov-2022				
	765934-1-0	New	0				Hrs	0				
	765934IN00685		0				Ldg	0				
	Mfg#:28-41-02-RI											
284140		**Wing Outer Tank Fuel Probe - Removal / Installation**							RE (O/C)			
28 A/F		Right No.4	0				Mos	20-Nov-2022				
	765934-1-0	New	0				Hrs	0				
	765934IN00688		0				Ldg	0				
	Mfg#:28-41-02-RI											
284147		**Wing Inner Tank Fuel Probe - Removal / Installation**							RE (O/C)			
28 A/F		Left No.1	0				Mos	20-Nov-2022				
	765935-1-0	New	0				Hrs	0				
	765935IN00712		0				Ldg	0				
	Mfg#:28-41-02-RI											
284148		**Wing Inner Tank Fuel Probe - Removal / Installation**							RE (O/C)			
28 A/F		Right No.1	0				Mos	20-Nov-2022				
	765935-1-0	New	0				Hrs	0				
	765935IN00718		0				Ldg	0				
	Mfg#:28-41-02-RI											
284149		**Wing Inner Tank Fuel Probe - Removal / Installation**							RE (O/C)			
28 A/F		Left No.2	0				Mos	20-Nov-2022				
	765936-1-0	New	0				Hrs	0				
	765936IN00723		0				Ldg	0				
	Mfg#:28-41-02-RI											
284150		**Wing Inner Tank Fuel Probe - Removal / Installation**							RE (O/C)			
28 A/F		Right No.2	0				Mos	20-Nov-2022				
	765936-1-0	New	0				Hrs	0				
	765936IN00731		0				Ldg	0				
	Mfg#:28-41-02-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
284151		**Wing Inner Tank Fuel Probe - Removal / Installation**							RE (O/C)			
	28 A/F	Left No.3	0				Mos	20-Nov-2022				
	765937-1-0	New	0				Hrs	0				
	765937IN00675		0				Ldg	0				
	Mfg#:28-41-02-RI											
284152		**Wing Inner Tank Fuel Probe - Removal / Installation**							RE (O/C)			
	28 A/F	Right No.3	0				Mos	20-Nov-2022				
	765937-1-0	New	0				Hrs	0				
	765937IN00678		0				Ldg	0				
	Mfg#:28-41-02-RI											
284155		**Feed Tank Fuel Probe - Removal / Installation**							RE (O/C)			
	28 A/F	Left	0				Mos	20-Nov-2022				
	765938-1-0	New	0				Hrs	0				
	765938IN00694		0				Ldg	0				
	Mfg#:28-41-02-RI											
284156		**Feed Tank Fuel Probe - Removal / Installation**							RE (O/C)			
	28 A/F	Right	0				Mos	20-Nov-2022				
	765938-1-0	New	0				Hrs	0				
	765938IN00716		0				Ldg	0				
	Mfg#:28-41-02-RI											
284161		**Center Tank Fuel Probe - Removal / Installation**							RE (O/C)			
	28 A/F	No.1	0				Mos	20-Nov-2022				
	765926-1-0	New	0				Hrs	0				
	765926IN00459		0				Ldg	0				
	Mfg#:28-41-02-RI											
284162		**Center Tank Fuel Probe - Removal / Installation**							RE (O/C)			
	28 A/F	No.2	0				Mos	20-Nov-2022				
	765927-1-0	New	0				Hrs	0				
	765927IN00418		0				Ldg	0				
	Mfg#:28-41-02-RI											
284163		**Center Tank Fuel Probe - Removal / Installation**							RE (O/C)			
	28 A/F	No.3	0				Mos	20-Nov-2022				
	765928-1-0	New	0				Hrs	0				
	765928IN00452		0				Ldg	0				
	Mfg#:28-41-02-RI											
284166		**Fuel Temperature Sensor - Removal / Installation**							RE (O/C)			
	28 A/F		0				Mos	20-Nov-2022				
	722872-1-0	New	0				Hrs	0				
	722872IN02433		0				Ldg	0				
	Mfg#:28-41-03-RI											
284168		**High Level Sensor - Removal / Installation**							RE (O/C)			
	28 A/F						Mos	01-Jun-2024				
	722861-1-0 AMDT A						Hrs	848:22				
	1230						Ldg	497				
	Mfg#:28-41-04											
284170		**Oil Level Signal Conditioner - Removal / Installation**							RE (O/C)			
	28 A/F		0				Mos	20-Nov-2022				
	738776	New	0				Hrs	0				
	738776IN00364		0				Ldg	0				
	Mfg#:28-41-06											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
291103		**Engine-Driven Pump - Removal / Installation**							RE (O/C)			
29 A/F		Left	2				Mos	08-Feb-2023				
	291GA0001-1		24:24				Hrs	24:24				
	K0533		7				Ldg	7				
	Mfg#:29-11-01											
291104		**Engine-Driven Pump - Removal / Installation**							RE (O/C)			
29 A/F		Right	2				Mos	08-Feb-2023				
	291GA0001-1		24:24				Hrs	24:24				
	K0529		7				Ldg	7				
	Mfg#:29-11-01											
291109		**Electric Motor Pump - Removal / Installation**							RE (O/C)			
29 A/F		Left	0				Mos	20-Nov-2022				
	46133	New	0				Hrs	0				
	KH580		0				Ldg	0				
	Mfg#:29-11-02-RI											
291110		**Electric Motor Pump - Removal / Installation**							RE (O/C)			
29 A/F		Right	0				Mos	20-Nov-2022				
	46133	New	0				Hrs	0				
	KH579		0				Ldg	0				
	Mfg#:29-11-02-RI											
291203		**Hydraulic Reservoir - Removal / Installation**							RE (O/C)			
29 A/F		Left	0				Mos	20-Nov-2022				
	7579	New	0				Hrs	0				
	MAR22-0267		0				Ldg	0				
	Mfg#:29-12-01											
291204		**Hydraulic Reservoir - Removal / Installation**							RE (O/C)			
29 A/F		Right	0				Mos	20-Nov-2022				
	7578	New	0				Hrs	0				
	DEC21-0261		0				Ldg	0				
	Mfg#:29-12-01											
291209		**Hydraulic Manifold - Removal / Installation**							RE (O/C)			
29 A/F		Left	0				Mos	20-Nov-2022				
	2590-1	New	0				Hrs	0				
	DEC19-0517		0				Ldg	0				
	Mfg#:29-12-02											
291210		**Hydraulic Manifold - Removal / Installation**							RE (O/C)			
29 A/F		Right	0				Mos	20-Nov-2022				
	2590-1	New	0				Hrs	0				
	OCT19-0500		0				Ldg	0				
	Mfg#:29-12-02											
291215		**Hydraulic Fire Shut-off Valve - Removal / Installation**							RE (O/C)			
29 A/F		Left	0				Mos	20-Nov-2022				
	ZMV28-12-2	New	0				Hrs	0				
	2490762-5		0				Ldg	0				
	Mfg#:29-12-03											
291216		**Hydraulic Fire Shut-off Valve - Removal / Installation**							RE (O/C)			
29 A/F		Right	0				Mos	20-Nov-2022				
	ZMV28-12-2	New	0				Hrs	0				
	2440801-2		0				Ldg	0				
	Mfg#:29-12-03											

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
291221	**Manifold Relief Valve - Removal / Installation**							RE (O/C)			
29 A/F	Left	0				Mos	20-Nov-2022				
3464-0000-000	New	0				Hrs	0				
IL-1359		0				Ldg	0				
Mfg#:29-12-04											
291222	**Manifold Relief Valve - Removal / Installation**							RE (O/C)			
29 A/F	Right	0				Mos	20-Nov-2022				
3464-0000-000	New	0				Hrs	0				
IL-1358		0				Ldg	0				
Mfg#:29-12-04											
291227	**Reservoir Bleed / Relief Valve - Removal / Installation**							RE (O/C)			
29 A/F	Left	0				Mos	20-Nov-2022				
HV50-17	New	0				Hrs	0				
2440794-3		0				Ldg	0				
Mfg#:29-12-04											
291228	**Reservoir Bleed / Relief Valve - Removal / Installation**							RE (O/C)			
29 A/F	Right	0				Mos	20-Nov-2022				
HV50-17	New	0				Hrs	0				
2440794-1		0				Ldg	0				
Mfg#:29-12-04											
291233	**Hydraulic Sampling Valve - Removal / Installation**							RE (O/C)			
29 A/F	Left					Mos	20-Nov-2022				
Unknown						Hrs	0				
Unknown						Ldg	0				
Mfg#:29-12-06											
291234	**Hydraulic Sampling Valve - Removal / Installation**							RE (O/C)			
29 A/F	Right					Mos	20-Nov-2022				
Unknown						Hrs	0				
Unknown						Ldg	0				
Mfg#:29-12-06											
291303	**Hydraulic System Pressure Filter Assembly (EDP) - Removal / Installation**							RE (O/C)			
29 A/F	Left	0				Mos	20-Nov-2022				
AEC6108	New	0				Hrs	0				
00525		0				Ldg	0				
Mfg#:29-13-01											
291304	**Hydraulic System Pressure Filter Assembly (EDP) - Removal / Installation**							RE (O/C)			
29 A/F	Right	0				Mos	20-Nov-2022				
AEC6108	New	0				Hrs	0				
00520		0				Ldg	0				
Mfg#:29-13-01											
291307	**Hydraulic System Pressure Filter Assembly (EMP) - Removal / Installation**							RE (O/C)			
29 A/F	Left	0				Mos	20-Nov-2022				
AEC6096	New	0				Hrs	0				
00531		0				Ldg	0				
Mfg#:29-13-01											
291308	**Hydraulic System Pressure Filter Assembly (EMP) - Removal / Installation**							RE (O/C)			
29 A/F	Right	0				Mos	20-Nov-2022				
AEC6096	New	0				Hrs	0				
00533		0				Ldg	0				
Mfg#:29-13-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
291311		**Hydraulic System Pressure Filter Element (EDP) - Removal / Installation**							RE (O/C)			
29 A/F		Left					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:29-13-01												
291312		**Hydraulic System Pressure Filter Element (EDP) - Removal / Installation**							RE (O/C)			
29 A/F		Right					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:29-13-01												
291315		**Hydraulic System Pressure Filter Element (EMP) - Removal / Installation**							RE (O/C)			
29 A/F		Left					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:29-13-01												
291316		**Hydraulic System Pressure Filter Element (EMP) - Removal / Installation**							RE (O/C)			
29 A/F		Right					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:29-13-01												
291323		**Hydraulic System Return Filter Assembly - Removal / Installation**							RE (O/C)			
29 A/F		Left					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:29-13-02												
291324		**Hydraulic System Return Filter Assembly - Removal / Installation**							RE (O/C)			
29 A/F		Right					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:29-13-02												
291327		**Hydraulic System Return Filter Element - Removal / Installation**							RE (O/C)			
29 A/F		Left	0				Mos	20-Nov-2022				
AEC6118		New	0				Hrs	0				
00514			0				Ldg	0				
Mfg#:29-13-02												
291328		**Hydraulic System Return Filter Element - Removal / Installation**							RE (O/C)			
29 A/F		Right	0				Mos	20-Nov-2022				
AEC6118		New	0				Hrs	0				
00520			0				Ldg	0				
Mfg#:29-13-02												
293105		**Hydraulic Temperature Sensor - Removal / Installation**							RE (O/C)			
29 A/F		Left	0				Mos	20-Nov-2022				
9634		New	0				Hrs	0				
NSN			0				Ldg	0				
Mfg#:29-31-02												
293106		**Hydraulic Temperature Sensor - Removal / Installation**							RE (O/C)			
29 A/F		Right	0				Mos	20-Nov-2022				
9634		New	0				Hrs	0				
NSN			0				Ldg	0				
Mfg#:29-31-02												

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
293111		**Manifold Pressure Switch (EDP) - Removal / Installation**							RE (O/C)			
29 A/F		Left	0				Mos	20-Nov-2022				
15778		New	0				Hrs	0				
1321			0				Ldg	0				
Mfg#:29-31-03												
293112		**Manifold Pressure Switch (EDP) - Removal / Installation**							RE (O/C)			
29 A/F		Right	0				Mos	20-Nov-2022				
15778		New	0				Hrs	0				
1318			0				Ldg	0				
Mfg#:29-31-03												
293115		**Manifold Pressure Switch (EMP) - Removal / Installation**							RE (O/C)			
29 A/F		Left	0				Mos	20-Nov-2022				
15777		New	0				Hrs	0				
0911			0				Ldg	0				
Mfg#:29-31-03												
293116		**Manifold Pressure Switch (EMP) - Removal / Installation**							RE (O/C)			
29 A/F		Right	0				Mos	20-Nov-2022				
15777		New	0				Hrs	0				
0909			0				Ldg	0				
Mfg#:29-31-03												
293119		**Manifold Pressure Transmitter - Removal / Installation**							RE (O/C)			
29 A/F		Left	0				Mos	20-Nov-2022				
IPTE-16-1000-4000A		New	0				Hrs	0				
8814-3-95			0				Ldg	0				
Mfg#:29-31-03												
293120		**Manifold Pressure Transmitter - Removal / Installation**							RE (O/C)			
29 A/F		Right	0				Mos	20-Nov-2022				
IPTE-16-1000-4000A		New	0				Hrs	0				
8814-3-89			0				Ldg	0				
Mfg#:29-31-03												
293201		**Hydraulic System Pressure Filter Differential Pressure Switch (EDP) - Removal / Installation**							RE (O/C)			
29 A/F		Left					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:29-13-01												
293202		**Hydraulic System Pressure Filter Differential Pressure Switch (EDP) - Removal / Installation**							RE (O/C)			
29 A/F		Right					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:29-13-01												
293203		**Hydraulic System Pressure Filter Differential Pressure Switch (EMP) - Removal / Installation**							RE (O/C)			
29 A/F		Left					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:29-13-01												
293204		**Hydraulic System Pressure Filter Differential Pressure Switch (EMP) - Removal / Installation**							RE (O/C)			
29 A/F		Right					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:29-13-01												

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
293205		**Hydraulic System Return Filter Differential Pressure Switch - Removal / Installation**							RE (O/C)			
29 A/F		Left					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
	Mfg#:29-13-02											
293206		**Hydraulic System Return Filter Differential Pressure Switch - Removal / Installation**							RE (O/C)			
29 A/F		Right					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
	Mfg#:29-13-02											
301101		**Wing Anti-ice Crossover Valve - Removal / Installation**							RE (O/C)			
30 A/F			0				Mos	20-Nov-2022				
63292106-2		New	0				Hrs	0				
378			0				Ldg	0				
301103		**Wing Anti-ice Valve - Removal / Installation**							RE (O/C)			
30 A/F		Left	0				Mos	20-Nov-2022				
3215976-1		New	0				Hrs	0				
653			0				Ldg	0				
	Mfg#:30-11-01											
301104		**Wing Anti-ice Valve - Removal / Installation**							RE (O/C)			
30 A/F		Right	0				Mos	20-Nov-2022				
3215976-1		New	0				Hrs	0				
654			0				Ldg	0				
	Mfg#:30-11-01											
301107		**Wing Anti-ice Valve Filter - Removal / Installation**							RE (O/C)			
30 A/F		Left					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
	Mfg#:30-11-01											
301108		**Wing Anti-ice Valve Filter - Removal / Installation**							RE (O/C)			
30 A/F		Right					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
	Mfg#:30-11-01											
301113		**Wing Anti-ice Overtemperature Switch - Removal / Installation**							RE (O/C)			
30 A/F		Left Outboard					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
	Mfg#:30-11-02											
301114		**Wing Anti-ice Overtemperature Switch - Removal / Installation**							RE (O/C)			
30 A/F		Left Inboard					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
	Mfg#:30-11-02											
301115		**Wing Anti-ice Overtemperature Switch - Removal / Installation**							RE (O/C)			
30 A/F		Right Inboard					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
	Mfg#:30-11-02											

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
301116	**Wing Anti-ice Overtemperature Switch - Removal / Installation**							RE (O/C)			
30 A/F	Right Outboard					Mos	20-Nov-2022				
Unknown						Hrs	0				
Unknown						Ldg	0				
Mfg#:30-11-02											
301119	**Wing Anti-ice Over/Under Temperature Switch - Removal / Installation**							RE (O/C)			
30 A/F	Left					Mos	20-Nov-2022				
Unknown						Hrs	0				
Unknown						Ldg	0				
Mfg#:30-11-02											
301120	**Wing Anti-ice Over/Under Temperature Switch - Removal / Installation**							RE (O/C)			
30 A/F	Right					Mos	20-Nov-2022				
Unknown						Hrs	0				
Unknown						Ldg	0				
Mfg#:30-11-02											
301125	**Wing Anti-ice Temperature Sensor - Removal / Installation**							RE (O/C)			
30 A/F	Left	0				Mos	20-Nov-2022				
51090040-1	New	0				Hrs	0				
51090040-00645		0				Ldg	0				
Mfg#:30-11-03											
301126	**Wing Anti-ice Temperature Sensor - Removal / Installation**							RE (O/C)			
30 A/F	Right	0				Mos	20-Nov-2022				
51090040-1	New	0				Hrs	0				
51090040-00660		0				Ldg	0				
Mfg#:30-11-03											
302103	**Engine Nacelle Anti-ice Valve - Removal / Installation**							RE (O/C)			
30 A/F	Left	2				Mos	31-Jan-2023				
WBG3020G103-003		24:24				Hrs	24:24				
0968		7				Ldg	7				
Mfg#:30-21-01											
302104	**Engine Nacelle Anti-ice Valve - Removal / Installation**							RE (O/C)			
30 A/F	Right	2				Mos	27-Jan-2023				
WBG3020G103-003		24:24				Hrs	24:24				
0970		7				Ldg	7				
Mfg#:30-21-01											
302107	**Engine Anti-ice Pressure Switch - Removal / Installation**							RE (O/C)			
30 A/F	Left	2				Mos	30-Jan-2023				
WBA3020G107-007		24:24				Hrs	24:24				
2447		7				Ldg	7				
Mfg#:30-21-02											
302108	**Engine Anti-ice Pressure Switch - Removal / Installation**							RE (O/C)			
30 A/F	Right	2				Mos	27-Jan-2023				
WBA3020G107-007		24:24				Hrs	24:24				
2448		7				Ldg	7				
Mfg#:30-21-02											
304103	**Windshield De-ice Controller - Removal / Installation**							RE (O/C)			
30 A/F	Pilot	0				Mos	20-Nov-2022				
300-048-130	New	0				Hrs	0				
1299		0				Ldg	0				
Mfg#:30-41-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
304104		**Windshield De-ice Controller - Removal / Installation**							RE (O/C)			
	30 A/F	Copilot	0				Mos	20-Nov-2022				
	300-048-130	New	0				Hrs	0				
	1284		0				Ldg	0				
	Mfg#:30-41-01											
308103		**Ice Detector - Removal / Installation**							RE (O/C)			
	30 A/F	Left	0				Mos	20-Nov-2022				
	0871LM4-1MOD 1	New	0				Hrs	0				
	2857		0				Ldg	0				
	Mfg#:30-81-01											
308104		**Ice Detector - Removal / Installation**							RE (O/C)			
	30 A/F	Right	0				Mos	20-Nov-2022				
	0871LM4-1MOD 1	New	0				Hrs	0				
	2861		0				Ldg	0				
	Mfg#:30-81-01											
311104		**Cockpit Overhead Switch Panel - Removal / Installation**							RE (O/C)			
	31 A/F		0				Mos	20-Nov-2022				
	110TS11ABY03	New	0				Hrs	0				
	0620		0				Ldg	0				
311106		**Cockpit Overhead Switching Panel - Removal / Installation**							RE (O/C)			
	31 A/F		0				Mos	20-Nov-2022				
	109TS11AAY05	New	0				Hrs	0				
	0341		0				Ldg	0				
311202		**Landing Gear Control Panel - Removal / Installation**							RE (O/C)			
	31 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:31-12-01											
313106		**Enhanced Multipurpose Flight Recorder (FDR) - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	7				Mos	04-Jun-2024				
	D51615-3411-250	New	0				Hrs	866:28				
	A28894-001		0				Ldg	501				
	Mfg#:31-31-01											
313107		**Enhanced Multipurpose Flight Recorder (CVR) - Removal / Installation**							RE (O/C)			
	31 A/F	No.1					Mos	01-Jun-2024				
	D51615-3411-250						Hrs	848:22				
	A27306-002						Ldg	497				
	ATA Ref::31-31-01, Ref#:31-31-01											
313108		**Recorder Independent Power Supply - Removal / Installation**							RE (O/C)			
	31 A/F		0				Mos	20-Nov-2022				
	100-3010-001	New	0				Hrs	0				
	002425		0				Ldg	0				
	Mfg#:31-31-01											
313110		**Cockpit Control Unit - Removal / Installation**							RE (O/C)			
	31 A/F		0				Mos	20-Nov-2022				
	D51616-1021	New	0				Hrs	0				
	A26220-004		0				Ldg	0				
	Mfg#:31-31-02											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
313111		**Recorder Independent Power Supply Battery Pack - Removal / Installation**							RE (O/C)			
	31 A/F		0				Mos	20-Nov-2022				
	100-3010-001	New	0				Hrs	0				
	002425		0				Ldg	0				
313112		**Cockpit Area Microphone - Removal / Installation**							RE (O/C)			
	31 A/F		0				Mos	20-Nov-2022				
	D51702-10	New	0				Hrs	0				
	568		0				Ldg	0				
	Mfg#:31-31-03											
313114		**Underwater Locator Beacon (ULB) - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	2				Mos	09-Feb-2023				
	Unknown		24:24				Hrs	24:24				
	Unknown		7				Ldg	7				
	Mfg#:31-31-05-RI											
313116		**Underwater Locator Beacon Battery - Removal / Installation**							RE (O/C)			
	31 A/F	No.1					Mos	01-Jun-2024				
	DK290-11						Hrs	848:22				
	JM004064						Ldg	497				
	Mfg#:31-31-05-RI											
313123		**Inertial Switch - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	3LO-871/6	New	0				Hrs	0				
	126525		0				Ldg	0				
	Mfg#:31-31-04-RI											
313124		**Inertial Switch - Removal / Installation**							RE (O/C)			
	31 A/F	No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Ref#:31-31-04-RI											
313126		**Underwater Locator Beacon (ULB) - Removal / Installation**							RE (O/C)			
	31 A/F	No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Ref#:31-31-05-RI											
313127		**Underwater Locator Beacon (ULB) Battery - Removal / Installation**							RE (O/C)			
	31 A/F	No.2					Mos	04-Jun-2024				
	DK290-11	New	0				Hrs	866:28				
	JM005679		0				Ldg	501				
	ATA Ref::31-31-05, Ref#:31-31-05-RI											
313131		**Accelerometer - Removal / Installation**							RE (O/C)			
	31 A/F		0				Mos	10-Feb-2023				
	971-4193-001	New	0				Hrs	24:24				
	20378		0				Ldg	7				
314106		**Integrated Processing Cabinet - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-2404-101	New	0				Hrs	0				
	4PT36Y		0				Ldg	0				
	Mfg#:31-41-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
314107		**Integrated Processing Cabinet - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-2404-101	New	0				Hrs	0				
	4PT56Y		0				Ldg	0				
	Mfg#:31-41-01											
314108		**Integrated Processing Cabinet - Removal / Installation**							RE (O/C)			
	31 A/F	No.3	0				Mos	20-Nov-2022				
	822-2142-101	New	0				Hrs	0				
	4M86X1		0				Ldg	0				
	Mfg#:31-41-01											
314114		**Cover and Environmental Module (IPC) - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-2405-101	New	0				Hrs	0				
	4RT0RT		0				Ldg	0				
	Mfg#:31-41-02											
314115		**Cover and Environmental Module (IPC) - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-2405-101	New	0				Hrs	0				
	4RT0RN		0				Ldg	0				
	Mfg#:31-41-02											
314116		**Cover and Environmental Module (IPC) - Removal / Installation**							RE (O/C)			
	31 A/F	No.3	0				Mos	20-Nov-2022				
	822-2406-101	New	0				Hrs	0				
	4T10TK		0				Ldg	0				
	Mfg#:31-41-02											
314123		**Integrated Processing Cabinet Module (CCM No. 1) - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-1991-002	New	0				Hrs	0				
	4PT4C2		0				Ldg	0				
	Mfg#:31-41-03-RI											
314124		**Integrated Processing Cabinet Module (CCM No. 2) - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-1991-002	New	0				Hrs	0				
	4PT49T		0				Ldg	0				
	Mfg#:31-41-03-RI											
314125		**Integrated Processing Cabinet Module (CCM No. 3) - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-1991-002	New	0				Hrs	0				
	4PT64H		0				Ldg	0				
	Mfg#:31-41-03-RI											
314126		**Integrated Processing Cabinet Module (CCM No. 1) - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-1991-002	New	0				Hrs	0				
	4PT617		0				Ldg	0				
	Mfg#:31-41-03-RI											
314127		**Integrated Processing Cabinet Module (CCM No. 2) - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-1991-002	New	0				Hrs	0				
	4PT49V		0				Ldg	0				
	Mfg#:31-41-03-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
314128		**Common Computer Module No. 6 (Cab No. 2) - Removal / Installation**							RE (O/C)			
	31 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
314130		**Integrated Processing Cabinet Module (CCM No. 1) - Removal / Installation**							RE (O/C)			
	31 A/F	No.3					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:31-41-03-RI											
314132		**Integrated Processing Cabinet Module (TAWS CCM) - Removal / Installation**							RE (O/C)			
	31 A/F	No.3	0				Mos	20-Nov-2022				
	822-2192-002	New	0				Hrs	0				
	4T10XK		0				Ldg	0				
	Mfg#:31-41-03-RI											
314134		**Integrated Processing Cabinet Module (TPM) - Removal / Installation**							RE (O/C)			
	31 A/F	No.3	0				Mos	20-Nov-2022				
	822-2586-001	New	0				Hrs	0				
	4T0K9H		0				Ldg	0				
	Mfg#:31-41-03-RI											
314138		**Integrated Processing Cabinet Module (DSM) - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-2133-020	New	0				Hrs	0				
	4R0GL5		0				Ldg	0				
	Mfg#:31-41-03-RI											
314139		**Integrated Processing Cabinet Module (DSM) - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-2133-020	New	0				Hrs	0				
	4R0GKX		0				Ldg	0				
	Mfg#:31-41-03-RI											
314140		**Integrated Processing Cabinet Module (DSM) - Removal / Installation**							RE (O/C)			
	31 A/F	No.3	0				Mos	20-Nov-2022				
	822-2133-020	New	0				Hrs	0				
	4R0DV4		0				Ldg	0				
	Mfg#:31-41-03-RI											
314144		**Integrated Processing Cabinet Module (PEM) - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-2352-001	New	0				Hrs	0				
	4PT4GF		0				Ldg	0				
	Mfg#:31-41-03-RI											
314145		**Integrated Processing Cabinet Module (PEM) - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-2352-001	New	0				Hrs	0				
	4PT4GD		0				Ldg	0				
	Mfg#:31-41-03-RI											
314146		**Integrated Processing Cabinet Module (PEM) - Removal / Installation**							RE (O/C)			
	31 A/F	No.3	0				Mos	20-Nov-2022				
	822-2352-001	New	0				Hrs	0				
	4PT472		0				Ldg	0				
	Mfg#:31-41-03-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
315103		**Data Concentration Unit Cabinet - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-2403-111	New	0				Hrs	0				
	4PT60P		0				Ldg	0				
	Mfg#:31-51-01											
315104		**Data Concentration Unit Cabinet - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-2403-111	New	0				Hrs	0				
	4PT3F8		0				Ldg	0				
	Mfg#:31-51-01											
315107		**Cover and Environmental Module (DCU) - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-2401-001	New	0				Hrs	0				
	4RT09X		0				Ldg	0				
	Mfg#:31-51-02											
315108		**Cover and Environmental Module (DCU) - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-2401-001	New	0				Hrs	0				
	4RRY94		0				Ldg	0				
	Mfg#:31-51-02											
315113		**Data Concentration Unit Module (DCM Ch A, Slots 5-6-7) - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-2394-002	New	0				Hrs	0				
	4T13NK		0				Ldg	0				
	Mfg#:31-51-03-RI											
315114		**Data Concentration Unit Module (DCM Ch B, Slots 8-9-10) - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-2394-002	New	0				Hrs	0				
	4PT5RR		0				Ldg	0				
	Mfg#:31-51-03-RI											
315115		**Data Concentration Unit Module (DCM Ch A, Slots 5-6-7) - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-2394-002	New	0				Hrs	0				
	4PT4TR		0				Ldg	0				
	Mfg#:31-51-03-RI											
315116		**Data Concentration Unit Module (DCM Ch B, Slots 8-9-10) - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-2394-002	New	0				Hrs	0				
	4PPF8F		0				Ldg	0				
	Mfg#:31-51-03-RI											
315129		**Data Concentration Unit Module (IOM Ch A, Slot 3) - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-2397-011	New	0				Hrs	0				
	4RRXMN		0				Ldg	0				
	Mfg#:31-51-03-RI											
315130		**Data Concentration Unit Module (IOM Ch B, Slot 12) - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-2397-011	New	0				Hrs	0				
	4RRXMR		0				Ldg	0				
	Mfg#:31-51-03-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
315131		**Data Concentration Unit Module (IOM Ch A, Slot 3) - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-2397-011	New	0				Hrs	0				
	4N8NV5		0				Ldg	0				
	Mfg#:31-51-03-RI											
315132		**Data Concentration Unit Module (IOM Ch B, Slot 12) - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-2397-011	New	0				Hrs	0				
	4RRXMP		0				Ldg	0				
	Mfg#:31-51-03-RI											
315133		**Data Concentration Unit Module (IOM Ch A, Slot 2) - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-2396-012	New	0				Hrs	0				
	4RRXCR		0				Ldg	0				
	Mfg#:31-51-03-RI											
315134		**Data Concentration Unit Module (IOM Ch A, Slot 4) - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-2396-012	New	0				Hrs	0				
	4RRXCT		0				Ldg	0				
	Mfg#:31-51-03-RI											
315135		**Data Concentration Unit Module (IOM Ch B, Slot 13) - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-2396-012	New	0				Hrs	0				
	4RRXH0		0				Ldg	0				
	Mfg#:31-51-03-RI											
315136		**Data Concentration Unit Module (IOM Ch B, Slot 11) - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-2396-012	New	0				Hrs	0				
	4RRXCM		0				Ldg	0				
	Mfg#:31-51-03-RI											
315137		**Data Concentration Unit Module (IOM Ch A, Slot 2) - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-2396-012	New	0				Hrs	0				
	4RRXCL		0				Ldg	0				
	Mfg#:31-51-03-RI											
315138		**Data Concentration Unit Module (IOM Ch A, Slot 4) - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-2396-012	New	0				Hrs	0				
	4RRXCN		0				Ldg	0				
	Mfg#:31-51-03-RI											
315139		**Data Concentration Unit Module (IOM Ch B, Slot 13) - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-2396-012	New	0				Hrs	0				
	4RRXCP		0				Ldg	0				
	Mfg#:31-51-03-RI											
315140		**Data Concentration Unit Module (IOM Ch B, Slot 11) - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-2396-012	New	0				Hrs	0				
	4RRXH2		0				Ldg	0				
	Mfg#:31-51-03-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
315145		**Data Concentration Unit Module (PPM Ch A, Slot 1) - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-2395-002	New	0				Hrs	0				
	4T10Y2		0				Ldg	0				
	Mfg#:31-51-03-RI											
315146		**Data Concentration Unit Module (PPM Ch B, Slot 14) - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-2395-002	New	0				Hrs	0				
	4RT04K		0				Ldg	0				
	Mfg#:31-51-03-RI											
315147		**Data Concentration Unit Module (PPM Ch A, Slot 1) - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-2395-002	New	0				Hrs	0				
	4T10XY		0				Ldg	0				
	Mfg#:31-51-03-RI											
315148		**Data Concentration Unit Module (PPM Ch B, Slot 14) - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-2395-002	New	0				Hrs	0				
	4T10YL		0				Ldg	0				
	Mfg#:31-51-03-RI											
315151		**Data Concentrator Unit Aircraft Personality Module - Removal / Installation**							RE (O/C)			
	31 A/F	Left	0				Mos	20-Nov-2022				
	822-2195-001	New	0				Hrs	0				
	4PT4XK		0				Ldg	0				
	Mfg#:31-51-04											
315152		**Data Concentrator Unit Aircraft Personality Module - Removal / Installation**							RE (O/C)			
	31 A/F	Right	0				Mos	20-Nov-2022				
	822-2195-001	New	0				Hrs	0				
	4PT43G		0				Ldg	0				
	Mfg#:31-51-04											
315303		**Master Warning / Caution Panel - Removal / Installation**							RE (O/C)			
	31 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
315304		**Master Warning / Caution Panel - Removal / Installation**							RE (O/C)			
	31 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
316304		**Adaptive Flight Display - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-2276-440	New	0				Hrs	0				
	4R5L9Y		0				Ldg	0				
	Mfg#:31-63-01											
316305		**Adaptive Flight Display - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-2276-440	New	0				Hrs	0				
	4RFLTM		0				Ldg	0				
	Mfg#:31-63-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
316306		**Adaptive Flight Display - Removal / Installation**							RE (O/C)			
	31 A/F	No.3	0				Mos	20-Nov-2022				
	822-2276-440	New	0				Hrs	0				
	4MCG6T		0				Ldg	0				
	Mfg#:31-63-01											
316309		**Display Control Panel - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-2333-001	New	0				Hrs	0				
	4MRL5R		0				Ldg	0				
	Mfg#:31-63-03											
316310		**Display Control Panel - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-2333-001	New	0				Hrs	0				
	4P5RCX		0				Ldg	0				
	Mfg#:31-63-03											
316313		**Display Select Panel - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	822-2334-001	New	0				Hrs	0				
	4MC9N8		0				Ldg	0				
	Mfg#:31-63-04											
316314		**Display Select Panel - Removal / Installation**							RE (O/C)			
	31 A/F	No.2	0				Mos	20-Nov-2022				
	822-2334-001	New	0				Hrs	0				
	4MC93V		0				Ldg	0				
	Mfg#:31-63-04											
316318		**Adaptive Flight Display Tray - Removal / Installation**							RE (O/C)			
	31 A/F	No.1					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
316319		**Adaptive Flight Display Tray - Removal / Installation**							RE (O/C)			
	31 A/F	No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
316320		**Adaptive Flight Display Tray - Removal / Installation**							RE (O/C)			
	31 A/F	No.3					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
316322		**Display Dimmer Panel - Removal / Installation**							RE (O/C)			
	31 A/F		0				Mos	20-Nov-2022				
	822-2830-001	New	0				Hrs	0				
	4MC8FR		0				Ldg	0				
	Mfg#:31-63-06											
316325		**Cursor Control Device - Removal / Installation**							RE (O/C)			
	31 A/F	No.1	0				Mos	20-Nov-2022				
	999-7913	New	0				Hrs	0				
	0276		0				Ldg	0				
	Mfg#:31-63-05											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
316326		**Cursor Control Device - Removal / Installation**							RE (O/C)			
31 A/F		No.2	0				Mos	20-Nov-2022				
	999-7914	New	0				Hrs	0				
	0282		0				Ldg	0				
	Mfg#:31-63-05											
317051		**Quick Access Recorder (QAR) - Removal / Installation**							RE (O/C)			
31 A/F			0				Mos	10-Feb-2023				
	OAR200-35-04	New	0				Hrs	24:24				
	002079910		0				Ldg	7				
321003		**Main Landing Gear - Removal / Installation**							RE (O/C)			
32 A/F		Left	0				Mos	20-Nov-2022				
	30A2520100-509	New	0				Hrs	0				
	257		0				Ldg	0				
	Mfg#:32-10-00-RI											
321004		**Main Landing Gear - Removal / Installation**							RE (O/C)			
32 A/F		Right	0				Mos	20-Nov-2022				
	30A2520100-510	New	0				Hrs	0				
	257		0				Ldg	0				
	Mfg#:32-10-00-RI											
321103		**Main Landing Gear Support Strut - Removal / Installation**							RE (O/C)			
32 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-11-01-RI											
321104		**Main Landing Gear Support Strut - Removal / Installation**							RE (O/C)			
32 A/F		Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-11-01-RI											
321109		**Main Landing Gear Shock Absorber - Removal / Installation**							RE (O/C)			
32 A/F		Left	0				Mos	20-Nov-2022				
	30A2520200-501	New	0				Hrs	0				
	519		0				Ldg	0				
	Mfg#:32-11-02											
321110		**Main Landing Gear Shock Absorber - Removal / Installation**							RE (O/C)			
32 A/F		Right	0				Mos	20-Nov-2022				
	30A2520200-501	New	0				Hrs	0				
	522		0				Ldg	0				
	Mfg#:32-11-02											
321117		**Main Landing Gear Trailing Link - Removal / Installation**							RE (O/C)			
32 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-11-03-RI											
321118		**Main Landing Gear Trailing Link - Removal / Installation**							RE (O/C)			
32 A/F		Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-11-03-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
321203		**Main Landing Gear Side Brace Assembly - Removal / Installation**							RE (O/C)			
32 A/F		Left	0				Mos	20-Nov-2022				
	30A2520300-503	New	0				Hrs	0				
	258		0				Ldg	0				
	Mfg#:32-12-01-RI											
321204		**Main Landing Gear Side Brace Assembly - Removal / Installation**							RE (O/C)			
32 A/F		Right	0				Mos	20-Nov-2022				
	30A2520300-504	New	0				Hrs	0				
	258		0				Ldg	0				
	Mfg#:32-12-01-RI											
321207		**Main Landing Gear Upper Side Brace - Removal / Installation**							RE (O/C)			
32 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-12-01-RI											
321208		**Main Landing Gear Upper Side Brace (Right) - Removal / Installation**							RE (O/C)			
32 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
321211		**Main Landing Gear Lower Side Brace - Removal / Installation**							RE (O/C)			
32 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-12-01-RI											
321212		**Main Landing Gear Lower Side Brace - Removal / Installation**							RE (O/C)			
32 A/F		Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-12-01-RI											
321215		**Main Landing Gear Side Brace Universal Link - Removal / Installation**							RE (O/C)			
32 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-12-01-RI											
321216		**Main Landing Gear Side Brace Universal Link - Removal / Installation**							RE (O/C)			
32 A/F		Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-12-01-RI											
321307		**Main Landing Gear Inboard Door - Removal / Installation**							RE (O/C)			
32 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-13-01											
321308		**Main Landing Gear Inboard Door - Removal / Installation**							RE (O/C)			
32 A/F		Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-13-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
321311		**Main Landing Gear Outboard Door - Removal / Installation**							RE (O/C)			
	32 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-13-02											
321312		**Main Landing Gear Outboard Door - Removal / Installation**							RE (O/C)			
	32 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-13-02											
321317		**Main Landing Gear Outboard Door Hinge - Removal / Installation**							RE (O/C)			
	32 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-13-02											
321318		**Main Landing Gear Outboard Door Hinge - Removal / Installation**							RE (O/C)			
	32 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-13-02											
321321		**Main Landing Gear Inboard Door Mechanism - Removal / Installation**							RE (O/C)			
	32 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-13-03-RI											
321322		**Main Landing Gear Inboard Door Mechanism - Removal / Installation**							RE (O/C)			
	32 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-13-03-RI											
321325		**Main Landing Gear Outboard Door Spring Rod - Removal / Installation**							RE (O/C)			
	32 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-13-03-RI											
321326		**Main Landing Gear Outboard Door Spring Rod - Removal / Installation**							RE (O/C)			
	32 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-13-03-RI											
321331		**Main Landing Gear Door Lower Rod Assembly - Removal / Installation**							RE (O/C)			
	32 A/F	Left	0				Mos	20-Nov-2022				
	30P265036001-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:32-13-03-RI											
321332		**Main Landing Gear Door Lower Rod Assembly - Removal / Installation**							RE (O/C)			
	32 A/F	Right	0				Mos	20-Nov-2022				
	30P265036001-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:32-13-03-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
322002		**Nose Landing Gear - Removal / Installation**							RE (O/C)			
	32 A/F		0				Mos	20-Nov-2022				
	30A2720150-503	New	0				Hrs	0				
	257		0				Ldg	0				
	Mfg#:32-20-00											
322102		**Nose Landing Gear Shock Strut Assembly - Removal / Installation**							RE (O/C)			
	32 A/F		0				Mos	20-Nov-2022				
	30A2720150-503	New	0				Hrs	0				
	257		0				Ldg	0				
	Mfg#:32-21-01-RI											
322108		**Nose Landing Gear Shock Absorber - Removal / Installation**							RE (O/C)			
	32 A/F		0				Mos	20-Nov-2022				
	30A2720200-501	New	0				Hrs	0				
	265		0				Ldg	0				
322109		**Nose Landing Gear Drag Brace Assembly - Removal / Installation**							RE (O/C)			
	32 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
322110		**Nose Landing Gear Drag Brace - Removal / Installation**							RE (O/C)			
	32 A/F	Lower	0				Mos	20-Nov-2022				
	30A2720300-503	New	0				Hrs	0				
	256		0				Ldg	0				
	Mfg#:32-21-02-RI											
322114		**Nose Landing Gear Drag Brace - Removal / Installation**							RE (O/C)			
	32 A/F	Upper					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-21-02-RI											
322118		**Nose Landing Gear Universal Link - Removal / Installation**							RE (O/C)			
	32 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-21-02-RI											
322121		**Nose Landing Gear Jury Brace - Removal / Installation**							RE (O/C)			
	32 A/F	Upper					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-21-03-RI											
322122		**Nose Landing Gear Jury Brace - Removal / Installation**							RE (O/C)			
	32 A/F	Lower					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-21-03-RI											
322125		**Nose Landing Gear Torque Link - Removal / Installation**							RE (O/C)			
	32 A/F	Upper					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-21-04-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
322126		**Nose Landing Gear Torque Link - Removal / Installation**							RE (O/C)			
	32 A/F	Lower					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-21-04-RI											
322131		**Nose Landing Gear Downlock Springs - Removal / Installation**							RE (O/C)			
	32 A/F	Left	0				Mos	20-Nov-2022				
	30A2720310-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:32-21-05-RI											
322132		**Nose Landing Gear Downlock Springs - Removal / Installation**							RE (O/C)			
	32 A/F	Right	0				Mos	20-Nov-2022				
	30A2720310-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:32-21-05-RI											
322136		**Nose Landing Gear Towing Adapter - Removal / Installation**							RE (O/C)			
	32 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-21-06											
322203		**Nose Landing Gear Door - Removal / Installation**							RE (O/C)			
	32 A/F	Left Fwd	0				Mos	20-Nov-2022				
	30P283311100-001	New	0				Hrs	0				
	2253		0				Ldg	0				
	Mfg#:32-22-01											
322204		**Nose Landing Gear Door - Removal / Installation**							RE (O/C)			
	32 A/F	Right Fwd	0				Mos	20-Nov-2022				
	30P283321100-001	New	0				Hrs	0				
	2253		0				Ldg	0				
	Mfg#:32-22-01											
322208		**Nose Landing Gear Aft Door - Removal / Installation**							RE (O/C)			
	32 A/F		0				Mos	20-Nov-2022				
	30P283331100-001	New	0				Hrs	0				
	2253		0				Ldg	0				
	Mfg#:32-22-02-RI											
323102		**Landing Gear Selector Valve - Removal / Installation**							RE (O/C)			
	32 A/F		0				Mos	20-Nov-2022				
	3451	New	0				Hrs	0				
	1269		0				Ldg	0				
	Mfg#:32-31-01-RI											
323104		**Landing Gear Handle Assembly - Removal / Installation**							RE (O/C)			
	32 A/F		0				Mos	20-Nov-2022				
	801201-25	New	0				Hrs	0				
	300		0				Ldg	0				
	Mfg#:32-31-02											
323106		**Landing Gear Control Cable - Removal / Installation**							RE (O/C)			
	32 A/F		0				Mos	20-Nov-2022				
	38027300	New	0				Hrs	0				
	0266		0				Ldg	0				
	Mfg#:32-31-03-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
323203		**Main Landing Gear Actuator - Removal / Installation**							RE (O/C)			
32 A/F		Left	0				Mos	20-Nov-2022				
	30A2520400-513	New	0				Hrs	0				
	263		0				Ldg	0				
	Mfg#:32-32-01-RI											
323204		**Main Landing Gear Actuator - Removal / Installation**							RE (O/C)			
32 A/F		Right	0				Mos	20-Nov-2022				
	30A2520400-514	New	0				Hrs	0				
	263		0				Ldg	0				
	Mfg#:32-32-01-RI											
323209		**Main Landing Gear Uplock Assembly - Removal / Installation**							RE (O/C)			
32 A/F		Left	0				Mos	20-Nov-2022				
	30A2520700-505	New	0				Hrs	0				
	261		0				Ldg	0				
	Mfg#:32-32-02											
323210		**Main Landing Gear Uplock Assembly - Removal / Installlation**							RE (O/C)			
32 A/F		Right	0				Mos	20-Nov-2022				
	30A2520700-506	New	0				Hrs	0				
	260		0				Ldg	0				
	Mfg#:32-32-02											
323302		**Nose Landing Gear Actuator - Removal / Installation**							RE (O/C)			
32 A/F			0				Mos	20-Nov-2022				
	28300-000-00	New	0				Hrs	0				
	IL-529AB		0				Ldg	0				
	Mfg#:32-33-01											
323306		**Nose Landing Gear Unlock Actuator - Removal / Installation**							RE (O/C)			
32 A/F			0				Mos	20-Nov-2022				
	28500-000-00	New	0				Hrs	0				
	IL-516		0				Ldg	0				
	Mfg#:32-33-02-RI											
323308		**Nose Landing Gear Uplock Assembly - Removal / Installation**							RE (O/C)			
32 A/F			0				Mos	20-Nov-2022				
	28400-000-01	New	0				Hrs	0				
	IL-525		0				Ldg	0				
	Mfg#:32-33-03											
323404		**Emergency Landing Gear Pressure Vessel - Removal / Installation**							RE (O/C)			
32 A/F							Mos	10-Feb-2023				
	41004664						Hrs	24:24				
	E4356D1						Ldg	7				
	Mfg#:32-34-01											
323408		**Emergency Landing Gear Pressure Vessel Transducer - Removal / Installation**							RE (O/C)			
32 A/F			0				Mos	20-Nov-2022				
	IPTE-16-1000-4000A	New	0				Hrs	0				
	8823-11-50		0				Ldg	0				
	Mfg#:32-34-01											
323410		**Emergency Landing Gear Pressure Vessel Gage - Removal / Installation**							RE (O/C)			
32 A/F			0				Mos	20-Nov-2022				
	GP20-24	New	0				Hrs	0				
	2490743-7		0				Ldg	0				
	Mfg#:32-34-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
323412		**Emergency Landing Gear Selector Valve - Removal / Installation**							RE (O/C)			
32 A/F			0				Mos	20-Nov-2022				
	42000821-1	New	0				Hrs	0				
	VA-00277		0				Ldg	0				
	Mfg#:32-34-02											
323414		**Emergency Landing Gear Dump Valve - Removal / Installation**							RE (O/C)			
32 A/F			0				Mos	20-Nov-2022				
	283279-0001/REV-F	New	0				Hrs	0				
	M1046		0				Ldg	0				
	Mfg#:32-34-03											
323416		**Emergency Landing Gear Cable - Removal / Installation**							RE (O/C)			
32 A/F			0				Mos	20-Nov-2022				
	38027500	New	0				Hrs	0				
	0278		0				Ldg	0				
	Mfg#:32-34-04											
324105		**Main Wheel Assembly - Removal / Installation**							RE (O/C)			
32 A/F		Left Outboard					Mos	03-Aug-2024				
	30P255001001-501	Repaired				0	Hrs	985:12				
	OCT21-1492					0	Ldg	575				
	Mfg#:32-41-01											
324106		**Main Wheel Assembly - Removal / Installation**							RE (O/C)			
32 A/F		Left Inboard					Mos	03-Aug-2024				
	30P255001001-501	Repaired				0	Hrs	985:12				
	MAY22-1540					0	Ldg	575				
	Mfg#:32-41-01											
324107		**Main Wheel Assembly - Removal / Installation**							RE (O/C)			
32 A/F		Right Inboard					Mos	28-Aug-2024				
	90005996	Repaired				0	Hrs	1058				
	DEC21-1508					0	Ldg	618				
	Mfg#:32-41-01											
324108		**Main Wheel Assembly - Removal / Installation**							RE (O/C)			
32 A/F		Right Outboard					Mos	28-Aug-2024				
	90005996	Repaired				0	Hrs	1058				
	JAN22-1511					0	Ldg	618				
	Mfg#:32-41-01											
324203		**Nose Wheel Assembly - Removal / Installation**							RE (O/C)			
32 A/F		Left					Mos	28-Aug-2024				
	90005995	Repaired				0	Hrs	1058				
	JAN22-0911					0	Ldg	618				
	Mfg#:32-42-01-RI											
324204		**Nose Wheel Assembly - Removal / Installation**							RE (O/C)			
32 A/F		Right					Mos	28-Aug-2024				
	90005995	Repaired				0	Hrs	1058				
	JAN22-0916					0	Ldg	618				
	Mfg#:32-42-01-RI											
324305		**Brake Assembly - Removal / Installation**							RE (O/C)			
32 A/F		Left Outboard	0				Mos	20-Nov-2022				
	90005997-1	New	0				Hrs	0				
	JAN22-1132		0				Ldg	0				
	Mfg#:32-43-01-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
324306		**Brake Assembly - Removal / Installation**							RE (O/C)			
32 A/F	90005997-1	Left Inboard New	0 0				Mos Hrs	20-Nov-2022 0				
	JAN22-1130		0				Ldg	0				
	Mfg#:32-43-01-RI											
324307		**Brake Assembly - Removal / Installation**							RE (O/C)			
32 A/F	90005997-1	Right Inboard New	0 0				Mos Hrs	20-Nov-2022 0				
	JUN22-1161		0				Ldg	0				
	Mfg#:32-43-01-RI											
324308		**Brake Assembly - Removal / Installation**							RE (O/C)			
32 A/F	90005997-1	Right Outboard New	0 0				Mos Hrs	20-Nov-2022 0				
	JUN22-1164		0				Ldg	0				
	Mfg#:32-43-01-RI											
324406		**Brake Control Unit - Removal / Installation**							RE (O/C)			
32 A/F	90006001-2	New	0 0				Mos Hrs	20-Nov-2022 0				
	APR22-5681		0				Ldg	0				
	Mfg#:32-44-01											
324411		**Brake Control Valve - Removal / Installation**							RE (O/C)			
32 A/F	90005990-1	Left Outboard New	0 0				Mos Hrs	20-Nov-2022 0				
	21-06-1142		0				Ldg	0				
	Mfg#:32-44-02											
324412		**Brake Control Valve - Removal / Installation**							RE (O/C)			
32 A/F	90005990-1	Left Inboard New	0 0				Mos Hrs	20-Nov-2022 0				
	21-05-1137		0				Ldg	0				
	Mfg#:32-44-02											
324413		**Brake Control Valve - Removal / Installation**							RE (O/C)			
32 A/F	90005990-1	Right Inboard New	0 0				Mos Hrs	20-Nov-2022 0				
	22-01-1152		0				Ldg	0				
	Mfg#:32-44-02											
324414		**Brake Control Valve - Removal / Installation**							RE (O/C)			
32 A/F	90005990-1	Right Outboard New	0 0				Mos Hrs	20-Nov-2022 0				
	20-09-1116		0				Ldg	0				
	Mfg#:32-44-02											
324417		**Brake Shut-off Valve - Removal / Installation**							RE (O/C)			
32 A/F	90005991	Left New	0 0				Mos Hrs	20-Nov-2022 0				
	SEP21-0563		0				Ldg	0				
	Mfg#:32-44-03											
324418		**Brake Shut-off Valve - Removal / Installation**							RE (O/C)			
32 A/F	90005991	Right New	0 0				Mos Hrs	20-Nov-2022 0				
	OCT21-0566		0				Ldg	0				
	Mfg#:32-44-03											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
324425		**Shuttle Valve - Removal / Installation**							RE (O/C)			
	32 A/F	Left Outboard	0				Mos	20-Nov-2022				
	5156	New	0				Hrs	0				
	DEC21-1022		0				Ldg	0				
	Mfg#:32-44-04											
324426		**Shuttle Valve - Removal / Installation**							RE (O/C)			
	32 A/F	Left Inboard	0				Mos	20-Nov-2022				
	5156	New	0				Hrs	0				
	DEC21-1017		0				Ldg	0				
	Mfg#:32-44-04											
324427		**Shuttle Valve - Removal / Installation**							RE (O/C)			
	32 A/F	Right Inboard	0				Mos	20-Nov-2022				
	5156	New	0				Hrs	0				
	DEC21-1072		0				Ldg	0				
	Mfg#:32-44-04											
324428		**Shuttle Valve - Removal / Installation**							RE (O/C)			
	32 A/F	Right Outboard	0				Mos	20-Nov-2022				
	5156	New	0				Hrs	0				
	JAN22-1074		0				Ldg	0				
	Mfg#:32-44-04											
324435		**Hydraulic Fuse - Removal / Installation**							RE (O/C)			
	32 A/F	Left Outboard	0				Mos	20-Nov-2022				
	6444	New	0				Hrs	0				
	DEC21-1057		0				Ldg	0				
	Mfg#:32-44-05											
324436		**Hydraulic Fuse - Removal / Installation**							RE (O/C)			
	32 A/F	Left Inboard	0				Mos	20-Nov-2022				
	6444	New	0				Hrs	0				
	DEC21-1051		0				Ldg	0				
	Mfg#:32-44-05											
324437		**Hydraulic Fuse - Removal / Installation**							RE (O/C)			
	32 A/F	Right Inboard	0				Mos	20-Nov-2022				
	6444	New	0				Hrs	0				
	DEC21-1058		0				Ldg	0				
	Mfg#:32-44-05											
324438		**Hydraulic Fuse - Removal / Installation**							RE (O/C)			
	32 A/F	Right Outboard	0				Mos	20-Nov-2022				
	6444	New	0				Hrs	0				
	DEC21-1061		0				Ldg	0				
	Mfg#:32-44-05											
324445		**Pedal Position Transducer - Removal / Installation**							RE (O/C)			
	32 A/F	Pilot - Left	0				Mos	20-Nov-2022				
	90005940-1	New	0				Hrs	0				
	JUN20-0981		0				Ldg	0				
	Mfg#:32-44-06											
324446		**Pedal Position Transducer - Removal / Installation**							RE (O/C)			
	32 A/F	Pilot - Right	0				Mos	20-Nov-2022				
	90005940-1	New	0				Hrs	0				
	JUL20-0997		0				Ldg	0				
	Mfg#:32-44-06											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
324447		**Pedal Position Transducer - Removal / Installation**							RE (O/C)			
	32 A/F	Copilot - Left	0				Mos	20-Nov-2022				
	90005940-1	New	0				Hrs	0				
	JAN21-1014		0				Ldg	0				
	Mfg#:32-44-06											
324448		**Pedal Position Transducer - Removal / Installation**							RE (O/C)			
	32 A/F	Copilot - Right	0				Mos	20-Nov-2022				
	90005940-1	New	0				Hrs	0				
	JUL20-0998		0				Ldg	0				
	Mfg#:32-44-06											
324453		**Brake Pressure Transducer - Removal / Installation**							RE (O/C)			
	32 A/F	Left Outboard	0				Mos	20-Nov-2022				
	90006334	New	0				Hrs	0				
	APR21-1035		0				Ldg	0				
	Mfg#:32-44-07											
324454		**Brake Pressure Transducer - Removal / Installation**							RE (O/C)			
	32 A/F	Left Inboard	0				Mos	20-Nov-2022				
	90006334	New	0				Hrs	0				
	NOV19-0933		0				Ldg	0				
	Mfg#:32-44-07											
324455		**Brake Pressure Transducer - Removal / Installation**							RE (O/C)			
	32 A/F	Right Inboard	0				Mos	20-Nov-2022				
	90006334	New	0				Hrs	0				
	JAN22-1083		0				Ldg	0				
	Mfg#:32-44-07											
324456		**Brake Pressure Transducer - Removal / Installation**							RE (O/C)			
	32 A/F	Right Outboard	0				Mos	20-Nov-2022				
	90006334	New	0				Hrs	0				
	APR21-1038		0				Ldg	0				
	Mfg#:32-44-07											
324458		**AUTOBRAKE Selector Switch - Removal / Installation**							RE (O/C)			
	32 A/F		0				Mos	20-Nov-2022				
	90006480-1	New	0				Hrs	0				
	MAR20-0875		0				Ldg	0				
	Mfg#:32-44-11											
324463		**Thermal Relief Valve - Removal / Installation**							RE (O/C)			
	32 A/F	Left	0				Mos	20-Nov-2022				
	RV99-250	New	0				Hrs	0				
	2440796-2		0				Ldg	0				
	Mfg#:32-44-08											
324464		**Thermal Relief Valve - Removal / Installation**							RE (O/C)			
	32 A/F	Right	0				Mos	20-Nov-2022				
	RV99-250	New	0				Hrs	0				
	2440796-1		0				Ldg	0				
	Mfg#:32-44-08											
324467		**Park / Emergency Brake Accumulator Release Valve - Removal / Installation**							RE (O/C)			
	32 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-44-09											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
324468		**Park / Emergency Brake Accumulator Release Valve - Removal / Installation**							RE (O/C)			
	32 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-44-09											
324475		**Brake Temperature Sensor - Removal / Installation**							RE (O/C)			
	32 A/F	Left Outboard	0				Mos	20-Nov-2022				
	90006116-1	New	0				Hrs	0				
	JUN21-0035		0				Ldg	0				
	Mfg#:32-44-10											
324476		**Brake Temperature Sensor - Removal / Installation**							RE (O/C)			
	32 A/F	Left Inboard	0				Mos	20-Nov-2022				
	90006116-1	New	0				Hrs	0				
	JUN21-0040		0				Ldg	0				
	Mfg#:32-44-10											
324477		**Brake Temperature Sensor - Removal / Installation**							RE (O/C)			
	32 A/F	Right Inboard	0				Mos	20-Nov-2022				
	90006116-1	New	0				Hrs	0				
	JUN21-0045		0				Ldg	0				
	Mfg#:32-44-10											
324478		**Brake Temperature Sensor - Removal / Installation**							RE (O/C)			
	32 A/F	Right Outboard	0				Mos	20-Nov-2022				
	90006116-1	New	0				Hrs	0				
	MAY20-0012		0				Ldg	0				
	Mfg#:32-44-10											
324505		**Park / Emergency Brake Accumulator - Removal / Installation**							RE (O/C)			
	32 A/F	Left	0				Mos	20-Nov-2022				
	7643	New	0				Hrs	0				
	DEC21-0508		0				Ldg	0				
	Mfg#:32-45-01											
324506		**Park / Emergency Brake Accumulator - Removal / Installation**							RE (O/C)			
	32 A/F	Right	0				Mos	20-Nov-2022				
	7643	New	0				Hrs	0				
	DEC21-0509		0				Ldg	0				
	Mfg#:32-45-01											
324510		**Dual Parking Brake Valve - Removal / Installation**							RE (O/C)			
	32 A/F		0				Mos	20-Nov-2022				
	90005993-1	New	0				Hrs	0				
	DEC21-0264		0				Ldg	0				
	Mfg#:32-45-02											
324512		**Parking / Emergency Brake Cable - Removal / Installation**							RE (O/C)			
	32 A/F		0				Mos	20-Nov-2022				
	38049900	New	0				Hrs	0				
	0277		0				Ldg	0				
	Mfg#:32-45-03											
324514		**Parking / Emergency Brake Handle Assembly - Removal / Installation**							RE (O/C)			
	32 A/F		0				Mos	20-Nov-2022				
	9401720300-1	New	0				Hrs	0				
	0207		0				Ldg	0				
	Mfg#:32-45-04											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
324517		**Park / Emergency Brake Accumulator Pressure Transducer - Removal / Installation**							RE (O/C)			
	32 A/F	Left	0				Mos	20-Nov-2022				
	IPTE-16-1000-4000A	New	0				Hrs	0				
	8883-5-76		0				Ldg	0				
	Mfg#:32-45-05											
324518		**Park / Emergency Brake Accumulator Pressure Transducer - Removal / Installation**							RE (O/C)			
	32 A/F	Right	0				Mos	20-Nov-2022				
	IPTE-16-1000-4000A	New	0				Hrs	0				
	8823-11-45		0				Ldg	0				
	Mfg#:32-45-05											
324523		**Emergency Brake Pressure Transducer - Removal / Installation**							RE (O/C)			
	32 A/F	Inboard	0				Mos	20-Nov-2022				
	IPTE-16-1000-4000A	New	0				Hrs	0				
	8823-11-46		0				Ldg	0				
	Mfg#:32-45-05											
324524		**Emergency Brake Pressure Transducer - Removal / Installation**							RE (O/C)			
	32 A/F	Outboard	0				Mos	20-Nov-2022				
	IPTE-16-1000-4000A	New	0				Hrs	0				
	8883-5-57		0				Ldg	0				
	Mfg#:32-45-05											
324527		**Park / Emergency Brake Accumulator Pressure Gage - Removal / Installation**							RE (O/C)			
	32 A/F	Left	0				Mos	20-Nov-2022				
	GP20-24	New	0				Hrs	0				
	2490743-3		0				Ldg	0				
	Mfg#:32-45-06											
324528		**Park / Emergency Brake Accumulator Pressure Gage - Removal / Installation**							RE (O/C)			
	32 A/F	Right	0				Mos	20-Nov-2022				
	GP20-24	New	0				Hrs	0				
	2490743-9		0				Ldg	0				
	Mfg#:32-45-06											
324605		**Wheel Speed Transducer - Removal / Installation**							RE (O/C)			
	32 A/F	Left Outboard					Mos	10-Feb-2023				
	90005994-1						Hrs	24:24				
	NOV21-1646						Ldg	7				
	Mfg#:32-46-01											
324606		**Wheel Speed Transducer - Removal / Installation**							RE (O/C)			
	32 A/F	Left Inboard	0				Mos	20-Nov-2022				
	90005994-1	New	0				Hrs	0				
	NOV21-1644		0				Ldg	0				
	Mfg#:32-46-01											
324607		**Wheel Speed Transducer - Removal / Installation**							RE (O/C)			
	32 A/F	Right Inboard	0				Mos	20-Nov-2022				
	90005994-1	New	0				Hrs	0				
	OCT21-1617		0				Ldg	0				
	Mfg#:32-46-01											
324608		**Wheel Speed Transducer - Removal / Installation**							RE (O/C)			
	32 A/F	Right Outboard	0				Mos	20-Nov-2022				
	90005994-1	New	0				Hrs	0				
	OCT21-1614		0				Ldg	0				
	Mfg#:32-46-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
325102		**Nose Wheel Steering Control Handle - Removal / Installation**							RE (O/C)			
	32 A/F		0				Mos	20-Nov-2022				
	230TS09Y01	New	0				Hrs	0				
	0812		0				Ldg	0				
	Mfg#:32-51-01											
325104		**Rudder Pedal Potentiometer - Removal / Installation**							RE (O/C)			
	32 A/F		0				Mos	20-Nov-2022				
	30A2520485-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:32-51-02											
325202		**Nose Wheel Steering Control Unit - Removal / Installation**							RE (O/C)			
	32 A/F		0				Mos	20-Nov-2022				
	28700-000-04	New	0				Hrs	0				
	IL-651		0				Ldg	0				
	Mfg#:32-52-01											
325204		**Nose Wheel Steering Control Valve - Removal / Installation**							RE (O/C)			
	32 A/F						Mos	11-Jan-2024				
	28800-000-02	Repaired				0	Hrs	609:34				
	IL-103A					0	Ldg	366				
	Mfg#:32-52-02-RI											
325206		**Nose Wheel Steering Actuator - Removal / Installation**							RE (O/C)			
	32 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-52-03											
325209		**Feedback Potentiometers - Removal / Installation**							RE (O/C)			
	32 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
326103		**Main Landing Gear Downlock Switch - Removal / Installation**							RE (O/C)			
	32 A/F	Left	0				Mos	20-Nov-2022				
	30A2520485-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:32-61-01											
326104		**Main Landing Gear Downlock Switch - Removal / Installation**							RE (O/C)			
	32 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-61-01											
326203		**Main Landing Gear Uplock Switch - Removal / Installation**							RE (O/C)			
	32 A/F	Left	0				Mos	20-Nov-2022				
	84799119	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:32-62-01											
326204		**Main Landing Gear Uplock Switch - Removal / Installation**							RE (O/C)			
	32 A/F	Right	0				Mos	20-Nov-2022				
	84799119	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:32-62-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
326208		**Nose Landing Gear Uplock Switch - Removal / Installation**							RE (O/C)			
32 A/F			0				Mos	20-Nov-2022				
	622EN222	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:32-62-02											
326402		**Nose Wheel Steering Horn - Removal / Installation**							RE (O/C)			
32 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-64-01											
326406		**Nose Wheel Steering Limit Switch - Removal / Installation**							RE (O/C)			
32 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
326408		**Nose Wheel Steering Proximity Switch - Removal / Installation**							RE (O/C)			
32 A/F			0				Mos	20-Nov-2022				
	622EN1-6	New	0				Hrs	0				
	NSN		0				Ldg	0				
326503		**Main Landing Gear Downlock Switch Harness - Removal / Installation**							RE (O/C)			
32 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-65-01											
326504		**Main Landing Gear Downlock Switch Harness - Removal / Installation**							RE (O/C)			
32 A/F		Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-65-01											
326507		**Main Landing Gear Uplock Switch Harness - Removal / Installation**							RE (O/C)			
32 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-65-01											
326508		**Main Landing Gear Uplock Switch Harness - Removal / Installation**							RE (O/C)			
32 A/F		Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-65-01											
326513		**Main Landing Gear Weight on Wheels Switch and Harness - Removal / Installation**							RE (O/C)			
32 A/F		Left Outboard					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-65-01											
326514		**Main Landing Gear Weight on Wheels Switch and Harness - Removal / Installation**							RE (O/C)			
32 A/F		Left Inboard					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-65-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
326515		**Main Landing Gear Weight on Wheels Switch and Harness - Removal / Installation**							RE (O/C)			
	32 A/F	Right Inboard					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-65-01											
326516		**Main Landing Gear Weight on Wheels Switch and Harness - Removal / Installation**							RE (O/C)			
	32 A/F	Right Outboard					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-65-01											
326518		**Nose Wheel Steering Harness - Removal / Installation**							RE (O/C)			
	32 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-65-02-RI											
326521		**Nose Landing Gear Harness and Switches - Removal / Installation**							RE (O/C)			
	32 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-65-02-RI											
326522		**Nose Landing Gear Harness and Switches - Removal / Installation**							RE (O/C)			
	32 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-65-02-RI											
326524		**Thrust Reverser Weight on Wheels Harness and Switch - Removal / Installation**							RE (O/C)			
	32 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-65-02-RI											
326526		**Nose Landing Gear Uplock Switch Harness - Removal / Installation**							RE (O/C)			
	32 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:32-65-02-RI											
331103		**Map Light - Removal / Installation**							RE (O/C)			
	33 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::33-11-02, Mfg#:33-11-02-RI											
331104		**Map Light - Removal / Installation**							RE (O/C)			
	33 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::33-11-02, Mfg#:33-11-02-RI											
331106		**Dome Light - Removal / Installation**							RE (O/C)			
	33 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	ATA Ref::33-11-03, Mfg#:33-11-03-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
331108		**Dimmer Box - Removal / Installation**							RE (O/C)			
	33 A/F		0				Mos	20-Nov-2022				
	101ZT02Y03	New	0				Hrs	0				
	0341		0				Ldg	0				
	ATA Ref::33-11-04, Mfg#:33-11-04											
332225		**Upwash Light - Removal / Installation**							RE (O/C)			
	33 A/F	Left No.1	0				Mos	10-Feb-2023				
	0213LS05-030-13	New	0				Hrs	24:24				
	30137		0				Ldg	7				
332226		**Upwash Light - Removal / Installation**							RE (O/C)			
	33 A/F	Right No.1	0				Mos	10-Feb-2023				
	0213LS05-030-13	New	0				Hrs	24:24				
	30182		0				Ldg	7				
332227		**Upwash Light - Removal / Installation**							RE (O/C)			
	33 A/F	Left No.2	0				Mos	10-Feb-2023				
	0213LS05-036-11	New	0				Hrs	24:24				
	30698		0				Ldg	7				
332228		**Upwash Light - Removal / Installation**							RE (O/C)			
	33 A/F	Right No.2	0				Mos	10-Feb-2023				
	0213LS05-036-11	New	0				Hrs	24:24				
	30700		0				Ldg	7				
332229		**Upwash Light - Removal / Installation**							RE (O/C)			
	33 A/F	Left No.3	0				Mos	10-Feb-2023				
	0213LS05-036-11	New	0				Hrs	24:24				
	30546		0				Ldg	7				
332230		**Upwash Light - Removal / Installation**							RE (O/C)			
	33 A/F	Right No.3	0				Mos	10-Feb-2023				
	0213LS05-036-11	New	0				Hrs	24:24				
	30570		0				Ldg	7				
332231		**Upwash Light - Removal / Installation**							RE (O/C)			
	33 A/F	Left No.4	0				Mos	10-Feb-2023				
	0213LS05-036-11	New	0				Hrs	24:24				
	30563		0				Ldg	7				
332232		**Upwash Light - Removal / Installation**							RE (O/C)			
	33 A/F	Right No.4	0				Mos	10-Feb-2023				
	0213LS05-036-11	New	0				Hrs	24:24				
	30571		0				Ldg	7				
332233		**Upwash Light - Removal / Installation**							RE (O/C)			
	33 A/F	Left No.5	0				Mos	10-Feb-2023				
	0213LS05-036-11	New	0				Hrs	24:24				
	30564		0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
332234		**Upwash Light - Removal / Installation**							RE (O/C)			
	33 A/F	Right No.5	0				Mos	10-Feb-2023				
	0213LS05-036-11	New	0				Hrs	24:24				
	30572		0				Ldg	7				
332235		**Upwash Light - Removal / Installation**							RE (O/C)			
	33 A/F	Left No.6	0				Mos	10-Feb-2023				
	0213LS05-030-13	New	0				Hrs	24:24				
	30176		0				Ldg	7				
332236		**Upwash Light - Removal / Installation**							RE (O/C)			
	33 A/F	Right No.6	0				Mos	10-Feb-2023				
	0213LS05-030-13	New	0				Hrs	24:24				
	30165		0				Ldg	7				
332255		**Downwash Light - Removal / Installation**							RE (O/C)			
	33 A/F	Left No.1	0				Mos	10-Feb-2023				
	0213LS05-036-13	New	0				Hrs	24:24				
	30138		0				Ldg	7				
332256		**Downwash Light - Removal / Installation**							RE (O/C)			
	33 A/F	Right No.1	0				Mos	10-Feb-2023				
	0213LS05-036-13	New	0				Hrs	24:24				
	30183		0				Ldg	7				
332257		**Downwash Light - Removal / Installation**							RE (O/C)			
	33 A/F	Left No.2	0				Mos	10-Feb-2023				
	0213LS05-036-11	New	0				Hrs	24:24				
	30565		0				Ldg	7				
332258		**Downwash Light - Removal / Installation**							RE (O/C)			
	33 A/F	Right No.2	0				Mos	10-Feb-2023				
	0213LS05-036-11	New	0				Hrs	24:24				
	30699		0				Ldg	7				
332259		**Downwash Light - Removal / Installation**							RE (O/C)			
	33 A/F	Left No.3	0				Mos	10-Feb-2023				
	0213LS05-036-11	New	0				Hrs	24:24				
	30566		0				Ldg	7				
332260		**Downwash Light - Removal / Installation**							RE (O/C)			
	33 A/F	Right No.3	0				Mos	10-Feb-2023				
	0213LS05-036-11	New	0				Hrs	24:24				
	30574		0				Ldg	7				
332261		**Downwash Light - Removal / Installation**							RE (O/C)			
	33 A/F	Left No.4	0				Mos	10-Feb-2023				
	0213LS05-036-11	New	0				Hrs	24:24				
	30567		0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
332262		**Downwash Light - Removal / Installation**							RE (O/C)			
33 A/F		Right No.4	0				Mos	20-Oct-2023				
	0213LS05-036-11	New	0				Hrs	490:27				
	31114		0				Ldg	293				
332263		**Downwash Light - Removal / Installation**							RE (O/C)			
33 A/F		Left No.5	0				Mos	10-Feb-2023				
	0213LS05-036-11	New	0				Hrs	24:24				
	30568		0				Ldg	7				
332264		**Downwash Light - Removal / Installation**							RE (O/C)			
33 A/F		Right No.5	0				Mos	10-Feb-2023				
	0213LS05-036-11	New	0				Hrs	24:24				
	30576		0				Ldg	7				
332265		**Downwash Light - Removal / Installation**							RE (O/C)			
33 A/F		Left No.6	0				Mos	10-Feb-2023				
	0213LS05-030-13	New	0				Hrs	24:24				
	30196		0				Ldg	7				
332266		**Downwash Light - Removal / Installation**							RE (O/C)			
33 A/F		Right No.6	0				Mos	10-Feb-2023				
	0213LS05-030-13	New	0				Hrs	24:24				
	30166		0				Ldg	7				
332270		**Nano Wash Light Driver- Removal / Installation**							RE (O/C)			
33 A/F		Left	0				Mos	10-Feb-2023				
	1203LS05-000-00	New	0				Hrs	24:24				
	30088		0				Ldg	7				
332271		**Nano Wash Light Driver - Removal / Installation**							RE (O/C)			
33 A/F		Right	0				Mos	10-Feb-2023				
	1203LS05-000-00	New	0				Hrs	24:24				
	30090		0				Ldg	7				
332272		**Nano Wash Light Driver - Removal / Installation**							RE (O/C)			
33 A/F		Lavatory	0				Mos	10-Feb-2023				
	1203LS05-000-00	New	0				Hrs	24:24				
	30095		0				Ldg	7				
332273		**Vanity Mirror Wash Light Driver- Removal / Installation**							RE (O/C)			
33 A/F		Lavatory	0				Mos	10-Feb-2023				
	1203LS05-000-00	New	0				Hrs	24:24				
	30150		0				Ldg	7				
332278		**PSU Effect Light (Lavatory) - Removal / Installation**							RE (O/C)			
33 A/F		Upper	0				Mos	10-Feb-2023				
	0213LS05-027-13	New	0				Hrs	24:24				
	30109		0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
332279		**PSU Effect Light (Lavatory) - Removal / Installation**							RE (O/C)			
	33 A/F	Lower	0				Mos	10-Feb-2023				
	0213LS05-027-13	New	0				Hrs	24:24				
	30121		0				Ldg	7				
332280		**Vanity Mirror Nano Effect Light**							RE (O/C)			
	33 A/F	Fwd Lavatory No.1	0				Mos	10-Feb-2023				
	0213LS05-027-11	New	0				Hrs	24:24				
	30035		0				Ldg	7				
332281		**Vanity Mirror Nano Effect Light**							RE (O/C)			
	33 A/F	Fwd Lavatory No.2	0				Mos	10-Feb-2023				
	0213LS05-027-13	New	0				Hrs	24:24				
	30111		0				Ldg	7				
332282		**Vanity Mirror Nano Effect Light**							RE (O/C)			
	33 A/F	Aft Lavatory No.1	0				Mos	10-Feb-2023				
	0213LS05-027-13	New	0				Hrs	24:24				
	30114		0				Ldg	7				
332283		**Vanity Mirror Nano Effect Light**							RE (O/C)			
	33 A/F	Aft Lavatory No.2	0				Mos	10-Feb-2023				
	0213LS05-009-11	New	0				Hrs	24:24				
	30152		0				Ldg	7				
332502		**Entry Light - Removal / Installation**							RE (O/C)			
	33 A/F	No.1	0				Mos	10-Feb-2023				
	5200-00	New	0				Hrs	24:24				
	032000379		0				Ldg	7				
332504		**Entry Light - Removal / Installation**							RE (O/C)			
	33 A/F	No.2	0				Mos	10-Feb-2023				
	5200-00	New	0				Hrs	24:24				
	032000380		0				Ldg	7				
332508		**Main Entrance Door Safety Switch - Removal / Installation**							RE (O/C)			
	33 A/F		0				Mos	10-Feb-2023				
	LED-44-14-ED-E2XVF	New	0				Hrs	24:24				
	NSN		0				Ldg	7				
332510		**Med Door Close**							RE (O/C)			
	33 A/F		0				Mos	10-Feb-2023				
	LED-41-11-HE-E2X9K	New	0				Hrs	24:24				
	NSN		0				Ldg	7				
332623		**Vanity Light - Removal / Installation**							RE (O/C)			
	33 A/F	No.1	0				Mos	10-Feb-2023				
	0213LS05-009-11	New	0				Hrs	24:24				
	30153		0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
332624		**Vanity Light - Removal / Installation**							RE (O/C)			
33 A/F		No.2	0				Mos	10-Feb-2023				
	0213LS05-009-11	New	0				Hrs	24:24				
	30154		0				Ldg	7				
332625		**Lavatory Vanity Light - Removal / Installation**							RE (O/C)			
33 A/F		No.3	0				Mos	10-Feb-2023				
	0213LS05-009-11	New	0				Hrs	24:24				
	30155		0				Ldg	7				
332651		**Baggage Dome Light - Removal / Installation**							RE (O/C)			
33 A/F			0				Mos	10-Feb-2023				
	5215-00	New	0				Hrs	24:24				
	3152		0				Ldg	7				
332652		**Baggage Light Assembly - Removal / Installation**							RE (O/C)			
33 A/F		Left	0				Mos	10-Feb-2023				
	5210-01	New	0				Hrs	24:24				
	3159		0				Ldg	7				
332653		**Baggage Light Assembly - Removal / Installation**							RE (O/C)			
33 A/F		Right	0				Mos	10-Feb-2023				
	5210-00	New	0				Hrs	24:24				
	3150		0				Ldg	7				
332702		**Cabin Exit Sign - Removal / Installation**							RE (O/C)			
33 A/F		Fwd	0				Mos	10-Feb-2023				
	GAC-ELES-2004	New	0				Hrs	24:24				
	5550332		0				Ldg	7				
332704		**Entry Way Exit Sign - Removal / Installation**							RE (O/C)			
33 A/F			0				Mos	10-Feb-2023				
	GAC-ELES-2008	New	0				Hrs	24:24				
	5550327		0				Ldg	7				
332720		**Main Entrance Door Exit Sign - Removal / Installation**							RE (O/C)			
33 A/F			0				Mos	10-Feb-2023				
	GAC-ELES-2007	New	0				Hrs	24:24				
	5550203		0				Ldg	7				
332722		**Emergency Exit Sign (Wedge Sign) - Removal / Installation**							RE (O/C)			
33 A/F		Right Aft	0				Mos	10-Feb-2023				
	GAC-ELES-2018	New	0				Hrs	24:24				
	5617304		0				Ldg	7				
333212		**Aft Equipment Utility Light - Removal / Installation**							RE (O/C)			
33 A/F			0				Mos	10-Feb-2023				
	GAC-ELDM-2000-2	New	0				Hrs	24:24				
	5572607		0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
334103		**Taxi Light Assembly - Removal / Installation**							RE (O/C)			
	33 A/F	Left					Mos	13-Dec-2022				
	B4150B9-4626		21:24				Hrs	21:24				
	NSN		5				Ldg	5				
	Mfg#:33-41-01-RI											
334104		**Taxi Light Assembly - Removal / Installation**							RE (O/C)			
	33 A/F	Right					Mos	13-Dec-2022				
	B4150B9-4626		21:24				Hrs	21:24				
	NSN		5				Ldg	5				
	Mfg#:33-41-01-RI											
334203		**Landing Light Assembly - Removal / Installation**							RE (O/C)			
	33 A/F	Left					Mos	13-Dec-2022				
	B-5325A4-24		21:24				Hrs	21:24				
	NSN		5				Ldg	5				
	Mfg#:33-42-04-RI											
334204		**Landing Light Assembly - Removal / Installation**							RE (O/C)			
	33 A/F	Right					Mos	13-Dec-2022				
	B-5325A4-24		21:24				Hrs	21:24				
	NSN		5				Ldg	5				
	Mfg#:33-42-04-RI											
334205		**Landing Light Lens Assembly - Removal / Installation**							RE (O/C)			
	33 A/F	Left					Mos	10-Feb-2023				
	30P6810603-001						Hrs	24:24				
	0003344563						Ldg	7				
334209		**Landing Light Sealed Beam Lamp - Removal / Installation**							RE (O/C)			
	33 A/F	Left	3				Mos	13-Dec-2022				
	LSM-SCD-039-1						Hrs	21:24				
	NSN						Ldg	5				
334210		**Landing Light Sealed Beam Lamp - Removal / Installation**							RE (O/C)			
	33 A/F	Right	3				Mos	13-Dec-2022				
	LSM-SCD-039-1						Hrs	21:24				
	NSN						Ldg	5				
334211		**Wing Position Light Assembly - Removal / Installation**							RE (O/C)			
	33 A/F	Left	0				Mos	20-Nov-2022				
	30-2926-7	New	0				Hrs	0				
	1279		0				Ldg	0				
	Mfg#:33-42-02											
334212		**Wing Position Assembly - Removal / Installation**							RE (O/C)			
	33 A/F	Right	0				Mos	20-Nov-2022				
	30-2926-8	New	0				Hrs	0				
	1278		0				Ldg	0				
	Mfg#:33-42-02											
334215		**Position Light Lens Assembly - Removal / Installation**							RE (O/C)			
	33 A/F	Left	0				Mos	20-Nov-2022				
	30-3060-3	New	0				Hrs	0				
	0732		0				Ldg	0				
	Mfg#:33-42-02											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
334216		**Position Light Lens Assembly - Removal / Installation**							RE (O/C)			
	33 A/F	Right	0				Mos	20-Nov-2022				
	30-3060-4	New	0				Hrs	0				
	0735		0				Ldg	0				
	Mfg#:33-42-02											
334219		**Wing Anticollision / Strobe Light Assembly - Removal / Installation**							RE (O/C)			
	33 A/F	Left	0				Mos	20-Nov-2022				
	30-2943-1	New	0				Hrs	0				
	1245		0				Ldg	0				
	Mfg#:33-42-03											
334220		**Wing Anticollision / Strobe Light Assembly - Removal / Installation**							RE (O/C)			
	33 A/F	Right	0				Mos	20-Nov-2022				
	30-2943-2	New	0				Hrs	0				
	1259		0				Ldg	0				
	Mfg#:33-42-03											
334302		**Tail Position / Strobe Light - Removal / Installation**							RE (O/C)			
	33 A/F						Mos	01-Mar-2023				
	30-1192-9						Hrs	34:12				
	2105						Ldg	10				
	Mfg#:33-43-02											
334304		**Tail Recognition Light - Removal / Installation**							RE (O/C)			
	33 A/F		0				Mos	20-Nov-2022				
	30-2140-11	New	0				Hrs	0				
	3034		0				Ldg	0				
	Mfg#:33-43-03											
334305		**LED Taxi Light (Talon / Lopresti) - Removal / Installation**							RE (O/C)			
	33 A/F	Left	0				Mos	10-Feb-2023				
	LSM-SCD-042-1	New	0				Hrs	24:24				
	NSN		0				Ldg	7				
334306		**LED Taxi Light (Talon / Lopresti) - Removal / Installation**							RE (O/C)			
	33 A/F	Right	0				Mos	10-Feb-2023				
	LSM-SCD-042-1	New	0				Hrs	24:24				
	NSN		0				Ldg	7				
334307		**LED Landing Light Assembly (Talon / Lopresti) - Removal / Installation**							RE (O/C)			
	33 A/F	Left	0				Mos	10-Feb-2023				
	LSM-SCD-039-1	New	0				Hrs	24:24				
	NSN		0				Ldg	7				
334308		**LED Landing Light Assembly (Talon / Lopresti) - Removal / Installation**							RE (O/C)			
	33 A/F	Right	0				Mos	10-Feb-2023				
	LSM-SCD-039-1	New	0				Hrs	24:24				
	NSN		0				Ldg	7				
334313		**Logo Light Assembly - Removal / Installation**							RE (O/C)			
	33 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
334314		**Logo Light Assembly - Removal / Installation**							RE (O/C)			
	33 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
334402		**Pulse Light Control Unit - Removal / Installation**							RE (O/C)			
	33 A/F		0				Mos	20-Nov-2022				
	020P0029-1	New	0				Hrs	0				
	BR00646		0				Ldg	0				
	Mfg#:33-44-01											
334405		**Strobe / Anticollision Power Supply - Removal / Installation**							RE (O/C)			
	33 A/F	Left	0				Mos	20-Nov-2022				
	60-5114-11-2	New	0				Hrs	0				
	1113		0				Ldg	0				
	Mfg#:33-44-02											
334406		**Strobe / Anticollision Power Supply - Removal / Installation**							RE (O/C)			
	33 A/F	Right	0				Mos	20-Nov-2022				
	60-5114-11-2	New	0				Hrs	0				
	1136		0				Ldg	0				
	Mfg#:33-44-02											
335021		**Aisle Light 584 Xds 101 - Removal / Installation**							RE (O/C)			
	33 A/F	Left	0				Mos	10-Feb-2023				
	SFT-WB02E-006-6	New	0				Hrs	24:24				
	5505079		0				Ldg	7				
335022		**Aisle Light 584 Xds 102 - Removal / Installation**							RE (O/C)			
	33 A/F	Left	0				Mos	10-Feb-2023				
	SFT-WB02E-010-6	New	0				Hrs	24:24				
	5505171		0				Ldg	7				
335023		**Aisle Light 584 Xds 103 - Removal / Installation**							RE (O/C)			
	33 A/F	Left	0				Mos	10-Feb-2023				
	SFT-WB02E-036-6	New	0				Hrs	24:24				
	5633609		0				Ldg	7				
335024		**Aisle Light 584 Xds 104 - Removal / Installation**							RE (O/C)			
	33 A/F	Left	0				Mos	10-Feb-2023				
	SFT-WB02E-036-6	New	0				Hrs	24:24				
	5633610		0				Ldg	7				
335025		**Aisle Light 584 Xds 105 - Removal / Installation**							RE (O/C)			
	33 A/F	Left	0				Mos	10-Feb-2023				
	SFT-WB02E-020-6	New	0				Hrs	24:24				
	543991		0				Ldg	7				
335026		**Aisle Light 584 Xds 106 - Removal / Installation**							RE (O/C)			
	33 A/F	Left	0				Mos	10-Feb-2023				
	SFT-WB02E-056-6	New	0				Hrs	24:24				
	5496244		0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
335027		**Aisle Light 584 Xds 107 - Removal / Installation**							RE (O/C)			
33 A/F		Left	0				Mos	10-Feb-2023				
	SFT-WB02E-030-6	New	0				Hrs	24:24				
	5642241		0				Ldg	7				
335028		**Aisle Light 584 Xds 108 - Removal / Installation**							RE (O/C)			
33 A/F		Left	0				Mos	10-Feb-2023				
	SFT-WB02E-015-6	New	0				Hrs	24:24				
	240615-3-5		0				Ldg	7				
335029		**Aisle Light 584 Xds 109 - Removal / Installation**							RE (O/C)			
33 A/F		Left	0				Mos	10-Feb-2023				
	SFT-WB02E-004-6	New	0				Hrs	24:24				
	5520051		0				Ldg	7				
335031		**Aisle Light 584 Xds 201 - Removal / Installation**							RE (O/C)			
33 A/F		Right	0				Mos	10-Feb-2023				
	SFT-WB02E-010-6	New	0				Hrs	24:24				
	5505172		0				Ldg	7				
335032		**Aisle Light 584 Xds 202 - Removal / Installation**							RE (O/C)			
33 A/F		Right	0				Mos	10-Feb-2023				
	SFT-WB02E-006-6	New	0				Hrs	24:24				
	5505080		0				Ldg	7				
335033		**Aisle Light 584 Xds 203 - Removal / Installation**							RE (O/C)			
33 A/F		Right	0				Mos	10-Feb-2023				
	SFT-WB02E-035-6	New	0				Hrs	24:24				
	5619177		0				Ldg	7				
335034		**Aisle Light 584 Xds 204 - Removal / Installation**							RE (O/C)			
33 A/F		Right	0				Mos	10-Feb-2023				
	SFT-WB02E-035-6	New	0				Hrs	24:24				
	5619178		0				Ldg	7				
335035		**Aisle Light 584 Xds 205 - Removal / Installation**							RE (O/C)			
33 A/F		Right	0				Mos	10-Feb-2023				
	SFT-WB02E-010-6	New	0				Hrs	24:24				
	5505173		0				Ldg	7				
335036		**Aisle Light 584 Xds 206 - Removal / Installation**							RE (O/C)			
33 A/F		Right	0				Mos	10-Feb-2023				
	SFT-WB02E-035-6	New	0				Hrs	24:24				
	5619179		0				Ldg	7				
335037		**Aisle Light 584 Xds 207 - Removal / Installation**							RE (O/C)			
33 A/F		Right	0				Mos	10-Feb-2023				
	SFT-WB02E-026-6	New	0				Hrs	24:24				
	5642165		0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
335038		**Aisle Light 584 Xds 208 - Removal / Installation**							RE (O/C)			
33 A/F		Right	0				Mos	10-Feb-2023				
	SFT-WB02E-026-6	New	0				Hrs	24:24				
	5642166		0				Ldg	7				
335039		**Aisle Light 584 Xds 209 - Removal / Installation**							RE (O/C)			
33 A/F		Right	0				Mos	10-Feb-2023				
	SFT-WB02E-026-6	New	0				Hrs	24:24				
	5642167		0				Ldg	7				
335041		**Emergency Aisle Light 486 Xds 206 - Removal / Installation**							RE (O/C)			
33 A/F		Right	0				Mos	10-Feb-2023				
	SFT-WB02E-025-6	New	0				Hrs	24:24				
	5642140		0				Ldg	7				
335103		**Securaplane Battery - Removal / Installation**							RE (O/C)			
33 A/F		No.1	4				Mos	10-Feb-2023				
	100-1080-02						Hrs	24:24				
	1214416						Ldg	7				
335104		**Securaplane Battery - Removal / Installation**							RE (O/C)			
33 A/F		No.2	4				Mos	10-Feb-2023				
	100-1088-02						Hrs	24:24				
	1214417						Ldg	7				
341109		**Air Data Computer - Removal / Installation**							RE (O/C)			
34 A/F		No.1	3				Mos	20-Nov-2022				
	822-2083-001						Hrs	0				
	4MRM48						Ldg	0				
	Mfg#:34-11-01											
341110		**Air Data Computer - Removal / Installation**							RE (O/C)			
34 A/F		No.2	3				Mos	20-Nov-2022				
	822-2083-001						Hrs	0				
	4P5NT1						Ldg	0				
	Mfg#:34-11-01											
341204		**Pitot Probe - Removal / Installation**							RE (O/C)			
34 A/F		Left					Mos	10-Feb-2023				
	0851LT						Hrs	24:24				
	423134						Ldg	7				
	Mfg#:34-12-01											
341205		**Pitot Probe - Removal / Installation**							RE (O/C)			
34 A/F		Right					Mos	10-Feb-2023				
	0851LT						Hrs	24:24				
	425878						Ldg	7				
	Mfg#:34-12-01											
341206		**Pitot Probe - Removal / Installation**							RE (O/C)			
34 A/F		StandBy	0				Mos	20-Nov-2022				
	0851LT	New	0				Hrs	0				
	424187		0				Ldg	0				
	Mfg#:34-12-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
341223		**Static Port (Upper) - Removal / Installation**							RE (O/C)			
	34 A/F	Left Fwd	0				Mos	20-Nov-2022				
	0860CW	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:34-12-02-RI											
341224		**Static Port (Lower) - Removal / Installation**							RE (O/C)			
	34 A/F	Left Fwd	0				Mos	20-Nov-2022				
	0860CW	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:34-12-02-RI											
341225		**Static Port (Lower) - Removal / Installation**							RE (O/C)			
	34 A/F	Left Aft	0				Mos	20-Nov-2022				
	0860CW	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:34-12-02-RI											
341226		**Static Port (Upper) - Removal / Installation**							RE (O/C)			
	34 A/F	Right Fwd	0				Mos	20-Nov-2022				
	0860CW	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:34-12-02-RI											
341227		**Static Port (Lower) - Removal / Installation**							RE (O/C)			
	34 A/F	Right Fwd	0				Mos	20-Nov-2022				
	0860CW	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:34-12-02-RI											
341228		**Static Port (Upper) - Removal / Installation**							RE (O/C)			
	34 A/F	Right Aft	0				Mos	20-Nov-2022				
	0860CW	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:34-12-02-RI											
341229		**Static Port (Lower) - Removal / Installation**							RE (O/C)			
	34 A/F	Right Aft	0				Mos	20-Nov-2022				
	0860CW	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:34-12-02-RI											
341302		**Static Air Temperature / Total Air Sensor Probe - 102EW1DF Removal / Installation**							RE (O/C)			
	34 A/F		0				Mos	20-Nov-2022				
	102EW1DF	New	0				Hrs	0				
	B83240		0				Ldg	0				
	Mfg#:34-13-01-RI											
341403		**Angle of Attack Probe - Removal / Installation**							RE (O/C)			
	34 A/F	Left	0				Mos	20-Nov-2022				
	0861JP	New	0				Hrs	0				
	5221		0				Ldg	0				
	Mfg#:34-14-01											
341404		**Angle of Attack Probe - Removal / Installation**							RE (O/C)			
	34 A/F	Right	0				Mos	20-Nov-2022				
	0861JP	New	0				Hrs	0				
	5236		0				Ldg	0				
	Mfg#:34-14-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
342103		**Attitude Heading Reference Unit / Inertial Reference Unit - Removal / Installation**							RE (O/C)			
	34 A/F	No.1	0				Mos	20-Nov-2022				
	HG2112BB03	New	0				Hrs	0				
	56207920		0				Ldg	0				
	Mfg#:34-21-01											
342104		**Attitude Heading Reference Unit / Inertial Reference Unit - Removal / Installation**							RE (O/C)			
	34 A/F	No.2	0				Mos	20-Nov-2022				
	HG2112BB03	New	0				Hrs	0				
	56208754		0				Ldg	0				
	Mfg#:34-21-01											
342107		**Attitude Heading Reference System Mounting Tray - Removal / Installation**							RE (O/C)			
	34 A/F	No.1					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	(SOURCE: 34-21-03)											
342108		**Attitude Heading Reference System Mounting Tray - Removal / Installation**							RE (O/C)			
	34 A/F	No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	(SOURCE: 34-21-03)											
342115		**Aircraft Personality Module - Removal / Installation**							RE (O/C)			
	34 A/F	No.1	0				Mos	20-Nov-2022				
	7519272-901	New	0				Hrs	0				
	40861432		0				Ldg	0				
	Mfg#:34-21-02											
342116		**Aircraft Personality Module - Removal / Installation**							RE (O/C)			
	34 A/F	No.2	0				Mos	20-Nov-2022				
	7519272-901	New	0				Hrs	0				
	40861422		0				Ldg	0				
	Mfg#:34-21-02											
342117		**Aircraft Personality Module (IRU) - Removal / Installation**							RE (O/C)			
	34 A/F	No.3					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:34-21-02											
342121		**Attitude Heading Reference System Mounting Tray (IRU) - Removal / Installation**							RE (O/C)			
	34 A/F	No.3	0				Mos	10-Feb-2023				
	WG2001AA03	New	0				Hrs	24:24				
	10952		0				Ldg	7				
	Mfg#:34-21-03											
342202		**Attitude Heading Reference Unit / Inertial Reference Unit (IRU) - Removal / Installation**							RE (O/C)			
	34 A/F	No.3	0				Mos	10-Feb-2023				
	HG2100BB02	New	0				Hrs	24:24				
	56204782		0				Ldg	7				
	Mfg#:34-21-01											
342704		**Remote Sensor Electronics Unit - Removal / Installation**							RE (O/C)			
	34 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
342707		**Heading Sensor Unit - Removal / Installation**							RE (O/C)			
	34 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
342712		**Magnetic Compass - Removal / Installation**							RE (O/C)			
	34 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
342732		**Standby Flight Instrument System Unit - Removal / Installation**							RE (O/C)			
	34 A/F		3				Mos	20-Nov-2022				
	866-0205-101						Hrs	0				
	78M16						Ldg	0				
	Mfg#:34-27-02-RI											
342734		**Magnetometer - Removal / Installation**							RE (O/C)			
	34 A/F		0				Mos	20-Nov-2022				
	866-0206-020	New	0				Hrs	0				
	4275FF		0				Ldg	0				
	Mfg#:34-27-01-RI											
342736		**Configuration Module, OCM - 3900 - Removal / Installation**							RE (O/C)			
	34 A/F		0				Mos	20-Nov-2022				
	866-0210-010	New	0				Hrs	0				
	491XGV		0				Ldg	0				
344001		**HUD Computer - Removal / Installation**							RE (O/C)			
	34 A/F		0				Mos	10-Feb-2023				
	1500-3060-001	New	0				Hrs	24:24				
	78714		0				Ldg	7				
344002		**HGS Overhead Unit - Removal / Installation**							RE (O/C)			
	34 A/F		0				Mos	10-Feb-2023				
	1500-3070-001	New	0				Hrs	24:24				
	78577		0				Ldg	7				
344003		**Combiner - Removal / Installation**							RE (O/C)			
	34 A/F		0				Mos	10-Feb-2023				
	1500-3080-201	New	0				Hrs	24:24				
	78425		0				Ldg	7				
344004		**HUD/EVS APM - Removal / Installation**							RE (O/C)			
	34 A/F		0				Mos	10-Feb-2023				
	822-1424-001	New	0				Hrs	24:24				
	4RTV54		0				Ldg	7				
344006		**EVS Processor - Removal / Installation**							RE (O/C)			
	34 A/F		0				Mos	10-Feb-2023				
	48539-101	New	0				Hrs	24:24				
	02688		0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
344007		**EVS Camera - Removal / Installation**							RE (O/C)			
34 A/F			0				Mos	10-Feb-2023				
58534-101		New	0				Hrs	24:24				
02620			0				Ldg	7				
344008		**EVS Video Amp - Removal / Installation**							RE (O/C)			
34 A/F			0				Mos	10-Feb-2023				
30300051		New	0				Hrs	24:24				
S00139			0				Ldg	7				
344009		**EVS Window Assembly - Removal / Installation**							RE (O/C)			
34 A/F			0				Mos	10-Feb-2023				
50889-101		New	0				Hrs	24:24				
0820			0				Ldg	7				
344010		**Low Speed Switch - Removal / Installation**							RE (O/C)			
34 A/F			0				Mos	10-Feb-2023				
035640501		New	0				Hrs	24:24				
E22363941			0				Ldg	7				
344107		**Radio Altimeter - Removal / Installation**							RE (O/C)			
34 A/F		No.1	0				Mos	20-Nov-2022				
822-0615-315		New	0				Hrs	0				
4LD71D			0				Ldg	0				
Mfg#:34-41-01												
344108		**Radio Altimeter - Removal / Installation**							RE (O/C)			
34 A/F		No.2					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:34-41-01												
344113		**Radio Altimeter Antenna (Transmit) - Removal / Installation**							RE (O/C)			
34 A/F		No.1	0				Mos	20-Nov-2022				
S67-2002		New	0				Hrs	0				
543-105725			0				Ldg	0				
Mfg#:34-41-02												
344114		**Radio Altimeter Antenna (Receive) - Removal / Installation**							RE (O/C)			
34 A/F		No.1	0				Mos	20-Nov-2022				
S67-2002		New	0				Hrs	0				
543-105732			0				Ldg	0				
Mfg#:34-41-02												
344115		**Radio Altimeter Antenna (Transmit) - Removal / Installation**							RE (O/C)			
34 A/F		No.2					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:34-41-02												
344116		**Radio Altimeter Antenna (Receive) - Removal / Installation**							RE (O/C)			
34 A/F		No.2					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:34-41-02												

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
344204		**Weather Radar RTA - Removal / Installation**							RE (O/C)			
	34 A/F		0				Mos	20-Nov-2022				
	822-2259-002	New	0				Hrs	0				
	4RK2XH		0				Ldg	0				
	Mfg#:34-42-01											
344404		**TCAS Transponder - Removal / Installation**							RE (O/C)			
	34 A/F		3				Mos	20-Nov-2022				
	822-2132-001						Hrs	0				
	78VN9						Ldg	0				
	Mfg#:34-44-01-RI											
344406		**TCAS Omnidirectional Antenna - Removal / Installation**							RE (O/C)			
	34 A/F		0				Mos	20-Nov-2022				
	DMNI50-6-2	New	0				Hrs	0				
	31475		0				Ldg	0				
	Mfg#:34-44-02-RI											
344408		**TCAS Directional Antenna - Removal / Installation**							RE (O/C)			
	34 A/F		0				Mos	20-Nov-2022				
	866-0016-101	New	0				Hrs	0				
	4P54NM		0				Ldg	0				
	Mfg#:34-44-02-RI											
344410		**TCAS External Compensation Unit - Removal / Installation**							RE (O/C)			
	34 A/F		0				Mos	20-Nov-2022				
	822-1200-803	New	0				Hrs	0				
	4RK2GM		0				Ldg	0				
	Mfg#:34-44-03-RI											
345107		**GPS Antenna - Removal / Installation**							RE (O/C)			
	34 A/F	No.1	0				Mos	20-Nov-2022				
	S67-1575-232	New	0				Hrs	0				
	472-1760		0				Ldg	0				
	Mfg#:34-51-02											
345108		**GPS Antenna - Removal / Installation**							RE (O/C)			
	34 A/F	No.2	0				Mos	20-Nov-2022				
	S67-1575-232	New	0				Hrs	0				
	472-1742		0				Ldg	0				
	Mfg#:34-51-02											
345111		**GPS Receiver - Removal / Installation**							RE (O/C)			
	34 A/F	No.1	0				Mos	20-Nov-2022				
	822-2189-101	New	0				Hrs	0				
	4PR5GG		0				Ldg	0				
	Mfg#:34-51-01											
345112		**GPS Receiver - Removal / Installation**							RE (O/C)			
	34 A/F	No.2	0				Mos	20-Nov-2022				
	822-2189-101	New	0				Hrs	0				
	4PR5L6		0				Ldg	0				
	Mfg#:34-51-01											
345213		**VHF Navigation Receiver - Removal / Installation**							RE (O/C)			
	34 A/F	No.1	0				Mos	20-Nov-2022				
	822-1465-101	New	0				Hrs	0				
	4L0CFV		0				Ldg	0				
	Mfg#:34-52-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
345214		**VHF Navigation Receiver - Removal / Installation**							RE (O/C)			
	34 A/F	No.2					Mos	10-Feb-2023				
	822-1465-101						Hrs	24:24				
	4RGT0H						Ldg	7				
	Mfg#:34-52-01											
345218		**VHF Navigation Receiver - Removal / Installation**							RE (O/C)			
	34 A/F	No.3					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Ref#:34-52-01											
345223		**VOR / Localizer / ILS Antenna - Removal / Installation**							RE (O/C)			
	34 A/F	Left	0				Mos	20-Nov-2022				
	S65-247170-7	New	0				Hrs	0				
	180-14751		0				Ldg	0				
	Mfg#:34-52-03											
345224		**VOR / Localizer / ILS Antenna - Removal / Installation**							RE (O/C)			
	34 A/F	Right	0				Mos	20-Nov-2022				
	S65-247170-7	New	0				Hrs	0				
	180-14590		0				Ldg	0				
	Mfg#:34-52-03											
345226		**Power Combiner - Removal / Installation**							RE (O/C)			
	34 A/F		0				Mos	20-Nov-2022				
	SSPD-113-38	New	0				Hrs	0				
	666-5456		0				Ldg	0				
	Mfg#:34-52-03											
345228		**VOR/ILS Coupler - Removal / Installation**							RE (O/C)			
	34 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
345232		**Glide Slope Antenna - Removal / Installation**							RE (O/C)			
	34 A/F		0				Mos	20-Nov-2022				
	S41422-2	New	0				Hrs	0				
	111-10514		0				Ldg	0				
	Mfg#:34-52-04											
345234		**Glide Slope Diplexer - Removal / Installation**							RE (O/C)			
	34 A/F		0				Mos	20-Nov-2022				
	DMH24-1	New	0				Hrs	0				
	30496		0				Ldg	0				
345238		**Marker Beacon Antenna - Removal / Installation**							RE (O/C)			
	34 A/F		0				Mos	20-Nov-2022				
	DMN27-1/A	New	0				Hrs	0				
	12089		0				Ldg	0				
	Mfg#:34-52-05											
345243		**Marker Beacon Diplexer - Removal / Installation**							RE (O/C)			
	34 A/F	Left	0				Mos	20-Nov-2022				
	DMH21-1	New	0				Hrs	0				
	57955		0				Ldg	0				
	Mfg#:34-52-06											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
345244		**Marker Beacon Diplexer - Removal / Installation**							RE (O/C)			
	34 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
345248		**Automatic Direction Finding Antenna - Removal / Installation**							RE (O/C)			
	34 A/F		0				Mos	20-Nov-2022				
	622-7384-001	New	0				Hrs	0				
	4PR62C		0				Ldg	0				
	Mfg#:34-52-07											
345306		**ATC Transponder - Removal / Installation**							RE (O/C)			
	34 A/F	No.1					Mos	10-Feb-2023				
	622-9210-501						Hrs	24:24				
	4L0V9T						Ldg	7				
	Mfg#:34-53-01-RI											
345307		**ATC Transponder - Removal / Installation**							RE (O/C)			
	34 A/F	No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:34-53-01-RI											
345309		**ATC Antenna - Removal / Installation**							RE (O/C)			
	34 A/F	No.1 (Upper)	0				Mos	20-Nov-2022				
	DMNI50-6-2	New	0				Hrs	0				
	31709		0				Ldg	0				
	Mfg#:34-53-02											
345310		**ATC Antenna - Removal / Installation**							RE (O/C)			
	34 A/F	No.2 (Lower)	0				Mos	20-Nov-2022				
	DMNI50-6-2	New	0				Hrs	0				
	31507		0				Ldg	0				
	Mfg#:34-53-02											
345407		**DME Transceiver - Removal / Installation**							RE (O/C)			
	34 A/F	No.1	0				Mos	20-Nov-2022				
	822-1466-001	New	0				Hrs	0				
	4RGC5G		0				Ldg	0				
	Mfg#:34-54-01											
345408		**DME Transceiver - Removal / Installation**							RE (O/C)			
	34 A/F	No.2	0				Mos	20-Nov-2022				
	822-1466-001	New	0				Hrs	0				
	4T6DYR		0				Ldg	0				
	Mfg#:34-54-01											
345411		**DME Antenna - Removal / Installation**							RE (O/C)			
	34 A/F	No.1	0				Mos	20-Nov-2022				
	DMNI50-6-2	New	0				Hrs	0				
	31494		0				Ldg	0				
	Mfg#:34-54-02											
345412		**DME Antenna - Removal / Installation**							RE (O/C)			
	34 A/F	No.2	0				Mos	20-Nov-2022				
	DMNI50-6-2	New	0				Hrs	0				
	31480		0				Ldg	0				
	Mfg#:34-54-02											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
346007		**Control Display Unit - Removal / Installation**							RE (O/C)			
34 A/F		No.1	0				Mos	20-Nov-2022				
	822-1485-606	New	0				Hrs	0				
	4P5R39		0				Ldg	0				
	Mfg#:34-60-01											
346008		**Control Display Unit - Removal / Installation**							RE (O/C)			
34 A/F		No.2	0				Mos	20-Nov-2022				
	822-1485-606	New	0				Hrs	0				
	4P5R23		0				Ldg	0				
	Mfg#:34-60-01											
346009		**Control Display Unit - Removal / Installation**							RE (O/C)			
34 A/F		No.3					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:34-60-01											
351102		**Oxygen Cylinder - Removal / Installation**							RE (O/C)			
35 A/F				0			Mos	19-Jan-2023				
	807435-02	Overhauled		0			Hrs	22:54				
	C22040248			0			Ldg	6				
	Mfg#:35-11-01											
351108		**Main Oxygen Shut-off Valve - Removal / Installation**							RE (O/C)			
35 A/F			0				Mos	20-Nov-2022				
	2440	New	0				Hrs	0				
	19013		0				Ldg	0				
	Mfg#:35-11-02											
351110		**Oxygen Pressure Switch - Removal / Installation**							RE (O/C)			
35 A/F			0				Mos	20-Nov-2022				
	9H0018-1G	New	0				Hrs	0				
	0274		0				Ldg	0				
	Mfg#:35-11-03											
351114		**Oxygen Charging Valve - Removal / Installation**							RE (O/C)			
35 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:35-11-04											
351120		**Oxygen Regulator Assembly - Removal / Installation**							RE (O/C)			
35 A/F			0				Mos	20-Nov-2022				
	803980-05	New	0				Hrs	0				
	C22031103		0				Ldg	0				
351123		**Oxygen Temperature / Pressure Transducer - Removal / Installation**							RE (O/C)			
35 A/F			0				Mos	20-Nov-2022				
	10016624	New	0				Hrs	0				
	20212641		0				Ldg	0				
351203		**Crew Oxygen Mask - Removal / Installation**							RE (O/C)			
35 A/F		Pilot	9				Mos	20-Nov-2022				
	MLD20-563						Hrs	0				
	B179327						Ldg	0				
	Mfg#:35-12-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
351204		**Crew Oxygen Mask - Removal / Installation**							RE (O/C)			
	35 A/F	Copilot	5				Mos	20-Nov-2022				
	MLD20-563						Hrs	0				
	B182837						Ldg	0				
	Mfg#:35-12-01											
351211		**Crew Mask Stowage Box - Removal / Installation**							RE (O/C)			
	35 A/F	Pilot	0				Mos	20-Nov-2022				
	MXP807	New	0				Hrs	0				
	SE131757		0				Ldg	0				
	Mfg#:35-12-02											
351212		**Crew Mask Stowage Box - Removal / Installation**							RE (O/C)			
	35 A/F	Copilot	0				Mos	20-Nov-2022				
	MXP807	New	0				Hrs	0				
	SE131628		0				Ldg	0				
	Mfg#:35-12-02											
352102		**Passenger Oxygen Controller - Removal / Installation**							RE (O/C)			
	35 A/F						Mos	10-Feb-2023				
	P27096						Hrs	24:24				
	R22050339						Ldg	7				
	Mfg#:35-21-01											
352125		**Passenger Oxygen Drop Box (Cabin) - Removal / Installation**							RE (O/C)			
	35 A/F	No.1	2				Mos	10-Feb-2023				
	P25094						Hrs	24:24				
	D22121487						Ldg	7				
352126		**Passenger Oxygen Drop Box (Cabin) - Removal / Installation**							RE (O/C)			
	35 A/F	No.2	2				Mos	10-Feb-2023				
	P25094						Hrs	24:24				
	D22121703						Ldg	7				
352127		**Passenger Oxygen Drop Box (Cabin) - Removal / Installation**							RE (O/C)			
	35 A/F	No.3	2				Mos	10-Feb-2023				
	P25094						Hrs	24:24				
	D22121704						Ldg	7				
352128		**Passenger Oxygen Drop Box (Cabin) - Removal / Installation**							RE (O/C)			
	35 A/F	No.4	2				Mos	10-Feb-2023				
	P25094						Hrs	24:24				
	D22121705						Ldg	7				
352129		**Passenger Oxygen Drop Box (Cabin) - Removal / Installation**							RE (O/C)			
	35 A/F	No.5	2				Mos	10-Feb-2023				
	P25094						Hrs	24:24				
	D22121706						Ldg	7				
352131		**Passenger Oxygen Drop Box (Entry) - Removal / Installation**							RE (O/C)			
	35 A/F		2				Mos	10-Feb-2023				
	P25093						Hrs	24:24				
	D22120004						Ldg	7				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
352132	**Passenger Oxygen Drop Box (Aft Lavatory) - Removal / Installation**							RE (O/C)			
35 A/F		2				Mos	10-Feb-2023				
P25093						Hrs	24:24				
D22120009						Ldg	7				
352145	**Passenger Oxygen Mask (Cabin) - Removal / Installation**							RE (O/C)			
35 A/F	No.1	3				Mos	10-Feb-2023				
P20066						Hrs	24:24				
NSN						Ldg	7				
352146	**Passenger Oxygen Mask (Cabin) - Removal / Installation**							RE (O/C)			
35 A/F	No.2	3				Mos	10-Feb-2023				
P20066						Hrs	24:24				
NSN						Ldg	7				
352147	**Passenger Oxygen Mask (Cabin) - Removal / Installation**							RE (O/C)			
35 A/F	No.3	3				Mos	10-Feb-2023				
P20066						Hrs	24:24				
NSN						Ldg	7				
352148	**Passenger Oxygen Mask (Cabin) - Removal / Installation**							RE (O/C)			
35 A/F	No.4	2				Mos	10-Feb-2023				
P20066						Hrs	24:24				
NSN						Ldg	7				
352149	**Passenger Oxygen Mask (Cabin) - Removal / Installation**							RE (O/C)			
35 A/F	No.5	2				Mos	10-Feb-2023				
P20066						Hrs	24:24				
NSN						Ldg	7				
352151	**Passenger Oxygen Mask (Entry) - Removal / Installation**							RE (O/C)			
35 A/F	No.1	3				Mos	10-Feb-2023				
P20061						Hrs	24:24				
NSN						Ldg	7				
352152	**Passenger Oxygen Mask (Aft Lavatory) - Removal / Installation**							RE (O/C)			
35 A/F	No.1	3				Mos	10-Feb-2023				
P20061						Hrs	24:24				
NSN						Ldg	7				
352153	**Passenger Oxygen Mask (Entry) - Removal / Installation**							RE (O/C)			
35 A/F	No.2	3				Mos	10-Feb-2023				
P20061						Hrs	24:24				
NSN						Ldg	7				
352154	**Passenger Oxygen Mask (Aft Lavatory) - Removal / Installation**							RE (O/C)			
35 A/F	No.2	3				Mos	10-Feb-2023				
P20061						Hrs	24:24				
NSN						Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
352180		**Passenger Oxygen Mask (Cabin) - Removal / Installation**							RE (O/C)			
	35 A/F	No.6		2			Mos	10-Feb-2023				
	P20066						Hrs	24:24				
	NSN						Ldg	7				
352181		**Passenger Oxygen Mask (Cabin) - Removal / Installation**							RE (O/C)			
	35 A/F	No.7		2			Mos	10-Feb-2023				
	P20066						Hrs	24:24				
	NSN						Ldg	7				
352182		**Passenger Oxygen Mask (Cabin) - Removal / Installation**							RE (O/C)			
	35 A/F	No.8		2			Mos	10-Feb-2023				
	P20066						Hrs	24:24				
	NSN						Ldg	7				
352183		**Passenger Oxygen Mask (Cabin) - Removal / Installation**							RE (O/C)			
	35 A/F	No.9		2			Mos	10-Feb-2023				
	P20066						Hrs	24:24				
	NSN						Ldg	7				
352184		**Passenger Oxygen Mask (Cabin) - Removal / Installation**							RE (O/C)			
	35 A/F	No.10		2			Mos	10-Feb-2023				
	P20066						Hrs	24:24				
	NSN						Ldg	7				
352185		**Passenger Oxygen Mask (Cabin) - Removal / Installation**							RE (O/C)			
	35 A/F	No.11		2			Mos	10-Feb-2023				
	P20066						Hrs	24:24				
	NSN						Ldg	7				
352186		**Passenger Oxygen Mask (Cabin) - Removal / Installation**							RE (O/C)			
	35 A/F	No.12		2			Mos	10-Feb-2023				
	P20066						Hrs	24:24				
	NSN						Ldg	7				
352187		**Passenger Oxygen Mask (Cabin) - Removal / Installation**							RE (O/C)			
	35 A/F	No.13		2			Mos	10-Feb-2023				
	P20066						Hrs	24:24				
	NSN						Ldg	7				
352188		**Passenger Oxygen Mask (Cabin) - Removal / Installation**							RE (O/C)			
	35 A/F	No.14		2			Mos	10-Feb-2023				
	P20066						Hrs	24:24				
	NSN						Ldg	7				
352189		**Passenger Oxygen Mask (Cabin) - Removal / Installation**							RE (O/C)			
	35 A/F	No.15		2			Mos	10-Feb-2023				
	P20066						Hrs	24:24				
	NSN						Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
352202		**Therapeutic Oxygen Outlet - Removal / Installation**							RE (O/C)			
	35 A/F	No.1	0				Mos	10-Feb-2023				
	P80364	New	0				Hrs	24:24				
	0175		0				Ldg	7				
361103		**High-pressure Shut-off Valve - Removal / Installation**							RE (O/C)			
	36 A/F	Left					Mos	10-Feb-2023				
	3215978-1						Hrs	24:24				
	634						Ldg	7				
	Mfg#:36-11-01											
361104		**High-pressure Shut-off Valve - Removal / Installation**							RE (O/C)			
	36 A/F	Right					Mos	10-Feb-2023				
	3215978-1						Hrs	24:24				
	626						Ldg	7				
	Mfg#:36-11-01											
361107		**Intermediate Pressure Check Valve - Removal / Installation**							RE (O/C)			
	36 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:36-11-02											
361108		**Intermediate Pressure Check Valve - Removal / Installation**							RE (O/C)			
	36 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:36-11-02											
361111		**Manifold Pressure Regulator Shut-off Valve - Removal / Installation**							RE (O/C)			
	36 A/F	Left					Mos	10-Feb-2023				
	3215980-1						Hrs	24:24				
	103						Ldg	7				
	Mfg#:36-11-03											
361112		**Manifold Pressure Regulator Shut-off Valve - Removal / Installation**							RE (O/C)			
	36 A/F	Right					Mos	10-Feb-2023				
	3215980-1						Hrs	24:24				
	643						Ldg	7				
	Mfg#:36-11-03											
361114		**Bleed Air Isolation Valve - Removal / Installation**							RE (O/C)			
	36 A/F		0				Mos	20-Nov-2022				
	3291942-1	New	0				Hrs	0				
	363		0				Ldg	0				
	Mfg#:36-11-04											
361202		**APU Load Control Valve - Removal / Installation**							RE (O/C)			
	36 A/F		0				Mos	20-Nov-2022				
	109812-12	New	0				Hrs	0				
	5769		0				Ldg	0				
	Mfg#:36-12-01											
361204		**APU Check Valve - Removal / Installation**							RE (O/C)			
	36 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:36-12-02											

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
361206	**Ground Connection Check Valve - Removal / Installation**							RE (O/C)			
36 A/F						Mos	20-Nov-2022				
Unknown						Hrs	0				
Unknown						Ldg	0				
Mfg#:36-12-03											
361303	**Fan Air Valve - Removal / Installation**							RE (O/C)			
36 A/F	Left	0				Mos	20-Nov-2022				
3291944-1	New	0				Hrs	0				
630		0				Ldg	0				
Mfg#:36-13-01											
361304	**Fan Air Valve - Removal / Installation**							RE (O/C)			
36 A/F	Right	0				Mos	20-Nov-2022				
3291944-1	New	0				Hrs	0				
636		0				Ldg	0				
Mfg#:36-13-01											
361307	**Precooler - Removal / Installation**							RE (O/C)			
36 A/F	Left	0				Mos	20-Nov-2022				
2342132-1	New	0				Hrs	0				
0277		0				Ldg	0				
Mfg#:36-13-02											
361308	**Precooler - Removal / Installation**							RE (O/C)			
36 A/F	Right	0				Mos	20-Nov-2022				
2342132-2	New	0				Hrs	0				
0265		0				Ldg	0				
Mfg#:36-13-02											
362103	**Manifold Pressure Sensor - Removal / Installation**							RE (O/C)			
36 A/F	Left	0				Mos	20-Nov-2022				
1151584-1-1	New	0				Hrs	0				
1151584-09334		0				Ldg	0				
Mfg#:36-21-01											
362104	**Manifold Pressure Sensor - Removal / Installation**							RE (O/C)			
36 A/F	Right	0				Mos	20-Nov-2022				
1151584-1-1	New	0				Hrs	0				
1151584-09335		0				Ldg	0				
Mfg#:36-21-01											
362203	**Precooler Inlet Temperature Sensor - Removal / Installation**							RE (O/C)			
36 A/F	Left	0				Mos	20-Nov-2022				
1150124-2-2	New	0				Hrs	0				
1150124-18596		0				Ldg	0				
Mfg#:36-22-01											
362204	**Precooler Inlet Temperature Sensor - Removal / Installation**							RE (O/C)			
36 A/F	Right	0				Mos	20-Nov-2022				
1150124-2-2	New	0				Hrs	0				
1150124-19113		0				Ldg	0				
Mfg#:36-22-01											
362207	**Precooler Outlet Temperature Sensor - Removal / Installation**							RE (O/C)			
36 A/F	Left	0				Mos	20-Nov-2022				
1150124-2-2	New	0				Hrs	0				
1150124-18846		0				Ldg	0				
Mfg#:36-22-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
362208		**Precooler Outlet Temperature Sensor - Removal / Installation**							RE (O/C)			
36 A/F		Right	0				Mos	20-Nov-2022				
1150124-2-2		New	0				Hrs	0				
1150124-18837			0				Ldg	0				
Mfg#:36-22-01												
380002		**Water / Waste System Heating Control Module - Removal / Installation**							RE (O/C)			
38 A/F			0				Mos	20-Nov-2022				
SHCM9280-05		New	0				Hrs	0				
04740308			0				Ldg	0				
Mfg#:38-00-01												
380006		**Water / Waste System Lines (301M) - Removal / Installation**							RE (O/C)			
38 A/F			0				Mos	20-Nov-2022				
RL-01		New	0				Hrs	0				
NSN			0				Ldg	0				
380008		**Water / Waste System Lines (406M) - Removal / Installation**							RE (O/C)			
38 A/F			0				Mos	20-Nov-2022				
PWL18-01		New	0				Hrs	0				
NSN			0				Ldg	0				
380010		**Water / Waste System Lines (410M) - Removal / Installation**							RE (O/C)			
38 A/F			0				Mos	20-Nov-2022				
GWL-14-01		New	0				Hrs	0				
NSN			0				Ldg	0				
380012		**Water / Waste System Lines (411M) - Removal / Installation**							RE (O/C)			
38 A/F			0				Mos	20-Nov-2022				
PWL-10-01		New	0				Hrs	0				
NSN			0				Ldg	0				
380014		**Water / Waste System Lines (412M) - Removal / Installation**							RE (O/C)			
38 A/F			0				Mos	20-Nov-2022				
PWL16-01		New	0				Hrs	0				
NSN			0				Ldg	0				
380016		**Water / Waste System Lines (413M) - Removal / Installation**							RE (O/C)			
38 A/F			0				Mos	20-Nov-2022				
PWL20-01		New	0				Hrs	0				
NSN			0				Ldg	0				
380018		**Water / Waste System Lines (414M) - Removal / Installation**							RE (O/C)			
38 A/F			0				Mos	20-Nov-2022				
PWL17-01		New	0				Hrs	0				
NSN			0				Ldg	0				
380020		**Water / Waste System Lines (415M) - Removal / Installation**							RE (O/C)			
38 A/F			0				Mos	20-Nov-2022				
PWL-14		New	0				Hrs	0				
NSN			0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
380022		**Water / Waste System Lines (416M) - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	GWL-11-01	New	0				Hrs	0				
	NSN		0				Ldg	0				
380024		**Water / Waste System Lines (417M) - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	PWL-13	New	0				Hrs	0				
	NSN		0				Ldg	0				
380026		**Water / Waste System Lines (418M) - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	PWL-34	New	0				Hrs	0				
	NSN		0				Ldg	0				
380028		**Water / Waste System Lines (419M) - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	PWL-30	New	0				Hrs	0				
	NSN		0				Ldg	0				
380030		**Water / Waste System Lines (421M) - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	PWL11-01	New	0				Hrs	0				
	NSN		0				Ldg	0				
380032		**Water / Waste System Lines (422M) - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	PWL-29	New	0				Hrs	0				
	NSN		0				Ldg	0				
380034		**Water / Waste System Lines (423M) - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	PWL-32	New	0				Hrs	0				
	NSN		0				Ldg	0				
380036		**Water / Waste System Lines (424M) - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	SL-04-01	New	0				Hrs	0				
	NSN		0				Ldg	0				
380038		**Water / Waste System Lines (425M) - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	PWL21-01	New	0				Hrs	0				
	NSN		0				Ldg	0				
380040		**Water / Waste System Lines (432M) - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	PWL19-01	New	0				Hrs	0				
	NSN		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
380042		**Water / Waste System Lines (434M) - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	GWL-13-01	New	0				Hrs	0				
	NSN		0				Ldg	0				
380044		**Water / Waste System Lines (442M) - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	PWL23-01	New	0				Hrs	0				
	NSN		0				Ldg	0				
380046		**Water / Waste System Lines (450M) - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	SL-02	New	0				Hrs	0				
	NSN		0				Ldg	0				
380048		**Water / Waste System Lines (451M) - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	PWL01-01	New	0				Hrs	0				
	NSN		0				Ldg	0				
380050		**Water / Waste System Lines (452M) - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	PWL-02-01	New	0				Hrs	0				
	NSN		0				Ldg	0				
380052		**Water / Waste System Lines (453M) - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	PWL-03-01	New	0				Hrs	0				
	NSN		0				Ldg	0				
380054		**Water / Waste System Lines (454M) - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	GWL-01-01	New	0				Hrs	0				
	NSN		0				Ldg	0				
381006		**Water Heater - Removal / Installation**							RE (O/C)			
	38 A/F	Aft Lavatory	0				Mos	10-Feb-2023				
	MRX-1000-501A-S	New	0				Hrs	24:24				
	1051-582A-S		0				Ldg	7				
381008		**Water Heater - Removal / Installation**							RE (O/C)			
	38 A/F	Galley	0				Mos	10-Feb-2023				
	MRX-1000-501A-S	New	0				Hrs	24:24				
	1051-581A-S		0				Ldg	7				
381103		**Potable Water Pump - Removal / Installation**							RE (O/C)			
	38 A/F	No.1					Mos	10-Feb-2023				
	PWP9282-02						Hrs	24:24				
	04220674						Ldg	7				
	Mfg#:38-11-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
381104		**Potable Water Pump - Removal / Installation**							RE (O/C)			
	38 A/F	No.2	0				Mos	20-Nov-2022				
	PWP9282-02	New	0				Hrs	0				
	04220670		0				Ldg	0				
	Mfg#:38-11-01											
381106		**Manual Shut-off Valve - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	MSV9297-00	New	0				Hrs	0				
	03260271		0				Ldg	0				
	Mfg#:38-11-02											
381202		**Potable Water Control Unit - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	WLS9292-03	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:38-12-01											
381209		**Potable Water Pressure Switch - Removal / Installation**							RE (O/C)			
	38 A/F	No.1	0				Mos	20-Nov-2022				
	PS9283-00	New	0				Hrs	0				
	04520601		0				Ldg	0				
	Mfg#:38-12-03											
381210		**Potable Water Pressure Switch - Removal / Installation**							RE (O/C)			
	38 A/F	No.2	0				Mos	20-Nov-2022				
	PS9283-00	New	0				Hrs	0				
	04520600		0				Ldg	0				
	Mfg#:38-12-03											
381302		**Potable Water Tank Module - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	PWM9290-05	New	0				Hrs	0				
	03470560		0				Ldg	0				
	Mfg#:38-13-01											
381306		**Potable Water Pressure Reservoir - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	PA9285-01	New	0				Hrs	0				
	03540293		0				Ldg	0				
	Mfg#:38-13-02											
381502		**Potable Water Drain Valve - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	DV9277-03	New	0				Hrs	0				
	0353		0				Ldg	0				
	Mfg#:38-15-01											
381506		**Potable Water Fill / Drain Valve - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	FDH9286-01	New	0				Hrs	0				
	0354		0				Ldg	0				
	Mfg#:38-15-01											
381508		**Fill / Drain Control Panel - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	FDCP9219-00	New	0				Hrs	0				
	04630262		0				Ldg	0				
	Mfg#:38-15-02											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
381510		**Potable Water Drain Mast - Removal / Installation**							RE (O/C)			
38 A/F		Aft	0				Mos	20-Nov-2022				
DM9293-00		New	0				Hrs	0				
HL5112			0				Ldg	0				
Mfg#:38-15-03												
381512		**Potable Water Drain Mast - Removal / Installation**							RE (O/C)			
38 A/F		Fwd	0				Mos	20-Nov-2022				
DM9298-00		New	0				Hrs	0				
HL5040			0				Ldg	0				
Mfg#:38-15-03												
381514		**Potable Water Overflow Nipple - Removal / Installation**							RE (O/C)			
38 A/F			0				Mos	20-Nov-2022				
SP9289-01		New	0				Hrs	0				
04670341			0				Ldg	0				
Mfg#:38-15-04												
381516		**Potable Water Fill / Drain Nipple - Removal / Installation**							RE (O/C)			
38 A/F			0				Mos	20-Nov-2022				
FDP9296-01		New	0				Hrs	0				
04660344			0				Ldg	0				
Mfg#:38-15-04												
381518		**Water Waste System Control Panel - Removal / Installation**							RE (O/C)			
38 A/F		Galley	0				Mos	10-Feb-2023				
WWP9278-01		New	0				Hrs	24:24				
04680461			0				Ldg	7				
381520		**Water Filter - Removal / Installation**							RE (O/C)			
38 A/F		Galley	0				Mos	10-Feb-2023				
770109		New	0				Hrs	24:24				
A036645			0				Ldg	7				
381522		**Drain Valve - Removal / Installation**							RE (O/C)			
38 A/F		Galley	0				Mos	10-Feb-2023				
300-0015-01		New	0				Hrs	24:24				
33225314			0				Ldg	7				
381524		**Manual Valve - Removal / Installation**							RE (O/C)			
38 A/F		Galley	0				Mos	10-Feb-2023				
4E4474-1		New	0				Hrs	24:24				
N3000505			0				Ldg	7				
381525		**Galley Float Check Valve - Removal / Installation**							RE (O/C)			
38 A/F		No.1	0				Mos	10-Feb-2023				
4E4350-2		New	0				Hrs	24:24				
N3000180			0				Ldg	7				
381526		**Manual Valve - Removal / Installation**							RE (O/C)			
38 A/F		Galley	0				Mos	10-Feb-2023				
4E4474-1		New	0				Hrs	24:24				
N3000506			0				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
381528		**Drain Valve - Removal / Installation**							RE (O/C)			
38 A/F		Lavatory	0				Mos	10-Feb-2023				
	300-0015-01	New	0				Hrs	24:24				
	33225313		0				Ldg	7				
381530		**Manual Valve - Removal / Installation**							RE (O/C)			
38 A/F		Lavatory	0				Mos	10-Feb-2023				
	4E4474-1	New	0				Hrs	24:24				
	N3000508		0				Ldg	7				
381532		**Manual Valve - Removal / Installation**							RE (O/C)			
38 A/F		Lavatory	0				Mos	10-Feb-2023				
	4E4474-1	New	0				Hrs	24:24				
	N3000507		0				Ldg	7				
381533		**Galley Float Check Valve - Removal / Installation**							RE (O/C)			
38 A/F		No.2	0				Mos	10-Feb-2023				
	4E4350-1	New	0				Hrs	24:24				
	N3000764		0				Ldg	7				
381534		**Float Check Valve - Removal / Installation**							RE (O/C)			
38 A/F		Galley - No.3	0				Mos	10-Feb-2023				
	4E4350-2	New	0				Hrs	24:24				
	N3000137		0				Ldg	7				
383102		**Waste System Tank Module - Removal / Installation**							RE (O/C)			
38 A/F			0				Mos	20-Nov-2022				
	TM9210-03	New	0				Hrs	0				
	03500499		0				Ldg	0				
	Mfg#:38-31-01											
383104		**Waste Control Unit - Removal / Installation**							RE (O/C)			
38 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Ref#:38-31-02											
383106		**Vacuum Generator - Removal / Installation**							RE (O/C)			
38 A/F			0				Mos	20-Nov-2022				
	VR9218-01	New	0				Hrs	0				
	03700375		0				Ldg	0				
	Mfg#:38-31-03											
383202		**Service Panel Lever - Removal / Installation**							RE (O/C)			
38 A/F			0				Mos	20-Nov-2022				
	SPL9205-00	New	0				Hrs	0				
	03630275		0				Ldg	0				
	Mfg#:38-32-01											
383204		**Actuation Unit - Removal / Installation**							RE (O/C)			
38 A/F			0				Mos	20-Nov-2022				
	DVA9216-00	New	0				Hrs	0				
	03530278		0				Ldg	0				
	Mfg#:38-32-02											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
383206		**Waste System Dump Valve - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	WDV9215-00	New	0				Hrs	0				
	03490273		0				Ldg	0				
	Mfg#:38-32-03											
383208		**Waste System Drain Valve - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	WBV9741-00	New	0				Hrs	0				
	07600021		0				Ldg	0				
	Mfg#:38-32-04											
383210		**Waste Drain Heaters - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	HD9209-01	New	0				Hrs	0				
	03550294		0				Ldg	0				
	Mfg#:38-32-04											
383212		**Waste System Flush Nipple - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	20-Nov-2022				
	FNH9217-01	New	0				Hrs	0				
	05510340		0				Ldg	0				
	Mfg#:38-32-05											
383306		**Vacuum Toilet Assembly - Removal / Installation**							RE (O/C)			
	38 A/F		0				Mos	10-Feb-2023				
	TA9208-1	New	0				Hrs	24:24				
	03640282		0				Ldg	7				
463103		**Information Management System Unit - Removal / Installation**							RE (O/C)			
	46 A/F		0				Mos	20-Nov-2022				
	822-3132-301	New	0				Hrs	0				
	4R0GY1		0				Ldg	0				
	Mfg#:46-31-01											
463106		**Wireless LAN Antenna - Removal / Installation**							RE (O/C)			
	46 A/F		0				Mos	20-Nov-2022				
	822-1531-001	New	0				Hrs	0				
	4M5R94		0				Ldg	0				
	ATA Ref::46-31-02, Mfg#:46-31-02											
463108		**Data Load Switch - Removal / Installation**							RE (O/C)			
	46 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
463110		**Adaptive Flight Display - Reload Software**							RE (O/C)			
	46 A/F	No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	(SOURCE: 46-05-00)											
463111		**Adaptive Flight Display - Reload Software**							RE (O/C)			
	46 A/F	No.3					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	(SOURCE: 46-05-00)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
463128		**Air Data Computer - Field Load Software**							RE (O/C)			
	46 A/F	No.1					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	(SOURCE: 46-02-00)											
463129		**Air Data Computer - Field Load Software**							RE (O/C)			
	46 A/F	No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	(SOURCE: 46-02-00)											
490002		**APU - Removal / Installation**							RE (O/C)			
	49 A/F		3				Mos	20-Nov-2022				
	3800710-3						Hrs	0				
	P-362						Ldg	0				
	Mfg#:49-00-00-RI											
490014		**APU Wiring Harness - Removal / Installation**							RE (O/C)			
	49 APU1		0				Mos	16-Aug-2022				
	3888566-1	New	0				Hrs	0				
	22-129505-00125		0				APUS	0				
	Mfg#:49-00-00-RI											
491105		**APU Lower Mount - Removal / Installation**							RE (O/C)			
	49 A/F	Left	0				Mos	20-Nov-2022				
	94923-31	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:49-11-01-RI											
491106		**APU Lower Mount - Removal / Installation**							RE (O/C)			
	49 A/F	Right	0				Mos	20-Nov-2022				
	94923-31	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:49-11-01-RI											
491107		**APU Upper Mount - Removal / Installation**							RE (O/C)			
	49 A/F		0				Mos	20-Nov-2022				
	94923-31	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:49-11-01-RI											
492002		**APU Ejector Assembly - Removal / Installation**							RE (O/C)			
	49 APU1						Mos	16-Aug-2022				
	Unknown						Hrs	0				
	Unknown						APUS	0				
	Mfg#:49-20-01											
492101		**APU - Power Section Assembly Cylindrical Roller Bearing - Removal / Installation**							RE (O/C)			
	49 APU1						Mos	09-Apr-2024				
	3842004-1	New	0				Hrs	443				
	22-162370-04447		0				APUS	626				
492102		**APU - Power Section Assembly Annular Ball Bearing - Removal / Installation**							RE (O/C)			
	49 APU1						Mos	09-Apr-2024				
	3822129-1	New	0				Hrs	443				
	UNKNOWN		0				APUS	626				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
492103		**APU - Gear Set - Spur, Matched, Crowned, Planet - Removal / Installation**							RE (O/C)			
49 APU1		No.1					Mos	09-Apr-2024				
	3860339-1	New	0				Hrs	443				
	UNKNOWN		0				APUS	626				
492106		**Apu - Compressor Seal Set (Matched)**							RE (O/C)			
49 APU1							Mos	09-Apr-2024				
	70721582-1	New	0				Hrs	443				
	01069		0				APUS	626				
492107		**APU - Power Section Assembly - Removal / Installation**							RE (O/C)			
49 APU1			0				Mos	16-Aug-2022				
	3801320-4	New	0				Hrs	0				
	6013767572		0				APUS	0				
492203		**APU - Accessory Drive - Gearbox Assembly Generator Seal Set (Matched) - Removal / Installation**							RE (O/C)			
49 APU1							Mos	09-Apr-2024				
	70721719-1	New	0				Hrs	443				
	01204		0				APUS	626				
493102		**APU Fuel Control - Removal / Installation**							RE (O/C)			
49 APU1			0				Mos	16-Aug-2022				
	3882730-8	New	0				Hrs	0				
	43327		0				APUS	0				
	Mfg#:49-31-01											
493104		**APU Fuel Shut-off Valve - Removal / Installation**							RE (O/C)			
49 APU1			0				Mos	16-Aug-2022				
	692545-18	New	0				Hrs	0				
	NSN		0				APUS	0				
	Mfg#:49-31-02											
493106		**APU Primary Fuel Manifold - Removal / Installation**							RE (O/C)			
49 APU1			0				Mos	16-Aug-2022				
	3830155-2	New	0				Hrs	0				
	NSN		0				APUS	0				
	Mfg#:49-31-03											
493108		**APU Secondary Fuel Manifold - Removal / Installation**							RE (O/C)			
49 APU1			0				Mos	16-Aug-2022				
	3830156-2	New	0				Hrs	0				
	NSN		0				APUS	0				
	Mfg#:49-31-03											
493115		**APU Fuel Nozzle Assembly (Primary) - Removal / Installation**							RE (O/C)			
49 APU1		No.1					Mos	16-Aug-2022				
	Unknown						Hrs	0				
	Unknown						APUS	0				
	Mfg#:49-31-04											
493116		**APU Fuel Nozzle Assembly (Primary) - Removal / Installation**							RE (O/C)			
49 APU1		No.2					Mos	16-Aug-2022				
	Unknown						Hrs	0				
	Unknown						APUS	0				
	Mfg#:49-31-04											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
493117		**APU Fuel Nozzle Assembly (Primary) - Removal / Installation**							RE (O/C)			
	49 APU1	No.3					Mos	16-Aug-2022				
	Unknown						Hrs	0				
	Unknown						APUS	0				
	Mfg#:49-31-04											
493123		**APU Fuel Nozzle Assembly (Secondary) - Removal / Installation**							RE (O/C)			
	49 APU1	No.1					Mos	16-Aug-2022				
	Unknown						Hrs	0				
	Unknown						APUS	0				
	Mfg#:49-31-04											
493124		**APU Fuel Nozzle Assembly (Secondary) - Removal / Installation**							RE (O/C)			
	49 APU1	No.2					Mos	16-Aug-2022				
	Unknown						Hrs	0				
	Unknown						APUS	0				
	Mfg#:49-31-04											
493125		**APU Fuel Nozzle Assembly (Secondary) - Removal / Installation**							RE (O/C)			
	49 APU1	No.3					Mos	16-Aug-2022				
	Unknown						Hrs	0				
	Unknown						APUS	0				
	Mfg#:49-31-04											
493128		**APU Fuel Flow Divider Valve - Removal / Installation**							RE (O/C)			
	49 APU1		0				Mos	16-Aug-2022				
	3830166-1	New	0				Hrs	0				
	NSN		0				APUS	0				
	Mfg#:49-31-05											
493130		**APU Fuel Tube - Removal / Installation**							RE (O/C)			
	49 APU1						Mos	16-Aug-2022				
	Unknown						Hrs	0				
	Unknown						APUS	0				
	Mfg#:49-31-06											
493202		**APU Fuel Filter - Removal / Installation**							RE (O/C)			
	49 APU1		0				Mos	16-Aug-2022				
	3882440-1	New	0				Hrs	0				
	NSN		0				APUS	0				
	Mfg#:49-32-01-RI											
494202		**APU Ignition Unit - Removal / Installation**							RE (O/C)			
	49 APU1		0				Mos	16-Aug-2022				
	3888000-3	New	0				Hrs	0				
	J21080307		0				APUS	0				
	Mfg#:49-42-01											
494204		**APU Igniter Plug - Removal / Installation**							RE (O/C)			
	49 APU1						Mos	09-Apr-2024				
	3888002-5	New	0				Hrs	443				
	NSN		0				APUS	626				
	Mfg#:49-42-02											
494206		**APU Igniter Plug Lead - Removal / Installation**							RE (O/C)			
	49 APU1						Mos	16-Aug-2022				
	Unknown						Hrs	0				
	Unknown						APUS	0				
	Mfg#:49-42-03											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
495104		**APU Air Inlet Door Actuator - Removal / Installation**							RE (O/C)			
	49 A/F		0				Mos	20-Nov-2022				
	221400-2 M00	New	0				Hrs	0				
	539		0				Ldg	0				
	Mfg#:49-51-02											
495202		**APU Surge Control Valve - Removal / Installation**							RE (O/C)			
	49 APU1		0				Mos	16-Aug-2022				
	3884538-6	New	0				Hrs	0				
	NSN		0				APUS	0				
	Mfg#:49-52-01											
496102		**APU Electronic Control Unit - Removal / Installation**							RE (O/C)			
	49 APU1		0				Mos	16-Aug-2022				
	2119584-7003	New	0				Hrs	0				
	71-AM0162		0				APUS	0				
	Mfg#:49-61-01											
496108		**APU Speed Sensor - Removal / Installation**							RE (O/C)			
	49 APU1						Mos	16-Aug-2022				
	Unknown						Hrs	0				
	Unknown						APUS	0				
	Mfg#:49-61-02											
496110		**APU Inlet Temperature Sensor - Removal / Installation**							RE (O/C)			
	49 APU1						Mos	16-Aug-2022				
	Unknown						Hrs	0				
	Unknown						APUS	0				
	Mfg#:49-61-03											
496112		**APU EGT Thermocoupler - Removal / Installation**							RE (O/C)			
	49 APU1		0				Mos	16-Aug-2022				
	3876003-3	New	0				Hrs	0				
	2215027700289		0				APUS	0				
	Mfg#:49-61-04											
497102		**APU Hourmeter - Removal / Installation**							RE (O/C)			
	49 APU1		0				Mos	16-Aug-2022				
	3876316-1	New	0				Hrs	0				
	NSN		0				APUS	0				
	Mfg#:49-71-01-RI											
497103		**APU Start Counter - Removal / Installation**							RE (O/C)			
	49 APU1						Mos	16-Aug-2022				
	Unknown						Hrs	0				
	Unknown						APUS	0				
	Mfg#:49-71-02											
498104		**APU Exhaust Duct - Removal / Installation**							RE (O/C)			
	49 APU1		0				Mos	16-Aug-2022				
	4AS6900250-503	New	0				Hrs	0				
	NSN		0				APUS	0				
	Mfg#:49-81-01-RI											
499102		**APU Oil Pump - Removal / Installation**							RE (O/C)			
	49 APU1						Mos	09-Apr-2024				
	3880225-2	Overhauled		0			Hrs	443				
	UNKNOWN			0			APUS	626				
	Mfg#:49-91-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
499104		**APU Oil Pressure Regulator - Removal / Installation**							RE (O/C)			
	49 APU1						Mos	16-Aug-2022				
	Unknown						Hrs	0				
	Unknown						APUS	0				
	Mfg#:49-91-02											
499202		**APU Oil Filter Element - Removal / Installation**							RE (O/C)			
	49 APU1						Mos	09-Apr-2024				
	3608765-1	New	0				Hrs	443				
	NSN		0				APUS	626				
	Mfg#:49-92-01											
499206		**APU Magnetic Chip Detector - Removal / Installation**							RE (O/C)			
	49 APU1		0				Mos	16-Aug-2022				
	P91	New	0				Hrs	0				
	NSN		0				APUS	0				
	Mfg#:49-92-02-RI											
499302		**APU High Oil Temperature Sensor - Removal / Installation**							RE (O/C)			
	49 APU1						Mos	16-Aug-2022				
	Unknown						Hrs	0				
	Unknown						APUS	0				
	Mfg#:49-93-01											
499304		**APU Oil Level Sensor - Removal / Installation**							RE (O/C)			
	49 APU1						Mos	16-Aug-2022				
	Unknown						Hrs	0				
	Unknown						APUS	0				
	Mfg#:49-93-02											
499306		**APU Low Oil Pressure Switch - Removal / Installation**							RE (O/C)			
	49 APU1						Mos	10-Feb-2023				
	3876001-8						Hrs					
	NSN						APUS					
	Mfg#:49-93-03											
499901		**APU - Electro-Magnetic Control Valve - Removal / Installation**							RE (O/C)			
	49 APU1		0				Mos	16-Aug-2022				
	3160785-27	New	0				Hrs	0				
	172167		0				APUS	0				
499902		**APU - Valve Set Slv Mtg - Removal / Installation**							RE (O/C)			
	49 APU1		0				Mos	16-Aug-2022				
	3601509-1	New	0				Hrs	0				
	MS21-150493-04464		0				APUS	0				
499903		**APU - Torque Motor - Removal / Installation**							RE (O/C)			
	49 APU1		0				Mos	16-Aug-2022				
	3876077-10	New	0				Hrs	0				
	22-150275-03078		0				APUS	0				
499904		**APU - Planetary Assembly - Removal / Installation**							RE (O/C)			
	49 APU1		0				Mos	16-Aug-2022				
	3801320-902	New	0				Hrs	0				
	LA101310		0				APUS	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
499905		**APU - Heatsink & Circuit Card Assembly, I/0 - Removal / Installation**							RE (O/C)			
49 APU1			0				Mos	16-Aug-2022				
	4244283-6	New	0				Hrs	0				
	NSN		0				APUS	0				
499906		**APU - Heatsink & Circuit Card Assembly, Cpu/Po - Removal / Installation**							RE (O/C)			
49 APU1			0				Mos	16-Aug-2022				
	4244263-4	New	0				Hrs	0				
	NSN		0				APUS	0				
499907		**APU - Rotor Mark - Removal / Installation**							RE (O/C)			
49 APU1			0				Mos	16-Aug-2022				
	3842088-111	New	0				Hrs	0				
	21-156101-05545		0				APUS	0				
499908		**APU - Gearbox Assembly - Removal / Installation**							RE (O/C)			
49 APU1			0				Mos	16-Aug-2022				
	3805052-2	New	0				Hrs	0				
	LA101311		0				APUS	0				
499909		**APU - Rotor - Removal / Installation**							RE (O/C)			
49 APU1			0				Mos	16-Aug-2022				
	3609831-111	New	0				Hrs	0				
	22-181967-00053		0				APUS	0				
521101		**Passenger / Crew Door Stair Assembly - Removal / Installation**							RE (O/C)			
52 A/F							Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	(SOURCE: 52-11-03)											
521102		**Main Entrance Door - Removal / Installation**							RE (O/C)			
52 A/F			0				Mos	20-Nov-2022				
	30P331008002-501	New	0				Hrs	0				
	FED-256		0				Ldg	0				
	Mfg#:52-11-01-RI											
521112		**Main Entrance Door Seals - Removal / Installation**							RE (O/C)			
52 A/F		Inner	0				Mos	20-Nov-2022				
	4AS3130038-001	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:52-11-02											
521114		**Main Entrance Door Seals - Removal / Installation**							RE (O/C)			
52 A/F		Outer	0				Mos	20-Nov-2022				
	4AS3130037-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:52-11-02											
521202		**Main Entrance Door Actuator - Removal / Installation**							RE (O/C)			
52 A/F			0				Mos	20-Nov-2022				
	90-10202-01	New	0				Hrs	0				
	F0269		0				Ldg	0				
	Mfg#:52-12-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
521204		**Main Entrance Door Solenoid Shut-Off Valve - Removal / Installation**							RE (O/C)			
52 A/F			0				Mos	20-Nov-2022				
90-10203-01		New	0				Hrs	0				
F0266			0				Ldg	0				
Mfg#:52-12-02												
521317		**Main Entrance Door Upper Rollers - Removal / Installation**							RE (O/C)			
52 A/F		Fwd					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:52-13-06												
521318		**Main Entrance Door Upper Rollers - Removal / Installation**							RE (O/C)			
52 A/F		Aft					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:52-13-06												
521321		**Main Entrance Door Lower Rollers - Removal / Installation**							RE (O/C)			
52 A/F		Fwd					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:52-13-06												
521322		**Main Entrance Door Lower Rollers - Removal / Installation**							RE (O/C)			
52 A/F		Aft					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:52-13-06												
521327		**Main Entrance Door Telescopic Rods - Removal / Installation**							RE (O/C)			
52 A/F		Fwd					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:52-13-07												
521328		**Main Entrance Door Telescopic Rods - Removal / Installation**							RE (O/C)			
52 A/F		Aft					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:52-13-07												
521333		**Main Entrance Door Airsprings - Removal / Installation**							RE (O/C)			
52 A/F		Fwd					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:52-13-05												
521334		**Main Entrance Door Airsprings - Removal / Installation**							RE (O/C)			
52 A/F		Aft					Mos	20-Nov-2022				
Unknown							Hrs	0				
Unknown							Ldg	0				
Mfg#:52-13-05												
522102		**Emergency Exit - Removal / Installation**							RE (O/C)			
52 A/F			0				Mos	20-Nov-2022				
30P332100002-501		New	0				Hrs	0				
2253			0				Ldg	0				
Mfg#:52-21-01-RI												

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
522205		**Emergency Exit Torsion Springs - Removal / Installation**							RE (O/C)			
	52 A/F	Fwd					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-22-02											
522206		**Emergency Exit Torsion Springs - Removal / Installation**							RE (O/C)			
	52 A/F	Aft					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-22-02											
523102		**Baggage Door - Removal / Installation**							RE (O/C)			
	52 A/F		0				Mos	20-Nov-2022				
	30P333010001-501	New	0				Hrs	0				
	2253		0				Ldg	0				
	Mfg#:52-31-01-RI											
523116		**Baggage Door Seal - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-31-02											
523203		**Baggage Door Balance Spring Reel - Removal / Installation**							RE (O/C)			
	52 A/F	Fwd	0				Mos	20-Nov-2022				
	300810-1	New	0				Hrs	0				
	40747		0				Ldg	0				
	Mfg#:52-32-02											
523204		**Baggage Door Balance Spring Reel - Removal / Installation**							RE (O/C)			
	52 A/F	Aft	0				Mos	20-Nov-2022				
	300810-1	New	0				Hrs	0				
	40816		0				Ldg	0				
	Mfg#:52-32-02											
523209		**Baggage Door Track Roller Assembly - Removal / Installation**							RE (O/C)			
	52 A/F	Fwd - Upper					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-32-05											
523210		**Baggage Door Track Roller Assembly - Removal / Installation**							RE (O/C)			
	52 A/F	Fwd - Lower					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-32-05											
523211		**Baggage Door Track Roller Assembly - Removal / Installation**							RE (O/C)			
	52 A/F	Aft - Upper					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-32-05											
523212		**Baggage Door Track Roller Assembly - Removal / Installation**							RE (O/C)			
	52 A/F	Aft - Lower					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-32-05											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
524103		**Nose Avionics Service Door - Removal / Installation**							RE (O/C)			
52 A/F		Left	0				Mos	20-Nov-2022				
	30P311031005-501	New	0				Hrs	0				
	CCAC-065		0				Ldg	0				
	Mfg#:52-41-01											
524104		**Nose Avionics Service Door - Removal / Installation**							RE (O/C)			
52 A/F		Right	0				Mos	20-Nov-2022				
	30P311031005-502	New	0				Hrs	0				
	CCAC-065		0				Ldg	0				
	Mfg#:52-41-01											
524107		**Wing Tank Drain Valve Door - Removal / Installation**							RE (O/C)			
52 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-40-01											
524108		**Wing Tank Drain Valve Door - Removal / Installation**							RE (O/C)			
52 A/F		Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-40-01											
524111		**Central Fuel Tank Drain Valve Door - Removal / Installation**							RE (O/C)			
52 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-40-01											
524112		**Central Fuel Tank Drain Valve Door - Removal / Installation**							RE (O/C)			
52 A/F		Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-40-01											
524115		**Feed Tank Drain Valve Door - Removal / Installation**							RE (O/C)			
52 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-40-01											
524116		**Feed Tank Drain Valve Door - Removal / Installation**							RE (O/C)			
52 A/F		Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-40-01											
524119		**Battery Receptacle Door - Removal / Installation**							RE (O/C)			
52 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-40-01											
524120		**Battery Receptacle Door - Removal / Installation**							RE (O/C)			
52 A/F		Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-40-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
524122		**External Electrical Power Door - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-40-01											
524124		**Water Service Door - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-40-01											
524126		**Hydraulic Service Door - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-40-01											
524128		**Waste System Service Door - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-40-01											
524130		**ATS Door - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-40-01											
524132		**Refuel Adapter Door - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-42-01											
524134		**Refuel Control Panel Door - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-42-01											
524136		**Service Compartment Door - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-44-01											
524138		**APU Door - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-44-01											
525102		**Auxiliary Bulkhead Door - Removal / Installation**							RE (O/C)			
	52 A/F		0				Mos	20-Nov-2022				
	30P336010001-501	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:52-51-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
527102		**Main Entrance Door Handle Switch - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-71-01											
527104		**Main Entrance Door Limit Switch - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-71-01											
527106		**Main Entrance Door Position Switch - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-71-01											
527109		**External Baggage Door Switch - Removal / Installation**							RE (O/C)			
	52 A/F	Fwd					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-71-01											
527110		**External Baggage Door Switch - Removal / Installation**							RE (O/C)			
	52 A/F	Aft					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-71-01											
527112		**Auxiliary Bulkhead Door Switch - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-71-01											
527114		**Emergency Exit Door Switch - Removal / Installation**							RE (O/C)			
	52 A/F		0				Mos	20-Nov-2022				
	MS272406	New	0				Hrs	0				
	NSN		0				Ldg	0				
	Mfg#:52-71-01											
527119		**Main Entrance Door Safety Switch - Removal / Installation**							RE (O/C)			
	52 A/F	Fwd	0				Mos	10-Feb-2023				
	LED-42-11 -HE-SB ATT	New	0				Hrs	24:24				
	NSN		0				Ldg	7				
527120		**Main Entrance Door Safety Switch - Removal / Installation**							RE (O/C)			
	52 A/F	Aft					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
527122		**Aft Service Compartment Door Switch - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-71-02-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
527125		**Left Avionics Door Switch - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-71-02-RI											
527126		**Right Avionics Door Switch - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-71-02-RI											
527128		**Refuel Adapter Door Switch - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-71-02-RI											
527130		**Refuel Control Panel Door Switch - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-71-02-RI											
527132		**Hydraulic Service Door Switch - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-71-02-RI											
527135		**Left Battery Door Switch - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-71-02-RI											
527136		**Right Battery Door Switch - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-71-02-RI											
527138		**Water Service Door Switch - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-71-02-RI											
527140		**Waste System Service Door Switch - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-71-02-RI											
527142		**ATS Door Switch - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-71-02-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
527144		**APU Door Switch - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-71-02-RI											
527146		**External Electrical Power Door Switch - Removal / Installation**							RE (O/C)			
	52 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:52-71-02-RI											
531104		**Radome - Removal / Installation**							RE (O/C)			
	53 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:53-11-01-RI											
533202		**Tail Cone - Removal / Installation**							RE (O/C)			
	53 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:53-32-01-RI											
539003		**Fuel Tank Fairing - Removal / Installation**							RE (O/C)			
	53 A/F	Fwd - Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
539004		**Fuel Tank Fairing - Removal / Installation**							RE (O/C)			
	53 A/F	Fwd - Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
551002		**Horizontal Stabilizer - Removal / Installation**							RE (O/C)			
	55 A/F		0				Mos	20-Nov-2022				
	30P450000000-501	New	0				Hrs	0				
	2253		0				Ldg	0				
	Mfg#:55-10-00-RI											
551105		**Horizontal Stabilizer Leading Edge - Removal / Installation**							RE (O/C)			
	55 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:55-10-00-RI											
551106		**Horizontal Stabilizer Leading Edge - Removal / Installation**							RE (O/C)			
	55 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:55-10-00-RI											
551171		**Horizontal Stabilizer Scissors Assembly - Removal / Installation**							RE (O/C)			
	55 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:55-11-01-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
551172		**Horizontal Stabilizer Scissor Brace - Removal / Installation**							RE (O/C)			
	55 A/F	Upper					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:55-11-01-RI											
551173		**Horizontal Stabilizer Scissor Brace - Removal / Installation**							RE (O/C)			
	55 A/F	Lower					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:55-11-01-RI											
553002		**Vertical Stabilizer - Removal / Installation**							RE (O/C)			
	55 A/F		0				Mos	20-Nov-2022				
	30P410000000-501	New	0				Hrs	0				
	2253		0				Ldg	0				
553006		**Vertical Stabilizer Bullet Fairing - Removal / Installation**							RE (O/C)			
	55 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:55-30-00											
561103		**Windshield Assembly - Removal / Installation**							RE (O/C)			
	56 A/F	Pilot	0				Mos	20-Nov-2022				
	NP-178201-21	New	0				Hrs	0				
	22174H7981		0				Ldg	0				
	Mfg#:56-11-01											
561104		**Windshield Assembly - Removal / Installation**							RE (O/C)			
	56 A/F	Copilot	0				Mos	20-Nov-2022				
	NP-178201-22	New	0				Hrs	0				
	22080H0558		0				Ldg	0				
	Mfg#:56-11-01											
561107		**Side Window Assembly - Removal / Installation**							RE (O/C)			
	56 A/F	Pilot	0				Mos	20-Nov-2022				
	NP-178202-13	New	0				Hrs	0				
	22021H5624		0				Ldg	0				
	Mfg#:56-11-02											
561108		**Side Window Assembly - Removal / Installation**							RE (O/C)			
	56 A/F	Copilot	0				Mos	20-Oct-2023				
	NP-178202-10	New	0				Hrs	490:27				
	23047H6833		0				Ldg	293				
	Mfg#:56-11-02											
562121		**Cabin Window Assembly - Removal / Installation**							RE (O/C)			
	56 A/F	Left No.1	0				Mos	20-Nov-2022				
	NP-178203-3	New	0				Hrs	0				
	22032H6473		0				Ldg	0				
	Mfg#:56-21-01											
562122		**Cabin Window Assembly - Removal / Installation**							RE (O/C)			
	56 A/F	Right No.1	0				Mos	20-Nov-2022				
	NP-178203-3	New	0				Hrs	0				
	22034H6665		0				Ldg	0				
	Mfg#:56-21-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
562123		**Cabin Window Assembly - Removal / Installation**							RE (O/C)			
56 A/F	NP-178203-3	Left No.2	0				Mos	20-Nov-2022				
	22073H9991	New	0				Hrs	0				
	Mfg#:56-21-01		0				Ldg	0				
562124		**Cabin Window Assembly - Removal / Installation**							RE (O/C)			
56 A/F	NP-178203-3	Right No.2	0				Mos	20-Nov-2022				
	22041H7304	New	0				Hrs	0				
	Mfg#:56-21-01		0				Ldg	0				
562125		**Cabin Window Assembly - Removal / Installation**							RE (O/C)			
56 A/F	NP-178203-3	Left No.3	0				Mos	20-Nov-2022				
	22074H0063	New	0				Hrs	0				
	Mfg#:56-21-01		0				Ldg	0				
562126		**Cabin Window Assembly - Removal / Installation**							RE (O/C)			
56 A/F	NP-178203-3	Right No.3	0				Mos	20-Nov-2022				
	22073H9992	New	0				Hrs	0				
	Mfg#:56-21-01		0				Ldg	0				
562127		**Cabin Window Assembly - Removal / Installation**							RE (O/C)			
56 A/F	NP-178203-3	Left No.4	0				Mos	20-Nov-2022				
	22070H9840	New	0				Hrs	0				
	Mfg#:56-21-01		0				Ldg	0				
562128		**Cabin Window Assembly - Removal / Installation**							RE (O/C)			
56 A/F	NP-178203-3	Right No.4	0				Mos	20-Nov-2022				
	22070H9835	New	0				Hrs	0				
	Mfg#:56-21-01		0				Ldg	0				
562129		**Cabin Window Assembly - Removal / Installation**							RE (O/C)			
56 A/F	NP-178203-3	Left No.5	0				Mos	20-Nov-2022				
	22074H0059	New	0				Hrs	0				
	Mfg#:56-21-01		0				Ldg	0				
562130		**Cabin Window Assembly - Removal / Installation**							RE (O/C)			
56 A/F	NP-178203-3	Right No.5	0				Mos	20-Nov-2022				
	22066H9300	New	0				Hrs	0				
	Mfg#:56-21-01		0				Ldg	0				
562131		**Cabin Window Assembly - Removal / Installation**							RE (O/C)			
56 A/F	NP-178203-3	Left No.6	0				Mos	20-Nov-2022				
	22075H0185	New	0				Hrs	0				
	Mfg#:56-21-01		0				Ldg	0				
562132		**Cabin Window Assembly - Removal / Installation**							RE (O/C)			
56 A/F	NP-178203-3	Right No.6	0				Mos	20-Nov-2022				
	22073H9989	New	0				Hrs	0				
	Mfg#:56-21-01		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
562133		**Cabin Window Assembly - Removal / Installation**							RE (O/C)			
56 A/F	NP-178203-3	Left No.7 / New	0				Mos	20-Nov-2022				
	22032H6469		0				Hrs	0				
	Mfg#:56-21-01		0				Ldg	0				
562134		**Cabin Window Assembly - Removal / Installation**							RE (O/C)			
56 A/F	NP-178203-3	Right No.7 / New	0				Mos	20-Nov-2022				
	22136H4912		0				Hrs	0				
	Mfg#:56-21-01		0				Ldg	0				
562135		**Cabin Window Assembly - Removal / Installation**							RE (O/C)			
56 A/F	NP-178203-3	Left No.8 / New	0				Mos	20-Nov-2022				
	22041H7305		0				Hrs	0				
	Mfg#:56-21-01		0				Ldg	0				
562136		**Cabin Window Assembly - Removal / Installation**							RE (O/C)			
56 A/F	NP-178203-3	Right No.8 / New	0				Mos	20-Nov-2022				
	22066H9299		0				Hrs	0				
	Mfg#:56-21-01		0				Ldg	0				
562137		**Cabin Window Assembly - Removal / Installation**							RE (O/C)			
56 A/F	NP-178203-3	Left No.9 / New	0				Mos	20-Nov-2022				
	22063H9254		0				Hrs	0				
	Mfg#:56-21-01		0				Ldg	0				
562138		**Cabin Window Assembly - Removal / Installation**							RE (O/C)			
56 A/F	NP-178203-3	Right No.9 / New	0				Mos	20-Nov-2022				
	22073H9990		0				Hrs	0				
	Mfg#:56-21-01		0				Ldg	0				
562140		**Cabin Window Assembly - Removal / Installation**							RE (O/C)			
56 A/F	NP-178203-3	Right No.10 / New	0				Mos	20-Nov-2022				
	22038H6963		0				Hrs	0				
	Mfg#:56-21-01		0				Ldg	0				
564002		**Main Entrance Door Viewport Assembly - Removal / Installation**							RE (O/C)			
56 A/F	Unknown						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Mfg#:56-40-01						Ldg	0				
564004		**Main Entrance Door Viewport Scope - Removal / Installation**							RE (O/C)			
56 A/F	Unknown						Mos	20-Nov-2022				
	Unknown						Hrs	0				
							Ldg	0				
570135		**Wing Fuel Access Panel (521AL) - Removal / Installation**							RE (O/C)			
57 A/F	Unknown	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Mfg#:57-01-00-RI						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
570136		**Wing Fuel Access Panel (621AR) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570137		**Wing Fuel Access Panel (521BL) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570138		**Wing Fuel Access Panel (621BR) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570139		**Wing Fuel Access Panel (521CL) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570140		**Wing Fuel Access Panel (621CR) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570141		**Wing Fuel Access Panel (521DL) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570142		**Wing Fuel Access Panel (621DR) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570143		**Wing Fuel Access Panel (521EL) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570144		**Wing Fuel Access Panel (621ER) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570145		**Wing Fuel Access Panel (521FL) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
570146		**Wing Fuel Access Panel (621FR) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570147		**Wing Fuel Access Panel (521GL) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570148		**Wing Fuel Access Panel (621GR) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570149		**Wing Fuel Access Panel (521HL) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570150		**Wing Fuel Access Panel (621HR) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570151		**Wing Fuel Access Panel (521JL) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570152		**Wing Fuel Access Panel (621JR) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570153		**Wing Fuel Access Panel (521KL) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570154		**Wing Fuel Access Panel (621KR) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570155		**Wing Fuel Access Panel (521LL) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
570156		**Wing Fuel Access Panel (621LR) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570157		**Wing Fuel Access Panel (521ML) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570158		**Wing Fuel Access Panel (621MR) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570159		**Wing Fuel Access Panel (521NL) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570160		**Wing Fuel Access Panel (621NR) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570161		**Wing Fuel Access Panel (521PL) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570162		**Wing Fuel Access Panel (621PR) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570163		**Wing Fuel Access Panel (521QL) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570164		**Wing Fuel Access Panel (621QR) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
570165		**Wing Fuel Access Panel (521RL) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
570166		**Wing Fuel Access Panel (621RR) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-01-00-RI											
571607		**Wing To Fuselage Drag Link - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-16-00											
571608		**Wing To Fuselage Drag Link - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-16-00											
573103		**Winglet Assembly (Left) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-31-01											
573104		**Winglet Assembly (Right) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-31-01											
574111		**Wing Leading Edge - Removal / Installation**							RE (O/C)			
	57 A/F	Left No.1					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
574112		**Wing Leading Edge - Removal / Installation**							RE (O/C)			
	57 A/F	Right No.1					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
574113		**Wing Leading Edge - Removal / Installation**							RE (O/C)			
	57 A/F	Left No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
574114		**Wing Leading Edge - Removal / Installation**							RE (O/C)			
	57 A/F	Right No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
574115		**Wing Leading Edge - Removal / Installation**							RE (O/C)			
	57 A/F	Left No.3					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
574116		**Wing Leading Edge - Removal / Installation**							RE (O/C)			
	57 A/F	Right No.3					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
574117		**Wing Leading Edge - Removal / Installation**							RE (O/C)			
	57 A/F	Left No.4					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
574118		**Wing Leading Edge - Removal / Installation**							RE (O/C)			
	57 A/F	Right No.4					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
574125		**Wing Inboard Leading Edge Upper Panel (511AT) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
574126		**Wing Inboard Leading Edge Lower Panel (511BB) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
574127		**Wing Inboard Leading Edge Upper Panel (611AT) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
574128		**Wing Inboard Leading Edge Lower Panel (611BB) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
574139		**Wing Leading Edge Access Panel (Gap Band - 512AL) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
574140		**Wing Leading Edge Access Panel (Gap Band - 612AR) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
574141		**Wing Leading Edge Access Panel (Gap Band - 512BL) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
574142		**Wing Leading Edge Access Panel (Gap Band - 612BR) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
574143		**Wing Leading Edge Access Panel (Gap Band - 512CL) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
574144		**Wing Leading Edge Access Panel (Gap Band - 612CR) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
574145		**Wing Leading Edge Access Panel (Gap Band - 512DL) - Removal / Installation**							RE (O/C)			
	57 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
574146		**Wing Leading Edge Access Panel (Gap Band - 612DR) - Removal / Installation**							RE (O/C)			
	57 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
574153		**Wing Outboard Bellcrank Assembly Access Cover (512EB) - Removal / Installation**							RE (O/C)			
	57 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
574154		**Wing Outboard Bellcrank Assembly Access Cover (612EB) - Removal / Installation**							RE (O/C)			
	57 A/F						Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-41-01-RI											
576015		**Aileron Panels - Removal / Installation**							RE (O/C)			
	57 A/F	Lower - Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-60-00-RI											
576016		**Aileron Panels - Removal / Installation**							RE (O/C)			
	57 A/F	Lower - Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-60-00-RI											
576017		**Aileron Panels - Removal / Installation**							RE (O/C)			
	57 A/F	Upper - Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-60-00-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
576018		**Aileron Panels - Removal / Installation**							RE (O/C)			
	57 A/F	Upper - Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-60-00-RI											
577013		**Upper Cove Panel - Removal / Installation**							RE (O/C)			
	57 A/F	Left No.1					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-70-00-RI											
577014		**Upper Cove Panel - Removal / Installation**							RE (O/C)			
	57 A/F	Right No.1					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-70-00-RI											
577015		**Upper Cove Panel - Removal / Installation**							RE (O/C)			
	57 A/F	Left No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-70-00-RI											
577016		**Upper Cove Panel - Removal / Installation**							RE (O/C)			
	57 A/F	Right No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-70-00-RI											
577017		**Upper Cove Panel - Removal / Installation**							RE (O/C)			
	57 A/F	Left No.3					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-70-00-RI											
577018		**Upper Cove Panel - Removal / Installation**							RE (O/C)			
	57 A/F	Right No.3					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-70-00-RI											
577019		**Lower Cove Panel - Removal / Installation**							RE (O/C)			
	57 A/F	Left No.1					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-70-00-RI											
577020		**Lower Cove Panel - Removal / Installation**							RE (O/C)			
	57 A/F	Right No.1					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-70-00-RI											
577021		**Lower Cove Panel - Removal / Installation**							RE (O/C)			
	57 A/F	Left No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-70-00-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
577022		**Lower Cove Panel - Removal / Installation**							RE (O/C)			
	57 A/F	Right No.2					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-70-00-RI											
577023		**Lower Cove Panel - Removal / Installation**							RE (O/C)			
	57 A/F	Left No.3					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-70-00-RI											
577024		**Lower Cove Panel - Removal / Installation**							RE (O/C)			
	57 A/F	Right No.3					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:57-70-00-RI											
710003		**Powerplant - Removal / Installation**							RE (O/C)			
	71 A/F	Left	1				Mos	10-Feb-2023				
	3030002-2						Hrs	24:24				
	P130647		1				Ldg	7				
	Mfg#:71-00-00											
710004		**Powerplant - Removal / Installation**							RE (O/C)			
	71 A/F	Right	1				Mos	10-Feb-2023				
	3030002-2						Hrs	24:24				
	P130648		1				Ldg	7				
	Mfg#:71-00-00											
711103		**Upper Cowl - Removal / Installation**							RE (O/C)			
	71 A/F	Left	10				Mos	20-Oct-2023				
	WBD7111E301-043		490:27				Hrs	490:27				
	PZ231		293				Ldg	293				
	Mfg#:71-11-01-RI											
711104		**Upper Cowl - Removal / Installation**							RE (O/C)			
	71 A/F	Right	10				Mos	20-Oct-2023				
	WBD7112E301-043		490:27				Hrs	490:27				
	PZ232		293				Ldg	293				
	Mfg#:71-11-01-RI											
711107		**Lower Cowl - Removal / Installation**							RE (O/C)			
	71 A/F	Left	10				Mos	20-Oct-2023				
	WBD7113E301-047		490:27				Hrs	490:27				
	PZ317		293				Ldg	293				
	Mfg#:71-11-02											
711108		**Lower Cowl - Removal / Installation**							RE (O/C)			
	71 A/F	Right	10				Mos	20-Oct-2023				
	WBD7114E301-047		490:27				Hrs	490:27				
	PZ316		293				Ldg	293				
	Mfg#:71-11-02											
711119		**Hook Latch - Removal / Installation**							RE (O/C)			
	71 A/F	Left Fwd					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-11-03											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
711120		**Hook Latch - Removal / Installation**							RE (O/C)			
	71 A/F	Right Fwd					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-11-03											
711121		**Hook Latch (Forward Mid) - Removal / Installation**							RE (O/C)			
	71 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-11-03											
711122		**Hook Latch (Forward Mid) - Removal / Installation**							RE (O/C)			
	71 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-11-03											
711123		**Hook Latch (Aft Mid) - Removal / Installation**							RE (O/C)			
	71 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-11-03											
711124		**Hook Latch (Aft Mid) - Removal / Installation**							RE (O/C)			
	71 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-11-03											
711125		**Hook Latch - Removal / Installation**							RE (O/C)			
	71 A/F	Left Aft					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-11-03											
711126		**Hook Latch - Removal / Installation**							RE (O/C)			
	71 A/F	Right Aft					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-11-03											
711135		**Hold Open Rod - Removal / Installation**							RE (O/C)			
	71 A/F	Left Fwd					Mos	20-Oct-2023				
	Unknown						Hrs	490:27				
	Unknown						Ldg	293				
	Mfg#:71-11-04											
711136		**Hold Open Rod - Removal / Installation**							RE (O/C)			
	71 A/F	Right Fwd					Mos	20-Oct-2023				
	Unknown						Hrs	490:27				
	Unknown						Ldg	293				
	Mfg#:71-11-04											
711137		**Hold Open Rod - Removal / Installation**							RE (O/C)			
	71 A/F	Left Aft					Mos	20-Oct-2023				
	Unknown						Hrs	490:27				
	Unknown						Ldg	293				
	Mfg#:71-11-04											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
711138		**Hold Open Rod - Removal / Installation**							RE (O/C)			
	71 A/F	Right Aft					Mos	20-Oct-2023				
	Unknown						Hrs	490:27				
	Unknown						Ldg	293				
	Mfg#:71-11-04											
711159		**Cowl Door Tie Rod - Removal / Installation**							RE (O/C)			
	71 A/F	Left Fwd					Mos	20-Oct-2023				
	Unknown						Hrs	490:27				
	Unknown						Ldg	293				
	Mfg#:71-11-05-RI											
711160		**Cowl Door Tie Rod - Removal / Installation**							RE (O/C)			
	71 A/F	Right Fwd					Mos	20-Oct-2023				
	Unknown						Hrs	490:27				
	Unknown						Ldg	293				
	Mfg#:71-11-05-RI											
711161		**Cowl Door Tie Rod (Forward Mid) - Removal / Installation**							RE (O/C)			
	71 A/F	Left					Mos	20-Oct-2023				
	Unknown						Hrs	490:27				
	Unknown						Ldg	293				
	Mfg#:71-11-05-RI											
711162		**Cowl Door Tie Rod (Forward Mid) - Removal / Installation**							RE (O/C)			
	71 A/F	Right					Mos	20-Oct-2023				
	Unknown						Hrs	490:27				
	Unknown						Ldg	293				
	Mfg#:71-11-05-RI											
711163		**Cowl Door Tie Rod (Aft Mid) - Removal / Installation**							RE (O/C)			
	71 A/F	Left					Mos	20-Oct-2023				
	Unknown						Hrs	490:27				
	Unknown						Ldg	293				
	Mfg#:71-11-05-RI											
711164		**Cowl Door Tie Rod (Aft Mid) - Removal / Installation**							RE (O/C)			
	71 A/F	Right					Mos	20-Oct-2023				
	Unknown						Hrs	490:27				
	Unknown						Ldg	293				
	Mfg#:71-11-05-RI											
711165		**Cowl Door Tie Rod - Removal / Installation**							RE (O/C)			
	71 A/F	Left Aft					Mos	20-Oct-2023				
	Unknown						Hrs	490:27				
	Unknown						Ldg	293				
	Mfg#:71-11-05-RI											
711166		**Cowl Door Tie Rod - Removal / Installation**							RE (O/C)			
	71 A/F	Right Aft					Mos	20-Oct-2023				
	Unknown						Hrs	490:27				
	Unknown						Ldg	293				
	Mfg#:71-11-05-RI											
711173		**ECU Access Panel - Removal / Installation**							RE (O/C)			
	71 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-11-06											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
711174		**ECU Access Panel - Removal / Installation**							RE (O/C)			
	71 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-11-06											
711177		**T2 Access Panel - Removal / Installation**							RE (O/C)			
	71 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-11-06											
711178		**T2 Access Panel - Removal / Installation**							RE (O/C)			
	71 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-11-06											
711181		**Air Turbine Starter (ATS) Access Panel - Removal / Installation**							RE (O/C)			
	71 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-11-06											
711182		**Air Turbine Starter (ATS) Access Panel - Removal / Installation**							RE (O/C)			
	71 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-11-06											
711185		**Monopole and Thermal Anti-ice (TAI) Access Panel - Removal / Installation**							RE (O/C)			
	71 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-11-06											
711186		**Monopole and Thermal Anti-ice (TAI) Access Panel - Removal / Installation**							RE (O/C)			
	71 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-11-06											
712103		**Yoke Assembly - Removal / Installation**							RE (O/C)			
	71 A/F	Left	0				Mos	20-Nov-2022				
	WBA7121E001-049	New	0				Hrs	0				
	SAM125901L		0				Ldg	0				
	Mfg#:71-21-03-RI											
712104		**Yoke Assembly - Removal / Installation**							RE (O/C)			
	71 A/F	Right	0				Mos	20-Nov-2022				
	WBA7121E001-050	New	0				Hrs	0				
	SAM126501R		0				Ldg	0				
	Mfg#:71-21-03-RI											
712109		**Link Assembly - Removal / Installation**							RE (O/C)			
	71 A/F	Upper - Left	0				Mos	20-Nov-2022				
	WBA7121E006-051	New	0				Hrs	0				
	SAM065403		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
712110		**Link Assembly - Removal / Installation**							RE (O/C)			
	71 A/F	Upper - Right	0				Mos	20-Nov-2022				
	WBA7121E006-051	New	0				Hrs	0				
	SAM065406		0				Ldg	0				
712111		**Link Assembly - Removal / Installation**							RE (O/C)			
	71 A/F	Lower - Left	0				Mos	20-Nov-2022				
	WBA7121E006-051	New	0				Hrs	0				
	SAM065404		0				Ldg	0				
712112		**Link Assembly - Removal / Installation**							RE (O/C)			
	71 A/F	Lower - Right	0				Mos	20-Nov-2022				
	WBA7121E006-051	New	0				Hrs	0				
	SAM065405		0				Ldg	0				
712117		**Upper Mount Assembly - Removal / Installation**							RE (O/C)			
	71 A/F	Left	2				Mos	30-Jan-2023				
	WBA7121E011-047		24:24				Hrs	24:24				
	SAM063401		7				Ldg	7				
	Mfg#:71-21-03-RI											
712118		**Upper Mount Assembly - Removal / Installation**							RE (O/C)			
	71 A/F	Right	2				Mos	26-Jan-2023				
	WBA7121E011-047		24:24				Hrs	24:24				
	SAM063303		7				Ldg	7				
	Mfg#:71-21-03-RI											
712121		**Lower Mount Assembly - Removal / Installation**							RE (O/C)			
	71 A/F	Left	2				Mos	30-Jan-2023				
	WBA7121E011-047		24:24				Hrs	24:24				
	SAM063402		7				Ldg	7				
	Mfg#:71-21-03-RI											
712122		**Lower Mount Assembly - Removal / Installation**							RE (O/C)			
	71 A/F	Right	2				Mos	26-Jan-2023				
	WBA7121E011-047		24:24				Hrs	24:24				
	SAM063403		7				Ldg	7				
	Mfg#:71-21-03-RI											
712127		**Mid Mount Assembly - Removal / Installation**							RE (O/C)			
	71 A/F	Left	2				Mos	30-Jan-2023				
	WBA7121E009-047		24:24				Hrs	24:24				
	SAM035912		7				Ldg	7				
	Mfg#:71-21-03-RI											
712128		**Mid Mount Assembly - Removal / Installation**							RE (O/C)			
	71 A/F	Right	2				Mos	26-Jan-2023				
	WBA7121E009-047		24:24				Hrs	24:24				
	SAM036001		7				Ldg	7				
	Mfg#:71-21-03-RI											
712133		**Forward Mount Shoulder Bolt - Removal / Installation**							RE (O/C)			
	71 A/F	Left	2				Mos	08-Feb-2023				
	WBA7121E014-109		24:24				Hrs	24:24				
	15580		7				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
712134		**Forward Mount Shoulder Bolt - Removal / Installation**							RE (O/C)			
71 A/F	WBA7121E014-109	Right	2				Mos	08-Feb-2023				
	15581		24:24				Hrs	24:24				
			7				Ldg	7				
712139		**Forward Mount Shoulder Bolt - Removal / Installation**							RE (O/C)			
71 A/F	WBA7121E015-111	Left	2				Mos	08-Feb-2023				
	15972		24:24				Hrs	24:24				
			7				Ldg	7				
712140		**Forward Mount Shoulder Bolt - Removal / Installation**							RE (O/C)			
71 A/F	WBA7121E015-111	Right	2				Mos	08-Feb-2023				
	15974		24:24				Hrs	24:24				
			7				Ldg	7				
712141		**Forward Mount Shoulder Bolt - Removal / Installation**							RE (O/C)			
71 A/F	WBA7121E015-111	Left	2				Mos	08-Feb-2023				
	15971		24:24				Hrs	24:24				
			7				Ldg	7				
712142		**Forward Mount Shoulder Bolt - Removal / Installation**							RE (O/C)			
71 A/F	WBA7121E015-111	Right	2				Mos	08-Feb-2023				
	15973		24:24				Hrs	24:24				
			7				Ldg	7				
712145		**Forward Mount Shoulder Bolt - Removal / Installation**							RE (O/C)			
71 A/F	WBA7121E016-107	Left New	0				Mos	20-Nov-2022				
	15646		0				Hrs	0				
			0				Ldg	0				
712146		**Forward Mount Shoulder Bolt - Removal / Installation**							RE (O/C)			
71 A/F	WBA7121E016-107	Right New	0				Mos	20-Nov-2022				
	15647		0				Hrs	0				
			0				Ldg	0				
712205		**Aft Strut - Removal / Installation**							RE (O/C)			
71 A/F	WBA7122E013-101	Upper - Left	2				Mos	08-Feb-2023				
	SAM046503		24:24				Hrs	24:24				
	Mfg#:71-22-03		7				Ldg	7				
712206		**Aft Strut - Removal / Installation**							RE (O/C)			
71 A/F	WBA7122E013-101	Upper - Right	2				Mos	08-Feb-2023				
	SAM046504		24:24				Hrs	24:24				
	Mfg#:71-22-03		7				Ldg	7				
712207		**Aft Strut - Removal / Installation**							RE (O/C)			
71 A/F	WBA7122E101-041	Lower - Left	2				Mos	08-Feb-2023				
	SAM046502		24:24				Hrs	24:24				
	Mfg#:71-22-03		7				Ldg	7				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
712208		**Aft Strut - Removal / Installation**							RE (O/C)			
	71 A/F	Lower - Right	2				Mos	08-Feb-2023				
	WBA7122E101-041		24:24				Hrs	24:24				
	SAM046505		7				Ldg	7				
	Mfg#:71-22-03											
712213		**Aft Mount Shoulder Bolt - Removal / Installation**							RE (O/C)			
	71 A/F	Upper - Left	2				Mos	08-Feb-2023				
	WBA7122E014-103		24:24				Hrs	24:24				
	15751		7				Ldg	7				
712214		**Aft Mount Shoulder Bolt - Removal / Installation**							RE (O/C)			
	71 A/F	Upper - Right	2				Mos	08-Feb-2023				
	WBA7122E014-103		24:24				Hrs	24:24				
	15753		7				Ldg	7				
712215		**Aft Mount Shoulder Bolt - Removal / Installation**							RE (O/C)			
	71 A/F	Lower - Left	2				Mos	08-Feb-2023				
	WBA7122E014-103		24:24				Hrs	24:24				
	15750		7				Ldg	7				
712216		**Aft Mount Shoulder Bolt - Removal / Installation**							RE (O/C)			
	71 A/F	Lower - Right	2				Mos	08-Feb-2023				
	WBA7122E014-103		24:24				Hrs	24:24				
	13752		7				Ldg	7				
715103		**Engine FADEC Electrical Harness - Removal / Installation**							RE (O/C)			
	71 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-51-01											
715104		**Engine FADEC Electrical Harness - Removal / Installation**							RE (O/C)			
	71 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-51-02											
715107		**Engine Generator and Power Cable Harness - Removal / Installation**							RE (O/C)			
	71 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-51-03											
715108		**Engine Generator and Power Cable Harness - Removal / Installation**							RE (O/C)			
	71 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-51-04											
715111		**Engine Zone 2 Fire Detection Harness - Removal / Installation**							RE (O/C)			
	71 A/F	Left	0				Mos	20-Nov-2022				
	WBA7151E014-055	New	0				Hrs	0				
	CN149085501		0				Ldg	0				
	Mfg#:71-51-05											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
715112		**Engine Zone 2 Fire Detection Harness - Removal / Installation**							RE (O/C)			
71 A/F		Right	0				Mos	20-Nov-2022				
	WBA7151E014-055	New	0				Hrs	0				
	CN149085001		0				Ldg	0				
	Mfg#:71-51-06											
715115		**Engine Pylon Fire Detection Harness - Removal / Installation**							RE (O/C)			
71 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-51-07											
715116		**Engine Pylon Fire Detection Harness - Removal / Installation**							RE (O/C)			
71 A/F		Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-51-08											
715119		**Engine Gearbox Fire Detection Harness - Removal / Installation**							RE (O/C)			
71 A/F		Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-51-09											
715120		**Engine Gearbox Fire Detection Harness - Removal / Installation**							RE (O/C)			
71 A/F		Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:71-51-10											
716103		**Inlet - Removal / Installation**							RE (O/C)			
71 A/F		Left	2				Mos	31-Jan-2023				
	WBD7160E101-047		24:24				Hrs	24:24				
	GAHWN221		7				Ldg	7				
	Mfg#:71-61-01											
716104		**Inlet - Removal / Installation**							RE (O/C)			
71 A/F		Right	2				Mos	26-Jan-2023				
	WBD7160E101-047		24:24				Hrs	24:24				
	PZ296		7				Ldg	7				
	Mfg#:71-61-01											
720005		**Towershaft Assembly**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3033197-1	New	0				Hrs	0				
	22-1034-38465		0				Enc	0				
720005		**Towershaft Assembly**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3033197-1	New	0				Hrs	0				
	22-1034-37643		0				Enc	0				
722102		**Fan Inlet Housing Assembly - Removal / Installation**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	70040173-2	New	0				Hrs	0				
	22-156138-00002		0				Enc	0				
	Mfg#:72-21-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
722102		**Fan Inlet Housing Assembly - Removal / Installation**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	70040173-2	New	0				Hrs	0				
	22-156138-00006		0				Enc	0				
	Mfg#:72-21-01											
723000		**Vortex Spoiler - Discard**							RE (O/C)	LMM 05-10-00 Airworthiness Limitations		
72 ENG1							Mos	26-Jan-2023				
	Unknown						Hrs	0				
	Unknown						Enc	0				
	ATA Ref:72-30-00, MRB Ref:72-30-00/05 (SOURCE: AS907-2-1G LMM (72-05-16))											
723000		**Vortex Spoiler - Discard**							RE (O/C)	LMM 05-10-00 Airworthiness Limitations		
72 ENG2							Mos	20-Jan-2023				
	Unknown						Hrs	0				
	Unknown						Enc	0				
	ATA Ref:72-30-00, MRB Ref:72-30-00/05 (SOURCE: AS907-2-1G LMM (72-05-16))											
723002		**Vortex Sleeve - Removal / Installation**							RE (O/C)	LMM 05-10-00 Airworthiness Limitations		
72 ENG1							Mos	26-Jan-2023				
	Unknown						Hrs	0				
	Unknown						Enc	0				
	ATA Ref:72-30-00, MRB Ref:72-30-00/05 (SOURCE: AS907-2-1G LMM (72-05-16))											
723002		**Vortex Sleeve - Removal / Installation**							RE (O/C)	LMM 05-10-00 Airworthiness Limitations		
72 ENG2							Mos	20-Jan-2023				
	Unknown						Hrs	0				
	Unknown						Enc	0				
	ATA Ref:72-30-00, MRB Ref:72-30-00/05 (SOURCE: AS907-2-1G LMM (72-05-16))											
723016		**Diffuser Case - Removal / Installation**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	70040463-1	New	0				Hrs	0				
	22-156138-01449		0				Enc	0				
723016		**Diffuser Case - Removal / Installation**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	70040463-1	New	0				Hrs	0				
	22-156138-02126		0				Enc	0				
723018		**Support Assembly, Stage 1**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3033175-3	New	0				Hrs	0				
	22-1034-39000		0				Enc	0				
723018		**Support Assembly, Stage 1**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3033175-3	New	0				Hrs	0				
	21-1034-32765		0				Enc	0				
723019		**Front Frame Assembly**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3030204-927	New	0				Hrs	0				
	LA103412		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
723019		**Front Frame Assembly**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3030204-927	New	0				Hrs	0				
	LA103413		0				Enc	0				
723020		**Support Assembly, IGV**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3030204-914	New	0				Hrs	0				
	LA103414		0				Enc	0				
723020		**Support Assembly, IGV**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3030204-914	New	0				Hrs	0				
	LA103415		0				Enc	0				
723021		**Support Assembly, IGV**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3033163-2	New	0				Hrs	0				
	22-109742-00617		0				Enc	0				
723021		**Support Assembly, IGV**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3033163-2	New	0				Hrs	0				
	22-109742-00618		0				Enc	0				
723022		**Bearing, Ball, Annular**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3033024-6	New	0				Hrs	0				
	22-162255-13265		0				Enc	0				
723022		**Bearing, Ball, Annular**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3033024-6	New	0				Hrs	0				
	22-162255-13270		0				Enc	0				
723023		**Accessory Gearbox Build Unit, Htf7350**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3030204-925	New	0				Hrs	0				
	LA103428		0				Enc	0				
723023		**Accessory Gearbox Build Unit, Htf7350**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3030204-925	New	0				Hrs	0				
	LA103429		0				Enc	0				
723024		**Accessory Gearbox Build Unit, Htf7000**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3036000-6	New	0				Hrs	0				
	23P41600		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
723024		**Accessory Gearbox Build Unit, Htf7000**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3036000-6	New	0				Hrs	0				
	23P41601		0				Enc	0				
723025		**Hp Module**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3030204-902	New	0				Hrs	0				
	LA103406		0				Enc	0				
723025		**Hp Module**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3030204-902	New	0				Hrs	0				
	LA103407		0				Enc	0				
723026		**Compressor Case**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	70041060-1	New	0				Hrs	0				
	22-150568-00491		0				Enc	0				
723026		**Compressor Case**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	70041060-1	New	0				Hrs	0				
	22-150568-00550		0				Enc	0				
723027		**Gas Turbine Engine Aircraft Front Frame**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	70040471-1	New	0				Hrs	0				
	15-162489-00136		0				Enc	0				
723027		**Gas Turbine Engine Aircraft Front Frame**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	70040471-1	New	0				Hrs	0				
	17-162489-00235		0				Enc	0				
723028		**Vane, Compressor Stator, Stage 2**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	70040972-3	New	0				Hrs	0				
	22-3300-07647		0				Enc	0				
723028		**Vane, Compressor Stator, Stage 2**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	70040972-3	New	0				Hrs	0				
	22-3300-07464		0				Enc	0				
723029		**Vane, Compressor Stator, Stage 3**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	70040973-3	New	0				Hrs	0				
	22-3300-06209		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
723029		**Vane, Compressor Stator, Stage 3**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	70040973-3	New	0				Hrs	0				
	22-3300-06366		0				Enc	0				
723030		**Vane, Compressor Stator, Stage 4**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	70040947-3	New	0				Hrs	0				
	22-3300-06457		0				Enc	0				
723030		**Vane, Compressor Stator, Stage 4**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	70040947-3	New	0				Hrs	0				
	22-3300-06511		0				Enc	0				
723031		**Ring Assembly Set, Unison**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3033142-2	New	0				Hrs	0				
	22-113332-00292		0				Enc	0				
723031		**Ring Assembly Set, Unison**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3033142-2	New	0				Hrs	0				
	22-113332-00258		0				Enc	0				
723032		**Carbon Ring Seal**							RE (O/C)			
72 ENG1		No.3	0				Mos	26-Jan-2023				
	3033180-3	New	0				Hrs	0				
	22-162255-12486		0				Enc	0				
723032		**Carbon Ring Seal**							RE (O/C)			
72 ENG2		No.3	0				Mos	20-Jan-2023				
	3033180-3	New	0				Hrs	0				
	22-162255-12466		0				Enc	0				
723033		**Carbon Ring Seal**							RE (O/C)			
72 ENG1		No.2	0				Mos	26-Jan-2023				
	3033189-1	New	0				Hrs	0				
	20-169020-03939		0				Enc	0				
723033		**Carbon Ring Seal**							RE (O/C)			
72 ENG2		No.2	0				Mos	20-Jan-2023				
	3033189-1	New	0				Hrs	0				
	20-169020-03890		0				Enc	0				
723034		**Carbon Ring Seal**							RE (O/C)			
72 ENG1		No.1	0				Mos	26-Jan-2023				
	3033189-1	New	0				Hrs	0				
	20-169020-03941		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
723034		**Carbon Ring Seal**							RE (O/C)			
72 ENG2		No.1	0				Mos	20-Jan-2023				
	3033189-1	New	0				Hrs	0				
	20-169020-03901		0				Enc	0				
723035		**Unison Ring Set, Assembly, Stage 1 (Matched)**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3033143-2	New	0				Hrs	0				
	22-113332-00267		0				Enc	0				
723035		**Unison Ring Set, Assembly, Stage 1 (Matched)**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3033143-2	New	0				Hrs	0				
	22-113332-00280		0				Enc	0				
723036		**Upper Bevel Gear Housing Assembly**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3033022-2	New	0				Hrs	0				
	22-162620-00093		0				Enc	0				
723036		**Upper Bevel Gear Housing Assembly**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3033022-2	New	0				Hrs	0				
	22-162620-00133		0				Enc	0				
723037		**Bearing Set**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3033023-2	New	0				Hrs	0				
	22-162111-06303		0				Enc	0				
723037		**Bearing Set**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3033023-2	New	0				Hrs	0				
	20-162111-07332		0				Enc	0				
723038		**Bearing Carbon Seal**							RE (O/C)			
72 ENG1		No.3	0				Mos	26-Jan-2023				
	3033035-1	New	0				Hrs	0				
	22-169020-02209		0				Enc	0				
723038		**Bearing Carbon Seal**							RE (O/C)			
72 ENG2		No.3	0				Mos	20-Jan-2023				
	3033035-1	New	0				Hrs	0				
	22-169020-02070		0				Enc	0				
723045		**Compressor Blisk Assembly - Stage 3**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3033108-8	New	0				Hrs	0				
	2218244940017		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
723045		**Compressor Blisk Assembly - Stage 3**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3033108-8	New	0				Hrs	0				
	2218244939587		0				Enc	0				
724001		**Combustion Chamber Case - Removal / Installation**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3034063-3	New	0				Hrs	0				
	22-3300-05896		0				Enc	0				
724001		**Combustion Chamber Case - Removal / Installation**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3034063-3	New	0				Hrs	0				
	22-3300-05390		0				Enc	0				
724004		**Ring - Cooling, Air, Blade, Swirl**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	70040476-3	New	0				Hrs	0				
	22-3300-06750		0				Enc	0				
724004		**Ring - Cooling, Air, Blade, Swirl**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	70040476-3	New	0				Hrs	0				
	22-3300-07137		0				Enc	0				
725101		**HP Turbine Rotor Asssembly (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	70040856-6	New	0				Hrs	0				
	2218244937936		0				Enc	0				
725101		**HP Turbine Rotor Asssembly (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	70040856-6	New	0				Hrs	0				
	2218244939926		0				Enc	0				
725102		**HP Turbine Rotor Asssembly (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3035135-7	New	0				Hrs	0				
	2218244940576		0				Enc	0				
725102		**HP Turbine Rotor Asssembly (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3035135-7	New	0				Hrs	0				
	2218244939337		0				Enc	0				
725110		**First Stage High Pressure Turbine Nozzle Assembly**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3030204-910	New	0				Hrs	0				
	LA103408		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725110		**First Stage High Pressure Turbine Nozzle Assembly**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3030204-910	New	0				Hrs	0				
	LA103409		0				Enc	0				
725111		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.1	0				Mos	26-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108271865		0				Enc	0				
725111		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.1	0				Mos	20-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108269940		0				Enc	0				
725112		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.2	0				Mos	26-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108271869		0				Enc	0				
725112		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.2	0				Mos	20-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108269942		0				Enc	0				
725113		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.3	0				Mos	26-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108271871		0				Enc	0				
725113		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.3	0				Mos	20-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108269949		0				Enc	0				
725114		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.4	0				Mos	26-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108271873		0				Enc	0				
725114		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.4	0				Mos	20-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108269952		0				Enc	0				
725115		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.5	0				Mos	26-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108271880		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725115		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.5	0				Mos	20-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108270219		0				Enc	0				
725116		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.6	0				Mos	26-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108271894		0				Enc	0				
725116		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.6	0				Mos	20-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108270224		0				Enc	0				
725117		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.7	0				Mos	26-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108272386		0				Enc	0				
725117		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.7	0				Mos	20-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108270230		0				Enc	0				
725118		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.8	0				Mos	26-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108272389		0				Enc	0				
725118		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.8	0				Mos	20-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108270231		0				Enc	0				
725119		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.9	0				Mos	26-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108272391		0				Enc	0				
725119		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.9	0				Mos	20-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108270241		0				Enc	0				
725120		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.10	0				Mos	26-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108272395		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725120		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.10	0				Mos	20-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108270244		0				Enc	0				
725121		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.11	0				Mos	26-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108272399		0				Enc	0				
725121		**HP Turbine Nozzle Segment (1st Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.11	0				Mos	20-Jan-2023				
	3035145-1	New	0				Hrs	0				
	22108270247		0				Enc	0				
725125		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.1	0				Mos	26-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108270100		0				Enc	0				
725125		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.1	0				Mos	20-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271560		0				Enc	0				
725126		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.2	0				Mos	26-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271572		0				Enc	0				
725126		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.2	0				Mos	20-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271568		0				Enc	0				
725127		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.3	0				Mos	26-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271574		0				Enc	0				
725127		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.3	0				Mos	20-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271582		0				Enc	0				
725128		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.4	0				Mos	26-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271599		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725128		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.4	0				Mos	20-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271596		0				Enc	0				
725129		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.5	0				Mos	26-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271607		0				Enc	0				
725129		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.5	0				Mos	20-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271600		0				Enc	0				
725130		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.6	0				Mos	26-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271612		0				Enc	0				
725130		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.6	0				Mos	20-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271601		0				Enc	0				
725131		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.7	0				Mos	26-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271614		0				Enc	0				
725131		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.7	0				Mos	20-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271602		0				Enc	0				
725132		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.8	0				Mos	26-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271619		0				Enc	0				
725132		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.8	0				Mos	20-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271603		0				Enc	0				
725133		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.9	0				Mos	26-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271621		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725133		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.9	0				Mos	20-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271604		0				Enc	0				
725134		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.10	0				Mos	26-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271625		0				Enc	0				
725134		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.10	0				Mos	20-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271609		0				Enc	0				
725135		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.11	0				Mos	26-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271687		0				Enc	0				
725135		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.11	0				Mos	20-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271610		0				Enc	0				
725136		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.12	0				Mos	26-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271739		0				Enc	0				
725136		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.12	0				Mos	20-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271681		0				Enc	0				
725137		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.13	0				Mos	26-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271942		0				Enc	0				
725137		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.13	0				Mos	20-Jan-2023				
	3035141-3	New	0				Hrs	0				
	22108271745		0				Enc	0				
725138		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG1		No.14	0				Mos	26-Jan-2023				
	3035141-4	New	0				Hrs	0				
	22108266292		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725138		**HP Turbine Nozzle Segment (2nd Stage) - Removal / Installation**							RE (O/C)			
72 ENG2		No.14	0				Mos	20-Jan-2023				
	3035141-4	New	0				Hrs	0				
	22108270941		0				Enc	0				
725140		**High Pressure Turbine Rotor Case**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	70041114-1	New	0				Hrs	0				
	22-3300-00305		0				Enc	0				
725140		**High Pressure Turbine Rotor Case**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	70041114-1	New	0				Hrs	0				
	22-3300-00301		0				Enc	0				
725141		**High Pressure Turbine Seal Plate Coupler (Stage 2)**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3035053-751	New	0				Hrs	0				
	22-1034-38356		0				Enc	0				
725141		**High Pressure Turbine Seal Plate Coupler (Stage 2)**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3035053-751	New	0				Hrs	0				
	22-1034-38363		0				Enc	0				
725150		**High Pressure Turbine (HPT) Case**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3035118-6	New	0				Hrs	0				
	22-182382-01061		0				Enc	0				
725150		**High Pressure Turbine (HPT) Case**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3035118-6	New	0				Hrs	0				
	22-182382-01065		0				Enc	0				
725151		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.1	0				Mos	26-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01252		0				Enc	0				
725151		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.1	0				Mos	20-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01360		0				Enc	0				
725152		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.2	0				Mos	26-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01256		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725152		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.2	0				Mos	20-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01361		0				Enc	0				
725153		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.3	0				Mos	26-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01257		0				Enc	0				
725153		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.3	0				Mos	20-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01367		0				Enc	0				
725154		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.4	0				Mos	26-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01268		0				Enc	0				
725154		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.4	0				Mos	20-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01381		0				Enc	0				
725155		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.5	0				Mos	26-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01269		0				Enc	0				
725155		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.5	0				Mos	20-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01570		0				Enc	0				
725156		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.6	0				Mos	26-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01276		0				Enc	0				
725156		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.6	0				Mos	20-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01572		0				Enc	0				
725157		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.7	0				Mos	26-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01284		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725157		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.7	0				Mos	20-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01575		0				Enc	0				
725158		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.8	0				Mos	26-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01345		0				Enc	0				
725158		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.8	0				Mos	20-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01624		0				Enc	0				
725159		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.9	0				Mos	26-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01349		0				Enc	0				
725159		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.9	0				Mos	20-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01626		0				Enc	0				
725160		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.10	0				Mos	26-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01351		0				Enc	0				
725160		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.10	0				Mos	20-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01634		0				Enc	0				
725161		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.11	0				Mos	26-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01430		0				Enc	0				
725161		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.11	0				Mos	20-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01635		0				Enc	0				
725162		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.12	0				Mos	26-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01436		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725162		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.12	0				Mos	20-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01636		0				Enc	0				
725163		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.13	0				Mos	26-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01437		0				Enc	0				
725163		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.13	0				Mos	20-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01661		0				Enc	0				
725164		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.14	0				Mos	26-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01439		0				Enc	0				
725164		**Second-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.14	0				Mos	20-Jan-2023				
	3035130-1	New	0				Hrs	0				
	22-120374-01851		0				Enc	0				
725165		**High Pressure Turbine (HPT) Seal Assembly (Stage 2)**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3035093-3	New	0				Hrs	0				
	2218244939806		0				Enc	0				
725165		**High Pressure Turbine (HPT) Seal Assembly (Stage 2)**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3035093-3	New	0				Hrs	0				
	2218244939807		0				Enc	0				
725171		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.1	0				Mos	26-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03223		0				Enc	0				
725171		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.1	0				Mos	20-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03262		0				Enc	0				
725172		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.2	0				Mos	26-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03400		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725172		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.2	0				Mos	20-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03266		0				Enc	0				
725173		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.3	0				Mos	26-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03418		0				Enc	0				
725173		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.3	0				Mos	20-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03279		0				Enc	0				
725174		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.4	0				Mos	26-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03419		0				Enc	0				
725174		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.4	0				Mos	20-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03289		0				Enc	0				
725175		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.5	0				Mos	26-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03422		0				Enc	0				
725175		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.5	0				Mos	20-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03290		0				Enc	0				
725176		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.6	0				Mos	26-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03427		0				Enc	0				
725176		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.6	0				Mos	20-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03291		0				Enc	0				
725177		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.7	0				Mos	26-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03436		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725177		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.7	0				Mos	20-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03310		0				Enc	0				
725178		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.8	0				Mos	26-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03456		0				Enc	0				
725178		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.8	0				Mos	20-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03328		0				Enc	0				
725179		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.9	0				Mos	26-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03459		0				Enc	0				
725179		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.9	0				Mos	20-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03338		0				Enc	0				
725180		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.10	0				Mos	26-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03462		0				Enc	0				
725180		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.10	0				Mos	20-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03340		0				Enc	0				
725181		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.11	0				Mos	26-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03467		0				Enc	0				
725181		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.11	0				Mos	20-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03362		0				Enc	0				
725182		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.12	0				Mos	26-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03472		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725182		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.12	0				Mos	20-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03368		0				Enc	0				
725183		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.13	0				Mos	26-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03473		0				Enc	0				
725183		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.13	0				Mos	20-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03377		0				Enc	0				
725184		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG1		No.14	0				Mos	26-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03496		0				Enc	0				
725184		**First-Stage High Pressure Turbine Shroud Segment**							RE (O/C)			
72 ENG2		No.14	0				Mos	20-Jan-2023				
	70041107-1	New	0				Hrs	0				
	22-162015-03386		0				Enc	0				
725185		**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG1		No.1	0				Mos	26-Jan-2023				
	3035145-1LC	New	0				Hrs	0				
	22108271865		0				Enc	0				
725185		**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG2		No.1					Mos	20-Jan-2023				
	Unknown						Hrs	0				
	Unknown						Enc	0				
725186		**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG1		No.2	0				Mos	26-Jan-2023				
	3035145-1LC	New	0				Hrs	0				
	22108271869		0				Enc	0				
725186		**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG2		No.2					Mos	20-Jan-2023				
	Unknown						Hrs	0				
	Unknown						Enc	0				
725187		**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG1		No.3	0				Mos	26-Jan-2023				
	3035145-1LC	New	0				Hrs	0				
	22108271871		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725187		**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG2		No.3					Mos	20-Jan-2023				
Unknown							Hrs	0				
Unknown							Enc	0				
725188		**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG1		No.4	0				Mos	26-Jan-2023				
3035145-1LC		New	0				Hrs	0				
22108271873			0				Enc	0				
725188		**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG2		No.4					Mos	20-Jan-2023				
Unknown							Hrs	0				
Unknown							Enc	0				
725189		**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG1		No.5	0				Mos	26-Jan-2023				
3035145-1LC		New	0				Hrs	0				
22108271880			0				Enc	0				
725189		**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG2		No.5					Mos	20-Jan-2023				
Unknown							Hrs	0				
Unknown							Enc	0				
725190		**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG1		No.6	0				Mos	26-Jan-2023				
3035145-1LC		New	0				Hrs	0				
22108271894			0				Enc	0				
725190		**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG2		No.6					Mos	20-Jan-2023				
Unknown							Hrs	0				
Unknown							Enc	0				
725191		**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG1		No.7	0				Mos	26-Jan-2023				
3035145-1LC		New	0				Hrs	0				
22108272386			0				Enc	0				
725191		**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG2		No.7					Mos	20-Jan-2023				
Unknown							Hrs	0				
Unknown							Enc	0				
725192		**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG1		No.8	0				Mos	26-Jan-2023				
3035145-1LC		New	0				Hrs	0				
22108272389			0				Enc	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725192	**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG2	No.8					Mos	20-Jan-2023				
Unknown						Hrs	0				
Unknown						Enc	0				
725193	**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG1	No.9	0				Mos	26-Jan-2023				
3035145-1LC	New	0				Hrs	0				
22108272391		0				Enc	0				
725193	**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG2	No.9					Mos	20-Jan-2023				
Unknown						Hrs	0				
Unknown						Enc	0				
725194	**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG1	No.10	0				Mos	26-Jan-2023				
3035145-1LC	New	0				Hrs	0				
22108272395		0				Enc	0				
725194	**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG2	No.10					Mos	20-Jan-2023				
Unknown						Hrs	0				
Unknown						Enc	0				
725195	**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG1	No.11	0				Mos	26-Jan-2023				
3035145-1LC	New	0				Hrs	0				
22108272399		0				Enc	0				
725195	**Nozzle-Meyer - Less Coating - Removal / Installation**							RE (O/C)			
72 ENG2	No.11					Mos	20-Jan-2023				
Unknown						Hrs	0				
Unknown						Enc	0				
725505	**LP Turbine Rotor Assembly (Stage 1) - Removal / Installation**							RE (O/C)			
72 ENG1		0				Mos	26-Jan-2023				
3035692-2	New	0				Hrs	0				
21-162246-05074		0				Enc	0				
725505	**LP Turbine Rotor Assembly (Stage 1) - Removal / Installation**							RE (O/C)			
72 ENG2		0				Mos	20-Jan-2023				
3035692-2	New	0				Hrs	0				
21-162246-05063		0				Enc	0				
725506	**LP Turbine Rotor Assembly (Stage 2) - Removal / Installation**							RE (O/C)			
72 ENG1		0				Mos	26-Jan-2023				
3035660-2	New	0				Hrs	0				
21-162246-04280		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725506		**LP Turbine Rotor Assembly (Stage 2) - Removal / Installation**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3035660-2	New	0				Hrs	0				
	21-162246-04600		0				Enc	0				
725507		**LP Turbine Rotor Assembly (Stage 3) - Removal / Installation**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3035662-3	New	0				Hrs	0				
	21-162246-03556		0				Enc	0				
725507		**LP Turbine Rotor Assembly (Stage 3) - Removal / Installation**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3035662-3	New	0				Hrs	0				
	21-162246-05266		0				Enc	0				
725511		**LP Turbine Nozzle (Stage 1) - Removal / Installation**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3035612-6	New	0				Hrs	0				
	23-182273-A0029		0				Enc	0				
725511		**LP Turbine Nozzle (Stage 1) - Removal / Installation**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3035612-6	New	0				Hrs	0				
	23-182273-A0027		0				Enc	0				
725512		**LP Turbine Nozzle (Stage 2) - Removal / Installation**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3035681-3	New	0				Hrs	0				
	NSN		0				Enc	0				
725512		**LP Turbine Nozzle (Stage 2) - Removal / Installation**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3035681-3	New	0				Hrs	0				
	NSN		0				Enc	0				
725513		**LP Turbine Nozzle (Stage 3) - Removal / Installation**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3035682-3	New	0				Hrs	0				
	NSN		0				Enc	0				
725513		**LP Turbine Nozzle (Stage 3) - Removal / Installation**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3035682-3	New	0				Hrs	0				
	NSN		0				Enc	0				
725514		**Low Pressure Turbine (LPT) Case**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3035695-4	New	0				Hrs	0				
	22-182273-A0933		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725514		**Low Pressure Turbine (LPT) Case**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3035695-4	New	0				Hrs	0				
	22-182273-A0820		0				Enc	0				
725515		**Low Pressure Turbine (LPT) (Stage 1) Nozzle Assembly**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3035708-1	New	0				Hrs	0				
	22-3300-05385		0				Enc	0				
725515		**Low Pressure Turbine (LPT) (Stage 1) Nozzle Assembly**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3035708-1	New	0				Hrs	0				
	22-3300-05492		0				Enc	0				
725516		**Low Pressure Turbine (LPT) Stub Shaft Roller Bearing (Outer Race)**							RE (O/C)			
72 ENG1	No.4		0				Mos	26-Jan-2023				
	3035647-7	New	0				Hrs	0				
	22-162111-07829		0				Enc	0				
725516		**Low Pressure Turbine (LPT) Stub Shaft Roller Bearing (Outer Race)**							RE (O/C)			
72 ENG2	No.4		0				Mos	20-Jan-2023				
	3035647-7	New	0				Hrs	0				
	22-162111-07833		0				Enc	0				
725517		**Bearing Carbon Seal**							RE (O/C)			
72 ENG1	No.4		0				Mos	26-Jan-2023				
	70041289-2	New	0				Hrs	0				
	22-169020-03740		0				Enc	0				
725517		**Bearing Carbon Seal**							RE (O/C)			
72 ENG2	No.4		0				Mos	20-Jan-2023				
	70041289-2	New	0				Hrs	0				
	22-169020-03726		0				Enc	0				
725518		**Low Pressure Turbine Module**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3030204-906	New	0				Hrs	0				
	LA103418		0				Enc	0				
725518		**Low Pressure Turbine Module**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3030204-906	New	0				Hrs	0				
	LA103419		0				Enc	0				
725519		**Nozzle, EGV Tube Assembly**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3035676-3	New	0				Hrs	0				
	22-156101-06181		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725519		**Nozzle, EGV Tube Assembly**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3035676-3	New	0				Hrs	0				
	22-156101-05868		0				Enc	0				
725520		**Nozzle, Exit Guide Vane**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3035677-2	New	0				Hrs	0				
	22-156101-06181		0				Enc	0				
725520		**Nozzle, Exit Guide Vane**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3035677-2	New	0				Hrs	0				
	22-156101-05868		0				Enc	0				
725521		**Seal, Stationary Inner**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3035659-2	New	0				Hrs	0				
	22-3300-05385		0				Enc	0				
725521		**Seal, Stationary Inner**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3035659-2	New	0				Hrs	0				
	22-3300-05492		0				Enc	0				
725522		**Centering Cage Roller Bearing (Outer Race)**							RE (O/C)			
72 ENG1		No.5	0				Mos	26-Jan-2023				
	3035683-5	New	0				Hrs	0				
	22-162111-08701		0				Enc	0				
725522		**Centering Cage Roller Bearing (Outer Race)**							RE (O/C)			
72 ENG2		No.5	0				Mos	20-Jan-2023				
	3035683-5	New	0				Hrs	0				
	22-162111-08693		0				Enc	0				
725523		**Carbon Seal Segmented**							RE (O/C)			
72 ENG1		No.5	0				Mos	26-Jan-2023				
	3035687-3	New	0				Hrs	0				
	22-169020-03649		0				Enc	0				
725523		**Carbon Seal Segmented**							RE (O/C)			
72 ENG2		No.5	0				Mos	20-Jan-2023				
	3035687-3	New	0				Hrs	0				
	22-169020-03678		0				Enc	0				
725524		**Bearing Housing**							RE (O/C)			
72 ENG1		No.5	0				Mos	26-Jan-2023				
	3035705-3	New	0				Hrs	0				
	22-150568-00109		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
725524		**Bearing Housing**							RE (O/C)			
72 ENG2		No.5	0				Mos	20-Jan-2023				
	3035705-3	New	0				Hrs	0				
	22-150568-00150		0				Enc	0				
726001		**Accessory Gearbox Assembly (AGB) - Removal / Installation**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3036004-2	New	0				Hrs	0				
	22-169019-05215		0				Enc	0				
726001		**Accessory Gearbox Assembly (AGB) - Removal / Installation**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3036004-2	New	0				Hrs	0				
	22-169019-05217		0				Enc	0				
726005		**Oil Tank Pressure Valve**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3038797-1	New	0				Hrs	0				
	22-150503-03136		0				Enc	0				
726005		**Oil Tank Pressure Valve**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3038797-1	New	0				Hrs	0				
	22-150503-03139		0				Enc	0				
727001		**Roller Bearing - Cylindrical Roller Bearing (Outer Race) - Removal / Installation**							RE (O/C)			
72 ENG1		No.2	0				Mos	26-Jan-2023				
	3037041-3	New	0				Hrs	0				
	22-162111-06686		0				Enc	0				
727001		**Roller Bearing - Cylindrical Roller Bearing (Outer Race) - Removal / Installation**							RE (O/C)			
72 ENG2		No.2	0				Mos	20-Jan-2023				
	3037041-3	New	0				Hrs	0				
	22-162111-06659		0				Enc	0				
727002		**Bearing Housing Assembly**							RE (O/C)			
72 ENG1		No.1	0				Mos	26-Jan-2023				
	70040457-1	New	0				Hrs	0				
	22-162111-06686		0				Enc	0				
727002		**Bearing Housing Assembly**							RE (O/C)			
72 ENG2		No.1	0				Mos	20-Jan-2023				
	70040457-1	New	0				Hrs	0				
	22-150568-00343		0				Enc	0				
727003		**Bearing Carbon Seal**							RE (O/C)			
72 ENG1		No.1	0				Mos	26-Jan-2023				
	3037037-3	New	0				Hrs	0				
	22-169020-00720		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
727003		**Bearing Carbon Seal**							RE (O/C)			
72 ENG2		No.1	0				Mos	20-Jan-2023				
	3037037-3	New	0				Hrs	0				
	22-169020-00734		0				Enc	0				
727004		**Bearing Housing Annular Ball Bearing**							RE (O/C)			
72 ENG1		No.1	0				Mos	26-Jan-2023				
	3037038-2	New	0				Hrs	0				
	22-162255-12064		0				Enc	0				
727004		**Bearing Housing Annular Ball Bearing**							RE (O/C)			
72 ENG2		No.1	0				Mos	20-Jan-2023				
	3037038-2	New	0				Hrs	0				
	22-162255-12939		0				Enc	0				
727010		**Bearing Housing**							RE (O/C)			
72 ENG1		No.1	0				Mos	26-Jan-2023				
	3037031-111	New	0				Hrs	0				
	NSN		0				Enc	0				
727010		**Bearing Housing**							RE (O/C)			
72 ENG2		No.1	0				Mos	20-Jan-2023				
	3037031-111	New	0				Hrs	0				
	NSN		0				Enc	0				
727070		**Trim Balance Weight**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3037065-1	New	0				Hrs	0				
	NSN		0				Enc	0				
727070		**Trim Balance Weight**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3037065-1	New	0				Hrs	0				
	NSN		0				Enc	0				
727111		**Fan Rotor Assembly - Removal / Installation**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	70041044-1	New	0				Hrs	0				
	2218244940372		0				Enc	0				
727111		**Fan Rotor Assembly - Removal / Installation**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	70041044-1	New	0				Hrs	0				
	2218244940509		0				Enc	0				
727112		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.1	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61086		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
727112		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.1	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	21-182297-05704		0				Enc	0				
727113		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.2	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61156		0				Enc	0				
727113		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.2	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61426		0				Enc	0				
727114		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.3	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61192		0				Enc	0				
727114		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.3	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61441		0				Enc	0				
727115		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.4	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61326		0				Enc	0				
727115		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.4	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61470		0				Enc	0				
727116		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.5	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61413		0				Enc	0				
727116		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.5	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61691		0				Enc	0				
727117		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.6	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61429		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
727117		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.6	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-05438		0				Enc	0				
727118		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.7	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61467		0				Enc	0				
727118		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.7	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-05498		0				Enc	0				
727119		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.8	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61612		0				Enc	0				
727119		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.8	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-05499		0				Enc	0				
727120		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.9	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61613		0				Enc	0				
727120		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.9	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-05541		0				Enc	0				
727121		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.10	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61654		0				Enc	0				
727121		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.10	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-05615		0				Enc	0				
727122		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.11	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61660		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
727122		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.11	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-05671		0				Enc	0				
727123		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.12	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61664		0				Enc	0				
727123		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.12	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-05800		0				Enc	0				
727124		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.13	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61667		0				Enc	0				
727124		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.13	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-05920		0				Enc	0				
727125		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.14	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61682		0				Enc	0				
727125		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.14	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-05933		0				Enc	0				
727126		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.15	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61688		0				Enc	0				
727126		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.15	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-06109		0				Enc	0				
727127		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.16	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61698		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
727127		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.16	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-06140		0				Enc	0				
727128		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.17	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-181958-61722		0				Enc	0				
727128		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.17	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-06141		0				Enc	0				
727129		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.18	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-05548		0				Enc	0				
727129		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.18	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-06168		0				Enc	0				
727130		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.19	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-05550		0				Enc	0				
727130		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.19	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-06202		0				Enc	0				
727131		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.20	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-06169		0				Enc	0				
727131		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.20	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-06207		0				Enc	0				
727132		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.21	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-06201		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
727132		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.21	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-06209		0				Enc	0				
727133		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG1		No.22	0				Mos	26-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-06662		0				Enc	0				
727133		**Fan Blade - Removal / Installation**							RE (O/C)			
72 ENG2		No.22	0				Mos	20-Jan-2023				
	70040466-2	New	0				Hrs	0				
	22-182297-06316		0				Enc	0				
729901		**Plenum Assy**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3030204-916	New	0				Hrs	0				
	22-3300-07570		0				Enc	0				
729901		**Plenum Assy**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3030204-916	New	0				Hrs	0				
	22-3300-07495		0				Enc	0				
729902		**Valve & Sleeve Assembly, Pressurizing (Matched)**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	2687693	New	0				Hrs	0				
	150529-3028		0				Enc	0				
729902		**Valve & Sleeve Assembly, Pressurizing (Matched)**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	2687693	New	0				Hrs	0				
	150529-3040		0				Enc	0				
729903		**Valve & Sleeve Assy Bypass (Matched)**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	2687957	New	0				Hrs	0				
	150529-2170		0				Enc	0				
729903		**Valve & Sleeve Assy Bypass (Matched)**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	2687957	New	0				Hrs	0				
	150529-2182		0				Enc	0				
729904		**Valve & Sleeve Assy Servo Regulator (Matched)**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	2688153	New	0				Hrs	0				
	150493-2726		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729904		**Valve & Sleeve Assy Servo Regulator (Matched)**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	2688153	New	0				Hrs	0				
	150493-2727		0				Enc	0				
729905		**Valve & Sleeve Assy (Matched)**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	2687127	New	0				Hrs	0				
	150529-2998		0				Enc	0				
729905		**Valve & Sleeve Assy (Matched)**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	2687127	New	0				Hrs	0				
	150529-2959		0				Enc	0				
729906		**Valve & Sleeve Assy Motive Flow (Matched)**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	2687205	New	0				Hrs	0				
	150529-2544		0				Enc	0				
729906		**Valve & Sleeve Assy Motive Flow (Matched)**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	2687205	New	0				Hrs	0				
	150529-2601		0				Enc	0				
729907		**Transformer Diff. Lin Var, Dual In-Line**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	2718896	New	0				Hrs	0				
	4563		0				Enc	0				
729907		**Transformer Diff. Lin Var, Dual In-Line**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	2718896	New	0				Hrs	0				
	4551		0				Enc	0				
729908		**Servo Valve Elhyd. One Stage. Two Way**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	2718901	New	0				Hrs	0				
	03846		0				Enc	0				
729908		**Servo Valve Elhyd. One Stage. Two Way**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	2718901	New	0				Hrs	0				
	03850		0				Enc	0				
729909		**Torque Motor Base Assembly**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	2685627	New	0				Hrs	0				
	150529-133730		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729909		**Torque Motor Base Assembly**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	2685627	New	0				Hrs	0				
	150529-133399		0				Enc	0				
729910		**Torque Motor Assembly, Servo Valve**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	2685759-005	New	0				Hrs	0				
	06848-133730		0				Enc	0				
729910		**Torque Motor Assembly, Servo Valve**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	2685759-005	New	0				Hrs	0				
	06848-133399		0				Enc	0				
729911		**Servo Valve, Elhyd, One Stage Three Way**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	2718972	New	0				Hrs	0				
	03886		0				Enc	0				
729911		**Servo Valve, Elhyd, One Stage Three Way**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	2718972	New	0				Hrs	0				
	03919		0				Enc	0				
729912		**Silicon Pressure Transducer, 20 Psia**							RE (O/C)			
72 ENG1		No.1	0				Mos	26-Jan-2023				
	4201680-1002	New	0				Hrs	0				
	82-A7079		0				Enc	0				
729912		**Silicon Pressure Transducer, 20 Psia**							RE (O/C)			
72 ENG2		No.1	0				Mos	20-Jan-2023				
	4201680-1002	New	0				Hrs	0				
	82-A7088		0				Enc	0				
729913		**Silicon Pressure Transducer, 20 Psia**							RE (O/C)			
72 ENG1		No.2	0				Mos	26-Jan-2023				
	4201680-1002	New	0				Hrs	0				
	82-A7084		0				Enc	0				
729913		**Silicon Pressure Transducer, 20 Psia**							RE (O/C)			
72 ENG2		No.2	0				Mos	20-Jan-2023				
	4201680-1002	New	0				Hrs	0				
	82-A7090		0				Enc	0				
729914		**Transducer**							RE (O/C)			
72 ENG1		No.1	0				Mos	26-Jan-2023				
	4201681-1	New	0				Hrs	0				
	82-A7053		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729914		**Transducer**							RE (O/C)			
72 ENG2	4201681-1	No.1 New	0				Mos	20-Jan-2023				
	82-A7061		0				Hrs	0				
			0				Enc	0				
729915		**Transducer**							RE (O/C)			
72 ENG1	4201681-1	No.2 New	0				Mos	26-Jan-2023				
	82-A7066		0				Hrs	0				
			0				Enc	0				
729915		**Transducer**							RE (O/C)			
72 ENG2	4201681-1	No.2 New	0				Mos	20-Jan-2023				
	82-A7054		0				Hrs	0				
			0				Enc	0				
729916		**Sensor Assembly, Silicon**							RE (O/C)			
72 ENG1	4201682-2004	No.1 New	0				Mos	26-Jan-2023				
	698248		0				Hrs	0				
			0				Enc	0				
729916		**Sensor Assembly, Silicon**							RE (O/C)			
72 ENG2	4201682-2004	No.1 New	0				Mos	20-Jan-2023				
	908109		0				Hrs	0				
			0				Enc	0				
729917		**Sensor Assembly, Silicon**							RE (O/C)			
72 ENG1	4201682-2004	No.2 New	0				Mos	26-Jan-2023				
	908048		0				Hrs	0				
			0				Enc	0				
729917		**Sensor Assembly, Silicon**							RE (O/C)			
72 ENG2	4201682-2004	No.2 New	0				Mos	20-Jan-2023				
	698263		0				Hrs	0				
			0				Enc	0				
729918		**CKT Card Assy**							RE (O/C)			
72 ENG1	4244697-2	No.1 New	0				Mos	26-Jan-2023				
	CMY9124-2241		0				Hrs	0				
			0				Enc	0				
729918		**CKT Card Assy**							RE (O/C)			
72 ENG2	4244697-2	No.1 New	0				Mos	20-Jan-2023				
	CMY9103-2241		0				Hrs	0				
			0				Enc	0				
729919		**CKT Card Assembly**							RE (O/C)			
72 ENG1	4244697-2	No.2 New	0				Mos	26-Jan-2023				
	CMY9127-2241		0				Hrs	0				
			0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729919		**CKT Card Assembly**							RE (O/C)			
72 ENG2		No.2	0				Mos	20-Jan-2023				
	4244697-2	New	0				Hrs	0				
	CMY9121-2241		0				Enc	0				
729920		**Sensor As900**							RE (O/C)			
72 ENG1		No.1	0				Mos	26-Jan-2023				
	4244822-2	New	0				Hrs	0				
	696073		0				Enc	0				
729920		**Sensor As900**							RE (O/C)			
72 ENG2		No.1	0				Mos	20-Jan-2023				
	4244822-2	New	0				Hrs	0				
	696553		0				Enc	0				
729921		**Sensor As900**							RE (O/C)			
72 ENG1		No.2	0				Mos	26-Jan-2023				
	4244822-2	New	0				Hrs	0				
	695964		0				Enc	0				
729921		**Sensor As900**							RE (O/C)			
72 ENG2		No.2	0				Mos	20-Jan-2023				
	4244822-2	New	0				Hrs	0				
	695959		0				Enc	0				
729922		**Servo Valve Elhyd, 2 Stage, 4 Way**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	442197-1	New	0				Hrs	0				
	ESVBD13450		0				Enc	0				
729922		**Servo Valve Elhyd, 2 Stage, 4 Way**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	442197-1	New	0				Hrs	0				
	ESVBD13457		0				Enc	0				
729923		**Body Assembly Servo Valve**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	2687749	New	0				Hrs	0				
	150529-3475		0				Enc	0				
729923		**Body Assembly Servo Valve**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	2687749	New	0				Hrs	0				
	150529-3488		0				Enc	0				
729924		**Circuit Card Assembly, Cpu, Power Supply**							RE (O/C)			
72 ENG1		No.1	0				Mos	26-Jan-2023				
	65052375-2	New	0				Hrs	0				
	CMY6898-2239		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729924		**Circuit Card Assembly, Cpu, Power Supply**							RE (O/C)			
72 ENG2		No.1	0				Mos	20-Jan-2023				
	65052375-2	New	0				Hrs	0				
	CMY4886-2238		0				Enc	0				
729925		**Circuit Card Assembly, Cpu, Power Supply**							RE (O/C)			
72 ENG1		No.2	0				Mos	26-Jan-2023				
	65052375-2	New	0				Hrs	0				
	CMY9973-2243		0				Enc	0				
729925		**Circuit Card Assembly, Cpu, Power Supply**							RE (O/C)			
72 ENG2		No.2	0				Mos	20-Jan-2023				
	65052375-2	New	0				Hrs	0				
	CMY4061-2143		0				Enc	0				
729926		**Solenoid Assembly**							RE (O/C)			
72 ENG1		No.1	0				Mos	26-Jan-2023				
	80000153-001	New	0				Hrs	0				
	2-103692-541		0				Enc	0				
729926		**Solenoid Assembly**							RE (O/C)			
72 ENG2		No.1	0				Mos	20-Jan-2023				
	80000153-001	New	0				Hrs	0				
	2-103692-496		0				Enc	0				
729927		**Fan Stator Vane Assembly**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3037108-3	New	0				Hrs	0				
	22P41472		0				Enc	0				
729927		**Fan Stator Vane Assembly**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3037108-3	New	0				Hrs	0				
	22P41365		0				Enc	0				
729928		**Rotor Outline, Pma**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	2713780-4	New	0				Hrs	0				
	3437		0				Enc	0				
729928		**Rotor Outline, Pma**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	2713780-4	New	0				Hrs	0				
	3434		0				Enc	0				
729929		**Forging Compressor Rotor (Stage 1)**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3900347-111	New	0				Hrs	0				
	2218244938573		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729929		**Forging Compressor Rotor (Stage 1)**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3900347-111	New	0				Hrs	0				
	2118244936482		0				Enc	0				
729930		**Forging Compressor Rotor (Stage 2)**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3900348-111	New	0				Hrs	0				
	2218244938258		0				Enc	0				
729930		**Forging Compressor Rotor (Stage 2)**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3900348-111	New	0				Hrs	0				
	2218244939459		0				Enc	0				
729931		**Forging Compressor Rotor (Stage 3)**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3900349-111	New	0				Hrs	0				
	2218244940009		0				Enc	0				
729931		**Forging Compressor Rotor (Stage 3)**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3900349-111	New	0				Hrs	0				
	2218244939587		0				Enc	0				
729932		**Forging Compressor Rotor (Stage 4)**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3900350-111	New	0				Hrs	0				
	2218244939522		0				Enc	0				
729932		**Forging Compressor Rotor (Stage 4)**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3900350-111	New	0				Hrs	0				
	2218244940075		0				Enc	0				
729933		**Impeller**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3900360-111	New	0				Hrs	0				
	2218244940218		0				Enc	0				
729933		**Impeller**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3900360-111	New	0				Hrs	0				
	21-162246-02182		0				Enc	0				
729934		**Forging Rotating Seal (Stage 2)**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3900311-111	New	0				Hrs	0				
	22-122065-00961		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729934		**Forging Rotating Seal (Stage 2)**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3900311-111	New	0				Hrs	0				
	22-122065-01058		0				Enc	0				
729935		**Forging Rotating Seal (Stage 3)**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3900312-111	New	0				Hrs	0				
	21-156113-26931		0				Enc	0				
729935		**Forging Rotating Seal (Stage 3)**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3900312-111	New	0				Hrs	0				
	21-156113-26889		0				Enc	0				
729936		**Forging Coupler Forward - Hpt**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3900319-111	New	0				Hrs	0				
	22-162246-02209		0				Enc	0				
729936		**Forging Coupler Forward - Hpt**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3900319-111	New	0				Hrs	0				
	22-162246-02249		0				Enc	0				
729937		**Forging Seal Plate - Hpt (Stage 1)**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3900298-113	New	0				Hrs	0				
	2218244940152		0				Enc	0				
729937		**Forging Seal Plate - Hpt (Stage 1)**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3900298-113	New	0				Hrs	0				
	2218244940137		0				Enc	0				
729938		**Forging, Disk, Turbine Rotor - HP Stage 1**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3900299-112	New	0				Hrs	0				
	2218244940576		0				Enc	0				
729938		**Forging, Disk, Turbine Rotor - HP Stage 1**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3900299-112	New	0				Hrs	0				
	2218244939337		0				Enc	0				
729939		**Main Body**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	82010899-001	New	0				Hrs	0				
	005101-OA4879		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729939		**Main Body**							RE (O/C)			
72 ENG2							Mos	20-Jan-2023				
Unknown							Hrs	0				
Unknown							Enc	0				
729940		**Turbine Axial Flow Wheel**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
361655-4		New	0				Hrs	0				
G100991			0				Enc	0				
729940		**Turbine Axial Flow Wheel**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
361655-4		New	0				Hrs	0				
G101006			0				Enc	0				
729941		**Fwd Fan Bypass Duct Assembly**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
3030205-902		New	0				Hrs	0				
LA103424			0				Enc	0				
729941		**Fwd Fan Bypass Duct Assembly**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
3030205-902		New	0				Hrs	0				
LA103425			0				Enc	0				
729942		**Flow Divider Valve & Sleeve Assy (Matched)**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
2688069		New	0				Hrs	0				
150592-2361			0				Enc	0				
729942		**Flow Divider Valve & Sleeve Assy (Matched)**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
2688069		New	0				Hrs	0				
150592-2362			0				Enc	0				
729943		**Flow Divider Body Assembly**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
2690213		New	0				Hrs	0				
005101-A2236			0				Enc	0				
729943		**Flow Divider Body Assembly**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
2690213		New	0				Hrs	0				
005101-A2205			0				Enc	0				
729944		**Cvg Actuator Housing Assembly**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
2687477		New	0				Hrs	0				
005101-A2167			0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729944		**Cvg Actuator Housing Assembly**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	2687477	New	0				Hrs	0				
	005101-A2225		0				Enc	0				
729945		**Transformer Diff. Lin Var, Dual-In-Line**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	2718897	New	0				Hrs	0				
	4324		0				Enc	0				
729945		**Transformer Diff. Lin Var, Dual-In-Line**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	2718897	New	0				Hrs	0				
	4526		0				Enc	0				
729946		**Forging, Rotating Seal**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3900331-111	New	0				Hrs	0				
	2218244939777		0				Enc	0				
729946		**Forging, Rotating Seal**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3900331-111	New	0				Hrs	0				
	2218244939974		0				Enc	0				
729947		**Forging, Lpt Drive Arm**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3900313-112	New	0				Hrs	0				
	2218244940704		0				Enc	0				
729947		**Forging, Lpt Drive Arm**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3900313-112	New	0				Hrs	0				
	2218244940707		0				Enc	0				
729948		**Nose Cone**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3030204-908	New	0				Hrs	0				
	22-1034-38565		0				Enc	0				
729948		**Nose Cone**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3030204-908	New	0				Hrs	0				
	22-1034-38569		0				Enc	0				
729949		**Aft Bearing Support**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3030204-918	New	0				Hrs	0				
	LA103420		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729949		**Aft Bearing Support**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3030204-918	New	0				Hrs	0				
	LA103421		0				Enc	0				
729950		**Hpt 1St/2Nd Stg Shrd & Noz Assy**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3030204-904	New	0				Hrs	0				
	23-3300-00149		0				Enc	0				
729950		**Hpt 1St/2Nd Stg Shrd & Noz Assy**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3030204-904	New	0				Hrs	0				
	23-3300-00148		0				Enc	0				
729951		**Compressor Case Assy**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3030204-912	New	0				Hrs	0				
	LA103410		0				Enc	0				
729951		**Compressor Case Assy**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3030204-912	New	0				Hrs	0				
	LA103411		0				Enc	0				
729952		**CKT Card Assy**							RE (O/C)			
72 ENG1		No.2	0				Mos	26-Jan-2023				
	4244697-1	New	0				Hrs	0				
	CMY8790-2241		0				Enc	0				
729952		**CKT Card Assy**							RE (O/C)			
72 ENG2		No.2	0				Mos	20-Jan-2023				
	4244697-1	New	0				Hrs	0				
	CMY8778-2241		0				Enc	0				
729953		**CKT Card Assy**							RE (O/C)			
72 ENG1		No.3	0				Mos	26-Jan-2023				
	4244697-1	New	0				Hrs	0				
	CMY8785-2241		0				Enc	0				
729953		**CKT Card Assy**							RE (O/C)			
72 ENG2		No.3	0				Mos	20-Jan-2023				
	4244697-1	New	0				Hrs	0				
	CMY8781-2241		0				Enc	0				
729954		**Valve And Sleeve Assy, Meter In G (Matched)**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	2691823	New	0				Hrs	0				
	150529-1340		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729954		**Valve And Sleeve Assy, Meter In G (Matched)**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	2691823	New	0				Hrs	0				
	150529-1343		0				Enc	0				
729955		**Core Assembly**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	2372677-1	New	0				Hrs	0				
	09222361		0				Enc	0				
729955		**Core Assembly**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	2372677-1	New	0				Hrs	0				
	09222358		0				Enc	0				
729956		**Armature Assembly**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	2684714-001	New	0				Hrs	0				
	150529-27148		0				Enc	0				
729956		**Armature Assembly**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	2684714-001	New	0				Hrs	0				
	150529-27110		0				Enc	0				
729957		**Sensor Assembly, Silicon**							RE (O/C)			
72 ENG1		No.1	0				Mos	26-Jan-2023				
	4201682-3101	New	0				Hrs	0				
	696073		0				Enc	0				
729957		**Sensor Assembly, Silicon**							RE (O/C)			
72 ENG2		No.1	0				Mos	20-Jan-2023				
	4201682-3101	New	0				Hrs	0				
	696553		0				Enc	0				
729958		**Sensor Assembly, Silicon**							RE (O/C)			
72 ENG1		No.2	0				Mos	26-Jan-2023				
	4201682-3101	New	0				Hrs	0				
	695964		0				Enc	0				
729958		**Sensor Assembly, Silicon**							RE (O/C)			
72 ENG2		No.2	0				Mos	20-Jan-2023				
	4201682-3101	New	0				Hrs	0				
	695959		0				Enc	0				
729961		**Circuit Card Assy, ECU EMI**							RE (O/C)			
72 ENG1		No.1	0				Mos	26-Jan-2023				
	4245012-2	New	0				Hrs	0				
	CMY6795-2239		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729961		**Circuit Card Assy, ECU EMI**							RE (O/C)			
72 ENG2		No.1	0				Mos	20-Jan-2023				
	4245012-2	New	0				Hrs	0				
	CMY6826-2239		0				Enc	0				
729962		**Circuit Card Assy, ECU EMI**							RE (O/C)			
72 ENG1		No.2	0				Mos	26-Jan-2023				
	4245012-2	New	0				Hrs	0				
	CMY1466-2223		0				Enc	0				
729962		**Circuit Card Assy, ECU EMI**							RE (O/C)			
72 ENG2		No.2	0				Mos	20-Jan-2023				
	4245012-2	New	0				Hrs	0				
	CMY1549-2244		0				Enc	0				
729963		**Circuit Card Assembly, Ecu I/O**							RE (O/C)			
72 ENG1		No.1	0				Mos	26-Jan-2023				
	4245273-2	New	0				Hrs	0				
	CMY6196-2239		0				Enc	0				
729963		**Circuit Card Assembly, Ecu I/O**							RE (O/C)			
72 ENG2		No.1	0				Mos	20-Jan-2023				
	4245273-2	New	0				Hrs	0				
	CMY9820-2242		0				Enc	0				
729964		**Circuit Card Assembly, Ecu I/O**							RE (O/C)			
72 ENG1		No.2	0				Mos	26-Jan-2023				
	4245273-2	New	0				Hrs	0				
	CMY6175-2239		0				Enc	0				
729964		**Circuit Card Assembly, Ecu I/O**							RE (O/C)			
72 ENG2		No.2	0				Mos	20-Jan-2023				
	4245273-2	New	0				Hrs	0				
	CMY6207-2239		0				Enc	0				
729965		**Main Body Assembly**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	82010898-001	New	0				Hrs	0				
	005101-OA4879		0				Enc	0				
729965		**Main Body Assembly**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	82010898-001	New	0				Hrs	0				
	005101-OA4948		0				Enc	0				
729966		**Forging Seal Plate - Hpt (Stage 2)**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3900300-113	New	0				Hrs	0				
	2218244939806		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
729966		**Forging Seal Plate - Hpt (Stage 2)**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3900300-113	New	0				Hrs	0				
	2218244939807		0				Enc	0				
729967		**Vortex Forging**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3900317-111	New	0				Hrs	0				
	22-162045-00319		0				Enc	0				
729967		**Vortex Forging**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3900317-111	New	0				Hrs	0				
	22-162045-00250		0				Enc	0				
729968		**Forging, Fan Disk**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3900284-114	New	0				Hrs	0				
	2218244940372		0				Enc	0				
729968		**Forging, Fan Disk**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3900284-114	New	0				Hrs	0				
	2218244940509		0				Enc	0				
729969		**Deswirl Assembly**							RE (O/C)			
72 ENG1			0				Mos	26-Jan-2023				
	3030204-930	New	0				Hrs	0				
	22-3300-07564		0				Enc	0				
729969		**Deswirl Assembly**							RE (O/C)			
72 ENG2			0				Mos	20-Jan-2023				
	3030204-930	New	0				Hrs	0				
	22-3300-07666		0				Enc	0				
731001		**Housing Assy Filter Module**							RE (O/C)			
73 ENG1			0				Mos	26-Jan-2023				
	2688742	New	0				Hrs	0				
	005101-X-153172		0				Enc	0				
731001		**Housing Assy Filter Module**							RE (O/C)			
73 ENG2			0				Mos	20-Jan-2023				
	2688742	New	0				Hrs	0				
	005101-X-153178		0				Enc	0				
731002		**Valve & Sleeve Assy Filter Bypass (Matched)**							RE (O/C)			
73 ENG1			0				Mos	26-Jan-2023				
	2687210	New	0				Hrs	0				
	150529-2677		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
731002		**Valve & Sleeve Assy Filter Bypass (Matched)**							RE (O/C)			
	73 ENG2		0				Mos	20-Jan-2023				
	2687210	New	0				Hrs	0				
	150529-2620		0				Enc	0				
731005		**Fuel Manifolds - Removal / Installation**							RE (O/C)			
	73 ENG1		0				Mos	26-Jan-2023				
	2372682-1	New	0				Hrs	0				
	NSN		0				Enc	0				
	(ACCESS: 73-10-01)											
731005		**Fuel Manifolds - Removal / Installation**							RE (O/C)			
	73 ENG2		0				Mos	20-Jan-2023				
	2372682-1	New	0				Hrs	0				
	NSN		0				Enc	0				
	(ACCESS: 73-10-01)											
731006		**Fuel Manifold - Removal / Installation**							RE (O/C)			
	73 ENG1	No.2	0				Mos	26-Jan-2023				
	2372683-1	New	0				Hrs	0				
	NSN		0				Enc	0				
731006		**Fuel Manifold - Removal / Installation**							RE (O/C)			
	73 ENG2	No.2	0				Mos	20-Jan-2023				
	2372683-1	New	0				Hrs	0				
	NSN		0				Enc	0				
731012		**Fuel Heater Oil Cooler - Removal / Installation**							RE (O/C)			
	73 ENG1		0				Mos	26-Jan-2023				
	160658-1	New	0				Hrs	0				
	3378		0				Enc	0				
731012		**Fuel Heater Oil Cooler - Removal / Installation**							RE (O/C)			
	73 ENG2		0				Mos	20-Jan-2023				
	160658-1	New	0				Hrs	0				
	3375		0				Enc	0				
731015		**W4 Branched Wiring Harness**							RE (O/C)			
	73 ENG1		0				Mos	26-Jan-2023				
	3034430-2	New	0				Hrs	0				
	22-162599-09037		0				Enc	0				
731015		**W4 Branched Wiring Harness**							RE (O/C)			
	73 ENG2		0				Mos	20-Jan-2023				
	3034430-2	New	0				Hrs	0				
	22-162599-08996		0				Enc	0				
731016		**Flow Divider**							RE (O/C)			
	73 ENG1		0				Mos	26-Jan-2023				
	442425	New	0				Hrs	0				
	FDAZ3292		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
731016		**Flow Divider**							RE (O/C)			
73 ENG2			0				Mos	20-Jan-2023				
442425		New	0				Hrs	0				
FDAZ3293			0				Enc	0				
731102		**Fuel Pump - Removal / Installation**							RE (O/C)			
73 ENG1			0				Mos	26-Jan-2023				
82011224-001		New	0				Hrs	0				
150329-1032			0				Enc	0				
731102		**Fuel Pump - Removal / Installation**							RE (O/C)			
73 ENG2			0				Mos	20-Jan-2023				
82011224-001		New	0				Hrs	0				
150329-1053			0				Enc	0				
732005		**Wiring Harness, Branched, W3**							RE (O/C)			
73 ENG1			0				Mos	26-Jan-2023				
3034431-2		New	0				Hrs	0				
22-162599-09385			0				Enc	0				
732005		**Wiring Harness, Branched, W3**							RE (O/C)			
73 ENG2			0				Mos	20-Jan-2023				
3034431-2		New	0				Hrs	0				
22-162599-09378			0				Enc	0				
732013		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
73 ENG1		No.1	0				Mos	26-Jan-2023				
70040941-1		New	0				Hrs	0				
AAF45051			0				Enc	0				
Mfg#:73-13-01-RI												
732013		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
73 ENG2		No.1	0				Mos	20-Jan-2023				
70040941-1		New	0				Hrs	0				
AAF52392			0				Enc	0				
Mfg#:73-13-01-RI												
732014		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
73 ENG1		No.2	0				Mos	26-Jan-2023				
70040941-1		New	0				Hrs	0				
AAF45052			0				Enc	0				
Mfg#:73-13-01-RI												
732014		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
73 ENG2		No.2	0				Mos	20-Jan-2023				
70040941-1		New	0				Hrs	0				
AAF52394			0				Enc	0				
Mfg#:73-13-01-RI												
732015		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
73 ENG1		No.3	0				Mos	26-Jan-2023				
70040941-1		New	0				Hrs	0				
AAF45054			0				Enc	0				
Mfg#:73-13-01-RI												

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
732015		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG2	No.3	0				Mos	20-Jan-2023				
	70040941-1	New	0				Hrs	0				
	AAF53830		0				Enc	0				
	Mfg#:73-13-01-RI											
732016		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG1	No.4	0				Mos	26-Jan-2023				
	70040941-1	New	0				Hrs	0				
	AAF45055		0				Enc	0				
	Mfg#:73-13-01-RI											
732016		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG2	No.4	0				Mos	20-Jan-2023				
	70040941-1	New	0				Hrs	0				
	AAF53832		0				Enc	0				
	Mfg#:73-13-01-RI											
732017		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG1	No.5	0				Mos	26-Jan-2023				
	70040941-1	New	0				Hrs	0				
	AAF45056		0				Enc	0				
	Mfg#:73-13-01-RI											
732017		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG2	No.5	0				Mos	20-Jan-2023				
	70040941-1	New	0				Hrs	0				
	AAF53833		0				Enc	0				
	Mfg#:73-13-01-RI											
732018		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG1	No.6	0				Mos	26-Jan-2023				
	70040941-1	New	0				Hrs	0				
	AAF45057		0				Enc	0				
	Mfg#:73-13-01-RI											
732018		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG2	No.6	0				Mos	20-Jan-2023				
	70040941-1	New	0				Hrs	0				
	AAF53834		0				Enc	0				
	Mfg#:73-13-01-RI											
732019		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG1	No.7	0				Mos	26-Jan-2023				
	70040941-1	New	0				Hrs	0				
	AAF45059		0				Enc	0				
	Mfg#:73-13-01-RI											
732019		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG2	No.7	0				Mos	20-Jan-2023				
	70040941-1	New	0				Hrs	0				
	AAF53835		0				Enc	0				
	Mfg#:73-13-01-RI											
732020		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG1	No.8	0				Mos	26-Jan-2023				
	70040941-1	New	0				Hrs	0				
	AAF45060		0				Enc	0				
	Mfg#:73-13-01-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
732020		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG2	No.8	0				Mos	20-Jan-2023				
	70040941-1	New	0				Hrs	0				
	AAF53836		0				Enc	0				
	Mfg#:73-13-01-RI											
732021		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG1	No.9	0				Mos	26-Jan-2023				
	70040941-1	New	0				Hrs	0				
	AAF45063		0				Enc	0				
	Mfg#:73-13-01-RI											
732021		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG2	No.9	0				Mos	20-Jan-2023				
	70040941-1	New	0				Hrs	0				
	AAF53838		0				Enc	0				
	Mfg#:73-13-01-RI											
732022		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG1	No.10	0				Mos	26-Jan-2023				
	70040941-1	New	0				Hrs	0				
	AAF45064		0				Enc	0				
	Mfg#:73-13-01-RI											
732022		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG2	No.10	0				Mos	20-Jan-2023				
	70040941-1	New	0				Hrs	0				
	AAF53839		0				Enc	0				
	Mfg#:73-13-01-RI											
732023		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG1	No.11	0				Mos	26-Jan-2023				
	70040941-1	New	0				Hrs	0				
	AAF45065		0				Enc	0				
	Mfg#:73-13-01-RI											
732023		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG2	No.11	0				Mos	20-Jan-2023				
	70040941-1	New	0				Hrs	0				
	AAF53840		0				Enc	0				
	Mfg#:73-13-01-RI											
732024		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG1	No.12	0				Mos	26-Jan-2023				
	70040941-1	New	0				Hrs	0				
	AAF51746		0				Enc	0				
	Mfg#:73-13-01-RI											
732024		**Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG2	No.12	0				Mos	20-Jan-2023				
	70040941-1	New	0				Hrs	0				
	AAF53842		0				Enc	0				
	Mfg#:73-13-01-RI											
732045		**Start Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG1	No.1	0				Mos	26-Jan-2023				
	3034073-1	New	0				Hrs	0				
	22-169016-02888		0				Enc	0				
	Mfg#:73-13-01-RI											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
732045		**Start Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG2	No.1	0				Mos	20-Jan-2023				
	3034073-1	New	0				Hrs	0				
	22-169016-02466		0				Enc	0				
	Mfg#:73-13-01-RI											
732046		**Start Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG1	No.2	0				Mos	26-Jan-2023				
	3034073-1	New	0				Hrs	0				
	22-169016-02891		0				Enc	0				
	Mfg#:73-13-01-RI											
732046		**Start Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG2	No.2	0				Mos	20-Jan-2023				
	3034073-1	New	0				Hrs	0				
	22-169016-02492		0				Enc	0				
	Mfg#:73-13-01-RI											
732047		**Start Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG1	No.3	0				Mos	26-Jan-2023				
	3034073-1	New	0				Hrs	0				
	22-169016-02892		0				Enc	0				
	Mfg#:73-13-01-RI											
732047		**Start Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG2	No.3	0				Mos	20-Jan-2023				
	3034073-1	New	0				Hrs	0				
	22-169016-02496		0				Enc	0				
	Mfg#:73-13-01-RI											
732048		**Start Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG1	No.4	0				Mos	26-Jan-2023				
	3034073-1	New	0				Hrs	0				
	22-169016-02893		0				Enc	0				
	Mfg#:73-13-01-RI											
732048		**Start Fuel Nozzle - Removal / Installation**							RE (O/C)			
	73 ENG2	No.4	0				Mos	20-Jan-2023				
	3034073-1	New	0				Hrs	0				
	22-169016-02499		0				Enc	0				
	Mfg#:73-13-01-RI											
732056		**Hydromechanical Unit (HMU) - Removal / Installation**							RE (O/C)			
	73 ENG1		0				Mos	26-Jan-2023				
	442661	New	0				Hrs	0				
	FHC3415		0				Enc	0				
	Mfg#:73-20-01											
732056		**Hydromechanical Unit (HMU) - Removal / Installation**							RE (O/C)			
	73 ENG2		0				Mos	20-Jan-2023				
	442661	New	0				Hrs	0				
	FHC3416		0				Enc	0				
	Mfg#:73-20-01											
732102		**Fuel Filter Assembly - Removal / Installation**							RE (O/C)			
	73 ENG1		0				Mos	26-Jan-2023				
	442322	New	0				Hrs	0				
	FMJ3288		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
732102		**Fuel Filter Assembly - Removal / Installation**							RE (O/C)			
73 ENG2			0				Mos	20-Jan-2023				
	442322	New	0				Hrs	0				
	FMJ3291		0				Enc	0				
732104		**Fuel Filter Element - Removal / Installation**							RE (O/C)			
73 ENG1			0				Mos	26-Jan-2023				
	2687159	New	0				Hrs	0				
	NSN		0				Enc	0				
	Mfg#:73-10-05											
732104		**Fuel Filter Element - Removal / Installation**							RE (O/C)			
73 ENG2			0				Mos	20-Jan-2023				
	2687159	New	0				Hrs	0				
	NSN		0				Enc	0				
	Mfg#:73-10-05											
733102		**Fuel Flow meter - Removal / Installation**							RE (O/C)			
73 ENG1			0				Mos	26-Jan-2023				
	3034257-1	New	0				Hrs	0				
	22-152330-00487		0				Enc	0				
	Mfg#:73-31-02											
733102		**Fuel Flow meter - Removal / Installation**							RE (O/C)			
73 ENG2			0				Mos	20-Jan-2023				
	3034257-1	New	0				Hrs	0				
	22-152330-00484		0				Enc	0				
	Mfg#:73-31-02											
733302		**Dual Function Fuel Switch - Removal / Installation**							RE (O/C)			
73 ENG1			0				Mos	26-Jan-2023				
	2718964	New	0				Hrs	0				
	3439		0				Enc	0				
733302		**Dual Function Fuel Switch - Removal / Installation**							RE (O/C)			
73 ENG2			0				Mos	20-Jan-2023				
	2718964	New	0				Hrs	0				
	3442		0				Enc	0				
739901		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.1	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M14765		0				Enc	0				
739901		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.1	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15811		0				Enc	0				
739902		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.2	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15193		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
739902		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.2	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15812		0				Enc	0				
739903		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.3	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15234		0				Enc	0				
739903		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.3	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15813		0				Enc	0				
739904		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.4	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15533		0				Enc	0				
739904		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.4	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15816		0				Enc	0				
739905		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.5	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15536		0				Enc	0				
739905		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.5	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15817		0				Enc	0				
739906		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.6	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15722		0				Enc	0				
739906		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.6	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15818		0				Enc	0				
739907		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.7	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15794		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
739907		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.7	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15819		0				Enc	0				
739908		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.8	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15800		0				Enc	0				
739908		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.8	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M21276		0				Enc	0				
739909		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.9	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15889		0				Enc	0				
739909		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.9	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M21277		0				Enc	0				
739910		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.10	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15890		0				Enc	0				
739910		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.10	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M21279		0				Enc	0				
739911		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.11	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15891		0				Enc	0				
739911		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.11	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M21281		0				Enc	0				
739912		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.12	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15892		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
739912		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.12	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M21288		0				Enc	0				
739913		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.13	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15893		0				Enc	0				
739913		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.13	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M23676		0				Enc	0				
739914		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.14	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15894		0				Enc	0				
739914		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.14	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M23679		0				Enc	0				
739915		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.15	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15895		0				Enc	0				
739915		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.15	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M23875		0				Enc	0				
739916		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.16	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15903		0				Enc	0				
739916		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.16	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M23879		0				Enc	0				
739917		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.17	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15920		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
739917		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.17	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M23880		0				Enc	0				
739918		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.18	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15942		0				Enc	0				
739918		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.18	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M23996		0				Enc	0				
739919		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.19	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M15973		0				Enc	0				
739919		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.19	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M23998		0				Enc	0				
739920		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.20	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M16117		0				Enc	0				
739920		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.20	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M33624		0				Enc	0				
739921		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.21	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M16180		0				Enc	0				
739921		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.21	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M33711		0				Enc	0				
739922		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.22	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M16199		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
739922		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.22	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M33712		0				Enc	0				
739923		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.23	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M16200		0				Enc	0				
739923		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.23	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	22M21338		0				Enc	0				
739924		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.24	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M16201		0				Enc	0				
739924		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.24	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	22M21339		0				Enc	0				
739925		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.25	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M16209		0				Enc	0				
739925		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.25	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	22M21344		0				Enc	0				
739926		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.26	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M16211		0				Enc	0				
739926		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.26	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	22M21600		0				Enc	0				
739927		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.27	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M16756		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
739927		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.27	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	22M21601		0				Enc	0				
739928		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.28	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M16757		0				Enc	0				
739928		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.28	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	22M22021		0				Enc	0				
739929		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.29	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M16758		0				Enc	0				
739929		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.29	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	22M22066		0				Enc	0				
739930		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.30	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M16760		0				Enc	0				
739930		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.30	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	22M22072		0				Enc	0				
739931		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.31	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M16762		0				Enc	0				
739931		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.31	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	22M22078		0				Enc	0				
739932		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.32	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M16763		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
739932		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.32	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	22M22535		0				Enc	0				
739933		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.33	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M16764		0				Enc	0				
739933		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.33	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	22M22555		0				Enc	0				
739934		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.34	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M16766		0				Enc	0				
739934		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.34	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	22M22560		0				Enc	0				
739935		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.35	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M16768		0				Enc	0				
739935		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.35	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	22M22563		0				Enc	0				
739936		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.36	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M31600		0				Enc	0				
739936		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.36	0				Mos	20-Jan-2023				
	3035114-112	New	0				Hrs	0				
	22M22594		0				Enc	0				
739937		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.37	0				Mos	26-Jan-2023				
	3035114-112	New	0				Hrs	0				
	21M34077		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
739937		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.37	0				Mos	20-Jan-2023				
3035114-112		New	0				Hrs	0				
22M22595			0				Enc	0				
739938		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG1		No.38	0				Mos	26-Jan-2023				
3035114-112		New	0				Hrs	0				
22M03260			0				Enc	0				
739938		**HP Turbine Rotor Blade Casting (Stage 1)**							RE (O/C)			
73 ENG2		No.38	0				Mos	20-Jan-2023				
3035114-112		New	0				Hrs	0				
22M22893			0				Enc	0				
741002		**Ignition Unit - Removal / Installation**							RE (O/C)			
74 ENG1			0				Mos	26-Jan-2023				
3038100-6		New	0				Hrs	0				
2216250400767			0				Enc	0				
Mfg#:74-10-01												
741002		**Ignition Unit - Removal / Installation**							RE (O/C)			
74 ENG2			0				Mos	20-Jan-2023				
3038100-6		New	0				Hrs	0				
2216250400769			0				Enc	0				
Mfg#:74-10-01												
742003		**Ignition Lead - Removal / Installation**							RE (O/C)			
74 ENG1		Lower - Left					Mos	26-Jan-2023				
Unknown							Hrs	0				
Unknown							Enc	0				
Mfg#:74-20-02-RI												
742003		**Ignition Lead - Removal / Installation**							RE (O/C)			
74 ENG2		Lower - Left					Mos	20-Jan-2023				
Unknown							Hrs	0				
Unknown							Enc	0				
Mfg#:74-20-02-RI												
742004		**Ignition Lead - Removal / Installation**							RE (O/C)			
74 ENG1		Lower - Right					Mos	26-Jan-2023				
Unknown							Hrs	0				
Unknown							Enc	0				
Mfg#:74-20-02-RI												
742004		**Ignition Lead - Removal / Installation**							RE (O/C)			
74 ENG2		Lower - Right					Mos	20-Jan-2023				
Unknown							Hrs	0				
Unknown							Enc	0				
Mfg#:74-20-02-RI												
742007		**Igniter Plug - Removal / Installation**							RE (O/C)			
74 ENG1		Lower - Left					Mos	26-Jan-2023				
Unknown							Hrs	0				
Unknown							Enc	0				
Mfg#:74-20-01-RI												

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
742007		**Igniter Plug - Removal / Installation**							RE (O/C)			
74 ENG2		Lower - Left					Mos	20-Jan-2023				
Unknown							Hrs	0				
Unknown							Enc	0				
Mfg#:74-20-01-RI												
742008		**Igniter Plug - Removal / Installation**							RE (O/C)			
74 ENG1		Lower - Right					Mos	26-Jan-2023				
Unknown							Hrs	0				
Unknown							Enc	0				
Mfg#:74-20-01-RI												
742008		**Igniter Plug - Removal / Installation**							RE (O/C)			
74 ENG2		Lower - Right					Mos	20-Jan-2023				
Unknown							Hrs	0				
Unknown							Enc	0				
Mfg#:74-20-01-RI												
753001		**Wiring Harness, Branched, W5**							RE (O/C)			
75 ENG1			0				Mos	26-Jan-2023				
3034427-3		New	0				Hrs	0				
22-162599-09090			0				Enc	0				
753001		**Wiring Harness, Branched, W5**							RE (O/C)			
75 ENG2			0				Mos	20-Jan-2023				
3034427-3		New	0				Hrs	0				
22-162599-09966			0				Enc	0				
753102		**Compressor Variable-Geometry Actuator - Removal / Installation**							RE (O/C)			
75 ENG1			0				Mos	26-Jan-2023				
442321		New	0				Hrs	0				
ACD3293			0				Enc	0				
Mfg#:75-31-01												
753102		**Compressor Variable-Geometry Actuator - Removal / Installation**							RE (O/C)			
75 ENG2			0				Mos	20-Jan-2023				
442321		New	0				Hrs	0				
ACD3302			0				Enc	0				
Mfg#:75-31-01												
753106		**Trim-Surge Bleed Valve (A) - Removal / Installation**							RE (O/C)			
75 ENG1							Mos	10-Feb-2023				
540-1798-4							Hrs					
3343							Enc					
Mfg#:75-31-03												
753106		**Trim-Surge Bleed Valve (A) - Removal / Installation**							RE (O/C)			
75 ENG2			0				Mos	20-Jan-2023				
540-1798-5		New	0				Hrs	0				
3334			0				Enc	0				
Mfg#:75-31-03												
753107		**Main-Surge Bleed Valve (B) - Removal / Installation**							RE (O/C)			
75 ENG1			0				Mos	26-Jan-2023				
540-1796-5		New	0				Hrs	0				
6787			0				Enc	0				
Mfg#:75-31-03												

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
753107		**Main-Surge Bleed Valve (B) - Removal / Installation**							RE (O/C)			
75 ENG2			0				Mos	20-Jan-2023				
	540-1796-5	New	0				Hrs	0				
	6795		0				Enc	0				
	Mfg#:75-31-03											
753108		**Main-Surge Bleed Valve (C) - Removal / Installation**							RE (O/C)			
75 ENG1			0				Mos	26-Jan-2023				
	540-1796-5	New	0				Hrs	0				
	6788		0				Enc	0				
	Mfg#:75-31-03											
753108		**Main-Surge Bleed Valve (C) - Removal / Installation**							RE (O/C)			
75 ENG2			0				Mos	20-Jan-2023				
	540-1796-5	New	0				Hrs	0				
	6798		0				Enc	0				
	Mfg#:75-31-03											
754002		**T2 Sensor - Removal / Installation**							RE (O/C)			
75 ENG1			0				Mos	26-Jan-2023				
	3038225-2	New	0				Hrs	0				
	2216901761896		0				Enc	0				
754002		**T2 Sensor - Removal / Installation**							RE (O/C)			
75 ENG2			0				Mos	20-Jan-2023				
	3038225-2	New	0				Hrs	0				
	2216901761904		0				Enc	0				
754005		**Wiring Harness, Branched, W6**							RE (O/C)			
75 ENG1			0				Mos	26-Jan-2023				
	3034432-3	New	0				Hrs	0				
	22-162599-09213		0				Enc	0				
754005		**Wiring Harness, Branched, W6**							RE (O/C)			
75 ENG2			0				Mos	20-Jan-2023				
	3034432-3	New	0				Hrs	0				
	22-162599-09129		0				Enc	0				
761001		**Pma Stator Assembly**							RE (O/C)			
76 ENG1			0				Mos	26-Jan-2023				
	3038504-3	New	0				Hrs	0				
	3313		0				Enc	0				
761001		**Pma Stator Assembly**							RE (O/C)			
76 ENG2			0				Mos	20-Jan-2023				
	3038504-3	New	0				Hrs	0				
	3316		0				Enc	0				
761002		**Pma Rotor**							RE (O/C)			
76 ENG1			0				Mos	26-Jan-2023				
	3038506-3	New	0				Hrs	0				
	3437		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
761002		**Pma Rotor**							RE (O/C)			
	76 ENG2		0				Mos	20-Jan-2023				
	3038506-3	New	0				Hrs	0				
	3434		0				Enc	0				
761002		**Throttle Quadrant Assembly - Removal / Installation**							RE (O/C)			
	76 A/F		0				Mos	20-Nov-2022				
	4260-0051-5	New	0				Hrs	0				
	273157		0				Ldg	0				
	Mfg#:76-10-01-RI											
761003		**Alternator Outline**							RE (O/C)			
	76 ENG1		0				Mos	26-Jan-2023				
	2713779-3	New	0				Hrs	0				
	3313		0				Enc	0				
761003		**Alternator Outline**							RE (O/C)			
	76 ENG2		0				Mos	20-Jan-2023				
	2713779-3	New	0				Hrs	0				
	3316		0				Enc	0				
761005		**Electronic Control Unit (ECU) (Dual Channel - Channel A) - Removal / Installation**							RE (O/C)			
	76 ENG1		0				Mos	26-Jan-2023				
	2119576-3202	New	0				Hrs	0				
	102-AK0710		0				Enc	0				
	Mfg#:76-10-02-RI											
761005		**Electronic Control Unit (ECU) (Dual Channel - Channel A) - Removal / Installation**							RE (O/C)			
	76 ENG2		0				Mos	20-Jan-2023				
	2119576-3202	New	0				Hrs	0				
	102-AK0709		0				Enc	0				
	Mfg#:76-10-02-RI											
761006		**Electronic Control Unit (ECU) (Dual Channel - Channel B) - Removal / Installation**							RE (O/C)			
	76 ENG1		0				Mos	26-Jan-2023				
	2119576-3202	New	0				Hrs	0				
	102-AK0713		0				Enc	0				
	Mfg#:76-10-02-RI											
761006		**Electronic Control Unit (ECU) (Dual Channel - Channel B) - Removal / Installation**							RE (O/C)			
	76 ENG2		0				Mos	20-Jan-2023				
	2119576-3202	New	0				Hrs	0				
	102-AK0715		0				Enc	0				
	Mfg#:76-10-02-RI											
771002		**N1 Speed Sensor Monopole - Removal / Installation**							RE (O/C)			
	77 ENG1		0				Mos	26-Jan-2023				
	3038500-2	New	0				Hrs	0				
	22-134436-03792		0				Enc	0				
	Mfg#:77-10-01											
771002		**N1 Speed Sensor Monopole - Removal / Installation**							RE (O/C)			
	77 ENG2		0				Mos	20-Jan-2023				
	3038500-2	New	0				Hrs	0				
	22-134436-03796		0				Enc	0				
	Mfg#:77-10-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
771004		**N1 Compensator - Removal / Installation**							RE (O/C)			
77 ENG1	3060735-5						Mos	10-Feb-2023				
	1616909400673						Hrs					
	Mfg#:77-10-02						Enc					
771004		**N1 Compensator - Removal / Installation**							RE (O/C)			
77 ENG2	3060735-5	New	0				Mos	20-Jan-2023				
	1616909400410		0				Hrs	0				
	Mfg#:77-10-02		0				Enc	0				
771006		**N2 Speed Sensor - Removal / Installation**							RE (O/C)			
77 ENG1	3038501-2	New	0				Mos	26-Jan-2023				
	2213443609062		0				Hrs	0				
	Mfg#:77-10-03		0				Enc	0				
771006		**N2 Speed Sensor - Removal / Installation**							RE (O/C)			
77 ENG2	3038501-2	New	0				Mos	20-Jan-2023				
	2213443609060		0				Hrs	0				
	Mfg#:77-10-03		0				Enc	0				
772005		**EGT Probe Assembly - Removal / Installation**							RE (O/C)			
77 ENG1	3038509-2	Left New	0				Mos	26-Jan-2023				
	2315027700103		0				Hrs	0				
	Mfg#:77-20-01		0				Enc	0				
772005		**EGT Probe Assembly - Removal / Installation**							RE (O/C)			
77 ENG2	3038509-2	Left New	0				Mos	20-Jan-2023				
	2315027700115		0				Hrs	0				
	Mfg#:77-20-01		0				Enc	0				
772006		**EGT Probe Assembly - Removal / Installation**							RE (O/C)			
77 ENG1	3038509-2	Right New	0				Mos	26-Jan-2023				
	2315027700105		0				Hrs	0				
	Mfg#:77-20-01		0				Enc	0				
772006		**EGT Probe Assembly - Removal / Installation**							RE (O/C)			
77 ENG2	3038509-2	Right New	0				Mos	20-Jan-2023				
	2315027700123		0				Hrs	0				
	Mfg#:77-20-01		0				Enc	0				
773002		**Vibration Sensor Transducer - Removal / Installation**							RE (O/C)			
77 ENG1	3038503-2	New	0				Mos	26-Jan-2023				
	2216328723380		0				Hrs	0				
	Mfg#:77-30-01		0				Enc	0				
773002		**Vibration Sensor Transducer - Removal / Installation**							RE (O/C)			
77 ENG2	3038503-2	New	0				Mos	20-Jan-2023				
	2216328723370		0				Hrs	0				
	Mfg#:77-30-01		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
781103		**Mixer Nozzle - Removal / Installation**							RE (O/C)			
	78 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:78-11-01											
781104		**Mixer Nozzle - Removal / Installation**							RE (O/C)			
	78 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:78-11-01											
781107		**Center Body and Core Plug Cover - Removal / Installation**							RE (O/C)			
	78 A/F	Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:78-11-02											
781108		**Center Body and Core Plug Cover - Removal / Installation**							RE (O/C)			
	78 A/F	Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Mfg#:78-11-02											
783001		**Switch, Thrust Reverser**							RE (O/C)			
	78 ENG1		0				Mos	26-Jan-2023				
	70041063-1	New	0				Hrs	0				
	00900		0				Enc	0				
783001		**Switch, Thrust Reverser**							RE (O/C)			
	78 ENG2		0				Mos	20-Jan-2023				
	70041063-1	New	0				Hrs	0				
	00930		0				Enc	0				
783103		**Thrust Reverser - Removal / Installation**							RE (O/C)			
	78 A/F	Left	2				Mos	08-Feb-2023				
	31A512-04-0G		24:24				Hrs	24:24				
	TR543		7				Ldg	7				
	Mfg#:78-30-00-RI											
783104		**Thrust Reverser - Removal / Installation**							RE (O/C)			
	78 A/F	Right	2				Mos	09-Feb-2023				
	31A513-04-0G		24:24				Hrs	24:24				
	TR542		7				Ldg	7				
	Mfg#:78-30-00-RI											
783107		**Upper Pivot Door - Removal / Installation**							RE (O/C)			
	78 A/F	Left	0				Mos	20-Nov-2022				
	31E617-04-6U	New	0				Hrs	0				
	1791405		0				Ldg	0				
	Mfg#:78-31-01											
783108		**Upper Pivot Door - Removal / Installation**							RE (O/C)			
	78 A/F	Right	0				Mos	20-Nov-2022				
	31E618-05-6U	New	0				Hrs	0				
	1790634		0				Ldg	0				
	Mfg#:78-31-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
783111		**Lower Pivot Door - Removal / Installation**							RE (O/C)			
78 A/F		Left	0				Mos	20-Nov-2022				
	31E603-05-6U	New	0				Hrs	0				
	1791404		0				Ldg	0				
	Mfg#:78-31-01											
783112		**Lower Pivot Door - Removal / Installation**							RE (O/C)			
78 A/F		Right	0				Mos	20-Nov-2022				
	31E603-05-6U	New	0				Hrs	0				
	1790633		0				Ldg	0				
	Mfg#:78-31-01											
783303		**Isolation Control Unit - Removal / Installation**							RE (O/C)			
78 A/F		Left	0				Mos	20-Nov-2022				
	P518A0001-00	New	0				Hrs	0				
	22673802		0				Ldg	0				
	Mfg#:78-33-01											
783304		**Isolation Control Unit - Removal / Installation**							RE (O/C)			
78 A/F		Right	0				Mos	20-Nov-2022				
	P518A0001-00	New	0				Hrs	0				
	22563635		0				Ldg	0				
	Mfg#:78-33-01											
783307		**Thrust Reverser Directional Control Unit - Removal / Installation**							RE (O/C)			
78 A/F		Left	0				Mos	20-Nov-2022				
	P519A0001-01	New	0				Hrs	0				
	22922114		0				Ldg	0				
	Mfg#:78-33-02											
783308		**Thrust Reverser Directional Control Unit - Removal / Installation**							RE (O/C)			
78 A/F		Right	0				Mos	20-Nov-2022				
	P519A0001-01	New	0				Hrs	0				
	22937371		0				Ldg	0				
	Mfg#:78-33-02											
783315		**Pivot Door Actuator - Removal / Installation**							RE (O/C)			
78 A/F		Upper - Left	0				Mos	20-Nov-2022				
	P517A0001-05	New	0				Hrs	0				
	22976240		0				Ldg	0				
	Mfg#:78-32-02											
783316		**Pivot Door Actuator - Removal / Installation**							RE (O/C)			
78 A/F		Upper - Right	0				Mos	20-Nov-2022				
	P517A0001-05	New	0				Hrs	0				
	22972854		0				Ldg	0				
	Mfg#:78-32-02											
783317		**Pivot Door Actuator - Removal / Installation**							RE (O/C)			
78 A/F		Lower - Left	0				Mos	20-Nov-2022				
	P517A0001-05	New	0				Hrs	0				
	22976257		0				Ldg	0				
	Mfg#:78-32-02											
783318		**Pivot Door Actuator - Removal / Installation**							RE (O/C)			
78 A/F		Lower - Right	0				Mos	20-Nov-2022				
	P517A0001-05	New	0				Hrs	0				
	22972855		0				Ldg	0				
	Mfg#:78-32-02											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
783323		**Thrust Reverser Hydraulic Primary Lock - Removal / Installation**							RE (O/C)			
78 A/F		Left	0				Mos	20-Nov-2022				
	P520A0001-00	New	0				Hrs	0				
	22954063		0				Ldg	0				
	Mfg#:78-32-05-RI											
783324		**Thrust Reverser Hydraulic Primary Lock - Removal / Installation**							RE (O/C)			
78 A/F		Right	0				Mos	20-Nov-2022				
	P520A0001-00	New	0				Hrs	0				
	22954062		0				Ldg	0				
	Mfg#:78-32-05-RI											
783327		**Thrust Reverser Electro-Hydraulic Primary Lock - Removal / Installation**							RE (O/C)			
78 A/F		Left	0				Mos	20-Nov-2022				
	P521A0001-01	New	0				Hrs	0				
	22946328		0				Ldg	0				
	Mfg#:78-32-06											
783328		**Thrust Reverser Electro-Hydraulic Primary Lock - Removal / Installation**							RE (O/C)			
78 A/F		Right	0				Mos	20-Nov-2022				
	P521A0001-01	New	0				Hrs	0				
	22946322		0				Ldg	0				
	Mfg#:78-32-06											
783405		**Thrust-Reverser Door Deploy Switch - Removal / Installation**							RE (O/C)			
78 A/F		Upper - Left	0				Mos	20-Nov-2022				
	83-990-140	New	0				Hrs	0				
	06444		0				Ldg	0				
783406		**Thrust-Reverser Door Deploy Switch - Removal / Installation**							RE (O/C)			
78 A/F		Upper - Right	0				Mos	20-Nov-2022				
	83-990-140	New	0				Hrs	0				
	06442		0				Ldg	0				
783407		**Thrust-Reverser Door Deploy Switch - Removal / Installation**							RE (O/C)			
78 A/F		Lower - Left	0				Mos	20-Nov-2022				
	83-990-140	New	0				Hrs	0				
	06445		0				Ldg	0				
783408		**Thrust-Reverser Door Deploy Switch - Removal / Installation**							RE (O/C)			
78 A/F		Lower - Right	0				Mos	20-Nov-2022				
	83-990-140	New	0				Hrs	0				
	06443		0				Ldg	0				
783419		**Thrust Reverser Door Stow Switch - Removal / Installation**							RE (O/C)			
78 A/F		Upper - Left Outboard	0				Mos	20-Nov-2022				
	83-990-168	New	0				Hrs	0				
	30550		0				Ldg	0				
783420		**Thrust Reverser Door Stow Switch - Removal / Installation**							RE (O/C)			
78 A/F		Upper - Right Outboard	0				Mos	20-Nov-2022				
	83-990-168	New	0				Hrs	0				
	30554		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
783421		**Thrust Reverser Door Stow Switch - Removal / Installation**							RE (O/C)			
78 A/F	83-990-168	Upper - Left Inboard New	0 0				Mos Hrs	20-Nov-2022 0				
	30551		0				Ldg	0				
783422		**Thrust Reverser Door Stow Switch - Removal / Installation**							RE (O/C)			
78 A/F	83-990-168	Upper - Right Inboard New	0 0				Mos Hrs	20-Nov-2022 0				
	30555		0				Ldg	0				
783423		**Thrust Reverser Door Stow Switch - Removal / Installation**							RE (O/C)			
78 A/F	83-990-168	Lower - Left Outboard New	0 0				Mos Hrs	20-Nov-2022 0				
	30552		0				Ldg	0				
783424		**Thrust Reverser Door Stow Switch - Removal / Installation**							RE (O/C)			
78 A/F	83-990-168	Lower - Right Outboard New	0 0				Mos Hrs	20-Nov-2022 0				
	30556		0				Ldg	0				
783425		**Thrust Reverser Door Stow Switch - Removal / Installation**							RE (O/C)			
78 A/F	83-990-168	Lower - Left Inboard New	0 0				Mos Hrs	20-Nov-2022 0				
	30553		0				Ldg	0				
783426		**Thrust Reverser Door Stow Switch - Removal / Installation**							RE (O/C)			
78 A/F	83-990-168	Upper - Right Inboard New	0 0				Mos Hrs	20-Nov-2022 0				
	30557		0				Ldg	0				
783437		**Thrust Reverser Harness (Multiplexer to Direction Control Unit and Upper Deploy Switches) - Removal / Installation**							RE (O/C)			
78 A/F	Unknown	Upper - Left					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Mfg#:78-34-03-RI						Ldg	0				
783438		**Thrust Reverser Harness (Multiplexer to Direction Control Unit and Upper Deploy Switches) - Removal / Installation**							RE (O/C)			
78 A/F	Unknown	Upper - Right					Mos	20-Nov-2022				
	Unknown						Hrs	0				
	Mfg#:78-34-03-RI						Ldg	0				
783447		**Thrust Reverser Multiplexer Harness - Removal / Installation**							RE (O/C)			
78 A/F	13W007-04-0U	Left New	0 0				Mos Hrs	20-Nov-2022 0				
	02959		0				Ldg	0				
783448		**Thrust Reverser Multiplexer Harness - Removal / Installation**							RE (O/C)			
78 A/F	13W007-04-0U	Right New	0 0				Mos Hrs	20-Nov-2022 0				
	02958		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
792001		**Valve De-Oil**							RE (O/C)			
79 ENG1	3038779-3	Fwd / New	0				Mos	26-Jan-2023				
	22-150503-03276		0				Hrs	0				
			0				Enc	0				
792001		**Valve De-Oil**							RE (O/C)			
79 ENG2	3038779-3	Fwd / New	0				Mos	20-Jan-2023				
	22-150503-03343		0				Hrs	0				
			0				Enc	0				
792102		**Oil Pump - Removal / Installation**							RE (O/C)			
79 ENG1	3038704-6	New	0				Mos	26-Jan-2023				
	22-162407-00601		0				Hrs	0				
	Mfg#:79-21-01		0				Enc	0				
792102		**Oil Pump - Removal / Installation**							RE (O/C)			
79 ENG2	3038704-6	New	0				Mos	20-Jan-2023				
	22-162407-00603		0				Hrs	0				
	Mfg#:79-21-01		0				Enc	0				
792104		**Oil Filter - Removal / Installation**							RE (O/C)			
79 ENG1	3038727-3	New	0				Mos	26-Jan-2023				
	22-162287-03389		0				Hrs	0				
	Mfg#:79-21-02-RI		0				Enc	0				
792104		**Oil Filter - Removal / Installation**							RE (O/C)			
79 ENG2	3038727-3	New	0				Mos	20-Jan-2023				
	22-162287-03390		0				Hrs	0				
	Mfg#:79-21-02-RI		0				Enc	0				
792108		**Chip Detector - Removal / Installation**							RE (O/C)			
79 ENG1	3038706-3	New	0				Mos	26-Jan-2023				
	2216238100212		0				Hrs	0				
	Mfg#:79-21-03		0				Enc	0				
792108		**Chip Detector - Removal / Installation**							RE (O/C)			
79 ENG2	3038706-3	New	0				Mos	20-Jan-2023				
	2216238100218		0				Hrs	0				
	Mfg#:79-21-03		0				Enc	0				
793001		**Sensor, Remote Oil Level**							RE (O/C)			
79 ENG1	793GA0001-1	New	0				Mos	26-Jan-2023				
	0715		0				Hrs	0				
			0				Enc	0				
793001		**Sensor, Remote Oil Level**							RE (O/C)			
79 ENG2	793GA0001-1	New	0				Mos	20-Jan-2023				
	0714		0				Hrs	0				
			0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
793202		**Oil Temperature Transducer - Removal / Installation**							RE (O/C)			
79 ENG1			0				Mos	26-Jan-2023				
	3038701-1	New	0				Hrs	0				
	2216901727734		0				Enc	0				
	Mfg#:79-32-01											
793202		**Oil Temperature Transducer - Removal / Installation**							RE (O/C)			
79 ENG2			0				Mos	20-Jan-2023				
	3038701-1	New	0				Hrs	0				
	2216901727641		0				Enc	0				
	Mfg#:79-32-01											
793302		**Oil Pressure Transducer - Removal / Installation**							RE (O/C)			
79 ENG1			0				Mos	26-Jan-2023				
	3038700-3	New	0				Hrs	0				
	2216206700233		0				Enc	0				
	Mfg#:79-33-01											
793302		**Oil Pressure Transducer - Removal / Installation**							RE (O/C)			
79 ENG2			0				Mos	20-Jan-2023				
	3038700-3	New	0				Hrs	0				
	2216206700193		0				Enc	0				
	Mfg#:79-33-01											
801103		**Air Turbine Starter - Removal / Installation**							RE (O/C)			
80 A/F		Left	0				Mos	20-Nov-2022				
	3506000-5	New	0				Hrs	0				
	2688		0				Ldg	0				
	Mfg#:80-11-01											
801104		**Air Turbine Starter - Removal / Installation**							RE (O/C)			
80 A/F		Right	0				Mos	20-Nov-2022				
	3506000-5	New	0				Hrs	0				
	2684		0				Ldg	0				
	Mfg#:80-11-01											
801107		**Starter Control Valve - Removal / Installation**							RE (O/C)			
80 A/F		Left	0				Mos	20-Nov-2022				
	3215772-3	New	0				Hrs	0				
	3424		0				Ldg	0				
	Mfg#:80-11-02											
801108		**Starter Control Valve - Removal / Installation**							RE (O/C)			
80 A/F		Right	0				Mos	20-Nov-2022				
	3215772-3	New	0				Hrs	0				
	3422		0				Ldg	0				
	Mfg#:80-11-02											
801111		**Air Turbine Starter Duct - Removal / Installation**							RE (O/C)			
80 A/F		Left	2				Mos	08-Feb-2023				
	WBA8010G131-001		24:24				Hrs	24:24				
	NSN		7				Ldg	7				
	Mfg#:80-11-03											
801112		**Air Turbine Starter Duct - Removal / Installation**							RE (O/C)			
80 A/F		Right	2				Mos	08-Feb-2023				
	WBA8010G131-001		24:24				Hrs	24:24				
	NSN		7				Ldg	7				
	Mfg#:80-11-03											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 1. RE See Note											
324109		**Main Wheel Assembly - Special Detailed Inspection (NDT)**						RE (See Note)	05-20-00 Scheduled Maintenance Checks		
	32 A/F					Mos					
						Hrs					
		ATA Ref:32-41-01, MRB Ref:32-49-00-01 (SOURCE: G280 AMM) (NOTE: Accomplish at next opportunity defined by Inspection and Restoration Schedule for ABS Main and Nose Wheels table after the date of Revision 16. See List of Revisions.)				Ldg					
324110		**Main Wheel Assembly - Special Detailed Inspection (NDT)**						RE (See Note)	05-20-00 Scheduled Maintenance Checks		
	32 A/F					Mos					
						Hrs					
		ATA Ref:32-41-01, MRB Ref:32-49-00/01 (SOURCE: G280 AMM) (NOTE: Accomplish at next opportunity defined by Inspection and Restoration Schedule for ABS Main and Nose Wheels table after the date of Revision 16. See List of Revisions.)				Ldg					
324111		**Main Wheel Assembly - Special Detailed Inspection (NDT)**						RE (See Note)	05-20-00 Scheduled Maintenance Checks		
	32 A/F					Mos					
						Hrs					
		ATA Ref:32-41-01, MRB Ref:32-49-00/01 (SOURCE: G280 AMM) (NOTE: Accomplish at next opportunity defined by Inspection and Restoration Schedule for ABS Main and Nose Wheels table after the date of Revision 16. See List of Revisions.)				Ldg					
324112		**Main Wheel Assembly - Special Detailed Inspection (NDT)**						RE (See Note)	05-20-00 Scheduled Maintenance Checks		
	32 A/F					Mos					
						Hrs					
		ATA Ref:32-41-01, MRB Ref:32-49-00/01 (SOURCE: G280 AMM) (NOTE: Accomplish at next opportunity defined by Inspection and Restoration Schedule for ABS Main and Nose Wheels table after the date of Revision 16. See List of Revisions.)				Ldg					
324113		**Main Wheel Assembly - Overhaul**						RE (See Note)	05-10-00 Time Limits, 05-20-00 Scheduled Maintenance Checks		
	32 A/F					Mos					
						Hrs					
		ATA Ref:32-41-01, MRB Ref:32-49-00-06 (SOURCE: G280 AMM) (NOTE: In accordance with Gulfstream G280, Chapter 5, 05-20-00, Inspection and Restoration Schedule for ABS Main and Nose Wheels table.)				Ldg					
324114		**Main Wheel Assembly - Overhaul**						RE (See Note)	05-10-00 Time Limits, 05-20-00 Scheduled Maintenance Checks		
	32 A/F					Mos					
						Hrs					
		ATA Ref:32-41-01, MRB Ref:32-49-00-06 (SOURCE: G280 AMM) (NOTE: In accordance with Gulfstream G280, Chapter 5, 05-20-00, Inspection and Restoration Schedule for ABS Main and Nose Wheels table.)				Ldg					
324115		**Main Wheel Assembly - Overhaul**						RE (See Note)	05-10-00 Time Limits, 05-20-00 Scheduled Maintenance Checks		
	32 A/F					Mos					
						Hrs					
		ATA Ref:32-41-01, MRB Ref:32-49-00-06 (SOURCE: G280 AMM) (NOTE: In accordance with Gulfstream G280, Chapter 5, 05-20-00, Inspection and Restoration Schedule for ABS Main and Nose Wheels table.)				Ldg					
324116		**Main Wheel Assembly - Overhaul**						RE (See Note)	05-10-00 Time Limits, 05-20-00 Scheduled Maintenance Checks		
	32 A/F					Mos					
						Hrs					
		ATA Ref:32-41-01, MRB Ref:32-49-00-06 (SOURCE: G280 AMM) (NOTE: In accordance with Gulfstream G280, Chapter 5, 05-20-00, Inspection and Restoration Schedule for ABS Main and Nose Wheels table.)				Ldg					
324205		**Nose Wheel Assembly - Special Detailed Inspection (NDT)**						RE (See Note)	05-20-00 Scheduled Maintenance Checks		
	32 A/F					Mos	12-Jul-2023				
						Hrs	290:13				
		ATA Ref:32-42-01, MRB Ref:32-49-00-02 (SOURCE: G280 AMM) (NOTE: Accomplish at next opportunity defined by Inspection and Restoration Schedule for ABS Main and Nose Wheels table after the date of Revision 16. See List of Revisions.)				Ldg	170				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
324206		**Nose Wheel Assembly - Special Detailed Inspection (NDT)**							RE (See Note)	05-20-00 Scheduled Maintenance Checks		
	32 A/F						Mos	12-Jul-2023				
							Hrs	290:13				
		ATA Ref:32-42-01, MRB Ref:32-49-00-02 (SOURCE: G280 AMM) (NOTE: Accomplish at next opportunity defined by Inspection and Restoration Schedule for ABS Main and Nose Wheels table after the date of Revision 16. See List of Revisions.)					Ldg	170				
324207		**Nose Wheel Assembly - Overhaul**							RE (See Note)	05-10-00 Time Limits, 05-20-00 Scheduled Maintenance Checks		
	32 A/F						Mos	12-Jul-2023				
							Hrs	290:13				
		ATA Ref:32-41-01, MRB Ref:32-49-00-07 (SOURCE: G280 AMM) (NOTE: In accordance with Gulfstream G280, Chapter 5, 05-20-00, Inspection and Restoration Schedule for ABS Main and Nose Wheels table. Refer to Inspection and Restoration Schedule for ABS Main and Nose Wheels table for restore requirements. Wheels not tracking tire change or landing intervals must accomplish all inspection and restoration requirements at each tire change.)					Ldg	170				
324208		**Nose Wheel Assembly - Overhaul**							RE (See Note)	05-10-00 Time Limits, 05-20-00 Scheduled Maintenance Checks		
	32 A/F						Mos	12-Jul-2023				
							Hrs	290:13				
		ATA Ref:32-41-01, MRB Ref:32-49-00-07 (SOURCE: G280 AMM) (NOTE: In accordance with Gulfstream G280, Chapter 5, 05-20-00, Inspection and Restoration Schedule for ABS Main and Nose Wheels table. Refer to Inspection and Restoration Schedule for ABS Main and Nose Wheels table for restore requirements. Wheels not tracking tire change or landing intervals must accomplish all inspection and restoration requirements at each tire change.)					Ldg	170				
324313		**Brake Rotors and Stators - Detailed Inspection**							RE (See Note)	05-20-00 Scheduled Maintenance Checks		
	32 A/F						Mos					
							Hrs					
		ATA Ref:32-43-00, MRB Ref:32-49-00/03 (SOURCE: G280 AMM) (NOTE: Perform at wheel removal.)					Ldg					
324314		**Brake Rotors and Stators - Detailed Inspection**							RE (See Note)	05-20-00 Scheduled Maintenance Checks		
	32 A/F						Mos					
							Hrs					
		ATA Ref:32-43-00, MRB Ref:32-49-00/03 (SOURCE: G280 AMM) (NOTE: Perform at wheel removal.)					Ldg					
324315		**Brake Rotors and Stators - Detailed Inspection**							RE (See Note)	05-20-00 Scheduled Maintenance Checks		
	32 A/F						Mos					
							Hrs					
		ATA Ref:32-43-00, MRB Ref:32-49-00/03 (SOURCE: G280 AMM) (NOTE: Perform at wheel removal.)					Ldg					
324316		**Brake Rotors and Stators - Detailed Inspection**							RE (See Note)	05-20-00 Scheduled Maintenance Checks		
	32 A/F						Mos					
							Hrs					
		ATA Ref:32-43-00, MRB Ref:32-49-00/03 (SOURCE: G280 AMM) (NOTE: Perform at wheel removal.)					Ldg					
551111		**Horizontal Stabilizer Attach Points to Vertical Stabilizer (Horizontal Stabilizer Removed) - Detailed Inspection**							RE (See Note)	05-20-00 Scheduled Maintenance Checks		
	55 A/F						Mos					
							Hrs					
		ATA Ref:55-11-01, MRB Ref:55.02.00/08 (SOURCE: G280 AMM) (NOTE: Perform at horizontal stabilizer removal.)					Ldg					
551126		**Horizontal Stabilizer Actuator Lower Structural Fitting and Shafts - Detailed Inspection**							RE (See Note)	05-20-00 Scheduled Maintenance Checks		
	55 A/F						Mos					
							Hrs					
		ATA Ref:55-11-02, MRB Ref:55.02.01/02 (SOURCE: G280 AMM) (NOTE: Perform at horizontal stabilizer trim actuator removal.)					Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
551128	**Horizontal Stabilizer Actuator Upper Structural Attachment and Fittings - Detailed Inspection**							RE (See Note)	05-20-00 Scheduled Maintenance Checks		
55 A/F						Mos					
						Hrs					
	ATA Ref:55-11-02, MRB Ref:55.02.01/04 (SOURCE: G280 AMM) (NOTE: Perform at horizontal stabilizer removal.)					Ldg					
552101	**Elevator Hinge Points (Elevator Removed) (Left)- Detailed Inspection**							RE (See Note)	05-20-00 Scheduled Maintenance Checks		
55 A/F						Mos					
						Hrs					
	ATA Ref:55-21-01, MRB Ref:55.02.00/09 (SOURCE: G280 AMM) (NOTE: Perform at elevator removal.)					Ldg					
552102	**Elevator Hinge Points (Elevator Removed) (Right) - Detailed Inspection**							RE (See Note)	05-20-00 Scheduled Maintenance Checks		
55 A/F						Mos					
						Hrs					
	ATA Ref:55-21-01, MRB Ref:55.02.00/09 (SOURCE: G280 AMM) (NOTE: Perform at elevator removal.)					Ldg					
553101	**Vertical Stabilizer Attach Points (Vertical Stabilizer Removed) - Detailed Inspection**							RE (See Note)	05-20-00 Scheduled Maintenance Checks		
55 A/F						Mos					
						Hrs					
	ATA Ref:55-31-01, MRB Ref:55.02.00/07 (SOURCE: G280 AMM) (NOTE: Perform at vertical stabilizer removal.)					Ldg					
554101	**Rudder Hinge Points (Rudder Removed) - Detailed Inspection**							RE (See Note)	05-20-00 Scheduled Maintenance Checks		
55 A/F						Mos					
						Hrs					
	ATA Ref:55-41-01, MRB Ref:55.02.00/10 (SOURCE: G280 AMM) (NOTE: Perform at rudder removal.)					Ldg					
575105	**Main Landing Gear Support Bushings and Bearings (Visible Portions) (Left) - Detailed Inspection**							RE (See Note)	05-20-00 Scheduled Maintenance Checks		
57 A/F						Mos					
						Hrs					
	ATA Ref:57-51-00, MRB Ref:57.14.00/04 (SOURCE: G280 AMM) (NOTE: Perform at main landing gear removal.)					Ldg					
575106	**Main Landing Gear Support Bushings and Bearings (Visible Portions) (Right) - Detailed Inspection**							RE (See Note)	05-20-00 Scheduled Maintenance Checks		
57 A/F						Mos					
						Hrs					
	ATA Ref:57-51-00, MRB Ref:57.14.00/04 (SOURCE: G280 AMM) (NOTE: Perform at main landing gear removal.)					Ldg					
▼ 1. T - | 2. RE -										Man Hours: 274+	
280-23-003 Rev 1	**Communications - Audio System - Installation of Third Audio System**							T (-)		Optional	
23 A/F						Mos					
Eff: 20-Dec-2013						Hrs					
						Ldg					
280-23-006	**Communications - High Frequency System - Installation of Second HF System**							T (-)		Optional	
23 A/F						Mos					
Eff: 20-Nov-2012						Hrs					
						Ldg					
280-23-006 Rev 1	**Communications - High Frequency System - Installation of Second HF System**							T (-)		Optional	
23 A/F						Mos					
Eff: 20-Dec-2013						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-23-007	**Communications - Datalink System - Audio Integrating - Installation of Second Datalink System**							T (-)		Optional	
23 A/F						Mos					
Eff: 21-Nov-2012						Hrs					
						Ldg					
280-23-007 Rev 1	**Communications - Datalink System - Audio Integrating - Installation of Second Datalink System**							T (-)		Optional	
23 A/F						Mos					
Eff: 31-Oct-2013						Hrs					
						Ldg					
280-23-007 Rev 2	**Communications - Datalink System - Audio Integrating - Installation of Second Datalink System**							T (-)		Optional	
23 A/F						Mos					
Eff: 01-Jun-2015						Hrs					
						Ldg					
D201907000030	**Biocide Treatment Process**							T (-)		Service Information Letter	
28 ENG1						Mos					
Eff: 13-Aug-2019						Hrs					
						Enc					
D201907000030	**Biocide Treatment Process**							T (-)		Service Information Letter	
28 ENG2						Mos					
Eff: 13-Aug-2019						Hrs					
						Enc					
D201907000030 Rev 1	**Biocide Treatment Process**							T (-)		Service Information Letter	
28 ENG1						Mos					
Eff: 07-May-2020						Hrs					
						Enc					
D201907000030 Rev 1	**Biocide Treatment Process**							T (-)		Service Information Letter	
28 ENG2						Mos					
Eff: 07-May-2020						Hrs					
						Enc					
280-31-009	**Indicating/Recording Systems - Secondary Flight Data Recorder (FDR) System - Installation**							T (-)		Optional	
31 A/F						Mos					
Eff: 19-Jun-2015						Hrs					
						Ldg					
280-31-009 Rev 1	**Indicating/Recording Systems - Secondary Flight Data Recorder (FDR) System - Installation**							T (-)		Optional	
31 A/F						Mos					
Eff: 24-Jul-2015						Hrs					
						Ldg					
280-31-009 Rev 2	**Indicating/Recording Systems - Secondary Flight Data Recorder (FDR) System - Installation**							T (-)		Optional	
31 A/F						Mos					
Eff: 04-Aug-2017						Hrs					
						Ldg					
280-31-009 Rev 3	**Indicating/Recording Systems - Secondary Flight Data Recorder (FDR) System - Installation**							T (-)		Optional	
31 A/F						Mos					
Eff: 01-Oct-2019						Hrs					
(AVG MAN HRS: 220)						Ldg					
G-004-09-83	**SUPERSEDED BY CAA UK AD 017-11-83**							RE (-)		Mandatory	
32 A/F						Mos	14-Apr-2023				
Eff: 12-Dec-1983 Superseded						Hrs	112:17				
						Ldg	61				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G-005-09-83	**SUPERSEDED BY CAA UK AD 016-11-83**							RE (-)		Mandatory	
32 A/F						Mos	14-Apr-2023				
Eff: 12-Dec-1983 Superseded						Hrs	112:17				
						Ldg	61				
G-013-08-90	**SUPERSEDED BY CAA UK AD 009-02-93**							RE (-)		Mandatory	
32 A/F						Mos	14-Apr-2023				
Eff: 20-Jan-1993 Superseded						Hrs	112:17				
						Ldg	61				
2012-26-15 R1	**Honeywell International Inc. - Air Data Pressure Transducers (This action rescinds AD 2012-26-15, Amendment 39-17310 (78 FR 1735, January 9, 2013).)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	10-Feb-2023				
Eff: 03-Dec-2014 Not Applicable	NOT INSTALLED					Hrs	24:24				
						Ldg	7				
2019-12-09	**Navigation - Rockwell Collins, Inc. (Rockwell Collins) Flight Display System Application FDSA-6500 - Revise AFM/ Fabricate Placard (Superseded by AD 2021-05-17)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	10-Feb-2023				
Eff: 23-Jul-2019 Not Applicable	NOT INSTALLED					Hrs	24:24				
						Ldg	7				
(NOTE: NOTE: This AD applies to Rockwell Collins, Inc. (Rockwell Collins) Flight Display System Application FDSA-6500, P/N 810-0234-1H0001, 810-0234-1H0002, 810-0234-1H0003, 810-0234-2H0001, 810-0234-2C0001, 810-0234-2C0002, and 810-0234-4B0001.)											
2021-23-12	**Indicating/Recording System, Navigation - Radio Altimeter (Transport and Commuter Category Airplanes) (This AD is Superseded by FAA AD 2023-10-02)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	10-Aug-2023				
Eff: 03-Jan-2022 Complied With						Hrs					
(UPDATE NOTE: BY REVISING AFM LIMITATIONS BY REV. 9) (NOTE: COMPLIANCE: On or before January 4, 2022: Revise the Limitations Section of the existing AFM by incorporating the limitations specified in figure 1 to paragraph (g) of this AD. This may be done by inserting a copy of this AD into the existing AFM.)						Ldg					
280-34-001	**Navigation - Radio Altimeter - Installation of Secondary Radio Altimeter**							T (-)		Optional	
34 A/F						Mos					
Eff: 20-Nov-2012						Hrs					
						Ldg					
280-34-001 Rev 1	**Navigation - Radio Altimeter - Installation of Secondary Radio Altimeter**							T (-)		Optional	
34 A/F						Mos					
Eff: 31-Oct-2013						Hrs					
						Ldg					
280-34-001 Rev 2	**Navigation - Radio Altimeter - Installation of Secondary Radio Altimeter**							T (-)		Optional	
34 A/F						Mos					
Eff: 15-Dec-2015						Hrs					
						Ldg					
280-34-002	**Navigation - Inertial Reference System (IRS) - Installation of Third IRS System**							T (-)		Optional	
34 A/F						Mos					
Eff: 13-Nov-2012						Hrs					
						Ldg					
280-34-004	**Navigation - Automatic Direction Finder (ADF) - Installation of Second ADF System**							T (-)		Optional	
34 A/F						Mos					
Eff: 20-Nov-2012						Hrs					
						Ldg					
280-34-004 Rev 1	**Navigation - Automatic Direction Finder (ADF) - Installation of Second ADF System**							T (-)		Optional	
34 A/F						Mos					
Eff: 20-Dec-2013						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-34-005	**Navigation - Very High Frequency (VHF) - Installation of Third VHF NAV System**							T (-)		Optional	
34 A/F						Mos					
Eff: 20-Nov-2012						Hrs					
						Ldg					
280-34-005 Rev 1	**Navigation - Very High Frequency (VHF) - Installation of Third VHF NAV System**							T (-)		Optional	
34 A/F						Mos					
Eff: 15-Dec-2015						Hrs					
						Ldg					
280-34-008	**Navigation - Flight Management System (FMS) - Installation of Third FMS**							T (-)		Optional	
34 A/F						Mos					
Eff: 21-Nov-2012						Hrs					
						Ldg					
280-34-008 Rev 1	**Navigation - Flight Management System (FMS) - Installation of Third FMS**							T (-)		Optional	
34 A/F						Mos					
Eff: 31-Oct-2013						Hrs					
						Ldg					
280-34-008 Rev 2	**Navigation - Flight Management System (FMS) - Installation Of Third FMS System (MODG25-10005)**							T (-)		Optional	
34 A/F						Mos					
Eff: 15-Dec-2015						Hrs					
						Ldg					
280-34-008 Rev 3	**Navigation - Flight Management System (FMS) - Installation of Third FMS**							T (-)		Optional	
34 A/F						Mos					
Eff: 23-Aug-2018						Hrs					
(AVG MAN HRS: 12)						Ldg					
280-34-290	**Navigation - Terrain Awareness and Warning System - SMS Override Lighted Switch Retrofit and SMS/TLAF Application Enable**							T (-)		Optional	
34 A/F						Mos					
Eff: 27-May-2021						Hrs					
(AVG MAN HRS: 24) (NOTE: CONCURRENT REQUIREMENTS: Aircraft PlaneView Avionic suite version 3.6.1 installed (Ref. SB 280-34-273 / MOD G25-10074).)						Ldg					
2011-04-09	**Chemical oxygen generator deactivation (Superseded by FAA AD 2012-11-09)**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	10-Feb-2023				
Eff: 14-Mar-2011 Not Applicable	NOT INSTALLED					Hrs	24:24				
						Ldg	7				
36-49-8190	**AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Group Balance and Assembly of the Power Section for 36-150[IAI] APU PN 3800710-1 -2 and -3**							T (-)			
49 APU1						Mos					
Eff: 23-Mar-2017						Hrs					
						APUS					
36-49-8190 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Group Balance and Assembly of the Power Section for 36-150[IAI] APU PN 3800710-1 -2 and -3**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 13-Nov-2017 Not Applicable	before manufacture					Hrs					
(AVG MAN HRS: 3) (NOTE: APU P/N: 3800710-3.)						APUS					
36-49-8361 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet PN M24243/6A401H with Rivet PN 627-504-9209 on 36-150 Engine Models**							RE (-)		Cat. 2 - Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 30-Mar-2022 Not Applicable	as per APU S/N					Hrs					
(AVG MAN HRS: 1)						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
36-49-8361 Rev 3	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet PN M24243/6A401H with Rivet PN 627-504-9209 on 36-150 Engine Models**							RE (-)		Cat. 2 - Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 14-Apr-2022 Not Applicable	as per APU S/N					Hrs					
						APUS					
3822101-49-8148 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, P/N 3822101-1, on Multiple APU's**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 20-Oct-2015 Not Applicable	as per compressor rotor P/N					Hrs					
						APUS					
3882730-49-7974 Rev 1	**INSTALL FUEL FLOW DEFLECTOR, PN 70720001-1 ON THE FUEL CONTROL DIFFERENTIAL PRESSURE (DELTA P) SLEEVE**							T (-)			
49 APU1						Mos					
Eff: 10-Apr-2009						Hrs					
						APUS					
49-7933 Rev 5	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**							T (-)		Service Bulletin	
49 APU1						Mos					
Eff: 23-Oct-2014						Hrs					
						APUS					
49-7933 Rev 7	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**							T (-)		Service Bulletin	
49 APU1						Mos					
Eff: 09-Feb-2017						Hrs					
						APUS					
49-7933 Rev 8	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**							T (-)		Service Bulletin	
49 APU1						Mos					
Eff: 27-Jul-2017						Hrs					
						APUS					
49-7933 Rev 9	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**							T (-)		Service Bulletin	
49 APU1						Mos					
Eff: 03-Apr-2020						Hrs					
						APUS					
49-7997 Rev 4	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							T (-)		Service Bulletin	
49 APU1						Mos					
Eff: 12-Jan-2015						Hrs					
						APUS					
49-7997 Rev 5	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							T (-)		Service Bulletin	
49 APU1						Mos					
Eff: 03-Feb-2017						Hrs					
						APUS					
49-8252	**Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs**							T (-)			
49 APU1						Mos					
Eff: 31-Aug-2018						Hrs					
						APUS					
49-8252 Rev 1	**Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs**							T (-)			
49 APU1						Mos					
Eff: 07-Mar-2019						Hrs					
						APUS					
70721598-49-8168 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 20-Oct-2015 Not Applicable	before manufacture					Hrs					
						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
70721598-49-8168 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 10-Jan-2017 Not Applicable	before manufacture					Hrs					
						APUS					
70721725-49-8152 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 27-May-2015 Not Applicable						Hrs					
						APUS					
70721725-49-8152 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Not Applicable						Hrs					
						APUS					
70721725-49-8152 Rev 3	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 27-Nov-2017 Not Applicable						Hrs					
						APUS					
D201107000024	**Approved Use of Hydroprocessed Esters and Fatty Acids (HEFA) Biofuel Blends for all Honeywell Commercial Auxiliary Power Units (APU)**							T (-)		Service Information Letter	
49 APU1						Mos					
Eff: 07-Sep-2011						Hrs					
						APUS					
GTCP36-49-8096	**Airborne Auxiliary Power - Gas Turbine Engine - Replace the Fuel Supply Tube Assembly PN 3882732-1 with PN 3882732-2**							RE (-)		Recommended, Service Bulletin	
49 APU1						Mos	17-Apr-2023				
Eff: 22-Jul-2013 Not Applicable	APU P/N not installed					Hrs					
						APUS					
GTCP36-49-8191	**Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine 36-150[IAI],PN 3800710-1 and PN 3800710-2, for Incorporation of Improved Compressor Carbon Seal and Related Components**							T (-)		Optional	
49 APU1						Mos					
Eff: 14-Feb-2017						Hrs					
(NOTE: CONCURRENT REQUIREMENTS)						APUS					
SIL D201701000026 Rev 1	**Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine Worksheet for 36-100, 36-150, RE100, and RE220 APUs**							T (-)		Service Information Letter	
49 APU1						Mos					
Eff: 23-Jan-2018						Hrs					
						APUS					
AS907-3 Rev 2	**AS907 Jet-Care Trend Monitoring System**							T (-)		Service Information Letter	
72 ENG1						Mos					
Eff: 08-Nov-2017						Hrs					
						Enc					
AS907-3 Rev 2	**AS907 Jet-Care Trend Monitoring System**							T (-)		Service Information Letter	
72 ENG2						Mos					
Eff: 08-Nov-2017						Hrs					
						Enc					
AS907-3 Rev 3	**AS907 Trend Monitoring System**							T (-)		Service Information Letter	
72 ENG1						Mos					
Eff: 02-Apr-2019						Hrs					
						Enc					
AS907-3 Rev 3	**AS907 Trend Monitoring System**							T (-)		Service Information Letter	
72 ENG2						Mos					
Eff: 02-Apr-2019						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-72-9001 Rev 2	**Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	17-Apr-2023				
Eff: 14-Aug-2018 Not Applicable	as per engine S/N					Hrs	97:47				
(AVG MAN HRS: 5)						Enc	64				
AS907-72-9001 Rev 2	**Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 14-Aug-2018 Not Applicable	as per engine S/N					Hrs	117:47				
(AVG MAN HRS: 5)						Enc	76				
AS907-72-9045 Rev 2	**Engine - Compressor Section - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2, -4 or -6**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	17-Apr-2023				
Eff: 06-Sep-2018 Not Applicable	as per engine S/N					Hrs	97:47				
						Enc	64				
AS907-72-9045 Rev 2	**Engine - Compressor Section - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2, -4 or -6**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	17-Apr-2023				
Eff: 06-Sep-2018 Not Applicable	as per engine S/N					Hrs	117:47				
						Enc	76				
AS907-72-9046	**Hp Turbine Section - Install New Hp Turbine Stage 2 Nozzle Segments Pn 3035141-3 -4 On As907 Engine Models**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	10-Feb-2023				
Not Applicable	PER ENGINE PART NUMBER					Hrs					
						Enc					
AS907-72-9046	**Hp Turbine Section - Install New Hp Turbine Stage 2 Nozzle Segments Pn 3035141-3 -4 On As907 Engine Models**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	10-Feb-2023				
Not Applicable	PER ENGINE PART NUMBER					Hrs					
						Enc					
AS907-72-9057	**Engine - HP Turbine Section - Install New Forward Vane Baffle, PN 70040799-1, on AS907-1-1A and AS907-2-1G Model Engines**							RE (-)			
72 ENG1						Mos	10-Feb-2023				
Eff: 13-Oct-2016 Not Applicable	PER S/N, incorporated in Production					Hrs					
						Enc					
AS907-72-9057	**Engine - HP Turbine Section - Install New Forward Vane Baffle, PN 70040799-1, on AS907-1-1A and AS907-2-1G Model Engines**							RE (-)			
72 ENG2						Mos	10-Feb-2023				
Eff: 13-Oct-2016 Not Applicable	PER S/N, incorporated in Production					Hrs					
						Enc					
AS907-72-9063	**Engine - HP Compressor - Install New Centrifugal Compressor Rotor PN 3033207-1 Shroud PN70040911-1 or PN 70040911-2 and Diffuser PN 70040018-1 for AS907-2-1G Engine Models**							RE (-)			
72 ENG1						Mos	10-Feb-2023				
Eff: 08-May-2015 Not Applicable	PER S/N, incorporated in Production					Hrs					
						Enc					
AS907-72-9063	**Engine - HP Compressor - Install New Centrifugal Compressor Rotor PN 3033207-1 Shroud PN70040911-1 or PN 70040911-2 and Diffuser PN 70040018-1 for AS907-2-1G Engine Models**							RE (-)			
72 ENG2						Mos	10-Feb-2023				
Eff: 08-May-2015 Not Applicable	PER S/N, incorporated in Production					Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-72-9084	**Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	17-Apr-2023				
Eff: 12-Jun-2019 Not Applicable	as per engine S/N					Hrs	97:47				
						Enc	64				
(AVG MAN HRS: 1) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished within 150 to 250 hours after receipt of the service bulletin and every 150 to 250 hours thereafter.)											
AS907-72-9084	**Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 12-Jun-2019 Not Applicable	as per engine S/N					Hrs	117:47				
						Enc	76				
(AVG MAN HRS: 1) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished within 150 to 250 hours after receipt of the service bulletin and every 150 to 250 hours thereafter.)											
AS907-72-9084 Rev 2 Par. E.(2)	**Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components - Oil Filter Replacement**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	17-Apr-2023				
Eff: 12-Jun-2019 Not Applicable	as per engine S/N					Hrs	97:47				
						Enc	64				
(NOTE: Honeywell recommends replacement of the engine oil filter every 150 to 250 hours of engine operation. Honeywell recommends initiating this oil filter replacement within 250 engine operation hours after receipt of the initial issue of this service bulletin. The removed oil filter should be sent to a Honeywell approved laboratory for analysis.)											
AS907-72-9084 Rev 2 Par. E.(2)	**Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components - Oil Filter Replacement**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 12-Jun-2019 Not Applicable	as per engine S/N					Hrs	117:47				
						Enc	76				
(NOTE: Honeywell recommends replacement of the engine oil filter every 150 to 250 hours of engine operation. Honeywell recommends initiating this oil filter replacement within 250 engine operation hours after receipt of the initial issue of this service bulletin. The removed oil filter should be sent to a Honeywell approved laboratory for analysis.)											
AS907-72-9084 Rev 2 Par. E.(3)	**Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components - (EEI) Download**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	17-Apr-2023				
Eff: 21-Feb-2020 Not Applicable	as per engine S/N					Hrs	97:47				
						Enc	64				
(NOTE: Honeywell recommends downloading the engine ECUs every 25 to 35 days if engine operation has occurred during this period. Honeywell recommends initiating this ECU downloading interval within 35 days after receipt of Revision 1 of this service bulletin.)											
AS907-72-9084 Rev 2 Par. E.(3)	**Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components - (EEI) Download**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 21-Feb-2020 Not Applicable	as per engine S/N					Hrs	117:47				
						Enc	76				
(NOTE: Honeywell recommends downloading the engine ECUs every 25 to 35 days if engine operation has occurred during this period. Honeywell recommends initiating this ECU downloading interval within 35 days after receipt of Revision 1 of this service bulletin.)											
AS907-72-9091	**Engine - HP Turbine Section - HPT-2 Rotor Assembly, PN 3035135-5/-6/-7, Institute Enhanced Inspection and Reporting for the HPT Rotating Interstage Seal, PN 3035134-3 on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG1						Mos	17-Apr-2023				
Eff: 16-Oct-2020 Not Applicable	before manufacture					Hrs	97:47				
						Enc	64				
(AVG MAN HRS: 1) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at first access to affected parts.)											

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-72-9091	**Engine - HP Turbine Section - HPT-2 Rotor Assembly, PN 3035135-5/-6/-7, Institute Enhanced Inspection and Reporting for the HPT Rotating Interstage Seal, PN 3035134-3 on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 16-Oct-2020 Not Applicable	before manufacture					Hrs	117:47				
						Enc	76				
(AVG MAN HRS: 1) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at first access to affected parts.)											
D201903000028	**AS907 Aft Sump Event Discussion**							T (-)		Service Information Letter	
72 ENG1						Mos					
Eff: 26-Mar-2019						Hrs					
						Enc					
D201903000028	**AS907 Aft Sump Event Discussion**							T (-)		Service Information Letter	
72 ENG2						Mos					
Eff: 26-Mar-2019						Hrs					
						Enc					
D202102001590	**Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download and Honeywell Forge Engine Data Viewer (EDV)**							T (-)		Service Information Letter	
72 ENG1						Mos					
Eff: 22-Feb-2021						Hrs					
						Enc					
D202102001590	**Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download and Honeywell Forge Engine Data Viewer (EDV)**							T (-)		Service Information Letter	
72 ENG2						Mos					
Eff: 22-Feb-2021						Hrs					
						Enc					
D202102001590 Rev 1	**Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download and Honeywell Forge Engine Data Viewer (EDV)**							T (-)		Service Information Letter	
72 ENG1						Mos					
Eff: 14-Apr-2021						Hrs					
						Enc					
D202102001590 Rev 1	**Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download and Honeywell Forge Engine Data Viewer (EDV)**							T (-)		Service Information Letter	
72 ENG2						Mos					
Eff: 14-Apr-2021						Hrs					
						Enc					
D202102001590 Rev 2	**Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download and Honeywell Forge Engine Data Viewer (EDV)**							T (-)		Service Information Letter	
72 ENG1						Mos					
Eff: 14-May-2021						Hrs					
						Enc					
D202102001590 Rev 2	**Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download and Honeywell Forge Engine Data Viewer (EDV)**							T (-)		Service Information Letter	
72 ENG2						Mos					
Eff: 14-May-2021						Hrs					
						Enc					
D202102001590 Rev 3	**Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download 1.6.0 and Honeywell Forge Engine Data Viewer (EDV)**							T (-)		Service Information Letter	
72 ENG1						Mos					
Eff: 27-Jan-2022						Hrs					
						Enc					
D202102001590 Rev 3	**Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download 1.6.0 and Honeywell Forge Engine Data Viewer (EDV)**							T (-)		Service Information Letter	
72 ENG2						Mos					
Eff: 27-Jan-2022						Hrs					
						Enc					
D202102001590 Rev 4	**Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download 1.6.0 and Honeywell Forge Engine Data Viewer (EDV)**							T (-)		Service Information Letter	
72 ENG1						Mos					
Eff: 14-Nov-2022						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
D202102001590 Rev 4	**Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download 1.6.0 and Honeywell Forge Engine Data Viewer (EDV)**							T (-)		Service Information Letter	
72 ENG2						Mos					
Eff: 14-Nov-2022						Hrs					
						Enc					
AS907-76-9014 Rev 1	**ENGINE CONTROLS - POWER CONTROLS - Install Improved Electronic Control Unit (ECU) PN 2119576-3102 on AS907-2-1G Model Engines**							T (-)			
76 ENG1						Mos					
Eff: 08-Sep-2017						Hrs					
						Enc					
AS907-76-9014 Rev 1	**ENGINE CONTROLS - POWER CONTROLS - Install Improved Electronic Control Unit (ECU) PN 2119576-3102 on AS907-2-1G Model Engines**							T (-)			
76 ENG2						Mos					
Eff: 08-Sep-2017						Hrs					
						Enc					
D202308004115	**Thrust Reverser Unit (TRU) - MAPAERO Anomalies**							T (-)		Service Information Letter	
78 ENG1						Mos					
Eff: 09-Oct-2023						Hrs					
						Enc					
D202308004115	**Thrust Reverser Unit (TRU) - MAPAERO Anomalies**							T (-)		Service Information Letter	
78 ENG2						Mos					
Eff: 09-Oct-2023						Hrs					
						Enc					
D202308004115 Rev 1	**Thrust Reverser Unit (TRU) - MAPAERO Anomalies**							T (-)		Service Information Letter	
78 ENG1						Mos					
Eff: 17-Apr-2024						Hrs					
						Enc					
D202308004115 Rev 1	**Thrust Reverser Unit (TRU) - MAPAERO Anomalies**							T (-)		Service Information Letter	
78 ENG2						Mos					
Eff: 17-Apr-2024						Hrs					
						Enc					
D202011001451	**Thrust Reverser Unit (TRU) - MAPAERO Overview**							T (-)		Service Information Letter	
100 ENG1						Mos					
Eff: 06-Jan-2021						Hrs					
						Enc					
D202011001451	**Thrust Reverser Unit (TRU) - MAPAERO Overview**							T (-)		Service Information Letter	
100 ENG2						Mos					
Eff: 06-Jan-2021						Hrs					
						Enc					
D202011001451 Rev 1	**Thrust Reverser Unit (TRU) - MAPAERO Overview**							T (-)		Service Information Letter	
100 ENG1						Mos					
Eff: 05-May-2021						Hrs					
						Enc					
D202011001451 Rev 1	**Thrust Reverser Unit (TRU) - MAPAERO Overview**							T (-)		Service Information Letter	
100 ENG2						Mos					
Eff: 05-May-2021						Hrs					
						Enc					
▼ 1. T 10000 Ldg | 2. RE 2500 Ldg											
522112	**Emergency Door Bracket, Frame 33 and Frame 35 CF22.1 Emergency Door Brackets at Frame 33 and Frame 35 - NDT Inspection - [HFEC / MFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
52 A/F						Mos					
						Hrs					
ATA Ref:52-21-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
522113		**Emergency Door Bracket, Upper Sill CF22.2 Emergency Door Brackets Upper Sill - NDT Inspection - [HFEC / MFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	52 A/F						Mos					
							Hrs					
	ATA Ref:52-21-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
522114		**Emergency Door Bracket, Lower Sill CF22.3 Emergency Door Bracket Lower Sill - NDT Inspection - [HFEC / MFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	52 A/F						Mos					
							Hrs					
	ATA Ref:52-21-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
523121		**Baggage Door Brackets CF22.4 - CF22.12 Baggage Door Brackets - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	52 A/F						Mos					
							Hrs					
	ATA Ref:52-31-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
523122		**Baggage Door Brackets CF22.4 - CF22.12 Baggage Door Brackets - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	52 A/F						Mos					
							Hrs					
	ATA Ref:52-31-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
523123		**Baggage Door Brackets CF22.4 - CF22.12 Baggage Door Brackets - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	52 A/F						Mos					
							Hrs					
	ATA Ref:52-31-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
523124		**Baggage Door Brackets CF22.4 - CF22.12 Baggage Door Brackets - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	52 A/F						Mos					
							Hrs					
	ATA Ref:52-31-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
523125		**Baggage Door Brackets CF22.4 - CF22.12 Baggage Door Brackets - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	52 A/F						Mos					
							Hrs					
	ATA Ref:52-31-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
523126		**Baggage Door Brackets CF22.4 - CF22.12 Baggage Door Brackets - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	52 A/F						Mos					
							Hrs					
	ATA Ref:52-31-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
523127		**Baggage Door Brackets CF22.4 - CF22.12 Baggage Door Brackets - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	52 A/F						Mos					
							Hrs					
	ATA Ref:52-31-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
523128		**Baggage Door Brackets CF22.4 - CF22.12 Baggage Door Brackets - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	52 A/F						Mos					
							Hrs					
	ATA Ref:52-31-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
523129	**Baggage Door Brackets CF22.4 - CF22.12 Baggage Door Brackets - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
52 A/F						Mos					
						Hrs					
ATA Ref:52-31-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
▼ 1. T 10000 Ldg | 2. RE 5000 Ldg											
232746	**KA-Band Aft Pressure Bulkhead Special Detailed Inspection**							T			**≈30-Mar-2044**
23 A/F						Mos					
						Hrs					
						Ldg		10,000		10,000	9,382 Ldg
521312	**Entry Door Stopper FF10.5 Main Entrance Door Assembly Stopper - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
52 A/F						Mos					
						Hrs					
ATA Ref:52-13-03 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531009	**Upper Skin Panel, FS 229.21 - FS 346.38 (5822 - 8798 mm) FF5.3 Forward Fuselage Skin Upper Panel FS 229.21 - FS 346.38 (5822 - 8798 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
53 A/F						Mos					
						Hrs					
ATA Ref:53-10-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531025	**Left Connector Plate FF1.5 Forward Pressure Bulkhead Left Connector Plate - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
53 A/F						Mos					
						Hrs					
ATA Ref:53-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531026	**Right Connector Plate FF1.6 Forward Pressure Bulkhead Right Connector Plate - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
53 A/F						Mos					
						Hrs					
ATA Ref:53-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531027	**Forward Window Frame FF7.1 Forward Fuselage Window Frames - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
53 A/F						Mos					
						Hrs					
ATA Ref:53-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531029	**Upper Panel, Right Longeron, FS 177.87 - FS 229.21 (4518 - 5822 mm) FF8.2 Forward Fuselage Upper Panel Right Longeron FS 177.87 - FS 229.21 (4518 - 5822 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
53 A/F						Mos					
						Hrs					
ATA Ref:53-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531038	**Stiffeners at BL 8.3 (210 mm) FF1.7 Forward Pressure Bulkhead Stiffeners, FS 105.1 (2669 mm) at BL 8.3 (210 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
53 A/F						Mos					
						Hrs					
ATA Ref:53-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531039	**Stiffeners at BL 12.2 (310 mm) FF1.8 Forward Pressure Bulkhead Stiffeners, FS 105.1 (2669 mm) at BL 12.2 (310 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
53 A/F						Mos					
						Hrs					
ATA Ref:53-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
531223		**Cockpit Side Window Retainer, Left / Right FF7.2 Cockpit Side Windows Retainer - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-12-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531231		**Left / Right Lower Canopy Sill FF2.7, FF2.8 Canopy Lower Sills - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-12-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531232		**Left / Right Lower Canopy Sill FF2.7, FF2.8 Canopy Lower Sills - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-12-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531233		**Splice Upper Sill and Central Post FF2.9 Canopy Splice Upper Sill and Central Post - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-12-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531234		**Lower Sills Doubler FF2.10 Canopy Lower Sills Doubler - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-12-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531235		**Lower Sills Splice FF2.11 Canopy Lower Sills Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-12-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531236		**Left / Right Lower Sill Fitting Reinforcement , FS 139.09 - FS 148.35 (3533 - 3768 mm) FF2.12 Canopy Fitting Lower Sill Reinforcement FS 139.09 - FS 148.35 (3533 - 3768 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-12-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531237		**Center Post Attach Fitting, FS 105.1 (2669 mm) FF2.13 Canopy Center Post Attachment Fitting FS 105.1 (2669 mm) - NDT Inspection, 53-12-02, Inspection / Check or Code 531237 - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-12-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531238		**Left / Right Frame 5, FS 128.93 (3275 mm) FF17.1 Cockpit Frame 5 FS 128.93 (3275 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-12-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531239		**Left / Right Frame 6, FS 139.09 (3533 mm) FF17.2 Cockpit Frame 6 FS 139.09 (3533 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-12-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
531240		**Left / Right Frame 7, FS 148.35 (3768 mm) FF17.3 Cockpit Frame 7 FS 148.35 (3768 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-12-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531241		**Lower Sill Lightning Holes FF2.14 Canopy Lower Sill Lightning Holes - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-12-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531242		**Lower Sill Forward Integral Rib FF2.15 Canopy Lower Sill Forward Integral Rib - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-12-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531243		**Lower Sill Fastener Holes FF2.16 Canopy Lower Sill Fastener Holes - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-12-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531316		**Lower Left Intercostal, FS 177.87 - FS 185.94 (4518 - 4723 mm), BL 330 FF13.1 Forward Cabin Lower Left Intercostal FS 177.87 - FS 185.94 (4518 - 4723 mm) BL330 - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-13-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531317		**Left Frame, FS 185.94 (4723 mm) FF10.1 Forward Cabin Left Frame at FS 185.94 (4723 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-13-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531319		**Lower Left Fitting, FS 185.94 (4723 mm) FF10.3 Forward Cabin Lower Fitting at FS 185.94 (4723 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-13-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531320		**Upper Sill, FS 185.94 - FS 221.77 (4723 - 5633 mm) FF11.1 Forward Cabin Upper Sill FS 185.94 - FS 221.77 (4723 - 5633 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-13-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531322		**Fitting, FS 185.94 (4723 mm), BL 22.24 (565 mm) FF12.1 Forward Cabin Fitting FS 185.94 (4723 mm) BL 22.24 (565 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-13-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531323		**Fitting, FS 221.77 (5633 mm), BL 22.24 (565 mm) FF12.2 Forward Cabin Fitting FS 221.77 (5633 mm) BL 22.24 (565 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-13-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
531324		**Left / Right Frame, FS 346.38 (8798 mm) FF14.1 Forward Cabin Frames FS 346.38 (8798 mm) - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-13-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531325		**Upper Frame, FS 346.38 (8798 mm) FF14.2 Forward Cabin Upper Frame FS 346.38 (8798 mm) - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-13-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531326		**Lower Frame, FS 346.38 (8798 mm) FF14.3 Forward Cabin Lower Frame FS 346.38 (8798 mm) - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-13-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531327		**Lower Frame, FS 221.77 (5633 mm) FF15.1 Forward Cabin Lower Frame FS 221.77 (5633 mm) - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-13-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531328		**Lower Frame, FS 185.94 (4723 mm) FF15.2 Forward Cabin Lower Frame FS 185.94 (4723 mm) - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-13-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531329		**Door Stop Fitting FF10.4 Main Entrance Door Support Stopper - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-13-02 (SOURCE: G280 AMM) (NOTE: Applies to Aircraft 2001 thru Aircraft 2020 Post Mod G25-20026 and Aircraft 2021 thru Aircraft 9999.)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531330		**MED Jamb Assembly, Frame 14, FS 221.77 (5663 mm) FF10.2A Forward Cabin Frame 14 MED Jamb Assembly FS 221.77 (5633 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-13-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531331		**Frame 10, Left Side, FS 177.87 (4518 mm) FF10.6 Frame 10, Left Side, FS 177.87 (4518 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-13-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531604		**Left / Right NLG Trunnion Fitting FF3.4 Nose Landing Gear Trunnion Fittings - NDT Inspection, 53-16-00, Inspection / Check or Code 531604 - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-16-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531605		**Left NLG Bay Brace Fitting, FS 148.07 (3761 mm) FF3.5 Nose Landing Gear Brace Fittings - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-16-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
531606		**NLG Bay Ceiling FF3.6 Nose Landing Gear Bay Ceiling - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-16-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531607		**Doubler, FS 122.16 (3103 mm) FF3.8 Nose Landing Gear Bay Doubler FS 122.16 (3103 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-16-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531608		**Doubler, FS 177.87 (4518 mm) FF3.9 Nose Landing Gear Bay Doubler FS 177.87 (4518 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-16-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531609		**NLG Bay Intergral Intercostal FF3.10 Nose Landing Gear Bay Intercostal Splices - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-16-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
531610		**NLG Vertical Stiffener, Left Side FF3.11 Nose Landing Gear Bay Vertical Stiffener, FS 158.19 (4018 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-16-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532008		**Emergency Exit Frame 32 CF6.1 Emergency Exit Frame 32 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532009		**Emergency Exit Frame 33 CF6.2 Emergency Exit Frame 33 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532010		**Emergency Exit Frame 34 CF6.3 Emergency Exit Frame 34 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532013		**Emergency Exit Frame 35 CF6.4 Emergency Exit Frame 35 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532014		**Emergency Exit Frame 36 CF6.5 Emergency Exit Frame 36 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
532019		**Center Fuselage Right Side Skin, Frame 27 - Frame 41 CF1.1 Center Fuselage Right Skin Frame 27 - Frame 41 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532020		**Center Fuselage Left Side Skin, Frame 27 - Frame 41 CF1.2 Center Fuselage Left Skin Frame 27 - Frame 41 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-01 (SOURCE: G280 AMM)						Ldg		10,000	-/+5%	10,000	9,382 Ldg (+500)
532021		**Center Fuselage Right Side Skin, Frame 41 - Frame 50 CF1.3 Center Fuselage Right Skin Frame 41 - Frame 50 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532022		**Center Fuselage Left Side Skin, Frame 41 - Frame 50 CF1.4 Center Fuselage Left Skin Frame 41 - Frame 50 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532023		**Center Fuselage Upper Skin, Frame 27 - Frame 41 CF2.1 Center Fuselage Upper Skin Frame 27 - Frame 41 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532024		**Center Fuselage Upper Skin, Frame 41 - Frame 50 CF2.2 Center Fuselage Upper Skin Frame 41 - Frame 50 - NDT Inspection, 53-20-01, Inspection / Check or Code 532024 - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532025		**Center Fuselage Lower Skin, Frame 27 - Frame 41 CF3.1 Center Fuselage Lower Skin Frame 27 - Frame 41 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532026		**Center Fuselage Lower Skin, Frame 41 - Frame 50 CF3.2 Center Fuselage Lower Skin Frame 41 - Frame 50 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532027		**Emergency Exit Doubler CF7.1 Emergency Exit Doubler - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532030		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
532031		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532032		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532033		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532034		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532035		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532036		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532037		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532038		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532039		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532040		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
532041		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532042		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532043		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532044		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532045		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532046		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532047		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532048		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532049		**Center Fuselage Lower Frame 28 - Frame 50 CF4.1 - CF4.20 Center Fuselage Lower Frames - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532052		**Wing Pickup Fitting, Frame 29 CF14.1 Wing Pickup Fitting Left and Right Frame 29 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
532053		**Wing Pickup Fitting, Frame 29 CF14.1 Wing Pickup Fitting Left and Right Frame 29 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532054		**Center Fuselage Upper Frame 29 and Frame 38 CF14.2 Center Fuselage Upper Frame 29 and Frame 38 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532055		**Center Fuselage Upper Frame 29 and Frame 38 CF14.2 Center Fuselage Upper Frame 29 and Frame 38 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532056		**Wing Pickup Fitting, Frame 38 CF15.1 Wing Pickup Fitting Left and Right Frame 38 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532057		**Wing Pickup Fitting, Frame 38 CF15.1 Wing Pickup Fitting Left and Right Frame 38 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532067		**Center Fuselage Side Frame 34, Lower Left / Right CF19.1 Center Fuselage Side Frame 34 Lower Left and Right - NDT Inspection - [LFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532068		**Center Fuselage Side Frame 34, Lower Left / Right CF19.1 Center Fuselage Side Frame 34 Lower Left and Right - NDT Inspection - [LFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532069		**Center Fuselage Side Frame 37, Lower Left / Right CF19.2 Center Fuselage Side Frame 37 Lower Left and Right - NDT Inspection - [LFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532070		**Center Fuselage Side Frame 37, Lower Left / Right CF19.2 Center Fuselage Side Frame 37 Lower Left and Right - NDT Inspection - [LFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532071		**Center Fuselage Side Frame 39, Left / Right CF19.3 Center Fuselage Side Frame 39 Left and Right - NDT Inspection - [LFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
532072		**Center Fuselage Side Frame 39, Left / Right CF19.3 Center Fuselage Side Frame 39 Left and Right - NDT Inspection - [LFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532073		**Center Fuselage Side Frame 41, Left / Right CF19.4 Center Fuselage Side Frame 41 Left and Right - NDT Inspection - [LFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532074		**Center Fuselage Side Frame 41, Left / Right CF19.4 Center Fuselage Side Frame 41 Left and Right - NDT Inspection - [LFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532075		**Center Fuselage Side Frame 50, Left / Right CF19.5 Center Fuselage Side Frame 50 Left and Right - NDT Inspection - [LFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532076		**Center Fuselage Side Frame 50, Left / Right CF19.5 Center Fuselage Side Frame 50 Left and Right - NDT Inspection - [LFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532077		**Center Fuselage Upper Frame 41 CF19.6 Center Fuselage Upper Frame 41 - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532078		**Center Fuselage Upper Frame 50 CF19.7 Center Fuselage Upper Frame 50 - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532079		**Center Fuselage Side Splices, Frame 28 - Frame 50 CF4.21 - CF4.39 Center Fuselage Side Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532080		**Center Fuselage Side Splices, Frame 28 - Frame 50 CF4.21 - CF4.39 Center Fuselage Side Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532081		**Center Fuselage Side Splices, Frame 28 - Frame 50 CF4.21 - CF4.39 Center Fuselage Side Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
532082		**Center Fuselage Side Splices, Frame 28 - Frame 50 CF4.21 - CF4.39 Center Fuselage Side Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532083		**Center Fuselage Side Splices, Frame 28 - Frame 50 CF4.21 - CF4.39 Center Fuselage Side Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532084		**Center Fuselage Side Splices, Frame 28 - Frame 50 CF4.21 - CF4.39 Center Fuselage Side Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532085		**Center Fuselage Side Splices, Frame 28 - Frame 50 CF4.21 - CF4.39 Center Fuselage Side Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532086		**Center Fuselage Side Splices, Frame 28 - Frame 50 CF4.21 - CF4.39 Center Fuselage Side Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532087		**Center Fuselage Side Splices, Frame 28 - Frame 50 CF4.21 - CF4.39 Center Fuselage Side Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532088		**Center Fuselage Side Splices, Frame 28 - Frame 50 CF4.21 - CF4.39 Center Fuselage Side Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532089		**Center Fuselage Side Splices, Frame 28 - Frame 50 CF4.21 - CF4.39 Center Fuselage Side Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532090		**Center Fuselage Side Splices, Frame 28 - Frame 50 CF4.21 - CF4.39 Center Fuselage Side Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532091		**Center Fuselage Side Splices, Frame 28 - Frame 50 CF4.21 - CF4.39 Center Fuselage Side Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
532092		**Center Fuselage Side Splices, Frame 28 - Frame 50 CF4.21 - CF4.39 Center Fuselage Side Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532093		**Center Fuselage Side Splices, Frame 28 - Frame 50 CF4.21 - CF4.39 Center Fuselage Side Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532094		**Center Fuselage Side Splices, Frame 28 - Frame 50 CF4.21 - CF4.39 Center Fuselage Side Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532095		**Center Fuselage Side Splices, Frame 28 - Frame 50 CF4.21 - CF4.39 Center Fuselage Side Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532096		**Center Fuselage Side Splices, Frame 28 - Frame 50 CF4.21 - CF4.39 Center Fuselage Side Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532097		**Center Fuselage Side Splices, Frame 28 - Frame 50 CF4.21 - CF4.39 Center Fuselage Side Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532098		**Center Fuselage Window Frame CF5.1 Center Fuselage Window Frame Between Frame 27 - Frame 41 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-20-03 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532122		**Center Fuselage Longeron Fitting, Auxiliary Bulkhead, BL 12.99 (330 mm) CF23.1, CF23.2 Auxiliary Bulkhead Forward Inboard Longeron Fitting, Left and Right Side, BL 12.99 (330 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-21-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532123		**Center Fuselage Longeron Fitting, Auxiliary Bulkhead, BL 12.99 (330 mm) CF23.1, CF23.2 Auxiliary Bulkhead Forward Inboard Longeron Fitting, Left and Right Side, BL 12.99 (330 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-21-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532208		**Baggage Compartment Exit Doubler, Frame 45 - Frame 49 CF10.1 Baggage Compartment Exit Doubler Between Frame 45 and Frame 49 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-22-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
532209		**Baggage Compartment Exit Side Frame 45 and Side Frame 49 CF11.3 Baggage Compartment Exit Frame 45 and Frame 49 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
		53 A/F					Mos					
							Hrs					
		ATA Ref:53-22-02 (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532211		**Baggage Compartment Exit Side Frame 45 CF11.1 Baggage Compartment Exit Frame 45 - NDT / Visual Inspection - [LFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
		53 A/F					Mos					
							Hrs					
		ATA Ref:53-22-02 (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532212		**Baggage Compartment Exit Side Frame 49 CF11.2 Baggage Compartment Exit Frame 49 - NDT / Visual Inspection - [LFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
		53 A/F					Mos					
							Hrs					
		ATA Ref:53-22-02 (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
532213		**Baggage Compartment Exit Upper Sill, Frame 45 - Frame 49 CF12.1 Baggage Compartment Exit Upper Sill - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
		53 A/F					Mos					
							Hrs					
		ATA Ref:53-22-02 (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533301		**Aft Fuselage Upper Skin, Frame 50 - Frame 64 AF8.1 Aft Fuselage Upper Skin - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
		53 A/F					Mos					
							Hrs					
		ATA Ref:53-33-01 (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533302		**Aft Fuselage Upper Skin Doubler, Frame 56 AF10.1 Aft Fuselage Upper Skin Doubler Frame 56 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
		53 A/F					Mos					
							Hrs					
		ATA Ref:53-33-01 (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533306		**Upper Longeron, Frame 56 - Frame 60, Left AF4.4 Aft Fuselage Left Upper Longeron Frame 56 - Frame 60 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
		53 A/F					Mos					
							Hrs					
		ATA Ref:53-33-02 (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533307		**Upper Longeron, Frame 56 - Frame 60, Right AF4.5 Aft Fuselage Right Upper Longeron Frame 56 - Frame 60 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
		53 A/F					Mos					
							Hrs					
		ATA Ref:53-33-02 (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533316		**Aft Fuselage Upper Joint Splice, Frame 56, FS 639.41 (16,241 mm) AF6.1 Aft Fuselage Joint Splice Frame 56 FS 639.41 (16,241 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
		53 A/F					Mos					
							Hrs					
		ATA Ref:53-33-02 (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533324		**Aft Fuselage, Frame 56 at Boomerang Attachment AF11.1 Aft Fuselage Upper Frame 56 at Boomerang Attachment - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
		53 A/F					Mos					
							Hrs					
		ATA Ref:53-33-02 (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
533328		**Aft Fuselage, Frame 60 at Boomerang Attachment AF11.5 Aft Fuselage Upper Frame 60 at Boomerang Attachment - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-33-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533329		**Aft Fuselage, Frame 63 at Boomerang Attachment AF11.6 Aft Fuselage Upper Frame 63 at Boomerang Attachment - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-33-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533346		**Aft Fuselage Lower Right Angle Support, FS 578.27 (14,688 mm) AF1.7 Aft Pressure Bulkhead Lower Right Angle Support FS 578.27 (14688 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-33-03 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533347		**Aft Fuselage Lower Left Angle Support, FS 578.27 (14,688 mm) AF1.8 Aft Pressure Bulkhead Lower Left Angle Support FS 578.27 (14688 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-33-03 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533352		**Aft Fuselage Lower Frame, FS 582.2 (14,788 mm) AF1.13 Aft Pressure Bulkhead Lower Frame Inner Flanges at Corner Radius - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-33-03 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533359		**Aft Pressure Bulkhead Omega Channel 4, WL 35.43 (WL 900 mm) AF1.20 Aft Pressure Bulkhead Omega Channel 4 WL35.43 (WL900 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-33-03 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533360		**Aft Pressure Bulkhead Omega Channel 5, WL 27.95 (WL 710 mm) AF1.21 Aft Pressure Bulkhead Omega Channel 5 WL27.95 (WL710 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-33-03 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533362		**Aft Pressure Bulkhead Web, FS 577.48 (14,668 mm) AF1.25 Aft Pressure Bulkhead Web - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-33-03 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533364		**Aft Pressure Bulkhead Doubler, Aperture 4 AF1.29 Aft Pressure Bulkhead Doubler Aperture 4 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-33-03 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533365		**Aft Pressure Bulkhead Doubler, Aperture 1 AF1.30 Aft Pressure Bulkhead Doubler Aperture 1 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-33-03 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
533366		**Aft Pressure Bulkhead Doubler, Aperture 3 AF1.31 Aft Pressure Bulkhead Doubler Aperture 3 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-33-03 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533367		**Aft Pressure Bulkhead Doubler, Aperture 2 AF1.32 Aft Pressure Bulkhead Doubler Aperture 2 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-33-03 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533368		**Aft Pressure Bulkhead Right Doubler Adaptor, FS 577.64 (14,672 mm), WL 32.28 (WL 820 mm) AF1.33 Aft Pressure Bulkhead Doubler Adaptor Right FS 577.64 (14672 mm) WL32.28 (WL820 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-33-03 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533393		**Aft Pressure Bulkhead Right Longeron Bath Tab Fitting AF1.47 Aft Pressure Bulkhead Bathtub Fitting Right Longeron - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-33-03 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533394		**Aft Pressure Bulkhead Left Longeron Bath Tab Fitting AF1.48 Aft Pressure Bulkhead Bathtub Fitting Top Left Longeron - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-33-03 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533411		**Pressure Bulkhead Shear Ties, Frame 50 - Frame 51 CF21.1 - CF21.6 Aft Fuselage Pressure Bulkhead Shear Ties Between Frames 50 and Frame 51 - NDT / Visual Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533412		**Pressure Bulkhead Shear Ties, Frame 50 - Frame 51 CF21.1 - CF21.6 Aft Fuselage Pressure Bulkhead Shear Ties Between Frames 50 and Frame 51 - NDT / Visual Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533413		**Pressure Bulkhead Shear Ties, Frame 50 - Frame 51 CF21.1 - CF21.6 Aft Fuselage Pressure Bulkhead Shear Ties Between Frames 50 and Frame 51 - NDT / Visual Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533414		**Pressure Bulkhead Shear Ties, Frame 50 - Frame 51 CF21.1 - CF21.6 Aft Fuselage Pressure Bulkhead Shear Ties Between Frames 50 and Frame 51 - NDT / Visual Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533415		**Pressure Bulkhead Shear Ties, Frame 50 - Frame 51 CF21.1 - CF21.6 Aft Fuselage Pressure Bulkhead Shear Ties Between Frames 50 and Frame 51 - NDT / Visual Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
533416		**Pressure Bulkhead Shear Ties, Frame 50 - Frame 51 CF21.1 - CF21.6 Aft Fuselage Pressure Bulkhead Shear Ties Between Frames 50 and Frame 51 - NDT / Visual Inspection - [HFEC / Visual]**							T	05-10-10	Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533417		**Pressure Bulkhead Shear Ties, Frame 50 - Frame 51 CF21.1 - CF21.6 Aft Fuselage Pressure Bulkhead Shear Ties Between Frames 50 and Frame 51 - NDT / Visual Inspection - [HFEC / Visual]**							T	05-10-10	Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533418		**Pressure Bulkhead Shear Ties, Frame 50 - Frame 51 CF21.1 - CF21.6 Aft Fuselage Pressure Bulkhead Shear Ties Between Frames 50 and Frame 51 - NDT / Visual Inspection - [HFEC / Visual]**							T	05-10-10	Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533419		**Pressure Bulkhead Shear Ties, Frame 50 - Frame 51 CF21.1 - CF21.6 Aft Fuselage Pressure Bulkhead Shear Ties Between Frames 50 and Frame 51 - NDT / Visual Inspection - [HFEC / Visual]**							T	05-10-10	Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533420		**Pressure Bulkhead Shear Ties, Frame 50 - Frame 51 CF21.1 - CF21.6 Aft Fuselage Pressure Bulkhead Shear Ties Between Frames 50 and Frame 51 - NDT / Visual Inspection - [HFEC / Visual]**							T	05-10-10	Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533421		**Pressure Bulkhead Shear Ties, Frame 50 - Frame 51 CF21.1 - CF21.6 Aft Fuselage Pressure Bulkhead Shear Ties Between Frames 50 and Frame 51 - NDT / Visual Inspection - [HFEC / Visual]**							T	05-10-10	Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533422		**Pressure Bulkhead Shear Ties, Frame 50 - Frame 51 CF21.1 - CF21.6 Aft Fuselage Pressure Bulkhead Shear Ties Between Frames 50 and Frame 51 - NDT / Visual Inspection - [HFEC / Visual]**							T	05-10-10	Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533425		**Forward Engine Mount Lugs, Left / Right AF2.1 Forward Engine Mount Lugs - NDT Inspection - [HFEC]**							T	05-10-10	Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533426		**Forward Engine Mount Lugs, Left / Right AF2.1 Forward Engine Mount Lugs - NDT Inspection - [HFEC]**							T	05-10-10	Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533433		**Engine Yoke Connection Bolt, Left / Right AF2.9 Forward Engine Mount Bolt Yoke Connection - NDT Inspection - [HFEC]**							T	05-10-10	Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
533434		**Engine Yoke Connection Bolt, Left / Right AF2.9 Forward Engine Mount Bolt Yoke Connection - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533445		**Engine Thrust Link Fitting, Left / Right AF3.4 Aft Engine Mount Thrust Link Fitting - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533446		**Engine Thrust Link Fitting, Left / Right AF3.4 Aft Engine Mount Thrust Link Fitting - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533447		**Aft Engine Mount Frame 55, Left / Right AF3.5, AF3.6 Aft Engine Mount Frame 55 to Rib 6 - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
533448		**Aft Engine Mount Frame 55, Left / Right AF3.5, AF3.6 Aft Engine Mount Frame 55 to Rib 6 - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	53 A/F						Mos					
							Hrs					
	ATA Ref:53-34-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
545009		**Engine Pylon Rib 6, Left / Right AF3.2 Engine Pylon Rib 6 Upper and Lower Lugs / Flange - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	54 A/F						Mos					
							Hrs					
	ATA Ref:54-50-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
545010		**Engine Pylon Rib 6, Left / Right AF3.2 Engine Pylon Rib 6 Upper and Lower Lugs / Flange - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	54 A/F						Mos					
							Hrs					
	ATA Ref:54-50-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
545011		**Aft Engine Mount Strut Connection Bolt, Left / Right AF3.2.1 Aft Engine Mount Strut Connection 1/2 Inch Bolts - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	54 A/F						Mos					
							Hrs					
	ATA Ref:54-50-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
545012		**Aft Engine Mount Strut Connection Bolt, Left / Right AF3.2.1 Aft Engine Mount Strut Connection 1/2 Inch Bolts - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	54 A/F						Mos					
							Hrs					
	ATA Ref:54-50-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
545013		**Engine Thrust Link, Left / Right AF3.3 Engine Thrust Link - NDT Inspection - [Ultrasonic]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	54 A/F						Mos					
							Hrs					
	ATA Ref:54-50-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
545014		**Engine Thrust Link, Left / Right AF3.3 Engine Thrust Link - NDT Inspection - [Ultrasonic]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	54 A/F						Mos					
							Hrs					
	ATA Ref:54-50-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551131		**Horizontal Stabilizer Upper Center Skin E10.1 Horizontal Stabilizer Upper Center Skin - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551133		**Horizontal Stabilizer Upper Outer Skin, Left / Right E10.2 Horizontal Stabilizer Upper Outer Skin - Visual / NDT Inspection - [Visual / Tap Test]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551134		**Horizontal Stabilizer Upper Outer Skin, Left / Right E10.2 Horizontal Stabilizer Upper Outer Skin - Visual / NDT Inspection - [Visual / Tap Test]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551135		**Horizontal Stabilizer Lower Center Skin E10.3 Horizontal Stabilizer Lower Center Skin - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551136		**Horizontal Stabilizer Lower Center Skin E10.3 Horizontal Stabilizer Lower Center Skin - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551137		**Horizontal Stabilizer Lower Outer Skin, Left / Right E10.4 Horizontal Stabilizer Lower Outer Skin - Visual / NDT Inspection - [Visual / Tap Test]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551138		**Horizontal Stabilizer Lower Outer Skin, Left / Right E10.4 Horizontal Stabilizer Lower Outer Skin - Visual / NDT Inspection - [Visual / Tap Test]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551139		**Horizontal Stabilizer Center Front Spar E11.1 Horizontal Stabilizer Center Front Spar - Visual / NDT Inspection - [LFEC / HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551141		**Horizontal Stabilizer Outer Front Spar, Left / Right E11.2 Horizontal Stabilizer Outer Front Spar - Visual / NDT Inspection - [Visual / Tap Test]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
551142		**Horizontal Stabilizer Outer Front Spar, Left / Right E11.2 Horizontal Stabilizer Outer Front Spar - Visual / NDT Inspection - [Visual / Tap Test]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551143		**Horizontal Stabilizer Front Spar Splice Fitting, Left / Right E11.3 Horizontal Stabilizer Front Spar Splice Fitting - NDT Inspection - [LFEC / X-ray]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551144		**Horizontal Stabilizer Front Spar Splice Fitting, Left / Right E11.3 Horizontal Stabilizer Front Spar Splice Fitting - NDT Inspection - [LFEC / X-ray]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551145		**Horizontal Stabilizer Center Rear Spar E11.4 Horizontal Stabilizer Center Rear Spar - Visual / NDT Inspection - [LFEC / HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551147		**Horizontal Stabilizer Outer Aft Spar, Left / Right E11.5 Horizontal Stabilizer Outer Rear Spar - Visual / NDT Inspection - [Visual / Tap Test]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551148		**Horizontal Stabilizer Outer Aft Spar, Left / Right E11.5 Horizontal Stabilizer Outer Rear Spar - Visual / NDT Inspection - [Visual / Tap Test]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551149		**Horizontal Stabilizer Rear Spar Splice, Left / Right E11.7 Horizontal Stabilizer Rear Spar Splice - NDT Inspection - [LFEC / X-ray]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551150		**Horizontal Stabilizer Rear Spar Splice, Left / Right E11.7 Horizontal Stabilizer Rear Spar Splice - NDT Inspection - [LFEC / X-ray]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551151		**Horizontal Stabilizer Rib 0 E13.1 Horizontal Stabilizer Rib 0 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551152		**Horizontal Stabilizer Rib 1, Left / Right E13.2 Horizontal Stabilizer Left and Right Rib 1 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
551153		**Horizontal Stabilizer Rib 2 - Rib 4, Left / Right E13.3, E13.4, E13.5 Horizontal Stabilizer Rib 2, Rib 3 and Rib 4 - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551154		**Horizontal Stabilizer Rib 2 - Rib 4, Left / Right E13.3, E13.4, E13.5 Horizontal Stabilizer Rib 2, Rib 3 and Rib 4 - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551155		**Horizontal Stabilizer Rib 2 - Rib 4, Left / Right E13.3, E13.4, E13.5 Horizontal Stabilizer Rib 2, Rib 3 and Rib 4 - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551156		**Horizontal Stabilizer Pivot Fitting E14.1 Horizontal Stabilizer Pivot Fitting - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551157		**Horizontal Stabilizer Rib 2 - Rib 3 Intercostal E14.2 Horizontal Stabilizer Rib 2 and Rib 3 Intercostal - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551158		**Horizontal Stabilizer Rib 2 - Rib 3 Intercostal E14.2 Horizontal Stabilizer Rib 2 and Rib 3 Intercostal - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551159		**Horizontal Stabilizer Actuator Backup Intercostal E14.3 Horizontal Stabilizer Actuator Backup Intercostal - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551161		**Elevator Actuator Rear Fitting E14.4 Elevator Actuator Rear Fitting - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551162		**Elevator Actuator Rear Fitting E14.4 Elevator Actuator Rear Fitting - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551163		**Elevator Actuator Front Fitting E14.5 Elevator Actuator Front Fitting - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
551164		**Elevator Actuator Front Fitting E14.5 Elevator Actuator Front Fitting - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551165		**Horizontal Stabilizer Flight Control Fittings 1 and 2 E14.7, E14.8 Horizontal Stabilizer Flight Control Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551166		**Horizontal Stabilizer Flight Control Fittings 1 and 2 E14.7, E14.8 Horizontal Stabilizer Flight Control Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551167		**Elevator Stop Fitting E14.9 Elevator Stop Fitting - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551168		**Horizontal Stabilizer Rib 1-1 Intercostal, Left / Right E13.6 Horizontal Stabilizer Rib 1-1 Intercostal - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-10-02 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551177		**Horizontal Stabilizer Scissors, Lower Brace Fitting E8.1 Horizontal Stabilizer Scissors Lower Brace Fitting - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-11-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551178		**Horizontal Stabilizer Scissors, Upper Brace E8.2 Horizontal Stabilizer Scissors Upper Brace - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-11-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551179		**Horizontal Stabilizer Scissors, Lower Brace E8.3 Horizontal Stabilizer Scissors Lower Brace - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-11-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551180		**Horizontal Stabilizer Scissors, Upper Brace Fitting E8.4, E8.5 Horizontal Stabilizer Scissors Upper Brace Fittings - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-11-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551181		**Horizontal Stabilizer Scissors, Upper Brace Fitting E8.4, E8.5 Horizontal Stabilizer Scissors Upper Brace Fittings - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-11-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
551182		**Horizontal Stabilizer Brace Backup Fitting E8.6 Horizontal Stabilizer Backup Brace Fitting - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-11-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551183		**Horizontal Stabilizer Upper Attachment E12.1, E12.2, E12.3 Horizontal Stabilizer Forward Attachment Fitting - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-11-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551184		**Horizontal Stabilizer Upper Attachment E12.1, E12.2, E12.3 Horizontal Stabilizer Forward Attachment Fitting - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-11-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
551185		**Horizontal Stabilizer Upper Attachment E12.1, E12.2, E12.3 Horizontal Stabilizer Forward Attachment Fitting - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-11-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552007		**Elevator Torsion Box Skins E16.6 Elevator Torsion Box Skins - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-20-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552008		**Elevator Torsion Box Skins E16.6 Elevator Torsion Box Skins - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-20-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552105		**Elevator Hinge Fittings E15.1, E15.2, E15.3, E15.4, E15.5, E15.6 Elevator To Horizontal Stabilizer Attachment Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552106		**Elevator Hinge Fittings E15.1, E15.2, E15.3, E15.4, E15.5, E15.6 Elevator To Horizontal Stabilizer Attachment Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552107		**Elevator Hinge Fittings E15.1, E15.2, E15.3, E15.4, E15.5, E15.6 Elevator To Horizontal Stabilizer Attachment Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552108		**Elevator Hinge Fittings E15.1, E15.2, E15.3, E15.4, E15.5, E15.6 Elevator To Horizontal Stabilizer Attachment Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
552109		**Elevator Hinge Fittings E15.1, E15.2, E15.3, E15.4, E15.5, E15.6 Elevator To Horizontal Stabilizer Attachment Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552110		**Elevator Hinge Fittings E15.1, E15.2, E15.3, E15.4, E15.5, E15.6 Elevator To Horizontal Stabilizer Attachment Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552111		**Elevator Hinge Fittings E15.1, E15.2, E15.3, E15.4, E15.5, E15.6 Elevator To Horizontal Stabilizer Attachment Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552112		**Elevator Hinge Fittings E15.1, E15.2, E15.3, E15.4, E15.5, E15.6 Elevator To Horizontal Stabilizer Attachment Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552113		**Elevator Hinge Fittings E15.1, E15.2, E15.3, E15.4, E15.5, E15.6 Elevator To Horizontal Stabilizer Attachment Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552114		**Elevator Hinge Fittings E15.1, E15.2, E15.3, E15.4, E15.5, E15.6 Elevator To Horizontal Stabilizer Attachment Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552115		**Elevator Hinge Fittings E15.1, E15.2, E15.3, E15.4, E15.5, E15.6 Elevator To Horizontal Stabilizer Attachment Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552116		**Elevator Hinge Fittings E15.1, E15.2, E15.3, E15.4, E15.5, E15.6 Elevator To Horizontal Stabilizer Attachment Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552121		**Elevator Fittings E16.1, E16.2, E16.3, E16.4 Elevator Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552122		**Elevator Fittings E16.1, E16.2, E16.3, E16.4 Elevator Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
552123		**Elevator Fittings E16.1, E16.2, E16.3, E16.4 Elevator Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552124		**Elevator Fittings E16.1, E16.2, E16.3, E16.4 Elevator Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552125		**Elevator Fittings E16.1, E16.2, E16.3, E16.4 Elevator Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552126		**Elevator Fittings E16.1, E16.2, E16.3, E16.4 Elevator Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552127		**Elevator Fittings E16.1, E16.2, E16.3, E16.4 Elevator Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
552128		**Elevator Fittings E16.1, E16.2, E16.3, E16.4 Elevator Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-21-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553021		**Vertical Stabilizer Front Spar E1.1 Vertical Stabilizer Front Spar - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553022		**Vertical Stabilizer Front Boomerang Fittings 1 and 2 E1.2 Vertical Stabilizer to Aft Fuselage Front Boomerang Attach Fittings - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553023		**Vertical Stabilizer Front Drag Fitting E1.4 Vertical Stabilizer to Aft Fuselage Front Drag Fittings - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553025		**Vertical Stabilizer Front Attach Strap E1.6, E1.7 Vertical Stabilizer Fuselage Front Attach Strap - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
553026		**Vertical Stabilizer Front Attach Strap E1.6, E1.7 Vertical Stabilizer Fuselage Front Attach Strap - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553027		**Vertical Stabilizer Mid Spar E2.1 Vertical Stabilizer Mid Spar - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553028		**Vertical Stabilizer Mid Boomerang Fittings 1 and 2 E2.2 Vertical Stabilizer to Aft Fuselage Mid Boomerang Attach Fittings - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553029		**Vertical Stabilizer Mid Attach Angle E2.6, E2.7 Vertical Stabilizer Fuselage Mid Attach Angle - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553030		**Vertical Stabilizer Mid Attach Angle E2.6, E2.7 Vertical Stabilizer Fuselage Mid Attach Angle - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553031		**Vertical Stabilizer Mid Drag Fitting E2.11 Vertical Stabilizer to Aft Fuselage Mid Drag Fittings - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553032		**Vertical Stabilizer Rear Spar E3.1 Vertical Stabilizer Rear Spar - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553033		**Vertical Stabilizer Rear Boomerang Fittings 1 and 2 E3.2 Vertical Stabilizer to Aft Fuselage Rear Boomerang Attach Fittings - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553034		**Vertical Stabilizer Rear Drag Fitting E3.3 Vertical Stabilizer to Aft Fuselage Rear Drag Fittings - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553035		**Vertical Stabilizer Rear Attach Angle E3.7 Vertical Stabilizer Fuselage Rear Attach Angle - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
553037		**Vertical Stabilizer Shear Deck, Front and Rear Lower, Rib 0 E4.1, E4.2 Vertical Stabilizer Front and Rear Lower Shear Deck Rib 0 - NDT / Visual Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553038		**Vertical Stabilizer Shear Deck, Front and Rear Lower, Rib 0 E4.1, E4.2 Vertical Stabilizer Front and Rear Lower Shear Deck Rib 0 - NDT / Visual Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553039		**Vertical Stabilizer Shear Deck, Front, Rib 1 E4.3 Vertical Stabilizer Front Rib 1 - NDT / Visual Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553040		**Vertical Stabilizer Shear Deck, Rear, Rib 2 E4.4 Vertical Stabilizer Rear Rib 2 - NDT / Visual Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553041		**Vertical Stabilizer Rear Rib 6 E4.5 Vertical Stabilizer Rear Rib 6 - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553042		**Vertical Stabilizer Rear Rib 10 E4.6 Vertical Stabilizer Rear Rib 10 - NDT / Visual Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553043		**Vertical Stabilizer Fitting, Rear Rib 10 E4.7 Vertical Stabilizer Rear Rib 10 Fitting - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553044		**Vertical Stabilizer Shear Deck, Upper, Rib 12 E4.8 Vertical Stabilizer Upper Shear Deck Rib 12 - NDT / Visual Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553045		**Horizontal Stabilizer Trim Actuator Fittings E5.1, E5.2 Vertical Stabilizer Lower Horizontal Stabilizer Trim Actuator Fittings - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553046		**Horizontal Stabilizer Trim Actuator Fittings E5.1, E5.2 Vertical Stabilizer Lower Horizontal Stabilizer Trim Actuator Fittings - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
553047		**Vertical Stabilizer Mid Spar Flight Control Fittings E5.3, E5.4 Vertical Stabilizer Upper and Lower Flight Control Fittings - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553048		**Vertical Stabilizer Mid Spar Flight Control Fittings E5.3, E5.4 Vertical Stabilizer Upper and Lower Flight Control Fittings - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553049		**Front Rudder Actuator Fittings 1 and 2 E5.5 Vertical Stabilizer Mid Spar Forward Rudder Actuator Fittings - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553050		**Rear Rudder Actuator Fittings 1 and 2 E5.6 Vertical Stabilizer Rear Spar Rudder Actuator Fittings - NDT Inspecton - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553051		**Vertical Stabilizer Composite Skins E7.1, E7.2 Vertical Stabilizer Composite Skin - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553052		**Vertical Stabilizer Composite Skins E7.1, E7.2 Vertical Stabilizer Composite Skin - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-30-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553121		**Upper Rudder Hinge Fittings 1 and 2 E3.13 Vertical Stabilizer Rear Spar Upper Rudder Hinge Fitting 1 and Fitting 2 - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-31-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553122		**Mid Rudder Hinge Fittings 1 and 2 E3.14 Vertical Stabilizer Rear Spar Mid Rudder Hinge Fitting 1 and Fitting 2 - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-31-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553123		**Lower Rudder Hinge Fittings 1 and 2 E3.15 Vertical Stabilizer Rear Spar Lower Rudder Hinge Fitting 1 and Fitting 2 - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-31-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553124		**Vertical Stabilizer Pivot Fittings E5.7 Vertical Stabilizer Pivot Fittings - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-31-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
553125		**Left / Right Primary Sleeve Pivot E6.3, E6.4 Horizontal to Vertical Stabilizer Primary Sleeve Pivot - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-31-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553126		**Left / Right Primary Sleeve Pivot E6.3, E6.4 Horizontal to Vertical Stabilizer Primary Sleeve Pivot - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-31-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
553127		**Secondary Sleeve Pivot E6.5 Horizontal to Vertical Stabilizer Secondary Sleeve Pivot - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-31-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
554011		**Rudder Torsion Box E17.6 Rudder Torsion Box - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-40-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
554111		**Rudder Fittings E17.1, E17.2, E17.3 Rudder Fittings - Visual or NDT Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-41-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
554112		**Rudder Fittings E17.1, E17.2, E17.3 Rudder Fittings - Visual or NDT Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-41-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
554113		**Rudder Fittings E17.1, E17.2, E17.3 Rudder Fittings - Visual or NDT Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-41-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
554114		**Rudder Actuator Fittings E17.4, E17.5 Rudder Actuator Fittings - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-41-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
554115		**Rudder Actuator Fittings E17.4, E17.5 Rudder Actuator Fittings - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	55 A/F						Mos					
							Hrs					
	ATA Ref:55-41-01 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
570221		**Front Spar Splice CP1 Front Spar Splice - Visual / NDT Inspection - [LFEC / HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-02-00 (ZONE: W1.1, W1.2, W1.3, W4.1) (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
570222		**Front Spar Splice CP1 Front Spar Splice - Visual / NDT Inspection - [LFEC / HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W1.1, W1.2, W1.3, W4.1) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
570223		**Front Spar Web Penetrations CP2 Front Spar Web Penetrations - Visual / NDT Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W1.1, W1.2) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
570224		**Front Spar Web Penetrations CP2 Front Spar Web Penetrations - Visual / NDT Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W1.1, W1.2) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
570225		**Rear Spar Splice CP3 Rear Spar Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W2.1, W2.2, W2.3, W4.3) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
570226		**Rear Spar Splice CP3 Rear Spar Splice - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W2.1, W2.2, W2.3, W4.3) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
570227		**Rear Spar Web Penetrations CP4 Rear Spar Web Penetrations - Visual / NDT Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W2.1, W2.2) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
570228		**Rear Spar Web Penetrations CP4 Rear Spar Web Penetrations - Visual / NDT Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W2.1, W2.2) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
570229		**Lower Skin Splice at Front Spar, BL 0 CP5 Lower Skin Splice at Front Spar BL 0 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W1.1, W4.1, W4.4) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
570230		**Lower Skin Splice at Front Spar, BL 0 CP5 Lower Skin Splice at Front Spar BL 0 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W1.1, W4.1, W4.4) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
570231		**Lower Skin Splice at Rear Spar, BL 0 CP6 Lower Skin Splice at Rear Spar BL 0 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W2.1, W4.3, W4.4) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
570232		**Lower Skin Splice at Rear Spar, BL 0 CP6 Lower Skin Splice at Rear Spar BL 0 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W2.1, W4.3, W4.4) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
570233		**Lower Spar Caps and Stiffeners CP8 Front and Rear Lower Spar Caps and Stiffeners - Visual / NDT Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W1.1, W1.2, W2.1, W2.2, W4.1, W4.2, W4.3) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
570234		**Lower Spar Caps and Stiffeners CP8 Front and Rear Lower Spar Caps and Stiffeners - Visual / NDT Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W1.1, W1.2, W2.1, W2.2, W4.1, W4.2, W4.3) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
570235		**Lower Skin and Lower Stringers CP9 Lower Skin and Lower Stringer - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W5.1, W5.2, W5.3) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
570236		**Lower Skin and Lower Stringers CP9 Lower Skin and Lower Stringer - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W5.1, W5.2, W5.3) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
570237		**Lower Skin Stringer Runouts CP10 Lower Skin and Lower Stringer Runouts - Visual / NDT Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W4.1, W4.2, W4.3, W5.1, W5.2, W5.3) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
570238		**Lower Skin Stringer Runouts CP10 Lower Skin and Lower Stringer Runouts - Visual / NDT Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W4.1, W4.2, W4.3, W5.1, W5.2, W5.3) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
570239		**Lower Skin Access Cutouts CP11 Lower Skin Access Cutouts - Visual / NDT Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W4.2) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
570240		**Lower Skin Access Cutouts CP11 Lower Skin Access Cutouts - Visual / NDT Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-02-00 (ZONE: W4.2) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571003		**Lower Skin Splice, Stringer Runouts, and Drain Holes at BL 0 CP7, CP12 BL 0 Lower Skin Splice, Stringer Runouts and Drain Holes - NDT / Visual Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-10-00 (ZONE: W4.1, W4.2, W4.3, W4.4, W5, W7.1) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
571004		**Lower Skin Splice, Stringer Runouts, and Drain Holes at BL 0 CP7, CP12 BL 0 Lower Skin Splice, Stringer Runouts and Drain Holes - NDT / Visual Inspection - [HFEC / Visual]**					T			05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F					Mos					
						Hrs					
	ATA Ref:57-10-00 (ZONE: W4.1, W4.2, W4.3, W4.4, W5, W7.1) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571005		**Rib 0 CP36 Rib 0 - Visual / NDT Inspection - [LFEC / HFEC / Visual]**					T			05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F					Mos					
						Hrs					
	ATA Ref:57-10-00 (ZONE: W1.1, W2.1, W7.1, W7.5) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571007		**Rib 1 CP37 Rib 1 - Visual / NDT Inspection - [HFEC / Visual]**					T			05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F					Mos					
						Hrs					
	ATA Ref:57-10-00 (ZONE: W1.1, W2.1, W7.2) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571008		**Rib 1 CP37 Rib 1 - Visual / NDT Inspection - [HFEC / Visual]**					T			05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F					Mos					
						Hrs					
	ATA Ref:57-10-00 (ZONE: W1.1, W2.1, W7.2) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571009		**Rib 2 CP38 Rib 2 - Visual / NDT Inspection - [HFEC / Visual]**					T			05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F					Mos					
						Hrs					
	ATA Ref:57-10-00 (ZONE: W1.1, W2.1, W7.3) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571010		**Rib 2 CP38 Rib 2 - Visual / NDT Inspection - [HFEC / Visual]**					T			05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F					Mos					
						Hrs					
	ATA Ref:57-10-00 (ZONE: W1.1, W2.1, W7.3) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571011		**Main Landing Gear Actuator and Side Brace Attachments and Backup Structure CP19 Main Landing Gear Actuator and Side Brace Fittings - Visual / NDT Inspection - [HFEC / Visual]**					T			05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F					Mos					
						Hrs					
	ATA Ref:57-10-00 (ZONE: W2.1, W4.3, W8.4, W8.5, W8.6) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571012		**Main Landing Gear Actuator and Side Brace Attachments and Backup Structure CP19 Main Landing Gear Actuator and Side Brace Fittings - Visual / NDT Inspection - [HFEC / Visual]**					T			05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F					Mos					
						Hrs					
	ATA Ref:57-10-00 (ZONE: W2.1, W4.3, W8.4, W8.5, W8.6) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571013		**Rib 5 Forward Radius CP41 Rib 5 - NDT Inspection - [HFEC]**					T			05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F					Mos					
						Hrs					
	ATA Ref:57-10-00 (ZONE: W7.4) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571014		**Rib 5 Forward Radius CP41 Rib 5 - NDT Inspection - [HFEC]**					T			05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F					Mos					
						Hrs					
	ATA Ref:57-10-00 (ZONE: W7.4) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
571015		**Butterfly Clips at Rib 0, Rib 1, and Rib 2 CP53 Butterfly Clips of Rib 0 - Rib 2 - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-10-00 (ZONE: W24.1, W24.2, W24.3) (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571016		**Butterfly Clips at Rib 0, Rib 1, and Rib 2 CP53 Butterfly Clips of Rib 0 - Rib 2 - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-10-00 (ZONE: W24.1, W24.2, W24.3) (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571625		**Wing-to-Fuselage Left Fitting, Frame 29 CF16.1 Wing Attachment Fitting Left Frame 29 - NDT Inspection - [HFEC / Ultrasonic]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-16-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571626		**Wing-to-Fuselage Right Fitting, Frame 29 CF16.2 Wing Attachment Fitting Right Frame 29 - NDT Inspection - [HFEC / Ultrasonic]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-16-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571627		**Wing-to-Fuselage Right Fitting, Frame 38 CF16.3 Wing Attachment Fitting Vertical Frame 38 - NDT Inspection - [HFEC / Ultrasonic]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-16-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571628		**Wing-to-Fuselage Left Fitting, Frame 38 CF16.4 Wing Attachment Fitting Horizontal Frame 38 - NDT Inspection - [HFEC / Ultrasonic]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-16-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571629		**Wing-to-Fuselage Connection Forward Drag Link, Frame 28 - Frame 29 CF18.1 Wing to Fuselage Attachment Forward Drag Link Between Frame 28 and Frame 29 - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-16-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571630		**Wing-to-Fuselage Connection Forward Right Link, Frame 29 CF18.2 Wing to Fuselage Attachment Forward Link Right Frame 29 - NDT Inspection - [HFEC / Ultrasonic]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-16-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571631		**Rear Vertical Wing-to-Fuselage Connection Link, Frame 38 CF18.5 Wing to Fuselage Attachment Rear Vertical Link Frame 38 - NDT Inspection - [HFEC / Ultrasonic]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-16-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571632		**Forward and Aft Horizontal Wing-to- Fuselage Connection Link, Frame 38 CF18.3, CF18.4, CF18.7 - CF18.10 Wing to Fuselage Attachment Rear Horizontal Link Frame 38 - NDT Inspection - [HFEC / Ultrasonic]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-16-00 (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
571633		**Forward and Aft Horizontal Wing-to- Fuselage Connection Link, Frame 38 CF18.3, CF18.4, CF18.7 - CF18.10 Wing to Fuselage Attachment Rear Horizontal Link Frame 38 - NDT Inspection - [HFEC / Ultrasonic]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-16-00 (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571634		**Forward and Aft Horizontal Wing-to- Fuselage Connection Link, Frame 38 CF18.3, CF18.4, CF18.7 - CF18.10 Wing to Fuselage Attachment Rear Horizontal Link Frame 38 - NDT Inspection - [HFEC / Ultrasonic]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-16-00 (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571635		**Forward and Aft Horizontal Wing-to- Fuselage Connection Link, Frame 38 CF18.3, CF18.4, CF18.7 - CF18.10 Wing to Fuselage Attachment Rear Horizontal Link Frame 38 - NDT Inspection - [HFEC / Ultrasonic]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-16-00 (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571636		**Forward and Aft Horizontal Wing-to- Fuselage Connection Link, Frame 38 CF18.3, CF18.4, CF18.7 - CF18.10 Wing to Fuselage Attachment Rear Horizontal Link Frame 38 - NDT Inspection - [HFEC / Ultrasonic]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-16-00 (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571637		**Forward and Aft Horizontal Wing-to- Fuselage Connection Link, Frame 38 CF18.3, CF18.4, CF18.7 - CF18.10 Wing to Fuselage Attachment Rear Horizontal Link Frame 38 - NDT Inspection - [HFEC / Ultrasonic]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-16-00 (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571638		**Wing-to-Fuselage Forward Attachments CP13, CP14 Wing To Fuselage Forward Attachments - Visual / NDT Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-16-00 (ZONE: W1.1, W6.1, W6.2) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571639		**Wing-to-Fuselage Forward Attachments CP13, CP14 Wing To Fuselage Forward Attachments - Visual / NDT Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-16-00 (ZONE: W1.1, W6.1, W6.2) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571640		**Wing-to-Fuselage Forward Attachments CP13, CP14 Wing To Fuselage Forward Attachments - Visual / NDT Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-16-00 (ZONE: W1.1, W6.1, W6.2) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571641		**Wing-to-Fuselage Aft Fittings CP15, CP16 Wing To Fuselage Aft Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-16-00 (ZONE: W2.1, W6.3, W6.4) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571642		**Wing-to-Fuselage Aft Fittings CP15, CP16 Wing To Fuselage Aft Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-16-00 (ZONE: W2.1, W6.3, W6.4) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
571643		**Wing-to-Fuselage Aft Fittings CP15, CP16 Wing To Fuselage Aft Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-16-00 (ZONE: W2.1, W6.3, W6.4) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571645		**Wing-to-Fuselage Drag Link Fitting CP17 Wing Drag Link Fitting - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-16-00 (ZONE: W1.1, W6.5) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
571646		**Wing-to-Fuselage Drag Link Fitting CP17 Wing Drag Link Fitting - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-16-00 (ZONE: W1.1, W6.5) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575015		**Spoiler No. 1 Fittings and Backup Structure CP25 Spoiler No. 1 Fittings and Backup Structure - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W2.2, W14.1, W23.1, W23.2, W23.3, W23.4, W23.5) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575016		**Spoiler No. 2 Fittings and Backup Structure CP26 Spoiler No. 2 Fittings and Backup Structure - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W2.2, W15.1, W23.6, W23.7, W23.8, W23.9, W23.10) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575017		**Spoiler No. 3 Fittings and Backup Structure CP27 Spoiler No. 3 Fittings and Backup Structure - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W2.2, W16.1, W23.6, W23.11, W23.12, W23.13, W23.14) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575018		**Aileron Inboard Fittings and Backup Structure CP28 Aileron Inboard Fittings and Backup Structure - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W2.2, W17.1, W17.2, W17.3) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575019		**Aileron Mid Fittings and Backup Structure CP29 Aileron Mid Fittings and Backup Structure - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W2.2, W18.1, W18.2, W18.3) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575020		**Aileron Outboard Fittings and Backup Structure CP30 Aileron Outboard Fittings and Backup Structure - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W2.2, W19.1, W19.2, W19.3) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575021		**Aileron Trim Tab Inboard Fittings CP31 Aileron Trim Tab Inboard Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W20.1, W20.2) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
575022		**Aileron Trim Tab Outboard Fittings CP32 Aileron Trim Tab Outboard Fittings - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-50-00 (ZONE: W20.3, W20.4) (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575023		**Aileron Gear Tab Inboard Fittings CP33 Aileron Gear Tab Inboard Fitting - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-50-00 (ZONE: W21.1, W21.2) (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575024		**Aileron Gear Tab Outboard Fittings CP34 Aileron Gear Tab Outboard Fitting - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-50-00 (ZONE: W21.3, W21.4) (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575027		**Flap Tracks A and D Flanges ,Roller Fittings and Support Structure CP20, CP23 Flap Tracks A and D Flanges and Roller Fittings (Left) - NDT Inspection - [BHEC / HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-50-00 (ZONE: W9.1, W9.6, W9.7, W12.1, W12.6, W12.7) (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575028		**Flap Tracks A and D Flanges ,Roller Fittings and Support Structure CP20, CP23 Flap Tracks A and D Flanges and Roller Fittings (Right) - NDT Inspection - [BHEC / HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-50-00 (ZONE: W9.1, W9.6, W9.7, W12.1, W12.6, W12.7) (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575035		**Flap Track A Support and Ribs CP20 Flap Track A Support and Ribs - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-50-00 (ZONE: W9.1, W9.2, W9.4, W9.8, W9.9) (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575036		**Flap Track A Support and Ribs CP20 Flap Track A Support and Ribs - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-50-00 (ZONE: W9.1, W9.2, W9.4, W9.8, W9.9) (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575037		**Flap Track B and Backup Structure CP21 Flap Track B and Backup Structure - NDT Inspection - [BHEC / HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-50-00 (ZONE: W10.1,10.2,10.4,10.6,10.7,10.8,10.9,10.10,10.11) (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575038		**Flap Track B and Backup Structure CP21 Flap Track B and Backup Structure - NDT Inspection - [BHEC / HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-50-00 (ZONE: W10.1,10.2,10.4,10.6,10.7,10.8,10.9,10.10,10.11) (SOURCE: G280 AMM)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575043		**Flap Track C and Backup Structure CP22 Flap Track C and Backup Structure - NDT Inspection - [BHEC / HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
	ATA Ref:57-50-00 (ZONE: W11.1,W11.2,W11.4,W11.6,W11.7,) (SOURCE: G280 AMM) (NOTE: Zone continued: W11.8,W11.9,W11.10,W11.11)						Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
575044		**Flap Track C and Backup Structure CP22 Flap Track C and Backup Structure - NDT Inspection - [BHEC / HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W11.1,W11.2,W11.4,W11.6,W11.7,) (SOURCE: G280 AMM) (NOTE: Zone continued: W11.8,W11.9,W11.10,W11.11)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575051		**Flap Track D Support and Ribs CP23 Flap Track D Support and Ribs - NDT Inspection - [BHEC / HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W12.1, W12.2, W12.4, W12.8, W12.9) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575052		**Flap Track D Support and Ribs CP23 Flap Track D Support and Ribs - NDT Inspection - [BHEC / HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W12.1, W12.2, W12.4, W12.8, W12.9) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575059		**Flap Forward Spar CP24 Flap Forward Spar - NDT / Visual Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W13.1, W25.1) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575060		**Flap Forward Spar CP24 Flap Forward Spar - NDT / Visual Inspection - [HFEC / Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W13.1, W25.1) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575065		**Spoiler No. 1 Fittings and Backup Structure CP25 Spoiler No. 1 Fittings and Backup Structure - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W2.2, W14.1, W23.1, W23.2, W23.3, W23.4, W23.5) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575066		**Spoiler No. 2 Fittings and Backup Structure CP26 Spoiler No. 2 Fittings and Backup Structure - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W2.2, W15.1, W23.6, W23.7, W23.8, W23.9, W23.10) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575067		**Spoiler No. 3 Fittings and Backup Structure CP27 Spoiler No. 3 Fittings and Backup Structure - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W2.2, W16.1, W23.6, W23.11, W23.12, W23.13, W23.14) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575068		**Aileron Inboard Fittings and Backup Structure CP28 Aileron Inboard Fittings and Backup Structure - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W2.2, W17.1, W17.2, W17.3) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575069		**Aileron Mid Fittings and Backup Structure CP29 Aileron Mid Fittings and Backup Structure - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W2.2, W18.1, W18.2, W18.3) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
575070		**Aileron Outboard Fittings and Backup Structure CP30 Aileron Outboard Fittings and Backup Structure - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W2.2, W19.1, W19.2, W19.3) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575073		**Aileron Gear Tab Inboard Fittings CP33 Aileron Gear Tab Inboard Fitting - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W21.1, W21.2) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575074		**Aileron Gear Tab Outboard Fittings CP34 Aileron Gear Tab Outboard Fitting - Visual Inspection - [Visual]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W21.3, W21.4) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575109		**Main Landing Gear Sponson CP18 Main Landing Gear Sponson and Attachments To Torsion Box - NDT Inspection - [BHEC / HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-51-00 (ZONE: W2.1, W4.3, W8.1, W8.2) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
575110		**Main Landing Gear Sponson CP18 Main Landing Gear Sponson and Attachments To Torsion Box - NDT Inspection - [BHEC / HFEC]**							T		05-10-10 Airworthiness Limitations	**≈30-Mar-2044**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-51-00 (ZONE: W2.1, W4.3, W8.1, W8.2) (SOURCE: G280 AMM)					Ldg		10,000	+5%	10,000	9,382 Ldg (+500)
▼ 1. T 12 Mos | 2. RE -												
2023-14-10 Par. (h)		**Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - New Mandatory Terminating Action**							RE (-)		Mandatory (Appliance AD)	
	25 A/F						Mos	10-Aug-2023				
	Eff: 07-Sep-2023 Not Applicable						Hrs					
		(UPDATE NOTE: N/A by SN of the pilot/co-pilot seats) (NOTE: COMPLIANCE: As a mandatory terminating action to the inspections required by paragraph (g)(2)(i) of this AD, within 12 months after the effective date of this AD, or at the next Base Maintenance check, whichever occurs later, modify and re-identify each affected seat in accordance with the Accomplishment Instructions of Ipeco SB Number 063-25-15, Issue 2; SB Number 063-25-16, Issue 2; SB Number 063-25-17, Issue 2; or SB Number 063-25-18, Issue 2; all dated March 8, 2022, as applicable to each affected seat.)					Ldg					
2024-0024		**Navigation - Digital Air Data Computer - Replacement**							RE (-)		Mandatory (Appliance AD)	
	34 A/F						Mos	27-May-2024				
	Eff: 07-Feb-2024 Not Applicable	affected P/N not installed					Hrs	842:13				
							Ldg	496				
		(NOTE: COMPLIANCE: For Group 1 aircraft: Within 12 months after the effective date of this AD, remove each affected part from service and replace it with a serviceable part in accordance with the instructions of the SB.)										
2015-23-09 Para (i)		**Oxygen - Regulator Replacement**							RE (-)		Mandatory (Appliance AD)	
	35 A/F						Mos	10-Feb-2023				
	Eff: 28-Dec-2015 Not Applicable	PER REGULATOR P/N					Hrs	24:24				
							Ldg	7				
▼ 1. T 12 Mos, 500 Hrs | 2. RE 6 Mos, 500 Hrs												
243305		**Main Battery - Functional Check (Capacity)**							RE	05-20-00 Scheduled Maintenance Checks		
	24 A/F RG-380E/53GH-6 41280033	Left					Mos	26-Jul-2024	6	-/+1m	31-Jan-2025	4.8 Months (+28 Days)
							Hrs	967:25	500	-/+50	1467:25	409:25 Hrs (+50)
		ATA Ref:24-33-01, MRB Ref:24-30-00/01 (SOURCE: G280 AMM) (NOTE: NOTE: Perform initial at 1A or 1C, whichever occurs first and every 1A or 6 months whichever occurs first, thereafter.)					Ldg	562				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
243306	**Main Battery - Functional Check (Capacity)**							RE	05-20-00 Scheduled Maintenance Checks		
24 A/F	Right					Mos	26-Jul-2024	6	-/+1m	31-Jan-2025	4.8 Months (+28 Days)
RG-380E/53GH-6											
41284436						Hrs	967:25	500	-/+50	1467:25	409:25 Hrs (+50)
	ATA Ref:24-33-01, MRB Ref:24-30-00/01 (SOURCE: G280 AMM) (NOTE: NOTE: Perform initial at 1A or 1C, whichever occurs first and every 1A or 6 months whichever occurs first, thereafter.)					Ldg	562				
▼ 1. T 12 Mos, 750 Hrs | 2. RE -										Man Hours: 1	
2017-22-14	**Navigation - Upgrade the Rockwell Collins, Inc. TSSA-4100 FLS to RCPN 810-0052-013 or 810-0052-102**							RE (-)	Mandatory (Appliance AD)		
34 A/F						Mos	10-Feb-2023				
Eff: 20-Dec-2017 Complied With	IAI MOD25-20133, INCORPORATED IN PRODUCTION. UPGRADED THE TSSA-4100 FLS TO RCPN 810-0052-102.					Hrs	24:24				
						Ldg	7				
	(AVG MAN HRS: 1) (NOTE: NOTE: Refer to Rockwell Collins Service Information Letter, TSSA-4100-SIL-10-1, Revision No. 9, dated March 31, 2017; or Rockwell Collins Service Information Letter TSSA-4100-SIL-10-1, Revision No. 10, dated July 10, 2017.)										
▼ 1. T 144 Mos | 2. RE 96 Mos											
276011	**Spoiler and Hinge - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
27 A/F						Mos		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
	ATA Ref:27-60-00, MRB Ref:57.70.00/01 (SOURCE: G280 AMM)					Hrs					
						Ldg					
276012	**Spoiler and Hinge - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
27 A/F						Mos		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
	ATA Ref:27-60-00, MRB Ref:57.70.00/01 (SOURCE: G280 AMM)					Hrs					
						Ldg					
575003	**Flap Tracks, Supports and Rollers - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
57 A/F						Mos		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
	ATA Ref:57-50-00, MRB Ref:57.53.00/01 (SOURCE: G280 AMM)					Hrs					
						Ldg					
575004	**Flap Tracks, Supports and Rollers - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
57 A/F						Mos		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
	ATA Ref:57-50-00, MRB Ref:57.53.00/01 (SOURCE: G280 AMM)					Hrs					
						Ldg					
576007	**Aileron Hinge and Clevises - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
57 A/F						Mos		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
	ATA Ref:57-60-00, MRB Ref:57.50.01/01 (SOURCE: G280 AMM)					Hrs					
						Ldg					
576008	**Aileron Hinge and Clevises - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
57 A/F						Mos		144	-/+1m	31-Mar-2035	10.6 Years (+30 Days)
	ATA Ref:57-60-00, MRB Ref:57.50.01/01 (SOURCE: G280 AMM)					Hrs					
						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 1. T 15000 Ldg | 2. RE -											
530010	**Aircraft Design Service Life**							T		05-10-10 Airworthiness Limitations	**≈07-Sep-2054**
53 A/F						Mos					
						Hrs					
(SOURCE: G280 AMM)						Ldg		15,000		15,000	14,382 Ldg
▼ 1. T 18 Mos, 400 Hrs | 2. RE -											
280-76-232	**Engine Controls - Power Controls - Apply Sealant to Prevent Water Entry Into Electronic Control Unit (ECU) on AS907 Model Engines**							RE (-)		Mandatory	
76 ENG1						Mos	10-Feb-2023				
Eff: 13-May-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs					
						Enc					
(NOTE: EFFECTIVITY: Aircraft Serial Numbers 2001 through 2090. COMPLIANCE: Compliance with this service bulletin is mandatory at the next suitable planned maintenance period within 400 engine operating hours, not to exceed 18 months, from the original release date of Honeywell SB AS907-76-9021 dated May 13, 2016.)											
280-76-232	**Engine Controls - Power Controls - Apply Sealant to Prevent Water Entry Into Electronic Control Unit (ECU) on AS907 Model Engines**							RE (-)		Mandatory	
76 ENG2						Mos	17-Apr-2023				
Eff: 13-May-2016 Not Applicable	as per a/c S/N					Hrs	117:47				
						Enc	76				
(NOTE: EFFECTIVITY: Aircraft Serial Numbers 2001 through 2090. COMPLIANCE: Compliance with this service bulletin is mandatory at the next suitable planned maintenance period within 400 engine operating hours, not to exceed 18 months, from the original release date of Honeywell SB AS907-76-9021 dated May 13, 2016.)											
▼ 1. T 192 Mos | 2. RE -											
280-23-320	**Communications - Inspection and Replacement of VIASAT GAT-5510 Ka-Band Antenna**							RE (-)		Recommended	
23 A/F						Mos	29-Nov-2023		-/+1m		
Not Applicable						Hrs					
(UPDATE NOTE: N/A by SN of the aircraft) (NOTE: EFFECTIVITY: Please refer to Par. 1.A. of this SB for more information. COMPLIANCE: Compliance with this service bulletin is recommended at the first access to the Ka-band antenna and not to exceed a 16C check.)						Ldg					
▼ 1. T 192 Mos | 2. RE 144 Mos											
523110	**Baggage Door (Internal) - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
52 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
ATA Ref:52-31-01, MRB Ref:52.30.00/02 (SOURCE: G280 AMM)						Hrs					
						Ldg					
531206	**Cockpit Side Console (Internal) - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
ATA Ref:53-12-01, MRB Ref:53.11.00/03 (SOURCE: G280 AMM)						Hrs					
						Ldg					
531207	**Cockpit Structure Below Floor - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
ATA Ref:53-12-01, MRB Ref:53.11.00/07 (SOURCE: G280 AMM)						Hrs					
						Ldg					
531211	**Cockpit Floor Structure - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
53 A/F						Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
ATA Ref:53-12-01, MRB Ref:53.11.00/06 (SOURCE: G280 AMM)						Hrs					
						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
531213		**Cockpit Internal Structure (Above Floor to Window Sill) - General Visual Inspection**							T	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-12-01, MRB Ref:53.11.00/02 (SOURCE: G280 AMM)					Hrs					
							Ldg					
531214		**Cockpit Window Skin (Internal) - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-12-02, MRB Ref:53.17.00/02 (SOURCE: G280 AMM)					Hrs					
							Ldg					
531216		**Cockpit Upper Structure (Internal) - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-12-02, MRB Ref:53.17.00/05 (SOURCE: G280 AMM)					Hrs					
							Ldg					
531220		**Cockpit Forward Floor Panels - General Visual Inspection**							T	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-12-01, MRB Ref:53.11.00/04 (SOURCE: G280 AMM)					Hrs					
							Ldg					
531221		**Cockpit Floor Surface - General Visual Inspection**							T	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-12-01, MRB Ref:53.11.00/05 (SOURCE: G280 AMM)					Hrs					
							Ldg					
532115		**Auxiliary Pressure Bulkhead Forward and Aft Faces - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-21-02, MRB Ref:53.05.00/01 (SOURCE: G280 AMM)					Hrs					
							Ldg					
532116		**Auxiliary Pressure Bulkhead Forward and Aft Composite Faces - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
53 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:53-21-02, MRB Ref:53.05.00/02 (SOURCE: G280 AMM)					Hrs					
							Ldg					
551113		**Horizontal Stabilizer Upper and Lower Fittings (Horizontal Stabilizer Installed) - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:55-11-01, MRB Ref:55.02.00/05 (SOURCE: G280 AMM)					Hrs					
							Ldg					
551114		**Horizontal Stabilizer Attachment Points to Vertical Stabilizer (Horizontal Stabilizer Installed) - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:55-11-01, MRB Ref:55.02.00/02 (SOURCE: G280 AMM)					Hrs					
							Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
551116		**Horizontal Stabilizer Internal Box Structure - General Visual Inspection**							T	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:55-11-01, MRB Ref:55.11.00/03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
552103		**Elevator Hinge Points (Elevator Installed) (Left) - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:55-21-01, MRB Ref:55.02.00/03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
552104		**Elevator Hinge Points (Elevator Installed) (Right) - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:55-21-01, MRB Ref:55.02.00/03 (SOURCE: G280 AMM)					Hrs					
							Ldg					
553105		**Vertical Stabilizer Attach Points (Vertical Stabilizer Installed) - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:55-31-01, MRB Ref:55.02.00/01 (SOURCE: G280 AMM)					Hrs					
							Ldg					
554102		**Rudder Hinge Points (Rudder Installed) - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
55 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:55-41-01, MRB Ref:55.02.00/04 (SOURCE: G280 AMM)					Hrs					
							Ldg					
575107		**Main Landing Gear Support - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-51-00, MRB Ref:57.14.00/02 (SOURCE: G280 AMM)					Hrs					
							Ldg					
575108		**Main Landing Gear Support - Detailed Inspection**							T	05-20-00 Scheduled Maintenance Checks		
57 A/F							Mos		192	-/+1m	31-Mar-2039	14.6 Years (+30 Days)
		ATA Ref:57-51-00, MRB Ref:57.14.00/02 (SOURCE: G280 AMM)					Hrs					
							Ldg					
▼ 1. T 2 Yrs | 2. RE -												
2023-14-10 Par. (g)(1)		**Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Modify and Re-Identify each Affected Pilot and Co-Pilot Seat**							RE (-)	Mandatory (Appliance AD)		
25 A/F							Yrs	10-Aug-2023				
		Eff: 12-Dec-2017 Not Applicable					Hrs					
		(UPDATE NOTE: N/A by SN of the pilot/co-pilot seats) (NOTE: COMPLIANCE: For seats that have not installed the track lock spring modification kit, within two years after December 12, 2017 (the effective date of AD 2017-22-02, Amendment 39-19082 (82 FR 51552, November 7, 2017)), modify and re-identify each affected pilot and co-pilot seat using the Accomplishment Instructions of Ipeco SB Number 063-25-08, Revision 00; Ipeco SB Number 063-25-09, Revision 00; or Ipeco SB Number 063-25-10, Revision 00; all dated May 31, 2016, as applicable to each affected seat.)					Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 1. T 2000 Hrs | 2. RE -											
AS907-76-9017	**ENGINE CONTROLS - EMERGENCY SHUTDOWN - Replace Potentially Non-Conforming Overspeed Shutoff Detector (OSSD) on AS907 Engines**							RE (-)			
76 ENG1						Mos	10-Feb-2023				
Eff: 08-Jan-2016 Not Applicable	PER S/N. INCORPORATED IN PRODUCTION					Hrs					
						Enc					
AS907-76-9017	**ENGINE CONTROLS - EMERGENCY SHUTDOWN - Replace Potentially Non-Conforming Overspeed Shutoff Detector (OSSD) on AS907 Engines**							RE (-)			
76 ENG2						Mos	10-Feb-2023				
Eff: 08-Jan-2016 Not Applicable	PER S/N. INCORPORATED IN PRODUCTION					Hrs					
						Enc					
▼ 1. T 24 Mos | 2. RE -										Man Hours: 27+	
2020-21-02	**Fire protection - Kidde Aerospace & Defense - Cargo Fire Extinguisher Halon Bottles**							RE (-)	Mandatory (Appliance AD)		
26 A/F						Mos	10-Feb-2023				
Eff: 19-Nov-2020 Not Applicable	NOT INSTALLED					Hrs	24:24				
						Ldg	7				
280-27-324	**Flight Controls - Rudder Servo Actuator - Replacement**							RE (-)	Recommended		
27 A/F						Mos	26-Jul-2024				
Eff: 26-Jul-2023 Complied With						Hrs	967:25				
(AVG MAN HRS: 15) (NOTE: EFFECTIVITY: Please refer to Par. 1 of this SB for more information. COMPLIANCE: Compliance with this service bulletin is recommended in the next 24 months after the original release date of this service bulletin.)						Ldg	562				
2014-18-01	**Rockwell Collins, Inc. - Navigation - inspect the airplane type code category strapping setting for a value of zero (0) or one (1) following Rockwell Collins, Inc. Service Information Letter 07-2, 523-0810069-101000, TDR-94() SIL 07-02.**							RE (-)	Mandatory (Appliance AD)		
34 A/F						Mos	10-Feb-2023				
Eff: 14-Oct-2014 Not Applicable	PER PART NUMBER					Hrs	24:24				
Brand A:9990-2014-18-01 (AVG MAN HRS: 4) (APX COST: 85)						Ldg	7				
280-57-330	**Wings - Addition of Drain Holes in Lower Ailerons Seal Panels**							RE (-)	Recommended		
57 A/F						Mos	10-Sep-2024				
Eff: 09-Aug-2024 Complied With						Hrs					
(AVG MAN HRS: 8) (UPDATE NOTE: AF) (NOTE: COMPLIANCE: Compliance with this service bulletin is recommended at the next suitable planned maintenance period within 24 months from the original release of this service bulletin.)						Ldg					
▼ 1. T 3 Mos | 2. RE -											
2016-11-20 Paragraph (g)	**Oxygen - Aerospace Protective Breathing Equipment (PBE), part number (P/N) 119003-11 - Inspection**							RE (-)	Mandatory (Appliance AD)		
35 A/F						Mos	10-Feb-2023				
Eff: 15-Jul-2016 Not Applicable	NOT INSTALLED					Hrs	24:24				
Brand A:9990-2016-11-20(g) (NOTE: Applicability: This AD applies to B/E Aerospace Protective Breathing Equipment (PBE), part number (P/N) 119003-11, that is installed on airplanes)						Ldg	7				
▼ 1. T 30 Days | 2. RE -											
2023-21-05 Par. (g)(1)	**Navigation - Thales AVS France SAS Flight Management Computer Navigation Modules (FMC2 NAVM) - Revise the Limitations Section of the Existing Airplane Flight Manual**							RE (-)	Mandatory (Appliance AD)		
34 A/F						Days	20-Nov-2023				
Eff: 12-Dec-2023 Not Applicable						Hrs					
(UPDATE NOTE: Thales AVS France SAS flight management computer navigation modules (FMC2 NAVM), part number (P/N) C13084CA03 - Not installed on the aircraft) (NOTE: APPLICABILITY: This AD applies to Thales AVS France SAS flight management computer navigation modules (FMC2 NAVM), part number (P/N) C13084CA03, installed on, but not limited to airplanes, certificated in any category. COMPLIANCE: Within 30 days after the effective date of this AD, revise the Limitations Section of the existing airplane flight manual (AFM) for your airplane by adding the information in Table 1 to the introductory text of paragraph (g)(1) of this AD and Table 2 to the introductory text of paragraph (g)(1) of this AD.)						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2023-21-05 Par. (g)(2)	**Navigation - Thales AVS France SAS Flight Management Computer Navigation Modules (FMC2 NAVM) - Update the Database for Thales FMC2 NAVM - P/N C13084CA03**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Days	20-Nov-2023				
Eff: 12-Dec-2023 Not Applicable						Hrs					
	(UPDATE NOTE: Thales AVS France SAS flight management computer navigation modules (FMC2 NAVM), part number (P/N) C13084CA03 - Not installed on the aircraft) (NOTE: APPLICABILITY: This AD applies to Thales AVS France SAS flight management computer navigation modules (FMC2 NAVM), part number (P/N) C13084CA03, installed on, but not limited to airplanes, certificated in any category. COMPLIANCE: Within 30 days after the effective date of this AD, update the database for your Thales FMC2 NAVM, P/N C13084CA03, with a database that does not contain the procedures specified in section II of Thales Service Information Letter F9111-J70859DN-00, issued January 18, 2022 (Thales SIL F9111-J70859DN-00).)						Ldg					
2015-23-09 Para (g)	**Oxygen - Inspect Each Flightcrew Oxygen Mask Regulator To Identify The Part Number And Serial Number**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	10-Feb-2023				
Eff: 28-Dec-2015 Not Applicable	PER REGULATOR P/N					Hrs	24:24				
						Ldg	7				
▼ 1. T 30 Days | 2. RE 1000 Hrs											
74-08-09 R3 Paragraph (k)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Inspect all lavatory paper and linen waste receptacle enclosure access doors and disposal doors for proper operation, fit, sealing, and latching for the containment of possible trash fires.**							RE		Mandatory	**≈02-Dec-2025**
25 A/F						Mos	26-Jul-2024				
Eff: 06-Aug-1974 Complied With						Hrs	967:25	1,000		1967:25	909:25 Hrs
						Ldg	562				
▼ 1. T 4 Mos | 2. RE -											
2023-12-25 Par. (g)	**Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets - Inspection**							RE (-)		Mandatory	
25 A/F						Mos	10-Aug-2023				
Eff: 23-Aug-2023 Not Applicable						Hrs					
	(UPDATE NOTE: N/A by type of the Life Jackets. Current Life Jackets made by ZODIAC AEROSPACE) (NOTE: COMPLIANCE: Within 4 months after the effective date of this AD, do a general visual inspection for a discrepancy (mismatch of the valise/container description and life jacket type) of the life jacket, in accordance with paragraphs 2.A. through 2.C. of the Accomplishment Instructions of Survitec [RFD] Alert Service Bulletin 25-207-A, Version 1, dated November 24, 2021.)						Ldg					
▼ 1. T 5000 Ldg | 2. RE 2500 Ldg											
575039	**Flap Track B Flange CP21 Flap Track B Flange - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈21-Oct-2033**
57 A/F						Mos					
						Hrs					
ATA Ref:57-50-00 (ZONE: W10.1) (SOURCE: G280 AMM)						Ldg		5,000	+5%	5,000	4,382 Ldg (+250)
575040	**Flap Track B Flange CP21 Flap Track B Flange - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈21-Oct-2033**
57 A/F						Mos					
						Hrs					
ATA Ref:57-50-00 (ZONE: W10.1) (SOURCE: G280 AMM)						Ldg		5,000	+5%	5,000	4,382 Ldg (+250)
▼ 1. T 5000 Ldg | 2. RE 5000 Ldg											
522111	**Emergency Exit Window Cut Out CF9.1 Emergency Exit Window Cut Out Perimeter - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈21-Oct-2033**
52 A/F						Mos					
						Hrs					
ATA Ref:52-21-00 (SOURCE: G280 AMM)						Ldg		5,000	+5%	5,000	4,382 Ldg (+250)
531004	**Left Skin Panel, FS 117.87 - FS 229.21 (4518 - 5822 mm) FF4.3 Forward Fuselage Skin Left Side FS 177.87 - FS 229.21 (4518 - 5822 mm) - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈21-Oct-2033**
53 A/F						Mos					
						Hrs					
ATA Ref:53-10-01 (SOURCE: G280 AMM)						Ldg		5,000	+5%	5,000	4,382 Ldg (+250)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
575025		**Flap Track A - D CP20 - CP23 Flap Tracks A - D - NDT Inspection - [BHEC / HFEC]**							T		05-10-10 Airworthiness Limitations	**≈21-Oct-2033**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W2.2, W4.3, W9.3, W9.5, W10.3,) (SOURCE: G280 AMM) (NOTE: Zone continued: W10.5, W11.3, W11.5, W12.3, W12.5)					Ldg		5,000	+5%	5,000	4,382 Ldg (+250)
575026		**Flap Track A - D CP20 - CP23 Flap Tracks A - D - NDT Inspection - [BHEC / HFEC]**							T		05-10-10 Airworthiness Limitations	**≈21-Oct-2033**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (ZONE: W2.2, W4.3, W9.3, W9.5,) (SOURCE: G280 AMM) (NOTE: Zone continued: W10.3, W10.5, W11.3, W11.5, W12.3, W12.5)					Ldg		5,000	+5%	5,000	4,382 Ldg (+250)
575091		**Skin Upper Inboard Trailing Edge, Flap, CP60 Flap Upper Trailing Edge - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈21-Oct-2033**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (SOURCE: G280 AMM)					Ldg		5,000	+5%	5,000	4,382 Ldg (+250)
575092		**Skin Upper Inboard Trailing Edge, Flap, CP60 Flap Upper Trailing Edge - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈21-Oct-2033**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (SOURCE: G280 AMM)					Ldg		5,000	+5%	5,000	4,382 Ldg (+250)
575093		**Flap Upper Mid Skin 4, CP61 Flap Upper Mid Skin - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈21-Oct-2033**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (SOURCE: G280 AMM)					Ldg		5,000	+5%	5,000	4,382 Ldg (+250)
575094		**Flap Upper Mid Skin 4, CP61 Flap Upper Mid Skin - NDT Inspection - [HFEC]**							T		05-10-10 Airworthiness Limitations	**≈21-Oct-2033**
	57 A/F						Mos					
							Hrs					
		ATA Ref:57-50-00 (SOURCE: G280 AMM)					Ldg		5,000	+5%	5,000	4,382 Ldg (+250)
▼ 1. T 6 Mos | 2. RE -											Man Hours: 1+	
2015-16-04		**Fire Protection**							RE (-)		Mandatory (Appliance AD)	
	26 A/F						Mos	10-Feb-2023				
	Eff: 15-Sep-2015 Not Applicable	NOT INSTALLED					Hrs	24:24				
							Ldg	7				
2017-11-11		**ATC Transponder System - Automatic Dependent Surveillance Broadcast (ADS-B) Universal Access Transceiver Units**							RE (-)		Mandatory (Appliance AD)	
	34 A/F						Mos	10-Feb-2023				
	Eff: 11-Jul-2017 Not Applicable	MODEL NOT INSTALLED					Hrs	24:24				
							Ldg	7				
		(AVG MAN HRS: 1) (NOTE: APPLICABILITY: This AD applies to the following NavWorx, Inc., Automatic Dependent Surveillance-Broadcast (ADS-B) Universal Access Transceiver units (unit) installed on aircraft certificated in any category, including experimental: (1) Model ADS600-B part number (P/N) 200-0012; (2) Model ADS600-B P/N 200-0013; and (3) Model ADS600-EXP P/N 200-8013.)											

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 1. T 60 Days | 2. RE -											
2023-04-02	**Navigation - AFM Wet Runway Performance Tables**							RE (-)		Mandatory	
34 A/F						Days	22-Mar-2023				
Eff: 07-Apr-2023 Complied With	AFM R10 in aircraft					Hrs					
						Ldg					
(NOTE: COMPLIANCE: Unless already accomplished, comply with this AD within 60 days...Please refer to FAA AD 2023-04-02 Par. (h) for Compliance and Effective Date.)											
2023-13-11	**Oxygen - AVOX Systems Inc. (Formerly Scott Aviation) Oxygen Cylinder and Valve Assemblies (Supersedes FAA AD 2022-04-09)**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Days	10-Aug-2023				
Eff: 05-Sep-2023 Not Applicable						Hrs					
(UPDATE NOTE: N/A by SN of the parts) (NOTE: APPLICABILITY: This AD applies to AVOX Systems Inc. (formerly Scott Aviation) oxygen cylinder and valve assemblies having part number (P/N) 89794077, 89794015, 891511-14, 806835-01, 807982-01, 808433-01, or 891311-14; and oxygen valve assemblies (body and gage assemblies) having P/N 807206–01. These assemblies might be installed on, but not limited to, the aircraft identified in paragraphs (c)(1) through (12) of this AD, certificated in any category. COMPLIANCE: Within 60 days after the effective date of this AD, inspect the oxygen valve assemblies, and oxygen cylinder and valve assemblies, to determine if the serial numbers of the valve, cylinder, and entire assembly, are listed in Appendix 1 or Appendix 2, "Affected Shipments," of the applicable service information identified in paragraphs (h)(1) through (3) of this AD. A review of airplane maintenance records is acceptable in lieu of this inspection if the serial numbers can be conclusively determined from that review.)						Ldg					
2018-04-13 Par. (g)(2)(i)	**Engine Controls Section - Engine Electronic Control Unit (ECU) - Revise AFM**							RE (-)		Mandatory	
76 ENG1						Mos	10-Feb-2023				
Eff: 12-Apr-2018 Not Applicable						Hrs					
						Enc					
2018-04-13 Par. (g)(2)(i)	**Engine Controls Section - Engine Electronic Control Unit (ECU) - Revise AFM**							RE (-)		Mandatory	
76 ENG2						Mos	10-Feb-2023				
Eff: 12-Apr-2018 Not Applicable						Hrs					
						Enc					
ISR-I-97-2022-04-9	**Revision of G280 AFM Wet Runway Performance Tables**							RE (-)		Mandatory	
97 A/F						Mos	22-Mar-2023				
Eff: 15-Jun-2022 Complied With						Hrs					
(NOTE: COMPLIANCE: Unless already accomplished, comply with this AD within 60 days from the effective date of this AD.)						Ldg					
▼ 1. T 720 Ldg | 2. RE -										Man Hours: .5	
2018-16-13	**Zodiac Seats France - 537-Series Cabin Attendant Seats - Safety Belt Webbing - Inspection/ Modification**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	10-Feb-2023				
Eff: 26-Oct-2018 Not Applicable	NOT INSTALLED					Hrs	24:24				
						Ldg	7				
(AVG MAN HRS: 0.5) (NOTE: NOTE: Refer to Zodiac Seats France Service Information Letter 537-01, dated July 31, 2015, and the Accomplishment Instructions, paragraphs 2.A. through 2.B., of Zodiac Seats France Service Bulletin No. 537-25-003, Revision 1, dated August 29, 2016.)											
▼ 1. T 9 Mos, 200 Hrs | 2. RE -											
2018-04-13 Par. (g)(1)(i)	**Engine Controls Section - Engine Electronic Control Unit (ECU) - Apply Sealant (Terminating Action)**							RE (-)		Mandatory	
76 ENG1						Mos	10-Feb-2023				
Eff: 12-Apr-2018 Not Applicable						Hrs					
						Enc					
2018-04-13 Par. (g)(1)(i)	**Engine Controls Section - Engine Electronic Control Unit (ECU) - Apply Sealant (Terminating Action)**							RE (-)		Mandatory	
76 ENG2						Mos	10-Feb-2023				
Eff: 12-Apr-2018 Not Applicable						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 1. T 90 Days | 2. RE -											
ISR-I-04-2020-06-02	**Revision of Table 9 - Temporary Limitations and Inspection Requirements of the Section 05-10-10 (Airworthiness Limitations Section) of the G280 Airplane Maintenance Manual - Addition of AWL-3 Task**							RE (-)		Mandatory	
5 A/F						Mos	10-Feb-2023				
Eff: 28-Jun-2020 Complied With	AWL-3 TASK ADDED TO TABLE 9 OF G280 AIRPLANE MAINTENANCE MANUALS SECTION 05-10-10 (AIRWORTHINESS LIMITATIONS SECTION)					Hrs	24:24				
	(NOTE: COMPLIANCE: Within 90 days from the effective date of this AD.)					Ldg	7				
2020-26-12	**Flight controls - Revision of Table 9 - Temporary Limitations and Inspection Requirements of the Section 05-10-10 (Airworthiness Limitations Section) of the G280 Airplane Maintenance Manual - Addition of AWL-3 Task**							RE (-)		Mandatory	
27 A/F						Mos					
Eff: 01-Feb-2021 Not Applicable	N/A by original export CoA, SEE ISRAEL CAAI AD ISR-L-04-2020-06-02. AWL-3 TASK ADDED TO TABLE 9 OF G280 AIRPLANE MAINTENANCE MANUALS SECTION 05-10-10 (AIRWORTHINESS LIMITATIONS SECTION)					Hrs					
						Ldg					
▼ 1. T A/R | 2. RE -										Man Hours: 665.5+	
280-00-243	**Aircraft General - Documentation Of Steep Approach Certification For Specific Serial Numbers (MOD G25-10059)**							T (A/R)		Optional	
0 A/F						Mos					
Eff: 31-Jan-2017						Hrs					
						Ldg					
280-00-243 Rev 1	**Aircraft General - Documentation of Steep Approach Certification for Specific Serial Numbers (MODG25-10059)**							RE (-)		Optional	
0 A/F						Mos	10-Feb-2023				
Eff: 27-Jun-2017 Complied With						Hrs	24:24				
						Ldg	7				
G25-00151	**PYLON COVERS MATERIAL CHANGE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-00217	**AUXILIARY DOOR MECHANISM- ADDING STOPPER, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-00330	**BAGGAGE DOOR SPRING REEL- ENLARGE FORCE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-00463	**AUXILIARY BULKHD SPLICE - CHANGE RAW MATERIAL DUE LACK OF CURRENT MATERIAL, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-00512	**REPLACEMENT OF HYDRAULIC RETURN LINE TUBES IN THE V/S, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-00679	**MED LEVER-BOLT HEAD PROXIMETY, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-00705	**ICE DETECTOR - CONDUCTIVE GASKET AND PROPER BONDING, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G25-00709	**BAGGAGE DOOR- INTERLOCK ROLLER IMPROVEMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-00899	**MED MAIN AXLE - FASTENERS TORQUE CLARIFICATION TO EASE MANUFACTURING, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-00980	**CHANGE PROCESS STANDARD AND TYPE OF RESIN FOR MANUFACTURING PYLON NACA SCOOPS, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-00993	**ADD NOTE FOR LIQUID SHIM BETWEEN WING FITTINGS, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-01042	**WING ICE INSPECTION AND LOGO LIGHTS CHECK ON GROUND WITHOUT OPERATING THE APU, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-01216	**BAGGAGE COMPARTMENT- ADD TRANSPARENT ACCESS PANELS FOR DC BOXES, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-01237	**TILLER (GSCH)- MANUFACTURING PROCESS CHANGE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-01276	**MODIFICATION OF COCKPIT PEDESTAL AND ILLUMINATED PANELS, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-01357	**THERMAL AND ACOUSTIC INSULATION SYSTEM-BLANKET REINFORCEMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-01441	**BAGGAGE DOOR - OUTER HANDLE SLIDING MECHANISM - CHANGES IN MATERIAL AND GEOMETRY OF COMPONENTS TO PREVENT EXCESSIVE WEAR, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-01495	**ELEVATOR SERVO ACTUATOR EXTERNAL PAINT REMOVAL, DUE NOT REQUIRED AND PEELING IN SERVICE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-01504	**CHANGE RAW MATERIAL OF SPLICE RHS LONG SIDE FR43, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G25-01568	**THERMAL AND ACOUSTIC INSULATION SYSTEM -BLANKET ADHESIVE TAPE OBSOLESCENCE FOR FERRY KITS, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-01662	**COCKPIT SIDE WINDOW-CHANGE PROFILE OF Z-RETAINER TO ENSURE REQUIRED GAP WITH STRUCTURE ON INSTALLATION, TO PREVENT NEED FOR REWORK, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-01697	**NOSE SECTION - HIGH PRESSURE OXYGEN FLEXIBLE HOSE - REPLACE WITH NON-MAGENETIC MODEL -TO REMOVE SUSPICIION OF INTERFERENCE WITH MAGNETOMETER LOCATED AT DISTANCE OF SEVERAL INCHES, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-01698	**NLG COMPONENTS - REFER TO IAI PS INSTEAD OF TO MIL SPEC FOR DEFINITION OF REQUIRED HEAT TREATMENT, PER IAI QA REQUIREMENT, AND CHANGE CONDITION FROM H975 TO G1D25, PER IAI M&P RECOMMENDATION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-01756	**MFSA PAINT REMOVAL, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-01772	**GSA EXTERNAL PAINT REMOVAL, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-02051	**G25-02051 , MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-07112	**ADD LIQUID SHIM BELOW FLAP TRACK D ROLLER FITTINGS, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-07243	**IMS-6000 REPLACEMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10022	**GADC -4 MODIFICATIONS AND WAI OPTIMIZATIONS, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10023	**MAIN STRUT - CHANGING INNER DIAMETER, UPDATING DEFINITION OF SHOT PEENING FORGING - ADDING CUT THROUGH TRUNNION HOLE FOR HEAT TREATMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G25-10024	**ACT-3010 AND OCMT-3900 MODIFICATION FOR RVSM GROUP APPROVAL, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10026	**MOOG FCECU SW VERSION 13, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10032	**RED LABEL RC VERSION 3.6 POST EIS IMPLEMENTATION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10033	**G280AFM REV 3, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10034	**INTRODUCTION OF METAL AUXILIARY DOOR INST. OF COMP MATERIAL, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10035	**AFM UPDATE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10038	**WINDSHIELD LOWERS SILLS IMPROVEMENT, COCKPIT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10039	**ADD COLD WORK ON HOLES LOCATED BETWEEN FRAMES 32 THROUGH 36., MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10040	**LOWER SILLS COLD WORK, COCKPIT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10041	**AFM REV. 5, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10044	**ECU HARDWARE AND FADEC SOFTWARE UPDATE, V2G, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10045	**CRACKS ON INTERCOSTALS (LH & RH SIDES) STA4518., MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G25-10046	**REPLACING STOPPERS FITTING AND SERRATED PLATES ON AROUND STRUCTURE BAGGAGE COMP. BAY., MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10047	**G280 AFM REV6 + ECL, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10048	**G280AFMREV7, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10052	**G280 IPPS-EATON FUEL AND HYDRAULIC HOSES, FIRE RESISTING SLEEVING, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10053	**G280 AFM AIRPLANE FLIGHT MANUAL (AFM) ISSUE 1 REV 0, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10054	**INCORPORATION OF UNCONTROLLED HIGH THRUST (UHT) AUTOMATIC PROTECTION ACTION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10063	**G280 AIRPLANE FLIGHT MANUAL REVISION 3, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10066	**CHANGE OF THE BAGGAGE ACCESS DOOR LIMITATION PLACARD, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10068	**G280 AFM ISSUE 2 REV 1, G280 AFM ISSUE 1 REV 3, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10069	**G280 AFM ISSUE 2 REV 3, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10070	**FLIGHT CONTROL CABLES - SUBSTITUTE FOR OBSOLETE PART, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10071	**G280 AFM ISSUE 2 REVISION 4 AND ISSUE 1 REVISION 4., MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G25-10077	**G25-10077 , MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10700	**REDUCE LANDING AROUND ACCESS PANELS IN BAY 11 AND OUTBD FOR WEIGHT SAVINGS, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10702	**DESIGN OF REAR SPAR INCORPORATING SERIAL FIXES FOR ULTIMATE LOAD TEST FAILURE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10703	**DESIGN OF WING RIBS INCORPORATING SERIAL FIXES FOR ULTIMATE LOAD TEST FAILURE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10704	**DESIGN OF WING STRINGERS INCORPORATING SERIAL FIXES FOR ULTIMATE LOAD TEST FAILURE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10705	**CHANGE TURN DOWN HOOK TO INCREASE GAP TO TRACK, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10706	**FAA REQUIREMENT TO CORRECT ROUTING OF WIRE HARNESSES TO ENSURE NO CHAFING WITH ADJACENT STRUCTURES OR SYSTEMS (ECP G28D-7501). ALSO INCORPORATES THE REQUIREMENT (ECP G280-7502) THAT THERE CANNOT BE ANY TWO CLAMPS LOST ON THE LE HARNESS, OR SINGLE CLAMP LOSS ON THE TE HARNESS RESULTING IN WIRE CONTACTING STRUCTURE OR SYSTEMS AND CHAFFING, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10708	**CHANGE TRACK D ROLLER FITTINGS FOR FATIGUE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10709	**FWD SPAR / RIB 0 FIXES FROM FATIGUE TEST FAILURES, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10709 REVB	**FWD SPAR FIXES FROM FATIGUE TEST FAILURES, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10710	**REDESIGN TRACK A ROLLER FITTINGS FOR FATIGUE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-10711	**IMPROVE SEALING BETWEEN OUTBOARD SPAR TO LOWER AND UPPER SKINS ATTACHMENTS., MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G25-20006	**ALTERNATIVE LEFT WHEEL SPROCKET, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20007	**MATERIAL CHANGE OF RIB 4 P/N 30P318354100-501 (PYLON) FROM TITANIUM TO ALUMINUM., MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20008	**CROWN DAMPING, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20016	**PARKING BRAKE HANDLE (PBH) - NEW SUPPLIER, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20018	**PYLON TRAILING FADE FROM SHEETMETAL, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20019	**G280 REDESIGN OF MLG DOOR MECHANISM LOWER ROD 30P265036001-501, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20023	**BRAKE CONTROL SYSTEM - WHEEL SPEED TRANSDUCER (WST) CHANGE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20025	**NEW FQMS SOFTWARE 738721-1-4, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20026	**MED STOPPERS- REARRANGE ON FRAMES, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20029	**NEW CVR RIPS PART NUMBER, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20031	**GPS-4000S PRODUCT REPLACEMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20032	**NEW ANTI ROLL WASHERS FOR WING TO FUSE LINKS, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G25-20034	**AFD PART NUMBER CHANGE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20035	**CONTROL COLUMN - CHAIN AND SPROCKET SUPPLIER REPLACMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20037	**G280 WING-TIP LIGHT MODIFICATION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20038	**FTE AND LWR BAY MODIFICATION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20040	**ECE DC BOX, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20041	**NWS NEW RACK P/N 30A2720181-001 FOR G-280 AND ADD INSERVICE GREASING REQUIREMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20042	**NLG P/N 30A2720451 (NWS) COLLAR -UPDATING PLATING DEFINITION AND ADD PERIODICAL GREASING REQUIREMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20043	**ACP REPLACEMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20045	**ECL DATABASE (-0004) UPDATE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20047	**TE AND LE HARNESSES SEPARATION {COMPLY TO 25.981), MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20047A	**TE AND LE HARNESSES SEPARATION (COMPLY TO 25.981), MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20048	**WWS SYSTEM HEATING CONTROL MODULE (SHCM) SOFTWARE MODIFICATION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G25-20049	**WWS WATER CONTROL UNIT (WLS) SOFTWARE MODIFICATION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20050	**DGCU NEW AMND C - NEW IAI PART NUMBER, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20051	**TQA MODIFICATION (-5), MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20052	**CONTAMINATED VSPEEDS DATA BASE UPDATE FOR AVIONICS S/W VERSION 3.6, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20053	**G280 PERFORMANCE DATA BASE (PDB) INCORPORATION FOR SW VERSION 3.2 1, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20054	**G280 VSPEEDS DATA BASE (DRY&WET) INCORPORATION FOR SW VERSION 3.2.1, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20055	**WWS POTABLE WATER PUMP (PWP) DESIGN MODIFICATION OF HEATER, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20056	**INSTALLATION OF ACOUSTIC INSULATION IN METAL AUX BULKHEAD DOOR, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20057	**HARNESS ROUTING MODIFICATION IN FWD FUEL TANK, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20058	**G280 PERFOMANCE DATA BASE (PDB) UPDATE FOR SW VERSION 3.6, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20059	**BAGGAGE COMPARTMENT LINERS - USE OF NEW MATERIALS, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20060	**PILOT CONTROL-WHEEL - DISCONNECT MECHANISM, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G25-20061	**FADEC SOFTWARE V1.5G UPDATE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20062	**EMPFR REPLACEMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20063	**PILOT/COPILOT CONTROL-WHEEL PITCH-TRIM SWITCH IMPROVEMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20067	**UNIFY SKIN AND DOUBLER, UPPER, STA. 1663 - 2669 30P311101002-001, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20068	**OXYGEN CYLINDER ASSY.-REPLACEMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20069	**ADDITIONAL DRAIN HOLES TO FLAP ACTUATORS, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20070	**UPDATING OF SHCM SW. WLS SW, PWM P/N, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20071	**WDIC MODIFICATION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20072	**WAI - MANIFOLD PRESSURE SENSOR REMOVAL, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20073	**REMOVAL OF PLACARD PROHIBITING WAI AUTO OPERATION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20074	**AUTOBRAKE SELECT SWITCH (ABS) P/N 90006480-1, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20075	**MODIFY STATIC PORTS WITH LARGE HOLES, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G25-20077	**DGCU NEW AMND D INCORPORATION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20078	**HSTA SECONDARY MOTOR CAP SCREW INTERFERENCE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20079	**UNIFY SKIN AND DOUBLER TO AN INTEGRAL PART, LOWER, STA. 1663 - 2669 30P311201003-001, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20080	**CHANGE LOCATION AND TYPE OF FASTENERS FOR EASE INSTALLATION AT MED STRUCTURE., MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20081	**VHF COMM REPLACEMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20083	**G280 ELEVATOR SERVO ACTUATOR - TRANSFER TUBE CHANGE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20086	**MED AXLE - BEARING HOUSINGS CHANGE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20088	**REPLACEMENT OF MATERIAL IN BLEED DUCT ASSY., MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20089	**NOSE LANDING GEAR-STEERING CONTROL UNIT LPRV SUPPLIER CHANGE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20091	**MODIFICATION OF UPPER JURY BRACE ON NLG BRACE ASSEMBLY, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20092	**PEDESTAL - CUTTING CORNER ON SIDE PANEL TO PREVENT DAMAGE ON FLOOR PANEL, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20093	**LH DISTRIBUTION BUS - NEW LOGIC (FOR DUAL GENERATOR FAIL), MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G25-20095	**FPCU DESIGN CHANGE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20096	**RSA CET IMPROVEMENTS, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20097	**REVISE PLENUM BEAM TO INTEGRATE PLENUM RIBS, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20101	**AHRS (ATTITUDE AND HEADING REFERENCE SYSTEM) AND IRS (INERTIAL REFERENCE SYSTEM) MAGVAR TABLES AND SW UPDATE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20102	**NEW CONFIGURATION OF BAGGAGE COMPARTMENT LOADING, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20103	**AFD-6510 REPLACEMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20105	**APM 3RD PARTY OPTIONS FILE - DISABLE FMS PREDICTED STEPS FUNCTIONALITY, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20108	**REDUCE NUMBER OF DOOR SWITCHES, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20113	**IPPS- THRUST REVERSER INNER DUCT SKIN -ADDITION OF A TATANIUM HEATSHIELD TO PROVIDE THERMAL PROTECTION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20118	**TDR-94 REPLACEMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20119	**MAIN ENTRANCE DOOR AXLE - FORWARD BEARING IMPROVEMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20121	**RADIO INTERFACE UNIT (RIU) REPLACEMENT TO SUPPORT SECOND DATA LINK OPTION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G25-20122	**FMS PERFORMANCE DATABASE UPDATE - DUE ENGINE DECK #17 IMPLEMENTATION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20123	**FMS VSPEEDS DATABASE UPDATE - DUE ENGINE DECK #17 IMPLEMENTATION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20124	**MFG. IMPROVEMENT -PANELS 5 & 6, FWD FUSELAGE LHS & RHS PANELS (FASTENERS CHANGE), MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20128	**DGCU AMDT E - PBIT SOFTWARE CHANGE AND GAIA CONVERTER MODIFICATIONS, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20129	**IMS-6000 SOFTWARE UPDATE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20130	**G280 APU 36-150[IAI] COMPRESSOR SEAL IMPROVEMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20131	**BAGGAGE COMPARTMENT LINERS -INSULATION FOAM USE OF NEW MATERIAL, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20132	**FORWARD FUEL TANK - ACCESS PANELS JUMPER ATTACHMENTS SEALING IMPROVEMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20133	**TSSA-4100 REPLACEMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20134	**CHANGE P/N OF SCOTCHMATE IN THE BC LINERS PANELS WAS: SJ3586FR AND SJ3587FR NOW:SJ3519FRAND SJ3518FR ALTERNATIVE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20135	**VERTICAL STABILIZER RIBS - ENLARGE LIGHTENING HOLES AND CANCEL CHEMICAL MILLING, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20136	**HORIZONTAL STABILIZER LEADING EDGE CHEMICAL MILLING CANCELLATION AND MATERIAL CHANGE FOR COST REDUCTION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G25-20137	**MAIN ENTRANCE DOOR- AIRSTAIRS- ADD A STORAGE BOX, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20138	**FPCU ODC SOFTWARE CHANGE & FIDEX HARDWARE CHANGE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20139	**ALLEVIATE SHOT PEENING PROCESS IN BRACE FITTING NLG BAY, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20140	**HIGH LEVEL SENSOR (HLS) - RESIN REPLACEMENT FROM SCOTCHCSST N8 TO DURALCO 4525., MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20141	**GPS-4000S REPLACEMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20143	**BLANKET ADHESIVE TAPE OBSOLESCENCE FOR FERRY KITS, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20144	**CHANGE HYDRAULIC TUBES MATERIAL - COST REDUCTION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20146	**AUX BHD WEBS - CHANGE MATERIAL FROM COMPOSITE TO MACHINED ALUMINUM, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20147	**AFT FUSELAGE INSULATION FOAM ON SKIN -REVISED 168 AM JEHIER, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20148	**CENTER FUSELAGE- KEEPING TOOLING HOLES AND KEY HOLES UNPLUGGED IN INTERCOSTAL, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20149	**INCORPORATION OF THALES STARTER GENERATOR P/N G3666-4O0, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20150	**RUDDER PEDALS - USE ALUMINUM AS ALTERNATIVE MATERIAL, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G25-20152	**STANDBY FLIGHT INSTRUMENT SYSTEM SFIS-3900 REPLACEMENT, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20153	**FMS DISABLE ETP FEATURE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20154	**FORWARD FUSELAGE - REMOVE REQUIREMENT TO PLUG A CERTAIN KEY HOLE AND CERTAIN TOOLING HOLES, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20156	**A/P SERVO CABLES - SUBSTITUTE FOR OBSELETE PART, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20157	**REVISED EDGE SEAL ON G280 COMPOSITE FLOOR PANELS, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20161	**EMP EMI FILTER TERMINAL CONNECTIONS INSTALLATION CHANGE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20163	**BC DOOR FILLER PADS NEW MATERIAL AND FLAMMABILITY TEST, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20165	**MFSA PAINT REMOVAL, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20172	**ECS LUGS ALTERNATIVE MATERIAL, CHANGE FROM CAST TO MACHINED LUGS, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20174	**ECS SUPP BRACKET PN 2002 ATTEM MAT'L & PROD METHOD, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20177	**NEW WEATHER RADAR RTA-4218, WITH SDDED PWS (PREDICTIVE WINDSHEAR) AND VWX (VERTICAL WEATHR) CAPABILITIES, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20179	**G25-20179 , MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G25-20702	**WING UPPER SKIN -INCREASE CHEM MILL POCKET (DECREASE RADIUS OF CORNERSS) AND REDUCE ALLOWED FLAP TRACK SHIM GAP, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20703	**WING LOWER SKIN - DECREASE CHEM MILL CORNER RADIUSES & ADD CHAMFER TO NACA SCOOP HOLE CIRCUMFERENCE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20706	**MODELLING OF RIB 00, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20707	**TRIM UP TO .24" FROM AFT EDGE OF LOWER SKIN TO ENSURE CLEARANCE WITH AIRLERON - 2005-2014 TO BE REWORKED TBD BY UPDATE TO ECP, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20709	**AILERON BALANCE WEIGHT - MASS OPTIMIZATION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20713	**TRIM MATERIAL FROM TRACK C LOWER, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20716	**CHANGE FLAP TRACK D MATERIAL, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20717	**REVISE FASTENERS AT TRACK B OUTBOARD ROLLER, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20718	**MODIFY HOLE IN SIDF BRACE FOR BARREL NUTS AND FASTENER CHANGE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20719	**REDUCE SPOILER HINGE BOLTTORQUE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20721	**ADD DRAIN HOLE IN DRY BAY IN WING TORSION BOX, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20722	**AFT SPONSON BEAM BEARING INSTALLATION IMPROVEMENTS, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G25-20723	**FUEL SYSTEM-SINGLE MOTOR ACTUATOR MODIFICATION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20725	**CHANGE FLAP TRACK 8 & C ROLLER FITTINGS CONFIGURATION AND MATERIAL, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20726	**FEED TANK BRACKETS - ENLARGE CORNER HOLES TO PREVENT LOAD TRANSFER, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20728	**UPDATE ACCESS PANEL CONFIGURATION TO SATISFY TCCA CERTIFICATION REQUIREMENTS., MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20729	**INCREASED CLEARANCE REQUIRED FOR FLAP ROLLERS, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20730	**FLAP TRACK C OUTBD MID-FLANGE ADDITIONAL CHAMFER REWORK, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20731	**CREATE NEW METAL OUTBD FTE INSTEAD OF EXISTING COMPOSITE PART TO REDUCE MRBS DURING WING PRODUCTION,, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20733	**GROUND SPOILER ACTUATOR ATTACHMENT HARDWARE CHANGE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20734	**WIRING BUTTERFLY CLIPS MODIFICATIONS FOR EASE OF FASTENER INSTALLATION AND IMPROVED FATIGUE RESISTANCE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20735	**MINIMAZE STEP ISSUE FROM WINGTET TO WING SKIN TO EASE MANUFACTURING, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20736	**ADDITIONAL AILERON WEIGHT CLEARANCE FOR INBOARD SIDE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20737	**TRACK A - LOWER TURN DOWN HOOKS TO AN OPTIMA) LEVEL TO PREVENT FLAP NON SMOTH MOVEMENTS, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G25-20738	**FLAP UPPER MID SKIN- INCREASE CUTOUT AT SPOILER 3 POCKET TO PREVENT STRESS CONCENTRATION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20739	**WING-INBD UPPER SKIN - MATERIAL CHANGE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20740	**REDUCE BOSS ON INBOARD TRACK A ROLLER FITTING TO MATCH OUTBOARD ROLLER FITTING CONFIGURATION, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20741	**FEED TANK BRACKET ATTACH TO STRINGER 3 - ADD COLD WORK, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
G25-20742	**RIB 2 CUTOUT FOR STRINGER - MODIFY TO IMPROVE FATIGUE RESISTANCE, MODIFICATION**							RE (-)			
0 A/F						Mos	20-Nov-2022				
Complied With	AT MANUFACTURE					Hrs	0				
						Ldg	0				
280-23-003 Rev 2	**Communications - Audio System - Installation of Third Audio System**							RE (-)		Optional	
23 A/F						Mos	10-Feb-2023				
Eff: 01-Sep-2021 Complied With						Hrs	24:24				
(AVG MAN HRS: 15)						Ldg	7				
280-23-006 Rev 2	**Communications - High Frequency System - Installation of Second HF System**							RE (-)		Optional	
23 A/F						Mos	10-Feb-2023				
Eff: 01-Sep-2021 Complied With						Hrs	24:24				
(AVG MAN HRS: 150)						Ldg	7				
280-23-007 Rev 3	**Communications - Datalink System - Audio Integrating - Installation of Second Datalink System**							RE (-)		Optional	
23 A/F						Mos	10-Feb-2023				
Eff: 01-Sep-2021 Complied With						Hrs	24:24				
(AVG MAN HRS: 15)						Ldg	7				
280-24-085	**Electrical Power - DC Generation - Replacement of the Existing APU Digital Generator Control Unit (DGCU) MODS A and B with an Upgraded DGCU, MOD D (MODG25-20050)**							RE (-)		Recommended	
24 A/F						Mos	19-Apr-2023				
Eff: 12-Jan-2016 Not Applicable	as per A/C S/N					Hrs	124:16				
						Ldg	71				
280-24-209	**Electrical Power - DC Generation - Replacement Of The Existing Engines Digital Generator Control Unit (DGCU) MODS A And B With An Upgraded DGCU MOD D (MODG25-20077)**							RE (-)		Recommended	
24 A/F						Mos	19-Apr-2023				
Eff: 12-Jan-2016 Not Applicable	as per A/C S/N					Hrs	124:16				
						Ldg	71				
280-24-209 Rev 1	**Electrical Power - DC Generation - Replacement of the Existing Engines Digital Generator Control Unit (DGCU) MODS A and B with an Upgraded DGCU MOD D (MOD G25-20077)**							RE (-)		Recommended	
24 A/F						Mos	10-Feb-2023				
Eff: 28-Feb-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
(NOTE: This revision cancels this SB. Compliance is no longer required.)											

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2014-20-11	**Zodiac Seats France - Equipment/Furnishings - Seats**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	10-Feb-2023				
Eff: 22-Oct-2014 Not Applicable	NOT INSTALLED					Hrs	24:24				
						Ldg	7				
2023-12-25 Par. (h)	**Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets - Follow-On and Corrective Action**							RE (-)		Mandatory	
25 A/F						Mos	10-Aug-2023				
Eff: 23-Aug-2023 Not Applicable						Hrs					
(UPDATE NOTE: N/A by type of the Life Jackets. Current Life Jackets made by ZODIAC AEROSPACE) (NOTE: COMPLIANCE: Before further flight after accomplishing the requirements of paragraph (g) of this AD, do the applicable actions required by paragraph (h)(1) and (2) of this AD.)						Ldg					
2023-14-10 Par. (g)(2)(ii)	**Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Replace both Track Lock Springs of the Affected Seat**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	10-Aug-2023				
Eff: 07-Sep-2023 Not Applicable						Hrs					
(UPDATE NOTE: N/A by SN of the pilot/co-pilot seats) (NOTE: COMPLIANCE: If, during any inspection as required by paragraph (g)(2)(i) of this AD, any damage on, or incorrect installation of, any track lock spring is found on the pilot or co-pilot seat, before further flight, replace both track lock springs of the affected seat with a part eligible for installation using the Accomplishment Instructions, paragraph 3.3.3.1 or 3.3.3.2, as applicable, of Ipeco SB Number 063-25-14, Revision 00, dated August 14, 2018.)						Ldg					
280-25-014	**Equipment and Furnishings - Flight Compartment - Flight Compartment Interior Furnishings Installation (MODG25-20004)**							RE (-)		Recommended	
25 A/F						Mos	10-Feb-2023				
Eff: 13-Nov-2012 Complied With						Hrs	24:24				
						Ldg	7				
280-25-053	**Equipment And Furnishings - Baggage Compartment - Light Switch Angle Support Assembly Installation - Rework (MODG25-00319)**							RE (-)		Recommended	
25 A/F						Mos	19-Apr-2023				
Eff: 12-Dec-2014 Not Applicable	as per A/C S/N					Hrs	124:16				
						Ldg	71				
280-26-195	**Fire Protection - Fire Protection Control Unit (FPCU) - Replacement of Existing FPCU P/N 30P841300000-001 with New FPCU P/N 30P841300000-003 (MODG25-20095)**							RE (-)		Recommended	
26 A/F						Mos	19-Apr-2023				
Eff: 18-Sep-2015 Not Applicable	as per A/C S/N					Hrs	124:16				
						Ldg	71				
280-26-195 Rev 1	**Fire Protection - Fire Protection Control Unit (FPCU) - Replacement of Existing FPCU P/N 30P841300000-001 With New FPCU P/N 30P841300000-003 (MODG25- 20095)**							RE (-)		Recommended	
26 A/F						Mos	10-Feb-2023				
Eff: 10-May-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	24:24				
						Ldg	7				
(NOTE: This revision cancels this SB. Compliance is no longer required.)											
280-27-068	**Flight Controls - Aileron Trim - Rework Of Aileron Trim Actuator Output Shaft Arms (MODG25-00382)**							RE (-)		Recommended	
27 A/F						Mos	19-Apr-2023				
Eff: 30-Apr-2013 Not Applicable	as per A/C S/N					Hrs	124:16				
						Ldg	71				
D200906000007 Rev 2	**Background and Current Situation Regarding Possible Fatty Acid Methyl Ester (FAME) Contamination in Aviation Turbine Fuel**							T (A/R)		Service Information Letter	
28 ENG1						Mos					
Eff: 02-Aug-2021						Hrs					
						Enc					
D200906000007 Rev 2	**Background and Current Situation Regarding Possible Fatty Acid Methyl Ester (FAME) Contamination in Aviation Turbine Fuel**							T (A/R)		Service Information Letter	
28 ENG2						Mos					
Eff: 02-Aug-2021						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
D201907000030 Rev 2	**Biocide Treatment Process**							T (A/R)		Service Information Letter	
28 ENG1						Mos					
Eff: 02-Aug-2021						Hrs					
						Enc					
D201907000030 Rev 2	**Biocide Treatment Process**							T (A/R)		Service Information Letter	
28 ENG2						Mos					
Eff: 02-Aug-2021						Hrs					
						Enc					
280-30-017	**Ice And Rain Protection - Wing Anti-Ice (WAI) System - Air Flow And General Aviation Digital Controller (GADC) Modifications - Installation Of System Crossover Valve And New GADC-4 (MODG25-10022, MODG25-00262, MODG25-00821 , MODG25- 00808)**							RE (-)		Mandatory	
30 A/F						Mos	17-Apr-2023				
Eff: 12-Dec-2014 Not Applicable	as per a/c S/N					Hrs	122:11				
						Ldg	69				
D202106001848	**Thermal Anti Ice Valve (TAIV) Part Number (PN) WBG3020G103-003**							T (A/R)		Service Information Letter	
30 ENG1						Mos					
Eff: 23-Jul-2021						Hrs					
						Enc					
D202106001848	**Thermal Anti Ice Valve (TAIV) Part Number (PN) WBG3020G103-003**							T (A/R)		Service Information Letter	
30 ENG2						Mos					
Eff: 23-Jul-2021						Hrs					
						Enc					
280-31-009 Rev 4	**Indicating/Recording Systems - Secondary Flight Data Recorder (FDR) System - Installation**							RE (-)		Optional	
31 A/F						Mos	10-Feb-2023				
Eff: 01-Sep-2021 Complied With						Hrs	24:24				
(AVG MAN HRS: 220)						Ldg	7				
280-31-173	**Indicating/Recording Systems - Installation Of Quick Access Recorder (QAR)**							T (A/R)		Optional	
31 A/F						Mos					
Eff: 27-Feb-2015						Hrs					
						Ldg					
280-31-173 Rev 1	**Indicating/Recording Systems - Installation Of Quick Access Recorder (QAR)**							RE (-)		Optional	
31 A/F						Mos	10-Feb-2023				
Eff: 27-Feb-2015 Complied With						Hrs	24:24				
						Ldg	7				
280-32-025	**Landing Gear - Wheels And Brakes - Park / Emergency Brake Cable Replacement (MODG25-00122)**							RE (-)		Recommended	
32 A/F						Mos	19-Apr-2023				
Eff: 13-Sep-2013 Not Applicable	as per A/C S/N					Hrs	124:16				
						Ldg	71				
280-33-121	**Lights - Strobe Light - Addition Of Cap To Receptacle 57L (MODG25-00590)**							RE (-)		Recommended	
33 A/F						Mos	19-Apr-2023				
Eff: 14-Nov-2014 Not Applicable	as per A/C S/N					Hrs	124:16				
						Ldg	71				
2002-06-05	**Mode C 621A-3 Air Traffic Control (ATC) Transponders**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	10-Feb-2023				
Eff: 26-Apr-2002 Not Applicable	COLLINS 622-9210-XXX TRANSPONDERS ARE INSTALLED					Hrs	24:24				
						Ldg	7				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2012-02-08	**Aviation Communication & Surveillance Systems (ACSS) Traffic Alert and Collision Avoidance System (TCAS) Units - Navigation**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	10-Feb-2023				
Eff: 13-Mar-2012 Not Applicable	NOT INSTALLED					Hrs	24:24				
						Ldg	7				
Brand A:9990-2012-02-08 (AVG MAN HRS: 2) (APX COST: 3,040)											
2023-10-02 Par. (j)	**Navigation - Radio Altimeters - Terminating Action for AFM Limitations**							T (A/R)		Mandatory (Appliance AD)	
34 A/F						Mos					
Eff: 26-May-2023						Hrs					
(NOTE: COMPLIANCE: Modifying the airplane from a non-radio altimeter tolerant airplane to a radio altimeter tolerant airplane terminates the limitations in paragraph (i) of this AD for that airplane. After modifying the airplane to a radio altimeter tolerant airplane, the limitations specified by paragraph (i) of this AD may be removed from the AFM.)						Ldg					
280-34-001 Rev 3	**Navigation - Radio Altimeter - Installation of Secondary Radio Altimeter**							T (A/R)		Optional	
34 A/F						Mos					
Eff: 01-Sep-2021						Hrs					
(AVG MAN HRS: 15)						Ldg					
280-34-002 Rev 1	**Navigation - Inertial Reference System (IRS) - Installation of Third IRS System**							RE (-)		Optional	
34 A/F						Mos	10-Feb-2023				
Eff: 01-Sep-2021 Complied With						Hrs	24:24				
(AVG MAN HRS: 15)						Ldg	7				
280-34-004 Rev 2	**Navigation - Automatic Direction Finder (ADF) - Installation of Second ADF System**							RE (-)		Optional	
34 A/F						Mos	10-Feb-2023				
Eff: 01-Sep-2021 Complied With						Hrs	24:24				
(AVG MAN HRS: 15)						Ldg	7				
280-34-005 Rev 2	**Navigation - Very High Frequency (VHF) - Installation of Third VHF NAV System**							T (A/R)		Optional	
34 A/F						Mos					
Eff: 01-Sep-2021						Hrs					
(AVG MAN HRS: 15)						Ldg					
280-34-008 Rev 4	**Navigation - Flight Management System (FMS) - Installation of Third FMS**							T (A/R)		Optional	
34 A/F						Mos					
Eff: 01-Sep-2021						Hrs					
(AVG MAN HRS: 12)						Ldg					
280-34-093	**Navigation - Flight Management System - (FMS) - Performance Database (PDB) Upload (MODG25-20053)**							RE (-)		Recommended	
34 A/F						Mos	19-Apr-2023				
Eff: 11-Apr-2014 Not Applicable	as per A/C S/N					Hrs	124:16				
						Ldg	71				
280-34-097	**Navigation - Independent Position Determining - Automatic Dependent Surveillance - Broadcast (ADS-B) - Air Traffic Control (ATC) Transponder (TDR-94D) No. 2 Activation (MODG25-00426)**							RE (-)		Recommended	
34 A/F						Mos	19-Apr-2023				
Eff: 27-Aug-2013 Not Applicable	as per A/C S/N					Hrs	124:16				
						Ldg	71				
280-34-122	**Navigation - Attitude And Direction - MGR-3000 Magnetometer - Extreme Temperature Improvement (MODG25-00607)**							RE (-)		Recommended	
34 A/F						Mos	19-Apr-2023				
Eff: 26-Nov-2014 Not Applicable	as per A/C S/N					Hrs	124:16				
						Ldg	71				
280-34-290 Rev 1	**Navigation - Terrain Awareness and Warning System - SMS Override Lighted Switch Retrofit and SMS/TLAF Application Enable**							T (A/R)		Optional	
34 A/F						Mos					
Eff: 08-Sep-2021						Hrs					
(AVG MAN HRS: 85) (NOTE: CONCURRENT REQUIREMENT: Aircraft PlaneView Avionic suite version 3.6.1 installed (Ref. SB 280-34-273 / MOD G25-10074).)						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
280-34-291	**Navigation - Predictive Wind Shear and Vertical Weather Upgrade**							RE (-)		Optional	
34 A/F						Mos	10-Feb-2023				
Eff: 27-May-2021 Complied With						Hrs	24:24				
	(AVG MAN HRS: 12) (NOTE: CONCURRENT REQUIREMENTS: Service Bulletin 280-34-273, Navigation - Avionics v3.6.1 Update if MOD G25-10074 is not installed. NOTE: The -141 or -440 AFDs are a prerequisite for vertical weather. Aircraft must be equipped with any combination of 822-2276-141 or 822-2276-440 in all three locations. The -100 and -140 configurations are not compatible with this option.)					Ldg	7				
CF-2024-14 Part I	**Navigation - Aeroplane - Limitations of Operations with Non-Tolerant Radio Altimeter when Operating in Canada due to 5G C-Band Wireless Broadband Interference - Radio Altimeter Tolerant Aeroplane / Non-Radio Altimeter Tolerant Aeroplane / Tolerance for Emissions**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	27-May-2024				
Eff: 29-May-2024 Complied With	AFM updated					Hrs	842:13				
						Ldg	496				
CF-2024-14 Part III	**Navigation - Aeroplane - Limitations of Operations with Non-Tolerant Radio Altimeter when Operating in Canada due to 5G C-Band Wireless Broadband Interference - Terminating Action for AFM Limitations**							T (A/R)		Mandatory (Appliance AD)	
34 A/F						Mos					
Eff: 29-May-2024						Hrs					
	(NOTE: COMPLIANCE: Modifying the aeroplane from a non-radio altimeter tolerant to a radio altimeter tolerant aeroplane, as defined in Part I of this AD, terminates the limitations specified by Part II of this AD, which may be removed from the AFM.)					Ldg					
CE-CSB-2001	**Cabin Systems (ATA 44) Advanced Cabin Server (ACS) System Firmware Update 4.4.3.3**							T (A/R)		Cabin Service Bulletin	
44 A/F						Mos					
Eff: 17-Feb-2014						Hrs					
						Ldg					
CE-CSB-2002	**Cabin Service Bulletins (ATA 44) GCMS Cabin System Firmware Update 1.9.2**							RE (-)		Recommended	
44 A/F						Mos	19-Apr-2023				
Eff: 17-Feb-2014 Not Applicable	before aircraft manufacture					Hrs	124:16				
						Ldg	71				
CE-CSB-2002A	**Cabin Service Bulletins (ATA 94) GCMS Cabin System Firmware Update 1.9.2.1**							RE (-)		Recommended	
44 A/F						Mos	19-Apr-2023				
Eff: 17-Feb-2014 Not Applicable	before aircraft manufacture					Hrs	124:16				
						Ldg	71				
CE-CSB-2002B	**Cabin Service Bulletins (ATA 44) GCMS Cabin System Firmware Update 1.9.2.1**							RE (-)		Recommended	
44 A/F						Mos	19-Apr-2023				
Eff: 13-Nov-2014 Not Applicable	before aircraft manufacture					Hrs	124:16				
						Ldg	71				
CE-CSB-2003	**Cabin Service Bulletins (ATA 44) Advanced Cabin Server (ACS) System Software Upgrade**							T (A/R)		Cabin Service Bulletin	
44 A/F						Mos					
Eff: 09-Jul-2015						Hrs					
						Ldg					
CE-CSB-2004	**Cabin Service Bulletins (ATA 44) GCMS Cabin System Firmware Update**							RE (-)		Recommended	
44 A/F						Mos	19-Apr-2023				
Eff: 09-Jul-2015 Not Applicable	before aircraft manufacture					Hrs	124:16				
						Ldg	71				
CE-CSB-2005	**Cabin Service Bulletins (ATA 44) Advanced Cabin Server (ACS) System Software Upgrade**							T (A/R)		Cabin Service Bulletin	
44 A/F						Mos					
Eff: 09-Jul-2015						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
CE-CSB-2006	**Cabin Service Bulletins (ATA 44) GCMS Cabin System Firmware Update**							RE (-)		Recommended	
44 A/F						Mos	19-Apr-2023				
Eff: 24-Jun-2016 Not Applicable	before aircraft manufacture					Hrs	124:16				
						Ldg	71				
CE-CSB-2008	**Cabin Systems (ATA 44) Advanced Cabin Server (ACS) (Gen 4) Cabin View tm Software Upgrade**							T (A/R)		Cabin Service Bulletin	
44 A/F						Mos					
Eff: 04-May-2018						Hrs					
						Ldg					
CE-CSB-2008 Rev A	**Cabin Systems (ATA 44) Advanced Cabin Server (ACS) (Gen 4) Cabinview tm Software Upgrade**							T (A/R)		Cabin Service Bulletin	
44 A/F						Mos					
Eff: 10-May-2017						Hrs					
						Ldg					
CE-CSB-2009	**Cabin Service Bulletins (ATA 44) Gulfstream Cabin Management System (GCMS 1) Firmware Update**							RE (-)		Recommended	
44 A/F						Mos	19-Apr-2023				
Eff: 08-Aug-2018 Not Applicable	before aircraft manufacture					Hrs	124:16				
						Ldg	71				
CE-CSB-2010	**Cabin Systems (ATA 44) Advanced Cabin Server (ACS) (GEN4) Cabinview tm Software Upgrade**							T (A/R)		Cabin Service Bulletin	
44 A/F						Mos					
Eff: 01-Feb-2019						Hrs					
						Ldg					
CE-CSB-2011	**Cabin Systems (ATA 44) Advanced Cabin Server (ACS) (GEN4) Cabinview tm Software Upgrade**							T (A/R)		Cabin Service Bulletin	
44 A/F						Mos					
Eff: 21-Mar-2019						Hrs					
						Ldg					
CE-CSB-2012	**Cabin Service Bulletins (ATA 44) Gulfstream Cabin Management System (GCMS 1) Firmware Update**							RE (-)		Recommended	
44 A/F						Mos	19-Apr-2023				
Eff: 08-Apr-2019 Not Applicable	before aircraft manufacture					Hrs	124:16				
						Ldg	71				
CE-CSB-2015	**Cabin Systems (ATA 44) Gulfstream Cabin Management System (GCMS 1) Firmware Update V1.10.6**							RE (-)		Recommended	
44 A/F						Mos	19-Apr-2023				
Eff: 29-Oct-2019 Not Applicable	before aircraft manufacture					Hrs	124:16				
						Ldg	71				
CSB 016	**Cabin Systems - Gulfstream Cabin Management System (GCMS 2) Firmware Update**							RE (-)		Recommended	
44 A/F						Mos	19-Apr-2023				
Eff: 01-May-2020 Not Applicable	before aircraft manufacture					Hrs	124:16				
						Ldg	71				
(AVG MAN HRS: 4) (NOTE: PREREQUISITES: GCMS installed with v2.1.0 software version or later approved version. EFFECTIVITY)											
CSB 017	**Cabin Systems - Gulfstream Cabin Management System (GCMS 1) Firmware Update**							RE (-)		Recommended	
44 A/F						Mos	19-Apr-2023				
Eff: 14-Aug-2020 Not Applicable	before aircraft manufacture					Hrs	124:16				
						Ldg	71				
(AVG MAN HRS: 4) (NOTE: PREREQUISITES: GCMS 1 with v1.10.0 firmware or later approved version.)											
CSB 018	**Cabin Systems - Gulfstream Cabin Management System (GCMS 2) Firmware Update**							RE (-)		Recommended	
44 A/F						Mos	19-Apr-2023				
Eff: 22-Oct-2020 Not Applicable	before aircraft manufacture					Hrs	124:16				
						Ldg	71				
(AVG MAN HRS: 4) (NOTE: PREREQUISITES)											

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
CSB 022	**Cabin Systems - Gulfstream Cabin Management System (GCMS 2) Firmware Update**							RE (-)		Cabin Service Bulletin, Recommended	
44 A/F						Mos	20-Oct-2023				
Eff: 22-Mar-2023 Complied With						Hrs	490:27				
(AVG MAN HRS: 4) (NOTE: EFFECTIVITY: Aircraft serials having the GCMS 2 installed. PREREQUISITES: GCMS installed with v2.1.0 software version or later approved version. NOTE: Software v2.4.9 is only compatible with GCMS 2 systems. It is not compatible with GCMS 1 systems.)						Ldg	293				
GPECSB20001	**G280 Cabin System Level E Firmware Update (ATA 44)**							T (A/R)		Optional	
44 A/F						Mos					
Eff: 26-Jan-2013						Hrs					
						Ldg					
21-4187	**Modification from part number 2119922-2S1, -3S1, and -4S1 to part number 2119922-6S1**							T (A/R)			
49 APU1						Mos					
Eff: 17-Jun-2005						Hrs					
						APUS					
21-4187 Rev 1	**Modification from part number 2119922-2S1, -3S1, and -4S1 to part number 2119922-6S1**							T (A/R)			
49 APU1						Mos					
Eff: 15-Sep-2006						Hrs					
						APUS					
3610004-49-8319	**Airborne Auxiliary Power - Gas Turbine Engine - Rework Fuel Nozzle Assembly, PN 3610004-3 and -4 to PN 3610004-5 and -6**							RE (-)		Recommended	
49 APU1						Mos	20-Oct-2023				
Eff: 17-Mar-2020 Complied With	During manufacturing					Hrs					
(AVG MAN HRS: 4)						APUS					
36-49-8119	**AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Rotating Group Balance Procedure on 36-150[F] [R] [W] [BD] [CX] [DD] [HH] [RR] [F2M] and [IAI] Auxiliary Power Units (APUs)**							T (A/R)			
49 APU1						Mos					
Eff: 22-Aug-2013						Hrs					
						APUS					
36-49-8119 Rev 1	**AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Rotating Group Balance Procedure on 36-150[F] [R] [W] [BD] [CX] [DD] [HH] [RR] [F2M] and [IAI] Auxiliary Power Units (APUs)**							T (A/R)			
49 APU1						Mos					
Eff: 13-Sep-2013						Hrs					
						APUS					
36-49-8119 Rev 2	**AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Rotating Group Balance Procedure on 36-150[F] [R] [W] [BD] [CX] [DD] [HH] [RR] [F2M] and [IAI] Auxiliary Power Units (APUs)**							T (A/R)			
49 APU1						Mos					
Eff: 13-Jan-2014						Hrs					
						APUS					
36-49-8119 Rev 3	**AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Rotating Group Balance Procedure on 36-150[F] [R] [W] [BD] [CX] [DD] [HH] [RR] [F2M] and [IAI] Auxiliary Power Units (APUs)**							T (A/R)			
49 APU1						Mos					
Eff: 16-Apr-2014						Hrs					
						APUS					
36-49-8119 Rev 4	**AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Rotating Group Balance Procedure on 36-150[F] [R] [W] [BD] [CX] [DD] [HH] [RR] [F2M] and [IAI] Auxiliary Power Units (APUs)**							T (A/R)			
49 APU1						Mos					
Eff: 30-Mar-2017						Hrs					
						APUS					

Task No / SEQ	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
36-49-8190 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Group Balance and Assembly of the Power Section for 36-150[IAI] APU, PN 3800710-1, -2, and -3**							RE (-)		Recommended	
49 APU1						Mos	09-Apr-2024				
Eff: 20-Aug-2018 Complied With						Hrs	443				
(AVG MAN HRS: 3) (NOTE: APPLICABILITY: APU P/N: 3800710-3. CONCURRENT REQUIREMENTS)						APUS	626				
36-49-8361 Rev 4	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet PN M24243/6A401H with Rivet PN 627-504-9209 on 36-150 Engine Models**							RE (-)		Category 2	
49 APU1						Mos	17-Apr-2023				
Eff: 18-Jan-2023 Not Applicable	as per APU S/N					Hrs					
(AVG MAN HRS: 1) (NOTE: EFFECTIVITY: See Par. 1.A for more information. COMPLIANCE: This service bulletin, recommended by Honeywell, is done at the next access to the parts.)						APUS					
3822101-49-8148 Rev 3	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, P/N 3822101-1, on Multiple APU's**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 27-Nov-2017 Not Applicable	as per compressor rotor P/N					Hrs					
(AVG MAN HRS: 1)						APUS					
3822632-49-8146 Rev 4	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 3822632-1, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 21-Nov-2017 Not Applicable	as per compressor rotor P/N					Hrs					
(AVG MAN HRS: 1)						APUS					
3842064-49-8192	**AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Rework the Turbine Rotor PN 3842064-1 to PN 3842064-5 for Use on Multiple APUs**							T (A/R)			
49 APU1						Mos					
Eff: 21-Oct-2016						Hrs					
						APUS					
3842064-49-8193 Rev 1	**AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Balance Repair of the Turbine Rotors PN 3842064-1 and PN 3842064-5 on Multiple Auxiliary Power Units (APUs)**							RE (-)		Recommended, Service Bulletin	
49 APU1						Mos	14-Apr-2023				
Eff: 14-Sep-2017 Not Applicable	turbine rotor P/N not installed					Hrs					
(NOTE: Honeywell recommends this service bulletin be done for the balance repair of turbine rotors, PN 3842064-1 and PN 3842064-5.)						APUS					
3882730-49-7974	**INSTALL FUEL FLOW DEFLECTOR, PN 70720001-1 ON THE FUEL CONTROL DIFFERENTIAL PRESSURE (DELTA P) SLEEVE**							T (A/R)			
49 APU1						Mos					
Eff: 25-Feb-2009						Hrs					
						APUS					
3882730-49-7974 Rev 2	**Main Fuel Control Unit (FCU) - Install Fuel Flow Deflector, PN 70720001-1 On the Fuel Control Differential Pressure (DELTA P) Sleeve as Required at Next APU Shop Visit. Check Nameplate for Latest Change Number Prior to the FCU Removal**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 11-May-2019 Not Applicable	before manufacture					Hrs					
(AVG MAN HRS: 1)						APUS					
3888021-49-8206	**AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Rework Fluid Pressure Regulating Valve, PN 3880021-2, -5 Thru -17 to PN 70721587-4, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos	09-Apr-2024				
Eff: 07-Apr-2016 Complied With						Hrs	443				
(AVG MAN HRS: 1.5) (NOTE: not found)						APUS	626				
49-7552	**AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE ELECTRONIC CONTROL UNIT (ECU), PN 2118988-1 WITH PN 2118988-2**							T (A/R)			
49 APU1						Mos					
Eff: 13-Oct-1999						Hrs					
						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
49-7691	**REPLACE FUEL SHUTOFF SOLENOID VALVE, PART NO. 692545-17 OR PART NO. 3888134-5 WITH PART NO. 692545-18**							T (A/R)			
49 APU1						Mos					
Eff: 14-Aug-2002						Hrs					
						APUS					
49-7691 Rev 1	**REPLACE FUEL SHUTOFF SOLENOID VALVE, PART NO. 692545-17 OR PART NO. 3888134-5 WITH PART NO. 692545-18**							T (A/R)			
49 APU1						Mos					
Eff: 01-Feb-2003						Hrs					
						APUS					
49-7691 Rev 2	**REPLACE FUEL SHUTOFF SOLENOID VALVE, PART NO. 692545-17 OR PART NO. 3888134-5 WITH PART NO. 692545-18**							T (A/R)			
49 APU1						Mos					
Eff: 03-Aug-2005						Hrs					
						APUS					
49-7717	**Airborne Auxiliary Power - Gas Turbine Engine - Inspection/Replacement of the Coupling Clamp, PN 234-511-9059, T-Bolt (Fuel Control to Lube Pump Flanges)**							T (A/R)			
49 APU1						Mos					
Eff: 25-Sep-2002						Hrs					
						APUS					
49-7717 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Inspection/Replacement of the Coupling Clamp, PN 234-511-9059, T-Bolt (Fuel Control to Lube Pump Flanges)**							T (A/R)			
49 APU1						Mos					
Eff: 25-Sep-2002						Hrs					
						APUS					
49-7717 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Inspection/Replacement of the Coupling Clamp, PN 234-511-9059, T-Bolt (Fuel Control to Lube Pump Flanges)**							T (A/R)			
49 APU1						Mos					
Eff: 17-Apr-2003						Hrs					
						APUS					
49-7730	**REPLACE INLET SCREEN HALVES**							T (A/R)			
49 APU1						Mos					
Eff: 22-Jul-2003						Hrs					
						APUS					
49-7933 Rev 10	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**							T (A/R)		Service Bulletin	
49 APU1						Mos					
Eff: 18-Jan-2022						Hrs					
						APUS					
49-7969	**Replace the Plain Seal (Compressor Seal), Part Number 3616650-1 with Plain Seal (Compressor Seal), Part Number 3616650-3**							T (A/R)			
49 APU1						Mos					
Eff: 30-Apr-2008						Hrs					
						APUS					
49-7969 Rev 1	**Replace the Plain Seal (Compressor Seal), Part Number 3616650-1 with Plain Seal (Compressor Seal), Part Number 3616650-3**							T (A/R)			
49 APU1						Mos					
Eff: 01-Feb-2013						Hrs					
						APUS					
49-7997 Rev 6	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							T (A/R)		Service Bulletin	
49 APU1						Mos					
Eff: 05-Nov-2020						Hrs					
						APUS					
49-8209	**AIRBORNE AUXILIARY POWER (APU) - GAS TURBINE ENGINE - Rework Fluid Pressure Regulating Valve PN 70721587-3 to PN 70721587-4 on Multiple APUs**							RE (-)			
49 APU1						Mos	09-Apr-2024				
Eff: 06-Apr-2016 Complied With						Hrs	443				
						APUS	626				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
49-8210	**SB 49-8210 - Inspect and Replace Fuel Shutoff Valve (FSOV), PN 692545-18, on 36-150 APUs.**							T (A/R)			
49 APU1						Mos					
Eff: 04-Apr-2016						Hrs					
						APUS					
49-8252 Rev 2	**Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs**							T (A/R)		Service Bulletin	
49 APU1						Mos					
Eff: 13-Oct-2020						Hrs					
						APUS					
49-A7758	**ONE TIME INSPECTION/LEAK CHECK ON THE DOWN STREAM SIDE OF THE APU FUEL SHUTOFF VALVE, PART NO. 692545-18**							T (A/R)			
49 APU1						Mos					
Eff: 14-Aug-2003						Hrs					
						APUS					
49-A7758 Rev 1	**ONE TIME INSPECTION/LEAK CHECK ON THE DOWN STREAM SIDE OF THE APU FUEL SHUTOFF VALVE, PART NO. 692545-18**							T (A/R)			
49 APU1						Mos					
Eff: 04-Sep-2003						Hrs					
						APUS					
49-A7758 Rev 2	**ONE TIME INSPECTION/LEAK CHECK ON THE DOWN STREAM SIDE OF THE APU FUEL SHUTOFF VALVE, PART NO. 692545-18**							T (A/R)			
49 APU1						Mos					
Eff: 13-Dec-2004						Hrs					
						APUS					
70721597-49-8166 Rev 3	**Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos	17-Apr-2023				
Eff: 13-Oct-2017 Not Applicable	as per rotor P/N					Hrs					
						APUS					
(AVG MAN HRS: 1) (NOTE: COMPLIANCE: Honeywell recommends this service bulletin be done for the balance repair of the compressor rotor, PN 70721597-1.)											
70721598-49-8168 Rev 3	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos	09-Apr-2024				
Eff: 14-Dec-2017 Complied With						Hrs	443				
(AVG MAN HRS: 1)						APUS	626				
70721725-49-8152 Rev 4	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos	09-Apr-2024				
Eff: 19-Dec-2017 Complied With						Hrs	443				
						APUS	626				
APU-146	**Special On-wing Troubleshooting Check Sheet for Oil "Smell-In-Cabin" (SIC) Complaints**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 18-Aug-2007						Hrs					
						APUS					
APU-151	**Honeywell Commercial Auxiliary Power Unit (APU) Oil Approvals.**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 25-Oct-2007						Hrs					
						APUS					
APU-41 Rev 1	**PRECAUTIONARY MEASURES TO PREVENT EXCESSIVE AXIAL LOADING OF APUGENERATOR OUTPUT SHAFT SEALS AND BEARINGS**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 05-May-1989						Hrs					
						APUS					
APU-42	**IMPROPER SERVICING PROCEDURES - UNAUTHORIZED USE OF SILICONE BASEDLUBRICANTS ON OIL-WETTED COMPONENTS WITHIN THE APU'SLUBRICATION SYSTEM**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 17-Feb-1989						Hrs					
						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
APU-46	**RECOMMENDED ONE-TIME INSPECTION OF NAMEPLATE RIVETS FOR PROPERINSTALLATION**						T (A/R)		Service Information Letter	
49 APU1					Mos					
Eff: 25-Feb-1991					Hrs					
					APUS					
APU-7 Rev 2	**Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)**						T (A/R)		Service Information Letter	
49 APU1					Mos					
Eff: 02-Mar-2015					Hrs					
					APUS					
APU-78 Rev 2	**Auxiliary Power Unit (APU) Operational Instructions**						T (A/R)		Service Information Letter	
49 APU1					Mos					
Eff: 30-Sep-2004					Hrs					
					APUS					
APU-83 Rev 2	**SPOTLIGHT TROUBLESHOOTING SYSTEM**						T (A/R)		Service Information Letter	
49 APU1					Mos					
Eff: 31-Jan-2007					Hrs					
					APUS					
D200904000013	**To advise the field of the release of Service Bulletin GTCP36-49-7969.**						T (A/R)		Service Information Letter	
49 APU1					Mos					
Eff: 13-Apr-2009					Hrs					
					APUS					
D201010000068	**Operations in Volcanically Active Areas**						T (A/R)		Service Information Letter	
49 APU1					Mos					
Eff: 03-Mar-2011					Hrs					
					APUS					
D201012000013 Rev 1	**General Handling Information for Ignition Exciters Containing the Radioactive Element Krypton-85(Krypton 85) Above 10,000 Becquerels**						T (A/R)		Service Information Letter	
49 APU1					Mos					
Eff: 15-Jan-2015					Hrs					
					APUS					
D201107000024 Rev 1	**Approved Use of Biofuel Blends for All Honeywell Commercial and Military Auxiliary Power Units (APU)**						T (A/R)		Service Information Letter	
49 APU1					Mos					
Eff: 03-Jun-2020					Hrs					
					APUS					
D201107000065	**Auxiliary Power Unit Operations in Volcanically Active Areas**						T (A/R)		Service Information Letter	
49 APU1					Mos					
Eff: 19-Aug-2011					Hrs					
					APUS					
D202311004191	**GTCP36-150 Series APU LCV Filter - Removal, Inspection, and Installation Procedure**						T (A/R)		Service Information Letter	
49 APU1					Mos					
Eff: 28-Nov-2023					Hrs					
(NOTE: EFFECTIVITY: Refer to Par. B of this SIL for more information.)					APUS					
GTCP36-49-8119 Rev 4	**Airborne Auxiliary Power - Gas Turbine Engine - Rotating Group Balance Procedure**						T (A/R)		Optional	
49 APU1					Mos					
Eff: 30-Mar-2017					Hrs					
					APUS					
GTCP36-49-8191 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine 36-150[IAI], PN 3800710-1 and PN 3800710-2, for Incorporation of Improved Compressor Carbon Seal and Related Components**						T (A/R)		Optional	
49 APU1					Mos					
Eff: 31-Jan-2019					Hrs					
(NOTE: CONCURRENT REQUIREMENTS)					APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
GTCP36-49-8318	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Fuel Nozzle Assembly, PN 3610004-3 and 3610004-4 with Fuel Nozzle Assembly PN 3610004-5 and 3610004-6 on Affected APU Models**							RE (-)		Recommended	
49 APU1						Mos	20-Oct-2023				
Eff: 30-Jun-2020 Not Applicable						Hrs	333				
(NOTE: COMPLIANCE: This service bulletin is recommended at removal for cause. Cause is defined as an APU that is removed from service for compressor surge or loud bang noise during APU operation.)						APUS	483				
SIL 78	**36-150 EMB APU Lift Fixture, Retrofit of sub-component PN 31060 shoulder bolt**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 11-Sep-2011						Hrs					
						APUS					
SIL APU-152 Rev 4	**Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 08-Feb-2018						Hrs					
						APUS					
SIL D201701000026 Rev 2	**Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine worksheet for 36-100, 36-150, RE100, and RE220 APUs**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 21-Mar-2018						Hrs					
						APUS					
SIL No. APU-49 Rev 13	**Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APU)**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 23-Nov-2023						Hrs					
						APUS					
280-52-013	**Doors - Main Entrance Door (MED) - Installation Of Fiber Optics Viewport (MODG25- 20003)**							RE (-)		Mandatory	
52 A/F						Mos	10-Feb-2023				
Eff: 13-Nov-2012 Complied With						Hrs	24:24				
						Ldg	7				
280-52-116	**Doors - Fuselage Fairing Doors - Wing Tank Drain Valve Door Hinge Rework (MODG25-00579)**							RE (-)		Recommended	
52 A/F						Mos	14-Apr-2023				
Eff: 26-Nov-2014 Not Applicable	as per a/c S/N					Hrs	112:17				
						Ldg	61				
280-52-126	**Doors - Auxiliary Bulkhead Door Lock Mechanism - D-Ring And Bolt Replacement (MODG25-00619)**							RE (-)		Recommended	
52 A/F						Mos	14-Apr-2023				
Eff: 05-Mar-2015 Not Applicable	as per a/c S/N					Hrs	112:17				
						Ldg	61				
280-53-096	**Fuselage - Forward Right Side - Fuel Tank Assembly Rework And Electrical Harness Routing Modification (MODG25-20057)**							RE (-)		Recommended	
53 A/F						Mos	14-Apr-2023				
Eff: 07-Nov-2014 Not Applicable	as per a/c S/N					Hrs	112:17				
						Ldg	61				
280-53-162	**Fuselage - Tail Compartment - Installation Of A Water Collection And Drainage Diversion At Frame 63 (MODG25-00841)**							RE (-)		Recommended	
53 A/F						Mos	14-Apr-2023				
Eff: 02-Feb-2017 Not Applicable	as per a/c S/N					Hrs	112:17				
						Ldg	61				
D202010001408	**Aircraft Nacelle Inlet Cowl Assembly - Gold Tinting/Discoloration of Lip Skin**							T (A/R)		Service Information Letter	
54 ENG1						Mos					
Eff: 17-Nov-2020						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
D202010001408	**Aircraft Nacelle Inlet Cowl Assembly - Gold Tinting/Discoloration of Lip Skin**							T (A/R)		Service Information Letter	
54 ENG2						Mos					
Eff: 17-Nov-2020						Hrs					
						Enc					
280-57-047	**Wings - Wing Flap Track D Roller Fittings Retrofit (MODG25-10708 , MODG25- 07112)**							RE (-)		Recommended	
57 A/F						Mos	14-Apr-2023				
Eff: 19-Jan-2015 Not Applicable	as per a/c S/N					Hrs	112:17				
						Ldg	61				
280-57-133	**Wings - Wing Flap Track A Inboard And Outboard Roller Fittings Retrofit (MODG25- 10710)**							RE (-)		Recommended	
57 A/F						Mos	14-Apr-2023				
Eff: 19-Jan-2015 Not Applicable	as per a/c S/N					Hrs	112:17				
						Ldg	61				
280-57-222	**Wings - Inspection and / or Repair of Flap Spar Cracks On Track D (MODG25-01308)**							RE (-)		Recommended	
57 A/F						Mos	14-Apr-2023				
Eff: 13-May-2016 Not Applicable	as per a/c S/N					Hrs	112:17				
						Ldg	61				
D201406000102 Rev 1	**Setup Instructions for Electronic Engine Interface (EEI) Kit, PN 5837831-4, on all AS907 (HTF) Turbofan Engines**							T (A/R)		Service Information Letter	
71 ENG1						Mos					
Eff: 11-Jan-2021						Hrs					
						Enc					
D201406000102 Rev 1	**Setup Instructions for Electronic Engine Interface (EEI) Kit, PN 5837831-4, on all AS907 (HTF) Turbofan Engines**							T (A/R)		Service Information Letter	
71 ENG2						Mos					
Eff: 11-Jan-2021						Hrs					
						Enc					
D201807000004	**AS907 - Ice Formation in the Air Turbine Starter Start Valve Resulting in a No-Start Condition**							T (A/R)		Service Information Letter	
71 ENG1						Mos					
Eff: 10-Aug-2018						Hrs					
						Enc					
D201807000004	**AS907 - Ice Formation in the Air Turbine Starter Start Valve Resulting in a No-Start Condition**							T (A/R)		Service Information Letter	
71 ENG2						Mos					
Eff: 10-Aug-2018						Hrs					
						Enc					
3727214-SB-001	**DISKBAL BLADE MAPPING SOFTWARE PN 3727214**							T (A/R)			
72 ENG1						Mos					
Eff: 28-Jan-2016						Hrs					
						Enc					
3727214-SB-001	**DISKBAL BLADE MAPPING SOFTWARE PN 3727214**							T (A/R)			
72 ENG2						Mos					
Eff: 28-Jan-2016						Hrs					
						Enc					
72-9045	**ENGINE - COMPRESSOR SECTION - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2**							T (A/R)			
72 ENG1						Mos					
Eff: 18-Apr-2011						Hrs					
						Enc					
72-9045	**ENGINE - COMPRESSOR SECTION - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2**							T (A/R)			
72 ENG2						Mos					
Eff: 18-Apr-2011						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
72-9045 Rev 1	**ENGINE - COMPRESSOR SECTION - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2**							T (A/R)			
72 ENG1						Mos					
Eff: 19-Jul-2012						Hrs					
						Enc					
72-9045 Rev 1	**ENGINE - COMPRESSOR SECTION - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2**							T (A/R)			
72 ENG2						Mos					
Eff: 19-Jul-2012						Hrs					
						Enc					
72-9047	**ENGINE - BY-PASS SECTION - INSTALL NEW VIBRATION DAMPENERS PN 70040770-1**							RE (-)			
72 ENG1						Mos	10-Feb-2023				
Eff: 13-Jun-2012 Complied With						Hrs					
(UPDATE NOTE: AT MANUFACTURE)						Enc					
72-9047	**ENGINE - BY-PASS SECTION - INSTALL NEW VIBRATION DAMPENERS PN 70040770-1**							T (A/R)			
72 ENG2						Mos					
Eff: 13-Jun-2012						Hrs					
						Enc					
72-9050	**ENGINE - LOW PRESSURE TURBINE - INSTALL WASHERS PN NAS1149E0432R IN PLACE OF WASHERSPN NAS1149C0432R**							T (A/R)			
72 ENG1						Mos					
Eff: 06-Sep-2012						Hrs					
						Enc					
72-9050	**ENGINE - LOW PRESSURE TURBINE - INSTALL WASHERS PN NAS1149E0432R IN PLACE OF WASHERSPN NAS1149C0432R**							T (A/R)			
72 ENG2						Mos					
Eff: 06-Sep-2012						Hrs					
						Enc					
AS907-3 Rev 4	**AS907 Trend Monitoring System**							T (A/R)		Service Information Letter	
72 ENG1						Mos					
Eff: 06-Oct-2021						Hrs					
						Enc					
AS907-3 Rev 4	**AS907 Trend Monitoring System**							T (A/R)		Service Information Letter	
72 ENG2						Mos					
Eff: 06-Oct-2021						Hrs					
						Enc					
AS907-72-9005	**SB AS907-72-9005 - Installation of Engine Water Wash System**							RE (-)			
72 ENG1						Mos					
Eff: 25-Mar-2005						Hrs					
						Enc					
AS907-72-9005	**SB AS907-72-9005 - Installation of Engine Water Wash System**							RE (-)			
72 ENG2						Mos					
Eff: 25-Mar-2005						Hrs					
						Enc					
AS907-72-9005 Rev 1	**ENGINE - GENERAL - Installation of Engine Water Wash System on AS907 Engines Models**							T (A/R)			
72 ENG1						Mos					
Eff: 07-Aug-2013						Hrs					
						Enc					
AS907-72-9005 Rev 1	**ENGINE - GENERAL - Installation of Engine Water Wash System on AS907 Engines Models**							T (A/R)			
72 ENG2						Mos					
Eff: 07-Aug-2013						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-72-9005 Rev 2	**ENGINE - GENERAL - Installation of Engine Water Wash System on AS907 Engines Models**							T (A/R)			
72 ENG1						Mos					
Eff: 16-Nov-2015						Hrs					
						Enc					
AS907-72-9005 Rev 2	**ENGINE - GENERAL - Installation of Engine Water Wash System on AS907 Engines Models**							T (A/R)			
72 ENG2						Mos					
Eff: 16-Nov-2015						Hrs					
						Enc					
AS907-72-9005 Rev 3	**ENGINE - GENERAL - Installation of Engine Water Wash System on AS907 Engines Models**							RE (-)			
72 ENG1						Mos	10-Feb-2023				
Eff: 29-Aug-2016 Not Applicable	PER ENGINE PART NUMBER					Hrs					
						Enc					
AS907-72-9005 Rev 3	**ENGINE - GENERAL - Installation of Engine Water Wash System on AS907 Engines Models**							RE (-)			
72 ENG2						Mos	10-Feb-2023				
Eff: 29-Aug-2016 Not Applicable	PER ENGINE PART NUMBER					Hrs					
						Enc					
AS907-72-9005 Rev 4	**Engine - General - Installation of Engine Water Wash System, on AS907 Engines Models**							T (A/R)		Category 3	
72 ENG1						Mos	10-Feb-2023				
Eff: 14-Jul-2020 Not Applicable	PER ENGINE PART NUMBER					Hrs					
(AVG MAN HRS: 6)						Enc					
AS907-72-9005 Rev 4	**Engine - General - Installation of Engine Water Wash System, on AS907 Engines Models**							T (A/R)		Category 3	
72 ENG2						Mos	10-Feb-2023				
Eff: 14-Jul-2020 Not Applicable	PER ENGINE PART NUMBER					Hrs					
(AVG MAN HRS: 6)						Enc					
AS907-72-9047	**Bypass Section - Install New Vibration Dampeners, Pn 70040770-1**							RE (-)		Category 3	
72 ENG1						Mos	10-Apr-2023				
Complied With	AT MANUFACTURE					Hrs	84:18				
(AVG MAN HRS: 1)						Enc	54				
AS907-72-9047	**Bypass Section - Install New Vibration Dampeners, Pn 70040770-1**							RE (-)		Category 3	
72 ENG2						Mos	10-Apr-2023				
Complied With	AT MANUFACTURE					Hrs	104:18				
(AVG MAN HRS: 1)						Enc	66				
AS907-72-9050	**Low Pressure Turbine - Install Washers, Pn Nas1149E0432R, In Place Of Washers, Pn Nas1149C0432R**							RE (-)		Category 2	
72 ENG1						Mos	26-Jan-2023				
Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
AS907-72-9050	**Low Pressure Turbine - Install Washers, Pn Nas1149E0432R, In Place Of Washers, Pn Nas1149C0432R**							RE (-)		Category 2	
72 ENG2						Mos	20-Jan-2023				
Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
AS907-72-9051	**ENGINE - HP TURBINE SECTION - INSTALL NEW STAGE 1 HIGH PRESSURE TURBINE (HPT1) ROTOR ASSEMBLY PN 70040856-1**							RE (-)			
72 ENG1						Mos	26-Jan-2023				
Eff: 14-Jan-2014 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-72-9051	**ENGINE - HP TURBINE SECTION - INSTALL NEW STAGE 1 HIGH PRESSURE TURBINE (HPT1) ROTOR ASSEMBLY PN 70040856-1**							RE (-)			
72 ENG2						Mos	20-Jan-2023				
Eff: 14-Jan-2014 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
AS907-72-9052	**ENGINE - HIGH PRESSURE TURBINE SECTION - Install New Double Stage 1 Nozzle Inner Seals PN70040688-1 and Stage 1 Nozzle Outer Seals PN 70040687-1 in the First Stage High Pressure TurbineNozzle Assembly on AS907-2-1G Engine Models**							RE (-)			
72 ENG1						Mos	10-Feb-2023				
Eff: 05-May-2015 Not Applicable	PER S/N. INCORPORATED IN PRODUCTION					Hrs					
						Enc	2				
AS907-72-9052	**ENGINE - HIGH PRESSURE TURBINE SECTION - Install New Double Stage 1 Nozzle Inner Seals PN70040688-1 and Stage 1 Nozzle Outer Seals PN 70040687-1 in the First Stage High Pressure TurbineNozzle Assembly on AS907-2-1G Engine Models**							RE (-)			
72 ENG2						Mos	10-Feb-2023				
Eff: 05-May-2015 Not Applicable	PER S/N. INCORPORATED IN PRODUCTION					Hrs					
						Enc					
AS907-72-9053	**ENGINE - BYPASS SECTION - Install New Fan Stator Vanes PN 70040191-1 or New/Reworked Fan Stator Vane Assembly for AS907-1-1A and AS907-2-1G Model Engines**							RE (-)			
72 ENG1						Mos	10-Feb-2023				
Eff: 20-Nov-2015 Not Applicable	PER S/N, incorporated in Production					Hrs					
						Enc					
AS907-72-9053	**ENGINE - BYPASS SECTION - Install New Fan Stator Vanes PN 70040191-1 or New/Reworked Fan Stator Vane Assembly for AS907-1-1A and AS907-2-1G Model Engines**							RE (-)			
72 ENG2						Mos	10-Feb-2023				
Eff: 20-Nov-2015 Not Applicable	PER S/N, incorporated in Production					Hrs					
						Enc					
AS907-72-9060	**ENGINE - HP COMPRESSOR - New Investment Cast Front Frame Assemblies PN 70040792-2 and PN 70040792-3 for Affected AS907 Engine Models**							RE (-)			
72 ENG1						Mos	10-Feb-2023				
Eff: 19-Dec-2014 Not Applicable	PER S/N. INCORPORATED IN PRODUCTION					Hrs					
						Enc					
AS907-72-9060	**ENGINE - HP COMPRESSOR - New Investment Cast Front Frame Assemblies PN 70040792-2 and PN 70040792-3 for Affected AS907 Engine Models**							RE (-)			
72 ENG2						Mos	10-Feb-2023				
Eff: 19-Dec-2014 Not Applicable	PER S/N. INCORPORATED IN PRODUCTION					Hrs					
						Enc					
AS907-72-9061	**ENGINE - HIGH PRESSURE COMPRESSOR (HPC) ASSEMBLY - Inspect the Bore of the 2nd 3rd and 4th Stage Axial Compressor Blisks and Replace Non-conforming Blisks on AS907-1-1A and AS907-2-1G Model Engines**							RE (-)			
72 ENG1						Mos	10-Feb-2023				
Eff: 01-Sep-2015 Not Applicable	PER S/N. INCORPORATED IN PRODUCTION					Hrs					
						Enc					
AS907-72-9061	**ENGINE - HIGH PRESSURE COMPRESSOR (HPC) ASSEMBLY - Inspect the Bore of the 2nd 3rd and 4th Stage Axial Compressor Blisks and Replace Non-conforming Blisks on AS907-1-1A and AS907-2-1G Model Engines**							RE (-)			
72 ENG2						Mos	10-Feb-2023				
Eff: 01-Sep-2015 Not Applicable	PER S/N. INCORPORATED IN PRODUCTION					Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-72-9064	**ENGINE - BYPASS SECTION - Apply Secondary Corrosion Protection (Paint) to Forward Outer FanBypass Duct PN WBA7271E102-XXX and/or Aft Outer Fan Bypass Duct PN WBA7271E112-XXX and/orInner Fan Bypass Duct Panels and Supports on AS907 Engines**						T (A/R)			
72 ENG1					Mos					
Eff: 12-Jun-2015					Hrs					
					Enc					
AS907-72-9064	**ENGINE - BYPASS SECTION - Apply Secondary Corrosion Protection (Paint) to Forward Outer FanBypass Duct PN WBA7271E102-XXX and/or Aft Outer Fan Bypass Duct PN WBA7271E112-XXX and/orInner Fan Bypass Duct Panels and Supports on AS907 Engines**						T (A/R)			
72 ENG2					Mos					
Eff: 12-Jun-2015					Hrs					
					Enc					
AS907-72-9064 Rev 1	**ENGINE - BYPASS SECTION - Apply Secondary Corrosion Protection (Paint) to Forward Outer FanBypass Duct PN WBA7271E102-XXX and/or Aft Outer Fan Bypass Duct PN WBA7271E112-XXX and/orInner Fan Bypass Duct Panels and Supports on AS907 Engines**						RE (-)			
72 ENG1					Mos	10-Feb-2023				
Eff: 14-Mar-2016 Not Applicable	PER ENGINE PART NUMBER				Hrs					
					Enc					
AS907-72-9064 Rev 1	**ENGINE - BYPASS SECTION - Apply Secondary Corrosion Protection (Paint) to Forward Outer FanBypass Duct PN WBA7271E102-XXX and/or Aft Outer Fan Bypass Duct PN WBA7271E112-XXX and/orInner Fan Bypass Duct Panels and Supports on AS907 Engines**						RE (-)			
72 ENG2					Mos	10-Feb-2023				
Eff: 14-Mar-2016 Not Applicable	PER ENGINE PART NUMBER				Hrs					
					Enc					
AS907-72-9066	**Engine - HP Turbine Section - Install New Stage 1 High Pressure Turbine (HTP1) Rotor Assembly PN 70040856-6 and High Pressure Turbine (HPT) Nozzle Support PN 3035056-6 for AS907-2-1G Model Engines**						T (A/R)		Category 3, Optional	
72 ENG1					Mos					
Eff: 19-Sep-2018					Hrs					
(NOTE: CONCURRENT REQUIREMENTS)					Enc					
AS907-72-9066	**Engine - HP Turbine Section - Install New Stage 1 High Pressure Turbine (HTP1) Rotor Assembly PN 70040856-6 and High Pressure Turbine (HPT) Nozzle Support PN 3035056-6 for AS907-2-1G Model Engines**						T (A/R)		Category 3, Optional	
72 ENG2					Mos					
Eff: 19-Sep-2018					Hrs					
(NOTE: CONCURRENT REQUIREMENTS)					Enc					
AS907-72-9089	**Engine - Air Inlet Section - Install New Fan Inlet Housings on AS907 Model Engines**						T (A/R)		Category 3, Optional	
72 ENG1					Mos					
Eff: 03-Mar-2020					Hrs					
					Enc					
AS907-72-9089	**Engine - Air Inlet Section - Install New Fan Inlet Housings on AS907 Model Engines**						T (A/R)		Category 3, Optional	
72 ENG2					Mos					
Eff: 03-Mar-2020					Hrs					
					Enc					
AS907-72-9091 Rev 1	**Engine - HP Turbine Section - HPT-2 Rotor Assembly, PN 3035135-2/-4/-5/-6/-7, Institute Enhanced Inspection and Reporting for the HPT Rotating Interstage Seal, PN 3035134-1 or PN 3035134-3 on AS907 Model Engines**						RE (-)		Cat. 2 - Recommended	
72 ENG1					Mos	17-Apr-2023				
Eff: 22-Mar-2021 Not Applicable	before manufacture				Hrs	97:47				
					Enc	64				
(AVG MAN HRS: 1) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at first access to affected parts.)										

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-72-9091 Rev 1	**Engine - HP Turbine Section - HPT-2 Rotor Assembly, PN 3035135-2/-4/-5/-6/-7, Institute Enhanced Inspection and Reporting for the HPT Rotating Interstage Seal, PN 3035134-1 or PN 3035134-3 on AS907 Model Engines**							RE (-)		Cat. 2 - Recommended	
72 ENG2						Mos	17-Apr-2023				
Eff: 22-Mar-2021 Not Applicable	before manufacture					Hrs	117:47				
						Enc	76				
(AVG MAN HRS: 1) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at first access to affected parts.)											
AS907-72-9095RWK	**Engine - Turbine Section - Rework, HPT Case, Matched Set Assembly with New HPT1 Shroud Segments and/or New or Serviceable HPT2 Shroud Segments**							RE (-)		Service Bulletin	
72 ENG1						Mos	17-Apr-2023				
Eff: 13-Dec-2021 Not Applicable	applicable before manufacture					Hrs	97:47				
						Enc	64				
(ZONE: 16.5)											
AS907-72-9095RWK	**Engine - Turbine Section - Rework, HPT Case, Matched Set Assembly with New HPT1 Shroud Segments and/or New or Serviceable HPT2 Shroud Segments**							RE (-)		Service Bulletin	
72 ENG2						Mos	17-Apr-2023				
Eff: 13-Dec-2021 Not Applicable	applicable before manufacture					Hrs	117:47				
						Enc	76				
(ZONE: 16.5)											
D201212000050 Rev 1	**Engine Preservation Procedures; Use of Castrol Brayco 599 Rust Preventive Concentrate for Synthetic Turbine Oil**							T (A/R)		Service Information Letter	
72 ENG1						Mos					
Eff: 08-Aug-2023						Hrs					
						Enc					
D201212000050 Rev 1	**Engine Preservation Procedures; Use of Castrol Brayco 599 Rust Preventive Concentrate for Synthetic Turbine Oil**							T (A/R)		Service Information Letter	
72 ENG2						Mos					
Eff: 08-Aug-2023						Hrs					
						Enc					
D201603000064 Rev 1	**AS907 Engine Ground Start Procedure Following Shutdown (Quick Turn Around)**							T (A/R)		Service Information Letter	
72 ENG1						Mos					
Eff: 27-Aug-2020						Hrs					
						Enc					
D201603000064 Rev 1	**AS907 Engine Ground Start Procedure Following Shutdown (Quick Turn Around)**							T (A/R)		Service Information Letter	
72 ENG2						Mos					
Eff: 27-Aug-2020						Hrs					
						Enc					
D201903000028 Rev 1	**AS907 Aft Sump Event Discussion**							T (A/R)		Service Information Letter	
72 ENG1						Mos					
Eff: 11-Jun-2021						Hrs					
						Enc					
D201903000028 Rev 1	**AS907 Aft Sump Event Discussion**							T (A/R)		Service Information Letter	
72 ENG2						Mos					
Eff: 11-Jun-2021						Hrs					
						Enc					
D201908000020	**Honeywell AS907 Oil Filter Analysis Program**							T (A/R)		Service Information Letter	
72 ENG1						Mos					
Eff: 21-Aug-2019						Hrs					
						Enc					
D201908000020	**Honeywell AS907 Oil Filter Analysis Program**							T (A/R)		Service Information Letter	
72 ENG2						Mos					
Eff: 21-Aug-2019						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
D202001000409	**Usage-Based MSP Program**						T (A/R)		Service Information Letter	
72 ENG1					Mos					
Eff: 22-Jan-2020					Hrs					
					Enc					
D202001000409	**Usage-Based MSP Program**						T (A/R)		Service Information Letter	
72 ENG2					Mos					
Eff: 22-Jan-2020					Hrs					
					Enc					
D202008001224	**Transition of No. 4 Carbon Seal Oil Pressure Bimodality Monitoring and Inspection Recommendations via Engine Health Monitoring Report (EHM) to CAMP**						T (A/R)		Service Information Letter	
72 ENG1					Mos					
Eff: 27-Aug-2020					Hrs					
					Enc					
D202008001224	**Transition of No. 4 Carbon Seal Oil Pressure Bimodality Monitoring and Inspection Recommendations via Engine Health Monitoring Report (EHM) to CAMP**						T (A/R)		Service Information Letter	
72 ENG2					Mos					
Eff: 27-Aug-2020					Hrs					
					Enc					
D202102001590 Rev 5	**Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download 1.8.0 and Honeywell Forge Engine Data Viewer (EDV)**						T (A/R)		Service Information Letter	
72 ENG1					Mos					
Eff: 29-Jun-2023					Hrs					
					Enc					
D202102001590 Rev 5	**Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download 1.8.0 and Honeywell Forge Engine Data Viewer (EDV)**						T (A/R)		Service Information Letter	
72 ENG2					Mos					
Eff: 29-Jun-2023					Hrs					
					Enc					
D202109001999	**AS907 Turbofan Engine Low Pressure Turbine Blade; Recommended Service Lives**						T (A/R)		Service Information Letter	
72 ENG1					Mos					
Eff: 21-Sep-2021					Hrs					
					Enc					
D202109001999	**AS907 Turbofan Engine Low Pressure Turbine Blade; Recommended Service Lives**						T (A/R)		Service Information Letter	
72 ENG2					Mos					
Eff: 21-Sep-2021					Hrs					
					Enc					
D202208002772	**AS907 Engine Thermal Anti-Ice Valve (TAIV) PN WBG3020G103-003**						T (A/R)		Service Information Letter	
72 ENG1					Mos					
Eff: 10-Aug-2022					Hrs					
					Enc					
D202208002772	**AS907 Engine Thermal Anti-Ice Valve (TAIV) PN WBG3020G103-003**						T (A/R)		Service Information Letter	
72 ENG2					Mos					
Eff: 10-Aug-2022					Hrs					
					Enc					
D202306004018	**Honeywell Service Bulletin AS907-76-9014 for AS907-2-1G Model Engines Used on Gulfstream G280 Aircraft and an Impending Federal Aviation Administration (FAA) Airworthiness Directive (AD)**						T (A/R)		Service Information Letter	
72 ENG1					Mos					
Eff: 22-Jun-2023					Hrs					
	(NOTE: EFFECTIVITY: Aircraft powered by the AS907-2-1G turbofan engine with Electronic Control Units (ECUs), PN 2119576-3001 or PN 2119576-3002, installed.)				Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
D202306004018	**Honeywell Service Bulletin AS907-76-9014 for AS907-2-1G Model Engines Used on Gulfstream G280 Aircraft and an Impending Federal Aviation Administration (FAA) Airworthiness Directive (AD)**						T (A/R)		Service Information Letter	
72 ENG2					Mos					
Eff: 22-Jun-2023					Hrs					
(NOTE: EFFECTIVITY: Aircraft powered by the AS907-2-1G turbofan engine with Electronic Control Units (ECUs), PN 2119576-3001 or PN 2119576-3002, installed.)					Enc					
442650-73-0001	**Engine Fuel and Control - Model FH-C6 Hydromechanical Unit - Incorporation of New Main Body Assembly with Fuel Vent Plug to the PX2 Fuel Pressure Port**						RE (-)		Recommended	
73 ENG1					Mos	14-Apr-2023				
Eff: 11-Feb-2019 Not Applicable	HMU 442650 not installed				Hrs	87:53				
(AVG MAN HRS: 20)					Enc	56				
442650-73-0001	**Engine Fuel and Control - Model FH-C6 Hydromechanical Unit - Incorporation of New Main Body Assembly with Fuel Vent Plug to the PX2 Fuel Pressure Port**						RE (-)		Recommended	
73 ENG2					Mos	14-Apr-2023				
Eff: 11-Feb-2019 Not Applicable	HMU 442650 not installed				Hrs	107:53				
(AVG MAN HRS: 20)					Enc	68				
442661-73-0001	**ENGINE FUEL AND CONTROL - MODEL FH-C3 HYDROMECHANICAL UNIT (HMU) - Replacement of the Metering Valve Assembly With One Having a Larger Metered Flow Window For Increased Flow**						T (A/R)			
73 ENG1					Mos					
Eff: 05-Apr-2017					Hrs					
					Enc					
442661-73-0001	**ENGINE FUEL AND CONTROL - MODEL FH-C3 HYDROMECHANICAL UNIT (HMU) - Replacement of the Metering Valve Assembly With One Having a Larger Metered Flow Window For Increased Flow**						T (A/R)			
73 ENG2					Mos					
Eff: 05-Apr-2017					Hrs					
					Enc					
442661-73-0002	**Engine Fuel and Control - Model FH-C3 Hydromechanical Unit (HMU) (HFT 7000) - Incorporation of New Main Fuel Pump Assembly**						RE (-)		Recommended	
73 ENG1					Mos	14-Apr-2023				
Eff: 17-Jan-2019 Not Applicable	fuel pump PN 82011224-001 installed				Hrs	87:53				
(AVG MAN HRS: 4)					Enc	56				
442661-73-0002	**Engine Fuel and Control - Model FH-C3 Hydromechanical Unit (HMU) (HFT 7000) - Incorporation of New Main Fuel Pump Assembly**						RE (-)		Recommended	
73 ENG2					Mos	14-Apr-2023				
Eff: 17-Jan-2019 Not Applicable	fuel pump PN 82011224-001 installed				Hrs	107:53				
(AVG MAN HRS: 4)					Enc	68				
AS907-73-9005	**ENGINE FUEL AND CONTROL - CONTROLLING SECTION - Replace Non-Conforming Main Fuel Control PN 442324 with PN 442661 on AS907-2-1G Model Engines**						RE (-)			
73 ENG1					Mos	10-Feb-2023				
Eff: 14-Apr-2017 Not Applicable	PER ENGINE PART NUMBER				Hrs					
					Enc					
AS907-73-9005	**ENGINE FUEL AND CONTROL - CONTROLLING SECTION - Replace Non-Conforming Main Fuel Control PN 442324 with PN 442661 on AS907-2-1G Model Engines**						RE (-)			
73 ENG2					Mos	10-Feb-2023				
Eff: 14-Apr-2017 Not Applicable	PER ENGINE PART NUMBER				Hrs					
					Enc					
2119576-76-4181	**ENGINE CONTROLS - POWER CONTROLS - Modify the Electronic Control Unit (ECU) From PN 2119576-3001 to PN 2119576-3002**						T (A/R)			
76 ENG1					Mos					
Eff: 15-Aug-2014					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2119576-76-4181	**ENGINE CONTROLS - POWER CONTROLS - Modify the Electronic Control Unit (ECU) From PN 2119576-3001 to PN 2119576-3002**							T (A/R)			
76 ENG2						Mos					
Eff: 15-Aug-2014						Hrs					
						Enc					
2119576-76-4181 Rev 1	**ENGINE CONTROLS - POWER CONTROLS - Modify the Electronic Control Unit (ECU) From PN 2119576-3001 to PN 2119576-3002**							T (A/R)			
76 ENG1						Mos	10-Feb-2023				
Eff: 18-Sep-2014 Not Applicable	PER ECU PART NUMBER, incorporated in production					Hrs					
						Enc					
2119576-76-4181 Rev 1	**ENGINE CONTROLS - POWER CONTROLS - Modify the Electronic Control Unit (ECU) From PN 2119576-3001 to PN 2119576-3002**							RE (-)			
76 ENG2						Mos	10-Feb-2023				
Eff: 18-Sep-2014 Not Applicable	PER ECU PART NUMBER, incorporated in production					Hrs					
						Enc					
540-1796-76-0001	**ENGINE CONTROLS - SOLENOID OPERATED BLEED VALVE - Replace the Solenoid Assembly PN 540-1817-1 with PN 80000152-001**							T (A/R)			
76 ENG1						Mos					
Eff: 06-Apr-2017						Hrs					
						Enc					
540-1796-76-0001	**ENGINE CONTROLS - SOLENOID OPERATED BLEED VALVE - Replace the Solenoid Assembly PN 540-1817-1 with PN 80000152-001**							T (A/R)			
76 ENG2						Mos					
Eff: 06-Apr-2017						Hrs					
						Enc					
540-1798-76-0001	**ENGINE CONTROLS - SOLENOID OPERATED BLEED VALVE - Replace the Solenoid Assembly PN 540-1839-1 with PN 80000153-001**							T (A/R)			
76 ENG1						Mos					
Eff: 06-Apr-2017						Hrs					
						Enc					
540-1798-76-0001	**ENGINE CONTROLS - SOLENOID OPERATED BLEED VALVE - Replace the Solenoid Assembly PN 540-1839-1 with PN 80000153-001**							T (A/R)			
76 ENG2						Mos					
Eff: 06-Apr-2017						Hrs					
						Enc					
76-9016	**ENGINE CONTROLS - POWER CONTROLS - INSTALL SOFTWARE VERSION 90721G0201 IN ELECTRONIC CONTROL UNIT (ECU)**							T (A/R)			
76 ENG1						Mos					
Eff: 24-Jul-2013						Hrs					
						Enc					
76-9016	**ENGINE CONTROLS - POWER CONTROLS - INSTALL SOFTWARE VERSION 90721G0201 IN ELECTRONIC CONTROL UNIT (ECU)**							T (A/R)			
76 ENG2						Mos					
Eff: 24-Jul-2013						Hrs					
						Enc					
76-9016 Rev 1	**ENGINE CONTROLS - POWER CONTROLS - INSTALL SOFTWARE VERSION 90721G0201 IN ELECTRONIC CONTROL UNIT (ECU)**							RE (-)			
76 ENG1						Mos	26-Jan-2023				
Eff: 03-Dec-2013 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
76-9016 Rev 1	**ENGINE CONTROLS - POWER CONTROLS - INSTALL SOFTWARE VERSION 90721G0201 IN ELECTRONIC CONTROL UNIT (ECU)**							RE (-)			
76 ENG2						Mos	20-Jan-2023				
Eff: 03-Dec-2013 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-76-9014	**ENGINE CONTROLS - POWER CONTROLS - Install Improved Electronic Control Unit (ECU) PN 2119576-3102 on AS907-2-1G Model Engines**							RE (-)			
76 ENG1						Mos	10-Feb-2023				
Eff: 24-Jan-2017 Not Applicable	PER ENGINE PART NUMBER					Hrs					
						Enc					
AS907-76-9014	**ENGINE CONTROLS - POWER CONTROLS - Install Improved Electronic Control Unit (ECU) PN 2119576-3102 on AS907-2-1G Model Engines**							RE (-)			
76 ENG2						Mos	10-Feb-2023				
Eff: 24-Jan-2017 Not Applicable	PER ENGINE PART NUMBER					Hrs					
						Enc					
AS907-76-9015	**ENGINE CONTROLS - EMERGENCY SHUTDOWN - Replace Bracket PN 3038418-14 With PN 70040451-2 on AS907 Model Engines**							RE (-)			
76 ENG1						Mos	10-Feb-2023				
Eff: 09-Dec-2016 Not Applicable	PER S/N, incorporated in Production					Hrs					
						Enc					
AS907-76-9015	**ENGINE CONTROLS - EMERGENCY SHUTDOWN - Replace Bracket PN 3038418-14 With PN 70040451-2 on AS907 Model Engines**							RE (-)			
76 ENG2						Mos	10-Feb-2023				
Eff: 09-Dec-2016 Not Applicable	PER S/N, incorporated in Production					Hrs					
						Enc					
AS907-76-9018	**ENGINE CONTROLS - EMERGENCY SHUTDOWN - New Alternate Overspeed Shutoff Detector (OSSD) on AS907 Engine Models**							T (A/R)			
76 ENG1						Mos					
Eff: 23-Jan-2015						Hrs					
						Enc					
AS907-76-9018	**ENGINE CONTROLS - EMERGENCY SHUTDOWN - New Alternate Overspeed Shutoff Detector (OSSD) on AS907 Engine Models**							T (A/R)			
76 ENG2						Mos					
Eff: 23-Jan-2015						Hrs					
						Enc					
AS907-76-9018 Rev 1	**ENGINE CONTROLS - EMERGENCY SHUTDOWN - New Alternate Overspeed Shutoff Detector (OSSD) on AS907 Engine Models**							RE (-)			
76 ENG1						Mos	26-Jan-2023				
Eff: 09-Nov-2015 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
AS907-76-9018 Rev 1	**ENGINE CONTROLS - EMERGENCY SHUTDOWN - New Alternate Overspeed Shutoff Detector (OSSD) on AS907 Engine Models**							RE (-)			
76 ENG2						Mos	20-Jan-2023				
Eff: 09-Nov-2015 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
AS907-76-9021	**SB AS907-76-9021 - Apply Sealant to Prevent Water Entry Into Electronic Control Unit (ECU) on AS907 Model Engines**							T (A/R)			
76 ENG1						Mos					
Eff: 13-May-2016						Hrs					
						Enc					
AS907-76-9021	**SB AS907-76-9021 - Apply Sealant to Prevent Water Entry Into Electronic Control Unit (ECU) on AS907 Model Engines**							T (A/R)			
76 ENG2						Mos					
Eff: 13-May-2016						Hrs					
						Enc					
D202401004213	**A Discussion Regarding the AS907 Wire Harnesses; Issue and Investigation**							T (A/R)		Service Information Letter	
76 ENG1						Mos					
Eff: 02-Feb-2024						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
D202401004213	**A Discussion Regarding the AS907 Wire Harnesses; Issue and Investigation**							T (A/R)		Service Information Letter	
76 ENG2						Mos					
Eff: 02-Feb-2024						Hrs					
						Enc					
AS907-77-9001	**ENGINE INDICATING - TEMPERATURE - Replace Brackets PN 3038418-13 and PN 3038418-15 With PN 70040328-2 on AS907 Model Engines**							RE (-)			
77 ENG1						Mos	10-Feb-2023				
Eff: 12-Dec-2016 Not Applicable	PER S/N, incorporated in Production					Hrs					
						Enc					
AS907-77-9001	**ENGINE INDICATING - TEMPERATURE - Replace Brackets PN 3038418-13 and PN 3038418-15 With PN 70040328-2 on AS907 Model Engines**							RE (-)			
77 ENG2						Mos	10-Feb-2023				
Eff: 12-Dec-2016 Not Applicable	PER S/N, incorporated in Production					Hrs					
						Enc					
D202107001885	**Aircraft Nacelle Thrust Reverser Unit (TRU) - Use of Non-Honeywell Authorized Corrosion Repairs and Prevention Systems**							T (A/R)		Service Information Letter	
78 ENG1						Mos					
Eff: 26-Jul-2021						Hrs					
						Enc					
D202107001885	**Aircraft Nacelle Thrust Reverser Unit (TRU) - Use of Non-Honeywell Authorized Corrosion Repairs and Prevention Systems**							T (A/R)		Service Information Letter	
78 ENG2						Mos					
Eff: 26-Jul-2021						Hrs					
						Enc					
D202308004115 Rev 2	**Thrust Reverser Unit (TRU) - MAPAERO Observations**							T (A/R)		Service Information Letter	
78 ENG1						Mos					
Eff: 17-Jun-2024						Hrs					
						Enc					
D202308004115 Rev 2	**Thrust Reverser Unit (TRU) - MAPAERO Observations**							T (A/R)		Service Information Letter	
78 ENG2						Mos					
Eff: 17-Jun-2024						Hrs					
						Enc					
79-9050	**ENGINE - LOW PRESSURE TURBINE - INSTALL WASHERS PN NAS1149E0432R IN PLACE OF WASHERS PN NAS1149C0432R ? INACTIVATED FOR FURTHER ACCOMPLISHMENT**							T (A/R)			
79 ENG1						Mos					
Eff: 06-Sep-2012						Hrs					
						Enc					
79-9050	**ENGINE - LOW PRESSURE TURBINE - INSTALL WASHERS PN NAS1149E0432R IN PLACE OF WASHERS PN NAS1149C0432R ? INACTIVATED FOR FURTHER ACCOMPLISHMENT**							T (A/R)			
79 ENG2						Mos					
Eff: 06-Sep-2012						Hrs					
						Enc					
79-9050 Rev 1	**ENGINE - LOW PRESSURE TURBINE - INSTALL WASHERS PN NAS1149E0432R IN PLACE OF WASHERS PN NAS1149C0432R ? INACTIVATED FOR FURTHER ACCOMPLISHMENT**							T (A/R)			
79 ENG1						Mos					
Eff: 06-Sep-2012						Hrs					
						Enc					
79-9050 Rev 1	**ENGINE - LOW PRESSURE TURBINE - INSTALL WASHERS PN NAS1149E0432R IN PLACE OF WASHERS PN NAS1149C0432R ? INACTIVATED FOR FURTHER ACCOMPLISHMENT**							T (A/R)			
79 ENG2						Mos					
Eff: 06-Sep-2012						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AS907-79-9007	**SB AS907-79-9007 - Rework Oil Filler Cap Assembly, PN 3036061-3, to Prevent Chain Interference During Oil Supply Servicing**							T (A/R)			
79 ENG1						Mos					
Eff: 15-Dec-2011						Hrs					
						Enc					
AS907-79-9007	**SB AS907-79-9007 - Rework Oil Filler Cap Assembly, PN 3036061-3, to Prevent Chain Interference During Oil Supply Servicing**							T (A/R)			
79 ENG2						Mos					
Eff: 15-Dec-2011						Hrs					
						Enc					
AS907-79-9007 Rev 1	**SB AS907-79-9007R1 - Rework Oil Filler Cap Assembly, PN 3036061-3, to Prevent Chain Interference During Oil Supply Servicing**							T (A/R)			
79 ENG1						Mos					
Eff: 10-Dec-2012						Hrs					
						Enc					
AS907-79-9007 Rev 1	**SB AS907-79-9007R1 - Rework Oil Filler Cap Assembly, PN 3036061-3, to Prevent Chain Interference During Oil Supply Servicing**							T (A/R)			
79 ENG2						Mos					
Eff: 10-Dec-2012						Hrs					
						Enc					
AS907-79-9007 Rev 2	**OIL - STORAGE SECTION - Rework Oil Filler Cap Assembly PN 3036061-3 to Prevent Chain Interference During Oil Supply Servicing for AS907 Model Engines**							RE (-)			
79 ENG1						Mos					
Eff: 09-Mar-2015						Hrs					
						Enc					
AS907-79-9007 Rev 2	**OIL - STORAGE SECTION - Rework Oil Filler Cap Assembly PN 3036061-3 to Prevent Chain Interference During Oil Supply Servicing for AS907 Model Engines**							RE (-)			
79 ENG2						Mos					
Eff: 09-Mar-2015						Hrs					
						Enc					
AS907-79-9008	**OIL - DISTRIBUTION - Install New Oil Scavenge Metal Tube Assembly and Bracket for AS907 Engine Models**							RE (-)			
79 ENG1						Mos	10-Feb-2023				
Eff: 27-Feb-2017 Not Applicable	PER S/N, incorporated in Production					Hrs					
						Enc					
AS907-79-9008	**OIL - DISTRIBUTION - Install New Oil Scavenge Metal Tube Assembly and Bracket for AS907 Engine Models**							RE (-)			
79 ENG2						Mos	10-Feb-2023				
Eff: 27-Feb-2017 Not Applicable	PER S/N, incorporated in Production					Hrs					
						Enc					
AS907-79-9009	**OIL - DISTRIBUTION - Replace Bolt PN AS3236-06 with PN AS3236-05 on the Upper Tube Retainer of the No. 3 Bearing Oil Drain Tube Assembly on AS907-1 -1A and AS907-2-1G Engines**							RE (-)			
79 ENG1						Mos	26-Jan-2023				
Eff: 05-May-2015 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
AS907-79-9009	**OIL - DISTRIBUTION - Replace Bolt PN AS3236-06 with PN AS3236-05 on the Upper Tube Retainer of the No. 3 Bearing Oil Drain Tube Assembly on AS907-1 -1A and AS907-2-1G Engines**							RE (-)			
79 ENG2						Mos	20-Jan-2023				
Eff: 05-May-2015 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
D201908000007	**AS907 Oil Pump Discussion**							T (A/R)		Service Information Letter	
79 ENG1						Mos					
Eff: 17-Sep-2019						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
D201908000007	**AS907 Oil Pump Discussion**							T (A/R)		Service Information Letter	
79 ENG2						Mos					
Eff: 17-Sep-2019						Hrs					
						Enc					
3506000-80-1872	**SB 3506000-80-1872 - Conversion of the Air Turbine Engine Starter From PN 3506000-4 to PN 3506000-5**							T (A/R)			
80 ENG1						Mos					
Eff: 15-Aug-2014						Hrs					
						Enc					
3506000-80-1872	**SB 3506000-80-1872 - Conversion of the Air Turbine Engine Starter From PN 3506000-4 to PN 3506000-5**							T (A/R)			
80 ENG2						Mos					
Eff: 15-Aug-2014						Hrs					
						Enc					
3506000-80-1872 Rev 1	**ENGINE STARTING - AIR TURBINE ENGINE STARTER - Conversion of the Air Turbine Engine Starter From PN 3506000-4 to PN 3506000-5**							RE (-)			
80 ENG1						Mos	10-Apr-2023				
Eff: 21-Nov-2014 Complied With						Hrs					
(UPDATE NOTE: Verified Engine Starter PN 35060000-5 Installed)						Enc					
3506000-80-1872 Rev 1	**ENGINE STARTING - AIR TURBINE ENGINE STARTER - Conversion of the Air Turbine Engine Starter From PN 3506000-4 to PN 3506000-5**							RE (-)			
80 ENG2						Mos	10-Apr-2023				
Eff: 21-Nov-2014 Complied With						Hrs					
(UPDATE NOTE: Verified Engine Starter PN 35060000-5 Installed)						Enc					
AS907-80-9001	**STARTING - AIR TURBINE STARTER - Install Improved Packing on the Air Turbine Starter (ATS) on AS907-1-1A and -2-1G Engines**							T (A/R)			
80 ENG1						Mos					
Eff: 09-Jun-2011						Hrs					
						Enc					
AS907-80-9001	**STARTING - AIR TURBINE STARTER - Install Improved Packing on the Air Turbine Starter (ATS) on AS907-1-1A and -2-1G Engines**							T (A/R)			
80 ENG2						Mos					
Eff: 09-Jun-2011						Hrs					
						Enc					
AS907-80-9001 Rev 1	**STARTING - AIR TURBINE STARTER - Install Improved Packing on the Air Turbine Starter (ATS) on AS907-1-1A and -2-1G Engines**							T (A/R)			
80 ENG1						Mos					
Eff: 29-Aug-2014						Hrs					
						Enc					
AS907-80-9001 Rev 1	**STARTING - AIR TURBINE STARTER - Install Improved Packing on the Air Turbine Starter (ATS) on AS907-1-1A and -2-1G Engines**							T (A/R)			
80 ENG2						Mos					
Eff: 29-Aug-2014						Hrs					
						Enc					
AS907-80-9001 Rev 2	**STARTING - AIR TURBINE STARTER - Install Improved Packing on the Air Turbine Starter (ATS) on AS907-1-1A and -2-1G Engines**							RE (-)			
80 ENG1						Mos	26-Jan-2023				
Eff: 10-Nov-2015 Complied With AT MANUFACTURE						Hrs	0				
						Enc	0				
AS907-80-9001 Rev 2	**STARTING - AIR TURBINE STARTER - Install Improved Packing on the Air Turbine Starter (ATS) on AS907-1-1A and -2-1G Engines**							RE (-)			
80 ENG2						Mos	20-Jan-2023				
Eff: 10-Nov-2015 Complied With AT MANUFACTURE						Hrs	0				
						Enc	0				
ST02893AT	**LoPresti Boom Beam Lights**							RE (-)			
90 A/F						Mos	10-Feb-2023				
Complied With						Hrs	24:24				
(SOURCE: STC) (NOTE: STC ST02893AT LoPresti Boom Beam Lights. Drawing number LSM-500-103 (Landing) and 104 (Taxi).)						Ldg	7				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
ST04025AT-D	**Link 2000+ Software Installation**							RE (-)		STC	
90 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
						Ldg	10				
ST04026AT-D	**Automatic Dependent Surveillance Broadcast (ADS-B) System Installation**							RE (-)		Informational, STC	
90 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
CMP:900075						Ldg	10				
ST04266AT-D	**Installation of an Executive Cabin Interior**							RE (-)		Informational, STC	
90 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
CMP:900040						Ldg	10				
ST04271AT-D	**Installation of Observer Seat**							RE (-)		Informational, STC	
90 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
Brand C:900035						Ldg	10				
ST04274AT-D	**Installation of Rockwell Collins Second IFIS**							RE (-)		Informational, STC	
90 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
CMP:900005						Ldg	10				
ST04283AT-D	**Installation of Heads Up Display (HUD) And Enhanced Vision System (EVS)**							RE (-)		Informational, STC	
90 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
CMP:900050						Ldg	10				
ST04288AT-D	**Activation of Future Air Navigation System (FANS)**							RE (-)		STC	
90 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
CMP:900055						Ldg	10				
ST04321AT-D	**Installation of VIASAT GAT-5510 KA-Band High Speed (HSD) System**							RE (-)		STC	
90 A/F						Mos	02-Mar-2023				
						Hrs	34:12				
						Ldg	10				
D201910000091	**To Notify Operators of Gulfstream G280 Aircraft and Engine Service Centers of the Recently Released Light Maintenance Manual (LMM) and Aircraft Maintenance Manual (AMM)**							T (A/R)		Service Information Letter	
100 ENG1						Mos					
Eff: 13-Nov-2019						Hrs					
(NOTE: APPLICABILITY: This service information letter is only applicable to equipment received from Original Equipment Manufacturers or equipment received from in-service aircraft. Aircraft tail number should be provided, as applicable. This service information letter is not applicable to excess equipment and equipment removed from parked or dismantled aircraft.)						Enc					
D201910000091	**To Notify Operators of Gulfstream G280 Aircraft and Engine Service Centers of the Recently Released Light Maintenance Manual (LMM) and Aircraft Maintenance Manual (AMM)**							T (A/R)		Service Information Letter	
100 ENG2						Mos					
Eff: 13-Nov-2019						Hrs					
(NOTE: APPLICABILITY: This service information letter is only applicable to equipment received from Original Equipment Manufacturers or equipment received from in-service aircraft. Aircraft tail number should be provided, as applicable. This service information letter is not applicable to excess equipment and equipment removed from parked or dismantled aircraft.)						Enc					
D202005000806	**Biocide Treatment Process**							T (A/R)		Service Information Letter	
100 APU1						Mos					
Eff: 06-May-2020						Hrs					
						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
D202011001451 Rev 3	**Thrust Reverser Unit (TRU) - MAPAERO Overview**							T (A/R)		Service Information Letter	
100 ENG1						Mos					
Eff: 04-Jan-2023						Hrs					
						Enc					
D202011001451 Rev 3	**Thrust Reverser Unit (TRU) - MAPAERO Overview**							T (A/R)		Service Information Letter	
100 ENG2						Mos					
Eff: 04-Jan-2023						Hrs					
						Enc					
D202406004425	**Field Loadable Software Update Instructions for Connected Engine Data Service - EDG100**							T (A/R)		Service Information Letter	
100 ENG1						Mos					
Eff: 02-Jul-2024						Hrs					
						Enc					
D202406004425	**Field Loadable Software Update Instructions for Connected Engine Data Service - EDG100**							T (A/R)		Service Information Letter	
100 ENG2						Mos					
Eff: 02-Jul-2024						Hrs					
						Enc					
▼ 1. T Due | 2. RE -											
2023-10-02 Par. (h)	**Navigation - Radio Altimeters - Airplane Flight Manual (AFM) Revision Until June 30, 2023**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	10-Aug-2023				
Eff: 25-May-2023 Complied With						Hrs					
(UPDATE NOTE: BY REVISING AFM LIMITATIONS BY REV. 9) (NOTE: COMPLIANCE: For non-radio altimeter tolerant airplanes, before further flight, revise the Limitations Section of the existing AFM to include the information specified in figure 3 to paragraph (h) of this AD. This may be done by inserting a copy of figure 3 to paragraph (h) of this AD into the existing AFM. If an operator has complied with paragraph (g) of AD 2021–23–12, that action satisfies the requirements of this paragraph.)						Ldg					
2023-10-02 Par. (i)	**Navigation - Radio Altimeters - AFM Revision After June 30, 2023**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	10-Aug-2023				
Eff: 29-Jun-2023 Complied With						Hrs					
(UPDATE NOTE: BY REVISING AFM LIMITATIONS BY REV. 9) (NOTE: COMPLIANCE: On or before June 30, 2023, revise the Limitations Section of the existing AFM to include the information specified in figure 4 to paragraph (i) of this AD. This may be done by inserting a copy of figure 4 to paragraph (i) of this AD into the existing AFM. Incorporating the AFM revision required by this paragraph terminates the AFM revision required by paragraph (h) of this AD. (2) Before further flight after incorporating the limitations specsified in figure 4 to paragraph (i) of this AD, remove the AFM revision required by paragraph (h) of this AD.)						Ldg					
CF-2024-14 Part II	**Navigation - Aeroplane - Limitations of Operations with Non-Tolerant Radio Altimeter when Operating in Canada due to 5G C-Band Wireless Broadband Interference - Airplane Flight Manual (AFM) Revision**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	27-May-2024				
Eff: 28-May-2024 Complied With AFM updated						Hrs	842:13				
(NOTE: COMPLIANCE: For non-radio altimeter tolerant aeroplanes, as of the effective date of this AD, revise the Limitations Section of the existing AFM to include the information specified in Figure 3 of this AD. This may be accomplished by inserting a copy of Figure 3 of this AD, or the AD itself, into the existing AFM.)						Ldg	496				