

Company

 Owner: ABS Jets, a.s.
 Operator:

Major Assemblies

Airframe	560XL (Citation XLS 560-6325 +)	13-Oct-2024	1359:56 Hrs	957 Ldg	923:54 Hrs(APU)	26 Start(APU)
Eng 1	PW545C	PCE-DF0667	13-Oct-2024	1359:56 Hrs	957 Enc	
Eng 2	PW545C	PCE-DF0666	13-Oct-2024	1026:48 Hrs	742 Enc	
APU 1	RE100[XL]	P-1131	01-Oct-2024	923:54 Hrs	26 APUS	

Additional Information

Program Type: MSG-3, General Categories: FAR 91,Extended TBO,Honeywell Avionics,Extended HSI

 Cost: 85+
 Man Hrs: 1,172.01+

Analyst: Laurence Kirk lkirk@jetsupport.com

Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
▼ 0 - GENERAL											
Engine data download	Engine data download							RE			
 0 A/F						Mos	10-Oct-2024	1		10-Nov-2024	26 Days
						Hrs	1356:53				
						Ldg	955				
 KGR-WP-010 START 11-NOV-2024											
▼ 2 - *Reserved for Airline Use											
SL560XL-02-01	Year 2000 Readiness Disclosure							T (A/R)		Informational	
 2 A/F						Mos					
Eff: 03-Dec-1998						Hrs					
						Ldg					
SL560XL-02-02	Airport Noise Abatement Information							RE (-)		Recommended	
 2 A/F						Mos	22-Jun-2022				
Not Applicable	effective before manufacture					Hrs	8				
						Ldg	6				
SL560XL-02-02 Rev 01	Airport Noise Abatement Information							T (A/R)		Informational	
 2 A/F						Mos					
Eff: 10-Jan-2002						Hrs					
						Ldg					
SL560XL-02-03	Miscellaneous - Cessna CD-ROM Technical Library							T (A/R)		Informational	
 2 A/F						Mos					
Eff: 11-Nov-1999						Hrs					
						Ldg					
▼ 3 - *Reserved for Airline Use											
CIL-03-01	Certification Requirements - Supplemental Type Certificate (STC)							T (A/R)		Informational	
 3 A/F						Mos					
Eff: 03-Jun-2013						Hrs					
						Ldg					
SL560XL-03-01	Supplemental Type Certificate (STC) - CANCELLED							RE (-)		Service Letter	
 3 A/F						Mos					
						Hrs					
						Ldg					
SL560XL-03-01 Rev 01	Supplemental Type Certificate (STC) - CANCELLED							T (A/R)		Service Letter	
 3 A/F						Mos					
Eff: 03-Jun-2013						Hrs					
						Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
▼ 4 - AIRCRAFT STATS / LIMITATIONS										
4-12-MB		Airworthiness Limitations Inspection Document MB						RE (N/A)	Airworthiness Limitations Inspection Document	
	4 A/F					Mos				
					Hrs					
	(AVG MAN HRS: 7.2) (SOURCE: 560 XL MM Section 4-12-00)				Ldg					
4-12-MD		Airworthiness Limitations Inspection Document MD						T	Airworthiness Limitations Inspection Document	≈29-Mar-2031
	4 A/F					Mos	120		22-Jun-2032	7.7 Years
					Hrs	6,000		6000	4640:04 Hrs	
	(AVG MAN HRS: 15.75) (SOURCE: 560 XL MM Section 4-12-00)				Ldg					
4-12-ME		Airworthiness Limitations Inspection Document ME						RE	Airworthiness Limitations Inspection Document	≈08-Oct-2043
	4 A/F					Mos				
					Hrs	15,000		15000	13640:04 Hrs	
	(AVG MAN HRS: 91.24) (SOURCE: 560 XL MM Section 4-12-00)				Ldg					
4-12-MF		Airworthiness Limitations Inspection Document MF						T	Airworthiness Limitations Inspection Document	≈29-Apr-2033
	4 A/F					Mos				
					Hrs	7,500		7500	6140:04 Hrs	
	(AVG MAN HRS: 30.38) (SOURCE: 560 XL MM Section 4-12-00)				Ldg					
4-12-MG		Airworthiness Limitations Inspection Document MG						RE (N/A)	Airworthiness Limitations Inspection Document	
	4 A/F					Mos				
					Hrs					
	(AVG MAN HRS: 1.13) (SOURCE: 560 XL MM Section 4-12-00)				Ldg					
4-12-MH		Airworthiness Limitations Inspection Document MH						RE (N/A)	Airworthiness Limitations Inspection Document	
	4 A/F					Mos				
					Hrs					
	(AVG MAN HRS: 1.13) (SOURCE: 560 XL MM Section 4-12-00)				Ldg					
4-12-MI		Airworthiness Limitations Inspection Document MI						RE (N/A)	Airworthiness Limitations Inspection Document	
	4 A/F					Mos				
					Hrs					
	(AVG MAN HRS: 1.13) (SOURCE: 560 XL MM Section 4-12-00)				Ldg					
4-12-MJ		Airworthiness Limitations Inspection Document MJ						RE	Airworthiness Limitations Inspection Document	≈25-Dec-2040
	4 A/F					Mos				
					Hrs	13,000		13000	11640:04 Hrs	
	(AVG MAN HRS: 13.5) (SOURCE: 560 XL MM Section 4-12-00)				Ldg					
4-12-MK		Airworthiness Limitations Inspection Document MK						RE (N/A)	Airworthiness Limitations Inspection Document	
	4 A/F					Mos				
					Hrs					
	(AVG MAN HRS: 1.13) (SOURCE: 560 XL MM Section 4-12-00)				Ldg					
4-12-ML		Airworthiness Limitations Inspection Document ML						T	Airworthiness Limitations Inspection Document	≈24-Nov-2038
	4 A/F					Mos				
					Hrs	11,500		11500	10140:04 Hrs	
	(AVG MAN HRS: 2.25) (SOURCE: 560 XL MM Section 4-12-00)				Ldg					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
4-12-MM		Airworthiness Limitations Inspection Document MM						RE (N/A)		Airworthiness Limitations Inspection Document	
	4 A/F										
		(AVG MAN HRS: 1.13) (SOURCE: 560 XL MM Section 4-12-00)									
4-12-MN		Airworthiness Limitations Inspection Document MN						RE (N/A)		Airworthiness Limitations Inspection Document	
	4 A/F										
		(AVG MAN HRS: 1.13) (SOURCE: 560 XL MM Section 4-12-00)									
4-12-MO		Airworthiness Limitations Inspection Document MO						RE (N/A)		Airworthiness Limitations Inspection Document	
	4 A/F										
		(SOURCE: 560 XL MM Section 4-12-00)									
4-12-MP		Airworthiness Limitations Inspection Document MP						RE (N/A)		Airworthiness Limitations Inspection Document	
	4 A/F										
		(AVG MAN HRS: 0.23) (SOURCE: 560 XL MM Section 4-12-00)									
4-12-MR		Airworthiness Limitations Inspection Document MR						RE (N/A)		Airworthiness Limitations Inspection Document	
	4 A/F										
		(AVG MAN HRS: 1.13) (SOURCE: 560 XL MM Section 4-12-00)									
4-12-MS		Airworthiness Limitations Inspection Document MS						T		Airworthiness Limitations Inspection Document	≈20-Sep-2034
	4 A/F										
		(SOURCE: 560 XL MM Section 4-12-00)						8,500		8500	7140:04 Hrs
4-12-MT		Airworthiness Limitations Inspection Document MT						T		Airworthiness Limitations Inspection Document	≈22-Oct-2036
	4 A/F										
		(SOURCE: 560 XL MM Section 4-12-00)						10,000		10000	8640:04 Hrs
4-12-MU		Airworthiness Limitations Inspection Document MU						T		Airworthiness Limitations Inspection Document	≈05-Aug-2039
	4 A/F										
		(SOURCE: 560 XL MM Section 4-12-00)						12,000		12000	10640:04 Hrs
4-12-MV		Airworthiness Limitations Inspection Document MV						RE		Airworthiness Limitations Inspection Document	
	4 A/F							24		[31-May-2026]	1.6 Years
		(SOURCE: 560 XL MM)									
▼ 5 - TIME LIMITS/MAINTENANCE CHECKS											
05-00-00-001		Airworthiness Review Certificate Renewal/Extension						RE (Due)		Custom Task	
	5 A/F							31-May-2024		23-Jun-2025	8.4 Months
		Expiration Date 23-Jun-2025									

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
05-50-00(A)(1)		Hard/overweight landings - Check								RE (A/R)	Unscheduled Maintenance Check
5 A/F											

Task No		Description								Categories	Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining		
05-50-00(A)(5)		Landing Gear Assembly Overspeed - Check								RE (A/R)	Unscheduled Maintenance Check		
	5 A/F												
		Note: Note: A condition in which the landing gear is extended at airspeeds that are more than those permitted by the Approved Airplane Flight Manual.											
05-50-00(A)(6)		Dangerous air turbulence or dangerous maneuvers - Check								RE (A/R)	Unscheduled Maintenance Check		
	5 A/F												
		Note: (1) Conditions that can dangerously shake an airplane. Dangerous maneuvers are any maneuvers that are more than those permitted by the Approved Airplane Flight Manual.											
05-50-00(A)(7)		Accidental in-flight thrust reverser deployment - Check								RE (A/R)	Unscheduled Maintenance Check		
	5 A/F												
05-50-00(A)(8)		Lightning Strike - Check								RE (A/R)	Unscheduled Maintenance Check		
	5 A/F												
05-50-00(A)(9)		Foreign Object Damage - Check								RE (A/R)	Unscheduled Maintenance Check		
	5 A/F												
5-12-01		Inspection Document 1 (Every 12 Mos)								RE 5-91-01 MSG-3 INSPECTION TIME LIMITS			
	5 A/F	(SOURCE: 560 XL MM Section 5-12-00)					Mos	22-May-2024	12	-/+1m	31-May-2025	7.6 Months (+30 Days)	
							Hrs	1020:11					
							Ldg	698					
5-12-02		Inspection Document 2 (Every 600 Hrs)								RE (N/A) 5-91-01 MSG-3 INSPECTION TIME LIMITS			
		5 A/F	(SOURCE: 560 XL MM Section 5-12-00)					Mos					
					Hrs								
					Ldg								
5-12-03			Inspection Document 3 (Every 24 Mos)								RE 5-91-01 MSG-3 INSPECTION TIME LIMITS		
	5 A/F		(SOURCE: 560 XL MM Section 5-12-00)					Mos	22-May-2024	24	-/+1m	31-May-2026	1.6 Years (+30 Days)
						Hrs	1020:11						
						Ldg	698						
5-12-06		Inspection Document 6 (Every 48 Mos)								RE 5-91-01 MSG-3 INSPECTION TIME LIMITS			
		5 A/F	(SOURCE: 560 XL MM Section 5-12-00)					Mos		48	-/+1m	30-Jun-2026	1.7 Years (+30 Days)
					Hrs								
					Ldg								
5-12-07			Inspection Document 7 (Every 1600 Hrs)								RE 5-91-01 MSG-3 INSPECTION TIME LIMITS	≈12-Feb-2025	
	5 A/F		(SOURCE: 560 XL MM Section 5-12-00)					Mos					
						Hrs	1,600	-/+25	1600	240:04 Hrs (+25)			
						Ldg							
		KGR-WP-011 START 21-JAN-2025											

Task No		Description							Categories		Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
5-12-08		Inspection Document 8 (Every 2400 Hours))							RE 5-91-01 MSG-3 INSPECTION TIME LIMITS		≈25-Mar-2026	
	5 A/F	(SOURCE: 560 XL MM Section 5-12-00)					Mos					
							Hrs	2,400	-/+25	2400	1040:04 Hrs (+25)	
							Ldg					
5-12-11		Inspection Document 11 (Every 48 Months, then Every 24 Months thereafter)							T 5-91-01 MSG-3 INSPECTION TIME LIMITS			
	5 A/F	(SOURCE: 560 XL MM Section 5-12-00)					Mos	48	-/+1m	30-Jun-2026	1.7 Years (+30 Days)	
							Hrs					
							Ldg					
5-12-12		Inspection Document 12 (Every 60 Months)							RE 5-91-01 MSG-3 INSPECTION TIME LIMITS			
	5 A/F	(SOURCE: 560 XL MM Section 5-12-00)					Mos	60	-/+1m	30-Jun-2027	2.7 Years (+30 Days)	
							Hrs					
							Ldg					
5-12-13		Inspection Document 13 (Every 72 Months)							RE 5-91-01 MSG-3 INSPECTION TIME LIMITS			
	5 A/F	(SOURCE: 560 XL MM Section 5-12-00)					Mos	72	-/+1m	30-Jun-2028	3.7 Years (+30 Days)	
							Hrs					
							Ldg					
5-12-16		Inspection Document 16 (Every 96 Months)							RE 5-91-01 MSG-3 INSPECTION TIME LIMITS			
	5 A/F	(SOURCE: 560 XL MM Section 5-12-00)					Mos	96	-/+1m	30-Jun-2030	5.7 Years (+30 Days)	
							Hrs					
							Ldg					
5-12-17		Inspection Document 17 (6000 Flight Hours, Then Every 1600 Flight Hours Thereafter)							T 5-91-01 MSG-3 INSPECTION TIME LIMITS		≈29-Mar-2031	
	5 A/F	(SOURCE: 560 XL MM Section 5-12-00)					Mos					
							Hrs	6,000	-/+25	6000	4640:04 Hrs (+25)	
							Ldg					
5-12-18		Inspection Document 18 (Every 150 Flight Hours)							RE (N/A) 5-91-01 MSG-3 INSPECTION TIME LIMITS			
	5 A/F	(SOURCE: 560 XL MM Section 5-12-00)					Mos					
							Hrs					
							Ldg					
5-12-19		Inspection Document 19 (Every 300 Flight Hours)							RE 5-91-01 MSG-3 INSPECTION TIME LIMITS		≈08-Feb-2025	
	5 A/F	(SOURCE: 560 XL MM Section 5-12-00)					Mos	16-Sep-2024				
							Hrs	1292:19	300	-/+25	1592:19	232:23 Hrs (+25)
							Ldg	898				
		KGR-WP-011 START 21-JAN-2025										
5-12-20			Inspection Document 20 (Every 100 Flight Hours or 12 Months)							RE (A/R) 5-91-01 MSG-3 INSPECTION TIME LIMITS		
	5 A/F	(SOURCE: 560 XL MM Section 5-12-00)					Mos					
							Hrs					
							Ldg					
5-12-21		Inspection Document 21 (Every 600 Flight Hours or 12 Months)							RE (N/A) 5-91-01 MSG-3 INSPECTION TIME LIMITS			
	5 A/F	(SOURCE: 560 XL MM Section 5-12-00)					Mos					
							Hrs					
							Ldg					

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
5-12-22		Inspection Document 22 (Every 6600 Flight Hours)							RE 5-91-01 MSG-3 INSPECTION TIME LIMITS	≈29-Jan-2032
	5 A/F									
	(SOURCE: 560 XL MM Section 5-12-00)									
5-12-25		Inspection Document 25 (Every 7200 Flight Hours)							RE 5-91-01 MSG-3 INSPECTION TIME LIMITS	≈28-Nov-2032
	5 A/F									
	(SOURCE: 560 XL MM Section 5-12-00)									
SL560XL-05-01		Time Limits/Maintenanance Checks - Transmittal of Pratt & Whitney Canada Maintenance Manual Temporary Revision No. 05-6, Scheduled Maintenance Checks							T (A/R)	Informational
	5 A/F									
	Eff: 06-Dec-2002									
SL560XL-05-02		Corrosive Environment Inspection							T (A/R)	Informational
	5 A/F									
	Eff: 23-Feb-2006									
SL560XL-05-05		Time Limit/Maintenance Checks - MSG-3 Scheduled Maintenance Program Change Bridging Document							RE (-)	Service Letter
	5 A/F									
	Eff: 08-Aug-2018									
SL560XL-05-05 Rev 1		Time Limit/Maintenance Checks - MSG-3 Scheduled Maintenance Program Change Bridging Document							RE (-)	Informational, Service Letter
	5 A/F									
	Eff: 28-Sep-2018									
SL560XL-05-05 Rev 2		Time Limit/Maintenance Checks - MSG-3 Scheduled Maintenance Program Change Bridging Document							RE (-)	Informational, Service Letter
	5 A/F									
	Eff: 31-Jan-2019									
SL560XL-05-06		Time Limits/Maintenance Checks - New AE13083-5 Engine and Auxiliary Power Unit Fire Extinguisher Cartridge Squib Interval Grace Period Implementation							T (A/R)	Informational, Service Letter
	5 A/F									
	Eff: 31-Jan-2019									
▼ 8 - LEVELING AND WEIGHING.										
08-10-01-001		Aircraft Weighing and Balancing							RE	
	8 A/F								48	01-Jun-2026 1.6 Years
	Inspected Date 01-Jun-2022									
▼ 11 - PLACARDS AND MARKINGS										
SL560XL-11-01		Model 560XL Illustrated Parts Catalog and Maintenance Manual Changes							T (A/R)	Informational
	11 A/F									
	Eff: 01-Oct-2003									
▼ 12 - SERVICING - ROUTINE MAINTENANCE										
12-20-27-6400		Flap Roller Lubrication							RE 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	12 A/F	5-12-01							12	-/+1m (31-May-2025) 7.6 Months (+30 Days)
	(ZONE: 512, 522, 612, 622) (SOURCE: 560 XL MM Section 5-10-02)								1020:11	
									698	

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
12-20-32-6100	Shimmy Damper Servicing						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 12 A/F 5543001-12 31092429C (ZONE: 710) (SOURCE: 560 XL MM Section 5-10-02)	5-12-01				Mos	22-May-2024	12	-/+1m (31-May-2025)		7.6 Months (+30 Days)
					Hrs	1020:11				
					Ldg	698				
12-20-32-6400	Landing Gear and Landing Gear Doors Lubrication						RE	05-10-01, 05-10-02, Category 5, Category 6		
 12 A/F	5-12-01				Mos	22-May-2024	12	-/+1m (31-May-2025)		7.6 Months (+30 Days)
MRBR Task:32-10-00-601, MRBR Task:32-20-00-601, MRBR Task:32-20-00-602, MRBR Task:32-20-00-604, MRBR Task:52-80-00-601, MRBR Task:52-80-00-602, MRBR Task:32-50-00-601 (ZONE: 710, 720, 730) (SOURCE: 560XL MM)					Hrs	1020:11				
					Ldg	698				
12-20-52-6400	Cabin Door Hinge Lubrication						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 12 A/F	5-12-06				Mos		48	-/+1m (30-Jun-2026)		1.7 Years (+30 Days)
(ZONE: 810, 811) (SOURCE: 560 XL MM Section 5-10-02)					Hrs					
Note: NOTE: It is recommended you do this task at the same time as Task 52-10-00-2200					Ldg					
12-26-00-6001	15 Day High Exposure Area Wash						RE (N/A)	Discretionary Maintenance		
 12 A/F					Mos					
Ref:Chapter 20, Exterior Cleaning/Washing/Rinse - Servicing, Ref:Chapter 51, Corrosion Severity Maps - Description and Operation, Ref:Chapter 51, Corrosion - Description and Operation (SOURCE: 560 XL MM Section 5-19-00)					Hrs					
					Ldg					
12-26-00-6002	45 Day Medium Exposure Area Wash						RE (N/A)	Discretionary Maintenance		
 12 A/F					Mos					
Ref:Chapter 20, Exterior Cleaning/Washing/Rinse - Servicing, Ref:Chapter 51, Corrosion Severity Maps - Description and Operation, Ref:Chapter 51, Corrosion - Description and Operation (SOURCE: 560 XL MM Section 5-19-00)					Hrs					
					Ldg					
12-26-00-6003	90 Day Low Exposure Area Wash						RE	Discretionary Maintenance		
 12 A/F					Days	31-Aug-2024	90	29-Nov-2024		45 Days
Ref:Chapter 51, Corrosion - Description and Operation, Ref:Chapter 51, Corrosion Severity Maps - Description and Operation, Ref:Chapter 20, Exterior Cleaning/Washing/Rinse - Servicing (SOURCE: 560 XL MM Section 5-19-00)					Hrs	1259:01				
					Ldg	874				
▼ 20 - STANDARD PRACTICES – AIRFRAME										
560XL-20-04	Standard Practices - Cessna Standard Practices Manual						T (A/R)	Service Letter		
 20 A/F Eff: 05-Oct-2017					Mos					
					Hrs					
					Ldg					
CIL-20-01	Standard Practices - Cessna Certification Of Nondestructive Testing Facilities/Personnel						RE (-)	Informational		
 20 A/F Eff: 09-Apr-2012					Mos					
					Hrs					
					Ldg					
CIL-20-01 R3	Standard Practices - Cessna Certification of Nondestructive Testing Facilities/Personnel (This SL has been Cancelled)						RE (-)	Service Letter		
 20 A/F Eff: 30-May-2023					Mos					
					Hrs					
					Ldg					
CIL-20-01 Revision 1	Standard Practices - Cessna Certification Of Nondestructive Testing Facilities/Personnel						RE (-)	Informational		
 20 A/F					Mos					
					Hrs					
					Ldg					
SL560XL-20-01	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)	Optional		
 20 A/F					Mos					
					Hrs					
					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-20-01 Rev 01  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-20-01 Rev 02  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-20-01 Rev 03  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-20-01 Rev 04  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-20-01 Rev 05  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-20-01 Rev 06  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-20-01 Rev 07  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-20-01 Rev 08  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-20-01 Rev 09  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-20-01 Rev 10  20 A/F	Cessna Certification of Nondestructive Testing Facilities/Personnel						RE (-)		Optional	
					Mos					
					Hrs					
					Ldg					
SL560XL-20-01 Rev 11  20 A/F Eff: 21-Sep-2012	Cessna Certification of Nondestructive Testing Facilities/Personnel						T (A/R)		Informational	
					Mos					
					Hrs					
					Ldg					
▼ 21 - AIR CONDITIONING AND PRESSURIZATION										
	A/C Compressor						RE (O/C)			
 21 A/F					Mos					
Unknown					Hrs					
Unknown					Ldg					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		A/C Condenser Coil Assembly								RE (O/C)	
	21 A/F	Unknown Unknown					Mos				
							Hrs				
							Ldg				
		Acm Cooling Turbine								RE (O/C)	
	21 A/F	2206610-1 1614					Mos			22-Jun-2022	
							Hrs			0	
							Ldg			0	
		Bi-Level Valve								RE (O/C)	
	21 A/F	Left 1988-00-3 4661					Mos			22-Jun-2022	
							Hrs			0	
							Ldg			0	
		Bi-Level Valve								RE (O/C)	
	21 A/F	Right 1988-00-3 4667					Mos			22-Jun-2022	
							Hrs			0	
							Ldg			0	
		Binary Pressure Switch								RE (O/C)	
	21 A/F	Unknown Unknown					Mos				
							Hrs				
							Ldg				
		Cabin Altitude (U1005) Controller								RE (O/C)	
	21 A/F	52770-116 05210					Mos			22-Jun-2022	
							Hrs			0	
							Ldg			0	
		Cabin Altitude Pressure Switch								RE (O/C)	
	21 A/F	GB300NA161 2140872					Mos			22-Jun-2022	
							Hrs			0	
							Ldg			0	
		Cabin Duct Overheat (SC013) Switch								RE (O/C)	
	21 A/F	1173T42 4425					Mos			22-Jun-2022	
							Hrs			0	
							Ldg			0	
		Cabin Duct Temperature (UC014) Sensor								RE (O/C)	
	21 A/F	Left Unknown Unknown					Mos			22-Jun-2022	
							Hrs			0	
							Ldg			0	
		Cabin Temp Sensor								RE (O/C)	
	21 A/F	No.1 1E47-1 3BW9					Mos			22-Jun-2022	
							Hrs			0	
							Ldg			0	
		Cabin Temp Sensor								RE (O/C)	
	21 A/F	No.2 1E47-1 3BW8					Mos			22-Jun-2022	
							Hrs			0	
							Ldg			0	

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	21 A/F 27241287-14 2BW35F	Cabin Temperature Control (VT029) Valve						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	21 A/F 1173T42 4428	Cockpit Duct Overheat (SF034) Switch						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	21 A/F 27241287-14 2BW36F	Cockpit Temperature Control (VT030) Valve						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	21 A/F Unknown Unknown	Condenser Hour Meter						RE (O/C)			
							Mos				
							Hrs				
	21 A/F Unknown Unknown	Condenser/Compressor Switch						RE (O/C)			
							Mos				
							Hrs				
	21 A/F 927223-2-3 0744	ECU Overheat Switch						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	21 A/F 27241287-14 2BW40F	ECU Temp Control Valve						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	21 A/F 4713-19 1834	Emergency Pressurization Flow (Uy005) Valve						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	21 A/F 2215460-4 1638	Environmental Control Unit						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	21 A/F 1E64-2 12BV19	Environmental Temp Controller						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	21 A/F Unknown Unknown	Evaporator Assembly						RE (O/C)			
							Mos				
							Hrs				
	21 A/F Unknown Unknown	Aft									
							Mos				
							Hrs				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	21 A/F Unknown Unknown	Evaporator Assembly								RE (O/C)	
		Fwd					Mos				
							Hrs				
	21 A/F 4001-20 8786A	Lower Warm Air Check Valve								RE (O/C)	
		Left					Mos	22-Jun-2022			
							Hrs	0			
	21 A/F 4001-20 8781A	Lower Warm Air Check Valve								RE (O/C)	
		Right					Mos	22-Jun-2022			
							Hrs	0			
	21 A/F Unknown Unknown	Manual Control Outflow Valve								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
	21 A/F 52773-114 05109	Manual Toggle Valve								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
	21 A/F 7003-400 1380	Motor And Blower Assembly								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
	21 A/F 31A437-1 2794	Ozone Converter								RE (O/C)	
		Left					Mos	22-Jun-2022			
							Hrs	0			
	21 A/F 31A437-1 2796	Ozone Converter								RE (O/C)	
		Right					Mos	22-Jun-2022			
							Hrs	0			
	21 A/F 52771-314 05184	Primary Outflow Valve								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
	21 A/F 52772-114 05174	Secondary Outflow Valve								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
	21 A/F 4001-20 8797A	Upper Cool Air Check Valve								RE (O/C)	
		Left					Mos	22-Jun-2022			
							Hrs	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
	21 A/F 4001-20 8788A	Upper Cool Air Check Valve Right						RE (O/C)				
							Mos	22-Jun-2022				
							Hrs	0				
								Ldg	0			
	21 A/F 2341316-3 1512	Water Separator						RE (O/C)				
							Mos	22-Jun-2022				
							Hrs	0				
								Ldg	0			
	21 A/F 1E62-1 3BW26	Water Separator Temp 1 Sensor						RE (O/C)				
							Mos	22-Jun-2022				
							Hrs	0				
								Ldg	0			
	21 A/F Unknown Unknown	Water Spray ECU Aspirator						RE (O/C)				
							Mos	22-Jun-2022				
							Hrs	0				
								Ldg	0			
	21 A/F 1E46-1 12BV56	Zone Temperature (UC021) Sensor						RE (O/C)				
							Mos	22-Jun-2022				
							Hrs	0				
								Ldg	0			
	21 A/F 1E46-1 1BW3	Zone Temperature (UF029) Sensor						RE (O/C)				
							Mos	22-Jun-2022				
							Hrs	0				
								Ldg	0			
12-20-21-1600		Water Separator (Cleaning) Restoration						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈12-Feb-2025	
	21 A/F 2341316-3 1512	5-12-07					Mos					
							Hrs	1,600	-/+25	(1600)	240:04 Hrs (+25)	
							Ldg					
		(ZONE: 312) (SOURCE: 560 XL MM Section 5-10-02) KGR-WP-011 START 21-JAN-2025										
12-20-21-1601		Ozone Converters (Cleaning) Restoration						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈29-Jan-2022	
	21 A/F 31A437-1 2794	Left5-12-22					Mos					
							Hrs	6,600	-/+25	(6600)	5240:04 Hrs (+25)	
							Ldg					
		(ZONE: 321) (SOURCE: 560 XL MM Section 5-10-02)										
12-20-21-1601		Ozone Converters (Cleaning) Restoration						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈29-Jan-2022	
	21 A/F 31A437-1 2796	Right5-12-22					Mos					
							Hrs	6,600	-/+25	(6600)	5240:04 Hrs (+25)	
							Ldg					
		(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02)										
2013-09-11		Air Conditioning						RE (-)		Mandatory		
	21 A/F Eff: 05-Jul-2013 Not Applicable (ISSUING AUTHORITY: FAA)	Due to aircraft is not in suspect serial range					Mos	22-Jun-2022				
							Hrs	8				
							Ldg	6				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2013-09-11 Par. (m)	Air Conditioning - Replacement Of The Brushes On A/C Compressor Motors, Part Nos. 1134104-1/1134104-5, Or Deactivation Of The A/C System Parts Return And Reporting Requirements						RE (-)		Mandatory	
21 A/F	Not Applicable due to S/N				Mos	22-Jun-2022				
	(ISSUING AUTHORITY: FAA)				Hrs					
					Ldg					
21-22-00-2900	Cabin Air Distribution Check Valves (Borescope) Special Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
21 A/F	5-12-16				Mos		96	-/+1m (30-Jun-2030)	5.7 Years (+30 Days)	
	(ZONE: 161, 162) (SOURCE: 560 XL MM Section 5-10-02)				Hrs					
					Ldg					
21-22-00-9600	Cockpit Side Window Defog Filter Discard						RE (A/R)	Discretionary Maintenance		
21 A/F					Mos					
	Ref:Chapter 21, Warm Air Distribution - Inspection/Check (SOURCE: 560 XL MM Section 5-19-00)				Hrs					
	Note: As Necessary				Ldg					
21-30-00-7200	Pressurization System Operational and Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
21 A/F	5-12-03				Mos	22-May-2024	24	-/+1m (31-May-2026)	1.6 Years (+30 Days)	
	(ZONE: 241, 261, 262) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-03)				Hrs	1020:11				
					Ldg	698				
21-31-05-7200	Cabin Altitude Pressure Switch Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
21 A/F	5-12-06				Mos		48	-/+1m (30-Jun-2026)	1.7 Years (+30 Days)	
	GB300NA161				Hrs					
	2140872				Ldg					
	(ZONE: 241) (SOURCE: 560 XL MM Section 5-10-02)									
21-52-00-2100	Vapor Cycle Cooling System Hour Meter Visual Check (Airplanes Incorporating Vapor Cycle Cooling with 1134104-1 and -5 Compressor Motors)						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS, Airworthiness Limitations Inspection Time Limits		
21 A/F					Mos					
	MRBR Task:21-52-00-205 (ZONE: 322) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02, 5-10-01, 5-10-02)				Hrs					
					Ldg					
21-52-00-2101	Vapor Cycle Cooling System 500 Compressor Hour Maintenance (Airplanes Incorporating Vapor Cycle Cooling System with 1134104-1 and -5 Compressor Motors)						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
21 A/F					Mos					
	MRBR Task:21-52-00-203, MRBR Task:21-52-00-202, MRBR Task:21-52-00-201 (ZONE: 322) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02)				Hrs					
					Ldg					
21-52-00-2200	Vapor Cycle Cooling System 12 Month Maintenance (Airplanes Incorporating Vapor Cycle Cooling System)						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
21 A/F					Mos	02-Jun-2023				
	MRBR Task:21-52-00-204 (ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02)				Hrs	460:06				
					Ldg	317				
21-52-00-9600	Vapor Cycle Cooling System 500 Compressor Hour Drive Motor Brush Discard (Airplanes Incorporating Vapor Cycle Cooling System with 1134104-1 and -5 Compressor Motors)						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS, Airworthiness Limitations Inspection Time Limits		
21 A/F					Mos					
	MRBR Task:21-52-00-901 (ZONE: 311) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02, 5-10-02, 5-18-00)				Hrs					
					Ldg					

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
CIL-21-03		Air Conditioning - Transmittal of Honeywell Service Bulletin 2341316-21-2828, Inspection and Repair of the Interior Surfaces of the Water Separator, PN 2341316-2 and -3, for Corrosion							T (-)		Informational	
	21 A/F					Mos						
	Eff: 22-Oct-2015					Hrs						
						Ldg						
Note: This service letter is for informational purposes only.												
CIL-21-03 R1		Air Conditioning - Transmittal of Honeywell Service Bulletin 2341316-21-2828, Inspection and Repair of the Interior Surfaces of the Water Separator, PN 2341316-2 and -3, for Corrosion							T (A/R)		Informational	
	21 A/F					Mos						
	Eff: 25-May-2022					Hrs						
						Ldg						
SL560XL-21-07		Transmittal of Honeywell Service Bulletin 2215460-21-2762, Environmental Control Unit (ECU) - Inspect and Replace the Over Temperature Switch							RE (-)		Optional	
	21 A/F					Mos						
						Hrs						
						Ldg						
SL560XL-21-07 Rev 01		Transmittal of Honeywell Service Bulletin 2215460-21-2762, Environmental Control Unit (ECU) - Inspect and Replace the Over Temperature Switch							RE (-)		Recommended	
	21 A/F					Mos	22-Jun-2022					
	Eff: 10-Feb-2004 Not Applicable	effective before manufacture				Hrs	8					
						Ldg	6					
SL560XL-21-12		Transmittal of Honeywells Service Bulletin 2215460-21-2814, Air Conditioning - Environmental Control Unit - Modification of Environmental Control Unit (ECU), PN 2215460-3 Series 1, By Replacement of Compressor Outlet Over Temperature Switch, PN 927223-2-2							RE (-)		Informational	
	21 A/F					Mos						
	Eff: 03-Jun-2010					Hrs						
						Ldg						
▼ 22 - AUTOFLIGHT												
		Aileron Drive Servo							RE (O/C)			
	22 A/F					Mos	22-Jun-2022					
	822-1168-022					Hrs	0					
	4MD4KK					Ldg	0					
		Autopilot (PC400) Controller							RE (O/C)			
	22 A/F					Mos	22-Jun-2022					
	Unknown					Hrs	0					
	Unknown					Ldg	0					
		Autopilot Elevator Trim Servo							RE (O/C)			
	22 A/F					Mos	22-Jun-2022					
	822-1168-023					Hrs	0					
	4MD50M					Ldg	0					
		Elevator Drive Servo							RE (O/C)			
	22 A/F					Mos	22-Jun-2022					
	822-1168-022					Hrs	0					
	4MD4D8					Ldg	0					
		Pitch Servo Mount							RE (O/C)			
	22 A/F					Mos	22-Jun-2022					
	Unknown					Hrs	0					
	Unknown					Ldg	0					

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
Pitch Trim Servo Mount											
	22 A/F						Mos	22-Jun-2022		RE (O/C)	
	Unknown						Hrs	0			
	Unknown						Ldg	0			
Roll Servo Mount											
	22 A/F						Mos	22-Jun-2022		RE (O/C)	
	Unknown						Hrs	0			
	Unknown						Ldg	0			
Rudder Drive Servo											
	22 A/F						Mos	22-Jun-2022		RE (O/C)	
	822-1168-022						Hrs	0			
	4MD4CX						Ldg	0			
SMT-65 Servo Mount											
	22 A/F	Aileron	0				Mos	22-Jun-2022		RE (O/C)	
	622-5735-021	New	0				Hrs	0			
	Unknown		0				Ldg	0			
Alias1:22-10-00											
Yaw Servo Mount											
	22 A/F						Mos	22-Jun-2022		RE (O/C)	
	Unknown						Hrs	0			
	Unknown						Ldg	0			
▼ 23 - COMMUNICATIONS											
ABC Switch											
	23 A/F						Mos	22-Jun-2022		RE (O/C)	
	SWI829-02	New					Hrs	0			
	202200000004662						Ldg	0			
AFIS Antenna											
	23 A/F						Mos	22-Jun-2022		RE (O/C)	
	Unknown						Hrs	0			
	Unknown						Ldg	0			
Airborne Duplexer											
	23 A/F						Mos	22-Jun-2022		RE (O/C)	
	Unknown						Hrs	0			
	Unknown						Ldg	0			
Aircell (ATG) Antenna											
	23 A/F	Aft					Mos	22-Jun-2022		RE (O/C)	
	Unknown						Hrs	0			
	Unknown						Ldg	0			
Aircell (ATG) Antenna											
	23 A/F	Fwd					Mos	22-Jun-2022		RE (O/C)	
	Unknown						Hrs	0			
	Unknown						Ldg	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	23 A/F P17500-002 1750000200868	Aircell Axxess Satellite Transceiver							RE (O/C)		
							Mos	23-Jun-2023			
							Hrs				
							Ldg				
	23 A/F P14126 1412627519	Aircell Configuration Module							RE (O/C)		
							Mos				
							Hrs				
							Ldg				
	23 A/F Unknown Unknown	Aircell Configuration Module No.2							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	23 A/F Unknown Unknown	Aircell High Speed Internet (ATG 5000) Unit							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	23 A/F P28950 2895000000134	Aircell Router Repaired							RE (O/C)		
							Mos	20-Jun-2023			
			0				Hrs	509			
			0				Ldg	343			
	23 A/F Unknown Unknown	Airshow Unit							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	23 A/F 405001A-PMA OP000803	Antenna, IGA-5001 New							RE (O/C)		
							Mos	22-May-2024			
			0				Hrs	1020:11			
			0				Ldg	698			
	23 A/F Unknown Unknown	ATG4000 Broadband RLU Aircell							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	23 A/F Unknown Unknown	Audio Amplifer							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	23 A/F 822-2381-230 4P5626	Audio Control Panel Amplifier No.1							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	23 A/F 822-2381-230 4P627	Audio Control Panel Amplifier No.2							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			

Task No	Description		TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition								DUE	Remaining
 23 A/F Unknown Unknown		Axxess Call Alerter II (ACA II)						RE (O/C)			
						Mos					
						Hrs					
								Ldg			
 23 A/F Unknown Unknown		Call Alerter Switch						RE (O/C)			
						Mos					
						Hrs					
								Ldg			
 23 A/F Unknown Unknown		Cluster Comm Module No.1						RE (O/C)		Honeywell Avionics	
						Mos	22-Jun-2022				
						Hrs	0				
								Ldg	0		
 23 A/F Unknown Unknown		Cluster Comm Module No.2						RE (O/C)		Honeywell Avionics	
						Mos	22-Jun-2022				
						Hrs	0				
								Ldg	0		
 23 A/F Unknown Unknown		Cockpit Airshow Controller						RE (O/C)			
						Mos	22-Jun-2022				
						Hrs	0				
								Ldg	0		
 23 A/F 2100-1025-22 002073318		Cockpit Voice Recorder (CVR)						RE (O/C)			
						Mos	22-Jun-2022				
						Hrs	0				
								Ldg	0		
Note: HW MOD 08, 11, 13, 14, 15, 17											
 23 A/F Unknown Unknown		Cockpit Voice Recorder (CVR) Gravity Switch						RE (O/C)			
						Mos	22-Jun-2022				
						Hrs	0				
								Ldg	0		
 23 A/F Unknown Unknown		Cockpit Voice Recorder (CVR) Underwater Locating Device (ULD)						RE (O/C)			
						Mos	22-Jun-2022				
						Hrs	0				
								Ldg	0		
 23 A/F 147-E5542-00 ULB042079 Ref:23-70-00-9600		Cockpit Voice Recorder (CVR) Underwater Locating Device (ULD) Battery						RE (H/T)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
						Mos	06-Jun-2022				
						Hrs					
								Ldg			
 23 A/F S055-0067-00 Unknown Alias1:23-70-00		Cockpit Voice Recorder Microphone						RE (O/C)			
		New				0	Mos	22-Jun-2022			
						0	Hrs	0			
								Ldg	0		

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
✖	23 A/F S65-8280-45 326-2842	Comm Antenna No.1					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	23 A/F 21-38-1RF/36 51282	Comm Antenna No.2					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	23 A/F 21-38-1RF/36 51284	Comm Antenna No.3					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	23 A/F 822-1468-110 791RR	Comm Transceiver No.1					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	23 A/F 822-1468-110 791V8	Comm Transceiver No.2					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	23 A/F S251-1120-00 100000028	CVR Control Unit					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	23 A/F Unknown Unknown	Diversity Antenna Remote No.1					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	23 A/F Unknown Unknown	Diversity Antenna Remote No.2					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	23 A/F Unknown Unknown	Flitephone 800 Radiotelephone Antenna					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	23 A/F Unknown Unknown	Flitephone 800 Radiotelephone Tranceiver					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	23 A/F Unknown Unknown	Flitephone Vi Assembly Antenna					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			

Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	23 A/F 405001A-PMA Unknown	GSM/WLAN Antenna New								RE (O/C)	
			0			Mos	22-Jun-2022				
			0			Hrs	0				
			0			Ldg	0				
	23 A/F Unknown Unknown	H.F. Antenna/Cable Assembly								RE (O/C)	
						Mos					
						Hrs					
						Ldg					
	23 A/F Unknown Unknown	Handset Phone Cabin								RE (O/C)	
						Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
	23 A/F Unknown Unknown	Handset Phone Cockpit								RE (O/C)	
						Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
	23 A/F Unknown Unknown	High Frequency (HF) Antenna								RE (O/C)	
						Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
	23 A/F Unknown Unknown	High Frequency (HF) Power Amp								RE (O/C)	
						Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
	23 A/F Unknown Unknown	High Frequency (HF) Receiver/Exciter								RE (O/C)	
						Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
	23 A/F 405016A 81370261	HLD (HPA/LNA/Diplexer) Tested/Inspected								RE (O/C)	
						Mos	11-Jun-2024				
						Hrs	1060:22				
						Ldg	732				
	23 A/F Unknown Unknown	Integrated Communication Unit No.1								RE (O/C)	Honeywell Avionics
						Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
	23 A/F Unknown Unknown	Integrated Communication Unit No.2								RE (O/C)	Honeywell Avionics
						Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
	23 A/F Unknown Unknown	KHF950 High Frequency (HF) Adapter								RE (O/C)	
						Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
23 A/F Unknown Unknown		KHF950 High Frequency (HF) Controller								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
23 A/F Unknown Unknown		Magnastar-CDR								RE (O/C)	
							Mos				
							Hrs				
23 A/F QAR200-30-04 002068742		Mini Quick Access Recorder								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
23 A/F 822-2177-001 4P5616		Nav/Comm Control								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
23 A/F PBS250-2-G5 252002495		PBS250 Briefer Control New								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
23 A/F 822-1863-577 4RG9R1		Radio Interface Unit No.1 Overhauled								RE (O/C)	
							Mos	08-Sep-2023			
							Hrs	687:05			
23 A/F 822-1864-022 4RG9NG		Radio Interface Unit No.2								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
23 A/F CDM610-31 202200000009273		RHF - Monitor New								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
23 A/F Unknown Unknown		Rosen Cockpit Controller								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
23 A/F S67-1575-165 449-9549		Satcom Antenna New								RE (O/C)	Honeywell Avionics
							Mos	21-Jul-2023			
							Hrs	576:24			
23 A/F 405040A 23430355		SBU Transceiver New								RE (O/C)	
							Mos	11-Jun-2024			
							Hrs	1060:22			
							Ldg	732			

Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
ST-4300								RE (O/C)			
	23 A/F Unknown Unknown						Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
Standby Nav/Com Control Unit								RE (O/C)			
	23 A/F Unknown Unknown						Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
Stereo Amplifier								RE (O/C)			
	23 A/F Unknown Unknown						Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
23-00-CUS-001 VHF navigational check (IFR check)								RE			
	23 A/F						Mos	22-May-2024	12	22-May-2025	7.3 Months
							Hrs	1020:11			
							Ldg	698			
Note: CAA Requirement											
23-10-00-7100 Crew Oxygen Mask Microphone and Switch Operational Check								RE 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	23 A/F MC10-16-150 B179178 (ZONE: 242) (SOURCE: 560 XL MM Section 5-10-02)	Copilot5-12-01					Mos	22-May-2024	12	-/+1m (31-May-2025)	7.6 Months (+30 Days)
							Hrs	1020:11			
							Ldg	698			
23-10-00-7100 Crew Oxygen Mask Microphone and Switch Operational Check								RE 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	23 A/F MC10-16-150 B178643 (ZONE: 241) (SOURCE: 560 XL MM Section 5-10-02)	Pilot5-12-01					Mos	22-May-2024	12	-/+1m (31-May-2025)	7.6 Months (+30 Days)
							Hrs	1020:11			
							Ldg	698			
23-50-00-7100 Audio Amplifier Emergency Switch Operational Check (Airplanes -5001 thru - 6000)								RE (N/A) 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	23 A/F						Mos	02-Jun-2023			
							Hrs	460:06			
							Ldg	317			
23-60-00-7200 Static Discharging System Functional Check								T 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	23 A/F	5-12-11					Mos		48	-/+1m (30-Jun-2026)	1.7 Years (+30 Days)
							Hrs				
							Ldg				
23-70-00-9600 DK120 or DK120/90 Cockpit Voice Recorder Underwater Locator Beacon Battery Discard								RE 05-10-01, 05-10-02, 05-12-00, Category 9			
	23 A/F 147-E5542-00 ULB042079 Expiration Date 28-Feb-2029 MRBR Task:23-70-00-902, MRBR Task:23-70-00-901 (ZONE: 312) (SOURCE: 560XL MM) Note: 72 Months (DK120) Tracked by Component Expiration Date. NOTE: Per Supplier Recommendation Dukane Seacom 03-TM-0037 (DK120) or 03-TM-0063 (DK120/90) Technical Manual Underwater Acoustic Beacon.						Mos	06-Jun-2022	72	28-Feb-2029	4.4 Years
							Hrs				
							Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
23-90-20-7200	Transponder Functional Check (Airplanes -5001 thru -6000)						RE (N/A)		Regulatory Inspections/Time Limits	
 23 A/F	No.1					Mos				
622-9210-501						Hrs				
4NC98N						Ldg				
(SOURCE: 560 XL MM Section 5-13-00)										
23-90-20-7200	Transponder Functional Check (Airplanes -5001 thru -6000)						RE (N/A)		Regulatory Inspections/Time Limits	
 23 A/F	No.2					Mos				
622-9210-501						Hrs				
4NC987						Ldg				
(SOURCE: 560 XL MM Section 5-13-00)										
239910-0101	Comm Transceiver						RE (O/C)			
 23 A/F	No.3					Mos	03-Sep-2022			
822-1468-310	Overhauled		0			Hrs	108:42			
4J0TY			0			Ldg	72			
FA2100CVR SB024 Rev 4	MOD DOT 17 Introduction of New CSMU Part Number						RE (-)		Recommended	
 23 A/F						Mos	05-Oct-2023			
Eff: 15-Sep-2023 Complied With	MOD 17 already c/w					Hrs	732:45			
						Ldg	484			
Note: CONCURRENT REQUIREMENTS: This Service Bulletin is eligible only for recorders with MOD DOT 14. For P/N 2100-1925-22, Service Bulletin FA2100CVR-033 (ATA No. 23-70-04-033) which installs Software Revision 12 and CSMU, Part No. 253E6995-06 must be completed after this Service Bulletin (SB).										
SB560XL-23-10	Communications - Aviator 300 SATCOM Intermediate Gain Antenna (IGA) Replacement						RE (-)		Optional	
 23 A/F						Mos				
Eff: 16-Jun-2021						Hrs				
						Ldg				
SB560XL-23-11	Communications - ATN-B1 Controller Pilot Data Link Communications (CPDLC) Installation						T (A/R)		Optional	
 23 A/F						Mos				
Eff: 07-Apr-2022						Hrs				
						Ldg				
SL560XL-23-01	Communication - Transmittal Of Airshow Service Bulletin 920720-1 Airshow 400 Digital Interface Unit						T (A/R)		Optional	
 23 A/F						Mos				
Eff: 04-Nov-1999						Hrs				
						Ldg				
SL560XL-23-02	Communication - Transmittal Of Airshow Service Bulletin 20721-1 Genesys Data Communication Unit						T (A/R)		Optional	
 23 A/F						Mos				
Eff: 04-Nov-1999						Hrs				
						Ldg				
SL560XL-23-09	Communications - SITA Datalink Frequency Change for North America						T (A/R)		Service Letter	
 23 A/F						Mos				
Eff: 12-May-2017						Hrs				
						Ldg				
Note: COMPLIANCE: This service document is for informational purposes only.										
SL560XL-23-10	Communications - ATG 4000 Software Update						RE (-)		Service Letter	
 23 A/F						Mos				
Eff: 12-Sep-2017						Hrs				
						Ldg				
SL560XL-23-11	Communications - ATG 4000 Software Update To Version 2.8						T (A/R)		Service Letter	
 23 A/F						Mos				
Eff: 25-Jan-2018						Hrs				
						Ldg				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-23-12	Communications - Installation of the Satcom Antenna Doublers						RE (-)		Optional	
 23 A/F						Mos				
Eff: 12-Jul-2019						Hrs				
						Ldg				
SL560XL-23-13	Communications - Cockpit Voice Recorder (CVR) Control Panel Replacement						RE (-)		Recommended	
 23 A/F						Mos	22-Jun-2022			
Eff: 18-Aug-2021 Not	effective before manufacture					Hrs	8			
Applicable						Ldg	6			
(AVG MAN HRS: 3)										
SL560XL-23-14	Communications - Transmittal of Collins Operators Bulletin - OPSB 0244-23 RIU-4010 CPDLC ATN-B1 Dropouts						T (A/R)		Informational	
 23 A/F						Mos				
Eff: 27-Nov-2023						Hrs				
						Ldg				
Note: NOTE: This service letter is applicable to the aircraft serial numbers listed above that have complied with Optional Service Bulletin SB560XL-23-11 - Communication - ATN-B1 Controller Pilot Data Link Communications (CPDLC) Installation, original issue or latest.										
▼ 24 - ELECTRICAL POWER										
	2000 Inverter						RE (O/C)			
 24 A/F						Mos	22-Jun-2022			
6432000-1	New					Hrs	0			
M21-10186						Ldg	0			
	30Va Static Inverter						RE (O/C)			
 24 A/F						Mos	22-Jun-2022			
Unknown						Hrs	0			
Unknown						Ldg	0			
	Ac (UD017) Generator						RE (O/C)			
 24 A/F						Mos	22-Jun-2022			
91372-3						Hrs	0			
2190B						Ldg	0			
	Ac (UE018) Generator						RE (O/C)			
 24 A/F						Mos	22-Jun-2022			
91372-3						Hrs	0			
2191B						Ldg	0			
	Anti Ice NZ019 PCB						RE (O/C)			
 24 A/F						Mos	22-Jun-2022			
6618826-1						Hrs	0			
31300870-4						Ldg	0			
	Anti-Ice NZ018 PCB						RE (O/C)			
 24 A/F						Mos	22-Jun-2022			
6618826-1						Hrs	0			
31300870-1						Ldg	0			
	APU Generator (UT032) Control Unit						RE (O/C)			
 24 A/F						Mos	22-Jun-2022			
51525-001F						Hrs	0			
P9718						Ldg	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	24 A/F 6618808-43 0271	APU NZ025 PCB New							RE (O/C)		
							Mos	15-Apr-2023			
			0				Hrs	402:30			
			0				Ldg	276			
	24 A/F 6618809-6 31861246-4	APU NZ026 PCB Tested/Inspected							RE (O/C)		
							Mos	30-Mar-2023			
							Hrs	380:19			
							Ldg	262			
	24 A/F A876K CU-91383	Battery Disconnect (KY001) Relay							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	24 A/F Unknown Unknown	Battery Temp Indicator							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	24 A/F Unknown Unknown	Battery Temp Sensor							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	24 A/F 6618823-16 32079694-3	Cabin Door NZ007 PCB New							RE (O/C)		
							Mos	02-Nov-2022			
			0				Hrs	190:48			
			0				Ldg	130			
	24 A/F C662502-0101 B22-12450	Dc (EI009) Voltmeter							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	24 A/F MD144-1 L21-11580	Dc (EI010) Ammeter							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	24 A/F MD144-1 L21-11583	Dc (EI011) Ammeter							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	24 A/F 6518366-3 0951	Dimming NZ023 PCB							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	24 A/F Unknown Unknown	EEC Interface (NZ021) PCB Left							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
24 A/F 6618831-11 31308946-2		EEC Interface NZ020 PCB Right								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
										RE (O/C)	
							Mos	22-Jun-2022			
24 A/F 6618825-6 31278168-1		Fuel NZ014 PCB					Hrs	0			
							Ldg	0			
										RE (O/C)	
24 A/F 6618825-6 31278168-3		Fuel NZ015 PCB					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
24 A/F 51525-001F P9713		Generator (UT007) Control Unit								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
										RE (O/C)	
							Mos	22-Jun-2022			
24 A/F 51525-001F P9715		Generator (UT008) Control Unit					Hrs	0			
							Ldg	0			
										RE (O/C)	
24 A/F Unknown Unknown		Ground Fault Current (UT017) Transformer Left					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
24 A/F Unknown Unknown		Ground Fault Current (UT018) Transformer Right								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
										RE (O/C)	
							Mos	22-Jun-2022			
24 A/F 106072-1 6010322		Ground Fault Interrupter					Hrs	0			
							Ldg	0			
										RE (O/C)	
24 A/F 6618820-1 0409		Hydraulic NZ016 PCB New					Mos	15-Apr-2023			
			0				Hrs	402:30			
			0				Ldg	276			
24 A/F SS-50 9301		Inverter, 110								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
										RE (O/C)	
							Mos	22-Jun-2022			
24 A/F 6618822-6 31278159-3		Landing Gear Control NZ009 PCB					Hrs	0			
							Ldg	0			
										RE (O/C)	

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Landing Gear NZ004 PCB								RE (O/C)	
	24 A/F	6618821-14 31263501					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Main Battery (UY006)								RE (O/C)	
	24 A/F	S3597-8 41223048					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Miscellaneous NZ035 PCB								RE (O/C)	
	24 A/F	6618832-17 0435					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		No Take-Off NZ008 PCB								RE (O/C)	
	24 A/F	6618824-6 31300906-2					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		NZ022 Diagnostics PCB								RE (O/C)	
	24 A/F	6618828-7 31154994-1					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Overvoltage (UZ003) Monitor								RE (O/C)	
	24 A/F	1645-1-3 105758					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		P-110 VAC-USB Outlet								RE (O/C)	
	24 A/F	106430-11 150222					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		PCB-APU Current Limiter								RE (O/C)	
	24 A/F	6618833-5 32366498-3					Mos	15-Apr-2023			
			0				Hrs	402:30			
			0				Ldg	276			
		Power Control (UD015) Unit								RE (O/C)	
	24 A/F	91479-1 3355					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Power Control (UE016) Unit								RE (O/C)	
	24 A/F	91479-1 3357					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Press NZ002 PCB								RE (O/C)	
	24 A/F	Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
24 A/F 6618830-7 0497		Rudder Bias NZ029 PCB						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
24 A/F 6618706-1 1205		Squat Switch NZ006 PCB						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
24 A/F Unknown Unknown		Start Control NZ012 PCB						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
24 A/F Unknown Unknown		Start Control NZ013 PCB						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
24 A/F 6618829-14 0771		Start NZ013 PCB Left						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
24 A/F 6618829-14 0790		Start NZ013 PCB Right						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
24 A/F Unknown Unknown		Tail Deice (NZ005) PCB						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
24 A/F 6618730-1 31278186-2		Tail Deice Cont NZ031 PCB						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
24 A/F 6618731-1 0797		Tail Deice Mon NZ033 PCB						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
24 A/F Unknown Unknown		Trim (NZ001) PCB						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
24 A/F 6618827-1 0446		Two Position Tail NZ017 PCB						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2017-04-14	Electrical Power - Inspections of the Fuel Tube and Right Alternating Current (AC) Generator Wires						RE (-)		Mandatory	
 24 A/F					Mos	22-Jun-2022				
Eff: 09-Mar-2017 Complied With					Hrs	8				
(AVG MAN HRS: 17) (ISSUING AUTHORITY: FAA)					Ldg	6				
2017-04-14 Par. 2(g)	Electrical Power - Inspections of the Fuel Tube and Right Alternating Current (AC) Generator Wires - Inspections, Adjustments, and Corrective Actions						RE (-)		Mandatory	
 24 A/F					Mos	22-Jun-2022				
Eff: 09-Mar-2017 Complied With					Hrs	8				
(AVG MAN HRS: 16) (ISSUING AUTHORITY: FAA)					Ldg	6				
2017-04-14 Par. 2(h)	Electrical Power - Inspections of the Fuel Tube and Right Alternating Current (AC) Generator Wires - Reporting						RE (-)		Mandatory	
 24 A/F					Mos	22-Jun-2022				
Eff: 09-Mar-2017 Complied With					Hrs	8				
(AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA)					Ldg	6				
24-32-00-7200	44 Amp-Hour Marathon Ni-Cad Main Battery (Capacity Check) Functional Check						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 24 A/F					Mos					
S3597-8					Hrs					
41223048					Ldg					
(ZONE: 311) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00)										
24-32-00-7201	43 Amp-Hour Saft Ni-Cad Main Battery (Capacity Check) Functional Check						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 24 A/F					Mos					
S3597-8					Hrs					
41223048					Ldg					
(ZONE: 311) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00)										
24-32-00-7202	42 Amp-Hour Concorde Lead Acid Main Battery (Capacity Check) Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈22-Feb-2025	
 24 A/F	5-12-21				Mos	22-May-2024	12	-/+1m	31-May-2025	7.6 Months (+30 Days)
S3597-8					Hrs	1020:11	600	-/+25	1620:11	260:15 Hrs (+25)
41223048					Ldg	698				
(ZONE: 311) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00)										
Note: Per Supplier Recommendation. Reference Concorde Battery Corp. 24-30-71 Component Maintenance Manual. The recurring interval may be adjusted after the useful battery life is established, based on operations										
 KGR-WP-011 START 21-JAN-2025										
24-32-00-7203	L3 Com PS-835D Standby Battery Pack (Capacity Check) Functional Check						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 24 A/F	Left				Mos	02-Jun-2023				
100-2410-04					Hrs	460:06				
1211128					Ldg	317				
(ZONE: 211) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00)										
24-32-00-7203	L3 Com PS-835D Standby Battery Pack (Capacity Check) Functional Check						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 24 A/F	Right				Mos	02-Jun-2023				
Unknown					Hrs	460:06				
Unknown					Ldg	317				
(ZONE: 212) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00)										
24-32-00-7204	L3 Com PS-855B Standby Battery Pack (Capacity Check) Functional Check						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 24 A/F	Left				Mos	02-Jun-2023				
100-2410-04					Hrs	460:06				
1211128					Ldg	317				
(ZONE: 211) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00)										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
24-32-00-7204	L3 Com PS-855B Standby Battery Pack (Capacity Check) Functional Check						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 24 A/F	Right				Mos	02-Jun-2023				
Unknown					Hrs	460:06				
Unknown					Ldg	317				
(ZONE: 212) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00)										
24-32-00-7205	Securaplane Standby Battery (Energy Level Test) Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 24 A/F	Left5-12-03				Mos	22-May-2024	24	-/+1m (31-May-2026)	1.6 Years (+30 Days)	
100-2410-04					Hrs	1020:11				
1211128					Ldg	698				
(ZONE: 211) (SOURCE: 560 XL MM Section 5-10-02, 5-18-00)										
Note: NOTE:Per Supplier Recommendation. Reference Securaplane Technologies Inc. 24-32-24 Component Maintenance Manual.										
24-41-02-7200	External Power Overvoltage System Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 24 A/F	5-12-13				Mos		72	-/+1m (30-Jun-2028)	3.7 Years (+30 Days)	
					Hrs					
					Ldg					
(ZONE: 321) (SOURCE: 560 XL MM Section 5-10-02)										
560XL-24-01	Electrical Power - Saft Battery Installation						T (A/R)		Optional	
 24 A/F					Mos					
Eff: 13-May-1999					Hrs					
					Ldg					
560XL-24-02	Electrical Power - Concorde Battery Installation						RE (-)		Recommended	
 24 A/F					Mos	22-Jun-2022				
Not Applicable	effective before manufacture				Hrs	8				
					Ldg	6				
560XL-24-02 Rev 01	Electrical Power - Concorde Battery Installation						T (A/R)		Optional	
 24 A/F					Mos					
Eff: 20-Feb-2001					Hrs					
					Ldg					
560XL-24-16	APU Starter/Generator Wiring Improvement						RE (-)		Recommended	
 24 A/F					Mos	22-Jun-2022				
Eff: 15-Nov-2010 Not Applicable	effective before manufacture				Hrs	8				
					Ldg	6				
560XL-24-17	Tailcone Inverter Relocation						RE (-)		Discretionary	
 24 A/F					Mos					
Eff: 28-Jul-2010					Hrs					
					Ldg					
560XL-24-18	Standby Power Wiring Modification						RE (-)		Recommended	
 24 A/F					Mos	22-Jun-2022				
Eff: 03-Nov-2011 Not Applicable	effective before manufacture				Hrs	8				
					Ldg	6				
560XL-24-19	Electrical Power - Right Hand Engine Wire Bundle Routing Improvement						RE (-)		Recommended	
 24 A/F					Mos	22-Jun-2022				
Eff: 08-Mar-2017 Not Applicable	effective before manufacture				Hrs	8				
(AVG MAN HRS: 1)					Ldg	6				
560XL-24-20	Electrical Power - AC J-Box Wire Bundle Anchor Installation						RE (-)		Mandatory	
 24 A/F					Mos	22-Jun-2022				
Eff: 03-Oct-2017 Not Applicable	by S/N				Hrs	8				
(AVG MAN HRS: 3)					Ldg	6				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SB560XL-24-21	Electrical Power - Install New Right Alternator Power Control Unit (PCU) (UE016) Mounting Bracket						RE (-)		Recommended, Service Bulletin	
 24 A/F						Mos	22-Jun-2022			
Eff: 08-Nov-2019 Complied With						Hrs	8			
(AVG MAN HRS: 3)						Ldg	6			
SB560XL-24-21 R1	Electrical Power - Install New Right Alternator Power Control Unit (PCU) (UE016) Mounting Bracket						RE (-)		Recommended	
 24 A/F						Mos	22-Jun-2022			
Eff: 13-Mar-2020 Not	basic issue c/w					Hrs	8			
Applicable						Ldg	6			
(AVG MAN HRS: 3)										
SL560XL-24-07	Electrical Power - Right Ac Generator Wire Routing Verification						RE (-)		Mandatory	
 24 A/F						Mos	22-Jun-2022			
Eff: 13-Jan-2017 Not	by aircraft S/N					Hrs	8			
Applicable						Ldg	6			
(AVG MAN HRS: 16)										
SL560XL-24-08	Starting - Engine Starter Generator and Auxiliary Power Unit (APU) Starter Generator Ground Repair						RE (-)		Service Letter	
 24 A/F						Mos				
Eff: 02-Jan-2018						Hrs				
(AVG MAN HRS: 13)						Ldg				
SL560XL-24-09	Electrical Power - Battery Temperature Indicator Gage Blanking Plate Installation						RE (-)		Service Letter	
 24 A/F						Mos				
Eff: 30-Mar-2018						Hrs				
						Ldg				
▼ 25 - EQUIPMENT/FURNISHINGS										
	ABC Vanity Switch						RE (O/C)			
 25 A/F						Mos	22-Jun-2022			
Unknown						Hrs	0			
Unknown						Ldg	0			
	Crew Flashlight						RE (O/C)			
 25 A/F						Mos	22-Jun-2022			
Unknown						Hrs	0			
Unknown						Ldg	0			
	Crew Flashlight Battery						RE (H/T)			
 25 A/F						Mos	22-Jun-2022			
Unknown						Hrs	0			
Unknown						Ldg	0			
	Crew Seat Assy						RE (O/C)			
 25 A/F	Copilot					Mos	22-Jun-2022			
Unknown						Hrs	0			
Unknown						Ldg	0			
	Crew Seat Assy						RE (O/C)			
 25 A/F	Pilot					Mos	22-Jun-2022			
Unknown						Hrs	0			
Unknown						Ldg	0			
	Digital Interface Unit (DIU)						RE (O/C)			
 25 A/F						Mos	22-Jun-2022			
Unknown						Hrs	0			
Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		DVD Player								RE (O/C)	
	25 A/F	Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		ELT Antenna								RE (O/C)	
	25 A/F	110-340 686028					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		ELT Buzzer								RE (O/C)	
	25 A/F	130-4004 Unknown					Mos	22-Jun-2022			
			0				Hrs	0			
			0				Ldg	0			
		ELT Code-15 digit								RE (O/C)	
	25 A/F	NAV ELT CODE 21C693A9EEFFBFF					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		ELT Programming Adapter								RE (O/C)	
	25 A/F	453-5068 Unknown					Mos	22-Jun-2022			
			0				Hrs	0			
			0				Ldg	0			
		ELT Remote Switch								RE (O/C)	
	25 A/F	452-0010 Unknown Alias1:25-60-00					Mos	22-Jun-2022			
			0				Hrs	0			
			0				Ldg	0			
		Emergency Locator Transmitter								RE (O/C)	
	25 A/F	453-5060 252-06961 Brand C:256019					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Emergency Locator Transmitter Battery								RE (H/T)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS
	25 A/F	452-0133 394153-020 Brand C:256025, Ref.:25-60-10-9600					Mos	06-Jun-2022			
							Hrs				
							Ldg				
		Externally Servicable Toilet								RE (O/C)	
	25 A/F	15900-023 0502					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		First Aid Kit								RE (O/C)	
	25 A/F	Unknown 032822004 Expiration Date 31-May-2025					Mos	22-May-2024		31-May-2025	7.6 Months
			0				Hrs	1020:11			
			0				Ldg	698			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	25 A/F Unknown Unknown	Heated Water Tank (Prepco)						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	25 A/F Unknown Unknown (ZONE: 261, 262)	Life Raft						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	25 A/F P01074-207 22032070058	Life Vest Copilot New						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	25 A/F P01074-207 22040410021	Life Vest Lavatory New						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	25 A/F P01074-207 22032070008	Life Vest Left No.1 New						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	25 A/F P01074-207 22040410087	Life Vest Left No.2 New						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	25 A/F P01074-207 22040410165X	Life Vest Left No.3 New						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	25 A/F P01074-207 22032050070	Life Vest Left No.4 New						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	25 A/F Unknown Unknown	Life Vest No.10						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	25 A/F Unknown Unknown	Life Vest No.11						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	25 A/F Unknown Unknown	Life Vest No.9						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	25 A/F Unknown Unknown	Life Vest No.9						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	25 A/F	Life Vest Pilot						RE (O/C)			
	P01074-207	New					Mos	22-Jun-2022			
	22040410047						Hrs	0			
							Ldg	0			
	25 A/F	Life Vest Right No.1						RE (O/C)			
	P01074-207	New					Mos	22-Jun-2022			
	22032070064						Hrs	0			
							Ldg	0			
	25 A/F	Life Vest Right No.2						RE (O/C)			
	P01074-207	New					Mos	22-Jun-2022			
	22032070043						Hrs	0			
							Ldg	0			
	25 A/F	Life Vest Right No.3						RE (O/C)			
	P01074-207	New					Mos	22-Jun-2022			
	22032070054						Hrs	0			
							Ldg	0			
	25 A/F	Life Vest Right No.4						RE (O/C)			
	P01074-207	New					Mos	22-Jun-2022			
	21110270028						Hrs	0			
							Ldg	0			
	25 A/F	Media Server Cabin						RE (O/C)			
	Unknown						Mos	22-Jun-2022			
	Unknown						Hrs	0			
							Ldg	0			
	25 A/F	Microwave Oven						RE (O/C)			
	910-0029-02						Mos				
	21-12-32883						Hrs				
							Ldg				
	25 A/F	Mode S Code						RE (O/C)			
	Unknown						Mos	22-Jun-2022			
	010 010 011 101 010 011 1						Hrs	0			
							Ldg	0			
	25 A/F	Passenger Seat Left No.1						RE (O/C)			
	Unknown						Mos	22-Jun-2022			
	Unknown						Hrs	0			
							Ldg	0			
	25 A/F	Passenger Seat Left No.2						RE (O/C)			
	Unknown						Mos	22-Jun-2022			
	Unknown						Hrs	0			
							Ldg	0			
	25 A/F	Passenger Seat Left No.3						RE (O/C)			
	Unknown						Mos	22-Jun-2022			
	Unknown						Hrs	0			
							Ldg	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	25 A/F Unknown Unknown	Passenger Seat Left No.4					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F Unknown Unknown	Passenger Seat Right No.1					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F Unknown Unknown	Passenger Seat Right No.2					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F Unknown Unknown	Passenger Seat Right No.3					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F Unknown Unknown	Passenger Seat Right No.4					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F SWI829-31 202200000002713	RHF Armrest - Armrest Switch New					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F Unknown Unknown	SCS Equipment					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F Unknown Unknown	Smoke Goggle Assembly Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F Unknown Unknown	Smoke Goggle Assembly Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F Unknown Unknown	Switch Galley					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	25 A/F SWI829-O8 202200000004502	Switch Panel Galley					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining	
Temperature Probe											
	25 A/F					Mos	22-Jun-2022		RE (O/C)		
	Unknown					Hrs	0				
	Unknown					Ldg	0				
Vanity Sink Drain Valve											
	25 A/F					Mos	22-Jun-2022		RE (O/C)		
	Unknown					Hrs	0				
	Unknown					Ldg	0				
2023-12-25 Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets											
	25 A/F					Mos	08-Aug-2023		RE (-)	Mandatory	
	Eff: 23-Aug-2023 Not Applicable	as per installed P/N					Hrs	616:39			
	(ISSUING AUTHORITY: FAA) Note: APPLICABILITY: This AD applies to Survitec Group Limited (RFD Beaufort Ltd.) life jackets identified in paragraphs (c) (1) and (2) of this AD, having a part number and serial number identified in tables 2 through 13 of Survitec [RFD] Alert Service Bulletin 25-207-A, Version 1, dated November 24, 2021, and a date of manufacture between October 1, 2018, and April 30, 2019, inclusive.						Ldg	407			
2023-12-25 Par. (g) Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets - Inspection											
	25 A/F					Mos	08-Aug-2023		RE (-)	Mandatory	
	Eff: 23-Aug-2023 Not Applicable	as per installed P/N					Hrs	616:39			
	(ISSUING AUTHORITY: FAA) Note: COMPLIANCE: Within 4 months after the effective date of this AD, do a general visual inspection for a discrepancy (mismatch of the valise/container description and life jacket type) of the life jacket, in accordance with paragraphs 2.A. through 2.C. of the Accomplishment Instructions of Survitec [RFD] Alert Service Bulletin 25-207-A, Version 1, dated November 24, 2021.						Ldg	407			
2023-12-25 Par. (h) Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets - Follow-On and Corrective Action											
	25 A/F					Mos	08-Aug-2023		RE (-)	Mandatory	
	Eff: 23-Aug-2023 Not Applicable	as per installed P/N					Hrs	616:39			
	(ISSUING AUTHORITY: FAA) Note: COMPLIANCE: Before further flight after accomplishing the requirements of paragraph (g) of this AD, do the applicable actions required by paragraph (h)(1) and (2) of this AD.						Ldg	407			
2023-14-10 Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats (Supersedes FAA AD 2019-21-06)											
	25 A/F					Mos	08-Aug-2023		RE (-)	Mandatory (Appliance AD)	
	Eff: 07-Sep-2023 Not Applicable	affected seats not installed					Hrs	616:39			
	(ISSUING AUTHORITY: FAA) Note: APPLICABILITY: (1) This AD applies to: (i) Ipeco Holdings Limited (Ipeco) pilot and co-pilot seats with a part number (P/N) listed in Paragraph 1.A., Planning Information, Tables 1 and 2, of Ipeco Service Bulletin (SB) Number 063-25-14, Revision 00, dated August 14, 2018, and (ii) Ipeco pilot seat P/N 3A063-0099-01-1 and Ipeco co-pilot seat P/N 3A063-0100-01-1. (2) These seats are installed on, but not limited to, ATR-GIE Avions de Transport Regional ATR 42 and ATR 72 airplanes.						Ldg	407			
2023-14-10 Par. (g)(1) Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Modify and Re-Identify each Affected Pilot and Co-Pilot Seat											
	25 A/F					Yrs	08-Aug-2023		RE (-)	Mandatory (Appliance AD)	
	Eff: 12-Dec-2017 Not Applicable	affected seats not installed					Hrs	616:39			
	(ISSUING AUTHORITY: FAA) Note: COMPLIANCE: For seats that have not installed the track lock spring modification kit, within two years after December 12, 2017 (the effective date of AD 2017-22-02, Amendment 39-19082 (82 FR 51552, November 7, 2017)), modify and re-identify each affected pilot and co-pilot seat using the Accomplishment Instructions of Ipeco SB Number 063-25-08, Revision 00; Ipeco SB Number 063-25-09, Revision 00; or Ipeco SB Number 063-25-10, Revision 00; all dated May 31, 2016, as applicable to each affected seat.						Ldg	407			
2023-14-10 Par. (g)(2)(i) Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Inspect the Track Lock Spring of Each Seat											
	25 A/F					Mos	08-Aug-2023		RE (-)	Mandatory (Appliance AD)	
	Eff: 07-Sep-2023 Not Applicable	affected seats not installed					Hrs	616:39			
	(ISSUING AUTHORITY: FAA)						Ldg	407			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2023-14-10 Par. (g)(2)(ii)	Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Replace both Track Lock Springs of the Affected Seat						RE (-)		Mandatory (Appliance AD)	
 25 A/F					Mos	08-Aug-2023				
Eff: 07-Sep-2023 Not Applicable	affected seats not installed				Hrs	616:39				
(ISSUING AUTHORITY: FAA)					Ldg	407				
Note: COMPLIANCE: If, during any inspection as required by paragraph (g)(2)(i) of this AD, any damage on, or incorrect installation of, any track lock spring is found on the pilot or co-pilot seat, before further flight, replace both track lock springs of the affected seat with a part eligible for installation using the Accomplishment Instructions, paragraph 3.3.3.1 or 3.3.3.2, as applicable, of Ipeco SB Number 063-25-14, Revision 00, dated August 14, 2018.										
2023-14-10 Par. (h)	Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - New Mandatory Terminating Action						RE (-)		Mandatory (Appliance AD)	
 25 A/F					Mos	08-Aug-2023				
Eff: 07-Sep-2023 Not Applicable	affected seats not installed				Hrs	616:39				
(ISSUING AUTHORITY: FAA)					Ldg	407				
Note: COMPLIANCE: As a mandatory terminating action to the inspections required by paragraph (g)(2)(i) of this AD, within 12 months after the effective date of this AD, or at the next Base Maintenance check, whichever occurs later, modify and re-identify each affected seat in accordance with the Accomplishment Instructions of Ipeco SB Number 063-25-15, Issue 2; SB Number 063-25-16, Issue 2; SB Number 063-25-17, Issue 2; or SB Number 063-25-18, Issue 2; all dated March 8, 2022, as applicable to each affected seat.										
25-00-CUS-001	ELT test and inspection per National Authority						RE			
 25 A/F					Mos	22-May-2024	12		22-May-2025	7.3 Months
					Hrs	1020:11				
					Ldg	698				
Note: CAA Requirement										
251000-0102	PA AMPLIFIER +32DBV						RE (O/C)			
 25 A/F					Mos	22-Jun-2022				
Unknown					Hrs	0				
Unknown					Ldg	0				
25-11-01-2200	Crew Seat Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Mar-2026
 25 A/F	Copilot5-12-08				Mos					
Unknown					Hrs		2,400	-/+25	(2400)	1040:04 Hrs (+25)
Unknown					Ldg					
(ZONE: 244) (SOURCE: 560 XL MM Section 5-10-02)										
25-11-01-2200	Crew Seat Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Mar-2026
 25 A/F	Pilot5-12-08				Mos					
Unknown					Hrs		2,400	-/+25	(2400)	1040:04 Hrs (+25)
Unknown					Ldg					
(ZONE: 243) (SOURCE: 560 XL MM Section 5-10-02)										
25-21-01-2200	Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 25 A/F	Left No.15-12-06				Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
Unknown					Hrs					
Unknown					Ldg					
(ZONE: 252, 261, 262, 171)										
25-21-01-2200	Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 25 A/F	Left No.25-12-06				Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
Unknown					Hrs					
Unknown					Ldg					
(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
25-21-01-2200		Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection									
	25 A/F	Left No.35-12-06				Mos		48	-/+1m	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS (30-Jun-2026)	1.7 Years (+30 Days)
	Unknown					Hrs					
	Unknown					Ldg					
		(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)									
25-21-01-2200		Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection									
	25 A/F	Left No.45-12-06				Mos		48	-/+1m	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS (30-Jun-2026)	1.7 Years (+30 Days)
	Unknown					Hrs					
	Unknown					Ldg					
		(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)									
25-21-01-2200		Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection									
	25 A/F	Right No.15-12-06				Mos		48	-/+1m	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS (30-Jun-2026)	1.7 Years (+30 Days)
	Unknown					Hrs					
	Unknown					Ldg					
		(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)									
25-21-01-2200		Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection									
	25 A/F	Right No.25-12-06				Mos		48	-/+1m	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS (30-Jun-2026)	1.7 Years (+30 Days)
	Unknown					Hrs					
	Unknown					Ldg					
		(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)									
25-21-01-2200		Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection									
	25 A/F	Right No.35-12-06				Mos		48	-/+1m	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS (30-Jun-2026)	1.7 Years (+30 Days)
	Unknown					Hrs					
	Unknown					Ldg					
		(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)									
25-21-01-2200		Passenger Seats and Forward and Aft Side-Facing Seats Detailed Inspection									
	25 A/F	Right No.45-12-06				Mos		48	-/+1m	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS (30-Jun-2026)	1.7 Years (+30 Days)
	Unknown					Hrs					
	Unknown					Ldg					
		(ZONE: 252, 261, 262, 171) (SOURCE: 560 XL MM Section 5-10-02)									
25-60-00-2200		First Aid Kit Detailed Inspection									
	25 A/F	5-12-01				Mos	22-May-2024	12	-/+1m	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS (31-May-2025)	7.6 Months (+30 Days)
	Unknown					Hrs	1020:11				
	032822004					Ldg	698				
		(ZONE: 241, 242) (SOURCE: 560 XL MM Section 5-10-02)									
25-60-00-2201		Smoke Goggle Detailed Inspection									
	25 A/F	Left5-12-01				Mos	22-May-2024	12	-/+1m	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS (31-May-2025)	7.6 Months (+30 Days)
	Unknown					Hrs	1020:11				
	Unknown					Ldg	698				
		(ZONE: 241) (SOURCE: 560 XL MM Section 5-10-02)									
25-60-00-2201		Smoke Goggle Detailed Inspection									
	25 A/F	Right5-12-01				Mos	22-May-2024	12	-/+1m	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS (31-May-2025)	7.6 Months (+30 Days)
	Unknown					Hrs	1020:11				
	Unknown					Ldg	698				
		(ZONE: 242) (SOURCE: 560 XL MM Section 5-10-02)									

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection									
	25 A/F	Copilot5-12-12				Mos		60	-/+1m	(30-Jun-2027)	2.7 Years (+30 Days)
	P01074-207					Hrs					
	22032070058					Ldg					
	(ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)										
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection									
	25 A/F	Lavatory5-12-12				Mos		60	-/+1m	(30-Jun-2027)	2.7 Years (+30 Days)
	P01074-207					Hrs					
	22040410021					Ldg					
	(ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)										
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection									
	25 A/F	Left No.15-12-12				Mos		60	-/+1m	(30-Jun-2027)	2.7 Years (+30 Days)
	P01074-207					Hrs					
	22032070008					Ldg					
	(ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)										
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection									
	25 A/F	Left No.25-12-12				Mos		60	-/+1m	(30-Jun-2027)	2.7 Years (+30 Days)
	P01074-207					Hrs					
	22040410087					Ldg					
	(ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)										
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection									
	25 A/F	Left No.35-12-12				Mos		60	-/+1m	(30-Jun-2027)	2.7 Years (+30 Days)
	P01074-207					Hrs					
	22040410165X					Ldg					
	(ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)										
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection									
	25 A/F	Left No.45-12-12				Mos		60	-/+1m	(30-Jun-2027)	2.7 Years (+30 Days)
	P01074-207					Hrs					
	22032050070					Ldg					
	(ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)										
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection									
	25 A/F	No.10				Mos		RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	Unknown					Hrs					
	Unknown					Ldg					
	(ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)										
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection									
	25 A/F	No.11				Mos		RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	Unknown					Hrs					
	Unknown					Ldg					
	(ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)										
25-60-00-2202		P01074-207 Life Vest Pouch Detailed Inspection									
	25 A/F	No.9				Mos		RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	Unknown					Hrs					
	Unknown					Ldg					
	(ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
25-60-00-2202	P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 25 A/F P01074-207 22040410047 (ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)	Pilot5-12-12				Mos		60	-/+1m (30-Jun-2027)	2.7 Years (+30 Days)	
					Hrs					
					Ldg					
25-60-00-2202	P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 25 A/F P01074-207 22032070064 (ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)	Right No.15-12-12				Mos		60	-/+1m (30-Jun-2027)	2.7 Years (+30 Days)	
					Hrs					
					Ldg					
25-60-00-2202	P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 25 A/F P01074-207 22032070043 (ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)	Right No.25-12-12				Mos		60	-/+1m (30-Jun-2027)	2.7 Years (+30 Days)	
					Hrs					
					Ldg					
25-60-00-2202	P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 25 A/F P01074-207 22032070054 (ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)	Right No.35-12-12				Mos		60	-/+1m (30-Jun-2027)	2.7 Years (+30 Days)	
					Hrs					
					Ldg					
25-60-00-2202	P01074-207 Life Vest Pouch Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 25 A/F P01074-207 21110270028 (ZONE: 251, 252, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)	Right No.45-12-12				Mos		60	-/+1m (30-Jun-2027)	2.7 Years (+30 Days)	
					Hrs					
					Ldg					
25-60-00-9600	P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 25 A/F P01074-207 22032070058 Manufactured Date 31-Mar-2022 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)	Copilot				Mos	22-Jun-2022	120	31-Mar-2032	7.5 Years	
					Hrs					
					Ldg					
25-60-00-9600	P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 25 A/F P01074-207 22040410021 Manufactured Date 07-Apr-2022 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)	Lavatory				Mos	22-Jun-2022	120	07-Apr-2032	7.5 Years	
					Hrs		8			
					Ldg		6			
25-60-00-9600	P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 25 A/F P01074-207 22032070008 Manufactured Date 31-Mar-2022 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)	Left No.1				Mos	22-Jun-2022	120	31-Mar-2032	7.5 Years	
					Hrs					
					Ldg					

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.2				Mos	22-Jun-2022	120		07-Apr-2032	7.5 Years	
	P01074-207					Hrs						
	22040410087					Ldg						
	Manufactured Date 07-Apr-2022 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.3				Mos	22-Jun-2022	120		07-Apr-2032	7.5 Years	
	P01074-207					Hrs						
	22040410165X					Ldg						
	Manufactured Date 07-Apr-2022 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Left No.4				Mos	22-Jun-2022	120		31-Mar-2032	7.5 Years	
	P01074-207					Hrs						
	22032050070					Ldg						
	Manufactured Date 31-Mar-2022 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	No.10				Mos						
	Unknown					Hrs						
	Unknown					Ldg						
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	No.11				Mos						
	Unknown					Hrs						
	Unknown					Ldg						
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	No.9				Mos						
	Unknown					Hrs						
	Unknown					Ldg						
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Pilot				Mos	22-Jun-2022	120		07-Apr-2032	7.5 Years	
	P01074-207					Hrs						
	22040410047					Ldg						
	Manufactured Date 07-Apr-2022 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F	Right No.1				Mos	22-Jun-2022	120		31-Mar-2032	7.5 Years	
	P01074-207					Hrs						
	22032070064					Ldg						
	Manufactured Date 31-Mar-2022 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration									
	25 A/F	Right No.2				Mos	22-Jun-2022	120		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	7.5 Years
	P01074-207					Hrs					
	22032070043					Ldg					
	Manufactured Date 31-Mar-2022 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration									
	25 A/F	Right No.3				Mos	22-Jun-2022	120		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	7.5 Years
	P01074-207					Hrs					
	22032070054					Ldg					
	Manufactured Date 31-Mar-2022 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9600		P01074-207 Life Vest (Accomplish Supplier 120 Month Maintenance Inspection) Restoration									
	25 A/F	Right No.4				Mos	22-Jun-2022	120		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	7.1 Years
	P01074-207					Hrs					
	21110270028					Ldg					
	Manufactured Date 15-Nov-2021 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration									
	25 A/F	Copilot				Mos		RE (N/A)		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	P01074-207					Hrs					
	22032070058					Ldg					
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration									
	25 A/F	Lavatory				Mos		RE (N/A)		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	P01074-207					Hrs					
	22040410021					Ldg					
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration									
	25 A/F	Left No.1				Mos		RE (N/A)		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	P01074-207					Hrs					
	22032070008					Ldg					
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration									
	25 A/F	Left No.2				Mos		RE (N/A)		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	P01074-207					Hrs					
	22040410087					Ldg					
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration									
	25 A/F	Left No.3				Mos		RE (N/A)		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	P01074-207					Hrs					
	22040410165X					Ldg					
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Left No.4									
	P01074-207										
	22032050070										
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	No.10									
	Unknown										
	Unknown										
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	No.11									
	Unknown										
	Unknown										
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	No.9									
	Unknown										
	Unknown										
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Pilot									
	P01074-207										
	22040410047										
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Right No.1									
	P01074-207										
	22032070064										
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Right No.2									
	P01074-207										
	22032070043										
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Right No.3									
	P01074-207										
	22032070054										
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
25-60-00-9601		P01074-103, P0723E105PA, GA12 Life Vest (Accomplish Supplier 60 Month Maintenance Inspection) Restoration							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	25 A/F	Right No.4									
	P01074-207										
	21110270028										
	(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										

Task No	Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
25-60-00-9602		Crew Flashlight D-Cell Battery Discard						RE	05-10-01, 05-10-02, Category 8		
	25 A/F	5-12-01				Mos	22-May-2024	12	-/+1m	(31-May-2025)	7.6 Months (+30 Days)
	Unknown					Hrs	1020:11				
	Unknown					Ldg	698				
MRBR Task:33-50-00-901 (ZONE: 241, 242) (SOURCE: 560XL MM)											
25-60-10-7200		Artex 110-4 Emergency Locator Transmitter System Detailed Inspection and Functional Check (Airplanes -5001 thru -5500 Not Incorporating SB560XL-25-11)						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F					Mos					
	453-5060					Hrs					
	252-06961					Ldg					
(SOURCE: 560 XL MM Section 5-10-02, 5-13-00)											
25-60-10-7201		Artex 110-406 Emergency Locator Transmitter System Detailed Inspection and Functional Check (Airplanes -5501 thru -5564 and Airplanes -5002 thru -5372 Not Incorporating SB560XL-25-11)						RE (N/A)	05-10-01, 05-10-02, Category 8		
	25 A/F					Mos					
	453-5060					Hrs					
	252-06961					Ldg					
MRBR Task:25-60-00-704, MRBR Task:25-60-00-703, MRBR Task:25-60-00-701, MRBR Task:25-60-00-205, MRBR Task:25-60-00-204 (SOURCE: 560XL MM)											
25-60-10-7202		Artex C406-2 Emergency Locator Transmitter System Detailed Inspection and Functional Test (Airplanes -5501 thru -5564 and Airplanes -5002 thru -5372 Incorporating SB560XL-25-11)						RE (N/A)	05-10-01, 05-10-02, Category 8		
	25 A/F					Mos					
	453-5060					Hrs					
	252-06961					Ldg					
MRBR Task:25-60-00-204, MRBR Task:25-60-00-706, MRBR Task:25-60-00-704, MRBR Task:25-60-00-703, MRBR Task:25-60-00-701, MRBR Task:25-60-00-209, MRBR Task:25-60-00-206, MRBR Task:25-60-00-205 (SOURCE: 560XL MM)											
25-60-10-7203		Artex C406-N Emergency Locator Transmitter System Detailed Inspection and Functional Check (Airplanes -5565 and On)						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	25 A/F					Mos	22-May-2024	12		31-May-2025	7.6 Months
	453-5060					Hrs	1020:11				
	252-06961					Ldg	698				
(SOURCE: 560 XL MM Section 5-10-02, 5-13-00)											
Note: NOTE: National Requirements may exist with a different interval											
25-60-10-9600		Emergency Locator Transmitter Battery Discard						RE	05-10-01, 05-10-02, 05-12-00, Category 8		
	25 A/F					Mos	06-Jun-2022	36		31-Mar-2027	2.5 Years
	452-0133					Hrs					
	394153-020					Ldg					
Expiration Date 01-Mar-2027											
MRBR Task:25-60-00-902 (SOURCE: 560XL MM)											
560XL-25-12		Glareshield Leather Strip Installation						RE (-)	Optional		
	25 A/F					Mos					
						Hrs					
						Ldg					
560XL-25-12 Rev 01		Glareshield Leather Strip Installation						T (A/R)	Optional		
	25 A/F					Mos					
	Eff: 24-Aug-2004					Hrs					
						Ldg					
560XL-25-18		Equipment/Furnishings - Passenger Seat Web Guide Improvement						RE (-)	Optional		
	25 A/F					Mos					
	Eff: 20-Aug-2015					Hrs					
						Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
74-08-09 R2	Equipment/furnishings - Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles						RE (-)		Mandatory	
25 A/F					Mos	22-Jun-2022				
Eff: 06-Aug-1974 Superseded					Hrs	8				
(ISSUING AUTHORITY: FAA)					Ldg	6				
74-08-09 R2 Paragraph (g)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - (1) Install a placard on each side of each lavatory door over the door knob, or on each side of each lavatory door, or adjacent to each side of each lavatory door. (2) Install a placard on or near each lavatory paper or linen waste disposal receptacle door, containing the legible words or symbology indicating "No Cigarette Disposal."						RE (-)		Mandatory	
25 A/F					Mos	22-Jun-2022				
Eff: 06-Aug-1974 Superseded					Hrs	8				
(ISSUING AUTHORITY: FAA)					Ldg	6				
74-08-09 R2 Paragraph (h)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - establish a procedure that requires that, no later than a time immediately after the "No Smoking" sign is extinguished following takeoff, an announcement be made by a crewmember to inform all aircraft occupants that smoking is prohibited in the aircraft lavatories; except that, if the aircraft is not equipped with a "No Smoking" sign, the required procedure must provide that the announcement be made prior to each takeoff.						RE (-)		Mandatory	
25 A/F					Mos	22-Jun-2022				
Eff: 06-Aug-1974 Superseded					Hrs	8				
(ISSUING AUTHORITY: FAA)					Ldg	6				
74-08-09 R2 Paragraph (i)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Install a self-contained, removable ashtray on or near the entry side of each lavatory door. One ashtray may serve more than one lavatory door if the ashtray can be seen readily from the cabin side of each lavatory door served.						RE (-)		Mandatory	
25 A/F					Mos	22-Jun-2022				
Eff: 06-Aug-1974 Superseded					Hrs	8				
(ISSUING AUTHORITY: FAA)					Ldg	6				
74-08-09 R2 Paragraph (j)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - An airplane with multiple lavatory doors may be operated with up to 50 percent of the lavatory door ashtrays missing or inoperative, provided 50 percent of the missing or inoperative ashtrays are replaced within 3 days and all remaining missing or inoperative ashtrays are replaced within 10 days. An airplane with only 1 lavatory door may be operated for a period of 10 days with the lavatory door ashtray missing or inoperative						RE (-)		Mandatory	
25 A/F					Mos	22-Jun-2022				
Eff: 06-Aug-1974 Superseded					Hrs	8				
(ISSUING AUTHORITY: FAA)					Ldg	6				
74-08-09 R2 Paragraph (k)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Inspect all lavatory paper and linen waste receptacle enclosure access doors and disposal doors for proper operation, fit, sealing, and latching for the containment of possible trash fires.						RE (-)		Mandatory	
25 A/F					Mos	22-Jun-2022				
Eff: 06-Aug-1974 Superseded					Hrs	8				
(ISSUING AUTHORITY: FAA)					Ldg	6				
74-08-09 R3	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles						RE (-)		Mandatory	
25 A/F					Mos	18-Apr-2024				
Eff: 28-Mar-2012 Complied AD Not Adopted by EASA					Hrs	979:20				
With					Ldg	667				
(ISSUING AUTHORITY: FAA)										
74-08-09 R3 Paragraph (g)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - (1) Install a placard on each side of each lavatory door over the door knob, or on each side of each lavatory door, or adjacent to each side of each lavatory door. (2) Install a placard on or near each lavatory paper or linen waste disposal receptacle door, containing the legible words or symbology indicating "No Cigarette Disposal."						RE (-)		Mandatory	
25 A/F					Mos	18-Apr-2024				
Eff: 06-Aug-1974 Complied AD Not Adopted by EASA					Hrs	979:20				
With					Ldg	667				
(ISSUING AUTHORITY: FAA)										
74-08-09 R3 Paragraph (h)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - establish a procedure that requires that, no later than a time immediately after the "No Smoking" sign is extinguished following takeoff, an announcement be made by a crewmember to inform all aircraft occupants that smoking is prohibited in the aircraft lavatories; except that, if the aircraft is not equipped with a "No Smoking" sign, the required procedure must provide that the announcement be made prior to each takeoff.						RE (-)		Mandatory	
25 A/F					Mos	18-Apr-2024				
Eff: 06-Aug-1974 Complied AD Not Adopted by EASA					Hrs	979:20				
With					Ldg	667				
(ISSUING AUTHORITY: FAA)										

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
74-08-09 R3 Paragraph (i)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Install a self-contained, removable ashtray on or near the entry side of each lavatory door. One ashtray may serve more than one lavatory door if the ashtray can be seen readily from the cabin side of each lavatory door served.						RE (-)		Mandatory	
25 A/F					Mos	18-Apr-2024				
Eff: 06-Aug-1974 Complied	AD Not Adopted by EASA				Hrs	979:20				
With					Ldg	667				
(ISSUING AUTHORITY: FAA)										
74-08-09 R3 Paragraph (j)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - An airplane with multiple lavatory doors may be operated with up to 50 percent of the lavatory door ashtrays missing or inoperative, provided 50 percent of the missing or inoperative ashtrays are replaced within 3 days and all remaining missing or inoperative ashtrays are replaced within 10 days. An airplane with only 1 lavatory door may be operated for a period of 10 days with the lavatory door ashtray missing or inoperative						RE (-)		Mandatory	
25 A/F					Mos	18-Apr-2024				
Eff: 28-Mar-2012 Complied	AD Not Adopted by EASA				Hrs	979:20				
With					Ldg	667				
(ISSUING AUTHORITY: FAA)										
Note: Note 1 to paragraph (j) of this AD; This AD permits a lavatory door ashtray to be missing, although the FAA-approved Master Minimum Equipment List (MMEL) may not allow such provision. In any case, the provisions of this AD prevail.										
74-08-09 R3 Paragraph (k)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Inspect all lavatory paper and linen waste receptacle enclosure access doors and disposal doors for proper operation, fit, sealing, and latching for the containment of possible trash fires.						RE		Mandatory	≈24-Aug-2025
25 A/F					Mos	18-Apr-2024				
Eff: 06-Aug-1974 Complied	AD Not Adopted by EASA				Hrs	979:20	1,000		1979:20	619:24 Hrs
With					Ldg	667				
(ISSUING AUTHORITY: FAA)										
CF-48-05	Emergency Flare Installations (Previously issued as T/11/48)						RE (-)		Mandatory	
25 A/F					Mos	22-Jun-2022				
Not Applicable	by installed equipment				Hrs	8				
(ISSUING AUTHORITY: TC)										
CF-59-01	Floor-Mounted Hand-Pump Type Fire Extinguishers						RE (-)		Mandatory	
25 A/F					Mos	22-Jun-2022				
Eff: 31-Mar-1959 Not	by installed equipment				Hrs	8				
Applicable					Ldg	6				
(ISSUING AUTHORITY: TC)										
CF-83-31R2	Lavatory Flush Pump Motors						RE (-)		Mandatory	
25 A/F					Mos	22-Jun-2022				
Eff: 07-Apr-1986 Not	by installed equipment				Hrs	8				
Applicable					Ldg	6				
(ISSUING AUTHORITY: TC)										
CIL-25-02	Equipment/Furnishings - Medaire Aircraft First Aid Kits with Medication Subject to Recall Notice						RE (-)	Informational, Service Bulletin		
25 A/F					Mos					
Eff: 05-Nov-2019					Hrs					
					Ldg					
CIL-25-03	Equipment/Furnishings - Seat Pan Tilt Blocking Tab Installation						RE (-)	Informational, Service Letter		
25 A/F					Mos					
Eff: 12-Aug-2020					Hrs					
(AVG MAN HRS: 0.25)					Ldg					
CIL-25-03 R1	Equipment/Furnishings - Seat Pan Tilt Blocking Tab Installation						RE (-)	Informational, Service Letter		
25 A/F					Mos					
Eff: 08-Oct-2020					Hrs					
(AVG MAN HRS: 0.25)					Ldg					
PAD-PAK-04	Pediatric Pad with Battery						RE (-)			
25 A/F					Mos	16-Aug-2024			[01-Jan-2028]	3.2 Years
PAD-PAK-04					Hrs					
L0067					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
PAD-PAK-07	Adult Pad-Pak with Battery						RE (-)			
 25 A/F						Mos	16-Aug-2024		[01-Mar-2028]	3.4 Years
PAD-PAK-07						Hrs				
M0075						Ldg				
PADSAM350P	Defibrillator Heartshine Samaritan						RE (-)			
 25 A/F						Mos	16-Aug-2024		[01-Sep-2028]	3.9 Years
PADSAM350P						Hrs				
24D98027654C24						Ldg				
SB560XL-25-19	Equipment/Furnishings - Replacement of the 4569508-1 Water Barrier Assembly						T (A/R)		Recommended	
 25 A/F						Mos	24-Jul-2024		[31-Jul-2026]	1.8 Years
Eff: 15-Jul-2024 On Hold						Hrs				
(AVG MAN HRS: 0.5)						Ldg				
SL560XL-25-13	Transmittal of Rockwell Collins Aishow 4000 Service Bulletin 30, Correction of Hard Drive Mounting Screws - Mod U						RE (-)		Recommended	
 25 A/F						Mos	22-Jun-2022			
Eff: 22-Mar-2010 Not	effective before manufacture					Hrs	8			
Applicable						Ldg	6			
SL560XL-25-15	Transmittal of Aircraft Belts Inc. SB-BUC062-A001 Inspection of Buckles for Proper Operation						RE (-)		Optional	
 25 A/F						Mos				
						Hrs				
						Ldg				
SL560XL-25-15 Rev 01	Transmittal of Aircraft Belts Inc. SB-BUC062-A001 Inspection of Buckles for Proper Operation						RE (-)		Mandatory	
 25 A/F						Mos	22-Jun-2022			
Eff: 16-Aug-2010 Not	by aircraft S/N					Hrs	8			
Applicable						Ldg	6			
SL560XL-25-16	Transmittal of IPECO Service Bulletins 428-25-01, and 429-25-01, Addition of Cable Clip						RE (-)		Recommended	
 25 A/F						Mos	22-Jun-2022			
Eff: 13-Dec-2010 Not	effective before manufacture					Hrs	8			
Applicable						Ldg	6			
SL560XL-25-17	Transmittal of Goodrich Service Bulletin 1423-25-003 Revision C Lumbar Assembly Cable Wear						RE (-)		Recommended	
 25 A/F						Mos	22-Jun-2022			
Eff: 03-Aug-2012 Not	by S/N					Hrs	8			
Applicable						Ldg	6			
SL560XL-25-18	Equipment/Furnishings - Replacement of the Cabinet Spring Assembly Pins						RE (-)		Recommended	
 25 A/F						Mos	22-Jun-2022			
Eff: 18-Jul-2019 Not	effective before manufacture					Hrs	8			
Applicable						Ldg	6			
(AVG MAN HRS: 3)										
SL560XL-25-19	Equipment/Furnishings - Inspection of the Millennium Crew Seat Assemblies for Incorrectly Installed Seat Pan Tilt Mechanism Snap Rings (Millennium Service Bulletin SB2050-25-20-02)						RE (-)		Recommended, Service Letter	
 25 A/F						Mos	22-Jun-2022			
Eff: 11-Sep-2019 Not	by aircraft S/N					Hrs	8			
Applicable						Ldg	6			
(AVG MAN HRS: 1.8)										
SL560XL-25-19 R1	Equipment/Furnishings - Replacement of the Seat Pan Tilt Snap Rings (Millennium Service Bulletin SB2050-25-20-02B)						RE (-)		Recommended, Service Letter	
 25 A/F						Mos	22-Jun-2022			
Eff: 21-Nov-2019 Not	by aircraft S/N					Hrs	8			
Applicable						Ldg	6			
(AVG MAN HRS: 1.5)										

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SL560XL-25-21		Equipment/Furnishings - Transmittal of Millennium Service Bulletin SB2050-25-20-09 Model 2050 Seating System Cross Tube Cover Installation							RE (-)	Optional	
	25 A/F										
	Eff: 19-Dec-2022										
	(AVG MAN HRS: 0.25)										
SL560XL-25-22		Equipment/Furnishings - Inspection of the SWI610-31 Entry Door Switch Indicator Light Emitting Diode (Led) Lights for Proper Indication							RE (-)	Recommended	
	25 A/F										
	Eff: 09-Jan-2023 Complied With										
	(AVG MAN HRS: 3)										
SL560XL-25-23		Equipment/Furnishings - Passenger Seat Swivel Plate Swing Arm Assembly Fastener Inspection for Proper Adhesive Application							RE (-)	Recommended	
	25 A/F										
	Eff: 05-Apr-2023 Not Applicable	as per A/C S/N									
	(AVG MAN HRS: 8)										
▼ 26 - FIRE PROTECTION											
		Aft Vanity Fire Extinguisher							RE (O/C)		
	26 A/F										
	Unknown										
	Unknown										
		APU Fire Bottle Cartridge							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	26 A/F										
	13083-5										
	NSN										
		Manufactured Date 01-Oct-2021									
		Task:26-21-01-9601, Task:26-21-01-9603 (ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00)									
		Note: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual.									
		Engine Fire Bottle							RE (O/C)		
	26 A/F										
	30400037-1										
	84951B1										
		Engine Fire Bottle							RE (O/C)		
	26 A/F										
	30400037-1										
	84950B1										
		Engine Fire Bottle Cartridge							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	26 A/F										
	13083-5										
	NSN										
		Manufactured Date 01-Sep-2021									
		Task:26-21-01-9600, Task:26-21-01-9602 (ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00)									
		Note: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual.									

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
Engine Fire Bottle Cartridge											
⚙️	26 A/F	Aft - No.2							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	13083-5	New					Mos	13-May-2022	108	31-Oct-2030	6 Years
	NSN						Hrs				
							Ldg				
Manufactured Date 21-Oct-2021											
Task:26-21-01-9600, Task:26-21-01-9602 (ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00)											
Note: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual.											
Engine Fire Bottle Cartridge											
⚙️	26 A/F	Fwd - No.1							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	13083-5	New					Mos	13-May-2022	108	31-Jan-2031	6.3 Years
	NSN						Hrs				
							Ldg				
Manufactured Date 22-Jan-2022											
Task:26-21-01-9600, Task:26-21-01-9602 (ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00)											
Note: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual.											
Engine Fire Bottle Cartridge											
⚙️	26 A/F	Fwd - No.2							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	13083-5	New					Mos	13-May-2022	108	30-Sep-2030	6 Years
	NSN						Hrs				
							Ldg				
Manufactured Date 01-Sep-2021											
Task:26-21-01-9600, Task:26-21-01-9602 (ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00)											
Note: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual.											
Engine Fire Detect (UE001) Cable											
⚙️	26 A/F	Left							RE (O/C)		
	Unknown						Mos	22-Jun-2022			
	Unknown						Hrs	0			
							Ldg	0			
Engine Fire Detect (UE001) Cable											
⚙️	26 A/F	Right							RE (O/C)		
	Unknown						Mos	22-Jun-2022			
	Unknown						Hrs	0			
							Ldg	0			
Engine Fire Detect (UT020) Control Unit											
⚙️	26 A/F								RE (O/C)		
	377-02838						Mos	22-Jun-2022			
	2206-569						Hrs	0			
							Ldg	0			
Engine Fire Detect (UT021) Control Unit											
⚙️	26 A/F								RE (O/C)		
	377-02838						Mos	22-Jun-2022			
	2206-571						Hrs	0			
							Ldg	0			
Fire Bottle APU											
⚙️	26 A/F								RE (O/C)		
	30100033-7						Mos	14-May-2022			
	99333A1						Hrs				
							Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining	
	26 A/F	Portable Fire Extinguisher					RE (O/C)				
	P3APP003010D	Cabin				Mos	24-May-2022		30-Nov-2033	9.1 Years	
	042276	New				Hrs	0				
	Expiration Date 30-Nov-2033				Ldg	0					
	26 A/F	Portable Fire Extinguisher					RE (O/C)				
	P3APP003010D	Cockpit				Mos	24-May-2022		30-Nov-2033	9.1 Years	
	041518	New				Hrs					
	Expiration Date 30-Nov-2033				Ldg						
2006-04-10		This AD Requires Installing Identification Sleeves On The Wires For The Positive And Negative Studs Of The Engine And/ Or (APU) Fire Extinguishing Bottles, As Applicable, And Reconnecting The Wires To The Correct Terminal Studs. (Superseded by AD 2007-11-17						RE (-)		Mandatory	
	26 A/F					Mos	22-Jun-2022				
	Eff: 24-Mar-2006 Superseded				Hrs	8					
	(ISSUING AUTHORITY: FAA)				Ldg	6					
2007-11-17		Wires for the positive and negative terminal studs of the engine and/or auxiliary power unit (APU) fire extinguishing bottles.						RE (-)		Mandatory	
	26 A/F					Mos	22-Jun-2022				
	Eff: 06-Jul-2007 Complied With				Hrs	8					
	(AVG MAN HRS: 4) (ISSUING AUTHORITY: FAA)				Ldg	6					
2021-0185R2		Fire Protection - Hand-operated Fire Extinguishers - Inspection/Replacement						RE (-)		Mandatory (Appliance AD)	
	26 A/F					Mos	12-Sep-2022				
	Eff: 14-Sep-2022 Not	affected P/N not installed				Hrs	129				
	Applicable					Ldg	90				
	(ISSUING AUTHORITY: EASA)										
26-11-00-7200		Optional Baggage Compartment and Lavatory Smoke Detection System Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	26 A/F	5-12-06				Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
					Hrs						
	(ZONE: 235, 311) (SOURCE: 560 XL MM Section 5-10-02)				Ldg						
26-20-00-2200		Left Engine Fire Deployment Check Tee Special Detailed Inspection						RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	26 A/F					Mos					
					Hrs						
	(ZONE: 321) (SOURCE: 560 XL MM Section 5-10-02)				Ldg						
	Note: NOTE: Anytime bottle 1 or 2 of the associated Engine Fire Extinguishing System is fired										
26-20-00-2200		Right Engine Fire Deployment Check Tee Special Detailed Inspection						RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	26 A/F					Mos					
					Hrs						
	(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02)				Ldg						
	Note: NOTE: Anytime bottle 1 or 2 of the associated Engine Fire Extinguishing System is fired										
26-21-00-2200		Engine Fire Extinguisher Wiring Detailed Inspection						RE		04-10-01	
	26 A/F	4-12-MV				Mos		24		(31-May-2026)	1.6 Years
					Hrs						
	(ZONE: 311, 312) (SOURCE: 560 XL MM)				Ldg						
26-21-00-7100		Left Engine Fire Extinguishing System Functional Check						RE	05-10-01, 05-10-02, Category 8, Category 9		
	26 A/F	5-12-06				Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
					Hrs						
	MRBR Task:26-20-00-701, MRBR Task:26-20-00-702, MRBR Task:26-20-00-703, MRBR Task:26-20-00-704, MRBR Task:26-20-00-706, MRBR Task:26-20-00-709 (ZONE: 313, 235, 321) (SOURCE: 560XL MM)				Ldg						

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
26-21-00-7100		Right Engine Fire Extinguishing System Functional Check									
	26 A/F	5-12-06				Mos		48	-/+1m	05-10-01, 05-10-02, Category 8, Category 9 (30-Jun-2026)	1.7 Years (+30 Days)
		MRBR Task:26-20-00-701, MRBR Task:26-20-00-702, MRBR Task:26-20-00-703, MRBR Task:26-20-00-704, MRBR Task:26-20-00-706, MRBR Task:26-20-00-709 (ZONE: 314, 235, 322) (SOURCE: 560XL MM)				Hrs					
						Ldg					
26-21-01-7100		Engine Fire Extinguisher Aft Bottle Low Pressure Switch Operational Check									
	26 A/F					Mos	13-May-2022	60		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS 31-May-2027	2.6 Years
		Hydrostatic Tested Date 13-May-2022				Hrs					
		MRBR Task:26-20-00-711 (ZONE: 312) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00)				Ldg					
		Note: NOTE: This task is accomplished during the Hydrostatic check. Per Supplier Recommendation. Reference Pacific Scientific 26-20-202 Component Maintenance Manual.									
26-21-01-7100		Engine Fire Extinguisher Fwd Bottle Low Pressure Switch Operational Check									
	26 A/F					Mos	13-May-2022	60		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS 31-May-2027	2.6 Years
		Hydrostatic Tested Date 13-May-2022				Hrs					
		MRBR Task:26-20-00-711 (ZONE: 235) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00)				Ldg					
		Note: NOTE: This task is accomplished during the Hydrostatic check. Per Supplier Recommendation. Reference Pacific Scientific 26-20-202 Component Maintenance Manual.									
26-21-01-7200		Optional Aft Vanity Fire Extinguisher Bottle (Weight Check) Functional Check (Airplanes - 6224 and On)									
	26 A/F					Mos		60		Regulatory Inspections/Time Limits 30-Jun-2027	2.7 Years
		Unknown				Hrs					
		Unknown				Ldg					
		(SOURCE: 560 XL MM Section 5-13-00, 5-18-00)									
26-21-01-7800		Engine Fire Extinguisher Bottle (Hydrostatic Test) Restoration									
	26 A/F	Aft				Mos	13-May-2022	60		Regulatory Inspections/Time Limits 31-May-2027	2.6 Years
		30400037-1				Hrs					
		84951B1				Ldg					
		Hydrostatic Tested Date 13-May-2022									
		(SOURCE: 560 XL MM Section 5-13-00)									
		Note: Regulation : US DOT CFR 49 Part 180.209 Requirements for Re-qualification of Specification Cylinders. NOTE: The fire extinguisher bottle is manufactured under U.S. DOT-SP-7945									
26-21-01-7800		Engine Fire Extinguisher Bottle (Hydrostatic Test) Restoration									
	26 A/F	Fwd				Mos	13-May-2022	60		Regulatory Inspections/Time Limits 31-May-2027	2.6 Years
		30400037-1				Hrs					
		84950B1				Ldg					
		Hydrostatic Tested Date 13-May-2022									
		(SOURCE: 560 XL MM Section 5-13-00)									
		Note: Regulation : US DOT CFR 49 Part 180.209 Requirements for Re-qualification of Specification Cylinders. NOTE: The fire extinguisher bottle is manufactured under U.S. DOT-SP-7945									
26-21-01-9600		13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)									
	26 A/F	Aft - No.1				Mos	13-May-2022	72		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS 31-May-2028	3.6 Years
		13083-5				Hrs					
		NSN				Ldg					
		(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									
		Note: NOTE: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months Tracked by Component Installation Date. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual									

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
26-21-01-9600	13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 26 A/F	Aft - No.2				Mos	13-May-2022	72	31-May-2028	3.6 Years	
13083-5					Hrs					
NSN					Ldg					
(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
Note: NOTE: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months Tracked by Component Installation Date. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual										
26-21-01-9600	13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 26 A/F	Fwd - No.1				Mos	13-May-2022	72	31-May-2028	3.6 Years	
13083-5					Hrs					
NSN					Ldg					
(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
Note: NOTE: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months Tracked by Component Installation Date. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual										
26-21-01-9600	13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 26 A/F	Fwd - No.2				Mos	13-May-2022	72	31-May-2028	3.6 Years	
13083-5					Hrs					
NSN					Ldg					
(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
Note: NOTE: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months Tracked by Component Installation Date. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual										
26-21-01-9601	13083-5 Auxiliary Power Unit Fire Extinguisher Cartridge Squib Discard (In Service Limitation)						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 26 A/F					Mos	14-May-2022	72	31-May-2028	3.6 Years	
13083-5					Hrs					
NSN					Ldg					
(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
Note: NOTE: Per Supplier Recommendation. The Service Life of the cartridge is 72 Months Tracked by Component Installation Date. The Total Life of the cartridge including shelf life is 108 Months. Reference Manual 26-20-202 Pacific Scientific Component Maintenance Manual										
26-21-01-9602	AE 13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)						RE (N/A)	05-10-01, 05-10-02, Category 8		
 26 A/F	Aft - No.1				Mos					
13083-5					Hrs					
NSN					Ldg					
MRBR Task:25-20-00-903 (ZONE: 322) (SOURCE: 560XL MM)										
26-21-01-9602	AE 13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)						RE (N/A)	05-10-01, 05-10-02, Category 8		
 26 A/F	Aft - No.2				Mos					
13083-5					Hrs					
NSN					Ldg					
MRBR Task:25-20-00-903 (ZONE: 322) (SOURCE: 560XL MM)										
26-21-01-9602	AE 13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)						RE (N/A)	05-10-01, 05-10-02, Category 8		
 26 A/F	Fwd - No.1				Mos					
13083-5					Hrs					
NSN					Ldg					
MRBR Task:25-20-00-903 (ZONE: 322) (SOURCE: 560XL MM)										
26-21-01-9602	AE 13083-5 Engine Fire Extinguisher Cartridge Squib Discard (In Service Limitation)						RE (N/A)	05-10-01, 05-10-02, Category 8		
 26 A/F	Fwd - No.2				Mos					
13083-5					Hrs					
NSN					Ldg					
MRBR Task:25-20-00-903 (ZONE: 322) (SOURCE: 560XL MM)										

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
26-21-01-9603	AE 13083-5 Auxiliary Power Unit Fire Extinguisher Cartridge Squib Discard (In Service Limitation)						RE (N/A)	05-10-01, 05-10-02, Category 8		
 26 A/F						Mos				
13083-5						Hrs				
NSN						Ldg				
MRBR Task:25-20-00-904 (ZONE: 322) (SOURCE: 560XL MM)										
26-22-00-2200	Portable Fire Extinguisher Detailed and (Weight) Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 26 A/F	Cabin					Mos	22-May-2024	12	31-May-2025	7.6 Months
P3APP003010D						Hrs	1020:11			
042276						Ldg	698			
(ZONE: 242) (SOURCE: 560 XL MM Section 5-10-02, 5-13-00)										
Note: NOTE: Per Supplier Recommendation and/or Local Regulatory Requirement. Reference NFPA 10										
26-22-00-2200	Portable Fire Extinguisher Detailed and (Weight) Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 26 A/F	Cockpit					Mos	22-May-2024	12	31-May-2025	7.6 Months
P3APP003010D						Hrs	1020:11			
041518						Ldg	698			
(ZONE: 262) (SOURCE: 560 XL MM Section 5-10-02, 5-13-00)										
Note: NOTE: Per Supplier Recommendation and/or Local Regulatory Requirement. Reference NFPA 10										
26-22-00-2201	Portable Fire Extinguisher Restoration (Internal Inspection)						RE	Regulatory Inspections/Time Limits		
 26 A/F	Cabin					Mos	24-May-2022	72	31-May-2028	3.6 Years
P3APP003010D						Hrs				
042276						Ldg				
(SOURCE: 560 XL MM Section 5-13-00)										
Note: National Fire Protection Agency										
NFPA 10: Standard for Portable										
Fire Extinguishers										
26-22-00-2201	Portable Fire Extinguisher Restoration (Internal Inspection)						RE	Regulatory Inspections/Time Limits		
 26 A/F	Cockpit					Mos	24-May-2022	72	31-May-2028	3.6 Years
P3APP003010D						Hrs				
041518						Ldg				
(SOURCE: 560 XL MM Section 5-13-00)										
Note: National Fire Protection Agency NFPA 10: Standard for Portable Fire Extinguishers										
26-22-00-7800	Portable Fire Extinguisher (Hydrostatic Test) Functional Check						RE	Regulatory Inspections/Time Limits		
 26 A/F	Cabin					Mos	24-May-2022	144	31-May-2034	9.6 Years
P3APP003010D						Hrs				
042276						Ldg				
Hydrostatic Tested Date 24-May-2022										
(SOURCE: 560 XL MM Section 5-13-00)										
Note: Regulation: National Fire Protection Agency										
NFPA 10: Standard for Portable										
Fire Extinguishers										
26-22-00-7800	Portable Fire Extinguisher (Hydrostatic Test) Functional Check						RE	Regulatory Inspections/Time Limits		
 26 A/F	Cockpit					Mos	24-May-2022	144	31-May-2034	9.6 Years
P3APP003010D						Hrs				
041518						Ldg				
Hydrostatic Tested Date 24-May-2022										
(SOURCE: 560 XL MM Section 5-13-00)										
Note: Regulation: National Fire Protection Agency										
NFPA 10: Standard for Portable										
Fire Extinguishers										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
26-23-00-2200	Auxiliary Power Unit Fire Extinguisher Wiring Detailed Inspection (If APU installed)						RE		04-10-01	
 26 A/F	4-12-MV					Mos	24		(31-May-2026)	1.6 Years
						Hrs				
	(ZONE: 312) (SOURCE: 560 XL MM)					Ldg				
26-23-00-7100	Auxiliary Power Unit Fire Extinguishing System Operational and Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 26 A/F	5-12-06					Mos	48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
						Hrs				
	(ZONE: 235, 313) (SOURCE: 560 XL MM Section 5-10-02)					Ldg				
26-23-00-7101	Auxiliary Power Unit Fire Extinguisher Bottle Low Pressure Switch Operational Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 26 A/F						Mos	14-May-2022	60	31-Oct-2026	2 Years
	Hydrostatic Tested Date 01-Oct-2021					Hrs				
	(ZONE: 312) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)					Ldg				
	Note: NOTE: This task is accomplished during the Hydrostatic check. Per Supplier Recommendation. Reference Pacific Scientific 26-22-202 Component Maintenance Manual.									
26-23-00-7800	APU Fire Extinguisher Bottle (Hydrostatic Test) Restoration						RE	Regulatory Inspections/Time Limits		
 26 A/F						Mos	14-May-2022	60	31-Oct-2026	2 Years
	30100033-7					Hrs				
	99333A1					Ldg				
	Hydrostatic Tested Date 01-Oct-2021									
	(SOURCE: 560 XL MM Section 5-13-00)									
	Note: Regulation : US DOT CFR 49 Part 180.209 Requirements for Re-qualification of Specification Cylinders. NOTE: The fire extinguisher bottle is manufactured under U.S. DOT-SP-7945									
560XL-26-03	Engine Fire Bottle Arm Annunciation Modification						RE (-)		Mandatory	
 26 A/F						Mos	22-Jun-2022			
	Eff: 28-May-2009 Not Applicable					Hrs	8			
	by S/N					Ldg	6			
CIL-26-01	Fire Protection - Fire Extinguisher Bottle Cartridge Ground Stud Torquing						RE (-)		Mandatory	
 26 A/F						Mos	22-Jun-2022			
	Eff: 10-May-2016 Not Applicable					Hrs	8			
	(AVG MAN HRS: 0.5)					Ldg	6			
CIL-26-01 R1	Fire Protection - Fire Extinguisher Bottle Cartridge Ground Stud Torquing						RE (-)		Mandatory	
 26 A/F						Mos	22-Jun-2022			
	Eff: 10-May-2016 Not Applicable					Hrs	8			
	(AVG MAN HRS: 0.5)					Ldg	6			
SB560XL-26-04	Fire Protection - Replacement of the Halon Type 1211 Portable Fire Extinguishers						T (A/R)		Optional	
 26 A/F						Mos				
	Eff: 26-May-2022					Hrs				
						Ldg				
SL560XL-26-02	Fire Protection - Fire Bottle Wire Verification and Test						RE (-)		Mandatory	
 26 A/F						Mos	22-Jun-2022			
	Eff: 08-Jul-2021 Not Applicable					Hrs	8			
	(AVG MAN HRS: 3)					Ldg	6			
SL560XL-26-02 R1	Fire Protection - Fire Bottle Wire Verification and Test						RE (-)		Mandatory	
 26 A/F						Mos	19-Aug-2024			
	Eff: 31-Jul-2024 Not Applicable					Hrs				
	(AVG MAN HRS: 3)					Ldg				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
▼ 27 - FLIGHT CONTROLS											
		Actuator Aileron Trim Tab								RE (O/C)	
27 A/F	Unknown						Mos	22-Jun-2022			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
		Aft Elevator Trim Cable Assembly								RE (O/C)	
27 A/F	Unknown						Mos	22-Jun-2022			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
		Aileron Assembly								RE (O/C)	
27 A/F	6624031-4	Left					Mos	22-Jun-2022			
	31430392						Hrs	0			
							Ldg	0			
		Aileron Assembly								RE (O/C)	
27 A/F	6624032-4	Right					Mos	22-Jun-2022			
	31358682						Hrs	0			
	(ZONE: r)						Ldg	0			
		Airspeed Switch								RE (O/C)	
27 A/F	Unknown						Mos	22-Jun-2022			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
		Elev Trim Switch								RE (O/C)	
27 A/F	Unknown						Mos	22-Jun-2022			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
		Elevator Assembly								RE (O/C)	
27 A/F	6634200-13	Left					Mos	22-Jun-2022			
	31200621						Hrs	0			
							Ldg	0			
		Elevator Assembly								RE (O/C)	
27 A/F	6634200-14	Right					Mos	22-Jun-2022			
	31211576						Hrs	0			
							Ldg	0			
		Elevator Electric Trim Actuator								RE (O/C)	
27 A/F	Unknown						Mos	22-Jun-2022			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
		Elevator Trim Actuator								RE (O/C)	
27 A/F	Unknown	Left					Mos	22-Jun-2022			
	Unknown						Hrs	0			
	Unknown						Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	27 A/F Unknown Unknown	Elevator Trim Actuator Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	27 A/F 1535000-3 3952	Flap Actuator Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	27 A/F 1535000-3 3972	Flap Actuator Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	27 A/F 9912625-5 0273	Flap Control (Uy024) Valve Overhauled					Mos	10-May-2023		RE (O/C)	
				0			Hrs	441:12			
				0			Ldg	301			
	27 A/F 4218-1 0672	Horizontal Stab Valve Assy					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	27 A/F 41016450-101 1409D	Horizontal Stabilizer Actuator					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	27 A/F 4220-1 0672	Horizontal Stabilizer Isolation (Uy015) Valve					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	27 A/F 8244-2 0663	Hydraulic Manifold Assembly					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	27 A/F 6633000-31 31607646	Rudder Assembly					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	27 A/F Unknown Unknown	Rudder Bias Actuator					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	27 A/F 5307-1 2226C	Rudder Bias Shutoff Valve					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Rudder Trim Tab Actuator								RE (O/C)	
	27 A/F	Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Servo Actuator								RE (O/C)	
	27 A/F	Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Speed Brake Actuator								RE (O/C)	
	27 A/F	Left 1535500-1 4306					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Speed Brake Actuator								RE (O/C)	
	27 A/F	Right 1535500-1 4325					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Speed Brake Control Valve								RE (O/C)	
	27 A/F	4216-2 0677					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Speed Brake Safety Valve								RE (O/C)	
	27 A/F	4217-1 0678					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Stick Shaker (MC001) Unit								RE (O/C)	
	27 A/F	201 188969-15					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Stick Shaker (MF004) Unit								RE (O/C)	
	27 A/F	201 1888969-17					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Throttle Quadrant Assembly								RE (O/C)	
	27 A/F	6665260-4 ICE-00150					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
12-20-27-6401		Trim Actuators Lubrication								RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS
	27 A/F	5-12-01 (ZONE: 340, 351, 352, 532) (SOURCE: 560 XL MM Section 5-10-02) Note: NOTE: It is recommended to do this task at the same time as Tasks 27-10-00-2202 and 27-20-00-2201.					Mos	22-May-2024	12	-/+1m (31-May-2025)	7.6 Months (+30 Days)
							Hrs	1020:11			
							Ldg	698			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
12-20-27-6403	Horizontal Stabilizer Scissor Fitting Bolts and Aft Pivot Bolts Lubrication									
 27 A/F	5-12-03				Mos	22-May-2024	24	-/+1m	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	1.6 Years (+30 Days)
	(ZONE: 340) (SOURCE: 560 XL MM Section 5-10-02)				Hrs	1020:11				
					Ldg	698				
2000-15-51	Aileron Cable Fairlead Tube and Aileron Cable Sector									
 27 A/F					Mos	22-Jun-2022			RE (-)	Mandatory
	Eff: 14-Aug-2000 Complied With				Hrs	8				
	(ISSUING AUTHORITY: FAA)				Ldg	6				
2000-15-51 Paragraph (a)	Aileron Cable Fairlead Tube - Pre-modification Inspection									
 27 A/F					Mos	22-Jun-2022			RE (-)	Mandatory
	Eff: 14-Aug-2000 Complied With				Hrs	8				
	(ISSUING AUTHORITY: FAA)				Ldg	6				
2000-15-51 Paragraph (b)	Aileron Cable Fairlead Tube - Modification									
 27 A/F					Mos	22-Jun-2022			RE (-)	Mandatory
	Eff: 14-Aug-2000 Complied With				Hrs	8				
	(ISSUING AUTHORITY: FAA)				Ldg	6				
2000-15-51 Paragraph (c)	Aileron Cable Fairlead Tube - Post-modification Inspection									
 27 A/F					Mos	22-Jun-2022			RE (-)	Mandatory
	Eff: 14-Aug-2000 Complied With				Hrs	8				
	N/A as per documents from delivery of new A/C				Ldg	6				
	(ISSUING AUTHORITY: FAA)									
27-10-00-2201	Aileron Left Wing Cable Detailed Inspection (Airplanes -5556 and On, and Airplanes -5002 thru - 5555 Incorporating SB560XL-27-22)									
 27 A/F	5-12-08				Mos				RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS
	(ZONE: 313, 314, 512, 522, 532) (SOURCE: 560 XL MM Section 5-10-02)				Hrs		2,400	-/+25	(2400)	1040:04 Hrs (+25)
	Note: NOTE: It is recommended you do this task at the same time as Task 27-10-00-2203				Ldg					
27-10-00-2201	Aileron Right Wing Cable Detailed Inspection (Airplanes -5556 and On, and Airplanes -5002 thru - 5555 Incorporating SB560XL-27-22)									
 27 A/F	5-12-08				Mos				RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS
	(ZONE: 612, 622, 632) (SOURCE: 560 XL MM Section 5-10-02)				Hrs		2,400	-/+25	(2400)	1040:04 Hrs (+25)
	Note: NOTE: It is recommended you do this task at the same time as Task 27-10-00-2203				Ldg					
27-10-00-2202	Aileron Trim Actuator Detailed Inspection									
 27 A/F	5-12-01				Mos	22-May-2024	12	-/+1m	05-10-01, 05-10-02, Category 6	7.6 Months (+30 Days)
	Unknown				Hrs	1020:11				
	Unknown				Ldg	698				
	MRBR Task:27-10-00-208 (ZONE: 532) (SOURCE: 560XL MM)									
	Note: NOTE: It is recommended to do this task at the same time as Tasks 12-20-27-6401 and 27-20-00-2201.									
27-10-00-2203	Aileron and Aileron Trim Detailed Inspection and Functional Check									
 27 A/F	5-12-08				Mos				RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS
	(ZONE: 141,153,163,165,236,241,242,313,512,522,532,534) (SOURCE: 560 XL MM Section 5-10-02)				Hrs		2,400	-/+25	(2400)	1040:04 Hrs (+25)
	Note: NOTE: It is recommended you do this task at the same time as Task 27-10-00-2201				Ldg					
27-10-00-7201	Aileron Trim Tab and Pushrod (Free Play) Functional Check									
 27 A/F	5-12-07				Mos				RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS
	(ZONE: 532) (SOURCE: 560 XL MM Section 5-10-02)				Hrs		1,600	-/+25	(1600)	240:04 Hrs (+25)
	KGR-WP-011 START 21-JAN-2025				Ldg					

Task No		Description							Categories		Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
27-20-00-2200		Rudder Bias Cable Assembly Detailed Inspection (Airplanes - 5001, -5044, -5052, -5085, -5088 and On. And Airplanes -5002 thru -5043, -5045 thru -5051, -5053 thru -5084 and -5086 thru -5087 Incorporating SB560XL-27-06)						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Mar-2026
	27 A/F	5-12-08					Mos				
(ZONE: 340) (SOURCE: 560 XL MM Section 5-10-02)							Hrs	2,400	-/+25	(2400)	1040:04 Hrs (+25)
							Ldg				
27-20-00-2201		Rudder Trim Actuator Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	27 A/F	5-12-01					Mos	22-May-2024	12	-/+1m (31-May-2025)	7.6 Months (+30 Days)
Unknown							Hrs	1020:11			
Unknown							Ldg	698			
(ZONE: 340) (SOURCE: 560 XL MM Section 5-10-02)											
Note: NOTE: It is recommended to do this task at the same time as Tasks 12-20-27-6401 and 27-10-00-2202											
27-20-00-2202		Rudder and Rudder Trim Detailed Inspection and Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Mar-2026
	27 A/F	5-12-08					Mos				
(ZONE: 241, 242, 251, 252, 263, 264, 321, 322, 340, 341) (SOURCE: 560 XL MM Section 5-10-02)							Hrs	2,400	-/+25	(2400)	1040:04 Hrs (+25)
							Ldg				
27-20-00-7201		Rudder Trim Actuator and Pushrod (Free Play) Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈12-Feb-2025
	27 A/F	5-12-07					Mos				
(ZONE: 340) (SOURCE: 560 XL MM Section 5-10-02)							Hrs	1,600	-/+25	(1600)	240:04 Hrs (+25)
KGR-WP-011 START 21-JAN-2025							Ldg				
27-31-00-2200		Elevator and Trim Tab System Detailed Inspection						RE	05-10-01, 05-10-02, Category 5, Category 6		
	27 A/F	5-12-06					Mos	48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
MRBR Task:27-30-00-212, MRBR Task:27-30-00-211, MRBR Task:27-30-00-208, MRBR Task:27-30-00-205, MRBR Task:27-30-00-204 (ZONE: 241, 242, 141, 353, 354, 142, 340) (SOURCE: 560XL MM)							Hrs				
Note: NOTE: It is recommended you do this task at the same time as Tasks 53-30-00-2200 and 55-20-00-2200							Ldg				
27-31-00-2201		Elevator and Elevator Trim Detailed Inspection and Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Mar-2026
	27 A/F	5-12-08					Mos				
(ZONE: 340,322,141,151,163,165,313,321,236,161,171,311) (SOURCE: 560 XL MM Section 5-10-02)							Hrs	2,400	-/+25	(2400)	1040:04 Hrs (+25)
							Ldg				
27-31-00-7201		Elevator Trim Tab and Pushrod (Free Play) Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈12-Feb-2025
	27 A/F	5-12-07					Mos				
(ZONE: 353, 354) (SOURCE: 560 XL MM Section 5-10-02)							Hrs	1,600	-/+25	(1600)	240:04 Hrs (+25)
KGR-WP-011 START 21-JAN-2025							Ldg				
27-40-00-7200		Two-Position Horizontal Stabilizer Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Mar-2026
	27 A/F	5-12-08					Mos				
(ZONE: 252, 340) (SOURCE: 560 XL MM Section 5-10-02)							Hrs	2,400	-/+25	(2400)	1040:04 Hrs (+25)
							Ldg				
27-51-00-2200		Flap Cables Detailed Inspection and Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Mar-2026
	27 A/F	5-12-08					Mos				
(ZONE: 514, 614, 241) (SOURCE: 560 XL MM Section 5-10-02)							Hrs	2,400	-/+25	(2400)	1040:04 Hrs (+25)
							Ldg				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE		Remaining
27-71-00-7100		Control (Gust) Lock System Operational Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	27 A/F	5-12-01				Mos	22-May-2024	12	-/+1m	(31-May-2025)		7.6 Months (+30 Days)
		(ZONE: 141, 235) (SOURCE: 560 XL MM Section 5-10-02)				Hrs	1020:11					
						Ldg	698					
560XL-27-32		Rudder Pedal Position Modification						RE (-)			Optional	
	27 A/F					Mos						
						Hrs						
						Ldg						
560XL-27-32 Rev 01		Rudder Pedal Position Modification						RE (-)			Optional	
	27 A/F					Mos						
						Hrs						
						Ldg						
560XL-27-32 Rev 02		Rudder Pedal Position Modification						RE (-)			Recommended	
	27 A/F					Mos	22-Jun-2022					
	Eff: 10-May-2011 Not Applicable	effective before manufacture				Hrs	8					
						Ldg	6					
560XL-27-35		Flight Controls - Stainless Steel Hydraulic Tube Replacement						RE (-)			Optional	
	27 A/F					Mos						
						Hrs						
						Ldg						
560XL-27-35 Rev 01		Flight Controls - Stainless Steel Hydraulic Tube Replacement						RE (-)			Optional	
	27 A/F					Mos						
	Eff: 11-Nov-2014					Hrs						
						Ldg						
57-50-00-2200		Left Speed Brake Panels and Attachment Fittings Detailed Inspection						REMSG-3 Structures Inspection Tasks				
	27 A/F	5-12-06				Mos		48	-/+1m	(30-Jun-2026)		1.7 Years (+30 Days)
		(ZONE: 522) (SOURCE: 560 XL MM Section 5-10-03)				Hrs						
						Ldg						
57-50-00-2200		Right Speed Brake Panels and Attachment Fittings Detailed Inspection						REMSG-3 Structures Inspection Tasks				
	27 A/F	5-12-06				Mos		48	-/+1m	(30-Jun-2026)		1.7 Years (+30 Days)
		(ZONE: 622) (SOURCE: 560 XL MM Section 5-10-03)				Hrs						
						Ldg						
SL560XL-27-05		Cable Fairlead Replacement						RE (-)			Recommended	
	27 A/F					Mos	22-Jun-2022					
	Not Applicable	by aircraft S/N				Hrs	8					
						Ldg	6					
SL560XL-27-05 Rev 01		Cable Fairlead Replacement						RE (-)			Recommended	
	27 A/F					Mos	22-Jun-2022					
	Not Applicable	by aircraft S/N				Hrs	8					
						Ldg	6					
SL560XL-27-05 Rev 02		Cable Fairlead Replacement						RE (-)			Mandatory	
	27 A/F					Mos	22-Jun-2022					
	Eff: 05-Feb-2014 Not Applicable	by aircraft S/N				Hrs	8					
						Ldg	6					
SL560XL-27-14		Horizontal and Vertical Stabilizer Erosion Boot Installation						T (A/R)			Optional	
	27 A/F					Mos						
	Eff: 30-Mar-2006					Hrs						
						Ldg						

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-27-18	Elevator Trim Cable Replacement Intervals						T (A/R)		Informational	
 27 A/F						Mos				
Eff: 21-Feb-2012						Hrs				
						Ldg				
SL560XL-27-20	Rudder Torque Tube/Sector Assembly Gap Inspection						RE (-)		Recommended	
 27 A/F						Mos	22-Jun-2022			
Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			
SL560XL-27-20 Rev 01	Rudder Torque Tube/Sector Assembly Gap Inspection						RE (-)		Recommended	
 27 A/F						Mos	22-Jun-2022			
Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			
SL560XL-27-20 Rev 02	Rudder Torque Tube/Sector Assembly Gap Inspection						RE (-)		Mandatory	
 27 A/F						Mos	22-Jun-2022			
Eff: 18-Jan-2014 Not	by aircraft S/N					Hrs	8			
Applicable						Ldg	6			
SL560XL-27-21	Rudder Torque Tube/Sector Assembly Inspection						RE (-)		Mandatory	
 27 A/F						Mos	22-Jun-2022			
Eff: 18-Jan-2014 Not	by aircraft S/N					Hrs	8			
Applicable						Ldg	6			
SL560XL-27-33	Flight Controls - Elevator Cable Inspection at the Aft Canted Bulkhead						RE (-)		Mandatory	
 27 A/F						Mos	22-Jun-2022			
Eff: 05-Nov-2014 Not	by aircraft S/N					Hrs	8			
Applicable						Ldg	6			
SL560XL-27-34	Flight Controls - Right Outboard Aileron Wing Up Cable Assembly Inspection						RE (-)		Recommended	
 27 A/F						Mos	22-Jun-2022			
Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			
SL560XL-27-34 Rev 01	Flight Controls - Right Outboard Aileron Wing Up Cable Assembly Inspection						RE (-)		Mandatory	
 27 A/F						Mos	22-Jun-2022			
Eff: 22-Jan-2015 Not	by aircraft S/N					Hrs	8			
Applicable						Ldg	6			
SL560XL-27-34 Rev 02	Flight Controls - Right Outboard Aileron Wing Up Cable Assembly Inspection						RE (-)		Mandatory	
 27 A/F						Mos	22-Jun-2022			
Eff: 12-Jun-2019 Not	by aircraft S/N					Hrs	8			
Applicable						Ldg	6			
(AVG MAN HRS: 3.2)										
SL560XL-27-35	Flight Controls - AFT Aileron Sector Assembly Inspection						RE (-)		Mandatory	
 27 A/F						Mos	22-Jun-2022			
Eff: 16-Nov-2015 Not	by aircraft S/N					Hrs	8			
Applicable						Ldg	6			
(AVG MAN HRS: 1)										
SL560XL-27-36	Flight Controls - Horizontal Stabilizer Actuator Bolt Inspection						RE (-)		Mandatory	
 27 A/F						Mos	22-Jun-2022			
Eff: 26-Aug-2015 Not	by aircraft S/N					Hrs	8			
Applicable						Ldg	6			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-27-37	Flight Controls - Rudder Position Sensor Wire Routing Improvement						RE (-)		Mandatory	
 27 A/F						Mos	22-Jun-2022			
Eff: 13-Jan-2016 Not Applicable	by aircraft S/N					Hrs	8			
(AVG MAN HRS: 1.5)						Ldg	6			
SL560XL-27-37 Rev 01	Flight Controls - Rudder Position Sensor Wire Routing Improvement						RE (-)		Mandatory	
 27 A/F						Mos	22-Jun-2022			
Eff: 25-Mar-2016 Not Applicable	by aircraft S/N					Hrs	8			
(AVG MAN HRS: 1.5)						Ldg	6			
SL560XL-27-37 Rev 02	Flight Controls - Rudder Position Sensor Wire Routing Improvement						RE (-)		Mandatory	
 27 A/F						Mos	22-Jun-2022			
Eff: 21-Jul-2016 Not Applicable	by aircraft S/N					Hrs	8			
(AVG MAN HRS: 1.5)						Ldg	6			
SL560XL-27-38	Flight Controls - Inspection of the Horizontal Stabilizer Upper Scissor Link Fitting						RE (-)		Recommended	
 27 A/F						Mos	13-Sep-2023			
Eff: 05-Oct-2022 Not Applicable	as per A/C S/N					Hrs	699:29			
						Ldg	460			
SL560XL-27-39	Flight Controls - Control Lock Cable Assembly Swivel Seal Inspection						T (A/R)		Recommended	
 27 A/F						Mos			[12-Nov-2024]	28 Days
Eff: 03-Sep-2024						Hrs				
(AVG MAN HRS: 7.5)						Ldg				
 KGR-WP-010 START 11-NOV-2024										
▼ 28 - FUEL										
	Boost Fuel Electric Pump						RE (O/C)			
 28 A/F	Left					Mos	22-Jun-2022			
LR55540B						Hrs	0			
B2205						Ldg	0			
	Boost Fuel Electric Pump						RE (O/C)			
 28 A/F	Right					Mos	22-Jun-2022			
LR55540B						Hrs	0			
B2201						Ldg	0			
	Fuel Boost Cartridge						RE (O/C)			
 28 A/F	Left					Mos	22-Jun-2022			
LR55505-2						Hrs	0			
E-330						Ldg	0			
	Fuel Boost Cartridge						RE (O/C)			
 28 A/F	Right					Mos	22-Jun-2022			
LR55505-2						Hrs	0			
E-329						Ldg	0			
	Fuel Crossfeed Actuator						RE (O/C)			
 28 A/F						Mos	12-Jul-2022			
9914423-2	New	0				Hrs	20:05			
AA754978		0				Ldg	10			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	28 A/F 125838AW AA791107	Fuel Crossfeed Valve						RE (O/C)			
						Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
	28 A/F 10634T07Y00 MN53698	Fuel Qty W0 Probe						RE (O/C)			
		Left				Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
	28 A/F 10634T07Y00 MN53117	Fuel Qty W0 Probe						RE (O/C)			
		Right				Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
	28 A/F 10634T02Y00 MN53687	Fuel Qty W1 Probe						RE (O/C)			
		Left				Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
	28 A/F 10634T02Y00 MN53609	Fuel Qty W1 Probe						RE (O/C)			
		Right				Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
	28 A/F 10634T03Y00 MN53688	Fuel Qty W2 Probe						RE (O/C)			
		Left				Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
	28 A/F 10634T03Y00 MN52722	Fuel Qty W2 Probe						RE (O/C)			
		Right				Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
	28 A/F 10634T04Y00 MN52939	Fuel Qty W3 Probe						RE (O/C)			
		Left				Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
	28 A/F 10634T04Y00 MN53109	Fuel Qty W3 Probe						RE (O/C)			
		Right				Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
	28 A/F 10634T05Y00 MN53334	Fuel Qty W4 Probe						RE (O/C)			
		Left				Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
	28 A/F 10634T05Y00 MN53333	Fuel Qty W4 Probe						RE (O/C)			
		Right				Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
✖	28 A/F 10634T01Y00 MN53098	Fuel Qty W5 Probe Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	28 A/F 10634T01Y00 MN53095	Fuel Qty W5 Probe Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	28 A/F 10634T06Y00 MN53339	Fuel Qty W6 Probe Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	28 A/F 10634T06Y00 MN53043	Fuel Qty W6 Probe Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	28 A/F 10635B03Y04 2111862	Fuel Quantity Signal Conditioner					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	28 A/F 840203-105 3081	Fuel Relief Valve Assy Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	28 A/F 840203-105 3107	Fuel Relief Valve Assy Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	28 A/F 71498 2502A	Fuel Shut-Off Valve Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	28 A/F 71498 2474A	Fuel Shut-Off Valve Right					Mos			RE (O/C)	
							Hrs				
							Ldg				
✖	28 A/F Unknown Unknown	Fuel Temperature (EI014) Indicator					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	28 A/F 750800-2 3697	Fuel Valve Assy Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	28 A/F 750800-2 3667	Fuel Valve Assy Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	28 A/F 60221-4 3734	Fuel Vent Float Valve Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	28 A/F 60221-4 3741	Fuel Vent Float Valve Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	28 A/F 61087 8113	High Level Fuel Valve Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	28 A/F 61087 8111	High Level Fuel Valve Right					Mos			RE (O/C)	
							Hrs				
							Ldg				
	28 A/F L16H-15 1558	Low Fuel Level Sensor Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	28 A/F L16H-15 1545	Low Fuel Level Sensor Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	28 A/F 726400-1 3188	Low Level Valve Assy Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	28 A/F 726400-1 3186	Low Level Valve Assy Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	28 A/F 4151 2171	Motive Flow Shutoff (UY008) Valve					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	28 A/F 4151 2176	Motive Flow Shutoff (UY009) Valve					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	28 A/F 2950023-101 2139	Primary Motive Flow Ejector Pump Left						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	28 A/F 2950023-101 2155	Primary Motive Flow Ejector Pump Right						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	28 A/F 2950024-101 6313	Scavenge Fuel Ejector Pump Aft - Left						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	28 A/F 2950024-101 6312	Scavenge Fuel Ejector Pump Aft - Right						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	28 A/F 2950024-101 6315	Scavenge Fuel Ejector Pump Fwd - Left						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	28 A/F 2950024-101 6310	Scavenge Fuel Ejector Pump Fwd - Right						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	28 A/F 2950024-101 6314	Scavenge Fuel Ejector Pump Mid - Left						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	28 A/F 2950024-101 6311	Scavenge Fuel Ejector Pump Mid - Right						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	28 A/F 80002-101 2849	Single Point Refuel/Defuel Shutoff Valve Left						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	28 A/F 80002-101 2851	Single Point Refuel/Defuel Shutoff Valve Right						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	28 A/F 9036-351-2 2785	Valve-Refuel/Defuel						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time Remaining
SEQ	PN/SN	MOC Note or Component Condition							DUE	
	28 A/F	Wing Fuel Low Level Float Switch Left					RE (O/C)			
	Unknown						Mos	22-Jun-2022		
	Unknown						Hrs	0		
							Ldg	0		
28-00-02-2200		Microbiological Contamination Inspection (Airplanes Not Using the Biocidal Preventative Treatment)					RE		Discretionary Maintenance	
	28 A/F					Mos	24-Jul-2024	3	31-Oct-2024	16 Days
						Hrs	1180:34			
	Ref:Chapter 28, Fuel Contamination - Inspection/Check (SOURCE: 560 XL MM Section 5-19-00)					Ldg	819			
28-00-02-2201		Microbiological Contamination Inspection (Airplanes Using the Biocidal Preventative Treatment)					RE (N/A)		Discretionary Maintenance	
	28 A/F					Mos				
						Hrs				
	Ref:Chapter 28, Fuel Contamination - Inspection/Check (SOURCE: 560 XL MM Section 5-19-00)					Ldg				
28-11-04-2200		Fuel Filler Cap Detailed Inspection and Lubrication					RE		05-10-01, 05-10-02, Category 9	
	28 A/F	5-12-01				Mos	22-May-2024	12	-/+1m (31-May-2025)	7.6 Months (+30 Days)
						Hrs	1020:11			
	MRBR Task:28-10-00-201, MRBR Task:28-10-00-601 (ZONE: 531) (SOURCE: 560XL MM)					Ldg	698			
28-11-04-2200		Fuel Filler Cap Detailed Inspection and Lubrication					RE		05-10-01, 05-10-02, Category 9	
	28 A/F	5-12-01				Mos	22-May-2024	12	-/+1m (31-May-2025)	7.6 Months (+30 Days)
						Hrs	1020:11			
	MRBR Task:28-10-00-201, MRBR Task:28-10-00-601 (ZONE: 631) (SOURCE: 560XL MM)					Ldg	698			
28-42-00-7100		Fuel Low Level Float Switch Operational Check					RE		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	28 A/F	5-12-06				Mos		48	-/+1m (30-Jun-2026)	1.7 Years (+30 Days)
		(ZONE: 235) (SOURCE: 560 XL MM Section 5-10-02)				Hrs				
	Note: NOTE: It is recommended you do this task at the same time as Tasks 57-00-00-2101 and 57-00-00-2102					Ldg				
CIL-28-01		Fuel - Microbiological Contamination in Aircraft Fuel Tanks and Fuel Systems					T (A/R)		Informational	
	28 A/F					Mos				
	Eff: 24-Feb-2023					Hrs				
						Ldg				
SIL-GEN-108		Jet Fuel Containing Fatty Acid Methyl Esters (FAME)					RE (-)		Service Information Letter	
	28 ENG1					Mos				
						Hrs				
						Enc				
SIL-GEN-108		Jet Fuel Containing Fatty Acid Methyl Esters (FAME)					RE (-)		Service Information Letter	
	28 ENG2					Mos				
						Hrs				
						Enc				
SIL-GEN-108 Rev 1		Jet Fuel Containing Fatty Acid Methyl Esters (FAME)					RE (-)		Service Information Letter	
	28 ENG1					Mos				
						Hrs				
						Enc				
SIL-GEN-108 Rev 1		Jet Fuel Containing Fatty Acid Methyl Esters (FAME)					RE (-)		Service Information Letter	
	28 ENG2					Mos				
						Hrs				
						Enc				
SIL-GEN-108 Rev 2		Jet Fuel Containing Fatty Acid Methyl Esters (FAME)					T (A/R)		Service Information Letter	
	28 ENG1					Mos				
	Eff: 01-Nov-2017					Hrs				
						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-108 Rev 2		Jet Fuel Containing Fatty Acid Methyl Esters (FAME)						T (A/R)		Service Information Letter	
	28 ENG2						Mos				
	Eff: 01-Nov-2017						Hrs				
							Enc				
SL560XL-28-03		Motive Flow Shutoff Valve O-Ring Replacement						RE (-)		Recommended	
	28 A/F						Mos	22-Jun-2022			
	Eff: 15-Nov-2010 Not Applicable	effective before manufacture					Hrs	8			
							Ldg	6			
SL560XL-28-06		Fuel - Fuel Hopper Panel Protection						RE (-)		Service Letter	
	28 A/F						Mos				
	Eff: 26-Feb-2018						Hrs				
	(AVG MAN HRS: 6)						Ldg				
SL560XL-28-07		Fuel - 6621102-1 Left Web Corrosion Protection						RE (-)		Recommended	
	28 A/F						Mos	22-Jun-2022			
	Eff: 16-May-2022 Not Applicable	effective before manufacture					Hrs	8			
	(AVG MAN HRS: 8)						Ldg	6			
▼ 29 - HYDRAULIC POWER											
		Firewall Hyd Shutoff Valve						RE (O/C)			
	29 A/F	Left					Mos	22-Jun-2022			
	AV24B1325C5						Hrs	0			
	AA787514						Ldg	0			
		Firewall Hyd Shutoff Valve						RE (O/C)			
	29 A/F	Right					Mos	22-Jun-2022			
	AV24B1325C5						Hrs	0			
	AA778421						Ldg	0			
		Hydraulic Bypass Valve						RE (O/C)			
	29 A/F						Mos	22-Jun-2022			
	Unknown						Hrs	0			
	Unknown						Ldg	0			
		Hydraulic Flow Switch						RE (O/C)			
	29 A/F	Left					Mos	22-Jun-2022			
	3520020100-4						Hrs	0			
	08318						Ldg	0			
		Hydraulic Flow Switch						RE (O/C)			
	29 A/F	Right					Mos	22-Jun-2022			
	3520020100-4						Hrs	0			
	08352						Ldg	0			
		Hydraulic Pressure Switch						RE (O/C)			
	29 A/F						Mos	22-Jun-2022			
	80637						Hrs	0			
	2119						Ldg	0			
		Hydraulic Pump						RE (O/C)			
	29 A/F	Left					Mos	12-Oct-2022			
	9912062-7						Hrs	167:59			
	0575A						Ldg	115			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
Hydraulic Pump										
29 A/F	4120-045000	Right				Mos	22-Jun-2022		RE (O/C)	
	0522A					Hrs	0			
						Ldg	0			
Hydraulic Relief Valve										
29 A/F	Unknown					Mos	22-Jun-2022		RE (O/C)	
	Unknown					Hrs	0			
						Ldg	0			
Hydraulic Reservoir										
29 A/F	7470-1					Mos	22-Jun-2022		RE (O/C)	
	1247					Hrs	0			
						Ldg	0			
Hydraulic Thermal Relief Valve										
29 A/F	Unknown					Mos	22-Jun-2022		RE (O/C)	
	Unknown					Hrs	0			
						Ldg	0			
Speed Brake Thermal Relief Valve										
29 A/F	2664					Mos	22-Jun-2022		RE (O/C)	
	0669					Hrs	0			
						Ldg	0			
29-11-04-9600 Hydraulic System Filters Discard										
29 A/F	5-12-13					Mos			RE 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	(ZONE: 313) (SOURCE: 560 XL MM Section 5-10-02)					Hrs			72 -/+1m (30-Jun-2028)	3.7 Years (+30 Days)
						Ldg				
SL560XL-29-04 Hydraulic Power - Hydraulic Manifold Control Valve Wire Bundle Inspection										
29 A/F	Eff: 15-Jan-2015 Not Applicable	effective before manufacture				Mos	22-Jun-2022		RE (-)	Recommended
						Hrs	8			
						Ldg	6			
SL560XL-29-04 Rev 1 Hydraulic Power - Hydraulic Manifold Control Valve Wire Bundle Inspection										
29 A/F	Eff: 12-Jun-2019 Not Applicable	effective before manufacture				Mos	22-Jun-2022		RE (-)	Recommended
	(AVG MAN HRS: 1.5)					Hrs	8			
						Ldg	6			
SL560XL-29-05 Engine Driven Pump Hydraulic Verification										
29 A/F	Eff: 14-Jun-2017 Not Applicable	effective before manufacture				Mos	22-Jun-2022		RE (-)	Recommended, Service Letter
						Hrs	8			
						Ldg	6			
▼ 30 - ICE AND RAIN PROTECTION										
Anti-Ice Bleed Air Under Temp SI013 Switch										
30 A/F	1173T42-4	Left				Mos	22-Jun-2022		RE (O/C)	
	5907					Hrs	0			
						Ldg	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	30 A/F 1173T42-4 5908	Anti-Ice Bleed Air Under Temp Sr016 Switch Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	30 A/F 3D2353-06 N300129	Deice Tail Valve Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	30 A/F 3D2353-06 N00128	Deice Tail Valve Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	30 A/F P29S4D5280-11 167301701	Horiz Stab Deice Boot Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	30 A/F P29S4D5280-12 167679874	Horiz Stab Deice Boot Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	30 A/F 1962-00-7 7836	Inlet Anti-Ice Pressure Reg Shutoff Vd001 Valve Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	30 A/F 1962-00-7 7828	Inlet Anti-Ice Pressure Reg Shutoff Ve002 Valve Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	30 A/F 2602-36 2887	Isolation Valve					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	30 A/F 1173T0759 9064	Nacelle Inlet Switch Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	30 A/F 1173T0759 9079	Nacelle Inlet Switch Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	30 A/F Unknown Unknown	Nose Compartment Overtemperature Switch					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	30 A/F PH1100-1-VCW AS03227914	Pitot Tube Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	30 A/F PH1100-1-VCW AS03227915	Pitot Tube Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	30 A/F 1946-00-19 6565	Pressure Reg Valve Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	30 A/F 1946-00-19 6566	Pressure Reg Valve Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	30 A/F PH1100-1-RCDW AS09203711	Standby Pitot Tube					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	30 A/F 1106P55-1 13372A	Tail Deice Pressure Sv004 Switch Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	30 A/F 1106P55-1 13305A	Tail Deice Pressure Sv005 Switch Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	30 A/F 856-1-3 01407	Windshield Controller Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	30 A/F 856-1-3 01208	Windshield Controller Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	30 A/F 011598-501 C21450073	Windshield Rain Removal Mn001 Fan					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
2012-06-01		To Prevent Ice Accumulation on the Cables and Pulleys of the Stinger						RE (-)		Mandatory	
	30 A/F						Mos	22-Jun-2022			
	Eff: 25-Apr-2012 Not Applicable	Due to aircraft is not in the suspect serial range					Hrs	8			
	(ISSUING AUTHORITY: FAA)						Ldg	6			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30-11-00-7100	Bleed Air Anti-Ice Systems Operational Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 30 A/F	5-12-01					Mos 22-May-2024	12	-/+1m (31-May-2025)		7.6 Months (+30 Days)
	(ZONE: 162, 235) (SOURCE: 560 XL MM Section 5-10-02)					Hrs 1020:11				
						Ldg 698				
30-12-00-7100	Horizontal Stabilizer Deice System Operational Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 30 A/F	5-12-01					Mos 22-May-2024	12	-/+1m (31-May-2025)		7.6 Months (+30 Days)
	(ZONE: 311, 312, 321, 322, 340) (SOURCE: 560 XL MM Section 5-10-02)					Hrs 1020:11				
						Ldg 698				
560XL-30-06	Horizontal Stabilizer Deice System Pressure Switch Installation Improvement						RE (-)		Discretionary	
 30 A/F						Mos				
	Eff: 15-Sep-2008					Hrs				
						Ldg				
98-04-38	AFM - Limitations Section - Icing						RE (-)		Mandatory	
 30 A/F						Mos 22-Jun-2022				
	Eff: 25-Mar-1998 Not due to S/N					Hrs 8				
	Applicable					Ldg 6				
	(ISSUING AUTHORITY: FAA)									
CIL-30-01	Ice and Rain Protection - Approved Deicing Program Updates						RE (-)		Informational	
 30 A/F						Mos				
						Hrs				
						Ldg				
CIL-30-01 R1	Ice and Rain Protection - Approved Deicing Program Updates						T (A/R)		Informational	
 30 A/F						Mos				
	Eff: 13-Sep-2013					Hrs				
						Ldg				
SL560XL-30-01	Approved Deicing Program Updates						RE (-)		Optional	
 30 A/F						Mos				
						Hrs				
						Ldg				
SL560XL-30-01 Rev 01	Approved Deicing Program Updates						RE (-)		Optional	
 30 A/F						Mos				
						Hrs				
						Ldg				
SL560XL-30-01 Rev 02	Approved Deicing Program Updates						RE (-)		Optional	
 30 A/F						Mos				
						Hrs				
						Ldg				
SL560XL-30-01 Rev 03	Approved Deicing Program Updates						RE (-)		Optional	
 30 A/F						Mos				
						Hrs				
						Ldg				
SL560XL-30-01 Rev 04	Approved Deicing Program Updates						RE (-)		Optional	
 30 A/F						Mos				
						Hrs				
						Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-30-01 Rev 05  30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
SL560XL-30-01 Rev 06  30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
SL560XL-30-01 Rev 07  30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
SL560XL-30-01 Rev 08  30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
SL560XL-30-01 Rev 09  30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
SL560XL-30-01 Rev 10  30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
SL560XL-30-01 Rev 11  30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
SL560XL-30-01 Rev 12  30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
SL560XL-30-01 Rev 13  30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
SL560XL-30-01 Rev 14  30 A/F	Approved Deicing Program Updates						RE (-)		Optional	
SL560XL-30-01 Rev 15  30 A/F Eff: 08-Oct-2012	Approved Deicing Program Updates						T (A/R)		Informational	
▼ 31 - INDICATING / RECORDING SYSTEM										
 31 A/F M877A5V 25625	Digital Clock Left						RE (O/C)			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	31 A/F Unknown Unknown	Digital Clock Right						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	31 A/F 6222SM15 23653	Engine Accelerometer Left						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	31 A/F 6222SM15 23658	Engine Accelerometer Right						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	31 A/F 3001-7440-03 002055167	Flight Data Aquisition (Fdau) Unit						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	31 A/F 2100-2045-00 002070581	Flight Data Recorder (FDR)						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	31 A/F 3001-01-111-3 0921-DT9894T	Flight Data Recorder (FDR) Accelerometer						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	31 A/F Unknown Unknown	Flight Data Recorder (FDR) Fail Annunciator						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	31 A/F Unknown Unknown	Flight Data Recorder (FDR) Impact Switch						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	31 A/F Unknown Unknown	Flight Data Recorder (FDR) Underwater Locating Device (ULD)						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
								RE (H/T)		5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	31 A/F 147-E5542-00 ULB041454 Ref:31-30-04-9600	New					Mos	06-Jun-2022			
							Hrs				
							Ldg				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Inclinometer								RE (O/C)	
	31 A/F	Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Master Warning Annunicator								RE (O/C)	
	31 A/F	Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		MFDAU Flight Data Recorder (FDR) Unit								RE (O/C)	
	31 A/F	Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Printed Circuit Board Assembly - Flight Data COL								RE (O/C)	
	31 A/F	Inboard Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Tilt Indicator								RE (O/C)	
	31 A/F	3001J72 26097					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Warning Gen/Mixer Unit								RE (O/C)	
	31 A/F	Left Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Warning Gen/Mixer Unit								RE (O/C)	
	31 A/F	Right Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
31-20-01-9600		Left Digital Clock AA Long Life Battery Discard								RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS
	31 A/F	Left5-12-01 M877A5V 25625 (ZONE: 235) (SOURCE: 560 XL MM Section 5-10-02)					Mos	22-May-2024	12	-/+1m (31-May-2025)	7.6 Months (+30 Days)
							Hrs	1020:11			
							Ldg	698			
31-20-01-9600		Right Digital Clock AA Long Life Battery Discard								RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS
	31 A/F	Right5-12-01 Unknown Unknown (ZONE: 235) (SOURCE: 560 XL MM Section 5-10-02)					Mos	22-May-2024	12	-/+1m (31-May-2025)	7.6 Months (+30 Days)
							Hrs	1020:11			
							Ldg	698			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
31-30-04-9600	DK120 or DK120/90 Flight Data Recorder Underwater Locator Beacon Battery Discard						RE	05-10-01, 05-10-02, 05-12-00, Category 9		
 31 A/F						Mos	06-Jun-2022	72	30-Sep-2028	4 Years
147-E5542-00						Hrs				
ULB041454						Ldg				
Expiration Date 30-Sep-2028										
MRBR Task:31-31-00-901, MRBR Task:31-31-00-902, MRBR Task:31-30-00-902, MRBR Task:31-30-00-901 (SOURCE: 560XL MM)										
Note: 72 Months (DK120) Tracked by Component Expiration Date. NOTE: Per Supplier Recommendation. Reference L3 Communications FA2100FDR Component Maintenance Manual or the Dukane Seacom 03-TM-0037 (DK120) Technical Manual										
319911-0101	Outboard Flight Data Recorder (PCB) Printed Circuit Board						RE (O/C)			
 31 A/F						Mos	22-Jun-2022			
8718973-1						Hrs	0			
31278170-2						Ldg	0			
319911-0102	Inboard Flight Data Recorder (PCB) Printed Circuit Board						RE (O/C)			
 31 A/F						Mos	22-Jun-2022			
8718973-1						Hrs	0			
31278170-3						Ldg	0			
560XL-31-05	Data Concentrator Unit Software Upgrade						RE (-)		Mandatory	
 31 A/F						Mos	22-Jun-2022			
Eff: 03-Jun-2009 Not Applicable	by S/N					Hrs	8			
						Ldg	6			
CIL-31-01	Indicating/Recording Systems - CVR, FDR, and CVDR 90-Day Battery Underwater Locator Beacon (ULB) Installation						T (A/R)		Informational, Service Letter	
 31 A/F						Mos				
Eff: 02-Feb-2018						Hrs				
						Ldg				
Note: EFFECTIVITY: All Citation airplanes that are equipped with a Textron Aviation engineered CVR, FDR, or CVDR installation.										
SB560XL-31-06	Indicating/Recording Systems - Option to Replace the Avionics Secondary Quick Access Recorder (QAR) with an L-3 Secondary Quick Access Recorder						T (A/R)		Optional, Service Bulletin	
 31 A/F						Mos				
Eff: 28-Aug-2019						Hrs				
						Ldg				
SL560XL-31-05	Transmittal of L-3 Communications Alert Bulletin No. Cessna SB 001						RE (-)		Mandatory	
 31 A/F						Mos	22-Jun-2022			
Eff: 04-Aug-2011 Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			
SL560XL-31-06	Inspection of the Position-Sensor Potentiometer for the Elevator Trim Tab						RE (-)		Recommended	
 31 A/F						Mos	22-Jun-2022			
Eff: 22-Oct-2012 Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			
SL560XL-31-07	Indicating/ Recording Systems - Rudder Surface Input Sensor Pushrod Lockwire Installation						RE (-)		Recommended, Service Letter	
 31 A/F						Mos	22-Jun-2022			
Eff: 23-Jun-2017 Not Applicable	effective before manufacture					Hrs	8			
(AVG MAN HRS: 1.4)						Ldg	6			
SL560XL-31-08	Indicating/Recording Systems - Collins Environmental Controller (IEC) and Power Supply (PWR) IAPS Modules Inspection/Replacement						RE (-)		Recommended	
 31 A/F						Mos	13-Sep-2023			
Eff: 14-Jun-2023 Not Applicable	as per A/C S/N					Hrs	699:29			
(AVG MAN HRS: 4.5)						Ldg	460			

Task No SEQ PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
▼ 32 - LANDING GEAR										
32 A/F 39-837 1369	Antiskid Control (UY009) Valve						RE (O/C)			
							Mos 22-Jun-2022			
							Hrs 0			
32 A/F 42-985-2 1159B*	Antiskid Digital Control						RE (O/C)			
							Mos 22-Jun-2022			
							Hrs 0			
32 A/F 42-92750 2889A	Antiskid Fault Display						RE (O/C)			
							Mos 22-Jun-2022			
							Hrs 0			
32 A/F 1785-2 1470	Antiskid Hyd Relief Valve						RE (O/C)			
							Mos 22-Jun-2022			
							Hrs 0			
32 A/F 19940929-1 79712	Antiskid Pressure Gauge						RE (O/C)			
							Mos 22-Jun-2022			
							Hrs 0			
32 A/F 640931 6BV24	Brake Press Pump Assembly						RE (O/C)			
							Mos 22-Jun-2022			
							Hrs 0			
32 A/F 211-114 2717	Brake Shuttle Valve Left						RE (O/C)			
							Mos 22-Jun-2022			
							Hrs 0			
32 A/F 211-114 2718	Brake Shuttle Valve Right						RE (O/C)			
							Mos 22-Jun-2022			
							Hrs 0			
32 A/F 65830-4 1424	Emergency Air Brake Control Valve						RE (O/C)			
							Mos 22-Jun-2022			
							Hrs 0			
32 A/F 9615 0678	Emergency Dump Valve						RE (O/C)			
							Mos 22-Jun-2022			
							Hrs 0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description						Categories		Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Emergency Gear Extension/Brake Pneumatic Storage Bottle						RE	Regulatory Inspections/Time Limits		
	32 A/F	40005347-3 10806 Manufactured Date 01-Nov-2021 Ref:32-30-09-9600 (SOURCE: 560 XL MM Section 5-13-00) Note: Regulation: US DOT CFR 49 Part 180.209 Requirements for Re-qualification of Specification Cylinders. NOTE: The pneumatic storage bottle is manufactured under U.S. DOT 3HT				Mos		288	01-Nov-2045		
						Hrs			21.1 Years		
						Ldg					
		Extend/Retract Valve						RE (O/C)			
	32 A/F	Left				Mos	22-Jun-2022				
	98120					Hrs	0				
	5711A					Ldg	0				
		Extend/Retract Valve						RE (O/C)			
	32 A/F	Right				Mos	22-Jun-2022				
	98120					Hrs	0				
	5710A					Ldg	0				
		Landing Gear Control						RE (O/C)			
	32 A/F	049801-001 00266				Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
		Landing Gear Control (VY047) Valve						RE (O/C)			
	32 A/F	4219-1 0669				Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
		Loading Valve						RE (O/C)			
	32 A/F	4215-2 0552				Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
		Main Brake Assembly						RE (O/C)			
	32 A/F	Left 2-1601-1 D0128				Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
		Main Brake Assembly						RE (O/C)			
	32 A/F	Right 2-1601-1 D0126				Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
		Main Gear Down and Lock (SN011) Switch						RE (O/C)			
	32 A/F	Left Unknown Unknown				Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
		Main Gear Down and Lock (SR008) Switch						RE (O/C)			
	32 A/F	Right Unknown Unknown				Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	32 A/F Unknown Unknown	Main Gear Up & Locked (S3) Switch Left								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	32 A/F Unknown Unknown	Main Gear Up & Locked (S3) Switch Right								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	32 A/F 6641501-33L 31491286	Main Landing Gear Assy Left								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	32 A/F 6641501-34R 31491282	Main Landing Gear Assy Right								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	32 A/F Unknown Unknown	Main Landing Gear Breather Vent Left								RE (H/T)	
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	32 A/F Unknown Unknown	Main Landing Gear Breather Vent Right								RE (H/T)	
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	32 A/F M13702 3060T201	Main Tire Left New								RE	
			0			Yrs	03-Oct-2024	15		03-Oct-2039	15 Years
			0			Hrs	1335:15				
			0			Ldg	938				
	32 A/F M13702 3060T190	Main Tire Right New								RE	
			0			Yrs	03-Oct-2024	15		03-Oct-2039	15 Years
			0			Hrs	1335:15				
			0			Ldg	938				
	32 A/F 3-1571-6 D0289	Main Wheel Assembly Left Repaired								RE (O/C)	
							Mos	03-Oct-2024			
			0				Hrs	1335:15			
			0				Ldg	938			
	32 A/F 3-1571-6 D0128	Main Wheel Assembly Right Repaired								RE (O/C)	
							Mos	03-Oct-2024			
			0				Hrs	1335:15			
			0				Ldg	938			
	32 A/F Unknown Unknown	Master Brake Cylinder Left Inboard								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	32 A/F Unknown Unknown	Master Brake Cylinder Left Outboard					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	32 A/F Unknown Unknown	Master Brake Cylinder Right Inboard					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	32 A/F Unknown Unknown	Master Brake Cylinder Right Outboard					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	32 A/F Unknown Unknown	Nose Gear Down and Lock (SN002) Switch					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	32 A/F Unknown Unknown	Nose Gear Up & Locked (SN001) Switch					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	32 A/F 98120 5714A	Nose Landing Gear Extend/Retract Valve					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	32 A/F 5543001-12 31092429C	Nose Landing Gear Shimmy Damper					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	32 A/F Unknown Unknown	Nose Landing Gear Trunnion					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	32 A/F 5527504-3 5311	Nose Landing Gear Uplock Actuator					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	32 A/F 3-1418 D0537	Nose Landing Gear Wheel Assembly Overhauled					Mos	01-Oct-2024		RE (O/C)	
				0			Hrs	1332:19			
				0			Ldg	934			
	32 A/F 031-613-8 4081T00405	Nose Tire New		0			Yrs	01-Oct-2024	15	01-Oct-2039	15 Years
							Hrs	1332:19			
							Ldg	934			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	32 A/F 98433-2 0742	Parking Brake Valve						RE (O/C)			
						Mos	22-Jun-2022				
						Hrs	0				
	32 A/F 7551-1 0588	Power Brake Accumulator						RE (O/C)			
						Mos	22-Jun-2022				
						Hrs	0				
	32 A/F 6617515-6 5889	Power Brake Assembly Motor						RE (O/C)			
						Mos	22-Jun-2022				
						Hrs	0				
	32 A/F 32-105-3 790	Power Brake Valve						RE (O/C)			
						Mos	22-Jun-2022				
						Hrs	0				
	32 A/F MP50B1 5889	Power Pack Motor						RE (O/C)			
						Mos	22-Jun-2022				
						Hrs	0				
	32 A/F GPP1250-73 2201174	Press Antiskid Brk Switch						RE (O/C)			
						Mos	22-Jun-2022				
						Hrs	0				
	32 A/F GPP1250-52 2144530	Pressure (SN011) Switch						RE (O/C)			
						Mos	22-Jun-2022				
						Hrs	0				
	32 A/F 19940929-1 79409	Pressure Emer Gear Gauge						RE (O/C)			
						Mos	22-Jun-2022				
						Hrs	0				
	32 A/F 5527504-3 5325	Uplock Actuator Left						RE (O/C)			
						Mos	22-Jun-2022				
						Hrs	0				
	32 A/F 5527504-3 5327	Uplock Actuator Right						RE (O/C)			
						Mos	22-Jun-2022				
						Hrs	0				
	32 A/F Unknown Unknown	Wheel Transducer Left						RE (O/C)			
						Mos	22-Jun-2022				
						Hrs	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
Wheel Transducer										
	32 A/F	Right				Mos	22-Jun-2022		RE (O/C)	
	Unknown					Hrs	0			
	Unknown					Ldg	0			
2012-09-01 To Prevent Brake Failure, Which Could Result in an Airplane Not Being Able to Stop on the Runway										
	32 A/F					Mos	22-Jun-2022		RE (-)	Mandatory
	Eff: 07-Jun-2012 Not Applicable	Due to aircraft is not in suspect serial range				Hrs	8			
	(ISSUING AUTHORITY: FAA)					Ldg	6			
32-00-00-2101 Left Main Landing Gear Door General Visual Inspection										
	32 A/F	5-12-06				Mos		48	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
						Hrs		-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
	(ZONE: 720) (SOURCE: 560 XL MM Section 5-10-02)					Ldg				
Note: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-7100, 53-10-00-2100, and 57-10-00-2100										
32-00-00-2101 Nose Landing Gear Door General Visual Inspection										
	32 A/F	5-12-06				Mos		48	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
						Hrs		-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
	(ZONE: 710) (SOURCE: 560 XL MM Section 5-10-02)					Ldg				
Note: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-7100, 53-10-00-2100, and 57-10-00-2100										
32-00-00-2101 Right Main Landing Gear Door General Visual Inspection										
	32 A/F	5-12-06				Mos		48	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
						Hrs		-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
	(ZONE: 730) (SOURCE: 560 XL MM Section 5-10-02)					Ldg				
Note: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-7100, 53-10-00-2100, and 57-10-00-2100										
32-00-00-7100 Landing Gear System General Visual Inspection, Operational Check and Functional Check										
	32 A/F	5-12-06				Mos		48	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
						Hrs		-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
	(ZONE: 211, 235,313, 710, 720, 730) (SOURCE: 560 XL MM Section 5-10-02)					Ldg				
Note: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-2101, 53-10-00-2100, and 57-10-00-2100										
32-10-00-2200 Left Main Landing Gear Detailed Inspection										
	32 A/F	5-12-08				Mos			RE 05-10-01, 05-10-02, Category 5, Category 6	≈25-Mar-2026
						Hrs	2,400	-/+25	(2400)	1040:04 Hrs (+25)
	MRBR Task:32-10-00-205, MRBR Task:32-10-00-204, MRBR Task:32-10-00-203, MRBR Task:32-10-00-202, MRBR Task:32-10-00-201 (ZONE: 720) (SOURCE: 560XL MM)					Ldg				
32-10-00-2200 Right Main Landing Gear Detailed Inspection										
	32 A/F	5-12-08				Mos			RE 05-10-01, 05-10-02, Category 5, Category 6	≈25-Mar-2026
						Hrs	2,400	-/+25	(2400)	1040:04 Hrs (+25)
	MRBR Task:32-10-00-205, MRBR Task:32-10-00-204, MRBR Task:32-10-00-203, MRBR Task:32-10-00-202, MRBR Task:32-10-00-201 (ZONE: 730) (SOURCE: 560XL MM)					Ldg				
32-10-00-2201 Main Landing Gear Actuator Rod End Detailed Inspection (Airplanes Operating in Severe Corrosion Environments)										
	32 A/F					Mos		48	Discretionary Maintenance	
						Hrs			[30-Jun-2026]	1.7 Years
	Ref:Chapter 32, Main Landing Gear and Doors - Inspection/Check (SOURCE: 560 XL MM Section 5-19-00)					Ldg				
32-10-00-9600 Main Landing Gear Oleo Breather Vent Discard (If Installed)										
	32 A/F	Left				Mos	02-Jun-2023		RE (N/A) 5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	Unknown					Hrs	460:06			
	Unknown					Ldg	317			
	(ZONE: 720) (SOURCE: 560 XL MM Section 5-10-02)									

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
32-10-00-9600	Main Landing Gear Oleo Breather Vent Discard (If Installed)						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 32 A/F	Right				Mos	02-Jun-2023				
Unknown					Hrs	460:06				
Unknown					Ldg	317				
(ZONE: 730) (SOURCE: 560 XL MM Section 5-10-02)										
32-10-00-9601	Main Landing Gear Trunnion Subassembly						RE	Airworthiness Limitations Inspection Time Limits		≈13-Mar-2080
 32 A/F	Left				Mos	22-Jun-2022				
6641630-41					Hrs	0				
31372567		0			Ldg	0	27,500		27,500	26,543 Ldg
(ZONE: 730) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
32-10-00-9601	Main Landing Gear Trunnion Subassembly						RE	Airworthiness Limitations Inspection Time Limits		≈13-Mar-2080
 32 A/F	Right				Mos	22-Jun-2022				
6641630-42		0			Hrs	0				
31180204		0			Ldg	0	27,500		27,500	26,543 Ldg
(ZONE: 720) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
32-10-00-9602	Main Landing Gear Trailing Link Assembly						RE	Airworthiness Limitations Inspection Time Limits		≈22-Apr-2092
 32 A/F	Left				Mos	22-Jun-2022				
6641530-3		0			Hrs	0				
31223139		0			Ldg	0	33,300		33,300	32,343 Ldg
(ZONE: 730) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
32-10-00-9602	Main Landing Gear Trailing Link Assembly						RE	Airworthiness Limitations Inspection Time Limits		≈22-Apr-2092
 32 A/F	Right				Mos	22-Jun-2022				
6641530-4		0			Hrs	0				
31067421		0			Ldg	0	33,300		33,300	32,343 Ldg
(ZONE: 720) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
32-10-00-9603	Main Landing Gear Trailing Link Spacer						RE	Airworthiness Limitations Inspection Time Limits		≈22-Apr-2092
 32 A/F	Left				Mos	22-Jun-2022				
6641533-2		0			Hrs	0				
508486-6		0			Ldg	0	33,300		33,300	32,343 Ldg
(ZONE: 730) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
32-10-00-9603	Main Landing Gear Trailing Link Spacer						RE	Airworthiness Limitations Inspection Time Limits		≈22-Apr-2092
 32 A/F	Right				Mos	22-Jun-2022				
6641533-2		0			Hrs	0				
505066-1		0			Ldg	0	33,300		33,300	32,343 Ldg
(ZONE: 720) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
32-10-00-9604	Main Landing Gear Oleo Assembly (Except Upper Cap)						RE	Airworthiness Limitations Inspection Time Limits		≈04-May-2088
 32 A/F	Left				Mos	22-Jun-2022				
6641615-7		0			Hrs	0				
30850429		0			Ldg	0	31,400		31,400	30,443 Ldg
(ZONE: 730) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
32-10-00-9604	Main Landing Gear Oleo Assembly (Except Upper Cap)						RE	Airworthiness Limitations Inspection Time Limits		≈04-May-2088
 32 A/F	Right				Mos	22-Jun-2022				
6641615-7		0			Hrs	0				
31355728		0			Ldg	0	31,400		31,400	30,443 Ldg
(ZONE: 720) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										

Task No	Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
32-10-00-9604		Main Landing Gear Oleo Upper Cap						RE		Airworthiness Limitations Inspection Time Limits	≈18-Jun-2048
	32 A/F	Left				Mos	22-Jun-2022				
	6641616-5			0		Hrs		0			
	30850429			0		Ldg		0	12,300	12,300	11,343 Ldg
	(ZONE: 730) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
32-10-00-9604		Main Landing Gear Oleo Upper Cap						RE		Airworthiness Limitations Inspection Time Limits	≈18-Jun-2048
	32 A/F	Right				Mos	22-Jun-2022				
	6641616-5			0		Hrs		0			
	31355728			0		Ldg		0	12,300	12,300	11,343 Ldg
	(ZONE: 720) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
32-10-00-9605		Main Landing Gear Actuator Assembly						RE		Airworthiness Limitations Inspection Time Limits	≈22-Apr-2168
	32 A/F	Left				Mos	22-Jun-2022				
	1550000-7			0		Hrs		0			
	2254			0		Ldg		0	69,700	69,700	68,743 Ldg
	(ZONE: 730) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
32-10-00-9605		Main Landing Gear Actuator Assembly						RE		Airworthiness Limitations Inspection Time Limits	≈22-Apr-2168
	32 A/F	Right				Mos	22-Jun-2022				
	1550000-8	New		0		Hrs		0			
	2255			0		Ldg		0	69,700	69,700	68,743 Ldg
	(ZONE: 720) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
32-20-00-2200		Nose Landing Gear Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Mar-2026
	32 A/F	5-12-08				Mos					
						Hrs		2,400	-/+25	(2400)	1040:04 Hrs (+25)
						Ldg					
	(ZONE: 710) (SOURCE: 560 XL MM Section 5-10-02)										
32-20-00-9600		Nose Landing Gear Assembly						RE (O/C)		Airworthiness Limitations Inspection Time Limits	
	32 A/F					Mos	22-Jun-2022				
	6642635-6			0		Hrs		0			
	31551560			0		Ldg		0			
	(ZONE: 710) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
32-20-00-9601		Nose Landing Gear Actuator						RE		Airworthiness Limitations Inspection Time Limits	≈22-Apr-2092
	32 A/F					Mos	22-Jun-2022				
	9912491-6			0		Hrs		0			
	1330			0		Ldg		0	33,300	33,300	32,343 Ldg
	(ZONE: 710) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
	Note: Vendor PN: 1549300-11										
32-30-09-7800		Emergency Gear Extension/Brake Pneumatic Storage Bottle (Hydrostatic Test) Restoration						RE		Regulatory Inspections/Time Limits	
	32 A/F					Mos	06-Jun-2022	36		30-Nov-2024	46 Days
	40005347-3					Hrs					
	10806					Ldg					
	Hydrostatic Tested Date 01-Nov-2021										
	(SOURCE: 560 XL MM Section 5-13-00)										
	Note: Regulation: US DOT CFR 49 Part 180.209 Requirements for Re-qualification of Specification Cylinders. NOTE: The pneumatic storage bottle is manufactured under U.S. DOT 3HT										
	KGR-WP-010 START 11-NOV-2024										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
32-40-00-2200		Main Landing Gear Brakes Detailed Inspection, Landing Gear Axle General Visual Inspection, and Functional (Wear Pin) Check							RE (A/R)	05-10-01, 05-10-02, Category 6	
	32 A/F	Left									
	2-1601-1										
	D0128										
	MRBR Task:32-41-00-701, MRBR Task:32-42-00-201, MRBR Task:32-41-00-201, MRBR Task:32-40-00-203, MRBR Task:32-42-00-701, MRBR Task:32-40-00-202, MRBR Task:32-40-00-206 (ZONE: 720) (SOURCE: 560XL MM)										
	Note: Every Wheel Removal										
32-40-00-2200		Main Landing Gear Brakes Detailed Inspection, Landing Gear Axle General Visual Inspection, and Functional (Wear Pin) Check							RE (A/R)	05-10-01, 05-10-02, Category 6	
	32 A/F	Right									
	2-1601-1										
	D0126										
	MRBR Task:32-40-00-206, MRBR Task:32-40-00-202, MRBR Task:32-42-00-701, MRBR Task:32-41-00-701, MRBR Task:32-42-00-201, MRBR Task:32-41-00-201, MRBR Task:32-40-00-203 (ZONE: 730) (SOURCE: 560XL MM)										
	Note: Every Wheel Removal										
32-40-00-2201		Main Landing Gear Brake Master Cylinder Detailed Inspection (Airplanes -5001 thru -5500)							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	32 A/F	Left Inboard									
	Unknown										
	Unknown										
	(ZONE: 235) (SOURCE: 560 XL MM Section 5-10-02)										
32-40-00-2201		Main Landing Gear Brake Master Cylinder Detailed Inspection (Airplanes -5001 thru -5500)							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	32 A/F	Left Outboard									
	Unknown										
	Unknown										
	(ZONE: 235) (SOURCE: 560 XL MM Section 5-10-02)										
32-40-00-2201		Main Landing Gear Brake Master Cylinder Detailed Inspection (Airplanes -5001 thru -5500)							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	32 A/F	Right Inboard									
	Unknown										
	Unknown										
	(ZONE: 235) (SOURCE: 560 XL MM Section 5-10-02)										
32-40-00-2201		Main Landing Gear Brake Master Cylinder Detailed Inspection (Airplanes -5001 thru -5500)							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	32 A/F	Right Outboard									
	Unknown										
	Unknown										
	(ZONE: 235) (SOURCE: 560 XL MM Section 5-10-02)										
32-40-00-2202		Emergency Brake System Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈25-Mar-2026
	32 A/F	5-12-08									
	(ZONE: 211, 235, 720, 730) (SOURCE: 560 XL MM Section 5-10-02)										
								2,400	-/+25	(2400)	1040:04 Hrs (+25)
	(ZONE: 211, 235, 720, 730) (SOURCE: 560 XL MM Section 5-10-02)										
32-40-00-2203		Nose Landing Gear Axle General Visual Inspection							RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	32 A/F										
	MRBR Task:32-40-00-202, MRBR Task:32-40-00-206 (ZONE: 710) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00)										
	Note: Every Wheel Removal										
32-40-00-7100		Emergency Brake System Operational Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈25-Mar-2026
	32 A/F	5-12-08									
	(ZONE: 211, 235) (SOURCE: 560 XL MM Section 5-10-02)										
								2,400	-/+25	(2400)	1040:04 Hrs (+25)
	(ZONE: 211, 235) (SOURCE: 560 XL MM Section 5-10-02)										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
32-40-00-9600		Brake System Filters Discard (Airplanes -5001 thru -5500)						RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F										
		(ZONE: 211) (SOURCE: 560 XL MM Section 5-10-02)									
32-40-00-9601		Power Brake and Antiskid Filter Element Discard (Airplanes -5501 and On)						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Mar-2026
	32 A/F	5-12-08									
		(ZONE: 165) (SOURCE: 560 XL MM Section 5-10-02)						2,400	-/+25	(2400)	1040:04 Hrs (+25)
32-41-00-2101		Optional Nose Wheel Spin Up General Visual Inspection						RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F										
		(ZONE: 710) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00)									
		Note: Every Wheel Removal									
32-41-00-2200		Left Main Landing Gear Wheel and Tire Detailed Inspection						REMSG-3 Structures Inspection Tasks			
	32 A/F										
		(ZONE: 720) (SOURCE: 560 XL MM Section 5-10-01, 5-10-03, 5-12-00)									
		Note: Every Wheel Removal not to Exceed 24 Months									
32-41-00-2200		Right Main Landing Gear Wheel and Tire Detailed Inspection						REMSG-3 Structures Inspection Tasks			
	32 A/F										
		(ZONE: 730) (SOURCE: 560 XL MM Section 5-10-01, 5-10-03, 5-12-00)									
		Note: Every Wheel Removal not to Exceed 24 Months									
32-41-00-2800		Nose Landing Gear Wheel (Eddy Current) Special Detailed Inspection						RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F										
		3-1418 D0537									
		(ZONE: 710) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									
		Note: Tracked by Tire Changes NOTE:Per Supplier Recommendation. Reference BF Goodrich 32-47-42 Component Maintenance Manual									
32-41-00-2801		Main Landing Gear Wheel (Eddy Current) Special Detailed Inspection						RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F	Left									
		3-1571-6 D0289									
		(ZONE: 720) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									
		Note: Tracked by Tire Changes NOTE:Per Supplier Recommendation. Reference BF Goodrich 32-45-48 Component Maintenance Manual									
32-41-00-2801		Main Landing Gear Wheel (Eddy Current) Special Detailed Inspection						RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F	Right									
		3-1571-6 D0128									
		(ZONE: 730) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)									
		Note: Tracked by Tire Changes NOTE:Per Supplier Recommendation. Reference BF Goodrich 32-45-48 Component Maintenance Manual									

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
32-41-00-7200		Optional Nose Wheel Spin up Functional Check						RE (A/R)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F						Mos				
		(SOURCE: 560 XL MM Section 5-10-02, 5-12-00)					Hrs				
		Note: Every Wheel Removal					Ldg				
32-50-00-2200		Steering System Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F	5-12-06					Mos	48	-/+ 1m	(30-Jun-2026)	1.7 Years (+30 Days)
		(ZONE: 710) (SOURCE: 560 XL MM Section 5-10-02)					Hrs				
		Note: NOTE: It is recommended you do this task at the same time as Task 32-50-00-7200					Ldg				
32-50-00-7200		Steering Cable System Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	32 A/F	5-12-06					Mos	48	-/+ 1m	(30-Jun-2026)	1.7 Years (+30 Days)
		(ZONE: 710, 241, 242) (SOURCE: 560 XL MM Section 5-10-02)					Hrs				
		Note: NOTE: It is recommended you do this task at the same time as Task 32-50-00-2200					Ldg				
560XL-32-38		Landing Gear - Remove the Quick Disconnect from the Nose Landing Gear Torque Link						RE (-)		Recommended	
	32 A/F						Mos	22-Jun-2022			
	Not Applicable	effective before manufacture					Hrs	8			
							Ldg	6			
560XL-32-38 Rev 01		Landing Gear - Remove the Quick Disconnect from the Nose Landing Gear Torque Link						T (-)		Optional	
	32 A/F						Mos				
	Eff: 07-Dec-2010						Hrs				
							Ldg				
560XL-32-38 Rev 02		Landing Gear - Remove the Quick Disconnect from the Nose Landing Gear Torque Link						T (A/R)		Optional	
	32 A/F						Mos				
	Eff: 15-Feb-2019						Hrs				
							Ldg				
560XL-32-41		Transmittal of Goodrich Service Bulletin 3-1571-32-7						RE (-)		Recommended	
	32 A/F						Mos	22-Jun-2022			
	Not Applicable	effective before manufacture					Hrs	8			
							Ldg	6			
560XL-32-41 Rev 01		Transmittal of Goodrich Service Bulletin 3-1571-32-7						RE (-)		Mandatory	
	32 A/F						Mos	22-Jun-2022			
	Eff: 05-May-2011 Not Applicable	effective before manufacture					Hrs	8			
							Ldg	6			
		Note: This service bulletin must be accomplished at the next tire change or one year from the date of receipt, whichever occurs first.									
560XL-32-42		Landing Gear - Stainless Steel Hydraulic Tube Replacement						RE (-)		Recommended	
	32 A/F						Mos	22-Jun-2022			
	Not Applicable	effective before manufacture					Hrs	8			
							Ldg	6			
560XL-32-42 Rev 01		Landing Gear - Stainless Steel Hydraulic Tube Replacement						RE (-)		Recommended	
	32 A/F						Mos	22-Jun-2022			
	Not Applicable	effective before manufacture					Hrs	8			
							Ldg	6			
560XL-32-42 Rev 02		Landing Gear - Stainless Steel Hydraulic Tube Replacement						RE (-)		Optional	
	32 A/F						Mos				
	Eff: 11-Nov-2014						Hrs				
							Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
CIL-32-01	Improved Nose Wheel Grease Seal						RE (-)		Informational	
 32 A/F										
Eff: 07-Feb-2013										
Note: With 3-1418OPT2 (9914069-2), 3-1418OPT3 (9914069-3), or 3-1418OPT4 (9914069-4) Nose Wheels installed.										
CIL-32-04	Landing Gear - Wireless Tire Pressure Monitoring System Installation						T (A/R)		Informational	
 32 A/F										
Eff: 25-Sep-2014										
CIL-32-06	Landing Gear - Wireless Tire Pressure Sensor Fill Valve Torque Verification						T (A/R)		Informational	
 32 A/F										
Eff: 09-Mar-2020										
G-004-09-83	SUPERSEDED BY CAA UK AD 017-11-83						RE (-)		Mandatory	
 32 A/F										
Eff: 12-Dec-1983 Superseded										
(ISSUING AUTHORITY: EASA)										
G-005-09-83	SUPERSEDED BY CAA UK AD 016-11-83						RE (-)		Mandatory	
 32 A/F										
Eff: 12-Dec-1983 Superseded										
(ISSUING AUTHORITY: EASA)										
G-013-08-90	SUPERSEDED BY CAA UK AD 009-02-93						RE (-)		Mandatory	
 32 A/F										
Eff: 20-Jan-1993 Superseded										
(ISSUING AUTHORITY: EASA)										
SB560XL-32-44	Landing Gear - Nose Landing Gear Bearing Grease Fitting Installation						T (-)		Optional	
 32 A/F										
Eff: 07-Jun-2017										
SB560XL-32-44 R1	Landing Gear - Nose Landing Gear Bearing Grease Fitting Installation						T (-)		Optional	
 32 A/F										
Eff: 13-Nov-2018										
SB560XL-32-44 R2	Landing Gear - Nose Landing Gear Bearing Grease Fitting Installation						RE (-)		Optional, Service Bulletin	
 32 A/F										
Eff: 25-Nov-2019										
SB560XL-32-47	Landing Gear - Main Landing Gear Brake Hydraulic Line Fitting Replacement						T (A/R)		Optional	
 32 A/F										
Eff: 11-Sep-2023										
SL560XL-32-06	Landing Gear - Power Brake System Operation						T (A/R)		Informational	
 32 A/F										
Eff: 08-Aug-2000										
SL560XL-32-08	Landing Gear - Transmittal Of BFGoodrich Service Letter SL1866 Landing Gear Main And Nose Wheels Approved Cleaners For Aluminum Wheel Assembly						T (A/R)		Informational	
 32 A/F										
Eff: 30-Oct-2000										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SL560XL-32-09		Landing Gear - Transmittal Of BFGoodrich Service Letter SL1878, Effect Of Disinfectant On Wheel And Brake Assemblies						T (A/R)		Informational	
	32 A/F					Mos					
	Eff: 08-May-2001					Hrs					
						Ldg					
SL560XL-32-22		Landing Gear Component Placard Installation						RE (-)		Optional	
	32 A/F					Mos					
	Eff: 10-Aug-2009					Hrs					
						Ldg					
SL560XL-32-22 Rev 1		Landing Gear Component Placard Installation						RE (-)		Optional	
	32 A/F					Mos					
	Eff: 03-May-2019					Hrs					
						Ldg					
SL560XL-32-24		Revision 1 Cancels Transmittal of Curtiss Wright SB 049801-32-01, Landing Gear Control - Alternate LED Lighting Bulb						RE (-)		Optional	
	32 A/F					Mos					
						Hrs					
						Ldg					
SL560XL-32-24 Rev 01		Revision 1 Cancels Transmittal of Curtiss Wright SB 049801-32-01, Landing Gear Control - Alternate LED Lighting Bulb						RE (-)		Informational	
	32 A/F					Mos					
	Eff: 01-May-2012					Hrs					
						Ldg					
SL560XL-32-25		Main Wheel Assembly, P/N 3-1571 Series - Model 560XL/XLS Series Aircraft - Improved Inspection Procedure						T (A/R)		Informational	
	32 A/F					Mos					
	Eff: 29-Jun-2010					Hrs					
						Ldg					
SL560XL-32-27		Landing Gear - Hydraulic Loading Valve Wire Bundle Inspection						RE (-)		Optional	
	32 A/F					Mos					
						Hrs					
						Ldg					
SL560XL-32-27 Rev 01		Landing Gear - Hydraulic Loading Valve Wire Bundle Inspection						RE (-)		Mandatory	
	32 A/F					Mos	22-Jun-2022				
	Eff: 15-Jan-2015 Not Applicable	by aircraft S/N				Hrs	8				
						Ldg	6				
SL560XL-32-27 Rev 02		Landing Gear - Hydraulic Loading Valve Wire Bundle Inspection						RE (-)		Mandatory	
	32 A/F					Mos	22-Jun-2022				
	Eff: 12-Jun-2019 Not Applicable	by aircraft S/N				Hrs	8				
	(AVG MAN HRS: 1.5)					Ldg	6				
SL560XL-32-29		Main Landing Gear Actuator Lock Tab Verification						RE (-)		Recommended	
	32 A/F					Mos	22-Jun-2022				
	Eff: 22-Dec-2016 Not Applicable	effective before manufacture				Hrs	8				
	(AVG MAN HRS: 5)					Ldg	6				
SL560XL-32-30		Landing Gear - Brake Hydraulic Reservoir Sight Glass Fastener Torque Inspection						RE (-)		Recommended	
	32 A/F					Mos	13-Sep-2023				
	Eff: 11-Sep-2023 Not Applicable	as per A/C S/N				Hrs	699:29				
	(AVG MAN HRS: 0.5)					Ldg	460				
SL560XL-32-32		Landing Gear - Main Landing Gear Components Repair						T (A/R)		Informational	
	32 A/F					Mos					
	Eff: 20-May-2024					Hrs					
						Ldg					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
▼ 33 - LIGHTS											
	33 A/F 273-1 00715	5 Vdc UN002 Dimmer Power Supply Left							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
	33 A/F 273-1 00736	5 Vdc UN004 Dimmer Power Supply Center							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
	33 A/F Unknown Unknown	5 Vdc UN006 Dimmer Power Supply Right							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
	33 A/F Unknown Unknown	Cabin & Entry Light Panel Switch							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
	33 A/F EM2044-1 6559A	Electroluminescent Panel Inverter							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
	33 A/F 9913-1 103130	Emergency Lighting Battery Pack (UC019) Fwd Overhauled							RE (O/C)		
							Mos	09-Nov-2023			
							Hrs	777:40			
	33 A/F 9913-1 1993 (UPDATE NOTE: Robbed from OK-ECR)	Emergency Lighting Battery Pack (UC020) Aft Tested/Inspected							RE (O/C)		
							Mos	13-Oct-2024			
							Hrs	1359:56			
	33 A/F Unknown Unknown	Empennage Light Assy							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
	33 A/F Unknown Unknown	Entertainment Switch Panel No.6							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
	33 A/F Unknown Unknown	Glareshield Inverter							RE (O/C)		
							Mos	22-Jun-2022			
							Hrs	0			
	33 A/F Unknown Unknown										
							Mos	22-Jun-2022			
							Hrs	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	33 A/F Unknown Unknown	Light Power Supply Left No.1					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Left No.2					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Left No.3					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Left No.4					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Left No.5					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Left No.6					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Left No.7					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Left No.8					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Left No.9					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Right No.1					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Right No.10					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	33 A/F Unknown Unknown	Light Power Supply Right No.2					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Right No.3					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Right No.4					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Right No.5					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Right No.6					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Right No.7					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Right No.8					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Light Power Supply Right No.9					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F SWI829-12 202100000002812	Light Switch Panel Vanity					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Navigation Light Tail					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	33 A/F Unknown Unknown	Overwing Emergency Light Aft					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
	33 A/F 2401C TR02964	Pulse Lite Control							RE (O/C)	
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
	33 A/F 01-0771120-00 1157453003	Strobe Power Supply Left							RE (O/C)	
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
	33 A/F 01-0771120-00 1157453001	Strobe Power Supply Right							RE (O/C)	
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
	33 A/F SWI610-31 202200000011555	Switch Entry							RE (O/C)	
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
	33 A/F 01-0770966-00 420020	Tail Light Assy							RE (O/C)	
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
	33 A/F Unknown Unknown	Wing Tip Navigation FL001 Light Left							RE (O/C)	
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
	33 A/F Unknown Unknown	Wing Tip Navigation FR001 Light Right							RE (O/C)	
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
2001-14-09		Wiring of the Landing Light Switch and theJ-Box Fairing Light Relays							RE (-)	Mandatory (Appliance AD)
	33 A/F Eff: 26-Jul-2001 Complied With (ISSUING AUTHORITY: FAA)					Mos	22-Jun-2022			
				Hrs	8					
				Ldg	6					
33-40-00-7200		Tail Light Assembly (NAV-LED 72 segment) Functional Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS
	33 A/F 01-0770966-00 420020 (ZONE: 340) (SOURCE: 560 XL MM Section 5-10-02) Note: -5001 and On Incorporating NAV-LED 72 Segment Tail Light Assembly	5-12-03				Mos	22-May-2024	24	-/+1m	(31-May-2026) 1.6 Years (+30 Days)
					Hrs	1020:11				
					Ldg	698				
33-50-00-7100		Emergency Lighting System Operational Check							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS
	33 A/F (ZONE: 166, 241, 251, 261, 262) (SOURCE: 560 XL MM Section 5-10-02)	5-12-03				Mos	22-May-2024	24	-/+1m	(31-May-2026) 1.6 Years (+30 Days)
					Hrs	1020:11				
					Ldg	698				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time Remaining	
SEQ	PN/SN	MOC Note or Component Condition							DUE		
33-50-00-7200		Emergency Battery Pack (Capacity Check) Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	33 A/F	Aft				Mos	13-Oct-2024	12	-/+1m	31-Oct-2025	1 Year (+30 Days)
	9913-1					Hrs	1359:56				
	1993					Ldg	957				
	MRBR Task:33-50-00-701 (ZONE: 261, 262) (SOURCE: 560XL MM Section 5-10-01, 5-10-02, 5-12-01)										
	KGR-WP-010 START 11-NOV-2024										
33-50-00-7200		Emergency Battery Pack (Capacity Check) Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	33 A/F	Fwd				Mos	09-Nov-2023	12	-/+1m	30-Nov-2024	46 Days (+30)
	9913-1					Hrs	777:40				
	103130					Ldg	514				
	MRBR Task:33-50-00-701 (ZONE: 251, 252) (SOURCE: 560XL MM Section 5-10-01, 5-10-02, 5-12-01)										
	KGR-WP-010 START 11-NOV-2024										
33-50-00-9600		Emergency Lighting Battery Pack Restoration						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS, MSG-3 Inspection Documents		
	33 A/F	Aft				Mos	13-Oct-2024	48	-/+1m	30-Sep-2027	3 Years (+30 Days)
	9913-1					Hrs	1359:56				
	1993					Ldg	957				
	Restored Date 15-Sep-2023										
MRBR Task:33-50-00-902 (SOURCE: 560 XL MM Section 5-10-01, 5-12-00)											
Note: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored emergency lighting battery pack and/or refer to Avtech Emergency Battery Pack Component Maintenance Manual, 33-50-01.											
33-50-00-9600		Emergency Lighting Battery Pack Restoration						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS, MSG-3 Inspection Documents		
	33 A/F	Fwd				Mos	09-Nov-2023	48	-/+1m	30-Nov-2027	3.1 Years (+30 Days)
	9913-1					0 Hrs	777:40				
	103130					0 Ldg	514				
	Restored Date 09-Nov-2023										
MRBR Task:33-50-00-902 (SOURCE: 560 XL MM Section 5-10-01, 5-12-00)											
Note: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored emergency lighting battery pack and/or refer to Avtech Emergency Battery Pack Component Maintenance Manual, 33-50-01.											
CF-58-03		Emergency Lighting for Aircraft Cabin Interiors						RE (-)	Mandatory		
	33 A/F					Mos	22-Jun-2022				
	Eff: 30-Jun-1959 Complied With					Hrs	8				
	(ISSUING AUTHORITY: TC)					Ldg	6				
SL560XL-33-01		Lights - DeVore Logo Light Installation						T (A/R)	Informational		
	33 A/F					Mos					
	Eff: 15-Sep-1999					Hrs					
					Ldg						
▼ 34 - NAVIGATION											
		Performance Database						RE (O/C)			
	34 A/F					Mos					
	811-2957-001	New				Hrs					
	Unknown					Ldg					
		ADF Antenna						RE (O/C)	Honeywell Avionics		
	34 A/F	No.1				Mos	22-Jun-2022				
	622-7383-001					Hrs	0				
	4RGF6P					Ldg	0				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	34 A/F Unknown Unknown	ADF Antenna No.2					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	34 A/F Unknown Unknown	ADF Receiver Module No.1					Mos	22-Jun-2022		RE (O/C)	Honeywell Avionics
							Hrs	0			
							Ldg	0			
	34 A/F Unknown Unknown	ADF Receiver Module No.2					Mos	22-Jun-2022		RE (O/C)	Honeywell Avionics
							Hrs	0			
							Ldg	0			
	34 A/F Unknown Unknown	AFIS Configuration Module					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	34 A/F Unknown Unknown	AFIS Data Management Unit					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	34 A/F Unknown Unknown	AHRS 1 Battery Pack No.1					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	34 A/F 822-1110-002 4MT9XV	AHRS Computer Left					Mos	02-May-2024		RE (O/C)	
							Hrs	998:13			
							Ldg	683			
	34 A/F 822-1110-002 4MTDCD	AHRS Computer Right					Mos	02-May-2024		RE (O/C)	
							Hrs	998:13			
							Ldg	683			
	34 A/F 822-1109-126 4MR9NX	Air Data Computer No.1					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	34 A/F 822-1109-126 4MR9ND	Air Data Computer No.2					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	34 A/F 622-9210-501 4NC98N	ATC Transponder No.1					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
✖	34 A/F 622-9210-501 4NC987	ATC Transponder No.2					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F Unknown Unknown	Comm Unit Rack No.1					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F Unknown Unknown	Comm Unit Rack No.2					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F 822-1363-002 4MCX3C	Configuration Strapping Unit Switch No.1					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F 822-1363-002 4MCX38	Configuration Strapping Unit Switch No.2					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F 822-2388-001 4R60NR	Control Display Panel No.1					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F 822-2388-001 4R60RT	Control Display Panel No.2					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F Unknown Unknown	Cooling Fan					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F 822-2389-001 4R60R6	Cursor Control Panel No.1					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F 822-2389-001 4R60R3	Cursor Control Panel No.2					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F 822-1538-104 3YB5C	Data Concentrator Unit Overhauled					Mos	02-Nov-2022		RE (O/C)	
				0			Hrs	190:48			
				0			Ldg	130			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	34 A/F Unknown Unknown	Data Link Radio Antenna						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	34 A/F Unknown Unknown	Data Transfer Unit (DTU)						RE (O/C)	Honeywell Avionics		
							Mos	22-Jun-2022			
							Hrs	0			
	34 A/F Unknown Unknown	Detach Configuration Module						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	34 A/F Unknown Unknown	Differential Pressure Switch						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	34 A/F Unknown Unknown	Display Computer Left						RE (O/C)	Honeywell Avionics		
							Mos	22-Jun-2022			
							Hrs	0			
	34 A/F Unknown Unknown	Display Computer Right						RE (O/C)	Honeywell Avionics		
							Mos	22-Jun-2022			
							Hrs	0			
	34 A/F L10-611-14 15736	Distance Measuring Equipment (DME) Antenna No.1						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	34 A/F L10-611-14 15820	Distance Measuring Equipment (DME) Antenna No.2						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	34 A/F Unknown Unknown	DME Indicator Left						RE (O/C)	Honeywell Avionics		
							Mos	22-Jun-2022			
							Hrs	0			
	34 A/F Unknown Unknown	DME Indicator Right						RE (O/C)	Honeywell Avionics		
							Mos	22-Jun-2022			
							Hrs	0			
	34 A/F Unknown Unknown	DME Interrogator No.1						RE (O/C)	Honeywell Avionics		
							Mos	22-Jun-2022			
							Hrs	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	34 A/F Unknown Unknown	DME Interrogator No.2					Mos	22-Jun-2022		RE (O/C)	Honeywell Avionics
							Hrs	0			
							Ldg	0			
	34 A/F 822-1466-001 4KDCRT	DME Transceiver No.1					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	34 A/F 822-1466-001 4RGF4H	DME Transceiver No.2					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	34 A/F P13167 1316712431	Dual Iridium Filter New					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	34 A/F 69000941-102 MK5A-11414	Egpws Computer					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	34 A/F 501-1879-0102 1744B	Elec Horiz Sit Indicator					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	34 A/F Unknown Unknown	Electronic Display Unit (EDU) Center					Mos	22-Jun-2022		RE (O/C)	Honeywell Avionics
							Hrs	0			
							Ldg	0			
	34 A/F Unknown Unknown	Electronic Display Unit (EDU) Left					Mos	22-Jun-2022		RE (O/C)	Honeywell Avionics
							Hrs	0			
							Ldg	0			
	34 A/F Unknown Unknown	Electronic Display Unit (EDU) Right					Mos	22-Jun-2022		RE (O/C)	Honeywell Avionics
							Hrs	0			
							Ldg	0			
	34 A/F 822-1200-998 4MTCCC	External Compensation FSU Unit					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	34 A/F 822-1200-003 4MTF8H	External Compensation Unit No.1					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	34 A/F 822-1200-003 4MTF83	External Compensation Unit No.2						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	34 A/F 822-1543-201 4RKGHF	File Server Unit						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	34 A/F Unknown Unknown	Flight Display Controller Copilot						RE (O/C)	Honeywell Avionics		
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	34 A/F Unknown Unknown	Flight Display Controller Pilot						RE (O/C)	Honeywell Avionics		
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	34 A/F 822-1108-143 4MVC01	Flight Guidance Computer No.1						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	34 A/F 822-1108-143 4MCT95	Flight Guidance Computer No.2						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	34 A/F 822-1107-116 4R60T3	Flight Guidance Panel						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	34 A/F 822-1193-001 NSN	Flux Detector Left						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	34 A/F 822-1193-001 NSN	Flux Detector Right						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	34 A/F 822-2215-602 4MRC1N	FMS Data Base Unit						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
	34 A/F 822-0884-604 4P5TDX	FMS-Control Display Unit No.1						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
✖	34 A/F 822-0884-604 4P5TDY	FMS-Control Display Unit No.2					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F RGS10-48 21925	Glideslope Antenna					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F DGSC20-02 10274	Glideslope Antenna Coupler					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F CI401-460 485274	GPS Antenna No.1					Mos			RE (O/C)	
							Hrs				
							Ldg				
✖	34 A/F S67-1575-132 435-6976	GPS Antenna No.2					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F 822-0883-038 4MCR6T	GPS Flight Management Computer No.1					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F 822-0883-038 4MCX8P	GPS Flight Management Computer No.2					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F 822-2189-101 4RGFCL	GPS W/SBAS Receiver No.1					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F 822-2189-101 4RGCL4	GPS W/SBAS Receiver No.2					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F 822-2191-001 4MCV6D	IAPS Card Cage					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F 822-1167-001 4RTD31	IAPS Environmental Controller					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
✖	34 A/F 822-1137-001 4MCX1T	IAPS Power Supply No.1					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F 822-1137-001 4MCX3X	IAPS Power Supply No.2					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F Unknown Unknown	Indicator - Standby HSI					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F 822-2065-001 4MCV1K	Input/Output loc Concentrator Aft					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F 822-2065-001 4MCV1L	Input/Output loc Concentrator Fwd					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F Unknown Unknown	Integrated Nav Unit (INU) No.1					Mos	22-Jun-2022		RE (O/C)	Honeywell Avionics
							Hrs	0			
							Ldg	0			
✖	34 A/F Unknown Unknown	Integrated Nav Unit (INU) No.2					Mos	22-Jun-2022		RE (O/C)	Honeywell Avionics
							Hrs	0			
							Ldg	0			
✖	34 A/F 405019A 857	Iridium Filter New					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F 822-1993-100 4P5P5N	Litef LCR-93 AHRS Tray Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F 822-1993-100 4P5P79	Litef LCR-93 AHRS Tray Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
✖	34 A/F 501-1826-03 97901	Magnetometer					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	34 A/F 822-1987-007 4FM6Y1	Maintenance Diagnostic Computer						RE (O/C)			
								Mos	22-Jun-2022		
								Hrs	0		
								Ldg	0		
	34 A/F MB10-754 3038	Marker Beacon Antenna						RE (O/C)			
								Mos	22-Jun-2022		
								Hrs	0		
								Ldg	0		
	34 A/F C1509 687912	Marker Beacon Antenna Coupler						RE (O/C)			
								Mos	22-Jun-2022		
								Hrs	0		
								Ldg	0		
	34 A/F Unknown Unknown	MD302 Standby Attitude Module						RE (O/C)			
								Mos	22-Jun-2022		
								Hrs	0		
								Ldg	0		
	34 A/F 9200-34502-0101 3242	Meggitt Secondary Flight (EI016) Display						RE (O/C)			
								Mos	22-Jun-2022		
								Hrs	0		
								Ldg	0		
	34 A/F Unknown Unknown	Meggitt Static Converter						RE (O/C)			
								Mos	22-Jun-2022		
								Hrs	0		
								Ldg	0		
	34 A/F Unknown Unknown	MSU Calibration Prom Unit Left						RE (O/C)			
								Mos	22-Jun-2022		
								Hrs	0		
								Ldg	0		
	34 A/F Unknown Unknown	MSU Calibration Prom Unit Right						RE (O/C)			
								Mos	22-Jun-2022		
								Hrs	0		
								Ldg	0		
	34 A/F 822-2349-100 4P5P9R	Multi Function (MFD) Display No.1						RE (O/C)			
								Mos	22-Jun-2022		
								Hrs	0		
								Ldg	0		
	34 A/F 822-2349-100 4M9M0H	Multi Function (MFD) Display No.2						RE (O/C)			
								Mos	22-Jun-2022		
								Hrs	0		
								Ldg	0		
	34 A/F 822-1579-001 4RGG22	Nav (VOR/ILS) Receiver No.2						RE (O/C)			
								Mos	22-Jun-2022		
								Hrs	0		
								Ldg	0		

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
✖	34 A/F DMN4-17-1N 673596	Nav Antenna Left						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
✖	34 A/F DMN4-17-1N 673597	Nav Antenna Right						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
✖	34 A/F Unknown Unknown	NAV Cluster Module No.1						RE (O/C)	Honeywell Avionics		
							Mos	22-Jun-2022			
							Hrs	0			
✖	34 A/F Unknown Unknown	NAV Cluster Module No.2						RE (O/C)	Honeywell Avionics		
							Mos	22-Jun-2022			
							Hrs	0			
✖	34 A/F 822-1465-001 4RGDH1	Nav VOR/ILS/ADF Receiver No.1						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
✖	34 A/F CI-120-5 674606	Navigation Antenna Coupler						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
✖	34 A/F 822-1993-100 Unknown	Primary Flight (PFD) Display No.1 New						RE (O/C)			
			0				Mos	22-Jun-2022			
			0				Hrs	0			
✖	34 A/F 822-1993-100 Unknown	Primary Flight (PFD) Display No.2 New						RE (O/C)			
			0				Mos	22-Jun-2022			
			0				Hrs	0			
✖	34 A/F Unknown Unknown	Primus 1000 EFIS BL870 Bezel Controller Pilot						RE (O/C)	Honeywell Avionics		
							Mos	22-Jun-2022			
							Hrs	0			
✖	34 A/F Unknown Unknown	Primus 1000 EFIS BL871 Bezel Controller Copilot						RE (O/C)	Honeywell Avionics		
							Mos	22-Jun-2022			
							Hrs	0			
✖	34 A/F Unknown Unknown	Primus 1000 EFIS DC550 Display Controller Copilot						RE (O/C)	Honeywell Avionics		
							Mos	22-Jun-2022			
							Hrs	0			
✖	34 A/F Unknown Unknown							RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	34 A/F Unknown Unknown	Primus 1000 EFIS DC550 Display Controller Pilot					Mos	22-Jun-2022		RE (O/C)	Honeywell Avionics
							Hrs	0			
							Ldg	0			
	34 A/F Unknown Unknown	Primus 1000 EFIS DU870 Multifunction Display Unit Copilot					Mos	22-Jun-2022		RE (O/C)	Honeywell Avionics
							Hrs	0			
							Ldg	0			
	34 A/F Unknown Unknown	Primus 1000 EFIS DU870 Multifunction Display Unit Pilot					Mos	22-Jun-2022		RE (O/C)	Honeywell Avionics
							Hrs	0			
							Ldg	0			
	34 A/F Unknown Unknown	Primus 1000 EFIS IC600/IC615 Integrated Avionics Computer No.1					Mos	22-Jun-2022		RE (O/C)	Honeywell Avionics
							Hrs	0			
							Ldg	0			
	34 A/F Unknown Unknown	Primus 1000 EFIS IC600/IC615 Integrated Avionics Computer No.2					Mos	22-Jun-2022		RE (O/C)	Honeywell Avionics
							Hrs	0			
							Ldg	0			
	34 A/F Unknown Unknown	Primus 1000 EFIS MC800 Multifunction Display Controller (MDC)					Mos	22-Jun-2022		RE (O/C)	Honeywell Avionics
							Hrs	0			
							Ldg	0			
	34 A/F Unknown Unknown	Primus 1000 EFIS MS560 Mode Selector Unit					Mos	22-Jun-2022		RE (O/C)	Honeywell Avionics
							Hrs	0			
							Ldg	0			
	34 A/F Unknown Unknown	Primus 1000 EFIS RI553 Remote Instrument Controller					Mos	22-Jun-2022		RE (O/C)	Honeywell Avionics
							Hrs	0			
							Ldg	0			
	34 A/F Unknown Unknown	Radar Controller					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	34 A/F S67-2002 543-106795	Radio Alt Receiver Antenna Aft					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	34 A/F S67-2002 543-106793	Radio Alt Transmitter Antenna Fwd					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Radio Altimeter ALT-55B Transceiver								RE (O/C)	
	34 A/F	822-0615-206 4RGFOX					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Radio Management Unit (RMU)								RE (O/C)	Honeywell Avionics
	34 A/F	No.1 Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Radio Management Unit (RMU)								RE (O/C)	Honeywell Avionics
	34 A/F	No.2 Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Ram Air Temp Display								RE (O/C)	
	34 A/F	Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Receiver/Ant/ Weather Radar Transceiver								RE (O/C)	
	34 A/F	622-8439-004 4N8TR2					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Safe Flight AOA EI001 Indicator								RE (O/C)	
	34 A/F	Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Safe Flight AOA FI003 Indexer								RE (O/C)	
	34 A/F	C12763-1 188973-08					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Safe Flight Aoa UC009 Computer								RE (O/C)	
	34 A/F	C13006-3 189790-02					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Safe Flight Aoa UF004 Sensor								RE (O/C)	
	34 A/F	C-12717-1 189142-02					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Secondary ADU								RE (O/C)	
	34 A/F	9200-30000-080 9104					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Secondary Flight Display								RE (O/C)	
	34 A/F	Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Speaker Amplifier								RE (O/C)	
	34 A/F	Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Standby Battery (AHR5)								RE (O/C)	
	34 A/F	Right Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Standby Battery (Secondary Flight Display)								RE (O/C)	
	34 A/F	Left 100-2410-04 1211128					Mos	04-Jun-2022			
							Hrs				
							Ldg				
		Standby Comm-Nav Control Head								RE (O/C)	
	34 A/F	Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Standby Magnetic Compass								RE (O/C)	
	34 A/F	Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Stormscope Antenna								RE (O/C)	
	34 A/F	78-8051-9200-8 S00193					Mos				
							Hrs				
							Ldg				
		Stormscope Processor								RE (O/C)	
	34 A/F	78-8060-6086-5 S00126					Mos				
							Hrs				
							Ldg				
		Stormscope WX-1000E								RE (O/C)	
	34 A/F	S3100-512 Unknown					Mos				
							Hrs				
							Ldg				
		Taws,Waas Options Control Module								RE (O/C)	
	34 A/F	No.1 822-1484-228 4MCVTD					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Taws,Waas Options Control Module								RE (O/C)	
	34 A/F	No.2 822-1484-228 4MCVTC					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		TCAS Antenna								RE (O/C)	
	34 A/F	Bottom 622-8973-001 4RKR23					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
TCAS Processor										
34 A/F	822-3075-001					Mos	22-Jun-2022		RE (O/C)	
	78VC0					Hrs	0			
						Ldg	0			
Top Transponder Diversity Antenna										
34 A/F	L10-611-14	No.1				Mos	22-Jun-2022		RE (O/C)	
	15940					Hrs	0			
						Ldg	0			
Top Transponder Diversity Antenna										
34 A/F	L10-611-14	No.2				Mos	22-Jun-2022		RE (O/C)	
	15800					Hrs	0			
						Ldg	0			
Transponder Bottom Antenna										
34 A/F	L10-611-14	No.1				Mos	22-Jun-2022		RE (O/C)	
	16240					Hrs	0			
						Ldg	0			
Transponder Bottom Antenna										
34 A/F	L10-611-14	No.2				Mos	22-Jun-2022		RE (O/C)	
	15840					Hrs	0			
						Ldg	0			
Upper TCAS Antenna										
34 A/F	622-8973-001					Mos	22-Jun-2022		RE (O/C)	
	4RKR20					Hrs	0			
						Ldg	0			
VHF NAV Receiver										
34 A/F	Unknown	No.1				Mos	22-Jun-2022		RE (O/C)	Honeywell Avionics
	Unknown					Hrs	0			
						Ldg	0			
VHF NAV Receiver										
34 A/F	Unknown	No.2				Mos	22-Jun-2022		RE (O/C)	Honeywell Avionics
	Unknown					Hrs	0			
						Ldg	0			
XM Weather Receiver Unit										
34 A/F	Unknown					Mos	22-Jun-2022		RE (O/C)	
	Unknown					Hrs	0			
						Ldg	0			
XMWR-1000S SXM Receiver										
34 A/F	822-3365-001					Mos	22-Jun-2022		RE (O/C)	
	Unknown					Hrs	0			
						Ldg	0			
Garmin GNS 430 units										
2001-23-17	34 A/F					Mos	22-Jun-2022		RE (-)	Mandatory (Appliance AD)
	Eff: 28-Dec-2001	Due to suspect parts are not installed on this aircraft				Hrs	8			
	Applicable					Ldg	6			
	Brand A:9990-2001-23-17 (ISSUING AUTHORITY: FAA)									

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2007-23-13	Inspect - Adjustment Of Stall Warning System (Superseded by AD2008-26-04)						RE (-)		Mandatory	
34 A/F						Mos	22-Jun-2022			
Eff: 30-Nov-2007 Not	to the model					Hrs	8			
Applicable						Ldg	6			
(ISSUING AUTHORITY: FAA)										
2010-07-02	Integrated Navigation Units (INUs) - Honeywell Primus II RNZ-850()/-851() (This AD supersedes AD 2006-22-05)						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	22-Jun-2022			
Eff: 03-May-2010 Not	Due to suspect parts are not installed on this aircraft					Hrs	8			
Applicable						Ldg	6			
(ISSUING AUTHORITY: FAA)										
2012-26-15 R1	Honeywell International Inc. - Air Data Pressure Transducers (This action rescinds AD 2012-26-15, Amendment 39-17310 (78 FR 1735, January 9, 2013).)						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	22-Jun-2022			
Eff: 03-Dec-2014 Not	Due to suspect parts are not installed on this aircraft					Hrs	8			
Applicable						Ldg	6			
(ISSUING AUTHORITY: FAA)										
2014-18-01	Rockwell Collins, Inc. - Navigation - inspect the airplane type code category strapping setting for a value of zero (0) or one (1) following Rockwell Collins, Inc. Service Information Letter 07-2, 523-0810069-101000, TDR-94() SIL 07-02.						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	22-Jun-2022			
Eff: 14-Oct-2014 Not	Due to pages 6 & 7 section (C) (3) (V) and ECR 58032					Hrs	8			
Applicable						Ldg	6			
Brand A:9990-2014-18-01 (AVG MAN HRS: 4) (APX COST: 85) (ISSUING AUTHORITY: FAA)										
2020-10-05	Flight Management Computing Hardware System - Rockwell Collins Pro Line 4 and Pro Line 21 Flight Management Systems						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	22-Jun-2022			
Eff: 24-Jun-2020 Not	Due to suspect parts are not programed for this option					Hrs	8			
Applicable						Ldg	6			
(ISSUING AUTHORITY: FAA)										
2021-23-12	Indicating/Recording System, Navigation - Radio Altimeter (Transport and Commuter Category Airplanes) (This AD is Superseded by FAA AD 2023-10-02)						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	22-Jun-2022			
Eff: 03-Jan-2022 Complied With						Hrs	8			
(ISSUING AUTHORITY: FAA)						Ldg	6			
Note: COMPLIANCE: On or before January 4, 2022: Revise the Limitations Section of the existing AFM by incorporating the limitations specified in figure 1 to paragraph (g) of this AD. This may be done by inserting a copy of this AD into the existing AFM.										
2023-10-02	Navigation - Radio Altimeters (This AD Replaces AD 2021-23-12)						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	15-Jun-2023			
Eff: 26-May-2023 Complied With						Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				
Note: APPLICABILITY: This AD applies to all transport and commuter category airplanes equipped with a radio (also known as radar) altimeter. These radio altimeters are installed on various transport and commuter category airplanes including, but not limited to, the airplanes for which the design approval holder is identified in paragraphs (c)(1) through (18) of this AD. (1) The Boeing Company (2) Airbus SAS (3) Bombardier Inc.(4) Embraer S.A. (including type certificates previously held by Yavorã Indústria Aeronáutica S.A., which are now held by Embraer S.A.) (5) Gulfstream Aerospace Corporation (6) Gulfstream Aerospace LP (7) Textron Aviation Inc. (8) Pilatus Aircraft Limited (9) Fokker Services B.V. (10) Saab AB, Support and Services (11) DeHavilland Aircraft of Canada Limited (12) Airbus Canada Limited Partnership (13) ATR-GIE Avions de Transport Régional (14) MHI RJ Aviation ULC (15) BAE Systems (Operations) Limited (16) Lockheed Martin Corporation/Lockheed Martin Aeronautics Company (17) Viking Air Limited (18) Dassault Aviation										
2023-10-02 Par. (h)	Navigation - Radio Altimeters - Airplane Flight Manual (AFM) Revision Until June 30, 2023						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	15-Jun-2023			
Eff: 25-May-2023 Complied With	Complied as per AD 2021-23-12 par(g)					Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				
Note: COMPLIANCE: For non-radio altimeter tolerant airplanes, before further flight, revise the Limitations Section of the existing AFM to include the information specified in figure 3 to paragraph (h) of this AD. This may be done by inserting a copy of figure 3 to paragraph (h) of this AD into the existing AFM. If an operator has complied with paragraph (g) of AD 2021-23-12, that action satisfies the requirements of this paragraph.										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2023-10-02 Par. (i)	Navigation - Radio Altimeters - AFM Revision After June 30, 2023						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	26-Jun-2023			
Eff: 29-Jun-2023 Complied With	AFM updated					Hrs	518:21			
(ISSUING AUTHORITY: FAA)						Ldg	348			
Note: COMPLIANCE: On or before June 30, 2023, revise the Limitations Section of the existing AFM to include the information specified in figure 4 to paragraph (i) of this AD. This may be done by inserting a copy of figure 4 to paragraph (i) of this AD into the existing AFM. Incorporating the AFM revision required by this paragraph terminates the AFM revision required by paragraph (h) of this AD. (2) Before further flight after incorporating the limitations specified in figure 4 to paragraph (i) of this AD, remove the AFM revision required by paragraph (h) of this AD.										
2023-10-02 Par. (j)	Navigation - Radio Altimeters - Terminating Action for AFM Limitations						T (A/R)		Mandatory (Appliance AD)	
34 A/F						Mos				
Eff: 26-May-2023						Hrs				
(ISSUING AUTHORITY: FAA)						Ldg				
Note: COMPLIANCE: Modifying the airplane from a non-radio altimeter tolerant airplane to a radio altimeter tolerant airplane terminates the limitations in paragraph (i) of this AD for that airplane. After modifying the airplane to a radio altimeter tolerant airplane, the limitations specified by paragraph (i) of this AD may be removed from the AFM.										
2023-21-05	Navigation - Thales AVS France SAS Flight Management Computer Navigation Modules (FMC2 NAVM)						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	13-Nov-2023			
Eff: 12-Dec-2023 Not Applicable	affected P/N is not installed					Hrs	783:10			
(ISSUING AUTHORITY: FAA)						Ldg	518			
2023-21-05 Par. (g)(1)	Navigation - Thales AVS France SAS Flight Management Computer Navigation Modules (FMC2 NAVM) - Revise the Limitations Section of the Existing Airplane Flight Manual						RE (-)		Mandatory (Appliance AD)	
34 A/F						Days	13-Nov-2023			
Eff: 12-Dec-2023 Not Applicable	affected P/N is not installed					Hrs	783:10			
(ISSUING AUTHORITY: FAA)						Ldg	518			
Note: APPLICABILITY: This AD applies to Thales AVS France SAS flight management computer navigation modules (FMC2 NAVM), part number (P/N) C13084CA03, installed on, but not limited to airplanes, certificated in any category. COMPLIANCE: Within 30 days after the effective date of this AD, revise the Limitations Section of the existing airplane flight manual (AFM) for your airplane by adding the information in Table 1 to the introductory text of paragraph (g)(1) of this AD and Table 2 to the introductory text of paragraph (g)(1) of this AD.										
2023-21-05 Par. (g)(2)	Navigation - Thales AVS France SAS Flight Management Computer Navigation Modules (FMC2 NAVM) - Update the Database for Thales FMC2 NAVM - P/N C13084CA03						RE (-)		Mandatory (Appliance AD)	
34 A/F						Days	13-Nov-2023			
Eff: 12-Dec-2023 Not Applicable	affected P/N is not installed					Hrs	783:10			
(ISSUING AUTHORITY: FAA)						Ldg	518			
Note: APPLICABILITY: This AD applies to Thales AVS France SAS flight management computer navigation modules (FMC2 NAVM), part number (P/N) C13084CA03, installed on, but not limited to airplanes, certificated in any category. COMPLIANCE: Within 30 days after the effective date of this AD, update the database for your Thales FMC2 NAVM, P/N C13084CA03, with a database that does not contain the procedures specified in section II of Thales Service Information Letter F9111-J70859DN-00, issued January 18, 2022 (Thales SIL F9111-J70859DN-00).										
2024-0024	Navigation - Digital Air Data Computer - Replacement						RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	26-Jan-2024			
Eff: 07-Feb-2024 Not Applicable	as per installed PN					Hrs	883			
(ISSUING AUTHORITY: EASA)						Ldg	593			
Note: COMPLIANCE: For Group 1 aircraft: Within 12 months after the effective date of this AD, remove each affected part from service and replace it with a serviceable part in accordance with the instructions of the SB.										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
24-32-00-9600	Securaplane Battery Discard						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 34 A/F	Left					Mos	04-Jun-2022	48	31-Dec-2025	1.2 Years
100-2410-04						Hrs				
1211128						Ldg				
Manufactured Date 01-Dec-2021										
(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)										
Note: 48 Months										
Tracked by										
Component										
Expiration Date. NOTE: Per Supplier Recommendation. Reference Securaplane Technologies Inc. 24-32-24 Component Maintenance Manual										
34-00-CUS-001	Compass swing						RE			
 34 A/F						Mos	22-May-2024	12	22-May-2025	7.3 Months
						Hrs	1020:11			
						Ldg	698			
Note: CAA Requirement										
34-00-CUS-002	Functional test of Air Data Computer No.1						RE			
 34 A/F						Mos	22-May-2024	24	22-May-2026	1.6 Years
						Hrs	1020:11			
						Ldg	698			
Note: CAA Requirement										
34-00-CUS-002	Functional test of Air Data Computer No.2						RE			
 34 A/F						Mos	22-May-2024	24	22-May-2026	1.6 Years
						Hrs	1020:11			
						Ldg	698			
Note: CAA Requirement										
342200-0101	Data Configuration Module						RE (O/C)			
 34 A/F						Mos	22-Jun-2022			
9230-34012-01						Hrs	0			
3260						Ldg	0			
342507-0101	FMS Display Controller						RE (O/C)			
 34 A/F	Left					Mos	22-Jun-2022			
Unknown						Hrs	0			
Unknown						Ldg	0			
342507-0102	FMS Display Controller						RE (O/C)			
 34 A/F	Right					Mos	22-Jun-2022			
Unknown						Hrs	0			
Unknown						Ldg	0			
34-53-07-7200	Transponder System Functional Check (Airplanes -6001 and On)						RE	Regulatory Inspections/Time Limits		
 34 A/F	No.1					Mos	22-May-2024	24	31-May-2026	1.6 Years
622-9210-501						Hrs	1020:11			
4NC98N						Ldg	698			
(SOURCE: 560 XL MM Section 5-13-00)										
Note: Regulation: 14 CFR Part 91.413. NOTE : This task also includes inspections necessary for RVSM Certified Airplanes										
34-53-07-7200	Transponder System Functional Check (Airplanes -6001 and On)						RE	Regulatory Inspections/Time Limits		
 34 A/F	No.2					Mos	22-May-2024	24	31-May-2026	1.6 Years
622-9210-501						Hrs	1020:11			
4NC987						Ldg	698			
(SOURCE: 560 XL MM Section 5-13-00)										
Note: Regulation: 14 CFR Part 91.413. NOTE : This task also includes inspections necessary for RVSM Certified Airplanes										

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
34-90-10-7200		Pitot-Static System Functional Check (Airplanes -5001 thru -6000)							RE (N/A)	Regulatory Inspections/Time Limits		
	34 A/F						Mos					
							Hrs					
	(SOURCE: 560 XL MM Section 5-13-00)						Ldg					
34-90-12-7200		Functional Check Secondary (Standby) ADU Pitot-Static System Functional Check (Airplanes -6001 and on) (14 CFR 91.411, 91.413 and RVSM Certification)							RE			
	34 A/F						Mos	22-May-2024	24	22-May-2026	1.6 Years	
							Hrs	1020:11				
							Ldg	698				
Note: CAA Requirement												
34-90-12-7200		Pitot-Static System Functional Check (Airplanes -6001 and On)							RE	Regulatory Inspections/Time Limits		
	34 A/F						Mos	22-May-2024	24	31-May-2026	1.6 Years	
							Hrs	1020:11				
							Ldg	698				
(SOURCE: 560 XL MM Section 5-13-00)												
Note: Regulation: 14 CFR 91.411, 91.413 and RVSM certification. NOTE : This task also includes inspections necessary for RVSM Certified Airplanes												
34-90-12-7200		Rvsm Skin Waviness Inspection Pitot-Static System Functional Check (Airplanes -6001 And On) (14 Cfr 91.411, 91.413 And Rvsm Certification)							RE			
	34 A/F						Mos	22-May-2024	24	22-May-2026	1.6 Years	
							Hrs	1020:11				
							Ldg	698				
Note: CAA Requirement												
349965-0101		External Compensation Unit							RE (O/C)			
	34 A/F	No.3					Mos	15-Apr-2023				
	822-1200-997	New					Hrs	402:30				
	4K1CH8						Ldg	276				
560XL-34-27		Navigation - Universal Avionics Performance Database							T (A/R)	Optional		
	34 A/F						Mos					
	Eff: 01-May-2003						Hrs					
							Ldg					
560XL-34-37		Enhanced Ground Proximity Warning System (EGPWS) Steep Approach Switch Installation							T (A/R)	Optional		
	34 A/F						Mos					
	Eff: 29-Mar-2004						Hrs					
							Ldg					
560XL-34-40		Enhanced Ground Proximity Warning System (EGPWS) Runway Awareness Advisory System (RAAS) Upgrade							RE (-)	Recommended		
	34 A/F						Mos	22-Jun-2022				
	Not Applicable	effective before manufacture					Hrs	8				
							Ldg	6				
560XL-34-40 Rev 01		Enhanced Ground Proximity Warning System (EGPWS) Runway Awareness Advisory System (RAAS) Upgrade							T (A/R)	Optional		
	34 A/F						Mos					
	Eff: 05-Mar-2008						Hrs					
							Ldg					
560XL-34-41		Honeywell Transponder Upgrade for Elementary Surveillance							RE (-)	Recommended		
	34 A/F						Mos	22-Jun-2022				
	Not Applicable	effective before manufacture					Hrs	8				
							Ldg	6				
560XL-34-41 Rev 01		Honeywell Transponder Upgrade for Elementary Surveillance							RE (-)	Recommended		
	34 A/F						Mos	22-Jun-2022				
	Not Applicable	effective before manufacture					Hrs	8				
							Ldg	6				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
560XL-34-41 Rev 02  34 A/F Eff: 15-Jun-2006	Honeywell Transponder Upgrade for Elementary Surveillance						T (A/R)		Optional	
						Mos				
						Hrs				
						Ldg				
560XL-34-43  34 A/F Not Applicable	Universal Avionics Performance Database Upgrade effective before manufacture						RE (-)		Recommended	
						Mos	22-Jun-2022			
						Hrs	8			
						Ldg	6			
560XL-34-43 Rev 01  34 A/F Eff: 27-Jan-2006	Universal Avionics Performance Database Upgrade						T (A/R)		Optional	
						Mos				
						Hrs				
						Ldg				
560XL-34-49  34 A/F Not Applicable	Runway Awareness Advisory System (RAAS) Audio Inhibit Switch Installation effective before manufacture						RE (-)		Mandatory	
						Mos	22-Jun-2022			
						Hrs	8			
						Ldg	6			
560XL-34-49 Rev 01  34 A/F Eff: 29-Nov-2007	Runway Awareness Advisory System (RAAS) Audio Inhibit Switch Installation						T (A/R)		Optional	
						Mos				
						Hrs				
						Ldg				
560XL-34-63  34 A/F Not Applicable	XLS+ FMS 4.0 (WAAS) Upgrade and V-Speeds Database Installation effective before manufacture						RE (-)		Recommended	
						Mos	22-Jun-2022			
						Hrs	8			
						Ldg	6			
560XL-34-63 Rev 01  34 A/F Eff: 30-Mar-2010 Not Applicable	XLS+ FMS 4.0 (WAAS) Upgrade and V-Speeds Database Installation effective before manufacture						RE (-)		Recommended	
						Mos	22-Jun-2022			
						Hrs	8			
						Ldg	6			
560XL-34-64  34 A/F Eff: 02-Dec-2009	CAT II Landing Operation Option						T (A/R)		Optional	
						Mos				
						Hrs				
						Ldg				
560XL-34-65  34 A/F Eff: 02-Dec-2009 Not Applicable	XLS+ Adaptive Flight Displays (AFD) Software and Hardware effective before manufacture						RE (-)		Recommended	
						Mos	22-Jun-2022			
						Hrs	8			
						Ldg	6			
560XL-34-68  34 A/F Not Applicable	AFD AOA Configuration Wiring Installation effective before manufacture						RE (-)		Recommended	
						Mos	22-Jun-2022			
						Hrs	8			
						Ldg	6			
560XL-34-68 Rev 01  34 A/F Eff: 15-Jun-2011 Not Applicable	AFD AOA Configuration Wiring Installation effective before manufacture						RE (-)		Recommended	
						Mos	22-Jun-2022			
						Hrs	8			
						Ldg	6			
560XL-34-73  34 A/F Eff: 01-Aug-2012	Traffic Surveillance System (TTR-4000) TCAS II Software 7.1 Upgrade						RE (-)		Optional	
						Mos				
						Hrs				
						Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
560XL-34-74	Navigation - GPS-4000S Software Update						RE (-)		Recommended	
 34 A/F						Mos	22-Jun-2022			
Eff: 28-Apr-2014 Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			
560XL-34-76	Navigation - Automatic Dependent Surveillance Broadcast (ADS-B) Out Transponder Installation						RE (-)		Optional	
 34 A/F						Mos				
Eff: 03-Mar-2016						Hrs				
						Ldg				
94-01-04	Honeywell - Traffic Alert And Collision Avoidance System (TCAS) II						RE (-)		Mandatory (Appliance AD)	
 34 A/F						Mos	22-Jun-2022			
Eff: 04-Feb-1994 Complied With (ISSUING AUTHORITY: FAA)						Hrs	8			
						Ldg	6			
96-24-06	Icing Condition or Ice on the Wing Addition to AFM (Superseded by AD 2000-03-09)						RE (-)		Mandatory	
 34 A/F						Mos	22-Jun-2022			
Eff: 05-Dec-1996 Not Applicable (ISSUING AUTHORITY: FAA)	Due to aircraft is not in the suspect serial range					Hrs	8			
						Ldg	6			
98-25-02	BF Goodrich Avionics Systems, Inc. SKYWATCH SKY497 Installations with a Top-Mounted Antenna						RE (-)		Mandatory (Appliance AD)	
 34 A/F						Mos	22-Jun-2022			
Eff: 22-Dec-1998 Not Applicable (ISSUING AUTHORITY: FAA)	Due to suspect parts are not installed on this aircraft					Hrs	8			
						Ldg	6			
CIL-34-04	Navigation - TDR-94/94D Transponder All - Call						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 25-Sep-2014						Hrs				
						Ldg				
CIL-34-08	Navigation - Transmittal of Collins Aerospace Service Bulletin ATL-4000-34-D, Navigation - ALT-4000 - Evaluation of Surface Mount Ferrite Bead Used on the Power Supply						RE (-)		Recommended	
 34 A/F						Mos	22-Jun-2022			
Eff: 18-May-2021 Not Applicable (AVG MAN HRS: 2.5)	effective before manufacture					Hrs	8			
						Ldg	6			
CIL-34-11	Navigation - Transmittal of Collins Aerospace Service Bulletin ALT-4000-34-14, Navigation - ALT 4000 Power Supply Robustness Improvement						RE (-)		Optional, Service Letter	
 34 A/F						Mos				
Eff: 17-Oct-2022 (AVG MAN HRS: 2.5)						Hrs				
						Ldg				
ICA-560XL-34-00010	Honeywell ADS-B Out (ICA Supplement)						RE (-)		Mandatory	
 34 A/F						Mos	22-Jun-2022			
Eff: 26-Apr-2016 Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			
ICA-560XL-34-00011	GH-3000/3900 Electronic Standby Instrument - System Update						T (A/R)		ICA Supplement	
 34 A/F						Mos				
Eff: 22-Mar-2018						Hrs				
						Ldg				
SB560XL-34-81	Navigation - FMS-3000 Flight Management System (FMS) Search and Rescue Upgrade						T (A/R)		Optional	
 34 A/F						Mos				
Eff: 17-Dec-2018						Hrs				
						Ldg				
Note: NOTE: Airplanes -6002, -6004 thru -6013, -6015 thru -6023, -6025 thru -6028, -6030, -6032 thru -6035 and -6037 thru -6044 must incorporate SB560XL-34-63 Navigation - XLS+ FMS 4.0 (WAAS) Upgrade and V-Speeds Database Installation prior to or in conjunction with this service bulletin.										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SB560XL-34-82	Navigation - Standby Flight Display (SFD) Weight on Wheels (WOW) Electrical Wiring Improvement						RE (-)		Recommended	
 34 A/F						Mos	10-Jul-2023			
Eff: 22-May-2023 Not Applicable	as per aircraft s/n					Hrs	556:05			
(AVG MAN HRS: 3.5)						Ldg	369			
SL560XL-34-01	Navigation - B-RNAV Operation Navigation System Approval						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 27-Jul-1998						Hrs				
						Ldg				
SL560XL-34-02	Reduced Vertical Separation Minimum (RVSM)						RE (-)		Optional	
 34 A/F						Mos				
						Hrs				
						Ldg				
SL560XL-34-02 Rev 01	Reduced Vertical Separation Minimum (RVSM)						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 01-Dec-2004						Hrs				
						Ldg				
SL560XL-34-04	Navigation - IC-600/IC-615 Integrated Avionics Computer Operational Check						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 17-Sep-2001						Hrs				
						Ldg				
SL560XL-34-05	Navigation - Transmittal of Meggitt Avionics Service Information Letter No. 17, Secondary Flight Displays Mark 2						RE (-)		Optional	
 34 A/F						Mos				
						Hrs				
						Ldg				
SL560XL-34-05 Rev 01	Navigation - Transmittal of Meggitt Avionics Service Information Letter No. 17, Secondary Flight Displays Mark 2						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 21-Dec-2001						Hrs				
						Ldg				
SL560XL-34-06	Navigation - TCAS Compatibility with RVSM Operations						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 17-Jul-2002						Hrs				
						Ldg				
SL560XL-34-08A	Navigation - Transmittal of Honeywell Technical Newsletter A23-3850-001						RE (-)		Mandatory	
 34 A/F						Mos	22-Jun-2022			
Eff: 17-Feb-2003 Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			
SL560XL-34-10	Navigation - Pitot/Static Leak Check Update						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 21-Apr-2003						Hrs				
						Ldg				
SL560XL-34-14	Flux Valve Inspection Criteria						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 01-Apr-2004						Hrs				
						Ldg				
SL560XL-34-15	560XL Compass System Troubleshooting Procedures						T (A/R)		Informational	
 34 A/F						Mos				
Eff: 01-Apr-2004						Hrs				
						Ldg				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-34-21	Operational Compliance Summary for EASA Temporary Guidance Leaflet (TGL) -36 Approval of Electronic Flight Bags (EFB) for the Rockwell Collins Integrated Flight Information System (IFIS)						T (A/R)		Informational	
 34 A/F Eff: 25-Feb-2009						Mos				
						Hrs				
						Ldg				
SL560XL-34-25	Navigation - Transmittal of Rockwell Collins Service Information Letter 16-1 - Function of Reset Override Mode Switch on XM Weather Receiver for Proline 21/Proline Fusion						RE (-)		Informational	
 34 A/F Eff: 22-Jun-2016						Mos				
						Hrs				
						Ldg				
SL560XL-34-26	Navigation - 822-2189-100 GPS-4000S SB15 Update						RE (-)	Recommended, Service Letter		
 34 A/F Eff: 13-Mar-2019 Not Applicable (AVG MAN HRS: 2)	effective before manufacture					Mos	22-Jun-2022			
						Hrs	8			
						Ldg	6			
SL560XL-34-27	Navigation - GPS-4000S Global Positioning System Software Update						RE (-)	Recommended		
 34 A/F Eff: 19-Aug-2020 Not Applicable	by aircraft S/N					Mos	22-Jun-2022			
						Hrs	8			
						Ldg	6			
SL560XL-34-27 R1	Navigation - GPS-4000s Global Positioning System Software Update						RE (-)	Recommended, Service Letter		
 34 A/F Eff: 15-Mar-2021 Not Applicable	by aircraft S/N					Mos	22-Jun-2022			
						Hrs	8			
						Ldg	6			
SL560XL-34-27 R2	Navigation - GPS-4000s Global Positioning System Software Update						RE (-)	Mandatory		
 34 A/F Eff: 06-Oct-2021 Not Applicable	by aircraft S/N					Mos	22-Jun-2022			
						Hrs	8			
						Ldg	6			
SL560XL-34-29	Navigation - Implement Airplane Flight Manual (AFM) Changes						RE (-)	Mandatory, Service Letter		
 34 A/F Eff: 01-Sep-2020 Not Applicable (AVG MAN HRS: 0.5)	by aircraft S/N					Mos	22-Jun-2022			
						Hrs	8			
						Ldg	6			
SL560XL-34-30	Navigation - Transmittal of Collins Aerospace Service Bulletin FGC-3XXX-22-AA - Pitch Trim Failure and/or Chatter at Start-Up						T (A/R)		Optional	
 34 A/F Eff: 26-Sep-2022						Mos				
						Hrs				
						Ldg				
Note: EFFECTIVITIY: 560XL (XLS+) 560-6001 thru 560-6044, that have incorporated SB 560XL-34-63.										
SL560XL-53-20	Fuselage - Instrument Panel Support Fastener Verification						RE (-)	Recommended		
 34 A/F Eff: 03-Dec-2018 Not Applicable (AVG MAN HRS: 14)	effective before manufacture					Mos	22-Jun-2022			
						Hrs	8			
						Ldg	6			
▼ 35 - OXYGEN										
	Crew Mask and Stowage Boxe						RE (O/C)			
 35 A/F Unknown Unknown	Copilot					Mos	22-Jun-2022			
						Hrs	0			
						Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
Crew Mask and Stowage Box										
35 A/F	Pilot						RE (O/C)			
Unknown						Mos	22-Jun-2022			
Unknown						Hrs	0			
						Ldg	0			
Oxygen Bottle Assembly										
35 A/F							RE	Regulatory Inspections/Time Limits		
804882-14						Mos	06-Jun-2022	180	31-Aug-2036	11.9 Years
C21080835						Hrs				
						Ldg				
Manufactured Date 20-Aug-2021										
Ref:35-90-00-9600 (SOURCE: 560 XL MM Section 5-13-00)										
Note: NOTE: The Oxygen Bottle Assembly is manufactured Under U.S. DOT-SP 8162.										
Oxygen Charging Valve										
35 A/F							RE (O/C)			
Unknown						Mos	22-Jun-2022			
Unknown						Hrs	0			
						Ldg	0			
Oxygen Dropout Box										
35 A/F	No.1						RE (O/C)			
Unknown						Mos	22-Jun-2022			
Unknown						Hrs	0			
						Ldg	0			
Oxygen Dropout Box										
35 A/F	No.2						RE (O/C)			
Unknown						Mos	22-Jun-2022			
Unknown						Hrs	0			
						Ldg	0			
Oxygen Dropout Box										
35 A/F	No.3						RE (O/C)			
Unknown						Mos	22-Jun-2022			
Unknown						Hrs	0			
						Ldg	0			
Oxygen Dropout Box										
35 A/F	No.4						RE (O/C)			
Unknown						Mos	22-Jun-2022			
Unknown						Hrs	0			
						Ldg	0			
Oxygen Dropout Box										
35 A/F	No.5						RE (O/C)			
Unknown						Mos	22-Jun-2022			
Unknown						Hrs	0			
						Ldg	0			
Oxygen Dropout Box										
35 A/F	No.6						RE (O/C)			
Unknown						Mos	22-Jun-2022			
Unknown						Hrs	0			
						Ldg	0			
Oxygen Mask										
35 A/F	Copilot						RE (O/C)			
MC10-16-150	New					Mos	24-May-2022			
B179178						Hrs				
						Ldg	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	35 A/F MC10-16-150 B178643	Oxygen Mask Pilot New					Mos	24-May-2022		RE (O/C)	
							Hrs				
							Ldg				
	35 A/F C668512-0101 M21-12452	Oxygen Pressure (EI002) Gage					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	35 A/F C668512-0101 A22-12946	Oxygen Pressure Gauge					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	35 A/F 804881-01 C21070842	Oxygen Regulator					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	35 A/F P24032 D19090017	Passenger Oxygen Altitude Pressure Switch					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	35 A/F P21006 R21120106	Passenger Oxygen Control Valve					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	35 A/F Unknown Unknown Ref:35-90-00-9601 (SOURCE: 560 XL MM Section 5-13-00)	Portable Oxygen Bottle					Mos			RE (O/C) Regulatory Inspections/Time Limits	
							Hrs				
							Ldg				
	35 A/F MR-10051N E2106778 Manufactured Date 28-Feb-2022 Ref:35-30-00-9600 (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) Note: NOTE:Per Supplier Recommendation. Reference EROS (Air Liquid) 35-32- 17 Component Maintenance Manual With IPC or AVOX Component Maintenance Manual With IPC	Protective Breathing Equipment					Mos	16-Jun-2022		120	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS 28-Feb-2032 7.4 Years
							Hrs				
							Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
2023-13-11 Oxygen - AVOX Systems Inc. (Formerly Scott Aviation) Oxygen Cylinder and Valve Assemblies (Supersedes FAA AD 2022-04-09)										
35 A/F						Days	08-Aug-2023		RE (-)	Mandatory (Appliance AD)
Eff: 05-Sep-2023 Not Applicable	as per P/Ns installed					Hrs	616:39			
(ISSUING AUTHORITY: FAA)						Ldg	407			
Note: APPLICABILITY: This AD applies to AVOX Systems Inc. (formerly Scott Aviation) oxygen cylinder and valve assemblies having part number (P/N) 89794077, 89794015, 891511-14, 806835-01, 807982-01, 808433-01, or 891311-14; and oxygen valve assemblies (body and gage assemblies) having P/N 807206-01. These assemblies might be installed on, but not limited to, the aircraft identified in paragraphs (c)(1) through (12) of this AD, certificated in any category.										
COMPLIANCE: Within 60 days after the effective date of this AD, inspect the oxygen valve assemblies, and oxygen cylinder and valve assemblies, to determine if the serial numbers of the valve, cylinder, and entire assembly, are listed in Appendix 1 or Appendix 2, "Affected Shipments," of the applicable service information identified in paragraphs (h)(1) through (3) of this AD. A review of airplane maintenance records is acceptable in lieu of this inspection if the serial numbers can be conclusively determined from that review.										
35-10-00-2200 Crew Mask and Stowage Box Detailed Inspection										
35 A/F	Copilot5-12-06					Mos			RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS
Unknown						Hrs	48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
Unknown						Ldg				
(ZONE: 245) (SOURCE: 560 XL MM Section 5-10-02)										
35-10-00-2200 Crew Mask and Stowage Box Detailed Inspection										
35 A/F	Pilot5-12-06					Mos			RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS
Unknown						Hrs	48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
Unknown						Ldg				
(ZONE: 246) (SOURCE: 560 XL MM Section 5-10-02)										
35-10-00-9600 MC10-16-150, MC10-16-100 or MLD20- 505 Crew Mask (Accomplish Supplier Testing and Fault Isolation Task) Restoration										
35 A/F	Copilot					Mos	24-May-2022	72	RE	05-10-01, 05-10-02, Category 8
MC10-16-150						Hrs				31-May-2028
B179178						Ldg				3.6 Years
Restored Date 24-May-2022										
MRBR Task:35-10-00-902, MRBR Task:35-10-00-901 (ZONE: 245) (SOURCE: 560XL MM)										
Note: Tracked by Component Time Limits.										
NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored MC10-16-150, MC10-16-100, or MLD20-505 Crew Mask and/or reference EROS (Intertechnique) 35-13-63 (MC10- 16-150 and MC10-16-100) and 35-13-64 (MLD20-505) Component Maintenance Manual and IPL.										
35-10-00-9600 MC10-16-150, MC10-16-100 or MLD20- 505 Crew Mask (Accomplish Supplier Testing and Fault Isolation Task) Restoration										
35 A/F	Pilot					Mos	24-May-2022	72	RE	05-10-01, 05-10-02, Category 8
MC10-16-150						Hrs				31-May-2028
B178643						Ldg				3.6 Years
Restored Date 24-May-2022										
MRBR Task:35-10-00-902, MRBR Task:35-10-00-901 (ZONE: 246) (SOURCE: 560XL MM)										
Note: Tracked by Component Time Limits.										
NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored MC10-16-150, MC10-16-100, or MLD20-505 Crew Mask and/or reference EROS (Intertechnique) 35-13-63 (MC10- 16-150 and MC10-16-100) and 35-13-64 (MLD20-505) Component Maintenance Manual and IPL.										
35-20-00-2200 Passenger Drop Box and Mask Assembly Detailed Inspection										
35 A/F	No.15-12-06					Mos			RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS
Unknown						Hrs	48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
Unknown						Ldg				
(ZONE: 171) (SOURCE: 560 XL MM Section 5-10-02)										
Note: NOTE: It is recommended you do this task at the same time as Task 35-20-00-7200										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
35-20-00-2200		Passenger Drop Box and Mask Assembly Detailed Inspection									
	35 A/F	No.25-12-06						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	Unknown					Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
	Unknown					Hrs					
		(ZONE: 172) (SOURCE: 560 XL MM Section 5-10-02)				Ldg					
		Note: NOTE: It is recommended you do this task at the same time as Task 35-20-00-7200									
35-20-00-2200		Passenger Drop Box and Mask Assembly Detailed Inspection									
	35 A/F	No.35-12-06						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	Unknown					Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
	Unknown					Hrs					
		(ZONE: 251) (SOURCE: 560 XL MM Section 5-10-02)				Ldg					
		Note: NOTE: It is recommended you do this task at the same time as Task 35-20-00-7200									
35-20-00-2200		Passenger Drop Box and Mask Assembly Detailed Inspection									
	35 A/F	No.45-12-06						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	Unknown					Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
	Unknown					Hrs					
		(ZONE: 252) (SOURCE: 560 XL MM Section 5-10-02)				Ldg					
		Note: NOTE: It is recommended you do this task at the same time as Task 35-20-00-7200									
35-20-00-2200		Passenger Drop Box and Mask Assembly Detailed Inspection									
	35 A/F	No.55-12-06						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	Unknown					Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
	Unknown					Hrs					
		(ZONE: 261) (SOURCE: 560 XL MM Section 5-10-02)				Ldg					
		Note: NOTE: It is recommended you do this task at the same time as Task 35-20-00-7200									
35-20-00-2200		Passenger Drop Box and Mask Assembly Detailed Inspection									
	35 A/F	No.65-12-06						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	Unknown					Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
	Unknown					Hrs					
		(ZONE: 262) (SOURCE: 560 XL MM Section 5-10-02)				Ldg					
		Note: NOTE: It is recommended you do this task at the same time as Task 35-20-00-7200									
35-20-00-7100		Passenger Oxygen System Operational Check									
	35 A/F	5-12-03						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
						Mos	22-May-2024	24	-/+1m	(31-May-2026)	1.6 Years (+30 Days)
						Hrs	1020:11				
		(ZONE: 171, 172, 235, 251, 252, 261, 262, 235) (SOURCE: 560 XL MM Section 5-10-02)				Ldg	698				
35-20-00-7200		Passenger Oxygen System Functional Check									
	35 A/F	5-12-06						RE	05-10-01, 05-10-02, Category 8, Category 9		
						Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
						Hrs					
		MRBR Task:21-30-00-702, MRBR Task:35-10-00-704, MRBR Task:35-10-00-705, MRBR Task:35-10-00-706, MRBR Task:35-10-00-707 (ZONE: 171, 172, 235, 251, 252, 261, 262) (SOURCE: 560XL MM)				Ldg					
		Note: NOTE: It is recommended you do this task at the same time as Task 35-20-00-2200									
35-30-00-2200		Optional Protective Breathing Equipment Detailed Inspection									
	35 A/F	5-12-01						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	MR-10051N					Mos	22-May-2024	12	-/+1m	(31-May-2025)	7.6 Months (+30 Days)
	E2106778					Hrs	1020:11				
		(ZONE: 245) (SOURCE: 560 XL MM Section 5-10-02)				Ldg	698				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
35-90-00-7800		Oxygen Bottle Assembly (Hydrostatic Test) Restoration								RE	Regulatory Inspections/Time Limits
	35 A/F	804882-14 C21080835 Hydrostatic Tested Date 20-Aug-2021 (SOURCE: 560 XL MM Section 5-13-00) Note: NOTE: The Oxygen Bottle Assembly is manufactured Under U.S. DOT-SP 8162.					Mos	06-Jun-2022	60	31-Aug-2026	1.9 Years
	Unknown						Hrs				
	Unknown						Ldg				
35-90-00-7801		Portable Oxygen Bottle Assembly (Hydrostatic Test) Restoration								RE (N/A)	Regulatory Inspections/Time Limits
	35 A/F	Unknown Unknown (SOURCE: 560 XL MM Section 5-13-00)					Mos				
	Unknown						Hrs				
	Unknown						Ldg				
CIL-35-02		Oxygen-Transmittal of Zodiac Aerotechnics Service Bulletin MC10-35-274								RE (-)	Mandatory
	35 A/F	Eff: 12-Jun-2015 Not Applicable by aircraft S/N					Mos	22-Jun-2022			
							Hrs	8			
							Ldg	6			
CIL-35-05		Oxygen - Transmittal of Zodiac Aerospace Service Bulletin MCF-35-001								RE (-)	Mandatory
	35 A/F	Eff: 08-Jan-2016 Not Applicable (AVG MAN HRS: 3) Note: All Citation Models with flight crew oxygen mask regulators, having P/N MC10, MF10, MF20 series with S?N as listed in Zodiac Aerospace SB MCF-SBU-35-001					Mos	22-Jun-2022			
							Hrs	8			
							Ldg	6			
SB560XL-35-04		Oxygen - Oxygen System Pressure Switch Replacement for Chinese Registered Airplanes								T (A/R)	Optional
	35 A/F	Eff: 13-Aug-2018					Mos				
							Hrs				
							Ldg				
SL560XL-35-03		Transmittal of AVOX Systems Service Bulletin 36758-35-01								RE (-)	Recommended
	35 A/F	Eff: 23-Jul-2009 Not Applicable effective before manufacture					Mos	22-Jun-2022			
							Hrs	8			
							Ldg	6			
SL560XL-35-04		Transmittal of Intertechnique Service Bulletin MXH-35-240 Revision 2								RE (-)	Optional
	35 A/F						Mos				
							Hrs				
							Ldg				
SL560XL-35-04 Rev 01		Transmittal of Intertechnique Service Bulletin MXH-35-240 Revision 2								RE (-)	Optional
	35 A/F						Mos				
							Hrs				
							Ldg				
SL560XL-35-04 Rev 02		Transmittal of Intertechnique Service Bulletin MXH-35-240 Revision 2								RE (-)	Mandatory
	35 A/F	Eff: 25-Oct-2012 Not Applicable by aircraft S/N					Mos	22-Jun-2022			
							Hrs	8			
							Ldg	6			
▼ 36 - PNEUMATIC		APU Bleed Air Shutoff (VT004) Valve								RE (O/C)	
	36 A/F	Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	36 A/F 8C1045 3933	APU Check Valve						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	36 A/F 1E51-1 3BW95	Bleed Air Manifold Temperature (TT001) Sensor						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	36 A/F 1E51-1 3BW96	Bleed Air Manifold Temperature (TT002) Sensor						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	36 A/F 1173T181-2 9103	Bleed Air Overtemp (ST014) Switch						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	36 A/F 1173T181-2 9104	Bleed Air Overtemp (ST017) Switch						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	36 A/F Unknown Unknown	Bleed Air Temperature (ST020) Switch Right						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	36 A/F Unknown Unknown	Bleed Air Temperature (ST021) Switch Left						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	36 A/F 8C1045 3876	Bleed Air to Presurization Check Valve No.1						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	36 A/F 8C1045 3878	Bleed Air to Presurization Check Valve No.2						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	36 A/F 5035-00-1 3682	Door Solenoid Valve						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			
	36 A/F 8230-2 S4883T4014	Heat B/A Exchanger Left						RE (O/C)			
							Mos	22-Jun-2022			
							Hrs	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
 36 A/F 8230-2 S4883T3994	Heat B/A Exchanger Right						RE (O/C)			
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
 36 A/F 2340594-6 1792	Heat Exchanger Left						RE (O/C)			
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
 36 A/F Unknown Unknown	Heat Exchanger Right						RE (O/C)			
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
 36 A/F 1E50-2 1BW6	Heat Exchanger Actuator Left						RE (O/C)			
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
 36 A/F 1E50-2 4BW2	Heat Exchanger Actuator Right						RE (O/C)			
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
 36 A/F 1406-7 1144	Precooler VD003 Valve Left						RE (O/C)			
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
 36 A/F 1406-8 2197	Precooler VD003 Valve Right						RE (O/C)			
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
 36 A/F 8C1045 3879 (ZONE: .)	Rudder Bias Check Valve						RE (O/C)			
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
 36 A/F 1H75-18 12BV98	Service Air Regulator						RE (O/C)			
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
36-11-03-2100	Precooler Heat Exchanger General Visual Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 36 A/F 2340594-6 1792 (ZONE: 411) (SOURCE: 560 XL MM Section 5-10-02)	Left5-12-01						12	-/+1m (31-May-2025)	7.6 Months (+30 Days)	
					Mos	22-May-2024				
					Hrs	1020:11				
							Ldg	698		

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
36-11-03-2100	Precooler Heat Exchanger General Visual Inspection									
 36 A/F	Right5-12-01					Mos	22-May-2024	12	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	7.6 Months (+30 Days)
Unknown						Hrs	1020:11	-/+1m	(31-May-2025)	
Unknown						Ldg	698			
(ZONE: 412) (SOURCE: 560 XL MM Section 5-10-02)										
36-12-00-2200	Auxiliary Power Unit Bleed Air Check Valve Detailed Inspection									
 36 A/F	5-12-06					Mos		48	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	1.7 Years (+30 Days)
						Hrs		-/+1m	(30-Jun-2026)	
						Ldg				
(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02)										
36-15-00-1700	Particulate Trap (Cleaning) Restoration									
 36 A/F	5-12-06					Mos		48	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	1.7 Years (+30 Days)
						Hrs		-/+1m	(30-Jun-2026)	
						Ldg				
(ZONE: 171, 261) (SOURCE: 560 XL MM Section 5-10-02)										
▼ 38 - WATER/WASTE										
	Flush Switch								RE (O/C)	
 38 A/F						Mos	22-Jun-2022			
101001-904	New					Hrs	0			
1450222						Ldg	0			
38-30-02-2200	Externally Serviceable Toilet System Detailed Inspection									
 38 A/F	5-12-03					Mos	22-May-2024	24	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	1.6 Years (+30 Days)
15900-023						Hrs	1020:11	-/+1m	(31-May-2026)	
0502						Ldg	698			
(ZONE: 172, 170, 315) (SOURCE: 560 XL MM Section 5-10-02)										
Note: NOTE: It is recommended you do this task at the same time as Task 53-10-11-2200										
560XL-38-03	Toilet Override Relay Installation								RE (-)	Optional
 38 A/F						Mos				
Eff: 03-Mar-2014						Hrs				
						Ldg				
SL560XL-38-01	Transmittal of Monogram Systems Service Information Letter SIL 15900-023								RE (-)	Recommended
 38 A/F						Mos	22-Jun-2022			
Eff: 06-Jan-2011 Not	effective before manufacture					Hrs	8			
Applicable						Ldg	6			
▼ 44 - CABIN SYSTEMS										
442000	Wireless Media Server								RE (O/C)	
 44 A/F						Mos	30-Mar-2023			
DMS720-31	New					Hrs	380:19			
202300000006180						Ldg	262			
▼ 49 - AIRBORNE AUXILIARY POWER										
	APU Electronic Control								RE (O/C)	
 49 APU1						Mos	27-Dec-2021			
2119552-4						Hrs	0			
81-N0821						APUS	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	49 APU1 Unknown Unknown	APU Igniter Plug						RE (O/C)			
								Mos	27-Dec-2021		
								Hrs	0		
								APUS	0		
	49 APU1 70722450-1 21-162111-05155	Bearing, Roller, Cylindrical New						RE (O/C)			
								Mos	27-Dec-2021		
								Hrs	0		
								APUS	0		
	49 APU1 1413-19 1817	Bleed Air Shutoff Valve						RE (O/C)			
								Mos	27-Dec-2021		
								Hrs	0		
								APUS	0		
	49 APU1 Unknown Unknown	Compressor Rotor, Centrifugal						RE (O/C)			
								Mos	27-Dec-2021		
								Hrs	0		
								APUS	0		
	49 APU1 3613567-111 19-162053-43639	Compressor Rotor, Forging New						RE (O/C)			
								Mos	27-Dec-2021		
								Hrs	0		
								APUS	0		
	49 A/F MD144-3 L21-11588	DC Ammeter						RE (O/C)			
								Mos	22-Jun-2022		
								Hrs	0		
								Ldg	0		
	49 APU1 Unknown Unknown	Electrical Igniter Lead						RE (O/C)			
								Mos	27-Dec-2021		
								Hrs	0		
								APUS	0		
	49 APU1 3883900-1 2202609	Fuel Control Assembly New						RE (O/C)			
								Mos	12-Jul-2022		
			0				Hrs	15:40			
			0				APUS	43			
	49 APU1 Unknown Unknown	Fuel Filter						RE (O/C)			
								Mos	27-Dec-2021		
								Hrs	0		
								APUS	0		
	49 APU1 Unknown Unknown Brand CE:054906	Fuel Nozzle Assembly						RE (O/C)			
								Mos	27-Dec-2021		
								Hrs	0		
								APUS	0		
	49 APU1 Unknown Unknown	Fuel Shut-Off Valve						RE (O/C)			
								Mos	27-Dec-2021		
								Hrs	0		
								APUS	0		

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Hourmeter								RE (O/C)	
	49 A/F	Unknown Unknown					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Housing Assembly								RE (O/C)	
	49 APU1	New 3863409-6 21-1034-31477					Mos	27-Dec-2021			
							Hrs	0			
							APUS	0			
		Housing Assembly, Engine Compressor								RE (O/C)	
	49 APU1	New 3827449-1 Unknown					Mos	27-Dec-2021			
							Hrs	0			
							APUS	0			
		Ignition Unit								RE (O/C)	
	49 APU1	3888000-7 J21431103					Mos	27-Dec-2021			
							Hrs	0			
							APUS	0			
		Low Oil Pressure Switch								RE (O/C)	
	49 APU1	3876351-1 20-150241-02935					Mos	27-Dec-2021			
							Hrs	0			
							APUS	0			
		Lube Pump Assembly								RE (O/C)	
	49 APU1	New 3881825-1 P-494					Mos	27-Dec-2021			
							Hrs	0			
							APUS	0			
		Oil Level Switch								RE (O/C)	
	49 APU1	3876318-3 2116222102291					Mos	27-Dec-2021			
							Hrs	0			
							APUS	0			
		Overheat Detector								RE (O/C)	
	49 A/F	3001-212-1004/455-9 218592					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Power Section Assembly								RE (O/C)	
	49 APU1	New 3801116-1 6013259636					Mos	27-Dec-2021			
							Hrs	0			
							APUS	0			
		RPM/Max Indicator								RE (O/C)	
	49 A/F	MD680-4 F21-13034					Mos	22-Jun-2022			
							Hrs	0			
							Ldg	0			
		Seal Set, Compressor, Matched								RE (O/C)	
	49 APU1	New 70722248-1 00514					Mos	27-Dec-2021			
							Hrs	0			
							APUS	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	49 APU1 70722432-1 00349	Seal Set, Generator, Matched						RE (O/C)			
		New				Mos	27-Dec-2021				
						Hrs	0				
						APUS	0				
	49 APU1 66503-101165-001 21-272	Tee-Flow Divider Valve						RE (O/C)			
						Mos	27-Dec-2021				
						Hrs	0				
						APUS	0				
	49 APU1 3842338-1 Unknown	Tie Rod Turb Rotor						RE (O/C)			
		New				Mos	27-Dec-2021				
						Hrs	0				
						APUS	0				
	49 APU1 3883912-1 21-272	Torque motor, Fuel Control						RE (O/C)			
		New				Mos	27-Dec-2021				
						Hrs	0				
						APUS	0				
	49 APU1 3842305-111 20-156101-01488	Turbine Rotor, Radial-Investment Casti						RE (O/C)			
		New				Mos	27-Dec-2021				
						Hrs	0				
						APUS	0				
	49 APU1 3601509-5 MS2115049304599	Valve & Sleeve Assy Metering, Matched, FC						RE (O/C)			
		New				Mos	27-Dec-2021				
						Hrs	0				
						APUS	0				
3615880-49-8149		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUs						RE (-)		Recommended	
	49 APU1 Eff: 12-Jun-2015 Not Applicable	effective before manufacture					Mos	22-Jun-2022			
							Hrs	09:06			
							APUS	26			
3615880-49-8149 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUs						RE (-)		Recommended	
	49 APU1 Not Applicable	effective before manufacture					Mos	22-Jun-2022			
							Hrs	09:06			
							APUS	26			
3615880-49-8149 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUs						RE (-)		Recommended	
	49 APU1 Not Applicable	effective before manufacture					Mos	22-Jun-2022			
							Hrs	09:06			
							APUS	26			
3615880-49-8149 Rev 3		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUs						RE (-)		Recommended	
	49 APU1 Eff: 15-Dec-2017 Not Applicable (AVG MAN HRS: 1.5)	effective before manufacture					Mos	22-Jun-2022			
							Hrs	09:06			
							APUS	26			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
3822101-49-8148 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, P/N 3822101-1, on Multiple APU's						RE (-)		Recommended	
	49 APU1						Mos	22-Jun-2022			
	Eff: 20-Oct-2015 Not Applicable	effective before manufacture					Hrs	09:06			
							APUS	26			
3881800-49-7523		Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS						RE (-)		Recommended	
	49 APU1						Mos	22-Jun-2022			
	Eff: 01-Feb-2000 Not Applicable	effective before manufacture					Hrs	09:06			
	(AVG MAN HRS: 2)						APUS	26			
3881800-49-7523 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS						RE (-)		Recommended	
	49 APU1						Mos	22-Jun-2022			
	Eff: 05-May-2000 Not Applicable	effective before manufacture					Hrs	09:06			
	(AVG MAN HRS: 2)						APUS	26			
3881800-49-7523 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS						RE (-)		Recommended	
	49 APU1						Mos	22-Jun-2022			
	Eff: 26-Oct-2001 Not Applicable	effective before manufacture					Hrs	09:06			
	(AVG MAN HRS: 2)						APUS	26			
3881800-49-7523 Rev 3		Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS						RE (-)		Recommended	
	49 APU1						Mos	22-Jun-2022			
	Eff: 22-Feb-2002 Not Applicable	effective before manufacture					Hrs	09:06			
	(AVG MAN HRS: 2)						APUS	26			
3881800-49-7523 Rev 4		Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS						RE (-)		Recommended	
	49 APU1						Mos	22-Jun-2022			
	Eff: 30-Oct-2014 Not Applicable	effective before manufacture					Hrs	09:06			
	(AVG MAN HRS: 2)						APUS	26			
3883900-49-7976		Airborne Auxiliary Power - Main Fuel Control Unit (FCU) - Check Nameplate for Latest Change Number. Install Fuel Flow Deflector, PN 70720001-1, on the Fuel Control Differential Pressure (Delta P) Sleeve as Required at Next Auxiliary Power Unit (APU) Shop Visit						RE (-)		Recommended	
	49 APU1						Mos	22-Jun-2022			
	Eff: 25-Feb-2009 Not Applicable	effective before manufacture					Hrs	09:06			
	(AVG MAN HRS: 1)						APUS	26			
3883900-49-7976 Rev 1		Airborne Auxiliary Power - Main Fuel Control Unit (FCU) - Check Nameplate for Latest Change Number. Install Fuel Flow Deflector, PN 70720001-1, on the Fuel Control Differential Pressure (Delta P) Sleeve as Required at Next Auxiliary Power Unit (APU) Shop Visit						RE (-)		Recommended	
	49 APU1						Mos	22-Jun-2022			
	Eff: 10-Apr-2009 Not Applicable	effective before manufacture					Hrs	09:06			
	(AVG MAN HRS: 1)						APUS	26			
3883900-49-7976 Rev 2		Airborne Auxiliary Power - Main Fuel Control Unit (FCU) - Check Nameplate for Latest Change Number. Install Fuel Flow Deflector, PN 70720001-1, on the Fuel Control Differential Pressure (Delta P) Sleeve as Required at Next Auxiliary Power Unit (APU) Shop Visit						RE (-)		Recommended	
	49 APU1						Mos	22-Jun-2022			
	Eff: 11-May-2019 Not Applicable	effective before manufacture					Hrs	09:06			
	(AVG MAN HRS: 1)						APUS	26			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
3883900-49-8297	Airborne Auxiliary Power - Gas Turbine Engine - Replace Oil Seal, PN 3883905-1, with PN 70722907-1 on the Fuel Control Unit (FCU), PN 3883900-1 for the RE100 APU						RE (-)		Recommended	
 49 APU1					Mos	22-Jun-2022				
Eff: 24-Feb-2020 Not Applicable	effective before manufacture				Hrs	09:06				
					APUS	26				
Note: COMPLIANCE: This service bulletin, recommended by Honeywell, is done on an attritional basis, oil seal to be replaced if a high leakage rate is present.										
49-00-00-2100	Auxiliary Power Unit General Visual Inspection and Operational Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 49 A/F	5-12-06				Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
					Hrs					
(ZONE: 322) (SOURCE: 560 XL MM Section 5-10-02)					Ldg					
Note: NOTE: It is recommended you do this task at the same time as Tasks 53-10-12-2100, 53-10-12-2102, 53-10-12-2103, 53-10-12-2104, and 53-10-12-2200										
49-00-00-2103	Auxiliary Power Unit Containment Box Assembly General Visual Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 49 A/F	5-12-13				Mos		72	-/+1m	(30-Jun-2028)	3.7 Years (+30 Days)
					Hrs					
(ZONE: 312) (SOURCE: 560 XL MM Section 5-10-02)					Ldg					
49-00-00-9600	Compressor Rotor Disk Discard						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈10-Mar-2058
 49 APU1					Mos	27-Dec-2021				
70722359-1		0			Hrs	0				
19-162053-42639		0			APUS	0	12,000		12,000	11,957 APUS
MRBR Task:49-01-00-902 (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00, 5-18-00)										
Note: NOTE: Per Supplier Recommendation. Reference Honeywell 49-25-85 RE100 (XL) Maintenance Manual.										
49-00-00-9601	Turbine Rotor Disk Discard						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈30-Apr-2034
 49 APU1					Mos	27-Dec-2021				
70722360-1					Hrs	0				
20-156101-01488		0			APUS	0	4,000		4,000	3,957 APUS
MRBR Task: 49-01-00-903 (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00, 5-18-00)										
Note: NOTE: Per Supplier Recommendation. Reference Honeywell 49-25-85 RE100 (XL) Maintenance Manual.										
492040-0101	Bearing Ball Anlr						RE (O/C)			
 49 APU1					Mos	27-Dec-2021				
3822570-1	New				Hrs	0				
21-162255-16488					APUS	0				
49-30-00-9600	Auxiliary Power Unit Fuel Filter Element Discard						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 49 APU1					Mos	22-May-2024	24		31-May-2026	1.6 Years
					Hrs	703:54	900		1603:54	680 Hrs
					APUS					
MRBR Task:49-01-00-901 (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00, 5-18-00)										
Note: NOTE: Per Supplier Recommendation. Reference Honeywell 49-25-85 RE100 (XL) Maintenance Manual.										
49-30-00-9600-AF	Auxiliary Power Unit Fuel Filter Element Discard						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 49 A/F					Mos	22-May-2024	24		31-May-2026	1.6 Years
					Hrs	1020:11				
					Ldg	698				
MRBR Task:49-01-00-901 (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00, 5-18-00)										
Note: NOTE: Per Supplier Recommendation. Reference Honeywell 49-25-85 RE100 (XL) Maintenance Manual.										
					Hrs (APU)	703:54	900		1603:54	680 Hrs(APU)

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
49-40-00-2200	Auxiliary Power Unit Igniter Plug Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 49 APU1					Mos	22-May-2024	24		31-May-2026	1.6 Years
Unknown					Hrs	703:54	900		1603:54	680 Hrs
Unknown					APUS					
MRBR Task:49-01-00-201 (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00, 5-18-00)										
Note: NOTE: Per Supplier Recommendation. Reference Honeywell 49-25-85 RE100 (XL) Maintenance Manual.										
49-70-01-2200	Auxiliary Power Unit Magnetic Chip Collector Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 49 APU1					Mos	22-May-2024	12		31-May-2025	7.6 Months
					Hrs	703:54	450		1153:54	230 Hrs
					APUS					
MRBR Task:49-01-00-202 (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00, 5-18-00)										
Note: NOTE: Per Supplier Recommendation. Reference Honeywell 49-25-85 RE100 (XL) Maintenance Manual.										
49-70-01-2200-AF	Auxiliary Power Unit Magnetic Chip Collector Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈22-May-2025
 49 A/F					Mos	22-May-2024	12		31-May-2025	7.6 Months
					Hrs	1020:11				
					Ldg	698				
MRBR Task:49-01-00-202 (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00, 5-18-00)										
Note: NOTE: Per Supplier Recommendation. Reference Honeywell 49-25-85 RE100 (XL) Maintenance Manual.										
					Hrs (APU)	703:54	450		1153:54	230 Hrs(APU)
49-7933	Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						RE (-)			
 49 APU1					Mos					
Eff: 24-Apr-2007					Hrs					
					APUS					
49-7933 Rev 1	Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						RE (-)		Service Bulletin	
 49 APU1					Mos					
Eff: 04-Jun-2007					Hrs					
					APUS					
49-7933 Rev 10	Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						T (A/R)		Service Bulletin	
 49 APU1					Mos					
Eff: 18-Jan-2022					Hrs					
					APUS					
49-7933 Rev 2	Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						RE (-)		Service Bulletin	
 49 APU1					Mos					
Eff: 09-Apr-2010					Hrs					
					APUS					
49-7933 Rev 3	Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						RE (-)		Service Bulletin	
 49 APU1					Mos					
Eff: 31-Oct-2011					Hrs					
					APUS					
49-7933 Rev 4	Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						RE (-)		Service Bulletin	
 49 APU1					Mos					
Eff: 12-Aug-2014					Hrs					
					APUS					
49-7933 Rev 5	Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						T (-)		Service Bulletin	
 49 APU1					Mos					
Eff: 23-Oct-2014					Hrs					
					APUS					
49-7933 Rev 6	Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						RE (-)		Service Bulletin	
 49 APU1					Mos					
					Hrs					
					APUS					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
49-7933 Rev 7	Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						T (-)		Service Bulletin	
 49 APU1										
Eff: 09-Feb-2017										
49-7933 Rev 8	Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						T (-)		Service Bulletin	
 49 APU1										
Eff: 27-Jul-2017										
49-7933 Rev 9	Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils						T (-)		Service Bulletin	
 49 APU1										
Eff: 03-Apr-2020										
49-7992	Remove and Replace Electronic Control Unit, PN 2119552-2 or PN 2119552-3, with Electronic Control Unit, PN 2119552-4						RE (-)		Optional	
 49 APU1										
49-7992 Rev 1	Remove and Replace Electronic Control Unit, PN 2119552-2 or PN 2119552-3, with Electronic Control Unit, PN 2119552-4						RE (-)		Optional	
 49 APU1										
49-7997	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines						RE (-)		Service Bulletin	
 49 APU1										
Eff: 16-Sep-2009										
49-7997 Rev 1	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines						RE (-)		Service Bulletin	
 49 APU1										
Eff: 11-Feb-2010										
49-7997 Rev 2	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines						RE (-)		Service Bulletin	
 49 APU1										
Eff: 22-Dec-2010										
49-7997 Rev 3	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines						RE (-)		Service Bulletin	
 49 APU1										
Eff: 16-Jan-2014										
49-7997 Rev 4	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines						T (-)		Service Bulletin	
 49 APU1										
Eff: 12-Jan-2015										
49-7997 Rev 5	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines						T (-)		Service Bulletin	
 49 APU1										
Eff: 03-Feb-2017										
49-7997 Rev 6	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines						T (A/R)		Service Bulletin	
 49 APU1										
Eff: 05-Nov-2020										
49-8252	Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs						T (-)			
 49 APU1										
Eff: 31-Aug-2018										

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
49-8252 Rev 1	Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs						T (-)			
 49 APU1					Mos					
Eff: 07-Mar-2019					Hrs					
					APUS					
49-8252 Rev 2	Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs						T (A/R)		Service Bulletin	
 49 APU1					Mos					
Eff: 13-Oct-2020					Hrs					
					APUS					
49-90-00-9600	Auxiliary Power Unit Oil and Oil Filter Discard						RE	05-10-01, 05-10-02, Category 9		
 49 APU1					Mos	22-May-2024	24		31-May-2026	1.6 Years
					Hrs	703:54	900		1603:54	680 Hrs
	MRBR Task:49-01-00-904 (SOURCE: 560XL MM)				APUS					
	Note: NOTE: Per Supplier Recommendation. Reference Honeywell 49-25-85 RE100 (XL) Maintenance Manual.									
49-90-00-9600-AF	Auxiliary Power Unit Oil and Oil Filter Discard						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 49 A/F					Mos	22-May-2024	24		31-May-2026	1.6 Years
					Hrs	1020:11				
	MRBR Task:49-01-00-904 (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-12-00, 5-18-00)				Ldg	698				
	Note: NOTE: Per Supplier Recommendation. Reference Honeywell 49-25-85 RE100 (XL) Maintenance Manual.				Hrs (APU)	703:54	900		1603:54	680 Hrs(APU)
49-CUS-001	APU SOAP Sample						RE			≈08-Feb-2025
 49 A/F					Mos	16-Sep-2024				
					Hrs	1292:19	300		1592:19	232:23 Hrs
					Ldg	898				
					Hrs (APU)	703:54	500		1203:54	280 Hrs(APU)
 KGR-WP-011 START 21-JAN-2025										
560XL-49-17	Auxiliary Power - Auxiliary Power Unit Mount Bolt Change						RE (-)		Optional	
 49 A/F					Mos					
Eff: 05-Oct-2015					Hrs					
					Ldg					
70721597-49-8166	Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs						RE (-)		Recommended	
 49 APU1					Mos	22-Jun-2022				
Eff: 02-Jul-2015 Not Applicable	effective before manufacture				Hrs	09:06				
					APUS	26				
70721597-49-8166 Rev 1	Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs						RE (-)		Recommended	
 49 APU1					Mos	22-Jun-2022				
Eff: 31-Aug-2015 Not Applicable	effective before manufacture				Hrs	09:06				
					APUS	26				
70721597-49-8166 Rev 2	Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs						RE (-)		Recommended	
 49 APU1					Mos	22-Jun-2022				
Eff: 25-Oct-2016 Not Applicable	effective before manufacture				Hrs	09:06				
					APUS	26				
70721597-49-8166 Rev 3	Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs						RE (-)		Recommended	
 49 APU1					Mos	22-Jun-2022				
Eff: 13-Oct-2017 Not Applicable	effective before manufacture				Hrs	09:06				
	(AVG MAN HRS: 1)				APUS	26				
	Note: COMPLIANCE: Honeywell recommends this service bulletin be done for the balance repair of the compressor rotor, PN 70721597-1.									

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
70721598-49-8168		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs								RE (-)	Recommended
	49 APU1						Mos	22-Jun-2022			
	Eff: 02-Jul-2015 Not Applicable	effective before manufacture					Hrs	09:06			
							APUS	26			
70721598-49-8168 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs								RE (-)	Recommended
	49 APU1						Mos	22-Jun-2022			
	Eff: 20-Oct-2015 Not Applicable	effective before manufacture					Hrs	09:06			
							APUS	26			
70721598-49-8168 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs								RE (-)	Recommended
	49 APU1						Mos	22-Jun-2022			
	Eff: 10-Jan-2017 Not Applicable	effective before manufacture					Hrs	09:06			
							APUS	26			
70721598-49-8168 Rev 3		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs								RE (-)	Recommended
	49 APU1						Mos	22-Jun-2022			
	Eff: 14-Dec-2017 Not Applicable	effective before manufacture					Hrs	09:06			
	(AVG MAN HRS: 1)						APUS	26			
70721725-49-8152		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs								RE (-)	Recommended
	49 APU1						Mos	22-Jun-2022			
	Eff: 27-May-2015 Not Applicable	effective before manufacture					Hrs	09:06			
							APUS	26			
70721725-49-8152 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs								RE (-)	Recommended
	49 APU1						Mos	22-Jun-2022			
	Eff: 27-May-2015 Not Applicable	effective before manufacture					Hrs	09:06			
							APUS	26			
70721725-49-8152 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs								RE (-)	Recommended
	49 APU1						Mos	22-Jun-2022			
	Not Applicable	effective before manufacture					Hrs	09:06			
							APUS	26			
70721725-49-8152 Rev 3		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs								RE (-)	Recommended
	49 APU1						Mos	22-Jun-2022			
	Eff: 27-Nov-2017 Not Applicable	effective before manufacture					Hrs	09:06			
							APUS	26			
70721725-49-8152 Rev 4		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs								RE (-)	Recommended
	49 APU1						Mos	22-Jun-2022			
	Eff: 19-Dec-2017 Not Applicable	effective before manufacture					Hrs	09:06			
							APUS	26			
APU 1		Honeywell - RE100[XL]								RE (-)	
	49 A/F						Mos				
	3800722-1	Time at install:					Hrs				
	P-1131						Ldg				
D20110700024 Rev 1		Approved Use of Biofuel Blends for All Honeywell Commercial and Military Auxiliary Power Units (APU)								T (A/R)	Service Information Letter
	49 APU1						Mos				
	Eff: 03-Jun-2020						Hrs				
							APUS				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
D201112000050	Acceptance Criteria for On-Wing Borescope Inspections						RE (-)		Service Information Letter	
 49 APU1 Eff: 13-Jan-2012					Mos					
					Hrs					
					APUS					
D201112000050 Rev 1	Acceptance Criteria for On-Wing Borescope Inspections						T (A/R)		Service Information Letter	
 49 APU1 Eff: 14-Aug-2012					Mos					
					Hrs					
					APUS					
D201308000026	Uncommanded High Oil Temperature (HOT) Shutdown of the RE100[CS] and RE100[XL] AuxiliaryPower Units (APU)s						RE (-)		Service Information Letter	
 49 APU1 Eff: 10-Jan-2014					Mos					
					Hrs					
					APUS					
D201308000026 Rev 1	Uncommanded High Oil Temperature (HOT) Shutdown of the RE100[CS] and RE100[XL] AuxiliaryPower Units (APU)s						T (A/R)		Service Information Letter	
 49 APU1 Eff: 30-Mar-2016					Mos					
					Hrs					
					APUS					
D202207002674	Procedure to Determine if Hydro Pad Compressor Seal is Damaged and Evaluate if it was the Cause for Oil Leaks on the RE100 Series and 36-150 Series APU's						T (A/R)		Service Information Letter	
 49 APU1 Eff: 16-Aug-2022					Mos					
					Hrs					
					APUS					
	Note: EFFECTIVITY: Please see Par. B for more details.									
RE100-49-7400	Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, PN 3881739-2 with PN 3881800-1, Gearbox Housing, PN 3863409-4 with PN 3863409-2, and O-Ring, PN M83248/1-115 with PN M83248/1-116						RE (-)		Optional	
 49 APU1 Eff: 01-Feb-2000					Mos					
					Hrs					
					APUS					
RE100-49-7400 Rev 1	Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, Part No. 3881739-2 with Part No. 3881800-1, Gearbox Housing, Part No. 3863409-1/-2 with Part No. 3863409-3/-4 (Respectively), and O-ring, Part No. M83248/1-116 with Part No. M83248/1-115						T (A/R)		Optional	
 49 APU1 Eff: 14-Jun-2000					Mos					
					Hrs					
					APUS					
RE100-49-7465	Replace Thermocouple, Part No. 3876315-1						RE (-)		Recommended	
 49 APU1 Not Applicable	effective before manufacture				Mos	22-Jun-2022				
					Hrs	09:06				
					APUS	26				
RE100-49-7489	Airborne Auxiliary Power - Gas Turbine Engine - Replace Oil Filler Neck And Cap, PN 2A1126 (527-510-9001) With Oil Filler Neck and Dipstick Cap, PN 2A7732 (361-530-9354)						RE (-)		Optional	
 49 APU1 Eff: 02-Feb-2000					Mos					
					Hrs					
					APUS					
RE100-49-7530	Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, PN 3881800-1 with PN 3881825-1						RE (-)		Recommended	
 49 APU1 Eff: 01-Feb-2000 Not Applicable	effective before manufacture				Mos	22-Jun-2022				
					Hrs	09:06				
					APUS	26				
RE100-49-7530 Rev 1	Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, PN 3881800-1 with PN 3881825-1						RE (-)		Recommended	
 49 APU1 Not Applicable	effective before manufacture				Mos	22-Jun-2022				
					Hrs	09:06				
					APUS	26				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description									Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
	RE100-49-7530 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, PN 3881800-1 with PN 3881825-1									
	49 APU1						Mos	22-Jun-2022		RE (-)	Recommended	
	Eff: 22-Feb-2002 Not Applicable	effective before manufacture					Hrs	09:06				
							APUS	26				
	RE100-49-7535		Airborne Auxiliary Power - Gas Turbine Engine - Replace Flow Divider Tee, PN 3883921-1 with PN 3883921-2									
	49 APU1						Mos	22-Jun-2022		RE (-)	Recommended	
	Eff: 01-Oct-1999 Not Applicable	effective before manufacture					Hrs	09:06				
							APUS	26				
	RE100-49-7563		Airborne Auxiliary Power - Gas Turbine Engine - Replace Generator Seal, PN 3863387-1 with PN 3863504-1									
	49 APU1						Mos	22-Jun-2022		RE (-)	Recommended	
	Eff: 11-May-2000 Not Applicable	effective before manufacture					Hrs	09:06				
							APUS	26				
	RE100-49-7563 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Replace Generator Seal, PN 3863387-1 with PN 3863504-1									
	49 APU1						Mos	22-Jun-2022		RE (-)	Recommended	
	Eff: 22-May-2002 Not Applicable	effective before manufacture					Hrs	09:06				
							APUS	26				
	RE100-49-7773		Replace Electronic Control Unit (ECU), Part No. 2119552-2 with Part No. 2119552-3									
	49 APU1						Mos			RE (-)		
							Hrs					
							APUS					
	RE100-49-7787		Replace Low Oil Level Switch, Part No. 3876318-1 with Part No. 3876318-2									
	49 APU1						Mos			RE (-)	Optional	
	Eff: 21-Jun-2004						Hrs					
							APUS					
	RE100-49-7855		Replace Low Oil Level Switch, Part No. 3876318-1 or Part No. 3876318-2 with Part No. 3876318-3									
	49 APU1						Mos			RE (-)	Optional	
	Eff: 09-Aug-2005						Hrs					
							APUS					
	RE100-49-7896		Replace Oil Filler Neck and Cap									
	49 APU1						Mos			RE (-)	Optional	
							Hrs					
							APUS					
	RE100-49-7896 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Replace Oil Filler Neck and (Dipstic) Cap, P/N 361-530-9354									
	49 APU1						Mos			T (A/R)	Optional	
							Hrs					
							APUS					
	RE100-49-8139		Airborne Auxiliary Power - Gas Turbine Engine - Increase the Installation Torque and add the Use of Locking Compound During Carbon Seal Assembly on the RE100 APU									
	49 APU1						Mos	22-Jun-2022		RE (-)	Recommended	
	Eff: 15-Aug-2014 Not Applicable	effective before manufacture					Hrs	09:06				
							APUS	26				
	RE100-49-8250		Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Module, PN 3881825-1 with PN 3881825-2, for the RE100[CS] and RE100[XL] Auxiliary Power Unit (APU)									
	49 APU1						Mos			RE (-)		
	Eff: 11-Sep-2017						Hrs					
							APUS					

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
RE100-49-8250 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Module, PN 3881825-1 with PN 3881825-2 for the RE100[CS] and RE100[XL] Auxiliary Power Unit (APU)						RE (-)			
	49 APU1										
	Eff: 15-Jun-2018										
RE100-49-8250 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Module, PN 3881825-1 with PN 3881825-2, for the RE100[CS] and RE100[XL] Auxiliary Power Unit (APU)						RE (-)		Service Bulletin	
	49 APU1										
	Eff: 30-Oct-2020										
RE100-49-8303		Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)						RE (-)		Optional	
	49 APU1										
	Eff: 24-Feb-2020										
RE100-49-8303 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)						RE (-)		Optional	
	49 APU1										
	Eff: 01-Jul-2020										
RE100-49-8303 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)						RE (-)		Optional	
	49 APU1										
	Eff: 28-Aug-2020										
RE100-49-8303 Rev 3		Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)						RE (-)		Optional	
	49 APU1										
	Eff: 01-Sep-2020										
RE100-49-8303 Rev 4		Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)						RE (-)		Optional	
	49 APU1										
	Eff: 18-May-2022										
RE100-49-8360 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet PN M24243/6A401H with PN 627-504-9209 on Engines RE100[CS], RE100[LJ], and RE100[XL]						RE (-)		Cat. 2 - Recommended	
	49 APU1										
	Eff: 23-Feb-2022 Not Applicable	effective before manufacture					22-Jun-2022				
	(AVG MAN HRS: 1)						09:06				
RE100-49-8360 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet PN M24243/6A401H with PN 627-504-9209 on RE100 Engine Models						RE (-)		Cat. 2 - Recommended	
	49 APU1										
	Eff: 29-Mar-2022 Not Applicable	effective before manufacture					22-Jun-2022				
	(AVG MAN HRS: 1)						09:06				
RE100-49-8363		Airborne Auxiliary Power - Gas Turbine Engine - Replace Inlet Housing PN 3810880-1/-2 with PN 70724596-1 or PN 70724596-2, Gearbox Housing PN 3863409-6 with PN 70724597-1, Gearbox Housing PN 3863409-5 with PN 70724597-2 and Gearbox Housing PN 3863409-4 with PN 70724597-3 on the RE100 Auxiliary Power Unit (APU)						RE (-)		Optional	
	49 APU1										
	Eff: 10-May-2022										

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
RE100-49-8363 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Replace Inlet Housing PN 3810880-1/-2 with PN 70724596-1 or PN 70724596-2, Gearbox Housing PN 3863409-6 with PN 70724597-1, Gearbox Housing PN 3863409-5 with PN 70724597-2 and Gearbox Housing PN 3863409-4 with PN 70724597-3 on the RE100 Auxiliary Power Unit (APU)						T (A/R)		Optional	
	49 APU1										
	Eff: 04-Aug-2022										
		Note: EFFECTIVITY: Refer to Par. 1.A. of this SB for more information.									
SIL APU-152		Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel						RE (-)		Service Information Letter	
	49 APU1										
	Eff: 18-Jul-2008										
SIL APU-152 Rev 1		Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel						RE (-)		Service Information Letter	
	49 APU1										
	Eff: 24-Jul-2009										
SIL APU-152 Rev 2		Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel						RE (-)		Service Information Letter	
	49 APU1										
	Eff: 30-Nov-2010										
SIL APU-152 Rev 3		Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel						RE (-)		Service Information Letter	
	49 APU1										
	Eff: 19-Feb-2015										
SIL APU-152 Rev 4		Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel						T (A/R)		Service Information Letter	
	49 APU1										
	Eff: 08-Feb-2018										
SIL APU-7		Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)						RE (-)		Service Information Letter	
	49 APU1										
SIL APU-7 Rev 1		Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)						RE (-)		Service Information Letter	
	49 APU1										
	Eff: 03-Mar-1988										
SIL APU-7 Rev 2		Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)						T (A/R)		Service Information Letter	
	49 APU1										
	Eff: 02-Mar-2015										
SIL APU-95 Rev 1		Uncommanded Protective Shutdown of the Auxiliary Power Unit (APU) with High Oil Temperature (HOT) Identified						RE (-)		Cancelled	
	49 APU1										
	Eff: 13-Jul-2020										
SIL D201701000026		Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine Worksheet for 36-100, 36-150, RE100, and RE220 APUs						RE (-)		Service Information Letter	
	49 APU1										
	Eff: 30-Jan-2017										

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
 SIL D201701000026 Rev 1 49 APU1 Eff: 23-Jan-2018	Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine Worksheet for 36-100, 36-150, RE100, and RE220 APUs						T (-)		Service Information Letter	
					Mos					
					Hrs					
					APUS					
 SIL D201701000026 Rev 2 49 APU1 Eff: 21-Mar-2018	Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine worksheet for 36-100, 36-150, RE100, and RE220 APUs						T (A/R)		Service Information Letter	
					Mos					
					Hrs					
					APUS					
 SIL No. APU-49 Rev 10 49 APU1	Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)						RE (-)		Service Information Letter	
					Mos					
					Hrs					
					APUS					
	Note: COMPLIANCE: Every Aircraft 'A' check or every 500 APU hours or per AMM or MM criteria (customer option).									
 SIL No. APU-49 Rev 11 49 APU1	Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units(APUs)						RE (-)		Service Information Letter	
					Mos					
					Hrs					
					APUS					
	Note: Analyst/operator will need to manually set the calendar start. COMPLIANCE: Every Aircraft 'A' check or every 500 APU hours or per AMM or MM criteria (customer option).									
 SIL No. APU-49 Rev 12 49 APU1	Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)						RE (-)		Service Information Letter	
					Mos					
					Hrs					
					APUS					
	Note: COMPLIANCE: First and subsequent oil and filter sample. Every Aircraft 'A' check or every 500 APU hours or per AMM or MM criteria (customer option).									
 SIL No. APU-49 Rev 13 49 APU1 Eff: 23-Nov-2023	Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APU)						T (A/R)		Service Information Letter	
					Mos					
					Hrs					
					APUS					
 SIL No. APU-49 Rev 9 49 APU1	Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)						RE (-)		Service Information Letter	
					Mos					
					Hrs					
					APUS					
	Note: The SOAP and filter analysis program was initially limited to the operators of the GTCP36-100/-150 Series Auxiliary Power Units enrolled in the Honeywell Engines, Systems & Services APU Maintenance Service Plan (MSP). The program is now offered to all operators of the Honeywell GTCP36-100/-150, RE100 and RE220 Series APUs.									
 SL560XL-49-09 49 A/F Eff: 08-Apr-2011	Transmittal of Honeywell Service Bulletin RE100-49-7992 Airborne Auxiliary Power - Gas Turbine Engine - Remove and Replace Electronic Control Unit, PN 2119552-2 or PN 2119552-3, with Electronic Control Unit, PN 2119552-4						RE (-)		Informational	
					Mos					
					Hrs					
					Ldg					
 SL560XL-49-13 49 A/F Eff: 08-May-2018	Auxiliary Power - Transmittal of Honeywell Service Bulletin RE100-49-8250 Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Module, PN 3881825-1 with PN 3881825-2, for the RE100[CS] and RE100[XL] Auxiliary Power Unit (APU)						RE (-)		Informational, Service Letter	
					Mos					
					Hrs					
					Ldg					
 SL560XL-49-14 49 A/F Eff: 13-Mar-2023	Auxiliary Power - Transmittal of Honeywell Service Bulletin RE100-49-8364 Auxiliary Airborne - Gas Turbine Engine - Replace Wiring Harness PN 3888395-2 with PN 3888395-3 on the RE100[XL] Auxiliary Power Unit (APU)						T (A/R)		Optional	
					Mos					
					Hrs					
					Ldg					

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
▼ 52 - DOORS												
	52 A/F Unknown Unknown	Acoustic Lower Aft Seal						RE (O/C)				
							Mos	22-Jun-2022				
							Hrs	0				
							Ldg	0				
	52 A/F Unknown Unknown	Acoustic Lower Fwd Seal						RE (O/C)				
							Mos	22-Jun-2022				
							Hrs	0				
							Ldg	0				
	52 A/F Unknown Unknown	Acoustic Upper Seal						RE (O/C)				
							Mos	22-Jun-2022				
							Hrs	0				
							Ldg	0				
	52 A/F Unknown Unknown	Cabin Door - Vent Door Proximity Switch						RE (O/C)				
							Mos	22-Jun-2022				
							Hrs	0				
							Ldg	0				
	52 A/F Unknown Unknown	Cabin Door Primary Inflatable Pressure Seal						RE (O/C)				
							Mos	22-Jun-2022				
							Hrs	0				
							Ldg	0				
	52 A/F Unknown Unknown	Cabin Entrance Door Warning (SC046) Switch						RE (O/C)				
							Mos	22-Jun-2022				
							Hrs	0				
							Ldg	0				
	52 A/F 8-405-04 B85650	Emergency Exit Switch						RE (O/C)				
							Mos	22-Jun-2022				
							Hrs	0				
							Ldg	0				
12-20-52-6401		Door Keyed Cam Lock Lubrication						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	52 A/F (ZONE: 211, 212, 323, 331, 810, 811, 831) (SOURCE: 560 XL MM Section 5-10-02)	5-12-01					Mos	22-May-2024	12	-/+1m	(31-May-2025)	7.6 Months (+30 Days)
							Hrs	1020:11				
							Ldg	698				
52-10-00-2100		Cabin Door Seals General Visual Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
	52 A/F (ZONE: 810) (SOURCE: 560 XL MM Section 5-10-02)	5-12-01					Mos	22-May-2024	12	-/+1m	(31-May-2025)	7.6 Months (+30 Days)
							Hrs	1020:11				
							Ldg	698				
52-10-00-2200		Cabin Door Assembly Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS, MSG-3 Structures Inspection Tasks			
	52 A/F (ZONE: 810, 811) (SOURCE: 560 XL MM Section 5-10-02, 5-10-03) Note: NOTE: It is recommended you do this task at the same time as Task 12-20-52-6400	5-12-06					Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
							Hrs					
							Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
52-10-00-2200	Cabin Door Assembly Detailed Inspection.						RE		Airworthiness Limitations Inspection Time Limits	≈08-Oct-2043
 52 A/F	4-12-ME				Mos					
	(ZONE: 810, 811) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Hrs		15,000		(15000)	13640:04 Hrs
					Ldg					
52-20-00-2200	Emergency Exit Door Assembly Detailed Inspection and Operational Check						RE	05-10-01, 05-10-02, Category 6, Category 8, Category 9		
 52 A/F	5-12-03				Mos	22-May-2024	24	-/+1m	(31-May-2026)	1.6 Years (+30 Days)
	MRBR Task:52-20-00-201, MRBR Task:52-20-00-202, MRBR Task:52-20-00-203, MRBR Task:52-20-00-701, MRBR Task:52-20-00-702 (ZONE: 820, 821) (SOURCE: 560XL MM)				Hrs	1020:11				
					Ldg	698				
52-20-00-2200	Emergency Exit Door Assembly Detailed Inspection and Operational Check						RE	04-10-01, 04-10-02, Airworthiness Limitations Inspection Time Limits, Category 6, Category 8, Category 9		≈08-Oct-2043
 52 A/F	4-12-ME				Mos					
	MRBR Task:52-20-00-702, MRBR Task:52-20-00-701, MRBR Task:52-20-00-203, MRBR Task:52-20-00-202, MRBR Task:52-20-00-201 (ZONE: 820, 821) (SOURCE: 560XL MM)				Hrs		15,000		(15000)	13640:04 Hrs
					Ldg					
52-20-00-2201	Emergency Exit Door Internal Detailed Inspection						REMSG-3 Structures Inspection Tasks			
 52 A/F	5-12-16				Mos		96	-/+1m	(30-Jun-2030)	5.7 Years (+30 Days)
	(ZONE: 820) (SOURCE: 560 XL MM Section 5-10-03)				Hrs					
					Ldg					
52-30-00-2200	Baggage Door Assembly Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
 52 A/F	5-12-06				Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
	(ZONE: 830, 831) (SOURCE: 560 XL MM Section 5-10-02)				Hrs					
					Ldg					
SL560XL-52-07	Exterior Door Switch Improvement						RE (-)		Informational	
 52 A/F					Mos					
	Eff: 03-Mar-2011				Hrs					
					Ldg					
SL560XL-52-08	Doors - Cabin Door Lintel Fastener Verification						RE (-)		Recommended	
 52 A/F					Mos	22-Jun-2022				
	Eff: 14-May-2020 Not Applicable				Hrs	8				
	(AVG MAN HRS: 1)				Ldg	6				
SL560XL-52-09	Doors - Cabin Entry Door Fastener Verification						RE (-)		Service Letter	
 52 A/F					Mos					
	Eff: 08-Dec-2017				Hrs					
	(AVG MAN HRS: 2)				Ldg					
SL560XL-52-11	Doors - Installation of Protective Sleeve on the Cabin Entry Door Step Light Wire Harness Assembly						RE (-)		Recommended	
 52 A/F					Mos	13-Sep-2023				
	Eff: 17-Jul-2023 Not Applicable				Hrs	699:29				
	(AVG MAN HRS: 2)				Ldg	460				
▼ 53 - FUSELAGE										
	Nose Landing Gear Actuator Fitting Assy						RE (O/C)			
 53 A/F					Mos	22-Jun-2022				
	Unknown				Hrs	0				
	Unknown				Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
Radome Assembly										
	53 A/F					Mos	22-Jun-2022	RE (O/C)		
	Unknown					Hrs	0			
	Unknown					Ldg	0			
53-00-00-2100 Left Fuselage Fairing Internal Zonal General Visual Inspection										
	53 A/F	5-12-06				Mos		48	MSG-3 Zonal Inspection Tasks	
						Hrs		-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
	MRBR Task:53-100-03 (ZONE: 153, 163, 165, 313) (SOURCE: 560 XL MM Section 5-10-04)				Ldg					
53-00-00-2100 Right Fuselage Fairing Internal Zonal General Visual Inspection										
	53 A/F	5-12-06				Mos		48	MSG-3 Zonal Inspection Tasks	
						Hrs		-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
	MRBR Task:53-100-03 (ZONE: 154, 164, 166, 314) (SOURCE: 560 XL MM Section 5-10-04)				Ldg					
53-00-00-2101 Fuselage and Fairing External Zonal General Visual Inspection										
	53 A/F	5-12-06				Mos		48	MSG-3 Zonal Inspection Tasks	
						Hrs		-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
	MRBR Task:53-100-05, MRBR Task:53-200-03 (ZONE: 155, 167, 169, 315, 156, 168, 170, 316) (SOURCE: 560XL MM) Note: Zones Cont: 111, 143, 144, 213, 214, 223, 224, 253, 254, 263, 264, 153, 154, 163, 164, 165, 166, 263, 264. NOTE: It is recommended you do this task at the same time as Task 53-00-00-2201				Ldg					
53-00-00-2102 Communication and Navigation Antenna Mounting Corrosion General Visual Inspection										
	53 A/F	5-12-06				Mos		48	05-10-01, 05-10-03	
						Hrs		-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
	MRBR Task:53-20-01-002 (ZONE: 263, 264) (SOURCE: 560XL MM) Note: This is a CPCP Task				Ldg					
53-00-00-2201 Forward and Aft Lower Fairing External L/HIRF Detailed Inspection										
	53 A/F	5-12-06				Mos		48	MSG-3 L/HIRF Inspection Tasks	
						Hrs		-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
	(ZONE: 155, 156, 315, 316) (SOURCE: 560 XL MM Section 5-10-06) Note: NOTE: It is recommended you do this task at the same time as Task 53-00-00-2101				Ldg					
53-00-00-9600 Nose Landing Gear Trunnion Support Assembly										
	53 A/F	Left				Mos	22-Jun-2022		RE	Airworthiness Limitations
	6613020-63					Hrs		0		Inspection Time Limits
	126953-002					Ldg		0	25,500	25,500
(ZONE: 710) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
53-00-00-9600 Nose Landing Gear Trunnion Support Assembly										
	53 A/F	Right				Mos	22-Jun-2022		RE	Airworthiness Limitations
	6613020-64					Hrs		0		Inspection Time Limits
	130856-020					Ldg		0	25,500	25,500
(ZONE: 710) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
53-00-00-9601 Nose Landing Gear Actuator Fitting Assembly										
	53 A/F					Mos	22-Jun-2022		RE	Airworthiness Limitations
	6211191-3-1					Hrs		0		Inspection Time Limits
	6325					Ldg		0	25,500	25,500
(ZONE: 710) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
53-10-00-2100 Nose Landing Gear Wheel Well and Door Internal Zonal General Visual Inspection										
	53 A/F	5-12-06				Mos		48	MSG-3 Zonal Inspection Tasks	
						Hrs		-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
	MRBR Task:32-700-01 (ZONE: 710) (SOURCE: 560 XL MM Section 5-10-04) Note: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-2101, 32-00-00-7100, and 57-10-00-2100				Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time Remaining
SEQ	PN/SN	MOC Note or Component Condition							DUE	
53-10-00-2101		Nose Section Internal Zonal General Visual Inspection and Restoration								
	53 A/F	5-12-13					RE	05-10-01, 05-10-04, 05-10-05		
					Mos		72	-/+1m	(30-Jun-2028)	3.7 Years (+30 Days)
					Hrs					
					Ldg					
MRBR Task:211-001, MRBR Task:112-001, MRBR Task:53-200-01, MRBR Task:222-102E, MRBR Task:221-102E, MRBR Task:212-102E, MRBR Task:211-102E, MRBR Task:212-001, MRBR Task:221-001, MRBR Task:222-001 (ZONE: 110, 211, 212, 221, 222) (SOURCE: 560XL MM) Note: NOTE: It is recommended you do this task at the same time as Tasks 53-10-00-2102 and 53-10-00-2103										
53-10-00-2102		Nose Avionics Components Wiring and Bulkhead Connectors Standalone EZAP General Visual Inspection								
	53 A/F	5-12-13					RE	MSG-3 Zonal Inspection Tasks		
					Mos		72	-/+1m	(30-Jun-2028)	3.7 Years (+30 Days)
					Hrs					
					Ldg					
(ZONE: 211, 212, 221, 222) (SOURCE: 560 XL MM Section 5-10-05) Note: NOTE: It is recommended you do this task at the same time as Tasks 53-10-00-2101 and 53-10-00-2103										
53-10-00-2103		Nose Avionics L/HIRF Standalone General Visual Inspection (Airplanes -5001 thru -6000)								
	53 A/F						RE (N/A)	MSG-3 L/HIRF Inspection Tasks		
					Mos					
					Hrs					
					Ldg					
(ZONE: 211, 212) (SOURCE: 560 XL MM Section 5-10-06)										
53-10-00-2200		Nose Landing Gear and Wheel Well Structure and Corrosion General Visual and Detailed Inspection								
	53 A/F	5-12-01						REMSG-3 Structures Inspection Tasks		
					Mos	22-May-2024	12	-/+1m	(31-May-2025)	7.6 Months (+30 Days)
					Hrs	1020:11				
					Ldg	698				
(ZONE: 710, 711) (SOURCE: 560 XL MM Section 5-10-03) Note: NOTE: This is a CPCP Task										
53-10-00-2201		Nose Structure Internal Detailed Inspection								
	53 A/F	5-12-16						REMSG-3 Structures Inspection Tasks		
					Mos		96	-/+1m	(30-Jun-2030)	5.7 Years (+30 Days)
					Hrs					
					Ldg					
(ZONE: 110, 211, 212, 221, 222) (SOURCE: 560 XL MM Section 5-10-03)										
53-10-00-2202		Nose Non-Metallic Structure (Radome, Door Drip Caps) Internal Detailed Inspection								
	53 A/F	5-12-06						REMSG-3 Structures Inspection Tasks		
					Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
					Hrs					
					Ldg					
(ZONE: 110,211, 212, 221, 222) (SOURCE: 560 XL MM Section 5-10-03) Note: NOTE: It is recommended you do this task at the same time as Task 53-10-00-2203										
53-10-00-2203		Radome Diverter Strips L/HIRF Detailed Inspection								
	53 A/F	5-12-06					RE	MSG-3 L/HIRF Inspection Tasks		
					Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
					Hrs					
					Ldg					
(ZONE: 111) (SOURCE: 560 XL MM Section 5-10-06) Note: NOTE: It is recommended you do this task at the same time as Task 53-10-00-2202										
53-10-11-2200		Lower Aft Cabin Internal (Below Externally Serviced Toilet) Structural and Corrosion (Borescope) Special Detailed Inspection								
	53 A/F	5-12-03						REMSG-3 Structures Inspection Tasks		
					Mos	22-May-2024	24	-/+1m	(31-May-2026)	1.6 Years (+30 Days)
					Hrs	1020:11				
					Ldg	698				
(ZONE: 172) (SOURCE: 560 XL MM Section 5-10-03) Note: NOTE: This is a CPCP Task. NOTE: It is recommended you do this task at the same time as Task 38-30-02-2200.										
53-10-11-2201		Aft Cabin Lower Skin (Below Drop Aisle) Internal Structural and Corrosion Detailed Inspection								
	53 A/F	5-12-06						REMSG-3 Structures Inspection Tasks		
					Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
					Hrs					
					Ldg					
(ZONE: 151, 152, 161, 162, 171, 172) (SOURCE: 560 XL MM Section 5-10-03) Note: NOTE: This is a CPCP Task										
53-10-11-2202		Lower Aft Cabin Internal (Below Carry-Out Toilet) Structural and Corrosion Detailed Inspection								
	53 A/F	5-12-03						REMSG-3 Structures Inspection Tasks		
					Mos	22-May-2024	24	-/+1m	(31-May-2026)	1.6 Years (+30 Days)
					Hrs	1020:11				
					Ldg	698				
(ZONE: 171) (SOURCE: 560 XL MM Section 5-10-03) Note: NOTE: This is a CPCP Task.										
53-10-11-2501		Forward Pressure Bulkhead (Eddy Current) Special Detailed Inspection								
	53 A/F	4-12-MD					T	Airworthiness Limitations Inspection Time Limits		≈29-Mar-2031
					Mos		120			7.7 Years
					Hrs		6,000		(6000)	4640:04 Hrs
					Ldg					
(ZONE: 141, 142, 241, 242) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
53-10-11-2502		Aft Pressure Bulkhead General Visual Inspection						RE		Airworthiness Limitations Inspection Time Limits	≈08-Oct-2043
	53 A/F	4-12-ME				Mos					
						Hrs		15,000		(15000)	13640:04 Hrs
	(ZONE: 171, 172, 261, 262) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Ldg					
53-10-12-2100		Baggage Door and Forward Tailcone Internal Zonal General Visual Inspection						RE		MSG-3 Zonal Inspection Tasks	
	53 A/F	5-12-06				Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
						Hrs					
	MRBR Task:53-300-01 (ZONE: 311, 312) (SOURCE: 560 XL MM Section 5-10-04) Note: NOTE: It is recommended you do this task at the same time as Tasks 49-00-00-2100, 53-10-12-2102, 53-10-12-2103, 53-10-12-2104, and 53-10-12-2200					Ldg					
53-10-12-2101		Tailcone External Zonal General Visual Inspection						RE		MSG-3 Zonal Inspection Tasks	
	53 A/F	5-12-06				Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
						Hrs					
	MRBR Task:53-300-02 (ZONE: 317, 318, 323, 324) (SOURCE: 560 XL MM Section 5-10-04)					Ldg					
53-10-12-2102		Auxiliary Power Unit Enclosure and Stinger Internal Zonal General Visual Inspection and Restoration						RE		05-10-01, 05-10-04, 05-10-05	
	53 A/F	5-12-06				Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
						Hrs					
	MRBR Task:53-300-03 (ZONE: 321, 322) (SOURCE: 560XL MM) Note: NOTE: It is recommended you do this task at the same time as Tasks 49-00-00-2100, 53-10-12-2100, 53-10-12-2103, 53-10-12-2104, and 53-10-12-2200					Ldg					
53-10-12-2103		Forward Tailcone Avionics Components, Wire Bundles and Connectors Standalone EZAP General Visual Inspection						RE		MSG-3 EZAP Inspection Tasks	
	53 A/F	5-12-06				Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
						Hrs					
	(ZONE: 311, 312) (SOURCE: 560 XL MM Section 5-10-05) Note: NOTE: It is recommended you do this task at the same time as Tasks 49-00-00-2100, 53-10-12-2100, 53-10-12-2102, 53-10-12-2104, and 53-10-12-2200					Ldg					
53-10-12-2104		Auxiliary Power Unit Generator Power Feeder Cables Standalone EZAP General Visual Inspection						RE		MSG-3 EZAP Inspection Tasks	
	53 A/F	5-12-06				Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
						Hrs					
	(ZONE: 321, 322) (SOURCE: 560 XL MM Section 5-10-05) Note: NOTE: It is recommended you do this task at the same time as Tasks 49-00-00-2100, 53-10-12-2100, 53-10-12-2102, 53-10-12-2103, and 53-10-12-2200					Ldg					
53-10-12-2200		Auxiliary Power Unit Generator, Auxiliary Power Unit Generator Control Unit and Left / Right Engine Generator Control Unit L/HIRF Detailed Inspection						RE		MSG-3 L/HIRF Inspection Tasks	
	53 A/F	5-12-06				Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
						Hrs					
	(ZONE: 321, 322) (SOURCE: 560 XL MM Section 5-10-06) Note: NOTE: It is recommended you do this task at the same time as Tasks 49-00-00-2100, 53-10-12-2100, 53-10-12-2102, 53-10-12-2103, and 53-10-12-2104					Ldg					
53-20-00-2100		Cockpit Internal (Below Floorline) Zonal General Visual Inspection and Restoration						RE		05-10-01, 05-10-04, 05-10-05	
	53 A/F	5-12-13				Mos		72	-/+1m	(30-Jun-2028)	3.7 Years (+30 Days)
						Hrs					
	MRBR Task:53-100-01, MRBR Task:141-001, MRBR Task:142-001, MRBR Task:142-102E, MRBR Task:141-102E (ZONE: 141, 142) (SOURCE: 560XL MM) Note: NOTE: It is recommended you do this task at the same time as Task 53-20-00-2102					Ldg					
53-20-00-2101		Cockpit Internal (Above Floorline) Zonal General Visual Inspection and Restoration						RE		05-10-01, 05-10-04, 05-10-05	
	53 A/F	5-12-16				Mos		96	-/+1m	(30-Jun-2030)	5.7 Years (+30 Days)
						Hrs					
	MRBR Task:53-200-02, MRBR Task:235-001, MRBR Task:236-001, MRBR Task:241-001, MRBR Task:242-001, MRBR Task:246-102E, MRBR Task:245-102E, MRBR Task:236-102E, MRBR Task:235-102E, MRBR Task:246-001, MRBR Task:245-001 (ZONE: 235, 236, 241, 242, 245, 246) (SOURCE: 560XL MM) Note: NOTE: It is recommended you do this task at the same time as Tasks 53-20-00-2103, 53-20-00-2104, 53-30-00-2101, and 56-11-00-2204					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
53-20-00-2102	Cockpit Wire Bundles Standalone EZAP General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks		
 53 A/F	5-12-13				Mos		72	-/+1m	(30-Jun-2028)	3.7 Years (+30 Days)
	(ZONE: 141, 142) (SOURCE: 560 XL MM Section 5-10-05)				Hrs					
	Note: NOTE: It is recommended you do this task at the same time as Task 53-20-00-2100				Ldg					
53-20-00-2103	Cockpit Avionics Components and Wire Bundles Standalone EZAP General Visual Inspection						RE	MSG-3 EZAP Inspection Tasks		
 53 A/F	5-12-16				Mos		96	-/+1m	(30-Jun-2030)	5.7 Years (+30 Days)
	(ZONE: 235, 236, 245, 246) (SOURCE: 560 XL MM Section 5-10-05)				Hrs					
	Note: NOTE: It is recommended you do this task at the same time as Tasks 53-20-00-2101, 53-20-00-2104, 53-30-00-2101, and 56-11-00-2204				Ldg					
53-20-00-2104	Cockpit Avionics Control Head L/HIRF Standalone General Visual Inspection						RE	MSG-3 L/HIRF Inspection Tasks		
 53 A/F	5-12-16				Mos		96	-/+1m	(30-Jun-2030)	5.7 Years (+30 Days)
	(ZONE: 235, 236) (SOURCE: 560 XL MM Section 5-10-06)				Hrs					
	Note: NOTE: It is recommended you do this task at the same time as Tasks 53-20-00-2101, 53-20-00-2103, 53-30-00-2101, and 56-11-00-2204				Ldg					
53-30-00-2100	Cabin Internal Zonal General Visual Inspection and Restoration						RE	05-10-01, 05-10-04, 05-10-05		
 53 A/F	5-12-16				Mos		96	-/+1m	(30-Jun-2030)	5.7 Years (+30 Days)
	MRBR Task:812-001 , MRBR Task:172-001, MRBR Task:822-101E, MRBR Task:812-101E, MRBR Task:172-101E, MRBR Task:171-101E, MRBR Task:162-101E, MRBR Task:161-101E, MRBR Task:822-001, MRBR Task:262-001, MRBR Task:261-001, MRBR Task:252-001, MRBR Task:251-001, MRBR Task:171-001, MRBR Task:162-001, MRBR Task:161-001, MRBR Task:53-100-02 (ZONE: 161, 162, 171, 172, 251, 252, 261, 262, 810, 820) (SOURCE: 560XL MM)				Ldg					
53-30-00-2101	Forward Cabin (Below Floorline) Internal General Visual Inspection and Restoration						RE	05-10-01, 05-10-04, 05-10-05		
 53 A/F	5-12-16				Mos		96	-/+1m	(30-Jun-2030)	5.7 Years (+30 Days)
	MRBR Task:152-001, MRBR Task:151-001, MRBR Task:53-100-06, MRBR Task:246-102E, MRBR Task:245-102E, MRBR Task:236-102E, MRBR Task:235-102E (ZONE: 151, 152) (SOURCE: 560XL MM)				Hrs					
	Note: NOTE: It is recommended you do this task at the same time as Tasks 53-20-00-2101, 53-20-00-2103, 53-20-00-2104, and 56-11-00-2204				Ldg					
53-30-00-2200	Elevator and Elevator Trim Control System Support Structural Detailed Inspection						REMSG-3 Structures Inspection Tasks			
 53 A/F	5-12-06				Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
	(ZONE: 141, 142, 241, 242, 311, 312, 321, 322, 351, 352, 340, 151, 152, 161, 162, 171, 172) (SOURCE: 560 XL MM Section 5-10-03)				Hrs					
	Note: NOTE: It is recommended you do this task at the same time as Tasks 27-31-00-2200 and 55-20-00-2200				Ldg					
53-30-01-2100	Upper Fuselage Skin from Right Stringer 13 to Left Stringer 13 General Visual Inspection						RE	Airworthiness Limitations Inspection Time Limits		≈25-Dec-2040
 53 A/F	4-12-MJ				Mos					
	(ZONE: 213, 243, 253, 263, 323, 214, 244, 254, 264, 324) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Hrs		13,000		(13000)	11640:04 Hrs
					Ldg					
53-30-01-2101	Lower Fuselage Skin from Right Stringer 13 to Left Stringer 13 General Visual Inspection						RE	Airworthiness Limitations Inspection Time Limits		≈08-Oct-2043
 53 A/F	4-12-ME				Mos					
	(ZONE: 143, 151, 161, 171, 213, 144, 152, 162, 172, 214) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Hrs		15,000		(15000)	13640:04 Hrs
					Ldg					
53-30-01-2500	Fuselage External Surface (Eddy Current) Special Detailed Inspection						REMSG-3 Structures Inspection Tasks			≈28-Nov-2032
 53 A/F	5-12-25				Mos					
	(ZONE: 143, 144, 223, 224, 243, 244, 253, 254, 263, 264) (SOURCE: 560 XL MM Section 5-10-03)				Hrs		7,200	-/+25	(7200)	5840:04 Hrs (+25)
	Note: Zone cont.: 317, 318, 323, 324				Ldg					
53-30-01-2501	Upper Fuselage Skin Splice at BL 0.00 (Eddy Current) Special Detailed Inspection						RE	Airworthiness Limitations Inspection Time Limits		≈08-Oct-2043
 53 A/F	4-12-ME				Mos					
	(ZONE: 241, 242, 251, 252, 261, 262) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Hrs		15,000		(15000)	13640:04 Hrs
					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
53-30-01-2502	Lower Fuselage Skin Splices at Stringers 13R and 13L (Eddy Current) Special Detailed Inspection						RE		Airworthiness Limitations Inspection Time Limits	≈08-Oct-2043
 53 A/F	4-12-ME					Mos				
	(ZONE: 151, 161, 171, 152, 162, 172) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs	15,000		(15000)	13640:04 Hrs
						Ldg				
53-31-00-2200	Composite Ventral Strake (Coin Tap) Special Detailed Inspection						REMSG-3 Structures Inspection Tasks			
 53 A/F	5-12-16					Mos	96	-/+1m	(30-Jun-2030)	5.7 Years (+30 Days)
	(ZONE: 323, 324) (SOURCE: 560 XL MM Section 5-10-03)					Hrs				
						Ldg				
560XL-53-13	Nose Drip Cap Bond Inspection						RE (-)		Recommended	
 53 A/F						Mos	22-Jun-2022			
Not Applicable	by S/N					Hrs	8			
						Ldg	6			
560XL-53-13 Rev 01	Nose Drip Cap Bond Inspection						RE (-)		Mandatory	
 53 A/F						Mos	22-Jun-2022			
Eff: 05-Oct-2011 Not Applicable	by S/N					Hrs	8			
						Ldg	6			
560XL-53-14	Carbon Fiber Strake Modification						RE (-)		Optional	
 53 A/F						Mos				
Eff: 09-Apr-2012						Hrs				
						Ldg				
560XL-53-15	Fastener Installation F.S. 115.20						RE (-)		Mandatory	
 53 A/F						Mos	22-Jun-2022			
Eff: 19-Jan-2011 Not Applicable	by S/N					Hrs	8			
						Ldg	6			
560XL-53-16	Stinger Drain Installation						RE (-)		Mandatory	
 53 A/F						Mos	22-Jun-2022			
Eff: 04-Oct-2011 Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			
ASL560XL-53-08A	Aft Canted Bulkhead Drain Installation						RE (-)		Recommended	
 53 A/F						Mos	22-Jun-2022			
Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			
ASL560XL-53-08A Rev 01	Aft Canted Bulkhead Drain Installation						RE (-)		Mandatory	
 53 A/F						Mos	22-Jun-2022			
Eff: 27-Jan-2011 Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			
CIL-53-01	Fuselage - Nose Radome Guide Pin Replacement						RE (-)		Recommended, Service Letter	
 53 A/F						Mos	22-Jun-2022			
Eff: 17-Dec-2020 Not Applicable	effective before manufacture					Hrs	8			
(AVG MAN HRS: 1.5)						Ldg	6			
CIL-53-01 R1	Fuselage - Nose Radome Guide Pin Replacement						RE (-)		Recommended	
 53 A/F						Mos	22-Jun-2022			
Eff: 17-Mar-2021 Not Applicable	effective before manufacture					Hrs	8			
(AVG MAN HRS: 1.5)						Ldg	6			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-53-03	Fuselage - Lightning Diverter Strip Installation/Repair Procedure Change (Radome)						T (A/R)		Informational	
 53 A/F						Mos				
Eff: 14-Aug-2001						Hrs				
						Ldg				
SL560XL-53-07	Lower Skin Assembly Fastener Inspection						RE (-)		Mandatory	
 53 A/F						Mos	22-Jun-2022			
Eff: 14-Apr-2009 Not	by aircraft S/N					Hrs	8			
Applicable						Ldg	6			
SL560XL-53-16	Fastener Inspection/Installation						RE (-)		Mandatory	
 53 A/F						Mos	22-Jun-2022			
Eff: 16-Aug-2011 Not	by aircraft S/N					Hrs	8			
Applicable						Ldg	6			
SL560XL-53-17	Dorsal Duct Inspection						RE (-)		Recommended	
 53 A/F						Mos	22-Jun-2022			
Eff: 20-Nov-2012 Not	effective before manufacture					Hrs	8			
Applicable						Ldg	6			
SL560XL-53-18	Fuselage - Tailcone Missing Fastener Inspection and Installation						RE (-)		Mandatory	
 53 A/F						Mos	22-Jun-2022			
Eff: 13-Jan-2016 Not	by aircraft S/N					Hrs	8			
Applicable						Ldg	6			
(AVG MAN HRS: 2.2)										
SL560XL-53-18 Rev 01	Fuselage - Tailcone Missing Fastener Inspection and Installation						RE (-)		Mandatory	
 53 A/F						Mos	22-Jun-2022			
Eff: 22-Jun-2016 Not	by aircraft S/N					Hrs	8			
Applicable						Ldg	6			
(AVG MAN HRS: 2.2)										
SL560XL-53-19	Fuselage - Empennage Fastener Verification						RE (-)		Recommended	
 53 A/F						Mos	22-Jun-2022			
Eff: 14-May-2020 Not	effective before manufacture					Hrs	8			
Applicable						Ldg	6			
(AVG MAN HRS: 1)										
SL560XL-53-19 R1	Fuselage - Empennage Fastener Verification						RE (-)		Recommended	
 53 A/F						Mos	22-Jun-2022			
Eff: 19-Jun-2020 Not	effective before manufacture					Hrs	8			
Applicable						Ldg	6			
(AVG MAN HRS: 1)										
SL560XL-53-21	Fuselage - Inspection of the Tailcone Stinger Attach Nutplates for Damage						RE (-)		Recommended, Service Letter	
 53 A/F						Mos	19-Jul-2024			
Eff: 24-Jun-2024 Not	N/A Due to aircraft different SN					Hrs				
Applicable						Ldg				
(AVG MAN HRS: 4)										
▼ 54 - NACELLES/PYLONS										
54-50-01-2100	Left Side Engine Cowlings and Pylons Internal and External Zonal General Visual Inspection and Restoration						RE	05-10-01, 05-10-04, 05-10-05		
 54 A/F	5-12-03					Mos	22-May-2024	24	-/+1m (31-May-2026)	1.6 Years (+30 Days)
						Hrs	1020:11			
						Ldg	698			
MRBR Task:71-400-01, MRBR Task:411-001, MRBR Task:412-001, MRBR Task:415-001, MRBR Task:421-001, MRBR Task:71-400-02, MRBR Task:413-001, MRBR Task:414-001, MRBR Task:431-001, MRBR Task:441-001, MRBR Task:411-101E, MRBR Task:412-101E, MRBR Task:415-101E, MRBR Task:421-101E (ZONE: 411, 413, 410, 430) (SOURCE: 560XL MM)										
Note: NOTE: It is recommended you do this task at the same time as Tasks 71-00-00-2100 and 71-00-00-2200										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
54-50-01-2100	Right Side Engine Cowlings and Pylons Internal and External Zonal General Visual Inspection and Restoration						RE	05-10-01, 05-10-04, 05-10-05		
54 A/F	5-12-03					Mos 22-May-2024	24	-/+1m	(31-May-2026)	1.6 Years (+30 Days)
	MRBR Task:71-400-01, MRBR Task:411-001, MRBR Task:412-001, MRBR Task:415-001, MRBR Task:421-001, MRBR Task:71-400-02, MRBR Task:413-001, MRBR Task:414-001, MRBR Task:431-001, MRBR Task:441-001, MRBR Task:411-101E, MRBR Task:412-101E, MRBR Task:415-101E, MRBR Task:421-101E (ZONE: 412, 414, 420, 440) (SOURCE: 560XL MM)					Hrs 1020:11				
	Note: NOTE: It is recommended you do this task at the same time as Tasks 71-00-00-2100 and 71-00-00-2200					Ldg 698				
54-50-10-2100	Left Aft Engine Beam General Visual Inspection						RE (N/A)		Airworthiness Limitations	
54 A/F						Mos			Inspection Time Limits	
	(ZONE: 311, 411) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs				
						Ldg				
54-50-10-2100	Right Aft Engine Beam General Visual Inspection						RE (N/A)		Airworthiness Limitations	
54 A/F						Mos			Inspection Time Limits	
	(ZONE: 312, 412) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs				
						Ldg				
54-50-10-2500	Left Forward Engine Beam Upper Angles, Horizontal Cap Flange at BL 30.5 thru BL 42.0 (Eddy Current) Special Detailed Inspection						RE (N/A)		Airworthiness Limitations	
54 A/F						Mos			Inspection Time Limits	
	(ZONE: 311, 411) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs				
						Ldg				
54-50-10-2500	Right Forward Engine Beam Upper Angles, Horizontal Cap Flange at BL 30.5 thru BL 42.0 (Eddy Current) Special Detailed Inspection						RE (N/A)		Airworthiness Limitations	
54 A/F						Mos			Inspection Time Limits	
	(ZONE: 312, 412) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Hrs				
						Ldg				
▼ 55 - STABILIZERS										
55-00-00-2200	Empennage Cove Structure and Corrosion Detailed Inspection						REMSG-3 Structures Inspection Tasks			
55 A/F	5-12-01					Mos 22-May-2024	12	-/+1m	(31-May-2025)	7.6 Months (+30 Days)
	(ZONE: 321, 322, 341 353, 354) (SOURCE: 560 XL MM Section 5-10-03)					Hrs 1020:11				
	Note: NOTE: This is a CPCP Task.					Ldg 698				
55-10-00-2100	Empennage External Zonal General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks		
55 A/F	5-12-13					Mos	72	-/+1m	(30-Jun-2028)	3.7 Years (+30 Days)
	MRBR Task:55-300-01 (ZONE: 341, 353, 354) (SOURCE: 560XL MM)					Hrs				
	Note: NOTE: It is recommended you do this task at the same time as Tasks 55-10-00-2200 and 55-10-00-2201					Ldg				
55-10-00-2101	Horizontal Stabilizer Surfaces Internal Zonal General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks		
55 A/F	5-12-16					Mos	96	-/+1m	(30-Jun-2030)	5.7 Years (+30 Days)
	MRBR Task:55-300-03 (ZONE: 351, 352) (SOURCE: 560XL MM)					Hrs				
	Note: NOTE: It is recommended you do this task at the same time as Task 55-10-00-2900					Ldg				
55-10-00-2200	Horizontal Stabilizer Position Switches L/HIRF Detailed Inspection						RE	MSG-3 L/HIRF Inspection Tasks		
55 A/F	5-12-13					Mos	72	-/+1m	(30-Jun-2028)	3.7 Years (+30 Days)
	(ZONE: 342) (SOURCE: 560 XL MM Section 5-10-06)					Hrs				
	Note: NOTE: It is recommended you do this task at the same time as Tasks 55-10-00-2100 and 55-10-00-2201					Ldg				
55-10-00-2201	Flux Detectors L/HIRF Detailed Inspection						RE	MSG-3 L/HIRF Inspection Tasks		
55 A/F	5-12-13					Mos	72	-/+1m	(30-Jun-2028)	3.7 Years (+30 Days)
	(ZONE: 351, 352) (SOURCE: 560 XL MM Section 5-10-06)					Hrs				
	Note: NOTE: It is recommended you do this task at the same time as Tasks 55-10-00-2100 and 55-10-00-2200					Ldg				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
55-10-00-2900		Internal Horizontal Stabilizer (Borescope) Special Detailed Inspection								REMSG-3 Structures Inspection Tasks	
	55 A/F	5-12-16						96	-/+1m	(30-Jun-2030)	5.7 Years (+30 Days)
		(ZONE: 351, 352) (SOURCE: 560 XL MM Section 5-10-03)					Mos				
		Note: NOTE: It is recommended you do this task at the same time as Task 55-10-00-2101					Hrs				
							Ldg				
55-20-00-2200		Elevator Assembly Detailed Inspection								RE 05-10-01, 05-10-02, 05-10-03, Category 5	
	55 A/F	Left5-12-06						48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
		6634200-13					Mos				
		31200621					Hrs				
		MRBR Task:55-20-01-001, MRBR Task:55-20-01-002 (ZONE: 354) (SOURCE: 560XL MM)					Ldg				
		Note: NOTE: It is recommended you do this task at the same time as Tasks 27-31-00-2200 and 53-30-00-2200									
55-20-00-2200		Elevator Assembly Detailed Inspection								RE 05-10-01, 05-10-02, 05-10-03, Category 5	
	55 A/F	Right5-12-06						48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
		6634200-14					Mos				
		31211576					Hrs				
		MRBR Task:55-20-01-001, MRBR Task:55-20-01-002 (ZONE: 353) (SOURCE: 560XL MM)					Ldg				
		Note: NOTE: It is recommended you do this task at the same time as Tasks 27-31-00-2200 and 53-30-00-2200									
55-30-00-2102		Vertical Stabilizer Internal Zonal General Visual Inspection								RE MSG-3 Zonal Inspection Tasks	
	55 A/F	5-12-16						96	-/+1m	(30-Jun-2030)	5.7 Years (+30 Days)
		MRBR Task:55-300-02 (ZONE: 340) (SOURCE: 560XL MM)					Mos				
		Note: NOTE: It is recommended you do this task at the same time as Task 55-30-00-2900					Hrs				
							Ldg				
55-30-00-2200		Rudder and Rudder Trim Control System Structural Support Detailed Inspection								REMSG-3 Structures Inspection Tasks	
	55 A/F	5-12-06						48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
		(ZONE: 141,142,161,162,241,242,311,312,313,323,324,341) (SOURCE: 560 XL MM Section 5-10-03)					Mos				
		Note: NOTE: It is recommended you do this task at the same time as Task 55-40-00-2200					Hrs				
							Ldg				
55-30-00-2201		Vertical Stabilizer Pivot Fitting Detailed Inspection								TMSG-3 Structures Inspection Tasks	≈29-Mar-2031
	55 A/F	5-12-17									
		(ZONE: 340) (SOURCE: 560 XL MM Section 5-10-03)					Mos				
							Hrs	6,000	-/+25	(6000)	4640:04 Hrs (+25)
							Ldg				
55-30-00-2500		Vertical Stabilizer Rear Spar Cap at WL 146 (Eddy Current) Special Detailed Inspection								RE (N/A)	Airworthiness Limitations Inspection Time Limits
	55 A/F										
		(ZONE: 321, 322, 340) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Mos				
							Hrs				
							Ldg				
55-30-00-2501		Vertical Stabilizer Rear Spar Nested Angle at WL 146 (Eddy Current) Special Detailed Inspection								RE (N/A)	Airworthiness Limitations Inspection Time Limits
	55 A/F										
		(ZONE: 321, 322, 340) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Mos				
							Hrs				
							Ldg				
55-30-00-2502		Vertical Stabilizer Rear Spar Strap at WL 146.00 (Eddy Current) Special Detailed Inspection								RE (N/A)	Airworthiness Limitations Inspection Time Limits
	55 A/F										
		(ZONE: 321, 322, 340) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Mos				
							Hrs				
							Ldg				
55-30-00-2503		Vertical Stabilizer Forward Spar Strap at WL 150 (Eddy Current) Special Detailed Inspection								RE (N/A)	Airworthiness Limitations Inspection Time Limits
	55 A/F										
		(ZONE: 321, 322, 340) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)					Mos				
							Hrs				
							Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
55-30-00-2504	Vertical Stabilizer Forward Spar Strap at WL 188.00 (Eddy Current) Special Detailed Inspection						RE (N/A)		Airworthiness Limitations Inspection Time Limits	
 55 A/F						Mos				
						Hrs				
(ZONE: 340) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)						Ldg				
55-30-00-2900	Vertical Stabilizer (Areas With Limited Access) (Borescope) Internal Special Detailed Inspection						REMSG-3 Structures Inspection Tasks			
 55 A/F	5-12-16					Mos	96	-/+1m	(30-Jun-2030)	5.7 Years (+30 Days)
						Hrs				
(ZONE: 340) (SOURCE: 560 XL MM Section 5-10-03)						Ldg				
Note: NOTE: It is recommended you do this task at the same time as Task 55-30-00-2102										
55-40-00-2200	Rudder and Rudder Trim Tab Detailed Inspection						RE	05-10-01, 05-10-02, 05-10-03, Category 5		
 55 A/F	5-12-06					Mos	48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
						Hrs				
MRBR Task:55-40-01-001 (ZONE: 341) (SOURCE: 560XL MM)						Ldg				
Note: NOTE: It is recommended you do this task at the same time as Task 55-30-00-2200										
SL560XL-55-01	Stabilizers - Pivot Fitting Inspection						RE (-)		Mandatory	
 55 A/F						Mos	22-Jun-2022			
Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			
SL560XL-55-01 Rev 01	Stabilizers - Pivot Fitting Inspection						RE (-)		Mandatory	
 55 A/F						Mos	22-Jun-2022			
Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			
SL560XL-55-01 Rev 02	Stabilizers - Pivot Fitting Inspection						RE (-)		Mandatory	
 55 A/F						Mos	22-Jun-2022			
Eff: 12-Jun-2015 Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			
Note: This service letter must be accomplished on airplanes that have attained 6,000 flight hours or more within 600 flight hours or one year from the date of receipt of the original issue of service letter. Aircraft that are under 6,000 flight hours on the date of receipt of the original issue of this service letter will need to comply with this service letter upon attaining 6,000 flight hours but not exceeding 6,600 flight hours.										
SL560XL-55-01 Rev 03	Stabilizers - Pivot Fitting Inspection (Cancelled)						RE (-)		Mandatory	
 55 A/F						Mos	22-Jun-2022			
Eff: 09-Jun-2016 Not Applicable	by aircraft S/N					Hrs	8			
						Ldg	6			
Note: NOTE: The inspection requirement previously contained in this service letter can now be found in the Phase 71 and the Inspection Document 52 inspections in the Cessna Model 560XL Maintenance Manual Revision 40. NOTE: This revision replaces the original issue of SL560XL-55-01 and previous revisions in their entirety.										
SL560XL-55-02	Stabilizers - Replacement of the Rudder Stop Block						RE (-)		Recommended, Service Letter	
 55 A/F						Mos	22-Jun-2022			
Eff: 04-Nov-2019 Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			
SL560XL-55-03	Stabilizers - Inspection of the Horizontal Stabilizer Upper and Lower Splice Plate Huck Bolt Fasteners						RE (-)		Recommended	
 55 A/F						Mos	03-Oct-2022			
Eff: 16-May-2022 Not Applicable	as per A/Cs S/N					Hrs	167:53			
(AVG MAN HRS: 194)						Ldg	115			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
SL560XL-55-03 R1		Stabilizers - Inspection of the Horizontal Stabilizer Upper and Lower Splice Plate Huck Bolt Fasteners							RE (-)		Recommended	
	55 A/F	as per A/Cs S/N					Mos	03-Oct-2022				
	Eff: 26-Sep-2022 Not Applicable						Hrs	167:53				
	(AVG MAN HRS: 194)						Ldg	115				
▼ 56 - WINDOWS												
	56 A/F	Cabin Window					RE (O/C)					
	167400-03	Left No.2					Mos	22-Jun-2022				
	11182						Hrs	0				
							Ldg	0				
	56 A/F	Cabin Window					RE (O/C)					
	167400-03	Left No.3					Mos	22-Jun-2022				
	11178						Hrs	0				
							Ldg	0				
	56 A/F	Cabin Window					RE (O/C)					
	167400-03	Left No.4					Mos	22-Jun-2022				
	11174						Hrs	0				
							Ldg	0				
	56 A/F	Cabin Window					RE (O/C)					
	167400-03	Left No.5					Mos	22-Jun-2022				
	11181						Hrs	0				
							Ldg	0				
	56 A/F	Cabin Window					RE (O/C)					
	167400-03	Left No.6					Mos	22-Jun-2022				
	11171						Hrs	0				
							Ldg	0				
	56 A/F	Cabin Window					RE (O/C)					
	Unknown	Left No.7					Mos	22-Jun-2022				
	Unknown						Hrs	0				
							Ldg	0				
	56 A/F	Cabin Window					RE (O/C)					
	167400-03	Right No.2					Mos	22-Jun-2022				
	11180						Hrs	0				
							Ldg	0				
	56 A/F	Cabin Window					RE (O/C)					
	167400-03	Right No.3					Mos	22-Jun-2022				
	11159						Hrs	0				
							Ldg	0				
	56 A/F	Cabin Window					RE (O/C)					
	167400-03	Right No.4					Mos	22-Jun-2022				
	11146						Hrs	0				
							Ldg	0				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
56 A/F 167400-03 11173		Cabin Window Right No.5								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
56 A/F 167400-03 11161		Cabin Window Right No.6								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
56 A/F Unknown Unknown		Cabin Window Right No.7								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
56 A/F NP139722-7 21305H0363		Electrically Heated Cockpit Forward Side Window Left								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
56 A/F NP139722-8 21334H2319		Electrically Heated Cockpit Forward Side Window Right								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
56 A/F 167400-03 11172		Emergency Door Window Right No.1								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
56 A/F NP139731-1 21214H3740		Main Windshield Left								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
56 A/F 9914380-14 22157H6606		Main Windshield Right								RE (O/C)	
							Mos	02-Sep-2022			
							Hrs	108:42			
56 A/F NP139703-3 100Y1		Openable Cockpit Aft Side Window Left								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			
56 A/F NP139703-4 10094		Openable Cockpit Aft Side Window Right								RE (O/C)	
							Mos	22-Jun-2022			
							Hrs	0			

Task No		Description							Categories		Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
56-11-00-2200		Heated Windshield Assembly Hump Seal Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	56 A/F NP139731-1 21214H3740 (ZONE: 243) (SOURCE: 560 XL MM Section 5-10-02)	Left5-12-01					Mos	22-May-2024	12	-/+1m (31-May-2025)	7.6 Months (+30 Days)	
							Hrs	1020:11				
							Ldg	698				
56-11-00-2200		Heated Windshield Assembly Hump Seal Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	56 A/F 9914380-14 22157H6606 (ZONE: 244) (SOURCE: 560 XL MM Section 5-10-02)	Right5-12-01					Mos	22-May-2024	12	-/+1m (31-May-2025)	7.6 Months (+30 Days)	
							Hrs	1020:11				
							Ldg	698				
56-11-00-2201		Cockpit Openable Aft Side Window Hinge and Latch Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈12-Feb-2025
	56 A/F NP139703-3 100Y1 (ZONE: 241) (SOURCE: 560 XL MM Section 5-10-02)	Left5-12-07					Mos				240:04 Hrs (+25)	
							Hrs	1,600	-/+25 (1600)			
							Ldg					
	KGR-WP-011 START 21-JAN-2025											
56-11-00-2201		Cockpit Openable Aft Side Window Hinge and Latch Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈12-Feb-2025
	56 A/F NP139703-4 10094 (ZONE: 242) (SOURCE: 560 XL MM Section 5-10-02)	Right5-12-07					Mos				240:04 Hrs (+25)	
							Hrs	1,600	-/+25 (1600)			
							Ldg					
	KGR-WP-011 START 21-JAN-2025											
56-11-00-2202		Windshield Detailed Inspection							REMSG-3 Structures Inspection Tasks			
	56 A/F (ZONE: 241, 242, 243, 244) (SOURCE: 560 XL MM Section 5-10-03)	5-12-03					Mos	22-May-2024	24	-/+1m (31-May-2026)	1.6 Years (+30 Days)	
							Hrs	1020:11				
							Ldg	698				
56-11-00-2203		Windshield Retainer Detailed Inspection							REMSG-3 Structures Inspection Tasks			
	56 A/F (ZONE: 243, 244) (SOURCE: 560 XL MM Section 5-10-03)	5-12-16					Mos		96	-/+1m (30-Jun-2030)	5.7 Years (+30 Days)	
							Hrs					
							Ldg					
56-11-00-2204		Cockpit and Openable Side Window Internal Structure Detailed Inspection							REMSG-3 Structures Inspection Tasks			
	56 A/F (ZONE: 241, 242, 243, 244) (SOURCE: 560 XL MM Section 5-10-03) Note: NOTE: It is recommended you do this task at the same time as Tasks 53-20-00-2101, 53-20-00-2103, 53-20-00-2104, and 53-30-00-2101	5-12-16					Mos		96	-/+1m (30-Jun-2030)	5.7 Years (+30 Days)	
							Hrs					
							Ldg					
56-11-00-2207		Openable Side Cockpit Window (Transparency) Detailed Inspection							REMSG-3 Structures Inspection Tasks			
	56 A/F NP139703-3 100Y1 (ZONE: 241, 243) (SOURCE: 560 XL MM Section 5-10-03)	Left5-12-06					Mos		48	-/+1m (30-Jun-2026)	1.7 Years (+30 Days)	
							Hrs					
							Ldg					
56-11-00-2207		Openable Side Cockpit Window (Transparency) Detailed Inspection							REMSG-3 Structures Inspection Tasks			
	56 A/F NP139703-4 10094 (ZONE: 242,244) (SOURCE: 560 XL MM Section 5-10-03)	Right5-12-06					Mos		48	-/+1m (30-Jun-2026)	1.7 Years (+30 Days)	
							Hrs					
							Ldg					

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time	
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining	
56-11-00-7200	Heated Windshield Assembly Fastener Torque Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Mar-2026	
 56 A/F NP139731-1 21214H3740 (ZONE: 243) (SOURCE: 560 XL MM Section 5-10-02)	Left5-12-08					Mos					
						Hrs	2,400	-/+25	(2400)	1040:04 Hrs (+25)	
						Ldg					
56-11-00-7200	Heated Windshield Assembly Fastener Torque Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈25-Mar-2026	
 56 A/F 9914380-14 22157H6606 (ZONE: 244) (SOURCE: 560 XL MM Section 5-10-02)	Right5-12-08					Mos	02-Sep-2022				
						Hrs	108:42	2,400	-/+25	(2400)	1040:04 Hrs (+25)
						Ldg	72				
56-11-00-7201	Left Windshield Surface Seal (Mist Spray) Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
 56 A/F NP139731-1 21214H3740 (ZONE: 243) (SOURCE: 560 XL MM Section 5-10-02) Note: NOTE: Operational Environment May Require Reduced Interval	Left5-12-01					Mos	22-May-2024	12	-/+1m (31-May-2025)	7.6 Months (+30 Days)	
						Hrs	1020:11				
						Ldg	698				
56-11-00-7201	Right Windshield Surface Seal (Mist Spray) Functional Check						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS			
 56 A/F 9914380-14 22157H6606 (ZONE: 244) (SOURCE: 560 XL MM Section 5-10-02) Note: NOTE: Operational Environment May Require Reduced Interval	Right5-12-01					Mos	22-May-2024	12	-/+1m (31-May-2025)	7.6 Months (+30 Days)	
						Hrs	1020:11				
						Ldg	698				
SL560XL-56-02	Windshield Delamination						T (A/R)		Informational		
 56 A/F Eff: 31-Mar-2009						Mos					
						Hrs					
						Ldg					
SL560XL-56-03	Openable Cockpit Window Hinge and Latch Inspection						RE (-)		Mandatory		
 56 A/F Eff: 07-Dec-2010 Not Applicable	by aircraft S/N					Mos	22-Jun-2022				
						Hrs	8				
						Ldg	6				
▼ 57 - WINGS											
 57 A/F 6525130-37 31172035	Flap Assy Left Inboard						RE (O/C)				
						Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
 57 A/F 6525135-35 31238373	Flap Assy Left Outboard						RE (O/C)				
						Mos	22-Jun-2022				
						Hrs	0				
						Ldg	0				
 57 A/F 6525130-38 32056723	Flap Assy Right Inboard New						RE (O/C)				
						Mos	11-Apr-2023				
						Hrs	402:15				
						Ldg	276				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
Flap Assy							RE (O/C)			
	57 A/F	Right Outboard			Mos	22-Jun-2022				
	6525135-36				Hrs	0				
	31238371				Ldg	0				
57-00-00-2100 Left Wing External Zonal General Visual Inspection							RE	MSG-3 Zonal Inspection Tasks		
	57 A/F	5-12-06			Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
					Hrs					
	MRBR Task:57-20-03-001, MRBR Task:641-001, MRBR Task:632-001, MRBR Task:631-001, MRBR Task:622-001, MRBR Task:621-001, MRBR Task:612-001, MRBR Task:611-001, MRBR Task:610-001, MRBR Task:542-001, MRBR Task:532-001, MRBR Task:531-001, MRBR Task:522-001, MRBR Task:521-001, MRBR Task:512-001, MRBR Task:511-001, MRBR Task:510-001, MRBR Task:57-500-01, MRBR Task:57-50-02-001, MRBR Task:57-20-04-001 (ZONE: 511, 512, 515, 521, 522, 531, 532, 540) (SOURCE: 560 XL MM Section 5-10-01, 5-10-04, 5-12-06)				Ldg					
	Note: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-2101, 32-00-00-7100, and 53-10-00-2100									
57-00-00-2100 Right Wing External Zonal General Visual Inspection							RE	MSG-3 Zonal Inspection Tasks		
	57 A/F	5-12-06			Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
					Hrs					
	MRBR Task:57-500-01, MRBR Task:510-001, MRBR Task:511-001, MRBR Task:512-001, MRBR Task:521-001, MRBR Task:522-001, MRBR Task:531-001, MRBR Task:532-001, MRBR Task:542-001, MRBR Task:610-001, MRBR Task:611-001, MRBR Task:612-001, MRBR Task:621-001, MRBR Task:622-001, MRBR Task:631-001, MRBR Task:632-001, MRBR Task:641-001, MRBR Task:57-20-03-001, MRBR Task:57-50-02-001, MRBR Task:57-20-04-001 (ZONE: 611, 612, 615, 621, 622, 631, 632, 641) (SOURCE: 560 XL MM Section 5-10-01, 5-10-04, 5-12-06)				Ldg					
	Note: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-2101, 32-00-00-7100, and 53-10-00-2100									
57-00-00-2101 Left Wing Internal Zonal General Visual Inspection							RE	MSG-3 Zonal Inspection Tasks		
	57 A/F	5-12-06			Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
					Hrs					
	(ZONE: 513, 514, 515, 523, 524, 533, 534) (SOURCE: 560 XL MM Section 5-10-04)				Ldg					
	Note: NOTE: It is recommended you do Task 28-42-00-7100 before you do this task.NOTE: It is recommended you do this task at the same time as Task 57-00-00-2102									
57-00-00-2101 Right Wing Internal Zonal General Visual Inspection							RE	MSG-3 Zonal Inspection Tasks		
	57 A/F	5-12-06			Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
					Hrs					
	(ZONE: 613, 614, 615, 623, 624, 633, 634) (SOURCE: 560 XL MM Section 5-10-04)				Ldg					
	Note: NOTE: It is recommended you do Task 28-42-00-7100 before you do this task.NOTE: It is recommended you do this task at the same time as Task 57-00-00-2102									
57-00-00-2102 Left Wing Fuel Probe Wiring Harness Standalone EZAP General Visual Inspection							RE	MSG-3 EZAP Inspection Tasks		
	57 A/F	5-12-06			Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
					Hrs					
	(ZONE: 513, 514, 515, 523, 524, 533, 534) (SOURCE: 560 XL MM Section 5-10-05)				Ldg					
	Note: NOTE: It is recommended you do Task 28-42-00-7100 before you do this task. NOTE: It is recommended you do this task at the same time as Task 57-00-00-2101									
57-00-00-2102 Right Wing Fuel Probe Wiring Harness Standalone EZAP General Visual Inspection							RE	MSG-3 EZAP Inspection Tasks		
	57 A/F	5-12-06			Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)
					Hrs					
	(ZONE: 613, 614, 615, 623, 624, 633, 634) (SOURCE: 560 XL MM Section 5-10-05)				Ldg					
	Note: NOTE: It is recommended you do Task 28-42-00-7100 before you do this task. NOTE: It is recommended you do this task at the same time as Task 57-00-00-2101									
57-00-00-2200 Left Wing Cove and Rear Spar Structure and Corrosion Detailed Inspection							REMSG-3 Structures Inspection Tasks			
	57 A/F	5-12-01			Mos	22-May-2024	12	-/+1m	(31-May-2025)	7.6 Months (+30 Days)
					Hrs	1020:11				
	(ZONE: 512, 516, 522, 532) (SOURCE: 560 XL MM Section 5-10-03)				Ldg	698				
	Note: NOTE: This is a CPCP Task									
57-00-00-2200 Right Wing Cove and Rear Spar Structure and Corrosion Detailed Inspection							REMSG-3 Structures Inspection Tasks			
	57 A/F	5-12-01			Mos	22-May-2024	12	-/+1m	(31-May-2025)	7.6 Months (+30 Days)
					Hrs	1020:11				
	(ZONE: 614, 615, 624, 634) (SOURCE: 560 XL MM Section 5-10-03)				Ldq	698				
	Note: NOTE: This is a CPCP Task									

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note or Component Condition							DUE	Remaining
57-10-00-2100	Left Main Landing Gear Wheel Well and Door Internal Zonal General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks		
 57 A/F	5-12-06				Mos		48	-/+1m (30-Jun-2026)	1.7 Years (+30 Days)	
					Hrs					
		MRBR Task:731-001, MRBR Task:721- 001, MRBR Task:32-700-02 (ZONE: 730) (SOURCE: 560 XL MM Section 5-10-01, 5-10-04, 5-12-06)			Ldg					
		Note: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-2101, 32-00-00-7100, and 53-10-00-2100								
57-10-00-2100	Right Main Landing Gear Wheel Well and Door Internal Zonal General Visual Inspection						RE	MSG-3 Zonal Inspection Tasks		
 57 A/F	5-12-06				Mos		48	-/+1m 30-Jun-2026	1.7 Years (+30 Days)	
					Hrs					
		MRBR Task:731-001, MRBR Task:721- 001, MRBR Task:32-700-02 (ZONE: 720) (SOURCE: 560 XL MM Section 5-10-01, 5-10-04, 5-12-06)			Ldg					
		Note: NOTE: It is recommended you do this task at the same time as Tasks 32-00-00-2101, 32-00-00-7100, and 53-10-00-2100								
57-10-00-2101	Left and Right Wing Forward Spar (Forward Side) and Wing Tip Internal Standalone General Visual Inspection						REMSG-3 Structures Inspection Tasks			
 57 A/F	5-12-16				Mos		96	-/+1m (30-Jun-2030)	5.7 Years (+30 Days)	
					Hrs					
		(ZONE: 513, 523, 533, 541, 613, 623, 633, 642) (SOURCE: 560 XL MM Section 5-10-03)			Ldg					
		Note: NOTE: It is recommended you do this task at the same time as Task 57-30-01-2100								
57-10-00-2200	Left Main Landing Gear and Wheel Well Structure and Corrosion General Visual Inspection						REMSG-3 Structures Inspection Tasks			
 57 A/F	5-12-01				Mos	22-May-2024	12	-/+1m (31-May-2025)	7.6 Months (+30 Days)	
					Hrs	1020:11				
		(ZONE: 720) (SOURCE: 560 XL MM Section 5-10-03)			Ldg	698				
		Note: NOTE: This is a CPCP Task								
57-10-00-2200	Right Main Landing Gear and Wheel Well Structure and Corrosion General Visual Inspection						REMSG-3 Structures Inspection Tasks			
 57 A/F	5-12-01				Mos	22-May-2024	12	-/+1m (31-May-2025)	7.6 Months (+30 Days)	
					Hrs	1020:11				
		(ZONE: 730) (SOURCE: 560 XL MM Section 5-10-03)			Ldg	698				
		Note: NOTE: This is a CPCP Task								
57-10-00-2500	Left Lower Wing Main Spar Lower Skin Splice at WS 22.50 (Eddy Current and Ultrasonic) Special Detailed Inspection						T	Airworthiness Limitations Inspection Time Limits	≈29-Apr-2033	
 57 A/F	4-12-MF				Mos					
					Hrs	7,500		(7500)	6140:04 Hrs	
		(ZONE: 515) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)			Ldg					
57-10-00-2500	Right Lower Wing Main Spar Lower Skin Splice at WS 22.50 (Eddy Current and Ultrasonic) Special Detailed Inspection						T	Airworthiness Limitations Inspection Time Limits	≈29-Apr-2033	
 57 A/F	4-12-MF				Mos					
					Hrs	7,500		(7500)	6140:04 Hrs	
		(ZONE: 516) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)			Ldg					
57-10-00-2501	Left Lower Wing Main Spar Skin Splice Flange at WS 11.50 (Eddy Current and Ultrasonic) Special Detailed Inspection						T	Airworthiness Limitations Inspection Time Limits	≈24-Nov-2038	
 57 A/F	4-12-ML				Mos					
					Hrs	11,500		(11500)	10140:04 Hrs	
		(ZONE: 515) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)			Ldg					
57-10-00-2501	Right Lower Wing Main Spar Skin Splice Flange at WS 11.50 (Eddy Current and Ultrasonic) Special Detailed Inspection						T	Airworthiness Limitations Inspection Time Limits	≈24-Nov-2038	
 57 A/F	4-12-ML				Mos					
					Hrs	11,500		(11500)	10140:04 Hrs	
		(ZONE: 615) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)			Ldg					
57-10-00-2502	Left Lower Wing Main Spar at WS 114.57 (Eddy Current) Special Detailed Inspection						T	Airworthiness Limitations Inspection Time Limits	≈05-Aug-2039	
 57 A/F	4-12-MU				Mos					
					Hrs	12,000		(12000)	10640:04 Hrs	
		(ZONE: 523, 524) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)			Ldg					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
57-10-00-2502		Right Lower Wing Main Spar at WS 114.57 (Eddy Current) Special Detailed Inspection							T	Airworthiness Limitations Inspection Time Limits	≈05-Aug-2039
	57 A/F	4-12-MU (ZONE: 623, 624) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Mos					
						Hrs	12,000	(12000)	10640:04 Hrs		
						Ldg					
57-10-00-2503		Left Lower Wing Main Spar at WS 131.07 (Eddy Current) Special Detailed Inspection							T	Airworthiness Limitations Inspection Time Limits	≈20-Sep-2034
	57 A/F	4-12-MS (ZONE: 523, 524) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Mos					
						Hrs	8,500	(8500)	7140:04 Hrs		
						Ldg					
57-10-00-2503		Right Lower Wing Main Spar at WS 131.07 (Eddy Current) Special Detailed Inspection							T	Airworthiness Limitations Inspection Time Limits	≈20-Sep-2034
	57 A/F	4-12-MS (ZONE: 623, 624) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Mos					
						Hrs	8,500	(8500)	7140:04 Hrs		
						Ldg					
57-10-00-2504		Left Lower Wing Main Spar at WS 149.57 (Eddy Current) Special Detailed Inspection							T	Airworthiness Limitations Inspection Time Limits	≈22-Oct-2036
	57 A/F	4-12-MT (ZONE: 523, 524) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Mos					
						Hrs	10,000	(10000)	8640:04 Hrs		
						Ldg					
57-10-00-2504		Right Lower Wing Main Spar at WS 149.57 (Eddy Current) Special Detailed Inspection							T	Airworthiness Limitations Inspection Time Limits	≈22-Oct-2036
	57 A/F	4-12-MT (ZONE: 623, 624) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)				Mos					
						Hrs	10,000	(10000)	8640:04 Hrs		
						Ldg					
57-10-00-9600		Main Landing Gear Forward Trunnion Fitting							RE	Airworthiness Limitations Inspection Time Limits	≈15-Sep-2063
	57 A/F 6622123-5 508467-2 (ZONE: 730) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)	Left				Mos	22-Jun-2022				
			0			Hrs	0				
			0			Ldg	0	19,600	19,600	18,643 Ldg	
57-10-00-9600		Main Landing Gear Forward Trunnion Fitting							RE	Airworthiness Limitations Inspection Time Limits	≈15-Sep-2063
	57 A/F 6622123-6 511251-3 (ZONE: 720) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)	Right				Mos	22-Jun-2022				
			0			Hrs	0				
			0			Ldg	0	19,600	19,600	18,643 Ldg	
57-10-00-9601		Main Landing Gear Aft Trunnion Fitting							RE	Airworthiness Limitations Inspection Time Limits	≈15-Sep-2063
	57 A/F 6622124-5 505861-3 (ZONE: 730) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)	Left				Mos	22-Jun-2022				
			0			Hrs	0				
			0			Ldg	0	19,600	19,600	18,643 Ldg	
57-10-00-9601		Main Landing Gear Aft Trunnion Fitting							RE	Airworthiness Limitations Inspection Time Limits	≈15-Sep-2063
	57 A/F 6622124-6 566100-2 (ZONE: 720) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)	Right				Mos	22-Jun-2022				
			0			Hrs	0				
			0			Ldg	0	19,600	19,600	18,643 Ldg	

Task No	Description									Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
57-10-00-9602	Main Landing Gear Actuator Fitting						RE		Airworthiness Limitations Inspection Time Limits		≈22-Jan-2072
57 A/F	Left				Mos	22-Jun-2022					
6621125-9		0			Hrs	0					
508486-6		0			Ldg	0	23,600		23,600		22,643 Ldg
(ZONE: 730) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)											
57-10-00-9602	Main Landing Gear Actuator Fitting						RE		Airworthiness Limitations Inspection Time Limits		≈22-Jan-2072
57 A/F	Right				Mos	22-Jun-2022					
6621125-10		0			Hrs	0					
505066-1		0			Ldg	0	23,600		23,600		22,643 Ldg
(ZONE: 720) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)											
57-30-01-2100	Wing Tip Internal Zonal General Visual Inspection and Restoration						RE	05-10-01, 05-10-04, 05-10-05			
57 A/F	5-12-16				Mos		96	-/+1m	(30-Jun-2030)	5.7 Years (+30 Days)	
MRBR Task:642-001, MRBR Task:541-001, MRBR Task:57-500-03, MRBR Task:642-101E, MRBR Task:541-101E (ZONE: 541, 642) (SOURCE: 560XL MM)											
Note: NOTE: It is recommended you do this task at the same time as Task 57-10-00-2101											
57-50-03-2200	Aileron, Aileron Trim Tab and Hinge Brackets Detailed Inspection						REMSG-3 Structures Inspection Tasks				
57 A/F	5-12-06				Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)	
(ZONE: 532, 534, 632, 634) (SOURCE: 560 XL MM Section 5-10-03)											
Note: NOTE: It is recommended you do this task at the same time as Task 57-60-00-2200											
57-50-04-2900	Flap (Coin Tap) Special Detailed Inspection						REMSG-3 Structures Inspection Tasks				
57 A/F	Left Inboard5-12-06				Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)	
6525130-37					Hrs						
31172035					Ldg						
(ZONE: 512) (SOURCE: 560 XL MM Section 5-10-03)											
57-50-04-2900	Flap (Coin Tap) Special Detailed Inspection						REMSG-3 Structures Inspection Tasks				
57 A/F	Left Outboard5-12-06				Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)	
6525135-35					Hrs						
31238373					Ldg						
(ZONE: 612) (SOURCE: 560 XL MM Section 5-10-03)											
57-50-04-2900	Flap (Coin Tap) Special Detailed Inspection						REMSG-3 Structures Inspection Tasks				
57 A/F	Right Inboard5-12-06				Mos	11-Apr-2023	48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)	
6525130-38					Hrs	402:15					
32056723					Ldg						
(ZONE: 522) (SOURCE: 560 XL MM Section 5-10-03)											
57-50-04-2900	Flap (Coin Tap) Special Detailed Inspection						REMSG-3 Structures Inspection Tasks				
57 A/F	Right Outboard5-12-06				Mos		48	-/+1m	(30-Jun-2026)	1.7 Years (+30 Days)	
6525135-36					Hrs						
31238371					Ldg						
(ZONE: 612) (SOURCE: 560 XL MM Section 5-10-03)											
57-50-04-9600	Left Wing Aft Flap Roller						RE		Airworthiness Limitations Inspection Time Limits		≈22-Mar-2033
57 A/F	Left Inboard				Mos	22-Jun-2022					
S3049-5F8		0			Hrs	0					
Unknown		0			Ldg	0	5,000		5,000		4,043 Ldg
(ZONE: 500) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)											
57-50-04-9600	Left Wing Aft Flap Roller						RE		Airworthiness Limitations Inspection Time Limits		≈22-Mar-2033
57 A/F	Left Outboard				Mos	22-Jun-2022					
S3049-5F8		0			Hrs	0					
Unknown		0			Ldg	0	5,000		5,000		4,043 Ldg
(ZONE: 500) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)											

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
57-50-04-9600		Left Wing Aft Flap Roller						RE		Airworthiness Limitations Inspection Time Limits	≈22-Mar-2033
⚙	57 A/F	Right Inboard				Mos	22-Jun-2022				
	S3049-5F8		0			Hrs	0				
	Unknown		0			Ldg	0	5,000		5,000	4,043 Ldg
(ZONE: 500) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)											
57-50-04-9600		Left Wing Aft Flap Roller						RE		Airworthiness Limitations Inspection Time Limits	≈22-Mar-2033
⚙	57 A/F	Right Outboard				Mos	22-Jun-2022				
	S3049-5F8		0			Hrs	0				
	Unknown		0			Ldg	0	5,000		5,000	4,043 Ldg
(ZONE: 500) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)											
57-50-04-9600		Left Wing Fwd Flap Roller						RE		Airworthiness Limitations Inspection Time Limits	≈22-Mar-2033
⚙	57 A/F	Left Inboard				Mos	22-Jun-2022				
	S3049-5F8		0			Hrs	0				
	Unknown		0			Ldg	0	5,000		5,000	4,043 Ldg
(ZONE: 500) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)											
57-50-04-9600		Left Wing Fwd Flap Roller						RE		Airworthiness Limitations Inspection Time Limits	≈22-Mar-2033
⚙	57 A/F	Left Outboard				Mos	22-Jun-2022				
	S3049-5F8		0			Hrs	0				
	Unknown		0			Ldg	0	5,000		5,000	4,043 Ldg
(ZONE: 500) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)											
57-50-04-9600		Left Wing Fwd Flap Roller						RE		Airworthiness Limitations Inspection Time Limits	≈22-Mar-2033
⚙	57 A/F	Right Inboard				Mos	22-Jun-2022				
	S3049-5F8		0			Hrs	0				
	Unknown		0			Ldg	0	5,000		5,000	4,043 Ldg
(ZONE: 500) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)											
57-50-04-9600		Left Wing Fwd Flap Roller						RE		Airworthiness Limitations Inspection Time Limits	≈22-Mar-2033
⚙	57 A/F	Right Outboard				Mos	22-Jun-2022				
	S3049-5F8		0			Hrs	0				
	Unknown		0			Ldg	0	5,000		5,000	4,043 Ldg
(ZONE: 500) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)											
57-50-04-9600		Right Wing Aft Flap Roller						RE		Airworthiness Limitations Inspection Time Limits	≈22-Mar-2033
⚙	57 A/F	Left Inboard				Mos	22-Jun-2022				
	S3049-5F8		0			Hrs	0				
	Unknown		0			Ldg	0	5,000		5,000	4,043 Ldg
(ZONE: 600) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)											
57-50-04-9600		Right Wing Aft Flap Roller						RE		Airworthiness Limitations Inspection Time Limits	≈22-Mar-2033
⚙	57 A/F	Left Outboard				Mos	22-Jun-2022				
	S3049-5F8		0			Hrs	0				
	Unknown		0			Ldg	0	5,000		5,000	4,043 Ldg
(ZONE: 600) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)											
57-50-04-9600		Right Wing Aft Flap Roller						RE		Airworthiness Limitations Inspection Time Limits	≈22-Mar-2033
⚙	57 A/F	Right Inboard				Mos	22-Jun-2022				
	S3049-5F8		0			Hrs	0				
	Unknown		0			Ldg	0	5,000		5,000	4,043 Ldg
(ZONE: 600) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)											

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
57-50-04-9600		Right Wing Aft Flap Roller						RE	Airworthiness Limitations Inspection Time Limits		≈22-Mar-2033	
	57 A/F	Right Outboard					Mos	22-Jun-2022				
	S3049-5F8		0				Hrs	0				
	Unknown		0				Ldg	0	5,000	5,000	4,043 Ldg	
(ZONE: 600) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)												
57-50-04-9600		Right Wing Fwd Flap Roller						RE	Airworthiness Limitations Inspection Time Limits		≈22-Mar-2033	
	57 A/F	Left Inboard					Mos	22-Jun-2022				
	S3049-5F8		0				Hrs	0				
	Unknown		0				Ldg	0	5,000	5,000	4,043 Ldg	
(ZONE: 600) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)												
57-50-04-9600		Right Wing Fwd Flap Roller						RE	Airworthiness Limitations Inspection Time Limits		≈22-Mar-2033	
	57 A/F	Left Outboard					Mos	22-Jun-2022				
	S3049-5F8		0				Hrs	0				
	Unknown		0				Ldg	0	5,000	5,000	4,043 Ldg	
(ZONE: 600) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)												
57-50-04-9600		Right Wing Fwd Flap Roller						RE	Airworthiness Limitations Inspection Time Limits		≈22-Mar-2033	
	57 A/F	Right Inboard					Mos	22-Jun-2022				
	S3049-5F8		0				Hrs	0				
	Unknown		0				Ldg	0	5,000	5,000	4,043 Ldg	
(ZONE: 600) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)												
57-50-04-9600		Right Wing Fwd Flap Roller						RE	Airworthiness Limitations Inspection Time Limits		≈22-Mar-2033	
	57 A/F	Right Outboard					Mos	22-Jun-2022				
	S3049-5F8						Hrs	0				
	Unknown		0				Ldg	0	5,000	5,000	4,043 Ldg	
(ZONE: 600) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)												
▼ 58 - *Unassigned												
57-60-00-2200		Aileron, Aileron Wing Sectors and Aileron Trim Components Structure Detailed Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS, MSG-3 Structures Inspection Tasks			
	58 A/F	5-12-06					Mos		48	-/+1m (30-Jun-2026)	1.7 Years (+30 Days)	
							Hrs					
		MRBR Task:27-10-00-213, MRBR Task:27-10-01-001, MRBR Task:27-10-01-002 (ZONE: 141, 142, 153, 154, 236, 241, 242, 248, 512, 522, 523, 532, 534, 612, 622, 632, 634) (SOURCE: 560 XL MM Section 5-10-01, 5-10-02, 5-10-03) Note: NOTE: It is recommended you do this task at the same time as Task 57-50-03-2200					Ldg					
▼ 71 - POWER PLANT												
		Engine Aft Isolator						RE (O/C)				
	71 A/F	Left					Mos	22-Jun-2022				
	LM451-SA2						Hrs	0				
	LK2209						Ldg	0				
		Engine Aft Isolator						RE (O/C)				
	71 A/F	Right					Mos	22-Jun-2022				
	LM451-SA2						Hrs	0				
	LK2211						Ldg	0				
		Engine Vibration Monitor						RE (O/C)				
	71 A/F						Mos	22-Jun-2022				
	2789						Hrs	0				
	00084						Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time Remaining
SEQ	PN/SN	MOC Note or Component Condition							DUE	
	71 A/F LM451-SA4 LK4921	Forward Engine Isolator Lower - Left					RE (O/C)			
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
	71 A/F LM451-SA4 LK4911	Forward Engine Isolator Lower - Right					RE (O/C)			
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
	71 A/F LM451-SA4 LK4927	Forward Engine Isolator Upper - Left					RE (O/C)			
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
	71 A/F LM451-SA4 LK4906	Forward Engine Isolator Upper - Right					RE (O/C)			
					Mos	22-Jun-2022				
					Hrs	0				
					Ldg	0				
54-50-01-2101	Left Engine Cowling, Engine Pylon Firewall General Visual Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	71 A/F	5-12-06 (ZONE: 410) (SOURCE: 560 XL MM Section 5-10-02) Note: NOTE: It is recommended you do this task at the same time as Task 71-00-00-2201				Mos		48	-/+1m (30-Jun-2026)	1.7 Years (+30 Days)
					Hrs					
					Ldg					
54-50-01-2101	Right Engine Cowling, Engine Pylon Firewall General Visual Inspection						RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		
	71 A/F	5-12-06 (ZONE: 420) (SOURCE: 560 XL MM Section 5-10-02) Note: NOTE: It is recommended you do this task at the same time as Task 71-00-00-2201				Mos		48	-/+1m (30-Jun-2026)	1.7 Years (+30 Days)
					Hrs					
					Ldg					
560XL-71-11	Engine Fuel Manifold Drain Line Installation Revision 1						RE (-)		Optional	
	71 A/F					Mos				
					Hrs					
					Ldg					
560XL-71-11 Rev 01	Engine Fuel Manifold Drain Line Installation Revision 1						T (A/R)		Optional	
	71 A/F Eff: 02-Aug-2012					Mos				
					Hrs					
					Ldg					
560XL-71-12	Engine Fuel Manifold Drain Line Removal						T (A/R)		Optional	
	71 A/F Eff: 01-Oct-2012					Mos				
					Hrs					
					Ldg					
71-00-00-2100	Left Engine Fire Detection Element Standalone EZAP General Visual Inspection						RE	MSG-3 EZAP Inspection Tasks		
	71 A/F	5-12-03 (ZONE: 410) (SOURCE: 560 XL MM Section 5-10-05) Note: NOTE: It is recommended you do this task at the same time as Tasks 54-50-01-2100 and 71-00-00-2200				Mos	22-May-2024	24	-/+1m (31-May-2026)	1.6 Years (+30 Days)
					Hrs	1020:11				
					Ldg	698				
71-00-00-2100	Right Engine Fire Detection Element Standalone EZAP General Visual Inspection						RE	MSG-3 EZAP Inspection Tasks		
	71 A/F	5-12-03 (ZONE: 420) (SOURCE: 560 XL MM Section 5-10-05) Note: NOTE: It is recommended you do this task at the same time as Tasks 54-50-01-2100 and 71-00-00-2200				Mos	22-May-2024	24	-/+1m (31-May-2026)	1.6 Years (+30 Days)
					Hrs	1020:11				
					Ldg	698				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
71-00-00-2200 Left Engine Starter Generator, Alternator, Alternator PCU, Full Authority Digital Electronic Control L/HIRF Detailed Inspection											
	71 A/F	5-12-03					Mos	22-May-2024	24	MSG-3 L/HIRF Inspection Tasks	
							Hrs	1020:11		-(+1m (31-May-2026)	1.6 Years (+30 Days)
							Ldg	698			
(ZONE: 410) (SOURCE: 560 XL MM Section 5-10-06)											
Note: NOTE: It is recommended you do this task at the same time as Tasks 54-50-01-2100 and 71-00-00-2100											
71-00-00-2200 Right Engine Starter Generator, Alternator, Alternator PCU, Full Authority Digital Electronic Control L/HIRF Detailed Inspection											
	71 A/F	5-12-03					Mos	22-May-2024	24	MSG-3 L/HIRF Inspection Tasks	
							Hrs	1020:11		-(+1m (31-May-2026)	1.6 Years (+30 Days)
							Ldg	698			
(ZONE: 420) (SOURCE: 560 XL MM Section 5-10-06)											
Note: NOTE: It is recommended you do this task at the same time as Tasks 54-50-01-2100 and 71-00-00-2100											
71-00-00-2201 Left Engine Cowling L/HIRF Detailed Inspection											
	71 A/F	5-12-06					Mos		48	MSG-3 L/HIRF Inspection Tasks	
							Hrs			-(+1m (30-Jun-2026)	1.7 Years (+30 Days)
							Ldg				
(ZONE: 430, 440) (SOURCE: 560 XL MM Section 5-10-06)											
Note: NOTE: It is recommended you do this task at the same time as Task 54-50-01-2101											
71-00-00-2201 Right Engine Cowling L/HIRF Detailed Inspection											
	71 A/F	5-12-06					Mos		48	MSG-3 L/HIRF Inspection Tasks	
							Hrs			-(+1m (30-Jun-2026)	1.7 Years (+30 Days)
							Ldg				
(ZONE: 430, 440) (SOURCE: 560 XL MM Section 5-10-06)											
Note: NOTE: It is recommended you do this task at the same time as Task 54-50-01-2101											
71-00-PW-009 Engine Externals and Compressor Wash (Desalination)											
	71 ENG1							RE (A/R)		EMM - Requirement	
							Days				
							Hrs				
							Enc				
Ref:71-00-00-cl											
Note: As general observations warrant. As necessary by ECTM or at every approx. 20 °C ITT increase. Also by visual inspection of compressor gas path when you operate the engine in an adverse environment											
71-00-PW-009 Engine Externals and Compressor Wash (Desalination)											
	71 ENG2							RE (A/R)		EMM - Requirement	
							Days				
							Hrs				
							Enc				
Ref:71-00-00-cl											
Note: As general observations warrant. As necessary by ECTM or at every approx. 20 °C ITT increase. Also by visual inspection of compressor gas path when you operate the engine in an adverse environment											
71-22-00-9600 Engine Aft Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration											
	71 A/F	Left					Mos			5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈14-Mar-2038
	LM451-SA2						Hrs	11,000	+50	11000	9640:04 Hrs (+50)
	LK2209						Ldg				
(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											
Note: Every Second Engine Overhaul, Not To Exceed 11,000 Flight Hours NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored Forward Engine Isolator Mount and/or reference LORD Corporation 71-20-55 Component Maintenance Manual											
71-22-00-9600 Engine Aft Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration											
	71 A/F	Right					Mos			5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈14-Mar-2038
	LM451-SA2						Hrs	11,000	+50	11000	9640:04 Hrs (+50)
	LK2211						Ldg				
(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)											
Note: Every Second Engine Overhaul, Not To Exceed 11,000 Flight Hours NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored Forward Engine Isolator Mount and/or reference LORD Corporation 71-20-55 Component Maintenance Manual											

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
71-22-00-9600		Engine Forward Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈14-Mar-2038
	71 A/F	Lower - Left				Mos					
	LM451-SA4					Hrs		11,000	+50	11000	9640:04 Hrs (+50)
	LK4921					Ldg					
(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) Note: Every Second Engine Overhaul, Not To Exceed 11,000 Flight Hours NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored Forward Engine Isolator Mount and/or reference LORD Corporation 71-20-55 Component Maintenance Manual											
71-22-00-9600		Engine Forward Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈14-Mar-2038
	71 A/F	Lower - Right				Mos					
	LM451-SA4					Hrs		11,000	+50	11000	9640:04 Hrs (+50)
	LK4911					Ldg					
(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) Note: Every Second Engine Overhaul, Not To Exceed 11,000 Flight Hours NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored Forward Engine Isolator Mount and/or reference LORD Corporation 71-20-55 Component Maintenance Manual											
71-22-00-9600		Engine Forward Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈14-Mar-2038
	71 A/F	Upper - Left				Mos					
	LM451-SA4					Hrs		11,000	+50	11000	9640:04 Hrs (+50)
	LK4927					Ldg					
(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) Note: Every Second Engine Overhaul, Not To Exceed 11,000 Flight Hours NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored Forward Engine Isolator Mount and/or reference LORD Corporation 71-20-55 Component Maintenance Manual											
71-22-00-9600		Engine Forward Isolator Mount (Metal Parts Detailed Inspection and Special Detailed Inspection and Housing Bushing Functional Check) Restoration							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈14-Mar-2038
	71 A/F	Upper - Right				Mos					
	LM451-SA4					Hrs		11,000	+50	11000	9640:04 Hrs (+50)
	LK4906					Ldg					
(SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00) Note: Every Second Engine Overhaul, Not To Exceed 11,000 Flight Hours NOTE: You may contact Textron Aviation Parts Department (TAPD) at 316-517-6002 for assistance with obtaining a properly restored Forward Engine Isolator Mount and/or reference LORD Corporation 71-20-55 Component Maintenance Manual											
71-71-00-2100		Left Engine Drains General Visual Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈25-Mar-2026
	71 A/F	5-12-08				Mos					
						Hrs		2,400	-/+25	(2400)	1040:04 Hrs (+25)
		(ZONE: 410) (SOURCE: 560 XL MM Section 5-10-02)				Ldg					
71-71-00-2100		Right Engine Drains General Visual Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈25-Mar-2026
	71 A/F	5-12-08				Mos					
						Hrs		2,400	-/+25	(2400)	1040:04 Hrs (+25)
		(ZONE: 420) (SOURCE: 560 XL MM Section 5-10-02)				Ldg					
CIL-71-01		Transmittal of Pratt & Whitney Canada Service Bulletin 30463							RE (-)		Optional
	71 A/F					Mos					
	Eff: 29-Jan-2013					Hrs					
						Ldg					
SIL-PW500-068		PW500 Engine Calibration Check							T (A/R)		Service Information Letter
	71 ENG1					Mos					
	Eff: 31-May-2017					Hrs					
						Enc					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-PW500-068	PW500 Engine Calibration Check						T (A/R)		Service Information Letter	
 71 ENG2						Mos				
Eff: 31-May-2017						Hrs				
						Enc				
SL560XL-71-01	Power Plant - Transmittal Of Aeroquip Aerospace Service Bulletin ASB125 How To Repair Silicone Covered Hose Abrasions Using AE272 Flexwrap Firesleeve						T (A/R)		Informational	
 71 A/F						Mos				
Eff: 21-Jan-2001						Hrs				
						Ldg				
SL560XL-71-09	Transmittal of Pratt & Whitney Canada (P&WC) Service Bulletin Number 30294R2, Turbofan Engine Oil Tank Filler Cap Inspection Of						T (A/R)		Informational	
 71 A/F						Mos				
Eff: 15-Jun-2006						Hrs				
						Ldg				
SL560XL-71-11	Power Plant - Inspect the Left and Right Engine Forward Upper and Lower Isolator Assembly Mount Bolt Heads for Safety Wire Holes						RE (-)		Recommended, Service Letter	
 71 A/F						Mos	22-Jun-2022			
Eff: 15-Aug-2019 Not Applicable	by aircraft S/N					Hrs	8			
(AVG MAN HRS: 4)						Ldg	6			
SL560XL-71-11 R1	Power Plant - Inspect the Left and Right Engine Forward Upper and Lower Isolator Assembly Mount Bolt Heads for Safety Wire Holes						RE (-)		Recommended, Service Letter	
 71 A/F						Mos	22-Jun-2022			
Eff: 29-Aug-2019 Not Applicable	by aircraft S/N					Hrs	8			
(AVG MAN HRS: 4)						Ldg	6			
SL560XL-71-11 R2	Power Plant - Inspect the Left and Right Engine Forward Upper and Lower Isolator Assembly Mount Bolt Heads for Safety Wire Holes						RE (-)		Recommended, Service Letter	
 71 A/F						Mos	22-Jun-2022			
Eff: 23-Oct-2019 Not Applicable	by aircraft S/N					Hrs	8			
(AVG MAN HRS: 4)						Ldg	6			
▼ 72 - ENGINE										
	1st Stage HP Compressor Rotor						RE		EMM - Life Limit	≈21-Dec-2050
 72 ENG1						Mos	30-Dec-2021			
30J2821-01	New					Hrs	0			
A005156A		0				Enc	0	13,500	13,500	12,543 Enc
	1st Stage HP Compressor Rotor						RE		EMM - Life Limit	≈02-Jun-2051
 72 ENG2						Mos	31-Dec-2021			
30J2821-01	New	0				Hrs	0			
A0050ET5		0				Enc	0	13,500	13,500	12,758 Enc
	1st-Stage Turbine Disk						RE		EMM - Life Limit	≈21-Dec-2050
 72 ENG1						Mos	30-Dec-2021			
30J3461-01	New					Hrs	0			
A0050NK7		0				Enc	0	13,500	13,500	12,543 Enc
	1st-Stage Turbine Disk						RE		EMM - Life Limit	≈02-Jun-2051
 72 ENG2						Mos	31-Dec-2021			
30J3461-01	New	0				Hrs	0			
A00512P8		0				Enc	0	13,500	13,500	12,758 Enc
	2nd Stage HP Compressor Rotor						RE		EMM - Life Limit	≈21-Dec-2050
 72 ENG1						Mos	30-Dec-2021			
30J2429-01	New					Hrs	0			
EAAF000D681		0				Enc	0	13,500	13,500	12,543 Enc

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR, SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG2 30J2429-01 EAAF000D679	2nd Stage HP Compressor Rotor New							RE	EMM - Life Limit	≈02-Jun-2051
							Mos	31-Dec-2021			
							Hrs	0			
							Enc	0	13,500	13,500	12,758 Enc
	72 ENG1 30H3172 ABT07225	2nd-Stage Turbine Disk New							RE	EMM - Life Limit	≈21-Dec-2050
							Mos	30-Dec-2021			
							Hrs	0			
							Enc	0	13,500	13,500	12,543 Enc
	72 ENG2 30H3172 ABT07224	2nd-Stage Turbine Disk New							RE	EMM - Life Limit	≈02-Jun-2051
							Mos	31-Dec-2021			
							Hrs	0			
							Enc	0	13,500	13,500	12,758 Enc
	72 ENG1 30H3173 ABT07128	3rd-Stage Turbine Disk New							RE	EMM - Life Limit	≈21-Dec-2050
							Mos	30-Dec-2021			
							Hrs	0			
							Enc	0	13,500	13,500	12,543 Enc
	72 ENG2 30H3173 ABT06700	3rd-Stage Turbine Disk New							RE	EMM - Life Limit	≈02-Jun-2051
							Mos	31-Dec-2021			
							Hrs	0			
							Enc	0	13,500	13,500	12,758 Enc
	72 ENG1 30H3174 ABT07085	4th-Stage Turbine Disk New							RE	EMM - Life Limit	≈21-Dec-2050
							Mos	30-Dec-2021			
							Hrs	0			
							Enc	0	13,500	13,500	12,543 Enc
	72 ENG2 30H3174 ABT07102	4th-Stage Turbine Disk New							RE	EMM - Life Limit	≈02-Jun-2051
							Mos	31-Dec-2021			
							Hrs	0			
							Enc	0	13,500	13,500	12,758 Enc
	72 ENG1 30J2973-01 PKAAA933278	AC, Alternator Drive Spur Gearshaft Assembly New							RE (O/C)		
							Mos	30-Dec-2021			
							Hrs	0			
							Enc	0			
	72 ENG2 30J2973-01 PKAAA933279	AC, Alternator Drive Spur Gearshaft Assembly New							RE (O/C)		
							Mos	31-Dec-2021			
							Hrs	0			
							Enc	0			
	72 ENG1 30J3620-01 PKAAA925837	Accessory Drive Gearshaft Assembly New							RE (O/C)		
							Mos	30-Dec-2021			
							Hrs	0			
							Enc	0			
	72 ENG2 30J3620-01 PKAAA925820	Accessory Drive Gearshaft Assembly New							RE (O/C)		
							Mos	31-Dec-2021			
							Hrs	0			
							Enc	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Accessory Gearbox Shaft								RE (O/C)	
	72 ENG1	New					Mos	30-Dec-2021			
	30J2937-01						Hrs	0			
	PKAAA945053						Enc	0			
		Accessory Gearbox Shaft								RE (O/C)	
	72 ENG2	New					Mos	31-Dec-2021			
	30J2937-01						Hrs	0			
	PKAAA945052						Enc	0			
		Annular Ball Bearing								RE (O/C)	
	72 ENG1	New					Mos	30-Dec-2021			
	30J3207-01						Hrs	0			
	AEB0344696						Enc	0			
		Annular Ball Bearing								RE (O/C)	
	72 ENG2	New					Mos	31-Dec-2021			
	31J2196-01						Hrs	0			
	AEB0344695						Enc	0			
		Anti-Icing Valve								RE (O/C)	
	72 ENG1	New					Mos	30-Dec-2021			
	30J4184						Hrs	0			
	5617						Enc	0			
		Anti-Icing Valve								RE (O/C)	
	72 ENG2	New					Mos	31-Dec-2021			
	30J4184						Hrs	0			
	5622						Enc	0			
		Bearing - Roller, Cylindrical								RE (O/C)	
	72 ENG1	Unknown Unknown					Mos	30-Dec-2021			
	Unknown						Hrs	0			
	Unknown						Enc	0			
		Bearing - Roller, Cylindrical								RE (O/C)	
	72 ENG2	Unknown Unknown					Mos	31-Dec-2021			
	Unknown						Hrs	0			
	Unknown						Enc	0			
		Bearing Seal Runner								RE (O/C)	
	72 ENG1	No.3 New					Mos	30-Dec-2021			
	31J2757-01						Hrs	0			
	AFD01F684						Enc	0			
		Bearing Seal Runner								RE (O/C)	
	72 ENG2	No.3 New					Mos	31-Dec-2021			
	31J2757-01						Hrs	0			
	AFD01F682						Enc	0			
		Bearing-rlr, .9453x1.6535x.4724, FLG								RE (O/C)	
	72 ENG1	No.1 New					Mos	30-Dec-2021			
	31J2637-01						Hrs	0			
	FAA2102896						Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG2 30J3209-01 AEB0357955	Bearing-rlr, .9453x1.6535x.4724, FLG No.1 New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
							Enc	0			
	72 ENG1 31J2637-01 FAA2102902	Bearing-rlr, .9453x1.6535x.4724, FLG No.2 New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			
							Enc	0			
	72 ENG2 30J3209-01 AEB0357959	Bearing-rlr, .9453x1.6535x.4724, FLG No.2 New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
							Enc	0			
	72 ENG1 30J1450-01 A004NF4H	Centrifugal Impeller New						RE		EMM - Life Limit	≈21-Dec-2050
							Mos	30-Dec-2021			
							Hrs	0			
			0	Enc	0	13,500	13,500	12,543 Enc			
	72 ENG2 30J1450-01 A004NBP5	Centrifugal Impeller New						RE		EMM - Life Limit	≈02-Jun-2051
							Mos	31-Dec-2021			
			0	Hrs	0						
			0	Enc	0	13,500	13,500	12,758 Enc			
	72 ENG1 30J2486-01 FAA2107697	Cyl Roller Bearing New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			
							Enc	0			
	72 ENG2 Unknown Unknown	Cyl Roller Bearing						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
							Enc	0			
	72 ENG1 30J3670-01 FCN547179	Cylindrical Roller Bearing New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			
							Enc	0			
	72 ENG2 30J3670-01 FCN547153	Cylindrical Roller Bearing New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
							Enc	0			
	72 ENG1 30J3460-01 BDA35964367	Fan Case Assembly New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			
							Enc	0			
	72 ENG2 30J3460-01 BDA35964368	Fan Case Assembly New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
							Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Flanged Ball Bearing								RE (O/C)	
	72 ENG1	New					Mos	30-Dec-2021			
	30J3209-01						Hrs	0			
	AEB0357957						Enc	0			
		Flanged Ball Bearing								RE (O/C)	
	72 ENG1	New					Mos	30-Dec-2021			
	30J3209-01						Hrs	0			
	FAA2105355						Enc	0			
		Flanged Ball Bearing								RE (O/C)	
	72 ENG1	New					Mos	30-Dec-2021			
	30J3209-01						Hrs	0			
	AEB0359965						Enc	0			
		Flanged Ball Bearing								RE (O/C)	
	72 ENG2	New					Mos	31-Dec-2021			
	30J2936-01						Hrs	0			
	FAA2105335						Enc	0			
		Flanged Ball Bearing								RE (O/C)	
	72 ENG2	Unknown Unknown					Mos	31-Dec-2021			
	Unknown						Hrs	0			
	Unknown						Enc	0			
		Flanged Ball Bearing								RE (O/C)	
	72 ENG2	Unknown Unknown					Mos	31-Dec-2021			
	Unknown						Hrs	0			
	Unknown						Enc	0			
		Flanged Roller Bearing								RE (O/C)	
	72 ENG1	New					Mos	30-Dec-2021			
	31J2196-01						Hrs	0			
	FAA2104672						Enc	0			
		Flanged Roller Bearing								RE (O/C)	
	72 ENG2	New					Mos	31-Dec-2021			
	31J2196-01						Hrs	0			
	FAA2104671						Enc	0			
		Flanged Roller Bearing								RE (O/C)	
	72 ENG1	No.2 New					Mos	30-Dec-2021			
	30J3209-01						Hrs	0			
	AEB0357949						Enc	0			
		Flanged Roller Bearing								RE (O/C)	
	72 ENG2	No.2 Unknown Unknown					Mos	31-Dec-2021			
	Unknown						Hrs	0			
	Unknown						Enc	0			
		Flanged Roller Bearing								RE (O/C)	
	72 ENG1	No.3 New					Mos	30-Dec-2021			
	30J3209-01						Hrs	0			
	AEB0357965						Enc	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
72 ENG2 30J3209-01 AEB0357960		Flanged Roller Bearing No.3 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J3209-01 AEB0357968		Flanged Roller Bearing No.4 New								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J3209-01 AEB0357966		Flanged Roller Bearing No.4 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J3209-01 AEB0357970		Flanged Roller Bearing No.5 New								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J3209-01 AEB0357971		Flanged Roller Bearing No.5 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J3209-01 AEB0357975		Flanged Roller Bearing No.6 New								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J3209-01 AEB0357972		Flanged Roller Bearing No.6 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J3651-01 MDA21016822		Front Bearing Seal Runner No.4 New								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J3651-01 MDA21016858		Front Bearing Seal Runner No.4 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J3357-01 KYAA032A159		Front Outer Bypass Duct Assy New								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J3357-01 KYAA030A094		Front Outer Bypass Duct Assy New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG1	New					Mos	30-Dec-2021	RE (O/C)		
	30J3519-01						Hrs	0			
	RWA29H040						Enc	0			
	72 ENG2	New					Mos	31-Dec-2021	RE (O/C)		
	30J3519-01						Hrs	0			
	RWA24H523						Enc	0			
	72 ENG1	New					Mos	30-Dec-2021	RE (O/C)		
	30J2801-01						Hrs	0			
	A0051TEE						Enc	0			
	72 ENG2	New					Mos	31-Dec-2021	RE (O/C)		
	30J2801-01						Hrs	0			
	A0052027						Enc	0			
	72 ENG1	New					Mos	30-Dec-2021	RE (O/C)		
	31J1654-01						Hrs	0			
	PKAAA948709						Enc	0			
	72 ENG2	New					Mos	31-Dec-2021	RE (O/C)		
	31J1654-01						Hrs	0			
	PKAAA935831						Enc	0			
	72 ENG1	New					Mos	30-Dec-2021	RE (O/C)		
	30J3619-01						Hrs	0			
	PKAAA940973						Enc	0			
	72 ENG2	New					Mos	31-Dec-2021	RE (O/C)		
	30J3619-01						Hrs	0			
	PKAAA932058						Enc	0			
	72 ENG1	New					Mos	30-Dec-2021	RE (O/C)		
	30J2997-01						Hrs	0			
	EAAF000E096						Enc	0			
	72 ENG2	New					Mos	31-Dec-2021	RE (O/C)		
	30J2997-01						Hrs	0			
	EAAF000D896						Enc	0			
	72 ENG1	No.1 New					Mos	30-Dec-2021	RE (O/C)		
	30J1581-01						Hrs	0			
	HA002N4C						Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
72 ENG2 30J1581-01 HA001TH0		High Pressure Turbine Blade No.1 New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002M3X		High Pressure Turbine Blade No.10 New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA002451		High Pressure Turbine Blade No.10 New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002M40		High Pressure Turbine Blade No.11 New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA002456		High Pressure Turbine Blade No.11 New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002M47		High Pressure Turbine Blade No.12 New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA0024EA		High Pressure Turbine Blade No.12 New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002M49		High Pressure Turbine Blade No.13 New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA0024EB		High Pressure Turbine Blade No.13 New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002M4B		High Pressure Turbine Blade No.14 New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA0024EN		High Pressure Turbine Blade No.14 New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG1	High Pressure Turbine Blade No.15						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002MD6						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.15						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA0028P9						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.16						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002MDH						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.16						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA0029AB						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.17						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002MDT						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.17						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA0029DT						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.18						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002ME4						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.18						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA0029E2						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.19						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002MLD						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.19						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA0029F5						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.2						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002B4D						Hrs	0			
							Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG2 30J1581-01 HA001TLT	High Pressure Turbine Blade No.2 New					Mos	31-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG1 30J1581-01 HA002MLF	High Pressure Turbine Blade No.20 New					Mos	30-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG2 30J1581-01 HA0029FH	High Pressure Turbine Blade No.20 New					Mos	31-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG1 30J1581-01 HA002MLH	High Pressure Turbine Blade No.21 New					Mos	30-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG2 30J1581-01 HA002K1H	High Pressure Turbine Blade No.21 New					Mos	31-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG1 30J1581-01 HA002MLW	High Pressure Turbine Blade No.22 New					Mos	30-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG2 30J1581-01 HA002KKX	High Pressure Turbine Blade No.22 New					Mos	31-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG1 30J1581-01 HA002MLX	High Pressure Turbine Blade No.23 New					Mos	30-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG2 30J1581-01 HA002KLK	High Pressure Turbine Blade No.23 New					Mos	31-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG1 30J1581-01 HA002MT3	High Pressure Turbine Blade No.24 New					Mos	30-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG2 30J1581-01 HA002W5Y	High Pressure Turbine Blade No.24 New					Mos	31-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
72 ENG1 30J1581-01 HA002MT7		High Pressure Turbine Blade No.25 New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA002W61		High Pressure Turbine Blade No.25 New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002MTP		High Pressure Turbine Blade No.26 New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA002W86		High Pressure Turbine Blade No.26 New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002MWX		High Pressure Turbine Blade No.27 New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA002WAC		High Pressure Turbine Blade No.27 New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002MX4		High Pressure Turbine Blade No.28 New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA002WAP		High Pressure Turbine Blade No.28 New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002MX5		High Pressure Turbine Blade No.29 New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA002WEW		High Pressure Turbine Blade No.29 New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002B92		High Pressure Turbine Blade No.3 New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG2 30J1581-01 HA001TM5	High Pressure Turbine Blade No.3 New					Mos	31-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG1 30J1581-01 HA002MX7	High Pressure Turbine Blade No.30 New					Mos	30-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG2 30J1581-01 HA002WEY	High Pressure Turbine Blade No.30 New					Mos	31-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG1 30J1581-01 HA002MX8	High Pressure Turbine Blade No.31 New					Mos	30-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG2 30J1581-01 HA002WF6	High Pressure Turbine Blade No.31 New					Mos	31-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG1 30J1581-01 HA002MXE	High Pressure Turbine Blade No.32 New					Mos	30-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG2 30J1581-01 HA002WKW	High Pressure Turbine Blade No.32 New					Mos	31-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG1 30J1581-01 HA002MXL	High Pressure Turbine Blade No.33 New					Mos	30-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG2 30J1581-01 HA002WM8	High Pressure Turbine Blade No.33 New					Mos	31-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG1 30J1581-01 HA002MXN	High Pressure Turbine Blade No.34 New					Mos	30-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
	72 ENG2 30J1581-01 HA002WMD	High Pressure Turbine Blade No.34 New					Mos	31-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
72 ENG1 30J1581-01 HA002N01		High Pressure Turbine Blade No.35 New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA002WME		High Pressure Turbine Blade No.35 New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002N0D		High Pressure Turbine Blade No.36 New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA002WMM		High Pressure Turbine Blade No.36 New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002N0H		High Pressure Turbine Blade No.37 New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA002WMR		High Pressure Turbine Blade No.37 New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002N0W		High Pressure Turbine Blade No.38 New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA002WN0		High Pressure Turbine Blade No.38 New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002R7E		High Pressure Turbine Blade No.39 New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA002WN3		High Pressure Turbine Blade No.39 New						RE (O/C)			
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002LAE		High Pressure Turbine Blade No.4 New						RE (O/C)			
							Mos	30-Dec-2021			
							Hrs	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG2	High Pressure Turbine Blade No.4						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA001WX2						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.40						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002R7M						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.40						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002WPN						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.41						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002RAT						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.41						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002WR0						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.42						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002RB1						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.42						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002WR4						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.43						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002RCR						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.43						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002WR5						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.44						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002RD6						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.44						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002WR7						Hrs	0			
							Enc	0			

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
	72 ENG1 30J1581-01 HA002RE7	High Pressure Turbine Blade No.45 New						RE (O/C)				
							Mos	30-Dec-2021				
							Hrs	0				
							Enc	0				
	72 ENG2 30J1581-01 HA002X0P	High Pressure Turbine Blade No.45 New						RE (O/C)				
							Mos	31-Dec-2021				
							Hrs	0				
							Enc	0				
	72 ENG1 30J1581-01 HA002REC	High Pressure Turbine Blade No.46 New						RE (O/C)				
							Mos	30-Dec-2021				
							Hrs	0				
							Enc	0				
	72 ENG2 30J1581-01 HA002X4K	High Pressure Turbine Blade No.46 New						RE (O/C)				
							Mos	31-Dec-2021				
							Hrs	0				
							Enc	0				
	72 ENG1 30J1581-01 HA002REK	High Pressure Turbine Blade No.47 New						RE (O/C)				
							Mos	30-Dec-2021				
							Hrs	0				
							Enc	0				
	72 ENG2 30J1581-01 HA002X4M	High Pressure Turbine Blade No.47 New						RE (O/C)				
							Mos	31-Dec-2021				
							Hrs	0				
							Enc	0				
	72 ENG1 30J1581-01 HA002T3B	High Pressure Turbine Blade No.48 New						RE (O/C)				
							Mos	30-Dec-2021				
							Hrs	0				
							Enc	0				
	72 ENG2 30J1581-01 HA002X50	High Pressure Turbine Blade No.48 New						RE (O/C)				
							Mos	31-Dec-2021				
							Hrs	0				
							Enc	0				
	72 ENG1 30J1581-01 HA002T3E	High Pressure Turbine Blade No.49 New						RE (O/C)				
							Mos	30-Dec-2021				
							Hrs	0				
							Enc	0				
	72 ENG2 30J1581-01 HA002X5E	High Pressure Turbine Blade No.49 New						RE (O/C)				
							Mos	31-Dec-2021				
							Hrs	0				
							Enc	0				
	72 ENG1 30J1581-01 HA002LE5	High Pressure Turbine Blade No.5 New						RE (O/C)				
							Mos	30-Dec-2021				
							Hrs	0				
							Enc	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG2	High Pressure Turbine Blade No.5						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA0023Y5						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.50						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002T3N						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.50						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002X5L						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.51						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002T6W						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.51						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002X7D						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.52						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002T73						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.52						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002X80						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.53						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002T8H						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.53						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002X87						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.54						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002T93						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.54						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002X8E						Hrs	0			
							Enc	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG1	High Pressure Turbine Blade No.55						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002T99						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.55						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002X8P						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.56						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002TAL						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.56						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002X8X						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.57						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002TAM						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.57						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002X91						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.58						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002TAP						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.58						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002XT1						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.59						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002TB0						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.59						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002XT5						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.6						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002LLE						Hrs	0			
							Enc	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
72 ENG2 30J1581-01 HA0023YE		High Pressure Turbine Blade No.6 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002TB2		High Pressure Turbine Blade No.60 New								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA002XYH		High Pressure Turbine Blade No.60 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002TD1		High Pressure Turbine Blade No.61 New								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA002Y8L		High Pressure Turbine Blade No.61 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002TDC		High Pressure Turbine Blade No.62 New								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA002Y8N		High Pressure Turbine Blade No.62 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002TDH		High Pressure Turbine Blade No.63 New								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA002Y8P		High Pressure Turbine Blade No.63 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002TE0		High Pressure Turbine Blade No.64 New								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA002Y91		High Pressure Turbine Blade No.64 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG1	High Pressure Turbine Blade No.65						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002TFF						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.65						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002Y9A						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.66						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002TFN						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.66						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002Y9F						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.67						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002THB						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.67						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002YAB						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.68						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002TTX						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.68						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002YRA						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.69						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002WKT						Hrs	0			
							Enc	0			
	72 ENG2	High Pressure Turbine Blade No.69						RE (O/C)			
	30J1581-01	New					Mos	31-Dec-2021			
	HA002YRK						Hrs	0			
							Enc	0			
	72 ENG1	High Pressure Turbine Blade No.7						RE (O/C)			
	30J1581-01	New					Mos	30-Dec-2021			
	HA002MON						Hrs	0			
							Enc	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
72 ENG2 30J1581-01 HA00244C		High Pressure Turbine Blade No.7 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA00307P		High Pressure Turbine Blade No.70 New								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA002YYE		High Pressure Turbine Blade No.70 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002MOW		High Pressure Turbine Blade No.8 New								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA00244L		High Pressure Turbine Blade No.8 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J1581-01 HA002M3N		High Pressure Turbine Blade No.9 New								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J1581-01 HA00244N		High Pressure Turbine Blade No.9 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J3652-01 PKAAA928406		High Pressure Turbine Rotor Seal New								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J3652-01 PKAAA920623		High Pressure Turbine Rotor Seal New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
72 ENG1 30J4164 ECB10033		HP Turbine Air Seal New								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
72 ENG2 30J4164 ECB10107		HP Turbine Air Seal New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
	72 ENG1 30J2431CL02 PDANL37Y01	HPT Vane Ring New						RE (O/C)				
							Mos	30-Dec-2021				
							Hrs	0				
							Enc	0				
	72 ENG2 30J2431CL02 PDANLX1L01	HPT Vane Ring New						RE (O/C)				
							Mos	31-Dec-2021				
							Hrs	0				
							Enc	0				
	72 ENG1 30J3782-01 A0051DH7	Inner Combustion Chamber Liner New						RE (O/C)				
							Mos	30-Dec-2021				
							Hrs	0				
							Enc	0				
	72 ENG2 30J3782-01 A0051DH6	Inner Combustion Chamber Liner New						RE (O/C)				
							Mos	31-Dec-2021				
							Hrs	0				
							Enc	0				
	72 ENG1 30J3740-01 A0051YRK	Intermediate Case Assembly New						RE (O/C)				
							Mos	30-Dec-2021				
							Hrs	0				
							Enc	0				
	72 ENG2 30J3746-01 A0051NBA	Intermediate Case Assembly New						RE (O/C)				
							Mos	31-Dec-2021				
							Hrs	0				
							Enc	0				
	72 ENG1 30J2939-01 PKAAA929401	Lower Spiral Bevel Gearbox Drive Gearshaft New						RE (O/C)				
							Mos	30-Dec-2021				
							Hrs	0				
							Enc	0				
	72 ENG2 30J2939-01 PKAAA929398	Lower Spiral Bevel Gearbox Drive Gearshaft New						RE (O/C)				
							Mos	31-Dec-2021				
							Hrs	0				
							Enc	0				
	72 ENG1 30J2210-01 A0050WME	LP Compressor Boost Rotor New						RE		EMM - Life Limit		≈21-Dec-2050
							Mos	30-Dec-2021				
							Hrs	0				
			0	Enc		0	13,500	13,500	12,543 Enc			
	72 ENG2 30J2210-01 A0051AAE	LP Compressor Boost Rotor New						RE		EMM - Life Limit		≈02-Jun-2051
							Mos	31-Dec-2021				
							Hrs	0				
			0	Enc		0	13,500	13,500	12,758 Enc			
	72 ENG1 30J2921-01 A0051N28	LP Compressor Fan Rotor New						RE		EMM - Life Limit		≈31-Aug-2043
							Mos	30-Dec-2021				
							Hrs	0				
			0	Enc		0	10,000	10,000	9,043 Enc			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		LP Compressor Fan Rotor								RE	EMM - Life Limit
	72 ENG2	New					Mos	31-Dec-2021			
	30J2921-01						Hrs	0			
	A00514E0						Enc	0	10,000	10,000	9,258 Enc
		LPT Rotor Balancing Assembly								RE (O/C)	
	72 ENG1	New					Mos	30-Dec-2021			
	31H3160-01						Hrs	0			
	BU5452153						Enc	0			
		LPT Rotor Balancing Assembly								RE (O/C)	
	72 ENG2	New					Mos	31-Dec-2021			
	31H3160-01						Hrs	0			
	BU5452156						Enc	0			
		No. 1 Annular Ball Bearing								RE (O/C)	
	72 ENG1	New					Mos	30-Dec-2021			
	31J2816-01						Hrs	0			
	FCN550683						Enc	0			
		No. 1 Annular Ball Bearing								RE (O/C)	
	72 ENG2	New					Mos	31-Dec-2021			
	31J2816-01						Hrs	0			
	FCN550657						Enc	0			
		No.3 Annular Ball Bearing								RE (O/C)	
	72 ENG1	New					Mos	30-Dec-2021			
	31J1272-01						Hrs	0			
	FCN552993						Enc	0			
		No.3 Annular Ball Bearing								RE (O/C)	
	72 ENG2	New					Mos	31-Dec-2021			
	31J1272-01						Hrs	0			
	FCN552985						Enc	0			
		No.5 Cylindrical Roller Bearing								RE (O/C)	
	72 ENG1	New					Mos	30-Dec-2021			
	31J1292-01						Hrs	0			
	FCN551867						Enc	0			
		No.5 Cylindrical Roller Bearing								RE (O/C)	
	72 ENG2	New					Mos	31-Dec-2021			
	30J1292-01						Hrs	0			
	FCN551868						Enc	0			
		Oil Pump Assembly								RE (O/C)	
	72 ENG1	New					Mos	30-Dec-2021			
	30J3365-03						Hrs	0			
	EC01A007A151						Enc	0			
		Oil Pump Assembly								RE (O/C)	
	72 ENG2	New					Mos	31-Dec-2021			
	30J3365-03						Hrs	0			
	EC01A007A149						Enc	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
		Outer Combustion Chamber Liner								RE (O/C)	
	72 ENG1	New					Mos	30-Dec-2021			
	30J3746-01						Hrs	0			
	A0051WCD						Enc	0			
		Outer Combustion Chamber Liner								RE (O/C)	
	72 ENG2	New					Mos	31-Dec-2021			
	30J3746-01						Hrs	0			
	A0051FYY						Enc	0			
		Rear Bearing Seal Runner								RE (O/C)	
	72 ENG1	No.4					Mos	30-Dec-2021			
	30J3653-01	New					Hrs	0			
	MDA21017269						Enc	0			
		Rear Bearing Seal Runner								RE (O/C)	
	72 ENG2	No.4					Mos	31-Dec-2021			
	30J3653-01	New					Hrs	0			
	MDA21017285						Enc	0			
		Rear Bypass Duct Assy								RE (O/C)	
	72 ENG1	New					Mos	30-Dec-2021			
	30J3358-01						Hrs	0			
	KYAA032A145						Enc	0			
		Rear Bypass Duct Assy								RE (O/C)	
	72 ENG2	New					Mos	31-Dec-2021			
	30J3358-01						Hrs	0			
	KYAA032A144						Enc	0			
		Stage 2 Turbine Multiple								RE (O/C)	
	72 ENG1	New					Mos	30-Dec-2021			
	31H3132-06						Hrs	0			
	MAR32972						Enc	0			
		Stage 2 Turbine Multiple								RE (O/C)	
	72 ENG2	New					Mos	31-Dec-2021			
	31H3132-04						Hrs	0			
	MAR24758						Enc	0			
		Stage 3 Turbine Multiple								RE (O/C)	
	72 ENG1	New					Mos	30-Dec-2021			
	31H3133-01						Hrs	0			
	MAR27194						Enc	0			
		Stage 3 Turbine Multiple								RE (O/C)	
	72 ENG2	New					Mos	31-Dec-2021			
	31H3133-01						Hrs	0			
	MAR30063						Enc	0			
		Stage 4 Turbine Multiple								RE (O/C)	
	72 ENG1	New					Mos	30-Dec-2021			
	31H3134-01						Hrs	0			
	MAR31548						Enc	0			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	72 ENG2	New						RE (O/C)			
	31H3134-01							Mos	31-Dec-2021		
	MAR31571							Hrs	0		
								Enc	0		
	72 ENG1	New						RE (O/C)			
	31H3148-01							Mos	30-Dec-2021		
	MAP36353							Hrs	0		
								Enc	0		
	72 ENG2	New						RE (O/C)			
	31H3148-01							Mos	31-Dec-2021		
	MAR26205							Hrs	0		
								Enc	0		
	72 ENG1	New						RE (O/C)			
	31H3038-06							Mos	30-Dec-2021		
	MAR28427							Hrs	0		
								Enc	0		
	72 ENG2	New						RE (O/C)			
	31H3038-06							Mos	31-Dec-2021		
	MAR28428							Hrs	0		
								Enc	0		
	72 ENG1	New						RE (O/C)			
	30J2938-01							Mos	30-Dec-2021		
	PKAAA941758							Hrs	0		
								Enc	0		
	72 ENG2	New						RE (O/C)			
	30J2938-01							Mos	31-Dec-2021		
	PKAAA929370							Hrs	0		
								Enc	0		
	72 ENG1	Unknown						RE (O/C)			
	Unknown							Mos	30-Dec-2021		
	Unknown							Hrs	0		
								Enc	0		
	72 ENG2	Unknown						RE (O/C)			
	Unknown							Mos	31-Dec-2021		
	Unknown							Hrs	0		
								Enc	0		
05-50-00-01		FOD						RE (A/R)		EMM - Unscheduled	
	72 ENG1							Mos			
								Hrs			
								Enc			
05-50-00-01		FOD						RE (A/R)		EMM - Unscheduled	
	72 ENG2							Mos			
								Hrs			
								Enc			

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
05-50-00-02	72 ENG1	Bird Strike						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
05-50-00-02	72 ENG2	Bird Strike						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
05-50-00-03	72 ENG1	Engine Windmilling In Flight						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
05-50-00-03	72 ENG2	Engine Windmilling In Flight						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
05-50-00-04	72 ENG1	Lightning Strike						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
05-50-00-04	72 ENG2	Lightning Strike						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
05-50-00-05	72 ENG1	Fuel Filter Impending/Actual Bypass						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
05-50-00-05	72 ENG2	Fuel Filter Impending/Actual Bypass						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
05-50-00-06	72 ENG1	Engine Exposed To Fire Extinguishing Agent						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
05-50-00-06	72 ENG2	Engine Exposed To Fire Extinguishing Agent						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
05-50-00-07	72 ENG1	Incorrect Engine Shutdown On The Ground						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
05-50-00-07	72 ENG2	Incorrect Engine Shutdown On The Ground						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					
05-50-00-08	72 ENG1	Heavy Landing						RE (A/R)		EMM - Unscheduled	
						Mos					
						Hrs					

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
05-50-00-08	Heavy Landing						RE (A/R)		EMM - Unscheduled	
 72 ENG2					Mos					
					Hrs					
	Brand A:726013				Enc					
05-50-00-09	Sustained Running At An Oil Temperature Outside Of Limits						RE (A/R)		EMM - Unscheduled	
 72 ENG1					Mos					
					Hrs					
	Brand A:726015				Enc					
05-50-00-09	Sustained Running At An Oil Temperature Outside Of Limits						RE (A/R)		EMM - Unscheduled	
 72 ENG2					Mos					
					Hrs					
	Brand A:726015				Enc					
05-50-00-10	Higher-Than-Normal ITT Transient Excursion On Engine Start Due To A Frozen Fan						RE (A/R)		EMM - Unscheduled	
 72 ENG1					Mos					
					Hrs					
	Brand A:726017				Enc					
05-50-00-10	Higher-Than-Normal ITT Transient Excursion On Engine Start Due To A Frozen Fan						RE (A/R)		EMM - Unscheduled	
 72 ENG2					Mos					
					Hrs					
	Brand A:726017				Enc					
05-50-00-11	Leakage Of P3 Air In The Nacelle (From Engine P3 Air Tubes, Cabin Air Bleed Ports Or Airframe Tubes)						RE (A/R)		EMM - Unscheduled	
 72 ENG1					Mos					
					Hrs					
					Enc					
05-50-00-11	Leakage Of P3 Air In The Nacelle (From Engine P3 Air Tubes, Cabin Air Bleed Ports Or Airframe Tubes)						RE (A/R)		EMM - Unscheduled	
 72 ENG2					Mos					
					Hrs					
					Enc					
05-50-00-12	Aircraft Flown Through A Cloud Of Volcanic Ash						RE (A/R)		EMM - Unscheduled	
 72 ENG1					Mos					
					Hrs					
	Brand A:726023 (SOURCE: PW545C MM 05-50-00)				Enc					
05-50-00-12	Aircraft Flown Through A Cloud Of Volcanic Ash						RE (A/R)		EMM - Unscheduled	
 72 ENG2					Mos					
					Hrs					
	Brand A:726023 (SOURCE: PW545C MM 05-50-00)				Enc					
05-50-00-13	Starter Generator Fail Indication						RE (A/R)		EMM - Unscheduled	
 72 ENG1					Mos					
					Hrs					
	(SOURCE: PW545C MM 05-50-00)				Enc					
05-50-00-13	Starter Generator Fail Indication						RE (A/R)		EMM - Unscheduled	
 72 ENG2					Mos					
					Hrs					
	(SOURCE: PW545C MM 05-50-00)				Enc					
05-50-00-14	Hydraulic Pump Unscheduled Removal						RE (A/R)		EMM - Unscheduled	
 72 ENG1					Mos					
					Hrs					
	(SOURCE: PW545C MM 05-50-00)				Enc					
05-50-00-14	Hydraulic Pump Unscheduled Removal						RE (A/R)		EMM - Unscheduled	
 72 ENG2					Mos					
					Hrs					
	(SOURCE: PW545C MM 05-50-00)				Enc					

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
05-50-00-15		Fuel Contamination (Fuel contamination with Diesel Exhaust Fluid (DEF) additive, improper concentration of biocide or hydraulic fluid or as recommended by P&WC.)						RE (A/R)		EMM - Unscheduled	
	72 ENG1										
(SOURCE: PW545C MM 05-50-00)											
05-50-00-15		Fuel Contamination (Fuel contamination with Diesel Exhaust Fluid (DEF) additive, improper concentration of biocide or hydraulic fluid or as recommended by P&WC.)						RE (A/R)		EMM - Unscheduled	
	72 ENG2										
(SOURCE: PW545C MM 05-50-00)											
30325		Oil-Pump Plain Seal - Replacement						RE (-)		Category 6	
	72 ENG1										
	Complied With						30-Dec-2021				
30325		Oil-Pump Plain Seal - Replacement						RE (-)		Category 6	
	72 ENG2										
	Complied With						31-Dec-2021				
30325 Rev 1		Oil-Pump Plain Seal - Replacement						RE (-)		Category 6	
	72 ENG1										
	Eff: 12-Jun-2009 Complied With						30-Dec-2021				
30325 Rev 1		Oil-Pump Plain Seal - Replacement						RE (-)		Category 6	
	72 ENG2										
	Eff: 12-Jun-2009 Complied With						31-Dec-2021				
30325 Rev 3		Oil-Pump Plain Seal - Replacement						RE (-)		Category 6	
	72 ENG1										
	Eff: 30-Aug-2017 Complied With (AVG MAN HRS: 2)						30-Dec-2021				
30325 Rev 3		Oil-Pump Plain Seal - Replacement						RE (-)		Category 6	
	72 ENG2										
	Eff: 30-Aug-2017 Complied With (AVG MAN HRS: 2)						31-Dec-2021				
30333		Fan Rotor Balancing Assembly - Replacement / Modification						RE (-)		Category 7	
	72 ENG1										
	Eff: 26-Jan-2010 Complied With						30-Dec-2021				
30333		Fan Rotor Balancing Assembly - Replacement / Modification						RE (-)		Category 7	
	72 ENG2										
	Eff: 26-Jan-2010 Complied With						31-Dec-2021				
30354		Accessory-Gearbox Plain-Seal - Replacement						RE (-)		Category 7	
	72 ENG1										
	Complied With						30-Dec-2021				
30354		Accessory-Gearbox Plain-Seal - Replacement						RE (-)		Category 7	
	72 ENG2										
	Complied With						31-Dec-2021				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30354 Rev 1	Accessory-Gearbox Plain-Seal - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 28-Apr-2008 Complied With						Hrs				
						Enc				
30354 Rev 1	Accessory-Gearbox Plain-Seal - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 28-Apr-2008 Complied With						Hrs				
						Enc				
30361	Outer Front Bypass Duct With New Studs - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 05-May-2008 Complied With						Hrs				
						Enc				
30361	Outer Front Bypass Duct With New Studs - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 05-May-2008 Complied With						Hrs				
						Enc				
30362	HP Turbine Disk Balancing Assembly with Thicker Feather Seals - Replacement						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 05-Jun-2008 Complied With						Hrs				
						Enc				
30362	HP Turbine Disk Balancing Assembly with Thicker Feather Seals - Replacement						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 05-Jun-2008 Complied With						Hrs				
						Enc				
30365	Inlet Pressure Oil Tube Assy - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 09-May-2008 Complied With						Hrs				
						Enc				
30365	Inlet Pressure Oil Tube Assy - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 09-May-2008 Complied With						Hrs				
						Enc				
30366	Air/Oil Separator - Replacement						RE (-)		Category 7	
 72 ENG1						Mos				
Eff: 01-May-2008 Complied With						Hrs				
						Enc				
30366	Air/Oil Separator - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 01-May-2008 Complied With						Hrs				
						Enc				
30369	Oil Pump Assembly With A New Rear Oil Pump Housing - Replacement/Modification						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30369	Oil Pump Assembly With A New Rear Oil Pump Housing - Replacement/Modification						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30369 Rev 1	Oil Pump Assembly With A New Rear Oil Pump Housing - Replacement/Modification						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 02-Sep-2011 Complied With						Hrs				
						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30369 Rev 1		Oil Pump Assembly With A New Rear Oil Pump Housing - Replacement/Modification								RE (-)	Category 6
	72 ENG2						Mos	31-Dec-2021			
	Eff: 02-Sep-2011	Complied With					Hrs				
							Enc				
30370		Fuel Metering Unit - Replacement								RE (-)	Category 7
	72 ENG1						Mos	30-Dec-2021			
	Complied With						Hrs				
							Enc				
30370		Fuel Metering Unit - Replacement								RE (-)	Category 7
	72 ENG2						Mos	31-Dec-2021			
	Complied With						Hrs				
							Enc				
30370 Rev 1		Fuel Metering Unit - Replacement								RE (-)	Category 7
	72 ENG1						Mos	30-Dec-2021			
	Eff: 16-Feb-2009	Complied With					Hrs				
							Enc				
30370 Rev 1		Fuel Metering Unit - Replacement								RE (-)	Category 7
	72 ENG2						Mos	31-Dec-2021			
	Eff: 16-Feb-2009	Complied With					Hrs				
							Enc				
30371		Accessory Gearbox FCU - Starter Gearshaft Oil Baffle - Introduction								RE (-)	Category 10
	72 ENG1						Mos	30-Dec-2021			
	Complied With						Hrs				
							Enc				
30371		Accessory Gearbox FCU - Starter Gearshaft Oil Baffle - Introduction								RE (-)	Category 10
	72 ENG2						Mos	31-Dec-2021			
	Complied With						Hrs				
							Enc				
30371 Rev 1		Accessory Gearbox FCU - Starter Gearshaft Oil Baffle - Introduction								RE (-)	Category 10
	72 ENG1						Mos	30-Dec-2021			
	Complied With						Hrs				
							Enc				
30371 Rev 1		Accessory Gearbox FCU - Starter Gearshaft Oil Baffle - Introduction								RE (-)	Category 10
	72 ENG2						Mos	31-Dec-2021			
	Complied With						Hrs				
							Enc				
30371 Rev 2		Accessory Gearbox FCU - Starter Gearshaft Oil Baffle - Introduction								RE (-)	Category 10
	72 ENG1						Mos	30-Dec-2021			
	Eff: 11-Mar-2014	Complied With					Hrs				
							Enc				
30371 Rev 2		Accessory Gearbox FCU - Starter Gearshaft Oil Baffle - Introduction								RE (-)	Category 10
	72 ENG2						Mos	31-Dec-2021			
	Eff: 11-Mar-2014	Complied With					Hrs				
							Enc				
30373		Secondary Fuel Pressure Tube and Support Bracket - Replacement								RE (-)	Category 3
	72 ENG1						Mos	30-Dec-2021			
	Eff: 15-Aug-2008	Complied With					Hrs				
							Enc				
30373		Secondary Fuel Pressure Tube and Support Bracket - Replacement								RE (-)	Category 3
	72 ENG2						Mos	31-Dec-2021			
	Eff: 15-Aug-2008	Complied With					Hrs				
							Enc				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30376	Oil Pump Assembly and Oil-Pump-Drive Spur Gear - Replacement/Modification						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
30376	Oil Pump Assembly and Oil-Pump-Drive Spur Gear - Replacement/Modification						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
30376 Rev 1	Oil Pump Assembly and Oil-Pump-Drive Spur Gear - Replacement/Modification						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 19-Dec-2011 Complied With					Hrs					
					Enc					
30376 Rev 1	Oil Pump Assembly and Oil-Pump-Drive Spur Gear - Replacement/Modification						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 19-Dec-2011 Complied With					Hrs					
					Enc					
30376 Rev 2	Oil Pump Assembly and Oil-Pump-Drive Spur Gear - Replacement/Modification						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 16-Jun-2016 Complied With					Hrs					
					Enc					
30376 Rev 2	Oil Pump Assembly and Oil-Pump-Drive Spur Gear - Replacement/Modification						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 16-Jun-2016 Complied With					Hrs					
					Enc					
30379	By-Pass Ducts - Replacement/Modification						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
30379	By-Pass Ducts - Replacement/Modification						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
30379 Rev 1	By-Pass Ducts - Replacement/Modification						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 11-Sep-2015 Complied With					Hrs					
					Enc					
30379 Rev 1	By-Pass Ducts - Replacement/Modification						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 11-Sep-2015 Complied With					Hrs					
					Enc					
30380	Gearbox-Drive-Shaft-Accessory Gearbox Drive Gearshaft-Assembly Gearbox Drive Spline Bevel- Gearshaft / Replacement						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 09-Dec-2008 Complied With					Hrs					
					Enc					
30380	Gearbox-Drive-Shaft-Accessory Gearbox Drive Gearshaft-Assembly Gearbox Drive Spline Bevel- Gearshaft / Replacement						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 09-Dec-2008 Complied With					Hrs					
					Enc					
30384	Air/Oil Separator - Replacement						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30384		Air/Oil Separator - Replacement						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
30384 Rev 1		Air/Oil Separator - Replacement						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 02-Sep-2011	Complied With				Hrs					
						Enc					
30384 Rev 1		Air/Oil Separator - Replacement						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 02-Sep-2011	Complied With				Hrs					
						Enc					
30385		Data Collection Unit - Replacement						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 27-Jan-2009	Complied With				Hrs					
						Enc					
30385		Data Collection Unit - Replacement						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 27-Jan-2009	Complied With				Hrs					
						Enc					
30389		Carbon Seal No. 4 Bearing - Replacement						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 05-Mar-2009	Complied With				Hrs					
						Enc					
30389		Carbon Seal No. 4 Bearing - Replacement						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 05-Mar-2009	Complied With				Hrs					
						Enc					
30391		Inlet Pressure Oil Tube Assy - Replacement						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 11-Jun-2009	Complied With				Hrs					
						Enc					
30391		Inlet Pressure Oil Tube Assy - Replacement						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 11-Jun-2009	Complied With				Hrs					
						Enc					
30392		Bolts - Replacement						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 25-Jun-2009	Complied With				Hrs					
						Enc					
30392		Bolts - Replacement						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 25-Jun-2009	Complied With				Hrs					
						Enc					
30393		EEC Support Brackets - Replacement						RE (-)		Category 3	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
30393		EEC Support Brackets - Replacement						RE (-)		Category 3	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					

Task No	Description											Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining		
30393 Rev 1		EEC Support Brackets - Replacement						RE (-)		Category 3			
	72 ENG1	Eff: 02-Jun-2010 Complied With				Mos	30-Dec-2021						
						Hrs							
						Enc							
30393 Rev 1		EEC Support Brackets - Replacement						RE (-)		Category 3			
	72 ENG2	Eff: 02-Jun-2010 Complied With				Mos	31-Dec-2021						
						Hrs							
						Enc							
30400		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7			
	72 ENG1	Complied With				Mos	30-Dec-2021						
						Hrs							
						Enc							
30400		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7			
	72 ENG2	Complied With				Mos	31-Dec-2021						
						Hrs							
						Enc							
30400 Rev 1		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7			
	72 ENG1	Complied With				Mos	30-Dec-2021						
						Hrs							
						Enc							
30400 Rev 1		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7			
	72 ENG2	Complied With				Mos	31-Dec-2021						
						Hrs							
						Enc							
30400 Rev 2		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7			
	72 ENG1	Complied With				Mos	30-Dec-2021						
						Hrs							
						Enc							
30400 Rev 2		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7			
	72 ENG2	Complied With				Mos	31-Dec-2021						
						Hrs							
						Enc							
30400 Rev 3		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7			
	72 ENG1	Eff: 31-Oct-2012 Complied With				Mos	30-Dec-2021						
						Hrs							
						Enc							
30400 Rev 3		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7			
	72 ENG2	Eff: 31-Oct-2012 Complied With				Mos	31-Dec-2021						
						Hrs							
						Enc							
30400 Rev 4		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7			
	72 ENG1	Eff: 23-Nov-2016 Complied With				Mos	30-Dec-2021						
						Hrs							
						Enc							
30400 Rev 4		Intermediate Case Assembly and Intershaft Seal Carrier - Replacement						RE (-)		Category 6, Category 7			
	72 ENG2	Eff: 23-Nov-2016 Complied With				Mos	31-Dec-2021						
						Hrs							
						Enc							
30400 Rev 4 Part A		Intermediate Case Assembly - Replacement						RE (-)		Category 6			
	72 ENG1	Eff: 23-Nov-2016 Complied With				Mos	30-Dec-2021						
						Hrs							
						Enc							

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30400 Rev 4 Part A		Intermediate Case Assembly - Replacement						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 23-Nov-2016 Complied With					Hrs					
						Enc					
30400 Rev 4 Part B		Intershaft Seal Carrier - Replacement						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 23-Nov-2016 Complied With					Hrs					
						Enc					
30400 Rev 4 Part B		Intershaft Seal Carrier - Replacement						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 23-Nov-2016 Complied With					Hrs					
						Enc					
30401		Electronic Engine Control Re-Programming / Replacement-Modification						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
30401		Electronic Engine Control Re-Programming / Replacement-Modification						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
30401 Rev 1		Electronic Engine Control Re-Programming / Replacement-Modification						RE (-)		Category 10	
	72 ENG1					Mos					
						Hrs					
						Enc					
30401 Rev 1		Electronic Engine Control Re-Programming / Replacement-Modification						RE (-)		Category 10	
	72 ENG2					Mos					
						Hrs					
						Enc					
30401 Rev 2		Electronic Engine Control Re-Programming / Replacement-Modification						T (A/R)		Category 10	
	72 ENG1					Mos					
	Eff: 20-Aug-2015					Hrs					
						Enc					
30401 Rev 2		Electronic Engine Control Re-Programming / Replacement-Modification						T (A/R)		Category 10	
	72 ENG2					Mos					
	Eff: 20-Aug-2015					Hrs					
						Enc					
30403		Replacement of Tee Head Bolt/1st - 2nd. Stage HP Compressor Assemblies						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
30403		Replacement of Tee Head Bolt/1st - 2nd. Stage HP Compressor Assemblies						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
30403 Rev 1		Replacement of Tee Head Bolt/1st - 2nd. Stage HP Compressor Assemblies						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 02-Oct-2009 Complied With					Hrs					
						Enc					
30403 Rev 1		Replacement of Tee Head Bolt/1st - 2nd. Stage HP Compressor Assemblies						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 02-Oct-2009 Complied With					Hrs					
						Enc					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30403 Rev 2	Replacement of Tee Head Bolt/1st - 2nd Stage HP Compressor Assemblies						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 20-Apr-2017 Complied With						Hrs				
						Enc				
30403 Rev 2	Replacement of Tee Head Bolt/1st - 2nd Stage HP Compressor Assemblies						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 20-Apr-2017 Complied With						Hrs				
						Enc				
30403 Rev 3	Replacement of Tee Head Bolt/1st - 2nd Stage HP Compressor Assemblies						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 05-Mar-2018 Complied With						Hrs				
						Enc				
30403 Rev 3	Replacement of Tee Head Bolt/1st - 2nd Stage HP Compressor Assemblies						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 05-Mar-2018 Complied With						Hrs				
						Enc				
30403 Rev 4	Replacement of Tee Head Bolt/1st - 2nd Stage HP Compressor Assemblies						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 12-Feb-2019 Complied With						Hrs				
						Enc				
30403 Rev 4	Replacement of Tee Head Bolt/1st - 2nd Stage HP Compressor Assemblies						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 12-Feb-2019 Complied With						Hrs				
						Enc				
30404	Servo Valve For The Intercompressor Bleed-Valve - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30404	Servo Valve For The Intercompressor Bleed-Valve - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30404 Rev 1	Servo Valve For The Intercompressor Bleed-Valve - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30404 Rev 1	Servo Valve For The Intercompressor Bleed-Valve - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30404 Rev 2	Servo Valve For The Intercompressor Bleed-Valve - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30404 Rev 2	Servo Valve For The Intercompressor Bleed-Valve - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30404 Rev 3	Servo Valve For The Intercompressor Bleed-Valve - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 03-May-2010 Complied With						Hrs				
						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30404 Rev 3	Servo Valve For The Intercompressor Bleed-Valve - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 03-May-2010 Complied With						Hrs				
						Enc				
30407	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 12-Nov-2009 Complied With						Hrs				
						Enc				
30407	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 12-Nov-2009 Complied With						Hrs				
						Enc				
30407 Rev 1	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 30-Aug-2017 Complied With						Hrs				
(AVG MAN HRS: 2)						Enc				
30407 Rev 1	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 30-Aug-2017 Complied With						Hrs				
(AVG MAN HRS: 2)						Enc				
30411	Gaskets - Replacement						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30411	Gaskets - Replacement						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30411 Rev 1	Gaskets - Replacement						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 22-Mar-2010 Complied With						Hrs				
						Enc				
30411 Rev 1	Gaskets - Replacement						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 22-Mar-2010 Complied With						Hrs				
						Enc				
30413	Introduction of Deeper Sump						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30413	Introduction of Deeper Sump						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30413 Rev 1	Introduction of Deeper Sump						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30413 Rev 1	Introduction of Deeper Sump						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30413 Rev 10		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 29-Aug-2017	Complied With				Hrs					
						Enc					
30413 Rev 10		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 29-Aug-2017	Complied With				Hrs					
						Enc					
30413 Rev 11		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 30-Nov-2018	Complied With				Hrs					
						Enc					
30413 Rev 11		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 30-Nov-2018	Complied With				Hrs					
						Enc					
30413 Rev 12		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 21-Dec-2021	Complied With				Hrs					
						Enc					
30413 Rev 12		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 21-Dec-2021	Complied With				Hrs					
						Enc					
30413 Rev 2		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
30413 Rev 2		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
30413 Rev 3		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
30413 Rev 3		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
30413 Rev 4		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
30413 Rev 4		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
30413 Rev 5		Introduction of Deeper Sump						RE (-)		Category 6	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30413 Rev 5	Introduction of Deeper Sump						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30413 Rev 6	Introduction of Deeper Sump						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30413 Rev 6	Introduction of Deeper Sump						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30413 Rev 7	Introduction of Deeper Sump						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 08-Oct-2013 Complied With						Hrs				
						Enc				
30413 Rev 7	Introduction of Deeper Sump						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 08-Oct-2013 Complied With						Hrs				
						Enc				
30413 Rev 8	Introduction of Deeper Sump						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 08-Jan-2016 Complied With						Hrs				
						Enc				
30413 Rev 8	Introduction of Deeper Sump						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 08-Jan-2016 Complied With						Hrs				
						Enc				
30413 Rev 9	Introduction of Deeper Sump						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 10-Aug-2016 Complied With						Hrs				
						Enc				
30413 Rev 9	Introduction of Deeper Sump						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 10-Aug-2016 Complied With						Hrs				
						Enc				
30415	No. 4 Roller Bearing - Replacement						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30415	No. 4 Roller Bearing - Replacement						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30415 Rev 1	No. 4 Roller Bearing - Replacement						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 13-May-2013 Complied With						Hrs				
						Enc				
30415 Rev 1	No. 4 Roller Bearing - Replacement						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 13-May-2013 Complied With						Hrs				
						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30415 Rev 2	No. 4 Roller Bearing - Replacement						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 06-Jan-2016 Complied With						Hrs				
						Enc				
30415 Rev 2	No. 4 Roller Bearing - Replacement						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 06-Jan-2016 Complied With						Hrs				
						Enc				
30415 Rev 3	Replacement of No. 4 Roller Bearing						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 13-Oct-2016 Complied With						Hrs				
						Enc				
30415 Rev 3	Replacement of No. 4 Roller Bearing						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 13-Oct-2016 Complied With						Hrs				
						Enc				
30415 Rev 4	Replacement of No. 4 Roller Bearing						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 06-Aug-2020 Complied With						Hrs				
						Enc				
30415 Rev 4	Replacement of No. 4 Roller Bearing						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 06-Aug-2020 Complied With						Hrs				
						Enc				
30416	No.4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30416	No.4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30416 Rev 1	No.4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
 72 ENG1						Mos	30-Dec-2021			
Eff: 23-Oct-2013 Complied With						Hrs				
						Enc				
30416 Rev 1	No.4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
 72 ENG2						Mos	31-Dec-2021			
Eff: 23-Oct-2013 Complied With						Hrs				
						Enc				
30417	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30417	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30417 Rev 1	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30417 Rev 1	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
30417 Rev 2	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
30417 Rev 2	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
30417 Rev 3	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
30417 Rev 3	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
30417 Rev 4	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
30417 Rev 4	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
30417 Rev 5	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
30417 Rev 5	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
30417 Rev 6	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
30417 Rev 6	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
30417 Rev 7	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
30417 Rev 7	Front Seal Runner No. 4 Bearing - Replacement						RE (-)		Category 10	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30417 Rev 8	Front Seal Runner No. 4 Bearing - Replacement								RE (-)	Category 10
 72 ENG1						Mos	30-Dec-2021			
Eff: 23-Nov-2012 Complied With						Hrs				
						Enc				
30417 Rev 8	Front Seal Runner No. 4 Bearing - Replacement								RE (-)	Category 10
 72 ENG2						Mos	31-Dec-2021			
Eff: 23-Nov-2012 Complied With						Hrs				
						Enc				
30418	Electrical Wiring Harness (TT0 Sensor) - Replacement								RE (-)	Category 6
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30418	Electrical Wiring Harness (TT0 Sensor) - Replacement								RE (-)	Category 6
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30418 Rev 1	Electrical Wiring Harness (TT0 Sensor) - Replacement								RE (-)	Category 6
 72 ENG1						Mos	30-Dec-2021			
Eff: 12-Apr-2011 Complied With						Hrs				
						Enc				
30418 Rev 1	Electrical Wiring Harness (TT0 Sensor) - Replacement								RE (-)	Category 6
 72 ENG2						Mos	31-Dec-2021			
Eff: 12-Apr-2011 Complied With						Hrs				
						Enc				
30419	Combustion Chamber Liner - Replacement								RE (-)	Category 7
 72 ENG1						Mos	30-Dec-2021			
Eff: 28-Sep-2010 Complied With						Hrs				
						Enc				
30419	Combustion Chamber Liner - Replacement								RE (-)	Category 7
 72 ENG2						Mos	31-Dec-2021			
Eff: 28-Sep-2010 Complied With						Hrs				
						Enc				
30419 Rev 1	Combustion Chamber Liner - Replacement								RE (-)	Category 7
 72 ENG1						Mos	30-Dec-2021			
Eff: 26-Feb-2016 Complied With						Hrs				
						Enc				
30419 Rev 1	Combustion Chamber Liner - Replacement								RE (-)	Category 7
 72 ENG2						Mos	31-Dec-2021			
Eff: 26-Feb-2016 Complied With						Hrs				
						Enc				
30420	Replacement Intercompressor Bleed Valve/Servo-Valve								RE (-)	Category 3, Category 6
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30420	Replacement Intercompressor Bleed Valve/Servo-Valve								RE (-)	Category 3, Category 6
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30420 Rev 1	Replacement Intercompressor Bleed Valve/Servo-Valve								RE (-)	Category 3, Category 6
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30420 Rev 1		Replacement Intercompressor Bleed Valve/Servo-Valve									
	72 ENG2					Mos	31-Dec-2021	RE (-)		Category 3, Category 6	
	Complied With					Hrs					
						Enc					
30420 Rev 2		Replacement Intercompressor Bleed Valve/Servo-Valve									
	72 ENG1					Mos	30-Dec-2021	RE (-)		Category 3, Category 6	
	Complied With					Hrs					
						Enc					
30420 Rev 2		Replacement Intercompressor Bleed Valve/Servo-Valve									
	72 ENG2					Mos	31-Dec-2021	RE (-)		Category 3, Category 6	
	Complied With					Hrs					
						Enc					
30420 Rev 3		Replacement Intercompressor Bleed Valve/Servo-Valve									
	72 ENG1					Mos	30-Dec-2021	RE (-)		Category 3, Category 6	
	Complied With					Hrs					
						Enc					
30420 Rev 3		Replacement Intercompressor Bleed Valve/Servo-Valve									
	72 ENG2					Mos	31-Dec-2021	RE (-)		Category 3, Category 6	
	Complied With					Hrs					
						Enc					
30420 Rev 4		Replacement Intercompressor Bleed Valve/Servo-Valve									
	72 ENG1					Mos	30-Dec-2021	RE (-)		Category 3, Category 6	
	Eff: 18-Jun-2014 Complied With					Hrs					
						Enc					
30420 Rev 4		Replacement Intercompressor Bleed Valve/Servo-Valve									
	72 ENG2					Mos	31-Dec-2021	RE (-)		Category 3, Category 6	
	Eff: 18-Jun-2014 Complied With					Hrs					
						Enc					
30420 Rev 5		Replacement Intercompressor Bleed Valve/Servo-Valve									
	72 ENG1					Mos	30-Dec-2021	RE (-)		Category 3, Category 6	
	Eff: 20-Apr-2018 Complied With					Hrs					
	(AVG MAN HRS: 4)					Enc					
30420 Rev 5		Replacement Intercompressor Bleed Valve/Servo-Valve									
	72 ENG2					Mos	31-Dec-2021	RE (-)		Category 3, Category 6	
	Eff: 20-Apr-2018 Complied With					Hrs					
	(AVG MAN HRS: 4)					Enc					
30420 Rev 6		Replacement Intercompressor Bleed Valve/Servo-Valve									
	72 ENG1					Mos	30-Dec-2021	RE (-)		Category 3, Category 6	
	Eff: 16-Jul-2020 Complied With					Hrs					
	(AVG MAN HRS: 4)					Enc					
30420 Rev 6		Replacement Intercompressor Bleed Valve/Servo-Valve									
	72 ENG2					Mos	31-Dec-2021	RE (-)		Category 3, Category 6	
	Eff: 16-Jul-2020 Complied With					Hrs					
	(AVG MAN HRS: 4)					Enc					
30423		Intermediate Case Assembly - Replacement/Modification									
	72 ENG1					Mos	30-Dec-2021	RE (-)		Category 6	
	Complied With					Hrs					
						Enc					
30423		Intermediate Case Assembly - Replacement/Modification									
	72 ENG2					Mos	31-Dec-2021	RE (-)		Category 6	
	Complied With					Hrs					
						Enc					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30423 Rev 1	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 17-Sep-2012 Complied With						Hrs				
						Enc				
30423 Rev 1	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 17-Sep-2012 Complied With						Hrs				
						Enc				
30425	No. 4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
 72 ENG1						Mos				
						Hrs				
						Enc				
30425	No. 4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
 72 ENG2						Mos				
						Hrs				
						Enc				
30425 Rev 1	No. 4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
 72 ENG1						Mos				
						Hrs				
						Enc				
30425 Rev 1	No. 4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
 72 ENG2						Mos				
						Hrs				
						Enc				
30425 Rev 2	No. 4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
 72 ENG1						Mos				
						Hrs				
						Enc				
30425 Rev 2	No. 4 Bearing Carbon Seal - Replacement						RE (-)		Category 10	
 72 ENG2						Mos				
						Hrs				
						Enc				
30425 Rev 3	No. 4 Bearing Carbon Seal - Replacement						T (A/R)		Category 10	
 72 ENG1						Mos				
Eff: 23-Oct-2013						Hrs				
						Enc				
30425 Rev 3	No. 4 Bearing Carbon Seal - Replacement						T (A/R)		Category 10	
 72 ENG2						Mos				
Eff: 23-Oct-2013						Hrs				
						Enc				
30426	Fan Case Assembly - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 08-Jul-2011 Complied With						Hrs				
						Enc				
30426	Fan Case Assembly - Replacement						T (A/R)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 08-Jul-2011 Complied With						Hrs				
						Enc				
30427	Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30427		Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
30427 Rev 1		Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
	72 ENG1	Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
30427 Rev 1		Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
30427 Rev 2		Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
	72 ENG1	Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
30427 Rev 2		Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
30427 Rev 3		Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 7	
	72 ENG1	Eff: 13-Mar-2013 Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
30427 Rev 3		Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 7	
	72 ENG2	Eff: 13-Mar-2013 Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
30427 Rev 4		Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
	72 ENG1	Eff: 06-Nov-2018 Complied With (AVG MAN HRS: 3)					Mos	30-Dec-2021			
							Hrs				
							Enc				
30427 Rev 4		Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
	72 ENG2	Eff: 06-Nov-2018 Complied With (AVG MAN HRS: 3)					Mos	31-Dec-2021			
							Hrs				
							Enc				
30428		Replacement Fuel Manifold System Interface						RE (-)		Category 6	
	72 ENG1	Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
30428		Replacement Fuel Manifold System Interface						RE (-)		Category 6	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				
30428 Rev 1		Replacement Fuel Manifold System Interface						RE (-)		Category 6	
	72 ENG1	Complied With					Mos	30-Dec-2021			
							Hrs				
							Enc				
30428 Rev 1		Replacement Fuel Manifold System Interface						RE (-)		Category 6	
	72 ENG2	Complied With					Mos	31-Dec-2021			
							Hrs				
							Enc				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30428 Rev 2	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
30428 Rev 2	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
30428 Rev 3	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
30428 Rev 3	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
30428 Rev 4	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Eff: 03-May-2013 Complied With					Hrs					
					Enc					
30428 Rev 4	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Eff: 03-May-2013 Complied With					Hrs					
					Enc					
30428 Rev 5	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Eff: 19-Apr-2017 Complied With					Hrs					
(AVG MAN HRS: 16)					Enc					
30428 Rev 5	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Eff: 19-Apr-2017 Complied With					Hrs					
(AVG MAN HRS: 16)					Enc					
30428 Rev 6	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Eff: 08-Feb-2019 Complied With					Hrs					
(AVG MAN HRS: 16)					Enc					
30428 Rev 6	Replacement Fuel Manifold System Interface						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Eff: 08-Feb-2019 Complied With					Hrs					
(AVG MAN HRS: 16)					Enc					
30429	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
30429	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
30429 Rev 1	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30429 Rev 1	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30429 Rev 2	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30429 Rev 2	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30429 Rev 3	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 22-Jun-2015 Complied With						Hrs				
						Enc				
30429 Rev 3	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 22-Jun-2015 Complied With						Hrs				
						Enc				
30429 Rev 4	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 14-Mar-2016 Complied With						Hrs				
						Enc				
30429 Rev 4	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 14-Mar-2016 Complied With						Hrs				
						Enc				
30429 Rev 5	Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 10-Aug-2016 Complied With						Hrs				
						Enc				
30429 Rev 5	Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 10-Aug-2016 Complied With						Hrs				
						Enc				
30429 Rev 6	Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 02-Aug-2017 Complied With						Hrs				
						Enc				
30429 Rev 6	Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 02-Aug-2017 Complied With						Hrs				
						Enc				
30432	Plain Seal Accessory Gearbox - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30432	Plain Seal Accessory Gearbox - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30432 Rev 1		Plain Seal Accessory Gearbox - Replacement						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 12-May-2011	Complied With				Hrs					
						Enc					
30432 Rev 1		Plain Seal Accessory Gearbox - Replacement						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 12-May-2011	Complied With				Hrs					
						Enc					
30434		Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
30434		Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
30434 Rev 1		Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
30434 Rev 1		Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
30434 Rev 2		Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
30434 Rev 2		Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
30434 Rev 3		Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
30434 Rev 3		Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
30434 Rev 4		Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
30434 Rev 4		Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
30434 Rev 5		Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 15-Jul-2015	Complied With				Hrs					
						Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30434 Rev 5		Electronic Engine Control / Replacement-Modification						RE (-)		Category 10	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 15-Jul-2015 Complied With					Hrs					
						Enc					
30436		LPT 2nd Stage Vane Assembly - Replacement/Modification						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
30436		LPT 2nd Stage Vane Assembly - Replacement/Modification						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
30436 Rev 1		LPT 2nd Stage Vane Assembly - Replacement/Modification						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
30436 Rev 1		LPT 2nd Stage Vane Assembly - Replacement/Modification						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
30436 Rev 2		LPT 2nd Stage Vane Assembly - Replacement/Modification						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
30436 Rev 2		LPT 2nd Stage Vane Assembly - Replacement/Modification						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					
30436 Rev 3		LPT 2nd Stage Vane Assembly - Replacement/Modification						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 28-Jul-2015 Complied With					Hrs					
						Enc					
30436 Rev 3		LPT 2nd Stage Vane Assembly - Replacement/Modification						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 28-Jul-2015 Complied With					Hrs					
						Enc					
30436 Rev 4		Replacement/Modification of LPT 2nd Stage Vane Assembly						RE (-)		Category 7	
	72 ENG1					Mos	30-Dec-2021				
	Eff: 18-Apr-2018 Complied With					Hrs					
						Enc					
30436 Rev 4		Replacement/Modification of LPT 2nd Stage Vane Assembly						RE (-)		Category 7	
	72 ENG2					Mos	31-Dec-2021				
	Eff: 18-Apr-2018 Complied With					Hrs					
						Enc					
30438		Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
	72 ENG1					Mos	30-Dec-2021				
	Complied With					Hrs					
						Enc					
30438		Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
	72 ENG2					Mos	31-Dec-2021				
	Complied With					Hrs					
						Enc					

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30438 Rev 1	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30438 Rev 1	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30438 Rev 2	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30438 Rev 2	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30438 Rev 3	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30438 Rev 3	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30438 Rev 4	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30438 Rev 4	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30438 Rev 5	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
 72 ENG1						Mos	30-Dec-2021			
Eff: 15-Jul-2015 Complied With						Hrs				
						Enc				
30438 Rev 5	Electronic Engine Control (EEC) - Replacement/Modification						RE (-)		Category 10	
 72 ENG2						Mos	31-Dec-2021			
Eff: 15-Jul-2015 Complied With						Hrs				
						Enc				
30440	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30440	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30440 Rev 1	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30440 Rev 1	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
30440 Rev 2	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
30440 Rev 2	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
30440 Rev 3	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
30440 Rev 3	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
30440 Rev 4	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Eff: 07-Oct-2013 Complied With					Hrs					
					Enc					
30440 Rev 4	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Eff: 07-Oct-2013 Complied With					Hrs					
					Enc					
30440 Rev 5	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Eff: 07-Jan-2016 Complied With					Hrs					
					Enc					
30440 Rev 5	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Eff: 07-Jan-2016 Complied With					Hrs					
					Enc					
30440 Rev 6	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
 72 ENG1					Mos	30-Dec-2021				
Eff: 24-May-2019 Complied With					Hrs					
					Enc					
30440 Rev 6	Replacement of New or Modified Oil Tank Vent Tube Assembly						RE (-)		Category 6	
 72 ENG2					Mos	31-Dec-2021				
Eff: 24-May-2019 Complied With					Hrs					
					Enc					
30445	Electrical Wiring Harness - Replacement						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 16-Sep-2011 Complied With					Hrs					
					Enc					
30445	Electrical Wiring Harness - Replacement						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 16-Sep-2011 Complied With					Hrs					
					Enc					

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30446	Low Pressure Compressor Shaft Balancing Assembly - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30446	Low Pressure Compressor Shaft Balancing Assembly - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30446 Rev 1	Low Pressure Compressor Shaft Balancing Assembly - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30446 Rev 1	Low Pressure Compressor Shaft Balancing Assembly - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30446 Rev 2	Low Pressure Compressor Shaft Balancing Assembly - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 11-Mar-2014 Complied With						Hrs				
						Enc				
30446 Rev 2	Low Pressure Compressor Shaft Balancing Assembly - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 11-Mar-2014 Complied With						Hrs				
						Enc				
30447	Gas Generator Case - New Coating Modification						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30447	Gas Generator Case - New Coating Modification						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30447 Rev 1	Gas Generator Case - New Coating Modification						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Eff: 09-May-2012 Complied With						Hrs				
						Enc				
30447 Rev 1	Gas Generator Case - New Coating Modification						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Eff: 09-May-2012 Complied With						Hrs				
						Enc				
30449	HP Turbine Disk Assembly - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30449	HP Turbine Disk Assembly - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30449 Rev 1	HP Turbine Disk Assembly - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30449 Rev 1	HP Turbine Disk Assembly - Replacement								Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30449 Rev 2	HP Turbine Disk Assembly - Replacement								Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 11-Sep-2015 Complied With						Hrs				
						Enc				
30449 Rev 2	HP Turbine Disk Assembly - Replacement								Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 11-Sep-2015 Complied With						Hrs				
						Enc				
30453	No. 4 Carbon Seal - Replacement								Category 6, Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30453	No. 4 Carbon Seal - Replacement								Category 6, Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30453 Rev 1	No. 4 Carbon Seal - Replacement								Category 6, Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 31-Jan-2014 Complied With						Hrs				
						Enc				
30453 Rev 1	No. 4 Carbon Seal - Replacement								Category 6, Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 31-Jan-2014 Complied With						Hrs				
						Enc				
30453 Rev 2	No. 4 Carbon Seal - Replacement								Category 6, Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 23-Dec-2015 Complied With						Hrs				
						Enc				
30453 Rev 2	No. 4 Carbon Seal - Replacement								Category 6, Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 23-Dec-2015 Complied With						Hrs				
						Enc				
30453 Rev 3	No. 4 Carbon Seal - Replacement								Category 6, Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 11-Aug-2017 Complied With						Hrs				
						Enc				
30453 Rev 3	No. 4 Carbon Seal - Replacement								Category 6, Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 11-Aug-2017 Complied With						Hrs				
						Enc				
30463	Accessory Drive Lip Seal - Replacement								Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30463	Accessory Drive Lip Seal - Replacement								Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description											Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining			
30463 Rev 1	Accessory Drive Lip Seal - Replacement											Category 7	
 72 ENG1					Mos	30-Dec-2021	RE (-)						
Eff: 20-Nov-2012 Complied With					Hrs								
					Enc								
30463 Rev 1	Accessory Drive Lip Seal - Replacement											Category 7	
 72 ENG2					Mos	31-Dec-2021	RE (-)						
Eff: 20-Nov-2012 Complied With					Hrs								
					Enc								
30463 Rev 2	Replacement of Accessory Drive Lip Seal											Category 7	
 72 ENG1					Mos	30-Dec-2021	RE (-)						
Eff: 18-Aug-2016 Complied With					Hrs								
(AVG MAN HRS: 1)					Enc								
30463 Rev 2	Replacement of Accessory Drive Lip Seal											Category 7	
 72 ENG2					Mos	31-Dec-2021	RE (-)						
Eff: 18-Aug-2016 Complied With					Hrs								
(AVG MAN HRS: 1)					Enc								
30465	Fuel Manifold Tubes - Replacement											Category 7	
 72 ENG1					Mos	30-Dec-2021	RE (-)						
Complied With					Hrs								
					Enc								
30465	Fuel Manifold Tubes - Replacement											Category 7	
 72 ENG2					Mos	31-Dec-2021	RE (-)						
Complied With					Hrs								
					Enc								
30465 Rev 1	Fuel Manifold Tubes - Replacement											Category 7	
 72 ENG1					Mos	30-Dec-2021	RE (-)						
Eff: 26-Aug-2014 Complied With					Hrs								
					Enc								
30465 Rev 1	Fuel Manifold Tubes - Replacement											Category 7	
 72 ENG2					Mos	31-Dec-2021	RE (-)						
Eff: 26-Aug-2014 Complied With					Hrs								
					Enc								
30466	Replacement/Modification of 2nd Stage Turbine Vane Assy											Category 7	
 72 ENG1					Mos	30-Dec-2021	RE (-)						
Eff: 19-Sep-2012 Complied With					Hrs								
					Enc								
30466	Replacement/Modification of 2nd Stage Turbine Vane Assy											Category 7	
 72 ENG2					Mos	31-Dec-2021	RE (-)						
Eff: 19-Sep-2012 Complied With					Hrs								
					Enc								
30466 Rev 1	Replacement/Modification of 2nd Stage Turbine Vane Assy											Category 7	
 72 ENG1					Mos	30-Dec-2021	RE (-)						
Eff: 02-Mar-2016 Complied With					Hrs								
					Enc								
30466 Rev 1	Replacement/Modification of 2nd Stage Turbine Vane Assy											Category 7	
 72 ENG2					Mos	31-Dec-2021	RE (-)						
Eff: 02-Mar-2016 Complied With					Hrs								
					Enc								
30466 Rev 2	Replacement/Modification of 2nd Stage Turbine Vane Assy											Category 7	
 72 ENG1					Mos	30-Dec-2021	RE (-)						
Eff: 12-Jul-2018 Complied With					Hrs								
					Enc								

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30466 Rev 2	Replacement/Modification of 2nd Stage Turbine Vane Assy						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 12-Jul-2018 Complied With						Hrs				
						Enc				
30470	Data Collection Unit - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30470	Data Collection Unit - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30470 Rev 1	Data Collection Unit - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 31-Aug-2015 Complied With						Hrs				
						Enc				
30470 Rev 1	Data Collection Unit - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 31-Aug-2015 Complied With						Hrs				
						Enc				
30474	Replacement of Electrical Wiring Harness						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 30-Jul-2013 Complied With						Hrs				
						Enc				
30474	Replacement of Electrical Wiring Harness						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 30-Jul-2013 Complied With						Hrs				
						Enc				
30474 Rev 1	Replacement of Electrical Wiring Harness						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 10-Nov-2015 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30474 Rev 1	Replacement of Electrical Wiring Harness						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 10-Nov-2015 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30475	Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30475	Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30475 Part A	Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Fuel Control Drive Gearshaft (Category 7)						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30475 Part A		Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Fuel Control Drive Gearshaft (Category 7)						RE (-)		Category 7	
	72 ENG2 Complied With					Mos	31-Dec-2021				
						Hrs					
						Enc					
30475 Part B		Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Accessory Drive Gearshaft (Category 7)						RE (-)		Category 7	
	72 ENG1 Complied With					Mos	30-Dec-2021				
						Hrs					
						Enc					
30475 Part B		Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Accessory Drive Gearshaft (Category 7)						RE (-)		Category 7	
	72 ENG2 Complied With					Mos	31-Dec-2021				
						Hrs					
						Enc					
30475 Rev 1		Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly - Replacement						RE (-)		Category 7	
	72 ENG1 Complied With					Mos	30-Dec-2021				
						Hrs					
						Enc					
30475 Rev 1		Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly - Replacement						RE (-)		Category 7	
	72 ENG2 Complied With					Mos	31-Dec-2021				
						Hrs					
						Enc					
30475 Rev 1 Part A		Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Fuel Control Drive Gearshaft (Category 7)						RE (-)		Category 7	
	72 ENG1 Complied With					Mos	30-Dec-2021				
						Hrs					
						Enc					
30475 Rev 1 Part A		Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Fuel Control Drive Gearshaft (Category 7)						RE (-)		Category 7	
	72 ENG2 Complied With					Mos	31-Dec-2021				
						Hrs					
						Enc					
30475 Rev 1 Part B		Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Accessory Drive Gearshaft (Category 7)						RE (-)		Category 7	
	72 ENG1 Complied With					Mos	30-Dec-2021				
						Hrs					
						Enc					
30475 Rev 1 Part B		Remove Replacement Of Accessory Drive Gearshaft Assembly And Fuel Control Drive Spur Gearshaft Assembly /Install The Accessory Drive Gearshaft (Category 7)						RE (-)		Category 7	
	72 ENG2 Complied With					Mos	31-Dec-2021				
						Hrs					
						Enc					
30475 Rev 2		Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly - Replacement						RE (-)		Category 7	
	72 ENG1 Eff: 18-Dec-2013 Complied With					Mos	30-Dec-2021				
						Hrs					
						Enc					
30475 Rev 2		Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly - Replacement						RE (-)		Category 7	
	72 ENG2 Eff: 18-Dec-2013 Complied With					Mos	31-Dec-2021				
						Hrs					
						Enc					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30475 Rev 2 Part A	Replacement of Fuel Control Drive Spur Gearshaft Assembly								RE (-)	Category 7
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30475 Rev 2 Part A	Replacement of Fuel Control Drive Spur Gearshaft Assembly								RE (-)	Category 7
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30475 Rev 2 Part B	Replacement of Accessory Drive Gearshaft Assembly								RE (-)	Category 7
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30475 Rev 2 Part B	Replacement of Accessory Drive Gearshaft Assembly								RE (-)	Category 7
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30475 Rev 3	Replacement of Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly								RE (-)	Category 7
 72 ENG1						Mos	30-Dec-2021			
Eff: 18-Aug-2016 Complied With						Hrs				
						Enc				
30475 Rev 3	Replacement of Accessory Drive Gearshaft Assembly and Fuel Control Drive Spur Gearshaft Assembly								RE (-)	Category 7
 72 ENG2						Mos	31-Dec-2021			
Eff: 18-Aug-2016 Complied With						Hrs				
						Enc				
30475 Rev 3 Part A	Replacement of Fuel Control Drive Spur Gearshaft Assembly								RE (-)	Category 7
 72 ENG1						Mos	30-Dec-2021			
Eff: 18-Aug-2016 Complied With						Hrs				
						Enc				
30475 Rev 3 Part A	Replacement of Fuel Control Drive Spur Gearshaft Assembly								RE (-)	Category 7
 72 ENG2						Mos	31-Dec-2021			
Eff: 18-Aug-2016 Complied With						Hrs				
						Enc				
30475 Rev 3 Part B	Replacement of Accessory Drive Gearshaft Assembly								RE (-)	Category 7
 72 ENG1						Mos	30-Dec-2021			
Eff: 18-Aug-2016 Complied With						Hrs				
						Enc				
30475 Rev 3 Part B	Replacement of Accessory Drive Gearshaft Assembly								RE (-)	Category 7
 72 ENG2						Mos	31-Dec-2021			
Eff: 18-Aug-2016 Complied With						Hrs				
						Enc				
30478	Electronic Engine Control (EEC) - Replacement/Field Modification								RE (-)	Category 3
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30478	Electronic Engine Control (EEC) - Replacement/Field Modification								RE (-)	Category 3
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30478 Rev 1	Electronic Engine Control (EEC) - Replacement/Field Modification								RE (-)	Category 3
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30478 Rev 1	Electronic Engine Control (EEC) - Replacement/Field Modification						RE (-)		Category 3	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30478 Rev 2	Electronic Engine Control (EEC) - Replacement/Field Modification						RE (-)		Category 3	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30478 Rev 2	Electronic Engine Control (EEC) - Replacement/Field Modification						RE (-)		Category 3	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30478 Rev 3	Electronic Engine Control (EEC) - Replacement/Field Modification						RE (-)		Category 3	
 72 ENG1						Mos	30-Dec-2021			
Eff: 15-Jul-2015 Complied With						Hrs				
						Enc				
30478 Rev 3	Electronic Engine Control (EEC) - Replacement/Field Modification						RE (-)		Category 3	
 72 ENG2						Mos	31-Dec-2021			
Eff: 15-Jul-2015 Complied With						Hrs				
						Enc				
30479	No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement						RE (-)		Category 5	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30479	No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement						RE (-)		Category 5	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30479 Rev 1	No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement						RE (-)		Category 5	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30479 Rev 1	No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement						RE (-)		Category 5	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30479 Rev 2	No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement						RE (-)		Category 5	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30479 Rev 2	No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement						RE (-)		Category 5	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30479 Rev 3	No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement						RE (-)		Category 5	
 72 ENG1						Mos	30-Dec-2021			
Eff: 22-Jun-2015 Complied With						Hrs				
						Enc				
30479 Rev 3	No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement						RE (-)		Category 5	
 72 ENG2						Mos	31-Dec-2021			
Eff: 22-Jun-2015 Complied With						Hrs				
						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30479 Rev 4	No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement						RE (-)		Category 5	
 72 ENG1						Mos	30-Dec-2021			
Eff: 04-Jan-2016 Complied With						Hrs				
						Enc				
30479 Rev 4	No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement						RE (-)		Category 5	
 72 ENG2						Mos	31-Dec-2021			
Eff: 04-Jan-2016 Complied With						Hrs				
						Enc				
30479 Rev 5	No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement						RE (-)		Category 5	
 72 ENG1						Mos	30-Dec-2021			
Eff: 21-Jan-2016 Complied With						Hrs				
						Enc				
30479 Rev 5	No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement						RE (-)		Category 5	
 72 ENG2						Mos	31-Dec-2021			
Eff: 21-Jan-2016 Complied With						Hrs				
						Enc				
30479 Rev 6	No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement						RE (-)		Category 3	
 72 ENG1						Mos	30-Dec-2021			
Eff: 20-May-2016 Complied With						Hrs				
						Enc				
30479 Rev 6	No. 4 Bearing Front Cover HPT Rotor Seal Cold Start Valve Assembly and the Oil Transfer Tube - Replacement						RE (-)		Category 3	
 72 ENG2						Mos	31-Dec-2021			
Eff: 20-May-2016 Complied With						Hrs				
						Enc				
30480	Rear Outer By-Pass Duct Silver Plated Nuts - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 05-Dec-2013 Complied With						Hrs				
						Enc				
30480	Rear Outer By-Pass Duct Silver Plated Nuts - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 05-Dec-2013 Complied With						Hrs				
						Enc				
30481	Fuel Shut-Off Cable - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 06-Dec-2013 Complied With						Hrs				
						Enc				
30481	Fuel Shut-Off Cable - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 06-Dec-2013 Complied With						Hrs				
						Enc				
30482	Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection						RE (-)		Category 10	
 72 ENG1						Mos				
						Hrs				
						Enc				
30482	Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection						RE (-)		Category 10	
 72 ENG2						Mos				
						Hrs				
						Enc				
30482 Rev 1	Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection						RE (-)		Category 10	
 72 ENG1						Mos				
						Hrs				
						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30482 Rev 1  72 ENG2	Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection						RE (-)		Category 10	
					Mos					
					Hrs					
					Enc					
30482 Rev 2  72 ENG1	Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection						RE (-)		Category 10	
					Mos					
					Hrs					
					Enc					
30482 Rev 2  72 ENG2	Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection						RE (-)		Category 10	
					Mos					
					Hrs					
					Enc					
30482 Rev 3  72 ENG1 Eff: 22-Oct-2014	Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection						T (A/R)		Category 10	
					Mos					
					Hrs					
					Enc					
30482 Rev 3  72 ENG2 Eff: 22-Oct-2014	Combustion Chamber Liner Cooling Ring Segments Self-Locking Nut - Inspection						T (A/R)		Category 10	
					Mos					
					Hrs					
					Enc					
30483  72 ENG1 Complied With	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 10	
					Mos	30-Dec-2021				
					Hrs					
					Enc					
30483  72 ENG2 Complied With	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 10	
					Mos	31-Dec-2021				
					Hrs					
					Enc					
30483 Rev 1  72 ENG1 Complied With	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 10	
					Mos	30-Dec-2021				
					Hrs					
					Enc					
30483 Rev 1  72 ENG2 Complied With	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 10	
					Mos	31-Dec-2021				
					Hrs					
					Enc					
30483 Rev 2  72 ENG1 Complied With	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 10	
					Mos	30-Dec-2021				
					Hrs					
					Enc					
30483 Rev 2  72 ENG2 Complied With	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 10	
					Mos	31-Dec-2021				
					Hrs					
					Enc					
30483 Rev 3  72 ENG1 Eff: 22-Oct-2014 Complied With	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 10	
					Mos	30-Dec-2021				
					Hrs					
					Enc					
30483 Rev 3  72 ENG2 Eff: 22-Oct-2014 Complied With	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 10	
					Mos	31-Dec-2021				
					Hrs					
					Enc					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30485	Rear Outer By-Pass Duct Hardware - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 19-Nov-2013 Complied With						Hrs				
						Enc				
30485	Rear Outer By-Pass Duct Hardware - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 19-Nov-2013 Complied With						Hrs				
						Enc				
30485 Rev 1	Rear Outer By-Pass Duct Hardware - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 31-May-2016 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				
30485 Rev 1	Rear Outer By-Pass Duct Hardware - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 31-May-2016 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				
30485 Rev 2	Rear Outer By-Pass Duct Hardware - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 14-Aug-2017 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				
30485 Rev 2	Rear Outer By-Pass Duct Hardware - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 14-Aug-2017 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				
30487	Fuel Control Drive and Accessory Drive Lip Seal - Replacement						RE (-)		Category 10	
 72 ENG1						Mos				
						Hrs				
						Enc				
30487	Fuel Control Drive and Accessory Drive Lip Seal - Replacement						RE (-)		Category 10	
 72 ENG2						Mos				
						Hrs				
						Enc				
30487 Rev 1	Fuel Control Drive and Accessory Drive Lip Seal - Replacement						RE (-)		Category 10	
 72 ENG1						Mos				
						Hrs				
						Enc				
30487 Rev 1	Fuel Control Drive and Accessory Drive Lip Seal - Replacement						RE (-)		Category 10	
 72 ENG2						Mos				
						Hrs				
						Enc				
30487 Rev 2	Fuel Control Drive and Accessory Drive Lip Seal - Replacement						RE (-)		Category 10	
 72 ENG1						Mos				
						Hrs				
						Enc				
30487 Rev 2	Fuel Control Drive and Accessory Drive Lip Seal - Replacement						RE (-)		Category 10	
 72 ENG2						Mos				
						Hrs				
						Enc				
30487 Rev 3	Fuel Control Drive and Accessory Drive Lip Seal - Replacement						T (A/R)		Category 10	
 72 ENG1						Mos				
Eff: 09-Oct-2014						Hrs				
						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30487 Rev 3	Fuel Control Drive and Accessory Drive Lip Seal - Replacement						T (A/R)		Category 10	
 72 ENG2						Mos				
Eff: 09-Oct-2014						Hrs				
						Enc				
30491	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30491	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30491 Rev 1	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30491 Rev 1	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30491 Rev 2	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 27-Jul-2015 Complied With						Hrs				
						Enc				
30491 Rev 2	Combustion Chamber Liner Assembly - Replacement/Modification						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 27-Jul-2015 Complied With						Hrs				
						Enc				
30492	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30492	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30492 Rev 1	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30492 Rev 1	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30492 Rev 2	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30492 Rev 2	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30492 Rev 3	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
 72 ENG1	Eff: 27-Nov-2014 Complied With					Mos	30-Dec-2021			
						Hrs				
						Enc				
30492 Rev 3	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
 72 ENG2	Eff: 27-Nov-2014 Complied With					Mos	31-Dec-2021			
						Hrs				
						Enc				
30492 Rev 4	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
 72 ENG1	Eff: 10-Jan-2017 Complied With (AVG MAN HRS: 1.5)					Mos	30-Dec-2021			
						Hrs				
						Enc				
30492 Rev 4	Combustion Chamber Liner - Replacement / Modification						RE (-)		Category 6	
 72 ENG2	Eff: 10-Jan-2017 Complied With (AVG MAN HRS: 1.5)					Mos	31-Dec-2021			
						Hrs				
						Enc				
30495	Accessory Gearbox Cover Bolt Torquing Procedure - Modification						RE (-)		Category 10	
 72 ENG1	Eff: 15-Sep-2014 Complied With					Mos	30-Dec-2021			
						Hrs				
						Enc				
30495	Accessory Gearbox Cover Bolt Torquing Procedure - Modification						RE (-)		Category 10	
 72 ENG2	Eff: 15-Sep-2014 Complied With					Mos	31-Dec-2021			
						Hrs				
						Enc				
30495 Rev 1	Accessory Gearbox Cover Bolt Torquing Procedure - Modification						RE (-)		Category 10	
 72 ENG1	Eff: 13-Oct-2016 Complied With (AVG MAN HRS: 1.5)					Mos	30-Dec-2021			
						Hrs				
						Enc				
30495 Rev 1	Accessory Gearbox Cover Bolt Torquing Procedure - Modification						RE (-)		Category 10	
 72 ENG2	Eff: 13-Oct-2016 Complied With (AVG MAN HRS: 1.5)					Mos	31-Dec-2021			
						Hrs				
						Enc				
30496	Replacement/Modification of Second Stage Turbine Vane						RE (-)		Category 6	
 72 ENG1	Eff: 12-Aug-2014 Complied With					Mos	30-Dec-2021			
						Hrs				
						Enc				
30496	Replacement/Modification of Second Stage Turbine Vane						RE (-)		Category 6	
 72 ENG2	Eff: 12-Aug-2014 Complied With					Mos	31-Dec-2021			
						Hrs				
						Enc				
30496 Rev 1	Replacement/Modification of Second Stage Turbine Vane						RE (-)		Category 6	
 72 ENG1	Eff: 01-Oct-2018 Complied With (AVG MAN HRS: 1.5)					Mos	30-Dec-2021			
						Hrs				
						Enc				
30496 Rev 1	Replacement/Modification of Second Stage Turbine Vane						RE (-)		Category 6	
 72 ENG2	Eff: 01-Oct-2018 Complied With (AVG MAN HRS: 1.5)					Mos	31-Dec-2021			
						Hrs				
						Enc				
30498	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 7	
 72 ENG1	Eff: 12-Sep-2014 Complied With					Mos	30-Dec-2021			
						Hrs				
						Enc				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30498	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 12-Sep-2014 Complied With						Hrs				
						Enc				
30498 Rev 1	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 16-Nov-2016 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30498 Rev 1	Intermediate Case Assembly - Replacement/Modification						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 16-Nov-2016 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30498 Rev 2	Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 10-Aug-2017 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30498 Rev 2	Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 10-Aug-2017 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30498 Rev 3	Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 20-Sep-2017 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30498 Rev 3	Replacement/Modification of Intermediate Case Assembly						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 20-Sep-2017 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30502	Fuel Control Drive and Accessory Drive Plain Seal - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30502	Fuel Control Drive and Accessory Drive Plain Seal - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30502 Rev 1	Fuel Control Drive and Accessory Drive Plain Seal - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30502 Rev 1	Fuel Control Drive and Accessory Drive Plain Seal - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30502 Rev 2	Fuel Control Drive and Accessory Drive Plain Seal - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 02-Oct-2015 Complied With						Hrs				
						Enc				
30502 Rev 2	Fuel Control Drive and Accessory Drive Plain Seal - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 02-Oct-2015 Complied With						Hrs				
						Enc				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30502 Rev 2 Part A	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Fuel Control Gearshaft Seal						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30502 Rev 2 Part A	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Fuel Control Gearshaft Seal						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30502 Rev 2 Part B	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Accessory Gearshaft Seal						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30502 Rev 2 Part B	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Accessory Gearshaft Seal						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30502 Rev 3	Fuel Control Drive and Accessory Drive Plain Seal - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 04-Jan-2016 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				
30502 Rev 3	Fuel Control Drive and Accessory Drive Plain Seal - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 04-Jan-2016 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				
30502 Rev 3 Part A	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Fuel Control Gearshaft Seal						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 04-Jan-2016 Complied With						Hrs				
						Enc				
30502 Rev 3 Part A	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Fuel Control Gearshaft Seal						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 04-Jan-2016 Complied With						Hrs				
						Enc				
30502 Rev 3 Part B	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Accessory Gearshaft Seal						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 04-Jan-2016 Complied With						Hrs				
						Enc				
30502 Rev 3 Part B	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Accessory Gearshaft Seal						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 04-Jan-2016 Complied With						Hrs				
						Enc				
30502 Rev 4	Fuel Control Drive and Accessory Drive Plain Seal - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 20-Oct-2016 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				
30502 Rev 4	Fuel Control Drive and Accessory Drive Plain Seal - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 20-Oct-2016 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				
30502 Rev 4 Part A	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Fuel Control Gearshaft Seal						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 20-Oct-2016 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30502 Rev 4 Part A	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Fuel Control Gearshaft Seal						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 20-Oct-2016 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				
30502 Rev 4 Part B	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Accessory Gearshaft Seal						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 20-Oct-2016 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				
30502 Rev 4 Part B	Fuel Control Drive and Accessory Drive Plain Seal - Replacement of Accessory Gearshaft Seal						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 20-Oct-2016 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				
30504	Replacement of Fuel/Oil Heat Exchanger						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30504	Replacement of Fuel/Oil Heat Exchanger						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30504 Rev 1	Replacement of Fuel/Oil Heat Exchanger						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 25-Sep-2015 Complied With						Hrs				
						Enc				
30504 Rev 1	Replacement of Fuel/Oil Heat Exchanger						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 25-Sep-2015 Complied With						Hrs				
						Enc				
30505	Replacement Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30505	Replacement Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30505 Rev 1	Replacement Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30505 Rev 1	Replacement Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30505 Rev 2	Replacement Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
 72 ENG1						Mos	30-Dec-2021			
Eff: 21-May-2015 Complied With						Hrs				
						Enc				
30505 Rev 2	Replacement Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
 72 ENG2						Mos	31-Dec-2021			
Eff: 21-May-2015 Complied With						Hrs				
						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30505 Rev 3	Replacement of Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
 72 ENG1						Mos	30-Dec-2021			
Eff: 16-Jul-2020 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30505 Rev 3	Replacement of Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
 72 ENG2						Mos	31-Dec-2021			
Eff: 16-Jul-2020 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30505 Rev 4	Replacement of Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
 72 ENG1						Mos	04-Jan-2023			
Eff: 16-Nov-2022 Not Applicable	as per engine S/N					Hrs	251:12			
(AVG MAN HRS: 1.5)						Enc	171			
30505 Rev 4	Replacement of Bleed Off Valve (BOV) Gaskets						RE (-)		Category 3	
 72 ENG2						Mos	08-Aug-2023			
Eff: 16-Nov-2022 Not Applicable	as per engine S/N					Hrs	283:31			
(AVG MAN HRS: 1.5)						Enc	192			
30506	Fuel Manifold Adapters - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30506	Fuel Manifold Adapters - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30506 Rev 1	Fuel Manifold Adapters - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30506 Rev 1	Fuel Manifold Adapters - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30506 Rev 2	Fuel Manifold Adapters - Replacement						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 11-Sep-2015 Complied With						Hrs				
						Enc				
30506 Rev 2	Fuel Manifold Adapters - Replacement						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 11-Sep-2015 Complied With						Hrs				
						Enc				
30508	Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30508	Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30508 Rev 1	Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Complied With					Hrs					
					Enc					
30508 Rev 1	Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Complied With					Hrs					
					Enc					
30508 Rev 2	Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 14-May-2015 Complied With					Hrs					
					Enc					
30508 Rev 2	Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 14-May-2015 Complied With					Hrs					
					Enc					
30508 Rev 3	Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 06-Dec-2018 Complied With					Hrs					
(AVG MAN HRS: 5)					Enc					
30508 Rev 3	Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 06-Dec-2018 Complied With					Hrs					
(AVG MAN HRS: 5)					Enc					
30508 Rev 4	Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 13-Apr-2020 Complied With					Hrs					
(AVG MAN HRS: 5)					Enc					
30508 Rev 4	Replacement/Modification of Intermediate Case Assembly and Oil Level Indicators						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 13-Apr-2020 Complied With					Hrs					
(AVG MAN HRS: 5)					Enc					
30510	Primary and Secondary Fuel Tube Support Bracket - Replacement						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 29-Jan-2015 Complied With					Hrs					
					Enc					
30510	Primary and Secondary Fuel Tube Support Bracket - Replacement						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 29-Jan-2015 Complied With					Hrs					
					Enc					
30511	AGB Cover Bolts or Nuts - Re-Torqueing						T (-)		Category 6	
 72 ENG1					Mos					
Eff: 31-Jul-2015					Hrs					
					Enc					
30511	AGB Cover Bolts or Nuts - Re-Torqueing						T (-)		Category 6	
 72 ENG2					Mos					
Eff: 31-Jul-2015					Hrs					
					Enc					
30511 Rev 1	Re-Torqueing of AGB Cover Bolts or Nuts						T (-)		Category 6	
 72 ENG1					Mos					
Eff: 14-Jun-2016					Hrs					
(AVG MAN HRS: 1.5)					Enc					

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30511 Rev 1	Re-Torqueing of AGB Cover Bolts or Nuts						T (-)		Category 6	
 72 ENG2										
Eff: 14-Jun-2016										
(AVG MAN HRS: 1.5)										
30511 Rev 2	Re-Torqueing of AGB Cover Bolts or Nuts						T (A/R)		Category 6	
 72 ENG1										
Eff: 02-Mar-2021										
(AVG MAN HRS: 1.5)										
30511 Rev 2	Re-Torqueing of AGB Cover Bolts or Nuts						T (A/R)		Category 6	
 72 ENG2										
Eff: 02-Mar-2021										
(AVG MAN HRS: 1.5)										
30516	HP Turbine Seal Rings - Replacement						RE (-)		Category 7	
 72 ENG1										
Complied With										
30516	HP Turbine Seal Rings - Replacement						RE (-)		Category 7	
 72 ENG2										
Complied With										
30516 Rev 1	HP Turbine Seal Rings - Replacement						RE (-)		Category 7	
 72 ENG1										
Complied With										
30516 Rev 1	HP Turbine Seal Rings - Replacement						RE (-)		Category 7	
 72 ENG2										
Complied With										
30516 Rev 2	HP Turbine Seal Rings - Replacement						RE (-)		Category 7	
 72 ENG1										
Eff: 22-Jun-2015 Complied With										
30516 Rev 2	HP Turbine Seal Rings - Replacement						RE (-)		Category 7	
 72 ENG2										
Eff: 22-Jun-2015 Complied With										
30517	Igniter Flange Gaskets - Deletion						RE (-)		Category 6	
 72 ENG1										
Eff: 09-Apr-2015 Complied With										
30517	Igniter Flange Gaskets - Deletion						RE (-)		Category 6	
 72 ENG2										
Eff: 09-Apr-2015 Complied With										
30517 Rev 1	Igniter Flange Gaskets - Deletion						RE (-)		Category 6	
 72 ENG1										
Eff: 05-Jan-2016 Complied With										
(AVG MAN HRS: 1.5)										
30517 Rev 1	Igniter Flange Gaskets - Deletion						RE (-)		Category 6	
 72 ENG2										
Eff: 05-Jan-2016 Complied With										
(AVG MAN HRS: 1.5)										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30518	Turbine Exhaust Case End Cone - Saleability Change						T (A/R)		Category 9	
 72 ENG1										
Eff: 13-Oct-2017										
30518	Turbine Exhaust Case End Cone - Saleability Change						T (A/R)		Category 9	
 72 ENG2										
Eff: 13-Oct-2017										
30521	Replacement of Combustion Chamber Liner						RE (-)		Category 7	
 72 ENG1										
Eff: 20-Nov-2015 Complied With						30-Dec-2021				
(AVG MAN HRS: 1.5)										
30521	Replacement of Combustion Chamber Liner						RE (-)		Category 7	
 72 ENG2										
Eff: 20-Nov-2015 Complied With						31-Dec-2021				
(AVG MAN HRS: 1.5)										
30521 Rev 1	Replacement of Combustion Chamber Liner						RE (-)		Category 7	
 72 ENG1										
Eff: 18-Dec-2015 Complied With						30-Dec-2021				
(AVG MAN HRS: 1.5)										
30521 Rev 1	Replacement of Combustion Chamber Liner						RE (-)		Category 7	
 72 ENG2										
Eff: 18-Dec-2015 Complied With						31-Dec-2021				
(AVG MAN HRS: 1.5)										
30523	Accessory Gearbox Cover Gasket - Replacement						RE (-)		Category 7	
 72 ENG1										
Eff: 07-Aug-2015 Complied With						30-Dec-2021				
30523	Accessory Gearbox Cover Gasket - Replacement						RE (-)		Category 7	
 72 ENG2										
Eff: 07-Aug-2015 Complied With						31-Dec-2021				
30523 Rev 1	Accessory Gearbox Cover Gasket - Replacement						RE (-)		Category 7	
 72 ENG1										
Eff: 30-May-2016 Complied With						30-Dec-2021				
(AVG MAN HRS: 1.5)										
30523 Rev 1	Accessory Gearbox Cover Gasket - Replacement						RE (-)		Category 7	
 72 ENG2										
Eff: 30-May-2016 Complied With						31-Dec-2021				
(AVG MAN HRS: 1.5)										
30526	Modification of Intermediate Case Assembly						T (-)		Category 6	
 72 ENG1										
Eff: 10-Aug-2016										
Note: NOTE: This service bulletin supersedes P&WC SB30429 at overhaul or heavy maintenance where sufficient access to the intermediate case is available.										
30526	Modification of Intermediate Case Assembly						T (-)		Category 6	
 72 ENG2										
Eff: 10-Aug-2016										
Note: NOTE: This service bulletin supersedes P&WC SB30429 at overhaul or heavy maintenance where sufficient access to the intermediate case is available.										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30526 Rev 1	Modification of Intermediate Case Assembly						T (A/R)		Category 6	
 72 ENG1						Mos				
Eff: 21-Dec-2021						Hrs				
(AVG MAN HRS: 1)						Enc				
Note: CONCURRENT REQUIREMENTS: Operators must incorporate SB 30413 prior to, or in conjunction with this service bulletin.										
30526 Rev 1	Modification of Intermediate Case Assembly						RE (-)		Category 6	
 72 ENG2						Mos	30-Jun-2023			
Eff: 21-Dec-2021 Complied With						Hrs				
(AVG MAN HRS: 1)						Enc				
Note: CONCURRENT REQUIREMENTS: Operators must incorporate SB 30413 prior to, or in conjunction with this service bulletin.										
30527	Replacement of No.4 Roller Bearing						RE (-)		Category 9	
 72 ENG1						Mos				
Eff: 01-Dec-2015						Hrs				
						Enc				
30527	Replacement of No.4 Roller Bearing						RE (-)		Category 9	
 72 ENG2						Mos				
Eff: 01-Dec-2015						Hrs				
						Enc				
30535	Replacement of Engine Shipping Container						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 24-Aug-2017 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30535	Replacement of Engine Shipping Container						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 24-Aug-2017 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30535 Rev 1	Replacement of Engine Shipping Container						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 29-Sep-2017 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30535 Rev 1	Replacement of Engine Shipping Container						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 29-Sep-2017 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30535 Rev 2	Replacement of Engine Shipping Container						RE (-)		Category 7	
 72 ENG1						Mos				
Eff: 15-Sep-2023						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30535 Rev 2	Replacement of Engine Shipping Container						RE (-)		Category 7	
 72 ENG2						Mos				
Eff: 15-Sep-2023						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30540	Replacement of High Pressure Turbine Air Seal (CONTROLLED SERVICE USE NO. 0004160)						RE (-)			
 72 ENG1						Mos	30-Dec-2021			
Eff: 26-Feb-2018 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30540	Replacement of High Pressure Turbine Air Seal (CONTROLLED SERVICE USE NO. 0004160)						RE (-)			
 72 ENG2						Mos	31-Dec-2021			
Eff: 26-Feb-2018 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30540 Rev 1	Replacement of High Pressure Turbine Air Seal						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 12-Nov-2020 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30540 Rev 1	Replacement of High Pressure Turbine Air Seal						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 12-Nov-2020 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30540 Rev 2	Replacement of High Pressure Turbine Air Seal						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 26-Oct-2021 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30540 Rev 2	Replacement of High Pressure Turbine Air Seal						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 26-Oct-2021 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30540 Rev 3	Replacement of High Pressure Turbine Air Seal						RE (-)		Category 7	
 72 ENG1						Mos				
Eff: 25-Jul-2024						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30540 Rev 3	Replacement of High Pressure Turbine Air Seal						RE (-)		Category 7	
 72 ENG2						Mos				
Eff: 25-Jul-2024						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30541	Replacement of Fuel Control Drive and Accessory Drive Plain Seal						RE (-)		Category 6, Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 07-Mar-2018 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30541	Replacement of Fuel Control Drive and Accessory Drive Plain Seal						RE (-)		Category 6, Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 07-Mar-2018 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30541 Part A	Replacement of Fuel Control Gearshaft Seal						RE (-)		Category 6, Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 07-Mar-2018 Complied With						Hrs				
						Enc				
30541 Part A	Replacement of Fuel Control Gearshaft Seal						RE (-)		Category 6, Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 07-Mar-2018 Complied With						Hrs				
						Enc				
30541 Part B	Replacement of Accessory Drive Plain Seal						RE (-)		Category 6, Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 07-Mar-2018 Complied With						Hrs				
						Enc				
30541 Part B	Replacement of Accessory Drive Plain Seal						RE (-)		Category 6, Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 07-Mar-2018 Complied With						Hrs				
						Enc				
30541 Rev 1	Replacement of Fuel Control Drive and Accessory Drive Plain Seal						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 12-Jun-2018 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30541 Rev 1	Replacement of Fuel Control Drive and Accessory Drive Plain Seal						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 12-Jun-2018 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30541 Rev 1 Part A	Replacement of Fuel Control Gearshaft Seal						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 12-Jun-2018 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30541 Rev 1 Part A	Replacement of Fuel Control Gearshaft Seal						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 12-Jun-2018 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30541 Rev 1 Part B	Replacement of Accessory Drive Plain Seal						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 12-Jun-2018 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30541 Rev 1 Part B	Replacement of Accessory Drive Plain Seal						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 12-Jun-2018 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30546	Replacement of HPT Air Seal						RE (-)		Category 9	
 72 ENG1						Mos	30-Dec-2021			
Eff: 05-Sep-2019 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30546	Replacement of HPT Air Seal						RE (-)		Category 9	
 72 ENG2						Mos	31-Dec-2021			
Eff: 05-Sep-2019 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30546 Rev 1	Replacement of HPT Air Seal						RE (-)		Category 9	
 72 ENG1						Mos	30-Dec-2021			
Eff: 06-Nov-2019 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30546 Rev 1	Replacement of HPT Air Seal						RE (-)		Category 9	
 72 ENG2						Mos	31-Dec-2021			
Eff: 06-Nov-2019 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30546 Rev 2	Replacement of HPT Air Seal						RE (-)		Category 9	
 72 ENG1						Mos	30-Dec-2021			
Eff: 12-Apr-2021 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30546 Rev 2	Replacement of HPT Air Seal						RE (-)		Category 9	
 72 ENG2						Mos	31-Dec-2021			
Eff: 12-Apr-2021 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30550	Replacement of No. 4 Bearing Seal Runners						RE (-)		Category 7	
 72 ENG1						Mos	30-Dec-2021			
Eff: 09-May-2019 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30550	Replacement of No. 4 Bearing Seal Runners						RE (-)		Category 7	
 72 ENG2						Mos	31-Dec-2021			
Eff: 09-May-2019 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30550 Part A	Replacement of No. 4 Bearing Seal Runners - Front No.4 Bearing Seal Runner						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 09-May-2019 Complied With					Hrs					
(AVG MAN HRS: 1.5)					Enc					
30550 Part A	Replacement of No. 4 Bearing Seal Runners - Front No.4 Bearing Seal Runner						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 09-May-2019 Complied With					Hrs					
(AVG MAN HRS: 1.5)					Enc					
30550 Part B	Replacement of No. 4 Bearing Seal Runners - Rear No.4 Bearing Seal Runner						RE (-)		Category 7	
 72 ENG1					Mos	30-Dec-2021				
Eff: 09-May-2019 Complied With					Hrs					
(AVG MAN HRS: 1.5)					Enc					
30550 Part B	Replacement of No. 4 Bearing Seal Runners - Rear No.4 Bearing Seal Runner						RE (-)		Category 7	
 72 ENG2					Mos	31-Dec-2021				
Eff: 09-May-2019 Complied With					Hrs					
(AVG MAN HRS: 1.5)					Enc					
30562	Replacement of Mixer Assembly						RE (-)		Category 9	
 72 ENG1					Mos	30-Dec-2021				
Eff: 18-May-2021 Complied With					Hrs					
(AVG MAN HRS: 1.5)					Enc					
30562	Replacement of Mixer Assembly						RE (-)		Category 9	
 72 ENG2					Mos	31-Dec-2021				
Eff: 18-May-2021 Complied With					Hrs					
(AVG MAN HRS: 1.5)					Enc					
30562 Rev 1	Replacement of Mixer Assembly						RE (-)		Category 9	
 72 ENG1					Mos	30-Dec-2021				
Eff: 27-May-2021 Complied With					Hrs					
(AVG MAN HRS: 1.5)					Enc					
30562 Rev 1	Replacement of Mixer Assembly						RE (-)		Category 9	
 72 ENG2					Mos	31-Dec-2021				
Eff: 27-May-2021 Complied With					Hrs					
(AVG MAN HRS: 1.5)					Enc					
30562 Rev 2	Replacement of Mixer Assembly						RE (-)		Category 9	
 72 ENG1					Mos	30-Dec-2021				
Eff: 26-Oct-2021 Complied With					Hrs					
(AVG MAN HRS: 1.5)					Enc					
30562 Rev 2	Replacement of Mixer Assembly						RE (-)		Category 9	
 72 ENG2					Mos	31-Dec-2021				
Eff: 26-Oct-2021 Complied With					Hrs					
(AVG MAN HRS: 1.5)					Enc					
30562 Rev 3	Replacement of Mixer Assembly						RE (-)		Category 9	
 72 ENG1					Mos	30-Dec-2021				
Eff: 04-Nov-2021 Complied With					Hrs					
(AVG MAN HRS: 1.5)					Enc					
30562 Rev 3	Replacement of Mixer Assembly						RE (-)		Category 9	
 72 ENG2					Mos	31-Dec-2021				
Eff: 04-Nov-2021 Complied With					Hrs					
(AVG MAN HRS: 1.5)					Enc					
30564	Replacement of Lockbolt Collar						T (-)		Category 9	
 72 ENG1					Mos					
Eff: 16-Sep-2022					Hrs					
(AVG MAN HRS: 1.5)					Enc					

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30564		Replacement of Lockbolt Collar						T (-)		Category 9	
	72 ENG2					Mos					
	Eff: 16-Sep-2022					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30564 Rev 1		Replacement of Lockbolt Collar						T (-)		Category 9	
	72 ENG1					Mos					
	Eff: 21-Dec-2022					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30564 Rev 1		Replacement of Lockbolt Collar						T (-)		Category 9	
	72 ENG2					Mos					
	Eff: 21-Dec-2022					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30564 Rev 2		Replacement/Modification of Second Stage Turbine Vane						T (-)		Category 7	
	72 ENG1					Mos					
	Eff: 27-Jan-2023					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30564 Rev 2		Replacement/Modification of Second Stage Turbine Vane						T (-)		Category 7	
	72 ENG2					Mos					
	Eff: 27-Jan-2023					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30564 Rev 3		Replacement/Modification of Second Stage Turbine Vane						T (A/R)		Category 7	
	72 ENG1					Mos					
	Eff: 18-Sep-2023					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30564 Rev 3		Replacement/Modification of Second Stage Turbine Vane						T (A/R)		Category 7	
	72 ENG2					Mos					
	Eff: 18-Sep-2023					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30568		Replacement of No. 4 Bearing Front and Rear Seal Runners						T (-)		Category 7	
	72 ENG1					Mos					
	Eff: 17-Oct-2022					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30568		Replacement of No. 4 Bearing Front and Rear Seal Runners						T (-)		Category 7	
	72 ENG2					Mos					
	Eff: 17-Oct-2022					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30568 Rev 1		Replacement of No. 4 Bearing Front and Rear Seal Runners						RE (-)		Category 7	
	72 ENG1					Mos					
	Eff: 12-Jan-2023					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30568 Rev 1		Replacement of No. 4 Bearing Front and Rear Seal Runners						RE (-)		Category 7	
	72 ENG2					Mos					
	Eff: 12-Jan-2023					Hrs					
	(AVG MAN HRS: 1.5)					Enc					
30568 Rev 1 Part A		Replacement of No. 4 Bearing Front and Rear Seal Runners - Replacement of the Front No. 4 Bearing Seal Runner						T (A/R)		Category 7	
	72 ENG1					Mos					
	Eff: 12-Jan-2023					Hrs					
						Enc					
30568 Rev 1 Part A		Replacement of No. 4 Bearing Front and Rear Seal Runners - Replacement of the Front No. 4 Bearing Seal Runner						T (A/R)		Category 7	
	72 ENG2					Mos					
	Eff: 12-Jan-2023					Hrs					
						Enc					

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
30568 Rev 1 Part B		Replacement of No. 4 Bearing Front and Rear Seal Runners - Replacement of the Rear No. 4 Bearing Seal Runner						T (A/R)		Category 7	
	72 ENG1										
	Eff: 12-Jan-2023										
30568 Rev 1 Part B		Replacement of No. 4 Bearing Front and Rear Seal Runners - Replacement of the Rear No. 4 Bearing Seal Runner						T (A/R)		Category 7	
	72 ENG2										
	Eff: 12-Jan-2023										
30569		Replacement of Intermediate Case						RE (-)		Category 7	
	72 ENG1										
30569		Replacement of Intermediate Case						RE (-)		Category 7	
	72 ENG2										
30569 Rev 1		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG1										
	Eff: 24-Dec-2023										
30569 Rev 1		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG2										
	Eff: 24-Dec-2023										
30569 Rev 2		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG1										
	Eff: 18-Jan-2024										
30569 Rev 2		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG2										
	Eff: 18-Jan-2024										
30569 Rev 3		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG1										
	Eff: 31-Jan-2024										
30569 Rev 3		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG2										
	Eff: 31-Jan-2024										
30569 Rev 4		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG1										
	Eff: 22-Feb-2024										
30569 Rev 4		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG2										
	Eff: 22-Feb-2024										
30569 Rev 5		Replacement of Intermediate Case						T (-)		Category 7	
	72 ENG1										
	Eff: 15-Mar-2024										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30569 Rev 5	Replacement of Intermediate Case						T (-)		Category 7	
 72 ENG2										
Eff: 15-Mar-2024										
30569 Rev 6	Replacement of Intermediate Case						T (-)		Category 7	
 72 ENG1										
Eff: 10-Apr-2024										
30569 Rev 6	Replacement of Intermediate Case						T (-)		Category 7	
 72 ENG2										
Eff: 10-Apr-2024										
30569 Rev 7	Replacement of Intermediate Case						T (-)		Category 7	
 72 ENG1										
Eff: 26-Jul-2024										
30569 Rev 7	Replacement of Intermediate Case						T (-)		Category 7	
 72 ENG2										
Eff: 26-Jul-2024										
30569 Rev 8	Replacement of Intermediate Case						T (A/R)		Category 7	
 72 ENG1										
Eff: 20-Sep-2024										
30569 Rev 8	Replacement of Intermediate Case						T (A/R)		Category 7	
 72 ENG2										
Eff: 20-Sep-2024										
30572	Inspection of HP Turbine Disk						T (A/R)		Category 5	
 72 ENG1										
Eff: 31-Jul-2023										
(AVG MAN HRS: 2)										
Note: EFFECTIVITY: Refer to Par. 1.A. of this SB for more information.										
30572	Inspection of HP Turbine Disk						T (A/R)		Category 5	
 72 ENG2										
Eff: 31-Jul-2023										
(AVG MAN HRS: 2)										
Note: EFFECTIVITY: Refer to Par. 1.A. of this SB for more information.										
72-00-PW-057	Low Utilization Inspection						T		EMM - Requirement	
 72 ENG1							10		30-Dec-2031	7.2 Years
Note: An additional 1 month or 10 flight-hours, whichever comes first, is available for scheduling purposes. Following the overhaul of a low utilization engine, the recommended initial on-wing Low Utilization Inspection (LUI) is at 10 years after engine overhaul.										
72-00-PW-057	Low Utilization Inspection						T		EMM - Requirement	
 72 ENG2							10		31-Dec-2031	7.2 Years
Note: An additional 1 month or 10 flight-hours, whichever comes first, is available for scheduling purposes. Following the overhaul of a low utilization engine, the recommended initial on-wing Low Utilization Inspection (LUI) is at 10 years after engine overhaul.										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
72-00-PW-059	Engine - Overhaul						RE	05-20-00, EMM - Requirement, Extended TBO		≈18-Jul-2030
 72 ENG1	(SOURCE: PW535B MM (P/N 3071822); PW545A MM (P/N 30J1272)) Note: Applicable to PW545C engines which meet the following criteria: (a)The participation in an engine condition trend monitoring (ECTM) program, as defined in the P&WC Publication SIL GEN-055, is required from new engine delivery or from a scheduled maintenance event (HSL/Overhaul). (b) The rotor component life limitations, as outlined in the AIRWORTHINESS LIMITATIONS section of this manual, are not exceeded. Replace engine mount isolators at every second Engine Overhaul. The engine mount isolators do not have an hourly replacement requirement. They are replaced by the number of engine overhauls. Discard LP Compressor Shaft at scheduled overhaul if shaft has accumulated 10,000 hours or more.									
					Mos					
					Hrs		5,500	+50	5500	4140:04 Hrs (+50)
					Enc					
72-00-PW-059	Engine - Overhaul						RE	05-20-00, EMM - Requirement, Extended TBO		≈04-Jan-2031
 72 ENG2	(SOURCE: PW535B MM (P/N 3071822); PW545A MM (P/N 30J1272)) Note: Applicable to PW545C engines which meet the following criteria: (a)The participation in an engine condition trend monitoring (ECTM) program, as defined in the P&WC Publication SIL GEN-055, is required from new engine delivery or from a scheduled maintenance event (HSL/Overhaul). (b) The rotor component life limitations, as outlined in the AIRWORTHINESS LIMITATIONS section of this manual, are not exceeded. Replace engine mount isolators at every second Engine Overhaul. The engine mount isolators do not have an hourly replacement requirement. They are replaced by the number of engine overhauls. Discard LP Compressor Shaft at scheduled overhaul if shaft has accumulated 10,000 hours or more.									
					Mos					
					Hrs		5,500	+50	5500	4473:12 Hrs (+50)
					Enc					
72-00-PW-061	Engine - Hot Section Inspection (HSI)						RE	EMM - Requirement, Extended HSI		≈19-Sep-2026
 72 ENG1	Ref:72-00-00-ic Note: Applicable to PW545C engines which meet the following criteria: (a)The participation in an engine condition trend monitoring (ECTM) program, as defined in the P&WC Publication SIL GEN-055, is required from new engine delivery or from a scheduled maintenance event (HSL/Overhaul). (b) The rotor component life limitations, as outlined in the AIRWORTHINESS LIMITATIONS section of this manual, are not exceeded.									
					Mos					
					Hrs		2,750	-/+50	2750	1390:04 Hrs (+50)
					Enc					
72-00-PW-061	Engine - Hot Section Inspection (HSI)						RE	EMM - Requirement, Extended HSI		≈07-Mar-2027
 72 ENG2	Ref:72-00-00-ic Note: Applicable to PW545C engines which meet the following criteria: (a)The participation in an engine condition trend monitoring (ECTM) program, as defined in the P&WC Publication SIL GEN-055, is required from new engine delivery or from a scheduled maintenance event (HSL/Overhaul). (b) The rotor component life limitations, as outlined in the AIRWORTHINESS LIMITATIONS section of this manual, are not exceeded.									
					Mos					
					Hrs		2,750	-/+50	2750	1723:12 Hrs (+50)
					Enc					
72-00-PW-063	Check Time Limited Dispatch Annunciations						RE	EMM - Requirement		≈23-Nov-2024
 72 ENG1										
					Mos	16-Sep-2024				
					Hrs	1292:19	150	-/+20	1442:19	82:23 Hrs (+20)
					Enc	898				
 KGR-WP-010 START 11-NOV-2024										
72-00-PW-063	Check Time Limited Dispatch Annunciations						RE	EMM - Requirement		≈23-Nov-2024
 72 ENG2										
					Mos	16-Sep-2024				
					Hrs	959:11	150	-/+20	1109:11	82:23 Hrs (+20)
					Enc	683				
 KGR-WP-010 START 11-NOV-2024										
723004-0101	LP Compressor Shaft						RE	05-20-00, EMM - Life Limit		≈22-Oct-2036
 72 ENG1										
					Mos	30-Dec-2021				
30J3206-01	New				Hrs	0	10,000		10000	8640:04 Hrs
PKAA938876		0			Enc	0	20,000		20,000	19,043 Enc
(SOURCE: PW545C MM (P/N 30J2302)) Note: Discard at scheduled overhaul. If shaft has accumulated 10,000 hours or more.										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
723004-0101		LP Compressor Shaft						RE	05-20-00, EMM - Life Limit		≈09-Apr-2037
	72 ENG2					Mos	31-Dec-2021				
	30J3206-01	New	0			Hrs	0	10,000		10000	8973:12 Hrs
	PKAAA927820		0			Enc	0	20,000		20,000	19,258 Enc
	(SOURCE: PW545C MM (P/N 30J2302))										
	Note: Discard at scheduled overhaul. If shaft has accumulated 10,000 hours or more.										
72-31-00-201		Engine Mount General Visual Inspection: Do a check for security and condition of the engine mount.						RE	EMM - Periodic Inspection		≈25-Jan-2025
	72 ENG1	72EH0800				Mos	27-Oct-2023				
						Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
						Enc	505				
	KGR-WP-011 START 21-JAN-2025										
72-31-00-201		Engine Mount General Visual Inspection: Do a check for security and condition of the engine mount.						RE	EMM - Periodic Inspection		≈03-Jun-2025
	72 ENG2	72EH0800				Mos	22-May-2024				
						Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
						Enc	483				
72-31-00-202		External Engine General Visual Inspection: Do an inspection for fuel and oil leaks, corrosion, cracks and signs of damage.						RE	EMM - Periodic Inspection		≈25-Jan-2025
	72 ENG1	72EH0000,...				Mos	27-Oct-2023				
						Hrs	763:53	800	-/+25	≈1563:53	
						Enc	505				
	KGR-WP-011 START 21-JAN-2025										
72-31-00-202		External Engine General Visual Inspection: Do an inspection for fuel and oil leaks, corrosion, cracks and signs of damage.						RE	EMM - Periodic Inspection		≈03-Jun-2025
	72 ENG2	72EH0000,...				Mos	22-May-2024				
						Hrs	687:03	800	-/+25	≈1487:03	
						Enc	483				
72-31-00-203		Compressor Inlet General Visual Inspection: Do an inspection of the compressor inlet fan, fan exit stator vanes, abradable fan seal for cleanliness, damage, corrosion, erosion and FOD.						RE	EMM - Periodic Inspection		≈25-Jan-2025
	72 ENG1	72EH0800				Mos	27-Oct-2023				
						Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
						Enc	505				
	(SOURCE: PW545C MM 30J2302)										
	Note: For engine that operates more than 40% of the time in zones considered extreme in terms of environmental harshness per environment maps (Ref. 05-20-00, ENGINE EXTERNALS AND COMPRESSOR WASH, Fig. 1 thru 6), do a borescope/visual inspection of the bleed valve seat on the intermediate case, main intermediate case flanges. Do a magnesium corrosion treatment as necessary (Ref. 70-00-00, STANDARD PRACTICES - MAINTENANCE PROCEDURES).										
	KGR-WP-011 START 21-JAN-2025										
72-31-00-203		Compressor Inlet General Visual Inspection: Do an inspection of the compressor inlet fan, fan exit stator vanes, abradable fan seal for cleanliness, damage, corrosion, erosion and FOD.						RE	EMM - Periodic Inspection		≈03-Jun-2025
	72 ENG2	72EH0800				Mos	22-May-2024				
						Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
						Enc	483				
	(SOURCE: PW545C MM 30J2302)										
	Note: For engine that operates more than 40% of the time in zones considered extreme in terms of environmental harshness per environment maps (Ref. 05-20-00, ENGINE EXTERNALS AND COMPRESSOR WASH, Fig. 1 thru 6), do a borescope/visual inspection of the bleed valve seat on the intermediate case, main intermediate case flanges. Do a magnesium corrosion treatment as necessary (Ref. 70-00-00, STANDARD PRACTICES - MAINTENANCE PROCEDURES).										
72-31-00-203		Compressor Inlet General Visual Inspection: Do an inspection of the compressor inlet fan, fan exit stator vanes, abradable fan seal for cleanliness, damage, corrosion, erosion and FOD. When outside air temperature is 5°C (41°F) or below: Examine the bottom center area of the fan case for ice. Make sure that the fan turns freely.						RE (PreFlight)	EMM - Periodic Inspection		
	72 ENG1	72EH0000				Mos					
						Hrs					
						Enc					
72-31-00-203		Compressor Inlet General Visual Inspection: Do an inspection of the compressor inlet fan, fan exit stator vanes, abradable fan seal for cleanliness, damage, corrosion, erosion and FOD. When outside air temperature is 5°C (41°F) or below: Examine the bottom center area of the fan case for ice. Make sure that the fan turns freely.						RE (PreFlight)	EMM - Periodic Inspection		
	72 ENG2	72EH0000				Mos					
						Hrs					
						Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
72-31-00-901		Low Pressure Compressor Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈18-Jul-2030
	72 ENG1					Mos					
		(SOURCE: PW545C MM 30J2302)				Hrs		5,500	+50	5500	4140:04 Hrs (+50)
		Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.				Enc					
72-31-00-901		Low Pressure Compressor Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈04-Jan-2031
	72 ENG2					Mos					
		(SOURCE: PW545C MM 30J2302)				Hrs		5,500	+50	5500	4473:12 Hrs (+50)
		Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.				Enc					
72-32-00-201		Compressor Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈19-Sep-2026
	72 ENG1					Mos					
		Ref:72-00-00-ic (SOURCE: PW545C MM 30J2302)				Hrs		2,750	+50	2750	1390:04 Hrs (+50)
		Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.				Enc					
72-32-00-201		Compressor Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈07-Mar-2027
	72 ENG2					Mos					
		Ref:72-00-00-ic (SOURCE: PW545C MM 30J2302)				Hrs		2,750	+50	2750	1723:12 Hrs (+50)
		Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.				Enc					
72-32-00-901		High Pressure Compressor Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303. Second-stage HP Compressor Rotor: If the rotor has accumulated more than 4000 hours, replace the rotor at scheduled overhaul.						RE	EMM - Periodic Inspection, Extended TBO		≈18-Jul-2030
	72 ENG1					Mos					
		(SOURCE: PW545C MM 30J2302)				Hrs		5,500	+50	5500	4140:04 Hrs (+50)
		Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.				Enc					
72-32-00-901		High Pressure Compressor Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303. Second-stage HP Compressor Rotor: If the rotor has accumulated more than 4000 hours, replace the rotor at scheduled overhaul.						RE	EMM - Periodic Inspection, Extended TBO		≈04-Jan-2031
	72 ENG2					Mos					
		(SOURCE: PW545C MM 30J2302)				Hrs		5,500	+50	5500	4473:12 Hrs (+50)
		Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.				Enc					
72-40-00-201		Combustion Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈19-Sep-2026
	72 ENG1					Mos					
		Ref:72-00-00-ic (SOURCE: PW545C MM 30J2302)				Hrs		2,750	+50	2750	1390:04 Hrs (+50)
		Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.				Enc					
72-40-00-201		Combustion Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈07-Mar-2027
	72 ENG2					Mos					
		Ref:72-00-00-ic (SOURCE: PW545C MM 30J2302)				Hrs		2,750	+50	2750	1723:12 Hrs (+50)
		Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.				Enc					
72-40-00-901		Combustion Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈18-Jul-2030
	72 ENG1					Mos					
		(SOURCE: PW545C MM 30J2302)				Hrs		5,500	+50	5500	4140:04 Hrs (+50)
		Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.				Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
72-40-00-901		Combustion Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈04-Jan-2031
	72 ENG2					Mos					
		(SOURCE: PW545C MM 30J2302)				Hrs		5,500	+50	5500	4473:12 Hrs (+50)
		Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.				Enc					
72-50-00-201		Turbine Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈19-Sep-2026
	72 ENG1					Mos					
		Ref:72-00-00-ic (SOURCE: PW545C MM 30J2302)				Hrs		2,750	+50	2750	1390:04 Hrs (+50)
		Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.				Enc					
72-50-00-201		Turbine Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈07-Mar-2027
	72 ENG2					Mos					
		Ref:72-00-00-ic (SOURCE: PW545C MM 30J2302)				Hrs		2,750	+50	2750	1723:12 Hrs (+50)
		Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.				Enc					
72-50-00-701		Performance Calibration (5-Point Run) Functional Check: Do a performance calibration check (Ref. 71-00-00, POWER PLANT - ADJUSTMENT/TEST) and compare with previous 5-point performance calibration. Alternatively, monitor the engine performance through Engine Condition Trend Monitoring (ECTM).						RE	EMM - Periodic Inspection		≈25-Jan-2025
	72 ENG1	72EH0800				Mos	27-Oct-2023				
		Ref:71-00-00-at				Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
	KGR-WP-011 START 21-JAN-2025										
72-50-00-701		Performance Calibration (5-Point Run) Functional Check: Do a performance calibration check (Ref. 71-00-00, POWER PLANT - ADJUSTMENT/TEST) and compare with previous 5-point performance calibration. Alternatively, monitor the engine performance through Engine Condition Trend Monitoring (ECTM).						RE	EMM - Periodic Inspection		≈03-Jun-2025
	72 ENG2	72EH0800				Mos	22-May-2024				
		Ref:71-00-00-at				Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
						Enc	483				
72-50-00-901		Turbine Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303. Discard the HPT nut and keywasher.						RE	EMM - Periodic Inspection, Extended TBO		≈18-Jul-2030
	72 ENG1					Mos					
		(SOURCE: PW545C MM (P/N 30J2302))				Hrs		5,500	+50	5500	4140:04 Hrs (+50)
		Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.				Enc					
72-50-00-901		Turbine Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303. Discard the HPT nut and keywasher.						RE	EMM - Periodic Inspection, Extended TBO		≈04-Jan-2031
	72 ENG2					Mos					
		(SOURCE: PW545C MM (P/N 30J2302))				Hrs		5,500	+50	5500	4473:12 Hrs (+50)
		Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.				Enc					
72-60-00-201		Engine Accessory General Visual Inspection: Do a check for security of installation and general condition of accessories and gearbox.						RE	EMM - Periodic Inspection		≈25-Jan-2025
	72 ENG1	72EH0800				Mos	27-Oct-2023				
						Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
						Enc	505				
	KGR-WP-011 START 21-JAN-2025										
72-60-00-201		Engine Accessory General Visual Inspection: Do a check for security of installation and general condition of accessories and gearbox.						RE	EMM - Periodic Inspection		≈03-Jun-2025
	72 ENG2	72EH0800				Mos	22-May-2024				
						Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
						Enc	483				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
72-60-00-901	Accessory Gearbox (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈18-Jul-2030
 72 ENG1						Mos				
	(SOURCE: PW545C MM 30J2302)					Hrs	5,500	+50	5500	4140:04 Hrs (+50)
	Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.					Enc				
72-60-00-901	Accessory Gearbox (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈04-Jan-2031
 72 ENG2						Mos				
	(SOURCE: PW545C MM 30J2302)					Hrs	5,500	+50	5500	4473:12 Hrs (+50)
	Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.					Enc				
726060	Annular Ball Bearing						RE (O/C)			
 72 ENG1						Mos	30-Dec-2021			
31J2322-01	New					Hrs	0			
FCN547890						Enc	0			
726060	Annular Ball Bearing						RE (O/C)			
 72 ENG2						Mos	31-Dec-2021			
31J2322-01	New					Hrs	0			
FCN547884						Enc	0			
72-70-00-201	Bypass Ducts and Fairings General Visual Inspection: Do a check for cleanliness and FOD.Do an inspection for cracks in the outer bypass duct, rear bypass duct, struts and fairing.						RE	EMM - Periodic Inspection		≈25-Jan-2025
 72 ENG1	72EH0800					Mos	27-Oct-2023			
						Hrs	763:53	800	-/+25 (1563:53)	203:57 Hrs (+25)
						Enc	505			
 KGR-WP-011	START 21-JAN-2025									
72-70-00-201	Bypass Ducts and Fairings General Visual Inspection: Do a check for cleanliness and FOD.Do an inspection for cracks in the outer bypass duct, rear bypass duct, struts and fairing.						RE	EMM - Periodic Inspection		≈03-Jun-2025
 72 ENG2	72EH0800					Mos	22-May-2024			
						Hrs	687:03	800	-/+25 (1487:03)	460:15 Hrs (+25)
						Enc	483			
72-70-00-202	Bypass Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈19-Sep-2026
 72 ENG1						Mos				
	Ref:72-00-00-ic (SOURCE: PW545C MM 30J2302)					Hrs	2,750	+50	2750	1390:04 Hrs (+50)
	Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.					Enc				
72-70-00-202	Bypass Section (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈07-Mar-2027
 72 ENG2						Mos				
	Ref:72-00-00-ic (SOURCE: PW545C MM 30J2302)					Hrs	2,750	+50	2750	1723:12 Hrs (+50)
	Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.					Enc				
72-70-00-901	Bypass Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈18-Jul-2030
 72 ENG1						Mos				
	(SOURCE: PW545C MM 30J2302)					Hrs	5,500	+50	5500	4140:04 Hrs (+50)
	Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.					Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
72-70-00-901	Bypass Section (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈04-Jan-2031
 72 ENG2						Mos				
	(SOURCE: PW545C MM 30J2302)					Hrs	5,500	+50	5500	4473:12 Hrs (+50)
	Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.					Enc				
72EH0000	Pre-flight/Daily Engine Inspection						RE (PreFlight)			
 72 ENG1						Mos				
						Hrs				
						Enc				
72EH0000	Pre-flight/Daily Engine Inspection						RE (PreFlight)			
 72 ENG2						Mos				
						Hrs				
						Enc				
72EH0800	800 Engine Hours Periodic Inspection (For MSG-3 Scheduled Maintenance Program)						RE	EMM - Periodic Inspection		≈25-Jan-2025
 72 ENG1						Mos	27-Oct-2023			
						Hrs	763:53	800	-/+25	1563:53
						Enc	505			203:57 Hrs (+25)
 KGR-WP-011 START 21-JAN-2025										
72EH0800	800 Engine Hours Periodic Inspection (For MSG-3 Scheduled Maintenance Program)						RE	EMM - Periodic Inspection		≈03-Jun-2025
 72 ENG2						Mos	22-May-2024			
						Hrs	687:03	800	-/+25	1487:03
						Enc	483			460:15 Hrs (+25)
A30452	Oil System - Special Inspection of MOP						RE (-)		Category 10	
 72 ENG1						Mos				
						Hrs				
						Enc				
A30452	Oil System - Special Inspection of MOP						RE (-)		Category 10	
 72 ENG2						Mos				
						Hrs				
						Enc				
A30452 Rev 1	Oil System - Special Inspection of MOP						RE (-)		Category 10	
 72 ENG1						Mos				
						Hrs				
						Enc				
A30452 Rev 1	Oil System - Special Inspection of MOP						RE (-)		Category 10	
 72 ENG2						Mos				
						Hrs				
						Enc				
A30452 Rev 2	Oil System - Special Inspection of MOP						T (A/R)		Category 10	
 72 ENG1						Mos				
Eff: 31-Jul-2015						Hrs				
						Enc				
A30452 Rev 2	Oil System - Special Inspection of MOP						T (A/R)		Category 10	
 72 ENG2						Mos				
Eff: 31-Jul-2015						Hrs				
						Enc				
Engine 1	Pratt & Whitney of Canada - PW545C						RE (-)			
 72 A/F						Mos				
30J2934-01	Time at install:					Hrs				
PCE-DF0667						Ldg				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
Engine 2	Pratt & Whitney of Canada - PW545C								RE (-)	
72 A/F						Mos	21-Jul-2023			
30J2934-01	Time at install: 243.2 Hrs, 165 Enc					Hrs	576:24			
PCE-DF0666						Ldg	380			
SIL No. GEN-143	P&WC Oil Analysis Technology Trial Program								T (-)	Service Information Letter
72 ENG1						Mos				
Eff: 18-Aug-2016						Hrs				
	Note: NOTE: The purpose of this Service Information Letter is to introduce P&WC operators to the new Oil Analysis Technology Trial program currently in progress for the next 18 to 24 months at P&WC.					Enc				
SIL No. GEN-143	P&WC Oil Analysis Technology Trial Program								T (-)	Service Information Letter
72 ENG2						Mos				
Eff: 18-Aug-2016						Hrs				
	Note: NOTE: The purpose of this Service Information Letter is to introduce P&WC operators to the new Oil Analysis Technology Trial program currently in progress for the next 18 to 24 months at P&WC.					Enc				
SIL No. GEN-143 Rev 1	P&WC Oil Analysis Technology Trial Program								T (A/R)	Service Information Letter
72 ENG1						Mos				
Eff: 02-Feb-2017						Hrs				
	Note: NOTE: It is recommended that this procedure be accomplished by the operator as soon as practicable upon first oil sampling kit reception and during scheduled maintenance.					Enc				
SIL No. GEN-143 Rev 1	P&WC Oil Analysis Technology Trial Program								T (A/R)	Service Information Letter
72 ENG2						Mos				
Eff: 02-Feb-2017						Hrs				
	Note: NOTE: It is recommended that this procedure be accomplished by the operator as soon as practicable upon first oil sampling kit reception and during scheduled maintenance.					Enc				
SIL-GEN-015 R2	Shipment Discrepancies, New Non-Conforming Material and Material Returns								T (A/R)	Service Information Letter
72 ENG1						Mos				
Eff: 23-Nov-2020						Hrs				
						Enc				
SIL-GEN-015 R2	Shipment Discrepancies, New Non-Conforming Material and Material Returns								T (A/R)	Service Information Letter
72 ENG2						Mos				
Eff: 23-Nov-2020						Hrs				
						Enc				
SIL-GEN-016	Basic Unplanned Removals (BUR)								T (-)	Service Information Letter
72 ENG1						Mos				
Eff: 01-Jun-1995						Hrs				
						Enc				
SIL-GEN-016	Basic Unplanned Removals (BUR)								T (-)	Service Information Letter
72 ENG2						Mos				
Eff: 01-Jun-1995						Hrs				
						Enc				
SIL-GEN-016 Rev 1	Basic Unplanned Removals (BUR)								T (A/R)	Service Information Letter
72 ENG1						Mos				
Eff: 22-Jun-2023						Hrs				
						Enc				
SIL-GEN-016 Rev 1	Basic Unplanned Removals (BUR)								T (A/R)	Service Information Letter
72 ENG2						Mos				
Eff: 22-Jun-2023						Hrs				
						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description								CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI							DUE	Remaining
SIL-GEN-020 Rev 5  72 ENG1 Eff: 15-Jul-2015	Vane Rings Airflow Rig Correlation and Calibration with P&WC					Mos				T (-)		Service Information Letter	
						Hrs							
						Enc							
SIL-GEN-020 Rev 5  72 ENG2 Eff: 15-Jul-2015	Vane Rings Airflow Rig Correlation and Calibration with P&WC					Mos				T (-)		Service Information Letter	
						Hrs							
						Enc							
SIL-GEN-020 Rev 6  72 ENG1 Eff: 27-Sep-2021	Vane Rings Airflow Rig Correlation and Calibration with P&WC					Mos				T (-)		Service Information Letter	
						Hrs							
						Enc							
SIL-GEN-020 Rev 6  72 ENG2 Eff: 27-Sep-2021	Vane Rings Airflow Rig Correlation and Calibration with P&WC					Mos				T (-)		Service Information Letter	
						Hrs							
						Enc							
SIL-GEN-020 Rev 7  72 ENG1 Eff: 09-Jan-2023	Vane Rings Airflow Rig Correlation and Calibration with P&WC					Mos				T (-)		Service Information Letter	
						Hrs							
						Enc							
SIL-GEN-020 Rev 7  72 ENG2 Eff: 09-Jan-2023	Vane Rings Airflow Rig Correlation and Calibration with P&WC					Mos				T (-)		Service Information Letter	
						Hrs							
						Enc							
SIL-GEN-020 Rev 8  72 ENG1 Eff: 10-Jan-2023	Vane Rings Airflow Rig Correlation and Calibration with P&WC					Mos				T (-)		Service Information Letter	
						Hrs							
						Enc							
SIL-GEN-020 Rev 8  72 ENG2 Eff: 10-Jan-2023	Vane Rings Airflow Rig Correlation and Calibration with P&WC					Mos				T (-)		Service Information Letter	
						Hrs							
						Enc							
SIL-GEN-020 Rev 9  72 ENG1 Eff: 12-Jan-2024	Vane Rings Airflow Rig Correlation and Calibration with P&WC					Mos				T (A/R)		Service Information Letter	
						Hrs							
						Enc							
SIL-GEN-020 Rev 9  72 ENG2 Eff: 12-Jan-2024	Vane Rings Airflow Rig Correlation and Calibration with P&WC					Mos				T (A/R)		Service Information Letter	
						Hrs							
						Enc							
SIL-GEN-022 R10  72 ENG1 Eff: 27-Apr-2020	P&WC Service Tool Procurement					Mos				T (-)		Service Information Letter	
						Hrs							
						Enc							
SIL-GEN-022 R10  72 ENG2 Eff: 27-Apr-2020	P&WC Service Tool Procurement					Mos				T (-)		Service Information Letter	
						Hrs							
						Enc							
SIL-GEN-022 Rev 11  72 ENG1 Eff: 27-Apr-2020	PWC Service Tool Procurement					Mos				T (-)		Service Information Letter	
						Hrs							
						Enc							

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-022 Rev 11		PWC Service Tool Procurement						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 27-Apr-2020					Hrs					
						Enc					
SIL-GEN-022 Rev 12		PWC Service Tool Procurement						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 29-May-2023					Hrs					
						Enc					
	Note: Applicability: ALL P&WC ENGINE.										
SIL-GEN-022 Rev 12		PWC Service Tool Procurement						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 29-May-2023					Hrs					
						Enc					
	Note: Applicability: ALL P&WC ENGINE.										
SIL-GEN-034 Rev 3		Engine Maintenance at other than Pratt and Whitney Canada Corp. ("PWC") Recommended Time Between Overhaul ("TBO")/Hot Section Inspection ("HSI") Intervals and the Effect on Warranty						T (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 10-Nov-2012					Hrs					
						Enc					
SIL-GEN-034 Rev 3		Engine Maintenance at other than Pratt and Whitney Canada Corp. ("PWC") Recommended Time Between Overhaul ("TBO")/Hot Section Inspection ("HSI") Intervals and the Effect on Warranty						T (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 10-Nov-2012					Hrs					
						Enc					
SIL-GEN-034 Rev 4		Engine Maintenance at other than Pratt and Whitney Canada Corp. ("PWC") Recommended Time Between Overhaul ("TBO")/Hot Section Inspection ("HSI") /Periodic Maintenance Intervals and the Effect on Warranty						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 13-Jun-2023					Hrs					
						Enc					
SIL-GEN-034 Rev 4		Engine Maintenance at other than Pratt and Whitney Canada Corp. ("PWC") Recommended Time Between Overhaul ("TBO")/Hot Section Inspection ("HSI") /Periodic Maintenance Intervals and the Effect on Warranty						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 13-Jun-2023					Hrs					
						Enc					
SIL-GEN-038 R4		Use of Non-Pratt and Whitney Canada (PWC) Supported Parts or Non-PWC Approved Repair Schemes						T (A/R)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 13-Jun-2023					Hrs					
						Enc					
SIL-GEN-038 R4		Use of Non-Pratt and Whitney Canada (PWC) Supported Parts or Non-PWC Approved Repair Schemes						T (A/R)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 13-Jun-2023					Hrs					
						Enc					
SIL-GEN-044		Return of Engine Parts to Pratt & Whitney Canada Inc. (P&WC) for Investigation - Evaluation						RE (-)		Service Information Letter	
	72 ENG1					Mos					
	Eff: 03-Jun-1998					Hrs					
						Enc					
SIL-GEN-044		Return of Engine Parts to Pratt & Whitney Canada Inc. (P&WC) for Investigation - Evaluation						RE (-)		Service Information Letter	
	72 ENG2					Mos					
	Eff: 03-Jun-1998					Hrs					
						Enc					

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-044 R1		Material Returned to PWC						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 16-Oct-2017										
SIL-GEN-044 R1		Material Returned to PWC						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 16-Oct-2017										
SIL-GEN-044 Rev 2		Material Returned to PWC						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 03-Aug-2023										
SIL-GEN-044 Rev 2		Material Returned to PWC						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 03-Aug-2023										
SIL-GEN-049		Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code						RE (-)		Service Information Letter	
	72 ENG1										
SIL-GEN-049		Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code						RE (-)		Service Information Letter	
	72 ENG2										
SIL-GEN-049 R1		Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 02-Nov-2012										
SIL-GEN-049 R1		Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 02-Nov-2012										
SIL-GEN-049 R2		Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 13-Sep-2019										
SIL-GEN-049 R2		Warranty Coverage Minimum Service Bulletin Lists and Service Bulletin (SB) Compliance Code						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 13-Sep-2019										
SIL-GEN-055		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
	72 ENG1										
SIL-GEN-055		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
	72 ENG2										
SIL-GEN-055 R1		Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
	72 ENG1										

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
 SIL-GEN-055 R1 72 ENG2	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
 SIL-GEN-055 R10 72 ENG1 Eff: 13-Nov-2018	Guidelines and Standards for Subscribing and Utilizing the Internet-Based Engine Condition Trend Monitoring EHM Services						T (A/R)		Service Information Letter	
 SIL-GEN-055 R10 72 ENG2 Eff: 13-Nov-2018	Guidelines and Standards for Subscribing and Utilizing the Internet-Based Engine Condition Trend Monitoring EHM Services						T (A/R)		Service Information Letter	
 SIL-GEN-055 R2 72 ENG1	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
 SIL-GEN-055 R2 72 ENG2	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
 SIL-GEN-055 R3 72 ENG1	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
 SIL-GEN-055 R3 72 ENG2	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
 SIL-GEN-055 R4 72 ENG1	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
 SIL-GEN-055 R4 72 ENG2	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
 SIL-GEN-055 R5 72 ENG1	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
 SIL-GEN-055 R5 72 ENG2	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
 SIL-GEN-055 R6 72 ENG1	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	
 SIL-GEN-055 R6 72 ENG2	Guidelines And Standards For Subscribing And Utilizing The Internet-Based Engine Condition Trend Mon						RE (-)		Service Information Letter	

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-055 R8		Guidelines and Standards for Subscribing and Utilizing the Internet-based Engine Condition Trend Monitoring EHM Services						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 06-Nov-2018										
SIL-GEN-055 R8		Guidelines and Standards for Subscribing and Utilizing the Internet-based Engine Condition Trend Monitoring EHM Services						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 06-Nov-2018										
SIL-GEN-055 R9		Guidelines and Standards for Subscribing and Utilizing the Internet-based Engine Condition Trend Monitoring EHM Services						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 08-Nov-2018										
SIL-GEN-055 R9		Guidelines and Standards for Subscribing and Utilizing the Internet-based Engine Condition Trend Monitoring EHM Services						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 08-Nov-2018										
SIL-GEN-061		Engine Related Requests						RE (-)		Service Information Letter	
	72 ENG1										
SIL-GEN-061		Engine Related Requests						RE (-)		Service Information Letter	
	72 ENG2										
SIL-GEN-061 Rev 1		Engine Related Requests						RE (-)		Service Information Letter	
	72 ENG1										
SIL-GEN-061 Rev 1		Engine Related Requests						RE (-)		Service Information Letter	
	72 ENG2										
SIL-GEN-061 Rev 10		Engine Related Requests						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 25-Jan-2021										
SIL-GEN-061 Rev 10		Engine Related Requests						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 25-Jan-2021										
SIL-GEN-061 Rev 11		Engine Related Requests						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 19-Mar-2024										
SIL-GEN-061 Rev 11		Engine Related Requests						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 19-Mar-2024										
SIL-GEN-061 Rev 2		Engine Related Requests						RE (-)		Service Information Letter	
	72 ENG1										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-061 Rev 2  72 ENG2		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 3  72 ENG1		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 3  72 ENG2		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 4  72 ENG1		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 4  72 ENG2		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 5  72 ENG1		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 5  72 ENG2		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 6  72 ENG1		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 6  72 ENG2		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 7  72 ENG1		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 7  72 ENG2		Engine Related Requests						RE (-)		Service Information Letter	
SIL-GEN-061 Rev 8  72 ENG1 Eff: 10-Apr-2018		Engine Related Requests						T (-)		Service Information Letter	
SIL-GEN-061 Rev 8  72 ENG2 Eff: 10-Apr-2018		Engine Related Requests						T (-)		Service Information Letter	

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-061 Rev 9		Engine Related Requests								T (-)	Service Information Letter
	72 ENG1										
	Eff: 21-Mar-2019										
SIL-GEN-061 Rev 9		Engine Related Requests								T (-)	Service Information Letter
	72 ENG2										
	Eff: 21-Mar-2019										
SIL-GEN-065 Rev 1		Information Required to Process New Engine Accessory Warranty Claims								T (-)	Service Information Letter
	72 ENG1										
	Eff: 29-Jun-2023										
SIL-GEN-065 Rev 1		Information Required to Process New Engine Accessory Warranty Claims								T (-)	Service Information Letter
	72 ENG2										
	Eff: 29-Jun-2023										
SIL-GEN-065 Rev 2		Information Required to Process New Engine Accessory Warranty Claims								T (A/R)	Service Information Letter
	72 ENG1										
	Eff: 13-Mar-2024										
SIL-GEN-065 Rev 2		Information Required to Process New Engine Accessory Warranty Claims								T (A/R)	Service Information Letter
	72 ENG2										
	Eff: 13-Mar-2024										
SIL-GEN-093		Engine Preservation and Storage								RE (-)	Informational
	72 ENG1										
	Eff: 20-Mar-2009										
SIL-GEN-093		Engine Preservation and Storage								RE (-)	Informational
	72 ENG2										
	Eff: 20-Mar-2009										
SIL-GEN-093 R1		Engine Preservation and Storage								T (-)	Informational
	72 ENG1										
	Eff: 14-Apr-2016										
SIL-GEN-093 R1		Engine Preservation and Storage								T (-)	Informational
	72 ENG2										
	Eff: 14-Apr-2016										
SIL-GEN-093 R2		Engine Preservation and Storage								T (A/R)	Service Information Letter
	72 ENG1										
	Eff: 22-Oct-2021										
SIL-GEN-093 R2		Engine Preservation and Storage								T (A/R)	Service Information Letter
	72 ENG2										
	Eff: 22-Oct-2021										
SIL-GEN-110		Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)								RE (-)	Service Information Letter
	72 ENG1										

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-GEN-110  72 ENG2	Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						RE (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-110 Rev 1  72 ENG1	Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						RE (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-110 Rev 1  72 ENG2	Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						RE (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-110 Rev 3  72 ENG1 Eff: 19-Dec-2018	Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						T (A/R)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-110 Rev 3  72 ENG2 Eff: 19-Dec-2018	Pratt & Whitney Canada Corp. (P&WC) Customer Training Collaborative Agreement with FlightSafety International (FSI)						T (A/R)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-117 Rev 1  72 ENG1 Eff: 14-Apr-2023	Warranty Allowance for Consumable Materials and Miscellaneous Parts Used During Engine Line Maintenance Work in the Field						T (A/R)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-117 Rev 1  72 ENG2 Eff: 14-Apr-2023	Warranty Allowance for Consumable Materials and Miscellaneous Parts Used During Engine Line Maintenance Work in the Field						T (A/R)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-121 Rev 1  72 ENG1 Eff: 13-Apr-2023	Mobile Repair Team Travel Allowance Instructions for Warranty or ESP Program Coverage						T (A/R)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-121 Rev 1  72 ENG2 Eff: 13-Apr-2023	Mobile Repair Team Travel Allowance Instructions for Warranty or ESP Program Coverage						T (A/R)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-122  72 ENG1	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-122  72 ENG2	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-122 R1  72 ENG1	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-122 R1  72 ENG2	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
										Mos
										Hrs
										Enc

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-122 R10	72 ENG1	Recovery Fee for Maintenance Deviation Letters						RE (-)		Service Information Letter	
SIL-GEN-122 R10	72 ENG2	Recovery Fee for Maintenance Deviation Letters						RE (-)		Service Information Letter	
SIL-GEN-122 R11	72 ENG1 Eff: 29-Jun-2022	Recovery Fee for Maintenance Deviation Letters						T (A/R)		Service Information Letter	
SIL-GEN-122 R11	72 ENG2 Eff: 29-Jun-2022	Recovery Fee for Maintenance Deviation Letters						T (A/R)		Service Information Letter	
SIL-GEN-122 R2	72 ENG1	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
SIL-GEN-122 R2	72 ENG2	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
SIL-GEN-122 R3	72 ENG1	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
SIL-GEN-122 R3	72 ENG2	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
SIL-GEN-122 R4	72 ENG1	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
SIL-GEN-122 R4	72 ENG2	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
SIL-GEN-122 R5	72 ENG1	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
SIL-GEN-122 R5	72 ENG2	Recovery Fee For Maintenance Deviation Letters						RE (-)		Service Information Letter	
SIL-GEN-122 R6	72 ENG1 Eff: 29-Dec-2017	Recovery Fee For Maintenance Deviation Letters						T (-)		Service Information Letter	

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-GEN-122 R6  72 ENG2 Eff: 29-Dec-2017	Recovery Fee For Maintenance Deviation Letters								T (-) Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-122 R7  72 ENG1 Eff: 19-Dec-2018	Recovery Fee For Maintenance Deviation Letters								T (-) Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-122 R7  72 ENG2 Eff: 19-Dec-2018	Recovery Fee For Maintenance Deviation Letters								T (-) Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-122 R8  72 ENG1 Eff: 20-Dec-2019	Recovery Fee for Maintenance Deviation Letters								T (-) Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-122 R8  72 ENG2 Eff: 20-Dec-2019	Recovery Fee for Maintenance Deviation Letters								T (-) Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-122 R9  72 ENG1 Eff: 18-Dec-2020	Recovery Fee for Maintenance Deviation Letters								T (-) Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-122 R9  72 ENG2 Eff: 18-Dec-2020	Recovery Fee for Maintenance Deviation Letters								T (-) Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-123  72 ENG1 Eff: 21-Jan-2013	Qualified Engine Oil Analysis Laboratory List								RE (-) Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-123  72 ENG2 Eff: 21-Jan-2013	Qualified Engine Oil Analysis Laboratory List								RE (-) Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-123 R1  72 ENG1	Qualified Engine Oil Analysis Laboratory List								RE (-) Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-123 R1  72 ENG2	Qualified Engine Oil Analysis Laboratory List								RE (-) Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-123 R2  72 ENG1	Qualified Engine Oil Analysis Laboratory List								RE (-) Service Information Letter	
										Mos
										Hrs
										Enc
SIL-GEN-123 R2  72 ENG2	Qualified Engine Oil Analysis Laboratory List								RE (-) Service Information Letter	
										Mos
										Hrs
										Enc

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-123 R3	72 ENG1	Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-123 R3	72 ENG2	Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-123 R4	72 ENG1	Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-123 R4	72 ENG2	Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-123 R5	72 ENG1	Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-123 R5	72 ENG2	Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-123 R6	72 ENG1	Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-123 R6	72 ENG2	Qualified Engine Oil Analysis Laboratory List						RE (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-123 R7	72 ENG1 Eff: 10-Jul-2018	Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-123 R7	72 ENG2 Eff: 10-Jul-2018	Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-123 Rev 10	72 ENG1 Eff: 13-Mar-2023	Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-123 Rev 10	72 ENG2 Eff: 13-Mar-2023	Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	
						Mos					
						Hrs					
SIL-GEN-123 Rev 11	72 ENG1 Eff: 12-Sep-2023	Qualified Engine Oil Analysis Laboratory List						T (-)		Service Information Letter	
						Mos					
						Hrs					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-GEN-123 Rev 11  72 ENG2 Eff: 12-Sep-2023	Qualified Engine Oil Analysis Laboratory List								T (-)	Service Information Letter
SIL-GEN-123 Rev 12  72 ENG1 Eff: 04-Dec-2023	Qualified Engine Oil Analysis Laboratory List								T (A/R)	Service Information Letter
SIL-GEN-123 Rev 12  72 ENG2 Eff: 04-Dec-2023	Qualified Engine Oil Analysis Laboratory List								T (A/R)	Service Information Letter
SIL-GEN-123 Rev 8  72 ENG1 Eff: 25-Jul-2018	Qualified Engine Oil Analysis Laboratory List								T (-)	Service Information Letter
SIL-GEN-123 Rev 8  72 ENG2 Eff: 25-Jul-2018	Qualified Engine Oil Analysis Laboratory List								T (-)	Service Information Letter
SIL-GEN-123 Rev 9  72 ENG1 Eff: 14-Jul-2022	Qualified Engine Oil Analysis Laboratory List								T (-)	Service Information Letter
SIL-GEN-123 Rev 9  72 ENG2 Eff: 14-Jul-2022	Qualified Engine Oil Analysis Laboratory List								T (-)	Service Information Letter
SIL-GEN-128 Rev 1  72 ENG1 Eff: 15-Jul-2013	Limited Time Offer for P&WC Engine Diagnostic System for Applicable P&WC Turbofan Powered Aircraft								T (A/R)	Service Information Letter
SIL-GEN-128 Rev 1  72 ENG2 Eff: 15-Jul-2013	Limited Time Offer for P&WC Engine Diagnostic System for Applicable P&WC Turbofan Powered Aircraft								T (A/R)	Service Information Letter
SIL-GEN-135  72 ENG1 Eff: 21-Feb-2017 Note: APPLICABILITY: All P&WC engines.	Aviation Accidents / Incidents - Return to Service of Affected P&WC Products and the Effect on Engine Warranty and Service Policies Status (This Service Information Letter (SIL) supersedes SIL GEN-039)								T (-)	Service Information Letter
SIL-GEN-135  72 ENG2 Eff: 21-Feb-2017 Note: APPLICABILITY: All P&WC engines.	Aviation Accidents / Incidents - Return to Service of Affected P&WC Products and the Effect on Engine Warranty and Service Policies Status (This Service Information Letter (SIL) supersedes SIL GEN-039)								T (-)	Service Information Letter
SIL-GEN-135 Rev 1  72 ENG1 Eff: 03-Jun-2021	Aviation Accidents / Incidents - Return to Service of Affected P&WC Products and the Effect on Engine Warranty and Service Policies Status								T (A/R)	Service Information Letter

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-135 Rev 1		Aviation Accidents / Incidents - Return to Service of Affected P&WC Products and the Effect on Engine Warranty and Service Policies Status						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 03-Jun-2021										
SIL-GEN-143		P&WC'S Oil Analysis Technology Trial Program						RE (-)		Service Information Letter	
	72 ENG1										
	Eff: 18-Aug-2016										
SIL-GEN-143		P&WC'S Oil Analysis Technology Trial Program						RE (-)		Service Information Letter	
	72 ENG2										
	Eff: 18-Aug-2016										
SIL-GEN-143 R1		P&WC'S Oil Analysis Technology Trial Program						RE (-)		Service Information Letter	
	72 ENG1										
SIL-GEN-143 R1		P&WC'S Oil Analysis Technology Trial Program						RE (-)		Service Information Letter	
	72 ENG2										
SIL-GEN-143 R2		P&WC'S Oil Analysis Technology Trial Program						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 09-Jul-2018										
SIL-GEN-143 R2		P&WC'S Oil Analysis Technology Trial Program						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 09-Jul-2018										
SIL-GEN-153		P&WC's Oil Analysis Technology Program Logistics Information						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 17-Jul-2018										
SIL-GEN-153		P&WC's Oil Analysis Technology Program Logistics Information						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 17-Jul-2018										
SIL-GEN-153 Rev 1		P&WC's Oil Analysis Technology Program Logistics Information						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 10-Mar-2019										
SIL-GEN-153 Rev 1		P&WC's Oil Analysis Technology Program Logistics Information						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 10-Mar-2019										
SIL-GEN-153 Rev 10		P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 31-Oct-2022										
SIL-GEN-153 Rev 10		P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 31-Oct-2022										

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-153 Rev 11	72 ENG1 Eff: 22-Dec-2022	P&WC's Oil Analysis Technology Service Logistics Information								T (-)	Service Information Letter
SIL-GEN-153 Rev 11	72 ENG2 Eff: 22-Dec-2022	P&WC's Oil Analysis Technology Service Logistics Information								T (-)	Service Information Letter
SIL-GEN-153 Rev 12	72 ENG1 Eff: 23-Jan-2024	P&WC's Oil Analysis Technology Service Logistics Information								T (A/R)	Service Information Letter
SIL-GEN-153 Rev 12	72 ENG2 Eff: 23-Jan-2024	P&WC's Oil Analysis Technology Service Logistics Information								T (A/R)	Service Information Letter
SIL-GEN-153 Rev 2	72 ENG1 Eff: 20-Jun-2019	P&WC's Oil Analysis Technology Service Logistics Information								T (-)	Service Information Letter
SIL-GEN-153 Rev 2	72 ENG2 Eff: 20-Jun-2019	P&WC's Oil Analysis Technology Service Logistics Information								T (-)	Service Information Letter
SIL-GEN-153 Rev 3	72 ENG1 Eff: 26-Sep-2019	P&WC's Oil Analysis Technology Service Logistics Information								T (-)	Service Information Letter
SIL-GEN-153 Rev 3	72 ENG2 Eff: 26-Sep-2019	P&WC's Oil Analysis Technology Service Logistics Information								T (-)	Service Information Letter
SIL-GEN-153 Rev 4	72 ENG1 Eff: 05-May-2020	P&WC's Oil Analysis Technology Service Logistics Information								T (-)	Service Information Letter
SIL-GEN-153 Rev 4	72 ENG2 Eff: 05-May-2020	P&WC's Oil Analysis Technology Service Logistics Information								T (-)	Service Information Letter
SIL-GEN-153 Rev 5	72 ENG1 Eff: 28-Sep-2020	P&WC's Oil Analysis Technology Service Logistics Information								T (-)	Service Information Letter
SIL-GEN-153 Rev 5	72 ENG2 Eff: 28-Sep-2020	P&WC's Oil Analysis Technology Service Logistics Information								T (-)	Service Information Letter
SIL-GEN-153 Rev 6	72 ENG1 Eff: 30-Oct-2020	P&WC's Oil Analysis Technology Service Logistics Information								T (-)	Service Information Letter

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-153 Rev 6		P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 30-Oct-2020										
SIL-GEN-153 Rev 7		P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 05-Jan-2021										
SIL-GEN-153 Rev 7		P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 05-Jan-2021										
SIL-GEN-153 Rev 8		P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 15-Sep-2021										
SIL-GEN-153 Rev 8		P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 15-Sep-2021										
SIL-GEN-153 Rev 9		P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 18-Jan-2022										
SIL-GEN-153 Rev 9		P&WC's Oil Analysis Technology Service Logistics Information						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 18-Jan-2022										
SIL-GEN-155		Introduction of Hyperlinks in P&WC Service Bulletins						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 14-Jun-2019										
SIL-GEN-155		Introduction of Hyperlinks in P&WC Service Bulletins						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 14-Jun-2019										
SIL-GEN-156 R1		DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation						T (-)		Service Information Letter	
	72 ENG1										
	Eff: 02-Apr-2020										
SIL-GEN-156 R1		DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation						T (-)		Service Information Letter	
	72 ENG2										
	Eff: 02-Apr-2020										
SIL-GEN-156 R2		DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 07-Apr-2020										
SIL-GEN-156 R2		DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 07-Apr-2020										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-157		Preservation - Engines Removed from Service on Temporary Basis						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 18-Mar-2020										
SIL-GEN-157		Preservation - Engines Removed from Service on Temporary Basis						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 18-Mar-2020										
SIL-GEN-158		Handling of Suspected Hexavalent Chromium Residue on Engine Parts During Maintenance, Repair and Overhaul						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 20-Jul-2020										
SIL-GEN-158		Handling of Suspected Hexavalent Chromium Residue on Engine Parts During Maintenance, Repair and Overhaul						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 20-Jul-2020										
SIL-GEN-159		Environmentally Assisted Cracking in Certain Aluminium Alloys						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 08-Jul-2020										
SIL-GEN-159		Environmentally Assisted Cracking in Certain Aluminium Alloys						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 08-Jul-2020										
SIL-GEN-160		Occasional Dust Plume Exposure						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 30-Jun-2020										
SIL-GEN-160		Occasional Dust Plume Exposure						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 30-Jun-2020										
SIL-GEN-161		Operations in Environments Affected by Wildfires, Bushfires and Forest Fires						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 19-Oct-2020										
SIL-GEN-161		Operations in Environments Affected by Wildfires, Bushfires and Forest Fires						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 19-Oct-2020										
SIL-GEN-166		Critical Component Accumulated Cycle Counting						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 23-Jun-2021										
SIL-GEN-166		Critical Component Accumulated Cycle Counting						T (A/R)		Service Information Letter	
	72 ENG2										
	Eff: 23-Jun-2021										
SIL-GEN-168		Reminder Regarding Scheduled Maintenance Tasks at Engine Shop Visits						T (A/R)		Service Information Letter	
	72 ENG1										
	Eff: 23-Sep-2022										

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-168	Reminder Regarding Scheduled Maintenance Tasks at Engine Shop Visits						T (A/R)		Service Information Letter	
 72 ENG2										
Eff: 23-Sep-2022										
SIL-GEN-169	PWC Generation 3 Recorder End of New Production						T (A/R)		Service Information Letter	
 72 ENG1										
Eff: 27-Mar-2023										
SIL-GEN-169	PWC Generation 3 Recorder End of New Production						T (A/R)		Service Information Letter	
 72 ENG2										
Eff: 27-Mar-2023										
SIL-PW200-004	New Engine Serial Numbering Methodology						RE (-)		Service Information Letter	
 72 ENG1										
Eff: 20-Jun-1996										
SIL-PW200-004	New Engine Serial Numbering Methodology						RE (-)		Service Information Letter	
 72 ENG2										
Eff: 20-Jun-1996										
SIL-PW200-004 R1	New Engine Serial Numbering Methodology						RE (-)		Service Information Letter	
 72 ENG1										
Eff: 23-Sep-1998										
SIL-PW200-004 R1	New Engine Serial Numbering Methodology						RE (-)		Service Information Letter	
 72 ENG2										
Eff: 23-Sep-1998										
SIL-PW200-004 R2	New Engine Serial Numbering Methodology						T (A/R)		Service Information Letter	
 72 ENG1										
Eff: 12-Mar-2004										
SIL-PW200-004 R2	New Engine Serial Numbering Methodology						T (A/R)		Service Information Letter	
 72 ENG2										
Eff: 12-Mar-2004										
SIL-PW300-007	New Engine Serial Numbering Methodology						RE (-)		Service Information Letter	
 72 ENG1										
Eff: 20-Jun-1996										
SIL-PW300-007	New Engine Serial Numbering Methodology						RE (-)		Service Information Letter	
 72 ENG2										
Eff: 20-Jun-1996										
SIL-PW300-007 Rev 1	New Engine Serial Numbering Methodology						T (A/R)		Service Information Letter	
 72 ENG1										
Eff: 23-Sep-1998										
SIL-PW300-007 Rev 1	New Engine Serial Numbering Methodology						T (A/R)		Service Information Letter	
 72 ENG2										
Eff: 23-Sep-1998										

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-PW500-022  72 ENG1 Eff: 01-Jan-2006	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)						RE (-)		Service Information Letter	
					Mos					
					Hrs					
					Enc					
SIL-PW500-022  72 ENG2 Eff: 01-Jan-2006	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)						RE (-)		Service Information Letter	
					Mos					
					Hrs					
					Enc					
SIL-PW500-022 Rev 1  72 ENG1	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)						RE (-)		Service Information Letter	
					Mos					
					Hrs					
					Enc					
SIL-PW500-022 Rev 1  72 ENG2	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)						RE (-)		Service Information Letter	
					Mos					
					Hrs					
					Enc					
SIL-PW500-022 Rev 2  72 ENG1	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)						RE (-)		Service Information Letter	
					Mos					
					Hrs					
					Enc					
SIL-PW500-022 Rev 2  72 ENG2	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)						RE (-)		Service Information Letter	
					Mos					
					Hrs					
					Enc					
SIL-PW500-022 Rev 3  72 ENG1 Eff: 13-Sep-2019	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)						T (A/R)		Service Information Letter	
					Mos					
					Hrs					
					Enc					
SIL-PW500-022 Rev 3  72 ENG2 Eff: 13-Sep-2019	Extended Engine Service Policy (EESP) Limited Cost Overhaul (LCO)						T (A/R)		Service Information Letter	
					Mos					
					Hrs					
					Enc					
SIL-PW500-067  72 ENG1 Eff: 28-Feb-2017	High Compressor Rotor 2nd Stage						T (A/R)		Service Information Letter	
					Mos					
					Hrs					
					Enc					
SIL-PW500-067  72 ENG2 Eff: 28-Feb-2017	High Compressor Rotor 2nd Stage						T (A/R)		Service Information Letter	
					Mos					
					Hrs					
					Enc					
SIL-PW500-069  72 ENG1 Eff: 20-Jun-2017	Electronic Engine Control (EEC) Service Bulletin 30478						T (A/R)		Service Information Letter	
					Mos					
					Hrs					
					Enc					
Note: Note: CSPN 1006723R08 will close on 31 December 2017, operators are advised that P&WC does not plan to extend the program beyond this date.										
SIL-PW500-069  72 ENG2 Eff: 20-Jun-2017	Electronic Engine Control (EEC) Service Bulletin 30478						T (A/R)		Service Information Letter	
					Mos					
					Hrs					
					Enc					
Note: Note: CSPN 1006723R08 will close on 31 December 2017, operators are advised that P&WC does not plan to extend the program beyond this date.										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SIL-PW500-071  72 ENG1 Eff: 21-Nov-2017	Electronic Data Analysis Service for Engine DCU Downloads						T (A/R)		Service Information Letter	
SIL-PW500-071  72 ENG2 Eff: 21-Nov-2017	Electronic Data Analysis Service for Engine DCU Downloads						T (A/R)		Service Information Letter	
SIL-PW500-072  72 ENG1 Eff: 02-Oct-2018	ACES Viper II Analyzer Introduction						T (A/R)		Service Information Letter	
SIL-PW500-072  72 ENG2 Eff: 02-Oct-2018	ACES Viper II Analyzer Introduction						T (A/R)		Service Information Letter	
SIL-PW500-073  72 ENG1 Eff: 01-Aug-2019	Oil Analysis Technology Solution Now available						T (-)		Service Information Letter	
SIL-PW500-073  72 ENG2 Eff: 01-Aug-2019	Oil Analysis Technology Solution Now available						T (-)		Service Information Letter	
SIL-PW500-073 Rev 1  72 ENG1 Eff: 04-Oct-2019	Oil Analysis Technology Solution Now Available						T (-)		Service Information Letter	
SIL-PW500-073 Rev 1  72 ENG2 Eff: 04-Oct-2019	Oil Analysis Technology Solution Now Available						T (-)		Service Information Letter	
SIL-PW500-073 Rev 2  72 ENG1 Eff: 08-Jan-2020	P&WC's Oil Analysis Technology Solution Now Available						T (-)		Service Information Letter	
SIL-PW500-073 Rev 2  72 ENG2 Eff: 08-Jan-2020	P&WC's Oil Analysis Technology Solution Now Available						T (-)		Service Information Letter	
SIL-PW500-073 Rev 3  72 ENG1 Eff: 05-Jan-2021	P&WC's Oil Analysis Technology Solution Now Available						T (A/R)		Service Information Letter	
SIL-PW500-073 Rev 3  72 ENG2 Eff: 05-Jan-2021	P&WC's Oil Analysis Technology Solution Now Available						T (A/R)		Service Information Letter	
SIL-PW500-075  72 ENG1 Eff: 14-Dec-2021	BOV Servo Valve - New Revision to PW500 Maintenance Manuals, Section 05-20-00 Scheduled Maintenance Check - Engine Accessories at Engine Overhaul						T (A/R)		Service Information Letter	

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	SIL-PW500-075		BOV Servo Valve - New Revision to PW500 Maintenance Manuals, Section 05-20-00 Scheduled Maintenance Check - Engine Accessories at Engine Overhaul						T (A/R)	Service Information Letter	
	72 ENG2					Mos					
	Eff: 14-Dec-2021					Hrs					
						Enc					
	SIL-PW500-078		Low Pressure Shaft Balancing Assembly - New revision to PW500 Maintenance Manuals, section 05-20-00 Scheduled Maintenance Check - Periodic Inspections						T (A/R)	Service Information Letter	
	72 ENG1					Mos					
	Eff: 04-Dec-2023					Hrs					
						Enc					
	SIL-PW500-078		Low Pressure Shaft Balancing Assembly - New revision to PW500 Maintenance Manuals, section 05-20-00 Scheduled Maintenance Check - Periodic Inspections						T (A/R)	Service Information Letter	
	72 ENG2					Mos					
	Eff: 04-Dec-2023					Hrs					
						Enc					
	SL560XL-72-04		Engine - Transmittal Of Pratt & Whitney Canada Service Bulletin PW500-72-30110R1, Turbofan Engine - Oil Level Indicator - Replacement Of						RE (-)	Recommended	
	72 A/F					Mos	22-Jun-2022				
	Eff: 15-Mar-2001 Not Applicable	effective before manufacture				Hrs	8				
						Ldg	6				
	SL560XL-72-05		Engine - Transmittal Of Pratt & Whitney Canada Service Bulletin PW500-72-30135R1, Turbofan Engine - Oil Filler Cap - Replacement Of						RE (-)	Recommended	
	72 A/F					Mos	22-Jun-2022				
	Eff: 15-Mar-2001 Not Applicable	effective before manufacture				Hrs	8				
						Ldg	6				
	SL560XL-72-07		Engine - Transmittal of Pratt & Whitney Canada (PW&C) Service Bulletins PW500-72-30193 and PW500-72-30193, Turbofan Engine Oil Leaks From No. 4 Bearing Pressure and Scavenge Transfer Tubes.						T (A/R)	Informational	
	72 A/F					Mos					
	Eff: 17-Dec-2001					Hrs					
						Ldg					
	SL560XL-72-08		Engine - Transmittal of Pratt & Whitney Canada (P&WC) Service Bulletin PW500-72-30203, Replacement of Alternator Shaft Plain Seal						RE (-)	Recommended	
	72 A/F					Mos	22-Jun-2022				
	Eff: 01-May-2002 Not Applicable	effective before manufacture				Hrs	8				
						Ldg	6				
	SL560XL-72-09		Engine - Transmittal of Pratt & Whitney Canada Service Bulletin PW500-72-30217, Turbofan Engine Fuel Tube - Inspection Of						RE (-)	Recommended	
	72 A/F					Mos	22-Jun-2022				
	Eff: 03-Jun-2002 Not Applicable	effective before manufacture				Hrs	8				
						Ldg	6				
	SL560XL-72-10		Transmittal of Pratt & Whitney Canada (P&WC) Service Information Letter PW500-015, PW545A Fan Case Extension Cracking						T (A/R)	Informational	
	72 A/F					Mos					
	Eff: 11-Aug-2003					Hrs					
						Ldg					
	SL560XL-72-11		Transmittal of Pratt & Whitney Canada Service Bulletin PW500-72-30252 Number Four Bearing Oil Pressure and Oil Scavenge Tubes - Replacement Of						RE (-)	Optional	
	72 A/F					Mos					
						Hrs					
						Ldg					
	SL560XL-72-11 Rev 01		Transmittal of Pratt & Whitney Canada Service Bulletin PW500-72-30252 Number Four Bearing Oil Pressure and Oil Scavenge Tubes - Replacement Of						RE (-)	Recommended	
	72 A/F					Mos	22-Jun-2022				
	Eff: 27-Nov-2007 Not Applicable	effective before manufacture				Hrs	8				
						Ldg	6				

Note: Cancelled - superseded by SL560XL-72-14

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
▼ 73 - ENGINE - FUEL AND CONTROL											
⚙	73 A/F 9-231-28 L10532	Fuel Flow Transmitter Left								RE (O/C)	
						Mos	22-Jun-2022				
						Hrs	0				
⚙	73 A/F 9-231-28 L10528	Fuel Flow Transmitter Right								RE (O/C)	
						Mos	22-Jun-2022				
						Hrs	0				
⚙	73 ENG1 30J2313-02 DEAAB70793	Fuel Nozzle Assembly No.1								RE (O/C)	
						Mos	30-Dec-2021				
						Hrs	0				
⚙	73 ENG2 30J2313-02 DEAA71607	Fuel Nozzle Assembly No.1 New								RE (O/C)	
						Mos	31-Dec-2021				
						Hrs	0				
⚙	73 ENG1 30J2313-02 DEAAB71613	Fuel Nozzle Assembly No.10								RE (O/C)	
						Mos	30-Dec-2021				
						Hrs	0				
⚙	73 ENG2 30J2313-02 DEAAB71931	Fuel Nozzle Assembly No.10 New								RE (O/C)	
						Mos	31-Dec-2021				
						Hrs	0				
⚙	73 ENG1 30J2313-02 DEAAB71614	Fuel Nozzle Assembly No.11								RE (O/C)	
						Mos	30-Dec-2021				
						Hrs	0				
⚙	73 ENG2 30J2313-02 DEAAB71932	Fuel Nozzle Assembly No.11 New								RE (O/C)	
						Mos	31-Dec-2021				
						Hrs	0				
⚙	73 ENG1 30J2313-02 DEAAB70796	Fuel Nozzle Assembly No.2								RE (O/C)	
						Mos	30-Dec-2021				
						Hrs	0				
⚙	73 ENG2 30J2313-02 DEAA71609	Fuel Nozzle Assembly No.2 New								RE (O/C)	
						Mos	31-Dec-2021				
						Hrs	0				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
73 ENG1 30J2313-02 DEAAB70799		Fuel Nozzle Assembly No.3								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
73 ENG2 30J2313-02 DEAA71611		Fuel Nozzle Assembly No.3 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
73 ENG1 30J2313-02 DEAAB70800		Fuel Nozzle Assembly No.4								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
73 ENG2 30J2313-02 DEAA71616		Fuel Nozzle Assembly No.4 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
73 ENG1 30J2313-02 DEAAB70801		Fuel Nozzle Assembly No.5								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
73 ENG2 30J2313-02 DEAA71617		Fuel Nozzle Assembly No.5 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
73 ENG1 30J2313-02 DEAAB71331		Fuel Nozzle Assembly No.6								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
73 ENG2 30J2313-02 DEAA71618		Fuel Nozzle Assembly No.6 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
73 ENG1 30J2313-02 DEAAB71344		Fuel Nozzle Assembly No.7								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			
73 ENG2 30J2313-02 DEAA71926		Fuel Nozzle Assembly No.7 New								RE (O/C)	
							Mos	31-Dec-2021			
							Hrs	0			
73 ENG1 30J2313-02 DEAAB71345		Fuel Nozzle Assembly No.8								RE (O/C)	
							Mos	30-Dec-2021			
							Hrs	0			

Task No		Description								Categories	Time					
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining					
	73 ENG2	Fuel Nozzle Assembly								RE (O/C)						
	30J2313-02	No.8					Mos	31-Dec-2021								
	DEAA71927	New					Hrs	0								
								Enc	0							
	73 ENG1	Fuel Nozzle Assembly								RE (O/C)						
	30J2313-02	No.9					Mos	30-Dec-2021								
	DEAAB71610						Hrs	0								
								Enc	0							
	73 ENG2	Fuel Nozzle Assembly								RE (O/C)						
	30J2313-02	No.9					Mos	31-Dec-2021								
	DEAA71930	New					Hrs	0								
								Enc	0							
	73 A/F	Fuel Pressure Switch								RE (O/C)						
	9914112-3	Left					Mos	15-Apr-2023								
	3701	New	0				Hrs	402:30								
								Ldg	276							
	73 A/F	Fuel Pressure Switch								RE (O/C)						
	6057-3	Right					Mos	22-Jun-2022								
	3892						Hrs	0								
								Ldg	0							
	73 ENG1	Hydromechanical Fuel Control								RE (O/C)						
	30J3050-03	New					Mos	30-Dec-2021								
	F86818						Hrs	0								
								Enc	0							
	73 ENG2	Hydromechanical Fuel Control								RE (O/C)						
	30J3050-03	New					Mos	31-Dec-2021								
	F86850						Hrs	0								
								Enc	0							
30405		Fuel Nozzle Manifold - Replacement								RE (-)	Category 6					
	73 ENG1						Mos	30-Dec-2021								
	Complied With								Hrs							
								Enc								
30405		Fuel Nozzle Manifold - Replacement								RE (-)	Category 6					
	73 ENG2						Mos	31-Dec-2021								
	Complied With								Hrs							
								Enc								
30405 Rev 1		Fuel Nozzle Manifold - Replacement								RE (-)	Category 6					
	73 ENG1						Mos	30-Dec-2021								
	Complied With								Hrs							
								Enc								
30405 Rev 1		Fuel Nozzle Manifold - Replacement								RE (-)	Category 6					
	73 ENG2						Mos	31-Dec-2021								
	Complied With								Hrs							
								Enc								

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30405 Rev 2	Fuel Nozzle Manifold - Replacement								RE (-)	Category 6
 73 ENG1						Mos	30-Dec-2021			
Complied With						Hrs				
						Enc				
30405 Rev 2	Fuel Nozzle Manifold - Replacement								RE (-)	Category 6
 73 ENG2						Mos	31-Dec-2021			
Complied With						Hrs				
						Enc				
30405 Rev 3	Fuel Nozzle Manifold - Replacement								RE (-)	Category 6
 73 ENG1						Mos	30-Dec-2021			
Eff: 20-Jul-2012 Complied With						Hrs				
						Enc				
30405 Rev 3	Fuel Nozzle Manifold - Replacement								RE (-)	Category 6
 73 ENG2						Mos	31-Dec-2021			
Eff: 20-Jul-2012 Complied With						Hrs				
						Enc				
30405 Rev 4	Fuel Nozzle Manifold - Replacement								RE (-)	Category 6
 73 ENG1						Mos	30-Dec-2021			
Eff: 14-Mar-2018 Complied With						Hrs				
						Enc				
30405 Rev 4	Fuel Nozzle Manifold - Replacement								RE (-)	Category 6
 73 ENG2						Mos	31-Dec-2021			
Eff: 14-Mar-2018 Complied With						Hrs				
						Enc				
30418 Rev 2	Replacement/ Modification of Electrical Wiring Harness (TT0 Sensor)								RE (-)	Category 6
 73 ENG1						Mos	30-Dec-2021			
Eff: 12-May-2016 Complied With						Hrs				
(AVG MAN HRS: 2.5)						Enc				
30418 Rev 2	Replacement/ Modification of Electrical Wiring Harness (TT0 Sensor)								RE (-)	Category 6
 73 ENG2						Mos	31-Dec-2021			
Eff: 12-May-2016 Complied With						Hrs				
(AVG MAN HRS: 2.5)						Enc				
30465 Rev 2	Replacement of Fuel Manifold Tubes								RE (-)	Category 7
 73 ENG1						Mos	30-Dec-2021			
Eff: 08-Jul-2016 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30465 Rev 2	Replacement of Fuel Manifold Tubes								RE (-)	Category 7
 73 ENG2						Mos	31-Dec-2021			
Eff: 08-Jul-2016 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30474 Rev 2	Replacement/ Modification of Electrical Wiring Harness								RE (-)	Category 7
 73 ENG1						Mos	30-Dec-2021			
Eff: 12-May-2016 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30474 Rev 2	Replacement/ Modification of Electrical Wiring Harness								RE (-)	Category 7
 73 ENG2						Mos	31-Dec-2021			
Eff: 12-May-2016 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30474 Rev 3	Replacement/ Modification of Electrical Wiring Harness								RE (-)	Category 7
 73 ENG1						Mos	30-Dec-2021			
Eff: 16-Oct-2018 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description										Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining		
30474 Rev 3	Replacement/ Modification of Electrical Wiring Harness						RE (-)		Category 7			
 73 ENG2						Mos	31-Dec-2021					
Eff: 16-Oct-2018 Complied With						Hrs						
(AVG MAN HRS: 1.5)						Enc						
30478 Rev 4	Electronic Engine Control (EEC) - Replacement/Field Modification						RE (-)		Category 3			
 73 ENG1						Mos	30-Dec-2021					
Eff: 01-Dec-2015 Complied With						Hrs						
(AVG MAN HRS: 2.5)						Enc						
30478 Rev 4	Electronic Engine Control (EEC) - Replacement/Field Modification						RE (-)		Category 3			
 73 ENG2						Mos	31-Dec-2021					
Eff: 01-Dec-2015 Complied With						Hrs						
(AVG MAN HRS: 2.5)						Enc						
30504 Rev 2	Replacement of Fuel/Oil Heat Exchanger						RE (-)		Category 7			
 73 ENG1						Mos	30-Dec-2021					
Eff: 04-Jan-2016 Complied With						Hrs						
(AVG MAN HRS: 1.5)						Enc						
30504 Rev 2	Replacement of Fuel/Oil Heat Exchanger						RE (-)		Category 7			
 73 ENG2						Mos	31-Dec-2021					
Eff: 04-Jan-2016 Complied With						Hrs						
(AVG MAN HRS: 1.5)						Enc						
30504 Rev 3	Replacement of Fuel/Oil Heat Exchanger						RE (-)		Category 7			
 73 ENG1						Mos	30-Dec-2021					
Eff: 15-Jan-2019 Complied With						Hrs						
(AVG MAN HRS: 1.5)						Enc						
30504 Rev 3	Replacement of Fuel/Oil Heat Exchanger						RE (-)		Category 7			
 73 ENG2						Mos	31-Dec-2021					
Eff: 15-Jan-2019 Complied With						Hrs						
(AVG MAN HRS: 1.5)						Enc						
30539	Replacement of Fuel Supply Pad						RE (-)		Category 7			
 73 ENG1						Mos	30-Dec-2021					
Eff: 26-Sep-2017 Complied With						Hrs						
(AVG MAN HRS: 1.5)						Enc						
30539	Replacement of Fuel Supply Pad						RE (-)		Category 7			
 73 ENG2						Mos	31-Dec-2021					
Eff: 26-Sep-2017 Complied With						Hrs						
(AVG MAN HRS: 1.5)						Enc						
30539 Rev 1	Replacement of Fuel Supply Pad						RE (-)		Category 7			
 73 ENG1						Mos	30-Dec-2021					
Eff: 01-Oct-2019 Complied With						Hrs						
(AVG MAN HRS: 1.5)						Enc						
30539 Rev 1	Replacement of Fuel Supply Pad						RE (-)		Category 7			
 73 ENG2						Mos	31-Dec-2021					
Eff: 01-Oct-2019 Complied With						Hrs						
(AVG MAN HRS: 1.5)						Enc						

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
73-00-PW-001		Fuel Metering Unit (FMU) - Overhaul (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO	≈18-Jul-2030
	73 ENG1						Mos				
	30J3050-03						Hrs	5,500	+100	5500	4140:04 Hrs (+100)
	F86818						Enc				
		(SOURCE: PW545C MM (P/N 30J2302))									
		Note: NOTE: 1. The Fuel Control Unit (FCU) has the same TBO as the engine. If the FCU was replaced since last engine overhaul, at operator discretion, it can continue in service if: (1) The FCU was operating correctly at engine removal for overhaul, (2) The FCU remaining running time allows the engine to reach the next scheduled major maintenance event (preferably HSI)									
		NOTE: 2. Providing the accessory was operating correctly at engine removal, do a general visual inspection. If the accessory is reported as malfunctioning examine and test per CMM.									
		NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.									
73-00-PW-001		Fuel Metering Unit (FMU) - Overhaul (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO	≈04-Jan-2031
	73 ENG2						Mos				
	30J3050-03						Hrs	5,500	+100	5500	4473:12 Hrs (+100)
	F86850						Enc				
		(SOURCE: PW545C MM (P/N 30J2302))									
		Note: NOTE: 1. The Fuel Control Unit (FCU) has the same TBO as the engine. If the FCU was replaced since last engine overhaul, at operator discretion, it can continue in service if: (1) The FCU was operating correctly at engine removal for overhaul, (2) The FCU remaining running time allows the engine to reach the next scheduled major maintenance event (preferably HSI)									
		NOTE: 2. Providing the accessory was operating correctly at engine removal, do a general visual inspection. If the accessory is reported as malfunctioning examine and test per CMM.									
		NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.									
73-00-PW-002		Fuel to Oil Heat Exchanger - Overhaul or Refurbish (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO	≈18-Jul-2030
	73 ENG1						Mos				
	31J2955-03						Hrs	5,500	+100	5500	4140:04 Hrs (+100)
	0031695727						Enc				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-002		Fuel to Oil Heat Exchanger - Overhaul or Refurbish (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO	≈04-Jan-2031
	73 ENG2						Mos				
	31J2955-03						Hrs	5,500	+100	5500	4473:12 Hrs (+100)
	0031695720						Enc				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-003		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO	≈18-Jul-2030
	73 ENG1	No.1					Mos				
	30J2313-02						Hrs	5,500	+100	5500	4140:04 Hrs (+100)
	DEAAB70793						Enc				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-003		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO	≈04-Jan-2031
	73 ENG2	No.1					Mos				
	30J2313-02						Hrs	5,500	+100	5500	4473:12 Hrs (+100)
	DEAA71607						Enc				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-004		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO	≈18-Jul-2030
	73 ENG1	No.2					Mos				
	30J2313-02						Hrs	5,500	+100	5500	4140:04 Hrs (+100)
	DEAAB70796						Enc				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
73-00-PW-004		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
	73 ENG2	No.2				Mos					
	30J2313-02					Hrs		5,500	+100	5500	4473:12 Hrs (+100)
	DEAA71609					Enc					
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-005		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
	73 ENG1	No.3				Mos					
	30J2313-02					Hrs		5,500	+100	5500	4140:04 Hrs (+100)
	DEAAB70799					Enc					
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-005		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
	73 ENG2	No.3				Mos					
	30J2313-02					Hrs		5,500	+100	5500	4473:12 Hrs (+100)
	DEAA71611					Enc					
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-006		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
	73 ENG1	No.4				Mos					
	30J2313-02					Hrs		5,500	+100	5500	4140:04 Hrs (+100)
	DEAAB70800					Enc					
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-006		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
	73 ENG2	No.4				Mos					
	30J2313-02					Hrs		5,500	+100	5500	4473:12 Hrs (+100)
	DEAA71616					Enc					
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-007		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
	73 ENG1	No.5				Mos					
	30J2313-02					Hrs		5,500	+100	5500	4140:04 Hrs (+100)
	DEAAB70801					Enc					
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-007		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
	73 ENG2	No.5				Mos					
	30J2313-02					Hrs		5,500	+100	5500	4473:12 Hrs (+100)
	DEAA71617					Enc					
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-008		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
	73 ENG1	No.6				Mos					
	30J2313-02					Hrs		5,500	+100	5500	4140:04 Hrs (+100)
	DEAAB71331					Enc					
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-008		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
	73 ENG2	No.6				Mos					
	30J2313-02					Hrs		5,500	+100	5500	4473:12 Hrs (+100)
	DEAA71618					Enc					
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
73-00-PW-009		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
	73 ENG1	No.7					Mos				
	30J2313-02						Hrs	5,500	+100	5500	4140:04 Hrs (+100)
	DEAAB71344						Enc				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-009		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
	73 ENG2	No.7					Mos				
	30J2313-02						Hrs	5,500	+100	5500	4473:12 Hrs (+100)
	DEAA71926						Enc				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-010		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
	73 ENG1	No.8					Mos				
	30J2313-02						Hrs	5,500	+100	5500	4140:04 Hrs (+100)
	DEAAB71345						Enc				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-010		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
	73 ENG2	No.8					Mos				
	30J2313-02						Hrs	5,500	+100	5500	4473:12 Hrs (+100)
	DEAA71927						Enc				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-011		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
	73 ENG1	No.9					Mos				
	30J2313-02						Hrs	5,500	+100	5500	4140:04 Hrs (+100)
	DEAAB71610						Enc				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-011		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
	73 ENG2	No.9					Mos				
	30J2313-02						Hrs	5,500	+100	5500	4473:12 Hrs (+100)
	DEAA71930						Enc				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-012		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
	73 ENG1	No.10					Mos				
	30J2313-02						Hrs	5,500	+100	5500	4140:04 Hrs (+100)
	DEAAB71613						Enc				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-012		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
	73 ENG2	No.10					Mos				
	30J2313-02						Hrs	5,500	+100	5500	4473:12 Hrs (+100)
	DEAAB71931						Enc				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									
73-00-PW-013		Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
	73 ENG1	No.11					Mos				
	30J2313-02						Hrs	5,500	+100	5500	4140:04 Hrs (+100)
	DEAAB71614						Enc				
		Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)									

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
73-00-PW-013	Fuel Nozzles - Overhaul or Refurbish (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
 73 ENG2	No.11					Mos				
30J2313-02						Hrs	5,500	+100	5500	4473:12 Hrs (+100)
DEAAB71932						Enc				
Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-015	Fuel Filter Differential Pressure Switch - Examine and functional test (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
 73 ENG1						Mos				
						Hrs	5,500	+100	5500	4140:04 Hrs (+100)
Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
						Enc				
73-00-PW-015	Fuel Filter Differential Pressure Switch - Examine and functional test (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
 73 ENG2						Mos				
						Hrs	5,500	+100	5500	4473:12 Hrs (+100)
Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
						Enc				
73-00-PW-016	Fuel Manifold - Inspect/Examine (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
 73 ENG1						Mos				
Unknown						Hrs	5,500	+100	5500	4140:04 Hrs (+100)
Unknown						Enc				
Ref:73-10-04-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
Note: Ref: 73-10-04, NOZZLES & MANIFOLD - MAINTENANCE PRACTICES (Pre-SB30405) or Ref: CIR Post-SB30405										
73-00-PW-016	Fuel Manifold - Inspect/Examine (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
 73 ENG2						Mos				
Unknown						Hrs	5,500	+100	5500	4473:12 Hrs (+100)
Unknown						Enc				
Ref:73-10-04-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
Note: Ref: 73-10-04, NOZZLES & MANIFOLD - MAINTENANCE PRACTICES (Pre-SB30405) or Ref: CIR Post-SB30405										
73-00-PW-017	Fuel Filter - Inspect and replace (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈11-Aug-2031
 73 ENG1						Mos	27-Oct-2023			
						Hrs	763:53	5,500	+100	6263:53
Ref:73-10-05-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.										
						Enc	505			4903:57 Hrs (+100)
73-00-PW-017	Fuel Filter - Inspect and replace (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
 73 ENG2						Mos				
						Hrs	5,500	+100	5500	4473:12 Hrs (+100)
Ref:73-10-05-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.										
						Enc				
73-00-PW-018	Fuel Shut-off Cable - Examine per CIR						RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
 73 ENG1						Mos				
Unknown						Hrs	5,500	+100	5500	4140:04 Hrs (+100)
Unknown						Enc				
Ref:CIR Manual P/N 30J2306 (SOURCE: EMM 05-20-00 Par. 3 Table 1)										
73-00-PW-018	Fuel Shut-off Cable - Examine per CIR						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
 73 ENG2						Mos				
Unknown						Hrs	5,500	+100	5500	4473:12 Hrs (+100)
Unknown						Enc				
Ref:CIR Manual P/N 30J2306 (SOURCE: EMM 05-20-00 Par. 3 Table 1)										

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
73-00-PW-020		Engine Wiring Harness - Examine and do a functional test (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
	73 ENG1						Mos				
	30J2970-06						Hrs	5,500	+100	5500	4140:04 Hrs (+100)
	ADXAX001246						Enc				
	Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.										
73-00-PW-020		Engine Wiring Harness - Examine and do a functional test (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
	73 ENG2						Mos				
	30J2970-06						Hrs	5,500	+100	5500	4473:12 Hrs (+100)
	ADXAX001247						Enc				
	Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.										
731004-001		Fuel Manifold						RE (O/C)			
	73 ENG1						Mos	30-Dec-2021			
	Unknown						Hrs	0			
	Unknown						Enc	0			
731004-001		Fuel Manifold						RE (O/C)			
	73 ENG2						Mos	31-Dec-2021			
	Unknown						Hrs	0			
	Unknown						Enc	0			
731007-001		Fuel Shut-off Cable						RE (O/C)			
	73 ENG1						Mos	30-Dec-2021			
	Unknown						Hrs	0			
	Unknown						Enc	0			
731007-001		Fuel Shut-off Cable						RE (O/C)			
	73 ENG2						Mos	31-Dec-2021			
	Unknown						Hrs	0			
	Unknown						Enc	0			
731007-002		Fuel Shut-off Valve						RE (O/C)			
	73 ENG1						Mos	30-Dec-2021			
	Unknown						Hrs	0			
	Unknown						Enc	0			
731007-002		Fuel Shut-off Valve						RE (O/C)			
	73 ENG2						Mos	31-Dec-2021			
	Unknown						Hrs	0			
	Unknown						Enc	0			
731013-0101		Fuel Manifold Pad						RE (O/C)			
	73 ENG1						Mos	30-Dec-2021			
	Unknown						Hrs	0			
	Unknown						Enc	0			
731013-0101		Fuel Manifold Pad						RE (O/C)			
	73 ENG2						Mos	31-Dec-2021			
	Unknown						Hrs	0			
	Unknown						Enc	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
73-11-00-201	Fuel Oil Heat Exchanger General Visual Inspection: Do an inspection for security, leakage and general condition.						RE	EMM - Periodic Inspection		≈25-Jan-2025
73 ENG1	72EH0800				Mos	27-Oct-2023				
	Ref:73-10-02-mp				Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
	KGR-WP-011 START 21-JAN-2025				Enc	505				
73-11-00-201	Fuel Oil Heat Exchanger General Visual Inspection: Do an inspection for security, leakage and general condition.						RE	EMM - Periodic Inspection		≈03-Jun-2025
73 ENG2	72EH0800				Mos	22-May-2024				
	Ref:73-10-02-mp				Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
					Enc	483				
73-11-00-202	Fuel Metering and Control Components General Visual Inspection: Do a check for security, leakage and general condition.						RE	EMM - Periodic Inspection		≈25-Jan-2025
73 ENG1	72EH0800				Mos	27-Oct-2023				
					Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
	KGR-WP-011 START 21-JAN-2025				Enc	505				
73-11-00-202	Fuel Metering and Control Components General Visual Inspection: Do a check for security, leakage and general condition.						RE	EMM - Periodic Inspection		≈03-Jun-2025
73 ENG2	72EH0800				Mos	22-May-2024				
					Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
					Enc	483				
73-11-00-203	External Tubing General Visual Inspection: Examine for signs of wear, chafing, cracks, leaks and corrosion.						RE	EMM - Periodic Inspection		≈25-Jan-2025
73 ENG1	72EH0800				Mos	27-Oct-2023				
					Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
	KGR-WP-011 START 21-JAN-2025				Enc	505				
73-11-00-203	External Tubing General Visual Inspection: Examine for signs of wear, chafing, cracks, leaks and corrosion.						RE	EMM - Periodic Inspection		≈03-Jun-2025
73 ENG2	72EH0800				Mos	22-May-2024				
					Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
					Enc	483				
73-11-00-204	Fuel Distribution (Engine HSI) Special Detailed Inspection: If the engine is Pre-SB30539, replace fuel manifold pad when part has accumulated 7600 cycles.						RE	EMM - Periodic Inspection, Extended HSI		≈19-Sep-2026
73 ENG1					Mos					
Unknown					Hrs		2,750	+50	2750	1390:04 Hrs (+50)
Unknown					Enc					
	(SOURCE: PW545C MM 30J2302)									
	Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.									
73-11-00-204	Fuel Distribution (Engine HSI) Special Detailed Inspection: If the engine is Pre-SB30539, replace fuel manifold pad when part has accumulated 7600 cycles.						RE	EMM - Periodic Inspection, Extended HSI		≈07-Mar-2027
73 ENG2					Mos					
Unknown					Hrs		2,750	+50	2750	1723:12 Hrs (+50)
Unknown					Enc					
	(SOURCE: PW545C MM 30J2302)									
	Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.									
73-11-00-204 (Replace)	Fuel Distribution (Engine HSI) Special Detailed Inspection: If the engine is Pre-SB30539, replace fuel manifold pad when part has accumulated 7600 cycles.						RE (N/A)	EMM - Periodic Inspection		
73 ENG1					Mos					
					Hrs					
					Enc					
73-11-00-204 (Replace)	Fuel Distribution (Engine HSI) Special Detailed Inspection: If the engine is Pre-SB30539, replace fuel manifold pad when part has accumulated 7600 cycles.						RE (N/A)	EMM - Periodic Inspection		
73 ENG2					Mos					
					Hrs					
					Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
73-11-00-205		Fuel Filter Element Detailed Inspection: Do an inspection for foreign material and damage.						RE	EMM - Periodic Inspection		≈25-Jan-2025
	73 ENG1	72EH0800				Mos	27-Oct-2023				
	Ref:73-10-05-mp					Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
	KGR-WP-011 START 21-JAN-2025					Enc	505				
73-11-00-205		Fuel Filter Element Detailed Inspection: Do an inspection for foreign material and damage.						RE	EMM - Periodic Inspection		≈03-Jun-2025
	73 ENG2	72EH0800				Mos	22-May-2024				
	Ref:73-10-05-mp					Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
						Enc	483				
73-11-00-206		Emergency Fuel Shutoff System Detailed Inspection: Do an inspection through hole in the exhaust cone and check for- Security of control lever- Signs of oil leaks or carbon at No.5 bearing area. Do an inspection of cable and linkages.						RE	EMM - Periodic Inspection		≈25-Jan-2025
	73 ENG1	72EH0800				Mos	27-Oct-2023				
	Ref:73-10-07-mp					Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
	KGR-WP-011 START 21-JAN-2025					Enc	505				
73-11-00-206		Emergency Fuel Shutoff System Detailed Inspection: Do an inspection through hole in the exhaust cone and check for- Security of control lever- Signs of oil leaks or carbon at No.5 bearing area. Do an inspection of cable and linkages.						RE	EMM - Periodic Inspection		≈03-Jun-2025
	73 ENG2	72EH0800				Mos	22-May-2024				
	Ref:73-10-07-mp					Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
						Enc	483				
73-11-00-701		Emergency Fuel Shutoff System Operational Check: Removal/Adjustment & Installation (Ref. 73-10-07, EMERGENCY FUEL SHUT-OFF - MAINTENANCE PRACTICES).						RE	EMM - Periodic Inspection, Extended HSI		≈19-Sep-2026
	73 ENG1					Mos					
	Ref:73-10-07-mp (SOURCE: PW545C MM 30J2302)					Hrs		2,750	+50	2750	1390:04 Hrs (+50)
	Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.					Enc					
73-11-00-701		Emergency Fuel Shutoff System Operational Check: Removal/Adjustment & Installation (Ref. 73-10-07, EMERGENCY FUEL SHUT-OFF - MAINTENANCE PRACTICES).						RE	EMM - Periodic Inspection, Extended HSI		≈07-Mar-2027
	73 ENG2					Mos					
	Ref:73-10-07-mp (SOURCE: PW545C MM 30J2302)					Hrs		2,750	+50	2750	1723:12 Hrs (+50)
	Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.					Enc					
73-11-00-901		Fuel Filter Element Discard: Install the new fuel filter element.						RE	EMM - Periodic Inspection		≈16-Aug-2025
	73 ENG1					Mos	27-Oct-2023				
	Ref:73-10-05-mp					Hrs	763:53	1,200	-/+25	1963:53	603:57 Hrs (+25)
						Enc	505				
73-11-00-901		Fuel Filter Element Discard: Install the new fuel filter element.						RE	EMM - Periodic Inspection		≈09-Jan-2025
	73 ENG2					Mos					
	Ref:73-10-05-mp					Hrs		1,200	-/+25	1200	173:12 Hrs (+25)
	KGR-WP-011 START 21-JAN-2025					Enc					
73-11-00-902		Fuel Distribution (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈18-Jul-2030
	73 ENG1					Mos					
	(SOURCE: PW545C MM 30J2302)					Hrs		5,500	+50	5500	4140:04 Hrs (+50)
	Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.					Enc					
73-11-00-902		Fuel Distribution (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈04-Jan-2031
	73 ENG2					Mos					
	(SOURCE: PW545C MM 30J2302)					Hrs		5,500	+50	5500	4473:12 Hrs (+50)
	Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.					Enc					

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
732002	 73 ENG1 30J2970-06 ADXAX001246	Electrical Wiring Harness New						RE (O/C)				
							Mos	30-Dec-2021				
							Hrs	0				
							Enc	0				
732002	 73 ENG2 30J2970-06 ADAXAX001247	Electrical Wiring Harness New						RE (O/C)				
							Mos	31-Dec-2021				
							Hrs	0				
							Enc	0				
73-21-00-201		Engine Wiring Harness General Visual Inspection: Do a check for security of all clamps and brackets. Examine the cables for sign of wear, fraying, chafing and cracks. Do a check for security of all wiring harness connectors. Examine the outer surfaces for cracks and corrosion. For Pre-SB30393 Engine: Do a visual inspection of the EEC support beams, and the five support brackets for crack indications. (Ref. 73-20-03, EEC-MAINTENANCE PRACTICES, INSPECTION). For Post-SB30393 Engine: No action is necessary.							RE	EMM - Periodic Inspection	≈25-Jan-2025	
	73 ENG1 Ref:73-20-03-mp (SOURCE: PW545C MM (P/N 30J2302))  KGR-WP-011 START 21-JAN-2025	72EH0800					Mos	27-Oct-2023				
							Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
							Enc	505				
73-21-00-201		Engine Wiring Harness General Visual Inspection: Do a check for security of all clamps and brackets. Examine the cables for sign of wear, fraying, chafing and cracks. Do a check for security of all wiring harness connectors. Examine the outer surfaces for cracks and corrosion. For Pre-SB30393 Engine: Do a visual inspection of the EEC support beams, and the five support brackets for crack indications. (Ref. 73-20-03, EEC-MAINTENANCE PRACTICES, INSPECTION). For Post-SB30393 Engine: No action is necessary.							RE	EMM - Periodic Inspection	≈03-Jun-2025	
	73 ENG2 Ref:73-20-03-mp (SOURCE: PW545C MM (P/N 30J2302))	72EH0800					Mos	22-May-2024				
							Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
							Enc	483				
73-21-00-901		Engine Wiring Harness (Cleaning) Restoration: Disconnect each wiring harness connector, clean, inspect (Ref. 73-20-02, ELECTRICAL HARNESS - MAINTENANCE PRACTICES). Do the necessary engine checks after wiring harness replacement. For Pre-SB30434 Engine: Perform an EEC/DCU download (Ref: 72-00-01, ELECTRONIC ENGINE CONTROL - FAULT ISOLATION). Review download for fault codes 112 (T6 fault) and 252 (EEC overtemperature fault). If found recorded, proceed with fault isolation chart (Ref: 72-00-01, ELECTRONIC ENGINE CONTROL - FAULT ISOLATION). For Post-SB30434 Engine: No action is necessary.							RE	EMM - Periodic Inspection	≈25-Jan-2025	
	73 ENG1 Ref:73-20-02-mp (SOURCE: PW545C MM 30J2302)  KGR-WP-011 START 21-JAN-2025	72EH0800					Mos	27-Oct-2023				
							Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
							Enc	505				
73-21-00-901		Engine Wiring Harness (Cleaning) Restoration: Disconnect each wiring harness connector, clean, inspect (Ref. 73-20-02, ELECTRICAL HARNESS - MAINTENANCE PRACTICES). Do the necessary engine checks after wiring harness replacement. For Pre-SB30434 Engine: Perform an EEC/DCU download (Ref: 72-00-01, ELECTRONIC ENGINE CONTROL - FAULT ISOLATION). Review download for fault codes 112 (T6 fault) and 252 (EEC overtemperature fault). If found recorded, proceed with fault isolation chart (Ref: 72-00-01, ELECTRONIC ENGINE CONTROL - FAULT ISOLATION). For Post-SB30434 Engine: No action is necessary.							RE	EMM - Periodic Inspection	≈03-Jun-2025	
	73 ENG2 Ref:73-20-02-mp (SOURCE: PW545C MM 30J2302)	72EH0800					Mos	22-May-2024				
							Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
							Enc	483				
73-21-00-902		Fuel Controlling (Engine TBO) Restoration: Refer to Para. 3.							RE	EMM - Periodic Inspection, Extended TBO	≈18-Jul-2030	
	73 ENG1 (SOURCE: PW545C MM 30J2302) Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.						Mos					
							Hrs	5,500	+50	5500	4140:04 Hrs (+50)	
							Enc					
73-21-00-902		Fuel Controlling (Engine TBO) Restoration: Refer to Para. 3.							RE	EMM - Periodic Inspection, Extended TBO	≈04-Jan-2031	
	73 ENG2 (SOURCE: PW545C MM 30J2302) Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.						Mos					
							Hrs	5,500	+50	5500	4473:12 Hrs (+50)	
							Enc					

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-73-06	Transmittal of ELDEC Corporation Service Letter SL9-231-73-04, Shipping Instructions for the 9-231-28 Fuel Flow Transmitters						T (A/R)		Informational	
 73 A/F						Mos				
Eff: 21-Jun-2005						Hrs				
						Ldg				
SL560XL-73-07	Transmittal of Pratt & Whitney Canada (P&WC) Service Bulletin 30197R4, Turbofan Engine New Fuel Manifold - Introduction Of						RE (-)		Optional	
 73 A/F						Mos				
						Hrs				
						Ldg				
SL560XL-73-07 Rev 01	Transmittal of Pratt & Whitney Canada (P&WC) Service Bulletin 30197R4, Turbofan Engine New Fuel Manifold - Introduction Of						RE (-)		Optional	
 73 A/F						Mos				
						Hrs				
						Ldg				
SL560XL-73-07 Rev 02	Transmittal of Pratt & Whitney Canada (P&WC) Service Bulletin 30197R4, Turbofan Engine New Fuel Manifold - Introduction Of						T (A/R)		Informational	
 73 A/F						Mos				
Eff: 02-Jul-2007						Hrs				
						Ldg				
▼ 74 - IGNITION										
	Ignition Exciter						RE (O/C)			
 74 ENG1						Mos	30-Dec-2021			
31J2807-07	New					Hrs	0			
NNA21440008						Enc	0			
	Ignition Exciter						RE (O/C)			
 74 ENG2						Mos	31-Dec-2021			
31J2807-07	New					Hrs	0			
NNA21440007						Enc	0			
	Inboard Ignitor						RE (O/C)			
 74 ENG1						Mos	30-Dec-2021			
Unknown						Hrs	0			
Unknown						Enc	0			
	Inboard Ignitor						RE (O/C)			
 74 ENG2						Mos	31-Dec-2021			
Unknown						Hrs	0			
Unknown						Enc	0			
	Long Ignitor Lead						RE (O/C)			
 74 ENG1						Mos	30-Dec-2021			
Unknown						Hrs	0			
Unknown						Enc	0			
	Long Ignitor Lead						RE (O/C)			
 74 ENG2						Mos	31-Dec-2021			
Unknown						Hrs	0			
Unknown						Enc	0			
	Outboard Ignitor						RE (O/C)			
 74 ENG1						Mos	30-Dec-2021			
Unknown						Hrs	0			
Unknown						Enc	0			

Task No	Description								Categories	Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
		Outboard Ignitor								RE (O/C)		
	74 ENG2	Unknown Unknown					Mos	31-Dec-2021				
							Hrs	0				
							Enc	0				
		Short Ignitor Lead								RE (O/C)		
	74 ENG1	Unknown Unknown					Mos	30-Dec-2021				
							Hrs	0				
							Enc	0				
		Short Ignitor Lead								RE (O/C)		
	74 ENG2	Unknown Unknown					Mos	31-Dec-2021				
							Hrs	0				
							Enc	0				
30542	Replacement of Igniter Cables									RE (-)	Category 7	
	74 ENG1	Eff: 25-Apr-2018 Complied With (AVG MAN HRS: 1.5)					Mos	30-Dec-2021				
							Hrs					
							Enc					
30542	Replacement of Igniter Cables									RE (-)	Category 7	
	74 ENG2	Eff: 25-Apr-2018 Complied With (AVG MAN HRS: 1.5)					Mos	31-Dec-2021				
							Hrs					
							Enc					
74-00-PW-001	Ignition Exciter Box - Clean and Examine (at Engine Overhaul)									RE	EMM - Requirement, Extended TBO	≈18-Jul-2030
	74 ENG1	31J2807-07 NNA21440008 Ref:74-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.					Mos					
							Hrs	5,500	+100	5500	4140:04 Hrs (+100)	
							Enc					
74-00-PW-001	Ignition Exciter Box - Clean and Examine (at Engine Overhaul)									RE	EMM - Requirement, Extended TBO	≈04-Jan-2031
	74 ENG2	31J2807-07 NNA21440007 Ref:74-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.					Mos					
							Hrs	5,500	+100	5500	4473:12 Hrs (+100)	
							Enc					
74-00-PW-002	Ignition Cable - Examine (at Engine Overhaul)									RE	EMM - Requirement, Extended TBO	≈18-Jul-2030
	74 ENG1	Inboard 30J4166 NNAS21370023 Ref:74-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.					Mos					
							Hrs	5,500	+100	5500	4140:04 Hrs (+100)	
							Enc					
74-00-PW-002	Ignition Cable - Examine (at Engine Overhaul)									RE	EMM - Requirement, Extended TBO	≈04-Jan-2031
	74 ENG2	Inboard 30J4166 NNAS21370021 Ref:74-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.					Mos					
							Hrs	5,500	+100	5500	4473:12 Hrs (+100)	
							Enc					

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
74-00-PW-003		Ignition Cable - Examine (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO	≈18-Jul-2030
	74 ENG1	Outboard					Mos				
	30J4167						Hrs	5,500	+100	5500	4140:04 Hrs (+100)
	NNAS21370016						Enc				
		Ref:74-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.									
74-00-PW-003		Ignition Cable - Examine (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO	≈04-Jan-2031
	74 ENG2	Outboard					Mos				
	30J4167						Hrs	5,500	+100	5500	4473:12 Hrs (+100)
	NNAS21370009						Enc				
		Ref:74-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.									
74-00-PW-004		Inboard Ignition Plug - Examine (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO	≈18-Jul-2030
	74 ENG1						Mos				
	Unknown						Hrs	5,500	+100	5500	4140:04 Hrs (+100)
	Unknown						Enc				
		Ref:74-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.									
74-00-PW-004		Inboard Ignition Plug - Examine (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO	≈04-Jan-2031
	74 ENG2						Mos				
	Unknown						Hrs	5,500	+100	5500	4473:12 Hrs (+100)
	Unknown						Enc				
		Ref:74-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.									
74-00-PW-005		Outboard Ignition Plug - Examine (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO	≈18-Jul-2030
	74 ENG1						Mos				
	Unknown						Hrs	5,500	+100	5500	4140:04 Hrs (+100)
	Unknown						Enc				
		Ref:74-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.									
74-00-PW-005		Outboard Ignition Plug - Examine (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO	≈04-Jan-2031
	74 ENG2						Mos				
	Unknown						Hrs	5,500	+100	5500	4473:12 Hrs (+100)
	Unknown						Enc				
		Ref:74-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.									
741001-001		Cable Ignition Exciter to Igniter							RE (O/C)		
	74 ENG1	Inboard					Mos	30-Dec-2021			
	30J4166	New					Hrs	0			
	NNAS21370023						Enc	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
741001-001	Cable Ignition Exciter to Igniter						RE (O/C)			
 74 ENG2	Inboard					Mos	31-Dec-2021			
30J4166	New					Hrs	0			
NNAS21370021						Enc	0			
741001-002	Cable Ignition Exciter to Igniter						RE (O/C)			
 74 ENG1	Outboard					Mos	30-Dec-2021			
30J4167	New					Hrs	0			
NNAS21370016						Enc	0			
741001-002	Cable Ignition Exciter to Igniter						RE (O/C)			
 74 ENG2	Outboard					Mos	31-Dec-2021			
30J4167	New					Hrs	0			
NNAS21370009						Enc	0			
74-20-00-201	Ignition Exciter General Visual Inspection: Do a check for security and general condition.						RE	EMM - Periodic Inspection		≈25-Jan-2025
 74 ENG1	72EH0800					Mos	27-Oct-2023			
Ref:74-10-01-mp						Hrs	763:53	800	-/+25 (1563:53)	203:57 Hrs (+25)
 KGR-WP-011 START 21-JAN-2025						Enc	505			
74-20-00-201	Ignition Exciter General Visual Inspection: Do a check for security and general condition.						RE	EMM - Periodic Inspection		≈03-Jun-2025
 74 ENG2	72EH0800					Mos	22-May-2024			
Ref:74-10-01-mp						Hrs	687:03	800	-/+25 (1487:03)	460:15 Hrs (+25)
						Enc	483			
74-20-00-204	Igniters (Tip Measurement) Functional Check: Do a check for cleanliness and measure erosion. (Ref. 74-20-02, SPARK IGNITERS - MAINTENANCE PRACTICES).						RE	EMM - Periodic Inspection		≈25-Jan-2025
 74 ENG1	72EH0800					Mos	27-Oct-2023			
(SOURCE: PW545C MM 30J2302)						Hrs	763:53	800	-/+25 (1563:53)	203:57 Hrs (+25)
 KGR-WP-011 START 21-JAN-2025						Enc	505			
74-20-00-204	Igniters (Tip Measurement) Functional Check: Do a check for cleanliness and measure erosion. (Ref. 74-20-02, SPARK IGNITERS - MAINTENANCE PRACTICES).						RE	EMM - Periodic Inspection		≈03-Jun-2025
 74 ENG2	72EH0800					Mos	22-May-2024			
(SOURCE: PW545C MM 30J2302)						Hrs	687:03	800	-/+25 (1487:03)	460:15 Hrs (+25)
						Enc	483			
74-20-00-205	Ignition Cables General Visual Inspection: Do a check for chafing, wear and security.						RE	EMM - Periodic Inspection		≈25-Jan-2025
 74 ENG1	72EH0800					Mos	27-Oct-2023			
						Hrs	763:53	800	-/+25 (1563:53)	203:57 Hrs (+25)
 KGR-WP-011 START 21-JAN-2025						Enc	505			
74-20-00-205	Ignition Cables General Visual Inspection: Do a check for chafing, wear and security.						RE	EMM - Periodic Inspection		≈03-Jun-2025
 74 ENG2	72EH0800					Mos	22-May-2024			
						Hrs	687:03	800	-/+25 (1487:03)	460:15 Hrs (+25)
						Enc	483			
74-20-00-206	Ignition (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈19-Sep-2026
 74 ENG1						Mos				
(SOURCE: PW545C MM 30J2302)						Hrs	2,750	+50	2750	1390:04 Hrs (+50)
Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.						Enc				

Task No	Description								Categories	Time		
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
74-20-00-206	Ignition (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).								RE	EMM - Periodic Inspection, Extended HSI		≈07-Mar-2027
 74 ENG2	(SOURCE: PW545C MM 30J2302) Note: NOTE 1: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.						Mos					
							Hrs	2,750	+50	2750	1723:12 Hrs (+50)	
							Enc					
74-20-00-701	Igniters Operational Check: Do an operational test (Ref. 74-10-01, IGNITION SYSTEM - MAINTENANCE PRACTICES).								RE	EMM - Periodic Inspection		≈25-Jan-2025
 74 ENG1	72EH0800						Mos	27-Oct-2023				
							Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
							Enc	505				
 KGR-WP-011 START 21-JAN-2025												
74-20-00-701	Igniters Operational Check: Do an operational test (Ref. 74-10-01, IGNITION SYSTEM - MAINTENANCE PRACTICES).								RE	EMM - Periodic Inspection		≈03-Jun-2025
 74 ENG2	72EH0800						Mos	22-May-2024				
							Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
							Enc	483				
74-20-00-901	Ignition (Engine TBO) Restoration: Do the engine restoration at an approved facility (Ref. Para. 3.).								RE	EMM - Periodic Inspection, Extended TBO		≈18-Jul-2030
 74 ENG1	(SOURCE: PW545C MM 30J2302) Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.						Mos					
							Hrs	5,500	+50	5500	4140:04 Hrs (+50)	
							Enc					
74-20-00-901	Ignition (Engine TBO) Restoration: Do the engine restoration at an approved facility (Ref. Para. 3.).								RE	EMM - Periodic Inspection, Extended TBO		≈04-Jan-2031
 74 ENG2	(SOURCE: PW545C MM 30J2302) Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.						Mos					
							Hrs	5,500	+50	5500	4473:12 Hrs (+50)	
							Enc					
▼ 75 - BLEED AIR												
		Bleed Servo Valve					RE (O/C)					
 75 ENG1 30J4133-01 TRAXY000402	New						Mos	30-Dec-2021				
							Hrs	0				
							Enc	0				
		Bleed Servo Valve					RE (O/C)					
 75 ENG2 30J4133-01 TRAXY000395	New						Mos	31-Dec-2021				
							Hrs	0				
							Enc	0				
		Compressor Bleed Valve Assy					RE (O/C)					
 75 ENG1 30J2954-01 AHX2100608	New						Mos	30-Dec-2021				
							Hrs	0				
							Enc	0				
		Compressor Bleed Valve Assy					RE (O/C)					
 75 ENG2 30J2954-01 AHX2100605	New						Mos	31-Dec-2021				
							Hrs	0				
							Enc	0				
		Linear Transducer					RE (O/C)					
 75 ENG1 30J3053-01 120291755	New						Mos	30-Dec-2021				
							Hrs	0				
							Enc	0				

Task No	Description										Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
Linear Transducer								RE (O/C)				
	75 ENG2	New					Mos	31-Dec-2021				
	30J3053-01						Hrs	0				
	120291756						Enc	0				
30548	Replacement/Modification of Anti-Icing Valve						RE (-)			Category 7		
	75 ENG1	Eff: 03-Jul-2018 Complied With (AVG MAN HRS: 1)					Mos	30-Dec-2021				
							Hrs					
							Enc					
30548	Replacement/Modification of Anti-Icing Valve						RE (-)			Category 7		
	75 ENG2	Eff: 03-Jul-2018 Complied With (AVG MAN HRS: 1)					Mos	31-Dec-2021				
							Hrs					
							Enc					
30548 R1	Replacement/Modification of Anti-Icing Valve						RE (-)			Category 7		
	75 ENG1	Eff: 05-Sep-2018 Complied With (AVG MAN HRS: 1)					Mos	30-Dec-2021				
							Hrs					
							Enc					
30548 R1	Replacement/Modification of Anti-Icing Valve						RE (-)			Category 7		
	75 ENG2	Eff: 05-Sep-2018 Complied With (AVG MAN HRS: 1)					Mos	31-Dec-2021				
							Hrs					
							Enc					
30548 R2	Replacement/Modification of Anti-Icing Valve						RE (-)			Category 7		
	75 ENG1	Eff: 21-Sep-2018 Complied With (AVG MAN HRS: 1)					Mos	30-Dec-2021				
							Hrs					
							Enc					
30548 R2	Replacement/Modification of Anti-Icing Valve						RE (-)			Category 7		
	75 ENG2	Eff: 21-Sep-2018 Complied With (AVG MAN HRS: 1)					Mos	31-Dec-2021				
							Hrs					
							Enc					
30554 Rev 1	Replacement of Intercompressor Bleed Valve/ Servo-Valve						RE (-)			Category 7		
	75 ENG1	Eff: 03-Mar-2021 Complied With (AVG MAN HRS: 1.5)					Mos	30-Dec-2021				
							Hrs					
							Enc					
30554 Rev 1	Replacement of Intercompressor Bleed Valve/ Servo-Valve						RE (-)			Category 7		
	75 ENG2	Eff: 03-Mar-2021 Complied With (AVG MAN HRS: 1.5)					Mos	31-Dec-2021				
							Hrs					
							Enc					
30554 Rev 2	Replacement of Intercompressor Bleed Valve/ Servo-Valve						RE (-)			Category 7		
	75 ENG1	Eff: 26-Oct-2021 Complied With (AVG MAN HRS: 1.5)					Mos	30-Dec-2021				
							Hrs					
							Enc					
30554 Rev 2	Replacement of Intercompressor Bleed Valve/ Servo-Valve						RE (-)			Category 7		
	75 ENG2	Eff: 26-Oct-2021 Complied With (AVG MAN HRS: 1.5)					Mos	31-Dec-2021				
							Hrs					
							Enc					

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
75-00-PW-001		FADEC (EEC) - Inspection (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
	75 ENG1	(SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: PW545A: EEC (Pre-SB30567) Comply with SB30567, EEC (Post-SB30567) (Ref. Notes 2 and 3). PW545B: EEC (Pre-SB30567) Comply with SB30567, EEC (Post-SB30567) (Ref. Notes 2 and 3). PW545C: FADEC (EEC) Ref. Note 2 and 3. NOTE: 2. Providing the accessory was operating correctly at engine removal, do a general visual inspection. If the accessory is reported to malfunction, examine and test per CMM. NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.					Mos					
							Hrs		5,500	+100	5500	4140:04 Hrs (+100)
							Enc					
75-00-PW-001		FADEC (EEC) - Inspection (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
	75 ENG2	(SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: PW545A: EEC (Pre-SB30567) Comply with SB30567, EEC (Post-SB30567) (Ref. Notes 2 and 3). PW545B: EEC (Pre-SB30567) Comply with SB30567, EEC (Post-SB30567) (Ref. Notes 2 and 3). PW545C: FADEC (EEC) Ref. Note 2 and 3. NOTE: 2. Providing the accessory was operating correctly at engine removal, do a general visual inspection. If the accessory is reported to malfunction, examine and test per CMM. NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.					Mos					
							Hrs		5,500	+100	5500	4473:12 Hrs (+100)
							Enc					
75-00-PW-002		Anti-Icing Valve - Overhaul or Refurbish (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
	75 ENG1 30J4184 5617	(SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 1. The accessories have the same TBO as the engine. If the accessories was replaced since last engine overhaul, it can continue in service per operator decision and it must obey the conditions that follow: 1. The accessories are operating correctly at the engine removal for overhaul. 2. The accessory remaining time (run time) must let the engine reach the next scheduled major maintenance event (recommended HSI).					Mos					
							Hrs		5,500	+50	5500	4140:04 Hrs (+50)
							Enc					
75-00-PW-002		Anti-Icing Valve - Overhaul or Refurbish (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
	75 ENG2 30J4184 5622	(SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 1. The accessories have the same TBO as the engine. If the accessories was replaced since last engine overhaul, it can continue in service per operator decision and it must obey the conditions that follow: 1. The accessories are operating correctly at the engine removal for overhaul. 2. The accessory remaining time (run time) must let the engine reach the next scheduled major maintenance event (recommended HSI).					Mos					
							Hrs		5,500	+50	5500	4473:12 Hrs (+50)
							Enc					
75-00-PW-003		P3 Air Inertial Separator - Inspect/Examine (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
	75 ENG1 Unknown Unknown Ref:75-30-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)						Mos					
							Hrs		5,500	+100	5500	4140:04 Hrs (+100)
							Enc					
75-00-PW-003		P3 Air Inertial Separator - Inspect/Examine (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
	75 ENG2 Unknown Unknown Ref:75-30-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)						Mos					
							Hrs		5,500	+100	5500	4473:12 Hrs (+100)
							Enc					

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
75-00-PW-005		BOV Torque Motor - Replace with new (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
	75 ENG1						Mos					
	30J2954-01						Hrs		5,500	+100	5500	4140:04 Hrs (+100)
	AHX2100608						Enc					
(SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE 1: The accessories have the same TBO as the engine. If the accessory was replaced since last engine overhaul, it can continue in service per operator decision and it must obey the conditions that follow: 1. The accessory is operating correctly at the engine removal for overhaul. 2. The accessory remaining time (run time) must let the engine reach the next scheduled major maintenance event (recommended HSI).												
75-00-PW-005		BOV Torque Motor - Replace with new (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
	75 ENG2						Mos					
	30J2954-01						Hrs		5,500	+100	5500	4473:12 Hrs (+100)
	AHX2100605						Enc					
(SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE 1: The accessories have the same TBO as the engine. If the accessory was replaced since last engine overhaul, it can continue in service per operator decision and it must obey the conditions that follow: 1. The accessory is operating correctly at the engine removal for overhaul. 2. The accessory remaining time (run time) must let the engine reach the next scheduled major maintenance event (recommended HSI).												
75-00-PW-005		Compressor Air Bleed Valve - Inspection (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
	75 ENG1						Mos					
	30J2954-01						Hrs		5,500	+100	5500	4140:04 Hrs (+100)
	AHX2100608						Enc					
Ref:CIR (SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.												
75-00-PW-005		Compressor Air Bleed Valve - Inspection (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
	75 ENG2						Mos					
	30J2954-01						Hrs		5,500	+100	5500	4473:12 Hrs (+100)
	AHX2100605						Enc					
Ref:CIR (SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.												
75-00-PW-006		Linear Variable Differential Transformer (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
	75 ENG1						Mos					
							Hrs		5,500	+100	5500	4140:04 Hrs (+100)
							Enc					
(SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 2. Providing the accessory was operating correctly at engine removal, do a general visual inspection. If the accessory is reported as malfunctioning examine and test per CMM., NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace												
75-00-PW-006		Linear Variable Differential Transformer (at Engine Overhaul)							RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
	75 ENG2						Mos					
							Hrs		5,500	+100	5500	4473:12 Hrs (+100)
							Enc					
(SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 2. Providing the accessory was operating correctly at engine removal, do a general visual inspection. If the accessory is reported as malfunctioning examine and test per CMM., NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace												

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR, SN 560-6325

Task No SEQ PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
									DUE	Remaining
75-10-00-201	Anti-ice Valve and P3 Anti-ice Tube (Leak Check) General Visual Inspection: Do a check for leakage at P3 air supply to bleed valve, ant-ice valve, anti-ice air tube and FCU.						RE	EMM - Periodic Inspection		≈25-Jan-2025
 75 ENG1	72EH0800				Mos	27-Oct-2023				
					Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
					Enc	505				
 KGR-WP-011 START 21-JAN-2025										
75-10-00-201	Anti-ice Valve and P3 Anti-ice Tube (Leak Check) General Visual Inspection: Do a check for leakage at P3 air supply to bleed valve, ant-ice valve, anti-ice air tube and FCU.						RE	EMM - Periodic Inspection		≈03-Jun-2025
 75 ENG2	72EH0800				Mos	22-May-2024				
					Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
					Enc	483				
75-10-00-202	P3 Bellows Seal and Bleed Air Transfer Tube General Visual Inspection: Do a visual inspection for air leak.						RE	EMM - Periodic Inspection		≈25-Jan-2025
 75 ENG1	72EH0800				Mos	27-Oct-2023				
					Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
					Enc	505				
 KGR-WP-011 START 21-JAN-2025										
75-10-00-202	P3 Bellows Seal and Bleed Air Transfer Tube General Visual Inspection: Do a visual inspection for air leak.						RE	EMM - Periodic Inspection		≈03-Jun-2025
 75 ENG2	72EH0800				Mos	22-May-2024				
					Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
					Enc	483				
75-10-00-203	Bleed Off Valve General Visual Inspection: Examine the torque motor electrical connection for security, fraying and corrosion. NOTE: If Pre-SB30420 intercompressor bleed valve servo valve, then replace it with Post-SB30420 configuration.						RE	EMM - Periodic Inspection		≈25-Jan-2025
 75 ENG1	72EH0800				Mos	27-Oct-2023				
					Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
					Enc	505				
 KGR-WP-011 START 21-JAN-2025										
75-10-00-203	Bleed Off Valve General Visual Inspection: Examine the torque motor electrical connection for security, fraying and corrosion. NOTE: If Pre-SB30420 intercompressor bleed valve servo valve, then replace it with Post-SB30420 configuration.						RE	EMM - Periodic Inspection		≈03-Jun-2025
 75 ENG2	72EH0800				Mos	22-May-2024				
					Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
					Enc	483				
75-10-00-204	Air System (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈19-Sep-2026
 75 ENG1					Mos					
	(SOURCE: PW545C MM 30J2302)				Hrs	2,750		+50	2750	1390:04 Hrs (+50)
	Note: NOTE 1: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.				Enc					
75-10-00-204	Air System (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈07-Mar-2027
 75 ENG2					Mos					
	(SOURCE: PW545C MM 30J2302)				Hrs	2,750		+50	2750	1723:12 Hrs (+50)
	Note: NOTE 1: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.				Enc					
75-10-00-901	Air System (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈18-Jul-2030
 75 ENG1					Mos					
	(SOURCE: PW545C MM 30J2302)				Hrs	5,500		+50	5500	4140:04 Hrs (+50)
	Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.				Enc					
75-10-00-901	Air System (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈04-Jan-2031
 75 ENG2					Mos					
	(SOURCE: PW545C MM 30J2302)				Hrs	5,500		+50	5500	4473:12 Hrs (+50)
	Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.				Enc					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
753001-001	P3 Air Inertial Separator						RE (O/C)			
 75 ENG1						Mos	30-Dec-2021			
Unknown						Hrs	0			
Unknown						Enc	0			
753001-001	P3 Air Inertial Separator						RE (O/C)			
 75 ENG2						Mos	31-Dec-2021			
Unknown						Hrs	0			
Unknown						Enc	0			
▼ 76 - ENGINE CONTROLS										
	Electronic Engine Control						RE (O/C)			
 76 ENG1						Mos	11-Jun-2024			
1012400-4-005	Modified					Hrs	1060:22			
2009014047						Enc	732			
(UPDATE NOTE: Actual S/N has no history about any failures)										
	Electronic Engine Control						RE (O/C)			
 76 ENG2						Mos	22-May-2024			
1012400-4-005						Hrs	687:03			
2021100377						Enc	483			
	Throttle Bank Switch						RE (O/C)			
 76 A/F	Left					Mos	22-Jun-2022			
Unknown						Hrs	0			
Unknown						Ldg	0			
	Throttle Bank Switch						RE (O/C)			
 76 A/F	Right					Mos	22-Jun-2022			
Unknown						Hrs	0			
Unknown						Ldg	0			
	Throttle Detent Valve						RE (O/C)			
 76 A/F	Left					Mos	22-Jun-2022			
Unknown						Hrs	0			
Unknown						Ldg	0			
	Throttle Detent Valve						RE (O/C)			
 76 A/F	Right					Mos	22-Jun-2022			
Unknown						Hrs	0			
Unknown						Ldg	0			
2020-26-05	Power Lever - Throttle Quadrant Inspection						RE (-)		Mandatory	
 76 A/F						Mos	22-Jun-2022			
Eff: 17-Dec-2020 Not	Due to aircraft is not in suspect serial range					Hrs	8			
Applicable						Ldg	6			
(ISSUING AUTHORITY: FAA)										
4-50-00-7100	Time Limited Dispatch Fault Visual Check						RE (N/A)		Airworthiness Limitations	
 76 A/F						Mos			Inspection Time Limits	
						Hrs				
(ZONE: 247) (SOURCE: 560 XL MM Section 4-10-01, 4-10-02)										
						Ldg				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
560XL-76-04		Transmittal of Pratt & Whitney Canada (P&WC) Service Bulletin 30434 Turbofan Engine - Electronic Engine Control/Replacement-Modification and P&WC Service Bulletin 30438 Turbofan Engine Electronic Engine Control (EEC) - Replacement/Modifications Of							RE (-)	Recommended	
	76 A/F					Mos	22-Jun-2022				
	Eff: 07-Sep-2011 Not Applicable	effective before manufacture				Hrs	8				
						Ldg	6				
76-10-00-7200		Left Fuel Control Unit Throttle Lever Cutoff Functional Check (Airplanes -5001 thru -5196 Not Incorporating SB560XL-76-03)							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	76 A/F					Mos					
						Hrs					
	(ZONE: 410) (SOURCE: 560 XL MM Section 5-10-02)					Ldg					
76-10-00-7200		Right Fuel Control Unit Throttle Lever Cutoff Functional Check (Airplanes -5001 thru -5196 Not Incorporating SB560XL-76-03)							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	76 A/F					Mos					
						Hrs					
	(ZONE: 420) (SOURCE: 560 XL MM Section 5-10-02)					Ldg					
76-10-00-7201		Left Fuel Control Unit Throttle Lever Cutoff Functional Check (Airplanes -5197 thru -6000, and Airplanes -5001 thru -5196 Incorporating SB560XL-76-03)							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	76 A/F					Mos	02-Jun-2023				
						Hrs	460:06				
	(ZONE: 410) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	317				
76-10-00-7201		Right Fuel Control Unit Throttle Lever Cutoff Functional Check (Airplanes -5197 thru -6000, and Airplanes -5001 thru -5196 Incorporating SB560XL-76-03)							RE (N/A)	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	
	76 A/F					Mos	02-Jun-2023				
						Hrs	460:06				
	(ZONE: 420) (SOURCE: 560 XL MM Section 5-10-02)					Ldg	317				
SL560XL-76-03		Transmittal of Pratt & Whitney Canada Service Bulletin 30438 Turbofan Electronic Engine Control (EEC) - Replacement/Modifications of							RE (-)	Discretionary	
	76 A/F					Mos					
						Hrs					
						Ldg					
SL560XL-76-03 Rev 02		Transmittal of Pratt & Whitney Canada Service Bulletin 30438 Turbofan Electronic Engine Control (EEC) - Replacement/Modifications of							RE (-)	Recommended	
	76 A/F					Mos	22-Jun-2022				
	Eff: 25-Sep-2015 Not Applicable	effective before manufacture				Hrs	8				
	(AVG MAN HRS: 2.5)					Ldg	6				
SL560XL-76-03 Rev 1		Transmittal of Pratt & Whitney Canada Service Bulletin 30438 Turbofan Electronic Engine Control (EEC) - Replacement/Modifications of							RE (-)	Recommended	
	76 A/F					Mos	22-Jun-2022				
	Eff: 13-Sep-2011 Not Applicable	effective before manufacture				Hrs	8				
						Ldg	6				
SL560XL-76-04		Engine Controls - Throttle Quadrant RVDLT Linkage Inspection							RE (-)	Mandatory	
	76 A/F					Mos	22-Jun-2022				
	Eff: 12-Nov-2020 Not Applicable	by aircraft S/N				Hrs	8				
	(AVG MAN HRS: 6)					Ldg	6				
SL560XL-76-04 R1		Engine Controls - Throttle Quadrant RVDLT Linkage Inspection							RE (-)	Mandatory	
	76 A/F					Mos	22-Jun-2022				
	Eff: 24-Nov-2020 Not Applicable	by aircraft S/N				Hrs	8				
	(AVG MAN HRS: 6)					Ldg	6				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560XL-76-05	Engine Controls - Inspection of the Right Engine Throttle Quadrant Rotary Variable Differential Transformer (RVDT) Electrical Wiring						RE (-)		Mandatory	
 76 A/F						Mos	06-Feb-2023			
Eff: 06-Feb-2023 Not Applicable	N/A per A/C SN					Hrs				
(AVG MAN HRS: 45)						Ldg				
▼ 77 - ENGINE INDICATING										
	Data Collection Unit						RE (O/C)			
 77 ENG1						Mos	30-Dec-2021			
30J3470-02	New					Hrs	0			
21088634						Enc	0			
	Data Collection Unit						RE (O/C)			
 77 ENG2						Mos	31-Dec-2021			
30J3470-01	New					Hrs	0			
21088051						Enc	0			
	Fuel Quantity Flow Indicator						RE (O/C)			
 77 A/F						Mos	22-Jun-2022			
Unknown						Hrs	0			
Unknown						Ldg	0			
	Standby Engine Indicator						RE (O/C)			
 77 A/F						Mos	22-Jun-2022			
10677N02M01						Hrs	0			
0883A						Ldg	0			
30534	Replacement of Data Collection Unit						RE (-)		Category 7	
 77 ENG1						Mos	30-Dec-2021			
Eff: 28-Mar-2017 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30534	Replacement of Data Collection Unit						RE (-)		Category 7	
 77 ENG2						Mos	31-Dec-2021			
Eff: 28-Mar-2017 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30534 Rev 1	Replacement of Data Collection Unit						RE (-)		Category 7	
 77 ENG1						Mos	30-Dec-2021			
Eff: 23-May-2017 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30534 Rev 1	Replacement of Data Collection Unit						RE (-)		Category 7	
 77 ENG2						Mos	31-Dec-2021			
Eff: 23-May-2017 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30534 Rev 2	Replacement of Data Collection Unit						RE (-)		Category 7	
 77 ENG1						Mos	30-Dec-2021			
Eff: 31-Oct-2017 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				
30534 Rev 2	Replacement of Data Collection Unit						RE (-)		Category 7	
 77 ENG2						Mos	31-Dec-2021			
Eff: 31-Oct-2017 Complied With						Hrs				
(AVG MAN HRS: 1.5)						Enc				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
30534 Rev 3	Replacement of Data Collection Unit						RE (-)		Category 7	
 77 ENG1					Mos	30-Dec-2021				
Eff: 06-Feb-2018 Complied With					Hrs					
(AVG MAN HRS: 1.5)					Enc					
30534 Rev 3	Replacement of Data Collection Unit						RE (-)		Category 7	
 77 ENG2					Mos	31-Dec-2021				
Eff: 06-Feb-2018 Complied With					Hrs					
(AVG MAN HRS: 1.5)					Enc					
30534 Rev 4	Replacement of Data Collection Unit						RE (-)		Category 7	
 77 ENG1					Mos	30-Dec-2021				
Eff: 29-Jun-2018 Complied With					Hrs					
(AVG MAN HRS: 1.5)					Enc					
30534 Rev 4	Replacement of Data Collection Unit						RE (-)		Category 7	
 77 ENG2					Mos	31-Dec-2021				
Eff: 29-Jun-2018 Complied With					Hrs					
(AVG MAN HRS: 1.5)					Enc					
77-00-PW-001	N1 Speed Sensor - Inspection (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
 77 ENG1					Mos					
Ref:77-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)					Hrs		5,500	+100	5500	4140:04 Hrs (+100)
Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.					Enc					
77-00-PW-001	N1 Speed Sensor - Inspection (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
 77 ENG2					Mos					
Ref:77-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)					Hrs		5,500	+100	5500	4473:12 Hrs (+100)
Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.					Enc					
77-00-PW-002	N2 Speed Sensor - Inspection (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
 77 ENG1					Mos					
Ref:77-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)					Hrs		5,500	+100	5500	4140:04 Hrs (+100)
Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.					Enc					
77-00-PW-002	N2 Speed Sensor - Inspection (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
 77 ENG2					Mos					
Ref:77-10-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)					Hrs		5,500	+100	5500	4473:12 Hrs (+100)
Note: NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace.					Enc					
77-00-PW-003	T6 Harness and Thermocouples - Inspect and do a functional check (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
 77 ENG1					Mos					
Ref:77-20-02-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)					Hrs		5,500	+100	5500	4140:04 Hrs (+100)
					Enc					
77-00-PW-003	T6 Harness and Thermocouples - Inspect and do a functional check (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
 77 ENG2					Mos					
Ref:77-20-02-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)					Hrs		5,500	+100	5500	4473:12 Hrs (+100)
					Enc					

Task No	Description								Categories	Time
SEQ PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
77-00-PW-005	Data Collection Unit - Download data (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈11-Aug-2031
 77 ENG1 30J3470-02 21088634 (SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 2. Providing the accessory was operating correctly at engine removal, do a general visual inspection. If the accessory is reported as malfunctioning examine and test per CMM., NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace					Mos	27-Oct-2023				
					Hrs	763:53	5,500	+100	6263:53	4903:57 Hrs (+100)
					Enc	505				
77-00-PW-005	Data Collection Unit - Download data (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈11-Aug-2031
 77 ENG2 30J3470-01 21088051 (SOURCE: EMM 05-20-00 Par. 3 Table 1) Note: NOTE: 2. Providing the accessory was operating correctly at engine removal, do a general visual inspection. If the accessory is reported as malfunctioning examine and test per CMM., NOTE: 3. The engine test after overhaul determines if the accessory is serviceable. If any faults associated with the accessory are found at engine test, examine the accessory per CMM or replace					Mos	27-Oct-2023				
					Hrs	430:45	5,500	+100	5930:45	4903:57 Hrs (+100)
					Enc	290				
77-10-00-201	Engine Wiring Harness General Visual Inspection: Do a check for security of all clamps and brackets, cables for signs of wear, fraying, chafing and cracks.Do a check for security of all wiring harness connectors.Examine the outer surfaces for cracks and corrosion.						RE	EMM - Periodic Inspection		≈25-Jan-2025
 77 ENG1 72EH0800  KGR-WP-011 START 21-JAN-2025					Mos	27-Oct-2023				
					Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
					Enc	505				
77-10-00-201	Engine Wiring Harness General Visual Inspection: Do a check for security of all clamps and brackets, cables for signs of wear, fraying, chafing and cracks.Do a check for security of all wiring harness connectors.Examine the outer surfaces for cracks and corrosion.						RE	EMM - Periodic Inspection		≈03-Jun-2025
 77 ENG2 72EH0800					Mos	22-May-2024				
					Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
					Enc	483				
77-10-00-202	Engine Indicating Speed Sensor (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈19-Sep-2026
 77 ENG1 (SOURCE: PW545C MM 30J2302) Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.					Mos					
					Hrs		2,750	+50	2750	1390:04 Hrs (+50)
					Enc					
77-10-00-202	Engine Indicating Speed Sensor (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈07-Mar-2027
 77 ENG2 (SOURCE: PW545C MM 30J2302) Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.					Mos					
					Hrs		2,750	+50	2750	1723:12 Hrs (+50)
					Enc					
77-10-00-901	Engine Wiring Harness (Cleaning) Restoration: Disconnect each wiring harness connector, clean, inspect and connect again (Ref. 73-20-02, WIRING HARNESS - MAINTENANCE PRACTICES).Do the necessary engine checks after the replacement of wiring harness (Ref. 71-00-00, POWER PLANT - ADJUSTMENT/TEST).						RE	EMM - Periodic Inspection		≈25-Jan-2025
 77 ENG1 72EH0800  KGR-WP-011 START 21-JAN-2025					Mos	27-Oct-2023				
					Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
					Enc	505				
77-10-00-901	Engine Wiring Harness (Cleaning) Restoration: Disconnect each wiring harness connector, clean, inspect and connect again (Ref. 73-20-02, WIRING HARNESS - MAINTENANCE PRACTICES).Do the necessary engine checks after the replacement of wiring harness (Ref. 71-00-00, POWER PLANT - ADJUSTMENT/TEST).						RE	EMM - Periodic Inspection		≈03-Jun-2025
 77 ENG2 72EH0800					Mos	22-May-2024				
					Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
					Enc	483				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
77-10-00-902		Engine Indicating Speed Sensor System (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.							RE	EMM - Periodic Inspection, Extended TBO		≈18-Jul-2030
	77 ENG1						Mos					
							Hrs	5,500	+50	5500	4140:04 Hrs (+50)	
	(SOURCE: PW545C MM 30J2302)						Enc					
	Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.											
77-10-00-902		Engine Indicating Speed Sensor System (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.							RE	EMM - Periodic Inspection, Extended TBO		≈04-Jan-2031
	77 ENG2						Mos					
							Hrs	5,500	+50	5500	4473:12 Hrs (+50)	
	(SOURCE: PW545C MM 30J2302)						Enc					
	Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.											
771002-0101		N1 Computer Display							RE (O/C)			
	77 A/F						Mos	22-Jun-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
771004-0101		N1/ITT Temp Indicator							RE (O/C)			
	77 A/F						Mos	22-Jun-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
771005-0101		N2/Oil Pressure/Oil Temperature Indicator							RE (O/C)			
	77 A/F						Mos	22-Jun-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
SL560XL-77-01		Transmittal of Pratt & Whitney Canada Service Information Letter PW500-016, PW545A ITT and N2 Splits in Climb							T (A/R)		Informational	
	77 A/F						Mos					
	Eff: 25-Jun-2003						Hrs					
							Ldg					
SL560XL-77-02		Transmittal of Pratt & Whitney Canada (P&WC) Service Information Letter PW500-018, PW500 High ITT							T (A/R)		Informational	
	77 A/F						Mos					
	Eff: 11-Aug-2003						Hrs					
							Ldg					
▼ 78 - EXHAUST												
		ARM Pressure Switch							RE (O/C)			
	78 A/F	Left					Mos	22-Jun-2022				
	80637-1						Hrs	0				
	2141						Ldg	0				
		ARM Pressure Switch							RE (O/C)			
	78 A/F	Right					Mos	22-Jun-2022				
	80637-1						Hrs	0				
	2162						Ldg	0				
		Deploy Limit Switch							RE (O/C)			
	78 A/F	Left					Mos	22-Jun-2022				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	78 A/F Unknown Unknown	Deploy Limit Switch Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	78 A/F Unknown Unknown	Stow Limit Switch Left Inboard					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	78 A/F Unknown Unknown	Stow Limit Switch Left Outboard					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	78 A/F Unknown Unknown	Stow Limit Switch Right Inboard					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	78 A/F Unknown Unknown	Stow Limit Switch Right Outboard					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	78 A/F 64ND-78204-7 4459	Thrust Reverser Actuator Left Inboard					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	78 A/F 64ND-78204-7 4460	Thrust Reverser Actuator Left Outboard					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	78 A/F 64ND-78204-7 4472	Thrust Reverser Actuator Right Inboard					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	78 A/F 64ND-78204-7 4474	Thrust Reverser Actuator Right Outboard					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	78 A/F 64ND-78002-7 EX1875-4	Thrust Reverser Assembly Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
	78 A/F 64ND-78002-8 EX1880-2	Thrust Reverser Assembly Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
	78 A/F	Thrust Reverser Isolation Valve						RE (O/C)			
	4222	Left					Mos	22-Jun-2022			
	1317M						Hrs	0			
							Ldg	0			
	78 A/F	Thrust Reverser Isolation Valve						RE (O/C)			
	4222	Right					Mos	22-Jun-2022			
	1316M						Hrs	0			
							Ldg	0			
	78 A/F	Thrust Reverser Manifold Assembly						RE (O/C)			
	8245	Left					Mos	22-Jun-2022			
	1315						Hrs	0			
							Ldg	0			
	78 A/F	Thrust Reverser Manifold Assembly						RE (O/C)			
	8245	Right					Mos	22-Jun-2022			
	1314						Hrs	0			
							Ldg	0			
	78 A/F	Thrust Reverser Valve						RE (O/C)			
	4221	Left					Mos	22-Jun-2022			
	1334						Hrs	0			
							Ldg	0			
	78 A/F	Thrust Reverser Valve						RE (O/C)			
	Unknown	Right					Mos	22-Jun-2022			
	Unknown						Hrs	0			
							Ldg	0			
	78 A/F	Thrust Reverser Valve						RE (O/C)			
	4221	Right					Mos	22-Jun-2022			
	1332						Hrs	0			
							Ldg	0			
12-20-78-6400		Left Thrust Reverser Guide Rod (D-5100NS Aerosol Spray Method) Lubrication							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈08-Feb-2025
	78 A/F	5-12-19					Mos	16-Sep-2024			
		(ZONE: 410) (SOURCE: 560 XL MM Section 5-10-02)					Hrs	1292:19	300	-/+25 (1592:19)	232:23 Hrs (+25)
							Ldg	898			
		KGR-WP-011 START 21-JAN-2025									
12-20-78-6400		Right Thrust Reverser Guide Rod (D-5100NS Aerosol Spray Method) Lubrication							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS	≈08-Feb-2025
	78 A/F	5-12-19					Mos	16-Sep-2024			
		(ZONE: 420) (SOURCE: 560 XL MM Section 5-10-02)					Hrs	1292:19	300	-/+25 (1592:19)	232:23 Hrs (+25)
							Ldg	898			
		KGR-WP-011 START 21-JAN-2025									

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
12-20-78-6401	Thrust Reverser Pivot Point (WC-393 Method) Lubrication (Airplanes -5001 and On)						RE	05-10-01, 05-10-02, 05-12-00, Category 6		≈08-Feb-2025
 78 A/F	Left5-12-19				Mos	16-Sep-2024				
64ND-78002-7					Hrs	1292:19	300	-/+25	(1592:19)	232:23 Hrs (+25)
EX1875-4					Ldg	898				
MRBR Task:78-30-00-602 (ZONE: 410) (SOURCE: 560XL MM) Note: This task gives a Thrust Reverser Pivot Point Lubrication method that is an alternate to Task 12-20-78-6402 (C-5A Anti-Seize Method) Lubrication which is completed at a 600 Flight Hour interval. It is not required to complete this task if Task 12-20-78-6402 (C-5A Anti-Seize Method) Lubrication is currently being followed.										
 KGR-WP-011 START 21-JAN-2025										
12-20-78-6401	Thrust Reverser Pivot Point (WC-393 Method) Lubrication (Airplanes -5001 and On)						RE	05-10-01, 05-10-02, 05-12-00, Category 6		≈08-Feb-2025
 78 A/F	Right5-12-19				Mos	16-Sep-2024				
64ND-78002-8					Hrs	1292:19	300	-/+25	(1592:19)	232:23 Hrs (+25)
EX1880-2					Ldg	898				
MRBR Task:78-30-00-602 (ZONE: 420) (SOURCE: 560XL MM) Note: This task gives a Thrust Reverser Pivot Point Lubrication method that is an alternate to Task 12-20-78-6402 (C-5A Anti-Seize Method) Lubrication which is completed at a 600 Flight Hour interval. It is not required to complete this task if Task 12-20-78-6402 (C-5A Anti-Seize Method) Lubrication is currently being followed.										
 KGR-WP-011 START 21-JAN-2025										
12-20-78-6402	Thrust Reverser Pivot Point (C-5A Anti-Seize Method) Lubrication (Airplanes -5001 and On)						RE (N/A)	05-10-01, 05-10-02, Category 6		
 78 A/F	Left				Mos					
64ND-78002-7					Hrs					
EX1875-4					Ldg					
MRBR Task:78-30-00-603 (ZONE: 410) (SOURCE: 560XL MM) Note: NOTE: This task is not required if the Thrust Reverser Pivot Point (WC-393 Method) Lubrication is used										
12-20-78-6402	Thrust Reverser Pivot Point (C-5A Anti-Seize Method) Lubrication (Airplanes -5001 and On)						RE (N/A)	05-10-01, 05-10-02, Category 6		
 78 A/F	Right				Mos					
64ND-78002-8					Hrs					
EX1880-2					Ldg					
MRBR Task:78-30-00-603 (ZONE: 420) (SOURCE: 560XL MM) Note: NOTE: This task is not required if the Thrust Reverser Pivot Point (WC-393 Method) Lubrication is used										
78-10-00-201	Turbine Exhaust Case and Mixer (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈19-Sep-2026
 78 ENG1					Mos					
					Hrs		2,750	+50	2750	1390:04 Hrs (+50)
Ref:72-00-00-ic (SOURCE: PW545C MM 30J2302) Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.										
					Enc					
78-10-00-201	Turbine Exhaust Case and Mixer (Engine HSI) Special Detailed Inspection: Do a hot section inspection (Ref. 72-00-00, ENGINE GENERAL - INSPECTION).						RE	EMM - Periodic Inspection, Extended HSI		≈07-Mar-2027
 78 ENG2					Mos					
					Hrs		2,750	+50	2750	1723:12 Hrs (+50)
Ref:72-00-00-ic (SOURCE: PW545C MM 30J2302) Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.										
					Enc					
78-10-00-202	Emergency Fuel Shut Off Lever and Cable Detailed Inspection: Do an inspection through hole in theexhaust cone for - Security of control lever - Signs of oil leaks or carbon at No.5 bearing area - Examine the cable and linkages.						RE	EMM - Periodic Inspection		≈12-Feb-2025
 78 ENG1					Mos					
					Hrs		1,600	-/+25	1600	240:04 Hrs (+25)
Ref:73-10-07-mp										
 KGR-WP-011 START 21-JAN-2025										
78-10-00-202	Emergency Fuel Shut Off Lever and Cable Detailed Inspection: Do an inspection through hole in theexhaust cone for - Security of control lever - Signs of oil leaks or carbon at No.5 bearing area - Examine the cable and linkages.						RE	EMM - Periodic Inspection		≈31-Jul-2025
 78 ENG2					Mos					
					Hrs		1,600	-/+25	1600	573:12 Hrs (+25)
Ref:73-10-07-mp										
					Enc					

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time	
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining	
78-10-00-901		Turbine Exhaust Case and Mixer (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.							RE	EMM - Periodic Inspection, Extended TBO		≈18-Jul-2030
	78 ENG1	(SOURCE: PW545C MM 30J2302) Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.					Mos					
							Hrs	5,500	+50	5500	4140:04 Hrs (+50)	
							Enc					
78-10-00-901		Turbine Exhaust Case and Mixer (Engine TBO) Restoration: Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.							RE	EMM - Periodic Inspection, Extended TBO		≈04-Jan-2031
	78 ENG2	(SOURCE: PW545C MM 30J2302) Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.					Mos					
							Hrs	5,500	+50	5500	4473:12 Hrs (+50)	
							Enc					
78-31-00-2200		Thrust Reverser Assembly Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈12-Feb-2025
	78 A/F 64ND-78002-7 EX1875-4 (ZONE: 410) (SOURCE: 560 XL MM Section 5-10-02) KGR-WP-011 START 21-JAN-2025	Left5-12-07					Mos					
							Hrs	1,600	-/+25	(1600)	240:04 Hrs (+25)	
							Ldg					
78-31-00-2200		Thrust Reverser Assembly Detailed Inspection							RE	5-91-02 MSG-3 SYSTEMS, APU, AND POWERPLANT TASKS		≈12-Feb-2025
	78 A/F 64ND-78002-8 EX1880-2 (ZONE: 420) (SOURCE: 560 XL MM Section 5-10-02) KGR-WP-011 START 21-JAN-2025	Right5-12-07					Mos					
							Hrs	1,600	-/+25	(1600)	240:04 Hrs (+25)	
							Ldg					
78-31-00-7200		Thrust Reverser Assembly Functional Check and Operational Check							RE	05-10-01, 05-10-02, Category 6, Category 9		≈12-Feb-2025
	78 A/F 64ND-78002-7 EX1875-4 MRBR Task:78-30-00-702, MRBR Task:78-30-00-701 (ZONE: 410, 235) (SOURCE: 560XL MM) KGR-WP-011 START 21-JAN-2025	Left5-12-07					Mos					
							Hrs	1,600	-/+25	(1600)	240:04 Hrs (+25)	
							Ldg					
78-31-00-7200		Thrust Reverser Assembly Functional Check and Operational Check							RE	05-10-01, 05-10-02, Category 6, Category 9		≈12-Feb-2025
	78 A/F 64ND-78002-8 EX1880-2 MRBR Task:78-30-00-702, MRBR Task:78-30-00-701 (ZONE: 420, 235) (SOURCE: 560XL MM) KGR-WP-011 START 21-JAN-2025	Right5-12-07					Mos					
							Hrs	1,600	-/+25	(1600)	240:04 Hrs (+25)	
							Ldg					
SL560XL-78-04		Thrust Reverser Stow Limit Switch Test							RE (-)	Discretionary		
	78 A/F						Mos					
							Hrs					
							Ldg					
SL560XL-78-04 Rev 01		Thrust Reverser Stow Limit Switch Test							RE (-)	Informational		
	78 A/F Eff: 21-Mar-2007						Mos					
							Hrs					
							Ldg					
▼ 79 - OIL												
		Engine Oil Transmitter							RE (O/C)			
	79 A/F APTE-237E-1000-250D 8765-5-31	Left					Mos	22-Jun-2022				
							Hrs	0				
							Ldg	0				

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
79 A/F	APTE-237E-1000-250D 8892-1-657	Engine Oil Transmitter Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
79 ENG1	31J2955-03 0031695727	Fuel Oil Heat Exchanger New					Mos	30-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
79 ENG2	31J2955-03 0031695720	Fuel Oil Heat Exchanger New					Mos	31-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
79 ENG1	Unknown Unknown	Magnetic Chip Collector					Mos	30-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
79 ENG2	Unknown Unknown	Magnetic Chip Collector					Mos	31-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
79 ENG1	Unknown Unknown	No.1 Oil Level Indicator					Mos	30-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
79 ENG2	Unknown Unknown	No.1 Oil Level Indicator					Mos	31-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
79 ENG1	Unknown Unknown	No.2 Oil Level Indicator					Mos	30-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
79 ENG2	Unknown Unknown	No.2 Oil Level Indicator					Mos	31-Dec-2021		RE (O/C)	
							Hrs	0			
							Enc	0			
79 A/F	1153P0098-01 2896	Oil Pressure Switch Left					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			
79 A/F	1153P0098-01 2899	Oil Pressure Switch Right					Mos	22-Jun-2022		RE (O/C)	
							Hrs	0			
							Ldg	0			

Task No	Description	Categories	Time
SEQ PN/SN	MOC Note or Component Condition	DUE	Remaining
 79 A/F 102-00083 274853	Oil Temp Transmitter Sensor Left	RE (O/C)	
		Mos 22-Jun-2022	
		Hrs 0	
 79 A/F 102-00083 274854	Oil Temp Transmitter Sensor Right	RE (O/C)	
		Mos 22-Jun-2022	
		Hrs 0	
 30325 Rev 2 79 ENG1 Eff: 23-Dec-2015 Complied With (AVG MAN HRS: 2)	Oil-Pump Plain Seal - Replacement	RE (-) Category 6	
		Mos 30-Dec-2021	
		Hrs	
 30325 Rev 2 79 ENG2 Eff: 23-Dec-2015 Complied With (AVG MAN HRS: 2)	Oil-Pump Plain Seal - Replacement	RE (-) Category 6	
		Mos 31-Dec-2021	
		Hrs	
 79-00-PW-001 79 ENG1 Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)	Oil Filter Differential Pressure Switch - Examine and do a functional test (at Engine Overhaul)	RE EMM - Requirement, Extended TBO	≈18-Jul-2030
		Mos	
		Hrs 5,500 +100 5500	4140:04 Hrs (+100)
 79-00-PW-001 79 ENG2 Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)	Oil Filter Differential Pressure Switch - Examine and do a functional test (at Engine Overhaul)	RE EMM - Requirement, Extended TBO	≈04-Jan-2031
		Mos	
		Hrs 5,500 +100 5500	4473:12 Hrs (+100)
 79-00-PW-002 79 ENG1 Unknown Unknown Ref:79-30-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)	Chip Detector/Collector - Examine (at Engine Overhaul)	RE EMM - Requirement, Extended TBO	≈18-Jul-2030
		Mos	
		Hrs 5,500 +100 5500	4140:04 Hrs (+100)
 79-00-PW-002 79 ENG2 Unknown Unknown Ref:79-30-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)	Chip Detector/Collector - Examine (at Engine Overhaul)	RE EMM - Requirement, Extended TBO	≈04-Jan-2031
		Mos	
		Hrs 5,500 +100 5500	4473:12 Hrs (+100)
 79-00-PW-003 79 ENG1 Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)	Oil Tank Filler Cap - Overhaul or Refurbish (at Engine Overhaul)	RE EMM - Requirement, Extended TBO	≈18-Jul-2030
		Mos	
		Hrs 5,500 +100 5500	4140:04 Hrs (+100)
 79-00-PW-003 79 ENG2 Ref:CMM (SOURCE: EMM 05-20-00 Par. 3 Table 1)	Oil Tank Filler Cap - Overhaul or Refurbish (at Engine Overhaul)	RE EMM - Requirement, Extended TBO	≈04-Jan-2031
		Mos	
		Hrs 5,500 +100 5500	4473:12 Hrs (+100)

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
79-00-PW-004		Oil Level Indicator (sight glass) - Inspect (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
	79 ENG1					Mos					
						Hrs		5,500	+100	5500	4140:04 Hrs (+100)
		Ref:CIR (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Enc					
79-00-PW-004		Oil Level Indicator (sight glass) - Inspect (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
	79 ENG2					Mos					
						Hrs		5,500	+100	5500	4473:12 Hrs (+100)
		Ref:CIR (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Enc					
79-00-PW-005		Oil Filter - Examine and replace (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈18-Jul-2030
	79 ENG1					Mos					
						Hrs		5,500	+100	5500	4140:04 Hrs (+100)
		Ref:79-20-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Enc					
79-00-PW-005		Oil Filter - Examine and replace (at Engine Overhaul)						RE	EMM - Requirement, Extended TBO		≈04-Jan-2031
	79 ENG2					Mos					
						Hrs		5,500	+100	5500	4473:12 Hrs (+100)
		Ref:79-20-01-mp (SOURCE: EMM 05-20-00 Par. 3 Table 1)				Enc					
79-10-00-201		External Oil Tube General Visual Inspection: Examine for signs of wear, chafing, cracks, leaks and corrosion.						RE	EMM - Periodic Inspection		≈25-Jan-2025
	79 ENG1	72EH0800				Mos	27-Oct-2023				
						Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
						Enc	505				
	KGR-WP-011 START 21-JAN-2025										
79-10-00-201		External Oil Tube General Visual Inspection: Examine for signs of wear, chafing, cracks, leaks and corrosion.						RE	EMM - Periodic Inspection		≈03-Jun-2025
	79 ENG2	72EH0800				Mos	22-May-2024				
						Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
						Enc	483				
79-10-00-202		Fuel Oil Heat Exchanger General Visual Inspection: Do an inspection for security, leakage and general condition. No leakage permitted.						RE	EMM - Periodic Inspection		≈25-Jan-2025
	79 ENG1	72EH0800				Mos	27-Oct-2023				
						Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
						Enc	505				
	KGR-WP-011 START 21-JAN-2025										
79-10-00-202		Fuel Oil Heat Exchanger General Visual Inspection: Do an inspection for security, leakage and general condition. No leakage permitted.						RE	EMM - Periodic Inspection		≈03-Jun-2025
	79 ENG2	72EH0800				Mos	22-May-2024				
						Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
						Enc	483				
79-10-00-203		Accessory Gear Box Pad Seal General Visual Inspection: Examine the pad seals for oil leaks.						RE	EMM - Periodic Inspection		≈25-Jan-2025
	79 ENG1	72EH0800				Mos	27-Oct-2023				
						Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
		Ref:72-60-01-mp				Enc	505				
	KGR-WP-011 START 21-JAN-2025										
79-10-00-203		Accessory Gear Box Pad Seal General Visual Inspection: Examine the pad seals for oil leaks.						RE	EMM - Periodic Inspection		≈03-Jun-2025
	79 ENG2	72EH0800				Mos	22-May-2024				
						Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
		Ref:72-60-01-mp				Enc	483				
79-10-00-204		External Engine General Visual Inspection: Examine for fuel and oil leaks, corrosion, cracks and signs of damage.						RE	EMM - Periodic Inspection		≈25-Jan-2025
	79 ENG1	72EH0800				Mos	27-Oct-2023				
						Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
						Enc	505				
	KGR-WP-011 START 21-JAN-2025										

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
79-10-00-204		External Engine General Visual Inspection: Examine for fuel and oil leaks, corrosion, cracks and signs of damage.						RE		EMM - Periodic Inspection	≈03-Jun-2025
	79 ENG2	72EH0800				Mos	22-May-2024				
						Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
						Enc	483				
79-10-00-205		Oil Filter Detailed Inspection: Remove and do a check for foreign material and damage.						RE		EMM - Periodic Inspection	≈25-Jan-2025
	79 ENG1	72EH0800				Mos	27-Oct-2023				
						Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
						Enc	505				
	Ref:79-20-01-mp										
	KGR-WP-011 START 21-JAN-2025										
79-10-00-205		Oil Filter Detailed Inspection: Remove and do a check for foreign material and damage.						RE		EMM - Periodic Inspection	≈03-Jun-2025
	79 ENG2	72EH0800				Mos	22-May-2024				
						Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
						Enc	483				
	Ref:79-20-01-mp										
79-10-00-206		Oil Special Detailed Inspection: Do a check for oil level with the outboard sight glass.						RE (PreFlight)		EMM - Periodic Inspection	
	79 ENG1	72EH0000				Mos					
						Hrs					
						Enc					
	Ref:72-00-00-svc										
79-10-00-206		Oil Special Detailed Inspection: Do a check for oil level with the outboard sight glass.						RE (PreFlight)		EMM - Periodic Inspection	
	79 ENG2	72EH0000				Mos					
						Hrs					
						Enc					
	Ref:72-00-00-svc										
79-10-00-206		Oil Special Detailed Inspection: Do a check for oil level with the outboard sight glass. Monitor the oil quality on condition and do analysis periodically as observations warrant (Ref. 72-00-00, ENGINE, GENERAL - SERVICING).						RE		EMM - Periodic Inspection	≈25-Jan-2025
	79 ENG1	72EH0800				Mos	27-Oct-2023				
						Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
						Enc	505				
	Ref:72-00-00-svc										
	KGR-WP-011 START 21-JAN-2025										
79-10-00-206		Oil Special Detailed Inspection: Do a check for oil level with the outboard sight glass. Monitor the oil quality on condition and do analysis periodically as observations warrant (Ref. 72-00-00, ENGINE, GENERAL - SERVICING).						RE		EMM - Periodic Inspection	≈03-Jun-2025
	79 ENG2	72EH0800				Mos	22-May-2024				
						Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
						Enc	483				
	Ref:72-00-00-svc										
79-10-00-207		Oil Filter Bypass Valve Functional Check (Ref. 79-30-02, OIL PRESSURE SWITCH-MAINTENANCE PRACTICES - INSPECTION).						RE		EMM - Periodic Inspection, Extended HSI	≈19-Sep-2026
	79 ENG1					Mos					
						Hrs		2,750	+50	2750	1390:04 Hrs (+50)
						Enc					
	Ref:79-30-02-mp (SOURCE: PW545C MM 30J2302)										
	Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.										
79-10-00-207		Oil Filter Bypass Valve Functional Check (Ref. 79-30-02, OIL PRESSURE SWITCH-MAINTENANCE PRACTICES - INSPECTION).						RE		EMM - Periodic Inspection, Extended HSI	≈07-Mar-2027
	79 ENG2					Mos					
						Hrs		2,750	+50	2750	1723:12 Hrs (+50)
						Enc					
	Ref:79-30-02-mp (SOURCE: PW545C MM 30J2302)										
	Note: NOTE: 1. For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 2750 hours.										
79-10-00-208/209		Magnetic Chip Detector/Collector General Visual Inspection: (Ref. 79-30-01, CHIP DETECTION-MAINTENANCE PRACTICES - REMOVAL/INSTALLATION)						RE		EMM - Periodic Inspection	≈25-Jan-2025
		Remove and do a check for metallic debris									
	79 ENG1	72EH0800				Mos	27-Oct-2023				
						Hrs	763:53	800	-/+25	(1563:53)	203:57 Hrs (+25)
						Enc	505				
	Ref:79-30-01-mp (SOURCE: PW545C MM 30J2302)										
	KGR-WP-011 START 21-JAN-2025										

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR, SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
79-10-00-208/209	Magnetic Chip Detector/Collector General Visual Inspection: (Ref. 79-30-01, CHIP DETECTION-MAINTENANCE PRACTICES - REMOVAL/INSTALLATION) Remove and do a check for metallic debris						RE	EMM - Periodic Inspection		≈03-Jun-2025
 79 ENG2	72EH0800				Mos	22-May-2024				
					Hrs	687:03	800	-/+25	(1487:03)	460:15 Hrs (+25)
	Ref:79-30-01-mp (SOURCE: PW545C MM 30J2302)				Enc	483				
79-10-00-901	Oil Filter Discard: Install the new oil filter element.						RE	EMM - Periodic Inspection		≈25-Mar-2026
 79 ENG1					Mos	30-Jul-2024				
	(Tol. Adjustment: 2.3 Hrs) (SOURCE: PW545C MM (P/N 30J2302))				Hrs	1197:40	1,200	-/+25	2400	1040:04 Hrs (+25)
					Enc	831				
79-10-00-901	Oil Filter Discard: Install the new oil filter element.						RE	EMM - Periodic Inspection		≈09-Jan-2025
 79 ENG2					Mos					
	(SOURCE: PW545C MM (P/N 30J2302))				Hrs		1,200	-/+25	1200	173:12 Hrs (+25)
	 KGR-WP-011 START 21-JAN-2025				Enc					
79-10-00-902	Engine Restoration (TBO): Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈18-Jul-2030
 79 ENG1					Mos					
	(SOURCE: PW545C MM 30J2302)				Hrs		5,500	+50	5500	4140:04 Hrs (+50)
	Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.				Enc					
79-10-00-902	Engine Restoration (TBO): Do the engine restoration at an approved facility IAW PW545C per Overhaul Manual P/N 30J2303.						RE	EMM - Periodic Inspection, Extended TBO		≈04-Jan-2031
 79 ENG2					Mos					
	(SOURCE: PW545C MM 30J2302)				Hrs		5,500	+50	5500	4473:12 Hrs (+50)
	Note: NOTE 2: For engine on the extended TBO (Ref: 05-20-00, SCHEDULED MAINTENANCE CHECKS), the interval is 5500 hours.				Enc					
▼ 80 - STARTING										
 80 A/F	Starter/Generator Left						RE (O/C)			
300SGL138Q-4	Overhauled				Mos	18-Apr-2024				
S00256			0		Hrs	979:20				
			0		Ldg	667				
 80 A/F	Starter/Generator Right						RE (O/C)			
300SGL138Q-4	Overhauled				Mos	18-Apr-2024				
6499XL			0		Hrs	979:20				
			0		Ldg	667				
 80 A/F	Starter/Generator APU						RE (O/C)			
300SGL138Q-6					Mos	22-Jun-2022				
S00280					Hrs	0				
					Ldg	0				
80-10-00-9600	Engine Starter - Generator (Bearings Discard and Armature Functional Check) Restoration						RE	05-10-01, 05-10-02, Category 6		≈03-Sep-2025
 80 A/F	Left				Mos	18-Apr-2024				
300SGL138Q-4					Hrs	979:20	1,000	-/+25	2000	640:04 Hrs (+25)
S00256					Ldg	667				
	MRBR Task:80-10-00-901 (Tol. Adjustment: 20.7 Hrs) (SOURCE: 560XL MM)									
80-10-00-9600	Engine Starter - Generator (Bearings Discard and Armature Functional Check) Restoration						RE	05-10-01, 05-10-02, Category 6		≈03-Sep-2025
 80 A/F	Right				Mos	18-Apr-2024				
300SGL138Q-4					Hrs	979:20	1,000	-/+25	2000	640:04 Hrs (+25)
6499XL					Ldg	667				
	MRBR Task:80-10-00-901 (Tol. Adjustment: 20.7 Hrs) (SOURCE: 560XL MM)									

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
80-11-00-2200	Auxiliary Power Unit Starter - Generator Detailed Inspection									
 80 A/F						Mos	27-Oct-2023			
300SGL138Q-6						Hrs	763:53			
S00280						Ldg	505			
(ZONE: 322) (Tol. Adjustment: -21.5 Hrs(APU)) (SOURCE: 560 XL MM Section 5-10-02, 5-12-00, 5-18-00)						Hrs				
Note: NOTE:Per Supplier Recommendation. Reference Skurka Aerospace Incorporated 300SGL Series Installation Maintenance Manual.						Hrs (APU)	521:30	500	-/+25	1000
 KGR-WP-010 START 11-NOV-2024										76:06 Hrs(APU) (+ 25)
80-11-00-9600	Auxiliary Power Unit Starter - Generator (Bearings Discard and Armature Functional Check) Restoration									
 80 A/F						Mos				
300SGL138Q-6						Hrs				
S00280						Ldg				
MRBR Task:80-10-00-902 (SOURCE: 560XL MM)						Hrs				
 KGR-WP-010 START 11-NOV-2024						Hrs (APU)		1,000	-/+25	1000
										76:06 Hrs(APU) (+ 25)
▼ 99 - --										
CIL-99-01	Use of Corrosion Inhibiting Compounds									
 99 A/F						Mos				
						Hrs				
						Ldg				
CIL-99-01 R1	Use of Corrosion Inhibiting Compounds									
 99 A/F						Mos				
Eff: 15-Feb-2013						Hrs				
						Ldg				
CIL-99-01 R2	Use of Corrosion Inhibiting Compounds									
 99 A/F						Mos				
Eff: 02-Jul-2015						Hrs				
						Ldg				
CIL-99-01 R3	Use of Corrosion Inhibiting Compounds (Cancels this Service Letter)									
 99 A/F						Mos				
Eff: 14-Aug-2019						Hrs				
						Ldg				
CIL-99-02	Avoid Operations on Runways Treated with Runway De-Ice (RDI) Fluids. Aircraft Washing Recommended after Exposure to RDI Fluids									
 99 A/F						Mos				
Eff: 23-May-2012						Hrs				
						Ldg				
Note: the airplane should be washed within 3 days of any exposure to RDI fluids										
CIL-99-02 R1	Avoid Operations on Runways Treated with Runway De-Ice (RDI) Fluids. Aircraft Washing Recommended after Exposure to RDI Fluids - (Cancels this Service Letter)									
 99 A/F						Mos				
Eff: 14-Aug-2019						Hrs				
						Ldg				
CIL-99-03	Miscellaneous - Corrosion Prevention and Control Program (CPCP)									
 99 A/F						Mos	22-Jun-2022			
Eff: 04-Jan-2013 Not Applicable	effective before manufacture					Hrs	8			
						Ldg	6			
Note: his service letter should be accomplished at a scheduled maintenance period or phase inspection.										
CIL-99-03 R1	Miscellaneous - Corrosion Prevention and Control Program (CPCP)									
 99 A/F						Mos				
Eff: 25-Mar-2013						Hrs				
						Ldg				
Note: This service letter should be accomplished at a scheduled maintenance period or phase inspection.										

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA
 560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note or Component Condition								DUE	Remaining
 CIL-99-03 R2 99 A/F Eff: 14-Aug-2019	Miscellaneous - Corrosion Prevention and Control Program (CPCP) (Cancels this Service Letter)						RE (-)		Service Letter	
					Mos					
					Hrs					
					Ldg					
 CIL-99-04 99 A/F Eff: 23-May-2012	Miscellaneous - Incremental Library Updates For Cesview, Service Letter						RE (-)		Service Letter	
					Mos					
					Hrs					
					Ldg					
 CIL-99-04 R1 99 A/F Eff: 14-Aug-2019	Miscellaneous - Incremental Library Updates For Cesview, Service Letter - (Cancels this Service Letter)						RE (-)		Service Letter	
					Mos					
					Hrs					
					Ldg					
 SL560XL-99-03 99 A/F	Transmittal of Cessna's Certification Requirements for Personal Electronic Device Usage						RE (-)		Discretionary	
					Mos					
					Hrs					
					Ldg					
 SL560XL-99-03 Rev 01 99 A/F Eff: 23-Aug-2013	Transmittal of Cessna's Certification Requirements for Personal Electronic Device Usage						T (A/R)		Informational	
					Mos					
					Hrs					
					Ldg					
 SL560XL-99-04 99 A/F Eff: 15-Nov-2011	Cessna Part Number Suffixes For Remanufactured Parts						T (A/R)		Informational	
					Mos					
					Hrs					
					Ldg					
 SL560XL-99-05 99 A/F Eff: 22-Nov-2011	Cessna Service Document Change Notification						T (A/R)		Informational	
					Mos					
					Hrs					
					Ldg					
 SL560XL-99-07 99 A/F Eff: 17-Aug-2017	Miscellaneous - Transmittal of Rockwell Collins Operators Bulletin (OPSB) 0166-17 - The FMS May Turn In The Wrong Direction After Sequencing A "Climb To" Altitude That Was Manually Edited Or Temperature Compensated						T (A/R)		Informational, Service Letter	
					Mos					
					Hrs					
					Ldg					
▼ 100 - GENERAL										
 CF-58-02 100 A/F Complied With (ISSUING AUTHORITY: TC) Note: COMPLIANCE: Compliance with this Directive is effective immediately for all aircraft affected by this order.	Radio Equipment Installed Directly Under an Engine Fuel Primer in Aircraft Must Be Relocated Owing to Fire Hazard (This cancels Airworthiness Directive 51-4)						RE (-)		Mandatory	
					Mos	22-Jun-2022				
					Hrs	8				
					Ldg	6				
 D20200500806 100 APU1 Eff: 06-May-2020	Biocide Treatment Process						T (A/R)		Service Information Letter	
					Mos					
					Hrs					
					APUS					
 SIL-GEN-156 100 ENG1 Eff: 06-Aug-2019	DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation						T (-)		Service Information Letter	
					Mos					
					Hrs					
					Enc					
 SIL-GEN-156 100 ENG2 Eff: 06-Aug-2019	DUPONT KATHON™ FP 1.5 Fuel Biocide Product Discontinuation						T (-)		Service Information Letter	
					Mos					
					Hrs					
					Enc					

OK-KGR STATUS REPORT

Owner/Operator: ABS Jets, a.s.

CESSNA

560XL (Citation XLS+) OK-KGR,SN 560-6325

Task No		Description								Categories	Time
SEQ	PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
SIL-GEN-163		Removal of AWL Requirement to Mark Parts with Accumulated Cycles and/or Time						T (A/R)		Service Information Letter	
	100 ENG1										
	Eff: 03-Mar-2021										
SIL-GEN-163		Removal of AWL Requirement to Mark Parts with Accumulated Cycles and/or Time						T (A/R)		Service Information Letter	
	100 ENG2										
	Eff: 03-Mar-2021										
SIL-PW500-074		United States Parts Distribution						T (A/R)		Service Information Letter	
	100 ENG1										
	Eff: 02-Jun-2021										
SIL-PW500-074		United States Parts Distribution						T (A/R)		Service Information Letter	
	100 ENG2										
	Eff: 02-Jun-2021										